# Available from

NRC/GPO Sales Program

Superintendent of Documents Government Printing Office Washington, D. C. 20402

A year's subscription consists of 12 issues for this publication.

Single copies of this publication are available from National Technical Information Service, Springfield, VA 22161

Microfiche of single copies are available from NRC/GPO Sales Program Washington, D. C. 20555

.

# Title List of Documents Made Publicly Available

August 1-31, 1984

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555



		,

# CONTENTS

Preface	v
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket Items by Facility Name	xvii
Docketed Items	
Low Level Radwaste Disposal Sites — Docket 27.	1
Low Level Radwaste Disposal Sites — Docket 27	ı
Domestic Licensing of Production and Utilization Facilities — Docket 50	9
Domestic Licensing of Special Nuclear Material — Docket 70	424
Packaging of Radioactive Material for Transport and Transportation of	
Radioactive Material Under Certain Conditions — Docket 71	431
Licensing of Independent Spent Fuel Storage — Docket 72	444
Nondocketed Items	445
10 CFR — Commission Meeting Records	445
ACRS — Advisory Committee on Reactor Safeguards	445
ADVCM — NRC Advisory Committees	447
COMMISSION — NRC Commissioners	447
CONTRACT — NRC Contracts and Modifications	449
FOIA — Freedom of Information Act Requests and Releases	453
GEN TECH IS — Generic Technical Issues	
I&E — Inspection and Enforcement	468
MISC — Public Document Room Miscellaneous	
NUREG — NUREG Reports and Related Correspondence	
ORG — Correspondence with Other Organizations	
PR — Proposed Rule	49()
PRM — Petition for Rulemaking	492
PROJ — Projects - Predocket Licensing	492
PT21 — Noncompliance Reports and Related Correspondence	492
QA999 — Quality Assurance Inspections	494
REGGD — Regulatory Guides	497
REVIEW GROUP - NRC Research Review Groups	498
SECY — Position Papers Before the Commission	498
STATE PROG — State Programs	499
TOPREP — Vendor Reports and Related Correspondence	500
WASTE MGT — Nuclear Waste Management	508
WASTE RES — Waste Management Research Reports	515
XPORTLIC — Export and Import Licenses	516
Personal Author Index	521
Corporate Source Index	553
Report Number Index	583
Cross Reference of Enclosures to Principal Documents	585
Appendix A — Definitions of Docket 50 Categories	A-1
Appendix B — Definitions of Nandocketed Categories	T)

		1
		1

#### PREFACE

The Title 1 ist of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

#### DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K Utility Final Safety Analysis Report (FSAR) and amendments
- Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IF Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences, I ERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U Congressional/executive correspondence
- V. Licensing operators and related correspondence

- W Decommissioning stage documents and correspondence
- X Onsite low-level wastes storage

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

Operating license stage documents & correspondence

2
3
8203090028 Responds to 820201 ltr requesting documents re environ qualification of electrical equipment. All nonproprietary repts will be provided to Franklin Research. Ctr by 820408. Proprietary repts will be provided to NRC by 820510

4 MILLS, L.M (5) Tennessee Valley Authority. (6) 82/03/04 (7) VASSALLO, D B Operating Reactors Branch 2 (8) 1p. 1216:254. 24XFiche: 50-259, 82/03/04, 8203090028.

- 1 NRC/PDR Document category (see Appendix A).
- 2. NRC Accession Number (year, month, day, and sequence number of item).
- 3. Description of information contained in the document.
- 4. Personal author(s) An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source
- 6. Date of document described
- 7. Recipient of document and NRC or corporate affiliation.
- 8. Pages in this document.
- 9 The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files
- 10. This three-digit portion of this entry is the number of the frame on which this document starts.
- 11. The 24X Fiche designation consists of the docket number followed by the date of the document and the accession number for the document. This designation provides the information needed by subscribers to the National Technical Information Service docket microfiche to locate the document fiche.
- 12 If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

#### NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. These categories and their symbols are:

10CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION — NRC Commissioners
CONTRACT — NRC Contracts and Modifications
DISCLOSURE — Financial Disclosure Information
FOIA — Freedom of Information Act Requests and Releases
GEN TECH IS — Generic Technical Issues

I&E -- Inspection and Enforcement

MISC - Public Document Room Miscellaneous

NUREG - NUREG Reports and Related Correspondence

ORG — Correspondence with Other Organizations

PR — Proposed Rule

PRM — Petition for Rulemaking

PROJ - Projects-Predocket Licensing

PT21 - Noncompliance Reports and Related Correspondence

QA999 — Quality Assurance Inspections

REGGD - Regulatory Guides

RES - Research and Technical Assistance Reports

REVIEW GRP — NRC Research Review Groups

RM - Rulemakings

SECY — Position Papers Before the Commission

STATE PROG — State Programs

TOPREP — Vendor Reports and Related Correspondence


WASH - Regulatory Publications-Pre-NUREG Series

WASTE MGT — Nuclear Waste Management

XPORTLIC — Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:



- 1. Nondocketed category
- 2. NRC Accession Number (year, month, day, and sequence number of item)
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 6. Corporate, agency or other nonindividual source.
- 7. Contract or financial (FIN) number (if any). If the document has a sceondary report number, it will appear following this entry.
- 8. Secondary report number assigned by originator.
- 9. Date of document described.
- 10. NRC organizational recipient.
- 11. Pages in document.
- All NUREG-series documents are available for purchase at NRC. Information on ordering documents is given below. All NUREG-series documents are also available at NTIS. Information on ordering from NTIS is also given below.
- 13 Price for which NRC sells the document.

- 14 The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
- 15. This three-digit portion of this entry is the number of the frame on which this document starts

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

#### NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the chargecard number when placing your order

3. The address for the PDR is:

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: (1) paper to paper is \$0.05 per page except for oversized documents and engineering drawings, which vary from \$0.50 to \$1.00 per square foot; (2) microform to paper is \$0.05 a page for pages on microfiche and is \$0.20 a square foot for a full-size print or \$0.25 for a reduced-size print (18" x 24") of a drawing on an aperture card; and (3) microform to microform is \$0.10 per microfiche and \$0.20 per aperture card. Orders completed for mailing or for a special delivery service will have an additional fee for the actual mailing, shipping, or delivery service rate. Unless a user requests special packing materials, there is no additional charge by the contractor for handling and wrapping materials

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Literature Research Company. An account may be established with the Literature Research Company by calling (703)-941-8018.

# ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
Low Level Rad	lwaste Disposal Sites - Docket 27		40-8452	Bear Creek Uranium Co., Casper, WY	6
27-039	Sheffield, IL, U.S. Ecology, Inc.	1	40-8502	Wyoming Mitteral Corp., Lakewood, CO	6
27-048	Richland, WA, U.S. Ecology, Inc.	1	40-8584	Minerals Exploration Co., Los Angeles, CA	7
			40-8585	Wyoming Mitteral Corp., Lakewood, CO	7
	sing of Source Material — Docket 40		40-8586	Keir-McGee Nuclear Corp ,	_
40-0299	Union Carbide Corp., Grand Junction, CO	1	44.114.414	Oklahoma City, OK	7
40-0672	Nuclear Metals, Inc., Concord, MA	2	40-8602	Silver King Mines, Inc., Casper, WY	7
40-0791	United Technologies Corp , East Hartford, CT	2	40-8674	Plateau Resources, Ltd Grand function, CO	7
40-1162	Western Nuclear, Inc., Jeffrey City, WY	2	40-8675	Energy Fuels Nuclear, Inc., Denver, CO	7
40-1341	Tennessee Valley Authority, Chattanooga, TN	2	40-8681	Energy Fuels Nuclear, Inc., Denver, CO	7
40-2061	Kerr-McGee Chemical Corp.,	-	40-8684	Western Nuclear, Inc., Lakewood, CO	8
10 400.	Oklahoma City, OK	2	40-8697	Rocky Mountain Energy Co , Denver, CO	8
40-2259	Pathfinder Mines Corp., Riverton, WY	3	40-8698	Plateau Resources, Ltd., Grand Junction, CO	8
40-3392	Allied Chemical Corp., Morristown, NJ	4	40-8722	Brush Wellman, Inc., Cleveland, OH	8
40-3453	Atlas Minerals, Inc., Denver, CO	4	40-8724	Chemetron Corp., Chicago, IL	8
40-4492	Federal-American Partners, Riverton, WY	4	40-8727	Kerr-McGee Nuclear Corp , Oklahoma City, OK	8
40-6499	Maine Maritime Academy, Castine, ME	4	40-8728	Teton Exploration Drilling Co , Inc ,	
40-6500	Energy, Dept of, Canonsburg, PA	4		Casper, WY	8
40-6622	Pathfunder Mines Corp , Shirley Basın, WY	4	40-8745	Ogle Petroleum, Inc., Casper, WY	8
40-6659	Getty Oil Co -Petrotomics Co., Shirley Basin, WY	5	40-8768	Ken-McGee Nuclear Corp , Oklahoma City, OK	8
40-6940	Kaweeki Berylco Industries, Inc.,		40-8769	Exxon Co., USA, Billings, MT	9
10 7155	Boyertown, PA	5	40-8783	Uranerz USA, Inc., Casper, WY	9
40-7455	Whittaker Metals, Los Angeles, CA	5	40-8786	Uranium Resources, Inc., Richardson, TX	9
40-7869	Plateau Resources, Ltd., Grand Junction, CO	5	40-8822	Omaha Public Power District, Omaha, NE	9
40-8027	Kerr-McGee Nuclear Corp., Oklahoma City, OK	5	40-8829	Wyoming Fuel Co., Lakewood, CO	9
40-8064	Exxon Minerals Co , USA, Houston, TX	5	40-8842	Minnesota, Univ. of, Minneapolis, MN	9
40-8084	Rio Algom Corp., Moab, UT	5	40-8857	Everest Minerals Corp., Converse County, WY	9
40-8102	Exxon Co , USA, Houston, TX	5	Domestic Licen	sing of Production and Utilization Facilities—	
40-8380	Rocky Mountain Energy Co , Broomfield, CO	6	Docket 50 50-2	Univ of Michigan Research Reactor	9
40-8434	Homestake Mining Co., Lakewood, CO	6	50-3	Indian Point Station, Unit 1	9

Docket	Name	Page	Docket	Name	Page
50-5	Pennsylvania State Univ. Research Reactor	10	50-186	Univ. of Missouri Research Reactor	22
50-10	Dresden Nuclear Power Station, Unit 1	10	50-188	Kansas State Univ Research Reactor	22
50-13	Babeock & Wilcox Co. Critical Facility	12	50-192	Univ of Texas Research Reactor	22
50-27	Washington State Univ. Research Reactor	12	50-193	Rhode Island & Providence Plantations AEC	22
50-29	Yankee-Rowe Nuclear Power Station	12	50-199	Manhattan College Research Reactor	23
50-30	Plum Brook Research Reactor Facility	14	50-206	San Onofre Nuclear Station, Unit 1	23
50-54	Union Carbide Research Reactor	15	50-213	Haddam Neck Plant	26
50-57	State Univ. of New York Research Reactor	15	50-219	Oyster Creek Nuclear Power Plant	28
50-59	Texas A&M Univ. Research Reactor	15	50-220	Nine Mile Point Nuclear Station, Unit 1	31
50 62	Univ. of Virginia Research Reactor	15	50-223	Univ. of Lowell Research Reactor	33
50-70	General Electric Test Reactor	15	50-225	RPI Critical Experiment	33
50-73	General Electric Nuclear Test Reactor	15	50-237	Dresden Nuclear Power Station, Unit 2	33
50-89	General Atomic Co	15	50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	36
50-97	Cornell Univ Zero Power Reactor	16	50-245	Millstone Nuclear Power Station, Unit 1	38
50-112	Univ. of Oklahoma Research Reactor	16	50-247	Indian Point Station, Unit 2	41
50-116	Iowa State Univ. Research Reactor	16	50-249	Dresden Nuclear Power Station, Unit 3	44
50-123	Umv of Missouri Research Reactor	16	50-250	Turkey Point Plant, Unit 3	46
50-133	Humboldt Bay Power Plant, Unit 3	16	50-251	Turkey Point Plant, Unit 4	49
50-134	Worcester Polytechnic Institute Research Reactor	17	50-252	Univ. of New Mexico Research Reactor	52
EO 120		17	50-254	Quad-Cities Station, Unit 1	52
50-139	Univ of Washington Research Reactor	17	50-255	Palisades Nuclear Plant	54
50-142 50-150	UCLA Training Reactor  Ohio State Univ. Research Reactor	17	50-259	Browns Ferry Nuclear Power Station, Unit 1	57
50-151	Univ of Illinois Research Reactor	17	50-260	Browns Ferry Nuclear Power Station, Unit 2	61
		18	50-261	H B Robinson Plant, Unit 2	65
50-155 50-156	Big Rock Point Nuclear Plant	20	50-262	Brigham Young Univ Research Reactor	68
50-150	Univ. of Wisconsin Research Reactor  Cornell Univ. Research Reactor		50-263	Monticello Nucleai Generating Plant	68
50-160		21	50-264	Dow Chemical Co	70
20-100	Georgia Institute of Technology Research Reactor	21	50-265	Quad-Cities Station, Unit 2	70
50-163	GA Technologies	21	50-266	Point Beach Nuclear Plant, Unit 1	72
50-166	Univ. of Maryland Research Reactor	21	50-267	Fort St. Vrain Nuclear Generating Station	74
50-170	National Naval Medical Center	22	50-269	Oconce Nuclear Station, Unit 1	76
50-171	Peach Bottom Atomic Power Station, Unit 1	22	50-270	Oconce Nuclear Station, Unit 2	79
50-182	Purdue Univ. Research Reactor	22	50-271	Vermont Yankee Nuclear Power Station	81
50-184	National Bureau of Standards Reactor	22	50-272	Salem Nuclear Generating Station, Unit 1	83
50-185	Plum Brook Reactor-Mock-Up	22	50-274	U.S Geological Survey Research Reactor	85

I	Oocket	Name	Page	Docket	Name	Page
	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	85	50-323	Diablo Canyon Nuclear Power Plant, Unit 2	167
	50-276	Georgia Tech Research Reactor	90	50-32‡	Brunswick Steam Electric Plant, Unit 2	171
	50-277	Peach Bottom Atomic Power Station, Unit 2	90	5()-325	Brunswick Steam Electric Plant Unit 1	173
	50-278	Peach Bottom Atomic Power Station, Unit 3	92	50-326	Univ of California at Livine Research Reactor	175
	50-280	Surry Power Station, Unit 1	94	50-327	Sequoyah Nuclear Plant, Unit 1	175
	50-281	Surty Power Station, Unit 2	97	50-328	Sequoyah Nuclear Plant, Unit 2	177
	50-282	Prairie Island Nuclear Station, Unit 1	98	50-329	Midland Plant, Unit 1	179
	50-284	Idaho State Univ. Research Reactor	100	50-330	Midland Plant, Unit 2	195
	50-285	Fort Calhoun Station, Unit 1	100	50-331	Duane Arnold Energy Center	211
	50-286	Indian Point Station, Unit 3	101	50-333	James A. Eitzpatrick Nuclear Power Plant	213
	50-287	Oconee Nuclear Station, Unit 3	103	50-334	Beaver Valley Power Station, Unit 1	215
	50-289	Three Mile Island Nuclear Station, Unit 1	106	50-335	St. Lucie Plant, Unit 1	217
	50-293	Pilgrim Nuclear Power Station, Unit 1	112	50-336	Millstone Nuclear Power Station, Unit 2	219
	50-294	Michigan State Univ Research Reactor	115	50-338	North Anna Power Station, Unit 1	222
	50-295	Zion Nuclear Power Station, Unit 1	115	50-339	North Anna Power Station, Unit 2	225
	50-296	Browns Ferry Nuclear Power Station, Unit 3	119	50-341	Emico Fermi Atomic Power Plant, Unit 2	227
	50-297	North Carolina State Univ		50-344	Irojan Nuclear Plant	231
		PULSTAR Reactor	122	50-346	Davis-Besse Nuclear Power Station, Unit 1	234
	50-298	Cooper Nuclear Station	122	50-348	Joseph M. Farley Nuclear Plant, Unit 1	237
	50-301	Point Beach Nuclear Plant, Unit 2	124	50-352	Limerick Generating Station, Unit 1	238
	50-302	Crystal River Nuclear Plant, Unit 3	127	50-353	Limerick Generating Station, Unit 2	246
	50-304	Zion Nuclear Power Station, Unit 2	129	50-354	Hope Creek Nuclear Station, Unit 1	253
	50-305	Kewaunee Nuclear Power Plant	132	50-355	Hope Creek Nuclear Station, Unit 2	258
	50-306	Prairie Island Nuclear Station, Unit 2	134	50-356	Univ of Illinois Research Reactor	258
	50-309	Maine Yankee Atomic Power Plant	135	50-358	William H. Zimmer Nuclear Station, Unit 1	259
	50-311	Salem Nuclear Generating Station, Unit 2	137	50-361	San Onofre Nuclear Station, Unit 2	260
	50-312	Rancho Seco Nuclear Generating Station	139	50-362	San Onofic Nuclear Station, Unit 3	262
	50-313	Arkansas Nuclear One, Unit 1	142	50-364	Joseph M. Fatley Nuclear Plant, Unit 2	265
	50-315	Donald C Cook Nuclear Power Plant, Unit I	144	50-366	Edwin I Hatch Nuclear Plant, Unit 2	266
	50-316	Donald C. Cook Nuclear Power Plant, Unit 2	146	50-367	Bailly Generating Station	269
	50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	148	50-368	Arkansas Nuclear One, Unit 2	269
	50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	151	50-369	William B. McGuire Nuclear Station, Unit 1	272
	50-320	Three Mile Island Nuclear Station, Unit 2	153	50-370	William B, McGune Nuclear Station, Unit 2	274
	50-321	Edwin I. Hatch Nuclear Plant, Unit 1	156	50-373	LaSalle County Station, Unit 1	276
	50-322	Shorcham Nuclear Power Station	159	50-374	LaSalle County Station, Unit 2	279

Docket	Name	Page	Docket	Name	Page
50-382	Waterford Generating Station, Unit 3	283	\$1N-50-456	Braidwood Station Unit I	381
50-387	Susquehanna Steam Electric Station Umt 1	287	S1N-50-457	Braidwood Station Unit 2	384
50-388	Susquehanna Steam Electric Station Unit 2	289	50-458	River Bend Station Unit I	388
50-389	St Lucie Plant Unit 2	291	50-459	River Bend Station Unit 2	392
50-390	Watts Bar Nuclear Plant Unit 1	293	50-460	WPPSS Nuclear Project. Unit 1	393
50-391	Watts Bar Nuclear Plant, Unit 2	295	50-461	Clinion Power Station Unit 1	394
50-395	Virgil C. Summer Nuclear Station. Unit 1	297	50-462	Clinton Power Station Unit 2	396
50-396	Unix of Virginia Cavalier Reactor	299	STN-50-470	CESSAR System 80	396
50-397	WPPSS Nuclear Project Unit 2	299	S fN-50-482	Wolf Creek Generating Station	397
50-400	Shearon Harris Nuclear Power Plant Unit 1	302	STN-50-483	Callaway Plant, Unit 1	400
50-401	Shearon Hairis Nuclear Power Plant, Unit 2	306	STN-50-491	Cherokee Nuclear Station Unit 1	403
50-409	La Crosse Boiling Water Reactor	308	S FN-50-492	Cherokee Nuclear Station Unit 2	403
50-410	Nine Mile Point Nuclear Station, Unit 2	310	STN-50-493	Cherokee Nuclear Station Unit 3	403
50-412	Beaver Valley Power Station, Unit 2	312	50-496	Montague Nuclear Power Station Unit 1	403
50-413	Catawba Nuclear Station, Unit 1	314	50-497	Montague Nuclear Power Station Unit 2	403
50-414	Catawba Nuclear Station, Unit 2	320	STN-50-498	South Texas Project Unit 1	404
50 416	Grand Gulf Nuclear Station, Unit 1	324	STN-50-499	South Texas Project Unit 2	406
50-417	Grand Gulf Nuclear Station, Unit 2	329	STN-50-508	WPPSS Nuclear Project Unit 3	407
50-423	Millstone Nuclear Power Station, Unit 3	332	STN-50-509	WPPSS Nuclear Project, Unit 5	408
50-424	Vogtle Electric Generating Plant	333	S FN-50-518	Hartsville Nuclear Plant, Unit 1	408
50-425	Vogtle Electric Generating Plant	336	STN-50-520	Haitsville Nuclear Plant, Unit 3	408
50-433	UC-Santa Barbara Research Reactor	338	50-522	Skagit Nuclear Power Project Unit 1	408
STN-50-437	Floating Nuclear Plant	339	50-523	Skagit Nuclear Power Project, Unit 2	409
50-438	Bellefonte Nuclear Plant, Unit 1	339	S FN-50-528	Palo Verde Nuclear Station Unit 1	409
50-439	Bellefonte Nuclear Plant, Unit 2	341	STN-50-529	Pulo Verde Nuclear Station Unit 2	414
50-440	Perry Nuclear Power Plant, Unit 1	343			
50-441	Perry Nuclear Power Plant, Unit 2	346	\$1 N-50-530	Palo Verde Nuclear Station, Unit 3	-118
50-443	Seabrook Nuclear Station, Unit 1	349	50-538 57N 50-546	Memphis State Univ. Research Reactor	422
50-444	Seabrook Nuclear Station, Unit 2	350	STN-50-546	Marble Hill Nuclear Station Unit 1	422
50-445	Comanche Peak Steam Electric Station, Unit 1	352	STN-50-547	Marble Hill Nuclear Station Unit 2	423
50-446	Comanche Peak Steam Electric Station.		STN-50-566	Yellow Creek Nuclear Plant, Unit 1	423
	Unit 2	361	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	423
STN-50-447	GESSAR-238	369	50-601	RESAR SP/90	423
STN-50-454	Byron Station, Unit 1	370	Domestic Licens	sing of Special Nuclear Material — Docket 70	
STN-50-455	Byron Station, Unit 2	376	70-0008	Battelle Memorial Institute, Columbus, OH	424

Docket	Name	Page	Docket	Name	Page
70-0025	Rockwell International Corp	12.1	70-2872	RS Holding Inc. Cleveland OH	431
70.0027	Canoga Park, CA	424	70-2884	Long Island Lighting Co. Hicksville, NY	431
70-0027	Babcock & Wilcox Co., Lynchburg, VA	424	70-2988	Philadelphia Electric Co , Philadelphia, PA	431
70-0036	Combustion Engineering Inc. Windsoi CT	425	70-2998	Gulf States Utilities Co Beaumont TX	431
70-0143	Nuclear Fuel Services, Inc. Erwin, TN	425			
70-0221	General Dynamics Corp., Groton, CT	427	Transportati	Radioactive Material for Transport and ion of Radioactive Material Under Certain	
70-0303	Carnegie-Mellon Univ Pittsburgh, PA	427		- Docket 71	
70-0364	Babcock & Wilcox Co - Apollo - PA	427	71 0008	Commonwealth Edison Co	431
70-0371	UNC Naval Products, Inc., Uncasville, CI	427	71-0011	Arrow Tank & Engineering Co	431
70-0398	Commerce, Dept. of, Washington, DC	427	71-0014	Adirondack Steel Casting Co	431
70-0466	Maine Maritime Academy, Castine, ME	427	71-0015	Chicago Bridge & Iton Co	432
<i>7</i> 0-0687	Union Carbide Corp., Tuxedo, NY	428	71-0016	Northwest Airlines, Inc	432
70-0734	GA Technologies, Inc., San Diego, CA	428	71-0020	International Testing Laboratories	432
70-0820	United Nuclear Corp , Wood River Junction, RI	428	71-0022	Newport News Industrial Corp	432
70-0824	Babeock & Wilcox Co , Lynchburg, VA	428	71-0028	Borg-Warner Corp	432
70-0824	Keir-McGee Nuclear Corp .	7-0	71-0032	Panhandle Eastern Pipe I inc Co	432
70-0923	Oklahoma City, OK	428	71-0033	Industrial Testing Laboratory Services Corp	432
70-0938	Massachusetts Institute of Technology,	110	71-0034	Babcock & Wilcox Co	432
70.0001	Cambridge MA	428	71-0036	ITT Grinnell Corp	432
70-0984	Battelle Memorial Institute, Richland, WA	429	71-0037	Navy, Dept of	432
70-1068	Florida, Univ of, Gamesville, FL	429	71-0038	Crane Co	432
70-1113	General Electric Co., Wilmington, NC	429	71-0039	Walworth Co	432
70-1143	Westinghouse Electric Corp., Putsburgh, PA	429	71-0044	United Airlines, Inc	432
70-1151	Westinghouse Electric Corp., Pittsburgh, PA	429	71-0047	Capitof International Arrways, Inc.	432
70-1193	Kerr-McGee Nuclear Corp., Oklahoma City, OK	430	71-0051	Harrison Steel Castings Co	432
70-1201	Babenek & Wilcox Co., Lynchburg, VA	430	71-0055	H R. Inspection Service	433
70-1257	Exxon Nuclear Co , Inc , Richland, WA	430	71-0056	Philadelphia Electric Co.	433
70-1308	General Electric Co., San Jose, CA	430	71-0057	Exxon Co , USA	433
70-1342	Coratomic, Inc., Indiana, PA	430	71-0059	General Electric Co.	433
70-1362	Hahnemann Medical College & Hospital, Philadelphia, PA	430	71-0061	Navy, Dept of	433
70-1450	Berkshire Medical Center, Pittsfield, MA	431	71-0063	Ozark Aulines, Inc	433
			71-0066	Certified Testing Laboratories, Inc	433
70-1941	Passaic General Hospital, Passaic, NJ	431	71-0068	Yankee Atomic Electric Co	433
70-2377	Dentsply International, Inc., York, PA	431	71-0070	Gamma Field Radiographic Facility	433
70-2571	Yale-New Haven Hospital, New Haven, CT	431	71-0074	Nuclear Welding, Inc.	433
70-2838	Cincinnati Gas & Electric Co., Cincinnati, OH	431	71-0075	Norfolk Shipbuilding & Dry Dock Co	433

Docket	Name	Page	Docket	Name	Page
71 0077	Midstate Testing Laboratory	433	71-0156	Industrial Fabricating Co	435
71-0080	Transworld Airlines, Inc	433	71-0157	Froehling & Robertson Inc	435
71-0081	ITT Grinnell Industrial Piping Inc.	433	71-0158	X-Ray Industries Inc	436
71-0083	Northern States Power Co	433	71-0161	Curtiss-Wright Corp	436
71-0087	Navy Dept of	134	71-0162	Ebaseo Services Inc	436
71-0089	Navy Dept of	434	71-0166	New York Testing Laboratories Inc.	436
71-0093	Huntington Testing	434	71-0167	Finlay Testing Laboratories	436
71-0095	United States Testing Co Inc	434	71-0168	Quality Assurance Laboratories	436
71-0099	Foster Wheeler Energy Corp	434	71-0169	Florida Power & Light Co	436
71-01()()	Venegas Industrial Testing Laboratories	134	71-0171	Industrial Inspection Industries	436
71-0103	Twin City Testing & Engineering	131	71-0172	Empire Steel Castings, Inc	436
	Laboratory Inc	434	71-0174	Southern California Edison Co	436
71-0104	Chicago Bridge & Iron Co	434	71-0175	QC Services, Inc.	436
71-0105	Universal Testing Laboratories	434	71-()181	Consolidated X-Ray Service Corp.	436
71-0110	Buckeye Steel Castings	434	71-0183	Gamma Sonics Examination	126
71-0111	Material Testing Laboratory of Virginia, Inc	434	71.0191	Laboratones, Inc	436
71-0113	Nooter Corp	434	71-0184	Pullman Power Products	436
71-0119	Ingersoli-Rand Co	434	71-0186	High Steel Structures, Inc	436
71-0120	Daniel International Corp	434	71-0188	Maynard Steel Casting Co	436
71-0123	Herron Testing Laboratories, Inc	434	71-0195	Toledo Edison Co	437
71-0124	Houston Inspectson Laboratories, Inc	434	71-0202	Pacific Gas & Electric Co	437
71-0125	Testeo, Inc	435	71-0205	Quality Testing, Inc	437
71-0127	National Annealing Box Co	435	71 0207	Connecticut Yankee Atomic Power Co	437
71-0128	Amoco Oil Co	435	71-0208	Northeast Nuclear Energy Co	437
71-0130	Chicago Bridge & Iron Co	435	71-0211	Boston Edison Co.	437
71-0132	Advanced Radiation Service	435	71-0212	General Electric Co	437
71-0133	Navy, Dept. of	435	71-0213	Intermountain Testing Co	437
71-0134	Labarge, Inc	435	71-0214	Gas Rentals, Inc	437
71-0137	Metals Testing Co., Inc	435	71-0215	Space Science Services Inc	437
71-0140	Walworth Co	435	71-0216	Nuclear Energy Services Inc	437
71-0145	Thayer Inspection Service, Inc	435	71-0217	Pullman, Inc	437
71-0148	United Engineers & Constructors, Inc.	435	71-0218	Cumberland Bridge Co	437
71-0151	Hess Oil Virgin Islands Corp.	435	71-0219	Terex Corp	437
71-0152	Virginia Commonwealth of	435	71-0220	General Dynamics Corp	437
71-0154	General Dynamics Corp	435	71-0221	Allis-Chalmers Corp	437

Docket	Name	Page	Docket	Name	Page
71-0222	St. Louis Testing Laboratories. Inc.	437	71-0289	Terradata Geophysical, Inc	440
71-0223	Benjamin F Shaw Co	438	71-0290	United Testing Services, Inc.	440
71-0224	Guyon Power & Process Piping	438	71-0291	DJ Inspection Services, Inc	<b>4</b> 40
71-0225	Navy Dept of	438	71-0292	Industrial Gamma Inspection	440
71-0229	Word Industries Pipe Fabricating Inc	438	71-0293	Brand X Perforators, Inc	440
71-0232	Lakehead Testing Laboratories Inc	438	71-0294	Applied Engineering Co	440
71-0233	O Neill Tank Co - Inc	438	71-0295	Acurex Corp	440
71-0234	X-Ray Inc	438	71-0296	lowa Electric Light & Power Co	440
71-0237	Columbia Gas Transmission Corp	438	71-0297	E Lewis Cook & Associates	440
71-0240	Power Authority of State of New York	438	71-0298	Steel Tank Construction Co	440
71-0242	Law Engineering Testing Co	438	71-0299	Quality Control Services	44()
71-0245	Navy Dept of	438	71-0300	Independent Testing Laboratories	440
71-0247	IR T Corp	438	71-0301	CTL Engineering, Inc	440
71-0253	Iwin Ports Testing Inc	438	71-0302	Associated Piping & Engineering Corp	440
71-0254	General Electric Co	438	71-0303	Memphis Testing Services, Inc	440
71-0256	Omaha Public Power District	438	71-0304	Feledyne Brown Engineering, Co	440
71-0257	Industrial Laboratories Inc	438	71-0305	American X-Ray & Inspection, Inc	440
71-0261	Navy Dept of	439	71-0306	Snyder Drilling & Well Servicing	44
71-0268	Navy Dept of	439	71-0307	Texas Pipe Bending Co. of Puerto Rico	441
71-0269	Lehigh Testing Laboratories Inc	439	71-0310	Bucyrus-Ene Co	441
71-0270	Factory Mutual Engineering Corp	-139	71-0311	Logwell, Inc	441
71-0272	Crane Co	439	71-0312	Metalforms, Inc	441
71-0274	Navy Dept of	439	71-0313	Precision Inspection, Ltd	441
71-0275	Duquesne Light Co	439	71-0314	Smith-Emery Co.	441
71-0276	Navy Dept of	439	71-0317	Hudson Products Corp.	441
71-0279	Universal Testing, Inc.	439	71-0318	Marathon Oil Co	441
71-0280	ABCO Perforators Inc	439	71-0319	General Testing & Inspection Co	441
71-0281	Delta Airlines, Inc	439	71-0320	Putsburgh-Des Momes Steel Co	441
71-0282	WKM Wellhead Systems. Inc	439	71-0322	Babcock & Wilcox Co	441
71-0283	McManus Inspection Service	439	71-0325	Consumers Power Co.	441
71-0284	Ultrasonic Specialists, Inc	439	71-0326	Industrial NDT Services Division	441
71-0285	Belt Geophysics	439	71-0327	Portland General Electric Co.	441
71-0286	BPB Instruments Inc	439	71-0328	Public Service Electric & Gas Co	441
71-0287	Carson Non-Destructive Testing	439	71-0329	Howmet Turbine Components Corp	441
71-0288	North Dakota. State of	439	71-0330	Allied Inspection Services, Inc.	442

Docket	Name	Page	Docket	Name	Page
71-0522	California Univ of Los Angeles, CA	442	71-9126	Model 20 20A, 50 50A Gamma Industries	443
71-5805	Model CNS 3-55 Chem-Nuclear Systems, Inc	442	71-9143	Model 920, Technical Operations Inc	443
71-5926	Model GE-100, General Electric Co	442	71-9147	Model 850 Technical Operations Inc	443
71-6244	Model 6244, Chem-Nuclear Systems, Inc	142	71-9151	Model HN-100 Series 3 CNS 14-170 Series III & NUS	443
71-6346	Model FSV-1, GA Technologies, Inc.	442	71-9163	Model GNG-20 Guli Nuclear, Inc	443
71-6581	Model 51032-1 & 1A Exxon Nuclear Co., Inc	442	71-9184	Model PAS-1, Nuclear Packaging, Inc.	443
71-6717	Model 6717-B, Gamma Industries	442	71-9186	Model S-6213, Energy, Dept of	443
71-9001	Model 1F-300. General Electric Co	442	71-9188	Model, AP-300, ANEFCO, Inc	444
71-9016	Model TN-9, No Users	442	71-9192	Model AP-300, ANEFCO, Inc	444
71-9021	Model 750, Technical Operations, Inc	443	71-9193	Model NES-5, Nuclear Energy Services Inc	444
71-9073	Model OH-142 Series & NUS 10-135, Nuclear Packaging, Inc	443			
71-9092	Model HN-300, Hittman Nuclear &		Licensing of I	ndependent Spent Fuel Storage - Docket 72	
	Development Corp	443	72-0001	Morris Operations, General Electric Co	444
71-9093	Model: HN-400, Hitiman Nuclear & Development Corp	443	72-0002	Virginia Electric & Power Co	444
71-9111	Model CNS 6-80-2 & CNS 6-80-2A. Chem-Nuclear Systems Inc	443			

# ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Low Level Radwaste Disposal Sites Docket 27			Minerals Exploration Co. Los Angeles, CA.	40 8584	7
Richland, WA, U.S. Ecology, Inc.	27-048	i	Minnesota Univ of Minneapolis MN	40-8842	Ŋ
Sheffield, IL, U S Ecology, Inc	27-039	ı	Nuclear Metals Inc. Concord. MA	40-0672	2
Domestic Licensing of Source Material — Dock	et 40		Ogle Petroleum Inc Casper WY	40-8745	8
Allied Chemical Corp., Morristown, NJ	40-3392	4	Omaha Public Power District, Omaha NI.	40 8822	Ŋ
Atlas Minerals, Inc., Denver, CO	40-3453	4	Pathfinder Mines Corp. Riverton, WY	40-2259	3
Bear Creek Uranium Co , Casper, WY	40-8452	6	Pathlinder Mines Corp Shuley Basin WY	40 6622	4
Brush Wellman, Inc., Cleveland, OH	40-8722	8	Plateau Resources Ltd Grand Junction CO	40-7869	5
Chemetron Corp , Chicago, IL	40-8724	8	Plateau Resources Ltd Grand Junction CO	40-8674	7
Energy Fuels Nuclear, Inc., Denver, CO	40-8675	7	Plateau Resources Ltd Grand Junction CO	40-8698	8
Energy Fuels Nuclear, Inc., Denver, CO	40-8681	7	Rio Algom Corp Moab UT	40-8084	5
Energy, Dept of, Canonsburg, PA	40-6500	4	Rocky Mountain Energy Co Broomfield CO	10-8380	n
Everest Minerals Corp., Converse County, WY	40-8857	9	Rocky Mountain Energy Co Denvei CO	40-8697	8
Exxon Co., USA, Billings, MT	40-8769	9	Silver King Mines Inc. Casper WY	40-8602	7
Exxon Co., USA, Houston, TX	40-8102	5	Tennessee Valley Authority Chattanooga TN	40-1341	2
Exxon Minerals Co., USA, Houston, TX	40-8064	5	Feron Exploration Drilling Co - Inc Casper, WY	40-8728	8
Federal-American Partners, Riverton, WY	40-4492	4	Union Carbide Corp Grand Junction, CO	40 0299	1
Getty Oil CoPetrotomics Co , Shirley Basin, WY	40-6659	5	United Technologies Corp  East Hartford, CT	40-0791	2
Homestake Mining Co , Lakewood, CO	40-8434	6	Uranerz USA Inc. Casper WY	40-8783	y
Kawecki Berylco Industries Inc., Boyertown, PA	4()-694()	5	Uranium Resources, Inc. Richardson TX	40-8786	0)
Kerr-McGee Chemical Corp ,	40-2061	2	Western Nuclear Inc., Jettrey City, WY	10-1162	2
Oklahoma City, OK			Western Nuclear Inc., Lakewood CO	40-8684	8
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8027	5	Whittaker Metals, Los Angeles CA	40-7455	5
Kerr-McGee Nuclear Corp , Oklahoma City, OK	40-8586	7	Wyoming Fuel Co Lakewood CO	40-8829	ij
·	40 9727	o	Wyoming Mineral Corp. Lakewood, CO	40-8502	b
Kerr-McGee Nuclear Corp , Oklahoma City, OK	40-8727	8	Wyoming Mineral Corp., Lakewood, CO	40-8585	7
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8768	8	Domestic Licensing of Production Docket 50		
Maine Maritime Academy, Castine, ME	40-6499	4	Arkansas Nuclear One, Unit 1		

Name	Docket	Page	Name	Docket	Page
Arkansas Nuclear One Unit 2	50-368	269	Crystal River Nuclear Plant, Unit 3	50-302	127
Babcock & Wilcox Co. Crinical Facility	50-13	12	Davis-Besse Nuclear Power Station Unit I	50-346	234
Bailly Generating Station	50-367	269	Diablo Canyon Nuclear Power Plant Unit 1	50 275	85
Beaver Valley Power Station Unit 1	50-334	215	Diablo Canyon Nuclear Power Plant, Unit 2	50-323	167
Beaver Valley Power Station Unit 2	50-412	312	Donald C. Cook Nuclear Power Plant Umt I	50-315	144
Bellefonte Nuclear Plant, Umt 1	50-438	,179	Donald C. Cook Nuclear Power Plant. Unit 2	50-316	146
Belletonte Nuclear Plant, Unit 2	50-439	311	Dow Chemical Co	50-264	70
Big Rock Point Nuclear Plant	50-155	18	Diesden Nuclear Power Station Unit 1	50-10	10
Braidwood Station Unit 1	S1N-50-456	381	Diesden Nuclear Power Station Unit 2	50-237	33
Braidwood Station Unit 2	STN-50-457	384	Diesden Nuclear Power Station Unit 3	50-249	44
Brigham Young Univ. Research Reactor	50-262	68	Duane Arnold Pnergy Center	50-331	211
Browns Ferry Nuclear Power Station Unit 1	5()-259	57	Edwin l. Hatch Nuclear Plant, Unit 1	50-321	156
Browns Ferry Nuclear Power Station, Unit 2	50-260	61	Edwin I Hatch Nuclear Plant Umt 2	50-366	266
Browns Ferry Nuclear Power Station, Unit 3	50-296	119	Entico Fermi Atomic Power Plant, Unit 2	50-341	227
Brunswick Steam Electric Plant Unit 1	50-325	173	Floating Nuclear Plant	STN-50-437	339
Brunswick Steam Electric Plant   Unit 2	50-324	171	Lort Calhoun Station Unit 1	5()-285	100
Byron Station Unit 1	STN-50-454	370	Fort St. Vrain Nuclear Generating Station	50-267	74
Byron Station, Unit 2	SIN-50 455	376	GA Technologies	50-163	21
Callaway Plant, Unit 1	51N-50 483	400	General Atomic Co	50-89	15
Calvert Chits Nuclear Power Plant, Unit 1	50-317	148	General Flectric Nuclear Test Reactor	50-73	15
Calveri Cliffs Nuclear Power Plant, Unit 2	50-318	151	General Electric Fest Reactor	50-70	15
Catawba Nuclear Station Unit 1	50-413	314	Georgia Institute of Technology	50-160	21
Catawba Nuclear Station, Unit 2	50-414	320	Research Reactor		
CESSAR System 80	STN-50-470	396	Georgia Tech Research Reactor	50-276	90
Cherokee Nuclear Station Unit 1	S I N-50-491	F()4	GESSAR-238	STN-50-447	369
Cherokee Nuclear Station, Unit 2	STN-50-492	403	Grand Gult Nuclear Station Unit 1	50-416	324
Cherokee Nuclear Station, Unit 3	STN-50-493	4()3	Grand Gult Nuclear Station Unit 2	50-417	329
Chinton Power Station, Unit 1	50-461	394	H B Robinson Plant, Unit 2	50-261	65
Clinton Power Station, Unit 2	50-462	396	Haddam Neck Plant	50-213	26
Comanche Peak Steam Electric Station Unit 1	50-445	352	Hartsville Nuclear Plant, Unit 1	S1N-50-518	408
Comanche Peak Steam Electric Station	50 11c	341	Hartsville Nuclear Plant, Unu 3	STN-50-520	408
Unit 2	50-446	361	Hope Creek Nuclear Station Unit 1	50-354	253
Cooper Nuclear Station	50-298	122	Hope Creek Nuclear Station Unit 2	50-355	258
Cornell Univ. Research Reactor	50-157	21	Humboldt Bay Power Plant, Unit 3	50-133	16
Cornell Univ. Zero Power Reactor	50-97	16	klaho State Univ. Research Reactor	50-284	100

Name	Docket	Page	Name	Docket	Page
Indian Point Station Unit 1	50-3	ij	Oconee Nuclear Station Unit 1	50-269	76
Indian Point Station Unit 2	50-247	41	Oconee Nuclear Station   Unit 2	50-270	79
Indian Point Station Unit 3	50-286	101	Oconee Suclear Station Unit 3	50-287	103
Iowa State Univ. Research Reactor	50-116	16	Ohio State Univ. Research Reactor	50-150	۱۶
James A. Fitzpatrick Nuclear Power Plant	5()-333	213	Oyster Creek Nuclear Power Plant	50-219	28
Joseph M. Farley Nuclear Plant. Unit 1	50-348	237	Palisades Nuclear Plant	50-255	54
Joseph M. Farley Nuclear Plant, Unit 2	50-364	265	Palo Verde Nuclear Station Unit 1	\$15-50-528	409
Kansas State Univ. Research Reactor	50-188	22	Palo Verde Nuclear Station Unit 2	\$18-50-520	414
Kewaunee Nuclear Power Plant	50-305	142	Palo Verde Nuclear Station Unit 3	\$18.50-530	418
La Crosse Boiling Water Reactor	50-409	308	Peach Bottom Atomic Power Station Unit I	50-171	22
LaSalle County Station Unit 1	50-373	276	Peach Bottom Atomic Power Station. Unit 2	50-277	90
LaSalle County Station Unit 2	50-374	279	Peach Bottom Atomic Power Station, Unit 3	50-278	92
Limetick Generating Station Unit 1	50-352	238	Pennsylvama State Univ. Research Reactor	50-5	10
Limerick Generating Station Unit 2	50-353	246	Perry Nuclear Power Plant Unit I	50 440	343
Maine Yankee Atomic Power Plant	50-309	135	Perty Nuclear Power Plant Unit 2	5()-4-11	146
Manhattan College Research Reactor	50-199	23	Pilgrim Nuclear Power Station Unit 1	5()-293	112
Marble Hill Nuclear Station, Unit 1	\$18-50-546	422	Plum Brook Reactor-Mock-Up	50-185	22
Marble Hill Nuclear Station Unit 2	\$18-50-547	423	Phim Brook Research Reactor Facility	50-30	1-1
Memphis State Univ. Research Reactor	50-538	422	Point Beach Nuclear Plant Unit 1	50-266	72
Michigan State Univ. Research Reactor	50-294	115	Point Beach Nuclear Plant, Unit 2	50-301	124
Midland Plant, Unit 1	50-329	179	Prairie Island Nuclear Station, Unit 1	5()-282	98
Midland Plant   Unit 2	50-330	195	Prairie Island Nuclear Station, Unit 2	50-306	134
Millstone Nuclear Power Station Unit I	50-245	38	Purdue Univ. Research Reactor	50-182	23
Millstone Nuclear Power Station Unit 2	50-336	219	Quad-Cities Station Unit 1	50-254	52
Millstone Nuclear Power Station Unit 3	50-423	332	Quad-Cities Station   Unit 2	50-265	70
Montague Nuclear Power Station Unit I	50-496	403	Rancho Seco Nuclear Generating Station	50-312	130
Montague Nuclear Power Station Unit 2	50-497	403	RESAR SP 90	50-601	423
Monticello Nuclear Generating Plant	50-263	68	Rhode Island & Providence Plantations AEA	50-193	22
National Bureau of Standards Reactor	50-184	22	River Bend Station, Unit 1	50-458	388
National Naval Medical Center	50-170	22	River Bend Station Unit 2	50-459	302
Nine Mile Point Nuclear Station, Unit 1	50-220	31	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	36
Nine Mile Point Nuclear Station Unit 2	50-410	310	RPI Critical Experiment	50-225	3,3
North Anna Power Station Unit I	50-338	222	Salem Nuclear Generating Station, Unit 1	50-272	83
North Anna Power Station Unit 2	50-339	225	Salem Nuclear Generating Station, Unit 2	50-311	137
North Carolina State Univ PULSTAR Reactor	50-297	122	San Onolre Nuclear Station Unit 1	504206	23

Name	Docket	Page	Name	Docket	Page
San Onolie Nuclear Station Unit 2	50-361	260	Univ of Michigan Research Reactor	50-2	Ŋ
San Onofre Nuclear Station, Unit 3	50-362	262	Univ of Missouri Research Reactor	50-186	22
Seabrook Nuclear Station Unit 1	50-443	349	Univ of Missouri Research Reactor	5()-123	16
Seabrook Nuclear Station Umt 2	50-444	350	Univ of New Mexico Research Reactor	50 252	52
Sequovah Nuclear Plant Unit I	50-327	175	Univ of Oklahoma Research Reactor	50-112	16
Sequovah Nuclear Plant Unit 2	50-328	177	Univ of Texas Research Reactor	50-192	22
Shearon Harris Nuclear Power Plant Umt 1	50-400	302	Univ of Virginia Cavalier Reactor	5()-396	299
Shearon Harris Nuclear Power Plant Umt 2	50-401	306	Unix of Vugima Research Reactor	50-62	15
Shoteham Nuclear Power Station	50-322	159	Unis of Washington Research Reactor	5()-  39	17
Skagit Nuclear Power Project Unit I	50-522	408	Univ of Wisconsin Research Reactor	50-156	20
Skagit Nuclear Power Project Unit 2	50-523	409	Vermont Yankee Nuclear Power Station	50-271	81
South Texas Project Unit 1	S FN-50-498	404	Virgil C. Summer Nuclear Station, Unit 1	50-395	297
South Fexas Project Unit 2	STN-50-499	406	Vogtle Electric Generating Plant	50-424	113
St. Lucie Plant, Unit 1	50-335	217	Vogde Electric Generating Plant	50 425	336
St. Lucie Plant, Unit 2	50-389	291	Washington State Univ. Research Reactor	50-27	12
State Univ of New York Research Reactor	50-57	15	Waterford Generating Station Unit 3	50-382	283
Surry Power Station Unit 1	50-280	94	Watts Bar Nuclear Plant Unit 1	5()-39()	293
Surry Power Station Unit 2	50-281	97	Watts Bar Nuclear Plant Unit 2	50-391	295
Susquehanna Steam Electric Station, Unit 1	50-387	287	William B. McGuire Nuclear Station. Unit 1	50 369	272
Susquehanna Steam Electric Station, Umt 2	50-388	289	William B. McGuire Nuclear Station. Unit 2	50-370	274
Texas A&M Univ. Research Reactor	50-59	15	William H. Ziminer Nuclear Station, Unit 1	50-358	259
Three Mile Island Nuclear Station Unit 1	50-289	106	Wolf Creek Generating Station	STN-50-482	307
Three Mile Island Nuclear Station Unit 2	50-320	153	Worcester Polytechnic Research Reactor	5()-  3-	17
Trojan Nuclear Plant	50-344	231	WPPSS Nuclear Project, Unit 1	50-460	393
Turkey Point Plant, Unit 3	50-250	46	WPPSS Nuclear Project Umt 2	5()-397	200
Turkey Point Plant, Unit 4	50-251	<b>4</b> 9	WPPSS Nuclear Project, Unit 3	S I N-50-508	407
U S Geological Survey Research Reactor	50-274	85	WPPSS Nuclear Project, Unit 5	S EN-50-509	408
UC-Santa Barbara Research Reactor	50-433	338	Yankee-Rowe Nuclear Power Station	50-29	12
UCLA Training Reactor	50-142	17	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	423
Union Carbide Research Reactor	50-54	15	Yellow Creek Nuclear Plant Unit 2	S1N-50-567	423
Univ of California at Irvine Research Reactor	50-326	175	Zion Nuclear Power Station, Unit 1	50-295	115
Univ of Illinois Research Reactor	50-356	258	Zion Nuclear Power Station, Unit 2	50-304	129
Univ of Illinois Research Reactor	50-151	17	Domestic Licensing of Special Nuclear Materi	al — Docket 70	
Univ of Lowell Research Reactor	50-223	33	Babcock & Wilcox Co., Apollo, PA	70-0364	427
Univ of Maryland Research Reactor	50-166	21	Babcock & Wilcox Co., Lynchburg, VA	70-0824	428

Name	Docket	Page	Name	Docket	Page
Babcock & Wilcox Co - Lynchburg, VA	70-1201	430	Westinghouse Electric Corp., Pittsburgh, PA	70-1143	458
Babcock & Wilcox Co , Lynchburg VA	70-0027	424	Westinghouse Electric Corp - Pittsburgh - PA	70-1151	429
Battelle Memorial Institute, Columbus OH	70-0008	424	Yale-New Haven Hospital New Haven CI	70-2571	431
Battelle Memorial Institute, Richland WA	70-0984	429	ABCO Perforators Inc	71-0280	439
Berkshire Medical Center, Pittsfield MA	70-1450	431	Acurex Corp	71-0295	440
Carnegre-Mellon Univ , Putsburgh, PA	70-0303	427	Adirondack Steel Casting Co	71-0014	431
Cincinnati Gas & Electric Co , Cincinnati, OH	70-2838	431	Advanced Radiation Service	71-0132	435
Combustion Engineering, Inc., Windson CI	70-0036	425	Allied Inspection Services Inc	71-0330	4 12
Conuncice, Dept. of, Washington, DC	70-0398	427	Allis-Chalmers Corp	71-0221	437
Coratomic, Inc., Indiana, PA	70-1342	430	American X-Ray & Inspection Inc	71-0305	14()
Dentsply International, Inc. York, PA	70-2377	431	Amoco Oil Co	71-0128	435
Exxon Nuclear Co , Inc , Richland WA	70-1257	430	Applied Engineering Co	71-0294	44()
Florida, Univ. of, Gamesville, FL	70-1068	429	Arrow Lank & Engineering Co	71-0011	431
GA Technologies, Inc., San Diego, CA	70-0734	428	Associated Piping & Engineering Corp	71-0302	440
General Dynamics Corp., Groton, CT	70-0221	427	Babcock & Wilcox Co	71-0034	432
General Electric Co., San Jose, CA	70-1308	430	Babcock & Wilcox Co	71-0322	441
General Electric Co Wilmington, NC	70-1113	429	Bell Geophysics	71-0285	439
Gult States Utilities Co., Beaumont, TX	70-2998	431	Benjamin F Shaw Co	71-0223	438
Hahnemann Medical College & Hospital,	70-1362	430	Borg-Warner Corp	71-0028	432
Philadelphia, PA	74-12-024	11.0	Boston Edison Co.	71-0211	437
Kett-McGee Nuclear Cotp , Oklahoma City, OK	70-0925	428	BPB Instruments, Inc	71-0286	439
Kerr-McGee Nuclear Corp ,	70-1193	430	Brand X Perforators, Inc	71-0293	11()
Oklahoma City, OK			Buckeye Steel Castings	71-0110	434
Long Island Lighting Co , Hicksville, NY	70-2884	431	Bucyrus-Erie Co	71-0310	441
Maine Maritime Academy, Castine, ME	70-0466	427	California, Univ. of, I os Angeles, CA	71-0522	4-12
Massachusetts Institute of Technology, Cambridge, MA	70-0938	428	Capitol International Airways, Inc	71-0047	432
Nuclear Fuel Services, Inc., Erwin, TN	70-0143	425	Carson Non-Destructive Testing	71-0287	439
Passaic General Hospital, Passaic, NJ	70-1941	431	Certified Testing Laboratories	71-0066	433
Philadelphia Electric Co , Philadelphia, PA	70-2988	431	Chicago Bridge & Iron Co	71-0015	432
Rockwell International Corp., Canoga Park, CA	70-0025	424	Chicago Bridge & Iron Co Chicago Bridge & Iron Co	71-0104 71-0130	434 435
RS Holding, Inc., Cleveland, OH	70-2872	431	Columbia Gas Transmission Corp	71-0237	438
UNC Naval Products, Inc., Uncasville, CT	70-2371	427	Commonwealth Edison Co	71-0008	431
Union Carbide Corp., Tuxedo, NY	70-0687	428	Connecticut Yankee Atomic Power Co	71-0207	437
United Nuclear Corp ,	70-0087	428			437
Wood River Junction, RI	/V-V04U	740	Consolidated X-Ray Service Corp	71-0181	4.30

Name	Docket	Page	Name	Docket	Page
Consumers Power Co	71 0325	441	Howmet Turbine Components Corp	71-0329	441
Crane Co	71 0038	432	Hudson Products Corp	71-0317	441
Crane Co	71-0272	439	Huntington Testing	71-0093	434
CTL Engineering Inc	71-0301	440	Industrial Testing Laboratories Services Corp	71-0033	432
Cumberland Bridge Co	71-0218	437	Independent Testing Laboratories	71-0300	440
Curtiss-Wright Corp	71-01 <b>61</b>	436	Industrial Fabricating Co	71-0156	435
Daniel International Corp	71-0120	434	Industrial Gamma Inspection	71-0292	44()
Delta Airlines Inc	71-0281	439	Industrial Inspection Industries	71-0171	436
DJ Inspection Services Inc	71-0291	440	Industrial Laboratories, Inc.	71-0257	438
Duquesne Light Co	71-0275	439	Industrial NDI Services Division	71-0326	441
E Lewis Cook & Associates	71-0297	440	Ingersoll-Rand Co	71-0119	434
Ebasco Services Inc	71-0162	436	Intermountain Testing Co.	71-0213	437
Empire Steel Castings, Inc	71-0172	136	International Testing Laboratories	71-0020	432
Exxon Co USA	71-0057	433	Iowa Electric Light & Power Co	71-0296	440
Lactory Munual Engineering Corp	71-0270	439	IRT Corp	71-0247	438
Finley Festing Laboratories	71-0167	436	ITT Grinnell Corp	71-0036	432
Florida Power & Light Co	71-0169	436	ITT Grinnell Industrial Piping, Inc	71-0081	433
Foster Wheeler Energy Corp	71-0099	434	Labarge, Inc.	71-0134	435
Freehling & Robertson, Inc.	71-0157	435	Lakehead Testing Laboratories, Inc	71-0232	438
Gamma Field Radjographic Facility	71-0070	433	Law Engineering Testing Co	71-0242	438
Gamma Somes Examination Laboratories, Inc	71-0183	436	Lehigh Testing Laboratories, Inc.	71-0269	439
Gas Rentals, Inc	71-0214	437	Logwell, Inc.	71-0311	441
General Dynamics Corp	71-0154	435	Marathon Oil Co.	71-0318	441
General Dynamics Corp	71-0134	437	Material Testing Laboratories of Virginia, Inc.	71-0111	4.34
General Electric Co.	71-0059	433	Maynard Steel Casting Co.	71-0188	436
General Electric Co	71-0212	437	McManus Inspection Service	71-0188	439
General Electric Co	71-0254	438	Memphis Testing Services, Inc.	71-0303	440
General Testing & Inspection Co.	71-0319	441	Metallorms, Inc.	71-0303	441
Guyon Power & Process Piping	71-0319	438	Metals Testing Co., Inc.	71-0312	435
H R Inspection Service	71-0055	433	Midstate Testing Laboratory	71-0137	433
Harrison Steel Castings Co	71-00-5		Model. 20, 20A, 50, 50A, Gamma Industries		
Herron Testing Laboratories, Inc	71-0031	432	Model 51032-1 & 1A, Exxon Nuclear	71-9126 71-6581	443 442
Hess Oil Virgin Islands Corp		434	Co., Inc.	(1-0301	442
High Steel Structures, Inc	71-0151 71-0186	435	Model: 6244, Chem-Nuclear Systems, Inc.	71-6244	442
Houston Inspection Laboratories, Inc.		436	Model: 6717-B, Gamma Industries	71-6717	442
construction region and the file.	71-0124	434			

Name	Docket	Page	Name	Docket	Page
Model 750 Technical Operations, Inc.	71-9021	443	Newport News Industrial Corp	71-0022	432
Model 850, Technical Operations, Inc	71-9147	443	Nooter Corp	71-0113	434
Model 920, Fechnical Operations, Inc.	71-9143	443	Norfolk Shipbuilding & Dry Dock Co	71-0075	433
Model AP-300, ANEFCO, Inc	71-9188	444	North Dakota, State of	71-0288	439
Model, AP-300, ANEFCO, Inc	71-9192	444	Northeast Nuclear Energy Co	71-0208	437
Model CNS 3-55, Chem-Nuclear Systems, Inc	71-5805	442	Northern States Power Co	71-0083	433
Model CNS 6-80-2 & CNS 6-80-2A,	71-9111	443	Northwest Airlines, Inc	71-0016	432
Chem-Nuclear Systems, Inc	71-9111	77.7	Nuclear Energy Services Inc	71-0216	437
Model FSV-1, GA Technologies, Inc	71-6346	442	Nuclear Welding, Inc	71-0074	433
Model GE-100, General Electric Co	71-5926	442	O'Neill Fank Co , Inc	71-0233	438
Model GNG-20, Gulf Nuclear, Inc	71-9163	443	Omaha Public Power District	71-0256	438
Model, HN-100 Series 3, CNS 14-170	71-9151	443	Ozark Airlines, Inc	71-0063	433
Series III & NUS  Model, HN-300, Hittman Nuclear &	71-9092	1.12	Pacific Gas & Electric Co	71-0202	437
Development Corp	71-9092	443	Panhandle Eastern Pipe Line Co	71-0032	432
Model HN-400, Hittman Nuclear & Development Corp	71-9093	443	Philadelphia Electric Co	71-0056	433
Model 1F-300, General Electric Co	71-9001	442	Pittsburgh-Des Moines Steel Co	71-0320	441
Model NES-5, Nuclear Energy Services, Inc	71-9193	444	Portland General Electric Co	71-0327	441
Model. OH-142 Series & NUS 10-135,	71-9193	443	Power Authority of State of New York	71-0240	438
Nuclear Packaging, Inc.	11-9073	447	Precision Inspection, Ltd	71-0313	441
Model PAS-1, Nuclear Packaging, Inc	71-9184	443	Public Service Electric & Gas Co.	71-0328	441
Model S-6213, Energy, Dept. of	71-9186	443	Pullman Power Products	71-0184	436
Model TN-9, No Users	71-9016	442	Pullman, Inc.	71-0217	437
National Annealing Box Co	71-0127	435	QC Services, Inc.	71-0175	436
Navy Dept of	71-0087	434	Quality Assurance Laboratories	71-0168	436
Navy, Dept. of	71-0037	432	Quality Control Services	71-0299	440
Navy, Dept of	71-0089	434	Quality Testing, Inc	71-0205	437
Navy Dept of	71-0061	433	Smith-Emery Co.	71-0314	441
Navy, Dept of	71-0261	439	Snyder Drilling & Well Servicing	71-0306	441
Navy, Dept of	71-0245	438	Southern California Edison Co	71-0174	436
Navy, Dept. of	71-0133	435	Space Science Services, Inc.	71-0215	437
Navy. Dept of	71-0274	439	St Louis Testing Laboratories, Inc.	71-0222	437
Navy, Dept of	71-0268	439	Steel Tank Construction Co	71-0298	440
Navy, Dept. of	71-0276	439	Teledyne Brown Engineering Co.	71-0304	440
Navy, Dept. of	71-0225	438	Terex Corp.	71-0219	437
New York Testing Laboratories, Inc	71-0166	436	Terradata Geophysical, Inc.	71-0289	440

Name	Docket	Page	Name	Docket	Page
Festeo Inc	71-0125	435	Universal Testing Inc	71-0279	439
Texas Pipe Bending Co. of Puerto Rico	71-0307	441	Venegas Industrial Testing Laboratories Inc	71 0100	131
Thaver Inspection Service, Inc.	71-0145	435	Virginia Commonwealth of	71-0152	435
Foledo Edison Co	71-0195	437	Walworth Co	71-0039	432
Transworld Antines Inc	71-0080	433	Walworth Co	71-0140	435
Twin City Testing & Engineering	71-0103	434	WKM Wellhead Systems, Inc.	71-0282	430
Laboratories			Word Industries Pipe Fabricating, Inc	71-0229	438
fwin Ports Testing Inc	71-0253	438	X-Ray Industries Inc	71-0158	436
Ultrasonic Specialists Inc	71-0284	439	X-Ray, Inc	71-0234	438
United Airlines, Inc	71-0044	432	Yankee Atomic Electric Co	71-0068	433
United Engineers & Constructors, Inc.	71-01-48	435		71.000	7, 12,
United States Testing Co., Inc.	71-0095	434	Licensing of Independent Spent Fuel Storage — Docket 72		
United Testing Services, Inc.	71-0290	440	Morris Operations, General Electric Co	72-000 t	444
Universal Testing Laboratories	71-0105	434	Virginia Electric & Power Co.	72-0002	111

# DOCKETED ITEMS

#### LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 SHEFFIELD, IL, U S ECOLOGY, INC

8408060026 "Piezometers & Wells Trench 18 Monitoring Rept,Apr-June 1784 " W/840706 ltr ARMBRUST,A J U S Ecology, Inc (formerly Nuclear Engineering, Inc.) 84/06/30 SHAFFNER,J Division of Waste Management 2p; 25736 360

DOCKET 27-048 RICHLAND, WAI U B ECOLOGY, INC

8408010034 Forwards two oversize drawings showing proposed method of disposal of containers containing glove boxes contaminated w/Pu Method meets stability & intruder protection requirements of 10CFR61 Aperture cards in PDR SAUER.R E U.S Ecology, Inc (formerly Nuclear Engineering, Inc ) 84/07/24 SCHAFFNER, J Low Level Waste Licensing Branch 2pp 23872 328

#### DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0279 UNION CARBIDE CORP , GRAND JUNCTION, CO

- 8407230131 Confirms 840104 telcon reporting that level of liquor in low grade liquor collection pand lowered on 840103 & all flow into monitor drain ceased on 840104 Plastic liner will be repaired as weather allows Withheld LYONG.P J Union Carbide Corp 84/01/06 CAIN.C L Region 4, Office of Director ip 26255 335
- 8408270188 Informs of 500-gallon spill of tallings water to restricted area at Gas Hills Mill on 840522 Pipeline shutdown until repair made Mine spoils affected LYONS, P.J. Union Carbide Corp. 84/06/14 GARCIA,P.J. Uranium Recovery Field Office. 2pp. 26277 318
- 8408060383 Application for amend to License SUA-648 requesting variance from License Condition 47, allowing disposal of 247,000 tons of tailings during 1984 One oversize map encl Aperture card available in PDR
  LYONS, P. J. Union Carbide Corp. 84/06/29 GARCIA, P. Uranium
  Recovery Field Office. 2pp. 25951 355
- 840B280399 Forwards maps showing temporarily installed surface line extending from Standpipe 10 to Standpipe 16 in order to mitigate operation of buried line w/o monitor stations W/two oversize maps Aperture cards available in PDR LYONS.P J Union Carbide Corp 84/07/09 GARCIA.P Uranium Racovery Field Office. 2pp 26299 361
- B40B240344 Informs that final rept on 840604 spill of heap leach liquor at Umetco Mineral Corp Ges Hills Mill will not be issued until all Ra-226 analyses on soil samples received. Analyses should be available by 840720 LYONS, P J. Union Carbide Corp 84/07/10 PETTENGILL, H Uranium Recovery Field Office ip 26253 312
- 8408240412 Forwards water level exaluation repts for monitor wells near A-9 seepage collection sys Diagrams encl LYDN8,P J Union Carbide Corp. 01253 84/07/10 PETTENGILL,H Uranium Recovery Field Office 23pp. 26248 286.
- 8408240396 Forwards quarterly rept for Second Quarter 1984 re A-9 collection drip sys Control of acid drip to sys has not been optimum Request to use micrometering valves in place of bellows metering pumps will be submitted LYQNG; P J Union Carbide Corp 84/07/17 GARLAND, W L. Wyoming, State of 3pp. 26248,343
- --8408240400 Rept for Second Guarter 1784 re A-9 collection drip sys \* Union Carbida Corp 84/06/30 11pp 26248.346

- 8408270120 Advises that submittal of final rept on stability of inactive tailings will be delayed until mid-Sept 1984 Hater. Waste & Land. Inc 840605 ltr encl LYONS.P J Union Carbide Corp 84/07/18 GARCIA.P Uranium Recovery Field Office 2pp 26277 352
- 8408240384 Advises of steps taken to address license compliance deficiencies deviations & areas of concern from NRC 840619-22 insp.per 840622 closeout meeting Revised shift record sheet printed for use in dryer operation section LYONS,P J Union Carbide Corp 84/07/23 SMITH,R D Uranium Recovery Field Office 10pp 26254 304
- B408270064 Reviews Union Carbide Corp rept re seepage leaving impoundment, deterioration of groundwater & hydrology near inactive teilings Addl review of groundwater & reclamation activities recommended KONMINEKI & R. PETTENGILL, H.J. Uranium Recovery Field Office. Spp. 26278 345
- 8408240213 Informs of issuance of Amend 24 to License SUA-648 revising Condition 42 Amend incorporates berm sump monitoring program & deletes certain requirements no longer necessary SMITH.R D. Uranium Recovery Field Office 84/07/25 Union Carbide Corp. 2pp. 26254-356
- 8408270037 Recommends issuance of Amend 24 to License SUA-648 re berm sump monitoring programs, deleting unnecessary requirements by revising Condition 42 GARCIA.P J. PETTEMOILL.H J. Uranium Recovery Field Office 84/07/25 Uranium Recovery Field Office ip 26258:337.
- 8408240018 Forwards riders for Permits 349c & 33Ac-L2, changing name to Umetco Minerale Corp LYONS,P J Union Carbide Corp 84/07/27 BDSCO,C Wyoming, State of 7pp 24284 291
- 8408270077 Forwards 840606 rept on heap leach liquor spill W/one oversize map Apenture card available in PDR LYONS.P J Union Carbide Corp. 84/07/27 PETTENGILL.H. Uranium Recovery Field Office 8pp 26278 148
- 8408240185 Recommends issuance of Amend 25 to License 8UA-64B, revising Condition 47 to variance for Tailings Area A-9, per licenses 840629 request OARCIA.P J, PETTENGILL.H J Uranium Recovery Field Office 84/08/02 Uranium Recovery Field Office 3pp 262551266
- 8408270487 Advises of issuance of Amend 25 to License 8UA-648, revising Condition 47 re disposal of 1,600,000 tons of tailings in A-9 tailings area SMITH.R D Uranium Recovery Field Office 84/08/02 Union Carbide Corp 1p 26277.043.
- 8408240187 Recommends issuance of Amend 26 to License BUA-648, changing name in Condition I to Umetco Minerals Corp to reflect corporate reorganization per 840301.02,20 to 0727 ltrs.
  8HOPENNN M PETTENGILL. H. J. Uranium Recovery Field Office 84/08/06 Uranium Recovery Field Office 2pp 26254 361
- 8408270334 Advises of issuance of Amend 26 to License SUA-648, revising Condition i re name change.

  SMITH.R P Uranium Recovery Field Office 84/08/06 UMETCO Minerals Corp (subs of Union Carbide Corp.) ip. 26277.239
- 8408240192 Informs that Amend 27 to Licensa 8UA-648; issued 840807 to change tailings line insp from monthly to quarterly, exempt from fees
  JIERREE, C C., PETTENGILL, H J Uranjum Recovery Field Office
  84/08/07 MILLER, W O License Fee Management Branch Ip.
  26293 235

- ---B408240197 Recommends issuance of Amend 27 to License SUA-648, changing monthly testing to quarterly JIERREE,C C , PETTENGILLH J Uranium Recovery Field Office B4/08/07 Uranium Recovery Field Office Ip 26255 256
- --8408240201 Issues Amend 27 to License SUA-648 changing testing from monthly to quarterly per 840619-22 insp SMITH:R D. Uranium Recovery Field Office 84/08/07 UMETCO Minerals Corp. (subs. of Union Carbide Corp.) ip 26255-237
- B408240163 Advises that Amend 28 to License SUA-648 issued B40808 erempt from fees
  GARCIA:P J . PETTENGILL, H J Uranium Retovery Field Office
  B4/0B/0B MILLER, H D License Fee Management Branch ip
  26254 258
- --B40B240166 Advises of issuance of Amend 2B to License SUA-648 revising address SMITH.R D Uranium Recovery Field Office 84/08/08 UNETCO Minerals Corp (subs of Union Carbide Corp ) Ip 26254 259
- 8408240380 Presents review of Union Carbide Corp 1983 environ monitoring data for East Gas Hills Mill Licensee 830831 & 840228 submittals indicate sampling & analysis performed as required by License Condition 58 GARCIA:PJ. PETTERMILL:HJ Urranium Recovery Field Office 84/08/09 Uranium Recovery Field Office 5pp 26254 323
- 8408240116 Discusses request for amend to License SUA-648 re-compaction of clay cap matl Amend 29 should require 90% compaction of clay cap & soil cover matl four field density tests & submittal of const rept within 1 months of const completion OARCIA:P J Uranium Recovery Field Office 84/08/14. Uranium Recovery Field Office 44pp 26254 262
- 84082700AB Summarizes Umetco Minerals Corp 840604 ltr re 840522 tailings line spill at East Oas Hills Mill Spill of approx 500 gallons of tailings liquid resulted from crack in flange of pipeline Repair made Area will be reclaimed OARCIA.P J , PETTENOILL.H J Uranium Recovery Field Office 84/08/14 Uranium Recovery Field Office 2pp 26278 350
- 8408280005 Advises of issuance of Amend 29 to License 8UA-548, revising Condition 67 re const specs for placement of reclamation cover on inactive tailings area SMITH.R D Uranium Recovery Field Office 84/08/14 UMETCO Minerals Corp (subs of Union Carbide Corp ) 2pp 26293 360
- DOCKET 40-0572 NUCLEAR METALS, INC., CONCORD, MA
- 8408270283 Forwards Insp Repts 40-0472/84-01 & 30-17374/84-01 on 840616-19 MARTIN.T T Division of Engineering & Technical Programs 84/08/09 TUFFIN.W B Nuclear Metals. Inc 2pp 26256 241
- --8408270277 Insp Repts 40-0672/84-01 & 30-19374/84-01 on 840616-19 Violations noted employee exposure in excess of NRC limits, contamination on trailer in excess of BDT regulations & failure to self-monitor for contamination on erit ROME.C., THOMPSON.T., KINNEMAN.J. Region 1, Office of Director 84/08/09 3pp 26236-243
- DOCKET 40-0791 UNITED TECHNOLOGIES CORP . EAST HARTFORD, CT
- 8408230193 Ack receipt of 840410 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-0791/84-01. Actions will be examined during future insp MARTIN.T T Division of Engineering & Technical Programs 84/08/17 BALADUER, J P United Technologies Corp. 2pp. 26209 244
- --B40B230198 Responds to NRC 840321 ltr re violations noted in IE Insp Rept 40-0791/84-01 Corrective actions transfer of mickel-thoria waste to Suisman & Blumenthal discontinued in March 1983 PARSONS, Q E United Technologies Corp 84/04/10 MARTIN, T T Division of Engineering & Technical Programs ip 26209 246
- DOCKET 40-1162 WESTERN NUCLEAR, INC , JEFFREY CITY, WY
- 8408270131 Forwards rept to semiannual audit/ALARA proceedings on 840326-29, per License Condition 43
  BOODEN.O Mestern Nuclear. Inc. (subs of Phelps Dodge Corp.) 84/05/10 PETTENGILL.H J Uranium Recovery Field Office 21p. 26277.331

- 9408240186 Informs of issuance of Amend 20 to License SUA-56, revising License Conditions 11 & 61 Amend authorizes changes in air sampling frequencies, instrument calibr procedures & other radiological requirements
  SMITH R D Uranium Recovery Field Office 84/07/18 BOGDEN, G Western Nuclear, Inc (subs of Phelps Dodge Corp ) 2pp 26255 264
- 8409240324 Discusses Amend 20 to License SUA-56 re air sampling frequencies, instrument calibr procedures & other radiological monitoring requirements Proposed mods listed MONINSKI, GR Uranium Recovery Field Office 84/07/18 Uranium Recovery Field Office 7pp 26253 340
- 8408240345 Responds to 840428 ltr detailing this of heap leach & forwards documentation re reclamation program Licensee has fulfilled reclamation requirements Neeting planned w/ licensee re site visit & further action W/o encls PETTENGILL. H J Uranium Recovery Field Office 84/08/02 MOXLEY, M Myoming, State of 2pp 24253 310
- 8408270047 Trip rept of 840601 site visit w/Western Nuclear re pumpback wells tailings impoundment & associated alluvial valleys KONNINSKI, 0 R., PETTENGILL.H J. Uranium Recovery Field Office B4/08/02 Uranium Recovery Field Office 2pp 26298 313
- 8408270220 Reviews First Guarter 1984 water quality sampling results for Split Rock Mill.submitted in compliance w/License Conditions 23,25 & 31 KOHINSKI, G R Uranium Recovery Field Office 84/08/02 Uranium Recovery Field Office 5pp 26277 309
- 8408270063 Reviews Western Nuclear semiannual audit/ALARA rept for Split Rock V Mill, submitted per License Condition 43 KCNWINSKI,OR Uranium Recovery Field Office 84/08/07 Uranium Recovery Field Office 2pp 26277 362
- 8408270033 Trip rept of 840809 site visit w/American Nuclear Corp & Btate of WY Mining District re heap leach locations KONWINBKI.G R, PETTENGILL.H J Uranium Recovery Field Office 84/08/14 Uranium Recovery Field Office 4pp 26258 343
- DOCKET 40-1341 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN
- 8408240211 Forwards, for execution, DDE/TVA interagency agreement for disposal of residual radioactive matts removed by DDE from Edgement, SD vicinity Agreement subj to NRC & State of SD concurrence
  HILL, TV Energy, Dept of 84/03/31 DONDVAN, TK Tennessee Valley Authority 12pp 26255 157
- B408270036 Bummary of 840711 meeting w/TVA at Recovery Field Ofc re project schedule rev to Edgemont Decommissioning Project BRICH:R F Uranium Recovery Field Office 84/07/26 Uranium Recovery Field Office App 26278 354
- B408240391 Presents review of TVA 10CFR40 65 environ manitoring rept for Edgement Mill for Nov 1982 - Oct 1983 Util has not followed license requirements precisely re-sediment monitoring program Corrective action taken BRICH-R F Uranium Recovery Field Dffice 84/08/08 Uranium Recovery Field Office 5pp 26249 355
- DOCKET 40-2061 KERR-MCGEE CHEMICAL CORP , OKLAHOMA CITY, OK
- 8408010244 Requests info re removal of thorium from Reed-Keppler Park & ganitary treatment plant CUNNINGHAM, RE Division of Fuel Cycle & Material Safety DSB 656 84/07/26 RENNELS: A E Chicago, IL Spp 25856 006
- B408030183 Amends license to permit onsite receipt of contaminated matl in accordance w/city of West Chicago-Kerr-McGee agreement Procedures for removal & transport of radwaste discussed CUNNINGHAM, R E Division of Fuel Cycle & Material Safety B4/07/26 RENNELS, A E West Chicago, IL 3pp 25917-356
- B408060023 Requests listed info.should Kerr-McGee decide to move therium from Reed-Koppler Park & sanitary treatment plant GUNNINGHAM.R E Division of Fuel Cycle & Material Safety 84/07/26 RICE.G Kerr-McGee Corp 4pp 25937 OOI
- B408150062 Response supporting Nichiren Shoshu Temple (NST) & People of State of IL petition for leave to intervene, subj to limiting Contention I to radiological matters & NST submission of one admissible contention Certificate of Svc encl CUCCO.L M Regional Operations & Enforcement Division BURNS, S. 9 Regulations Division. B4/07/30 Atomic Safety and Licensing Board Panel. 18pp 26104.319.

- 8408070311 Notices of appearance in proceeding Syc list encl RAPKIN.A. BARZANO.W J Illinois. State of DSB 787 84/08/02 4pp 25947 338
- B40B070294 Motion for extension of time until 840915 for all parties to respond to requests for admissions, interrogatories & requests for documents Certificate of Svc encl MESERVE, R A Kerr-McGee Chemical Corp (subs of Kerr-McGee Curp ) DBB 800 84708703 Atomic Safety and Licensing Board Panel 5pp 25948 073
- 8408070482 Forwards motion for extension of time W/o encl Related correspondence MESERVE.R A Covington & Burling MESERVE.R A Kerr-McGee Corp DSU 799 84/08/03 Docketing & Services Branch Ip 25941 21
- B408080235 Motion for extension of time until 840915 for all parties to respond to requests for admissions to interrogatories & to requests for documents Granted for ASLAB on 840806 Served on 840807 MESERVE, R A Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) MESERVE, R A Covington & Burling DSB 830 84/08/03 Atomic Safety and Licensing Board Panel 3pp 25967 050
- 8408080173 Forwards suppl to 840711 petition for leave to intervene Nichiren Shoshu Temple welcomes ASLD decision to tour Kress Creek & visit property PROTO,N T Kelley Drye & Warren PROTO,N T Nichiren Shoshu Temple DSB 827 84/08/06 FRYE,J H Atomic Safety and Licensing Board Panel 4pp 25959 004
- --8408080180 Suppl to 840711 petition for leave to intervene Nichiren Shoshu Temple requests contentions be admitted & petition for leave to intervene be granted Certificate of Svc encl PROTO, N T Nichiren Shoshu Temple PROTO, N T Kelley Drye & Warren 84/08/06 Commissioners 14pp 25959 008
- B40B200603 Responds to B40724 ltr re remedial investigation/feasibility study (RI/FS) for vendor radiation sites Vendor considers any implementation of work plan unlawful & unwarranted duplication of previous scientific surveys RICE: 0 B Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp ) DSB 160 B4/08/06 CONSTANTELOS, B Environmental Protection Agency Spp 26137 136
- 8408130329 Motion for leave to file reply brief instanter Motion due 840806, but due to difficulties w/word processing equipment, final printout of brief unavailable until 840807 RAPKIN.A , BARZAND,W J Illinois. State of DSB 907 84/08/07 Atomic Safety and Licensing Board Panel ip 26007 001
- ---8408130337 Reply brief responding to Kerr-McGee & staff briefs on People of State of IL contentions, including Kerr-McGee supplemental memorandum on Contentions 2(u) & (w) RAPKINA : GARZANO, W J Illinois, State of 84/08/07 Atomic Safety and Licensing Board Panel 85pp 26007 002
- 840B170310 Provides director w/items of interest Items include 840B22 conference for Kress Creek in Chicago, IL re consolidation of Kress Creek & main plant & 840713-24 visit to Madrid, Spain to view new LHR fuel fabrication facility PAGE, R 9 Uranium Fuel Licensing Branch 84/08/09 DAVIS, J 9 Office of Nuclear Material Safety & Safeguards, Director 1p 24134, 197
- 8408170383 Motion for leave to file Contention 2(x) re long-term radiological impacts resulting from onsite disposal & second discovery request Related correspondence RAPKIN, A Illinois, State of DSB 098 84/08/15 Atomic Safety and Licensing Board Panel 2pp 26128 244
- --8408170387 First set of interrogatories & request for documents Related correspondence
  RAPKIN.A Illinois, State of 84/08/15 Office of the
  Executive Legal Director 7pp 26128 246
- ---8408170389 Second set of interrogatories & request for documents Proof of Svc & svc list encl Related correspondence RAPKIN.A Illinois, State of 84/08/15 Kerr-McGee Chemical Corp. (subs of Kerr-McGee Corp ) App. 26128
- 8408170376 Amend to 840710 petition for leave to intervene, amending Contention 3 to adding Contention 6 re liability of Kerr McGes to clean up Kress Creek contamination Proof of Svc & svc list encl
  RAPKIN,A Illinois, State of DSB 097 84/08/15 Atomic Safety and Licensing Board Panel 5pp 26128 239

- B408230055 Submits items of interest re Whittaker Corp.Greenville.PA. EIAs & Kerr-McGoe - Oklahoma PAGE.RG Ovanium Fuel Licensing Branch B4/08/14 DAVIS.J G Office of Nuclear Material Safety & Safeguards.Director 2pp 32074 288
- B408220351 Notice of appearance in proceeding Certificate of Syc enci LUBLINSKI, M. Nichiren Shoshu Temple LUBLINGKI, M. Kelley Drye & Warren DSB 192 84/08/17 4pp 26189 351
- 8408270189 Transcript of 840822 hearing in Chicago. IL. Pp 220-244 \* Atomic Safety and Licensing Board Panel 84/08/22 45pp 26240 218
- 8408270445 Transcript of 840822 hearing in Chicago.IL redecontamination Pp 1-61 \* Atomic Safety and Licensing Board Panel 84/08/22 61pp 26237 160
- 8408290008 Contention 2(x) re inaccuracy of applicant & NRC assessments of post-closure radiation doses & applicant failure to demonstrate that doses will be low enough to adequately protect public Proof of svc encl RAPKIN.A Illinois, State of DSB 353 84/08/22 Atomic Safety and Licensing Board Panel 4pp 26291 282
- DOCKET 40-2259 PATHFINDER MINES CORP , RIVERTON, WY
- 8408200400 Responds to 840419 ltr re discontinuance of any free surface flow of solutions across surface of tailings impoundment Engineering plan encl Surface flow reduced, per 840413 discussion NUGENT. E. L. Pathfinder Mines Corp. 84/06/29 PETTENGILL, H. Uranium Recovery Field Office ip 26141 194
- --8408200401 "Proposed Program for Cessation of Mill Yard Drainage to Tailings Pond 1 at Lucky McMine, Qas Hills, WY " \* Pathfinder Mines Corp 84/06/30 15pp 26141 195
- B40B240181 Informs of issuance of Amend 19 to License BUA-672, adding Condition 39 Amend diverts mill yard draining from Tailings Pond 2A Proposed program to be operational by B41201
  SMITH,R D Uranium Recuvery Field Office 84/07/26 NUGENT,E L Pathfinder Mines Corp 1p 26255 270
- B40B270041 Recommends issuance of Amend 17 to License BUA-612 by adding Condition 59 recessation of mill yard dvainage.

  KONHINSKI.O R , PETTENGILL, H J Uranium Recovery Field Office 3pp 26258-330
- 8408270093 Forwards two 200-scale topographic maps.covering Lucky Mc tailings area.per request Wells C-8.T2-4 & T2-33 added to tailings monitor well sys W/o maps HARDORDUMET W Pathfinder Mines Corp 84/07/27 KONWINBKI.G. Uranium Recovery Field Office ip 26277 290
- 8408210110 Forwards IE Insp Rept 40-2259/84-01 on 840528-0601 & notices of violation & deviation PETTENGILL, H J Uranium Recovery Field Office 84/07/31 Pathfinder Mines Corp 2pp 26184 174
- --8408210111 Natice of violation from insp on 840528-0601 \* Region 4, Office of Director 84/07/31 2pp. 26184 176
- --8408210114 Natice of deviation from insp on 840528-0601 \* Region 4, Office of Director 84/07/31 lp 26184:178
- --8408210120 IE Insp Rept 40-2259/84-01 on 840528-0401 Violations noted, failure to establish std operating procedures for air sampling, failure to calibr airborne samples quarterly & failure to perform weekly documented insps of Ore piles GARCIA, P. J. JIERREL, C. C. SPITZBERG, D. B. Region 4, Office of Director 84/07/31 lipp 26/84 179
- 8408240413 Forwards statistical data for source term evaluation program HARDBROVE, T. W. Pathfinder Mines Corp. 84/08/02 JIERREE, C. Uranium Recovery Field Office 11pp 26248 275.
- 8408240414 Forwards addendum to application for renewal of License 8UA-672 describing proposed renovation program. NUGENT, E.L. Pathfinder Mines Corp. 84/08/02 PETTENGILL, H. Uranium Recovery Field Office ip 26237-244
- --8408240419 Addendum to application for renewal of License SUA-672, describing proposed removation program for Lucky McMill.

  \* Pathfinder Mines Corp. 84/08/31, 21pp. 26237:245

# DOCKETED ITEMS

- DOCKET 40-3392 ALLIED CHEMICAL CORP , MORRISTOWN, NJ
- 8408130240 Submits add1 info re application for renewal of License BUB-526, concerning UF6 product cylinders within plant, per telcon Three operating options to reduce handling of each full cylinder listed CIPOLLA:A J Allied Chemical Corp 84/07/09 KOSLA:B M Uranium Fuel Licensing Branch 5pp 26040 358
- 8408130273 Advises that during Second Guarter 1984 average airborne radioactivity measured at meanest residence sampling station exceeded concentration action level specified in Amend 4 to
  - license CIPOLLA:A J Allied Chemical Corp 84/07/19 Office of Nuclear Material Safety & Safeguards.Director 2pp 26040 341
- 8408170395 Forwards corrected Page C-11 of application for renewal of License 508-326 reflecting conditions at one concentrate CIPOLLA: A J Allied Chemical Corp 84/08/01 KDSLA, B M Uranium Cirol Licansino Branch 2pp 26/34 182

# DOCKET 40-3453 ATLAS MINERALS, INC . DENVER, CD

- B40B270044 Reviews Second Half 1983 environ monitoring rept for Moab Mill submitted per License Condition 43 & 10CFR40 65 SHOPENN,N M , PETTENGILL H J Uranium Recovery Field Office 84/07/19 Uranium Recovery Field Office 5pp 2625B 315
- 8408270062 Summarizes 840223 tailings reclaim line rupture during routine weekly cleaning operation Approx 5.000 gallons of tailings solution released Area cleaned Berm will be constructed to retain any future leaks
  SHOPENN,N.M. PETTENOILL,N.J. Uranium Recovery Field Office.
  84/07/25 Uranium Recovery Field Office 2pp 26278 352
- 8408240056 Submits annual technical evaluation of Embankment performance.per License Condition 52(2) BLUBAUGH.R E. Atlas Minerals, Inc. 84/07/26 BMITH,R.D. Uranium Recovery Field Office 7pp 26255 327
- B40B270235 Reviews annual technical evaluation of embankment performance for Mosb Mill.submitted in compliance w/License Gondition 52
  KONMINSKI.0 R Uranium Recovery Field Office 84/08/10
  Recovery Field Office 2pp 26277 236 Uranium
- 8408240190 Discusses Amend id to License SUA-917, revising in-plant radiological monitoring & environ monitoring programs
  License should be amended by deleting Conditions 30 & 39 & revising Conditions 12, 25, 28 & 37
  BHOPENNIN H . PETYENVILL. H J Uranium Recovery Field Office
  84/08/14 Uranium Recovery Field Office 6pp 26255 258
- 1408280023 Advises of issuance of Amend 16 to License SUA-917, deleting Conditions 30 & 39 & revising Conditions 12,25,28 & 37 redaily visual surveillance of mill area to insure proper implementation of good radiation safety practices SMITH.R D Uranium Recovery Field Office 84/08/14 Atlas Hinsrals, Inc. 3pp. 26293 332
- 8408240142 Recommends approval of request to amend License SUA-917, authorizing disposal of contaminated solid wastes in sump collection pond south of main tailings disposal area SHOPPEN.N M . PETTENGILL.H J Uranium Recovery field Office Spp 26253 359
- 8408270482 Advises of issuance of Amend 17 to License SUA-917, changing License Condition 56 re disposal of matls w/o authorization of U Recovery Field Ofc SHITH.R.D Uranium Recovery Field Office. 84/08/15 Atlas Minerals, Inc. 2pp 26277-064

# DOCKET 40-4492 FEDERAL-AMERICAN PARTNERS, RIVERTON, WY

- 8408310338 Forwards delayed response to 830410 ltr re Amend 14 to to allowers the stage of response to usual to the reamend a License SUA-6A7 adding License Condition AO Delay due to Impending new EPA stds codified after issuance of Amend 14. Witwo oversite maps Aperture cards available in PDR ANDRUGN J. American Nuclear Corp. 84/05/02 EMITH, R.D. Recovery Field Office. 15pp. 26/350.109 SHITH, R. D. Uranium
- 8408270104 Forwards permit transfer approvals.per request Present bond deficient traise of figure proposed ENGELMANN:R Hyoming: State of. 84/06/04 GARCIA:P Uranium any Field Office 11pp. 26278:303

- 8408240174 Comments on 840604 cost estimates for American Nuclear Corp Gas Hills.WY Mill decommissioning & tailings area reclamation PETTENGILL.H J Uranium Recovery Field Office 84/07/10 MOXLEY,M Wyoming, State of 2pp 24255 271
- 8408240379 Forwards 840628 annual insp rept re Permits 3230,352,436 & 438 Rept summarizes reclamation & remedial action projects requiring completion in 1984 Revised bonds requested within 30 days MOXLEY,M Wyoming, State of 84/07/11 ANDRUS,N American Nuclear Corp 10pp 26248 328
- 840B270361 Forwards corrected copy of analysis for U308 & calculations re max burden that could have been received by employees collecting samples, per request ANDRUS, N J American Nuclear Corp 84/07/31 SHOPENN, M Uranium ANDRUS, N J American Nuclear Corp 84/07/31 SHOPENN, M Uranium Racovery Field Office 3pp 26277 227
- 8408240182 Advises that manhours expended on Amends 15 & 16 to License 8UA-667, issued 831228 & 840517, respectively, should be incorporated into time charged to ANC reclamation plan
  Manpower rept forthcoming
  PETTENGILLH J Uransum Recovery Field Office 84/08/02
  WEISS, D J License Fee Management Branch 1p 26255 269
- 8408210129 Forwards IE Insp Rept 40-4492/84-01 on 840618-19 & notices of violation & deviation PETTENGILL.H J Uranium Recovery Field Office 84/08/03 COX.E J American Nuclear Corp 2pp 26184 143
- --8408210131 Notice of violation from insp on 840618-19 \* Region 4. Office of Director 84/08/03 ip 26184 145
- --8408210134 Notice of deviation from insp on 840418-19 \* Region 4, Office of Director 84/08/03 2pp 26184 146
- --B40B210E43 IE Insp Rept 40-4492/84-01 on B4061B-19 Violations & deviations noted employee exposures not accurately determined inspectors not instructed to self-monitor after exiting mill & restricted boundary not replaced SHOPENN.N M . GARCTA.P J . JIERREE.C C Region 4. Office of Director B4/0B/03 4pp 26184 148
- 8408270033 Trip rept of 840809 site visit w/American Nuclear Corp & State of WY Mining District re heap leach locations KONMINSKI.G R , PETTENGILL.H J Uranium Recovery Field Office 84/08/14 Uranium Recovery Field Office 4pp 2628 343

#### DOCKET 40-6499 MAINE MARITIME ACADEMY, CASTINE, ME

- 840B010397 Discusses IE inep of Licenses SNM-493 & SUD-283 on 840614 & forwards notice of violation MARTIN.T T Region i, Office of Director 84/07/19 CUKIERSKI,M W Haine Maritime Academy, Castine, ME 2pp 25866 053
- --B408010400 Notice of violation from insp on 840614 Violation noted yearly calibr of survey meters undocumented monthly exchange of film badges not performed & sealed sources not tested for Region 1. Office of Director 84/07/19 1p 25866 055
- DOCKET 40-4500 ENERGY, DEPT OF, CANONSBURG, PA
- 840B150193 Forwards Mod A003 to Cooperative Agreement DE-FC04-B2AL19487 between DDE & Commonwealth of PA Mod reflects std format being negotiated w/other affected states HILL: TV Energy, Dept. of. 84706/27 HIGGINBOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch 5ipp 26104 067

#### DUCKET 40-6622 PATHFINDER MINES CORP , SHIRLEY BASIN, WY

- 840B060326 Requests extension to 840B13 for submitting proposal to mitigate sespage from tailings pond.per 840308 ltr.due to necessary addl field work, including drilling 14 holes to define geological extent of surficial aquifer RUSBELL.J E Pathfinder Mines Corp. 84/06/13 PETTENGILL, H J Uranium Recovery Field Office 3pp. 28978 201
- 8408240334 Responds to notice of violation from insp on 840527-31 Corrective actions fill matl placed in four embankment areas threatened by erosion & tailings discharge line constructed RUBBELL, J E Pathfinder Mines Corp. 84/07/11 PETTINGILL, H J Uranium Recovery Field Office ip 26253 332

- 8408240347 Accepts licensee commitment to submit mitigative action plan by 840815.per 840613 ltr Program will utilize hydrological data from two wells.per 840712 telicon PETTENGILL.H J Uranium Recovery Field Office 84/07/25 RUSSELL.J Pathfinder Mines Corp 1p 24233 204
- 8408240340 Ack receipt of 840711 ltr responding to 840705 notice of violation Corrective actions will be examined at future insp PETTENGILL.H J Uranium Recovery Field Office 84/08/03 POYSER.R W Pathfinder Mines Corp ip 26253 318
- DOCKET 40-4659 GETTY BIL CO PETROTOMICS CO , SHIRLEY BASIN, WY
- B408240336 Responds to 840620 notice of violation Corrective actions personnel briefed on respirator incident & trained during refresher course & procedure established to insure pressure readings properly recorded W/a stated procedure HHITMAN, J H Getty/Petrotomics Co 8407/11 PETTENGILL, H J Region 4. Office of Director 2pp 26253 323
- 8408240346 "Radioactive Airborne V Dust Samples,840507" PFAFF,8 J Getty/Petrotomics Co 84/07/11 PETTENGILL,H J Uranium Recovery Field Office 2pp 26253 201
- 8408270022 Ack receipt of 840711 ltr informing NRC of steps taken to correct violations noted in 840620 notice of violation Corrective actions to be examined at future insp PETTERGILL.H J. Urantum Recovery Field Office. 84/08/03 WHITMAN.J H. Getty/Petrotomics Co. 1p 26258-356
- DOCKET 40-6940 KAWECKI BERYLCO IND . INC , BOYERTOWN, PA
- B40B090319 Forwards request for addl info re proposed groundwater monitoring program CROW-W T Uranium Fuel Licensing Branch 84/08/03 CDYLE,F T Kawecki Berylco Industries, Inc 2pp 25984 350
- DOCKET 40-7455 WHITTAKER METALS, LOS ANGELES, CA
- 8408230055 Submits items of interest re Whittaker Corp.Oreenville.PA. EIAs & Kerr-McGes - Oklahoma PAGE.R 0 Uranjum Fuel Licensing Branch 84/08/16 DAVIS.J 0 Office of Nuclear Material Safety & Safeguards.Director 2pp
- DOCKET 40-7869 PLATEAU RESOURCES, LTD , GRAND JUNCTION, CO
- B408240371 Informs of resignation of radiation safety officer, effective B40807 GERDEMAN, F W Plateau Resources, Ltd B4/07/31 SMITH, R D Uranium Recovery Field Office Ip 26253 282
- DOCKET 40-8027 KERR-MCGEE NUCLEAR CORP , DKLAHOMA CITY, OK
- 8406130219 Requests public hearing re raffinate deep well injection project at facility near Gore, DK HENSHAW, E. Affiliation Not Assigned 84/05/22 NIXON, W. A. Division of Fuel Cycle & Material Bafety 1p 26011 361
- 8408020103 Provides followup to recent telcons re Kerr-McGee Nuclear Corp UFA facility near Corp.OX Clarification of discrepancies concerning levels of injected raffinate requested KIMERY.A L Affiliation Not Assigned 84/06/20 CROW.W T Uranium Fuel Licensing Branch 3pp 28878 104
- 8408020153 Forwards HK Van Poollen rept on modeling results for injection of 35 million gallons of treated raffinate STAUTER, J C Kerr-McGee Corp 84/07/05 WYNGARDEN, S Uranium Fuel Licensing Branch 8pp 25878 082
- 8408020161 Summarizes into supplied by Kerr-McGeo re estimate of final pressure buildup to be expected after injection of proposed 35 million gallons of treated liquid raffinate Injection can be done w/o exceeding allowable pressure WARNER, D L Don L Warner, Inc 84/07/10 WYNGARDEN, B D Uranium Fuel Licensing Branch 2pp 25898 076

- B407230112 Responds to 840522 request for hearing on proposed amend permitting disposal of raffinate through deep well injection Add1 info re issues to be raised requested within 10 days
  CHILK-S J Dffice of the Secretary of the Commission DSB 403 B4/07/20 HENSHAW, E Affiliation Not Assigned 1p 25706 102
- 8408150671 Forwards "Environ Assessment Update of Raffinate Pond 2 " STAUTER, J.C. Kerr-McGee Corp. 84/07/26 CROW, W.T. Uranium Fuel Licensing Branch 1p. 26105 270
- --8408150675 "Environ Assessment Update of Raffinate Pond 2" STAUTER, J C Kerr-McGee Corp 84/06/30 58pp 26105 272
- B408080455 Requests hearing on proposed license amend re disposal of well mat! HENSHAM.E Affiliation Not Assigned DBB B34 84/07/31 CHILK.8 J Office of the Secretary of the Commission 2pp 25943 274
- 8408230035 Submits items of interest re Whittaker Corp. Oreenville.PA. EIAs & Kerr-McGee - Okiahoma PAOG.R O Uranium Fuel Licensing Branch 84/08/16 DAVIS.J O Office of Nuclear Material Safety & Bafeguards.Director 2pp
- DOCKET 40-8064 EXXON MINERALB CO . USA: HOUSTON, TX
- 8408270197 Summarizes Exxon Minerals Co rept for First Quarter 1984
  Pilot well field conditions stable In-plant radiological
  monitoring performed as required Rn-222 & U concentrations
  at or below 2% of 10CFR20 max for restricted areas
  MASTLER.S L . HAMKINSLE F Uranium Recovery Field Office 84/07/20
  Uranium Recovery Field Office 2pg 26277 316
- DOCKET 40-8004 RIG ALGOM CORP , MOAB, UT
- 8408070509 "Remedial Action Plan for Groundwater Contamination Control at Lisbon U Mill," Vol i text, W/nine oversize maps
  Aperture cards available in PDR # EarthFax Engineering, Inc 84/04/30 128pp 25956 001
- 8408270228 Reviews addendum to environ monitoring rept for Second Half 1983 containing Tb-230 & Pb-210 air particulate data not in 840217 original rept GARCIA.P J. PETTEMOILL, H J Uranium Recovery Field Office 84/07/19 Uranium Recovery Field Office 1p 26277 238
- 8408240138 Advises of issuance of Amend 21 to License SUA-1119, incorporating name change & authorizing const of berm in upper tailings pand SMITH, R D Uranium Recovery Field Office 84/08/10 Rio Algom Corp 2pp 26253 362
- 840B240209 Recommends issuance of Amend 21 to License BUA-1119, changing name in Condition 1 to Rio Algom Mining Corp & revising Conditions 31,32 & 34 re upper tailings pond JIERREE.C C. PETTEMOILLH J. Uranium Recovery Field Office 84/08/10 Uranium Recovery Field Office 4pp 26255 244
- DOCKET 40-8102 EXXON CO , USA, HOUSTON, TX
- 8408060297 Forwards list of activities to be undertaken during period between and of milling & issuance of decommissioning license amend PATTON.J D Exxon Corp 84/06/14 SMITH.R D Uranium Recovery Field Office 5pp 25950 355
- B408270055 Reviews environ & effluent manitoring rept for Jul-Dec 1983, submitted per 10CR40 65 & License Conditions 14 & 33 PANDBURN.0 C . PETTENGILL, H J Uranium Recovery Field Office. 84/07/24 Uranium Recovery Field Office 4pp 26279 037
- 8408230472 Forwards 1E Insp Rept 40-8102/84-01 on 840709-12 & notices of violation & deviation PETENGILL, H J Uranium Recovery Field Office. 84/07/31 SHANNON.J B. Exxon Corp 2pp 26212: 192
- --8408230475 Notice of violation from insp on 840709-12 \* Region 4, Office of Director 84/07/31 Lp. 26212 194
- --8408230478 Notice of deviation from insp on 840709-12 \* Region 4. Office of Director. 84/07/31. 1p. 26212 195

- --8408230481 IE Insp Rept 40-8102/84-01 on 840709-12 Violation noted lack of approved respiratory protection program & use of uncertified respirator Deviation noted failure to calibr alpha survey instruments
  JERREE, C C , PANOBURN, G C , PETTENOILL, H J Uranium Recovery
  Field Office 84/07/31 10pp 26212 196
- 8408240169 Advises of issuance of Amend 8 to License SUA-1139, revising License Condition 11
  SMITH.D F Uranium Recovery Field Office 84/08/03 PAFTON, J D Exion Corp 2pp 26254 260
- 8408270035 Recommends issuance of Amend 8 to License 5UA-1139, changing Condition 11 to allow routine organizational & administrative changes u/o approval in form of amend PANGBURN, 6 C. PETTENSILL, H.J. Uranium Recovery Field Office 84/08/03 Uranium Recovery Field Office 2pp 26258 341
- DOCKET 40-9390 ROCKY MOUNTAIN ENERGY CO . DROCMFIELD. CO
- 8408240149 Forwards Form NRC-591, "Insp Findings & Licensee Ack." reviolations observed during 840626 insp of License SVA-1228 Bignature requested within 30 days M/o encl HASTLER.S L. Uranium Recovery Field Office 84/07/13 NEUMAN.M R Rocky Mountain Energy Co ip 26254 257
- 8408240102 "Nine Mile Lake Quarterly Rept.Second Guarter 1984" SPIELES,P R Rocky Mountain Energy Co 84/07/31 SMITH,R D Uransum Recovery Field Office 10pp 26254 272
- DOCKET 40-8434 HOMESTAKE MINING CO / LAKEHOOD, CD
- 8409280365 Confirms that Homestake Mining Co does not intend to renew License SUA-1249 CRDUCH D B Homestake Mining Co 84/07/30 WASTLER, S Uranium Recovery Field Office 1p 26272 360
- DOCKET 40-8452 BEAR CREEK URANIUM CO . CASPER, MY
- B40B0B0429 Application for amend to License SUA-1319, revising Nov 1981 tailings mat plan to include plans to raise tailings dam to intermediate elevation of 5.166 ft W/three oversize drawings Aperture cards in PDR Fee encl
  MEDLOCK.R L Bear Greek Uranium CD 84/04/17 PETTENGILL, H. PANGBURN, O Uranium Recovery Field Office 11p 25975 337
- 8408270106 Submits review of 1984 reclamation & decommissioning bonds Bond amount adequate for tasks License SUA-1310.Condition 16 satisfied PANOBURN, C C , PETTENGILL. H J Uranium Recovery Field Office 84/07/31 Uranium Recovery Field Office 2pp 26277 360
- 3408270049 Reviews Bear Creek U Hill environ monitoring data for Oct 1981 - Sept 1982 re 400FR190 compliance assessment JIERREC, C Uranium Recovery Field Office 84/08/01 Uranium Recovery Field Office. 2pp 26277 285
- 8408240212 Recommends issuance of Amend 24 to License SUA-1310, revising Condition 31 re tailing dam raise, per licenses 831122 request PANOBURN, G C , PETTENGILL, H J Uranium Recovery Field Diffice 84/08/03 Uranium Recovery Field Office 3pp 28254 358
- B408270331 Advises of issuance of Amend 24 to License SUA-1310. revising Condition 51 me const of proposed dam raise, per const Specs C-1 & C-2 SMITH.R D Uranium Recovery Field Office 84/09/07 Bear Creek Uranium Co Spp 26277 240.
- DOCKET 40-8502 WYDNING MINERAL CORP . LAKENOOD, CO
- 8408240427 Requests confirmation of timely filing of 830928 renewal application for License 8UA-1341 & application fee Extension 1tr requested.

  RUTLEDGE.C Westinghouse Electric Corp 84/01/27 Division of Fuel Cycle & Material Safety 1p 26248-226
- 9408240381 Forwards rapt of action for mitigation re 830605 event concerning Monitor Hells R8-79 in production area exceeding action levels for chloride Rapt submitted per Condition 16D. License SUA-1341 RUTLEDER.C. Westinghouse Electric Corp. 84/02/16 SMITH.R D. Uranium Recovery Field Office App. 26254-323

- 8408240409 Submits monthly rept on corrective action status of Well 988-29 at Irigaray Mine Site Chloride returned below upper control limit RUTLEDGE.C Westinghouse Electric Corp 84/02/16 CHANCELLOR.R Wyoming, State of 2pp 26248 312
- 8408240402 Recommends that no action be taken on groundwater restoration plan for alternative lixiviant test area until addl info submitted re listed issues OGLE.K M Alyaming Mineral Corp 84/02/17 Wyoming Mineral Corp 4pp 26248 320
- 8408270424 Discusses items of concern requiring response before approval may be granted for 031115 proposed groundwater restoration for alternate Hiziviant test area MDDNEV. 0 Myoming, State of 84/02/23 RUTLEDOE, C Westinghouse Electric Corp 4pp 26277 230
- 8408240397 Provides status rept on mitigation of excessive chloride action levels in monitor wells at irigaray Mine Site.per License Condition 16D RUTLEDOE.C Westinghouse Electric Corp 84/03/19 PETERSON, K Uranium Recovery Field Office 5pp 26248 338
- 8408270032 Forwards monthly rept re analyses of samples from Monitor Well 9RS-25 Well exhibited irregular behavior Chloride remained under upper control limit for 4 wks RUTLEDGE. C Westinghouse Electric Corp 84/03/19 CHANCELLOR, R Wyoming, State of 2pp 26258 347
- ---B408270034 Analyses of samples from Monitor Well 988-25 for B40830-0311 # Westinghouse Electric Corp. 84/03/11 200 28298 348
- 8408270362 Forwards response to 840223 request for add1 info re alternate lixiviant test area restoration demonstration Expeditious review requested RUTLEDGE.C Westinghouse Electric Corp 84/03/28 MODNEY.G Wyoming, State of 10pp 26277 253
- B408270138 Submits status rept on action for mitigation of excessive chloride action levels in Wells 9R8-79,517-Mi & 517-M2,per License Condition 16D FAUBER. On Mestinghouse Electric Corp 84/04/18 SHITH,D Uranium Recovery Field Office 3pp 26277 328
- 8408270042 Comments on Westinghouse 840328 responses to 840223 ltr re Irigaray Ranch Mine: Permit 478 MODNEY. 6 Wyoming, State of 84/05/11 RUTLEDGE, C Westinghouse Electric Corp 10pp 26258 320
- 8408270031 Monthly rept on corrective action status of Wells 9R8-79, 517-M1 & 517-M2 at Irigaray Mine, 830605-840513 FAUBER, J Westinghouse Electric Corp 84/05/16 SMITH, D NRC No Betailed Affiliation Given 3pp 26258 349
- 9408270550 Reviews Hestern Nuclear 840419 submittal re alternate lixiviant test area restoration demonstration Add1 info requested re well integrity testing OOLE, K Myoming, State of 84/05/25 Wyoming, State of 12pp 26277 273
- B40B240349 Ack receipt of B40522 ltr re B40412 request for redefinition of carbonaceous shale zone & review of proposed monitoring & restoration program Review of revised monitoring & restoration program as applied to license requested RITNER, T H Hestinghouse Electric Corp 84/06/12 SMITH, R D Uranium Recovery Field Office ip 26253 203
- 8498270364 Forwards response to 840605 request for add1 info re restoration demonstration Authorization for demonstration requested RUTLEOGE.C Westinghouse Electric Corp 84/06/19 RANDEN.L D Wyoming. State of 10pp 26279 003
- 8408270069 Forwards monthly rept on corrective action status of Wells 988-79 & 517-M2 at Irigaray Mine FAUBER, J Westinghouse Electric Corp 84/06/20 SMITH, D Uranium Recovery Field Office 3pp 26277 287
- 8408270571 Forwards response to 840611 request for add1 info re application for groundwater pollution control permit Issuance of permit to begin work requested RUTLEDGE.C Mestinghouse Electric Corp 84/06/20 GARLAND, W Wyoming, State of 2pp 26279 015
- 8408270177 Informs that response to \$30627 request for amend to License SUA-1341, authorizing action level adjustment for Irigaray Mine Site: not received RUTLEDGE.C Westinghouse Electric Corp. 84/06/27 SMITH: R D. Uranium Recovery Field Office. 19. 26277-320

- 8408280014 Advises of issuance of Amend 9 to License SUA-1341, authorizing add1 restoration of Wellfield E at site SMITH.R D Uranium Recovery Field Office 84/07/16 RUTLEDGE.C Westinghouse Electric Corp 2pp 26293 355
- --840B2B0016 Documents issuance of Amend 9 to License SUA-1341, authorizing addl restoration of Wellfield E at site PETERSON.K A Uranium Recovery Field Office 84/07/16 Uranium Recovery Field Office 3pp 26293-357
- B408270545 Confirms plan to drill Well 517-NM2, per 840727 discussion Application for permit to appropriate groundwater filed w/State of WY & application to substitute new well forthcoming VASELIN. J Westinghouse Electric Corp 84/07/30 MODNEY, G Wyoming, State of 1p 26277 038
- DOCKET 40-8584 MINERALS EXPLORATION CO . LOS ANGELES, CA
- 8408270238 Forwards revised application for renewal of License SUA-1350, describing existing mill processes & monitoring programs Summary listing of license conditions & amends included as integral part of renewal application HILL.C Z Union Minerals 84704703 PETTENGILL, H Uranium Recovery Field Office 14pp 26276 276
- --8408270243 Revised application for renewal of License SUA-1350, describing existing mill process & monitoring programs W/ one oversize map Aperture card available in PDR \* Union Minerals 84/03/31 64pp 26276 295
- 8408270157 Informs that on 840521; two corners of hypaton liner matl observed separating Storm ripped liner matl & areas stabilized by plastic sheeting & sandbagging Repairs made KLEIN TJ Union 76 Minerals Exploration Co 84/05/23 SMITH,R D Uranium Rocovery Field Office 3pp 26277 325
- 8408240406 Reviews 840512 responses to Fall 1983 completeness review W/exception of vegetation, soils & wind erosion, sufficient info supplied for technical review Adequacy of soils, vegetation & wind erosion info not yet evaluated ENGELMANN, R Wyoming, State of 84/07/11 HILL, C 2 Minerals Exploration Co (subs of Union Oil Co of California) 2pp 26248 318
- 8408240408 Advises that proposal for addl monitoring wells modified to include Tailings Monitor Wells TMM-15,TMM-17 & TMM-18
  Initial analysis will include listed parameters TMM-15 sampling will be revised KLEIN.T J Union Minerals 84/07/20 SMITH.R D Uranium Recovery Field Office 4pp 26248 314
- 8408240417 Forwards revised Pages 5-9 & 5-18A to 840403 application to renew License SUA-1350, including external radiation exposure history & discussion of tailings cell leak detection monitoring sys 40CFR192 requirements respectively HILL, C Z Union Minerals 84/07/27 PETTENGILL, H Uranium Recovery Field Office 3pp 26248 272
- --8408240423 Revised Pages 5-7 & 5-18A to 840403 application to renew License SUA-1350, including external radiation exposure history & discussion of tailings cell leak detection manitoring sys 400FR192 requirements, respectively \* Union Minerals 84/07/27 2pp 26248 273
- 8408270053 Summary of 840601 meeting w/licensee & State of HY at mill site re liner damage reported in 840822 telcon KONWINSKI.O R , PETTENGILL,H J Uranium Recovery Field Office 84/08/02 Uranium Recovery Field Office 3pp 26278 360
- 8408270248 Provides annual review of bond covering mill decommissioning & site reclamation, submitted in compliance w/License Condition 17 KONMINSKI, G R , PETTENGILL, H J Uranium Recevery Field Office 84/08/10 Uranium Recevery Field Office 2pp 26277 234
- DOCKET 40-8585 WYOMING MINERAL CORP , LAKEWOOD, CO
- 8408270028 Forwards "Semiannual Effluent Monitoring Rept. Jul-Dec 1983" Name changed to U Resources Div of Westinghouse effective 840101 BERO, R E Westinghouse Electric Corp 84/02/27 Region 4, Office of Director 1p 26258
- --8408270029 "Semiannual Effluent Monitoring Rept. Jul-Dec 1983 " \* Westinghouse Electric Corp 83/12/31 1p 26298 353

- DOCKET 40-8584 KERR-MCGEE NUCLEAR CORP . DKLAHOMA CITY, DK
- 8408240331 Responds to 831121 notice not to renew License SUA-1330 Insp performed 840628 confirmed wells properly plugged & reclaimed License SUA-1330 terminated SMITH,R D Unantum Recovery field Office 84/08/07 STAUTER.J Sequoyah Fuels Corp ip 26283 333
- --8408240333 Discusses decommissioning of facility & termination of License SUA-1330 Facility decommissioned & reclaimed per license conditions HILDENBRAND, P Uranium Recovery Field Office &4/08/07 Uranium Recovery Field Office 2pp 26253 334
- DUCKET 40-8602 SILVER KING MINES, INC , CASPER. MY
- 8408240216 Reviews Silver King Mines, Inc 840228 submittal re preoperational radiological environ monitoring Pept for Jul-Dec 1983 PANOBURN, G C., PETTENGILL. H. J. Uranium Recovery Field Office 84708/14 Uranium Recovery Field Office 4pp 26254 347
- DOCKET 40-8674 PLATEAU RESOURCES, LTD , GRAND JUNCTION, CO
- 8408130272 Requests amend to Condition 26 D of License SUA-1326, reflecting renewal of 1tr of credit Revised 1tr of credit expires 830413 GERDEMAN,F W Plateau Resources, Ltd 84/07/10 Uranium Recoverifield Office 1p 26040 344
- 8408240047 Explains reason for not revising estimate of decommissioning costs for Blanding Ore Buying Station.per License Condition 26 Dollar amount for surety exceeds amount for decommissioning OERDEMAN.F W Plateau Resources, Ltd 84/07/26 SMITH.R D Uranium Recovery Field Office 2pp 26255 340
- 8408240351 Informs of resignation of radiation safety officer; effective 840809 GERDEMAN.F W Plateau Resources. Ltd 84/07/31 \$MITH.R D Uranium Recovery Field Office 1p 26253 282
- 8408240385 Presents review of Plateau Resources.Ltd 10CFR40 65 environ monitoring rept for Blanding Dre Buying Station for First Half 1983 No one stored at facility No further action necessary HILDENBRAND,P Uranium Recovery Field Office 84/08/07 Uranium Recovery Field Office 84/08/07
- DOCKET 40-8675 ENERGY FUELS NUCLEAR, INC , DENVER, CO
- 8408280110 Application for amend to Litense SUA-1325, to dispose of approx 4,000 tons of contaminated soil & low grade ore in licensed tailings disposal facility ROBERTS. HR Energy Fuels Nuclear: Inc. 84/05/10 HAWKINS. E
- 8408280010 Forwards decommissioning plan for Hanksville Buying Station Decommissioning activities will begin on 840604 w/equipment removal & cleanup of sample plant bldg interior VINCELETTE,M D Energy Fuels Nuclear, Inc. 84/05/25 HILDENBRAND,P Uranium Recovery Field Office ip 26294:001.
- --8408280012 Decammissioning plan for Hanksville Duying Station \* Energy Fuels Nuclear, Inc 84/05/24 4pp 26274 002
- DOCKET 40-8681 ENERGY FUELB NUCLEAR: INC , DENVER. CD
- B40B0B0144 Application for amend to Liconse BUA-133B, transferring White Mesa, UT facility to Umetco Minerals Corp Umetco acquired 70%, undivided interest in U & vanadium milling facility at White Mesa GRANELEY, G W Energy Fuels Nuclear, Inc. ALEBIO, W G. UMETCO Minerals Corp (subs of Union Carbide Corp.) 84/03/15 SMITH, R D Uranium Recovery Field Office 26pp 25979, 036.
- 8408240393 Notifies that two acres of grazing land cleared for agricultural use & that residence under constrin compliance w/License SUA-1388 requirement for annual accounting of changes in land use PERKINS.L.K. Energy Fuels Nuclear, Inc. 84/07/13 SMITH.R D Uranium Recovery Field Office ip 26248-362

- 8408270040 Summarites Energy Fuets Nuclear 840504 semiannual environ monitoring rept for Jul-Dec 1783.per 100FR40 65 & License Condition 38 Concern expressed Te significant change noted in Ra-266 analyses of vegetation samples HILDEMBRAND.P. HAWKINS.E F. Uranium Recovery Field Office 84/07/20 Uranium Recovery Field Defice 4pp 26258 333
- 8408290216 Application for amend to License SUA-135 extending license for 90 days beyond 840831 expiration date VINCELETTE.M D Energy Fuels Nuclear, Inc 84/07/23 HILOEMBRAND.M Uranium Recovery Field Office ip 26312 343
- 8408270117 Submits review of semiannual ALARA rept for 1983 for White Mesa Mill HILDENBRAND,P , HAWKINS,E F Uranium Recovery Field Office 84/07/26 Uranium Recovery Field Office App 26277 354
- 8408290366 Forwards fee for amend to License SUA-1356, extending expiration date by 90 days, per 840723 ltr
  VINCELETTE. N D Energy Fuels Nuclear, Inc 84/07/30
  HILDENBRAND.M Uranium Recovery Field Office ip 26310 358
- DOCKET 40-8684 HESTERN NUCLEAR. INC . LAKEWOOD, CO
- 8408270038 Application for amend to License SUA-1937, revising App D-1 re-past & present land use. App D-7 re-soil assessment & App D-8 re-vagetation inventory W/four oversize figures Aperture cards available in PDR BD00EN. O Western Nuclear. Inc (subs of Phelpt Bodge Corp.) 84/07/23 HILDENBRAND.P Uranium Recovery Field Office 147pp
- DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO , DENVER, CO
- 8408240031 Environ monitoring quarterly rept for Apr-June 1984, Reno Creek R&D project SPIELE6.P Rocky Mountain Energy Co 84/07/24 SMITH, R D Uranium Recovery Field Office 9pp 28254 282
- DOCKET 40-8698 PLATEAU RESGURCES, LTD , GRAND JUNCTION, CO
- B408240410 Updates situation in which tailings contaminated solution exceeded layel of clay liner in lower impoundment area at Shootaring Canyon processing facility Coring program will be initiated Survey results encl GERDEMAN.F W Plateau Resources. Ltd 84/07/16 SMITH.R D Uranium Recovery Field Office Spp 26248 309
- 8408240207 Bummary of 840620 meeting w/Plateau Resources, Ltd in Benver. CO re Shootaring Canyon U Mill license & Blanding Ore Buying Station license renewal application SHOPENN.N N PETTENGILLH J . HAMKINS, E F Uranium Recovery Field Office GA/07/27 Uranium Recovery Field Office 3pp 26255 248
- 8408240351 Informs of resignation of radiation safety officer, effective 840809 GERDEMAN.F.W Plateau Resources, Ltd 84/07/31 BMITH.R D Uranium Recovery Field Office ip 26253 282
- 8408240195 Recommends License SUA-1371 be amended to extend expiration date to 841231 to allow time for preparation of renewal application SHOPENNIN M Granium Recovery Field Office 94/08/07 Uranium Recovery Field Office 94/08/07
- --8408240198 Issues Amend 10 to License SUA-1371 extending expiration date to 841231
  SMITH.R D Uranium Recovery Field Office 84/08/07
  9ERBEHAN.F W Flateau Resources, Ltd 1p 26255 254
- 8408270100 Reviews 1782 chemical analysis & analytical detection limits re groundwater for Shootaring Canyon U processing facility HARKINGLE F. SHOPENN.N K Uranium Recovery Field Office 84/08/08 Uranium Recovery Field Office 4pp 24278 314

- BOCKET 40-8722 BRUSH WELLMAN, INC., CLEVELAND, OH
- 8408060300 Application for renewal of License SUA-1354, extending expiration date until Jan 1986 Fee encl
  VALIQUETIE, J C Brush Wellman, Inc 84/06/01 SHITH, R D Uranium Recovery Field Office 6pp 28951 001
- 8408240177 Ack receipt of renewal application for License SUA-1354 HAWKING.E F Uranium Recovery Field Office 84/07/19 VALIQUETTE.J C Brush Wellman, Inc. ip 26259 273
- DOCKET 40-8724 CHEMETRON CORP , CHICAGO, IL
- 8408020228 Forwards Health Physics Procedure 9, "Confirmatory Survey Methods" Procedure will be included in decontamination plan PECK, 8 Radiation Management Corp 84/06/28 CODL, D NRC No Detailed Affiliation Given 1p 25898 173
- --8408020230 Health Physics Procedure 9, "Confirmatory Survey Methods" \* Radiation Management Corp 84/06/28 4pp 25878 174
- DOCKET 40-8727 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK
- 8408240040 Notifies that R&D License BRD may be terminated & responsibility for revegetation must be included in Permit 304c BUNDIN, R., RANDEN, L., OARLAND, W. Wyoming, State of 84/07/31 BTAUTER, J. C. Sequoyak Fuels Corp. lpp 26295 342
- DUCKET 40-8728 TETON EXPLORATION DRILLING CO , INC , CASPER, WY
- 8408270205 Summarizes Teton Exploration First Quarter 1984 rept Site remained shutdown Activities included evaporation pond insp. leak detection monitoring, an-plant rediation monitoring & security No leaks detected in pond liners
  WABTLER.S.L., HAWKINS.E.F. Uranium Recovery Field Office 84/07/20
  Uranium Recovery Field Office 2pp 26277 314
- DOCKET 40-8745 GGLE PETROLEUM, INC . CASPER, WY
- 8408240079 Requests that Dison Dasin Mine, Permit 504, be placed on interim stabilization, per 35-11-401(n) Mine not in operation due to depressed market conditions Required environ sampling & analyses continues to take place Table withheld CATCHPOLE. Q J Ogle Petroleum, Inc 84/07/16 ENGELMANN, R Hyoming, State of 2pp 26255 334
- 8408240050 Forwards mat1 re Technology Lab. Inc alpha contamination survey, per request CATCHPOLE. 0 J Ogle Petroleum, Inc 84/08/06 HASTLER. 8 Uranium Recovery Field Office 4pp 26255 336
- DOCKET 40-8768 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OX
- 8408240175 Forwards amended License SVA-1387, EIA & BER BMITH, R D. Uranium Recovery Field Office 84/07/25 STANTER, J Baquogah Fuels Corp. ip. 26253 001
- --8408240178 Amended License SUA-1387 for Sequoyah Fuels Corp, authorizing R&D scale U in situ leach activities SMITH:R D Urantum Recovery Field Office 84/07/25 15pp 282823 002
- --B408240183 EIA supporting amend to License SUA-1387 HILDENBRAND, P., HAWKINS, E.F. Uranium Recovery Field Office 84/07/25 177pp. 26253-023
- 8408240337 "Soil Sediment Analysis Summary NPDES Drainage Sys, June 1983 - Mar 1984 " FREEMAN M D Sequeyah Fuels Corp 84/06/07 HILDENBRAND, P Uranium Recovery Field Office 2pp 26253 319

## **DOCKETED ITEMS**

- 8408240377 Notifies of 840702 lab analysis of Ra-266 at 10 8 pC1/g for 840404 soil samplefrom outfall location.8 3 pC1/g above baseline value Sample taken on 840611 showed only I pC1/g above baseline Similar reading occurred in first quarter FREEMAN, M D Saquoyah Fuels Corp 84/07/07 HANKINS, E, HILDENBRAND, P Uranium Recovery Field Office Ip 26254 333
- 8408240154 Forwards form NRC-591. "Insp Findings & Licensee Ack," re violations observed during 840627-28 imap of License SUA-1387 Signature requested within 30 days M/o encl MASTLER,S L Uranium Recovery Field Office 84/07/13 ORELL,E Kerr-McGee Nuclear Corp 1p 26254 256
- B408240375 Ack receipt of B40613 ltr to R Spears Q-Sand restoration proposal acceptable As stated on Page 2.approval from Dept of Environ Guality & NRC needed before sodium sulfide added to injection stream MCCARTY, C Myoming. State of B4/07/23 FREEMAN, M L Sequoyab Fuels Corp ip 26254 335
- 8408270048 Reviews Sequoyah Fuels Corp First Quarter 1984 rept for Q-Sand R&D In Situ Leach Project, submitted per License Condition 38
  HILDENBRAND, P., HAWKINS, E.F. Uranium Recovery Field Office 84/07/26
  Uranium Recovery Field Office 4pp 26258 309
- 8408280334 Reviews Sequoyah Fuels Corp semiannual ALARA audit rept of Q-Sand R&D In Situ Leach Project for Nov 1983 Apr 1984, submitted per License Condition 27 HILDENBRAND, P. HAWKINS, E. F. Uranium Recovery Field Office 84/07/26 Uranium Recovery Field Office 4pp 26294 109

# DOCKET 40-8769 EXXON CO . USA, BILLINGS, MT

- 8408090157 IE Insp Findings & Licensee Ack on 840710 of License SUB-1382 Insp findings records re receipt of licensed matl not properly maintained & documents not properly posted MILBORN.L Region 4. Office of Director 84/07/10 ip 25994 324
- DOCKET 40-8783 URANERZ USA, INC , CASPER, WY
- 8408240341 Forwards author 840710 ltr to State of WY Dept of Environ Quality re state annual rept & request to skip monitor well sampling period SOMERVILLE.K G Uranerz USA, Inc. 84/07/10 HAWKINS.E Uranium Recovery Field Office 3pp 26253 315

#### DOCKET 40-8786 URANIUM RESDURCES, INC., RICHARDSON, TX

- 8408070226 Forwards IE Insp Rept 40-8786/84-01 on 840103 & 07 & notice of violation Insp examined allegations of violations of license conditions One allegation substantiated Insp rept withheld SMITH/R D Uranium Recovery Field Office 84/07/09 RICHARDSON Uranium Resources, Inc. 2pp 25957-048
- --8408070231 Notice of violation from insp on 840105 & 07 Violation noted failure to rept leaks in east & west ponds on 840310 & 830120, respectively \* Region 4. Office of Director 84/07/09 ip 25987 050
- 8408240353 Responds to 840709 notice of violation of Condition 17 refailure to rept leaks in avaporation ponds on 820310 to 830120 Corrective action holes patched to prevent leakage into monitor sumps
  PELIZZA: M B Uranium Resources, Inc 84/07/20 SMITH, R D Uranium Recovery Field Office ip 26253 281
- 8408270024 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in 840620 notice of violation Actions to be examined at future insp NRC reporting requirements reiterated SMITH.R D Uranium Recovery Field Office 84/08/10 PELIZZA.M 8 Uranium Resources, Inc. 2pp 26258 354

# DOCKET 40-8922 OMAHA PUBLIC POWER DISTRICT, OMAHA, NE

8408090127 IE Insp Findings & Licensee Ack on 840716-17 of License SMC-1420 Insp findings no violations observed SPITZBERG, D B Region 4. Office of Director 84/07/17 2pp 25993 146

#### DOCKET 40-8029 WYOMING FUEL CO , LAKEWOOD, CD

- 8408240393 Reviews draft EIA re source matl license for Wyoming Fuel Co Document should be entitled "Draft Environ Assessment" rather than DES Conclusion should not foreshadow decision BROWN, U. Region 4, Office of Director 84/07/27 SMITH, R D Uranium Recovery Field Office 3pp 26248 357
- 8408270099 Summary of 840716 informal public meeting w/State of NE,EPA & public interest groups in Crawford.NE re draft EIA for praposed Crow Butte project Appropriate comments will be incorporated into EIA MASTLER.8 L. HAMKINS.E F Uranium Recovery Field Office 84/08/08 Uranium Recovery Field Office 2pp 26277 291

# DOCKET 40-8842 MINNESOTA, UNIV OF MINNEAPOLIS, MN

- 8408010394 IE Insp Findings & Licensee Ack on 840710-11 of Licenses 22-00187-49, 22-00187-09, 22-00187-53, 22-00218-31 & SUD-1434 Insp findings no violations observed LYNCH, J L Region 3, Office of Director 84/07/11 1p 25866 062
- DOCKET 40-8857 EVEREST MINERALS CORP : CONVERSE COUNTY, WY
- 840B280018 Forwards application for license to conduct production scale recovery & processing of natural U via in situ leaching operations at Highland Sito in Converse County, MY "Highland In Situ U Project" also encl Fee paid MAYS, W K Everest Minerals Corp 84/07/24 HAWKINS, E F Urenium Recovery Field Office 4pp 26292 090
- --8408280022 Application for license to conduct production scale recovery & processing of matural U via in situ leaching operations at Highland Site in Converse County, WY MAYS, W M Everest Minerals Corp. 84/07/17 2pp 26272 094
- --8408280024 "Highland In Situ U Project " W/two oversize figures Aperture cards available in PDR \* Everest Minerals Corp 84/07/24 250pp 26292 096

#### DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 UNIV OF MICHIGAN RESEARCH REACTOR

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners WALKER, R D Region 3. Office of Director 84/08/10 Michigan, Univ of. Ann Arbor, MI 2pp 26051

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

- F Security, medical, emergency & fire protection plans
- 8405240290 Responds to 840424 memo for FEMA review of util request for delay in scheduling next full-scale emergency preparedness exercise at sits until 84130 Delay acceptable KRIMM.R Federal Emergency Management Agency 84/05/18 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 8pp 24614 336 24X Fiche 50-003,84/05/18,8405240290
- 8408060349 Forwards revs to physical security plan Revs withheld (ref 10CFR73 21) 0'T80LE,J D Consolidated Edison Co of New York, Inc 84/07/16 MURLEY,T E Region 1, Office of Director 1p. 25936 032 24X Fiche, 50-003, 84/07/16, 8408060349
- 8408130121 Forwards public version of revs to Book II to emergency procedures document including App A, "Emergency Roster" & App B, "Con Ed Medical Dept. Consultants & Agencies" O'TOOLE.J D Consolidated Edison Co of New York, Inc 84/07/16 MURLEY.T E Region 1, Office of Director 2pp 26104 238 24% Fiche 80-003.84/07/16.8408130121
- --8408150125 Public version of revs to Book II to emergency procedures document including App A, "Emergency Roster" & App B "Con E6 Medical Dept.Consultants & Agencies " H/JM Felton 840808 release memo \* Consolidated Edison Co of New York, Inc 84/06/29 21pg 26104 260 24X Fiche 50-003,84/07/16,8408150121

# P Operating license stage documents 5 correspondence

- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933. "Prioritization of Generic Safety Issues "Svc list encl EISCHHUT.D G Division of Licensing 81/08/06 Consolidated Edison Co of New York, Inc. 18pp. 26129 238 24X Fiche 50-000.84/08/06.8408070110
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for DLs re-scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions 8vc list encl EISENHUT.D g Division of Licensing 84/08/20 Consultdated Edison Co of New York, Inc. 17pp 26276-244 24x Fiche \$0-000,84/08/20.8408200275
- 840B280333 Staff requirements memo re 840B16 continuation of 840723 discussion of issues requiring resolution prio: to issuance of order in proceeding Commission requested briefing on PRA including discussion of uncertainties & basis of comparison CHILK.B J Office of the Secretary of the Commission 84/08/21 DIRCKS.H J Office of the Executive Director for Operations ZERBS.J E Office of Policy Evaluations 2pp 26274 050 24X Fichs 50-003,84/08/21.8408280333
- @ Inspection reports, IE Bulletins & Correspondence
- 8407250229 IE Info Notice 84-37. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc. (19pp. 23865-047-24X Fiche 50-000,84/07/27,8407250229
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 8301033 84/08/06 Consolidated Edison Co. of New York, Inc. 85pp. 26067 278 24X Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Mest Efficiency Requirement " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000.84/08/06,8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORBAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York, Inc. 120pp 26129 118 24X fiche 50-000,84/08/08,8408070120
- 8408070376 IE Info Natice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list encl GRACE.J N Division of QA. Gafeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York. Inc 125pp 26127 256 24X Fiche 50-000.84/08/10,8408070376
  - 3100009 IE Info Notice 84-63, "Defective R/IR Replacement Piping "vc list and; "Defective R/IR Replacement Piping "vc list and; "Defective R/IR Replacement Piping "Vc list and; "Defective R/IR Replacement Piping "Vc list and III Replacement Piping" "Defective R/IR Replacement Piping "Vc list and III Replacement Piping" "Defective R/IR Replacement Piping "Vc list and III Replacement Pipin
- H408100038 IE Info Notice B4-64, "BWR HPCI Initiation Heal-In & Indication "Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 80103) 84/08/15 Consolidated Edison Co of New York Inc 104pp 26198 093 24X Fiche 50-000.84/08/15 8408100038
- 8408100021 IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list enci JORDAN.E L Division of Emergency Preparedness & Empireering
- list encl
  JORDAN.E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/16 Consolidated Edison Co of New
  York, Inc 118pp 26197 337 24% Fiche 50-000,84/08/16,8408100021
- 8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidabed Edison Co of New York, Inc. 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100035
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc. 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

- 8408210142 IE info Notice 84-68, 'Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves "Svc list encl UCRDANIE C Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000.84/08/21,8408210142
- T Hearing transcripts on non-antitrust matters
- 8408280025 Transcript of 840816 Commission meeting in Washington, DC recontinuation of 840723 discussion of adjudicatory proceeding Pp 1-76

  \* Commissioners 84/08/16 78pp 26293 169 24X

  Fiche 50-003,84/08/16,8408280025
- DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR

  F Security, medical, emergency & fire protection plans
- 8408030205 Requests application for renewal of License R-2.including environ rept swargency plan, physical security plan & Tech Spec info,per 10CFR50 33 & 10CFR50 34 DL scheduled to expire on 850630
  THOMAS.C O Standardization & Special Projects Branch 84/07/26 CUNNINGHAM.R 6 Pennsylvania State Univ. University Park. PA 7p. 25921 352 24X Fiche 50-005,84/07/26,8408030205
- P Operating license stage documents & correspondence
- 8408030205 Requests application for renewal of License R-2, including environ rept, emergency plan, physical security plan & Tech Spec info,per 10CFR50 34 (OCFR50 34 OL scheduled to expire on 830630
  THOMAS. C O Standardization & Special Projects Branch 84/07/26 CUNNINGHAM.R O Pennsylvania State Univ., University Park. PA 7pp 23921 352 24X Fiche 50-005,84/07/26,8408030205
- 8408230267 Responds to 840726 itr re renewal of License R-2
  Documentation requested in ltr will be included in application for renewal of license to be submitted during First Quarter 1985
  CUNNINGHAMR Q Pennsylvania State Univ , University Park, PA 84/08/10 THOMAS.C Standardization & Special Projects Branch ip 26209 322 24X Fiche 50-005.84/08/10.8408230267
- 9409270327 Responds to 840612 ltr re notification of change in storage location of SNM Info acceptable
  MARTIN.T Division of Engineering & Technical Programs 84/08/22
  CUNNINGHAM.R Q Pennsylvania State Univ , University Park, PA
  2pp 26243 278 24X Fiche 50-005,84/08/22,8408270327
- DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8404040169 Forwards exercise repts for LaBalle & Dresden offsite radiological emergency preparedness exercises conducted 820414-15 & 0629-30.respectively KRIMM.R & Federal Emergency Management Agency 84/03/26 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 22883 122 24X Fiche 50-000.84/03/26, 8404040169
- --8404040172 Evaluation of State of IL full-scale emergency preparedness exercise plan, final rept

  \* Federal Emergency Management Agency 82/05/31 68pp
  22883 124 24X Fiche 50-000,84/03/26,8404040169
- B40B130401 Responds to B40705 clarification of info re util means of satisfying annual regulatory requirement to review emergency action levels w/offsite emergency support organizations info acceptable PAPERIELLO, C.J. Region 3. Office of Director B4/08/07 REED, C. Commonwealth Edison Co. 1p. 26010 130 24X Fiche 50-000, 84/08/07.
- --8408130413 Responds to 840604 ltr re means for satisfying requirements of 10CFR50, App E.Paragraph IV B Proposal for satisfying requirements to review emergency action levels by offsite agencies clarified FARRAR, D L Commonwealth Edison Co 84/07/05 PAPERIELLO, C J Region 3, Office of Director Bpp 26010 131 24X Fiche 50-000, 84/08/07,8408130401
- 8408130289 Forwards FR notice of environ assessment & finding of no significant impact re 840405 & 26 requests for exemption of state & local govt participation in 840605 exercise PAULSON.« A Operating Reactors Branch 5 84/08/10 FARRAR.D L Commonwealth Edison Co 2pp 26010 262 24% Fiche 50-010.84/08/10.8408130289

- --B408130399 Notice of environ assessment % finding of no significant impact re exemption from requirements of IOCFR90. App E re state & local govt participation at B40605 evercise EISENNUT, D 0 Division of Licensing 84/08/10 1pp 26010 264 24X Fiche 50-010.84/08/10,8408130289
- 8408200281 Advises that 840803 Rev 15 to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable AXELSON, W.L. Region 3, Office of Director 84/08/14 FARRAR, D.L. Commonwealth Edison Co. 2pp. 26133 023 24X Fiche 50-010,84/08/14,8408200281
- B40B210001 Forwards exemption from certain requirements of Section IV F 1 of App E to 10CFR50 for Dresden 840605 emergency preparedness exercise w/o full-scale participation by state t local govts in plume exposure pathway PAULSGN.W A Operating Reactors Branch 5 84/09/14 FARRAR,D L Commonwealth Edison Co 3pp 26181 320 24X Fiche 50-010.84/08/14,8408210001
- ---8408210005 Exemption from Section IV F 1 of App E to iOCFR50 requiring full-scale emergency preparedness exercise at least annually, invalving participation of state & local govts within plume exposure pathway emergency planning zone ETSENHUT.D G Division of Licensing 84/08/14 Commonwealth Edison Co 3pp 26181 323 24X Fiche 50-010,84/08/14,8408210001
- 8408230283 Revised emergency plan implementing procedures including EPIP 100-C3 re generating station emergency plan log, replacing record of generating station emergency plan activities form W/840820 ltr SCOTT.D J Commonwealth Edison Co 84/08/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 67pp 26207 275 24X Fiche 50-010,84/08/20.8408230283
- J Insurance & indemnity information
- 8408290038 Forwards Endorsement 158 to NELIA Policy NF-43 & Endorsement 134 to MAELU Policy MF-22 OBTER: J Commonwealth Edison Co. 84/08/22 SALTZMAN, J Assistant Director for State & Licensue Relations 3pp 26291 251 24X Fiche 90-010,84/08/22,8408290038
- P Operating license stage documents & correspondence
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for GLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl EISENNUT, D 0 Division of Licensing 84/09/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000,84/08/06,8408070110
- 8408200275 Generic Ltr 84-20 to all licenses of operating reactors & applicants for QLs re scheduling guidance for licenses submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 50-000,84/08/20,8408200275
- G Inspection reports, IE Bulletins & correspondence
- 8408030251 Ack receipt of 840622 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-010/84-05, 50-237/84-07 & 50-247/84-06
  PAPERIELLO: C J Region 3, Office of Director 84/07/10 REED.C Commonwealth Edison Co ip 25917 226 24X Fiche 50-010.84/07/10.8408030251
- --B408030252 Responds to NRC B40524 ltr re violations noted in IE Insp Repts 30-010/84-05,50-237/84-07 & 50-249/84-06 Corrective actions sludge removed from Toledo & Joliet facilities Survey of sumps found no residual activity FARRAR, D L Commonwealth Edison Co B4/06/22 KEPPLER, J G Region 3. Office of Director 4pp 25917 227 24X Fichs 50-010,84/07/10,8408030251
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24% Fiche 50-000.84/07/27,8407250229
- B408070046 Notifies of 840823 meeting w/util at Region III ofc to review findings of SALP assessment re util performance Encourages mgt representation to ensure mutual understanding of issues & findings presented by NRC NORELIUS, C E Region 3. Office of Director 84/08/03 REED, C Commonwealth Edison Co 2pg 25949 337 24X Fiche 50-000.84/08/03,8498070066

- 8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during inspiristituted, effective 840820 Preprinted form will be used rather than ltr
  KEPPLER J G Region 3, Office of Director 84/08/03
  Commonwealth Edison Co. 3pp. 25942 188 24% Fiche 50-000,84/08/03,8408070401
- 8408010333 IE Info Notice 84-59, 'Deliberate Circumventing of Station Health Physics Procedures ' Svc list enc: JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 85pp. 26067 278 24% Fiche 50-000,84/08/06,8408010333
- 840801033/ IE Info Notice 84-60. Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement "Svc list encl JORDAN.C L Division of Emergency Proparedness & Engineering Response (Post 820103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR
  Refueling Cavity " Svc list encl
  JDRDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/08 Consolidated Edison Co of New
  York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08.8408070120
- B40Si40344 Confirms B40B03 plans to meet w/util on B40907 in Glen Ellyn: IL to discuss regulatory improvement program NDRELIUS, C E Region 3, Office of Director B4/0B/0B REED, C Commonwealth Edison Co 2pp 26041 030 24X Fiche 30-000, B4/0B/0B, B40B140344
- 8408300095 Forwards Insp Repts 50-010/84-10, 50-237/84-12 & 50-247/84-11 on 840618-0726 & notice of violation SHAFER, W D Region 3, Office of Director 84/08/00 REED, C Commonwealth Edison Co 2pp 26307 201 24X Fiche 50-010, 94/08/09, 840830095
- --B40B300099 Notice of violation from insp on B4061B-0726 SHAFER.W D Region 3. Office of Director B4/08/08 1p 26307 203 24X Fiche 50-010.B4/08/08.B40B300095
- --B40B30010B Insp Repts 50-010/B4-10:50-237/84-12 & 50-249/B4-11 on 840618-0726 Noncompliance noted inadequate corrective action taken in response to Tech Spec violation re open submarine door in Unit 2 reactor bldg TONOUE, T M . STASEK. S . ANDERSON. C D . Region 3. Office of Director 84/08/07 lipp 2630/204 24Y Fiche 50-010,84/08/08,8408300095
- 8408070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments ' Svc list encl GRACE, I N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 128pp 26127-256 24x Fichs 50-000.84/08/10.8408070376
- B408160139 Ack receipt of 840/30 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Repts 50-010/84-09, 50-23/784-11 & 30-249/84-10 SHAFER.W D Region 3. Office of Director B4/08/10, REED, C Commonwealth Edison Co ip 26092 040 24X Fiche 50-010, 84/08/10, 8408160139
- --840B160145 Responds to NRC 840703 ltr re noncompliance noted in IE Insp Repts 50-010/84-09.50-237/84-11 & 50-249/84-10 Corrective actions special procedure for testing automatic function of master pilot valve incorporated into existing Cardox sys FARRAR.D L Commonwealth Edison Co 84/07/30 KCPPLER, J G Region 3, Office of Director 3pp 26092 041 24X Fiche 50-010.84/08/10.8408160139
- 8408100007 IE Info Notice 84-63, "Defective RHA Replacement Piping "
  Syc list encl
  JGRDAN: C. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York: Inc. 119pp 25197 218 24X Fiche 50-000.84/08/13.8408100009
- 8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26197 337 24% Fiche 30-000,84/08/16,8408100021

- B408100055 IE Info Notice B4-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post E330103) 84/08/17 Consolidated Editon Co of New York, Inc 120pp 26276 001 24X Fiche 50-000.84/08/17.8408100055
- B40B14020B IE Info Notice B4-67, "Recent Snubber Inservice Testing 4/ Migh Pailure Rates " Syr list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/17 Consolidated Edison Co
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiving to Solenoid Valves " Svc list encl JORDAN,E L Division of Emergency Freparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 1159p 26329 008 24X Fiche 50-000,84/08/21,8408210142
- R Periodic operating reports & related correspondence
- B40B30036B "Rept of Radioactive Effluents," Jan-June 1984 W/840B15 ltr 8COTT.D J Commonwealth Edison Co 84/06/30 KEPPLER, J G Region 3. Office of Director 17pp 26308 172 24x Fiche 50-010,84/06/30, RADBROOMS
- S Reportable occurrences, LERs & related correspondence
- 8408200501 LER 84-001-00 on 840717, unplanned radioactive release to discharge canal determined Caused by stagnant contaminated water & corrosion products flushed out into discharge canal New operating order & mod established W/840813 ltr COYLE, L. SCOTT, D. J. Commonwealth Edison Co. 84/08/13 4pp 26138 302 24X Fiche 50-010.84/08/13.8408200501
- DDCKET 30-13 BABCOCK & WILCOX CO CRITICAL FACILITY

  F Security, medical, emergency & fire protection plans
- 8408310068 Confirms arrangements made between JB Mahle & DA Fethich re 840831 mgt megting in Atlanta.CA to apprise NRC of B&W organization & responsibilities of key radiation safety & safeguards mgt personnel Proposed agenda encl STOHR.J P Region & Office of Director 84/05/29 ECKERT.J P Babcock & Wilcox Co 2pp 26034-349 24X Fiche 50-013.84/05/29.8408310048
- P. Operating license stage documents & correspondence
- 8408130115 Application to amend License CX-10, to dismantle reactor & dispose of component parts Fee encl OLSEN,A F Babcock & Milcos Co 84/08/07 Standardization & Special Projects Branch 2pp 26073 274 24X Fichs 50-013, 84/08/07,8408150115
- --8408150118 "Dismantling Plan for CX-10 Reactor "
  # Babcock & Wilcox Co 84/07/31 30pp 26073 276 24%
  Fiche 50-013,84/08/07,8408150115
- DOCKET 30-27 WASHINGTON STATE UNIV RESEARCH REACTOR

  R Periodic operating reports & related correspondence
- 8408300293 "Annual Rept on Operation of Washington State Univ TRIGA Reactor, Jul 1983 - June 1984, "W/840813 ltr \* Mashington State Univ, Pullman. WA 84/06/30 6pp 26306 340 24X Fich: 50-027.84/06/30,8408300293
- 8 Reportable occurrences, LERs & related correspondence
- 840Bi4046i Ack receipt of Part 21 rept re potentially defective personnel neutron desimeters Requests resolution of problem, plans to disseminate info to potentially affected customers & steps planned or taken to prevent recurrence BAER.R. L. Engineering & Generic Communications Branch 84/08/05 TODD, W.E. Sienens Cammasonics, Inc. 3pp. 2606i 286 24X Fiche 30-027,84/08/03,8408i4044i
- DOCKET 50-29 YANKEE-ROME NUCLEAR POWER BYATION

  F. Security, medical, emergency & fire protection plans
- 8408150573 Forwards IE Insp Rept 50-029/84-12 on 640626-29 No violations noted.

  MARTIN.T.T Division of Engineering & Technical Programs 84/07/26
  HEIDER.L.H Yankee Atomic Electric Co 2pp 26079 217 24X
  Fiche 50-029.84/07/26

- --8408150580 IE insp Rept 50-029/84-12 on 840626-29 No vibiations noted Hajor areas inspected status of programs for shift staffing & augmentation public info.licensee audits & emergency worker protection HOLTNER, E., CROCKER, H. W. Region 1, Office of Director 84/07/16 3pp 26079 219 24X Fiche 50-029,84/07/26.8408150573
- 8408070393 Submits info on schedule for implementing upgraded emergency operating procedures per Suppl ! to NUREO-0737 Schedule outline prepared to perform listed actions Upgraded procedures will be implemented prior to Cycle !9 operation KAY, J A Yankee Atomic Electric Co 84/07/27 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 25945 246 24X Fiche 50-029,84/07/27,8408070393
- B40B160073 Forwards Enforcement Conference Rept 50~029/B4-16 on B40621 STARDSTECKI.R Division of Project & Resident Programs 84/07/27 HEIDER, L. H. Yankee Atomic Electric Co. 2pp. 26108 226 24X Fiche 50~029.84/07/27.840B160073
- --840B160082 IE Enforcement Conference Rept 50-029/84-16 on B40621 Major areas discussed failure to procedurally implement required security program compensatory measures Safeguards info deleted (ref 10CFR73 21)

  EICHENHOLZ-M , KEIMIG, R , KENZINGER, E Region 1, Office of Director 84/07/27 App 2610B 22B 24X Fiche 50-029,84/07/27, B408160073
- 8408200476 Forwards IE Safeguards Insp Rept 50-029/84-09 on 840514-17 No violations noted MARTIN T T Division of Engineering & Technical Programs 84/07/30 HEIBER.L H Yankee Atomic Electric Co 2pp 26138 283 24X Fiche 50-029.84/07/30.8408200476
- --8408200487 IE Safeguards Insp Rept 50-029/84-07 on 840514-17 No violations noted Major areas inspected security organization, security program audit & physical barriers Safeguards into deleted (ref 100FR73 2) & 2 790)
  MADDEN, W. J. KEINIG, R. Region I. Office of Director 84/07/26 5pp 26138 285 24% Fiche 50-029,84/07/30.8408200476
- 8408140304 Revised Emergency plan operating pracedures, consisting of Rev 38 to table of contents. Rev 2 to OP-3343. "Release of Public Info Under Emergency Conditions & Rev 1 to OP-3346, "Vital Computer Sys Operation Under Emergency Conditions "

  \* Yankee Atomic Electric Co 84/08/07 29pp 26049 150 24X Fiche 50-029.84/08/07.8908140304
- 8408i30330 Ack receipt of 8407i3 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 30-029/84-04 STAROSTECKI.R Division of Project & Resident Programs 84/08/09 HEIBER,L H Vankse Atomic Electric Ca 2pp 26010 245 24X Fiche 50-029,84/08/09,8408130330
- --8408130354 Responds to NRC 840613 ltr reviolations noted in IE Safeguards Insp Rept 50-029/R4-06 Corrective actions effectiveness of Mgt control sys will be improved Safeguards info deleted (ref 10CFR/3 21)

  VANDEMBURGH, D Yankee Atomic Electric Co 84/07/13 MURLEY, T E Region I. Office of Director 3pp 26010 247 24X

  Fiche 50-029,84/08/09,8408130350
- 8408270577 Forwards Insp Rept 50-029/84-07 on 840320-0630 No violations noted STAROSTECKI, R Division of Project & Resident Programs 84/08/10 HEIDER, L H Yankee Atomic Electric Co 2pp 26256-068 24X Fiche 50-029,84/08/10,8408270577
- --B408270579 Insp Rept 50-029/84-07 on 840320-0630 No violations nated Major areas inspected licensee action on previous insp findings.operational safety verification reviews & reviews of plant events & LERs EICHENHOL7.H , WENTINGER.E Region 1, Office of Director 84/08/06 33pp 26256.070 24% Fiche 50-029.84/08/10.8408270577
- 8408240266 Forwards order correcting administrative error in 840612 order re licensee commitments on emergency response capability Order requires implementation to meet criteria of Table I of Buppl I to NUREO-0737 by 850701 PAULEDN,N A Operating Reactors Branch 5 84/08/23 KAY, J A Yankee Atomic Electric Co 3pp 26223 112 24X Fiche 50-029,84/08/23,8408240266
- --8408240281 Order confirming further licensee commitment on emergency response capability. Licensee required to complete implementation of upgraded emergency operations facility to meet criteria of Table 1 of Suppl 1 to NURED-0737 by 950901 HIRAGLIA, F J Division of Licensing 84/08/23 Yankee Atomic Electric Co 4pp 26223 115 24X Fiche 50-029,84/08/23,8408240266

- 8408130322 Change 4.consisting of Rev 3 to emergency plan \* Yankee Atomic Electric Co 84/08/31 175pp 26006 025 24Y Fiche 50-029.84/08/31.8408130329
- 8408220012 Rev 3 to Emergency Plan Implementing Procedure CP-3300, "Classification of Emergencies" W/840817 transmittal ltr \* Yankee Atomic Electric Co 84/08/31 35pp 24193 203 24X Fiche 30-029:84/08/31,8408220012
- 8408240153 Rev 6 to emergency plan ST LAURENT, N N Yankee Atomic Electric Co 84/08/3; 20pp 26228 185 24% Fiche 50-029,84/08/31,8408240153
- P Operating license stage documents & correspondence
- 840B010141 Submits schedule to provide add1 info requested in NRC 840725 ltr re YAEC-1300P, "RELAP5YA Computer Program for LWR Sys Thermal-Hydraulic Analysis," submitted in response to TMI Action Item II K 3 30 KAY.J A Vankee Atomic Electric Co 84/07/25 CRUTCHFIELD D Operating Reactors Branch 5 2pp 25855 182 24X Fiche 50-029,84/07/25,8408010141
- 8408020039 Submits current status of updated SEP schedule containing intermediate milestones, per 831118 ltr in response to NRC 831006 request All scheduled items completed to date KAY, J A Yankee Atomic Electric Co 84/07/26 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 25880 260 24X Fiche 50-029,84/07/26,8408020039
- 8408070099 Forwards Ceneric Ltr 84-13, "Tech Specs for Snubbers," omitted from 840503 ltr to all SEP licensees NRC position that issue of Tech Specs for snubbers will be resolved on generic basis restated CRUTCHFIELD. D Assistant Director for Safety Assessment 84/07/31 KAY. J A Yankee Atomic Electric Co COUNBIL. N G Connecticut Yankee Atomic Power Co COUNBIL. N G Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp Fiche 50-000,84/07/31,8408070099
- 8408070472 Forwards "Reactor Coplant Pump Operation During Small Break LOCA Transients at Yankee Nuclear Power Station." per TMI Action Item II K 35. "Automatic Trip of Reactor Coolant Pump" & Generic Ltr 83-52
  THAYER, J K Yankee Atomic Electric Co. 84/08/01 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 25941 011 24X
  Fiche 50-027,84/08/01,8408070472
- --8408070478 "Reactor Coolant Pump Operation During Bmall Break LOCA Transients at Yankee Nuclear Power Station " LOOMIS, J N . PHILLIPS, J H . HUSAIN, A Yankee Atomic Electric Co YAEC-1437 B4/08/01 153pp 25941 013 24X Fiche 50-029,84/08/01,8408070472
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Bafety Issues" Svc list encl EISEMHUT, D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000,84/08/06.8408070110
- B40B140312 Responds to request for addl info re degraded grid voltage protection sys, clarifying installed second level undervoltage protection for number of relays & describing currently installed sys KAY, J A Yankee Atomic Electric Co B4/08/07 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 26042 356 24X Fiche 50-027,84/08/07.8408140312
- 8408130282 Forwards request for add1 info re 840307.13.0615 & 0725 requests for exemption from App K requirements, to proceed w/evaluation of YAEC-1431-P PAULSON, W A Derating Reactors Branch 5 84/08/08 KAY, J A Yankee Atomic Electric Co 5pp 26008 340 24X Fiche 50-027.84/08/08.8408130282
- 8408130358 Forwards BER re licensee 831105,08 & 840113 responses to Generic Ltr 83-28, Item 4 3, "Automatic Shunt Trip for Scram Breakers" Loss of power will disable shunt trip & drop control rods No further action required PAULSBN,W A Operating Reactors Branch 5 84/08/09 KAY,J A Yankee Atomic Electric Co 2pp 26010 067 24X Fiche 50-029,84/08/09,8408130358
- --8409130363 Safety evaluation re licensee 831105.08 & 840113 responses to Generic Ltr 83-28, Item 4 3. "Automatic Shunt Trip for Scram Breakers " Item does not apply to facility No further action required

  \* Office of Nuclear Reactor Regulation, Director, 84/08/09 3pp 26010 069 24% Fiche 50-029,84/08/09,8408130358

- 8408160149 Forwards summary of 840717 meeting w/util in Bethesda, MD re 810531 exemption request from App K requirements Summary includes schedule of submittals in response to NRC questions & attendee list PAULSON, W A Operating Reactors Branch 5 84/08/15 KAY, J A Yankee Atomic Electric Co Spp 26085 172 24X Fiche 50-029.84/08/15.8408160147
- B40B210419 Forwards Rev O to CYGNA rept, "Main Steam/Feedwater Piping Analysis Rept " Rept addresses SEP Topic III-6 re safe shutdown sys piping outside vapor container KAY, J A Yankee Atomic Electric Co 84/08/16 CRUTCHFIELD.D Operating Reactors Branch 5 tp 26178 196 24X Fiche 50-029.84/08/16.8408210419
- --B408210426 Rev O to "Main Steam/Feedwater Piping Analysis Rept.Yankee Nuclear Power Station " NGUYEN,T , MINICHIELLO,J , STIJGEREN,E V CYONA Energy Services E-Y-YR-B3033-4 ROO B4/07/31 48pp 26178 197 24X Fiche 50-029,84/08/16,8408210419
- B408210573 Notification of 840823 meeting w/util in Bethesda,MD to discuss SEP schedule BOYLE,M L. Bystematic Evaluation Program Branch 94/08/16 GRIMES,C I Systematic Evaluation Program Branch 2pg 26187 361 24X Fiche 50-029,84/08/16,8408210573
- 8408230162 Forwards response to concerns re staff review of proposed Change 180 concerning containment isolation sysper request Tests vent & drain connections reviewed to determine isolation

  KAY, J. A. Yankee Atomic Electric Co. 84/08/16 CRUTCMFIELD, D. Operating Reactors Branch 5. 5pp. 26209 277. 24X

  Fiche 50-029,84/08/16,8408230162
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for GLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT, D 0 Division of Licensing 84/08/20 Consolidated Edison Co of Naw York, Inc 17pp 26276 244 24X Fiche 30-000.84/08/20,8408200275
- G Inspection reports, IE Bulletins & correspondence
- B40B100053 Responds to IE Builetin 84-02, "Failures of QE Type HFA
  Relays Used in Class IE Gafety Sys " HFA relays having
  coils wound on nylon or Leran spools replaced w/new GE
  Century Series HFA relays having Tefici spool
  HEIDER, L. H. Yankee Atomic Electric Co. 84/07/23 MURLEY, T. E.
  Region I. Office of Director 2pp 25990 036 24X
  Fiche 50-029.84/07/23.8408100053
- 8408190573 Forwards IE Insp Rept 50-029/84-12 on 840626-29 No violations noted MARTIN,T T pivision of Engineering & Technical Programs H4/07/26 HEIDER.L H Yankes Atomic Electric Co 2pp 26079 217 24X Ficho 50-029.84/07/26.8408150573
- --84081305B0 IE Insp Rept 50-029/84-12 on 840626-29 No violations noted Major areas inspected status of programs for shift staffing & augmentation, public info, licensee audits & emergency worker protection MOLTNER, E., CROCKER, H. W. Region 1, Office of Director 84/07/16 3pp 26079 217 24X Fiche 50-029,84/07/26,8408150573
- 8407250227 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Gonsolidated Edison Co. of New York, Inc. 119pp 25865 047 24X Fiche 30-000,84/07/27,8407250227
- 8408160073 Forwards Enforcement Conference Rept 50-029/84-16 on B40621 BTAROSTECKI,R Division of Project & Resident Programs 84/07/27 HEIDER,L H Yankee Atomic Electric Co 2pp 26108-226 24X Fiche 50-029,84/07/27,8408160073
- --8408160082 IE Enforcement Conference Rept 50-029/84-16 on 840621 Major areas discussed failure to procedurally implement required security program compensatory measures Bareguards info deleted (ref 10CFR73 21), EICHEMHOLZUM . KEIMIQUR . WENZINGER. E. Region i, Office of Director 84/07/27 4pp 26108 228 24X Fiche 50-029,84/07/27,8408160073
- 8408200476 Forwards IE Bafaguards Insp Rept 50-029/84-09 on 840514-17 No violations noted MARTIN, T T Division of Engineering & Technical Programs, 84/07/30 HEIDER: L H Yankee Atomic Electric Co 2pp. 26138, 283 24X Fichs 50-029, 84/07/30, 8408200476

- --8408200487 IE Safeguards Insp Rept 50-029/81-09 on 840514-17 No violations noted Major areas inspected security organization, security program audit & physical barriers Safeguards info deleted (ref 100FR73 21 & 2 790) MADDEN.W J. KEIMIG.R R. Region 1. Office of Director 84/07/26 Spp 26138 285 24X Fiche 50-029/84/07/30.8408200476
- 8408010333 IE Info Notice 84-59, "Deliberate Circum enting of Station Health Physics Procedures " Svc list encl JORDAN,E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 83pp. 26068 001 24% Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Furlfying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN, E 1. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc. 123pp 26067 158 24X Fichs 50-000 84/08/06, 8408010337
- 8408070120 IE Info Notice 84-41, "Overexposure of Daver in PUR Refueling Cavity " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York, Inc. 120pp 24129 118 24% Fiche 90-000,84/08/08.8408070120
- 8408130350 Ack receipt of 840713 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-027/24-06 STAROSTECKI.R Division of Project & Resident Programs 84/08/09 HEJDER.L N Yankee Atomic Electric Co 2pp 26010 245 24X Fische 50-027,84/08/09.8408130350
- --B40Bi30354 Responds to NRC 840613 itr re violations noted in IE Safeguards Insp Rept 50-029/84-06 Corrective actions effectiveness of mgt control sus will be improved Safeguards info deloted (ref 100FR73 21) VANDENBURGH, D. Yankee Atomic Electric Co. 84/07/13 MURLEY, T.E. Region I. Oppice of Director. Spp. 26010 247 24X Fiche 50-029, 84/08/09, 8408130350
- B408070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Toletherapy Treatments." Suc list encl GRACE, J. N. Division of GA. Safeguards & Inspection Programs (Post B30103) 84/08/10 Consolidated Edison Co. of New York. Inc 125pp 26130-001 24x Fichs 50-000.84/08/10.84080/0376
- 8408270577 Forwards Insp Rept 50-029/84-07 on 840320-0630 No violations nated STAROSTECKI.R Division of Project & Resident Programs 84/08/10 HEIDER.L H Yankee Atomic Electric Co 2pp 26256 068 24X Fiche 50-029.84/08/10.8408270577
- --B40B270579 Insp Rept 50-029/84-07 on B40320-0630 No violations noted Hajor areas inspected licensee action on previous insp findings.operational safety verification reviews & reviews of plant events & LERs EICHENHOLZ-H , WENZINGER, E Region (, Office of Director B4/08/06 33pp 26256 070 24% Fiche 50-029, B4/08/10.840B270577
- B40B100009 IE Info Notice B4-63. "Defective RHR Replacement Piping "
  Syr list encl
  JDRDAN-E L. Division of Emergency Proparedness & Engineering
  Response (Post 830103) B4/08/13 Consolidated Edison Co of New
  York, Inc. 119pp 26197 218 24% Fiche 50-000, 04/08/13, 8408100009
- 8408300107 Forwards Insp Rept 50-029/84-14 on 840709-13 No violations noted MARTIN.T T Division of Engineering & Technical Programs 84/08/13 HEIDEN.L H Yankes Atomic Electric Co 2pp 26308 107 24X Fiche 50-029,84/08/13,8408300107
- --8408300116 Insp Rept 50-029/84-14 on 840709-13 No violations noted Major areas inspected actions in response to IE Bulletins 79-02 re pipe support design.79-04 re swing check valves & 79-07 & 79-14 re seismic analysis of piping NARROW.L., DURR.J P Region i. Office of Director 84/08/05 7pp 26308 109 24x Fiche 50-029,84/08/13.8408300107
- 8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Syc list encl JURDAN: L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc. 104pp. 25198 093 24% Fiche 50-000,84/08/19,8408100038
- B40Bi00021 IE Info Notice 84-45, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/08/16 Consolidated Edison Co of New York, Inc. 118pp 26198 OOI 24X Fiche 50-000.84/08/16.8408100021

- 8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Diiven Auxiliary Feedwater Train " Svc list encl URBAN,F t. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 001 24x Fiche 50-000.84/08/17,8408100055
- B408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/08/17 Consolidated Edison Co of New York Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26327 008 24X Fiche 50-000,84/08/21,8408210142
- S Reportable occurrences, LERs & related correspondence
- 8408070205 PNO-1-84-045 on 840802, personnel noted smoke coming from cobicle in switchgear room Caused by tripped breaker due to electrical fault during surveillance testing Damaged bus demergized Licensee decreasing power for plant shutdown ELSABSER, T., GREENMAN.E. Region 1. Office of Director 84/08/02 2pp 25949 268 24% Fiche 50-027.84/08/02.8408070205
- 8408090104 LER 84-011-00 on 840703 during review of documentation accompanying recent replacement of two pressurizor code safety valves, determined lift setpoint of safety valve PR-SV-182 exceeded Tech Specs W/840802 ltr ELLIS, D. K., ST LAURENT, N. N. Yankee Atomic Electric Co. 84/08/02 3pp. 25992 239 24% Fichs 50-029,84/08/02,8408090104
- 8408210350 Forwards LER 84-011-00 ST LAURENT, N N Yankee Atomic Electric Co 84/08/02 MURLEY, T E Region 1, Office of Director ip 26179 195 24X Fiche 50-029, 84/08/02, 8408210350
- 8408160527 LER 84-012-00 on 840712, automatic reactor scram followed by turbine trip, cross tie of ctr bus via 62GTX relay % start of emergency diesel generator 2 occurred Cause (indeterminable Effects of scram mitigated W/840B10 ltr MAY, E L . ST LAURENT.N Yankee Atomic Electric Co 84/08/10 2pp 26108 040 24X Fiche 50-027,84/08/10.8408160527
- 8408300441 Forwards LER 84~012-00 ST LAURENT, N N Yanker Atomic Electric Co 84/08/10 MURLEY, T & Region 1. Office of Director 1p 26314 215 24X Fiche 50~029.84/08/10.8408300441
- 8408230077 Summary of 840807 operating reactor events meeting re occurrences since 840719 meeting List of attendees, significant elements 3 status of previous assignments encl CRUTCHFIELD.D Assistant Director for Safety Assessment 84/08/16 EISENNUT.D G Division of Licensing 20pp 26233 249 24X Fiche 50-000.84/08/16.8408230077
- 8408230540 LER 84-011-01 on 840703 during documentation review, lift aetpoint of safety valve PR-5V-182 found to exceed Toch Spectolerance Cause not stated Proposed Tach Specchange will be submitted M/840817 ltr ELLIS,D (V, ST LAURENT,N N Yankee Atomic Electric Co 84/08/17 3pp 26212 353 24X Fiche 50-027,84/08/17,8408230540
- DOCKET 50-30 PLUM BROOK RESEARCH REACTOR FACILITY

  P Operating license stage documents & correspondence
- 8408210629 Advises that Licenses TR-3 & R-93 should be reinstated to prior possess-but-not-use status or revised dismantlement plans should be submitted, por 10CFR50 82 or 10CFR50 70, respectively Plans should update mgt controls
  THOMAS, C O Standardization & Special Projects Branch 84/06/26
  RICHLEY, E A National Agronautics & Space Admin 3pp 26187 357 24X Fiche 50-030,84/06/26,8408210629

- W. Decommissioning Stage Documents & Correspondence
- 8408240107 Requests submittal of either request for reinstatement of possess but-not-use license or revised dismantlement plan w/schedule commitments Dismantlement authorized in 1981 delayed by lack of funds
  THOMAS.C.O. Standardization : Special Projects Branch 84/08/16
  RICHLEY.E.A. National Aeronautics & Space Admin 5pp. 26255-313-24X Fishe 50-030,84/08/16,8408240107

DOCKET 50-54 UNION CARBIDE RESEARCH REACTOR

- @ Inspection reports, IE Bulletins \* correspondence
- 8408270510 Forwards Insp Repts 50 054/84-02 % 70-0687/84-02 on 840709-11 No violations observed STAROSIECKI, R Division of Project & Resident Programs 84/08/07 MCGOVERNI J Union Carbide Corp 2pp 26256 162 24X Fichs 50-054,84/08/01,8408270510
- --84082/0518 Insp Repts 50-054/84-02 & 70-0687/84-02 on 840709-11 No deviations of violations identified Major areas inspected organization, facility changes & mods, safety committees, nuclear criticality safety & radiation protection ROTH, J. Region 1, Defice of Director ELEASSER, T.C. Division of Project & Resident Programs 84/08/02 App 26256 164 24% Fiche 50-054,84/08/07,8408270510

DOCKET 50-57 STATE UNIV OF NEW YORK RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

- 8408060162 Forwards Rev 1 to "Nuclear Science & Technology Facility Emergency Plan " Amend request will be forwarded upon completion & approval by nuclear safety committee HENRY.L G New York. State Univ of Buffalo. NY 84/07/31 THOMAS.C Standardization & Special Projects Branch ip 25933 013 24X Fiche 50-057.84/07/31.8408060162
- --B408060167 Rev 1 to "Nuclear Science & Technology Facility Emergency Plan" \* New York, State Univ of, Buffalo, NY 84/07/31 36pp 25933 014 24% Fiche 50-057,84/07/31,8408060162

DOCKET 50-59 TEXAS ARM UNIV RESCARCH REACTOR

R Periodic operating reports & related correspondence

B408150371 "Annual Operations Rept of Texas A&M Univ AGN-201M Training Reactor, June 1983 - May 1984 " W/840706 ltr CARPENTER, D C., ERDMAN, C A. Texas A&M Univ , College Station, TX B4/05/31 COLLINS, J. Region 4, Office of Director 10pp 24075 191 24X Fiche 50-059, B4/05/31, B408150371

DOCKET 50~62 UNIV OF VIRGINIA RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8408010391 Forwards revised emergency plan, incorporated add1 info, per request Info should resolve plan prior deficiencies Univ of Virginia reactor safety committee will review plan Approval expected MULUER, R U Virginia, Univ of, Charlottesville, VA 84/07/12 THOMAS, C U Standardization & Special Projects Branch ip 25866 063 24X Fiche 50-062,84/07/12,8408010391

840B010390 Resubmits 840712 request for approval of emergency plan Ltr notarized per request Univ of Virginia reactor safety committee reviewed & approved emergency plan on 840725 MULDER, R V Virginia, Univ of. Charlottesville, VA 84/07/26 THDMAS. C O Beandardization & Special Projects Branch 1p 25866 307 24X Fiche 50-062.84/07/26.8408010350

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

G Adjudicatory correspondence

B40B040183 Responses to OE & NRC filings re California PIRG participation in proceeding BARCOM, G Public Interest Research Group, California DBB 749 84/07/30 6pp 25932 253 24X Fiche 50-070, B4/07/30, 8408060183

- 8408060191 Revised contentions & responses to ASLB 810703 order reparticipation in proceeding
  BARLUNG Public Interest Research Group California 84/07/31
  Atomic Safety and Licensing Board Panel 20pp 25932 259 24x
  Fiche 50-070,84/07/30,8408060183
- --8408060197 Declaration of California PIRG members Notice of appearance encl BATSEL, J MEEK, S. BARLOW, G. Public Interest Research Group, California 84/07/26 3pp 25932 279 24Y Fiche 50-070 84/07/30 8408060183
- --8498060206 Request for readmission to proceedings Statement of correct address t Certificate of Svc encl BARLON.G Public Interest Research Group, California 84/06/08 Commissioners 4pp 25932 282 24X Fiche 50-070.84/07/30.
- 8408060209 Submittal of new info re 840424 Morgan Hill earthquake Request to consolidate party opposed TURK, J. Turk, J. DSB 748 B4/07/31 Atomic Safety and Licensing Board Panel 14pp 25923 310 24X Fiche 50-070,84/07/31, 8408060209
- B408220288 Prehearing conference order directing staff. OE & J Turk to confer re contentions & rept results by 84:117 & California PIRO to serve & file chronology of events re involvement by 840907 Served on 840821 LINENBERGER, C., FRYEL JH. Atomic Bafety and Licensing Board Panel DSB 205 B4/08/20 Office of the Crecutive Legal Director Slpp 26193 084 24% Fiche 50-070.84/08/20,8408220288
- T Hearing transcripts on non-antitrust matters
- 8408140269 Transcript of 840809 hearing in San Francisco.CA Pp 1-230 \* Atomic Safety and Licensing Board Panel 84/08/09 231pp 26055 074 24X Fiche 50-070,84/08/09,8408140269

DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

P Operating license stage documents & correspondence

- B40B090335 Forwards "Proposed Tech Specs for GE Nuclear Test Reactor."

  per B40601 request New License Condition 2 B also encl
  CUNNINGMAN.C E General Electric Co B4/08/02 THOMAS.C O
  Standardisation & Special Projects Branch 3pp 25971 057 24X

  Fiche 50-073.84/08/02.8408090335
- ---B40B090337 "Proposed Tech Specs for GE Nuclear Test Reactor "

  \* General Electric Co NCDD-12728A 84/07/31 Sipp 25971 Ob0
  24X Fiche 50-073,84/08/02,840B090335

DOCKET 50-89 GENERAL ATOMIC CD

- F Security, medical, emergency & fire protection plans
- 8408270311 Forwards ltrs documenting cooperation w/local law enforcement agencies & medical facilities re radiological contingency plan MOMRY, W R GA Technologies, Inc /General Atomic Co D4/08/22 CUNNINOHAM, R Division of fuel Cycle & Material Safety THOMAS, C D Standardization & Special Projects Branch 4pp 26241 004 24X Fiche 50-089,84/08/22,8408270311
- P Operating license stage documents & correspondence
- 8405160470 Forwards Amend 25 & 31 to Licenses R-38 & R-67, respectively & notice of issuance & availability Amends change corporate name of licenses to GA Technologies. Inc EISCNHUT.D 0 Division of Licensing 84704/27 MOWRY, W R GA Technologies, Inc /General Atomic Co 3pp 24492 253 24X Fiche 50-087,84704/27,8405160470
- --B403160473 Amends 25 & 31 to Licenses R-3B & R-67, respectively, changing corporate name of licensee to GA Technologies. Inc EISENHUT, D Q Division of Licensing 84/04/27 4pp 24492 256 24X Fiche 30-089, 84/04/27, 8405160470
- --8405160476 Notice of issuance & availability of Amends 25 & 31 to Licenses R-38 & R-67, respectively THOMAS.C O Standardization & Special Projects Branch 84/04/27 2pp 24472 260 24% Fiche 50-089, 84/04/27, 8405160470

DOCKET 50-97 CORNELL UNIV ZERG POWER REACTOR

F Security, medical, energency & fire protection plans

B40B210097 Forwards "Emergency Plan Evaluation Rept.Cornell Univ " Plan meets requirements of regulations & guidelines & is acceptable THOMAS,C D Standardization & Special Projects Branch 84/08/15 CLARK,D D Cornell Univ, Ithaca, NY 3pp 26195 213 24X Fiche 50-097,84/08/15:6408210097

--8408140349 "Emergency Pian Evaluation Rept.Cornell Univ "

\* Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/31 4pp 26195 216 24X Fiche 50-097,84/08/15.8408210097

DOCKET 50-112 UNIV OF CKLAHOMA RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8408030066 Ack receipt of itr approving emergency plan Plan implementation begun Requests extension for completion until 84130 JENBEN,C M Gilahoma. Univ of Norman, GK 84/07/24 THOMAS.C G Standardization & Special Projects Branch ip 25917 322 24X Fiche 50-112.84/07/24.8408030066

DOCKET 50-116 ICHA STATE UNIV RESEARCH REACTOR

F Security, medical, energency & fire protection plans

B40B210101 Forwards "Emergency Plan Evaluation Rept. Iowa State Univ "
Evaluation revised to correctly describe status of facility
Plan meets requirements of regulations & guidelines & is
acceptable
THOMAS.C.O Standardisation & Special Projects Granch 84/08/14
HENDRICKSON.R Iowa State Univ . Ames, IA Jpp 26195 345 24X
Fiche 50-116.84/08/14.8408210101

~-8408210117 Revised "Emergency Plan Evaluation Rept. Iowa State Univ" e Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/31 3pp 26195 348 24% Fiche 50-116.84/08/14, 8408210101

### V Operator Examinations

840B140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners HALKER,R D. Region 3. Office of Director 8470B/10 Michigan, Univ of Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10.8408140426

DOCKET 50-123 UNIV OF MISSOUR! RESEARCH REACTOR
V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners WALKER,R D Region 3. Office of Director 84/08/10 Michigan. Univ of. Ann Arbor. MI 2pp 24051

DOCKET 50-133 HUMBOLDT DAY POWER PLANT, UNIT 3

P Operating license stage documents & correspondence

8408020056 Forwards Application Request 84-01 for amend to License DPR-7.reflecting plans for facility decommissioning & maint of safe storage condition for 30 yrs before ultimate removal Fee encl
SCHUVLER, JO Pacific Oas & Electric Co 84/07/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 25894 245 24X Fiche 50-133,84/07/30.8408020054

--B408020063 Application Request B4-01 for amend to License DPR-7, reflecting plans for facility decommissioning & maint of safe storage condition for 30 yrs before ultimate removal Two Bechtel decommissioning repts encl
SCHUYLER.J O Pacific Gas & Electric Co 84/07/30 4pp 25894 247 24X Fiche 50-133,84/07/30,8408020036

~-8408020067 "SAFSTOR Decommissioning "
# Pacific Gas & Electric Co 84/07/30 374pp 25894 251 24X
Fiche 50~133,84/07/30,8408020056

--8408020070 "For Decommissioning of Humboldt Bay Power Plant.Unit 3," environ rept AUSMUS.B 5 . HOFMAN.L A TRINDSKEY.P A Bechtel Corp 84/07/31 492pp 25895 285 24X Fiche 50-133.84/07/30.8408020056

8408070110 Generic Ltr 84-19 to all licensess of operating reactors, applicants for OLs & holders or CPs re availability of Suppl i to NUREG-0933. "Prioritization of Generic Safety Issues" Svc list encil EISENNUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York. Inc. 18pp. 26129 238 24X Fiche 50-000.84/08/06,8408070110

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for QLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT,D 0 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 50-000,84/08/20,8408200275

Q Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JURDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 117pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 85pp. 26068 001 24% Fiche 50-000, 84/08/06, 8408010333

B40B010337 IE Info Notice B4-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/0B/04 Consolidated Edison Co of New York, Inc 123pp 24047 158 24X Fiche 50-000.84/0B/04,8408010337

8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svt list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/09/08 Consolidated Edison Co of New York Inc 120pp 26129 118 24X Fiche 50-000.84/08/08.8408070120

8408070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list oncl GRACE.J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fishe 50-000.84/08/10.8408070376

840B100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New
York, Inc. 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list enc!

JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co. of New York, Inc. 104pp 26178 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Syc list encl

list encl
JGRDAN,E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New
York, Inc. 118pp 26178 001 24X Fiche 30-000.84/08/16,8408100021

840BiQQ053 lE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Syc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Natice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26327 008 24X Fiche 50-000.84/08/21,8408210142

- DOCKET 50-134 WORCESTER POLYTECH INST RESEARCH REACTOR

  F. Security, medical, emergency & fire protection plans
- 8408040144 Forwards "Emergency Plan Evaluation Rept. Worcester Polytechnic Inst " Plan neets requirements of 10CFR50, App E & ANSI/ANS-15 14-192 Full implementation requested within 120 days of itr receipt THOMAS.C O Standardization & Special Projects Branch 84/07/26 MILBURL C Worcester Polytechnic Institute, Worcester, MA 3pp 25936-344 24X Fiche 50-134.84/07/26.8408060146
- --84080&01&0 "Emergency Plan Evaluation Rept, Worcester Polytechnic Inst "
  \* NRC No Detailed Affiliation Given 84/07/31 3pp
  25936 347 24X Fiche 50-134.84/07/26,84080&0146

DOCKET 50-139 UNIV OF WASHINGTON RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

B40B170040 Forwards amend to security plan Amend withheld (ref 10CFR73 21) ROBKIN,M A Washington, Univ of, Seattle, WA 64/07/27 Office of Nuclear Material Safety & Safeguards, Director 1p 2611B 357 24X Fiche 50-139,84/07/27,840B170040

#### DOCKET 50-142 UCLA TRAINING REACTOR

- F Security, medical, emergency & fire protection plans
- 8408210161 Forwards IE Safeguards Insp Rept 50-142/84-01 on 840320-21 & 0604-07 No violations noted SCHUSTER.M D Region 5. Office of Director 84/07/26 WEGST.W California, Univ of. Los Angeles. CA ip 26180 353 24X Fiche 50-142.84/07/26.8408210161
- --8408210167 IE Safeguards Insp Rept 50-142/84-01 on 840320-21,0404-07 & 0716 No violations noted Major areas inspected security plan & procedures, access control, alarm sys.locks & surveillance Details withheld (ref 10CFR2 790) NORDERHAUG, L R , SCHAFFER, D , SCHUSTER, M D Region 5, Office of Director 84/07/26 ip 26/80 354 24X Fiche 50-142,84/07/26,8408210161

### G Adjudicatory correspondence

- 8408010207 Reply to Committee to Bridge the Gap 840703 response to univ 840614 request to uithdraw application for renewal of license ASLB should grant univ request for withdrawal Certificate of Svc encl WDDDHEAD, C.P. Hearing Branch 4 DSB 677 84/07/27 Atomic Safety and Licensing Board Panel 9pp 25855 173 24x Fiche 50-142.84/07/27.8408010207
- B408070386 Response opposing staff proposed conditions for UCLA withdrawal of license renewal application ASLB should follow required practice consistent w/NRC case law Certificate of Bvc encl HIRBCH, D Committee to Bridge the Gap DBB 801 84/08/01 Atomic Safety and Licensing Board Panel 83pp 25945 280 24X Fiche 50-142,84/08/01,8408070386
- B40B070474 Informs of Unsuccessful attempts to reach UH Frye to inform of delay in pleading re UCLA reactor renewal due to breakdown of typewriter Pleading sent out by express mail to ensure prompt delivery Related correspondence HIRSCH, D Committee to Bridge the Gap DBB 805 84/08/01 FRYEL, JH Atomic Safety and Licensing Board Panel 1p 25940 342 24X Fiche 50-142,84/08/01,8408070474
- 8408080239 Memorandum & order requesting further elaboration of staff position re applicability of Atomic Energy Act, Section 189 to UCLA request to decommission reactor & terminate license, by 840907 Served on 840806.

  FRYE.J H Atomic Safety and Licensing Board Panel DSB 829 84/08/04 Office of the Executive Legal Director 2pp 23967 043 24X Fiche 50~142,84/08/06,84080808239
- 84083i0207 Requests prompt notification when petitions for leave to intervene & for hearing may be formally filed on proposed parallel license amends & related 10CFR50 82 dismantlement/license termination application
  HIRBCH.D Covernment Accountability Project DBB 425 84/08/25
  Office of the Secretary of the Commission 3pp 86318 064 24X
  Fiche 50-142.84/08/25.8408310207

- P Operating license stage documents & correspondence
- 8408310152 FD1A request for all correspondence or other documents hetween UCLA & NRC re incident occurring in early Feb 1984, which led to current shutdown of UCLA research reactor HIR8CH.D Committee to Bridge the Cap 84/04/24 Office of Administration ip 26351 356 24% Fiche 50-142,84/04/24. 8408310152
- 8408310151 Responds to FOIA request for documents between UCLA & NRC recurrent reactor shutdown & records re proposed work to be performed during shutdown Forwards WF Wegst B40213 1tr to NRC FELTON.J M Division of Rules and Records 84/06/04 HIRSCH.D Committee to Bridge the Cap ip 26351 355 24X Fiche 50-142.84/06/04.8408310151
- B40B010339 Application to terminate License R-71 Request for amend to Tech Specs to provide immediate relief from reactor calibr, maint & reporting requirements will be submitted separately HE0GT.W F California, Univ of, Los Angeles, CA B4/07/26 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 25866 072 24x Fiche 50-142.84/07/26, B40B010339
- 8408270142 Forwards M Conzalez-Cuesta memo re assessment of risk from seismic errors in design & const.per 840810 telcon OKRENT.D California. Univ of. Los Angeles. CA 84/08/13 DEYGUNG.R Director's Office. Office of Inspection and Enforcement 8pp 26237 270 24X Fiche 50-142.84/08/13.8408270142
- G Inspection reports. IE Bulletins & correspondence
- 8408210161 Forwards IE Safeguards Insp Rept 50-142/84-01 on 840320-21 & 0404-07 No violations noted SCHUSTER.M D Region 3. Office of Director 84/07/26 WEG87, W California Univ of Los Angeles, CA 1p 26180 353 24% Fiche 50-142,84/07/26,8408210161
- --8408210167 IE 8afeguards Insp Rept 50-142/84-01 on 840320-21,0604-07 & 0716 No violations noted Major areas inspected security plan & procedures, access control, alarm sys.locks & surveillance Details withheld (ref 100FR2 790) NORDERHAUG, L R , SCHAEFER, D , SCHUSTER, M D Region 5, Defice of Director 84/07/26 ip 26180 354 24X Fiche 50-142,84/07/26,8408210161
- R Periodic operating reports & related correspondence
- 8408300107 "Annual Rept 1983, Nuclear Energy Lab " W/830821 ltr OSTRANDER, N C California, Univ of, Los Angeles, CA 83/12/31 14pp 26314 335 24X Fiche 50-142,83/12/31,8408300107

DOCKET 50-150 OHIO STATE UNIV RESEARCH REACTOR
V Operator Examinations

B40B140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners WALKER: R D Region 3: Office of Director 84/08/10 Michigan. Univ of. Ann Arbor. MI 2pp 26051

DOCKET 50-151 UNIV OF ILLINDIS RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

- B408010302 Forwards IE Insp Repts 50-151/84-01 & 50-356/84-01 on B40617-22 No noncompliance nated NGRELIUS, C E Region 3, Office of Director 84/07/19 MILEY, & H Illinois, Univ of, Urbana, IL 2pp 25866 117 24X Fiche 50-151,84/07/19.8408010302
- --8408010308 IE Insp Repts 50-151/84-01 & 50-356/84-01 on 840619-22. No noncompliance noted Major areas insected requalification training fuel handling & surveillance activities, radiation control practices & emergency planning TAUBLING. T N Region 3, Office of Director THOMAS, C C., HYDER, J E. Los Alamos Scientific Laboratory 84/07/18 10pp 25866 119 24X Fiche 50-151,84/07/19,8408010302
- B40B030276 Certifies nuclear reactor committee formal approval of additions & changes to emergency plan on 840723 Last sentence in Section 3 4 3 changed for clarity BECK, 9 P . HOPKE, P K . MILEY, 9 H . Illinois. Univ of Urbana. IL. B407/24 THOMAS. C O Standardization & Special Projects Branch ip 25917 258 24X Fiche 50-151.84/07/24.8408030276

- Q Inspection reports: [E Bulletins ' correspondence
- 8408010302 Forwards IE Insp Repts 50-151/84-01 & 50-355/84-01 on B40619-22 No noncompliance mated NORELIUS, C.E. Region 3, Office of Director 84/07/19 Miley, G.H. Illinois, Univ. of, Urbana, IL. 2pp. 25866 117 24x Fiche 50-151.84/07/19,8408010302
- --8408010308 IE Insp Repts 50-151/84-01 & 50-356/84-01 on 640619-22
  No noncompliance noted Major areas inspected requalification training fuel handling & surveillance activities radiation control practices & emergency planning
  TAUBLING. T N. Region 3. Office of Director THOMAS. C C .
  HYDER. JE Los Alamos Scientific Laboratory 84/07/18 10pp
  25866 119 24X Fiche 50-151.84/07/19.8408010302
- S Reportable occurrences, LERs & related correspondence
- 8408300184 RC on 840816, fast transient control red remained in withdrawn position 20 s after air released Caused by swalling of control rod Nylon piece removed & replaced Section of rod where air supplied cleaned BECK, 8 P. STUBBINS. J F. Illinois. Univ. of, Urbana, IL. 84/08/24 Record Services Branch (Document Control Desk) ip 26308-336-24X Fiche 50-151.84/08/24,8408300184

#### V Operator Examinations

840B140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners WALKER, R.D. Region 3, Office of Director 84/09/10 Michigan. Univ of. Ann Arbor. MI 2pp 26031

DOCKET 50-155 BIO ROCK POINT NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

- 8408210498 Responds to NRC 840601 ltr approving util 840417 request for schedule change for 1984 annual medical exercise Annual medical exercise schedule medical exercise scheduled for 841030-31 KRICH-R M Gonsumers Power Co 84706/28 KEPPLER, J Q Region 3, Office of Director 1p 26148 174 24X Fiche 50-155,84706/28, 8408210498
- 840B07036B Advises of FEMA 840706 completion of analysis of elect notification sys Sys adequate eliminating caveat in FEMA 830516 finding FEMA rept encl Related correspondence OUDDARD,R J Hearing Branch 3 DSB 817 B470B702 BLDCH,P B , PAR18,O H , SHON,F J Atomic Safety and Licensing Board Panel 72pp 25744 210 24X Fiche 50-155,8470B702,840807036B
- 8408130370 Responds to 840711 ltr relaccess authorization program Access authorization list development & maint functions being transferred to Div of Resource Mgt Notification of terminated employees will be on as needed basis AXELBONN W. Region 3. Office of Director 84/08/07 VANDEWALLE, D. J. Consumers Power Co. 1p. 26010 359 24X Fiche 30-000.84/08/07.8408130370
- --B408130376 Submits list of items discussed in B40703 telcon No termination notifications received Updates on activities will be submitted Concurrence needed for documentation LATHMELL.H J Consumers Power Co B4/07/11 CREED.J Region 3. Office of Director 2pp 26010 359 24X Fiche 50-000. B4/08/09, 8408130370
- 8408140130 Ack receipt of 831214 1tr informing NRC of steps taken to carrect violations noted in IE Insp Rept 50-195/82-13
  LITHLENUS Region 3. Office of Director 84/08/10 DEWITT, R B
  Consumers Power Co 1p 26047 011 24X Fiche 50-155, 84/08/10,
- 8408270390 Ack receipt of 840727 ltm informing NRC of steps taken to correct violations noted in Insp Rept 50-135/84-03
  PAPERIELLOC J Region 3, Office of Director 84/08/22
  DEWITTER 6 Consumers Power Co 2pp 26240 197 24X
  Fiche 50-155,84/08/22.8408270390
- --B408270392 Responds to NRC B40627 ltr re violations noted in Insp Rept 50-155/B4-03 Corrective actions site emergency plan inplementing procedure reporting time requirements revised, following 840822 incident VANDEWALLE, D J Consumers Power Co B4/07/27 KEPPLER, J G Region 3. Office of Director Jpp 26240 199 24X Fiche 50-135,84/08/22,8408270390

- G Adjudicatory correspondence
- 8408010240 Forwards affidavits of F Turski & C Norman, in response to request made by Judge Bloch during 840713 & 16 telcons reclarification of relationship between I ton jib crane & 75 ton gantry crane Related correspondence COPELAND, V G Isham, Lincoln & Beale COPELAND, V G Consumers Pawer Co DSB 673 84/07/30 BLOCH, P B , SHON, F J , PARIS, O H Atomic Safety and Licensing Board Pahel 2pp 25854 071 24X Fiche 50-155/84/07/30, 8408010260
- --8408010263 Affidavit of A Turski re relationship between 1 ton jib crane & 79 ton single gantry trane in context of seismic events TURSKI.F A Consumers Power Co 84/07/20 7pp 25854 073 24X Fiche 50-155.84/07/30.8408010260
- --B40B010269 Affidavit of CR Norman re relationship between I ton jib crane t 75 ton single log gantry crane in context of seismic event NGRMAN.CR Whiting Corp NORMAN.CR Consumers Power Co 84/07/23 Atomic Safety and Licensing Board Panel 9pp 25854 080 24X Fiche 50-155,84/07/30.8408010260
- B40B070368 Advises of FEMA 840706 completion of analysis of elect notification sys Sys adequate eliminating caveat in FEMA 830516 finding FEMA rept encl Related correspondence GODDARD.R J. Hearing Branch 3 DSB 817 84/08/02 BLOCH,PB., PARIS.O.H., SHON.F.J. Atomic Safety and Licensing Board Panel 72pp 25944 210 24X Fiche 50-155.84/08/02,8408070368
- 8408080224 Forwards Whiting Corp B40727 rept re analysis of structural adequacy of jib crane to withstand seismic event Rept referenced in B40730 response to ASLB request for clarification reg jib crane/gantry crane relationship COPCLAND, V G Isham, Lincoln & Beale COPELAND, V G Consumers Power Co DSB 823 84708706 BLOCK, P B , PARTS, O H , SHON, F J Atomic Safety and Licensing Board Panel 14pp 25967 034 24% Fiche 50-135,84708/06,8408080224
- 8408210327 Motion for show cause order on whether util financially qualified to safely modify & maintain modified spent fuel pool as proposed O'NE(LL.) O'Ne(I), J DSB 179 84/08/15 Office of Nuclear Reactor Regulation, Director 4pp 26179 274 24X Fiche 50-155.84/08/15.8400210327
- --8408210330 Motion for enforcement of Atomic Energy Act & 10CFR50 33(f) re whether util financially qualified to safely modify & maintain modified spent fuel pool Certificate of Svc encl O'NEILL.J O'Neill. J 84/08/15 Atomic Safety and Licensing Board Fanel 18pp 26179 278 24X Fiche 50-155.84/08/15, 8408210327
- --B408210337 Motion for default against staff re ability of monitors to operate during accident conditions, inadequate address of root cause of multiple systematic errors & possibility of further errors Certificate of Svc encl
  O'NCILLJ O'Neill. J B4/08/14 Atomic Bafety and Licensing Board Panel 2pp 26179 276 24X Fiche 50-155,84/08/15.
- 8408270164 Forwards affidavit of NC Chokshi attesting to adequacy of seismic stability of jib crane issue raised during hearings on seismic adequacy of util semigantry crane in 1983 Related correspondence GBDDARD.R J Hearing Branch 3 DSB 305 84/08/22 BLOCH,P.B., SHON.F.J., PARIS,O H. Atomic Safety and Licensing Board Panel 1p 26246 089 24X Fiche 50-155,84/08/22,8408270164
- --8408270170 Affidavit of NC Chokshi attesting to adequacy of seismic stability of jib crane.issue raised during hearings on seismic adequacy of util semigantry crane in 1983 Related correspondence CHOKABHINC Hydrologic & Geotechnical Engineering Branch 84/08/22 3pp 26245 090 24X Fiche 50-155,84/08/22.8408270164
- B40B280244 Motion re violation of full disclosure requirement Documents detailing number of areas in which full disclosure requirements violated & Cartificates of Syc encl Related correspondence
  D'NEILL.J P O'Neill, J DSB 324 84/08/22 Atomic Safety and Licensing Board Panel 5pp 26279 206 24X Fiche 50-155.84/08/22, 8408280244
- 8408280391 Memorandum & order deciding three motions filed by J D'Neillin 840625 document, including motion to strike testimony of R Krich-relief from alleged violation of full disclosure requirement & financial qualifications Served on 840628 BLOCH-F F, SHON, F J Atomic Safety and Licensing Board Panel DSB 330 84/08/27 O'NEILL J O'Neill, J 4pp 26280 034 24X Fiche 50-155.84/08/27.8408280391

;

- 8408300152 Initial Decivion 79-432-11 LA on all remaining issues, including Christa-Maria Contention 8 to O'Neill Contention IIIE-2 re reliability of makeup water sys Served on 840829 at Atomic Safety and Licensing Board Panel DSB 387 84/08/29 279pp 26302 240 24X Fiche 30-155.88/08/29,8408300152
- P Operating license stage documents & correspondence
- 8408030109 Forwards application for amend to DPR-6 revising Tech Specs re administrative controls & definitions per NRC request VANDEWALLE, D.J. Consumers Power Co. 84/07/30 CRUTCHFIELD, D. Operating Reactors Branch 5 1p. 25916-087 24X Fiche 50-155,84/07/30,8408030109
- --8408030113 Application for amend to DPR-6, revising Tech Specs re administrative controls & definitions to reflect 10CFR30 72 & 30 73 reporting requirements REYNOLDS.J W Consumers Power Co 84/07/30 2pp 25916 088 24X Fiche 50-155.84/07/30,8408030109
- --8408030116 Proposed Tach Specs, Section 1 2 re definitions & 6 0 re administrative controls \* Consumers Power Co 84/07/30 10pp 25916 090 24X Fiche 50-155,84/07/30.8408030109
- 8408070040 Requests remittance of application fee for 840629 request for exemption from IOCFRSO 49 schedular requirement for environ qualification of electrical equipment Request filed after effective date of revised IOCFR170 DIGOS.R M License Fee Hanagement Branch 84/07/30 VANDEMALLE, D J Consumers Power Co ip 25955 351 24X Fiche 50-155.84/07/30,8408070040
- 8408070097 Forwards Generic Ltr 84-13, "Toch Specs for Snubbers," anitted from 840503 ltr to all SEP licensees NRC position that issue of Tech Specs for snubbers will be recolved on generic basis restated CRUTCHFIELD,D Assistant Director for Safety Assessment 84/07/31 KAY,J A Yankee Atomic Electric Co FARRAR,D L. Commonwealth Edison Co VANDEWALLE,D J Consumers Power Co 4pp 28935 227 24X Fiche 50-000,84/07/31,8408070099
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl EISENHUT.D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000.84/08/06,8408070110
- 8408080224 Forwards Whiting Corp 840727 rept re analysis of structural adequacy of jib crane to withstand seignic event Rept referenced in 840730 response to ASLB request for clarification re jib crane/gentry crane relationship COPELAND.V 0 Isham, Lincoln & Beale COPFLAND.V 0 Consumers Power Co DSB 823 84/08/06 BLBCH,P B , PARIS.Q H , SHON.F J Atomic Safety and Licensing Board Panel 16pp 25767 034 24X Fiche 50-155,84/08/06,8408080224
- 8498090164 Forwards application for amend to License DPR-6, revising Tech Specs re plant review committee review & approval of documents by document routing Fee encl VANDEWALLE, D. J. Consumers Power Co. 84/08/06 CRUTCHFIELD, D. Operating Reactors Branch 5 ip 25971 034 24X Fiche 50-155,84/08/06.8408090166
- --8408090171 Application for amend to License DPR-6, revising Tech Specs re plant review committee review & approval of documents by document reuting VANDEWALLE,D J. Consumers Power Co. 84/08/06. 4pp. 25971 035 24% Fiche 50-155.84/08/06.8408090166
- --8408090327 Proposed Tech Bpec changes re plant review committee review & approval of documents by document routing \* Cansumers Power Co 84/08/06 2pp 25971 039 24X Fiche 50-155, 84/08/06, 8408090166
- 840B090307 Forwards rept of electrical equipment environ qualification audit on 840605-07 Files inadequate to demonstrate qualification Reaudit planned for late Summer 1984 PAULSON. W. A. Operating Reactors Branch 5 84/08/08 VANDEHALLE, D. J. Consumers Power Co. 4pp. 25972 127 24X Fiche 50-135,84/08/08.8408090307
- B40B160172 Board Notification 84-141 forwards rept of electrical equipment environ qualification audit on B40605-07, for consideration in current litigation re spent fuel peol storage expansion.

  CRUTCHFIECD, D. Assistant Director for Safety Assessment 84/08/07 BLOCH, P. B., PARIS, O. H., SHON, F. J. Atomic Safety and Licensing Board Panel 3pp 26126 253 24% Fiche 50-155.84/08/07.8408160172

- B40B1601B1 Forwards remittance for extension request re 10CFR50 49 schedular requirements for environ qualification of electrical equipmentiper NRC 840730 request KUEMIN.J.L. Consumers Power Co. 84/08/09 MILLER.W.O. License Fee Management Branch 1p. 26091 242 24% Fiche 50~155.84/08/09. 840B1601B1
- 8408160343 Notification of 840824 meeting w/util in Charlevalx.MI to discuss radiological effluent Tech Specs EMCH.R L. Operating Reactors Branch 5 84/08/14 PAULSON.W A Operating Reactors Branch 5 4pp 26092 129 24X Fiche 50-155,84/08/14,8408160343
- B40B160346 Notification of B40905 meeting w/util in Bethesda.MD to discuss environ qualification of electrical equipment EMCH.R L Operating Reactors Branch 5 B4708714 PAULSDN,W A Operating Reactors Branch 5 4pp 26092 185 24X Fiche 50-155,84708/14,8408160346
- 8408170022 Informs that 840523 9A program submittal requires identification of each change, reason for change & basis for concluding that revised program incorporating each change satisfies 10CFR50, App 8 & SAR 9A program commitments SPESSARD, R L. Region 3, Office of Director 84/08/14 DEWITT, R 2 Consumers Power Co 2pp 26119 077 24X Fiche 50-000, 84/08/14, 8408170022
- B40B2102B7 Forwards listings of issues completed between 840202 & end of 1984 refueling outage, issues scheduled to be completed, but dolayed between 840202 & end of 1984 refueling outage & remaining active issues

  KRICH,R N Consumers Power Co 84/08/14 CRUTCHFIELD,D Operating Reactors Branch 5 14pp 26180 201 24X Fiche 50-155,64/08/14,80029102B7
- 8408210338 Informs that no add1 post-accident sampling sys required to meet guidance of NUREO-0737. Item II B 3 item complete
  High-range containment radiation monitors acceptable method of providing indication of core damage
  PAULEON.W A Operating Reactors Branch 5 84/08/17
  VANDEMALLE, D J Consumers Power Co 3pp 26179 358 24X
  Fiche 50-155.84/08/17.8408210338
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for CLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Bvc list encl EISCNHUT,D 0 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fichs 50-000.84/08/20.8408200275
- 8408290001 Advises that Multi-Plant Action B-59 re masonry wall design complete Plant structures will be selsmically evaluated for weak links, per NUREO-OBER PAULBON.WA Operating Reactors Branch 5 84/08/27 VANDEWALLE.D U Consumers Power Co Spp 26291 289 24X Fiche 50-135,84/08/27,8408290001
- G Inspection reports, IE Bulletins & correspondence
- B40B030176 Forwards IE Insp Rept 50-155/84-05 on B40421-0615 No noncompliance noted BHAFER.W D Region 3, Office of Director 84/07/13 DEWITT.R D Consumers Power Co 2pp 25917 302 24X Fiche 50-155, 84/07/13, 840B030174
- --8408030179 IE Insp Rept 50-155/84-05 on 840421-0615 No noncompliance noted Major areas inspected licenses actions on previous insp findings, operational safety & surveillance DEFAYETTE.R W . TAMBLING.T N . OUTHRIE.8 Region 3. OFFice of Director 84/07/12 App 25917 304 24X Fichy 50-155,84/07/13,8408030176
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 23865 047 24X Fiche,50~000,84/07/27, 8407280229
- 8408060110 Ack receipt of 840627 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-155/84-04 Clarification of callbr practices on portable high-range gamma measuring instruments awaited PAPERIELLO, C. J. Region 3. Office of Director 84/07/31 DECHITIR B Consumers Power Co. 1p 25933 176 24X Fiche 50-155,84/07/31.8408060110

- --B408060113 Responds to NRC 840529 ltr re violations noted in IE Insp Rept 50-155/84-04 Corrective actions Xetex fission pole & Eberline telector sent to vendors for calibr on all scales & will be calibr on all scales every 6 months KRICH:R H Consumers Power Co 84/06/27 KEPPLER.J Q Region 3: Office of Director 2pp 25933 177 24X Fiche 50-135,84/07/31. 8408060110
- 8408200233 Forwards IE Insp Rept 50-155/84-08 on 840709-12 No violations noted PAPERIELLO,C J Region 3, Office of Director 84/08/02 DENITTIR B Consumers Power Co 2pp 26140 155 24X Fiche 50-155,84/08/02,8408200233
- --8408200241 IE Insp Rept 50-153/84-08 on 840709-12 No violations noted Major areas inspected operational radiation protection program including planning & preparation changes, training & qualifications of new personnel & exposure control LOVENDALE,P C . FRANCE, G M . GREGER, L R . Region 3, Office of Director 84/08/01 7pp 26140 157 24x Fiche 50-155.84/08/02, 8408200233
- 8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during inspiratituted, effective 840820 Preprinted form will be used rather than itr
  KEPPLER.J 0 Region 3. Office of Director 84/08/03
  Commonwealth Edison Co. 3pp 25942 188 24X Fiche 50-000.84/08/03.8408070401
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 800103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26048 001 24X Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000.84/08/06.8408010337
- 8408070180 IE info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 188 24X Fiche 50-000,84/08/08,8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl QRACE.J N Division of OA, Safeguards & Inspection Programs (Post B30103) B4/08/10 Consolidated Edison Co of New York. Inc 125pp 26:30 001 24X Fichs 30-000.64/08/10,8408070376
- 8408140130 Ack receipt of B31216 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50~155/82-13 LITTLE:W S Region 3: Office of Director 84/08/10 DEWITT, R B Consumers Power Co ip 26047 011 24X Fiche 50~155,84/08/10. B408140130
- 108100009 1E Info Natice 84-63, "Defective RHR Replacement Piping "
  Svc list enc!
  JORDAN.E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 117pp 26197 218 24X Fiche 50-000.84/08/13,8408100009
- 8408100038 IE Info Notice 84-64, "BHR HPCI Initiation Seal-In & Indication "Svc list encl JURDANA E. Division of Emergency Praparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000.84/08/15.8408100038
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Bvc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc. 118pp 26198 001 24% Fiche 30-000.84/08/16.8408100021
- 8408100055 IE Info Notice 84~66, "Undetected Unavailability of Turbine-Driven Auxiliary Fordwater Train " Svc list encl URDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 24274 001 24% Fiche 50~000,84/08/17,8408100055
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl. JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 122pp 26276 122 24X Fiche 50-000,84/09/17,8408140208

- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc. 115pp 26329 008 24X Fiche 50-000.84/08/21.8408210142
- 8408270390 Ack receipt of 840727 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-155/84-03
  PAPERIELLO.C J. Region 3. Office of Director 84/08/22
  DEWITTR B. Consumers Power Co. 2pp 26240 197 24X
  Fiche 50-155.84/08/22.8408270390
- --8408270392 Responds to NRC 840627 ltr re violations noted in Insp Rept 50-155/84-03 Corrective actions site emergency plan implementing procedure reporting lime requirements revised, following 840222 incident VANDEWALLE.D J Consumers Power Co 84/07/27 KEPPLER, J G Region 3, Office of Director 3pp 26240 199 24X Fiche 50-155.84/08/22,8408270390
- S Reportable occurrences, LERs & related correspondence
- 840824034B Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated SHERNOOD, 0 G Ceneral Electric Co 84/04/13 DEYCUNG.R C Director's Office, Office of Inspection and Enforcement 3pp 24222 256 24% Fiche 50-000.84/04/13.8408240348
- B408230239 LER 84-003-01 on 840530, samples taken of water in belowgrade wall of radwaste pump room indicated presence of tritium & I-131 Caused by leak in underground pipe Pipe replaced & discharge canal monitored daily W/840816 ltr DEMOGRO E , KEMMIN J L. Consumers Power Co 84/08/16 5pp 24213 298 24X Fiche 50-155,84/08/16,8408230239
- B40B300086 LER 83-007//01T-i on B30B09.MBIV MD-7050 failed to stroke closed Caused by bent tripper arm on torque switch & probable ancreased switch sensitivity due to interference w/gear case hardened lubricant W/B40B16 ltr
  KUEMIN.J L Consumers Power Co 84/08/16 KEPPLER, J G Region 3. Defice of Director 3pp 26307 198 24X Fiche 50-155.84/08/16. BADGEROORS
- 8408290067 LER 84-010-00 on 840727.w/control rods inserted for turbine bupass valve investigation, reactor protection sys Channel 5 period monitor spuriously tripped, indicating short reactor period, due to electrical noise interference W/840822 ltr CASTIGLIONE.L. KUEMIN.J L Consumers Power Co 84/08/22 3pp 26297 322 24X Fiche 50-155.84/08/22.8408290067
- B40B290251 LER B4-009-00 on 840726, w/plant at 13% power, reactor scram from high pressure occurred Caused by turbine bypass valve failing closed in autonatic mode Turbine bypass valve operational characteristics to be examined W/840822 ltr CASTIOLIGNE, L. KUEMIN. J. Consumers Power Co B4/0B/22 4pp 22494 338 24K Fichs 50-155.84/0B/22,8408290251
- V Operator Examinations
- B40B200233 Forwards IE Insp Rept 50-155/84-0B on 840709-12 No violations noted PAPERIELLO,C J Region 3, Office of Director 84/08/02 DEMITT,R B Consumers Power Co 2pp 26140 155 24X Fiche 50-155/84/08/02/8408200233
- --8408200241 lE Insp Rept 50-155/84-08 on 840709-12 No violations noted Major areas inspected operational radiation protection gropram.including planning & preparation.changes, training & qualifications of new personnel & exposure control LOVENDALE.P C . FRANCE.G M . GREGER.L R Region 3. Office of Director 84/08/01 7pp 26140 137 24X Fiche 50-155.84/08/02, 8408200233
- B40Bi40426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners WALKER,R D Region 3. Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50~000, 84/08/10,8408140426
- DOCKET 50-156 UNIV OF WISCONSIN RESEARCH REACTOR

  F Security, medical, emergency & fire protection plans
- B4QB010045 Forwards "Emergency Plan Evaluation Rept.Univ of Wisconsin" Plan acceptable Plan should be implemented within 120 days of itr date THDMAS.C O Btandardization & Special Projects Branch B4/07/25 GASHMELL.R J Wisconsin. Univ of Madison, WI 3pp 25866 335 24% Fiche 50-156.84/07/25,8408010045

- --8408010047 "Emergency Plan Evaluation Rept,Univ of Wisconsin" \* NRC - No Detailed Affiliation Given 84/07/31 3pp 25866 338 24X Fiche 50-156.84/07/25.8408010045
- 8408140521 Advises that recently approved emergency plan will be fully implemented by 840831 CASHWELL, R J Wisconsin, Univ of Madison, WI 84/08/06 THOMAS, C O Standardization & Special Projects Branch ip 26064 162 24X Fiche 50-156,84/08/06,8408140521

#### V Operator Examinations

B40Bi40426 Provides address for transmitting all operator licensing correspondence to Region III off. except info for examiners MALKER, R D Region 3. Office of Director B4/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051

DOCKET 50-157 CORNELL UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

- 8408210097 Forwards "Emergency Plan Evaluation Rept,Cornell Univ " Plan meets requirements of regulations & guidelines & 1s acceptable THOMAS.C O Standardization & Special Projects Branch 84/08/15 CLARK.D D Cornell Univ , Ithaca, NY 3pp 26195 213 24X Fiche 50-097.84/08/15.8408210097
- --B40B140349 "Emergency Plan Evaluation Rept.Cornell Univ"

  \* Division of Emergency Preparedness & Engineering Response (Post B30103) 84/07/31 4pp 26195 216 24X Fiche 50-097, B4/08/15, B40B210097

DOCKET 50-160 GEORGIA INST OF TECH RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

- B408280195 "Emergency Preparedness Plan for Neely Nuclear Research Ctr, Georgia Inst of Technology " W/one oversize brochure Aperture card available in PDR W/B40821 Itr KARAM.R A Georgia Institute of Technology, Atlanta, QA 84/08/31 THOMAS.C O Standardization & Special Projects Branch 35pp 26275 001 24% Fiche 50-160,84/08/31,8408280199
- P Operating license stage documents & correspondence
- B40B010259 Requests application for amend executed per 10CFR50 30(a)-(c) & info showing all parts of Section 6 l of Tech Specs being fulfilled before action can be taken on 840324 request for dismantling facilities THOMAS, C O Standardization & Special Projects Branch 84/07/23 KARAM, R A Georgia Institute of Technology, Atlanta, GA 3pp 25B72 339 24X Fiche 50-160,84/07/23,8408010259

#### DOCKET 50-163 OA TECHNOLOGIES

- F Becurity, medical, emergency & fire protection plans
- 8408270311 Forwards ltrs documenting cooperation w/local lew enforcement agencies & medical facilities re radiological contingency plan MEWRY, W.R. OA Technologies, Inc./General Atomic Co. 84/08/22 CUNNINGHAM, R. Division of Fuel Cycle & Material Safety THOMAS, C.C. Standardization & Special Projects Branch 4pp 26241 004 24X Fiche 50-089,84/08/22,8408270311
- P Operating license stage documents & correspondence
- 8405160470 Forwards Amend 25 & 31 to Licenses R-38 & R-67, respectively & notice of issuance & availability Amends change corporate name of licensee to GA Technologies, Inc EISENHUT, D G Division of Licensing 84/04/27 MOWRY, W R GA Technologies, Inc /General Atomic Co 3pp 24492 253 24X Fiche 50-089, 84/04/27, 8405160470
- --B405160473 Amends 25 & 31 to Licenses R-38 & R-67, respectively, changing corporate name of licenses to GA Technologies, Inc EISENHUT, D.G. Division of Licensing B4/04/27 4pp 24492 256 24X Fiche 50-089, B4/04/27, B405160470

- 8408270277 Forwards Amend 33 to License R-67 & safety evaluation Amend authorizes increase in number of thermionic devices to be irradiated simultaneously from three to four & removes limit on total reactivity worth of combination of experiments THOMAS.C O Standardization & Special Projects Branch 84/08/17 MCNRY.W R GA Technologies, Inc /General Atomic Co 3pp 26312 331 24X Fiche 50-163.84/08/17.8408290277
- --B40B270286 Amend 33 to License R-67, increasing in number of thermionic devices to be irradiated simultaneously, removing limit on total reactivity worth of combination of experiments & changing fastening restrictions THOMAS, C O Standardization & Special Projects Branch 5pp 26312 334 24X Fiche 50-163, B4/08/17, 840B270277
- --8408290291 Safety evaluation supporting Amend 33 to License R-67

  \* Office of Nuclear Reactor Regulation, Director 84/08/17 4pp
  26312 339 24% Fiche 50-163.84/08/17.8408290277

DOCKET 50-166 UNIV OF MARYLAND RESEARCH REACTOR
P Operating license stage documents & correspondence

- 8408070124 Forwards FR notice of final finding of no significant environ impact re proposed renewal of License R-70 THOMAS.C O Standardization & Special Projects Branch 84/07/31 KERR.F Maryland, Univ of, College Park, MD 3pp 25757-201 24X Fiche 50-166,84/07/31,8408070124
- --8408070127 Notice of final finding of no significant environ impact re proposed renewal of License R-70 EIBENHUT, D © Division of Licensing 84/07/31 6pp 25757 204 24X Ficha 30-166.84/07/31.8408070124
- 8408140558 Forwards Amend 7 to License R-70, SER, EIA & notice of issuance & availability Amend renews license until June 29, 2000
  EIGENHUT, D Ø Division of Licensing 84/08/07 KERR, F Maryland, Univ of, College Park, MD Jpp 26065 236 24X
  Fiche 50-166, 84/08/07, 8408140558
- --8408140561 Amend 7 to License R-70, renewing license until June 29,2000. Tach Specs encl EISENUT,D G Division of Licensing 84/08/07 34pp 26065 239 24X Fiche 50-166,84/08/07,8408140558
- --8408140569 Notice of renewal of License R-70 THOMAS.C O Standardization & Special Projects Branch 2pp 26065 274 24X Fiche 50-166,84/08/07,8408140558
- --8408140564 EIA supporting Amend 7 to License R-70 \* NRC - No Detailed Affiliation Given 84/08/07 7pt 26065 276 24X Fiche 50-166,84/08/07,8408140558
- 8408300079 Application for amend to License R-40, correcting typographical error on Tech Spec Page 12 WOCKENFUSS W A Maryland, Univ of College Park, MD 84/08/17 THOMAS C 0 Standardization & Special Projects Branch 1p. 26305 361 24X Fiche 50-166,84/08/17,8408300079
- --8408300083 Proposed Tech Spec correcting typographical peror on Page 12 \* Maryland, Univ of. College Park, MD 84/08/17 1p 26305 362 24X Fiche 50-166.84/08/17,8408300079
- 8408270462 Forwards errata to Amend 8 to License R-70, corracting editorial error in Tech Spec re min radiation monitoring channels
  THOMAS, C O Btandardization & Special Projects Branch 84/08/21
  KERR, F Maryland, Univ of, College Park, MD 3pp 26277 2RO 24X
  Fichs 50-166:84/08/21.8408270462
- ---B408270466 Errata to Amend 8 to License R-70, correcting additorial error in Tech Spec re min radiation monitoring channels
  THOMAS, C O Standardization & Special Projects Branch
  4pp 26277 223 24% Fichs 50-166, 84/08/21, 8408270462
- R Periodic operating reports & related correspondence
- B408220172 Annual operating rept, Jul 1983 June 1984 BELCHER, R L Maryland, Univ of, College Park, MD. 84/07/23 TEDESCO, R L Division of Licensing 4pp 26188 172 24X Fiche 50-166, 84/07/23, 8408220172

- DUCKET 50-170 NATIONAL NAVAL MEDICAL CENTER
- P Operating license stage documents & correspondence
- B408070035 Forwards FR notice of final finding of no significant environ impact re renewal of License R-84 projects Branch 84/07. ADCORN. B National Naval Medical Center Bethesda. MD 3pp 25954 131 24X Fiche 50-170.84/07/30.8408070035 84707730
- --B408070038 Notice of final finding of no significant environ impact re proposed amend to License R-B4.renewing DL until Yr 2000 EISENHUT.D g Division of Licensing B4/07/27 7pp 25956 134 24% Fiche 50-170,84/07/30.8408070035
- 8408090533 Forwards Amend 18 to License R-84, safety evaluation, notice of issuance & availability & Tech Specs Amend renews license for 20 yrs
  EISENHUT.D G Division of Licensing 84/08/01 ADCOCK.B Armad Forces Radiobiological Research Institute 4pp 25983 277 24X
  Fiche 50-170,84/08/01.8408093533
- --8408070534 Amend 18 to License R-B4, renewing license EISENHUT,D 0 Division of Licensing 84/08/01 3pp 24X Fiche 50-170,84/08/01,8408070533 25983 281
- --8408070536 Notice of issuance & availability of Amend 18 to License R-B4
  THOMAS, C O Standardization & Special Projects Branch
  200 25983 284 24x Fichs 50-170.84/08/01:9408090533 8470B701
- DOCKET 50-171 PEACH BOTIOM ATOMIC POWER STATION, UNIT 1 R Periodic operating reports & related correspondence
- 8408210546 Forwards "Environ Radiation Monitoring Program, 1983" & "Regional Radiological Environ Monitoring Program, 1983"
  WILLSEY, W B Philadelphia Electric Co 84/08/09 DEYGUNG, R C Director's Office. Office of Inspection and Enforcement 1p 26189 001 24X Fiche 30-171,84/08/09,8408210944
- --B408210549 "Environ Radiation Monitoring Program 1983 \* Chamical Waste Management, Inc. 41 83/12/31 26185 002 24X Fiche 50-171.84/08/09.8408210546
- --8408210555 "Regional Radiological Environ Monitoring Program,1983 " \* Teledyne Isotopes 19 83/12/31 129pp 26185 126 24X Fiche 50-171,84/08/09,8408210546
- DOCKET 50-192 PURDUE UNIV RESEARCH REACTOR
- V Operator Examinations
- B408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners WALVER,R D. Region 3. Office of Director B4/08/10 Michigan Univ of. Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000. 84/08/10.8408140426
- JCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR
- @ Inspection reports: IE Bulletins & correspondence
- 8408270477 Forwards Insp Rept 50-184/84-01 on 840711-12 No violations ROTER STARDSTECKI, R Division of Project & Resident Programs CARTER, R S Commerce. Dept of National Bureau of Stan. 26236 203 24% Fiche 50-184,84/08/06,8408270477 84/08/06 Standards
- --B408270486 Insp Rept 50-184/84-01 on 840711-12 No violations or deviations noted Major areas inspected organization.logs & records.reviews & audits.equipment condition.experiments.surveillance activities & engineering changes TRIMBLE.D C . ELSASSER.T C Region 1. Office of Director 84/08/01 App 26236 205 24X Fiche 50-184.84/08/06.840827047/

- DOCKET 50-185 PLUM BROOK REACTOR MOCK-UP P Operating license stage documents & correspondence
- 8408210629 Advises that Licenses TR-9 & R-93 should be reinstated to 109410629 Advisor that Licenses IR-3 & R-93 should be rein-prior possess-but-not-use status or revised dismantlement plans should be submitted.per 100FR50 82 or 100FR50 90, respectively plans should update mgt controls THOMAS.C O Standardization & Special Projects Branch i RICHLEY,E A National Aeronautics & Space Admin 3pp : 24% Fiche 50-030,84/06/26.8408210689 26197 357
- W Decommissioning Stage Documents & Correspondence
- 8408240107 Requests submittal of either request for reinstatement of possess-but-not-use license or revised dismantlement plan w/schedule commitments Dismantlement authorized in 1981 delayed by lack of funds
  THOMAS, C. O. Standardization & Special Projects Branch. 84/08/16 THOMAS. C O Standardization & Special Projects Branch RICHLEY, E A National Agronautics & Space Admin Spp. 24% Fiche 50-030,84/08/16,8408240107
- DOCKET 50-186 UNIV OF MISSOURI RESEARCH REACTOR V Operator Examinations
- B408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners WALMER.R D Region 3. Office of Director 84/08/10 Michigan, Univ of Ann Arbor, MI 2pp 26051 198 24% Fiche 50-000, 84/08/10,8408140426
- DOCKET 50-188 KANSAS STATE UNIV RESEARCH REACTOR F Security, medical, emergency & fire protection plans
- 8408200461 Forwards review & evaluation of emergency plan for Kansas State Univ submitted on 840620, per 10CFRSO 54(q) & (r) Emergency plan meets requirements of regulations & guidelines & is acceptable THOMAS.C O Standardization & Special Projects Branch 84/08/13 FAW.R E Kansas State Univ. Manhattan. KS 3pp 26144 316 24) Fiche 90-188.84/08/13.8408200461
- --8408200464 "Emergency Plan Evaluation Rept Kansas State Univ "
  \* NRC No Detailed Affiliation Given 84/07/31 3pp
  26144 319 24X Fiche 50-188,84/08/13,8408200461
- 84083i0117 Ack receipt of 840813 emergency plan evaluation rept Last paragraph on Page 2 of rept in error Operations boundary encompasses reactor facility Room 110 of Ward Hall.per Paragraph 1 i of emergency plan FAW.R E Kansas State Univ , Manhattan, KS 84/08/20 CHU.A Standardization & Special Projects Branch 1p 26322 112 24X Fiche 50-188,84/08/20,8408310117
- DOCKET 50-192 UNIV OF TEXAS RESEARCH REACTOR
- Security, medical, emergency & fire protection plans
- 8407110379 Forwards Safety evaluation re 830721 emergency plan Plan acceptable Full implementation should be completed within 120 days of itr date & FIRC informed of date implementation achieved W/o encl
  THUMAS.C O Standardization & Special Projects Branch 84/07/03
  KLEIN,D E Texas. Univ of, Austin, TX 2pp 25545 358 24X
  Fiche 50-192,84/07/03,8407110379
- DOCKET 90-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC S Reportable occurrences, LERs & related correspondence
- 8408210328 RD on 840810, telephone lines between Narragansett,RI & Providence,RI Pailed, preventing transmission of signals from burglar alarm & supervisory sys Cause unknown Line DIMEGLIO. A F Rhode Island & Providence Plantation Region 1. Office of Director ip 26179 331 24x Fiche 50-193.84/08/10.8408210328 84/08/10

DOCKET 50-199 MANHATTAN COLLEGE RESEARCH REACTOR I Financial information

8408170407 Forwards proprietary financial info required for renewal of License R-94 t "Environ Rept." per 640702 telcon Proprietary info & rept withheld (ref 100FR2 790)
KANE,R S Manhattan College, Riverdale, NY 64/08/13 THOMAS.C O Standardization & Special Projects Branch 1p 26129 117 24X
Fiche 50-199.84/08/13.8408170407

#### P Operating license stage documents & correspondence

840B170407 Forwards proprietary financial info required for renewal of License R-94 & "Environ Rept." per 840702 telcon Proprietary info & rept withheld (ref 100FR2 770) KANE.R S Manhattan Coilege, Riverdalo, NY 84/08/13 THOMAS.C D Standardization & Special Projects Branch 1p 26127 117 24X Fiche 50-199.84/08/13.8408170407

# V Operator Examinations

8408030301 Forwards evaluation of Rev 3 to operator requalification program Rev approved, per 10CFR55, App A THOMAS, C O Standardization & Special Projects Branch 84/07/26 KANE, R S Manhattan College, Riverdale, NY 5pp 25920 063 2: Fiche 50-199, 84/07/26 8408030301

DOCKET 50-206 SAN DNOFRE NUCLEAR STATION, UNIT 1

- F Security, medical, emergency & fire protection plans
- 8408030123 Forwards Rev 2 to physical security plan & description of changes Encls withhold (rof 10CFR73 21)
  HAYNES J G Southern California Edwan Co 84/07/25 MARTIN, J B Region 5, Office of Director 1p 25714 119 24x
  Fiche 50-206,84/07/25,8408030123
- 8408170130 Forwards Amends 78,23 & 12 to Licenses DPR-13,NPT-10 & NOBLIVISUS FORWARDS AMENDS 78,23 & 12 to Licenses DPR-13 NPF-15 respectively & safety evaluation Amends approve security plan revs which consolidate & reduce size of adjacent vital areas PAULBON, W A Operating Reactors Branch 5 84/08/07 Bouthern California Edison Co 5pp 26134 302 24X Fiche 50-206,84/08/07,8408170130 84/08/07 BASKIN, K
- --8408170143 Amends 78,23 & 12 to Licenses DPR-13,NPF-10 & NPF-15, menons of each of the country of the
- --8408170155 Safety evaluation supporting Amends 78,23 & 12 to Licenses DPR-13,NPF-10 & NPF-15, respectively # Office of Nuclear Reactor Regulation, Director 84/08/07 5pp 26134 313 24X Fiche 30-206,84/08/07,8408170130
- 8408130450 Advises that 840523 Revs 1-13 to physical security plan consistent w/provisions of 10CFRDO 54(p) & acceptable MCGNEEN.A D Region 5. Office of Director 84/08/08 Southern California Edison Co 4pp 26004 359 24X Fichs. 50-206.84/08/08.8408130450
- 8408310285 Forwards Bafeguards Insp Repts 50-206/84-18,50-361/84-23 & 50-362/84-23 on 840723-27 No violations noted Repts withheld (ref 10CFR2 790 & 73 21) SCHUSTER.M D Region 5. Office of Director 84/08/15 BASKIN,K B SCHUBTER.M D Region 5. Office of Director 84/08/1 Southern California Edison Co 2pp 26333 288 24X Fiche 50-206.84/08/15.8408310285
- 8408230114 Informs that 840613 rev to emergency plan compatible w/provisions of 10CFR50 47,App E & Rev 1 to NUREO-0654 SCHUSIER.M D Region 5. Diffice of Director 84/08/16 MEDFO Southern California Edison Co 3pp 26347 274 24X Fiche 50-206.084/08/16.8408230114 MEDFORD, M O

### P Operating license stage documents & correspondence

8408210042 Notification of contract execution, Mod 4, to "Followon Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station "Contractor MIT HOPPER: A Administrative Contracts Branch FIN 8-6878 84/06/12 VOLLMER: R Division of Engineering JACKBON, R NRC - Na Detailed Affiliation Given 1p 26175 176 24X Fiche 50-206, 84/06/12, 8408210042

- --8408210046 Mod 4. deobligating unliquidated fee remaining in contract, to "Followon Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station"

  AYI.K Massachusetts Institute of Technology, Cambridge, MA HAGAN, T P Division of Contracts FIN 8-6898 84/06/12 ip 24195 177 24X Fiche 9-206,884/06/12.8808210042
- 8408060408 Requests assistance in review of licensee 840717 Tech Spec revs on plant staff overtime limits (TMI Item I A i 3 i) Completed SER & SALP input due 840920 EISENHUT. D G Division of Licensing 84/07/25 DISHOP, T W Division of Resident Reactor Project & Engineering Programs 3pp 23951 154 24% Fiche 50-206.84/07/25,8408060408
- B408010038 Informs of review of 840629 ltr on operating experience, insp & analysis results re reliability of TDI V-20 diesols Lead engine testing, disassembly & insp not required before restart CRUTCHFIELD,D Assistant Director for Bafety Assessment 84 BABKIN,K P Bouthern California Edison Co 7pp 25855 333 Fiche 50~206.84/07/26.8408010038
- 8408010226 Forwards addl info re Proposed Changes 76 & 126 to Tech Specs in response to NRC 840309 request Calculation sheets and Withree oversize drawings Aperture cards available in PDR MEDPORD, M O Southern California Edison Co 84/07// CRUTCHFICLD, D Operating Reactors Branch B 132pp Fiche 50-206,84/07/27,8408010226 84/07/27 25054 1BO 24X
- 8408010272 Requests extension of environ qualification of electrical equipment to 851130.per 10CFR30 49(g) & forwards Nucon Increpts. "Plant Risk Impact Evaluation of Certain Electrical Equipment" & "Evaluation of Core Damage Risk " MEDFORD.M O Southern California Edison Co 84/07/30 CRUTCHFIELD. D Operating Reactors Branch 5 7pp 25854 089 243 Fiche 50-206.84/07/30.8408010272 25854 089 24X
- --8408010276 "Plant Risk Impact Evaluation of Certain Electrical Equipment" Equipment " LYDELL, B O , MORGAN, T A , HUGHES E A Nucon, Inc 84/ 52pp 25854 096 24X Fiche 50-206,84/07/30,8408010272
- --8408010287 "Evaluation of Core Damage Risk Reduction Associated W/ Selsmic Mods at San Dnofre Nuclear Generating Station.Unit I." executive summary GUEY. C N . LAMBERT. H E . HUGHES, E A Nucon, Inc 84/07/31 10pp 25854 158 24X Fiche 50-206.84/07/30,8408010272
- B40809020B Forwards draft nemo re boron injection test, which will be finalized after comments received Final memo will satisfy final milestone defined in 189. "Boron Mixing & Cooldown Under Accident Conditions"
  PRATT.N T Brookhaven National Laboratory FIN A-3368 84/07/30 LIANO, C Y Reactor Systems Branch 18pp 25971 193 24%
  Fiche 50-206.84/07/30.8408090208
- 8408070099 forwards Generic Ltr 84-13, "Tech Specs for Anubbers." omitted from 840503 ltr to all SEP licensess NRC position that issue of Tech Specs for snubbers will be resolved on generic basis restated
  CRUTCHFIELD.D Assistant Director for Safety Assessment, 84/07/31
  KAY.J A Yankee Atomic Electric Co 4pp 25955 227 24x
  Fiche 50-000.84/07/31.8408070099
- 8408030166 Forwards Rev 1 to "Offsite Dose Calculation Manual" & response to NRC 840418 comments
  MEDPORD.M O Batthern California Edison Co 84/08/01
  CRUTCHFIELD.D Operating Reactors Branch 5 7pp 25 25714:047 24X Fiche 50-206.84/08/01.8408030166
- --8408030169 Rev 1 to "Offsite Dose Calculation Manual," consisting of corrected pages, per NRC 840418 request to support review of radiological effluent Tech Specs 8 Southern California Edison Co B4/06/13 20pp 25914 054 B4/06/13 20pp 25914 054 24X Fiche 50-206,84/08/01,8408030166
- 8408070331 Informs that licansee 840709 proposal to resolve TMI Item II F I 4 acceptable Computer software will be modified so that data will be collected once per second & highest value over each minute will be recorded PANLSON.W A Operating Reactors Branch 5 84/08/03 BASKIN.K P Southern California Edison Co. 2pp 25745 235 24X Fiche 50-206.84/08/03.8408070331
- B408070110 Generic Ltr B4-19 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of Suppl I to NUREG-0733, "Prioritization of Generic Safety Issues" "Svc list encl
  EISCHHUT, D © Division of Licensing B4/08/06 Consolidated Edison Co of New York, Inc 18pp 26127 238 24X
  Fichs 50-000.84/08/06.8408070110

- 840B140188 Lists required confirmatory evaluations to be performed prior to startup to estimate inclastic capability of structural elements to retain function during DBE CRUYCHFIELD, D. Assistant Director for Safety Assessment 84/08/07 BASKIN.K P. Bouthern California Edison Co. 4pp. 26044 035 24X Fichs 50-206,84/08/07.8408140188
- --B40Bi40194 Submits review of EG&G consultant agreement, "Adequacy of Structural Beams for Safety-Related Piping, San Onofre.
  Unit i "More rationally based, sys-wide study of safety sys appropriate
  HALL, W J Dr W J Hall B4/05/21 CHENG, T Systematic Evaluation Program Branch BARNES, B L EG&G, Inc. 7pp 26044 039 24% Fiche 50-206,84/08/07,8408140188
- 8408170130 Forwards Amends 78,23 & 12 to Licenses DPR-13.NPF-10 & NPF-15.respectively & safety evaluation Amends approve security plan revs which consolidate & reduce size of adjacent vital areas PAULBON. & A Operating Reactors Branch 5 84/08/07 BASKIN, X Southern California Edison Co HOLCOMBE. J C San Diego Gas & Electric Co Spp 26134 302 24X Fiche 50-206.84/08/07.8408170130
- --8408170143 Amends 78.23 & 12 to Licenses DPR-13.NPF-10 & NPF-15, respectively, approving security plan revs which consolidate & reduce size of adjacent vital areas & move equipment not required for sefety gutside vital boundary PAULSON.H A Operating Reactors Branch 5 84/08/07 App 26134 307 24% Fiche 50-206.84/08/07.8408170130
- ~~8408170155 Safety evaluation supporting Amends 78,23 & 12 to Licenses DPR-13.NPF-10 & NPF-15, respectively 
  \*\* Office of Nuclear Reactor Regulation, Director 84/08/07 5pp 26134 313 24X Fiche 50-206.84/08/07.8408170130
- 8408160215 Forwards add1 info re current alternate post-accident sampling sys methods, completion schedules for procurement of components, const & operator training & justification for deferral to Cycle IX refueling outage MEDFORD, M O Southern California Edison Co 84/08/14 PAULSON, W A Operating Reactors Branch 5 17pp 26090 034 24X Fisha 50-206, 84/08/14, 8408160215
- 8408160359 Notification of 840823 meeting w/util in Bethesda, MD to discuss intate structure rebar corrosion MCKENNA: E Operating Reactors Branch 5 84/08/15 PAULSON, W A Operating Reactors Branch 5 3pp 26071 233 24X Fiche 50-206.84/08/15.8408160359
- 8408160375 Notification of 840905 & 06 meetings w/util & Franklin Research Ctr in Berkeley & San Diego.CA: respectively, to audit results for masonry wall seismic qualification & conduct sits visit MCKENNA.E Operating Reactors Branch 5 84/08/15 PAULSON, W A Operating Reactors Branch 5 3pp 26092 176 24X Fichs 50-206.84/08/15.8408160375
- 8408200114 Forwards SER rs vertical seismic ground motion for facility, per SEP Topic III-6 Original estimate for free-field ground motion described in 820916 itr appropriate for seismic resvaluation CRUTCHFIELD, D. Assistant Director for Safety Assessment 84/08/16 BASKIN, K.P. Southern California Edison Co. 9pp. 26132 309 24X Fiche 50-206,84/08/16,8408200114
- J408210165 Application for amend to License DPR-13, changing Tech Specs re max reactor coolant activity, leakage, safety injection says hydraulic valve testing, reactivity anomalies & miscellaneous radioactive maths sources.

  MEDFORD, M O Bouthern California Edison Co 84/08/16 PAULSON, W A Operating Reactors Branch 5 4pp 26103 067 24X

  Ficha 50-206.84/08/16.8408210165
- --8408210179 Proposed & sxisting Tech Specs re max reactor coolant activity, leakage, safety injection sys hydraulic valve testing, reactivity anomalies & miscellaneous radioactive matts sources

  \* Southern California Edison Co B4/08/16 29pp 26183 071 24x Fiche 50-206,84/08/16,8408210165
- 8408210625 Requests remittance of fee for 840730 request for extension of 1007850 49 schedular requirements for environ qualification of certain electrical equipment. Application subj to 840620 rev to 10078770 on fees DIGOS, RM License Fee Management Branch 84/08/16 RAY, H B Southern California Edison Co ip 26187-360 24X Fiche 50-296.84/08/16,8408210625

- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for DLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety quastions Svc list enc)
  EISENNUT,D 9 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X
  Fiche 50-000.84/08/20.8408200275
- B40B21037i Advises that concrete cracks & corrosion of underlying rebar found in uall of facility intake structure Licensee will make presentation on extent of problem & proposed corrective actions at B40B23 meeting PAULBON.W A Operating Reactors Branch 5 84/08/20 LEAR.O Btructural & Geotechnical Engineering Branch 1p 26180 355 24x Fiche 50-206.84/08/20.8408210371
- 8408230178 Forwards info to resolve SEP Topics IV-2, "Reactivity Control Sys" & VII-1 A, "Isolation of Reactor Protection Sys From Nonsefety Sys " Six oversize drawings encl Aporture cards available in PDR MEDFORD.M O Southern California Edison Co 84/08/21 PAULSON.W A Operating Reactors Branch 5 26207 188 24x Fiche 50-206.84/08/21.8408230178
- 8408240168 Submits results of analyses re temp profile for 4,160-voit & 480-voit rooms to confirm post-accident cooling of room not necessary to assure operability of electrical components Info resolves SEP Tapic IX-5 MEDFORD, M O Southern California Edison Co 84/08/21 PAULSON, W & Operating Reactors Branch 5 3pp 26228 175 24X Fiche 50-206,84/08/21.8408240168
- B408270325 Advises that Amend 7 to Topical Rept SCE-1-A. "GA Program," consistent w/provisions of 10CFR50 S4(a) & acceptable BISHOP. T W Division of Resident Reactor Project & Engineering Programs 84/08/21 BASKIN. K P Southern California Edison Co 1p 26244 107 24X Fiche 50-206.84/08/21,8408270325
- 8408280173 Summary of 840823 meeting w/otil & Bechtel in Bethesda, MD re degradation of intake structure reinfercing steel (rebar) Meeting attendess list & handouts encl MCKENNA, E M Operating Reactors Branch 5 84/08/27 Operating Reactors Branch 5 39pp 26259 016 24% Fiche 50-206, 84/08/27, 8408280173
- 8408270136 Forwards final SER re SEP Topics II 3-A re hydrologic description. II-3 B re flooding potential & protection. II-3 B re coping w/design basis flood conditions & II-3 C re UHB PAULSION. M A Operating Reactors Branch 5 84/08/27 BASKIN, K P Southern California Edison Co Opp 26271 274 24X Fiche 50-206.84/08/27.8408270136
- G Inspection reports. IE Bulletins & correspondence
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Byo list encl JCRDAN, E. L. Division of Emergency Preparedness & Engineering Respense (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc. 117pp 25865-047 24X Fiche 50-000.84/07/27, 8407250229
- 8408070411 Responds to IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Sys " Thirty-one relays found at Unit 1 will be replaced by 860312 MEDFORD.M O Bouthern California Edison Co 84/07/30 MARTIN.J B Region 3, Office of Director 3pg 25942 170 24X Fiche 50-204.84/07/30.8408070411
- 8408130203 Responds to NRC 840706 ltr re violations noted in IE Insp. Rept 30~206/84-10 Corrective actions GA program implemented for enhanced contractor GA Field surveillances to ensure work in conformance w/drawings & procedures

  BABKIN, K.P. Bouthern California Edison Co. 84/07/30 MARTIN, J.B. Region & Defice of Director. 12pp. 26008 297 24X

  Fiche 50-206,84/07/30,8408130203
- 8408310243 Forwards Exam Rept 50-206/OL-84-01 administered on BA0710-13, written exam & answer key PATE/R J Region 5. Office of Director 84/08/03 BASKIN, K P Southern Callfornia Edison Co 1p 26334 001 24X Fiche 50-206, 84/08/03. 8408310243
- --8408310244 Exam Rept 50-206/OL-84-01 administered on 840710-13 Exam results all candidates passed ELIN.J O. MILLER.L F Region 5. Office of Director 84/07/31 109pp 26334 002 24X Fiche 50-206.84/08/03,8408310243
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Byo list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/04 Consolidated Edison Co. of New York, Inc. 85pp. 24048 001 24% Fiche 50-000,84/08/04,8408010333

- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000.84/08/06,8408010337
- 8408070120 IE Info Natice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830109) 84/08/08 Consolidated Edison Co. of New York, Inc. 120pp 26129 118 24X Fiche 50-000.84/08/08.8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Pattents Undergoing Co-60 Teletherapy Treatments " Bvc list encl ORACE,J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000.84/08/10.8408070376
- 940B100009 IE Info Notice 84-63. "Defective RHR Replacement Piping "
  Svc list enc!
  JORDAN.E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000.84/08/13.8408100009
- B40B10003B lE Info Notice 84-64, "DWR HPCI Initiation Seal-In & Indication "Bvc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,840810003B
- 8408310285 Forwards Safeguards Insp. Repts 50-206/84-18,50-361/84-23 & 50-362/84-23 on 840723-27 No violations noted Repts withheld (ref 100FR2 790 & 73 21)
  SCHUSTER, H D. Region 5, Office of Director 84/08/15 BASKIN, K B Southern California Edison Co. 2pp. 26333 288 24X
  Ficha 50-206,84/08/15,8408310285
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Advarsely Affect Operation of Essential Electrical Equipment " Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26178 001 24% Fiche 50-000.84/08/16,8408100021
- 8408100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Foedwater Train " Syc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc. 120pp 26276 001 24X Fiche 50-000,84/08/17.8408100055
- 89408140208 IE Info Notice 84-67. "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000.84/08/17.8408140208
- E9408280109 Forwards nutline of actions required to insure reliability of TDI V-20 diesel engines prior to restart in response to 840829 summary of operating experience.insp results to analysis results

  BERLINGER.C H Division of Licensing 84/08/20 GRIMES.C I Systematic Evaluation Program Branch 11pp 26294 141 24X Fiche 50-206,84/08/20.8408280109
- 83408210142 IE Info Natice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Bolenaid Valves " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329:008 24X Fiche 50-000.84/08/21.8408210142
- ₹408270349 Ack receipt of 840730 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-206/84-10
  BISHOP, T W Region 5. Office of Director 84/08/21 BASKIN, K P
  Southern California Edison Co ip 26244 357 24X
  Fiche 50-206,84/08/21.8408270349
- 🖴. Reportable occurrences, LERs & related correspondence
- © 405270062 Forwards "Investigation of Types AF & AE Piston Skirts "
  Rept supercedes 840227 submittal
  RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group RAY.C L
  Duke Power Co 84/05/24 DENTON,H R Office of Nuclear Reactor
  Regulation, Director 2pp 24670 045 24X Fiche 50-000,84/05/24,8405270062

- --8405290075 "Investigation of Types AF & AE Piston Skirts "
  \* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp
  24X Fiche 50-000,84/05/24.8405290062
- 8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations " RAY, C L TDI (Transamerica Delaval, Inc.) Owners Group RAY, C L Duke Power Co 84/05/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 24692 090 24X Fiche 50-000, 84/05/24, 8405290179
- --8405290271 "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations " \* Failure Analysis Associates FAAA-84-3-16 84/05/22 89pp 24672 092 24X Fiche 50-000.84/05/24.8405290179
- 8408040403 Forwards repts received by BNHL & consultants directly from FAAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts.Analysis & Recommendations re Hain Propulsion Engines M/V Columbia" encl
  ALZHEINER.J M Battelle Memorial Institute, Pacific Northwest
  Laboratories B4/06/28 MILLER.M Division of Licensing 158pp 25926 173 24X Fiche 30-000.84/06/28.8408060405
- 8408060050 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Generator Owners Group 840622 meeting
  RAY.C.L. TDI (Transamerica Delaval: Inc.) Dwners Group RAY.C.L.
  Duke Power Co. 84/07/10 BERLINGER.C. Director's Office. Office of
  Inspection and Enforcement 43pp 25933 133 24X
  Fithe 50-000.84/07/10.8408060050
- B408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Gualification Review " Addition copies sent to BNML RAY, C t. TDI (Transamerica Delaval, Inc.) Duners Group RAY, C t. Duke Power Co. B4/07/27 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp. 25932 137 24X Fichs 50-000, 84/07/27, 8408060102
- --8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review"

  \* Stone & Webster Engineering Corp. 84/07/31 34pp 25932 139 24X Fiche 50-000,84/07/27,8408060102
- B40B060324 Forwards "Design Review of Elliott Model 650 Turbecharger Used on TDI DBRV-12-4 & DBRV-20-4 Emergency Diesel Generator Bets "
  RAY.C L TDI (Transamerica Delayal, Inc.) Dwners Group RAY.C L
  Duke Power Co B4/0B/01 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 25927 064 24X Fiche 50-000.B4/0B/01.840B040324
- --8408060387 "Design Review of Elliott Model 659 Turbacharger Used an TDI DBRV-12-4 & DBRV-20-4 Emergency Diesel Generator Sets " \* Failure Analysis Associates FAAA-84-6-56 84/07/31 62pp 25927 066 24X Fiche 30-000,84/08/01,8408060324
- 840Bi40216 Special rept on B31217 fire detection sys back in syc but for Zones B & 16 Engineering evaluations complete Mods to Zones B & 16 will be finished & zones back in syc by 841015 HAYNESIJO Southern California Edison Co 84/08/01 MARTIN, J B Region 5. Dffice of Director 2pp 26053 361 24X Fiche 50-206,84/08/0108140216
- 8408070379 LER 84-007-00 on 840703, temporary change notice for Procedure 802-3-3 31, "Inservice Valve Testing Cold Bhutdown," not approved within 14 days, contrary to Tech Specs Caused by administrative error W/840803 ltr HAYNEB, J 9 Southern California Edison Co 84/08/03 2pp 25947 156 24X Fiche 50-204,84/08/03,8408070379
- 8408160374 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
  RAY.C L TDI (Transamerica Delaval, Inc.) Dwners Group RAY.C L Duke Fower Co. 84/08/10 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 26071 147 24% Fiche 50-000, 84/08/10, 8408160394
- --8408160403 "Design Review of Engine Dase & Bearing Caps for TDI DBRV-16 Diesel Engines." \* Failure Analysis Associates FAAA-84-6-83 84/08/31. 44pp 26071 149 24X Fiche. 50-000,84/08/10,8408160394
- 8408240115 Forwards SER re TDI Guners Group program plan BER addresses design review/quality revalidation program, testing & insp. maint & surveillance & sets forth requirements for operation prior to completion of program plan EIBENHUT.D G. Division of Licensing 84/08/13 GEORGE, J B TDI (Transamprica Delaval, Inc.) Owners Group GEORGE, J B Texas Utilities Electric Co (formerly Texas Utilities Generating Co) ip 26253 194 24% Fiche 30-000,84/08/13,8408240115

- --9409240:57 Safety evaluation of TDI Coners Group program plan Based on BNNL evaluation, plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI
  - engines for nuclear syc \* NRC No Detailed Affiliation Given 84/08/13 21pp 2625 195 24X Fiche 50-000.84/08/13,8408240115
- 8408160395 Forwards "Design Review of Elliott Model 906 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets: "representing final GA verified rept Addl copy forwarded to BMML.per NRC request RAY.C L TDI (Transamerica Delaval, Inc.) Dwners Group RAY.C L Duke Power Co. 84/08/14 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 24088-163 24X Fiche 50-000.84/08/14. Regulation, Director 8408160395
- --8408160397 "Design Review of Elliott Model 900 Turbocharget Used on TDI DSR-48 & DSRV-16 Energency Diesel Generator Sets "
  \* Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp
  26088 165 24/ Ficho 50-000.84/08/14.8408160395
- B408290179 Forwards response to B40723 request for add1 info on repts NUMERVOLTY FORWARDS PESPONSE to B40723 request for add1 info on repts submitted by TDI Diosel Generator Gwmers Group RAY, C L TDI (Transamerica Delaval, Inc.) Gwmers Group RAY, C L Duke Power Co. B4708/23 BERLINGER. C. Office of Nuclear Reactor Regulation. Director 12pp 26289-221 247 Fiche 30-000.84/08/23.8408290179
- 8408300232 Forwards description of program to implement TDI diesel insprequirements for restart & methods used to determine ESF loads, per 840726 request Program covers insps. tests & maint & surveillance activities
  MEDFORD, MO Southern California Edison Co 84/08/28 PAULSON, WA Operating Reactors Branch 5 12pp 26300 111 24x
  Fiche 50-206,84/08/28,8408300202
- T Hearing transcripts on non-antitrust matters
- 8404220299 Board Notification 84-120 forwards transcripts of 840426.
  0502 & 24 meetings w/TDI Owners Group re status of program
  to establish diesel generator reliability
  EISENHUT, D G Division of Licensing 84/06/20 PALLADING,
  GILINSKY, ROBERTS Commissioners 54pp 25204 099 24X
  Fichs 50-000,84/06/20,8406220259

### V Operator Examinations

- 8408310243 Forwards Exam Rept 50-206/OL-84-01 administered on B40710-13, unitten exam & answer key PATE.R J Region 5. Office of Director 84/08/03 DASKIN.K P Southern California Edison Co lp 26334 001 24x Fiche 50-206.84/08/03.8408310243
- --B408310244 Exam Rept 50-206/GL-B4-01 administered on 840710-13 Exam Tesults all candidates passed
  ELINJO, MILLERIL F Region 5, Office of Director 8, 109pp 26334 002 24X Fiche 30-204, 84/08/03, 8408310243

# DOCKET 50-213 HADDAM NECK PLANT

- Security, medical, emergency & fire protection plans
- 3408070180 Responds to NRC 840419 ltr re violations noted in IE Insp Rept 50-213/84-03 Corrective actions cavity water level indication will be permanently installed COUNSIL.W G Connecticut Yankee Atomic Power Co 84/05/17 STAROSTECKI.R Division of Project & Resident Programs 3pp 25992 072 24X Fiche 50-213.84/03/17.8408090180
- 8408090133 Forwards IE Insp Rept 50-213/84-07 on 840401-0605 No violations observed STAROSTECKI, R Division of Project 3 Resident Programs 84/07/20 COUNSIL, W 9 Connecticut Yankee Atomic Power Co 2pp 25974 305 24X Fiche 50-213,84/07/20,8408090133
- --8408090141 IE Insp Rept 50-213/84-07 on 840401-0605 No violations voovol41 it Insp Rept 50-213/84-07 on 840401-0605 No violat observed Major areas inspected turbine bldg.physical security.primary auxiliary bldg.auxiliary feed pump room & radiation protection Info deleted (ref 10CFR2 790) SWETLAND.P D Region 1, Office of Director ELSASSER.T C Division of Project & Resident Programs B4/06/22 13pp 25994 307 24X Fichs 50-213.84/07/20,8406090133
- B408150251 Forwards IE Insp Rept 50-213/84-12 on 840605-0715 No violations noted

  STAROSTECKI,R Division of Project & Resident Pr
  COUNSIL,W G Connecticut Yankee Atomic Power Co
  24X Fiche 50-213,84/07/25,8408150251 d Division of Project & Resident Programs - 84/07/25 Onnecticut Yankee Atomic Power Co - 2pp - 26077-002

- --8408150255 IE Insp Rept 50-213/84-12 on 840605-0719 No Violations 408150255 IE Insp Rept 50-213/84-12 on 840605-0/15 No violations noted Major areas inspected control room, turbine bldg, primary auxiliary bldg, auxiliary feed pump room, radiation protection, physical security & plant procedures SWETLAND, P D, ELSASSER, T C Region 1, Defice of Director 84/07/24 12pp 26077 004 24/ Fiche 50-213 84/07/25,8408150251
- 8408140328 Revised Emergency Plan Implementing Procedures EPIP 1 5-2, "Notification & Communication," EPIP 1 5-10, "Offsite Emergency Radiological Surveys' & EPIP 1 5-45, "Emergency Communications Bys Testing ' W/840813 ltr CDUNSIL N G Connecticut Yankee Atomic Power Co 84/08/13 83pp 26088 314 24X Fiche 50-213,84/08/13,8408160328
- 840B160350 Forwards revised emergency plan implementation procedures, including CONI i O2 re corporate organization for nuclear incidents & CONI i O2 re on-call manager or radiological consequences assessment W/a encls COUNSIL.0 G Northeast Utilities 84/08/13 Record Services Branch (Document Control Desk) 2ppl 26091 193 24X Fiche 50-000.84/08/13,8408160350
- 840B280171 Responds to 840719 interpretation of order confirming licensee commitments on emergency capability, focusing on Suppl 1 to NUREO-0737 requirements Integrated assessment to be conducted pending Congressional consent EISENHUT, D G Division of Licensing 84/08/23 COUNSIL, W G Connecticut Yankee Atomic Power Co 3pp 26277 224 24X Fiche 50-000,84/08/23,8408980171
- 8408310187 Submits update to corrective actions taken re deficiencies 408310187 Submits update to corrective actions taken re deficiencies noted during B40512 emergency preparudness exercise
  Emergency action level procedure revised to place greater emphasis on classification/reclassification of emergencies
  COUNSIL.W G Connecticut Yankee Atomic Power Co COUNSIL.W G Northeast Nuclear Emergy Co (subs of Northeast Utilities)
  COUNSIL.W G Northeast Utilities B4/08/23 MURLEY, T E Region 1, Dffice of Director 3pp 26318 330 24X Fiche 50-000, 84/08/23, B460810187 B408310187

#### H Ceneral correspondence

- 8408070321 Advises that K McCarthy should appear on license amends as appropriate state official to receive amend applications McCarthy new director of radiation control for State of CT. Dept of Environ Protection
  COUNSIL.W G Connecticut Yankee Atomic Power Co CDUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities)
  CDUNSIL.W G Northeast Utilities 84/07/27 MILLER, J R Operating Reactors Branch 3 CRUTCHFIELD.D Operating Reactors Branch 5 1p 25945 128 24% Fiche 50-000.84/07/27,8408070321
- P Operating license stage documents & correspondence
- 8408070194 Ack receipt of 840407 application re revised inservice insp & testing program Remittance of Class III fee requested since review involves single safety issue DIGGS.R M Office of Administration 84/07/30 COUNSIL.W G Connecticut Yankee Attant Power Co ip 25957 118 24X Fiche 50-213.84/07/30.8408070154
- 840B100063 Forwards Vols I & II of "NUSCo Thermal Hydraulic Model Qualification." for RETRAN & VIPRE COUNSIL.W G Connecticut Vankee Atomic Power Co COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities 84/07/30 MILLER.J R Open Reactors Branch 3 CRUTCHFIELD.D Opensting Reactors Branch 5 2pp 25987 072 24X Fiche 50-213.84/07/30.8408100063 Operating
- -940BlG0070 Vol I of "NUSCo Thermal Hydraulic Model Qualification (RETRAN)" \* Northeast Utilities NUSCO 140-1 84/07/30 262pp 25987 074 24Y Fiche 50-213,84/07/30,8408100063
- --B4081G0077 Vol II of "NUSCo Thermal Hydraulic Model Gualification (VIPRE) " \* Northeast Utilities NUSCO 140-2 84/07/30 225pp 25987 336 24% Fiche 50-213,84/07/30,8408100063
- B40B070099 Forwards Generic Ltr 84-13. "Toch Specs for Snubbers," omitted from 840503 Itr to all SEP licensees NRC position that issue of Tech Specs for snubbers will be resolved on generic basis restated
  CRUTCHFIELD.D Assistant Director for Safety Assessment 84/07/31
  KAY.J A Yanke Atomic Electric Ca COUNSIL.N Q Connecticut
  Yankee Atomic Pawer Ca COUNSIL.N Q Northeast Nuclear Energy Co
  (subs of Northeast Utilities) 4pp 25955 227 24x
  Fiche 50-000,84/07/31.8408070099 84/07/31

- 8408070320 Ack receipt of 840608 ltr forwarding Rev 6 to 9A program topical rept, per 100FR50 54 & 50 55 Revs acceptable MARTIN, T T Division of Engineering % Technical Programs 84/08/01 COUNSIL, W G Connecticut Yankee Atomic Power Co 2pp 29945 244 24X Fiche 50-000.84/08/01.8408070320
- 8408070210 Informs that proposed radiological effluent Tech Specs under review by NRC & Franklin Research Ctr NRC guidelines for radiological effluent Tech Spec 840816-17 meetings encl PAULSON, W.A. Operating Reactors Branch 5 84/08/03 COUNSIL, W.G. Connecticut Yankee Atunic Power Co. 2pp 25949 361 24X Fiche 50-213,84/08/03,8408070210
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for QLs & holders of CPs re availability of Suppl 1 to NUMEO-0933, "Prioritization of Generic Safety Issues " Svc list encl EISENHUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24% Fiche 50-000.84/08/06.8408070110
- 840Bi4040B Forwards request for addl info to complete evaluation of util 8303il response to Generic Ltr 82-20 re inadequate core cooling instrument sys.NUREG-0737. Item II F 2 CRUTCHFIELD, D. Assistant Director for Safety Assessment 84/08/06 CDUNSIL.W 0 Connecticut Yankee Atomic Power Co. 6pp 26050 349 24X Fiche 50-213.84/08/06,840Bi40408
- 8408290298 Requests extension until 841214 to respond to Generic Ltr B4-15 re proposed staff actions to improve & maintain diesel generator reliability Addl time will result in more complete & concise submittal COUNSIL.W G Connecticut Yankee Atomic Power Co COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities B4/08/17 EISENHUT.D G DIvision of Licensing 2pp 26290 342 24X Fiche 50-000.84/08/17, 8408290298
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for QLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT.D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276-244 24X Fiche 50-000.84/08/20.8408200275
- B408220326 Forwards safety evaluation & technical evaluation rept re NVREC-06/2, "Control of Heavy Loads at Nuclear Power Plants - Phase I "Sections 5 1 1 & 5 3 satisfied Phase I acceptable PAULSON.W A Operating Reactors Branch 5 84/08/20 COUNSIL.W G Connecticut Yankee Atomic Power Co 2pp 26/93 111 24X Fiche 50-213,84/08/20,8408220326
- --8408220330 Safety evaluation re NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants - Phase I " \* Operating Reactors Branch 5 84/08/20 2pp 26193 113 24X Fiche 50-213,84/08/20,8408220326
- --8407300134 "Control of Heavy Loads. Connecticut Yankee Atomic Power Co, Haddam Neck Plant," technical evaluation rept BOMBERGER.C Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-358 84/07/25 81NGH, A NRC - No Detailed Affiliation Olven 24pp 26193 115 24x Fiche 50-213,84/08/20,8408220326
- B408230386 Notification of B40823 meeting w/util in Bethesda.MD to discuss amend request to increase amount of zirconium in four zirconium clad demonstration assemblies LYONS, J E Operating Reactors Branch 5 B4/08/21 PAULSON.W A Operating Reactors Branch 5 3pp 26205 312 24X Fiche 50-213.84/08/21.8408230386
- 8408300135 Forwards proprietary topical repts, Suppl 1 to "Northeast Utils Loss of Coolant Analysis Program" & "Calculative Methods for Northeast Utils Small Break LUCA ECCS Evaluation Model," for review Repts withheld (ref lOCFR2 770) COUNSTL.N 9 Connecticut Yankee Atomic Power Co 84/08/23 PAULBON,N A Deprating Reactors Branch 5 5pp 26305 189 24X Fiche 50-213,84/08/23,8408300135
- G Inspection reports, IE Bulletins & correspondence
- 8408090180 Responds to NRC 840419 ltr re violations noted in IE Insp Rept 50-213/84-03 Corrective actions cavity water level indication will be permanently installed GDUNSIL.W G Connecticut Yankee Atomic Power Co 84/05/17 STAROSTECKI.R Division of Project & Resident Programs 3pp 25992 072 24X Fiche 50-213,84/05/17,8408090180

- 8408060190 Forwards IE Insp Rept 50-213/84-06 on 840509-11 No violations noted Items of concern noted in App A MARTIN.T T Division of Engineering & Technical Programs 84/07/09 COUNSIL, W G Connecticut Yankee Atomic Power Co 3pp 25935 191 24X Fiche 50-213,84/07/09,8408060190
- --B408060208 IE Insp Rept 50-213/84-06 on 840509-11 No violations noted Major areas inspected status of previously identified inspitens & IE Insp Procedures 82206.82207 & 82208 SMITH.R H. CROCKER.H W. Region I. Office of Director 84/06/26 Spp. 25935 194 24X Fiche 50-213.84/07/09.8408060190
- 840B090133 Forwards IE Insp Rept 50-213/84-07 on 840401-0605 No violations observed STAROSFECKI, R Division of Project & Resident Programs 84/07/20 CDUNGIL.W G Connecticut Yankee Atomic Power Co 2pp 25994 305 24X Fiche 50-213/84/07/20/8408090133
- ~-8408070141 IE Insp Rept 50~213/84~07 on 840401~0605 No violations observed Major areas inspected turbine bldg.physical security.primary auxiliary bldg.auxiliary feed pump room & radiation protection Info deleted (ref 10CFR2 790)
  SMETLAND.P D Region 1, Office of Director ELSASSER,T C Division of Project & Resident Programs 84/06/22 13pp 25994 307 24X Fiche 50~213,84/07/20,8408090133
- 840Bi50251 Forwards IE Insp Rept 50-213/84-12 on 840605-0715 No violations noted STAROSTECKI, R Division of Project & Resident Programs 84/07/25 COUNSIL. W G Connecticut Yankee Atomic Power Cu 2pp 26077 002 24X Fiche 50-213,84/07/25,8408150251
- ~-B408150255 IE Insp Rept 50-213/B4-12 on 840605-0715 No violations noted Major areas inspected control room turbine bldg, primary auriliary bldg, auriliary feed pump room, radiation protection, physical security & plant procedures SWETLAND, P.D., ELSASSER, T.C. Region 1. Office of Director 84/07/24 12pp 26077 004 24X Fiche 50-213,84/07/25,8408150251
- 8407250229 IE Info Notice 84-97, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc 11st encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc. 119pp. 25865-047 24X Fiche 50-000,84/07/27,9407250229
- 8408070194 Ack receipt of 840409 application re revised inservice insp & testing program Remittance of Class III fee requested since review involves single safety issue DIGGS.R M Office of Administration 84/07/30 COUNBIL.W Q Connecticut Yankee Atomic Power Co 1p 25957 118 24X Fische 50-213.84907/30.8408070154
- 8408100114 Responds to IE Bulletin 83-07, "Apparently Fraudulent Products Gold by Ray Miller, Inc " Entry & anginearing evaluation for Millstone Unit 2 will be done by Feb 1985 refueling outage No Ray Miller products supplied at Haddam COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W C Connecticut Vankee Atomic Power Co COUNSIL, W G Northeast Utilities 84/07/31 MURLEY, T E Ragion 1. Office of Director 3pp 25988 247 24% Fiche 50-000.84/07/31.
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 800103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000.84/08/06.8408010333
- 8408010337 IC Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp. 26067 158 24X Fiche 50-000,84/08/06,8408010337
- 8408240220 Forwards Insp Rept 50-213/84-11 on 840626-29 & notices of violation & deviation of Engineering & Technical Programs 84/08/06 COUNSIL.W © Connecticut Yankee Atomic Power Co 2pp 26236 300 24X Fiche 50-213.84/08/06.8408240220
- ---8408240223 Notice of violation from Insp on 840626-29 \* Region 1, Office of Director 84/07/31 2pp 26236 302 24X Fiche 50-213,84/08/06,8408240220
- ---B408240226 Notice of deviation from insp on B40626-29 \* Region i, Office of Director B4/07/31 ip 26236 304 24X Fiche 50-213,84/08/06,8408240220

- -8408240231 Insp Rept 50-213/84-11 on 840626-29 Noncompliance noted receipt insp rept 30-213/84-1) on 840626-27 Noncompitance in receipt insps not performed on high integrity containers. GC program not conducted to ensure compitance of radwaste transfer & radwaste transfer mati not maintained and CEMONS.P. pASCIAK.U Region 1. Office of Director 84/08 Bpp 26236 305 24X Fiche 50-213.84/08/06.8408240220 84/08/01
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " 8vc 11st encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 8230103) 84408/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 84% Fiche 50-000.84/08/08.8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc Parties of the Consultation of GA. Safeguards & Inspection Programs (Post 830103) 84/08/10 Consultdated Edison Co. of New York, Inc. 125pp. 26130 001 24% Fiche 50~000.84/08/10.8408070376
- 8408210480 Responds to notice of violation in IE Insp Repts 50-213/83-25 & 50-245/84-07 Corrective actions taken to restore post-accident sampling sys units to see & determine problem COUNSIL, W G Connecticut Yankse Atomic Power Co COUNSIL, W.G. Northeast Nuclear Energy Co (subs of Northeast Chilities)
  COUNBIL W G Northeast Utilities 84/08/10 DEYCUNG, R C
  Director's Office, Office of Inspection and Enforcement 1.
  24181 196 24X Fishe 50-000, 84/08/10, 8408210480
- 8408100009 IE Info Natice 84-69. "Defective RHR Replacement Piping "
- 8408220222 Forwards fee for review of revised inservice insp &
- 8408100038 IE Info Notice 84~64, "BWR HPCI Initiation Seal-In & NOTIONAL IC INFO NOTICE 84-04. "BWK MPC| Initiation Seal-In & Indication "Syc Inst ent]
  JURDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 630103) 84/08/15 Consolidated Edison Co of New
  York, Inc 104pp 26198 093 24X Fiche 50-000.84/08/15.8408100038
- 840B100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp. 26198 001 24% Fiche 50-000,84/08/16,8408100021
- 8408100095 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list enci JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 820103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- 8408140208 IE Info Notice 84-67, "Recent Shubber Inservice Testing W/ High Failure Rates" Svc list encl JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New 03) 84/08/17 Consolidated Edison Co of New 25275 122 24% Fiche 50-000,84/08/17,8408140208 122pp
- 8408210142 I& Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc. 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142
- S Reportable occurrences, LERs & related correspondence
- 8408230482 LER 84-008-00 on 840721, fire door separating safety & nonsefety-related areas discovered w/inoperable latching mechanism Caused by personnel error Door repaired W/840814
- 8408280107 PNO-1-84-070 on 840821: reactor vansel cavity seal failed when initially filled Caused by trip in containment sump pump under reactor vessel Licentee evaluating tituation Notification of state & lotal authorities undertaken SWETLAND.P., MCCABE, E. Region 1. Office of Director 84/08/21 26261 301 24% Fiche 50-213.84/08/21,8408280107 84/08/21 1p

- 8408310107 Discusses 840821 reactor cavity seal ring failure & followup Actions Evaluations of consequences of event or corrective actions incomplete NRC will be informed of findings prior to resumption of refueling activaties COUNSIL.W G Connecticut Yankee Atomic Power Co B4/08/23 CRUICHFIELD, D Assistant Director for Safety Assessment 26322 279 24X Fiche 50-213.84/08/23.8408310107
- 8408310074 PNO-I-84-073 on 840824, offsite power lost Emergency diesel A started but did not close to bus % RHR flow for shutdown reactor lost until RHR pump supplied by emergency diesel placed on-line Tripped transformer placed on-line SWETLAND.P. MCCAUE.E. Region 1. Office of Director 84/08/24 is 26322 201 24% Fiche 50-213,84/08/24,8408310074
- B40B310111 PND-1-84-070A on B40B23, refueling cavity to reactor vessel seal failure identified during fuel transfer Cavity-to-vessel inflatable boot seal unique in US Failure w/fuel transfer tube open would result in high radiation SWETLAND.P., MCCABE.E. Region i. Office of Director 84/08/24 ip 26322 113 24X Fiche 30-213,84/08/24,840B310111
- 8408310125 Advises that submittal of proposed corrective action for NRC review & approval will be required prior to any fuel handling over reactor or in transfer tube, per util 840823 notification of reactor cavity seal ring failure PAULSON. WA Operating Reactors Branch 5 84/08/29 COUNSIL, WG Connecticut Yankee Atomic Power Co 2pp 26322 109 24% Fiche 50-213.84/08/29.8408310125
- DOCKET 90-219 OYSTER CREEK NUCLEAR POWER PLANT F Security, medical, emergency & fire protection plans
- 8408060139 Ack receipt of 840924 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/84-05
  MARTIN.T T Division of Engineering & Technical Programs 84/07/18
  FIEDLER.P B General Public Ubilities GPU Service Corp 2pp
  25935 161 24X Fichs 50-219.84/07/18.8408060139
- -8408060142 Responds to NRC 840412 ltr re violations noted in IE Insp Rept 50-219/84-05 Corrective actions description of onsite meteorological monitoring sys will be included in emergency plan
  FIEDLER, P B General Public Utilities - GPU Service Corp
  84/05/24 MARTIN T T Division of Engineering & Technical
  Programs 3pp 25935 163 24% Fiche 50-219,84/07/18,8408060139
- 8408150238 Advises that portions of 840131 Rev 15 to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable Certain other portions of rev considered unacceptable Reasons stated in one! Encl withheld (ref 10CFR73 21) MARTIN,T T Division of Engineering & Technical Programs FIEDLER.P B General Public Utilities OPU Bervice Corp 3pp 26066 001 24x Fiche 50-219.84/08/03.8408150238
- 840Bi30191 Informs of error in 840627 correspondence re NUREO-0737.ltem I C 1.Table 2 Phase I emergency operating procedures (EUPs) not in place in Nov 1983 EUPs will be implemented prior to restart from Cycle 10 refueling outage FIEDLER.P B General Public Utilities ~ GPU Service Corp 84/08/06 CRUTCHFIELD.D D Operating Reactors Branch 5 1p 26006 362 24x Fiche 50~219.84/08/06.8408130191
- 8408280291 Forwards Insp Rept 50-219/84-10 on 840316-0430 No violations STAROSTECKI.R Division of Project & Resident Programs & FIEDLER.P D General Public Utilities - GPU Service Corp 24282 183 24X Fiche 50-219.84/08/10,8408280291
- --8408280293 Insp Rept 50-219/84-10 on 840316-0430 No violations noted Major areas inspected plant operations, logs & records, plant tours, physical security, radiation protection, maint observation, refueling preparations & periodic repts HECHSELBEROER, COMPILL, C. J., CONNER, E. L. Region 1, Office of Director 84/08/07 10pp 26282 185 24X Fiche 50-219,84/08/10,8408280291
- 8408300087 Forwards Insp Rept 50-219/84-03 on 840201-0315 No violations noted STARGSTECKI,R Division of Project & Resident Programs 84/08/10 FIEDLER,P D General Public Utilities - GPU Service Corp 2pp 26308 086 24x Fiche 50-219.84/08/10.8408300087
- AUB300096 Insp Rept 50-219/84-03 on 840201-0315 No violations noted Major areas inspected previous insplitmms, records, plant operations, physical security, radiation protection, maint & surveillance & review of periodic repts CDWOILL, C. J., WECHBELBERGER, CDWNER, E. L. Region 1, Office of Director 84/08/08 8pp 26308 08B 24% Fiche 50-219,84/08/10.8408300087 ---8408300076 Insp Rept 50-219/84-03 on 840201-0315 No violations noted

- 8408190269 Forwards "Evaluation of Detailed Control Room Design Review Summary Rept for Ogster Creek Nuclear Generating Station," technical evaluation rept, per Suppl 1 to NUREG-0737 SALP input also encl
  - Input also enc!
    PAULESON, W A Operating Reactors Branch 5 84/08/14 FIEDLER, P B
    General Public Utilities GPU Service Corp 14pp 26067 066 24)
    Fiche 50-219,84/08/14,8408150269
- --B408150275 "Evaluation of Detailed Control Room Design Review Summary Rept for Ogster Creek Nuclear Generating Station," final technical rept \* Science Applications, Inc NRC-03-82-096 1-263-07-557-48 B4/07/20 35pp 26067 078 24X Fiche 50-219,84/08/14,8408150269
- B408300172 Forwards exemption from schedular requirements re fire protection of equipment used for safe shutdown by means of separation & barriers per 10CFR50 4B(c)(4) Exemption effective until startup from Cycle 11 refueling outage PAULSON.W A Operating Reactors Branch 5 84/08/23 FIEDLER, P B General Public Utilities OPU Service Corp 2pp 26304 349 24X Fiche 50-219.84/08/23 B408300172
- --B40B300175 Exemption from schedular requirements re fire protection of equipment used for safe shutdown by means of separation & barriers
  DENTON.HR Defice of Nuclear Reactor Regulation, Director B4/08/23 General Public Utilities GPU Service Corp 6pp 26304 351 24X Fiche 50-217,84/08/23,840B300172

#### G Adjudicatory correspondence

- B40B140449 Petition for revocation of license on basis of deficient character Licensee record of whengdoing directly related to fundamental character flaws inherent within company Certificate of Svc encl HAMBACH.P C. SHUMAKER, J. Pennsylvania, Commonwealth of, SCRDILL, P. Women's International League for Peace & Freedom DSI COT B4/0B/13 Commissioners 200pp 26061 023 24X Fiche 30-000.84/0B/13,840B140449
- 8408240250 Forwards supplemental pages for 840813 petition for revocation of license of GPU on basis of deficient character DOROSHOW, J Three Mile Island Alert DSD 258 84/08/22 Commissioners ip 26223 018 24X Fiche 50-000,84/08/22, RACCPAD250
- --8408240257 Supplemental pages to petition for revocation of license on basis of deficient character Certificate of Svc encl \* General Public Utilities GPU Service Corp 64/08/13 Atomic Safety and Licensing Board Panel 43pp 26223 019 24X Fiche 50-000,84/08/22,8408240250
- P Operating license stage documents & correspondence
- 8408070052 Forwards "Evaluation of Spent Fuel Racks Structural Analysis, Gyster Creek," technical evaluation rept Adequacy of structural design cannot be determined Add1 info requested within 15 days FAVLSON, W.A. Operating Reactors Branch 5 84/07/27 FIEDLER, P.B. General Public Utilities GPU Service Corp. 4pp. 25956 141 24X Fiche 50-219,84/07/27.8408070082
- --8407090037 "Evaluation of Spent Fuel Racks Structural Analysis. Oyster Creek Nuclear Generating Station." technical evaluation rept
  HERRICK.R C Franklin Institute/Franklin Research Center NRC-03-91-130 TER-05304-325 84/07/05 KIM.S B NRC No Detailed Affiliation Given 34pp 25936 144 24X Fiche 50-219,84/07/27,8408070052
- 8408070300 Forwards "SEP Topic III-10A.Thermal Overload Protection for Motors of Motor Operated Valves "Methodology to determine optimum setpoints (heater size) for thermal overload relays developed FIEDLER.P B General Public Utilities GPU Service Corp 84/07/30 CRUTCHFIELD.D Operating Reactors Branch 5 3pp 26106 063 24X Fiche 50-219.84/07/30,8408070300
- --8408070306 "SEP Topic III-10A, Thermal Overload Protection for Motors of Motor Operated Valves " \* General Public Utilities - GPU Bervice Corp TDR 519 R00 84/07/30 33pp 25947 253 24X Fiche 50-219,84/07/30,8408070300
- 8408070454 Forwards Rev 2 to "SEP Topic VI-7 C ; App K-Electrical Instrumentation & Gontrol Re-Review." including new coordination plots for Faults F1-7, per 820528 commitment Trip units will installed by end of Cycle XI outage FIEDLER:P B. General Public Utilities GPU Service Corp 84/07/30 CRUTCHFIELD.D Operating Reactors Branch 5 27pp 25940 069 24) Fiche 50-219,84/07/30.8408070454

- 6408070079 Forwards Generic Ltr 84-13, "Tech Specs for Snubbers," omitted from 840503 ltr to all SEP licensees NRC position that issue of Tech Specs for snubbers will be resolved on generic basis restated CRUTCHFICLD.O Assistant Director for Safety Assessment 84/07/31 KAY, J A Yankee Atomic Electric Co KOBER, R W Buchester Cas & Electric Cop BASKINK P Southern California Edison Co 4pp 25755 227 24% Fiche 50-000, 84/07/31, 8408070079
- 8408070152 Forwards response to questions forwarded by 840727 ltr reutil request to expand capacity of spent fuel pool FIEDLER.P B General Public Utilities GPU Service Corp 84/07/31 CRUTCHFIELD.D Opera+ing Reactors Branch 5 3pp 25947 358 243 Fiche 50-219,84/07/31.8408070152
- B408070348 Forwards revised Pages 6-17 & 6-18 to 830702 submittal of facility description & SAR Amend 79 re spent fuel pool expansion FIEDLER.P B General Public Utilities GPU Service Corp 84/07/3: Office of Nuclear Reactor Regulation, Director 3pp 25945 176 24X Filhe 50-219, 84/07/31. B408070348
- B408070304 Forwards FR notice of environ assessment & finding of no significant impact re util 840802 request for schedular exemption from requirements of 100FR50 44(c)(3)(i)i) PAULSON.W A Operating Reactors Branch 5 84/08/02 FIEDLER.P 8 General Public Utilities GPU Service Corp 2pp 25947 224 24X Fiche 50-219:84/08/02.8408070304
- --8408070309 Notice of environ assessment & finding of no significant impact re util 840802 request for schedular exemption from requirements of 100FR90 44(c)(3)(iii) re isolation condenser high point vents EISENHUT.D o Division of Licensing 84/08/02 9pp 25947 226 24% Fiche 90-219,84/08/02,8408070304
- 8408090250 Forwards Rev O to TDR 481, "SEP Topic VII-iA, Isolation of Reactor Protection Sys From Nonsafety Sys. Including Qualifications of Isolation Devices." failure mode & effects analysis
  FIEDLER.P B General Public Utilities GPU Service Corp 84/08/03
  CRUTCHFIELD.D Operating Reactors Branch 5 2pp 25972 267 249
  Fiche 50-219,84/08/03,8408090250
- --8408090257 Rev O to "SEP Topic VII-1A. Isolation of Reactor Protection Bys From Nonsafety Sys. Including Qualifications of Isolation Devices: "failure mode & effects analysis \* General Public Utilities - GPU Service Corp TOR 481 ROO 84/08/03 lipp 25972 269 24X Fiche 50-219.84/08/03.8408090250
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of Suppl 1 to NUREO-0933. "Prioritization of Generic Safety Issues: "Svc list encl EISENHUT,D 9 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000.84/08/06.8408070110
- 840B150225 Forwards schedular exemption from compliance w/10CFR50 44 ro installation of isolation condensor high point vents during current Cycle 10 refueling outage to Cycle 11 refueling outage PAULSON, W.A. Operating Reactors Branch 5 B4/08/09 FIEDLER, P.B. General Public Utilities - GPU Service Corp. 2pp. 26066 074 24X Fiche 50-217.84/08/09.8408150225
- --840Bi50228 Schedular exemption from compliance w/10CFR50 44 re installation of isolation condenser high point vents during current Cycle 10 refueling outage to Cycle 11 refueling outage EISENHUT. D.G. Division of Licensing 84/08/09 General Public Utilities - OPU Service Copp. 5pp. 26066 076 24X Fiche 50-219,84/08/09.840Bi50225
- 8408150227 Summary of 840718 meeting w/utils in Bethesda, MD re ECCS evaluation methodology for BWR-2 applications Agenda & Viewgraphs enci LOMBARDDIJ J Operating Reactors Branch 5 84/08/14 Operating Reactors Branch 5 22pp 24064 048 24X Fiche 50-000, 84/08/14, 8408190229
- 8408220375 Responds to request for add1 info re analysis to determine gas & water clearing thrust loads concerning second safety relief valve actuations in discharge lines.per NUREG-0641 Containment adequate for five & add1 five valve actuation FIEOLER.P B General Public Utilities OPU Service Corp 84/08/15 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 26171 347 24X Fiche 50-219.84/08/15.8408220375

- 0356 Informs that procedural changes in response to Generic Ltt 8. Items 1 1 & 1 2 (post-trip review) not made by 040331 chedwise due to estended Cycle 10 outage Changes will be prior to startup Rept re Item 4 5 3 due by 050915 LCR.P 0 General Public Utilities GPU Service Corp 04/08/16 ivision of Licensing 2pp 26189 355 24% e 50-219.84/08/16.8408220356
- ID275 Coneric Ltr 84-20 to all licenses of operating reactors trants for DLs re-scheduling guidance for licenses intrals of reloads that involve unreviewed safety tions Svc list encl NHUT.D G Division of Licensing 84/08/20 Consolidated on Co of New York, Inc. 17pp 26278-244 24% ie 50-000.84/08/20.8408200275
- 0008 Forwards notice of environ assessment % finding of no inficant impact re-extension of deadline for safe down equipment installation per 840711 request for adular exemption from 100FR\$0.48(c)(4) requirements SDN.W.A. Operating Reactors Branch 5. 84/08/20 FIEDLER.P. 10 and Public Utilities GPU Service Corp. 2pp. 26181-326. 24% of 50-318.84(8)(20, 640-320, 650-310, 650-310) ie 50-219,84/08/20,8408210008
- 321001| Notice of environ assessment & finding of no significant spact re-extension of deadline for safe shutdown juipment installation Division of Licensing 84/08/20 4pp 26181 328 ISENHUT D G 4X Fiche 50-217,84/08/20,8408210008
- 30384 Forwards SER re util resolution of integrated plant SAR tion 4 14 re thermal overload protection of or operated valves Program described in 840730 ltr eptable LSON,W A Operating Reactors Branch 5 84/08/20 FIEDLER,P B sey Cential Power & Light Co 2pp 26205 315 24X he 50-219.84/08/20.8408230384
- 8230385 Safety evaluation re-integrated plant SAR Section 4 14 re-harmal overload protection of motor operated valves Program roposed in 840730 ltr acceptable

  Operating Reactors Branch 5 84/08/20 2pp 26205 317 24X 1che 50-219,84/08/20,8408230384
- '703B1 Responds to request for reliable ventilation for B battery & or generator room & 460-volt switchgear room, per SEP , it IX-5 (New redundant relay w/switch & associated wiring 1 be installed by end of next refueling outage IDLER.P B General Public Utilities GPU Service Corp E4/08/21 (UTCHFIELD.D Operating Reactors Branch 5 2pp 26240 250 24% he 50-219.84/08/21.8408270381
- 270285 Forwards Technical Data Rept 580 re repair & failure 3/0283 Forwards lectrical Data Rept Sed Fe repair 2 Failure signis data for isolation condenser sys piping cracked lds.per 940628 request concerning SER of Rev 1 to 180-0313 imblementation
  EDLER.P B General Public Utilities - GPU Service Corp 84/08/22 WUL-90R,N A Operating Reactors Branch 5 1p 26243 158 24% che 50-219.84/08/22.8408270285
- 08270290 Rev O to "Isolation Condender Sys Piping Cracked Welds -Repair & Failure Analysis "
  ABRAMQVICI.JD . COVILL.D W . ELAM.B D General Public Utilities PU Service Corp 580 R00 B4/08/04 B6pp 26243 159 24X
  Fiche 50-217,84/08/22,8408270285
- 300148 Forwards safety evaluation re NUREG-0737. Item II B 3 nomining post-accident sampling sys Post-accident sampling sacreptable ULBON, W A Operating Reactors Branch 5 84/08/29 FIEDLER, P B neral Public Utilities GPU Service Corp 8pp 26306 001 24) che 50-219.84/08/29.8408300148
- napection reports. IE Bulletins & correspondence
- 040139 Ack receipt of 840524 ltr informing NRC of steps taken to rrect violations noted in IE Insp Rept 50-219/84-05
  RTIN, T T Division of Engineering & Technical Programs 84/07/18
  IEDLER, P B General Public Utilities GPU Service Corp 2p 24x Fiche 50-219.84/07/18.8408060139
- 08060142 Responds to NRC 840412 ltr re violations noted in IE Insp Rept 80-219/84-05 Corrective actions description of onsite meteorological monitoring sys will be included in emergency
- meteorological months, by Type Plan FIEDLER, P. B. General Public Utilities GPU Service Corp. 84/03/24 MARTIN, T. Division of Engineering & Technical Programs 3pp 25735 163 24X Fiche 50-219,84/07/18,8408060139

- 8408080463 Forwards 16 Insp Rept 50-219/84-17 on 810601-08 No violations noted
  MARTIN-1 T Division of Engineering & Technical Programs 84/07/20
  FIEDLER,P B General Public Utilities - GPU Service Corp 2pp
  25975-075 24x Fiche 50-219 84/07/20.8408080443
- --8408080167 IE Insp Rept 50-219/84-17 on 840604-08 No noncompliance 408080167 IE Insp Rept 50-219/84-17 on B40604-08 No nonco noted Majot areas inspected program for QA of analytical measurements, training. ngt controls, audit results to analytical procedures for chemistry & radiochemistry JANG. J. C. PABCIAK.W. J. Region 1, Office of Director Bpp 25975 077 24X Fiche 30-219, 84/07/20, 8408080463 04/06/27
- 8407250229 IE Info Notice 84-57, "Operating Experience to Moisture 407250229 IE Info Notice 84-57. "Operating Experience to Notice 84-57. "Operating Experience to Notice 84-57. "Operating Experience to Notice 84-57. "Operating Experience 90 Propuredness 9 Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc. 119pp 25865-047 24X Fiche 50-000.84/07/27.8407250229
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list end!

  JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 85pp 26068 001 24/4 Fiche 30-000,84/08/06,8408010333
- 8408010337 IE Info Natice 84-40. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list oncl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York. Inc. 123pp. 26067 158 24% Fiche 50-000,84708/06,8408010337
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Past 830103) 84/08/08 Consolidated Edison to of New York Inc 120pp 26129 118 244 Fiche 30-000.84/08/08.8408070120
- 8408070J76 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list encl GRACE.J N. Division of OA. Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000.84/08/10.8408070376
- B40B230094 Ack receipt of B40725 ltr informing NRC of steps taken to correct items noted in 1E Insp Rept 90-219/83-24

  MARTIN.T T Division of Engineering & Technical Programs 84/08/10

  FIEDLER.P B General Public Utilities 9PU Service Corp 1p

  26214 158 24X Fiche 50-219.84/08/10.8498230094
- --8408230098 Responds to NRC 840209 ltm relitems noted in IE Insp. Rept. 50-219/83-24 Corrective actions Procedure 125, 'Engineering Calculations & Technical Evaluations,' prepared FIEDLER.P B General Public Utilities GPU Service Corp. 84/07/25 MARTIN,T T Division of Engineering ? Technical Programs 2pp 26214 159 24% Fiche 50-219.84/08/10.8408230094
- --8408230101 Rev & to Procedure 129, "Engineering Calculations & Technical Evaluations "

  \* General Public Utilities - GPU Gervico Corp 84/07/25 7pp
  26214 161 24% Fiche 50-219,84/08/10,8408230094
- 8408280291 Forwards Insp Rept 50-219/84-10 on 840316-0430 No violations noted
  STARDSTECKI:R Division of Project & Resident Programs D4/08/10
  FIEDLER.P B General Public Utilities - GPU Service Corp 2pp
  26282 183 24X Fiche 50-219:84/08/10.8400280291
- --8408280293 inso Rept 50-219784-10 un 840316-0430 No violations noted NUMBERURYS Insp Rept 50-219/84-10 on 840316-0430 No violations noted Major areas inspected plant operations logs & records plant tours physical security, radiation protection, maint observation, refueling preparations & periodic repts MECHSELBERGER, COMOILL, C.J., CONNER, E.L., Region I, Office of Director 84/08/07 iOpp 26282 IBS 24X Fiche 50-217,84/08/10,8408280291
- 8408300087 Forwards Insp Rept 50-219/84-03 on 840201-0315 No violations noted STARDSTECKI.R Division of Project & Hesident Programs 84/08/10 FIEDLER.P B General Public Utilities - GPU Service Corp 2pp 26008 086 24x Fiche 50-219.84/08/10.8408300087
- Major areas inspected previous insplitems, records, plant one noted Major areas inspected previous insplitems, records, plant operations, physical security, radiation protection, maint & surveillance & review of periodic lepts COMMILL, C. J., WECHSELBERGEN, CONNER, E. L. Region i, Defice of Director 84/08/08 8pp 26308 08B 24X Fiche 50-219,84/08/10,8408300087 --8408300096 Insp Rept 50-219/84-03 on 840201-0315 No violations noted

- 840B100009 IE Info Notice 84-53, 'Defective RHR Replacement Piping " Svc list encl JORDAN, E L Division of Emergency Preparedness' Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Itic 119pp 26197 218 24x Fiche 50-000,84/08/13,8408100009
- 8408310128 Responds to IE Bulletin 83-07 re apparently fraudulent products sold by Ray Miller. Inc Mechanisms which can detect major breakdowns in GA program listed Current program verifies quality of safety items
  FIEDLER, P B General Public Utilities GPU Service Corp 84/08 EBNETER, S D Region 1, Office of Director 3pp 26JR2 257 2 Fiche 50-239,84/08/14,8408310128
- 840810003E IE Info Notice 84-64, 'BWR MPCI Initiation Seal-In & Indication 'Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24% Fiche 50-000/84/08/15,8408100038
- 8408100021 IE Info Notice 84-65, "Undersated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JURDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26198 001 24X Fiche 50-000.84/08/16,8408100021
- 8408100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Foodwater Train " Svc list encl JORDAN.E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York. Inc 120pp 26276 001 24X Fiche 50-000.84/08/17.8408100055
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Ratas " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York Inc 122pp 26276 122 24X Fiche 50-000.84/08/17,8408140208
- 8408210142 JE Info Notice B4-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves "Svc list enci JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc. 115pp 26327 008 24X Fiche 50-000-84/08/21, 8408210142
- 9 Reportable occurrences. LERs & related correspondence
- 8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit stram pilot solenaid valve plunger Initially reported on 840413 New thread locking devices investigated SHERWOOD, GO General Electric Co 84/04/13 DYYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24% Fiche 50-000,04/04/13,8408240348
- 8408010293 LER B4-016-00 on 840625, during review of instrument surveillance procedures, not all 60 installed excess flow check valves found functionally tested per Toch Specs Functional test surveillance rev in progress U/940724 ltr MURDDCK, R J , FIEDLER, P B General Public Utilities GPU Service Corp 84/07/24 App 25866 191 247 Fiche 50-219,84/07/24, 8408010293
- 8408080478 LER 84-017-00 on 840627, during lifting of noutral electrical lead, 15 primary containment isolation valves ispositioned & half scram experienced Caused by intermediate range monitor Neutral wiring configuration will be modified W/840726 ltr ALLEN, M H . FIEDLER, P B General Public Utilities GPU Service Corp 84/07/26 12pp 25975 220 24X Fiche 30-217, 84/07/26, 8408080478
- 8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl 9E lacks technical info to adequately evaluate condition

  VILLA: R General Electric Co 84/08/21 ROSSI: C E Director's Office, Office of Inspection and Enforcement Spp 26318 327 24X Fiche 50-000.84/08/21.8408310186
- DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8408040171 Revised emergency procedures, including Rev 1 to EPMP-5, "On-Call Procedure" & Rev 0 to EPMP-8, "Maint fosting & Operation of Oswego County Prompt Notification Sys "
  W/840801 ltr
  MANGAN.C V Niagara Mohawk Power Corp 84/08/01 87pp 25932 288
  24X Fiche 50-220,84/08/01.8408040171

- 8408/30226 Forwards (E Insp Rept 50-220/84-10 on 840611-15 & notice of violation
   0 f violation

   MARTIN, T T Division of Engineering & Technical Programs
   84/08/01 H00TEN B Q Niagara Mohawk Power Corp 2pp 26213 329
   24X

   Fight 50-220 84/08/01 8408/330226
- --B40B230230 Notice of violation from insp on 840611-15 List of recommended emergency preparedness program improvements encl # Region I. Office of Director 84/07/31 2pp 26213 331 24X fiche 50-220,84/08/01.8408230226
- --8408230235 IL Insp Rept 50-220/84-10 on 840611-15 Violation noted failure to conform to environ surveillance requirements for maintaining meteorological monitoring equipment HAWKHURSI.J. COMEN.I., CRACKER.H W. Region 1. Office of Director 84/07/31 6pp 26213 333 244 Fiche 50-220.84/08/01.84082302&6
- 8408070434 Forwards rev to "NY State Radiological Emergency Preparedness Plan" MANGAN.C V Niagara Mohawk Power Corp 84/08/03 Record Services Branch (Document Control Desk) 2pp 25938 014 24x Fiche 50-220.84/08/03.8408070434
- --8408070439 Rev to "NY State Radiological Emergency Preparedness Flan " a New York, State of 84/07/12 557pp 25738 018 24X Fiche 50-220,84/08/03,8408070434
- P Operating license stage documents & correspondence
- 8408030180 Forwards SER re completion of Multi-Plant Insues B-24, "Venting & Purging of Containment" & F-19. Item II E 4 2, "Containment Isolation Dependability " Demonstration of containment purge & Vent valve operability acceptable VASSALLO, D B Operating Roactors Blanch 2 84/07/24 MODYEN, B 9 Niagara Mohawk Power Corp 7pp 25917 349 24X Fiche 50-220,84/07/24,8408030180
- 8408060154 Completes response to Generic Ltr 84-09 re NAC decision not to backfit requirement for hydrogen recombiner capability in inserted Mark I containments to control post-accident hydrogen Capability not required MANGAN, C V Niagara Mohawk Powel Corp 84/07/31 VASSALLD, D B Operating Roactors II anch 2 2pp 25923 051 24x Fiche 50-220,84/07/31,8408060154
- B40B06024B Forwards add1 response to Generic Ltr 83-28 ie generic implications of Salem ATUS events Reactor protection system-line surveillance program requirements assure reliability of system function properly MANGAN, CV Niegare Mohawk Power Corp 84/07/31 VASSALLCI, D B Operating Reactors Branch 2 4pp 25934 108 24X Fiche 50-220,84/07/31,8408060248
- 9408060278 Notification of 840B17 meeting w/util in Dathesda.MD to discuss control design review HEIMANN.R A Operating Reactors Dranch 2 84/07/31 VASSALLD.D D Operating Reactors Branch 2 2pp 29937 361 24x Fiche 50-220.84/07/31.8408060278
- B40B060332 Notification of B40B23-24 meetings w/utils in Waltham,MA to discuss open items on Hark I containment program HERMANN,R A Operating Reactors Branch 2 B4/07/31 VASSALLO.D B Operating Reactors Branch 2 2pp 2593/357 24X Fichs 50-000.B4/07/31.B408060332
- B408090077 Forwards Pages 226 to 226a to Table 3 6 21 of Tech Specs redigeel generator for instrument setpoint logic in support of B40413 amend application Response to NRC questions also encl (MANGAN, C.V. Niagara Mohawk Power Corp. 84/08/03 VASSALLO, D. 8 Operating Reactors Branch 2 tp. 25793 001 24X Fiche 50-220.84/08/03.8408090077
- --840809008: Proposed revs to Tech Spec Table 3 & 2; re diracl generator initiation.iimiting condition for operation \* Niagara Mohauk Power Corp 84/08/03 9pp 25993 002 24X Fiche 30-220,84/08/03,8408090077
- 8408070110 Generic Ltr 84-19 to all licenses of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Generic Safety Issues " Svc list and EISENWITD O Division of Licensing 84/08/06 Consulidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000.84/08/06.8408070110

- B40B100074 Forwards Rev 2 to "Leak-Before-Break Analysis of High Energy Piping Sys " Rept includes detailed stress & fracture mechanics analyses MANGAN.C V. Niagera Mohawk Power Cotp. 84/08/06 VASSALLG.D B Operating Reactors Branch 2 1p. 25988 285 24X Fiche 50-220.84/08/06.8408100074
- --8408100080 Rev 2 to "Leak-Before-Break Analysis of High Energy Piping Bys "
  # MPR Associates. Inc MPR-820 RO2 84/09/06 86pp 25988 287
  24% Fiche 50-220.84/08/06.8408100074
- 840810D076 Forwards application for amend to License DPR-63, changing Tech Specs to remove commitment to perform independent audit under cognizance of Safety Review & Audit Board MANGAN, C V Niagara Mohawk Power Corp 84/08/06 VASSALLO, D B Operating Reactors Branch 2 1p 25987 020 24% Fiche 50-220,84/08/06,8408100076
- --840B1000B1 Application for amend to License DPR-63, changing Toch Specs to remove commitment to perform independent audit under cognitance of Safety Review & Audit Board MANDAN.C V Niagara Mohawk Power Corp 84/08/06 2pp 25987 021 24X Fithe 50-220,84/08/06,8408100076
- -8408100086 Proposed Tech Specs, removing commitment to perform independent audit under cognizance of Safety Review & Audit Board ntagara Mchawk Power Corp. 84/08/06. 4pp. 25987 023. 24% Fiche 50-220,84/08/06,8408100076
- 0408100103 Forwards application for amend to License DPR-63.per Generic Ltr 83-19 Fee encl MANGAN, C V Niagara Mohawk Power Corp 84/08/07 VASSALLO, D B Operating Reactors Branch 2 ip 25990 355 24x Fiche 50-220,84/08/07.8408100103
- --8408100111 Application for amond to License DPR-63, changing Tech Spocs by deleting "all" from review & audit section to be consistent u/Rev 2 to BMR Tech Specs (NUREO-0123) MANOAN.C V Ningara Mohawi Power Corp 84/08/07 5pp 25970 356 24% Fiche.50-220,84/08/07,8408100103
- --B408100120 Proposed Tech Spec & 5 2 B re audits \* Niagara Hohawk Power Corp 84/08/07 ip Fiche 50-220,84/08/07,8408100103 1p 25990 341 24X
- 8408170079 Informs of review of 840610 & 11 QA program description changes Changes acceptable Concerns in unrevised portions of program noted MARTIN.T T Division of Engineering & Technical Programs 84/08 HOGTEN, B J Niagara Mohawk Power Corp 2pp 26119 022 24X Fiche 50-220,84/08/09,8408170079
- 84708709
- 8408160367 Forwards "SER, Evaluation of Turbine Missile Protection," NOBIOUSIN FORWARDS "ERK, Evaluation of Turbine Missile Priper 8006-97 commitment Bafe shutdown capability would be maintained if turbine missile generated MANGAN.C V Niagara Mohawk Power Corp 84/08/14 VABS Operating Reactors Branch 2 ip 26091 237 24X Fiche 50-220,84/08/14.8408160267 /14 YABBALLO,D <u>B</u> 24%
- -8408160372 "SER, Evaluation of Turbine Missile Protection" # Niagera Mohawk Power Corp 84/07/31 4pp 26091 238 24X Fichs 50-220, 84/08/14,8408160367
- 408200275 Generic Ltr 84~20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EIBENHUT.D Q Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000,84/08/20,8408200275
- 8408300035 Forwards application for amend to License DPR-63, changing Tuch Specs re containment leak test program Application suppls 831101 amend request MANGAN.C V Niagara Mohawk Power Corp 84/08/27 VASSALLO.D B Operating Reactors Branch 2 ip 26306 028 24% Fichs 50-220,84/08/27,8408300035
- --B40B300037 Application for amend to License DPR-63, changing Tech Specs to revise containment losk test program HANGAN.C V Niagara Mnhawk Power Carp B4/0B/27 2pp 26304 029 24% Fiche 50-220, B4/0B/27, B40B300035

- --B408300041 Proposed changes to Tech Specs, tevising containment leak test program
  hagara Mohawk Power Corp 84/08/27 46pp 26306 031 24x
  Fite 3-20, 84/08/27, 8488300035
- O Inspection reports: IE Nulletins & correspondence
- 8408080456 Forwards IE Insp Sept 50-220/84-08 on 840509-11 & 0606-08 No violations noted
  MARTIN, T T Division of Engineering & Technical Programs
  HQQTEN, B C Niegara Mohawk Power Corp 2pp 25975 066
  Fiche 50-220, 04/07/18, 8408080456 84/07/18
- --8408080461 IE Insp Rept 50-220/84-08 on 840509-11 & 0606-08 No violations noted Major areas inspected containment leakage testing program, including procedure review of integrated leak rate test & local leak rate test procedures VIIU.D J Region 1. Office of Director BETTENHAUSEN, L Divisi of Engineering & Technical Programs 84/06/29 7pp 25975 068 24X Fiche 50-220,84/07/18,8408080456
- 8408080204 Forwards IE Insp Rept 50-220/84-12 on 840618-22 No violations observed
  MARTIN T T Division of Engineering & Technical Programs 84/07/19
  HQQTEN,B G , SEIBERT C R Niagara Mohawk Power Corp 2pp
  25975 016 24X Fiche 50-220,84/07/19,8408080204
- --8408080209 IE Insp Rept 50-220/84-12 on 840618-22 No violations (AG080209 IE Insp Rept 50-220/84-12 on 840618-22 No viol.
  noted Hajor areas inspected nonradiological chemistry
  program.including staffing & training. 9C of analytical
  measurements & procedures
  TIBULSKY, H. PASCIAK, U. J. Region 1, Office of Director
  3pp 25975 018 24X Fichs 50-220,84/07/19.8408080204
- B407280227 lE Info Notice 84-97, "Operating Experience re Moisture Intrusion in Bafety-Related Electrical Equipment at Commercial Power Plants " Svc list enci JORDAN, El Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of York, Inc 117pp 25865 047 24% Fiche 50-000,84/07/27,8407250 24X Fiche 50~000,84/07/27,8407250229
- 8408230226 Forwards IE Insp Rept 50-220/84-10 on 840611-15 & natice of violation

  MARTIN T T Division of Engineering & Technical Programs 84/08/01

  HODIEN, 8 0 Niagara Hohawk Power Corp 2pp 24213 329 24X

  Fithe 50-220, 84/08/01, 8408230226
- --8408230230 Notice of violation from insp on 840611-15 List of recommended emergency proparedness oragiam improvements enc: \* Region I. Office of Director 84/07/31 2pp 26213 331 24% Fiche 50-220,84/08/01,8408230226
- -8409230235 IE Insp Rept 50-220/84-10 on 840611-15 Violation noted failure to conform to environ surveillance requirements for maintaining networological monitoring equipment HAMXHURST, J. COMEN. I. CRACKER, H. Region I. Office of Director 84/07/31 App. 26213 333 24X Fiche 30-220,84/08/01,8408230226
- 8408010333 IC Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures "Syc list oncl JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of Ne York, Inc. BSpp. 26048 001 24X Fiche 50-000.84/09/06.8408010333 85pp
- 8408010337 & Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Moet Efficiency Requirement " Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 26067 138 24X Fiche 50-000, 84/08/06, 8408010337
- 8408070120 It Info Notice 84-61, "Giver exposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 500103) 84/08/08 Consolidated Edison Co. of New York, Inc. 120pp 26127 118 24% Fiche 50-000,84/08/08,8408070120
- 8408070376 IE Info Notice 84-68, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc BING UNION OF CA. Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24x Fiche 50-000,84/08/10,8408070376
- 8408100009 IC Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Ficae 50-000,84/08/13,8408100009

- 8408100038 IE Info Notice 84-64. "BWR HPC] Initiation Scal-In & Indication ' Svc list enci UCRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 247 Fiche 50-000.64/08/15,8408100038
- 8408100021 IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Syc 11st enc! JORDAN, E.L. Division of Emergency Proparedness & Engineering Response (Post 830103) 847081/16 Consolidated Edison Co of New York, Inc. (188p) 26198 001 24X Fiche 50-000.847081/16.8408100021
- 8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list oncl JORDAN,C L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- 8408280245 Ack receipt of 840731 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-220/80-11 MARTIN T Division of Engineering & Technical Programs 84/08/20 HOUTEN.8 G Niagara Mohawk Power Corp 2pp 26262 001 24x Fiche 50-220,84/08/20,8408280245
- --B408280248 Responds to NRC ltr re violations noted in Insp Rept 50-220/80-11 Corrective actions addl supervisory & technical personnel added to radiation protection organization & respiratory protective equipment procedures revised LEMPOES.T E Niagara Mohauk Power Corp 84/07/31 MURLEY.T E Region 1. Office of Director 5pp 26262 003 24% Fiche 50-220.84/08/20.8408280245
- 8408210142 IC Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JURDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc. 115pp 26029 008 24X Fiche 50-000.84/08/21,8408210142
- R Periodic operating reports & related correspondence
- 8408020115 Forwards revised rept of operating experience of monthly operating rept for Jul 1983
  LEMPOES.T E Niagara Mohawk Power Corp 84/07/26 Director's Office, Office of Inspection and Enforcement 2pp 25892 264 24x Fiche 50-220.84/07/26.8408020115
- --8408020119 Revised operating experience reptimenthly operating rept for Jul 1983 ROMAN.T W Niagara Mohawk Power Corp 83/07/31 4pp 25892 266 24X Fiche 50-220,84/07/26,8408020115
- S Reportable occurrences, LEAs & related correspondence
- 8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger initially reported on 840413 New thread locking devices investigated SHERWOOD. O Oeneral Electric Co 84/04/13 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000.84/04/13.8408240348
- 8408030201 LER 84-011-00 on 840603, scram occurred when reactor mode switch changed to shutdown Caused by improper connection on reactor protection sys (RPS) Channel 11 RPS channel removed & checked W/840702 ltr
  RANDALLR, LEMPGES T E Niagara Mohawk Power Corp 84/07/02 3pp 25917 119 24X Fiche 50-220.84/07/02,8408030201
- 8408080259 LER 84-013-01 on 840614, during testing three main steam line solenoid actuated rolief valves failed Two valves stuck open Caused by seat leakage Maint performed On 840617, three valves leaked again W/840727 ltr
  RANDALL-R . LEMPGES. T E Niagara Mohawk Power Corp 84/07/27 4pp 25974 337 24X Fiche 50-220,84/07/R7,8408080259
- 8408080483 LER 84-014-01 on 840617, during startup & re-testing of main steam line solenoid-actuated relief valves, one valve stuck open & three indicated seat leakage Reactor shut down & maint performed All valves operable on 840622 W/840727 ltr RANDALL,R, LEMPGES,T E Niagara Mohauk Power Corp 84/07/27 4pp 25975 181 24X Fiche 50-220,84/07/27,8408080483
- B40B200535 LER B4-009-00, on B40713, loss of plant process computer caused each Acurez channel to become inoperable Channels disconnected from computer & manually restored to operable status Software changed to avoid future error W/B40B13 ltr RANDALLR, MANDAN, C V Niagara Mohauk Power Corp 84/08/13 Spp 26139:024 24X Fiche 50-220, B4/08/13, B40B200535

- 8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memb of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl OE lacks technical info to adequately evaluate condition VILLA.R General Electric Co 84/08/21 RDSSI.C E Director's Office Office of Inspection and Enforcement Jpp 26318 327 24X Fiche 50-000.84/08/21.8408310186
- X Onsite Storage of Low Level Waste
- 8408230237 Forwards certificate re pollution control facilities for NRC signature per Internal Revenue Svc requirements Info re radwaste solidification & storage bldg, radioactive solid waste & spent fuel storage encl for approval MANGAN, C V Niagara Mohawk Power Corp 84/08/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 86207 278 24X Fiche 50-220,84/08/21,8408230237
- DOCKET 50-223 UNIV OF LOWELL RESEARCH REACTOR
- P Operating license stage documents & correspondence
- 8408060369 Informs of expiration of License R-125 on 850420 & outlines procedures for preparing renewal application Copy of Univ of Virginia renewal application encl for guidance THOMAB.C D Standardization & Special Projects Branch 84/07/30 BEGMIAN.L Lowell, Univ of, Lowell, MA 5pp 25951 238 24X Fiche 50-223,84/07/30,8408060369
- DOCKET 50-225 RPI CRITICAL EXPERIMENT
- F Security, medical, emergency & fire protection plans
- B40B070097 Forwards request for add1 info re B40206 proposed revised emergency plan, per 100FR50.App & requirements, Rev i to Reg Guide 2 & & ANBL/ANB-15 16-1982 Response requested within 40 days of 1tr receipt
  THDMAS.C D Standardization & Special Projects Branch B4/07/30 HARRIS, D R Renselaer Polytechnic Institute, Trey, NY 29955 241 24X Fiche 50-225,84/07/30,8408070097
- DOCKET 90-237 DREADEN NUCLEAR POWER STATION, UNIT 2

  F. Security, medical, emergency & fire protection plans
- B4D4040169 Forwards exercise repts for LaBalle & Dresden offsite radiological emergency preparedness exercises conducted B2O414-15 & O629-30, respectively KRIMM, R W Federal Emergency Management Agency 84/03/26 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 22883 122 24% Fiche 30-000, 84/03/26, 8404040169
- 840Bi40137 Forwards listed revs to security plans Revs address fence height requirements Revs withheld (ref 10CFR73 21) FARRAR, D.L. Commonwealth Edison Co. 84/08/03 Region 3, Office of Director ip 26044 232 24X Fiche 50-000,84/08/03,840Bi40I39
- 840Bi30401 Responds to 840705 clarification of info re util means of satisfying annual regulatory requirement to review emergency action levels w/offsite emergency support organizations Info acceptable PAPERIELLO.C J Region 3, Office of Director 84/08/07 REED, C Commonwealth Edison Co in 26010 130 24X Fiche 50-000,84/08/07,040Bi30401
- --B40Bi304i3 Responds to B40604 ltr re means for satisfying requirements of 10CFR50. App E. Paragraph IV II Proposal for satisfying requirements to review emergency action levels by offsite agencies clarified FARRAR. D L. Commonwealth Edison Co. B4/07/05 PAPERIELLO. C J. Region 3. Office of Director Bp. 26010 131 24X Fiche 50-000.84/08/07.840Bi30401
- B40Bi30289 Forwards FR notice of environ assessment & finding of no significant impact re 840405 & 26 requests for exemption of state & local govt participation in 840605 exercise PAULSBONN A Operating Reactors Branch 5. 84/08/10 FARRAR, D L Commonwealth Edison Co 2pp 26010 262 24% Fiche 50-010, 84/08/10, 8408130289
- --840Bi30298 Notice of environ assessment & finding of no significant impact re examption from requirements of iOCFR50. App E re state & local govt participation at 840605 exercise EISENHUT.D.O. Division of Licensing 84/08/10 4pp 26010 264 24X Fiche 50-010,84/08/10.840BI30289

- 140397 Forwards summary of App R reservitication methodology buts, per 840427 commitment to submit results of hot judown portion of fire protection program independent view W/28 oversize drawings Aperture cards in PDR RRAR D L Commonwealth Edison Co. 84/08/10 DEHTON, H R Office Nuclear Reactor Regulation, Director 222pp 24049-079 24(che 50-237,84/08/10,8408140397
- 200281 Advises that 840803 Rev 15 to physical security plan neistent 4/provisions of 10CFR50 54(p) & acceptable ELSON, M L. Region 3. Office of Director 84/09/14 FARRAR, D L. monowealth Edison Co. 2pp. 26193-023 24X Fithe 50-010,84/08/14.08200281
- 108210005 Exemption from Section IV F 1 of App E to 10CFR50 requiring full-scale emergency preparedness exercise at least annually involving participation of state & local govts uithin plume exposure pathway emergency planning ione EIBENHUT.D 0 Division of Licensing 84/08/14 Commonwealth Edison Co 3pp 26181 323 24X Fiche 50-010.84/08/14.8408210001
- 230283 Revised emergency plan implementing procedures, including PIP 100-C3 re generating station emergency plan log, placing record of generating station emergency plan tivities form M/E40920 ltr POTT, D J Commonwealth Edison Co B4/08/20 DENTON, H R Dffice Nuclear Reactor Regulation, Director 67pp 26207 295 24X che 50-010,84/08/20.8408230283
- Operating license stage documents & correspondence
- 8070099 Forwards Generic Ltr 84-13. "Tech Specs for Snubbers." mitted from 840503 ltr to all SEP licensees NRC position hat issue of Tech Specs for snubbers will be resolved on energy basis restated RUSCHFIELD, D. Assistant Director for Safety Assessment 84/07/3 AY, J.A. Yankee Atomic Electric Co. COUNSIL, W.G. Connecticut ankee Atomic Power Co. COUNSIL, W.G. Connecticut ankee Atomic Power Co. COUNSIL, W.G. Rortheast Nucleor Energy Co. subs. of Northeast Utilities). App. 25953-227. 24X
- B150113 Forwards reformatted Tech Specs improving legibility & ersatility, per request W/o encl
  YBAK.8 Commonwealth Edison Co. 84/08/01 DENTON.H R. Office of uclear Regulation, Director ip 26066-351 24x
  iche 50-237.84/08/01.8408150113
- BO60276 Forwards revised Tech Spec changes to Licenses DPR-19 & PR-25, submitted on 84061) Tech Specs revised Into new ormat, incorporating NRC comments w/o changing technical ontent Ontent YBAK, B Commonwealth Edison Co 84/08/02 DENTIN, H R Dffice of Ucclear Reactor Regulation, Director 3pp 25939 223 24% iche 50-237,84/08/02,8408060276
- |408060280 Proposed Tech Specs,revising format to incorporate NRC comments w/o changing technical content \* Commonwealth Edison Co 84/08/02 30pp 25933 226 24X Fiche 50-237,84/08/02,8408040276
- IBO70110 Generic Ltr 84-19 to all licensees of operating reactors, ipplicants for OLs & holders of CPs re availability of uppl 1 to NUREO-0793, "Prioritization of Generic Safety ssues " Svc last encl IBENRUF.D & Division of Licensing 84/08/06 Consolidated dison Co of New York, Inc 18pp 26129 238 24X iche 50-000,84/08/06,8408070110
- IBO90317 Forwards monthly status rept re plant-specific backfitting ctivities for operating reactors & license applicants for ul 1994 REMBLAY.P P Operating Reactors Assessment Branch B4/08/06/10LAHAN.O M Operating Reactors Assessment Branch 13pp 24X Fiche 50-000.84/08/06,8408090317

- 8409160062 Forwards Amends 82 ? 7" to licenses DPR-19 ; DPR-25 respectively Amends consist or reformatted Tech Specs to provide clarity PAUSONINA Operating Reactors Branch 5 84/08/06 FARRAR B L Commonwealth Edison Co 3pp 2609P 189 24% fiche 50-237,84/08/06,8408160062
- --B408160070 Amends B2 ½ 75 to Licenses DPR-19 ½ DPR-25, respectively, consisting of reforma+ted Tech Specs PAUL50N, M A Openating Reacture Branch 5 84/08/06 500pp 26092 192 24X Fiche 50-237,84/08/06,8408160062
- 8408160345 Advises that GA program applicable to all nuclear generating stations 5 satisfies provisions of 10CFR71 Fee remitted per 10CFR170 31 FARRAR.D L. Commonwealth Edison Co. 84/08/06 Office of Nuclear Material Safety & Safeguards.Director 1p 26072 184 24X Fiche 50-000.84/08/06.8408160345
- B408170017 Notifies of Class 1 t 11 tees due for 840611 Tech Spoc change request Fee will be adjusted if appropriate D1955.R H License Fee Management Branch 84/08/10 fARRAR.D C Componuealth Edison Co ip 26135 344 24X Fiche 50-237.84/08/10. 8408170017
- B408270114 Provides supplemental response to Generic Lt: 83-36.
  "NNR60-073/ Tech Specs" Mods to Quad Cities radiological
  ETS will not be complete until Fall 1984 Complete response
  u/amend requests expected by 841115
  ALEYANDER, G L Commonwealth Edison Co 84/09/15 DENTON, H R
  Office of Nuclear Reactor Regulation. Director 2pp 26247-330
  24X Fiche 50-000,84/09/15,8409270114
- B4082002/5 Generic Ltr 84-20 to all licensees of operating reactors to applicants for CLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENNUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24x Fiche 50-000.84/08/20.8408200275
- 8408310211 forwards final response to second 5 final set of questions re Mark I containment plant-unique ahalysis RYBAK B Commonwealth Edison (o B4/08/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 97pp 26318 072 24x Fiche 50-000.04/08/24.8408310211
- B408300102 Forwards corrected pages to 840806 Amends 82 % 75 to Liconses DRR-19 & DRR-29, respectively PAULS0N.4 A Derasting Reactors Branch 5 84/08/27 FARRAR D L Commonwealth Edison Co 2pp 26306 135 24X Fithe 50-237.84/08/27.
- --8408300111 Corrected pages to Amends 82 & 75 to Licenses DPR 19 & DPR 25.respectively PAULSDRLW A Operating Reactors Dranch 5 84/08/2/ 3pp 24/364 13/ 24X Fiche 50-237.84/08/27,8408300102
- O Inspection reports: IS Bulletine & Correspondence
- B408030291 Ack receipt of B40622 ltr informing NRC of stops taken to correct violations noted in 1E lnsp Repts 50-010/B4-05, 50-23/704-07 & 50-23/704-06 PAPERIELLO.C J Region 3, Office of Director B4/07/10 REFD.C Commonwealth Edison Co ip 25917 226 24X Fiche 50-010.84/07/10, 8408030291
- --8408030252 Responds to NRC 840524 itr re violations noted in 15 Insp. Repts 30-010/84-05.50-23/84-07 & 50-249/84-06 Corrective actions sludge romoved from Taledo & Joliet Pacilities Survey of Sumps found no residual activity FARRARIO L. Componwealth Edison Co. 84/06/22 ReppleR.J G. Region 3. Office of Director 4pp 25917 227 24X Fichs 50-010.84/07/10.8408030251
- B40725029 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Rolated Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN,C | Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc. 119pp 25865 047 24X Fiche 50-000-84/07/27, 8407250229
- B408070066 Notifies of B40823 meeting w/util at Region III oft to review findings of BALP assessment re util performance Encourages mgt representation to ensure mutual understanding of issues & findings presented by NRC NORELIUS.C E. Region 3. Office of Director 84/QB/03 REED.C Communumealth Edison Co. 2pp. 25749 337 24x Fiche 50-000.84/08/03.84080/0066

- 8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re-noncompliance found during inspirative december of the structured form will be used rather than ltr

  KEPPLER. J G Region 3, Office of Director 84/08/03

  Commonwealth Edison Co 3pp 25942 180 24% Fishe 50-000,84/08/03,84/98/07/401
- B408010333 IE Info Notice 84-59, 'Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JURDAN E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/08/06 Consolidated Edison Co of Net York, Inc 85pp 26068 001 24X Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement' Svc list enci JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 26067-158 24x Fiche 50-000,84/08,06,8408010337
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PUR Refueling Cavity " Svc list and! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York, Inc. 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- 8408140344 Confirms 840803 plans to meet w/wtil on 840907 in Glen Ellyn, IL to discuss regulatory improvement program NORELIUS, C.E. Region 3, Office of Director 84/08/08 REED, C. Commonwealth Edison Co. 2pp. 26041 050 24% Fiche 50-000, 84/08/08, 8408140244
- 8408150098 Suppls 840711 response to IC Bulletin 84-02 re visual insp during monthly functional tests to verify proper contact on reactor trip sys & primary containment isolation sys relays Exemptions requested for listed relays ALEXANDER, 0 L. Commonwealth Edison Co. 84/08/08 KEPPLER, J.G. Region 3. Office of Director. 3pp. 2606/ 053 24X Fiche 50-000,84/08/08,8408150098
- B408200331 Supple response to IE Bulletin B4-02 re failure of GE Type HFA relays Exemption requested from commitment for visual insp verifying proper relay contact during monthly functional check for listed relays ALEXANDER.G L Commonwealth Edison Co 84/08/08 KEPPLER, J G Region 3, Office of Director 3pp 26132 318 24% Fiche 50-000,84/08/08.8408200331
- B408300095 Forwards Insp Repts 50-010/84-10, 50-237/84-12 & 50-249/84-11 on 840618-0726 & notice of violation SHAFER, U Region 3, Office of Director 84/08/08 RCED, C Commonwealth Edison Co 2pp 264307 201 84/08/08 RCED, C 24X Fiche 50-010,84/08/08,840830095
- --8408300099 Notice of violation from insp on 840818-0/26 SMAFER.W D Region 3. Office of Director 84/08/08 ip 26307 203 24% Fiche 50-010.84/08/08.8408300095
- --B40B30010B Insp Repts 50-010/B4-10.50-237/B4-12 & 50-249/B4-11 on 840618-0726 Noncompliance noted inadequate corrective action taken in response to Tech Spec violation re-open submarine door in Unit 2 reactor bldg TONOUL:T M , STASEK:S , ANDERSON.C D Region 3, Office of Director 84/08/07 lipp 26307 204 24X Fiche 30-010.84/08/08, B40B300095
- B408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Ca-60 Toletherapy Treatments " Svc list encl ORACE.J N Division of QA, Safeguards & Inspection Programs (Post B30103) B4/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376
- B40B160139 Ack receipt of B40730 ltr informing NRC of steps taken to correct noncompliance noted in IF Insp Repts 50-010/B4-09, 50-237/84-11 & 50-247/84-10 BHAFER, W D Region 3, Office of Director B4/08/10 REED, C Commonwealth Edison Co Ip 26092 040 24X Fichs 50-010, 84/08/10, 8408160139
- --8408160145 Responds to NRC 840703 ltr re noncompliance noted in IE losp Repts 50-010/β4-09,50-237/β4-11 & 50-249/β4-10 Corrective actions special procedure for testing automatic function of master pilot valve incorporated into existing Cardox sys FARRAR, D L. Commonwealth Edison Co 84/07/30 KEPPLER, J Q Region 3. Office of Director 3ρp 26092 041 24X Fiche 50-010,84/08/10,8408160139
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping"
  Svc list encl
  JURDANNE L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000.84/08/13.8408100009

- 8408100038 IE Infg Notice 84-64, "BUR MPC1 Initiation Seal-In & Indication ' Sec list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co. of New York, Inc. 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038
- 8408100021 IE Info Notice 81-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN.E L Division of Emergency Proparadness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York. Inc 118pp 26198 001 24% Fiche 55-000.64/08/16.8408100021
- 8408100055 IE Info Notice 84-66. 'Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list enc! JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Post B30103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 001 24X Fiche 50-000 84/08/17, 8408100055
- 8408140208 IC Info Notice 84-67. "Recent Shubber Inservice Testing W/ High Failure Rates " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000.84/08/17.8408140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solonoid Valves " Svc list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26327 008 24X Fiche 50-000,84/08/21,8408210142
- R Periodic operating reports & related correspondence
- 8408300368 "Rept of Radioactive Effluents," Jan-June 1784 W/840815 itr SCOTT.D J Commonwealth Edison Co 84/06/30 KEPPLER.J G Region J. Office of Director 17pp 26308 1/2 24x Fiche 30-010.84/06/30. 8408300368
- 8408130271 Monthly operating repts for Jul 1984 W/B40803 ltr 8CHR0EDER,8 A . SCOTT.D J Commonwealth Edison Co 84/07/31 20pp 26006 342 24X Fiche 50-237.84/07/31.8408130271
- S Reportable occurrences, LERs & related correspondence
- 8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit acram pilot solemoid valve plunger Initially reported on 840413 New thread locking devices investigated SHERMODD, G G General Electric Co 84/04/13 DEVDVNG, R C Director's Office. Office of Inspection and Enforcement 3pp 24282 256 24% Fiche 50-000,84/04/13.8408240348
- 8408130330 LER 84-012-00 on 840707 reactor scrammed Caused by instrument mechanic mistakenly turning reactor protective sys Channel B instead of Channel A hydrogen addition switch to sef M/840807 ltr WDJTULEWICZ.T., SCOTT.D J Commonwealth Edison Co 84/07/17 3p. 26010 325 24% Fiche 50-237.84/07/17, 8408130330
- B408060100 LCR 84-010-00 on 840626 during startup feeder breaker position in control room lost on breaker at bus 27 which feeds MCC 28-7 & 29-7 Breaker inadvertently tripped Caused by loose wire Operator training conducted W/B40724 ltr BERGAN 0 W . SCOTT.D J Commonwealth Edison Co 84/07/24 4pp 25936 024 24X Fiche 50-237.84/07/24.8408060100
- 8408060203 LER 84-007-00 on 840628, during hot standby, fuse 2330-702 removed causing loss of automatic control for LPCI/component couling water sys HX delta p Caused by wiring sys using same fuse circuits W/840725 ltr COYLE.L. SCOTT, L. Commonwealth Edison Co 84/07/25 3pp 25935 197 24% Fiche 30-237.84/07/25,84080608203
- 8408040293 LER 84-011-00 on 840705, several mechanical penetrations found not smalled Fire watch established Penetrations smalled w/cerafiber & vimasco W/840726 ltr MERRITT.5 , SGOTT.0 J Commonwealth Edison Co 84/07/26 3pp 25736 083 24X Fichs 50-237, 84/07/26, 8408060273
- 8408090052 LER 84-015-00 on 840627 during startup operation time pumpdown of drywell equipment & floor drain sumps not performed at proper time Personnel involved given addl training W/840802 ltr Shiftle L. SCOTT.D.J. Commonwealth Edison Co 84/08/02 3pp 25992 136 24% Fiche 50-237,84/08/02,8408090052
- 8408090151 LER 84-014-00, on 840109, during normal operations, HPCI Turbine Trip Low Pressure Surveillance DIS 2300-3 performed late Caused by personnel error Addl training provided M/840802 ltr BMITH, G.L., SCDTT, D.J. Commonwealth Edison Co. 84/08/02 3pp 25993 191 24X Fiche 50-237, 84/08/02, 8408090151

- 408310067 LER 84-006-01 on 840208.east LPC; corner room submarine door to torus basement open & unattended Caused by personnel error Personnel retrained W/840809 ltr
  LEAHY, M. SCOTT, D. J. Commonwealth Edison Co. 84/08/09 4pp
  26034 345 24x Fithe 50-237,84/08/07,8408310067
- 408310063 LER 84-009-01 on 840530, during fire protection Tech Spec audit lack of Cardox sys master valve test in automatic mode noted Surveillance procedure revised to test valve in both manual & automatic nodes W/840813 ltr
  HERRITTS , SCOTT D J Commonwealth Edison Co 84/08/13 4pp 26334 352 24x Fiche 50-237,84/08/13,8408310063
- 1408240218 LER 84-013-00 on 840722.flow bypats valve FV-1 of electro hydraulic control sys opened causing turbine trip & reactor scram Gaused by personnel error Investigation committee convened to review event H/840817 ltr COYLE.L. 800TT.D J Commonwealth Edison Co 84/08/15 3pp 26236 297 24x Fiche 50-237.84/08/15,8408240218
- 3408230077 Summary of 840837 operating reactor events meeting re occurrences since 840719 meeting List of attendees, significant algoents & status of previous assignments encl CRUTCHFIGLD.D Assistant Director for Safety Assessment 84/08/16 EISENHUT.D © Division of Licensing 20pp 26233 249 24X Fiche 50-000,84/08/16.8408230077
- B40B310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840B20 telcon reporting equipment quality & separation of controls to butterfly values encl GE lacks technical info to adequately evaluate condition
  VILLA: General Electric Co 84/08/21 RDS8I.C E Director's
  Office, Office of Inspection and Enforcement 3pp 26318 327 24)
  Fiche 50-000.84/08/21.840B310386
- V Operator Examinations
- 8408140372 Forwards proposed new to "Requalification Program for Licensed Operators Senior Operators & Senior Operators (Limited)," in response to NUREO-0737, Item I A 3 i MARSHALL, J G Commonwealth Edison Co 94/08/07 DENTON. H R Office of Nuclear Reactor Regulation, Director 2pp 26051 240 24% Fiche 50-000,84/08/07,8408140372
- ---8408140387 "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited) "

  + Commonwealth Edison Co 84/07/19 10pp 26051 242 24X Fiche 30-000, 84/08/07, 8408140372
- 8408140424 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners MALKER, R O Region 3. Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26031
- DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1
  F. Security, medical, emergency & fire protection plans
- 8408100043 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/84-08
  MARTIN'T T Division of Engineering & Technical Programs 84/08/03
  KDSER'R W Rochester Oas & Electric Corp ip 25990 191 24X
  Fiche 50-244.84/08/03.8408100043
- --8408100056 Responds to NRC B40621 ltr reviolations noted in lE Insp. Rept 50-244/84-08 Corrective actions Procedure SC-600 reviewed & revised to require individuals be retrained annually in emergency response function KOBER.R W Rochester Oas & Electric Corp. 84/07/20 MARTIN,T T Division of Engineering & Technical Programs App. 25990 192 24X Fiche 50-244,84/08/03.8408100043
- 8408080029 Notification of 840813 meeting w/util in Bethesda.MD to discuss util alternative safe shutdown sys proposal DICK-8 F Operating Reactors Branch 5 84/08/06 PAULSON.W A Operating Reactors Branch 5 3pp 85962 003 24X Fiche 50-244.84/08/06.8408080029
- 8408140161 Forwards Rev O to "Nuclear Emergency Response Plan:"
  incorporating offsite & onsite plans & responding to mode
  recommended in IE Insp Rept 50-244/83-25
  KOBER.R W Rochester Gas & Electric Corp 84/09/09 MURLEY.T E
  Region 1, Office of Director Ip 26045 026 24X
  Fithe 50-244.84/08/09.8408140161
- --8408140167 Rev O to "Nuclear Emergency Response Plan "
  \* Rothester Gas & Electric Corp B4/07/31 178pp 26045 027
  24X Fiche 50-244,84/98/07,8408140161

- B40B270252 Revised emergency plan implementing procedures, including SC-100 re event evaluation/classification. SC-200 re emergency response organization/responsibilities. SC-212 re site evacuation & SC-420 re offsite doses W/B40B22 ltr e Rochester Gas & Electric Corp. 84/0B/22 MURLEY. T. E. Region i. Office of Director. 131pp. 26238 151 24% Fiche 50-244, 84/0B/22, 840B270252
- 8408300027 Summary of 8408[3 meeting w/util re 840ii6 submittal revising proposals for fire protection mode Util described changes to fire hazards analysis & new info Agenda & list of attendees encl DICK, O F Operating Reactors Branch 5 84/08/27 Operating Reactors Branch 5 4pp 26305 185 24X Fiche 50-244,84/08/27,8408300027
- G Adjudicatory correspondence
- 8408070420 Motion to terminate proceeding based on ML Slade 840724 withdrawal of outstanding contentions No contentions romain to be heard or decided Proceeding should be terminated Cortificate of Svc encl VDIGT.H H Rochester Gas & Electric Corp VDIGT.H H LeBoeuf. Lamb. Leiby & MacRae DSB 788 B4/08/03 Atomic Safety and Licensing Board Panel Spp 25742 028 24X Fiche 50-244.84/08/03,8408070420
- B408150133 Status rept re discovery record & suggested schedule for prehearing & hearing activities/per ASLB 840525 memorandum & order Staff will not pursue discovery Certificate of Svc encl Related correspondence YOUNG
- B40B200507 Informs that as result of ML Slade B40724 motion withdrawing outstanding contentions, applicant believes schedule for further proceeding no longer appropriate Related correspondence VOIGT. H Legoevf. Lamb. Leiby & MacRae VOIGT. H Rochester Gas & Electric Corp. DBB 151 B4/08/15 GROSSMAN. H, COLE.R F, LUEBKE.C A Atomic Safety and Licensing Board Panel 2pp 26/136 338 24x Fiche 50-244. B4/08/15, B40B200507
- J Insurance & indomnity information
- B40B190129 Forwards Endorsements 98 & 83 to NELIA Policy NF-170 & MAELU Policy NF-47, respectively GOLDEN, N P Marsh & McLennan, Inc B4/08/10 SALTZMAN, J D Assistant Director for State & Licensee Relations 3pp 26064 355 24Y Fiche 50-244, 84/08/10, 8408150129
- O Advisory Committee on Reactor Bafeguards reports & correspondence
- E408020250 Proposed minutes of ACRB Extreme External Phenomena 840404 meeting in Mashington.DC re review of generic methodology for developing design basis severe winds for SEP plants & specific applications for Ginna Nuclear Power Plant \* ACRB Advisory Committee on Reactor Safeguards 84/05/17 ACRB Advisory Committee on Reactor Safeguards 25pp 25878 120 24X Fiche 50-244.84/05/17,8408020250
- P Operating license stage documents & correspondence
- 8408070524 Forwards "Startup Physics Testing Program," per Tech Spec 6 9 i 1.as result of installation of 20 Westinghouse optimized fuel assembliss into Cycle 14 loading pattern for 1984 KDBER, R W Rochester Oas & Electric Corp 84/07/09 MURLEY, T E Region 1. Office of Director 1p 25953 033 24X Fich 50-244:84/07/09.8408070524
- --8408070526 "Startup Physics Testing Program"
  \* Rochester Gas & Electric Corp 84/06/26 4pp 25953 034 24x
  Fichs 50-244,84/07/09,8408070524
- 8408090275 Forwards notice of consideration of issuance of amend to License DPR-18 & proposed NBHC determination & opportunity for hearing re-proposed increase in Spent fuel pool storage capacity PAULBON, WA Operating Reactors Branch 5 84/07/24 KOBER, R W Rochester Gas & Electric Corp 2pp 25994 184 24X Fichs 30-244, 84/07/24, 8408090275
- --8408090281 Notice of consideration of issuance of amend to License DPR-18 & proposed NBMC determination to opportunity for hearing on util 840402 & 0612 requests re spent fuel pool storage expansion
  PAUL880N.W A Operating Reactors Branch 5 84/07/24 15pp 25974 186 24X Fichs, 50-244,84/07/24,8408090275

- 8408070099 Forwards Generic Ltr 84-i3, "Tech Specs for Snubbers," omitted from 840503 ltr ta all SEP licensees NRC position that issue of Tech Specs for snubbers will be resolved on generic basis restated CRUTCHFIELD, D Assistant Director for Safety Assessment 84/07/31 KAY, J A Vankee Atomic Electric Co KOBER, R N Rochester Oas & Electric Corp BASKIN, X P Southern California Edison Co 4pp 25995 227 24X Fiche 50-000.84/07/31.8408070099
- 8408070248 Forwards application for withholding & nonproprietary & proprietary versions of revised DNBR licensing basis for steam break analysis at roduced pressure W/o nonproprietary version Encl withheld (ref 10CFR2 790)
  KOBER.R W Rochester Gas & Electric Corp 84/07/31 PAULSON.W A Operating Reactors Branch 5 2p 25948 110 24X
  Fiche 50-244.84/07/31.8408070248
- ---8408070257 Requests withholding of proprietary revised DNBR licensing basis for steam break analysis at reduced pressure Encl withheld (ref 10CFR2 790)
  WIESEMANN.R A Westinghouse Electric Corp 84/07/20
  CRUTCHF[ELD,D] Operating Reactors Branch 5 11pp 25948 112
  24X Fiche 50-244,84/07/31,8408070248
- 8408070251 Forwards Amund 62 to License DPR-18 & safety evaluation Amend revises Toch Specs to limit working hours of staff performing safety-related functions & provides for reporting valve failures PAULSON, W. A. Operating Reactors Branch 5 84/07/31 KOBER, R. W. Rochester Øas & Electric Corp. 4pp. 25948 089 24X Fiche 50-244,84/07/31,8408070251
- --8408070255 Amend 62 to License DPR-18, revising Tech Specs to limit working hours of staff performing safety-related functions & providing for reporting of safety & relief valve failures & challengos
  PAULSON,W A Operating Reactors Branch 5 84/07/31 9pp 25948 087 24X Fiche 50-244,84/07/31,8408070291
- --8408070258 Safety evaluation supporting Amend 62 to License DPR-18 LAZARUS.W Region 1. Office of Director 84/07/31 Spp 25948 096 24X Fiche 50-244,84/07/31.8408070251
- 8408070315 Forwards "NUREO-0612. Control of Heavy Loads," final rept Bubmittal contains evaluation results & resolutions of open items since 840326 submittal KOBER,R W Rochester Gas & Electric Corp 84/07/31 PAULSON,W A Operating Reactors Branch 5 ip 25941 172 24X Fiche 50-244.84/07/31.8408070515
- --8408070516 "NUREG-0612, Control of Heavy Loads," final rept \* Rochester Gas & Electric Corp B4/08/31 12pp 25941 173 24X Fiche 50-244, 84/07/31, 8408070515
- 8408080091 Forwards responses to questions re 840402 application for amend to License DPR-18 Six proprietary oversize drawings encl Drawings withheld Aperture cards available in Central Files
  KOBER: R W Rochester Oas & Electric Corp 84/07/31 PAULSON, W A Operating Reactors Dranch 5 24pp 25961 037 24X
  Fiche 80-244.84/07/31.8408080091
- 8408090497 Summary of 840717 meeting w/Westinghouse Owners Steam Generator Tube Rupture Subgroup in Bethesda MD ra proposed steam generator tube rupture generic program List of attendees & viewgraphs encl SINOM B K Licensing Branch 3 84/07/31 Licensing Branch 3 18pp 25983 130 24X Fiche 50-000,84/07/31,8408090497
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Generic Bafety Issues " Svc list encl EISENHUT.D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26127 238 24X Fiche 50-000.84/08/06.8408070110
- 8408130357 Forwards response to 840604 request for add1 info re NUREO-0737.1tem II F 2 concerning inadequate core cooling instrumentation KOBER.R W Rochester Qas & Electric Corp 84/08/07 PAULSON.W A Operating Reactors Br
- 8408150108 Discusses encl results of analysis of Reactor Vessel Surveillance Capsule T. supporting 821208 application for amend to License DPR-18 Fluence data & analysis presented in MCAP-10085 verified ROBER.R W Rochester Oas & Electric Corp 84/08/08 PAULSDN.W / Operating Reactors Branch 5 12pp 26067 001 24X Fiche 50-244.84/08/08.8498150108

- 8408160482 Summary of 840724 meeting w/Westinghouse Owners Group reupper plenum injection for two loap plants
  DITANNI.D C Operating Reactors Branch 3 84/08/09 Operating
  Reactors Branch 3 4pp 26108 327 24X Fiche 50-000,84/08/09,
  8408160482
- 840B170047 Requests authorization to dispose of 70 tons low level radwaste in municipal landfill Matl from roofs of plant bldgs Average concentration of matl from auxiliary bldg 14 picocuries/g Annual dose equivalent i mrem KOBER.R W Rochester Oas & Electric Corp 84/08/10 PAULSON,W A Operating Reactors Branch 5 App 26117 085 24x Fichs 50-244,84/08/10,8408170047
- 8408170058 Forwards responses to NRC questions re 840402 application for amend to License DPR-18 All employees involved in spent fuel pool rerack mods will be required to complete radiation protection training program KOBER,R W Rochester Oas & Electric Corp 84/08/10 PAULSON,W A Operating Reactors Branch 5 16pp 26119 096 24X Fiche 50-244.84/08/10.8408170058
- 8408170168 Responds to 840609 submittal of Rev 9 to QA program Changes acceptable, except for Figure 2-1 ro organizational structure, which reflects proposed Amend 63 to Tech Specs MARTIN, T 7 Division of Engineering & Technical Programs 84/08/10 KDBER, W Rochester Oas & Electric Corp 2pp 26118 345 24X Fiche 50-244,84/08/10,8408170168
- 8408160353 Forwards Amend 63 to License DPR-18 & safety evaluation Amend approves Tech Spec changes to organization titles PAULBON.W A Operating Reactors Branch 5 84/08/14 KOHER.R W Rochester Gas & Electric Corp 3pp 26091 195 24X Fiche 50-244.84/08/14.8408160353
- --8408160356 Amend 63 to License DPR-18, revising Tech Space to consolidate positions of superintendent of nuclear production & superintendent of plant & to recognize organizational title changes within util organization PAULBON, WA Operating Reactors Branch 5 84/08/14 5pp 26091 198 24X Fiche 50-244,84/08/14,8408160352
- --8408160361 SER supporting Amend 63 to License DPR-18 \* Office of Nuclear Reactor Regulation, Director 84/08/14 3pp 26091 203 24% Fiche 50-244,84/08/14,8408160353
- B40B200279 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
  CISENHUT.D 0 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
  Fiche 50-000.84/08/20.8408200279
- G Inspection reports. IE Bulletins & correspondence
- 8408080233 Forwards IE Insp Rept 30-244/84-13 on 840514-18 & notice of violation MARTIN.T T Division of Engineering & Technical Programs 84/07/14 KOBER.R W Rochester Oas & Electric Corp 2pp 29773 OO1 24X Fiche 30-244.84/07/16.8408080233
- --8408080238 Notice of violation from insp on 8140514-18
  \* Region 1, Office of Director 84/07/16 1p 25975 003 243
  Fiche 50-244,84/07/16,8408080233
- --8408080242 IE Insp Rept 50-244/84-13 on 840514-18 Noncompliance opted failure to control access to Level D storage areas & failure of semiannual audits required by Tuch Epecs to include results of actions taken to correct deficiencies, NAPUDA:0, OLIVEIRA:N Region 1. Office of Director QCDY:A T Division of Engineering & Technical Programs 84/07/09 Epp 25975 004 24X Fiche 50-244,84/07/16,8408080233
- B40B030005 Ack receipt of B40629 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/B4-05 MARTIN.T T Division of Engineering & Technical Programs 84/07/26 KODER, R W Rechester Gas & Electric Corp 2pp 25906.019 24X Fiche 50-244.84/07/26.8408030005
- --8408030014 Responds to NRC 840611 ltr re violations noted in IE Insp Rept 50-244/84-05 Corrective actions procedures developed or revised to provide formalized method re additions to inservice insp gragram for modified sus & components KOBER, RW Rochester Oas & Electric Corp 84/06/27 MURLEY, T E Region 1. Office of Director 2pp 25906 021 24X Fiche 50-244,84/07/26.8408030005

- 8407250229 IE Info Notice 84-37, "Operating Experience to Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants "Svo List encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc. 119pp 25865-047 24x Fiche 50-000.84/07/27,8407250229
- 8408070198 Forwards response to 840612 request for add1 info re 831201 request for objection exemption from containment tendon visual insp requirements Individual tendon force levels provided KOBER: R W Rochester Gas & Electric Corp 84/07/31 PAULSON, W A Operating Reactors Branch 5 4pp 25950 021 24% Fiche 50-244,84/07/31,8408070198
- 8408070174 Ack receipt of 840727 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/84-02 MARTIN T T Division of Engineering & Technical Programs 84/08/08/08/RR W Rochester Gas & Electric Corp 2pp 25990 042 24X Fiche 50-244.84/08/02/8408070174
- --8408070178 Responds to NRC 840602 ltr re valations noted in IE Insp Rept 50-244/84-02 Corrective actions development of new procedure to cover use of air sampling devices will be completed prior to 840901 KOBER.R W Rochester Cas & Electric Corp 84/07/27 HARTIN.T T Division of Engineering & Technical Programs ip 25950 044 24x Fiche 50-244,84/08/02.8408070174
- 8408100022 Ack receipt of 840727 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/84-12
  MARTIN.T T Division of Engineering & Technical Programs 84/08/03
  KOSER, R W Rochester Gas & Electric Corp ip 25970 188 24V
  Fichs 50-244,84/08/03,8408100022
- --8408100032 Responds to NRC 840629 ltr re violations noted in IE insp Rept 50-244/84-12 Corrective actions procedure being developed to cover overall use of air samplers should be completed by 840901 KDBER.R W Rachester Oas & Electric Corp 84/07/27 MURLEY.T E Region 1. Office of Director 2pp 25970 189 24X Fiche 50-244,84/08/03,8408100022
- 840B100043 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in IE Insp Ropt 50-244/84-08
  MARTIN T T Division of Engineering & Technical Programs 84/08/03
  KDBER,R W Rochester Gas & Electric Corp 1p 25990 191 24X
  Fiche 50-244.84/08/03.8408100043
- --R40B100036 Responds to NRC 840421 itr re-violations noted in JE Insp Rept 50-244/84-08 Corrective actions Procedure SC-600 reviewed & revised to require individuals be retrained annually in emergency response function KUBER.R W. Acchester Oas & Electric Corp. 84/07/20 MARTIN, T.T. Division of Engineering & Technical Programs. 4pp. 25990-192 E4X Fiche 50-244.84/08/03.8408100043
- 8408010333 IE info Notice 84-59. "Deliberate Circumventing of Station Health Physics Prutedures " Svc list and JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 24048 001 24X Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Into Notice 84-61, "Dverexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fiche 50-000,84/08/08,8408070120
- B40B140161 Forwards Rev O to "Nuclear Emergency Response Plan." incorporating offsite & onsite plans & responding to mods recommended in IE Insp. Rept 50-244/83-25 KOBER N Rochester Cas & Electric Corp. B4/08/09 MURLEY, FC Ragion 1. Office of Director 1p. 26045 026 24X Ficha 50-244/84/08/09,8408140161
- 8408070376 IE Info Notice 84-42, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Bvc list enc! ORACE.J N Division of GA, Bafeguards & Inspection Programs (Post 930103) 84/08/10 Consolidated Edison Co of New York. Inc 95pp 26130 001 24X Fiche 50-000.84/08/10.8408070376

- 8408100007 IC Info Notice 84-63, "Detective RHR Replacement Piping "
  Svc list encl
  JORDAN.E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York Inc 119pp 26197 218 24% Fiche 50-000.84/08/13.8408100007
- 8408100038 IE Info Notice 84-64. BWR HPCI Initiation Seal-In & Indication Svc list encl URDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24% Fiche 50-000.84/08/15,8408100038
- 8408100021 IC Info Notice 84-65, "Underrated Fuses Which flay Adversely Affect Operation of Essential Electrical Equipment." Svc list encl URRDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26198 001 24X Fiche 50-000.84/08/16,8408100021
- 8408100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Tiain " Svc list encl URDAN:E L Division of Emergency Preparedness & Engineering Responsa (Post 830103) 84/08/17 Consolidated Edison Co of New York: Inc 120pp 26276 001 24X Fiche 50-000.84/08/17.8408100055
- 8408140208 IE Info Notice 84-67. "Recent Snubber Inservice lesting W/ High Failure Rates " Svc list encl JORDAN, E. L. Division of Emergency Pieparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 122pp 26276 122 24% Fiche 50-000.84/08/17,8408140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Responte (Post B30103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000.84/08/21,8408210142
- S Reportable occurrences, LERs & related correspondence
- 8408290112 LER 84-008-00 on 840725, isolation valves left in closed position & firewatch removed violating Tech Specs which requires continuous firewatch when Suppression systoporable Caused by miscommunication N/840824 ltm LARIZZA, 0 F. KOBER, R.W. Rochester Gas & Electric Corp. 84/08/24 3pp. 26291 248 24X Fiche 50-244,84/08/24,8408290112
- DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

  F. Security, medical, emergency & fire protection plans
- 8408010288 Forwards IE Insp Regts 50-245/84-13 & 50-336/84-13 on 840329-0601 & notice of violation MARTIN, T T Division of Engineering & Technical Programs 84/07/1: COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 25866 200 24X Fiche 50-245/84/07/11,8408010288
- --8408010290 Notice of violation from insp on 840529-0401 \* Region 1, Office of Director 84/07/11 1p 29866 202 24% Fiche 50-245,84/07/11.8408010288
- --8408010272 IE Insp Repts 50-245/84-13 & 50-336/84-13 on 840529-0601 Violations noted failure to adhere to Tech Spec 6 11 procedures for radiation work permit preparation NIMITZ.R L , SHANBAKY.M M Region 1. Office of Director 64/07/02 12pp 25866 203 24X Fiche 50-245.84/07/11.8408010288
- 8408080383 Forwards IE Insp Repts 50~245/84-11 & 50~336/84-12 on 640306~0609 & notice of violations Also ack receipt of 840308 itr informing NRC of steps taken to correct violation noted in IE Insp Rept 50~336/84-02 STAROSTICKI.R Division of Project & Resident Programs 84/07/20 CDUNSTI.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp 25775 021 24X Fiche 30-245,84/07/20,8408060353
- --8408080374 Notice of violation from insp on 840504-0607 Safeguards info deleted (ref 10CFR73 21) \* Region 1, Office of Director 84/07/20 ip 25975 025 24X Fiche 50-249,84/07/20,8408080353

- 8408150688 Forwards IE Safeguards Insp Repts 50-245/84-14 & 50-336/84 14 on 840604-03 No noncompliance noted Steps taken to correct violations discussed in 831107 & 16 ltrs verified
  - verified MARTIN.T T Division of Engineering & Technical Piograms 84/07/27 COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26079 001 24% Fiche 50-245,84/0//27,8408150688
- --8408150693 IE Safeguards Insp Repts 50-245/84-14 ½ 50-336/64-14 on 840604-08 No noncompliance noted Major areas inspected security program audit % organization, testing & maint ½ assessment aids Safeguards info deleted (ref 10CFR2 790) MADDEN,W. KEIMIG.R. R. Region 1. Office of Diroctor 84/07/26 4pp 26079 003 21x Fichs 50-245,84/07/27,8408150688
- 8408210494 Forwards IE Insp Repts 50-245/84-15 & 50-336/84-15 on 840611-15 & notices of violation & deviation MARTIN, T T Division of Engineering & Technical Programs 84/08/01 COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26187 145 24X Fiche 50-245.84/08/01.8408210494
- --B40B210501 IE Insp Repts 50-245/B4-15 & 50-336/B4-15 on 840611-15 Violations identified failure to perform surveillance testing per Tech Specs & to maintain integrity of fire barriers

  KRASDPOULOS, A., PULLANI, S. V., ANDERSON, C. J. Region 1, Office of Director B4/07/27 ip 26/87 149 24X Fiche 50-245, B4/08/01, B40B210494
- 8408160350 Forwards revised emergency plan implementation procedures, including CONI 1 02 re corporate organization for nuclear incidents 3 CONI 4 02 re on-call manager of radiological consequences assessment W/o encis COUNSIL. K 9 Northeast Utilities 84/08/13 Record Services Branch (Document Control Dosk) 2ppl 26091 193 24X Fiche 50-000.84/08/13.8408160390
- 8408280171 Responds to 840712 interpretation of order confirming licensee commitments on emergency capability, focusing on Suppl 1 to NURCO-0737 requirements Integrated assessment to be conducted pending Congressional consent EISENHUT.D G Division of Licensing 84/08/23 COUNSIL, W G Connecticut Yankee Atomic Power Co 3pp 26277 224 24X Fiche 50-000.84/08/23.8408280171
- 8408310187 Submits update to corrective actions taken re deficiencies noted during 840512 emergency preparedness exercise Emergency action level procedure revised to place greater emphasis on classification/reclassification of emergencies CDUNBIL.W G Connecticut Yankee Atomic Power Co COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W O Northeast Utilities 84/08/23 MURLEY.T E Region 1. Office of Director 3pp 26318 330 24X Fiche 50-000.84/08/23.

### H General correspondence

- 8408070321 Advises that K McCarthy should appear on license amends as appropriate state official to receive amend applications McCarthy new director of radiation control for State of CT. Dept of Environ Protection COUNSIL.W G Connecticut Yankee Atomic Power Co COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W O Northeast Utilities 84/07/27 MILLER, J. R Operating Reactors Branch 3 CRUTCH/TELD, D Operating Reactors Branch 5 ip 25945 128 24X Fiche 50-000.84/07/27, 8408070321
- P Operating license stage documents & correspondence
- 8408100102 Confirms info discussed during 840622 conference call replant-unique analysis rept Taledyne Engineering Svcs has done addl work re allowable multiplier which can be applied w/o exceeding allowable stress in torus shell COUNSIL.W 9 Northeast Huclear Energy Co (subs of Northeast Utilities) COUNSIL.W 9 Northeast Utilities 84/07/27 CRUICHFIELD.D Operating Reactors Branch 5 2pp 25990 275 24X Fiche 50-245.84/07/27.8408100102
- 840B010030 Forwards SER re containment hydrogen monitor (NUREG-0737, Item II F 1 6) Monitor meets all criteria of NUREG-073/ except requirement for redundancy Response requested within 30 days
  PAULSDN.W A Operating Reactors Branch 5 84/07/30 COUNSIL,W O
  - PAULSON.W A Operating Reactors Branch 5 84/07/30 COUNBIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 7pp 25855 326 R4X Fiche 50-R45,84/07/30,8408010030
- 8408070099 Forwards Generic Ltr 84-13, "Tech Specs for Shubbers," omitted from 840903 ltr to all SEP licensees NRC position that issue of Tech Specs for shubbers will be resolved on generate basis restated CRUTCHFIELD.D Assistant Director for Safety Assessment 84/07/31 KAY, J A Yankee Atomic Electric Co FARRAR.D L Commonwealth Edison Co VANDEWALLE.D J Consumers Power Co 4pp 25955 227, 24X Fiche 50-000,84/07/31,8408070099

- 840B070320 Ack receipt of B4060B ltr forwarding Rev 4 to GA program topical rept,per 10CFR50 54 & 50 55 Revs acceptable MARTIN.T T Division of Engineering & Technical Programs B4/0B/01 COUNSIL W G Connecticut Yankes Atomic Power Co 2pp 25945 244 24X Fiche 50-000.84/0B/01.8408070320
- B408070110 Generic Ltr B4-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl i to NUREO-0933. "Prioritization of Generic Safety Issues " Svc list enci EISENHUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000.84/08/06.8408070110
- B40B210306 Forwards requested info on TM1 Item I1 K 3 28 requalification of automatic depressurization system accumulators

  COUNSIL.W G Northeast Nuclear Energy Co (substantial Substitution of Northeast Utilities) COUNSIL.W G Northeast Utilities B4/08/13

  FAULSON.W A Operating Reactors Branch 5 5pp 26179 326 24X

  Fichs 50-245,84/08/13.0408210306
- 840B200190 Forwards SER on proposed resolution for integrated glant BAR (NUREG-0824).Bection 4 28 3 re gas turbine preventive maint program acceptable SHEA.J Operating Reactors Branch 5 84/08/16 COUNGIL, W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 26133 064 24X Fishe 50-245.84/08/16.840B200190
- 8408290278 Requests extension until 841214 to respond to Generic Ltr 84-15 re proposed staff actions to improve & maintain diesel generator reliability Addl time will result in more complete & concise submittal COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 84/08/17 EISEN.CUT.D G Division of Licensing 2pp 26290 342 24X Fiche 50-000, 84/08/17, 8408270278
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for DLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISCNHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24% Fiche 50-000.84/08/20.8408200275
- Q Inspection reports. IE Bulletins & correspondence
- B408010288 Forwards IE Insp Repts 50-249/84-13 & 50-336/84-13 on 840929-0601 & notice of violation MARTIN, I T Division of Engineering & Technical Programs B4/07/11 COUNSIL, N G Northeast Nuclear Energy Co (5085 of Northeast Utilities) 2pp 29866 200 24% Fichs 50-245,84/07/[1.8408010288
- --8408010290 Notice of violation from insp on 840529-0401 \* Region 1, Office of Director 84/07/11 1p 25866 202 24X Fiche 50-245, 84/07/11, 8408010288
- --8408010292 IE Insp Repts 50-245/84-13 & 50-336/84-13 on 840529-0601 Violations noted failure to adhere to Tech Spec & II procedures for radiation work permit preparation NIMIT.R L , SHANBAKY,M M Region 1, Qffice of Director 84/07/02 12pp 23866 203 24X Fiche 50-245.84/07/11.8408010288
- 8408080464 Forwards Exam Rept 50-245/84-17 of exam administered during wk of 840424
  STARDSTECKI, R Division of Project & Resident Programs 84/07/17 COUNBIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 25775 085 24X Fiche 30-245,84/07/17,8408080464
- --8408080466 Exam Rept 50-245/84-17 administered on 840424-26 Exam results four candidates passed & six failed BERRY, J A Region 1, Office of Director 84/06/22 70pp 85975 087 24% Fiche 30-245.84/07/17,8408080464
- 8408080353 Forwards IC Insp Repts 50-245/84-11 & 50-336/84-12 on 840506-0609 & notice of violations Also ack receipt of 840508 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-336/84-02 STAROBICCKI, R Division of Project & Resident Programs 84/07/20 CDUNBILLW 0 Northeast Nuclear Energy Co (subs. of Northeast Utilities) 3pp 25975 021 24X Fiche 50-245.84/07/20.8408080353
- --8408080383 Natice of violation from insp on 840506-0609 \* Region i, Office of Director 84/07/20 ip 25975 024 24% Fiche 50-245.84/07/20,8408080353
- --8408080394 Notice of violation from insp on 840505-0509 Safeguards info deleted (ref 105FR73 21) \* Region 1, Office of Director 84/07/20 1p 25975 025 24X Fiche 50-245,84/07/20,8408080353

MONTHLY TITLE LIST U. S. NUCLEAR REGULATORY COMMISSION

#### MONTHLY TITLE LIST U S NUCLEAR REGULATORY COMMISSION

84/08/01 - 84/08/31 PAGE

- --8408080403 IE Insp Repts 50-245/84-11 & 50-336/84-12 on 840506-0609 Violations noted failure to follow radiation protection procedures & fulfill station security plan commitments Safeguards info deleted SHEDLOSKY, J T. LIPINSKI, D R. Region 1, Office of Director ELSASSER, T C. Division of Project & Resident Programs 84/06/26 3pp 25975 026 24X Fiche 50-245,84/07/20,8408080353
- --B40B0B0414 Responds to NRC B40213 & 0409 itrs re violations noted in IE Insp Rapt 50-336/84-02 Corrective actions Instrument & Controls Procedure IC 2417M re design changes revised COUNSIL.W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W 0 Northeast Utilities B4/05/0B MURLEY.T E Region 1. Office of Director 5pp 25975 041 24X Fiche 50-245, 84/07/20, 8408080353
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Bafety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York Inc 119pp 25865 047 24X Fiche 50~000.84/07/27,8407250229
- 8408150698 forwards IE Bafeguards Insp Repts 50-245/64-14 & 50-336/84-14 on 840604-08 No noncompliance notes Steps taken to correct violations discussed in 831107 & 16 ltrs verified

  MARTIN.T T Division of Engineering & Technical Programs B4/07/2

  CDUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast

  Utilities) 2pp 26077 001 R4X Fiche 50-245.84/07/27.8408150688 B4/07/27
- --8408150693 IE Bafeguards Insp Repts 50-245/84-14 & 30-336/84-14 on 840604-08 No noncompliance noted Major areas inspected security program audit & organization, testing & maint & assessment aids Safeguards info deleted (ref 10CFR2 790) MADDEN.W. WEIMIG.R. Region 1. Office of Director 84/07/26 4pp 26079 003 24% Fiche 50-245.84/07/27,8408150688
- 8408100116 Responds to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc " Entry & engineering evaluation for Millstone Unit 2 will be done by Feb 1985 refueling outage No Ray Miller products supplied at Haddam COUNSIL, W @ Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W @ Connecticut Yankee Atomic Power Co COUNSIL, W @ Northeast Utilities 84/07/31 MURLEY, T E Reg Office of Director 3pp 25988 247 24X Fiche 30-000,84/07/3808100116 Region 1. 24X Fiche 50-000, B4/07/31,
- 8408160235 Forwards IE Insp Rept 50-245/84-16 on 840613-15 No violations observed MARTIN.T T Division of Engineering & Technical Programs 84/08/0 COUNSIL NG Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26106 214 24X Fiche 50-245/84/08/01/8408160235 84709701
- --8408160246 IE Insp Rept 50-245/84-16 on 840613-15 No violations observed Major areas inspected emergency diesel generator operation in area of prelube oil Seepage from exhaust flumes adjacent to turbacharger MCDMARD.C H. ANDERBON.C J. Region 1. Office of Director 84/07/18 4pp 26106-216 24X Fiche 50-245-84/08/01,8408160235
- 8408140428 Forwards IE Insp Rept 50-245/84-18 on 840616-22 No 40B16042B Forwards IE 110p her--violations observed
  WARTIN.T T Division of Engineering & Technical Programs B4/08/03
  HARTIN.T T Division of Engineering & Technical Programs B4/08/03
  COUNSIL.G W Northeast Nuclear Energy Co (subs of Northeast
  Utilities) 2pp 26129 103 24X Fiche 50-245.84/08/01.840B16042B
- --8408140432 It Insp Rept 50-245/84-18 on 840416-22 No violations observed Major areas inspected containment leakage testing program.local leak rate test.test results review & general towns of facility VITQ, D. J. LIPINGKI, D. R., BETTENHAUSEN, L. Region 1, Office of Director 64/07/18 9pp 26129 105 24X Fiche 50-245, 84/08/01, 8408160428
- 8408210494 Forwards IE Insp Repts 50-245/84-15 & 50-336/84-15 on 840611-15 & notices of violation & deviation MARTIN.T T Division of Engineering & Technical Programs 84/08/01 COUNBIL.W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26187 145 24X Fiche 50-245.84/08/01.8408210494
- --8408210495 Notice of violation from insp on 840611-15 \* Region 1. Office of Director 84/09/01 1p 26187 147 24X Fiche 50-245,84/08/01.8408210494
- --8408210496 Notice of deviation from insp on 840611-15 \* Region 1, Office of Director 84/08/01 1p 26187 I48 24X Fiche 50-245.84/08/01.8408210494

- --B40B210501 IE Insp Repts 50-245/84-15 % 50-336/84-15 on 840611-15 Violations identified failure to perform surveillance testing per Tech Specs % to maintain integrity of fire barriers KRASOFOULGS A , PULLANI, S V , ANDERSON, C J Region 1, Office of Director 84/07/27 ip 26187 149 24% Fichs 50-245,84/08/01,8408210494
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 85pp 26068 001 24% Fiche 50-000,84/08/06.8408010333
- 840B010337 IE Info Notice B4-60, "Failure of Ail Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post E30103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Natice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list enc! JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Cansolidated Edison Co 09) 84/08/08 Consolidated Edison Co. of New 26129 118 24% Fiche 50-000,84/08/08,8408070120 Yark Inc 120op
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Telethorapy Treatments " Svc list encl | Iist enc| | GRACE.J N | Division of QA, Bafeguards & Inspection Programs (Post 820103) | B4/08/10 | Consolidated Edison Co of New York, Inc. 129pp | 26130 001 | 24X Fiche 50-000.84/08/10.8408070376
- 8408210480 Responds to notice of violation in IE Insp Repts 50-213/83-25 & 30-245/84-07 Corrective actions taken to restore post-accident sampling sys units to svc & determine Problem G Connecticut Yankse Atomic Power Co COUNSIL. W G Connecticut Yankse Atomic Power Co COUNSIL. Northeast Nuclear Energy Co (subs of Northeast Utilities COUNSIL. W G Northeast Utilities B4/08/10 DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 26181 196 24X Fiche 50-000, B4/08/10, B408210480 CHUNSIL.W G
- 8408100009 IE Info Notice 84~63, "Defective RHR Replacement Piping " NORIDOUS IE INFO NOVICE 07-83, 20. The Committee of the Syc list encl
  JURDAN E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Cansolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fishe 50-000, 84/08/13, 8408100009
- B40B10003B IE Info Notice 84~64, "BWR HPCI Initiation Seal-In & Indication "Syc list encl JURBAN.E.L Division of Emergency Preparedness & Engineering Response (Post 200103) 84/08/15 Consolidated Edison Co of Now York, Inc 104pp 26198 093 24X Fiche 50-080,84/08/15,8408100038
- 840B100021 IE Info Notice 84~65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list entl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26198 001 244 Fiche 50-000,84/08/16,8408100021 list onel
- 8408100095 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co 26274 001 120pp 24X Fiche 50-000, 84/08/17, 8408100055
- 840B14020B IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates" Svc list encl JORDANAE L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/17 Consolidated Edison Co. of New 03) 84/08/17 Consolidated Edison Co of New 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84~68. "Potential Deficiency in Improperly Rated Field Wiring to Bolemoid Valves " Svc list encl JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc. 115pp 26329 008 24X Fiche 50~000.84/08/21.8408210142
- R Periodic operating reports & related correspondence
- 8408230431 Monthly operating rept for Jul 1984 W/840815 ltr HARRANIO: MRCCZKA.E J Northeast Nuclear Energy Co (subs Northeast Utilities) MRCCZKA.E J Northeast Utilities E 5pg 26213 068 24X Fichs 30-245,84707/31,8408230431 H4/07/31

- S Reportable occurrences. LERs & related correspondence
- B408220317 Part 21 rept re failure of ITE-27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diode must be added Affected units listed DUVALL.D D Brown Boveri Corp (subs of Brown Boveri & Co., Ltd.) B4/03/13 DEYDUNG, R.C. Director's Dffice, Dffice of Inspection and Enforcement 3pp 26191 357 24% Fiche 50-000.84/03/13.8408220317
- 8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated SHERWOOD, G General Electric Co 84/04/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000.84/04/13.8408240348
- 8408070112 LER 84-014-00 un 840709, isolation condenser containment isolation valve motor overloaded & 125-volt dc ground alarm annunciated in control room Caused by limit switch out of adjustment Breaker i-IC-3 replaced W/840727 ltr
  THULL, T S , MRCCZKA, E J Northeast Nuclear Energy Co (subs of Mrcheast Utilities) RRCCZKA, E J Northeast Utilities 84/07/2.
  2pp 25753 ii3 24X Fiche 50-245,84/07/27,8408070112
- 8408090340 LER 84-015-00 on 840709, isolation condenser containment isolation valve motor overloaded & 125-volt dc ground alarm annunciated in control room Caused by limit switch out of adjustment Breaker replaced & switch adjusted WR40731 ltr THULL, T S , HERBERT, R J Northeast Nuclear Energy Co (subs of Northeast Utilities) THULL. T S Northeast Utilities 84/07/30 2pp 25994 064 24% Fiche 50-245,84/07/30,8408090340
- 8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
  VILLA: R General Clectric Co 84/08/21 ROSSI.C E Director's
  Office. Office of Inspection and Enforcement 3pp 26318 327 24X
  Fiche 50-000.84/08/21,8408310186
- 8408290004 LER 84-017-00 on 840802, unidentified leak rate increased to Tech Spec limit of 2 5 gpm & plant shut down in preparation for drywell entry Leak caused by packing leak in recirculation riser stop valve 0 W/840824 ltr THULL.T S , MROCZKA.E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA.E J Northeast Utilities 84/08/24 3pp 26291 238 24X Fiche 50-245,84/08/24,8408290004

### V Operator Examinations

- 8408080464 Forwards Exam Rept 50-245/04-17 of exam administated during wh of 840424 STAROSTECKI.R Division of Project & Resident Programs 84/07/17 COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 25975 085 24X Fiche 50-245,84/07/17.8408080464
- --8408080466 Exam Rept 50-245/84-17 administered on 840424-26 Exam results four candidates passed & six failed BERRY.J A Region 1. Office of Director 84/06/22 70pp 25975 087 24X Fiche 50-245.84/07/17.8408080464

### DOCKET 50-247 INDIAN POINT STATION, UNIT 2

- F Security, medical, emergency & fire protection plans
- 8405240290 Responds to 840424 memo for FCMA review of util request for dalay in scheduling next full-scale emergency preparedness exercise at site until 841130 Delay acceptable RRIMM,R Federal Emergency Management Agency 84/05/18 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 8pp 24614 336 24X Fichs 50-003.84/05/18, 8405240290
- 8408010296 Forwards IE Insp Rept 50-247/84-12 on 840514-0615 & notice of violation
  STAROSTECKI, R Division of Project & Resident Programs 84/07/12
  O'TODLE, J D Consolidated Edison Co of New York, Inc 3pp
  25866 175 24X Fiche 50-247,84/07/12,8408010296
- --8408010298 Natice of violation from insp on 840514-0615 Bafeguards info deleted (ref 10CFR2 790 & 73 21) \* Division of Project & Resident Programs 84/07/12 2pp 25866 178 24% Fiche 50-247.84/07/12,8408010296

- --8408010300 IE Insp Rept 50-247/84-12 on 840314-0613 Violations noted health physics program deficiencies & security personnel failed to comply w/access control procedures Safeguards info deleted (ref 10CFR2 790 & 73 21)
  FCLEY. T. KOLTAY.P. NORRHOLM.L. Division of Project & Resident Programs 84/06/27 10pp 25866 180 24X Fiche 50-247.84/07/12, 8408010276
- B408010282 Forwards IE Insp Rept 50-247/84-13 on 040612-15 & 0705-06 & notice of violation Enforcement conference scheduled for 840718 to discuss unplanned exposure of two workers on 840419 MARTIN, T T Division of Engineering & Technical Programs 84/07/
  - 840619 MARTIN,T T Division of Engineering & Technical Programs 84/07/13 0'TOOLE,J D Consolidated Edison Co of New York, Inc. 3pp 25866 222 24X Fiche 50-247,84/07/13,8408010282
- --B408010286 IE Insp Rept 50-247/84-13 on B40612-15 & 0705-06 Violations noted failure to post & barricade high radiation area, failure to perform airborne radioactivity surveys & adhere to physical security plan Bafeguards info deleted NIMITZ.R L , MILLER.M M , CLEMONS.P E Region 1, Office of Director 84/07/13 15pp 25866 228 24X Fiche 50-247.84/07/13, 8408010282
- B408060349 Forwards revs to physical security plan Revs withheld (ref 10CFR73 21) O'TQOLE, J D Consolidated Edison Co of New York, Inc 84/07/14 MURLEY, T E Region 1. Office of Director 1p 25936 052 24X Fiche 50-003, 84/07/16, 8408060349
- 8408150121 Forwards public version of revs to Book II to emergency procedures document including App A. "Emergency Roster" & App B. "Con Ed Medical Dept. Consultants & Agencies "O'TOOLE, J D Consolidated Edison Co of New York. Inc 84/07/16 MURLEY, T E Region 1. Office of Director 2pp 26104 258 24X Fichs 50-003.84/07/16,8408150121
- --8408150125 Public version of revs to Book II to emergency procedures document including App A, "Emergency Roster" & App B "Can Ed Medical Dept Consultants & Agencies " W/JM Felton B40808 release memo \* Consolidated Edison Co of New York, Inc 84/05/27 21pp 26104 260 24X Fiche 30-003,84/07/16,8408130121
- 8408070114 Provides schedule info re NUREG-0737, Suppl 1 on emergency response commitment & clarifies schedular error in B40612 confirmatory order Amend to order prior to Sept 1985 suggested O'TOOLE, J D Consolidated Edison Co of New York, Inc 84/07/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 25950 034 24% Fiche 50-247,84/07/31,8408070114
- 8408090056 Clarifies addl issues raised by NRC in 840626 telcon re
  New York PIRO petition to suspend OLs due to emergency
  planning inadequacies FEMA rept & State of NY response to
  FEMA 840611 it renc!
  KRIMM.R W Federal Emergency Management Agency 84/07/31
  JORDAN, E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) ip 25992 335 24X Fiche 50-247,84/07/31,84080900056
- --8408090059 "Evaluation of Addl Issues Raised by NRC re New York PIRO Patition to Suspend Operation of Indian Point. Units 2 & 3 " # Federal Emergancy Management Agency 84/07/22 10pp 2992 336 24X Fiche 50-247,84/07/31.8408090056
- --8408090061 "Add1 Info Obtained From NY State on New York PIRO Patition Which Supple FEMA Rept to NRC dtd 840608" \* Federal Emergency Management Agency 84/07/26 Bpp. 85972 346 24X Fiche 30-247.84/07/31,8408090056
- 8408070421 Responds to manual reactor conlant pump trip issue, Upgraded emergency operating procedures & integrated operator training being implemented per Suppl i to NUREG-0737 & Generic Ltr 83-100 O'TOOLE J D Consolidated Edison Co of New York, Inc 84/08/01 EISENHUT. D Q Division of Licensing 200 23742 024 24X Fiche 50-247,84/08/01,840807042i
- 8408130325 Submits schedule info on detailed control room design review summary rept, per Suppl 1 to NuREO-0737 Clarifies schedular error in 840612 confirmatory order Amend to order requested prior to Sept 1985
  O'TODLE, J D Consolidated Edison Co of New York, Inc. 84/08/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26010 057 24% Fiche: 50-247, 84/08/06, 8408130325.
- 8408160279 Notifies of fees due for review of fire protection requests Discussion of 10CFR170 fee requirements & list of applications & fees due encl MILLER. H. D. License Fee Management Branch 84/08/09 0'TOOLE, J D Consolidated Edison Co of New York. Inc 4pp 26122:359. 24x Fiche 50-247,84/08/09,8408160299

8408210002 Forwards SAR for safety assessment sys/safety parameter display sys.per NUREG-0737 Suppl ( & 830415 & 840312 ltrs O'TOOLE. J D Consolidated Edison Co of New York, Inc 84/08/15 EISENNUT.D G Division of Licensing 13pp 26183 054 24X Fiche 50-247,84/08/15,8408210002

### 9 Adjudicatory correspondence

- 8408140448 Responses to 840730 unpublished order directing NRC to inviting other parties to submit views on Judge Gleason dissent re ASLB recommendation concerning accident probability Certificate of Svc encl SHOLLY.S C Union of Concerned Scientists DSB 027 84/08/13 Commissioners Spp 26061 007 24x Fiche 30-247,84/08/13.8408484848
- B40B1404BB Response to Commission B40730 order permitting comments from parties re Chairman Gleason dissent to ASLB recommendations to Commission Certificate of Svc encl COLLARULLI, P F Power Authority of the State of New York COLARULLI, P F Morgan Associates DBC 030 84/08/13 Commissioners 14pp 26060 261 24x Fiche 50-247,84/08/13, B40B1404B
- B408140493 Comments on ASLB Chairman Gleason dissent in recommendations of special proceeding Significant risk reduction already accomplished at facility Certificate of Svc enci BRANDENBURG B Consolidated Edison Co of New York, Inc DSB 031 B4/03/13 Commissioners 12pp 26060 249 24x Fiche 50-247-84/08/13,8408140493
- 840Bi30111 Response to Commission 840730 order directing NRC to file comments on Judge Oleason dissent to portion of ASLB recommendations Supports Gleason dissent MODRE. J E Hearing Branch 1 DSB 042 84/08/13 Commissioners 14pp 26066 265 24X Fiche 50-247.84/08/13.8408150111
- 8409170270 Comments on dissenting views of Chairman Gleason re safety of plant mods Cartificate of Svc encl BRANDENBURG, B Consolidated Edison Co of New York, Inc DSB QBS 84/08/13 12pp 26118 041 24X Fiche S0-247,84/08/13,8408170270

### P Operating license stage documents & correspondence

- 8407120020 Forwards request for addl info to complete SER re review of environ qualification of electrical equipment important to safety info required by 840715
  VARGA.S A Operating Reactors Branch 1 84/06/22 D'TODLE.J D Consolidated Edison Co. of New York. Inc. 4pp 29973 128 24% Fiche 30-247.84/06/22,8407120020
- B408020138 Advises that Tech Spec change requests per Generic Ltr 83-37, "NUREG-0737 Tech Specs," will be submitted by 841231, per 840615 telcon request 0'TOCLE.J D Consolidated Edison Co of New York, Inc 84/07/26 EISENHUT, D O Division of Licensing 1p 25872 305 24X Fiche 50-247.84/07/26,8408020138
- 8408130211 Forwards requests for relief from five testing requirements of ARME Code.Section XI Provisions of requests intended for application during current refueling & inservice inspoutage O'TODLE.J D Consolidated Edison Co of New York, Inc 84/07/30 VARGA.S A Operating Reactors Branch 1 App 26010 019 24X Fichs 50-247.84/07/30.8408130218
- B408090530 Forwards request for add1 info for review of 840214 submittal re control of heavy loads Tech Spec change Response requested within 45 days of 1tr receipt VARQA/S A Operating Reactors Branch i 84/08/01 0'TODLE, J Consolidated Edison Co of New York, Inc. 4pp 25783 332 24X fiche 50-247.84/08/01,8408090530
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUMEG-0933. "Prioritization of Generic Safety Issues " Svc list end EISENHUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000.84/08/06.8408070110
- 8408310136 Forwards Matls Engineering Branch request for add1 info re potential flaw indication on reactor vessel, as discussed at 840811 meeting w/util VARGA.5 A Operating Reactors Branch : 84/08/16 D'TDDLE, J D Consolidated Edison Co of New York. Inc. 7pp 26352 017 24X Fiche 50-247,84/08/16,8408310136

- 8408240164 Forwards requests for tellef from ASME Boiler & Pressure Vessel Code Section XI requirements re exam of reactor vessel flange ligaments between threaded stud holes & hydrostatic pressure testing of generator coolers (7TDDLE.JD) Consolidated Edison Co of New York, Inc. 84/08/17 VARGA, 6 A Operating Reactors Branch I Spp. 26228 179 24X Fichs 50-247.84/08/17.8408240164
- 8408200275 Generic Ltr 84~20 to all licensees of operating reactors & applicants for QLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT.D 0 Division of Licensing 84/08/20 Consolidated Edison Co. of New York, Inc. 17pp. 26276-244 24X Fich. 50-000.84/08/20.8408200275
- 8408280290 Forwards draft technical evaluation rept re control of heavy loads, for review & comment Project manager should be contacted within 30 days to discuss outstanding items W/o encl VAROA:8 A Operating Reactors Branch 1 84/08/20 O'TOOLE, J D Consolidated Edison Co of New York, Inc 1p 26294 086 24x Fichs 50-247,84/08/20,8408280290
- 8408280333 Staff requirements memo re 840814 continuation of 840723 discussion of issues requiring resolution prior to issuance of order in proceeding Commission requested briefing on PRA including discussion of uncertainties & basis of comparison CHILK.S J Office of the Secretary of the Commission 84/08/21 DIRCKS.W J Office of the Executive Director for Operations ZERBE, J C Office of Policy Evaluations 2pp 24294 050 24X Fiche 50-003.84/08/21.8408280333
- Q Inspection reports, IE Bulletins & Correspondence
- ~-8408010278 Notice of violation from insp on 840814-0615 Safeguards info deleted (ref 10CFR2 770 & 73 21) \* Division of Project & Resident Programs 84/07/12 2pp 25866 178 24X Fichs 50-247.84/07/12.8408010296
- ~-8408010300 IE Insp Rept 50-247/84-12 on 840514-0615 Violations noted health physics program deficiencies & security personnel failed to comply w/access control procedures Safeguards info deleted (ref 100FR2 790 & 73 2) FOLEY, T, KCLTAY, P, NDRRHOLM, L Division of Project & Resident Programs 84/04/27 10pp 25866 180 24X Fiche 50~247,84/07/12,8408010296
- 8408010282 Forwards IE Insp Rept 30-247/84-13 on 840612-13 & 0705-06 & notice of violation Enforcement conference scheduled for 840718 to discuss unplanned exposure of two workers on 840619 MARTIN, T Division of Engineering & Technical Programs 84/07/13 O'TOOLE, J D Consolidated Edison Co of New York, Inc. 3pp 25866 222 24X Fiche 50-247,84/07/13,8408010282
- ~-8408010284 Notice of Violation from insp on 840612-15 Safeguards info deleted \* Region 1, Office of Director 64/07/13 3pp 25866 225 24X Fiche 50-247,84/07/13,8408010282
- --8408010286 IE Insp Rept 50~247/84~13 on 840612-15 t 0705-06 Violations noted failure to post t barricade high radiation area, failure to perform airborne radioactivity surveys t adhere to physical security plan Bafeguards info deleted NIMIT2.R L , MILLER,M M , CLEICNS,P E Region 1, Office of Director 84/07/13 15pp 25866 228 24X Fichu 50-247,84/07/13,8408010282
- 8407250229 IE Info Notice 84-57. "Operating Experience re Moisture Intrusion in Bafety-Related Electrical Equipment at Commercial Power Plants " Bvc list encl JORDAN. EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc. 119pp 25865-047 24X Fiche 50-000,84/07/27,8407250229
- 8408070425 Responds to IE Bulletin 84~02. "Failure of GE Tupe HFA Relays in Use in Class IE Bafety Bys " GE NFA relays not used in safety-related applications O'TOOLE.J D Consolidated Edison Co of New York, Inc 84/07/30 MURLEY.T E Region 1, Office of Director 2pp 25942 023 24X Fiche 50-247.84/07/30.8408070425

- 8408130211 Forwards requests for relief from five testing requirements of ASME Code Section XI Provisions of requests intended for application during current refueling & inservice inspoutage U-TOOLE, J D Consolidated Edison Co. of New York, Inc. 84/07/30
- 0/TDDLE.J D Consolidated Edison Co of New York, Inc. 84/07/30 VARGA:S A Operating Reactors Branch 1 App. 26010-019 24X Fiche 50-247,84/07/30,8408130211
- B40B200510 Forwards IE Insp Rept 50-247/B4-14 on 84061B-22 & notices of Midlation & deviation MARTIN.T T Division of Engineering & Technical Programs B4/0B/O O'TOOLE, J D Consolidated Edison Co of New York, Inc. 3pp 2613B 173 24X Fiche 50-247.84/0B/OI.840B200510
- --8408200518 Notice of violation from insp on 840618-22 \* Region 1, Office of Director 84/08/01 2pp 26138 176 24X Fiche 50-247,84/08/01.8408200510
- --8408200530 Notice of deviation from insp on 840618-22 \* Region 1, Office of Director 84/08/01 1p 26138 178 24X Fichs 50-247.84/08/01.8408200510
- --B409200544 IE Insp Rept 50-247/B4-i4 on B40618-22 Violations noted failure to comply W/conditions of certificate of compliance, failure to review & approve procedures & failure to train personnel involved in transportation activities HOBAN,R T , STRUCKMEYER,R , PASCIAK,W J Region 1, Office of Director B4/07/20 App 26138 179 24X Fiche 50-247,84/08/01,8408200510
- 8408210238 Forwards IE Enforcement Conference Rept 50-247/84-20 on 840718 Appropriate enforcement action will be specified at later date MARTIN.T T Division of Engineering & Technical Progrems 84/08/ D'TODIE.J D Consolidated Edison Co of New York, Inc 2pp 26184 292 24X Fiche 50-247.84/08/02.8408210238
- --8408210244 IE Enforcement Conference Rept 50-247/84-20 on 840718 Major areas discussed deficiencies in control of high radiation. performance & unplanned exposures of two workers on 840619 NIMITA:R L , SHANBAKY, M M Region I. Office of Director 84/07/31 3pp 26184 294 24X Fiche 50-247,84/08/02,8408210238
- 8408010333 IE Info Notice 84-59, "Deliborate Circumventing of Station Health Physics Procedures "Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc. 85pp. 24068 001 24% Fiche 50-000,84/08/06.8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list encl JURDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Cansolidated Edison Co. of New York, Inc. 123pp 26067 158 24X Fichs 50-000.84/08/06,8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York: Inc 120pp 26129 118 24X Fichs 50-000.84/08/08.8408070120
- 8408130385 Ack receipt of 840619 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-247/84-03 Corrective actions will be examined during future insp MARIIN.T T Division of Engineering & Technical Programs 84/08/0 O'TOOLE.J D Consolidated Edison Co of New York, Inc 2pp 26010 175 24Y Fiche 50-247.84/08/08.8408130385
- --8408130388 Responds to NRC 840426 ltr re violations noted in IE Insp Rept 50-247/84-03 Corrective actions include implementation of engineering personnel training, maint procedural changes & GA procedures review & rev O'TOOLE, J D Consolidated Edison Co of New York, Inc 84/06/19 MARTIN.T T Division of Engineering & Technical Programs Spp 26010 177 24X Fichs 50-247,84/08/08,8408130385
- B408070376 IE Info Notice B4~62, "Therapy Misadministrations to Patients Undergoing Co~60 Teletherapy Treatments " 8vc list enc! GRACE.J N Division of QA, Safeguards & Inspection Pragrams (Post 830103) B4/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376
- 8408100009 IE Info Notice 94-63. "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN, EL Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 30-000,84/08/13,8408100009

- 8408200309 Advises of results of 840805 10-yr inservice insp of reactor vessel Significant amplification of indications on outside surface demonstrated Add1 info will be submitted prior to return to power operation
  O'TOOLE, J D Consolidated Edison Co of New York, Inc. 84/08/13
  DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26/32 361 24X Fiche 50-247.84/08/13.8408200309
- ## B40B300106 Forwards Insp Rept 50-247/84-18 on ### B40717-20 No violations noted ### MARTIN.T T | Division of Engineering & Technical Programs | ### B4/08/14 | D'TOOLE, J D | Consolidated Edison Co | of New York Inc | 2pp | 26308 100 | 24X Fiche 50-247.84/08/14.8408300106
- --8408300113 Insp Rept 50-247/84-18 on 840717-20 No violations noted Major areas inspected inservice activities including program review observations of work in progress NDE procedure & licensee actions re Reg Gulet 1 150 MCBRCARTY R A Region 1 Office of Director DURR, J P Division of Engineering & Technical Programs 84/08/06 5pp 26308 102 24X Fiche 50-247.84/08/14.8408300106
- 8408100038 IE Info Notice 84-64. "BWR HPCI Initiation Seal-In & Indication " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 073 24X Fiche 50-000,84/08/15,8408100038
- 8408100021 IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl URBDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc. 118pp 26198-001 24X Fiche 50-000.84/08/16, 8408100021
- 8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- 8408140208 IE Info Notice 84-67. "Recent Snubber Inservice Testing W/
  High Failure Rates " Svc list encl
  JORDAN,E L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 94/08/17 Consolidated Edison Co of New
  York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 8408270279 Forwards completed response to IE Bulletin 83-07,
  "Apparently Fraudulent Products Sold by Ray Miller, Inc."
  including review of general concerniper SD Ebneter 840658
  request Fraudulent safety-related math will not be used
  O'TCOLE.J D Consolidated Edison Co of New York, Inc 84/08/17
  DEYQUNG.R C Director's Office, Office of Inspection and
  Enforcement ERNETER, 8 D Region 1. Office of Director 3pp
  R6270 333 24X Fiche 50-247,84/08/17,8408270279
- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Salenoid Valves " Svc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc. 113pp 26329 008 24X Fiche 90-000.84/08/21.8408210142
- 8 Reportable occurrences. LERs & related correspondence
- 840B100072 PNO-1-84-067 on 840B06 indication detected in reactor vessel wall during ultrasonic test Evaluation & review of const records & photographs continuing Startup from 10-yr inservice insp outage scheduled for late Sept 1984 DURR. J P. NORRHOLMIL Region i. Office of Director 84/08/08 ip 25970 043 24X Fiche SO-247.84/08/08.840B100072
- 8408200539 LER 84-007-00 on 840711.during continuous fire watch, personnel failed to watch cable spreading room for 4 h Personnel reinstructed W/840810 ltr BLATT.M, O'TOUE.J D Consolidated Edison Co of New York, Inc 84/08/10 3pp 26139 027 24% Fiche 50-247.84/08/10, 8408200539
- 8408220214 LER 84-008-00 on 840713 during refusling outage, one channel of manual safety injection circuitry spuriously & partially actuated, causing partial initiation of engineered safeguards equipment Activation apparently imadvertent W/840812 itr BLATE, M., U'TOOLE, J.D. Consolidated Edison Co. of New York, Inc. 84/08/12 3pp 26189 261 24% Fichs. 50-247, 84/08/12, 8408220214
- T Hearing transcripts on non-antitrust matters
- B40B280025 Transcript of B40B16 Commission meeting in Washington DC recontinuation of 840723 discussion of adjudicatory proceeding Pp 1-76.

  \* Commissioners 84/08/16 78pp 26293 169 24X Fiche 50-003;84/08/16.8408280025

- DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

  F. Security, medical, emergency & fire protection plans
- 8404040169 Forwards exercise repts for LaSalle & Dresden offsite radiological emergency preparedness exercises conducted 820414-13 & 0629-30, respectively KRIMM.R & Federal Emergency Management Agency 84/03/26 JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 22883 122 24X Fiche 50-000, 84/03/26, 8404040169
- B40B140139 Forwards listed revs to security plans Ravs address fence height requirements Revs withheld (ref 10CFR73 21) FARRAR, D. Commonwealth Edison Co. 84/08/03 Region 3, Office of Director ip 26044 252 24X Fiche 50-000,84/08/03,8408140139
- 8408130401 Responds to 840705 clarification of info re util means of satisfying annual regulatory requirement to review emergency action levels w/offsite emergency support organizations Info acceptable PAPERIELLO, C. J. Region 3. Office of Director 84/08/07 REED.C Commonwealth Edison Co. ip 26010 130 24X Fiche 50-000,84/08/07.8408130401
- ~-8408130413 Responds to 840604 ltr re means for satisfying requirements of 10CFR50.App E.Paragraph IV B Proposal for satisfying requirements to review emergency action levels by offsite agencies clarified.

  FARRAR, D L Commonwealth Edison Co 84/07/05 PAFERIELLO, C J Region 3, Office of Director Bpp 26010 131 24X Fiche 50-000,84/08/07.8408130401
- 8408130289 Forwards FR notice of environ assessment & finding of no significant impact re 840405 & 26 requests for exemption of state & local govt participation in 840405 exercise PAULSON.W A Operating Reactors Branch 5 84/08/10 FARRAR.D L. Commonwealth Edison Co 2pp 26010 262 24x Fiche 50-010,84/08/10.8408130289
- --B408130298 Notice of environ assessment & finding of no significant impact re exemption from requirements of 10CFR50, App E re state & local govt participation at 840603 exercise EISEMHUT.D Q. Division of Licensing 84/08/10 4pp 26010 264 24X Fiche 50-010.84/08/10.8408130289
- 8408140377 Forwards summary of App R reverification methodology & status.per 840627 commitment to submit results of hot shutdown portion of fire protection program independent review W/28 oversize drawings Aperture cards in PDR FARRAR.D L Commonwealth Edison Co. 84/08/10 DENTON, H.R. Defice of Nuclear Reactor Regulation, Director 222pg 26049 079 24X Fiche 50-237.84/08/10.8408140397
- B40B200281 Advises that B40B03 Rev 15 to physical security plan consistent w/provisions of 10CRSO 54(p) & acceptable AXELSON.W L. Region 3. Office of Director B4/0B/14 FARRAH, D.L. Commonwealth Edison Co. 2pp 26133 023 24X Fiche 50-010,84/0B/14,840B20021
- 8408210001 Forwards exemption from cortain requirements of Section IV F.I of App E to 10CFR50 for Dresden 840605 emergency preparedness exercise w/o full-scale participation by state & local govts in plume exposure pathway FAULSON-W A Operating Reactors Branch 5 84/08/14 FARRAR, D L. Commonwealth Edison Co 3pp 2618; 320 24x Fiche 50-010,84/08/14,8408210001
- --B40B210005 Exemption from Section IV F 1 of App E to 10CFR50 requiring full-scale emergency preparedness exercise at least annually, involving participation of state & local govts within plume exposure pathway emergency planning zone EIBENHUT, D G Division of Licensing B4/08/14 Commonwealth Edison Co 3pp 26181 323 24% Fiche 50-010,84/08/14,8408210001
- 8408230283 Revised emergency plan implementing procedures, including EPIP 100-C3 re-generating station emergency plan log, replacing record of generating station emergency plan activities form W/840820 ltr 800TT.D J Commonwealth Edison Co 84/08/20 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 67pp 26207 295 24X Fiche 50-010.84/08/20.8408230283

# icense stage documents & correspondence

of schedular requirements of nt/mod of specific equipment subj le.Next refueling outage

on Co 84/07/31 DENTON.H R Office of Director 2pp 25923 006 24X 60071

- 8408060425 Notification of 840809-10 meetings w/utils.NUTECH.Franklin Research Cti & DNL in San Jose CA to discuss comments resulting from post-implementation review re plant-unique analysis repts BEVAN.R B . ROUNEY.V L . THADANI,M C Operating Reactors Branch 2 84/07/31 VASSALLO.D B Operating Reactors Branch 2 ip 25937 335 24X Fiche 50-000.84/07/31.8408060425
- 8408150113 Forwards reformatted Tech Specs improving legibility & versatility, per request W/o encl HYBAK, B Commonwealth Edison Co 84/08/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 26066 351 24% Fiche 50-237, 84/08/01.8408150113
- 8408060276 Forwards revised Yech Spec changes to Licenses DPR-19 & DPR-25, submitted on 840611 Tech Specs revised into new format.incorporating NRG comments w/o changing technical content RYBAK.8 Commonwealth Edison Co 84/08/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 25933 223 24X Fiche 50-237,84/08/02,8408060276
- --8408060280 Proposed Tech Specs, revising format to incorporate NRC comments w/o changing technical content
   Commonwealth Edison Co 84/08/02 30pp 29939 226 24x
  Fiche 50-237,84/08/02,8408060276
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933; "Prioritization of Generic Safety Issues " Svc list encl EISENHUT.D G Division of Licensing 84/08/04 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fichs 50-000.84/08/06.8408070110
- 8408160062 Forwards Amends 82 & 75 to Licenses DPR-19 & DPR-25, respectively Amends consist of reformatted Tech Specs to provide clarity PAVILSON. WA Operating Reactors Branch 5 84/08/06 FARRAR. D L Commonwealth Edison Co 3pp 26092 189 24X Fiche 50-237, 84/08/06, 8008160062
- --8408160070 Amends 82 % 75 to Licenses DPR-19 & DPR-25, respectively, consisting of reformatted Tech Specs
  PAULSON W A Operating Reactors Branch 5 94/08/06 600pp
  26090 192 24X Fiche 50-237,84/08/06,8408160062
- 840BiA0345 Advises that QA program applicable to all nuclear generating stations & satisfies provisions of 10CFR71 Fee remitted per 10CFR170 31 FARAR. D. L. Commonwealth Edison Co. 84/08/06 Office of Nuclear Material Safety & Gafeguards. Director 1p 26072 184 24X Fichm 50-000, 84/08/06.8408160345
- 8408170017 Notifies of Class I & II fees due for 840611 Tech Spec change request Fee will be adjusted if appropriate DIO95.R M License Fee Hamagement Branch 84/08/10 FARRAR.D L Commonwealth Edison Co 1p 26135 344 24X Fiche 50~237.84/08/10, 8408170017
- B408270114 Provides supplemental response to Generic Ltr B3-36, "NUREG-0737 Toch Specs" Mads to Guad Citius radiological ETB will not be complete until Fall 1984 Complete response W/amend requests expected by B41115
  ALEXANDER.O 1. Commonuealth Edison Co. B4/08/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp. 26247 330 24X Fiche 50-000,84/08/15,8408270114
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittels of reloads that involve unreviewed safety questions Svc list enci EISENHUT.D 0 Division of Licensing 84/08/20 Consulidated Edison Co of New York, Inc. 17pp 26276 244 24X Fichs 30-000.84/08/20,8408200275
- 840B310211 Forwards final response to second & final set of questions re Mark I containment plant-unique analysis RYBAK, B Commonwealth Edison Co 84708/24 DENTUN, H R Office of Nuclear Reactor Regulation, Director 37pp 26318 072 24X Fiche 50-000.84/08/24.8408310211
- B40B300102 Forwards corrected pages to 840806 Amends 82 & 75 to Licenses DPR-19 & DPR-25, respectively PAUL6DN, W A Operating Reactors Branch \$ 84/08/27 FARRAR, D L Communicalth Edison Co. 2pp 26306 135 24X Fiche 50-237, 84/08/27, 840B300102
- --8408300111 Corrected pages to Amends 82 & 75 to Licenses DPR-19 & BPR-25.respectively PAULBON W A Operating Reactors Branch 5 84/08/27 3pp 26306 137 24x Fichs 50-237.84/08/27.8408300102

- G Inspection reports, IE Bulletins & correspondence
- B408030251 Ack receipt of 840622 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/B4-05, 50-237/B4-07 & 50-247/B4-06
  PAPERIELLO.C J Region 3, Office of Director 84/07/10 REED.C Commonwealth Edison Co 1p 25917 226 24X Fiche 50-010, B4/07/10. RAGBRODEN
- --B408030252 Responds to NRC B40524 ltr re violations noted in IE Insp Repts 50-010/84-05,50-237/84-07 & 50-249/84-06 Corrective actions sludge removed from Toledo & Joliet facilities Survey of sumps found no residual activity FARRAR.D L Commonwealth Edison Co B4/06/22 KEPPLER, J Q Region 3, Office of Director 4pp 25917 227 24x Fiche 50-010,84/07/10,8408030251
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229
- 8408070066 Notifies of 840823 meeting w/util at Region III ofc to review findings of SALP assessment re util performance Encourages mgt representation to ensure mutual understanding of issues & findings presented by NRC NORELIUS, C E Region 3, Office of Director 84/08/03 REED. C Commonwealth Edison Ca 2pp 25747 337 24X Fichs 50-000,84/08/03,8408070064
- 8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during inspinstituted.effective 840820 Preprinted form will be used rather than ltr
  KEPPLER.J G Region 3, Office of Director 84/08/03
  Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000,84/08/03,84088/03/041
- B40B010333 IE Info Notice 84-57, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Divor in PWR Refueling Cavity " Svc list encl JORDAN, E. L. Division of Emergency Proparodness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York, Inc. 120pp 26127 118 24X Fiche 50-000,84/08/08,8408070120
- B40Bi40344 Confirms 840B03 plans to meet w/util on 840907 in Glen Ellyn, IL to discuss regulatory improvement program NURELIUS, C E Region 3. Office of Director 84/08/08 REED, C Commanuealth Edison Co. 2pp 26041 050 24X Fiche 50-000, 84/08/08. 8408140344
- 8408150078 Suppls 840711 response to IE Bulletin 84-02 re visual insp during monthly functional tests to verify proper contact on reactor trip sys & primary containment isolation sys relays Exemptions requested for listed relays ALEXANDER: 6 L. Commonwealth Edison Co. 84/08/08 KEPPLER. J G Region 3. Office of Director 3pp 26067 053 24X Fiche 50-000.84/08/08.8408150098
- 8408200331 Suppls response to IE Bulletin 84-02 re failure of GE Type HFA relays Exemption requested from commitment for visual insp verifying proper relay contact during monthly functional check for listed relays
  ALEXANDER, G L Commonwealth Edison Co 84/08/08 KEPPLER, J G Region J, Office of Director 3pp 26132 318 24X
  Fiche 50-000,84/08/08.8408200331
- 8408300075 Forwards Insp Repts 50-010/84-10, 50-237/84-12 & 50-249/84-11 on 840618-0726 & notice of violation SHAFER, W D Region 3, Diffice of Director SHAFER, W D Region 3, Diffice of Director Commonwealth Edison Co 2pp 26307 201 84/08/08 REED, C 24X Fiche 50-010, 84/08/08, 84/08/08
- --8408300108 Insp Repts 50-010/84-10, 50-237/84-12 & 50-249/84-11 on 840618-0726 Noncompliance noted inadequate corrective action taken in response to Tech Spec violation re open submarine door in Unit 2 reactor bldg
  TONGUE, T M , STABEK, S , ANDERSON, C D Region 3, Office of Director 84/08/07 11pp 26307 204 24X Fiche 50-010,84/08/08.8408300095

- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list enc! GRACE.J N Division of QA, Bafeguards & Inspection Pragrams (Post 830103) 84708/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24% Fishe 30-000.84/08/10.8408070376
- B40Bi60139 Ack receipt of 840730 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Repts 50~010/B4-09, 30-237/84-11 % 50-249/84-10 B40Bifo B4
- --8408160145 Responds to NRC 840703 ltr re noncompliance noted in IE Insp Repts 30-010/84-07.30-237/84-11 & 50-247/84-10 Corrective actions special procedure for testing automatic function of master pilot valve incorporated into existing Cardox sus FARRAR.D L Commonwealth Edison Co 84/07/30 KEPPLER.J 0 Region 3. Defice of Director 3pp 26092 041 24X Fiche 50-010,84/08/10.8408140139
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  8vc list encl
  JDRDAN.E L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc. 117pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 840Bi0003B IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl JORDAN.E L. Division of Emergency Proparedness & Engineering Response (Past B30103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26178 073 24X Fiche 50-000.84/08/15.840B100038
- 840B100021 IE info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Byc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc. 118pp 26198 001 24X Fiche 50-000,84/08/16.8408100021
- B40B100055 IE Info Notice B4-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Bvc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/0B/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000.84/0B/17,8408100055
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/High Failure Rates" Bvc list encl
  JORDAN E L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/17 Consolidated Edison Co of New
  York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Bolenoid Valves " Svc list encl JORDAN.E L Division of Emergency Properedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000.84/08/21.8408210142
- R Periodic operating reports & related correspondence
- 840B300368 "Rept of Radioactive Effluents," Jan-June 1984 W/890813 ltr BCOTT,D J CammonuBalth Edison Co 84/06/30 KEPPLER.J Q Region 3. Office of Director 17pp 26308 172 24X Fiche 30-010.84/06/30, 8408300368
- 840B13027i Monthly operating repts for Jul 1984 W/840B03 ltr SCHROEDER, B A . BCOTT, D J Communwealth Edison Co B4/07/31, 20pp 26006 342 24X Fiche 50-237.B4/07/31.B40B130271
- 8 Reportable occurrences. LERs & related correspondence
- 8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated SHERWOOD, O O oneral Electric Co 8404413 DEYCUNO. R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000,84/04/13,8408240348
- 8408130146 LER 84-006-00 on 840711, reactor vessel found not vented at less than 149 F Caused by inadvertent procedure violation Reactor metal temp increased Personnel reminded of venting requirement W/840807 ltr WOJTULEWICZ, T , 8COTT, D J Commonwealth Edison Co 84/08/03 3pp 26007 347 24X Fiche 50-249,84/08/03,8408130146

- B408200319 LER 84-001-01 on 840323, reactor water level decreased to low level alarm point Copiant loss compounded by two open bypass valves Procedures revised to remind operators to close turbine valves #/840809 ltr
  BERGAN, G. W. BCOTT, D. J. Commonwealth Edison Co. 84/08/09 4pp 26138 317 24% Fiche 50-249, 84/08/09, 8408200519
- 8408210104 LER 84-005-00 on 840716, east LPCI corner room submarine door found open Caused by stationmen working in area Door closed & Tech Specs requiring door to be closed emphasized Annunciators will be installed H/840813 ltr
  LEAHY, M. SCOTT, D. J. Cormonwealth Edison Co. 84/08/13 3pp
  26184 015 24x Fiche 50-249.84/08/13.8408210104
- 8408230077 Summary of 840807 operating reactor events meeting re occurrences since 840719 meeting List of attendees, significant elements & status of previous assignments encl CRUTCHFIELD.D Assistant Director for Safety Assessment 84/08/L6 ETSENHUT.D @ Division of Licensing 20pp 26233 249 24X Fiche 50-000.84/08/L6.8408230077
- 8408270455 LER 84-007-00 on 840722 turbine bypass valve 1 operated erratically causing Group i isolation on main steam low pressure Caused by failure of servovalve (Model 450-1680) mechanism for opening & closing valve W/840817 ltr CDYLE, L. SCOTT, D. J. Commonwealth Edison Co. 84/08/17 Spp 26257:203 24X Fiche 50-249.84/08/17.8408270455
- 8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evalvate condition
  VILLA: General Electric Co 84/08/21 ROSSI.C E Director's
  Defice, Office of Inspection and Enforcement 3pp 26318 327 24%
  Fiche 50-000.84/08/21.8408310186
- 8408310071 LER 84-008-00 on 840804, while opening valve t601-58, drywell to tarus differential pressure fell below Tech Spec level Caused by closed pressure control valve 8599-538 Personnel counseled M/840822 ltr BDYLE, L A . SCOTT. D J Commonwealth Edison Co 84/08/22 3pp 26334 239 24X Fiche 50-249,84/08/22.8408310071

### V Operator Examinations

- B40B140372 Forwards proposed rev to "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," in response to NUREG-0737, Item I A 3 1 MARSHALL.J O Commonwealth Edison Co 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26051 240 24X Fiche 50-000, 84/08/07, 8408140372
- ~~B40Bi403B9 "Requalification Program for Licensed Operators. Senior Operators (Limited) "
  \* Commonwealth Edison Co 84/07/19 10pp 26051 242 24X
  Fiche 50-000,84/08/07.8408140372
- 8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners WALKER'R D Region 3. Office of Director 84/08/10 Michigan, Univ of Ann Arbor, NI 2pp 26051 198 24X Fiche 50-000. 84/08/10.8408140426
  - CKET 50-250 TURKEY POINT PLANT, UNIT 3

    Security, medical, emergency & fire protection plans
- OBOIO109 Informs that proposed schedules for implementation of alternate shutdown capability & mods for App R. Section III G in accordance w/10CFR50 48 & require no schedular exemptions VAROA.S A Operating Reactors Branch 1 84/07/09 WILLIAMS, J W Florida Power & Light Co. 3pp 25873 352 24X Fiche 50-250.84/07/09.8408010109
- -8408270275 Inep Repts 50-250/84-19 & 30-251/84-19 on 840604-08 No violations or deviations noted Major areas inspected emergency preparedness MARBION.R R. CLING.N & Region 2. Office of Director 84/07/06 9pp 26258 169. 24X Ficha 50-250.84/07/09,8408270289

- 8408100016 Forwards Emergency Plan Implementing Procedure EPIP-1301. "Emergency Roster - Offsite Emergency Organization" WILLIAMS.J W Florida Power & Light Co 84/08/08 O'REILLY, J P Region 2. Office of Director ip 25987 006 24X Fiche 50-000.84/08/08.8408100016
- --8408100034 Emergency Plan Implementing Procedure EPIP-1301. "Emergency Roster - Offsite Emergency Organization " JOHNSDN.H D Florida Power & Light Co 84/08/08 13pp 23987 007 24% Fiche 30-000/84/08/08/8408100015
- 8408240328 Confirms 840829 meeting in Bethesda, MD to discuss task analysis requirements of NUREO-0737. Suppl 1 & SER open items on CEN-152 re inadequate core cooling & reactor vessel level monitoring sys
  THOMPSIN.H L Division of Human Factors Safety 84/08/13
  BARROW, J Florida Power & Light Co 1p 26253 336 24X
  Fiche 30-250.84/08/13.8408240328
- --B40B240330 Notification of B40829 meeting w/util in Bethesda:MD to discuss task analysis requirements of NUREG-0737. Suppl 1 & SER open items on CEM-132 re inadequate core cooling & reactor vessel level monitoring sys CLAYTON.H B Procedures & Systems Review Branch B4/0B/09 ZIEMAN,D L Procedures & Bystems Review Branch 2pp 26253 337 24X Fiche 30-250.84/08/13.8408240328
- B40B310003 Forwards request for add1 info re safety parameter display sys implementation plan & parameter solection rept submitted in B40B01 response to Generic Ltr 82-33 (NUREO-0737, Buppl 1) Response requested within 45 days VAROA.5 A Operating Reactors Branch 1 84/08/15 WILLIAMS. J W Florida Power & Light Co 4pp 26350 202 24X Fiche 50-250.84/08/15.840B310003
- 8408310133 Revs to emergency plan implementing procedures, including 2010, "Duties of Emergency Coordinator," 20201, "Maintaining Emergency Preparedness Radiological Emergency Plan Training" & 20126, "Offsite Dose Colculation " W/840824 ltr WILLIAMS, J W Florida Power & Light Co 84/08/24 O'REILLY, J P Region 2, Office of Director 108pp 26322 001 24X Fiche 50-250,84/08/24,8408310133
- @ Adjudicatory correspondence
- 8408010213 Response supporting J Lorion & Ctr for Nuclear Responsibility 840709 request for hearing & petition for leave to intervene re amends to expand spent fuel pool Notice of appearance & Certificate of Bvc encl YOUNG M A Hearing Branch 4 DSB 676 84/07/30 Atomic Safety and Licensing Board Panel 12pp 25856 040 24X Fichs 50-250.84/07/30.8408010213
- 8408070305 Response supporting Ctr for Nuclear Responsibility request for hearing & petition for leave to intervene re amends to allow storage of fuel w/increased onrichment Notice of appearance & Certificate of Byc encl YOUNG, M A Hearing Branch 4 DSB 810 84/07/31 Atomic Safety and Licensing Board Panel 12pp 25947 316 24X Fiche 50-250.84/07/31, 8408070305
- 8408070377 Notice of appearance in proceeding Certificate of Svc encl COLL,N A Florida Power & Light Co COLL,N A Steel, Hector & Davis DSB 878 84708/07 3pp 25982 173 24Y Fiche 50-250,84708/07.8408090397
- 8408090437 Notice of appearance in proceeding Certificate of Syc encl COLL,N A Florida Power & Light Co COLL,N A Steel, Hector & Davis DSB 879 84/08/07 Atomic Bafety and Licensing Doard Panel 3pp 25982 176 24% Fiche 50-250, 84/08/07,84400904437
- B40B140214 Forwards B40B10 motions for summary disposition of intervenor Contentions (b) & (d) & statement of matl facts & menorandum of law in support of motions Related correspondence
  BAUSER, M A Neuman & Holtzinger BAUSER, M A Florida Power & Light Co DBB 961 84/08/10 LAZD, R M , COLE, R F , LUEBKE, E A Atomic Bafety and Licensing Board Panel ip 26056.024 24X Fiche 50~250.84/08/10.840B140214
- --8408140220 Motion for summary dispositon of intervenor Contention b No genuine issue of meth fact exists & util entitled to favorable decision Related correspondence
  BAUSER, M.A. Florida Power & Light Co. BAUSER, M.A. Newman & Holtringer 84/08/10 Atomic Safety and Licensing Board Panel
  5pp 26056 025 24X Fiche 50-250,84/08/10,8408140214
- ---8408140226 Affidavit of MJ Parvin in support of applicant 840810 motion for summary disposition of intervenor Contention (b) Related correspondence PARVIN.M J Florida Power & Light Co PARVIN.M J Hestinghouse Electric Corp 84/08/03 App 26054 030 24X Fiche 50-250,84/08/10,8408140214

- --8408140236 Statement of nat! facts as to which there is no genuine issue Related correspondence
  BAUSER.M A Florida Power & Light Co BAUSER.M A Newman & Holtzinger BAUSER.M A Steel, Hector & Davis 84/08/10
  Atomic Safety and Licensing Board Panel 3pp 26056 036 24X
  Fiche 50-250,84/08/10,8408140214
- --B408140253 Motion for summary disposition of intervenor Contention (d)

  No genuine issue of natl fact exists & util entitled to
  favorable decision Related correspondence
  BAUSER, M A Florida Power & Light Co BAUSER, M A Neuman &
  Holtzinger BAUSER, M A Steel, Hector & Davis 84/08/10

  Atomic 53fety and Licensing Board Panel Bpp 26056 039 24X
  Fiche 50-250, 84/08/10, 8408140214
- --8408140262 Affidavit of EA Dienis in support of licensee 840810 motion for summary disposition of intervenor Contention (d)
  Realted correspondence
  DZENIS,E A Florida Power & Light Co DZENIS,E A Westinghouse
  Electric Corp 84/08/08 15pp 26056 047 24x
  Fiche 50-250,84/08/10,8408140214
- --B408140271 Statement of matl facts as to which there is no genuine issue re intervenor Contention (d) Related correspondence BAUSER, M A Florida Power & Light Co BAUSER, M A Nowman & Holtzinger B4/0B/10 Atomic Safety and Licensing Board Panel 7pp 26056 062 24X Fiche 50-250,84/0B/10,8408140214
- --8408140277 Memorandum of law in support of motions for summary disposition of intervenor Contentions (b) & (d) Certificate of Svc encl Related correspondence BAUSER, M A Florida Power & Light Co BAUSER, M A Newman & Holtzinger BAUSER, M A Steel, Hector & Davis B4/08/10 Bp 26056 069 24X Fiche 50-250,84/08/10,8408140214
- B408210347 Notice of appearance in proceeding Certificate of Svc encl REIS.H F Florida Power & Light Co REIB.H F Neuman & Holtringer DSB 178 84/08/16 3pp 26179 180 24X Fiche 50-250.84/08/16, 84/08210347
- 8408210380 Notice of appearance in proceeding Certificate of Svc encl REIS.H F Florida Power & Light Co REIS.H F Newman & Holtzinger DSB 180 84/08/16 3pp 26180 248 24X Fiche 50-250,84/08/16, 8408210380
- H General correspondence
- 8408210441 Informs of address change for plant manager PEEBLES.T A Florida Power & Light Co 84/08/15 NRC - No Detailed Affillation Given 2pp 26/81 256 24X Fichs 50-250.84/08/15.8408210441
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8407260218 Forwards Rev 2 to updated FSAR for Turkey Point, Units 3 & 4 Changes made under provisions of 1007850 59 for Jul 1983 June 1984 will be provided by 840901 WILLIAMS. J W Florida Power & Light Co 84/07/23 DENTON, H & Office of Nuclear Reactor Regulation. Director 4pp 25771 129 24X Fiche 50-250.84/07/23,8407260218
- --8407260220 Rev 2 to updated FSAR for Turkey Point, Units 3 & 4 # Florida Power & Light Co 84/07/31 429pp 25771 133 24X Fiche 50-250, 84/07/23, 8407260218
- P Operating license stage documents & correspondence
- 8408300382 Summarizes 840517 meeting w/util in Region II ofc re plant performance enhancement program Meeting beneficial & provided better understanding of plans
  O'REILLY, J P Region 2. Office of Director 84/05/25
  WILLIAMS, J W Floride Power & Light Ca 1p 26308 160 24X
  Fiche 50-250,84/05/25.8408300382
- 8408300419 Summarizes 840618 meeting w/util in Region 11 ofc reperformance enhancement program & quarterly progress rept meeting scheduled for 840712
  DANGE,H C Region 2. Office of Director 84/06/25 WILLIAMS, J W Florida Power & Light Co ip 26313 307 24X Fiche 50-250, 84/06/25,8408700419
- 840B010119 Forwards request for addl info re measures taken to ensure ALARA doses during proposed spent fuel pool expansion Response within 30 days of 1tr receipt requested VARGA, 8 A Operating Reactors Branch 1 B4/07/19 WILLIAMS, J W Florida Power & Light Co 6pp 25B73 321 24X Fiche 50-250,84/07/19.8408010119

- 840806043a Summary of 840713 meeting w/util in Bethesda MD re reactor matts sorveillance program (CDDMALD.D C Operating Reactors Branch i 84/07/19 Operating Reactors Branch i 94/07/19 Operating Reactors Branch i 39p 25937 317 24x Fiche 50~250. 04/07/19, 8408060436
- 8408070032 Corrects issuance date of ltr ie proposed spent fuel poel expansion to 840702 MCDUMALD.D G Operating Reactors Branch I 84/07/19 WILLIAMS.J W Florida Power & Light Co 2pp 25955 360 24X Fiche 50-250. 84/07/19.8408070032
- B40B010005 Request correction to date of its forwarded on G40602, requesting info on NAREO-0737, Item II D 1 to performance testing of relief & safety valves Correct date is B40702 VARGA, 8 A Operating Reactors Branch 1 B4/07/23 MCDUNALD.R P Alabama Power Co 2pp 25867 361 24X Fiche 50-250.84/07/23. B40B010005
- 8408070079 Forwards request for addl info re pressurized thermal shock flux reduction program Response requested within 3 wks of 1tr receipt W/o encl VARGA,S A Operating Reactors Branch ; 84/07/26 WILLIAMS,J W Florida Power & Light Co 2pp 25759 317 24X Fiche 50-250.84/07/26.8408070075
- 8408090491 Requests remittance of fee for review of 840921 application for amend to Tech Bpecs re safety-related anubbers.

  BIGGS.R.M. License Fee Management Branch 84/07/31 WILLIAMS, J.W. Florida Power & Light Co. 1p. 25983 152 24X Fiche 50-250. 84/07/31.8408070491
- 8408070110 Constic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Oeneric Hafety Issues" Svc list encl EIBENIUT.D 9 Division of Licensing 89/08/06 Consolidated Edison Co of New York, Inc. 18pp 26/27 238 24X Fichu 50-000,84/08/96,8408070110
- 8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1914
  TREMBLAY, P. P. Operating Reactors Assessment Branch HICLAYAN, O. M. Operating Reactors Assessment Branch 13pp 25991 350 24X Fiche 50-000, 84/08/04, 8408090317
- 8408160319 Forwards "Maint & Surveillance Program Plon," revised following 840706 NRC/NUMARC meeting RUSSELL,W T Division of Human Factors Safety 84/08/07 WDDDY,C O Florida Power & Light Co 1p 26126 019 24X Fiche 50-000,84/08/60316319
- --8408160325 "Maint & Burveillance Program Flan " \* NRC - No Datailed Affiliation Olven 84/07/31 23ap 24124 020 24% Fiche 50-000.84/08/07/8408160319
- B408210634 Requests add1 info re structural design aspects of 830314 request for Tech Spec mod to expand spent fuel storage facilities Mod necessary to accommodate increased inventory Add1 info requested within 2 was to meet review scheduler VARGA: S A Operating Reactors Branch 1 B4/08/13 WillIAMB.J H Flortida Power & Light Co ip 26187 356 24X Fiche 50-280, 84/08/13,8408210634
- 840B1700B4 Forwards addl info re spent fuel storage facility expansion, per NRC 840702 request NITAML XBDRNPM & Keno-IV used to calculate reactivity of checkerboard & configuration in Region 2

  WILLIAMS J W Fibrida Power & Light Co 84/08/14 VARGA, S A . Operating Reactors Branch 1 7pp 26117-024 24X

  Fiche 50-250.84/08/14.8408170084
- 8408210564 Forwards fruft safety evaluation of NUREO-0737. Item II F Q re inadequate core cooling instrumentation sys Evaluation identifies open items Addl info requested within 2 wks W/o encl VARGA. B A Operating Reactors Branch 1 84/08/14 WILLIAMS. J P Florida Power & Light Co lp 26195 255. 24X Fiche 50-250, 84/08/14,8408210864.
- 8408230477 Forwards Amonds 104 & 98 to Licenses DPR-31 & DPR-41, respectively & safety evaluation Amends provide protection of safety-related equipment subjected to degraded voltage at offsite power source M/o encis
  MCDONALD, D G Operating Reactors Branch | 84/08/14 WILLIAMS, J W Florida Power & Light Co | p. 26230 216 24X
  Fiche 50-230,84/08/14,8408230477

- 8408230364 Notification of 840906 & 07 meetings w/util in Bethesda.MD to discuss control room design reviews
  MCDDHALD.D G Operating Reactors Branch 1 84/08/16 VARGA.S A.
  MILLER, J R Operating Reactors Branch 1 2pp 26230 260 24X
  Fiche 50-000.84/08/16.8408230564
- 8408820546 Notification of 840823 meeting w/util in Bethesda MD to discuss details & review process for converting facility. Tech Specs to STS format & content for Westinghouse reactors MCDDMALD.D G. Operating Reactors Branch 1 84/08/17 VARGA,S A Operating Reactors Branch 1 2pp 26199 340 24x Fiche 50-250,84/08/17,8408220546
- B40B270015 Requests meeting w/NRC to discuss details of proposed Tech Spec rev program, including purpose for rev.plan & schedule, integration w/related projects. limitations & licensing approach HILLIAMS. J W Florida Power & Light Co 84/08/17 EISENHUT, D G Division of Licensing 1p 26247 193 24X Fiche 50-230.84/08/17, 840B270015
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee aubmittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT.D & Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24% Fiche 50-000, 84/08/20.8408200275
- 8408270019 Forwards remittance for 840619 request for amends in response to Generic Ltr 83-37 re NUREQ-0737 Tech Specs, per 100FR170 22 WILLIAMS. J W Florida Power & Light Co 84/08/21 EISENHUT. D G Division of Licensing by 26247 174 24x Fiche 50-250, 84/08/21. B408270019
- 8408270344 Forwards response to IRC 840719 requests for add1 info re health physics aspects of proposed amend to spent fuel storage facility expansion WILLIAMS.J W Florida Power & Light Co 84/08/22 VARGA.S A Operating Reactors Branch I 28pp 26244 329 24X Fiche 50-250.84/08/22.8408270344
- 8408280238 Forwards add1 neutron source data for NRC review of pressurized thermal shock flux reduction program.per 840726 request WILLIAMS. J W Florida Power & Light Co 84/08/22 VARGA. S A Operating Reactors Branch I 36pp 26262 243 24% Ficher 50-250.84/08/22.8408280238
- O Inspection reports. IE Bulletins & correspondence
- 8408270287 Forwards Insp Repts 30-250/84-19 & 50-251/84-19 on 840604-08 No violations or deviations noted BANCE. H C Region 2. Office of Director 84/07/09 WILLIAMS. J W Florida Power & Light to 2pp 26258 167 24X Fiche 50-250.84/07/09.8408270289
- --8408270295 Insp Repts 50-250/84-19 & 50-251/84-19 on 840604-09 No violations or deviations noted Major areas inspected emergency preparedness MARSTON, R R , CLINE,W E Region 2, Office of Director 84/07/06 9pp 26258 169 24X Fiche 50-250,84/07/09,8408270289
- 8407250229 IE Infa Notice 84-37, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list end JORDAN. E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc. 119pp 25865 047 24% Fichs 50-000 84/07/27, 8407250229
- 408270314 Ack receipt of 840716 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-250/84-14 & 50-251/84-14
  LEHIS.R C Division of Project & Resident Programs 84/07/31
  HILLIAMS.J W Florida Power & Light Co 2pp 26257 263 24X
  Fiche 50-250.84/07/31.8408270314
- -8408270316 Responds to NRC 840615 ltr re violations noted in Insp Repts 50-250/84-14 & 50-251/84-14 Corrective actions tracking sys developed to ensure that all license amend requirements will be met during implementation pracess HILLIAMS. J W Florida Power & Light Co 84/07/16 O'REILLY, J P Region 2. Office of Director 4pp 26257 265 24% Fiche 50-250,64/07/31,8408270314
- 8408270322 Forward\* Insp Repts 50-250/84-14 & 50-251/84-14 on 840407-28 & notice of violation LEMIS.R C Division of Project & Resident Programs 84/06/15 WILLIAMS.J W Florida Power & Light Co 2pp 26257 269 24X Fiche 50-250,84/07/31.8408270314

- --8408270324 Notice of Violation from Insp on 840407-28 • Region 2, Office of Director 84/06/15 2pp 26257 271 244 Fiche 50-250,04/07/31,8408270314
- --8408270327 Insp Repts 50-250/84-14 & 50-251/84-14 on 840407-28 Violation noted clearance tags not properly filled out-hung or liftled & insufficient deta taken to complete evaluation of cooling sys

  PEEGLES, T A Region 2, Office of Director ELROD, S A Division of Project & Resident Programs 84/06/15 11pp 26257 273 24X Ficha 50-250, 84/07/31,8408270314
- 8408010333 IE Info Notice 84-37, "Deliberate Circumventing of Station Health Physics Procedures " Svc list enc) JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/04 Consolidated Edison Co of New York: Int 85pp 26048 001 24X Fiche 50-000,84/08/06.8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list enc! JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York: Inc 123pp 26067 158 24X Fiche 30-000:84/08/06.8408010337
- 8408070120 IE Info Notice 84-6), "Gverexposure of Diver in PWR
  Refueling Cavity " Svc list encl
  JDRDAN,E L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/08 Consolidated Edison Co. of New
  York Inc. 120pg 26129 118 24X Fichs 50-000.84/08/08.8408070120
- 8408070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list encl GRACE.J N Division of OA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000.84/08/10.8408070376
- 8408100009 [E Info Notice 84-63. "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (fost 830103) 84/08/13 Cansolidate Edison Co of New
  York Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408100038 IE Info Nutice 84-64, "BWR HPCI Initiation Seal-In & Indication" Svc list encl UDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list enc! JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24% Fiche 50-000,84/08/16.8408100021
- 8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24% Fiche 30-000,84/08/17,8408100055
- 8408140208 IE Info Notice 84-67. "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 64/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24% Fiche 50-000,84/08/17,8408140208
- 8408230148 Ack receipt of 840101.30.0216 & 0713 ltrs informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-250/83-35.50-251/83-28, 50-250/83-40, 50-251/83-39, 50-250/83-41 & 50-251/83-40
  LEWISIR C Region 2 Office of Director 84/08/17 WILLIAMS, J W Florida Power & Light Cn ip 26209 283 24X Fiche 50-250, 84/08/17.8409230148
- 8408310189 Forwards request for add1 info re inservice insp program Info needed to ensure conformance w/ASME Boiler & Pressure Vessel Code Section 11 Info should be provided within 30 days from receipt of ltr. VARGA.S A Operating Reactors Branch 1 84/08/17 WILLIAMS.J W Florida Power & Light Co 4pp 26350 359 24X Fiche 50-230.84/08/17.8408310189
- B409270384 Forwards responses to notice of violation & proposed imposition of civil penalty Corrective actions include implementation of performance enhancement program to address concerns re mgt control of operation Penalty paid WILLIAMS. J W Florida Power & Light Co 84/08/20 O'REILLY, J Region 2. Office of Director 11pp 26239 116 24X Fiche 50-250.84/08/20.8408270384

- B40B210142 IE Info Notice B4-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list enc) JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/0B/21 Consolidated Edisen Co. of New York, Inc. 1155p 26329 008 24X Fiche 50-000.84/08/21,8408210142
- S Reportable occurrences. LERs & related correspondence
- 8408030239 LER 84-019-00 on 840625, unit shut down due to RCS leak of approx 10 gpm Caused by packing leak due to broken gland follower on valve 3-532 Affected loop bistables tripped & valve 3-352 manually backseated W/840725 ltr HART.R D . WILLIAMS. J U Fiorida Power & Light Co 84/07/25 3pp 25917 217 24X Fiche 50-250,84/07/25,8408030239
- B408080230 LER 82-021/03L-0 on B20511, self-initiated audits revealed inadequate surveillance of emergency diesel generators for tests required by Tech Spec 4 8 1 a 5 Caused by Inadequate review of Operating Procedure 4304 1 W/840730 ltr HART,R D, WILLIAMS, J W Florida Power & Light Co 84/07/30 3pp 2974 357 24X Fiche 50-250,84/07/30,8408080230
- 8408140521 LER 84-020-00 on 840712 unit shut down due to RCS leak of approx 13 5 gpm Leakage caused by broken gland flange on valve 3-538 Valve packing gland flange replaced & all Rockwell 3/4-inch valves inspected W/840810 ltr LOVELL, J. WILLIAMS, J. W. Florida Power & Light Co. 84/08/10 3pp 24108 021 24% Fiche 50-250.84/08/10.8408160521
- B408200273 LER 84-021-00 on B40714 reactor tripped from subtritical condition. Caused by power interruption of source range nuclear instrumentation control power Personnel counseled H/ 840813 ltr LOVELL, J. WILLIAMS, J. H. Florida Power & Light Co. 84/08/13 3pp 26139 114 24x fiche 50-250.84/08/13.8408200273
- 8408270203 LER 84-022-00 on 840721 & 22, daily calibr of nuclear power range (thermal power calculation) not performed per Tech Specs Caused by personnel oversight Checks for calculations made & supervisory discussions held W/840820 ltr HART.R D , WILLIAMS.J W Floryda Power & Light Co 84/08/20 2pp 26297 336 24% Fiche 50-250,84/08/20,8408270203
- V Operator Examinations
- 8408300360 Summarizes 840426 meeting w/util in Region II ofc re eligibility criteria for certain candidates to take NRC senior operator license exam Attendance list encl LEWIS.R C Region 2. Office of Director 84/05/25 WILLIAMS, J W Florida Power & Light Co 3pp 26/308 198 24X Fiche 50-250,84/05/25,8408300360
- 8408310030 Forwards comments on equivalent cold license training program Requests addl info re hot license program Hot license program equivalent to cold license training for determining sligibility DANCC.H C Region 2, Office of Director 84/06/07 WILLIAMS, J W Florida Power & Light Co 3pp 26335 017 24X Fichs 50-250,84/06/07.8408310030
- 8408310064 Confirmation of action ltr re 840614 teleon conterning results of NRC operator exams on 840430 Operators who failed exam prohibited from performing licensed duties until Sections & & 7 completed satisfactorily O'REILLY, J P. Region 2, Office of Director 84/06/18 WILLIAMS, J W. Carolina Power & Light Co. 2pp. 26334 349 24X Fichs 50-250,84/06/18,8408310064
- 8408310425 Forwards summary of NRC 840627 meeting w/util in Region II ofc re util plans for training program improvements DANGE.H C Region R. Office of Director 84/07/24 WILLIAMB.J W Florida Power & Light Co 5pp 26335 024 24X Fiche 50-250.84/07/24.8408310425
- DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

  F Security, medical, emergency & fire protection plans
- 8408010109 Informs that proposed schedules for implementation of alternate shutdown capability & mods for App R. Section III G in accordance w/10CFR50 48 & require no schedular exemptions
  VAR9A.5 A Operating Reactors Branch 1 84/07/09 WILLIAMB, J W Florida Power & Light Co 3pp 25873 352 24X Fiche 50-250.84/07/09.8408010109
- 8408270289 Forwards Insp Repts 50-290/84-19 & 50-251/84-19 on 840604-08 No violations or deviations noted DANCE, H C Region 2. Office of Director 84/07/09 WILLIAMS, J W Florida Power & Light Co 2pp 26258 167 24% Fichs 50-290,84/07/09.8408270289

- --8408270295 Insp Repts 50-250/84-19 % 50-251/84-19 on 840404-08 No violations or deviations noted Major areas inspected emergency preparedness MARSTON.R R Region 2. Office of Director 84/07/06 9pp 26258 169 24X Fiche 50-250.84/07/09.8408270289
- 8408100016 Forwards Emergency Plan Implementing Procedure EPIP-1301.
  "Emergency Roster Offsite Emergency Organization"
  WILLIAMS, J W Florida Power & Light Co 84708/08 0'REILLY, J P
  Region 2. Office of Director ip 25987 004 24X
  Fiche 50-000.84/08/08.8408100016
- --8408100054 Emergency Plan Implementing Procedure EPIP-1301, "Emergency Roster - Offsite Emergency Organization" JOHNSON, H D Florida Power & Light Co 84/08/08 13pp 25987 007 24X Fichs 30-000.84/08/08.8408100014
- 8408240328 Confirms B40829 meeting in Bethesda. MD to discuss task analysis requirements of NUREG-0737. Suppl 1 & SER open items on GEN-152 re inadequate core cooling & reactor vessel level monitoring sys THOMPSON.H L Division of Human Factors Safety 84/08/13 BARRIGM. J Florida Power & Light Co 1p 26253 336 24X Fiche 50-250.84/08/13.8408240328
- ---8408240330 Notification of 840829 meeting w/util in Bethesda.MD to discuss task analysis requirements of NUREG-0737. Suppl 1 & SER open items on CEN-152 re inadequate core cooling & reactor vessel level monitoring sys CLAYTON.H B Procedures & Systems Review Branch 84/08/09 ZIEMAN.D L Procedures & Systems Review Branch 2pp 26253 337 24X Fiche 50-230.84/08/13.8408240328
- 840B310003 Forwards request for add1 info re safety parameter display sys implementation plan & parameter selection rept submitted in B40501 response to Generic Ltr 82-03 (NUREO-0737, Buppl 1) Response requested within 45 days VAROA. B A Operating Reactors Branch 1 D4/08/19 WILLIAMB, J W Florida Power & Light Co 4pp 26350 202 24X Fiche 50-250.84/08/15.840B310003
- B408310133 Revs to emergency plan implementing procedures, including 2010, "Duties of Emergency Coordinator," 20201, "Maintaining Emergency Preparedness Radiological Emergency Plan Training" & 20126, "Offsite Dose Calculation" W/840824 1tr WILLIAMS. J W Floride Power & Light Co 24/08/24 0'REILLY, J P Region 2. Office of Director 108pp 26322 001 24% Fiche 50-250,84/08/24,8408310133

#### G Adjudicatory correspondence

- 8408010213 Response supporting J Lorion & Ctr for Nuclear Responsibility 840709 request for hearing & petition for leave to intervene re amends to expand spent fuel pool Notice of appearance & Certificate of Byc encl YOUNG M A Hearing Branch 4 DSB 676 84707/30 Atomic Bafety and Licensing Board Panel 12pp 25856 040 24X Fichs 50-250,84/07/30,8408010213
- B40B070305 Response supporting Ctr for Nuclear Responsibility request for hearing & petition for leave to intervene re amends to allow storage of fuel w/increased enrichment Notice of appearance & Certificate of Svc encl YOUNO-M A Hearing Branch 4 DSB B10 84/07/31 Atomic Bafety and Litensing Board Panel 12pp 25947 314 24X Fiche 50-250,84/07/31 B40B070305
- 8408090397 Notice of appearance in proceeding Certificate of Svc ancl COLL,N A Florida Power & Light Co COLL,N A. Step1. Hector & Davis DSN 878 8408/07 3pp 25982 173 24% Fiche 50-250.84/08/07.8408090397
- 8408090437 Notice of appearance in proceeding Certificate of Bvc and CDLL,N A Fibrida Power & Light Co COLL,N A Steel, Hector & Davis DSB 879 84/08/07 Atomic Safety and Licensing Board Panel 3pp 25982 176 24× Ficher 50-250,84/08/07,8408090437
- B40B140214 Forwards 840B10 motions for summary disposition of intervenor Contentions (b) & (d) & statement of matl facts & memorandum of law in support of motions Related correspondence
  BAUSER, M A Neuman & Holtzinger BAUSER, M A Florida Power & Light Co DBB 961 B470B710 LAZOR M , COLER F , LUEBKE, E A Atomic Safety and Licensing Board Panel ip 26056 024 24X Fiche 50-250,8470B710,840B140214
- --B40B140220 Motion for summary dispositon of intervenor Contention b No genuine issue of matl fact exists & util entitled to favorable decision Related correspondence BAUSER, M A Florida Power & Light Co BAUSER, M A Newman & Holtzinger 64/08/10 Atomic Safety and Licensing Board Panel Spp 26056 025 24X Fiche 50-250,84/08/10,8408140214

- --B408140226 Affidavit of MJ Parvin in support of applicant B40810 motion for summary dispositon of intervenor Contention (6) Related torraspondance PARVIN.M J Florida Power & Light Co PARVIN.M J Westinghouse Electric Corp B4/0B/03 App 26056 030 24X Fiche 50-250,84/08/10,8408140214
- --B40B140236 Statement of matl facts as to which there is no genuine issue Related correspondence BAUSER.M A Florida Power & Light Co BAUSER.M A Newman & Holtringer BAUSER.M A Steel Mector & Davis 84/08/10 Atomic Safety and Licensing Board Panel 3pp 26056 036 24X Fiche 30-250,84/08/10.8408140214
- --8408140253 Motion for summary dispositon of intervenor Contention (d)
  No genuine issue of natl fact exists & util entitled to
  favorable decision Related correspondence
  BAUSER:N A Florida Power & Light Co BAUSER:M A Newman &
  Holtzinger BAUSER:M A Steel, Hector & Davis 84/08/10
  Atumic Safety and Licensing Board Panel 8pp 26056 039 24X
  Fiche 50-250,84/08/10,8408140214
- --8408140262 Affidavit of EA Dienis in support of licenses 840810 motion for summary disposition of intervenor Contention (d) Realted correspondence DZENIS,E A Florida Power & Light Co DZENIS,E A Westinghouse Electric Corp 84/08/08 15pp 26056 047 24X Fiche 50-250,84/08/10,8408140214
- --840B140271 Statement of natl facts as to which there is no genuine issue re intervenor Contention (d) Related correspondence BAUSER. M A Florida Power & Light Co BAUSER. M A Newman & Holtzinger 84/08/10 Atomic Safety and Licensing Board Panel 7pp. 26056 062 24X Fiche 50-250.84/08/10.8408140214
- --8408140277 Memorandum of law in support of motions for summary disposition of intervenor Contentions (b) & (d) Centificate of Svc encl Related correspondence BAUSER, M A Florida Power & Light Co BAUSER, M A Newman & Holtzinger BAUSER, M A Steel, Hector & Davis B4/0B/10 Bp. 24056 069 24X Fiche 50-250,84/0B/10,8408140214
- 8408210347 Notice of appearance in proceeding Certificate of Svc encl REIS.H F Florida Power & Light Co REIS.H F Newman & Holtzinger D88 178 84/08/16 3pp 26179 180 24X Fiche 50-250.84/08/16, B408210347
- B40B210380 Notice of appearance in proceeding Certificate of Svc encl REIS.H F Florida Power & Light Co REIS.H F Newman & Holtringer D8B 180 84/08/16 3pp 26180 248 24x Fiche 50-250, B4/08/16. B40B2103B0
- H. General correspondence
- 8408210441 Informs of address change for plant manager PEEBLES.T A Florida Power & Light Co 84/08/15 NRC No Detailed Affillation Given 2pp 26181 256 24X Fiche 50-250,84/08/15.8408210441
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8407260218 Forwards Rev 2 to updated FSAR for Turkey Point, Units 3 & 4 Changes made under provisions of 10CFR30 59 for Jul 1983 June 1984 will be provided by 800701 HILLIAMS, J W Florida Power & Light Co 84/07/23 DENTON, H R Office of Nuclear Reactor Regulation, Director App 25771 129 24X Fichs 30-250, 84/07/23, 8407260218
- --8407260220 Rev 2 to updated FSAR for Turkey Point, Units 3 & 4 \* Florida Power & Light Co. 84/07/31 425pp 25771 133 24X Fiche. 50-250, 84/07/23, 8407260218
- P Operating license stage documents & correspondence
- 8408300382 Summarizes 840517 meeting w/util in Region II of: re plant performance anhancement program Meeting beneficial & provided better understanding of plans D'REILLYJP Region 2. Office of Director 84/05/25. WILLIAMS, J W Florida Power & Light Co ip 26308 160 24X Fiche 50-280,84/05/25,8408300382
- B40B300417 Summarizes B40618 meeting w/util in Region II ofc reperformance enhancement program & quarterly progress rept meeting scheduled for 840712
  DANCE.H C Region 2. Office of Director 84/06/25 WILLIAMS.J W Florida Power & Light Co ip. 26313 307 24X Fiche 50-250, 84/06/25.8408300417

- 8408010117 Forwards request for add1 info re measures taken to ensure ALARA doses during proposed spent fuel pool expansion Response within 30 days of ltr receipt requested VARGA. S A Operating Reactors Branch 1 84/07/19 WILLIAMS, J W Florida Power & Light Co 6pp 25873 321 24X Fiche 50-250.84/07/19.8408010119
- B40B060436 Summary of 840713 meeting w/util in Bethesda, MD re reactor matts surveillance program MCDDNALD, D G Operating Reactors Branch 1 84/07/19 Operating Reactors Branch 1 3pp 25937 317 24X Fiche 50-250, 84/07/19, 8408060436
- 8408070032 Corrects issuance date of itr re proposed spent fuel pool expansion to 840702 MCDONALD, D 0 Operating Reactors Branch 1 84/07/19 WILLIAMS, J W Florida Power & Light Co 2pp 25755 360 24X Fiche 50-250.84/07/19.8408070032
- 8408010005 Request correction to date of ltr, forwarded on 840602, requesting info on NUREO-0737, Item JI D 1 re performance testing of relief & safety valves Correct date is 840702 VARQA, B A Operating Reactors Branch i 84/07/23 MCDONALD, R P Alabama Power Co 2pp 25867 361 24X Fiche 50-250,84/07/23, 8408010005
- 8408070075 Forwards request for additutor e pressurized thermal shock flux reduction program Response requested within 3 wks of ltr receipt W/o encl. VARGA. B A Operating Reactors Branch 1 84/07/26 WILLIAMS, J W Florida Power & Light Co. 2pp. 25955 317 24% Fiche 50-250.84/07/26.8408070075
- 8408090491 Requests remittance of fee for review of 840521 application for amend to Tech Specs re safety-related southers
  DIGOS.R M License Fee Management Branch 84/07/31 WILLIAMS.J W
  Florida Power & Light Co ip 25983 152 24X Fiche 50-250.
  B4/07/31.8408090491
- B40B070ilO Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl i to NUREO-0933, "Prioritization of Generic Safety Issues " Svc list encl EISENHUT, D © Division of Licensing B4/08/06 Consolidated Edison Cu of New York, Inc 18pp 26127 238 24X Fiche 30-000,84/08/06,8408070110
- B40B090317 Forwards monthly status rept re plant-specific backfilting activities for operating reactors & license applicants for Jul 1984
  TREMBLAY, P P Operating Reactors Assessment Branch 84/08/06
  HOLAHAN, G M Operating Reactors Assessment Branch 13pp
  25991 390 24X Fiche 30-000, 84/08/06, 8408070317
- 8408160319 Forwards "Maint & Burveillance Program Plan," revised following 840706 NRC/NUMARC meeting RUSSELL,W T Division of Human Factors Safety 84/08/07 WOODY,C D Florida Power & Light Co ip 26124 019 24X Fiche 50-000,84/08/07,8408160319
- B40B210634 Requests add1 info re structural design aspects of 830314 request for Tech Spec mod to expand spent fuel storage facilities Mod necessary to accommodate increased inventory Add1 info requested within 2 was to meet review schedule VARGA.B A Operating Reactors Branch 1 84/08/13 WILLIAMS.J W Florida Power & Light Co ip 26187 396 24% Fiche 50-250. 84/08/13,8408210634
- 8408170084 Forwards addl info re spent fuel storage facility expansion, per NRC 840702 request NITAML.XBDRNPM & Keno-IV used to calculate reactivity of checkerboard & configuration in Region 2 WILLIAMS.J W Florida Power & Light Co 84/08/14 VAROA,8 A Operating Reactors Branch i 7pp 26119 024 24X Fiche 30-230,84/08/14,8408170084
- B40B210364 Forwards draft safety evaluation of NUREO-0737, item II F 2 re inadequate core cooling instrumentation sys Evaluation identifies open items Addl info requested within 2 wks W/o encl VAROA.B A Operating Reactors Brench i 84/08/14 WILLIAMS, J W Florida Power & Light Co ip 26195, 255 24X Fiche 50-250, B4/08/14, 8408210564
- 8408230477 Forwards Amends 104 & 98 to Licenses DPR-31 & DPR-41, respectively & safety evaluation Amends provide protection of safety-related equipment subjected to degraded voltage at offsite power source W/O encls
  MCDQNALD, D 0. Operating Reactors Branch 1 84/08/14 WILLIAMS, J W Florida Power & Light Co 1p 26230 216 24X
  Fiche 50-250.84/08/14.8408230477

- 8408230564 Notification or 840996 & 07 meetings w/util in Bethesda.MD to discuss control room design reviews MCDDMALD,D G Derating Reactors Branch I 84/08/16 VARGA.S A, MILLER,J R Operating Reactors Branch I 2pp 26230 260 24% Fiche 50-000.84/08/16,8408230564
- 8408220546 Notification of 840823 meeting w/util in Bethasda.MD to discuss details & review process for converting facility. Tech Specs to 978 format & content for Westinghouse reactors. MCDONALD, D.G. Operating Reactors Branch | 84/08/17 VARGA, S.A. Operating Reactors Branch | 24/08/17 VARGA, S.A. Fiche 50-250, 84/08/17, 8408220546
- 8408270015 Requests meeting w/NRC to discuss details of proposed Tech Bpec rev program, including purpose for rev.plan & schedule, integration w/related projects, limitations & licensing approach WILLIAMS, J W Florida Power & Light Co 84/08/17 EISENHUT, D Q Division of Licensing 1p 26247 193 24X Fiche 50-250,84/08/17, 8408270015
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000.84/08/20,8408200275
- 8408270019 Forwards remittance for 840615 request for amends in response to Generic Ltr 83-37 re NUREO-0737 Tech Specs, per 10CFR170 22 WILLIAMS, J W Florida Power & Light Co 84/08/21 EISENHUT, D G Division of Licensing ip 26247 194 24X Fiche 50-250.84/08/21, 8408270019
- 8408270344 Forwards response to NRC 840719 requests for addl info re health physics aspects of proposed amend to spent fuel storage facility expansion WILLIAMS.J W Florida Fower & Light Co 84/08/22 VARGA.S A Operating Reactors Branch 1 28pp 26244 327 24X Fiche 50-250.84/08/22.34408270344
- 8408280238 Forwards add1 neutron source data for NRC review of pressurized thermal shock flux reduction programs per 840726 request WILLIAMS. J W Florida Power & Light Co 84/08/22 VARGAS A Operating Reactors Branch 1 35p 26262 243 24X Fiche 50-250.84/08/28.8408280238
- O Inspection reports, IE Bulletins & correspondence
- 8408270289 Forwards Insp Repts 50-250/84-19 & 50-251/84-19 on 840604-08 No violations or deviations noted DANCE,H C Region 2. Office of Director 84/07/09 WILLIAMS,J W Florida Power & Light Co 2pp 24258 167 24X Fiche 50-250.84/07/09.8408270289
- --8408270273 Insp Repts 50-250/84-19 & 50-251/84-19 on 840604-08 Na violations or deviations noted Major areas inspected emergency preparedness MARSTON,R R. CLINE. W E Region 2. Office of Director 84/07/06 9pp 26258 169 24X Fiche 50-250,84/07/09,8408270289
- B407250229 IE Info Notice 84-57. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 23865 047 24X Fiche 50-000,84/07/27,8407250229
- 8408270314 Ack receipt of 840716 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-250/84-14 & 50-251/84-14 LEWIS.R C Division of Project & Resident Programs 84/07/31 WILLIAMS.J W Floride Power & Light Co 2pp 26257 263 24X Fiche 50-250,84/07/31,8408270314
- --8408270316 Responds to NRC 840615 ltr re violations noted in Insp Repts 50-250/84-14 & 50-251/84-14 Corrective actions tracking sys developed to ensure that all license amend requirements will be met during implementation process WILLIAMS, J W Florida Pawer & Light Co 84/07/16 D'REILLY, J P Region 2. Office of Director 4pp 26257 265 24X Fiche 50-250,84/07/31,8408270314
- --8408270322 Forwards Insp Repts 50-250/84-14 & 50-251/84-14 on 840407-28 & notice of violation LEMISR C Division of Project & Resident Programs 84/06/15 WILLIAMS, J W Fibrida Power & Light Co 2pp 26257 269 24X Fiche 50-250,84/07/31,8408270314

- --8408270324 Notice of violation from insp on 840407-28 # Region 2, Office or Director 84/06/15 2pp 26257 271 24% Fiche 50-250, 84/07/31, 8408270314
- --8408270329 Insp Repts 50-250/84-14 & 50-251/84-14 on 840407-28 Violation noted clearance tags not properly filled out-hung or lifted & insufficient data taken to complete evaluation of cooling sys
  PEEBLES.T A Region 2, Office of Director ELROD, S A Division of Project & Resident Programs 84/06/15 11pp 26257 273 24X Fiche 50-250,84/07/31.8408270314
- B40B010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York Inc 85pp 26068 001 24X Fiche 50-000.84/08/06,840B010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Past 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06.8408010337
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fiche 50-000.84/08/08.8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 feletherapy Treatments " Svc list enc! GRACE, J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolldated Edison Co of New York, Inc 125pp 26130 001 24% Fiche 50-000.84/08/10.8408070376
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list enc!
  JURDAN E C Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000-84/08/13, 8408100009
- 8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication "Svc list encl JORDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc. 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038
- 840B100021 JE Info Notice B4-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Syc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc. 118pp 26198 001 24X Fichs 50-000,84/08/16,8408100021
- 8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN:C L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- B40B14020B IE Info Notice 84-67, "Recent Enubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN: E. Division of Emergency Preparedness & Engineering Response (Post 800103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp. 26276 122 24X Fiche 50-000;84/08/17;8408140208
- BAOB23014B Ack receipt of 840101,30,0216 & 0713 ltrs informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-250/83-32,50-251/83-29, 50-250/83-40,50-251/83-39, 50-250/83-40 & 50-2
- 8408230151 Ack receipt of 840806 ltr informing NRC of steps taken to correct violations noted in IE Imap Rept 50-251/84-21 Corrective actions will be examined during future imap LEWIB, RC Region 2. Office of Director 84/08/17 WILLIAMS. J W Florida Power & Light Co ip 26207 284 24X Fiche. 50-251, 84/08/17,8408230151
- --B408230155 Responds to NRC B40705 ltr re violations noted in IE Insp Rept 50-251/84-21 Corrective actions temporary sys alteration documentation required by Administrative Procedure 103 3 completed & personnel counseled WILLIAMS.J W Florida Power & Light Co. B4/08/06 O'REILLY.J. P Region 2. Office of Director 2pp 26209 285 24X Fiche 50-251,84/08/17,8408230151

- ~-8408230158 Forwards IE Insp Rept 50~251/84~21 on 840604~06 & notice of violation LEWIS.RC Region 2. Office of Director 84/07/05 WILLIAMS.J W Florida Power & Light Co 3pp 26209 287 247 Fiche 50~251,84/08/17.8408230151
- ~-8408230161 Notice of violation from insp on 840604~06 \* Region 2, Office of Director 84/07/05 ip 26207 270 24x Fiche 50-251,84/08/17,8408230151
- --8408230166 IE Insp Rept 50-251/84-21 on 840604-06 Violations noted failure to follow plant procedure for temporary sys alteration FALCOMER.D P , KRUG.H E Region 2, Office of Director 84/07/02 7pp 26209 291 24x Fiche 50-251.84/08/17.8408230151
- 8408310189 Forwards request for add1 info re inservice insp program
  Info needed to ensure conformance w/ASME Boiler & Pressure
  Vessel Code Section 11 Info should be provided within 30
  days from receipt of ltr
  VARGA-5 A Operating Reactors Branch | 84/08/17 WILLIAMS, J W
  Florida Power & Light Co 4pp 26350 399 24X
  Fithe 50-250.84/08/17.8408310189
- 8408270384 Forwards responses to notice of violation & proposed imposition of civil penalty Corrective actions include implementation of performance enhancement program to address concerns re mgt control of operation Penalty paid HILLIAMS, J W Florida Power & Light Co 84/08/20 O'REILLY, J P Region 2, Offics of Director lipp 26/37 116 24X Fiche 50-250,84/08/20,8408270384
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Miring to Solenoid Valves" Svc list encl JURDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc. 115pp 26329 008 24% Fiche 50-000;84/08/21,8408210142
- S Reportable occurrences, LERs & related correspondence
- 8408010311 LER 84-014-00 on 840626, reactor tripped from hot shutdown conditions while unit subcritical for prectice startups Caused by failure of source range detector N-32 Detector replaced M/840725 ltm HART, R D . WILLIAMS.J W Florida Power & Light Co 84/07/25 3pp 28866 159 24% Fiche 50-251, 84/07/25,8408010311

#### V Operator Examinations

- 8408300360 Summarizes 840424 meeting w/util in Region II ofc re eligibility criteria for certain candidates to take NRC senior operator license exam Attendance list encl LEMIS.R C Region 2: Office of Director 84/03/25 WILLIAMS.J W Florida Power & Light Co 3pp 24308 198 24X Fiche 80-250.84/03/25.8408300350
- B40B310030 Forwards comments on equivalent cold license training program Requests additing are but license program Hot license program equivalent to cold license training for determining eligibility

  DANCE.H C Region 2. Office of Director 84/06/07 WILLIAMS, J W Florida Power & Light Co 3pp 26335 017. 24X

  Fiche 50-230.84/06/07.8408310030
- 8408310064 Confirmation of action ltr re 840614 teleon concerning results of NRC operator exams on 840430 Operators who failed exam prohibited from performing licensed duties until Sections 6 % 7 completed tatisfactorily O'REILLY, J.P. Region 2, Deffice of Director B4/06/18, WILLIAMS, J.W. Carolina Power & Light Co. 2pp 26334 349 244 Fiche 50-250,84/06/18,8408310064
- 8408310429 Forwards summary of NRC B40627 meeting w/otil in Region II ofc resutil plans for training program improvements DANCE.H C Region 2: Office of Director 84/07/24, WILLIAMS, J W Florida Power & Light Co. 5pp 26335 024 24X Fiche 50-250,84/07/24,8408310429
- DOCKET 50-252 UNIV OF NEW MEXICO RESEARCH REACTOR
  F. Security, medical, emergency & fire protection plans
- 8408090525 Approves 840717 request for 30-day extension for resubmittal of revised emergency plan Revised plan expected by 840920 THOMAS: C O Standardization & Special Projects Branch 84/08/01 WHAN.6 A New Maxico. Univ. of. Albuquerque, NM 3pp 23983 123 Fiche 50-252,84/08/01,8408090525

- DOCKET 50-254 GUAD CITIES STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- B40B140139 Forwards listed revs to security plans Revs address fence height requirements Revs withheld (ref 10CFR73 21) FARRAILD L Commonwealth Edison Co 84/08/03 Region 3, Office of Director 1p 26044 252 24X Fiche 50-000,84/08/03,8408140139
- 8408140365 Revised emergency implementing procedures, including Rev 7 to GEP 180-0 re shift engineer, Rev 6 to GEP 180-0 re Rad-Chem director & Rev 17 to GEP 200-0 re emergency conditions \* Commonwealth Edison Co 84/08/04 84pp 26041 032 24X Fiche 50-294, 84/08/04,8408140365
- 8408130401 Responds to 840705 clarification of info re util means of satisfying amoual regulatory requirement to review emergency action levels w/offsite emergency support organizations Info acceptable PAPERIELLO.C J Region 3, Office of Director 84/08/07 REED.C Commonwealth Edison Co ip 26010 130 24% Fiche 50-000,84/08/07,8408130401
- --8408130413 Responds to 840604 ltr re means for satisfying requirements of 10CFR50. App E.Paragraph IV B Proposal for satisfying requirements to review emergency action levels by offsite agencies clarified FARRAR. D. L. Commonwealth Edison Co. 84/07/05 PAPERIELLO, C. J. Region 3. Office of Director 8pp 26010 131 24X Fiche 80-000,84/08/07,8408130401
- 8408200249 Advises that 840803 Rev 15 to physical security plan consistent u/provisions of IOCFR50 54(p) & acceptable AXELSON.k L Region 3. Office of Director 84/08/14 FARRAR, D L Commonwealth Edison Co 2pp 26133 190 24X Fiche 50-254.84/08/14, 8408200248
- 8408230270 Revised emergency plan implementing procedures including Rev 23 to GEP-310-0, "Notification of Responsible Authorities," & Rev 13 to GEP 310-T3, "Prioritical Notification Listing " W/rev receipt form # Commonwealth Edison Co 84/08/16 11pp 26209 323 24% Fiche 50-254.84/08/16,8408230270
- P Operating license stage documents & correspondence
- 8408150411 Grants 840527 request for extension until 851001, but no later than 851130, for replacement of four Limitorque actuator motors & qualification of MSIV selencid operators DENTON. H R Office of Nuclear Reactor Regulation. Director 84/07/30 FARRAR.D L Commonwealth Edison Co 3pp 26105 357 24% Fiche 50-254.84/07/30,8408150611
- 8408050425 Notification of 840809-10 meetings w/utils.NUTECH.Franklin Research Ctr & INL in San Jose.CA to discuss comments resulting from post-implementation review re plant-unique analysis repts BEVAN.R B , ROONEY, V L , THADANI.M C Operating Reactors Branch 2 84/07/31 VASSALLO, D B Operating Reactors Branch 2 1p 23937 335 24X Fiche 50-000,84/07/31,8408060425
- B408140317 Forwards response to B40626 request for add1 info re 125-volt dc sys Facility recently completed replacement of 125-volt battery chargers w/200 ampere-rated units RYBAX.B Commonwealth Edison Ca 84/08/01 DENTON,H R Office of Nuclear Reactor Regulation, Director 17pp 26042 333 24X Fiche 50-254.84/08/01.8408140317
- 8408130588 Forwards Amend 90 to License DPR-29 & safety evaluation Amend incorporates new MAPLHOR curves for new linear fuel & changes calibr & functional test frequencies for Instrumentation BEVAN.R 8 Operating Reactors Branch 2 84/08/02 FARRAR, D L Commonwealth Edison Co. 2pp 26106-025 24X Fithe 50-254,84/08/02,8408180588
- ~-8408150893 Amend 90 to License DPR-29, incorporating new MAPLHOR curves for new linear fuel change calibr & functional test frequencies for instrumentation & adding new Yech Specs remodified scram discharge sys VABBALLO, D O Operating Reactors Branch 2 84/08/02 23pp 26104 027 24X Fiche 50~254,84/08/02,8408150588
- ~-8408150597 Safety evaluation supporting Amend 90 to License DPR-29 \* Office of Nuclear Reactor Regulation, Director 84/08/02 4pp 26106 050 24% Fiche 50-254.84/08/02.8408150588

- 8408160465 Forwards 840802 SER re IGSCC insp & repair IGSCC insp & repair performed in accordance w/Generic Ltr 84-11
  Insp &/or mod plans in util 840730 Itr meet requirements
  VASSALLO, r B Operating Reactors Branch 2 84/08/02 FARRAR, D L
  Commonwealth Edison Co 2pp 26120 349 24X Fiche 50-254,84/08/02,840816045
- --B40B160467 Safety evaluation re reinsp % repairs of RCS piping Plant can be safely returned to power % operated in present configuration for one 18-month fuel cycle \* Office of Nuclear Reactor Regulation. Director 84/08/02 11pp 26120 351 24X Fiche 50-254.84/08/02.8408160465
- 8408070110 Generic Ltr 84-i9 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of Suppl 1 to NUREO-0933, 'Prioritization of Generic Safety Issues' Svc list encl EISENHUT, D @ Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000.84/08/06.8408070110
- 840Bi60345 Advises that QA program applicable to all nuclear generating stations 2 satisfies provisions of 10CFR71 Fee remitted per 10CFR170 31 FARRAR, D. L. Commonwealth Edison Co. 84/08/06 Office of Nuclear Material Safety & Safeguards, Director ip 26072 184 24X Fiche 30-000, 84/08/06, 840Bi60345
- B408270114 Provides supplemental response to Generic Ltr B3-36, "NUREG-0737 Tech Specs " Mods to Guad Cities radiological ETS will not be complete until Fall 1984 Complete response w/amend requests expected by 841115 ALEXANDER, G L Commonwealth Edison Co 84/08/15 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 26247 330 24X Fiche 50-000,84/08/15,8408270114
- 8408200275 Generic Ltr 84-20 to all licenses of operating reactors & applicants for OLs re scheduling guidance for licenses submittals of reloads that involve unreviewed safety questions Svc list encl EISEMHUT, D © Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp. 26276 244 24X Fiche 50-000,84/08/20,8408200275
- 8408310203 Suppl to 830217 application for amend to Licenses DPR-29 & DPR-30, revising Tech Specs to incorporate listed changes reflecting rev to 10CFR50 72 & new Section 50 73 LER reporting requirements, per Generic Ltr 83-43 RYDAK.B Commonwealth Edison Co 84/08/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 26320 245 24X Fiche 50-234,84/08/23,8408310203
- --8408310206 Proposed Tech Spec changes reflecting revised 10CFR50 72 & new Section 50 73 LER reporting requirements \* Commonwealth Edison Co 84/08/23 42pp 26320 231 24X Fiche 50-294,84/08/23,8408310203
- B40B310211 Forwards final response to second & final set of questions re Mark I containment plant-unique analysis RYBAK.B Commonwealth Edison Co. B4/08/24 DENTON, H.R. Office of Noclear Reactor Regulation, Director 37pp 26318 072 24X Fiche 50-000, 84/08/24, 840B310211
- Q Inspection reports: IE Bulletins & correspondence
- 8408060065 Commits to performing visual exam of reactor coolant piping during each outage in which containment deinerted, per Generic Ltr 94-11 RYBAK.B Commonwealth Edison Co 84/07/25 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 25933 103 24X Piche 50-254,84/07/25,84080606065
- 8408150392 Forwards IE Insp Repts 50-254/84-10 & 50-265/84-09 on 840625-28 & 0706 No noncompliance noted PAPERIELLO.C J Region 3. Office of Director 84/07/26 REED,C Commonwealth Edison Co 2pp 26077 340 24% Fiche 50-254,84/07/26.8408150392
- --8408150401 IE Insp Repts 50-254/84-10 & 50-265/84-09 on 840625-28 & 0706 No violations or deviations noted Major areas inspected confirmatory measures; radiological environ monitoring program & licensee actions on open items ROZAK.S. CESTMANN.M J. SCHUMACHER.M C. Region 3, Office of Director 84/07/25 10pp 26077 242 24X Fiche 50-254,84/07/26,8408150392
- 8407250227 IE Info Notice 84-57. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JDRDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25845 047 24X Fiche 50-000,84/07/27,8407250229

- B4080&0108 Advises that plans for insps.corrective actions &/or mods.including replacement of recirculation & piping.will be submitted 90 days prior to next refueling outage.per B40604 & 0725 commitments

  RYBAK.B Commonwealth Edison Co 84/07/30 DENTON.H R Defice of Nuclear Reactor Regulation. Director 1p 25933 179 24X Fishe 50-254.B4/07/30.B40806018
- 8408070026 Notifies of 840823 meeting w/util at Region III ofc to review findings of SALP assessment re util performance Encourages mgt representation to ensure mutual understanding of issues 2 findings presented by NRC NORELIUS.C E Region 3, Office of Director 84/08/03 REED.C Commonwealth Edison Co 2pp 25949 337 24X Fiche 50-000.84/08/03, 84/08/04.
- 8408230549 Forwards IE Insp Repts 50-254/84-08 & 50-265/84-07 on 840520-0623 & notice of violation Type A tests must be conducted during each refueling outage.unless request & granted exemption from requirement received NORELIUS.C E Region 3. Office of Director 84/08/03 REED.C Commonwealth Edison Co. 2pg 26213 005 24% Fiche 50-254,84/08/03.8408210549
- --8408230351 Notice of violation from insp on 840820-0623 NORELIUS.C E Region 3. Office of Director 84/08/03 2pp 26213 007 24X Fiche 50-254.84/08/03.8408230549
- ---8408230555 IE Insp Repts 50-254/84-08 & 50-265/84-07 on 840520-0623 Noncompliance noted failure to local leak rate test gasketed penetration & failure to quantify leakage during integrated leak rate test CHRISSOTIMOS, N Region 3, Office of Director 84/07/23 9pp 26213 007 24X Fiche 50-254.84/08/03.8408230549
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc. 85pp 26068 001 24% Fiche 50-000,84/08/06.8408010333
- B408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Neet Efficiency Requirement " Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4708/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24% Fiche 50-000.84/08/06.8408010337
- B408070120 IE Info Notice B4-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/08/08 Consolitated Edison Co of New York
- 8408140344 Confirms 840803 plans to meet w/util on 840707 in Olen Ellyn, fl. to discuss regulatory improvement program NDRELIUS.C E Region 3, Office of Director 84/08/08 REED.C Commonwealth Edison Co 2pp 26041 050 24X Fiche 50-000,84/08/08,8408140344
- 840B150098 Suppls 840711 response to IE Bulletin 84-02 re visual insp during monthly functional tests to verify proper contact on reactor trip sys & primary containment isolation sys relays Exemptions requested for listed relays ALEXANDER: 0 L Commonwealth Edison Co 84/08/08 KEPPLER: J Q Region 3, Office of Director 3pp 26067 053 24X Fiche 30-000:84/08/08:840B150078
- B408200331 Suppls response to IE Bulletin B4-02 re failure of MFA relays Exemption requested from commitment for Visua inspiverifying proper relay contact during monthly functional check for listed relays ALEXANDER: 0 L Commonwealth Edison Co B4/08/07 Region 3. Office of Director Jpp 26432 318 Fisher Do-000.84/08/08 B408200331
- 8408070376 IE Info Notice 84-62. "Therapy Misadmi Patients Undergoing Co-60 Yeletherapy Treatment list enc! ORACE.J N Division of GA, Safeguards & Inspec 830103) 84/08/10 Consolidated Edison Co 125pp 26130 001 24X Fiche 50-000.84/08/10.8
- B40B100009 IE Info Notice 84~63, "Defective RHR R Svc list entl JORDAN.C L Division of Emergency Preparedness Response (Post B30103) B4/08/13 Comsolida York, Inc 119pp 26197.218 24X Fiche 30-00

- 840B2800B0 Forwards Insp Rept 50-254/84-12 on 840720-26 No noncompliance noted Confainment integrated leak rate test exceeded App J limit due to leakage in HFCI turbine exhaust valve & MSIV Type A test must be performed at neit outage LITILE.W S Region 3. Office of Director 84/08/13 REED.C Commonwealth Edison Co 2pp 26261 199 24X Fiche 50-254,84/08/13,8408280080
- --8408280083 Insp Rept 50~254/84~12 on 840720-25 No noncompliance or deviations noted Major areas inspected containment integrated leak rate test HARE,S M. GULDEMOND,W G. Region 3, Office of Director 84/08/10 5pp 24261 201 24x Fiche 59-254,84/08/19,8408280080
- 840B10003B IE Info Notice 84-54, "BWR HPCI Initiation Seal-In & Indication " Svc list enc!
  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co. of New York, Inc. 104pp 26198 093 24X Fichs 50-000.84/08/15,840810003B
- B40B100021 IE Info Notice B4-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Syc list encl list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc. 118pp. 26198 001 24X Fiche 50-000,84/08/16.8408100021
- 8408100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 001 24X Fiche 50-000.84/08/17,8408100055
- 8408140208 IE Info Notice 84-67. "Recent Shubber Inservice Testing W/ High Failure Rates " Syc list encl JORDAN,E C Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Fdison Co of New York, Inc 122pp 26276 122 24% Fiche 50-000,84/08/17,8408140208
- 9408210142 lE Info Notice 94-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 930103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26327 008 247 Fiche 50-000.84/08/21,8408210142
- R Periodic operating reports & related correspondence
- 8408210066 Rept of changes, tests & experiments completed during Jul 1984 W/640801 ltr KALIVIANAKIS.N Commonwealth Edison Co 84/0//31 CASE,E G Office of Nuclear Reactor Regulation, Director 2pp 26184 307 24X Fiche 30-254,84/07/31,8408210068
- 8408230435 Monthly operating repts for Jul 1984 W/840801 ltr KIMLER.D., KALIVIANAKIS.N. Commonwealth Edison Co. 84/07/31 24pp 24213 074 24% Fithe 50-254.84/07/31,8408230435
- 8408300299 Forwards "Effluent & Maste Disposal Semiannual Rept, Jan-June 1984, Gaseous Effluents - Summation of All Releases" & errata to semiannual repts for Jan-June & Jul-Dec 1983 MALIVIANAKIS, N. Com-Tonucalth Edison Co. 84/08/15 KEPPLER, J. G. Region 3, Office of Director 1p 26314 225 24X Fiche 50-254, 84/08/15, 8408300299
- -8408300308 "Effluent t Waste Disposal Semiannual Rept. Jan-June 1984 " BEHREMS.P A Commonwealth Edison Co 84706/30 12pp 26314 226 24X Fiche 50-254.84708/15.8408300299
- --8408300329 Errata to "Liquid Effluents Summation of All Releases " Jan-June 1983 \* Commonwealth Edison Co 83/06/30 7pp 26314 233 24X Fiche 50-234,84/08/15,8408300279
- --8408300336 Errato to "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1983, Caseous Effluents - Summation of All Releases " \* Commonwealth Edison Co 83/12/31 2pp 26314 240 24X Fiche 50-254, 84/08/15, 8408300297
- 8 Reportable occurrences, LERs & related correspondence
- B40824034B Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated SHERKHODD G Q General Effection Co 84/04/13 DEYONNOR C Director's Office Office of Inspection and Enforcement 3pp 26222-236 24X Fiche 50-000,84/04/13,8408240348

- 8408230496 LER 84-014-00 on B40808, while starting shutdown cooling mode of RHR sys, LPCI valves 1-1001-294 & B would not open Caused by personnel error Valve stems removed & being replaced W/840814 ltr COOK, D.B., KALIVIANAKIS, N. Commonwealth Edison Co. 84/08/14 4pp 26212 255 24X Fiche 50-254.84/08/14.8408230496
- 8408310186 Part 21 rept re torus-to-reactor bidg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition

  VILLA-R General Electric Co 84/08/21 RDSSI C E Director's Office, Office of Inspection and Enforcement 3pp 26318 327 243
  Fiche 50-000.84/08/21.8408310186
- V Operator Examinations
- B408140372 Forwards proposed rev to "Requalification Program for Licensed Operators, Senior Operators 7 Senior Operators (Limited)." In response to NUREO-0737, Item J A 3 1 MARSHALL.J G Commonwealth Edison Co 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26051 240 24% Fiche 50-000, 84/08/07, 8408140372
- --8409140389 "Requalification Program for Licensed Operators Senior Operators (Limited)"

  \* Commonwealth Edison Co 84/07/19 10pp 26051 242 24X Fiche 50-000.84/08/07,8408140372
- 8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners HALKER,R D Region 3, Office of Director 84/08/10 Michigan. Univ of. Ann Arbor, MI 2pp 24051 198 24X Fiche 50-000, 84/08/10.8408140424
- DOCKET 50-255 PALIBADES NUCLEAR PLANT
- D NRC Draft/Final Environmental Statements, supple & correspondence
- B40Bi30366 Forwards request for add1 info re FES & final addendum in preparation for conversion of provisional OL Response requested within 30 days of 1tr receipt PAULSON.WA Deracting Reactors Branch 5 84/08/08 VANDEMALLE.D J Consumers Power Co 3pp 26011 071 24X Fiche 50-255.84/08/08.043660130366
- F Security, medical, emergency & fire protection plans
- 8408240082 Forwards IE Insp Rept 50-255/84-10 on 840529-0713 & notice of violation B40529-0713 & notice of Director B4/07/24 DCWITT, R B Consumers Power Co 2pg 26237 023 24X Fiche 30-255,84/07/24,8408240082
- --8408240085 Notice of Violation from insp on 840529-0713 SHAFER.W D Region 3, Office of Director 84/07/24 ip 26237 025 24X Fiche 50-255,84/07/24,8408240082
- ---8408240088 IE Insp Rept 50-255/84-10 on 840527-0/13 Noncompliance noted failure to document missing tags when performing engineered safeguards (lodine removal) k auxiliary feedwater sys checklists
  WRIGHT, C.C. Region 3, Office of Director 84/07/24 Opp. 26237 026 24% Fiche 50-255,84/07/24,8408240082
- 840B070435 Forwards Rev 3 to milestone commitments on Suppl 1 to NVREO-0737 & "PSAK, Safety Parameter Display Sys." per 830913 & 16 submittals JOHNSON, D D Consumers Power Co 84/07/31 CRUTCHFIELD, D Sperating Reactors Branch 5 6pp 25942 361 24X Fiche 50-255, 84/07/31. 840B070435
- 840813033 Forwards Rev 10 to security plan & Rev 1 to safeguards contingency plan Revs withheld (ref 10CR73 21)
  VANDEWALLE,D Consumers Power Co 84/08/06 KEPPLER, J 9 Region 3, Office of Director, 1p 26010 059 24X Fiche 50-295, 84/08/06, 8408130353
- 8408090179 Responds to 840417 request for exemption from App E to 10CFR50, excluding state & county participation in 840821 emergency preparedness exercise Request for exemption not required, por 840706 rev to App E PAULBON, W A Operating Reactors Branch 5 84/08/07 VANDEWALLE, D J Consumers Power Co 2pp 25972 288 24X Fiche 50-255.84/08/07.8408090179

- 8408130370 Responds to 840711 ltr relaccess authorization program Access authorization list development & maint functions being transferred to Div of Resource Mgt Notification of terminated employees will be on as needed basis AXELSON. & L. Rogion J. Diffice of Director 84/08/09 VANDEMALLE. D J. Consumers Power Co. 1p. 26010 358 24X Fiche 50-000.84/08/09 8408130370
- --B409130376 Submits list of items discussed in 840703 telcom No termination notifications received Updates on activities will be submitted Concurrence needed for documentation LATHWELL, II J Consumers Power Co B4/07/11 CREED, J Region 3 Office of Director 2pg 26010 359 24% Fiche 50-000, 84/08/09, 8408130370
- B408140295 Provides editorial changes to B40731 cover itr & Attachment i re Suppl 1 to NUREG-0737, sarety parameter display sys PBAR & implementation schedule,per Reg Guide i 97 variables JOHNSON, B D Consumers Power Co B4/08/09 CRUTCHFIELD, D Operating Reactors Branch 5 bpp 26043 144 24X Fiche 50-255,84/08/09,8408140295
- 8408170364 Forwards Rev 3 to fire protection exemption requests & modified commitments List of equipment necessary for safe shutdown & exemption request re local tending of diesel generators included JOHNSON. B D Consumers Power Co. 84/08/10 CRUICHFIELD. D Operating Reactors Branch 5 61pp 26114 001 24X Fiche 50-255.84/08/10.8408170364
- 8408200319 Advises that 840806 Rev 10 to physical security plan & Rev i to safeguards contingency plan consistent w/provisions of 10CFR90 54(p) & acceptable AXELBON,W L Region 3, Office of Director 84/08/13 VANDEWALLE:D J Consumers Power Ce 2pp 26133 010 24X Fiche 50-255.84/08/13,8408200319
- 8408280113 Responds to 840717 ltr requesting extension of completion dates for submitting final rept re Reg Guide 1 97 requirements of Suppl 1 to NUREG-0737 Extension granted Adequate justification provided EISENHUT.D G Division of Licensing 84/08/23 VANDEWALLE.D J Consumers Pawer Co 4pp 26261 276 24X Fiche 50-255,84/08/23,84008/2013
- 840B300048 Ack receipt of 840326 ltr re new volumetric intrusion detection sys Concern expressed re delay in completion of upgrade Compensatory measures may be required if not complete by Dec 1986 PAULEON.W A Operating Reactors Branch 5 84/08/24 VANDEWALLE, D. J. Consumers Power Co. 4pp. 26331 341 24X Fiche 50-255,84/08/24,8408300048
- O Advisory Committee on Reactor Bafeguards reports & correspondence
- 840B200182 Advises that encl "Rept to ACRS, CPC of Michigan Palisades Plant," may be declassified & made available to public FUNCHES, JL Planning & Program Analysis Staff 84/0B/08 SCATOLINI, L B Public Document Branch 2pp 26142 295 24X Fiche 50-255,84/0B/08,8408200182
- --8408200184 "Rept to ACRB, CPC of Michigan Palisades Plant "

  \* Atomic Energy Commission 69/08/26 24pp 26142 297 24X
  Fiche 50-255, 84/08/08, 8408200182
- P Operating license stage documents & correspondence
- 8408030150 Forwards application for amend to License DPR-20, modifying Tech Spec Sections 1 0 % 6 0 re definitions & administrative controls respectively, to reflect IOCFR50 73 reporting requirements
  VANDEWALLE, D J Consumers Power Co 84/07/30 CRUTCHFIELD, D Operating Reactors Branch 5 1p 20713 347 24X
  Fiche 50-255,84/07/30,8408030150
- --8408030151 Application to amend License DPR-20, modifying Tech Spec Sections 1 0 & 6 0 re definitions & administrative controls, respectively, reflecting 100FRSD 73 reporting requirements REYNOLDS.J W Consumers Power Co 84/07/30 2pp 25715 350 24X Fiche 50-255.84/07/30.8408030150
- --8408030152 Proposed changes to Tech Specs 1 0 & 6 0, reflecting 10CFR50 73 reporting requirements \* Cansumers Power Co. 84/07/30 11pp 25715 352 24X Fiche 50-255, 84/07/30, 8408030150

- 8408070099 Forwards Generic Ltr 84-13, "Tech Specs for Snubbers,"
  omitted from 840503 ltr to all SEP licensess NRC position
  that issue of Tech Specs for snubbers will be resolved on
  generic basis restated
  CRUTCHFIELD.D Assistant Director for Safety Assessment 84/07/31
  KAY, J A Yanker Atomic Electric Co LINDER, F Dairyland Power
  Cooperative FIEDLER, P II General Public Utilities GPU Service
  Corp 4pp 2595 227 24X Fiche 50-000,84/07/31,8408070099
- B40B070431 Application for amend to License DPR-20, adding Section 3 0 limiting conditions for operation applicability, in response to 831031 radiological effluent Tech Specs transmitting Draft 7 of Rev 3 to NUREO-0472 VANDEMALE, D. J. Consumers Power Co. 84/07/31 CRUTCHFIELD, D. Derating Reactors Branch 3 10pp. 25939 221 24X Fiche 30-255, 84/07/31, 840B070431
- --8408070438 Proposed Toch Specs adding Section 3 0 limiting conditions for operation applicability.deleting Section 3 9. "Effluent Releases" & adding new Section 4 24, "Radiological Effluent Releases" # Consumers Power Co 84/07/31 175pp 25939 228 24X Fiche 30-233,84/07/31.8408070431
- B40B080331 Forwards add1 fee for review of 840613 Tech Spec change application re containment purge & ventilation sys
  JDHNBDN,B D Consumers Power Co 84708702 DIGGER M License Fee
  Management Branch 1p 25964 109 24X Fiche 50-255.84708702.
  840B080331
- 8408070110 Generic Ltr 84-19 to all licensees of operating resctors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Generic Bafety leaves " Svc list encl EISENHUT.D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26127 238 24X Fiche 50-000.84/08/06, 8408070110
- 8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
  TREMBLAY.P P Operating Reactors Assessment Branch 84/08/06
  HDLAHAN,O M Operating Reactors Assessment Branch 13pp 25991 350 24X Fiche 50-000.84/08/06.8408090317
- 8408100134 Application for amend to License DPR-20, changing Tech Spec re plant review committee, in response to NRC concerns VANDEWALLE, D. J. Consumers Power Co. 84/08/08 CRUTCHFIELD, D. Operating Reactors Branch 5 5pp. 25991 038 24X Fiche 50-295,84/08/06,8408100134
- --B40B10013B Proposed Tech Spec re administrative controls \* Consumors Power Co 64/08/06 2pp 25791 040 24X Fiche 50-255,84/08/06,8408100134
- B408160295 Natifies of Class III fee due for review of 840814 request for relief from ASME Code requirements DIGGS.R M License Fee Management Branch 84/0H/09 VANDEMALLE, D J Consumers Fouer Co 1p 26124 345 24X Fiche 50-255
- 840B140388 Advises that NRC 840624 comments re Multi-Plant Action 8-57, "DHR Capability," reviewed Changes to Tech Specs may be warranted Preparation of proposed Changes & Justifications for specs not being altered will be submitted by Doc 1704 JOHNSON, B D Consumers Power Co 84/08/10 CRUTCHFIELD, D Operating Reactors Branch 5 p 26033 349 24x Fiche 50-255-84/08/10,8408140388
- B40B170022 Informs that 840523 QA program submittal requires identification of each change reason for change & basis for concluding that revised program incorporating each change satisfies iGCFR50,App B & SAR QA program commitments SPESSARD.R L. Region 3. Office of Director 84/08/14, DEWITT.R B Consumers Power Co 2pp 26119 077 24X Fiche 50-000,84/08/14. B40B170022
- 8408230201 Forwards remittance for hydrotest relief 840514 request, per 840809 ltr JOHNBON, B D Consumers Power Co 84/08/17 DICOS, R M License Fee Management Branch ip 26209 197 24X Fiche 50-255, 84/08/17, 8408230201
- B40B200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for QLs re scheduling guidance for licensee submittals of reloads that involve Unreviewed safety questions Svc list encl EIBENRUT, D 9 Division of Licensing 84/08/20 Consolidated Edison Co of New York. Inc. 17pp 26276-244 24X Fiche 50-000.84/08/20.8408200275

- 8408210307 Forwards notice of environ assessment & finding of no significant impact re 801112 application & 821116 supplemental ltr for relief from requirements of Section XI of ASME Boiler & Pressure Vessel Code PAULSON.W A Operating Reactors Branch 5 84/08/20 VANDEMALLE, D. J. Consumers Power Co 2pp 26180 222 24X Fiche 50-235,84/08/20,8408210307
- --8408210307 Notice of environ assessment & finding of no significant impact EISENHUT, D O Division of Licensing 84/08/20 3pp 26180-224 24% Fiche 50-255.84/08/20.8408210307
- 8408240161 Requests extension until 840201 to submit final PRA & costbenefit analyses, in response to SEP Topic XV-2, "Spectrum of Steam Piping Failures Inside & Outside Containment (PUR) " Extension due to difficulties in new tempoter codes VANDEWALLE.D J Consumers Power Co 84/08/21 Office of Nuclear Reactor Regulation, Director 1p 26228 184 24X Fiche 50-253,84/08/21,8408240161
- 8 Inspection reports, IE Bulletins & correspondence
- 8408300156 Forwards Insp Rept \$0-255/84-06 on 840322-23 & 0427 W/o notice of violation KEPPLER, J G Region 3, Office of Director 84/07/11 DEWITT, R B Consumers Power Co 2pp 26307 333 24X Fiche 50-255,84/07/11, 8408300156
- --8408300164 Insp Rept 50-255/84-06 on 840322-23 & 0427 Noncompliance noted dose to worker exceeded 100FR20 101 limits, failure to provide proper monitoring for high radiation area access & failure to follow radiation protection procedures LOVENDALE.P C . GREGER.L R Region 3. Office of Director 84/07/10 13pp 26/307/335 24X Fishe 50-255.84/07/11. 8408300156
- 8408090192 Forwards IE Insp Rept 50-255/84-12 on 840713 No noncompliance identified LITTLE-N 8 Region 3. Office of Director 84/07/24 DEWITT.R B Consumers Power Co 2pp 25992 084 24X Fiche 50-255.84/07/24, 840809018
- --8408070195 IE Insp Rept 50-255/84-12 on 840713 No nencompliance identified Hajor areas inspected followup of valve shaft insp & replacement of HBIVs JONES DE , DANIELSON, D H Region 3, Office of Director 84/07/24 3pp 25992 086 24% Fiche 50-255,84/07/24,8408090192
- 8408240082 Forwards IE Insp Rept 50-235/84-10 on 840529-0713 & notice of violation SHAFER.ND Region 3, Office of Director 84/07/24 DEWITT.RB Consumers Power Co 2pp 26237 023 24% Fiche 50-235,84/07/24,8408240082
- --8408240085 Natice of violation from insp on 840529-0713 SHAFER.W D Region 3. Office of Director 84/07/24 1, 2623/025 244 Fiche 50-255,84/07/24,8408240082
- --8408240088 lE Insp Rept 50~255/84-10 on 840527-0713 Noncompliance noted failure to document missing tags when performing engineered safequards (iodine removal) & auxiliary feedwater sys checklists
  WRIGHT.0 C Region 3, Office of Director 84/07/24 Bpp 28237 026 24X Fiche 50~255.84/07/24,8408240082
- 408150290 Forwards IE Insp Rept 50~255/84~13 on 840711-12 No noncompliance noted LITILE: S Region 3, Office of Director 84/07/25 DEWITT.R 3 Consumers Power Co 2pp 26075 292 24% Fiche 50~255.84/07/25, 8408150290
- --8408150293 IE Insp Rept 50-253/84-13 on 840711-12 No noncompliance noted Major areas inspected corrective action on LER recables damaged due to excessivally high temp NOIDU.K R. FALEVITB.Z. HILLIAMB.C.C. Region 3, Office of Director 84/07/24 3pp 26075 294 24X Fiche 50-255.84/07/25.8408150290
- 840B130277 Submits listed actions to be taken prior to commencing power operations due to 80 on 840703 event re cables damagad by excessively high temp KEPPLER.J G Region 3, Office of Director 84/07/13 DEWITT.R.B Consumers Fower Co 2pp 26073 297 24% Fiche 50-235,84/07/25,8408180293
- 8407230227 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Flants " Svc list encl JORDAN.BL Division of Emergency Preparedness & Engineering Described Flants (Fost 830103) 84/07/27 Consolidated Edison Co of New Inc 119pp 25865 047 24X Fiche: 50-000, 84/07/27, 8407250227

- B40B310161 Forwards summary of primary coolant pump inservice inspresults for B31216-B40804
  DHHS0N.8 D Consumers Power Co B4/OB/02 KEPPLER.J G Region 3.
  Office of Director 1a 26319 143 PAX Fiche 50-255,84/OB/02.
  BA0B310161
- --B408310165 Inservice insp rept for 831216-840504 All reportable indications reprimally coolant pumps evaluated % dispositioned to accept as is VAN HAGNER, B V . BEACH, D L . ESCH. H E Consumers Power Co 84/08/02 29pp 26319 144 24X Fiche 50-255.84/08/02, 8408310161
- 8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during inspiratived effective 840820 Preprinted form will be used rather than ltr
  KEPPLERI, G. Region 3. Office of Director 84/08/03
  Commonwealth Edison Co. Jpp. 25942 188 24X Fiche 50~000,84/08/03,840807040
- 8408010333 IE info Notice 84-39, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edisun Co of New York, Inc 85pp 26048 001 24X Fiche 50-000,84/08/06,8408010333
- B408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IC Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN: EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Cansolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- 8408070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list and Office and Offi
- 840B100009 IC Info Notice 84-63, "Defective RHR Replacement Fiping "
  Svc list encl
  JORDAN, EL Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc. 117pp 26197 218 24% Fiche 30-000,84/08/13,8408100009
- 8408100038 IE Info Notice 84-44. "BWR MPCI Initiation Seal-In & Indication " Svc list enc! JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24% Fiche 50-000,84/08/15,8408100038
- 8408310299 Forwards exam rept of exam administered on 840626-0701 WALKER, R D Region 3. Office of Director 84/08/15 DEWITT, R B Consumers Pawer Co 2pp 26333 222 24X Fiche 50-255,84/08/15,8408310299
- ~-B408310302 Exam rept administered on B40626-0701 Exam results eight candidates passed & two candidates failed HIGGINS.R L . STREIER, 0 . WHITTEMBRE, J Region 3, Office of Director B4/08/14 63pp 26333 224 24X Fiche 50-255,84/08/15,8408310297
- 8408100021 IE Info Notice 84-45, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list end."

  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc. 118pp 24198 001 24% Fiche 50-000,84/08/16,8408100021
- 840Bi00055 IE Info Notice 8A-66, "Undetected Unavailability of Turbine-Driven Auxiliary Fredwater Train " Svc list encl JORDAN: L Division of Emergency Preparedness & Engineering Response (Post 830105) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- 8408140208 IE Info Notice 84-47, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/08/17 Consolidated Edison Co of New York: Inc 122pp 26876 128 24X Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-58. "Potential Deficiency in Improperly Rated Field Wiring to Solonoid Volves " Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/08/21 Consolidated Edison Co of New York, Inc 115pp 25327 008 24X Fiche 50-000,84/08/21,8408210142

- 8408270273 Ack receipt of 840815 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-255/84-06 \* Region 3, Office of Director 84/08/21 Consumers Power Co ip 26241 018 24X Fiche 50-255.84/08/21.8408270273
- --8408270281 Responds to NRC 840711 ltr re violations noted in Insp Rept 50-255/84-06 Corrective actions detailed radiological work plan developed.reliable underwater survey equipment procured δ personnel failing to document surveys counseled VANDEMALLE.D J Consumers Power Co 84/08/15 ΚΕΡΡΙΕR.J Q Region J. Defice of Director δρρ 26241 017 24X Fiche 30-255,84/08/21,8408270273
- 8408300128 Forwards safety evaluation supporting licensee request for relief from inservice insp requirements Safety evaluation delineates items for which relief granted & alternate schedules & procedures defined PAULSON. WA Operating Reactors Branch 5 84/08/23 VANDEWALLE, D J Consumers Power Co 3pp 26306 088 24X Fiche 50-255,84/08/23,8408300128
- --8408300132 Safety evaluation supporting licenses request for relief from inservice insp requirements \* Office of Nuclear Reactor Regulation, Director 84/08/23 llpp 26304 091 24X Fiche 50-255,84/08/23,8408300128
- B40B2B0002 Ack receipt of B40B10 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-255/84-07 Supplemental response required within 30 days of ltr date WALKER, D Region 3, Office of Director B4/0B/24 DEWITT, R Consumers Power Co ip 26261 235 24X Fiche 50-255,84/0B/24, BA0082B0002
- --8408200003 Responds to NRC 840629 itr re violations noted in Insp Rept 50-255/84-09 Corrective actions Tech Spec Surveillance Procedure RM-45 modified by acceptance criteria reflecting ASME requirements for mechanical snubber operability BORDINE.T C Consumers Power Co 84/08/10 KEPPLER.J 0 Region 3, Office of Director 5pp 26261 236 24X Fiche 50-255, 84/08/24,846380002
- R Periodic operating reports & related correspondence
- 840B160255 Monthly operating rept for Jul 1984 W/840810 ltr DIENESA F . VAN DENBERG, D Consumers Power Co 84/07/31 5pp 26106 188 24% Fiche 50-255.84/07/31.8408160255
- 9 Reportable occurrences, LERs & related correspondence
- 8408060263 LER 84-008-00 on 840628 & 27, test of seals of inner door of personnel air lock revealed leakage due to cracks in inner seal Caused by personnel calculation error Adjustments completed on seals W/840726 ltr ROGERS, D W. JOHNSON, B D. Consumers Power Ca 84/07/26 4pp 25736 174 24x Fiche 50-255.84/07/26.8408060263
- 8408090398 LCR 84-009-00 on 840704, spurious left channel safety injection signal actuation occurred Caused by inadequate procedure Procedure revised & personnel counseled W/840803 ltr ROSERS.D W , FRISCH.R R Consumers Power Co 84/08/03 2pp 25793 273 24X Fiche 50-255.84/08/03,8408090398
- B40Bi40279 LER B4-010-00 on 840703, section of cable tray encl by fire barrier discovered hot to touch Insp found insulation on cables sustained damage due to excessive temp Caused by long-term thermal degradation Cable replaced W/840Bi3 ltr R00EB9, D W , JDHNBON, B D Consumers Fower Co B4/0B/13 ip 26106 164 24% Fiche 50-255, 84/08/13, 840BI40279
- B40B20030B PND-11I-B4-063 on B40B10, unusual event declared due to leakage from primary coolant sys pressure sensing line solation value MV-1019A Weld cracked Piping & weld to be cut out & replaced Startup scheduled by B40B16 MRIGHT.0 , BHAFER.W Region 3, Office af Director 84/08/13 1p 26133 018 24X Fiche 50-255,84/08/13,840B20030B
- 8408270127 LER 84-012-00 on 840729, unidentified primary coolant sys (AB) leakage greater than 1gpm discovered Caused by leakage past loopcheck valves into safety injection lines Check valves thushed to facilitate improved seating W/840820 ltr ROGERS.D W. BORDINE, T C consumers Power Ca 84/08/20 2pp 26298 200 24x Fiche 50-255.84/08/20.8408270127
- 8408270130 LER 84-011-00 on 840719, while technicians calibr containment pressure suitches two spurious containment high pressure signals generated resulting in ESF actuations Caused by personnel error W/840820 ltr ROCERS, D W, BORDINE, T C Consumers Power Co 84/08/20 3pp 26238 195 24X Fiche 50-255,84/08/20,8408270130

- 8408310056 LER 84-014-00 on 840728. w/reactor critical in hot standby condition.primary coolant temp dropped below 525 F Caused by personnel error Procedure revised W/840827 It ROSERS, D w . JUHNSON. B D Consumers Power Co 84/08/27 3pp 26335 009 24% Fiche 50-255.84/08/27.8408310056
- 8408310059 LER 84-013-00 on 840727, results of daily leak rate calculation indicated unidentified primary coolant sys leakage greater than 1 gpm Caused by charging pump seal leak Pump repaired & procedures revised W/840827 ltr ROGERS, D.W. JOHNSON, 8 D. Consumers Power Co. 84/08/27 3p 26334 235 24% Fiche 50-255,84/08/27,8408310059
- V Operator Examinations
- 8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051
- B40B170050 Confirms scheduling of operator/senior operator licensing exams for 84;21:-14 & 17-19 List of ref matl required & NRC administrative requirements encl MALKER,R D Region 3, Office of Director 84/08/14 DEWITT,R B Consumers Power Co Spp 26119 089 24X Fiche 50-255.84/08/14, B40B170050
- B40B310279 Forwards exam rept of exam administered on 840626-0701 WALKER, R D Region 3. Office of Director 84/08/15 DEWITT, R D Consumers Fower Co. 2pp 26333 222 24X Fiche 50-255, 84/08/15, 840B310279
- --8408310302 Exam rept administered on 840626-0701 Exam results eight candidates passed & two candidates failed HIGOINS,R L , STREIER,O , WHITTEMORE,J Region 3, Office of Director 84/08/14 63pp 26333 224 24X Fiche 50-255,84/08/15,8408310279
- DOCKET 50-239 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- B40B300402 Forwards summary of 840530 meeting w/TVA.Alabama Power Co-Florida Power Corp.Florida Power & Light & Georgia Power Core selected emergency preparedness issues D'REILLY, J.P. Region 2, Office of Director 84/06/08 PARRIE.31 & Tennessee Valley Authority App 26308 116 24X Fiche 50-000.84/06/08.8408300402
- 8408280096 Ack receipt of 840707 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-259/84-i7, 50-280/84-17 & 50-296/84-17 VERRELLI.D H Region 2. Office of Director 84/07/25 PARRIS.H & Tennesses Valley Authority ip 26281 319 24X Fiche 50-209.84/07/25.8408280096
- --B40B2B0ii6 Respands to NRC 840607 ltr re violations noted in Insp Repts 50-259/84-17.50-260/84-17 & 50-296/84-17 Corrective actions temporary fire load form posted & daily fire load insps performed until removal of combustibles MILLS.L M Tennessee Valley Authority B4/07/09 O'REILLY, J P Region 2. Office of Director 2pp 26281 320 24X Fiche 50-259.84/07/25.8408280096
- --8408280124 Forwards Insp Repts 30-259/84-17, 30-260/8-50-294/84-17 on 840508-11 & notice of violation VERRELLI, D M. Region 2, Office of Director 84/0c PARKIS, H G Tennesses Valley Authority 2pp 26; Fiche 50-259,84/07/25,8408280094
- --8408280134 Notice of violation from insp on 8° \* Region 2, Office of Director 84/06/07 Fiche 50-259,84/07/25.8408280094
- ---8408280140 Insp Repts 50-259/84 840508-11 Violations noted fa prevention procedures for con MADDEN,P M Region 2, Office 24281 325 24X Fiche 50-259.6
- 8408020145 Forwards ravs to imple/ of IP-6, "Activation of Technica "Technical Support Ctr Operation Emergency Plan" MILLS.L. M Tennessee Valley Aut Region 2, Office of Director 1 Fiche 50-239,84/07/27,840802014

- --940802015: Revs to radiological emergency plan procedures, consisting of IP-6, "Activation of Technical Support Ctr" & IP-20, "Technical Support Ctr Operation"

  \* Tennessee Valley Authority 84/07/27 12pp 25886 012 24X
  Fiche 50-259,84/07/27,8408020145
- --8408020156 Rev 14 to "Radiological Emergency Plan" \* Tennessee Valley Authority BFN-REP R14 84/06/29 4pp 25886 024 24% Fiche 50-259,84/07/27,8408020145
- B40B030015 Forwards safety analysis implementation plan & implementation schedule for safety parameter display sys.per DB Vassallo 840612 confirmatory order to HG Parris MILLS.L H Tennessee Valley Authority 84/07/30 DENTON.H R Office of Nuclear Reactor Regulation, Director App 25907 118 24% Fiche 50-259,84/07/30.8408030015
- 8408230167 Ack receipt of 840801 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15 LEHIS.R C Region 2. Office of Director 84/08/13 PARRIS.H G Tennesse
- ---8408230192 Responds to NRC 840712 ltr re violations noted in IE Inso Rapts 50-239/84-15, 50-240/84-15 & 50-296/84-15 Corrective actions total sys walldown for control air sys flow diagrams performed by plant personnel MILLS,L M Tennessee Valley Authority 84/09/01 D'REILLY, J P Region 2, Office of Director 4pp 24206 318 24X Fiche 50-259,84/08/13,8409230167
- --8408230208 Responds to NRC 840523 ltr re violations noted in IE Insp Repts 50-259/84-15.50-260/84-15 & 50-296/84-15 Corrective actions 8td Practice 14 25 revised to require second party verification in hanging & removing clearance tags MILLS.L M Tennessee Valley Authority 84/06/29 D'REILLY, J P Region 2. Office of Director 11pp 26206 324 24X Fiche 50-259,84/08/13,8408230167
- --8408230225 Notice of violation from insp on 840326-6425 \* Region 2, Office of Director 84/05/23 5pp 26206 337 24X Fiche 50-259,84/08/13,8408230167
- --B408230240 IE Insp Repts 30-259/B4-15, 30-260/B4-15 & 50-296/B4-15 on B40326-0425 Violations noted misaligned sys valves on control air compressor, incorrect valve on control air sys & inadequate fire protection surveillance procedures PAULK, G L Region 2. Office of Director B4/05/17 14pp 26206 342 24X Fichs 50-259, B4/0B/13, B408230167
- 8408290245 Forwards justification which supple 840612 schedular examption request re fire protection mode MILLS.L M Tennessee Valley Authority 84/08/23 DENTON, H R Office of Nuclear Resource Regulation, Director 7pp 26290 317 24X Fichs 50-259,84/08/23,8408290245
- P Operating license stage documents & correspondence
- 8408300434 Confirms 840601 telton between JA Coffey & RC Lewis re 840621 enforcement conference in Region II ofc to discuss design problems w/power supply & distribution sys Proposed agenda encl 0'REILLY,J P Region 2, Office of Director 84/06/05 PARRIS,H B Tennesses Valley Authority 2pp 26314 328 24x Fichs 50-259,84/06/05,8408300434
- 8408140026 Forwards requests for add1 info re Mark I containment longterm program vent sys analysis & details of seismic lugs Recommends 840910 meeting w/BNL & Franklin Research Ctr to discuss response prior to submittal of formal response VASSALLO, D 8 Operating Reactors Branch 2 84/07/26 PARRIS, H G Tennessee Valley Authority 14pp 26061 245 24X Fiche 50-259.84/07/26.8408140026
- 840B010344 Responds to 840613 request for add1 info re Mark I containment long-term program analyses Safety relief valve discharge piping sys mods based on most severe reflood conditions predicted by RVRIZ & RVFDR codes MILLS.L H. Tennessee Valley Authority 84/07/27 DENTON,H R Office of Nuclear Reactor Regulation. Director 2pp. 25866-322 24X Fichs 50-259.84/07/27,8408010344
- 8408130026 Forwards Amends 104 & 98 to Licenses DPR-33 & DPR-52, respectively & safety evaluation Amends change Tech Spacs to delate surveillance requirements for Dampers FCG-150A & FCG-150C CLARK-R J Operating Reacture Branch 2 84/07/27 PARRIS, H Tannessee Valley Authority 2pp 26038 329 24X Fichs. 50-259,84/07/27,8408130026

- --8408130037 Safety evaluation supporting Amends 104 & 98 to Licenses DPR-33 & DPR-52.respectively \* Office of Nuclear Reactor Regulation, Director 84/07/27 2pp 24038 339 24X Fiche 50-259,84/07/27,8408130026
- 840Bi50575 Responds to 830422 submittal of Tech Spec amends per TMI Item I A 1 3, "Limit Overtime" & Generic Ltr 83-02 Tech Spec change request to ensure overtime controls implemented, required VASSALLO, D B Operating Reactors Branch 2 84/07/27 PARRIS, H O Tennessee Valley Authority 2pp 26080 353 24% Fiche 30-259,84/07/27,8408150375
- B40B160155 Forwards SER on NUREQ-0737. Item II K 3 22 re automatic switchover of RCIC sys suction Manual switchover of RCIC suction on low water level in condensate storage tank acceptable VASBALLO, D B Operating Reactors Branch 2 84/07/27 PARRIS, H G Tennossee Valley Authority 9pp 26126 154 24X Fiche 30-259, 84/07/27. 840B160155
- 840B160424 Forwards Amends 105, 97 & 72 to Licenses DPR-33, DPR-52 & BPR-68, respectively & safety evaluation Amends replace word "operator" w/ "reactor operator" to provide consistent numenclature
  CLARK, R J Derating Reactors Branch 2 84/07/30 PARRIS, H G Tannessee Valley Authority 3pp 26126 229 24X Fiche 50-237, 84/07/30.840B160424
- --B40B160426 Amends 105,99 & 72 to Licenses DPR-33, DPR-52 & DPR-68, respectively, replacing word "operator" w/ "reactor operator" to provide consistent nomenclature & parmitting fuel handling supervises by senior reactor operator VASBALLO, D B Operating Reactors Branch 2 84/07/30 12pp 26126 232 24X Fichs 50-259,84/07/30,840B160424
- ---B40B160427 Safety evaluation supporting Amends 105.99 & 72 to Licenses DPR-33.DPR-52 & DPR-6B, respectively \* Office of Nuclear Reactor Regulation, Director 26126 244 24X Fiche 50-259:84/07/30,840B160424
- B408060021 Application for amend to License DPR-33, changing Tech Specs to allow operation w/flow control valve 84-88 (containment atmosphere dilution supply to torus for Sys A) inoperable until next cold salutdown Fee encl MILLS,L M Tennessee Valley Authority 84/07/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 25923 047 24X Fiche 50-257,84/07/31,8406060021
- --8408060027 Proposed changes to Tech Specs 3 7 & 4 7 to permit operation w/flow control valve 84-88 (containment atmosphere dilution supply to torus for Sys A) inoperable until next cold shutdown # Tennessee Valley Authority 84/07/31 7pp 25923 052 24X Fiche 50-259,84/07/31.8408060021
- D408070370 Suppl : to 831027 application for amend to Licenses DPR-33, DPR-52 & DPR-48, consisting of minor revs to Tech Space in response to NRC 831220 camments & request for add1 info MILLS.L M Tennessee Valley Authority 84/08/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 25947 174 24X Fiche 50-259, 84/08/01, 8408070370
- --8408070375 Proposed Tech Spec re radioactive gaseous effluent instrumentation surveillance
  \* Tennesses Valley Authority 84/08/01 44pp 25947 178 24X
  Fiche 50-259,84/08/01,8408070370
- 8408200264 Forwards Amends 104,100 & 73 to Licenses DPR-33,DPR-52 & DPR-68, respectively & safety evaluation Amends clarify correct operating positions & identify proper action for initiating signal for suppression chamber drain values CLARK,R J Operating Reactors Branch 2 84/08/02 PARRIS.H G Tennessee Valley Authority 2pp 26142 345 24% Fiche 50-259.84/08/02,8408200264
- --8408200269 Amends 106.100 & 73 to Licenses DPR-33, DPR-52 & DPR-68, respectively Amends change Tech Specs re suppression chamber drain valves, clarify operating positions & identify proper action in initiating signal VASBALLO, D B Operating Reactors Branch 2 84/08/02 12pp 26142 347 24X Fiche, 50-259, 84/08/02,8408200264
- --8408200280 Safety evaluation supporting Amends 106,100 & 73 to Licenses DPR-33, DPR-52 & DPR-68, respectively \* Office of Nuclear Reactor Regulation, Director 84/08/02 2pp 26142 359 24X Fishe 50-259,84/08/02,8408200264

- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Generic Safety Issues " Svc list encl EISENHUT.D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000,84/08/06.8408070110
- B40B140375 Forwards response to NRC B31012 request for add1 info re reactor protection sys power monitoring sys design mods. Tech Specs will be submitted in future W/12 oversize drawings Aperture cards available in PDR DDMER.J A Tennessee Valley Authority 84/08/09 DENTON.H R Office of Nuclear Reactor Regulation. Director 11pp 26051 187 24X Fiche 50-259,84/08/09,840B140375
- 8408210003 Forwards Amends 107.101 & 74 to Licenses DPR-33,DPR-52 & DPR-68,respectively & safety evaluation Amends change Tech Specs to allow operation for 30 days w/16 main steam tunnel high temp switches bypassed CLARK,R J Operating Reactors Branch 2 84/08/09 PARRIS,H 0 Tennessee Valley Authority 2pp 26195 194 24X Fiche 50-259,84/08/09,8408210003
- --8408210004 Amends 107.101 & 74 to Licenses DPR-33, DPR-52 & DPR-68, respectively, changing Tech Specs to allow operation for 30 days w/16 main steam tunnel high temp switches bypassed VASSALLO, D B Operating Reactors Branch 2 84/08/09 12pp 26195 196 24X Fiche 50-259,84/08/09.8408210003
- --8408210007 Safety evaluation supporting Amends 107.101 & 74 to Licenses DPR-33, DPR-52 & DPR-68; respectively \* Office of Nuclear Reactor Regulation, Director 84/08/09 5pp 26195 208 24X Fiche 50-259,84/08/09,8408210003
- 8408200131 Forwards response to 840501 ltr re Criteria 1,2,10 & 11 for permanent post-accident sampling facility Info on interim sys submitted on 840606 DOMER, J A Tennessee Valley Authority 84/08/13 DENTON, H R Diffice of Nuclear Reactor Regulation, Director 5pp 26133 255 24X Fiche 50-259,84/08/13,8408200131
- 8408220137 Application for amend to Licenses DPR-33.DPR-52 & DPR-48, incorporating integrated schedule into license Detailed explanation of methodology utilized definition of revised integrated schedule & fee encl MILLS.L M Tempssoe Valley Authority 84/08/14 DENTON, H R Office of Nuclear Reactor Regulation. Director 84pp 26193 318 24X Fiche 50-259,84/08/14,8408220137
- B408280257 Forwards Amends 110.103 & 76 to Licenses DPR-33.DPR-52 & DPR-60 respectively & safety evaluation Amends revise Tech Specs to permit main steam line high temp isolation function to be ineperable for up to 4 h for testing & maint CLARK,R J Operating Reactors Grant 2 B4/08/15 PARRIS,H G Tennessee Valley Authority 2pp 26294 090 24X Fiche 50-259,84/08/15,8408280257
- --8408280261 Amends 110,103 & 76 to Licenses DPR-33. DPR-52 & DPR-68, respectively, revising Yech Specs to permit main steam line high temp isolation function to be inoperable for up to 4 h for testing & maint purposes VABBALLO.D B Operating Reactors Branch 2 84/08/15 15pp 26274 092 24X Fiche 50-257,84/08/15,8408280237
- --8408280276 Safety evaluation supporting Amends 110,103 & 76 to Licenses DPR-33 DPR-52 & DPR-6B, respectively \* Office of Nuclear Reactor Regulation, Director 84/08/15 2pp 26294 107 24X Fiche 50-259,84/08/15,8408280257
- B408290282 Forwards Amend 109 to License DPR-33 & safety evaluation Amend revises Tech Specs to temporarily permit Train A of containment air dilution sys to be considered operable w/ Valve FCV-84-8B inoperable CLARK.R J Operating Reactors Branch 2 84/08/15 PARRIB,H 0 Tennessee Valley Authority 2pp 26312 320 24X Fiche 50-259,84/08/15,8408290282
- --8408290287 Amend 109 to License DPR-33, changing Tech Specs to temporarily permit Train A of containent air dilution sys to be considered operable w/Valve FCV-84-8B inoperable VASSALLO, D B Operating Reactors Granch 2 84/08/15 4pp 26312 322 24X Fichs 50-259,84/08/15,8408290282
- --8408270272 Safety evaluation supporting Amend 109 to License DRR-33 \* Office of Nuclear Reactor Regulation, Director 84/08/15 5pp 26312 326 24% Fiche 50-257,84/08/15,8408270282

- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for GLs re-scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl.
  EISENNUT.D © Division of Licensing 84/08/20 Consolidated Edison Co of New York. Inc. 17pp 26276-244 24X
  Fiche 50-000.84/08/20.8408200275
- 8408310414 Notification of 840913 meeting w/util & Franklin Research Ctr in Knozvilje. TN to discuss resolution of issues identified in request for add info on structural evaluation in plant-unique analysis rept re Mark I torus mod CLARK, R J Operating Reactors Branch 2 84/08/24 VASSALLO, D B Operating Reactors Branch 2 1p 26350 222 24% Fiche 50-259,84/08/24,8408310414
- 8408310420 Notification of 840905 meeting w/util & BNL in Knoxville, TN to discuss resolution of issues identified in staff request for addlinfo on hydrodynamic leads in plant-unique analysis rept re Mark I torus mads

  CLARK, R J Operating Reactors Branch 2 84/08/24 VASSALLO, D 0

  Operating Reactors Branch 2 1p 26350 215 24X

  Fiche 50-259,84/08/24,8408310420
- Q Inspection reports, IE Bulletins & correspondence
- 8407100322 Responds to 840605 itr providing results of reanalysis of four walls info resolves concerns re four walls identified in 84016 EER concerning IE Bulletin 83-11. "Masonry Wall Design "
  VASBALLO,D B Operating Reactors Branch 2 84/06/26 PARRIS.H G Tennessee Valley Authority 2pp 25513 317 24X
  Fiche 50-259,84/06/26.8407100322
- B40B310109 Forwards Enforcement Conference Repts 50-259/B4-21, 50-260/84-21 & 50-276/84-21 on B40621 O'REILLY, J P Region 2, Office of Director B4/07/09 PARRIB, H Q Tennessee Valley Authority 2pp 26334 227 24X Fiche 50-259,84/07/09,840B310109
- --B408310114 Engartement Conference Repts 50-239/B4-21.50-260/B4-21 & 50-296/B4-21 on B4062! Major areas discussed design errors associated w/separation of electrical cables: paralleling dises! generators & shutdown board room cooling BUTCHER:R C Region 2. Office of Director CANTRELL.F S Division of Project & Resident Programs 84/07/05 App 26934 227 24X Fiche 50-259.B4/07/09.B40B310109
- 840824033B Forwards Insp Repts 50-259/84-22.50-260/84-22 & 50-296/84-22 on 840626-29 No violations or deviations noted VERRELLI, D M Region 2. Defice of Director 84/07/12 PARRIE, H G Tennssee Valley Authority 2pp 26236 131 24X Fichs 50-259.84/07/12.8408240338
- --8408240342 Insp Repts 50-259/84-22, 50-260/84-22 & 50-296/84-22 on B40626-27 No violations or deviations noted Major areas inspected licensee action on previous enforcement matters, welding inservice testing, IE bullotins & LERs GIRARD, C.H., BLAKE, J.J. Region 2, 0841ce of Director B4/07/12 6pp 26236 133 24X Fiche 50-259, 84/07/12, 8408240338
- 8408280096 Ack receipt of 840709 itr informing NRC of steps taken to correct violations noted in Insp Repts 50-239/84-17, 50-236/84-17 & 50-236/84-17 & 50-236/84-17 & 50-236/84-17 & 50-236/84-17 & 50-236/84-17 & 50-236/84-17 & 50-236/84-17 & 50-236/84-17 & 50-236/84-17 & 50-236/84-17 & 50-236/84-17 & 50-236/84-17 & 50-236/84-18 & 50-236/84/07/25,8408280096
- ---8408280116 Responds to NRC 840607 ltr rs violations noted in Insp Repts 50-239/84-17, 50-260/84-17 & 50-276/84-17 Corrective actions temporary fire load form posted & daily fire load insps performed until removal of combustibles MILLGL M Tennessee Valley Authority 84/07/07 0'REILLY, J P Region 2, Office of Director 2pp 26281 320 24X Fichs 50-259,84/07/25,8408280096
- --8408280124 Forwards Imap Repts 50-259/84-17, 50-260/84-17 & 50-296/84-17 on 840508-i1 & notice of violation.
  VERRELLI, D M Region 2. Office of Director 84/06/07
  PARRISH 9 Tennessee Valley Authority 2pp 26281 322 24X
  Fiche 50-259, 84/07/25, 8408280096
- --8408280134 Notice of violation from insp on 840508-11 \* Region 2, Office of Director 84/95/07 ip 26281 324. 24X Fiche 50-259,84/07/25,8408280096
- --8408280140 Insp Repts 50-259/84-17.50-260/84-17 & 50-294/84-17 on 840508-11 Violations noted failure to follow fire prevention procedures for control of temporary fire loads MADDEN, P M , MILLER, W H . CONLON, T E Region 2, Office of Director 84/06/01 9pp 26281 325 24X Fiche 50-259,84/07/25,8408280094

- 8407250229 IE Info Notice 84-57. "Operating Experience re Moisture Intrusion in Bafety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc. 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229
- 8408270196 Ack receipt of 840719 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-259/84-10.
  50-260/84-10 t 50-296/84-10
  VERRELLI,D M Region 2, Office of Director 84/07/31 PARRIS,H (Tennessee Valley Authority 1p 26257 352 24X
  Fiche 50-259,84/07/31,8408270196
- --8408270199 Responds to NRC 840509 ltr re violations noted in Insp Repts 50-259/84-10.50-260/84-10 & 50-296/84-10 Corrective actions Procedures 1053 & 1053A revised to correct actions Procedures 1053 & 1053A revised to currect procedural violations MILLS,L M Tennessee Valley Authority 84/07/19 (Region 2. Office of Director 2pp 26257 353 24X Fiche 30-259, 84/07/31,8408270176
- B408010333 IE Info Notice B4-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl
  JORDAN.E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) B4/08/06 Consolidated Edison Co of New
  York, Inc 85pp 26068 001 24% Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24% Fiche 50-000.84/08/06,8408010337
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Respective (Post 830103) 84/08/09 Consolidated Edison Co 26129 118 24% Fiche 50-000,84/08/08,8408070120 120pp
- 8408070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl list enc! GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche. 50-000, 84/08/10, 8408070376
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping" 408100009 It into musice 5. 3... Svc list encl JORDAN: EL Bivision of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York: Inc 119pp 26197 218 24X Fiche 50-000.84/08/13,8408100009
- 8408230147 Ack receipt of 840801 ltr informing NRC of steps taken to correct violations noted in IE Insp Ropts 50-259/64-15, 50-260/84-15 & 80-296/84-15 CEWIS.R C Region 2. Office of Director 84/08/13 PARRIS.H G Tennesses Valley Authority 1p 26206 316 24X Fiche 50-259.84/08/13.8408230167
- --8408230180 Ack receipt of 840629 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/84-15. 50-260/64-15 & 50-276/84-15 Supplemental response expected LÉMIBIR C Region 2, Office of Director 84/07/12 PARRIS,H O Tennessee Valley Authority 1p 26206 317 24X Fiche 30-259,84/08/13,8409230167
- -8408230192 Responds to NRC 840712 ltr re violations noted in IE Insp Repts 50-259/84-15,50-260/84-15 & 50-276/84-15 Corrective actions total sys walkdown for control air sys flow diagrams performed by plant personnel HILLS.L M Tennessee Valley Authority 84/08/01 0'REILLY.J P Region 2: Office of Director App 26206-318 24X Fiche 50-259,84/08/13,8408230167
- -8408230208 Responds to NRC 840523 ltr re violations noted in IE Insp Repts 30-259/84-15.30-260/84-15 & 80-294/84-15 Corrective actions 8td Practice 14 25 revised to require second party verification in hanging & removing clearance tags MILLBL M Tonnessee Valley Authority 84/06/29 0'REILLY, J P. Region 2, Office of Diractor 11pp 26206-324 24X Fiche 50-259,84/08/13,8408230167
- --B408230219 Forwards IE Insp Repts 50~259/84-15.50~260/84-15 & 50-276/84-15 on 840326-0425 & notice of violations Add1 attention must be given to Tech Spec maint LEWIS.R C Region 2. Office of Director 84/05/23 PARRIS.H Q Tennessee Valley Authority 2pp 26206 335 24X Fiche 50-259.84/08/13.8408230167

- --8408230225 Notice of violation from insp on 840326-0425
   Region 2, Office of Director 84/05/23 5pp 26;
  Fiche 50-259,84/08/13,8408230167 26206 337
- 408230240 IE Insp Repts 50-259/84-15.50-260/84-15 & 50-296/84-15 on 840326-0425 Violations noted misaligned sys valves on control air compressor, incorrect valve on control air sys & inadequate fire protection surveillance procedures PAULK. © L. PATTERSON. C. A. CANTRELL, F. S. Region 2. Office of Director 84/05/17 14pp 26206 342 24X Fiche 50-259.84/08/13.8408230167 --8408230240 IE Imsp Repts 50-259/84-15.50-260/84-15 & 50-296/84-15 on
- 8408100038 IE Info Notice 84-64. "BWR HPCI Initiation Seal-In & Indication "Svc list encl
  JORDANNE L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/15 Consplidated Edison Co of New
  York, Inc. 104pp 26178 093 24X Fiche 50-000.84/08/15, 8408100038 104pp
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Syc list encl
  - list encl
    JORDAN, Et. Division of Emergency Preparedness & Engineering
    Response (Post 830103) 84/08/16 Consolidated Edison Co of New
    York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021
- 8408100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- B408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York Inc 122pp 26276 122 24X Fiche 50-000.84/08/17.8408140208
- B40B240109 Forwards response to NRC B40720 ltr re violations noted in listed insp repts & Proposed Civil Penalty Action EA B4-025 Corrective actions include rev to Plant Instruction T1-4 to upgrade post-trip review Civil penalty fee will be wired DDMER. J A Tennessee Valley Authority B4/08/20 DEVDUNG. R C DIrector's Office. Office of Inspection and Enforcement 10pp 26228 233 24% Fiche 50-239, 84/08/20, 8408240109
- B408210142 IC Info Notice B4-6B, "Potential Deficiency in Improperly Rated Field Wiring to Solonoid Valves " Svc list enc) JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/21 Consolidated Edison Co of New York Inc 115pp 26329 008 24X Fiche 50-000.84/08/21,8408210142
- R Periodic operating reports & related correspondence
- B408060098 "NPDES Discharge Monitoring Rept for Apr 1984" \* Tennessee Valley Authority \_\_84/04/30 54pp 25935 \* Tennessee Valley Authority ( Fiche 50-259,84/04/30,8408060098 25935 208 24X
- B4082/0366 Forwards "Effluent & Waste Disposal Semiannual Rept. Supplemental Info.First Half 1984" & revised "Effluent & Waste Disposal Semiannual Rept Liquid Releases for Second Half 1983 Batch Mode "
  JONES O T Tennesse Valley Authority 84/08/21 Directo Office Office of Inspection and Enforcement 1p 26240 320 Fiche 50-259.84/08/21.8408270366 Director's 1p 26240 320
- --8408270369 "Effluent & Waste Disposal Semiannual Rept Supplemental Info, First Half 1984 "
  - \* Tennesses Valley Authority Fiche 50-259.04/08/21.8408270366 84/06/30 15pp 26240 321 24X
- ---B408270374 Revised "Effluent & Waste Disposal Semiannual Rept Liquid Releases for Becond Half 1983 Batch Mode " \* Tennessee Valley Authority B3/12/31 ip 26240 336 24X Fiche 50-239,84/08/21,8408270366
- S Reportable occurrences, LERs & related correspondence
- 8408220317 Part 21 rept re failure of ITE-27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diade must be added Affected units listed DUVALL.D D Brown Boveri Corp (subs of Brown Boveri & Co. Ltd.) 84/03/13 DEYDUNG, R.C. Director's Office, Office of Inspection and Enforcement 3pp 26191-357 24X Fiche 50-000.84/03/13, 8408220317
- B408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated BHERMOOD, G O General Electric Co 84/04/13 DEYOUNG, R C Director's Office. Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000,84/04/13,8408240348.

- 8408090341 LER 83-016/03X-2 on 830309 analysis of charcoal sample from control room emergency ventilation sys showed methyl indide removal efficiency of less than 90% Caused by degradation of stored charcoal prior to use W/840713 ltr CLARK.J R. JONES.Ø T Tennessee Valley Authority 84/07/13 O'REILLY.J P. Region 2. Office of Director 5pp 25994 059 24% Fiche 90-259,84/07/13.8408090341
- 8408030257 Updated LER 84-022-01 on 840212, investigation determined that single failure or LOCA & loss of offsite power could cause equipment necessary for electrical board room cooling to be lost Caused by design oversight W/840720 ltr WALMER, J. B. JONES, G. T. Tennessee Valley Authority 84/07/20 3pp 25917 241 24X Fiche 50-259, 84/07/20, 8408030257
- 8408060113 LER 84-027-00 on 840627 during startup & at 1% power & rated pressure main steam relief valve began to unseat causing torus temp to approach limits Unit manually scrammed Cause unstated Valve replaced & unit restarted W/840724 ltr SMITH.D L . JONES.G T Tennessee Valley Authority 84/07/24 3pp 25936 030 24X Fiche 50-259.84/07/24.8408060113
- 8408080518 LER 84-023-01 on 840518, during replacement of failed relay 16AK20, adjacent internal panel wire supplying power to primary containment isolation valves came loose Caused by wire incorrectly terminated W/840727 ltr SMITH, D. . JONES, O.T. Tennesses Valley Authority 84/07/27 3pp 25975 269 24X Fiche 50-259,84/07/27,0408080518
- 8408090020 Updated LER 83-018/031-2 on 830325, while performing SI 4 2 A-13, standby gas train B found inoperable Caused by erratic McDonnel & Miller flow switch Ewitch replaced & SI 4 7 B-1 & SI 4 7 A-13 completed M/840727 ltr CARTER, S. JONES, G T Tennessee Valley Authority 84/07/27 3pp 25793 247 24% Fiche 50-259,84/07/27,8408090020
- 8408160508 LER 84-022-02 on 840512, IE Bulletin 79-018 investigation determined that single failure or LOCA & loss of offsite power could cause loss of electric board room cooling equipment Operating instructions revised W/840808 ltr WALKER, J B , JONES, G T Tennessee Valley Authority 84/08/08 3pp 26107 357 24X Fiche 50-259,84/08/08,8408160508
- 8408160518 LER 84-021-01 on 840505, automatic depressurization systematic telefolic cables not fully separated from nonautomatic depressurization systeller valve cables Caused by design error Mods completed on 840524 W/8408080 ltr ROBERTS, W A , JONES, C T Tennesses Valley Authority 84/08/08 3pp 26107 361 24X Fiche 50-259,84/08/08.8408160518
- 840B160519 LER 84-028-00 on 840710 automatic discharge transfer logic for HPCI from discharging to condensate storage tanks to reactor vessel failed Caused by dirty contact on limit switch Contact cleaned W/840808 ltr SMITH, D. L. JONES, G. T. Tennessee Valley Authority 84/08/08 3pp 2610B 024 24X Fiche 50-259,84/08/08,8408160519
- 8408140331 Requests approval of proposed Tech Spec 178 re failure of containment atmospheric dilution sys torus supply valve on 840717 Approval needed by 840817 to prevent forced shutdown DOMER. J A Tennessee Valley Authority 84/08/07 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 26042 353 24X Fiche 50-259,84/08/09.8408140331
- 8408200300 LER 84-026-01 on 840620, unidentified drywell laakage exceeded Tech Spec conlant leakage rate of 5 gpm Orderly shutdown initiated & unit manually scrammed at 97% power Seal replaced W/840810 ltr ROBERTS, W A , JONES, O T Tennessee Valley Authority 84/08/10 3pp 26140 087 24% Fiche 50-259,84/08/10,8408200300
- B408230040 PNO-II-84-049 on B40814, possible overpressurization of one care spray sys loop occurred Caused by backflow of primary coolant into loop because outboard isolation valve & inboard isolation check valve leaked BUTCHER, R C , CANTRELL, F 9 Region 2, Office of Director 84/08/15 2pp 26204 018 24X Fiche 50-259, 84/08/15, 8408230040
- 8408280349 LER 84-029-00 on 840720,24 h limiting condition for operation entered when ASME Section XI pump pressure criteria not met for four RHR svc water pumps Tech Spec flow methout pumps declared inoperable H/840817 ltr SMITH.D.L., JONES, O.T. Tennessee Valley Authority 84/08/17. 3pp 26282 275 24X Fiche 50-259,84/08/17,8408280349
- 8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers. Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
  VILLA: R General Electric Co 84/08/21 RQSBI.CE Director's Office, Office of Inspection and Enforcement 3pp 26318 327 24X Fiche 50-000,84/08/21,8408310186

#### V Operator Examinations

- 8408310036 Confirmation of action ltr re 040521 telcon between RC Lewis & JA Coffey concerning results of operator exams conducted on 840323 Operators who failed exam prohibited from licensed duties until Sections & or 7 completed satisfactority O'REILLY.J P. Region 2. Office of Director 84/05/23 PARRIS.H Q Tennessee Valley Authority 3pp 26335 020 24X Fiche 50-259.84/05/23.8408310036
- DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2

  F. Security, medical, emergency & fire protection plans
- 8408300402 Forwards summary of 840530 meeting w/TVA Alabama Power Co, Florida Power Corp.Florida Power & Light & Georgia Power Core selected emergency preparedness issues O'REILLY. J.P. Region 2. Office of Director 84/06/08 PARRIS, N.O. Tennessee Valley Authority 4pp 26308 116 24X Fiche 50-000.84/06/08.8408300402
- ---8408280116 Responds to NRC 840607 ltr re violations noted in Insp. Repts 50-259/84-17,50-260/84-17 & 50-296/84-17 Corrective actions: temporary fire load form posted & daily fire load insps performed until removal of combustibles MILLS.L M Tennessee Valley Authority 84/07/07 D'REILLY, J.P. Region 2. Office of Director 2pp 26261 320 24X Fiche 50-259,84/07/25,8400280096
- ---8408280124 Forwards Insp Repts 50-259/84-17,50-260/84-17 & 50-296/84-17 on 840508-11 & notice of violation VERRELLI,D M Region 2, Office of Director 84/06/07 PARRIS.H 0 Tennessee Valley Authority 2pp 26281 322 24X Fiche 50-259,84/07/25,8408280096
- --8408280134 Notice of violation from insp on 040500-11 \* Region 2, Office of Director 84/06/07 ip 26281 324 24X Fiche 30-257.84/07/25,8408280096
- --8408280140 Insp Repts 50-299/84-17.30-260/84-17 & 50-294/84-17 an 840508-11 Violations noted failure to follow fire prevention procedures for control of temporary fire loads MADDEN.P K Region 2. Office of Director 84/06/01 3pp 24X Ficho 50-259.84/07/25.8408280096
- 8408020149 Forwards revs to implementing procedures document, consisting of IP-6. "Activation of Technical Support Ctr." IP-20. "Technical Support Ctr Depration" & Ray 14 to "Radiological Emergency Plan" MILLB.L M Tennessee Valley Authority 84/07/27 C'REILLY, J P Region 2. Office of Director 1p 25886 011 24X Fiche 50-259,84/07/27. 8408020145
- --8408020151 Revs to radiological emergency plan procedures, consisting of IP-6, "Activation of Technical Support Ctr" & IP-20, "Technical Support Ctr Operation" a Technical Support Ctr Operation Technical Support Valley Authority 84/07/27 12pp 25806 012 24X Ficho 50-257,84/07/27,8408020145
- --8408020156 Rev 14 to "Radiological Emergency Plan "

  \* Tennossee Valley Authority BFN-REP R14 84/06/29 4pp
  25886 024 24X Fiche 56-259,84/07/27,8408020145
- B408030015 Forwards safety analysis, implementation plan & implementation schedule for safety parameter display mys.per DB Vassallo 840612 confirmatory order to HO Parris MILLE, LM Tennessee Valley Authority 84/07/30 DENTON, H, R. Office of Nuclear Reactor Regulation. Director App. 25907:116
- 8408230167 Ack receipt of 840801 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/86-15 LEWIS, R C Region 2. Office of Director 84/08/13 PARRIS, H, Q Tennssee Valley Authority in 26206 316 24% fiche 50-259,84/08/13,8408230167
- --8408230192 Responds to NRC 840712 ltr re violations noted in IE Insp. Repts 50-259/84-15.50-260/84-15 & 50-296/84-15. Corrective actions total sys walkdown for control air sys flow diagrams performed by plant personnel MILLS, L. M. Tennessee Valley Authority 84/08/01, O'REILLY, J. P. Region 2, Office of Director 6pp 26206-318-24X Fiche 50-259,84/08/13,8408230167.

- ~-B40B230208 Responds to NRC B40523 itr re violations noted in IE Insp Repts 50-259/84-15.50-240/84-15 % 50-276/84-15 Corrective actions Std Practice 14 25 revised to require second party verification in hanging & removing clearance tags MILLS.L M Tennessee Valley Authority B4/06/27 O'REILLY, J P Region 2. Office of Director 11pp 26206 324 24X Fiche 50-259,84/08/13,8408230167
- ~-8408230225 Notice of Violation from Insp on 840324-0425 \* Region 2, Office of Director 84/05/23 5pp 25205 337 24X Fiche 50-259,84/08/13,8408230167
- --8408230240 IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15 on 840326-0425 Violations noted misaligned sys valves on control air compressor, incorrect valve on control air sys & inadequate fire protection surveillance procedures PAULK, 0 L. Region 2, Office of Director 84/05/17 14pp 86206 342 24X Fiche 50-259,84/08/13,8408230167
- 8408290245 Forwards justification which supple 840612 schedular exemption request re fire protection mode MILLS,L M Tennessee Valley Authority 84/08/23 DENTON,H R Office of Nuclear Reactor Regulation, Director 7pp 26290 317 24X Fiche 50-259,84/08/23,8408290245
- P Operating license stage documents & correspondence
- 8408300434 Confirms 840801 telcon between JA Coffey & RC Lewis re 340821 enforcement conference in Region II of< to discuss design problems w/power supply & distribution sys Proposed agenda encl O'REILLY, JP Region 2, Office of Director 84/06/05 PARRIS, H B Tennessee Valley Authority 2pp 26314 328 24X Fiche 30-259,84/06/05.8408300434
- 8408140026 Forwards requests for addl info re Mark I containment longterm program vent sys analysis & details of seismic lugs Recommends 840910 meeting w/BNL & Franklin Research Ctr to discuss response prior to submittal of formal response VASSALLO.D B Operating Reactors Branch 2 84/07/26 PARRIS, H G Tennessee Valley Authority 14pp Fiche 50-299,84/07/26/8408140026
- 8408010344 Responds to 840613 request for add1 info re Mark I containment long-term program analyses Safety relice valve discharge piping sys mods based on most severe reflood conditions predicted by RVRII & RVFDR codes MILLS.L M Tennessee Valley Authority 84/07/27 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 25866 322 24X Fiche 50-259.84/07/27,8408010344
- 8408130026 Forwards Amends 104 & 98 to Licenses DPR-33 & DPR-52, respectively & safety evaluation Amends change Tech Specs to delete surveillance requirements for Dampers FCO-150A & FCO-150C CLARK, R J Operating Reactors Branch 2 B4/07/27 PARRIS, H O Tennessee Valley Authority 2pp 26030 329 24X Fiche 50-259,84/07/27,8408130026
- --8408130032 Amends 104 ½ 98 to Licenses DPR-33 & DPR-52, respectively, changing Tech Specs to delete surveillance requirements for Dampers FCO-1506 & FCO-1506 VASSALLO, D B Derating Reactors Branch 2 84/07/27 8pp 24038 331 24X Fiche 50-259,84/07/27,8408130026
  - B408130037 Safety evaluation supporting Amends 104 & 78 to Licenses DRR-33 & DRR-32, respectively \* Office of Nuclear Reactor Regulation, Director 24038 339 24X Fichs 30-259, B4/07/27, B408130026
- .408150575 Responds to 830422 submittal of Tech Bpec amends per TMI
  Item I A 1 3, "Limit Overtime" & Generic Ltr 83-02 Tech
  Spec change request to snaure overtime controls implemented.
  required
  VASSALLO.D B Operating Reactors Branch 2 84/07/27 PARRIS.H Q
  Tennessee Valley Authority 2pp 26080 353 24x
  Fiche 50-259.84/07/27.8408150575
- 8408160155 Forwards SER on NUREC-0737. Item 11 X 3 22 re automatic suitchover of RCIC sus suction Manual switchover of RCIC sus suction Manual switchover of RCIC suction on low water level in condensate storage tank acceptable value of the suspension of the suspension of the value of the suspension of the suspension of the value of the suspension of th
- 8408160424 Forwards Amends 105,99 & 72 to Licenses DPR-33,DPR-52 & DPR-68, respectively & safety evaluation Amends replace word "Operator" w/ "reactor operator" to provide consistent nomenclature CLARK-R J Operating Reactors Branch 2 84/07/30 PARRIE, H G Tennesse Valley Authority 3pp 26126 229 24X Fiche 50-259,84/07/30,8408160424

- --8408160427 Safety evaluation supporting Amends 105,99 & 72 to Licenses DPR-33, DPR-52 & DPR-66, respectively
  \* Office of Nuclear Reactor Regulation, Director 84/07/30 2pp 26126 244 24X Fiche 30-259,84/07/30,8408160424
- 9408070370 Suppl 1 to 831027 application for amend to Licenses DPR-33, DPR-52 & DPR-68, consisting of minor revs to Tech Specs in response to NRC 831220 comments & request for addl info MILLS, L M Tennessee Valley Authority 84/08/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 25947 176 24X Fiche 50-259,84/08/01,8408070370
- ---8408070375 Proposed Tech Spec re radioactive gaseous effluent instrumentation surveillance
  \*\* Tennessee Valley Authority 84/08/01 44pp 25947 178 24X
  Fiche 50-259,84/08/01.8408070370
- 8408200264 Forwards Amends 106,100 & 73 to Licenses DPR-33, DPR-52 & DPR-66, respectively & safety evaluation Amends Clarify correct operating positions & identify proper action for initiating signal for suppression chamber drain valves CLARK, R. J. Operating Reactors Branch 2 84/08/02 PARRIS, H. O. Tennessee Valley Authority 2pp. 26142 345 24% Fiche 50-259,84/08/02,8408200264
- --8408200269 Amends 106.100 & 73 to Licenses DPR-33, DPR-52 & DPR-68, respectively Amends change Tech Specs re suppression chamber drain valves, clarify operating positions & identify proper action in initiating signal VASSALLO, D B Operating Reactors Branch 2 84/08/02 12pp 26142 347 24X Fiche 50-259,84/08/02,8408200264
- ---B408200280 Safety evaluation supporting Amends 104,100 & 73 to Licenses DPR-33, DPR-52 & DPR-60, respectively \* Office of Nuclear Reactor Regulation, Director 84/08/02 2pp 26142 359 24X Fiche 50-259,84/08/02,8408200264
- 8408070110 Generic Ltr 84-19 to all licenses of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl CIBENHUT.D 0 Division of Licensing B4/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000.84/08/06.8408070110
- 8408140375 Forwards response to NRC 831012 request for add1 info re reactor protection sys power monitoring sys design mods. Tech Specs will be submitted in future W/12 oversize drawings Aperture cards available in PDR DDMER. J A Tennessee Valley Authority 84/08/09 DENTON, H R Office of Nuclear Reactor Regulation. Director 11pp 26081 187 24X Firbs 50~259,84/08/09,8408140375
- 840820390 Forwards notice of environ assessment & finding of no significant impact re 840402 application for exemption from requirements of 100FR50, App J
  VASSALLO, D B Operating Reactors Branch 2 84/08/09 PARRIS. H G
  Tennessee Vallay Authority 2pp 26/41 210 24x
  Fiche 50-260,84/08/09,8408200390
- --8408200393 Notice of environ assessment & finding of no significant impact re 840725 exemption from requirements of 10CFR50, App J VASBALLD, D B Operating Reactors Branch 2 84/08/09 3pp 26141 212 24X Ficho 50-260,84/08/09,8408200390
- 8408210003 Forwards Amends 107.101 & 74 to Licenses DPR-33.DPR-52 & DPR-68.respectively & safety evaluation Amends change Tech Specs to allow operation for 30 days w/16 main steam tunnel high tump switches bypassed CLARK,R J Operating Reactors Branch 2 84/08/09 PARRIS,H G Tennessee Valley Authority 2pp 26195 194 24X Fiche 50-259.84/08/09.8408210003
- --8408210004 Amends 107.101 & 74 to Licenses DPR-33, DPR-52 & DPR-68, respectively, changing Tech Specs to allow operation for 30 days w/ib main steam tunnel high temp switches bypassed VASSALLO, D B Operating Reactors Branch 2 84/08/09 12pp 26195 196 24X Fichs 50-259,84/08/09,8408210020
- --8408210007 Safety evaluation supporting Amends 107.101 & 74 to Licenses DPR-33.DPR-52 & DPR-6B, respectively \* Dffice of Nuclear Reactor Regulation, Director 26195 208 24X Fichs 50-259.84/08/09.8408210003

- 8408200131 Forwards response to 840501 ltr re Criteria 1,2,10 & 11 for permanent post-accident sampling facility Info on interim sys submitted on 840406
  DDMER.J A Tennessee Valley Authority 84/08/13 DENTON.H R
  Office of Nuclean Reactor Regulation. Director 5pp 26133 255
  24X Fiche 50-259,84/08/13.8408200131
- 8408200437 Forwards exemption to test interval requirements of App J to 10CFRSO.in response to 840402 request Two-yr test interval for performing local leav rates extended to 840915 for components specified in exemption VASSALLO.D B Operating Reactors Branch 2 84/08/13 PARRIS.H G Tennessee Valley Authority 2pp 26144 329 24X Fiche 50-260.84/08/13.8408200437
- --8408200441 Exemption from lest interval requirements of App J to 10CFR50 re local leak rate test interval for specified components

  EISENHUT D O Division of Licensing 84/08/13 Tennessee Valley Authority 7pp 26144 331 24X Fiche 50-260,84/08/13,8408200437
- B408220137 Application for amend to Licenses DPR-33, DPR-52 & DPR-68, incorporating integrated schedule into license Detailed explanation of methodology utilized definition of revised integrated schedule & fee enci MILLS.L M Tennesse Valley Authority 84/08/14 DENTON.H R Office of Nuclear Reactor Regulation. Director 84pp 26193-318-24X Fiche 50-259,84/08/14,8408220137
- 8408280257 Forwards Amends 110.103 & 76 to Licenses DPR~33, DPR-52 & DPR~6B, respectively & safety evaluation Amends revise Tech Specs to permit main steam line high temp isolation function to be inoperable for up to 4 h for testing & main t CLARK, R J Operating Reactors Branch 2 84/08/15 PARRIS, H G Tennessee Valley Authority 2pp 26294 090 24% Fiche 50-259,84/08/15,8408280257
- --8408280261 Amends t10.103 & 76 to Licenses DPR-33, DPR-52 & DPR-68, respectively, revising Tech Specs to permit main steam line high temp isolation function to be inoperable for up to 4 h for testing & maint purposes VASSALLO, D B Operating Reactors Branch 2 84/08/15 15pp 26294 092 24X Fiche 50-259,84/08/13,8408280257
- --8408280276 Safety evaluation supporting Amends 110,103 & 74 to Licenses DPR-93, DPR-82 & DPR-68, respectively \* Office of Nuclear Reactor Regulation, Director 84/08/15 2pp 26294 107 24X Fiche 50-259,84/08/15,8408280257
- 8408310424 Forwards Amends 104 & 77 to Licenses DPR-52 & DPR-68, respectively & safety evaluation Amends revise Tech Specs to change neutron flux trip setting adjustment factor CLARK, R J Operating Reactors Branch 2 84/08/17 PARRIS, H G Tennessee Valley Authority 2pp 26350 142 24X Fiche 50-260,84/08/17,8408310424
- --8408310431 Amends 104 & 77 to Licenses DPR-52 & DPR-68, respectively, revising Tech Specs to change neutron flux trip setting adjustment factor from limiting safety sys to limiting condition for operation w/6 h action statement VASSALLO,D B Operating Reactors Branch 2 84/08/17 32pp 26350 144 24X Fiche 50-260,84/08/17,8408310424
- --9408310432 Safety evaluation supporting Amends 104 & 77 to Licenses DPR-52 & DPR-68.respectively \* Office of Nuclear Reactor Regulation, Director 84/08/17 2pp 26350 176 24% Fiche 50-260,84/08/17,8408310424
- 840B200275 Generic Ltr 84-20 to all licenses of operating reactors & applicants for QLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EIBEMHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 30-000,84/08/20,8408200275
- 8408280220 Application for amend to License DPR-52, changing Tech Specs to accommodate Unit 2, Cycle & operation & reflecting plant mods to be performed during refueling outage MILLS.L M Tennessee Valley Authority 84/08/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 26267 201 24X Fiche 50-260,84/08/23,8408280220
- --8408280222 Proposed Tech Specs reflecting plant mods to be performed during refueling outage & changing Tech Specs to accommodate Unit 2.0ucle & operation # Tennessee Valley Authority 84/08/23 53pp 26267 204 24X Fichs 50-260,84/08/23.8408280220

- --8408280226 'Reload Licensing Rept for Browns Ferry Unit 2, Cycle 6 " Determination of no significant hazards encl \* Tennessee Valley Authority TVA-RLR-002 84/07/31 38pp 26269 282 24X Fiche 50-260.84/08/23,8408280220
- B408310414 Notification of 840913 meeting w/util & Franklin Research Ctr in Knoxville.TN to discuss resolution of issues identified in request for add info on structural evaluation in plant-unique analysis rept re Mark I turus mod CLARK.R J Operating Reactors Branch 2 84/08/24 VASSALLO,D B Operating Reactors Branch 2 1p 26350 222 24x Fiche 50~259.84/08/24,8408310414
- B40B310420 Natification of 840905 meeting w/util & ENL in Knoxville.TN to discuss resolution of issues identified in staff request for additure on hydrodynamic loads in plant-unique analysis rept re Mark I torus mode CLARK.R J Operating Reactors Branch 2 84/08/24 VASSALLO,D B Operating Reactors Branch 2 84/08/24 VASSALLO,D B Fiche 50-299,84/08/24,8408310420
- G Inspection reports, IE Bulletins & correspondence
- 8407100322 Responds to 840609 ltr providing results of reanalysis of four walls info resolves concerns re four walls identified in 840116 SER concerning IC Bulletin 83-11, "Masonry Wall Design"

  VABSALLO, D B Operating Reactors Branch 2 84/06/26 PARRIS, H 0 Tennessee Valley Authority 2pp 25513 317 24x

  Fichs 50-259,84/06/26,8407100322
- 8408310109 Forwards Enforcement Conference Repts 50-259/84-21, 50-260/84-21 & 50-276/84-21 on 840621 O'REILLY, J P Region 2, Office of Director 84/07/09 PARRIS, H O Tennessee Valley Authority 2pp 26334 227 24X Fichs 50-259,84/07/09,8408310109
- --8408310114 Enforcement Conference Repts 50-259/84-21,50-260/84-21 & 50-295/84-21 on 840421 Major areas discussed design errors associated wiseparation of electrical cables, paralleling diesel generators & shutdown board room cooling BUTCHER.R C Region 2. Defice of Director CANFRELL.F 8 Division of Project & Resident Programs 84/07/05 App 26334 229 24X Fiche 50-259,84/07/09.8408310109
- 8408240338 Forwards Insp Repts 50-259/84-22,50-260/84-22 t 50-296/84-22 on 840626-29 No violations or deviations noted VERRELLI,D M Region 2, Office of Director 84/07/12 PARRIS,H O Tennossee Valley Authority 2pp 26236 131 24X Fiche 50-259,84/07/12,8408240338
- --B40B240342 Insp Repts 50-259/B4-22,50-260/B4-22 & 50-296/B4-22 on B40626-29 No violations or deviations noted Major areas inspected licensee action on previous enforcement matters, welding, inservice testing, IE bulletins & LERs GIRARD,E H., BLAKE,J J. Region 2. Defice of Director 84/07/12 6pp 26236 133 24X Fiche 50-259,84/07/12,840B240338
- 8408280096 Ack receipt of 840709 ltr informing NRC of steps taken to correct violations noted in Insp Repts 30~259/84-17, 50~254/84-17 & 50~254/84-17 WERRELLI,D M Region 2, Office of Director 84/07/25 PARRIS,H G Tennessee Valley Authority ip 26281 319 24X Fiche 50~239,84/07/25,8408280096
- --8408280116 Responds to NRC 840607 ltr re violations noted in Insp Repts 50-259/84-17.50-260/84-17 & 50-276/84-17 Corrective actions temporary fire load form posted & daily fire load insps performed until removal of combustibles MILLS.L M Tennessee Vallay Authority 84/07/09 O'REILLY, J P Region 2. Office of Director 2pp 26281 320 24X Fiche 80-259,84/07/25.8408280076
- --B40B280124 Forwards Insp Repts 50-259/84-17, 50-260/84-17 & 50-294/84-17 on 840508-11 & notice of violation VERNELLI,D M Region 2, Office of Director 84/04/07 PARTB,H 0 Tennessee Valley Authority 2pp 26281 322 24X Fiche 50-259,84/07/25,8408280096
- --8408280134 Notice of Violation from insp on 840908-11 \* Region 2, Office of Director. 84/06/07 ip 26281 324 24% Fiche 50-259,84/07/25,8408280096
- --8408280140 Insp Repts 50-259/84-17.50-260/84-17 & 50-296/84-17 on 840508-11 Violations noted failure to follow fire prevention procedures for control of temporary fire loads MADDEN, P H . MILLER, W H . COM.ON.T E Region 2. Office of Director 84/06/01 9pp. 26281 325 24X Fiche: 50-259.84/07/25, 8408280096

- B407250229 IE Info Notice B4-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants "Svc list encl JDROAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/07/27. Consolidated Edison Co of New York, Inc. 119pp 23865 047 24X Fiche 50-000.84/07/27. B007250227
- 8408270196 Ack receipt of 840719 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-259/84-10. 50-260/84-10 & 50-296/84-10 WERELLI, D M Region 2, Office of Director 84/07/31 FARRIS, H G Tennessee Valley Authority 1p 26257 352 24X Fiche 50-259,84/07/31.8408270196
- --8408270199 Responds to NRC 840509 ltr re violations noted in Insp Repts 50-259/84-10.50-260/84-10 & 30-296/84-10 Corrective actions Procedures 1053 & 1053A revised to correct procedural violations MILLS.L M Tennessee Valley Authority 84/07/19 0'REJLLY.J P Region 2. Office of Director 2pp 26257 353 24X Fiche 50-259.84/07/31.8408270196
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 800103) 84708/05 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 138 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York, Inc. 120pp 26129 118 24X Fiche 50-000.84/08/08.8408070120
- B40B070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl GRACE.J N Bivision of CA. Safeguards & Inspection Programs (Post B30103) B4/0B/10 Consolidated Edison Co of New York, Inc 125p. 26130 001 24X Fiche 50-000.B4/0B/10.B40B070376
- 840B100007 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Eve list encl
  JORDAN,E t. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc. 119pp 26197 218 24% Fiche 30-000.84/08/13,840B100009
- 8408230167 Ack receipt of 840801 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15
  LEWIS.R C Region 2, Office of Director 84/08/13 PARRIB.H O Tennessee Valley Authority 1p 26206 316 24X
  Fiche 50-259.84/08/13.8408230167
- --B40B230180 Ack receipt of B40629 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15 Supplemental response expected by B40B01 LEWIS.R C Region 2, Office of Director B4/07/12 PARRIS.H Q Tennessee Valley Authority. Ip 26206 317 24X Fiche 50-259,84/08/13,8408230167
- -8408230192 Responds to NRC 840712 ltr re violations noted in 1E Insp Repts 50-259/84-15, 50-240/84-15 & 50-296/84-15 Corrective actions total sys walkdown for control air sys flow diagrams performed by plant personnel MILLS-L M Tennessee Valley Authority 84/08/01 0'REILLY-J P Region 2. Office of Director 6pp 26206 318 24X Fiche 50-259,84/08/13,8408230167
- -8408230208 Responds to NRC 840523 ltr re violations noted in IE Insp Repts 50-259/84-13, 50-260/84-15 & 50-296/84-15 Corrective actions 8td Practice 14 25 revised to require second party verification in hanging & removing clearance tags MILLS, L M Tennessee Vallay Authority 84/06/29 O'REILLY, J P Region 2, Office of Director lipp 26206 324 24% Fiche 50-259,84/08/13,8408230167
- --8408230219 Forwards IE Insp Repts 50-259/84-15.50-260/84-15 & 50-296/84-15 on 840326-0425 & notice of violations Addl attention must be given to Tech Spec maint LEWIGR C Region 2, Office of Director 84/05/23 PARRIB, H. Q Tannessee Valley Authority 2pp 26206 335 24X Fiche 50-259,84/08/13,8408230167

- --B408230225 Notice of violation from insp on 840326-0425 \* Region 2, Office of Director B4/05/23 5pp 26206 337 24) Fiche 50-259, B4/08/13,8408230167
- --8408230240 IE Insp Repts 50-259/84-15.50-260/84-15 & 50-296/84-15 on 840326-0425 Violations nated misaligned sys valves on control air compressor.incorrect valve on control air sys & inadequate fire protection surveillance procedures PAULK.G L . PATTERSON.C A . CANTRELL.F S Region 2. Office of Director 84/05/17 14pp 26206-342 24X Fiche 50-239.84/08/13, 8408230167
- B408100038 IE Info Notice B4-64, "BWR MPCI Initiation Seal-In & Indication " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co. of New York, Inc. 104pp 26198 093 24% Fiche 50-000,84/08/15,8408100038
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc. (18pp 26198 001 24X Fiche 50-000.84/08/16.8408100021
- 8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- 8408140208 IE Info Notice 84-67. "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000.84/08/17,8408140208
- 8408240107 Forwards response to NRC 840720 ltr re violations noted in listed insp repts & Proposed Civil Penalty Action EA 84-025 Corrective actions include rev to Plant Instruction TI-74 to upgrade post-trip review Civil penalty fee will be wired DOMER. J A Tennessee Valley Authority 84/08/20 DEYOUNG. R C Director's Office. Office of Inspection and Enforcement 10pp 26228 233 24X Fiche 50-257.84/08/20.8408240107
- 8408210142 IC Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of Now York, Inc. 115pp 26329 008 24X Fiche 50-000.84/08/21.8408210142
- R Periodic operating reports & related correspondence
- B40806009B "NPDES Discharge Monitoring Rept for Apr 1984 "
  \* Tennessee Valley Authority 84/04/30 54pp 25935 208 24X
  Fiche 50-259.84/04/30.8408060098
- 8408270366 Forwards "Effluent & Waste Disposal Bemiannual Rept.
  Supplemental Info.First Half 1984" & revised "Effluent &
  Waste Disposal Semiannual Rept Liquid Releases for Second
  Half 1983 Batch Mode "
  JONES.G T Tennessee Valley Authority 84/08/21 Director's
  Office. Office of Inspection and Enforcement ip 26240 320 24X
  Fiche 50-259.84/08/21.8408270366
- --8408270369 "Effluent & Waste Disposal Semiannual Rept Supplemental Info.First Half 1984" \* Tennessee Valley Authority 84/06/30 15pp 26240 321 24x Fiche 50-259,84/08/21.8408270366
- --BA08270374 Revised "Effluent & Waste Disposal Semiannual Rept Liquid Releases for Second Half 1983 Batch Mode " \* Tennessee Valley Authority 83/12/31 ip 26240 336 24X Fiche 50-239,84/08/21,8408270366
- 8 Reportable occurrences, LERs & related correspondence
- B408220317 Part 2: rept re Pailure of ITE-27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diode must be added Affected units listed DUVALL,D D Brown Bover: Corp. (subs of Brown Bover: & Co., Ltd.) 84/03/13 DEYGUNG,R C Director's Office, Office of Inspection and Enforcement 3pp 26191 357 24% Fiche 50-000,84/03/13,8408220317
- 8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated SHERMOOD, G C Qeneral Electric Co 84/04/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24% Fiche 50-000,84/04/13.8408240348

840B310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of GAOB20 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
VILLA: General Electric Co 84/08/21 ROSSI.C & Director's
Dffice Office of Inspection and Enforcement 3pp 26318 327 243
Fiche 50-000.84/08/21.8408310186

#### V Operator Examinations

840B310036 Confirmation of action ltr re 840521 telcon between RC Lewis & JA Coffey concerning issults of operator exams conducted on 840323 Operators who failed exam prohibited from licensed duties until Sections & or 7 completed satisfactorily O'REILLY, J P Region 2. Office of Director 84705723 PARRIS, H G Tennessee Valley Authority 3pp 26335 020 24X Fiche 50-299,84705723,8408310036

#### DOCKET 50-261 H B ROBINSON PLANT, UNIT 2

- F Security, medical, emergency & fire protection plans
- 840B300361 Ack receipt of 840606 ltr re emergency exercise scheduled during wk of 840B22 Final scenario & controller messages will be reviewed when received Comments will be made following evaluation of submittal VERRELLI, D M Region 2, Office of Director 84/06/18 UTLEY, E Carolina Power & Light Co 1p 2630B 213 24X Fiche 50-261.84/06/18,8408300361
- 840B310411 Forwards summary of 840B30 meeting re proposed 10CFR50 54(p) changes to industrial security plans & contractor screening program Meeting beneficial & provided better understanding between security staffs LEWIS.R C Region 2. Office of Director 84/06/19 UTLEY.E E Carolina Power & Light Co 3pp 26339 318 24% Fiche 50-000.84/06/19.8408310411
- 8408240007 Forwards Insp Rept 50-261/84-21 on 840611-15 & notice of violation Notice of violation withheld (ref 10CFR2 790 & 73 21)

  VERRELLI,D M Region 2. Office of Director 84/07/10 UTLCY.E E Carolina Power & Light Co 2pp 26228 249

  Fiche 50-261.84/07/10.8408240007
- --8408240010 Insp Rept 50~261/84-21 on 840611-15 Violation identified failure to maintain security-related equipment in operable condition Details withheld (ref 10CFR2 790 & 73 21)
  TILLMAN, A. ROGUIRE, D. R. Region 2. Office of Director 84/06/28 ip 26228 251 24X Fiche 50-261.84/07/10.8408240007
- 8408030074 Requests two technical exemptions from requirements of 10CFR50, App R, Section 11I G 3 per 10CFR50 12, re 11I G 3 suppression requirements for six plant fire areas & for suppression & detection for single fire area CUTTER, A B Carolina Power & Light Co 84/07/20 VARGA, 8 A Licensing Branch 1 8pp 25906 266 24X Fiche 50-261,84/07/20,8408030094
- 8408030162 Requests uithdrawal of 801202 license amend request re dedicated shutdown sys Implementation of sys concurrent w/ fire protection mods more appropriate Revised request will be submitted by 850329 CUTTER.A B Carolina Pouer & Light Co 84/07/20 VARGA, 9 A Operating Reactors Branch i 2pp. 25912 016 24X Fiche 50~261,84/07/20,8408030162
- 8408060074 Advises that Amend 80 to License DPR-23 re relaxation of physical security requirements of 10CFR73 55 during steam generator repair outage, will not be implemented ZIMMERMAN, 8 R Carolina Power & Light Co 84/07/30 VARGA. 8 A Operating Reactors Branch 1 ip 25933 222 24X Fiche 50-261,84/07/30,8408060074
- 8408310051 Advises that exercise scenario description & concurrence in scope & concept reviewed Detailed exercise package will be reviewed when received & comments provided VERRELLI,D M Region 2. Office of Director 84/08/02 UTLEY,E E Caroline Power & Light Co ip 26334 358 24X Fiche 50-261.84/08/02.8408310051
- 8408100004 Forwards Rev 5 to Emergency Plan & Procedure PEP-2004, "HB Robinson Unit 2 Personnel," per 10CFR30 54(q) Listing of revenc!

  MDRGAN.R E Carolina Power & Light Co 84/08/07 O'REILLY, J P Region 2, Office of Director 2pp 25986 357 24X Fiche 50-261.84/08/07.8408100004
- --B408100010 Rev 5 to Emergency Plan & Procedure PEP-2004, "HB Robinson, Unit 2 Personnel " \* Carolina Power & Light Co '84/08/07 9pp 25986 359 24X Fache 50-261,84/08/07,8408100004

- 8408230073 Responds to 840427 request for exemption from App E to 10CFR50, to exclude state & local govt participation in 840821 annual emergency preparedness exercise Exemption not required in view of 840706 rev to App E to 10CFR50 VARGA. S A Operating Reactors Branch i 84/08/13 UTLEY, E E Carolina Power & Light Co 2pp 26233 267 24X Fiche 50-261,84/08/15,8408230073
- B40B220126 Requests exemption from 10CFR50.App R. Section II Q 2 to extent that Rockbestos cables inside containment be kept free of fire damage & provides addl technical info.per NRC request Fee encl CUTTER.A B Carolina Power & Light Co 84/08/17 VARQA. S A Operating Reactors Branch 1 7pp 26/19 307 24X Fiche 50-261.84/08/17.8408220126
- 8408300512 Forwards FR notice of environ assessment & finding of no significant impact re 820427,830607 & 840425 requests for exemption from 100FR50,App R to relax requirement for complete area—wide autonatic fire suppression coverage VAR9A.S A Operating Reactors Branch i 84/08/17 UTLEY.E E Carolina Power & Light Co 3pp 26315 318 24X Ficho 50-261,84/08/17,8408300512
- ---840B300515 Notice of environ assessment & finding of no significant impact re 820427,830607 & 840425 requests for exemption from 10CFR50,App R, to relax requirement for complete area-wide automatic fire suppression coverage EISCNHUT,D © Division of Licensing 84/08/17 3pp 26315-321 24X Fiche 50-261,84/08/17,8408300512
- 8408240091 Ack receipt of 840809 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-261/84-21 VERRELLI, D M Region 2. Office of Director 84/08/21 UTLEY, E E Carolina Power & Light Co 1p 26228 246 24X Fiche 50-261,84/08/21.8408240091
- --8408240095 Forwards response NRC 840710 ltr re violations noted in Insp Rept 50-261/84-21 Response withheld (ref 100FR2 790 & 73 21)
  MORGAN, R E Carolina Power & Light Co 84/08/09 0 (REILLY, J P Rejion 2. Defice of Director ip 26228 247 24X Fiche 50-261,84/08/21,8408240091
- 8408240316 Forwards BALP Repts 50-261/84-24.30-324/84-16.50-325/84-16 & 50-400/84-18 for Føb 1983 Apr 1984 
  LEMIS,R C Region 2. Office of Director 84/08/21 UTLEY,E E Carolina Power & Light Co Rpp 26225 230 24X 
  Fiche 50-000.84/08/21.8408240316
- --8408240319 SALP Repts 50-261/84-24.50-324/84-14.50-325/84-14 & 50-400/84-18 for Feb 1983 Apr 1984 \* Region 2, Office of Director 64/04/30 71pp 26225.232 24 Fiche 50-000,64/08/21.8408240314
- P Operating license stage documents & correspondence
- B40B090444 Notification of B40607 meeting w/util in Bethesda.MD to discuss status of Cycle 10 core reload review REBUA:0 Operating Reactors Branch I B4/06/01. VARGA.B A Operating Reactors Branch I 3pp 25982 351 24x Fiche 50-261.B4/06/01.840B090444
- 8408030248 Informs that correct date of issuance of Amend 81 to License DPR~23 is 840628 REGUA.0 Operating Reactors Branch 1 84/07/16 UTLEY.E E Carolina Power & Light Co 2pp 25719 358 24X Fiche.50-261,84/07/16.8408030248
- 8408030096 Application for amend to License DPR-23, revising Tech Specs re reactor vessel level instrumentation sys Revs will include instrumentation sys, per NUREO-0737 requirements CUTTER: A B Carolina Power & Light Co 84/07/20 VARQA, B A Operating Reactors Branch 1 2pp 25704 347 24X Fiche 50-261,84/07/20,8408030076
- --8408030100 Proposed Tech Spacs re reactor vessel level instrumentation w Carolina Power & Light Co 84/07/20, 4pp 25904 351 24X Fiche 50-261,84/07/20,8408030096
- 8408030162 Requests withdrawal of 801202 license amend request re dadicated shutdown sys Inplementation of sys concurrent w/ fire protection mods more appropriate Revised request will be submitted by B30329 CUTTER:A.B. Carolina Power & Light Co. 84/07/20 VAR9A.B A Operating Reactors Branch 1 2pp 25912.016 24X Fichs 50-261.84/07/20.8408030162

- 8408030234 Submits integrated startup test plans for review, Fulfilling requirement of Amend 77 to License DPR-23 Integrated startup test effort unil demonstrate ability to safely return unit to aperation BEATTY, G P Carolina Power & Light Co 84/07/26 VARGA, S A Operating Reacture Branch 1 139p 23917 177 24X Fiche S0-261.84/07/26.8408030234
- 8408080332 Responds to 840409 telcon & 840419 telecopy request for info on reactor trip breaker testing Periodic callbr & tests currently performed adequate Tach Spec changes unnecessary ZIMMERMAN, S.R. Carolina Power & Light Co. 84/07/27 VARGA, S.A. Operating Reactors Branch 1 4pp 25984 105 24X Fiche 50-261,84/07/27,8408080332
- E408060074 Advises that Amend 80 to Litense DPR-23 re relaxation of physical security requirements of 10CFR73 55 during steam generator repeir outage.uill not be implemented ZIMMERMAN, 8 R Carolina Power & Light Co 84/07/30 VARGA, S A Operating Reactors Branch 1 1p 2593 222 24X Fichs 50-261.84/07/30.8408060074
- 8408070374 Application for amend to License DPR-23, revising Tech Spec Section 3 5, "Containment Sys," to allow performance of CRD evolutions when containment integrity not intact while maintaining required level of safety CUTTER, A B Capolina Power & Light Co. 84/08/01 VARGA, S A Operacting Reactors Branch 1 3pp 25947 (A5 24X Fiche 50-26),84/08/01,8408070374
- --BAOR070378 Proposed revs to Tech Spec Section 3 4, "Containment Sys," for conduct of CRD evolutions when containment integrity not
- 8408070110 Generic Ltr 84-19 to all litensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933. "Prioritization of Generic Safety Issues "Svc list encl EISENHUT, D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000,84/08/05,8408070110
- 8408240309 Forwards preliminary neutronic parameters for steamline break analysis using RELAPS Info developed assuming end-of-cycle core w/all control rod clusters, less most reactive control rod clusters
  KILLOURE,M R Exxon Nuclear Co . Inc (subs of Exxon Corp )
  84/08/07 OUTTMANN.J Reactor Systems Branch 6pp 26225 315
  24X Fiche 50-261.84/08/07.8408240309
- 8408140356 Forwards Suppl 1 to Rev 2 to XN-NF-83-72, "HB Robinson, Unit 2, Cycle 10 SAR Disposition of Chapter 15 Events " Rept provides confirmatory analyses results for SAR Remainder of analyses will be submitted by 840817
  ZIMMERMAN, 8 R Carolina Power & Light Co 84/08/08 VARGA, S A Operating Reactors Branch 1 2pp 26041 001 24X
  Fiche: 50-261,84/08/08,8408140356
- --8408140363 Suppl i to Rev 2 to "HB Robinson, Unit 2, Cycle 10 SAR -Disposition of Chapter 13 Events "
  LEACH, C E . KAYSER, W V . CHANDLER, J C Exxon Nuclear Co , Inc
  (subs of Exron Corp.) XN-NF-883-72 S01 KOZ 84/07/20 33pg
  26041 003 24X Fiche 50-261,84/08/08,8408140356
  - '8220094 Notification of 940627 meeting w/util (n Bethesda, MD to iscuss Cycle 10 reload review & schedules (EGUA, G Operating Reactors Branch | B4/08/15 VARGA, G A Operating Reactors Branch | 2pp 25209, 357 24X Fiche 50-251, 84/08/15, 8408220094
- 3408220229 Requests that 840723 proposed Tech Spec revs for Cycle 10 operation receive expedited review & approval to support 840924 fuel load date CUTTER, A B Carolina Power & Light Co 84/08/17 VARSA, S A Operating Reactors Branch i 1p 26194 080 24X Fiche 50-261.84/08/17.8408220229
- 8408200275 Generic Ltr 84-20 to all licenses of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions 8vc list encl EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison to af New York, Inc. 17pp 26276 244 24X Fiche 50-000.84/08/20,8408200275
- 8408230093 Forwards XN-NF-84-72. Suppl 1. "Large Break LOCA-ECCS Analysis W/Increased Enthalpy Rise Factor Break Spectrum " Info submitted to suppl request for license amend for Cycle 10 operation CUTTER, A B Carolina Power & Light Co 84/08/20 VARGA, S A Operating Reactors Branch 1 2pp 26208 082 24X Fiche 50-261,84/08/20,6408230093

- 8408230117 Forwards XN-NF-84-74, "Plant Transient Analysis for HB Robinson Unit 2 at 2,300 MHt W/Increased FN(Delta)H " CUTIER, A B Carolina Power & Light Co 84/08/20 VARGA, S A Operating Reactors Branch i 2pp 26208 187 24X Fiche 50-261,84/08/20.8408230117
- --8408230122 "Plant Transient Analysis for HB Robinson Unit 2 at 2,300 MMt H/Increased FN(Delta)H " LEACH.C E , ADAMS.F T , KILLGORE,M R Exxon Nuclear Co , Inc (subs of Exxon Corp ) XN-WF-84-74 84/08/16 200pp 26208 189 24X Fiche 50-261,84/08/20,8408230117
- 8408280199 Documents closeout of several issues raised by NRC during review of responses to requirements of Generic Ltr 81-14, "Seismic Gualification of Auxiliary Feedwater Sys " Any mods will be made per Generic Issue A-44
  ZIMMERMAN.S R Carolina Power & Light Co 84/08/23 VARGA.S A Operating Reactors Branch 1 1p 26275 362 24X
  Fiche 50-261,84/08/23,8408280199
- 8408290011 Forwards fee for 840723 application for license amend in response to 840810 request ZIMMERMAN.S R Carolina Power & Light Co 84/08/23 MILLER, W D License Fee Management Branch 1p 26291 281 24X Fiche 30-241,84/08/23.8408290011
- G Inspection reports: IE Bulletins & correspondence
- 8408280133 Provides updated schedule for completion of IE Bulletins 79-02 & 79-14 Due to increase in scape of project following thorough third party review, projected completion of insp & as-built documentation scheduled for 841030 MCRGAN, E Carolina Power & Light Co. 84/06/29 O'REILLY, J P Region 2, Office of Director ip 26275 145 24X Fiche 50-261.84/06/29.8408280133
- 8408240007 Forwards Insp Rept 50-261/84-21 on 840611-15 & notice of violation Notice of violation withheld (ref 100FR2 790 & 73 21)
  VERRELLI,D M Region 2, Office of Director 84/07/10 UTLEY, & E Carolina Power & Light Co 2pp 26228 249 24X
  Fiche 50-261,84/07/10,8408240007
- --B40B240010 Insp Rept 50-261/84-21 on B40611-15 Violation identified failure to maintain security-related equipment in operable condition Details withheld (ref 10CFR2 790 & 73 21) TILLMAN.A., MCOURE.D R Region 2, Office of Director 84/06/28 ip 26228 251 24% Fichs 50-261.84/07/10.8408240007
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Bafety-Related Electrical Equipment at Commercial Power Plants " Svc jist encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229
- B408270813 Ack receipt of 840719 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-261/84-19 LEWISAR C Region 2. Office of Director 84/07/30 UTLEY, E E Carolina Power & Light Co 1p 26236 143 24X Fiche 50-261.84/07/30.8408270513
- --8408270321 Responds to NRC 840617 ltr re violations noted in Insp Rept 50-261/84-19 Currective actions regulatory compliance instruction for preparing correspondence implemented & investigation of circuit conducted to identify occurrence MORGAN, R E Carolina Power & Light Co 84/07/19 O'REILLY, J P Repion 2. Gefice of Director 3pp 26256 144 24X Fiche 50-261,84/07/30,8408270513
- --8408270528 Forwards Insp Rept 50-261/84-19 on 840511-0610 & notice NOB270328 FORWARDS SUBPERIOR TO A STATE OF VIOLATION OF A STATE OF SUBPERIOR SUBPERIOR
- --8408270530 Notice of violation from insp on 840511-0610 \* Region 2. Office of Director 84/06/17 2pp 26254 149 24X Fithe 50-261.84/07/30.8408270513
- --8408270336 Insp Rept 50-261/84-19 on 840511-0610 Violations noted failure to implement procedures failure to adequately establish surveillance procedures & inaccurate statement in LER. WEISE, S. QARNER, L. BEMIB, P. R. Region 2, Office of Director 84/06/18 11pp 26256 151 24X Fiche 50-261,84/07/30,8408270513

- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/04 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000.84/08/06,8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 26067 158 24X Fiche 50-000.84/08/06,8408010337
- 8408280027 Ack receipt of 840726 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-261/84-22 VERRELLI D M Region 2. Office of Director 84/08/07 UTLEY, E Carolina Power & Light Co ip 26281 350 24X Fiche 50-261.84/08/07.8408280027
- --8408280035 Responds to NRC 840629 ltr re violations noted in Insp Rept 50-261/84-22 Corrective actions post-weld heat treatment contractor marked all thermocouple locations adjacent to thermocouples prior to grinding MDRGAN.R E Carolina Power & Light Co 84/07/26 D'REILLY, J P Region 2. Office of Director 2pp 26281 351 24X Fiche 50-261.84/08/07.8408280027
- --8408280039 Forwards Insp Rept 50-261/84-22 on 840612-15 & notice of violation
  VERRELLI,D M Region 2, Office of Director 84/06/29 UTLEY,E E Carolina Power & Light Co 2pp 26281 353 24X
  Fiche 50-261.84/08/07.8408280027
- --8408280042 Notice of violation from insp on 840612-15 \* Region 2: Office of Director 84/06/27 ip 26281 355 24X Fiche 50-261,84/08/07.8408280027
- --B40B280046 Insp Rept 50-261/B4-22 on 840612-15 Violation noted failure to follow temporary attachment procedure KLEINSCROE: W P . BLAKE.J J Region 2. Office of Director 84/06/27 15pp 26281 356 24X Fiche 50-261.B4/0B/07.B40B2B0027
- B408290021 Ack receipt of B40608 & 0724 ltrs informing NRC of steps taken to correct violations noted in Insp Rept 50-261/84-li VERRELLI.D M Region 2. Office of Director B4/08/07 UTLEY.E E Carolina Power & Light Co 1p 26298 020 24x Fiche 50-261.84/08/07.8408290021
- --8408290025 Responds to NRC 840510 ltr re violations noted in Insp Rept 50-261/84-il Corrective actions conservative changes made to WP-502 in Rev II & Coated electrodes not issued in portable rod caddie destroyed regardless of exposure time MORGAN. R E Carolina Power & Light Co 84/07/24 D'REILLY, J P Region 2. Office of Director 2pp 26298 021 24X Fiche 50-261.84/08/07.8408290021
- --8408290028 Responds to violations noted in Insp Rept 50-261/84-i1 Violation denied Conservative changes made to WP-502 in Rev 11 & coated electrodes not issued in portable rod caddie will be destroyed regardless of exposure time MORGAN.R E Carolina Power & Light Co 84/06/08 O'REILLY, J P Region 2, Office of Director 2pp 26278 023 24X Fichs 50-261.84/08/07.8408290021
- --8408270031 Ack receipt of 840408 response denying violations noted in Insp Rept 30-261/84-11 NRC concluded violation did occur Corrective actions requested within 30 days of ltr date LEMIS.R C Region 2, Office of Director 84/06/89 UTLEY.E E Carolina Power & Light Co 2pp 26278 025 24% Fiche 50-261,64/08/07.8408270021
- --8408290034 Forwards Insp Rept 50-261/84-11 on 840410-13 & notice of violation VERRELLI,D M Region 2, Office of Director 84/05/10 UTLEY,E E Carolina Power & Light Co 2pp 26298 027 24X Fiche 50-261,84/08/07,8408290021
- --8408270035 Notice of Violation from insp on 840410-13 \* Region 2, Offlice of Director 84/05/10 2pp 26278 027 24X Fiche 50-261,84/08/07,8408270021
- --8408270039 Insp Rept 50-261/84-11 on 840410-13 Violation noted procedure inadequate for segregation of weld rods w/exposure time COLEY, JL , BLAKE, JJ Region 2, Office of Director 84/05/09, 10pp 26298 031 24X Fiche 50-261,84/08/07,8408290021
- B408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity" Evc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fiche 50-000.84/08/08.8408070120

- 8408070374 If Info Notice 84-62. Therapy Misadministrations to Patients Undergoing Co-60 foletherapy Treatments \* Svc list encl GRACE.J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000.84/08/10.8408070376
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc. 119pp 26197 218 24X Fiche 30-000,84/08/13,8408100009
- 840B10003B | E Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl JGRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,840B160038
- 8408100021 IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021
- 8408100035 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/17 Consolidated Edison Co of New York, Inc. 120pp 26276 001 24X Fiche 50-000.84/08/17.8408100055
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solennid Valves " Svc list encl JCRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142
- 8408240091 Ack receipt of 840809 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-261/84-21 VERRELLI, D M Region 2, Office of Director, 84/08/21 UTLEY, E & Carolina Power & Light Co ip 26228 246 24X Fiche 50-261/84/08/21/8408240091
- --8408240095 Forwards response NRC 840710 ltr re violations noted in Insp Rept 50-261/84-21 Response withheld (ref 10CFR2 770 & 73 21) MOROAN,R E Carolina Power & Light Co 84/08/09 O'REILLY, J P Region 2, Office of Director 1p 26228 247 24x Fiche 50-261,84/08/21,8408240091
- 8408240316 Forwards SALP Repts 50-261/84-24, 50-324/84-16, 50-325/84-16 & 50-400/84-18 for Feb 1983 Apr 1984 LEWIS.R C Region 2. Office of Director 84/08/21 UTLEY.E E Carolina Power & Light Co 2pp 26225 230 24X Fiche 50-000.84/08/21.8408240316
- --8408240319 SALP Repts 50-261/84-24,50-324/84-16,50-325/84-16 & 50-400/84-18 for Feb 1983 Apr 1984 \* Region 2, Office of Director 64/04/30 71pp 26225 232 24X Fiche 50-000,84/08/21,8408240316
- 8408300146 EN-84-009A notice of violation & proposed imposition of civil penalty in amount of \$30,000 issued re failure to follow procedures for entry into locked high realization area FLACK.E. AXELRAD, J. Director's Office. Office of Inspection and Enforcement 84/08/28 ip 26304 357 24X Fiche 50-261,84/08/28.
- R Periodic operating reports & related correspondence
- 8408160144 Monthly operating rept for Jul 1984 W/840809 ltr. SCOTT.A E., MORGAN.R.E. Carolina Power & Light Co. 84/07/31. DEYOUNG.R. Director's Office. Office of Inspection and Enforcement 4pp 26108 071 24X Fiche 30-261.84/07/31.8408160144.
- S Reportable occurrences, LERs & related correspondence
- 8408060315 LER 84-008-00 on 840626, condensate storage tank level transmitters LT-1454A & 8 identified as out of calibr Caused by physical jarring Transmitters recalibr W/840726 ltr WRIGHT, C. L., MDRGAN, R E Carolina Power & Light CO 84/07/26. 3pp. 25936 089 24X Fiche 30-261,84/07/26,8408060315

- 8408170188 LER 84-009-00 on 840707. W/unit in shutdown, during annual containment pressure channel calibr. review of as found data revealed nonlinear error over range of instruments Caused by personnel error in test equipment setup W/840809 ltr WRIGHT, C L . MORGAN.R E Carolina Power & Light Co 84/08/09 Jpp 26130 028 24X Fiche 80-261,84/08/09.8408170188
- V Operator Examinations
- B40B310014 Confirms 840605 telcon re 840612 mgt meeting in Region II ofce to discuss upcoming operator exams & requalification of licensed operators following steam generator outage D'ARILLY, J P Region 2, Office of Director 84/06/08 UTLFY, E E Carolina Power & Light Co 1p 26333 357 24X Fiche 80-000.84/06/08.8408310014
- DOCKET 50-262 Brigham Young univ RESEARCH REACTOR

  G Inspection reports, IE Bulletins & correspondence
- 8407250227 JE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Bafety-Related Electrical Equipment at Commercial Power Plants " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc. 117pp 25865-047 24% Fiche 50-000,84/07/27,8407250229
- 8408010333 IE Info Notice 84-59. "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Canabidated Edison Co of New York, Inc 85pp 26048 001 24% Piche 50-000,84/08/06.8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN, E. L. Division of Emergenty Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- B408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Bvc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24% Fiche 50-000,84/08/08.8408070120
- 8408070376 IE Info Notice 84-62. "Thorapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments "Syc list encl ORACE.J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10.8408070376
- 840B100007 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list enc!
  JDROAN.E.L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consultdated Edison Co of New
  York, Inc. 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- B40Bi0003B IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Byc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/08/13 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 30-000,84/09/15,8408100038
- 8408100021 IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Fost 830103). 84/08/16. Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16.8408100021
- 840B100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000.84/08/17.8408100055
- B40B140208 IE Info Notice B4-67. "Recent Bnubber Inservice Testing W/ High Failure Rates " Byo list and! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Past 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pg 26276 122 24X Fiche: 50-000,84/08/17,840B140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/08/21 Consolidated Edison Co of New York, Inc 115pp. 26327.008 24X Fiche 50-000.84/08/21.8408210142

- DDCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT

  F Security, medical, emergency & fire protection plans
- 8408080171 Forwards IE Insp Rept 50-243/84-11 on 840521-25 & notice of deviation SPESSARD, R L Region 3, Dffice of Director 84/07/20 LARSON, C E Northern States Power Co 2pp 25974 278 24X Fiche 50-243,84/07/20,8408080171
- --8408080174 Notice of deviation from insp on 840821-25 SPESSARD,R L Region 3, Office of Director 84/07/20 ip 25974 280 24% Fiche 50-263,84/07/20,8408080171
- --8408080181 IE Insp Rept 30-263/84-11 on 840521-25 Deviation noted failure of fire detection sys to provide permanent record of signals sent to central supervising station ULIE.J M , GULDEMOND, W G Region 3. Office of Director 84/07/20 19pp 25974 281 24x Fiche 50-263,84/07/20,8408080171
- 8408090011 Forwards "Procedures Generation Package," as identified in Generic Ltr 82-33 & Commission 840412 order confirming licensee commitments MUSQLF,D Northern States Power Co 84/07/31 Office of Nuclear Reactor Regulation, Director ip 25972 300 24X Fiche 50-243.84/07/31.8408090011
- --8408090014 "Procedures Generation Package"

  \* Northern States Power Co 84/07/31 66pp 25972 331 24X
  Fiche 50-263.84/07/31.8408090011
- 8408160169 Rev 4 to emergency plan W/transmittal & receipt forms MATHIASE.C D , WILLIAMS.Q Morthern States Power Co 84/08/01 100pp 26091 259 24% Fiche 50-263.84/08/01.8408160169
- 8408300176 Forwards Rev 7 to "Northern States Power Co Corporate Nuclear Emergency Plan " Rev includes changes resulting from annual internal review, update & certification of emergency plans & agreements FEV.F L Northern States Power Co 84/08/02 Region 3, Office of Director 4pp 24302 106 24X Fiche 30-000.84/08/02,8408300176
- --8408300180 Rev 7 to "Northern States Power Co Corporate Nuclear Emergency Plan " HUDSON.G , FEY.F L , LARSON, C E Northern States Power Co 84/08/02 116pp 26302.110 24% Fiche 50-000,84/08/02. 8408300176
- --8408300183 Revised "Radiation Environ Monitoring Plan" CLARK.D W : FEY.F L. Northern States Power Co 84/02/29 14pp 26302 226 24X Fiche 50-000.84/08/02.8408300176
- P Operating license stage documents & correspondence
- B408150513 Forwards request for info re torus attached piping & suppression chamber penetration as part of Mark I containment long-torus program Response will be discussed at 840807 & 10 meetings w/NRC & consultants VASBALLO.D B Operating Reactors Branch 2 84/07/27 MUSDLF, D M Northern States Power Co 3pp 26105 360 24X Fiche 50-263.84/07/27.8408150513
- B40B160222 Forwards application for amend to License DPR-22, changing Tech Specs to increase degraded voltage protection setpoint, per station electric distribution sys voltage analysis Fee encl MUSDLF, D. Northern States Power Co. B4/07/2/ Office of Nuclear Reactor Regulation, Director ip 26092 143 24X Fiche 50-263,84/07/27,8408160222
- --8408160229 Application for amend to License DPR-22, changing Tech Specs to increase degraded voltage protection setpoint MUSOLF.D Northern States Power Co 84/07/27 3pp 26092 144 24% Fiche 50-263,84/07/27,8408160229
- --8408160233 Proposed Tech Spec changes, increasing degraded voltage protection setpoint \* Northern States Power Co 84/07/27 7pp 26092 147 24X Fiche 50-263,84/07/27,8408160222
- 8408050425 Notification of 840809-10 meetings w/utils.NUTECH.Franklin Research Ctr & BNL in 8an Jose,CA to discuss comments resulting from post-implementation review re plant-unique analysis repts
  BEVAN.R D Operating Reactors Branch 2 84/07/31 VASBALLO,D B Operating Reactors Branch 2 1p 25737 335 24X
  Fiche 50-000.84/07/31.8408050425

- 8408270110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933. 'Prioritization of Generic Safety Issues " Svc list encl EISENHUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26127 238 24X Fiche 50-000.84/08/06.8408070110
- 8408200423 Forwards request for addl info re 831230 reanalysis of station electrical distribution sys voltages Response to encl questions requested within 60 days of ltr receipt VASSALLO,D B. Operating Reactors Branch 2 84/08/09 MUSDLF,D f Northern States Power Co. 3pp. 26144-361 24X Fishe 50-263,84/08/09,8408200423
- 8408290314 Forwards Amend 25 to License DPR-22 % safety evaluation Amend extends interval between integrated containment leak rate tests & adds intake structure sprinkler sys requirements RODNEY, V L. Operating Reactors Branch 2 84/08/15 MUSOLF, D M Northern States Power Co. 2pp. 26312 297 24X Fiche 50-263.84/08/15.8408290314
- --8408290324 Amend 25 to License DPR-22, extending interval between integrated containment leak rate tests, adding requirements for new intake structure sprinkler sys & making other nonsafety-related Tech Spec changes
  VASSALLO.D B Decrating Reactors Branch 2 84/08/15 18pp 26312 299 24X Fiche 50-263,84/08/15,8408290314
- --8408290329 Safety evaluation supporting Amend 25 to License DPR-22 \* Office of Nuclear Reactor Regulation, Director 84/08/15 3p 26312 317 24X Fiche 50-263,84/08/15,8408290314
- 8408170252 Forwards Rev j to NEOD-30477, "Safety Analysis of RHR
  Intertie Line, Monticello Nuclear Generating Plant " Rev
  suppls 840927 application to amend License DPR-22
  MUSOLF.D Northern States Power Co 84/08/16 Office of Nuclear
  Reactor Regulation, Director 1p 26/18/103 24X
  Fiche 50~263,84/08/16.8408170252
- --B408170262 Rev 1 to, "Safety Analysis of RHR Intertie Line, Monticello Nuclear Generating Plant" BRANDON,R J , GRIDLEY,R L General Electric Ca NEDO-30477 RO1 B4/06/30 27pp 2611B 104 24X Fiche 50-263,84/0B/16,8408170252
- 8408270293 Forwards Rev 1 to 840103 application for amend to License DPR-22 Rev modifies surveillance requirements for emergency filtration train charcoal absorber & filters & toxic gas monitoring requirements for control room MUSQLF.D Northern States Power Co 84/08/17 Office of Nuclear Reactor Regulation, Director ip 26242 313 24% Fiche 50-263,84/08/17,8408270293
- --8408270299 Rev 1 to 840403 application for amend to License DPR-22, authorizing changes to Tech Specs re surveillance requirements for control room habitability & toxic gas monitors, per NUREG-0737, Item III D 3 4 MUSDLF, D Northern States Power Co 84/08/17 5pp 26242 314 24X Fiche 50-263, 84/08/17, 8408270273
- --8408270302 Proposed Tech Spec changes re surveillance requirements for control room habitability & toxic gas monitors \* Northern States Pouer Co 84/08/17 17pp 26242 319 24X Fiche 30-263,84/08/17,8408270293
- --8408270307 "Monticello Cenerating Station Toxic Chemical Study Incapacitation Levels " \* Bechtel Corp 84/06/20 13pp 25242 336 24X Fishe 50-263,84/08/17,8408270293
- 8408280160 Forwards application for amend to License DPR-R2, revising Tach Specs to support use of Hybrid I control rod assemblies for completion of Cycle 11 fuel loading Fee paid MUSOLF, D Northern States Power Co 84/08/17 Office of Nuclear Reactor Regulation, Director ip 26275 109 24x Fiche 50-263,84/08/17,8408280160
- ---B4002B0164 Application for amend to License DPR-22, revising Tech Specs to support use of Hybrid I control rod assemblies for completion of Cycle ii fuel loading MUSDLF, D Northern States Power Co 84/08/17 5pp 26275 110 24X Fiche 50-263,84/08/17,84082B0160
- --8408280169 Proposed Tech Spec 5 O. "Design Features." supporting use of Hybrid I control red assemblies for completion of Cycle 11 fuel loading \* Northern States Power Co 84/08/17 lp 26275 115 24X Fiche 50-263,84/08/17,8408280160

- 840B200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT D 0 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 50-000:84/08/20.840B200275
- Q Inspection reports, IE Bulletins & correspondence
- 8408010401 Forwards IE Insp Rept 50-263/84-09 on 840302-0614 No noncompliance noted SHAPER.W D Region 3. Office of Director 84/07/12 LARSON.C E Northern States Power Co 2pp 25866 044 24X Fiche 50-263.84/07/12.8408010401
- --8408010402 IE Insp Rept 50-263/84-09 on 840502-0616 No noncompliance noted Major areas inspected previous insp findings, ventilation sys damper actuators. Unistrut Bracket P-2073A insp. LERs, onsite revieu committee & long-term shukdown BDVD. D C Region 3. Office of Director 84/07/11 3pp 23865 046 24X Fiche 50-263.84/07/12.8408010401
- 8408080171 Forwards IE Insp Rept 50-263/84-11 on 840521-25 & notice of deviation
  SPESBARD,R L. Region 3, Office of Director 84/07/20 LARSON,C E
  Northern States Power Co 2pp 25974 278 24X
  Fiche 50-263,84/07/20,8408080171
- --8408080174 Notice of deviation from insp on 840521-25 SPCSSARD.R L. Region 3. Office of Director 84/07/20 lp 25974 280 24X Fiche 50-263.84/07/20.8400080171
- --9408080101 IE Insp Rept 50-263/84-11 on 840521-25 Deviation noted. failure of fire detection sys to provide permanent record of signals sent to central supervising station ULIE, J M , GULDEMOND, W 9 Region 3, Defice of Director 84/07/20 17pp 25974 201 24% Fiche 50-263, 84/07/20,8408080171
- 8408180544 Forwards IE Insp Rept 50-263/84-14 on 840625-29 & notice of Violation PAPERIELLO,C J Region 3, Office of Director 84/07/26 LARSON,C E Northern States Power Co 2pp 26079 222 24X Fische 50-263.84/07/26.8408150544
- --8408150546 Notice of violation from Insp on 840625-29 PAPERIELLO.C J Region 3, Office of Director 84/07/26 ip 26079 224 24X Fiche 50-263,84/07/26,8408150544
- --B40B150547 IE Insp Rept 50-262/804-14 on B406289-27 Violation noted solid radwaste contained free standing liquid GRANT.W B . NICHOLSON.N A . GRECER.L R Region J. Defice of Director B4/07/26 9pp 26079 223 24X Fiche 50-263.84/07/26, 840B150544
- B408230489 Forwards IE Insp Rept 50-263/84-12 on B40617-0707 No noncompliance noted SHAFER.W D Region 3, Office of Director 04/07/26 LARSON.C E Northern States Fower Co 2pp 26212 249 24X Fiche 50-263.84/07/26.8408230489
- --8408230497 IE Insp Rept 50-263/84-12 on 840612-0707 No noncompliance or deviations noted Major areas inspected onsite review committee-procedures-recirculation vessel riser & long-term shutdown BOYD. D C Region 3. Office of Director 84/07/26 App 26212 251 24X Fiche 50-263.84/07/26.84008230489
- 8408070401 Informs that now sys of acknowledging raceipt of licensee correspondence re noncompliance found during inspiratived effective 840820 Preprinted form will be used rather than ltr

  KEPPLER, J O Region 3, Diffice of Director 84/08/03
  Commonwealth Edison Co 3pp 23942 188 24X Fiche 50-000,84/08/03,8408070401
- 8408300038 Forwards exam rept on 840626-28 WALKER.R D Region 3. Office of Director 84/08/13 LARBON.C.E Northern States Power Co 1p 26307 240 24% Fiche 50-263, 84/08/13,8408300058
- --8408300060 Exam rept on 840626-27 Exam results one operator candidate failed written & simulator exams
  DIMMOCK,L , MCMILLEN,J I Region 3, Office of Director
  OROVES,D N EG&O, Inc. 84708/10 64pp 26307 241 24X
  Fiche 50-263,84/08/13,8408300058

- 8 Reportable occurrences, LERs & related correspondence
- 8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scran pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated SHERWOOD, G O General Electric Co 84/04/13 DEYGUNG.R C Director's Office. Office of Inspection and Enforcement 3pp 26222 256 244 Fiche 50-000.84/04/13.8409240348
- 8407100420 LER 84-022-00 on 840605, reactor bldg ventilation isolation & standby gas treatment initiation occurred Caused by blown fuse in reactor bldg spent fuel pool rediation monitor Channel B Fuse replaced W/840705 ltr BAYLESS,R S . MUSQLF,D Northern States Power Co 84/07/05 3pp 25464 280 24% Fiche 50-263,84/07/05.8407100420
- 8408080079 LER 84-024-00 on B40627, during cold shutdown, reactor bldg ventilation isolation & standby gas treatment sys initiation occurred Channel A reactor bldg vent wide range gas monitor deenergized Caused by personnel error W/840727 ltr LARSON.D E . MUSCLED Northern States Power Co 84/07/27 Jpp 25974 275 24% Fiche 50-263.88/07/27.84080800079
- 8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of B40820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition

  VILLA.R General Electric Co 84/08/21 ROSSI.C E Director's Office Office of Inspection and Enforcement 3pp 26318.327 24x Fichs 50-000.84/08/21.8408310186
- B408280127 Part 21 rept re defects in 18-inch SA-333 RHR pipe Samples of defective pipe math being shipped to Techninat Corp.per request Defects located in one length of SA-333 Grade & pipe CRUSBY. GE Northern States Power Co 84/08/22 COLLING. J NRC No Detailed Affiliation Given ip 26275 144 24X Fiche 30-263.84/08/22.8408280127
- V. Operator Examinations
- 8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners MALKER, R D Region 3. Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051
- 840930005B Forwards exam rept on 840626-28 WALKER, R D Region 3. Office of Director 84/08/13 LARSON, C E Northern States Fower Co ip 26307 240 24% Fiche 50-263, 84/08/13.840830005B
- --8408300060 Exam rept on 840626-29 Exam results one operator candidate failed written & simulator exams DIMHOCK, L. MCMILLEN, J I Region 3, Office of Director 980VES, D N E646, Inc. 84/08/10 649p 26307 241 24X Fiche 50-263,84/08/13,8408300058
- 8408230132 Informs of review of 840705 ltr which clarified interpretation of on-shift training requirements Util will be required to provide documentation that senior reactor operator upgrade candidates comply w/listed requirements MALKER, D Region 3. Office of Director 84/08/20 LARSON, C E Northern States Power Co 2pp 26209 061 24X Fiche 50-000.84/08/20.8408230132
- ODCKET 50-264 DOW CHEMICAL CO
- 8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners WALKER, R D Region 3. Office of Director 84/08/10 Michigan. Univ of. Ann Arbor. MI 2pp 26051
- DOCKET 50-265 QUAD CITIES STATION, UNIT 2
- F Security, medical, emergency & fire protection plans
- 8408140137 Forwards listed revs to security plans Revs address fence height requirements Revs withheld (ref 10CR73 21) FARRAR,D L Commonuealth Edison Co 84/08/03 Region 3, Office of Director 1p 26044 252 24X Fiche 50-000,84/08/03,8408140139

- 8408140365 Revised emergency implementing procedures, including Rev 7 to GEP 110-2 re shift engineer. Rev 6 to GEP 180-0 re Rad-Chem director & Rev 17 to GEP 200-0 re emergency conditions

  \* Commonwealth Edison Co 84/08/04 84pp 26041 052 24X Fiche 50-254.88/08/04.8408140365
- 8408130401 Responds to 840705 clarification of info re util means of satisfying annual regulatory requirement to review emergency action levels w/offsite emergency support organizations. Info acceptable PAPERIELLO,C J. Region 3, Office of Director 84/08/07 REED,C Commonwealth Edison Co. Lp. 26010 130 24X Fiche 50-000,84/08/07, GAOGISTAGO
- --8408130413 Responds to B40604 ltr re means for satisfying requirements of 10CFR50, App E, Paragraph IV B Proposal for satisfying requirements to review emergency action levels by offsite agencies clarified FARRAR. D L Commonwealth Edison Co 84/07/05 PAPERIELLO, C J Region 3, Offsice of Director Bpp 26010 131 24X Fiche 50-000,84/08/07,8408130401
- B40B20024B Advises that 840B03 Rev 15 to physical security plan consistent w/provisions of 10CFR90 54(p) & acceptable AXELSON, U. Region 3. Office of Director 84/08/14 FARRAR, D. L. Commonwealth Edison Co. 2pp. 26133 190 24X Fiche 50-254,84/08/14, AAGRENO248
- 8408230270 Revised emergency plan implementing procedures, including Rev 23 to GEP-310-0, "Notification of Responsible Authorities," & Rev 13 to GEP 310-T3, "Prioritized Notification Listing" W/rev receipt form \* Commonwealth Edison Co 84/08/16 11pp 26209 323 24X Fiche 50-254,84/08/16,8408230270
- P Operating license stage documents & correspondence
- 8408060425 Notification of 840809-10 meetings w/utils,NUTECH,Franklin Research Ctr & BNL in San Jose,CA to discuss comments resulting from post-implementation review re plant-unique analysis repts BEVAN,R B Operating Reactors Branch 2 84/07/31 VASSALLD,D B Operating Reactors Branch 2 ip 25937 335 24X Fishe 50-000.84/07/31.8408060423
- 8408140317 Forwards response to 840626 request for add1 info re
  125-volt dc sys Facility recently completed replacement of
  125-volt battery chargers w/200 ampere-rated units
  RYBAK, B Commonwealth Edison Co 84/08/01 DENTON, H R Office of
  Nuclear Reactor Regulation, Director 17pp 26042 333 24X
  Fiche 50-234,84/08/01,8408140317
- 8408070110 Generic Ltr 84-17 to all licensess of operating reactors, applicants for GLs & holders of CPs re availability of Suppl I to NUREG-0733, "Prioritization of Generic Safety Issues " Svc list encl EISENHUT, D @ Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26127 238 24X Ficha 50-000,84/08/06.8408070110
- 8408160345 Advises that GA program applicable to all nuclear generating stations & satisfies provisions of 10CFR71 Fee remitted per 10CFR170 31

  FARRAR, D L Commonuealth Edison Co 84/08/06 Office of Nuclear Material Safety & Safeguards, Director 1p 26092 184 24X Fiche 50-000.84/08/06.8408160345
- B40B270114 Provides supplemental response to Generic Ltr 83-34, "NUREO-0737 Tech Specs" Mods to Quad Cities radiological ETS will not be complete until Fall 1984 Complete response w/Tech Spec amend requests expected by B41115 ALEXANDER, O L Commonwealth Edison Co B4/0B/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26247-330 24X Fichs 50-000,84/08/15,8408270114
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT. D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 50-000.84/08/20,8408200275
- 8408310203 Suppl to 830217 application for amend to Licenses DPR-29 & DPR-30, revising Toch Specs to incorporate listed changes reflecting rev to 100FR50 72 & new Section 50 73 LER reporting requirements, per Generic Ltr 83-43 RYBAK, B Commonwealth Edison Co 84/08/23 DENYON, H R Office of Nuclear Reactor Regulation, Director 6pp 26320 245 24X Fiche 50-254,84/08/23,8408310203

- --8408310204 Proposed Tech Spec changes reflecting revised 10CFR50 72 % new Section 50 73 LER reporting requirements \* Commonwealth Edison Co 84/08/23 62pp 26320 251 24X Fiche 50-254,84/08/23,8408310203
- 8408310211 Furwards final response to second & final set of questions re Mark I containment plant-unique analysis RYBAK, B Commonwealth Edison Co 84/08/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 37pp 26318 072 24X Fichs 50-000.84/08/24.8408310211
- Q Inspection reports, IE Bulletins & correspondence
- 8408150392 Forwards IE insp Repts 50-254/84-10 & 50-265/84-09 on 840625-28 & 0706 No nencompliance noted PAPERICLLO,C J Region 3, Office of Director 84/07/26 REED,C Commonwealth Edison Co 2pp 26077 340 24X Fichs 50-254.84/07/26,8408150392
- --B40B190401 IE Insp Repts 50-254/B4-10 & 50-265/B4-09 on B40625-28 & O706 No violations or deviations noted flajor areas inspected confirmatory measures, radiological environ monitoring program & licensee actions on open items ROZAK, S. OEBTMANN, M. J. SCHUMACHER, M. C. Region 3, Office of Director B4/07/25 10pp 26077 342 24X Fiche 50-254,84/07/26, B408150392
- 8407250227 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000.84/07/27, 8407250229
- 8408070066 Notifies of 840823 meeting w/util at Region III ofc to review findings of SALP assessment re util performance Encourages mgt representation to ensure mutual understanding of issues & findings presented by NRC NORELIUS, C E Region 3. Office of Director 84/08/03 REED, C Commonwealth Edison Co. 2pp. 25949-337 24X Fiche 50~000,84/08/03,8408070066
- B40B230549 Forwards IE Insp Repts 50-254/84-00 & 50-265/84-07 on B40520-0623 & notice of violation Type A tests must be conducted during each refueling outage, unless request & granted exemption from requirement received NORELIUG.C E Region 3. Office of Director B4/08/03 REED.C Commanuealth Edison Co 2pp 26213 005 24X Fiche 50-254.84/08/03, B408230549
- --8408230551 Notice of violation from insp on 840520-0623 NDRELIUS.C E Region 3. Office of Director 84/08/03 29p 26213 007 24X Fiche 50-254.84/08/03,8408230549
- --8408230555 IE Insp Repts 50-254/84-08 & 50-265/84-07 on 840520-0623
  Noncompliance noted failure to local leak rate test
  gasketed penetration & failure to quantify leakage during
  integrated leak rate test
  CHRISSOTIMOS, N Region 3, Office of Director 84/07/23 9pp
  26213 009 24X Fiche 50-254.84/08/03.8408230349
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/04 Consolidated Edison Co. of New York, Inc. 85pp. 24048 001 24X Fiche 50-000.84/08/04.8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list enci JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York Inc 123pp 26067 158 24X Fiche 30-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- B40B140344 Confirms 840B03 plans to meet w/util on B40907 in Olen Ellyn IL to discuss regulatory improvement program NORELIUS,C E Region 3, Office of Director B4/0B/0B REED,C Commonwealth Edison Co 2pp 26041 050 24X Fiche 50~000,84/0B/0B, B40B140344
- E40B15009B Suppls 840711 response to IE Bulletin 84-02 re visual insp during monthly functional tests to verify proper contact on reactor trip sys & primary containment isolation sys relays Exemptions requested for listed relays ALEXANDER, 9 L. Commonwealth Edison Co. 84/08/08 KEPPLER, J Q RESION 3, Office of Director 3pp 26067 053 24X Fiche 50-000,84/08/08,8408150098

- 8408200331 Supplis response to IE Bulletin 84-02 re failure of GE Type MFA relays Exemption requested from commitment for visual inspirational check for listed relays ALEXANDER.G L. Commonwealth Edison Co. 84/08/08 KEPPLER.J G Region 3. Office of Director Typ. 26132 318 24X Fiche 50-000.84/08/08.8408200331
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl ORACE, J M Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24x Fiche 50-000,84/08/10,8408070376
- BAOBIO0009 IE Info Notice 84-63. "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26178 073 24X Fiche 50-000,84/08/15,8408100038
- 8408100021 IE Info Notice 84-45, "Underrated Fuses Which May Adversely Affact Operation of Essential Electrical Equipment" Svc list encl JDRIDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/14 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021
- 840B100035 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Bvc list encl JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000.84/08/17,8408100055
- 8408140208 IF Info Natice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates" Svc list encl JORDAN,C L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Golenaid Valves" Svc 1ist encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc. 1(5pp. 26329 008 24X Fiche 50-000, 84/08/21, 8408210142
- R Periodic operating reports & related correspondence
- 840821006B Rept of changes, tests & experiments completed during Jul 1984 W/840801 ltr KALTVIANAKIS, N. Commonwealth Edison Co. 84/97/31 CABE, E. G. Office of Nuclear Reactor Regulation, Director 2pp 26184 307 24X Fiche 30-254,84/07/31,84,0821006B
- 8408230435 Monthly operating repts for Jul 1984 W/840801 ltr KIMLER, D., KALIVIANAKIB, N. Commonwealth Edison Co. 84/07/31 24pp 26213 074 24X Fichs 50-254,84/07/31,8408230435
- B40B300299 Forwards "Effluent & Waste Disposal Semiannual Rept. Jan-June 1784. Gassous Effluents - Summation of All Releases" & errate to semiannual repts for Jan-June & Jul-Dec 1983 KALIVIANAKISIN Commonwealth Edison Cd 84/08/15 KEPPLER. J 0 Region 3. Diffice of Director ip 26314 225 24X Fiche 80-254.84/08/15.840B300299
- --8408300308 "Effluent & Waste Disposal Semiannual Rept, Jan-June 1984 "
  BEHREMS.P A Commonwealth Edison Co 84/06/30 12pp 26314-226
  24X Fiche 50-254.84/08/15,8408300299
- --8408300329 Errate to "Liquid Effluents Summation of All Releases " Jan-June 1983 \* Cammonwealth Edison Co 83/06/30 7pp 26314 233 24X Fiche 50-234,84/08/15,8408300299
- --8408300336 Errata to "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1983, Gassous Effluents - Summation of All Releases " \* Commonwealth Edison Co 83/12/31 2pp 26314, 240 24X Fiche 50-234, 84/08/15, 8408300297

# S Reportable occurrences, LERs & related correspondence

- 8408240348 Part 21 rept re presence of Loctite~242 in CRD hydraulic control unit scram pilot solemoid valve plunger Initially reported on 840413 New thread locking devices investigated SHERMDOD, G G Ceneral Electric Co 84/04/13 DEYCUNG. R C Director's Office. Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50~000.84/04/13.8408240348
- B408050251 LER 84-008-00 on 840703, after surveillance, HPCI cooling water return valve HO-2-2301-48 could not be reopened from control room Cause unknown Valve manually opened, declared aperable & cycled several times w/no problems W/840720 ltr EAGLE-J B , KALIVIANAKES, N Commonwealth Edison Co 84/07/20 25935 141 24X Fiche 50-265, 84/07/20,8408060251 84/07/20 366
- B40B310186 Part 21 rept ra turus-to-reactor bldg vacuum breakers Memo of B40B20 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
  VILLAR General Electric Co B4/OB/21 ROSSI.C E Director's Office. Office of Inspection and Enforcement 3pp 26318 327 243 Fiche. 50-000.84/08/21,8408310186

#### V Operator Examinations

- 8408140372 Forwards proposed rev to "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," in response to NUREO-0737, Item I A 3 I MARSHALL, J O Commonwealth Edison Co 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26051 2424% Fiche 50-000,84/08/07.8408140372
- --8408140387 "Requalification Program for Licensed Operators. Senior Operators (Limited) "

  \*\* Commonwealth Edison Co 84/07/19 10pp 26051 242 24X Fiche 50-000.84/08/07,8408140372
- B40B140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners MALKER.R D Region 3. Office of Director 84/08/10 Michigan. Univ of. Ann Arbor. MI 2pp 26051 Michigan,

#### DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

- F Security, medical, emergency & firs protection plans
- 8408020150 Ack receipt of 840705 ltr forwarding scope & objectives for 840911 emergency preparedness exercise Proposed objectives acceptable winclusion of assembly/accountability PAPERIELLO.C. J. Region 3. Defice of Director 84/07/27 FAY.C W Hisconsin Electric Power Co. ip 25886-028 24X Fiche 50-266.84/07/27.8408020150.
- --8408020155 Forwards draft scope for 840711 emergency preparedness exercise Detailed scenario will be provided by first wk of Aug & associated controller packages will be provided by
- 8408020160 Notifies that review completed re 840629 revs to App C of emergency plan Plan changes do not downgrade effectiveness of emergency plan PAPERIELLO.C J. Region 3. Office of Director 84/07/27 FAY.C W Hisconsin Electric Power Co. ip 25886 039 24X Fiche: 50-266.04/07/27.8408020160
- 8408030167 Forwards Rev O to "Control Room Design Review Program Plan," in partial fulfillment of Generic Ltr 82-33, "Suppl 1 to NUREG-0737 Requirements for Emergency Response Capability "FAY,C W Wisconsin Electric Power Co 84/07/31 DENTON, H R Office of Nuclear Reactors Regulation, Director 1p 25911 193 24X Fiche 30-266,84/07/31,8408030167
- --B408030170 Rev 0 to "Control Room Design Review Program Plan "

  \* Wisconsin Electric Power Co B4/07/31 180pp. 25911 194 24X
  Fiche 50-264, 84/07/31, 8408030167
- 8408170198 Ack receipt of 840731 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Repts 50-266/84-08 & 50-301/84-06 AXELSGN,W L Region 3, Office of Director 84/08/13 CASSIDY,T 50-301/84-04
  AXEL6GN,W L Region 3, Office of Director 84/08/13 CA981DY,T J
  Wisconsin Electric Power Co 10 26118 093 24X
  Fiche 50-266,84/08/13,8408/70198

- -8408170203 Forwards response to NRC 840711 ltr re noncompliance noted in IE Insp Repts 50-265,84-08 & 50-301/84-06 Encl withheld (ref 100FR/3 21)
  CASBIDY. 7 J Wisconsin Electric Pawer Co 84/07/31 KEPPLER, J G Region 3, Office of Director ip 26118 094 24y
  Fichs 50-266,84/08/13,8408170198
- 8408210343 Revised emergency plan maint procedures including 1 1 re routine check, mainticalibr & inventory schedule for health physics equipment & 1 2 re routine check, maint & calibr instructions for emergency plan equipment W/840814 ltr \* Hisconsin Electric Pouer Co 84/08/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 74pp 26181 043 24X Fiche 50-266.84/08/14,8408210343
- B408290197 Informs that NRC representative will not be available to attend FEMA presercise briefing W Snell will contact FEMA after NRC B40910 entrance & attend B40913 public critique Region III representation at FY85 public critiques unlikely PAPERIELLO.C J Division of Emergency Preparadness & Engineering Response (Post B30103) B4/08/24 WEAVER.W J Federal Emergency Management Agency Ip 26291 176 24X Fiche 50-266,84/08/24, B408290197
- --8408290206 Forwards schedule for 1984 emergency exercise NRC representation at pre & post-exercise briefings requested MEAVER, W J Federal Emergency Management Agency 84/08/16 KEPPLER, J G Region 3. Office of Director 33p 26291 177 Fiche 50-266,84/08/24,8408290197

#### H General correspondence

- 8408090514 Informs that NRC deleting organization on distribution for correspondence between NRC & util Correspondence available in LPDR ANDERSON, P
  - IN LIDM COLBURN, T G Operating Reactors Branch 3 84/07/27 Wisconsin's Environmental Decade 1p 25983 115 24; Fiche 50-266,84/07/27,8408090514 248
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8407310166 Forwards rev to updated FSAR for Point Beach Nuclear Polant Units I & 2

  FAY.C W Wisconsin Electric Power Co 84/07/20 DENTON, H R

  Dffice of Nuclear Reactor Regulation, Director MILLER, J R

  Operating Reactors Branch 3 2pp 25905 001 24X

  Fiche 50-266/84/07/20,8407310166
- --8408020148 Rev to updated FSAR for Point Beach Nuclear Plant, Units
- P Operating license stage documents & correspondence
- B40B0i0120 Forwards marked-up radiological ETS for Units 1 & 2 Review of comments requested in preparation for discussion at meeting w/MRC, tentatively scheduled for mid-Aug in Bethesda.HD MILLER.J.R. Operating Reactors Branch 3 84/07/17 FAY.C.W. Wisconsin Electric Power Co. 81pp 25872 216 24% Ficho 50-266.84/07/17.8408010120
- 8408070492 Forwards comments on 840902 amend application for Tech Spec changes concerning containment tendon surveillance Mod of application or justification of position requested within 43 days MILLER, J R Operating Reactors Branch 3 84/07/24 FAY, C W Operating Reactors Branch 3 84/07/24 249 24X Wisconsin Electric Power Co 6pp Fiche 50-286,84/07/24,8408070492 25954 249
- 840B060127 Advises of revised schedule to install new single-failureproof auxiliary bldg crane trolley installation will begin following Spring 1985 Unit 1 refueling outage Final design reviews & license amend application will be submitted BRITT,R W Wisconsin Electric Power Co. 84/07/30 DENTON. Office of Nuclear Reactor Regulation. Director MILLER, J R Operating Reactors Branch 3 1p. 25933 057 24X Fiche 50-266.84/07/30.8408060127 DENTON H R
- 8408070328 Forwards Rev 1 to "Process Control Program," listing vendor procedures governing processing & packaging of solid radwaste radwaste

  BRITT,R W Wisconsin Electric Power Co 84/08/01

  Offlice of Nuclear Reactor Regulation, Director MLL

  Operating Reactors Branch 3 ip 25945 139 24X

  Fiche 50-266.84/08/01.8408070328 DENTON, H R MILLER, J R
- --8408070330 Rev 1 to "Process Control Program"

  \* Wisconsin Electric Power Co 84/08/01 3pp 25945 140 24X
  Fiche 50-266.84/08/01.8408070328

- B40B200002 Forwards request for addl info re 830314 & 0904 requests for Tech Spec changes allowing use of Westinghouse optimized fuel W/o encl MILLER. J R Operating Reactors Branch 3 84/08/01 FAY. C W Wisconsin Electric Power Co ip 26143 264 24X Fiche 50-266,84/08/01.8408200002
- 8408070030 Responds to 840326 request for periodic updates re progress made toward alleviating shortage of licensed operators Adequate number of licensed operators anticipated after scheduled reactor license esam in Dec 1984 BRITT,R W. Wisconsin Electric Power Co. 84/08/02 DENTON.H R. Office of Nuclear Reactor Regulation. Director MILLER.J. R. Operating Reactors Brain Regulation. Director MILLER.J. Fiche 50-266.84/08/02.8408070030
- 6408070245 Requests extension of qualification program completion schedule to end of June 1985 refueling outage for Crosby lift indicating switch assemblies & Veam thermocouple connectors

  BRITT, R W Wisconsin Electric Power Co B4/08/02 DENTON.H R Office of Nuclear Reactor Regulation. Director MILLER, J R Operating Reactors Branch 3 3pp 25949 017 24X
  Fiche 50-266.84/08/02.8408070245
- B408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl EISENHUT.D © Division of Licensing B4/08/04 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000.84/08/06.8408070110
- 8408160482 Summary of 840724 meeting w/Westinghouse Owners Group re upper plenum injection for two loop plants DIANNI.D C Operating Reactors Branch 3 84/08/07 Operating Reactors Branch 3 4pp 26108 327 24% Fiche 50-000.84/08/09, 8408160482
- 8408270233 Forwards proprietary & nonproprietary responses to request for add1 info re Tech Spec Change Request 87 concerning use of Westinghouse optimized fuel assembly Application for withholding proprietary response (ref 10CFR2 790) encl FAY,C W Wisconsin Electric Power Co 84/08/17 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER,J R Operating Reactors Dranch 3 3pp 26242 203 24x Fiche 50-266,84/08/17,8408270233
- --8408270246 Requests proprietary responses to NRC questions re optimized fuel assembly design be withheld (ref 10CFR2 790) Affidavit encl WIESEMANN,R A Westinghouse Electric Corp 84/08/07 DENTON,H R Office of Nuclear Reactor Regulation, Director 111pp 26242 208 24X Fiche 50-266,84/08/17,8408270233
- B408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
  EISENHUT, D © Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X
  Fiche 50-000.84/08/20.8408200275
- 8408280216 Forwards add1 info re methodology & results of analysis performed to determine impact of parking rod cluster control assemblies at 225 steps uithdrawn position, per request FAY; C.W. Wisconsin Electric Power Co. 84/08/22 DENTON, H.R. Office of Nuclear Reactor Regulation. Director. MILLER, J.R. Licensing Branch 3. 4pp. 26279 183. 24X Fiche 50-266,84/08/22,840820216
- 8408280128 Confirms 840820 telcon between R Seizert & C Trammel ra axistance of potential defect in Anker-Holth large bore snubbers Info provided in 840810 ltr presently being evaluated to determine inpact upon facility operations FAY.C W Wisconsin Electric Power Co 84/08/24 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 ip 26261 317 24X Fiche 50-266,84/08/24,8408280128
- 8408310284 Advises that nods to motor operated discharge valves for alactric driven auxiliary feedwater pumps completed & tested satisfactorily EISENHUT, D.O. Division of Licensing 84/08/24 NORELIUS, C.E. Division of Project & Resident Programs ip 26351 334 24X Fiche 50-266,84/08/24,8408310284
- O Inspection reports, IE Bulletins & correspondence
- 8408090184 Forwards IE Insp Repts 50-246/84-12 & 50-301/84-10 on 840711 No noncompliance identified LITTLE.W S Region 3. Office of Director 84/07/23 FAY.C W Wisconsin Electric Power Co 2pp 25992 075 24X Fiche 50-266.84/07/23.8408090184

- --8408090189 IE Insp Repts 50-266/84-12 & 50-301/84-10 on 840711 No noncompliance identified Major areas inspected followup of valve shaft insps on main steamline isolation swing check & swing stop valves
  JONES: D E . DANIELBON, D H Region 3. Office of Director 84/07/23 2pp 25992 077 24X Fiche 50-266.84/07/23.8408090184
- B408150399 Forwards IE lnsp Repts 50-266/84-10 & 90-301/B4-08 on B40625-29 No noncompliance noted PAPEMICLLD, C J Region 3. Defice of Director 84/07/25 FAY, C W Wisconsin Electric Power Co 2pp 26077 320 24X Fiche 50-266.84/07/25.8408150399
- ---B408150406 IE Insp Repts 50-266/84-10 & 50-301/84-0B on B40625-29 No violations noted Major areas inspected operational radiation protection program, including mgt.staffing, esposure control, ALARA, surveys, posting & controls & TMI action items PAUL, R A. GREGER, L R. Region 3. Office of Director 84/07/25 8pp 26077 322 24% Fiche 50-266,84/07/25,8408150399
- 8407250227 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 1179p 25065 047 24X Fiche 50-000, 84/07/27, 8407250229
- 8408160329 Forwards IE Inep Repts 50-266/84-11 & 50-301/84-09 on B40702-03 No noncompliance noted LITTLE, W S Region 3. Office of Director 84/07/30 Wisconsin Electric Power Co 2pp 26106 094 24X Fichs 50-266,84/07/30,8408160329
- --8408160331 IE Insp Repts 50-266/84-11 & 50-301/84-09 on 840702-03 No noncompliance or deviations noted Major areas inspected Followup action of previously identified insp findings MILBROT.W.E., GULDEMOND, W.G. Region 3. Office of Director 84/07/27 Spp 26106-096 24X Fiche 50-266-84/07/30-8408160329
- 8408070A01 Informs that new sys of acknowledging receipt of licensee carrespandence re noncompliance found during inspirative took effective 840820 Preprinted form will be used rather than ltr
  KEPPLER. J G Region 3. Office of Director 84/08/03
  Companies the Edison Co. 3pp. 25942 188 24% Fiche 30-000.84/08/03, 8408070401
- 8408100044 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/83-21 & 50-301/83-20.per 840517 request BPESSARD.R L. Region 3. Office of Director 84/08/03 FAY.C W Wisconsin Electric Power Co. ip 25987 063 24X Fiche 50-266.84/08/03.8408100044
- --8408100032 Further response to NRC 840317 ltr re violations noted in H. Insp Repts 50-266/83-21 & 90-301/83-20 Corrective actions drawings received after 840601 stamped w. "For Info Only" unless updated control drawings fleview completed FAY. C. W. Misconsin Electric Power Co. 84/07/20 SPESBARD, R. L. Region 3. Office 90 Director 4pp 23997 064 24X Fiche 30-266,84/08/03.8408100044
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list enc! JORDAN, C. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consol(datad Edison Co of New York, Inc. 85pp. 24068 001 24% Fiche 30-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Bvc list enci JORDAN,E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/06 Cansolidated Edison Co of New York, Inc 123pp 26067 158 24X fiche 30-000.84/08/06.8408010337
- B408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/09/0B Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- 8408070376 IC Info Notice 84-62, "Therapy Hisadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Bvc list encl ORACE,J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 24130 001 24x Fiche 50-000,84/08/10,8408070376
- 8408290365 Forwards Insp Repts 50-266/84-07 & 50-301/84-05 on 840601-0731 No noncompliance noted 8HAFER, M D Region 3. Office of Director 84/08/10 FAY, C W Misconsin Electric Power Co 2pp 26276 298 24X Fiche 50-266, 84/08/10. 8408290565

- --8408290570 Insp Repts 50-266/84-07 ' 50-301/84-05 on 810601-0731 No noncompliance noted Major areas inspected operational safety, maint, surveillance, independent insp & plant trips JACKIM.I N Region 3. Office of Director 84/08/09 9pp 26296 297 24X Fiche 50-266,84/08/10.8408290565
- B408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping"

  Svc list encl

  JORDAN, E. Division of Emergency Preparedness & Engineering

  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc. 119pp 25197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408170178 Ack receipt of 840731 ltr informing NRC of steps taken to correct noncompliance noted in IE Imap Repts 50-266/84-08 & 50-201/84-06 AKELSON, W.L. Region 3, Defice of Director 84/08/13 CASSIDY, T.J. Wisconsin Electric Power Co. 1p. 26/18/093 247 Fiche 50-266, 84/08/13, 8408170198
- --8408170203 Forwards response to NRC 840711 ltr re noncompliance noted in IE Insp Repts 50-266/84-08 & 50-301/84-06 Encl withheld (ref 10CFR73 21)
  CABSIDY.T J. Wisconsin Electric Power Co. 84/07/31 KEPPLER.J G. Region 3. Office of Director 1p. 26118 094 24X
  Fichs 50-266,84/08/13.8408170198
- B408100038 IE Info Notice B4-64. "BWR HPCI Institution Seal-In & Indication "Syc list encl URDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 8301031 84/08/15 Consolidated Edison Co. of New York, Inc. 194pp 26198 093 24X Fiche 50-000.84/08/15,8408100038
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JURGONNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc. 118pp. 26198-001 24X Fiche 50-000,84/08/16,8408100021
- 8408210550 Requests remittance of fee for 840706 application requesting relief from certain ASME Code requirements for second 10-yr inspinterval Application subjit to 840620 rev to 10CFR170 refees Discussion of fees encl W/o encl DIGGS.R M License Fee Hanagement Branch 84/08/16 FAY.C W Wisconstin Electric Power Co 1p 26195 262 24X Fiche 50-266.84/08/16.8408210550
- 8408100055 IE Info Notice 84~66. "Undetected Unavailability of Turbine-Driven Aurillary Feedwater Train " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000.84/08/17.8408100055
- 8408140208 IE info Notice 84-67, "Recent Gnubber Inservice Testing W/
  High Failure Rates " Svc list encl
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/17 Consolidated Edison Co of New
  York, Inc 122pp 26276 122 24X Fichs 50-000.84/08/17,8408140208
- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solencid Valves " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Int 115pp 26329 008 24X Fiche 50-000.84/08/21,8408210142
- R Periodic operating reports & related correspondence
- 8408310229 "Semiannual Monitoring Rept. Jan-June 1984 " \* Misconsin Electric Power Co 84/06/30 17pp 26022 165 24X Fiche 50-266,84/06/30,8408310229
- 8408210232 Monthly operating repts for Jul 1984 W/840810 ltr XRAUSE,C W , FAY,C W Wisconsin Electric Power Co 84/07/31 10pg 26184 297 24X Fiche 50-246.84/07/31.8408210232
- S Reportable occurrences. LERs & related correspondence
- B40B300511 LER B4-004-00 on 840721, inadvertent actuation of reactor protection sys occurred on low presSurizer pressure Caused by interlock circuit P7 deenergized due to maint work Maint work procedure under review W/640820 Itr FAY: C W Wisconsin Electric Power Co 84/08/20 KEPPLER, J G Region 3. Office of Director 3pg, 26313 340 24% Fiche 50-266.84/08/20.8408300511

- 8408300518 LER 84-003-00 on 840721, high neutron flux generated by source range instrumentation Channel 32, activating reactor profection sys Caused by detector malfunction after source range intruments energized when unblocked W/840820 ltr FAY.C W Risconsin Electric Power Co 84/08/20 KEPPLER.J G Region 3. Office of Director 33pp 26313 351 249 Fiche 50-266,84/08/20,8408300518
- V Operator Examinations
- 8408070030 Responds to 840326 request for periodic updates re progress made toward alleviating shortage of licensed operators. Adequate number of licensed operators anticipated after scheduled reactor license exam in Dec 1984.

  BRITT.R W Wisconsin Electric Power Co. B4/08/02 DENION, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 2pp 25950-036 24X Fiche 50-266.84/08/08.8408070030
- 8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners MALKER,R D Region 3. Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10.8408140426
- 8408230321 Advises that operator & senior operator licensing exams scheduled for 841204-06 Matl listed in encl "Ref Metl Requirements for Operator/Spnior Operator Licensing Exams" requested by 841004 WALMER, R D Region 3, Office of Director 84/08/17 FAY, C W Wisconsin Electric Power Co. Spp. 26212 286 24X Fiche 50-266.84/08/17.8408230521
- DDCKET 50-267 FORT ST VRAIN NUCLEAR GENERATING STATION

  F Security, medical, emergency & fire protection plans
- 8408290264 Forwards complete package for 1984 Fort St Vrain radiological emergency exercise Package consists of scope & objectives.narrative summary & sequence of events.conduct of exercise & observer/prompter packages
  WAREMBOURG, D. W. Public Service Co. of Colorado. 84/06/11
  JOHNSDN.E H. Region 4. Office of Director. 135pp. 26295-065. 24
  Fiche 50-267.84/06/11.8408290264
- B408310040 Advisor that Scenario F08AVEX-84 door not support escalation to general emergency classification & not consistent w/App E of IOCFR50 Early warning alert sys should be included in exercise
  JOHRSEN,E H Region 4, Office of Director 84/07/07 LEE,O R Public Service Co of Colorado 2pp 26333 358 24X
  Fiche 50-267,84/07/09,8408310040
- B408290181 Confirms scheduling change for 1984 radiological emergency exercise, per 840716, 17 & 18 telcons Exercise postponed until 840815 Revised scope & objectives, summary & sequence of events & conduct of exercise encl MAREMBOURG, D & Public Service Co of Colorado 84/07/20 JOHNSON, E H. Region 4, Office of Director 141pp 26309 010 24X Fiche 50-267, 84/07/20, 8408290181
- 8408030168 Responds to NRC 840625 concorns re Bldg 10 const Concept of Bldg 10 finalized to relieve crouding conditions & to accommodate equipment replacements being planned Bldg 10 constitutes mad not requiring amend to OL LEE.O R Public Service Co of Colorado 84/07/25 JOHNSON,E H Region 4. Office of Director 399pp 25913 048 24x Ficho 50-267.84/07/25.8408030168
- 9408070313 Forwards NRC/DDE Form 741 for Transaction YVB-JXI-0079 Encl withheld WAREHBOURG D Public Service Co of Colorado 84/07/30 JOHNSON, E.H. Region 4. Office of Director 1p 25948 001 24X Fiche 50-26/,84/07/30.8408070313
- 840809031: Forwards application for amend to License DPR-34, revising Tech Specs to comply w/MUREQ-0737. Items II 8 3.II F 1 3 & 11I D 3 4 LEE, O R Public Service Ca of Colorado 84/07/31 JOHNSON, E H Region 4, Office of Director 3pp 25994 114 24X Fichs 50-267.84/07/31,8408090311
- --8408070316 Application for amend to License DPR-34, revising Tech Specs to comply w/NUREG-0737. Items II B 3, II F 1 3 t 11 D, 3 4 Fee encl
  LEE, O R Public Service Co of Colorado 84/07/31 6pp
  25794 117 24X Fiche 50-267,84/07/31,8408070311

- --8408090322 Proposed revs to Tech Spec limiting conditions re control room temp, area radiation monitors, selamic instrumentation, primary coolant noisture instrumentation, suitchgear room temp, emergency ventilation sys 5 fire suppression sys Public Service Co of Colorado 84/07/31 21pp 25994 123 24X Fiche 50-267,84/07/31,8108090311
- B40B280480 Forwards NRC/DDE Form 741 for Transaction YVB-JXI-00B3 Encl withheld GAMM, J W Public Service Co of Colorado 84/08/15 JOHNSON, E H Region 4, Office of Director ip 26282 102 24X Fiche 50-267.84/08/15.8408280480
- P Operating license stage documents? correspondence
- 840B020198 Provides advance notification of spent fuel shipments from plant in Platteville.CD to Idaho Chemical Processing Plant in Scoville.ID during Jul & Aug 1984 Info withheld (ref 10CFR73 72)
  WAREMBOURG, D Public Service Co of Colorado 84/0//13
  JOHNSON.E H , KELLEY.J Region 4. Office of Director 1p
  25898 187 24X Fiche 50-267.84/07/13.8408020178
- 8408080525 Discusses proposal for documentation of disciplinary action against employees When NRC requests info re disciplinary action for employee, licensee will submit info w/individual name purged

  LEE, O R Public Service Co of Colorado 84/07/24 COLLINS, J T Region 4, Office of Director 2pp 25975 288 24x

  Fiche 50-267, 84/07/24, 8408080525
- 8408070225 Ack receipt of 840627 ltr transmitting current description of GA program, implemented per 10CFR50 54(a) Review continuing JOHNSON, E H Region 4, Office of Director 84/07/31 LEE, O R Public Service Co of Colorado 1p 25748 303 24X Ficha 50-267,84/07/31,8408070225
- 840B090313 Forwards application for amend to License DPR-34, revising Tech Specs to comply w/NUREG-0737, Items II B 3, II F 1 3 % III D 3 4 LEE, D R Public Bervice Co of Colorado 84/07/31 JOHNSON, E H Region 4, Office of Director 3pp 25974 114 24X Fiche 50-267,84/07/31,8408090311
- --B40B090316 Application for amend to License DPR-34, revising Tech Spels to comply w/NUREO-0737, Items II B 3, II F I 3 % II D 3 4 Fee encl LEE, O R Public Service Co of Colorado 84/07/31 App 25994 117 24X Fiche 50-267,84/07/31,640B090311
- --8408090322 Proposed revs to Tech Spec limiting conditions re control room temp, area radiation monitors, seismic instrumentation, primary coolant moisture instrumentation, switchgear room temp, emergency ventilation sys & fire suppression sys # Public Service Co of Colorado 84/07/31 21pp 25994 123 24X Fiche 50-267,84/07/31,8408090311
- 8408090405 Advises that refund will be sent for everywhent of fee for review of 830419 application for Amend 43 to License DPR-34 MILLER.W O License Fee Management Branch 84/08/01 LEE.O R Public Service Co of Colorado 2pp 25978 0/6 24X Fiche 50-267.84/08/01.8408080405
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl EISENHUT.D © Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000,84/08/06.8408070110
- B40Bi40370 Amended notification of significant licensee meeting on 840B23 in Arlington.TX to discuss progress on evaluating changes to Tech Spec Liniting Conditions for Operation 4 1 7 \* Region 4, Office of Director 84/08/09 Region 4, Office of Director 1p 26126 246 24X Fiche 50-267,84/08/09,840B160370
- B40B200559 Confirms B40B06 telcon on Tech Bpec change request retendon corrosion & anchor assembly surveillance Tech Spec change request will be submitted by B4090 MREMBOURG, DW Public Service Co of Colorado 84/08/09 JOHNBON, E H Region 4, Office of Director 2pp 26139 041 24X Fiche 50-247, B4/0B/09, B40B200559
- 8408200581 Informs that Rev 1 to FSAR App B.GA program for plant operation.satisfies requirements of 10CFR50.App B & is acceptable DHNSMIN.E H Region 4. Office of Director 84/08/10 LEE.O R Public Service Co of Colorado 2pp 26139 058 24X Fiche 50-267.84/08/10.8408200581

- 8408270256 Forwards "Response to NRC/LASL Concerns to Cracked Fuel Element Integrity " Issues thated by LASL pose no problem w/ regard to fuel elements w/cracked webs LEE.O R Public Service Co of Colorado 84/08/13 JOHNSON, E H Region 4, Office of Director 7pp 26275 049 24X Fiche 50-267.84/08/13.84082270256
- 8408210462 Forwards response to QRNL concerns & proposal identified in NRC 840523 itr Basis for discussion of DRNL/util concerns & resolution of issues delaying implementation of revised Limiting Condition for Operation 4 i 7 discussed GAMM.J W Public Service Co of Colorado 84/08/14 JOHNSON, E H Region 4. Office of Director 9pp 26149 330 24X Fiche 50-267,84/08/14,8408210462
- B40B200275 Generic Ltr B4-20 to all licensees of operating reactors & applicants for DLs re scheduling guidance for licensee submittals of reloads that involve Unreviewed safety questions Svc list encl
  EISENHUT, D G Division of Licensing B4/0B/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X
  Fiche 30-000, 84/0B/20, 840B200275
- 4 Inspection reports: IE Bulletins & correspondence
- 8408230471 Forwards IE Insp Rept 50-267/84-15 on 840604-08 No violations or deviations noted JOHNSDN.E H Region 4. Office of Director 84/07/05 LEG.O R Public Service Co of Colorado 2pp 26212 184 24X Fiche 50-26/,84/07/05,8408230471
- --8408230522 IE Insp Rept 50-267/84-15 on 840604-08 No violations or deviations noted Major areas inspected collection storage & maint of GA records EVANS.C A. HALL.R E. Region 4, Office of Director B4/06/29 5pp 26212 186 24X Fiche 50 267.84/07/05.8408230471
- 8408080520 Informs of control rod & CRD insp & testing in response to NRC 840709 insp Major power consumption & scram verification of all 37 CRD & orifice assemblies completed & insp underway Plan for further action described LEE.D R Public Service Co of Colorado 84/07/18 JOHNSON, E H Region 4, Office of Director 5pp 25975 272 24X Fiche 50-267.84/07/18,8408080520
- 8408160507 Forwards IE Insp Rept 50-267/84-15 on 840601-30 & netices of violation & deviation
  JOHNSON,E H Region 4, Office of Director 84/07/23 LEE, D R Public Service Co of Colorado 2pp 26107 335 24X
  Fiche 50-267.84/07/23,8408160507
- --8408160509 Notice of violation from imsp on 840601-30

  \*\* Region 4. Office of Director 84/07/23 3pp 26107 337 24X
  Ficha 50-267,84/07/23,8408160507
- ---8408160513 Notice of deviation from inap on 840601-30 \* Region 4, Office of Director 84/07/23 1p 26107 340 24x Fiche 50-267,84/07/23,8408160507
- --8408160516 IE Insp Rept 50-267/84-15 on 840601-30 Violation & deviation noted special test initiated w/o supervisor signature & independent check of shift turnaver procedures did not occur during 1983
  PLUMLEE,G L., IRELAND,R E. Region 4, Office of Director 84/07/17 16pp 26107 341 24X Fiche 50-267.84/07/23,8408160507
- 8407250227 [E Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Clectrical Equipment at Commercial Power Plants" Byc list encl JORDAN, C. Division of Emergency Preparedness & Engineering Response (Post 830107) 84/07/27 Consolidated Edison Co of New York, Inc. 117pp 25865-047 24X Fiche 50-000,84/07/27,8407250227
- B40BiB0B06 Submits description of spent fuel insp program to be incorporated into Teth Specs Changes concern obtaining photographic record of vertical faces of fuel elements ramoved from core during each refueling MARCHBOURG. D Public Bervice Co of Colorado B4/07/31 JDHNBON. E H Region 4, Office of Director 2pp 26075 290 24X Fiche 90-267, B4/07/31, B4091B0306
- 8408160207 Responds to NRC ltr re violations noted in IE Insp Rept 50-267/84-14 Corrective actions nitrogen pressurization sys returned to svc & shift supervisor warned re failure to sign off on power ascension procedure MAREMBOURG, D.W. Public Service Co. of Colorado 84/08/03 JOHNSON.E H. Region 4, Office of Director 13pp 26106 287 24) Fiche 50-267,84/08/03,8408160207

- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures ' Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/09/04 Consolidated Edison Co of New York, Inc 85pp 24048 001 24X Fiche 50~000,84/08/04.84080103333
- 8408010337 IE Info Notice 84-60, 'Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " SvC 1)st encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 630103) 84/08/06 Consolidated Edison Co of New York, Int 123pp 26067 158 24X Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc. 120pp 26129 118 24% Fiche 50-000,84/08/08.8408070120
- 840807037& IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl ORACE,J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 123pp 26130 001 24x Fiche 30-000,84/08/10,8408070374
- B40B21d42B Requests 30-day extension to implement shift turnover procedure in response to notice of violation in IE Insp. Rept 50-267/84-16 Further R&D needed MAREMBOURG.D Public Service Co. of Colorado. 84/08/10 JOHNSON.E Region 4. Office of Director. 2pp. 26179 202. 24X Fiche 50-267.84/08/10.8408210428
- 840Bi00009 IE Info Notice 84-63. "Defective RHR Replacement Piping "
  Svc list encl
  JORDANIE L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc. 119pp 26197 218 24X Fiche 50-000.84/08/13.8408100009
- 8408100038 IE Info Notice 84-64, "BWR HPCF Initiation Seal-In & Indication " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038
- 8408100021 IE Info Notice 84-65, "Underrated Puses Which May Adversely Affact Operation of Essential Electrical Equipment" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 1180p 26118 001. 24X Fiche 50-000.84/08/16 8408100021
- 8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN-E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000.84/08/17.8408100055
- 8408140208 IE Info Notice 84-47, "Recent Snubber Inservice Testing W/ High Failure Rates " Suc list end! JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000.84/08/17, 8408140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperty Rated Field Wiring to Bolenoid Valves " Svc list enct JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/08/21 Consolidated Edison Co of New York, Inc 115pp. 26329 008 24X Fiche 50-000.84/08/21.8408210142
- Periodic operating reports & related correspondence
- B40B010006 Forwards "Rept of Changes, Tests & Experiments Not Requiring Prior Commission Approval" for 840101-22 Anniversary date of rept changed to correspond w/submittal of annual update to FSAR Future annual repts will cover Jan 23 Jan 22 HAREMBOURG, D Public Service Co of Colorado 84/07/20. JOHNSON, E H Region 4, Office of Director ip 25866 244 24X Fiche 50-267,84/07/20,84087010006
- --8408010008 "Rept of Changes, Test & Experiments Not Requiring Prior Commission Approval per 100FR80 39(a) for 840101-22 " \* Public Service Co of Colorado 84/01/22 22pp 25866 245 24X Fiche 50-267,84/07/20,8408010006
- 8408230456 Forwards monthly operating rept for Jul 1984 Revised monthly operating rept for June 1984 also encl due to problems experienced w/turbine generator integrator OAHM, J W Public Service Co of Colorado 04/08/15 Record Services Branch (Document Control Desk) ip 26213 105 247 Fiche 50-267.84/08/15.8408230456

- --8408230457 Monthly operating rept for Jul 1984 FULLER.C Public Service Co of Colorado 126 84/07/31 8p; 26213 106 24X Fiche 50-267.84/08/15.8408230456
- --8408230459 Revised monthly operating rept for June 1784 FULLER, C Public Service Co of Coloredo 125 84/06/30 8pp 26213 144 24X Fiche 50-267.84/08/15.8408230456
- S Reportable occurrences, LERs & related correspondence
- 840B080514 LFR 84-005-01 on 840327, inspirevealed wire failures in PCRV prestressing tendons Caused by corrosion Visual inspired anchor assemblies, lift-off testing detensioning gas sampling & metallurgical analysis completed W/840727 tr NOVACHEK, F. WAREMBOURG, D. Public Service Co. of Colorado 84/07/27 9pp 25974 235 24X Fiche 50-267,84/07/27,8408080514
- 8408070176 PND-IV-84-015 on 840720, liquid release from reactor bldg exceeded Tach Spec gross beta limits by factor of 2 24 Violation not recognized until 840726 Investigation engoing Special insp of event scheduled for wk of 840730 MURRAY, B . HALL, R Region 4. Office of Director 84/07/27 ip 25974 362 24% Fiche 30-267.84/07/27,8408090176
- 840B070233 Potential Part 21 rept re defective threaded rod matl supplied by Texas Bolt Co on 840618 Rods returned to vendor for replacement Nonconformance Repts 84-187 & 84-205 encl LEE.O R Public Service Co of Colorado 84/07/30 Director's Office, Office of Inspection and Enforcement 19pp 2594B 304 24X Fiche 50-267,84/07/30,8408070233
- DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8408300244 Ack receipt of scape & objectives for 840621 emergency preparedness exercise Submittal fulfills min requirements for small-scale eiercise Complete scenario will be reviewed when received & comments transmitted DANCE.H C Region 2, Office of Director 84/05/21 TUCKER,H B Dute Power Co 1p 26307 015 24% Fiche 50-269.84/05/21, B408300244
- B40B300427 Forwards FEMA "Oconee Nuclear Power Plant Full-Scale Local Exercise Conducted on B30406," final rept DANCE.H C Region 2. Office of Director B4/07/11 TUCKER.H B Duke Power Co ip 26315 205 24x Fiche 50-269.84/07/11, 840B300427
- B408150326 Forwards public version of Rev 84-02 to "Emergency Plan Implementing Procedures " TUCKER, H B Duke Power Co 84,07/17 O'REILLY, J P Region 2, Uffice of Director ip 26099 001 24X Fiche 50-269,84/07/17, B408150326
- --8408150335 Public version of Rev 84-02 to "Emergency Plan Implementing Procedures " W/JM Felton 840808 release memo TUCKMAN.H 8 Duke Power Co 84/06/07 195pp 26099 002 24X Fichs 50-269,84/07/17,8408150326
- B408240416 Forwards Insp Repts 50-269/84-15,50-270/84-14 & 50-287/84-18 on B40611-07to No violations or deviations noted DANCE.H C Region 2, Office of Director 84/07/19 TUCKER,H B Duke Fouer Co 1p 26237 113 24X Fiche 50-269,84/07/19, B408240416
- --8408240421 Insp Repts 50-269/84-15,50-270/84-14 & 50-287/84-18 on 840611-0710 No noncompliance or deviations noted Major areas inspected operations, maint, surveillance, ESF, emergency drills & fual handling BRYANT, J Region 2. Office of Director 84/07/19 6pp 26237 114 24X Fiche 50-269,84/07/19,8408240416
- 8408280361 Forwards Insp Repts 50-269/84-14, 50-270/84-13 & 50-287/84-16 on 840619-21 No violations or deviations identified DANCE.H C Region 2: Office of Director 84/07/20 TUCKER.H B Duke Power Co 2pp 26282 239 24X Fiche 50-269,84/07/20,
- --8408280370 Insp Repts 50-269/84-14.50-270/84-13 & 50-287/84-16 on 840619-21 No violations or deviations identified Major area inspected emergency preparedness exercise DECKER: TR Region 2. Office of Director 84/07/06 9pp 26282 241 24X Fiche 50-269.84/07/20,8408280361

- 8408130149 Forwards IE Safeguards Insp Repts 50-269/84-17,50-270/84-16 & 50-287/84-19 on 840716-20 Ne violations or deviations
- Manual Control of the Control of the Control of Control
- --840B130166 IE Bafeguards Insp Repts 50-269/84-17,50-270/84-16 & 50-287/84-19 on 840716-20 No violation or deviations identified Major areas inspected security sys power supply & alarm station Details withheld (ref 10CFR2 790 & 73 21) MODRE, D & Region 2, Office of Director 84/08/07 1p 26007 346 24X Fiche 50-269,84/08/07,8408130149
- 840B170329 Commits to assure that operators can obtain flashlight to assist in safe passage to standby shotdown facility,per requirements of 10CFR50.App R
  TUCKER.H B Duke Power Co B4/0B/0B DENTON.H R Office of Nuclear Reactor Regulation, Director STOLZ.JF Operating Reactors Branch 4 2pp 26112 361 24X Fiche 50-249,84/0B/0B.840B170329
- B40B300357 Confirms 840B06 telcon w/JP 0'Reilly re 840B15 meeting in Region II ofc to discuss dusign & operation of standby shutdown facility concerning App R to 100FR30, fire protection & 100FR30 physical protection Agenda anci LEMIS.R C Region 2. Office of Director B4/0B/08 TUCKER,H B Duke Power Co 3pp 26314 222 24X Fiche 50-000,84/0B/0B, B40B300357
- 8408200414 Forwards draft safety evaluation of procedures generation ROB200414 Forwards draft safety evaluation of procedures gone package for emergency operating procedures Response to open items re witters guide & validation/verification programs requested within 30 days of ltr neceipt RIVENBARK, G W Operating Reactors Branch 4 84/08/09 TUC Duke Power Co 2pp 26182 OOI 24X Fiche 50-249,84/08/09, 8408200414
- ---B408200424 Draft safety evaluation of procedures generation package Package should be revised to address items in Section 2 \* NRC No Detailed Affiliation Given 84/08/09 11pp 26182 003 24X Fiche 50-269,84/08/09,8408200444
- 8408300014 Forwards public version of Rev 13 to crisis mgt plan & ravised emergency plan implementing procedures
  TUCKER.H B Duke Power Co 84/08/10 Record Services Branch
  (Document Control Desk) 21pp 26332 393 24X
  Fiche 50-000.84/08/10.8408300014
- --8408300021 Public version of Rev 13 to "Crisis Mgt Plan for Nuclear Stations "
  \* Duke Power Co 84/08/15 30pp 26333 010 24x
  - Fiche 50-000,84/08/10,8408300014
- ---8408300028 Public version of revised crisis mgt plan implementing procedures including 5 3 1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group W/Felton 840823 mema \* Duke Power Co. 84/08/15 170pp 26333 040 24% Fiche 50-000.84/08/10,8408300014
- 8408220071 Forwards three exemption requests from 10CFR30, App R. Section III G 2 requirements re fire protection of safe shotdown capability, supplementing 831024 initial request No add1 fees TUCKER, H B Duke Power Co 84/08/14 DENTON, H R Office of Nuclear Reactor Regulation, Director STDLZ, J F Operating Reactors Branch 4 App 26193 289 24X Fiche 50-269, 84/08/14, 8408220091
- B40B310121 Requests extension of time to respond to B40720 ltr re util plans for establishing emergency operations facility design consistent w/requirements of Suppl 1 to NUREO-0737 Extension requested due to judicial review of util appeal TUCKER.H B Duke Pawer Co B4/0B/24 DENTON,H R Office of Nuclear Reactor Regulation, Director BTULZ.JF Operating Reactors Branch 4 2pp 26322 243 24% Fiche 50-269.84/0B/24,840B310121
- I Financial information
- 8408240224 Forwards Duke Power Go & North Carolina Municipal Power NOBESCIZE FORWARDS DUKE POWER CO & North Carolina Munici Agency i 1983 annual repts TUCKER.H B Duke Power Co 84/08/16 DENTON.H.R De Nuclear Reactor Regulation, Director 2pp 26237 137 Fiche 50-000.84/08/16.8408240224 Office of
- -8408240242 "1983 Annual Rept " LEE.W S Duke Pover Co 83/12/31 Fiche 50-000,84/08/16,8408240224 26237 167 47pp 24X

- J Insurance & indemnity information
- 8408270006 Forwards Endorsements 11 & 12 to NELIA Policy NF-281 DJEMAL.A Marsh & McLennan, Inc. 84/08/24 DINITZ, I Assi Director for State & Licensee Relations 3pp 26291 235 2 Fiche 50-269,84/08/24,8408270006 26291 235 24
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8408220201 Forwards updated FSAR for Oconee Nuclear Station Info brings FSAR up to date as of 831231 TUCKER.H B Duke Power Co 84/08/15 DENTON.H R Office of Nuclear Reactor Regulation, Director STOLZ.JF Operating Rea Branch 4 1p 26191 023 24X Fiche 50-269,84/08/15,8408220201
- --B408220208 Updated FSAR for Oconee Nuclear Station \* Duke Power Co 83/12/31 180pp 26191 024 24X Fichs 50-269,84/08/15,8408220201
- P Operating license stage documents & correspondence
- 8408070389 Forwards "Extension of Retainer Lifetime to Four Cycles," for Oconee. Unit 3 w/results of exams of two retainers after three cycles Approval of four-cycle retainer usage requested before Dec 1984
  TAYLOR.J H Babcock & Wilcox Co 84/07/24 STOLZ.J F Operating Reactors Branch 4 1p 25945 252 24X Fiche 50-000, 84/07/24. Dograting
- ~-8408070392 "Extension of Retainer Lifetime to 4 Cycles " \* Babcock & Wilcox Co 84/07/12 App 25945 253 24X Fiche 50-000,84/07/24,8408070389
- 8408080288 Summary of 840712 meeting w/8&W Owners Group re mon-muclear instrumentation sys status Attendance list & viewgraphs MADAMBI.P Operating Reactors Branch 4 84/07/27 Operating Reactors Branch 4 34pp 25978 228 24X Fiche 50-000,84/07/27, Reactors Branch 4 8408080288
- B408160248 RELAPS THERMAL-HYDRAULIC ANALYSES OF PRESSURIZED THERMAL-SHOCK SEQUENCES FOR THE DCONEE-1 PRESSURIZED WATER REACTOR FLETCHER.C D . DOLANDER.M A . STITT.B D EGG. Inc FIN A-6047 NURED/CR-3761 B4/07/31 Division of Accident Evaluation 16: 26125 001 24X Fiche 50-269, 84/07/31, 8408160248
- 8408200149 Application for amend to Licenses DPR-38.DPR-47 & DPR-55, updating Tech Spec 4 2 4 re reactor vessel matt surveillance to incorporate changes documented in DAM-1343 W/o stated ree TUCKER.H B Duke Power Co 84/08/02 DENTON.H R Defice of Nuclear Reactor Regulation, Director STOL2,J F Operating Reactors Branch 4 3pp 26133 286 24X Fiche 50-269,84/08/02,8408200149
- --8408200155 Proposed Tech Spec 4 2 4 re reactor vessel matl surveillance NSEC evaluation encl \* Duke Power Co 84/08/02 7pp 26133 289 24x Ficha 50-269,84/08/02,8408200149
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Pripritization of Generic Bafety Issues" Svc list ancl ETSENHUT.D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238, 24X Fiche 50-000.84/08/06.8408070110
- 8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984 JUL 1984
  TREMBLAY,P P Operating Reactors Assessment Branch
  HOLAMAN,O M Operating Reactors Assessment Branch
  25991 350 24X Fiche 50-000,84/08/06,8408090317
- 8408200059 Application for amend to Licenses DPR-36,DPR-47 & DPR-55, revising air lock testing frequency from quarterly to semiannually Fee encl
  TUCKER.H B Duke Power Co 84/08/08 DENTON,H R Office of Nuclear Reactor Regulation, Director STGLZ,J F. Operating React Branch 4 3pp 26133,296 24X Fiche 50-269,84/08/08,8408200059 Зрр
- --8408200069 Proposed Tech Specs 4 4 i 5 2 (a), revising air lock testing frequency from quarterly to semiannually # Duke Power Co 84/08/08 6pp 26133 299 24X Fiche 50-269, 84/08/08,8408200059

- 6408220292 Forwards augmented response to Generic Ltr B3-28, Items 4 i & 4 2 re reactor trip sys reliability vendor related mods & preventive maint & surveillance program for reactor trip broakers, rospectively, per 831104 & 1230 ltrs
  TUCKER.H B Duke Power Co 84/08/10 DENTON, HR Gefice of Nuclear Reactor Regulation, Director 9TGLZ, Jf Operating Reactors Branch 4 6pp 26194 072 24X Fiche 80-269.84/08/10,8408220292
- 8408230527 Forwards payment for application fee re 840802 to 08 Tech Spec changes BARR.8 Duke Power Co 84/08/15 DENTON.H R Office of Nuclear Reactor Regulation, Director STOLZ.J F Operating Reactors Branch 4 1p 26236 286 24X Fiche 50-000.84/08/15.8408230527
- B40B270339 Application for amend to Licenses DPR-3B, DPR-47 & DPR-55, revising Tech Specs re reactor bldg purge sys.protection from inadvertent low temp overpressurization & min operator staffing requirements

  TUCKER.H B Duke Power Co 84/0B/15 DENTON R Office of Nuclear Reactor Regulation, Director STOLZ.J F Operating Reactors Branch 4 Bpp 26244 307 24X Fiche 50-269,84/08/15,8408270339
- --8408270345 Proposed Tech Specs, changing reactor bldg purge sys, protection from inadequate low temp overpressurisation & min operator staffing requirements

  \* Duke Power Co 84/08/15 14pp 26244 315 24X
  Fiche 50-269,84/08/15,8408270339
- 8408270160 Forwards Rev 4 to "Dfrsite Dose Calculation Manual," incorporating Catawba calculation info Rev submitted prior to submitted of semiannual radioactive effluent release rept for Jul-Dec 1984
  TUCKER, H B Duke Pouer Co 84/08/16 DENTON, H R Office of Nuclear Reaction Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 26279 112 24X Fiche 50-000,84/08/16 8408270160
- --8408270169 Rev 4 to "Offsite Dose Calculation Manual" BIRCH,M E., HAMPTON,J W. Duke Power Co. 84/07/18 39pp 26279 114 24X Fiche 50-000,84/08/16,8408270160
- 8408270464 Forwards list of questions generated during preliminary review of pump 2 valve inservice testing Conference call should be arranged w/staff able to provide appropriate technical expertise

  STDL7.J F Operating Reactors Branch 4 84/08/17 TUCKER.H B

  Duke Power Co 10pp 26277 210 24% Fiche 50-269.84/08/17,
- 8408270499 Forwards request for add1 info re NUREG-0737, Item III D 3 4, "Control Room Habitability " Response requested within 30 days of itr receipt STOL2.J F Operating Reactors Branch 3 84/08/17 TUCKER.H B Duke Power Co 3pp 26277 039 24X Fiche 50-267, 84/08/17. 8408270499
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors to applicants for OLs re-scheduling guidance for licensee submittals of releads that involve unreviewed safety uestions Svc list encl

  15ENNUT, D © Division of Licensing 84/08/20 Consolidated ison Co of New York, Inc. 17pp 26276-244 24X che 50-000.84/08/20.8408200275
  - napection reports, IE Bulletins & correspondence
  - 328024i Informs of delay until 86030i to complete mods required by E Bulletin 79-14 Delay due to increase in total number of mods required TUCKER. H B Duke Pouer Co E4/06/21 O'REILLY, J P Region 2, Office of Director 2pp 26262 241 24X Fiche 50-269,84/06/21, 8408280241
- --8408240421 Insp Repts 50-269/84-15.50-270/84-14 & 50-287/84-18 on 840611-0710 No noncompliance or deviations noted Major areas inspected operations, naint, surveillance, ESF, emergency drills & fuel handling BRYANT, J. SASSER, K. BROWNLEE, V.L. Region 2. Office of Director 84/07/19 6pp 26237 114 24X Fiche 50-269.84/07/19.8408240416
- 8408280361 Forwards Insp Repts 50-267/84-14, 50-270/84-13 & 50-287/84-16 on 840619-21 No violations or deviations identified BANCE. H C Region 2. Office of Director 84/07/20 TUCKER. H B Duke Power Co 2pp 26282 239 24X Ficho 50-269, 84/07/20, 840820361

- --8408280370 Insp Repts 50-269/84-14.50-270/84-13 % 50-287/84-16 on 840619-21 No violations or deviations identified Major area inspected emergency preparedness exercise DECKER.T R , STANSBERRY, U W , CLINE, W E Region 2, Office of Director 84/07/06 9pp 26282 241 24X Fiche 50-269.84/07/20.8408280361
- B407250229 IF Info Notice B4-5/. Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000.84/07/27.8407250229
- 840B280472 Acv receipt of 840720 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-269/84-12, 50-270/84-12 & 50-287/84-14 LEMIS.R C Region 2. Office of Director B4/08/01 TUCKER.H I Duke Pawer Co lp 26282 045 24X Fiche 50-269.84/08/01. 8408280472
- ---B408280476 Responds to NRC 840622 1tr reviolations noted in Insp Repts 50-269/84-12, 50-270/84-12 & 50-287/84-14 Corrective actions Procedure OP/0/4/1510/10 revised to require neutron shield tank level prior to affsite shipments TUCKER, H.B. Duke Power Co. 84/07/20 O'REILLY, J.P. Region 2, Office of Director 4pp 26282 046 24X Fiche 50-269, 84/08/01, 8408280472
- --8408280479 Forwards Insp Repts 50-269/84-12.50-270/84-12 & 50-287/84-14 on 840604-08 & notice of violation LEWIS.R C Region 2. Office of Director 84/06/22 TUCKER.H B Duke Power Co 2pp 26282 050 24X Fiche 50-269,84/08/01. 8408280472
- --8409280481 Notice of violation from insp on 840604-08 \* Region 2. Office of Director 84/06/22 2pp 26282 052 24X Fiche 50-269,84/08/01,8408280472
- --B408280485 Insp Repts 50-269/84-12,50-270/84-12 & 50-287/84-14 on 840804-08 Noncompliance noted failure to verify presence % condition of neutron radiation moderator prior to shipping & failure to perform neutron radiation surveys MEDDINGTON.R E . JENKINS,G R Region 2, Office of Director 84/06/17 8pp 28282-034 24X Fiche 50-269.84/08/01.8408280472
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84708/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000.84708/06.8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list encl JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- B40B130149 Forwards IE Safeguards Insp Repts 50-269/84-17,50-270/84-16 t 50-287/84-19 on 840716-20 No violations or deviations identified DANCE, H C Region 2, Office of Director 84/08/07 TUCKER, H B Duke Power Co 2pp 26007 344 24X Fiche 50-269,84/08/07, 840B130149
- --8408130166 IE Bafeguards Insp Repts 50-267/84-17.50-270/84-16 & 50-287/84-17 on 840716-20 No violation or deviations identified Major areas inspected security sys jower supply & alarm station Details withheld (ref 10CFR2 770 & 73 21) MDDRE.D E MCOVIRE.D R Region 2. Defice of Director 84/08/07 1p 26007 346 24X Fiche 50-267.84/08/07.8408130149
- B40B070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity" Svc list encl JORDAN,C L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Cansolidated Edison Ca of New York, Inc 120pp 26127 118 24X Fiche 50-000.84/08/08.8408070120
- 84080703/6 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl ORACE.J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376
- 8408100009 IE Info Natice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN,C L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

- 8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication 'Svc list encl JURDAN, E L Division of Emergency Preparedness / Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co. of New O3) 84/08/15 Consolidated Edison Co. of New 26198 O93 24% Fiche 50~000,84/08/15,8408100038 104рр
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
- JORDAN.E L Division of Emergency Freparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26198-001 24X Fiche 50~000.84/08/16.8408100021
- 840B100055 IE Info Notice 84~66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 001 24X Fiche 50-000.84/08/17,8408100055
- 8408140208 IE Info Notice 84-67. "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN,E C. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 122pp 26276 122 24% Fiche 50-000.84/08/17.8408140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc. 115pp 26329 008 24X Fiche 50~000.84/08/21,8408210142
- R Pariodic operating reports & related correspondence
- B40822046B Monthly operating repts for Jul 1984 W/8408J5 ltr REAVIS, J A . TUCKER. H B Duke Power Co 84/07/31 17pp 26196 033 24X Fiche 50-249,84/07/31,8408220468
- B Reportable occurrences, LERs & related correspondence
- 8408140417 RO 269/83-20 re trip shaft & bearing assembly portions of CRD breaker front frame assemblies Nine of 17 GE frames defective Util awaiting schedule for delivery of new frames TUCKER.H B Duke Power Co 84/07/27 O'REILLY.J P Region 2, Office of Director 2pp 26106 074 24X Fiche 50-267.84/07/27, 8408160417
- DOCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8408300244 Ack receipt of scope & objectives for 840621 emergency preparedness exercise Submittal fulfills min requirements for small-scale exercise Complete scenario will be reviewed when received & comments transmitted DANCE.H C Region 2. Office of Director 84/05/21 TUCKER.H B Duke Power Co 1p 26307 015 24X Fiche 50-269.84/05/21. 8408300244
- B40B300427 Forwards FEMA "Oconee Nuclear Power Plant Full-Scale Local Exercise Conducted on B30406," final rept DANCE.H C Region 2. Office of Director 84/07/11 TUCKER.H I Duke Power Co ip 26315 205 24% Fiche 30-269,84/07/11. 8408300427
- 8408130326 Forwards public version of Rev 84-02 to "Emergency Plan Implementing Procedures " TUCKER.H B Duke Power Ca 84/07/17 D'REILLY, J P Region 2, Office of Director 1p 26099 001 24X Fiche 50-269, 84/07/17, 8408150326
- --8408150335 Public version of Rev 84-02 to "Emergency Plan Implementing Procedures " W/JM Felton 840808 release memo TUCKMAN.M S Duke Power Co 84/06/07 195pp 26099 002 24X Fiche 50-269,84/07/17.8408150326
- 8408240416 Forwards Insp Repts 50-269/84-15, 50-270/84-14 & 50-287/84-18 on 840611-0710 No violations or deviations noted DANCE.H C Region 2, Office of Director 84/07/19 TUCKER.H B Duke Power Co 1p 26237 113 24% Fiche 50-269, 84/07/19, 8408240416
- ---8408240421 Insp Repts 50-269/84-15,50-270/84-14 & 50-287/84-18 on 840611-0710 No noncompliance or deviations noted Major areas inspected operations,maint,surveillance,ESF,emergency drills & fuel handling BRYANT, J Region 2, Office of Director 84/07/ 26237 114 24X Fiche 50~269,84/07/19,8408240416 84/07/19 6pp

- 8408280361 Forwards Insp Repts 50-269/84-14.50-270/84-13 & 50-287/84-16 on 840619-21 No violations or deviations identified

  ANCE: H C Region 2. Office of Director 84/07/20 TUCKER

  DANCE: H C Region 2.0 Office of Director 84/07/20 TUCKER 8408280361
- --8408280370 Insp Repts 50-269/84-14.50-270/84-13 & 50-287/84-16 on 840619-21 No violations or deviations identified Major area inspected emergency preparedness exercise DECKER.T R Region 2. Office of Director 84/07/06 9pp 26282 241 24X Fiche 50-269.84/07/20.8408280361
- 8408130149 Forwards IE Safeguards Insp Repts 50-269/84-17.50-270/84-16 t 50-287/84-19 on 840716-20 No violations or deviations DANCE H C Region 2, Office of Director 84/08/07 TUCKER.H B Duke Power Co 2pp 26007 344 24X Ficho 50-269,84/08/07,84/08/30149
- --8408130166 IE Safeguards Insp Repts 50-269/84-17.50-270/84-16 & 50-287/84-19 on 840716-20 No violation or deviations identified Major areas inspected security sys power supply & alarm station Details withheld (ref 10CFR2 790 & 73 21) MODRE.D E Region 2. Office of Director 84/08/07 ip 26007 346 24X Fiche 50-269,84/08/07,8408130149
- B40B170329 Commits to assure that operators can obtain flashlight to assist in safe passage to standby shutdown facility.per requirements of 10CRF80.App R
  TUCKER.H B Duke Power Co B4/OB/OB DENTON.H R Dffice of Nuclear Reactor Regulation. Director STOLZ.J F Operating Reactors Branch 4 2pp 26112 361 24X Fiche 30-269.84/08/08.8408170329
- 8408300357 Confirms 840805 teleon w/JP O'Reilly re 840815 meeting in Region II ofe to discuss design & operation of standby shutdown facility concerning App R to 10CFR50.fire protection & 10CFR73.physical protection Agenda encl LEWIS.R C Region 2. Office of Director 84/08/08 TUCKER,H B Duke Power Co 3pp 26314 222 24X Fiche 50-000.84/08/08. B40B300357
- A40A200414 Forwards draft safety evaluation of procedures generation 408200414 Forwards draft safety evaluation or proteoures generation package for emergency operating procedures Response to open items re writers guide & validation/verification programs requested within 30 days of ltr roceipt RIVENBARK.G W Operating Reactors Branch 4 84/08/09 TUCKER.H B Duke Power Co 2pp 26182 001 24X Fiche 50-269.84/08/09.
- --8408200424 Draft safety evaluation of procedures generation package Package should be revised to address items in Section 2 \* NRC No Detailed Affiliation Given 84/08/09 1ipp 24182 003 24X Fiche 50-269,84/08/09,8408200414
- 8408300014 Forwards public version of Rev 13 to trisis mgt plan & revised emergency plan implementing procedures TUCKER: H B Duke Pouer Co B4/0B/10 Record Services Branch (Dacument Control Desk) 21pp 26332 353 24X Fiche 50-000.84/08/10.8408300014
- --B408300021 Public version of Rev 13 to "Crisis Mgt Plan for Nuclear Stations ## Duke Power Co | 84/08/15 | 30pp | 26333 010 | 24X | Fichs 50-000,84/08/10,8408300014
- --8408300028 Public version of revised crisis mgt plan implementing procedures including 5 3 1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group W/Felton 840823 memo \* Duke Power Co 84/08/15 170pp 26333 040 24X Fiche 50-000, 84/08/10, 8408300014
- 840822009) Forwards three exemption requests from 10CFR50.App R. Section III 0 2 requirements re fire protection of safe shutdown capability, supplementing 831024 initial request No addl fees necessary TUCKER, H B Duke Power Co 84/08/14 DENTON, H R Office of Nuclear Reactor Regulation, Director BTGLZ, J F Operating Reac Branch 4 4pp 26193 289 24X Fiche 50-269, 84/08/14, 8408220091
- 8408310121 Requests extension of time to respond to 840720 ltr resutil plans for establishing emergency operations facility design consistent w/requirements of Suppl 1 to NUREG-0737 Extension requested due to judicial review of util appeal TUCKER.H B Duke Power Co. 8408/24 DENTON.H R. Dffice of Nuclear Reactor Regulation, Director STOLZ.J F Operating Reactors Branch 4 2pp 26327 243 24X Fiche 30-269.84/08/24, 8408310121

Financial information

- 1408240224 Forwards Duke Power Co & North Carolina Municipal Power 108240224 Forwards Duke Power Co & North Carolina Muni Agency I 1983 annual repts TUCKER H B Duke Power Co 84/08/16 DENTUN.H R Nuclear Reactor Regulation. Director 2pp 26237 13 Fiche 50-000.84/08/16.8408240224 Office of 26237 137
- ~8408240242 "1983 Annual Rept " LEE:W S Duke Power Co 83/12/31 Fiche 50-000,84/08/16,8408240224 47pp 26237 167 24x
- .. Utility Final Bafety Analysis Report (FSAR) & amends
- 1408220201 Forwards updated FBAR for Oconee Nuclear Station Info brings FBAR up to date as of 831231 TUCKER.H B Duke Power Co 84/08/15 DENTON,H R Office of Nuclear Reactor Regulation, Director 870LZ,JF Operating Reactors Branch 4 1p 26191 023 24% Fithe 50-269,84/08/15.8408220201
- -8408220208 Updated F5AR for Oconee Nuclear Station \* Duke Power Co 83/12/31 180pp 26171 024 24x Fiche 50-267,84/08/15,8408220201
- . Operating license stage documents & correspondence
- 1408080288 Summary of 840712 meeting w/B&W Chiners Group re non~nuclear instrumentation sys status Attendance list & viewgraphs enci KADAMBI,P Operating Reactors Branch 4 84/07/27 Operating Reactors Branch 4 36pp 25978 228 24X Fiche 50-000,04/07/27,
- Reactors Branch 4 8408080288
- 1408200149 Application for amend to Licenses DPR-3B, DPR-47 & DPR-55, updating Tech Spec 4 2 4 re reactor vessel matl surveillance to incorporate changes documented in BAW-1543 N/o stated
- fee TUCKER.H B Dute Power Co BA/OB/OZ DENTON.H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 3pp 26133 286 24X Fiche 50-269,84/08/02,8408260149
- -8408200155 Proposed Tech Spec 4 2 4 re reactor vessel matl surveillance NBHC evaluation enct \* Duke Power Co 84/08/02 7pp 26133 289 24x Fithe 50-265,84/08/02.8408200145
- 1408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Generic Safety Issues" Svc list encl EIGENHUT, D. G. Division of Licensing 84/08/04 Consolidated Edison Co. of New York, Inc. 10pp 26129 238 24X Fiche 50-000,84/08/06.8408070110
- 1408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
- Jul 1984
  TREMBLAY,P P Operating Reactors Assessment Branch 84/4
  HDLAMAN.O M Operating Reactors Assessment Branch 13pp
  25991 350 24X Fiche 50-000,84/08/06,8408090317
- |408200039 Application for amend to Licenses DPR-38, DPR-47 & DPR-55, revising air lock testing Prequency From quarterly to semiannually Fee encl TUCKER, H B Duke Power Co 84/08/08 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 3pp 26133 276 24% Fiche 50-267.84/08/08,8408200059
- -8408200069 Proposed Tech Specs 4 4 1 5 2 (a), revising air lock testing frequency from quarterly to seniannually \* Duke Power Co. 84/08/08 4pp. 26133 299 24X Fiche 50-269,84/08/08,8408200059
- 408220272 Forwards augmented response to Generic itr EG-28, Items 4 i & 4 2 re reactor trip sys reliability vendor related mods & preventive maint t surveillance program for reactor trip breakers, respectively, per B31104 & 1230 ltrs
  TUCKER, H B Duke Power Co 84/08/10 DENION, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 6pp 26194 072 24X Fiche 50-267, 84/08/10,840820292
- 408230527 Forwards payment for application fee re 840802 & QB Tech 10823052 Forwards Payment 10. 5,7

  Spac Changes

  BARRIS, Duke Power Co. 84/08/15 DENTON, H.R. Office of Nuclear

  Reactor Regulation, Director STOLZ, J.F. Operating Reactors Branch

  4 ip 26236 286 24x Fichs 50-000, 84/08/15, 8408230527

- 8408270339 Application for amend to Licenses DPR-38.DPR-47 & DPR-55, revising Tech Specs re reactor bldg purge sys.protection from inadvertent low temp overpressurmation & min operator from Inadvertent low temp overpressurviation & min operator staffing requirements TUCKER.H B Duke Power Co B4/08/15 DENTON.H R Office of Nuclear Reactor Regulation, Director STOLZ.J F Operating Reac Branch 4 Bpp 26244 307 24% Fiche 30-269.84/08/15,8408270339
- ~-8408270345 Proposed Tech Specs, changing reactor bldg purge sys, protection from inadequate low temp overpressuritation & min operator staffing requirements

   Duke Fower Co 84/08/15 14pp 26244 315 24x
  Fiche 50-269,84/08/15,8408270339
- 8408270140 Forwards Rev 4 to "Offsite Dose Calculation Manual," incorporating Catamba calculation info Rev submitted prior to submitted of semiannual radioactive effluent release rept to submittal of semiannual residents.

  for Jul-Dec 1984

  YUCKER: H B Duke Power Co 84/08/16 DENTON: H R Office of 
  Nuclear Reactor Regulation, Director ADENSAM: E C Licensing Branch 
  4 2pp 26279 112 24x Fiche 50-000, 84/08/16, 8408270160
- ---8408270169 Rev 4 to "Offsite Dose Calculation Manual" BIRCH.M L . HAMPTON.J W Duke Power Co 84/07/18 39pp 26279 114 24% Fiche 50-000.84/08/16.8408270160
- 8408270464 Forwards list of questions generated during preliminary review of pump 5 valve inservice testing Conference call should be arranged w/staff able to provide appropriate technical expertise SYOL7.JF Operating Reactors Branch 4 84/08/17 TUCKER, H B Duke Power Co 10pp 26277 210 24X Fiche 50-269.84/08/17.
- 8408270477 Forwards request for add1 info re NUREO-0737, Item III D 3 4, "Control Room Habitability " Response requested within 30 days of ltr receipt
  BTOLZ, J F Operating Reactors Branch 3 84/08/17 TUCKER, H B Duke Power Co 3pp 26277 039 24X Fiche 50-269, 84/08/17, 8408270479
- B408200275 Generic Ltr B4-20 to all licensees of operating reactors & applicants for Ols re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISEN-MUT, D G Division of Licensing B4/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 50-000,84/08/20,8408200275
- Q Inspection reports. IE Gulletins & correspondence
- 8408280241 Informs of delay until 850301 to complete mods required by IE Bulletin 79-14 Delay due to increase in total number of The Bulletin 7714 being 466 to the construction of the constructio
- 8408240414 Forwards Insp Repts 50-269/84-15.50-270/84-14 & 50-287/84-18 on 840611-0710 Ng violations or deviations noted BANCE.H C Region 2. Office of Director 84/07/19 TUCKER.H B Duke Power Co 1p 26237 113 24X Fiche 50-269.84/07/19.
- --B408240421 Insp Repts 50-269/84-15, 50-270/84-14 & 50-287/84-18 on 840611-0710 No noncompliance or deviations noted Major areas inspected operations, maint, surveillance. ESF, emergency drills & fuel handling BRYANT, J. SASSER, K., BROWNLEE, V.L. Region 2, Office of Director 84/07/19 6pp 26237 114 24% Fiche 50-269,84/07/19,8408240416
- 840828036: Forwards Insp Repts 50-269/84-14.50-270/84-13 & 50-287/84-16 on 840619-21 No violetions or deviations identified DANCE.H C Region 2. Office of Director 84/07/20 TUCKER Duke Power Co 2pp 26282 839 24X Fiche 50-269.84/07/20, 840880361
- --B40B280370 Insp Rapts 50-269/84-14,50-270/84-13 & 50-287/84-16 on 840619-21 No violations or deviations identified Major area inspected emergency preparedness exercise DECKER,TR, BTANSBERRY,WW, CLINE,WE Region 2, Office of Sirector 84/07/06 9pp 26282 241 24% Fiche 50-269.84/07/20, 8408280361
- 8407280229 IE Info Notice 84-87, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc. 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

- 8408280472 Ack receipt of 840/20 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-269/84-12, 50-270/84-12 & 50-287/84-14 LEWIS,R C Region 2, Office of Director 84/08/01 TUCKER,H B Duke Power Co ip 26282 045 24X Fiche 50-269,84/08/01, 8408260472
- --8408280476 Responds to NRC 840622 ltr re violations noted in lnsp Repts 50-249/84-12, 50-270/84-12 & 50-287/84-14 Corrective actions Procedure OP/O/A/1510/10 revised to require neutron shield tank level prior to offsite shipments TUCKER.H B Duke Power Co 84/07/20 O'REILLY, J P Region 2, Office of Director 4pp 26282 046 24X Fiche 50-269,84/08/01,8408280472
- --8408280479 Forwards Insp Repts 50-249/84-12,50-270/84-12 & 50-287/84-14 on 840404-08 & notice of violation LEWIS:R C Region 2: Office of Director 84/04/22 TUCKER:H # Duke Power Co 2pp 24282 050 24X Fiche 50-269,84/08/01;8408280472
- --9408280481 Notice of violation from insp on 840604-08 \* Region 2, Office of Director 84/06/22 2pp 26282 052 24X Ficha 50-269,84/08/01.8408200472
- --8408280485 Insp Repts 50-269/84-12, 50-270/84-12 & 50-287/84-14 on 840604-08 Noncompliance noted failure to verify presence & cendition of neutron radiation moderator prior to shipping & failure to perform neutron radiation surveys MEDD/ROTON,R E , JENNINS, C R Region 2, Office of Director 84/06/19 8pp 26282 054 24X Fiche 50-269.84/08/01.8408280472
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JORDAN, E. L. Division of Emergency Proparedness & Engineering Response (Past 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 85pp. 26068 001 24X Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Moet Efficiency Requirement " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of Now York, Inc. 123pp. 26067 158 24X Fiche 50-000.84/08/06.8408010337
- B40B130149 Forwards IE Bafeguards Insp Ropts 50-28/984-17.50-270/84-16 & 50-287/84-19 on B40716-20 No violations or deviations identified DANCE.H C Region 2. Office of Director 84/08/07 TUCKER.H B Duke Power Co 2pp 26007 344 24X Fiche 50-269,84/08/07.
- --8408130166 IE Bafeguards Insp Repts 90-267/84-17.50-270/84-16 & 50-287/84-19 on 840716-20 No violation or deviations identified Hajor areas inspected security sys power supply & alarm station Details withheld (ref 10CFR2 790 & 79 21) MORE, D E . MCGUIRE, D R Region 2. Office of Director 84/08/07 1p 26007 346 24% Fiche 50-269.84/08/07.8408130149
- 8408070120 IE info Notice 84-61, "Overexposure of Diver in PHR Refueling Cavity " 8vc list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- 8408070376 IC Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl ORACE, J N Division of GA. Bafeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp. 26130 001 24X Fiche 50-000,84/08/10.8408070376
- 8408100009 IE Info Notice 04-63, "Defective RHR Replacement Piping "
  Svc list encl
  JURDAN,E L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc. 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408100038 IE info Notice 84-64, "BWR HPCI Initiation Beal-In & Indication " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038
- 8408100021 IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " 8vc list enci JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Go of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

- B408100055 IE Info Notice 84-66. "Undetected Unavailability of Furbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830105) B4/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8409100055
- B40B140208 IE Info Notice 84-67, "Recent Shubber Inservice Testing W/ High Failure Rates " Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 122pp 26276 122 24X Fishe 50-000.84/08/17,8408140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves" Svc list encl JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York: Inc 115pp 26327 008 24X Fiche 50-000.84/08/21,8408210142
- R Periodic operating reports & related correspondence
- 8408220468 Monthly operating repts for Jul 1984 W/840815 ltr REAVIB.J A. TUCKER.H B. Duke Power Co. 84/07/31 17pp 26176 033 24X Fiche 50-269,84/07/31,8408220468
- DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION

  F Security, medical, emergency & fire protection plans
- B40B030052 Forwards SSER concluding that proposed mods for alternate safe shutdown are in accordance w/App R.Section II G 3 & III L. requirements w/respect to control room & cable spreading room VASSALLO, D B. Operating Reactors Branch 2 84/07/24 SINCLAIR, J Vermont Yankes Nuclear Power Corp. 2pp. 25917 341 24X Fishe 50-271.84/07/24.8408030052
- --B408030057 SSER concluding that proposed mods for alternate safe shutdown are in accordance w/App R. Section II 0 3 & III L requirements w/respect to control room, cable spreading room & switchgear room & Garacter Stranch 2 84/07/24 2pp 25917 343 24X Fiche 50-271,84/07/24,8408030052
- B40B0B0041 Requests exemption from requirements of Section IV F of App E to 19CFR50 re annual emergency preparedness exercise Event on 840615 resulted in complete implementation of emergency plan to alert level MURPHV.W P Vermont Yankse Nuclear Power Corp B4/0B/04 EISENHUT.D Q Division of Licensing 5pp. 25970 301 24X Fiche 50-271.84/0B/06.B40B0B0041
- 8408270451 Forwards Insp Rept 50-271/84-16 on 840717-19 No violations noted MARTIN.T T Division of Engineering & Technical Programs 84/08/08 MURPHY.W P Vermont Yankee Nuclear Power Corp 2pp. 26286 230 24X Fiche 50-271.84/08/08.8408270461
- --8408270465 Insp Rept 50-271/84-16 on 840717-19 No violations noted Major areas inspected changes to emergency preparedness program, elift staffing & augmentation, knowledge & performance of duties & public info program WOLTNER.E . SMITH.R W. Region i. Office of Director CROCKER.H W Division of Engineering & Technical Programs 84/08/07 3pp 26856 232 24X Fichs 50-271.84/08/08.8408270461
- 8408240272 Requests add1 compensatory measures be documented & sent to Region 1 ofc for App R deficiencies identified by Insp Rept 50-271/83-26 MARTIN.T T Division of Engineering & Technical Programs 84/08/2R MURPHY.W P Vermont Yankes Nuclear Power Corp. 2pp 26223.170 24X Fiche 50-271/84/08/22/8408240272
- B408310093 Requests extension of schedule for implementation of upgraded emergency operating procedures until B50601, due to need to complete operator training on procedures.per Suppl 1 to NUREO-0737 MURPHY, WP Vermont Yankee Nuclear Power Corp B4/08/22 VASSALU, DB Qperating Reactors Branch 2 2pp R6323 200 24X Fiche. 50-271, 84/08/22, 8408310093
- 8408160357 Rev 5 to emergency plan. "Ltrs of Agreement" \* Yankee Atomic Electric Co 84/08/31 27pp. 26091 206 24X Fiche 50-271.84/08/31.8408160357

# : General correspondence

- 3408310277 Requests that NRC make listed change to "list copies" re License DPR-28 JB Sinclair should be deleted from lists & RW Capstick added CAPSTICK, R W Vermont Yankee Nuclear Power Corp & Office of Nuclear Reactor Regulation, Director ip Fiche 50-271,84/08/24,9408310279 84/08/24 26333 287 24X
- Operating license stage documents & correspondence
- 8408150378 Forwards FR notice of environ assessment & finding of no significant impact, in response to 840330 request for exemption to permit 6-month extension for updating FSAR VASSALLO,D B Operating Reactors Branch 2 84/07/30 SINCLAIR. Vermont Yankee Nuclear Power Corp 2pp 26104 002 24x Fiche 50-271.84/07/30.8408150578 SINCLAIR J B
- --B408150585 Notice of environ assessment & finding of no significant impact, based on granting 6-month extension for updating FSAR 84/07/30 4pp

EISENHUT, D. G. Division of Licensing 24x Fiche 50-271, 84/07/30, 8408150578

- 8408150599 Forwards Amend 82 to License DPR-28 & safety evaluation Amend deletes requirement for automatic air dump sys VABSALLO.D B Operating Reactors Branch 2 84/08/03 SINCLAIR, J B Vermont Yankee Nuclear Power Corp 2pp 26105 351 24X Fiche 50-271,84/08/01.8408150559
- --8408150604 Amend 82 to License DPR-28, deleting requirement for automatic air dump sys VASSALLO,D B Operating Reactors Branch 2 84/08/01 2pp 26105 353 24X Fiche 50-271,84/08/01,8408150599
- --B408150606 Safety evaluation supporting Amend 82 to License DPR-28 \* Office of Nuclear Reactor Regulation, Director 94/08/01 29 26105 355 24X Fiche 50-271,84/08/01,8408150599
- 8408160161 Grants util 840725 request for extension of environ qualification of electrical equipment to 850331

  Justifications for continued operation acceptable Unfinished items should be qualified by 851130

  DENTON, HR Office of Nuclear Reactor Regulation, Director 84/08/02 SINCLAIR, J B Vermont Yankee Nuclear Power Corp 3pp 26124 357 24X Fiche 50-271,84/08/02,8408160161
- 8408160090 Accepts corrective actions taken to repair recirculation sys piping per 840726 meeting w/NRC Plant restart authorized authorized VASSALLO.D B Operating Reactors Branch 2 84/09/0 Vermont Yankee Ruclear Power Corp 2pp 26126 341 Fiche 50-271.84/08/03.8408160090 18 EQ\80\48 SINCLAIR, J B
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for GLs & holders of CPs re availability of Suppl 1 to NUREO-0939, "Prioritization of Generic Safety Issues" Syc list encl EISCNHUT, D 0 Division of Licensing 84/08/96 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24x Fiche 50-000.84/08/06/8408070110
- 8408160052 Forwards Rev 2 to "Environ Qualification Master Equipment List" Requests rev be reflected in SER for purposes of future IE audit of compliance w/10CFR50 49
  FINCLAIR.J B Vermont Yankee Ruclear Power Corp 84/08/10
  VASSALLO.D B Operating Reactors Branch 2 2pp 26092.075 24X
  Fiche 50-271.84/08/10.8408160052
- --8408160054 Rev 2 to "Environ Qualification Master Equipment List" \* Vermont Yankee Nuclear Power Corp 84/08/10 26pp 26092 077 24X Fithe 50-271.84/08/10.8408160052
- 8408240004 Requests extension until B41101 for responding to Goneric Ltr 84-15 re dissal generator rellability Delay due to extensive engineering efforts associated w/8-wk 1784 refueling outage
  MURRHY.W P Vermont Yankee Nuclear Power Corp 84/0
  EISENHUT, D Division of Licensing 1p 26228 252
  Fiche 50-271.84/08/16.8408240004 84/08/16
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & ficants for DLs re scheduling guidance for licensee ittals of reloads that involve unreviewed safety tons Svc list encl 407.D G Division of Licensing 84/08/20 Consolidated Co of New York, Inc 17ep 26876 244 24X 700.84/08/20.8408200275

- 8408280055 Responds to 840508 request for review of applicability or generic studies subnitted by Mark I Guners Group is recombiner capability requirements of 10CFR50 44(c)(3)(11) Util meets conditions to take credit for studies KADAK,A C Vermont Yankee Nuclear Power Corp 84/08/24 VASSALLD,D B Operating Reactors Blanch 2 3pp 26261 227 24X Ficha 50-271,84/08/24,8498280055
- G Inspection reports, IE Bulletins & correspondence
- 8408090085 Requests NRC withdraw violations noted in IC Insp Rept 50-271/84-02 for listed reasons MURPHY.W P Varmont Yahkoe Nuclear Power Corp 84/05/08 MARTIN.T T Division of Engineering \* Tochnical Programs 4pp 25993-254 24X Fiche 50-2/1.84/03/08,8408090085
- --8408090088 Ack receipt of 840508 itr informing NRC of objection to violations noted in IE Insp Rept 50~271/84-02 Violations valid Corrective actions requested within 20 days of itr date MARTIN, T T Division of Engineering & Technical Programs 84/07/25 MURPHY, W P Vermont Yankee Nucleal Power Corp 25993 258 24X Fiche 50-271.84/05/08.8408090085
- 8408030222 Forwards IE Insp Rept 50-271/84-10 on 840508-0604 & notice of violation

  STAROSTECKI, R Division of Project : Resident Programs

  MURPHY, W P Vermont Vankee Nuclear Power Corp 2pp =

  24X Fiche 50-271,84/07/12,8408030222 25917 153
- --8408030224 Notice of violation from insp on 840508-0604 \* Region 1, Office of Director 84/07/12 1p 259 Fiche 50-271,84/07/12,8408030222 25917 155 24X
- --8408030227 IE Insp Rept 50-271/84-10 on 840508-0404 Noncompliance noted failure of instrument & control personnel to complete testing in accordance w/OP 4374 RAYMOND.N J. GALLO.R M. Region 1. Office of Director 84/05/3 84/06/28
- 8407250227 IE Info Notice 84-57, "Operating Experience re Maisture Intrusion in Safety-Related Electrica) Equipment at Commercial Power Plants " Svc list onel JORDAN,E L Division of Emergency Preparedness & Engineering Response (Past 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25845 047 24% Piche 50-000,84/07/27,8407250229
- 8408020002 Forwards POE-1021, "1984 Refuel Outage Augmented Inservice Insp Program." final rept Program implemented to address concerns detailed in IE Dulletin 83-02 SINCLAIR.J B Vermont Yankee Nuclear Power Corp 84/07/30 VASSALLO.D M Operating Reactors Branch 2 2pp 25872 007 24X Fiche 50-271.84/07/30.8408020082
- --8408020097 "1984 Refuel Cutage Augmented Inservice Insp Program," final
- 8408060226 Forwards supplemental info re refueling outage augmented inservice insp program, addressing concerns of IE Aulletin 83-02 & Generic Ltr 84-11 GINCLAIR, J B Vermont Yankee Nuclear Power Corp. 84/07/31 VABSALLO.D D Operating Reactors Branch 2 20pp. 25923 3 Fiche 50-271.84/07/31.8408060226 25723 335 24X
- 8408230139 Forwards IE Insp Rept 50-271/84-13 on 840625-29 & 0712-13 No violations observed MARTIN. I I Division of Engineering & Technical Programs 84/08 MUTPHY, W P Vermont Yankoe Nuclear Power Corp 2pp 26214 019 24X Fiche 50-271,84/08/01,8408230139 84/09/01
- --8408230145 IC Insp Rept 50-271/84-13 on 840625-29 & 0712-13 No 409220149 It Imap Rept 30-271/44-13 on 840629-29 & 07(2-13 Novice and the state of Division 26214 021
- 840Bi50241 Summary of 840726 meeting w/util in Nethesda.MD re pipe crack insps performed during 1784 refueling outage Results of insps justify plant operation during 1984/85 operating cycle Liconsee presentation & list of attendees encl ROONEY, V.L. Operating Reactors Branch 2 84/08/02 Operatin Reactors Branch 2 57pp 26105 011 24X Fiche 50-271.84/08/0R 8408150261

- 8408010333 IF Into Notice 84-59, "Deliberate Circumventing of Skation Health Physics Procedures " Suc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/04 Consolidated Edison Co. of New York, Inc. 85pp. 26068 001 247 Fiche 50-000.84/08/06.8408010333
- 8408010337 IF Info Notice 84-60. 'Failure of Air Purifying Respirator Filters to Most Efficiency Requirement 'Suc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 24067-158 247 Fiche 50-000-84/08/06, 8408010337
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity ' Svc list encl
  JORNAN.E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/08 Consolidated Edison Co of New
  York, Inc. 120pp 26129 118 24x Fiche 30-000.84/08/08.8408070120
- 8408270461 Forwards Insp Rept 50-271/84-16 on 840717-19 No violations
- MARTIN.TT Division of Engineering & Technical Programs 84/08, MURPHY, W.P. Vermont Yankee Nuclear Power Corp. 2pp. 26256-230 24X Fiche 50-271,84/08/08,8408270461
- ~-8408270465 Inap Rept 50-271/84-16 on 840717-19 No violations noted Mdagr areas inspected changes to emergency preparedness program, shift staffing & augmentation, knowledge & performance of duties & public info program WOLTNER, E. SMITH.R W. Region 1. Défice of Divector of Division of Engineering & Technical Programs 84/08/07 26256 232 244 Fiche 50-271,84/08/08,8408270461 CROCKER, H W
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc
  - list encl
    ORACE, J N Division of QA, Safeguards & Inspection Programs (Post
    830103) 84/08/10 Consolidated Edison Co of New York, Inc
    125pp 26/30 001 24X Fiche 50-000,84/08/10.8408070376
- 8408100009 IE Info Notice 81-63, "Defective RHR Replacement Piping"
  - 40B100007 IE ARTH NOTES 2 2 Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50~000,84/08/13,8408100009
- 8408100038 IE Info Notice 84-64, "BUR HPCI Initiation Seal-In & Indication " Syc list enci JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co. of New York, Inc. (04pp. 26198 093 24% Fiche 50-000.84/08/15.8408100038
- 8408100021 IF Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JORDAN E L Division of Emergency Preparedness \* Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24% Fiche 50-000.84/08/16.8408100021
- 8408100055 IE Info Notice 84~66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN.C L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 001 24% Fiche 50-000,84/08/17,8408100055
- 8408140209 IE Info Notice 84-67. "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 (Consolidated Edison Co. of New York, Inc. 122pp 26276 122 24% Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-6B. "Potential Deficiency in Improperly Rated Field Wiring to Solenaid Valves " Svc list encl JORDAN.C L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pg 24327 008 24X Fiche 50-000.84/08/21,8408210142
- 8408240292 Requests add1 compensatory measures be documented & sent to Region I ofc for App R deficiencies identified by Insp Rept 50-271/43-26
- MARTIN T Division of Engineering & Technical Programs 84/08. MURPHY, W P Vermont Yankee Nuclear Power Corp 2pp 26223 190 24X Fiche 50-271,84/08/22,8408240292 84/08/22
- R Periodic operating reports & related correspondence
- 8408270152 Monthly operating rept for Jul 1984 W/840810 ltr BURGER: F J . MURPHY: W P Vermont Yankee Nuclear Power Corp 84/07/31 7pp 26257 299 24X Fiche 50-271:84/07/31;8408270152

- S Reportable occurrences. LERs & related correspondence
- 8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated SHERWOOD, G. G. General Electric Co. 84/04/13. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 3pp 26222 256. 24X Fiche 50-000, 84/04/13. 8408240348
- 840808004) Requests exemption from requirements of Section IV F of App E to 10CFR50 re annual emergency preparedness exercise Event on 840815 resulted in complete implementation of emergency plan to alert level MURPHY, W.P. Vermont Yankee Nuclear Power Corp. 84/08 MURPHY, W P Vermont Yankee Nuclear Power Corp 84/08/ EISENHUT, D G Division of Licensing 5pp 25970 301 Fiche 50-271,84/08/06,8408080041
- 8408230334 LER 84-011-01 on 840616, while performing Type C leak rate testing, valves MSIV-86D, CRD-412A, PCAC V16-19-8, FDIJ-96A & CA-89C found w/seat leakage above Tech Spec limits Maint performed & valves retested W/840816 ltr PELLETIER. J P Vermont Yankee Nuclear Power Corp 84/08/16 4pp 26212 348 24x Fiche 50-271, 84/08/16, 8408230534
- 8408230542 LER 84-012-00 on 840717.contractor failed to properly tag out reactor bldg air conditioning unit.causing supply line 2 to inspire into svc cater sys Caused by personnel error Sys isolated W/840816 ltr PELLETIER.JP Vermont Yankee Nuclear Power Corp 84/08/16 5pp 26212 356 24% Fiche 50-27(.64/08/16,8408230542
- 8408280307 LER 84-013-00 on 840721, during maint on standby liquid control systelist valves SR-11-39A & B found to have setpoints below required range Caused by testing technique Valves resettretested & reinstalled W/840820 ltr PELLETIER.J P Vermont Yankee Nuclear Power Corp 84/08/20 26282 163 24X Fiche 50-271,84/08/20,8408280307 84/0B/20 3pp
- 8408300478 LER 84-014-00 on 040723 during weekly environ air sample collections, Sample Station AT i 2 discovered not drawing continuous sample Caused by blown main fuse Fuse replaced be equipment returned to see M/840820 ltr PELLETIER, J.P. Vermant Yankee Nuclear Power Corp. 84/08/20. 3pp. 26314 092 24% Fiche 50-271, 84/08/20, 8408300478 84/08/20 3pp
- 8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcan reporting equipment quality & separation of controls to butterfly valves entl 9E lacks technical info to adequately evaluate condition

  VILLA/R General Electric Co 84/08/21 R0981.C E Director's

  Office, Office of Inspection and Enforcement 3pp 26318 327 24X

  Fichs 50-000,84/08/21.8408310186
- 8408300488 LER 84-018-00 on 840724, during second verification that diesal generator 8 4 kV bus pot fuse drawer racked in, operator inadvertently withdrew drawer Caused by insufficent instructions W/840823 | 1th PELLEFIER.U P. Vermont Yankee Niclear Power Corp. 84/08/23 | 3pp 24x Fiche 50-271,84/08/23,8408300488
- DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1 F Security, medical, \*mergoncy & firs protection plans
- 8408030236 Ack receipt of 840608 ltr informing NRC of steps taken to correct violations novey ... ——
  50-311/84-10
  BELLAMY,R R Division of Engineering & Technical Programs
  B4/07/18 UDERITZ,R A Public Service Electric & Gas Co of N.
  Jersey 2pp 25917 192 24X Fiche 50-272,84/07/18,8408030236 correct violations noted in IE Insp Repts 50-272/84-10 &
- --8408030247 Responds to NRC 840504 ltr re violations noted in IE Insp Repts 50-272/84-10 & 50-311/84-10 Corrective actions revised emergency plan brochure distributed in Feb 1984 & emergency response training program undergoing review & evaluation LIDEN.E A Public Service Electric & Gas Co of New Jersey 84/06/08 HARTIN.T T Region 1, Office of Director Bpp 25917 194 24X Fiche 50-272,84/07/18,8408030236
- B408070065 Forwards corrected page to B40612 confirmatory order, confirming Dec 1986 schedule for implementation of Suppl 1 to NUREO-0737 & Generic Ltr 82-33 re completion of structural mods to technical support ctr W/o encl VAROA, B A Operating Reactors Branch 1 84/07/26 UDERITZ, R Public Service Electric & Gas Co of New Jersey 3pp 25755; 24X Fiche 50-272,84/07/26,8408070045 UDERITZ, R A

- 8408100093 Advises that 840106 Rev 8 to Amend 3 to physical security plan & contingency plan consistent w/provisions of 1000FRS 34(p) & acceptable MARTIN,T T Division of Engineering & Technical Programs 84/08/02 UBERITZ,R A Public Service Electric & Gas Co of New Jersey 3pp 25991 001 24x Fichs 50-272.84/08/02.8408100093
- 8408150223 Forwards responses to 840504 ltr re INEL rept on util conformance to Reg Quide 1 97 requirements for emergency response capability & Suppl 1 to NUMEG-0737 Changes to 830921 implementation plan listed LIDEN.E A Public Service Electric & Gas Co. of New Jersey 84/08/09 VARGA: SA Deprating Reactors Branch 1 9pp 26066 081 24X Fiche 30-272.84/08/09.8408150223
- B40B21040B Informs that FEMA does not intend to conduct full-scale evaluation of Hope Creek 1985 evercise Since Salem Unit 1 QL issued prior to 820713, full participation in 1985 not required by NRC or FEMA rules
  KRIMM.R W Federal Emergency Management Agency B4/0B/13
  JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 26177 296 24x Fiche 50-000, 84/08/13, 8408210408
- 8408220438 Notification of 840906 meeting w/otil in Bethesda, MD to discuss add1 App R exemptions
  FISCHER, D C Operating Reactors Branch 1 84/08/16 VARQA, S A
  Operating Reactors Branch 1 2pp 26201 362 24X
  Fiche 50-272,84/08/16.8408220428

### H General correspondence

- 8408230056 Responds to 840727 ltr transmitting EL Benavidez 840827 concerns re failure of reactor trip sys of nuclear plants NRC established 10CFR50 62 which requires add1 features be installed at each reactor to assure shutdown if sys fails DIRCKS, V J Office of the Executive Director for Operations 84/08/15 DOMENICI.P V Senate 6pp 26233 275 24X Fichs 50-000.84/08/15,8408230056
- --8408230063 Requests response to encl St. Denavider 840627 Ity re scram sys in nuclear reactors DOMENICI,P V Senate 84/07/27 KAPMERER,C C NRC - No Detailed Affiliation Given 8pp 26233 280 24% Fichs 50-000.84/08/15,
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8408020100 Forwards Rev 3 to updated FBAR for Salem Generating Station, volue forwards key 3 to updated FBAR for Salem Generating Station, Units 1 & 2 Changes made per 10CFR50 59, but not previously submitted to NRC, identified in monthly operating repts LIDEN.E A Public Service Electric & Qas Co of New Jersey 84/07/23 VARQA,S A Operating Roactors Branch I App 25910 076 24X Fiche 50-272-84/07/23,8408020100
- --8408020108 Rev 3 to updated FSAR for Salem Generating Station. Units i & 2 \* Public Service Electric & Gas Co of New Jersey 84/ 439pp 25910 082 24X Fiche 50-272,84/07/23,8408020100 84/07/22
- P. Operating license stage documents & correspondence
- 8408150245 Forwards rovs to Cycle 2 startup rept & safety evoluation 40B100245 Forwards revs to Cycle 2 startup rept & safety eve of util rod exchange methodology LIDEN.E A Public Service Electric & Gas Co of New Jersel 84/07/30 VARGA B Operating Reactors Dranch I lopp to 24X Fiche 50-272.84/07/30,8408150245
- B408070110 Generic Ltr 84-19 to all licensess of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Ceneric Safety Issues." Svc list encl EISEMHUT, D 0 Division of Licensing 84/08/06 Comsolidated Edison Co of New York, Int 18pp 26127 23B 24X Fichs 30-000, 84/08/06, 8408070110
- 8408200343 Forwards drawing of proposed upgraded core exit thermocouple sys showing layout of najor components, per TM1 Item II F 2
  LIBEN, EA Public Service Electric & Gas Co of New Jersey
  84/08/13 VARQA, S A Operating Reactors Branch 1 4pp 26131 081
  24X Fiche 50-272,84/08/13,8408200343
- 8408210994 Requests listed addl info re environ qualification of electrical equipment important to safety & remaining outstanding justifications for continued operation Addl info requested by 840827 VARGA,8 A Derating Reactors Branch ( 84/08/13 UDERITZ,R A Public Service Electric & Gas Co of New Jersey 2pp 26195 259 24X Fiche 50-272,84/08/13,8408210554

- 8408210335 Submits addl info to support 840621 request for relief from Articles IWB 5222 & IWC 5200 of ASME Boile: & Pressure Vessel Code Section XI Relief required because no viable means of heating certain components exists
  LIDEN.E A Public Service Electric <sup>7</sup> Oas Co of New Jersey
  84/08/15 VARGA.S A Operating Reactors Branch 1 2pp 26179 340
  24% Fiche 30-272,84/08/15,8+08210335
- 8408240317 Forwards suppl to 830422 response to Generic Ltr 83-10D re plan for resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps" LIDEN,E A Public Service Electric & Gas Co of New Jersey 84/08/15 VARCA: S A Operating Reactors Branch I 5pp 26228 224 24X Fiche 30-272,84/08/15,8408240117
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for CLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions SVc list encl EISENHUT, D C Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 50-000.84/08/20,8408200275
- B40B280330 Requests remittance of additee for review of 790209 & B10810 applications to arend Licenses DPR-70 & DPR-75 HILLER.W O License Fee Management Branch B4/08/20 UDERITZ. Public Service Electric & Gas Co of New Jersey 2pp 26294 OI 24X Fiche 50-272.04/08/20.8408280330 UDERITZIR A
- Q Inspection reports, IE Bulletins & correspondence
- 8408030259 Forwards IE Insp Repts 50-272/84-21 & 50-311/84-21 on B40529-0601 No violations noted MARTIN,T T Division of Engineering & Technical Programs B4/07/11 UDERITZ,R A Public Service Electric & Gas Co of New Jersey 2pp 25917 244 24X Fiche 50-272.84/07/11.8408030259
- --8408030267 IE Insp Repts 50-272/84-21 & 50-311/84-21 on 840529-0601 No violations noted Major areas inspected radiation protection program including ALARA implementation, external exposure control & surveillance & posting DRAGOUN, T., SHANBAKY, M. Region 1, Office of Director 84/07/09 Spp 25917 244 24x Fiche 50-272.84/07/11.8408030259
- 8408030236 Ack receipt of 840608 itr informing NRC of steps taken to correct violations noted in 1E Insp Repts 30-272/84-10 & 50-31/84-10
  BELLAMY.R R Division of Engineering & Technical Programs 84/07/18 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 2pp 25917 192 24% Fiche 50-272, 84/07/18, 8408030236 BELLANY... 84/07/18 UDI
- --8408030247 Responds to NRC 840504 ltr re violations noted in IE Insp Repts 30-272/84-10 & 50-311/84-10 Corrective actions revised emergency plan brochure distributed in Feb 1984 & emergency response training program undergoing review & evaluation LIDCN.E A Public Service Electric & Gas Co of New Jersey 84/04/08 MATIN.T T Region 1. Office of Director Bpp 25917 194 24X Fiche 50-272,84/07/18,8408030236
- 8408150631 Forwards IE Insp Rept 50-2/2/84-22 pn 840530-0608 No
  - violations noted

    MARTIN T T Division of Engineering & Technical Programs 84/(
    UDERITY, A Public Bervice Electric & Gas Co of New Jersey
    26079 056 24X Fiche 50-272,84/07/24.8408150631 84/07/24
- --8408150634 IE Insp Rept 50-272/84-22 on 840530-0608 No violations noted Major areas inspected licensee action on previous insp findings, inservice insp program & related activities, including observation of work in progress of NDE data MCBREARTY, R A. DURR, J P Region I. Office of Director 84/07, 7pp 26079 058 24% Fiche 50-272.84/07/24,8408150631 84/07/09
- 8408190366 Forwards IE Insp Repts 50-872/84-23 & 50-311/84-23 on 840609-0706 & notice of violation Both aspects of violation, including failure to include mechanical snubbers in formal snubber surveillance programs should be addressed STAROBIECKI.R Division of Project & Resident Programs 84/07 UDERITZ.R A Public Service Electric & Oas Co of New Jersey 26075 166 24X Fiche 50-272,84/07/25,8408150366
- --8408190368 Notice of violation from insp on 840609-0706 \* Region 1, Office of Director 84/07/25 lp 260 Fiche 50-272,84/07/28,8408150366 26075 168
- ~-84081503/0 IE Inup Reptu 50-272/84-23 & 50-311/84-23 on 840609-0706 Violation noted failure to establish procedure to perform functional testing of safety-related equipment & mechanical snubbers LINVILLE, J C , SUMMERS, R J , QRAY, E H Region 1, Office of Birector 84/07/23 lipp 26075 169 24X Fiche 50~272,84/07/25, 8408150366

- 8407250229 IE Info Notice 84-57. Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants "Svc list encl JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Int 119pp 25865 047 24% Fiche 50-000.84/07/27. 8407250229
- 8408030027 Forwards 1E Mgt Meeting Repts 50-272/84-30 & 50-311/84-29 on 840719
  STAROSIECKI, R Division of Project & Resident Programs 84/07/30
  UDFRITZ, R Public Service Electric & Gas Co of New Jersey 2pp 25907 077 24x Fiche 50-272,84/07/30,8408030027
- --8408030031 IE Mgt Meeting Repts 50-272/84-30 % 50-311/84-29 on 640719
  Major areas discussed responsiveness of action plan for
  inprovement of nuclear dept operations, submitted to NRC in
  Aug 1983, to recent insp findings
  LINVILLE, J C , NDRRHOLM, L J Region I, Office of Director
  84/07/24 3pp 25907 079 24x Fiche 50-272,84/07/30.8408030027
- 8408200043 Forwards IE Insp Repts 50-272/84-24 & 50-311/84-24 on 840529 No violations noted MARTIN, T T Division of Engineering & Technical Programs 84/07/30 UDERTIZ, R A Public Service Electric & Gas Co of New Jersey 2pp 26140 210 24X Fiche 50-272,84/07/30,8408200043
- --8408200052 IE Insp Repts 50-272/84-24 t 50-311/84-24 on 840529 No violations noted Mojor areas inspected circumstances surrounding transportation accident near Rock Springs, MY, including shipping documentation, waste packaging & shipment EVERETT, R J , HALL, R E Region 1, Office of Director 84/06/18 3pp 26140 212 24X Fichs 50-272,84/07/30,8408200043
- 8408070232 Forwards IE Mgt Meeting Repts 50-272/84-30 & 50-311/84-27 on 840719 STAROSTECKI, R Division of Project & Resident Programs 84/08/02 UDERITZ. R Public Service Electric & Qas Co of New Jersey 2pp 25948 233 24X Fiche 50-272,84/08/02,8408070232
- ~-B408070237 IE Mgt Meeting Repts 50-272/84-30 % 50-311/84-29 on 840719 Major areas discussed status of action plan for improvement of nuclear dept operations, including responsiveness to insp findings LINVILLE.J.C., NORRHOLM,L.J. Region 1, Office of Director B4/07/26 68pp 25948 235 24X Fiche 50-272,84/08/02.8408070232
- B40B010333 IE Infq Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 85pp. 26048 001 24X Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JURDAN,E L Division of Emergency Proparedness & Engineering Response (Post 83010") 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fiche 50-000.04/08/08.8408070120
- 8408070376 IE info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Toletherapy Treatments" Bvc
  list encl
  QRACE, J. N. Division of QA. Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Int
  128pp 26130 001 24% Fiche 50-000.84/08/10,8408070376
- 8408100009 IE Info Notice 84-63. "Defective RHR Replacement Piping "
  Svc list encl
  JORDANN E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24% Fiche 50-000.84/08/13.8408100009
- 8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000.84/08/15,8408100038
- P408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York Inc 118pp 26198 001 24X Fiche 50-000.84/08/16.8408100021

- 840B100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN,C L. Division of Emergency Preparedness & Engineering Response (Post B20103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 001 24X Fiche 50-000.84/08/17,8408100055
- 8408140208 IE Info Notice 84-67. "Recent Snubber Inservice Testing W/ High Failure Rates " Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc. (22pp. 26276-122 24X Fiche 50-000.84/08/17.8408140208
- B40B210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000.84/08/21.8408210142
- 8408310131 Responds to 830106 ltr.840131 telcon & 840626 meeting reviolation in Insp. Repts 90-272/83-29 & 50-311/83-31
  Violation will be withdrawn t concern will be classified as open item
  MARTIN.T T Division of Engineering & Technical Programs 84/08//
  UDERITZ.R A Public Service Electric & Oas Co of New Jersey 2, 26322 260 24x Fiche 50-278,84/08/21,8406310131
- R Periodic operating reports & related correspondence
- 8408160142 Forwards Nuclear Oversight Committee quarterly rept 4td 840731 LIDEN.E A Public Service Electric & Gas Co of New Jersey 84/08/03 VARGA, S Operating Reactors Branch 1 6pp 26108 075 24X Fiche 50-272,84/08/03,8408160142
- B Reportable occurrences, LERs & related correspondence
- 8408160276 LER 84-018-00 on 840713 inadvertent safety injection signal occurred due to personnel error Caused by failure to follow procedure Technicians counseled about responsibilities W/ 840810 ltr RUPP, J L , ZUPKO, J M Public Service Electric & Gas Co of New Jersey 84/08/10 5pp 26106 167 24X Fiche 50-272,84/08/10,8408160276
- 8408230501 LER 84-017-00 on 840716.insp revealed metal filings in charging pump casings Filings may have caused 840713 selzure of charging pump 12 & selzure of redundant centrifugal charging pump Investigation continuing W/840816 ltr RUPP.J L, ZUPKO,J W Public Service Ejectric & Gas Ca of New Jersey 84/08/16 5pp 26212 259 24% Fiche 50-272,84/08/16,8408230501
- 8408310065 PNS-I-84-017 on 640827, unidentified male telephoned security post at Elevation 100 ft of Unit 1 on internal line & told security guard that bomb planted in containment Bomb search teams deployed No bomb found No explosion occurred DUNLAP. J. KEIMIG.R. JOYNER. J. Region 1. Office of Director 84/08/27 1p 26323 203 24% Fiche 50-272,84/08/27,8408310065
- DOCKET 50-274 U S GEOLOGICAL SURVEY RESEARCH REACTOR
  F Security, medical, emergency & fire protection plans
- 8408200121 Advises of implementation of emergency plan RUSLING, D.H. Interior, Dept. of, Geological Survey 84/08/08 THOMAS, C. G. Standardization & Special Projects Branch 1p 26139 306 24X Fiche 50-274,84/08/08,8408200121
- DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANY, UNIT 1

  D. NRC Draft/Final Environmental Statements, supply & correspondence
- 8408140273 Forwards 69 photos attesting to serious long-range problems of erosion of siltation on property contiguous to facility Requests name of responsible NRC employee to respond to concerns
  BRUND.O E Affiliation Not Assigned B3/07/11 DENTON.H Office of Nuclear Reactor Regulation, Director 38pp 26051 203 24X
  Fichs 30-275.83/07/11.8408140273
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8407310038 Board Notification 84-137 forwards SSERs 24-27 re IDVP matters, piping & supports, allegations status & summary & full power license amend matters, respectively No substantive changes made W/o encls EISENHUT, D o Division of Licensing 84/07/30 PALLADING, ROBERTS, ASSELSTINE Commissioners 3pp 26011 015 24X Fichs 50-275,84/07/30,8407310038

- 8408130002 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS ( / 2 Docket Nos 50-275 & 50-323 (Pacific Gas & Electric Company) # Division of Licensing NURGO-0675 S24 84/07/31 16pp 26038 295 24X Fiche 50-275,84/07/31.8408130002
- G4081600B0 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIAGLO CANYON MUCLEAR POWER PLANT.UNITS 1 AND 2 Docket Nos 50-275 And 50-232 (Pacific Ges And Electric Corpany)

  \* Division of Licensing NUREG-0675 925 84/07/31 122pp
  Available at NRC \*5 50 26124 039 24x Fiche 50-2/5.84/07/31, B4081600B0
- B40B160250 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, URITS 1 AND 2 DOCKET Nos 50-275 And 50-233 (Pacific Cas And Electric Company)

  Division of Licensing NUREG-0675 S27 B4/07/31 31pp Available at NRC \$3 50 26122 235 24x Fiche 50-275, 84/07/31. B40B160250
- 8408220346 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 AND 2

  # Division of Licensing NUREG-0675 826 84/07/31 204pp
  Available at NRC \$6 50 26200 001 24X Fiche 50-275,84/07/31,8408220346
- 8409230379 Forwards SSERs 24-27 (NUREG-0675) Distribution of svc list includes SSERs 25-27 since Board Notification 84-137 issued 83ER 24 M/o encl MNIGHTUN.G W Licensing Branch 3 84/08/10 SCHUYLER, J O Pacific Gas & Electric Co 4pp 26230 334 24X Fiche 50-275,84/08/10.8408230379
- F Security, medical, emergency & fire protection plans
- 8408080453 Forwards public version of revs to Vol III of San Luis Dhispo County emergency response plan std operating procedures SCHUYLER.J O Pacific Gas & Electric Co 84/07/16 MARTIN, J B Region 5. Office of Director 2pp 25976 071 24X Fiche 50-275,84/07/16,8408080453
- --B49B0B04\$& Public version of revs to Vol III of San Luis Obispo County emergency response std operating procedures (SDP), including Section III 01, "SDP Emergency Svcs Director " N/Felton B40B02 release meno BCHUYLER, J O Pacific Oas & Electric Co B4/02/29 434pp 25976 073 24X Fiche 50-275,84/07/16.840B0B0453
- 8408160267 Forwards public version of emergency plan implementing procedures, including EP R-1 re personnel injury or illness (radiological related) &/or overerposure & EP M-1 re employee injury or illness (nonradiological)
  SCHUYLER, J O Pacific Gas & Electric Co 84/07/20 MARTIN, J B Region 5, Office of Director 4pp 26125 239 244
  Fiche 50-275,84/07/20,8408160267
- --8408160273 Public version of emergency plan implementing procedures, including EP R-1 repersonnel injury or illness (radiological related) t/or overexposure W/JM Felton 840808 release mema \* Pacific Cas & Electric Co 84/07/20 138pp 26125 243 24X Fiche 50-275,84/07/20,8408160267
- 840B230953 Forwards public version of updated emergency plan implementing procedures including EP R-1 re personnel injury or illness (radiologically related) //or overexposure & EP Q-4 re personnel accountability // assembly SCHUYLER. J O Pacific Gas & Electric Co 84/08/08 MARTIN. J B Region 5. Office of Director ip 26216 206 24X Fiche 50-275,84/08/08,8408230553
- --8408230558 Public version of updated emergency plan implementing procedures, including EP R-1 re personnel injury or illness (radiologically related) &/or overexposure & EP G-4 re personnel accountability & assembly W/840820 release memo THORNBERRY.R C Pacific Gas & Electric Co 84/08/08 182pp 26916 207 24X Fiche 50-275,84/08/08.8408230553
- B408230300 Forwards RW Krinm B40711 ltr transmitting FFMA interim finding in State of CA energency response plan Plan adequate Areas for improvement identified, including protective action guideline doses KNIGHTON-8 W Licensing Branch 3 B4/08/16 SCRUYLER.J D Pacific Oas & Electric Co 3pp 26236 105 24X Fiche 50-275.84/08/16, 8408230300

- 8408310230 Revised energency plan implementing procedures including EP R-2 for release of airborne radioactive matis EP E1-6 re EARS 9845c controlling stations > EP R8-15 \* 16 re sentry post accident sampling sys W\*840827 itr SCHUYLER.J O Pacific Gas > Electric Co 84/08/2/ MARTIN.J B Rogion 5. Office of Director 363pp 26321 001 21% Fiche 50-275.84/08/27 8408310230
- G Adjudicatory correspondence
- 8408010.35 Forwards afridavit of JL Notermott, per 840729 submittal Supporting brief will be sent to Commission on 840730 along w/G'Meill rebuttal affidavit
  DEVINE T Government Accountability Praject DSB 681 84/07/30 FALLADINO,N J. ROBERTS, T. ASSELSTINC, J Commissioners 1p 25854 001 24% Fiche 50-275,84'07/30,8408010235
- --8408010237 Affidavit of JL McDelmott re need for reinsps & systematic retraining of all personnel at facility HCDERMOTT.J L. Government Accountability Project 84/07/30 35pp 25854 002 24% Fiche 50-275,84/07/30.8408010235
- 8408060046 Motion for leave to withdraw confidential Exhibit 10 filed in support of Joint Intervenors 840214 motion to augment or reopen record Declaration in support of motion % Certificate of Svc encl REYROLDS, J. R. Joint Intervenors Diablo Canyon REYROLDS, J. R. Contar for Law in the Public Interest DSB 676 84/07/30 Atomic Safety and Licensing Appeal Panel 9pp 25925 298 24% Fische 50-275,84/07/30.8408060046
- B40806021/ Motion for leave to withdraw confidential exhibit previously filed in support of notion to augment or to reopen record Declaration encl Oranted on 840731
  REYNOLDS, J. R. Joint Intervenors Diablo Canyon REYNOLDS, J. R. Center for Law in the Public Interest D58 708 84/07/30 Atomic Safety and Licensing Appeal Panel App 25927 015 24X
  Firm 50-275,84/07/30,8408060217
- 8408070297 Motion for leave to withdraw confidential exhibit previously filed in support of 840214 motion to augment of it in alternative, to reopen record Declaration \* Certificate of Svc enci REYNOLDS, IR Joint Intervenors Diable Canyon DS8 809 84707730 About Safety and Licensing Appeal Panel 9pp 25947 297 24X Fiche 50-275,84707730,8408070297
- 8408020152 Forwards suppl supporting T O'Neill 840/P7 petition under 10CFR2 206 on behalf of J HcDermott T D'Neill Also expands original request for retraining DEVINL, T Government Accountability Project D58 701 84/07/31 PALLOJHO,N J Commissions 327pp P5884 139 24x Fiche 50-2/5.84/07/31.8408020152
- 8408020219 Order requiring Joint Intervenors to file reply addressing Jurisdictional question in 840716 motion to reopen record on setumic 155085 Served on 840801 SHOEMAKER.C. J. Atomic Safety and Licensing Appeal Panel DSB 716-84/08/01 Junt Intervenors Diable Canyon ip 25878-009 24X Fichs 50~275.84/08/01,8406020219
- 840B020922 Answer opposing Joint Intervenors 840725 application for stay re effectiveness of ASLB 820B31 Initial Decision LBP-84-70 % of issuance of full power IL CHANDLER L J Hearing Branch 2 D98 740 D4708701 Commissioners Lipp 27897 279 24% Fiche 50-275.04708701, BADDROWNER
- ---8408020227 Answer opposing Joint Intervenors 840717 petition for review of ALAB-775 Petition fails to establish existence of inpulsant issue of fact, law or policy warranting (namission review CHANDLER.L J. Hoaring Bronch 2 84/08/01 Commissioners 10pp 20877 270 24X Fiche 50-275,84/08/01.8408020222
- --8408020231 Answer opposing Joint Intervenors 840717 petition for review of ALAB-7/6 Petition foils to establish existence of important question of fact law or policy re ALAB-776 CHANDLER.L J Hearing Branch P 84/08/01 Commissioners 23pp 25897 300 24x Fiche 50-2/5,84/08/01.8408020222
- ---8408020233 Answer opposing Joint Intervenors 840716 motion to reopen rotal on seismir issues Motion fails to satisfy stds for reopening record Certificate of Svc encl CHANDLER.L. J. Hearing Branch 2 84/08/01 Atomic Safety and Licensing Appeal Panel 41pp 25897 323 248 Fiche 50-275,84/08/01.8408020222

. ......

- --8408020233 Answer opposing Joint Intervenors 840716 motion to reopen record on seismic issues Motion fails to satisfy sids for reopening record Certificate of Svc encl CHANDLER.L.J. Hearing Branch 2 84/08/01 Atomic Safety and Licensing Board Panel 41pp 25977-323 24 Fiche 50 275.84/08/01.8408020222
- 8408030154 Underscores need for prompt & favorable action on Northern California Power Agency 811204 petition under 10CFR2 206 to enforce & modify license conditions, based on recent evidence that util continues to violate license conditions MCDIARMID.R C Spiegel & McDiarmid 84/08/01 DENTON.H R Office of Nuclear Reactor Regulation. Director 592pp 25914 075 24X Fiche 50-2/5.84/08/01.8408030154
- 8408020197 Advises that time for Commission to review ALAB-756 expired Commission declined review Decision became final agency action on 840727 Served on 840802 CHILK.S J Office of the Secretary of the Commission DSB 717 84/08/02 REYNOLDS, JR. HAVIAN, E. PHILLIPS, J Center for Law in the Public Interest 1p 25878 001 24X Fiche 50-275,84/08/02,8408020197
- 8408020206 Advises that time for Commission to review ALAB-756 expired Commission declined review Decision became final agency action on 940726 Served on 840802 CHILK, S. J. Office of the Secretary of the Commission DSB 718 84/08/02 STRUMWASSER, M. California, State of 1p 25898 007 24X Fiche 50-275,84/08/02,8408020206
- B408070265 Order extending time until 840810 for Commission to act to review Director's Decision DD-84-8 Served on 840806 CHILK, B. J. Office of the Secretary of the Commission DS\$ 756840903 Commissioners ip 25949 239 24X Fiche 50-275,84/08/03,8408070265
- 8408070351 Order extending time until 840830 for Commission to act to review ACAB-776 Served on 840805 CHILK,S J. Office of the Secretary of the Commission DSB 755 84708703 Commissioners to 25945 177 24X Fiche 50-275.84708703.8408070361
- 8408070467 Order extending time until 840810 for Commission to act to review ALAB-763 Served on 840804 CHILK, 5 J Office of the Secretary of the Commission DSB 752 84/08/03 Commissioners 19 25940 341 24X Fiche 50-275,84/08/03,8408070467
- 8408090183 Order ALAB-775A denying 840628 motion to reopen record on basis of addl info provided by applicant re use of A307 hardware bolts Allegation does not present new evidence Served on 840808 SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel DSB 848 84/08/08 Joint Intervenors Diablo Canyon 2pp 25972 286 24X Fiche 50-275,84/08/09,8408090183
- 8408130389 Reply supporting ASLAB 840801 order establishing jurisdiction of ABLAB to review Joint Intervenor 840716 motion to reopen record on solemic issues Certificate of Svc encl REYNOLDS, J.R. Jaint Intervenors Diabla Canyon REYNOLDS, J.R. Center for Law in the Public Interest DSB 906 84/08/09 Atomic Safety and Licensing Appeal Panel Spp. 26011 094 24% Fiche 50-275,84/08/09,8408130389
- 8408140464 Reply re jurisdiction of ASLAB to consider 840716 motion to reapen record on seismic issues Motion should be granted Certificate of Svc encl REYNOLDS, J.R. Joint Intervenors Diablo Canyon REYNOLDS, J.R. Center for Law in the Public Interest DSB 017 84/08/09 Atomic Safety and Licensing Appeal Panel 8pp 26061 015 244 Fiche 50-275,84/08/09.8408140464
- 8408140006 Memorandum t Order Ct.I-84-13, determining that full power license may be issued by NRR Order effective on 840817. Commissioner Zech statement & Commissioner Asselstine dissenting views smal Served on 840810. CHILK, 5 J Office of the Secretary of the Commission DSB 940 84/08/10 Office of the Executive Legal Director 25pp 26045 001 24X Fiche 50-275, 84/08/10, 8408140006
- B40B140009 Decision CLI-84-12, initiating rulemaking re effects of seismic events on emergency planning Addl views of Palladino & Bernthal & dissenting view of Asselstine encl Served on B40B10 CHILK, 5 J Office of the Secretary of the Commission DSB 939 B4/08/10 29pp 26044 078 24X Fiche 50-275,84/08/10.840B140009
- 8408140460 Order extending time until 840817 for Commission to act to review ALAB-763 Served on 840814
  CHILK, B. J. Office of the Secretary of the Commission DSB 034
  84/081/0 Commissioners 1p. 26060 352 24X
  Fiche 50-275,84/08/10.8408140460

- 8408140486 Order extending time until 840817 for Commission to act to review Director's Decision pD-84-8 Served on 840814 CHILK.5 J. Office of the Secretary of the Commission DSB 035 84/08/10 Commissioners ip 26060 275 24X Fiche 50-275.84/08/10.8408140486
- B40B160234 Responds to RC McDiarmid petition for enforcement of license conditions to continue moribund enforcement proceeding & interpose Commission in pending contract litigation w/City of Healdsburg, CA HRC involvement unnacessary FALLIN, J F : SANDERSON, S A Pacific Cas & Electric Co 84/08/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 18pp 26092 154 24X Fiche 50-275,84/08/10.8408160234
- 8408140548 Forwards Commissioner Bernthal 840813 revised addl views to CLI-84-12 Served on 840813 CLEMENTS. W L Docketing & Services Branch DSB 009 84/08/13 Office of the Executive Legal Director 4pp 26060 243 24X Fiche 50-275:84/08/13.8408140548
- 8408220251 Order denying petitions for review of ALAB-736 subj to reservation re ASLB rationals for excluding joint intervenor & State of CA contentions concerning util QA program Served on 840820 CHILK.S J Office of the Secretary of the Commission DSE 190 84/08/20 3pp 26191 360 24X fishe 50-275.84/08/20.8408220251
- 8408220323 Order instructing IE to issue reclassified notice of violation re util math false statement by failing to rept Nuclear Svcs Corp 1977 audit of Pullman Power Products CA program Served on 840820 CHILK.S J Office of the Secretary of the Commission DSB 189 84/08/20 Director's Office of Inspection and Enforcement Spp 26194 055 24X Fiche 50-275.84/08/20.8408220323
- 8408240424 Staff requirements memo re affirmation/discussion & vote denying 2 206 relief (SECY-84-203).approving order responding to patitions for review of ALAD-763 (SECY-84-254) & approving order denying LILCO 840719 motion (SECY-84-296) CHILKS J Office of the Secretary of the Commission 84/08/20 Office of the Secretary of the Commission 84/08/20 Fiche 50-000.84/08/20.8408240424
- 8408230202 Forwards summary of 840726 site visit No new info impacting licensing decision identified Served on 840822 ZECHLL W Commissioners DSB 255 84/08/22 PALLADIND, ROBERTS, ASSELSTINE Commissioners Spg 26209 207 24x Fiche 50-275,84/08/22,8408230202
- 840B2B0217 Order extending time until 840913 for Commission to act to review ALAB-776 Served on 840827 CHILK,S J. Office of the Becretary of the Commission DSB 317 84/08/27 Commissioners 19 24275 143 24X Fiche 50-275,84/08/27,8408280217
- 8408310247 Notice of withdrawal of appearance in proceeding Related correspondence
  AXELRAD.II Neuman & Holtzinger DSB 428 84/08/28 Office of the Secretary of the Commission ip 26319 256 24X
  Fiche 50-275.84/08/28.8408310247
- 8408310210 Expresses apposition to util 840820 amend application extending term of license 1 requests hearing per Atomic Energy Act to be held prior to Commission decision on application REYNOLDS, J. R. Center for Law in the Public Interest REYNOLDS, J. R. Joint Intervenors Diablo Canyon DSB 147 84/08/29 PALLADINO, N. ASSELSTING, J. DERNIHAL, F. Commissioners 5pp 24318 047 24% Fiche 50-275.84/08/27,8408310210
- M Antitrust correspondence
- 8408130310 Ack receipt of 840801 ltr to HR Denton re request for enforcement of certain antitrust license conditions Allegations contained in ltr under review VOOLER,B H Hearing Branch 2 DSB 898 84/08/08 McDIARMID.R C Spiegel & McDiarmid 1p 26010 250 24X Fiche 50-275,84/08/08, 8408130310
- 8408280442 Confirms telcon repetition for enforcement of antitrust license conditions Staff awaits RC McDiarmid comments on util 840810 ltr repetition Staff requests wheel provisions of arbitrated settlement agreement re NCPA degree units VOGLER, B.H. Hearing Branch 2 DSD 343 BA/08/22 MCDIARMID, R.C. Spiegel & McDiarmid lp 26280 274 24% Fiche 50~275, 84/08/22, 8408280442

- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8408020242 Forwards comments on ACRS 840523 tour of plant site.in response to 840313 ltr MYSINGER.E D Tennessee Valley Authority 84/08/01 MCKINLEY.J C ACRS - Advisory Committee on Reactor Safeguards 4pp 25898 157 24X Fiche 50-275,84/08/01.8408020242
- P Operating license stage documents & correspondence
- 840B31013B F01A request for positive identification of Mothers for Peace of San Luis Obispo & calculations performed by P&&E re earthquate on Nacimiento fault & one equal to 1906 San Francisco earthquate CALSOYAS, C D Affiliation Not Assigned 84/04/07 NRC No Detailed Affiliation Given 4pp 26352 011 24X Fiche: 30-275, 84/04/07, 840B310138
- 8408310142 Responds to FOIA request for positive identification of Mothers for Peace of San Luis Obispo & calculations performed by PG&E re earthquake Forwards printout of documents in Mothers for Peace Other documents in PDR FELTON.J M Division of Rules and Records 84/06/01 CALSOYAS, C D Affiliation Not Assigned ip 26352 015 24X Fiche 50-275,84/06/01,8408310142
- 8406190149 Forwards add1 info re pipe Support design guides per NRC request as result of recent audits connected w/License Condition 2 C (11) SCHOYLER, J C Pacific Cas & Electric Co B4/06/11 EISENBUT, D C Division of Licensing 2pp 24951 009 24% Fiche 50-275,84/06/11.
- 840B3004B2 Requests exam & test requirements for all presently licensed personnel for Unit 1 be waived for Unit 2 & combined OLs for Units 1 & 2 be issued Supporting documentation encl Related correspondence
  8CHUYLER, J 0 , CRANE, P A Pacific Gas & Electric Co DBB 720
  84/07/17 HARTIN, J B , PATE, R J Region 5, Office of Director
  88pp 26329 189 24X Fiche 50-275,84/07/17,840B300482
- 840807053: Informs of completion of staff evaluation of const status & readiness for power ascension testing & full power operation Summaries of reviews & assessments which contributed to conclusion of readiness encl
  BISHOP.T W Region 5. Office of Director 84/07/20 EISENHUT.D O Division of Licensing 2pp 25953 039 24% Fiche 50-275.84/07/20. B408070531
- --8408070532 informs of results of 840404 meeting re status of facility & basis for full power license issuance recommendations BISHOP.T M. Region 5. Office of Director 84704/19 MARTIN.J B Region 5. Office of Director 18pp 25953 041 24X Fiche 50-275,84/07/20.8408070531
- 8408140011 Forwards 840713 rept. "June 20,1984 Banta Maria Offshore Earthquake Ground Motion at Diablo Campon Power Plant"
  Rept contains tabulation of peak accelerations & recorded accelerograms
  8CHUYLER. J O Pacific Gas & Electric Co 84/07/20 EISENHUT. D O Division of Licensing 1p 26044 128 24X Fiche 50-275,84/07/20.8408140011
- --8408140012 "June 20,1784 Santa Maria Offshore Earthquake,Oround Motion at Diablo Canyon Pouer Plant " \* TERA Corp 84/07/13 33pp 26044 129 24X Fiche 50-275,84/07/20,8408140011
- 408310032 Forwards Ofc of Inspector & Auditor 840801 rept of investigation re allegations against seven NRC employers as result of T Devine 840412 & OSO3 10CFR2 206 getitions on NRC misleading or matifalse statements to Commission
  MESSENDER: 0 H Office of Inspector & Auditor 84/08/01 PALLADIND, ROBERTS, ASSELSTINE Commissioners 2pp 26347'001 24X
  Fiche 50-275,84/08/01.8408310032
- --B40B310035 Investigation rept on B40B01 Major areas investigated allegations re NRC misleading or matl false statements to Commission during 840317.26 & 27 briefings & in BBER R1 & 22 for Bec 1983 & Mar 1984 respectively BMITH.R M , BONERS.H , MESSENBER.G H Office of Inspector & Auditor B4/08/01 400pp 26347 003 24% Fiche 50-275, 84/08/01, 8608310030
- 8408070110 Generic Ltr 84-19 to all licensess of operating reactors, applicants for OLS & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Generic Bafety Issues " Svc list encl EISENHUT.D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 R3B 24X Fiche: 80-000, 84/08/06.8408070110

- 840B130003 Requests exemption from IOCFR50.App G requirement for revs to curves, per review of pressure-temp limits for reactor vessel Westinghouse finite element stress analysis showed heatup & cool down curves not impacted by App G amond SCHUVLER.J O Pacific Cas & Electric Co 84/08/08 KNICHTON.Q W Licensing Branch 3 2pp 26010 047 24X Fiche 50-275.84/08/08, 8408130003
- B408130188 Forwards proposed changes in post-fuel loading initial test program to test scope clarification & conducting existing tests at add (lower) power plateaus Review & approval required by B40828 SCHUYLER.J O Pacific Oas & Electric Co 84/08/08 KNIGHTON.O W Licensing Branch 3 3pp 26008 288 24% Fiche 50-275,84/08/08,8408130188
- 8408210639 Forwards SLO-2 work request & work authorization mistakenly omitted from 840801 ltr PETERS, R J Pacific Gas & Electric Co 84/08/08 MITCHELL-WILSON California. State of 2pp 24184 351 24X Fiche 50-275,84/08/08,
- 8408210406 Requests approval for removal of RHR suction valve automatic closure interlock Upon approval.ut>1 will install alarms & restore power to RHR suction valve operators during periods of RHR sys operation while aligned to RCS SCHUYLER.J D Pacific Cas & Electric Co 84/08/15 KNIGHTON.9 W Licensing Branch 3 2pp 26180 336 24% Fiche 50-275.84/08/15, 8408210406
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for DLs re-scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
  EISENHUT,D 6 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276-244 24X
  Fiche 50-000,04/08/20,8408200275
- 840823000B Furwards application for amend to License DPR-76, extending termination date of license from 3 yrs from date of issuance to 4 yrs from date of issuance fee encl

  9CHUYLER, J D Pacific Cas & Electric Co 84/08/20 DENTON, H R

  Office of Nuclear Reactor Regulation, Director 1p 26209 155 24X

  Fichs 50-275.84/08/20,840823000B
- --8408230012 Application to amend License DPR-76, extending termination date of license from 3 yrs from date of issuance to 4 yrs from date of issuance to 4 yrs from date of issuance 260404267. Decision of the property of the second second
- 0 Inspection reports: IE Bulletins & correspondence
- 8407280029 IE Info Notice 84-97. "Operating Experience on Moisture Intrusion in Bafety-Related Electrical Equipment at Commercial Power Plants "Svc list end JDRDAN,C L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York: Inc. 119pp 25865-047 24X Fishe 50-000.84/07/27.8407850229
- 8408080491 Forwards IE Insp Repts 50-275/84-13 & 50-323/84-05 on 840430-0504 & notice of violation BISHOP, T W Region 5. Office of Director 84/07/27 SCHUYLER, J D Pacific Oas & Electric Co 2pp 25974 244 24X Fiche 50-275,84/07/27,8408080491
- --8408080901 Notice of violation from insp on 040430-0904 YOUNG, T Region 5, Office of Director 84/07/27 3pp 23974 246 24X Fiche 50-275.84/07/27,8408080491
- --8408080513 IC Insp Repts 50~275/B4~13 & 50~323/B4~05 an 840430~0504 Violation noted failure to follow approved QC procedures for safety-related pipe & electrical raceway supports DURDOIN,J F. YOUNG,T Region 5, Office of Director 84/07/11 App 25974 247 24X Fichs 50~275,84/07/27,8408080491
- --840B000515 "Technical Assistance for Insp of Diabla Canyon IDVP."
  progress rept for Feb 1984
  MADE.W G . CUMMINOS.O E Lawrence Livermore National Laboratory
  FIN N-8952 B470374 MORRILLE J Region 5. Office of Director
  Opp 25974 255 24% Fiche 50-275.04/07/27.8408080491
- --8408080317 "Technical Assistance for Insp of Diable Canyon IDVP," progress rept for Mar 1984 HADE.W O. CUMMINGS.G C. Lawrence Livermore National Laboratory FIN 8-8352 84/04/11 MORRILLE J. Region 5. Office of Director Gpp 25774 261 24% Fiche 50-275.84/07/27.8408080491

- --6408080521 "Technical Assistance for Insp of Diablo Canyon IDVP,"
  progress Lept for Apr 1984

  MADE.W O CUMMINGS.G E Lawrence Livermore National Laboratory
  FIN B-8552 84/05/14 MORRILL.P J Region 5. Office of Director
  6pp 25974 269 24% Fiche 50-275,84/07/27,8408080491
- 8407310035 Board Notification 84-138 forwards Investigation/Insp Rept 50-275/84-08 Subj matter of rept addressed in SSERs 25 & 26 EISEMHUT.D C Division of Licensing 84/07/30 PALLADINO, ROBERTS, ASSELSTINE Commissioners 2pp 25895 106 24X Fiche 50-275,84/07/30.8407310035
- --8408020131 Forwards Investigation/Insp Rept 50-279/84-08, concluding assignment under NRR
  YIN.1 T Region 3. Office of Director 84/07/23 VOLLMER, R H
  Division of Engineering 1p 25885 108 24X
  Fiche 50-279.84/07/30,8407310035
- --8408020134 Investigation/Insp Rept 50-275/84-08 YIN, I T Region 3. Office of Director 84/07/23 159pp 25885 109 24% Fiche 50-275,84/07/30,8407310035
- 8408130291 Responds to NRC 840628 ltr re violations noted in IE Insp Rept 50-275/84-10 Corrective actions Administrative Procedure (NPAP) C-451 revised training completed & existing jumpers backfitted SCHVYLER.J D Pacific Gas & Electric Co 84/07/30 MARTIN.J B Region 5. Office of Director 4pp 26008 345 24X Fiche 50-275.84/07/30.8408130291
- 8408070324 Ack receipt of 840618 ltr informing NRC of steps taken to correct violations noted in [E Insp Repts 50-275/83-37 & 50-323/83-25 BISHOP.T W Region 5. Office of Director 84/08/01 SCHUYLER, J O Pacific Gas & Electric Co ip 25943 130 24X Fiche 50-275.84708/01.8408070324
- --B408070327 Responds to NRC 840227 ltr re violations noted in IE Insp Repts 50-275/83-37 & 50-323/83-25 Corrective actions reinsp program implemented for welds originally accepted by unqualified inspectors SCHUYLER, J O Pacific Gas & Electric Co B4/06/18 MARTIN, J B Region 5. Office of Director Bpp 25945 i31 24X Fiche 50-275, 84/08/01, 8408070324
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York: Inc 85pp 24048 001 24X Fiche 50-000.84/08/04.8408010333
- B408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement." Svc list encl UORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06. Consolidated Edison Co. of New York, Inc. 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000.84/08/08.8408070120
- 8408130431 Ack receipt of \$50,000 payment of 840517 civil penalty Corrective actions will be examined during future insp AXELRAD, J A Enforcement Staff 84/08/08 MANEATIS, 6 A Pacific Gas & Electric Co ip 26058 358 24% Fiche 50-275,84/08/08,8408130431
- 8408220067 Informs of review of 51 LERs for Jan 1983 June 1984 in support of ongoing SALP review Review concentrated on completeness, accuracy & consistency of info No major deficiencies identified Summany of criteria & findings encl SEYFRIT, K V Reactor Operations Analysis Branch 84/08/09 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 3pp 26193 248 24X Fiche 50-275, 84/08/09, 8408220067
- 8408300140 Forwards Insp Repts 50-275/84-25 & 50-323/84-17 on 840709-13 No violations noted BISHOP, T W Division of Resident, Reactor Project & Engineering Progrems 84/08/09 SCHUYLER, J O Pacific Gas & Electric Co 1926307
- --8408300149 Insp Repts 50-275/84-29 & 50-323/84-17 on 840709-13 No violations or deviations noted Major areas inspected allegations re NRC assessment of Pullman Power audit program during Aug 1971 Dec 1973 HAGNER, W. J. KIRBCH, D. F. Region 5, Office of Director 84/08/08pp 26307 325 24X Fiche 30-275,84/08/09,8408300140

- 8400070376 IE Info Notice 84-42. 'Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl GRACE.J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York. Inc 125pp 26130 001 244 Fiche 30-000.84/08/10.8408070374
- 8408100007 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN, E. L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co. of New
  York, Inc. 119pp 26197 218 24% Fiche 50-000,84/08/13,8408100007
- 840B200313 Ack receipt of 840730 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-275/84-10
  BISHOP, T W Region 5. Office of Director 84/08/13 SCHUYLER, J D Pacific Gas & Electric Co. 1p. 26133 012 24X
  Fiche 50-275,84/08/13.8408200313
- --B40B20031B Responds to NRC 84062B ltr re violations noted in IE Insp Rept 50-275/84-10 Corrective actions Procedure C-461, "Mechanical Bypass, Jumper & Lifted Circuit Log." revised to include jumpers in clearance package SCHUYLER, J. O. Pacific Gas & Electric Co. 84/07/30 MARTIN, J. B Region 5. Office of Director 4pp 26133 013 24X Fiche 50-275,84/08/13,8408200313
- B40B100021 IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc List and JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consulidated Edison Co. of New York. Inc. 118pp 26198 001 24% Fiche 50-000:84/08/16.8408100021
- 8408100095 IE Info Notice 84-66, "Undetected Unavailability of Yurbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York Inc 120pp 26276 001 24X Fiche 50-000/84/08/17,8408100055
- 840B14020B IE Info Notice 84-67. "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 630103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Bolenoid Valves " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000-84/08/21,8408210142
- R Periodic operating reports & related correspondence
- 8408080491 Forwards IE Insp Repts 50-275/84-13 & 50-323/84-05 on 840430-0504 & notice of violation BISHOP, T W Region 5. Office of Director 84/07/27 SCHUYLER, J D Pacific Oas & Electric Co 2pp 25974 244 24X Fiche 50-275
- --B408080515 "Technical Assistance for Insp of Diablo Canyon IDVP."
  progress rept for Feb 1984

  WADE.W O, CUMMINGS.O E Lewrence Livermore National Laboratory
  FIN B-8552 84/03/14 MORRILL.F J. Region 5. Office of Director
- --8408080517 "Technical Assistance for Insp of Diablo Canyon IDVP," progress rept for Mar 1984 WADE.W G. CUMMIN08.0 E Lawrence Livermore National Laboratory FIN 8-8552 84/04/11 MDRRILL.P J Region 5, Office of Director 8pp 25974 261 24X Fiche 50-275,84/07/27,8408080491
- ~-B408080521 "Technical Assistance for Inap of Diablo Canyon IDVP,"
  progress rept for Apr 1984
  WADE.W D , CUMMINGS O E Lawrence Livermore National Laboratory
  FIN B-8552 84705744 MORRILL.P J Region 5, Office of Director
  App 25974 269 24X Fiche 50-275,84/07/27,8408080491
- 8 Reportable occurrences. LERs & related correspondence
- 8408060013 PNO-V-84-046 on 840728, w/unit in hot standby, inadvertent safety injection actuation occurred Caused by high steam flow signal resulting from surveillance testing in progress.

  JOHNSON.P . MENDONCA.M M Region 5. Office of Director 84/07/30 ip 25933 183 24X Fiche 50-275,84/07/30,8408060013

- 8408070367 LER 84-017-00 on 840629 plant vent iodine & particulate flow rate monitor FIS-24 declared inoperable when monitor failed functional test on 840709, discovered incorrect action statement entered Flow suitch adjusted W/840730 ltr
  KELLY, W J , SHIFFER, J D Pacific Gas & Electric Co 84/06/29 3pp 29744 207 24X Fichs 80-275.84/07/30.8408070369
- 8408310038 LER 84-017-00 on 840629, plant personnel did not comply w/correct Tech Spec action statement for period of nine days Caused by typographical error on surveillance test procedure Related correspondence W/840730 1tr KELLY, W J , SMIFFER, J D Pacific Oas & Electric Co D58 790 84/07/30 3pp 26350 187 24X Fiche 50-275, 84/07/30, 8408310038
- 8408160491 LER 84-018-00 on 840706, portion of ESF (control room ventilation sys) actuated in response to spurious radiation monitor alarm signal Caused by failed detector Detector replaced Sys tested & returned to svc W/840806 ltr SISN.D P. SHIFFER.J D. Pacific Gas & Electric Co. 84/08/06 3pp 26107 312 24x Fiche 50-275.84/08/06.840816049!
- 8408210226 LER 84-019-00 on 840714.control room ventilation sys activated & transferred to pressurization mode Caused by error in Drawing 458828 showing slave relay K605 as closed contact instead of open W/840813 ltr SISK.O P. SHIFFER.J D Pactfic Gas & Electric Co 84/08/13 3pp 24184 009 24X Fiche 50-275.84/08/13.8408210226
- B40B230476 LER 84-021-00 on 840720, reactor protection sys actuated due to coincidence of steam generator 1-3 low level & steam flou/freed flow mismatch Caused by failed valve operator Valve operator replaced W/840B17 ltr SISK,D P. SHIFFER.J D Pacific Gas & Electric Co 84/08/17 3pp 26212 214 24X Fiche 50-275.84/08/17.840B230476
- 8408270112 LER 84-020-00 on 840719, dieset generator 103 automatically started due to undervoltage on Unit 2 bus F Caused by const workers inadvertently jarring relay panel & actuating undervoltage relay W/840820 ltr SISK, D P , SHIFFER, J D Pacific Gas & Electric Co 84/08/20 3pp 26258 202 24X Fiche 50-275,84/08/20,8408270112
- 8408310143 LER 84-022-00 on 840728, safety injection & reactor trip occurred due to londo T average & high steam flow signals Caused by personnel not considering effect of low RCS signal on safety injection actuation logic W/840827 ltr SISK,D P . SHIFFER J D Pacific Gas & Electric Co 84/08/27 Jpp 26322 263 24X Fiche 50-275,84/08/27,8408310143
- T Hearing transcripts on non-antitrust matters
- 840822033B Transcript of 840802 open meeting in Washington, DC re discussion/possible vote on full power GL Pp 1-175 Supporting documentation encl \* Commissioners 84/08/02 222pp 26211 083 24X Fiche 50-275.84/08/02.8408220338
- 8408200A07 Transcript of 840803 Commission meeting in Washington, DC re discussion/possible vote on order concerning earthquakes & emergency planning Pp 1-8 \* Commissioners 84/08/03 12pp 26141 178 24x Fiche 50-275,84/08/03,8408200407
- 8408280020 Transcript of 840816 Commission meeting in Washington, DC re affirmation/discussion & vate Pp 1-7 \* Commissioners 84/08/16 10pp 26294 013 24X Fichs 50-000,84/08/16,8408280020
- U Congressional/Executive Correspondence
- 8408010275 Responds to 840208 ltr re concerns over perceived tendency by staff to assume that margins of safety established by criteria need not be adhered to for sys not pivotal to safety
  DIRCKS:W J Office of the Elecutive Director for Operations
  84/07/20 PANETTA:L House of Rep 9pp 25872 342 24X
  Fiche 50-273.84/07/20.8408010275
- --8408010277 Requests preparation of response to Panetta 840208 ltr on concerns re QA hearing PALLADINO.N J Commissioners 84/06/19 DIRCKS.W J Dffice of the Executive Director for Operations (p 29872 351 24X fithe 50-275,84/07/20,8408010275

- V Operator Examinations
- 840B070479 Discusses telcon between J Tinlin & J Elin re arrangements for administration of written & oral exams for senior reactor operators on 840718-28 License applications should be submitted at least 60 days prior to exam PATE.R J Region 5. Office of Director 84/08/02 SCHUYLER.J O Pacific Gas & Electric Co 4pp 25941 206 24X Fiche 50-275.84/08/02.8408070479
- DOCKET 50-276 GEORGIA TECH RESEARCH REACTOR

  P Operating license stage documents & correspondence
- B408010299 Requests application for amend executed per 10CFR50 30(a)-(c) & info showing all parts of Section 6 1 of Tech Specs being fulfilled before action can be taken on 840524 request for dismantling facilities
  THOMAS.C 0 Standardization & Special Projects Branch 84/07/23 KARAKIA A Georgia Institute of Technology Atlanta, GA 3pp 25872 339 24X Fiche 50-160.84/07/23,8408010259
- DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2
  F Security, medical, emergency & fire protection plans
- 8407160090 Forwards public version of revised emergency plan implementing procedures, including EP-103 re alort response, EP-104 re site emergency response, EP-105 re general emergency response & EP-201 re technical support ctr DALTROFF, S L. Philadelphia Electric Co. 83/08/29 MURLEY, T E Region 1. Office of Director 4pp. 25623-065 24X ficha 50-277,83/08/29,8407160090
- --8407160091 Public version of revised emergency plan implementing procedures including EP-103 re alert response EP-104 re site emergency response & EP-201 re support ctr \* Philadelphia Electric Co 83/09/01 84pp 25623 068 24; Fiche 50-277, B3/08/29, B407160090
- 8408060352 Notification of Significant Licenses Meeting 84-66 on 840731 w/util in King of Prussia.PA to discuss results of recent security insp BAILEY, J. Region 1. Defice of Director 84/07/25 Region 1. Office of Director 2ρρ 25937 346 24X Fiche 50-277.84/07/25. 8408060252
- 8408150409 Forwards IE Safeguards Insp Repts 50-277/84-19 & 50-278/84-10 on 840825-29 & 0711 Violations identified Confirms 840731 enforcement conference in Region I are Insp details withheld (ref 1006782 790 & 73 21) MARTIN.T T Division of Engineering & Technical Programs 84/07/25 DALTROFF.S L Philadelphia Electric Co 2pp 26077 301 24X Fiche 50-277.84/07/25.8408150409
- --8408130424 IE Safeguards Insp Repts 50-277/84-19 & 50-278/84-10 on 840525-29 & 0711 Viblation noted failure to have watchman controlling access & to notify Commission of change of security program Safeguards info deleted (ref 10CFR2 770) BAILEY.R J , SMITH.0 C , DUNLAP.J M Region I. Office of Director 84/07/25 17pp 26077 303 24X Fichs 50-277,84/07/25,8408150409
- 8408230290 Requests discussion of Lancaster County deficiencies & corrective actions by 840831.per review of FEMA final emergency preparedness exercise rept of 831116 joint exercise of state of local plans for TMI-1 MURLEY, T C Region I. Office of Director 84/08/13 DALTROFF. S L. Philadelphia Electric Co 2pp 26213 257 24X Fiche 50-277.84/08/13.8408230290
- 8408210389 Clarifies 830936 ltr re location of alternative control stations, implications of extensive circuit isolation performed at HPCI alternative control stations for alternative safe shutdoun & concept of fire safe relays 80YER, V S Philadelphia Electric Co 84/08/16 EISENHUT, P 6 Division of Licensing 5pp 26180 266 24X Fiche 30-277,84/08/16,8408210389
- P. Operating license stage documents & correspondence
- 8406220100 Requests notification of analyses utilizing methodology not previously approved in NUREG-Odéi. "Mark I Containment Long-Term Program" in determining need for logic changes RIVENNARK, G W Operating Reactors Branch 2 84/06/11 BAUER, E G Philadelphia Electric Co 3pp 25100 343 24X Fiche 50-277,84/06/11.8406220100

- 8408060321 Responds to Generic Ltr 84-09 rc recombiner capability requirements of 10CFR50 44 Facility complies w/technical criteria established in Generic Ltr 84-09 Recombiner capability not required DALTROFF. S. L. Philadelphia Electric Co. 84/07/31 EJSENHUT, D. G. Division of Licensing Gap. 25936 331 24X Fishe 50-277.84/07/31. B408060321
- B40Bi3036) Folwards B30403 & 0424 correspondence from State of PA.Dept of Environ Resources, changing Dec temp confidence limit in Bpscial Condition 9B of ETS App B.Item 7 4 2 B 2 from 1 5 F to 4 F WILLSEY, W B Philadelphia Electric Co 84/0B/03 DENTON, H R NOC

to 4 F WILLERY, W B Philadelphia Electric Co 84/08/03 DENTON, H R NRC - No Detailed Affiliation Given 3pp 26010 115 24x Ficha 50-277,84/08/03,8408130361

- 8408220527 Forwards Amends 102 & 104 to Licenses DPR-44 & DPR-56, respectively & safety evaluation Amends revise Tech Specs to implement requirements of App I to 10CFR50 & to revise environ manitoring programs

  OEARS, G E Operating Reactors Branch 4 84/08/03 BAUER, E 9
  Philadelphia Electric Co SPP 26210 001 24X
  Fiche 50-277,84/08/03.8408220527
- --8408220530 Amends 102 & 104 to Licenses DPR-44 & DPR-56, respectively, revising Tech Specs to implement requirements of App I to 10CFR50 & revising environ monitoring programs Tech Specs encl
  STDLZ.JF Operating Reactors Branch 4 84/08/03 175pp 26210 006 24X Fiche 50-277.84/08/03.8408220527
- --8408220531 Safety evaluation supporting Amends 102 & 104 to Licenses DPR-44 & DPR-56.respectively \* Office of Nuclear Reactor Regulation, Director 84/08/03 8pp 26210 173 24X Fichs 50-277.84/08/03.8408220527
- --8307010039 "Radiological Effluent Tech Spec Implementation (A-2),
  Peach Bottom Atomic Power Station Units 2 & 3," technical
  evaluation rept
  FERNANDEZ.C Franklin Institute/Franklin Research Center
  NRC-03-81-130 TER-05506-108/109 83/06/29 CONOEL.F. WILLIS.C
  NRC NO Petailed Affiliation Given 32pp 26210 181 24X
  Fiche 50-277,84/08/03.8408220527
- 8408070110 Generic Ltr 84~19 to all licensees of operating reactors, applicants for QLs & holders of CPs re availability of Suppl I to NUREG-0933, "Prioritiation of Generic Safety Issues" Svc list encl EISENHUT. D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000.84/08/06.8408070110
- 8408230077 Forwards dieff Industry Degraded Core Rulemaking Program Technical Rept 23 1, "Securoyah Nuclear Plant Containment Analysis:" for Meeting 3B Rept Inconsistent w/four encl repts previously sent FONTANA, M. H. Technology for Energy Corp. 84/08/07 DENTON, H.R., CABC. E. Office of Nuclear Reactor Regulation, Director HOUSTON, R. NRC No. Detailed Affiliation Given 2pp. 26234 COL. 24% Fiche 50-000,84/08/07,8408230097
- --8408230112 Praft "Evaluation of Containment Bypass & Failure to Isolate Sequences for Industry Degraded Core Rulemaking Program Ref Plants: "technical rept \* Industry Degraded Core Rulemaking Program \* Fauske & Associates, Inc FAI/84-7 DRFT 84/07/31 114pp 26234 231 24X Fiche 50-000,84/09/07,8408230097
- --8408230131 Draft, "Peach Bottom Atomic Power Station Integrated Containment Analysis," technical rept \* Industry Degraded Core Rulemaking Program 84/08/07 75pp 26235 269 24X Fithe 50-000.84/08/07.8408230097
- 8408210387 Clarifies 830916 ltr re location of alternative control stations, implications of extensive circuit isolation performed at HPCI alternative control stations for alternative safe shutdown & concept of fire safe relays BOYCR, V B Philadelphia Electric Co 84/08/16 EIGENHUT, P G Division of Licensing 5pp 26180 266 24% Fiche 50-277,84/08/16.
- 8408230185 Requests extension of final submittal date for response to Generic Ltr 84-15, until 841101 Extension required to allow collection & assessment of diesel testing date & to develop action plan
  COUNEY.M J Philadelphia Electric Co 84/08/16 EISENHUT.D O Division of Licensing 19 26207 301 24X Fiche 50-277,84/08/16.8408230185

- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list enci EISENHUT.D G Division of Licensing 84/08/20 Consolidated Edison Co of New York Inc 17pp 26276 244 24X Fiche 50-000.84/08/20.8408200275
- Q Inspection reports. IE Bulletins & correspondence
- 8408070036 Forwards IE Insp. Repts 50-277/84-14 & 50-278/84-12 on 840807-11 & notice of violation MARTIN, T. T. Division of Engineering & Technical Programs 84/07/18 DALTROFF, S. L. Philadelphia Electric Co. 2pp. 25992 310 24X Fichs 50-277/84/07/18/8408090036
- --8408090039 Notice of violation from insp on 840507-11 \* Region 1, Office of Director 84/07/18 2pp 25992 312 24x Fiche 50-277,84/07/18,8408090036
- --B40B090031 IE Insp Repts 50-277/84-14 & 50-278/84-12 on B40507-11
  Noncompliance noted failure to establish corrective measures
  for conditions adverse to quality re mechancial outdoor
  storage area
  EAPEN, P. K. PRELL, J. A., GUBY, A. T. Region 1, Uffice of Director
  B4/06/26 10pp 25992 314 24X Fiche 50-277.84/07/18.8408090036
- 84080&0352 Notification of Significant Licensee Meeting 84~66 on 84073i w/util in King of Prussia.PA to discuss results of recent security insp
  BAILEY.R J Region 1. Office of Director 84/07/25 Region 1. Office of Director 2pp 25737 346 24X Fiche 50-277.84/07/25. 84080£0352
- 8408150409 Forwards IE Safeguards Insp Repts 50~277/84~19 & 50~278/84~10 on 840625~29 & 0711 Violations identified Confirms 840731 enforcement conference in Region I ofc Insp details withheld (ref 10CFR2 790 & 73 21) MARTIN.T T Division of Engineering & Technical Programs 84/07/25 DALTROFF.S L Philadelphia Electric Co 2pp 26077 301 24X Fiche 50~277.84/07/25.8408150409
- --8408150424 IE Safeguards Insp Repts 50-277/84-19 & 50-278/84-10 on 840625-27 & 0711 Violation noted failure to have watchman controlling access & to notify Commission of change of security program Safeguards (nfo deleted (ref 10CFR2 790) BAILEY.R J , SMITH.0 C , DUNLAP.J M Region 1, Office of Director 84/07/25 17pp 26077 303 24X Fiche 50-277,84/07/25,8408150409
- 8408150233 Forwards IE Insp Regts 50-277/84-20 & 50-278/84-16 on 840608-0715 & notice of violation STARGSTECKI,R Division of Project & Resident Programs 84/07/26 DALTROFF,S L. Philadelphia Electric Co 2pp 26073 332 24X Fiche 50-277,84/07/26.8408150233
- --8408150236 Notice of violation from insp on 840607-0715 \* Region 1. Office or Director 84/07/26 2pp 26073 334 24% Fiche 50-277.84/07/26,8408150233
- --B408150244 IE Imsp Repts 50-277/84-20 & 50-278/84-16 on 840607-0715 Noncompliance noted failure to maintain access to fire extinguisher, up-to-date control drawings & up-to-date procedures in technical support ctr BLOUGH, A R , WILLIAMS, J H , MEYER, G W Region 1, Office of Director 84/07/25 12pp 26073 336 24X Fiche 50-277,84/07/26,8408150233
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 030103) 84/07/27 Consolidated Edison Co of New York: Inc 119pp 25865 047 24X Fiche 50-000.84/07/27.8407250229
- 8408230130 Forwards IE Insp Rept 50~277/84-18 on 840618-21 & notice of violation MARTIN, T T Division of Engineering & Technical Programs 84/08/03 DALTROFF, S L Philadelphia Electric Co 2pp 26214 145 R4X Fiche 50-277,84/08/03,8408230130
- ~~8408230133 Notice of violation from insp on 840618-21 \* Region 1, Office of Director 84/07/23 ip 26214 147 24X Fiche 50-277, 84/08/03, 8408230130
- --8408230134 IE Insp Rept 50-277/84-21 on 840618-18 Violations noted failure to train health physics technicians & provide specific radiological exposure controls on radiation work permit BICEHOUSE. H J . DRAGOUN, T F . 8HANDAKY, M M . Region 1. Office of Director 84/07/23 9pp 26214-148 24x Fiche 30-277.84/08/03.8408230130

- B40B010333 IE info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures ' Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/08/06 Consolidated Edison Co of New York Inc 85pp 26068 001 24X Fiche 50-900.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Evc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/04 Consolidated Edison Co of New York, Inc. 123pp 24067 138 24X Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fiche 50-000.84/08/08,8408070120
- B40B230070 Ack receipt of B4071B payment of \$30,000 for civil penalties noted in NRC 84051B ltm Corrective actions will be examined during future insps

  AXELRAD. JA Enforcement Staff B4/0B/09 BQYER. V Philadelphia Electric Co 1p 26233 271 24X Fiche 50-277,84/0B/09,8408230070
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Suc List encl ORACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24% Fiche 50-000.84/08/10.8408070376
- 840B100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN.8 t. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc. 119pp 26:97 218 24X Fiche 50-000,84/08/13,8408100009
- 8408100638 IE Info Notice 84-64, "BUR HPC! Initiation Seal-In & Indication "Bvc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 30-000,84/08/13,8408100038
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JOROBANE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc. (18pp. 26198-001 24X Fiche 50-000,84/08/16,8408100021
- 8408310004 Supply response to IE Bulletin 83-07. "Apparently Fraudulent Products Sold by Ray Miller Inc " Concerns in bulletin not applicable to facilities CONNEY, M J Philadelphia Electric Co 84/08/16 MURLEY, T E Region in Office of Director 2pp 26323 279 24X Ficha 50-277,84/08/16,8408310004
- B40B100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000.84/08/17.840B100055
- 8408140208 IE Info Notice 84-67, "Recent Enubber Inservice Testing W/ High Failure Rates " Syc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Cansolidated Edison Co of New York, Inc 122pp 26276 122 24% Ficha 50-000.84/08/17.8408140208
- 8408210142 IE Info Notice 84-66, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves" Evo list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc. 115pp 24327 008 24X Fiche 50-000.84/08/21.8408210142
- R Periodic operating reports & related correspondence
- 8408210346 Forwards "Environ Radiation Monitoring Program, 1983" & "Regional Radiological Environ Monitoring Program, 1983" MILLSEY, W B Philadelphia Electric Co 84/08/09 DEYDUNG, R C Director's Office, Office of Inspection and Enforcement ip 26183 001 24X Fiche 50-171,84/08/09,8408210346
- --8408210549 "Environ Radiation Monitoring Program, 1983 "
  \* Chemical Waste Management. Inc 41 83/12/31 1249p
  26185 002 24X Fiche 50-171,84/08/09.8408210546
- --8408210555 "Regional Radiological Environ Monitoring Program, 1783 " \* Teledyne Isotopes 17 83/12/31 127pp 26185 126 24X Fiche 50-171,84/08/09,8408210546

- 5 Reportable occurrences, LERs & related correspondence
- 8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solehold valve plunger Initially reported on 840413 New thread locking devices investigated SHERWOOD, G G General Electric Co 84/04/13 DEYOUNG, R C Director's Dffice, Office of Inspection and Enforcement 3pp 24222 254 24% Fiche 50-000,84/04/13.8408240348
- 8408080535 LER 84-012-00 on 840628, w/unit in cold shutdown for refueling, surveillance testing discovered inoperable horizontal fire damper in cable spreading room Caused by missing spring closure device W/840/27 ltr CLARN, B L , LOQUELR H Philadelphia Electric Co 84/07/27 4pp 25978 306 24% Fiche 50-277.84/07/27.8408080535
- 8408080933 LER 84-010-01 on 840607. w/unit shutdown for refueling & major mod outage, through-well crack discovered in loop A jet pump instrumentation penetration reducer to safe-end weld Caused by 168CC W/840730 ltr CLARK, B L , LOGUE, R H Philadelphia Electric Co 84/07/30 4pj 25775 302 24% Fiche 50-277, 84/07/30,8408080933
- B408130601 LER B4-011-01 on B40608.acety]ene leak occurred during drywell preheat welding Caused by leak where hose crimped to std screw connection Porsonnel evacuated & addl ventilation used to expol gas W/840806 ltr CLARK.B L . LOQUE.R H Philadelphia Electric Co B4/08/06 4pp 26030 336 24X Fische 50-2/7.84/08/06.8408130601
- B40B270107 LER B4-014-00 on B40716 continuous firewatch removed from cable spreading room w/o realizing that firewatch still needed due to out-of-sx. Cardox sys Condition discovered & firewatch reestablished on B40719 W/B40817 ltr CLARK, B L , ULLRICH, W T Philadelphia Electric Co B4/0B/17 4pp 26297 274 24X Fiche 50-2/7.84/0B/17,8408290107
- 8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl OE lacks technical info to adequately evaluate condition

  VILLA: General Electric Co 84/08/21 ROBSI.C E Director's Office, Office of Inspection and Enforcement 3pp 26318 327 24% Fiche 50-000.84/08/21.8408310186
- DOCKET 50-270 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

  F. Becurity, medical, emergency & fire protection plans
- 8407160090 Forwards public version of revised emergency plan implementing procedures including EP-103 re alert response. EP-104 re site emergency response EP-105 re general emergency response & EP-201 re technical support ctr DALTROFF, S L Philadelphia Electric Co B3/08/29 MURLEY, T E Region 1. Office of Director 4pp 25623 065 24X Fiche 50-277.83/08/29.840/160090
- --G407160091 Public version of revised omergency plan implementing procedures, including EP-103 re alert response, EP-104 re site emergency response, EP-105 re general emergency response & EP-201 re support ctr \* Philadelphia Electric Co 63/08/01 84pp 25623 068 24) Fiche 50-277, 83/08/29, 840/160090
- 8408060352 Natification of Significant Licensee Meeting 84-66 on 840731 w/util in King of Prussia.PA to discuss results of recent
  - w/otil in King of Progsia,PA to discuss results of recent security insp BAILEY.R J Region i, Office of Director 84/07/25 Region I, Office of Director 2pp 25937 346 24X Fiche 50-277,84/07/25, 8408050352
- 8408180409 Forwards IE Safeguerds Insp Repts 50-277/84-19 & S0-278/84-10 on 840625-29 & O711 Vibilations identified Confirms 840731 enforcement conference in Region 1 ofc Insp details withheld (ref 100FRZ 790 & 79 21)
  MARTIN,T T Division of Engineering & Technical Programs 84/07/25
  DALTRUFF,S L Philadelphia Electric Co 2pp 26077 301 24X
  Fiche 50-277.84/07/25.8408150409
- --B40B150424 IE Safeguards Insp Repts 50-277/B4-19 & 90-27B/B4-10 on B40625-29 & 0711 Violation noted failure to have watchman controlling access & to notify Commission of change of security program Safeguards info deleted (ref 10CFR2 770) BAILLY, R. J., KEIMIO, R. R. Region 1, Office of Director 84/07/25 17pp 26077 303 24% Fiche 50-277,84/07/25,840B150409

- 8408230290 Requests discussion of Lancaster County deficiencies & corrective actions by 840831, per review of FEMA final emergency preparedness exercise rept of 831116 joint exercise of state of local plans for TMI-1 MURLEY.T E Region 1. Office of Director 84/08/13 DALTROFF,S L Philadelphia Electric Co 2pp 26213 257 24X Fiche 50-277.84/08/13.8408230290
- 8408210389 Clarifies 830916 ltr re location of alternative control stations, implications of extensive circuit isolation performed at HPCl alternative control stations for alternative safe shutdown & control stations for BOYER, V S Philadelphia Electric Co 84/08/16 EIBENHUT, P G Division of Licensing 5pp 26180 266 24X Fiche 50-277, 84/08/16, 8408210389
- P Operating license stage documents & correspondence
- 8406220100 Requests notification of analyses utilizing methodology not previously approved in NUREG-0661. "Mark I Containment Long-Term Program" in determining need for logic changes RIVENBARK, G W Operating Reactors Branch 2 84/06/11 BAUER, E G Philadelphia Electric Co 3pp 25100 343 24X Fiche 50-277.84/06/11.8406220100
- B408060321 Responds to Generic Ltr 84-07 re recombiner capability requirements of iOCFR50 44 Facility complies w/technical criteria established in Generic Ltr 84-09 Recombiner capability not required DALTROFF.5 L Philadelphia Electric Co 84/07/31 EISENHUT.D 9 Division of Licensing 3pp 25926 331 24X Fiche 50-277.84/07/31. 8408060321
- 8408070303 Forwards Rev i to GE Rept MAR 84-27, "Residual Stress Analysis of Peach Bottom,Unit 3 Jet Pump Instrumentation Nozzle Weld Overlay " Rept withheld (ref 10CFR2 790) DALTROFF, S L Philadelphia Electric Co 84/08/03 EISENHUT.D G Division of Licensing 2pp 25947 222 24X Fiche 50-278,84/08/03. 8408070303
- 8408130361 Forwards 830603 & 0426 correspondence from State of PA, Dept of Environ Resources, Changing Dec temp confidence limit in Special Condition 98 of ETS App B, Item 7 4 2 B 2 from 1 5 f to 4 f HILLSEY, W B Philadelphia Electric Co 84/08/03 DENTON, H R NRC No Detailed Affiliation Given 3pp 26010 115 24X Fiche 50-277,84/08/03.8408130361
- B40B220527 Forwards Amends 102 & 104 to Licenses DPR-44 & DPR-54, respectively & safety evaluation Amends revise Tech Specs to implement requirements of App I to 10CFR50 & to revise environ monitoring programs
  GEARS, G E Operating Reactors Branch 4 B4/08/03 BAUER, E G Philadelphia Electric Co 5PP 26210 001 24X
  Fiche 50-277,84/08/03,8408220527
- --8408220330 Amends 102 & 104 to Licenses DPR-44 & DPR-56, respectively, revising Fech Space to implement requirements of App I to 100FR50 & revising environ monitoring programs Tech Space encl
  STOLZ, JF Operating Reactors Branch 4 84/08/03 175pp 26210 006 24% Fiche 50-277,84/08/03,8408200527
- ~-8408220931 Bafety evaluation supporting Amends 102 & 104 to Licenses DPR-44 & DPR-55, respectively \* Office of Nuclear Reactor Regulation, Director 26210 173 24X Fiche, 50-277, 84/08/03, 8408220927
- --8307010037 "Radiologica) Effluent Tech Spec Implementation (A-2),
  Peach Bottom Atomic Power Station Units 2 & 3," technical
  evaluation rept
  FERNANDEZ, C Franklin Institute/Franklin Research Center
  NRC-03-81-130 TER-05006-108/109 83/06/29 CONSEL.F, WILLIB,C
  NRC No Detailed Affiliation Given 32pp 26210 181 24X
  Fichs 50-277,84/08/03,8408220327
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues "Svc list encl EISENNUT.D O Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26127 238 24X Ficha 50-000,84/08/06,8408070110
- 8408210237 Forwards notice of consideration of issuance of amend to License DPR-96 & proposed NSHC determination & apportunity for hearing on 840390 application re increased core flow region rated throughout Cycle 6 Encls in Central Files OEARS, C Operating Reactors Branch 4 84708706 BAVER, E OPhiladelphia Electric Co 2pp 26187 349 24X Fiche 50-278,84708706,8408210237

- 8408230097 Forwards draft Industry Degraded Core Rulemaking Program Technical Rept 23 i. "Sequoyah Nuclear Plant Containment Analysis." for Meeting 3B Rept Inconsistent w/four encl repts previously sunt FONTANA.M H. Technology for Energy Corp. 84/08/07 DENTUN, H.R. Office of Nuclear Reactor Regulation. Director 2pp. 26234 ODI 24X Fiche 50-000.84/08/07.8408230097
- --8408230112 Draft "Evaluation of Containment Bypass & Failure to Isolate Sequences for Industry Degraded Core Rulemaking Program Ref Plants." technical rept \* Industry Degraded Core Rulemaking Program FAI/84-7 DRFT 84/07/31 114pp 26234 231 24X Fiche 30-000.84/08/07, 8408230097
- --8408230131 Draft, "Peach Bottom Atomic Power Station Integrated Containment Analysis," technical rept # Industry Degraded Core Rulemaking Program 84/08/07 75pp 26235 269 24X Fiche 50-000.84/08/07.8408230097
- 8408210389 Clarifies 830916 itr re location of alternative control stations, implications of extensive circuit isolation performed at HPCI alternative control stations for alternative safe shutdoon & concept of fire safe relays BOYER, V S Philadelphia Electric Co 84/08/14 EISENHUT, P G Division of Licensing 5pp 26180 266 24X Fiche 50-277,84/08/14.8408210389
- 8408230185 Requests extension of final submittal date for response to Generic Ltr 84-15 until 841101 Extension required to allow collection & assessment of diesel testing data & to develop action plan

  COONEY.M J Philadelphia Electric Co 84/08/16 EISENHUT.D Q

  Division of Licensing ip 26209 30: 24X Fiche 50-277.84/08/16, 8408230185
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for DLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
  EISENNUT.D 0 Division of Licensing 84/08/20 Consolidated Edison Co of New York Inc 17pp 26276 244 24X
  Fiche, 50-000, 84/08/20, 8408200275
- B408280272 Forwards application for amend to License DPR-56, revising 840530 application re operation w/increased core flows to provide add info re BWR thermal hydraulic stability requested by NRC RRADLEY, E. J. Philadelphia Electric Co. 84/08/24 DENTON, H. R. Office of Nuclear Reactor Regulation, Director Jp. 26274 310 24 Fiche: 50-278:84/08/24,8408280272
- --8408280273 Application for amend to License DPR-36, revising 840530 application re operation w/increased core flows to provide add1 info re DWR thermal hydraulic stability requested by NRC BRADLEY,E J Philadelphia Electric Go 84/08/24 DENTON,H R Office of Nuclear Reactor Regulation, Director ip 26274 311 24% Fiche 50-278,84/08/24,8408280272
- --8408280278 Proposed Tech Specs, allowing operation w/increased core flows
  \* Philadelphia Electric Co 84/08/24 7pp 26274 318 24X
  Fiche 50-278, 84/08/24, 8408280272
- Q Inspection reports: IE Bulletins & correspondence
- B408090036 Forwards IE Insp Repts 50-277/84-14 & 50-278/84-12 on B40507-11 & notice of violation MARTIN,1 T Division of Engineering & Technical Programs B4/07/18 DALTROFF,S L Philadelphia Electric Co 2pp 25992 310. 24X Fiche 50-277.84/07/18.8408090036
- --8408090039 Notice of violation from insp on 840507-11 \* Region 1, Office of Director 84/07/18 2pp 25792 312 24X Fiche 50-277,84/07/18,8408090036
- --8408090051 IE Insp Repts 50-277/84-14 & 50-278/84-12 on 840507-11 Noncompliance noted failure to establish corrective measures for conditions adverse to quality re mechanical outdoor storage area EAPEN.P.K. PRELL.J.A., GODY.A.T. Region 1, Office of Director 84/06/26 10pp 25992 314 24X Fiche 50-277.84/07/18,8408090036
- 8408040352 Notification of Significant Licensee Mesting 84-64 on 840731 w/util in King of Prussia,PA to discuss results of recent security insp BAILEY,R J Region 1. Office of Director 84/07/25 Region 1, Office of Director 2pp 25937 346 24X Fiche 50-277,84/07/25, page 07372

- 8408150409 Forwards IE Safeguards Insp Repts 50-277/84-19 & 50-278/84-10 on 840625-29 & 0711 Violations identified Confirms 840731 enforcement conference in Region 1 ofc Insp details withheld (ref 10CFR2 790 & 73 21)
  MARTIN.T T Division of Engineering & Technical Programs 84/07/25
  DALTROFF; & Philadelphia Electric Co 2pp 26077 301 24x
  Fiche 50-277,84/07/25.8408150409
- --8408150424 [E Safeguards Insp Repts 50-277/84-19 & 50-278/84-10 on B40625-29 & 0711 Violation noted failure to have watchman controlling access & to notify Commission of change of security program Safeguards info deleted (ref 10CFR2 790) BAILEY.R J. SMITH.Q C. DUMLAP.J M. Region 1. Office of Director 84/07/25 | 17pp 26077 303 24X Fiche 50-277.84/07/25, B408150407
- B40B150233 Forwards IE Insp Repts 50-277/84-20 & 50-278/84-16 on B40A08-0715 & notice of violation STAR03FECKI, R Division of Project & Resident Programs B4/07/26 DALTROFF, S L Philadelphia Electric Co 2pp 26073 332 24% Fichs 50-277, 84/07/26, 8408150233
- --8408150236 Notice of Violation from insp on 840607-0715 \* Region 1, Office of Director 84/07/26 2pp 26073 334 24X Fiche 50-277,84/07/26,8408150233
- --B40B150244 IE [nsp Repts 50-277/B4-20 & 50-278/B4-16 on B40607-0715 Norcompliance noted failure to maintain access to fire extinguisher, up-to-date control drawings & up-to-date procedures in technical support ctr
  BLOUGH.AR, WILLIAMS, J. H. MEVER, G. W. Region 1. Defice of Director 84/07/25 12pp 26073 336 24X Fiche 50-277, B4/07/26. 840B150233
- B407250229 IE Info Notice B4-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 1199p 25865-047 24X Fiche 50-000.84/07/27.8407250229
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JORDAN:E 1. Division of Emergency Pregaredness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24% Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/04 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000.84/08/06.8408010337
- B408230070 Ack receipt of 840718 payment of \$30,000 for civil penalties noted in NRC 840618 ltr Corrective actions will be examined during future insps AXECRAD. J A Enforcement Staff 84/08/09 BOYER, V Philadelphia Electric Co ip 26233 271 24X Fiche 50-277.84/08/09.8408230070
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list encl
  GRACE, J N Division of GA. Bafeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc. 125pp 26130 001 24% Fiche 50-000.84/08/10,8408070374
- 8408100007 IE Info Notice 84-63. "Defective RHR Replacement Piping "
  Syc list enc!
  JURDAN E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24% Fiche 50-000.84/08/13.8408100009
- B40BlQ003B IE Info Notice B4-64, "BWR HPCI Initiation Beal-In & Indication " Svc list encl JORDAN,E L Bivision of Emergency Preparedness & Engineering Response (Post B30103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24% Fiche 50-000:84/08/15,840810003B
- 3408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc. [18pp. 26198 001 24% Fiche 50-000,84/08/16,8408100021
- 8408310004 Suppls response to 1E Bulletin 83-07. "Apparently Fraudulent Products Sold by Rey Miller, Inc." Concerns in bulletin not applicable to facilities
  COONEY, M. J. Philadelphia Electric Co. 84/08/16 MURLEY, T.E. Region 1, Office of Director 2pp. 26323 279 24X
  Fishe 50-277.84/08/16.8408310004

- 8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train" Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000.84/08/17,8408100055
- 8408140208 [E Info Notice 84-67, "Recent Shubber Inservice Testing W/High Failure Rates " Svc list ent!
  JORDAN:E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/17 Consolidated Edison Co of New
  York Inc 122pp 26276 122 24X Fiche 50-000.84/08/17.8408140208
- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves" Svc list encl JURDAN,E L. Davision of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc. 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in fWR Refueling Cavity " Svc list encl JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York, Inc. 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- R Periodic operating reports & related correspondence
- 8408210546 Forwards "Environ Radiation Monitoring Program, 1983" & "Regional Radiological Environ Monitoring Program, 1983" WILLSEY, W B Philadelphia Electric Co 84/08/09 DEYDUNG, R C Director's Office Office of Inspection and Enforcement 1p 26185 001 24% Fiche 50-171, 84/08/09, 8408210546
- --8408210349 "Environ Radiation Monitoring Program, 1983 "

  \* Chemical Waste Management, Inc. 41 83/12/31 124pp
  26185 002 24X Fiche 50-171,84/08/09,8408210546
- --8408210555 "Regional Radiological Environ Munitoring Program, 1983 " \* Teledyne Isotopes 19 83/12/31 129pp 26185 126 24X Fiche 50-171, 84/08/09, 8408210546
- S Reportable occurrences, LERs & related correspondence
- 8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated SHERWOOD, O O General Electric Co 84/04/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 24222 236 24X Fiche 50-000,84/04/13,8408240348
- B40B10004B RD MM-3-01 on B40622 & 25 moisture sensors in recirculation sys maisture monitoring sys functioned improperly Cause unknown Drywell sump collection sys monitored hourly until next outage

  \* Philadelphia Ejectric Co 84/07/23 MURLEY, T E Region 1.

  Office of Director 3pp 25990 073 24X Fichs 50-278,84/07/23.
  840B10004B
- B40B2402B3 PMG-I-B4-071 on B40B21, reactor automatically scrammed due to low water level caused by feedwater control sys failure Scram resulted in primary containment isolation sys Group I isolation & tripped recirculation pumps OALLO, R Region 1. Office of Director B4/0B/21 1p 26223 196 24X Fiche 50-27B,84/0B/21,8408240283
- 8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
  VILLAIR. General Electric Co 84/08/21 ROSSI.CE Director's
  Office Office of Inspection and Enforcement 3pp 26318 327 24x
  Fichs 50-000.84/08/21.8408310186
- DOCKET 50-280 SURRY POWER STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- 840B310069 Confirms 840524 visit to Region to discuss access control at facilities LEWIB.R C Region 2, Office of Director 84/05/22 STEWART.W L Virginia Electric & Fower Co ip 26333 342 24X Fiche 50-000,84/05/22,840B310069
- 8408310401 Forwards summary of 840524 meeting re security interface activities Meeting beneficial & provided better understanding between security staffs LEWIS,R C Region 2. Office of Director 84/06/06 STEWART.W L Virginia Electric & Power Co 499 26333 311 24X Fiche 50-000,84/06/06,8408310401

- 8408300433 Forwards Commonueaith of VA response to comments & proposed corrective actions in reply to FEMA ropt of 831001 full-scale emergency wiercise DANCE.H C Region 2. Office of Director 84/06/26 STEWART.W L Virginia Electric & Power Co 1p 26314 308 24X Fiche 50-280.84/06/26.8408300433
- 8408020132 Revised emergency plan W/840727 ltr MILLER, H L . ORADY, W D . STEWART, W L Virginia Electric & Power Co 84/06/28 O REJLLY, J P . Region 2. Office of Director 276pp 25890 109 248 Fichs 50-280.84/06/28,8408020132
- B40B070039 Forwards replacement pages to control room design review program plan Adoption of Westinghouse Owners Group emergency response guidelines as basis for task analysis & verification/validation sections principal changes
  STEWART.W L Virginia Electric & Power Co B4/07/27 DENTON, H R
  Office of Nuclear Reactor Regulation, Director EISENHUT, D G
  Division of Liransing Bpp 25749 281 24X Fiche 50-000, 84/07/27, BARGOROUS
- 8408270443 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in Insp Repts 90~281/84-15 & 50~281/84-15 PANCE.H C Division of Project & Resident Programs 84/07/31 STEWART.W L Virginia Electric & Power Co ip 26257 187 24X Fiche 30~280.84/07/31.8408270443
- --8408270448 Responds to NRC 840620 ltr rg violations noted in Insp Repts 50-280/84-15 % 50-281/84-15 Corrective actions smake & heat detector periodic tests changed to include up to date testing techniques using heat gun test gas STEWART.W L Virginia Electric & Power Co 84/07/20 O'REILLY.J P Region 2. Office of Director 5pp 26257 188 24X Ficho 50-280,84/07/31,840827043
- --8408270452 Forwards Insp Repts 50-280/84-15 & 50-201/84-15 on 840401-0505 & notice of violation DANCE, H C Division of Project & Resident Programs 84/06/20 STEWART, W L Virginia Electric & Power Co 2pp 26257 193 24% Fiche 50-280.84/07/31.8408270443
- --B408270454 Notice of vialation from insp on B40401-0505 \* Region 2, Office of Director 84/06/20 2pp 26257 195 24X Ficho 50-280,84/07/31,8408270443
- --8408270456 Insp Repts 50-280/84-15 & 50-281/84-15 on 840401-0905 Violation noted procedures for testing certain components not adequate & fire protection program implementing procedures not properly followed BURKE.D J. DAVIS.M J. MYERS.D O Region 2. Office of Director 84/06/19 5pp 26257 197 24X Fichs 50-280.84/07/31,8408270443
- 8408310040 Advises that 840412 rev to emergency plan consistent w/provisions of 10CFR50 47(b) & requirements of App E
  DANCE, H C Region 2. Office of Director 84/08/01 STEWART, W L
  Virginia Electric & Power Co 2pp 26334 356 24X
  Fiche 50~280,64/08/01,8408310060
- B40B10007B Revs to rediation emergency plan W/840B03 ltr STEWART.W L. Virginia Electric & Power Co. 84/07/19 O'REILLY, J.F. Region 2. Office of Director . 70pp 25970 2B0 24X Fithe 50-280.84/08/03.8408100098
- 840B300429 Ack receipt of 840703 ltr re emergency exercise scheduled for plant during Sept 1984 Scenario & controller messages will be reviewed when received DANCE, H C Region 2, Office of Director 84/08/08 STEWART, W L Virginia Electric & Power Co lp 26314 330 24X Fiche 50-280,84/08/08,8408300429
- 8408200387 Advises that program plan for conducting detailed control room design review meets intent of Suppl 1 to NUREO-0737 Listed areas should be described in summary rept expected 830830 VAROA.5 A Licensing Branch 1 84/08/10 STEWART.W L Virginia Electric & Power Co 200 26141 215 24X Fiche 50-000.84/08/10.8408200387
- 8408140404 Forwards revised emergency plan implementing procedures, including EPIP-2 03 re repts to offsite agencies. EPIP-3 01 re callout of emergency response personnel & EPIP-5 01 re transportation of contaminated injured personnel W/o encl STEMART. W L Virginia Electric & Power Co 84/08/13 0'REILLY, J P Region 2, Office of Director 2pp 26092 179 24X Fiche 50-280,84/08/13,8408160406

- 8408170222 Revised emergency plan implementing procedures including EPIP-2 03 re repts to offsite agencies EPIP-3 01 re callout of emergency response personnel & EPIP-5 01 re transport of contaminated injured personnel W/840813 itr STEWART. W L Virginia Electric & Power Co 84/08/13 O'REILLY. J P Region 2. Office of Director 12pp 26/18 077 24x Fiche 50-280.84/08/13.8408170222
- P Operating license stage documents & correspondence
- B40B300369 Confirms 840501 telcon w/HC Dance re 840510 mgt meeting in Region II off to discuss organizational structure LEWIS,R C Region 2. Office of Director 84/05/07 BTEWART,W L Virginia Electric & Power Co 1p 26308 230 24V Fiche 50~000,84/05/07.8408300369
- 940801016! Notification of 840727 meeting w/util at site to discuss questions re control of heavy loads (Multi-Plant Action C-15)
  NEIGHBURS D Operating Reactors Branch 1 84/07/20 VARGA, 8 A Operating Reactors Branch 1 2pp 25873 304 24% Fiche 30-280.84/07/20.8408010161
- 8408160039 Advises that upgraded in-core thermocouple sys schedule will be completed by 1986 refueling outage.per 840221 commitment & will meet requirements of NUREG-0737, Item II F 2 STEMART, W L Virginia Electric & Power Co 84/08/01 DENTON, H R Office of Nuclear Reactor Regulation, Director EISEMHUT, D Q Division of Licensing 1p 26092 052 24X Fiche 50-280, 84/08/01, 8408160039
- B40B130595 Notifies that any permanent changes to new fuel container lifting rig will be made per ANSI NI4 6-1978 requirements & NUREG-0612 STEWART. W.L. Virginia Electric & Power Co. 84/08/03 DENTON. H.R. Dffice of Nuclear Reactor Regulation, Director EISENKUT, D.G. Division of Licensing 1p 26031-359 24X Fiche 50-280, 84/08/03, 8400810385
- 8408070110 Generic Ltr B4-19 to all licensees of operating reactors, applicants for OL's & holders of CPs re availability of Suppl 1 to NUREG-0933. "Prioritization of Generic Safety Issues " Svc list enc! EISENHUT.D G Division of Licensing 84/08/04 Consolidated Edison Co of New York, Inc. 18pp 26189 238 24% Fiche 50-000,84/08/06,8408070110
- 8408210132 Forwards Generic Ltr 84-15 response schedule, listing 840928 & 850131 as projected dates Justification for extension of responses included STEWART, W.L. Virginia Electric & Power Co. 84/08/16 DENTON, H.R. Office of Nuclear Reactor Regulation: Director EISENHUT, D. Ø. Division of Licensing 3pp 26181 348 24X Fiche 50-000.84/08/16, 8408210132
- 8408240280 Forwards response to 840606 request for add) info.to complete review of util 831209 request for relief from ASME Section XI re nonregenerative HX integrally weided support One oversize drawing encl Aperture card in PDR STEWART.W L. Virginia Electric & Power Co 84/08/17 DENTON.H R Office of Nuclear Reactor Regulation, Director VARGA.S A Operating Reactors Branch 1 4pp 26/227 227 24X Ficho 50-280.84/08/17.8408240280
- 8408200275 Generic Ltr 84-20 to all licenses of operating reactors & applicants for Ols re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list enc! EISENHUT.D G Division of Licensing 84/08/20 Consolidated Edison Co of New York. Inc 17pp 26276 244 24X Fich 50-000.84/08/20.8408200275
- @ Inspection reports, IE Bulletins & correspondence
- 8408010164 EN-84-049 on 840730 notice of violation & proposed imposition of civil penalties in amount of \$40,000 will be issued to licensee Action involves failure to adequately implement syc life monitoring program for snubbers KLINGLER.0 . AXELRAD.J Director's Office. Office of Inspection and Enforcement 84/07/25 ip. 25055 305 24X Fiche 50-280.84/07/25,8408010164
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Bafety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York. Inc. 119pp 25865-047 24X Fiche 50-000.84/07/27.8407250229

- B408020041 Forwards insp fees for Surry Power Station & North Anna, Unit i for Mar 1983 Mar 1984 & North Anna, Unit 2 for Apr 1983 Apr 1984 STEMART, W.L. Virginia Electric & Power Co. 84/07/27 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ip. 25880 304 24X Fiche 50-000, 84/07/27, 8408020041
- 840B070357 Discusses IE insp on 840320-23 & forwards notice of violation & proposed imposition of civil penalty O'REILLY, J P Region 2. Dffice of Director 84/07/30 STEWART, W L Virginia Electric & Power Co 4pp 25944 161 24x Fiche 30-280.84/07/30,8408070357
- --8408070360 Notice of violation & proposed imposition of civil penalty in amount of \$40,000 Violation noted svc life commencement date for snubbers incorrect & safety-related snubbers not reviewed per Tech Specs
  O'REILLY, JP Region 2. Office of Director 84/07/31 2pp
  25944 165 24X Fiche 30-280.84/07/31.8408070337
- B40B270443 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-281/84-15 & 50-281/84-15 DANCE, H C Division of Project & Resident Programs STEWART, W L Virginia Electric & Power Co ip 20 Fiche 50-280.84/07/31.8408270443 26257 187
- =~8408270448 Responds to NRC 840620 ltr re violations noted in Insp Repts 50-280/84-15 & 50-281/84-15 Corrective actions smoke & Solution 2 30 colors and the state of the st 26257 18R 24X
- ---8408270452 Forwards Insp Repts 50-280/84-t5 & 50-281/84-t5 en 840401-0305 & notice of violation DANCE,H C Division of Project & Resident Programs 84/06/2 STEMART.W L Virginia Electric & Power Co 2pp 26257 173 Fiche 50-280,84/07/31.8408270443 84/06/20
- --8408270454 Notice of Violation from insg on 840401-0505 \* Region 2, Office of Director 84/06/20 2pp 26 Fiche 50-280,84/07/31,8408270443 26257 195 24X
- 840B280150 Responds to 1E Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class 1E Safety Sys " All OE Type HTA relays in safety-related applications will be replaced STEMART.N L. Virginia Electric & Power Co. 84/07/31 0'REILLY, Region 2, Office of Director 4pp 26259 082 24X Fiche 50-000.84/07/31,8408280150 O'RETLLY, J P
- 8408010333 IE Info Notice 84-59. "Deliberate Circumventing of Station 408010333 It into notice 84-37, "uniterace dircumvencing or beation Health Physics Procedures " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333
- 8408010337 IE info Notice 84-60, "Faiture of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 R4X Fiche 30-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN, E.L. Division of Emergency Programedness & Engineering Response (Post 830103), 84708/08 Consolidated Edison Go of New York, Inc. 120pp 26127 118 24X Fiche 30-000,84708/08,8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list and list anci MRACE,J N Division of QA, Bafeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24x Fiche 50-000.84/08/10.8408070376
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping" 108100009 IE Info Notice 84-03, Development of Engineering Syc 15st encl
  JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

- 8408100038 IC Info Notice 84-64, "BWR HPC! Initiation Scal-In & Indication "Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co 103) B4/08/15 Consolidated Edison Co of New 26198 093 24x Fiche 50-000,84/08/15,8408100038
- B408100021 IE lafo Notice B4-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Syc list encl
  JORDAN.E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/16 Consolidated Edison Co of New
  York, Inc 118pp 26198 001 24X Fiche 50-000.84/08/16.8408100021
- B40B100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN.E t. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000.84/08/17.8408100055
- 8408140208 IE Info Notice 84-47, "Recent Snubber Inservice Testing W/ High Failure Rates "Svc list enc! United Barania My High Failure Rates "Svc list enc! JORAN.E L Division of Emergency Pieparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000.84/08/17, 8408140208
- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORBAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000.84/08/21,8408210142
- R Periodic operating reports & related correspondence
- 8408220171 Monthly operating repts for Jul 1984 W/840815 ltr JONES V H. STEMART. N L Virginia Electric & Power Co 8 BEBBE, M R Defice of Resource Management, Director 40pp 26188 132 24X Fichs 50-280.84/07/31,8408220171 84/07/31
- 8 Reportable occurrences, LFRs & related correspondence
- 8408010096 Forwards LERs 84-016-00,84-017-00 & 83-014/01x-1 SAUNDERS,8 F Virginia Electric & Power Co 84/07/19 Services Branch (Document Control Desk) 1p 25866 268 Record Fiche 50-280, 84/07/19, 8408010056
- --BA0B010060 LER 84-016-00 on B40619 automatic reactor trip resulted from exceeding 10% power on two of four nuclear power channels.

  NI 44 & NI 41, w/turbine unlatched Caused by isolation valve malfunction due to broken goar pin

  BAUNDERB.R F Virginia Electric & Power Co 84/07/17 3pp

  25866 269 24X Fiche 50-280.84/07/19.8408010056
- -8408010069 LER 84-017-00 on 840620 quadrant power tilt greater than 24 sisted longer than 24 h due to control rod 8-6 sticking at 56 step position Gause not determined Extensive monitoring being performed until cause determined SAUNDERS.R F Virginia Electric & Power Co 84/07/17 4pp 25864 272 24X Fiche 50-280.84/07/19.8408010086
- --8408010074 Updated LER 83-014/01X-1 on 830309, during refueling, abnormal degradation of fuel rods observed Caused by primary hydriding, weld defects, stress-related defects & debris induced feetting Mfg process analysis in progress SAUNDERS, R F Virginia Electric & Power Co 84/07/17 Spp 25066 276 24X Fiche 50-280,84/07/19,8408010056
- V Operator Examinations
- 8408070489 Forwards hot license simulator reactor startup certification program per NUREO-0094 Program limits student to instructor ratio to four-to-one-conforming to INPO Guide 82-005 W/o BTEMART, W.L. Virginia Electric & Power Co. 84/06/06 PERBENSKY, J. J. NRC - No Detailed Affiliation Given 25940 347 24X Fiche 80-000,84/06/06,8408070489
- Y Dry Cask Independent Spent Fuel Storage Installations
- 8408240009 Summary of 840810 meeting w/util. Bechtel & SAl in Bilver 408240009 Summary of M40810 meeting w/utilisechte; & MAI in Bpring,MD re dry cask speent fuel storage application Meeting agenda & attendees list enrl RODERTE,JP Advanced Fuel & Spent Fuel Licensing Branch. ROUSE,LC Advanced Fuel & Spent Fuel Licensing Branch ROUSE,LC Advanced Fuel & Spent Fuel Licensing Branch ROUSE,LC Advanced Fuel & Spent Fuel Licensing Branch 84/08/20

- DOCKET 50-281 SURRY POWER STATION, UNIT 2

  F. Security, medical, emergency & fire protection plans
- 8408310069 Confirms 840524 visit to Region to discuss access control at facilities
  LENIS.R C Region 2. Office of Director 84/05/22 STEWART, W L
  Virginia Electric & Power Co 1p 26333 342 24X
  Fiche 50-000,84/05/22,8408310069
- 8408310401 Forwards summary of 840524 meeting re security interface activities Meeting beneficial & provided better understanding between security staffs LEWIS.R C Region 2. Office of Director 84/06/06 STEWART.W L. Virginia Electric & Power Co 4pp 26333 311 24x Fiche 50-000.84/06/06.8408310401
- 8408300433 Forwards Commonwealth of VA response to comments & proposed corrective actions in reply to FEMA rept of 831001 full-scale emergency exercise

  DANCE:H C Region 2. Office of Director 84/06/26 STEWART; H L Virginia Electric & Power Co ip 26314 308 24X Fiche 50-280.84/06/26.8408300433
- 8408020132 Revised emergency plan H/840727 ltr MILLER, H L . GRADY, W D . STEWART, W L Virginia Electric & Power Co 84/06/28 O'REILLY, J P Region 2. Office of Director 276pp 25890 109 24% Fiche 50~280, 84/06/28, 8408020132
- 840B070039 Forwards replacement pages to control room design review program plan Adoption of Mestanghouse Owners Group emergency response guidelines as besis for task analysis & verification/validation sections principal changes BTEWART.W L Virginia Electric & Power Co B4/07/27 DENTON, H R Office of Nuclear Reactor Regulation. Director EISENHUT, D G Division of Licensing 8pp 25749 281 24X Fiche 50-000, 84/07/27, 8408070039
- 8408270443 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-281/84-15 & 50-281/84-15 DANCE.H C Division of Project & Resident Programs 84/07/31 BTEMART.W L Virginia Electric Power Co 1p 26237 187 24X Fichs 30-280,84/07/31.8408270443
- --8408270448 Responds to NRC 840620 ltr re violations noted in Insp Repts 50-280/84-15 & 50-281/84-15 Corrective actions smoke & heat detector periodic tests changed to include up to date testing techniques using heat gun test gas STEWART.W L Virginia Electric & Power Co 84/07/20 O'RE(ELLY. J. P. Region 2. Office of Director 5pp 26257 188 24X Fiche 50-280,84/07/31,8408270443
- --8408270452 Forwards Insp Repts 50-280/84-15 & 50-281/84-15 on 840401-0905 & notice of violation DANCE:H C Division of Project & Resident Programs 84/06/20 STEWART,W L Virginia Electric & Power Co 2pp 26297 193 24X Fiche 50-280,84/07/31.8408270443
- --8408270454 Notice of violation from insp on 840401-0505 # Region 2, Office of Director 84/06/20 2pp 26257 175 24X Piche 50-280,84/07/31,8408270443
- --8408270456 Insp Repts 50-280/84-15 & 50-281/84-15 on 840401-0505 Violation noted procedures for testing certain components not adequate & fire protection program implementing procedures not properly followed BURKE.D J Region 2. Office of Director ELROD.8 Division of Project & Resident Programs 84/06/19 5pp 26257 197 24% Fiche 50-280.84/07/31.8408270443
- 8408310060 Advises that 840412 rev to emergency plan consistent w/ provisions of 10CFR50 47(b) & requirements of App E DANCE: H C Region 2, Office of Director 84/08/01 STEMART, W L Virginia Electric & Power Co 2pp 26334 356 24X Fiche 50-280: 84/08/01: 8408310060
- 8408100078 Revs to radiation emergency plan W/840803 ltr BTEWART,W L. Virginia Electric & Power Co. B4/07/17 O'REILLY,J P Region 2. Office of Director 70pp 25770 280 24X Fiche 50-280, 84/08/03,8408100078
- 8408300429 Ack receipt of 840705 ltr re emergency exercise scheduled for plant during Bapt 1984 Scenario & controller messages will be reviewed when received DANCE, H C Region 2, Office of Director 84/08/08 STEWART, W L Virginia Electric & Power Co ip 26314 330 24X Fiche 50-280,84/08/08,8408300429

- 8408200387 Advises that program plan for conducting detailed control room design review meets intent of Suppl 1 to NUREC-0737 Listed areas should be described in summary rept expected 850830 VARGA: S.A. Licensing Branch 1 84/08/10 STEWART.W.L. Virginia Electric & Power Co. 2pp. 26141 215 24X Fiche 50-000.84/08/10.84/08/200387
- 8408160406 Forwards revised pmergency plan implementing procedures, including EPIP-2 03 re repts to offsite agencies EPIP-3 01 re callout of emergency response personnel & EPIP-5 01 re transportation of contaminated injured personnel W/o encl STEWART. W L Virginia Electric & Power Co 84/08/13 O'REILLY, J P Region 2. Office of Director 2pp 26092 179 24X Fiche 50-280.84/08/13.8408160406
- 8408170222 Revised emergency plan implementing procedures, including EPIP-2 03 re repts to offsite agencies, EPIP-3 01 re callout of emergency response personnel & EPIP-5 01 re transport of contaminated injured personnel #/840813 1tr STEWART, W L. Virginia Electric & Power Co. 84/08/13 0'REILLY, J P. Region 2, Office of Director 12pp 26118 077 24X Fiche 50-280, 84/08/13,8408170222
- P Operating license stage documents & correspondence
- 8408300369 Confirms 840501 telcon w/HC Dance re 840510 mgt meeting in Region II ofc to discuss organizational structure LEWIS.R C Region 2. Office of Director 84/05/07 STEWART.W L Virginia Electric & Power Co 1p 26308 230 24X Fiche 50-000.84/05/07.8408300369
- 840B010161 Notification of 840727 meeting w/util at site to discuss questions re control of heavy loads (Multi-Plant Action C-15)
  NEIGHBURS, D Operating Reactors Branch 1 84/07/20 VARGA, 8 A Operating Reactors Branch 1 2pp 25873 304 24X
  Fiche 50-280, 84/07/20, 8408010161
- 8408160037 Advises that upgraded in-core thermocouple sys schedule will be completed by 1986 refueling outage, per 840221 commitment & will meet requirements of NUREO-0737, Item II F 2 STEWART, W L. Virginia Electric & Power Co. 84708/01 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D 9 Division of Licensing 1p 26092 052 24% Fiche 50-280, 84/08/01, 84/08/6039
- 8408130585 Notifies that any permanent changes to new fuel container lifting rig will be made per ANSI NI4 6-1978 raquirements & NUREO-0612
  STEWART: W.L. Virginia Electric & Power Co. 84/08/03 DENTON, H.R. Defice of Nuclear Reactor Regulation. Director EISENHUT.D & Division of Licensing ip 26031 359 24% Fiche 50-280,84/08/03.8408130385
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors: applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritistion of Generic Bafety Issues" Svc list and EISENHUT.D O Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche. 50-000.84/08/06.8408070110
- 8408210132 Forwards Generic Ltr 84-15 response schedule, listing 840928 & 850131 as projected dates Justification for extension of responses included STEMART.W L Virginia Electric & Power Co 84/08/16 DENTON, H. R Office of Nuclear Reactor Regulation, Director EISENHUT, D O Division of Licensing 3pp 26181 348 24X Fiche.50-000,84/08/16,8408210132
- B408240280 Forwards response to 840606 request for add1 info.to complete review of util 831207 request for relief from ABME Section XI re monregenerative HX integrally welded support One oversize drawing encl Aperture cand in PDR STEWART, W. L. Virginia Electric & Power Co. B4/08/17 DENTON, H. R. Office of Nuclear Reactor Regulation. Director VARGA, S. A. Operating Reactors Branch 1. 4pp. 26227 227. 24X Fiche: 50-280, 84/08/17, 8408240280
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Evc list encl
  EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
  Fiche 50-000,84/08/20,8408200275

- O inspection reports, IE Bulletins & correspondence
- 8408010164 EN-84-049 on 840730, notice of violation & proposed imposition of civil penalties in amount of \$40,000 will be issued to licensee Action involves failure to adequately implement svc life monitoring program for snubbers KLINGLER, G. AXELRAD, Director's Office. Office of Inspection and Enforcement 84/07/25 ip 25855 305 24X Fiche 50-280,84/07/25,8408010164
- 8407250229 JE Info Notice 84-57. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants "Svc list encl JDRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York: Int. 119pp. 25865 047 24X Fithe 50-000.84/07/27.8407250229
- 8408020041 Forwards insp fees for Surry Power Station & North Anna, Unit 1 for Mar 1983 - Mar 1984 & North Anna, Unit 2 for Apr 1983 - Apr 1984 STEWART, W.L. Virginia Electric & Power Co. 84/07/27 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ip 25860 304 24X Ficha 50-000.84/07/27.8408020041
- 8408070357 Discusses IE insp on 840320-23 & forwards notice of violation & proposed imposition of civil penalty O'REILLY.J P Region 2. Office of Director 84/07/30 STEWART.W L Virginia Electric & Pawer Co 4pp 25744 161 24X Fiche 50-280.84/07/30.8408070357
- --8408070360 Notice of violation & proposed imposition of civil penalty in amount of \$40.000 Violation noted svc life commencement date for snubbers incorrect & safety-related snubbers not reviewed, per Tech Specs
  O'REILLY, J P Region 2. Office of Director 84/07/31 2pp
  25944 165 24X Fiche 50-280,84/07/31,8408070357
- B40B270443 Ack receipt of 840720 ltr informing NRC of steps taten to correct violations noted in Insp Repts 50-281/84-15 & 50-281/84-15
  DANCE/H C Division of Project & Resident Programs 84/07/31
  STEMART.W L Virginia Electric & Power Co Ip 26257 187 247
  Fiche 50-280/84/07/31/8408270443
- --8408270448 Responds to NRC 840620 ltr re violations noted in Insp Repts 50-280/84-15 & 50-281/84-15 Corrective actions smoke & heat detector periodic tests changed to include up to date testing techniques using heat gun test gas BIEMART.W L Virginia Electric & Power Co 84/07/20 O'REILLY.J P. Region 2, Office of Director 5pp 26237 188 24X Fiche 50-280,84/07/31,8408270443
- --8408270452 Forwards Insp Repts 50-280/84-15 & 50-281/84-15 on 840401-0505 & notice of violation DANCE, N C Division of Project & Resident Programs 84/06/20 STEMART, W L Virginia Electric & Power Co 2pp 26287 193 24X Fiche 50-280,84/07/31,8408270443
- --8408270454 Notice of violation from insp on 840401-0505 \* Region 2, Office of Director 84/06/20 2pp 26257 195 24X Fiche 50-280,84/07/31,8408270443
- --8408270456 Insp Repts 50-280/84-15 & 50-281/84-15 on 840401-0505 Violation noted procedures for testing certain components not adequate & fire protection program implementing procedures not properly followed BURKE.D J. DAVIS.M J. MYERS.D 0 Region 2. Office of Director 84/06/19 5pp. 26257 197 24X Fichs 50-280.84/07/31.8408270443
- 8408280150 Responds to IE Builetin 84-02, "Failures of GE Type HFA
  Relays in Use in Class iE Safety Sys " All GE Type HFA
  relays in safety-related applications will be replaced
  STEMART, W.L. Virginia Electric & Power Co 84/07/31 D'REILLY, J F
  Region 2, Office of Director 4pp 26259 082 24X
  Fiche 50-000,84/07/31,8408280150
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list encl JORDAN.E L Bivision of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc. 123pp 26067 158 24X Fiche 50-000.84/08/06.8408010337

- B40B070120 IE Info Notice B4-61. "Gveresposure of Diver in PUR Refueling Cavity " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of Ne-York Inc. 120pp 26129 118 244 Fiche 30-000,84/08/08,8408070120
- 8408070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list encl GRACE.J N Division of QA. Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24x Fiche 30-000.88/08/10.8408070376
- B40B100009 IE Info Notice B4-63, "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN, E. Division of Emergency Preparedness & Engineering
  Response (Post B30103) 84/08/13 Consolidated Edison Co of NeuYork, Inc. 119pp 26197 218 24X Fiche 50-000, 84/08/13, 840B100009
- 8408100038 IE info Notice 84-64, "BWR NPCI Initiation Seal-In & Indication "Sec list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24% Fiche 50-000,84/08/15,8408100038
- 8408100021 IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000.84/08/16.8408100021
- 8408100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 262/6 001 24X Fiche 50-000.84/08/17,8408100055
- B40614020B JE Info Notice 84-67, "Recent Snubber Inservice Testing W/High Failure Rates " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24% Fiche 50-000.84/08/17.8408140208
- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solonoid Valves " Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc. 115pp 26329 008 24% Fichs 50-000.84/08/21.8408210142
- A Periodic operating reports & related correspondence
- 8408220171 Monthly operating repts for Jul 1984 W/840815 ltr JONES, V H , STEHART H L Vsrginia Electric & Power Co 84/07/31 JEEBE M R Office of Resource Management, Director 4Opp 26188 132 24x Fiche 50-280,84/07/31.8408220171
- V Operator Examinations
- 8408070489 Forwards hat license simulator reactor startup certification program.per NUREG-0094 Program limits student to instructor ratio to four-to-one-conforming to INPD Guide 82-005 M/o encl
  STEWART.W L Virginia Electric & Power Co 84/06/06
  PERGENSKY, J J NRC No Detailed Affiliation Given 2pp
  25940 247 24X Fiche 50-000.84/06/06.8408070489
- Y Dry Cask Independent Spent Fuel Storage Installations
- 840B240009 Summary of 840B10 meeting w/util.Bechtel & SAI in Silver Spring.MD re dry cast spent fuel storage application Meeting agenda & attenders list encl ROBERTS.J P Advanced fuel & Spent Fuel Licensing Branch ROBEE.L C Advanced Fuel & Spent Fuel Licensing Branch 26252 355 24Y Fiche 50-280.84/08/20.8408240009
- DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8408200484 Grants exemption from certain requirements of 10CFR50. App R. Bubsections III 0 & & 111 0 re reactor coolant pump lube of 1 collection sys Commitment to protect redundant cabling expected to be completed by 841831
  HILLER, J & Operating Reactors Branch 3 84/07/31 MUSDLF, D M Northern States Fower Co 2pp 26143 331 24X
  Fiche 50-282,84/07/31,8408200484

- --8408200489 Exemption from certain requirements of 10CFR50. App R. Subsections III 6 2 & III 0 re Fire Areas 1 & 71 & reactor coolant pump lube oil sys EIEENHUT, D 6 Division of Licensing 84/07/31 Northern States Power Co 7pp 26143 333 24X Fiche 50-282.84/07/31.8408200484
- 8408300176 Forwards Rev 7 'o "Northern States Power Co Corporate Nuclear Emergency Plan " Rev includes changes resulting from annual internal review.update & certification of emergency plans & agreements
  FEY:F L Northern States Power Co 84/08/02 Region 3, Office of
  Director App 26302 106 24% Fiche 50-000.84/08/02,8408300176
- -8408300180 Rev 7 to "Northern States Power Co Corporate Nuclear Emergency Plan" HUDSON.G : FEY.F L : LARSON.C E Northern States Power Co 84/08/02 116pp 26302 110 24% Fiche 50-000.84/08/02, 8408300176
- ~8408300183 Revised "Radiation Environ Monitoring Plan" CLARK.B W. FEY.F L. Northern States Power Co. 84/02/29 14pp 26302 226 24X Fiche 50-000.84/08/02.8408300176
- 8408100029 Forwards IE Safeguards Insp Repts 50-282/84-10 & 50-306/84-09 on 840709-13 & notice of noncompliance Notice of noncompliance withheld (ref 100FR73 2))

  AXELEON,W L. Region 3, Office of Director 84/08/03 LARSON,C E Northern States Power Co 2pp 25987 068 24X

  Fiche 50-282,84/08/03,8408100029
- --8408100037 IE Safeguards Insp Repts 50-282/84-10 & 50-306/84-09 on 840709-13 Noncompliance noted failure to provide effective barrier in portion of protected area perimeter Details withheld (ref 10CFR73 21)
  KNICELEY, J R , BELANGER, J L , CREEO, J R Region 3, Office of Director 84/08/03 2pp 25987 070 24X Fiche 50-282,84/08/03,8408100029
- 8408310173 Ack receipt of 840625 Rev 4 to emergency plan Next rev should include description of onsite & offsite environs & radiological monitoring drills & monthly communications cneck PAPERIELLO.C J Region 3, Office of Director 84/08/27 LARBON.C E Northern States Power Co 2pp 26317 141 Fiche 50-282,84/08/27,8408310173
- P Operating license stage documents > correspondence
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors. NUBO/UllO Generic Ltr 84-19 to All licensees of operating reactors applicants for OLs & holders of CPs re availability of Suppl 1 to NURED-0933, "Prioritization of Generic Safety Issues " Svc list encl EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000,84/08/06,8408070110
- 8408160482 Summary of 840724 meeting w/Westinghouse Owners Group re upper plenum injection for two loop plants DIIANNI.D C Operating Reactors Branch 3 84/08/09 Operating Reactors Branch 3 4pp 26108 327 24X Fiche 50-000,84/08/09,
- B408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EIBENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Cp of New York, Inc. 17pp 262/6 244 24X Fiche 50-000, 84/08/20, 8408200275
- Q Inspection reports, IE Bulletins & correspondence
- 8407250229 IE Info Notice 84-97, "Operating Experience re Moisture 40/230227 It for Notice 84-37. "Operating Experience re masku Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co York, Inc. 119pp 25855 047 24X Fiche 50-000,84/07/27,8407. /27 Consolidated Edison Co of New 24X Fiche 50-000,84/07/27,8407250229
- 8408070189 Ack receipt of 840713 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/84-04 & 50-306/84-04 Corrective actions re sys blocking & tagging appropriate SHAPERN W D. Region 3. Office of Director 84/07/3! LARSON, C.E. Northern Statas Power Co. 24p. 25949 349 24X Fiche 50-282, 84/07/31.88()8070189

- --B408070197 Responds to NAC B40629 ltr re violations noted in IE Insp. Repts 50-282/84-04 & 50-306/84-04 Corrective actions reactor coolant vent sys solenoid valve fuses removed & will not be installed until requirements met LARBON.C & Northern States Power Co. 84/07/13 SHAFER,W D. Region 3, Office of Director 2pp. 25949 351 24X Fiche 50-282,84/07/31,8408070189
- 8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during inspirately defective 840820 Preprinted form will be used Repries 40 Region 3, Office of Director 84/08/03 Commonwealth Edison Co. 3pp. 25942 188 24X Fiche 30-200,84/08/03,
- B40B100029 Forwards [E Bafeguards Inap Repts 50-282/B4-10 & 50-306/84-09 on B40709-13 & notice of noncompliance Notice of noncompliance withheld (ref 100FR73 21) AXELSON.W L Region 3, Office of Director 84/08/03 LARSON.C E Northern States Power Co 2pp 25987 068 24X Fiche 50-282.84/08/03.8408100029
- --B40Bl00037 IE Safeguards Insp Repts 50-282/84-10 & 50-306/B4-09 on B40709-13 Noncompliance noted failure to provide effective barrier in portion of protected area perimeter Details withheld (ref 100FR73 21)
  KNICELEV.J R . BELANGER.J L . CREED, J R Region 3, Office of Director B4/0B/03 2pp 25987 070 24X Fiche 50-282, B4/0B/03, B40B100029
- 8408010333 [E Info Notice 84-59, "Deliberate Circumventing of Station Vacious it into Marie 94-97, Deliberate directivementing of Stateon Health Physics Procedures "Syc list encl
  JDRDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/06 Cansolidated Edison Co of New
  York, Inc. 122pp 26068 001 24X Fiche 30-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24% Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Info Notice 84-41, "Overexposure of Diver in FWR Refueling Cavity " Svc list encl JURDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Cunsolidated Edison Co of New York, Inc. 120pp 26129 118 24% Fiche 30-000,84/08/08,8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Telethorapy Treatments " Svc list encl

  GRACE: J N Division of OA, Bafeguards & Inspection Programs (Post
  830103) 84/08/10 Consolidated Edison Co of New York: Inc
  125pp 26130 001 24% Fiche 50-000.84/08/10,8408070376
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc. (17pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408100038 IE Info Notice 84-64. "BWR HPCI Initiation Seal-In & Indication " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000.84/08/15.8408100038
- 840810002: IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Syc list encl JGRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26198 001 24X Fiche 50-000.84/08/16.8408100021
- 8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc. 120pp 26276 001 24X Fiche 50-000,84/08/17.8408100055
- 8408140208 IE Info Notice 84-67. "Recent Snubber Inservice Testing W/
  High Fallure Rates" Syc list encl
  JORDANIE L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/17 Consolidated Edison Co of New 17 Consolidated Edison Co of New 24X Fiche 50-000,84/08/17,8408140208 26276 122
- 8408210142 IE Info Notice 84-46, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JDRDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York: Inc 115pp 26329 008 24X Fiche 50-000,84/08/21.8408210142

- S Reportable occurrences. LERs & related correspondence
- B40B210278 Part 21 rept re separation of rod eye connected to piston rod from threaded portion of piston rod at approx 750.000 lb stress load Caused by insufficient mati thickness to withstand faulted load Mati certification encl MILLS.C R Chicago Fluid Power Co 84/08/16 Director's Office. Office of Inspection and Enforcement 4pp 26180 349 24% Fiche 50-282.84/08/16.8408210278
- B40B24023B LER 84-029-00 on 84071B.lockout of 2RY transformer & autostart of both diesel generators occurred Caused by relay misoperation Relay replaced W/840B17 ltr HUNSTAD. A A. MUSDLF.D. Northern States Power Co 84/08/17 3pp 26236 251 24X Fiche 50-282.84/08/17.8408240238

### V Operator Examinations

- B40B140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners WALMER, R D Region 3, Office of Director B4/08/10 Michigan. Univ of. Ann Arbor, MI 2pp 26051 198 24% Fiche 50-000. B4/08/10,8408140426
- 8408230526 Advises that operator & senior operator litensing exams scheduled for 841i13-15 Matl listed in encl "Ref Matl Requirements for Operator/Senior Operator Licensing Exams" requested by 840913
  MALKER, R D Region 3. Office of Director 84/08/17 LARSON, C E Northern States Power Co 5pp 26212 338 24X
  Fiche: 50-282,84/08/17,8408230526
- B408230132 Informs of review of B40705 ltr which clarified interpretation of on-shift training requirements Utij will be required to provide documentation that sentor reactor operator upgrade candidates comply w/listed requirements WALMER.R B Region 3. Office of Director B4/08/20 LARSON, C E Northern States Power Co. 2pp 26209 O61 24X Fiche 50-000, B4/08/20, B40823D132

# DOCKET 50-284 IDAHO STATE UNIV RESEARCH REACTOR F Security, medical, emergency & fire protection plans

8403300696 Requests submittal of revised emergency plan, including info identified in enci.within 60 days of ltr Gate.based on revise of 830914 submittal THOMAS.C D Standardization & Special Projects Branch 84/05/21 KEGELC H Idaha State Univ. Pecatello. ID 4pp 24733 048 24X Fiche 50-284.84/05/21.8405300696

#### DOCKET 50-295 FORT CALHOUN STATION, UNIT 1

- F Security, medical, energency & fire protection plans
- 8408070142 Forwards request for addl info to continue review of 831028 submittal resafety parameter display systematically analysis, per Suppl 1 to NUREG-0737 Response requested within AD days MILLER, J R. Operating Reactors Branch 3 84/07/24 JONES, W C. Omaha Public Power District 4pp 25957 134 24% Fiche 50-285,84/07/24,8408070142
- P Operating license stage documents & correspondence
- 8408070128 Advises that reporting requirements for Tech Spec Sections 3 3(2)e(i) & 3 3(2)e(ii) re steam generators satisfied by util 840419 ltr.

  ANDREWS.R L Omaha Public Power District 84/07/3; MILLER, J R Operating Practors Branch 3 1p. 25949 276 24X Fiche 50-285,84/07/31.8408070128
- 8408100104 Notifies that info requested in NRC 840711 ltr & during 840725 telcon re inadequate core cooling instrumentation syscannot be furnished until 840930 ANDREWS.R L Dmaha Public Power District 84/08/02 MILLER.J R Operating Reactors Branch 3 ip 25990 277 24X Fiche:50-285,84/08/02.8408100104.
- 8408200339 Forwards Amend 82 to License DPR-40 & safety evaluation Amend adds operability & surveillance requirements for containment hydrogen, water & pressure monitors TOURIGNY.E 0 Deprating Reactors Brench 3 84/08/02 JONES, W C Omaha Public Power District ip 26141 220 24X Fiche. 50-285, 84/08/02, 8408200359.

- --8408200360 Amend 62 to Lirense DPR-40, adding operability & surveillance requirements for containment hydrogen, water & pressure monitors

  MILLER, J. R. Operating Reactors Branch 3 84/08/02 5pp 24141 221 24X Fiche 50-285,84/08/02,8408200359
- --B408200361 Safety evaluation supporting Amend 82 to License DPR-40
  \* Office of Nuclear Reactor Regulation, Director 84/08/02 4pp
  26141 226 24% Fiche 50-285.84/08/02,8408200359
- B40B070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for CLs & holders of CPs re availability of Suppl 1 to NUREG-0933. "Prioritization of Generic Safety Issues " Svc list encl EISENHUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24% Fiche 50-000.84/08/06.8408070110
- 8408270244 Discusses implementation status of toxic gas monitoring instrumentation sys Sys will be fully operable by 840930, based upon time required for procedure review & approval & training
  ANDREWG-R L Omaha Public Power District 84/08/13 MILLER, J R Operating Reactors Branch 3 2pp 26239 154 24X
  Fiche 50-285,84/08/13,8408270244
- @ Inspection reports, IE Bulletins & correspondence
- 8408060307 Forwards IE Insp Rept 50-285/84-13 on 840501-31 No violations or deviations noted JOHNSON, E. H. Region 4, Office of Director 84/06/29 JONES, W. C. Omaha Public Power District 2pp 25936 073 24X Fiche 50-285,84/06/29,8408060307
- --B408060313 JE Insp Rept 50-285/84-13 on 840501-31 No violations or deviations noted Major areas inspected safety verification, surveillance testing naint activities & followup of steam generator tube failure incident YANDELL.L A., TONLINSON.D P., JAUDON,J P. Region 4, Office of Director 84/06/27 Bpp 25736-075 24X Fiche 50-285,84/06/27,8408060307
- 8408230461 Forwards TE Insp Rept 50-285/84-15 on 840623-27 & notice of violation HUNTER, D R Region 4. Office of Director 84/07/23 JONES, W C Omaka Public Power District 2pp 26213 123 24X Fiche 50-285,84/07/23,8408230461
- --8408230463 Notice of violation from insp on 840623-27
  \* Region 4, Office of Director 84/07/23 2pp 26213 125 24X
  Fiche 50-285,84/07/23,8408230461
- --8408230464 IE Insp Rept 50-285/84-15 on 840623-27 Violation noted failure to follow procedures re insp of matl received CALDMELL.R A . HALL.R E . MARTIN.L E Region 4, Office of Director 84/07/23 7pp 26213 127 24X Fiche 50-285.84/07/23, 8408230461
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc. 119pp 25865-047 24X Fiche 50-000,84/07/27,8407250229
- B408010333 IE Info Notice 84-57, "Deliberate Circumventing of Station Mealth Physics Procedures" Evc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/0B/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24% Fiche 50-000.84/08/06, 8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Englineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- B408100057 Ack receipt of 840627 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/84-10 HUNTER, DR Regian 4. Office of Director 84/08/07 ANDREWS,R L Omaha Public Power District in 25987 089 24X Fiche 50-285,84/08/07.8408100057
- ---0408100062 Responds to NRC 840930 ltr re violations noted in IE Insp Rept 50-285/84-10 Corrective actions combined electrical/ mechanical/structural critical quality element list will be issued by 840715. JONES, W C Onaha Public Power District 84/06/27 DENISE, R P Division of Resident, Reactor Project & Engineering Programs 3pp 25987 060 24X Fiche 50-285,84/08/07,8408100057

- 8408070120 IE Info Notice 84-41. "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York
- 8408290140 Forwards reactor operator exam rept on 840605-07 Response describing corrective actions for training program weaknesses requested within 60 days of rept receipt HUNTER, D.R. Region 4, Office of Director 84/08/08 ANDREWS, R.L. Omaha Public Power District 2pp 26278 116 24X Fiche 50-285, 84/08/08 4408290140
- --8408290142 Exam rept on 840605-07 Exam results all three candidates failed MCCRURY,5 L., COOLEY,R A. Region 4, Office of Director 84/08/0 56pp 26298 118 24X Fiche 50-285,84/08/08,8408290140
- 8408070376 IE Info Natice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Syclist encl
  GRACE, J N Division of GA. Safeguards & Inspection Programs (Post
  830103) 84/08/10 Consolidated Edison Co of New York, Inc
  125p 26130 001 24% Fiche 50-000.84/08/10.8408070376
- B40B100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN-E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000.84/08/13.8408100009
- B408100038 IF Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co. of New York, Inc. 104pp 26198 093 24X Fichs 50-000.84/08/15,8408100038
- 8408100021 IE Info Notice 84~65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000.84/08/16.8408100021
- 8408100055 IE Info Notice 84-64, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Respanse (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Cansolidated Edison Co. of New York, Int. 122pp 26276 122 24X Fiche 50-000.84/08/17.8408140208
- B40B210142 If Info Notice B4-68, "Potential Deficiency in Improperty Rated Field Wiring to Solenoid Valves " Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc. 115pp 26329 008 24X Fiche 50-000.84/08/21.8408210142
- R Periodic operating reports & related correspondence
- B40B2005B9 Monthly operating rept for Jul 1984 W/840803 ltr MATTHEWB,TP, ANDREWB,RL Omaha Public Power District 84/07/31 DEYOUND,RC Director's Office, Office of Inspection and Enforcement 10pp 2613B 12B 24X Fiche 50-285,84/07/31, B40B2005B9
- S Reportable occurrences. LERs & related correspondence
- 8408060289 LER 84-009-00 on 840622, penetration assemblies failed Caused by brittle & cracked teflon inculation on lead wires Selected penetration assemblies modified Assemblies remaining will be qualified by Nov 1985 W/840723 ltr FISICARD.J J., ANDREWS.R L. Omaha Public Power District 84/07/23 4pp 25936 048 24% Fiche 50-285.84/07/23.8408040289
- B40809040i LER 84-015-00 on 840702, load of approx 250 lbs carried by polar crane over RCS when fluid in pressurizer greater than 225 F Procedure change made to RCS vent & leak test instructions W/840801 ltr KUSEK, L T. ANDREWS, R L Omaha Public Power District 84/08/01 3pp 25993 270 24% Fiche 50-285.84/08/01.8408090401

- 8408090405 LER 84-014-00 on 840703, during weekly replacement of iodine collection cartridge on RM-060, actuation of ventilation isolation actuation sys occurred No cause given RM-060 will be out of svc during filter replacement W/840703 ltr KUSEK/L I , ANDREWS/R L Omaha Public Power District 84/08/02 4pp 25993 263 24X Fiche 50-285,84/08/02,8408090405
- 8408240230 LER 84-012-00 on 840717,boron concentration in safety injection & refueling water tank below Tech Spec limits Caused by analytical error Boron concentration maintained at higher level W/840816 ltr FLUEHR,J J. ANDREWS.R L. Qmaha Public Power District 84/08/16 3pp 26236 316 24X Fiche 50-285.84/08/16,8408240230
- 8408280343 LER 84-011-03 on 840720, stainless steel woven connection from auxiliary bldg ventilation discharge duct to radiation monitors 8M-061/062 found disconnected Caused by loose \$11p fit connection Connector reattached W/840819 ltr FLUEHR.J. ANDREWS, R. L. Omaha Public Power District 84/08/19 App 26282 253 24X Fiche 50-285,84/08/19,8408280343
- 8408280288 LER 84-013-00 on 840722, trip signals received on Channels A & C of thermal margin/Jow pressure reactor protective syst circuits Caused by noise spikes on calculators Noise suppressors installed W/840821 ltr WUELLER, R J . ANDREWS, R L Omaha Public Power District 84/08/21 3pp 26282 180 24% Fiche 50-285,84/08/21,8408280288

### V Operator Examinations

- 8408290140 Forwards reactor operator exam rept on 840505-07 Response describing corrective actions for training program weaknesses requested within 50 days of rept receipt HUNTER: D.R. Regian 4. Office of Director 84/08/08 ANDREWS, R. L. Omaha Public Power District 29p 26278 116 24X Fiche 50-285, 84/08/08,8408290140
- --8408290142 Exam rept on 840605-07 Exam results all three candidates failed MCCRDRY,S L., CODLEY,R A. Region 4. Office of Director 84/08/0: 56pp 26298 118 24X Fiche 50-285.84/08/08.8408290140
- 8408280075 Confirms scheduling of operator exams for 841106-07 Submission of exam applications at least 60 days prior to exam requested Ref matl & administrative requirements encl HUNTER.D R Region 4. Office of Director 84/08/24 ANDREWS.R L Omaha Public Power District 5pp 26261 210 24X Fiche 50-285.84/08/24.8408280075

## DOCKET 50-286 INDIAN POINT STATION, UNIT 3 F Security, medical, emergency & fire protection plans

- 8405240290 Responds to 840424 memo for FEMA review of util request for delay in scheduling mest full-scale emergency preparedness exercise at site until 841130 Delay acceptable KRIMM, R Federal Emergency Management Agency 84/05/18 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 8pp 24614 336 24X Fiche 50-003,84/05/18,84065763200
- B40B070036 Clarifies add] issues raised by NRC in B40626 telcon re New York PIRO petition to suspend OLs due to emergency planning inadequacies FEHA rept & State of NY response to FEMA 840611 Itr encl KRIMM R W Federal Emergency Management Agency 84/07/31 JOROBAN E L Division of Emergency Preparedness & Engineering Response (Post B30103) ip 25992 335 24X Fiche 30-247,84/07/31, B40B0300004
- ~~B408070059 "Evaluation of Add1 Issues Raised by NRC re New York PIRO Petition to Suspend Operation of Indian Point, Units 2 & 3 " # Federal Emergency Management Agency 84/07/26 10pp 25992 336 24X Fiche 50-247,84/07/31,8408090056
- --8408070061 "Add1 Info Obtained From NY State on New York PIRO Petition Which Supple FEMA Rept to NRC 4t6 840608 " \* Federal Emergency Management Agency 84/07/26 8pp 25972 346 24X Fiche 50-247.84/07/31.8408090056
- B408130309 Forwards detailed control room design review program plan, per B40221 emergency response capability confirmatory order Program will be complete before startup from next (Gycle 4/5) refueling outage Schedule for mode will be submitted BAYNE. J P Power Authority of the State of New York, 84/08/03 VAROA. B A Sperating Reactors Branch 1 ip 26009 264 24% Fiche 50~286.84/08/03.8408130309
- --8408130313 "Detailed Control Room Design Review Program Plan "

  \* Power Authority of the State of New York 84/08/03 101pp 26009 265 24X Fiche 50-286,84/08/03,8408130309

- 8408150230 Forwards supplemental info re seismic capability of reactor coolant pump oil spillage collection sys & OA program utilized for initial App R. Section III G review Adds mods implemented to enhance seismic capability of collection sys BAYNE. J P Fower Authority of the State of New York B4/08/13 VARGA. S A Operating Reactors Branch 1 43pp 26066 005 24x Fiche 50-286.84/08/13.4408150230
- B408230164 Forwards "Reevaluation of App R.Section III G Requirements for Indian Point Nuclear Power Plant Unit 3 " Proposed schedule for implementation of mods encl BAYNE.J P Power Authority of the State of New York B4/08/16 VARGA.S A Operating Reactors Branch 1 7pp 26219 065 24X Fithe 50-286.84/08/16.8408230164
- --B408230171 "Reevaluation of App R.Section III G Requirements for Indian Point Nuclear Power Plant Unit 3 " \* Power Authority of the State of New York 84/08/31 494pp 26215 072 24X Fiche 50-286.84/08/16.8408230164

### G Adjudicatory correspondence

- 8408140448 Responses to 840730 unpublished order directing NRC & inviting other parties to submit views on Judge Gleason dissent re ASLB recommendation concerning accident probability Certificate of Svc encl SHOLLY, S C Union of Concerned Scientists DSB 029 84/08/13, Commissioners 8pp 26061 007 24X Fiche 50-247,84/08/13,
- 8408140488 Response to Commission 840730 order permitting comments from parties re Chairman Cleason dissent to ASLB recommendations to Commission Certificate of Svc encl
  CGLARULLI.P.F. Power Authority of the State of New York
  COLARULLI.P.F. Morgan Associates
  DSB 030 84/08/13
  Commissioners 14pp 26060 261 24x Fiche 50-247,84/08/13,840814088
- 840B140493 Comments on ASLB Chairman Gleason dissent in recommendations of special proceeding Significant risk reduction already accomplished at facility Certificate of Svc encl BRANDENBURG.B Consolidated Edison Co of New York, Inc DSB 031 84/08/13 Commissioners 12pp 26060 249 24% Fiche 50-247.84/08/i3.8408140493
- 8408150111 Response to Commission 940730 order directing NRC to file comments on Judge Oleason dissent to portion of ASLB recommendations Supports Gleason dissent MIDRE, J E Hearing Bianch 1 D8B 042 84/08/13 Commissioners
- B40B170270 Comments on dissenting views of Chairman Gleason re safety of plant mods Certificate of Svc encl
  BRANDEMBURG. B Consolidated Edison Co of New York, Inc DBB 0B3
  84/08/13 12pp 26118 041 24X Fiche 50-247, 84/08/13, 840B170270

## P Operating license stage documents & correspondence

- 840B070035 Notification of 840720 meeting w/util in Bethesda.MD to discuss ESF electrical distribution mods POLK.P J Operating Reactors Branch 1 84/07/18 VARGA.S A Operating Reactors Branch 1 3pp 23955 333 24x Fiche 50-286.84/07/18.8408070055
- 408090545 Summary of 840720 meeting w/util & BNL in Dethesda.MD re ESF mods Six solutions being considered & licensee agreed to docket final resolution Util agreed to expedite LER BNL & licensee presentations & attendance list encl POLK.P J Operating Reactors Branch 3 84/08/02 Operating Reactors Branch 3 84/08/02 Operating Reactors Branch 3 84/08/02 Section 84/08/02, 8408070545
- B40B070iiO Generic Ltr 84~19 to all licensees of operating reactors, applicants for GLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Generic Safety Issues" Svc list encl EISCRHUT,D Q Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26127 238 24X Fiche 50-000.84/08/06.8408070110
- 9408160528 Forwards listing of info needed to complete review of environ qualification program Response requested within 45 days of ltr receipt W/n encl VARGA: S A Operating Reactors Branch I 84/08/07 BAYNE, J P Power Authority of the State of New York Ip 26122:352 248 Fiche 50-286,84/08/07,8408160528

- 8408170277 Forwards info on NUREO-0737. Item II B 3 re post-accident sampling 64s, supplementing 831026. 1202 & 840323 submittals Results of engineering evaluation of post-accident airborne particulates will be sent by Jone 1985 BAYNC, J.P. Power Authority or the State of New York 84/08/13 VARGA. & A Operating Reactors Branch I 3pp 26115 256 24X Fiche 50-286.84/08/13.8408170277
- B40B210447 Forwards application for amend to License DPR-64, changing Tach Spec Sections 3 13,4 11 5 6 10 re snubber surveillance Interim exemption from functional testing for steam generator snubbers also requested BAYNE J P Power Authority of the State of New York 84/08/13 VARGA, S A Operating Reactors Branch 1 4pp 26181 262 24X Fiche 50-286,84/08/13,8408710443
- --8408210447 Application for amend to License DPR-64, changing Tech Spec Sections 3 i3.4 i1 t 6 i0 re unubber surveillance Safety evaluation of proposed Tech Spec change encl BAYNE J P Power Authority of the State of New York 84/09/13 VARGA, 5 A Deparating Reactors Branch i ip 26181 266 24x Fiche 50-286, 84/08/13, 8408210443
- --8408210451 Proposed Tech Specs.changing Sections 3 13,4 11 & 4 10 re shubber sulveillance \* Power Authority of the State of New York 84/08/13 16pp 24181 267 24X Fiche 50-286.84/08/13.8408210443
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re-scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT.D G Division of Licensing 84/08/20 Consolidated Edison Co of New York. Inc. 17pp 26276-244 24X Fiche 50-000.84/08/20.8408200275
- 8408280333 Staff requirements mamo re 840816 continuation of 840723 discussion of issues requiring resolution prior to issuance of order in proceeding Commission requested briefing on PRA including discussion of uncertainties & basis of comparison CHILK, S. J. Office of the Secretary of the Commission 84/08/21 DIRCKS, W.J. Office of the Esecutive Director for Operations 2pp 26294 DSO 24X Fiche 50-003,84/08/21,8408280333
- Q Inspection reports: IE Bulletins & Correspondence
- 8407250229 E Info Notice 84-97, "Operating Experience of Moisture Intrusion in Safety-Related Flectrical Equipment at Commercial Power Plants "Syclistence on JURDAN,C L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc. 119pp 29845 047 24% Fiche 50-000.84/07/27.8407250229
- 8408150697 Forwards IE Insp Rept 50-286/84-12 on 840521-25 No violations noted MARTIN.T T Division of Engineering & Technical Programs 84/07/27 BRONS.J C Power Authority of the State of New York 2pp 26079 009 24X Fiche 50-286,84/07/27,8408130697
- --8408130701 [C Insp Rept 50-286/84-12 on 840521-25 No noncompliance noted Major areas inspected mgt controls radioactive effluent release records, effluent control procedures, instrument calibrs & testing of air cleaning sys STRUCKMEYER, R. PASCIAN, M. J. Region I. Office of Director 84/07/20 App. 26079 Oil 24X Fiche 50-286,84/07/27,8408150497
- 8408010303 IE Info Notice 814-59. "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 8301031 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24% Fiche 50-000,84/08/06,8408010333
- B40B010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficioncy Requirement" Svc list encl JORDAN.I L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 138 24X Fiche 50-000.84/08/06,8408010337
- 8408070120 [E info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list enc! JORDAN, L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc. 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl GRACE.J N Division of QA, Safeguards 1 Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 183pp 26130 001 24% Fiche 50-000.84/08/10.8408070376

- 8408100009 IF Into datice 84-63, 'Defective RHR Replacement Piping "
- 10810000 IF 19th during and all frequency Preparedness / Engineering Svo list encl Division of Emergency Preparedness / Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co. of New York, Inc. 119pp 26197 218 24% Fishe 50-000 84/08/13,8408100009
- 8408100038 IL Info Notice 84-64 "BWR MPC! Initiation Seal-In 5 Indiration " Svc list enc! JORDAN.F L Division of Emergency Preparedness 5 Engineering Response (Post 830103) 81/07/15 Consolidated Edison Co 103) B1/07/15 Consolidated Edison Co of New 26198 093 24% Fiche 50~000 B4/08/15, 840B100038
- 8408100021 IF Info Notice 84-65. "Underlated Fuses Which May Adversely
- 108100021 IF Info Notice 84-65, "Undersated Fuses Which May Adversely Affect Coperation of Essential Electrical Equipment " Svc list eacl Universion of Emergency Preparedness / Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24% Fiche 50-000.84/08/16.8408100021
- B408100055 IF Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Augiliary Feedwater Train " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 001 24X Fiche 50-000.84/08/17,8408100055
- B40B14020B IE Info Notice B4~67, "Recent Snubber Inservice Testing W/ High failure Rates ' Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/0B/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000.84/08/17,8408140208
- B40B310177 Responds to Item 4 of IE Bulletin 83-07 re apparently fraudulent products sold by Ray Hiller, Inc Existing QA program will provide necessary methods for early detection of patentially fraudulent or deficient groducts BRONS, J C Power Authority of the State of New York B4/08/17 EBNEICR: S D Region 1, Office of Director 3pp 2631B 319 2 Fiche 50-286,84/08/17,8408310177
- 8408210142 IE Info Notice 81-68. "Potential Deficiency in Improperly Rated field Wiring to Solenoid Valves "Syc list encl JDROAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 11500 26329 008 247 Fiche 50-000.84/08/21.8408210142
- 8408310291 Notification of Significant Licenson Meeting 84-79 on 840913 w/util at site to present results of SALP NORRHOLM, L. Division of Project & Resident Programs 84/08/21 Division of Project & Resident Programs 2pp 24950 357 24X Fiche 50-286.84/08/21.8408310251
- R Periodic operating reports % related correspondence
- 8408230428 Monthly uperating rept for Jul 1984 W/840815 ltr KELLY,L , BRONS, J L Power Authority of the State of New York 84/07/31 7pp 26213 047 24% Fiche 50-286.84/07/31.8408230428
- S Reportable occurrences, LERs A related correspondence
- 8408010317 LER 84-011-00 on 840712, turbine generator trip & subsequent reactor trip initiated automatically due to failure of insulator on 345-kV feeder Caused by deposits on insulator Insulator replaced W/840725 ltr
  ANDERSON J J . BRONS J C Power Authority of the State of New York 84/07/25 3pp 25866 144 24X Fiche 50-286.84/07/25,8408010317
- 8408240048 LER 84-012-00 on 840712. Westinghouse advised of potential NUMEROUSE LER MI-UIZ-DU ON MADIZE WESTINGHOUSE MOVISH OF POTENTIAL OverPIESSURE IN COMPONENT COLLING WASTE MAY during inleakage & heat load increases due to tube rupture Relief & vent valves modified to ease overpressure concern W/840817 Itr ANDERSON.J J. BRONS.J C. Power Authority of the State of New York 84/08/17 3pp 26236 159 24X Fiche 50-286,84/08/17,8408240048
- T Hearing transcripts on non-antitrust matters
- B408280025 Transcript of 840816 Commission meeting in Washington, DC recontinuation of 840723 discussion of adjudicatory proceeding Pp 1-76
  \* Commissioners 84/08/16 78pp 26293 169 24X \* Commissioners 84/08/16 78 Fiche 50~003,84/08/16,8408280025

- DOCKET 50-287 OCCINEC NUCLEAR STATION, UNIT 3 F Security, medical, emergency & fire protection plans
- 840830024) Ack receipt of scope & objectives for 840621 emergency preparedness exercise Submittal fultils min requirements for small-scale exercise Complete scenario will be reviewed when received & comments transmitted DANCE, If C. Region 2. Office of Director 84/05/21 TUCKER, H. I. Duke Power Co. 1p. 26307-015 24x Fiche 50-267,84/05/21, 8408300244 TUCKER, H B
- 8408300427 Forwards FEMA "Oconee Nuclear Power Plant Full-Scale Local Exercise Conducted on 830406." final rept DANCE.H C Region 2. Office of Director 84/07/11 TUCKER.H B Duke Power Co ip 26315 205 24X Fiche 50-269.84/07/11.
- 8408150326 Forwards public version of Rev 84-02 to "Emergency Plan Implementing Procedures"
  TUCKER, H B Duke Power Co 84/07/17 G'REILLY, J P Region 2,
  Office of Director 1p 26099 001 24X Fithe 50-269, 84/07/17, 840B1 5032A
- ~-8408130335 Public version of Rev 84-02 to "Emergency Plan Implementing Procedures " W/JM Felton 840808 release memp TUCKMAN,M S Duke Power to 84/06/07 195pp 26099 002 24X Fiche 50-269,84/07/17,8408130326
- 8408240416 Forwards Insp Repts 50-269/84-15.50-270/84-14 & 50-287/84-18 on 840611-0710 No violations or deviations noted DANCE, H C Region 2. Office of Director 84/07/19 TUCKER, H B Duke Power Co ip 26237 113 24X Fiche 50-269, 84/07/19, 8408240416
- --8408240421 Insp Repts 50-249/84-15.50-270/84-14 & 50-287/84-18 on 840411-0710 No noncompliance or deviations noted Major areas inspected operations, naint, surveillance, ESF, emergency drills & fuel handling BRYANT, J Region 2, Office of Director 84/07/19 App 26237 114 247 Fiche 50-269,84/07/19,8408240414
- 8408280361 Forwards Insp Repts 50-269/84-14,50-270/84-13 & 50-287/84-16 on 840619-21 No violations or deviations Judentified
  JANGE, H.C. Region 2, Defice of Director 84/07/20 TUCKEI
  Dake Power Co. 2pp. 26282 239 24% Fiche 50-269, 84/07/20 TUCKER, H B
- --B40BEB0370 Insp Repts 50-269/84-14.50-270/84-13 & 50-287/84-16 on 840619-21 No violations or deviations identified Major area inspected emergency preparadness exercise BECKERIT Region 2, Office of Director 84/07/04 9pp 26282 241 24X Fiche 50-269.84/07/20.8408280361
- 8408130149 Forwards IE Safeguards Insp Repts 50-269/84-17,50-270/84-16 & 50-287/84-19 on 840716-20 No violations or deviations identified
  DANCE, H C Region 2, Office of Director 84/08/07 TUCKER, H D
  Duke Power Co 2pp 26007 344 24K Fiche 50-269, 84/08/07, 8408130149
- --8408130166 IE Safeguards Insp Repts 50-269/84-17.50-270/84~16 & 50-287/84-17 on 840716-20 No violation or deviations identified Major areas inspected security sys power supply & alarm station Details withheld (ref 10CFR2 790 & 73 21) MCDRC.D E Region 2. Office of Director 84/08/07 Ip 26007 346 24% Fiche 50-269.84/08/07.8408130149
- 8408170329 Commits to assure that operators can obtain flashlight to assist in safe passage to standby shutdown facility, per requirements of IOCFR20.App R
  TUCKER.H B Duke Power Co 84/08/08 DENTON.H R Office of Nuclear Reactor Regulation, Director STOLZ.J F Operating Reactors Branch 4 2pp 26112 361 24% Fiche 50-267,84/08/08,8408170329
- 8408300357 Confirms 840806 telcon w/JP D'Reilly re 840815 meeting in Region II ofc to discuss design & operation of standby shutdown facility concerning App R to 10CFR50, fire protection & 10CFR73, physical protection Agenda entl LENIS, R C Region 2, Office of Director 84/08/08 TUCKER Duke Power Co 3pp 26314 222 24% Fiche 50-000, 84/08/08. TUCKER, H B
- B40B200414 forwards draft safety evaluation of procedures generation package for emergency operating procedures Response to open items re writers guide & validation/verification programs requested within 30 days of itr receipt RIVENDARK,G W Operating Reactors Branch 4 84/08/09 TUCKER,H | Duke Power Co 2pp 26182 001 24X Fiche 50-269,84/08/09,8408200414

- --8408200424 Draft safety evaluation of procedures generation package Package should be revisud to address items in Section 2 \* NRC No Detailed Affiliation Gloven 84/08/09 Lipp 26182 003 24% Fiche 50-267.84/08/09.8408200414
- B40B300014 Forwards public version of Rev 13 to crisis mgt plan & revised emergency plan implementing procedures
  TUCFER.H B Duke Power Co 94/09/10 Record Services Branch (Document Control Desk) 21pp 26332 393 24X
  Fiche 50-000.84/08/10.8408300014
- --8408300021 Public version of Rev 13 to "Crisis Mgt Plan for Nuclear Stations " Buke Power Co 84/08/15 30pp 24333 010 21x

- 8408220071 Forwards three exemption requests from 10CFR50, App R. Section III G 2 requirements refire protection of safe shutdown capability, supplementing 83:024 initial request No add) fees necussary
  TUCKER H B Duke Power Co 84/08/14 DENTON H R Office of
  Nuclear Reactor Regulation. Director STOLZ, J F Operating Reactors
  Branch 4 4pp 26193 287 24X Ficho 50-269,84/08/14,8408220091
- 8408310121 Requests extension of time to respond to 840728 ltr re util ADBILOTET Requests extension of time to respond to 840/20 its to plans for establishing energency operations facility design consistent w/requirements of Suppl 1 to NUREG-0737 Extension requested due to judicial review of util appeal TUCKER. H B Duke Power Co 84/08/24 DENTON. H R Office of Nuclear Reactor Regulation. Director STOLT. J F Operating Reactors Branch 4 2pp 26322 243 24X Ficha 50-269.84/08/24,8408310121
- 1 Financial information
- 8408240224 Forwards Duke Power Co & North Carolina Municipal Power Agency 1 1989 annual repts TUCKER.H B Duke Power Co 84/08/16 DENTON,H R G Nuclear Reactor Regulation. Director 2pp 2623/ 137 Fiche 50-000,84/08/16.8408240224 define of
- --8408240242 "1983 Annual Rept LEE.W S Duke Power Co 03/12/ Fiche 50-000,84/09/16,8408240224 R3/12/31 4/no 26297 th7 248
- K Utility Final Safety Analysis Report (FSAR) & amends
- B408220201 Forwards updated FSAR for Dicense Nuclear Station Info brings FSAR up to date as of B31231 TUCKER.H B Duke Power Co 84/08/15 DENTON.H R Office of Nuclear Reactor Regulation. Director STOL7.J F Operating Read Branch 4 Ip 26191 023 24x Fiche 50-269.84/08/15, B408220201
- --8408220208 Updated FSAR for Oconee Nuclear Station
   Duke Power Co 83/12/31 180pp 26191 024 24x
  Fiche 50-269.84/08/15,8408220201
- P Operating license stage documents & correspondence
- 8408070389 Forwards "Extension of Retainer Lifetime to Four Cycles," for Ocones-Unit 3 u/results of exams of two retainers after three cycles Approval of four-cycle retainer usage requested before Dec 1984
  TAYLOR, J H Babcock & Wilcox Co 84/07/24 STOLZ, J | Operating Reactors Branch 4 1p 25945 252 24X Fiche 50-000,84/07/24, pages70380 8408070389
- 8408080888 Summary of 840712 meeting w/DEW Coners Oroup re non-nuclear instrumentation sys status Attendance list & viewgraphs KADAMBI,P Operating Reactors Branch 4 84/07/27 Operating Reactors Branch 4 36pp 25978 220 24% Fiche 50-000,84/07/27,8408080288

- 8408200149 Application for amend to Licenses DPR-38, DPR-47 f. DPR-59, updating Tech Spec 4 2 4 re reactor vessel matl surveillance to incorporate changes documented in BALM-1943 W/o stated to incorporate coords of the fee of tucker. H B Duke Power Co 84/08/02 BENION H R Office of Nuclear Reactor Regulation, Director STDL2.J F Operating Reactors Branch 4 3pp 26/33/286 24X Fiche 50-269,84/08/02,8408200149
- ---B408200155 Proposed Tech Spec 4 2 1 re reactor vessel matisus verillance NSHC evaluation encl > Duke Power Co B4/08/02 7pp 26133 289 24X Fithe 50-269,84/08/02.8408200149
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders or CPs re availability of Sugpl 1 to NUREO-0933, "Prioritisation of Generic Sarety Issues "Svc list encil EISENNUT D 6 Division of Licensing 84/08/06 Consolidated Edison Co of New York. Inc. 18pp 26129 238 24x Fishs 50-000.84/08/06.84080/0110
- 8408090317 Forwards nonthly status rept re plant specific backfitting activities for operating reactors \* license applicants for Jul 1984 Jul 1984 TREMBLAY.P P Operating Reactors Assessment Branch 84/ HOLAHAN.G M Operating Reactors Assessment Branch 13pp 25991 350 24% Fiche 50-000.84/08/06.8408090317 F4/08/06
- 8408200059 Application for amend to Licenses DPR-38.DPR-47 & DPR-55. AUBILUDIA Application for amend to ticenses DMR-38, DMR-47 & DMR-55, revising air lock testing frequency from quarterly to semiannually Fee encl TUCKER. H D Duke Power Co 84/08/08 DENTON, H R Office of Nuclear Reactor Regulation, Director STDLZ, J F Operating Reactors Branch 4 Jap 26133 296 247 Fiche 50-249,84/08/08,8408200059
- ~-8408200069 Proposed Tech Specs 4 4 1 5 2 (a), revising air lock testing frequency from quarterly to semiannually \* Duke Power Cd 84/08/08 5pp 26133 299 247 Filhe 50~269.84/08/08,840820059
- 8408220292 Forwards augmented response to Generic Ltr 83-28, Items 4 1 5 4 2 re reactor trip sys reliability vendor related mods 5 preventive maint & surveillance program for reactor trip breakers; respectively, per 831104 % 1230 ltrs
  TUCKER; H B Duke Power Co 84/08/10 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 4pp 26194 072 24% Fiche 50-269, 84/08/10, 8408220292
- 8408230527 Forwards payment for application fee re 840802 & 08 Tech Spec changes

  BARR, S Duke Power Co 84/08/15 DENTON H R Office of Nuclear

  Reactor Regulation, Director STOLZ, J F Operating Reactors Branch

  4 1p 26236 286 24% Fiche 50-000, 84/08/15, 8408230527
- 8408270339 Application for amend to Licenses DPR-38.DPR-47 & DPR-55. revising Tech Specs re reactor bldg purge sys.protection
  from inadvertent law temp overpressorization \* min operator
  staffing requirements
  TUCKFR, H B Duke Power Co 84/08/15 DENTON, H R Office of
  Nuclear Reactor Regularien, Director STOLZ, JF Operating Reactors
  Branch 4 Bpp 26244 307 24X Fiche 50-249,84/08/15,8408270339
- --8408270 145 Proposed Tech Specsichanging reactor bldg purge sys.
  protection from inadequate low temp overpressurization
  & min operator staffing requirements
  \* Duke Power Co 8408/15 14pp 26244 315 24X
  Fiche 50-269.84/08/15.8408270339
- B40B270160 Forwards Rev 4 to "Offsite Dose Calculation Manual," incorporating Catauba calculation info Rev submitted prior to submittal of seniannual radioactive officent release rept for Jul-Dec 1984
  TUCKER, H B Duke Fower Co 84/08/16 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2/pp 26279 112 24X Fiche 30-000, 84/08/16, 8408270160
- --8408270149 Rev 4 to "Bffsite Dose Calculation Manual " BIRCH-II L . HAMPTON J W Duke Power Co 84/07/18 26279 114 24X fiche 50-000.84/08/16.8408270160 84/07/18 37pp
- 8408270464 Forwards list of questions generated during preliminary review of pump & valve inservice testing Conference call should be arranged w/staff able to provide appropriate technical expertise STQLZ, J.F. Operating Reactors Branch 4 84/08/17 TUCKER, H.B. Duke Power Co. 10pp. 26277 210 24x Fiche 50-269, 84/08/17, 8408270464

- 8408270499 Forwards request for add1 info re NUREG-0737, Item III D 3 4 Control Room Habitability ' Response requested within 30
- Control Room Habitaurility Response requested Stimm 20 days of ltr receipt STOLZ.JF Operating Reactors Branch 3 84/08/17 TUCKER.H B Dute Power Co 3pp 26277 039 24X Fiche 50-269.84/08/17.
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & 408200275 Generic Ltr 84-20 to all licensees of operatir applicants for OLs re scheduling guidance for licensee submittais of reloads that involve unreviewed safety questions Svc list encl EISENIUT.D 6 Division of Licensing 84/08/20 Cor Edison Co of New York, Inc. 17pp 26276-244 24X Fiche 50-000.84/08/20.8498200275 84/08/20 Consolidated 26276 244 24X
- Q Inspection reports, IE Bulletins & correspondence
- 8408280241 Informs of delay until 860301 to complete mods required by IE Bulletin 79~14 Delay due to increase in total number of mods required mous required. TUCKER H B Duke Power Co 84/06/21 O'REILLY, J P Region 2. Office of Director 2pp 26262 241 24X Fiche 50-269.84/06/21. 8408280241
- 8408240416 Forwards Insp Repts 50-269/84-15.50-270/84-14 & 50-287/84-18 on 840611-0710 No violations or deviations noted DANCE.H C Region 2, Office of Director 84/07/19 TUCKER.H B Duke Power Co ip 26217 113 24X Fiche 50-269.84/07/19. R408240416
- --8408240421 Insp Repts 50-269/84-15,50-270/84-14 & 50-287/84-18 on 840611-0710 No noncompliance or deviations noted Major areas inspected operations, naint, surveillance, ESF, emergency drills & fuel handling BRYANT, J. SASSER, K., BROWNLEC, V.L. Region 2, Office of Director 84/07/19 &pp 26237 114 24X Fichs 50-269,84/07/19,8408240416
- 8408280361 Forwards Insp Repts 50-269/84-14,50-270/84-13 & 50-287/84-16 on 840619-21 No violations or deviations identified
  DANCE/H C Region 2, Office of Director 84/07/20 TUCKER
  Duke Fower Co 2pp 26282 239 24% Fiche 50-269,84/07/20. TUCKER, H B R408280361
- --8408280370 Insp Repts 50-269/84-14:50-270/84-13 & 50-287/84-16 on 840619-21 No violations or deviations identified Major area inspected emergency preparedness exercise DECKER.1 R , STANSBERRY, W W , CLINE, W E Region 2, Office of Director 84/07/06 9pp 26282 241 24X Fiche 50-267,84/07/20, 8408280361
- B407250229 IC Info Notice B4-57. "Operating Experience re Moisture Intrusion in Safety-Related Clectrical Equipment at Commorcial Power Plants " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229
- 8408280472 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-269/84-12, 50-287/84-14 LEWIS, R C Reg Duke Power Co Region 2, Defice of Director 84/08/01 TUCKE Co ip 26282 045 24% Fiche 50-269,84/08/01. TUCKER, H B 8408260472
- --8408280476 Responds to NRC 840622 ltr re violations noted in Insp Repts 50-269/84-12,50-270/84-12 & 50-287/84-14 Corrective actions Procedure OP/O/A/1510/10 revised to require neutron shield tank level prior to offsite shipments TUCKLR.H B Duke Power Co 84/07/20 O'REILLY.J P Region 2, Office of Director 4pp 26282 046 24X Fiche 50-269,84/08/01,8408280472 Office of Director 8408280472
- -8408280479 Forwards Insp Repts 50-269/84-12.50-270/84-12 & 50-297/84-14 on 840604-08 & notice of vigilation LEWIS.R C Region 2. Office of Director 84/06/22 TUCKER, H B Duke Power Cp 200 26282 050 24% Fiche 50-269, 84/08/01, 8408280472
- --8408280481 Natice of violation from 1nsp on 840404-08 \* Region 2, Office of Director 84/06/22 2pp 26282 052 24X Fiche 50-249,84/08/01,8408280472
- --8408280483 Insp Repts 30-269/84-12,50-270/84-12 & 50-287/84-14 on 840604-08 Noncompliance noted Pailure to verify presence & condition of neutron radiation moderator prior to shipping & failure to perform neutron radiation surveys NEDDINOTON.R E, JENKINS.O R Region 2, Office of Director 84/06/19 Spp 25282 054 24X Fichs 50-269.84/08/01,8408280472 Spp

- 8408010333 [E info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list end!
  JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26068 001 24% Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84~60, 'Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN, E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York Inc 123pp 26067 158 24% Fiche 50-000,84/08/06.8408010337
- 8408130149 Forwards IE Safeguards Insp Repts 50-269/84-17.50-270/84-16 & 50-287/84-19 on 840716-20 No violations or deviations identified
  DANGE:H C Region 2. Office of Director 84/08/07 TUCKER.H B
  Duke Power Co 2pp 26007 344 24X Fiche 50-269, 84/08/07,
  8408130149
- --8408130146 IE Safeguards Insp Repts 50-269/84-17.50-270/84-16 & 50-287/84-19 on 840716-20 No violation or deviations identified Major areas inspected security sys power supply & alarm station Details withheld (ref 105FR2 790 & 73 21) HOORE, D.C. HCGUIRE, D.R. Region 2, Office of Director 84/06 1p 24007 346 24X Fiche 50-269.84/08/07.8408130149
- B40B070120 IE Info Notice 84-61, "Depremented of Diver in PMR Refueling Cavity " Sec list end! JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
  GRACE.J N Division of GA, Safeguards & Inspection Programs (Post
  830103) 84/08/10 Gonsolidated Edison Co of New York, Inc
  125pp 26130 001 24X Fiche 50-000.84/08/10.8408070376 list encl
- 8408100009 IE Info Notice 84-63. "Defective RHR Replacement Piping " IOBIOCOOP IE Info Notice by Low.

  Syc list encl
  JORDAN:E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000.84/08/13.8408100009
- 8408100038 IE Info Notice 84-64. "BWR HPC1 Initiation Seal-In & Indication " Svc list encl JORDAN,E L Davision of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000.84/08/15,8408100038
- 8408100021 IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Syc list encl JURBAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 OOL 24X Fiche 30-000.84/08/16,8408J00021
- 8408100055 IE Info Notice 84-65. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Cansolidated Edison Co. of New York, Inc. 120pp 26276 001 24X Fiche 50-000.84/08/17.8408100055
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDANIC L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 122pp R6276 122 24% Fiche 50-000;84/08/17,8408140208
- 8408210142 IE Info Notice 84-66, "Potential Deficiency in Improperly Ratud Field Wiring to Solenoid Valves " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142
- R Periodic operating reports & related correspondence
- 8408220468 Monthly operating repts for Jul 1984 N/840815 ltr REAVIS, J A . TUCKER.H B Duke Power Co 84/07/31 17pp 26196 033 24X Fiche 50-269,84/07/31.8408220468
- S Reportable occurrences. LERs & related correspondence
- 8408300497 Suppl to Rev 1 to RO-287/83-13 containment isolation valve 308-5 declared inoperable due to leakage past seat.
  Investigation into valve failure conducted & diaphragm Duke Power Co & 84/08/22 Record Services Branch p 26314 071 24X Fiche 50-287, (Document Control Desk) 84/08/22,8408300497

- DOCKET 50-269 THREE MILE ISLAND MULLEAR STATION, UNIT 1

  F Security, medical energency of the protection plans
- 8408080243 Forwards IE Insp Rept 50-289/84-04 on 840212-0412 % notice of violation MARTIN,I T Division of Engineering % Technical Programs 84/07/18 #UKILL.H D General Public Utilities GPU Service Corp 2pp 25974 341 24% Fiche 50-289,84/07/18,8408080243
- ~~8408080250 Notice of Violation from this on 840212-0412
  \* Region 1. Office of Director 84/07/18 lp 25974 343 24x
  Fiche 50-289.84/07/18.8408080243
- --B408080256 IE Insp Rep+ 50~289/84-06 on B40212-0412 Violation noted failure to document engineering justification for "use-as-is" disposition of nonconforming items in area of fire protection/prevention NICHOLAS. H H Division of Engineering 5 Technical Programs PAOLINO.R J PAOLITY. F P Region 1. Office of Director B4/07/03 14pp 25974 344 24X Fiche 50-289.84/07/18, 8408080243
- 8408030088 Forwards fee for review & approval of tire protection alternate safe shutdown capability in response to NRC 840525 request Fee enci HUKILL-H D General Public Utilities - GPU Service Corp 84/07/30 MILLER, W O License Fee Management Branch 1p 25916 042 24% Fiche 50-287,84/07/30,8408030088
- 8408080131 Notification of 840815 meeting w/util & FEMA in Bethesda.MD to discuss resolution of offsite amargency planning deficiencies identified by FEMA during Billib exercise UAN VLIET.J Operating Reactors Branch 4 84/08/01 STOLZ,JF Operating Reactors Branch 4 2pp 25979 !!! 24Y Fiche 50-289,84/08/01,840808013!
- B40B090097 Notification of 840814 meeting w/util in Bethesda.MD to discuss fire protection requirements re-safe shutdown.fire areas vs fire iones & Rockbestos cable SILVER.H Operating Reactors Branch 4 84/08/01 STOLZ.J F Operating Reactors Branch 4 25971 255 24% Fiche 50-289.84/08/01.8408090097
- B40B090197 Notification or B40B16 meeting w/util & FEMA in Dethesda.MD to discuss resolution of official emergency planning deficiencies identified by FEMA during B31116 onnual exercise

  VAN VLIET, J Operating Reactors Branch 4 84/08/03 STOLZ, J F Operating Reactors Branch 4 2pp 25791 203 24X Fiche 50~2B9.B4/08/03.B408090199
- 8408233382 Rev 9 to Emergency Plan Implementing Procedure 1004 27. "Activation of Emergency Operations Facility" 
  \* General Public Utilities GPU Service Corp 84/08/08 31pp 26203 319 24% Fiche 50-289,84/08/08,8408233382
- 8408160165 Informs of refund of fees from 840727 application for exemption from certain annual exercise requirements of 10CFR50. App E & 840604 application to correct error in Tech Spec 3 & 7 Fee assessment info enci MILLER, 8 O License Fee Management Branch 84/08/10 HUKILL, H D General Public Utilities - GPU Service Corp 3pp 26124 382 247 Fiche 30~289.84/08/10. 18408160165
- 8408280179 Revised Emergency Plan implementing Procedures 1004 1 re unusual event, 1004 2 re alert \$ 1004 3 re site emergency W/transmittal & receipt form BROWN, N D General Public Utilities - GPU Service Corp 84/08/14 82pp 26275 333 24X Fiche 50-289.84/08/14,8408280179
- 8408310166 Revised Emergency Plan Implementing Procedures 1004 15, "Post-Accident RCS Sampling & 1004 33, "Handling High Activity Reactor Coolant Samples Under Accident Conditions " Wiftensmittel & receipt form KOUSEL.D J General Public Utilities GPU Service Corp 84/08/22 63pp 26319 176 24% Fische 50-289.84/08/22.8408310166
- G Adjudicatory correspondence
- 8408020208 Responds to order requesting comments on resolution of mgt concerns affecting restart NRC has not adequately resolved outstanding issues & 1979 shutdown order should remain affective indefinitely Served on 840802 GEKAS.6 M House of Rep DBB 714 84/06/05 PALLADING.N Commissioners ip 25898 009 24X Fiche 50-287.84/06/05.

- 8407130502 GPI V BEW LAWBUIT REVIEW AND ITS LFFECT ON TMI-1 General Public Utilities Corporation et al v The Bablock \* Wilcox Company, et al Thise Mile Island Novlear Station, Unit ; Docket 50-289
  - \* Office of Nuclear Reactor Regulation, Director MUREG-1020LD VQ1 84/06/30 152pp 25579 089 24% Fiche 50-289,84/06/30,8407130502
- 8408220362 Response to util comments on ASLB 840713 memorandum & order on lead intervenors 1 motion to partially exclude UCS from participation in mgt remand Certificate of Svc encl WEISS.E R Union of Concerned Scientists UEISS.E R Harmon & Weiss DSB 195 84/07/13 11pp 26193 032 24% Fiche 50-289.84/07/13.8408220362
- 8408010194 Comments on ASLB 840713 memorandum & order on lead intervenors Staff has no objection to assignment of lead intervenors provided that issue of NRC exam limited as previously ruled by ASLB Certificate of Svc encl OCLOBERG, J.R. Hearing Branch 2 DSB 688 84/07/26 5pp 25855 168 24% Fiche 50-289,84/07/26,8408010194
- 8408020040 Reply to licensee 840611 response to suppl to UCS petition to show cause to energency feedwater sys Util response evinces continuing ignorance & evision of substantive requirements Certificate of Svc encl WEISS.E R Union of Concerned Scientists DSB 691 84/07/31 Cffire of Nuclear Reactor Regulation. Director 10pp 25883 263 24X Fiche 50~287.84/07/31,8408020040
- 8408020042 Comments on 940713 memorandum toorder on lead intervenors to mation to partially exclude UCS from participation in mgt remand ASLB should exclude UCS from participation in Disckomp mailgram to leak rate issues W.Certificate of Svc BLAKE.E L Metropolitan Edison Co BLAKE.E L Shaw, Pittman, Potts to troubridge DSB 695 84/07/31 Atomic Safety and Licensing Board Panel 30pp 25880 274 24% Fiche 50-289,84/07/31, 8408020042
- 8408060201 First request for production of documents on or before 940816 Related correspondence DOROSHOW, J. BERNAREIL Three Mile Island Alort DOROSHOW, J. Christic Institute DSB 74/ 84/07/31 Atomic Safety and Licensing Board Panel 10pp 25925 319 24x Fiche 50-289,84/07/31. 8408060201
- --8408060224 First set of interrogatories to util Certificate of Svc encl DOROSHON, J., BERNABEI, L. Three Mile Island Alert DOROSHOW, J. Christic Institute 84/07/31 Atomic Safety and Licensing Board Panel 36pp 25925 329 24X Fiche 50-269,84/07/31,8408040201
- 840808024A Advises that proposed emergoncy exercise to be conducted on B41003 acceptable Region I will not participate in B40905 & 19 Pull-scale drills W/svc list Related correspondence MARTINA T Division of Engineering & Technical Programs DSD 828 84/08/01 HUKILL-H D General Public Utilities GPU Service Corp 3pp 25966 &97 24X Fithe 50-289.84/08/01.8408080246
- 8408070382 First request for production of documents by 840812 Certificate of Svc encl Related Correspondence DOROSHOW, J. BERNABIE; L. Three Mile Island Alert DOROSHOW, J. Christy, R. DSB 783 84708703 Office of the Executive Legal Director 12pp 25947 074 24X Fiche 50-287,84708703,8408070382
- 8408070408 first set of interrogatories Response by 840823 requested Certificate of Evc encl Related correspondence DOROSHOW. J. BERNABET. L. Three Mile Island Alert BERNABET. L. Government Accountability Project DSB 786 84/08/03 Office of the Executive Legal Director 189p 28742 152 24X Fiche 50 289,84/08/03.8408070408
- 8408070437 Proposed findings of fact, conclusions of law & brief in form of proposed initial decision to steam generator tepair Certificate of Syc encl
  CHURCHILL, B W Metropolitan Edison Co CHURCHILL, B W Shaw,
  Pittman, Potts & Trowbridge DSB 796 B4/08/03 111pp 25944 038
  24X Fiche 50-289,84/08/03,840807043/
- 8408270046 Order scheduling oral presontations on 840815 in Washington. BC re whether mgt concerns which lod to 1979 shutdown order sufficiently resolved Confirmation of participation requested by 840810 Served on 840806 CHILK.S J Office of the Secretary of the Commission BBB 298 84/08/06 14pp 26247 050 24X Fiche 50-289.84/08/06.8408270046
- 840B090415 Informs that NRC will part)cipate in aral presentation scheduled for 840B15 per Commission 840B06 profer Staff intends to present brief remarks & use remainder of time to respond to questions re restart GDLDBERG. J R Hearing Branch 2 DSB 886 84/08/08 CHILK.S J Office of the Secretary of the Commission ip 25982 217 24X Fiche 50-289,84/08/08,840B090415

- 8408090423 Advises that NG Kuhns & PR Clark will make principal 908040923 Advises that NG Kubns & PK Clark will make principal presentations on util behalf at 840815 Commission meeting, per Commission 840806 order TROUBRIDGE,G F Shaw. Pittman, Potts & Trowbridge TROUBRIDGE,G F Metropolitan Edison Co. DSB 882 84/08/08 CHILK.S J. Office of the Secretary of the Commission ip 25982 216 24x Fiche 50-209,84/08/08,8408090423
- 8408100133 Responds to 840607 request to postpone decision on restart until reactor safety & mgt integrity assured Oral argument scheduled for 840815 Restart will not be authorized until
- scheduled for B40813 restart w.t. Description of B40813 restart with safety assured MALBCH. M G Office of the General Counsel D58 889 84/08/08 SCHINK. A B . MCMANUS. A League of Women Voters of Pennsylvania 25791 024 24X Fiche 50-289.84/08/08.8408100133
- --8408100144 Requests restart decision be postponed until reactor safety & mgt integrity can be assured SCHINK.A B., MCMANUS,A League of Wamen Voters of Pennsylvania 84/06/07 PALLADINO,N J Commissioners 2pp 25991 025 2/ Fiche 30-289,84/08/08,8408100133
- 8408130300 Forwards 840725 status rept on licensee progress towards completion of required actions identified in Basic Energy Technology Assoc 830228 rept Svc list encl Related
- Technology Assoc Buveed rep.

  Correspondence
  BAUSER D B
  BAUSER D B
  Metropolitan Edison Co DSG 902 84/08/09 SMITH, I W WOLFE, S J.
  LINENDERGER, O Atomic Safety and Licensing Board Panel 22pp
  26010 281 24X Fiche 50-269.84/08/09.8408130300
- 8408130096 Motion for extension of time until 840817 to reply to liconsee 840731 motion to exclude UCS from particiption Certificate of Bvc encl JORDAN, V S Union of Concerned Scientists JORDAN, W S Harmo Weiss DSB 905 84708709 Atomic Safety and Licensing Hoar Panel 4pp 26011 108 24X Fiche 50-289,84708709,8408130396
- B408140035 Motion for extension of time to reply to licensee 840731 motion to exclude UCS from participation Granted for ASLB on 840813 Served on 840813 JORDAN, WS Union of Concerned Scientists JORDAN, WS Harmon & Heiss DSB 752 84/08/09 Atomic Safety and Licensing Board Panel 2pp 26044 207 24X Fichs 50-289,84/08/09,84081440035
- 8408140131 Informs that Commonwealth of PA will not file proposed fundings of fact or conclusions of law in proceeding but reserves right to participate on appeal,per 10CRF2 715(c) Certificate of Svc enc!
  AU, T Y Pennsylvania. Commonwealth of, DSB 960 84/08/09 #UBLFELS J. HETRICK,D L. LAMD.J C Atomic Safety and Licensing Board Panel 3pp 26047 016 24X Fiche 50-287.84/08/09,8408140131
- 8408200880 Expresses dissatisfaction w/staff conclusions re author in Suppl 9 to NUREO-0680 concerning RCS leak rate tests Conclusion that author involved or implicated in indictment misleading & unfair NRC conclusions should not be adopted SEELINGER.J L Affiliation Not Assigned DS8 163 84/08/09 PALLADINGIN J Commissioners 2pp 26137 138 24% Fiche 50-289,84/08/09,8408200580
- 8408140007 Reply to UCS 840726 comments on restart UCS comments reflect deep misunderstanding of procedural posture of restart proceeding Certificate of Svc encl
  TRCWDRIDGE, G F Metropolitan Edison Co TRCWBRIDGE, G F Pittman. Potts & Trowbridge DSB 953 84/08/10 16pp
  24X Ficha 50-289, 84/08/10, 8408140007
- 8408140010 Proposed findings of fact & conclusion of law re issue of steam generator repair Certificate of Svc encl
  BRADFORD.L Three Mile Island Alert DSB 934 84/08/10 21pp
  26044,107 24% Fiche 50~289,84/08/10,8408140010
- 8408140449 Petition for revocation of license on basis of deficient 40B140449 Petition for revocation of license on basis of defic character Licensee record of wrongdoing directly related to fundamental character flaws inherent within company Certificate of Svc encl WAMBACH, P C , SHAMAKER, J Pennsylvania, Commonwealth of, SORBILL, P Women's International League for Peace & Freedom 007 84/08/13 Commissioners 200pp 26061 023 24X Fiche 50-000.84/08/13.840B140449
- 8408140465 Response apposing 840806 order Commission should disqualify itself & refer restart decision to appropriate Federal Court Commission primary concern should not be protecting licensee
- Lewis, M DSR 016 84/08/13 Commissioners 2pp 24X Fiche 50-289,84/08/13,8408140465 26060 350

- 8408140474 Informs that ER Weiss will appear to present oral arguments on 840815 on behalf of UCS WEISS, E.R. Union of Concerned Scientists DSB 010 84708/13 CHILL, S.J. Office of the Secretary of the Commission 1p 26060 332 24% Fiche 50-289,84708/13.
- 8408140479 Second request for production of documents to GPU
  Certificate of Svc encl Related correspondence
  DDROSHOW.J , BERNABELL | Three Mile Teland Alert DDROSHOW.J
  Christy W DSO 032 84/08/13 Atomic Safety and Licensing Board
  Panel 14pp 26060 280 24X Fiche 50-289.84/08/13,8408140479
- 8408150139 Ack receipt of 840806 ltr presenting questions that ASLB answored during 840716 limited appearance session ASLB answers unchanged except that hearing was concluded on 840718 Served on 840814 WULFE.B J Atomic Safety and Licensing Board Panel DSB 047 84/08/13 CORRADI, J Affiliation Not Assigned 2pp 26046 24X Fiche 50-289,84/08/13,8408150139
- 8408200521 Protests ref to author in Suppl 5 to NUREG-0680 as one of five util mgt personnel involved or implicated in indictment Staff accusation improper & damaging to author reputation Pequests Withdrawal of findings KUNDER. G A Affiliation Not Assigned DSB 162 84/08/13 PALLADINO.N J Commissioners 2pp 26136 361 24X Fiche 50-289,84/08/13,8408200521
- B408200531 Protests treatment of author in Suppl 5 to NUREG-0680 re leak rate tests at TMI-2 US Atty conclusions in statement of fact misleading, out of context or erroneous Requests refusal of staff conclusions FLOYD, J R Affiliation Not Assigned DSB 161 84/08/13 PALLADING, N J Commissioners 2pp 26137 026 24X Fiche 50-289, 84/08/13, 8408200531
- 8408150145 Proposed correction to (ommission 840806 order Statement & implication in Page 2 footnote inaccurate UCS did not participate in initial hearings on mgt issues or in cheating hearings & was not directed to file findings by ASLU WEISS.E R Union of Concerned Scientists 858 041 84/08/14 3pp 26066 319 24X Fiche 50-289,84/08/14,8408150145
- B40Bi50458 Transmittal of "Risks to Safe Operation of TMI-1 Posed by Cleanup Operations at TMI-2" Svc list ancl Related correspondence BLAKE.E.L. Metropolitan Edison Co DSB 040 8 26048 271 24X Fiche 50-287.84/08/14,8408150458
- 8408150489 Informs of Commissioner Zech 840830-31 visit to facility Each party invited to send representablye to accompany Commissioner Response requested by 840824 Served on 840815 MONTGOMERY. J Commissioners DSB 058 84/08/14 Office of the Cxecutive Legal Director ip 24048 159 24% Fiche 50-289, 84/08/14.8408150489
- 8408200455 Expresses concern re cleanup of Unit 2 & possible restart of Unit 1 NRC should issue mandatory cleanup schedule & require adequate funding plan.plant demonstration of safe working order & proof of util integrity before restart FISCHER.D S Lancaster County, PA DSB 167 84/08/14 NRC No Detailed Affiliation Given 2pp 26136 290 24% Fiche 50-287.84/08/14.8408200455
- B40Bi703il Forwards Investigation Rept i-83-010 re TMI-2 alleged falsification of leak rate surveillance test data Served 84/08/15 PALLADINO,
- 8408170325 Motion for protective order on documents requested by TMI Alert concerning Disckanp mailgram which exceed or lie outside scope of mailgram & proceeding Related Outside scope of mailgran & proceeding Related correspondence TROWBRIDGE.Q F Metropolitan Edison Co TROWBRIDGE Pittman. Potts & Trowbridge DSB 087 84/08/15 and Licensing Board Panel 12pp 26113 335 24x Fiche 50-289,84/08/15,8408170325 TROWDRIDGE, Q F. Shaw, Atomic Gafety
- C-8408170330 Request for extension of time until 840904 to respond to TMI Alert 840731 first set of interrogatories Certificate of 8vc encl Related correspondences TROWBRIDGE, G. F. Metropolitan Edison Co. TROWBRIDGE, G. F. Shaw, Pittman, Potts & Trowbridge 84/08/15 Atomic 8afety and Licensing Board Panel 5pp 26113 347 24X Fiche-50-289, 84/08/15,8408170325

8408200561

- 8408220296 Urges that Commission not consider issue of restart unless & until all steps completed to ensure complete cleanup of TMI-2 & health & safety of public Served on 840921 HEINZ, J Senate DSS 202 84/08/15 PALLADINO, N J Commissioners 2pp 26193 081 24X Fichs 50-289,84/08/15.
- 8408170335 Proposed correction to Commission 840804 order Statement in Page 2 footnote & implications re UCS participation in hearings inaccurate Footnote should be expunded or modified to fully reflect facts HEISS.E R Union of Concerned Scientists DSB 0 26113 360 24x Fiche 50-289,84/08/16.8408170335 DSB 092 84/08/16 Jep
- 8408200448 First set of interrogatories & first request for production of documents re training Certificate of Svc encl Related correspondence SAUSER, D.B. Metropolitan Edison Co. BAUSER, D.B. Shaw, Pittman. Potts & Trombridge OSB 136 84/08/16 Three Mile Island Alert LOpp 26136 276 24% Fiche 50-289,84/08/16,8408200468
- 8408200515 First set of interrogatories & first request for production of documents re training Certificate of Svc encl Related of decoments re training co... correspondence BAUSER, D B Metropolitan Edison Co BAUSER, D B Shau, Pittman, Potts & Trowbridge BSB 155 84/08/16 Union of Concerned Scientists 9pp 26137 017 24% Fiche 50~289, 84/08/16, 8408200515
- 8408200557 Second set of interrogatories & request for production of documents pertaining to respond hearing on Dieckamp mailgram Certificate of Svc and Related correspondence BLAME.E L Metropolitan Edison Co DLAME.E L Shaw, Pittman, Potts & Troubridge DSB 147 84/08/17 Three Mile Island Alert 14pp 26137 030 24% Fishe 50-289,84/08/17,8408200557
- 8408200561 Memorializes changes to TMI Alert 840731 first request for production of decuments & first set of interrogatories to util discussed at 840813 meeting Svc list encl Related correspondence
  LEWIS.D R Shau, Pittman, Potts & Trombridge LEWIS.D R
  Metropolitan Edison Ca DSB 146 84/08/17 BERNABEI.L Government
  Accountability Project App 26/137 044 24X Fiche 50-289-84/08/17.
- B408220307 Forwards Harrisburg City Council Resolution 171-1984 objecting to TMI-1 restart & licensure of util to operate facility Served on 840821 W/Certificate of Svc BERRY, R B Harrisburg, PA B88 203 E4/08/17 PALLADING, R Commissioners 2pp 26194 067 24X Fiche 50-289, 84/08/17, R4092007
- 8408220258 Informs of agreement w/wording of 840813 discovery requests re interrogatories Verification that document requests & interrogatories not burdensome.oppressive or overbroad neverrogatories not surdensome, oppressive or overbroad requested

  BERNABEI, L. Government Accountability Project DERNABEI, L. Thi
  Mile Island Alert 050 193 84/08/20 LEMIS, D. R. Shaw, Pittm:
  Potts & Trombridge 1p 26193 140 24X Fiche 50-289, 84/08/20, 8408220288
- --8408220263 Opposition to licensee 840815 motion for protective order re TMI Alert first set of interrogatories & first request for production & motion for extension of time to reply to TMI Alert first set of interrogatories W/Certificate of Svc BERNABELL Three Hile Island Alert BERNABELL Government Accountability Project 84/08/20 Atomic Bafety and Licensing Board Panel 62pp 26173 141 24X Fichs 30-289.84/08/20.
- 840B220366 Forwards RD Parks 840724 ltm re concerns over NRC handling of allegations of mismanagement in cleanup. Ltm referred to in TMT Alert comments on Commission 840801 order BERNABELL Government Accountability Project DERNABEL. Three Mile Island Alert DSB 204 84/08/20 Atomic Safety and Licensing Board Panel 1p 26189 357 24X Fiche 50-289, 84/08/20, 8408220366
- --8408220373 Expresses concerns over NRC handling of allegations of mismanagement in cleanup NRC mastered art of objustation Response from Commission & forwarding of itr to ASLB requested
  PARKS.R D Affiliation Not Assigned 84/07/24, PALLADING, M J
  ROBERTS.T, ASSELSTING.J Commissioners 4pp 26:89 358 24: Fiche 50-289,84/08/20,8408220366
- 8408270176 Proposed findings of fact, conclusions of law & order in form of initial decision re steem generator tube repair MAGNER, M. R. Hearing Branch 4 058 297, 84/08/20 11pp 26243 280 24X Fichs 50-287,84/08/20,8408270176
- --8408270183 Brief in support of staff proposed findings of Pact restem generator tube repair

  MAGNER, M & Hearing Branch 4 84/08/20 26pp 26243 291 24%
  Fiche 50-289, 84/08/20, 8408270176

- B40B22035B Order extending time until B40B27 for Commission to act to review Director's Decision DD-84-18 Served on B40B21 CHILK'S J Office of the Secretary of the Commission DSB 194 84/08/21 Commissioners 1p 26191 354 24X Fiche 50-289.84/08/21.840B22035B
- 8408230207 Informs that licensee will make good faith effort to answer TMI Alert Document Request 7 % Interrogatories 2-9 % 42 Licensee reserves right to object to further efforts as burdensems & unreasonable W/svc list Related correspondence LEWIS.D R Shaw, Pittman. Potts & Trombridge LEWIS.D R Metropolitan Edison Co DSB 221 8408/21 8ERNABEI.L Government Accountability Pioject 3pp 26209 215 24% Fiche 50-289.84/08/21. 8408230207
- B40B230272 Reply to B40B10 & 20 proposed findings of fact & conclusions of law filed by TMI Alert & NRC staff, respectiyely Centificate of Svc encl CHURCHILL, B W Metropolitan Edstan Co CHURCHILL, B W Shaw, Pittman, Potts & Troubridge DSB 212 B4/08/21 20pp 262C 24X Fiche 50-289,84/08/21,B40B230272
- B10B240245 Notification of intent to attend B40B30-31 site visit & expresses objection to util ordentation UCS urges Commissionen to forego orientation Centificate of Svc encl WEJSB.E R Union of Concerned Stientists WEISB.E R Harmon & Weiss DSB 266 B4/0B/21 4pp 26223 062 24x Fiche 50-287.84/0B/21.840B240245
- 8408240251 Forwards Pages 16A & 16B of TMI Alert second set of interrugaturies re training issue Amend to Document Request 36 of second request for production to ref Interrogatories 28.29 & 30 recommended Related correspondence 28.27 & 30 recommended Related correspondence
  DERNABELL Oovernment Accountability Project BERNABELL Thre
  Mile Teland Alert DBB 265 84/08/21 BAUSER.D Show, Pittman,
  Potts & Trombridge 3pp 26222 355 24% Fiche 50-289,84/08/21, 8408240251
- 8408230325 Notice of withdrawal of appearance in proceeding Certificate 08 8vc encl SHOLLY, 9 C Union of Concerned Scientists DSB 256 3pp 26209 354 24% Fiche 50-287,84/08/22,8408230325
- 9408240250 Forwards supplemental pages for 840813 petition for revocation of license of GPU on basis of deficient revocation of the character character DRROSHOW, J Three Mile Island Alert DSB 258 84/08/22 Commissioners ip 26223 018 24% Fiche 50-000,84/08/22,
- --8408240257 Supplemental pages to petition for revocation of license on basis of deficient character Certificate of Svc encl # General Public Utilities GPU Service Corp 84/08/13 Atomic 84fety and Licensing Board Panel 43pp 26223 019 24x Fiche 50-000,84/08/22,8408240250
- 8408270072 Response opposing TMI Alert 840803 first set of interrogatories & motion for protective order re discovery to which staff objected Certificate of Svc encl Related correspondence GOLDBERG, J. R. Hearing Branch 2 DSB 307 84/08/22 Thr Island Alert 16pp 26247 167 24X Fiche 50~289,84/08/22,8408/2072 Three Mile 8408270072
- B408260175 Order extending time until B40907 for Commission to act to review ALAB-772 Served on B40823 CHILK 5 J Office of the Secretary of the Commission D98 335 84/08/22 Commissioners 1p 26259 055 24X Fiche 90-289.84/08/22 8408280175
- 8408280412 Comments on SCCY-84-237 to TMI-1 restart, per 840727 memo Cutting subcooling margin removes buffer of string error & time operator has to react to reading before problem LEWIS.M I lewis. M DSO 348 84/02/20 Office of the Secretary of the Commission 1p 26280 217 24X Fiche 50-289,84/08/22. 8408280412
- B408270115 Request for extension of time until 840712 to answer TM1 Alert second set of interrogatories Certificate of Svc encl Related correspondence BAUSER.D B Shaw, Pittman, Potts & Troubridge DSB 283 84/08/23 Atomic Safety and Licensing Board Panel App 26247 332 24X Fiche 50-289,84/08/23,8408270115
- 8408270145 Forwards TMI Public Health Fund "First Two Yrs Rept to Court & Public," per 840815 meeting re study unreleased by court & petition concerning expenditures from TMI Public COURT & Petition Concerning Capture Corp. B4/08/23 | BENTON: H. R. Office of Nuclear Reactor Regulation, Director App. 26245 137 | 24x Fiche 50-289,84/08/23.8408270145

- --8408270149 "First fwo irs Rept to Court & Public " Related info encl 4 THI Public Health Fund 84/08/23 44pp 26245 161 24X Fiche 50-289,84/08/23,8408270145
- 8408270359 Objection to valver of subcooling criteria & comments on NRC safety evaluation of subcooling criteria for actuating or throttling HPI Certificate of Svc encl HEISS,E R Union of Concerned Scientists WEISS,E R Harmon & Weiss DSB 316 84/08/24 15pp 26245 040 24x Fichs 50-289:84/08/24-8408270359
- 8408280493 Provides corrected date of 840817 to UCS 840713 response results comments on 830713 memorandum & order on lead intervenors & motion to partially exclude UCS from participation in mg t remand WEISS.E R Union of Concerned Scientists DSB 357 84/08/24 SMITH, I W . WDLFE.S J . (INCMBERGER.O Atomic Safety and Licensing Board Panel ip 26280 345 24X Fiche 50-289,84/08/24,8408280493
- 8408280148 Order extending time until 840907 for Commission to act to review Director's Decision DD-84-18 Served on 840827 CHILK, B. J. Office of the Secretary of the Commission DSB 320 84/08/27 Commissioners 1p. 26262 361 24X Fiche 50-289,84/08/27,8408280168
- 840828040? Responds to 840719 request for list of uncompleted restart shart-term actions Licensee action required on emergency planning offsity communications test & integrity of sys outside containment test program Related correspondence QDLDBERG. J R Hearing Branch 2 DSB 345 84/08/27 WEISS,E R Union of Concerned Scientists 1p 26280 216 24% Fiche 50-289.84/08/27,8408280409
- 8408280427 Ack receipt of 840821 ltr responding to Commissioner Zech 840814 memo re TMI-1 site visit Visit rescheduled for 840831 Clarification re Commission request for orientation concerning util organization provided Served on 840828 ZECH.L W Commissioners DSB 347 84708/27 WEISS,E R Union of Concerned Scientists WEISS,E R Harmon & Weiss 1p 26280 215 24X Fiche 50-289,84/08/27.8408280427
- 8408270012 Answer opposing licensee 840731 motion to partially exclude UCS from participation in mgt remand UCS participation on issues re Dieckamp mailgram & leak rate testing recommended Certificate of Svc encl
  OOLDDERO, J. R. Hearing Branch 2 DSB 346 84/08/27 Atomic Safety and Licensing Board Panel 8pp 26271 273 24X
  Fiche 50-289.84/08/27.8408290012
- 8408310423 Staff requirements memo summarizing 840815 oral presentations by parties re restart Commission requested Aamodt provide names of individuals appropriate to carry out epidemiological study CHILK.6 J Office of the Secretary of the Commission 84/08/27 DIRCKS, W J Office of the Executive Director for Operations 2pp 24363 047 24X Fiche 30-289,84/08/27,8408310423
- 8408310099 Order extending time until 840907 for Commission to act to review ALAB-774 Served on 840830 CHILK,S J Office of the Secretary of the Commission BSB 391 84/08/28 Commissioners Ip 26323 199 24X Fiche 50-289.84/08/28.8408310099
- B408310207 Informs that steam generator tube plugging issue will be resolved & repairs completed by 841004 8vc list entl Related correspondence
  BAUSER.D B Shaw, Pittman, Potts & Trombridge BAUSER.D B
  Metropolitan Edison Co DSB 431 B4/08/29 SMITH.I W. WOLFE,S J.
  LINENBERGER.O Atomic Safety and Licensing Board Panel. Spp
  26318 061 24X Fiche 50-289,84/08/29,8408310207
- H General correspondence
- 8408200274 Responds to 840626 ltr re penalties for excessive releases & regulations on effluent releases Purpose of 10CFR50 34a & 30.App I described
  BENTON.H R Office of Nuclear Reactor Regulation, Director 84/08/13 TAYLOR.F Z Affiliation Not Assigned 3pp 26142 337 24X Fiche 30-289,84/08/13.8408200274
- --8408200282 Questions competence of NRC inspectors, based on alleged failure of NRC inspector to recognize steam generator Concern expressed re release of Kr-85 & other effluents TAYLOR, F Z Affiliation Not Assigned 84/06/26 DIRCKE, W J Office of the Executive Director for Operations 3pp 26142 342 24X Fiche 50-289,84/08/13,8408200274

- B40B2R0390 Protests unfair treatment indicated in staff rept on NUREG-06B0, Suppl 5 re facility restart Conclusions re RCS leak tests unfair Refusal to endorse NRC conclusions requested Memo dtd 781020 to shift supervisors encl FLGYD. J. R. Affiliation Not Assigned 84/08/13 PALLADIND. N. J. Commissioners 2pp 26189 336 24X Fiche 50-289,84/08/13. BANB290390
- 8408230436 Responds to 840527 ltr expressing concerns re scope of TMI-1 restart proceedings Issues relied by Inquirer newspaper irrelevant to restart Proceeding addressed adequacy of plant operating maint & administrative procedures
  DENTON: HR Office of Nuclear Reactor Regulation, Director 84/08/16 VANCE. L.S. Affiliation Not Assigned 10pp 26237 266 24X Fiche 30-289,84/08/16,8408230436
- --8408230440 Requests response to encl LS Vance 840629 ltr re TMI-1 restart proceedings WENGER.N W Pennsylvania, Commonwealth of, 84/07/17 PALLADINO, N Commissioners 9pp 26237 275 24X Fiche 90-289,84/08/16.8408230436
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8408020137 Forwards Update 3 to TMI-1 updated F8AR Update reflects changes & analyses since 630718 update Chapter 11 update withheld HUKILL.N D. General Public Utilities OPU Service Corp. 84/07/DENTON.H R. Office of Nuclear Reactor Regulation, Director 19 29880 148 24X Fiche 50-289.84/07/26,8408020137
- --8408020141 Update 3 to TMI-1 updated FSAR \* Oeneral Public Utilities - GPU Service Corp 84/07/31 100pp 25880 149 24X Fiche 50-289,84/07/26.8408020137
- P Operating license stage documents & correspondence
- B40B160060 Forwards request for add1 info re DMR & technical evaluation rept Response requested within 30 days of itr receipt STOL7.JF Operating Reactors Branch 4 84/07/18 HUWILL.H D General Public Utilities GPU Bervice Corp App 26128 215 24X Fiche 30-289,84/07/18.8408160860
- 8408080438 Forwards request for add1 info re pipe stresses for high energy lines Response requested by 840730 to maintain VCB 10CFR2 20A petition decision review schedule STOLZ.JF Operating Reactors Branch 4 84/07/24 HUKILL.H D Ceneral Public Utilities OPU Service Corp 5pp 25977 177 24 Fiche 50-289.84/07/24.8408080438
- B408080288 Summary of B40712 meeting w/B&H Dwners Group re non-nuclear instrumentation sys status Attendance list & viewgraphs encl KADAMBI,P Operating Reactors Branch 4 84/07/27 Operating Reactors Branch 4 36pp 25978 228 24% Fiche 50-000,84/07/27, B408080288
- 8408030006 Forwards responses to NRC questions re emergency feedwater sys seismic interaction, per util 840716 submittal HUKILL.H D General Public Utilities - OPV Service Corp STGLZ.J F Operating Reactors Branch 4 4pp 25906 015 24X Fichs 50-289,84/07/30,8408030006
- 8408050413 TMI-1 RESTART An Evaluation Of The Licensee's Management Integrity As It Affects Restart Of Three Mile Island Unit 1 Dacket 50-289 \* Division of Licensing NUREO-0680 S05 84/07/31 179pp Available at NRC \$6.00 25937 102 24X Fiche 30-289,84/07/31. 8408060413
- 8408070280 Informs of completed mod to intermediate bldg flood protection, allowing 25 indutes w/o operator action before emergency feedbater components affected HUMILL.H D General Public Utilities OFU Service Corp 84/08/01 STOLZ.J F Operating Reactors Branch 4 3pp 25948 106 24% Fiche 50-289, 84/08/01 8408070280
- 8408080477 Informs of approval of request for withholding "Summary Info Package RCS Coolant Inventory Trending W/Reactor Coolant Pumps Operating," from public disclosure (ref iOCFR2 790) 840820 J F Operating Reactors Branch 4 84/08/01 HUKILL, H D General Public Utilities - GPU Service Corp 5pp 25976 054 24X Fiche 50-289,84/08/01.8408080477
- 840807023B Forwards analysis providing supplemental justification for Tach Spec Change Request 135.Rev i.as discussed w/C Nichols & D Dilanni of PRC Analysis demonstrates explosion resistance of waste gas haldup sys under worst conditions HUXILL.H D General Public Utilities 0PU Service Corp 84/0B/02 BTDLZ.J F Operating Reactors Branch 4 7pp 25748 32B 24X Fiche 50-287.84/08/02.8408070238

- 8408070110 Generic Ltr 84-i9 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioratization of Generic Safety Issues" Svc list encl
  EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X
  Fiche 50-000/84/08/06/8498070110
- 8408130343 Advises of intent to revise environ qualification program to include condensate storage tank valves to condenser hotwell & condensate storage tank cross connect valves, in response to NRC 840625 );
  HUKILLIH D General Public Utilities GPU Service Corp 84/08/06 STOLZ/JF Operating Reactors Branch 4 2pp 26010 318 24X Fiche 50-289,84/08/06.8408130343
- B408160285 Forwards handuritten notes from 840320-21.0507-08.0625 & OBO6 environ qualification file audits All emergency feedwater file deficiencies resolved & sys environmentally qualified STOL2.J F Operating Reactors Branch 4 84/08/07 WEISS.E R Harmon & Weiss 59pp 26126 170 24X Fiche 50-289.84/08/07.8408160285
- 8408310305 Forwards Amend 98 to License DPR-50 & safety evaluation Amend revises Tech Spec definition of operable & operablity to assure preservation of single failure criterion for safety sys Notice of issuance will be in next FR BTOLZ.JF Operating Reactors Branch 4 84/08/07 HUKILL.H D General Public Utilities GPU Service Corp 4pp 26350 240 24X Fiche 30-289.84/08/07.8408310305
- --8408310308 Amend 98 to License DPR-50, revising Tach Spec definition of operable & operability to assure preservation of single failure criterion for safety sys STOL7.JF Operating Reactors Branch 4 84/08/07 15pp 26350 244 24% Fiche 50-289,84/08/07.8408310305
- --B408310311 Bafety evaluation supporting Amend 98 to License DPR-50

   Office of Nuclear Reactor Regulation. Director 84/08/07 3pp
  R6350 259 24X Fiche 50-289,84/08/07,8408310305
- 840Bi30218 Forwards "PRA of Dffsite Releases Initiated by Toxic Chemical Release," per NUREG-0737. Item [II D 3 4
  Transportation of offsite chemicals in vicinity of facility will not pase undue risk to control room perator HUKILL-H D General Public Utilities GPU Service Corp B4/08/08
  STOLZ-J F Operating Reactors Branch 4 2pp 2400B 045 24X
  Fiche 50-287,84/08/08.8408130218
- --B408130225 "PRA of Offsite Releases Initiated by Toxic Chemical Release," final rept FENSTEPHACHER, HUBBARD, F. R., CALASRESE, R. V. Pickard, Lowe & Garrick, Inc. PLG-0370 84/07/30 118pp 26008 067 24X Fiche 30-289,84/08/08,8408130218
- 8408140406 Requests immediate implementation of Amend 78 to License DPR-50 to avoid administrative problems in Tech Spec change requests & subsequent amends HUXILL.H D General Public Utilities ~ GPU Service Corp 84/08/08 STOLZ.J F Operating Reactors Branch 4 19 26050 355 24X Fiche 50-289.84/08/08,8408140404
- 8408140411 Forwards corrected Tech Spec Section 6 16, "Post-Accident Sampling Programs" & Table 4 1-1 re instrument survoillance requirements in response to NRC request for changes to 840604 Tech Spec Change Request 115
  HUKILL-H D Qeneral Public Utilities QPU Service Corp 84/08/QB STOLZ-J F Operating Reactors Branch 4 1p 26048 399 24X
  Fiche 50-287,84/08/08.840B140411
- --B408140415 Corrected Tech Spec Change Request 115.adding phrases to clarify Tech Spec Section & 16. "Post-Accident Sampling Programs." (NURES-0737, II B 3 & II F 1 2) & Table 4 1-1 re instrument surveillance requirements \*\* General Public Utilities GPU Service Corp 84/08/OB 2pp

- --8408300237 Mod P.extending period of performance to 840915. to
  "Clinical Response to Chronic Stress in IMI"
  BAUM.A Uniformed Services Univ of Health Sciences HAGAN, I F
  Division of Contracts FII B-9008 84/08/14 ip 26315 342
  24X Fiche 50-289.84/08/14.8408309233
- 8408220218 Forwards Page 1 of Encl 10 inadvertently omitted from 840629 submittal re-polities for employee gintection from distrimination per 100FR\$0.7% polities for adequate, accurate corporate communications HOKILL.NID General Public Utilities GPU Service Corp. 84/08/16 EISENHUT.D G. Division of Licensing 2pp. 26194-051 24X Fiche 50-289,84/08/16.8408220218
- B40B220363 Forwards response to request for add1 info is control of heavy loads mods.per NUREG-0612 resulting from discussions w/Frankish Research Ctr & Rev O to Procedure 1408-6.
  "Procedure for Inso of Wire Rope or Synthetic Slings "
  MUXILL.N D General Public Utilities GPU Service Corp 84/08/16
  E16ENHUT, D O Division of Licensing App 24189 324 24X
  Fiche 50-287,84/08/16.8408220363
- --B40B220365 Rev O to Procedure 140B-6. "Procedure for Insp of Wire Rope or Synthetic Blings " NELBON.M A , TODLE.R General Public Utilities - GPU Bervice Corp 83/10/11 5pp 26189 330 24% Fiche 50-289.04/08/16.8408220363
- 8408240167 Informs of intent to provide response to NRC questions re DHR within 30 days of receipt of technical evaluation rept HUXILL.H D General Public Utilities - GPU Service Corp 84/08/17 STOL7.J F Operating Reactors Branch 4 ip 26228 178 24X Fiche 50-289,84/08/17.840824016/
- 8408270467 Advises that review of raiculations transmitted by 820623 & 840615 ltrs re hot leg restraints under asymmetric LOCA loads completed Calculations resolve NRC 840327 concerns & acceptable STOLZ, J F Operating Reactors Branch 4 84/08/17 HUKILL, H D General Public Utilities GPU Servico Corp 4pp 26277 206 24x Fiche 50-287, 84/08/17, 84088270467
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list enc: EISENWIT.D G Division of ticensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 28276 244 24X Fiche 90-000.84/08/20.8408200275
- B40B2B017B Forwards master list of electrical equipment located in harsh radiation environ, radiation qualification info for components 5 resolution of equipment items for which radiation documentation incomplete, per B00B0B itr WLESON, R F General Public Utilities GPU Bervice Corp 84/08/23 EIBENBUT, D 9 Division of Licensing 19pp 262/3 090, 24x Fiche 50-289,84/08/23.8408280178
- 8408310238 Forwards "Review of Dose Assessments at IMI to Recommendations for Future Research " Printed ropt summaries to 840829 pross release encl BERGER, B. Berger, D. 84/08/27 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 7pp 26316 293 24X Fiche 50-289,84/08/27.8408310238
- --8408310237 "Review of Dose Assessments at TMI & Recommendations for Future Research"

  DEVEAJ TMI Public Health Fund 84/08/15 2/0pp R6316 300 24% Fiche 50-249,84/08/27,8408310238
- 8408310183 Forwards TMI Public Health Fund rept, "Review of Dose Assessments at TMI & Recommendations for Future Research" CLARK,P R General Public Utilities - GPU Bervice Corp 84/08/28 DENTON,HR GPFice of Nuclear Reactor Regulation, Director 1p R4328 281 24x Fiche 50-R89,84/08/28,8408310183
- --8408310157 "Review of Dose Assessments at THT & Recommendations for Future Research " BEYEA.J TMI Public Health Fund 64/08/15 283pp 26383 283 24X Fichs 50-269,84/08/28.8408310153
- G Inspection reports: IE Bulletins & correspondence
- 0408080243 Forwards IE Insp Rept 50-209/84-06 on 040212-0412 & notice of virilation
  MARTIN.T T Division of Engineering & Technical Programs 84/07/18
  HUKILL.H D General Public Utilities QPU Service Corp 2pp
  25974 341 24X Fiche 50-289.84/07/18.8408080243
- --8408080250 Notice of violation from thep on 840212-0412 \* Region 1. Office of Director 84/07/18 1p 29974 343 24X Fiche 50-289,84/07/18,8408080243

- --B4080B0254 IE Insp Rept 50-2B9/B4-06 on B40212-0412 Violation noted failure to document engineering justification for "use-as-1s" disposition of nonconforming items in area of fire protection/prevention NICHOLAS H H Division of Engineering & Technical Programs PAOLINOLR J. PAULITY. F P. Region 1. Office of Director 84/07/05 14pp 25774 344 24% Fiche 50-2B9.84/07/18.84080B0243
- 8408080481 Forwards IE Insp Rept 50-289/84-14 on 840521-0601 No vialations observed MARTIN.T T Division of Engineering & Technical Programs 84/07/16 HUXILL.H O General Public Utilities GPU Service Corp 2pp 25975 172 24X Fiche 50-289.84/07/18,8408080481
- --B408080470 iE Insp Rep+ 50-289/84-14 on 840521-060) No violations noted Major areas inspected licensee action on previous insp findings, restart preoperational test program, including procedure review & hot functional testing NICHOLAS, H. WEN, P. FINKEL A Region 1. Office of Director B4/07/09 7pp 25975 174 24x Fiche 50-289,84/07/18,8408080481
- --8408150271 IE Insp Rept 50-289/84-17 on 840605-0703 No violations noted Major areas inspected plant operations inadvertent partial engineered safeguards actuation sys, maint activities, followup of LER & restart valve lineups YOUNG.F., BAUNACK, W., CONTE.R. Region 1. Office of Director 84/07/16 13pp 26076 339 24X Fichs 50-289,84/07/26,8408150264
- 8407250229 IE info Notice 84-57. "Operating Experience to Moisture Intrusion in Safoty-Related Electrical Equipment at Commercial Power Plants " Svc list encl JDRDAN.E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of Now York, Inc 119pp 25865 047 24% Fiche 50-000.84/07/27, 8407250229
- 8408030122 Requests listed design info re mods to RCS head & high point vents as followup to 840723-26 insp (90-289/84-22)

  MARTIN T T Division of Engineering & Technical Programs 84/07/27 RUKILL. R D General Public Utilities OPU Service Corp 85916 115 24X Fiche 50-289.84/07/27.8408030122
- 8408030104 Ack receipt of 840703 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-289/84-03 Corrective actions will be examined during future insp MARTIN.T T Division of Engineering & Technical Programs 84/07/30 HUKILL.H D General Public Utilities GPU Service Corp 4pp 25904 303 24X Fiche 50-289/84/07/30.8408030104
- ---8408030107 Suppls response to NRC 840214 ltr re violations noted in IE
  Insp Rept 50-289/84-03 Forwards update to list of
  outstanding items & Technical Data Rept \$63. "THI-1.PostAccident RMA-5 Grab Sampling & MAP-5 Filter Removal "
  HUXILL.II D General Public Utilities GPU Service Corp
  84/07/03 MURLEY.IT E Region 1. Office of Director 3pp
  25904 307 24X Fiche 50-289.84/07/30.8408030104
- --840803010B Rev O to "TMI-1,Post-Accident RMA-5 Grab Sampling & MAP-5 Filter Removal Radiological Analyses " \* General Public Utilities - OPU Service Corp TDR 543 B4/07/02 26pp 25904 310 24X Fiche 50-289,84/07/30,8408030104
- B40B200014 Forwards IE Insp Rept 50-289/84-16 on 840604-08 & notice of violation MARTIN.T T Division of Engineering & Technical Programs B4/07/31 HUKILL-H D General Public Utilities GPU Service Corp 2pp 26140 232 24X Fiche 50-289,84/07/31,8408200014
- --8408200017 Notice of violation from insp on 840604-08 \* Region 1, Office of Director 84/07/31 3pp 26140 234 24X Fiche 50-289,84/07/31,8408200014
- --8408200023 IE Insp Rept 50-287/84-16 on 840604-08 Noncompliance noted chemistry technician entered radiation area ω/o dose rate instrument or Xetex WHITE, J.R., BELL, J. KOTTAN, J. Region 1. Office of Director 84/07/26 29pp 26140 237 24X Fiche 50-289,84/07/31,8408200014
- 8408080300 Advises that response to notice of violation re false statements concerning retraining & qualification program will be submitted within 30 days after release of ref info Check for \$40,000 re operator cheating and HUKILL,H D General Public Utilities QPU Service Corp B4/08/02 DEYQUNG.M C Director's Office, Office of Inspection and Enforcement ip 23765 306 24X Fiche 50-289,84/08/02,8408090300

- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York Inc 122pp 26068 001 24% Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list encl JORDAN.E U Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000.84/08/06.8408010337
- 8408100123 Informs that util response date incorrectly noted in NRC 840709 transmittal of SALP rept Correct util response date was 840606 fMI hearing svc list encl STAROSTECKLIR Division of Project & Resident Programs 84/08/06 HWKILLH D General Public Utilities GPV Service Corp 25988 257 24x Fiche 50-289,84/08/06,8408100123
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svr list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc. 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- B408130406 Forwards IE Insp Rept 50-289/83-20 on B30711-0909 re RCS leak rate tests during Apr 1978 Mar 1979 Revised encl insp rept pages include add1 info obtained during 840208 site visit

  MARTIN. T Division of Engineering & Technical Programs B4/08/08 HUKILL-H D General Public Utilities GPU Service Corp 5pp 26007 086 24% Fiche 50-289.84/08/08.8408130406
- --B40B130410 Errata to IE Insp Rept 50-289/B3-20 on 830711-0909 Noncompliance nated failure to follow station procedures & regulatory requirements CHUNG.J W. MEN.P.C., VANTERPOOL.E.C. Region 1. Office of Director 83/09/21
- --8408130417 Forwards revised IE Insp Rept 50-289/83-20 re reanalysis of timing charts & understanding of computer data handling during RCS leak rate testing CHUNG, U W Division of Engineering & Technical Programs 84/02/24 MARTIN, T Division of Engineering & Technicak Programs ip 26007 316 24X Fiche 50-289,84/08/08.8408130406
- B40B070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list bincl GRACE,J N Division of OA, Safeguards & Inspection Programs (Post B30103) B40B010 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000:84/08/10.840B070376
- B40Bi00007 IE Info Notice B4-63, "Defective RHR Replacement Piping"
  Svc list encl
  JORDAN, E L Division of Emergency Preparedness & Engineering
  Response (Post B30103) B4/0B/13 Consolidated Edison Co of New
  York, Inc. 117pp 26177 218 24X Fiche 30-000, 84/0B/13, 840B100009
- 8408100038 FE Info Notice 84-64, "DWR HPCI Initiation Beal-In & Indication " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038
- 8408170311 Forwards Investigation Rept 1-82-010 re TMI-2 alleged falsification of leak rate surveillance test data Served on 840816 HAYES B B Office of Investigation DSB 094 84/08/15 PALLADING. ROBERTS. ASSELSTINE Commissioners 727pp 26114 001 24X Fithe 50-289.84/08/15.8408170311
- B40B20001B Board Notification 84-143 forwards Oft of Investigation Rept 1-83-010 on alleged falsification of TMI-2 leak rate surveillance test data Rept consistent w/Suppl 5 to NUREO-0680 re TMI-1 restart EISENHUT. D Ø Division of Licensing 84/08/15 PALLADING, ROBERTS, ASSELSTINE Commissioners 3pp 26/300 145 24X Fiche 50-289,84/08/15,8408200018
- 840Bi00021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24% Fiche 50-000,84/08/16,8408100021
- B40B100055 IE Info Notice B4-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN.C L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

- HOB140208 IE Info Notice 84-67. Recent Snubber Inservice Testing W/
  High Failure Rates "Svc list encl
  JORDAN.E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/17 Consulidated Edison Co of New
  York, Inc 122pp 26276 122 24X Fiche 50-000.84/08/17,8408140208
- 3408240104 Ack receipt of 840802 ltr & partial payment of \$40,000 for civil penalty proposed on 830702 Corrective actions will be examined during future insp AXELRAD. J A Enforcement Staff 84/08/17 CLARK.PR General Public Utilities GPU Service Corp 2pp 26255 350 24X Fiche 50-289,84/08/17,8408240104
- B40B210142 IE Info Notice 84-6B. "Potential Deficiency in Improperly Rated Field Wiring to Solemoid Valves " Svc list encl JORBANJE L Division of Emergency Preparedness & Engineering Response (Post 830103) a4/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000.84/08/21.8408210142
- н Periodic operating reports & related correspondence
- B408070334 "TMI Aquatic Study Monthly Rept for June 1984 " W/GPU 840717 ltr " EA Engineering, Science & Technology, Inc RESSLER, H C General Public Utilities GPU Service Corp 84/06/30 HICKEY.C NRC No Detailed Affiliation Given 14pp 25971 043 24X Fiche: 50-289: 84/06/30. 8408070334
- B408240066 Monthly operating rept for Jul 1984 W/B40816 ltr 8MYTH.C W. HUKILLIN D. General Public Utilities ~ QPU Service Corp B4/07/31 MCDDNALD.W C. Office of Resource Management. Director 11pp 26236 141 24X Fiche 50-289:84/07/31.8408240046
- 8408230425 Submits THI Program Off weekly status rept for 840805-il ORANT,P J TMI Program Office 84708/13 DENYOUMH R Office of Nuclear Reactor Regulation, Director SNYDER.B J TMI Program Office 12pp 26230 229 24x Fiche 50-289,84/08/13,8408230425
- S Reportable occurrences, LERs & related correspondence
- 8408090144 LER 84-003-00 on 840702.12 penetrations in instrument shop floor identified as not having fire-rated penetration seals Caused by inadequate supervision of contractor personnel during installation Insp procedure changed W/840801 ltr OTTO, S M. HUKILL-H D Openral Public Utilities CPU Service Corp 84/08/01 6pp 29993 145 24X Fiche 50-289.84/08/01.8408090144
- 8408140182 LER 84-004-00 on 830402, tube A-135-72 not plugged & tube A-134-74 found in tube A-135-72 location Correct tube plugged & all other tubes verified M/840807 ltr STCZECH:R A: HUKILL:H D. General Public Utilities OPU Service Corp. 84/08/07 App. 26106 310 24X Fishe 50-289, 84/08/07, 8408160182
- B40B2103B3 PNO-1-84-049 on B40714.licensee reported five missing lower head steam generator plugs Licensee working w/ Westinghouse to develop method of testing plugs Evaluation continuing CONNER.F Region 1, Office of Director 84/08/15 lp 26180 251 24X Fiche 50-289.84/08/13,8408210383
- 8408270195 LER 84-005-00 on B40716, diesel generator differential relays discovered potentially incapable of withstanding seismic svent Caused by improper application of relays in original plant design Relays will be replaced H/H40815 ltr KNIGHT.H R. HUKILL,H D. General Public Utilities GPU Service Corp. 84/08/15 4pp. 26257 332 24X Fiche. 50-289. 84/08/15. B408270195
- 8408230077 Summary of 840807 operating reactor events meeting re occurrences since 840719 meeting List of attendees, significant elements & status of previous assignments encl CRUTCHFIELD.D Assistant Director for Safety Assessment 84/08/16 EISENHUT,D 0 Division of Licensing 20pp 26233 247 24X Fiche 50-000,84/08/16.8408230077
- 8408300503 LER 84-004-00 on 840718 & 17. during performance of surveillance procedure, setpoints for three IIE 27H relays (27) in 4160-volt bus IE (EA) found but of callbr Caused by drift out of tolerance Faulty relays replaced W/840821 ltr HUKILL, HD General Public Utilities OPU Bervice Corp. 84/08/21 5pp 26314 001 24X Fiche 50-289.84/08/21,8408300503
- T Hearing transcripts on non-antitrust matters
- 8408290265 Forwards JR Spang 840820 testimony in conjunction w/840815 hearing re mgt integrity. Testimony illustrates philosophical shortcomings of phrase mgt integrity SPANGJ R American Society of Utility Investors DSB 375 84/08/24 CKILKS J Office of the Secretary of the Commission ip 26290 324 24% Fiche 50-287,84/08/24,8408290265

- --8408270267 Testimony of American Soc of Util Investors presented by JR Spang re mgt integrity SPANG, J R American Society of Utility Investors 84/08/20 4pp 26270 325 24X Fiche 50-289,84/08/24,8408290265
- DOCYET 50-293 PILGRIM NUCLEAR POWER STATION, UNIT I F Security, medical, emergency & fire protection plans
- 8408230082 Forwards IE Insp Rept 50-293/84~17 on 840605-0716 No violations noted Possible weakness in radiological controls program hoted STAROSTECKI, R Division of Project & Resident Programs 84/08/03 HARRINGTON N D Boston Edison CO 2pp 26214 128 24X Fiche 50-293.84/08/03.8408230082
- --B408230091 IE Insp Rept 50-293/84-17 on 840405-0714 No violations noted Major areas inspected plant operations including followup of previous findings operational safety verification, plant events & LERs
  JOHNSON, J. MORRIDE, H. LIPINSKI. D. Region 1. Office of Director 84/08/01 15pp 26214 130 24X Fiche 50-293.84/08/03.8408230082
- 8408170179 Natification of Significant Licensee Meeting 84-71 on 840814 w/util in King of Prustia.PA to discuss upgrading site security program KUSINER.W L. Region 1, Office of Director 84/08/07 Region 1, Office of Director 2pp 26/34/386 24% Fiche 50-293.84/08/07, 8408170179
- 8408140251 Application for amend to License DPR-35, changing Tech Specs to replace Halon 1301 sys in place of CO2 sys in cable spreading room HARRINOTON.W D Boston Edison Co 84/08/09 VASSALLO.D B Derating Reactors Branch 2 2pp 24054 340 24x Fiche 50-293.84/08/09.498808140251
- --8408140256 Proposed Tech Spec changes, substituting Halon 1301 sys in place of CO2 sys in cable spreading room \* Boston Edison Co 84/08/09 4pp 26054 342 24X Fiche 50-273, 84/08/09, 8408140251
- 8408170011 Notifies of fees due for consideration of requests for exemption from fire protection requirements including alternate safe shutdown capability Description of 10CFR170 fee requirements & list of applications & fees encl MILLER.W O License Fee Management Branch 84/08/09 HARRINOTON.W D Boston Edison Co 4pp 26135 351 24X Fiche 30-273.04/08/09.0408170011
- B408160374 Forwards proprietary "Conceptual Design Description for Pilgrim Nuclear Power Station Emergency & Plant Info Computer (CPIC) Safety Parameter Display Sys (SPDS)," per B31026 commitment & TMI Action Item I D 2 Rept withheld HARINGTON, W D Boston Edison Co 84/08/10 VASSALLO, D B Operating Reactors Branch 2 ip 26091 192 24X Fiche 50-293,84/08/10,8408160374
- 8408160368 Forwards Rev I to "Detailed Control Room Design Review Program Plan." per NUREG-0737, Item I D I & Suppl I to NUREG-0737
  HARRINGTON.W D Boston Edison Co 84/00/14 VASSALLO, D Departing Reactors Branch 2 10 26090 159 24X
  Fiche 50-293,84/08/14,8408160368
- --B40B160369 Rev 1 to "Detailed Control Room Design Review Program Plan " \* Noston Edison Co B4/06/30 120pp 26090 160 24X Fiche 30-293,84/08/14,8408160368
- 8408280267 "Pilgrim Nuclear Power Station Joint Emergency Plan Exercise" \* Boston Edison Co 84/08/15 84pp 26282 335 24X Fiche 50-273,84/08/15,8408280267
- B408310396 Forwards Amend 76 to License DPR-33 & safety evaluation Amend revises fire protection Tech Specs re penetration fire barriers LEECHIP H Operating Reactors Branch 2, B4/08/22 HARRINGTON, W D Botton Rdison Co 2pp 26350 228 24% Fiche 50~273,84/08/22, R408210394
- --8408310430 Amend 76 to License DPR-33 revising fire protection Tech Bpacs re penetration fire barriers to reflect changes made to station in accordance w/requirements of App R to 10CFR30 VASBALLO,D B Operating Reactors Branch 2 84/08/22 7pp 26350 230 24X Fiche 50-293,84/08/22,8408310396
- --8408310433 Safety evaluation supporting Amend 76 to License DPR-35 \* Office of Nuclear Reactor Regulation, Director 84/08/22 3pp 26350 237 24% Fiche 50~273,84/08/22,8408310396

ļ.

- 8408270230 Notifies that Rev 6 to security force training & qualification plan acceptable wichings Requested changes specified in encl Encl withheld (ref locing 3.21) MARTIN.T T Division of Engineering & Technical Programs 84/08/23 HARRINGTON, W.D. Boston Edison Co. 3pp. 26240-215 24X Fiche 50-293,84/08/23,8408270230
- G Vqlnqıcetori torresbnuqeuce
- 8408070471 Order extending time until 840810 for Commission to act to review Director's Decision DD-84-15 Served on 810806 CHILK.6 J Office of the Secretary of the Commission D58 754 84708703 Commissioners 1p 25940 094 24X Fiche 50-293,84708703,8408070491
- 8408200608 Advises that time for Commission to review Director's Decision OD-84-15 expired Commission declined review Decision became final agency action on 840810 Served on 840820 CHIEK.5 J Office of the Secretary of the Commission DSB 152 84/08/17 ERRST.M D Massachusetts Public Interest Research Group 1p 26137 180 24X Fiche 50-293.84/08/17.8408200608
- P Operating license stage documents & correspondence
- 8498060157 Forwards exemption from certain requirements of 10CFR50 54(a) & App J, permitting testing of MSTV at pressure of 23 paig All other exemption requests withdrawn or unnecessary Requests update of 760127 & O604 Tech Specs VASSALLO, D D Querating Reactors Branch 2 84/07/02 HARRINGTON, W D Boston Edison Co 2pp 25936 274 24X Fiche 50-293,84/07/02,8408060157
- --8408060363 Exemption from 10CFR30 54(o) & App J re Type C testing of MBIV at (Pa) test pressure Testing at reduced 23 psig pressure acceptable due to unique valve design EIBENHUT. B © Division of Licensing 84/07/02 Boston Edison Co 4pp 25936 276 24% Fiche 50-293.84/07/02.8408060137
- ---B408060172 Safety evaluation supporting 840702 exemption from certain requirements of 10CFR50 54(o) & App J permitting MSIV leakage rate testing at 23 psig \* Office of Nuclear Reactor Regulation, Director 84/07/02 4pp 25936 280 24X Fichs 50-273.84/07/02.840806015/
- --8105130143 "Containment Ledkage Rate Testing, Pilgrim Unit 1," technical evaluation rept SCHERRER, J S. Franklin Institute/Franklin Research Center NRC-02-79-118 TER-03257-040 81/05/05 HUANO, Y S. NRC - No Detailed Affiliation (diven 22pp 25936 284 24X Fiche 50-293,84/07/02,8408060157
- --8204150347 "Containment Leakage Rate Testing," technical evaluation rept DELGAIZA.T J Franklin Institute/Franklin Research Center NRC-03-79-118 TER-C5237-548 82/04/12 HUANG,Y S NRC - No Detailed Affiliation Given 17pp 25936 304 24X Fiche 50-293,84/07/02.8408060157
- 8408070129 Advises of discontinuation of consideration of proposed Tech Spec change re weekly surveillance testing of CRD, per 840716 ltr
  VASSALLO, D. B. Operating Reactors Branch 2 84/07/23
  HARRINGTON, W. D. Beston Edison Co. 2pp. 25937 199 24X
  Fiche 50-293.84/07/23,8408070129
- B40B020130 Clarifies util positions re NUREO-0737. Item I C 6 concerning tagging authorization. Independent verification. post-maint configuration varification & ALARA concerns, in response to NRC 840614 ltr Revised procedures encl HARRINGTON. WD B potton Edison Co. 84/07/27 VASGALLO, D D Operating Reactors Branch 2 4pp 25885 268 24% Fiche 50~293,84/07/27.0408020130
- --8408020139 Rev 15 to Procedure 1 4 5, "Tagging Procedure" \* Boston Edison Co 84/05/30 13pp 25885 272 24X Fiche 50-293,84/07/27,8408020130
- --8408020142 Rev 16 to Procedure 1 5 3, "Maint Requests "

  \* Boston Edison Co 83/03/04 28pp 25885 285 24X
  Fiche 50-293,84/07/27,8408020130
- ~-8408020144 Rev 4 to Procedure 1 3 34, "Conduct of Operations "
  \* Boston Edigon Co 83/05/31 24pp 25885 313 24X
  Fiche, 50~293, 84/07/27, 8408020130
- ~-8408020147 Rev 0 to Procedure 1 3 36. "Measurement & Test Equipment " \* Roston Edison Co 83/10/18 18pp 25885 337 24X Fiche 50-293.84/07/27.8408020130

- --8408020149 Rev O to Procedure 1 3 37, "Post-Trip Reviews" \* Boston Edison Co 84/02/28 18pp 25885 355 24X Fiche 50-293,84/07/27,8408020130
- 84CB160087 Forwards request for add1 info re safety relief valve \$ torus attacked piping sys.needed to complete plant-unique analysis rept Meeting requested on 84CB23-24 between NRC. NRC consultants.util \$ util contractor to discuss response VASSALLO,D B Operating Reactors Branch 2 84/07/27 HARRINOTON D Boston Edison Co 3pp 26126 343 24X Fishe 50-293.84/07/27.8408160087
- B408060005 Application for amend to License DPR-35 consisting of Proposed Tech Spec Change 84-07 revising thermal & pressurization limits for reactor pressure vessel before beginning hydro test for restart fee encl HARRINGION, P D Boston Edison Co 84/07/30 VASSALLO, D B Operating Reactors Branch 2 5pp 25933 060 24X Fiche 50-293,84/07/30,8408060005
- ~-8408060008 Proposed Tech Spec Change 84~07, revising thermal & pressurization limits for reactor pressure vessel before beginning hydro test for restart from current refueling outage \* Boston Edison Co. 84/07/30 App. 25933 065 24X Fithe 50-293,84/07/30,8408060005
- 8408060016 Rev 2 to "Pilgrim Nuclear Power Station Reactor Pressure Vessel Pressure Temp Limits " \* Teledyne Engineering Services TR-6052-1 R02 84/07/19 26pp 25933 072 24x Fiche 50-293.84/07/30,8708060005
- 8408030121 Forwards response to 840527 request for add1 info re Multi-Plant Action F-59 (TMI Item II K 3 28), "Qualification of Automatic Depressurization Sys Accumulators," per 10CFR30 54(f) OE will provide add1 info by 841001 HOWARD, J E Boston Edison Co 84/07/31 EISENHUT, D G Division of Licensing 3pp 25916 112 24X Fiche 30-293,84/07/31.8408030121
- 8408040332 Notification of 840823-24 meetings w/utils in Waltham, MA to discuss open items on Mark I containment program HERMANN, R A Operating Reactors Branch 2 84/07/31 VABSALLO, D & Operating Reactors Branch 2 2pp 25937 357 24x Fiche 50-000,84/07/31,8408060332
- 8408150620 Forwards FR notice of consideration of issuance of amend to License DRR-35 & proposed NSHC determination & opportunity for hearing re rev to scram discharge vol sys NSHC available in Central Files
  LEECH-P H Operating Reactors Branch 2 84/07/31 MARRINGTON W D Boston Edison Co 2pp 26103 300 24% Fiche 50-293,84/07/31,8408150620
- --8408150623 Notice of consideration of issuance of amend to License DPR-35 & proposed NSNC determination & opportunity for hearing re 840826 request for rev to scram discharge voleys
  HERMANN.R A Operating Reactors Branch 2 84/07/31 7pp.
  26103 302 24X Fiche 50-293.84/07/31,8408150620
- 8408070248 Forwards resolutions for environ qualification of safety-related electrical equipment & justification for continued operation for any equipment for which documentation for environ qualification not yet completed HARRINGTON W D Boston Edison Co 84/08/03 VASSALLO, D B Operating Reactors Branch 2 B2pp 2972 185 24x Fiche 50-273,84/08/03,8408090248
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of Suppl I to NUREQ-0933, "Prioritization of Generic Safety Issues." Svc list encl EISENNIAT, D 0 Division of Licensing 84/08/06 Consulidated Edison Co of New York, Inc. 18pp 26129 23B 24x Fiche 80-000,84/08/06.8408070110
- 8408140239 Application for amend to License DPR-35, changing Tech Specs to provide redundant temp monitoring sus for suppression pool & responding to portions of TM1 action plan requirements of NUREG-0737 HARRINGTON B Boston Edison Co 84/08/09 VASSALLO, D B Operating Reactors Branch 2 lp 24035 316 24X Fiche 50-293,84/08/09,8408140239
- --8408140249 Proposed Tech Spec changes, providing redundant temp manitoring sys for suppression pool & responding to portions of TM1 action plan requirements of NUREG-0737 \* Roston Edison Co 84/08/09 13pp 26055.317 24X Fiche 50-293.84/08/09.8408140239

- 8408140250 Responds to NRC 840613 request for into re analysis & methodology for Mark I long-term program for seffity relief valve actuation not in conformance w/NURFG-0661 Review of procedures levenls complete conformance

  HARRINGTON N D Boster Edison Co 84/08/09 VASSALLO, D B Operating Reactors Branch 2 ip 26093 398 24X

  Fiche 50-293,84/08/09,8408140250
- B40B140251 Application for amend to License DPR-35 changing Tech Specs to replace Halon 1301 sys in place of CD2 sys in cable spreading room HARRINGTON H D Boston Edison Co 84/08/09 VASSALLO D B Derating Reactors Branch 2 2pp 26054 340 24X Fiche 50-293 84/08/09, 8408140251
- ~-B40B140256 Proposed Tech Spet changes, substituting Halon 1301 sys in place of CO2 sys in cable spreading room \* Boston Edizon Co 84/08/09 App 26054 342 24X Fiche 50-293, 84/08/09, 840B140251
- B40Bi50087 Responds to NRC 820B09 ltr re guidelines developed to facilitate revieu following implementation of NVREG-6737. Item II B 3 re post-accident sampling sys Info submitted to assist in SER preparation HARRINGTON.W D Boston Edison Co 84/08/09 VASSALLO.D B Operating Reactors Branch 2 Spp 26086 256 24X Fishe 50-273.84/08/09.6408150087
- B40B160033 Application for amend to License DPR-35, consisting of proposed Tech Spec change re mod to surveillance requirements for containment cooling subsys & bases HARRINGTON, W D Boston Edison Co B4/08/09 VASSALLO, D B Operating Reactors Branch 2 1p 26092 044 24X Fiche 50-293, 84/08/09, 8408160033
- --B40Bi60034 Proposed Tech Spec change, modifying surveillance requirements for containment cooling subsys & bases \* Boston Edison Co 84/08/09 5pp 26092 045 24X Firne 50-293,84/08/09,8408160033
- 8408140041 Application to amend License DPR-35 changing Each Specs re standby gas treatment sys % control room high efficiency air filtration sys
  HARRINGTON, H D Boston Edison Co 84/08/09 VASSALLD, D D
  Operating Reactors Branch 2 jp 26092 053 24X
  Fiche 80-293,84/08/09,8408160041
- --8408160045 Proposed changes to Tech Spec Pages 158, 158A-C. 172,174 x 174A ra standby gas treatment sys & control room high efficiency air filtration sys \* Beston Edison Co. 84/08/09 12pp 26092 054 24X Fiche 50-273,84/08/09,8408160041
- 8408220133 Requests extension to 850131 for responding to Generic Ltr 84-15 re diesel generator surveillance tests & reliability data & programs Justification for extension provided HARRINGTONN D Buston Edison Co 84/08/15 EISEMNUT, D @ Bivision of Licensing 2pp 26193 316 24x Fiche 50-293,84/08/15,8408220133
- 8408200275 Ceneric Ltr 84-20 to ail licensoes of operating reactors & applicants for OLs re-scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list enci
  EISENMUT.D 9 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X
  Fiche 50-000.84/08/20.8408200275
- 8408310996 Forwards Amond 76 to License DPR-35 & safety evoluation Amend revises fire protection Tech Specs re penetration fire barriers LEECH.P H Operating Reactors Branch 2 84/08/22 HARRINGTON, N D Boston Edison Cu 2pp 26350 228 24X Fiche 50-293, 84/08/22, 8408310394
- --B408310430 Amend 76 to License DPR-35, revising fire protection Tech Spets re penetration fire barriers to reflect changes made to station in accordance w/requirements of App R to 1007R50 VASSALLO.D B Operating Reactors Branch 2 84/08/22 7pp 26350 230 24X Picks 50-273,84/08/22,8408310396
- --B408310433 Safety evaluation supporting Amend 74 to License DPR-35 \* Office of Nuclear Reactor Regulation, Director 64/08/22 3pp 26330 237 24X Fiche 50-273,84/08/22,8408310376
- 8408303178 Submit: "1984 Main Breakwater Surveillance Rept " No damage or major stone novement occurred to structure since 1983 rept Photographs & two oversize drawings encl. Aperture cards available in PDR 4RRINGTON N D Buston Edison Co 84/08/24 VASSALLO.D B arating Reactors Branch 2 56pp 26313 100 244 rhe 50-273.84/08/24.8408300198

- G Inspection reports IE Bulletins , correspondence
- B40B100B0B Forwards response to If Builetin 84-02, "Failures of CE Type HFA Relays in Class IE Safety Sys Util experienced failures of GE Type HFA. Series 51.40 normally energized relays Status of replacement program encl HARRINGTON. T.E. Boston Edison Co. 84/0//1/ MURLEY, T.E. Region J. Office of Director 6pp 25989 280 24x Fiche 50-293.84/07/17, 8408100008
- 8407250229 IE Info Notice 84-57, "Operating Experience me Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, Et Division of Emergency Frepatodiess & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc. 119pp 25865-047 21% Ficho 50-000.84/07/27, 8407250229
- 8408230276 Forwards IE Insp Rept 50-293/84-18 on 840611-15 No violations observed MARTIN T Division of Engineering & Technical Programs 84/08/01 HARRINGTON D Boston Edison to 2pp 26213 260 24x Fiche 50-293.84/08/01.8408230276
- --8408230283 IE Insp Rept 50-293/84-18 on 840611-19 No viplations identified Major areas inspected surveillance & functional tests of snubbers, hangers & supports, records of pipe support mods of turus external piping & modified pipe supports NARROW.L. DURR.J P Region i. Office of Director 84/07/20 6pp 26213 262 24x Fiche 50-293.84/08/01,8408230276
- 8408230566 Forwards IE Insp Rept 50-293/84-14 on 840509-11 & 14-16 & notice of violation
  MARTIN T T Division of Engineering & Technical Programs 84/08/02
  HARRINGION, W D Boston Edison Co 2pp 26213 018 24X
  Fiche 50-293.84/08/02.8408230566
- --8409230567 Notice of Violation from Insp on 840509-11 & 14-16 \* Region 1. Office of Director 84/08/02 2pp 26213 020 24x Fiche 50-293,84/08/02,8408230566
- --B408230569 1E Insp Rept 50-273/84-14 on 840509-11 & 14-16 Violations noted failure to adhere to procedures in accordance w/Tech Spec & 11, to perform surveys in accordance w/10CFR20 201 & adequately instruct curkers in accordance w/10CFR19 12 WHITE.J R , KATTAN.J , SHANBAKY,M M Region 1. Office of Director 84/07/26 11pp 26213 022 24X Fiche 50-293,84/08/02,8408233986
- 8408230082 Forwards IE losp Rept 50-293/84-17 on 840409-0716 No violations noted Possible weakness in radiological controls program noted STAROSTECKI.R Division of Project & Resident Programs 84/08/03 HARRINGTON.W D Boston Edison Co 2pp 26214 128 24X Fiche 50-293,84/08/03,8408230082
- --B408230091 IE Insp Rept 50-293/B4-17 on B40605-0716 No violations noted Hajor areas inspected plant operations including followup of previous findings, aperational safety verification, plant events & LERs
  JOHNBON, J. MCBRIDE, N. LIPINSKI, D. Region 1, Office of Director B4/08/01 15pp 26214 130 24x Fiche 50-293, 84/08/03, 8408230082
- B408010333 IC info Notice 84-59, "Deliberate Circumventing of Station Nealth Physics Procedures " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Compolidated Edison Co of New York, Inc 122pp 26068 001 24% Fiche 50-000,84/08/06,8408010333
- 8408010337 If. Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list encl JURDAN, C. L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 26067 158 24% Fiche 30-000,84/08/06,8408010337
- 8408070120 IE info Notice 84-61. "Querexposure of Diver in PWR Refueling Cavity " Suc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York. Inc 120pp 26129 118 24% Fiche 50-000,84/08/08,8408070120
- 8408150095 Supple 840517 response to violation & proposed imposition of civil penalties Procedure & t-024 revised on 840718 to provide more specific guidance re labeling radioactive matacontainers
  HARRINGTON.W D. Boston Edison Co. 84/08/08 DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 2pp 25067 050 28% Fische 50-293,84/08/08,8408150053

- მ40ტი 10376 IF Info Notice 84-62 Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
- 00ACE.J N Pivision of QA, Sarequards t Inspection Programs (Post 830103) 84708 10 Consolidated Edison Co of New York, Inc 185pp 26130 001 24% Fishe 50-000 84708/10.6408070376
- 8408100009 IE Info Notice 84-63, 'Defective RHR Replacement Piping "
- NORIDOUS IE III III III SV. list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co. of New York, Inc. 119pp 2619/ 218 24% Fiche 50-000,84/08/13,8408100009
- 8408100038 If Info Notice 84-64, "BWR PPCI Instruction Seal-In &
- Indication "Syc list encl JORDANNEL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co. of New York, Inc. 104pp 26198 093 24% Fiche 50-000.84/08/15.8408100038
- 8408100021 IE Info Notice 84-65, "Undornated Fuses Which May Adversely
  Affect Operation of Essential Electrical Equipment " Svc
- Affect Uperation of Emergency Preparedness & Engineering
  JURDAN, E. L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/16 Consolidated Edison Co. of New
  York, Inc. 118pp 26198 001 24% Fiche 50~000,84/08/16,8408100021
- B408100055 [E Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN, F. L. Division of Emergency Preparedness & Engineering Response (Post 630103) 84/08/17 Conselidated Edison Co. of New York, Inc. 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- B408140208 IE Info Notice 84-67. "Recent Snubber Inservice Testing W/ High Failure Rates " Syc list encl JDRDAN,E L. Division of Emergency Proparedness & Engineering Response (Past 830103) B4/08/17 Cansolidated Edison Co. of New York, Inc. 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26327 008 24% Fiche 50-000,84/08/21,8408210142
- R Pariodic operating reports & related correspondence
- 8408080503 "NPDES Discharge Monitoring Rept for Apr-June 1984" W/840728 | tt | HARRINGTON W D , MATHIS, C J | Boston Edison Co | 84/06/30 | 17pp | 25975 | 240 | 24x Fiche | 50-293, 84/06/30, 8408080503
- 8408160094 Monthly operating rept for Jul 1984 W/840809 ltm HAMILTON,P., HARRINGTON,W.D. Boston Edison Co. 84/07/31 26108 238 24X Fiche 50-293,84/07/31,8408160094
- 8 Reportable occurrences, LCRs & related correspondence
- 8408300348 LER 77-030/03x-1 on 770806.during normal shutdown for Refucling Outage 3,CRD 34-1; remained full-out when reactor scrammed Probably caused by foreign substance restricting narmal aperation CRD replaced W/840809 ltr HAMILTON.P J. HARRINGTON.W D Boston Edison Co 77/09/01 MCRLEY,T E Region J. Office of Director 3pp 26308 353 Fishe 50-273,77/09/01.8408300348
- 8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solemnid valve plunger Initially reported on 640413 New thread locking devices investigated BHERWOQD, O G Owneral Electric Co 84/04/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24% Fiche 50-000,84/04/13,8408240348
- 8408090114 Part 21 rept re twisted shielded pair cable in Nuthern Intl.
  Inc Analog Trip Cabinets C2228A1, C2228A2, C2229B1 & C2229B2
  Initially reported on 840713 Caused by poor workmanship
  Cables exhibiting defects replaced
  HARRINGTON.W D Boston Edison Co 84/07/13 MURLEY.T E Region 1,
  Office of Director 3pp 25992 242 24X Fiche 50-293,84/07/13,
  8408090114
- 0408100046 LER 02-049/01X-1 on 821102 main steam line safety valve A NOBIOUGAS LEK 82-044/01x-1 on 82:102: main sceam interserver is set wintrogen at steam relief softing Caused by personnel error Valve removed & replaced w/properly set spare valve Procedure revised W/840720 ltr
  HAMILTON,P J , HAMRINGTON,W D Doston Edison Co 84/07/20
  MURLEY,T E Region i, Office of Director Jap 25990 070
  Fiche 50-293.84/07/20,8408100046

- E40E100099 LER 77-018/03x-1 on 77050E, CRD 46-39 withdrawn bewond CRD 45-39 :emoved & replaced on 770901 during Refueling Outage 3 W/840720 ltr Outage 3 W/840720 ltr HAMILTON, P.J., HARRINGTON, W.D. Boston Edison Co. 84/07/20 MURLEY, T.E. Region 1, Office of Directol 3pp. 25990 352 Fiche 50-293,84/07/20,8498100097
- 8408030022 Special rept on 840628.during refueling outage.electric fire pump failed while conducting yearly 0-150% capacity test Caused by shorting within motor Motor rewound Fire pump not returned to operable status within required 7-day period HARRINGTON.W D Boston Edison Co 84/07/26 VASSALLO.D B Operating Reactors Branch 2 ip 25907 087 24% Fiche 50-293.84/07/26.8408030022
- 8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 teicon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
  VILLA.R General Electric Co 84/08/21 ROSSJ.C E Director's
  Office Office of Inspection and Enforcement 3pp 26318 327 243
  Fichu 50-000.84/08/21.84083(0186
- DOCKET 50-294 MICHIGAN STATE UNIV RESEARCH REACTOR V Operator Examinations
- B408090162 Forwards Rev 4 to "Requalification Program for Licensed Operators," in response to 840711 Generic Ltr 83-12A MILKINSON,R Michigan State Univ, East Lansing, MI 84/07/24 TROMAS Standardization & Special Projects Branch ip 29973 16 24X Fiche 50-294,84/07/24,8408090162
- ---8408090165 Rev 4 to "Requalification Program for Licensed Operators "
  \* Michigan State Univ , East Lansing, MI 84/07/13 3pp
  25973 125 24x Fiche 50-294,84/07/24,8408090162
- 8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners WALKER, R D Region 3. Office of Director 84/08/10 Michigan. Univ of. Ann Arbo: MI 2pp 26051 198 24% Ficha 50~000. 84/08/10.8408140426
- 8408210141 Informs of review of Rev 4 of requalification program for licensed operators Program satisfies criteria of 10CFR55. App A & ANSI/ANS 15 4 & is acceptable THOMAS.C O Standardization & Special Projects Branch 84/08/13 MILKINSON.R E Michigan State Univ . East Lansing. Mi 3pp 26193 311 24X Fiche 50-294.84/08/13.8408210141
- DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 8408070239 Rev 7 to Emergency Plan Implamenting Procedure EPIP 110-1. "Zion Station Nuclear Accident Reporting Bys Reporting Procedures " W/040719 transmittal memo NYKIRKJ Companiesalth Edison Co 84/07/19 10pp 25948 353 24X Fiche 50-295.84/07/19.8408070239
- 8408070240 Rev 3 to Emergency Plan Implementing Procedure EP1P 100-1, "Acting Station Director" W/840719 transmittal memo NYKIRK. J Commonwealth Edison Co 84/07/26 16pp 25949 001 24X Fiche 50-295.84/07/26.8408070240
- B40B010165 Forwards "Gafe Shutdown Capability Reasspsement & Proposed Mods, 10CFR30, App R." for approval Exemption from schedular requirements of 10CFR30 4B(c)(4) until B31231 requested Relabed tables & notes encl CASCARAND.R N Commonwealth Edison Co 84/07/27 DENTON.H R Office of Nuclear Reactor Regulation, Director 28pp 25874,001. 24X Fiche 30-295,84/07/27,8408010165
- 10CFR30.App R "

  \* Commonwealth Edison Co 84/07/31 499pp 25874 029 24X
  Fiche 50-295.84/07/27.8408010165
- B408170898 Forwards public version of Rev 3 to Emergency Plan Implementing Procedure B2P 500-A3. "Station Directory " \* Commonwealth Edison Co 84/07/3i Record Services Branch (Document Control Desk) 2pp 26134 171 24X Fiche 50-295. B4/07/31.8408170398
- --8408170399 Public version of Rev 3 to Emergency Plan Implementing Procedure BZP 600-A3, "Station Directory " W/JM Felton 840809 release memo \* Commonwealth Edison Co 84/07/31 10pp 26134 172 24X Fiche 50-295,84/07/31,8408170398

- B40B100060 Determines that based on evaluation. State of WI & local plans for radiological energencies adequate SPECKIS W Federal Emergency Management Agency 84/08/02 DIRCKS WJ Office of the Executive Director for Operations 1p 25789 052 24X Fichs 50-295.84/08/02,8408100060
- B40B140139 Forwards listed revs to security plans Revs address fence height requirements Revs withheld (ref 10CFR73 21) FARRAY, D. L. Commonwealth Edison Co. 84/08/03 Region 3, Office of Director. 1p. 26044 252 24X Fiche 50-000.84/08/03,8408140139
- B40B130401 Responds to 840705 clarification of info recutil means of satisfying annual regulatory requirement to review energoncy action levels w/offsite emergenty support organizations info acceptable PAPERIELLO, C.J. Region 3. Dérice of Director 84/08/07 REED. C. Commonwealth Edison Co. ip. 26010 130 24X Fiche 50-000,84/08/07,840B130405
- --B408130413 Responds to B40804 ltr re means for satisfying requirements of 10CFR50.App E.Paragraph IV B Proposal for satisfying requirements to review omergency action levels by offsite agencies clarified FARRAR.D L Commonwealth Edison Co B4/07/05 PAPERICALD.C J Region 3. Office of Director 3pp 25010 131 24X Fiche 50-000.84/08/07.8408130401
- B40B1404R8 Rev 3 to Emergency Plan implementing Procedure EPIP 350-2, "Calculation of Post-Accident Noble Gas Release Rates Via Vent Stacks & Quick Estimate of Offsite Dose Using SPINO Monitor RIA-PR49 Readings " W/840B08 transmittal memo KASSNER,G. PLIML.C Commonwealth Edison Co 84/08/08 13pp 240S1 170 24% Fichs 50-295.84/08/08,8408140428
- 8408200345 Advises that 840803 Rev 13 to physical security plan consistent w/provisions of 1007R50 54(p) & acceptable AXELSON, W.L. Region 3, Office of Director 84/08/14 FARRAR, D.L. Commonwealth Edison Co. 2pp. 26132 357 24X Fiche 50-275,84/09/14,8408200345
- 8408310168 Rev 3 to Emergency Pian Implementing Procedure EPIP 950-6. "Monthly Radiological Emergency Equipment Tests & Checks "W/transmittal & receipt form United States of Checks of Ch
- 8408270307 Informs of FEHA approval of State of WI emergency response & local plan Adequacy of public alerting & notification sysmust be verified per FEHA/NRC joint criteria in App 3 of NUREO-0654/FEHA-REP-1
  PAPERIELLO.C J. Region S. Office of Birector 84/08/22 REED.C Commonwealth Edison Co. 2pp. 26239 157 24X Fiche 50-275,84/08/22.8408270309
- P. Operating license stage documents & correspondence
- 8408280340 Ack receipt of 840710 ltr re author criticism of NRC present rules & practices Reponse to ARC seven stages of discussion listed Past tests should be reviewed & leak rate be retested Related into enci REYIBLATI, 2 V Warren Wilson College, Swannanoa, NC 84/07/22 RD85.0 F Office of Nuclear Regulatory Research, Director 8pg 26293 001 24% Fiche 50-000,84/07/22,8408280360
- --BA0B280366 Lists basic deficiencies & errors of present leak rate testing methodology as regulated by faulty stds
  REYTBLATT.7 V Extran, Inc. 84/03/15 ACRS ~ Advisory
  Committee on Reactor Safeguards 3pp 26293 007 24x
  Fichs 30-000,64/07/22.8408280360
- --8408280373 Requests documents re RFP R6~RE8-84-101. submitted on 840110 Author 840220 ltr to EM Gogol Citizens Against Nuclear Power encl REVIBLATT. Z V Extran, Inc. 84/03/02 Division of Rules and Records App. 26293 012 24% Fiche 50-800.84/07/22:8408280360
- --8406280378 Ack receipt of NRC B30722 response to 830705 itr re critoria for licensing nuclear containments Normal procedure substituted for handling hazardous situation Response to unsolicited proposals requested REYTBLATT, Z. Extran. Inc. 83/07/26 ARNOT.E D. Mechanical/Structural Engineering Branch. 4pp. 26293-019-24% Fiche 50-275,84/07/22,8408280360
- ~~8408280380 Discusses author presentation on 840319.0 Arnot & DRNL should be beend before committee on faulty look rate test Requests addit opportunity to present point of view REYTOLATT. 2 Extran. Inc. 84/05/18 ACRE Advisory Committee on Reactor Safeguards 1p 26293 023 24K Fiche 30~000.84/07/22.8408280360

- -8408280381 Requests that EG Aindt of Mechanical/Structural Engineering Branch be ordered to start evaluation of maths supporting author demand to suspend temporarily all intergrated leakage rate tests Dring history of problem listed REVIBLATT Z Extran. Inc. 83/07/26 PALLADINO, N Commissioners ip 26293-024 24x Fiche 50-295.84/07/22,8408280360
- --840820303 Discusses hearings on leak rate matters to proposed changes to 10CFR50 App J REY(BLAT), Z V Warren Wilson College, Swannanca NC 94/07/05 SIESG ACKG - Advisory Committee on Reactor Safeguards 3pp 26273 025 24% Fiche 50-245.84/07/22,8408280360
- --8498280307 Discusses concerns w/leak rate testing situation Draft reg guide on leak rate testing should not be presented to public w/o prior discussion by ACRS or subcommittees Requests that NRI take listed actions REYTBLATT, Z V Warren Wilson Cullege, Swannanca, NC 84/07/09 EBERSGLE ACRS - Advisory Committee on Reactor Safeguards 2pp 26273-028 24X Fiche 50-295,84/07/22,8408280360
- -~8408280390 Advises that no proven public health or safety hazard results from integrated leak rate test critoria.per 10CFR50.App J Issue considered resolved future comments on subj should be directed to Secretary of Commission ROSS.D F Office of Nuclear Regulatory Research. Director 84/07/10 REYTBLATT.Z Warren Wilson College, Swannanca, NC 2pp 26273 030 24x Fiche 50-295.84/07/22.8408280360
- --8409280395 Advises that no schedule planned for debriefing session to discuss technical evaluation results of proposal "Containment Sys Leakage Testing Requirements"
  THOMFSON.R D Division of Contracts 84/04/20 REYTBLATT, Z V Extran. Inc. ip 26293 032 24% Fiche 50-295,84/07/22,8409280360
- ~-8409280400 Responds to 840302 ltr to Chairman Palladino re proposal on containment sys leakage requirements Proposal not funded since current leak rate tost results not significantly attered
  BURNSIJ J Mechanical/Structural Engineering Granch 84/04/17
  REYTBLATT. Z Extran, Inc. 2pp 26293 033 24X
  Ficha 50-295,84/07/22.8408280360
- --8408280404 Informs that proposals "Improvements to Leak Rato Testing,"
  "Assessment of Past Leakage Rate Tests" & "High Trajectory
  Turbine Missile Hazard Evaluation" will not be funded due
  to listed reasons
  THOMPSON.R D Division of Contracts 84/03/20 REY/BLATT, Z
  Extran. Inc. 2pp. 26293-035 24X Fiche 50-295,84/07/22,
  8400280360
- --040028040/ Requests NRC participation in technical discussion recontainment leakage rate testing on 840312
  REYTOLATT, Z Affiliation Not Assigned 84/03/02 PALLADINO, N
  Commissioners 1p 26293 037 24X Filhe 50-295,84/07/22,
  8408280360
- --B408280411 Requests evaluation of oncl memo re integrated leakage rate test REYTULATT, Z Extran. Inc. B3/08/30 DURNS, J Division of Engineering Technology 3pp 26293 039 24X Fichs 50-295,84/07/22,8408280360
- --B309220362 Ack receipt of B30726 its to Chairman Pallading Response will be provided as soon as review completed BURNA, J Mechanical/Structural Engineering Branch B3/08/23 REYBLATT, 2 Extran. Inc. 1p. 26293-042 24X Fichs 50-295,84/07/22,8408280360
- --B40B2B0422 Requests that Paragraph 3 of 10CFR50.App J.be immediately rovoked.per 10CFR21 ANGI N48 4-1972 may not detect abnormally high leak tests
  REYTBLATT. Z Extran. Inc. 83/07/26 PALLADINO.N Commissioners
  By 26293 045 24% Ficho 50-295.84/07/22.8408280360
- --B40B2B0430 Requests that Paragraph 3 of iOCFRSO App J.be immediately revoked, por iOCFR21 ANSI N45 4-1971 may not detect abnormally high loak test because of numerous loopholes for distorting test results REYTDLATT. Z Extran, Inc. B3/07/26 ARNDT.E G NRC No Detaited Affiliation Given ip 26293 Q4B 24X Fiche 50-295, B4/07/22, B40B2B0360
- 8408060333 Notification of 840802 meeting w/util in Bethesda.MD to discust insights from review of probabilistic safety study NORRIS.JA Operating Reactors Branch | 84/07/27 VARGA, 8 A Operating Reactors Branch | 3pp 25937 354 24X Fiche 80-293.84/07/27.8408060335

- 8406130015 Submits summary of conduct or proposed integrated leak rate test Util will suppl normal instrument checkout wintegrated sus chick Check will be performed after instruments hung but pilor to containment pressurization CASCARANO, R N Commonwealth Edison Co. 84/07/27 KEPPLER, J G Regian 3. Office of Director 2pp. 25990 108 24X Fiche 50-295,84/07/2/.8408100015
- 8408130047 Notification of cancellation of B40802 meeting w/util in Bethewda.MD to discuss NRC review of probabilistic safety study NDRRIS, J.A. Operating Reactors Branch 1 84/07/27 VARSA, S.A. Operating Reactors Branch 1 2pp 26034 360 24x Fiche 50-295,84/07/27.8408130047
- 840Bi30022 Ack receipt or 840605 petition for emergency relief re adequacy of containment leak rate testing NRC conducting insp on allegations Util informed that Unit 1 not in compliance w/10CFR50.App J DENTON.H R Dffice or Nuclear Reactor Regulation, Director 84/07/30 GUGAL.E M Citizens Against Nuclear Power 9pp 26036 330 24X Fiche 50-295,84/07/30,840Bi30022

- B408090139 Advises that Class III fee appropriate for review of \$30727 submittal of "Comm Ed Topical Rept on Benchmark of PWR Nuclear Design Methods" Exemption from Class I fee granted W/o stated encls
  MILLER, W O License Fee Management Branch 84/08/03 FARRAR, D L
  Commonwealth Edison Co 2pp 25991 205 24X Fiche 50~295,84/08/03,840890139
- 8408070110 Generic Ltr 84-19 to all licenses of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Generic Safety Issues " Svc list enci EISENHUT.D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24% Fiche 50-000.84/08/06.8408070110
- 8408100110 Ack receipt of 840730 ltr 1e Citizens Against Nuclear Power petition for relief to correct hazardous & illegal situation at facility Data for 1981, 1983 & 1984 containment leak rate tests requested 9000L,E Citiens Against Nuclear Power 84/08/06 DENTON,H Office of Nuclear Reactor Regulation, Director 2pp 25991 033 24X Firhe 30-295.84/08/06,8408100110
- B408230097 Forwards draft Industry Degraded Core Rulemaking Program Technical Rept 23 i, "Sequoyah Nuclear Plant Containment Analysis." for Heeting 3B Rept inconsistent w/four encl repts previously sent FONTANA.M H Technology for Energy Corp 84/08/07 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 26234 001 24X Fiche 50-000.84/08/07.8408230097
- ---8408230112 Draft "Evaluation of Containment Bypass & Failure to Isolate Sequences for Industry Degraded Core Rulemaking Program Ref Plants." technical rept y Industry Degraded Core Rulemaking Program FAI/84-9 DRFT 84/07/31 114pp 26234 231 24X Fiche 50-000,84/08/07,8408230097
- --8408230116 Draft "Zion Nuclear Cenerating Station Integrated Containment Analysis," technical rept \* Industry Degraded Core Rulemaking Program 84/08/07 26234 335 24X Fiche 50-000,84/08/07,8408230097 84/08/07 119pp
- 8408170033 Notification of 840815 meeting w/util in Bethesda.MD to discuss proposed safety ngt program & integrated living schedule concepts NORRIS.J A Operating Reactors Branch 1 84/08/08 VARGA.S A Operating Reactors Branch 1 2pp 26134 361 24X Fiche 50-295.84/08/08.8408170033
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for CLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl CISENHUT, D Q Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000,84/08/20,8408200275

- 8408280119 Forwards fee for review of util topical lept on benchmark of PWR nuclear design methods in connection w/reloads at facility.per 940803 ltr
  ALEXANDER, G. L. Commonwealth Edison Co. 84/08/20 MILLER, W.D.
  License Fee Management Branch 1p 26261 300 24X
  Fiche 50-295,84/08/20,8408280119
- 8408270372 Forwards response to NRC request for clarification of svc water success criteria Adequacy of two svc water pumps to handle safe shutdown components reconfirmed by util corporate engineering dept CASCARAND. R N Commonwealth Edison Co 84/08/21 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 26/240 25/2 24X Fiche 50-295/84/08/21/8408/270372
- 8408280286 Summary of 840815 meeting w/util re integrated living schedule Attendee list, agenda & viewgraphs encl W/o encls NORRIS. J Operating Reactors Branch 1 84/08/21 Operating Reactors Branch 1 2pp 26294 087 24% Fiche 50-295,84/08/21,8408280286
- 8408310200 Discusses PRA of proposed mod to auxiliary feedwater sys, per NUREG-0737. Item II E 1 1 Efforts on mod stopped as result of PRA conclusion that installation of addi check valves will not significantly improve availability of sys CASCARANO.R N Commonwealth Edison Ca 84/08/23 DENTON.H R Office of Nuclear Reactor Regulation. Director 3pp 26318 308 24X Fiche 50-275,84/08/23.8408310200
- BAOB310202 Forwards add info re inadequate core cooling instrumentation sys.in response to NRC B40930 request Meeting suggested in Bethesda, MD to resolve any questions still outstanding CABCARANO, R N Commonwealth Edison Co. 84/08/24 DENTO, Office of Nuclear Reactor Regulation, Director 7pp 26: 24X Fiche 50-295, 84/08/24, 8408310202
- O Inspection reports. IE Builetins & correspondence
- 8408080485 Forwards IE Insp Repts 50-295/84-08 & 50-304/84-08 on B40531.0604-08, 12-13 & 0702 & notice of violation PAPERIELLD.C J Region 3. Office of Director B4/07/18 REED.C Commonwealth Edison Co 2pp 25975 188 24% Fiche 50-295.84/07/18, 6408080485
- --8408080488 Notice of violation from insp on 840531,0604-08,12-13 & 0702 PAPERIELLO,C J Region 3. Office of Director 2 2575 190 24X Fiche 50-295.84/07/18.8408080489
- --8408080496 IE Insp Repts 50-295/84-08 & 50-304/84-08 on 840531.0604-08, 12-13 & 0702 Violations noted unauthorized transfer of Am-241 sources to Byron Station LOVENDALE, P.C., NICHOLSON, N.A., GREGER, L.R. Region 3, Office of Director 84/07/17 11pp 25975 191 24X Fiche 50-295.84/07/18, 8408080485
- 8408090169 Forwards IE Insp. Repts 50-299/84-07 & 50-304/84-07 on B40812-0629 No noncompliance noted SHAFER.W D Region 3. Office of Director B4/07/20 REED.C Commonwealth Edison Co 2pp 25995 015 24% Fiche 50-295.84/07/20. B408090169
- --8408090177 IE Insp Repts 50-295/84-07 & 50-304/84-07 on 840512-0629 No OBOV017/ IE Insp Repts 30-293/44-0/ & 30-304/44-0/ & in moncompliance or deviations noted Major areas inspected maint on nuclear instrumentation operational safety & ESF walkdown surveillance & LER followup MRIGHT. 6 C Region 3, Office of Director 84/07/19 8pt 25998 017 24X Fiche 50-295.84/07/20,8408090169
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc. 119pp 25865 047 24X Fiche 80-000,84/07/27,8407250229
- B408070066 Notifies of 840823 meeting w/util at Region III oft to review findings of SALP assessment re util performance Encourages mgt representation to ensure mutual understanding of issues & findings prosented by NRC NORELIUS.C E Region 3, Office of Director 84/08/03 REED.C Commonwealth Edison Co 2pp 25949 337 24% Fiche 30-000,84/08/03,8408070066
- 8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during inspirations of fective 840820 Preprinted form will be used instituted.effective dad820 Preprinted form will be used rather than itr KEPPLER.J G Region 3. Office of Director B4/08/03 Commonwealth Edison Co 3pp 25942 (88 24% Fiche 50-000,84/08/03.840807040)

- 8408010333 IE Info Notice 84-59, 'Deliberate Circumventing of Station Health Physics Procedures 'Syc list enc! JURDAN,E L. Division of Emergency Pieparedness / Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26068 001 24K Fische 50-000.84/08/06.840801033)
- 8408010337 IE Info Notice 84~60. 'Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN, E. L. Division of Emergency Preparedness " Engineering Response (Post 820103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 26067 158 24x Fiche 50-000-84/08/06,8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list end!
  JURDAN,E L. Division of Emergency Preparedness V Engineering Response (Past 830103) 84/08/08 Consolidated Edison Co. of New York, Inc. 120pp 26129 118 24% Fiche 50-000-84/08/08,8408070120
- 840B140344 Confirms 840B03 plans to meet w/util on 840907 in Glen Ellyn. LL to discuss regulatory improvement program NORELIUS.C E Region 3. Office of Director 8470B708 HEED.C Commonwealth Edison Co. 2pp. 24041 050 24X Fiche 30-000.8470B708. 840B140344
- 8408150078 Suppls 840711 response to IE Bulletin 84-02 re visual insp during monthly functional tests to verify proper contact on reactor trip sus & primary containment isolation sys relays Exemptions requested for listed relays ALEXANDER.G L Commonwealth Edison Co 84/08/08 KEPPLER.J G Region 3. Defice of Director 1pp 24/057 053 24X Fiche 50-000.84/08/09.8408150098
- 8408200331 Suppls response to IE Bulletin 84-02 re failure of GE Type HFA relays Exemption requested from commitment for visual inspiverifying proper relay contact during monthly functional check for listed relays ALEXANDER, G & Communicalth Edison Co. 84/08/08 MEPPLER, J G Region 3, Office of Director. 3pp. 26/32 3/8 24X Fiche 50-000.84/08/08.8408200331
- 840B170243 Forwards SALP Repts 50-295/84-06 2 50-304/84-06 for Jan 1983 Apr 1984 KEPPLER J & Region 3, Office of Director 84/08/09 REED.C Commonwealth Edison Cq 2pp 2418 008 24X Fiche 50-275,84/08/09,8408170243
- --8408170265 SALP Repts 50-295/84-06 & 50-304/84-06 for Jan 1783 Apr 1784 Licensing activities assigned Catogory 1 rating \* Region 3. Office of Director 84/08/09 31pp 26418 010 24X Fiche 50-295,84/08/09,8408170263
- B40B070374 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Taletherapy Treatments " Svc list enc! GRACE.J N Division of GA. Safeguards & Inspection Programs (Post B30103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000.84/08/10,8408070376
- 840B100009 IE Info Notice 84-63, "Defective RIR Replacement Piping "
  Svc list encl
  JDRDAN, E.L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison to of New
  York, Inc. 119pp 26:97 218 24% Fichs 50-000.84/08/13,8408100009
- 8408220086 Supple 840626 response to 840511 request for add1 info re inservice insp program for second 10-yr interval Add1 relief requests & additions to program encl CASCARADO,R N Commonuealth Edison Co 84/08/14 DENTON,H R Office of Nuclear Reactor Regulation Director 37pp 26173 252 24X Fiche 50-295,84/08/14,8408220086
- 8408100038 IE Info Notice 84-64, "BWR HPC1 Initiation Seal-In & Indication " Svc list encl URBAN.E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/08/15 Consolidated Edison Co of New York: Inc 104pp 26198 093 24X Fiche 50-000.84/08/15,8408100038
- 840B100021 IE Info Notice 84-45, "Underrated Poses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl URROAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/14 Consolidated Edison Co. of New York, Inc. 1188p. 26198 001 24X Fiche 50-000.84/08/16,840B100021
- 8408270087 Suppls 840407 ltr re check valves in water cooling sys of diesel generators, per IE Bulletin 83-03 Valve insp on 840515 revealed no mechanical problems ALEXANDER. OL Commonwealth Edison Co. 84/08/16 KEPPLER. J Q Region 3. Office of Director 2pp 26247 355 24X Fiche 50-295.84/08/16.8408270087

- 840810005% If Info Notice 84-ob 'Unditected Unavailability of Turbine Dit en Auxiliang Feedwater Thain' Svc list encl JORDAN FI Division of Emergency Preparedness & Engineering Resoonse (Jost 830104) 84708/17 Consolidated Edison Co. of New York, Inc. 1200p 26276-001 247 Fichs 50-000-81708/17,840810005%
- 8408140208 IE Info Notice 84 6 Pecent Snubber Inservice Festing ()/ High Failure Rates Svc list encl UCROAN, E. L. Division of Emergency Preparedness 'Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 122pp 262/6/122 244 firsts 50-000-84/08/17, 8408140208
- 8408210142 IE Info Notice 81-68. Potintial Deficiency in Improperly Rated Field Miring to Solenuid Valvis Svr list encl JORDAN, F. L. Division of Emergency Preparedness? Engineering Response (Post #30103) 81/08/21 Consolidated Edison Co of New York, Inc. 115pp. 26329 000 244 Fiche 50-000-84/08/21,8408210142
- R Periodic operating reports & related correspondence
- 8408300136 "Effluent & Waste Disposal Semiannual Rept. Jan-June 1984 "
  W/B40803 ltr
  GRAESBER:K L Commonwealth Edison Co 84706/30 KEPPLER: J G
  Region 3. Office of Director 47pp 26308 029 24x
  Ficha 50-295.84706/30.8498300136
- 840816D122 Honthly operating repts for Jul 1984 W/840807 ltr AUSTIN.6., GRAESETR.K L. Commonwealth Edison Co. 84/07/31 13pp 26108 117 24x Fiche 50-275,84/07/31,8408160122
- S. Reportable occurrences. LFRs & related correspondence
- 8498140150 LER 84-017-01 on 849622 containment air monitol low range nuble gas detector failed to respond to check source % declared inoperable Caused by malfunction in check source mechanism Check source mechanism legalred W/840809 lt; KUECHLE. C. GRAESSER. K. L. Commonwealth Edison Co. 84/07/20 3pp 26108 069 24x Fiche 50-295.84/07/20 8408160150
- 8408100109 PNO-111-84-058B on B40/18 bicensee successfully completed integrated leak rate test following 84071B shutdown for failure to demonstrate integrity of containent Unit expected to start up by 840816 SUERMANNUJ WRIGHT.6. REYES.L. Region 3. Office of Director 84/08/02 1p 25990 362 24% Filhe 50-295.84/08/02,8408100109
- B408070404 LER B4-019-00 on B40621 startup repts for initial use of Nestinghouse optimized fuel assemblies submitted to NRC late Caused by misinterpretation of Tech Spec Repts tracked w/commitment list W/H40803 lt; CHIN.R Y . GRAESSER & Commonwealth Edison CD 64/08/03 3pp 2579-284 Fichs 50-295.84/08/03.8408090404
- 8408130604 LER 84-018-00 on 840641.blower for 10PRCAH (vent stack to iddine sampler) found off Cause unknown Blower turned on to verified operational Installation of low flow annuclator initiated Monitors checked shirtly W/840806 ltr
  KASSNER.G. GRAESSER.K.L. Commonwealth Edison Co. 84/08/06 3pp 26030 360 24x Fiche 50-295.84/08/06.8408170604
- 8408240042 LFR 84-020-00 on 840814.while releasing gas decay tank 10, loss of pressure occurred in gas decay tank 2 B Coured by improper linear rausing gas decay tank to be cross-trod Nork requests unitten for repair of rods W/840815 ltr BAHLEN.D. GRAESER.K L Commonwealth Edison Co 84/00/15 3pp 26236 351 24X Firbs 50-295.84/08/15.8408240042
- 940923007/ Summary of 94090/ operating reactor events meeting re occurrunces since 940719 mooting List of attendings, significant elements 5 status of provious assignments enci CRUTCHTIELD, D. Assistant Director for Safety Assessment 84/08/16 EISERHUT, D.G. Division of Licensing 20pp 26232 249 24X Fiche 30-000,84/08/16.84082300//
- B40B230514 LER B4-021-00 on B40/18, containment structure failed to meet requirements of 10CFR30. App J after exam of 1981 7, 1983 integrated loak tests Cause not stated Evaluation of test adequacy continuing W/B40B16, 1tr
  LANE. R E. GRAESBER.K L. Commonwealth Edison Co. 84/0B/16 4pp 26212 279 24X Fichs 50-275. 84/0B/16, 840B230514
- B40B300073 LER B2-03B/O3L on B21015.narrow-range temp cold leg Loup D low level amplifier (TM-471B failed Caused by incorrect capacitor voltage values Components replaced & module returned M/940B22 ltr WILHITE.X. GRAESSER.X i Commonwealth Edison Co 84/00/22 Jpp 2630B 096 24X Fiche 50-295.84/08/22.8408300093

### V Operator Examinations

- 8408140372 Forwards proposed rev to 'Requalification Program for Licensed Operators Senior Operators' benior Operators (Limited)," in response to NUREC-0737 Item I A 3 1 MARSHALL, J G Commonwealth Edison Co 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26051 240 24X Fiche 50-000,84/08/07.8408140372
- --B408140369 "Requalification Program for Licensed Operators, Senior Operators (Limited) (

  \* Commonwealth Edison Co B4/07/19 10pp 26051 242 24X Fiche 50-000.84708/07,8408110372
- 8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners MALMER'R D. Region 3. Office of Director 84/08/10 Michigan, Univ of. Ann Arbor. MI 2pp 26051
- DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3

  F. Security, medical, emergency & fire protection plans
- B40B300402 Forwards summary of B40B30 meeting w/TVA.Alabama Power CorFlorida Power Corp.Florida Power % Light % Georgia Power Core selected emergency preparedness issues O'REILLY, J.P. Region 2, Office of Director 64/06/08 PARRIS, H.G. Tennessee Valley Authority 4pp 26300 116 24% Fiche 90-000,84/06/08.8408300402
- 8408280096 Ack receipt of 840709 ltt informing NRC of steps taken to correct violations noted in Insp Repts 50-259/84-17, 50-250/84-17 & 50-276/84-17 PORRELLI, DM Region 2, Office of Director 84/07/25 PARRIS, H G Tennessee Valley Authority 1p 26281 319 24% Fiche 50-259,84/07/25,8108280096
- --84082A0116 Responds to NRC 840607 ltr re violations noted in Insp. Repts 50-239/84-17.50-260/84-17.50-276/84-1/ Corrective actions temporary fire load form posted 5 daily fire load insps performed until removal of combustibles INFLES.L M. Tennossee Valley Authority 84/07/09 D'REILLY, J.P. Region 2. Office of Director 2pp 26281 320 24X Fiche 50-259.84/07/25,8408280096
- --8408280124 Forwards Insp Repts 50-259/84-17.50-260/84-17 & 50-296/84-17 on 840550-ii & notice of violation VERRELLI.D M Region 2. Difice or Director 84/06/07 PARTS.H G Fennesse Valley Authority 2pp 26281 322 24X Fichs 50-259.84/07/25.840828009s
- --8408280134 Notice of violation from insp on 840508-11 \* Region 2. Office of Director 84/06/07 ip 26281 324 24X Fishe 50 259,04/07/25,8408280096
- --8408280140 Insp Repls 50-259/84-17.50-260/84-17 & 50-296/84-17 on 840508-11 Violations noted failure to rollow fire prevention procedures for control of temporary Fire loads MADDEN.P M. Region 2. Office of Director 94/06/01 9pp 26281 325 24X Fiche 50-259,84/07/25.8408280096
- G40BD20149 Forwards rovs to implementing procedures document.consisting of IP-4, "Activation of Technical Support Ctr." IP-20, "lechnical Support Ctr Operation" 5 Rev 14 to "Radiological Emerginery Plan" "MILLS.L M Tennessee Valley Authority 64/07/27 0'REILLY.J P Region 2, Office of Director in 25886 011 24X Fiche 70-259.84/07/27.8408020145
- --B408020151 Revs to radiological emergency plan procedures, consisting of IP-6, "Activation of Technical Support Ctr" & IP-20, "Technical Support Ctr Operation" \* Tennessee Valley Authority 84/07/27 12pp 29886 012 24X fiche 50-259,84/07/27.8408020145
- --8408020156 Rev 14 to "Radiological Emergency Plan"

  \* Tennessee Valley Authority | DFN-REP R14 | 84/06/29 | 4pg 25886 024 | 24% Fiche 50-259,84/07/27.8408020145
- B408030015 Forwards safety analysis, implementation plan & implementation schedule for safety parameter display sys, per DB Vassalto B40612 confirmatory order to H0 Parris MILLS,L M Tennessec Valley Authority 84/07/30 DENTON,H R Office of Nuclear Reactor Regulation. Director 6pp 25907 118 24X Fiche 50-259.84/07/30,8408030015

- 8408230167 Ack receipt of 840801 ltr informing NR\* of steps taken to correct violations noted in IE Insp Repts 50-259/84-15.
  50-260/84-15 \ 50-296/84-15
  LEMIS R C Region 2. Office or Director 84/08/13 PARRIS H 9
  Tennessee Valley Authority ip 26206 314 74X
  Fiche 50-259 84/08/13 8408230167
- --8408230192 Responds to NRC 840712 ltr re violations noted in IE Insp Repts 50-259/84-15.50-260/84-15 & 50-296/84-15 Corrective actions total sys walkdown for control air tys flow diagrams performed by plant personnel MILLS: L M Tennessee Valley Author)ty 84/03/01 O'REILLY, J P Region 2, Office of Director 6pp 26206 318 24% Fiche 50-259 84/08/13,8408230167
- --8408230208 Responds to NRC 840523 ltr re violations noted in IE Insp Repts 50-259/84-15.50-260/84-15 & 50-296/84-15 Corrective actions 5td Practice 14 25 revised to require second party verification in hanging & removing clearance tags MILLS.L M Tennessee Valley Authority 84/06/29 0'REILLY, J P Region 2. Office of Director 1 lipp 26206 324 24x Fiche 90-259,84/08/13.8408230167
- --9408230225 Notice of violation from insp on 840326-0425 \* Region 2. Office of Director 84/05/23 5pp 26206 337 24X Fiche 50-257, 84/08/13, 8408230167
- --8408230240 IE Insp Repts 50-259/84-15,50-260/84-15 & 50-296/84-15 on 840326-0425 Violations noted misaligned sign valves on control air compressor, incorrect valve on control air sign inadequate fire protection surveillance procedures PAULK, G. L. Region 2, Office of Director 84/05/17 14pp 26206 342 24X Fiche 50-259,84/08/13,8408230167
- B408290243 Forwards justification which suppls 840612 schedular exemption request re-fire protection mods
  MILGS.L II Tennessee Valley Authority 84/09/23 DENTOW,H R
  Office of Nuclear Reactor Regulation, Director 7pp 26290 317
  24X Fiche 50-299.84/08/23,8408290245
- H General correspondence
- 8408230056 Responds to 840727 itr transmitting SL Benavider 840627 concerns refailure of reactor trip sys of nuclear plants NRC established 10CFR50 62, which requires add! features be installed at each reactor to assure shutdown if sys fails DIRCKS, W J Office of the Executive Director for Operations 84/08/15 DOMENICI.F V Senate 6pp 26213 275 24X fiche 50-000.84/08/15.8408230036
- --8408230063 Requests response to encl SL Benevider 840627 ltr re scram sys in nuclear reactors DOMENICI,P V Senate 84/07/27 KAMMERER, C C NRC - No Detailed Affiliation Given 8pp 26233 260 24X Fiche 50-000.84/08/15, 8408232054
- P Dperating license stage documents & correspondence
- 840B300434 Confirms 840601 telcon between JA Coffey & RC Lowis re 840621 enforcement conference in Region II ofc to discuss design problems w/power supply & distribution sys Proposed agenda encl O'REILLY, J P Region 2. Office of Director 84/06/05 PARRIS, H D Tennessee Valley Authority 2pp 26314 328 294 Fiche 50-259,84/06/05,840B300434
- 8408030110 Forwards Amend 70 to License DPR-68 & safety evaluation Amend rovises Tech Specs to incorporate limiting safety syssettings & conditions during sixth cycle & reflect changes from thermal power monitor mods during refueling outage CLARK, R J Operating Reactors Branch 2 84/07/11 PARRIS.H 0 Tennessee Valley Autority 2pg 25920 326 24X Fiche 50-296.84/07/11.8408030110
- --8408030125 Amend 70 to License DPR-68,incorporating limiting safety sys settings & conditions during sixth cycle & Loflecting changes from thermal power monitor mods during current refueling outage VASSALLO,D D Operating Reactors Branch 2 84/07/11 23pp 25720 328 24X Fiche 50-276,84/07/11,8408030110
- --8408030140 Safety evaluation supporting Amend 70 to License DPR-68 \* Office of Nuclear Reactor Regulation, Director 84/07/11 App 28920 351 24X Fiche 50-276.84/07/11.8408030110
- B40B140026 Forwards requests for add1 info re Mark I containment longterm program vent sys analysis & details of saismic lugs Recommends 840910 meeting w/BNL & Franklin Research Ctr to discuss response prior to submittal of formal response VASSALLO,D B Operating Reactors Branch 2 84/07/26 PARRIS,H G Tennessee Valley Authority 14pp 26061 245 24X Fiche 50-259,84/07/26,8408140026

- B408010344 Responds to 840513 request for add1 info re Mark 1 containment long-term program analyses Safety relief valve discharge piping sys mods based on most severe reflood conditions predicted by RVNIZ & RVFDR codes MILLS.L II Tennessee Valley Authority 84/07/27 DENION.H R Defice of Nuclear Reactor Regulation. Director 2pp 25866 322 24X fiche 50-259,84/07/27,8408010344
- 840B150575 Responds to 833422 submittal of Tech Spec amends per INI Item I A 1 3. "Limit Overtime! '& Ceneric Ltr 83-02 Tech Spec change request to ensure overtime controls implemented, required VASSALLO.D B Operating Reactors Branch 2 84/07/27 PARRIS.H G Tennessee Valley Authority 2pp 26080 353 24X Fiche 50-259.84/07/27.840B150575
- 840B160155 Forwards SEN on NUPEC-0737. Item 11 K 3 22 re automatic switchover of RCIC sys suction Manual switchover of RCIC suction on low water level in condensate storage tank acceptable VASSALCO.D B Operating Reactors Branch 2 B4/07/27 PARRIS.H G Tennessee Valley Authority 9pp 26126 154 24% Fiche 50-259.84/07/27.8408160155
- 8408140424 Forwards Amends 105,97 & 72 to Licenses DPR-33,DPR-52 & DPR-68,respectively & safety evaluation Amends replace word "operator" w/ "reactor operator" to provide consistent nomenclature CLARK,R J Operating Reactors Branch 2 84/07/30 PARRIS.H G Tennessee Valley Authority 3pp 26126 229 24X Fiche 50-259,84/07/30.8408160424
- --8408160426 Amends 105.97 \* 72 to Licenses DPR-33, DPR-52 t DPR-68, respectively, replacing word "operator" w/ "reactor operator" to provide consistent nomenclature & permitting fuel bandling supervised by senior reactor operator VASSALLO, D 8 Operating Reactors Dranch 2 64/07/30 12pp 26126 232 24X Fiche 50-259.84/07/30.8408160424
- --B40816042/ Safety evaluation supporting Amends 105,99 & 72 to Litenses DPR-33,DPR-52 & DPR-6B, respectively \* Office of Nuclear Reactor Regulation, Director 84/07/30 2pp 26126 244 24% Fiche 50-259,84/07/30,8408160424
- B40B070370 Suppl 1 to 831027 application for amend to Licenses DPR-33. DPR-32 & DPR-68, consisting of minor revs to Yech Specs in response to NRC 831220 comments & request for add1 info MILLS,L B Tennessee Valley Authority 84/08/01 DFNTON.H R Office of Nuclear Reactor Regulation. Director 2pp 25947 176 24X Fichs 50-259, 84/08/01,8408070370
- --8408070375 Proposed Tech Spec re radioactive gasoous offluent instrumentation surveillance
   Tennossee Valley Authority 04/08/01 44pp 2894/178 24x
  Fichs 50-289, 64/08/01.8408070370
- 8408200264 Forwards Amends 105,100 % 73 to Licenses DPR-33,DPR-52 & DPR-68,respectively & safety evaluation Amends clarify correct operating positions & identify proper action for initiating signal for suppression chamber drain valves CLAYA.R J Operating Reactors Branch 2 84/08/02 PARRIS,H G Tennessee Valley Authority 2pg 26142 345 24X Fiche 50-257.89/08/02.8498200264
- --8408200269 Amends 106.100 & 73 to Licenses DPR-33.DPR-32 & DPR-66, respectively Amends change Tech Specs re suppression chamber drain valves.clarify operating positions & identify proper action in initiating signal VASSALLO.D B Operating Reactors Branch 2 84/08/02 12pp 26142 347 24X Fichs 30-259.84/08/02.8408200264
- --8408200280 Safety evaluation supporting Amends 104,100 & 73 to Licenses DPR-33,DPR-52 & DPR-68,respectively \* Office of Nuclear Reactor Repulation, Director 84/08/02 2pp 26142 359 24% Fiche 50-259,84/08/02,8408200264
- 8408070110 Generic Ltr 84-19 to all licensess of operating reactors, applicants for OLs & holders of CPs to availability of Suppl I to NUMEG-0933. "Priorititation of Generic Safety Issues" Sec list encil EISENHUT.D O Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fishe 50-000.84/08/06.8408070110
- 8408140375 Forwards response to MRC 831012 request for add1 info re reactor protection sys power monitoring sys design mods Tech Specs will be submitted in future W/12 oversize drawings Aperture cards available in PDR DOMER, J A Tennesson Valley Authority B4/06/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 11pp 26051 1B7 24X Fiche 50-259, 84/08/09.8408140375

- 840B210U03 forwards Amends 10 .101 1 /4 to Licenses DPR-33, DPR-52 & DPR-68.respectively 7 solety evaluation Amends change Fech Specs to allow operation for 30 days w/16 main steam tunnel high temp switches bypassed CLARK, R. J. Operating Reactors Branch 2 84/08/09 PARRIS, H. G. Tennessee Valley Authority 2pp 26195 194 24% Fiche 50-259.81/08/09.8408210003
- --B40B210004 Amends 107.101 % 74 to Licenses DPR-33.DPR-52 & DPR-68. respectively changing Tech Specs to allow operation for 30 days w/16 main steam tunnel high temp switches bypassed VASSALLO, D B Operating Reactors Branch 2 84/08/09 12pp 24195 176 24X Fiche 50-259,84/08/09,8408210003
- --8408210007 Safety evaluation supporting Amends 107.101 °, 74 to Licenses DPR-33.DPR-52 & DPR-68.respectively \* DFF1co of Nuclear Reactor Regulation, Director 84/08/09 26195 208 24% Fiche 50-259.84/08/09.8408210003
- 8408200131 Forwards response to 840501 ltr 10 Criteria 1,2,10 & 11 for permanent post-accident sampling facility Info on interim sys submitted on 840606 BDMER.J A Tennessee Valley Authority 84/08/13 DENTON.K R Office of Nuclear Reactor Regulation, Director 5pp 26133 255 24X Fiche 50-259,84/08/13,8408200131
- 8408220137 Application for amend to Licenses DPR-33 DPR-32 & DPR-68, incorporating integrated schedule into license Detailed explanation of nethodology utalized definition of revised integrated schedule & fee encl
  MILLS.L M Tennessee Valley Authority 84/08/14 DENTON, H R
  Office of Nuclear Reactor Regulation, Director 86pp 26193 318
  24X Fishe 50-259, 84/08/14, 8408220137
- B40B2B025/ Forwards Amends 110,103 % 76 to Licenses DPR-33,DPR-52 & DPR-68,respectively & safety evaluation Amends revise Tech Specs to permit main steam line high temp isolation function to be inoperable for up to 4 h for testing % maint CLARK.R J Operating fractors Branch 2 84/08/15 PARRIS.H G Tennessee Valley Authority 2pp 26294 090 24% Fiche 50-259,84/08/15,840G880257
- --8408280261 Amends 110, 103 & 76 to Licenses DPR-33, DPR-52 & DPR-48, respectively, revising Tech Specs to permit main steam line high temp isolation function to be inoperable for up to 4 h for testing & maint purposes VASBALLO, D B Operating Reactors Branch 2 84/08/13 15pp 26674 072 24x Fiche 50-239,84/08/15,8408280257
- --8408280276 Safety evaluation supporting Amends 110,103 & 76 to Licenses DPR-53, DPR-52 & DPR-68 respectively a Befice of Muclear Reactor Regulation, Director 84/08/15 2pp 26294 107 24% Fiche 50-259,84/08/15,8408280287
- 8408310424 Forwards Amonds 104 & 77 to Licenses DPR-52 & DPR-68, respectively & safety evaluation Amends revise Tech Specs to change neutron flux trip setting adjustment factor CLARK.R J Operating Reactors Branch 2 84/08/17 PARRIS.H G Tennessee Valley Authority 2pp 26350 142 P4X Fiche 50-260,84/08/17-8408310424
- --840B310431 Amends 104 & 77 to Licenses DPR-52 & DPR-68, respectively, revising Tech Specs to change neutron flux trip setting adjustment factor from limiting safety sys to limiting condition for operation w/6 h action statement VASSALLO.D B Depending Reactors Branch 2 84/08/17 32pp 26350 144 24X Fichs 50-260.E4/08/17.840B310424
- --8408310432 Safety evaluation supporting Amends 104 & 77 to Licenses DPR 52 & DPR-68 respectively \* Office of Nuclear Reactor Regulation, Director 84/08/17 2pp 26450 176 24X Fichs 50-260,84/08/17,8408310424
- 8408200275 Generic Ltr 84~20 to all licensees of operating reactors & applicants for OLs re scheduling quidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISCNN(F). D 0 Division of Licensing 84/08/20 Consolidated Edison Co of New York Inc. 17pp 26276 244 24X Fiche 50-000.84/08/20.8408200275
- 8408310414 Notification of 840913 meeting w/util & Franklin Research Ctr in Knoxville.TN to discuss resolution of issues identified in request for addl snip on structural evaluation in plant-unique analysis rept re Mark I torus mod CLARK.R J Operating Reactors Branch 2 84/08/24 VASSALLO,D B Operating Reactors Branch 2 84/08/24 VASSALLO,D B Fiche 50 259.04/08/24.8408310414

- 8408310430 Notification of 1850es identified in Staff request to discuss resolution of issues identified in Staff request for add info on hydrodynimic loads in plant-unique analysis rept in Mark I torus mods CLARK, R. J. Operating Reactors Branch 2 84/08/24 VASSALLO, D.B. Operating Reactors Branch 2 19 26350 215 24% Fiche 50-259, 84/08/24, 8108310420
- Q Inspection reports, IE Bulletins \* correspondence
- B407100322 Respond. To B40505 itr providing results of reanalysis of four walls large resolves concern- re four walls identified in B40116 SER concerning IE Bulletin 83-11. "Masonry Wall Descen"

Design "
VASSALLO D B Operating Rejetors Blanch 2 84/06/26 PARRIS.H G
Tennessee Valley Authority 2pp 25513 317 24X
Fiche 50-259.84/06/26 8407100322

- 8408310109 Forwards Enforcement Conference Repts 50-259/84-21, 50-260/84-21 & 50-296/84-21 on 840621 C/REILLY.J P Region 2. Office of Director 84/07/09 PARRIS, H G Tennessee Valley Authority 2pp 26/334 227 24x Fiche 50-259,84/07/09.8108310109
- ---8408310114 Enforcement Conforence Repts 50-259/84-21.50-260/84-21 & 50-296/84-21 on 840621 Major areas discussed design errors associated w/separation of electrical cables, paralleling dissel generators & shutdown board room cooling BUILHER, R C Region 2, Office of Director CANTRELL, F S Division of Project & Resident Programs 84/07/05 & pp 26334 229 24X Fiche 30-259.84/07/09.8408310109
- 8408240338 Forwards Insp Repts 50-259/84-22.50-260/84-22 & 50-296/84-22 on 840626-29 No violations of deviations noted VERRELLI,D M Region 2. Office of Director 84/07/12 PARRIS,H 0 Tennessee Valley Authority 2pp 26236 131 24X Fichs 50-259.84/07/12.8408240338
- --8408240342 insp Repts 50-259/84-22.50-260/84-22 & 50-296/84-22 on 840626-29 No violations or deviations noted Hajor areas inspected licensee action on previous enforcement matters, welding, inservice testing, IE bulletins & LERs GIRAND, E H. (BLAKE, ) J. Region 2. Office of Director 84/07/12 App. 26236 133 24x Fiche 50-259.84/07/12.8408240338
- B400280096 Ack recript of 840/09 ltr informing NRC of steps taken to carrect violations noted in Insp Repts 50-259/84-17.
  50-260/84 17 % 50-294/84-17
  VERRELLI,D M Region 2, Office or Director 84/07/25 PARRIS,H 0
  Tennessee Valley Authority ip 26201 319 24%
  Fiche 50-299,84/07/25,8400200096
- ~-8408280116 Responds to NRC 840507 itr re violations noted in Insp Repts 50-259/84-17.50-260/84-17 & 50-296/84-17 Corrective actions temporary fire load form posted & daily fire load inspa performed until removal of combustibles MILLS.L M Tannessee Valley Authority 84/07/09 D'REILLY, J P Region 2. Office of Director 20p 26281 320 24X Fiche 50-259,84/07/25,8408280096
- --8408280124 forwards Insp Repts %0-259/84-17,50-260/84-17 & 50-296/84-17 on 840508-11 & notice of violation VERRELLI.D M Region 2. Dirice of Director 84/06/07 PARRIS.H G Tennessee Valley Authority 2pp 26281 322 24X Fiche 50-259,84/07/25,8408280096
- --8498300134 Notice of violation from insp on 840508-11 \* Region 2, Office of Director 84/06/07 ip 2628; 324 24X Fiche 50-259,84/07/25,8408280096
- ~-8408280140 Insp Repts 50-259/84-17.50-260/84-17 v 50-296/84-17 on 840548-11 Violations noted failure to follow fire prevention procedures for control of temporary fire loads MADDLN.P h , MILLER.W H , CONLON.T E Region 2, Office of Director 84/06/01 9pp 26201 329 24X Fiche 50-259.84/07/25, 84002800096
- B407250229 IC Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Syc list entl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc. 119pp 25865-04/ 24X Fiche 50-000.84/07/27, 8407250229
- B40B270196 Ack receipt of B40719 ltr informing NRC of steps taken to correct violations noted in lnsp Repts 50-259/84-10. 50-240/84-10 & 50-296/84-10 BC CORRELLI,D M. Region 2. Office of Director 84/07/31 PARRIS,H G Tennessee Valley Authority 1p 26257 352 24X Fichs 50-259,84/07/31 B408270196

- --8408270:97 Responds to NRC 840507 ltr reviolations noted in Insp. Rept. 50-259/84-10.50-280/84-10.50-286/84-10. Corrective actions Procedures 1053 & 1053A revised to correct procedural violations
  MICLS L.M. Tennessee Valley Authority 84/07/19 D'REILLY, J.P. Region 2, Office of Director 2pp 26257 353 24X
  Fiche 50 259,84/07/31,8100270196
- 8408010333 IE Into Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc 1:st encl JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26068 001 24X Piche 50-000, 84/08/06, 8408010333
- 840801033/ IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Moet Efficiency Requirement " Svc list encl JCRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc. 123pp 26057 158 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN,C L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York, Inc. 120pp 26127 118 24X Fiche 50-000,84/08/08,8408070120
- B40B150213 Forwards rept required by Item IJI C 5 of 830826 order repting insp Results of 108CC insp.including pre & post-induction heating stress improvement insps, provided Unacceptable indication found in head spray piping DOMER. J A Tennessee Valley Authority 84/08/09 DENTON, H R Office of Nuclear Reactor Regulation. Director 100pp 26066 136 24X Fiche 50-296,84/08/09,8408150213
- 8408070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list encl
  GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Gongolidated Edison Co of New York, Inc
  125pp 26130 001 24X Fiche 50~000,84/08/10,8408070376
- B40B100009 IC Info Notice B4-63, "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN,E L Division of Emergency Proparedness & Engineering
  Response (Post 830103) B4/08/13 Consolidated Edison Co of New
  York, Inc. 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408230167 Ack receipt of 840801 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-25988-15, 50-260404-15 50-260404-15 50-260404-15 LEWIS,R C Region 2, Office of Director 84/08/13 PARRIG.H G Tennessee Valley Authority 1p 26206 316 24X Fiche 50-259,84/08/13,8408230167
- --8408230180 Ack receipt of 840629 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-276/84-15 Supplemental response expected by B40801

  LEWIS.R C Region 2, Office of Director 84/07/12 PARRIS.H 0

  Tennessee Valley Authority in 26206-317 24X

  Fichs 50-259,84/08/13,8408230167
- --8408230192 Responds to NRC 840712 ltr re violations noted in IE Insp Repts 50-259/84-15,50-260/84-15 t.50-296/84-15 Corrective actions total sys walkdown for control air sys flow diagrams performed by plant personnel MILLS.t. M. Tennessee Valley Authority 84/08/01 O'REILLY, J.P. Region 2, Office of Director App 26206 318 24X Fiche 50-259,84/08/13,8408230167
- --8408230208 Responds to NRC 840523 ltr re violations noted in IE Insp Repts 50-259/84-15.50-260/84-15 & 30-296/84-15 Corrective actions 8td Practice 14 25 revised to require second party verification in hanging & removing clearance tags MILLS.L M Tennessee Valley Authority 84/06/29 O'REILLY, J P Region 2, Office of Director 11pp 26206 324 24X Fiche 30-259,84/08/13.8408230167
- --8408230219 Forwards IE Insp Repts 50-259/84-15,50-260/84-15 & 50-296/84-15 on 840326-0425 & notice of violations Add1 attention must be given to Tech Spec maint LEWIS.R C Region 2. Office of Director 84/05/23 PARRIB,H 0 Tennessee Valley Authority 2pp 26206 335 24X Fiche 50-259,84/08/13,8408230167
- --9408230223 Notice of violation from insp on 840326-0425 \* Region 2, Office of Director 84/05/23 5pp 26206 337 24X Fiche 50-259,84/08/13,8408230167

- --B408230240 IE Insp Repts 50-259/B4-15,50-260/84-15 2 50-296/84-15 on 840326-0465 violations noted miseligned sys valves on control air compressor, incorrect valve on control air sys i inadequate fire profection surveillance procedures PAULK.G L., PATTERSON, C A., CANTRELL, F S. Region 2, Office of Director 84/05/17 14pp 26206 342 24% Fiche 50-259,84/08/13,8408230167
- 840810003B IE Info Notice 84-64, "BWR MPCI Initiation Seal-In & Indication " Svc list encl JOROAN.E C. Division of Emergency Preparedness & Engineering Response (Post 80100) 94/08/15 Consolidated Edison Co. of New York. Inc. 104pp 26198-093 24% Fiche 50-000.84/08/15.8408100038
- 8409100021 IR Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment." Svc list encl
  udRDAN.E L Division of Emergency Proposedness A Engineering
  Response (Post 830103) 84/08/16 Consolidated Edison Co of New
  York, Inc. 118pp 26178 001 24% Fiche 30-000,84/08/16,8408100021
- B40Bl00055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auriliary Feedwater Train " Svc list anci JORDAN, E. L. Division of Emergency Preparedness % Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 031 24X Fichs 50-000-84/08/17,8409100055
- 8408140208 IE Info Notice 84-67. "Recent Shubber Inservice Testing W/ High Failure Rates." Svc list enci JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 64/08/17 Consolidated Edison Co. of New York, Inc. 122pp 26276-122 24X Fiche 50-000.84/08/17,8408140208
- 8408240109 Forwards response to NRC 840720 ltr re violations noted in listed insprepts & Proposed Civil Penalty Action EA 84-095 Corrective actions include rev to Plant Instruction II-74 to upgrade post-trip review Civil penalty fee will be wired DOMER. J A Tennessee Valley Authority 84/08/20 DEYOUNG, R F Birecter's Office, Office of Inspection and Enforcement 10pp 26228 233 24X Fiche 50-259.84/08/20.8408240109
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenold Valves " Svz list encl JORDÁN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidates Edison Co. of New York, Inc. 115pp 26927 COS 24X Fiche 50-000,84/06/21,8408210142
- R Periodic operating reports & related correspondence
- 8408050098 "NPDES Discharge Monitoring Rept for Apr 1984 " \* Tennessee Valley Authority 84/04/30 54pp 25935 208 24x Fiche 50-259,84/04/30,8408060098
- B40B270366 Forwards "Effluent & Masto Disposal Semiannual Rept, Supplemental Info.First Half 1984" & revised "Effluent & Wasto Disposal Semiannual Rept Liquid Roleases for Second Half 1983 Batch Mode " JONES. O T Tennessee Valley Authority 84/08/21 Director's Office Office of Inspection and Enforcement 1p 26240 320 24x Fiche 90-257.84/08/21.8408270366
- --BADB270369 "Effluent & Haste Disposal Semiannus) Rept Supplemental Inforfirst Half 1984 "

  \* Tennessee Valley Authority 84/06/30 15pp 26240 DR1 24X Fiche 50~259,84/08/21,8408270366
- --8408270374 Revised 'Effluent & Waste Disposal Semionnual Rept Liquid Releases for Second Half 1983 Batch Mode " \* Tennessee Valley Authority 83/12/31 ip 26240 336 24x Fichs 50-259,84/08/21.8408270366
- 8 Reportable occurrences, LERs & related correspondence
- 8408280317 Part 21 rept re failure of lTE~27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diode must be added Affected units listed DUVALL.D D Brown Boveri Corp. (Subs. of Brown Boveri & Ca., Ltd.) 84/03/13 DEVOUND.R C Director's Office. Office of Inspection and Enforcement 3pp. 26191-357 24X Fiche 50-000,84/03/13,840022031/
- B408240348 Part 21 rept re presence of loctito-242 in CRD hydraulic control unit scran pilot solenoid valve plunger Initially reported on 640413 New thread locking devices investigated SHERMODD, G O general Electric Co B4/04/13 DEVOUNDER C ettor's Office, Office of Inspection and Enforcement 3pp 22 256 24% Fiche 50-000, 84/04/13, 8408240348

- 8408200412 LTR 84-005-01 on 840517, this of jet pump instrument norrige found two welds in need of repair Weld overlay procedure completed prior to starting Add) wolds will be inspected in upcoming outages w/840810 ltr SMITH, D. L. JONES, O. F. Tennesses Villey Authority 84/08/10 3pp 26138 261 24% Fichs 50-796,84/08/10.8408200112
- 8408270150 LER 84-006-02 on 840517 discovered 2 out of 10 welds HUM27U150 LER 84-006-02 on 840517 discovered 2 out of 10 welds inspected on jet pumb instrument notiles in need of repair Caused by intergranular stress corresion cracking Welds repaired by Ueld overlay procedure M/B40817 Ltr SMITH.D L. JONES. G T Tennessee Valley Authority 84/08/17 3pp 26245 154 24% Fiche 50~276.61/08/17,8100D70150
- B408310186 Part 21 lept re torus-to-leartor bidg vacuum breakers Memo of B40820 telicon reporting equipment quality & esparation of controls to butterfly valves encl OL larks tethnical info to adequately evaluate condition:
  VILLAR General Electric Co. 84/08/21 ROSSI.( C. Director's Office, Office of Inspection and Enforcement Opp. 26318-327 24x
  Fiche 50-000-04/08/21.8408310184
- V Operator Framinations
- BADB310D36 Confirmation of action it: 10 BAOD21 telenn between RC Lewis & JA Coffey concerning results of operator exams conducted on BAO323 Operators who failed exam prohibited from licensed duties until Sertion: 6 or 7 completed satisfactority O'REILLY, J.P. Region 2, Diffice of Director: 84/05/23 PARRIS, H. Q. Tennessee Valley Authority Spp 26/39 020 2/4% Fiche 90-299,84/05/23.8408310036
- DOCKET 50-297 NORTH CARD THA STATE UNIV PULSTAR REACTOR P Derating license stage documents & Correspondence
- BAOBO20049 Application for amend to (iconso R 120.chamying Tech Specs to inturporate organizational changes PAULIUN,B R North (arolina State Univ. Raleigh, NC 184/07/26 Division of (iconsing 19p 2889) 289 248 Fiche 90 297,84/07/26, 0408000005
- -8408020069 Propused Tech Spers in orporating organizational changes \* North Carolina State Univ , Raleigh, NC 84707726 PSep PSB91 296 244 Cirbs 30 297,84707726,8408020065
- DOCKET 50 290 COOPER NUCLEAR STATION
- F. Bacuvity, medical, omerguncy & fire protection plans
- 8408076267 Ray 4 to Emergency Plan Implementing Procedure EPIP 5 / 21, "Emergency Equipment Inventory " UZBAOUGE 1tm WINDIAM, 8 , WHITMAN, B , PILANLOJ M Nobraska Public Power District 8470801 (DLLING) J T Region 4 (DFILE of Director 30pp 25949 209 24% Films 50 (Vd. 04708701 0408970267
- Q400070316 Revised Pages 5-11-5 64-6 6-6 7-6 25-8 23-8 D 2 to station omargency plan M7040001 ltr Pleakled II Nebraska Public Power District (04/00/01 COLLING.) T Region 4. Office of Director (0pp 25947 100 248 Ct. he to 298-04/08/01-0498070 Hz
- Q408160072 forwards safety parameter display sys (OPDB) preimplementation and the solts in bodule for submittal of add 5005 info due within AO days of its receipt NURCO 0717, Supplit guidelines require resolution VASGALLO. D.B. Operating leactors Branch 2, D470H701 PILANT, J.B. Nebraska Public Power District 129p 26126 (229 24x fiche 30 276,0470H703, B40HAOOM).
- 840B140431 Responds to NRC 840604 review of detailed control room design review program plant per Buppl 1 to NUBLO-0717 Summary rept will be submitted by Dec 1934
  PILANI J M. Nebranka Public Power District 8470B709
  VASBALLO D D. Aperating Reactors Branch & Top. 26050 359 24x
  Fiche 86 296:8476B797; 849B14643B
- 04002401/1 "Hadiation Protection Plan" \* Nebraska Public Power District 04/08/15 | LIGENBUT D Q Division of Licensing 50pp Physel 105 24x Lichs 80 040.04/08/15 BA082401/1
- BAOBERGIDE Lorwards (her Rept 50 298764 17 on 640612-15 & notices of violation & deviation Notices withheld (ref 1001873 21) JUNESON F H. Region 4. Office of Director 04708716 PILANT, J 8 Hebrake Public Pause (Nietrit 250 2626 220 24x Fiche 50 298,04708715-04988290101 PELANTIJA

- --8408290104 Insp Rept 50-298/84-13 on 840412-15 re security plan & implementing procedures One violation & four deviations identified Details withheld (ref 10CFR/3 21)

  KELLY J A . HALL,R E . JAUDON J P Region 4. Office of Director 84/08/15 1p 26298 227 24% Fiche 50-298.84/08/16.8408290101
- I Financial information
- 8408150447 Submits info demonstrating ability to obtain funds for payment of deferred premiums within 3-month period Annual rept to Securities? Exchange Commission for 1983 % uniform forecast form for security analysts enci PILANT.J N Nobraska Public Power District 84/08/03 Office of Nuclear Reactor Regulation. Director 82pp 26077 157 24X Fiche 50-298.84/08/03.8408150447
- P Operating license stage documents & correspondence
- 8408100143 Forwards Pages 2-14 & 2-15 which were inadvertently omitted from 840305 Rev I to "Cooper Nuclear Station GA Program "
  PILANT, J M Nebraska Public Fower District 84/04/03 COLLINS, J T Region 4, Office of Director 3pp 25988 273 24x
  Fiche 50-298,84/04/03,8408100145
- 8408010018 Forwards SER & EG&G technical evaluation rept re response to Generic Ltr 81-04 (Rev 1 to NUREG-0313) concerning BWR coolant pressure boundary piping VASSALLO,D B Operating Reactors Branch 2 84/07/23 PILANT,J M Nebraska Public Power District 3pp 25867 305 24X Fiche 50-298,84/07/23,8408010018
- --B408010022 Safety evalution re 10SCC in RCPB piping sys.per Generic Ltr 81-04 Licensee response does not meet NUREQ-0313 guidelines Further action will depend upon responses to Generic Ltrs 84-07 & 84-11 \* Office of Nuclear Reactor Regulation, Director 84/07/23 4pp 25867 308 247 Fiche 50-278,84/07/23,8408010018
- --8408010027 "Technical Evaluation of Integrity of Cooper Nuclear Station Reactor Coolant Boundary Piping Sys " NAG41A.P K EG&G Inc FIN A-6429 EGG-FM-6521 B3/07/31 KGD.W H Division of Engineering 40pp 25867 312 24X Fiche 50-298.84/07/23,8408010018
- 8408070295 forwards response to 840529 request for additinfore TMI Item II K 3 28. "Gualification of Automatic Depressurisation Sys Actumulators." per 10CFR50 54(f) AE verified accumulators.components % tubing per Seismic I specs PILANT.J M Nebraska Public Power District 84707/26 EISENHUT.D G DIVISION OF Licensing 5pp 25948 078 24X Fiche 50-298.84/07/26.8408070295
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues "Svc list encl EISENHUT, D @ Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000.84/08/06.8408070110
- 840B200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT. D & Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000,84/08/20,8408200275
- Q Inspection reports. IE Bulletins & correspondence
- 8408060202 Forwards figures, charts % graphs emitted from 840511 exam rept JOHNSON, E.H. Region 4, Office of Director 84/07/03 PILANT, J.M. Nebraska Public Power District 10pp 25936 162 24X Fiche 50-298,84/07/03,8408060202
- B408030011 Responds to NRC 840611 ltr re violations noted in IE Insp Rept 50-278/84-09 Corrective actions matls admitting disposal by destruction or return to vendor identified; tagged & marked Marehouse personnel attended refresher session PILANT. J M Nebraska Public Power District 84/07/05 JOHNSON, E I Region 4. Office of Director 2pp 25915 315 24X Fiche 50-278,84/07/05,8408030011
- 8408070034 Forwards requalification program audit rept from exam condurted in May 1984 JDHN80N.E H Region 4, Office of Director 84/07/05 PILANT, J M. Nebraska Public Power District 2pp 25992 246 24X Fiche 50~298,84/07/05.8408090034

- --8408090037 Requalification program audit rept from exam conducted in May 1984 Audit results requalification program marginal PELLET, J L , COLLEY, A Region A, Office of Director 84/04/22 42pp 25992 268 24x Fiche 50-298
- 8407,250227 IE Info Notice 84-57. "Operating Experience re Moisture Intruston in Safety-Related Electrical Equipment at Commercial Power Plants " Syr list encl JDROAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc. 117pp 25865 047 24X Fiche 50-000,84/07/27,8407250229
- 8408030044 Ack receipt of 840705 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-298/84-09 Corrective actions will be reviewed during future insp JOHNSON.E H. Region 4. Orfice of Director 84/07/27 PILANT, J. Mebraska Public Power District ip 25907 029 24% fiche 50-298,84/07/27.8408030044
- 8408230010 Forwards IE Insp Rept 50-298/84-14 on 840625-29 No violations or deviations noted JDHNBON.E H Region 4, Office of Director 84/07/31 PILANT, J M Nebraska Public Power District 2pp 26214 201 24X Fiche 50-298.84/07/31.8408230010
- --8408230013 IE Imsp Rept 50-298/84-14 on 840625-27 No violations or deviations noted Major areas inspected mod activities re recirculation loop.core spray loop & reactor water cleanup piping replacement BARNES.I . JAUDON.J P Region 4. Office of Director 84/07/31 8pp 26214 203 24x Fiche 50-298.84/07/31.8408230010
- B408100107 Forwards QA Program Insp Rapts 99900911/B4-01,99900715/B4-01 & 99900325/B4-01 Requests evaluation of significance of reported findings re quality & acceptability of vendor product or svc W/o encis
  JDHNSON,E H Ragion 4, Office of Director B4/08/03 FILANT,J M Nebraska Fublic Power District 2pp 25990 200 24X
  Fiche 50-298,84/08/03,8408100107
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN,E E Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24% Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84~60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Comsolidated Edison Co of New York. Inc 123pp 26067 158 24X Fiche 50~000.84/08/06.8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PMR Refueling Cavity " Svc list encl JORBAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24% Fiche 50-000,84/08/08,8408070120
- 8408270487 Forwards Insp Rept 50-278/84-11 on 840501-0630 & notice of violation
  JOHNSON, E. H. Region 4, Office of Director 84/08/08 PILANT, J M. Nebraska Public Power District 2pp 26256 170 24X
  Fiche 50-298,84/08/08.8408270489
- --8408270494 Natice of violation from insp on 840501-0630 \* Region 4. Office of Director 84/08/08 2pp 26256 172 24X Fishe 50-298,84/08/08,8408270489
- --8408270500 Insp Rept 50-298/84-11 on 840501-0630 Violations noted failure to have procedures for maint & failure to perform safety review of change made to facility JOHNSON, E H., DUBOIS, D L., VANDELL, L A Region 4, Office of Director 84/08/08 14pp 26236 174 24X Fiche 50-298,84/08/08,8408270489
- 8408070376 JE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list encl GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24x Fiche 50-000, 84/08/10,8408070376
- 8408100009 IE Info Notice 84-63. "Defective RHR Replacement Piping "
  Svc list anci
  JURDAN.E L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

- 8408100038 IE Info Notice 84-64, 'BWR HPCI Initiation Seal-In &
  - Tollow B to Info Notice 84-64, 'BMK HPC| Initiation Seal-In & Indication 'Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/08/15 Consolidated Edison Co of New York, Inc. 104pp 26198 073 24X Fiche 50-000, 84/08/15, 8408100038
- 8408100021 IS Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc
  - list enc]
    JORDAN.E L. Division of Emergency Preparedness & Engineering
    Response (Post 830103) 84/08/14 Consolidated Edison Co. of New
    York, Inc. 118pp 26198 001 24% Fiche 50-000,84/08/16,8408100021
- B408290101 Forwards Into Rept 50-298/84~13 on B40612-15 & notices of violation & deviation Notices withheld (ref 10CFR73 21) JOHNSON,E H. Region 4. Office of Director B4/08/16 PILANT,J M Nebraska Public Power District 2pg 26278 220 24X Fiche 50-298/84/08/16,8408290101
- --8408290104 Insp Rept 50-298/84-13 on 840612-15 re security plan & implementing procedures the violation & four deviations identified Details withheld (ref 100FR/3 21) KELLY,J A. HALL,R E. JAUDON,J P. Region 4. Office of Director 84/08/15 1p 26298 822 24% Fiche 50-298/84/08/16,8408290101
- B408100055 lE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JRBOAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24x Fiche 50-000.04/08/17.8408100055
- 840Bi4020B IE Info Notice 84-67. "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24% Fiche 50-000,84/08/17,8408140208
- B40B210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Miring to Solehold Valves " Svc list encl JURDAN E L Division of Emergency Preparedness & Engineering Response (Post 8301073) B470B/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24% Fiche 50-000.84708/21,8408210142
- R Periodic operating reports & related correspondence
- 840B100014 Forwards errata to "Semiannual Operating Rept Radioactive Effluents, Jul-Dec 1983." consisting of corrected Tables 5.6.9 & 11 of App C
  PILANTOJ M Nebrasia Public Power District 84/07/09 GOLLINS, J T Fig. Region 4. Office of Director 1p 25989 273 Figh 50-298-84/07/07.8408100014
- --8408100017 Errata to "Sentannual Operating Rept Radioactive Effluents Jul-Doc 1983 " \* Nebraska Public Power District 83/12/31 6pp 25989 a 24X Fiche 50-298,84/07/09,8408100014 83/12/31 6pp 25989 274
- S Reportable occurrences, LERs & related correspondence
- 8408240348 Part 21 rapt re presence of Loctite-242 in CRD hydraulic control unit scram pilot splenoid valve plunger initially reported on 840413 New thread locking devices investigated SHERHOOD, G. G. General Electric C. 84/04/13 DEVOUNG. R. C. Director's Office, Office of Inspection and Enforcement. 3pp 26222 256—24X Fiche 50-000,84/04/13,8408240348
- 8408240072 LER 84-009-00 on 840719 operation of APRM flow blased scram & rod block sys inconsistent w/Tech Space Caused by configuration changes not fully incorporated in Tech Space Tech Space revised W/840817 ltr
  BALLINGER.P.L., THOMASON, P. V. Nebraska Public Power District 84/08/17 3pp 26237 014 24X Fiche 50-298,84/08/17.8408240072
- 8408310355 Forwards "Contamination of Gnubber Bleed Screw & Lockup Poppet Valve." technical review rept Event probably unique & does not have generic implications Corrective actions wate No further action required

  Reactor Operations Analysis Branch 84/08/20 SEYFRIT, Perations Analysis Branch 1p 26350 313 24X BEYFRITAK V
  - ination of Snubber Bleed Screw & Lockup Poppet review rept.

    Perations Analysis Branch 84/08/20 3pp
    1che 50-278,84/08/20,8408310355

- 8408310186 Part 21 rept re torus-to-leactor bldg vacuum breakers Memo of 846820 telcon reporting equipment quality & separation of controls to butterfly valvos enti 65 lacks technical info to adequately evaluate condition

  VILLAR General Electric Co 81/08/21 ROSSI.C & Director's Dffice Uffice of lospection and Enforcement 3pp 26318 327 24x Fiche 50-000.84/08/21.8408310186
- V Operator Elaminations
- 8408060202 Forwards figures, charts & graphs omitted from 840511 exam rept
  JOHNSON, E. H. Rogion 4. Office of Director 84/07/03 PILANT, J.M.
  Nebraska Public Power District (Opp. 25936 162 24X
  Fiche 50-298.84/07/03,8408060202
- B408090034 Forwards requalification program audit tept from exam conducted in May 1984 JOHNSON, E.H. Region 4. Office of Director 84/07/05 PILANT, J.M. Nebraska Public Power District 2pp 25992 266 24X Fiche 50-278:84/07/05,8408090034
- ---B408090037 Requalification program audit rept from exam conducted in May 1984 Audit results requalification program marginal PELLET, J. L., CODLEY, R. A. Region 4. Office of Director B4/06/P2 42pp 25992 268 24% Fichs 50-298,84/07/05.8408090034
- DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2 F Security, medical, emergency & fire protection plans
- B408020150 Ack receipt of 840705 ltr forwarding scope & objectives for 08020150 Ack receipt of 840705 ltr forwarding scape & objectives fo 840911 emergency preparedness extrictse Proposed objectives acceptable, w/inclusion of assembly/accountability PAPERIECLO, C. J. Region 3, Office of Director 84/07/27 FAY, C. W. Wisconsin Electric Power Co. 1p. 25886-020 P4X Fiche 50-266.84/07/27.8408020150
- --8408020155 Forwards draft scope for 840911 emergency preparedness exercise Detailed scenario will be provided by first wk of Aug & associated controller packages will be provided by third wk of Aug BRITT.R W Wisconsin floctric Pawer to 84/07/05 Regian 3. Office of Director 10pp 25886 029 2. Fithe 50-266.84/07/27.8408020150
- 8408020160 Notifies that review completed re 840629 revs to App C of emorgancy plan Plan changes do not downgrade offectiveness of emergency plan Plan changes do not downgrade offectiveness of emergency plan PAPLRICILD, C. J. Region 3, Office of Director 04/07/27 Wisconsin Electric Power Co. Ip. 29886 037 24X Fiche 50-266,04/07/27,8408020160 Π4/0//27 FAY, C W
- 8408030167 Forwards Rev O to "Control Room Dosign Review Program Plan." in partial fulfillment of Generic Ltr 82-33, "Guppl 1 to NUREO-0737 ~ Requirements for Fmergency Response Capability "FAY.C W Wisconsin Electric Power Co 84/07/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 25911 193 24X Fiche 50-266,84/07/31,8408030167
- ~-8408030170 Rev O to "Control Room Design Review Program Plan
  \* Misconsin Electric Power Co 84/07/31 180pp 25911 i
  Fiche, 30-264, 84/07/31, 8408040167 25711 174 P4X
- B40B170198 Ack receipt of 840711 ltr informing NRC of steps taken to correct noncompliance noted in 16 Insp Repts 50-266/84-00 & 90-301/84-06 AXELBON, W I Region 3. Office of Director 84/08/13 (ASBIDY, T. AXELEON, W. L. Region 3. Office of Director 84/00/13 (ASSIDY, T. J. Wisconsin Electric Power Co. ip Polits 09.) 24x Fiche 50-266,84/08/13,84081/0198
- --B408170203 Forwards response to NRC B40711 ltr re noncompliance noted in IE Insp Repts 30-265/84-00 & 30-301/84-06 Encl withheld (ref 10CFR73 21) CASSIDY, T J. Wisconsin flectric Power Co. 04/07/31 KCPPLER, J G Region 3, Office of Director ip 26/18 094 24X Ficho 50:266,84/09/13,8408170198
- B40B210343 Revised emergency plan maint procedures including 1 1 re routine check, maint, calibr 2 inventory schedule for health physics equipment & 1 2 re routine check, maint & calibr instructions for emergency plan equipment W/840814 1tr # Hisronsin Cleatric Power Co. 84/08/14 DENTON, H.R. Defice of Nuclear Reactor Regulation, Director 74pp 26181 043 24x Fiche, 50-266, 84/08/14, 8408210343 Office of

- B40B290197 informs that NRC representative will not be available to attend fEMA preexercise briefing W Shell will contact FEMA after NRC B40910 entrance \* attend 840913 public critique Region III representation at FYMS public critiques unlikely PAPERIELLO C. J. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/24 WEAVER N. J. Federal Emergency Management Agency 1p 262911/6 24X fiche 50-264.84/08/24, 8408290197
- --84082Y0206 forwards schedule for 1981 emergency exercise NRC representation at pre & post-oxercise bilefings requested MEAVER.W J. Fuderal Emergency Management Agency 84/08/16 MEPPLER.J G. Region J. Office of Director 33p 26291 177 24X Fiche 50-266,84/08/24,8408290197

#### H General correspondence

- 8408090514 Informs that NRC deleting organization on distribution for correspondence between NRC 3 util Correspondence available in LPDR COUNTRY OF CONTRIBUTE STREET, 3 84/07/27 ANDERSON COUNTRY OF CONTRIBUTE STREET, 3 84/07/27 ANDERSON CONTRIBUTE STREET, 3 84/07/27 AND CONTRIBUTE STREET, 3 84/07/
  - COLBURN. T G Operating Reactors Branch 3 84/07/27 ANDERSON, F Wisconsin's Environmental Decade Ip 25983 115 24X Fiche 50-266.84/07/27.8408090514
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8407310166 Forwards rev to updated FSAR for Point Beach Nuclear Plant.Units 1 & 2 FAY.C W Wisconsin Electric Power Co 84/07/20 DENTON, H R Office of Nuclear Reactor Regulation. Director MILLER, J R Operating Reactors Branch 3 2pp 25905 001 24X Fishe 50-266.84/07/20.8407310166
- --8408020148 Rev to updated FSAR for Point Beach Nuclear Plant.Units 1 & 2 \* Wisconsin Electric Power Co 84/07/20 360pp 25905 010 24X Fiche 50-266.84/07/20.8407310166
- P Operating license stage documents & correspondence
- 8408010120 Forwards marked-up radiological ETS for Units 1 & 2 Review of comments requested in preparation for discussion at maeting w/NRC, tentatively scheduled for mid-Aug in Bethesda. MD MILLER, J R Operating Reactors Branch 3 84/07/17 FAY, C W Wisconsin Electric Power Co 81pp 25872 216 24X Fichs 50-266.04/07/17.8408010120
- 8408070492 Forwards comments on 840502 amend application for Tech Spec changes concerning containment tendon surveillance Mod of application or justification of position requested within 45 days MILLER, J. R. Operating Reactors Branch 3 84/07/24 FAY, C. W Wisconsin Electric Power Co. App. 25956 249 24X Fishe 50-266,88/07/24,8408070492
- 8408060127 Advises of revised schedule to install new single-failureproof auxiliary bldg crame trolley Installation will begin following Spring 1985 Unit i refueling outage Final design review & license amend application will be submitted BRITT.R W Wisconsin Electric Power Co 84/07/30 DENTON.H R Office of Nuclear Reactor Regulation. Director MILLER.J R Operating Reactors Branch 3 1p 25933 057 24X Fiche 50-266.84/07/30.8408060127
- 8408070328 Forwards Rev 1 to "Process Control Program." listing vendor procedures governing processing & packaging of solid radwaste BRITT,R W Wisconsin Electric Power Co 84/08/01 DENTON.H R Office of Nuclear Reactor Regulation. Director MILLER.J R Operating Reactors Branch 3 ip 25945 139 24X Fiche 50-266.84/08/01.8408070328
- --B40B070330 Rev 1 to "Process Control Program"

  \* Wisconsin Electric Power Co 84/08/01 3pp 25945 140 24%
  Ficho 50-266.84/08/01.8408070328
- 8408200002 Forwards request for addl info re 830314 & 0906 requests for Tech Spec changes allowing use of Westinghouse optimized fuel W/o enci
  MILLER, J R Operating Reactors Branch 3 84/08/01 FAY, C W
  Wisconsin Electric Power Co ip 26143 264 24X
  Fiche 50-266,84/08/01.8408200002
- B408070030 Responds to B40326 request for periodic updates re-progress made toward alleviating shortage of licensed operators Adequate number of licensed operators anticipated after scheduled reactor license exam in Dec 1984 BRITT,R W Wisconsin Electric Power Co 84/08/02 DENTON.H.R Office of Nuclear Reactor Regulation, Director MILLER,J R Operating Reactors Branch 3 2pp 25950 036 24X Fiche 30-266,84/08/02,8408070030

- G40B070245 Requests extension or qualification program completion schedule to end of June 1985 refueling outage for Crosby lift indicating switch assemblies % Yeam thermocouple connectors

  BRITT,R W Wisconsin Electric Power Co 84/08/02 DENTON,H R Office of Muclear Reactor Regulation, Director MILLER,J R Operating Reactors Branch 3 3pp 25949 017 24X

  Fiche 50-266,84/08/02.8408070245
- B40B070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs 9 holders of CPs re availability of Suppl I to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list enci ETSENHUT.D Q Division of Licensing B4/08/04 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000.84/08/06.840B070110
- 8408160482 Summary of 840724 meeting w/Westinghouse Owners Group re upper plenum injection for two loop plants DIGANNI,D C Operating Reactors Branch 3 84/08/07 Operating Reactors Branch 3 App 26108 327 24% Fiche 50-000,84/08/09, 8408160482
- 8408270233 Forwards proprietary & honproprietary responses to request for add1 info re Tech Spec Change Request 87 concerning use of Westinghouse optimized fuel assembly Application For withholding proprietary response (ref 10CFR2 790) encl FAY, C W Hisconsin Electric Power Co 84/08/17 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 Jpp 26242 205 24X Fiche 50-266.84/08/17.8408270233
- --8408270244 Requests proprietary responses to NRC questions re optimized fuel assembly design be withheld (ref 10CFR2 790) Affidavit encl HIESEMANN.R A Westinghouse Electric Corp. 84/08/07 DENTON.H R Office of Nuclear Reactor Regulation. Director 111pp 26242 208 24X Fichs 50-266.84/08/17.840827023
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions EVC list encl EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 50-000,84/08/20,8408200275
- 8408280216 Forwards add1 info re methodology & results of analysis performed to determine impact of parking rod cluster control assemblies at 225 steps withdrawn position, per request FAY.C W Wisconsin Electric Power Co 84/08/22 DENTON.H R Office of Nuclear Reactor Regulation, Director MILLER,J R Licensing Branch 3 4pp 26279 183 24X Fiche 50-266.84/08/22, 8408280216
- 8408280128 Confirms 840823 telcon between R Soizert & C Trammel re existence of potential defect in Anker-Holth large bord snubbers Info provided in 840810 ltr presently being evaluated to determine inpact upon facility operations FAY.C W Wisconsin Electric Power Co 84/08/24 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 ip 26261 319 24X Fiche 50-266.84/08/24,8408280128
- B40B3102B4 Advises that nods to motor operated discharge valves for electric driven suxiliary feedwater pumps completed & tested satisfactors19 EISENHUT, D O Division of Licensing 84/08/24 NORELIUS, C E Division of Project & Resident Programs 1p 26351 234 24X Fiche 50-266.84/08/24.840B3102B4
- G Inspection reports. IE Bulletins & correspondence
- 8408070184 forwards IE Insp Repts 50-266/84-12 & 50-301/84-10 on 840711 No noncompliance identified LITTLE: K S Region 3. Office of Director 84/07/23 FAY, C, W Misconsin Electric Power Co 2pp 20792 075 24X Fiche 50-266:84/07/23:8408070184
- --8408070189 IE Insp Repts 50-266/84-12 & 50-301/84-10 on 840711 No noncompliance identified Major areas inspected followup of valve shaft insps on main steamline isolation swing check & swing stop valves
  JONES, D E. DANIELSON, D H Region 3, Office of Director 84/07/23 2pp 2992 077 24% Fichs 50-266, 84/07/23, 8408070184
- 8408150379 Forwards IE Insp Repts 50-266/84-10 & 50-301/84-08 on 840825-29 No noncompliance noted PAPERIELLO:C J Region 3. Office of Director 84/07/25 FAY.C W Wisconsin Electric Power Ca 20p 26077 320 24X Fiche 50-266,84/07/25,8408150399

- --8408150406 IE Insp Repts 50-266/84-10 & 50-301/84-08 on 840625-29 No violations noted Major areas inspected operational radiation protection program including Mgt staffing exposure control. ALARA, surveys, posting & controls & TMI action items PAUL, R A , GREGER, L R Region 3, Office of Director 84/07/25 8pp 26077 322 24X Fichs 50-266 84/07/25,8408150399
- 8407230229 IE Info Notice 84-57. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc. 117pp 25865 047 24x Fiche 50-000.84/07/27,8407250229
- 8408160329 Forwards IE Insp Repts 50-266/84-11 & 50-301/84-09 on 840702-03 No noncompliance noted LITTLE, NS Region 3. Office of Director 84/07/30 Wiscons Electric Power Co Spp 26106 094 24X Fiche 50-266,84/07/30. Wisconsin
- --B408160331 IE Insp Repts 50-266/84-11 & 50-301/84-09 on 840702-03 No noncompliance or deviations noted Major areas inspected following action of previously identified insp Findings MILBROT.W E, QULDEMOND.W O Region 3. Office of Director 84/07/27 5pp 26106 096 24X Fiche 50-266.84/07/30.8408160329
- 8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during inspirated effective 840820 Preprinted form will be used rather than ite KEPPLER,J G Region 3, Office of Director 84/08/03 Commonwealth Edison Co 3pp 25942 188 24% Fiche 50-000.84/08/03, 8408070401
- 8408100044 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in IE Imap Repts 50-266/83-21 & 50-301/83-20.per 840517 request SPESSARD.R L Region 3. Office of Director 84/08/03 FAY.C W Wisconsin Electric Fouer Co ip 25987 063 24X Fiche 50-266.84/08/03.8408100044
- --8408100052 Further response to NRC 840517 itr re violations noted in 1E Insp Repts 50-266/83-21 & 50-301/83-20 Corrective actions drawings received after 840601 stamped w/ "For Info Unit" unites updated control drawings Review completed FAY.C W Wisconsin Electric Power Co 84/07/20 SPEBSARD.R L Region 3. Office of Birector 4pp 25987 064 24x Fiche 50-266.84/08/03.8408100044
- 84080[0333] IE Info Notice 84-59. "Deliberate Circumventing of Station Health Physics Procedures " Svc list enc) JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830[03]) 84/08/06 Consolidated Edison Co of New York, Inc. 122pp 26068 001 24% Fiche 50-000,84/08/06,8408010333
- 8408010337 IE info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 820103) 84/08/04 Consolidated Edison Co of New York, Inc 123pp 26067 158 24% Fiche 50-000.84/08/06.8408010337
- MOBO70120 IE Info Notice 84-61. "Overexposure of Diver in PMR Refueling Cavity " Svc list encl JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fiche 30-000.84/08/08.8408070120
- 3408070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Syc GRACE J N Division of GA, Safeguards & Inspection Programs (Post 9 84/08/10 Consolidated Edison Co of New Yor 26130 001 24X Fiche 50-000,84/08/10,8408070376
- 3408290365 Forwards Insp Repts 50-266/84-07 & 50-301/84-05 on 840601-0731 No noncompliance noted SHAFER, W D. Region 3. Office of Director 84/08/10 FAY, C Wisconsin Electric Power to 2pp 26296 295 24χ Fiche 50-266,84/08/10,8408290365 84/08/10 FAY.CW
- --8408270570 Insp Repts 50-266/84-07 t 50-301/84-09 on 840601-0731 No homcompliance noted Hajor areas inspected operational safety maint, surveillance, independent insp & plant trips JACKIMIN N Region 3, Office of Director 84/08/09 7pp 26296 297 24X Fiche 50-266,84/08/10,8408270565
- 8408100009 IE Infa Notice 84-63. "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co. of New
  York, Inc. 119pp 26197 218 24X Fiche 50-000.84/08/13.8408100009

- 8408170198 Ack receipt or 840731 ltr informing NRC of steps taken to correct noncompliance noted in IE Jusp Repts 50~266/84-08 & 50~301/84-06
- --9408170203 Forwards response to NRC 840711 ltr re noncompliance noted in IE Insp Repts 50-265/84-08 50-301/84-06 Encl withheld (tef 10CFR73 21) CASSIDY, T ) Wisconsin Electric Power Co 84/ Region 3, Office of Director 1p 26118 094 Fiche 50-266,84/08/13,8408170198 Wisconsin Electric Power Co 84/07/31 KEPPLER, J G
- 8408100038 IE Info Notice 99-64. BWR HPC: Initiation Seal-In & Indication "Svc list entl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co 26198 093 24X Fiche 50-000, 84/08/15, 8408100038
- 840B100021 IE Info Notice 84-45, "Undersated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JORDAN, E. L. Division of Emergency Piepaiedness & Engineering Response (Post 830103) 84/09/14 Consolidated Edison Co. of New York, Inc. (18pp. 26198-001 24X Fiche 50-000,84/09/14,8408100021
- 8408210550 Requests remittance of fee for 840706 application requesting relief from certain ASMF Code requirements for second 10-yr insp interval Application subj to 840620 rev to 10CFR170 refees Discussion of fees encl W/o encl DIGGS.R M License Fee Management Branch 84/08/16 FAY.C W Hisconsin Electric Power Co Ip 26195 262 24X Fiche 50-266.84/08/16.8408210550
- 8408100055 IE Info Notice 84 66. "Undetected Unavailability of Turbine-Driven Auxiliary Foedwater Train " Syc list encl JORDAN, F. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 262/6 001 24X Fishe 50 000.84/08/17, 8408100055
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 8301021) 84708/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50 000,84708/17,8408140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field William to Solenoid Valves" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/09/21 Consolidated Edison Co. of New York, Inc. 115pp 26329 908 24X Fiche 30-000,84/08/21,8408210142
- R Periodic operating reports & related correspondence
- 8408310229 "Gemiannual Monitoring Rept. Jan-Jung 1984 " \* Wisconsin Electric Power Co 84/06/30 1/pp 26322 165 24X Fithe 50~266,84/06/30,8408310229
- 8408210232 Monthly operating repts for Jul 1984 W/840810 ltr KRAVEE.C W , FAY.C W Miscunsin Electric Pawer Co 84/07 26184 297 24% Fichs 50-266, 84/07/31, 8408210232 84/07/31 10pp

#### V Operator Examinations

- B408070030 Responds to B40326 request for periodic updates re-progress made toward alleviating shortage of licensed operators. Adequate number of licensed operators anticipated after scheduled reactor license pram in Dec 1984 BRITI,R W. Wisconsin Electric Power Co. 84/08/02 BENTON,H R. Office of Nuclear Reactor Regulation. Director . Ppp. 25930 036 24x Fiche 50 266,84/08/02,8408/070030
- B40B140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners MALKER'R D. Region 3. Office of Director 84/08/10 Michigan. Univ af. Ann. Arbor. MI 2pp 26051
- B40B230521 Advises that operator & senior operator licensing exams scheduled for 841204 OA Hatl listed in encl "Ref Hatl Requirements for Operator/Denior Operator Licensing Exams" requested by 841004 MALKER R D Region 3, Office of Director 84/08/1/ FAY.C W Wisconsin Electric Power Co 3pp 24212 286 24X Fiche 50-266,84/08/17,8408230521

- POCKET 50-302 CRYSTAL RIVEN NUCLEAR PLANT, UNIT 3

  F Security, medical emergency & fire protection plans
- 8408300208 Forwards FEMA findings on State of FL & associated local emergency plans replant DANCE. H C Region 2. Office of Director B4/06/05 WILOUS, W S Fiorida Power Corp ip 26307 044 24X Fiche 50-302,84/06/05,8408300208
- --B408300211 Approves State of FL \*1 local plans & preparedness for alerting \* protecting public in event of radiological emergency Approval conditional on verification of alert & notification per App 3 of NUREG-0654/FEMA-REP-1, Rev 1

  SPECK.5 W Federal Emergency Management Agency 84/02//5

  DIRCKS.W J Office of the Executive Director for Operations 1p 26307 045 24X Fiche 50-302.84/06/05.8408300208
- B408300417 Forwards summary of 840930 meeting w/utils & INPO re selected emergency preparadness issues Attendance list encl D'REILLY, J.P. Region 2, Office of Director 84/06/08 WILGUS, W.S. Florida Power Corp. 4pp. 26314 150 24X Fiche 50-302,84/06/08, 8408300417
- 8408270428 Forwards Insp Rept 50-302/84-18 on 840611-15 No violations or deviations identified DANCE.H C Region 2, Office of Director 84/07/10 WILDUS.W S Florida Power Corp 2pp 26257 019 24% Fiche 50-302.84/07/10, 8408270428
- --8408270432 Insp Rept 50-302/84-18 on 840611-15 No violations or deviations identified Major area inspected emergency preparedness KREH, J L . CLINE. W E Region 2. Office of Director 84/07/06 7pp 26257 021 24X Fiche 50-302.84/07/10.8408270428
- 8408270206 Ack receipt of 840705 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-302/84-13 LEWIS.R C Region 2. Office of Director 84/08/01 WILQUS.W S Florida Power Corp ip 26258 024 24X Fiche 50-302,84/08/01,8408270206
- ---B408270211 Responds to NRC B40605 ltr re violations noted in Insp Rept 30-302/84-13 Corrective actions ltr identifying problem & emphasizing importance of use of child thyroid dose sent to dose assessment team members
  BAYMARD.P Y Florida Power Corp 84/07/05 O'REILLY, J P Region 2, Office of Director 2pp 24290 025 24X Fiche 50-302, 84/08/01.8408270206
- --8408270219 Forwards Insp Rept 50-302/84-13 on 840424-26 & notice of violation
  DANCE, H C Region 2, Office of Director 84/06/05 WILGUB, W S
  Florida Power Corp 2pp 26258 027 24X Fiche 50-302, 84/08/01, 8408270206
- --8408270224 Notice of violation from insp on 840424-26 \* Region 2, Office of Director 84/06/05 1p 26258 029 24X Fiche 50-302,84/08/01,8408270206
- --8408270227 Insp Rept 50-302/84-13 on 840424-26 Violation noted failure to specify use of child thyroid in radiolodine dose assessment procedures STQODART.P 0 . DECKER.T R . CLINE.W Region 2. Office of Director 84/05/30 iipp 26258 030 24X Fiche 50-302,84/08/01, 8408270206
- 8408200311 Advises that Emergency Operating Procedure OP-404, "DHR Bys." addresses concern raised at 840215 meeting re boron precipitation decay heat sys flow into reactor hot lag WESTAPER.O R Florida Power Corp 84/08/08 RIVENBARK.G W Operating Reactors Branch 4 ip 26133 019 24X Fiche 50-302,84/08/08,8408200311
- 8408210094 Forwards Amend 71 to License DFR-72 & safety evaluation Amend revises format of physical security plan to be competible w/NUREO-0908 & changes number of operational & administrative requirements

  BILVER, H Operating Reactors Branch 4 84/08/13 WILQUS, W S. Florida Power Corp 3pp 26195 163 24X Fiche 50-302,84/08/13,8408210054
- --840821006: Amend 71 to License DFR-72, revising format of physical security plan to be compatible w/NUREQ-0908 & changing number of operational & administrative requirements STOL7.JF Operating Reactors Branch 4 84/09/13 2pp 26195 166 24X Fiche 50-302.84/08/13.8408210054
- ---8408210066 Safety evaluation supporting Amend 71 to License DPR-72 \* Office of Nuclear Reactor Regulation, Director 84/08/13, 3pp 26195 168 24% Fiche 50-302,84/08/13,8408210054

- 8408210346 Forwards "Crystal River Nuclear Power Plant Exercise "
  Few specific NUREG-0634/FEMA-REP-1.Rev i.deficiencies
  observed during 840425 energency exercise State of FL &
  Citrus / Levy counties participated
  KRIMM.R W Federal Emergency Management Agency 84/08/13
  JORDAN, E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 2pp 26179 136 24X Fiche 50-302.84/08/13,
  8408210346
- ---B408210354 "Crystal River Nuclear Power Plant Exercise" \* Federal Emergency Management Agency B4/05/11 42pp 26179 138 24X Fiche 50-302.84/08/13,8408210346
- 8408240155 Forwards description of how Rev 3 to Reg Quide 1 97.
  "Instrumentation for LWR Nuclear Power Plants to Assess Plant & Environs Condition During & Following Accident," per Suppl 1 to NURED-0737 Mods will be implemented by 871231 BAYNARD.P Y Florida Power Corp 84/08/21 RIVENBARK.0 W Operating Reactors Branch 4 85pp 26228 001 24X Fiche 50-302.84/08/21. 8408240155

### H General correspondence

- B408230355 Responds to B40717 ltr expressing concern re effect of proposed nearby mining operations on plant Calculations indicate resulting ground motion would be small fraction of design values used in plant DENTON.H R Diffice of Nuclear Reactor Regulation, Director B4/0B/16 SPIVEY.H L Affiliation Not Assigned 13pp 26236 079 24X Fiche 50-302.84/08/16.8408230355
- --8408230360 Expresses concern re proposed mining near power plant
  Residents of Yankeetown fearful of addl damage to homes
  Requests clarification of NRC regulations concerning const
  of plant on top of Florida Aquifer
  SPIVEY,H L Affiliation Not Assigned 84/07/17 DIRCKS,W
  Office of the Executive Director for Operations 5pp 26236 093
  24X Fiche 30-302.84/08/16.8408230355
- P Operating license stage documents & correspondence
- 8408310062 Confirms 840501 telton re 840606 meeting in Region II ofcs to discuss proposed responses to questions on QA program description submittal 4d 830610 telles. C Region 2. Office of Director 84/05/22 WILQUS. W 8 Florida Power Corp ip 26333 341 24% Fiche 50-302.84/05/22, 8408310062
- 8408080070 Forwards list of deficiencies noted in inservice testing program Advises that evaluation re 840412 request to test pumps quarterly rather than monthly separate from overall program continuing RIVENBARK, 0 W Operating Reactors Branch 4 84/07/20 WILGUS, W 8 Florada Pawer Corp 8pp 25981 088 24% Fiche 50-302,84/07/20,8408080070
- B408020010 Application for amend to License DPR-72, consisting of Tech Spec Change Request 103, Rev 2 re safety-related hydraulic snubbers & organizational structure Certificate of Svc encl WESTAFER, G R Florida Power Curp 84/07/25 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 25083 060 24X Fiche 50-302,84/07/25,8408020010
- ---BAGBO20018 Proposed Tech Spec Change Request 103.Rev 2 re safety-related hydraulic snubbers & organizational structure # Florida Power Corp 84/07/23 18pp 25883 070 24X Fiche 50-302,84/07/25,8408020010
- 8408060199 Forwards updated response to Generic Ltr 83-28 % info required on plant-specific basis re post-trip review, for approval Three oversize drawings enci Aperture cards available in PDR WESTAFER, G R Florida Power Corp 84/07/31 EISENAUT, D G Office of Nuclear Reactor Regulation, Director 39pp 25727 025 24X Fichs 50-302,84/07/31,8408040199
- 8408070ii0 Generic Ltr 84-i9 to all licensees of operating reactors, applicants for GLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl EIBENHUT, D Q Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000,84/08/06,8408070ii0
- 8408220203 Forwards corrected pages to Tech Spec 6 5 2 7 re administrative controls, submitted w/Amend 69 to License DPR-72 SILVER, H Operating Reactors Branch 4 84/08/07 WILQUS, H 5 Florida Power Corp 4pp 26207 353 24X Fiche 50-302, 84/08/07, 8408220203

- 84)8200330 Provides excerpts from Missile Impact Analysis Rept F/L 20422 re turbine-driven smergency feedwater pump missile potential, in response to NUREQ-0737, Item II E 1 1 Response satisfies Item 2b of 840501 SER WESTAFER. G R Florida Power Corp 84/08/08 RIVENBARK. 6 W Operating Reactors Branch 4 2pp 26133 002 24X Fiche 50-302,84/08/08,8408200320
- 3408200418 Summary of 840720 meeting w/ytil in Bethesda, MD re test results 5 other info concerning requested reactor head vent exemption SILVER.M Operating Reactors Branch 4 84/08/08 Operating Reactors Branch 4 26pp 26141 135 24X Fiche 50-302.84/08/08, 8408200418
- 8408210367 Forwards Amend 70 to License OPR-72 & safety evaluation Amend provides method for controlling personnel access to high radiation areas H/o encls SILVER: H Operating Reactors Branch 4 84/08/10 WILOUS, W S Florida Power Corp 2pp 26195 246 24X Fiche 50-302,84/08/10,8408210567
- --8408210576 Amend 70 to License DPR-72, changing Tech Spec Apps A & A to allow condoning & conspicuous lighting in lieu of lockable encl for access control to high radiation areas STOL7.J F Operating Reactors Branch 4 84/08/10 5pp 26195 248 24x Fiche 50-302.84/08/10.8408210567
- --R408210382 Safety evaluation supporting Amend 70 to License DPR-72 \* Office of Nuclear Reactor Regulation, Director 84/08/10 2pp 26195 253 24X Fiche 50-302.84/08/10.8408210567
- 8408210054 Forwards Amend 71 to License DPR-72 & safety evaluation Amend revises format of physical security plan to be compatible w/NUREC-0908 & changes number of operational & administrative requirements
  SILVER.H Operating Reactors Branch 4 84/08/13 WILGUS.W S Floride Power Corp 3pp 26195 163 24X Fiche.50-302.84/08/13.8408210054
- --8408210061 Amend 71 to License BPR-72, revising format of physical security plan to be compatible w/NUREQ-0908 & changing number of operational & administrative requirements STOL2. J F Operating Reactors Branch 4 84/08/13 2pp 26195 166 24% Fithe 50-302,84/08/13,8408210054
- --8408210046 Safety evaluation supporting Amend 71 to ticense DPR-72 \* Office of Nuclear Reactor Regulation: Director 84/08/13 3pp 26195 168 24% Fiche 50-302,84/08/13,8408210054
- 84082002/8 Requests extension of time to B41130 to respond to 840702 Owneric Ltr 84-55 requesting data % commentary reimprovement to & maint of diesel generator reliability WESTAFERROR Florida Power Corp 84/08/16 EISENHUT, D G Division of Licensing 2pp 26133 021 24% Fichs 50-302,84/08/16,8408200278
- 8408200275 Generic Ltr 84-20 to all licensess of operating reactors & applicants for DLs re-scheduling guidance for licenses submittals of reloads that involve unreviewed safety questions Svc list enci Questions Svc list enci EISENMUT.D 0 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276-244 24X Fiche 50-000,84/08/20,8408200275
- 8408310402 Ack receipt of util 840301 comments of proposal to remove engineered safeguards activation signal from makeup tank isolation valve MUV-24 Removal will not cause unacceptable reactor coolant boron dilution prior to manual isolation STOLZ.U F Operating Reactors Branch 4 84/08/22 NILCUE, N 8 Florids Power Corp 3pp 26350 350 24X Fiche 50-302.84/08/22, 8409810404
- 8408280134 Forwards NS D'Brien 840821 ltr transmitting notes of fourth quarterly progress meeting on 840802 re 316 study & corrected salinity figures for third quarterly rept to EPA HEBRAFER, G R Florida Power Corp 84/08/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 20pp 26275 046 24X Fiche 50-302,84/08/23,8408280134
- G Inspection reports, IE Bulletins & correspondence
- 8408270428 Forwards Insp Rept 50-302/84-18 on 840611-15 No violations or deviations identified DANCE.H C Region 2: Office of Director 84/07/10 HILQUB.H.B Florida Power Corp 2pp 26257 019 24% Fiche 50-302,84/07/10; 8408270428

- --B408270432 Insp Rept 50-302/84-18 on 840611-15 No violations or deviations identified Major area inspected emergency preparedness KREH, J.L., CLINE, N.E., Region 2, Office of Director 84/07/06 9pp 26257 O21 24x Ficha 30-302,84/07/10,8408270428
- B40B280170 Submits revised response to IE Bulletin 84-02, "Failure of GE Type HFA Relays in Use in Class IC Safety Sys 'All HFA relays will be rebuilt or replaced prior to restart following Refuel 5 HESTAFER, GR Florida Power Corp 84/07/18 O'RCILLY, J.P. Region 2, Office of Director 6pp 26259 010 24X Fiche 50-302,84/07/18,8408280170
- 8408280061 Ack receipt of 840710 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-302/04-17
  DANCE:H C Region 2, Office of Director 84/07/19 WILQUS.W 8
  Florida Power Corp 19 26282 016 24X Fiche 50-302,84/07/19,8408280061
- --8408280069 Responds to NRC 840613 Itr reviolations noted in Insp Rept 50-302/84-17 Corrective actions high radiation area sign relocated to personnel access hatch Radiation protection protedure will be revised.per iOCFR20 203(c)(3) WESTAFER: 0 R Florida Power Corp 84/07/10 O'REILLY, J P Region 2, Office of Director 2pp 26282 017 24X Fiche 50-302.84/07/19,8408280061
- --B408280072 Forwards Insp Rept 50-302/84-17 on 840515-18 & notice of Violation DANCE,N C Region 2, Office of Director 84/06/13 WILGUS,W S Florida Power Corp 2pp 26282 019 24X Fiche 50-302,84/07/19,8408280061
- --8408280077 Notice of violation from insp on 840515-18 \* Region 2, Office of Director 8406/13 ip 26282 021 24x Fiche 50-302.84/07/19,8408280061
- --B408280082 Insp Rept 50-302/84-17 on B40515-18 Violation noted failure to use proper locking device for high radiation area control COLLINS, T.R., JENKINS, O.R. Region 2, Office of Director 84/06/11 App 26282 022 24X Fiche 50-302-84/07/19.8408280061
- 0407250229 IE Info Notice 84-57. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Fower Plants " Syc list encl JORDAN,E L Division of Emergency Proparodness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 167pp 25865 047 24X Fiche 90 000,84/07/27,8407250229
- 8408270206 Ack receipt of 840/05 ltr informing NRC of steps taken to correct violations noted in Insp Ropt 50-302/04-13 LENIBLE C Region 2. Office of Director 84/08/01 WILQUS, W 8 Florida Power Corp ip 26258 024 24X Fiche 50-302, 84/08/01, 8408270206
- ~-8408270211 Responds to NRC 840605 iti re violations noted in Insp Rept 50~302/84~13 Corrective actions ltr identifying problem & emphasizing importance of use of child thyroid dose sent to dose assessment team numbers BAYNARD.P Y Florida Power Corp 84/07/05 O'REILLY, J P Region 2, Office of Director 2pp 24258 025 24X Fiche 70~302, 84/08/01.8408270204
- ~-B4082/0219 Forwards Insp Rept 50-302/04-13 on 840424-26 & notice of violation DANCE.N C Region 2. Office of Director 84/04/03 WILOUS, W 8 Florida Power Corp 2pp 26258 02/ 24X Fiche 50-302, 84/08/01, 84082/0206
- --B408270224 Notice of Violatian from insp on 840424-26 \*\* Region 2, Office of Director 84/06/05 ip 26258 029 24x Fiche 50-302,84/08/01,8408270206
- --0408270227 Insp Rep1 90-302/84-13 on 040424-26. Violation noted failure to sportey use of child thuroid in radiolodine dose assessment procedures.
  81000ART.P o. DECKET, T R . CLINE. H Region 2, Office of Director 04/08/30 ilap 24298 030. 24x Ficha 50-302, 84/08/01.
- 8408010333 IE Info Notice 84-99, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/00/06 Consolidated Edison Co of New York, Inc 122pp 26068:001 P4X Fiche 50-000,84/08/06,8408010333

- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svr list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 26067 158 24% Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity" Svc list encl
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/08 Consolidated Edison Co of New
  York, Inc. 120pp 26129 118 24% Fiche 50-000,84/08/08.8408070120
- 840B070376 IE Info Notice B4-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list Pnc! GRACE, J N Division of OA. Safeguards & Inspection Programs (Post B30103) B470B/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, B470B/10, B40B070376
- 840B100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN, EL Division of Emergency Praparedness & Engineering
  Response (Post 83010,3) 84/08/13 Consolidated Edison Co of New
  York, Inc. 117pp 26197 218 24% Fiche 50-000,84/08/13,8408100009
- 840Bi0003B IE Info Notice 84-64. "BWR HPCI Institution Seal-In & Indication "Syc list encl Justice 10 Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24% Fiche 50-000.84/08/15.8408100038
- 840B100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021
- 8408100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JARDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 001 24X Fiche 50-000.84/08/17,8408100035
- 8408140208 IE Info Notice 84-67. "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN.C L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 122pp 26276 122 24X Fiche 50-000.84/08/17.8408140208
- 8408210142 JE Info Notice 84-66, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN,E L Division of Emergency Proparedness & Engineering Response (Past 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142
- A Periodic operating reports & related correspondence
- 840B160326 Monthly operating rept for Jul 1984 W/840808 ltr GRAHAM, D., WESTAFER, O.R. Florida Power Corp. 84/07/31 DEYDUNG, R.C. Director's Office. Office of Inspection and Enforcement 5pp. 26108 027 24X Fiche 50-302,84/07/31,8408160526
- 8 Reportable occurrences, LERs & related correspondence
- 8408160410 Special Rept 84-03 on 840424, false low & high pressure injection occurred when Channel 2 low pressure bistable inadvertently actuated Cause not stated Bistable replaced. Plant stabilized w/injection of borated water into RCS WESTAFER, G.R. Florida Power Corp. 84/07/23 O'REILLY, J.P. Region 2, Office of Director. 3pp. 26106 087, 24% Fiche 50-302,84/07/23,8408160410
- B408060306 LER B4-014-00 on B40625 & O3R2, auxiliary bldg exhaust fans taken out of svc in order to perform mods to ventilation sys dampers Policy memo issued stating Tech Spec 3 0 3 should not be entered for maint w/o permission W/840725 ltr BANDHAUER, W K, WESTAFER, G R Florida Power Corp 84/07/25 App 25936 069 24X Fiche 50-302,84/07/25,8408040306
- 8408080189 NPDES noncompliance notification thermograph time data collection. From Dec 1983 840615, terminated, per plan of study & on 840726, sample of Discharge 006 could not be obtained for pH
  WESTAFER, G R Florida Power Corp 84/08/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 25960 247 24X
  Fiche 50-302,84/08/03,8408080189

- 8408160247 LER 84-010-01 on 840426, non-nuclear instrumentation power supply Y failed, causing erroneous signals to be sent to integrated control sys Caused by capacitor failure Capacitor replaced W/840808 ltr
  BANDHAUER K K, WESTAFER, O R Florida Power Corp 84/08/08 App 26106 202 24X Fiche 50-302,84/08/08.8408160247
- 8408140238 LER 84-004-01 on 840228.six manual isolation valves closed Caused by personnel error & inadequacies in mod approval record All six valves opened Process of sys turnover to be upgraded W/840808 ltr WILSON, K R; WESTAFER, G R Florida Power Corp 84/08/09 4pp 26106 210 24x Fiche 50-302,84/08/09,8408160238
- 8408200346 LER 84-015-00 on 840713 drain petcock on air filter in emergency diesel generator B air start sys failed resulting in start of diesel generator On 840404, similar failure occurred W/840809 ltr BANDHAUER, H K. WESTAFER, O R Florida Power Corp 84/08/09 3pp 26139 334 24X Fiche 50-302,84/08/09,8408200346
- 8408230424 LER 84-016-00 on 840720 quality programs audit determined that alarm/trip setpoint for fuel storage pool area gaseous activity process monitor RM-A4 exceeded Tech Spec limit Caused by not following action requirements W/840813 ltr BANDHAUER.W K. WESTAFER.O R. Florida Power Corp. 84/08/13 4pp 26213 040 24X Fiche 50-302.84/08/13,8408230424
- 8408230430 LER 84-016-00 on 840720, quality programs audit determined that alarm/trip setpoint for fuel storage puol area gaseous activity process monitor RM-A4 exceeded Tech Spec limit H/B40815 ltr
  BANDHAUER, W.K., WESTAFER, G.R. Florida Power Corp. 84/08/15 4pp 26213 064 24% Fiche 50-302.84/08/15.8408230430
- 8408300341 LER 83-043/03X-1 on 831003, fault light on emergency feedwater (EFH) ultrasonic flow indicator for steam generator 8 (FM-313-FI) discovered illuminated Caused by void in EFW line due to check valve leakage H/840824 ltr THOMPSON, R H, HESTAFER, Q R Florida Power Corp 84/08/24 3pp 26308 337 24X Fiche 50-302,84/08/24,8408300341
- DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2

  F Security, medical, emergency & fire protection plans
- B40B070239 Rev 7 to Emergency Plan Implementing Procedure EPIP 110-1, "Zion Station Nuclear Accident Reporting Sys Reporting Procedures "NyA00719 transmittal memo NYKIRK, J Commonwealth Edison Co 84/07/19 10pp 25948 353 24X Fiche 50-295.84/07/19, 840807029.
- B408070240 Rev 3 to Emergency Plan Implementing Procedure EPIP 100-1. "Acting Station Director" W/840719 transmittal memo NYKIRK. J Commonwealth Edison Co 84/07/26 16pp 25949 001 24X Fithe 50-295, 84/07/26.8408070240
- 8408010165 Forwards "Safe Shutdown Capability Reassessment & Proposed Mods.10CFR50.App R." for approval Exemption from schedular requirements of 10CFR50.48(c)(4) until 851231 requested Related tables & notes encl CASCARANO.R N Commonwealth Edison Co 84/07/27 DENTON.H R Office of Nuclear Reactor Regulation. Director 28pp 25874 001. 24X Fiche 50-295.84/07/27.8408010165
- --8408010171 "Safe Bhutdown Capability Reassessment & Proposed Mods, 10CFR30, App R " \* Commonwealth Edison Co 84/07/31 499pp 25874 029 24X Fiche 30-275.84/07/27,8408010165
- 840B170398 Forwards public version of Rev 3 to Emergency Plan Implementing Procedure BZP 600-A3, "Station Directory " \* Commonwealth Edison Co 84/07/31 Record Services Branch (Document Control Desk) 2pp 26134 171 24X Fiche 50-295, B4/07/31.8408170398
- --B408170399 Public version of Rav 3 to Emergency Plan Implementing Procedure BIP 600-A3, "Station Directory" W/JM Felton B40809 release memo \* Commonwealth Edison Co 84/07/31 10pp 26134 172. 24X Fiche 50-295,84/07/31.8408170398
- 8408100040 Determines that, based on evaluation, State of WI & local plans for radiological emergencies adequate SPECK-S W Federal Emergency Management Agency 84/08/02. DIRCKAS, W J Office of the Executive Director for Operations 1; 25787 052 24X Fiche 50~293.84/08/02,8408100060

- 8408140139 Forwards listed revs to security plans Revs address fence height requirements Revs withheld (ref 10CFR73 21) FARRAR, D. L. Commonwealth Edison Co. 84/08/03 Region 3, Office of Director ip 26044 252 24X Fiche 50-000,84/08/03,8408140139
- 8408130401 Responds to 840705 clarification of info re util means of satisfying annual regulatory requirement to review emergency action levels w/offsite emergency support organizations Info acceptable PAPERIELLO,C J. Region 3, Office of Director 84/08/07 REED.C Commonwealth Edison Co. ip. 26010 130 24X Fiche 50-000,84/08/07,
- ~~8408130413 Responds to 840604 ltr re means for satisfying requirements of 10CFR50. App E. Paragraph IV 8 Proposal for satisfying requirements to review emergency action levels by offsite agencies clarified FARRAR. D L Commonwealth Edison CO 84/07/05 PAPERIELLO, C J Region 3, Offsice of Director 8pp 26010 131 24X Fiche 50-000.84/08/07.8408130401
- 8408140428 Rev 3 to Emergency Plan Implementing Procedure EPIP 350-2. "Calculation of Post-Accident Nobie Gas Release Rates Via Vent Stacks & Guick Estimate of Diffsite Dose Using SPING Monitor RIA-PR49 Readings " W/840808 transmittal memo KASSHER. C. PLINL. O Commonwealth Edison Co 84/08/08 13pp 26051 170 24X Fiche 50-295.84/08/08.8408140428
- 8408200345 Advises that 840803 Rev 13 to physical security plan consistent w/provisions of 10CFR30 54(p) & acceptable AXELSON, W.L. Region 3, Office of Director 84/08/14 FARRAR, D.L. Commonwealth Edison Co. 2pp. 26132 357 24X Fiche 50-295,84/08/14,8408200345
- 8408310168 Rev 3 to Emergency Plan Implementing Procedure EPIP 550-6, "Monthly Radiological Emergency Equipment Tests & Checks "
  W/transmittal & receipt form
  GRAESSER, K L , PLIML 6 Commonwealth Edison Co 84/08/15 6pp
  26319 237 24X Fiche 50-295,84/08/15,8408310168
- B40B270309 Informs of FEMA approval of State of WI emergency response & local plan Adequacy of public alerting & notification sysmust be verified per FEMA/NRC joint criteria in App 3 of NURSC-0654/FEMA-REP-1 PAPERIELLD, C J Region 3. Office of Director 89/08/22 REED, C Commonwealth Edison Co 2pp 26239 137 24X Fiche 50-275,84/08/22,8408270309
- P Operating license stage documents & correspondence
- 8408280360 Ack receipt of 840710 ltr re author criticism of NRC present rules & practices Reponse to NRC seven stages of discussion listed Fast tests should be reviewed & leak rate be retested Related info encl REYTBLATT.2 V Warren Wilson College, Swannanoa, NC 84/07/22 RDSS, DF Office of Nuclear Regulatory Research, Director Bpp 26293 001 24X Fiche 50-000.84/07/2288408280360
- --B40B2B0373 Requests documents is RFP RB-RES-B4-101, submitted on 840ji0 Author 840220 ltr to EM Gogol, Citizens Against Nuclear Power and REYTBLATT, Z V Extran, Inc 84/03/02 Division of Rules and Records App 26293 012 24X Fichs 50-000, 84/07/22, 8408280360
- 408060333 Notification of 840802 meeting w/util in Bethesda, MD to discuss insights from review of probabilistic safety study NORRIE, J A Operating Reactors Branch 1 84/07/27 VARGA, 8 A Operating Reactors Branch 1 3pp 25937 354 24x Fiche 50-295, 84/07/27, 8408060335
- 408130047 Notification of cancellation of 840802 meeting w/util in Bethesda.MD to discuss NRC review of probabilistic safety study NORRIS.J A Operating Reactors Branch 1 84/07/27 VARGA.S A Operating Reactors Branch 1 2pp 26034 360 24X Fichs 50-275.84/07/27,8408130047
- 8408130022 Ack receipt of 840505 petition for emergency relief re adequacy of containment leak rate testing NRC conducting insp on allegations Util informed that Unit 1 not in compliance w/10CFR50.App J DENITON.HR Office of Nuclear Reactor Regulation, Director 84/07/30 GOGAL.E M Citizens Against Nuclear Power 7pp 26036 330 24X Fiche 50-295,84/07/30,8408130022
- 8408090137 Advises that Class III fee appropriate for review of 830727 submittal of "Comm Ed Topical Rept on Benchmark of PWR Nuclear Design Methods" Examption from Class I fee granted W/n stated encls
  MILLER.W.O. License Fee Management Branch 84/08/03 FARRAR.D. L. Commonwealth Edison Co. 2pp. 25971.205 24% Fiche 50-295.84/08/03.8408090139

- 8408070110 Generic Ltr 84-j9 to all licensees of operating reactors, applicants for DLs & holders or CPs re availability of Suppli 1 to NUREG-0933. "Prioritization of Generic Safety Issues." Svc list encl EISEMHUT. D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26127 238 24X Fichs 50-000.84/08/06.8408070110
- B408160345 Advises that DA program applicable to all nuclear generating stations & satisfies provisions of IOCFR71 fee remitted per IOCFR170 31 FARRARID L Commonwealth Edison Co 84/08/06 Office of Nuclear Material Safety & Safeguards, Director ip 26092 184 24X Fiche 50-000, 84/08/06.8408160345
- 8408230077 Forwards dreft Industry Degraded Core Rulemaking Program Technical Rept 23 1. "Sequoyah Nuclear Plant Containment Analysis." For Meeting 3B Rept inconsistent w/Four encirepts previously sent FONTANA.M H. Technology for Energy Corp. 84/08/07. DENTON.H R. Office of Nuclear Reactor Regulation. Director 2pp. 26234 001 24X Fiche 50-000,84/08/07.8408230097
- ~-8408230112 Draft "Evaluation of Containment Bypass & Failure to Isolate Sequences for Industry Degraded Core Rulemaking Program Ref Plants." technical rept
  \* Industry Degraded Core Rulemaking Program \* Fauske & Associates. Inc FAI/81-9 DRFT 84/07/31 114pp 26234 231 24% Fiche 50-000.84/08/07,8408230097
- ~-8409230116 Draft "Zion Nuclear Generating Station Integrated Containment Analysis," technical rept \* Industry Degraded Core Rulemaking Program 84/08/07 119pp 26234 333 24X Fiche 50-000,84/08/07,8408£30097
- 8408170033 Natification of 840815 meeting w/util in Bethesda.MD to discuss proposed safety rigt program & integrated living schedule concepts NORRIS.J A Operating Reactors Branch 1 84/08/08 VARGA,S A Operating Reactors Branch 1 2pp 26134 361 24X Fiche 50~275.84/08/08.8408170033
- 8408210552 Requests remittance of fee for 840627 application requesting extension of 10GFR50 49(g) schedular requirements for environ qualification of electrical equipment Application subj to 840620 rev to 10GFR170 re fees
  DIG95.R M License Fee Management Branch 84/08/16 FARRAR, D L Commonwealth Edison Co ip 26195 261 24X Fiche 50-304,84/08/16,8408210552
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EIBERMUT.D 0 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fichs 50-000.84/08/20.8408200275
- 8408280119 Forwards fee for review of util topical rept on benchmark of PWR Miclear design methods in connection w/reloads at facility, per 840803 ltr
  ALEXANDER. G L. Commonwealth Edison Co. 84/08/20 MILLER, W C. Licenso Fee Management Granch 1p. 26261 300 24X
  Fiche 50-295.84/08/20.8408280119
- 8408270372 Forwards response to NRC request for clarification of sycuater success criteria Adequacy of two sycuater pumps to handle safe shutdown components reconfirmed by util corporate engineering dept CABCARAND, R N Commenumenth Edison Co 84/08/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26240 252 24X Fiche 50-295, 84/08/21, 8408270372
- 8408280286 Summary of 840815 meeting w/util re integrated living schedule Attender list agenda & viewgraphs encl W/o encls NORRIS, J Operating Reactors Branch 1 84/08/21 Operating Reactors Branch 1 2pp 26294 087 24X Fiche 50-295,84/08/21,8408280286
- B408310115 Forwards fee for 840427 application for environ qualification of electrical equipment schedular extension CABCARAND, R N Commonwealth Edison Co 84/08/22 DIGGS, R M License fee Management Branch 1p 26382 111 24X Fiche 50-304,84/08/22,8408310115
- B40B310200 Discusses PRA of proposed mod to auxiliary feedwater sys,per NUREQ-0737, Item II E i ! Efforts on mod stopped as result of PRA conclusion that installation of addl check valves will not significantly improve availability of sys CABCARANG, R N Commonwealth Edison Co B4/08/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 26318 308 24X Fiche 90-295, 84/08/23, 8408310200

- 840B310202 Forwards add1 info to inadequate core tooling instrumentation systim response to NRC 840530 request Meeting suggested in Bethesda, ND to resolve any questions still outstanding CASCARANO, R N Commonwealth Edison Co 84/08/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 26318 312 24x Fiche 50-295,84/08/24,8408310202
- O Inspection reports, IE Bulletins & correspondence
- B408080485 Forwards IE Insp. Repts 50-295/84-08 \$ 50-304/84-08 on 840531.0604-08, 12-13 \$ 0702 \$ notice of violation PAPERIELLO.C J. Region 3. Office of Director 84/07/18 REED, C Commonwealth Edison Co. 2pp. 25975 188 24X Fiche 50-295, 84/07/18, 8408080485
- --8408080488 Notice of violation from Insp on 840531.0604~08.12~13 & 0/02
  PAPERIFLLO.C J Region 3. Defice of Director 84/07/18 Ip 25975 190 24X Fiche 50-275.84/07/18.8408080485
- --8408080496 IE Insp Repts 50-295/84-08 & 50-304/84-08 on 840531.0604-08, 12-13 & 0702 Violations nated unauthorized transfer of Am-241 sources to Byron Station LOVENDALE, P.C., NICHOLSON, N.A., GREGER, L.R. Region 3, Office of Director 84/07/17 lipp 25975 191 24X Fiche 50-295,84/07/18, B405080485
- B408090169 Forwards IE Insp Repts 50-295/84-07 & 50-304/84-07 on B40512-0629 No noncompliance noted BHAFER.N D. Region 3. Office of Director 84/07/20 REED, C Commonwealth Edison Co. 2pp. 25999 015 24% Fiche 50-295.84/07/20. B408090169
- --B408090177 IE Insp Repts 50-295/84-07 & 50-304/84-07 on 840512-0629 No noncompliance or deviations noted Major areas inspected maint on nuclear instrumentation, operational safety & EBF walkdown, surveillance & LER followup WRIGHT, G C Region 3, Office of Director 84/07/19 App 25995 017 24X Fiche 50-295,84/07/20,8408090169
- 8407250229 IE Info Notice 84-57, "Operating Experience re Muisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 117pp 23865 047 24X Fiche 50-000.84/07/27, 8407250229
- B408070066 Notifies of 840823 meeting w/util at Region III ofc to review findings of SALP assessment re util performance Encourages mgt representation to ensure mutual understanding of issues & findings presented by NRC NORELIUS.C E Region 3, Office or Director 84/08/03 REED.C Commonwealth Edison Co 2pp 25949 337 24% Fiche 30~000,84/08/03,84808070066
- B408070401 Informs that new sys of acknowledging receipt of licenses correspondence re noncompliance found during inspiristivited, effective B40820 Preprinted form will be used rather than Itr
  KEPPLER, J G Region 3, Office of Director B4/08/03
  Commonwealth Edison Co. 3pp. 25942 188 24X Fiche 50-000,84/08/03.
  B408070401
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Soc list encl JORDAN.C C Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York Inc 123pp 26067 158 24% Fiche 50-000.84/08/06.8408010337
- B40B070120 IE Info Notice 84-61. "Overexposure of Diver in PWR
  Refueling Cavity " Svc list encl
  JORDAN: E.L. Division of Emergency Preparedness & Engineering
  Response (Post B30103) 84/08/08 Consolidated Edison Co of New
  York, Inc 120pp 26127 118 24X Fiche 50-000.84/08/08.8408070120
- B40B140344 Confirms 840B03 plans to meet w/util on 840907 in Glen Ellyn, IL to discuss regulatory improvement program NORELIUS.C E Region 3. Office of Director 8470B708 REED.C Commonwealth Edison Co 2pp 26041 090 24X Fiche 50-000,8470B708.

- 8408150098 Supple 840711 response to IE Bulletin 84-02 re visual insp during monthly functional tests to venify proper contact on reactor trip sys & primary containment isolation sys relays Exemptions requested for listed relays ALEXANDER. G L Commonwealth Edison Co 84/08/08 KCPPLER. J G Region 3. Defice of Director 3pp 26067 053 24X Fiche 30-000,84/08/08.8408150098
- 8408200331 Suppls response to IE Bulletin 84-02 re failure of 0E Type HFA relays Exemption requested from commitment for visual insp verifying proper relay contact during monthly functional check for listed relays ALEXANDER.9 L Commonwealth Edison Co 84/08/06 KEPPLER.J O Region 3. Office of Director 3pp 26/32 318 24X Fiche 50-000.84/08/08.8408200331
- 8408170263 Forwards SALP Repts 50-295/84-06 & 30-304/84-06 for Jan 1983 Apr 1984 KEPPLER, J G Region J. Office of Director 84/08/09 REGD, C Commonwealth Edison Co 2pp 26118 008 24X Fiche 50-299, 84/08/09, 8408170263
- --8408170265 SALP Repts 50-275/84-06 & 50-304/84-06 for Jan 1783 --Apr 1784 Licensing activities assigned Category [ rating \* Region 3, Office of Director B4/08/07 Jigg 24118 010 24X Fiche 50-275,84/08/07,8408170263
- 8408070376 IC Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " 8vc list encl ORACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fishe 30-000,84/08/10,8408070376
- 840Bi00009 IE Infa Notice 84-63, "Defective RHR Replacement Piping "

  8vc list encl

  JORDAN,E L Division of Emergency Progaredness & Engineering

  Response (Past 830103) 84/08/13 Consolidated Edison Co of New

  York, Inc 119pp 26197 218 24% Fiche 50-000,84/08/13,8408100009
- 8408220086 Suppls 840626 response to 840311 request for add1 info re inservice inap program for second 10-yr interval Add1 relief requests & additions to program enc! CASCARANO,R N Commonwealth Edison Co 84/08/14 DENTON,H R Office of Nuclear Reactor Regulation, Director 37pp 26193 252 24% Fiche 50-295,84/08/14.8408220086
- 840810003B IE Info Notice 84-64, "BWR HPC! Initiation Seal-In & Indication "Swc list enc! JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York. Inc 104pp 26198 093 24X Fiche 50-000.84/08/15.840810003B
- B40B100021 IE Info Nutice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JORDAN, E.L. Division of Emergency Proparedness & Engineering Response (Post 830103) B4/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26198 001 24X Fiche 50-000. B4/08/16, 840B100021
- 8408270087 Suppls 840607 ltr re check valves in water cooling sys of diesel generators.per IE Bulletin 83-03 Valve into on 840515 revealed no mechanical problems ALEXANDER: G L Commonwealth Edison Co 84/08/16 KEPPLER, J G Region 3, Office of Director 2pp 26247 355 24X Fiche 50~275,84/08/16,8408270087
- 840BiQO055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JQRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000.84/08/17.8408100055
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 820103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl, JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 630103), 84/08/21 Consolidated Edison Co of New York, Inc. 115pp 26327 008 24X Fiche 50-000.84/08/21,84082101432
- R Pariodic operating reports t related correspondence
- B40B300136 "Effluent & Waste Disposal Semiannual Rept.Jan-June 1984 " W/840B03 ltr GRAEBSER, K.L. Commonwealth Edison Co 84/06/30 KEPPLER, J G Region 3, Office of Director 47pp. 26308 029 24X Fichs 50-295,84/06/30.840B300136

- B408160122 Monthly operating repts for Jul 1984 W/840807 ltr AUSTIN.G. GRAESSER.K.t. (ammonwealth Edison Co. 84/07/31 13pp 26108 117 24% Fiche 30-295.84/07/31.8408160122
- 8 Reportable occurrences, LERs & related correspondence
- 8408060270 LER 84-014-00 on 840626, five snubbers found inoperable Caused by poor seal conditions that allowed fluid to leak out Snubbers overhauled, tested & reinstalled W/840726 ltr PETROMBKI.S E. GRAESSER, K. L. Commonwealth Edison Co. 84/07/26 3pp 25936 086 94% Fiche 50-304, 84/07/26, 8408060290
- 8408090047 LER 84-017-00 on 840704.nuclear instrumentation sys channel 41 remained out of svc for test w/overpower & overtemp delta T bistables tripped Caused by personnel error Personnel counseled W/840803 ltr ROHDE.JE . GRAESSER.K L. Commonwealth Edison Cq 84/08/03 3pp 25792 133 24X Fiche 50-304.84/08/03.8408090047
- 8408090326 LER 84-015-00 on B40711.MSIV loop D distovered to have no closing side hydraulic pressure Caused by internal leakage of Keane salendids during shutdown New breaker installed & independent operation returned M/840803 ltr WODBS.J. GRAESSER.K.L. Commonwealth Edison Co. 84/08/03 3pp 25994 066 24% Fiche 50-304.84/08/03,8408090326
- 8408130456 LER 84-016-00 on 840709 reactor tripped from hot standby, Mode 2 Caused by instrument inverter 212 failure due to alaye output transformer short circuit Damaged transformers replaced W/840806 itr BAILEY.M W. GRAESSER.K L. Commonwealth Edison Co. 84/08/06. 3pp 26031 360 24X Fishe 50-304.84/08/06,8408130456
- 8408130405 LER 84-018-00 on 840708 turbine tripped & steam & feed flow channels needed to be calibr Bistables lit due to turbine trip Operating superviser reinstructed to use proper procedure change format W/840807 ltr
  BREEN.W , ORAESSER.K L Commonwealth Edison Co 84/08/07 3pp 24010.187 24% Fiche 50-304.84/08/07,8408130405
- 8408200547 LER 83-044-01 on 831111, during safeguards testing, valve 2MDV-CS0006 failed to stroke when actuated, placing plant in degraded mode Caused by failed main drive sleeve in Limitorque operator Decretor rebuilt W/840813 ltr PETROWSKI.8 : GRAESSER, K L Commonwealth Edison Co 84/08/13 3pg 26138 204 24% Fiche 50-304,84/08/13,8408200547

### V Operator Examinations

- B40Bi40372 Forwards proposed rev to "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," in response to NURED-0737, Item I A 3 HARSHALL-J G Commonwealth Edison Co 84/03/07 DENTON, H R Diffice of Nuclear Reactor Regulation, Director 2pp 26051 240 24X Fiche 50-000,84/08/07,8408140372
- --B40Bi403B9 "Requalification Program for Licensed Operators.Benior Operators & Benior Operators (Limited) "

  \* Commonwealth Edison Co B4/07/19 10pp 26051 242 24X Fiche. 30-000, B4/08/07, B40Bi40372
- "40Bi40A26 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners WALKER, R D. Region 3. Office of Director 84/08/10 Michigan. Univ. of. Ann Arbor. MI 2pg 26051
- OCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT

  Security, medical, emergency & fire protection plans
- 8408050422 Forwards request for add1 info re 831228 procedures generation package for emergency operating procedures Response requested within 30 days of ltr receipt unless schedule for response provided VARGA.8 A Operating Reactors Branch 1 84/07/25 OIESLER.C W Hisconsin Public Service Corp 2pp 25937 338 24x Fiche, 50-305, 84/07/25, 8408040422
- |408070272 Forwards revised index to radiological emergency response plan implementing procedures
  HINTZ,D C Wisconsin Public Service Corp 84/07/31 Record Services Branch (Document Control Desk) 1p 25948 005 24X
  Fiche 50-305,84/07/31,8408070272
- ~8408070276 Revised emergency plan implementing procedure index \* Wisconsin Public Service Corp 84/07/10 Spp 25748 006. 24X Fiche 50-305,84/07/31,8408070272.

- 8408070275 Forwards add1 info on safety parameter display sys in response to 840326 request & suppl to SAR Sys scheduled for implementation by end of Spring 1985 refueling outage Rev. 1-A to WCAP-78819 encl WINTZ. D C Washington Public Power Supply System 84/08/01 EISENHUT. D & Division of Licensing 25pp 25948 123 24X Fiche 50-305,84/08/01.8408070275
- --8408070282 Rev 1-A to 'Nuclear Instrumentation Sys isolation Amplifier " LIPCHAK.J B. BARTHOLOMEW.R Westinghouse Electric Corp WCAP-7819 ROIA 75/04/30 J3pp 25948 149 24x Fiche 50-305,84/08/01.8408070275
- --8408070288 "Test Rept on Isolation Amplifiers ' GARBER,I Westinghouse Electric Corp WCAP-7683-A 75/05/31 10pp 25948 183 24% Fiche 50-305,84/08/01,8408070275
- 840B100019 Revised radiological emergency response plan implementing procedures including EP-AD-1, "Plant Emergency Organization" & EP-OP-1, "Control Room Emergency Organization " W/840806 ltr HINTZ,D C Wisconsin Public Service Corp 84/08/06 i8pp 25989 286 24% Fiche 50-305,84/08/06,8408100019
- B408240428 Forwards Insp Rept 50~305/84-07 on 840709~13 & notice of violation Licensee should address emergency preparedness weatnesses identified in App B Shift staffing also questioned Wo notice of violation & App B HIND, J A Region 3, Office of Director 84/08/06 GIESLER, C W Wisconsin Public Service Corp 3pp 26237 121 24X Fiche 50-305,84/08/06,8408240428
- --8408240429 Emergency Proparedness Insp Rept 50-305/84-07 on 840709-10 Noncompliance noted failure to perform monthly communications tests SNELL,W O. GLOERSEN,W B. PHILLIPS,M P. Region 3, Office of Director 84/08/06 13pp 2623/124 24X Fiche 30-305,84/08/06,8400240428
- B40B2B0144 Advises that rev to procedures generation program describing method of developing & upgrading emergency procedures will be submitted by B41001 Training program on upgraded emergency operating procedures being finalized HINTZ.D C Misconsin Public Servico Corp 84/08/23 VARGA, & A Operating Reactors Dranch 1 ip 26275 187 24X Fiche 50-309.84/08/23.8408280144
- K Utility Final Bafety Analysis Report (FSAR) & amonds
- 8407260161 Forwards revised pages to updated FSAR for Kewaunee Nuclear Phmer Plant Pages revised due to minor typographical errors teditorial or administrative comments Drawings revised due to completion of plant design of the completion of the completio
- ~-8407260166 Revised pages to updated FBAR for Kewaunee Nuclear Power Plant # Wisconsin Public Bervice Corp 84/07/20 300pp 25823 009 24X Fiche 50-305.84/07/20,8407260161
- P Operating license stage documents & correspondence
- 8408010208 Notification of 840731-0801 meetings w/util at site to discuss radiological ETS NEIOHBURS, D. Operating Reactors Branch i 84/07/20 VAROA, B / Operating Reactors Branch i 3pp 25873 269 24X Fiche 50-305.84/07/20.8408010208
- 8408060407 Notification of location & time change for 840731-0801 meetings w/util in Orem Bay. WI to discuss radiological ETB Meeting originally scheduled at site MEIGHBURS D. Operating Reactors Branch 1 84/07/20 VARGA. 8 A Operating Reactors Branch 1 ip 25951 168 24x Fiche 50-305.84/07/20.8408060407
- 8408020073 Application for amend to License DPR-43, consisting of Proposed Amend 62, revising Toch Specs for consistency w/new reporting requirements of IOCRSO 73, "LER Bys" GIESLER.C W Wisconsin Public Service Corp 84/07/27 DENTON, WR Office of Nuclear Reactor Regulation. Director 12pp 25891 335, 24% Fichs 50-305,84/07/27,8408020073
- --8408020078 Proposed Tech Space for consistency w/new reporting requirements of 1007880, 73. "LER Sys "
  \* Wisconsin Public Service Corp 84/07/27 24pp 25891 347 24X Fiche 50-305, 84/07/27, 8408020073

- 8408060093 Forwards updated Tach Specs 1 2-1 & 4 5-2 for Amend 55 to License DPR-43 re ASME Code class inservice insp & testing Previous pages inadvertently issued as draft SAUER, D W Wisconsin Public Service Corp 84/07/27 NEIGHBORS, D NRC NO Dotatled Affiliation Civen 2pp 25925 315 24X Fiche 50-305,84/07/27,8408060093
- 8408050212 Requests fee for 840517 application transmitting safety evaluation of RHR sys autoclosure feature within 15 days of receipt of ltr MILLER, W O License Fee Management Branch 84/07/27 GIESLER, C W Wisconsin Public Service Coip 1p 25950 255 24X Fiche 50-305 84/07/27.8408060212
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for GLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000,84/08/06,8408070110
- B408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
  TREMBLAY.P. P. Operating Reactors Assessment Branch B4/08/04
  HOLAHAN.C M. Operating Reactors Assessment Branch 13pp
  25991 350 24X Fiche 30-000,84/08/06.8408090317
- B408100078 Forwards review fee for proposed removal of RHR autoclosure feature HINTZ:D C Wisconsin Public Service Corp 84/08/06 MILLER,W 0 License Fee Management Branch ip 25990 196 24X Fiche 50-305.84/08/06.8408100078
- 840Bi30372 Ack receipt of 840611 GA program Paragraph 3 of 10CFRSO 54 requires listed changes when GA program description reduces prior commitments Revised forwarding 1tr.which fully complies w/requirement.requested within 30 days SPESSARD.R L. Region 3. Office of Director 84/08/07 GILSLER.C W Hisconsin Public Service Corp 2pp 26010 361 24X Fiche 50-305.84/08/07.8408130372
- 8408160482 Summary of 840724 meeting w/Westinghouse Duners Oroup re upper plenum injection for two loop plants BIJANNI,D C Operating Reactors Branch 3 84/08/09 Operating Reactors Branch 3 4pp 26108 327 24X Fiche 50-000,84/08/09, 8408160482
- B408220284 Discusses rod position indication for shutdown modes, per NRC 830324 concerns Surveillance procedure performed each shift verifies rod position indication sys meets appropriate acceptance criteria MINTX, D.C. Wisconsin Public Service Corp. B4/08/15 VARGA, S.A. Operating Reactors Branch 1 2pp. 26189 315 24X Fiche 30-305.04/08/15,8408220284
- 8408200275 Generic Ltr D4~20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unroviewed safety questions Svc list encl EISENHUT. D © Division of Licensing 84/08/20 Consolidated Edigin Co of New York, Inc 17pp 26276 244 24X Fiche 50~000,84/08/20,8408200275
- 8408240199 Forwards "Kewaunee Nuclear Power Plant 1984 Integrated Leak Rate lest & 1981-1984 Local Leak Rate Tests," summary rept HINTZ, D.C. Wisconsin Public Service Corp. 84/08/20 VARGA, S.A. Deersting Reactors Branch 1 2pp. 26/27 231 24X Fiche 50-305,84/08/20,8408240199
- --8408240205 "Kewaunce Nuclear Power Plant 1784 Integrated Leak Rate Test & 1981-1984 Local Leak Rate Tests." summary rept \* Wisconsin Public Service Corp 84/08/20 90pp 26227 233 24X Fiche 50-305,84/09/20,8408240179
- 8408280475 Confirms commitments of 840731 meeting re implementation of radiological effluent Tach Specs (RETS) Tach Specs to be implemented & RETS format followed as closely as possible Separation of RETS & existing specs will minimize confusion HINTZ,D.C. Wisconsin Public Service Corp. 84/08/21 VARQA,S.A. Operating Reactors Branch 1 2pp 26282 100 24X
  Fiche 50-305,84/08/21,8408280475
- 8408310122 Application for amend to License DPR-43 consisting of proposed Amend 60a to Tech Specs correcting inadvertent deletion in Amend 40 & indicating organizational changes OIESELER.C W Wisconsin Public Service Corp 84/08/21 DENTON, H R Office of Nuclear Reactor Regulation. Director 4pp 26322 245 24X Fiche 50-305,84/08/21,8408310182

- --B408310126 Proposed Tech Specs correcting inadvertent deletion in Amend 48 & indicating organizational changes a Wisconsin Public Service Corp 84/08/21 8pp 26322 249 24X Ficha 50-305.84/08/21.8408310122
- B40B310374 Requests assistance in review of util B40/27 proposed amend to QL revising Tech Specs to reflect 10CFR50 73. "LER Sys "
  SRP & ST8 should be used as guidance SER & SALP input due by
  B410Q1 W/s encl
  EIBENHUT.D G Dffice of Nuclear Reactor Regulation, Director
  B4/08/27 NORELIUS.C E Division of Project & Resident Programs
  2pp 26350 325 24% Fiche 50-305.84/08/27.840B310374
- 8408310451 Advises that MB Fairtile assigned as NRC project manager for facility, effective 840823 Telephone number listed VARGA:5 A Operating Reactors Branch E 84/08/28 GIESLER.C W Wisconsin Public Service Corp 19 26390
- Q Inspection reports, IE Bulletins & Correspondence
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229
- 8408060093 Forwards updated Tech Specs 4 2-1 & 4 5-2 for Amend 55 to License DPR-43 re ASME Code class inservice insp & testing Previous pages inadvertently issued as draft SAUER, D W Misconsin Public Service Corp 84/07/27 NEIGHBORS, D NRC - No Detailed Affiliation Given 2pp 25925 315 24X Fiche 50-305,84/07/27,8408060093
- 8408070401 Informs that now sys of acknowledging receipt of licensee currespondence re nonconpliance found during insp instituted.effective 840820 Preprinted form will be used rather than ltr
  KEPPLER.J G Region 3, Office of Director 84/08/03
  Commonwealth Edison Co 3pp 25942 IBB 24X Fiche 50-000.84/08/03, BA08070401
- B40B010333 IE Info Notice B4-59, "Deliberate Circumventing of Station Health Physics Procedures" Bvc list encl JOROAN,E L. Division of Emergency Preparedness & Engineering Response (Post B33103) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26068 001 24X Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Maet Efficiency Requirement " Svc list enc! JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc. 123pp 26067 158 24% Fiche 50-000,84/08/06,8408010337
- 8408240428 Forwards Insp Rept 50-305/84-07 on 840709-13 & notice of violation Licensee should address mergency preparedness weaknesses identified in App 8 Shift staffing also questioned W/o notice of violation & App 8 HIND. J A Region 3. Office of Director 84/08/06 GIESLER.C W Wisconstin Public Service Corp 3pp 26237 121 244 Ficho 50-305.84/08/06.8408240428
- --8408240429 Emergency Preparedness Into Rept 50-305/84-07 on 840709-13 Nancompliance noted failure to perform monthly communictions tests &NELL.W G . GLORROSEN,W B . PHILLIPS,M P Region 3. Office of Director 84/08/06 13pp 26237 124 24X Fichs 50-305,84/08/06, 8408240428
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PMR Refueling Cavity " Set list encl JDRDAN,E. L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York, Inc. 120pp 26129 118 24X Fiche 50-000.84/08/08.8408070120
- 8408070374 IE Info Notice 84-42, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list enci ORACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 123pp 26130 001 24X Fiche 50-000.84/08/10.8408070374
- B40B100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JURDANNE L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc. 119pp 26197 218 24X Fithe 50-000.84/08/13,8408100009

- 840B300192 Forwards Insp Rept 50-305/84-11 on 840801-03 No ndhcompliance noted WALKER,R D Region 3. Office of Director 84/08/14 GIESLER,C W Wisconsin Public Service Corp 2pp 26307 355 24( Fiche 50-305.84/08/14.8408300192
- --8408300199 Insp Rept 90-305/84-11 on 840801-03 No nancompliance or deviations nated Major aleas inspected previous insp findings
  CHQULES,N C , HAWKINS,F C Region 3, Office of Director 84/08/13 4pp 26307 357 24% Fiche 50-305/84/08/14.8408300192
- B40810003B IE Info Notice 84-64, "BUR HPC1 Initiation Seci-In & Indication " Svc list enc! JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co. of New York, Inc. 104pp 26198-093 24X Fiche 50-000.84/08/15,8408100038
- 9408100021 IE Info Notice 84-65 Underrated Fuses Which Mag Adversely Affect Operation of Essential Electrical Equipment " Syc list enc! JORDANIE L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08//6 Consolidated Edison Co. of New York. Inc. 118pp. 26198-001 24X Fiche 50-000-84/08//6. 3408100021
- 8408100035 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26876 001 24K Fiche 50-000.84/08/17,8408100085
- 8408140208 IE Info Notice 84-67. "Recent Snubber Inservice Testing W/High Failure Rates "Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84408/17. Consolidated Edison Co. of New York, Inc. 122pp 26276 122 24% Fishe 50-000,84/08/17,8408140208
- 8408310288 Forwards Insp Rept 50-305/84-10 on 840802-03 No nancampliance moted PAPERIELLOC J. Region 3. Office of Director 84/08/17 GIESLERIC W. Wisconsin Public Service Corp. 2pp. 24333 290 24X Fiche 50-305.84/08/17.8408310288
- --8408310296 insp Rept 50-305/84-10 on 840802-03 No noncompliance or deviation identified Hajor areas inspected implementation of 10CFR20 & 61 & disposal of low level radwaste including mgt controls & waste form RUZAK, S. SCHUMACHER, M.C. Region 3. Diffice of Director 84/08/14pp 26333 292 24X Fiche 50-305,84/08/17.8408310288
- 840B210142 IF Info Notice 84-60. "Potential Deficiency in Improperly Rated Field Wiring to Bolenoid Valves " Svc list and Junearing Arabonse (Post 830103) 840B21 Consolidated Edison Co of New York Inc 115pp 26329 008 24X Fiche 50-000.84/09/21.8408210142

#### Periodic operating reports & related correspondence

- |408160211 Monthly operating tept for Jul 1984 H/840809 | tr | RUITER.C H : HINTZ,D C | Wisconsin Public Service Corp | B4/07/31 | Spp | 26106 262 | 24% Fiche 50-305.84/07/31.84081602}}
- Reportable occurrences. LERs & related correspondence
- |408040244 LER 84-012-00 on 840428, both trains of auxiliary bldg special vent sys inadvertently started during performance of l&C procedure Caused by personnel error Both trains secured & realigned for opromal operation #/840727 ltr 8ERNHOFTLS , HINTZLD C #lsconsin Fublic Service Corp 84/07/2: ip 25935 147 24% Fiche 50-305 84/07/27.8708060241
- #408080510 LER 84-013-00 on 840702, train 8 of auxiliary bldg special ventilation sys ran for no apparent reason Caused by burnt out Johnson solenoid valve coil in closed position basign change institated to replace valves W/#40801 its BERNHOFT.S. HINTZ.D C Wisconsin Public Service Corp 84/08/01 Jpp 25979 259 24X Fiche 50-309,84/08/01.8408080510
- M08080033 LER 84-014-00 on 840703 loss of power on instrument bus IV resulted in partial loss of instrumentation, alarms & level control problems on steam generators Caused by loose connection of ac output breaker 52 connector W/840802 ltr MARCHLM, HINTZ,D C Wisconsin Public Service Corp 84/08/02 3pp 25962 151 29X Fiche 50-305,84/08/02,8408080033

- V Operator Examinations
- 840B140426 Plovides address for transmitting all operator licensing correspondence to Region III officerent info for examiners WALKER, R.D. Region 3, Office of Director 84/08/10 Michigan. Univ. of, Ann Arbor, MI. 2pp. 26051 198 24X fiche 50-000, PRAIDELO, BIOREMAN 264
- DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION UNIT 2 F Security, medical, emergency & fire protection plans
- BAOB200484 Grants exemption from certain requirements of 10CFRSO. App R. Subsections III G 2\* III O re reactor coolant pump jube oil collection sys Commitment to protect redundant cabling expected to be completed by 841231 MILLER, J R Operating Reactors Branch 3 84/07/31 MUSDLF, D M Northern States Power Co 2pp 26143 331 24X Fiche 50-282.84/07/31.8408200484
- --8408200489 Exemption from certain requirements of 10CFR30. App R.
  Subsections III G 2 % III O re Fire Areas 1 % 71 & reactor
  coolant pump lube oil sys
  EISENHUT.D G Division of Licensing 84/07/31 Northern States
  Power Co 7pp 26143 333 24X Fiche 50 282,84/07/31.8408200484
- B40B300176 Forwards Rev 7 to "Northern States Power Co Corporate
  Nuclear Emergency Plan " Rev includes changes resulting from
  annual internal review, update & certification of emergency
  plans & agreements
  FEV.F L Northern States Power Co 84/08/02 Region 3. Office o
  Director 4pp 26302 106 24% Fishe 50-000.84/00/02.8408300176
- --84083001B0 Rev 7 to "Northern States Power Co Corporate Nuclear Emergency Plan " HUDSON.G , FEY.F L , LARSON.C E Northern States Power Co 84/08/02 | 116pp 26302 110 24% Ficho 50-000.84/08/02. 8408300176
- --8408300183 Revised "Radiation Environ Monitoring Plan"
  CLARK, B K : FEY. F L Northern States Power Co 84/02/29 14pp
  26302 286 24X Fiche 50-000.84/00/02.8408300176
- B408100029 Forwards IE Safeguards Insp Repts 50-282/84-10 & 90-306/84-09 on 840709-13 & notice of noncompliance Notice of noncompliance withheld (ref 100FR73 21) AXELSON, W.L. Region 3, Office of Director 844/08/03 LARSON, C.E. Northern Status Power Co. 2pp. 25987 068 24X fiche 50-282,84/08/03,8408100029
- --8408100037 IC Bafeguards Insp Repts 50-282/84-10 / 30-306/84-09 on 840709-13 Noncompliance noted failure to provide effective barrier in portion of protected area purimeter Details withheld (ref 10CFR73 21) KNICELEY, J. R. Region 3. Office of Director Q4/08/03 2pp 25987 070 24X Fiche 30-282.84/08/03.8408100029
- 8409310173 Ack receipt of 840625 Rev 4 to emergency plan Next rev should include description of ansite & offsite environs & radiological monitoring drills & monthly communications check PAPERIELLO, C J. Region 3, Office of Director 84/08/27 LARBUN, C E. Northern States Power Co. 2pp. 26319 141 24X Fiche 30-282,86/08/27,84083101/3
- P Operating license stage documents > Correspondence
- 84080/0110 Generic Ltr 84-19 to all licensess of operating reactors, applicants for OLs & helders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Bafety Issues " Svc list one! ELECNMUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26127 238 24X Fiche 50-000,84/08/06.84080/0110
- B40B1404B2 Summary of B40724 meeting w/Westinghouse Owners Group reupper plenum injection for two loop plants
  DIGANNI.D C Operating Reactors Branch 3 B4/0B/09 Operating
  Reactors Branch 3 4pp 2610B 327 24X Fiche 50-000, 84/0B/09.
  B40B1604B2
- B40B200275 Generic Ltr 84-20 to all licenses of operating reactors & applicants for GLs re-scheduling guidance for licenses submittals of relaads that involve unreviewed safety questions Svc list oncl CIBCNHUT, 0 G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276-244 24X Fiche 50-000.84/08/20.8408200275

- G Inspection reports, IE Bulletins / Correspondence
- 8407250929 IE Info Notice 84-57. Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants "Sic list encl JORDAN, E.L. Division of Emergency Preparedness "Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc. 119pp 25865-047 24% Fiche 50-000.84/07/27, 8407250229
- 8408070189 Ack receipt of 840713 ltr informing NRC of steps taken to correct violations noted in IC Insp Repts 50-282/84-04 & 50-306/84-04 Corrective actions Ie sus blocking & tagging appropriate SHAFER,!! D. Region 3. Office of Director 84/07/31 LARSON.C & Northern States Power Co. 2pp. 25949-349 24X Fiche 50-287,84/07/31 8408070189
- --8408070197 Responds to NRC 840629 ltr re violations noted in IE Insp Repts S0-282/84-04 & S0-306/84-04 Corrective actions reactor coolant vent sys solenoid valve fuses removed & will not be installed until requirements met LARSON.C E Northern States Power Co 84/07/13 SHAFER, W D Region 3. Office of Director 2pp 25949 351 24X Fiche 50-282,84/07/31,8408070189
- 8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re honcompliance found during inspirational structures and structures and structures are structured form will be used rather than ltr
  KEPPLER, J. G. Region 3. Office of Director 84/08/03
  Commonwealth Edison Co. 3pp. 25742 188 24X Fiche 50-000, 84/08/03.
- 8408100029 Forwards IC Safeguards Insp Repts 50-282/84-10 & 50-306/84-09 on 840709-13 / notice of noncompliance Notice of noncompliance withheld (ref 10CFR73 21) AXELSON, V. L. Region 3, Office of Director 84/08/03 LARSON, C. E. Northern States Power Co. 2pp. 25987 068 24X Fiche 30-282,84/08/03,8408100029
- --8408100037 IE Safeguards Insp Repts 50-282/84-10 & 50-305/84-09 on 840709-13 Nancompliance noted failure to provide effective barrier in portion of protected area perimeter Details withheld (ref 100FR73 21)
  KNICELEYJ R , BELANGER, J. L . CRCED, J. R. Region 3, Office of Director 84/08/03 2pp 29987 070 24X Fiche 50-282,84/08/03,8408100029
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JORDAN, E. L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26068 001 24% Fiche 50-000/84/08/06/8408010333
- BAOBO10337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list encl JORDAN, E. L. Division of Emergency Pieparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc. 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Natice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Past 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fiche 50-000.84/08/08.8408070120
- 8408070376 IE Info Notice 9.4-2P. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl GRACE.J N Division of QA. Safeguaids ! Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 123pp 26130 001 24% Fiche 50-000.84/08/10.8408070376
- \$\text{8408100009} \text{ IE Info Natice 84-63. "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN, E.L. Division of Emergency Proparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 117pp 26177 218 24X Fiche 50-000,84/08/13,8400100009
- 8408100038 IE Info Notice 84-64, "BUR MPCI Initiation Seal-In & Indication " Svc list encl JURDAN.E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000.84/08/15,8408100038
- B40Bi0002) IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

- 840B100055 IE Info Notice 84-66. Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN. C. L. Division of Emolgency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York. Inc. 120pp 26276 001 24% Fiche 50-000.84/08/17.8408100055
- 8408140208 IE Info Notice 84-67, "Recent Shubber Inservice Testing W/High Failure Rates" Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineeribg Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc. 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208
- 8408210142 IE Info Notice 84-68. 'Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 1:5pp 26327 008 24% Fiche 50-000,84/08/21,8408210142
- S Reportable occurrences, LERs & related correspondence
- 8408210278 Part 21 rept re separation of rod eye connected to piston rod from threaded portion of piston rod at approx 750,000 lb stress load Caused by insufficient mati thickness to withstand faulted load Matl certification encl MILLS.C. R. Chicago Fivid Pover Co. 84/08/16 Director's Office, Defice of Inspection and Enforcement 4pp 26180 349 24X Fiche 50-282,84/08/16.8408210278
- V Operator Examinations
- B40B140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examinars MALKER,R D Region 3. Office of Director B4/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10,840B140426
- 8408230526 Advises that operator & senior operator licensing exams scheduled for 841112-15 Matl listed in encl "Ref Matl Requirements for Operator/Senior Operator Licensing Exams" requested by 840913 MALYER, R D Region 3. Office of Director 84/08/17 LARSON, C & Northern States Power Co 5pp 26212 338 24% Fiche 50-282.84/08/17.8408230526
- 8408230132 Informs of review of 840705 ltr which clarified interpretation of on-shift training requirements Util will be required to provide documentation that senior reactor operator upgrade candidates comply w/listed requirements WALKER, R. D. Region 3, Office of Director 84/08/20 LARSUN.C. E. Northern States Power Co. 2pp. 26209 061 24% Fiche 50-000,84/08/20,8408230132
- DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT

  F Security, medical, emergency & fire protection plans
- 8408030008 Forwards fire haidrds evaluations for primary auxiliary & svc bldgs Evaluations demonstrate that structures maintain acceptable level of fire protection equivalent to requirements of 100FR90. App R
  HHITTIER: G D Maine Yankee Atomic Power Co 84/07/25 MILLER. J R
  Deerating Reactors Branch 3 5pp 25906 010 24X
  Fiche 50-309,84/07/25.8408030008
- 8408140399 Public version of Change 6 to emergency plan, Vol II \* Maine Yankee Atomic Power Co 84/08/01 231pp 26048 090 24X Fiche 50-309.84/08/01.8408140399
- 8408230487 Forwards IE Insp Rept 50-309/84-12 on 840604-08 & notice of violation MARTIN.7 T Division of Engineering & Technical Programs 84/08/02 RANDAZZA.J B Yankee Atomic Electric Co 2pp 26212 240 24X Ficha 50-309,84/08/02.8408230487
- --8408230492 Notice of violation from insp on 840604-08 Safeguards info withheld (ref 1007873 21) \* Region I. Office of Director 84/08/02 ip 26212 242 24X Fiche 50-309,84/08/02.8408230487
- --8408230495 IE Insp Rept 50-309/84-12 on 840404-08 Noncompliance noted plant security program Safeguards info withheld (ref 10CFR73 21) STRUCKMEYER, R. PASCIAK, W.J. Region I. Office of Director 84/07/20 App. 26212 243 24X Fiche 50-309,84/08/02,8408230487

- --8408270407 Notice of violation from this on 840315-0130

  \* Region 1, Office or Director 84/08/06 2pp 26256 319 44\*
  Piche 50-309,84/08/06,8408270406
- --8408270110 lnsp Rept 50-309/84-0b on 840315-0430 Violations noted failure to maintain fire protection procedures, incomiect auxiliary feeduater sys weld data sheets, lack of records of pest tank discharge & incomplete weld insp HOLDEN.C. FERLIC.N. QRAY E.H. Region 1. Office of Director 84/08/06 13pp 26255.321 24x Fiche 50-309,84/08/06.8408270406
- 8408230331 Revised emergency plan implementing procedures including 2 50 4 re general emergency 2 50 14 re emergency radiation exposure control 5 2 50 19 re technical support ctr W/rev transmittal fora # Maine Vankee Atomic Power Co 84/08/09 77pp 26206 054 245 Fiche 50-309, 84/03/09, 8408230331
- 8408310204 Rev & to Energency Plan Implementing Protedure 2 50 0. "Declaration & Categorization of Emergency Condition " Wome oversize table Aperture card available in PDR W/840824 transmittal form # Maine Yankee Atomic Power Co. 84/08/09 4pp 26317 223 24X Fiche 50-309,84/08/09,8408310204
- 8408230304 Requests updated evacuation time estimate study for NRC use in evaluating impact on state of emergency preparedness. Update should include listed criteria Response requested within 90 dys of itr date. HURLEY, F.E. Region I. Office of Director 84/08/10 RANDAZIA, J.B. Mains Yankee Atomic Power Co. 2pp. 26213 247 24X Fiche 50-309,84/08/10,8408230304
- 8408220431 Informs of N9C.uti) & FEMA efforts to resolve citizen concern re emergency preparedness. In particular, evacuation using State Road 27 Request for odd1 info (sawod to util Issue still under review DEYOUNG, R C Director's Defice. Office of Inspection and Enforcement BAYOB/20 MILLER D S Sensible Maine Power 3pp 26209 343 24X Fighe 50-309.84/08/20,8408220431
- 8408280210 Submits status rept of efforts to upgrade & implement plant-specific emergency operating procedures prior to issuance of NURGO-0737, Suppl 1 & before rest of Industry WHITTIER, G D Maine Yankee Atomic Power Co B4/08/22 MILLER, J R Operating Reactors Branch 3 Spp 26269 354 24% Fiche \$0-309,84/08/22,8408280210
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8408020121 Forwards updated FSAR replacement pages for Maine Yankee, por 100FRS0 71(e) Rev reflects Cycle 8 Core performance RANDAZZA-J B Haine Yankee Atomic Power Co 84/07/29 MILLER-J R Operating Reactors Branch 3 1p 25881 230 24X Fiche 50-309.84/07/23.8408020121
- -8408020125 Updated FSAR replacement pages for Maine Yankee + Maine Yankee Atomic Power Co 84/07/23 358pp 25881 231 24X Fiche 50-307.84/07/23.8408020121
- P Operating license stage documents & correspondence
- B408070367 Provides status on functional testing of post-accident sampling sys (PASS) analytic equipment, per TMI I tem II B 3 PASS procedures & methodology discussed & misonderstandings in NRC 831021 ltr corrected WHITTIER.9 D Manne Yankee Atomic Power Co 84/07/30 MILLER.J R Operating Reactors Branch 3 3pp 25944 281 24X Fiche 50-309.84/07/30.8408070367
- B4QB160167 Informs of review of B40615 ltr re auxiliary feedwater sys (AFW) (TMI ltem II E 1 1) Requests Tech Spec for monthly surveillance testing of AFW sys pumps
  MILLER, J. R. Operating Reactors Branch 3 84/08/01 RANDAZZA, J.D. Maine Yankee Atumic Power Co. 2pp. 26124 330 24X
  Fiche 50-309,84/08/01.8408160167
- 8408170036 Advises that 833728 seismic & closure analysis acceptable re operability of Masonellan Intl.Inc 8-inch containment ventilation sys globe valve MILLER, J. R. Operating Reactors Branch 3 84/08/01 RANDAZZA, J. B. Maine Yankee Atomic Power Co. 1p. 26134 360 24X Fiche 50-309.84/08/01.8408170036
- 8408090173 Forwards "Assessment of Driginal Design Methodology for Belamic Category I Piping Sys at Maine Yankee Atomic Power Statton " WHITTIER 6 D Haine Yankee Atomic Power Co 84/08/03 MILLER, J R Operating Reactors Branch 3 ip 25973 186 247 Fiche 30-309,84/08/03.8408090173

- --8408090182 Ascessment of Original Terign Nothodology for Seismic Category I Piping Sys at Nathe Yanker Atomic Power Station " HENRIES, of Yanker Atomic Electric Co. 8400430 95pp 259/2 188 24x Fithe 50 303 8108 03.8408090173
- B40B37011t Genetic Ltr 81 19 to all livensees of operating reactors applicants for QL- \* holders of CPs to availability of Suppl 1 to NUPEG-0933. \*Prioritization or Genetic Safety Issues \* Sec list encl EISENBULL O C. Division of licensing 81/08/06. Consolidated Edson Co. of Peu York, Inc. (Gpp. 26/129 238 24X Fiche 50-000 84/08/06.8408070110
- BAOB230291 Requestr fees for BAOL19 % 0522 applications for amends to License DPR-36, changing Treb Space to steam generator water level? containment integrity respectively DIGGS.R M. License Fee Management Branch B4/00/1/ RANDAZZA, J b Maine Yante Atomic Pours to 3pp 26276 126 PAX Fiche 50-309,84/08/17,84/08/30291
- 8408200275 General Ltt 84 20 to all licensees of operating reactors applicants for OLs re-scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions SVC list end.

  EISENNUT, D.G. Division of Licensing 84/08/20 Consolidated Edison Co of New York, for 17pp 26276-244 24X

  Fishe 50-000.84/03/20.8488200275
- 8408280227 Responds to NRC request to evaluate impact on safe shutdown equipment due to flooding flom non-Class I (seismic) sys. component or pipe Flooding will not impact safety-related electrical equipment HHITTER, G D Maine Yankee Atomic Power Co 84/08/23 MILLER, J R Operating Reservers Branch 3 1p 262/5 361 24X Fiche 50-309.84/08/23.8408280227
- **a** Inspection (cports, If Bulletins t correspondence
- 840725027 IE Info Notice 84-57, "Operating Experience to Mossture Intruston in Safety-Related Electrical Equipment at Commercial fouer Plants "Ser list end JORDAN, E. L. Divisson of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edisson Co. of New York, Inc. 119pp 25865-047 24X Liche 50-000,84/07/27,8407250229
- 840823048/ Forwards IE Insp. Rept. 50-309/84-12 on 140694-08 & notice of violation MARTIN. T. T. Division of Engineering & Technical Programs 84/08/02 RANDAZZA, J. B. Yankee Atomic Flectric Co. 2pp. 26/12-240-24X Fiche 30-309/84/08/02/8408/30487
- ---B408230492 Notice of violation from insp on 840604-08 Safeguards info withheld tref 10CFR73 21) \* Region I. Office ne Director 04/08/02 ip 26212 242 24x Fiche 50 309,04/08/02,8408230487
- ~-8408230495 It Insp Rept 50-309/84-12 on 840604 OB Noncompliance noted plant security program Safequands into withheld tref 1006873 21)
  STRUCKMEYER R. PASCIAK.R. J. Region 1. Office of Director 84/07/20 opp 26212 243 24X Fishe 50-309/84/08/02/8408230487
- 8408010333 IE Info Notice 84-59. "Deliberate Circumventing of Station Health Physics Procedures." For list encl JORDAN, E. L. Division of Emergency Preparedures & Engineering Response (Post 830103) 84/00/06. Consolidated Edison Co. of New York, Inc. 127pp 24068 001 24X Fiche 50-000.84/08/06.8408010333
- BAORO1033/ If Info Nutice B4 60, "failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/08/06 Consolidated Edison Co of New York, Inc 123pp 2606/158 24X Fiche 90-000,04/08/06.840801033/
- #408270406 Forwards Insp Rept 80-309/84-06 on U40319-0430 & notice of Violation BTARDSTECKI,R Division of Project & Resident Programs 84/08/06 RANDAZZA,J B Maine Yankee Atomic Power Co 3pp 26256 316 24X Fishe 50-309,84/08/06.8408270406
- --8408270407 Notice of vigilation from insp on 940315-0430 \* Region to Office of Director 84,08/04 Ppp 26256 319 24X Fishe 90-309,84/08/05,84082/0406
- --8408270410 Insp Rept 50-309/84 06 on 840315-0430 Violations noted failure to maintain fire protection procedures, incorrect auxiliary foodwater sys weld data sheet. Lark of records of test tank discharge t incomplete weld insp HBLDEN.C., FTRITCIK., ONAY.E.H. Region 1. Office of Director 84/08/06 13pp 26295 321 24X Fiche 50-309,84/08/06.8408270406

- 8408070120 IF Info Notice 84 61 "Overexposure of Diver in PWR Refueling Cavity 'Suc list encl JORDAN F L Division of Emergency Preparedness > Engineering Response (Post 837103) 84/08/08 Consolidated Edison Co of New York
- B408070376 IF Into Notice 84-62, 'Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Syc list enci GRACE. J N Division of GA Sareguerds & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co. of New York, Inc 125pp 26130 031 24% Fiche 50-000,84/08/10,8408070376
- 8408100009 If. Info Notice 84-63. "Defective RHR Replacement Piping "
  fvc list encl
  JORDAN, E. L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co. of New
  York, Inc. 119pp 26197 218 24% Fiche 50-000,84/08/13,8408100009
- B40B1C0038 IE Info Notice 84-64. "BWR HPCI Initiation Seal-In & Indication "Svc list encl JRDAN.E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York Inc 104pp 26178 093 24X Fiche 50-000.84/08/15. B408100038
- 8408100021 (E Info Notice 84-65, "Underrated Foses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JORDAN, E L Division of Emergency Proparedness & Engineering Response (Post 830103) 8408/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000.84708/16,8408100021
- B40B100055 IE Info Notice B4-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/0B/17 Consolidated Edison Co of New York: Inc 120pp 26276 001 24X Fiche 50-000.84/0B/17.8408100055
- B40Bi40208 IE Info Notice 84-67, "Recent Snubbar Inservice Testing W/ High Failure Rates " Svc list encl JORDAN, E.C. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 122pp 26276 122 24X Fiche 50-000.84/08/17,8408140208
- B408210142 IF Info Notice 84-66, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc. 115pp 26327 008 24X Fiche 50-000,84/08/21,8408210142
- B Reportable occurrences, IFRs & rolated correspondence
- B408030272 LER 84-009-00 on 840622 noise spake in channel provided 2 of A coincidence \* tripped reactor Control element assembly (CEA) group manually tripped when reactor operator attempted to drive in shutdown CEA group W/840/26 Itr SMITH 5 P . WHITTIER 0 D Maine Yankee Atomic Power Co 84/07/26 4pp 25917 254 24X Fiche 50-309.84/07/26.8408030272
- DDCKET 50-311 SALEM NUCLEAR GENERATING STATION. UNIT 2

  F Security, medical, emergency & fire protection plans
- 8408030236 Ack receipt of 840608 ltr informing NRC of steps taken to correct violations noted in JE Insp Repts 50-272/84-10 & 50-31/84-10 BELLAMY,R R Division of Engineering & Technical Programs 84/07/18 UDERITA:R A Public Service Electric & Gas Co of New Jersey 2pp 25917 192 24% Fiche 50-272.84/07/18,8408030236
- --8408030247 Responds to NRC 840504 ltr re violations noted in IE Insp Repts 50-272/84-10 & 50-311/84-10 Corrective actions revised amorgancy plan brocking distributed in Feb 1984 & emergency response training program undergoing review & evaluation LIDEN,E A Public Service Electric & Gas Co of New Jersey 84/06/08 MARTIN.T T Region 1, Office of Director Bpp 25917 194 24% Fiche 50-272,84/07/18,8408030236
- B40B070065 Forwards corrected page to 840612 confirmatory order, confirming Dec 1986 schedule for implementation of Suppl 1 to NUREG-0737 & Generic Ltr 82-33 re completion of structural mods to technical support tr W/o encl VARGA: S A Operating Reactors Branch 1 84/07/26 UDERITZ: R A Public Service Electric & Gas Co of New Jersey 3pp 25955 31 24x Fiche 50-272.84/07/26.8408070065

- 840B100093 Advises that B40106 Rev B to Amend 3 to physical security plan 5 contingency plan consistent w/provisions of 10CH50 54(p) A acceptable MARTIN. I T Division of Engineering 3 Technical Programs 84/08/02 UDERITZIR A Public Service Flectric & Oas Co of New Jersey 3pp 25991 001 24x Fiche 50-272.84/08/02,8408100093
- B40B150223 Forwards responses to B40504 ltr re INEL rept on util conformance to Reg Guide 1 97 requirements for emergency response capability & Suppl 1 to NUREG-0737 Changes to B30921 implementation plan listed LIBEN.E A Public Service Electric & Gas Co of New Jersey B4/08/09 VARGALS A Operating Reactors Branch 1 9pp 26066 081 24X Fiche 50-272,84/08/09,8408150223
- B408210408 Informs that FEMA does not intend to conduct full-scale evaluation of Hope Creek 1985 exercise Bince Balem Unit I OL issued prior to 820715 full participation in 1989 not required by NRC or FEMA rules KRIMMR W Federal Emergency Management Agency B4/0B/I3 JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 26177 256 24X Fiche 50-000.84/08/13.8408210408
- 8408220428 Notification of 840706 meeting w/util in Bethesda, MD to discuss add1 App R exemptions FISCHER, D C Derating Reactors Branch ! 84/08/16 VARQA, S A Operating Reactors Branch ! 2pp 26201 362 24X Fiche 50-272,84/08/16,8408220428
- % Utility Final Safety Analysis Report (FSAR) & amends
- B40B020100 Forwards Rev 3 to updated FSAR for Salem Generating Station, Units 1 & 2 Changes made per 10CFR30 39, but not previously submitted to NRC, identified in monthly operating repts LIDEN, E A Public Service Electric & Gas Co of New Jersey B4/07/23 VARGA, S A Operating Reactors Branch 1 6pp 25910 076 24X Fiche 50-272, 84/07/23, 8408020100
- --B408020108 Rev 3 to updated FSAR for Salem Conerating Station. Units 1 & 2 \* Public Service Electric & Gas Co of New Jersey 64/07/2: 439pp 25910 082 24X Fiche 50-272.84/07/23.8408020100
- P Operating license stage documents & correspondence
- B40B070059 Grants extension until no later than Jul 1984 for submittal of rept re reactor vessel mati surveillance program EISENHUT, D Q Division of Licensing 84/07/13 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 5pp 25955 325 24% Fiche 50-311.84/07/13,8408070059
- 8408130362 Revised Pages 6 & 7 to Salem. Unit 2 Cycle 2 startup test rept W/840730 ltr LIBEN.L A Public Service Electric & Gas Co of New Jersey 84707730 , MURLEY.T E Region 1, Office of Director Spp 26010 307 24X Fiche 50~311.84707/30.8408130362
- B40B190245 Forwards revs to Cycle 2 startup rept & safety evaluation of util rod exchange methodology LIDEN,E A Public Service Electric & Gas Co of New Jersey 64/07/30 VARGAS Operating Reactors Branch 1 10pp 26075 299 24X Fiche 50-272,84/07/30,8408150245
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for GLs & holders of CPs re availability of Suppl 1 to NUREO-0933. "Prioritization of Generic Safety Issues." Syc list encl EISENNUT, D 6 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000,84/08/06.8408070110
- 8408200343 Forwards drawing of proposed upgraded core exit thermocouple sys showing layout of major components, per TMI Item II F 2 LIDEN. E A Public Service Electric & Gas Co of New Jersey 84/08/13 VARGA: S A Operating Reactors Branch 1 4pp 26131 081 24X Fiche 80-272,84/08/13,8408200343
- 8408210554 Requests listed add1 info re environ qualification of electrical equipment important to safety & remaining outstanding justifications for continued operation Add1 info requested by 840827 VARGA, S.A. Operating Reactors Branch 1 84/08/13, UDERITZ, R.A. Public Service Electric & Gas Co. of New Jersey 2pp 26195 259, 24X Fiche 30-272,84/08/13,8408210554

- B210335 Submits add1 into to support B10621 request for relief fruiritides IWB 5222 5 IWU 5710 or ASME failer 5 Pressure essel Code. Secrion XI Relief required occause no viable leans of heating certain components orisis.

  IDEN.E.A. Public Ser ice Electric 6 Gas Co. or New Jersey.

  14/08/15 VARGALS A. Operating Reactors Branch 1. 2pp. 26179-340.

  24X Fiche. 50-272,84/08/15 8408210335
- )8240117 Forwards suppl to 830422 response to Generic Ltr 93-10D re lam for resolution of Thi Action Item 11 K 3 5, 'Automatic Frip of Reactor Coolant Pumps LIDEN.E A Public Service Electric t Gas Co of New Jersey R4/08/15 VAROA.S A Operating Reactors Branch 1 5pp 26228 224 24% Fiche 50-272.84/08/15 8409210117
- OSROO2/5 Generic Ltr 84-2C to all licensees of operating reactors & applicants for OLs re-scheduling guidance for licensee submittals of reloads that involve Unreviewed safety questions Svc list encl
  EISCHHUT, D G Di islom of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X
  Fiche 50-000 84/08/20.8408200275
- 108280330 Requests remittance or add1 fee for review of 770209 & 810810 applications to anend Licenses DPR-70 \* DPR-75 MILLER: M O License fee Management Branch 84/08/20 UDER:TZ:R Public Service Electric \* Gas Co of New Jersey 2pp 26294 081 24X Fiche 50-272.84/08/20.8408280330
- Inspection reports, IE Bulletins & correspondence
- 408030259 Forwards 1E Insp Repts 50-272/84-21 & 50-311/84-21 on 840589-0601 No Violations noted MARTIN 1 T Division of Engineering 5 Technical Programs 64/07/11 UDERITZIR A Public Service Flectric & Gas Co. of New Jersey 2pp 25917 244 24% Fiche 50-272.84/07/11.8408030259
- --8408030267 IE Inap Repts 50-2/2/84-21 / 50-311/84-21 on 840529-0601 No violations noted Major areas inspected radiation protection program including ALARA implementation eiternal exposure control 5 surveillance / posting DRAGGUN. T. SHAYBAY.M Region 1, Office of Director 84/07/09 5pp 25917 246 24x Fiche 50-272.84/07/11.8408030239
- 8408030236 Ack receipt or 840608 ltm informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-272/84-10 & 50-311/84-10
  BELLAMY, R R Division of Engineering / Technical Programs 84/07/18 UDERITZ R A Public Service Electric 2 Gas Co of New Jersey 2pp 25917 192 24% Fiche 50-272,84/07/18.8408030236
- --8408030247 Responds to NRC 840504 litrie violations noted in IE Inap Repts 50-272/84-10 / 50-311/84-10 Corrective actions revised emergency plan brockure distributed in Fob 1984 % emorgency response training program undergoing review & evaluation LIDEN, E.A. Public Service Electric & Gas Co. of New Jersey 84/06/05 MARTIN T.T. Region 1. Office of Director Bpp 25917 194 24K Fiche 50-272,84/07/18,8408030236
- M98160270 Discusses IE enforcement conference on 840627 & Forwards notice of violation associated w/IE Insp Rept 50-311/84-22 on 840529-30 Violation classified as Severity level IV STAROSTECKLR Division of Project / Resident Programs 84/07/20 UDERITA A Public Service Electric L 6as Co of New Jersey 20; 26106 172 24X Fiche 50-311,84/07/20,8408160270
- --8408160281 Notice of violation from insp on 840529-30 Violation noted on-the-spot change made on 840528 to operating procedure governing method to maintain prossure control resulting in blockage of automatic isolation function 4 Region 1. Office of Director 84/07/20 2pp 26106 173 24X Fiche 50-311.84/07/20,8408160270
- 8408150366 Forwards IE Insp Repts 50-2/2/84-23 % 50-311/84-23 on B40609-0706 % notice of violation Both aspects of violation. Including failure to include mechanical snubbers in formal snubber surveillance program, should be addressed STARDSTECKIER Division of Pioject / Resident Programs 84/07/25 UDERITE.R A Public Service Electric % Gas Co of New Jorsey 2pp 26079 166 24% Fiche 50-272,84/07/25,8408150366
- ~8408150369 Notice or violation from insp on 840609-0706 \* Region i. Office of Director 84/07/25 ip 26075 169 24X Fiche 50-272.84/07/25.8408150366
  - insp Repts 50-272/84 23 \* 50-311/84-23 on 840609-0706 oted failure to establish procedure to perform fing of safety-related equipment 2 mechanical
    - OMMERS Q J GRAY, E H Region 1, Office of pp 26075 169 24% Fiche 50-272, 84/07/25,

- 8407250rr it line into the ... Uperating to perience be Moisture Intrusion to Egypty helpto flectrical Equipment at Commutated Power Hambs "... that encl JUNDAY, to Distinct for Enclosing the Prepared News \* Engineering Response to at 8501.5; Ph. 07/2 Consolidated Edison Co. of New York In... 119pp 1985 647 EAS From 50-000 84/07/27,8407256229
- --B4080300-01 IE hit heating Repts 50 072784-30 t 50-311/84-29 on 840719 Major aleas discussed responsioness of action plan for improvement or multer dept uperations, submitted to NRC in Aug 1783 to recart insportations.

  I INVILLE J C NORRHGLM L J Region 1, Office of Director 84/07/20 App 25407 0/7 244 tiche 50-272,04/07/30,8408030027
- B40B200645 Forwards IE Insp Repts 50-2/2784-24 / 50-311/84-24 on B40529 No violations noted MARTIN I T Division of inginerring % Technical Programs B4/07/30 UDERITA A Public Service Electric \* Gas Co of New Jersey 2pp 26140 210 24X fithe 50-2/2.84/07/30.8408200043
- --8408200052 IE Insp Repts 50-272/84-24 % 50-311/84-24 on 840529 No violations noted Mojor are is inspected circumstances surrounding transportation accident near Rock Springs.WY. including shipping documentation waste packaging 8 shipment EVERTICA J. Mail R E. Rogion 1. Office of Director 84/06/18 3pp 26140 217 31x Fichs 50-279,84/07/30,8408200043
- B408070797 Forwards if ligt menting Ropts 50 272/84-30 \* 50-311/84-29 on 847/49

  STAROBIFCKI, R. Division of Project \* Resident Programs 84708/02

  UDRRITZ, R. Public Service Electric \* Gas Co. of New Jersey 2pp

  25948 243 213 Ficho 50~272,81708/02,8498070232
- --B408070237 IF Hqt Meeting Repts 50-2/2/84-30 % 50-31/84-29 on 840719 Hajor aleas discussed status of action plan for improvement of nuclear dept operations, including responsiveness to inspfindings
  LINVICE, J.C., NORRHCIM L. J. Region 1. Office of Director 84/07/26 68pp 25948 235 J4X Ficht 50-272,84/08/02.8408070232
- 840801033) IC info Natice 84 5%, 'Deliberate Circumventing of Station Health Physics Procedures 'S c list enci JORDAN, L Division of Emergency Preparedness & Engineering Response (Fost 830103) 84708706 Consolidated Edison Co of New York, Inc. 122pp. 26068 001 24X Fiche 50-000-84708706, 8408010333
- 8408010337 IF Info Notice 84 60. 'Failure of Air Purifying Respirator Filters to fleet Efficiency Requirement ' Svc list enci JORDAN:F ( Division of Emergency Preparagress & Engineering Response (Post 184003) 84/07/06 Consolidated Edison Co of New York: Inc 123pp 26067 188 F4X Fiche 50-000,84/08/06,8408010337
- 8408070120 IF Info Natice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Sec list end! URBANE to Division of Emergeficy Preparedness & Engineering Response (Post 0,3103) - 84708708 - Consolidated Edison Co. of New York, Inc. 120pp - 26127 118 - 24% Fiche 50-000,84708708,8408070120
- BAOBO703/a If Info Notice O4 A2, "Therapy Misadministrations to Patients Undergoing Co A0 Teletherapy Treatments " Svc list entl GRACE.J N Division of OA, Safequalds / Inspection Programs (Post B30103) (M/OB/19 (ansolidated Edison Co of New York Inc 129p 2/130 001 2/4 Fiche 50-000/04/08/10/08408070376
- B40B10003B II Info Datice D4-64, "BUR HPCI Initiation Seal-In & Indication 'Ave list enc!

  JBMDAN, E L Division of Emergency Preparedness & Engineering Response (Post 0701073) fi4/09/15 Consolidated Edison Co of New York, Inc. 104pp 7619B 073 24X Fishe 50-000.84/08/15.840810003B
- 6408100021 If Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Flectrical Equipment." Svc list encl JOHDAN, E. | Division of Emergency Pieparedness & Engineering Response (Post 83)103) 14/08/16 Consolidated Edison Co. of New York, Inc. 118pp 2/4198 UO1 24X Fiche 30-000,84/08/16,8408100021

- 810B100/05h IF Info Natice 84 to "Ondetested Unavailability of Furbine Ltd on Auxiliary Feedwater Train "See list encl JUNBON, C.L. District of Energy Preparedness & Engineering Response (P. st. 850/03) B1/03/17 Consolidated Edison Co. of New York Inc. 12/0pp 26276 Oct. 2xx Fiche 50-000 84/00/17, 840B100055
- 8498140205 IE Info Northe Glack, whereit Shubber Inservice Testing W/High Fullurc Rates Six List endl JORDAN, Li Dirision of Emergency Preparadness & Engineering Response (Fust 53103) 81/04/17 Consolidated Edison Co of New York In 124pp 262% 127 21X Fiche 50-000,84708/17,8408140208
- 8408210142 IL info Notice 84-68. "Patential Deficiency in Improperly Rated Field Wiring to Solinuid Valves Sve list encl JGRDAN, L. L. Di titon of Emergency Preparedness & Engineering Response (Post 830107) 81 08/21 Consolidated Edison Co. of New York, Inc. 115pp. 26329 008 24X Fiche 50-000.84/08/21,8408210142
- 8408310131 Responds to 83)102 ltr.840131 telcon to 840626 meeting reviolation in Insp Repts 50 272.83-29 t 50-311/83-31 Violation will be withdrawn toncern will be classified as open item MARTIN, T T Division of Engineering to Technical Programs 84/08/21 UDERICZ R Fublic Service Electric to Gas Co of New Jersey 2pp 26022 260 244 Fiche 50 272.84/08/21.8408310131
- R Periodic operating reports \* related correspondence
- 8408200276 Monthly operating light for Jul 1984 W/840810 lti MILLER, E.K., ZUPPO, J.M., Publik, Selvice Electric & Gas Co. of New Jersey 84/07/31 9pp 26139 105 24% fiche 50-311,84/07/31, 8408200276
- 840B160142 Forwards Nuclear Oversight Committee quarterly mept dtd 840731 LIDEM, E.A. Public Service Electric 7 Gas Co. of New Jersey 84/08/03 VARGA, S. Operating Reactors Branch 1 App. 2610B 075 24x Fichs 50-272.84-08/203.8498160142
- S Reputable occurrences. Ltks ' related correspondence
- 9408070076 LFR 84 017 03 on 840703 turtle found impinged on trash bars in circuliting uster sys intoke Crused by debits drawn into plant No corrective action required W/840802 ltr RUPP.J I ZUPKD / h Public Service Clectric & Gas Co. of New Jersey 84/08/02 app 25772/356 24X Fiche 50-311,84/08/02/ 8408070076
- 8408130588 LER 84-016-00 on 940705, leak discovered on common suction line to charging pumps Caused by 3 inch crack in Schedule 10 suction header pumping originating in the of weld Unit shutdown initiated Piping refliced U/910803 ltr RUPP. J. L. 20PAD. J. M. Public Scivice Electric 7 Gas Co. of New Jersey 84/08/03 5pp 26031303 24X Fiche 50-311.84/08/03.8408130588
- 8408230077 Cummary or blo837 operating reactor events meeting resoccurrences since 840719 meeting List of attendees, significant clenents % scatus of previous assignments encl CRUTCHS IFLD. D. Assistant Director for Safety Assessment 84/08/16 EISENHUT.D 6 Division of Licensing 20pp 26233 249 24X Fiche 50-000.84/08/16.8408230077
- 8408300349 LER 84-918-00 on 840/25 during pressurizer overpressure protection sys functional test, RCS pressure rapidly dropped upon opening PORV block valve SPR6 Valve failed to close in required time / resulted in reactor frip W/640824 ltr RUPP, J. L. ZUPKD, J. M. Public Service Electric & Gas Co. of New Jersey 84/08/24 8pp 26314 139 24% Fiche 50-311.84/08/24, 8408300349
- 8408300400 LER 84-019-00 on 840726.during controlled cooldown to Mode 5.both containment spray pumps inadvertently cleared & tagged while unit in Mode 4.contrary to Tech Specs Caused by personnel crore Pumps returned to svc W/840824 1th RUPP.J L. ZUPKO.J M. Public Service Electric & Gas Co. of New Jersey 84/08/24 5pp. 26308 208 24X Fiche 50-311,84/08/24,8408300400
- 8408310065 PNS-1-84-017 on 840827. unidentified male telephoned security post at Elevation 100 ft of Unit 1 on internal line & told security guard that bomb planted in containment Bomb search teams deployed No bomb found No explosion occurred DUNLAP. J. KEIMIGER. JOYNERJ. Region 1. Office of Director 84708727 10 26323 203 24x Fiche 50-272.84708727.8408310065

- DOCKET 50-312 RANCHO SELO NUCLEAR GENERATING STATION

  F. Security, medical, emergency & tire protection plans
- 8408080397 Forward, request for add1 info re emergoncy operation guidelines in order to continue review of 840301 plant-specific submittal Response requested within 7 days of iti receipt RIVENBARK, G. Operating Reactors Branch 4 84/07/24 RODRIGUEZ, R.J. Sacramento Municipal Utility District 3pp 25978 079 24X Fiche 50-312 84/07/24,8408080397
- 8408080445 Forwards request for add1 info re safety parameter display sys (9°PS) Continued implementation of SPDE acceptable Response requested within 40 days of ltr receipt RIVENBARK. O Operating Reactors Branch 4 84/07/27 RODRIGUEZ.R J Sacramento Municipal Utility District 4pp 25977 152 24% Fiche 50-312.84/07 27.8408080145
- ~~8408080449 Safety evaluation supporting continued implementation of safety parameter display sys.per Suppl 1 to NUREO-0737
  \* NRC No Datailed Arfiliation Given 84/07/27 Opp 20977 156 24X Fiche 50~312.84/07/27.8408080445
- B40B0702B2 Summary of 840620 meeting w/util & Bechtel in Bethesda, MD re implementation of Reg Ouide 1 97 requirements by licensee Util will provide supplemental rept to B40715 submission to address separation problems Viewgraphs encl MINER, 5 Operating Reactors Branch 4 84/08/01 Operating Reactors Branch 4 i2pp 25992 001 24% Fiche 50~312,84/08/01, B4080902B2
- 8408300493 Forwards Emergency Preparedness Insp Rept 50-312/84-11 on 840618-22 k notice of violation SCHUSTER.M D Region 5. Office of Director 84/08/02 RODRIGUEZ.R J Sacramento Municipal Utility District 2pp 26314 015 24X Fiche 50-312,84/08/02,8408300483
- --8408300498 Notice of Violation from insp on 840618-22 SCHUSTER.M D Region 5. Office of Director 84/08/02 2pp 26314 017 24X Fiche 50-312.84/08/02.8408300483
- --B408300004 Emergency Preparedness Insp Rept 30-312/84-11 on B40618-22 Violations noted failure to provide initial emergency preparedness training to two newly appointed shift supervisors t inadequate meteorological program FISH, R F. PRENDERGAST, K., SCHUSTER, M D. Region 5, Office of Director 84/08/02 12pp 26314 019 24X Fiche 30-312,84/08/02,8408300483
- 8408130207 Notifies that response to 840724 request for add1 infore emergency operating guidelines will be provided by 841214
  RODRIGUEZ.R J Sacramento Municipal Utility District 84/08/06
  STOLZ.J F Operating Reactors Branch 4 1p 26010 056 24X
  Fiche 50-312.84/08/06.8408130207
- P Operating license stage documents & correspondence
- B408310234 Application for amend to License DPR-54 revising Tech Specs re LER sys NBH. evaluation b description of proposed changes for Amend 105 & Rev 2 to Amend 93 enci RODRIGUEZ.R J Sacramento Municipal Utility District 84/06/25 EISENBUT.D C Division of Licensing App 26320 337 24X Fiche 50-312.84/06/25 8408310234
- --8408310237 Proposed Tech Specs re LER sys \* Sacramento Municipal Utility District 84/04/25 15pp 26320 343 24Y Fiche 50-312,84/06/25,8408310234
- B40B310217 Application for Amend 110 to License DPR-54, addressing changes resulting from BEW integrated reactor vessel mat1 surveillance program NSHC encl RDDRIGUEZ:R J Sacramento Municipal Utility District B4/06/27 CIBCNHUT:D G Division of Licensing 4pp 2631B f17 24X Fichs 90-312.84/06/27 840B310217
- ---B40B310220 Proposed Tech Specs addressing changes resulting from D&W integrated reactor Yessel math surveillance program \* Sacramento Municipal Utility District 84/06/27 App 26318 121 24% Fiche 50-318,84/06/27,840B310217
- 8408080298 Summary of 840712 meeting w/NEW Duners Group re non-nuclear instrumentation sys status Attendance list & viewgraphs encl KADAMBI,P Operating Reactors Branch 4 84/07/27 Operating Reactors Branch 4 34pp 25978 228 24X Fiche 90-000,84/07/27,8408080288

- B40E040177 Provides supplemental info to NSHC for proposed Amend 105 to License DPR-54 Info augments otil 840531 ltr describing living schedule plan
  RODRIGUEZ.R J Sacramento (Unicipal Utility District 84/07/31
  EISENHUT.D G Division of Licensing 2pp 25923 359 24X
  Fithe 50-312.84/07/31.8408040177
- 8408080161 Forwards SER & request for add; info for review of BAW-1702 re heutron dosinetry Info requested within 14 days of 1tr
- re Neutron dosailed y and organized transport transport transport to the struct of the structure of the
- --8408080170 Safety evaluation from review of BAN-1702 re surveillance of Capsule RSI-B of reactor pressure vessel surveillance Program

  \* Office of Nuclear Reactor Regulation, Director 84/07/31
  25979 004 24% Fiche 50-312,84/07/31,8408080161
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for QLs & holders or CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues "Svc list encl EISCNHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of Nau Vork, Inc. 18pp 26129 238 24x Fiche 50-000.84/08/06.8408070110
- 8408090317 Forwards monthly status mept me plant-specific backfitting activities for operating reactors & license applicants for Jul 1984 84/08/04
- Jul 1984
  TREMBLAY.P P Operating Reactors Assessment Branch 84/4
  HDLAMAN.G M Operating Reactors Assessment Branch 13pp
  25991 350 24% Fiche 50-000.84/08/04.8408090317
- B40B140239 Responds to request for add1 info re pressure & temp profiles for pipe breaks outside containment Pressure data encl
  - enct RODRIGUEZ,R J Sacramento Municipal Utility District B4 STOLZ,JF Operating Reactors Branch 4 2pp 26053 359 Fiche 50-312,84/08/09.8408140259 B4/08/09
- 8408210062 Forwards Amend 56 to License DRR-54 & safety evaluation Amend revises Tech Specs to incorporate leak testing of 66-inch containment purge & 12-inch containment equalizing valves at 6-month intervals STDLZ.JF Operating Reactors Branch 4 84/08/10 RODRIGUEZ.R J Sacramento Montcipal Utility District Spp 26195 152 24X Fiche 50-312.84/08/10.8408210062
- --8408210070 Amend 56 to License DPR-54, revising Tech Specs to incorporate leak testing of 66-inch containment purge & 12-inch containment equalizing valves at 6-month intervals STOL7.JF Operating Reactors Branch 4 84/08/10 4pp 26195 155 24x Fiche 50-312,84/08/10.8408210062
- --8408210074 Safety evaluation supporting Amend 56 to License DPR-54 \* Office of Nuclear Reactor Regulation, Director 34/09/10 3 26195 159 24X Fiche 50-312,84/08/10,8408210062
- 8408210152 Forwards request for addl info rp environ qualification of equipment important to safety Response requested within 30 days of itr receipt STOLZ.JF Operating Reactors Branch 4 84/08/10 RODRIGUEZ.R J Bacramento Municipal Utility District 4pp 26195 307 24X Fiche 50-312.84/08/10.8408210152
- 8408170362 Responds to recent telcom re effect of differing steam generator level setpoints on results of main steam line break scenario in FSAR, in connection w/IE Bulletin 80-04 ROBRIGUEZ, R J Sacramento Municipal Utility District 84/08/14 STOLZ, J F Operating Reactors Dranch 4 ip 26/12/357 24X Fiche 50-312,84/08/14,8408170362
- 8408210159 Notification of 840830 meeting w/util in Bathesda.MD to discuss implementation of Reg Quide I 97 requirements MINCR,8 Operating Reactors Branch 4 84/08/15 STOL7, J F Operating Reactors Branch 4 2pp 26195 223 24X Fiche 30-312.84/08/15.8408210159
- 3408240112 Requests extension until 850113 to respond to Generic Etr 84-15, "Proposed Staff Actions to Improve & Maintain Diesel Generator Reliability " Extension requested due to acope & magnitude of responses required RODRIGUEZ,R J Sacramento Municipal Utility District 84/08/16 EIBENHUT D © Division of Licensing 2pp 26228 229 24X Fiche 50-312,84/08/16,8408240112

- 8408200275 Generic Ltr 84-20 tu all licensees of opciating reactors & applicants for DLs re-scheduling guidance for licensee submittals or reloads that involve unreviewed safety questions Svc list end.
  EISENHUT D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X
  Fiche 50-000.84/08/20.8498200275
- B408270041 Notifies that response to NRC 840731 ltr requesting adding the neutron desinetry for surveillance capsule program will be submitted by 841001 ROCRIGUEZ.R J Sacramento Municipal Utility District 84/08/20 STOLZ.J F Operating Reactors Branch 4 1p 26247 068 24X Fiche 50-312.84/08/20.8408270061
- B40B310245 Application for Amerid 100 to License DPR-54, revising Tech Specs re instrument surveillance requirements for testing high-range noble gas effluent monitors & main steam line radiation monitors Supporting dorumentation encl RODRIGUEZ, R J Sacramento Municipal Utility District B4/0B/21 EISENHUT, D G Division of Licensing 2pp 26319 252 24X Fiche 50-312, B4/0B/21, B408310245
- --B408310246 Proposed Tech Specs revising instrument surveillance requirements for testing high-range noble gas effluent monitors " main steam line radiation monitors " Scramento Municipal Utility District B4/08/21 2pp 26319 254 24X Fiche 50-312.84/08/21.8408310245
- 840827040; Requests extension for implementation of NUREG-0737, Item III D 3 4 re control room habitability Existing single train control room HVAC being replaced w/redundant two train HVAC sys Fee paid RDDRIGUEZ.R J Sairamento Nunicipal Utility District 84/08/22 STOLZ.J F Operating Reactors Brench 4 2pp 26238 146 24X Fiche 50-312.84/08/22.8408270401
- 8408310113 Forwards correct fee for proposed Amend 109 per 840620 application Refund of fee sent w/proposed Amend 109 application expected.per 840820 telcon RODRIGUEZ.R J Sacramento Municipal Utility District 84/08/22 TREMPER.L License Fee Management Branch ip 26322 114 24) Fiche 50-312.84/08/22.8408310113 84/08/22
- 8408280240 Requests reinstatement of Amend 36 re gaseous effluent release point for niscellaneous water evaporator, inadvertently deleted from License DPR-54 on 840222 Safety evaluation to no significant hazards evaluation encl COLOMBO, R W Sacramento Municipal Utility District 84/08/23 DEAGAZIO, A Office of Nuclear Reactor Regulation, Director 3p 26279 180 24X Fithe 50-312,84/08/23,8408280240
- G Inspection reports, IE Bulletins & correspondence
- 8408090986 Forwards IE Insp Rept 50-312/84-16 on 840424-25 No noncompliance noted
  WENSLAMSKI,F A Region 5, Diffice of Director 84/07/2
  RODRIGUEZ.R J Sacramento Municipal Utility District
  25992 218 24X Fiche 50-312,84/07/23,8408090086 84/07/23
- --8408090091 IC Insp Rept 50-312/84-16 on 840424-25 No noncompliance noted Major areas inspected environ samples for NRC independent verification HAMADA. 0, NORTH, H. VUHAS. 0 Region 5, Office of Director 84/07/20 7pp 25792 220 24X Fiche 50-312.84/07/23,8408090086
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture NO/200229 IE Info Notice 84-57, "Uperating Experience re Moisture
  Intrusion in Safety-Related Electrical Equipment at
  Commercial Power Plants " Svc list encl
  JDRDAN,C L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/07/27 Consolidated Edison Co of New
  York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407850229
- B408040011 Responds to IE Bulletin 83-03. "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators " No check valves in flow path of cooling water for diesel generators found RODRIGUEZ, R J Sacramento Municipal Utility District 84/07/30 DEYDUNG.R C Director's Office, Office of Inspection and Enforcement ip 25933 184 24X Fiche 50-312.84/07/30.8408069011
- 8408230078 Forwards IE Insp Rept 50-312/84-08 on 840821-25 No violations noted Hatters re post-accident sampling program & offsite dose projection errors unresolved ScarRMO, R A Division of Radiological Safety & Safeguards Program 84/07/30 RDDRIGUEZ.R J Sacramento Municipal Utility District 3pp 26213 159 24% Fiche 50-312,84/07/30,8408230078
- --8408230087 IE Insp Rept 50-312/84-08 on 840521-29 No violations or deviations noted Major areas inspected unresolved items (NURES-0/37.II I 3 re post-accident sampling sys) & offsite dose calculation code errors NORTI, N S . YUHAS. & P Region 5. Office of Director 84/07/06 14pp 26213 161 24% Fiche 50-312,84/07/30,8408230078

- 8408300483 Forwards Emergency Freparedness Insp Rept 50-312/84-11 or 840618-22 \* notice of violation 96408708 D Region 5. Office of Director 84/08/02 RODRIGUEZ/R J Sacramento Hunicipal Utility District 2pp 26314 015 24X Fiche 50-312,84/08/02,8408300483
- --8408300478 Notice of violation from insp on 840618-22 SCHUSTER,M D. Region 5. Office of Director 84/08/02 2pg 26314-017 24x Fiche 50-312.84/08/02.8408300483
- --8408300504 Emergency Preparedness Insp Rept 50-312/84-11 on 840618-22 Violations noted Parlure to provide initial emergency preparedness training to two newly appointed shift supervisors to inadequate meteorological program FISH.R F PRENDERGAST, N., SCHUSTER, M.D. Region 5, Office of Director 84/08/02 12pg 26314 019 24x Fiche 50-312,84/08/02,8408300483
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN, L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 24069 001 24% Fiche 50-000,84/08/06,8408010333
- 8408010337 [E info Notice 84-60. "Failure of Air Purifying Respirator Pilters to Meet Efficiency Requirement " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PMR Refueling Cavity " Svc list encl JDRDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fiche 50-000.84/08/08.8408070120
- 8408300110 Forwards Insp Rept 50-312/84-13 on 840625-29 & notice of violation BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 84/08/08 RDDRIQUEZ.R J Sacramento Municipal Utility District 2pp 26308 076 24X Fiche 50-312.84/08/08.8408300110
- --8408300114 Notice of violation from insp on 840625-29 YDUNG.T Region 3 Office of Director 84/08/08 2pp 26308 078 24X fiche 50-312,84/08/08,8408300110
- --8408300133 Insp Rept 50-312/84-13 on 840625-29 Violation noted records unavailable re storage & protection of motor control ctrs & unauthorized inspector performed insp on safety-related items in diesel generator bldg gurbuin. J F. Youno. 7 Region 5. Office of Director 84/08/07 6pp 26308 080 24% Fiche 50-312.84/08/08.8408300110
- 8408070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list enc! GRACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070374
- 8408200339 Responds to NRC 840713 ltr re violations noted in IE Insp Rept 50-312/84-02 Corrective actions personnel instructed to perform calibr at plus or minus 2% deviation RODRIGUEZ:R J Sacramento Municipal Utility District 84/08/10 MARTIN.J B Region 5. Office of Director 4pp 26132 352 24X Fichs 50-312,84/08/10.8408200339
- 8408300248 Forwards Insp Rept 50-312/84-19 on 840418-0720 & notice of vibilation
  BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 84/08/10 ROBRIQUEZ, R Sacramento Municipal Utility District 2pp 24307 014 24X Fiche 50-312,84/08/10,8408300248
- --8408300250 Notice of violation from insp on 840618-0720 DDDD9,R T Region 5, Office of Director 84/08/10 2pp 24307 018 24% Fiche 50-312,84/08/10,8408300248
- --8408390254 Insp Rept 50-312/84-15 on 840648-0720 Noncompliance noted design calculation for auxiliary feedwater orifice plates not subj to calculation checking, review & approval process ECKHARDT.J H. PEREZ.Q P., MYERS.C J Region 5, Dffice of Director 84/08/10 8pp 26307 020 24X Fiche 50-312,84/08/10,8408300248
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Bvc list encl
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000.84/08/13.8408100009

- 8408170362 Responds to recent telcon releffect of differing steam generator level setpoints on results of main steam line break scenario in FSAR, in connection w/fE Bulletin 80-04 RODRIGUEZ,R J Sacramento Municipal Utility 7istrict 84/08/14 870LZ,J F Operating Reactors Branch 4 ip 26112 397 24% Fiche 50-312,84/08/14,8408170362
- 840B10003B (E Info Notice 84-54, "BWR HPC| Initiation Seal-In & Indication " Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26178 093 24% Fiche 50-000,84/08/15,8408100038
- 8408100021 IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consulidated Edison Co. of New York, Inc. 118pp 26198 001 24X Fiche 50-000.84/08/16,8408100021
- 8408100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JDRDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 001 24X Fiche 50-000.84/08/17,8408100055
- 8408140208 IE Info Notice 84-67. "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000.84/08/17,8408140208
- 8408210142 IE Infg Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York. Inc 115pp 26329 008 24X Fiche 50-000:84/08/21,8408210142
- S Reportable occurrences, LERs & related correspondence
- 8405270062 Forwards "Investigation of Types AF & AE Piston Bkirts "
  Rept supercedes 840227 submittal
  RAY.C L 101 (Transamorica Deleval, Inc.) Owners Oroup 84/05/24
  BENTON, HR Office of Nuclear Reactor Regulation, Director 2pp
  24690 045 24X Fiche 50-000,84/05/24.8405270062
- --8405270075 "Investigation of Types AF & AE Piston Bkirts," \* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp 24x Tiche 50-00.084/05/24,8405270062
- B405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shorehan & Grand Gulf Nuclear Power Stations" RAY, C L TDI (Transamerica Delaval, Inc.) Owners Group 84/05/24 DENTUN, H R Office of Nuclear Reactor Regulation, Director 2pp 24692 090 24X Fichs 50-000.84/05/24,8405290179
- 8408060409 Forwards repts received by BNML & consultants directly from FAAA & TDI dumers Group at 840622 meeting Draft "Overview of Repts, Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
  ALZHEIMER, J Battelle Memorial Institute, Pacific Northwest
  Laboratories 84/06/28 MILLER, M Division of Licensing 138pp
  25926 173 24% Fiche 30-000,84/06/28,8408060405
- 8408D&0050 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Generator Owners Group 840822 meeting RAY.C L TDI (Transsamerica Delaval, Inc.) Edwards Group 84/07/10 BERLINGER.C Director's Office, Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50-000,84/07/10, 84080&0050
- 8408310196 LER 84-018-01 on 840601, transient occurred on main feedwater loop B due to spurious closure of main feedwater startup & block valves Caused by intermittent short of pressure switches Buitches replaced W/840710 ltr COLOMBO.R W . RODRIGUEZ.R J Bacramento Municipal Utility District 84/07/10 ARTIN.J B Region 5, Office of Director 3pp 26318 289 24% Fiche 50-312.84/07/10.8408310196
- B408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Miring & Termination Qualification Review" Addl topies sent to BNAM. RAY.C L TDI (Transamerica Delaval. Inc.) Guners Group 84/07/27 DENTUN.H R Office of Nuclear Reactor Regulation, Director 2pp 25732 137 24X Fiche 50-000;84/07/27,8408060102
- --8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review "

  \* Stone L Webster Engineering Corp 84/07/31 36pp 25932 139 24X Fiche 50-000:84/07/27.8408060102

- 8408060123 PhO-V-84-045 on 810710, licensee began evaporating highly purified liquid raduaste to dryness, resulting in airboine release of radioactive tritjum Approx 5, 500 gallons water processed resulting in release of 1 39 Ci to atmosphere VUHAS, C. MENSLAUSKI, F. Region 5, 0ffice of Director 84/07/27 lp 25933 193 24x Fiche 50-312 84/07/27, 8408060123
- B40B040154 PRQ-V-84-044 on 840723, licensee learned that highly radioactive 2 x 0 6 x 0 i-inch metal object removed from steam generator B primary side inlet Soutce of metal or extent of personnel exposures not identified YUHAS,G., HENSLAHSKI,F. Region 5. Office of Director 84/07/27 bp 25932 198 24x Fiche 30-312.84/07/27,8408040156
- B40B070416 PNO-V-84-047 nn B40731. temporary work stoppage occurred following misunderstanding re alleged contamination of const workers on B40730 No contamination found on workers or vehicles Issue resolved by contractor NORTH-H , HENSLAMBKI.F Region 5. Office of Director 64/07/31 p 25942 052 24X Fiche 50-312.84/07/31.8408070416
- 84080&0324 Forwards "Design Review of Elliott Model ASG Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Bets " RAY.C L TDI (Transamerica Delaval: Inc.) Owners Group 84/08/01
- Bets "RAY.C L TOI (Transamerica Delaval, Inc.) Quiners Group 84/08/0; DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 25727 064 24% Fiche 50-000,84/08/01,8408060324
- 8408140346 PNO-V-B4-048 during present outage for steam generator tube plugging repairs, two swagelok fitting loaks identified in process piping installed during 1983 outage All swagelok Fittings undergoing insp Outage extended MYERS, C., ECKHAROT, J. Region 5, Office of Director 84/08/08 ip 26042 325 24% Fithe 50-312.84/08/08,8408140346
- 840B160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI BSRV-16 Diesel Engines "
  RAY: C. L. TDI (Transamerica Delavai: Inc.) Clumers Group 84/08/10 DENTON: HR Office of Nuclear Reactor Regulation. Director 2pp 26091 147 24% Fiche 50-000-84/08/10.8408160394
- --8408160403 "Design Revieu of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines " \* Fellure Analysis Associates FAAA-84-6-52 84/08/31 44pp 26091 149 24X Fiche 50-000,84/08/10.8408160394
- 8408240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program testing & insp. maint & surveillance & sets farth requirements for operation prior to completion of program plan EISENHUT, D @ Division of Licensing 84/08/13 @EDRGE, J B TDI (Transamerica Delaval, Inc.) Dumers Group 1p 26255 194 24X Fiche 50-000.84/08/13.8408/24015
- -8408240157 Safety evaluation of TDI Duners Group program plan Hased on BNML evaluation plan incorporates essential elements needed to resolve outstanding tencerns re reliability of TDI engines for nuclear svc w NRC No Detailed Affiliation Given 84/08/13 21pp 26255 195 24% Fiche 30-000,84/08/13.8408240115
- 408160395 Forwards "Design Review of Elliott Model 900 Turbockarger Used on TDI DER-48 & DSRV-16 Emergency Diesel Generator Bets," representing final GA verified rept Addl copy Forwarded to ENILL per NRC request RAY, C. L. TDI (Transamerica Delaval, Inc.) Guners Group 84/08/14 DENTON, H. D. Office of Nuclear Reactor Rogulation, Director 2pp 24088 143 24% Fiche 50-000,84/08/14,8408160375
- -B408160397 "Design Revieu of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Energency Diesel Generator Bets "
  Fallure Analysis Associates FAAA-84-5-7 B4/07/31 61pp 26088 165 24% Fiche 50-000, B4/08/14, B408160395
- |408230077 Summary of 840807 operating reactor events meeting re occurrences since 840719 meeting List of attendees, significant elements & status of previous assignments end CRUTCHFIELD.D Assistant Director for Bafety Assessment 84/09/16 EISENNUT.D C Division of Licensing 20pp 26233 249 24X Fiche 50-000.84/08/16.8498230077
- |408240111 Special Rept 84-03 on 840709, five identically defective switch yous found on Mestinghouse Type M9-6 relay Caused by excessively sharp bend radius on forming die All defective units replaced RODRIQUEZ.R J Sacramento Municipal Utility Bistrict 84/08/23 HARTIN.J B Region 5, Office of Director 2pp 26228 231 24x Fiche 50-312.84/08/23.8408240111

- B4082901/9 Firmards response to 840/23 request for add1 info on repts submitted by TD1 biese) Generator Owners Group RAY.C L TD1 (Transamerica Delaval Inc.) Dumers Group 84/08/23 HEMLINGER.C Office of Nuclear Reactor Pegulation, Director 12pp 26289 221 24% Fiche 50-000.84/08/23 84082901/9
- 8408290286 Forwards responses to 840131 questions re TD1 diesel generaturs kensining responses will be delayed until completion of TD1 Owners Group site-Specific BR/GR repts. Phase I disassembly / insp.Phase 2 testing 5 Phase 3 insp. RDBR (GUEZ/R J Sacramento Municipal Utility District 84/08/24 ST012.3 F Operating Reactions Branch 4 15pp 26291 161 24x Fiche 50 312-84/08/24-8408290288
- V Operator Cianinations
- 8408060006 Provides updata rept on plagiess of training blexam of candidates for operators license per 840600 commitment Sixteen add licenses issued at end of June RODRIGUEZ.R J Sacramento Municipal Utility District 84/07/26 STOLZ, J & Operating Reactors Blanch 4 2pp 25922 015 24X Fishe 50-012.84/07/26.8408060000
- DDCKET 50-713 ARKANBAS NUCLEAR ONE. UNIT 1

  F Security, medical, emergency & fire protection plans
- B40B14D49B Forwards IE Insp Repts 50-313/84-20 & 50-36B/84-20 an B40619-22 Na violations or deviations noted HUNTER D & Region 4. Office of Director B4/07/23 GRIFFIN, J M Arkansas Power & Light Co. 25p. 2610/ 318 24X Fiche 50-313/84/0//23/8408160498
- 8408080441 Forwards request for add1 into te procedures generation package for emergency operating procedures Response requested within 30 days of 1tr receipt RIVENBARK,0 k Upperating Reactors Branch 4 84/07/26 GRIFFIN,J M Arkansas Power 7 Light Co 3pp 25977 174 24% Fiche 50-313,84/07/26,8408080441
- 8408280184 Forwards "Reanalysis Against 100FR30, App R. Sections III G.J & O." por B30,328 % 0712 requests for exemption from 100FR30 48(c) schedulo for barriers, penetrations & suppression/detection sys for approx 1 y MARSIALL, J. R. Arkansas Power & Light Co. B4708/15 STOLZ, J.F. Operating Reactors Branch 4 MILLER, J. R. Operating Reactors Branch J. Pap. 26287 144 24X Fiche 50 313,84/08/15,8408280184
- --8408280108 "Reanalysia Against 1017R50, App R. Sections 111 0. J & Q "
  \* Arkansas Power & Light Co 84/08/15 120pp 26287 146 24x
  Fiche 50-313, 84/08/15, 8408200184
- B40B230401 Revised Emergency Procedures 1903 72 re St Marys Hosp, 1903 73 re Millard-Henry clinic & 1903 74 re Pope County ambulance svc \* Arkansas Power & Light Co 84/08/16 7pp 26206 001 24X Ciche 30-313,84/08/16 000230401
- 8408230417 Deletion of Nev O to Procedure 1903 34, "Administration of Potossium Todide"

  \* Arkansas Power & Light Co 84708/29 3pp 26204 011 24X Fiche 50 313,84708/29,8408230417
- P Operating license stage documents & correspondence
- 8408070389 Forwards "Extension of Retainer Lifetime to Four Cycles," for Ocanes.Unit 3 w/results of exams of two retainers after three cycles Approval of Four-cycle rotainer usage requested before Dec 1984

  TAYLOR, J H Sabcock & Milcox Co E4/07/24 STOLZ, J F Operating Reactors Branch 4 ip 25745 292 24x Fiche 50-000, 84/07/24, 84008070389
- B408090010 Forwards SER based on util responses to B10210 Generic Ltr B1-14, "Seismic Gwalification of Auxiliary Feedwater Sys "
  Cmergency feedwater sys acceptable following upgrade mod RIVENDARK, G W Operating Reactors Branch 4 84/07/26 GRIFFIN, J M Arkaneas Power & Light Co 2pp 25791 253 24%
  Fiche 50-313,64/07/26,840809/0010

1

- --8408090()13 SER re seismic qualification of emergency feedwater (EFW) sys EFW sys will have surricient capability to withstand SSE & accomplish sarety function following upgrade mod Technical evaluation rept enci

  # Office of Nuclear Reactor Regulation, Director 84/07/26 9pp 25971 295 24% Fiche 50-313,84/07/26,8408090010
- 8408080152 Forwards Amend 83 to License DPR-51 & safety evaluation Amend modifies pressure-temp limit curves for hydrostatic testinomal heatup? normal cooldown RIVENBARK, G W Dyerating Keactors Blanch 4 84/07/27 GRIFFIN, J M Arkansas Power & Light Co Top 25979 011 24x Fiche 50-313,84/07/27,8408080152
- --8408080158 Amend 83 to License DPR-51, modifying pressure-temp limit curves for hydrostatic test.normal heatup & normal cooldown RIVENBARK.G W Operating Reactors Branch 4 84/07/27 9pp 25979 014 24X Fiche 50-313.84/07/27.8408080152
- --8408080165 Safety evaluation supporting Amend 83 to License OPR-51 \* Office of Nuclear Reactor Regulation, Director 84/07/27 4pp 25979 023 24% Fiche 50-313,84/07/27,8408080152
- 8408080288 Summary of 840712 meeting w/8tW Dwners Group re non-nuclear instrumentation sys status Attendance list & viewgraphs encl
  KADAMBI.P Operating Reactors Branch 4 84/07/27 Operating Reactors Branch 4 84/07/27 Operating Reactors Branch 4 84/07/27 Operating Reactors Branch 4 84/08/20 Operating Reactor
- B408070483 Forwards Rev 6 to QA manual operations Return receipt requested MARSHALL, J Arkansas Poyot : Light Co 84/07/31 Record Services Branch (Dosument Control Desk) ip 25941 215 24x Fiche 50-313,84/07/31,8408070483
- --84080/0485 Rev 6 to GA manual ~ operations \* Arkansas Power & Light Co 84/05/30 158pp 25941 216 24% Fiche 50-313,84/07/31,8408070483
- 84080701iO Generic Lti 84-19 to all licensees of operating reactors, applicants for OLs \*\*, holders of CPs re availability of Suppl 1 to NUREO-0933. "Prioritization of Generic Safety Issues "Svc list encl EISENHUT.D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24% Fiche 50-000.84/08/06.8408070110
- 8408140335 Forwards corrected cover sheets for Copies 1-6 of Rev 6 to "GA Manual Operations" MARSMALL, J. R. Arkansas Power & Light Co. 84/08/06 Record Services Branch (Document Control Desk) 7pp 26041 037 24X Fiche 50-313,84/08/06,8408140359
- 8408140403 Forwards revised proposed resolutions of environ qualification SER deficiencies, per NRC 840426 comments Info documents results of listed issues not directly related to equipment, per 840426 meeting MARSHALL.J R Arkansas Power & Light Co 84/08/06 STQL7.J F Operating Reactors Branch 4 160pp 26050 162 24X Fiche 90-313.84/08/06.8408140403
- B40B140427 Forwards "Analyses of Capsule AN1-A, Arkansas Power & Light Co. Arkansas Nuclear One. Unit 1, Reactor Vessel Matl Burveillance Program "
  MARSHALL. J.R. Arkansas Power & Light Co. B4/08/06 STDL2. J.F. Operating Reactors Branch 4 1p 26049 301 24X Fiche 50-313.84/08/06.840B140427
- --B408140433 "Analyses of Capsule ANI-A.Arkansas Power & Light Co. Arkansas Nuclear One, Unit 1, Reactor Vessel Matl Surveillance Program " LOHE, A L., AADLAND, J D., CULLINS.L L. Babcuck & Wilcox Co BAM-1836 84/07/31 93pp 26049 302 24X fiche 50-313.84/08/06. 8408140429
- B408170061 Forwards corrected coversheet for Rev 6 to 0A manual operations Revised coversheet reflects Control Copy 7 MARBHALL, J R Arkansas Power & Light Co 84/08/06 ANKRUM, G T 9/8 Branch 4pp 26117 018 24X Fiche 30-313.84/08/06,8408170041
- 8408200303 Informs that response to Recommendation GL-2 re inadvertent closure to condensate storage tank isolation valve (NUREG-0737, Item [I E i 1] will be delayed until 840824 due to outage preparation work MARSHALL, J R Arkansas Power & Light Co 84/08/10 STOLZ, J F Derating Reactors Branch 4 ip 26133 358 24% Fiche 50-313,84/08/10,8408200303

- 840B150180 Application to amend License DPR-51, modifying designation of areas in steam generator imperfections found & allowing sleeving of tubes Proprietary affidavit \$ BAW-1823P, "Onco-Through Steam " encl Fee encl GRIFFIN.J M Arkansas Power & Light Co B4/08/13 STOLZ, JF Operating Reactors Branch 4 6pp 26067 132 24X Fiche 50-313.84/08/13.4408(50)80
- --8408150184 Proposed changes to Tech Spec Section 4 18 modifying designation of special areas in steam generator imperfections previously found % allowing sleeving of 10 steam generator tubes as part of demonstration program \* Arkansas Power % Light Co 84/08/13 20pp 26067 138 24X Fiche 50-313, 84/08/13.8408150180
- 8408220313 Application for amend to License DPR-51-revising Tech Specs to require add1 restrictions? testing of low temp overpressure protection sys GRIFFIN.J M Arkansas Power & Light Co 84/08/15 STOLZ, J F Operating Reactors Branch 4 4pp 26189 338 24X Fiche 50-313.84/08/15.8408220313
- --8408220316 Proposed Tech Specs changes requiring add1 restrictions to testing of low temp overpressure protection sys

  \* Arkansas Power & Light Co 84/08/15 5pp 26189 341 24X
  Fiche 50-313,84/08/15.8408220313
- B408200275 Generic Ltr B4-20 to all licensees of operating reactors & applicants for QLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Swc list encl EISENHUT.D G Division of Licensing B4/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000.84/08/20.8408200275
- 8408310831 Forwards revs to proposed Tech Spec changes for NUREG-0737 items to containment radiation monitors & post-accident sampling.per Generic Ltr 83-37 GRIFFIN.J M Arkansas Power & Light Co 84/08/22 STOLZ.J F Operating Reactors Branch 4 12pp 26320 314 24X Fichs 50-313,84/08/22.8408310231
- O Inspection reports: IE Bulletins & correspondence
- 8408150372 Forwards IE Insp Repts 50-313/84-11 & 50-368/84-11 on 840326-29 & notice of violation One unresolved item re maint program identified in Paragraph 2 of insp rept should be addressed in detail JCHNSON. E.H. Region 4, Office of Director 84/05/16 GRIFFIN, J. M. Arkansas Power & Light Co. 2pp. 26075 181 24% Fiche 50-313,84/05/16,8408150372
- --8408150373 Notice of violation from insp on 840326-30 \* Region 4. Office of Director 84/05/16 2pp 26075 183 24X Fiche 50-313,84/05/16,8408150372
- --8408150375 IE Insp Repts 50-313/84-11 & 50-368/84-11 on 840326-30 Violations noted failure to document & follow procedures for maint of MSIVs & HPCI valves BDARDMAN.J R., JGHN9DN,W D., JAUDDN,J P. Region 4. Office of Director 84/05/16 App 26075 185 24X Fiche 50-313,84/05/16,8408150372
- 8408090150 Forwards (E Insp Repts 50-313/84-18 & 50-368/84-18 on 840801-30 No violations or deviations identified JOHNBON,E H Region 4, Office of Director 84/07/11 GRIFFIN,J M Arkansas Power & Light Co 2pp 25993 178 24X Ficke 50-313,84/07/11.8408090150
- --8408090160 IE Insp Repts 50-313/84-18 & 50-368/84-18 on 840601-30 No violations identified Hajor areas inspected maint, surveillance, operational safety verification & followup on IE bulleting & Generic Ltr 83-28
  JOHNSON, W.D., HARRELL, P. H., MARTIN, L.E., Region 4, Office of Director 84/07/11 11pp 25993 180 24X Fiche 50-313,84/07/11, 8400090150
- 8408070121 Forwards IE Insp Repts 50-313/83-35 & 50-368/83-35 on 831203-08 & notice of violation W/o notice of violation HUNTER: D.R. Region 4. Office of Director 84/07/17 @RIFFIN, J.M. Arkansas Pawer & Light Co. 2pp 25773 148 24X Fiche 50-313,84/07/17,8408090;21
- ---B408090i30 IE Insp Repts 50-313/83-35 & 50-368/93-35 on 831205-08
  Nancompliance noted failure to verify that matls conform to
  procurement documents
  ELLERSHAW, L E. JOHNSON, W D., BARNES, I Region 4, Office of
  Director 84/02/21 9pp 25993 150 24X Fiche 50-313,84/07/17,
  B408090121

- B408150312 Ack receipt of 840615 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/84-11 & 50-364/84-11 Future insp will determine if corrective actions achieve compliance actions achieve compliance JUHNSON,E H. Region 4, Office of Director B4/07/23 GRIFFIN.J M Arkansas Power & Light Co. ip 26074 350 24X Fiche 50-313,84/07/23,8408150312
- --B408190317 Responds to NRC 840516 ltr re violations noted in IE Insp. Repts 30-312/84-11 & 50-368/84-11 Requests add) time to complete response to items noted in rept Response will be forwarded by 840627 MARSHALL.JR Arkansas Power & Light Co. 84/06/15 DENISE/R P. Division of Resident, Reactor Project & Engineering Programs 1p. 26074 351 24X Fiche 50-313.84/07/23.8408150312
- 8408160498 Forwards IE Insp Repts 50-313/84-20 & 50-368/84-20 on B40619-22 No violations or deviations noted HUNTER, D.R. Region 4, Defice of Director 84/07/23 GRIFFIN, J.M. Arkansas Power & Light Co. 2pp. 26107 318 24X Fiche 50-313.84/07/23.8408160498
- --B408160504 IE Insp Repts 50-313/B4-20 & 50-368/B4-20 on 840619-22 No violations or deviations noted Major areas inspected security program audit & physical barriers Details withheld (ref 10CFR73 21)

  EVANB.C A , HULL,R E , MARTIN.L E Region 4, Office of Director B4/07/23 (p 26107 320 24X Fiche 50-313,84/07/23,840B160498
- 8408070022 Discusses IE insp on 831205-08 & forwards notice of violation & proposed imposition of civil penalty Util failed to apply controls for procurement & installation of safety-related fasteness.per App D to 100FR80 N/o encl COLLINS.J T Region 4. Office of Director 84/07/25 ORIFFIN.J M Arkansas Power & Light Co 5pp 25992 089 24X Fiche 50-313.84/07/25.8408090022
- 8407250229 iC Info Notice 84-57, "Operating Experience re Moisture Intrusion in Bafety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JURDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc. 119pp 25865-047 24X Fiche 50-000.84/07/27, 8407250229
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list enc! JORDAN, E. L. Davision of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26048 001 24% Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list entl JORDAN, E. L. Division of Emergency Preparedness & Engineering Respinse (Post 830103) 84/08/06 Consolidated Edison Co. of New York: (Inc. 123pp 24067 158 24% Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Info Notice 84-61. "Oversposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc. 120pp 26189 118 24X Fiche 50-000,84/08/08,8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list enc!

  ORACE, J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125p 26130 001 24X Fiche 30-000 84/08/10 8408070376
- 840B100009 JE Info Notice 84-63, "Defective RHR Replacement Piping"
  Svc list encl
  JORDAN, E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc. 119pp 26197 218 24X Fiche 50-000,84/08/13,840B100009
- B40B10003B IC Info Notice 84-64. "BWR RPCI Initiation Beal-In & Indication " Byc list Bnc!
  JURDAN,E L. Division of Emergency Proparedness & Engineering
  Response (Post 830103) 84/0B/15 Consolidated Edison Co. of New
  York, Inc. 104pp 2619B 090 24X Fiche 50-000.84/0B/15,840B10003B
- 8408100021 IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Hasponse (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. (18pp. 26198 001 24X Fiche 50-000,84/08/16,8408100021
- 8408108055 IE Info Notice 84-65. "Undetected Unavailability of Turbing-Driven Auxiliary Feedwater Train " Svc list oncl. JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 630103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 CO1 24X Fiche 50-000,84/08/17,8408100035

- 8408140208 IE Info Notice 84-67. "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN,C L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/09/17 Consolidated Edison Co
- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24% Fiche 30-000.84/08/21,8408210142
- B408300154 Requests withdrawal of B40725 notice of violation & proposed imposition of civil penalty Corrective actions initiated prior to enforcement action, including augmenting GA staff, retraining GC staff & increasing vendor surveys MARSHALL.UR Arkansas Power & Light Co 84/08/24 DEYOUNG, R C Director's Office Office of Inspection and Enforcement 3pp 24304 257 24X Fight 50-313,84/08/24,8408300154
- --B40B3CO160 Licensee response to B40725 notice of violation Violation admitted & corrective actions outlined # Commissioners B4/0B/24 12pp 26304 260 24X Fiche 50-313,84/0B/24,840B300154
- --8408300166 Licensee ansuer protesting 840725 civil penalty Notice of violation fails to allow for corrective actions initiated prior to enforcement action # Commissioners 84/08/24 10pp 26304 272 24x Fiche 50-313,84/08/24,8408300154
- S Reportable occurrences, LERs & related correspondence
- 8408130170 LER 80-040/79X-1 on 801001. Emergency hatch local leak rate test connections found uncapped causing outer door to be bypassed by 3/4-inch connection Cause not stated Caps replaced & test procedures revised W/840803 ltr RCGERB.P MARSHALL.J R Arkansas Power & Light Co 84/08/03 3pp 2608 271 24% Fiche 50-313,84/08/03,8408130190
- 8408130326 LER 80-014/03X-1 on 800415 fire & smoke detector testing not completed within surveillance interval due to high radiation level Detectors tested at cold shutdown Tech Spec 4 19 revised W/840803 ltr RDGERS, P. MARSHALL, J. R. Arkansas Power & Light Co. 84/08/03 3pp 24006-331 24X Fiche 50-313,84/08/03,8408130326
- 8408240053 LER 82-017/03X-1 on 820714.while performing reactor bldg isolation & valve strole test.control valve 3807 closed & failed to open due to circuit breaker trip Cause undetermined No action taken 4/840810 ltr ROGERS, P. MARSHALL, J.R. Arkansas Power & Light Co. 82/07/14 2pp 26234 358 24X Fiche 50-313,84/08/10,8408240053
- DUCKET 80-319 DONALD C COOK NUCLEAR POWER PLANT, UNIT 1

  F Security, medical, emergency & fire protection plans
- E408060118 Forwards changes to modified amended security plan Changes withheld (ref 10CFR73 21)
  ALEXICH M P Indiana & Michigan Electric Co 84/07/17
  KEPPLER, J Q Region 3, Office of Director 1p 25936 029 24X
  Fiche 50-315
- 8408060348 Forwards revised Page B-14 to modified amended security plan.per 10CFR50 54(p) Page withheld (ref 10CFR73 21) ALCXICH.M P Indiana & Michigan Electric Co 84/07/19 KEPPLER.J O Region 3, Office of Director 1p 25936 096 24X Ficha 50-315,84/07/19,8408060348
- 8408020020 Ack receipt of 840719 itr re formal page changes to modified amended security plan Changes will be included as gart of approved plan Future changes whould ref 10CFR73 21 when requesting withhalding AXEL80N.N L. Region 3. Office of Director 84/07/26 ALEXICH.M P Indiana & Michigan Electric Co 2pp 25883 148 24X Fiche 50-315.84/07/26.8408020020
- 8408070060 Advises that 840719 changes to physical security plan consistent u/provisions of IOCTR50, 54(p) & acceptable AXELBON.W L. Region 3. Office of Director 84/08/01 ALEXICH.M P Indiana & Michigan Electric Co ALEXICH.M P American Electric Power Co . Inc. 2pp 25949 335 24X Fiche 50-315,84/08/01,84080/0660
- 8408070272 Rev 3 to Procedure PMP 2080 EPP 012, "Initial Offsite Notification" KRAVSE.D. Indiana & Michigan Electric Co 84/08/01 App 25949 203 24X Fiche 50-315.84/08/01.8408070272

- 8408070307 Rev & to Emergency Plan Implementing Procedure PMP 2080 EPP 008. "Initiating Hanning of Emergency Response Facilities & Calling Off-Duty Plant Personnel" • Indiana & Michigan Electric Co 84/08/01 13pp 25947 328 24x Fiche 50-315.84/08/01.8408070307
- 840B100094 Forwards responses to NRC 84050B request for add1 info redetailed control room design review (DCRDR) Encls include functions of DCRDR teams, control room instrumentation & emergency response capability integration plan ALEXICH, M P Indiana & Michigan Electric Co 84/08/06 DENTON, H Office of Nuclear Reactor Regulation, Director 26pp 25988 204 24X Fiche 50-315,84/08/06,8408100094
- --8405010079 Summarizes 840329 meeting w/Westinghouse Owners Oroup re task analysis requirements of Suppl 1 to NUREG-0737 (Generic Ltr 82-33) CLAYTON.H B Procedures & Systems Review Branch 84/04/05 ZIEMANN,D L Procedures & Systems Review Branch 17pp 2598B 230 24X Fiche 50-315.84/08/06.8408100094
- B40Bi30J21 Revs to Energency Plan Implementing Procedures PMP 2081 EPP 021. "Activation & Operation of Operations Staging Area & Personnel Accountability" & PMP 2081 EPP 004. "Protective Action Guides (PAGs) & Protective Actions " \* Indiana & Michigan Ejectric Co 84/08/07 24pp 26006 001 24X Fiche 50-315.84/08/07.8408130321
- 8408170322 Forwards Suppl 2 to "App R Evaluation of Auxiliary Bldg HVAC Duct Penetration & Containment Seismic Gaps," providing justification for technical exemptions requested in 840615 ltr
  ALEXICH, M P Indiana & Michigan Electric Co 84/08/13 DENTUN, H R
  Dffice of Nuclear Reactor Regulation, Director 2pp 26113 001
  24X Fiche 50-315,84/08/13,8408170322
- --8408170327 Suppl 2 to "App R Evaluation of Auxiliary Bldg HVAC Duct Penetration & Containment Seismic Caps " # Engineering Planning & Management, Inc 84/08/31 52pp 26113 003 24% Fiche 50-313.84/08/13.8408170322
- 8408210196 Rev 1 to Procedure PMP 2081 EPP 014, "Offsite Dase Assessments" \* Indiana & Michigan Electric Co 84/08/15 43pp 26147 078 24X Fiche 50-315.84/08/15.8408210136
- P Operating license stage documents & correspondence
- 8405160248 Requests that inservice insp/inservice testing second 10-yr internal for both units begin on 840701.1 yr earlier than stated in 840315 ltr.contingent upon acceptance of listed code relief requests HERINO.R F Indiana & Michigan Electric Co 84/05/11 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 24485 069 24X Fiche 50-313,84/05/11.8405160248
- 8408010310 Notification of date & location change for 840815 meeting w/util in Betheads, ND to discuss program for hydrogen control, equipment survivability & containment structural integrity heeting originally scheduled for 840725 WIGOINTON, D L. Operating Reactors Branch 1 84/06/27 VAROA, 8 A Operating Reactors Branch 1 2pp 25872 317 24% Fiche 50-315,84/06/27,8408010310
- 8408060076 Informs of temporary procedural change to ensure that plant operations consistent w/FSAR analysis assumptions for interim period, until proposed Tech Spec change re reactor coolant pump operability at hot zero power approved ALEXICH. M.P. Indiana & Michigan Clectric Co. 84/07/30 DENTON, H.R. Office of Nuclear Reactor Regulation, Director Spp. 35933 125 24X Fiche 30~315,84/07/30,8408060076
- 8408140425 Summary of 840720 meeting w/utils & Westinghouse re containment analysis & superheat effects on environ qualification WigoINTON.D.L. Operating Reactors Branch 1 84/07/30 Operating Reactors Branch 1 4pp 26143 265 24X Fiche 50-000,84/07/30, 8408140425
- 8408160188 Forwards results of review of NUREQ-0737. Item II B 3 open items re post-accident sampling sys Mods will be completed & sys operational by Sept 1984
  ALEXICH, M P Indiana & Michigan Electric Co 84/08/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 26092 036
  24X Fiche 50-315.84/08/02,8408160188
- B40B140164 Responds to 840720 verbal request re effects of superheated steam following postulated main steam line break Util will participate in Hestinghouse Dwners Group activities & involvement expected to suppl internal review ALEXICH.M P Indiana & Michigan Electric Co 84/08/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 26065 001 24X Fiche 50-313,84/08/03,8408140164

- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933. "Prioritization of Generic Safety Issues " Svc list encl EISENHUT, D G Division of Licensing B4/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000,84/08/06.8408070110
- 8408160494 Returns 840718 check which accompanied 840723 application for relief from certain ASME Code requirements Application subj to revised IOCFR170 Requests remission of required fee for application Discussion of fees encl DIGOSIR M License Fee Management Branch 84/08/09 DOLAN, J American Electric Power Service Corp 4pp 26124 337 24X Fiche 50-315,84/08/09.8408160494
- 8408200273 Generic Ltr 84-20 to all licensees of operating reactors & applicants for GLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
  EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276-244 24X
  Fiche 50-000.84/08/20.8408200275
- 8408240188 Forwards status rept on inadequate core cooling instrumentation sys.per B31219 request Rept addresses reactor vessel instrumentation sys.core exit thermocouples. subcooling margin monitor & NUREO-0737. Item II F 2
  ALEXICH.M P Indiama & Michigan Electric Co 84/08/20 DENTON, H R
  Office of Nuclear Reactor Regulation. Director 5pp. 26227 355
  24X Fiche 50-315.84/08/20.8408240188
- B40B230263 Forwards XN-NF-B3-61, "DC Cook Unit 1 LUCA-ECCS Analysis for Extended Exposure" & proprietary XN-NF-B4-25(F), "Machanical Design Rept Suppl for DC Cook Unit 1 Extended Burnup Fuel Assemblies " Proprietary rept withheld CHANDLER, J C Exxon Nuclear Co , Inc (subs of Exxon Corp ) B4/0B/21 DETOIN.H R Defice of Nuclear Reactor Regulation, Director 5pp 26204 028 24% Fiche 50-315.84/0B/21,8408230263
- --B408230266 "DC Cook Unit 1 LOCA-ECCS Analysis for Extended Exposure "
  TAHVILITT, KAYSER.W V. STOUT,R B Exxon Nuclear Co. Inc. (subs
  of Exxon Corp.) XN-NF-83-61 83/08/03 33pp 26204 033 24X
  Fiche 50-315,84/08/21,8408230263
- O Inspection reports: IE Bulletins & correspondence
- B403140248 Requests that inservice insp/inservice testing second i0-yr internal for both units begin on 860701.1 yr earlier than stated in 840315 ltr.contingent upon acceptance of listed code relief requests
  HERING.R F Indiana & Michigan Electric Co 84/05/11 DENTON,H R
  Office of Nuclear Reactor Regulation, Director 2pp 24485 069
  24X Fiche 50-315,84/05/11,8403160248
- 8408230204 Forwards IE Insp Repts 50-315/84-11 & 50-316/84-12 on 840604-08 No moncompliance noted 814FER, W D Region 3. Office of Director 84/07/24 DDLAN, J E American Electric Power Service Corp DDLAN, J E Indiana & Michigan Electric Co 2pp 26214 035 24X Fiche 50-315.84/07/24.8408230204
- --B408230211 IE Insp Repts 50-315/84-11 & 50-316/84-12 on B40604-08 No noncompliance noted Major breas inspected sys walkdown & print verification, surveillance, maint, inservice testing, work controls, callbr & operations review WRIGHT.0 C Region 3, Office of Director 84/07/24 10pp 26214 037 24X Fiche 50-315.84/07/24, B408230204
- 8407250227 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Byo list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consultdated Edison Co. of New York, Inc. 117pp 25865 047 24X Fiche 50-000,84/07/27,8407250227
- 840808084 Submits supplemental response to IE Bulletin 83-07.

  "Apparently Fraudulent Products Bold by Ray Hiller. Inc."

  Piping matts used in fabrication of chemical & vol control

  sups supplied by Ray Miller. Inc.

  ALEXICH.M P Indiana & Michigan Electric Co 84/08/01

  DEYOUNDO, R C Director's Office. Office of Inspection and

  Enforcement Spp 67473 131 24X Fiche 50-315.84/08/01.84080808084
- BAOBO70401 Informs that new sys of acknowledging receipt of litensee correspondence re noncompliance found during inspirately effective 840820 Preprinted form will be used rather than ltr KEPPLER, J G Region 3, Office of Director 84/08/03 Commonwealth Edison Co 3pp 25942 188 24% Fichs 50~000, 84/08/03, 84/08/070401

- 8408010333 IE Info Notice 84 59. "Deliberate Circumventing of Station Health Physics Procedures " Svc list encil JORDAN.R L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc. 122pp. 26068-001 24% Fiche 50-000.84/08/06.8408010333
- 840B010337 IE Info Notice 84-60. "Foolure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Syc list encl JORDAN. R L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York. Inc 123pp 26067 198 24x Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- 8408070374 [E Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl GRACE. J N Division of QA. Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000.84/08/10.8408070376
- 8408100009 IC Info Notice 84-63. "Defective RHR Replacement Piping "
  Svr list encl
  JURRANN,F L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc. 117pp 26197 218 24X Fiche 50-000.84/08/13,8408100009
- B40B300181 Forwards Insp Repts 50-315/84-14 & 50-316/84-16 on 840723-27 No noncompliance noted MALKER, R D Region 3, Diffice of Director 84/08/14 DDLAN, J E American Electric Power Service Corp DDLAN, J E Indiana & Michigan Electric Co 2pp 26313 263 24X Fichs 50-315.84/08/14, 8408300181
- --8408300188 Insp Repts 50-315/84-14 & 50-316/84-16 on 840723-27 No noncompliance or deviations noted Major areas inspected LCMs, startup test results packages. Unit 2. Cycle 4 core power distribution limits & Unit 2. Cycle 5 core reload analysis MRELER.J K. MCCORMICK-DARGE, REYES, L. A. Region 3. Office of Director 84/08/14 App. 26313 265 24% Fiche 50-315, 84/08/14, 8408300181
- 840B10003B IC Info Notice 84-64. "BWR HPCI Initiation Seal-In & Indication "Sec list encl JORDAN, E. E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co. of New York, Inc. 104pp 26198 093 24X Fiche 50-000.84/08/15.8408100038
- 8408100021 IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list sucl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York Inc 186p 26198 001 24X Fiche 50-000.84/08/16.8408100021
- 8408100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Syc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York: Inc. 120pp 26276 001 24X Fiche 50-000-84/08/17, 8408100055
- 8408140208 IC Info Notice 84-67, "Recent Shubber Inservice Testing W/ High Failure Rates " Svc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 122pg 26276 122 24X Fiche 50-000.84/08/17, 8408140208
- 8408210142 IE Info Notice 84-66. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valvos " Svc list encl. JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York: Inc. 115pp 26929 008 24X Fiche 50-000:84/08/21,8408210142
- 8408280147 Discusses 840421 meeting w/util re SALP Repts 30-315/84-08 & 50-316/84-09 for period from Apr 1983 Mar 1984 Summary of meeting, including list of attendees, encl as App A to SALP repts App final step in SALP assessment process KEPFLER. J O Region 3, Office of Director 84/08/23 DDLAN, J E American Electric Power Service Corp DDLAN, J E Indiana & Michigan Electric Co 2pp 26259 078 84X Fiche 50-315.84/08/23,8408280147
- --8408280155 App to SALP Repts 30-315/84-08 & 30-316/84-09 for period from Apr 1783 Mar 1784 Summarizing 840621 meeting & including list of attendees \* Region 3, Office of Director 84/08/23 2pp 26259 080 24X Fichs 50-315,84/08/23,8408280147

- S Reportable accurrences LERs & related correspondence
- 8408080536 LER 84-013-09 on 840706, discovered that fire watch not maintened in area fire retardant matls removed from previously protected conduit containing safety-related cables Fire watch patrol initiated W/840731 ltr STIETZEL.JF Indiana % Michigan Electric Co SMITH.W G Midwest Electric Cooperative 84/07/31 Jpp 25975 310 24X Fiche 50-315, 84/07/31 8408080536
- 840816052/ LER 84 007-01 on 840528 coding error discovered in DETECTOR code analyzing raw flux map data Cause not stated Independent line-by-line review of coding changes will be performed W/840810 ltr SAUM M A . SHITH.W G Indiana 5 Michigan Electric Co 84/08/10 Bpp 26108 032 24X Fiche 50-315.84/08/10.8408160527
- 8408210269 PNO III-84-065 on 840814 Unit 1 tripped from 100% due to failure of control room instrument distribution panel Failure caused reactor protection says to lose flow in one coolant Joap Panel replaced Tests performed for operability WRIGHT.G. SHAERLW Region 3. Office of Director 84/08/15 1p 24/80 344 24% Fishe 50-315,84/08/15,8408210269
- 8408220496 LER 84-014-00 on 840716 nonlicensed operator mistakenly isolated north low head safety injection pump Caused by personnel error Procedule revised W/840815 ltr BAKER, K.R. SMITH, W.G. Indiana & Michigan Electric Co. 84/08/15 Jpp 26196 029 P4X Fiche 50-315.84/08/15,8408220486
- 840B300505 LER 84-015-00 on 840728 & 29.Tech Spec 3 3 3 1.Action Statement 19 violated due to failure to complete daily survey of spent fuul storage area Caused by personnel error Written instructions improved W/840B24 ltr KRIESEL.T A. SHITH.W G Indiana & Michigan Electric Co 84/08/24 2pp 26313 362 24X Fiche 50-315.84/08/24.8408300505
- V Operator Examinations
- 8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10.8408140426
- 8408240276 Confirms actions to be taken by 840822 re results of 840618 licensed operator & senior operator requalification exams MEPPLER, JQ Region 3, Diffice of Director 84/08/21 DOLAN, JE American Electric Power Service Corp DOLAN, JE Indiana & Michigan Electric Co 3pp 26226 016 24X Fiche \$0-315,84/08/21,8408240276
- DOCKET 30-316 DONALD C COOK NUCLEAR POWER PLANT, UNIT 2

  F Security, medical, emergency & fire protection plans
- B408060118 Forwards thanges to modified amended security plan Changes withheld (ref 10CFR73 21)
  ALCXICH: MP Indiana & Michigan Electric Co 84/07/19
  KEPPLER: J G Region 3, Office of Director 1p 25936 029 24X
  Ficho 50-315,84/07/19,8408060118
- 8408040348 Forwards tovised Page B-14 to modified amended security plan.per 10CFR50 54(p) Page withheld (ref 10CFR73 Pl)
  ALEXICH.MP Indiana & Michigan Electric Co 84/07/19
  KEPPLER.J G Region 3. Office of Director 1p 29936 094 24X
  Ficho 50-315.84/07/19.8408060348
- 8408020020 Atk receipt of 840719 ltr re formal page changes to modified amonded security plan Changes will be included as part of approved plan Future changes should ref 1007873 21 when requesting withholding AXELSON.W L Region 3. Office of Director 84/07/26 ALEXICH.M P Indiana & Michigan Electric Co 2pp 25983 148 24X Fithe 50-315.84/07/26.8408020020
- 8408070060 Advises that 840719 changes to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable AXELS(N, W L. Region 3, Office of Director 84/08/01 ALEXICH, M P. Indiana & Michigan Electric Co. ALEXICH, M P. American Electric Power Co., Inc. 2pp. 25749 338 24X Fiche 50-315,84/08/01,8408070060
- 8408070272 Rev 3 to Procedure PMP 2080 EPP 012, "Initial Offsite Notification" XRAUSE, D. Indiana & Michigan Electric Co. 84/08/01 App 25949 203 24X Fiche 50-315.84/08/01.8408070272

- 840807030° kr. 6 to Emergency Plan Implementing Procedure PMP 2080 EPP 008. Initiating Manning or Emergency Response Facilities? Calling Off-Tour Plant Personnel " Indiana \* Michigan Electric Co. 84,08/01 13pp 25947 328 24X Fichs 50-315.84/08/01.8408070307
- 8408100094 Forwards responses to NRC 840508 request for addl info re detailed control room design review (DCRBN) Entls include functions of DCRDN teams, control room instrumentation 5 emergency response capability Integration plan ALEXICH, M.P. Indiana 5 flichigan Electric Co. 84/08/06 Office of Nuclear Reactor Regulation, Director 25pp 24X Fiche 50-315 84/08/05,8108100074 DENTON, H. R.
- --B405010079 Summarijes B40329 neeting widestinghouse Owners Group re task analysis requirements of Suppl | to NUREG-0737 (Generic Ltr B2-33) CLAYTON, H.B. Procedures & Systems Review Branch B4/04/05 ZIEMANN, D.L. Procedures & Systems Review Branch 17pp 2598B 230 24X Fiche 50-315,84/08/06,8408100094
- 8408130321 Revs to Emergency Plan Implementing Procedures PMP 2081 EPP 021. "Activation 5 Operation of Operations Staging Area & Personnel Accountability" 5 PMP 2081 EPP 004. "Protective Action Ouides (PAGs) & Protective Actions " \* Indians / Michigan Electric Co 84/08/07 24pp 26006 001 Fiche 50-315.84/08/07.8408130321 84/08/07 24pp 26006 001 24X
- B40B170322 Forwards Suppl 2 to "App R Evaluation of Auxiliary Bldg HVAC Duct Penetration & Containment Seismic Caps:" providing justification for technical exemptions requested in B40615 ltm ALEXICH.M P. Indiana & Michigan Electric Co. 84/08/13 DENTON.H R
  - ALEXICH.M P Indiana & Hichigan Flectric Co 84/08/13 DENTON, N Office of Nuclear Reactor Regulation, Director 2pp 26113 001 24X Fiche 50-315,84/08/13.8408170322
- --8408170327 Suppl 2 to "App R Evaluation of Auxiliary Bldg HVAC Duct Penetration & Containment Selsmic Gaps " \* Engineering Planning & Management, Inc 84/08/31 52pp 26113 003 24% Fiche 50-315,84/08/13,8408170322
- 8408210156 Rev 1 to Procedure PMP 2081 EPP 014. "Offsite Dase Assessments" \* Indiana & Michigan Electric Co 84/08/15 49pp 26147 078 24X Fiche 30-315.84/08/15.8408210156
- P. Operating license stage documents % correspondence
- B405160248 Requests that inservice insp/inservice testing second 10-yr internal for both units begin on 860701.1 yr earlier than stated in 840315 l\*r.contingunt upon acceptance of listed code relief requests HERIND, R. F. Indiana & Michigan Electric Co. 84/05/11 DENTON. Office of Nuclear Reactor Regulation. Director 2pp. 24485-069 24X Fiche 50-915,81/05/11,8405160248 DENTON, H R
- 8406080107 Forwards currected Tech Spec Page 3/4 10 5 re position indicator channels shutdown, submitted ω/840315 Tech Spec change request HERING R F I indiana / Michigan Flectric Co 84/06/04 DENTON/F Indiana / Michigan Flectric Co 84/06/04 DENTON/F Office of Nuclear Reactor Regulation, Director 3pp 24x Fiche 50-316,84/06/04,8406080109
- --8406080113 Corrected Tech Spec Page 3/4 10 5 re position indicator # Indiana & Michigan Electric Co 84/06/04 1p 24856 087 24X Fiche 50-316,84/06/04,8406080109
- B408010310 Notification of date & location change for B40815 meeting w/util in Bethesda.MD to discuss program for hydrogen control, equipment survivability & containment structural integrity Meeting originally scheduled for B40725 MIGGINTON, D I Operating Reactors Branch i 84/06/27 VAROA, B A Operating Reactors Branch i 292 25872 317 24% Fiche 50-315.84/06/29, 8408010310
- 8408060076 Informs of temporary procedural change to ensure that plant operations consistent u/FSAR analysis assumptions for interim period, until proposed Tech Spec change re reactor coolant pump operability at hot zero power approved ALEXICH:MP Indiana & Michigan Electric Co 84/07/30 DENTON.HR Office of Nuclear Reactor Regulation, Director 5pp 25933 125 24x Fiche 50-315,84/07/30,8408060076
- 8408160425 Summary of 840720 meeting w/utils & Westinghouse recontainment analysis & superheat effects on environ qualification HIGGINTON,D L. Operating Reactors Branch 1 84/07/30 Opera Reactors Branch 1 4pp 26143 265 24 Reactors Branch 1 8408160425

- 8408160188 Furwards results of teriew of NUREG-0737 Item II II 3 open items to post-actident sampling sys Mods will be completed a sys operational by Sept 1984
  ALEXICH.M P Indiana b Michigan Electric Co 84/08/02 DENTON.H
  Office of Nuclear Reactor Regulation, Director App 26092 036
  24% Fiche 50-315,81/08/02,8408160188 DENTON, H. R.
- 8408140164 Responds to 840720 verbal request re effects of superheated steam following postulated main steam line break Util will participate in Westinghouse Duners Group activities & involvement expected to suppl internal review ALEXICH II P. Indiana & Michigan Electric Co. 84/08/03 DENTON, H.R. Office of Nuclear Reactor Regulation. Director 7pp 26045 OOI 24X Fishe 50-315.84/08/03.8408140164
- 8408070110 Generic Ltr 84-19 to all licenses of operating reactors, applicants for OLs 8 holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Generic Safety Issues " Svc list encil EISENHUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000,84/08/06,8408070110
- 8408090198 Forwards nonproprietary version of Rev 2 to XN-NF-84-21. "DC Cook Unit 2.Cycle 5.5% Steam Generator Tube Plugging Limiting Break LOCA/ECCS Analysis." per American Electric Pawer Svc Co request
  CHANDLER, J C Exxon Nuclear Co. Inc (subs of Exxon Corp.)
  84/08/07 DENTON H R Office of Nuclear Reactor Regulation,
  Director 1p 25972 038 24% Fiche 50-316.84/08/07.8408090198
- --8408090209 Nonproprietary version of Rev 2 to "DC Cook, Unit 2 Cycle 5,5% Steam Generator Tube Plugging Limiting Break LOCA/ECCS Analysis " Analysis "

  KAYSER, W V, CHANDLER, J C, STOUT, R B Exxon Nuclear Co, 1

  (subs of Eyron Corp.) XN-NF-84-21 (NP) R02 84/08/07 7

  25972 039 24X Fiche 50-316.84/08/07.8408090198
- 8408160494 Returns 840718 check which accompanied 840723 application for relief from certain ASME Code requirements Application subj to revised 102FR170 Requests remission of required fee for application Discussion of fees encl
  DICOS.R M License Fee Management Branch 84/08/09 DOLAN, J American Electric Power Service Corp 4pp 26124 337 24X
  Fiche 50-315,84/08/09,8408160494
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & 408200275 Generic Ett 84-20 to All licensees of operati applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT.D G Division of Licensing 84/08/20 Co Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000.84/08/20.8408200275 Consolidated
- B40824012) Notifies of plans to submit listed documents re PTSPWR2 code NUBLEGIES OF Plans to somit listed documents as the ACO transient analysis methodology by BAOS31, per BAO601 itr App C for four-loop nothodology will be initiated following NRC comments be three-loop methodology ALEXICH. M P Indiana & Michigan Electric Co 84/08/20 Office of Nuclear Reactor Regulation, Director 2pp 26 24X fiche 30-316.81/08/20.8408240121 2pp 26228 214
- 8408240188 Forwards status rept on inadequate core cooling instrumentation sys.per 831219 request Rept addresses reactor vessel instrumentation sys.core exit thermocouples, subcooling margin monitor & RUREG-0737. Item II F 2
  ALEXICH. M P Indiana & Michigan Electric Ca 84/08/20 DENTON: H R
  Office of Ruciear Reactor Regulation, Director Spp 26227 355
  24X Fiche 50-315.84/08/20.8408240188
- Q Inspection reports. IE Bulletins & correspondence
- 8405160248 Requests that inservice insp/inservice testing second iO-yr internal for both units begin on 860701.1 yr earlier than stated in 840315 ltr.contingent upon acceptance of listed code rollef requests

  HERRING R F Indiana & Michigan Electric Co 84/05/11 DENTON.

  Office of Nuclear Reactor Regulation, Director 2pp 24485 069

  24X Fiche 50-315.84/05/11.8405160248 DENTON, H. R.
- B408230204 Forwards IE Insp Repts 50-315/84-11 & 50-316/84-12 on B40604-0B No noncompliance noted BHAFER.W D Region 3. Office of Director B4/07/24 DDLAN.J E American Eloctric Power Service Corp DDLAN.J E Indiana & Michiga Electric Co 2pp 36214 035 24X Fiche 50-315.84/07/24.8408230204
- --8408230211 IE Insp Repts 50-315/84-11 & 50-316/84-12 on 840604-08 No 008200211 IE Insp Repts 30-315/44-11 & 30-315/44-12 on B4060\* noncompliance noted Major areas inspected sys walkdown & print verification, surveillance, maint, inservice testing, work controls, calibr & operations review WRIGHT, G C Region 3, Office of Director 84/07/24 10pp 26214 037 24X Fiche 50-315,84/07/24,8408230204

- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants' Svc list end JURDAN.E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc. 119pp 25855 047 24% Fiche 50-000.84/07/27,8407250229
- 840808084 Submits supplemental response to IE Bulletin 83-07.

  "Apparently Fraudulent Products Sold by Ray Miller, Inc "
  Piping mails used in Fabrication of chemical 2 vol control sys supplied by Ray Miller, Inc 
  ALEXICH, M P Indiana & Michigan Electric C 84/08/01

  DEYOUNG, R C Director's Office, Office of Inspection and 
  Enforcement Spp 67473 131 242 Fiche 50-315.84/08/01,8408080084
- B408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance round during inspinstituted. effective B40820 Preprinted form will be used rather than ltr

  KEPPLER.J C Region 3. Office of Director B4/08/03
  Commonwealth Edison Co 3pp 25742 188 24% Fiche 50-000,84/08/03,8408070401
- 8408010333 IE Info Natice 84-59, 'Deliberate Circumventing of Station Health Physics Procedures "Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/04 Consolidated Edison Co of New York, Inc 122pp 26068 001 24% Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 630103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp. 26067 198 24x Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York. Inc. 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Freatments " Svc list Encl GRACE.J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24x Fiche 50-000.84/08/10.8408070376
- B40B100009 IE Info Notice 84~63, "Defective RHR Replacement Piping "
  Svc list encl
  JDRDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York Inc 1199p 26197 218 24x Fiche 50-000,84/08/13,840B100009
- 8408300181 Forwards Insp Repts 50-315/84-14 & 50-316/84-16 on 840723-27 No noncompliance noted WALKER, R D Region 3. Office of Director 84/08/14 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigar Electric Co 2pp 26313 263 24X Ficha 50-315,84/08/14,8408300181
- B408100038 IE Info Notice 84-44. "BWR HPC: Initiation Seal-In & Indication " Syc list enc! JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 073 24% Fichs 50-000.84/08/15,8408100038
- 8408100021 IE Info Notice 84~65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " 8vc list encl JDRDAN, E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/16 Consolitated Edison Co of New York: Inc 118pp 26198 001 24X Fiche 50-000.84/08/16,8408100021
- B40B100055 IR Info Notice B4-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post B30103) B4/0B/17 Consolidated Edison Co of New "---" 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
  - 'Info Notice 84-47, "Recent Snubber Inservice Testing W/
    'e Rates " Svc list encl
    Division of Emergency Preparedness & Engineering
    'est 830103) 84/08/17 Consolidated Edison Co of New
    122pg 26276 122 24x Fiche 50-000.84/08/17, 8408140208

- B40B210142 IE Info Notice 84 &B Potential Deficiency in Improperly Rated Field Wiring to Solehuid Valves 'Swc list enc! JORDAN.E L Division of the genry Preparedness 'Engineering Response (Post 620103) 84/08/21 Consolidated Edison Co of New York, Inc 11Spp 26329 008 24% fichc 50-000.84/08/21.8408210142
- BAOB280147 Discusses B40621 meeting w/util re SALP Repts 50-315/84-08 t 50-316/84-09 for period from Apr 1983 Mar 1984 Summary of meeting, including list of attendees encl as App A to SALP repts App final step in SALP assessment process KEPPLER. J G Region 3. Office of Director B4/08/23 DDLAN. J E American Electric Power Service Corp DDLAN. J E Indiana & Michigan Electric Co 2pp 26259 0/8 24% fiche 50-315.84/08/23.8408280147
- ---8408280155 App to SALP Repts 50-315.84-08 % 50-316/84 09 for period from Apr 1983 Mar 1984 Summarizing 840621 meeting % including list of attenders \* Region 3. Office or Director 84/08/23 2pp 26259 080 24% Fiche 50-315,84/08/23.8408280147
- S Reportable occurrences, LERs & related correspondence
- 8408060151 LER 84-017-00 on 840704, while in Mode 3, surveillance requirements of Yoch Spec 3 3 1 into performed as required for intermediate-range er-core detectors shiftly channel checks Procedures revised W/840726 ltr
  DAKER, K. R. 5 MITTH, W. G. Indiana & Michigan Electric Co. 84/07/26
  2pp 25938 167 24% Fiche 50-316,84/07/26,8408060151
- 8408130307 LER 84-018-00 on 840709, following refueling outage, RPI for rods R-8 & K-10 misaligned Caused by variables affecting secondary coil stack voltages Unit placed in Mode 3 W/840808 ltr BLIND.A A SMITTH, W G Indiana & Michigan Electric Co 84/08/08 200 26010 259 24% Fiche 50-316, 84/08/08, 8408130307
- 8408160127 LER 84-019-00 840710, reactor coolant pump removed from syc due to indication of problems Protective function channel was not tripped within specified time Procedures revised & personnel will be trained W/840809 ltr BAKER, K R , SHITH, W G Indiana & Michigan Electric Co 84/08/09 2pp 26108 115 24X Fiche 50-316,84/08/09,8408160127

#### V Operator Examinations

- 8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners MALKER, R D. Region 3. Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, M1 2pp 26051
- B408240296 Confirms actions to be taken by 840822 re results of 840818 licensed operator & senior operator requalification exams KCPPLER.J 9 Region 3, Office of Director B4708/21 DOLAN,J E American Electric Power Service Corp DOLAN,J E Indiana & Michigan Electric Co 3pp 26226 016 24% Fiche 50-315.84708/21.8408240296
- BDCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

  F. Becurity, medical, emergency & fire protection plans
- 8408170261 Rev 10 to Emergency Radiological Plan Implementing Procedure ERPIP 4 1 6. "Offsite Munitoring Team" \* Baltimore Gas & Electric Co 84/07/06 tipp 261(5 343 24X
- 8408150711 Forwards IE Safeguards Insp Regts 50-317/84-17 & 50-318/84-17 on 840611-15 & notice of violation MARTIN.T T Division of Engineering & Technical Programs 84/07/22 BOWMAKER.N J Baltimore Cas & Electric Co 2pp 26079 017 24X Fiche 50-317.84/07/27.8408150711
- --8408190715 Notice of violation from insp on 840611-15 Safeguards info deleted (ref 10CFR73 21 & 9 5) MARTIN.T T Division of Engineering & Technical Programs 84/07/27 1p 86079 019 24X Fiche 50-317.84/07/27.8408150711
- --8408150721 IR Safeguards Insp Repts 50-317/84-17 & 50-318/84-17 on 840611-15 Noncompliance noted failure to follow physical security plan implementing procedures Info deleted (ref 10CFR73 21 & 9 5) BALLEY, R J. KEIMIO.R Region 1. Office of Director 84/07/27 6408150711

- 8408200320 Forwards Amends 95 & 74 to Licenses DPR-53 & DPR-69, respectively & safety evaluation Amends revise licenses to include latest revs to security plan, safeguards contingency plan & guard training qualification plan JAFFE, D H Operating Reactors Branch 3 84/08/01 LUNDVALL, A & Baltimore Gas & Electric Co. ip P6141 233 24X Fiche 50-317,84/08/01,8408200320
- --8408200325 Amends 95 & 76 to Licenses DPR-53 & DPR-69, respectively, revising licenses to include latest revs to security plan, safeguards cuntingency plan % guard training qualification plan Plan IILLER, J. Operating Reactors Branch 3 84/08/01 4pp 26141 234 24X Fiche 50-317,84/08/01,8408200320
- --8408200327 Safety evaluation supporting Amends 95 & 76 to Licenses BPR-53 & DPR-69, respectively

  \* Office of Nuclear Reactor Regulation, Director 84/08/01 2p 26141 238 247 Fiche 50-317,84/08/01,8408200320
- B40B240015 Forwards Amends 96 & 77 to Licenses DPR-53 & DPR-69, respectively & safety evaluation Amends reflect administrative changes, addl fire protection instrumentation & change in area access control
  JAFFE.D.H. Operating Reactors Branch 3 B4/08/02 LUNDVALL,A & Baltimure Gas & Electric Ca ip 26256 034 24X
  Fiche 50-317.84/08/02.8408240015
- ---8408240017 Amends 96 & 77 to Licenses DPR-53 & DPR-69, respectively, reflecting administrative organization changes installation of addl fire protection instrumentation & change in control of access to high radiation areas

  MILLER, J. R. Operating Reactors Branch 3 84/08/02 30pp

  26256 035 24X Fiche 50-317.84/08/02.8408240015
- --8409240020 Safety evaluation supporting Amends 96 & 77 to Licenses DPR-53 & DPR-69, respectively \* Office of Nuclear Reactor Regulation, Director 84/08/02 3pp 26256 065 24X Fiche 50-317,84/08/02,8408240015
- 8408070343 Forwards plant-specific technical guidelines, required by Suppl 1 to NUREO-0737, to aid NRC in completing review of emergency procedures generation package, in response to B40614 request LUNDVALL, A E Baltimore Oas & Electric Co B4/0B/03 MILLER, J R Operating Reactors Branch 3 6pp 25944 154 24X Fiche 90-317.84/08/03.8408070343
- 8408150528 Notification of Significant Licensee Meeting 84-68 on 840808 in King of Prussia-PA to discuss revs to site security/contingency plans KUSHMER.PL Region 1. Office of Director 84/08/08 Region 1. 04/08/08 Security Security
- 8408240361 Forwards Insp Repts 50-317/84-08 & 50-318/84-08 on 840411-0515 Significant safety concerns re operability of component cooling HY identified Issue resolved pending followup to stated actions per 840517 meeting STAROSTECKI,R Division of Project & Resident Programs 84/08/08 LUNDWALL,A E Baltimore Gas & Electric Co 2pp 26237 065 24X Fiche 50-317.84/08/08.8408240361
- --8408240363 Insp Repts 50-317/84-08 & 50-318/84-08 on 840411-0515 Major areas inspected control room, accessible parts of plant structures, plant operations, radiation protection, physical security & fire protection
  FOLEY.17. TRIMBLE, D.C., WENZINGER, E.C. Region 1, Office of Director 64/07/31 13pp 26237 067 24X Fiche 50-317, 84/08/08, 8408240361
- 8408170086 Rev 11 to Emergency Response Plan Implementing Procedure ERPIP 3 0, "Immediate Action Procedures" W/840813 Rev 2 to table of contents # Baltimore Gas & Electric Co 84/08/13 36pp 26119 033 24X Fiche 50-317.84/08/13.8408170086
- 8408240272 Advises that 840510 Rev 4 to safeguards contingency plan consistent w/provisions of IOCFR50 54(p) & acceptable MARTIN, T T Division of Engineering & Technical Programs 84/08/16 8DWMAKER, N J Baltimore Cas & Electric Co Spp 26222 331 24X Fiche 50-317/84/08/16/8408240272
- P Operating license stage documents & correspondence
- 8406230301 THREE-DIMENSIGNAL CALCULATIONS OF TRANSIENT FLUID-THERMAL MIXING IN THE DUMNCOMER OF THE CLAVERT CLIFFS-1 PLANT USING BOLA-PTS
  DALY, B J Los Alamos Scientific Laboratory FIN A-7306
  NUREG/CR-3704 84/04/30 Division of Accident Evaluation 86pp 25131 319 24x Fiche 50-317,84/04/30,8406230301

- 8408070271 Responds to 840604 request for NRC concurrence in plans to train to qualify six senior control rodm operators as shift technical advisors Personnel entering program must be degreed or equivalent, per NUREO-0737, Item I A I 1 MILLER, J.R. Operating Reactors Branch 3 84/07/26 LUNDVALL, A E Baltimore Gas to Electric Co. 3pp. 25956 261 24X Fiche 50-317.84/07/26,8408070271
- 840B020031 Informs of planned mod to C-E control element assembly guide tube wear sleeve Mod includes relocation of sleeve flars sleeve expansion over full length of sleeve a relocation of crimp, providing resistance to axial motion SCHERER. A E Combustion Engineering. Inc 84/07/27 RUJENSTEIN. L S Assistant Director for Core & Plant Systems 2pp 25880 258 24X Fiche 50-000.84/07/27,8408020031
- B40B230172 Forwards DRNL draft "Chapter 5 Probabilistic Fracture-Mechanics Analysis of Calvert Cliffs Unit 1 Bequences." of pressurized thermal shock rept Comments requested by 840B22 JCHNBON, C NRC No Detailed Affiliation Given 84/07/30 HODDS, R NRC No Detailed Affiliation Given 126230 028 24X Fiche 50-317.84/07/30.8408230172
- --B408230184 Forwards DRNL draft "Chapter 5 Probabilistic Fracture-Mechanics Analysis of Calvert Cliffs Unit 1 Sequences," of pressurized thermal shock rept Comments requested by 840822 SELBY.D L. Dak Ridge National Laboratory B4/07/30 JDHNSDN.C E NRC - No Detailed Affiliation Given KDENIG.J E Los Alamos Scientific Laboratory MIRSKY.S M Baltimore Gas & Electric Co 1p 26230 029 24X Fiche 50-317.84/07/30.8408230172
- 8408230191 Draft "Pressurized Thermal Shock Evaluation of Calvert Cliffs Unit 1 Nuclear Power Plant. Chapter 5 Probabilistic Fracture-Mechanics Analysis of Calvert Cliffs Unit i Sequences "

  \* Oak Ridge National Laboratory 84/07/27 NRC No Detailed Affiliation Given 169pp 26230 030 24X Fiche 50-317,84/07/30,9408230172
- 8408200320 Forwards Amends 95 & 76 to Licenses DPR-53 & DPR-69, respectively & safety evaluation Amends revise licenses to include latest revs to soccurity plan, safeguards contingency plan & guard training qualification plan JAFFE, D H Operating Reactors Granch 3 84/08/01 LUNDVALL, A E Baltimore Gas & Electric Co ip 26141 233 24X Fiche 50-317.84/08/01.8408200320
- --8408200325 Amends 95 & 76 to Licenses DPR-53 & DPR-49, respectively, revising licenses to include latest revs to security plans safeguards contingency plan & guard training qualification plan MILLER. J R Operating Reactors Branch 3 84/08/01 4pp 26141 234 24X Fiche 50-317.84/08/01.8408200320
- --8408200327 Safety evaluation supporting Amends 95 & 76 to Licenses DPR-53 & DPR-69, respectively \* Office of Nuclear Reactor Regulation. Director 84/08/01 2pp 26141 236 24% Fiche 50-317.84/08/01.8408200320
- B40B240015 Forwards Amends 96 & 77 to Licenses DPR-93 & DPR-69, respectively & safety evaluation Amends reflect administrative changes, addl fire protection instrumentation & change in area access control

  JAFFE, D H Operating Reactors Branch 3 84/08/02 LUNDVALL, A. E. Bitimore Gas & Electric Co 1p 26256 034 24X

  Fiche 50-317,84/08/02,8408240015
- --8408240017 Amends 94 & 77 to Licenses DPR-53 & DPR-69, respectively, reflecting administrative organization changes installation of add1 fire protection instrumentation & change in control of access to high radiation areas
  MILLER.J R Operating Reactors Branch 3 84/08/02 30pp 26254 035 24% Fire 50-317,84/08/02,8408240015
- 8408070110 Generic Ltr 84-19 to all licenses of operating reactors, applicants for OLs & holders of CPs re availability of Buppl I to NUREO-0933; "Prioritization of Generic Safety Issues "Svc list encl EIBENHUT; D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129:838 24X Fichs 50-000,84/08/06.8408070110

- 8408200275 Generic Lor 84-20 to all licensees of operating reactors & applicants for DLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
  EISENHUT.D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp. 26276-244 24X
  Fiche 50-000.84/08/20,8408200275
- Q Inspection reports, IE Bulletine & correspondence
- B408150298 Forwards IE Insp Repts 50-317/84-09 & 50-318/84-09 on B40423-27 & notice of violation MARTIN, T Division of Engineering & Technical Programs 84/07/16 LUNGVALL: A E Baltimore Gas & Electric Co 2pp 26074 334 24X Fichs 50-317.84/07/18.8408150298
- --B408150301 Notice of violation from insp on B40423-2/ # Region (, Diffice of Director B4/07/18 2pp 26074 336 24X Fiche 50-317,84/07/18,8408150278
- --B408150305 IE Insp Repts 50-317/84-09 & 50-318/84-09 on 840423-27 Noncompliance noted failure to have radiochemistry procedures reviewed by POSRC STRUCKMEYER, R. JANG, J. C. HOGAN.R. T. Region 1. Office of Director 84/07/17 12pp 26074 338 24X Fiche 50-317.84/07/18, 8408150298
- 8408160102 Forwards IE Insp Repts 50-317/84-16 & 50-318/84-16 on 840604-08 & notice of violation MARTIN, T Division of Engineering & Technical Programs 84/07/24 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 26/08 135 24X Fiche 50-317,84/07/24,8408160102
- --8408160107 Notice of violation from insp on 840604-08 \*\* Region 1. Office of Director 84/07/24 1p 26108 137 24X Fiche 50-317,84/07/24.8408160102
- --8408160115 IE Insp Repts 50-317/84-16 to 50-318/84-16 on 840604-08 Violation noted failure to establish procedures for incomplete work followup on safety-related and to auxiliary feedwater sys BLUMBERG.N., BETYENHAUSEN.L. Region 1. Office of Director 84/07/12 12pp 26108 130 24X Fiche 50-317.84/07/24.8408160102
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, E. Olivision of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc. 119pp 25865-047 24X Fishe 50-000,84/07/27,8407250229
- 8408150711 Forwards [E Safeguards Insp Repts 50-317/84-17 to 50-318/84-17 to 840611-15 to notice of violation MARTIN,T T Division of Engineering to Technical Programs 84/07/27 BOWNMER,N J Balttmore Gas & Electric Co 2pp 26079 017 24X Fiche 50-317.84/07/27.8408150711
- --8408150715 Notice of violation from insp on 840511-15 Safeguards info deleted (ref 10CFR73 21 & 9 5) MARTIN.T T Division of Engineering & Technical Programs 84/07/27 ip 26079 019 24X Fiche 50-317.84/07/27.8408150711
- --8408150721 IE Safeguerds Insp Repts 50-317/84-17 t 50-318/84-17 on 840411-18 Noncompliance noted failure to follow physical security plan inplementing procedures Info deleted (ref 10CFR73 21 t 7 5) BAILEY.R J. KEIMIO.R R Region 1. Office of Director 84/07/27 6pp 24079 020 24x Fiche 50-317.84/07/27.8408150711
- 8408070074 Forwards check inadvertently emitted from 840305 ltr re inservice insp program DENTON:R E Baltimore Oas 1 Electric Co 84/07/30 MILLER, J.R. Operating Reactors Branch 3 ip 25949 280 24X Fiche 50-317.84/07/30.8408070074
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 24068 001 24X Fiche 50-000,84/08/06,8408010333
- B40B010337 IE Info Notice B4-40. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl UGRDAN, E L Division of Emergency Preparedness & Engineering Response (Fost B30107) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24% Fiche 50-000.84/08/06. B408010337

- 8408070120 IE Info Notice 84-61, Overhoposure of Diver in PWR Refueling Covity 'S.c list end! JORDAN.E L Division of Emergency Preparedness 'Engineering Response (Post 830107) 84 08/08 Consolidated Edison Co of New York, Inc. 120pp 26127 ILB 24% Fiche 50-000,84/08/08,8408070120
- 8408240361 Forwards Insp Repts 50-317/84-08 / 50-318/84-08 on 840411-0515 Significant safety conceins re operability of component cooling MY identified Issue resolved pending followup to stated actions per 840517 meeting STAROSTECKI.R Division of Project 'Resident Programs 84/08/08 LUNDVALL.A E Baltimore Cas 'Electric Co 2pp 26237 065 24% Fiche 50-317.84/08/08.8408240361
- --B408240363 Insp Repts 50-317.84-08 \* 50-318.84-08 on B40411-0515 Major areas inspected control room.accessible parts of plant structures, plant operations, radiation plotection, physical security \* file protection FOLEY.T. TRIMBLE.D C . WENTINGER.C C . Region 1, Office of Director 84/07/31 13pp 26237 067 24X Fiche 50-317.84/08/08, 8408240361
- 8408070376 IE Info Notice 84-62, "Therapy Hisadministrations to Patients Undergoing fo-60 Teletherapy Treatments" Syc list encl GRACE, J N Division of QA, Saregualds & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24x Fiche 50-000,84/08/10,8408070376
- 8408100009 IE lnfo Notice B4-63. "Defective RHR Replacement Piping " Svc list enct JORDAN.E L Division of Emergency Preparedness & Figureering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc. 119pp 26197 218 244 Fiche 50-000.84/08/13.8408100009
- 8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Scal-In t Indication "Syc list encl JURBAN, E. L. Division of Emergency Picparedness \* Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co. of New York, Inc. 104pp 86198 093 244 Fiche 50-000,84/08/15,8408100038
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Syc list cncl List cncl JORDAN, C. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc. 118pp 26198 001 24% Fiche 50-000, 04/08/16, 8408100021
- 8408100055 IF Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JCRDAN.E L Division of Emergency Preparedness " Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 86276 001 24% Fiche 50-000,84/08/17,8408100055
- 8408140208 IE Info Notice 84-67. 'Recent Snubber Inservice Testing W/ Migh Failure Rates " Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 83)109) 84/08/17 Consolidated Edison Co. of New York, Inc. 1829p 86274 122 24% Fiche 50-000.84/08/17,8408140208
- B40B210142 IE Info Notice 84-68, "Potential Deficioncy in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/08/21 Consolidated Edison Co of New York, Inc 115pp 26327 008 24% Fiche 50-000,84/08/21,8408216142
- R Periodic operating reports & related correspondence
- 8408270535 Nontquisine radiological environ operating rept re levels of Ag-110m in obster samples collected during June 1984 Dose rates within acceptable limits FURRMANNOR Baltimore Cas & Electric Co 64/07/31 Region 1, Office of Disector 3pp 26279 227 247 Fiche 50-317,84/07/31,8408270535
- S Reportable occurrences, LFRs % related correspondence
- 8405290354 Forwards LASL draft rept on boron dilution event to determine safety significance of unmitigated boron dilution event Staff templetion of review expected by 840515

  JAFFE, D H Operating Reactors Branch 3 84/05/04 LUNDVALL, A E Battimore Gas & Electric Co 47pp 24695 275 24X

  Fiche 50-317,84/05/04,8405290354
- 8408150188 LFR 63-009/03x-3 on 830210 review of Units 1 & 2 snubber surveillance test procedures revealed that snubber 2-15-10 not included in Unit 2 Tech Spocs & that missed surveillance occurred on snubber 1-15-8 W/840803 ltr FARRELL. C V RUSSELL L B Baltimore Gas & Electric Co 84/07/30 3pp 26075 350 24% Ficho 50-317.84/07/30.8408150188

- B40B310365 Forwards 'Events Involving Fires or Other Related Abnormalities in Motor Control Citis Wisheminum Bus Bars," technical review rept Forther actions relissue not warranted at present ASME, F. Resctor Operations Analysis Branch 84/08/06 SEYR
  - ac present ASHE, F. Reactor Operations Analysis Branch 64'08/06 SEYFRIT, K.V. Reactor Operations Analysis Blanch 1p 26350 295 24X Fiche 50-317 84/08/06,8408310365
- --8408310370 'Events Involving Fires or Other Related Abnormalities in Motor Control Ctrs W/Aluminum Bus Bais," technical review rept
  ASMF. F. Reactor Operations Abalusis Branch BA/08/06 3nn
  - repu ASHE,F Regitor Operations Analysis Branch 84/08/06 3pp 26350 296 24x Fiche 50-317 84/08/06 8408310365
- 8408290298 LER 84-007-00 on 840/2), during monthly surveillance test of ESF actuation sys, power lost on 4 160-volt emergency bus Caused by personnel indivertently depressing incurrect test autton Bus idenargized Button relabiled U/840823 Itr LDHR, J., RUSSELL, B. Baltimore Gas & Electric Co. 84/08/23 3pp 26295 056 24X Fiche 50-317.84/08/23,8408290258
- DOCKET 50 318 CALVERT CLIFFS NUCLEAR POWER PLANT. UNIT 2

  F. Security, medical, emergency % fire protection plans
- 8408170261 Rev 10 to Emergency Radiological Plan Implementing Procedure ERPIP 4 1 6, "Offsite Monitoring Team" • Baltimore Gas & Electric Co 84/07/06 llpp 26115 343 24X Fiche 50-317,84/07/06,8408170261
- 8408150711 Forwards IE Gafeguards Insp Repts 50-317/84-17 & 50-318/84-17 on 840611-15 % notice of violation MARTIN.T T. Division of Engineering % Technical Programs 84/07/27 BOWMAKER.N J. Baltimore Gas & Electric Co. 2pp. 26079 017 24X Fiche 50-317.84/07/27.8408150711
- --8408150715 Notice of violation from insp on 840611-15 Safeguards info deleted (ref 10CFR73 21 / 9 5) MARTIN,T T Division of Engineering & Technical Programs 84/07/27 ip 26079 019 24< Fiche 50-317.84/07/27,8408150711
- --8408150°21 IE Sateguards Insp Repts 50-317/84-17 & 50-318/84-17 on 840611-19 Noncompliance noted failure to follow physical security plan implementing procedures Info deleted (ref 100fR73 21 & 9 5)
  BAILEY,R J Region 1, Office of Director 84/07/27 App 24079 020 24X Fiche 50-317,84/07/27,8408150711
- 8408200320 Forwards Amends 95 % 76 to Licenses DPR-93 % DPR-69, respectively % safety evaluation Amends revise licenses to include latest revs to security plan, safeguards contingency plan & guard training qualification plan MAFFE D H Operating Reactors Branch 3 64/08/01 LUNDVALL, A & Baltimure Gas & Electric Co 19 26141 233 24% Fiche 50-317.84/08/01.8408200320
- --8408200325 Amends 95 & 76 to Licenses DPR-53 % DPR-69, respectively, revising licenses to include labest revs to security plan, safeguards contingency plan & quard training qualification plan HILLER.J R Operating Reactors Branch 3 64/08/01 4pp 26141 234 24X Fishe 50-3;7,84/08/01,8408200320
- --8498200327 Safety evaluation supporting Amends 95 & 76 to Licenses DPR-53 & DPR-69.respectively

  \* Office of Nuclear Reactor Regulation, Director 84/08/01 2pp 26141 238 24% Fishe 30-317.84/08/01,8408200320
- 8408240015 Forwards Amends 96 / 77 to Licenses DPR-53 % DPR-69, respectively % safety evaluation Amends reflect administrative changes, add | fire protection instrumentation % change in area access control Related correspondence JAFFE. D H Operating Reactors Branch 3 D58 619 84/08/02 LUNDVALL, A E Raltimore Gas / Electric Co 1p 26256 034 24X Fiche 50-317.84/08/02.8408240015
- -- E408240017 Amends 96 & 7/ to Licenses DPR-53 & DPR-69, respectively, reflecting administrative organization changes, installation of addl fire protection instrumentation & change in control of access to high radiation areas MILLER, JR Operating Reactors Branch 3 84/08/02 30pp 26256 039 24X Fiche 50-317,84/08/02,8408240015
- --8408240020 Safety evaluation supporting Amends 96 & 77 to Licenses DPR-53 & DPR-69, respectively + Office of Nuclear Reactor Regulation, Director 84/08/02 Spp 26256 065 24X Fiche 50-317,84/08/02,8408240015

- B108070343 Forwards plant-specific technical guidelines, required by Suppl 1 to MUREO-0727, to aid NRC in completing review of smergency procedures generation package, in response to 840614 request LUMDVALLA E Baltimore Gas / Electric Co 84/08/03 MILLER, J R Operating Reactors Branch 3 6pp 25944 154 244 Fiche 50-317,84/08/03,8498070343
- 8408150628 Notification of Significant Licensee Meeting 84-68 on 840808 in King of Prussia:PA to discuss revs to site security/continguncy plans KUSHNER.W.L. Region 1. Office of Director 84/08/08 Region 1. Office of Director 2pp 26102 336 24X Fiche 50-317.84/08/08. 8408150428
- B40B240361 Forwards Insp Repts 50-317/84-08 % 50-318/84-08 ©n B40411-0515 Significant safety concerns re operability of component cooling HX identified Issue resolved pending following to stated actions per 840917 meeting STAROSTECKI, R Division of Project & Resident Programs B4/08/08 LUNDVALLA E Baltimore Gas & Electric Co 2pp 26237 065 24X Fiche 50-317.84/08/08.8408240361
- --8408240363 Insp Repts 50-317/84-08 / 50-318/84-08 on 840411-0515 Major areas inspected control room accessible parts of plant structures, plant operations, radiation protection, physical security & fire protection
  FOLEY, T Region 1, Office of Director 84/07/31 13pp 26237 047 24X Fiche 50-317.84/08/08,8408240361
- 8408170086 Rev ii to Emergency Response Plan Implementing Procedure ERPIP 3 0. "Immediate Action Procedures " W/840813 Rev 2 to table of contents \* Baltimore Oas & Electric Co 84/08/13 36pp 26119 033 24X Fiche 50-317.84/08/13.8408170086
- 8408240272 Advises that 840510 Rev 4 to safeguards contingency plan consistent w/provisions of 100FR50 54(p) % acceptable MARTIN.T T Division of Engineering & Technical Programs 84/08/16 DOWMAREN.D & Baltimore Gas & Electric Co 3pp 26222 331 24X Ficha 50-317.84/08/16.8408240272
- P Operating license stage documents & correspondence
- B40B070271 Responds to B40604 request for NRC concurrence in plans to train t qualify six senior control now operators as shift technical advisors Personnel entering program must be degreed or equivalent.per NUREG-0737.item I A 1; MILLER, J R Operating Reactors Branch 3 B4/07/26 LUNDVALL, A E Baltimore Gas & Electric Co 3pp 25956 26; 24% Fiche 30-317.84/07/26.8408070271
- 8408200320 Forwards Amends 99 % 7b to Licenses DPR-59 % DPR-69, respectively & safety evaluation Amends revise licenses to include latest revs to security plan, safeguards contingency plan & guard training qualification plan JAFFE D H Operating Reactors Branch 3 84/08/01 LUNDVALL.A E Baltimare Gas & Electric Co ip 26141 233 24% Fiche 50-317.64/08/01.8408200320
- --B408200329 Amends 95 % 74 to Licenses DPR-53 % DPR-69, respectively, revising licenses to include latest revs to security plansafegueids contingency plan & guard training qualification plan MILLER. J. Operating Reactors Branch 3 84/08/01 4pp 24141 234 24X Fiche 50-317.84/08/01.8408200320
- --BAOB200327 Safety evaluation supporting Amends 95 & 76 to Licenses DPR-53 & DPR-69, respectively # Office of Nuclear Reactor Regulation, Director 84/08/01 2pp 26/41 238 24% Fiche 50-317,84/08/01,8408200320
- 8408240015 Forwards Amends 96 & 77 to Licenses DPR-53 & DPR-69, respectively & safety evaluation Amends reflect administrative changes, add1 rise protection instrumentation & change in area access control JAFFE, D H Operating Reactors Branch 3 84/08/02 LUNDVALL, A E Baltimore Gas & Electic Co 1p 26256 034 24% Fiche 50-317, 84/08/02, 8408240015
- --8408240017 Amends 96 & 77 to Licenses DPR-53 & DFR-69, respectively, reflecting administrative organization changes installation of add1 fire protection instrumentation & change in control of access to high radiation areas
  MILLER.J R Operating Reactors Branch 3 84/08/02 30pp
  26256 035 24X Fiche 50-317,84/08/02,8408240015
- ~-8408240020 Safety evaluation supporting Amends 96 & 77 to Licenses DPR-53 & DPR-69-respectively + Office of Nuclear Reactor Regulation, Director 84/08/02 3pp 26256 065 24X Fiche 50-317.84/08/02.8408240015

- B40B070110 Generic Ltr 84-19 to all licenses of operating reactors, applicants for OLs & holders or CPs re availability of Suppl I to NUREO-0933. "Prioritization of Generic Safety Issues." Svc list encl EISENHUT.D 6 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Ficho 50-000.84/08/06.84080/0110
- B40B200279 Generic Ltr B4~20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Bvc list encl
  EIBENNUT.D G Division of Licensing B4/0B/20 Consolidated Edison Co of New York, Inc 17pp 262/6 244 24X
  Fiche 90~000.B4/0B/20.B40B200275
- @ Inspection reports. IE Bulletins \* correspondence
- #408130298 Forwards IE Inep Repts 50-317/84-09 & 50-318/84-09 on B40423-27 & notice of violation MARTEN.T Y Division of Engineering & Technical Programs 84/07/18 LUNDVALL.A E Baltimore Gas & Electric Co 2pp 26074 334 24% Fiche 70-317.84/07/18,8408150298
- --8408130301 Notice of violation from insp on 840423-27 \* Region 1. Office of Director 84/07/18 2pp 26074 326 24X fiche 30-317, 84/07/18, 8408130278
- --0400150305 IE Insp Repts 50-317/84-07 & 50-318/84-09 on 840423-27 Noncompliance noted failure to have radiochemistry precedures reviewed by POSRC BIRUCKMEYER:R , JANG, J C , HOGAN,R T Region i, Office of Director 84/07/17 12pp 26074 338 24X Fiche 50-317.84/07/18, 8400150298
- 3408160102 Forwards IE Insp Repts 50-317/84-16 & 50-318/84-16 on B40604-08 & notice of violation MARTIN.T T Division of Engineering & Technical Programs B4/07/24 FUNDVALLA E Baltimore Gos & Electric Co 2pp 26108 135 24X Fichs 50-317.84/07/24.8408160102
- --B408160107 Notice of violation from insp on 840604-08 \* Region 1. Office of Director 84/07/24 ip 26108 137 24X Fiche 50-317,84/07/24.8408160102
- --B40Bi40115 IE Insp Repts 30-317/84-16 & 50-318/84-16 on 840404-08
  Violation noted failure to establish procedures for
  incomplete work followup on safety-related mod to auxiliary
  feedwater sys
  DL(MBERG,N, DETTENHAUSEN,L Region 1, Office of Director
  D4/07/12 12pp. 26108 138 24X Fiche 50-317,84/07/24,8408140102
- 0407250227 IC Info Notice 04-07. "Operating Experience re Moisture Intrusion in Gafety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JURDAN." L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/07/27 Consolidated Edison Co of New York, Inc. 119pp 20045 047 24X Fiche 50-000.84/07/27.8407250229
- 8408150711 Forwards IE Bafequerds Insp Repts 50-317/84-17 & 50-318/84-17 on 640611-15 & notice of violation MARTIN, T T Division of Engineering & Technical Programs 84/07/27 BOUNDAKER, N J Baltimore Gas & Electric Co 2pp 26079 017 24X Fiche 50-317.84/07/27.8408150711
- ~-B408190715 Notice of violation from insp on 840611-15 Safeguards info deleted (ref 10CFR73 21 & 9 5) MARTIN.T Division of Engineering & Technical Programs B4/07/27 1p 26079 019 24X Fiche 50-317.84/07/27.8408150711
- --8408150721 IE Bafeguards Insp Repts 50-317/84-17 t 50-318/84-17 an 8406(t-15 Noncompliance noted failure to follow physical security plan implementing procedures Info deleted (ref 10CFR73 21 t 7 5) BAILCY, R J., KEIMIG, R R. Region 1. Office of Director 84/07/27 6pp \$260/9 020 24% Fiche 50-317.84/07/27.8408150711.
- 8408070074 Forwards check inadvertently omitted from 840306 ltm re inservice insp program DENTON,R C Baltimore Cas & Electric Co 84/07/30 MILLER,J R Operating Reactors Branch 3 ip 25949 280 24x Fiche 50-317,84/07/30,8408070074
- B40B010333 IE Info Notice 84-57, "Deliberate Circumventing of Station Health Physics Procedures "Svc list encl URBANA E | Division of Emergency Preparedness & Engineering Response (Post 830107) 84/08/06 Consolidated Edison Co of New Yor), Inc 122pp 24068 001 24X Fiche 30-000,84/08/06.8408010333

- 8408010337 IE Info Notice 84-60. 'Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JURUSAN EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of his York, Inc. 123pp. 26067 158 244 Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Notice 83-61. "Overexposure of Diver in PNH Refueling Cavity " Svc list encl JORDAN, E.L. Division of Emergency Pieparedness ", Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York, Inc. 120pp 26129 118 24 (Fiche 50-000.84/08/08,840807)[2]
- 8408240361 Forwards Insp Repts 50-31//84-08 / 50-318/84-08 on 840411-0518 Significant safety contents to operability of component cooling HX identified Issue resolved pending followup to stated actions per 840517 meeting STAGDSTECKI.R Division of Project / Resident Programs 84/08/03 LUNDVALL.A E Baltimore Gas / Electric Co 2pp 26237 065 24% Fiche 50-317,84/08/08,8408240361
- --8408240343 lnsp Repts 50-317/84-08 & 50-318/84-08 on 840411-0515 Mijii areas inspected control room.accessible parts of plant structures, plant operations, radiation protection, physical security & fire protection. FOLEY, T. TRIMBLE, D. C. NENZINGER, E. C. Region 1, Office of Director 84/07/31 13pp 26237 067 24% Fiche 50-317, R4/03/(3-8408240361
- 8408070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list enc! ORACE, J N Division of OA, Bafeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000.84/08/10.8408070374
- B40B100007 IE Info Notice 84-63, "Defective RHR Replacement Piping" 8vc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of hir York, Inc. 119pp 26197-218 24X Fiche 50-000.84/08/13,840000000
- B408100038 IE Info Notice 84-64, "RWR HPCI Initiation Scal-In & Indication" Svc list encl JORDAN E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of No. York, Inc 104pp 26198 093 24% Fiche 50-000, 84/08/15, 84081003
- 8408100021 IE Info Notice 84-65. "Underrated Fuses Which May Adversity Affect Operation of Essential Electrical Equipment " 8vc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc. 1189p 26198 001 24X Fiche 50-000.84/08/16.840810021
- 8408100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwate: Train " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of his York, Inc. 120pp 26276 001 24X Fiche 50-000.84/08/17,8408100051
- B408140208 IE Info Notice 84-67. "Recent Snubber Inservice Testing W High Failure Rates " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of Mar Vork Inc 122pp 26276 122 24X Fiche 50-000,84/08/17. 840814023
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperty Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of No. York, Inc. 1155p 26327 008 24X Fiche 50-000,84/08/21,8408210147
- R Periodic operating reports & related correspondence
- 8408270535 Nonroutine radiological environ operating rept re levels of Ag-110m in ogster samples collected during June 1984 Dose rates within acceptable limits
  FURRMAN OR Baltimore Cas & Electric Co 84/07/31 Region |
  Office of Director 3pp 26279 227 24X Fiche 50-317,84/07/31,
  B408270535
- 8 Reportable occurrences, LFRs & related correspondence
- 8405290354 Forwards LASL draft rept on boron dilution event to determine safety significance of unmitigated boron dilution event Staff completion of review expected by 840515 JAFFE.D H Operating Reactors Branch 3 84/05/04 LUNDVALLAF Baltimore Gas & Electric Co 47pp 24675 275 24X Fithe 50-317.84/05/04.8405270354

- 8408010343 Forwards Engineering Evaluation Pept AFOD/E415, 'Overcooling
  - 103310343 Fulwards Engineering From 100 Control of Transport Trans
  - 8408010345 Engineering Evaluation Airpt ACOD/E415, "Overcooling
    - Transient 1 Transient 1 INBNO E Director S Urfice 84 06'06 5pp 25867 354 Fichs 50-31a, 84.06/06, 84.080)0343
- 8408150395 LER 84-00s-90 on 840'09, while in Mode 1, unidentified reactor OBJO0395 LER 84-006-00 on 840 '09 while in mode I unidentified react contant leading determined greater than I 0 gpm Caused by inservice ratique induced cracked wold Defective section of control bleedoff pips replaced W/840806 ltr DARLING 5 5, RUSSELL & B. Baltimore Gas \* Electric Co. 84/08/06 App. 26077 336 24% Fichs 50-318.84/08/06.8408150395
- 8408310365 Forwards "Events Involving Fires or Other Related Abnormalities in Motor Control Ctrs W/Aluminum Bus Bars," technical review rept Further actions relissue not warranted
- at present ASHLF Reactor Operations Analysis Branch 84/08/06 Si Reactor Operations Analysis Branch 1p 26/350 295 24X Fiche 50~317,84/08/06/8408310355 SEYFRIT K V
- --BioB310370 "Events Involving Fires or Other Related Abnormalities in Motor Control Ctrs W/Aluminum Bus Bars:" technical review
  - Reacto: Operations Analysis Branch 84/08/06 3pp 6 24X Fiche 50-317,84/08/06,8408310365 repr ASHE.F 26350 276
- B40B200492 LER P3-065/03X-1 on B31202 ' 10. erratic metrascope indication identified failed reed switch position transmitter stacks Stacks declared inoperable Transmitters replaced W/840B13 ltr RAYNDR.J W : RUSSELL.L B Baltimore Gas & Electric Co B4/2pp 26139 015 24X Fiche 50-310.84/08/13.8408200492
- 8408200512 LER 83-075/03X-1 on 831210 intermittent failure in 008200512 LER 83-0/5/03x-1 on B31230 intermittent Failure in metrascope control element assembly position indication systems. The same of the second of the 84/08/13
- 8408310042 LER 83 019703L-1 on 830909 pinhale leak discovered in reactor coolant charging line wild Caused by line vibration Restraint installed & repair cald completed W/840823 1tr PIERINGER, P. REID, K. RUSHELL, S. Baltimore Gas & Electric Co 84/08/23 3pp 26333 350 24% Fiche 50-318,84/08/23,8408310042
- DOCHET 50-320 THREE MILE ISLAND MUCLEAR STATION, UNIT 2 Security, medical, emergency & fire protection plans
- 8408390100 Rev 2 to Emergency Plan implementing Procedure 1054 28, "Activation of Technical Support Ctr " W/840803 transmittal ne General Public Utilitios – CPU Service Corp. 84/07/27 - 7pp 773 115 - 24x Fiche 50-320 84/07/27,8408090100
- 25973 115
- 8408060166 Forwards summary of present or proposed fine protection features for sys required to maintain or monitor cold shutdown.in response to 840518 request Tech Spec change not necessary, as present level of fire protection sufficient KANGA.B & General Public Utilities GPU Service Corp 84/07/3 SNYDER, B J TUI Program Diffice 80p 25725 277 24X Fiche 90-320.84/07/31.8408060166 84/07/31
- 8408140197 Revised emergency plan implementing procedures including Rey 11 to 1054 a re add1 assistance ! notification.Rev 6 1054 1 re unusual event & Rev 1 to 1054 20 re personnel/ vehicle monitoring & decontamination REAWER. J R Oeneral Public Utilities - GPU Service Corp 70pp 26044 258 24% Fiche 50-320.84/08/08.8408140197
- 8408230382 Rev 9 to Emergency Plan Implementing Procedure 1004 27.
  "Activation of Emergency Operations Facility "
  Operating Procedure 1998 Service Corp 84/08/08 31pp 26203 319 24% Fiche 50-289,84/08/08.8408230382
- 8408160160 Informs of refund of fees from 840727 application for exemption from certain annual exercise requirements of 10CFR50. App E & 840604 application to correct error in Tech Spec 3 6 7 Fee assessment into enc.]
  MILLER. W O License Fee Management Branch 84/08/10 HUKILL. General Public Utilities GPU Service Corp 3pp 26124 352
  Fiche 50-289. 84/08/10 8408160165

- 3408210320 Revised emergency plan implementing procedures, including 1094 36 re emergency assembly area 2 1099 re emergency preparedness drills WAB40814 transmittal memo & General Public Utilines - GPU Service Corp. 84/08/26179 127 24x Fiche 50-3/0.84/08/14.8408210320
- G Adjudicatory optrespondence
- 8498010209 Notice of issuance or amend to older modifying license requirements imposed by 800211 order 5 motion to conform proposed Tech Specs in accordance therewith Certificate of Svc encl CHANDLER,L J. Hearing Branch 2 DSB 675 84/07/25 / Safety and Licensing Board Panel /7pp 25856 056 24X Fiche 50-220.81/07/25.8408010209
- 8408030078 Memorandum 'order granting NRC 840718 motion to conform groposed Tech Specs w/Director.NRR 840615 amend of order Served on 840802 Served on 840802 MOLFE, J F Atomic Safety and Licensing Board Panel 84/07/31 Office of the Executive Legal Director 25907 001 24% Fiche 50-320,84/07/31,8408030078 DSR 726
- 8408070418 Response supporting staff 840725 motion to conform to proposed Tech Specs per 840717 amend of 800211 order Certificate of Svc encl RIDSWAY, D.A. Metropolitan Edison Co. RIDSWAY, D.A. Shaw, Pittman, Potts & Troubridge DS8 767 84/08/01 Atomic Safety and Litensing Beard Panel 5pp 25942 145 24% Fiche 50-320,84/08/01, 200807045 Licensing Board Panel 8408070418
- B40B070470 Response supporting IRC 840718 motion to conform proposed Tech Specs in accordance w/840615 amend of order recretraining & replacement training Certificate of Svc encl RIBGMAY,D A Metropolitan Edison Co. RIBBMAY,D A Shaw. Pittman, Potts & Troubridge DSB 764 84708701 Atomic Safety and Licumsing Board Panel Spp. 25941 195 244 Fiche 50-320,84708701, 8408070470
- 8408200380 Expresses dissatisfaction w/staff conclusions re author in Suppl 5 to NURCO-0680 concerning RCS leak rate tests Conclusion that author involved or implicated in indictment misleading t unfair NRC conclusions should not be adopted SEELINOFR, J L Affiliation Not Assigned DSB 163 84/08/09 PALLADINO.N J Commissioners 2pp 26137 138 24X Fiche 50-289,84/08/09.8408200580
- 8408140449 Petition for resocation of license on basis of deficient character (icensee record of wrongdoing directly related to fundamental character flaws inherent within company Certificate of Svc encl BAMBACH, P.C., SHUMAKER, J. Pennsylvania, Commonwealth of, BGRDILL, P. Wonen's International League for Peace & Freedom 00/ 84/08/13 Commissioners 200pp 24061 023 24X Fiche 30-000.84/08/13,8408140449 bsø
- 840B200521 Protests rer to author in Suppl 5 to NUREG-0680 as one of five util mgt personnel involved or implicated in indictment Starf accusation improper & damaging to author reputation Requests withdrawal of findings KUNDER: A Affiliation Not Assigned BGS 162 84/08/13 PALLADINO.N J Commissioners 2pp 26136 361 24x Fithe 50-287.84/08/13.8408200521
- 8408170291 Memorandum & order responding to NRC staff notice of issuance of arend of order & granting NRC staff motion to conform proposed Tech Specs in accordance therewith Berved on 840816

  MOLF.J F Atonic Safety and Licensing Board Panel DSB 093

  84708/15 Dffice of the Executive Legal Director App

  26115 117 24x Fiche 50-320.84/08/15.8408170291
- 8408240250 Forwards supplemental pages for 840813 petition for revocation of license of GPU on basis of deficient character DOROCHOW, J Three Mile Island Alert DSD 258 B4/08/22 Commissioners ip 26223 018 24% Fiche 50-000,84/08/22, 8408240250
- --B40B240257 Supplemental pages to petition for revocation of license on basis of deficient character Certificate of Svc enc)
  \*\* General Public Utilities GPU Service Corp 84/0B/13
  About Safety and Licensing Board Panel 43pp 26223 019 24X
  Fiche 50-000.84/08/22.8408240250

# H General correspondence

- B4080B00B. Responds to 819011 to to Fail ading commenting on 100FR50 54 permitting deviations from but Specs in one-gency through regulation be consoled lists circumstances which must exist before rule can be used DENTUN. HR Office of hother Healton Regulation. Director B4/07/26 YOUNG. Affiliation Not assigned 14pp 2597B 264 24X Fishe 50-320,84/07/26,84083800B2
- --B408080087 Reartires recommendations stated in B40\*03 ltm re canceling regulations permitting licensee to deviate from Tech Specs in energency 7 ensuring that president or facility implement policy to operate in accordance w/OL ! Tech Specs YOUNG.C Affiliation Not Assigned B3706/14 PALLADINO.N J Commissioners Bpp 25978 276 24x Fiche 50-320.84/07/26. B408080882
- 040809020 Urges cancellation of 10CFR50 51(1) & (y) Licensees should be required to follow Tech Specs when operating commercial nuclear power plants YOUNG C Affiliation Not Assigned 84/08/06 DENION, H.R. Office of Nuclear Reactor Regulation, Director 2pp 25971 241 24X Fiche 70-320,84/08/05,8408090220
- BACB220390 Protests untain treatment indicated in staff rept on NUREG-0680. Suppl 5 re facility restant Conclusions re RCS leak tests unfair Refusal to endorse NRC conclusions requested Hemo dtd 781020 to shift supervisors encl FLOYD. J R Affiliation Not Assigned 84/08/13 PALLADINO. N J Commissioners 2pp 2618\* 336 24x Fiche 50-289.84/08/13. 84080.20390
- 8408240225 Advises that all future correspondence to director of facility should be addressed to FR Standerfer KANGA.B K. General Public Utilities GPU Service Colp. 84/08/14 SNYBER:B J. TMI Program Office. Ip. 26236-313 24% Fiche 50~320.84/08/14.8408240225
- P Operating license stage documents / correspondence
- 8408310129 Requests elemption from provisions of LOCFR170 Elemption would allow diversion of necessary funds to facilitate expeditious cleanup operation Related correspondence KANGA, B.K. General Public Utilities GPU Service Corp. DSB 722 B4407/13 BIRGKS, M.J. Office of the Ficultive Director for Operations. 2pp. 26352 ORA. 24% Ficha 50-320,84/07/13,8408310129
- 8408010349 Forwards safety review of head removal orogram.per 840309 request for approval Program acceptable BNYDER.B J THI Program Diffice 84/07/17 KANGA.B K General Public Utilities GPU Service Corp 3pp 25870 335 24X Fithe 50~320,84/07/17.8408010049
- --8408010051 Safety review of head removal program Program acceptable # TM1 Program Office 84/07/17 37pp 25878 338 24X Fiche 50-320.84/07/17/8408010049
- 8408010105 Concurs w/util request to delete requirement for isolation of reactor bldg air coolers during load handling operations. Util should submit for approval procedures implementing cooling water & boron limits.

  GRANT.P J TMT Program Diffice 84/07/17 KANGA, B K General Public Utilities GPU Selvice Corp. 1p. 23873 359 24X

  Fiche 50-320.84/07/17.8408010105
- 8408030211 Advises that requests for exemption from 100FR50, App A, Critorien 36 acceptable Uminor changes Alternate design should be applied to requirements of Critorian 55, PRCPB Ponetrating Containment "SNYDER, B J THE Program Office 84/07/17 KANOA, B K General Public Utilities GPV Service Corp 3pp 25921 279 24X Fiche 30~320,84/07/17,8408030211
- --8408030215 Amend of order modifying proposed Tech Specs by incorporating or modifying specs required to be in place before reactor vessel head removed BENTON, H.R. Office of Nuclear Reactor Regulation, Director 84/07/17 General Public Utilities 6PU Service Corp. 6pt 25921 282 247 Fiche 50-320,84/07/17,8408030211
- --B408030218 Exemption from requirements of 10CFR50. App A. Criteria 2. 30 & 31 Exemption does not authorize change in effluent types or total amounts nor increase in power level & will not result in any significant environ impact DENION, H R OFFICE of Nuclear Reactor Regulation, Director B4/07/17 General Public Utilities 0PU Service Corp 5pp 25721 288 24% Fiche 50-120.84/07/17.8408030211

- --8403030 Connects a alcot on the literal of altrinate disign for 10006450 applies there is \$ 4.55 to consequently or attention acceptable a This tray and define the or 12. The Small 254 247 Faile 50-420 pd of 32 Herbothall
- --BAOGOBOLIST Expytion from the comment, or locally of Apple Criterion 57 Examption does not authorize things in effluent types or total amount nor increase in point level will not result in any significant while timpact DENION H.R. (Herica et al.) in Results began to the BAOOT 17 General Point (Hillitz CPU Service Corp., Apple 25921 278 (4x Fiche 5, 350 dd 67 ) single 30011
- --B40B020c20, Saring evaluation supporting licenses request for revior proposed lesh Spices reconstruction integrity code afternatur loss-roughlish botton contentration, control assemblies \* maurion non-furing instrumentation suffice of Nuclear Reactor hegulation Director B4/07/17 lipp 2597, 201 2.x Fichs 50-320 B3/07 17/840B030211
- --8403030^28 Proposed Tech Special tellsing containment integrity, change calibia, changed chack, controllers to meeting monitoring concentration for its assembles to meeting monitoring instrumentation

  > NRC recovaled Affiltation Given 84/07/17 27pp 25921 315 207 Fiche 50 364,0440017,8088030211
- --B408030231 North of environ assessment % findings of no significant environ impact liansrittal forms entl winds entl winds entl winds entl winds entl winds ently and environment of the second of t
- B408010100 Concor. willrenset assertions in definition of transfer of gazoous radwarts. Tech Sper. do not require shotdown of air filtration/yearfactor sys when auxiliary % fuel handling syr down GRANT,P = 101 Program Office B1/0\*\*26 KANGA B K General Public Utilitie, GPU Servic Lorp tp 25873 360 24% Fiche 50m320,84707/20 B408010100
- B40BJ10090 Forward- Her 21 to a rotally aperations plan in response to Recovery Operations Plan Change Requests 20 / 22 to deletion of operating pressure band for standby pressure control systimate vict nutragen supply bank ORANT.P J Thi Program Orfice 60/07/23 KANGA, B K General Public Utilifies 600 Settles Corp 4pp C5897 067 24X Fichs 50-3-0.0446/2 23 813dut/07/0
- B40B110212 Responds to B4053; 7 0716 Its forwarding safety evaluation & addendum describing addit hardward improvements to support proposed operation of internals index fixture water processing systems of internals index fixture water groupscing systems of internals index fixture water processing systems of internals index fixture water processing systems of internals of internal of internals of internal of internals of internals of internals of internals of internal of internals of internals of internals of internals of internal of internals of internals of internals of internals of internal of internals of internals of internals of internals of internal of internals of internals of internals of internals of internal of internals of internals of internals of internals of internal of internals of int
- B40B01032B Informs that licensee mods to reactor bidg polar crane trolled limit cuitches' bumps; staps conform to AMSI
  B30 2 1976' screptable Encl licensee safety evaluation also acceptable
  POLYNDEXTER. ( IIII Program Office 84/07/24 TMI Program Office 1p 25472 3/5 24x Fiche 50-320,84/07/24 8408010328
- --8408010327 Forwards "Safety F. Juation to Polar Crane Irolley Limit Suitch Bypass % Bumper Mod ' per NRC request Mods pormit reactor wessel hand to be contelled over storage stand prior to lowering into positioning for storage RUBAN.R E General Public Utilities GPU Service Corp 84/06/13 BARRETICL & THE Project Office of P. 25877 306 24% Fiche 50-375, 84/07/24, 8408010328
- --8408010331 "Sarety Evaluation for Polar Crame Trolley Switch Bypass & Bumper Mod " \* \* General Public Utilities - GPU Service Corp 94/06/13 Spp 25872 307 24X Fichs 50-320 84/07/24.8408010328
- 8408010209 Notice of issuance of amend to order modifying license requirements imposed by 80%\_1) order \* motion to conform proposed Tech Specs in acceptance the ewith Contificate of Sverenti CHANDLERL / Hearting Branch 2 DSB 675 84/07/25 Atomic Bafety and Licensing Board Panel 7/pp 20856 096 24X Fiche 50-320.847/07/25.840 000020
- 8408030141 Responds to 840702 itr requesting Class III fee for polar crane 648 approved in NRC 841118 ltr fee encl KANGA.B & General Public Utilities - GPU Service Corp 84/07/27 DIGGS.R M Litewise Foe Management Branch 1p 25916 136 24X Fishe 50-320.01/07/27.8100030141

- 8408050253 [enies 840 2] require to exceed 170-ton crane load limit on
- contingency bests
  SMFDER B J THI Program Diffice 84/07/27 MANGA, B K Ger
  Public Utilities CPU Ser it. Corp. 2pp. 25950-347 24X
  Fiche Sm 320-84/07/27.81080b00°53
- 8408070083 fundations on SER transmitted in 640618 ltm or preparatory activities for planum assumbly removal Environ effects of planum insplacious small ? do not warrant further
  - revisu SNYDLR.B U fil Program Office 84/07/51 KANGA.B K Ger Public Utilities GPU Service Corp. 3pg. 25955-254 24X Fiche 50-390 &4 07/31/640a0/7034a General
- B40B070110 Generic Ltt B4-19 to all licensees of operating reactors, applicants for GLs & holders or CPs to availability of Suppl 1 to NUREG-M933, "Prioritration of Generic Safety Issues 'Svo list oncl EISFN:U1.D G Division or Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche S0-000 84/08/06.8408070110
- 8406140279 Requests concurrence w/encl mod to SER re Fuel Pool A refurbishment Section 3 i revised as applied to decontamination of lower tanks lanks currently being flushed
- & decontaminated KANDA, B K General Public Utilities GPU Service Corp SNYDER, B J TMI Program Office 4pp 26054 360 24X Fiche 50-320.84/08/06.8408140279 84/08/06
- B40B160035 Invoiris that util plans to prepare general safety evaluation to expand safe load path boundaries in reactor bldg Evaluation util be submitted for review by 841001 KANGA, B K General Public Utilities GPU Service Corp 84/08/10 SNYDEN.B J fill Program Office 2pp 26092 050 24X Fiche 50-320,84/08/10,8408160035
- 8408160042 Advises of review or Rev 4 to general project design criteria for facility Design criteria does not relieve util from requesting exemptions from 10cFR10
  SNYDER, B J TMI Program Office 84/08/10 KANGA, B K Gener Public Utilities GPU Service Corp 2pp 26128 171 24X
  Fiche 50-320,84/08/10,8408160042
- 8408300233 Notification of contract execution, Nod 2, to "Clinical Response to Chronic Stress in TMI" Contractor Uniformed Svcs Univ of Health Sciences
  HCYLC A Administrative Contracts Branch FIN B-8008 84/08/
  VOLLMER.R H Division of Engineering CLEARY, D P NRC No Detailed Affilation Given 1p 26315 361 24X
  Fiche 50-289,84/08/14.8408300233 84/08/14
- --8408300237 flod 2.evi-noting period of performance to 840915, to "Clinical Response to Chronic Stress in TMI" BAVM.A Unitormed Services Univ of Health Sciences HAGAN,T Division of Contracts FIN 8-8008 84/08/14 ip 26315 362 24X Fiche 90-289 84/08/14,8408300233 HAGAN, T. F.
- B408280J41 Confirms into provided in still 840618 for re-plenum removal preparatory activities it requests additions necessary to complete review SNYDLM.B J. Fitt Program Office 84/08/15 KANGA.B K. General complete review SNYDER: B J - THI Program Office - 84/ Public Utilities - GPV Service Gorp Fiche 50 J20.04.08 15.0400200341 84/08/15 KANGA, BK Ge arp 4pp 26294 037 24 X
- 8408100021 IE Info Motice 84-55, "Undertated fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc
  - Affect Operation or Costine 1. Its encl
    JGRDAN,E L Division of Emergency Preparedness & Engineering
    Response (Post B.J.103) 84/08/16 Consolidated Edison Co of New
    York, Inc. 118pp 26198 001 24% Fiche 50-000,84/08/16,8408100021
- 8408220444 Accepts resignation from Advisory Panel on Decontamination of IMI-2 Expresses appreciation for & recognition of contributions hade to activities of panel while serving as
  - member since 1980 PALLADINO.1: J (unmissioners 44/08/16 HAGNER, H N Johns Hopkins Medical Institutions, Baltimore, MD 3pp 26201 391 24X Fiche 50-320,84/08/16.8408220444
- --R408220448 Subnits ltr of resignation from Citizen Advisory Panel on Decontamination of IMI-2 WAGNER: H N Johns Hopkins Medical Institutions, Baltimore, MD WAGNER: H N Advisory Council for Decontamination of TMI Unit 2 84/07/09 PALLADINO.N J Commissioners Ip 26201 354 24X Fiche 50-320,84/08/14,8408720441
- 84082002/9 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Sic list enri EISENHUTID G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 1769 26276-244 24X Fiche 50-000,84/03 20,8408200275

- 8408270493 Returns check remitted in payment of 840713 request for exemption from the projectors of 100FR170 Check returned since 100FR170 dues not provide for recovery fees for Part 170 exemption requests MILLER. O License Fee Management Branch 84/08/20 KANGA General Public Utilities - GPU Service Corp ip 26277 061 Fiche 70-320 81/08/20.8408270493 KANGA, B.K
- 8408300031 Rev & to Emergency Plan Implementing Procedure 1054 8. "Callout of Onsite % Offsite Duty Roster Personnel " W7800073 transmitted litr BEAVER. J. General Public Utilities GPU Service Corp. 19pp. 26306 009 24) Fiche 50-320.84/08/23.8408300031
- 8408310238 Forwards "Revieu of Dose Assessments at TMI & Recommendations for Future Research " Printed rept summaries & 840829 press release enci JERGER, D. Berger, D. 84/08/27 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 7pp 26316-293 24X Fiche 50-289,84/08/27,8408310238
- --8408310237 "Raviow or Dose Assessments at IIII t Recommendations for Future Research" BEYEA.J TMI Public Health Fund 84/08/15 270pp 26316 300 24X Fiche 50-289,84/08/27,8408310238
- & Inspection reports. IE Bulletins & correspondence
- B408070203 Recommends minor revs after reviewing encl draft info notice ()/o encl MILDEBRAND, J E General Public Utilities - GPU Service Corp 84/04/30 BAER,R L Engineering & Generic Communications Branch 3pp 25957 064 24/ Fiche 50-320,84/04/30,8408070203
- 8408100130 Advises that approval & implementation of sys upgrade for tracking specific radiation exposures originally acheduled for completion by 840801 delayed until 840903 because of accelerated reactor vessel head lift schedule KANGA, B K General Public Utilities GPU Service Corp 84/07/25 MURLLY, T E Region 1. Office of Director 2pp 25988 279 24X Fiche 50-320,84/07/25,8408100130
- 8407250729 IE info Notice 84-57. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 6301073) 84/07/27 Consolidated Edison Co. of New York, Inc. 119pp 25865-047 248 Fiche 90-000,84/07/27,8407250229
- 8408010333 IE Info Notice 84-59. "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JDRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333
- B408010337 If Info Notice B4~60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN. G. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York. Inc. 123pp 26067 138 24% Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Info Notice 84-61. 'Overexposure of Diver in PWR Refueling Cavity "Svt list end June Preparedness & Engineering Rossonse (Post 830)03) 84/08/08 Consolidated Edison Co. of New York, Inc. 120pp. 26129 118 24X Fiche 50-000-84/08/08,8408070120
- 8408070376 IE Info Notice 84~62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list encl QRACE.J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24% Fiche 50-000,84/08/10.8408070376
- 8408300374 Forwards Insp Rept 90-320/84-13 on 840825-0619 Apparent violation being considered for appropriate enforcement action Enforcement conference scheduled for 840817 in Region action Birrorteness to the second sec
- --8408300381 Insp Rept 50 320/84-13 on 840529-0619 Violation noted failure to close & deactivate inboard isolation valve on Purge Frain A? Continuing to purge though Train A w/authoard isolation valve inoperable CODK. R. THONUS, L. FABANO, A. Region 1. Office of Director 84/07/30 4pp 26308 163 24X Fiche 50-320.84/08/10.8408300374

- 8408100007 [E Into Notice 84-63, 'Detective RMR Replacement Piping "

  "You list enc!
  JORDAN, E L Division of Emergancy Preparedness ! Engineering
  Response (Post 830103) 84-03/13 Consolidated Edison Co of New
  York, Inc 117pp 26197 218 24X Fiche 50-000,84/08/13,8408100007
- 8408100038 [E Info Notice 84-64, 'BUR HPCI Initiation Seal-In & Indication "Syc list encl Indication "Syc list encl JORDAN, E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York Inc 104pp 26198 093 24% Fiche 50-000,84/08/15,8408100038
- B408280076 Provides add1 response to 1E Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller. Inc." per NRC 840618 ltr Measures taken to identify problems w/vendor GA program outlined KANGA.B K Goneral Public Utilities GPU Service Corp B4/08/15 MURLEY.T E Region 1. Defice of Director 3pp 26261 207 24X Fiche 50-320,84/08/15,8408280074
- 8408100055 lE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JCRDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc. (20pp. 26276 001—24% Fiche 50-000,84/08/17,9408100055
- 8408140208 IE Info Notice 84-67, "Retent Snubber Inservice Testing W/ High Failure Rates " Svc list enc! JURBAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 122pp 26276 122 24X Fiche 50-000.84/08/17, 8408140208
- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21. Consolidated Edison Co. of New York, Inc. \$15pp. 24327 008 24X Fiche 50-000,84/08/21,8408210142
- R Periodic operating reports & related correspondence
- 8408090334 "TM1 Aquatic Study Monthly Rept for June 1984 " W/GPU 840717 ltr 
  # EA Engineering, Science & Technology, Inc 
  Public Utilities OPU Service Corp 
  84/06/30 
  HICKEY.C 
  NRC No 
  Detailed Affiliation Given 
  14pp 
  14
- B408010035 Forwards TM1 Program Dfc weekly status rept for wk of B40715-21 GRANT,P J THI Program Office 84/07/23 DENYON,H R Office of Nuclear Reactor Regulation, Director SNYDER,B J THI Program Office lipp 25866-324 24X Fiche 50-320,84/07/23,8408010055
- 8408070292 Forwards TMI Program DFc weekly status rept for wk of 840722-28 GRANTP J TMI Program Office 84/07/30 DENFON,HR Office of Nuclear Reactor Regulation, Director ENVDER 8 TMI Program Office 8pp 25957 036 24X Fiche 50-320.84/07/30.8408070252
- 8408090555 Forwards TMI Program Ofc weekly status rapt for uk of 840729-0806 ORANT,P J TMI Program Office 84/08/06 DENTGN.H R Office of Nuclear Reactor Regulation, Director SNYDER,B J TMI Program Office 11pp 25983 210 24x Fiche 50-320.84/08/06.8408090555
- 8408230425 Submits YMI Program Ofc weekly status rept for 840805-11 GRANT,P J TMI Program Office 84/08/13 DENTON.H R Office of Nuclear Reactor Regulation, Director EMVDER, B J TMI Program Office 12pp 26230 229 24X Fiche 50-289, 84/08/13, 8408230425
- B408240394 Forwards TMI Program Oft weekly status rept for wk of B40812 TRAVERS,W D TMI Program Office 84/08/20 DENTON,H R Office of Nuclear Reactor Regulation, Director SNYDER, B J TMI Program Office 8pp 26249 342 24x Fiche 50-320,84/08/20,8408240394
- B Reportable occurrences, LERs & related correspondence
- 84080:0170 PND-THI-B4-C0BB on 840724, reactor vessel closure head set down on storage stand Placement accomplished by use of pry bar & winch attached to containment wall NRC will be supplied w/24 h/day coverage until fixture in place FABANO, A. CRANI.F. THI Program Office 84/07/25 ip 25855 320 24x Fiche 80-320.84/07/25.8408010170
- 3408010174 PNO-THI-84-008A on B40724 reactor vessel closure head lifted clear of reactor vessel flange Licensee devising means of aligning vessel head wistorage stand guide pins in preparation for lowering head to stand CODK, R. FASANO, A. ORANT, P. TMI Program Office 84/07/25 ip 2585 321 24% Fiche 50-320,84/07/25,8408010174

- 8408010220 PNU-TMI-84-OVBD on 64072c, lead shield platform put in place over top of internals indexing filture While lowering shielding criane failed Licensee manually unscrewed lifting turnbuciles until platform made contact COOK, R. FASAND, A. GRANI P. TMI Program Office 84/0//26 Ip 25855 026 24% Fiche 50~320.84/07/26.8408010220
- 8408010P30 PND-THI-84-008C on 840726, licensee lifted internals indering fixture w/polar crane & lowered fixture into place on reactor vessel flange Containment purging initiated CODK, R. FASAND, A. GRANT, P. THI Program Office 84/07/26 ip 25856 018 24% Fiche 50-320.84/07/26.8408010230
- 840B050310 LFR 84-010-00 on 840528 several containment isolation valves opened w/o required unit work instruction approvals Personnel will be briefed on event 8 need to obtain required approvals M/840726 itr SHART/HELDER, R. AAHGA, I. K. General Public Utilities GPU Service Corp 84/07/26 4pp 25736 044 24x Fiche 50-320, 84/07/26. 8408060310
- 8408200115 LER 84-011-00 on 840713.control room air inlet radiation monitor interlock placed in defeat Caused by personnel error Personnel reprimanded W/840810 ltr CHAPLIN.S D., KANGA.B K. General Public Utilities GPU Service Corp. 84/08/10 Spp. 26140 225 24X Fiche 50-320.84/08/10, 8408200115
- T Hearing transcripts on non-antitrust matters
- 8408020946 Transcript of 840712 meeting in Harrisburg.PA Pp 1-113 Supporting documentation enc) \* Advisory Council for Decontamination of TMI Unit 2 84/07/12 183pp 25883 316 24% Fiche 50-320,84/07/12,8408020046
- B408270096 Transcript of TMI Advisory Panel on TMI Unit 2
  Decontamination on 840809 public meeting in Harrisburg, PA
  Pp 1-33 Supporting documentation encl
  \* Advisory Council for Decontamination of TMI Unit 2 84/08/09
  138pp 2625/ 048 24X Fiche 50-320,84/08/09,8408270096
- U Congressional/Executive Correspondence
- B408270154 Accepts resignation as member of Advisory Panel for Decontamination for TMI-2 Certificate of appreciation encl PALLADINO, NO Commissioners B4/08/14 MAGNER, H N Affiliation Not Assigned 2pp 24311 340 24X Fiche 50-320,84/08/14.
- DOCKET 50-321 EDWIN | HATCH NUCLEAR PLANT, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8408300436 Forwards FEMA exercise rept for 831013 exercise BANCE, H C Region 2. Office of Director 84/05/07 KELLY, R J Georgia Power Co 1p 26311 247 24X Fiche 50-321,84/05/07. 8408300436
- --8404040322 Forwards FEMA 840124 ltr forwarding FEMA Region IV rept of 831013 joint exercise Recommends exercise rept be transmitted to licensee / coordination W/FEMA Region IV be continued to ensure deficiencies identified corrected JURINAVIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/13 STONE, J.P. Division of Emergency Preparedness & Engineering Females of Preparedness & Materials Safety 2pp 26314 248 24X Fiche 50-321,84/05/07.8408300436
- 8408303352 Confirms arrangements made on 840524 between JT Beckham & HC Dancs re 840531 enforcement conference in Region II ofc to discuss 840532 security event re access controls & events leading to inoperability of HPCI Agenda encl
  O'REILLY, J P Region 2, Office of Director 84/05/25 KELLY, R J Georgia Power Co 2pp 26314 147 247 Fiche 50-321,84/05/25,840830332
- 84083003/6 Forwards summary of 840530 meeting w/utils & INPO re salected emergency preparedness issues Attendance list also encl O'REILLY, J P Region 2, Office of Director 84/06/08 KELLY,R J Georgia Power Co 4pp 26308 237 24X Fiche 50-000,84/06/08, 8408300376
- 8408310097 Documents training & experience for evaluation team members, per 840723 ltr re training requirements for NRC & contract personnel observing 840802 emergency exercise DANCE.H C Region 2. Office of Director 84/07/24 KELLY.R J Georgia Power Co. 2pp 26333 332 24X Fiche 50-321,84/07/24, 8408310057

- BAOBJ30163 Revs to energency plan implementing procedures, consisting of Rev 4 to HNP-8024 "(n-Plant Radiation Level Monitoring" t Rev 1 to HNP-8061 'Eberline Model PCM-1 Portal Monitor Operation 'Calibi 'W/B40/31 ltr SDRRELL.C C Georgia Pover Co 84/07/31 JBpp 25912 022 24X Fiche 50-321.84/07/31.8408030163
- B40B130302 Responds to 840302 ltr.supplemented by 840413 ltr.requesting exemption from App E to 10CFR50.excluding state & county participation in 840B02 exercise Requested exemption unnecessary New rule requires participation every 2 yrs STULZ.JF Operating Reactors Branch 4 84/08/01 BECKHAM.JT Georgia Fower Co Spp 26040 331 24x Fiche 50-321.84/08/01.8408130302
- 8408070207 Notification or 840808 meeting w/util in Bethesda.MD to discuss approach for interim measures associated w/schedular exemption request for implementation of App R mods RIVENBARK.G Operating Reactors Branch 4 84/08/03 STOLZ,J F Operating Reactors Branch 4 2pp 25984 360 24X Fiche 50~321,84/08/03.8408070207
- 8408130379 Responds to 840717 request for add1 info re submittal of safety parameter display sys info Foxboro Procedures QDAAAD4 % QDAAB44, containing isolation devices pass/fail acceptance criteria.encl GUCNA.L T Georgia Power Co 84/08/07 STOLZ.J F Operating Rejecture Branch 4 3pp 26008 203 24X Fiche 50-221,84/08/07,8408130379
- 8408170258 Rev 7 to Emergency Implementing Procedure HNP-4852, "Offsite Bose Estimations" W/840814 1tr # Georgia Power Co 84/08/14 46pp 26115 297 24X Fiche 50-321.84/08/14, 8408170258
- 8408210472 Revised emergency plan implementing procedures including Rev 2 to FNP-2-4705 re turbine lube oil reservoir Rev 4 to HNP-4212 re emergency diesel generator bldg & Rev 3 to HNP-1-4216 re reactor bldg Elevation 203 fires W/840816 ltr NIX.H . SQRRELL,E C Georgia Power Co 84/08/16 246pp 26149 084 24X Fiche 50-321.84/08/16.8408210472
- B40B280233 Revised energoncy plan implementing procedures, including Rev 1 to HNP-1-4261 re south CRD & essential MCC area fires & Rev 1 to HNP-1-4263 re reactor water cleanup pump room fire W/B40B24 ltr
  NIX.H . SURRELL, E C Georgia Power Co B4/08/18 75pp 26269 125 24X Fiche 50-321, 84/08/18, 840B280233
- 8408270301 Rev 21 to Emergency Plan Implementing Procedure HNP-8008, "Radiation Work Permit" W/840921 ltr SDRRELL,E C Opergia Power Co 84/08/21 20pp 26240 337 24X Fiche 30-321,84/08/21,8408270301

#### I Financial information

- 8408300072 Forwards draft in furtherance certificate Approval requested in order to meet Internal Revenue Svc requirements for tax-exempt pollution control revenue bonds OUCHALI Georgia Power Co 84/08/20 STOL2. J Operating Reactors Branch 4 4pp 26/205/357 24% Fiche 50-321.84/08/20.8408300072
- P Operating license stage documents & correspondence
- 8408310021 Confirms 840514 telcon re 840521 meeting in Region II ofce to discuss planned mod to rod block monitoring sys at facility LEWIS.R C Region 2. Office of Director 84/05/16 KELLY.R J Georgia Power Co ip 26335 014 24X Fiche 50-321,84/05/16, RADRA10821
- 6408300320 Cunfirms 840522 telcon between J Badgett & H Dance re arrangements nade for R Hartin.Region II.Deputy Regional Administrator, to attend 840628 presentation of certificates to licensed operators LEWIGR C Region 2. Office of Director 64/05/29 KELLY.R J Georgia Power Co ip 24308 328 24X Fiche 50-321,84/05/29.
- 8408310052 Forwards summary of 840931 meeting in Region II ofcs re HPCI sys Meeting beneficial & provided better understanding of Issue LENIS:R C Region 2, Office of Director 84/06/08 KELLY,R J Georgia Power Co 3pp 26333

- 8408300421 Forwards summary of 840521 meeting w/otil in Region II ofter APRK sys block monitor sys t. Tech Spec activities proposed for Liceness DPR-57 & NPF-5 Attendante list encl LEWIS.R C Region 2. Office or Director 84/06/22 KELLY.R J Georgia Power Co 4pp 26314 217 24X Fiche 50-321.84/06/22, 8408300421
- B40807014B Notifies or potential equipment qualification problems re 10CFR50 49 equipment qualification deadline Problems result from inability of PYCO, Inc. to provide qualification for resistance tomp detectors in use GUCWALL 1 Georgia Power Co B4/07/19 STOL2.JF Operating Reactors Branch 4 3pp 25949 273 24X Fishe 50-321,84/07/19, B40807014B
- BAOBOSO178 Informs of review of responses to Generic Ltr 83-02 re Tech Specs for NUREG-0737 Frens which were to be implemented by B11231 Tech Specs for Item II E 4 2 7 have not been provided Response requested within 30 days STDL2.JF Operating Reactors Branch 4 84/08/01 BECKHAM.JT Georgia Power Co 2pp 25978 342 24X Fiche 50-321,84/08/01, B408080178
- B40B130B61 Application for amend to Licenses DPR-B7 & NPF-5, revising radiological effluent Tech Specs (RETS) by transferring RETS from App B to App A & including editorial & administrative changes & changes based on NRC comments
  BECKHAM, J T Georgia Power Co B4/0B/01 STDLZ, J F Operating Reactors Branch 4 Jpp 26031 001 24% Fiche 50-321.84/0B/01, B40B130561
- --8408130567 Proposed Tech Spec changes, transferring radiological effluent Tech Specs from App 8 to App A 
  \* Georgia Power Co 84/08/01 190pp 26031 004 24X 
  Fiche 50-321,84/08/01.8408130561
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of 8uppl 1 to NUREQ-0933, "Prioritization of Generic Bafety Issues " Svc 1st enci EISENHUI, D O Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000,84/08/06,8408070110
- 8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
  TREMBLAY,P P Operating Reactors Assessment Branch 84/08/06
  HDC.AHAN,G M Operating Reactors Assessment Branch 13pp
  25991 350 24X Fiche 50-000.84/08/06.8408090317
- B40B140106 Application to amend Licenses DPR-57 & NPF-5, changing Tech Specs to reflect implementation of TM1 Item II B 3, "Past-Accident Sampling Capability "Fee and BECKHAM, J T Georgia Power Co 84/08/07 STOLZ, J F Operating Reactors Branch 4 2pp 26051 252 24X Fiche 50-321, 84/08/07, 8408140106
- --8408140124 Proposed Tech Spac changes re pust-accident sampling & analysis & iodine monitoring # Gaurgia Power Co. 84/08/07 Spp. 26051\*254 24X Fiche 50-321,84/08/07.8408140106
- 8408210474 Provides info in support of 840806 request for proposed Tech Spec change re containment isolation valves Request should be treated as emergency request to avoid undue delay in unit startup GVCMA.L T Georgia Power Co 84/08/14 STDLZ.J F Operating Reactors Branch 4 2pp 26181 125 24X Fiche 50-321,84/08/14, 8408210474
- BAOB210357 Responds to 840801 itr re NUREG-0737. Item II E 4 2(7), "Purge 2 Vent Valve Isolation " Revs to Unit 2 Tech Specs expected to be submitted by 840905 Unit 1 mods will be completed during scheduled Fall 1984 refueling outage QUCWA.L T Georgia Power Co 84/08/16 STOLZ.J F Operating Reactors Branch 4 2pp 26180 241 24X Fiche 50-321,84/08/16,8408210357
- 8408230251 Requests extension until 841107, to respond to request for info re reliability & upgrading of diesel generators, per Oeneric Ltr 84-15 Extension due to workload at site for Unit 2 recirculation pipe replacement outage GUCHA.L T Genrgia Pawer Co 84/08/16 STOLZ, J.F. Operating Reactors Branch 4 2pp 26207 293 24X Fiche 50-321, 84/08/16, 8408230251
- 8408200275 Generic Ltr 84-20 to all licensess of operating reactors & applicants for OLs re scheduling guidance for licenses submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT, D & Division of Licensing B4/08/20 Consolidated E41son Co of New York, Inc. 17pp 26276 244 24X Fishe 50-000, 84/08/20, 8408200275

- 8408300024 Requests and to distribution for all plant correspondence Distribution page of recent Tech Spec amend o/requested change encl
  - emange enci GUCHA, L T Georgia Power Co 84'08/22 \$TOL2, J F Operating Reactors Branch 4 2pp 26359 183 24% Fiche 50-321,84'08/22, 8408300024
- Q Inspection reports: IE Bulletins \* correspondence
- 8408240356 Forwards Insp Repts 50-321/81-21 \*, 50-366/84-21 on 840611-15 No violations or deviations noted DAMCE.H C Region 2. Office or Director 84/07/10 KELLY.R J Georgia Power Co 2pp 26237 040 24% Fiche 50-321.84/07/10, 8408240356
- --B40B240359 Insp Repts 50-321/84-21 t 50-364/84-21 on 840611-15 No Violations or deviations noted Major areas inspected worker concerns re Newport News Industries recticulation pipe replacement project MERRIMEATHER.N. CONLON.T E Region 2. Office of Director 84/07/09 10pp 26237 042 24K Fichs 50-321.84/07/10.8408240356
- 8408240364 Forwards Insp Repts 50-321/84-23 % 50-366/84-23 on 840618-22 No violations or deviations noted Unresolved Items identified will be pursued during future insps DANCE.H C Region 2. Office of Director 84/07/11 KELLY.R J Georgia Power Co 2pp 26237 080 24% Fiche 50-321,84/07/11,8408240364
- --8408240366 Insp Repts 50-321/84-23 t 50-366/84-23 on 840618-22 No violations or deviations noted Major areas inspected evaluation of ultrasonic test indications in feedwater weld 2821-1FM-12AA-12 (Unit 2) CROWLEY, B R . COLEY, J L . BLAKE, J J Region 2. Office of Director 84/07/10 12pp 26237 082 24X Fichs 50-321.84/07/11.
- 8408280239 Advises of plans \* schedules for replacing HFA relays in reactor protection \* safety sys.per IE Bulletin 84-02 GUCMA.L T Georgia Power Co 84/07/13 D'REILLY.J P Region 2. Defice of Director 4pp 26262 237 24X Fiche 50-321,64/07/13. B408280239
- B40B270241 Ack receipt of 840707 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-321/84-13 & 50-36/44-13 LEMISHR C Division of Ploject & Resident Programs 84/07/20 KELLY,R J Georgia Power Co ip 26259 096 24X Fiche 50-321.84/07/20.8468270241
- --8408270247 Responds to NRC 840507 itr re violations noted in Insp Repts 50-321/84-13 & 50-364/84-13 Corrective actions GC dept will witness significant activities for safety-related major maint GUCWALL T Georgie Power Co 84/07/09 G'REILLY, J.P. Region 2, Gffice of Director 3pp 26258 087 24% Fiche 50-321,84/07/20,8408270241
- --B408270235 Forwards Insp Repts 50-321/64-13 & 50-366/84-13 on B40321-0420 & notice of violation LEMIS:R C Division of Project & Resident Programs 84/06/07 KELLY:R J Georgia Power Co 2pp 26258 090 24X Fiche 50-321,84/07/20,8408270241
- --8408270269 Insp Repts 50-321/84-13 & 50-366/84-13 on 840321-0420 Violation noted failure to restore sys to original design requirements CRLENJAK, R V , RAY-HOLMES, P , GARNER, L Region 2, Office of Director 84/06/05 7pp 26258 094 24X Fiche 50-321,84/07/20,8408270241
- --8408270261 Notice of violation from insp on 840321-0421 \* Region 2. Office of Director 84/05/07 2pp 26259 092 24X Fiche 50-321.84/07/20.8408270241
- 8408270334 Forwards Insp Repts 50-321/84-25 % 50-366/84-25 on 840619-22 Na violations or deviations nated DANCE, H C Region 2. Office of Director 84/07/20 KELLY, R J Georgia Power Co 2pp 26257 206 24X Fiche 50-321, 84/07/20, 8408270334
- --8408270338 Insp Repts 50-321/84-25 % 50-364/84-25 on 840619-22 No violations or deviations noted Major areas inspected review of local leak rate test program % followup of previous violation WHITEMEN, H L , JAPE, F Region 2, Office of Director 84/07/19 6pp 26257 208 24% Fiche 50-321,84/07/20,8408270334

- 8407250229 IE Info Notice 84-57. 'Operating Eiperlence is Moisture Intrusion in Safety-Related Flectrical Equipment at Commercial Fower Plants "Sclistencl JORDANI, EL Division of Emergency Preparedness \* Engineering Response (Post 830107) 84/07/27 Consolidated Edison Co. of New York, Inc. 119pp 25865-047 24% Fiche 50-000,84/07/27,8407250229
- 8408010334 IE Info Notice 84-59. "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JURDANLE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc. 122pp 24068 001 24x Fishe 50-000.84/08/04,8408010333
- 8408010337 IF Info Notice 84-60. "Failure of Air Purifying Respirator Filtors to Meet Efficiency Requirement " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co or New York, Inc 123pp 24067 156 24% Fiche 50-000.84/08/04,8408010337
- 8408070120 iE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list end! JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 24129 118 24X Fiche 50-000.84/08/08,8408070120
- 8408070376 IE Info Notice 84-62. "Therapy Hisadministrations to Patients Undergoing Co-60 Teletherapy Treatments " 8vc list enc! GRACE,J N Division of OA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24% Fichs 50-000.84/08/10.8408070376
- | S40B100009 | IE | Info | Notice | B4-63. | "Defective | RHR | Replacement | Piping | " | Syr | list | encl | JDRDAN.C | Division of | Emergency | Preparedness & Engineering | Response | (Post | 830103) | B4/08/13 | Consolidated | Edison | Color | of | New | York. | Inc | | 119pp | 24197 | 218 | 24X | Fiche | 50-000.84/08/13,840B100099
- 840B100G3B IE Info Notice B4-64, 'BWR HPC1 Institution Seal-In & Indication "Syc list encl JORDAN, C. Division of Emergency Preparedness & Engineering Response (Post 830303) 8470B/15 Consolidated Edison Co. of New York, Inc. 104pp 2619B 093 24X Fiche 50-000,8470B/15,840B10003B
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021
- 840B100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Foodwater Train." Svc. list encl. JORDAN, C. L. Division of Emergency Pieparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 001 247 Fiche 50-000.84/08/17, 8408100055
- 8408140208 IF Info Nutice 84-67. "Recent Snubber Inservice Testing W/High Failure Rates" Syc list entl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 122pp 26276 122 24% Fiche 80-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solencid Valves " Svc list encl JORDAN, E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 24329 008 24X Fiche 50-000,84/08/21,8408210142
- R Periodic operating reports & related correspondence
- 8408200001 Monthly operating repts for Jul 1984 W/840802 ltr NIX:N C Georgia Power Co 84/07/31 15pp 26140 264 24X Fiche 50-321:84/07/31:8408200001
- 8 Reportable occurrences, LERs & related correspondence
- 8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solencid valve plunger Initially reported on 840413 New thread locking devices investigated SHERNDOD:0 G General Electric Ca 84/04/13 DEYOUNG:R C Director's Office. Office of Inspection and Enforcement 3pp 26222 255 24% Fiche 50-000:84/04/13,8408240348
- 8408090287 Special Rept 50-321/1984-009 on B40720, level in both fire water storage tanks dropped to less than 270,000 gallons, due to initiation of diesel fire pumps during hydrant flush test Tank levels returned to Tech Spec limit
  NIX.HC Georgia Power Co 84/08/01 G'REILLY.J P Region 2.
  Office of Director 2pp 25994 163 24X Fichs 50-321,84/08/01.

- 8408270229 LER 64-025-00 on 840627, cable leads lifted h improperly tagged' siparared in control room claused by personnel error Procedure HMP-6921 ra cable ' cable ways installation revised to strengthen administrative control M/840814 ltr ELTON, I L , MIX.M C Georgia Power Co 64/08/14 3pp 26258 045 24X Fiche 50-321.84/08/14 8406270229
- 8408310186 Part 21 reptile turus-to-reactor bldg vacuum breakers Memo of 840820 teicon reporting equipment quality % separation of controls to butterfly valvos encl GE lacks technical info to adequately evaluate condition
  VILLA,R General Electric Co. 84/08/21, ROSSI,C E. Director's
  Office, Office of Inspection and Enforcement. 3pp. 26318-327, 243
  Fiche 50-000-84/08/21,8498310186
- 8408330333 LER 64-013-00 on 810729 during Procedure HNP-1-3154.HPCI malfunctioned % injected into reactor Caused by short circuit across 1/2 of HPCI automatic injection logic MPCI test jack E41-UI inspected % cleaned W/840822 ltr ELTON,T L , NIX.H C Georgia Power Co 84/08/22 3pp 26308 332 24X Fiche 50-321.84/09/22 8408300333

DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION

A Application/construction stage documents & correspondence

- 8407300105 Relates recent exemption decision to Section 185 of Atomic Energy Activequiring NRC to rind plant in conformity w/ provisions \* rujes \* regulations of Commission before issuing OL PLAINE, H Office of the General Counsel SECY-84-290A 84/07/24 2900 25920 001 24% Fiche 50-322.84/07/24,8407300105
- 8408130547 Provides preliminary comments on six items of Commissioner Assetstine 840725 proposal that NRC apply Shoreham Decision CLI-B4-8 generically to schedular exemption requests DIRCMS.W J. Diffice or the Executive Director for Operations 84/08/02 Commissioners 5pp 26294 158 24X Fiche 50-322,84/08/02.8408130547
- 8408070110 Generic Ltr 84-19 to all liconsess of operating reactors, applicants for CLs \* holders of CPs re availability of Suppl i to NUREO-0933, "Prioritization of Generic Bafety Issues." Syc list encil EISENHUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York. Inc. 18pp 26129 238 24% Fiche 50-000,84/08/06,8408070110
- B408070317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors? license applicants for Jul 1984
  TREMBLAY.P P Operating Reactors Assessment Branch B4/08/06
  HDLAMAN.G M Operating Reactors Assessment Branch 13pp
  25971 390 24x Fiche 50-000.84/08/06.8408090317
- B40B090210 Forwards A Schuencer B40730 memo to E Reis re license conditions & NRC 840731 ltr to util re amend extending expiration date of License SNI-1837 Certificate of Svc encl Related correspondence BORDEAICK.8 M Hearing Branch 3 DSB 868 84/08/07 Atomic Safety and Licensing Appeal Penel 4pp 25971 211 24X Fichb 50-322.84/08/07.8108090210
- --B408090213 Forwards status list of partial initial decision license conditions & details of NRC intended course of action Requests status rept be forwarded to util SCHMENCER. A Licensing Branch 2 84/07/30 REIS E Hearing Branch 3 5pp 25971 215 24X Fiche 50-322,84/08/07.8408090210
- B408200328 Forwards summary of disposition of generic ltrs for CY83 LEGNARD, J D. Long Island Lighting Co. 84/08/14 DENTON, H R Office of Nuclear Reactor Regulation. Director 6pp 26133.004 24X Fiche 50-322, 84/08/14,8408200328
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT.D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000,84/08/20,8408200275
- 840B270226 Forwards documents re recently conducted integrated electrical test at facility Encl represents summation of actual loads experienced during loss of affsite power/LOCA simulations for test LEDNARD. J D Long Island Lighting Co 84/08/22 DENTON. H R Office of Nuclear Reactor Regulation. Director 127pp 26243 001 24X Fiche 50-322,84/08/22,8408270226

- C Utility Environmental Report (ER), amends & correspondence
- 8408230409 Uithdraws util 840309 motion to strike portions of testimony of Suffolk County utnesses Harris & Mayer re Contention 75 Related correspondence MCCLESKEY. Hunton & Williams MCCLESKEY. Long Island Lighting Co DSB 209 84708/20 LAUREMSON.J A. KLINE, J R., SHON.F J Atomic Safety and Licensing Board Panel ip 26205 359 24X Fiche 50-322,84708/20.8408230409
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8408220107 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SHOREHAM NUCLEAR POWER STATION, UNIT NO 1 Docket No 50-322 (Long Island Lighting Company) # Division of Licensing NUREG-0420 905 84/07/31 33pp Available at NRC \$3.75 26197 304 24X Fiche 50-322,84/07/31,8408220107
- F Security, medical, energency & fire protection plans
- 8408080473 Forwards IE Insp Rept 50-322/84-22 on 840514-18 No violations noted MARTIN T Division of Engineering & Technical Programs 84/07/16 LEONARD. J D Long Island Lighting Co 2pp 25975 164 24X Fiche 50-322,84/07/16,8408080473
- --8408080478 IE Insp Rep\* 50-322/84-22 on 840514-18 No violations noted Mayor areas inspected plant facilities & Initial fuel load & startup testing planning Safeguards info deleted (ref locfR73 21)
  BLUMBERG, N , KUCHARS/I, S , BETTEMHAUSEN, L Region 1, Office of Director 84/07/03 6pp 25975 166 24X Fiche 50-322.84/07/16, 8408080473
- BA0829047B Forwards Insp Rept 50-322/84-23 on 840528-0701 No violations noted STARDBTECKI.R Division of Project & Resident Programs 84/08/08 LEONARD.J L Long Island Lighting Co App 26274 189 24X Fiche 50-322.84/08/08.8408290478
- --8408290483 Insp Rept 50-322/84-23 on 840928-0701 No violations noted Major areas inspected discharge of security guard weapon, status of Colt diesel generator project, storage of emergency equipment lockers & IE Bulletin 80-06 PETRONE, C . ESELEROTH, P . SHEDLOSKY, J Region 1, Office of Director 84/07/19 12pp 26294 193 24X Fiche 50-322,84/08/08,8408290478
- G Adjudicatory correspondence
- 8408010133 Staff requirements memo re 840516 Commission vote determining that 10CFK50 57(c) should not be read to make GDC 17 inapplicable to low power operation CHILK.8 J Office of the Secretary of the Commission 84/05/18 Office of the Secretary of the Commission 19 25873 312 24% Fiche 50-322,84/05/18,8408010133
- 8406040336 Discusses 840917 hearing of Congressional Subcommittee on Energy & Environ re licensing procedure Manner in which attempts made to expedite hearings unprecedented Requests disqualification from further action HOCHBRUECKNER New York, State of DSB 420 84/05/22 PALLADINON J Commissioners 2pp 24802 339 24% Fiche 90-322,84/05/22,8406040336
- 8408160123 Forwards NRC staff Exhibit 1 from 840424 hearing Related correspondence RILEY, 8 L Tayloe Associates 84/06/15 PLEASANT.E Administrative & Logistical Support Branch 1p 26126 168 24X Fiche 50-322,84/06/15,8408160123
- 8408160076 Forwards applicant Exhibits 38-47 from 840605-08 hearings Related correspondence RILEY, S. L. Taylor Associates 84/06/26 PLEASANT, E Administrative & Logistical Support Branch ip 26126-349, 24X Fiche 50-322,84/06/26,8408160076
- 840816011B Forwards intervenor Exhibits 67-74 Related correspondence RILEY,S.L. Tayloe Associates 84/06/26 PLEASANT.E Administrative & Logistical Support Branch ip 26126 169 24X Fiche 50-322,84/06/26.840816011B
- 8408060434 Staff requirements memo re 840725 meeting on interpretation of Dalisium CLI-84-8 & reexam of exemption process CHILK, S J Office of the Secretary of the Commission 84/07/26 DIRCKS, W J Office of the Executive Director for Operations 2pp 25937 322 24X Fiche 50~322,84/07/26,8408060434

- 8408010254 Informs that NRC testimony prepared by IE on Contention II will not be available until next uk Related correspondence BORDENICK.B M Hearing Branch 3 D58 677 84/07/27 LAURENSON.J A , SHON.F J KLINE J R Atomic Safety and Licensing Board Panel 2pp 25854 178 24× Fiche 50-322.84/07/27.8408010254
- B408010261 Application for issuance of subpoenss to command appearance & testinony by J Hines & FA Cipriani at emergency planning hearings Certificate of Svc encl Related correspondence CHRISTMAN.J N Long Island Lighting Co CHRISTMAN.J N Hunton & Hilliams DSB 662 B4/07/27 Atomic Safety and Licensing Board Panel 12pp 23854 044 24X Fiche 50-322.84/07/27,8408010261
- 8408060437 Revised staff requirements memo re 840725 discussion on interpretation of Decision CLI-84-8 & regiam of exemption process CHILK.S J. Office of the Secretary of the Commission 84/07/27 DIRCKS.W J. Office of the Executive Director for Operations PLAINE.H H. Office of the Executive Legal Director ip 25937 316 24% Fiche 50-322.84/07/27.8408060437
- B408010169 Answer apposing Suffalk County 840724 motion to compel production of documents Util has substantially complied w/ production of documents requested Certificate of Svc encl Related correspondence
  FARLEY.E M Long Island Lighting Co FARLEY.E M Hunton & Williams DSB 685 84/07/30 Atomic Safety and Licensing Board Panel 13pp 25895 307 24X Fiche 30-322.84/07/30.8408010169
- B408010239 Response to util motion for partial reconsideration of B40718 security proceedings order Motion should be denied due to util failure to demonstrate basis for motion Certificate of Syc encil LETBCHE, K. J. Suffolk County, NY LETBCHE, K. J. Kirkpatrick, Lockhart, Hill, Christopher & Phillips PALCMIND, F. O. New York, State of DSB 674 84/07/30 Atomic Safety and Licensing Board Panel 4pp 25855 010 24% Fiche 50-322,84/07/30,8408010239
- 8408020002 Requests to make limited appearance statement at B40804 low power test license hearing Served on B40801 BREDES.N Affiliation Not Assigned DSB 705 84/07/30 Docketing & Services Branch 1p 25882 300 24X Fiche 50-322.84/07/30.8408020002
- B40B020024 Motion to admit revised testimony of Phase II emergency planning Contentions 24 0.74 & 75 (relocation ctrs) Certificate of Svc enci Related correspondence MCCLESKEY.K E Long Island Lighting Co MCCLESKEY.K E Hunton & Milliams DSB 698 84/07/30 Atomic Safety and Licensing Board Panel 68pp 25983 150 24x Fache 30-322.84/07/30,8408020024
- B40B070274 Response to Suffolk County 840727 notice of execution of affidavits of nondisclosure Suffolk County representation premature Certificate of Svc encl IRWIN, DP Long Island Lighting Co IRWIN, DP Hunton & Williams DSB 761 B4/07/30 Abomic Safety and Licensing Board Panel 4pt 25949 199 24X Fiche 50-322,84/07/30,8408070274
- 8408020200 Statement of Covernor M Cuomo in support of Suffolk County 840723 motion for reconsideration of ASLB limitations on Suffolk County cross-examination of FEMA witness panel Certificate of Svc entl Related correspondence ZAHNLEUTER, R J New York, State of D6B 715 84/07/31 Atomic Safety and Licensing Board Panel 5pp 25898 002 24X Fiche 50-322,84/07/31,8408020200
- 8408030074 Notice to ASLB re-schedula for hearing strike issues
  Schedule too rigorous for parties to mast Truly full & fair
  hearing may require more realistic schedule Certificate of
  Svc encl
  MCMURRAY, C M Suffolk County, NY MCMURRAY, C M Kirkpatrick,
  Lockhart, Hill, Christopher & Fàllitps DBB 724 84/07/31 13pp
  25907 016 24X Fiche 50-322,84/07/31,8408030074
- 8408020044 Advises that time for Commission to review ALAB-773 expired Commission declined review Decision became final agency action on 840723 Served on 840801
  CHILKS J Office of the Secretary of the Commission DSD 707
  84/08/01 Atomic Safety and Licensing Board Panel ip 25883 262
  24X Fiche 50-322,84/08/01,84080200044
- 8408030085 Order establishing procedures & schedule for reply to LILCO 840730 answer to motion to compel production of documents. Reply requested by 840807 Courtesy notification encl Served on 840805 BRENNER. L Atonic Safety and Licensing Board Panel DSB 731 847080701 Seffolk County, NY 6pp 25906 331 24X Fiche 50-322,84/08/01.8408030085

- 8408030086 Memorandum to show cause why Suffolk County 840726 appeal of ASLB 840710 order should not be dismissed Appeal filed late for good cause Certificate of Svc on 1 Related correspondence MILLER, M S Suffolk County Ny MILLER, M S Kirkpatrick, Lockhart, Hill, Christopher & Phillips DSS 730 84708701 15pp 25906 336 24X Fiche 50-322,84708701,9408030086
- 8408030105 Motion to admit proposed modified emergency planning Contention 88 & revised testimony of GC Minor on emergency planning Contentions 85 & BB Related correspondence MILLER, M S Suffolk County, NY MILLER, M S Kirkpatrick, Lockhart-Hill Christopher & Phillips DSB 725 84708/01 Atomic Safety and Licensing Board Panel 11pp 25916 055 24X Fiche 50-322,84708/01,8408030105
- --B408030112 Revised testinony of GC Minor on emergency planning Contentions 85 & 88 re offsite recovery & reentry Prof qualifications statement & Certificate of Svc encl MINOR, G C Suffolk County, NY MINOR, G C MHB Technical Associates 84/08/01 18pp 25916 066 24X Fiche 50-322,84/08/01.8408030105
- 8408070475 Memorandum & order denying motion for disqualification of Judge Cotter Statement of BP Cotter & Certificate of Svc encl Served on 840806 COTTER.B P Atomic Safety and Licensing Board Panel DSB 759 84/08/01 New York, State of 15pp 25940 300 24X Fiche 50-322.84/08/01,8408070475
- 8408030090 Motion for directed certification of ASLB 840724 order, granting in part & denying in part.util motion for summary disposition on Phase I & II low power testing Certificate of Svc encl ROLFE, R M Long Island Lighting Co ROLFE, R M Hunton & Williams D88 728 84/08/02 Commissioners 59pp 25906 274 24X Fiche 50-322.64/08/02.8408030090
- B408030097 Order establishing pending appeal as motion for directed certification of ASLB order in question Party views as to whether criteria for granting certification met requested by 840810 Served on 840802 SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel DBB 72784/08002 Suffolk County, NY 2pp 25904 301 24X Fiche 50-322,84/08/02.8408030099
- 840B070256 Response opposing Suffalk County offer of proof for cross-examination of FEMA witnesses & request for reconsideration of ASLE limitation of cross-examination of FEMA witnesses Certificate of Svc enci MCCLESKEY, K E Long Island Lighting Co MCCLESKEY, K E Hunton & Williams DSB 768 84/08/02 Atomic Safety and Licensing Board Panel 17pp 25949 244 24X Fiche 50-322,84/08/02,8408070256
- B40B070395 Response opposing Suffol) County 640723 offer of proof & request for reconsideration of ASLB limitations on Suffolk County cross-examination of FEMA withess panel ASLB did not abuse discretion Certificate of Svc encl
  BORDENICK, B M Hearing Dranch 3 DBB 614 84/08/02 Atomic Safety and Licensing Board Panel 8pp 25745 259 24X
  Fiche 50-322.64/08/02.8408070395
- 8408070397 Motion for referral to Commission of ASLB 840723 order granting in part & denying in part. will 840523 motions for summary disposition on Phase I & Phase II low power testing Certificate of Evt encl ROLFE.R M Long Island Lighting Co ROLFE.R M Hunton & Williams DSB 778 84/08/02 Abomic Safety and Licensing Board Panel 12pp 25942 211 24X Fiche 50-322.84/08/02.8408070379
- 8408070427 Response opposing Suffalk County offer of proof & request for reconsideration of ASLB limitations on Suffalk County cross-examination of FEMA witness panel Certificate of Svc ancl GLASS, S M Federal Emergency Management Agency DSB 784 84/08/0 Atomic Safety and Licensing Board Panel 9pp 25942 014 24% Fiche 30-322,84/08/02.8408070427
- B408070308 Motion to compel util to produce FM Rasbury for deposition during wk of 840806-10 re relocation ctr issues or in alternative that FM Rasbury be stricken from util uitness panel. Certificate of Svc encl Related correspondence MCMURRAY.C M Suffolk County. NY MCMURRAY.C M Kirkpatrick. Lockhart Hill. Christophor & Phillips D88 797 84/08/03 Atomic Safety and Licensing Board Panel 17pp 25947 341 24X Fiche 50-322.84/08/03.8408070308
- 840B070358 Memorandum ALAB-779, stating ABLAB intention not to review ABLB 840B01 denial of Suffolk County 840622 motion for disqualification ASLAB expresses no view re merit of motion Served on 840B03 SHOEMAKER, C. J. Atomic Bafety and Licensing Appeal Panel DSB 758 B4/0B/03 3pp 25945 17A 24X Fiche 50-322,84/08/03,8408070358

- 8408070421 Motion for reconsideration of ASLB 840724 order re schedule for hearing & prohibiting written testimony on strike issues Certificate of Svc encl MILLER, M S Suffolk County, NY MILLER, M S Kirkpatrick, Lockhart, Hill, Christopher & Phillips D58 798 84/08/03 Atomic Safety and Licensing Board Panel 13pp 25940 056 24x Fichs 50-322,84/08/03.8408070424
- 8408070442 Forwards util motion for summary resolution of ASL8 determination involving effect of strike on local emergency response organization & proposal of license condition & statement of matl facts Related correspondence IRWIN.D P Hunton & Williams IRWIN.D P Long Island Lighting Co DSB 804 84/08/03 LAURENSON.J A KLINE, J R . SHON, F J Atomic Safety and Licensing Board Panel ip 25940 230 24X Fiche 50-322.84/08/03.8408070442
- --B408070348 Motion for summary resolution of ASLB 840724 memorandum & order re effects of strike of local emergency response organization workers on ability to implement offsite emergency preparedness plan & proposal of license condition IRWIN.D P Long Island Lighting Co IRWIN.D P Hunton & Williams B4708/03 Atomic Safety and Licensing Board Panel Opp 25740 231 24% Fishe 50-322.84/08/03.8408070442
- --8408070498 Statement of natl facts in support of util motion for summary resolution of ASLB 840724 order Unesecuted affidavits 2 Certificate of Svc encl \* Long Island Lighting Co 84/08/03 Atomic Safety and Licensing Board Panel 55pp 25940 237 24X Fiche 50-322,84/08/03,8408070442
- 8408070388 Informs that Judge Cotter 840801 memorandum & order denying disqualification motion of Suffolk County & State of NY & ALAB-779, did 840803.affirming subj order.docketed in low power phase of proceeding CLEMENTS, W.L. Docketing & Services Branch DSB 757 84/08/06 Office of the Executive Legal Director 1p 25945 279 24X Fiche 30-322.84/08/06.8408070388
- 8408880338 Motion for reconsideration of ASLB 840727 memorandum & order establishing format & schedule of proposed findings of fact & conclusions of law Certificate of Svc encl MCMURRAY.C M Surfolk County, NY MCMURRAY.C M Kirkpatrick, Lockhart, Hill, Christopher & Phillips DSB 820 84/08/06 Atomic Safety and Licensing Board Panel 20pp 25764 058 24% Fiche 50-322.84/08/06.4408080338
- 8408080408 Answer opposing Suffolk County 840803 motion to compel util to produce util witness.FM Rasbury, for deposition Certificate of Syc encl Related correspondence CHRISTMAN, JN Long Island Lighting Co CHRISTMAN, JN Hunton & Williams DSR 842 84/08/06 Atomic Safety and Licensing Board Panel App 25974 074 24X Fiche 50-322,84/08/06.8408080408
- 8408080417 Motion for summary disposition of Contentions 1-10 re legal authority No genuine issue of matl fact exists & util entitled to favorable decision Related correspondence CHRISTMAN.W T Long Island Lighting Co CHRISTMAN.W T Hunton & Williams DSG 843 84/08/06 Atomic Safety and Licensing Board Panel BAPP 25973 310 24X Fiche 50-322.84/08/06,8408080417
- ~-8408080423 Statement of matl facts as to which there is no genuine issue on Contentions 1-10 re legal authority Certificate of Svc encl
  \* Long Island Lighting Co 84/08/03 Atomic Bafety and
  - \* Long Island Lighting Co 84/08/03 Atomic Bafety and Licensing Goard Panel 14pp 25974 038 24X Fiche 50-322,84/08/06,8408080417
- 8408080428 Opposition to Suffolk County dilatory pleadings on strike issues & motion to direct parties to provide timely discovery on direct case Certificate of Svc encl. Related correspondence IRWIN, D P Long Island Lighting Co IRWIN, D P Hunton & Williams DBB 845 84/08/06 Atomic Safety and Licensing Board Panel 22pp 25973 288 24X Fichs 50-322,84/08/06,8408080428
- 8408090218 Forwards 840801 ltr & affidavit of CS Matthews for docketing Related correspondence DREIFUS.D Hunton & Williams DREIFUS.D Long Island Lighting Co DSS 840 84/08/06 Docketing & Services Branch ip 25971 220 24X Fiche 50-322,84/08/06.8408090218
- --8408090223 Forwards affidavit of C Matthews attesting to accuracy of info contained in 840712 ltr re crankshaft oil passage plug issue Related correspondence DREIFUS, D Hunton & Williams DREIFUS, D Long Island Lighting Co 84/08/01 BRENNER, L MORRIS, P A , FEROUSION, C A Atomic Safety and Licensing Board Panel 21pp 25971 221 24X F1che 50-322,84/08/06,8408090218

- 8408080410 Joint notion of State of NY & Suffolk County to compel discovery of documents & info sought in 840801 discovery request ASLB requested to give matter expeditious cansideration I/Certificate of Svc Related correspondence MCMURRAY.C M Suffolk County, NY MCMURRAY.C M Kirkpatrick, Lockhart, Hill, Christopher & Phillips ZAHNLEUTER.R J New York, State of DSB 847 84/08/07 Atomic Safety and Licensing Board Panel 20pp 25774 054 24X Fiche 50-322, 84/08/07. 8408080410
- 8408090161 Informs that NRC has no objection to title motion to admit revised testimony on Phase II emergency planning Contentions 24 0.74 & 75 (relocation ctrs) & Suffolk County motion to admit Contention 88 Related correspondence BORDENICK, B M Hearing Branch 3 DSD 869 84/08/07 LAURENSON, J A , SHON, F J , KLINE, J R Atomic Safety and Licensing Board Panel 2pp 25973 008 24% Fiche 50-322,84/08/07,8408090161
- 8408090210 Forwards A Schwencer 840730 memo to E Reis re license conditions b NRC 840731 ltr to util re amend extending expiration date of License SMM-1897 Certificate of Svc encl Related correspondence BCRDENICK, B M Hearing Branch 3 DSB 868 84/08/07 Atomic Safety and Licensing Appeal Panel 4pp 25971 211 24X Ficho 50-322.84/08/07.8408090210
- ---8408090213 Forwards status list of partial initial decision license conditions & details of NRC intended course of action Requests status rept be forwarded to util SCHMENCER. A Licensing Branch 2 84/07/20 REIS.E Hearing Branch 3 5pp 25971 215 24X Fiche 50-322.84/08/07,8408090210
- B40B090215 Order scheduling conference of counsel for B40B08 Agenda for conference includes scheduling re all pending discovery requests; scheduling of all a yearts in Aug & scheduling & formatting re sua sponte strike issues Served on 840B08 LAURENSON, J A Atomic Safety and Liconsing Board Panel DSB 853 B4708707 Office of the Executive Legal Director ip 25971 244 24% Fiche 50-322,84708/07,840B090215
- B408090411 Hution to compel identification of witnesses offering specific elements of testimony re Suffalk County emergency dissel generator contentions Certificate of Svc encl Related correspondence
  FARLEY.E M Long Island Lighting Co FARLEY.E M Hunton & Williams D88 875 84/08/07 Atomic Safety and Licensing Board Panel App 25982 218 24% Fiche 50-322,84/08/07.8408090411
- 8408070431 Motion to strike portions of joint direct testimony of RN Anderson. SO Christensen. OD Eley. A Bakshi. DO Bridenbaugh & RB Hubbard re emergency diesel generators Related correspondence
  FARLEY. E M Long Island Lighting Co FARLEY. E M Hunton & Hillams DBB 876 B4/08/07 Atomic Bafety and Licensing Board Panel 37pp 25982 179 24% Fiche 50-322.84/08/07.8408090431
- 8408070242 Memorandum & order granting Suffolk County 840803 motion to compel util to produce fit Rasbury as witness, for deposition Served on 840808 LAURENBON, J. A Atomic Safety and Licensing Board Panel DSB 861 B408708 Long Island Lighting Co. 3pp. 25972 164 24X Fiche 50-322,84/08/08,8408070242
- 8408070470 Order granting LILCO 840807 motion to compel identification of witnesses offering specific elements of testimony re Buffalk County emergency diesel generator contentions Courteey notification encl Served on 840807 BRENKERIL Atomic Safety and Licensing Board Panel DSD 885 84/08/08 Long Island Lighting Co 4pp 25902 227 24X Fichs 50-322.84/08/08,84080970490
- 8408130162 Motion to quash subposens of FA Cipriani & J Hines to testify on 840822 re ltrs disavowing use of American Red Cross Pacilities as relocation ctrs Certificate of Svc encl Related correspondence
  ZAHNLEUTER, R J New York, State of DSB 931 84/08/08 Atomic Bafety and Licensing Board Panel 10pp 26007 354 24X Fiche 50-322.84/08/08.8408130162
- 8408130264 Statement of MM Coomo, representing State of NY. in support of Suffolk County 840803 notion to compel LILCO to produce FM Rasbury, LILCO witness, for deposition Certificate of Svc encl Related correspondence Z
- 8408130284 Statement of Covernor MM Cuomo, representing State of NY, in support of Suffolk County 840803 & Ob motions for reconsideration of ASLB 840724 & 27 scheduling orders Certificate of Svc encl ZAHNLEUTER, R J New York, State of DSB 932 84/08/08 App 26008 282 24% Fiche 50-322,84/08/08,8408130284

- 8408130341 Notice of appearance in proceeding Certificate of Svc encl BRIGATI.J J Suffolk County, NY DSB 892 84/08/08 4pp 26010 216 24% Fiche 50-322.84/08/08.8408130341
- 8408130347 Forwards affidavits of MC Cordano.EP Stergakos, JA Rigert & JA Scalice, which accompanied util 840803 motion for summary resolution of ASLB determination & proposal of license condition Related correspondence ZEUGIN.L B Hunton & Williams ZEUGIN.L B Long Island Lighting Co DSB 891 84/08/08 LAURENSON, JA, KLINE, JR. SHON, FJ Atomic Safety and Licensing Board Panel 1p 26010 226 24X Fishe 50-322.84/08/08.8409130347
- --8408130352 Affidavit of MC Cordaro supporting util motion for summary resolution of issues re effect of Local Emergency Response Organisation strike against util Proposed license condition re strike issue encl Related correspondence CORDARO, MC C Long Island Lighting Co 84/08/03 4pp 26010 227 24x Fiche 50-322,84/08/08,8408130347
- --8408130355 Affidavit of JA Scalice re ASLB 840724 memorandum & order determining serious safety matter exists Related correspondence SCALICE. JA Long Island Lighting Co 84/08/03 App 26010 231 24X Fiche 50-322.84/08/08.8408130347
- --8408130359 Affidavit of EP Stergakos & JA Rigert in response to ASLB 640724 memorandum & order determining serious safety matter exists Supports proposition re radiological consequences of cold shutdoun u/normal procedures Related correspondence STERQAKGS E P. RIGERT, JA Long Island Lighting Co 84/08/03 Bpp 26010 237 24% Fiche 50-922,84/08/08,8408130347
- 840B130109 Order directing parties to file proposed findings of fact & conclusions of law by 840B31 % giving notice of 840B16 conference w/counsel Served on 840B10 MILLER.M E Atomic Safety and Licensing Doard Panel DSB 896 84/08/09 Office of the Executive Legal Director 2pp 26005 359 R4X Fiche 50-322.84/08/09.840B130109
- 840Bi40005 Notice of execution of affidavit of nondisclosure re-access to safeguards info relating to util security plan Certificate of Svc enct Related correspondence PALOMINO.F O New York, State of DSB 944 B4/08/09 Atomic Bafety and Licensing Board Panel 7pp 26044 348 24X Fiche 50-322.8470B/09.8408140005
- 8408140003 Memorandum in response to ASLAB 840802 order, asserting that Buffolk County has not met criteria for granting directed certification in County 840801 memorandum to show cause W/Certificate of Svc Related correspondence IRWIN.D P Long Island Lighting Co IRWIN.D P Hunton & Williams DSB 757 84/08/10 39pp 26052 265 24X Fiche 50-322.84/08/10.8408140003
- B40B14013B Memorandum in support of Suffolk County B40727 motion for directed certification Criteria for granting directed certification met 2 motion should be granted Certificate of Bvc encl Related correspondence ZAMNLEUTER, R J New York, Btate of DSB 963 84/08/10 Atomic Bafety and Licensing Appeal Panel 5pp 26044 253 24X Fiche 50-322,84/08/10.8408140138
- B40B140466 Requests that 840B16 conference re security issues be postponed until 840B20 or other date most convenient to ASLB DYNNER, A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips DYNNER, A R Suffolk County, NY D88 012 84/08/10 MILLER, ME, JOHNSON, E B, ERIGHT. G Atomic Safety and Licensing Board Panel 2pp. 26060 348 24X Fiche 50-322,84/08/10,8408140466
- 40B150090 Memorandum in opposition to Suffolk County motion for directed certification of ASLB 840710 oral order denying request for production of certain FEMA documents Certificate of Byc eacl Related correspondence BORDENICK, B M Hearing Branch 3 DBB 044 B4/0B/10 Atomic Safety and Licensing Appeal Panel 14pp 26067 039 24X Fiche 50-322.84/08/10.8408150090
- 40B150443 Response to Suffolk County motion for directed certification of ASLB 840710 order which denied Suffolk County request for production of documents dealt w/in ASLAB 840613 Order ALAB-773 Certificate of Svc encl Related correspondence GLABS.8 M Federal Emergency Management Agency DSB 063 84/08/10 Atomic Safety and Licensing Appeal Panel 14pp. 26068 235 24% Fiche 50-322,84/08/10.8408150443

- B40B140470 Opposition to LILCO B40B02 motion for directed certification of ASLB 840724 order granting in part & denuing in part LILCO motions for summary disposition of Phases I & II low power testing Related coriespondence LETSCHE.K J Suffolk County, NY LETSCHE.K J Kirkpatrick, Lockhart Hill, Christopher & Phillips PALDMINO, F G New York, State of D5B 008 84708713 Commissioners 9pp 26060 333 24X Fiche 50-322,84708713,8408140470
- --8408140477 Opposition to LILCO 840802 motion for referral of ASL8 840724 order granting in part 5 denying in part LILCO motions for summary disposition of Phases I & II low power testing Certificate of Svc enci Related correspondence LETSCHE.K J Suffolk County, NY LETSCHE.K J Kirkpatrick, Lockhart, Hill. Christophei & Phillips PALOMINO.F & New York. State of 84/08/13 Atomic Safety and Licensing Board Panel 6pp 26060 342 24X Fiche 50-322-84/08/13.8408140470
- 840B150073 Memorandum & order denying Suffolk County offer of proof & motion for reconsideration of ASLN limitations on cross-elamination of FEHA witness canel & granting Item 16 on Page 8 Served on 840B14
  LAURENSON.J A Atomic Safety and Licensing Board Panel DSN 052 84/08/13 Suffolk County, NY 12pp 26067 021 24X Fiche 50-322,84/08/13,840B150073
- B40B150142 Forwards nemorandum & order denying Suffolk County & State of NY petition for exemption from regulations precluding financial qualifications contention & motion for certification to Commission W/o encl Served on 840814 BEENNER.L. Atomic Safety and Licensing Bloard Panel DSB 051 84/08/13 PLAINE.H H Office of the General Counsel 2pp 24067 016 24X Fiche 50-322,81/08/13,840B150142
- B40B150155 Hemorandon & order denying Suffolk County & State of NY petition for exemption from regulations precluding financial qualifications contention? motion for certification to Commission Courtesy notification ent
- 8408150192 Order denying Suffolk County 840810 request for postponement of conference u/counsel re security issues acheduled on 840814 Served on 840814 HILLER, M.E. Atomic Safety and Licensing Board Panel DSB 053 84/08/13 Suffolk County, NY 3pp 24044 090 24X Fiche 50-322,84/08/13,8408150192
- B40B160100 Responds to Suffolk County request for postponement of B40B16 conference of counsel Util opposes any postponement which could prolong low power proceedings Certificate of Svc encl
  ROLFE.R M Hunton & Williams ROLFE.R M Long Island Lighting Co
  DSB 070 B4/0B/13 MILLER.M E , BRIGHT.G O , JOHNSON, E B Atomic
  Safety and Licensing Board Panel 4pp 260B5 31B 24X
  Fiche 50-322,B4/0B/13,840B160100
- 8408160210 Joint nation for summary disposition of emergency planning Contentions 24 0.74 & 75 No genuine issue of matl fact exists & Suffolk County & State of NY entitled to favorable decision Related correspondence LETSCHE,K J Suffolk County, NY LETSCHE,K J Kirkpatrick, Lockhart, Hill, Christopher & Philips ZAHNLEUTER,R J New York, State of DSB 076 84/08/13 Atomic Safety and Licensing Board Panel 12pp 26089 345 24% Fiche 50-322,84/08/13,8408160210
- --B408160224 Statement of nat1 racts as to which there is no genuine issue re emergency planning Contentions 24 0.74 & 75 Certificate of Svc encl Related correspondence \* Suffoly County, NY \* New York, State of 84/08/13 Atomic Safety and Licensing Board Panel App 26089 357 24% Fiche 50-322,84/08/13,8408160210
- B40B15043B Motion for leave to make restricted svc of certain documents, for protective order & for in camera cross-examination re documents Certificate of Svc enc! Related correspondence FARLEY, E M Long Island Lighting Co FARLEY, E M Hunton & Williams DSG 057 84/08/14 Atomic Safety and Licensing Board Panel 9pp 26068 242 24X Fiche 50-322,84/08/14,8408150438
- B408170315 Opposition to L1LCO 840807 motion to strike portions of joint direct testimony of RN Anderson, et al Certificate of 8vc encl Related correspondence SCHEIDT, D J Suffolk County, NY SCHEIDT, D J Kirkpatrick, Lockhart, Hill, Christopher & Phillips DSB 082 84/08/14 Atomic Safety and Licensing Board Panel 43pp 26114 237 24X Fiche 50-322.84/08/14.8408170315

- B40B15041B Memorandum! order dismissing Suffolk County 840726 notice of appeal to compel FEMA to produce certain documents Appeal treated as motion to direct certification Directed certification denied Served on B40B15 SHDEMAKER.C J Atomic Safety and Licensing Appeal Panel DSB 048 84/08/15 Suffalk County, NY 7pp 26048 254 24X Fiche 50-322.84/08/15.840B150418
- 8408170332 Memorandum 3 order denying LILCO 840814 motion for leave to make restricted syc of certain documents for protective order & for in camera cross-examination re documents Served on 840816 Courtesy notification enc!

  BRENNER.L Atomic Safety and Licensing Board Panel DS9 094
  84/08/15 Long Island Lighting Co 5pp 26113 355 24X
  Fiche 50-322.84/08/15.8408170332
- 840B220301 Urges ASLB to rule on emergency generators on basis of technical considerations & to not yield to public hysteria or political pressure to deny low power license w/o technical reason Svc on 840B21 MDRRIST W Citizens for an Orderly Energy Policy, Inc. DSB 20184/08/15 MILLER, M Atomic Safety and Licensing Board Panel ip 26193 083 24X Fichs 50-327,84/08/15,840B220301
- B40B20D250 Response supporting in part & apposing in part LILCO B40B07 motion to strike portions of Suffolk County B4073; joint testimany of RN Anderson, SØ Christenson & GØ Eley, et al Certificate of Svc encl Related correspondence GØDDARD.R J Hearing Branch 3 DSB 104 84/08/16 Atomic Bafety and Licensing Board Panel 16pc 26133 192 24X Fiche 50-322,84/08/16,8408200250
- 8408200607 Response supporting early consideration of issues raised in util 840802 motion for directed certification of ASLB 840723 order ruling on util motions for summary disposition of Phase I & II Certificate of Svc encl
  PERLIS.R 0 Hearing Branch 3 DSB 148 84/08/17 Commissioners
  7pp 26137 171 24% Fiche 50-322.84/08/17.8408200607
- 8408210351 Protective order stipulating that authorized persons shall not disclose protected info to anyone except another authorized person, unless info previously disclosed in public record of proceeding Served on 840820

  MELLER, M.E. Atomic Safety and Licensing Board Panel DSD 183
  84/08/17 8pp 2617/233 24X Fiche 50-322,84/08/17,8408210351
- 8408210398 Identification of witnesses offering specific elements of testimony re Suffolk County emergency dissel generator contentions Certificate of Svc encl
  BRIGATI.J J Suffolk County, NY BRIGATI.J J Kirkpatrick,
  Lockbart, Hill, Christopher & Phillips DSB 187 84/08/17 14pp
  26180 252 24X Fiche 50-322,84/08/17,8408210388
- 8408270082 Forwards affidavit of RJ Goddard re circumstances surrounding filing of NRC staff 840816 response to util motion to strike portions of joint testimony of RN Anderson, SG Christensen, GD Eley, et al Related correspondence GDDDARD.R J Hearing Branch 3 DSB 312 84/08/17 BRENNER.L., FERCUSUN.G A. MORRIS.P A. Atomic Safety and Licensing Roard Panel 2pp 26238 133 24% Fiche 50-322,84/08/17,8408270082
- --B408270088 Affidavit of RJ Goddard re circumstances surrounding filing af NRC staff 840816 response to util motion to strike portions of joint testimony of RN Anderson, 86 Christenson, et al Certificate of Svc encl Related correspondence GUDDARD, RJ Hearing Branch 3 84/08/17 App 26238 135 24X Fiche 50-322,84/08/17,8408270082
- 8408270111 Response supporting util motion for referral of ASLB 840723 order on summary disposition of Phases 1 & 2 of supplemental motion for low power OL Certificate of 8vc encl PERLIS.R G Hearing Branch 3 DSB 313 84/08/17 Atomic Safety and Licensing Board Panel 3pp 26247 326 24X Fiche 50-322.84/08/17.8408270111
- B40B270137 Motion for extension of time until 840B31 to file direct testimony as apposed to presently scheduled date of 840B21 Related correspondence ODDARD, R J Hearing Branch 3 DSB 314 84/08/17 Atomic Safety and Licensing Board Panel 2pp 26245 213 24X Fiche 50-322.84/08/17.8408270137
- --8408270143 Affidavit of R Caruso supporting NRC motion for extension of time to file testimony to TDI emergency diesel generators Centificate of Svc encl Related correspondence CARUSO, R Division of Licensing 84/08/17 7pp 26245 215 24X Fiche 50-322,84/08/17,8408270137
- 8408210352 Memorandum & order denying 840719 motion for reconsideration of Commission 840718 order re security contentions Served on 840820 CHILK.8 J. Office of the Secretary of the Commission BSB 194 84/08/20 Long Island Lighting Co. 2pp. 26179 198 24X Fiche 50-322.84/08/20.8408210352

- 8408230194 Motion to admit new contention addressing issues arising from recent LILCO employee strike Certificate of Svc encl LETSCHE, K J Suffolk County NY LETSCHE, K J Kirkpathick, Lockhart, Hill, Christopher ', Phillips DSB 214 84/08/20 Atomic Safety and Licensing Board Panel 19pp 26209 247 24% Fiche 50-322,84/08/20,8408230194
- 8408230199 Clarification of oral argument on matters presented in Suffolk County 840806 motion re proposed findings of fact & conclusions of law Certificate of Svc enci MCMURRAY, C M Suffolk County, NY MCMURRAY, C M Kirkpatrick, Luckhait Hill, Christopher & Phillips DSB 208 84/08/20 Atomic Safety and Licensing Board Panel 6pp 26207 175 24X Fiche 50-322.84/08/20,8408230199
- 8408230244 Response appasing NRC motion for extension of time to file testimany Certificate of Svc encl DYNNER.A R Suffalk County, NY DYNNER.A R Kirkpatrick, Lockhart. Hill: Christopher & Phillips DSB 220 84/08/20 Atomic Safety and Licensing Board Panel Spp 26204 317 24X Fiche 50-322,84/08/20.8408230264
- 8408240424 Staff requirements memo re affirmation/discussion & vote denying 2 206 relief (SECY-84-203), approving order responding to petitions for review of ALAB-763 (SECY-84-254) & approving order denying LILCO 840719 motion (SECY-84-296) CHILK, S. J. Office of the Secretary of the Commission 84/08/20 Office of the Secretary of the Commission 3pp 26248 269 24% Fiche 50-000.84/08/20,8408240424
- B40B270151 Forwards statements of prof qualifications for TR Quay, MW Hodges & RA Benedict List of witnesses NRC intends to present at B40B28 hearing on strike issues include TR Quay. MW Hodges RA Benedict & JR Sears Related correspondence HABSELL.D F Hearing Branch I DBB 296 84/08/20 LAURENBON.JA. SHON.F J. KLINE.JR Atomic Bafety and Licensing Board Panel 7pp 26245 146 24X Fiche 50-322.84/08/20,8408270151
- B408280249 Forwards affidavit of nondisclosure by LC Langher Inclusion of testimony of Suffolk County witnesses Mada & Dirmeir.not bound into 840803 hearing transcript.requested LETSCHE,K J Kirkpatrick, iockhart. Hill, Christopher & Phillips LETSCHE,K J Suffolk County, NY D88 328 84/08/20 MILLER,M E, JCHNSON,E B Atomic Safety and Licensing Board Panel Opp 26261 356 26X Fiche 50-322.84/08/20,8408280249
- 8408220342 Memorandom & order granting in part NRC 840817 motion for extension of time until 840831 to file testimony Testimony directed to be filed by 840830 Courtesy notification encl Served on 840821
  BRENNER.L. Atomic Safety and Licensing Board Panel DEB 200 84708/21
  26193 043 24x Fiche 80-322,84/08/21,8408220342
- 8408230231 Forwards list of errate for LILCO testimony on crankshafts, cylinder heads, pistons & cylinder blocks Corrected exhibits & syc list encl Related correspondence FARLEY,E M Hunton & Hilliams FARLEY,E M Long Island Lighting Co DSB 211 84/08/21 BRENNER L FEROUSON & A MORRIS, P. A Atomic Safety and Licensing Board Panel 12pp 26207, 260 24% Fiche 50-322, 84/08/21, 8408230231
- 8408230168 Order notifying of 840830 special prehearing conference in Bothosda. MD to consider & rule on socurity contentions
  Served on 840882
  MILLER.M E Atomic Safety and Licensing Board Panel DSB 253
  84/08/22 Office of the Executive Legal Director 2pp
  26209 266 24X Fiche 25-322.84/08/22.8408230168
- B408270364 Notice of resumption of hearing on 840910 in Hauppauge, NY re amorgency diasel engines Served on 840824 REENER.L. Atomic Safety and Licensing Board Panel 1088 315 84708723 3pp 26245 055 24X Fiche 50-322, 84708723, 8408270364
- 8408280433 Forwards corrections to 840816 transcript of util closing arguments in law power proceeding Corrections noted on transcript Copies provided to any party on svc list at party expense W/o encl Related correspondence MONAGHAN.J A Hunton & Williams MONAGHAN.J A Long Island Lighting Co DSD 351 84708/23 MILLER.M E Atomic Safety and Licensing Board Panel 2pp 26280 213 24X Fishe 50-322,84/08/23.8408280433
- 8408280492 Forwards master table of contents as requested by Judge Morris, for all testimony filed by LICO on crankshafts, pistons, cylinder heads & cylinder blocks Related correspondence FARLEY, EM Hunton & Williams FARLEY, EM Long Island Lighting Co DSB 354 B4/08/23 BREANER, L, FERGUSON, GA, MORRIS, PA Atomic Safety and Licensing Board Panel 7pp 24280 338 24% Fiche 50-322, 84/08/23,8408280492

- 8408290317 Forwards LILCO testimony on cylinder heads & pistons W/o encl Related correspondence FARLEY,E M Hunton & Williams FARLEY,E M Long Island Lighting Co DSB 378 84/08/23 MORRIS,P A Atomic Safety and Licensing Board Panel 1p 26290 337 24% Fiche 50-322,84/08/23,8408270317
- 8408280405 Informs that HR Brown, KJ Letsche, LC Lampher, D Kraemer, S Ober & P McGwire designated as authorized persons, per 840817 protective order Related correspondence LETSCHE, K J Kirkpatrict, Lockhart, Hill. Christopher & Phillips LETSCHE, K J Suffolk County, NY DSB 362 84708/24 MILLER, M E RRIGHT, O O , JOHNSON, E Atomic Safety and Licensing Board Panel 47pp 26280 129 24X Fiche 50-322.84709/24.8408280405
- 8408280424 Informs that staff proposed witnesses include C Berlinger, SJ Bush.AJ Heoriksen, Mi Laity & A Sarsten, per ASLB 840821 memorandum & order Prof qualifications of witnesses & Certificate of Svc anci Related correspondence GDDDARD.R J Hearing Dranch 3 DSB 339 84/08/24 BRENNER, L, MDRRIB, P A. FERGUSON, O A Atomic Safety and Licensing Board Panel 72pg 26280 218 24X Fiche.50-322.84/08/24,8408280424
- 8408300124 Answer in opposition to Suffolk County 840820 motion sacking admission of late-filed contention re recent strike by unions representing LILCO amployees Certificate of Svc encl CHRISTMAN.J N Long Island Lighting Co CHRISTMAN.J N Hunton & Williams DSB 385 94/08/27. Atomic Bafety and Licensing Board Panel 27pp 26305 194 24X Fiche 50-322,84/08/27,8408300124
- 8408300161 Order extending time until 840912 for Commission to act to review ALAB-777 Served on 840829 CHILK:S J Office of the Secretary of the Commission DSB 388 84/08/29 Commissioners 1p 26304 342 24X Fiche 50-322:84/08/29.8408300161
- 8408310224 Supplemental motion to strike portions of joint direct testimony of RN Anderson, 50 Christensen, 60 Eley. A Bakshi, 10 Bridenbaugh & RB Hubbard Certificate of Svc encl Related correspondence FARLEY, EM Long Island Lighting Co. FARLEY, EM Hunton & Hilliams 10 BB 422 84/08/27 Atomic Safety and Licensing Board Panel. 1799 26317:257 24% Fiche 50-322,84/08/27,8408310224
- 8408310218 Forwards attachments omitted from applicant motion to strike Incomplete dispositions of RN Anderson D Eley, RB Hubbard & SQ Christensen encl Related correspondence FARLEY,E M Hunton & Williams FARLEY,E M Long Island Lighting Co D88 424 84/08/30 BRENNER.L. FEROUBON,Q A, MORRIE,P A Atomic Safety and Licensing Board Panel Sipp 26318 127 24X Fiche 50-322,84/08/30,8408310218

## H General correspondence

- 8408070211 Ack receipt of 840622 ltr to Palladino requesting infore safety questions raised by AR Huber Concerns highlighted in Huber 830307 list, encompassing design const & testing, involve no vigistions of NRC regulations
  DIRCKS.W J Office of the Executive Director for Operations
  84/07/25 CARNEY.W House of Rep 4pp 25937 054 24X
  Fiche 50-322.84/07/25.8408070211
- --8408070217 Forwards JW Huber 840612 ltr re safety questions noted during employment by util Info addressing Huber contentions requested W/840611 telcon record CARNEY, W House of Rep. 84/06/22 PALLADINO, N J. Commissioners 3pp. 25957-057 24X Fiche 50-322,84/07/25,8408070211
- 108280054 Responds to 840717 ltm re plant completion & startup Issues under consideration include adequacy of emergency plan & adequacy of onsite emergency diesel generators
  DIRCKB.H J Office of the Executive Director for Operations
  84/08/20 SPENCER.F D. House of Rep 7pp 26309 001 24X
  Fiche. 50-322,84/08/20,8408280054
- -8408280056 Forwards NC Putnam ltr urging completion of plant & development of evacuation plan SPENCE.F D House of Rep 84/07/17 PALLADING.N J Commissioners 2pp 26309 007 24% Fichs 50-322,84/08/20,8408280054.
- , Inspection reports, IE Bulletins & correspondence
- 40B0B0473 Forwards IE Insp Rept 50-322/84-22 on 840514-18 No violations noted MARTIN.T T Division of Engineering & Technical Programs 84/07/16 LEGNARD.J.D Long Island Lighting Co 2pp 25975 164 24X Fichs 50-322.84/07/16.8408080473

- --B408080478 lE Insp Rept 50-322/84-22 on 840514-18 No violations noted Hajor areas inspected plant facilities & initial fuel load by startup testing planning Safeguards info deleted (ref 10CFR73 21)
  BLUMBERG, N., KUCHARSKI, S., BETTENHAUSEN, L., Region 1, Office of Director 84/07/05 App. 25975 166 24X Fiche 50-322.84/07/16, 8408080473
- 8408090315 Forwards IE Insp Rept 50-322/84-14 on 840416-27 No violations noted MARTIN, T.T. Division of Engineering & Technical Programs 84/07/16 LEONARD, J.D. Long Island Lighting Co. 2pp. 25994 072 24X Ficha 50-322.84/07/16.8408090315
- --8408090330 IE Insp Rept 50-322/84-14 on 840416-27 No violations noted Hajor areas inspected licensed action on previous inspected findings & NRC bulletins & circulars FINKEL: A : NAPUDA: G : NICHOLAS: H Region I. Office of Director 84/06/25 40pp 25974 074 24X Fiche 50-322.84/07/16,8408090315
- 8407250229 IE Info Notice 84-57, "Operating Experience re Maisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25845 047 24X Fiche 50-000.84/07/27, 8407250229
- 8408160251 Forwards IE Insp Rept 50-322/84-24 on 840626-29 No violations observed MARTIN, T T Division of Engineering & Technical Programs 84/08/09 LEONARD, J D Long Tsland Lighting Co 4pp 26106 193 24X Fiche 50-322,84/08/01,8408160251
- --B408160260 IE Insp Rept 50-322/B4-24 on B40626-29 No violations identified Hajor areas inspected civil/structural facilities re const of emergency diesel generator bldg & review of design & observation of const activities VARELA.A A , DURR.J P Region 1. Office of Director 84/07/20 Spp 26106 197 24X Fiche 50-322.84/08/01.8408160251
- 8408230242 Forwards 1E Insp Rept 50-322/84-25 on 840626-29 No viglations noted MARTIN.T T Division of Engineering & Technical Programs 84/08/03 LECNARD.J D Long Island Lighting Co 4pp 26213 284 24% Fiche 50-322,84/08/03,8408230242
- --8408230248 IE Insp Rept 50-322/84-25 on 840626-28 No violations noted Hajor areas inspected licensee action on previous insp findings.bulleting & circulars
  NIMITI,R L. Region 1, Office of Director PASCIAK,W J. Division of Engineering & Technical Programs 84/08/02 10pp 26213 288 24% Fiche 50-322,84/08/03,8408230242
- B408010333 IE info Notice 84-89. "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JRRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 198 24X Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Info Natice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Ficho 50-000,84/08/08,8408070120
- B40B290478 Forwards Insp Rept 50-322/84-23 on 840528-0701 No violations noted STAHOBIECKJ.R Division of Project & Resident Programs 84/08/08 LEDNARD.J L Long Island Lighting Co App 26294 189 24X Fiche 50-322.84/08/08.8408290478
- --B408290483 Insp Rept 50-322/84-23 on 840528-0701 No violations noted Major areas inspected discharge of security guard weapon, status of Colt dissel generator project, storage of ensigency equipment lockers & IE Bulletin 80-06, PETRONE, C. ESELGROTH, P. SHEDLOSKY, J. Region 1, Office of Director 84/07/19 12pp 26294 193 24X Fiche 50-322,84/08/08,8408290478
- --B408290486 Forwards directive & associated procedure for tightening diesel engine reassembly program in connection w/diesel generator rocker arm incident POLLOCK.M S Long Island Lighting Co 84/01/13 MURLEY.T E Region 1. Office of Director Spp 26274 211 24X Fiche 50-322, 84/08/08,8408270478

- 8408070376 [E Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc
  - list encl
    ORACE.J N Division of QA. Safeguards & Inspection Programs (Post
    830103) 84/08/10 Consolidated Edison Co of New York, Inc
    125pp 26/30 001 24X Fiche 50-000.84/08/10,8408070376
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping"
  - Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co. of New York, Inc. 119pp 26197 218 24X Fichs 50-000, 84/08/13, 8408100009
- 8408100038 IE Info Notice 84-64. "BWR HPC1 Initiation Seak-In & Indication "Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co
  - 26198 093 24X Fiche 50-000,84/09/15,8408100038 York, Inc 104pp
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc
  - list encl
    JORDAN, E.L. Division of Emergency Preparedness & Engineering
    Response (Post B30103) B4/08/16 Consolidated Edison Co. of New
    York, Inc. 118pp 26198 001 24X Fiche 30-000,84/08/16,8408100021
- 8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- B40814020B IE Info Notice 84-67. "Recent Snubber Inservice Testing W/ High Failure Rates " Byo list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B470B/17 Consolidated Edison Co
  - 26276 122 24X Fiche 50-000, 84/08/17, 8408140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 119pp 26329 008 24X Fiche 50-000.84/08/21.8408210142
- 8408280180 Informs that performance acceptable during period of const completion & readiness for operation, per SALP Util performance & responsiveness to NRC concerns improved during past yr MURLEY, T & Region 1. Office of Director 84/08/21 LEONARD J D Lighting Co Spp 26275 037 24% Fiche 50-322, Long Island Lighting Co 84/08/21,8408280180
- --9409280187 Responds to 840514 itr forwarding SALP rept for period Feb 1983 Feb 1784 Details of action being taken on functional areas will be addressed on site w/NRC resident
  - inspector LEGNARD, J D LEGNARD, J D Long Island Lighting Co 84/06/26 STAROSTECKI, R Division of Project & Resident Programs 4pp 26275 042 24X Fiche 50-322,84/08/21,8408280180
- S Reportable occurrences, LERs & related correspondence
- 8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated SHERWGOD, G General Electric Co 84/04/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 30-000, 84/04/13, 8408240348
- 8405290062 Forwards "Investigation of Types AF & AE Piston Skirts " TOWERVOURE TOPWARDS "INVESTIGATION OF Types AF & AE Piston Skirts "
  Rept supercedes 840227 submittal
  RAY.C L 1D1 (Transamerica Delaval, Inc.) Dwners Group RAY.C L
  Duke Power Co 84/05/24 DENTON.H R Office of Nuclear Reactor
  Regulation, Director 2pp 24690 045 24% Fiche 50-000,84/05/24,
  8405290042
- --8409290075 "Investigation of Types AF & AE Piston Skirts "
  \* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp
  24% Fiche 50-000,84/05/24,8405290062
- B405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "RAY,C L TDI (Transamerica Delaval, Inc.) Dwners Group RAY,C L Duke Power Co B4/05/24 DENTON.H R Dffice of Nuclear Reactor Regulation. Director 2pp 24692 090 24X Fiche 50~000, B4/05/24, B405290179
- --8405290271 "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations " \* Failure Analysis Associates FAAA-84-3-16 84/05/22 89pp 24692 072 24X Fiche 50-000,84/05/24,8405290179

- B408060405 Forwards repts received by BNML & consultants directly from FaAA & TDI Owners Oroup at 840622 meeting Draft "Overview of Repts Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl ALZHEIMER. J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER. M Division of Licensing 158pp 25926 173 24X Fiche 50-000.84/06/28.8408040405
- 8408060050 Forwards info addressing open items identified in NRC/BNML/TDI Diesel Generator Owners Group 840622 meeting RAY, C L. TDI (Transamerica Delaval. Inc.) Owners Group RAY, C L. Duke Power Co. 84/07/10 HERLINGER, C. Director's Office, Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 30-000.84/07/10.8408060050
- 8408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to DNNL RAY.C L TDI (Transamerica Delaval, Inc.) Quiners Group RAY.C L Duke Power Co. 84/07/27 DENTON:HR Office of Nuclear Reactor Regulation. Director 2pp 25932 137 24% Fiche SO-QCO.84/07/27, 8408060102
- ---B40B060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " \* Stone & Webster Engineering Corp 84/07/31 34pp 25932 139 24X Fiche 50-000, 84/07/27, 8408040102
- 8408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
  - Sets "
    RAY, C L TDI (Transamerica Delaval: Inc.) Dwners Group RAY, C L
    Duke Power Co B4/08/01 DENTON, H R Office of Nuclear Reactor
    Regulation, Director 2pp 25927 064 24% Fiche 50-000, B4/08/01,
    B408060324
- B408160394 Forwards "Design Review of Engine Base & Dearing Caps for TDI DERV-16 Diesel Engines "
  RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group RAY.C L
  Duke Power Co. 84/08/10 DENTON.H R Office of Nuclear Reactor
  Regulation, Director 2pp 26091 147 24X Fiche 50-000, 84/08/10, 8408160394
- --8408160403 "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines " # Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp 26091 149 24% Fiche 30-000,84/08/10,8408160394
- 8408240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program testing & insp. maint & surveillance & sets forth requirements for operation prior to completion of program plan EISENHUT, D. G. Division of Licensing 84/08/13 GEORGE, J. B. TDI (Transamerica Delaval, Int.) Owners Group GEORGE, J. B. Texas Utilities Electric Co. (Formerly Texas Utilities Generating Co.) 1p. 26255 194 24X Fiche 50-000.84/08/13.8408240115
- --B40B240157 Safety evaluation of TDI Owners Group program plan Based on BRWL evaluation.plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc \*\* NRC ~ No Detailed Affiliation Given B4/0B/13 2ipp 24255 175 24X Fiche 50~000,B4/0B/13,B40B240115
- 8408160395 Forwards "Design Review of Elliott Model 900 Turbocharger Used on TDI DER-48 & DSRV-16 Emergency Diesel Generator Sets." representing final GA verified rept Addl copy forwarded to BNHL, per NRC request RAY.C. L TDI (Transamerica Delaval. Inc.) Gunera Group RAY.C L Duke Power Co. 84/08/14 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 26088 163 24X Fiche 50-000.84/08/14, 8408163087 Regulation, Director 8408160395
- --8408160397 "Design Revieu of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Energency Diesel Generator Sets "

  \* Failure Analysis Associates FAAA-84-5-7 84/07/31 6ipp 26088 165 24X Fiche 50-000,84/08/14.8408160395
- B408290179 Forwards response to 840723 request for add1 (nfo on repts submitted by TDI Diesel Generator Guners Group RAY, C L TDI (Transamerica Delaval, Inc.) Guners Group RAY, C L Duke Power Co. 84/08/23 BERLINGER, C. Office of Nuclear Reactor Regulation, Director 12pp 26289 221 24X Fichs 50-000, 84/08/23, 8408290179
- T Hearing transcripts on non-antitrust matters
- 8406220259 Board Notification 84-120 forwards transcripts of 840426. 00502 & 24 meetings u/TDI Cumers Group re status of program to establish diesel generator reliability EIEENHUT, D © Division of Licensing 84/06/20 PALLADING OILINEXY, ROBERTS Commissioners 54pp 25206 099 24X Fiche 50-000, 84/06/20, 8406220259 PALLADINO,

- B408010077 Transcript of A Kessel 840702 deposition in New York, NY Pp.
  - 1-93
    \* Atomic Safety and Licensing Board Panel KESSEL.R New York,
    State of 84/07/02 94pp 25856 133 24x Fiche 50-322,84/07/02,
    8408010077
- B408020021 Direct testimony of EP Radford & SC Sargert re Contention 16 E Certificate of Svc encl Related correspondence RADFORD.E P . SAEGERT.S C Suffolk County. NY RADFORD.E P Pittsburgh. Univ of Pittsburgh. PA DSB 694 B4/07/30 16pp 25882 284 24x Fiche 50-322.84/07/30.8408020021
- 8408020024 Motion to admit revised testimony of Phase [] emergency planning Contentions 24 0.74 & 75 (relocation ctrs)
  Certificate of Svc enc; Related correspondence
  MCCLESKEY, K E Long Island Lighting Co MCCLESKEY, K E Hunton & Williams DSB 698 84/07/30 Atomic Safety and Licensing Board Panel 48pp 25883 150 24X Fiche 50-322,84/07/30,8408020024
- 8408020048 Testimony of CA Clayson, MC Cordaro & RJ Watts on Contention 16 E re public info on radiation Certificate of Svc encl Related corressondence CLAMBON, CA. CORDARD, M. C. WATTS, R. J. Long Island Lighting Co 697 84/07/30 40pp 25883 275 24% Fiche 50-322,84/07/30,
- 8408060078 Transcript of 840730 hearing in Hauppauge, NY Pp 714-1,027 Supporting documentation encl \* Atomic Safety and Licensing Board Panel 84/07/30 347pp 28722 017 24X Fiche 50-322.84/07/30,8408060078
- B40B020129 Joint direct testimony of RN Anderson. SC Christensen.
  Ob Eley. A Bakshi. DS Bridenbaugh & RB Hubbard to Suffolk
  County emergency diesel generator contentions Certificate of
  Svc encl Related correspondence
  ANDERSON. R N San Jose State Univ. San Jose. CA CHRISTENSEN, S
  U S Nerchant Marine Academy. Kings Point. NY ELEY. G D Grean
  Fleets Consultancy Service DSS 707 B4/07/31 1326pp 25886 223
  24X Fiche S0-322.84/07/31,8408020129
- 8408060086 Transcript of 840731 hearing in Hauppauge, NY re low power license Pp 1,028-1,347 \* Abomic Safety and Licensing Board Panel 84/07/31 321pp 23927 125 24X Fishe 50-322,84/07/31,8408060086
- 8408030105 Motion to admit proposed modified emergency planning Contention 89 & revised testimony of GC Minor on emergency planning Contentions 85 & BB Related correspondence MILLER, M S Suffolk County, NY MILLER, M S Kirkpatrick, Lockhart, Mill, Christopher & Phillips DSB 725 84/08/01 Atomic Safety and Licensing Board Panel 11pp 25916 055 24X Fiche 50-322,84/08/01,8408030105
- --B40B030112 Revised testinony of GC Minor on emergency planning Contentions B5 & B8 re offsite recovery & reentry Prof qualifications statement & Certificate of Svc encl MINOR, G C Suffolk County, NY MINOR, G C MHB Technical Associates B470B701 18pp 25916 066 24X Fiche 50-322, B470B701, 840B030105
- B4080B0039 Transcript of B40B01 hearing in Hauppauge,NY Pp 1.350 - 1.676 \* Atomic Safety and Licensing Board Panel 84/08/01 328pp 25969 335 24% Fiche 50-322.84/08/01/8408080039
- 8408080042 Transcript of 840802 hearing in Hauppauge.NY Pp 1.677-1.948 \* Atomic Safety and Licensing Board Panel 84/08/02 272pp 28961 061 24X Fiche 50-322.84/08/02.8408080042
- 8409070352 Testimony of SA Schwartz re emergency preparedness Contention II Certificate of Syc encl Related Correspondence
  SCHMARTZ.8 A Division of Emergency Preparedness & Engineerin
  Response (Post 833103) DSB 819 84/08/03 9pp 25945 200
  Fiche 50-322,84/08/03,8408070352
- 8408080190 Transcript of 840803 hearing in Hauppauge.NY Pp 1,749-2,196 \* Atomic Safety and Licensing Board Panel 84/08/03 250pp 25959 028 24% Fiche 50-322.84/08/03,8408080150
- 8408080035 Transcript of 840804 hearing in Riverhead, NY Pp 2,197-2,332 \* Atomic Safety and Licensing Board Panel 84/08/04 141pp 25962 006 24% Fiche 50-322.84/08/04,8408080035
- 9408130373 Testimony on training Contentions 39, 40, 41, 44, 98, 99 & 100 Pp 101-111 Certificate of Svc encl Related correspondence \* Federal Emergency Management Agency DSB 903 B4/08/06 14pp 26011 001 24X Fiche 50-322,84/08/06,8403130373

- 8408140391 Transcript of 840806 hearing in Hauppauge NY re low power operation Pp 2.333-2 657

  \* Atomic Safety and Licensing Board Panel 84/08/06 325pp 26053 001 24% Finhe 50~322.84/08/06.8408140391
- 8408140339 Transcript of 840807 hearing in Hauppauge.NY re low power operation Pp 2.658-2 968

  + Atomic Safety and Licensing Board Panel 84/08/07 311pp
  26041 165 24% Fiche 50-322.84/08/07/8408140339
- 840B130209 Transcript of B40B0B conference of counsel in Bethesda,MD re emergency planning procedure Pp 13,985-14,041 Supporting documentation encl \* Atomic Safety and Licensing Board Panel 84/08/08 64pp 26008 001 24x Fiche 50-322,84/08/08,840B130209
- 8408140255 Transcript of 840808 conference of counsel in Bethesde, MD re energency planning Pp 13, 985-14, 041 Supporting documentation entr. # Atomic Safety and Licensing Board Panel 84/126054 276 24X Fiche 50-322, 84/08/08, 8408140255 84/08/08 62pp
- 8408140013 Forwards table of contents for RN Anderson 840731 joint direct testimony re Model AE pistons, replacement cylinder heads & cylinder blocks, per ASLB 840801 order on miscellaneous prehearing matters Related correspondence DVNNER, A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips DVNNER, A R Suffolk County, NY DSB 755 84/08/09 BRENNER, L J, FERGUSON, G A, MORRIS, P A, Atomic Safety and Licensing Board Panel ip 26044 162 24% Fiche 50-322,84/08/09,8408140013
- --8408140017 Table of contents for RN Anderson B40731 joint direct testimony re Model AE pistons, replacement cylinder heads, replacement crankshafts & cylinder blocks ANDERSON, RN Suffoll County, NY 84/07/31 3pp 26044 163 24X Fiche 50-322,84/09/09,8408140013
- 8408190473 Forwards direc+ testimony & supporting exhibits on adequacy & reliability of TDI emergency diesel generators N/o motion for protective order Certificate of Svc encl Related TOP PROTECTIVE GROWN CERTIFICATE OF SECRET, Related Correspondence
  TARLETZ.D B Hunton & Williams TARLETZ.D B Long Island Lighting
  Co DBB 065 84/08/14 BRONER.L , FERGUSDN.O A , MORRIS, P A
  Atomic Safety and Licensing Board Panel 4pp 26068 295 24X
  Fiche 50-322.84/08/14.8408150473
- --8408150474 Testimony of CH Uclis.DP Johnson.HF Wachob, C Seaman, D Claimo & NK Burrell re shotpeening of replacement crankshafts Related correspondence NELLS, C H. JUHNSON, D P., WACHOB, H.F. Long Island Lighting Co 84/08/14 36pp 26058 299 24x Fiche 50-322.84/08/14.8408150473
- --8408150465 Testimony of HL McCarthy,PR Johnson,EF Montgomery & 6K Chen on Suffolk County contention re replacement crankshafts on diesel generators Related correspondence MCCARTHY,R L. JOHNSON,P R. INDNTOMERY,E F. Long Island Lig Co. 84/08/14 62pp 24068 337 24X Fiche 50-322,84/08/14 8408150473
- --9408150478 Testimony of EJ Youngling & FF Pischinger on Suffolk County contention re replacement crankshafts on diesel generators Exhibits encl Related correspondence YOUNGLING: EJ, PISCHINGER, FF Long Island Lighting Co 84/08/14 & 600pp 26069 036 24% Fiche 50-322,84/08/14,8408150473
- --B400150505 Vols 1.2 & 3 of testimony of RL McCarthy.CA Rau,CH Wells.
  HF Wachob,D Johnson.RK Taylor.CK Seaman.EJ Youngling.
  CS Mathews.HH Lourey.JF Wallace & MH Schuster on Suffolk
  County contention re cylinder blocks Related correspondence
  HCCARTHY.R L , RAU.C A , WELLS.C H Long Island Lighting Co
  B4/08/14 300pp 26070 313 24X Fiche 50-322,84/08/14,
  B408150473
- --B408150514 Vols 1 & 2 of testimony of DO Harris, DP Johnson, RL McCarthy. FF Pischinger, CK Seaman, I A Swanger & EJ Youngling on Suffolk County contention re AE piston skirts Related correspondence CO, PESSURGENCE

  HARRIS D D , JOHNSON, D P , MCCARTHY, R L. Long Island Lighting Co
  84/08/14 450pp 26071 200 24% Fiche 50-322,84/08/14,8408150473
- --8408150530 Vols 1 & 2 of testimony of CK Scaman,EJ Youngling,
  JC Kammeyor,CH Wells,LA Bwanger,JF Wallace,CS Mathews &
  FC Pischinger on Suffelk County contention re cylinder
  heads Exhibits I-26 encl Related correspondence
  BEAMAN,C K, YOUNGLING,E J, KAMMEYER,J C Long Island Lighting
  Co 84/08/14 300pp 26072 327 24X Fiche 50-322,84/08/14,

- 8408210209 Transcript of 840814 hearing in Hauppauge, NY re emergency planning Pp 14.042-14.240

  Atomic Safety and Licensing Board Panel 84/08/14 256pp 26147 124 24/ Fiche 50-3F2 84/08/14.8408210209
- 8408210035 Transcript or 810815 heating in Hauppauge, NY re emergency planning Pp 14.214-14.503 
  \* Atomic Safety and Licensing Board Panel 84/08/15 253pp 
  26146 165 24X Fiche 50-322.64/08/15.8408210035
- 8408210458 Transcript of B40816 hearing in Hauppauge, NY re emergency planning Pp 14, 504-14, 488 \* Atomic Safety and Licensing Board Panel 84/08/16 187pp 26177 001 24% Fiche 50-322, 84/08/16, 8408210458
- 8408280020 Transcript of 840816 Commission meeting in Washington,DC reaffirmation/discussion % vate Pp 1-7
  % Commissioners 84/09/16 10pp 26294 013 24X
  Fishe 50-000.84/08/18.8408280020
- 8408280135 Transcript of 840821 hearing in Hauppauge, NY
- - Pp 14,689-14,904A \* Atomic Safety and Licensing Board Panel 84/08/21 288pp 26259 213 24X Fiche 50-322,84/08/21,8408280135
- 840B280151 Transcript of 840B22 hearing in Hauppauge,NY re emergency planning Pp 14,907-15,176 Supporting documentation encl # Atomic Safety and Licensing Board Panel 84/08/22 294pp 26264 161 24X Fiche 50-322,84/08/22,840B280151
- 8408280004 Transcript of 840823 hearing in Hauppauge, NY
- Pp 15, 178-15, 242 \* Atomic Safety and Licensing Board Panel 84/08/23 329pp 26260 143 24X Fiche 50-322, 84/08/23, 8408280004
- B4082B0394 Forwards corrected master table of contents for testimony on crankshafts, pistons, cylinder heads & cylinder blocks Related correspondence RANDE, J Hunton & Williams RANGE, J Long Island Lighting Co DBB 352 84/08/24 BRENNER, L. MORRIS, P.A. FERGUSON, G.A. Atomic Safety and Licensing Board Panel 1p 262B0 03B 24X Fiche 50-322,84/08/24 840B280394
- --8408280397 Corrected master table of contents for testimony on crankshafts, pistons, cylinder heads // cylinder blocks Related correspondence \* Long Island Lighting Co 84/08/23 7pp 26280 039 24X Fiche 50-322,84/08/24

#### V Operator Examinations

- 8408070385 Forwards shift advisors resumes, per 840702 ltr in response to NRC 840531 request Shift advisors w/o operator license will be examined, per 10CFR55 50. "Exam Form "LEONARD, J D Long Island Lighting Co 84/07/25 DENTON, H R Office of Nucleum Reactor Regulation, Director 10pp 25945 269 24% Fiche 50-322 84/07/25.8408070385
- 8408060323 Forwards response to NRC comments on licensed operator requalification program LEOMARD. J D Long Island Lighting Co 84/07/31 DENTON, H R Office of Nuclear Reactor Pegulation, Director 4pp 25933 331 24% Fiche 50-322.84/07/31,8408040323
- 8408300123 Forwards updates on operating shift staffing submittals dtd 831221 t 8408322.per 840831 request Updates include qualification matrices for onsite mpt operating shift personnel t shift technical advisors LEDNARD.J D Long Island Lighting Co 84/08/21 DENTON.H R Office of Nuclear Reactor Regulation, Director 11pp 26306 07: 24% Fiche 50-322.84/08/21.8408300123 26306 077
- DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8408310138 FOIA request for positive identification of Mothers for Peace of San Luis Obispo & calculations performed by POWE re earthquake on Nacimiento fault & one equal to 1906 San
  - re earthquake on MacLimiento fautt & one equal by the Francisco earthquake CALSGYAS, C D Affiliation Not Assigned 84/04/07 Detailed Affiliation Glyen App 26332 011 24X Fiche 90-275,84/04/07,8408310138 NRC - No

- 8408310142 Responds to FOIA request for positive identification of Mothers for Peace of San Luis Obispo & calculations performed by PGSE re earthquake Forwards printout of documents re Mothers for Peace Other documents in PDR FELTON. J M Divisian of Rules and Records 84/06/01 CALSOYAS. Affiliation Not Assigned ip 26352 015 24% Fiche 50-275,84/06/01.8408310142 CALBOVAS C D
- 8408300482 Requests exam & test requirements for all presently licensed personnel for Unit 1 be waived for Unit 2 % combined DLs for Units 1 & 2 be issued Supporting documentation encl Related correspondence CONTESPONDENCE
  SCHUYLER, J Q, CRANE, P A Pacific Gas & Electric Co DSB 720
  B4/07/17 Martin, J B, PATE, R J Region 5, Office of Director
  BBpp 26329 189 24x Fiche 50-275,84/07/17,8408300482
- 8408140011 Forwards 840713 rept. "June 20,1984 Santa Maria Offshore Earthquake, Ground Hotton at Diablo Canyon Power Plant" Rept contains tabulation of peak accelerations & recorded accelerograms SCHUVLER, J. O. Pacific Gas & Electric Co. 84/07/20 EISENHUT, D. G. Division of Licensing ip 26044 128 24X Fishe 50-275,84/07/20, page 140014
- --B408140012 "June 20, 1984 Senta Maria Offshore Earthquake, Ground Motion at Diablo Campon Power Plant"

  \* TERA Corp 84/07/13 33pp 26044 129 24X Fiche 50-275, 84/07/20, 8408140011
- 8408060120 Forwards tube steel review in response to NRC 840717 verbal request re existence of tube steel of suspect quality Results confirm problem identified in one 20-ft section not Used in pipe support installation
  SCRWYLER, J O Pacific Oas & Electric Co 84/07/26 MARTIN, J B
  Region 5, Office of Director Jpp 25933 194 24X
  Fiche 50-323,84/07/26,8408060120
- 8408040124 Forwards IDVP internal review program summary & status rept, describing scope, methodology & status of resolution of verification issues SCHVYLER.J O Pacific Gas & Electric Co 84/07/31 KNIGHTON, 8 W Licensing Branch 3 49pp 25932 199 24X Fiche 50-323,84/07/31, Licensing Branch 3 8408060126
- 8408070278 Forwards comparison of safety-related design aspects of Unit 2 relative to Unit 1.in response to NRC request & to support licensing of Unit 2 SCHUYLER, J O Pacific Cas & Electric Co 84/07/31 KNIGHTON, O Licensing Branch 3 5pp 25948 101 24X Fiche 50-323,84/07/31, 8408070278 KNIGHTON, A M
- 8408310032 Forwards Ofc of Inspector & Auditor 840801 rept of investigation re allegations against seven NRC employees as result of T Devine 840912 t 0503 100FR2 205 petitions on NRC misleading or natl false statements to Commission MESSENGER G H Office of Inspector & Auditor 84708/01 P/ROBERTS, ASSELSTINE Commissioners 2pp 26347 001 24X Fiche 30-275.84/08/01.8408310032 PALLADINO
- --B408310035 Investigation rept on 840801 Major areas investigated allegations re MRC misleading or mat1 false statements to Commission Juring 840319.26 & 27 briefings & in SSER 21 & 22 for Dec 1963 & Mar 1984, respectively SMITH, R M. BOWERS, H., MESSENGER, O. H. Office of Inspector & Auditor 84/08/01 400pp 26349 003 24X Fiche 50-275, 84/08/01, 8608230032
- 8408070110 Ceneric Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933. "Prioritization of Generic Safety Issues" Svc list one! EIEENHUV.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000.84/08/06.8408070110
- 8408130188 Forwards proposed changes in post-fuel loading initial test program re test scope clarification & conducting existing tests at add1 (lower) power plateaus Review & approval required by 840828 SCHUVLER, J C Pacific Oas & Ejectric Co 84/08/08 KNIGHTON, O Licensing Branch 3 3pp 24008 288 24X Fiche 50-275, 84/08/08, 8408130188 KNIGHTON, O. W.
- 8408210639 Forwards SLO-2 work request & work authorization mistakenly omitted from 84080i ltr PETERS.R J Pacific Gas & Electric Co 84/08/08 MITCHELL-WILGON California, State of 2pp 26184 351 24X Fiche 50-275,84/08/08,

- 8408210406 Requests approval for removal of RHR suction valve automatic closure interlock Upon approval.util will install alarms & restore power to RHR suction valve operators during periods of RHR sys operation while aligned to RCS SCHUYLER.J Q Pacific Cas & Electric Co 84/08/15 KNIGHTGN.0 W Licensing Branch 3 2pp 26180 336 24% Fiche 50-275.84/08/15, 8408210406
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl RIBENHUT, D © Division of Licensing 84/08/20 Consolidated Edison Co of New York Inc 17pp 26276 244 24% Fiche 50-000.84/08/20.8408200275
- 8408270396 Forwards request for extension of const completion date until 850930 SCHUYLER.J O Pacific Gas & Electric Co 84/08/22 KNIGHTON.G H Licensing Branch 3 2pp 26238 144 24X Fiche 50-323.84/08/22.84082/0394
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8408140273 Forwards 69 photos attesting to serious long-range problems of erosion of siltation on property contiguous to facility Requests name of responsible NRC employee to respond to concerns

  8RUND, G E Affiliation Not Assigned 83/07/11 DENTON.H Office of Nuclear Reactor Regulation, Director 38pp 26051 203 24X

  Fiche 50-275,83/07/11,8408140273
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 840731003B Board Notification 84-137 forwards SBERs 24-27 re IDVP matters, piping & supports, allegations status & summary & full power license amend matters, respectively No substantive changes made W/o encls EISENHUT, D © Division of Licensing 84/07/30 PALLADINO, ROBERTS, ASSELSTINE Commissioners 3pp 26011 015 24X Fiche 50-275,84/07/30,840731003B
- 8408130002 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 & 2 Docket Nos 50-275 & 50-323 (Pacific Gas & Electric Company) \* Division of Litensing NUREC-0675 524 84/07/31 16pg 24038 295 24x Fiche 50-275.84/07/31,8408130002
- 8408160080 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 AND 2 Docket Nos 50-275 And 50-023 (Pacific Cas And Electric Company)

  \* Division of Licensing NUREG-0675 S25 84/07/31 122pp
  Available at NRC \$5 50 26124 033 24X Fiche 50-275,84/07/31,8408160080
- 8408160250 BAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 AND 2 Docket Nos 50-275 And 50-232 (Pacific Oas And Electric Company) \*\* Division of Licensing NUREG-0675 S27 84/07/31 31pp Available at NRC \$3 50 26122 235 24X Fiche 50-275,84/07/31,8408160250
- 8408220346 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT.UNITS 1 AND 2

  \* Division of Licensing, NUREG-0675 826 84/07/31 204pp
  Available at NRC \$6.50 26200 001 24X Fiche 50-275,84/07/31,8408220346
- F Security, medical, emergency & fire protection plans
- 8408080453 Forwards public version of revs to Vol III of San Luis Obispo County emergency response plan std operating procedures SCHUYLER.J O Pacific Oas & Electric Co 84/07/16 MARTIN.J B Region 5, Office of Director 2pp 25976 071 24X Fiche 50-275.84/07/16:8408080453
- --8408080458 Public version of revs. to Vol III of San Luis Obispo County smargency response std operating procedures (80P), including Section III 01, "SDP Emergency Svcs Director " W/Felton 840802 release memo SCHUYLER, J O Pacific Gas & Electric Co 84/02/29 434pp 23976 073 24X Fiche 50-275.84/07/16,8408080453
- 8408160267 Forwards public version of emergency plan implementing procedures including EP R-1 repersonnel injury or illness (nadialogical related) &/or overexposure & EP M-1 reemployee injury or illness (nonradiological) SCHUYLER.J D Pacific Oas & Electric Co. 64/07/20 MARTIN.J D Region 5. Office of Director App. 26125 237 24X Fichs 50-275.84/07/20.8408160267

- --8408160273 Public version of emergency plan implementing procedures, including EP R-1 re personnel injury or illness (radiological related) %/or overexposure W/JM Felton 840808 relasse memo = Pacific Gas & Electric Co 84/07/20 138pp 26125 243 24% Fiche 50-2/5 84/07/20, 840816026/
- 8408230553 Forwards public version of updated emergency plan implementing procedures, including EP R-1 re personnel injury or illness (radiologically related) \*/or overexposure \* EP G-4 re personnel accountability & assembly SCHUYLER.J O Pacific Cas & Electric Co 84/08/08 MARTIN.J B Region 5, Diffice of Director 1p 26216 206 24X Fiche 50-275,84/08/08.8408230553
- --R408230558 Public version of updated emergency plan implementing procedures, including EP R-1 re personnel injury or iliness (radiologically related) 8/or overerposure & EP G-4 re personnel accountability 8 ossembly W/840820 release memo THORNDERRY, R C Pacific Gas & Electric Co 84/08/08 182pp 26214 207 24X Fiche 50-275.84/08/08.8408230553
- 8408230300 Forwards RW Kilom 840711 ltr transmitting FEMA interim finding in State of CA energency response plan Plan adequate Areas for improvement identified, including protective action guideline doses KNIOHTON, GW Licensing Branch 3 84/08/16 SCHUYLER, J O Pacific Qas & Electric Co 3pp 26236 105 24X Fiche 50-275, 84/08/16, 8408230300
- 8408310230 Revised emergency plan implementing procedures, including EP R-2 re release of airborne radioactive matls, EP E1-6 re EARS 7843c controling stations & EP RB-15 % 16 re sentry post-accident sampling sys W/840827 ltr SCHUYLER, J O Pacific Gas & Electric Co 84/08/27 MARTIN, J B Region 5. Office of Director 363pp 26321 001 24X Fiche 50-275,84/08/27,8408310230
- G Adjudicatory correspondence
- B40B010235 Forwards affidavit of JL McDermott.per B40729 submittal Supporting brief will be sent to Commission on 640730 along w/O'Neill rebuttal affidavit BEVINE.T Government Accountability Project D80 681 B4/07/30 PALLADING,N J , ROBERTS.T , ASSELSTINE,J Commissioners ip 25854 001 24x Fiche 50-275,84/07/30,8408010235
- --8408010237 Affidavit of JL McDermott re need for reinsps & systematic retraining of all personnel at facility MCDERMOIT, J L Government Accountability Project 84/07/30 35pp 25854 002 24X Fiche 50-275,84/07/30,8408010235
- 8408060046 Motion for leave to withdraw confidential Exhibit 10 filed in support of Joint Intervenors 840214 motion to augment or reopen record Declaration in support of motion & Certificate of Svc enc!

  REYNOLDS, J. R. Joint Intervenors Diablo Canyon REYNOLDS, J. R. Center for Law in the Public Interest DSB 676 84/07/30 Atomic Safety and Licensing Appeal Panel 9pp 25925 298 247

  Fichs 50-275,84/07/30.8408060046
- 8408060217 Motion for leave to withdraw confidential exhibit previously filed in support of motion to augment or to reopen record Declaration encl Granted on 840731 REYNOLOS.J R Joint Intervenors Diablo Canyon REYNOLOS.J R Center for Lau in the Public Interest DSB 708 84/07/30 Atomic Safety and Licensing Appeal Panel App 25927 015 24X Fiche 50-275.84/07/30 8408060217
- B40B020152 Forwards suppl supporting T 0'Neill 840727 petition under 10CFR2 206 on behalf of J McDermott & T O'Neill Also expands original sequest for retraining DEVINE: T Gevernment Accountability Project DBB 701 84/07/31 PALLADIND:N J Commissioners 327pp 23884 139 24X Fiche 50-275.84/07/31.8408020152
- B40B020219 Order requiring Joint Intervenors to file reply addressing jurisdictional question in 840716 motion to reopen record on seismic issues Served on 840801
  SHDEMAKER.C J Atomic Safety and Licensing Appeal Panel DSS 716
  84/08/01 Joint Intervenors Diable Canyon ip 25878 007 24%
  Fiche 50-275,84/08/01,8408020217

- 8408020222 Answer opposing icini Intervenors 840725 application for stay re effectiveness of ASLB 820931 initial Decision LBP-82-70 k of issuance of full power OL CHANDLER.L J. Hearing Branch 2 DSB 710 84/08/01 Commissioners lipp 25897 279 24x Fiche 50-2/5,84/08/01,8408020222
- --8408020227 Answer opposing Joint Intervenors 840717 petition for review of ALAB-775 Petition fails to establish existence of important issue of fact law or policy warranting Commission review

  CHANDLER, L. J. Hearing Branch 2 84/08/01 Commissioners 10pp 25897 270 24X Fishe 50-275.84/08/01 8108020222
- ---B408020231 Answer opposing Joint Intervenors 840717 petition for review of ALAB-776 Petition rails to establish existence of important question of fact, law or policy re ALAB-776 CHANDLER.L J Healing Branch 2 84/08/01 Commissioners 23pp 25897 300 24% Fishe 50-2/5,84/08/01.8408020222
- --8408020233 Ansuer opposing Joint Intervenors 840716 motion to reopen recard on seismic issues Motion fails to satisfy stds for reopening record Certificate of Svc encl CHANDLER.L J. Hearing Branch 2 84/08/01 Atomic Safety and Licensing Appeal Panel 11pp 25897 323 24X Fiche 50-275,84/08/01,8408020222
- 8408030154 Underscores need for prompt b favorable action on Northern California Power Agency 811204 petition under 10CFR2 206 to enforce & modify license conditions, based on recent evidence that util continues to violate license conditions MCDIARMID.R C Spiegel & McDiarmid 84/08/01 DENTON.H & Office of Nuclear Reactor Regulation. Director 592pp 25914 075 24X Fiche 50-275.84/08/01.8408030154
- 8408020197 Advises that time for Commission to review ALAB-756 expired Commission declined review Decision became final agency action on 840727 Served on 840802 CHILK.S J Office of the Secretary of the Commission DSB 717 B4708/02 REYNOLDS.J R . HAVIAN.C . PHILLIPS.J Center for Law in the Public Interest 1p 25898 001 24X Fiche 50-275.84/08/02, 8408020197
- 8408020206 Advises that time for Commission to review ALAB-756 expired Commission declined review Decision became final agency action on 840726 Served on 840802 CHILK, B J Office of the Secretary of the Commission DSB 718 64/08/02 STRUMMASSEN. 11 California, State of ip 25878 007 24X Fiche 50-275,84/08/02,8408020206
- 8408070265 Order extending time until 840810 for Commission to act to review Director's Decision DD-84-8 Served on 840806 CHILK, 5 J Office of the Secretary of the Commission DBB 756 B4/08/03 Commissioners 1p 27949 239 24X Fiche 50-275,84/08/03,8408070265
- 8408070361 Order extending time until 840830 for Commission to act to review ALAB-776 Served on 840806 CHILK.B J Office of the Secretary of the Commission DSB 755 84708703 Commissionners Ip 25945 177 24X Fiche 50-275,847
- 8408070467 Order extending time until 840810 for Commission to act to review ALAB-763 Served on 840806 CHILK, 9 J Office of the Secretary of the Commission DSB 752 84/08/03 commissionners 1p 25940 341 247 Fiche 50-275,84/08/03,8408070467
- 8408070183 Order ALAB-775A denying 840628 motion to reopen record on basis of add1 info provided by applicant re use of A307 hardware bolts Allegation does not present new evidence Served on 840808 SHOEMAKER.C J. Atomic Safety and Licensing Appeal Panel D5B 848 84708/08 Joint Intervenors Diablo Canyon 2pp 25772 286 24% Fishe 50-275.84/08/08,8408070(83)
- 8408130389 Reply supporting A8LAU 840801 order establishing
  Jurisdiction of A8LAU to review Joint Intervenor 840716
  motion to reopen record on seismic issues Certificate of
  Svc encl
  REYNOLOS, J. R. Joint Intervenors Diablo Canyon REYNOLDS, J. R.
  Center for Lau in the Public Interest D88 906 84708709 Atomi
  Bafety and Licensing Appeal Panel 8pp 26011 094 24X
  Fiche 50-275,84/08/09.8408130389
- B408140464 Reply re jurisdiction of ASLAB to consider B40716 motion to reopen record on seismic issues Motion should be granted Centificate of Svc onci HEYNOLDS:JR Joint Intervenors Diablo Canyon REYNOLDS:JR Center for Lau in the Public Interest DSB 017 B4/08/09 Atomic Safety and Licensing Appeal Panel Bpp 26061 015 24% Fiche 50-275,84/08/09,8408140464

- 8408140005 Memorandum & Order CLI-84-13, detelmining that full power license may be issued by NRR Order effective on 840817 Commissioner Zech statement & Commissioner Asselstine dissenting views encl Served on 840810 CHILK, S. J. Office of the Secretary of the Commission DS8 940 84708/10 Orfice of the Executive Legal Director 25pp 26045 001 24x Fiche 50-275.84/08/10.8408140006
- 8408140009 Decision CL1-84-12. Initiating rulemaking releffects of seismic events on emergency planning Addl views of Palladino & Bernthal & dissenting view of Asselstine encl Served on BA0810 CHILKS J. Office of the Secretary of the Commission DBB 939 84/08/10 29pp 26044 078 24% Fiche 50-275.84/08/10,8408140009
- 8408140460 Order extending time until 840817 for Commission to act to review ALAD-763 Served on 840814 CHILK, S. J. Office of the Secretary of the Commission DSB 034 84408740 Commissioners 1p 26060 352 24X Fiche 50-275
- 8408140486 Order extending time until 840817 for Commission to act to review Director's Decision DD-84-8 Served on 840814 CHILK, 5 J Office of the Secretary of the Commission DBB 035 84708710 Commissioners 1p 26060 275 24X Fiche 50-275.84708/10.8408140486
- 8408160234 Responds to RC McDiarmid petition for enforcement of license conditions to continue noribund enforcement proceeding & interpose Commission in pending contract litigation w/City of Healdsburg, CA NRC involvement unnecessary FALLIN. J F. SANDERSON: S.A. Pacific Gas & Electric Co. 84/08/10 DENTON. H.R. Office of Nuclear Reactor Regulation, Director 18pp 26092 154 24X Fiche 50-275.84/08/10.8408160234
- 8408140548 Forwards Commissioner Bernthal 840813 revised addl views to CLI-84-12 Served on 840813 CLEMENTS,W L. Docketing & Services Branch DSB 007 84/08/13 Office of the Frecutive Lagal Director 4pp 26060 243 24X Fiche 50~275,84/08/13,8408140548
- 8408220231 Order denying petitions for review of ALAB-736 subj to reservation re ASLB rationals for excluding joint intervenor & State of CA contentions concerning util GA program Served on 840820 CHILK, S. J. Office or the Secretary of the Commission DSB 190 84/08/20 3pp 26191 360 24X Fiche 50-275,84/08/20,8408220251
- B40B240424 Staff requirements memo re affirmation/discussion & vote denying 2 206 relief (SECY-84-203), approving order responding to petitions for review of ALAB-763 (SECY-84-254) & approving order denying LILCO 840719 metion (SECY-84-254) CHILK, S J Office of the Secretary of the Commission 84/08/20 Office of the Secretary of the Commission 84/08/20 Fiche 50-000,84/08/20,8408240424
- 8408230202 Forwards summary of 840726 site visit No new info impacting licensing decision identified Served on 840822 ZECH-L W Commissioners DSD 255 84/08/22 PALLADIND, ROBERTS, ASSELETINE Commissioners 5pp 26209 209 24X Fiche 50-275,84/08/22.8408230202
- 8408280217 Order extending time until 840913 for Commission to act to review ALAB-776 Served on 840827 CHILV.8 J Office of the Secretary of the Commission DBG 317 84/08/27 Commissioners 1p 26275 143 24X Fiche 50-275.84/08/27.8408280217
- 8408310247 Notice of withdrawal of appearance in proceeding Related Correspondence AXELRAD.M Newman & Holtzinger DSB 428 84/08/28 Diffice of the Secretary of the Commission 1p 26319 256 24X Fiche 50-275.84/08/28.8408310247
- 8408310210 Expresses apposition to util 840820 amend application attending term of license & requests hearing.per Atomic Energy Act, to be held prior to Commission decision on application REYNOLDS.JR Center for Law in the Public Interest REYNOLDS.JR Joint Intervenors Diablo Canyon DSB 419 84/08/29 PALLADINO.N, ASSELBTINE.J, BERNTHAL.F Commissioners 5pp 26318 047 247 Fiche 50-275.84/08/29.8408310210
- M Antitrust correspondence
- B4081BQ310 Ack receip\* of 840801 ltr to HR Denton re request for enforcement of certain antitrust license conditions Allegations contained in ltr under review VUGLER, B H Hearing Branch 2 DS8 898 84/08/08 MCDIARMID.R C Bpiegel & McDiarmid ip 20010 250 24X Fiche 50-275,84/08/08, 8408130310

- 8408280442 Confirms telegalize petition for inforcement of antitrust license conditions Staff waits RC McDiarmid comments on otil 840810 for repetition Staff requests wheel provisions of arbitrated settlement agreement to NCPA Geyser units VGGLER, B.H. Hearing Branch 2 DSB 343 84/08/22 McDIARMID, R.C. Spiegel & McDiarmid 1p 26280 294 24% Fiche 50-275,84/08/22, gaggangars. Spiegel & McDiarmid 8408280442
- Q Advisory Committee on Reactor Safeguards reports & correspondence
- 8408020242 Forwards comments on ACRS 840523 tour of plant site.in response to 840515 ltr MYSINGER.E D. Januars MYSINGER.E D Tennessee Valley Authorsty 84/08/01 MCKINLEY.J C ACRB - Advisory Conmittee on Reactor Safeguards 4pg 25898 157 24X Fiche 50-275.84/08/01.8408020242
- P Operating license stage documents & correspondence
- 8408140341 Clarifies info previously submitted in 840601 & 26 ltrs re field change request procedure to facilitate field resolution of const problems re pipe supports Procedure revised to allow work to proceed for up to 7 calendar days SCHUYLER. J D Pacific Cas & Electric Co 84708702 MARTIN, J B SCHUYLER, J O Pacific Cas & Electric Co 84. Region 5. Office of Director ip 26042 324 Fiche 50-323,84/08/02.8408140341
- @ Inspection reports, IE Bullevins & correspondence
- 8407230229 IE Info Notice 84-57. "Operating Experience to Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc. 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229
- B408080491 Forwards IE Insp Repts 50-275/84-13 & 50-323/84-05 on B40430-0504 & notice of violation BISHOP, T W Region 5. Office of Director 84/07/27 SCHUYLER, J O Pacific Gas & Electric Co 2pp 25974 244 24X Fiche 50-275,84/07/27.8408080491
- --8409080501 Notice of violation from insp on 840430-0504 YOUNG,T Region 5, Office or Director 84/07/27 3 25974 246 24% Fiche 50-275,84/07/27,8408080491
- --8408080513 IE Insp Repts 50-275/84-13 5 50-323/84-05 on 840430-0504 Violation noted feature to follow appproved GC procedures for safety-related pipe 5 electrical raceway supports BURDOIN.J F. YOUNO, T. Region 5, Office of Director 84/07/11 6pp 25974 249 24% Fiche 50-275,84/07/27,8408080491
- 8407310035 Board Notification 84-138 forwards Investigation/Insp Rept 50-275/84~08 Subj matter of rept addressed in SSFRs 25 & 26 EISENHUT.D 9 Division of Licensing 84/07/30 PALLADING, ROBERTS, ASSELBTINE Commissioners 2pp 25865 106 24% Fiche 50-279,84/07/30,8407310035
- 8408070324 Ack receipt of 840618 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-275/83-37 & 30-323/83-29
  BISHOP, T W Region 5. Office of Director 84/08/0: SCHUYLER, J O Pacific Gas & Electric Co ip 25945 130 24X
  Fiche 50-275,84/08/01,8408070324
- --8408070327 Responds to NRC 840227 ltr re violations noted in HE Insp Repts 50-275/83-37 t 50-323/83-25 Corrective actions reinsp program implemented for welds originally accepted by program implemented for welds originally accept unqualified inspectors SCHUYLER.J O Pacific Gas & Electric Co 84/ Region 5, Office of Director 8pp 25945 131 Fiche 50-275,84/08/01,8408070324 84/06/18 MARTIN. J B
- 8408010333 lE Info Notice 84-59. "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN, E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Raison Co of New York, Inc 122pp 24048 001 24X Fiche 50-000,84/08/06.8408010333
- E408010337 lE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list encl JORDAN, E L. Division of Embryency Preparedness & Engineering Respinse (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 26067 158 24X Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Info Notice 84-61, "Gverexposure of Diver in PMR Refue.ing Cavity " Svc list end! JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24x Fiche 50-000,84/08/08,8408070120

- 8408270067 Intuins or teller of 51 Like for Jan 1 'd'3 June 1984 in support of ongoing SALP review Relical confentrated on completeness accuracy % consistency of info No major deficiencies identified Summary of criteria % findings encl SEYFRITI.K V Reactor Operations Analysis Branch 84708709 BISHOP, TU Division of Pesident, Mucrot Project % Engineering Programs 3pp 26153-218 244 Fiche 50-275,84708709,8408220067
- 8408300140 Forwards Insp Repts 50~275/84-25 / 50~323/84~17 on 840709-13 No violations noted BISHOP, T & Division of Resident Reactor Project / Engineering Programs 84/04.09 SCHOYLERJO Pacific Gas / Electric Co 26307 324 24x Fiche 50~275/84/08/09,8409300140
- --B40B300149 Insp Repts 50-2/5/84-25 \* 50 323/84-17 on 840709-13 No violations or deviations noted Major areas inspected allegations to MRC assessment of Pullman Power audit program during Aug 1971 Dec 1973 MAGNER W J. WIRSCH D F. Region 5 Office of Director 84/08/08pp 26307 325 24x Fichc 50-2/5,84/08/09,8408300140
- 8408070376 IE Into Notice 84 6., "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments." Syr list encl ORACE, J. Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 consolidated Edison Co of New York, Inc 125pp 26130 001 24x Fiche 50-000.84/08/10.8408070376
- 8408100009 IE info Notice 81 63. "Defective RHR Replacement Piping "
  Svc list enc!
  JORDAN,E L Division of Emelgency Preparedness & Engineering
  Response (Post 830103) 84'08'13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24% Fiche 50-000,84/08/13,8408100009
- 8408200313 Ack receipt or 840730 ltr informing NRC of steps taken to correct violations noted in IE Insp. Rept 50-275/84-10
  BISHOP, T.W. Region 5. Office of Director 84/08/13 SCHUYLER, J.C. Pacific Gas & Electric Co. 1p. 26133 012 24X
  Fiche 50-275,84/08/13,8408200317 SCHUYLER, J D
- -9408P0031B Responds to MRC 840-28 ltm re violations noted in IE Insp. Rept 50-2/5/04-10 Corrective actions Procedure C-491.
  "Mechanical Bypass Jumpom / Lifted Circuit Log," revised to include jumpers in Clearance package
  SCHUYLER.J O Pacific Gas & Electric Co 84/07/30 MARTIN, J B Region 5. Office of Director 4pp 26133 013 24x
  Fichs 50-275.84/08/13.8408200313
- 8408100038 lE into Notice 84-64, 'BWR HPCI Initiation Seal-In & Indication " Ser list encl JURDAN,E I Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 1049p 2619d 09; 24X Fiche 50-000,84/08/15,8408100038
- 8408100021 IE Info Notice 81-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc
- 8408100095 [E Info Notice 84-6a, "Undetected Unavailability of Turbine-Driven Auxiliary feedwater Train " Svc list encl JORDAN.C ( Division of Emergency Preparedness / Engineering Response (Post 830103) 84/03/17 Consolidated Edison Co of New York, Inc. 120pp 26276 001 24X Fichs 50-000.84/08/17.8408100055
- 408140208 IE Info Notice 84-67, "Recent amount.

  High Failure Rates " Scc list entl
  JORDAN, E. L. Division of Emergency Preparedness & Engineering
  Response (Pact 830103) 84/09/17 Consolidated Edison Co. of New
  John Tor. 192np 26276 122 24 (Fiche 50-000, 84/09/17, 8408140208 8408140208 lE Info Notice 84-67, "Recent Snubber Inservice Testing W/
- 8408210142 lE Info Notice 84 68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JDRDAN,E I Division of Emergency Preparedness & Engineering Respanse (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26327 008 24x Fiche 50-000.84/08/21.8408210142
- A Periodic operating reports & related correspondence
- 8408080491 Forwards IE Insp Repts 50-279/84-13 \$ 50-323/84-08 on 840430-0504 \$ notice of violation BISHOP:T N Region 5: Offfice of Director 84/07/27 SCHUYLER:J 0 Pacific Gas \* Electric Co Ppp 25974 244 24X Fiche 50-275:84/07/27:8408080491
- --B408080515 "Technical Assistance for Insp of Diable Canyon IDVP." 408080313 "Technical Assistance for Insp or Diable Langua IDVI.)
  progress rept for Feb 1964
  WADE-W O . CUMMINGS.O E Lawrence Livermore National Laboratory
  FIN 0-8552 84/02/14 MORRILL-P J Region 5. Office of Director
  App 20974 255 24X fiche 50-275,84/07/27.8408080491

- ~-Bip8080517 Tribuital Assistic & for the profit to the Canyon IDVP "
  progress tept for Mar 17(1)
  WADE & Or COMMINGS OF Transpace treatmers National Laboratory
  FIN 0-8552 84704711 M0881LL P. J. Region 5. Office of Director
  App. 2074-261 24x (1)the 50-275.84407727.8108080491
- --8408080521 "Technical Assistance for loss of Plablo Cangon IDVP,"
  progress lept for Apr 1984
  WADELWO, COMMINGS OF Laternot Livermore National Laboratory
  FIN B-8552 01/05/14 NORKILLER J Region 5. Office of Director
  App 259/4 269 244 Fich 50 275 84/07/27,8408080491

## T. Hearing thansonipts on num-antitrust matters

- B40822033B Transcript of B10802 open meeting in Mashington. DC rediscussion/possible vote on rull power OL Pp 1-195
  Supporting documentation encl
  \* Commissioners 84/08/02 222pp 24211 083 24X
  Fiche 50-2/5 84/08/02.84082
- 8408300407 Transcript of 840809 Commission meeting in Washington, DC rediscussion/possible vote on older concerning carthquakes & energency planning Pp 1-8 Commissioners 84703703 12pp 26141 178 24X Fiche 50-275,84708/03,8408200407
- 8408280020 Transcript of H10816 Commission meeting in Washington.DC re affirmation/discussion / vote Pp 1-/ \* Commissioners 84/08/16 10pp 26294 013 24X Fiche 50-000.84/08/16.8408280020

#### U Congressional/Executive Cairespondence

- 84080102/5 Responds to 840205 ltr re concerns over perceived tendency by staff to assume that margins of safety established by criteria need not be adhered to for sys not pivotal to safety DIRCKS.W U Office or the Executive Director for Operations 84/07/20 PAREITAL House or Rep 9pp 25872 342 24X Fiche 50-275.84/07/20.8408010275
- ---8408010277 Requests preparation of response to Panetta 840208 ltr on concerns re QA hearing PALLADINON J Cormissioners 84/06/19 DIRCKS,W J Office of the Liecutive Director for Operations 1p 25872 351 24X Fiche 50-2/5,84/07/20.8408010275

#### V Operator Examinations

- 8408070045 Continus scheduling of operator written t oral exams for 840918-28 Transmittal of lef moths listed in Entl 1 by 840810 requested list of logistical requirements also entl PATE.R J Region 5. Office of Director 84/08/02 SCHUYLER.J D Pacific Gas & Electric Co. 4pp. 25950 038 24% Fiche 50-323.61/08/02.8108070045
- 8408370479 Discusses telcon between J Tinlin & J Elin re arrangements for administration or unition to oral exams for senior reactor operators on 840918-28 License applications should be submitted at least &0 days grid to exam PATE.R J Region 5. Office of Director 84/08/02 SCHUYLER, J D Pactfir Gas & Electric Co 4pp 25941 206 24X Fichr 50-275.84/08/02/02.84080704/9
- DOCKET 50-344 BRUNSHICK STRAIN LLECTRIC PLANT, UNIT 2

  F Security, medical, emergency & fire protection plans
- 8408310411 Forwards summary of 840530 meeting re proposed 10CFR50 54(p) changes to industrial security plans a contractor screening program Meeting beneficial a provided better understanding between security staffe LEMISTR C Region 2. Office of Director 84/06/19 UTLEY.E E Carolina Power 9. Light Co 3pp 26333 318 24X Fiche 50-000.84/06/19.8408310411
- B40B300315 Forwards correspondence from FEMA forwarding evaluation of offsite emergency preparedness for 830517 exercise LEMIS.R C Region 2. Office of Director 84/07/19 UTLEY.E E Caralina Power 7 tight Co 2pp 26313 213 24X Fiche 50-324.84/07/19.8408300315
- --84083003)9 Forwards "Brunswick Nuclear Power Plant Exercise on B30517," final rept Primm.R & Federal Emergency Management Agency 84/06/19 JURIORN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 8pp 26313 215 24X Fiche 50 324,84/07/19,8/0830315

- --8408300220 'Brunsuick Neclear Power Plant Exercise on 830517." final hept \* fadoral Emergency Management Agency 84/04/03 40pp 26313 223 24x Fiche 50-324 84/07/19 8408300315
- 8408)30034 Revised eleigency plan implementing procedures, including Rev 7 to REP-02 2 re unusual event. Rev 7 to PEP-02 3 re alert. Rev 7 to PEP-02 4 re site emergency 8 Rev 11 to PEP-02 5 re general emergency 4 Carolina Fewer & Light Co. 84 07/24 3Bpp. 25906 228 24X Fiche 90-324.83/07/24-8408030034
- B408030040 Rev 15 to radiological emergency response plan # Caralina Power \* Light Co 84/07/24 27pp 25907 034 24X Fishe 50-324.84/07/24 8408030040
- 8408160046 Forwards request for add1 info re procedures generation package (PGP) Review of PGP conducted per Generic Ltr 82-33 (Suppl 1 to NAREO-0737) VASSALLO.D B Operating Reactors Branch 2 84/07/27 UTLEY, & E Carolina Power 7. Light Co 9pp 26128 162 24X Fiche 50-324.84/07/27, 8498160046
- 8408230249 Forwards IE Sareguards Insp Repts 50-324/84-21 & 50-325/84-21 on 840730-0803 No violations or deviations identified VERRELLI.D M Region 2. Office of Director 84/08/20 UTLEY.E E Carolina Power & Light Co 2pp 26207 290 24X Fiche 50-324,84/08/20.8408230249
- ~-8409230255 IE Safeguards Insp Repts 50-324/84-21 t 50-325/84-21 on 840730-0803 No noncompliance noted Major areas inspected implementation of approved security plan changes Details withheld (ref 100FR2 790 \* 73 21)
  TILLMAN.A. MCGUIRE.D R Region 2. Office of Director 84/08/15 ip 26207 292 24% Fiche 50-324-84/08/20.8406830249
- 8408240316 Forwards SALF Repts 50-261/84-24,50-324/84-16,50-325/84-16 & 50-400/84-18 for Feb 1983 Apr 1984
  LEWIS.R C Region 2, Office of Director 84/08/21 UTLEY.E E
  Caralina Power % Light Co 2pp 26225 230 24X
  Fithe 50-000,81/08/21,8408240316
- ---B409240319 SALP Repts 50-261/84-24,50-324/84-16,50-325/84-16 & 50-400/84-18 for Feb 1983 Apr 1984 # Region 2. Office of Director 84/04/30 71pp 26225 232 24X Fiche 50-000.84/08/21,8408240316
- 8408280235 Vol 13 of Rev 3 to Plant Emergency Procedure PEP-03 3 l. "In-Plant Monitoring & Surveys " W/840824 ltr HOME,P & Carolina Power & Light Co 84/08/24 D'REILLY, J P Region 2. Defice of Director Spp 26262 281 24X Fiche 50-024,84/08/24,8408280235

# K - Utility Final Safety Analysis Report (FSAR) & amends

- B4072601|1 Forwards Amend 2 to updated FSAR for Brunswick,Units 1 & 2 UTLEY.E E Carolina Power / Light Co 84/07/20 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p 25826 005 24X Fische 50-324.84/07/20.84072601|1
- --8407,'60112 Amend 2 to updated FSAR for Brunsuick,Units 1 & 2 \* Carolina Power & Light Co 84/07/20 912pp 25826 006 243 Fithe 50-324,84/07/20,8407260111

# P Operating license stage documents & correspondence

- 84080/0016 Forwards Page 3/4 3-29 to Amend 97 to License DPR-62, correcting error made in Amend 95 on 840328 VASSALLO.D 8 Operating Reactors Branch 2 84/07/26 UTLEY, E E Carolina Power & Light Co. 3pp. 25956 201 24% Fiche 50-324,84/07/26,8408070016
- --B40B070018 Errata to Anend 97 to License DPR-62, correcting error made in Amend 95 on B4032B re trip function & instrument number \* NRC - No Detailed Afriliation Given 84/07/26 ip 25956 203 24% Fiche 50-324,84/07/26,8408070016
- B408150310 Forwards SER re TMI Items II F 1 1. "Containment Pressure Manitor." II F 1 5. "Containment Hater Level Monitor" & II F 1 4. "Containment Hydrogen Monitor " Design acceptable VASSALLGID B Operating Reactors Branch 2 84/07/30 UTLEY, & E Carolina Power & Light Co 12pp 26099 341 24X Fiche \$0-324.84/07/30.840B150310

- 9408070218 Notification or 940°€1 meeting w/otil in Bethesda, MD to discuse integrated schedule methodology & preliminary schedule
  - schedule GROTENHUIS.M Operating Reactors Blanch 2 84/07/31 VASSALLO.D I Operating Reactors Branch 2 2pp 25757 053 24% Fiche 50-324.84/07/31.84080/0218
- B40B0B0276 Forwards addl into re reload analysis, per B40717 telcon request concerning B40315 subsittal Addl FIRWR compressed model cases run to allow code to (alculate core pressure drop ZIMMERMAN, S.R. Carolina Power & Light Co. 84/07/31 VASSALLD, D Operating Reactors Brench 2 app. 25965 261 24X Fiche 50-324,84/07/31.8408080276
- 8408080252 Responds to 040513 request for info ie analyses used in determining if setpoint logic changes needed to reduce water clearing thrust loads associated w/second safety leliof valve actuations analyses conducted per NUREG-0661 CUTTER.A B Carolina Power & Light Co 84/08/01 VASSALLO.D B Operating Reactors Branch 2 2pp 25966 300 24X Fiche 50-324.64/08/01.8408080252
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders or CPs re availability of Suppl i to NUREG-0933, "Prioritization of Generic Safety Issues" Svc list enc! EISENNUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of Rew York, Inc. 18pp 26129 238 24X Fiche 50-000.84/08/06.8408070110
- 8498230221 Informs that original startup date of 840925 revised to 840916 NRC action on five applications to amend Litense DPR-62 required prior to startup 7IMMERMAN, 8 8 Corolina Power ! Light Co 84/08/16 VASSALLD, D B Operating Reactors Branch 2 2pp 26209 228 24X Fichs 50-324,84/08/16,8498230221
- B4082002/5 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Bvc list encl EIBENHUT.D O Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24% Fiche 50-000.84/08/20.8408200278
- Q Inspection reports: IE Bulletins & correspondence
- B407250229 IE Info Notice B4-57, "Operating Experience of Moisture Intrusion in Safety-Rolated Electrical Equipment at Commercial Power Plants" Svc list encl JURDAN.E L Division of Emergency Proparedness & Engineering Response (Post B30103) 84/07/27 Consolidated Edison Co of New York, Inc. 119pp 25865-047 24x Fiche 50-000-84/07/27. B407250229
- 8408270426 Ack receipt of 840711 ltr informing NRC of steps taken to correct violations noted in insp Repts 50~324/84-14 & 50~325/84-14 WERRELLI.D M Division of Project & Resident Programs 84/07/31 UTLEY.E E Carolina Power & Light Co ip 26257 001 24X Fiche 50~324.84/07/31.8408270426
- --8408.270431 Responds to NRC 840613 ltr re violations noted in Insp Repts 30-324/84-14 & 50-325/84-14 Corrective attions procedures will be revised to allow tolerance for dead time of GetLij detector geometry calibr not to exceed 5% DIETZ.C R Carolina Power & Light Co 34/07/11 D'REILLY, J P. Region 2. Office of Director 4pp 26257 002 24X Fiche \$0-324,84/07/31,8408270426
- --8408270435 Forwards Insp Ropts 50-324/84-14 & 80-329/84-14 on 840521-25 & notice of violation ... VERRCLLI, D M Division of Project & Resident Programs 84/06/13 UTLEY, E E Carolina Power & Light Co 2pp 26257 006, 24X Fiche 80-324,84/07/31,8408270426
- --8408270437 Notice of violation from insp on 840521-25 \* Region 2. Dffice of Director 84/06/13 ip 26257 OOB 24X Fiche 80-324,84/07/31,8408270426
- --8408270439 Insp Repts 50-324/84-14 & 50-325/84-14 on 840521-25 Violation noted failure to follow procedures for calibr of Gett: detector 498 KUZO.0 B . MDN760MERY.D M Region 2. Dffice of Director 84/06/11 10pp 26257 009 24X Fiche 50-324.84/07/31,8408270426
- 8408280166 Supply response to IE Bulletin 83-07, "Apparently Fraudulent Products Bold by Ray Miller, Inc." No subj products in use at facilities CUTTER.A G. Carolina Power & Light Co. 84/07/31 G'REILLY, J.P. Region 2, Office of Director 2pp. 26260 141 24X Fiche 50-324,84/07/31,8408280166

- 8408010333 If Info Morice 84-50, "Deliberate Circumventing of Station Health Physics Procedures 5 list encl JORDAN, C.C. biviology of Emergency Preparedness & Engineering Response (Post Baulus: 84-75 % Consolidated Edison Co. of New York, Inc. 122pp 26068 Qoi. 247 Fiche 50-000.84/08/06, 8408010333
- B40BD10337 If Info Netice 84 50. Fullure of Air Purifying Respirator Filters to Meet Extriciency Requirement "Svc list Enci JURDAN, El Division of Emergency Preparedness & Engineering Response (Post B33103) B470B/06 Consolidate Edison Co of New York, Inc. 123pp 26067 158 24% Fiche 50-000,8470B/06,840B010337
- B40B070120 IE Info Notice 84-61 "Overexposure of Diver in PWR
  Refueling (avity "Svi list end)
  JORDAN,C L Division of Emergency Preparedness & Engineering
  Response (Post 8:00107) B4708/08 Consolidated Edison Co of New
  York, Inc. 120pp 3:6129 118 24X Fiche 50-000.84/08/08, 8408070128
- 84080703/6 IE Info Notice 84 62 'Incrapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments 'Svc list encl GRACELUN Division of QA. Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York. Inc 125pp 26130 001 247 Fichs 50-000.84/08/10.8408070376
- 840B16Qt29 Forwards Rev 1 to "Analysis of Unrepaired Flow Indications at Brunswick Steam Electric Plant.Unit 2 "felds acceptable per criteria in Ocheric Ltr 84-11 Performance capability of Level 1.2 or 1 demanstrated per 16 Bulletin 83-02 CUTTER.A B Carolina Power \* Light Co 84/08/10 VASSALLO, B B Operating Reactors Branch 2 2pp 26092 103 24X Fichs 50-324.84/08/10.8408160129
- --8408160192 Rev 1 to "Analysis of Unrepaired Flow Indications at Brunswick Steam Clectric Plant.Unit 2 " KLEINSHITH.M E . SUMP.H & MUTECH Engineers, Inc. CPL-19-103 R01 84097/31 25pp 26092 105 24X Fiche 50-324.84/08/10, 8409160129
- 840B100C09 IR Info Notice 84-63 "Defective RHR Replacement Piping" Byd list end JORDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc. 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- B408100038 IF Info Nutice 84 64. "BWR HPCI Initiation Seal-In & Indication " Svc list encl JORDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 84705/15 Consultdated Edison Co of New York, Inc. 104pp 26198 099 247 Fiche 50-000.84708/15.8408100038
- 940B100021 IC Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Clectrical Equipment" Sec list oncl JORDANIE C. Division of Emergency Preparedness & Engineering Response (Post B30:103) 84/09/16 Consolidated Edison Co. of New York, Inc. 1889 26198 001 24X Fiche 50-000.84/08/16.8408100021
- B40B100033 IE Info Notice B4-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train" Svc list encl JEROAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 001 24% Fischs 50-000,84/08/17,8408100055
- 8408140208 IE Inia Natice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " 8vc list encl JURDAN: E.L. Division of Emergency Proparedness & Engineering Response (Post 8331093) 84/08/17 Consolidated Edison Co of New York, Inc. 182pp 26276 125, 24X Fiche 50-000, 84/08/17, 8408140208
- 8408230249 Fullwards IE Safeguards has Repts 50-324/64-21 & 50-325/64-21 on 640730-0803 No violations or deviations identified VERRELLI, D.M. Region 2. Office of Director 84/08/20 UTLEY, E. Carolina Power & Light Co. 2pp 26207 290 24X Fiche 50-324, 64/08/20, 6400230249
- --8408230255 IE Safeguards insp Repts 50-324/84-21 & 50-325/84-21 on 840730-0803 No noncorpliance noted Major areas inspected implementation of approved security plan changes Details withhold (ref 10CFR-790 & 73 21)
  TILLMAN.A. MCGUIRE.D R Region 2. Office of Director 84/08/15 ip 26207 292 24% Fiche 50-324,84/08/20.8408230249
- 8408210142 IE Info Notice BA-64, "Potential Deficiency in Improperly Rated Field Wiring to Solemoid Valves " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/2! Consolidated Edison Co. of New York, Inc. 119pp 24327 008 24X Fiche 50-000,84/08/21,8408210142

- --B409P40315 CALF Repts 50-261/84-24,50-324/84-16,50-325/84-16 & 50-400/81-18 fnr Feb 1984 Apr 1984 Region 2, Office or Director 84/04/30 71pp 26225 238 Fiche 50-000.84/08/21,8408240316
  - 84/04/30 71pp 26225 232 24X
- 8 Reportable occurrences LLRs % related correspondence
- 8408240348 Part 21 rept to presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid value plunger Initially reparted on 840413 New thread locking devices investigated SHERUDDD. G. G. General Electric Co. 84/04/13 DEYDUNG. R.C. Director's Office Office of Inspection and Enforcement 3pp 24222 256 24x Fich. 53-000.83 04/13.8408240348
- 8408100039 Forwards LER 83-019 017-2 DIEFZ.C R Carolina Power 5 Light Co 84/07/12 O'REILLY, J Region 2, Office or Director 1p 24X Fiche 50-324.84/07/12, O'RELLY, J P 8408100039
- 8408090390 LER 83-0/5/UIL-1 on 830813 drywell floor drain flow integrator 2-G16-KU-KeOl indicated sump flow w/no pumps running Caused by railed solder joint on output connector of integrator square root converter W/640/17 ltr PASIVA, M J. DIETZ, C R. Carolina Power & Light Co. 84/07/17 D'REILLY, J P. Region 2, Office or Director. 2pp. 25993 284 Fiche 50 321-84 07 17 8408040390
- 8408130338 Special Rept 2-SR-84 10 on 840629, fire barrier limiting 408130333 special Reft 2-SR-84 to on 840629, fire barrier limicondition for aperation initiated for Fire Door 303 Door would not properly upen due to problems whinges & interlock device Door repaired
  DIETZ.C R Carolina Fuwer % Light Co 84/08/03 D'REILLY, Region 2, Office of Director ip 26010 215 24x
  Fiche 50 324.84/08/03.8408130338 D'RETLLY, J. P.
- 8408240227 (ER 81-002-00 on 840727) reactor protection sys actuated due to electronic noise spike (auxed by section of fallen grating resulting from snagged technician respirator air line Grating replaced (I) 840820 (Itr PASIVA) M. J. DIETZ C.R. Carolina Power & Light Co. 84/08/20 2pp 26236 314 24% Fiche 50-324.84/08/20,8408240227
- G408310186 Part all rept to torus to reactor bldg vacuum breakers Hemo of B40820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to Controls to outperfy valves one; on lacks committed fine co-adequately evaluate condition. VILLA-R General Electric Co 94/08/21 ROSSI.C E Director Office. Office of Inspection and Enforcement 3pp 26318 327 Fiche 50-000,84/08/21,8408310186
- V Operator Examinations
- 8408310014 Confirms 840605 teleum re 840612 mgt meeting in Region II ofes to discuss up oming aperator exams \* requalification of licensed operators following steam generator outage O'REILLY, J.P. Region 2, Office of Director 84/06/08 UTLEY, E.E. Carolina Pauer \* Light Co. 1p. 26333 357 24X
  Fiche 30-000.84/06/08.8408310014
- DOCKET 50-325 BRUNSWICK STEAM FLECTRIC PLANT, UNIT 1 F Security, medical, emergency 5 fire protection plans
- 8408310411 Forwards summary of 840530 meeting re proposed 10CFR50 54(p) changes to industrial security plans & contractor screening program Meeting beneficial & provided better understanding between security staffs.

  LEMISTR C Region 2. Office or Director 84/06/17 UTLEY.E E Carolina Power & Light Ca 3pp 26333 318 24X

  Fiche 50-000.84/06/19.8408310411
- 8408300315 Forwards correspondence from FEMA forwarding evaluation of offsite emorgency preparedness for 830517 exercise LENIS.R C Region 2. Office of Director 84/07/19 UTLEY.E E Carolina Power & Light Co 2pp 26313 213 24X Fiche 50-324.84/07/19.8408300315
- --8409300319 Forwards "Brunswick Nuclear Power Plant Exercise on 830517." Final rept
  KRIMM,R W Federal Emergency Management Agency 84/06/19
  JORDAN,C L Division of Emergency Preparedness & Engineering
  Response (Past 830103) 8pp 26/313 215 24X
  Fithe 50-324,84/07/19,8408300315

- --8408300323 Brunswick Nuclear Power Plant Exercise on 830517," final rept # Tederal Energency Management Agency 84/06/0 26913 223 24% Fiche 50-324.84/07/19.8408300315 B4/06/03 40pp
- 8408030034 Revised emergency plan implementing procedures, including Rev 7 to REP-02 3 re alert. Rev 7 to PEP-02 4 re site emergency & Rev 11 to PEP-02 5 re general emergency & Rev 11 to PEP-02 5 re general emergency & Carolina Power & Light Co 84/07/24 38pp 25906 228 24X Fiche 50-324, 84/07/24, 8408030034
- B40B030040 Rev 15 to radiological emergency response plan \* Carolina Power & Light Co 84/07/24 27pp 25907 034 Fishe 50-324.84/07/24.840B030040
- 8408160046 Forwards request for add1 info re procedures generation package (PGP) Review of PGP conducted per Generic Ltr 82-33 (Suppl 1 to NURCG-0737)
  VASSALLG,D B Operating Reactors Branch 2 84/07/27 UTLEY,E E Carolina Power & Light Co 9pp 26128 162 24X
  Fiche 50-324.84/07/27.8408160046
- 8408230249 Forwards IE Safaguards Insp Repts 50-324/84-21 & 50-325/84-21 on 840730-0303 No violations or deviations identified Tennettria VERRELLI.O M Region 2. Office of Director 84/08/20 UTLEY,E E Carolina Power & Light Co 2pp 26207 270 24x Fiche 50-324.84/08/20.8408230249
- --B409230255 IE Safeguards Insp Repts 50-324/B4-21 & 50-325/B4-21 on 840730-0803 No noncompliance noted Major areas inspected inplementation of approved security plan changes Details withheld (ref 10CFR2 790 & 73 21)
  TILLMAN A Region 2 Office of Director 84/08/15 ip 26207 292 24X Fiche 50-324,84/08/20,8408230249
- 8408240316 Forwards SALP Repts 50-261/84-24, 50-324/84-16, 50-325/84-16 & 50-400/84-18 for Feb 1983 Apr 1984 LEWIS R C Region 2. Office of Director 84/08/21 UTLEY,E E Carolina Power & Light Co 2pp 26225 230 24X Fiche 50-000.84/08/21,8408240316
- ---8408240319 SALF Repts 50-261/84-24.50-324/84-16.50-325/84-16 & 50-400/84-18 for Feb 1983 Apr 1984 \* Region 2, Office of Director 84/04/30 71pp 26225 232 24X Fiche 50-000,84/08/21,8408240316
- 8408280235 Vol 13 of Rev 3 to Plant Emergency Procedure PEP-03 3 1, "In-Plant Monitoring & Surveys " W/840824 1tr HOME,P W Carolina Power & Light Co 84/08/24 O'REILLY,J P Region 2, Office of Director 5pp 26262 281 24X Fiche 50-324,84/08/24,8408280235
- K Utility Fina) Safety Analysis Report (FSAR) & amends
- B407260111 Forwards Amend 2 to updated FSAR for Brunswick, Units 1 & 2 UTLEY, E & Carolina Power & Light Co 84/07/20 DENTON, H R Defice of Nuclear Reactor Regulation, Director 1p 25824 005 2/ Fiche 50-324, 84/07/20, 8407260111 25024 005 24X
- --8407260112 Amend 2 to updated FSAR for Brunswick,Units 1 & 2 \* Carolina Power & Light Co 84/07/20 912pp 25826 006 24X Fiche 50-324,84/07/20,8407260111
- P Operating license stage documents & correspondence
- 8408150310 Forwards SER re IMI Items 11 F i 1, "Containment Pressure 108150310 Forwards SER re IMI Items II F i 1, "Containment P Monitor:" II F i 5, "Containment Hater Level Monitor" & II F I 6, "Containment Hydrogen Monitor " Design acceptable VASSALLO.D B Operating Reactors Branch 2 84/07/30 UTL Carolina Power & Light Co 12pp 26079 341 24X Fiche 50-324.84/07/30.8408150310 UTLEY, E E
- 8408070218 Notification of 840821 meeting w/util in Bethesda,MD to discuss integrated schedule methodology & preliminary schedule OROTENHUIS.M Operating Reactors Branch 2 B/ Operating Reactors Branch 2 2pp 25957 053 Fiche 50-324,84/07/31.8408070218 84/07/31 VA98ALLO, D B
- 84080803/6 Forwards addl info re reload analysis, per 840717 telcon request concerning 840315 submittal Addl FIBWR compressed model cases run to allou code to calculate core pressure drop ZIMMERMAN,S R Carolina Power & Light Co 8: Carabina Peactors Branch 2 8pp 25945 261 84/07/31 VASSALLO, D R Operating Reactors Branch 2 8pp Fiche 50-324.84/07/31.8408080276

- B40B070110 General Ltr 84-19 to all licensees of operating reactors, applicants for OLS A holders of CPs to availability of Suppl 1 to NURFO-0933. "Prioritization of Generic Safety Issues." Svc list encl EISCN4UT.D 9 [Fivision of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000.84/08/06.8408070110
- 8408210009 Forwards Amend 72 to License DFR-71 t safety evaluation Amend defers full-stroke cycling of four reactor instrumentation sys isolation valves OROTENHUIS, M. Operating Reactors Bianch 2 84/08/10 UTLEY.E E Carolina Power t Light Co. 2pp. 26195-184 24X Fiche 50-325.84/08/10.8408210009
- --8408210012 Amend 72 to License DPR-71 deferring full-stroke cycling of four reactor instrumentation sys isolation valves VASSALLO, D B Operating Reactors Branch 2 84/08/10 4pp 24195 186 24X Fiche 50-325,84/08/10,8408210009
- --8408210013 Safety evaluation supporting Amend 72 to License DPR-71 \* Office of Nuclear Reactor Regulation, Director 84/08/10 4p 26175 190 24X Fiche 50-325,84/08/10.0408210009
- 84082002/5 Generic Ltr 84-20 to all licensees of operating reactors & applicants for DLs re-scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENNUT.D © Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276-244 24X Fiche 50-000.84/08/20.8408200275
- @ Inspection reports, IE Bulletins % correspondence
- 8407250229 IE Into Notice 84-57. 'Operating Experience re Noisture Intrusion in Safety-Related Clettrical Equipment at Commercial Power Plants " Svc list encl JURDAN.E L Division of Emergency Preparedness \* Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc. 119pp 25865-042 24% Fiche 50-000,84/07/27,8407250229
- 8408270426 Act receipt of 8407)1 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-324/84-14 & 50-325/84-14
  VERRELLI, D M Division of Project & Resident Programs 84/07/31
  VTLEY, E E Carolina Power & Light Co ip 26257 001 24X
  Fiche 50-324-84/07/31-8408270426
- --8408270431 Responds to NRC 840613 ltr re violations noted in Insp Repts 50-324/84-14 % 50-325/84-14 Corrective actions procedures will be revised to allow tolerance for doad time of Ge(Li) detector geometry calibr not to exceed 5% DIETZ-C R Carolina Power & Light Co 84/07/11 O'RE(LLY, J P Region 2. Office of Director 4pp 26257 002 24X Fichs 50-324,84/07/31,8408270426
- --8409270437 Notice of Violation from insp on 840521-25 \* Region 2. Office of Director 84/06/13 ip 26257 008 24x Fiche 50-324,84/07/31.8408270426
- --8408270439 Insp Repts 50-324/84-14 % 90-325/84-14 on 840521-25 Violation noted failure to follow procedures for calibr of Od(L1) detector sys KUZO.0 B. MONIGOMENI, D.M. Region 2, Office of Director 84/04/11 10pp 24257 009 24X Fiche 50-324,84/07/31,8408270424
- 9408290166 Supply response to 1E Bulletin B3-07. "Apparently Fraudulent Products Sold by Ray Miller.Inc " No subj products in use at facilities CUTTER.A B Carolina Power & Light Co 84/07/31 O'REILLY.J P Region 2. Office of Director 2pp 26260 141 24X Fiche 50-324.84/07/31.8409280166
- B408010333 IE Info Notice B4-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORBANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 182pp 26068 001 24% Fiche 50-000.84/08/06, 8408010333

- B40B010737 it Into Notice B177 'Failure of Air Purifying Respirator Filters to Newt Entriciency Anglirement Sec list encl URBANGE E Billion of Emergency Preparedness' Engineering Response () of B73107) 74 15 16 Consultated Edison Co of New York Inc 123pp 24067 152 24% Fiche 50-000.04708/06.8408010337
- 8408070126 (E Info Notice 81-61, 'Overexpusure of Diver in PWR Refueling Cavity 'Svc list encl JORDAN C L Division of Energy Preparadness & Engineering Response (Post 82:103) B1/05/06 (onsolidated Edison Co of New York, Inc. 120pp (\*E124 118 24% Fiche 50-000,84/08/08,8408070120
- 8408070376 IL Into Notice Blac Therapy Misadministrations to Patients (Indergoing Co-60 Teletherapy Treatments " Svc list enc) GRACL J N Division of QA, Sareguards & Inspection Programs (Post B30103) B4708 III Consolidated Edison Co of New York, Inc 125pp 26130 001 44 F chc 50-000.84/08/10.8408070376
- 8408100009 IC Info Notice 84-62 'Defective RHR Replacement Piping 'Svc list ent)
  JORDANNE L Pivision of Emergency Preparedness 7 Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc. 119pp 26197 218 24X Fishe 50-000,84/08/13,8408100009
- 8408100038 IE info Notice 84-64. "BMR HPC1 Initiation Seal-In & Indication " Sec list encl URBOANDE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co. of New York, Inc. 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038
- B408100021 If Info Notice B4-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl
  JURDAN: E L Bi,ision of Emergency Preparedness & Engineering
  Response (Post 830103) B4/00/16 Consolidated Edison Co of New York, Inc 110pp 26178 001 24% Fiche 50-000.84/08/16,8408100021
- 8408100075 [E. Into Notice 84-66, 'Undetected Unavailability of Turbing-Driven Auxiliary Feedwater Train " Svc list encl JORDAN, E. D. Driston of Emergency Preparedness & Engineering Response (Post 630103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 001 24X Fiche 50-000.84/08/17,8408100055
- 8408140309 IC Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAM.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/09/17 Consolidated Edison Co of New York, Inc 122pp 24274 122 24X Fiche 50-000,84/08/17,8408140208
- 8408230249 Forwards IE Safegualds Insp Repts 50-324/84-21 & 50-325/84-21 un 840730-0803 No violations or deviations identified VERRELLI.D M Region 2. Office of Director 84/08/20 UTLEY.£ E Carolina Power & Light Co 2pp 26207 270 24X Fiche 30-324.084/08/20.8408230249
- --B408230255 IE Safequards Insp Repts 50 324/84-21 % 50-325/84-21 on B40730-0803 No noncompliance noted Major areas inspected implementation of approved security plan changes Betails withheld (ref 10CFR2 790 & 73 21) TILLMAN.A. MOGUIRE.D R Region 2. Office of Director B4/08/15 ip 26207 292 24X Fiche 50-324,84/08/20,8408230249
- 8408210142 IC Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Combolidated Edison Co. of New York, Inc. 115pp 26329 008 24X Fiche 50-000.84/08/21,8408210142
- 8408240316 Forwards SALP Repts 50-261/84-24.50-324/84-16.50-325/84-16 & 50-400/84-18 for Feb 1983 - Apr 1984 LEWIS-R C Region 2: Office of Director 84/08/21 UTLEY.E E Carolina Power & Light Co 2pp 26225 230 24X Fiche 50-000.84/08/21.8498240316
- --8408240319 SALP Repts 50-261/84-24,30-324/84-16,50-325/84-16 & 50-400/84-18 for Feb 1983 Apr 1984 \* Region 2. Office of Director 84/04/30 71pp 26225 232 24X Fithe 50-000.84/08/21,8408240316
- S Reportable occurrences, LERs & related correspondence
- 8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solemnid valve plunger Initially reported on 840413 New thread locking devices investigated SHERWOOD, G G General Electric Co 84/04/13 DEYOUNG, R C Director's Office, Office of inspection and Enforcement 3pp 26222 256 24X Fiche 50-000,84/04/13,8408240348

- 84060766.60 NPHES numeropliance notification on 840517-21.one cooling water pump buy uses u o scribins Caused by temoval or bar trash rack for Lifaning Spare lack installed 1 scriens returned to Eve STARKLY R B Carolina Pawer / Light Co 84/06/04 WAKILD.C North Carolina, State of Ip 21 43 1000 F4x Fiche 50-325,84/06/04,84060/0066
- 8408390432 LER 83-023/03L-1 on 830426.loss of offsite power occurred when 230-VV bus 18 insdvertently tripped Caused by personnel error Trip signal cleared \* offsite power restored Transformer E-6 replaced U/840718 ltr
  PASTVA.M J. DIETZ C R Carolina Power t Light Co 84/07/18 O'REILLY, J P Region 2. Utrice of Priector 5pp 25993 239 24% Fiche 50 325.84/07/18.8408090432
- B40B060088 NPDES noncompliance notification on 840619 to 20.flow minimization suspended Flow of 1010 cubic ft per second recorded both days Weather change allowed return to min 200 MW sys reserve STARKEY.R B Carolina Power & Light Co. 84/07/26 WAKILD.C North Carolina State of 1p 25935-308 24X Fiche 50-325.84/07/26, 8408060088
- B438010295 NPDES noncompliance notification on 840704-11, unit operated w/less than two fine mesh screens on coaling water pump ID bay Caused by scheduled naint? miscommunication Action taken to prevent recurrence BTARKEY.R B Carolina Power & Light Ca 84/07/27 WAKILD.C North Carolina, State of 1p 25866 170 24X Fiche 50-325,84/07/27,
- B40B070()32 LFR 84-007-00 on B40b0).08 & 13.during power operation,min flow valves of core spray sys pumps closed & declared inoperable Caused by design defert flods will be implemented PABIVA.M J. DIETI.C R. Consumers Power C. 84/07/27 5pp 25992 097 24X Fiche 50-325.84/07/27.8408090032
- 84081600/5 LER 83-021/03L-1 on 831116 while withdrawing control rods during reactor startup.full-in light lit while rod 50-35 withdrawn Addl position indication problems noted Caused by defective PIP connectors & reed switches W/840727 ltr PASIVA.M J. DIETZ.C R. Cololina Power & Light Co. 84/07/28 O'REILLY.J P. Region 2. Office of Director 2pp 26108 232 24X Fiche 50-325.84/07/28.8408160075
- 8408060128 LER 84-011-00 on 840711, control bidg emergency air filtration sys Train A automatically star ad due to spurious fire alarm in back panel area No failures or personnel involvement identified H/840731 ltt PASTVA.M J , DIETZ.C R Carolina Power % Light Co 84/07/31 2pp 25932 191 24X Fiche 50-325.84/07/31.8408060128
- 8408160133 LER Bi-046-01T on 810414, snubber shaft of hydraulic snubber I-E11-4755326 broke Caused by water hummer of RHR syscundensing piping due to steam pocket Snubber repaired, twisted is returned to svc W/840803 ltr PASTVA, M.J. DIETZ, C.R. Carelina Pawer & Light Co. 84/08/03 D'REILLY, J.P. Region 2, Office of Director. 3pp. 26108 112 24X Fiche 50-325,84/08/03,8408160133
- 8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition

  VILLA.R General Electric Co 84/08/21 ROSSI.C E Director's

  Office Office of Inspection and Enforcement 3pp 26318 327 24%

  Fiche 50-000.84/08/21.8408310188
- 8408300312 NPDES noncompliance rept on 840801-02, unit operated w/less than two fine mesh screens Caused by clogging of circulating water pump by marine grouth & back pressure-induced trip due to impinged jellyfish Bar rack replaced & screens cleaned STARKEY, R B Carolina Power & Light Co 84/08/22 WAKILD, C North Carolina, State of ip 26314 331 24X Fiche 50-325, 84/08/22.

## V Operator Examinations

8408310014 Confirms 840605 telcon re 840612 mgt meeting in Region II ofcs to discuss upcoming operator exams & requalification of licensed operators following steam generator outage O'REILLY, J.P. Region 2, Office of Director 84/06/08 UTLEY, E.E. Carolina Pawer & Light Co. ip. 26333-357 24X Fiche 50-000,84/06/08.8408310014

- DOCKET 50-326 UNIV OF CALIFORNIA AT INVINE RES. REACTOR
  F. Security, medical emergency & fire protection plans
- 8408270071 Ack receipt of 840627 ltr te proposed research reactor emergency plan Sirty-day extension of deadline for response to questions raised by NRC tequested MILLER. G E California, Univ of Invine, CA 84/08/20 THOMAS, C O Standardization / Special Projects Branch (p 26247 357 24x Fiche 50-326,84/08/20,8408270091
- DOCKET 50-327 SEGUDYAH NUCLEAR PLANT, UNIT 1

  F Security, medical, emergency \* fire protection plans
- 8408300316 Ack receipt of 840503 ltr re emergency exercise scheduled for Jul 1984 Review of info submitted to scape & objectives of planned exercise indicates no questions Scenario & controller messages will be reviewed & evaluated VERRELLI.D M Region 2, Office of Director 84/05/31 PARRIS.H G Tennessee Valley Authority 1p 26308 327 24% Fiche 50-327.84/03/31.8408300314
- 8408300402 Forwards summary of 840530 meeting w/TVA.Alabama Power Co. Florida Power Corp.Florida Power & Light & Georgia Power Core selected emergency preparedness issues
  O'REILLY,J P Region 2. Office of Director 84/06/08 PARRIS.H & Tennessee Valley Authority 4pp 26308 116 24X
  Fiche 90-000.84/06/08.8408300402
- 8408300193 Forwards 840612 ltr detailing overall planning for 840620 French security team visit to facility Biographical info for each team member included LEWIS.R C Region 2. Office of Director 84/06/15 TUCKER.H B Duke Power Co 1p 26300 139 24X Fiche 50-000.84/06/15. 8408300193
- --8408300204 Requests authorisation for six French security experts hosted by NRC to visit McGuire facility on 840620 & Sequoyah facility on 840620 & Sequoyah LAFLEUR. J D Office of International Programs, Director 84/06/12 TUCKER. H B Duke Power Co PARRIS. H G Tennessee Valley Authority Spp 26300 140 24X Fiche 50-000,84/06/15,8408300193
- 8408300499 Ack receipt of 840620 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-327/83-13 & 50-328/83-13 VERRELLI.D M Division of Project & Resident Programs 84/07/13 PARRIB.H G Tennessee Valley Authority ip 26314 095 24% Fiche 50-327,84/07/13.8408300459
- --8408300469 Responds to NRC 830913 ltr re violations noted in Insp Repts 50-327/83-13 & 50-328/83-13 Installation of new communications sys delayed until 840901 due to revised mat! delivery date KAMMER, D.S. Tennessee Valley Authority 84/06/20 O'REILLY, J.P. Region 2. Office of Director 1p 26314 096 24X Fiche 50-327.84/07/13.8408300459
- --BA08300477 Responds to MRC 830913 ltr re-violations noted in Insp Repts 50-327/83-13 & 50-328/83-13 Corrective actions revised emergency monitoring implementing procedures will be completed by 840401 MILLS.L.M. Tennessee Valley Authority 84/05/01 O'REILLY, J P Region 2, Office of Director 1p 26314 097 24X Fiche 50-327,84/07/13,8408300459
- 8408300363 Forwards summary of 8407i1 meeting w/util in Region II ofc re proposed compensatory measures associated w/security power block concept Attendance list also encl LEWIS,R C Region 2. Office of Director 84/07/17 PARRIS.H 9 Tennessee Valley Authority 4pp 26308 194 24X Fiche 50-327,84/07/17.8408300363
- 8408060254 Revs to radiological emergency plan implementing procedures, including Rev 2 to SGN IP-7, "Activation of Operations Support Ctr" & "Rev 3 to SGN IP-15, "Emergency Exposure Quidelines " W/840730 ltr MILLS.L M Tennessee Valley Authority 84/07/30 O'REILLY, J P Region 2. Office of Director 30pp 25934 078 24X Fiche 50-327.84/07/30.8408060254
- 8408300519 Confirms 940726 telcon re 840803 mgt meeting to discuss development & implementation of 10CFR50.App R program at Watts Bar & status of Sequoyah program of PREILLY.J P Region 2. Office of Director 84/07/30 PARRIS.H 0 Tennesses Valley Authority 2pp 26313 300 24X Fiche 50-000.84/07/30.8408300519

- 8408100024 Rev 12 to radiological emergency plan W/840806 ltr MILLS.L M Tennessee Valley Authority 84/08/06 O'REILLY.J P Region 2. Office of Director 41pp 25990 117 24X Fiche 50-327.84/08/06.8408100024
- P Operating license stage documents & correspondence
- B408030019 Forwards responses to J Singh 840522 verbal questions re control of heavy loads MILLS,L M Tennessee Valley Authority 84/07/27 ADENSAM.E Licensing Branch 4 2pp 25907 092 24% Fiche 50-327, B4/07/27, B408030019
- --0408030025 Rev 3 to Procedure MI-6 22, "Control of Heavy Loads in Critical Lifting Zones - NUREQ-O&12 " DOTY, V W . WHEELER, L J Tennessee Valley Authority 84/05/21 23pp 25907 094 24% Fiche 50-327,84/07/27,8408030019
- 8408030026 Forwards request & justification for relief from hydrostatic test requirements in ASME Code, Section XI. Summer 1978 addenda Expeditious review requested to support Cycle 2 refueling outage scheduled for 840908 MILLS, L. M. Tennessee Valley Authority 84/07/30 ADENSAM, E Licensing Branch 4 2pp 25907 082 24X Fiche 50-327, 84/07/30, 8408030026
- 8408160425 Summary of 840720 meeting w/utils & Westinghouse re containment analysis & superheat effects on environ qualification WIGGINTON.D L Operating Reactors Branch 1 84/07/30 Operatin Reactors Branch 1 4pp 26143 265 24X Fiche 50-000.84/07/30. 8408160425
- B40B070133 Forwards response to B40720 request re postulated event concerning main steam line break inside & outside containment Based on modeling experimental data.containment temps would not approach FSAR values
  MILLS.L M Tennessee Valley Authority B4/08/02 ADENSAM.E
  Licensing Branch 4 4pp 25949 354 24% Fiche 50-327, 84/08/02.
  B408070133
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl I to NUREG-0933. "Prioritization of Generic Safety Issues " Svc list encl EISENHUT, D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000.84/08/06.8408070110
- 840B140532 Forwards Rev 10 to offsite dose calculation manual MILLS.L M Tennessee Valley Authority 84/08/06 ADENSAMSE Licensing Branch 4 ip 26064 123 24X Fiche 50-027, 84/08/06.8408140532
- --8408140535 Rev 10 to offsite dose calculation manual \* Tennessee Valley Authority 84/08/06 12pp 26064 124 24x Fiche 50-327,84/08/06,8408140532
- '408230097 Forwards draft Industry Degraded Core Rulemaking Program Technical Rept 23 i, "Sequoyah Nuclear Plant Containment Analysis," for Mesting 38 Rept inconsistent w/four encl repts previously sent FONTANA, M H Tachnology for Energy Corp 84/08/07 DENTON, H R , CASE, E Office of Nuclear Reactor Regulation, Director, HOUSTON, R NRC No Detailed Affiliation Given 2pp 26234 001 24X Fiche 30-000,84/08/07,8408230097
- -8408230105 Draft "Sequoyah Nuclear Plant Integrated Containment Analysis" technical rept \* Industry Degraded Core Rulemaking Program 84/07/31 152pP 26234 003 24% Fiche 50-000.84/08/07.8408230097
- 8408230108 Draft "Resuspension of Deposited Aerosols Following Primary Bys or Containment Failure," technical rept \* Industry Degraded Core Rulemaking Program 84/07/3i 75pp 26234 154 24% Fichs 50-000.84/08/07.8408230097
- 8408230116 Draft "Zion Nuclear Generating Station Integrated Containment Analysis," technical rept # Industry Degraded Core Rulemaking Program 84/08/07 [19pp 26234 335 24X Ficha 50-000.84/08/07,8408230097

- ---8408230119 Draft "Grand Gulf Nuclear Station Integrated Containment Analysis." technical rept \* Industry Degraded Core Rulemaking Program 84/08/07 175pp 26235 094 24X Fiche 50-000.84/08/07.8408230097
- --B408230131 Braft, "Peach Bottom Atomic Power Station Integrated Containment Analysis," technical rept a Industry Degraded Core Rulemaking Program 84/08/07 75pp 26235 269 24% Fiche 50-000.84/08/07.8408230097
- 840B200275 Generic Ltr 84-20 to all licensees of operating reactors to applicants for OLs re-scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svr list encl EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 30-000,84/08/20.8408200275
- 8408270156 Application to amend Licenses DPR-77 & DPR-79, changing Tech Specs to allow use of fifth vital battery when one of trained vital batteries out of svc Fee paid SHELL.R H Tennessee Valley Authority 84/08/20 ADENSAN, E Licensing Dranch 4 tp 26245 227 24X Fiche 50-327, 84/08/20, 8408270136
- --B408270162 Proposed Tech Specs allowing use of fifth vital battery when trained vital batteries out of svc \* Tennesse Valley Authority 84/08/20 30pp 26245 228 24% Fiche 50-327,84/08/20,8408270156
- Q Inspection reports, IE Bulletins & correspondence
- 8408300459 Ack receipt of 840620 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-327/83-13 b 50-328/83-13 VERRELLI,D M Division of Project & Resident Programs 84/07/13 PARRIS,H O Tennessee Valley Authority ip 26314 095 24X Fiche 50-327,84/07/13,8408300459
- --8408300469 Responds to NRC 830913 ltr re violations noted in Insp Repts 50-327/83-13 & 50-328/83-13 Installation of new communications sys delayed until 840901 due to revised matl delivery date KAMMER.D S Tennessee Valley Authority 84/06/20 O'REILLY.J P Region 2. Office of Director ip 26314 096 24X Fiche 50-327,84/07/13.8408300459
- --B408300477 Responds to NRC B30913 ltr re violations noted in Insp Repts 50-327/83-13 & 50-328/83-13 Corrective actions revised emergency monitoring implementing procedures will be completed by 840801 MILLS.L M Tennessee Valley Authority 84/05/01 D'REJLLY, J P Region 2. Office of Director 1p 26314 097 24X Fichs 50-327,84/07/13.8408300439
- B407250229 IE Info Notice B4-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORBAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/07/27 Consolidated Edison Co of New York, Inc 119pp 28865 047 24X Fiche 50-000,84/07/27,8407250229
- 8408270365 Ack receipt of 840716 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-327/84-11 & 50-328/84-11 LEMIS.R C Region 2. Office of Director 84/07/27 PARRIS.H G Tennessee Valley Authority ip 26256 248 24X Fiche 50-327.84/07/27.8408270365
- ---8408270370 Responds to NRC 840614 ltr re violations noted in Imap Repts 50-327/84-11 & 50-328/84-11 Corrective actions personnel reinstructed on importance of checking limiting condition for operations prior to mode change HILLS.L.M Tennesses Valley Authority 84/07/16 G'REILLY.JP Region 2. Office of Director 7pp 26256 249 24X Fiche 50-327,84/07/27.8408270365
- --8408270375 Forwards Insp Repts 50-327/84-11 & 50-328/84-11 on 840406-0505 & notice of violation LEMIB.R C Region 2. Office of Director 84/06/14 PARRIS.H 0 Tennessee Valley Authority 2pp 26256 236 24X Fichs 50-327,84/07/27.8408270365
- ---8408270378 Notice of Violation from insp on 840406-0505 \* Region 2, Office of Director 84/06/14 3pp 26256 258 24X Fiche 50-327,84/07/27,8408270365

- --B40B2703B2 Insp Repts 50-327/84-11 & 50-32B/84-11 on 640406-0505
  Noncompliance noted changing modes w/Tech Spec
  instrumentation out of communission failure to control mods,
  failure to retrieve QA records & inadequate testing of mods
  FORD, E J : BUTLER B D : JULIAN C A Region 2: Office of Director
  84/06/13 10pp 26256 261 24X Fiche 50-327:84/07/27.8408270365
- 84080:0333 IE Info Notice 84-57, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 26067 158 24X Fiche 30-000.84/08/06,8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PHR Refueling Cavity " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 30-000,84/08/08,8408070120
- 8408070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl GRACE.J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000.
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JURDON, E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408100038 IE Info Notice 84-64, "BWR MPCI Initiation Seal-In & Indication " Syc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26178 093 24X Fiche 50-000.84/08/15,8408100038
- 8408100021 IE Info Notice 84-45, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021
- 8408100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000.84/08/17.8408100055
- 8408140208 IE Info Notice 84-67. "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Rasponse (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000.84/08/17.8408140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JURDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 24329 008 24X Fiche 50-000,84/08/21,8408210142
- 8 Reportable occurrences, LERs & related correspondence
- B408220317 Part 21 rept re failure of ITE-27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diode must be added Affected units listed DUVALL.D D Brown Boveri Corp (subs of Brown Boveri & Co., Ltd.) B4/03/13. DEVQUNG,R C D Director's Office, Office of Inspection and Enforcement 3pp 26191 357 24X Fiche 50-000,84/03/13,8408220317
- 8408060241 LER 84-042-00 on 840527, radiation monitor O-RE-90-225 would not provide automatic isolation of direct releases from neutralization tank Batch releases made on 840624 & 25 w/o compliance w/limiting conditions W/840725 ltr
  MIRKAO B: WALLACE, P R Tennessee Valley Authority 84/07/26 3pp 25935 138 24X Fiche 50-327,84/07/26.8408060241.
- 8408160453 Special Rept 84-03 fire detector rendered inoperable when water for drill cooling dripped onto detector Hourly roving fire watch established MALLACE, P.R. Tennessee Valley Authority 84/08/02 Record Services Brench (Document Control Desk) 2pp 26107 276 24X Fithe 50-327.84/08/02.8408160453

- 840B090156 LER 84-044-00 on 840705 during SI-7 test on diesel generator IA-A-remaining three diesel generators automatically started Caused by personnel error Training revised to emphasize procedures W/840803 ltr CDOPER M R . WALLACE, P R Tennessee Valley Authority 84/08/03 3pp 25994 327 24X Fiche 50-327.84/08/03.8408090156
- 8408160493 LER 84-045-00 on 840709, w/auxiliary control air compressor A-A out of svc.compressor R-B removed from svc to investigate knocking noise Noise caused by disconnected piston rod due to broken lock-tab washer W/840807 ltr COOPER.M R. WALLACE.P R Tennessee Valley Authority 84/08/07 3pp 26107 315 24X Fiche 50-327.84/08/07.8408160493
- 840Bi60522 LER 84-046-00 on 840727, various safety-related sys interactions found not in compliance w/10CFR50, App R Cause not stated Fire watches established until compliance achieved W/840Bi0 ltr COOPER, M R . WALLACE, P R Tennessee Valley Authority 84/08/10 3pp 26108 018 24X Fiche 50-327,84/08/10,8408160522
- 8408240313 Part 21 rept re fitting leaks at incore probe seal tables at PWRs.per IE Info Notice 84-55 Sub; fittings not used as instructed WILSON.B Crawford Fitting Co 84/08/13 UGRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 26225 313 24X Fiche 50-327.84/08/13,8408240313
- 8408230809 LER 84-047-00 on 840717, high radiation signal actuated, causing ventilation isolation in auxiliary & containment bldgs Caused by radiation monitor wire slipping onto power supply, tripping breaker All equipment reset W/840815 ltr DUG01N.9 . WALLACE.P.R Tennasse Valley Authority 84/08/15, 3pp 26212-276 24X Fiche 50-327,84/08/15,8408230509
- 8408280267 PND-II-84-056 Nuclear Safety Review Staff rept assessing TVA actions re 840417 in-core probe seal table break received Inspectors will investigate event further on 840827 Util & NRC responding to media inquiries PREDERICKSON.P, HEISE.B Region 2. Optice of Director 84/08/24 ip 26261 341 24% Fichs 50-327.84/08/24.8408280267
- 8409310050 LER 84-048-00 on 940725 during review of instrumentation drawings, only one RCB pressure channel found existent in field where two are required Previous design change dictated moving channel Second channel installed W/840824 ltr DUGOIN G E. WALLACE, P R Tennessee Valley Authority 84/08/24 3pp 26335 001 24% Fiche 50-327,84/08/24,8408310050

#### DDCKET 50-328 SEGUOYAH NUCLEAR PLANT, UNIT 2

- F Security, medical, emergency & fire protection plans
- B40B300316 Ack receipt of B40503 ltr re emergency exercise scheduled for Jul 1984 Review of info submitted re scope & objectives of planned exercise indicates no questions Scenario & controller messages will be reviewed & evaluated VERRELLI.D M Region 2, Office of Director B4/05/31 PARRIS.H O Tennesses Valley Authority ip 2630B 327 24X Fiche 50-327,84/05/31.8408300316
- 8408300402 Forwards summary of 840530 meeting w/TVA.Alabama Power Co. Florida Power Corp.Florida Power & Light & Georgia Fower Co. Te selected emergency preparedness issues. O'REILLY.JP Region 2. Diffice of Director 84/06/08 PARRIS.H O Tennessee Valley Authority 4pp 26308 116 24X Fiche 50-000.84/06/08.8408300402
- 8408300193 Forwards 840612 itr detailing overall planning for 840620 French security team visit to facility Biographical info for each team member included LEMIS.R C Region 2. Office of Director. 84/06/15 TUCKER.H B Duke Power Co. 1p 26300 139 24X Fiche 50-000.84/06/15. 8408300193
- --B40B30C2O4 Requests authorization for six French security experts hosted by NRC to visit McQuire facility on B4062O & Bequovah facility on B4062O & Office of International Programs Director B4/O6/12 TUCKER: M. B. Duke Power Co. PARRIS: H. O. Tennessee Valley Authority Sep. 2630O 140 24X Fiche. 50-000, 84/O6/15, B40B30O193
- 8408300459 Ack receipt of 840620 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-327/83-13 & 50-328/83-13

  VERRELLI.D M. Division of Project & Resident Programs 84/07/13

  PARRIS.H O Tennessee Valley Authority 1p 26314 095 24X

  Fiche 50-327.84/07/13.8408300459

- --B408300469 Responds to NRC 830913 itr re-violations noted in Insp Repts 50-327/83-13 & 50-328/83-13 installation of new communications sys delayed until B40901 due to revised math delivery date KAMMER.D S Tonnessee Valley Authority B4/06/20 O'REILLY,J P Region 2. Office of Director 1p 26314 096 24x Fiche 50-327,84/07/13.8408300459
- ---8409300477 Responds to NRC 830913 ltr re violations noted in Insp. Repts 50-327/83-13 & 50-328/83-13 Corrective actions revised amergancy monitoring implementing procedures will be completed by 840601 MILLS, L. M. Tennessee Valley Authority 84/05/01 D'REILLY, J. P. Region 2: Defice of Director ip 26314 097 24X Fiche 50-327, 84/07/13,8408300459
- 840B300363 Forwards summary of 840711 meeting w/util in Region II ofc re proposed compensatory measures associated w/security power block concept Attendance list also encl LEWIS.R C Region 2. Office of Director 84/07/17 PARRIS.H G Tennessee Valley Authority 4pp 2630B 194 24X Fiche 50-327.84/07/17.8408300363
- 8408040254 Revs to radiological emergency plan implementing procedures, including Rev 2 to SGN IP-7, "Activation of Operations Support Ctr" & "Rev 3 to SGN IP-15, "Emergency Exposure Guidelines" W/840730 ltr
  MILLSI, LM Tempessee Valley Authority 84/07/30 D'REILLY, J P Region 2, Office of Director 30pp 25934 078 24X Fiche 30-327,84/07/30,8408060254
- 8408300519 Confirms 840726 telcon re 840803 mgt meeting to discuss development & implementation of 10CFR50.App R program at Watts Bar & status of Sequoyah program O'REILLY, J P Region 2, Office of Director 84/07/30 PARRIS.H G Tennessee Valley Authority 2pp 26313 300 24% Fiche 50-000,84/07/30.8408300519
- 8408100024 Rev 12 to radiological emergency plan W/840806 ltr MILLS.L M Tennessee Valley Authority 84/08/06 D'REILLY.J P Region 2. Office of Director 41pp 25990 117 24X Fiche 50-327.84/08/06.8408100024
- P Operating license stage documents & correspondence
- 8408030019 Forwards responses to J Singh 840522 Verbal questions recontrol of heavy loads MILLS, L M Tennessee Valley Authority 84/07/27 ADENSAM. E Licensing Branch 4 2pg 25907 092 24X Fiche 50-327.84/07/27.8408030019
- ---8408030025 Rev 3 to Procedure MI-6 22. "Control of Heavy Loads in Critical Lifting Zones - NUREG-0412" DOTY.J W. HHEELER.L J Tennesses Valley Authority 84/05/21 23pp 25907 074 24X Fiche 30-327.84/07/27.8408030019
- 8408030024 Forwards request & justification for relief from hydrostatic test requirements in ASHC Code, Section XI, Summer 1978 addenda Expeditious review requested to support Cycle 2 refueling outage scheduled for 840708

  MILLS, L.K. Tennessee Valley Authority 84/07/30 ADENSAM, E. Licensing Branch 4 2pp 25907 082 24X Fiche 50-327, 84/07/30, 840803026
- 8408160425 Summary of 840720 meeting w/utils & Westinghouse recontainment analysis & superheat effects on environ qualification
  WI00INTON,D L. Operating Reactors Branch | 84/07/30 Operatin
  Reactors Dranch | 4pp 26143 265 24X Fiche 50-000,84/07/30,
  8408160425
- 108060220 Forwards final summary Rept HCAP-10509, "Analysis of Capsule T From TVA Bequoyah, Unit 2 Reactor Vessel Radiation Burveillance Program " Change in capsule withdrawal schedule in Tech Spec Table 4 4-5 not required MILLBLC M Tennessee Valley Authority 84/07/31 ADENSAM.E Licensing Branch 4 2pp 25929 109 24X Fiche 50-328,84/07/31,8408060220
- 94080&0231 "Analysis of Capsule T From TVA Sequoyah,Unit 2 Reactor Vessel Radiation Surveillance Program " BOGOSIR S , VANICHKO, S E , CHENEY, C A Westinghouse Electric Corp WCAP-10509 B4/04/30 B5pp. 25729:111 24X Fiche 50-328,84/07/31,84080&0220
- IBO70133 Forwards response to B40720 request ra postulated event oncerning main steam line break inside & outside ontainment Based on modeling experimental data.containment temps would not approach FBAR values
  MILLS,L M. Tennessee Valley Authority B4/08/02 ADENBAN.E.
  Licensing Branch 4. 4pp 25949 354 24X Fiche 50-327.84/08/02.8408070133

- B40B070110 Generic Ltr B4-19 to all licensees of operating reactors, applicants for CLs & holders of CPs re availability of Suppl 1 to MUREQ-0933, "Prioritization of Generic Safety Issues" "Svc list encl CISENHUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000.84/08/06.8408070110
- B40B140532 Forwards Rev 10 to offsite dose calculation manual MILLS.L M Tennessee Valley Authority B4/0B/06 ADENSAM.E Licensing Branch 4 1p 26064 123 24X Fiche 50-327.B4/0B/06.840B140532
- --8408140535 Rev 10 to offsite dose calculation manual \* Tennessee Valley Authority 84/08/06 12pp 26064 124 24x Fiche 50-327,84/08/06,8408140532
- 8408230097 Forwards draft Industry Degraded Core Rulemaking Program Technical Rept 23 i. "Sequoyah Nuclear Plant Containment Analysis." For Meeting 38 Rept inconsistent w/four encl repts previously sent FONTANA.M H Technology for Energy Corp 84/08/07 DENTON.H R. CABE. E. Office of Nuclear Reactor Regulation. Director HOUSTON.R NRC No Detailed Affiliation Given 2pp 26234 001 24X Fiche 50-000.84/08/07.8408230097
- --8408230105 Draft "Sequoyah Nuclear Plant Integrated Containment Analysis." technical rept \* Infustry Degraded Core Rulemaking Program 84/07/31 132pP 84834 003 24% Fiche 50-000,84/08/07.8408230097
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors is applicants for OLs re-scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT. D 0 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276-244 24X Fiche 50-000.84/08/20.8408200275
- B40B270154 Application to amend Licenses DPR-77 & DPR-79 changing Tech Specs to allow use of fifth vital battery when one of trained vital batteries out of svc Fee paid SHELL,R H Tennessee Valley Authority 84/08/20 ADENSAM.E Licensing Branch 4 ip 26245 227 24X Fiche 50-327,84/08/20, 8408270156
- --8408270162 Proposed Tech Specs allowing use of fifth vital battery whiterines vital batteries out of svc

  \* Tennessee Valley Authority 84/08/20 30pp 26245 228 24x
  Fishe 50-327.84/08/20.8408270156
- 8408280086 Forwards peaking factor limit rept for Cycle 3 operations MILLE.L M Tennessee Valley Authority 84/08/23 BERLINGER.C N Division of Licensing 6pp 26261 191 24X Fiche 50-328, 84/08/23. 8408280086
- 8408300385 Forwards Amené 27 to License DPR-79 & safety evaluation Amend authorizes one-time 36 h extension of time for ECCS operability w/one centrifugal charping pump inoperable ADENBAM.E 0 Licensing Branch 4 84/08/23 PARRIE,H 0 Tennesset Valley Authority 2pp 26315-324 24X Fiche 50-328.84/08/23, 8408300385
- --8408300387 Amend 27 to License DPR-79 Amend authorizes one-time 36 between sion of for ECCS operability w/one centrifugal charging pump inoperable ADENSAME & Licensing Branch 4 84/08/23 5pp 26315 326 244 Fiche 50-328.84/08/23,8408300385
- --8408300389 Safety evaluation supporting Amend 27 to License DPR-79 \* Office of Nuclear Reactor Regulation, Director 84/08/23 5M 26315 331 24X Fiche 50-328,84/08/23,8408300385
- Q Inspection reports. IE Bulletins & correspondence
- B40B300439 Ack receipt of B40620 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-327/B3-13 & 50-328/B3-13 VERRELLI,D M Division of Project & Resident Programs B4/07/13 PARREB,H G Tennessee Valley Authority 1p 26314 095 24% Fiche 50-327, B4/07/13, B40B300439
- --8408300447 Responds to NRC 830913 ltr re violations noted in Insp. Repts 50-327/83-13 & 50-328/83-13 Installation of new communications sys delayed until 840901 due to revised mat1 delivery date.

  KAMMER: D 8 Tennessee Valley Authority 84/06/20 0'REILLY: J P Region 2: Office of Director 1p 26314 096 24X Fiche: 50-327.84/07/13.8408300459

- --8408300477 Responds to NRC 830913 ltr re violations noted in Insp Repts 50-327/83-13 & 50-328/83-13 Corrective actions revised emergency monitoring implementing procedures will be completed by 840601 MILLS.L M Tennessee Valley Authority 84/05/01 G'REILLY, J P Region 2, Office of Director 1p 26314 097 24X Fiche 50-327,84/07/13,8408300459
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consulidated Edison Co of New York, Inc 119pp 25845 047 24% Fiche 50-000,84/07/27,8407250229
- 8408270365 Ack receipt of 840716 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-327/84-11 & 50-328/84-11 LEWIS.R C Region 2. Office of Director 84/07/27 PARRIS.H G Tennessee Valley Authority 1p 26256 248 24X Fiche 50-327,84/07/27,8408270365
- --8408270370 Responds to NRC 840614 ltr re violations noted in Insp Repts 50-327/84-11 & 50-328/84-11 Corrective actions personnel reinstructed on importance of checking limiting condition for operations prior to mode change MILLS.L M Tennessee Valley Authority 84/07/16 O'REILLY, J P Region 2. Office of Director 7pp 26256 249 24X Fiche 50-327,84/07/27,8408270365
- --8408270375 Forwards Insp Repts 50-327/84-11 & 50-328/84-11 on 840404-0505 & notice of violation LEMIS:R C Region 2, Office of Director 84/06/14 PARRIS:H O Tennessee Valley Authority 2pp 26256 256 24x Fiche 50-327.84/07/27,8408270365
- --8408270378 Notice of viplation from insp on 840406-0505 \* Region 2, Office of Director 84/06/14 3pp 26256 258 24X fiche 50-327,84/07/27,8408270365
- --B4082703B2 Insp Repts 50-327/B4-i1 & 50-328/B4-i1 on 840406-0505 Noncompliance noted changing modes w/Tech Spec instrumentation out of commmission, failure to control mods, failure to retrieve QA records & inadequate testing of mods FORD,E J , BUTLER.S D , JULIAN.C A Region 2, Office of Director 84/06/i3 10pp 26256 261 24% Fiche 50-327.84/07/27.8408270365
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDANIC L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York: Inc 122pp 26068 001 24X Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN: E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list enci GRACE.J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 129pp 26130 001 24x Fiche 50-000.84/08/10,8408070376
- 840B100007 IE Info Notice 84-43, "Defective RHR Replacement Piping "
  Syc list encl
  JORDAN, E. L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/0B/13 Consolidated Edison Co. of New
  Yorks Inc. 119pp 26197 218 24X Fiche 50-000;84/0B/13,8408100009
- 8408100038 IE Info Notice 84-64. "BWR HPCI Initiation Seal-In & Indication " Svc list and! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc. 104pp 26198 093 24X Fichs 50-000.84/08/15.8408100038
- 8408100021 IE Info Natice 84~65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

- 8408100055 IE info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list enc! JORDAN,E L Division of Emeryency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000.84/08/17.8408100055
- 640B14020B IE Info Notice 84-67. "Recent Snubber Inservice Testing W/ High Failure Rates " Svc 1:st encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 122pp 26276 122 24X Fiche 50-000.84/08/17.8408140208
- B40B210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000.84/08/21.8408210142
- 5 Reportable occurrences, LERs & related correspondence
- B40B220317 Part 21 rept re failure of ITE-27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diode must be added Affected units listed DUVALL.D D Brown Boveri Corp (subs of Brown Boveri & Co., Ltd.) B4/03/13 BEYOUND,R C Director's Office, Office of Inspection and Enforcement 3pp 26191 357 24X Fiche 50-000,B4/03/13,B408220317
- 8408160269 LER 84-012-00 on 840710 during surveillance testing for external piping loakage, both RPR sys trains insperable when valve HCV-74-34 opened Cause not stated Procedure change issued W/840808 ltr
  KIRK, G B . WALLACE, P R Tennessee Valley Authority 84/08/08 3pp 26106 177 24X Fiche 50-328,84/08/08,8408160269
- 8408170053 LER 84-011-00 on 840713, high radiation alarm actuated, causing containment ventilation isolation Caused by voltage spike resulting from electromagnetic interference generated by low flow alarm switch Alarms reset W/840816 ltr DUG01N, G . WALLACE, P R Tennessee Valley Authority 84/08/10 3pp 26130 053 24X Fiche 50-328,84/08/10,8408170053
- 8408240313 Part 21 rept re fitting leaks at incore probe seal tables at PMRs.per IE Info Notice 84-55 Subj fittings not used as instructed HILBON. B Crawford Fitting Co. 84/08/13 JORDAN. Et. Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 26225 313 24X Fiche 50-327.84/08/13.8408240313
- 8408240286 PNO-II-84-053 on 840820 unit shut down after pressure surge caused opening of ice condenser doors, causing relief tank pressure drop & containment pressure rise Caused by relief tank disc rupture or broken safety valve tailpipe FREDERICKSON.P. CONTRELL, F & Region 2, Office of Director 84/08/21 2pp 26223 194 24X Fiche 50-328,84/08/21.8408240286

DOCKET 50-329 MIDLAND PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8408020015 Forwards response to NRC request for add1 info re Vol IX of seismic margin review rept. "Balance-of-Plant Class 1,2 & 3 Piping, Pipe Supports & Valves "COOK, J W Consumers Power Co 84/07/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 16pp 25883 120 24X Fiche 50-329,84/07/11.8408020015
- BAOBOIOO61 Further response to FOIA request for 16 categories of records re facility Documents identified by J Goold & M Biebert on BAO514 & 19 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing FELTON, J M Division of Rules and Records BX14 OOO 84/07/18 RICE.C M Kirkland & Ellis 2pp 26500 001 24X Fiche 50-329-84/07/18,8408010061
- --7Bi2070142 Discusses IE Insp Repts 50-329/78-12 & 50-330/78-12 Contributing factors to settlements of diesel generator bldg foundation & generator pedestals include variable groperties of random fill eatl supporting structure & cooling pond KEPPLER, J G Region 3, Chicago, Office of the Director BX16 001 78/11/01 THORNBURO.H D Division of Reactor Construction Inspection 2pp 26506 211 24X Fiche 50-327,84/07/18,8408010061
- --7909290119 Forwards outline history of geotechnical engineering problems we plant fill Lists pertinent PBAR & FBAR criteria & summarizes foundation conditions & remedial measures for all Category I structures founded on plant fill GILLEN.D M Geosciences Branch NX16 015 79/08/28 JACKGON,R E Geosciences Branch 10pp 24510 309. 24X Fiche 50-329,84/07/18,8408010061

- --8004040738 Summary of 800227 & 28 meeting & site visit w/otil in Midland.MI re soil settlement problems & related investigation program GENZALES.R O Hydrology Meteorology Branch 8XIA 032 80/03/10 BIVINS.W S Hydrology Meteorology Branch 9pp 26511 119 24X Fiche 50-329.84/07/18.8408010061
- --800Bi30764 Summarizas status of seismological input parameters re geosciences & geotechnical review of facilities as discussed at 800702 & 22 meetings KIMBALL, J. Geosciences Branch BX16 029 80/08/07 JACKSON, R. E. Geosciences Branch 6pp 26511 095 24X Fiche 50-329,84/07/18, 84086910061
- --8011240407 Forwards Hydrologic Engineering Section interrogatories re permanent dewatering sys at facilities LEAR, OE Hydrologic & Geotechnical Engineering Branch BX17 008 BO/11/10 TEDESCOR L Assistant Director for Licensing 3pp 26517 244 24X Fiche 50-329.84/07/18.8408010061
- --Bi05070480 Responds to request re Geouciences Branch estimate of time required to complete site review Approx 30 days are needed to review add1 info requested for Part 1 & 3 months are needed for review of Part 2 submittal KNIGHT. JP Assistant Director for Comp & Structures Engineering (Fre B30201) BX6 0578 B1/04/24 PATON, N D Office of the Executive Legal Director 1p 26513 189 24X Fiche 50-329, 84/07/18, 8408010061
- --Bii0170B0l Forwards topic discussions for inclusion in 1781 annual rept.per Bi0902 commitment Discussions of technical assistance program for licensing, GETR review & Midland remedial repair info encl HELLER, L W. Hydrologic & Geotechnical Engineering Branch BX16 053 Bi/07/16 LEAR, O. Hydrologic & Geotechnical Engineering Branch 6pp 26512 253 24X Fichs 50-329,84/07/18.8408010061
- ---8111240064 Informs of 811016 conference call w/util to discuss revised schedule for soils hearing requests revision to better accommodate const schedule Agreed schedule for hearings will be 811201-04 & 1214-18

  HOOD.D Licensing Branch 4 BX19 0368 81/10/30 TEDESCO.R L Assistant Director for Licensing 3pp 26535 252 24X

  Fiche 50-329,84/07/18.8408010061
- --8201050063 Summarizes 811207 telcon re 820105 soils hearing HOOD, D. Licensing Branch 4 BX18 032 81/12/14 ADENSAM, E. G. Licensing Branch 4 2pg 26526 099 24X Fiche 50-329,84/07/18, 8408010061
- --B201220049 Advises of 1-month delay in meeting R Tedesco Bil214 schedule in support of facility hearing & review Viable schedule must recognize need for iteration w/applicant following each significant submittal VOLLHER, R H Division of Engineering BX16 074 81/12/28 EIEENHUT. D G Division of Licensing 3pp 26514 188 24X Fiche 50-329, 84/07/19, 8408010061
- --B202040352 Informs that certain SER sections, especially soil remedial actions, will not be complete by 820406 deadline ADENSAM, E. Q. Licensing Branch 4 BXI6 055 82/01/19 EISENIUT, D. Q. Division of Licensing 3pp 26512 266 24X Fiche 50-329,84/07/18,840801006i
- --8203020050 Summary of Bil004-07 meeting w/util. Bechtel & consultants in Bethesda. MD re underground piping in inadequately compact plant fill HUDD. D S Licensing Branch 4 BX21 002 B2/02/05 DENTON, H R NRC No Detailed Affiliation Olven 37pp 26549 084 24X Fiche 30-329, 84/07/18.8408010061
- --8205080209 Forwards listing of issues to be resolved prior to start of Phase 2 underpinning operations for auxiliary bldg LEAR.0 Hydrologic & Geotechnical Engineering Branch 8x16 035. 82/04/28 ADENSAM.E Licensing Branch 4 2pp 26511 200 24X Fiche.50-329,84/07/18,8408010061
- --8205120033 Summarizes technical comments from ACRS subcommittee 820429 masting re remedial activities for deficient soils ADENSANIE G Licensing Branch 4 BXIB 035 82/05/04 BUSNAK,R NRC No Detailed Affiliation Given 4pp 26527 163 24X Fichs 50-329,84/07/18,8408010061
- --8205210467 Notifies that util submittal re Phase 2 of underpinning repair work at facility acceptable, provided that encl mods a requirements are incorporated into Phase 2 program KNIGHT. J.P. Assistant Director for Comp & Structures Engineering (Pre 930201) BXI6 039 92/05/10 TEDESCO.R L Assistant Director for Comp and Compact Structures Engineering (Pre 930201) BXI6 039 92/05/10 TEDESCO.R L Assistant Director for Licensing 34pp 26511 203 24X Fiche 50-329, 84/07/18, 8408010061

- --9206020051 Comments on draft of acceptance provisions for Phase 2 firtransmittal to applicant should move through DE for concurrence KNIGHT.JP Assistant Director for Comp & Structures Engineerin; (Pre 830201) BX16 036 82/09/13 KANE,J Assistant Director for Comp & Structures Engineering (Pre 830201) 1p 26511 202 24X Fiche 50-329,84/07/18,8408010061
- --9206240401 Forwards comments on 820422 response to NRC request for assiming on the borated water storage tank & underpinning of svc water pump structure Contact w/applicant to resolve differences recommended LEAR, G. Hydrologic & Geotechnical Engineering Branch 82/06/16 ADENSAM, E. Licensing Branch 4 105pp 66127-031 24X Fiche 50-329,84/07/18,8408010061
- ~~8206290161 Submits proposed schedule for facility soils review ADENSAM.E O Licensing Branch 4 BX18 036 82/06/25 EISENHUT, D 0 Division of Licensing 2pp 26527 187 24X Fiche 50-329, 84/07/18,8408010061
- --B207140330 Forwards request for add1 info from Structural Engineering Branch re applicant proposed remedial actions SCHAUER,F P Structural Engineering Branch BX19 029 02/05/15 ADENSAM.E Licensing Branch 4 5pp 26533 206 24X Fiche 50-329,84/07/18,8408010061
- --B210130322 Forwards info re location of data on underpinning dimensions & load transfer procedures
  POULDS: B J Geotechnical Engineers, Inc BX16 060 B2/10/07 KANE. J Division of Engineering 6pp 26513 234 24X
  Fiche 50-329,84/07/18,8408010061
- --8210150698 Clarifies NRC/util interaction re OL review Maint of prosecontrol by licensing property managers necessary to manage licensing activities properly Reviewers requested to follow guidelines ADENBAN.E O Licensing Branch 4 BX16 070 82/09/29 TOMLINSON.E NRC - No Detailed Affiliation Given 2pp 26314 109 24X Fiche 50-329.84/07/18.8408010061
- ---B305270222 Forwards trip rept of B30510-13 site visit re underpinning contract Other topics discussed include cracks in svc water pump structure, heave over freeze wall, need to step laying back soil along underpinning drifts & settlements POULOS.S J Geotechnical Engineers, Inc. BX18 022 83/05/23 KANE, J Division of Engineering 19pp 26524 317 24X Fiche 50-329,84/07/18.8408010061
- --83060603B7 Trip rept of 830511 & 12 site visits to view pier load trit installation & results KANE, J D Structural & Geotechnical Engineering Branch BXIS 021 83/05/27 LEAR, G Structural & Geotechnical Engineering Branch 2pp 26324 315 24X Fiche 50-329,84/07/18,8408010061
- --8307130423 Forwards paper entitled "Use of Site Dependent Spectrs" to be presented at workshop on "Site-Specific Effects of Soil & Rock on Ground Motion & Implications for Earthquake-Resistant Design" on 830726-28

  KIMBALL. J Geosciences Branch BX17 039 83/06/27 JACKSON.R E Geosciences Branch 1p 26520 069 24X Ficha 50-329.84/07/t8.8408010061
- --B307130425 Bpeech entitled "Use of Site Dependent Spectra," to be presented at 830724-28 workshop on "Site-Specific Effects of Boil & Rock on Ground Motion & Implications for Earthquate-Resistant Design" in Santa Fe.NM KIMDALL.J Geosciences Branch BX17 040 B3/06/27 25pp 26520 070 24X Fiche 50-329,84/07/18.8408010061
- --8310070262 Forwards second phase of Geotechnical Engineering input or findings of fact & conclusions of law in response to DELD request Several areas of significant differences exist re diesel generator bldg LEAR. © Structural & Geotechnical Engineering Branch BX17 032 B3709730. PATON. W D Office of the Executive Legal Director App 26519 246 24X Fiche 50-329,84/07/18.8408010061
- --B3120B0185 Forwards technical evaluation of HVAC structural design adequacy, based on findings of Mechanical Engineering Branch design review & audit MNIGHT.JP Assistant Director for Comp & Structures Engintering (Post 830201) BXI8 051 B3/11/25 NOVAK,T M Assistant Director for Comp & Structures Engintering (Post 830201) BXI8 051 B3/11/25 NOVAK,T M Assistant Director for Licensing 27pp 26528 206 24X Fiche 50-329,84/07/18.8408010061
- --8312120393 Requests requisite info re followup action to be tatem by Region III to 831108 recommendation for board notification EISENHUT.D 9 Division of Licensing BX21 014 83/11/30 WARNICK,R F Region 3, Office of Director 1p 26553 204 241 Fiche 50-329,84/07/18,8408010061

- --8406020280 Trip rept of 840504 site visit to participate in public meeting on mgt appraisal program to be performed on util Comments on independent mgt appraisal encl MCLAUGHLIN.P Licensee Gualifications Branch BX20 010 B4/05/22 BODHER.H R Licensee Gualifications Branch 5pp 26539 045 24X Fiche 50-329.84/07/18.8408010061
- --8408010149 Forwards executive summary re GA program update.per B10331 meeting commitment & NRC 810402 ltr Apps will be transmitted by 810522 COOK.J W Consumers Power Co BX14 007 B1/04/30 KEPPLER, J G Region 3. Chicago. Office of the Director (81/03/01) 19pp 26500 039 24X Fiche 50-329,84/07/18,8408010061
- --840802003B Lists questions asked of util during FSAR & 10CFR50 54(f) review, including questions re geological & seismological matters & intake & discharge structures for svc water sys KANEJ NRC Ng Detailed Apfiliation Given Bif 001 B4/07/18 19pp 26514 273 24X Fiche 50-329,84/07/18 8408010061
- --B408020043 Lists questions & responses re condition of soils onsite, correction to foundation problems & risk in allowing const to continue \* NRC ~ No Detailed Affiliation Given BX17 002 79/03/05 15pp 26514 322 24X Fiche 50-329,84/07/18,8408010061

--B408020099 Answers to util interrogatories re staff requests directed on determination & justification of acceptance criteria applied to various remedial measures taken on page 3 of

- --B408020112 Question re discrepancy in magnitude of loading stress on Fig 2 of 800714 rept & info on Tables 4-1A & 2 5-14 \* NRC No Detailed Affiliation Given BX17 012 84/0 26518 143 24X Fiche 50-329,84/07/18.8408010061 BX17 012 84/07/18 1p
- --B408020122 Provides trip rept for 781107 meeting in Urbana, IL resettlement of far east bay of diesel generator bldg List of correction action options provided CCDKE, T C Consumers Power Co BX17 015 78/12/12 Consumer Power Co 4pp 26518 264 24X Fiche 30-329.84/07/18.8408010061 4рр
- --8408020188 Responds to Mooney concept theory re SRP 2 5 4 & PSAR review Suggestion to GELD re Mooney testimony encl HOOD, D NRC No Detailed Affiliation Given BX17 027 B3/11/22 HASGEL, D M NRC No Detailed Affiliation Given 4pp 26519 153 24X Fiche 30-329,84/07/18,8408010061
- ---8408020192 Forwards applicant advance copy of meeting notes for 820727-30 design audit of soils remedial activities in Ann Arbor, MI Questions should be referred to J Kane LEAR, O Hydrologic & Oeotechnical Engineering Branch BX17 043 B2/09717 ADENSAM, E Licensing Branch 4 22pp. 26520 224 24X Fiche 50-327,84/07/18,8408010061
- -8408020173 Informs that Structural Mechanics Assoc seismic margin review studies indicate soil layering profiles & soil properties differ from properties previously addressed KANE.J Structural & Geotechnical Engineering Branch BX17 044 82/05/11 LEAR.G Structural & Geotechnical Engineering Branch 2pp 26520 247 24X Fiche 50-327,84/07/18.8408010061
- --8409020195 Summary of 840417 meeting w/TERA: Structural Mechanics Assoc (SMA) & util in Chicago, IL to discuss SMA seismic margins evaluation & potential applicability to disposition of outstanding civil/structural issues
  RIMALDI.F Structural & Geotechnical Enginearing Branch BX17
  O45 84/07/18 LEAR,O Structural & Geotechnical Engineering
  Branch 2pp 26520,249 24X Fiche 50-329,84/07/18,8408010061
- --8408020199 Forwards request for addi structural engineering info needed to continue OL review of NPP application as applicable to seismic margins review, svc water pump structure & diesel generator bldg.

  LEAR, 6 Structural & Geotechnical Engineering Branch. BX17 044

  84/05/03 ADENSAM Licensing Branch 4 Spp 26521.042 24X

  Fiche 50-329,84/07/18,8408010061
- --8408030001 Handwritten notes & outline of conference call w/Bechtel & util re review of buried piping, monitoring program & future settlement 81/12/15

- ~~B408030004 Summary of B11006-07 meeting w/util in Bethesda.MD re undarground piping in inadequately compacted plant fill Meeting agenda.attendance list & const hydro test viewgraphs HOOD, D S Branch 4 Licensing Branch 4 BX17 048 82/02/05 Licensing 36pp 26515 241 24X Fiche 50-329.84/07/19.8408010061
- -8408030009 Summary of 810721 meeting w/applicant in Bethesde, ND resummary of San Onofre meeting on confirmatory analysis of piping sys design Confirmatory analysis encl ROOD, H Licensing Branch 3 8XI7 049 81/08/19 Licensing Branch 3 29pp 26515 277 24X Fiche 50~329.84/07/18,8408010061
- --B40B030013 Notification of 820416 meeting w/util in Bethesda, MD to discuss buried piping & related applicant 820316 cubmittal W/handwritten notes of 820407 conference call & outline of outstanding issues in gentechnical engineering area HOUD. D S Licensing Branch 4 BX17 050 82704/13 ADENBAN.E 0 Licensing Branch 4 22pp 26515 306 24X Fiche 50-329,84/07/18,8408010061
- --8408030020 Handwritten notes on 810120 meeting re stress analysis for underground piping Outline of discussion topics for pipe stress analysis encl KANE, J NRC No Detailed Affiliation Given 8X17 052 81/01/20 NRC No Detailed Affiliation Given 18pp 24515:355 24X Fiche 50-329,84/07/18,8408010061
- --8408030028 Agenda for 820121-22 meeting to discuss underground piping concerns W/handwritten summary of 820107 conference call reunderground piping & 820120 evaluation of sand settlement due to earthquake
  KANE, J NRC No Detailed Affiliation Given 8X17 055 82/01/22
  NRC No Detailed Affiliation Given 23pp 26514 017 24X
  Fiche 50-329,84/07/18,8408010061
- --8408030042 Agenda for 811006 meeting w/Bachtel.util & Army Corps of Engineers to discuss underground piping reprofiling.proposed demonstration solution & 1981 measurement results \* NRC No Detailed Affiliation Given BX17 058 81/10/06 Office of Nuclear Reactor Regulation, Director 11pp 26516 045 24X Fiche 50-329,84/07/18.8408010061
- --8408030051 Handwritten notes re add1 boring logs at buried diesel generator fuel oil storage tank location Calculation sheets & boring logs encl MEISENHEIMER, J. NRC No Detailed Affiliation Given BX17 060 B2/03/27 XANE, J NRC No Detailed Affiliation Given 13pp 26516 057 24X Fiche 50-329,84/07/18,8408010061
- --8408030056 Handwritten notes re 810120 meeting w/applicant on settlement of Category I underground piping KANE, J NRC No Detailed Affiliation Given BX17 O61, 81/02/09 CAPPUCCI, T NRC No Detailed Affiliation Given App 26516 070 24X Fichs 50-329.84/07/18,8408010061
- --8408030058 Forwards svaluation of general acceptability of effects of settlement in several buried svc plping sys Rept partial response to FSAR Questions 16 through 20 & 34.

  KLEIN, B R Bachtel Corp BXI7 062 80/08/01 CURTIS. L H Bechtel Corp 7pp 26516-074 24X Fiche 30-329.84/07/18, 8408010061
- —8408030064 Forwards analysis of buried piping background info, in support of proposed demonstration solution & in response to NRC concern re underground piping Addl engineering info REELEY, O S Consumers Power Co BX17 063 81/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director, 76pp, 26516:081 24X fiche:50-329,84/07/18:8408010061 KEELEY C S
- --8408030068 Forwards stress analysis of several underground pipe lines as profiled in New 5 of "Responses to NRC 10CFR50 34(f) Requests re Plant Fill" dtd 800401.

  BATES, J D Rockwell International Corp BX17 064 80/10/01

  BOSNAK, R J Hechanical Engineering Branch 52pp. 26516 162 24X

  Fiche 50-329,84/07/18.8408010061
- ---8408130227 Contract for consulting svcs between util & Mgt Analysis Co.
  agreeing to perform technical svcs.including consulting & QA
  svcs Purchase requisition, internal memos & supporting documentation encl documentation enci COOK, J W Consumers Power Co 8X15 001 82/01/15 350pp 24500 316 24X Fiche 50-329,84/07/18,8408010061
- -8408130230 Discusses 830118 & 26 meetings in Olen Ellyn, IL re Region III insp of diesel generator bldg & independent design review program respectively Midland project manager will attend 830126 public meeting ADENSAM.E G Licensing Branch 4 BX15 002 83/01/05 NGVAK.T M Assistant Director for Licensing 19pp. 26502.089 24X Fichs 30-320.84074(8.840801006) Fiche 30-329,84/07/18,8408010061

- ---9408130234 Draft memo re issues of potential impact on Hearing Board considerations concerning GA program KEPPLER.J G Region 3. Defice of Director EIBENHUT.D Q Division of Licensing 7pp 26502 121 24X Fichs 50-329.84/07/18.8408010061
- --8408130241 Notification of 821207 mgt meeting w/Region III to discuss implementation of GA & IDVPs
  HERNAN,R W Licensing Branch 4 BX15 004 B2/11/01 NDVAK.T M Assistant Director for ticensing 2pp 26502 131 24X
  Fiche 50-327,84/07/18,8408010061
- --B408130244 Forwards SALP 3 echedule Internal memos, handwritten in-process inap hotices, program notes & supporting decumentation encl
  TAMBLING, T N Region 3, Office of Director BK15 005 82/11/01
  Region 3, Office of Director 53pp 26502 133 24X
  Fiche 50-329,84/07/18,8408010061
- --8408130255 Forwards response to draft SALP rept Requests meeting w/ Keppler to review detailed contents of response Internal memos & handwritten notes encl CCCK.J W Consumers Power Co 8X15 006 82/05/17 KEPPLER.J Q Region 3. Office of Director 71pp 26502 188 24X Fiche 50-327,84/07/18,8408010061
- ---8408130269 "Const Project Evaluation of Consumers Power Co. Midland Energy Ctr Project.Units 1 & 2 (Observations) "

  \* Management Analysis Co 8X15 007 83/01/31 160pp 26502 311 24X Fiche 50-329,84/07/18,8408010061
- --840Bi30290 Forwards Mgt Analysis Co assessment of Midland QA program Rept endorses program W/o encl
  CDOK-J W Consumers Power Co BX15 OO8A 81/06/01 KEPPLER.J O
  Region 3. Chicago Office of the Director (B1/03/01) 40pp
  26503 178 24X Fiche 50-329.84/07/18.840B010061
- --840Bi30301 Bubmits changes to be implemented prior to util resuming remedial soils work Draft list of noncompliances & deviations handwritten notes & list of events since Juli4981 hearings encl WARNICK R F Region 3. Office of Director BX15 010 82/09/20 MEPPLER, J Q Region 3. Office of Director 70pp 26504 031 24 Fiche 30-329, 84/07/18, 840B010061
- --8408130306 "Biennial GA Audit of Midland Plant, Units 1 & 2 " Opening remarks of NRC 830208 neeting w/util & independent review encl.

  \* Management Analysis Co 8X15 011 83/03/01 75pp 26504 131, 24X Fichs 30-327,84/07/18,8408010061
- ~~8408130311 Notification of significant licensee 830313 meeting in Glan Ellyn,IL to present INPO findings \* Region 3, Office of Director BX15 012 83/03/09 Region 3 Office of Director 1p 26504 261 24X Fiche 50-327,84/07/18, 8408010061
- --8408130320 Forwards status rept for Midland Project for Jan 1983 W/o encl WARNICK.R F Region 3. Office of Director BX15 013 B3/02/14 KEPPLER.J O Region 3. Office of Director ip 26504 293 24X Fiche 50-329,84/07/18.8408010061
- --B40B13G323 Forwards status rept for Jan 1983 Rept contains input from each member of insp site team of Ofc of Special Cases
  COOK.R J Region 3. Office of Director BX13 014 83/02/10
  SHAFER.W D Region 3. Office of Director 3pp 26504 294 24X
  Fichs 50-329,84/07/18.8408010061.
- --8408130327 Forwards monthly status repts for Aug-Oct 1782 WARNICK, R F. Region 3. Office of Directon BX15 015 82/12/20 KEPPLER.J. G. Region 3. Office of Director 10pp 26504 303 24X Fiche 50-329,84/07/18,8408010061
- --8408130336 Requests approval not to perform SALP 3 assessments, due to midespread recognition of mgt GA & const problems Draft notice of violation insp rept & handwritten notes re diesel generator hidg monorall end!

  KEPPLER, J & Region 3. Office of Director. 8X15 017 83/04/01 DEYOUNG, R & Director's Office, Office of Inspection and Enforcement 98pp. 26505 043 24X Fiche 50-329,84/07/18,8408010061
- --8408130348 Submits issues to be addressed at forthcoming evidentiary session on QA & GC matters
  PATON.W.D. Consumers Power Co. BX15 019. 82/08/10 ADENBAM, E 9
  NRC No Detailed Affiliation Given App. 26505 276 24X
  Fiche 30-329, 84/07/18, 8408010961

- --8408130356 Forwards monthly status rept for Midland Project for Jan 1983 COOK,R J Region 3, Office of Director BX15 022 83/02/10 SHAFER.W D Region 3, Office of Director 3pp 26905 302 24X Fiche 50-329,84/07/18,8408010061
- --8408140039 Draft IE Insp Repts 50-329/78-20 t 50-330/78-20 from insp on 791211-20 t 790104-25 Violations noted inadequate control t supervision of plant fill matl placement t const specs not followed PHILLIP, G A , GALLACHER, E J , MAXWELL, G F Region 3, Office of Director 8x16 002 84/07/18 60pp 26507 112 24X Fichs 50-329,84/07/18,8408010061
- --B40B140030 Summary of NRC 790407 site tour & mosting on differential sattlement of plant bldgs TC Cooke 790704 itt to Bechtel re stainless steel pipe deficiency encl COMK. T C Consumers Power Co BX14 003 79/04/13 Consumers Power Co App 26507 311 24X Fiche 50-329.84/07/18.8408010061
- --8408140055 Preliminary "Discussion of NRC Insp Facts Resulting From NRC Investigation of Diesel Generator Blidg Settlement" # Consumers Power Ce RX16 004 79/03/05 35pp 26507 315 24X Fichs 50-329.84/07/18,8408010061
- --8408140060 Forwards synopsis of 800228 presentation, "Remedial Measures for Electrical Penetration Wings of Control Bldg & Isolation Valve Pits" conducted before NRC representatives in Midland, MI
  GOULD.C H Affiliation Not Assigned BX16 005 80/03/17
  AFIF1.8 8 Bechtel Corp 22pp 26507 350 24X
  Fiche 50-327,84/07/18,8408010061
- --B40B140065 Forwards general procedures & details employed by contractor to undorpin fine arts bldg Bketches enci MARR.Q Bechtel Corp BX16 006 79/04/25 AFIF1.S Bechte Corp 6pp 2650B 010 24X Fiche 50-329.84/07/18.8408010061
- --8408140069 Lists areas to be clarified &/or amplified in responses to 10CFR50 54(f) questions Summary of spils chronology & 790807 internal manners pre-meeting w/consultants encl COCKE.F C Consumers Power Co BX16 007 80/01/25 ROTHWELL, M O Buchtel Corp 14pp 26508 016 24X Fichs 50-329,84/07/18.8408010061
- --B40B140071 Bubmits const QC response to 790329 questions re diesel generator bldg No variance exists from QA program requirements

  JOHNSON, D R Bechtel Carp BX16 008 79/04/09 RICHARDSON, O L
  Bechtel Corp 9pp 26508 030 24X Fiche 50-329, B4/07/18,
  B40B160061
- --8408140076 Comments on recommendations given in soils repts prepared by Dames & Moore as compared to Bechtel sarthwork specs Plant area fill supporting surrounding structures. Category I slopes & borm fill discussed

  AFIF1,8 8 Bechtel Corp 0X16 009, 74/09/13 CABTLEBERRY. R
  Bechtel Corp 5pp 26508 039 24X Fiche 50-329,84/07/18.
- --B408140077 Recommends issuance of revised TPO std specs re large settlement due to incorrectly placed backfill Addl correspondence on problem alert & summary of soils chronology encl
  RUMBAUGH.E Bechtel Corp BX16 010 79/12/27 JOHNSON.T E Bechtel Corp 33pp 26508 044 24X Fiche 50-329,84/07/18,8408010061
- ---S40B140102 Forwards complete set of all abstracts of transcripts of hearings conducted on 811231-830630 W/listing of entire set of abstracts
  HAMPTON.L Isham Lincoln & Beale BX16 012 83/07/18
  PATON.W D Hearing Branch 2 425pp 26508 097 24X
  Fiche 30-389,84/07/18,8408010041
- --B408140134 Handwritten notes re borings in area of svc water piping that have indicated potential for liquefaction W/Dept of Army memo re Feb 1980 visit to util & review of FEAR KANEJ NRC No Detailed Affiliation Given BX16 014 B2/10/14 19pp 26510 227 24X Fiche 50~329,84/07/18,8408010061
- --8408140194 Testimony of HN Bingh re unresolved geotechnical engineering safety issues, including reactor bldg foundation, diesel generator bldg settlement & svc water bldg foundation & borsted water tanks
  BINGH,H N Army, Dept of, Corps of Engineers BX16 016
  B4/07/18 13pp 26510 319 24X Fiche 50~329.84/07/18,8408010041

- --8408140192 Handwritten notes on admission of facts re plant fill problem & cracking of certain safety-related structures resulting from inadequately compacted fill matls W/handwritten notes re discussion w/B Paton on hearings + NRC No Detailed Affiliation Given 8X16 017 81/03/06 2pt 26510 331 24X Fiche 50-329,84/07/18,8408010061
- --8409140158 Notifies of plan to take depositions of Bechtel employees in Ann Arbor beginning on 801209 Depositions will address errors made in soil placement PATON, W.D. Office of the Executive Legal Director 0X16 018 80/11/19 0LMSTEAD. W.J. Regulations Division 2pp 26510 333 24X Fiche 50-329,84/07/18,8408010061
- ~~8408140163 Presents reasons why Phase II const will not be detrimental to foundation support of auxiliary bldg Phase II primary consists of 3x6 ft hand dug piers & 7x6 ft wide access drifts for access to pier
  KANE, J., BARTLETT, D. NRC No Detailed Affiliation Given BX16
  019 82/01/19 1ipp 26510 335 24X Fiche 50-329,84/07/18,8408010064
- --8408140170 Handwritten notes re general description of extent of plant fill problem Proposed remedial measures, list of viewgraphs & viewgraphs for ACRS presentation encl YANE. J NRC No Detailed Affiliation Given BX16 020 82/04/26 37pp 26510 346 24X Fiche 50-329,84/07/18,8408010061
- --8408140185 Confirms comments previously provided re Item E on Page 5 of 830715 ltr concerning slope layback during underpinning Item E expresses concern by 88M inspectors that slope layback is greater than in design POULOS, S J Ceotechnical Engineers, Inc BX16 022 83/07/22 KANE. J Office of Nuclear Reactor Regulation. Director 2pp 26311 029 24X Fiche 50-329,84/07/18,8408010061
- --8408140176 Summarizes comments re 830914-15 audit of facility underpinning Purpose of audit was to gather info from applicant re effect on design & const of reducing modulus of hard clay foundation from 3000 Ksf to 5000 Ksf PUULOS.S J Geotechnical Engineers, Inc BX16 023 83/09/22 KANE. J Office of Nuclear Reactor Regulation, Director 3pp 26511 031 24X Fiche 50-329,84/07/18,8408010061
- --8408140209 Handwritten notes re design details for borated water storage tanks & util position on cause of cracking KANE. J NRC - No Detailed Affiliation Given BX16 024 81/07/28 2pp 26911 050 24X Fiche 50-329.84/07/18.8408010061
- --8408140213 Handwritten summary of 810805 meeting in Ramada Central Inn re borated water storage tank W/810728 handwritten memo re status of review on borated water storage tank KANE. J NRC - No Detailed Affiliation Given BX16 025 81/08/05 NRC - No Detailed Affiliation Given 2pp 26511 032 24X Fiche 50~329.84/07/18.8408010061
- --840B140218 Handuritten notes re discussion w/O Gallagher about surcharging of valve pits near borated water tanks Record of telcon w/util.Bechtel & Geotechnical Engineering on 810715 re surcharging valve pits encl
  \* NRC No Detailed Affiliation Given BX16 026 81/07/01 4pp 26511 054 24X Fiche 50-329,84/07/18,8408010061
- --840B140223 Handwritten notes reviewing comments on borated water storage tanks & valve pit settlements KANE. J NRC - No Detailed Affiliation Given BX16 027 B1/07/28 1p 26511 074 24% Fiche 50-329.84/07/18.840B010061
- --8408140232 Forwards draft comments on info received from applicant through Amend 85 to OL request & Rev IO to 10CFR30 54(f) requests re borated water tanks Info received addresses all questions raised in 800707 itr
  MCCALLISTER,P Army, Dept of Corps of Engineers DXIA 028 81/03/26 JACKSON,R E NRC No Detailed Affiliation Given 14pp 26511 075 24X Fiche 50-329.84/07/18,8408010061
- --E40Bi40242 Forwards branch position re seismological input parameters
  Position necessary to resolve differences between applicant
  & NRC on seismological issues & to provide guidance for
  inputing vibratory motion in evaluations

  JACKBON.R E Geosciences Branch BX16 030 80/07/08
  SCHMENCER.A Licensing Branch 3 6pp 26511 101 24X
  Fiche 30-329,84/07/18,8408010061
- --B40B14024B Urges studies evaluating soil liquefaction & stability under dynamic loading & using values of acceleration in range of 0 12g to 0 17g at ground surface Also forwards list of strong motion records ROTFMAN.R L Geosciences Branch BXI6 031 B0/02/11 JACKSON.R E Geosciences Branch 7pp 26511 107 24X Fiche 50-329,84/07/18,8408010061

- --9408140263 Motion to consolidate for discovery, evidentiary presentation & fact finding purposes issues relating to soil conditions for safety-related structures & sus founded in & on plant fill math in hearing considering 791206 order FARNELLIA S Consumers Power Co FARNELLIA S Isham, Lincoln & Beale 8X16 034 80/05/27 Atomic Safety and Licensing Board Panel 15pp 26511 159 24X Fiche 50-329, 84/07/18,8408010061
- --B4081402B6 Testimony of H Singh re origin remedial measures proposed by applicant for auxiliary bldg & Corps of Engineers evaluation of remedial measures SINGH-H NRC - No Detailed Affiliation Civen BX16 038B B1/11/12 3pp 26511 242 24X Fiche 50-329.B4/07/18.840B010061
- --8408140296 Draft testimony of 8J Poulos re remedial underpinning of svc water pump structure POULOS, S J Geotechnical Engineers, Inc BX16 040 B2/03/30 lipp 26511 271 24X Fiche 80-329, 84/07/18,8408010061
- --8408140300 Testimony of HN Singh Te svc water pump structure SINOH: H N Geotechnical Engineers, Inc BX16 041 82/04/08 7pp 26311 282 24X Fiche 50-327,84/07/18,8408010061
- --8408140319 Summary of 810917 meeting w/CPC.US Army Corps of Engineers, NRC.Bechtel & Musser.Rutledge.Wentworth & Johnson in Bethesda.MD re preliminary design of proposed remedial measures for svc water pumping structure
  SINGH.H N Army, Dept of, Corps of Engineers BX16 044
  B1/09/18 Army, Dept of, Corps of Engineers 3pp 24511 341
  24X Fichs 50-329,84/07/18,8408010041
- --B408140347 Summary of 829422 meeting w/CPC.consisting of answers to GE8 questions re permanent dewatering sys. soil stabilization. Jacking procedure & draft SER KANE. J NRC No Detailed Affiliation Given BX16 046 82/06/25 NRC No Detailed Affiliation Given 4pp 26511 34B 24X Fiche 50-329,84/07/18,8408010061
- --B40Bi40332 "Dynamic Core Penetrometer " Sketchs & design calculations of underpinning & settlement analysis study encl ANDERSON, J NRC No Detailed Affiliation Divon BX16 047 B2/03/17 42pp 26512 056 24% Fiche 50-329
- ---8408140359 Handuritten notes re settlement monitoring programs, classification of fines, instrumentation & agenda for 781204 meeting re diesel generator bldg # NRC No Detailed Affiliation Given BX16 049 84/07/18 10pp 26512 210 24X Fiche 50-329,84/07/18 8408010061
- --8408140367 Draft ltr re Interagency Agreement NRC-03-76-167. Task 1.
  Subtask 3 concerning comment on Amend 85 List of specific discrepancies re settlement evaluations encl
  SINGH, H Army, Dept of, Corps of Engineers BX16 051 81/02/26
  KANE, J. JACKBON, R E NRC No Detailed Affiliation Given 13pp 26512 221 24X Fiche 50-329,84/07/18,8408010061
- --8408140513 Summary of R Landsman 810325-27 & 0407-09 insps conducted to verify QA program for util soil borings conducted in response to Corps of Engineers request for addition info \* NRC No Detailed Affiliation Given BX16 054 84/07/18 4pp 26512 259 24X Fiche 50-329,84/07/18.8408010061
- --8408140522 Informs that, in preparation for issuance of draft SER in mid-late Jan, section by section review of which sections of draft received by Div of Licensing to date complete HERNAN, R W Licensing Branch 4 8X16 055A 82/01/12 ADENGAM, E 0 Licensing Branch 4 3pp 26512 267 24X Fiche 30-329, 84/07/18, 8408010061
- ---B408140526 Summarizes B1040B stipulation filed by util & NRC re GA aspects of hearing on soils settlement scheduled to begin B10707
  HD0D,D Licensing Branch 4 BX16 036 B1/06/0B DENTON,H, CARTER,J Office of Nuclear Reactor Regulation, Director EIEENHUT,D G Division of Licensing ip 26512 272 24X Fiche 50-329,84/07/18,8408010061
- --840B140530 Draft memo providing estimate for completing review & preparing testimony on proposed remedial actions, in response to OELD request for schedule for review LEAR, J NRC No Detailed Affiliation Given BXI6 057 81/06/19 KNIGHT, J NRC No Detailed Affiliation Given 3pp 26513 185 24X Fiche 50-329,84/07/18,8408010061
- --8408140539 Requests estimate of time required to complete review & prepare testimony re proposed remedial actions Testimony by F Rinaldi, T Cappucci & J Kane needs to be filed by 810915 PATON, W D Office of the Executive Legal Director BX16 057A 81/07/18 KNIGHT, J P Assistant Director for Comp & Structures Engineering (Pre 830201) ip 26513 188 24X Fichs 50-329.84/07/18,8408010061

- --B40B140553 Util news ltr re lifting of part of series of stop work orders that halted const of plant \* Consumers Power Co BX16 O61 84/01/20 1p 26513 247 24X Fiche 50-329, 84/07/18, 8408010061
- --8408140556 Documents contacts by Kirkland & Ellis attys representing Dow Chemical in suit against CPC Summary of meeting by Gestechnical Engineering. Inc encl KANE. J D Structural & Gestechnical Engineering Branch BX16 062 84/01/23 Structural & Gestechnical Engineering Branch 14pp 26513 263 24X Fiche 50-329,84/07/18.6408010061
- ---8408140357 Forwards comments re applicant submissions concerning cracks in diesel generator, fixation of cracks in borated water storage tanks, underpinnings & effects or cracks on serviceability of structures MCGMLISTER, P Army, Dept of, Corps of Engineers BX16 063 BR/06/15 LEAR, G Division of Engineering 14pp R6513 277 24X Fiche 50-327,84/07/16,8408010061
- --8408140562 Handwritten document summarizing util response to NRC Guestians 24,45 & 47 on permanent dewatering re geotechnical engineering issues Meeting summaries encl.

  \* Consumers Power Co BX16 064 81/10/12 32pp 26513 271 24X Fiche 50-327,84/07/18.8408010061
- ---8408140565 Handuritten document re liquefaction analysis KANE, J C NRC - No Detailed Affiliation Given BX16 065 82/08/16 5pp 26513 323 24X Fiche 50-329,84/07/18,8408010061
- --8408140566 Requests analysis of possible enforcement action re applicant failure to inform NRC of settlement of diesel generator bldg PALLADIND, N NRC - No Detailed Affiliation Given. 8X16 066 84/05/24 DIRCKS.W Office of the Executive Director for Operations ip 26514 031. 24X Fiche 50-327,84/07/18,8408010061
- ---8408140570 "Administrative Bldg Foundation Settlements Along Column Line O 4 " \* Bechtel Corp BX16 068 77/12/31 21pp 26514 033. 24X Fiche 30-329,84/07/18,8408010061
- --8408140573 Forwards Bechtel rept. "Administrative Bldg Foundation Settlements Along Column Line O 4" BRUNNER, J E Consumers Power Co BX16 067 81/09/14 PATON, W NRC - No Detailed Affiliation Given 1p 26514 032 24X Ficus 50-029,84/07/18,8408010061
- --B40B150015 Requests add1 barings & existing soil data, Revised Encl 1 to B00327 ltr encl MCCALLIBTER.P., Army, Dept of, Corps of Engineers BX16 071 B4/07/18 JACKBON.R E NRC No Detailed Affiliation Given App 26514, 140 24% Fiche 50-329, 84/07/18, 840B010061
- --8408130019 Handwritten notes he status of ABLB hearings First session. completed 810707-17, covered items he Stamin's Contention I, GA breakdown, NRC--til stipulation on GA managerial attitude & FBAR false statement KANE, J NRC No Detailed Affiliation Given BX16 072 81/08/18 11pp 26514 146 24X Fiche 50-329,84/07/18,8408010061.
- --8408:80022 Handwritten notes to location of sources of important util submittals prior to 791206 Topics outlined include auxiliary bldg.diesel generator bldg.borated water storage tank & permanent dewatering KANE, J NRC No Detailed Affiliation Given. BX16 073 81/05/18 Gipp 26314 157 24X Fichs.50-329.84/07/18.8408010061
- --B40B150027 Summary of B40304 meeting w/util re schedules & topics for instant hearing on soils matters Hearing schedule resulting in inefficient reviews due to changing const priorities by applicant.

  HGDD,D Licensing Branch 4, BX16 075 B2/03/11 TEDESCO,R.L. Assistant Director for Licensing 43pp 26514 191 24X Fiche. 50-329, B4/07/18, 840B010061
- ---8408180027 Task interface agreement re plant remedial soils issue IPPOLITO, T Region 3. Office of Director. NORELIUS, C Director's Office, Office of Inspection and Enforcement VOLLMER, R Office of Nuclear Resolution. Director 8%16 076 83/04/18 8pp 26514:234 24% Fiche 50-329,84/07/18.8408010061

- --B408150033 Discusses 830929 conference call during which D Hood gave verbal approval to allow licensee to proceed w/underpinning through UATs LANDSMAN.R B Region 3. Office of Director 8X16 077 B3/09/30 Region 3. Office of Director ip 26914 241 24X Fiche 50-329,84/07/18.8408010061
- --8408190042 Handwritten notes commenting on Peck 810807 transcript re compaction criteria KANE, J NRC - No Detailed Affiliation Given 8X16 079 81/08/10 2pp 26514 264 24X Fiche 80-329,84/07/18,8408010061
- --8408130045 Handwritten notes re electrical penetration area w/comments of H Singh on unresolved issues prior to 791205 & underground utils SINGH.H NRC No Detailed Affiliation Given BX16 080 BI/05/20 2pp 26514 266 24X Fiche 50-329.84/07/18.8409010061
- --8408150560 Comments on licensee draft commitments to improve implementation of quality program in remedial soils area & remaining const activities.per 820907 request Noted changes should be made in program
  WARNICK.R F Region 3. Office of Director 8X21 001 82/09/24
  KEPPLER.J G Region 3. Office of Director 4pp 26549 080 24X
  Fiche 50-329.84/07/18.8408010061
- --B40B190366 "Pier Load Test Data Load by Carlson vs Load by Jacis " Related info enc! HUNT.S W Bechtel Corp BX21 003 83/04/29 200pp 26549 215 24X Fiche 30-329,64/07/18,8408010061
- --8408150571 "Well OBS-4 Subsidence Rept " HUNT.S W Bechtel Corp BX21 004 B2/06/11 50pp 26550 120 24X Fiche 50-329, 84/07/18, 8408010061
- --8408150577 Forwards recent audit repts by Midland GA dept.per request BRUNNER.J E Consumprs Power Co 8X21 005 82/01/15 BECHHOEFER.C. HARBOUR.J Atomic Bafety and Licensing Board Panel GOWAM.F P Affiliation Not Assigned 26pp 26550 222 24X Fiche 50-329,84/07/18.8408010061
- --8408150386 Forwards recent audit repts by Midland GA dept.per request
  Related info encl.including notes of CPC/NRC 630208 public
  meeting reconst completion program
  pRUNNER.J E Consumers Power Co BX21 006 82/02/05
  BECCHROEFER.C , HARIBUR.J Atomic Safety and Licensing Board Panel
  COMMAN.F P Affiliation Not Assigned 104pp 26550 248 24X
  Fiche 50-329,84/07/18.8408010061
- --8498150395 Opposes issuance of fuel license (10CFR70) for applicant, based upon extensiveness of remedial soils work & potential for work to inpact auxiliary bldg Related info encl COOK.R. J. Region 3. Office of Director 8X21 007 83/01/25 8HAFER.W D. Region 3. Office of Director 17pp 26551 001 24X Fiche 50-329,84/07/18.8408010061
- --8408150608 Rev 4 to "Quality Plan for Underpinning Activities " Relatif info enc! BIRD.W., BGDS,A J., MGDNEY, J. Consumers Power Co. 8X21 009 82/10/12 59pp 26551 316 24X Fiche 50-329,84/07/18,8408010061
- --840B150616 Enumerates QA issues to be addressed at evidentiary session in Midland proceeding, per encl B20707 memorandum & order W/o encl PATON, W D Office of the Executive Legal Director BX21 Ol1 B2/08/10 ADENSAM.E G NRC No Detailed Affiliation Given 269 26553 087. E4X Fiche 50-329.84/07/18,840B010061
- --8408130617 Forwards further response to FOIA-84-96, consisting of records selected from files of Harrison & Norelius during 840628 visit ROY, Q W. Office of Resource Management, Director 8X20 001 84/07/06 RICE, C M Kirkland & Ellis 3pp 26537 339 24X Fiche 50-329, 84/07/18, 8408010061
- --840BiS0624 Draft summary of NRC 840229 meeting w/util at Region III oft re results of NRC HVAC insps & investigation of allegations & expansion of GA training qualification & certification activities Viewgraphs encl \* Region 3, Office of Director 8X20 002 84/02/29 Region 3, Office of Director 2ipp 26537 342 24X Fiche 50-329,84/07/18, PANSULONG
- --8408130626 Forwards HR Denton B31219 itr distinguishing between terms "important to safety" & "safety-related" Related info encl KEPPLER, J & Region J, Office of Director BX21 013 B3/12/29 Region J. Office of Director Dpp 26553 163 24X Fiche 50-329,84/07/18,8408010061

- --B40B150630 Forwards addl info re Region III inquiries into Ofc of Special Cases concerning Midland & Zimmer Nuclear Power Plant problems in implementing GA programs Nonconformance rept also encl
  WARNICK.R F Region 3, Office of Director BX2O 003 83/09/16
  BOULDEN.H Office of Inspector & Auditor 18pp 26538 001 24X
  Fiche 50-329,84/07/18,8408010061
- --8408150635 Notifies that commercial operation date of Unit 2 may be delayed until mid-1986 Const schedule for Unit 1 will be revised based on cashflow requirements, need for power, final cost estimates & schedule for Unit 2 KOSCHIK, M & Consumers Power Co BX21 015 63/11/09 STRASMA, J Region 3. Office of Director 2pp 26553 216 24X Fiche 50-329,84/07/18,8408010061
- --B408150643 Forwards listed documentation in response to FDIA 83-397 for reproduction MARNICK,R F Region 3, Office of Director BX20 006 83/07/20 SKIDTH.P T Region 3, Office of Director 1p 26538 156 24X Fiche 50-329,84/07/18,8408010061
- --9408130648 Draft summary of NRC Caseload Forecast Panel 830419-21 meeting w/util at plant site re basis for util revised estimates of Oct 1984 & Feb 1985 for Unit 2 & 1, respectively Rept on Rev 12 schedule encl NOVAK.T H Assistant Director for Licensing 8X20 007 83/05/25 CDBK,J W Consumers Power Co 32pp 26538 157 24X Fiche 30-329,84/07/18,8408010061
- --8408150651 Requests NRC approval to postpone yellowbook update due to inadequate work experience enabling devolopment of definitive project schedule, per 831014 ltr GUAMME.D L Consumers Power Co 820 008 84/01/12 HARTFIELD.R A Management Information Branch 1p 26539 002 24X Fiche 50-329.84/07/18.8408010061
- --B408150652 Notifies of intent to continue const of plant following recent notification from Dow Chemical Co of decision to terminate agreement to purchase energy Related info enci FIT2PATRICK, R Consumers Power Co BX21
- --840B150656 Responds to 840409 comments re util proposed plan to conduct independent mgt appraisal of Midland Nuclear Project Affidavits of independence of individuals working on audit ancl.

  REHM. T A Office of the Executive Director for Operations 8X20 009 84/06/08 GARDE, B P Oovernment Accountability Project 31pg 26539 014 24X Ficho 30-329.84/07/18.8408010061
- --840Bi50662 Enumerates agreements/understandings reached at 820823 meeting w/NRC re approval for portions of Phase II underpinning work Related info encl MILLER, D B Consumers Power Co BX21 021 82/08/25 SHAFER, W D Region 3, Office of Director 14pp 26554 241 24X Fiche: 50-329, 84/07/18, 8408010061
- --8408150665 Comments on util 840307 proposed independent mgt plan Plan does not indicate how Cresap.McCormick & Paget & TERA will function & interface Roles, authorities & responsibilities should be identified Handwritten comments encl
  DEYOUNO.R C Director's Office, Office of Inspection and Enforcement BX20 Oii 84/03/27 KEPPLER.J G Region 3, Office of Director 4pp 26539 052 24X Fiche 50-329,84/07/18.
- ---8408150666 Summary of NRC 840314 meeting w/D Bridenbaugh of MAB Technical Assocs in Region III re info on Midland & Zimmer plants Util 840124 ltr to Atty General of State of MI encl MARNICK.R F Region 3, Diffice of Director BX20 012 84/03/20 Region 3, Office of Director 7pp 26537 136 24X Fiche 50-329,84/07/18,8408010061
- --8408130476 Forwards util testimony on cable pulling incident Requests comments Lists questions to be addressed WILCOVE, N N Office of the Executive Legal Director BX20 014 B3/05/13 LANDSHAN.R, COOK,R, GARDNER,R NRC No Detailed Affiliation Given 7pp 26539 306 24X Fiche 50-329.84/07/18, 8408010061
- --B468150681 Discusses policy & procedure changes re communications w/ licensee Related info encl HARNICK.R F Region 3, Office of Director 1821 027 82/09/17 BFL58ARD,R L Division of Project & Resident Programs NURELIUB.C E Division of Engineering HIND.J A Division of Radiological & Materials Safety Programs 8pp 26355 067 24X Fiche. 50-329, 84/07/18, 8408010061

- --B4081506B2 Advises that FDIA Request 62-616 received Matl requested must be submitted to director by 840103 Nonconformance repts & Interim Rept 3 re cable tray support const welding discrepancy encl
  SMIDTH, P T Region 3, Office of Director BX20 015 82/12/22 Region 3, Office of Director 2pp 26539 359 24X Fiche 50-329, 84/07/18,8408010061
- --8408130685 Discusses QA program re underpinning instrumentation installation Lists steps to follow to implement reclassification of underpinning activities COUK.J W ConsumBrs Power Co 8821 028 82/03/31 NORELIUS.C E Division of Engineering 2pp 26535 110 24X Fiche 50-327,84/07/18,8408010061
- ---B40B130686 Advises that allegations received from Dow Chemical & util are treated equally Forwards E Driker B40304 ltr re Dow Chemical vs CPC lawsuit
  BERKOVITZ, D.M. Office of the General Counsel BX20 016
  84/05/11 LEWIS, S.H. Region 3. Office of Director ip
  26540 094 24X Fiche 30-329,84/07/18,840B010061
- --B408130689 Buboits summary of views re regulatory status of plant Illegible handwritten notes encl KEPPLER, J & Region 3, Office of Director BX20 016A 84/06/06 FISCHER, R Michigan, State of 12pp 26540 095 24X Fiche 50-329, 84/07/18, 8408/010061
- --8408150492 Forwards newspaper stories indicating representives of Dow Chemical met w/NRC to discuss matters in littgation pending in County Circuit Court w/vtil JD Selby 840608 Itr to FJ Kalley encl
  DRIKER, E Barris, Sott, Dønn & Driker BX20 017 84/05/04
  BERROVITZ, D Office of the General Counsel 18pp 26540 160
  24X Fiche 50-329,84/07/18,8408010061
- --B408150495 "Site Visit to Evaluate Crack Reported B30218 in Roof of Feedwater Isolation Valve Pit Unit 1.Midland Nuclear Power Plant " Draft confirmatory orders handwritten notes & RF Warnick nemo re FOLA Request B4-24 encl CORLEY.W 0 Construction Technology Laboratories BX20 019 B3/02/28 111pp 26540 178 24X Fiche 50-327.84/07/18, B408010061
- --B408150700 Forwards draft confirmatory order prepared by IE re plan for independent appraisal of site & corporate mgt organizations Requests review prior to meeting LIEBERHAN. S NRC No Detailed Affiliation Given BX20 020 B3/12/30 KEPPLER: MARNICK, HARRISON NRC No Detailed Affiliation Given 10pp 26540 335 24X Fiche 50-329.84/07/18, B408010061
- --8408150706 Advises that 8 Lewis leaving Region III to assume position of Deputy Assistant Chief Hearing Counsel in OELD B Berson replacement Chronological list of reactor holddown bolt encl
  KEPPLER, J & Region 3, Office of Director BX20 022 84/05/14
  Region 3, Office of Director 12pp 26541 263 24X
  Fichs 50-329,84/07/18,8408010061
- --8408150709 Summary of 800523 meeting w/util.8&M. Bechtel & Teledyne in Bethesda, MD re preservice failure of three reactor vessel holddown studs List of attendees.agenda & viewgraph slides encl Sketches for underpinning auxiliary bldg encl HOOD.D B Licensing Branch 3 BX20 023 80/07/07 Licensing Branch 3 82pp 26541 328 24X Fiche 50-329.84/07/18,8408010061
- --8408150710 Assessment rept GA program, performed during Mar & Apr 1981 \* Management Analysis Co BX21 033 81/06/01 400pp 26555 182 24X Fiche 50-329,84/07/18,8408010061
- --8408150712 "Guality Program for Underpinning Activities"
  # Consumers Power Co. 8220 024A 82/04/05 82pp 24542 132
  24X Fiche 50-329.84/07/18.8408010061
- --8408150714 "Independent Assessment of Underpinning 90-bay Rept " KILBER,W E Stone & Webster, Inc 8X21 034 83/04/30 250pp 26556 194 24X Fiche 50-329.84/07/18,8408010061
- --8408130716 "Test Program Status & Rev 12 Test Schedule "
  \* Consumers Power Co 8X21 035 83/04/12 100pp 26557 091
  24X Fiche 50-329,84/07/18,8408010061
- --B40Bi507iB Documents conclusions & commitments made at 920330 meeting & B20402 telcons re GA applied to remedial foundation work Expansion of GA program recognized in overall success of project "Guality Program for Underpinning Activities" encl CODK. JW Consumers Power Co BX20 0248 B2/04/05 KEPPLER, J G Region 3, Office of Director 4pp 26542 154. 24% Fiche 50-329,84/07/18,8408010061

- --8408150720 "Electrical Raceway Support Tests Rept Part 1" NGMAK.A S Bechtel Corp BX21 036 81/11/25 100pp 26557 192 24X Fiche 50-329.84/07/18.8408010061
- --8408150723 Forwards CPC testimony on alleged violation of Board order Investigation of violation coming in future Requests analysis of testimony & comments Handwritten notes encl WILCOVE, M. N. Office of the Executive Legal Director BX20 026 83/05/13 LANDSMAN, R., COOX, R., HOOD, D. NRC No Detailed Affiliation Given 99pp 26542 165 24X Fiche 50-329, 84/07/18, 8408010061
- --8408150725 Requests review of attached draft SALP rept in preparation for 830706 SALP Board meeting WARNICK,R F Region 3. Office of Director BX20 027 83/07/01 HIND. J A. NORELIUS, C E. SPESSARD,R L NRC No Detailed Affiliation Given 149pp 25342 288 24X Fiche 50-327,84/07/18. 8408010061
- --B408150727 Summarates 830227-28 meeting at site re soils settlement issue & effects Handwritten note encl
  GALLAGHER, E. Region 3. Chicago. Diffice of the Director BX20 034
  80/03/03 FIORELLI, G. Region 3. Chicago. Reactor Construction & Engineering Support Branch 46pp 26344 306 24X
  Fiche 50-329.84/97/18.8408010061
- --B40B150728 Forwards advance copy of proposed rev to Manual Chapter 0516.SALP, for review NOREL1US,C E Division of Project & Resident Programs BX20 035 84/04/13 Region 3, Office of Director 2pp 26545 067 24X Fiche 50-329,84/07/18,8408010061
- --B40B150729 Advises of problems concurring w/proposed response to M Cherry 770427 Itr as noted by detailed comments provided Requests redraft be considered REINMUTH.0 H Division of Reactor Construction Inspection BY20 O29 77/06/10 HOEFLING.R K Office of the Executive Legal Director 7pp 26543 234 24X Fiche 50-329.84/07/18.8408010061
- --B40Bi50731 Advises of possible ax parts contact in facility proceeding Requests memo & attached summary of discussion be served to all parties in proceeding & PDR GIBBON.TR NRC No Detailed Affiliation Given Bx20 030 80/12/24 CMILK.B J Office of the Secretary of the Commission 2pp 26543 250 24x Fiche 50~329.84/07/18.8408010064
- --8408150732 Notifies that incorrect target dates entered in 830219
  SALP schedule Correct target dates provided
  NORELIUS.C E Division of Project & Resident Programs BX20 035A
  84/03/08 HIND. J A Division of Radiological & Materials Safety
  Programs SPESSARD.R L Division of Engineering DUUGHERTY.D J
  Office of Resource Management. Director 2pp 26545 117 24X
  Fiche 50-329.84/07/18.8408010061
- ---B40B150734 Revises previously issued SALP 4 schedule dtd B31004 by extending assessment to 18 months Rev Incorporates additional states and atom NORELIUS, C & Division of Project & Resident Programs BX20 035B B3/12/19 Region 3) Office of Director Epp 26545 119 24X Fiche 50-329 84/07/18, 8408010061
- --8408150735 Requests concurrence on proposed auxiliary bldg guideline.
  "Guidelines for Bldg Movements During Temporary
  Underplaning "Handwritter notes & communications record
  w/Warnick re withdrawel of patential (DOCRSO 351e) encl
  MGONEY. J A Consumers Fower Co 8X20 031 84/05/25
  HARRIBON, J J Region 3. Office of Director 25pp 26543 252
  24X Fiche 30-329,84/07/18,8408010061
- -8408150737 Forwards NRC Manual Chapter 0516, BALP Evaluation criteria published in FR on 820322 for public comments Comments due by 820701
  TAMBLING, T N Region 3, Office of Director 8220 0350 82/05/04
  AXELSON, N L , BARRETY, P A , BOYD, D C NRC No Datailed Affiliation Given 3pp 26545 123 24% Fiche 50-329,84/07/18, 8408010061
- 340815073B Forwards summary of 840227 meeting in Region III ofc re results of HVAC insps. & investigation of allegations & expansion of training, qualification & certification activities Handwritten notes enci NELLB,R A Consumers Power Co BX20 032 84/03/27 HARRISON,J J Region 3, Office of Director 169pp 26544 014 24X Fiche 50-327,84/07/18,8408010061
- iOB150740 "Chapter O516 BALP," describing basis structure & overall procedures for implementation of NRC program to assess litebrse performance MA Miller marked-up memo re evaluation of BALP encl \* Director's Office, Office of Inspection and Enforcement BX20 O350 B2/03/23 47ρρ 26545 126 24X Fichs 50-327,84/07/18,8408010061

- --B408150741 Forwards "Structural Evaluation of Diesel Conerator Bldg Assessment of Structural Performance Capability & Serviceability as Potentially Affected by Settlement Induced Cracking " LEVIN.H A TERA Corp DX20 033 83/01/04 KEPPLER.J G , EISENHUT.D G Region 3, Office of Director COCK,JW Consumers Power Co 4pp 26944 212 24X Fiche 50-329,84/07/18.8408010061
- --B408150743 Submits reasons for extending SALP 111 evaluation period to 821231 Rept contains issues being resolved between NRC & licensee Extension can be used as performance motivator Handwritten note & supporting documentation encl CODA, R. J. Region 3, Office of Director BX20 036 B2/08/06 SPESSARD, R. L. Division of Project & Resident Programs 350pp 26545 173 24X Fiche 50~329.84/07/18.8408010061
- --8408150745 "Structural Evaluation of Diesel Generator Bldg Assessment of Structural Performance Capability & Serviceability as Potentially Affected by Settlement Induced Cracking "Handwritten notes enc! 4 TERA Corp 8X20 033A 83/01/04 89pp 26544 216 24X Fiche 50-327,84/07/18,8408010061
- --8408150747 Submits supplemental SALP input for facility Changes required to provide overall Div of Engineering & Technical Insp rating for GA functional area & consolidate comments for recommended increased insp frequency PIRTLE.G Region 3. Office of Director 8X20 037 83/10/01 B0VO.D Region 3. Office of Director 19 26547 011 24X Fichs 50-329.84/07/18,8408010061
- --8408150749 Forwards list of items reviewed by util & determined ready for review & closure by NRC Handwritten notes & supporting documentation encl WELLS.R A Consumers Power Co BX20 038A 83/10/04 KEPPLER.J G Region 3. Office of Director 147pp 26547 165 24X Fiche 50-329.84/07/18.8408010061
- --8400150750 Forwards SALP input except for Matls & Processes Section PIRTLE.G Division of Engineering & Technical Inspection 8x20 O38 81/09/22 80YD,D Division of Engineering & Technical Inspection 137pp 26847 O12 24X Fiche 50-329,84/07/18,8408010061
- --8408150791 Forwards const status rept as of 791001 Handwritten note; redisesel generator bldg & soil settlement & errata to NUREG-0834 encl FIRELLI.O Region 3, Chicago, Reactor Construction & Engineering Eupport Branch BX20 041A 79710705 KNOP,R C , HAYES,D W , DANIELSON,D H NRC No Detailed Affiliation Given 107pp 26548 359 24X Fiche 50-329.84/07/18.8408010061
- --B408150752 Bubmits GA issues to be addressed at evidentiary session in facility proceeding Summary rept & oral communications record re reinsp requirements based on results of certification testing encl
  PATON, W D NRC No Detailed Affiliation Given BX20 041
  B2/08/10 ADENSAM, E G NRC No Detailed Affiliation Given
  18pp 26548 075 24X Fiche 50~329,84/07/18,8408010061
- --B408170081 "Response to NRC Staff Review Concerns for Undersinning of Auxiliary Bldg" # Consumers Fower Co BX19 001 B2/06/03 40pp 26529 122 24X Fiche 50-329, 84/07/18, 8408010061
- --840B170102 Forwards add1 documents re facility soils issue, in response to request for info DREMOBL.N E Consumers Power Co BX19 003 82/04/12 FISCHER.D C ACRS Advisory Committee on Reactor Safeguards 7pp 26530 009 24X Fiche 50-329,84/07/18,840B010061
- --8408170141 Requests review of files to determine documents withholdable under FOIA.per FOIA-84-96
  LEMIB.S H NRC No Detailed Affiliation Given 8x19 009
  B4/05/0B HARRISON, J J, GARDNER.R , LANDEMAN,R NRC No
  Detailed Affiliation Given 1p 26530 066 24X
  Fiche 50-329,84/07/18,8408010061
- --B40B170145 Forwards draft ltr to util re review of licensee B30310.0624 & 0712 responses to B30208 & 0523 notice of violation & proposed imposition of civil penalty Recommends imposition of \$120.000 civil penalty BCHULTZ.W H Region 3. Office of Director BX19 010 B3/07/28 AXELRAD.J A Director's Office. Office of Inspection and Enforcement 165pp 26530 067 24X Fiche B0-329,84/07/18, B408010061
- --B40Bi70166 Testimony of RN Oardner re allegations concerning qualification of personnel employed by Camstock GARDNER, RN Region 3. Office of Director BX19 012A 84/07/18 100pp 26530 321 24X Fiche 50-329,84/07/18,8408010061

- --B40B170187 Forwards rept results re special electrical overinsp requested by NRC to support testimony concerning adequacy of certification/qualification process of Bechtel electrical QC inspectors
  - Inspectors
    SHAEFFER'M J Consumers Power Co 8x19 015 82/02/25 COOKE,R
    NRC No Detailed Affiliation Given BIRD,W R, COOK,J W
    Consumers Power Co 14pp 26531 048 24X Fiche 50-329,84/07/18,8408010061
- --8409170195 Draft "Rept on Cable Installation" + Consumers Power Co BX19 014 92/05/14 111pp 26531 038 24X Fiche 50-329,84/07/18,8408010061
- --8403170253 Discusses W Marshal telton re permanent dewatering well being drilled at northeast corner of diesel generator bidg on 820319 Drilling mud flushed into line when drilling line broke No further comment necessary LANDSMAN.R B Region 3. Office of Director BX19 031 82/04/14 PATON.W Office of the Executive Legal Director 2pp 26533 325 24X Fiche 50-329,84/07/18,8408010061
- --B408170257 Summary of ACRS Subcommittee on Midland Units 1 & 2 820520 & 21 meetings w/util in Midland M1 re review of DL application FISCHER, D ACRS Advisory Committee on Reactor Bafeguards BX19 O32 82/08/07 DKRENT, D ACRS Advisory Committee on Reactor Safeguards 13pp 26533 359 24X Fiche 50-329,84/07/18,8408010061
- --B40B170260 Informs of review of encl allegations re Comstock QC at site Ofc of Investigations responsible for continuing investigation WARNICK, F F Region 3, Office of Director BX19 033 82/11/16 FISTER, J E Office of Investigation 125pp 26534 010 24X Fiche 50-329, 84/07/18, 840B010061
- --8408170279 "Structural Stresses Induced by Differential Settlement of Diesel Generator Bldg "

  \* Consumers Power Co BX19 037 84/07/18 51pp 26535 255 24X Fiche 50-329,84/07/18,8408010061
- --8408170284 Summary of 810802-04 meeting w/util & Bechtel in Bethesda.MD re remedial actions & update of soils deficiencies & to review Amend 85 to application LANDSMAN.R B Region 3. Office of Director DX19 039 81/05/12 WILLIAMS.C C Region 3. Office of Director 65pp 26536 043 24X Fiche 50-329.84/07/18.8408010061
- --8408170320 Summary of 840202-05 meeting w/util.Bechtel & consultants in Ann Arbor.MI re discussion & audit of preparations for underpinning southern part of auxiliary bldg Viewgraphs encl HODD, D Licensing Branch 4 BX19 045 84/02/22 Licensing Branch 4 81pp 26536 189 24X Fiche 50-327.84/07/18.8408010061
- ~-8408170358 S&W 840209 public meeting re cracking criteria & cracking mapping program \* Consumers Power Co 8X19 046 84/02/09 Consumers Power Co 2pp 26536 347 24X Fiche 50-329,84/07/18.8408010061
- --8408170360 Submits list of documents supplied or withheld by JJ Harrison & RO Landsman, in response to FOIA Request 84-24 WARNICK, R F Region 3, Office of Director 8X19 047 84/01/18 BMITH, P T Region 3, Office of Director 2pp 26836 351 24X Fiche 50-329,84/07/18,8408010061
- --B408170365 Handwritten summary of B40104 public meeting w/util, S&W Bechtol re monthly activities, crack rept, crack mapping & open items Supporting documentation & attendance list encl & Consumers Power Co BX19 04B 84/01/13 Consumers Power Co 74pp 26534 356 24X Fiche 50-329,84/07/18,8408010061
- --8408170367 Crack mapping monitoring status rept for 831031-1130, including handwritten status rept of 831208 S&W meeting & info re grillage acceptance criteria & Consumers Power Co 8X19 047 84/08/01 10pp 26537 107 24X Fiche 50-329,84/07/18,8408010061
- --8408170372 Handuritten summary of 831110 public meeting Re tracking open 1tems of new crack monitoring procedures 831007-1105
  \* Consumers Power Co 8X19 050 83/11/10 Consumers Power Co
  3pp 26537 129 24X Fiche 50-329,84/07/18:8408010061
- --8408170377 Handuritten notes re auxiliary bldg & underpinning design including settlement stress, results of areas of max stress & rigid body rotation # Consumers Pauer Co BX19 053 84/08/01 76pp 26537 253 24X Fiche 50-329, 84/07/18, 8408010061

- --8408210367 Agenda for 780502 site visit w/util Bechtel & NUS Agenda for 781204 meeting w/util & Bechtel on site encl

  \* NRC No Detailed Affiliation Given BX18 COI 78/05/02 NRC No Detailed Affiliation Given App 26521 049 24X Fiche 50-329, 84/07/18, 8408010061
- --8408210377 Notification of 780907 meeting w/Midland Technical Reviewers in Hashington, DC to discuss project status of facility safety review Reviewers will be asked to summarize roview status on problem areas affecting review schedule HOOD, D Light Water Reactors Branch 4 BXIB 003 78/09/06 NRC No Detailed Affiliation Given 7pp 26321 071 24X Fiche 50-329, 84/07/18,8408010061
- --8408210379 Provides info in response to B Oarde FDIAs 83-451,-452,-454 & -449 HOUO: D Licensing Branch 4 8X18 023 83/08/19 WILSON,V NRC - No Detailed Affiliation Given 2pp 26524 336 24X Fichs 50-329,84/07/18,8408010061
- --B408210384 Notification of rescheduled 790718 meeting w/uti) & Berhtel in Bethesda.MD to discuss abnormal settlement of Fill & structures at site Agenda & attendance list encl HDDD.D Light Water Reactors Branch 4 8X18 004 79/06/13 VAROA.S A Light Water Reactors Branch 4 7pp 26521 100 24X Fiche 50-329.84/07/18.8408010061
- --B408210386 Forwards B Carde FOIA request for documents re meetings between NRC. TERA & util on 830518.0608 & 23 concerning independent design verification W/draft ltr to util re implementation of Ford Amend WILSDN.V H Hangement Analysis Branch 8X18 024 83/08/09 Management Analysis Branch 2p 26524 338 24X Fiche 50-329.84/07/18.8408010061
- --8408210392 Forwards B Garde FOIA 63-452 request for documents to 830615 Commission briefing WILEON,V H Management Analysis Branch BX18 025 83/08/07 Management Analysis Branch 2pp 26524 354 24X Fiche 50-329,84/07/18,8408010061
- --B408210397 Forwards B Carde FDIA 83-454 request for documents re re-review of structural adequacy of diesel generator bldg WILBON,V H Management Analysis Branch BX18 026 B3/08/10 LEAR,O Hydrologic & Geotechnical Engineering Branch BOSNAK,R Mechanical Engineering Branch 2pp 26524 358 24X Ficho 50-329,84/07/18,8408010065
- --B40B210401 Forwards B Oardw FOIA Request 83-449 for documents submitted by util re consideration of candidate companies or methodologies to perform const implementation overview of const completion plan WILSUN,V H Management Analysis Branch BX19 027 84/08/09 Management Analysis Branch 2pp 26525 001 24X Fiche 50-329,84/07/18,8408010061
- ~-8408210404 Determines that info transmitted by 830721 memo should be issued as Board Notification 83-106
  EISENHUT, D & Division of Licensing BX18 028 84/07/18
  NOVAK, T Assistant Director for Licensing 10 26925 192 24X
  Fichs 50-329,84/07/18.8408010061
- --8408210410 Board Notification 83-016 forwards notice of violation & proposed imposition of civil penalties, based on util failure to implement adequate GA program for installation of electrical, mechanical & civil components
  NOVAK.TM Division of Licensing BXIB 029 84/02/15 Atomic Safety and Licensing Board Panel 1p 26525 160 24X
  Fiche 50-329,84/07/18,8408010061
- --8408210411 Handwritten questions for RB Peck re consultant responsibilities & settlement monitoring Handwritten deposition of RB Beck encl
  \* NRC No Detailed Affiliation Given BX18 008 81/01/31 NRC No Detailed Affiliation Given 36pp 26521 228 24X Fiche 80-329.84/07/18.8408010061
- --8408210414 Forwards Board Notification 83-16 which supersedes 830215 notification. NDVAK, TM NRC - No Detailed Affiliation Olven EX18 030 84702/18 Atomic Safety and Licensing Board Panel 1p 26525,184 24X Fishe 50-329,84/07/18,8408010061
- --8408210418 Submits package received from 8 Jones from H Bingh, consisting of questions of Dr Peck by H Singh, J Dunnicliff 800208 ltr to 8 Afifi & summary of J Kane deposition SINGH, H NRC No Detailed Affiliation Given DX18 009 84/07/18 JONES, B NRC No Detailed Affiliation Given Japp 24521 267 24X Fiche 50-329,84/07/18,8408010061

- --8408210421 "Questions for Davisson Bi0114-15 Deposition" Questions of Br Peck on testimony.dtd Bi0725 encl \* NRC - No Detailed Affiliation Given BX18 010 81/01/11 34pp 26521 305 24X Fiche 50-329,84/07/18.8408010061
- --8408210425 "Questions for Davisson 810114-15 Deposition" # NRC - No Detailed Affiliation Given 8X18 011 81/01/11 43pp 26522 070 24X Fiche 50-329,84/07/18,8408010061
- --8408210430 Draft memo informing of status of NRC-03-79-16T.Task 1. Bubtask 3 Index of Davisson deposition encl BINOH, H NRC - No Dotailed Affiliation Given BX18 012 B0/10/16 LEAR.G Hydrologic & Geotechnical Engineering Branch 17pp 26522-116 24X Fiche 50-329,84/07/18.8408010061
- --8408210433 Recommends issuance of encl matl as Board Notification 84-083 re update on stop work status & NRC staffing changes Related infe encl EISENHUT.D @ Division of Licensing BX18-016-84/04/18 NOVAK.T Division of Licensing 2pp 26522-350-24X Fiche 50-329,84/07/18.8408010061
- --B408210446 Summary of 820202-05 meeting w/util & Bechtel in Ann Arbor.
  MI re audit preparations for underpinning southern portion
  of auxiliary bldg Bechtel meeting notes & viewgraphs encl
  HUCD, D Licensing Branch 4 BXIB 019 B4/02/22 Licensing
  Branch 4 79pp 26523 232 24X Fiche 50-329.84/07/18.8408010061
- --8408210450 Determines that enci rept on review of diesel generator bldg should be issued as Board Notification B3-145 EISENHUT, B @ Division of Licensing 8XIB 020 83/10/28 NOVAK, T Assistant Director for Licensing. 4pp 26524 302 24X Fiche 50-329,84/07/18,8408010041
- --8408210453 "Observed Settlements (Inches) of Structures, 790930 to Present "Summary of soil properties & summary of soils info encl MANZEC,T NRC - No Detailed Affiliation Given BX18 037 80/08/27 10pp 26527 199 24X Fiche 50-329, 84/07/18, 8408010061
- --8408210453 Agenda for B00930 meeting w/util on site for appeal of NRC position

  \* NRC No Detailed Affiliation Given BX18 038 84/07/18 NRC No Detailed Affiliation Olven ip 26527 209 24X Fithe 50-329, 84/07/18, 8408010061
- --8408210461 Trip rept of 831005-07 site visit re design review & audit of NVAC sys
  TERAO, D. Mechanical Engineering Branch BX18 052 83/10/28
  BUSNAK, R. J. Mechanical Engineering Branch 17pp 26528 234 24X
  Fiche 50-329, 84/07/18, 8488010061
- --8408210463 Draft notes recommending that listed actions be considered by Region III in effort to improve licensee regulatory attitude & performance & increase assurance that completed & angoing const work acceptable wider of the NRC No Detailed Affiliation Given 8X18 046 82/09/06 4pp 26528 034 24X Fiche 50-329.84/07/18.8408010061.
- --B408220070 Delineates Control Sys Branch position on identification of protection sys instrument sensing lines & requests position be transmitted to mear-term OL applicants SPEIS.TP. Assistant Director for Reactor Safety BX19 025 B4/07/18 TEDESCO.R L Assistant Director for Licensing Spp 26033 051 24X Fichb 50~329,84/07/18.8408010061
- --8408220085 Attendance list of 820223 meeting w/util.chronological list events before & after issuance of NRC order modifying CPs, plant underpinning questions re svc water pump structure & review of 1981 technical rept on underpinning \* NRC No Detailed Affiliation Given 8X19 036A 82/02/23 38pp 26534 327. 24X Fiche 30-329,84/07/18.8408010061
- --8408220070 "Observed Cracks in Walls of Hidland Plant Structures"
  CORLEY.W O , FIORATO.A E Portland Cement Association 8X19 031A
  82/06/14 32pp. 26533 327 24X Fiche 50-329,84/07/18,
  8408010061
- -8408270315 Draft ltr informing of decision re add1 sail borings & testing NRC request for sampling & testing coaling pond enhankments reconsidered & relocation of certain borings determined VOLLMER.R H. Division of Engineering 8X18 010A 80/11/03 COOK.J W Consumers Power Co ip 26522 022 24X Fichs 30-329,84/07/18.8408010041
- -B408270323 Submits listed items that inspectors consider to be indicative of questionable licensee performance COOK:R J Region 3: Office of Director BX19 019 82/07/23 HARNICK:R F Region 3: Office of Director. 11pp 26531\*291 2Fiche 50-329,84/07/18,8408010061.

- 840B140311 Summary of 810917 meeting w/CPC re preliminary design of mods to svc water pump structure to resolve concerns resulting from inadequate compaction of site fill KANE. J NRC No Detailed Affiliation Given BX16 043 81/10/30 NRC No Detailed Affiliation Given 2pp 26511 339 24X Fiche SD-329.84/07/18.840B060006
- B408020014 Advises that util Board of Directors ordered shutdown of design const & testing activities for facilities on B40716 CP & Di applications for both units will be maintained Issuance of SBER 4 (NUREG-0793) requested COOK, J W Consumers Power Co 84/07/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 25883 116 24% Fiche 50-329,84/07/27.8408020014
- 8408080288 Summary of 840712 meeting w/B&W Owners Group re non-nuclear instrumentation sys status Attendance list & viewgraphs encl KADAMBI,P Operating Reactors Branch 4 84/07/27 Operating Reactors Branch 4 36pp 25978 228 24% Fiche 50-000.84/07/27, 8498080288
- 8408070173 Responds to 840726 request for authorization to complete soils shutdown activities Util authorized to proceed w/activities listed in 840726 ltr
  HARRISONJ J Region 3, Office of Director 84/07/31 MOONEY, J, Consumers Power Co 2pp 25747 343 24% Fiche 50-329, 84/07/31, 8408070173
- --8408070180 Requests authorization to complete proposed listed soits shutdown activities Updates of stop work activities will be gravided to Region III HOUNEY. J A Consumers Power CD 84/07/26 HARRISON, J J Region 3, Office of Director. 4pp 23949 345 24X Fiche 50-329, 84/07/31.8408070173
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0903, "Prioritization of Generic Safety Issues " Svc list encl EISENHUT, D © Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000,84/08/06,8408070110
- 8408130399 Finalizes limits for control of movements of control tower & electrical penetration areas during soils shutdown activities, based on review of latest settlement data obtained during 840801-03 site visit List of limits encl HARRISON, J J Region 3, Office of Director 84/08/08 MOONEY, J & Consumers Power Co 3pp 26010 185 24x Fiche 50-329, 84/08/08, 8408130399
- 840B200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions SVc 15st encl EISEMHUT, D 0 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000,84/08/20.8408200275
- 8408270239 Confirms 840824 meeting w/util in Olenn Ellyn, IL to discuss plans for facilities
  WARNICK, R F Region 3, Office of Director 84/08/22 CODK, J W
  Consumers Power Co ip 26239 156 24X Fiche 50-329,84/08/22,
  8408270239
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 8408010061 Further response to FDIA request for 16 categories of records re facility Documents Identified by J Goold & M Biobert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing FELTON.J M Division of Rules and Records BX14 000 84/07/18 RICE.C M Kirkland & Ellis 2pp 26500 001 24X Fiche: 50-329.84/07/18.8408010061
- --B207230536 Forwards discussion of deficiencies noted in Supplemental SER 2 Requests mod to attached draft be provided addressing concerns
  MDVAK, T M Assistant Director for Licensing BX18 040 B2/08/27 KNICHT J P Assistant Director for Comp & Structures Engineering (Pre B30201) 3pp 26527 243 24X Fiche 50-327,84/07/18.
- --B40B150612 Draft final SBER re geotechnical engineering Related info encl KANE.J D Hydrologic & Geotechnical Engineering Branch BX21 010 B2/08/12 78pp 26553 002 24X Fiche 50-329,84/07/18. 8408010061

- ---840B210454 Submits marked-up ltr re program for plant soils remedial work in response to draft SER open items
  COOX, J W Consumers Power Co BX18 047 82/09/07 DENTON, H R
  Office of Nuclear Reactor Regulation, Director 47pp 24528 039
  24X Fiche 50-329,84/07/18.8408010061
- 8408020014 Advises that util Board of Directors ordered shutdown of design const & testing activities for facilities on 840716 CP & OL applications for both units will be maintained Issuance of SSER 4 (NUREG-0793) requested CDOK.J W Consumers Power Co 84/07/27 DENTON.H R Office of Nuclear Reactor Regulation, Birector 4pp 25883 116 24x Fiche 50-329.84/07/27.8408020014

### F Sacurity, medical, emergency & fire protection plans

- 8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Ocold & M Biebert on 840914 & 13 (App B) Forwarded App A documents already forwarded Index forthcoming Search continuing FEL30N, J M Division of Rules and Records BX14 000 84/07/18 RICE.C M Kirkland & Ellis 2pp 26500 001 24% Fiche 50-329,84/07/18,8408010061
- --B40817026B Discusses 830922 off-the-record meeting w/Bechtel employee re allegations concerning inadequacy of plant fire detection says Concerns raised re copyright laws concerning App R to 100FR30 BURGESS.B L Region 3, Office of Director BX19 034 B3/09/26 ROY, G W Region 3, Office of Director 39pp 26534 244 24X Fichs 50-329, 84/07/18,8408010061

#### G Adjudicatory correspondence

- B40B010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Goold & M Simbert on B40014 & 19 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing FELTON.J. M Division of Rules and Records BX14 000 B4/07/18 RICE.C M Kirkland & Ellis 2pp 26500 001 24X Fiche 50-327.84/07/18.8408010061
- ~-8010140005 Submits questions in response to request for interrogatory input re hearing LEAR.O E Hydrologic & Geotechnical Engineering Branch BX17 013 80/10/06 MTRAGLIA.F Licensing Branch 3 2pp 26518 144 24X Ficha 50-329,84/07/18.8408010061
- --8104230479 Submits comments on applicant response to NRC Interrogatories 1-3 No results available for review of Interrogatories 1 & 2 since no consolidation tests on amples were obtained from surcharged area of plant fill MCCALLISTER.P Army, Dept of Corps of Engineers 8X17 OI4 81/03/27 LEAR,O Hydrologic & Geotechnical Engineering Branch 2pp 26518 150 24X Fiche 50-327,84/07/18,8408010061
- --B210270126 Forwards input for testimony for B21027-1104 ASLB hearings Stamiris Contention 4 C b re dewatering & svc water pump structure should be addressed by Structural Engineering Branch
  LEAR, 9 Hydrologic & Osotechnical Engineering Branch. BX17 018
  B2/10/15 ADENBAM, E Licensing Branch 4 4pp 26519 005 24X
  Fiche: 30-329, 84/07/18, 8408010061
- --B211030222 Forwards Hydrdological & Qeotechnical Engineering Branch input for testimony at ASLB B21027-1104 hearings re bearing capacity beneath diesel generator bldg, plping svc water pump structure & permanent dewatering LEAR, G. Hydrologic & Geotechnical Engineering Branch BX17 017 B2/10/14 ADENSAM, E O Licensing Branch 4 9pp 26518 358 24: Fiche. 50-329, 84/07/18, 8408010061
- --B301190487 Assigns NRC sponsors for each of M Binclair rewritten contentions for OL hearing Schedule for filing of testimony forthcoming HOOD, D S Licensing Branch 4 BX17 024 B3/01/14 NOVAK, T M Assistant Director for Licensing 1p 26519.072 24X Fiche 50-329,84/07/18,8408010061
- --8309270346 Responds to 830523 & 0810 requests for assistance in reviewing util proposed findings of fact & conclusions of law on remedial soils issues Agrees w/findings. Recommends paragraph re occurence of liquefaction be revised BALLARD, R L Environmental & Hydrologic Engineering Branch. BX17 037 83/09/14 PATON, W D Office of the Executive Legal Director 2pp 26520 062 24X Fiche 50-329.84/07/18,8408010061
- --B309270518 Forwards comments on util proposed findings of fact & conclusions of law on remedial soils issues
  JACKBON.R E. Geosciences Branch BX17 038 83/09/21 PATON.W D.
  Hearing Branch 2 5pp 26520 064, 24X Fiche 50-329.84/07/18;
  8408010061

- --8310050136 Discusses structural engineering review of "Applicants Proposed Findings of Facts & Conclusions of Law on Remedial Boil Issues" along w/related info on seismic models & barated water storage tanks resulting from ASLB hearings LEAR, G Structural & Geotechnical Engineering Branch BX17 035 B3/09/22 PATON,N Office of the Executive Legal Director Sp. 26520 031 24X Fiche 50-329,84/07/18,8408010061
- --B310070101 Forwards comments on applicant proposed findings of fact & conclusions of law on remedial soil issues
  LEAR.6 Structural & Geotechnical Engineering Branch BX17 035A
  B3707/29 PAYON.W Defice of the Executive Legal Director App
  26520 052 24X Fiche 50-329,84/07/18,8408010061
- --831024029! Informs that structural review of document "Applicant Proposed Findings of Facts & Conclusions of Law on Remedial Soil Issues," completed Structures adoquate Comments encl LEAR, O Structural & Geotechnical Engineering Branch BX17 036 83/10/14 PATON.W Office of the Executive Legal Director Spp 26520 036 24X Fiche 50-329,84/07/18.8408010061
- --840802007i Forwards draft answers to util interrogatories re definition of acceptance criteria of 791206 order on mod Opinion as to whether items in brackets should be deleted requested KANE, J NRC ~ No Detailed Affiliation Given BX17 006 81/02/24 HOCO, D NRC ~ No Detailed Affiliation Given 1p 26515 058 24% Fiche 50-329,84/07/18,8408010061
- --B40B020074 Braft ansuers to util interrogatories re definition of acceptance criteria on Page 3 of 791204 order on mod & NRC No Detailed Affiliation Given BX17 006A B4/07/18 Consumers Power Co B7pp 26515 059 24X Fiche 50~329.84/07/18-8408010061
- --8408020086 Marked-up copy of Rev 1.Vol 4 to F8AR re stability of subsurface matis & foundations.questions re response to Interrogatories 13-16 & interpretations of intent of Interogatory 13 KANE, J NRC - No Detailed Affiliation Given BX17 009 77/11/30 12pp 26517 302 24X Fiche 50-327.84/07/18.8408010061
- --B40B020107 Forwards motions.1980 audit repts & input re upcoming util GA decision Applicant acceptance of poor quality parformance by Bechtel criticized STAMIRIS,B Stamiris, B BX17 011. 81/05/26 KEPPLER.J G Region 3. Office of Director 2pp 26518 132 24X Fiche 50-329.84/07/18.8408010061
- --8408020127 Summary of NRC recommendations of ASLB position re Stamiris Contention 2 including draft ASLB proposed findings & input into NRC testimony re Peck 790810 Statement on electrical penetration area structures NAME, J NRC - No Detailed Affiliation Given BX17 016 81/10/19 91pp 26518 268 24X Fichm 50-329,84/07/18.8408010061
- --8408020171 Summarizes issues to be covered at ASLB 830214-18 hearing, including Stamiris contentions. Harren contention & seismic shakedown for all structures other than diesel generator bldg # NRC No Detailed Affiliation Given. 8X17 019 83/01/05 9pp 26519 009 24X Fithe SO-327.84/07/18.8408010061
- --8408020177 Suggests schedule for testimony to answer Harren Contentions 1-3.8tamin's Contention 4.8inclair Contention 24 & Marhsall Contention 2 in Feb & Mar hearings. Text of contentions encl Buggests Inclusion of rebuttals to contentions BLUME.M NRC No Detailed Affiliation Given BX17 020 BZ/01/27 HQCD,D , KANE,J , RINALDI,F NRC No Detailed Affiliation Given BX18 B408010061
- --B408020180 Forwards input to staff testimony in preparation for ASLB B21115-Q3 hearings.in response to W Paton verbal request & M Wilcove request Structural Engineering Branch input applicable only to svc water pump structure BCHAUER.F.P. Structural Engineering Branch BX17 022 B2/10/22 ADENSAM.E G Licensing Branch 4 Jpp. 24519 050 24X Fiche 50-329.84/07/18,8408010041
- --8408020181 Comments on applicant 840805 proposed findings of fact conclusions of law on remedial soils issues, including items re auxiliary bldg & svc water pump structure PDULOB, S J Gaotechnical Engineers, Inc 8X17 031. 83/09/23 KANE, J Division of Engineering 4pp 26519 242 24X Fiche 50-329,84/07/18,8408010061
- --B408020182 Responds to M Wilcove verbal request Structural Engineering Branch area of concern identified by Judge Harbour applies only to consideration of structure-to-structure interaction Outstanding contentions encl
  BCHAUER,F.P Structural Engineering Branch BX17 023 82/10/28
  ADENBAM,E.O Licensing Branch 4 7pp 26519 055 24X
  Fiche 50-329,84/07/18.8408010061

- --8408020183 Forwards response to applicant proposed findings of fact & conclusions of law on remedial soil issues Pagination needed Findings will be filed 831115
  PATUN.W D Hearing Branch 2 BX17 033 83/11/11 KANE, J NRC -- No Detailed Affiliation Given ip 26519 315 24X
  Fiche 50-329,84/07/18,8408010061
- --B408020184 Forwards marked-up input to staff testimony in preparation for ASLB 821027-1104 hearings re bearing capacity & underground piping, in response to verbal request of W Paton & M Wilcove Response to Stamin's contention encl LEAR.6 E Hydrologic & Geotechnical Engineering Branch 8X17 023A 62/10/14 ADEMSAM.6 C Licensing Branch 4 10pp 26519 062 24X Fiche 50-329.84/07/18.8408010061
- ---8408020185 Responsive findings to applicant proposed findings of fact & conclusions of law on remedial soil issues PATON.W D. WILCOVE.M N Hearing Branch 2 DX17 034 83/11/15 100pp 26517 316 24X Fiche 50-329,84/07/18.8408010061
- --8408020186 Response to R Landsman 830106 questions re B Stamiris Request 4(b) re excavation of deep "G" duct bans in Freezewall Pit 4 & Tech Spec for static core penetrometer KANE. J NRC - No Detailed Affiliation Given BX17 026 83/01/06 2pp 26519 146 24X Fiche 50-329.84/07/18.8408010061
- --B408020187 Forwards updated version of Stamiris contentions, including add1 Stamiris examples for Contentions 1,2 & 3 & thanged wording of Contention 4C NRC testimony must address encl additions & changes
  BROWN,E M NRC No Detailed Affiliation Given BX17 025
  BI/O5/19 Consumers Power Co 19pp 26519 124 24X
  Fiche 50-329, B4/07/18, B408010061
- --8408020189 Forwards applicant testimony re alleged violation of ASLB 820430 order for determination of cross-examination List of questions re excavations & fireline piping provided WILCOVE, M N Hearing Branch 2 BX17 042 B3/05/13 LANDSMAN,R, COOK,R, HOOD,D NRC No Detailed Affiliation Given 2pp 24520 114 24X Fiche 50-329,84/07/18,8408010061
- ---8408020202 Discusses status of efforts re NRC Midland findings due 831115 Requests meeting at earliest date HODD.D NRC - No Detailed Affillation Given BX17 041 83/09/23 PAYON.W D. WILCOVE,M N Hearing Branch 2 7pp 26520 095 24) Fiche 50-329,84/07/18,8408010061
- --8408140102 Forwards complete set of all abstracts of transcripts of hearings conducted on 811231-830630 W/listing of entire set of abstracts HAMPTON.L Isham Lincoln & Deale BX16 012 83/07/18 PATON.W D Hearing Dranch 2 425pp 26508 097 24X Fiche 50-829,84/07/18,8408010061
- --8408140258 Handurittem notes re ASLB actions on 800527 motion to consolidate for discovery, evidentiary presentation & fact finding purposes issues concerning soil canditions for safety-related structures & sys KANE, J NRC No Detailed Affiliation Given 3X16 033 80/06/09 1p 24511 158 24X Fichs 50-329,84/07/18,8408010061
- -B40B140263 Motion to consolidate for discovery, evidentiary presentation & fact finding purposes issues relating to soil conditions for safety-related structures & sys founded in & on plant fill mati in hearing considering 791204 order FARNELL.A S Consumers Power Co BX16 034 80/05/27 Atomic Safety and Licensing Board Panel 15pp 26511 159 24X Fiche 50-329,84/07/18,8408010061
- -B40Bi50702 Advises that Region III has no document re discovery request for info concerning alleged violation of ASLB order concerning remedial soils Handwritten notes, internal memos & list of repts.1977 1783, encl
  HARRISON, J. Region J. Office of Director BX20 021 83/10/25
  WRIONT, N. Diffice of the Executive Legal Director 199pp
  26540 345 24X Fiche 50-329,84/07/18,8408010061
- 8408170223 Requests Commission review Director's Decisions DD-83-16 & DD-84-02 to require all ongoing activity be included under order of mod of GP & remove util from managerial responsibility of GA/GC function GARDE.B P Government Accountability Project BX19 022 84/02/10 PALLADIND.N of CLINKY,V NASSELSTINE.J Commissioners 72pp 26532 090 24X Fiche 50-329,84/07/18.8408010061
  - 108210391 Notice of W Ferris. S Afifi & J Wanteck 801028-29 deposition in Ann Arbor, MI re 791206 order modifying const permits Related info encl PATON. W D. Office of the General Counsel BX18 005 80/10/06 68pp. 26521 126 24X Fiche 50-329, 84/07/18, 8408010061

- --8409210398 Notice of B Dahr 801217 deposition in Ann Arbor,MI re issues set forth in Licensing Board 791206 order modifying const permits t contentions of intervenors Stamiris 5 Warren Resume of TR Thiruvengadam encl # Atomic Safety and Licensing Board Panel BXID 006 80/12/11 topp 24521 199 24X Fiche 50-329.84/07/18.8408010061
- 8407300142 Responds to 840210 petition for specific Commission actions under 10CFR2 206 Petition denied per enc! Director's Decision DB-84-17 DEYBUNG.R C Director's Office Office of Inspection and Enforcement DSB 521 84/07/24 GARDE.B P Government Accountability Project GARDE.B P Lone Tree Council 3pp 25807 232 24X Fichs 50-329,84/07/24,8407300142
- --B407300151 Director's Decision DD-84-17 denying Govt Accountability Project 840210 petation for three Commission actions results work independent third party responsibility for GA & GC & Region [1] staffing DEYQUNG.R C Director's Office Office of Inspection and Enforcement 84/07/24 24pp 25807 235 24x Fiche 30-329,84/07/24,8407300142
- --B407300154 Notice of issuance of Director's Decision DD-84-17, denying Oavt Accountability Project 840210 petition for Commission action DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/07/24 49pp 25807 259 24X Fithe 30-329, 84/07/24, 8407300142
- B40B070377 Forwards NRC response to ASLB inquiry re Board Notification 84-119 oft 840418 which identified specific hearing evidence adversely impacted by discrepancies in original seismic design calculations PATCN.W D Hearing Branch 2 DSB 816 84/08/02 DECHHOEFER.C. HARBOUR.J. COMAN.F P Atomic Safety and Licensing Board Panel 7pp 25947 158 24X Fiche 50-329.84/08/02.8408070377
- B408200373 Order extending time until 841020 for Commission to act to review Director's Decision DD-84-17 Served on 840820 CHILK, B. J. Office of the Secretary of the Commission DSB 154 B4/08/17 PALLADING, N. J., ROBERTS, T. M., ASSELSTINE, J. K. Commissioners ip 26137 051 24X Fiche 50-329,84/08/17, B408200373
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Goold & M Siebert on 840514 & 15 (App 8) forwarded App A documents already forwarded Index forthcoming Search continuing FELTON, J M Division of Rules and Records 8X14 000 84/07/18 RICE, C M Kirkland & Ellis 2pp 26500 001 24X Fichs 50-329,84/07/18 8408010061
- --B408170374 Rev 44 & 47 to FSAR Response to Audit Point 1 & handwritten summaries of S&W B31013 public meeting encl # Consumers Power Co BX19 051 B4708/01 34pp 26537 170 24X Fichs 50-329. B4707/18,8408010061
- O Advisory Committee on Reactor Safeguards reports & correspondence
- B408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Goold & M Sinhert on B40514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing FELTON, J M Division of Rules and Records BX14 000 84/07/18 RICE, C M Kirkland & Ellis 2pp 24500 001 24X Fiche S0-329,84/07/18,8408010061
- --B205240403 Advises that ad hoc ACRS subcommittee recommendations refoundation problems & related remedial actions at facilities acceptable.per 820427 & 0306-08 meetings Discussion of setsmic-related issues tentatively scheduled for 820520-21 FRALEY,R F ACR8 Advisory Committee on Reactor Safeguards DX16 003 B2/05/14 DIRCKS,W J Office of the Executive Director for Operations Ip 26500 027 24X Fiche 50-329,84/07/18,8408010061
- --8206060008 Summarizes 266th ACRS meeting on 820603-05 Subj to satisfactorily completion of const & stafffing & if due regard given to ACRS comments, plant can operate at 5% power w/a undue risk to public Full power recommendation deterred SHEWMON-P ACRS Advisory Committee on Reactor Safeguards SXI4 004 82/05/08 PALLADINO, N Commissioners 6pp 26500 028 24% Fiche 50-329,84/07/18,8408010061
- --8408010132 Forwards TERA Corp 830815 ltr describing four conceptual options for independent quality verification program methodologies. Option i integral part of IDCVP at Midland FISCHER, D ACRS Advisory Committee on Reactor Safeguards 8X14 OO1 83/11/15. ACRS Advisory Committee on Reactor Safeguards 2pp 24500 012 24X Fiche 50-327,84/07/18,8408010061

- --B408010135 Forwards GA/GC project status rept presented at ACRS 274th meeting on B30210
  FISCHER.D C ACRS Advisory Committee on Reactor Safeguards
  BX14 002 B3/G3/O3 ACRS Advisory Committee on Reactor Safeguards 6pp 26500 021 24X Fiche 50-329,84/07/18.
  B408010061
- --8408010143 Forwards summary & conclusion of overall effectiveness portion of Region III rept on design & const problems Lack of aggressive GA attitude & overreliance on AE contribute to GA problems FISCHER.D C ACRS Advisory Committee on Reactor Safeguards BX14 005 B2/12/09 ACRS Advisory Committee on Reactor Safeguards 4pp 26500 034 24X Fiche 50-329.84/07/18, 8408010061
- --B40801D147 Forwards JW Cook B10430 ltr % executive summary re GA program update, per B30215 request SOMMERS, D A Consumers Power Co BX14 006 B3/02/16 FISCHER, D C ACRS Advisory Committee on Reactor Safeguards ip 24500 038 24X Fiche 50-329,84/07/18,8408010061
- --B408010152 Forwards status rept re GA/GC activities at facility to be presented at ACR5 274th meeting on 830210 FISCHER, D C ACR5 Advisory Committee on Reactor Safeguards BX14 00B 83/02/07 ACRS ~ Advisory Committee on Reactor Safeguards 7pp 26500 058 24X Fiche 50-327,84/07/18, B408010061
- --8408010153 Discusses major reduction in safety-related work at Midland ACRS comments to NJ Palladino encl FISCHER.D ACRS - Advisory Committee on Reactor Safeguards BX14 COP 82/12/09 ACRS - Advisory Committee on Reactor Safeguards 3pp 26500 065 24X Fiche 50-327.84/07/18.8408010041
- --8408010163 Forwards cost estimate for once through steam generator overfill protection nod.per request
  DREHOBL.K E Consumers Power Co BX14 012 82/08/17
  FISCHER.D C ACRS Advisory Committee on Reactor Safeguards
  2gp 26500 073 24X Fiche 50-329.84/07/18.8408010061
- --8408010168 Forwards BSER 1, addressing ACRS recommendations contained in B20608 interim rept Operating license review project status repts for B20520-21 & 0602 encl W/o BSER FISCHER, D ACRS Advisory Committee on Reactor Safeguards BX14 O13 82/07/19 OKRENT, D ACRS Advisory Committee on Reactor Safeguards 12pp 26500 075 24X Fiche 50-327,84/07/18
- --8408010173 Discusses util approach for satisfying safety review requirements at Big Rock Point, Palisades & Midland Summary of 820504 meeting & viewgraphs encl FISCHER, D C ACRS Advisory Committee on Reactor Safeguards BX14 Ol4 82/05/17 ACRS Advisory Committee on Reactor Safeguards 45pp 26500 OB7 24X Fiche 50-329, 84/07/18, 840801006
- --B40B010178 Forwards summary of ad hoc Subcommittee on Midland Units 1 & 2 820429 meeting Related info encl F18CHER, D ACRS Advisory Committee on Reactor Safeguards BX14 016 82/05/06 SIEBS, C ACRS Advisory Committee on Reactor Safeguards 32pp 26500 133 24X Fiche 50-327,84/07/18,
- --B408010183 Discusses acceptability of Midland reactor pressure vessel anchor bolts; per util Bill23 ltr & attached rept Expresses concern re rept sufficiency BHEMMON.P O ACRB Advisory Committee on Reactor Safeguards BX14 017 B2/02/03 VOLLMER.R H Division of Engineering ip 26500 173 24X Fichs 50-329,84/07/18.8408010061
- --8408010388 Forwards util 800522 ltr identifying one of many GA problems at facility incident re fill math under vital structures noted in P Tam 800516 ltr incidents should be considered in evaluation of need for subcommittee meeting YOUNO.0 G ACRS Advisory Committee on Reactor Safeguards BX14 O18 80/06/03 SHEMMON.P ACRS Advisory Committee on Reactor Safeguards ip 26500 174 24X Fiche 50-329.84/07/18.8408010061
- --B408010191 Summary of B00523 meeting w/util in Bethesda, MD re reactor vessel holddown stud failures at facility YDUNG, 0 G ACRS Advisory Committee on Reactor Safeguards BX14 O19 80/05/28 SHEMMON, P ACRS Advisory Committee on Reactor Safeguards 3pp 24500 184 24X Fiche 50-327, 84/07/18, 8448010041
- ----B408010195 Recommends review of foundation problems at facility Poor quality fill matl used under containment & other vital structures

  TAM.P. ACRS Advisory Committee on Reactor Safeguards BX14 020

  B0/05/16 SHEWMON.P ACRS Advisory Committee on Reactor Safeguards 1p 24500 187 24X Fiche 50-329.84/07/18.8408010061

- -8408010198 Advises that unresolved safety issue exists in poor quality of fill matl under containment b other vital structures as evidenced by diesel generator blig settlement MCKINLEY, J C ACRS Advisory Committee on Reactor Safeguards BX14 O21 80/05/09 TAM, P ACRS Advisory Committee on Reactor Safeguards 1p 26500 201 24X Fiche 50-327, 84/07/18, 8408010061
- --B40B010202 Forwards portions of FSAR for review of soil/foundation problems Site visit t subcommittee meeting will be arranged MCKINLEY, J C ACRS Advisory Committee on Reactor Safeguards BX14 022 B0/03/21 OSTERBERG, J O Northwestern Univ, Evanston. IL 1p 26500 202 24X Fiche 50-329,84/07/18,8408010061
- --8408010204 Discusses facility safe shutdown boration capability B&W Water Reactors Subcommittee review to explore proposed fixes suggested MULLER, R ACRS Advisory Committee on Reactor Safeguards BX14 Q23 79/11/14 EIHERINGTON.H ACRS Advisory Committee on Reactor Safeguards ip 26500 207 24X Fiche 50-329,84/07/18.
- --B408010204 Summary of 790718 meeting w/util onsite re abnormal settlement of fill & structures Agenda & visugraphs encl ZUMOR.D J ACRS Advisory Committee on Reactor Safeguards 024 79/07/21 ACRS Advisory Committee on Reactor Safeguards 78pp 26500 210 24X Fiche 50-329.84/07/18.8408010061
- G Inspection reports. IE Bullotins & correspondence
- B40B0701B3 Identifies activation completed &/or in progress, in response to IE Bulletin B3-07 re apparently fraudulent matl supplied by Ray Miller, Inc Final rept planned for B40901 CDDKI, JW Consumers Power Co B4/07/11 KEPPLER, J G Region 3, Office of Director App 25950 025 24X Fiche 50-329, 84/07/11, B40B0701B3
- 8408070227 Submits final response to IE Bulletin 83-06 re nonconforming matls supplied by Tube-Line Corp Investigation performed by Bechtel determined three vendors supplied Tube-Line matl All Tube-Line matls removed from log COOK.J W Consumers Power Co 84/07/11 KEPPLER.J C Region 3. Office of Director 3pp 25948 230 24X Fiche 50-329,84/07/11. 8408070227
- 8408030071 Forwards IE Insp Repts 50-329/84-21 & 50-330/84-22 on B40601-30 No moncompliance noted MARNICK.R F Region 3. Office of Director B4/07/12 COOK.J W Consumers Power Co 2pp 25917 315 24X Fiche 50-329.84/07/12. B408030071
- --B408030074 IE Insp Repts 50-327/84-21 & 50-330/84-22 on 840601-30 No noncompliance noted Major areas inspected remedial soil work activities, allegations, turbine roll, status assessment, quality verification programs & progress HARRISON J Region 3. Office of Director B4/07/12 Spp 25917 317 24% Fiche 50-329,84/07/12.8498030071
- B40B010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Goold & M Siebert on B40314 & 15 (App II) forwarded App A documents already forwarded Index forthcoming Search continuing FELTON, J M Division of Rules and Records EX14 000 B4/07/IB RICE.C M Kirkland & Ellis 2pp 26500 001 24X Fiche 50~329.84/07/IB,840B010061
- ---8408020190 IE Investigation Rept 3-82-061 on B30103-0330 No noncompliance noted Major areas investigated allegations that util violated ABLB B20430 order re NRC approval for excavating in remedial soils program Investigation closed WELL, C.H., PAMLICK, E.T. Region 3, Office of Director BX17 028 B3/06/02 17pp 26519 178 24X Fiche 50-329,84/07/18,8408010061
- --8408020194 IE Investigation Rept 3-82-061 on 830711-0808 No noncompliance noted Major areas investigated allegations that util violated ASLB 820430 order re NRC approval for excavating in remedial soils program investigation reopened WEIL.C H. PAMLICK.E T. Region 3. Office of Director WARD.W J. Office of Unvestigation BXT 027 83/09/12 20pp 26519 199 24X Fiche 50-329,84/07/18.8408010061
- --8408020194 Provides Supplemental Dfc of Investigation Rept 3-82-061 re util alleged violation of ASLB order HAYES, B 8 Office of Investigation BX17 030 83/09/12 KEPPLER. J 0 Region 3, Office of Director 3pp 26519 221 24X Fiche 50-329,84/07/18.8408010361

- --8408140039 Draft 1E Insp Repts 50-329/78-20 & 50-330/78-20 from insp on 781211-20 & 790104-25 Violations noted inadequate control & supervision of plant fill math placement & const specs not followed PHILL IP G A
- --8408i40055 Preliminary "Discussion of NGC Insp Facts Resulting From NRC Investigation of Discal Generator Bldg Settlement" " Consumers Power Co. BX16 004 79/03/05 35pp 26507 315 24X Fiche 50-329,84/07/18.8408010061
- --8408140913 Summary of R Landsman 810325-27 & 0407-09 insps conducted to verify GA program for util soil borings conducted in response to Corps of Engineers request for addl soil info \* NRC No Detailed Affiliation Given BX16 054 84/07/18 4pp 26912 299 24X fiche 50-329,84/07/18,8408010061
- --8408150622 Discusses basis for recommendation to extend SALP III evaluation period from 820630 to 821231.per 820719-20 discussions Related info encl COOK J. Region 3. Office of Director BX21 012 82/08/06 GPESBARD, R.L. Division of Project & Resident Programs 13pp. 26553 145 24X Fiche 50-329,84/07/18.8408010061
- --8408180624 Draft summary of NRC 840229 meeting w/util at Region III ofc re results of NRC HVAC insps & investigation of allegations & expansion of GA training, qualification & certification activities Viewgraphs and! & Region 3, Office of Director 8x20 002 84/02/29. Region 3, Office of Director 2ipp 26537 342 24X Fiche 30-329,84/07/18, 8408010064
- --B40Bi50633 Forwards Rev. 4 to "Region III SALP Schedule" Schedule changes to listed facilities explained in remarks sections of schedule Addl handuritten notes atso encl NORELIUS.C E. Region 3. Office of Director 8X20 004 84/06/04 KEPPLER, J. 0. DAVIB.A B., GPEBSARD.R L. Region 3. Office of Director 22pp 26538 025 24X Fiche. 50-327.84/07/18.8408010061
- --8408150639 Discusses Oft of Special Cases special ansp on 821012-1125 & forwards draft notice of violation re-significant breakdown in implementation of QA program Handwritten NRR comments The implementation of the confidence of Director BX20 005 83/01/05 KEPPLER, J Q Region 3, Office of Director BX20 005 83/01/05 CUDX, J W Consumers Power Co 84pp 26538 049 24X Fiths 50-329, 84/07/18, 8408010061
- --B408150640 Ack receipt of 830726 ltr & payment in amount of \$116,500 for rivil penalty imposed by 830829 order AXELRAD. J. A Enforcement Staff BX21 016 83/10/04 SELBY.J D Consumers Power Co. 2pp 26553 305 24X Fiche. 50-329, 84/07/18, 8400-10014
- --8408150644 Forwards payment in amount of \$116.500 in response to 830829 ltr imposing civil penalty for violations found during Insp 83-23 (&A 83-03). Related info encl.including matl on 830811 public meeting COOK.J W Consumera Power Co 822 017 83/09/26 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 29pp 26554 003 24% Fiche 50-329.84/07/18.8408010061
- -8408150669 Corrects Page 3-1 of Attachment 3 to wtil 820517 response to draft SALP rept for Jul 1980 June 1981, clarifying stop work under on drilling COCK, J H Consumera Power Co BX21 024. 82/05/21 KEPPLER, J G Region 3, Diffice of Director Sipp 26554 313 24X Fiche 50-329,84/07/18,8408010061
- -8408150672 Forwards response to draft BALP rept for Jul 1980 June 1981, discussed at 820426 meeting w/NRC CODK.J W Consumers Power Co BX21 025 82/05/17 KEPPLER, J 9 Region 3. Office of Director 38pp 24554 344 24X Fith
- 8408150677 Discusses SALP appraisals for Zimmer & Midland Suggests limited SALP-3 appraisal for Midland to cover remedial soils work, BBU work & HVAC activities MEPPLER, J & Region 3, Office of Director 8X21 026 83/04/18 HIND, J.A Division of Radiological & Materials Safety Programs. 1p. 26555 066 24X Fiche 50-329.84/07/18.8408010061
- 8408150490 Lists reasons why SALF III evaluation period should be extended to 821231, per 820719-20 discussion Related info COOK,R.J. Region 3. Office of Director BX21 029 82/0 SPEBBARD,R L. Division of Project & Resident Programs 24595 112 24X Fiche: 50-329,84/07/18,8408010061 BX21 029 82/08/06

- --8408150732 Forwards summary of 840229 meeting in Region III off re results of HVAC integs & investigation of allegations & expansion of training, qualification & certification activities Handouritten notes encl
  WELLS,R A Consumers Power Co 8220 032 84/03/29
  HARRISON,J J Region 3, Office of Director 169pp 26544 014
  24% Fiche 50-329,84/07/18,8408010061
- --8408150743 Submits reasons for extending SALP III evaluation period to 821231 Rept combains issues being resolved botween NNC & licensee Extension can be used as performance motivator Handwritten note & supporting documentation encl CODK, R J Region 3, Office of Director BX20 036 82/08/06 SPESSARD, R L Division of Project & Resident Programs 350pp 26546 001 24X Fiche 50-329,84/07/(8.8408010061
- --8408150747 Submits supplemental SALP input for facility Changes required to provide overall DIV of Engineering & Technical Inspirating for QA functional area & consolidate comments for recommended increased inspirateurs, PRRYLE, Q Region 3, Office of Director 8x20 037 83/10/01 BQYD.D Region 3, Office of Director 19 26547 011 24X Fiche 50-329,84/07/18,8408010061
- --8408150792 Submits GA issues to be addressed at evidentiary session in facility proceeding Summary rept & oral communications record re reinspreading encl certification testing encl PATON. W D NRC No Detailed Affiliation Given BX20 041 82/091/0 ADENSAM. E G NRC No Detailed Affiliation Given 18pp 24548 075 24X Fiche 50-329,84/07/18,8408010041
- ---840B170119 Confirms that underpinning instrumentation installation will be suspended until procedures & drawings developed & plans & schedules established to inspect & audit activities.per 820317 telon KEPPLER. J G Region 3, Office of Director BX19 007 COOK, J N Consumers Power Co 2pp 26530 037 24X Fiche 50-329,84/07/18,8408010061 82/03/19
- --B408170132 Forwards redrafted insp rept Rept has been reviewed w/NRC for format & content Rept covers insp made 821129-1210 CHARAK.I Argonne National Laboratory BX19 011 92/01/07 WARNICK.R Region 3, Office of Director 7pp 26530 233 24X Fiche 50-329,84/07/18,8408010061
- --B408170197 Forwards draft insp rept re findings of personnel who participated in routine insps on B21127-1203 & 1208-10 CHARAK.I. Argonne National Laboratory BX17 012 B2/12/22 MARNICK.B Region 3. Office of Director 14pp 26530 240 Fiche 50-329,84/07/18,8408010061
- --8408170174 Forwards IE Mgt Meeting Repts 50-329/82-09 & 50-330/82-09 on 820314 NORELIUS, C E Region 3, Office of Director B) CODK, J W Consumers Power Co 2pp 26531 033 Fiche 5D-329,84/07/18,8408010061 8X19 013 82/06/28
- --840Bi701Bi IE Mgt Meeting Repts 50-329/82-09 & 50-330/82-09 on 820514 Major areas discussed licenses disposition of results of electrical overview insps GARDNER, R N. HILLIAMS, C C Region 3, Office of Director EXIP 013A 88/06/24 3pp 26531 035 24X Fiche 50-329,84/07/18, 8408010061
- --840Bi70205 Forwards 1E Insp Repts 50-329/82-07 & 50-330/82-07 on 820421-23 No noncompliance noted Schedule for reinsp program of piping suspension sys requested within 25 days from receipt of itr 2, Office of Director 8x19 017 82/07/15 Consume 2pp 26531 071 24X Fiche 50-329,84/07/18,8408010061
- --B408170232 Forwards SALP Repts 50-329/82-14 & 50-330/82-14 for period Jul 1980 June 1981.

  KEPPLER.J G Region 3, Office of Director BX19 026 84/07/18 CCCK, J W Consumers Power Co 2pp 26533 158 24X Fiche 50-329,84/07/18,8408010061
- --8408170236 Ack receipt of 820114 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/81-12 & 50-330/81-12 NORELIUS.C E Division of Engineering BX19 028 82/02/03 COOK, J W Consumers Power Co 4pp 26333 188 24X Fiche 50-329.84/07/18.8408010061
- --B408170271 Requests Ofc of Investigations provide investigator to assist Ofc of Special Cases in closeout of unresolved item in Insp Rept 327/82-22-27 re use of unofficial documents for recording nonconformances & deficiencies WARNICK, R F NRC No Detailed Affiliation Given BX19 D35 B3/01/27 PAMLIK, E T. Region 3. Office of Director ip 26334 293 24X Fiche 50-329,84/07/18,8408010061

- --B40B170274 Discusses B31021 interview w/A Gautam & unmamed individual re allegations concerning Comstock, Bechtel & Zack const activities at plant Details of issues referred to Ofc of Investigation & Ofc of Inspector & Adultor HAWKINS, F C Region 3, Office of Director BX17 036 B3/10/26 Region 3, Office of Director 1p 26534 276 24X Fiche 50-329,84/07/18,8408010061
- --8408210464 Notifies of 830708 meeting to discuss NRR SALP III assessment based on recent hearing testimony by Region III & several third-party reviewers NBVAX,T M Assistant Director for Licensing BX18 055 83/07/07 JOHNSTON.W, KNIGHT,J P, RUDENSTEIN.L NRC No Detailed Affiliation Given 11pp 26528 262 24X Fiche 50-329,84/07/18,8408010041 64080100A1
- --8408220059 Responds to 830829 ltr re imposition of civil penalty for violations noted during Insp 83-23 Penalty reduced because of prompt corrective actions Check encl COOK.J W Consumers Power Co 8X19 052 83/09/26 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 2pp 26537 208 24X Fiche 50-329.84/07/18.8408010061
- --8408220078 SALP Repts 50-329/82-14 & 50-330/82-14 for Jul 1980 June .. Region 3, Office of Director DX19 027 B2/03/31 28pp 33 160 24X Fiche 50-329,84/07/18,8408010061
- --8408270330 Forwards summary of 840229 meeting w/Region III & util in Region III re results of insps & investigation into allegations re HVAC work WELLS,R A Consumers Power Co 8X19 020 84/03/24 HARRISON,J J Region 3, Office of Director 17pp 26532 023 24X Fiche 50-329,84/07/18,8408010061
- 8407250229 IE Info Notice 84-57. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JGRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000.84/07/27.8407250229
- 8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted effective 840820 Preprinted form will be used institutes.erres...
  rather than Itr
  REPPLER, J G Region 3, Office of Director 84/08/03
  REPPLER, J G Region Co 3pp 25742 188 24X Fiche 50-000,84/08/03,
- 8409230302 Forwards IE Insp Repts 50-329/84-24 & 50-330/84-25 on 840611-15 & 25-29 No noncompliance noted WARNICK.R F Region 3, Office of Director 84/08/03 COOK.J W Consumers Power Co 2pp 26212 264 24X Fiche 50-329.84/08/03.8408230502
- --8408230512 IE Insp Repts 50-329/84-24 & 50-330/84-25 on 840611-15 & 25-29 No noncompliance or deviations noted Major areas inspected licensee action on 10CFR50 35(e) items HARRISON.J J Region 3. Office of Director 84/08/03 8pp 26212 266 24X Fiche 50-329,84/08/03,8408230502
- 840B010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/04 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 138 24X Fiche 30-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JUNDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl list encl GRACE. J N Division of GA. Bafeguards & Inspection Programs (Post 830103) 84/0B/10 Consolidated Edison Co of New York, Inc 125pp. 26130 001 24X Fiche 50-000,84/08/10,8408070376
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping ' By: list encl.

  JORDAN, E L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co. of New
  York, Inc. 119pp 26197 218 24X Fiche 50-000.84/08/13,8408100009

- 6408100038 IE Info Notice 84-64, "HWR HPCI Initiation Seal-In & Indication " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co 03) 84/08/19 Consolidated Edison Co. of New 26198 093 24X Fiche 50-000:84/08/15:8408100038 104pp
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Syc list encl
  - list enc]

    JDRDAN, E L Division of Emergency Preparedness & Engineering

    Response (Post 830103) 84/08/16 Consolidated Edison Co of New

    York, Inc. 118pp 26198 0D1 24X Fiche 50-000,84/08/16,8408100021
- 840B100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055 120pp
- 840B14020B IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/08/17 Consolidated Edison Co of New York, Inc 182pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 8408240136 Forwards Mgt Meeting Repts 50-329/84-18 & 50-330/84-19 on D40/12
  WARNICK, R F Region 3, Office of Director B4/08/20 CODK, J H
  Consumers Power Co 2pp. 26228 205 24X Fiche 50-329,84/08/20,8408240136
- --8408240144 Mgt Hesting Repts 50-329/84-19 & 50-330/84-19 on 840712 Major areas discussed work activities for auxiliary bldg underpinning, status of svc water pump structure & GA/GC Activities
  LANDSMAN,R B . HARRISON, J J Region 3 Office of Director
  B4/08/20 4pp 26228, 207 24% Fichs 50-329, 84/08/20, 8408240136
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc. list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc. 115pp 26329 008 24X Fiche 50-000.84/08/21,8408210142
- R Periodic operating reports & related correspondence
- 8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Goold & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing FELTON, J M Division of Rules and Records BX14 000 84/07/18 RICE, C M Kirkland & Ellis 2pp. 26500 001 24X Fiche 50-329,84/07/18,8408010061 BX14 000 84/07/18
- -8408150603 Forwards Midland monthly status repts for Aug-Bept & Nov 1982 Related info encl. WARNICK:R F Region 3: Office of Director BX21 008 B2/12/20 KEPPLER.J O Region 3: Office of Director 23pp 26551 256 24X Fiche 50-329,84/07/19:8408010061
- --8408150698 Forwards monthly status rept for Dec 1983,containing input from insp site team of Ofc of Special Cases COOK, R. J. Region 3. Office of Director BX21 031 B3/01/12 WARNICK, R. F. Region 3. Office of Director. 2pp 26555 161 24X Fiche: 50-329, 84/07/18, 8408010061.
- 8408240132 Forwards minutes of monthly third party assessment 840712 meeting re status of independent assessment of underpinning & remedial soils work & status of const implementation Averview program & Webster, Inc. 84/08/07. HARRISON, J J. Region 3. Office of Director 43pp. 26226 033 24X Fiche 50-329,84/08/07.8408240132
- --8408240134 Forwards Independent Assessment of Underginning Weekly Rept 91 for 840610-16 Minutes of daily meetings between members of assessment team & site engineering.const & GA personnel LUCKS.A S Stone & Hebster, Inc. 84/06/20 EURGESS, I No Detailed Affiliation Given 15pp 26226:178 24X Fiche 50-329,84/08/07,8408240132. 84/04/20 BURGESS, B L NRC -
- --8408240138 Forwards Independent Assessment of Underpinning Weekly Rept 92 for 840417-0623. Minutes of daily meetings between members of assessment team & site angineering const & GA personnel LUCKS.A S Stone & Webster, Inc. 84/06/27 BURGESS.E L NRC - No Detailed Affiliation Gloven 16p 26226 193 24x Fiche.50-329,84/08/07,8400240192.

- 408240143 Forwards Independent Assessment of Underpanning Weekly Rept 93 for 840624-0630 Manutes of daily meetings between members of assessment team & site engineering.const & QA personnel encl LUCKS, A S Stone & Webster, Inc 84/07/03 BUI No Detailed Affiliation Given 11pp 26226 209 Fiche 50-329,84/08/07.8408240132 BURGESS D L NRC -
- 1408240148 Forwards Const Implementation Overview Weekly Rept 51 for #US240148 Forwards Const Implementation Overview Weetly Rept 31 for 840528-0501 Rept includes summary of activities & open items, nonconformance identification repts & hold points KARR, J. E. Stone & Webster, Inc. 84/06/08 MEPPLER, J. C. Region 3, Office of Director 18pp 26226-292 24X
  Fiche 50-329,84/08/07.8408240132
- 3408240152 Forwards Const Implementation Overview Heeliy Rept 53 for B40611-15 Rept includes summary of activities & open items, nonconformance identification repts & hold points KARR. J E Stone & Webster, Inc B4/06/22 KEPPLER. J G Region 3, Office of Director 18pp 26/28/28 228 24X Fiche 50-329,84/08/07.8408240132
- B40B240159 Forwards Const Implementation Overview Weekly Rept 54 for B40418-22 Rept includes summary of activities & open Items, nonconformance identification repts & hold points KARR.J E Btone & Webster, Inc. 84/07/02 KEPPLER.J G Region 3, Dffice of Director. 18pp. 26226-346 24X Fiche 55-329,84/08/07.8408240132
- Reportable occurrences, LERs & related correspondence
- O601003B Forwards Tracked Action Item 086 re NIR 022 t NIR 023 Obstrong Forwards tracked Action from 1986 Te Min Dea & Kin Dea Requests one reply Clarifying initial findings Current replies provide inaccurate & conflicting info KARR.J E Stone & Mebster, Inc 84/05/22 KEPPLER, J G . HARRISON, J J . BURGESS, B L . NRC - NO Detailed Affiliation Given 2pp 24757 351 24% Fiche 50-329,84/05/22.8406010038
- :05270062 Forwards "Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group 84/05/2: DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 24690 045 24X fiche 50-000.84/05/24.8405270062 84/05/24
- 8405270075 "Investigation of Types AF & AE Piston Skirts" \* Failure Analysis Associates FAAA-84-2-14 84/05/23 24X Fiche 50-000, 84/05/24, 8405290062
- 105290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
- RAY,C L TDI (Transamerica Delaval, Inc.) Owners Group B DENTON,H R Office of Nuclear Reactor Regulation, Director 24692 090 24% Fiche 50-000,84/05/24,8405290179 84/05/24
- 408060405 Forwards repts received by BNML & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts Analysis & Recommendations re Main Propulsion Engines M/V Columbia" and ALIMEIMER. J M Battelle Memorial Institute, Pacific Northwest Laboratories 8406/28 MILLER, M Division of Licensing 158pp 25926 173 24X Fiche 50-000.84/06/28.840806040405
- 408050050 Forwards info addressing open items identified in NRC/BNUL/TDI Diesel Generator Duners Group 840522 meeting RAY.C L TDI (Transanerica Delaval, Inc.) Owners Group 84/07/10 BERLINGER.C Birector's Office, Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50-000,84/07/10,8408060050
- 9310054 Final deficiency rept re concrete embedment design using ear lugs located outside compression zone Initially ported on 921203 Use of shear lugs outside compression ne 1s proper design technique Related correspondence IDV.J W. Consumers Power Co. DSB 986, 84/07/11 KEPPLER, J G gian 3, 0ffice of Director ip 26350 186 24X che 50-329,84/07/11.8408310054
- 408010061 Further response to FOIA request for 16 categories of records refacility Documents identified by J Goold & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing FELTON.J M Division of Rules and Records BX14 000 84/07/18 RIGE.C M Kirtland & Ellis 2pp 26500 001 24X Fichs 50-329,84/07/18.8408010061
- -8ii02&0082 Informs that licensee taking position that IEEE 279 jurisdiction starts u/transmitter Jurisdiction should start at sensing line connection to process piping HENDERSON, J B Reactor Projects Sections (Regions 1 & 3) I 024 8i/10/01 WILLIAMS, C C Plant Systems Section 1p 26533 050 24X Fiche 50-329,84/07/18,8408010061

- -8408010160 Forwards interim 10CFR50 55(e) rept re QA program & mfg deficiencies affecting radiation monitoring equipment supplied by Victoreen, Inc FISCHFR, D ACRS Advisory Committee on Reactor Safeguards BX14 O11 82/51/15 ORRENT, D ACRS Advisory Committee on Reactor Safeguards Ip 26500 072 24X Fiche 50-329,84/07/18,8408010061
- --8408150658 Recommends issuance of board notification for encl potential Part 21 rept from Zack Co (HVAC subcontractor) re accuracy of welder records HARNICK, R F. Region 3. Office of Director BX21 020 B2/09/01 EISENHUT, D 9 Division of Licensing 2pp 26554 179 24x Fiche 50-329, 84/07/18, 8408010061
- -8408130694 PNO-77-035 on 770226.bulge discovered in containment liner plate Caused by water coming through tears in liner plate Addl holes cut in plate to facilitate draining Related info enci WARNICK,R F, ROY,G W, THOMPSON, b Office of Inspection & Enforcement, Office of the Director DX21 030 77/03/01 7pp 26555 154 24X Fiche 50-329,84/07/18,8408010061
- --B408170090 Discusses util S20428 telcon notifying that, while drilling well in G area electric duct bank struck Drawings indicated duct bank elsewhere Investigation continuing SHAFER.W D Region 3. Office of Director BX19 0014 82/04/28 WILLIAMS, G C , LANDSHAH, R B NRC No Detailed Affiliation Given 1p 24529 285 24% Fiche 50-329.84/07/18.8408010061
- --B408170276 Forwards util repts re auxiliary bldg seismic analysis & cracks in borated water storage tank foundation, per util B10121-22 notifications Const deficiency info may aid in NORELIVE CONTINUES CONSTITUTING THE MAY 310 IN resolution of matter
  NORELIVE, C E Division of Engineering BX19 036AB 81/11/24
  ETSENHUT, D G Division of Licensing 10 26333 165 24X
  Fiche 50-329,84/07/18,8408010041
- 8408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addi copies sent to DNHL copies sont to INNL RAY.C L TDI (Transamerica Delaval. Inc.) Owners Group B4 DENTON.H R Office of Nuclear Reactor Regulation, Director 25932 137 24X Fiche 50-000, B4/07/27, B408060102 84/07/27
- --B40B060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Gualification Review " \* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139 24X Fiche 50-000,84/07/27,8408040102
- 8408070284 Forwards table indicating status of 10CFR50 55(e) issues Procedures revised to assure proper handling & reporting of add1 10CFR50 55(e) items COOK, J W Consumers Power Co 84/07/27 KEPPLER, J Q Region 3, Office of Director 4pp 25774 036 24x Fiche 50-327, 84/07/27, 84090784 8408090284
- 8408310237 Final deficiency rept re defective capstan springs in Pacific Scientific mechanical shock arrestors initially reported on B40104 W/o description of investigation & corrective actions Related correspondence COOK, J W Consumers Pauer Co DSB 978 84/07/27 KEPPLER, J G Region J. Office of Director ip 26350 281 24X Fiche 50-329,84/07/27.8408310239
- B40B040324 Forwards "Design Review of Elliott Model 459 Turbotharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets"
  RAY, C L TDI (Transamerica Delaval, Inc.) Owners Group B4/08/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 25727 044 24% Fiche 50-000, B4/08/01, B40B040324
- -9408060387 "Design Revieu of Elliott Model 659 Turbocharger Used an TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets " \* Failure Analysis Associates FAAA-84-6-56 84/07/31 62pp 25927 066 24X Fithe 50-000.84/08/01.808060324
- 8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DERV-16 Diesel Engines" RAY,C L TDI (Transamerica Delaval, Inc.) Owners Group 84/08/10 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 26091 147 24X Fiche 50-000,84/08/10.8408160394
- ~-8408160403 "Design Review of Engine Base & Beating Caps for TDI DSRV-16 Diesel Engines "

  \* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp 86091 149 24X Fiche 50-000,84/08/10,8408160394

jaids SER re TD1 Owners Group program plan SER addresses Adjusted the first Country Group program plan set address address of the first partial program plan set and program plan set and program plan bivision of Licensing 84/08/13 GEORGE. J. B. 71 Delayal, Inc.) Downers Group 1p 26255 194 24X 64/08/13/8408240115

Fety evaluation of TDI Coners Group program plan Based on tion.plan incorporates essential elements needed outstanding concerns re reliability of TDI nuclear svc Detailed Affiliation Given 84/08/13 21pp 24% Fiche 50-000,84/08/13,8498240115

prd\* "Design Review of Eiliott Model 906 Turbocharger SR-48 & DSRV-16 Emergency Diesel Generator prising final GA verified rept Addl copy GHUL, per NRC request (Transamerica Dglaval, Inc.) Owners Group 84/08/14 Jffice of Nuclear Resultan Repulation, Director 2pp 1x Fiche 50-000.84/08/14.8408160395

r sign Review of Elliott Hodel 900 Turbocharger Used on DSRV-16 Emergency Diesel Generator Sets " analysis Associates FAAA-84-57-7 B4/07/31 6ipp 24X Fiche 50-000,84/08/14.8408160395

rds response to 840723 request for addl info on repts DI Diesel Generator Owners Group (Transamerica Delaval, Inc.) Owners Group 84/08/23 Office of Nuclear Reactor Regulation, Director 12pp X Fiche 30-000.84/08/23,8408270179

## cripts on non-antitrust matters

er response to FOIA request for 16 categories of 11ty Documents identified by J Goold & 40314 & 15 (App B) forwarded App A documents ded Inder forthcoming Search continuing 1 vision of Rules and Records 8X14 000 84/07/18 tand & Ellis 2pp 26500 001 24X 4/07/18 8408010061

timony of DS Hood & J Kane re matl false statement n NRC 791206 mod order nNC - No Detailed Affiliation Given BXI7 021 3pp 26519 027 24X Fiche 50-329.84/07/18.8408010064

mimony of JG Kepplor re QA problems at facility & -tions taken Region 3, Office of Director BX15 012A 84/07/18 262 24X Fiche 50-329,84/07/18,8408010061

imony of HN Singh re unresolved geotechnical engineering including reactor bldg foundation diesel g settlement & svc water bldg foundation & tanks tanks tanky Dept of, Corps of Engineers BV16 016 pp 26510 319 24X Fiche 50-029,84707718,8408010061

imony of RB Landsman in Olen Elign. IL re GA criteria &

NRC - No Detailed Affiliation Given BX17 002 26529 332 24X Fiche 50-327.84/07/18,8408010061

tacript of B Stamiris 840425 statement re soil settlement lant eens Stamiris, 8 | IX17 041 | 84/04/25 | 30p | 26536 134 ~329:84/07/18:8408010061

acript of M Sinclair 840425 statement re problems w/util 1986 const completion date Documentation enct Sinclair, M BX17 042 B4/04/25 10pp 26536 137 329,84/07/18,840801006;

icript of T Hearron 840425 statement opposing menaing & operation of plant has Tree Council 8X19 043 84/04/25 4pp 1X Fiche 50-327.84/07/18.8408010061

Cript of BP Garde 840425 statement re Govt Project 840210 supplemental 100FR2 206 Preakdown, NRC action problems & adequate Lew of complex project Vernment Accountability Project BX19 044 D 26536 151 24X Fiche 50-329,84/07/18,8408010061

- --8408220064 Testimony of RN Gardner re qualification of Bechtel QC personnel Certificate of Syc & related info encl GARDNER, R N Region 3, Office of Director BX19 023 B2/01/22 120pp 26532 292 24% Fiche 50-329, 84/07/18, 8406010064
- --8408270336 Testimony of BF Garde re Midland Nutlear Power Plant CARDE, B P Government Accountability Project BX19 021 84/02/13 22pp 26532 040 24X Fiche 50-329,84/07/18,8408010061

## V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners MALKER.R D Region 3. Office of Director 84/08/10 Michigan. Univ of. Ann. Arbor, MI 2pp 26051 198 24x Fiche 50-000. 84/08/10.8408140426

DOCKET 50-330 MIDLAND PLANT. UNIT 2

A Application/construction stage documents & correspondence

8408020015 Forwards response to NRC request for add1 info re Vol 1X of seismic margin review rept. "Balance-of-Plant Class 1,2 & 3 Piping-Pipe Supports & Valves "COOK.J W Consumers Power Co 84/07/11 DENTON,H R Office of Nuclear Reactor Regulation. Director 16pp 25883 120 24X Fiche 50-329.84/07/11.8408020015

8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Doold & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing FELTON-J M Division of Rules and Records BX14 000 84/07/RICC, C N Kirkland & Ellis 2pp 26500 001 24X Fiche 50-329.84/07/18/8408010061

- --7012070142 Discusses IE Insp Repts 50-329778-12 & 50-330/78-12 Contributing factors to settlements of diesel generator bldg foundation & generator pedestals include variable properties of random fill math supporting structure & cooling pend KEPPLER.J C Region G. Chicago. Office of the Director BX16 001 78/11/01 THORNOURG, H D Division of Reactor Construction Inspection 2pp 26506 211 24X Fiche 50-329,84/07/18,840801006;
- --7909290119 Forwards outline history of geotechnical engineering problems re plant fill Lists pertinent PSAR & FSAR criteria & summarizes foundation conditions & remedial measures for all Category I structures founded on plant fill GILLEN.D M. Queosciences Branch 8X16 015 79/08/28 JACKSBN.R E. Geosciences Branch 10pp 26510 309 24X Fichs 50-929,84/07/18.8408010061
- --8004040738 Summary of 800227 & 28 meeting & site visit w/util in Midland.MI re soil settlement problems & related investigation program GONZALES.R D Hydrology Meteorology Branch BX16 032 80/03/BIVINS.W S Hydrology Meteorology Branch 7pp 26511 117 2 Fiche 50-329,84/07/18,8408010061
- --800B130764 Summarizes status of seismological input parameters regeosciences & geotechnical review of facilities as discussed at 800702 & 22 meetings
  KMMMALL.J. Geosciences Branch BX16 027 80/08/07 JACKBON.R E
  Geosciences Branch opp 26511 075 24X Fiche 50-327,84/07/18. Geosciences Branch 8408010061
- --8011240409 Forwards Hydrologic Engineering Section interrogatories re permanent dewatering sys at facilities LEAR.0 E Hydrologic & Geotechnical Engineering Branch BX17 008 80/11/10 TECESCO.R L Assistant Director for Licensing 3pp 26517 244 24X Fiche 50-329.84/07/18.8408010061
- ---8105070480 Responds to request re Geosciences Branch estimate of time required to complete site review. Approx 30 days are needed to review add1 info requested for fart i & 3 months are needed for review of Part 2 submittal KNIGHT. J P Assistant Director for Comp & Structures Engineering (Pre 830201) 8116 0378 81/04/24 PATON. H D Office of the Executive Legal Director 1p 26513 189 24X Fiche 50-329,84/07/18,8408010061
- --Bil0190801 Forwards topic discussions for inclusion in 1981 annual rept.per 810902 commitment Discussions of technical assistance program for licensing. GETR review & Midland assistance program for licensing welk review & nioland remedial repair info encl HELLERIL W Hydrologic & Geotechnical Engineering Branch BXI6 053 BI/09/16 LFAR.O Hydrologic & Geotechnical Engineering Dranch 6pp 26512 253 24% Fiche 80-329,64/07/18,8408010061

- ~8411240064 Informs of 811016 conference call w/util to discuss revised schedule for soils hearing requests revision to better accommodate const schedule Agreed schedule for hearings will be 811201-04 & 1214-18

  HOOD, D. Licensing Branch 4 8X19 0368 81/10/30 TEDESCO,R L Assistant Birector for Licensing 3pp 26535 252 24X

  Fiche 50-329,84/07/18,8408010061
- -8201050063 Summarizes 811207 telcon re 820105 soils hearing HOOD, D Licensing Branch 4 BX18 032 81/12/14 ADENSAM.E 0 Licensing Branch 4 2pp 26526 099 24X Fiche 50-329.84/07/18, B408010061
- ~8201220049 Advises of 1-month delay in meeting R Tedesco 811214 schedule in support of facility hearing & review Viable schedule must recognize need for iteration w/applicant following each significant submittal VOLLMER.R FI Division of Engineering 8X16 074 81/12/28 EISEMHUT, D © Division of Licensing 3pp 26514 188 24X Fiche 50-329,84/07/18,8408010061
- -8202040352 Informs that certain SER sections, especially soil remedial actions, will not be complete by 820406 deadline ADENSAM, E.G. Licensing Branch 4 BX16 055 82/01/19 EISENBUT, D.G. Division of Licensing 3pp 26512 266 24X Fiche 50-329,84/07/18.8408010061
- -8203020050 Summary of 811006-07 meeting w/util.Bechtel & consultants in Bethesda.MD re underground piping in inadequately compact plant fiil MOCD.D S Licensing Branch 4 8X21 002 82/02/05 DENTON.H R NRC No Detailed Affiliation Given 37pp 26549 084 24X Fiche SO-329.84/07/18.8408010061
- -8205030209 Forwards listing of issues to be resolved prior to start of Phase 2 underpinning operations for auxiliary bldg LEAR.9 Hydrologic & Geotochnical Engineering Branch BX16 035 82/04/28 ADRSAM.E Licansing Branch 4 2pp 26511 200 24X Fichs 30-329,84/07/18,8408010061
- ~8205120033 Summarizes technical comments from ACRS subcommittee 820429 meeting re remedial activities for deficient soils ADENSAM, E. G. Licensing Branch 4 BX16 035 82/05/04 BOSNAK, R. NRC No Detailed Affiliation Given 4pp 26527 183 24X Fiche 50-329, 84/07/18, 8408010061
- -8205210467 Notifies that util submittal re Phase 2 of underpinning repair work at facility acceptable, provided that encl mods & requirements are incorporated into Phase 2 program KNIGHT, JP Assistant Director for Comp & Structures Engineering (Pre 830201) 8X16 038 82/09/10 TEDESCO,R L Assistant Director for Licensing 34pp 26511,203 24X
  Fiche 50-329,84/07/18.8408010061
- -8206020051 Comments on draft of acceptance provisions for Phase 2 Final transmittal to applicant should move through DE for
  - transmittal to applicant should move through MC for concurrence KNICHT, J.P. Assistant Director for Comp. & Structures Engineering (Pre 830201) BX16 036 82/05/13 KANC, J. Assistant Director for Comp. & Structures Engineering (Pre 830201) ip 26511 202 24X Fiche, 50-329, 84/07/18, 8408010061
- -S206240401 Forwards comments on B20422 response to MRC request for add1 info re borated water storage tank & underpinning of svc water pump structure Contact w/applicant to resolve differences recommended LEAR, O Hydrologic & Geotechnical Engineering Branch 82/06/16. ADENSAM; E Licensing Branch 4 105pp 66129 OSI. 24X Fiche 50-329,84/07/18.8408010061
- -B206270161 Submits proposed schedule for facility soils review ADENSAM,E 0. Licensing Branch 4 BX18 036 82/06/25 EISENHUT.D G Division of Licensing 2pp 26527-187 24X Fiche 50-329,84/07/18.8408010061
- -8207140330 Forwards request for add1 info from Structural Engineering Branch re applicant proposed remedial actions SCHAUER,F.P. Structural Engineering Branch 8X19 029 B2/06/15. ADENSAM.E Licensing Branch 4 5pp 26533 206 24X Fiche 50-329,84/07/18,8408010061
- 8210130322 Forwards info re location of data on underpinning dimensions & load transfer procedures POULOS.B J Geotechnical Engineers, Inc. BX16 060 82/10/D7 KANEJ Division of Engineering. App 26513 234 24X Fiche 50-329,84/07/18,8408010061

- --8210150698 Clarifies NRC/util interaction re OL review Maint of proper control by licensing property managers necessary to manage licensing activities properly Reviewers requested to follow guidelines ADENSAM, E 0 Licensing Branch 4 BX16 070 82/09/29 ADENSAM, E 0XC - No Detailed Affiliation Given 201 26514 109 24X Fiche 50-329,84/0//18,8408010061
- --8305270222 Forwards trip rept of 830510-13 site visit re underpinning contract Other topics discussed include cracks in svc water pump structure heave over freeze wallineed to stop laying back soil along underpinning drifts & settlements POULOS, S J Geotechnical Engineers Inc BXIS 022 83/05/23 KANE, J Division of Engineering 17pp 26524 317 24X Fiche 50-327,84/07/18.8408010061
- --- 8304040387 Trip rept of 830511 & 12 site visits to view pier load test Installation & results

  KANE, J D Structural & Geotechnical Engineering Branch UX18 02

  B3/05/27 LEAR, G Structural & Geotechnical Engineering Branch

  2pp 24524 315 24X Fiche 50-329,04/07/18,8408010061
- --8307130423 Forwards paper entitled "Use of Site Dependent Spectra" to be presented at workshop on "Site-Specific Effects of Soil & Rock on Ground Motion & Implications for Earthqavake-Resistant Design" on 830726-28
  KIMBALL.J Geosciences Branch 8X17 039 83/06/27 JACKSON,R C Geosciences Branch 1p 26520 069 24X Fiche 50-329,84/07/18,8408010061
- --8307130425 Speech entitled "Uso of Site Dependent Spectra," to be presented at 830726-28 workshop on "Site-Specific Effects of Soil & Rock on Oround Motion & Implications for Earthquake-Resistant Design" in Santa Fe.NM KIMBALL.J Geosciences Branch BX17 040 83/06/27 25pp 26520 070 24X Fiche 50-329,84/07/18,8408010061
- --B310070262 Forwards second phase of Geotechnical Engineering input on findings of fact & conclusions of law in response to DELD request Several areas of significant differences exist ro diesel generator bidg
  LEAR. O Structural & Osotechnical Engineering Dranch BX17 032
  B3/09/30 PATON, W D Office of the Executive Legal Director 6pp 26519 246 24X Fiche 50-329.84/07/18.8408010061
- -8312080185 Forwards technical evaluation of HVAC structural design adequacy, based on findings of Mechanical Engineering Dranch design review & audit KNICHT.J P Assistant Director for Comp & Structures Engineering (Post 830201) IRXIB 051 83/11/25 NDVAK.T M Assistant Director for Licensing 27pp 26528 206 24X Fiche 50-329,84/07/18.8408010061
- -8312120393 Requests requisite info re followup action to be taken by Region III to 831108 recommendation for board notification EISENHUT.D @ Division of Licensing BX21 014 83/11/30 MARNICK.R F Region 3. Office of Director 1p 26593 204 24X Fiche 50-329,84/07/18,8408010961
- --B406020280 Trip rept of 840504 site visit to participate in public meeting on mgt appraisal program to be performed on util Comments on independent mgt appraisal encl MCLAUGHLIN.P Licensee Gualifications Branch BX20 010 84/05/22 BOOHER.H R Licensee Gualifications Branch 5pp 24537 045 24X Fiche: 50-327,84/07/18,8408010061
- -840B010149 Forwards executive summary re QA program update, per 010331 meeting commitment & NRC 810402 ltr Apps will be transmitted meeting commitment & PRC B10402 107 Ppps Will B10322
  CGOM, J W Consumers Power Co BX14 007 B1/04/30 KEPPLER, J 0
  Region 3, Chicago, Office of the Director (B1/03/01) 17pp
  26500 039 24X Fiche 50-329,84/07/18,8408010061
- --8408020038 Lists questions asked of util during FSAR & 10CFR50 54(f) review, including questions re geological & seismological matters & intake & discharge structures for svc water sys KANE, J NRC No Detailed Affiliation Olven BX17 001 84/07/18 19pp 26514 273 24X Fiche 50-329,84/07/18,8408010061
- --B408020043 Lists questions & responses re condition of soils onsite, correction to foundation problems & risk in allowing const to continue \* NRC - No Detailed Affiliation Given BX17 002 79/03/05 15pp 26514 322 24X Fiche 50-329,84/07/18,8408010061
- --8408020099 Answers to util interrogatories re staff requests directed on determination & justification of acceptance criteria applied to various renedial measures taken on page 3 of en BX17 010 84/07/18 24X Order
  KANE, J NRC - No Detailed Affiliation Given
  Consumers Power Co 3ipp 26517 331 24
  Fiche 50-329,84/07/18,8408010061

- --B408020112 Question re discrepancy in magnitude of loading stress on Fig 2 of B00914 rept & info on Tables 4-1A & 2 5-14
  - 5-14 NRC No Detailed Affiliation Given BX17 Of 518 143 24X Fiche 50-329,84/07/18,8408010061 26518 143
- --B40B020122 Provides trip rept for 781107 meeting in Urbana.fL resettlement of far east bay of diesel generator bldg List of correction action options provided COOKC.fC Consumer Power Co 8X17 015 78/12/12 Consumer Power Co 4pp 26518 264 24X Fiche 50-329.84/07/18.8408010061
- --8408020188 Responds to Mooney concept theory re SRP 2 5 4 & PSAR review Suggestion to DELD re Mooney testimony encl MIDDD. D NRC No Detailed Affiliation Given BX17 027 83/1: HASSEL, D M NRC No Detailed Affiliation Given 4pp 24519 153 24X Fiche 50-329,84/07/18,8408010061 83/11/22
- --8408020192 Forwards applicant advance copy of meeting notes for 820727-30 design audit of soils remedial activities in Ann Arbor, MI Questions should be referred to J Kane LEAR, G Hydrologic & Ocotechnical Engineering Branch BX17 043 82/09/17 ADENSAM, E Licensing Branch 4 22pp 26520 224 24X Fiche 50-329,84/07/18,8408010061
- --8408020193 Informs that Structural Mechanics Assoc seismic margin review studies indicate soil layering profiles & soil properties differ from properties previously addressed KANE.J Structural & Geotechnical Engineering Branch BX17 044 82/05/11 LEAR.O Structural & Geotechnical Engineering Branch 2pp 26520 247 24x Fiche 50-329.84/07/18,8408010061
- --8408020199 Summary of 840417 meeting w/TERA. Structural Mechanics Assoc (SMA) & util in Chicago, IL to discuss SMA seismic margins evaluation & potential applicability to disposition of outstanding civil/structural issues
  RIMALDI,F Structural & Geotechnical Engineering Granch BX17
  045 84/07/18 LEAR, G Structural & Geotechnical Engineering
  Branch 2pp 26520 247 24X Fiche 50-329,84/07/18,8408010061
- --8408020197 Forwards request for add1 structural engineering info needed to continue OL review of NPP application as applicable to seismic margins review.svc water pump structure & diesel generator bldg LEARL G Structural & Geotechnical Engineering Branch DX17 046 64/05/03 ADENSAM Licensing Branch 4 5pp 26521 042 24X Fiche 50-329.84/07/18.8408010061
- -8408030001 Handwritten noies & outline of conference call w/Bechtel & util re review of buried piping manitoring program & future settlement
- 81/12/15 6pp --8408030004 Summary of 811006-07 meeting w/util in Dethesda, MD re
- underground siping in inadequately compacted plant fill Meeting agenda, attendance list & const hydro test viewgraphs
  - HICID.D S Licensing Branch 4 BX17 048 82/02/03 Licensing Branch 4 36pp 26515 241 24X Fiche 50-329 84/07/18 8408010061
- --8408030009 Summary of 810721 meeting w/applicant in Bethesda.MD resummary of San Onefre neeting on confirmatory analysis of piping sys design Confirmatory analysis encl
  RDDD.H Licensing Branch 3 8X17 049 81708/19 Licensing
  Branch 3 29pp 26515 277 24X Fiche 50-329.84/07/18,8408010061
- --8408030013 Notification of 820416 meeting w/util in Bethesda, MD to discuss buried piping & related applicant 820316 submittal W/handwritten notes of 820407 conference call & outline of outstanding issues in gestechnical engineering area HODD, D S Licensing Branch 4 BX17 030 82/04/13 ADENSAM, E & Licensing Branch 4 22pp 26515 306 24X Fiche 50-329, 84/67/18, 8408010061
- --8408030020 Handwritten notes on 810120 meeting re stress analysis for underground piping Outline of discussion topics for pipe stress analysis encl KANE, J NRC No Detailed Affiliation Given BX17 052 Bi/01/20 NRC No Detailed Affiliation Given 18pp 26515 355 24X Fiche 50-329,84/07/18,840801006t
- --B40B03002B Agenda for B20121-22 meeting to discuss underground piping concerns W/handuritten summary of B20107 conference call re underground piping & B20120 evaluation of sand settlement due to barthquake
  KANE.J NRC No Detailed Affiliation Given BX17 059 B2/01/22
  NRC No Detailed Affiliation Given 23pp 26516 017 24X
  Fiche 50-329,84/07/18,8408010061

- ---8408030042 Agenda for 811006 meeting w/Bechtel.util & Army Corps of Engineers to discuss underground piping reprofiling.proposed demonstration solution & 1981 measurement results \* NRC No Detailed Affiliation Given BX17 058 81/10/06 Office of Nuclear Reactor Regulation, Director 11pp 26516 045 24X Fiche 50-329.84/07/18.8408010061
- --8408030051 Handuratten notes re addl boring logs at buried diesel generator fuel pil storage tank location Calculation sheets & boring logs encl MEISENHEIMER, J. NRC No Detailed Affiliation Given BX17 060 B2/03/29 PANE, J. NRC No Detailed Affiliation Given 13pp 26516 057 24X Fichs 50-329,84/07/18,8408010061
- --8408030056 Handuritten notes re 810120 meeting w/applicant on settlement of Category I underground piping
  KANE, J NRC - No Detailed Affiliation Given BX17 O61
  CAPPUCCI, T NRC - No Detailed Affiliation Given 4pp
  26516 070 24X Fiche 30-329.84/07/18.8408010061 81/02/09
- --B408030058 Forwards evaluation of general acceptability of effects of settlement in several buried svc piping sys Rept partial response to FBAR Questions 14 through 20 & 34 MLEIN-B R Bechtel Corp BXI7 062 B0/08/01 CURTIB, L H Bechtel Corp 7pp 26516 074 24x Fiche 50-329,84/07/18, B808010064 8408010061
- ---B40B03O064 Forwards analysis of buried piping background info.in support of proposed demonstration solution & in response to NRC concern re underground piping Addl angineering info
  - encl KEELEY.0 8 Consumers Pawer Co 8X17 O63 81/12/15 DENTON.H R Office of Nuclear Reactor Regulation, Director 76pp 24516 081 24X Fiche 30-329.84/07/18.8408010041
- --8408030068 Forwards stress analysis of several underground pipe lines as profiled in Rev 6 of "Responses to NRC 10CFR50 54(f)
  Requests re Plant Fill" dtd 800401
  BATES.J O Rockwell International Corp BX17 064 B0/10/01
  BUSNAK.R J Mechanical Engineering Branch 52pp 26516 162 24X
  Fiche 50-329,84/07/18,8408010061
- --840Bi30227 Contract for consulting svcs between util & Mgt Analysis Co, agreeing to perform technical svcs.including consulting & GA svcs Purchase requisition, internal memos & supporting documentation encl COOK, J W Consumers Power Co BX15 001 92/01 26500 316 24X Fiche 50~329,84/07/18,8408010061
- --8408130230 Discusses 830118 & 26 meetings in Olen Ellyn IL re Region III insp of diesel generator bldg & independent design review program: respectively Midland project manager will attend 830126 public meeting ADENSAM.E Q Licensing Branch 4 8315 002 83/01/05 NDVAK.T M Assistant Director for Licensing 17pp 26502 089 24X Fiche 50-329,84/07/18,8408010061
- --8408130234 Draft memo re issues of potential impact on Hearing Board considerations concerning GA program KEPPLER.J G Region 3. Office of Director BX15 003 82/04/02 ETSENIUT.D G Division of Licensing 7pp 26502 121 24X Fiche 50-329.84/07/18.8408010061
- --8408130241 Notification of 821207 mgt meeting w/Region III to discuss implementation of GA & IDVPs
  HERNAN,R W Licensing Branch 4 DX15 004 82/11/01 NOVAK,T M Assistant Director for Licensing 2pp 26502 131 24X
  Fiche 50-324,84/07/18.8408010061
- -8408130244 Forwards BALP 3 schedule Internal memos, handwritten in-process insp notices, program notes & supporting documentation encl TAMBLING,T N Region 3, Office of Director BX15 005 Region 3, Office of Director 53pp 26502 133 24X Fiche 50-329,84/07/18,8408010061 82/11/01
- --8408130255 Forwards response to draft SALP rept Requests meeting w/ Keppler to review detailed contents of response Internal memos & handwritten notes encl COOK, J W Consumers Power Co BX15 006 82/05/17 KEPPLER. J G Region G. Office of Director 71pp 26302 188 24X Fiche 50-329,84/07/18.8408010061
- --B408130269 "Const Project Evaluation of Consumers Power Co.Midland Energy Ctr Project Units 1 & 2 (Observations) " # Management Analysis Co BXIS DO7 83/01/31 160pp 26502 311 24X Fiche 50-329,84/07/18,8408010061
- --B40Bi3D290 Forwards Mgt Analysis Co Assessment of Midland GA program Rept endorses program M/o encl CODK.J W Consumers Power Co BX15 00BA 81/06/01 XEPPLER, J O Region 3, Chicago. Office of the Director (81/03/01) 40pp 26503 178 24X Fiche 50-329,84/07/18,8408010061

- |408130301 Submits changes to be implemented prior to util resuming remedial soils work Draft list of noncompliances & deviations handwritten notes & list of events since Jul 1981 hearings encl
  WARNICK.R F Region 3, Office of Director BY15 010 82/09/20
  KEPPLER.J G Region 3, Office of Director 70pp 26504 031 2
  Fiche 50-329,84/07/18,8408010061
- ~4×
- 1408130306 "Biennial GA Audit of Midland Plant,Units | & 2 " Opening remarks of NRC 830208 meeting w/util & independent review encl enti \* Management Analysis Co - BX15-011 - B3/03/01 - 75pp - 26504-131 - 24X Fiche - 50-329,84/07/18.8408010061
- 408130311 Notification of significant licensee 830313 meeting in Olen Ellyn, IL to present INPO findings \* Region 3, Office of Director 8X15 012 83/03/09 Region 3, Office of Director 1p 26504 261 24X Fiche 50-329,84/07/18, 8408D10061
- 1408130320 Forwards status rept for Midland Project for Jan 1983 W/o
- |408130323 Forwards status rept for Jam 1983 Rept contains input from each member of insp site team of Ofc of Special Cases COOK.R J Region 3. Office of Director BX15 014 83/02/10 SHAFER.W D Region 3. Office of Director 3pp 26504 294 24X Fiche 50-329,84/07/18.8408010061
- 1408130336 Requests approval not to perform SALP 3 assessments, due to widespread recognition of mgt QA & const problems Draft notice of violation insp rept & handwritten notes re diesel generator bldg monorail encl

  KEPPLER. J O Region 3. Office of Director 8X15 D17 83/04/01

  DEYBUNG.R C Director's Office. Office of Inspection and Enforcement 9Bpp 24505 043 24X Fiche 50-327.84/07/18, 8408010061
- i408130348 Submits issues to be addressed at forthcoming evidentiary session on QA & QC matters
  PATUN, W D Consumers Power Co BX15 019 B2/0B/10 ADENSAM, E G
  NRC NO Detailed Affiliation Given 6pp 26505 276 24X
  Fiche 50-329, 84/07/18, 8408010061
- 498130356 Forwards monthly status rept for Midland Project for Jan
- 408140039 Draft IE Insp Repts 50-329/78-20 & 50-330/78-20 from insp on 781211-20 & 790104-23 Violations noted inadequate control & supervision of plant fill math placement & const specs not PHILLIP.G A., GALLAGNER.E J., MAXWELL.G F Region 3. Office of Director BX16 002 84/07/18 60pp 26507 112 24X Fiche 50-329.84/07/18.8408010061
- 408140050 Summary of NRC 790607 site tour & meeting on differential settlement of plant bldgs TC Cooke 790706 ltr to Bechtel restainless steel pipe deficiency encl CODKE, TC Consumers Power Co BX16 003 79706/13 Consumers Power Co 4pp 26507 311 24X Fiche 50-329,84/07/18,8408010061
- 408140055 Preliminary "Discussion of NRC Insp Facts Resulting From NRC Investigation of Diesel Generator Bldg Settlement" \* Consumers Power Co. BX16 004 79/03/05 35pp 26507 315 24X Fiche 50-329,84/07/18,8408010061
- 40B140060 Forwards synopsis of 800228 presentation, "Remodial Measures for Electrical Penetration Wings of Control Bidg & Isolation Valve Pits" conducted before NRC representatives in Midland,
- M1 GGULD,C H Affiliation Not Assigned BX16 005 80/03/17 AFIF1,S S Bechtel Corp 22pp 26507 350 24X Fiche 50-329,84/07/18,8408010061
- iOB140065 Forwards general procedures & details employed by contractor to underpin fine arts bldg Eketches encl MARR. G Bechtel Corp BX16 006 79/04/25 AFIFI. S Bechtel Corp 6pp 26508 010 24X Fiche 50-329,84/07/18.8408010061

- -B40B140069 Lists areas to be clarified %/or amplified.in responses to 10CFR50 54(f) questions Summary of soils chronology % 790B07 internal memo re pre-neeting w/consultants encl GODKC.T C Consumers Power Co BX16 007 B0/01/25 ROTHWELL.M O Bechtel Corp 14pp 2650B 016 24X Fiche 50~329.84/07/18.840B010061
- --8408140071 Submits const QC response to 790329 questions re diesel generator bidg No variance exists from QA program requirements
  JUNNSON,D R Brohtel Corp BX14 008 79/04/09 RICHARDSON,0 L
  Bechtel Corp 9pp 26508 030 24X Fiche 50-329,84/07/18,
  B408010061
- ~~8408140076 Comments on recommendations given in soils repts prepared by Dames & Moore as compared to Bethtel earthwork specs Flant area fill supporting surrounding structures. Category I slopes & bern fill discussed AFIFI.8 Bechtel Corp BX16 009 74/09/13 CASTLEBERRY.R Bethtel Corp 5pp 26508 039 24X Fiche 50-329.84/07/18, 8408010061
- -8409140079 Recommends issuance of revised TPO std specs re large søttlement due to incorrectly placed backfill Addl correspondence on problem alert & summary of soils chronology encl RUMBAUGH.E Bechtel Corp BX16 010 79/12/27 JOHNSON,T E Bechtel Corp 33pp 26508 044 24X Fiche 50-329,84/07/18,84090.0064
- --8408140102 Forwards complete set of all abstracts of transcripts of hearings conducted on 811231-830430 W/listing of entire set of abstracts
  HAMPTON.L Isham, Lincoln & Beale BX14 012 83/07/18
  PATGN.W D Hearing Branch 2 425pp 26508 097 24X
  Fiche 50-329.84/07/18.8408010041
- --B40B140134 Handwritten notes re borings in area of svc water piping that have indicated potential for liquefaction W/Dept of Army memo re Feb 1980 visit to util & review of FSAR KANE, J NRC No Detailed Affiliation Given BX16 014 82/10/14 19pp 26510 227 24X Fiche 50-329,84/07/18,8408010061
- --8408140144 Testimony of HN Singh re unresolved gratechnical enginearing safety (saues, including reactor bldg foundation, diesel generator bldg settlement & svc water bldg foundation & borated water tanks
  SINGH.H N Army. Dept of, Corps of Engineers 8X16 016
  84/07/18 13pp 26510 319 24X Fiche 50-327,84/07/18,8408010061
- --8408140152 Handuritten notes on admission of facts re plant fill problem & cracking of certain safety-related structures resulting from inadequately compacted fill matls W/ handuritten notes re discussion w/B Paten on hearings # NRC No Detailed Affiliation Given BXI6 017 81/03/06 26510 331 24X Fiche 50-329,84/07/18,8408010061 81/03/06 2pp
- --B40B14015B Notifies of plan to take depositions of Bochtel employees in Ann Arbor beginning on 801209 Depositions will address errors made in soil placement PATDN, W D Office of the Executive Legal Director BX16 018 B0/11/19 DLMSTEAD, W J Regulations Division 2pp 26510 333 24X Fiche 50-329,84/07/18,8408010061
- --B40B140163 Presents reasons why Phase II const will not be detrimental to foundation support of auxiliary bldg Phase II primary consists of 3x6 ft hand dug piers & 7x6 ft wide access drifts for access to pier

  KANE.J., BARTLETT.D NRC ~ No Detailed Affiliation Given BX16
  017 B2/01/19 11pp 26510 335 24X Fichs 50-329,84/07/18,
  B408010041 E4080 1 00A 1
- ---8408140170 Handwritten notes re general description of extent of plant fill problem Proposed remedial measures. list of Viewgraphs & Viewgraphs for ACRS presentation enci KANE, J NRC No Detailed Affiliation Given GX14 020 82/04/26 37pp 26510 346 24X Fiche 50-329,84/07/18,8408010061
- -84G8140185 Confirms comments previously provided re Item E on Page 5 of 83O715 ltr concerning slope layback during underpinning Item E expresses concern by 86W inspectors that slope layback is greater than in design POULOS.6 J Geotechnical Engineers, Inc. 8X16 022 83/09/22 KANE.J Office of Nuclear Reactor Regulation, Director 2pp 26511 027 24X Fiche 50-329,84/07/18,8408010061
- --8408140196 Summarizes comments re 830914-15 audit of facility 408140196 Summarizes conments re B30914-15 audit of facility underpinning Purpose of audit was to gather info from applicant re effect on design & const of reducing modulus of hard clay foundation From 3000 Ksf to 5000 Ksf PDULLOS, S J Geotechnical Engineers, Inc BX16 O23 B3/09/22 KANC, J Office of Nuclear Reactor Regulation, Director 3pp 26311 O31 24X Fiche 50-329,84/07/18,8408010061

- --B40B140207 Handwritten notes re design details for borated water storage tanks & util position on cause of cracking PANE.J NRC - No Detailed Affiliation Given BX16 024 81/07/28 2pp 2651 050 24X Fiche 50-327,84/07/18,8408010061
- ~-8408140213 Handwritten summary of 810805 meeting in Ramada Central Inn re borated water storage tank W/810728 handwritten memo re status of review on borated water storage tank KANE, J NRC - No Detailed Affiliation Given 8X16 025 81/08/05 NRC - No Detailed Affiliation Given 2pp 26511 052 24X Fiche 50-329,84/07/18,8408010061
- --8408140218 Handwritten notes re discussion w/O Gallagher about surcharging of valve pits near burated water tanks Record of telcon w/outi, Bechtel & Geotechnical Engineering on 810715 re surcharging valve pits encl
  \* NRC No Detailed Affiliation Given BX16 026 81/07/01 4pp 26511 054 24X Fiche 50-329,84/07/18,8408010061
- --8408140223 Handwritten notes reviewing comments on borated water storage tanks & valve pit settlements KANE, J NRC - No Detailed Affiliation Given 8X16 027 81/07/28 ip 26311 074 24x Fiche 50~329.84/07/18.8408010061
- --8408140232 Forwards draft comments on info received from applicant through Amend 85 to GL request & Rev 10 to 10GFR50 54(f) requests re borated water tanks Info received addresses all questions raised in 800707 ltr
  MCCALLISTER.P Army, Dept of, Corps of Engineers BX16 028
  B1/03/26 JACKSGN.R E NRC No Detailed Affiliation Given 14pp 26511 075 24X Fiche 50~327,84/07/18,8408010061
- --8408140242 Forwards branch position re seismological input parameters
  Position necessary to resolve differences between applicant
  & NRC on seismological issues & to provide guidance for
  inputing vibratory motion in evaluations
  JACKSON.R E Genstiences Branch BX16 030 80/07/08
  SCHMENGER.A Licensing Branch 3 6pp 26511 101 24X
  Ficha 50-329.84/07/18.8408010061
- --8408140248 Urges studies evaluating soil liquefaction & stability under dynamic loading & using values of acceleration in range of 0 12g to 0 19g at ground surface Also forwards list of strong motion records ROTHMANIR L Geosciences Branch BX16 031 80/02/11 JACKSONIR E Geosciences Branch 7pp 26511 107 24X Fiche 50-329,84/07/18,8408010061
- --8408140263 Motion to consolidate for discovery, evidentiary presentation & fact finding purposes issues relating to soil conditions for safety-related structures & sys founded in & on plant fill math in hearing considering 791206 order FARNELL.A S Consumers Power Co FARNELL.A S Isham, Lincoln & Bealo BXI6 034 80/05/27 Atomic Safety and Licensing Board Panel 15pp 26511 159 24X Fiche 50-329.84/07/18.8408010061
- --8408140286 Testimony of H Singh re origin remedial measures proposed by applicant for auxiliary bidg & Corps of Engineers evaluation of remedial measures SINGH; H NRC - No Detailed Affiliation Given BX16 0388 81/11/12 Spp 26511 242 24X Fiche 50-329,84/07/18,8408010061
- ~-B40B140296 Draft tostimony of SJ Poulos re remedial underpinning of svc water pump structure POULOB,S J Geotechnical Engineers, Inc. BX16 040 82/03/30 lipp 26511 271 244 Piche 90-329,84/07/18,8408010061
- --8408140300 Testimony of HN Singh re syc water pump structure SINOH, H N Geotechnical Engineers, Inc BX16 041 82/04/08 7pp 26511 282 24X Fiche 50-329,84/07/18,8408010061
- --8408140319 Summary of 810917 meeting w/CPC.US Army Corps of Engineers.
  NRC.Rachtel & Mueser.Rutledge.Wentworth & Johnson in
  Bethesda:MD re preliminary design of proposed remedial
  measures for svc water pumping structure
  BINGH.H N Army. Dept of. Corps of Engineers BX16 044
  81/09/18 Army. Dept of. Corps of Engineers 3pp 26511 341
  24X Fiche 50-329,84/07/18,8408010061
- --B408140347 Summary of 820422 meeting w/CPC.consisting of answers to GES questions re permanent dewatering sys.soil stabilization, Jacking procedure & draft SER KANE, J NRC No Detailed Affiliation Given BX16 046 B2/06/25 NRC No Detailed Affiliation Given 4pp 26511 348 24X Fichs 50-329,84/07/18,8408010061
- --B408140352 "Dynamic Core Penetrometer" Sketchs & design calculations of underpinning & settlement analysis study encl ANDERSON, J NRC - No Detailed Affiliation Given BX16 047 82/03/17 42pp 24512 054 24X Fiche 50-329,84/07/18,8408010061

- --8408140339 Handuritten notes re settlement manitoring programs.
  classification of fines, instrumentation & agenda for 781204
  meeting re diesel generator bldg
  \* NRC No Detailed Affiliation Given BX16 049 84/07/18
  10pp 26512 210 24X Fiche 30-327, 84/07/18,8408010061
- ~~8408140367 Draft ltr re Interagency Agreement NRC-03-76-167, Task 1, Subtask 3 concerning comment on Amend 85 List of specific discrepancies re settlement evaluations encl SINGH. H Army, Dept of, Corps of Engineers BX16 051 81/02/26 KANE, J. JACKSON, R E NRC No Detailed Affiliation Given 13pp 26512 221 24X Fiche 50-329,84/07/18,8408010061
- --8408140513 Summary of R Landsman 810325-27 & 0407-09 insps conducted to verify GA program for util soil barings conducted in response to Carps of Engineers request for addl soil info \* NRC No Detailed Affiliation Given 8x16 054 84/07/18 4pp 26512 259 24X Fiche 50-329.84/07/18 8408010061
- ~-8408140522 Informs that in preparation for issuance of draft SER in mid-late Jan, section by section review of which sections of draft received by Div of Licensing to date complete HERNAN, R W Licensing Branch 4 BX16 055A 82/01/12 ADENBAM, E G Licensing Branch 4 3pp 26512 267 24X Fiche 50-327,84/07/18,8408010061
- --8408140526 Summarizes Bio608 stipulation filed by util & NRC re GA aspects of hearing on soils settlement scheduled to begin 810707
  HDDD.D Licensing Branch 4 BX16 056 81/06/08 DENTON.H, CARTER.J Diffice of Nuclear Reactor Regulation, Director EISENHUT.D G Division of Licensing 1p 26512 272 24X Fiche 30-329, 84/07/18.8408010061
- --8408140330 Draft memo providing estimate for completing review & preparing testimony on proposed remedial actions, in response to OELD request for schedule for review LEAR, J NRC No Detailed Affiliation Given BX16 057 81/06/19 KNIGHT, J NRC No Detailed Affiliation Given 3pp 26513 185 24X Fiche 30-329.84/07/18,8408010061
- ~~B40B140337 Requests estimate of time required to complete review & prepare testimony re proposed remedial actions Testimony by F Rinaldi. T Cappucci & J Kame needs to be filed by 810715 PATON.W D Office of the Executive Legal Director BX16 057A B1/07/1B KNIGHT.J P Assistant Director for Comp & Structures Engineering (Pre B30201) ip 26513 188 24X Fiche 50-329,84/07/18,8408010061
- --8408140593 Util news ltr re lifting of part of series of stop work orders that halted const of plant \* Consumers Power Co 8X16 Obl 84/01/20 lp 26513 249 24X Fiche 50-327,84/07/18,8408010061
- --8408140556 Documents contacts by Kirkland & Ellis attys representing
  Dow Chemical in suit against CPC Summary of meeting by
  Geotechnical Engineering, Inc encl.
  KANE, J D Structural & Geotechnical Engineering Branch 8X16 062
  84/01/23 Structural & Geotechnical Engineering Branch 14pp
  24513 243 24X Fiche 50-329,84/07/18,8408010061
- --8408140557 Forwards comments re applicant submissions concerning cracks in diesel generator, fixation of cracks in borated water storage tanks underpinnings & effects or cracks on serviceability of structures

  MCCALLISTER.P Army, Dept of Corps of Engineers BX16 063
  82/06/15 LEAR.G Division of Engineering 14pp 26513 277
  24x Fiche 50-329,84/07/18,8408010061
- --8408140562 Handwritten document summarizing util response to NRC Guestions 24,45 & 47 on permanent dewatering re gentechnical engineering issues Meeting summarizes encl \* Consumers Power Co 8X16 064 81/10/12 32pp 26513 291 24X Fiche 50-329,84/07/18.8408010061
- --8408140565 Handwritten document re liquefaction analysis KANE, J C NRC - No Detailed Affiliation Given BX16 065 82/08/16 5pp 26513 323 24X Fiche 50~329,84/07/18,8408010061
- --840B140366 Requests analysis of possible enforcement action re applicant failure to inform NRC of settlement of diesel generator bldg PALLADINO,N NRC - No Detailed Affiliation Given BX16 066 84/05/24 DIRCKS,W Office of the Executive Director for Operations 1p 26514 031 24X Fiche 50-329.84/07/18.8408010061
- --8408140370 "Administrative Bldg Foundation Settlements Along Column Line 0 4 " \* Bechtel Carp BX14 068 77/12/31 21pp 26514 033 24X Fiche 50-329,84/07/18,8408010061

- --8409140373 Forwards Bechtel rept. "Administrative Bldg Foundation Settlements Along Column Line 0 4 " BRUNNER, J E Consumers Power Co BX16 067 B1/09/14 PATON, W NRC - No Detailed Affiliation Given 1p 26314 032 24X Fiche 50-329, 84/07/18, 8408010061
- ~~8408140575 Handuritten summary of 781204 site meeting re excessive settlement of diesel generator bldg & foundations & other Category I structures GALLAGHER, O Region 3. Office of Director IX16 067 78/12/07 HOOD, D NRG ~ No Detailed Affiltation Given 8pp 26514 068 24X Fiche. 50-327,84/07/18,8408010061
- --8408150015 Requests add1 borings & existing soil data Revised Encl 1 to 800327 ltv encl MCCALLISTER,P Army, Dept of, Corps of Engineers 8X16 071 84/07/18 JACKSON,R E NRC - No Detailed Affiliation Given 6pp 26514 140 24X Fiche 50-329,84/07/18,8408010061
- --8408150019 Handwritten notes re status of ASLB hearings First session, completed BL0707-17.covered items re Stamiris Contention I. GA breakdown,NRC-util stipulation on GA managerial attitude & FBAR false statement KANE. J NRC No Detailed Affiliation Given BX16 072 81/08/18 11pp 26514-146 24X Fiche 50-329,84/07/18.8408010061
- --840B150022 Handwritten notes re location of sources of important util submittals prior to 791204 Topics outlined include auxiliary bldg, diesel generator bldg, borated water storage tank & permanent dewatering KANE.U ARC NO Detailed Affiliation Given BX16 073 B1/05/18 31pp 26514:157 24X Fiche 50-329, 84/07/18,8408010061
- --8408150027 Summary of 840304 meeting w/util re schedules & topics for instant hearing on soils matters Hearing schedule resulting in inefficient reviews due to changing const priorities by applicant HOOD, D. Licensing Branch 4 BX16 075 82/03/11 TEDESCO,R L Assistant Director for Licensing 43pp 26514 191. 24X Fiche 50-329,84/07/16.8408010061
- --8408150029 Task interface agreement re plant remodial soils issue IPPDLITO,T Region 3. Office of Director NDRELIUS.C Director's Office of Inspection and Enforcement VOLLMER.R Office of Nuclear Reactor Regulation, Director 83/6 076 83/04/18 3pp. 26514 234 24% Fiche 50-329.84/07/18.8408010061
- --840Bi50O33 Discusses 830929 conference call during which D Hood gave verbal approval to allow licenses to proceed w/underpinning through UATs
  LANDSHAN,R B Region 3, Office of Director BX16 077 83/09/30
  Region 3, Office of Director ip 26514 241 24x
  Fiche 50-329,84/07/18,8408010061
- --8408180042 Handwritten notes commenting on Peck 810807 transcript re compaction criteria KANE, J NRC - No Datailed Affiliation Given BX16 079, 81/08/10 2pp 26514 264 24X Fiche 50-329,84/07/18.8408010061
- --B40B150046 Handuritten notes re electrical penetration area w/comments of H Singh on unresolved issues prior to 791206 & underground utils SINGH.H NRC No Detailed Affiliation Given BX16 080 B1/05/20 2pp 26514 266 24X Fiche 50-329.84/07/18.840B010061
- --B40B150560 Comments on licenses draft commitments to improve implementation of quality program in remedial soils area & remaining const activities.per 820907 request Noted changes should be made in program
  WARNICK.R F Region 3. Office of Director. BX21 001 B2/09/24
  KEPPLER.J G Region 3. Office of Director 4pp 26549 080 24X
  Fichs 50-329.84/07/18.8408010061
- --8408150566 "Pier Load Test Data Load by Garlson vs Load by Jacks " Related info enc! HUNT.B W Bechtel Corp 8X21 003 83/04/29 200pp 26549 215 24X Fiche 50-329,84/07/18.8408010061
- --B498180571 "Well GBS-4 Subsidence Rept " HUNT.S.W Bechtel Corp BXZI 004 B2/06/11 50pp 26550 120 24X Fiche 50-329, B4/07/18, B408010061
- -8408150577 Forwards recent audit repts by Midland QA dept.per request BRUNNER.J E Consumers Fower Co BX21 005. 82/01/15 BECHHOEFER.C., HARBOUR.J Atomic Safety and Licensing Board Panel COMMAN.F P Affiliation Not Assigned. 20pp 24550 222 24X Fiche 50-329.84/07/18.8408010061

- --0408150586 Forwards recent audit repts by Midland QA dept, per request Related info encl, including notes of CPC/NRC 030208 public meeting re const completion program BRUNNERI, JE Consumers Power CO BX21 006 82/02/05 BECHHOEFER.C., HARBOUR, J. Atomic Safety and Licensing Board Panel COMMAN.F.P. Affiliation Not Assigned 106pp 2650 248 24X Fiche 50-329,84/07/18,8408010061
- --8408150595 Opposes issuance of fuel license (IOCFR70) for applicant, based upon extensiveness of remedial soils work & potential for work to inpact auxiliary bldg Related info encl COUK.R J Region 3, Office of Director BX21 007 83/01/25 SHAFER.W D Region 3, Office of Director 19pp 26551 001 24X Fiche 50-329,84/07/18.8498010061
- --B40B15060B Rev 4 to "Quality Plan for Underpinning Activities " Related info enc! BIRD,W . B00S,A J . MODNEY.J Consumers Power Co BX21 009 B2/10/12 59pp 24551 314 24X Fiche 50-329,B4/07/18,B40B010061
- --8408150616 Enumerates QA issues to be addressed at evidentiary session in Midland proceeding,per encl 820707 memorandum & order W/o encl PATON,W D Office of the Executive Legal Director BX21 011 82/08/10 ADENSAM,E G NRC - No Detailed Affiliation Given 2pp 26593 087 24X Fiche 50-329,84/07/18,8408010061
- --8409150617 Forwards further response to FOIA-84-96.comsisting of records selected from files of Harrison & Norelius during 840628 visit ROY.0 W Office of Resource Management, Director 8X20 001 84/07/06 RICE.C M Kirkland & Ellis 3pp 26537 339 24X Fiche 50-329.84/07/18,8408010061
- --8408150624 Draft summary of NRC 840229 meeting w/util at Region III ofc re results of NRC HVAC insps & investigation of allegations & expansion of 8A training, qualification & certification activities Viewgraphs encl. \* Region 3. Office of Director 8x20 002 84/02/29 Region 3. Office of Director 2ipp 26537 342 24X Fiche 50-329,84/07/18, 8408010064
- --8408150626 Forwards HR Denton 831219 1tr distinguishing between terms "important to safety" & "safety-related" Related info encl KEPPLER.J Q Region 3. Office of Director DX21 013 83/12/29 Region 3. Office of Director 5pp 26553 163 24X Fichs 50-329,84/07/18,8408010061
- --B408190630 Forwards add1 info re Region III inquiries into Ofc of Special Cases concerning Midland & Zimmer Nuclear Power Plant problems in implementing QA programs Nonconformance rept also encl WARNICK, R F Region 3, Office of Director 8X20 003 83/09/16 BOULDEN.H Office of Inspector & Auditor 18pp 26538 001 24X Fiche 50-329, 84/07/18.8408010061
- --840B150635 Notifies that commercial operation date of Unit 2 may be delayed until mid-1986 Const schedule for Unit 1 will be revised based on cashflow requirements need for power, final cost estimates & schedule for Unit 2
  KOSCHIK.M G Consumers Power Co BX21 015 B3/11/09 STRASMA, J Region 3. Office of Director 2pp 26553 216 24X Fiche 50-329,84/07/18,840B010061
- --8408150643 Forwards listed documentation in response to FOIA 83-397 for reproduction MARNICKLR F Region 3, Office of Director 8220 006 83/07/20 SMIDTH.P T Region 3, Office of Director 1p 26538 196 24X Fiche 50-329,84/07/18,8408010061
- --8408150648 Draft summary of NRC Caseload Forecast Panel 830419-21 maeting w/util at plant site re basis for util revised estimates of Oct 1984 & Feb 1985 for Unit 2 & 1, respectively Rept on Rev 12 schedule encl NOVAK.T.M Assistant Director for Licensing 8X20 007 83/05/25 COOK, J W Consumers Power Co 32pp 26538 157 24X Fiche 50-329,84/07/18,8408010061
- --8408130451 Requests NRC approval to postpone yellowbook update due to inadequate work experience enabling development of definitive project schedule, per 831014 ltr GUAME. D L Consumers Power Co 820 008 84/01/12 HARTFIELD. R A Management Information Branch ip 26539 002 24X Fiche 50-329,84/07/18,8408010061
- --8408150452 Notifies of intent to continue const of plant following recent notification from Dow Chemical Co of decision to terminate agreement to purchase energy Related info encl FITZPATRICK, R Consumers Power Co BX21

- --8408150656 Responds to 840409 comments re util proposed plan to conduct independent mgt appraisal of Midland Nuclear Project Affidavits of independence of individuals working on audit encl
  - encl REHM. TA Office of the Executive Director for Operations BX20 009 84/06/08 GARDE, B P Government Accountability Project 31pp 26539 014 24X Fiche 50-329,84/07/18,8408010061
- --B408150662 Enumerates agreements/understandings reached at 820823 meeting w/NRC re approval for portions of Phase II underpinning work Related info encl MILLER, D B Consurers Power Co BX21 021 82/08/25 SHAFER, W D Region 3. Office of Director 14pp 26554 241 24X Fiche 50-329,84/07/18,8408010061
- --8408150465 Comments on util 840307 proposed independent mgt plan Plan does not indicate how Cresap McCormick & Paget & TERA will function & interface Roles, authorities & responsibilities should be identified Handwritten comments encl
  DEVOUNG, R C Director's Office, Office of Inspection and Enforcement BX20 011 84/03/27 KEPPLER. J Q Region J, Office of Director 4pp 26539 052 24X Fiche 50-329,84/07/18.
- --B40B150666 Bummary of NRC 840314 meeting w/D Bridenbaugh of MAB Technical Assocs in Region III re info on Midland & Zimmer plants Util 840124 ltr to Atty General of State of MI enul MARNICK.R F Region 3. Office of Director BX20 012 84/03/20 Region 3. Office of Director 7pp 26539 136 24X Fiche 50-329,84/07/18.8408010061
- ---B40B150676 Forwards util testimony on cable pulling incident Requests comments Lists questions to be addressed MLCOVE.M N Office of the Executive Legal Director BX20 014 B3/05/13 LANDSMAN.R , COOK.R , GARDNER,R NRC No Detailed Affiliation Given 7pp 26539 306 24X Fiche 50-329,84/07/18,8408010061
- --B40B1506B1 Discusses policy & procedure changes re communications w/
  licensee Related info encl
  WARNICK,R F Region 3, Office of Director BX21 027 B2/09/17
  SPEBSARD,R L Division of Project & Resident Programs
  NORELIUS,C E Division of Engineering HIND,J A Division of
  Radialogical & Naterials Safety Programs Bpp 26559 067 24X
  Fiche 50-329,84/07/18,8408010061
- --8408150682 Advises that FOIA Request 82-616 received. Matl requested must be submitted to director by 840103 Nonconformance repts & Interim Rept 3 re cable tray support const welding discrepancy and SMIDTH.P T Region 3, Office of Director 8X20 015 82/12/22 Region 3, Office of Director 2pp 26539 359 24X Fiche 50-329,84/07/18,8408010061
- --8408150689 Discusses QA program re Underpinning instrumentation installation Lists steps to follow to implement reclassification of underpinning activities CUDK. J W Consumers Power Co BX21 028 82/03/31 NORELIUS, C E Division of Engineering 2pp 26555 110 24X Fiche 50~329,84/07/18,8408010061
- --8408130686 Advises that allegations received from Dow Chemical & util are treated equally Forwards E Driker 840504 ltr re Dow Chemical vs CPC leasuit
  BERKGVITZ.D M Office of the General Counsel BX20 016
  84705/11 LEWIS.S H Region 3. Office of Director ip
  24540 094 24X Fiche 50-327.84/07/18,8408010061
- ---B408150687 Submits summary of views re regulatory status of plant Illegible handwritten notes enci KEPPLER, J G Region 3. Diffice of Director BX20 016A B4/04/06 FISCHER, R Michigan, State of 12pp 26540 095 24X Fichs 50-329,84/07/18,8408010041
- --8408150692 Forwards newspaper stories indicating representives of Dow Chemical met w/NRC to discuss matters in litigation pending in County Circuit Court w/util JD Selby 840608 ltr to FJ Kelley snc1
  DRIKER.E Barris, Sott, Denn & Driker BX20 017 84/05/04
  BERKOVIYZ, D. Office of the General Counsel 18pp 26540 160 24X Fiche 50-329,84/07/19,8408010061
- --B408150695 "Site Visit to Evaluate Crack Reported B3021B in Roof of Feedwater Isolation Valve Pit Unit 1, Midland Nuclear Fower Plant "Draft confirmatory orders handwritten notes & RF Warnick memor re FUIA Request B4-24 encl CORLEY.W 9 Construction Technology Laboratories BX20 019 B3/02/28 11pp 26540 178 24X Fiche 50-329, B4/07/18.

- ~~B40B150700 Forwards draft confirmatory order prepared by IE re plan for independent appraisal of site & corporate mgt organizations Requests review prior to meeting ILEBERMAN.S. NRC No Detailed Affiliation Given BX20 020 B3/12/30 KEPPLER, WARNICK, HARRISON NRC No Detailed Affiliation Qiven 10pp 26540 335 24X Fiche 50-329, B4/07/18, B4/08010061
- ---B40B190706 Advises that S Lewis leaving Region III to assume position of Deputy Assistant Chief Mearing Counsel in OELD B Derson replacement Chronological list of reactor holddown bolt encl
  REPPLER.J G Region 3. Office of Director BX20 022 84/05/14
  - encl KEPPLER.J G Region 3. Office of Director BX20 022 84/05/14 Region 3. Office of Director 12pp 24541 263 24X Fiche 50-329,84/07/18.8408010061
- --840B190709 Summary of 800523 meeting w/util.8&W.Bechtel & Teledyne in Bethesda,MD re preservice failure of three reactor vessel holddown studs List of attendees agenda & viewgraph slides encl Sketches for underpinning auxiliary bldg encl HDDD.D S Licensing Branch 3 BX20 023 80/07/07 Licensing Branch 3 82pp 26541 328 24X Fiche 50-329,84/07/18,8408010061
- --8408150710 Assessment rept QA program, performed during Mar & Apr 1981 \* Management Analysis Co BX21 033 81/06/01 400pp 26555 182 24X Fiche 50~329.84/07/18,8408010061
- --B408150712 "Quality Program for Underpinning Activities "
  # Consumers Power Co 8X20 024A 82/04/05 22pp 26542 132
  24X Fiche 50-329,84/07/18,8408010061
- --8408150716 "Test Program Status & Rev 12 Test Schedule "
  \* Consumers Power Co BX21 035 83/04/12 100pp \$26557 091
  24X Fiche 50-329,84/07/18,8408010061
- --8408150718 Documents conclusions & commitments made at 820330 meeting & 820402 telcons re QA applied to remedial foundation work Expansion of QA program recognized in overall success of project "Quality Program for Underpinning Activities" encl CODK-J H Consumers Power Co 8X20 0248 82/04/05 KEPPLER-J O Region 3, Dffice of Director 4pp 26542 154 24X Fiche 50-329,84/07/18,8408010061
- --8408150723 Forwards CPC testimony on alleged violation of floard order Investigation of violation coming in future Requests analysis of testimony & comments Handwritten notes encl WILCOVE.M N Office of the Executive Legal Director BX20 026 83/05/13, LANDBMAN.R. CODX.R. HDDD.D NRC No Detailed Affiliation Civen 99pp 26542 165 24X Fiche 50-329, 84/07/18, 8408010061
- --8408130725 Requests review of attached draft SALP rept in preparation for 830706 SALP Board meeting. HARNICK,R F Region 3, Office of Director BX20 027 83/07/01 HIND,J A, NORELIUS,C E, SPESSARD,R L NRC - No Detailed Affiliation Given. 149pp 26542 288 24X Fiche 50-329,84/07/18, 8408010061
- --8408150727 Summarizes 800227-28 meeting at sits re soils settlement issue & effects Handwritten note encl
  OALLACHER.E Region 3. Chicago. Office of the Director. BX20 034
  80/03/03 FIDRELLI.O Region 3. Chicago, Reactor Construction & Engineering Support Branch 46pp 26544 306 24X
  Fiche 50-329,84/07/18,8408010061
- --8408150728 Forwards advance copy of proposed rev to Manual Chapter 0516, BALP, for review NORELIUS, C E Division of Project & Resident Programs. BXZO 035 84/04/13 Region 3, Office of Director 2pp 26545-069 24X Fichs 50-329, 84/07/18, 8408010061
- --8409150729 Advises of problems concurring w/proposed response to M Cherry 770427 1tr as noted by detailed comments provided Requests redraft be considered REINMUTH, G W Division of Reactor Construction Inspection BXRO 029, 77706/10 HORFLING.R.K Dffice of the Executive Legal Diractor 7pp 26543;234 24X Fiche 50-329,84/07/18,8408010061.
- --8408130731 Advises of possible ex parte contact in facility proceeding Requests memo & attached summary of discussion be served to all parties in proceeding & PDR GIBBON, T. R. NRC No Datailed Affiliation Given BX20 030 80/12/24 CHilk, B J Office of the Secretary of the Commission 2pp 26543 250 24X Fiche 50-329, 84/07/18, 8408010061

- --8408190732 Notifies that incorrect target dates entered in B30219
  SALP schedule Correct target dates provided
  NORELIUS C E Division of Project & Resident Programs BXZO 035A
  B4/03/08 H/ND, J A Division of Radiological & Materials Safety
  Programs SPESSARD R L Division of Engineering DQUCHERTY, D J
  Office of Resource Management, Director Zpp 26545 117 24X
  Fiche 50-329, 84/07/18, 840801006;
- --B408180734 Revises previously issued SALP 4 schedule dtd 831004.by extending assessment to 18 months Rev incorporates add1 mitestone dates
  NORELIUS.C E Division of Project & Resident Programs BX20 0358
  B3712/19 Region 3, Office of Director 2pp 26545 119 24X
  Fiche 50-327,847077/18,8408010061
- ~-8408150735 Requests concurrence on proposed auxiliary bldg guideline.

  "Guidelines for Bldg Movements During Temporary
  Underpinning " Handwritten notes & communications record
  w/Marnick re ulthdrawal of potential 10CFR50 55(e) encl
  HODNEY: J A Consumers Power Co BX20 Q31 84/05/25
  HARRISON, J J Region 3, Qf+ice of Director 25pp 26543 252
  24X Fiche 50-329.84/07/18.8408010061
- --8408150737 Forwards NRC Manual Chapter 0516, SALP Evaluation criteria published in FR on 820322 for public comments Comments due by 820701
  TAMBLING, T. N. Region 3, Office of Director \$420,035C 82/05/04
  AKELSON, W. L., BARRETT, P. A., BOYD, D. C. NRC No. Detailed
  Affiliation Oiven 3pp 26545 123 24X Fiche 30-329,84/07/18,8408010361
- --B408150738 Forwards surmary of B40227 meeting in Region III ofc re results of HVAC insps & investigation of allegations & expansion of training, qualification & certification activities Handuritten notes encl
  HELLS:R A Consumers Power Co BX20 032 84/03/29
  HARRISON J J Region 3, Dffice of Director 169pp 26544 014
  24X Fiche 50-329,84/07/18,8408010061
- --8408150740 "Chapter O516 SALP," describing basis structure & overall procedures for implementation of NRC program to assess licensee performance MA Miller marked-up memo re evaluation of BALP enct # Director's Office, Office of Inspection and Enforcement BX20 0350 82/03/23 47pp 26545 126 24X Fiche 50-329.84/07/18, 8480010061
- --B40B150741 Forwards "Structural Evaluation of Diesel Generator Eldg Assessment of Structural Performance Capability & Serviceability as Potentially Affected by Settlement Induced Cracking " LEVIN.H A TERA Corp BX20 033 B3/01/04 KEPPLER, J G, EISENHUT, D Q Region 3, Office of Director COOK, J W Consumers Power Co 4pp 26544 212 24X Fichs 50-329, 84/07/18,840B010061
- --8408150743 Submits reasons for extending SALP III evaluation period to 821231 Rept contains issues being resolved between NRC & licensee Extension can be used as performance motivator Handuritten note & supporting documentation encl COUM.R J Region 3, Office of Director BX20 036 82/08/06 SPESSARD.R L Division of Project & Resident Programs 350pp 26545 173 24X Piche 50-329.84/07/18.8408010066
- --8408150745 "Structural Evaluation of Diesel Generator Bldg Assessment of Structural Performance Capability & Serviceability as Potentially Affected by Settlement Induced Cracking "Handwritten notes encl # TERA Corp BX20 033A 83/01/04 89pp 26544 214 24X Fiche 50-329,84/07/18,8408010061
- --840B150747 Submits supplemental SALP input for facility Changes required to provide overall Div of Engineering & Technical Inspirating for QA functional area & consolidate comments for recommended increased inspiracu
- --8408150749 Forwards list of items reviewed by util & determined ready for review & closure by NRC Handwritten notes & supporting documentation encl HELLS.R A Consumers Power Co BX20 038A 83/10/04 KEPPLER.J G Region 3. Office of Director 147pp 26547 165 24X Fiche 30-329, 84/07/18. 8408010061
- --8408150780 Forwards SALP input except for Matls & Processes Section PIRTLE, G Division of Engineering & Technical Inspection BX20 038 81/09/22 BOYD, D Division of Engineering & Technical Inspection 137pp 26547 012 24X Fiche 50-329,84/07/18.

- --8408150751 Forwards const status rept as 0+ 791001 Handwritten notes re diesel generator bldg & soil settlement & errata to NUREG-0834 encl FIDRELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch BY20 041A 79/10/05 KNDP.R C . HAYES.D W . DANIELSON.D H NRC - No Detailed Affiliation Given 107pp 26548 359 24X Fiche 50-329.84/07/18.8408010061
- --8408150752 Submits GA issues to be addressed at evidentiary session in facility proceeding Summary rept & oral communications record re reinsp requirements based on results of certification testing encl
  PATON.W D NRC No Detailed Affiliation Given BX20 041
  B2/08/10 ADENSAM.E G NRC No Detailed Affiliation Given
  18pp 26548 075 24X Fiche 50-329,84/07/18:8408010061
- --8408170081 "Response to NRC Staff Review Concerns for Underpinning of Auxiliary Bldg" + Consumers Power Co 8X19 001 82/06/03 40pp 26529 122 24X Fiche 50-329,84407/18.8408010061
- ---8409170102 Forwards add1 documents re facility soils issue.in response to request for info DREMOBL.K E Consumers Power Co 3X19 003 82/04/12 FISCHER, D C ACRE - Advisory Committee on Reactor Safeguards 7pp 24530 009 24X Fiche 50-329.84/07/18.8408010061
- --8408170141 Requests review of files to determine documents withholdable under FOIA, per FOIA-84-96 LEMIS.8 H NRC No Detailed Affiliation Given BX19 009 B4/05/08 HARRISGN, J J GARDNER, R , LANDSMAN, R NRC No Detailed Affiliation Given 1p 26530 066 24X Fiche 50-329,84/07/18,8408010061
- --8408170145 Forwards staft 1tr to util re raview of licensee 830310,0624 & 0712 responses to 830208 & 0523 notice of violation & proposed imposition of civil penalty Recommends imposition of \$120,000 civil penalty 9CHULTZ,W H Region 3, Office of Director 8X19 010 83/07/28 AXELRAD,J A Director's Office, Office of Inspection, and Enforcement 165pp 26530 067 24X Fiche 50-329,84/07/18,8408010061
- --B40Bi70166 Testimony of RN Qurdner re allegations concerning qualification of personnel employed by Camstock GARDNER, R N Region 3, Office of Director BY19 012A 84/07/18 100pp 26530 321 24X Fiche 50-329, 84/07/18 840B010061
- --8408170187 Forwards rept results re special electrical overinsp requested by MRC to support testimony concerning adequacy of certification/qualification process of Bechtel electrical GC inspectors
  SHAEFFER.M U Consumers Power Co BX19 015 82/02/25 COOKE,R NRC No Detailed Affiliation Given BIRD.W R , COOK, U Consumers Power Co 14pp 26531 048 24X Fiche 50-327,84/07/18,8408010061
- --8408170195 Draft "Rept on Cable Installation" \* Consumers Power Co BX19 014 82/05/14 111pp 26531 038 24X Fiche 50-329, 84/07/18, 8408010061
- --B408170233 Discusses W Marshal telcon re permanent dewatering well being drilled at northeast corner of diesel generator bidg on B40519 Drilling mud flushed into line when drilling line broke No further comment necessary LANDSMAN.R B Region 3. Office of Director BX19 031 82/06/14 PATON.W Dffice of the Executive Legal Director 2pp 26533 325 24X Fiche 30-329.84/07/18.8408010061
- --840B170297 Summary of ACRS Subcommittee on Midland Units 1 & 2 820520 & 21 meetings w/util in Midland, MI re review of GL application FISCHER. D ACRS Advisory Committee on Reactor Safeguards BX19 O32 8270B/09 CXRENT. D ACRS Advisory Committee on Reactor Safeguards 13pp 26533 359 24X Fiche 50-329,84/07/18, 240B010061
- --840Bi70260 Informs of review of encl allegations re Comstock QC at site Ofc of Investigations responsible for continuing investigation HARNICK.R F Region 3. Office of Director 8X19 033 82/11/16 FOSTER.J E Office of Investigation 125pp 26534 010 24X Fiche 30-329,84/07/18.840B010061
- --8408170279 "Structural Stresses Induced by Differential Settlement of Diesel Generator Bldg " \* Consumers Power Co BX19 037 84/07/18 51pp 26535 255 24X Fiche 50-327.84/07/18,8408010061

- --8408170284 Summary of 810502-04 mueting w/util % Bechtel in Bethesda MD re remedial actions & update of soils deficienties & to review Amend 85 to application LANDSHAN, R B Region 3, Office of Director BX19 039 81/05/12 WILLIAMS, C C Region 3 Office of Director 65pp 26536 043 24X Fiche 50-329,84/07/18.8408010061
- --8408170320 Summary of B40202-05 meeting w/util.Bechtel & consultants in Ann Arbor.MI re discussion A audit of preparations for underpinning southern part of auxiliary bldg Viewgraphs enci
  - enci HOOD, D. Licensing Branch 4 BX19 045 84/02/22 Licensing Branch 4 81pp 26536 189 24% Fiche 50-329.84/07/18,8408010061
- ~-8408170358 88W 840209 public meeting re cracking criteria & cracking mapping program Consumers Power Co BX19 046 84/02/09 Consumers Power Co 2pp 26536 349 24X Fiche 50-329.84/07/18.8408010061
- --BACRI70360 Submits list of documents supplied or withheld by
  JJ Harrison & RB Landsman, in response to FBIA Request 84-24
  MARNICK,R F Region 3, Office of Director BX19 047 84/01/18
  SMITH,P T Region 3, Office of Director 2pp 26836 351 24X
  Fiche 50-329,84/07/18,8408010061
- --8408170365 Handwritten summary of 840104 public meeting w/util.5&H Bechtel re monthly activities, crack rept, crack mapping & open items Supporting documentation & attendance list encl \* Consumers Power Co BX17 048 B4/01/13 Consumers Power Co 74pp 26536 356 24X Fiche 50~329,84/07/18,8408010061
- --8408170367 Crack mapping monitoring status rept for 831031-1130, including handwritten status rept of 831208 S&W meeting & info re grillage acceptance criteria

  \* Consumors Power Co. 8X19 049 84/08/01 10pp 26537 107 24X Fiche 50-329,84/07/18,8408010061
- --B408170372 Handwritten summary of B31110 public meeting Re tracking open items of new crack monitoring procedures B31009-1105
  \* Consumers Power Co B&19 050 B3/11/10 Consumers Power Co
  3pp 26537 129 24x Fiche 50-329.84/07/18,8408010061
- --8408170377 Handuritten notes relauxiliary bldg & underpinning design including settlement stress, results of areas of max stress & rigid body rotation \* Consumers Power Co. BX19 053 β4/08/01 76pp 26537 253 24X Fiche 30-329, 84/07/18, 8408010061
- --8408210367 Agenda for 780502 site visit w/util Bechtel & NUS Agenda for 781204 meeting w/util & Bechtel on site encl \* NRC - No Detailed Affiliation Given BX18 ODI 78/05/02 NRC - No Detailed Affiliation Given App 26521 049 24X Fiche 50-329,84/07/18,8408010061
- "-B40B21037/ Natification of 780907 monthing w/Midland Technical Reviewers in Washington, DC to discuss project status of facility safety review Reviewers will be asked to summarize review status on problem areas affecting review schedule HQQD, D Light Water Reactors Branch 4 BX18 003 7B/09/06 NRC No Detailed Affiliation Given 7pp 26521 091 24X Fiche 50-329, 84/07/18, 8408010061
- --8408210379 Provides info in response to B Garde FDIAs 83-451,-452,-454 & -449 HOOD, D. Licensing Branch 4 8X18 023 83/08/19 WILBON,V NRC - No Detailed Affiliation Given 2pp 26924 336 24X Fiche 30-329,84/07/18,8408010061
- --B40B2103B4 Notification of rescheduled 79071B meeting w/util & Bechtel in Bethesda, Mp to discuss abnormal settlement of fill & structures at site Agenda & attendance list encl HODD. Light Wafer Reactors Branch 4 BX18 004 79/06/13 VARGA. S A Light Water Reactors Uranch 4 7pp 26521 100 24X Fiche 30-329,84/07/18,8408010061
- --B40B210386 Forwards B Oarde FOIA request for documents re meetings between NRC, TERA & util on 830518,0608 & 23 concerning independent design verification W/draft ltr to util re implementation of Ford Amend WILSON,V H Management Analysis Branch BX18 024 83/08/09 Management Analysis Branch 2pp 26524 338 24X Fiche 90-329,84/07/10,8408010061
- --840B210392 Forwards B Garde FOIA 83-492 request for documents re 830615 Commission briefing WILBON,V H Management Analysis Branch BX16 025 83/08/09 Management Analysis Branch 2pp 26524 354 24X Fiche 30-329,84/07/18.8408010061

- 8408210397 Forwards B Garde FDIA 83-154 request for documents re re-review of structural adequacy of diesel generator b108 WILSON V H Management Analysis Branch B(18 026 83/0B/10 LEAR, G Hydrologic & Geotechnical Engineering Branch BOSNAK, F Mechanical Engineering Branch 2pp 26524 358 24X Fiche 50-329, 84/07/18, 8408010061
- --B40B210401 Forwards B Garde FOIA Request B3-449 for documents submitted by util reconsideration of candidate companies or methodologies to perform const implementation overview of const completion plan
  WILSON.V H Hanagement Analysis Granch BXIS 027 B4/0B/09
  Management Analysis Branch 2pp 26525 001 24X
  Fiche 50-329,84/07/IB,840B010061
- --8408210404 Determines that info transmitted by 830721 memo should be issued as Board Notification 83-106
  EIBENHUT.D G Division of Licensing BX18 028 84/07/18
  NOVAK,T Assistant Director for Licensing 1p 26525 152 24X
  Fiche 50-329,84/07/18,8408010061
- ~-8408210410 Board Notification 83-016 forwards notice of violation & proposed imposition of civil penalties based on util failure to implement adequate GA program for installation of electrical mechanical & civil components NOVAK.T M Division of Licensing BXI8 029 84/02/15 Atomic Safety and Licensing Board Panel 1p 26525 160 24X Fiche 50-329,84/07/18.8408010061
- ~-8408210411 Handuritten questions for RB Peck re consultant responsibilities & settlement monitoring Handwritten deposition of RB Beck encl \* NRC - No Detailed Affiliation Given IXIS COB BI/01/31 NRC - No Detailed Affiliation Given 36pp 26521 228 24X Fichs 50-329,84/07/18,8408010061
- ---8408210414 Forwards Board Notification 83-16 which supersedes 830215 notification NOVAK,TM NRC - No Detailed Affiliation Olven 8X18 030 84/02/18 Atomic Safety and Licensing Board Panel 1p 26525 184 24X Fiche 50-329,84/07/18.8408010061
- --8408210418 Submits package received from 8 Jones from H Singh, consisting of questions of Dr Peck by H Singh, J Dunnicliff 800208 ltr to S Afifi & summary of J Kane deposition SINGH, H NRC No Detailed Affiliation Given BXI8 007 84/07/18 JUNES B NRC No Detailed Affiliation Given Siven 36pp 26521 269 24X Fiche 30-327,84/07/18,8408010061
- --B408210421 "Guestions for Davisson B10114-15 Deposition " Guestions of Dr Peck on testimony dtd B10725 enc! \* NRC - No Detailed Affiliation Given BX18 010 81/01/11 34pp 26521 305 24X Fiche 50-329, 84/07/18.8408010061
- --8408210425 "Guestions for Davisson 810114-15 Deposition" « NRC No Detailed Affiliation 910ven 1818 011 81/01/11 43pp 26522 070 24X Fiche 50-329, 84/07/18.8408010041
- --8408210430 Draft memo informing of status of NRC-03-79-16T, Task 1. Bubtask 3 Index of Davisson deposition encl SINGH.H NRC - No Detailed Affiliation Given DXIB 012 BO/10/16 LEAR.G Hydrologic & Geotechnical Engineering Branch 17pp 26522 116 24X Fiche 50-329,84/07/18.8408010061
- --8408210433 Recommends issuance of encl matl as Board Notification 84-083 re update on stop work status & NRC staffing changes Related infe encl EISENHUT, D G Division of Licensing 8X18 016 84/04/18 NDVAK, T Division of Licensing 2pp 26522 350 24X Fiche 50-329,84/07/18,8408010061
- --B40B210446 Summary of 820202-05 meeting w/stil & Bechtel in Ann Arbor.
  MI re audit preparations for underpinning southern portion
  of auxiliary bldg Bechtel meeting notes & viewgraphs encl
  HODD D Licensing Branch 4 8XH8 019 84/02/22 Licensing
  Branch 4 79pp 86583 232 24X Fiche 50-329.84/07/18,8408010061
- --840B210430 Determines that encl rept on review of diesel generator bldg should be issued as Board Notification 83-165 EISENHUT.D G Division of Licensing BX18 020 83/10/28 NOVAN,T Assistant Director for Licensing 4pp 26524 302 24X Fiche 50~329,84/07/18.8408010061
- --8408210453 "Observed Settlements (Inches) of Structures,790930 to Present " Summary of soil properties & summary of soils info encl WANZEC, T NRC - No Detailed Affiliation Given BX18 037 80/08/27 10pp 24527 199 24X Fiche 50-329,84/07/18,8408010061

- -8408210435 Agenda for B03930 meeting w/wiii on site for appeal of NRC position \* NRC - No Detailed Affiliation Given BX18 038 B4/07/18 NRC - No Detailed Affiliation Given 1p 26527 209 24X Fiche 50-329,84/07/18,8408010061
- -8408210461 Trip rept of 831005-07 site visit re design review & audit of HVAC sys
  TERAO. D Mechanical Engineering Branch 8x18 052 83/10/28
  BOSNAK, R J Mechanical Engineering Branch 17pp 26528 234 24x
  Fiche 50-329,04/07/18.8408010061
- ---B40B210463 Braft notes recommending that listed actions be considered by Region III in effort to improve licensee regulatory attitude & performance & increase assurance that completed & ongoing const work acceptable

  \* NRC No Detailed Affiliation Given BXIB 046 B2/0B/06 4pp 26528 034 24X Fiche 30-329, B4/07/IB, B40B010061
- --8408220070 Delineates Control Sys Branch position on identification of protection sys instrument sensing lines & requests position be transmitted to near-term OL applicants

  BREIS.T P Assistant Director for Reactor Safety BX19 025

  BAYO7/18 TEDESCO.R L Assistant Director for Licensing Spp

  26533 051 24X Fiche 50-329,84/07/18.8408010061
- --B408220085 Attendance list of B20223 moeting w/util,chronological list events before & after issuance of NRC order modifying CPs. plant underpinning questions re svc water pump structure & review of 1981 technical rept on underpinning \* NRC No Detailed Affiliation Given BX17 036A 82/02/23 38pp 24334,327 24X Fiche 50-327,84/07/16.8408010061
- --8408220090 "Observed Cracks in Walls of Midland Plant Structures" CGRLEY-W Q , FIGRATO.A & Portland Cement Association 0X19 031A 82/06/14 32pp 26593 327 24X Fiche 50-327,84/07/18, 8408010061
- --B408270315 Braft ltr informing of decision re addl sail borings & testing NRC request for sampling & testing coaling pond embankments reconsidered & relocation of certain borings determined

  VOLLMER R H Division of Engineering BX16 010A 80/11/03 CDOK, J W Consumers Power Co 1p 26522 022 24x Fithe 30-329, 84/07/18,8408010061
- --B408270323 Submits listed items that inspectors consider to be indicative of questionable licensee performance COUK.R J Region 3. Office of Director BX19 019 B2/07/23 HARNICK.R F. Region 3. Office of Director lipp 26331 291 24X Fiche 50-329.84/07/18.8408010061
- B40D140311 Summary of B10717 meeting w/CPC re preliminary design of mods to svc water pump structure to resolve concerns resulting from inadequate compaction of site fill KANE.J NRC No Detailed Affiliation Given BX16 043 81/10/30 NRC No Detailed Affiliation Given 2pp 26511 337 24X Fithe 50-329, 84/07/18.8408060061
- 8408020014 Advises that util Board of Directors ordered shutdown of design const & testing activities for facilities on B40716 CP & DL applications for both units will be maintained issuance of BSER 4 (RUREC-0793) requested COOK, J W Consumers Power Co 84/07/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 25883 116 24X Fishe 50-329,84/07/27,8408020014
- HODO70173 Responds to 840726 request for authorization to complete soils shutdown activities Util authorized to proceed w/activities listed in 840726 ltr
  MARKISON.J J Region 3, Office of Director 84/07/31 MODNEY.J A Consumers Power Co 2pp 25949 343 24X Fiche 50-329.84/07/31, 8408070173
- --B408070180 Requests authorization to complete proposed listed soils shutdown activities Updates of stop work activities will be provided to Region III MODNEY, J.A. Consumers Power Co. 84/07/26 HARRISON, J. Region 3, Office of Director. App. 25749 345 24X Fiche 50-329, 84/07/31,8408070173
- 3408070110 Observe its B4-19 to all licensess of operating reactors, applicants for GLs & holders of CPs re availability of Suppl 1 to NUXEG-0933. "Prioritization of Generic Safety Issues " Svc list encl EIGENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26127 238 24X Fiche 50-000,64/08/06,8408070110

- 8408130399 Finalizes limits for control of movements of control tower felectrical penetration areas during soils shutdown activities, based on roview of latest settlement data obtained during 840801-03 site visit List of limits encl HARRISON, J.J. Region 3. Office of Director 84/08/08 MOONEY, J.A. Consumers Power Co. 3pp. 26010 185 24% Fiche 50-329,84/08/08,8408130399
- 8408200275 Generic Ltr BA-20 to all licensees of operating reactors & applicants for QLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT.D © Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 50-000,84/08/20.8408200275
- 8408270239 Confirms 840824 meeting w/util in Gleon Ellyn, IL to discuss plans for facilities
  WARNICK, R. F. Ragion 3, Office of Director 84/08/22 COOK, J. W. Consumers Power Co. 1p. 26239 156 24X Fiche 50-329,84/08/22,8408270239
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Goold & M Slobert on 840514 & 15 (App B) forwarded App A documents already forwarded index forthcoming Search continuing FELTON, J M Division of Rules and Records 8X14 000 84/07/18 RICE, C M Kirkland & Ellis 2pp 26500 001 24X Fiche 50-329,84/07/18,8408010061
- --8209230334 Forwards discussion of deficiencies noted in Supplemental SER 2 Requests mod to attached draft be provided addressing concerns
  NOVAK.T M Assistant Director for Licensing 8XIB 040 82/08/27
  KNIGHT.J P Assistant Director for Comp & Structures Engineering (Pre 830201) 3pp 26527 243 24X Fiche 50-327.84/07/18, 8408010061
- --8408150612 Draft final SSER re geotechnical engineering Related info encl KANE, J D Hydrologic & Geotechnical Engineering Branch BX21 010 82/08/12 78pp 26553 002 24X Fiche 50-329,84/07/18, 8408010061
- --B40B210454 Submits marked-up ltr re program for plant soils remedial work, in response to draft SER open items
  CODK, U Consumers Power Co BX18 047 B2/09/07 DENTON, H R
  Dffice of Nuclear Reactor Regulation, Director 47pp 24528 039
  24X Fiche 50-329,84/07/18,8408010061
- 8408020014 Advises that util Board of Directors ordered shutdown of design const & testing activities for facilities on 840716 CP & OL applications fur both units will be maintained issuance of SEER 4 (NUREG-0793) requested COOK, J W Consumers Power Co 84/07/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 25883 116 24X Fiche 50-329,84/07/27,8408020014
- F Security, medical, emergency & fire protection plans
- 8408010061 Further response to FOIA request for 16 categories of Focords re facility Documents identified by J Goold & M Blobert on 840914 & 19 (App 8) forwarded App A documents already forwarded Index forthcoming Search continuing FELTON, J M Division of Rules and Records 8X14 000 84/07/18 RICE, C M Kirtland & Ellis 2pp 26500 001 24X Fiche 50-327,84/07/18,8408010061
- --8408170268 Discusses 830922 off-the-record meeting w/Bechtel employee re allegations concerning inadequacy of plant fire detection sys Concerns raised re copyright laws concerning App R to 100FR50 BURGESS, B L. Region 3, Office of Director BX19 034 83/09/26 ROY, 0 W Region 3, Office of Director 39pp 26534 246 24X Fiche 50-329, 84/07/18, 8408010061
- 9 Adjudicatory correspondence
- 8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Goold & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing FELTON, J M Division of Rules and Records BX14 000 84/07/18. RICE, C M Kirkland & Ellis 2pp 26500 001 24X Fiche. 50-329.84/07/18.8408010061

- --8010160005 Submits questions in response to request for interrogatory input re hearing LEAR.G E Hydrologic & Gentechnical Engineering Branch BX17 013 B0/10/06 MIRAGLIA.F Licensing Branch 3 2pp 26518 144 24X Fiche 50-379,84/07/18.8408010061
- --8104230479 Submits comments on applicant response to NRC
  Interrogatories 1-3 No results available for review of
  Interrogatories i & 2 since no consolidation tests on
  samples were obtained from surchdraged area of plant fill
  MCCALLISTER.P Army, Dept of. Corps of Engineers BX17 014
  B1/03/27 LEAR.G Hydrologic & Gootechnical Engineering Branch
  2pp 26518 150 24X Fiche 50-329.84/07/18.8408010061
- --8210270126 Forwards input for testimony for 821027-1104 ASLB hearings
  Stamicis Contention 4 C b re dewatering & svc water pump
  structure should be addressed by Structural Engineering
  Branch
  LEAR, G Hydrologic & Geotechnical Engineering Branch 8X17 018
  82/10/15 ADENBAN.E Licensing Branch 4 4pp 26319 005 24%
  Fiche 50-329,84/07/18.8408010061
- --B211030222 Forwards Hydrdological & Geotechnical Engineering Branch input for testimony at ASLB 821027-1104 hearings re bearing capacity beneath diesel generator bldg.piping avc water pump structura & permanent dewatering LEAP.G Hydrologic & Ceotechnical Engineering Branch BX17 017 B2/10/14 ADENSAM.EQ Licensing Branch 4 9pp 2651B 358 24X Fichs 50-329,84/07/18,8408010061
- --8301170487 Assigns NRC sponsors for each of M Sinclair rewritten contentions for OL hearing Schedule for filing of testimony forthcoming HODD.D S Licensing Branch 4 BX17 024 83/01/14 NOVAK.T M Assistant Director for Licensing 1p 26517 072 24X Fiche 50-329,84/07/18,8408010061
- --B309270366 Responds to B30523 & 0910 requests for assistance in reviewing util proposed findings of fact & conclusions of law on remedial soils issues Agrees w/findings Recommends paragraph re occurence of liquefaction be revised BALLARD, R. L. Environmental & Hydrologic Engineering Branch BX17 037 83/09/14 PATON.W D Office of the Executive Legal Director 2pp 26520 062 24X Fiche 50-329,84/07/18,8408010061
- --8309270518 Forwards comments on util proposed findings of fact & conclusions of law on remedial soils issues

  ACKBON.R E Geostiences Branch DX17 038 83/09/21 PATON.W D

  Hearing Branch 2 bpp 26520 064 24X Fiche 50-329,84/07/18,

  8400010061
- --8310050136 Discusses structural engineering review of "Applicants Proposed Findings of Facts & Conclusions of Law on Remedial Boil Issues" along w/related info on seismic models & borated water storage tanks resulting from ASLE hearings LEAR. G Structural & Deotschhical Engineering Branch BX17 035 83/09/22 PATON. W Office of the Crecutive Legal Director 5p. 26520 051 24X Fiche 50-329,84/07/18.8408010061
- --9310070101 Forwards comments on applicant proposed findings of fact & conclusions of law on remedial soil issues

  LEAR, O. Structural & Ocotechnical Engineering Branch BX17 035A
  B3/09/29 PATON.W. Office of the Executive Legal Director 4pp
  26520 052 24X Fiche 50-329.84/07/18.8408010041
- --B310240291 Informs that structural review of document "Applicant Proposed Findings of Facts & Conclusions of Law on Remedial Soil Issues," completed Structures adequate Comments encl LEAR.Q Structural & Qeotechnical Engineering Branch BX17 036 83/10/14 PATON.W Office of the Executive Legal Director Spt 26520 036 24X Fiche 50-329,84/07/18,8408010061
- --840802007! Forwards draft answers to util interrogatories re definition of acceptance critoria of 791206 order on mod Opinion as to whether items in brackets should be deleted requested KANE, J NRC No Detailed Affiliation Givon BX17 006 81/02/24 HODD, D NRC No Detailed Affiliation Givon Ip 26515 058 24X Fiche 50-329,84/07/18,8408010061
- --8408020074 Draft answers to util interregatories re definition of acceptance criteria on Page 3 of 791204 order on mod
  \* NRC No Detailed Affiliation Given BX17 OOAA 84/07/18
  Consumers Power Co 87pp 24515 059 24X Fiche 50~329,84/07/18,8408010041
- --8408020086 Marked-up capy of Rev 1.Vol 4 to FSAR re stability of subsurface matls & foundations, questions re response to Interrogatories 13-16 & interpretations of intent of Intercogatory 13 KANE, J NRC No Detailed Affiliation Given EX17 009 77/11/30 12pp 26517 302 24X Fiche 50-329,84/07/16,8408010061

- --8408020107 Forwards motions,1980 audit repts & input re upcoming util 9A decision Applicant acceptance of poor quality performance by Bechtel criticized STAMIRIS.B Stamiris.B BX17 011 81/05/26 KEPPLER.J G Region 3. Office of Director 2pp 26518 132 24X Fiche 50-329,84/07/18,8408010061
- --8408020127 Summary of NRC recommendations of ASLB position re Stamiris Contention 2 including draft ASLB proposed findings & input into NRC testimony re Peck 770810 statement on electrical penetration area structures KANE, J NRC - No Detailed Affiliation Given BX17 016 B1/10/19 91pp 26518 268 24X Fiche 50-329,84/07/18,8408010061
- --840B020171 Summarites issues to be covered at ASLB B30214-18 hearing, including Staniris contentions. Warren contention & seismic shakedown for all structures other than diesel generator bldg \* NRC No Detailed Affiliation Given BX17 017 83/01/05 9pp 26519 009 24X Fiche 50-229.84/07/18.8408010061
- --8408020177 Suggests schedule for testimony to answer Warren Contentions 1-3, Stamiris Contention 4, Binclair Contention 24 & Marhsall Contention 2 in Feb & Mar Averings Test of contentions encl Suggests inclusion of rebuttals to contentions
  BLUME, M NRC No Detailed Affiliation Given BX17 020
  B2701727 HODD, D, KANE, J, RINALDI, F, NRC No Detailed Affiliation Given 7pp 26519 020 24X Fiche 50-329,84/07/18,8408010064
- --8408020180 Forwards input to staff testimony in preparation for ABLB 821115-23 hearings, in response to W Paton verbal request & M Wilcove request Structural Engineering Branch input applicable only to svc water pump structure BCHAUER, F P Structural Engineering Branch BX17 022 82/10/22 ADENSAM, E G Licensing Branch 4 5pp 26519 050 24X Fiche 50-329,84/07/18.8408010061
- --8408020i81 Comments on applicant 840805 proposed findings of fact conclusions of law on remedial soils issues including items re auxiliary bldg & svc water pump structure PCULOS.8 J Geotechnical Engineers, Inc 8X17 031 83/09/23 KANE, J Division of Engineering 4pp 26519 242 24X Fiche 50-329,84/07/18.8408010061
- --8408020182 Responds to M Wilcove verbal request Structural Engineering Branch area of concern identified by Judge Harbour applies only to consideration of structure-ta-structure interaction Outstanding contentions encl
  SCHAUER: F P Structural Engineering Branch BX17 023 82/10/28
  ADENSAM.E Q Licensing Branch 4 7pp 26519 059 24X
  Fiche 50-329,84/07/18,8408010061
- --B408020183 Forwards response to applicant proposed findings of fact & conclusions of law on remedial soil issues Pagination needed Findings will be filed 831115
  PATON.W D Hearing Branch 2 BX17 033 B3/11/11 KANE.J NRC No Detailed Affiliation Given ip 28519 315 24X
  Fichs 50-329,84/07/18.8408010061
- ---B40B0201B4 Forwards marked-up input to staff testimony in preparation for ASLB 821027-1104 hearings re bearing capacity & underground piping, in response to verbal request of W Paton & M Wilcove Response to Stamiris contention enci LEAR, G E Hydrologic & Geotechnical Engineering Branch BX17 023A 82/10/14 ADENAM, E G Licensing Branch 4 10pp 26519 062 24X Fiche 50-329.84/07/18.8408010061
- --8408020185 Responsive findings to applicant proposed findings of fact & conclusions of law on remedial soil issues PATONAW D. WILCOVE.M N Hearing Branch 2 BX17 034 83/11/15 100pp 26519 316 24X Fiche 50-329, 84/07/18.8408010061
- --B40B020186 Response to R Landsman 830106 questions re B Stamiris Request 4(b) re excavation of deep "G" duct bans in Freezewall Pit 4 & Tech Spec for static core penetromater KANE.J NRC - Nu Detailed Affiliation Given BX17 026 83/01/06 2pp 26519 146 24X Fiche 50-329,84/07/18.8408010061
- --840B020187 Forwards updated version of Stamiris contentions, including add1 Stamiris examples for Contentions 1.2 & 3 & changed wording of Contention 4C NRC testimony must address encl additions & changes BROWN.E M NRC No Detailed Affiliation Given DX17 0.25 B1/05/19 Consumers Power Co 19pp 26519 124 24X Fiche 50-329, 84/07/18.8408010961
- --8408020189 Forwards applicant testimony re alleged violation of ASLB 820430 order for determination of cross-examination List of questions re excavations & fireline piping provided HILCOVE.M N Hearing Branch 2 BXI7 042 83/03/13 LANDSMAN.R . CODK.R . HOOD.D NRC No Detailed Affiliation Given 2pp 26520 116 24X Fiche 50-329.84/07/18.8408010061

- 408020202 Discusses status of efforts re NRC Midland findings due 831115 Requests meeting at earliest date HOOD, D. NRC No Detailed Affiliation Given 8X17 041 83/09/23 PATCH.W D. WILCOVE, N. Hearing Branch 2 7pp 26520 095 247 Fiche 90-329,84/07/18,8408010061
- 40B14010R Forwards complete set of all abstracts of transcripts of hearings conducted on B11231-B30630 M/listing of entire set of abstracts HAMPTON.L Isham. Lincoln & Beale BX16 012 B3/07/18 PATON.W D Hearing Branch 2 425pp 2650B 097 24X Fiche 50-329, B4/07/18.840B010061
- |408140298 Manduritten notes in ASLB actions on 600527 motion to consolidate for discovery evidentiary presentation & fact finding purposes issues concerning soil conditions for safety-related structures & sys KANE, J. NRC No Detailed Affiliation Given 8x16 033 80/06/09 ip 26511 158 24X Fiche 50-329,84/07/18,8408010061
- I408140263 Motion to consolidate for discovery, evidentiary presentation & fact finding purposes issues relating to soil conditions for safety-related structures & sys founded in & on plant fill matt in hearing considering 791206 order FARMELL, A S Consumers Power Co 8X16 034 80/05/27 Atomic Safety and Licensing Board Panel 15pp 26511 159 24X Fiche 50-329,84/07/18,8408010061
- 340B190702 Advises that Region [[] has no document re discovery request for info concerning alleged violation of ASLB order concerning remedial soils Handwritten notes, internal memos & list of repts,1977 - 1983, encl HARRISON. J J Region 3, Office of Director BX20 021 B3/10/25 WRIGHT, N Office of the Executive Legal Director 199pp 26940 345 24X Fiche 50~329,84/07/18,8408010061
- 3408170223 Requests Commission review Director's Decisions DD-83-16 & DD-84-02 to require all ongoing activity be included under order of med of CP & remove util from managerial responsibility of GA/GC function GARGE. B P Government Accountability Project BX19 022 B4/02/10 PALLABINO, N OILENSKY, V . ASSELBTINE, J Commissioners 72pp 26532 090 24X Fiche 50-329,84/07/18.84080;0061
- 8408210391 Notice of W Ferris, S Afifi & J Wanzeck 801028-29 deposition in Ann Arbor, MI re 791206 order modifying const permits Related info enci PATON, W D Office of the General Counsel BX18 005 80/10/06 68pp 26521 126 24X Fiche 30-329, 84/07/18,8408010061
- 8408210398 Notice of B Dahr 801217 deposition in Ann Arbor, MI re issues set forth in Licensing Board 791206 order modifying const permits & contentions of intervenors Stamiris & Warren Resume of TR Thiruvengadam encl \* Atomic Safety and Licensing Board Panel BX18 006 80/12/11 5pp 26521 197 24% Fiche 50-329,84/07/18.8408010061
- O7300142 Responds to 840210 petition for specific Commission actions under 10CFR2 206 Petition denied per encl Director's Decision 0D-04-17 DEYOUNG: R C Director's Office, Office of Inspection and Enforcement DBB 521 84/07/24 GARDE.B P Government Accountability Project GARDE.B P Lone Tree Council 3pp. 25807 232 24x Fiche 50-329,84/07/24,8407300142
- B407300151 Director's Decision DD-84-17 denying Govt Accountability Project B40210 jetition for three Commission actions resoils work, independent third party responsibility for GA & GC & Region III staffing DEYOUNG, R C Director's Defice, Office of Inspection and Enforcement B4707/24 24pp R5807 235 P4X Fiche 50-329,84/07/24.8407300142
- B407300156 Notice of issuance of Director's Decision DD-84-17, denying Govt Accountability Project B40210, getition for Commission action
  DEYDUNG.R C Director's Office, Office of Inspection and Enforcement B4/07/24 69pp 25807 259 24X
  Fiche 30-329,84/07/24,8407300142
- OBO70377 Forwards NRC response to ASLB inquiry re Board Notification B4-115 dtd 840618 which identified specific hearing evidence adversely impacted by discrepancies in original selsmic design calculations
  PATON.W D Hearing Branch 2 DSB 816 84/08/02 BECHHOEFER.C .
  HARBOURJ J, CDMAN.F P Atomic Safety and Licensing Board Panel 7pp 23947 138 24X Fiche 50-327.84/08/02.8408070377
- OB200573 Order extending time until 841020 for Commission to act to review Director's Decision DD-84-17 Served on 840820 CHILK, S. J. Office of the Secretary of the Commission DSB 154 84/08/17 PALLADING, N. J., ROBERTS, T. M., ASBELGTINE, J. K. Commissioners ip 26137-051 24X Fiche 50-327,84/08/17, RADB200573

- K Utility Final Safety Analysis Report (FSAR) & amonds
- 8408010061 Further resoonse to FOIA request for 16 categories of records re facility Documents identified by J Goold & M Siebert on 840514 % 15 (App B) forwarded App A documents already forwarded Index Forthcoming Search continuing FELTON J M Division of Rules and Records BX14 000 84/07/16 RICE.C M Kirkland % Ellis 2pp 26500 001 24% Fiche 50-329-84/07/18.8408010061
- ~-8408170374 Rev 44 & 47 to FSAR Response to Audit Point 1 D handwritten summaries of SRM 831013 public meeting encl \* Consumers Power Co 8X19 OS1 84/08/01 34pp 26537 170 24X Fiche 50-327.84/07/18.8408010061
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 840801006: Further response to FDJA request for 16 categories of records re facility Documents identified by J Goold & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing FELTON. J M Division of Rules and Records EX14 000 84/07/18 RICE.C M Kirkland & Ellis 2pp 26500 001 24% Fiche 50-329.84/07/18.8408010061
- ~-8205240403 Advises that ad hor ACRS subcommittee recommendations refoundation problems & related remedial actions at facilities acceptable, per 820427 & 0504-08 meetings Discussion of seismic-related issues tentatively scheduled for 820520-21 FRALEY, R F ACRS Advisory Committee on Reactor Safeguards BX14 003 82/05/14 DIRCKS, W J Diffice of the Executive Director for Operations 1p 24500 027 24X Fiche 90-329,84/07/18,8408010061
- --8204040008 Summarizes 244th ACRS meeting on 820403-05 Subj to satisfactorily completion of const & staffing & if due regard given to ACRS comments plant can operate at 57 power w/o undue risk to public Full power recommendation deteried SHEMMON.P ACRS Advisory Committee on Reactor Safeguards 8414 004 82/06/08 PALLADING.N Commissioners 6pp 26500 028 24X Fiche 50-327,84/07/18.8408010061
- --B408010132 Forwards TERA Corp B30815 ltr describing four conceptual aptions for independent quality verification program methodologies Option 1 integral part of IDCVP at Midland FISCHER.D ACRS Advisory Committee on Reactor Safeguards BX14 OO1 B3/11/15 ACRS Advisory Committee on Reactor Safeguards 2pp 26500 O12 24X Fiche 50-329.84/0//18.8408010061
- --B40B010135 Forwards GA/QC project status rept presented at ACRS 274th meeting on B30210
  FISCHER, D C ACRS Advisory Committee on Reactor Safeguards
  BX14 002 B3/03/03 ACRS Advisory Committee on Reactor
  Bafeguards App 26500 021 24X Fiche 50-327, 84/07/18,
  B40B010041
- --8408010143 Forwards summary & conclusion of overall effectiveness portion of Region III rept on design & const problems Lack of aggressive GA attitude & overreliance on AE contribute to GA problems

  FISCHER, D.C. ACRS Advisory Committee on Reactor Bafeguards

  RX14 OOS 82/12/09 ACR9 Advisory Committee on Reactor Bafeguards

  8478 Squards 4pp 24500 034 24X Fiche 50-329, 84/07/18, 8408010061
- --B40B01014/ Forwards JW Cook B10430 ltr & executive summary re 0A program update, per B30215 request BOMMERS, D A Consumers Power Co BX14 006 B3/02/16 F18CHER, D C ACRS Advisory Committee on Reactor Bafeguards 1p 26500 038 24X Fiche 50-329,84/0//18,840B010061
- --8408010152 Forwards status rept re GA/GC activities at facility to be presented at ACRS 274th meeting on 830210
  FISCHER, D.C. ACRS Advisory Cummittee on Reactor Safeguards
  BX14 008 83/02/07 ACRS Advisory Cummittee on Reactor
  Safeguards 7pp 26500 058 24X Fiche 50-329,84/07/18.
  8408010061
- --B40B010133 Discusses major reduction in safety-related work at Midland ACRS comments to NJ Palladino encl FISCHER D ACRS Advisory Committee on Reactor Safeguards BX14 OO? B2/12/09 ACRS Advisory Committee on Reactor Safeguards 3pp 26500 065 24X Fiche 50-329.84/07/18.8408010061
- ~~8408010163 Forwards cost estimate for once through steam generator overfill protection mod.per request
  DREHUBL.K E Consumers Power Co BX14 012 82/08/17
  FISCHER.D C ACRS Advisory Committee on Reactor Safeguards
  2pp 26500 073 24X Fiche 50-329.84/07/18.8408010061

- --840B01016B Forwards SSER 1.addressing ACRS recommendations contained in B2060B interim rept Operating license review project status repts for B20520-21 & 0602 encl Wa SSER FISCHER.D ACRS Advisory Committee on Reactor Safeguards BX14 013 82/07/19 OKREWIT, D ACRS Advisory Committee on Reactor Safeguards 12pp 26500 075 24X Fiche 50-329.84/07/18.
- --8408010173 Discusses util approach for satisfying safety review requirements at Big Rock Point Palisades & Midland Summary of 8020504 meeting & viewgraphs encl FISCHER, D.C. ACRS Advisory Committee on Reactor Safeguards BXI4 014 82/05/17 ACR5 Advisory Committee on Reactor Safeguards 45pp 24500 087 24X Fiche 50-329,84/07/18.
- --8408010178 Forwards summary of ad hoc Subcommittee on Midland Units 1 & 2 820429 meeting Related info encl FISCHER.D ACRS - Advisory Committee on Reactor Safeguards BX14 016 82/05/06 SIESS.C ACRS - Advisory Committee on Reactor Safeguards 32pp 26500 133 24X Fiche 50-329.84/07/18,
- --8408010183 Discusses acceptability of Midland reactor pressure vessel anchor bolts, per util 811123 ltr 5 attached rept Expresses concern re rept sufficiency SHEWMON.P G ACRS Advisory Committee on Reactor Safeguards BX14 017 82/02/03 VOLLMER.R H Division of Engineering 1p 26500 i73 24X Fiche 50-327.84/07/18.8408010061
- ~~B40B0101BB Forwards util 800522 ltr identifying one of many GA problems at facility Incident re fill math under vital structures noted in P Tam 800516 ltr Incidents should be considered in evaluation of need for subcommittee meeting YUUNG.0 C ACRB Advisory Committee on Reactor Safeguards DX14 O1B 80/06/03 SHEWMON.P ACRB Advisory Committee on Reactor Safeguards ip 26500 174 24X Fiche 50-329.84/07/18.8408010061
- --8408010171 Summary of 800523 meeting w/util in Bethesda, MD re reactor vessel holddown stud failures at facility YOUNG, G G ACRS Advisory Committee on Reactor Safeguards BX14 019 80/05/28 SHENYON, P ACRS Advisory Committee on Reactor Safeguards 3pp 26500 184 24X Fiche 50-329, 84/07/18, 8408010061
- --840B010195 Recommends review of foundation problems at facility Poor quality fill matl used under containment & other vital structures TAM.P ACRS - Advisory Committee on Reactor Safeguards BX14 020 80/05/16 SHEWMON.P ACRS - Advisory Committee on Reactor Bafeguards 1p 26500 187 24X Fiche 50-039.64/07/18,840B010061
- --B40B010198 Advises that unresolved safety issue exists in poor quality of fill matl under containment & other vital structures as evidenced by diesel generator bldg settlement MCKINLEY.J C ACRS Advisory Committee on Reactor Safeguards BX14 021 B0/05/07 TAM.P ACRB Advisory Committee on Reactor Bafeguards ip 26500 201 24X Fiche 50-329,84/07/18,8408010061
- --B40B010202 Forwards portions of FBAR for review of spil/foundation problems Site visit & subcommittee meeting will be arranged MCKINLEY.J C ACRB Advisory Committee on Reactor Safeguards BX14 022 80/03/21 0BTERDERG.J O Northwestern Univ , Evanston, IL ip 24500 202 24X Fiche 50-329, B4/07/18, 8408010061
- ~~B40B010204 Discusses facility safe shutdown boration capability B&M Water Reactors Bubcommittee review to explore proposed fixes suggested MULLER.R ACRS Advisory Committee on Reactor Safeguards BX14 O23 79/11/14 ETHERINOTON.H ACRS Advisory Committee on Reactor Safeguards 1p 26500 207, 24X Fiche 50-329,84/07/18,
- --8408010206 Summary of 790718 meeting w/util ensite re abnormal settlement of fill & structures Agenda & viewgraphs encl ZUKOR.D J ACRE Advisory Committee on Reactor Safeguards BX14 024 7970721 ACRE Advisory Committee on Reactor Safeguards 76pp 26500 210 24X Fiche 50~329.84/07/18.8408010061
- G Inspection reports, IE Bulletins & correspondence
- 8408070183 Identifies activation completed &/or in progress, in response to IE Bulletin 83-07 re apparently fraudulent matl supplied by Ray Miller. Inc Final rept planned for 840901 COOK, J & Consumers Pouer Co. 84/07/11 KEPPLER. J G. Region 3, Office of Director 4pp 25950 025 24X Fiche 50-329,84/07/11.

- 8408070227 Submits final response to IE Bulletin 83-06 re nonconforming matls supplied by Tube-Line Corp Investigation performed by Bechtel determined three vendors supplied Tube-Line matl All Tube-Line matls removed from log COOK.J W Consumers Power Co 84/07/11 KEPPLER.J G Region 3. Office of Director 3pp 25748 230 24X Fiche 50-329,84/07/11,840807027
- B40803007) Forwards IE Insp Repts 50-329/84-21 & 50-330/B4-22 on B40601-30 No noncompliance noted MARNICK.R F. Region 3. Office of Director 84/07/12 CDGK.J W Consumers Power Co 2pp 25917 315 24X Fiche 50-329.84/07/12. B408030071
- --8408030076 IE Insp Repts 50-327/84-21 % 50-330/84-22 on B40401-30 No noncompliance noted Major areas inspected remedial soil work activities allogations, turbine roll, status assessment, quality verification programs % progress

  HARRISON.J J Region 3. Office of Director B4/07/12 5pp 25917 317 24% Fiche 50-329.84/07/12.8408030071
- B408010061 Further response to FDIA request for 16 categories of records re facility Documents identified by J Goold & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing FELTON, J M Division of Rules and Records BX14 000 B4/07/18 RICE. C M Kirkland & Ellis 2pp 26500 001 24X Fiche 50-329,84/07/18,8408010061
- --8309130017 Discusses IE insp on 821012-1125 & 830119-21 & forwards order imposing civil monetary penalties in amount of \$120,000 for violation re breakdown in implementation of GA program per 10CFR30. App B DEYOUNG, R C Director's Office, Office of Inspection and Enforcement EX21 018 83/08/29 SELBY, J D Consumers Power Co 3pp 26534 045 24x Fiche 50-329,84/07/18.8408010061
- --B408020170 IE Investigation Rept 3-B2-061 on B30103-0330 No noncompliance nuted Major areas investigated allegations that util violated ASLB 820430 order re NRC approval for excavating in remedial soils program investigation closed WEIL. C H . PAMLICK.E T Region 3. Office of Director BX17 02B B3/06/02 17pp 26519 17B 24X Fiche 50-329.84/07/18.8408010061
- --8408020194 IE Investigation Rept 3-82-061 on 830711-0808 No noncompliance noted Major areas investigated allegations that util violated ASLB 820430 order re NRC approval for excavating in remedial soils pragram investigation reopened WEIL-C H. PAW-ICK-E T Region 3, Office of Director WARD, W J Office of Investigation BVI7 029 83/09/12 20pp 26519 199 24X Fiche 50-329,84/07/18,8408010061
- --8408020196 Provides Supplemental Ofc of Investigation Rept 3-82-061 re util alleged violation of ASLB order HAYES, B B Office of Investigation BX17 030 83/09/12 KEPPLER.J G Region 3, Office of Director 3pp 26519 221 24X Fiche 50-329,84/07/18.8408010061
- --8408140039 Draft IE Insp Repts 50-327/78-20 & 50-330/78-20 from insp on 781211-20 & 790104-25 Violations noted inadequate control & supervision of plant fill matl placement & const specs not followed PHILLIP,0 A Region 3, Office of Director BX16 002 84/07/18 60pp 26507 112 24% Fiths 50-327.04/07/18.8408010061
- --8408140055 Preliminary "Discussion of NRC Insp Facts Resulting From NRC Investigation of Diesel Generator Ildg Settlement "

  \* Consumers Pawer Co. 8X16 004 79/03/05 35pp 24507 315
  24X Fiche 50-329,84/07/18.8408010061
- --8408140513 Summary of R Landsman B10325-27 & 0407-09 insps conducted to verify GA program for util soil borings conducted in response to Corps of Engineers request for addl soil info \* NRC No Detailed Affiliation Given BX16 054 84/07/18 4pp 26512 259 24X Fiche 50-329.84/07/18.8408010061
- ---840815062P Discusses basis for recommendation to extend SALP 1II evaluation period from 820630 to 821231.per 820719-20 discussions Related info encl CODK.R J Region 3, Office of Director BX21 012 82/08/06 EPE88ARD.R L Division of Project & Resident Programs 13pp 26553 145 24X Fiche 50-329,84/07/18,8408010061
- --8408150424 Draft summary of NRC B40229 meeting w/util at Region III ofc re results of NRC HVAC insps & investigation of allegations & expansion of GA training, qualification & certification activities Viewgraphs encl # Region 3, Office of Director BX20 002 84/02/27 Region 3, Office of Director 21pp 26537 342 24X Fiche 50-327,84/07/18,

- --8408150633 Forwards Rev. 4 to "Region III SALP Schedule " Schedule changes to listed facilities explained in remarks sections of schedule Addl handwritten notes also encl NORELIUS, C.E. Region 3, Office of Director BY20 004 84/06/04 KEPPLER, J.O., DAVIS, A.B., SPESSARD, R.L. Region 3, Office of Director 22pp 26539 025 24X Fiche 50-327,84/07/18,8408010061
- --B40B150639 Discusses Ofc of Special Cases special insp on B21012-1125 & forwards draft notice of violation re significant breakdown in implementation of QA program Handwritten NRR comments also encl
  KEPPLER, J G Region 3, Office of Director BX20 005 83/01/05 COOK, J W Consumers Power Co 84pp 26538 049 24X Fiche 50-329,84/07/18,8408010061
- --8408150640 Ack receipt of 830926 ltr & payment in amount of \$116,500 for civil penalty imposed by B30829 order AXELRAD, J A Enforcement Staff BX21 016 83/10/04 SELBY, J D Consumers Power Co 2pp 26553 305 24X Fiche 50-329,84/07/18,8488010061
- --8408150644 Forwards payment in amount of \$116,500 in response to 830827 ltr imposing civil penalty for violations found during Insp 83-23 (EA 83-03) Related info encl.including mati on 830811 public meeting COOK, J R Consumers Power Co 8X21 017 83/09/26 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 27pp 26554 005 24X Fiche 50-329,84/07/18.8408010061
- ---8408150669 Corrects Page 3-1 of Attachment 3 to util 820517 response to draft SALP rept for Jul 1980 - June 1981, clarifying stop work order on drilling COOK, J W Consumers Power Co EX21 024 82/05/21 KEPPLER. J G Region 3. Office of Director 31pp 26554 319 24X Fiche 50-329,84/07/18,8408010061
- --8408150672 Forwards response to draft SALP rept for Jul 1980 June 1981, discussed at 820426 meeting w/NRC CODK, J W Consumers Power Co 8X21 025 82/05/17 KEPPLER, J 9 Region 3, Office of Director 38pp 26554 344 24X Fiche 50-329, 84/07/18, 8408010061
- --8408150677 Discusses SALP appraisals for Zimmer & Midland Suggests limited SALP-3 appraisal for Midland to cover remedial soils work. B&W work & HVAC activities KEPPLER, J O Region 3, Office of Director BX21 024 83/04/18 HNND. J A Division of Radiological & Materials Safety Programs 1p 26555 066 24X Fiche 50-329,84/07/18.8408010061
- --B408150690 Lists reasons why SALP III evaluation period should be extended to 821231.per 820719-20 discussion Related info encl
  COOK.R J Region 3, Office of Director BX21 029 B2/0B/06
  SPESSARD,R L Division of Project & Resident Programs 21pp 26555 112 24X Fiche 50-329,84/07/16.8408010061
- --840B15073B Forwards summary of B40229 meeting in Region III ofc re results of HVAC insps & investigation of allegations & expansion of training qualification & certification activities Handwritten notes end. HELLS,R A Consumers Power Co BX20 032 B4/03/29 HARRISON, J J Region 3, Office of Director 1A9pp 26544 014 24X Fiche 50-329,84/07/18,840B010061
- 8408150743 Submits reasons for extending SALP III evaluation period to 821231 Rept contains issues being resolved between NRC & litensee Extension can be used as performance notivator Handuritten note & supporting documentation encl CDDK.R J Region 3. Office of Director IN2O 036 82/08/06 8FESSARD.R L Division of Project & Resident Programs 350pp 24546 001 24X Fiche 50-329,84/07/18.8408010061
- PAOBISO747 Submits supplemental SALP input for facility Changes required to provide overall Div of Engineering & Technical Inspirating for GA functional area & consolidate comments for recommended increased inspirequency PIRTLE.6 Region 3. Office of Director BX20 037 83/10/01 B0VD, D Region 3. Office of Director 1p 26547 011 24X Fiche 50-329,84/07/18,8408010061
- 8408190752 Submits QA issues to be addressed at evidentiary session in facility proceeding Summary rept & oral communications record re reinsp requirements based on results of certification testing encl PATON.W D NRC No Detailed Affiliation Given BX20 041 B2/08/10 ADENSAM.E 0 NRC No Detailed Affiliation Given 18pp 26548 075 24X Fiche 50-329.84/07/18.8408010061

- --840Bi70il9 Confirms that underpinning instrumentation installation will be suspended until procedures \$ drawings developed & plans \$ schedules established to inspect & audit activities.per 820319 telcon KEPPLER.J G Region 3, Office of Director BX19 007 82/03/19 CCOK.J W Consumers Power Co 2pp 26530 037 24X Fiche 50-329,84/07/18.8408010061
- --B40B170152 Forwards redrafted insp rept Rept has been reviewed w'NRC for format & content Rept covers insp made 821129-1210 CHARAK. I Arganne National Laboratory BX19 011 B2/01/07 WARNICKLR Region 3, Office of Director 7pp 26530 233 24X Fiche 50-329, 84/07/18, 8408010061
- --8408170157 Forwards draft insp rept re findings of personnel who participated in routine insps on 821129-1203 & 1208-10 CHARAK, I Argonne National Laboratory 8X19 012 82/12/22 WARNICK, Region 3, Office of Director 14pp 26530 240 24X Fiche 50-329, 84/07/18, 8408010041
- --840B170174 Forwards IE Mgt Meeting Repts 50-329/82-09 % 50-330/82-09 on 820514 NORELIUS,C E Region 3, Office of Director 8X19 013 82/06/28 COOK, J W Consumers Power Co 2pp 26531 033 24X Fiche 50-329, 84/07/18, 8408010061
- --8408170181 IE Mgt Meeting Repts 50-329/82-09 & 50-330/82-09 on 820514 Major areas discussed licensee disposition of results of electrical averview insps GARDNER, R N , WILLIAMS, C C Region 3, Office of Director BX19 013A B2/06/24 3pp 26531 035 24X Fiche 50-329,84/07/18,8408010061
- --B40B170205 Forwards IE Insp Repts 50-329/82-07 & 50-330/82-07 on B20421-23 No noncompliance noted Schedule for reinsp program of piping suspension sys requested within 25 days from receipt of 1tr \* Region 3. Office of Director BX19 017 82/07/15 Consumer Power Co 2pp 26531 071 24X Fiche 50-329.84/07/18.8408010061
- ---8408170232 Forwards SALP Repts 50-329/82-14 & 50-330/82-14 for period Jul 1980 - June 1981 KEPPLER, J G Region 3, Office of Director BX19 026 84/07/18 CODK, J W Consumers Power Co 2pp 26533 158 24X Fiche 50-329,84/07/18,8408010061
- ~-8408170236 Ack receipt of 820114 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/81-12 & 50-330/81-12 NORELIUS,C E Division of Engineering 8X19 028 82/02/03 COOK, J W Consumers Power Co 4pp 26533 188 24X Fiche 50-329,84/07/18,8408010061
- --B40B170271 Requests Ofc of Investigations provide investigator to assist Ofc of Special Cases in closeout of unresolved item in Insp. Rept 329/B2-22-27 re use of unofficial documents for recording nonconformances & deficiencies WARNICK.R F NRC No Detailed Affiliation Given BX19 035 83/01/27 PAMLIK.E T Region 3, Office of Director 1p 26534 295 24X Fiche 50-329,84/07/18,8408010061
- --840B170274 Discusses 831021 interview w/A Gautam & unnamed individual re allegations concerning Comstock.Bechtel & Zack const activities at plant Details of issues referred to Ofc of Investigation & Ofc of Inspector & Auditor HAWKINS.F C Region 3. Office of Director BX19 036 83/10/26 Region 3. Office of Director 1p 26534 296 24X Fiche 50-329,84/07/18.8408010061
- --8408210464 Notifies of 830708 meeting to discuss NRR SALP III assessment based on recent hearing testimony by Region III & several third-party reviewers NDVAK.T M Assistant Director for Licensing BX18 055 83/07/07 JGHNBTON,W , KNIGHT,J P , RUBENSTEIN,L NRC No Detailed Affiliation Given lipp 26528 262 24X Fiche 50-329,84/07/18,8408010061
- --B408220059 Responds to B30829 ltr re imposition of civil penalty for violations noted during Insp B3-23 Penalty reduced because of prompt corrective actions Check encl COQK, J W Consumers Power Co BX19 052 B3/09/26 DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 26537 208 24X Fiche 50-329.84/07/18.8408010061
- --8408220078 SALP Repts 50-329/82-14 % 50-330/82-14 for Jul 1980 June 1981 \* Region 3, Office of Director BX19 027 82/03/31 28pp 26533 160 24X Fiche:50-329,84/07/18,8408010061

- -8408270330 Forwards summary of 840529 meeting w/Region III & util in Region III re results of insps & investigation into allegations re HVAC work NELLS, RA Consumers Power (o 8x19 020 84/03/24 HARRISON, J.J. Region 3. Office of Director 17pp 265,32 023
  - 24X Fiche 50-329,84/07/18,8408010061
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000.84/07/27,8407250229
- 8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during inspiring instituted effective 840820 Preprinted form will be used REPLER, J G Region 3, Office of Director 84/08/03 Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000,84/08/03,8408070401
- B408230502 Forwards IE Insp Repts 50-327/84-24 & 50-330/84-25 on B40611-15 & 25-27 No noncompliance noted NARNICK, R F Region 3. Office of Director 84/08/03 COOK, J W Consumers Power Co 2pp 262(2 264 24X Fiche 50-327,84/08/03,8408230502
- --840\$230512 IE Insp Repts 50-329/84-24 & 50-330/84-25 on 840611-15 & 25-29 No noncompliance or deviations noted Major areas inspected licensee action on 10CFR50 55(e) items HARRISON.J J Region 3. Office of Director 84/08/03 8pp 26212 266 24X Fichs 50-329.84/08/03.8408230502
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JURDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/04 Consolidated Edison Co of Net York Lip: 1250 24048-041 24X Fixe 50-000.84/08/040.84080013 Response (Post 830103) York, Inc. 122pp. 26 26048 001 24X Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84~60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN.E L Division of Emergency Proparedness & Engineering Response (Past 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50~000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24% Fiche 50-000,84/08/08,8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list encl CRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376
- 8408100007 IE Info Notice 84-63. "Defective RHR Replacement Piping " Syc list encl
  JORDAN.C.L. Bivision of Emergency Proparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co. of New
  York, Inc. 119pp 26197 218 24X Fiche 50-000.84/08/13.8408100009
- 8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication "Svc list end and an art first action Seal III & Indication "Svc list end Indication "Svc list end Indication "Svc list end Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 30-000.84/08/15,8408100038 104pp
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN, E.L. Division of Emergency Proparedness & Engineering Response (Post 830103) 94/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26178 001 24X Fiche 50-000,84/08/16,8408100021
- B408100055 IE Info Notice B4-66. "Undetected Unavailability of Turbine-Driven Auxiliary Foodwater Train " Svc list encl. JURDAN: E L Division of Emergency Proparedness & Engineering Response (Post 830103) B4/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000:84/08/17.8408100055
- B408140208 IE Info Notice 84-67, "Recent Enubber Inservice Testing W/ High Fallure Retes" Byo list encl JDRDAN:E L Division of Emergency Preparedness & Engineering Response (Post B30103) 64/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24% Fiche 50-000,84/08/17,8408140208

- 8408240136 Forwards Mgt Meeting Repts 50-329/84-18 & 50-330/84-19 on 840712 MARNICK,R F Region 3, Office of Director 84/08/20 CODK, J W Consumers Power Co 2pp 26228 205 24X Fiche 50-329,84/08/20, 8408240136
- --0400240144 Mgt Meeting Repts 50-329/84-18 & 50-330/84-19 on 840712 Major areas discussed work activities for auxiliary bldg underpinning, status of avc water pump structure & QA/9C Underpining, swall activities
  LANDSMAN,R B , HARRISON, J J Region 3, Office of Director
  R4/08/20 4pp 26928 207 24% Fiche 50-329,84/08/20,8408240136
- B40B210142 IE Info Notice B4~68, "Potential Deficiency in Improperly Rated Field Wiring to Bolenoid Valves " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B3010'3) B4/08/21 Consolidated Edison Co of No 26329 008 24X Fiche 50-000, 84/08/21, 8408210142
- R Periodic operating reports & related correspondence
- 8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Goold & M Siebert on 840914 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing FELTON, J M Division of Rules and Records 8X14 000 84/07/18 RICE, C M Kirkland & Ellis 2pp 26500 001 24X Fiche 50-329.84/07/18.8408010061
- --8408150603 Forwards Midland monthly status repts for Aug-Sept & Nov 1982 Related into encl WARNICK.R F Region 3, Office of Director BX21 008 82/12/20 KEPPLER.J 0 Region 3, Office of Director 23pp 26551 256 24X Fiche 30-329,84/07/18,8408010061
- --B408150698 Forwards monthly status rept for Dec 1983, containing imput from imsp site team of Ofc of Special Cases COOK, R J Region 3, Office of Director BX21 031 B3/01/12 WARNICK, R F Region 3, Office of Director 2pp 26555 161 24X Fiche 50-329, 84/07/18, 8408010061
- 8408240132 Forwards minutes of monthly third party assessment 840712 meeting re status of independent assessment of Underpinning & remedial soils work & status of const implementation overview program LUCKB, A S Stame & Webster, Inc 64/08/07 MARRISON, J J Region 3. Office of Director 43pp 26226 033 24% Fiche 50-329,84/08/07, 8408240132
- --8409240134 Forwards Independent Assessment of Underpinning Weekly Ropt 71 for 840410-16 Minutes of daily meetings between members of assessment team & site engineering.const & QA personnel enci LUCKB.A B Stone & Nebster, Inc 84/06/20 BURGEBB.B L NRC -No Detailed Affiliation Given 15pp 26226 178 24X Fiche 50-329, 84/08/07,8408240132
- --8408240138 Forwards Independent Assessment of Underpinning Weekly Rept 92 for 840617-0623 Minutes of daily meetings between members of assessment team & site engineering coast & GA personnel LUCKB, A S Stane & Webster, Inc 84/06/27 BUF No Detailed Affiliation Given 16p 26226 193 Fiche 30-329, 84/08/07,8408240132
- --B408240143 Forwards Independent Assessment of Underpinning Weekly Rept 93 for 840624-0630 Minutes of daily meetings between members of assessment team & site engineering.const & GA personnel oncl LUCKS.A 8 Stone & Webster. Inc. B4/07/03 BURGESS.B L NRC -No Detailed Affiliation (viven 11pp 26226 209 24X Fiche 50-329,84/08/07.8408240132
- -8408240148 Forwards Const Implementation Overview Weekly Rept 51 for 840528-0601 Rept includes summary of activities & open items, nonconformance identification repts & hold points KARR, J E Stane & Webster, Inc 84/06/08 KEPPLER, J G Region 3, Office of Director 18pp 26226 292 24X Fiche 50-329, 84/08/07, 8408240132
- --8408240152 Forwards Const Implementation Overview Weekly Rept 53 for 840611-15 Rept includes summary of activities & open items, nanconformance identification repts & hold points KARR, J E Btune & Webster, Inc. 84/06/22 KEPPLER, J G Region 3, Office of Director 18pp 26224, 328 24X Fiche 50-329,84/08/07,8408240132
- --8408240:159 Forwards Const Implementation Overview Weetly Rept 54 for 840618-22 Rept includes summary of activities & open items, nonconformance identification repts & hold points KARR, J E Stone & Webster, Inc 84/07/02 KEPPLER, J G Region 3, Office of Director 18pp 26224 346 24X Fiche 50-329,84/08/07,8408240132

- S Reportable occurrences, LERs & related correspondence
- B40601003B Forwards Tracked Action Item 086 re NIR 022 & NIR 023
  Requests one reply clarifying initial findings Current
  replies provide inaccurate & conflicting info
  KARR, J E Stone & Webster, Inc B4/05/22 KEPPLER, J G,
  HARRISON, J J, BURGESS, B L KRC NO Detailed Affiliation Given
  2pp 24757 351 24X Fiche 50-327,84/05/22,840601003B
- 8405290062 Forwards "Investigation of Types AF & AE Fiston Skirts "
  Rept supercedes 840227 submittal
  RAY.C L IDI (Transamerica Delaval. Inc.) Owners Group 84/05/24
  DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp
  24690 045 24x Fiche 50-000,84/05/24,8405290062
- --8405290075 "Investigation of Types AF & AE Piston Stirts "
  \* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp
  24% Fiche 50~000.84/05/24.8405290062
- B405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Btations" RAY.C L. TDI (Transamerica Delaval, Inc.) Owners Group B4/05/24 DENTON.H R. Office of Nuclear Reactor Regulation. Director 2pp 24672 090 24% Fiche 50-000.84/05/24,8403290179
- 84080&0405 Forwards repts received by BNWL & consultants directly from FAAA & TDI Duners Oroup at 840&22 meeting Draft "Overview of Repts, Analysis & Recommendations re Main Propulsion Engines M/V Culumbia" encl
  ALZHEINER, J M Battelje Memorial Institute, Pacific Northwest
  Laboratories 84/06/28 MILLER, M Division of Licensing 158pp
  25926 173 24x Fiche 30-000.84/06/28,8488060405
- 8408060050 Forwards info addressing open items identified in NRC/BNWL/TDI Dissel Generator Cuners Group 840622 meeting RAY.C. t TDI (Transamerica Delaval, Inc.) Owners Group 84/07/10 BERLINGER.C Director's Office, Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50-000.84/07/10.
- 8408310054 Final deficiency rept re concrete embedment design using shear lugs located outside compression zone Initially reported on 821203 Use of shear lugs outside compression zone is proper design technique Related correspondence COOK.J W. Consumers Power Co. DSB 786 84/07/ii KEPPLER, J G Region 3, Office of Director 1p 26350 186 24X Fiche 50-329,84/07/ii 8408310054
- 8408010061 Further response to FQIA request for 16 categories of records re facility Documents (dentified by J Goold & M Siebert on 840514 & 15 (App B) forwarded App A documents airpady forwarded Index forthcoming Search continuing FELTON.J M Division of Rules and Records BX14 000 84/07/18 RICE.C M Kirtland & Ellis 2pp 26500 001 24X Fiche 50-329.84/07/18,8408010061
- --Bi102600B2 Informs that licensee taking position that IEEE 279
  jurisdiction starts u/transmitter Jurisdiction should start
  at sensing line connection to process piping
  HENDERSON, J B Reactor Projects Sections (Regions 1 & 3) BX19
  024 Bi/10/01 WILLIAMS, C C Plant Systems Section ip
  26533 050 24X Fiche 50-329,84/07/18,8408010061
- 8408010160 Forwards interim 10CFR30 55(e) rept re GA program & mfg deficiencies affecting radiation monitoring equipment supplied by Victoreen. Inc FISCHER.D ACRS Advisory Committee on Reactor Safeguards BX14 011 B2/11/15 OKREMI.D ACRS Advisory Committee on Reactor Safeguards 1p 24500 072 24X Fiche 50-329.84/07/18.8408010061
- 8408180658 Recommends issuance of board notification for encl potential Part 21 rept from Zack Co (HVAC subcontractor) re accuracy of welder records HARAICK.R F Region 3, Office of Director 8X21 020 82/09/01 EISENHUT,D G Division of Licensing 2pp 26554 179 24X Fiche 50-329,84/07/18,8408010061
- B40B150694 PNO-77-035 on 770226 bulge discovered in containment liner plate Caused by water coming through tears in liner plate Add1 holes cut in plate to facilitate draining Related info enci
  MARNICK,R F , ROY.G W , THOMPSON.D Office of Inspection & Enforcement, Office of the Director BX21 030 77/03/01 7pp 26555 154 24X Fiche 50-329,84/07/18,840B010061
- -8408170070 Discusses util 820428 telcon notifying that, while drilling weil in G area, electric duct bank struck Drawings indicated duct bank elsewhere Investigation continuing SHAFER, W D Region 3. Office of Director BX19 GOIA 82/04/28 WILLIAMS, G C , LANDSMAN, R B NRC No Detailed Affiliation Given ip 26327 285 24% Fiche 50-327,84/07/18,8408010061

- --B40B170276 Forwards util repts to auxiliary bldg seismic analysis ? cracks in borated water storage tank roundation per util B10121-22 notifications Const deficiency info may aid in resolution of mattel NORELIUS.C E Division of Engineering BX19 O36AB B1/11/24 EISENHUT, D O Division of Litensing ip 26535 165 24X Fiche 50-329,84/07/18.8408010061
- 8408060102 Forwards "Emergency Diese) Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNML RAY,C L TDI (Transamerica Delaval, Inc.) Gwners Group B4/07/27 DENTUNJH R Office of Nuclear Reactor Regulation, Director 2pp 25932 137 24% Fiche 50-000, 84/07/27, 8408060102
- --8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " \* Stone / Webster Engineering Corp 84/07/31 34pp 25932 139 24X Fiche 50-000,84/07/27,8408060102
- 8408090284 Forwards table indicating status of 10CFR30 55(e) issues Procedures revised to assure proper handling & reporting of add1 10CFR30 53(e) items
  CODK, J W Consumers Power Co 84/07/27 KEPPLER, J G Region 3, Office of Director 4pp 25994 036 24X Fiche 50-329,84/07/27,840800284
- 8408310259 Final deficiency rept re defective capstan springs in Patific Scientific mechanical shock arrestors Initially reported on 840106 W/o description of investigation a corrective actions Related correspondence CODK, J W Consumers Power Co DSB 978 84/07/27 KEPPLER, J G Region 3, Office of Director ip 26350 281 24X Fiche 50-329,84/07/27,8408310259
- 840B060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Bets " RAY,C L TDI (Transamerica Delaval, Inc.) Dwners Group 84/08/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 25927 064 24% Fiche 50-000,84/08/01.8408060324
- --8408060387 "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets " \* Fallure Amalysis Associates FAAA-84-6-56 84/07/31 62pp 25927 066 24% Fiche 50-000.88/08/01.8408060324
- 8408160374 Forwards "Design Review of Engine Dase & Bearing Caps for TDI DSRV-16 Diesel Engines" RAY,C L TDI (Transamerica Delaval, Inc.) Owners Group 84/08/10 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 26091 147 24X Fiche 50-000,84/08/10,8408160394
- --B408160403 "Design Review of Engine Gase & Bearing Caps for TDI DBRV-16 Diesel Engines " \* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp 26071 149 24X Fiche 50-000.84/08/10,8408160394
- B408240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program, testing & insp, maint & surveillance & sets forth requirements for operation prior to completion of program plan EISENHUT.D 9 Division of Licensing B4/08/13 GEORGE, J B TDI (Transamerica Delaval, Inc.) Owners Group 1p 26255 194 24X Fiche 50-000,84/08/13 8408240115
- --B408240157 Safety evaluation of TDI Dwners Group program plan Based on BNML evaluation, plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc \* NRC - No Detailed Affiliation Given 84/08/13 21pp 26255 195 24X Fiche 50-000.84/08/13.8408240115
- 840Bi60375 Forwards "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets," representing final QA verified rapt Addl copy forwarded to BNML,per NRC request RAY,C L TDI (Transamerica Delaval, Inc.) Owners Group 84/08/14 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 260BB 143 24X Fiche 50-000.84/08/14.840B140375
- --B40Bi&0397 "Design Review of Elliott Model 909 Turbocharger Used on TDI DSR-48 & DBRV-16 Emergency Diesel Generator Sets " \* Failure Analysis Associates FAAA-84-75-7 84/07/31 6ipp 260BB 165 24X Fiche 50-000,84/08/14,8408160395
- 8408290179 Forwards response to 840723 request for additinfo on repts submitted by TDI Diesel Denerator Owners Group RAY: C L TDI (Transamerica Delaval, Inc.) Owners Group 84/08/23 BERLINDER, C Office of Nuclear Reactor Regulation, Director 12pp 26289 221 24% Fiche. 50-000.84/08/23,8408290179

- I Hearing transcripts on non-antitiust matters
- B40B010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Goold % M Stebert on B40514 5 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing FELTON, J M Division of Rules and Records BX14 COO 84/07/18 RICE.C M Kirkland & Ellis 2pp 26500 OO1 24X Fiche 50-329,84/07/18.8408010061
- --8408020178 Testimony of DS Hood & J Kane re matl false statement identified in NRC 791206 mod order HODD, D S . KANE, J . IRC - No Detailed Affiliation Given BX17 021 B3/01/31 3pp 26519 027 24% Fiche 50-329.84/07/18.8408010061
- --8408:30315 Testimony of JG Keppler to QA problems at facility & corrective actions taken
  KEPPLER, J G Region 3. Office of Director 8X15 012A 84/07/18
  25pp 26504 262 24X Fiche 50-329:84/07/18.8408010061
- --B408140144 Testimony of HN Singh re unresolved geotechnical engineering safety issues, including reactor bldg foundation, diesel generator bldg settlement & svc water bldg foundation & borated water tanks
  SINGH.H N Army, Dept of, Corps of Engineers BX16 016
  B4/07/18 13pp 26510 319 24% Fiche 50-329, B4/07/18, 8408010061
- --B40B170098 Testimony of RB Landsman in Glen Ellyn, IL re QA criteria & procedures to remedial foundation work underway at site LANDEMAN, R B NRC No Detailed Affiliation Given BX19 002 B2/04/19 2pp 26329 332 24X Fiche 50-329, B4/07/18, 840B010061
- --8408170292 Transcript of B Stamiris 840425 statement re soil settlement problems at plant STAMIRIS.B Q Stamiris.B BX19 041 84/04/25 3pp 26536 134 24X Fiche 50-329.84/07/18.8408010061
- --8408170277 Transcript of M Sinclair 840425 statement re problems w/util announced Dec 1986 const completion date Documentation encl SINCLAIR.M Sinclair, M BXI9 042 84/04/25 10pp 26536 137 24X Fiche 30-329,84/07/18,8408010061
- --8408170304 Transcript of T Hearron 840425 statement opposing completion.licensing & operation of plant HEARRON,T Lone Tree Council 8X19 043 84/04/25 4pp 26536 147 24X Fiche 50-329.84/07/18.8408010061
- --B40B170312 Transcript of BP Garde B40425 statement re Govt Accountability Project B40210 supplemental 10CFR2 206 patition, mgt breakdown, NRC action problems & adequate Cammission review of complex project GARDC. B P Government Accountability Project BX19 044 B4/04/25 19pp 26536 151 24X Fiche 50-329,84/07/18,840B010061
- --B40B220064 Testimony of RN Gardner re qualification of Bechtel QC personnel Certificate of Svc & related info encl GARDNER.R N Region 3. Office of Director BX19 023 82/01/22 120pp 26332 292 24X Fiche 30-329, 64/07/16.8408010061
- --B408270336 Testimony of BP Garde re Midland Nuclear Power Plant OARDE, B P Government Accountability Project BX19 021 84/02/13 22pp 26532 040 24X Fiche 50-329.84/07/16.8408010061

#### V Operator Examinations

B408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners WALKER R D Region 3. Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10,8408140426

### DOCKET 50-331 DUANE ARNOLD ENERGY CENTER

- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8408310228 Forwards scope of plant mods & projected completion dates needed to implement 840316 request for Tech Spec changes to incorporate findings of NRC SER MCGAUGHY,R W Iowa Electric Light & Power Co 84/08/24 DENTON,H Office of Nuclear Reactor Regulation, Director 3ep 26320 242 24X Fiche 50-331,84/08/24,8408310228

- F. Security, medical, emergency & fire protection plans
- BAO8050001 Forwards changes to security plan Changes withheld (ref 100FR73 21) MCGAUGHYR W Iowa Electric Light & Power Co BA/07/30 KEPPLER.J G Region 3, Office of Director 1p 25933 186 24X Fiche 50-331.84/07/30.8408050001
- B408060270 Notification or 840905 meeting w/util in Bethesda.MD to discuss util requests for addleremptions from fire protection requirements THADANI.M C Operating Reactors Branch 2 84/07/30 VASSALLO,D B Operating Reactors Branch 2 2pp 25950 298 24X Fiche 50-331.84/07/30.8408040270
- 8408070464 Advises that 840730 changes to guard training & qualification plan consistent w/provisions of 10CFR50 54(p) & acceptable
  AXELSON.W.L. Region 3. Office of Director 84/08/02 LIU.L. Iewa Electric Light & Power CO 2pp 25940 332 24X
  Fiche 50-331.84/08/02.8408070464

#### I Financial information

- 8408210256 Forwards 1983 annual repts for Iowa Electric Light & Power Co.Corn Belt Cooperative & Central Iowa Power Cooperative MCGAUGHY.R W Iowa Electric Light & Power Co 84/08/14 DENTON, H Office of Nuclear Reaction Regulation, Director 1p 26177 263 24% Fiche 50-331.84/08/14.8408210256
- --8408210263 "lowa Electric Light & Power Co. 1983 Annual Rept " LIU.L lowa Electric Light & Power Co. 83/12/31 35pp 26177 264 24% Fiche 50-331.84/08/14.8408210256
- --8408210258 "Road Ahead.Central lows Power Cooperative.Annual Rept 1983 " BISHOP.E Central lows Power Cooperative 83/12/31 25pp 26177 300 24% Fiche 50-331.84/08/14.8408210254
- --8408210272 "Corn Belt Cooperative, Annual Rept 1983 " \* Corn Belt Power Cooperative 83/12/31 32pp 26177 324 24X Fiche 50-331,84/08/14,8408210296

# J Insurance & indemnity information

- 8408030087 Forwards Endorsement 8 to NELIA Master Policy 1 SHEALK H Neuman & Holtringer 84/07/30 SALTZMAN, J D Assistant Director for State & Licensee Relations 2pp 25906 333 24X Fiche 50-331.84/07/30.8408030087
- 8408030129 Forwards Endorsements 61 & 64 to NELIA Policy NF-214 & Endorsement 50 to MAELU Policy MF-72 SHEA.K H Newman & Holtringer 84/07/30 SALTZMAN, J D Assistant Director for State & Licenses Relations 4pp 25916 125 24X Fiche 50-331.84/07/30.8408030129

## P Operating license stage documents & correspondence

- 8408020006 Application for amend to License DPR-47, allowing 18-month implementation period for radiological effluent Tech Specs & deleting App B of Tech Specs MCGAUGHY, R W Iowa Electric Light & Power Co 84/07/25 DENTON, H R Office of Nuclear Reactor Regulation, Director App 25882 302 24X Fiche 50-331,84/07/25,8408020006
- --8408020009 Proposed Change RTS-115E to radiological effluent & ETS \* Iowa Electric Light & Power Co 84/07/31 113pp 25882 308 24% Fiche 90-331,84/07/28,8408020006
- 8408030038 Responds to Generic Ltr B4-09, "Recombiner Capability Requirements of 10CFR50 44(c)(3)(i))" & NRC 840522 ltr Hydrogen recombiner capability not required based on BWR Dwners Group generic studies MCGAUCHY,R W Iowa Electric Light & Power Co 84/07/27 DENTON,H Office of Nuclear Reactor Regulation. Director 3pp 25907 060 24X Fiche 50-331.84/07/27,8408030038
- E40B160137 Forwards request for add1 info re torus attached piping analysis as part of plant-unique rept Participation of authorized representative in E40B09-10 meetings to discuss util response to issues requested VASBALLO, D B Operating Reactors Branch 2 B4/07/27 LIU.L Iowa Electric Light & Power Co. 3pp. 26126-163 24X Fichs 50-331.84/07/27.840B160137

- 8408060425 Notification of 840807-10 meetings w/utils, NUTECH, Franklin Research Ctr & BNL in San Jose CA to discuss comments resulting from post-implementation review re plant-unique analysis repts

  BEVAN.R B Operating Reactors Branch 2 84/07/31 VASSALLO.D B Operating Reactors Branch 2 ip 25937 335 244
  - Departing Reactors Branch 2 ip Fiche 50-000.84/07/31.8408060425
- B4080800B3 Rev & to "Duane Arnold Energy Ctr Inservice Testing Program " M/840801 Itr HOMARD,K E : MCGAUGHY:R W lows Electric Light & Power Co B4/08/01 DENTON.H Office of Nuclear Reactor Regulation. Director 22bpp 25943 048 24X Fiche 50-331.84/08/01.8408080083
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl I to NUREO-0933, "Prioritization of Generic Safety Issues" "Svc list encl EISENHUT, D 0 Division of Licensing 84/08/04 Consolidated Edison Co of New York, Jac 18pp 26129 238 24X Fiche 50-000.84/08/06.8408070110
- 840B130170 Forwards GE rept, "Reduced RHR Syc Water Flow & Suppression Pool Temp Response Licensing Ltr Rept " Encl replaces proprietary rept

  MCGAUGHY,R W | Iowa Electric Light & Power Co | 84/08/08 |

  Office of Nuclear Reactor Regulation, Director | Ip | 260 |

  Fiche 50-331,84/08/08.8408130170 DENTON, H 24010 030
- ---8408130173 "Reduced RHR Svc Water Flow & Suppression Pool Temp Response Licensing Ltr Rept ...
  GRIDLEY, R. L. General Electric Co. 84/07/18 5pp. 26010 031
  24X Fishs 30-331.84/08/08.8408130170
- 8408140247 Requests permanent relief from individual valve leakage testing requirements of ASME Boiler & Pressure Vessel Code. Section XI for torus-dryuell vacuum breakers Fee encl MCGAUGHY.R W lows Electric Light & Power Co. 84/08/09 DENTON:H R Office of Nuclear Reactor Regulation. Director 8pp 26053 350 24X Fiche 50-331.84/08/09.8408140247
- 8408140435 Forwards 28 oversite piping & instrumentation diagrams to facilitate NRC review of inservice testing program Aperture cards available in PDR cards available in PDR MCOAUGHY.R W lowa Electric Light & Power Co 84/08/09 DENTON,H Office of Nuclear Reactor Regulation. Director 3pp 26051 200 24X Fiche 50~331,84/08/09.8408140435
- 8408170097 Ack receipt of 830531 & 840531 GA programs Rev to SAR GA program description.per 10CF850 54(a) requirements, requested SPESBARD.R L. Region 3. Office of Director 84/08/14 LIU.L. Iowa Electric Light & Power Co. 2pp. 26119 128 24x Fiche 50-331.84/08/14.8408170099
- 8408210499 Revised application for amend to License DPR-49, revising Tech Specs to reflect administrative change MCGAUGHY,R W Iowa Electric Light & Power Co 84/08/16 DENTON, H Office of Nuclear Reacture Regulation, Director 2pp 26149 017 24X Fiche 50-331.84/08/16.8408210499
- --9408210502 Proposed Tech Specs reflecting administrative changes \* Idua Electric Light & Power Co 84/08/16 65pp 26149 019 24X Fiche 50-331,84/08/16,8408210499
- 8408240118 Application for amend to License DPR-49, consisting of proposed Tech Spec Change RTS-168, lowering setpoint for hypass of reactor scrams during turbine trips & generator load rejections at low power levels MCGAUGHY, R W I Iowa Electric Light & Power Co 84/08/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 26228.217 24x Fiche 50-031,84/08/17.8408240118
- -8408240124 Proposed Change RTS-168 to Tech Specs.correcting value of turbine first stage pressure to correspond to 30% of core power instead of 30% of turbine power \* Iowa Electric Light & Power Co 84/08/17 4pp 26228-220 24% Fiche 50-331,84/08/17,8408240118
- B408270167 Application to amend License DPR-49.revising Tech Specs to allow gower verset to 1.658 MHz Approval requested prior to startup for Cycle B Forwards NEDD-30603 & NEDC-30603-P NEDC-30603-P withheld (ref 10CFR2 790). Fee paid MCGAUGHY.R W Iowa Electric Light & Power Co 84/08/17 DENTON.H R Defice of Nuclear Reactor Regulation. Director 20pp 26244 081 24% Fiche 50-331.84/08/17.8408270167
- -8408270173 Proposed Tech Specs modified for power uprate to 1,638 nmt \* Iowa Electric Light & Power Co 84/06/30 50pp 26244 10≥ 24% Fiche 50-331.84/08/17,8408270167

- --84082/0175 'D Arnold Pouer Uprate
  BRANDON R J , GRIDLEY, R L General Electric Co NECO-10603
  84/07/31 33pp 26244 153 24% Fiche 50-331,84/08/17 8408270167
- 8408280202 Application for amend to License DPR-49.levising Tech Specs re operating limits of new bundle types.LOCA design basis. MAPLHOR & min critical power ratio for Cycle 8 reload MCGAUGHY, R k lowa Electric Light & Power Co 84/00/17 DENTON, H R Defice of Nuclear Reactor Regulation. Director 5pp 26264-067 24% Fiche 50-231.84/08/17.8409280202
- --B409280204 Proposed Tech Specs to operating limits of now bundle types. LOCA design basis MAPLHGR & min critical power ratio for Cycle B reload Cycle & Feldau \* Jawa Electric Light & Power Co : 1 24x Fiche 50-331,84/08/17,8408280202 84/08/17 19pp 26264 072
- --8408280209 App A to "LOCA Analysis Rept for Duane Arnold Energy Ctr (Lead Plant) " NEDD-21082-03 APP A 84/06/30 46pp General Electric Co NEDO-21082-03 APF A 8 244 691 24X Fiche 50-331.84/08/17.8408280202
- --8408280211 Rev O to "Supplemental Reload Licensing Submittal for Duane Arnold Atomic Energy Ctr. Unit 1.Reload 7 " LAMBERT.P A General Electric Co 2341739 ROO 84/06/30 22pp 26264 138 24X Fiche 50-331.84/08/17.8408280202
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl ETSENHUT.D © 01913100 of Licensing 84/08/20 Consolidated Edison Co of New York Inc 179p 26276 244 24% Fiche 50-000.84/08/20.8408200275
- B40B240105 Application for amend to License DPR-49, revising Tech Specs to clarify wording, correct typos & adjust testing requirements for a snubbers Fee paid MCGAUSHY, R W Inwa Electric Light & Power Co 84/08/20 DENION. H R Office of Nuclear Reactor Regulation, Director 4pp 2623 165 24X Fiche 50-331.84/08/20,8408240105
- --B408240235 Proposed Tech Specs clarifying wording correcting types & adjusting testing requirements for snubbers fower Co 84/08/20 16pp 26223 169 24X Fiche 50-331.84/08/20, B408240105
- G Inspection reports. IE Bulletins & correspondence
- 8407250229 IE Info Notice 84-37. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of 03) 84/07/27 Consolidated Edison Co of New 25865 047 24% Fiche 50-000,84/07/27,8407250229 York, Inc 119pp
- 8408070401 Informs that new sys of acknowledging receipt of licensoe correspondence re noncompliance found during insprinted effective 840920 Preprinted form will be used KEPPLER, J & Region 3, Office of Director 84/08/03 Commencealth Edison Co. 3pp 25942 188 24X Fiche 50-000,84/08/03, 8408070401
- 8408010333 TE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/04 Consolidated Edison Co. of New York. Inc. 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Mest Efficiency Requirement" Svc list encl JORDAN, EL Division of Emergancy Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 lE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fiche 50-000,84/08/08,8408070120
- 8408150004 Forwards payment of civil penalties assessed in NRC 840717 Order EA-84-9 HCGAUGHY,R W Iowa Electric Light & Power Co 84/08/09 DEYGUNG,R Director's Office, Office of Inspection and Enforcement 1p 26066 348 24% Fiche 50-331.84/08/09,8408150004

- 8408070376 IE Info Notice 84-62, "Thelapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments ' Svc list encl
- CRACE, J N Division of GA, Safeguards & Inspection Pingrams (Post B30103) 64/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24x Fiche 50-000.84/08/10.8408070376
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
- JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co. of New York, Inc. 119pp 26197 218 24% fiche 50-000,84/08/13,8408100009
- 8408100038 IE Info Notice 84-64, 'BWR HPCI Initiation Seal-In &
- Indication Sec list encl
  Indication Sec list encl
  JORDAN,E L. Division of Emergency Preparedness & Engineering
  Reaponee (Post 830103) 84/08/15 Consolidated Edison Co. of New 103) 84/08/15 Consolidated Edison Co of New 26198 093 24X Fiche 50-000.84/08/15,8408100038 104pp
- B40Bi00021 IC Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list enci
  - list enti JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021
- 8408100055 IE Info Notice 84~66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 24276 001 24X Fiche 50-000.84/08/17.8408100055
- 840B14020B IE Info Notice 84-67. "Recent Shubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of Nev York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,840814020 103) 84/08/17 Consolidated Edison Co of New 26276 122 24% Fiche 50-000,84/08/17,8408140208
- 8408240343 Ack receipt of \$20,000 check in full payment of civil penalties imposed on 840717 Corrective action will be axamined during future insp AXELRAD, J A Enforcement Staff 84/08/20 LIU.L Iowa Electric Light & Power Co 2pp 26253 313 24X Fiche 50-331.84/08/20. 8408240343
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated field Wiring to Solenoid Valves " Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of No 26329 008 24% Fiche 50-000, 84/08/21, 8408R10142 Inc 115рр
- A Periodic operating reports & related correspondence
- 8408230429 Monthly operating rept for Jul 1984 W/840815 1tr PUTMAN,K S. MINECK,D L. lowa Electric Light & Power Co 8pp 26213 056 24% Fiche 50-331,84/07/31,8408230429 84/07/31
- 8 Reportable occurrences. LERs & related correspondence
- B40B240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated SHERWODD, G G General Electric Co 84/04/13 DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24% Fiche 50-000,84/04/13,8408240348
- 8408240172 LER 84-029-00 on 840718, standby liquid control sys (SBLC) isolated for 5 h after inproper manipulation of common suction value from SBLC tank to SBLC pumps Caused by personnel error Procedures & training revised W/840815 ltr MARRIB, M S . MINECK, D L Iowa Electric Light & Power Co 84/07/17 pp 26236 244 24% Fichs 50-331.84/07/17,8408240172
- 8408040141 LER 84-024-00 on 840630, w/reactor critical & plant in startup mode, isolation valve on inlet line to reactor water cleanup sys automatically closed Caused by noise in reactor water cleanup sys H/840730 ltr
  PUTNAM, K B , MINECK, D L lowa Electric Light & Power Co 84/07/30
  3pp 25932 250 24X Fichs 50-331,84/07/30,8408060141
- 840816026: LER 84-027-00 on 840712.w/standby filter unit B inoperable due to inoperable radiation monitor.filter unit A failed to function during testing Caused by malfunction of air pilot positioner Monitors will be replaced W/840810 ltr
  KEITH.W R. MINECK.D L Jowa Electric Light & Power Co 26104 181 24X Fiche 50-331,84/08/10,8408140241

- or 8160471 LER 84-027-00 on 840712 sperious reactor scram occurred due (\*\*\*O1004\*). Let M4-02/-00 on 840/12. Spurious reactor Stram 0 to jarring of instrument rack in reactor bldg Caused by Lonst of scaffolding adjacent to instrument rack 10-36 Malticolored demarcation painted on floor W/800810 ltr MILLER, W J , MINECK, D L | Jowa Electric Light & Power Co 3pp 26107 286 24% Fiche 50-331,84/08/10.8408160471
- 8408220202 LER 84-028-00 on 840714 degraded voltage condition on offsite power grid resulted in automatic switching of essential buses from offsite to onsite power HPCI valve closed Cause unknown & under investigation H/840813 ltr FROBST. J R . MINECK.D L lowa Electric Light & Power Co. 84/6 3pp. 26188 209 24% Fiche 30-331.84/08/13.8408220202 84/08/13
- 8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl OE lacks technical info to adequately evaluate condition
  VILLA, R General Electric Co 84/08/21 ROS91.C E Director's
  Office, Office of Inspection and Enforcement 3pp 26318 327 243
- V Operator Examinations
- 8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners MALKER, R D Region 3. Office of Director 84/08/10 Michigan. Univ of Ann Arbor, MI 2pp 26051 198 24% Fiche 50-000. 84/08/10,8408140426
- DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT F Security, medical, emergency & fire protection plans
- 8408100087 Forwards objectives for 840718 full-scale emergency BAYNE, J P Power Authority of the State of New York 84/05/ MURLEY, T E Region 1. Office of Director 10pp 25995 353 Fiche 50-333,84/05/07.8408100087
- ---B408100105 "Emergency Response Plan Exercise Manual for JA Fitzpatrick Nuclear Power Plant " otlear Fouer Authority of the State of New York 84/07/18 4pp 5995 360 24X fiche 50-333.84/05/07.8408100087 25995 360
- B408030209 Forwards IE Insp Rept 50-333/84-10 on 840521-25 No violations noted Items of concern listed in App A BELLANY,R Region i Office of Director 84/07/03. FITZPATRICK,J Power Authority of the State of New York 4pp 25917 137 24X Fiche 50-333.84/07/03.8408030209
- ---940B030221 IE Insp Rept 50-333/84-10 on 840521-25 No violations noted Major areas inspected followup insp of items from prior insp & routine IE insp modules on emergency detection & Classification

  HANAHURST, J J COHEN. I , CROCKER. H W Region 1, Office of
  Director 84/06/15 7pp 25917 141 24X Fiche 50-333.84/07/03.8408033209
- 8408070015 Advises that 800930 description of proposed mads to ensure containment isolation single failure proof during purging satisfies requirements of Item II E 4 1 of NURE6-0737, based on completion of mods by 850701

  VASSALLD, D B Operating Reactors Branch 2 84/07/26 BAYNE, J P
  Power Authority of the State of New York 3pp 25956 204 24X
  Fiche 50-333.84/07/26.8408070015
- 0408270538 Forwards Insp Rept 50-333/84-08 on 940501-31 No violations notes STAROSTECKI.R Division of Project & Resident Programs 84 MCMEILL.C A Power Authority of the State of New York 2pp 26256 114 24X Fiche 50-333,84/08/03,8408270538
- --9408270541 Insp Rept 50-333/84-08 on 840501-31 No violations noted Major areas inspected licensee action on previous insp findings.LER review-operational safety verification & surveillence & maint observations
  DOERFLEIN.L T, COLLING.S J Region I. Office of Director 84/08/02 10pp 26254 116 24X Fiche 50-333.84/08/03.8408270538
- P Operating license stage documents & correspondence
- 8408010140 Notification of B40613 meeting w/util, Teledyne, Franklin Research Ctr.BNL, MIT & Princeton Univ in Waltham, MA to discuss NRC comments re post-implementation review of plant-unique analysis rept
  ABELBON, H I Operating Reactors Branch 2 84/05/24 VASSALLO, D 8 Operating Reactors Branch 2 1p 25873 307 24X
  Fiche 50-333,84/05/24,8408010140

- 8408030080 Forwards request for addl info re safety relief valve & torus attached piping sys.per Mark I containment long-term program Response requested within 30 days VASSALLO, D.B. Operating Reactors Branch 2 84/07/24 BAYNE, J.P. Power Authority of the State of New York 3pp 25917 346 24X Fiche 50-333,84/07/24,8408030080
- 8408010319 Forwards application to amend License DPR-59, changing Tech Specs re NUREG-0737, Item II K 3 18, "Mod of Automatic Depressurization Sys Logic Feasibility for Increased Diversity for Some Event Sequences "
  BAYNE, J P Power Authority of the State of New York 84/07/25 VASSALLO, D B Operating Reactors Branch 2 2pp 25866 129 24X Fiche 50-333,84/07/25,8408010319
- --8408010321 Application to amend License DPR-59, changing Tech Specs re NUREG-0737. Item II K 3 16. "Mod of Automatic Depressuriation Sys Logic - Feasibility for Increased Diversity for Some Event Sequences " BAYNE. J P Power Authority of the State of New York 84/07/24 3pp 25866 131 24X Fiche 50-333.84/07/25.8408010319
- --B408010322 Proposed Tech Spec changes re NUREG-0737.item II K 3 18 covering implementation of automatic depressurization sys logic mods

  \* Power Authority of the State of New York 84/07/25 10pp 25866 134 24X Fiche 50-333.84/07/25.8408010319
- 8408070417 Forwards application for amend to License DPR-59, changing Tech Specs to modify surveillance requirements for safety-related hydraulic & mechanical snubbers BAYNE.JP Power Authority of the State of New York 84/07/27 VASSALO.D B Operating Reactors Branch 2 2pp 25942 033 24X Fiche 50-333.84/07/27.8408070417
- --B40B070423 Application for amend to License DPR-59, changing Tech Specs to modify surveillance requirements for safety-related hydraulic & mechanical snubbers BAYNE.JP Power Authority of the State of New York 84/07/27 ip 25942 035 24X Fiche 50-333,84/07/27,8408070417
- --8408070428 Proposed Tech Specs.modifying surveillance requirements for safety-related hydraulic & mechanical snubbers

  \* Power Authority of the State of New York 84/07/27 16pp 25942 036 24X Fiche 30-333,84/07/27,8408070417
- B408070344 Advises of correction to Bi0512 response to request for addlentor containment vent & purge valves Fisher Controls confirms valves have off-set discs Investigation in progress
  BAYNE.JP Power Authority of the State of New York 84/08/02
  VASSALLO,D B Operating Reactors Branch 2 2pp 25945 126 24X
  Fiche 50-333.84/08/02.8408070344
- 8408150609 Forwards Amend 82 to License DPR-59 & safety evaluation Amend revises surveillance testing frequency for unit coolers serving ECCS components ABELSON.H I Operating Reactors Branch 2 84/08/03 BAYNE.J P Power Authority of the State of New York 2pp 26106 054 24X Fiche 50-333.84/08/03.8408150609
- --84081506i3 Amend 82 to License DPR-59, revising surveillance testing frequency for unit coolers serving ECCS components VASSALLO.D B Operating Reactors Branch 2 84/08/03 4pp 26106 036 24X Fichs 50-333,84/08/03,8808150609
  - 840Bi506i5 Safety evaluation supporting Amend 82 to License DPR-59 \* Office of Nuclear Reactor Regulation, Director 84/08/03 3pp 26106 060 24% Fiche 50-333.84/08/03.8408150609
- OBO70110 Generic Ltr B4-19 to all licenses of operating reactors, applicants for DLs & holders of CPs re availability of Suppl 1 to NUMEG-0933. "Prioritization of Generic Safety Issues." Svc list encl EISCN-U.T.D © Division of Licensing 84/08/06. Consolidated EISCN-U.T.D © Division of Licensing 84/08/06. Consolidated Edison Co of New York. Inc. 18pp. 26129 238 24X Fiche 50-000.84/08/06.8498070110
- 3408220224 Forwards addl info re Mark I program Documentation resolves all open items discussed at 840713 meeting w/exception of justifying 111 F pool temp for Case C3 2, which will be addressed in separate Itr
  BAYNE, J P Power Authority of the State of New York 84/08/14
  VASSALLO, D B Operating Reactors Branch 2 16pp 26188 266 24X
  Fiche 50-333,64/08/14,6408220224
- MOB200275 Generic Ltr 84-20 to all licenses of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT, D © Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fichm 50-000,84/08/20,8408200275

- 8408240145 Requests 6C-day extension of time after next refueling outage for response to 840702 Genetic Ltr 84-15 requesting inforce current programs to avoid cold fast start surveillance tests & diesel generator reliability data BAYNE. J P Power Authority of the State of New York 84/08/22 VASSALLO.D B Operating Reactors Branch 2 2pp 26227 361 24X Fiche 50-333,84/08/22.8408240145
- 8408310095 Forwards response to 840724 request for addl info re structural aspects of plant-unique analysis rept for torus attached piping BAYNE, J P Power Authority of the State of New York 84/08/24 VASSALLO, D B Operating Reactors Branch 2 5pp 26322 224 24x Fiche 50-333,84/08/24,8408310095
- Q Inspection reports, IE Bulletins & correspondence
- 8408030209 Forwards IE Insp Rept 50-333/84-10 on 840521-25 No violations noted Items of concern listed in App A BELLAMY.R Region i. Office of Director 84/07/03 FITZPATRICK.J Power Authority of the State of New York 4pp 25917 137 24X Fiche 50-333.84/07/03.8408030209
- --B408030221 IE Insp Rept 50-333/84-10 on 840521-25 No violations noted Major areas inspected followup insp of items from prior insp & routine IE insp modules on emergency detection & classification MAWXHURST, J J. CROCKER, H W Region 1, Office of Director B4/06/15 7pp 25917 141 24% Fiche 50-333,84/07/03.
- B40B150493 Forwards IE Insp Rept 50-333/84-11 on 840618-22 No violations noted MARTIN.T T Division of Engineering & Technical Programs B4/07/26 MCNEILL.C A Power Authority of the State of New York 2pp 26077 147 24X Ficho 50-333.84/07/26.8408190453
- --B408150455 IE Insp Rept 50-333/B4-11 on 840618-22 No violations noted Major areas inspected near-term followup of responses to Generic Ltr 83-28 equipment classification, post-maint testing & vendor interfaces HARPSTER.I L. NAPUDA.G. GODY, A.T. Region 1, Office of Director 84/07/20 Bpp 26077 149 24X Fiche 50-333,84/07/26,8408150453
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safoty-Related Electrical Equipment at Commercial Power Plants "Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc. 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229
- 840B150537 Forwards IE Insp Rept 50-333/84-09 on 840521-25 & notice of violation MARTIN,T T Division of Engineering & Technical Programs 84/07/27 MCNEILL,C A Power Authority of the State of New York 2pp 26079 026 24X Fiche 50-333,84/07/27,8408150537
- ---8408150539 Notice of violation from insp on 840521-25 \* Region 1. Office of Director 84/07/27 ip 26079 028 24x Fiche 50-333,84/07/27,8408150537
- --8408150541 IC Insp Rept 50-333/84-09 on 840521-25 Violations noted failure to have written procedures for waste classification & manifest preparation HDGAN, R. PASCIAK, W.J. Region 1. Office of Director 84/07/20 App 26079 027 24X Fiche 50-333,84/07/27,8408150537
- 0408270538 Forwards Insp Rept 50-333/84-08 on 840501-31 No violations noted STAROBIECKI,R Division of Project & Resident Programs 84/08/03 MCNEILL,C A Power Authority of the State of New York 2pp 26256 114 24X Fiche 50-333,84/08/03,8408270538
- --8408270941 Insp Rept 50-333/84-08 on 840301-31 No violations noted Major areas inspected licensee action on previous insp findings. LER review. operational safety verification & surveillance & maint observations
  DDERFLEIN.L T. COLLING, S.J. Region 1. Office of Director 84/08/02 10pp 26236 116 24X Fiche 90-333.84/08/03.8408270538
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24% Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

- B408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR
  Refueling Cavity "Svc list encl
  JORDAN, EL Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/08 Consolidated Edison Co of New
  York
- 8408270470 Forwards Insp Rept 50-333/84-13 on 840709-13 No violations noted MARTIN.T T Division of Engineering & Technical Programs 84/08/08 MCNEILL.C A Power Authority of the State of New York 2pp 26256 217 24X Fiche 50-333,84/08/08.8408270470
- --B408270473 Insp Rept 50-333/84-13 on 840709-13 No noncompliance noted Hayer areas inspected nonradiological chemical program, including GC of analytical measurements, analytical procedures, staffing & training ZIBULSKY, H., PABCIAK, W.J. Region 1, Office of Director 84/08/07 3pp 26286 219 24X Fiche 50-333,84/08/08,8408270470
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list enc! GRACE, J N Division of GA, Safeguards & Inspection Programs (Post B30103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376
- B40B100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svr list encl
  JORDAN-E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Ca of New
  York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Smal-In & Indication" Svc list encl
  JORDAN E L Division of Emergency Preparedness & Engineering
  Response (Post B30103) 84/08/15 Consolidated Edison Co of New
  York, Inc 104pp 26198 093 24X Fiche 50-000.84/08/15,8408100038
- 8408210277 Ack receipt of 840802 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/84-10
  MARTIN, T T Division of Engineering & Technical Programs 84/08/15
  MCNEILL, C A Power Authority of the State of New York 2pp 26180 215 24X Fiche 50-333.84/08/15,8408210277
- --8408210281 Responds to NRC 840703 ltr re violations noted in IE Insp Rept 50-333/84-10 Corrective actions specialized training will be provided to shift supervisors.per Protective Action Decisionmaking EAP-118 between 841021-1201 MCNEILL.C A Power Authority of the State of New York 84/08/02 MARTIN.T T Division of Engineering & Technical Programs 5pp 26180 217 24X Fiche 50-333.84/08/15.8408210277
- 840B100021 IE Info Notice 84~65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc List encl JORDAN, E.L. Division of Emergency Preparedness & Engineering
  - list entl
    JORDAN, E.L. Division of Emergency Preparedness & Engineering
    Response (Post 830103) 84/08/16 Consolidated Edison Co. of New
    York, Inc. 118pp 26178 001 24% Fiche 50-000,84/08/16,8408100021
- 8408210424 Ack receipt of 840712 ltr informing NRC of steps taken to correct violations noted in IE Operational Assessment Team Insp Rept 50-333/82-24
  MARTIN.T T Division of Engineering & Technical Programs 84/08/16
  MCNEILL.C A Power Authority of the State of New York 2pp 26181 298 24X Fiche 50-333,84/08/16,8408210424
- --8408210436 Responds to NRC 831128 ltr re violations noted in IE
  Operational Assessment Team Insp Rept 50-333/82-24
  Corrective actions administrative records mpt policy
  revised & records restention index complete
  BAYNE, J P Power Authority of the State of New York 84/07/12
  MURLEY, T E Region 1, Office of Director 5pp 26181 300 24X
  Fichs 50-333,84/08/16,8408210424
- 8408100055 IE Info Notice 84~66. "Undetected Unavailability of Turbina-Driven Auxiliary Feedwater Train " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000.84/08/17.8408100055
- 840B14020B IC Info Notice 94-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000.84/08/17.8408140208
- 8408210142 IE Info Notice 94-68, "Potential Deficiency in Improperly Rated Field Wiring to Solonoid Valves " Svc list enc)
  JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc. 115pp 26329 008 24X Fiche 50-000.84/08/21.8408210142

- 8408310271 Notification of Significant Licensee Meeting 84-78 on 840913 w/util at site to present results of SALP CulLINS, Division of Project & Resident Programs 84/08/22 Division of Project & Resident Programs 2pp 26351 337 24X Fiche 50-333,84/08/22,8408310271
- R Periodic operating reports & related correspondence
- 8408030287 SPDES discharge monitoring rept for Apr 1984 W/840724 ltr MCNEILL.C A Power Authority of the State of New York 84/04/30 DENTON.H R Office of Nuclear Reactor Regulation. Director App 25917 262 24X Fiche 50-333,84/04/30,8408030287
- 8408160311 Monthly sperating rept for Jul 1984 W/840806 ltr CDDK, J. MCNEILL, C.A. Power Authority of the State of New York 84/07/31 14pp 26106 131 24X Fiche 50-333.84/07/31.8408160311
- 5 Reportable occurrences. LERs & related correspondence
- 8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solonoid valve plunger Initially reported on 840413 New thread locking devices investigated SHERWODD, Q G Oeneral Electric Co 84/04/13 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 3pp 24222 256 24X Fiche 50-000.84/04/13,8408240348
- 8408030254 LER 84-013-00 on 840625, while placing main generator in syc, reactor scram occurred Gaused by high reactor pressure resulting when turbine bypass valve failed closed Hydraulic fluid filters replaced, W/840723 ltr
  LISEND, R T , NCNEILL, C A Power Authority of the State of New York 84/07/23 3pp 25917 231 24% Fiche 50-333,84/07/23,8408030254
- 8408030256 LER 84-014-00 on 840623,both inner & outer drywell entry hatch doors open,violating primary containment Caused by failure in mechanical interlock & failure of personnel to recognize integrity violated Doors shut W/840723 ltr LINBEEY.D J. MCNEILL.C A Power Authority of the State of New York 84/07/23 4pp 25917 237 24X Fiche 50-333,84/07/23,8408030256
- 8408230356 LER 84-015-00 on 840716.HPCI torus suction valve 23MOV-58 failed to open fully & declared inoperable Cause undetermined Operability surveillance successfully performed daily for 1 wk W/840815 ltr LISEMP.R T , MCNEILL.C A Power Authority of the State of New York 84/08/15 3pp 26213 196 24X Fiche 50-333.84/08/15.8408230356
- 8408240243 LER 84-016-00 on 840821, both 4 kV emergency bus undervoltage relays on 10500 bus (Div 1) found outside Tech Spec limits Cause not stated Procedure placed in new format highlighting Tech Spec requirements W/840815 ltr
  KEITH, H N , MCMEILL, C A Power Authority of the State of New York 84/08/15 4pp 26236 287 24% Fiche 50-333,84/08/15,8408240243
- B40B270144 LER 84-017-00 on 840720, remote alarm function for east cable tunnel smoke detection sign declared inoperable Hourly patrolling fire watch initiated but not performed for 2 h period Disciplinary action administered W/840B20 ltr LINDSEY, D.J. MCNEILL, C.A. Power Authority of the State of New York 84/08/20 3pp 26237 340 24% Fiche 50-333.84/08/20,840B270144
- 9406310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
  VILLA, R General Electric Co 84/08/21 ROSSI, C E Director's Office Office of Inspection and Enforcement 3pp 26318 327 24X Fiche 50-000.84/08/21.8408310186
- DDCKET 30-334 BEAVER VALLEY POWER STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- B40B0B0212 Forwards IE Insp Rept 50-334/84-15 on 840602-0706 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 84/07/17 CAREY, J J Duquesne Light Ca 2pp 25975 046 24X Fiche 50-334.84/07/17.8408080212
- --8408080213 Notice of violation from insp on 840602-0706 \* Region i, Office of Director 84/07/17 2pp 25975 048, 24X Fiche 50-334.84/07/17.8408080212
- --8408080448 IE Insp Rept 50-334/84-15 on 840602-0706 Violations noted inadequate control of station battery tests, failure to follow station equipment clearance procedures & missed surveillances
  TROSKOSKI, W M . JOHNBON, D M . TRIPP, L E Region I. Office of Director 84/07/16 16pp 25975 050 24X Fiche 50-334,84/07/17,8408080212

- 1408160266 Forwards IE Insp Rept 50-334/84-16 on 840825-28 No
- violations observed

  HARTIN.T T Division of Engineering & Technical Programs 84/07/30

  CAREY.J J Duquesne Light Co 2pp 26106 148 24x

  Fiche 50-334,84/07/30,8408160266
- --8408160272 IE Insp Rept 50-334/84-16 on 840625-28 No violations identified Major areas inspected annual full-scale emergency
  - exercise SMITH.R H . CROCKER.H W Region I. Office of Director 6pp 24106 150 24X Fiche 50-334.84/07/30.8408160264
- 3408170041 Forwards notice of environ assessment & finding of no significant impact re 831216 & 840530 applications for exemption from requirements of App R to 10CFR50 VARGA.S A Operating Reactors Branch 1 84/07/30 CAREY. J Duqueane Light Co 3pp 26135 338 24X Fiche 50-334.84/07/30.8408170041
- --8408170046 Notice of environ assessment & finding of no significant impact re 831216 & 840830 applications for exemption from 10CRF30.App R requirements for fixed suppression & detection sys.3 h rated fire barriers or 20-ft separation EXERNHUT.D 0 Division of Licensing 84/07/30 3pp 26135 341 24X Fiche 50-334.84/07/30.8408170041
- P Operating license stage documents & correspondence
- 840801021B Forwards SER re operation w/two of three reactor coolant loops Changes to proposed Tech Specs necessary N-1 loop operation does not constitute threat to public health &
  - various A. Operating Reactors Branch | 84/07/20 CAREY.J J Duquesne Light Co 4pp 25897 164 24X Fiche 50-334.84/07/20.
- --8408010221 Safety evaluation re operation w/two of three reactor coolent loops N-I loop operation acceptable \* Office of Ruclear Reactor Regulation. Director 84/07/20 26pp 25897 170 24% Fichs 50-334.84/07/20.8408010218
- 8408090515 Forwards FR notice of environ assessment & finding of no significant impact to 840625 application for exemption from requirements of App J to 10CFR50 VARGA.S.A Operating Reactors Branch 1 84/07/30 CAREY.J J Duquesne Light Co 7pp 25983 108 24X Fiche: 50-334,84/07/30,8408090515
- --B408070517 Notice of environ assessment & finding of no significant impact re 840625 application for exemption from requirements of App J to 10CFR50 concerning containment integrated leak rate test EIBENHUT.D.0 Division of Licensing 84/07/30 3pp 25983 112 24X Fiche.50-334.84/07/30.8408070515
- 408070521 Forwards FR notice of environ assetsment & finding of no signifficant impact to 831025 application & 840201 ltm requesting relief from requirements of ASME Code Section XI VARGA.8 A Deprating Reactors Branch 1 84/07/30 CAREY.J J Duquesns Light Co 4pp. 25983 116 24X Fiche 50-324,84/07/30,8408070521
- 408090524 Notice of environ assessment & finding of no significant impact re 831025 application & 840201 ltr requesting relief from requirements of ASME Code Section XI concerning Class 3 piping supports
  EIGENHUT, D Q, Division of Licensing 84/07/30 3pp 25983 120
  24X Fiche 50-334,84/07/30,8408090521
- B130436 Forwards application to amend License DPR-66, deleting ETS & ubstituting specs U/complete 1983 soil sampling & aerial hotography surveys AREV, J J Duquesne Light Co. 84/07/31 VAROA.8 A Operating eactors Branch 1 1p. 26005-344 24X Fiche 50-334,84/07/31,408130436
- 408130439 Application for amend to License DPR-66, authorizing deletion of ETB Specs will be replaced w/complete 1983 soil sampling & asrial photography surveys CAREY, J. Duquesne Light Co. 84/08/02. 2pp. 26005 345 24X Fiche 50-334,84/07/31,8408130436
- 408130441 Proposed Tech 8pecs re soil chemistry \* Duquesne Light Co 84/07/31 12pp 26005 347 24X Fiche.50-334,84/07/31,8408130436

- 8408150499 Responds to 840525 request for addl info & Generic Ltr 84-04 re 760114 & 0618 asymmetric LOCA loads analyses Util proceeding W/Fracture mechanics evaluation to demonstrate applicability to modeling CAREV. J J Duquesne Light Co 84/07/31 VAROA.S A Operating Reactors Branch 1 2pp 26079 107 24X Fiche 50-334.84/07/31. B40B150499
- 8408130554 Forwards notice of environ assessment & finding of no significant impact re 830714 & 840507 requests for exemption from 10CFR30,App J VARGA, 5 A Operating Reactors Branch 1 84/08/01 CAREY,J J Duquesne Light Co 4pp 26060 020 24X Fiche 50-334.84/08/01.
- --B408130559 Notice of environ assessment & finding of no significant impact re B30714 & B40507 requests for exemption from 10CFR50.App J for air lock leak rate test EISENUUT, D @ Division of Licensing B4/08/01 3pp 26060 024 24% Fiche 50-334.B4/08/01.8408130554
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl I to NUREG-0733, "Prioritization of Generic Safety Issues "Svc list ent! EIBENHUT,D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26127 238 24X Fiche 30-000,84/08/06,8408070110
- B40B150124 Forwards fee for B40A2B license amend application, consisting of Proposed Change Request 97, per loCrR170 Application forwarded separately SIEBER, J D Dequesne Light Co B4/0B/07 License Fee Management Branch lp 24046 354 24X Fiche 50-334.84/08/07.8408150124
- B408210058 Forwards Amend 79 to License DFR-66 & safety evaluation Amend revises Tech Specs to reflect new offsite organization M/o encis TAM,P Operating Reactors Branch 1 84/08/08 CAREY,J J Duq Light Co 1p 26195 162 24X Fiche 50-334,84/08/08,8408210058 Duquesne
- 8408200275 Generic Ltr 84-20 to all licenses of operating reactors & applicants for GLs re scheduling guidance for licenses submittals of reloads that involve unreviewed safety questions Svc list encl EISEMHUT.D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fichs 50-000,84/08/20.8408200275
- G Inspection reports. IE Bulletins & correspondence
- 8408080212 Forwards IE Insp Rept 50-334/84-15 on 840602-0706 & notice of violation

  STARQSTECKI,R Division of Project & Resident Programs

  CAREY,J J Duquesne Light Co 2pp 25975 046 24X

  Fiche 50-334,84/07/17,8408080212 84/07/17
- --8408080213 Notice of violation from insp on 840602~0706 \* Region 1, Office of Director 84/07/17 2pp 25' Fiche 50-334,84/07/17,8408080212 25975 04B 24X
- --8408080448 IE Insp Rept 50-334/84-15 on 840602-0706 Violations noted inadequate control of station battery tests, failure to follow station equipment clearance procedures & missed follow station equipment clearance procedures & missed surveillances
  TROEKOSKI,W M , JOHNSON,D M , TRIPP,L E Region 1, Office of Director 84/07/16 16pp 25975 030 24X Fiche 50-334,84/07/17,8400000212
- 8407250229 IE Info Notice 84~57, "Operating Experience re Moisture THE PROPERTY OF THE PROPERTY O
- 8408160266 Forwards IE Insp Rept 50-334/84-16 on 840625-28 No Violations observed

  MARTIN.T T Division of Engineering & Technical Programs 84/07/30

  CAREY, J Duquesne Light Co 2pp 26106 148 24X

  Fiche 30-334, 84/07/30, 8408160266
- --8408160272 IE Insp Rept 50-334/84-16 on 840625-28 No violations identified Major areas inspected annual full-scale emergency SMITH.R H , CROCKER.H H Region 1. Office of Director 6pp. 26106 150 24% Fiche 50-334.84/07/30,8408160266 84/07/24

- 8408240071 Forwards IE Insp Rept 50-334/84-17 on 840709-13 No violations noted MARTIN.T T Division of Engineering & Technical Programs 84/08/03 CAREY, J Duquesne Light Co 2pp 26237 006 24X Fichs 50-334,84/08/03,8408240071
- --8408240076 IE Insp Rept 50-334/84-17 on 840709-13 No violations noted Major areas inspected radiation protection program. including organization & mgt controls internal exposure control & assessment ALARA program & unusual event reviews DRAGBUN.T. JANG.J., SHANBAK'.M M Region 1. Dffice of Director 84/08/02 6pp 26237 008 24X Fiche 50-334,84/08/03.8408240071
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Cansolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000.84/08/06.8408010333
- B40B010337 IE info Notice B4-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list ancl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/0B/05 Consolidated Edison Co of New York, Inc. 123pp 26067 198 24X Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PHR Refueling Cavity " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fiche 50-000,84/08/08,8408070120
- 8408070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl ORACE, J N Division of QA. Safeguards & Inspection Programs (Post B30103) 84/08/10 Consolidated Edison Co of New York. Inc 125p 26130 001 24X Fiche 50-000.84/08/10.8808070376
- 840B100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "

  Svc list encl

  JORDAN, CL Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New

  York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408100038 IE Info Notice 84-64, "BWR HPC; Initiation Seal-In & Indication " Svc list enc!

  JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24% Fiche 50-000,84/08/15,8408100038
- 8408230297 Responds to addl concern re [E Bullatin 83-07 concerning apparently fraudulent natis received from Ray Miller, inc Program for random & periodic exams or tests on sample of products will be implemented by Jan 1985 CAREY, J J Duquesne Light Co 84/08/15 VAROA, 8 A Operating Reactors Branch 1 EBNFTER, 8 D Region 1, Office of Director 2pp 26208 003 24% Fiche 50-334,84/08/15,8408230279
- 8408100021 IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000.84/08/16.8408100021
- 8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- 8408140208 IE Info Notice 84~67. "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Sciencid Valves " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc 135pp 26329 008 24% Fiche 50-000.84/08/21,8408210142
- 8408270335 Discusses 840612 meeting w/util re encl SALP Repts 50-334/84-13 & 50-412/84-06 Overall assessment of performance for Unit 1 acceptable Lack of mgt control for Unit 2 identified List of meeting attendess encl MURLEY.T E Region 1. Office of Director 84/08/21 CAREY.J J Duquesne Light Co 6pp 26244 205 24X Fiche 50-334,84/08/21,8409270335

- --8408270341 Summarizes discussion at 840612 meeting re SALP Repts 50-334/84-13 & 50-412/84-06 Constructability review group for reviewing engineering output & organizational changes established CAREY, J Duquesne Light Co 84/06/29 STAROSTECKI, R Division of Project & Resident Programs 22pp 26244 285 24X Fiche 50-334,84/08/21,8408270335
- S Reportable occurrences, LERs & related correspondence
- 8408100113 LER 82-048/03L-1 on 821018, overcurrent condition detected by station svc transformer 18 primary side overcurrent relay Caused by add1 loads on associated busses Relay setting increased W/840718 ltr DRUGA: R J . LACEY.W S Duquesne Light Co 84/07/18 MURLEY.T E Region 1. Office of Director 4pp 25991 020 24% Ficho 50-334.84/07/18.8408100113
- 8408100092 LER 84-006-00 on 840621.18-month surveillance testing methods used on 120-volt dc station batteries determined inadequate Proposed Tech Spec change delaying test tentatively approved W/840720 ltr DRUGA:R J. LACEY.W S. Duqueene Light Co. 84/07/20 MURLEY.T E Region i. Office of Director 4pp 25991 004 24X Fiche 50-334.84/07/20.8408100092
- 840B210016 LER 94-008-00 on 840706 reactor shutdown bank rods tripped on pressurizer low pressure trip signal Caused by surveillance test performed w/reactor trip breakers closed Personnel counseled Procedure to be revised W/840B01 ltr DRUGA:R J. LACEY.W 8 Duquesne Light Co 84/08/01 MURLEY.T E Region 1. Office of Director 3pp 26181 332 24X Fiche 50-334.84/08/01.8408210016
- 8408210023 LER 84-007-00 on 840704, containment recirculation cooling coils chilled water sys putlet isolation valve failed shut, causing containment temp to reach 105 08 F Caused by failed pneumatic valve diaphragm W/840801 ltr DRUGA, R. J., LACEY, W. B. Duquesne Light Co. 84/08/01 MURLEY, T. E. Region 1, Office of Director 4pp 26146 161 24X Fiche 50-334.84/08/01.8408210023
- DDCKET 50-335 ST LUCIE PLANY, UNIT 1

  F Security, medical, emergency & fire protection plans
- B40BD10091 Forwards request for add1 info re procedures generation package for emergency operating procedures Response requested within 30 days of 1tr receipt MILLER. J R Operating Reactors Branch 3 84/07/17 WILLIAMS. J W Fiorida Power & Light Co 3pp 25897 054 24X Fiche 50-335.84/07/17.8408010091
- 8408010303 Forwards 8ER re alternate safe post-fire shutdown capability, in response to 830402,1007 & 840119 submittals
  Util meets App R. Section III 0 3 & III L requirements re alternate safe shutdown capability
  MYLLER, J R Operating Reactors Branch 3 84/07/17 WILLIAMS, J W Fiorida Power & Light Co. 2pp 25872 319 24%
  Fiche 50-335,84/07/17,8408010303
- --8408010306 SER re alternate safe post-fire shutdown capability, in response to 830402,1007 & 840119 submittals Util meets App R. Bection III 0 3 & III L requirements re alternate safe shutdown capability # Office of Nuclear Reactor Regulation. Director 84/07/17 7pp R5872 321 24% Fichs 50-335,84/07/17,8408010303
- 8408030126 Forwards IE Safeguards Insp Repts 50-339/84-24 & 50-389/84-26 on 840709-13 No violations or deviations nated DANCE, H G Region 2. Office of Director 84/07/30 WILLIAMS, J W Florida Power & Light Co 2pp 25916 120 24X Fiche 50-338,84/07/30.8408030126
- --B408030127 IE Bafeguards Insp Repts 50-335/B4-24 & 50-389/B4-26 on B40709-13 No noncompliance noted Major areas inspected changes to physical security plan & implementing procedures Details withheld (ref 10CFR2 790 & 10CFR73 21) TILLMAN, A. MCGUIRE, D.R. Region 2. Office of Director 84/07/27 ip 25916 122 24X Fiche 30-335.B4/07/30.8408030126
- 8408070007 Forwards response to 840605 request for add1 info re Rev 8 to physical security plan Response withheld (ref 10CFR73 21)
  HILLIAMS, J H Florida Power & Light Co 84/08/06, MILLER, J R Operating Reactors Branch 3 ip 25773 113 24X
  Fiche, 50-335,84/08/06,8408090007

- 8408100016 Forwards Emergency Plan Implementing Procedure EPIP-1301, "Emergency Roster - Offsite Emergency Organization " WILLIAMS, J W Florida Power & Light Co 84/08/08 O'REILLY, J P Region 2, Office of Director 1p 25987 006 24X
- --8408100054 Emergency Plan Implementing Procedure EPIP-1301, "Emergency Roster - Offsite Emergency Organization" JOHNSGN:H D Florida Power & Light Co 84/08/08 13pp 25987 007 24X Fiche 50-000,84/08/08,8408100016
- 8408130215 Notifies that responses to 840717 questions re procedure generation package for energoncy operating procedures, will be provided w/assistance of C-E Owners Group Procedure Subcommittee at 840829 meeting w/RRC reviewers WILLIAMS, J W Florida Power & Light Co 84/08/08 MILLER, J R Operating Reactors Branch 3 ip 26005 360 24x Fiche 50-335.84/08/08,8408130215
- 8408300303 Forwards FEMA "Exercise Rept on St Lucie Nuclear Power Plant Exercise on 840306" DANCE.H C Region 2. Office of Director 84/08/14 WILLIAMS.J W Florida Power Corp 3pp 26306 151 24X Fiche 50-335.84/08/14.
- 8408280097 Revised emergency plan implementing procedures, including 1-0970031, "Loss of SUPS-Nonsafety Vital AC or Fire & Security Inverters" & 2-0030141, "Control Room Inaccessibility " H/840822 ltr HETHY.C M Florida Power & Light Co 84/08/22 52pp 26261 128 24X Fiche 30-335.84/08/22.8408280097

### Η General correspondence

- 8408010338 Responds to 840608 request for comments & views on contents of BL Wells ltr expressing criticisms of safety re removal of thermal shield & storage capacity of spent fuel pools of nuclear power plants in State of FL DIRCKS.W J Office of the Executive Director for Operations 84/07/20 CHILES.H L Senate 6pp 25872 277 24X Fichs 50-335,84/07/20,8408010338
- --8408010340 Requests comments & views on encl BL Wells 840402 ltr CHILES,L Benate 84/06/08 KAMMERER,C Office of Congressional Affairs 1p 25872 302 24X Fiche 50-335,64/07/20,8408010338
- --8408010342 Forwards Palm Beach Post 840602 article entitled, "Error Costly at Reactor," which cites criticisms of util re removal of thermal heat shield Expresses concern re reserve capacity of spent fuel pools at all Florida nuclear plants MELLS,8 L Affiliation Not Assigned 84/06/02 PALLADINO,N Commissioners 2pp 25872 303 24X Fiche 50-335,84/07/20,8408010338
- P Operating license stage documents & correspondence
- 8408030164 Informs that complete response to 840531 request for add1 info re util 800808 ltr concerning RCS asymmetric LOCA loads evaluation expected by 841001 Delay due to detailed nature of response WILLIAMS.J W Florida Fower & Light Co 84/07/31 MILLER.J R Operating Reactors Branch 3 ip 23912 060 24X Fiche 50-335.84/07/31.8408030164
- 3408070110 Ceneric Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Buppl 1 to NUREC-0933, "Prioritization of Generic Safety Issues" Svc list encl EISENHUT.D 0 Division of Licensing 84/08/04 Consolidated Edison Co of New York, Inc. 18pp 26129 23B 24X Fiche 50-000.84/08/06.8408070110
- 8408090243 Responds to B Wright question re correlation of data on AB-inch purge valves Henry Pratt Co provided verification model testing for 48-inch RIA included model widisc structure similar to model installed at plant WILLIAMS.JW Florida Power & Light Co 84/08/06 MILLER,JR Operating Reactors Branch 3 ip 25972 169 24X Fiche 50-335,84/08/06,8408090243
- 8408160317 Forwards "Maint & Surveillance Program Plan," revised following 840706 NRC/NUMARC meeting RUSSELL, N T Division of Human Factors Safety 84/08/07 HODDY, C D Florida Power & Light Co 1p 26126 019 24X Fiche 50-000
- 8408160473 Reiterates 840404 request for remission of Class III fee for review of 830825 application resulting in Amend 65 to License PR-67, per ICCFR170 MILLER.W D License Fee Management Branch 84/08/09 WILLIAMS.J W Florida Power & Light Co. 1p 26108 352 24X Fithe 50-335.84/08/09.8408160473

- 8408170013 Notifies of Class I & II fees due for 840515 & 21 Tech Spet organizational change requests Discussion of fee requirements enci MILLER.W O License Fee Management Branch 84/08/10 WILLIAMB.J W Florida Power & Light Co 3pp 26135 347 24X Fiche 50-335.84/08/10.8408170013
- 8408230564 Notification of 840906 & O7 meetings w/util in Bethesda.MD to discuss control room design reviews MCDDNALD.D G Operating Reactors Branch i 84/08/16 VAR9A.S A , MILLER, J R Operating Reactors Branch i 2pp 26230 260 24X Fiche 50-000.84/08/16.8408230564
- 8408200273 Generic Ltr 84-20 to all licensees of operating reactors & applicants for DLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHULD 6 Division of Licensing 84/08/20 Consolidated Edison Co of New York. Inc. 17pp 26276-244 24X Fiche 50-000.84/08/20,8408200275
- @ Inspection reports, IE Bulletins & correspondence
- 8408280236 Submits results of Ebasco Svcs review of Ray Miller, Inc supplied matts, in response to IE Bulletin 83-07, per util 840404 ltr Ray Miller products not installed at facilities WILLIAMS.JW Florida Power & Light Co 84/06/01 D'REILLY,JP Region 2, Office of Director 2pp 26262 279 24X Fiche 50-333,64/06/01.8408280236
- 8408300375 Informs of incorrect rept number on 840530 rept Rept 50-389/84-18 should read 50-389/84-22 DANCE,H C Region 2, Office of Director 84/06/22 WILLIAMS.J W Florida Power & Light Co ip 26308 207 24X Fichs 50-335, 84/06/22.8408300395
- 8408280182 Informs of completion of balance of actions requested in IE Bulletin 82-02 Rept requested in Action Item 4 encl WILLIAMS.J W Florida Power & Light Co 84/06/26 O'REILLY,J P Region 2. Dffice of Director 3pp 26275 194 24X Fiche 50-335.84/06/26.8408280182
- 8408280056 Responds to IE Bulletin 84~02 re failure of GE HFA relays in Class IE safety sys All Unit i relays replaced w/Tefzel series relays & spare part specs upgraded Unit 2 relays mfg w/Tefzel species with the species with the species with the species will will be species will be species with the species will be species with the species will be species will be species will be species with the species will be species will be species with the species will be
- 8407250227 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants "Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000.84/07/27,8407250227
- 8408270192 Ack receipt of 840702 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-335/84-12 & 50-389/84-14 LEWIS, R C Division of Project & Resident Programs 84/07/27 WILLIAMS.J W Florida Power & Light Co 1p 26258 001 24X Fiche 50-335,84/07/27.8408270192
- ---8408270200 Responds to NRC 840601 ltr re violations noted in Insp Repts 50-335/84-12 & 50-389/84-14 Corrective actions calibr program under review & GA auditor counseled WILLIAMS.J W Florida Power & Light Co 84/07/02 O'REILLY.J P Region 2. Office of Director 3pp 26258 002 24X Fiche 50-335,84/07/27,8408270192
- --8408270207 Forwards Insp Repts 50-335/84-12 & 50-389/84-14 on 840423-27 & notice of violation LEMIS.R C Division of Project & Resident Programs 84/06/01 WILLIAMS.J W Florida Power & Light Co 2pp 26258 005 24X Fichs.50-335,84/07/27,8408270192
- ---8408270214 Notice of violation from insp on 840423-27 \* Region 2, Office of Director 84/06/01 2pp 26258 007 24% Fiche 50-335,84/07/27,8408270192
- --8408270221 Insp Repts 50-335/84-12 & 50-389/84-14 on 840423-27 Violations noted failure to include gauges in calibr program & failure to audit calibr program sufficiently BELIBLE, Q A , FUSTER, L E , UPRIGHT, C M Region 2, Office of Director 84/05/25 15pp 26258 009 24X Fiche 50-335,84/07/27, 8408270192

- 8408270360 Forwards Inap Repts 50-335/84-21 & 50-389/84-23 on 840610-0714 No violations or deviations noted DANCE H C Region 2. Office of Director 84/07/27 WILLIAMS, J W Florida Power & Light Co 2pp 26257 221 24X Fiche 50-335,84/07/27,8408270360
- -8408270363 Insp Repts 50-335/84-21 & 50-389/84-23 on 840610-0714 No violations noted Major areas inspected plant, surveillance & maint observations
  FEIERABEND, C D . BIBB, H E Region 2, Office of Director
  ELROD, S A Division of Project & Resident Programs 84/07/27
  4pp 26257 223 24% Fiche 50-335,84/07/27,8408270360
- 8408030126 Forwards IE Safeguards Insp Repts 50-335/84-24 & 50-389/84-26 on 840709-13 No violations or deviations noted DANCE, H C Region 2: Office of Director 84/07. Florida Power & Light Co 2pp 25916 120 24X Fiche 50-335:84/07/30:8408030126 84/07/30 WILLIAMS, J W
- -8408030127 IE Bafeguards Insp Repts 50-335/84-24 & 50-389/84-26 on 840707-13 No noncompliance noted Major areas inspected changes to physical security plan & implementing procedures Details withheld (ref 10CFR2 770 & 10CFR73 21)

  TILLMAN.A , MCGUIRE.D R Region 2, Office of Director 84/07/27 1p 25916 122 24% Fiche 50-335,84/07/30,8408030126
- 8408270291 Ack receipt of 840709 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-335/84-18 & 50-389/84-19
- 50-389/84-19
  DANCE,H C Region 2, Office of Director 84/08/02 WILLIAMS,J W Florida Power & Light Co ip 26258 178 24% Fiche 50-335, 84/08/02,8408270291
- --8408270278 Responds to NRC 840608 ltr re violations noted in Insp Repts 50-335/84-18 \$ 50-389/84-19 Corrective actions Repts 30-335/84-18 & 50-389/84-19 Corrective actions installed detectors will be replaced & two spare detectors properly calibr WILLIAMS, J W Florida Power & Light Co 84/07/09 O'REILLY, J P Region 2. Office of Director 2pp 26258 179 24X Fiche 50-335,84/08/02,8408270291
- --8408270306 Forwards Insp Repts 50-335/84-18 & 50-389/84-19 on 840514-18 & notice of violation DANCE:H C Region 2, Office of Director 84/06/08 WILLIAMS,J W Florida Power & Light Ca 2pp 26258 181 24X Fichs 50-335,84/08/02,8408270291
- --B408270310 Notice of Violation from insp on 840514-18 \* Region 2, Office of Director 84/05/08 ip 24 Fiche 50~335,84/08/02,8408270291 26258 183 24X
- --B40B270317 Insp Repts 50-335/84-18 & 50-389/84-19 on 840514-18 Noncompliance noted failure to certify proper vendor calibr of containment high-range radiation monitors prior to initial use

  WRAY, J. R. JENKING, O. R. Region 2, Office of Director 84/06/08

  App. 26258 184 24X Fiche 50-335,84/08/02,8408270291
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JDRDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New 26068 QQ1 24X Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list encl UDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity" Svc list encl JORDAN: C L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118. 24X Fiche 50-000.84/08/08.8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Syc Patients Undergoing Out-of patients. Inspection Programs (Post BRACE, J. N. Division of QA, Safeguards & Inspection Programs (Post B30103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24% Fiche 50-000.84/08/10.8408070376
- 840B100007 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Byc list encl
  JORDAN, E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,840B100009

- B40B170233 Forwards inservice insp rept.per ASME Code Bection XI WILLIAMS.J W Florida Fower & Light Co 84/08/14 EISENHUT.D G Division of Licensing 1p 26115 274 24X Fiche 50-335.84/08/14.
- --B408170237 Inservice insp rept on B30302-840516.describing exams purformed on pressure containment appurtenance for in-core instrumentation flange assembly # Florida Powor & Light Co. 84/08/09 29pp 26115 275 24X Fiche 50-335,84/08/14,8408170233
- 8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication "Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York Inc 104pp 26178 093 24X Fiche 50-000.84/08/15.8409100038
- B40B100021 IE Info Notice 84~65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc Affect Operation or Essential Electrical Equipments Office Inst encl
  JORDAN, E. L. Division of Emergency Preparedness & Engineering
  Response (Post 8:30:1073) B470B/16 Consolidated Edison Co of New
  York, Inc. 11Bpp. 26178 001 24X Fiche 50-000;84/08/16;8408100021
- B40B100095 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list ancl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- 840B14020B IE Info Notice 84-67, "Recent Shubber Inservice Testing W/ High Failure Rates " Svc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fichs 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142
- S Reportable occurrences, LERs & related correspondence
- 8408030235 LER 84-005-00 on 840426, reactor tripped due to failed MBIV Caused by failure of rupture disc in air supply to valve operator Rupture disk replaced & valve tested & returned to svc W/840725 ltr MEBT, D , WILLIAMS, J W Florida Power & Light Co 25917 190 24X Fiche 50-335,84/07/25,8408030235 84/07/25 2pp

### V Operator Examinations

840B300392 Confirms that operator who failed Section 7 of NRC senior reactor operator upgrade written exam, administered on 840619, has been prohibited from performing licensed duties O'REILLY, J P Region 2, Office of Director 84/08/13 WILLIAMS, J W Fibrida Power & Light Co 2pp 2630B 120 24X Fiche 50-335,84/08/13,8408300392

DOCKET 50-336 MILLBYONE NUCLEAR POWER STATION, UNIT 2 F Security, medical, emergency & fire protection plans

- 8408010289 Forwards IE Insp Repts 50-245/84-13 & 50-336/84-13 on 840527-0601 & notice of violation MARTINIT T Division of Engineering & Technical Programs 84/07/1 COUNBILIN 6 Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 25866 200 24X Fichs 50-245-84/07/11.8408010288
- ---B408010292 IE Insp Repts 50-245/84-13 & 50-336/84-13 on B40529-0401 Violations noted failure to adhere to Tech Spec 6 11 procedures for radiation work parmit preparation NIMIT; R L Region 1. Office of Director B4/07/02 12pp 25866 203 24X Fiche 50-245.84/07/11.8408010288
- B40B0B0353 Forwards IE Insp Repts 50-245/84-11 & 50-336/84-12 on B40506-0609 & notice of violations Also ack receipt of B40508 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-336/84-02 STAROSIECKI.R Division of Project & Resident Programs B4/07/20 COUNGIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp 25975 021 24% Fiche 50-245,84/07/20,8408080353
- --8408080403 IE Insp Repts 50-245/84-11 & 50-336/84-12 on 840506-0609 Violations noted failure to follow radiation protection procedures & fulfil station security plan commitments Safeguards info deleted SHEDLOSKI,J T Region 1, Office of Director 84/06/26 3pp. 25975 026 24X Fichs 50-245,84/07/20,8408080353

- 108190608 Forwards IE Safeguards Insp Repts 50-245/84-14 & 50-334/84-14 on 840604-08 No noncompliance nated Steps taken to correct violations discussed in 831107 & 16 ltrs verified
- taken to correct viscous account to the verified worlfied MARTIN.T T Division of Engineering & Technical Programs 84/07/27 COUNBIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26079 001 24X Fiche 50-245,84/07/27,8408150698
- -8408130693 IE Safegvards Insp Repts 50-245/84-14 & 50-326/84-14 on 840804-08 No noncompliance maked Major areas inspected security program audit & organization.testing & maint & assessment aids Safeguards info deleted (ref 10CFR2 790) NADDEN: W Region i. Office of Director 84/07/26 App 26079 003 24X Fiche 50-245,84/07/27,8408150688
- 408210494 Forwards IE Insp Repts 50-245/84-15 & 50-336/84-15 on 840611-15 & notices of violation & deviation MARTIN: T T Division of Engineering & Technical Programs 84/08/01 COUNBIL: M. G Wortheast Nuclear Energy Co (subs of Northeast Utilities), 2pp 26187 145 24X Fiche 50-245,84/08/01,8408210494
- ~8408210499 Notice of Violation from insp on 840611-15 \* Region 1, Office of Director 84/08/01 1p 26187 147 24X Fiche 50-245,84/08/01,8408210494
- -8408210496 Notice of deviation from insp on 840611-15 \* Region 1, Office of Director 84/08/01 1p 26187 14B 24X Fichs 50-245.64/08/01,8408210494
- -8408210501 IE Insp Repts 50-245/84-15 & 50-336/84-15 on 840611-15 Violations identified failure to perform surveillance testing per Tech Specs & to maintain integrity of fire harriers KRASOPDULOS, A Region 1, Office of Director 84/07/27 ip 26187 149 24X Fiche 50-245,84/08/01,8408210494
- |408160390 Forwards revised emergency plan implementation procedures, including CONI 1 02 re corporate organization for nuclear incidents & CONI 4 02 re on-call manager of radiological consequences assessment W/a encls COUNSIL.W 0 Northeast Utilities 84/08/13 Record Services Branch (Document Control Desk) 2001 26091 173 24X Fiche 50-000,84/08/13,8408160350
- 3408280171 Responds to 840712 interpretation of order confirming licenses commitments on emergency capability, focusing on Suppl 1 to NUREG-0737 requirements Integrated assessment to be conducted pending Congressional consent EISENHUT.D 0 Division of Licensing 84/08/23 COUNGIL, W G Connecticut Yankee Atomic Power Co 3pp 26279.224 24X Fiche 50-000.84/08/23,8408280171
- 408310187 Submits update to corrective actions taken re deficiencies noted during 840512 emergency preparedness exercise Emergency action level procedure revised to place greater emphasis on classification/reclassification of emergencies.

  COUNSIL.W G Connecticut Yankee Atomic Power Co COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities)

  CDUNBIL.W G Northeast Utilities 84/08/23 MURLEY.T E Region 1, 04fice of Director. 3pp 26318 330 24X Fiche 50-000,84/08/23,8408310187

## General correspondence

- OBO70321 Advises that K McCarthy should appear on license amends as appropriate state official to receive amend applications McCarthy new director of radiation control for State of CT, Dept of Environ Protection
  COUNBIL.W G. Connecticut Yankes Atomic Power Co COUNBIL.W Q
  Northeast Nuclear Energy Co (subs of Northeast Utilities)
  COUNBIL.W G Northeast Utilities 84/07/27. MILLER,J R Operating Reactors Branch 5 ip 25945:128 24X Fiche-50-000.84/07/27,8408070321
- Operating license stage documents & correspondence
- 340B070341 Clarifies Figure 7 3-1 of thermal shield damage recovery program final rept Figure shows views of core support barrel before & after milling of insp slot & crack arrestor hole COUNBIL.W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL.W Q Northeast Utilities 84/07/27 MILLER.J R Operating Reactors Branch 3 1p 25945-209 24X Fiche 30-336.84/07/27.8408070341
- #40B100063 Forwards Vols I & II of "NUSCo Thermal Hydraulic Model Qualification." for RETRAN & VIPRE COUNSIL. # @ Connecticut Yankes Atomic Power Co. COUNSIL. # @ Northeast Nuclear Energy Co (subs. of Northeast Utilities) COUNSIL. # @ Northeast Utilities. # 84/07/30 Miller.J. R Operating Reactors Branch 3 CRUTCHFIELD. D. Operating Reactors Branch 3 CRUTCHFIELD. D. Operating Reactors Branch 5 Cpp 25787 072 24X Fichs. 50-213, 84/07/30, 8408100063

- --8408100070 Vol 1 of "NUSCo Thermal Hydraulic Model Gualification (RETRAN)" \* Northeast Utilities NUSCO 140~1 84/07/30 262pp 25987 074 24X Fiche 50-213.84/07/30.8408100063
- --8400100077 Vol II of "NUSCo Thermal Hydraulic Model Qualification (VIPRE) " \* Northeast Utilities NUSCO 140-2 84/07/30 225pp 25987 336 24X Fichs 50-213,84/07/30,8408100063
- 8408070320 Ack receipt of 840608 ltr forwarding Rev 6 to 9A program topical rept,per 10CFR50 34 & 50 35 Revs acceptable MARTIN.T T Division of Engineering & Technical Programs 84/08/01 CULNSIL.N G Connecticut Yankee Atomic Power Co 2pp 23945 244 24X Fiche 50-000.84/08/01.8408070320
- B40B150232 Advises that due to extended outage in late 1983, 1984 refueling outage will not occur Next scheduled refueling outage will occur in Feb 1985 All mods scheduled for completion prior to startup following 1985 outage COUNSIL.W 6 Northeast Nuclear Energy Co. (subs of Northeast Nuclear Energy Co. (subs of Northeast Utilities) COUNSIL.W 0 Northeast Utilities 84/08/02 MILLER, JR Operating Reactors Branch 3 ip 26066 004 24X Fiche 50-396,84/08/02,8408150232
- 8408200161 Forwards Amend 96 to License DPR-65 & safety evaluation Amend changes Tech Specs to clarify frequency for visual insps & clarifies requirements for functional testing of snubbers which visually appear inoperable OBDRNE, D B Operating Reactors Branch 3 84/08/02 COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26182 177 24% Fiche 50-336,84/08/02,8408200161
- --8408200164 Amend 96 to License DPR-65, clarifying frequency for visual insps.providing requirements for functional testing of snubbers revising method of snubber listing to incorporate add1 info & clarifying testing acceptance criteria MILLER.J R Operating Reactors Branch 3 84/08/02 27pp 26182 179 24X Fiche 50-336.84/08/02,8408200161
- ---8408200167 8afety evaluation supporting Amend 96 to License DPR-65 \* Office of Nuclear Reactor Regulation, Director 84/08/02 4pp 26182 208 24X Fiche 50-336.84/08/02.8408200161
- --8408200173 "Technical Evaluation Rept on Proposed Tech Spec Changes for Inservice Surveiilance of Bafety-Related Hydraulic & Mechanical Bnubbers at Millstone Nuclear Power Station, Unit 2"

  SELAN, J C Lawrence Livermore National Laboratory FIN A-0250 UCID-1971B 83/08/18 NRC No Detailed Affiliation Given 15pp 26182 212 24X Fiche 50-336,84/08/02,8408200161
- 8408130316 Clarifies SER of Amend 95 to License DPR-65 re spacing discrepancy in reed switches in CEA position indication sys COUNSIL.W C Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W Q Northeast Utilities 84/08/03 MILLER, JR Operating Reactors Branch 3 ip 26010 328 24X Fiche 50-336, 84/08/03.8408130316
- B408070110 Generic Ltr 84-19 to all licensers of operating reactors, applicants for OLs & holders of CPs re availability of Suppl I to NUMEQ-0933, "Prioritization of Generic Safety Issues "Svc list encl EISENHUT,D Q Division of Licensing B4/08/06 Consulidated Edison Ca of New York, Inc. 18pp. 26127 238 24X Fiche 90-000,84/08/06,8408070110
- 8408200172 Forwards response to 840709 request for add1 info re inadequate core cooling instrumentation.per Generic Ltr 82-28 Comments re subcooled margin monitor.core exit thermocouples & heated junction thermocouples encl COUNSIL.W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W 9 Northeast Utilities 84/08/14 MILLER, JR Operating Reactors Branch 3 34pp 26133 025 24X Fichs 50-336.84/08/14 8408200172
- 8408270278 Requests extension until 841214 to respond to Generic Ltr 84-15 re proposed staff actions to improve & maintain diesel generator reliability Add1 time will result in more complete & concise submittal GOUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 84/08/17 EISENHUT, D G Division of Licensing 2pp 26270 342 24X Fiche 50-000,84/08/17,8408202028
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions 8vc list enci.
  EIBENNUT.D.O Division of Licensing 84/08/20 Consolidated Edison Co of New York Inc 17pp 26276 244 24X
  Fiche 90-000,84/08/20,8408200275

- a Inspection reports. IE Bulletins & correspondence
- 8408010288 Forwards IE Insp Repts 50-245/84-13 & 50-336/84-13 on 840529-0601 & notice of violation MARTIN,T T Division of Engineering & Technical Programs 84/07/11 COUNSIL,W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 25864 200 24X Fiche 50-245.84/07/11.8408010288
- --B408010292 IE Insp Repts 50-245/84-13 & 50-336/84-13 on 840529-0601 Violations noted failure to adhere to Tech Spec 6 11 procedures for radiation work permit preparation NIMITZ.R L , BHANBARY M M Region 1. Office of Director 84/07/02 12pp 25866 203 24X Fiche 50-245.84/07/11,8408010288
- 8408080353 Forwards IE Insp Repts 50-245/84-11 & 50-336/84-12 on 840506-0609 & notice of violations Also ack receipt of 840508 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-336/84-02 STANOSTECKI, R Division of Project & Resident Programs 84/07/20 COUNBIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp 25975 021 24% Fiche 50-245,84/07/20,8408080353
- --8408080403 IE Insp Repts 50-245/84-11 & 50-336/84-12 on 840506-0609 Violations noted failure to follow radiation protection procedures & fulfill station security plan commitments Safeguards info deleted SHEOLOSKY, J T , LIPINSKI, D R Region 1, Office of Director ELSASSER, T C Division of Project & Resident Programs 84/06/26 3pp 29775 026 24X Fiche 50-245,84/07/20,8408080353
- --B40B0B0414 Responds to NRC B40213 & 0409 ltrs re violations noted in IE Insp Rept 50-336/84-02 Corrective actions Instrument & Controls Procedure IC 2417M re design changes revised CDUNBIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) CDUNBIL,W O Northeast Utilities 84/05/08 MRREY,T E Region in Office of Director 5pp 25975 041 24X Fiche 50-245,84/07/20,8408080353
- B40B150107 Forwards IE Insp Rept 50-336/B4-16 on B40613-15 No violations noted MARTIN, T T Division of Engineering & Technical Programs 84/07/26 COUNSIL. W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26073 323 24X Fiche 50-336, B4/07/26, B408150107
- --B408150110 1E Insp Rept 50-336/84-16 on 840613-15 No violations noted Major areas inspected repeated failures of coolant charging pumps WOODARD, C H , ANDERSON, C J Region 1, Office of Director B4/07/12 4pp 26073 325 24X Fiche 50-336/84/07/26/8408150107
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25869 047 24X Fiche 50-000,84/07/27,8407250227
- 8408150688 Forwards IE Safeguards Insp Repts 50-245/84-14 & 50-336/84-14 on 840604-08 No noncompliance noted Steps taken to correct violations discussed in 831107 & 16 ltrs verified MARTIN.T T Division of Engineering & Technical Programs 84/07/27 COUNBIL,W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26079 001 24X Fichs 50-245,84/07/27,8408150688
- --8408150693 IE Bafeguards Insp Repts 50-245/84-14 & 50-336/84-14 on B40604-08 No noncompliance noted Mayor areas inspected. security program audit & organization, testing & maint & assassment aids Bafeguards info deleted (ref 10CFR2 790) MADDEN,W. KEIMIO,R. R. Region I. Office of Director 84/07/26 4pp 26079 003 24X Fiche 50-245,84/07/27,8408150688
- 8408100114 Responds to IE Bulletin 83-07. "Apparently Fraudulent Products Sold by Ray Miller, Inc "Entry & engineering svaluation for Millstone Unit 2 will be done by Feb 1985 refueling outage No Ray Miller products supplied at Haddam COUNSIL, N O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, N O Connecticut Yankee Atomic Power Co COUNSIL, N O Northeast Utilities 84/07/31 MURLEY, T E. Region 1, Office of Director 3pp 25988 247 24% Fiche 50-000.84/07/31.
- 8408210494 Forwards IE Insp Repts 50-245/84-15 & 50-336/84-15 on B40611-15 & notices of violation & deviation MARTIN.T T Division of Engineering & Technical Programs. B4/08/01. CDUNBIL.W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26187:145 24X Fiche 50-245,84/08/01.8408210494
- --8408R10495 Notice of violation from insp on 840611-15 \* Region 1. Office of Director 84/08/01 1p 26187 147 24X Fiche 50-245,84/08/01.8408210494

- --8408210496 Notice of deviating from insp on 840611-15 \* Region 1, Office of Director 84/08/01 ip 26187 148 24X Fiche 50-245,84/08/01,8408210494
- --B40B210501 IE Insp Repts 50-245/84-15 & 50-336/84-15 on 840611-15
  Violations identified failure to perform surveillance
  testing per Tech Specs & to maintain integrity of fire
  barriers
  KRABOPOULOS, A. PULLANI, S. V. ANDERSON, C. J. Region i. Office of
  Director 84/07/27 ip 26/87/149 24X Fiche 50-245,84/08/01,
  84/08210494
- 0408210915 Forwards IE Insp Rept 50-336/84-17 on 840626-28 No violations observed MARTIN: T Division of Engineering & Technical Programs 84/08/01 COUNSIL: W C Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26185 255 24X Fiche 50-336:84/08/01:8408210515
- --B408210517 IE Insp Rept 50-336/84-17 on 840626-28 No violations observed Major areas inspected inservice insp program & volumetric exam relief request on reactor coolant pump cast stainless steel welds (TAC 55011)
  GRAY.E H. DURR.J P. Region 1. Office of Director 84/07/20
  Spp 26185 257. 24X Fiche 50-336.84/08/01.8408210515
- 8408200161 Forwards Amend 96 to License DPR-65 & safety evaluation Amend changes Tach Bpecs to clarify frequency for visual insps & clarifies requirements for functional testing of snubbers which visually appear inoperable OBBURNE.D B Operating Reactors Branch 3 84/08/02 COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26182 177 24X Fiche 30-336.84/08/02.8408200161
- --8408200164 Amend 96 to License DPR-65, clarifying frequency for visual insps.providing requirements for functional testing of snubbers, revising method of snubber listing to incorporate add1 info & clarifying testing acceptance criteria MILLER, JR Derating Reactors Branch 3 84/08/02 29pp 26182 179 24X Fiche 50-336,84/08/02,8408200161
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN, E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York Inc 122pp 26068 001 24X Fiche 30-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 26067 138 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PHR Refueling Cavity " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08, Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche: 50-000.84/08/08.8408070120
- B40B070376 IE Info Notice 84-62, "Therapy Misedministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list encl QRACE, J N Division of OA, Safeguards & Inspection Programs (Post B30103) 840B/10 Consolidated Edison Co of New York, Inc 125p 26130 001 24X Fichs 50-000:84/08/10.8408070376
- 840B100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc. 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Syc list and JURDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co. of New York, Inc. 104pp. 26198-093 24X Fiche: 50-000,84/08/15,8408100038
- B40B100021 IE Info Notice B4-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021
- 8408210468 Ack receipt of 840702 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-336/80-11 MARTIN.T.T Division of Engineering & Technical Programs 84/08/16 CDUNBIL, W Q Northeast Nuclear Energy Co. (subs of Northeast Utilities) 2pp 26181 117 24X Fiche 50-336.84/08/16.8408210468

OB210469 Responds to NRC 810319 ltr re violations noted in IE Insp Rept 50-326/80-11 Corrective actions offstream liquid effluent monitors will be installed by 841330 CDUMSIL:W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL:W G Northeast Utilities 84/07/02 MURICEY.T E Region 1. Office of Director 2pp 26181 119 24X Fiche 50-336,84/09/16,8408210468

100055 IE Info Notice 84-66, "Undetected Unavailability of Irbine-Driven Auxiliary Feedwater Train " Svc list encl RDAN,E L Division of Emergency Preparedness & Engineering sponse (Post 830103) 84/08/17 Consolidated Edison Co of New rk, Inc 120pp 26276,001 24% Fiche 50-000,84/08/17,8408100055

1140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/gh Failure Rates " Svc list encl IRDAN.E L Division of Emergency Preparedness & Engineering ispanse (Post 830103) 84/08/17 Consolidated Edison Ca of New int, Inc 122pp 26276 122 24% Fiche 50-000,84/08/17.8408140208

210142 IE Info Notice 84-68. "Potential Deficiency in Improperly sted Field Wiring to Bolenoid Valves " Svc list encl RRDAN.E L. Division of Emergency Preparedness & Engineering sponse (Post 830103) 84/08/21 Consolidated Edison Co of New ork, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

'eriodic operating reports & related correspondence

Reportable occurrences, LERs & related correspondence

HOBOSSI LER B4-007-00 on 840703, during walk-through fire insp, while lant at 75% power, discovered door between east & west B0-volt switchgear rooms did not have required fire rating for replaced W/840730 ltr
EBLANDES, K D , MRCCZKA, E J Northeast Utilities B4/07/30 3pp 5975 290 24% Fiche 50-336, 84/07/30, 8408080531

4ET 50-338 NORTH ANNA POWER STATION, UNIT 1
Security, medical, emergency & fire protection plans

8310069 Confirms 840524 visit to Region to discuss access control at acilities
ENIS,R C Region 2, Diffice of Director 84/05/22 STEWART,W L
irginia Electric & Power Co ip 26333 342 24X
iche 50-000,84/05/22,8408310069

8310401 Forwards summary of 840524 meeting re security interface ctivities Meeting beneficial & provided better nderstanding between security staffs WIS,R C Region 2, Office of Director 84/06/06 STEWART,W L reinia Electric & Power Co 4pp 26393 311 24X che 50-000,84/06/06.8408310401

140029 Forwards corrected Page 2 to attachment to 840614 order nfirming licensee commitments to implement post-TMI lated items in Suppl i to NUREG-0737, "Requirements for ergency Response Capability" (Generic Ltr 82-33) LLER, J R Operating Reactors Branch 3 84/07/24 STEWART, W L rights Electric & Power Co. 3pp. 26061 259 24X che 50-338,84/07/24,8408140029

OBI40033 Correction to B40414 order confirming licenses commitments to Suppl 1 to NURE9-0737 Completion date for technical support ctr to be fully functional changed to B50731 MILLER.J R Operating Reactors Branch 3 84/07/24 Virginia Electric & Power Co 19 26061 263. 24X Fiche 50-338,84/07/24. 8408140029

BO70039 Forwards replacement pages to control room design review rogram plan Adoption of Westinghouse Comers Group emergency asponse guidelines as basis for task analysis & prification/vaildation sections principal changes
TEMART.W L Virginia Electric & Power Co 84/07/27 DENTON.H R Pfice of Nuclear Reactor Regulation, Director EISENNUT.D G ivision of Licensing 8pp 25949:281, 24X Fiche 50-000.84/07/27, 408070039

3070400 Forwards "VEPCO North Anna Power Station, Units 1 & 2 DCFR30.App R Rept — App A," per 840515 request Rept icludes summary comparison of 1984 App R reanalysis & util 20622 post-fire safe shutdown review [EWART.N L Virginia Electric & Power Co 84/07/27 DENTON, H R Pfice of Nuclear Reactor Regulation, Director MILLER, J R ierating Reactors Branch 3, 3pp 2542 171 24% iche.50-338,84/07/27.8408070400"

- --8408070406 "VEPCO North Anna Power Station, Units 1 & 2 10CFR50, App R Rept - App A " \* Virginia Electric & Power Co 84/06/30 17pp 25942 194 24x Fiche 50-33B, 84/07/27, 8408070400
- B40B02002B Forwards lists of mods & revised schedules re 10CFR50 48, App R reanalysis Compensatory measures for mods specified Completion of App R reanalysis scheduled for B40B12 STEWART, W. L. Virginia Electric & Power Co. B4/07/31 DENTON, H.R. Office of Nuclear Reactor Regulation, Director EISENHUT, D.G. Division of Licensing 9pp 258B0 265 24X Fiche 50-338,84/07/31,840B0202B
- 8408130394 Ack receipt of 840710 & 0801 ltrs informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 30-338/84-18 & 30-339/14-18 LEWIS.R C Division of Project & Resident Programs 84/08/09 STEWART.W L Virginia Electric & Power Co ip 26010 124 24x Fiche 50-338.84/08/09.8408130394
- --B40B130400 Responds to NRC 840611 ltr re violations noted in IE Safeguards Insp Repts 50-338/84-18 & 30-339/84-18 Corrective actions withheld (ref 10CFR73 21) STEMART,W L. Virginia Electric & Power Co 84/07/10 O'RETLLY,J P Region 2, Office of Director 1p 26010 125 24X Fiche 50-338,84/08/09,8408130374
- --8408130403 Suppls response to NRC 840611 ltr re violations noted in IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 Corrective actions withheld (ref 10CFR73 21) STEWART.N L Virginia Electric & Power Co 84/08/01 D'REILLY.J P Region 2. Defice of Director 1p 26010 126 24X Fiche 50-338.84/08/09.8408130394
- --8408130408 Forwards IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 on 840521-25 & notice of violation Notice of violation withheld (ref 100FRZ 790 & 100FR73 21) LEWIS.R C Region 2, Office of Director 84/06/11 STEWART.W L Virginia Electric & Power Co 2pp 26010 127 24X Fiche 50-338.84/08/09,8408130394
- --8408130418 IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 on 840521-25 Noncompliance noted in area of access control for personnel Details withheld (ref 100FR2 790 & 100FR73 21) ENNIS, J D. NGGUIRE, D R. Ragion 2, Office of Director 84/04/08 1p 26010 127 24X Fiche 50-338,84/08/09.8408130394
- 8408130433 Ack receipt of 840727 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 30-338/94-25 t 50-339/64-25 LEWIS.R C Division of Project & Resident Programs 84/08/09 BTEWART,W L Virginia Electric & Power Co 1p 26005 337 24X Fiche 30-338.84/08/09.8408130433
- --B408130438 Responds to NRC 840627 ltr re violations noted in IE Safeguards Insp Repts 50-338/84-25 & 50-339/84-25 Corrective actions withheld (ref 10CFR73 21) STEWART.W L. Virginia Electric & Power Co B4/07/27 O'AEILLY.J P Region 2, Office of Director ip 26005 340 24X Fiche 50-338.84/08/09,8408130433
- --8408130443 Forwards IE Safeguards Insp Repts 50-338/84-25 & 50-339/84-25 on 840606 & notice of violation Notice of violation withheld (ref 100FR2 790 & 100FR73 21)
  LEWIS.R C Region 2. Office of Director 84/06/29 STEWART.W L
  Virginia Electric & Power Co 2pp 26005 341 24X
  Fiche 50-338,84/08/09,8408130433
- --8408130446 IE Safeguards Insp Repts 50-338/84-25 & 50-339/84-25 on 840606 Violation noted re access to vital area Details withheld (ref 10CFR2 770 & 10CFR73 21) HALL.8 L : MCGUIRE.D R Region 2. Office of Director 84/06/26, 1p 26005 343 24X Fiche 50-338.84/08/07.8408130433
- B40B200387 Advices that program plan for conducting detailed control room design review meets intent of Suppl 1 to NUREO-0737 Listed areas should be described in summary rept expected 850B30 VAROA:8 A Licensing Branch 1 84/08/10 STEWART.W L Virginia Electric & Power Co 2pp 26141 215 24X Fiche 30-000,84/08/10,8408200387
- 8408290330 Forwards Safeguards Insp Repts 50-338/84-31 & 50-339/84-31 on 840805-10 No violations or deviations noted Repts withheld (ref 10CFR2 790 & 73 21)

  DANCE.H C Division of Project & Resident Programs 84/08/27 STEWART.W L Virginia Electric & Power Co 2pp 26289 345 24X Fiche 50-338,84/08/27,8408290330

#### Q Adjudicatory correspondence

- 8408010250 Informs that util t NRC intend to file response to objectionable contentions by 840817. based on discussions w/parties
  DOUGHERTY, J B Dougherty, J B DOUGHERTY, J B Concerned Citizens of Louisa County, VA DSB 665 84/07/30 MDLFE.S J, FERGURORN, G A , KLINE, J Atomic Safety and Licensing Board Panel 10pp 25854 342 24X Fiche 50-338,84/07/30,8408010250
- 8408150464 Response to 840730 third draft of contentions of Concerned Citizens of Louisa County All but Contention 4 should be denied Certificate of Svc encl MAUPIN, M W Virginia Electric & Power Co MAUPIN, M W Hunton & Hilliams DSB 056 84/08/14 Atomic Safety and Licensing Board Panel 3ipp 26068 163 24X Fiche 50-338.84/08/14,8408130464
- 8408200477 Forwards response to contentions of Concerned Citizens of Louisa County W/o encl Related correspondence MAUPIN.M W Hunton & Williams MAUPIN.M W Virginia Electric & Power Co DSB 157 84/08/14 Docketing & Services Branch 1p 26136 306 24% Fiche 50-338.84/08/14.8408200477
- 840B200587 Forwards NRC response to Concerned Citizens of Louisa County third draft of contentions Request by NRC for i-day extension in date for filing response granted by Chairman Molfe LENIS, S H Hearing Branch 2 DSB 173 84/08/15 MOLFE, B J , KLINE, J , FERGUSON, 6 A Atomic Safety and Licensing Board Panel 1p 24137 140 24X Fiche 50-338,84/08/15,8408200587
- ---B408200593 Response to Concerned Citizens of Louisa County third draft of contentions Certificate of Svc encl MCGURREN, H J Hearing Branch I LEMIS, B H Hearing Branch 2 B4/08/15 Atomic Safety and Licensing Board Panel 15pp 26137 141 24X Fiche 50-338,84/08/15,8408200587
- B40B300129 Response supporting admission of Concerned Citizens of Louisa County B40B14 revised Contention 4 Certificate of Svc encl HABBELL,D F Hearing Branch 1 DBB 3BO 84/0B/27 Atomic Safety and Licensing Board Panel 4pp 26304 358 24X Fiche 50-33B,84/0B/27,840B300129
- 8408300177 Response to Concerned Citizens of Louisa County,VA (CCLC) revised Contention 4 re-physical protection sys for spent fuel shipments Protective order necessary for CCLC access Certificate of Svc encl MAUPIN.M W Virginia Electric & Power Co MAUPIN.M W Hunton & Williams DS 384 84/08/27 Atomic Safety and Licensing Board Panel 14pp 26305 343 24X Fiche 50-338.84/08/27,8408300177
- 8408310150 Forwards applicant response to Concerned Citizens of Louisa County, Whrevised Contention 4 W/o encl Related correspondence MAUPIN, M W Hunton & Williams MAUPIN, M W Virginia Electric & Power Co DBB 414 84/08/27 Docketing & Services Branch tp 26322,202 24% Fiche 50-338,84/08/27,8408310150
- 8408310148 Order scheduling supplemental special prehearing conference on 840907 in Bethesda: MD & directing participants to appear Served on 840830 MOLFE, S J Atomic Safety and Licensing Board Panel DSB 392 84/08/28 Office of the Executive Legal Director 3pp 26380-358 R4X Fiche 50-338.84/08/88.8408310148

### P Operating license stage documents & correspondence

- 8408303349 Confirms 840501 telcon ω/HC Dance re 840510 mgt meeting in Region II ofc to discuss organizational structure LEWIS.R C Region 2. Office of Director 84/05/07 STEWART.W L Virginia Electric & Power Co 1p 26308 230 24X Fiche 50-000,84/05/07.8408300369
- 840B130223 Forwards safety evaluation re util 931104 response to Generic Ltr 83-28.ltem 4 3. "Reactor Trip Sys Reliability " Design mods acceptable MILLER, J R Operating Reactors Branch 3 84/07/24 STEHART, W L Virginia Electric & Power Co 2pp 26058 313 24X Fiche, 50-338, 84/07/24.8408130223
- --9408130226 Safety evaluation supporting licensee response to Generic Ltr 63-28, Item 4 3, "Reactor Trip Sys Reliability " Design mods acceptable \* NRC - No Detailed Affiliation Given 84/07/24 10pp 26059 315 24X Fiche 50-338,84/07/24,8408130223

- 8408140063 Forwards comments & questions for review & requests site visit to further discuss inservice testing program NRR should be contacted in approx 4 wks to confirm time & date for meeting MILLER, J R Operating Reactors Branch 3 84/07/24 STEWART, W L Virginia Electric & Power Co 9pp 26061 267 24% Fiche 50-338,84/07/24.8408140063
- 8408090235 Application for amends to Licenses NPF-4 & NPF-7, revising Tech Spacs re limiting conditions for operation & surveillance requirements consistent w/8TS STEWART.W L Virginia Electric & Power Co 84/08/01 DENTON.H R Office of Nuclear Reactor Regulation. Director MILLER, J R Operating Reactors Branch 3 4pp 25972 141 24X Fiche 50~338.84/08/01.8408090235
- --8408090239 Proposed Tech Spec changes re limiting conditions for operation & surveillance requirements, to provide consistency w/BTS

  \* Virginia Electric & Power Co 84/08/01 7pp 25972 145 24X Fiche 50-338.84/08/01,8408090235
- 8408070441 Notification of 840803 meeting w/util in Bethesda.MD to discuss compensatory measures for addressing nonquelification point on ductuort inside containment ENGLE.L B Operating Reactors Branch 3 84/08/02 MILLER.J R Operating Reactors Branch 3 2pp 25782 354 24X Fiche 50-338.84/08/02.8408070441
- 8408090149 Provides upgraded in-core thermocouple implamentation schedule, per 840221 commitment Util proposes to complete Reg Guide 1 97 (ref NUREO-0737, Item II F 2) mods prior to or during 1986 refueling outages STEWART.W L. Virginis Electric & Power Co. 84/08/03 DENTON, H R Office of Nuclear Reactor Regulation. Director EISENHUT, D G Division of Licensing 2pp 25973 122 24X Fishe 50-33B, 84/08/03, 84A08/03/04
- BAOBO7011D Generic Ltr 84-19 to all licensess of operating reactors, applicants for OLs & holders of CPs re availability of Buppl 1 to NUREO-0933, "Prioritization of Generic Safety Issues" Svc list encl EIBENHUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000,84/08/06,8408070110
- 84082105/5 Summary of 840803 meeting w/util in Bethesda, MD re nonqualified paint inside containment List of attenders & agenda encl ENQLE-L B Operating Reactors Branch 3 84/08/13 MILLER, J R Operating Reactors Branch 3 20pp 26195 226 24x Fiche 50-338,84/08/13,8408210575
- 8408170300 Requests relief from ASME hydrostatic testing requirements
  No leakage observed from welds on both sides of new valves
  during recent pressure test of reactor containment
  STEWART:N L Virginia Electric & Power Co B4/08/14 DENTON, H R
  Office of Nuclear Reactor Regulation. Director MILLER, J R
  Operating Reactors Branch 3 Spc 26115 070 24X
  Fiche 50-338,84/08/14,6408170300
- 8408210132 Forwards Generic Ltr 84-15 response achedule, listing 840928 & 850131 as projected dates Justification for extension of responses included STEWART.W L Virginia Electric & Power Co 84/08/16 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D & Division of Licensing 3pp 24181 348 24X Fiche 50-000,84/08/16,8408210132
- B40B210375 Forwards B&W summary technical repts of first capsule from reactor vessel surveillance program.per App H of 10CFR50 Repts delayed due to administrative oversight BTEWART.W L. Virginia Electric & Power Co. 84/08/16 DENTON.H R. Office of Nuclear Reactor Regulation, Director ip 26178 001 24) Fiche 50-338.84/08/16.8408210375
- --8408210387 "Analysis of Capsule V, VEPCO, North Anna Unit 2, Reactor Vessel Matls Surveillance Program " LOME, A L., COLLINS, L L., PAVINICH, W A Babcock & Wilcox Co BAM-1794 83/10/31 173pp 26178 002 24% Fiche 30-338, 84/08/16,8408210375
- --B408210393 "Analysis of Capsule V.VEPCD.North Anna Unit i,Reactor Vessel Matts Burveillance Program " LOWE, A L . PAVINICH, W A . SCHMOTZER, J K Babcock & Wilcox Co BAN-1638 81/05/31 76pp 26178 099 24X Fiche 50-338,84/08/16, 8408210375

- 8408200275 Generic Ltr B4-20 to all licensees of operating reactors & applicants for OLs rescheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list enci EISENHUT.D © Division of Licensing 84/08/20 Consolidated Edison Co of New York Inc 17pp 26274 244 24X Fiche 50-000,84/08/20,8408200275
- G Inspection reports, IE Bulletins & correspondence
- B408270387 Forwards Insp Repts 50-338/84-24 & 50-339/84-24 on B40618-22 No violations or deviations noted DANCE.H C Region 2. Office of Director 84/07/11 STEWART.W L Vinginia Electric & Power Co 2pp 26256 278 24X Fiche 50-338,84/07/11.8408270387
- ---B408270388 Insp Repts 50-338/84-24 & 50-337/84-24 on B40619-22 No Violations or deviations noted Major areas inspected plant chemistry & employee concerns ROSS, W J . BLAKE, J J Region 2. Office of Director B4/07/09 15pp 26286 280 24X Fiche 50-338,84/07/11,8408270387
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Bafety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
  JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc. 119pp 25865-047 24X Fiche 50-000.84/07/27, 8407250229
- 8408020041 Forwards insp fees for Surry Power Station & North Anna, Unit i for Mar 1983 - Mar 1984 & North Anna, Unit 2 for Apr 1983 - Apr 1984 STEMART, W. L. Virginia Electric & Power Co. 84/07/27 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ip 25880 304 24X Fiche 50-000, 84/07/27, 8408020041
- 8408280150 Responds to 16 Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class is Safety Sys " All GE Type HFA relays in safety-related applications will be replaced STEWART.W L Vinginia Electric & Power Co 84/07/31 O'REILLY, J P Region 2. Office of Director 4pp 26259 082 24x Fithe 50-000.84/07/31.8408280150
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consultidated Edison to of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IE info Notice 84-61, "Overexposure of Diver in PWR Refueling Covity" Evc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York, Inc. 120pp 26127 118 24X Fiche 50-000,84/08/08,8408070120
- 8408130394 Ack receipt of 840710 & 0801 ltrs informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 LEMIS, R C Division of Project & Resident Programs 84/08/09 BTEWART, M L Virginia Electric & Power Co ip 26010 124 24X Fiche 50-338.84/08/09.8408130394
- --B408130400 Responds to NRC B40611 ltr re violations noted in IE Bafeguards Insp Repts 50-338/B4-18 & 50-339/B4-18 Corrective actions withheld (ref 100FR73 21) BTEWART.W L Virginia Electric & Power Co. B4/07/10 O'REILLY,J P Region 2, Office of Director ip 26010 125 24X Fiche 50-338,84/08/09,8408130394
- --8408130403 Suppls response to NRC 840611 ltr re violations noted in IE Bafeguards Insp Repts 50-338/84-18 & 50-339/84-18 Corrective actions withheld (ref 10CFR73 21) STEWART,W L. Virginia Electric & Power Co. 84/08/01 O'REILLY, J.P. Region 2. Office of Director. 1p. 26010-126 24X Fiche 50-338,84/08/09,8408130394
- -8408130408 Forwards IE Bafeguards Insp Repts 50-339/84-18 & 50-339/84-18 on 840521-25 & notice of violation Notice of violation withheld (ref 100FR2 790 & 100FR73 21), LEWIS, R. C. Region 2, Office of Director 84/06/11 STEWART, W. L. Virginia Electric & Power Co. 2pp 26010.127 24X Fiche 50-338,84/09/07,8408130394

- --8408130418 IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 on 840521-25 Noncompliance noted in area of access control for personnel Details withheld (ref 10CFR2 790 & 10CFR23 21) ENNIS.J D., MCOUIRE.D R. Region 2. Office of Dijector 84/06/08 19 26010 129 24X Fiche 50-338.84/08/09.8408130394
- B408130433 Ack receipt of 840727 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-338/R4-25 & 50-339/R4-25 LEWIS.R C Division of Project & Resident Programs 84/08/09 STEWART.W L Virginia Electric & Power Co 1p 26005 339 24X Fiche 50-338, 84/08/09.8408130433

- --8408130446 IE Bafeguards Insp Repts 50-338/84-25 & 50-339/84-25 on 840606 Violation noted re access to vital area Details withheld (ref 10CFR2 790 & 10CFR23 21)
  HALL, B L , MCGUIRE, D R Region 2, Defice of Director 84/06/26 ip 26005 343 24% Fiche 50-338,84/08/09,8408130433
- B40B070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl GRACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376
- 8408100007 IE Info Notice 84-63, "Defective RHR Replacement Piping "

  Bvc list enc]

  JCRDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New

  York Inc 119pp 26197 218 24X Fiche \$0-000.84/08/13.8408100009
- 8408100038 IE Info Notice 84-64. "BWR HPCI Initiation Seal-In & Indication " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York. Int 104pp 26198 093 24X Fiche \$0-000.84/08/15.8408100038
- B40B100021 IE Info Notice B4-45, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl Just and Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021
- 8408100055 IE info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN.E. L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York. Inc. 120pp 26276 001 24% Fiche 50-000.84/08/17.8408100055
- B40B14020B IE Info Notice B4-67, "Recent Snubber Inservice Testing W/High Failure Rates" Svc list encl
  URDAN,E L. Division of Emergency Preparedness & Engineering
  Response (Post B30103) 84/08/17 Consolidated Edison Co of New
  York. Inc 122pp 26276 122 24X Fiche 50-000 84/08/17, 8408140208
- 8408210142 lE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Bolenoid Valves " Svc list encl JORDANIE L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24% Fiche 50-000,84/08/21,8408210142
- 8408290330 Forwards Safeguards Insp Repts 50-338/84-31 & 50-339/84-31 on 840806-10 No violations or deviations noted Repts withheld (ref 10CFR2 790 & 73 21)
  DANCE.H C Division of Project & Resident Programs 84/08/27
  STEWART.W L. Virginia Electric & Power Co 2pp 26289 345 24X
  Fiche 50-338,84/08/27,8408290330
- S. Reportable occurrences, LERs & related correspondence
- 8408230077 Summary of 840807 operating reactor events meeting reoccurrences since 840717 meeting List of attendees, significant elements & status of previous assignments encl CRUTCHFIELD.D Assistant Director for Safety Assessment 84/08/16 EIBENHUT.D C Division of Licensing 20pp 26233 249 24X Fichs 50-000, 84/08/16,8408230077

- 8408230392 PNO-11-84-051 on 840817.earth tremor measuring 3 8 on Richter scale occurred Tremor did not trip plant seismic monitoring equipment ELROD.5 A , DANCE.H C Region 2. Dffice of Director 84/08/17 26205 303 24% Fiche 50-338.84/08/17.8408230392
- 8408290193 Informs of oil spill on 840816 Two gallons of oil discovered near first storm drain at discharge canal Gil contained in area & cleaned up by use of absorbent pads & Fiber Pearl Caused by separator left running
  TAYLOR, J A Virginia Electric & Power Co 84/08/20 KREGLOE, W L
  Virginia, Commonwealth of. 1p 26297 222 24X
  Fiche 50-338,84/08/20,8408290193

### V Operator Examinations

- 8408070489 Forwards hot license simulator reactor startup certification program, per NUREG-0094 Program limits student to instructor ratio to four-to-one, conforming to INPO Guide 82-005 W/o PETEMART.W L. Virginia Electric & Power Co. 84/06/06 PERBENSKY.J J. NRC - No Datailed Affiliation Given 2pp. 25940 347 24X Fiche 50-000.84/06/06.8408070489 RTEUART, LI I
- DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2
- F. Security, medical, emergency & fire protection plans
- 8408310069 Confirms 840524 visit to Region to discuss access control at Tactivies
  LEWIS R C Region 2. Office of Director 84/0
  Virginia Electric & Power Co ip 26333 342
  Fiche 50-000,84/05/22,8408310069 84/05/22 STEWART, W.L.
- 84083i0401 Forwards summary of 840524 meeting re security interface activities Meeting beneficial & provided better understanding between security staffs
  LEMIS.R C Region 2. Office of Director 84/06/06 STEMART.W L Virginia Electric & Power Co 4pp 2633 311 24X Ficke 50-000.84/06/06.84083i0401
- B40B140029 Forwards corrected Page 2 to attachment to B40614 order confirming licensee commitments to implement post-YM1 related items in Buppl 1 to NURGE-0727, "Requirements for Emergency Response Capability" (Generic Ltr B2-33) MILLER, J R Operating Reactors Branch 3 84/07/24 STEWART, W I Virginia Electric & Power Co 3pp 26061 259 24X Fichs 50-338,84/07/24,8408140029 STEWART, W L
- --B408140033 Correction to 840614 order confirming licensee commitments to Suppl 1 to NUREO-0737 Completion date for technical support ctr to be fully functional changed to 850731 MILLER J R Operating Reactors Branch 3 84/07/24 Virginia Electric & Power Co 1p 26061 263, 24X Fiche 50-33B,84/07/24, 8408140027
- 8408070039 Forwards replacement pages to control room design review program plan Adoption of Westinghouse Owners Group emergency response guidelines as basis for task analysis & verification/validation sections principal changes STEWART.W L Virginia Electric & Power Co 84/07/27 DENTON.H F Office of Nuclear Reactor Regulation, Director 8pp 25949 281 24X Fiche 30-000,84/07/27,8408070039 07/27 DENTON:H R 8pp 25949 281
- 8408070400 Forwards "VEPCO North Anna Power Station, Units 1 & 2 4080/0400 Forwards "VEPCO North Anna Power Station.Units 1 & 10CFR50, App R Rept - App A." per 840515 request Rept includes summary comparison of 1984 App R reanalysis & util 820622 post-fire safe shutdown review STEMART, W L. Virginia Electric & Power Co. 84/07/27 DEN Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 3pp 25942 191 24x Fiche 50-338,84/07/27,8408070400
- --- 8408070404 "VEPCO North Anna Power Station, Units 1 & 2 10CFR50, App R 1080/0404 - VEP-CO 107 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010 | 1010
- 8408020028 Forwards lists of mods & revised schedules re 10CFR50 48, App R reanalysis Compensatory measures for mods specified Completion of App R reanalysis scheduled for 840812 BTEWART.W L Virginia Electric & Power Co 84/07/31 DENTON.H R Office of Nuclear Reactor Regulation, Director EISENHUT, D 0 Division of Licensing 9pp 23880 265 24X Fiche 30-338,84/07/31,848802009
- B408130394 Ack receipt of 840710 & 0801 ltrs informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 LEWISIR C Division of Project & Resident Programs 84/08/09 STEWART.W L Virginia Electric & Power Co 1p 26010 124 24X Fiche 30-338,04/08/09,8408130394

- --B408130400 Responds to NRC 840611 ltr re violations noted in IE Safeguards Insp Repts 50-339/84-18 t 50-339/84-18 Corrective actions withheld (ref 10CFR73 21) STEMART.W L Virginia Electric & Power Co 84/07/10 O'REILLY.J P Region 2, Office of Director 19 26010 125 24X Fiche 50-338,88/08/09,8408130394
- --8408130403 Suppls response to NRC B40611 ltr re violations noted in TE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 Corrective actions withheld (ref 10CFR73 21) STEWART, W L Virginia Electric & Power Co B4/08/01 O'REILLY, J P Region 2, Office of Director 1p 26010 126 24) Fiche 50-338,84/08/09,8408130394 26010 126 24X
- --B40B13040B Forwards IE Safeguards Insp Repts 50-33B/B4-1B & 50-339/B4-1B on B40521-25 & notice of violation Notice of violation withheld (ref 10CFR2 790 & 10CFR73 21) LEWIS.R C Region 2. Office of Director 84/06/11 BTEV 84/04/11 BTEWART, W L
- --8408130418 IE Bafeguards Insp Repts 50-338/84-18 & 50-339/84-18 on 840521-25 Noncompliance noted in area of access control for personnel Details withheld (ref 10CFR2 790 & 10CFR73 21) ENNIS, J D Region 2, Office of Director 84/06/08 le 26010 139 24X Fiche 50-338,84/08/09,8408130394
- 8408130433 Ack receipt of 840727 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-338/84-25 & 50-339/84-25 EEWIS, R C Division of Project & Resident Programs 84/08/ STEWART, W L Virginia Electric & Power Co ip 26005 339 Fiche 50-338,84/08/09,8408130433 84/88/89
- ---B40Bi30438 Responds to NRC B40629 ltr re violations noted in IE Bateguards Insp Repts 50-338/84-25 & 50-339/84-25 Corrective actions withheld (ref 10CFR73 21) BTEWART, W L Virginia Electric & Power Co 84/07/27 O'REILLY, J P Region 2, Office of Director 1p 26005 340 Fiche 50-338,84/08/09,8408130433
- --B408130443 Forwards IE Safeguards Insp Repts 50-338/84-25 & 50-339/84-25 on 640606 & notice of violation Notice of violation withheld (ref 100FR2 790 & 100FR73 21) LEWIB.R C Region 2, Office of Director 64/06/29 STEV STEWART, W L
- --8408130444 IE Safeguards Insp Repts 50-338/84-25 & 50-339/84-25 on 840404 Violation noted re access to vital area Details withheld (ref 10CFR2 790 & 10CFR73 21) HALL, B L Region 2. Office of Director 84/06/26 ip 24005 343 24X Fiche 50-338,84/08/09,8408130433
- B408200387 Advises that program plan for conducting detailed control room design review meets intent of Suppl 1 to NUREG-0737 Listed areas should be described in summary rept expected VARQA:5 A Licensing Branch 1 84/08/10 STEWART.W.L. Virginia Electric & Power Co 2pp 26141 R15 24X Fiche 50-000,84/08/10,
- B408290330 Forwards Safeguards Insp Repts 50-338/84-31 & 50-339/84-31 on B40806-10 No violations or deviations noted Repts withheld (ref 10CFR2 790 & 73 21)
  DANCE,H. C Division of Project & Resident Programs 84/08/27
  STEMART,W L Virginia Electric & Power Co 2pp 26289 345 24X
  Fichs 50-338,84/08/27.8408290330

#### O Adjudicatory correspondence

- B408010250 Enforms that util & NRC intend to file response to objectionable contentions by B40817, based on discussions w/ parties
  DDUOHERTY, J B Dougherty, J B DOUGHERTY, J B Concerned Citizens
  of Louisa County, VA DBB 665, B4/07/30 WOLFE, B J,
  FEROUSON, G A, KLING, J Atomic Safety and Licensing Board Panel
  10pp 25854 342 24X Fiche 50-338,84/07/30.8408010250
- 840B150464 Response to 840730 third draft of contentions of Concerned Citizens of Louisa County All but Contention 4 should be danied Certificate of Bvc encl MAUPIN, M W Virginia Electric & Power Co MAUPIN, M W Hunton & Williams DSB 056 84/08/14 Atomic Safety and Licensing Board Panel 31pp 26068 165 24X Fiche 50-338,84/08/14,8408150464
- 8408200477 Forwards response to contentions of Conterned Citizens of Louisa County W/o entl Related correspondence
  MAUPIN.M W. Hunton & Williams, MAUPIN.M W. Virginia Electric &
  Power Co. DSB 157 B4/08/14 Docketing & Services Branch, ip
  26136-306 24% Fiche 50-338.84/08/14.8408200477

- IOB200387 Forwards NRC response to Concerned Citizens of Louisa Goonty third draft of contentions Request by NRC for 1-day extension in date for filing response granted by Chairmen Wolfe LEWIS:S H Hearing Branch 2 DSB 173 84/08/15 WOLFE,S J. KLINC, J. FERGUSON,G A Atomic Safety and Licensing Board Panel 1p 26137 140 24X Fiche 50-338.84/08/15.8408200887
- -8408200593 Response to Concerned Citizens of Louisa County third draft of contentions Certificate of Svc encl MCGURREN.H J Hearing Branch i LEWIS.5 H Hearing Branch 2 84708/15 Atomic Safety and Licensing Board Panel 15pp 26137 141 24X Fiche 50-338,84/08/15,8408200587
- 108300129 Response supporting admission of Concerned Citizens of Louisa County 840814 revised Contention 4 Certificate of Svc encl HASBELL,D F Hearing Branch I DSB 380 84/08/27 Atomic Safety and Licensing Board Panel 4pp 26304 358 24X Fiche 50-336.84/08/27.8408300129
- OBSODITY Response to Concerned Citizens of Louise County, VA (CCLC) revised Contention 4 re physical protection sys for spent fuel shipments Protective order necessary for CCLC access Certificate of Byc enci MAUPIN, M & Virginia Electric & Power Co MAUPIN, M & Hunton & Williams DBB 384 84/08/27 Atomic Safety and Licensing Board Penel 14pp 26305 343 24X Fichs 50-338.84/08/27.8408300177
- 108310150 Forwards applicant response to Concerned Citizens of Louisa Gounty, VA revised Contention 4 W/o encl Related correspondence
  MAUPIN.H W Hunton & Williams MAUPIN.H W Virginia Electric & Power Co DSB 414 84/08/27 Doctoting & Services Branch Ip
  26322 202 24X Fiche 50-338,84/08/27.8408310150
- iOB310148 Order scheduling supplemental special prehearing conference on 840907 in Bethesda, MD & directing participants to appear 840830 MDLFE, 8 J Atomic Safety and Licensing Board Panel DSB 372 84/08/20 Dffice of the Executive Legal Director 3pp 26320 358 24% Fiche, 50-338, 84/08/28, 8408310148

## Operating license stage documents & correspondence

- 108300369 Confirms 840501 telcon w/HC Dance rs 840510 mgt meeting in Region II ofc to discuss organizational structure LEWIS,R C Region 2, Office of Director. 84/05/07 STEWART,W L Virginia Electric & Pouer Co ip 26308 230 24X Fichs 50-000,84/05/07.8408300349
- iOB130223 Forwards safety evaluation re util 831104 response to Generic Ltr 83-28. Item 4 3. "Reactor Trip Sys Reliability "Design mods acceptable MILLER, J R Operating Reactors Branch 3 84/07/24 STEWART, W L Virginia Electric & Power Co Esp 26058 313 24X Fiche, 50-336, 84/07/24, 8408130223
- 8408130226 Safety evaluation supporting licensee response to Deneric Ltr 83-28. Item 4 3. "Reactor Trip Sys Reliability " Design mods acceptable \* NRC - No Detailed Affiliation Given 84/07/24 10pp 26058 315 24X Fiche 50-338.84/07/24.8408130223
- OB140063 Forwards comments & questions for review & requests site visit to further discuss inservice treating program NRR should be contacted in approx 4 wks to confirm time & date for meeting MILLER, J R Operating Reactors Branch 3 84/07/24 STEWART, W L Virginia Electric & Pouer Co 9pp 26061 267 24% iche 50-338,84/07/24,8408140063
- BD90235 Application for amends to Licenses NPF-4 & NPF-7, revising ech Bpecs re limiting conditions for operation & unveillance requirements consistent w/ST8
  TEWART.W L Virginia Electric & Power Co 84/08/01 DENTON.H R ffice of Nuclear Reactor Regulation, Director MILLER, J R perating Reactors Branch 3 4pp 25972 141 24X iche 50-338,84/08/01,8408090235
- 3408070239 Proposed Tech Spec changes re limiting conditions for operation & surveillance requirements, to provide consistency w/8TB.

  \* Virginia Electric & Power Co 84/08/01 7pp 25972:145 24X Fiche 50-338,84/08/01,8408090235

- 8408090149 Provides upgraded in-core thermocouple implementation schedule.per 840221 commitment Util proposes to complete Reg Guide 1 97 (ref NUREG-0737. Item II F 2) mods prior to or during 1986 refueling outages
  STEWART.W L Virginia Electric & Power Co 84/08/03 DENTON, H R Office of Nuclear Reactor Regulation. Director £18ENHUT.D G Division of Licensing 2pp 25973 122 24X Fiche 50-338,84/08/03,84080970149
- 8408070110 Generic Ltr 84-19 to all licenses of operating reactors, applicants for OLs & holders of CPs re availability of Buppl I to NUREG-0933, "Prioritization of Generic Safety Issues "Svc list encl EISENHUTID 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24% Fiche 50-000,84/08/06.8408070110
- 8408210575 Summary of 840803 meeting w/util in Nethesda, MD re nonquallified paint inside containment List of attendees & agenda encl ENGLE, L B Operating Reactors Branch 3 84/08/13 MILLER, J R Operating Reactors Branch 3 20pp 26195 226 24x Fiche 50-338,84/08/13,8408210575
- 8408210132 Forwards Generic Ltr 84-15 response schedule, listing 840928 & 850131 as projected dates Justification for extension of responses included STEWART.W L Virginia Electric & Power Co 84/08/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 26181 348 24X Fiche 50-000, 84/08/16, 8408210132
- B408210375 Forwards B&W summary technical repts of first capsule from reactor vessel surveillance program per App H of 100FR50 Repts delayed due to administrative oversight STEWART, W L Virginia Electric & Power Co 84/08/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 26178 001 24 Fiche 50-338,84/08/16,8408210375
- --B40B2103B7 "Analysis of Capsule V.VEPCO.North Anna Unit 2. Reactor Vessel Matls Surveillance Program " LOME.A L . COLLINS.L L . PAVINICH.W A Babcock & Wilcox Co BAM-1794 B3/10/31 173pp 26178 002 24% Fiche 50-33B. B4/0B/16.8408210375
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for DLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT.D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276-244 24% Fiche 50-000.84/08/20.8408200275
- @ Inspection reports, IE Bulletins & correspondence
- 8408270387 Forwards Insp Repts 50-338/84-24 & 50-339/84-24 on 840618-22 No violations or deviations noted DANCE,H C Region 2: Office of Director 84/07/11 STEWART,W L Virginia Electric & Power Co Zpp 26256 278 24X Fichs 50-338,84/07/11,8408270387
- --B40B270388 Insp Repts 50-338/B4-24 & 50-339/B4-24 on B4061B-22 No violations or deviations noted Major areas inspected plant chemistry & employee concerns ROBE, W J , DLAKE, J J Region 2, Office of Director B4/07/09 15pp 26286 280 24X Fiche 50-338,84/07/11,840B2703B7
- 8407250229 IE Info Notice 84-57, "Operating Experience to Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list oncl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Ficher 50-000,84/07/27,8407250229
- B40B02004: Forwards insp fees for Surry Power Station & North Anna, Unit 1 for Mar 1983 - Mar 1984 & North Anna, Unit 2 for Apr 1983 - Apr 1984 STEWART, W. Virginia Electric & Power Co 84/07/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 25880 304 24X Fiche 50-000, 84/07/27, 840B020041
- B408280150 Responds to IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " All GE Type HFA relays in safety-related applications will be replaced STEWART, W L Virginia Electric & Power Co 84/07/31 O'REILLY, J P Region 2. Office of Director 4pp 26259 082 24X Fiche 50-000.84/07/31.8408280150
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

- 8408010337 IE Info Notice 84-60. 'Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc. 123pp 26067 158 24% Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR
  Refueling Cavity " Svc list encl
  JORDAN, E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/08 Consolidated Edison Co of New
  York, Inc & 120pp 26129 118 24X Fiche 50-000.84/08/08.8408070120
- 8408130394 Ack receipt of 840710 & 0801 ltrs informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-339/84-18 % 50-339/84-18 LEWIS, R C Division of Project & Resident Programs 84/08/09 STEWART, W L Virginia Electric & Power Co 1p 26010 124 24X Fiche 50-338,84/08/09,8408130394
- --8408130400 Responds to NRC 840511 ltr re violations noted in 1E Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 Corrective actions withheld (ref 10CFR73 21) STEWART, W L Virginia Electric & Power Co 84/07/10 O'RETLLY, J P Region 2. Office of Director ip 26010 125 24 Fiche 50-338,84/08/09.8408130394
- --B40B13Q403 Suppls response to NRC B40611 ltr re violations noted in IE Safeguards Insp Repts 50-33B/84-18 & 50-339/84-18 Corrective actions withheld (ref 10CFR73 21) STEWART.W L Virginia Electric & Power Co B4/08/01 O'REILLY, J P Region 2, OFFice of Director 1p 26010 124 24X Fiche 50-33B,84/08/09,8408130394
- --B408130408 Forwards IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 on 840521-25 & notice of violation Notice of violation withheld (ref 10CFR2 790 & 10CFR73 21) LEWIS,R C Region 2, Office of Director 84/06/11 STEWART,W L Virginta Electric & Power Co 2pp 26010 127 24X Fiche 50-338,84/08/09,8408130394
- --B408130418 IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 on B40921-25 Noncompliance noted in area of access control for personnel Details withheld (ref 10CFR2 790 & 10CFR23 21) ENNIS, J D, McGUIRE, D R Region 2. Defice of Director 84/06/08 ip 26010 127 24X Fiche 50-338,84/08/09,8408130394
- B49B130433 Ack receipt of B40727 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-338/B4-25 & 50-339/B4-25 LEWIB.R C Division of Project & Resident Programs 84/08/09 STEWART.W L Virginia Clectric & Power Co ip 26005 337 24X Fiche 50-33B.84/08/09.840B130433
- --8408130438 Responds to NRC 840629 itr re violations noted in IE Safeguards Insp Repts 50-338/84-25 5 50-339/84-25 Corrective actions withheld (ref 10CFR73 21)
  STEMART.W L Virginia Electric & Power Co 84/07/27
  O'REILLY.J P Region 2, Office of Director 1p 26005 340 24x
  Fiche 50-338,84/08/09,8408130433
- --8408130443 Forwards IE Safeguards Insp Repts 50-338/84-25 & 50-339/84-25 on 840606 & notice of violation Notice of violation withheld (ref 100FR2 790 & 100FR73 21)
  LEMIG.R C Region 2, Office of Director 84/06/29 STEWART.W L Virginia Electric & Power Co 2pp 26005 341 24X
  Fiche 50-338,84/08/09,8408130433
- --8408130446 IE Bafeguards Insp Repts 50-338/84-25 & 50-339/84-25 on 840606 Violation noted re access to vital area Details withheld (ref 10CFR2 790 & 10CFR73 21) HALL, B L , MCGUIRE, D R Region 2, Office of Director 84/06/26 1p 26005 343 24X Fiche 50-338,84/08/09,8408130433
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc 14st encl
  QRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24% Fiche 30-000,84/08/10,8408070376
- 8408100009 IE Info Notice 84~63, "Defective RHR Replacement Piping "
  Svc list encl
  JGRDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc. 119pp 26197 218 24X Fiche 50-000.84/08/13,8408100009
- 8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000:84/08/15,8408100038

- 8408100021 IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc. 118pp 26198 001 24X Fiche 50-000.84/08/16,8408100021
- 8408100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000.84/08/17.8408100055
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates" Svc list encl JORDAN: E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 122pp 26276 122 24X Fiche 50-000.84/08/17.8408140208
- B408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Hiring to Solenoid Valves "Svc list enc! JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000.84/08/21.8408210142
- 8408290330 Forwards Safeguards Insp Repts 50-338/84-31 & 50-339/84-31 on B40806-10 No violations or deviations noted Repts withheld (ref 10CFR2 790 & 73 21)
  DANCE, H C Division of Project & Resident Programs 84/08/27 STEMART. W L Virginis Electric & Power Co 2pp 26289 345 24X Fiche 50-338,84/08/27,8408290330
- B Reportable occurrences, LERs & related correspondence
- B408230077 Summary of 840807 operating reactor events meeting re occurrences since 840719 meeting List of attendees, significant elements & status of previous assignments encl CRUTCHFIELD, D. Assistant Director for Safety Assessment 84/08/14 EISENHUT, D. © Division of Licensing 20pp 26233 249 24X Fiche 50-000,84/08/14,8408230077
- 8408230392 PND-II-84-051 on 840817 earth tremor measuring 3 8 on Richter scale occurred Tremor did not trip plant seismic monitoring equipment ELRDD, S A . DANCE. H C Region 2. Diffice of Director 84/08/17 ip 26205 303 24X Fiche 50-338,84/08/17.8408230392
- 8408270193 Informs of oil spill on 840816 Two gallons of oil discovered near first storm drain at discharge canal Oil contained in area & cleaned up by use of absorbent pads & Fiber Pearl Caused by separator left running TAYLOR. J A Virginia Electric & Power Co 84/08/20 KREGLOE, W L Virginia, Commonwealth of. 1p 26297 222 24X Fiche 50-338,84/08/20,8408270193

# ∨ Operator Examinations

- 8408070489 Forwards hot license simulator reactor startup certification program.per NUREO-0094 Program limits student to instructor ratio to four-to-une.conforming to INPO Ouide 82-005 M/o encl
  8TEWART, M L Virginia Electric & Power Co 84/06/06
  PERSENSKY, J J NRC No Detailed Affiliation Given 2pp 25740 347 24X Fiche 30-000.84/06/06,8408070489
- DOCKET 50-341 ENRICO FEMMI ATOMIC POWER PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 8404010037 Responds to 840222 request for addl info re postulated failure of HPCI steam line w/o isolation Outboard isolation valve on HPCI steam line maintained in closed position Bypass valve must close against only 1-inch flow JENS.W H. Detroit Edison Co. 84/05/25 YOUNGBLOOD, B. J. Licensing Branch 1 2pp 24736-335 24X Fichs 50-341-84/05/25,8406010037
- 8408210079 Forwards revised offsite dose calculation manual, reflecting resolution of NRC 840508 questions on draft manual Specific responses encl JENS, W.H. Detroit Edison Co. 84/07/25 YOUNGBLOOD, B.J. Licensing Branch 1 4pp 26186 016 24X Fiche 50-341.84/07/25,8408210079
- --8408210085 "Offsite Dose Calculation Manual for Enrica Fermi Atomic Power Plant Unit 2 " \* Detroit Edison Co 84/05/31 119pp 26186 020 24X Fiche 50-341,84/07/25,8408210079

- 8408060388 Forwards proof & review Tech Specs Sections of Tech Specs pertaining to particular areas of responsibility should be reviewed Results of review requested by 840831 CRUTCHFIELD, D. Assistant Director for Safety Assessment 84/07/27 NOVAK: T. Assistant Director for Licensing JOHNSTON, W.V. Assistant Director for Matls, Chen & Environ Technology (Post 830201) RUBENSTEIN, L.S. Assistant Director for Core & Plant Systems 400pp 26228 256 24% Fiche 50-341.84/07/27.8408060388
- 8408070440 Advises of plans to implement Option 4 of NUREG-0737. Item II K 3 18, "Mod of Automatic Depressurization Sys Logic," per NRC approval Plans include installation of sys manual inhibit switch JENS,W H Detroit Edison Co 84/07/31 YOUNGBLOOD, B J Licens Branch 1 2pp 25942 337 24X Fiche 50~341,84/07/31.8408070440
- 8408160474 Forwards Certificate of Svc re Amend 58 to amended & substituted application for license EARLE.O K Detroit Edison Co 84/08/08 YOUNGBLOOD, B J Licensing Branch 1 3pp 26107-289 24% Fiche 50-341.84/08/08,8408160474
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licenses submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT.D 0 Division of Licensing B4/09/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000, B4/08/20, B408200275
- 8408310264 Notification of 840913 meeting w/vtil in Bethesda.MD to discuss applicant evaluation of coatings used in containment drgwell & wetwell urguesi & wetwell KINTNER.L L Licensing Branch ! 84/08/29 YDUNOBLOOD, B J Licensing Branch ! 4pp 26350 341 24X Fiche 50-341.84/08 8408310264 4pp 26350 341 24% Fiche 50-341.84/08/23,
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8408010216 Discusses control room design review open items status, per SER (NORSE-0798) Encls identify human engineering deficiencies.status 8, ohere possible, ref document to support closure of item SEMS (NORSE) SUPPORT (NORSE)
- 8408230296 Forwards Rev I to Radiation Chemistry Procedure 78 000 15.
  "Determination of Extent of Core Damage." to resolve SSER 3
  (NUREG-0798) open Items Procedure supports deletion of
  license condition proposed in SER
  JENS.W H Detroit Edison Co 84/08/16 YGUNGBLGDD.B J Licensin
  Branch I 4pp 26208 005 24X Fichs 50-341.84/08/16,8408230276
- --8408230301 Rev 1 to Radiation Chemistry Procedure 78 000 15, "Determination of Extent of Core Damage "
  HEINS, J Detroit Edison Co 84/06/12 28pp 26208 009 24X
  Fiche 50-341.84/08/16.8408230276
- F Security, medical, emergency & fire protection plans
- 8408150638 Forwards IE Insp Rept 50-341/84-15 on 840625-29 No noncompliance noted List of weaknesses identified in emergency preparedness exercise encl Corrective actions requested within 30 day of ltr receipt PAPERIELLO.C J Region 3. Office of Director 84/07/27 JENS, Datroit Edison Co 3pp 26079 065 24X Fiche 50-341.84/07/27, 8408150638
- -8408130646 IE Insp Rept 50-341/84-15 on 840623-29. No noncompliance or deviations noted Major areas inspected emergency preparedness exercise & licensee actions on previously identified items re emergency preparedness Scenario encl PATTERSON. J P. CHRISTOFFER. 0. KANTOR, F. Region 3. Office of Director 84/07/27 24pp 26079 068 24X Fiche 50-341,84/07/27,8408150638
- 40B060024 Forwards IE Bafeguards Insp Rept 90-341/84-26 on 840711-13 No noncompliance noted One potential deficiency involving design of certain portion of security sys requires review AXELSON, W. L. Region 3, Dffice of Director 84/07/30 JENS,W. H. Detroit Edison Co. 2pp 25933 099 24% Fiche 50-341,84/07/30,
- 8408060036 IE Safeguards Insp Rept 50~341/84-24 on 840711-13 No noncompliance noted Hajor areas inegeneted status of installation & implementation & operability of security program Details withheld (ref 10CFR73 21) MADEDA: T J. CREED: J R Region 3. Office of Director. 84/07/30. 1p 25933 101 24X Fiche 50-341.84/07/30.8408060024.

- B40B0B0305 Forwards discussion or known deviations from 10CFR50, App R (Generic Ltr 83-33) \$ guidance on App R. except for control ctr complex Deviations include justification showing equivalent level of fire protection provided JENS, W H Detroit Edison Co 84/08/03 YOUNOBLOOD, B J Licensing Branch : 113pp 25944 115 24% Fiche 50-341.84/08/03.840B080305
- B40B0B0299 Forwards "Analysis of Thermal Response of Junction Between Partially Protected Member Which Protrudes Thermo-Lag 330 Fire Barrier & Cable Tray' & summaries of test results for configurations of 3M fire protection envelope JENS. W H Detroit Edison Co 84/08/04 YOUNGBLOOD, B J Licensing Branch 1 3pp 23965 193 24X Fiche 30-341/84/08/04, 8408080299
- -8408080302 "Analysis of Thermal Response of Junction Between Partially Protected Hember Which Protrudes Thermo-Lag 330 Fire Barrier & Cable Tray " \* Detroit Edison Co & Cable Tray " \* Detroit Edison Co 84/04/30 63pp 25965 178 24X Fiche 50-341,84/08/04,8408080299
- 840809046B Summary of B40711 meeting w/util.Bechtel & consultants in Bethesda.MD re fire protection measures List of attendees & visugraphs encl LYNCH.M D Licensing Branch 1 84/08/06 Licensing Branch 1 20pp 25983 178 24X Fiche 50-341.84/08/06.8408090468
- 8408130153 Ack receipt of 840724 ltr informing NRC of steps taken to correct violations noted in IE Preoperational Safeguards
  Insp Rept 50-341/84-18 Corrective measures will be examined during subsequent insp AXELSON, W. L. Region 3, Office of Director 84/08/08 JENS, W Detroit Edison Co. 1p. 26007-350 24X Fiche 50-341,84/08/08, JENS, W. H. 8408130153
- --B40B130163 Responds to NRC 840621 ltr re violations noted in IE
  Preoperational Bafeguards Insp Rept 50-341/B4-18 Corrective
  actions re design of nain personnel access facility to potential design weakness within warehouse withheld
  JENS.W H Detroit Edison Co 84/07/24 KEPPLER.J G Region 3.
  Office of Director ip 26007 351 24X Fiche 50-341,84/08/08,8408130153
- 8408230274 Informs of intent to use alternative shutdown method described in 10CFH50. App R. Section III L as primary basis for satisfying requirements on fire protection for control ctr complex Review & approval requested

  JENS.W H Detroit Edison Co 84/08/16 DENTON, H Office of Nuclear Reactor Regulation, Director 6pp 26206 197 24X

  Fiche 50-341.84/08/16.8408230274
- 8408230389 Forwards, for review. "Control Room Design Review Program Plan for Fermi 2," per Suppl 1 to NUREG-0737 & Generic Ltr 82-33 Detroit Edison Ca 84/08/16 YOUNGBLOOD, B J Licens 2pp 26205 249 24X Fiche 50-341.84/08/16.8408230389 JENS'M H Licensina
- --B408230391 "Control Room Design Review Program Plan fo Fermi 2 "
  \* Detroit Edison Co 84/08/04 48pp 26205 251 24X
  Fiche 50-341.84/08/14.8408230389
- 8408270348 Ack receipt of 840808 ltr informing NRC of steps taken to correct violations noted in Emergency Preparedness Appraisal Rept 50-341/83-24 PAPERIFELLO.C J Region 3, Office of Director 84/08/22 JENS.W & Batroit Edison Co ip 26242 361 24X Fiche 50-341,84/08/22, JENB, W.H. Detroit Edison Co
- --8408270352 Responds to NRC 840201 ltr re violations noted in Emergency Preparedness Appraisal Rept 50-341/83-24 Corrective actions numerical values used to determine emergency classification incorporated into equipment air locks

  JENS,W H Detroit Edison Co 84/08/08 PAPERIELLO,C J Region
  G. Diffice of Director 1p 26242 362 R4X Fiche 50-341,84/08/22,8408270348
- 8408310188 Forwards Rev 3A to EPA-99, "Radiological Emergency Response Plan " Rev provided to support resolution of open items in emergency planning area JENS,W H Detroit Edison Co B4/08/24 YOUNGBLOOD,B J Licens: Branch I 2pp 26325 046 24% Fiche 50-341.84/08/24.8408310188
- --8408310191 Rev 3A to "Radiological Emergency Response Plan" CONNELL, K Detroit Edition Co 84/08/16 250pp 26325 048 24X Fiche 50-341,84/08/24,8408310488
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 8408020029 Amend 58 to FSAR W/840731 1tm CARLE.O K Detroit Edison Co 84/07/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 1,000pp 26399 172 24X Fiche 50-341,84/07/31,8408020029

- P Operating license stage documents & correspondence
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933. "Prioritization of Generic Safety Issues." Svc list encl
  EISENHUT, D 0 Division of Licensing 84/08/06 Consulidated Edison Co of New York, Inc. 18pp 26129 238 24x
  Fiche 50-000,84/08/06,8408070110
- Q Inspection reports, IE Bulletins & correspondence
- 840B030203 Forwards IE Insp Rept 50-341/84-07 on 840401-0615 No noncompliance noted WARNICY.R F Region 3. Office of Director 84/07/13 JENS,W H Detroit Edison Co 2pp 25917 122 24X Fiche 50-341,84/07/13. 8408030203
- --8408030207 IE Insp Rept 30-341/84-07 on 840401-0615 No noncompliance noted Major areas inspected previous inspector identified items.headquarters requestirequant requests. IE bulletins & circulars t preoperational test witnessing KNDP.R C Region 3. Office of Director 84/07/12 13pp 25917 124 24X Fiche 30-341.84/07/13.8408030203
- 8408010283 Forwards IE Insp Rept 50-341/84-22 on 840605-15 & 20-22 No noncompliance noted HALKER, D. Region 3. Office of Director 84/07/16 JENS,W H. Detroit Edison Co. 2pp. 25866-215 24X Fiche 50-341,84/07/16, RAD8010283
- --840B010285 IE Insp Rept 50-341/84-22 on 840405-15 & 20-22 No noncompliance noted Major areas inspected mgt of preoperational testing 84 program & quality verification & training & qualification of GA personnel MALLOY, J. HASSE, R. HAWKINS, F. Region 3, Office of Director 84/07/16 \$pp 25866 217 24X Fiche 50-341,84/07/16,8408010283
- 8408060082 Provides final response to IE Bulletin 83-06. "Nonconforming Matls Supplied by Tube-Line Corp " No Tube-Line Corp products received for use in safety-related sys JENS.W H Detroit Edison Co 84/07/23 KEPPLER, J G Region 3, Defice of Director 3pp 25933 130 24X Fiche 50-341,84/07/23, 8408060082
- 8497250229 IE Info Notice 84-57. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commencial Power Plants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 28665 047 24X Fichs 50-000.84/07/27\_8407250229
- 8408150471 Forwards IC Insp Rept 50-341/84-24 on 840612-0713 No noncompliance noted SPEBSARD: R L Region 3, Office of Director 84/07/27 JENS, W F Detroit Edison Co 2pp 26075 282 24X Fiche 50-341, 84/07/27, 8408150471
- 8408150638 Forwards IE Insp Rept 50-341/84-15 on 840525-29 No noncompliance noted List of weaknesses identified in emergency preparedness exercise encl Corrective actions requested within 30 day of ltr receipt PAPERIELLO,C J Region 3, Office of Director 84/07/27 JENS,W H Batroit Edison Co 3pp 26079 065 24% Fiche 50-341,84/07/27, 8408150638
- --8408150646 IE Insp Rept 50-341/84-15 on 840625-27 No noncompliance or deviations noted Major areas inspected emergency preparedness exercise & licensee actions on previously identified items re amergency preparedness Scenario encl PATTERSON, J P , CHRISTOFFER. G , KANTOR. F Region 3, Office of Director 84/07/27 24pp 26079 068 24X Fiche 50-341,84/07/27,8408150638
- 8408060024 Forwards IE Safeguards Insp Rept 50-341/84-26 on 840711-13 No noncompliance noted Dne potential deficiency involving design of certain portion of security sys requires review AMELSON, W. L. Region 3. Office of Director 84/07/30 JENS, W. H. Detroit Edison Co. 2pp 25933 099 24X Fiche 50-341.84/07/30, 8408060024

- --8408060036 IE Safeguards Insp Rept 50-341/B4-26 on 840711-13 No noncompliance noted Major areas inspected status of installation & inplementation & operability of security program Details withheld (ref 100FR73 21) MADEDA.T J. CREED.J R. Region 3. Office of Director 84/07/30 1p 25933 101 24X Fiche 50-341.84/07/30.8408060024
- 8408160334 Forwards IE Insp Rept 50-341/84-09 on 840409-0702 & notice of violation BPESSARD.R L Region 3, Office of Director 84/07/30 JENS,W H Detroit Edison Co 2pp 26106 101 24X Fiche 50-341,84/07/30, 8408160334
- --B408160338 Natice of violation from insp on B40409-0702 SPESSARD,R L Region 3, Office of Director B4/07/30 2pp 26106 103 24X Fiche 50-341,84/07/30,8408160334
- --8408160341 IE Insp Rept 50-341/84-09 on 840409-0702 Noncompliance noted failure to control rev to design documents & failure to fallow listed procedures

  KAUFMAN.P D., YIN.I T. CILIMBERG.R L. Region 3, Office of Director 84/07/27 21pp 26106 105 24X Fiche 50-341,84/07/30.8408160334
- 8408070334 Ack receipt of 840724 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-341/84-11 SPESSARD.R L. Region 3. Office of Director 8408/02 JENS,W H. Detroit Edison Co. Ip. 28945 144 24X Fiche 50-341,84/08/02,8408070354
- ---B408070356 Responds to NRC 840626 ltr re violations noted in IE Insp Rept 50-341/84-11 Corrective actions Test Change Notice 1722 issued to PRET N3202 001. Rev 1 to reconnect battery chargers prior to performance test JENS, N H Detroit Edison Co 84/07/24 KEPPLER, J @ Region 3, Office of Director 5pp 25745 145 24X Fiche 50-341, 84/08/02, 8408070354
- 8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp Instituted.effective 840820 Preprinted form will be used rather than ltr KEPPLER.J 9 Region 3, Office of Director 84/08/03 Commonwealth Edison Co App 25942 188 24% Fiche 50-000,84/08/03.840870401
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN, E. L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 26067 158 24X Fiche 50-000.84/08/06.8408010337
- 8408230141 Forwards IE Insp Rept 50-341/84-30 on 840627-29 & 0710-12 & notice of violation SPESSARD.R L Region 3, Office of Director 84/08/06 JENS,W H Detroit Edison Co 2pp 26214 001 24X Ficho 50-341,84/08/06,8408230141
- --8408230142 Notice of violation from insp on 840627-29 & 0710-12 SPES9ARD.R L Region 3. Office of Director 84/08/06 lp 26214 003 24X Fiche 50-341.84/08/06.8408230141
- --8408230144 IE Insp Rept 50-341/84-30 on 840627-27 & 0710-12
  Noncompliance noted failure to take appropriate corrective action re shore barrier structure configuration deviations NORTON.J. WILLIAMS.C Region 3. Office of Director 84/08/03 10pp 26214 004 24% Fiche 50-341.84/08/06.8408230141
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 90-000,84/08/08,8408070120
- B40Bi30i53 Ack receipt of 840724 ltr informing NRC of steps taken to correct violations noted in IE Preoperational Safeguards Insp Rept 50-341/84-18 Corrective measures will be examined during subsequent insp AXELSON. H L Region 3, Office of Director 84/08/08 JENS, W H Detroit Edison Co 1p 26007 350 24X Fiche 50-341,84/08/08,8408130153.

- --8408130163 Responds to NRC 840621 ltr re violations noted in IE Preoperational Safeguards Insp Rept 50-341/84-18 Corrective actions we design of main personnel access facility % potential design weakness within warehouse withheld JENS.W H Detroit Edison Co 84/07/24 KEPPLER.J G Region Office of Director Ip 26007 351 24X Fichs 50-341,84/08/08408130183 24x Fiche 50-341,84/09/08, 8408130153
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list\_enc1
  - CRACE. J N Division of QA, Safeguards & Inspection Programs (Post B30103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24x Fiche 50-000,84/08/10,8408070376
- 8408270084 Forwards Insp Rept 50-341/84-27 on 840709-13 & 25 No noncompliance noted PAPERIELLD, C J Rec Region 3. Office of Director B4/08/10 JENS. Co 2pp 26258 210 24% Fiche 50-341.84/08/10. JENS, U. R. Detroit Edison Co B408270084
- --B409270090 Insp Rept 50-341/84-27 on 840709-13 & 25 No noncompliance noted Major areas inspected preoperational radiation protection program, facilities, equipment, NUREG-0737 ltems, status of preoperational sys & drain sys HUETER, L. J., OILL, C.F., GREGER, L. R. Region 3, Office of Director 84/08/10 20pp 26258 212 24X Fiche 50-341,84/08/10,8408270084
- 8408100009 IE Info Notice 84-63. "Defective RHR Replacement Piping "
  - 308100009 IE Info Notice Carol.

    Svc list encl

    JORDAN.E L. Division of Emergency Preparedness & Engineering

    JORDAN.E L. Division of Emergency Preparedness & Engineering

    Response (Post 830103) 84/08/13 Consolidated Edison Co of New

    York, Inc. 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408300203 Forwards Insp Rept 50-341/84-17 on 840514-17,0529-0601 & 29 & notice of violation LITTLE, R S Region 3, Office of Director 84/08/14 JENS, W H Detroit Edison Co 2pp 26306 244 24X Fiche 50-341,84/08/14,
  - Detroit Ed 8408300203
- --8408300207 Notice of violation from insp on 840514-17,0529-0601 & 29 LITTLE,N S Region 3, Office of Director 84/08/14 ip 26306 248 24X Fiche 50-341,84/08/14,8408300203
- --8408300220 Insp Rept 50-341/84-17 on 840514-17.0527-0601 & 27
  Noncompliance noted personnel performed Raychem heat shrink
  application on Valve V4-2080 w/o previous training &
  Inadequate design review performed
  NAIDU,K , FALEVITS, Z , GAUTAMA Region 3, Office of Director
  84/08/14 35pp 26306 249 24% Fiche 50-341.84/08/14.8408300203
- 8408100038 IE Info Notice 84-64, "SWR HPCI Initiation Seal-In & Indication " Syc list encl JORDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fichs 50-000,84/08/15,8408100038
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Syc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Rasponse (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000.84/08/16.8408100021
- B40B100055 IE Info Notice 84-66, "Undetacted Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000-84/08/17,8408100055
- 9408140208 IE Info Notice 84-67. "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000:84/08/17,8408140208
- 940B3103B1 Forwards Insp Rept 50-341/84-31 on 840730-0803 No items of noncompliance identified SPEEBARD, R L. Region 3. Office of Director 84/09/17 JENS, W Detroit Edison Co 2pp 26333 303 24X Fiche 50-341, 84/08/17, 84083103B1 JENS, W. H.
- -8408310394 Insp Rept 50-341/84-31 on 840730-0803 No items of noncompliance or deviations noted Major areas inspected testing of pipe support & restraint sys & quality & design documents of safety-related piping sys in RHR complex (AMPHANN P D. DANIELSON) DH Region 3. Office of Director 84/08/16 6pp 26333 305 24% Fiche 50-341.84/08/17.8408310381

- 8408210142 IE Info Notice 84~68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JCROAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142
- 8408270348 Ack receipt or 840808 ltr informing NRC of steps taken to correct violations noted in Emergency Preparedness
  Appraisal Rept 50-341/83-24
  PAPERIELLO,C J Region 3. Office of Director 84/08/22 JENS.W H
  Detroit Edison Co 1p 26242 361 24X Fithe 50-341.84/08/22. 8408270348
- ---B408270352 Responds to NRC B40201 ltr re violations noted in Emergency Preparedness Appraisal Rept 50-341/83-24 Corrective actions numerical values used to determine emergency classification incorporated into equipment air locks

  JENS. W H Detroit Edison Co. B4/08/08 PAPERIELLO.C J Region
  3. Office of Director 1p 26242 362 24X Fichs 50-341,84/08/22.
- B Reportable occurrences, LERs & related correspondence
- 8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated SHERMODD. G O General Electric Co 84/04/13 DEYDUNG.R C Director's Office. Office of Inspection and Enforcement 3pp 24222 256 24X Fiche 50-000.84/04/13.8408240348
- 8408080511 Final deficiency rept.ltem 61 re undersized battery cables Initially reported on 820312 Design changes issued to require larger cables for affected motor operated valves & installation of interposing relays in trip/close circuits JENB,W H Detroit Edison Co 84/07/23 KCPPLER,J G Region 3, Office of Director 2pp 25975 262 24X Fiche 50-341,84/07/23, 8408080911
- 8408080516 Final deficiency rept. Item 87 repossible ITE circuit breaker failures Initially reported on 830304 Replacement solid state trip devices. w/Sprague Type 137D capacitor, obtained Mod request issued

  JENG, W H Detroit Edison Co 84/07/23 KEPPLER, J G Region 3, Dffice of Director 2pp 25975 267 24X Fiche 50-341, 84/07/23, 8408080516
- G40B090055 Interim deficiency rept. Item 131 re weldolets lacking complete chemical analysis documentation Initially reported un G40627 Corrective action to be determined upon completion of investigation Reported under Part 21 by Guyon Alloys JENS, W H Detroit Edison Co B4/07/24 KEPPLER, J G Region 3, Office of Director 2pp 25992 333 24X Fiche 50-341, 84/07/24, 840B090055
- 8408070062 Final deficiency rept. Item 91 re broken/cracked puffer piston rods in Brown Bover: 3HK circuit breakers (IE Info Notice 83-84) Item not reportable under 10CFR50 55(e) as deficiency would not adversely affect safe operation JENS:W H Detroit Edison Co 84/07/24 KEPPLER:J 9 Region 3: Office of Director 2pp 23992 141 24X Fiche 50-341,84/07/24. B40B070062
- B40B090071 Final deficiency rept. Item 130 re insufficient clearance between main steanlines & containment walls Initially reported on B40626 Pipe whip restraint design mod initiated to reduce gap between main steamline & restraint JENB.W H Detroit Edison Co. B4/07/24 KEPPLER, J G. Region 3, Office of Director 2pp 25992 334 24% Fishe 50-341.84/07/24, 8408090071
- 8408140016 Final deficiency rept. Item 104 re premature resetting of automatic digital load sequencer sys Initially reported on 831004 Control logic wiring separated from output relay contact wires to reduce voltage & surge assemblies added JENB.W H Detroit Edison Co 84/08/01 KEPPLER. J 9 Region 3, Office of Director 2pp 26044 166 24X Fiche 50-341,84/08/01.8408140016
- 8408160444 Final deficiency rept. Item 40 re calibr tolerances for torque wrenches Initially reported on 810303 Corrective actions include audit of site contractor torque wrench calibr programs Wrenches recalibr & tolerances clarified JENS: W H Detroit Edison Co 84/08/01 KEPPLER. J G Region 3. Office of Director 3pp 26107 273 24X Fiche 50-341,84/08/01. 8408160444
- B40B220207 Final deficiency rept.ltem 94 re loose pole piece wedges on four emergency diesel generators Initially reported on B30427 Dovetail wedges replaced w/stronger & longer model JENS.W H Detroit Edison Co 64/08/08 KEPPLER.J G Region 3, Office of Director 3pp 26189 143 24X Fiche 50-341,84/08/08, 840920209

- 8408220135 Final deficiency rept. Item 92 re structural steel sliding connections Initially reported in Apr 1983 Drawings revised to specify torque values Affected connections reworked JENS, WH Detroit Edison Co. 84/08/09 KEPPLER, J. G. Region 3. Office of Director 2pp 26198 060 24X Fiche 50-341,84/08/09,840820135
- 8408220175 Final deficiency rept. Item 66 re core spray pump motor damage Initially reported in Apr 1982 All damaged parts replaced & equipment inspected to ensure quality at installation

  JENS, W H Detroit Edison Co 84/08/09 KEPPLER, J G Region 3, Office of Director 2pp 26169 176 24X Fiche 50-341,84/08/09,8408220175
- B40B220193 Final deficiency rept.ltem 75 re calibr groblems w/Rosemount trip units Initially reported on 820720 Trip unit potentiometers made w/silver contacts replaced.recalibr & installed
  JENS.W H Detroit Edison Co 84/08/09 KEPPLER.J @ Region 3, Office of Director 2pp 26189 063 24X Fiche 50-341.84/08/09, 8408220193
- 8408300216 Final deficiency rept. Item 37 re Fisher Controls control valve actuators Initially reported on 801231 Engineering specs revised to include valve natural frequency criteria Actuators replaced JENS, W H Detroit Edison Co 84/08/14 KEPPLER, J G Region 3, Office of Director 2pp 26307 055 24X Fiche 50-341,84/08/14,8408300216
- B40B300045 Final deficiency rept, Item 113 re linear indications in seams of ASTM A500 Grade B tube steel Initially reported on B401B3 Supports fabricated from affected tube steel identified & being replaced JENS.W H Detroit Edison Co 84/08/15 AEPPLER.J G Region 3. Office of Director 2pp 26307 072 24X Fiche 30-341,84/08/15,880B300045
- 840830004i Final deficiency rept. Item 126 re underrated terminal blocks in Limitorque motor operated valve operators Initially reported on 840504 Twelve terminal blocks removed Four motor operators hard wired JENS. W H Detroit Edison Co 84/08/15 KEPPLER. J G Region 3, Office of Director 3pp 26307 308 24X Fiche 50-341,84/08/15, 840920641
- 8408300069 Final deficiency rept. Item 55 re defective spot welds in powerstrut support mot! Initially reported on 820211 Purchase & installation of all powerstrut configurations suspended by LK Comstock Supports reinfaced or replaced JENB. W H Detroit Edison Co 84/08/15 KEPPLER. J O Region 3, Office of Director 3pp 26307 175 24X Fiche 50-341,84/08/15,840830069
- 8408300209 Final deficiency rept. Item 74 re sway strut paddles clamped rigid Initially reported on 820702 Installation of strut assembly placed on hold while problem resolved Components modified JENB. H Detroit Edison Co. 84/08/15 KEPPLER. J G Region 3. Office of Director 2pp 26307 046 24X Fiche 50-341,84/08/15,
- 8408300223 Final deficiency rept, Item i20 re NPS Industries, Inc pipe support components w/same part number Initially reported on B40319 NPS Industries changed physical dimensions of parts, but parts retained same part number JENS, W H Detroit Edison Co 84/08/15 KEPPLER, J G Region 3, Office of Director 2pp 26306 338 24% Fiche 50-341,84/08/15, B408300223
- 8408300251 Final deficiency rept. Item 68 re defective pipe support strut swivel bearings Initially reported on 820514
  Engineering hold placed on all rework, pending resolution of problem & development of coordinated corrective action plan JENG, W. H. Detroit Edison Co. 84/08/13 KEPPLER. J. G. Region 3, Office of Director. 3pp. 26307-028 24X Fiche 50-341,84/08/15,8408300251
- 8408300257 Final deficiency rept, Item 50 re linear indications in Parker-Hannifin stainless steel tees Initially reported on 820112 All tees from affected heat numbers liquid penetrant tested & accepted or cut out & replaced JENS.W H Detroit Edisor Co 84/08/15 KEPPLER, J O Region 5, 84/08/15 of Director 3pp 26307 035 24X Fiche 50-341,84/08/15, 8408300257
- 8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly vaives encl GE lacks technical info to adequately evaluate condition
  VILLA: General Electric Co 84/08/21 RDSSI.C E Director's
  Office, Office of Inspection and Enforcement 3pp 26318 327 24%
  Fithe 50-000,84/08/21.8408310186

#### V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners WALKER, R D Region 3. Office of Director 84/08/10 Michigan, Univ of. Ann. Arbor. MI 2pp 26051

#### DOCKET 50-344 TROJAN NUCLEAR PLANT

- F Security, medical, emergency & fire protection plans
- 8408090017 Forwards IE Insp Rept 50-344/84-13 on 840514-18 & 29-0601 No noncompliance noted WENSLAHSKI.F A Region 5, Office of Director 84/07/25 WITHERB.B D Portland General Electric Co 2pp 25994 341 24X Fiche 50-344.84/07/25.8408090017
- --8408090021 IE Insp Rept 50-344/84-13 on 840514-18 & 29-0601 No violations noted Major areas inspected radiation protection program during refueling outage.including general employee training.organization & staffing & records & repts CILLIS,M., YUHAS,O.P. Region 5. Office of Director 84/07/18 19pp 25994 343 24% Fiche 50-344,84/07/25,8408090017
- 8408060058 Revised radiological emergency response plan implementing procedures, including EP-16, "Drills & Exercise," EP-24 1, "Emergency Reponse Manager," EP-24 2, "Radiological Manager," & EP-25, "Operation of Company " W/840727 1tr PUZEY, A M Portland General Electric Co 84/07/27 38pp 25723 008 24% Fiche 50-344.84/07/27,8408060058
- B40B1000SB Revs to radiological emergency response plan implementing procedures, including EP-B 8, "Dase Assessment Director" & EP-B 11, "Emergency Operations Facility Dose Assessment Staff " U/B40B03 transmittal form PUZEY, A M Portland General Electric Co B4/07/31 23pp 25990 074 24X Fiche 50-344,84/07/31,8408100058
- 840Bi30414 Forwards "Trojan Nuclear Plant 10CFR50, App R Review," describing util reassessment of compliance w/App R requirements & requests for exemptions implementation schedule will be provided by 840915 WITHERS. B D Portland General Electric Co 84/07/31 MILLER, J R Operating Reactors Branch 3 2pp 26109 001 24x Fiche 50-344.84/07/31.8408130414
- --8408130416 "Trojan Nuclear Plant 100FR30.App R Review "
  \* Portland General Electric Co 84/07/31 600pp 26109 005
  24X Fithe 50-344.84/07/31.8408130414
- 8408280233 Revised radiological emergency response plan implementing procedures.including EP-1 re emergency classification.EP-5 re emergency notification t EP-5 1 re notification of non-Trojan offsite emergencies

  # Portland General Electric Co 84/08/07 556pp 26273 109 24X Fiche 50-344.84/08/07.8408280283
- B40B210272 Revised radiological emergency response plan implementing procedures, including Rev B to EP-17 re medical & Rev I to EP-24 re long-term emergency organization W/B40B10 transmittal memo PUZEY, A M Portland General Electric Co B4/0B/10 33pp 26179 241 24X Fiche 50-344, B4/0B/10, B40B210292
- 8408210415 Requests extension for implementation of upgraded emergency operating procedures from Third Quarter 1985 until Fourth Quarter 1985 Extension will allow all licensed operators to receive training in use of new procedures at simulator WITHERS, B D Portland General Electric Co 84/08/15 EISENHUT, D Q Division of Licensing 5pp 26180 339 24% Fiche 30-344, 84/08/15, 8408210415
- 8408310315 Advises that Amend 4 to radiological emergency response plan acceptable.per 10CFRSO 47 & Rev I to NUREG-0654
  8CHUBIER:M D Region 5, Office of Director 84/08/17 Portitand General Electric Co 2pp 26333 298 24X
  Fiche 50-344.84/08/17.8408310315

#### G Adjudicatory correspondence

840,9250.251 Memorandum & order directing parties or counsel to attend 840.612 prehearing conference in Portland, OR re spent fuel pool amend Served on 840.925
SMITH.I W Atonic Safety and Licensing Board Panel DSB 312
84/05/24 1p 346.56.086 24X Fiche 50-344,84/05/24,840.9250.251

- K Utility Final Safety Analysis Report (FSAR) & amends
- 8408020050 Forwards Amend 2 to updated FSAR for Trojan Nuclear Power Plant Ack of receipt requested LENTSCH.J W Portland General Electric Co 84/07/20 Record Services Branch (Document Control Desk) ip 26003 090 24X Fiche.50-344,84/07/20,8408020050
- --8408020051 Amend 2 to updated FSAR for Trojan Nuclear Power Plant \* Portland General Electric Co 84/07/31 623pp 26003 091 24X Fichg 50-344.84/07/20,8408020050
- P Operating license stage documents & correspondence
- B40B3i0149 FDIA request for detailed instructions re use of risk assessment techniques & analysis & calculations on which ground accelerations for design & max hypothetical earthquake based CALBOYAS. C D Affiliation Not Assigned 84/05/12 NRC No Detailed Affiliation Given 4pp 26351 359 24% Fiche 50-344,84/05/12,84083i0149
- 8408310147 Partial response to FOIA request for detailed instruction reuse of risk assessment techniques & analysis & calculations on which ground accelerations for design & max hypothetical earthquake based Documents available in PDR FELTON.J M Division of Rules and Records 84/06/01 CALSOYAS.L D Affiliation Not Assigned 1p 26351 358 24X Fiche 50-344,84/06/01 8408310147
- 8408070082 Forwars safety evaluation based on review of 831104 & B40330 submittals re automatic actuation of shunt trip attachment for reactor trip breakers in response to Item 4 3 of Generic Ltr 83-28 Proposed mods acceptable MILLER. J R Operating Reactors Brench 3 84/07/26 WITHERS, B I Portland General Electric Co 2pp 25955 259 24X Fiche 50-344,84/07/26.8408070082
- --8408070084 Safety evaluation re Item 4 3 of Generic Ltr 83-28 concerning reactor trip breaker automatic shunt trip Progrased mods provided in 831104 & 840330 submittals acceptable

  \* NRC ~ No Detailed Affiliation Given 84/07/26 10pp 25953 261 24% Fiche 50-344.84/07/26,8408070082
- 8408020057 Forwards POE-1021, "Offsite Dose Calculation Manual " Manual revised to reflect LCA 50.Rev 2. "Radiological ETS " WITHERS. B D Portiand General Electric Co 84/07/27 Miller. J R Operating Reactors Branch 3 ip 25900 290 24X Fiche 50-344.84/07/27.8408020057
- --B408020059 Forwards PGE-1021, "Offsite Dose Calculation Manual"
  Requests act of receipt
  LENTECH.J W Portland General Electric Co B4/07/27 MILLER, J R
  Operating Reactors Branch 3 1p 25900 291 24X
  Fiche. 50-344. 84/07/27, 8408020057
- --8408020061 "Offsite Dose Calculation Manual"

  \* Portland General Electric Co 84/07/31 87pp 25900 292 24X
  Fiche 50-344,84/07/27,8408020057
- 10807050B Forwards Amend 89 to License NPF-1 Amend changes min required load for testing omergency diesel generators & deletes 18-month surveillance test
  MILLER, J H Operating Reactors Branch 3 84/07/27 MITHERS, E D Portland General Electric Co 4pp 25956, 226 24X
  Fiche 50-344,84/07/27,8408070508
- --8408070511 Amend 89 to License NPF-1, changing min required load for testing emergency diesel generators & deleting 18-month surveillance test MILLER, JR Operating Reactors Branch 3 84/07/27 5pp 25956 230 24X Fiche 50-344,84/07/27,8408070508
- 8408090237 Supple B40608 response to NRC B40508 ltr re electrical separation problem on Panel C-41 Problem isolated incident & not reflective of GA program weakness Addl physical insp of control room panels completed WITHERS. B D Portland General Electric Co B4/07/27 MARTIN, J B Region 5. Office of Director 3pp 25994 151 24X Fiche 50-344.84/07/27,8408090237
- 8408090158 Provides status of regulatory requirements verification program, per 830928 commitment Deficiencies found in 19 of 79 items reviewed Evaluation initiated to determine reportability & corrective action MITHERB.8 D Portland General Electric Co. 84/07/31 MARTIN. J B Region 5. Office of Director 2pp 25972.290 24X Fiche 50-344.84/07/31.8408090158

- B4G9170144 Forwards Amend 90 to License NPF-1 & safety evaluation Amend revises surveillance requirements for verifying reactor shutdown margin when one or more control rods immovable or untrippable & when starting up reactor TRAMMELL.C M Operating Reactors Branch 3 84/08/02 WITHERS.B D Portland General Electric Co 1p 26/34 328 24X Fiche 50-344.84/08/02.8408/170144
- --8408170147 Amend 90 to License NPF-1, revising surveillance requirements for verifying reactor shutdown margin when one or more control rods immovable or untrippable & when starting up reactor

  MILLER, JR Operating Reactors Branch 3 84/08/02 4pp
  26134 329 24X Fiche 50-344.84/08/02.8408170144
- --8408170150 Safety evaluation supporting Amend 90 to License NPF-1 \* Office of Nuclear Reactor Regulation, Director 84/08/02 2pp 26134 333 24X Fiche 50-344.84/08/02.8408170144
- 6408070447 Forwards add1 info re containment high-range radiation monitors & containment spray pump motors/per 840628 request Request for schedule extension & justification for continued operation previously provided WITHERS, B D. Portland General Electric Co. 84/08/03 MILLER, J. Operating Reactors Branch 3. 4pp. 25942 259 24X Fiche 50-344.84/08/03.8408070447
- B408080314 Forwards add1 fee for Amend 68 to License NPF-1, increasing storage capacity of spent fuel pool WITHERS, B D Portland Ceneral Electric Co 84/08/03 DIGGS, R M License Fee Management Branch 1p 25944 i10 24X Fiche 50-344,84/08/03.8408080316
- 8408070110 Generic Ltr 84-17 to all licenses of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Generic Safety Issues " Svc list enci EISENHUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24% Fichs 50-000,84/08/06,8408070110
- 8408140073 Ack receipt of 840612 Class II for for proposed Tech Bper changes re hydrogen mixing sys C5-B flow verification value Class III for required since review involved single safety issue DIGGS.R M License Fee Management Branch 84/08/06 WITHERS.R D Portland General Electric Co ip 26061 266 24X Fiche 50-344.84/08/06.8408140073
- 8408170007 Responds to 840601 request for extension of final environ qualification of equipment until end of next refueling outage Extension granted DENTON, HR Office of Nuclear Reactor Regulation, Director 84/08/06 WITMERS, B D Portland General Electric Co 2pp 26135 3355 24X Fiche 50-344.84/08/06,8408170007
- B408140202 Forwards clarification of responses to 840504 ltr reproposed snubber Tech Specs Tech Spec LCA 73 will be revised to add quantitative acceptance Criteria & resubmitted by B41001
  HITHERB.D D Portland General Electric Co 84/08/09 MILLER.J R Operating Reactors Branch 3 4pp 26044 328 24X Fiche 50-344.84/08/09.8408140202
- B40B140289 Forwards summary of control rod guide tube support pin replacement evaluation.per NRC request Bummary of Steam Generator B insp & repair work.as result of damage due to failure of control rod guide tube support pins.also encl HITHERS.B D Portland General Electric Co 84/08/09 MILLER.J R Operating Reactors Branch 3 10pp 26054 347 24X Fiche 50-344.84/08/09.8408140289
- 8408210139 Forwards safety evaluation concluding that loose/missing components from control rod guide tube support pins in RCS does not have adverse effect on public health & safety One of two missing sets of nuts; locking disks & pins found WITHERS: B D Portland General Electric Co 84/08/15 MILLER, J R Operating Reactors Branch 3 15pp 26183 039 24X Fiche 50-344.84/08/15,8408210139
- 8408210438 Requests extension until 841031 to respond to Generic Ltm 84-15, requesting info on diesel generator reliability & description of diesel generator reliability program Extended refueling outage drained manpower resources WITHERS. B D. Portland Ceneral Electric Co. 84/08/15 EISENHUT, D. G. Division of Licensing ip 26181 255 24X Fiche 50-344,84/08/15,8408210438

- 8408200273 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list enc: EIGENHUT, D © Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000,84/08/20,8408200275
- 8408280242 Advises of delay in submitting schedule for response to 840606 questions on asymmetric LOCA loads WITHERS, B D Portland General Electric Co 84/08/24 MILLER, J P Operating Reactors Branch 3 ip 26261 340 24X Fiche 50-344.84/08/24.8408280242
- O Inspection reports, IE Builetins & correspondence
- 8408130304 Requests assistance in assessing 840622 IE Insp Rept 50-344/84-14 Problems encountered in avaluating & reconstructing 840504 RHR loss of cooling event MARTIN.J B Region 5. Office of Director 84/06/22 WITHERS, B Partland General Electric Co ip 26010 256 24X Fiche 50-344.84/06/22 8408130304
- 8408010278 Ack receipt of 840531 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-344/84-08 Corrective actions will be verified during future insp BISHOP. T W Region 5. Diffice of Director 84/07/16 WITHERS. B D Portland General Electric Co ip 23866 196 24X Fiche 50-344,84/07/16,8408010278
- --8408010281 Responds to NRC 840907 ltr re violations noted in IE Insp Rept 50-344/84-08 Corrective actions Tech Spec change will be requested, per Generic Ltr 83-43, to replace existing requirements u/documents referencing 100FR80 72 WITHERS, B D Portland General Electric Co 84/05/31 MARTIN, J B Region 5, Office of Director 3pp 29866 197 24X Fiche 50-344,84/07/16,8408010278
- B408030262 Ack receipt of 840604 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-344/84-10
  BISHOP.T.W Region 5. Office of Director B4/07/17 Portland General Electric Co 1p 25917 iii 24X Fiche 50-344.84/07/17.6408030262
- 8408080494 Forwards IE Insp Rept 50-344/84-15 on 840604-08 No violations noted Meaknesses in oversight of GA program observed Assessment of situation requested within 30 days BISHOP, T W Region 5. Defice of Director 84/07/20 WITHERS, B D Portland General Electric Co 2pp 25975 205 24X Fiche 50-344,84/07/20.8408080494
- --8408080497 IE Insp Rept 50-344/84-15 on 840604-08 No nuncompliance or deviations noted Major areas inspected reactor internals mods to reverse bypass flow direction & provide for assessing adaquacy of QA program HAIST.DP, HON.A, DODBS,RT Region 5, Office of Director 84/07/19 13pp 25975 207 24X Fichs 50-344,84/07/20,8408080494
- 8408070075 Forwards IE Insp Rept 50-344/84-16 on 840709-13 No noncompliance noted WENSLAWSKIF A Region 5, Office of Director 84/07/23 WITHERS B D Portland Opneral Electric Co 2pp 25992 212 24X Fiche 50-344,84/07/23,8408090075
- --B4080900B0 IE Insp Rept 50-344/84-16 on 840709-13 No noncompliance or deviations noted Major areas inspected transportation, info notice followup & facility tour CILLIS,M , NORTH,H , YUHAB,O P Region 5, Office of Director B4/07/20 App 25992 214 24% Fiche 50-344,84/07/23,8408090075
- 8408090017 Forwards IE Insp Rept 50-344/84-13 on 840514-18 & 29-0601 No noncompliance noted HENSLAHSKI,F A Region 5, Office of Director 84/07/25 WITHERS, B D Portland General Electric Co 2pp 25994 341 24X Fiche 50-344,84/07/25.8408090017
- --8408090021 IE Insp Rept 50-344/84-i3 on 840514-i8 & 29-0601 No violations noted Major areas inspected radiation protection program during refueling outage, including general employee training, organization & staffing & records & repts CILLIS.M., YUHAS.O P Region 5, Office of Director 84/07/18 19pp 28994 343 24X Fiche 50-344,84/07/25,8408090017
- 8407250227 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc 119pp 25865 047 24% Fiche 50-000,84/07/27,8407250229

- 8408300373 Forwards Insp Rept 50-344/84-17 on 840604-0711 & notice of violation BISHOP, TW Region 5. Office of Director 84/08/01 WITHERS, B D Portland General Electric Co 2pp 26308 244 24X Fiche 50-344. B4/08/01. 8408300373
- ---B40B300377 Notice of violation from insp on 840604-0706 DDDD9s.R T Region 5. Diffice of Director 84/08/01 ip 26308 246 24X Fiche 50-344,84/08/01.8408300373
- --B40B3003B0 Insp Rept 50-344/B4-17 on 840604-0711 Violation noted temporary demineralizer sys from spent fuel cask loading pit to spent fuel pool purification pump installed w/o boing controlled or evaluated RICHARDS.S A. JOHNSTON.G W., DODDS.R T. Region 5, Office of Director 84/07/25 10pp 2630B 247 24X Fiche 50-344.84/08/01.840B300373
- 8408010333 IE Info Notice 84-89, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc 122pp 24048 OD1 24% Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list enci JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 24067 158 24% Fiche 50-000.84/08/06.8408010337
- 8408130318 Ack receipt of 840622 & 0719 ltrs informing NRC of steps taken to correct violations noted in NRC 840522 & 0629 ltrs Corrective actions will be verified during future insp WENBLAHSKI.F A Region 5. Office of Director 84/08/07 HITHER, B. D Portland General Electric Co ip 26010 139 24X Fiche 50-344.84/08/07.8408130318
- 8408070120 IE Info Natice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000.84/08/08.8408070120
- 8408140289 Forwards summary of control rod guide tube support pin replacement evaluation, per NRC request Summary of Steam Generator B insp & repair work, as result of damage due to failure of control rod guide tube support pins, also encl HITHERS. B D Portland General Electric Co 84/08/09 HILLER, J R Operating Reactors Branch 3 10pp 26054:347 24X Fiche 50-344,84/08/09,8408140289
- B40B070376 IE Info Notite 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Evc list encl ORACE," N Division of GA, Bafeguards & Inspection Programs (Post B30103) B4/08/10 Consolidated Edison Co of New Yort, Inc 125pp 26130 001 24% Fiche 50-000.84/08/10.8408070376.
- 8408100009 IE Info Notice 84-63, "Defective RMR Replacement Piping "
  8vc list enc!
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197.218 24X Fiche 30-000:84/08/13,8408100009
- 8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl URDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp. 26178.073 24X Fiche 50-000,84/08/15,8408100038
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16, Consolidated Edison Co. of New York, Inc 118pp. 26178 001 24X Fichs 50-000,84/08/16,8408100021
- 8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/08/17 Consolidate Edison Co. of New York, Inc. 120pp. 26276 001 24X Fiche 50-000.84/08/17.8408100055.
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " 8vc list encl. JORDAN,E L. Division of Emergency Preparedness & Engineering Rasponse (Post 830103). 84/08/17 Consolidated Edison Co. of New York, Inc. 122pp. 24276:122 24X Fiche 30-000.84/08/17.8408140208

- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves' Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc. 115pp 26329 008 24X Fiche 50-000.84/08/21. 8408210142
- 5 Reportable occurrences, LERs & related correspondence
- 8408070060 Updated special rept on 831022, fire suppression sys in cable spreading room failed electrically fire watch established.

  Sys must now be manually actuated instead of automatically Replacement monitoring sys will be operational by 840831 VUMDT.C P Portland General Electric Co 84/07/30 MARTIN.J 8 Region 5, Office of Director ip 25973 114 24x Fiche 50-344.84/07/30.8408070060
- B408310269 Forwards "Loss of ESF Auxiliary Feedwater Pump Capability at Brajan on B30122," technical review rept Addl study recommended to investigate issue 7UKORO D J Reactor Operations Analysis Branch 84/08/01 SEYFRIT. K V Reactor Operations Analysis Branch. 1p 26350 287 24X Fiche 50-344,84/08/01,8408310269
- ---B408310275 "Loss of EBF Auxiliary Feedwater Pump Capability at Trojan on 830122," technical review rept \* Director's Office 84708/01 3pp 26350 28B 24X F{che 50-344,84/08/01,8408310269
- 8408240287 PND-V-84-051 on 840818 control rod L-3 bank D, stuck at almost fully withdrawn position during cold rod drop tests
  Beal weld for control rod guide mechanism will be cut to detarmine if latching mechanism at fault
  DDDDB R T , RICHARDS S A Region 5. Office of Director 84/08/20
  1p 26223 186 24X Fiche 50-344.84/08/20,8408240287
- 8408280149 LER 84-012-00 on 840727, new nuclear fuel assemblies transferred from new fuel storage room to spent fuel pool which was a constant of the spent fuel pool ventilation train in spec Caused by personnel error Personnel counseled W/840822 ltr BAIR-C O, YUNDT. CP Portland General Elpotric Co B4/08/22 4pp 26279 192 24X Fiche 50-344, 84/08/22, 8408280149

#### V Operator Examinations

- 8408210415 Requests extension for implementation of upgraded emergency operating procedures from Third Quarter 1985 until Fourth Quarter 1985 Extension will allow all licensed operators to receive training in use of new procedures at simulator HITHERS.8 D Portland General Electric Co 84/08/15 EISENAUT, D G Division of Licensing 5pp 26180 339 24X Fiche 50-344, 84/08/15.8408210415
  - KET 50-246 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1
    Security, medical, emergency & fire protection plans
  - B080031 Forwards exemption from requirements of App E to 10CFR50 restate & local govt participation in emergency preparedness exercises, per B40411 request RIVENDARKS W Operating Reactors Branch 4 B4/07/26 CROUSE, R P Toledo Edison Co 3pp 25781 054 24X Fiche 50-346, 84/07/26,
  - 8408080037 Exemption from requirements of App E to 10CFR50 re state & local govt participation in emergency preparedness exercise EISENHUT.D 0 Division of Licensing 84/07/27 Toledo Edison Co 4pp 25981 057 24X Fiche 50-346.84/07/26,8408080030
- 408100061 Rev 16 to Health Physics Emergency Plan Procedure HP 1602 01. "External Personnel Radiation Exposure Monitoring " W/840801 transmittal form SCOTT, R, TAPLEY, J. Tolledo Edison Co 84/07/26 26pp 25987 033 24X Fiche 50-346.84/07/26.8408100061
- 408060322 Revised emergency plan implementing procedures, including EI 1300.07. "Technical Support Ctr Activation" & index \* Toledo Edison Co 84/07/31 15pp 25933 316 24X Fiche 50-346.84/07/31.8408860322
- 408080524 Forwards Amend 74 to License NPF-3 Amend changes Tech Specs to require annual audit of emergency & security plans & implementing procedures
  STOLZ,J F Operating Reactors Branch 4 B4/07/31 CROUSE,R P
  Tolese Edison Co 4pp 25975 360 24X Fiche 50-346,84/07/31,8408080524

- --8408080527 Amend 74 to License NPF-3 changing lech Specs to require annual audit of emergency & security plan & implementing procedures SEDLZ.JF Operating Reactors Branch 4 84/07/31 4pp 2576 002 24X Fiche 50-346,84/07/31,8408080524
- B40B200073 Rev 7 to Emergency Plan Implementing Procedure EI 1300 OB, "Emergency Control Ctr Activation" HORYATH, E Toleda Edison Co 84/08/06 App 26133 305 24X Fiche 50-346.84/08/06.8408200073
- 8408130387 Ack receipt of 840723 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/83-24 Corrective actions will be examined during subsequent insp SHAFER, N D Region 3. Office of Director 84/08/07 CROUSE, R P Toledo Edison Co 1p 26011 117 24X Fiche 50-346,84/08/07, 8408130387
- --840B130370 Responds to NRC 840625 ltr re violations nated in 1E insp Rept 50-344/83-24 Corrective actions health physics personnel instructed not to conduct respiratory training outside nuclear training dept w/o approval of director CROUSE.R P Toledo Edison Co 84/07/23 NORELIUS,C E Division of Project & Resident Programs 2pp 26011 118 24X Fichs 50-346,84/08/07,8408130387
- 840Bi60021 Requests justification of emergency operating guidelines by ref to Oconee guideline approved by NRC Response by 840914 requested STOLZ.J F Operating Reactors Branch 4 84/08/08 CROUSE.R P Toledo Edison Co 2pp 26128 210 24X Fiche 50-346,84/08/08, RAORIA0021
- B408280345 Forwards FR notice of issuance of environ assessment & final finding of no significant impact re 830930 & 1230 requests for exemption from requirements of 10CFRSO, App R Related correspondence
  DEAGAZIO A Operating Reactors Branch 4 84/08/14 CROUSE, R P Toledo Edison Co 2pp 26294 024 24% Fiche 50-346, 84/08/14, nan92803445
- --8408280348 Notice of environ assessment & final finding of no significant impact re 830730 & 1230 requests for exemption from requirements of 10CFR50, App R Exemption acceptable EISENHUT, D 9 Division of Licensing 84/08/14 5pp 26274 026 24X Fiche 50-346.84/08/14.8408280345
- 8408280145 Revised emergency plan implementing procedures, including T-8185 re station response to emergencies & T-8186 re operations support ctr.activation W/840821 transmittal ltr \* Toledo Edison Co B4/08/15 App 26275 355 24X Fiche 50-346,84/08/15 8408280149
- 8408280087 Emergency Plan Implementing Procedure AD 1827 16. "Search & Rescue " W/840821 transmittal 1tr HDWATH, E A Toledo Edison Co. 84/08/14. 3pp 26261 187 24X Fiche 50-346.84/08/16.8408280087
- 8408270471 Forwards exemption from requirements of 10CFR50, App R, per B30930 request & 831230 supplemental request DEAGAZIO. A Operating Reactors Branch 4 84/08/20 CROUSE, R P Tolado Edison Co 2pp 26277 198 24% Fiche 50-346, 84/08/20, 8408270471
- ---B40B270478 Exemption from requirements of 10CFR50.App R re fire barrier separation,72 h cold shutdown conditions & lube oil collection sys EISENHUT,D 0 Division of Licensing B4/08/20 Toledo Edison Co App 26277 200 24X Fiche 50-346.84/08/20,8408270471
- 8408200126 Rev 221 to emergency plan supporting procedures rev index \* Toledo Edison Co 84/08/31 ip 26133 254 24X Fiche 50-346.84/08/31.8408200126
- K Utility Final Bafety Analysis Report (FBAR) & amends
- 8408280197 Forwards corrected pages to Rev 2 to updated FSAR for Davis-Besse Unit 1 CROUSE.R P Toledo Edison Co 84/08/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 26275 226 24X Fiche 30-346,84/08/17,8408280197
- --8408280198 Corrected pages to Rev 2 to updated FSAR for Davis-Besse Unit 1 \* Toledo Edison Co 84/07/31 21pp 26275 227 24X Fichs 50-346,84/08/17,8408280197

- P Operating license stage documents & correspondence
- 8408020172 Forwards Amend 71 to License NPF-3 & safety evaluation Amend modifies Tech Specs re definition of term "operable" as applied to ESF sys to support sys outages RIVENBARK.6 W Operating Reactors Branch 4 84/07/09 CROUSE.R P Toledo Edison Co 2pp 25898 058 24X Fiche 50-346,84/07/09,8408020172
- --B408020173 Amend 71 to License NPF-3, modifying Tech Specs redefinition of term "operable" as applied to ESF sys to support sys outages of redundant components RIVENBARK, G W Operating Reactors Branch 4 84/07/09 10pp 25898 060 24X Fiche 50-346.84/07/09,8408020172
- --8408020174 Safety evaluation supporting Amend 71 to License NFF-3 \* Office of Nuclear Reactor Regulation, Director 84/07/09 2pp 29898 070 24% Fiche 50-346.84/07/09,8408020172
- E4G8070499 Forwards Amend 72 to License NPF-3 & safety evaluation Amend modifies Tech Spec Table 3 6-2 to permit delay of surveitlance test of MBIVs until after entering Mode 3 JEAGAZIO.A & Operating Reactors Granch 4 84707/20 CROUSE.R & Toledo Edison Co 2pp 25956 239 24X Fiche 50-346,84/07/20.
- --8408070502 Amend 72 to License NPF-3, modifying Tech Spec Table 3 4-2 to permit delay of surveillance test of MSIVs until after entering Mode 3 RIVENBARK. G W Operating Reactors Branch 4 84/07/20 5pp 25956 241 24X Fiche 30-346,84/07/20,8408070499
- ~-B40B070505 Safety evaluation supporting Amend 72 to License NPF-3 \* Office of Nuclear Reactor Regulation, Director 84/07/20 3pg 25956 246 24X Fiche 50-346,84/07/20,8408070499
- 8408130530 Forwards Amend 73 to License NPF-3 & safety evaluation Amend revises Tech Specs to add new Sections 3 3 2 3 & 4 3 2 3 & Tables 3 3-15 & 4 3-15 to reflect final anticipatory reactor trip sys
  RIVENBARK.G W Operating Reactors Branch 4 84/07/25 CROUSE.R P Tolede Edison Co 3pp 26038 341 24% Fiche 50-346,84/07/25,8408130530
- --B40B130537 Amend 73 to License NPF-3 adding new Tech Spec Bections 3 3 2 3 5 4 3 2 3 & Tables 3 3-15 & 4 3-15 to reflect addition of final anticipatory reactor trip sys RIVENNARK, C W Operating Reactors Branch 4 B4/07/25 11pp 2603B 344 24X Fiche 50-346, B4/07/25, B40B130530
- --8408130545 Safety evaluation supporting Amend 73 to License NPF-3 Evaluation of licensee 821115 response to Generic Ltr 82-16 also included \* Office of Nuclear Reactor Regulation, Director 84/07/25 8pp 26038 355 24% Fiche 50-346.84/07/25,8408130530
- B408080288 Summary of 840712 meeting w/8tW Dwners Group re non-nuclear instrumentation sys status Attendance list & viewgraphs enc!

  KADAMBI.P Operating Reactors Branch 4 84/07/27 Operating Reactors Branch 4 36pp 25978 228 24X Fiche 50-000.84/07/27.8408080288
- 8408070335 Supple 831107 response to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Salem ATMS Events" Program & planned enhancements listed, including commitment to participate in NPROS CROUSE.R P Toledo Edison Co 84/07/31 STOLZ, J.F. Operating Reactors Branch 4 3pp 25945 230 24X Fiche 50-246, 84/07/31, 8408070335
- 8408080524 Forwards Amend 74 to License NPF-3 Amend changes Tech Specs to require annual audit of emergency & security plans & implementing procedures
  STDL7.J F Operating Reactors Branch 4 84/07/31 CROUSE.R P
  Toledo Edison Co 4pp 25975 360 24X Fiche 50-346, 84/07/31.
- ---8402080927 Amend 74 to License NPF-3, changing Tech Specs to require annual audit of emergency & security plan & implementing procedures
  STOLZ.JF Operating Reactors Branch 4 84/07/31 4pp 25976 002 24X Fichs 50-346,84/07/31,8408080924
- 8408150565 Forwards SER re 830818 proposed Tech Spec re containment purge & vent valve leak testing to detect excessive resilient seal deterioration Revised mail required by 840907.

  STOLZ, J F Operating Reactors Branch 4 84/08/03 CROUSE, R P Toledo Edison Co 2pp 26080 308 24x Fiche 50-346, 84/08/03, 8408150565

- --8408150569 SER re 830818 proposed Tech Spec change re containment purge & vent valve leak testing to detect seal deterioration Proposed change unacceptable GUO.J S Office of Nuclear Reactor Regulation, Director 84/08/03 Spp 26080 311 24X Ficha 50-346.84/08/03.8408150565
- 8408130421 Forwards application for amend to License NPF-3, incorporating integrated living schedule program CROUSE.R P Toledo Edison Co 84/08/04 STOLT, J F Operating Reacture Branch 4 1p 26011 030 24% Fiche 50-346,84/08/04,84/08130421
- --8408130428 Application for amend to License NPF-3, incorporating integrated living schedule program SER & significant hazard consideration rept entl CROUSE.R P Toledo Edison to 84/08/04 7pp 26011 031 24% Fiche 50-346,84/08/04,8408130421
- B408070110 Generic Ltr 84-19 to all licenses of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933. "Prioritization of Generic Safety Issues "Svc list encl EISCNHUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26127 238 24X Fiche.50-000.84/08/06.8408070110
- B40B090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984

  TREMBLAY.P P Operating Reactors Assessment Branch B4/08/06
  HOLAHAN.G M Operating Reactors Assessment Branch 13pp
  25991 350 24X Fiche 50-000.84/08/06.84080990317
- 8408230465 Forwards corrected listing of page changes & affected pages of Amend 71 to License NPF-3. submitted on 840718 STOLZ.J.F. Operating Reactors Branch 4 84/08/09 CROUSE.R.F. Toledo Edison Co. 2pp 26230 219 24% Fiche 50-346.84/08/09. 8408230465
- ---B408230470 Corrected listing of page changes & affected pages to Amend 71 to License NPF-3 \* Operating Reactors Branch 4 84/08/09 6pp 26230 221 24X Fiche 50-346, 84/08/09.8408230465
- 8408140410 Forwards "Analyses of Capsule TE1-B, Toledo Edison Co, Davis-Besse Nuclear Power Station, Unit I Reactor Vessel Hatl Surveillance Program " CRCUSE, R P Toledo Edison Co 84/08/10 EIBENHUT, D 0 Division of Licensing 1p 26049 OD1 24X Ficke 50-344,84/08/10,8408140410
- ---8408140413 "Analyses of Capsule TEI-8, Toledo Edison Co, Davis-Besse Nuclear Power Station, Unit i Reactor Vessel Matl Burvaillance Program " LGME, A , COLLINS, L L , EWING, J W Babcock & Wilcox Co IAW-1834 84/05/31 75pp 26049 002 24X Fiche 50-346, 84/08/10, 8408140410
- 840B170D02 Notification of 840828 meeting w/util in Bethesda.MD to discuss reliability of auxiliary feedwater sys & pump driver diversity DEAGAZIG.A Operating Reactors Branch 4 84/08/13 STOLZ.J F Operating Reactors Branch 4 2pp 26135 357 24% Fiche 50-346.84/08/13.8408170002
- 8408210456 Withdraws Item 4 of 810925 application for amend to License NPF-3, per 840419 Itr CROUBER P Toledo Edison Co 84/08/13 STQLZ, J F Operating Reactors Branch 4 ip 26177 205 24X Fiche 50-346,84/08/13,
- 8408R00135 Forwards addl info concerning NNREO-0737, Item II B 3 repost-accident sampling.per 840717 request Rexnord Model 340 portable oxygen monitor used to determine dissolved oxygen in reactor collant sample CRONSE, R P Toledo Edison Co 84/08/14 STOLZ, J F Operating Reactors Branch 4 17pp 26133 260 24X Fiche 50~346,84/08/14.
- 8408230596 Requests and of 830701 application to amend Tech Spec Section 3 7 7 % Table 3 7-1 re snubbers Util should change insp frequency & testing provisions & review Generic Ltr 84-13 for guidance Revised application requested by 841001 BTOLZ.JT Operating Reactors Branch 4 84/08/15 CROUSE.R P Folede Edison Co 2pp 26230 266 24% Fiche 50-346, 84/08/15, 8408230554
- 840B280319 Forwards draft technical evaluation rept. "Control of Heavy Loads - Phase II, Davis-Besse Nuclear Power Station Unit 1." for review STOLZ-J F Operating Reactors Branch 4 84/08/17 CROUSE, R P Taledo Edison Co 2pp. 26294 053 24X Fiche 50-346, 84/08/17, 840B280319

- -8408280321 Draft "Control of Heavy Loads Phase II.Davis-Basse Nuclear Fower Station Unit i," technical evaluation rept BDMBERGER, C.R., WALTER, R.J., SARGENT, I.H. Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-489 DRFT 84/07/10 SINGH, A. NRC No Detailed Affiliation Given 26pp 26294 055 24% Fiche 50-346,84/08/17,8408280319
- 3408280488 Confirms util 840808 commitment to submit by 841001, revised Tech Specs re instrumentation for containment sump kevel & containment pressure & equipment for RCS high point vents, per Otheric Ltr 83-37 & NUREO-0737 STOLZ, JF Operating Reactors Branch 4 84/08/17 CROUSE, R P Toledo Edison Co 2pp 26272 355 24X Fiche 50-346,84/08/17. 8408280488
- 8408200275 Generic Ltr 84-20 to all licenses of operating reactors & applicants for DLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT.D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276-244 24X Fiche 50-000.84/08/20.8408200275
- Q Inspection reports. IE Bulletins & correspondence
- B407230227 IE Info Notice B4-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc. 119pp 23865 047 24% Fiche 30-000,84/07/27,8407250229
- 8408160324 Forwards IE Insp Rept 50-346/84-16 on 840724 No noncompliance noted LITTLE,W S Region 3. Office of Director 84/07/30 CROUSE,R P. Toledo Edison Co 2pp 26106 090 24X Fithe 50-346,84/07/30, 8408160324
- ~-8408160327 IE Insp Rept 50-346/84-16 on 840724 No moncompliance or deviations noted Major areas inspected follows of Titeflex metallic bellows improper attachment design, NDE & qualification testing JUNES, D E , DANIELSON, D H Region 3, Office of Director 84/07/30 2pp 26105 092 24X Fiche 50-346,84/07/3D,8408160324
- 8408070401 Informs that new sys of acknowledging receipt of licenses correspondence re noncompliance found during inspirative 840820 Preprinted form will be used rather than ltr
  KEPPLER.J G Region 3. Office of Director 84/08/03
  Jammonwealth Edison Co 3pp 25942 188 24X Fiche 50-000, 84/08/03.
  3408070401
  - )B010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Sesponse (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122py 26058 001 24X Fiche 50-000, 84/08/06, 8408010333
  - 3010337 1E Info Notice 84-60, "Failure of Air Purifying Respirator ilters to Meet Efficiency Requirement " Svc list encl RROAM, E L Division of Emergency Preparedness & Engineering espanse (Post 830103) 84/08/06 Consolidated Edison Co of New ark, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- 3130397 Ack receipt of B40723 ltr informing NRC of steps taken to arrect violations noted in IE Insp Rept 50-346/83-24 .arrective actions will be examined during subsequent insp HAFER.M.D Region 3. Office of Director 84/08/07 CRQUSE.R P Folded Edison Ca ip 26011 117 24X Fiche 50-346,84/08/07. 3408130387
- 340B130390 Responds to NRC 840623 ltr re violations noted in IE Insp Rept 30-346/83-24 Corrective actions health physics personnel instructed not to conduct respiratory training outside nuclear training dept w/o approval of director CRGUSE, R P Toledo Edison Co 84/07/23 NORELIUS, C E Division of Project & Resident Programs 2pp 26011 118 24X Fiche 50-346,84/08/07,8408130387
- )Bi30407 Ack receipt of 840718 ltr informing NRC of steps taken to orrect violations noted in IE Insp Repts 30-346/83-01 & 50-346/84-04 SHAFER; N D Region 3, Office of Director 84/08/07 CRDUSE, R. P Tolsdo Edison Co 1p 26011 018 24X Fiche 50-346, 84/08/07.

- --840813041; Responds to NRC 840418 ltr re noncompliance noted in IE Insp. Repts 50-346/83-01 & 50-346/84-04 Corrective actions commitment tracking sys established for entire station & sys utilized by maint staff CROUSE.R P Toledo Edison Co. 84/07/18 NORELIUS.C Region 3. Office of Director 11pp 26011 019 24X Fiche 50-346.84/08/07.8408130407
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York, Inc. 120pp 26127 118 24% Fiche 50-000.84/08/08.8408070120
- 8408130391 Ack receipt of 840727 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/84-06 SHAFER; & D Region 3, Office of Director 84/08/08 CROUSE, R P Toledo Edison Co ip 26011 102 24X Fiche 50-346,84/08/08,8408130391
- --840B130373 Responds to NRC 840627 ltr reviolations noted in IE Insp. Rept 50-346/84-06 Corrective actions licensed personnel reminded to comply w/prompt notification requirements & counseled on requirements for completing commitments CROUSE.R P Toledo Edison Co 84/07/27 NORELIUS.C E Division of Project & Resident Programs 3pp 26011 103 24X Fiche 50-346,84/08/08,8408130391
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list encl GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000.84/08/10.8408070376
- 840B100009 IE Info Notice 84-63, "Defettive RHR Replacement Piping "
  Svc list encl
  JURDANNE L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fithe 30-000,84/08/13,8408100009
- 8408170214 Forwards SER providing justification re request for relief from quarterly reverse flow testing of various svc water check valves Safety function of check valves to isolate trains will be provided by locked closed gate valves (AGUSC, R P Toledo Edison Co 84/08/14 STOLZ, J F Operating Reactors Branch 4 4pp 26/18 098 24X Fiche 50-346,84/08/14,8408/1702/14
- 8408100038 IE Info Notice 84-44, "BWR HPC1 Initiation Seal-In & Indication " Svc list encl JORDAN, E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24% Fiche 50-000,84/08/15,8408100038
- B40B210345 Forwards Relief Request 30 requesting exemption from testing valves DH-11 & DH-12.per requirements of 10CFR50.App J, Section III A i & III C Revised pages to inservice insp valve program.submitted on 800315.also encl W/o rev CRDUBE.R P Taledo Edison Co 84/08/13 STOLZ.J F Operating Reactors Branch 4 3pp 261B0 197 24X Fiche 50-346,84/08/15,840B210345
- 8408100021 IC Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " 8vc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021
- 8408100055 IE Info Notice 84-66. "Undetected Unavailability of Turbins-Driven Auxiliary Feedwater Train " Evc list encl URBAN, E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- B40814020B IE Info Notice B4-67. "Recent Snubber Inservice Testing W/
  High Failure Rates " Svc list encl
  JORDAN: E.L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/17 Consolidated Edison Co of New
  York: Inc 122pp 26276 122 24X Fiche 50-000.84/08/17.8408140208.
- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl. JURDAN, E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc. 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

#### R Periodic operating reports & related correspondence

- B408230104 "Effluent & Waste Disposal Semiannual Rept,Jan-June 1984"
  W/840815 ltr
  GUENNOZ,S M Toledo Edison Co 84/06/30 KEPPLER,J G Region 3,
  Office of Director 88pp 26209 063 24X Fiche 50-346,84/06/30,
  8408230104
- 8 Reportable occurrences, LERs & related correspondence
- 840B010313 LER 84-010-00 on 840624,loss of power to Y4.Channel 4 essential 120-volt ac bus.experienced Caused by failure of YV4 inverter due to failure of rener diode & resistor in logic power supply circuit board W/840724 ltr NARUS.0 E . MURRAY.T D Toledo Edison Co 84/07/24 4pp 25966 147 24X Fiche 50-346.84/07/24,8408010313
- 8408080508 Revised LER 94-003-01 on 840302 MSIV 2 closed, isolating steam side of steam generator 2 Caused by failed relay in safety instrumentation channel MSIV replaced Failed relay circuit repaired SHANGER, F Toledo Edison Co 84/07/26 ip 25975 258 24X Fishe 50-346.84/07/26.8408080508
- 8408070026 LER 84-003-01 on 840302.w/unit operating at 99% power.MSIV closed, isolating steam side of steam generator 2 Caused by undetected failed relay in safety instrumentation channel Relay replaced W/840727 ltr BMANGER.F, MURRAY.T D Toledo Edison Co 84/07/26 5pp 25972 257 24% Fiche 50-346.84/07/26,8408090026
- 8408160199 LER 84-006-01 on 840515, makeup level tank dropped at rate of three gpm Leak discovered in vicinity of pressurized spray control valve Reactor shut down & leak found in spray valve bypass valve Valve replaced W/840809 ltr
  NARUS, 0 E, OURNOZ. S N Toledo Edison Co 84/08/09 4pp
  26106 338 24X Fithe 50-346,84/08/09,8408160199
- 8408160497 LER 83-074/03X-1 on 831224.borated water storage tank hi fail alarm for safety features actuation sys Channel i received Caused by improperly installed heat trace Surveillance Test 87 5031 05 modified W/840809 ltr ISLCY.T., QUENNOZ.S M Toledo Edison Co 84/08/09 3pp 26129 114 24X Fiche 50-346.84/08/09.8408160497

## V Operator Examinations

- 8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners WALKER.R D Region 3. Office of Director 84/08/10 Michigan. Univ of. Ann Arbor. MI 2pp 26051 198 24% Fiche 50-000. 84/08/10.8408140426
- X Onsite Storage of Low Level Waste
- 8408070301 Forwards add1 info re util 830714 request for approval for alternative onsite disposal of very low level radioactively contaminated secondary-aide cleanup resins GROUMER P Tolede Edison Co 84/07/30 STOLZ, J F Operating Reactors Branch 4 11pp 25947 240 24% Fiche 50-346,84/07/30, 8408070301
- DOCKET 50-348 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8408170386 Requests meeting to discuss detailed control room design review w/respect to Nuclear Util Task Action Committee documents
  VAROA.8 A Operating Reactors Branch 1 84/05/24 MCDONALD.R P Alabama Power Co 3pp. 26134
- 840B300364 Forwards summary of 840B30 meeting w/Alabama Power Co. Florida Power Corp.Florida Power & Light, Georgia Power Co & TVA re selected emergency preparedness issues O'REILLY, J P Region 2, Office of Director 84/06/08, MCDUNALD, R P Alabama Power Co 4pp 26308 216 24X Fiche: 50-348,84/06/08,8408300364

- B408060070 Temporary change notices for Rev 7 to Procedure GD-EIP-111. "Corporate Activation & Notification " W/840727 ltr MUDD.C H Alabama Power Co B4/07/27 21pp 25933 104 24X Fiche 50-348,84/07/27.8408060070
- 8408070469 Forwards interim shutdown meaures re App R Eleven sys discussed which could potentially be impacted by cable spreading room fire Mods required to establish compliance w/App R MCDONALD: C E Alabama Power Co 84/07/27 VARGA: B A Office of Nuclear Reactor Regulation. Director 5pp 25940 336 24X Fiche 50-348.84/07/27.8408070469
- 8408130374 Submits add1 info re 10CFR50, App R schedular exemption for alternative shutdown mods Bases for schedular exemption until Unit I seventh & Unit 2 fourth refueling outages to completed mods provided MCDONALD, R P Alabama Power Co 84/08/06 VARGA, S A Office of Nuclear Reactor Regulation, Director 2pp 26005 337 24X Fiche 50-348,84/08/06.8408130374
- 8408240229 Summary of 840725 meeting w/util re detailed control room design review, per NUREO-0737. Suppl 1
  REEVES. E. A. Operating Reactors Branch 1 84/08/16 Operating Reactors Branch 1 64/08/16, 8408240229
- 8408230324 Revised emergency plan implementing procedures, including OD-EIP-101 re corporate emergency organization, 60-EIP-135 re emergency plan review & rev & 60-EIP-120 re ref guidance for recovery manager W/840817 ltr MUDD, C H Alabama Power Co 84/08/17 36pp 26206 018 24X Fiche 50-348, 84/08/17, 8408230326

#### M Antitrust correspondence

- 8408130075 Ack receipt of 840629 petition for enforcement action under 10CFR2 206 re antitrust license conditions Petition will be held in abeyance pending further Commission direction DENTON. HR Office of Nuclear Reactor Regulation, Director 84/07/30 BOBKEY, B Volpe, Boskey & Lyons 7pp 26034 353 24X Fiche:50-348,84/07/30.8408130075
- 8408080197 Reiterates 840702 request for notes, memoranda or transcripts of meetings between NRC & util as referenced in Palladino 840626 memo BOSKEY, B., HACQUINEAS: D.B. Volpe, Boskey & Lyons BOSKEY, B. Alabama Electric Cooperative, Inc. DSB 833 84/08/06 DIRCKB, W.J. Office of the Executive Director for Operations 2pp 25960 259 24X Fiche 50-348,84/08/06,8408080197
- 8408080202 Reiterates 840702 request for notes, memoranda or transcripts of meetings between NRC & util as referenced in Palladino 840626 memo BORKEY, B , MACGUINEAS, D B Volpe, Boskey & Lyons BORKEY, B Alabama Electric Cooperative, Inc BSB 831 84/08/06 BERNTHAL, F M Commissioners 2pp 25757 022 24X Fiche 50-348,84/08/06.8408080202
- 84080B024: Reiterates 840702 request for any notes or memoranda or transcripts of meetings u/util near and of June 1984 Certificate of Svc encl BOSKEY, B. MACOUINEAS, D.B. Volpe, Boskey & Lyons BOSKEY, B. Alabama Electric Cooperative, Inc. DSB 832, 84/08/06 ABBELBFINE, J.R. Commissioners 2pp 25766 271 24X Fichs 50-348,84/08/06,8408080241
- B408150120 Responds to 840806 ltr to MJ Dircks requesting any notes, memoranda or transcripts made of meetings between NRC & util No notes taken & no memoranda or transcripts of 840626 meeting prepared Related correspondence CUNNINOHAM, 6 H Office of the Executive Legal Director DSB 038 84708710 BBBKEY, 8 , MACGUINEAR, D B Volge, Bookey & Lyons 2pp 26066 352 24X Fiche 50-348,84708710,8408150180
- 8408200486 Responds to 840806 request for Commission records re 840625 meeting w/util Chairman Palladino 840624 memo accurately reflects conversation W/svc list Berved on 840817 BERNTHALF Commissioners DSB 166 84/08/16 BOSKEY.8 Volpe. Boskey & Lyons Opp 26136·318 24X Fiche: 30-348,84/08/16,8408200486
- P Operating license stage documents & correspondence
- 8408060277 Requests addl info needed for continuing review of 840203 license amend request, per generic Ltr 83-43 Deficiencies noted in Tech Byecs re deletion of ROs VARGA: 8 A Operating Reactors Branch i 84/07/25 MCDONALD.R P. Alabama Power Co 2pp 25750 274 24X Fiche 50-348,84/07/25,8408060277

- 8408130233 Forwards safety evaluation & technical evaluation rept re control of heavy loads, Phase 1 VARQA:S A Operating Reactors Branch 1 84/07/25 MCDONALD, R P Alabama Power Co 2pp 26060 027 24X Fiche 50-348.84/07/25, 8408130233
- --8408130258 SER re control of heavy loads,Phase I Phase i acceptable \* NRC - No Detailed Affiliation Given 84/07/25 2pp 26060 029 24X Fiche 50-348,84/07/25,8408130233
- B408100036 Forwards updated status of 1984 licensing stems identified in B40702 ltr Util ready to discuss mod of licensing status to address all licensing issues MCDONALD,R P Alabama Power Co 84/08/01 VARGA,B A Office of Nuclear Reactor Regulation, Director 7pp 23990 061 24X Fiche 50-348,84/08/01.8408100036
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933. "Prigritization of Generic Safety Issues "Svc list enci EISENHUT,D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26127 238 24X Fichs 50-000.84/08/06.8408070110
- 8408230398 Application for amend to Licenses NPF-2 & NPF-B, deleting words during shutdown from Tech Spec 4 7 1 2 2 b 1 re auxiliary feedwater sys Fee enc! MCDDNALD,R P Alabama Power Co 84/08/17 VAROA,S A Dffice of Nuclear Reactor Regulation, Director 3pp 26205 304 24% Fiche 5D-348,84/08/17.8408230398
- --8408230399 Proposed Tach Spac 4 7 1 2.2 b 1.deleting words during shutdown 4 Alabama Power Co 84/08/17 2pp 26205 307 24X Fiche.50-348,84/08/17,8408230378
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for DLs re-scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list enci EISENHUT,D 9. Division of Licensing 84/08/20 Consolidated Edison Co of New York. Inc. 17pp 26276-244 24X Fiche 50-000,84/08/20,8408200275

### Q Inspection reports: IE Bulletins & correspondence

- 6408280176 Discusses results of diesel generator check valve integrity insg.per IE Gulletin 83-03.during fifth refueling outage on 840210-0424 Inservice testing requirements for valves will be modified as listed MCDONALD.R P Alabama Power Co 84/06/01 D'REILLY.J P. Region 2. Office of Director 3pp 26279 196 24X Fiche 50-348.84/06/01.
- 10B280048 Forwards response to IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Unit 1 relays replaced w/GE Century Series HFA relays Thirty-three Unit 2 relays require replacement MCDDNALD, RP Alabama Power Co 84/07/12 O'REILLY, JP Region 2 Office of Director 5pp 26261 230 24X Fiche 50-348, 84/07/12, 8408980048
- B407250229 IE Info Notice S4-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants "Svc list encl JURBAN.E L Division of Emergency Preparedness & Engineering Response (Post 830(03) 84/07/27 Consolidated Edison Co of New York. Inc 119pp 25845 047 24X Fiche 50-000.84/07/27.8407250229
- 8408010333 IE Info Notice 84-39, "Daliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26048 001 24% Fichm 50-000,84/08/04,8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24% Fiche 50-000.84/08/06.8408010337
- 8408300169 Requests relief from inservice insp program for ASME Code Class 1.2 & 3 components by 850301.to allow for performance of insp activities during sixth refueling outage scheduled to begin 850405 Fee paid MCDDNALD,R P Alabama Power Co 84/08/06 VARCA,S A Office of Nuclear Reactor Regulation, Director Spp 26304 343 24X Fichs 50-348,84/08/06,8408300169

- 8408070120 IE Info Natice 84-61, "Overerposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000.84/08/08.8408070120
- 84080703/6 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list encl GRACELJ N Division of QA, Bafeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24% Fiche 50-000.84/08/10.8408070376
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list and I
  JORDAN, E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,9408100009
- 8408100038 IE Info Notice 84-64, "BWR HPCI Institution Seal-In & Indication" Svc list encl
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/15 Consolidated Edison Co of New
  York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038
- 8408100021 IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 820103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26198 001 24X Fiche 50-000.84/08/16.8408100021
- 8408100055 IE Info Notice 84-46, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000.84/08/17 8408100055
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list enci JDRBAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26327 008 24% Fiche 50-000,84/08/21,8408210142
- R Periodic operating reports & related correspondence
- 84082006i1 Monthly operating rept for Jul 1984 W/840814 ltr WOODWARD, J D , MCDONALD, R P Alabama Power Co 84/07/31 Spp 26138 117 24X Fiche 50-348,84/07/31,8408200611
- S Reportable occurrences. LERs & related correspondence
- B40B230515 LER 84-013-00 on 840716, continuous fire watch not posted in closed cooling water HX & pump room while maint personnel performing grinding & welding aperations Watch posted & maintained until no longer required W/840815 ltr WODDNALD, R P Alabama Power Co 84/08/15 3pp 26212 283 24X Fiche 50-348,84/08/15,8408230515

# V Operator Examinations

- 8408070314 Forwards response to Generic Ltr 84-14 re replacement & requalification training program Encl provides outline & description of simulator utilized in training & requalification program MCDDNALD.R P Alabama Power Co 84/07/26 VARGA.8 A Office of Nuclear Reactor Regulation, Director 3pp 25948 002 24X Fiche 50-348.84/07/26.8408070314
- DOCKET 50-952 LIMERICK GENERATING STATION, UNIT 1

  A Application/construction stage documents & correspondence
- 8408070228 Forwards response to 840527 ltr re anonymous allegation on cracked valve of recirculation sys B pump suction valve. Hased on results of 840614 visual insp. no crack identified Defect may have been surface irregularity OALLAOHER.JW Philadelphia Electric Co 84/06/18 MURLEY,T E Region i Office of Director 3pp 25948 225 24X Fiche 50-352.84/06/16.8408070228

- 8408010199 Notification of 840731 meeting w/util in Pottstown,PA to discuss electrical separation criteria,based on Wyle Labs test results
  MARTIN,R E Licensing Branch 2 84/07/23 SCHWENCER,A Licensing Branch 2 6pp 25873 280 24% Ficho 50-352,84/07/23,8408010199
- 8408080206 Notification of 840807 meeting w/util in Dethesda, MD to discuss outstanding items in detailed control room design review MARTIN.R E Licensing Branch 2 84/07/26 SCHWENCER, A Licensi Branch 2 5pp 25978 329 24% Fiche 50-352,84/07/26,8408080206
- 840B020030 Forwards requested info on NUREG-0737. Item II F 1 re interim procedures for quantifying high level accidental radioactive releases Info re Item III D 1 i will be furnished in Sept 1984 KEMPER, J S Philadelphia Electric Co 84/07/27 SCHWENGER, A Licensing Branch 2 14pp 25883 218 24X Fiche 50-352.84/07/27, 8408020030
- 8408060268 Notification of 840806 meeting w/util in Bethesda. MD to discuss applicant analysis of tornado missile effects on UHB Date changed MARTIN.R E Licensing Branch 2 84/07/27 SCHWENCER. A Licensing Branch 2 ip 25950 302 24X Fiche 50-352.84/07/27.8408060268
- --8408060273 Notifies of 840803 meeting w/util to discuss applicant 840322 analysis of tornado missile offects on UHS SCHWENCER.A Licensing Branch 2 84/07/26 BAUER.E 6 PAtladelphia Electric Co 6pp 29950 303 24X Fiche 50-352,84/07/27,8408060268
- B408020058 Forwards Amend 68 to OL application.consisting of Rev 34 to FSAR (Category K).Rev 19 to environ rept OL stage (Category C).Rev 9 to design assessment rept (DAR).Vols 1.2 & 3 4/o vol 2 DAR.Vol 3 withheld (ref 10CFR2 790) BRADLEY.E J Philadelphia Electric Co B4/07/31 DENTON.H R Office of Nuclear Reactor Regulation. Director 4pp 25904 001 24X Fiche 50-352.84/07/31.8408020058
- --8408020075 Amend &B to OL application, consisting of Rev 34 to FBAR, Rev 19 to environ rept OL stage & Rev 9 to design assessment rept (DAR), Vols 1 & 2 & proprietary Rev 9 to DAR, Vol 3 W/o Vol 2 DAR, Vol 3 withheld (ref 10CFR2 790) BOVER, V 8 Philadelphia Electric Co 84/07/31 &pp 25904 004 24X Fiche 30-352,84/07/31,8408020058
- --8408020090 Nonproprietary Rev 9 to Vol 1 of "Design Assessment Rept "
  \* Philadelphia Electric Co 84/07/31 9pp 25904 286 24X
  Fiche 50-352,84/07/31,8408020058
- B408220333 A REVIEW OF THE LIMERICK GENERATING STATION SEVERE ACCIDENT RISK ASSESSMENT Review of Core Melt Frequency AZARM.M A., BARI.R A., BOCCIO.J L. Brookhaven National Laboratory FIN A-3393 NUREO/CR-3493 84/07/31 Division of Safety Technology 192pp Available at NRC \$6.00 26200 205 24X Fiche S0-352,84/07/31.8408220333
- 8408070033 Forwards revised FSAR pages reflecting increase of reactor encl design inleakage rate from 50 to 100/ Free vol/day & doubling standby gas treatment sys fan flow during drawdown of Unit 1 encl FSAR rev scheduled for Aug 1984 BRADLEY,E J Philadelphia Electric Co 84/08/02 SCHWENCER, A Licensing Branch 2 39pp 25949 287 24X Fiche 50-352,84/08/02,8408070033
- 8408070037 Forwards response to Procedures & Sys Review Branch queries re emergency procedures & selection of containment vent pressure

  KEMPER, J 8 Philadelphia Electric Co 84/08/02 SCHNENCER, A Licensing Branch 2 bpp 25749 329 24X Fiche 50-352,84/08/02,8408070037
- B408140334 Notification of 840814 meeting w/util in Bethesda,MD to discuss analysis of tornado missile effects on UHS MARTIN,RE Licensing Branch 2 84/08/05 SCHMENCER,A Licensing Branch 2 4pp 26061 281 24X Fiche 50-352,84/08/05,8408140334
- 3408070110 Generic Ltr 84-19 to all licenses of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Generic Safety Issues "Svc list enci EISENNIUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26127 238 24X Fiche: 50-000, 84/08/06, 8408070110
- 3408130317 Advises that Preoperational Tost 100 3, "Mechanical Snubber Testing," will be deleted from preoperational test program, per 840716 & telcons Insp.xam & testing personnel will be qualified for snubber test per ANSI N45 2 6-1978
  KEMPER, J S Philadelphia Electric Co 84/08/07 SCHWENCER, A Licensing Branch 2 9pp 26010 329 24X Fiche 50-352,84/08/07, 8408130317

- 840B160477 Informs that all comments re risk evaluation rept received & incorporated into final version Rept ready for transmittal to applicant ACRS & ASLB EISENHUT. D & Division of Licensing 84/08/09 SPEIS.T NRC ~ No Detailed Affiliation Given 1p 2610B 351 24X Fiche 50-352.84/08/09.840B160479
- 8408210051 Notification of 840815 meeting w/util in Bethesda.MD to discuss further development of Tech Specs MARTIN.R E Licensing Branch 2 84/08/14 SCHHENCER.A Licensing Branch 2 5pp 26195 171 24X Fiche 50-352,84/08/14,8408210051
- 8408210303 Forwards draft changes to FSAR, Section 15 7 4 & response to Request for Add Info 410 37 re light loads/fuel handling accident Drop of baject would not result in consequences in excess of revised fuel handling accident KEMPER, J S Philadelphia Electric Co B4/08/14 SCHWENCER, A Licensing Branch 2 28pp 26179 298 24X Fiche 50-352,84/08/14, 8408210303
- 8408220165 Forwards response to NRC 840716 request for add1 info re offsite dose calculation manual & revised offsite dose calculation manual Related correspondence KEMPER. J S Philadelphia Electric Co 84/08/15 BCHWENCER, A Licensing Branch 2 7pp 26197 168 24X Fiche 50-352.84/08/15.8408220165
- --8409220168 Revised "Offsite Dose Calculation Hanual" \* Philadelphia Electric Co 84/08/10 41pp 26197 175 24x Fiche 50-352,84/08/15,8408220165
- 8408210513 Forwards Wyle test rept, "Electrical Separation Verification Testing on Terminal Blocks & Panel Meters," raceway separation criteria & design analysis documenting separation criteria rationale
  KEMPER, J B Philadelphia Electric Co 84/08/16 SCHWENCER, A
  Licensing Branch 2 3pp 26178 254 24X Fiche 50-352,84/08/16,8408210513
- --8408210518 "Test Rept on Electrical Separation Verification Testing on Terminal Blocks & Panel Meters for Limerick Generating Station Units 1 & 2"

  HAZELTINE, J., JOHNSON, F. R., ROBERTS, W. B., Hyle Laboratories 46960-4 B8/05/15 62pp. 26178 257. 24X Fiche 50-352,84/08/16,8408210513
- --8408210520 Rev O to "Raceway Separation Criteria " Raceway separation test program discussion encl \* Philadelphia Electric Co 84/08/09. 46pp 26178 316 24X Fiche 50-352,84/08/16,8408210313
- 8408220119 Requests that License Condition 2 re fuel rod pressure limit be closed based on recent resolution of generic issue between GE & NRC Evaluation demonstrates that bundles meet GE limit for fuel rod internal pressure KEMPER. J S Philadelphia Electric Co 84/08/17 SCHWENCER, A Licensing Branch 2 2pp 26193 307 24X Fiche 50-352.84/08/17, 8408220119.
- 8408270568 Summary of 840815 meeting w/util in Bethesda,MD re draft Tech Specs Attendees list encl MARTIN,R E Licensing Branch 2 84/08/17 Licensing Branch 2 4pp 26277 244 24% Fiche 50-352,84/08/17,8408270566
- 8408310012 Forwards response to Meteorological & Effluent Treatment Branch 840815 request for addl info re wide-range accident monitor calibr factors Related correspondence KEMPER. J B Philadelphia Electric Co D88 271 84/08/17 8CHHENCER. A Licensing Branch 2 3pp 26350 174. 24X Fiche 50-352.84/08/17.8408310012
- B40B31001B Requests that License Condition 2 re fuel rod pressure limit be closed, based on resolution of issue between GE & NRC. Related correspondence KEMPER, J S Philadelphia Electric Co DSB 292 B4/08/17 BCHWENGER, A Licensing Branch 2 2pp 26350 192 24X Fiche 50-352,84/08/17,8408310018
- B40B310007 Responds to 840206 ltr on SER License Condition 7 re compliance W/NUREO-0612.control of heavy loads.Phase II "Limerick Overhead Handling Stys Final Rept (Rev 3)" revised per 840206 request Related correspondence KEMPER.J S Philadelphia Electric Co DSB 293 84/08/18. BCHMENCER.A Licensing Branch 2 3pp 26350 177. 24X Fiche.50-352.84/08/18.8408310007
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT: D C Division of Licensing 84/08/20, Consolidated Edison Co of New York: Inc 17pp 26276 244 24X Fiche 50-000:84/08/20.8408200275

- 408220463 Board Notification 84-142 forwards R Starostecki 840731 memore alleged inadequate design of reactor enclivent stack Stack has no or limited safety significance NDVAK-T M Division of Licensing 84/08/20 BRENNER.L., CDLE.R.F., MDRRIB.P.A. Atomic Safety and Licensing Board Panel 2pp 26261 316 24X Fiche 50~332,84/08/20,8408220463
- -8408280101 Informs that on 840718.NRC interviewed confidential elleger re-concerns relative to response of reactor encl vent stacks to blast loads following railroad accident STARDSTECKI.R Division of Project & Resident Programs 84/07/31 EIBENHUT.D 0 Division of Licensing Ip 26261 318 24X Fiche 50-352,84/08/20,8408220463
- 408270161 Forwards revised response to Procedures & Sys Review Branch Question 430 72 re diesel oil storage tank lines to include addl info discussed in 840810 telecon KEMPER, J E Philadelphia Electric Co Licensing Branch 2 4pp 26245 259 24X Fiche 50-352.84/08/21, 8408270161
- 408310413 Forwards revised response to Procedure & Sys Review Branch Question 430 72 re diesel oil storage tank went lines, in response to 840810 request for addl info Related correspondence KEMPER. J S Philadelphia Electric Co DSB 288 84/08/21 BCHMENCER. A Licensing Branch 2 4pp 26350 224 24X Fiche 50-352,84/08/21,8408310413
- 408280130 Forwards Rev 1 to "Solid Radwaste Sys Process Control Program." in response to Meteorological & Effluent Treatment Sys Branch request for add1 info,per 840808 telcon Preperational testing of sys scheduled for end of month KEMPER.J S Philadelphia Electric Co 84708/23 SCHWENCER.A Licensing Branch 2 2pp 26259 064 24% Fishe 50~352,84708/23,8408280130
- -8408280132 Rev 1 to "Solid Radwaste Sys Process Control Program "
  # Philadelphia Electric Co 84/08/31 11pp 26259 066 24X
  Fiche 50-352,84/08/23,8408280130
- 408310144 Forwards response to 840507 request for add1 info re NUREG-0737, Item III D : 1. "Primary Coolant Dutside Containment " Info will be incorporated in Sept 1784 FBAR rev KEMPER. J S Philadelphia Electric Co 84/08/24 SCHWENCER. A Licensing Branch 2 7pp 26322 208 24% Fichs 50-352,84/08/24,8408310146
- IAO8270158 REVIEW INSIGHTS ON THE PROBABILISTIC RISK ASSESSMENTS FOR THE LIMERICK GENERATING STATION, UNIT 1 AND 2 CHELLIAM, E Division of Safety Technology NUREG-1058 84/08/31 126pp Available at NRC 55 00 24309 151 24X Fiche 50-352,84/08/31,8408270158
  - Utility Environmental Report (ER), amends & correspondence
- 408020058 Forwards Rev 19 to environ rept OL stage BRADLEY,E J Philadelphia Electric Co 84/07/31 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 25904 001 24X Fiche 50-352,84/07/31,8408020058
- -B40B0200B0 Rev 19 to environ rept OL stage \* Philadelphia Electric Co. B4/07/31 App 25904 010 24X Fiche 50-352,84/07/31,8408020058
- 408210076 Forwards Affidavit of Svc certifying distribution of Rev 34 to FBAR & Rev 19 to environ rept on 840809 BRADLEY.E J. Philadelphia Electric Co 84/08/14 DENTON.H R Office of Nuclear Resolution. Director 5pp 26184 327 24X Fiche 50-352,84/08/14.8408210076
- NRC Safety Evaluation Report (SER), suppls & correspondence
- 408040232 Forwards responses to questions & comments re 840322 analysis of ternado missile effects on UHS, supporting resolution of SER Open Issue 2 Responses do not affect results of prior analysis KEMPER, J. B. Philadelphia Electric Co. 84/07/27 SCHWENCER, A Licensing Branch 2 19pp 23934.117 24X Fiche 50-352,84/07/27,8408060232
- HOBO70289 Informs that upgrading & mods to RCIC turbine assembly completed, except for installation of threaded taper pins, in response to SER Open Item 6 Justification for interim operation of Unit 1 enc1
  KEMPER, J 8 Philadelphia Electric Co 84/08/01, SCHWENCER, A
  Licensing Branch 2 5pp. 25948 220 24X Fiche. 50-352, 84/08/01, 8408070289

- B40B0705i3 Forwards info to support resolution of SER proposed License Conditions 8.9.10 & 12 & to assist in preparation of License Condition 14 Info withheld (ref 10CFR2 790 & 73 21)
  Affidavit of withholding encl
  KEMPER, J S Philadelphia Electric Co B4/08/01 SCHWENCER, A
  Licensing Branch 2 Spp 25941 L67 24X Fiche 50-352, 84/08/01,
  B408070513
- 8408130296 Forwards relief requests from ASME Code.Section XI preservice insp requirements to resolve SER Confirmatory Issue 12 KEMPER, J S Philadelphia Electric Co 84/08/07 SCHWENCER, A Licensing Branch 2 7pp 26008 349 24X Fiche 50-352.84/08/07.8408130296
- 8409140303 Forwards responses to 840611 request for add1 info re SER Confirmatory Issues 3.5 & 6 & SER Open Issue 29 Related draft FSAR & design assessment rept page changes also encl XEMPER. J S Philadelphia Electric Co 84/08/08 SCHWENCER, A Licensing Branch 2 27pp 26111 129 24X Fiche 50-352,84/08/08,8408140303
- --8408140314 "Spec for Test Requirements for Hot Deflection Testing of ASME Section III. Nuclear Class 1.2.3 & ANSI B31 1.8echtel Piping, for Limerick Generating Station, Units 1 % 2 " # Bechtel Corp 84/05/29 159pp 26111 156 24X Fiche 50-352,84/08/08,8408140303
- ~~8408140320 "Spec for Test Requirements for Steady State Vibration Testing of ASME Section III.Nuclear Class 1.2.3 & ANSI B31 i.Bechtel Piping, for Limerick Generating Station, Units 1 & 2" \* Bechtel Corp 84/05/25 280pp 26111 317 24X Fiche 30-352,84/08/08,8408140303
- --B408140326 "Spec for Test Requirements for Dynamic Transient Testing of ASME Section III, Nuclear Class 1.2.3 & ANSI B31 1.Bechtel Piping, for Limerick Generating Station, Units 1 & 2 " & Bechtel Corp B4/05/27 129pp 26112 240 24X Fiche 50-352,84/08/08,8408140303
- 8409200262 Forwards responses to addl questions raised by Chemical Engineering Dranch re structural steel survivability evaluation Info supports final resolution of SER Open Item 14
  KEMPER, J S Philadelphia Electric Co 84/08/08 SCHWENCER, A Licensing Branch 2 26pp 26133 211 24X Fiche 50-352, 84/08/08, 8408200262
- BAORLAGGY Forwards draft FSAR pages in response to NRC B20825 request for add info re instrument setpoint methodology for reactor protection systems. I set instrumentation setpoints info should close SER Confirmatory Issue 26
  KEMPER, J S Philadelphia Electric Co BA/DB/10 SCHWENCER, A Licensing Branch 2 3pp 26072 173 24X Fiche 50-352, 84/08/10, 8408160379
- 8408230292 Forwards Rev 3 to "Overhead Handling Sys Review " Rept revised, per NUREG-0612, to address concerns identified in draft technical evaluation rept on control of heavy loads & support resolution of SER License Condition 7

  KEMPER, J S Philadelphia Electric Co 84708/13 BCHWENCER, A Licensing Branch 2 3pp 26207 001 24X Fiche 50-352,84708/13,8408230292
- --8408230297 Rev 3 to final rept "Overhead Handling Sys Review "

  \* Philadelphia Electric Co 84/06/30 175pp 26207 004 24X
  Fishs 50-392.84/08/13.8408230272
- 8408210031 Forwards addl info requested in NRC 840430 itr re exceptions to conformance to Rev 2 to Reg Guide 1 97 Encis should close Open Item 12 of SER (NUREO-0991)
  KEMPER.J 9 Philadelphia Electric Co 84/08/16 SCHWENCER, A Licensing Branch 2 lipp 26181 337 24% Fiche 50-352, 84/08/16, 8408210031
- B40B270376 Forwards add1 info re SER Confirmatory Issue 12 concerning preservice insp program, per 840817 request KEMPER, J S Philadelphia Electric Co 84/08/23 SCHWENCER, A Licensing Branch 3 62pp 26240 258 24X Fiche 50-352, 84/08/23, 840B270376
- 840B300215 Requests assistance in reviewing encl app to SER re identification of vital areas Response requested within 10 days of memo date to meet review 840907 completion date App withheld (ref 10CFR73 21) THOMAS.C O Standardization & Special Projects Branch 84/08/24 PARR.O D Auxiliary Systems Granch 1p 26307 054 24X Fiche 50-352,84/08/24,8408300215

#### F Security, medical, emergency & fire protection plans

- 840B160355 Forwards public version of emergency plan implementing procedures, including EP-101 re classification of emergencies, EP-102 re unusual event response, EP-103 re alart response & EP-104 re site emergency response COONEY, M J Philadelphia Electric Co 84/07/09 MURLEY, T E Region 1, Office of Director SCHMENCER, A Licensing Branch 2 5pp 26127 001 24X Fiche 50-352, 84/07/09, 840B160355
- ~-B408160360 Public version of revised emergency plan implementing procedures including EP-101 re classificaton of emergencies. EP-102 re unusual event response & EP-103 re alert response W/JM Felton B40B07 release memo Philadelphia Electric Co 84/06/08 450pp 26127 006 24X Fiche 50-332. B4/07/09.8408160355
- 8408070336 Emergecy plan exercise manual \* Philadelphia Electric Co 84/07/25 426pp 25946 001 24X Fiche 50-352.84/07/25.8408070336
- 8408020047 Forwards JL Patton 840723 ltr responding to RC Claypool 840607 ltr to Thornburgh re resources for radiological emergency response planning Related correspondence FERKIN, Z G Pennsylvania, Commonwealth of, DSB 704 84/07/27 BRENNER, L, COLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel 2pp 25883 273 24X Fiche 50-352,84/07/27,8408020047
- 8408070513 Forwards info to support resolution of SER proposed License Conditions 8:7:10 & 12 & to assist in preparation of License Condition 14 Info withheld (ref 10CFR2 790 & 73 21) Affidavit of withhelding encl KEMPER. J S Philadelphia Electric Co 84/08/01 SCHWENCER, A Licensing Branch 2 3pp 25941 167 24X Fiche 50-352, 84/08/01, 8408070513
- 8408070037 Forwards response to Procedures & Sys Review Branch queries re emergency procedures & selection of containment vent pressure KEMPER. J S Philadelphia Electric Co 84/08/02 SCHWENCER. A Licensing Branch 2 δρρ 25949 329 24X Fiche 50-352,84/08/02,8408070037
- 8408230153 Forwards IE Insp Rept 50-352/84-35 on 840702-03 & 05-06 No violations noted MARTIN, T T Region 1, Office of Director 84/08/03 KEMPER, J S Philadelphia Electric Co 4pp 26214 047 24X Fiche 50-352.84/08/03.8408230153
- --8408230157 IE Insp Rept 50-352/84-35 on 840702-03 & 05-06 No violations noted Major areas inspected chemistry, radioactive effluent control & radiation protection programs MILLER: M T , KOTTAN, J J , CARSON, B H Region L. Office of Director 84/08/03 6pp 26214 051 24X Fiche 50-352,84/08/03,8408230153
- 840B150A37 Revised notification of 840B07.07 & 10 meetings w/util in Bethesda.MD & Linfield.PA to discuss outstanding items in detailed control room design review MARTIN.R E Licensing Branch 2 84/08/07 SCHWENCER, A Licensing Branch 2 5pp 26102 339 24X Fiche 50-352,84/08/07,8408150637
- B408220497 Forwards public version of revised emergency plan implementing procedures, including EP-105, "General Emergency Response" & EP-304, "Partial Plant Evacuation " Release memo dtd 840820 encl
  DALTROFF, S L Philadelphia Electric Co 84/08/07 MURLEY, T E Region 1, Office of Director SCHWENCER, A Licensing Branch 2 7pp 26210 213 24% Fiche 50-352, 84/08/07, 8408220497
- ---9408220901 Public version of revised emergency plan implementing procedures including EP-105. "General Emergency Response" & EP-304. "Partial Plant Evacuation "

  \* Philadelphia Electric Co 84/08/07 25pp 26210 219 24X Fiche 50-352,84/08/07,8408220497
- B40B200147 Informs of review of schedule for sprinkler design & installation in conjunction w/possible temporary protective measures Installation of permanent sprinkler sys should be expedited KEMPER, J 8 Philadelphia Electric Co B4/08/08 SCHWENCER, A Licensing Branch 2 3pp 26133 283 24X Fiche 50~352,84/08/08,840B200147
- 8408200206 Forwards info re 4-kV penetrations, resolving item questioned during 840409-12 fire protection sys & documentation site audit Info will be incorporated into next rev to fire grotection evaluation rept
  KEMPER, J S Philadelphia Electric Co 84/08/08 SCHWENCER, A
  Licensing Branch 2 30pp 26133 069, 24X Fiche 50-352,84/08/08,8408200206

- 6408150404 Forwards correspondence & documents between applicant staff, Commonwealth of PA & responsible govt agencies re emargency planning Related correspondence CULLEN.E J Philadelphia Electric Co DSB 064 84/08/10 MULLIGAN.M Limerict Ecology Action 24pp 26068 196 24X Fishe 50-352.84/08/10.8408150404
- 840817038! Forwards supplemental info re Limerick Ecology Action 840806 response to util discovery request an admitted offsite emergency planning contentions Certificate of Svc encl MULLIGAN.M Limerick Ecology Action D88 102 84/08/13 RADER Philadelphia Electric Co 280pp 26137 181 24X Fiche 30-332,84/08/13.840817038!
- 840B200286 Forwards correspondence & documents among NRC, applicant & Commonwealth of PA re emergency planning, per ASL8 B20401 order Matl suppls 840810,0712 & 30 submittals Related correspondence CULLEN, E J Philadelphia Electric Co DSR 142 84/08/15 MULLIGAN, M Limerick Ecology Action 50pp 26131 085 24X Fiche 50-352,84/08/18,8408200286
- 840B210452 Responds to concerns discussed in 840720 telcon re control room design review final rept Final validation will be performed prior to fuel load Results will be submitted by 841031 KEMPER, J B Philadelphia Electric Co 84/08/16 SCHWENCER, A Licensing Branch 2 4pp 26177 200 24% Fiche 50-352,84/08/16,8408210452
- 8408240262 Forwards correspondence & documents among applicant,NRC & other parties re emergency planning Documents suppl matl forwarded in 840815 ltr & provide add1 correspondence dtd 840611-0808 Related correspondence CULLEN.E J Philadelphia Electric Co D88 264 84/08/20 MULLIGAN.M Limerick Ecology Action 652pp 26223 214 24X Ficher 50-352,84/08/20,8408240262
- B408280177 Provides resolution of conterns re fusible links on fire doors identified during B40407-12 site audit of fire protection sys & documentation Fusible links provided on hold open mechanisms for hollow metal doors XEMPER. J S Philadelphia Electric Co 84/08/22 SCHWENCER, A Licensing Branch 2 2pp 26275 088 24X Fiche 50-352,84/08/22,8408280177
- 8408270376 Forwards add1 info re SER Confirmatory Issue 12 concerning preservice inap program.per 840817 request KEMPER.J S Philadelphia Electric Co 84/08/23 SCHWENCER.A Licensing Branch 3 62pp 26240 258 24X Fiche 50-352.84/08/23.8408270376
- B408300215 Requests assistance in reviewing encl app to 8ER re identification of vital areas Response requested within 10 days of memo date to meet review 840907 completion date App withheld (ref 10CFR73 21) THUMAS.C II Standardization & Special Projects Branch 84/08/24 PARR.O ID Auxiliary Systems Branch ip 26307 094 24X Fiche 50-352.84/08/24.8408300215
- 840831000B Rev i to Emergency Plan Implementing Procedure EP-316, "Cumulative Population & Near Real-Time Emergency Dose Calculations for Airborne Releases Manual Method " W/840824 ltr DALTROFF, B L. Philadelphia Electric Co 84/08/24 MURLEY, T E Region 1, Office of Director SCHWENCER, A Licensing Branch 2 74pp 26323, 206 24% Fiche 50-352, 84/08/24, 8408310008.

#### G Adjudicatory correspondence

- 8408310076 Brief of RL Anthony & Friends of the Earth in support of appeal from ASLB 840306 & 21 verbal orders & 840316 written order & request for hearing ANTHONY, R. L. Anthony, R. L. ANTHONY, R. L. Friends of the Earth DSL 415 84/03/28 App 26322 229 24X Fiche 50-352.84/03/28.
- B408280491 Suppl to RL Anthony & Friends of the Earth motion vs applicant motion for partial decision & low power license & submitsion of B40518 contentions on new matter ANTHONY, R L Anthony, R L ANTHONY, R L Friends of the Earth. D88 358 B4/05/30 Atomic Safety and Licensing Board Panel 2pp. 26280:336 24X Fichs 50-352,84/05/30,8408280491
- 8408160112 Forwards intervenor Exhibits 3,4,47-135 & 136 Related correspondence.
  RILEY, S. L. Tayloe Associates 84/05/31 PLEASANT, E. Administrative & Logistical Support Branch ip 26126:325. 24X Fiche: 50-352,84/05/31,8408160112

- 8408160099 Forwards applicant Exhibits 137-151 Related correspondence RILEY.8 t. Taylor Associates 84/06/08 PLEASANT, E Administrative & Logistical Support Branch 19 26126 328 24X Fiche 50-352.84/06/08.408160099
- B408160103 Forwards NRC staff Exhibit 29 & intervenor Exhibits 1 & 2 Related correspondence RILEY, S L. Tayloe Associates B4/06/15 PLEASANT, E Administrative & Logistical Support Branch 1p 26126 327 24X Fiche 50-352,84/06/15,8408160103
- 8408160079 Forwards applicant Exhibits 153-173 Related correspondence RILEY, S.L. Tayloe Associates 84/06/26 PLEASANT, E. Administrative & Logistical Support Branch 1p 26126 346 24X Fichs 50-352, 84/06/26 48408160079
- 8408010223 Forwards suppl to 840523 ltr to ASLB & ASLAB re NRC duties concerning supplemental water Related correspondence SUGARMAN.R J Bugarman & Denworth SUGARMAN.R J Del-Aware Unlimited, Inc. DSB 659 84/07/13 PALLADINO.N Commissioners 2pp. 25856 022 24% Fiche 50-352.84/07/13.8408010223
- --8408010228 Submits followup to 840523 & 0705 Itrs re position that NRC exhibits pro-applicant bias Position based on Denton 840629 Itr & util 840417 notes Board action requested H/o ancls SUGARMAN, R J Sugarman & Denworth SUGARMAN, R J Del-Aware
  - SUGARMAN.R J Sugarman & Denworth SUGARMAN.R J Del-Aware Unlimited, Inc. 84/07/13 BRENNER.L , CDLE.R F , MORRIS.P A Atomic Bafety and Licensing Board Panel 2pp. 25856 024 24 Fiche 50-352.84/07/13.8408010223
- 8408010233 Response to NRC response to Air & Water Pollution Patrol 840626 contention re gross alpha W/svc list ROMANO,F R Air and Water Pollution Patrol DSB 658 84/07/25 4pp 25856 014 24% Fiche 50-352.84/07/25,8408010233
- 8408060179 Informs that borough participated in 840725 evacuation drill per Mayor recommendation Drill not sanctioned by borough council & evacuation per Draft 5 of smergency evacuation plans disapproved Served on 840803
  AUGUST, 8 K Phoenixville, PA DSB 735 84/07/25 BRENNER Atomic Safety and Licensing Board Panel 2pp 25932 183 24X
  Fiche 50-352,84/07/25,8408060179
- 8408010248 Forwards suppl to 840523 ltr to ASLB & ASLAB re NRC duties concerning supplemental vater Certificate of 8vc encl Related correspondence SUGARMAN.R J Suparman & Denworth SUGARMAN.R J Del-Aware Unlimited, Inc. DSB 643 84/07/26 PALLADINO, N Commissioners 2pp 25855 341 24X Fiche 50-352.84/07/26, 8408010248.
- 8408010170 Errata to 840726 proposed findings of fact & conclusions of law on Limerick Ecology Action Contentions DES-1. DES-2 DES-3 & DES-4 Proposed transcript corrections & Cartificate of Svc encl
  ELLIOTT.CW Limerick Ecology Action DS8 680 84/07/27 5pp 25855-163 24X Fichs 30-352.84/07/27, 8408010170
- 8408010255 Answer to Consumer Educ & Protective Assoc 840717 safety contentions Contentions lack basis, concern ratemaking matters outside NRC jurisdiction & should be denied Certificate of Svc encl
  CONNER.7 B Philadelphia Electric Co CONNER.7 B Conner & Hetterhahn DBB 670 84/07/27 Atomic Bafety and Licensing Board Panel Spp 25834 315 24X Fiche 50-352.84/07/27,8408010255
- 8408020047 Forwards JL Patton 840723 ltr responding to RC Claypool 840607 ltr to Thornburgh re resources for radiological amorgancy response planning. Related correspondence FERKIN. Z O Pennsylvania, Commonwealth of, DSB 704 84/07/27. BRENNER.L. COLE.R F. MORRIS.P A Atomic Safety and Licensing Board Panel 2pp 25883 273 24X Fache 50-352.84/07/27,8408020047
- B408070302 Response to Consumer Educ & Protective Assoc (CEPA) safety contentions received on 840716 CEPA contentions provide inadequate basis for concerns & should not be admitted Cartificate of Byc and WRIGHT, N A Hearing Branch 2 DSB 807 B4/07/31 Atomic Safety and Licensing Board Panel 9pp 25947:231 24X Fiche 30-352,84/07/31.8808070302
- 14080B0191 Appeal to Commission from ASLAB 340723 Memorandum & Order ALAB-778 re contentions on πuclear fuel Immediate stay requested W/avc list.
  ANTHONY.R L. Anthony.R L. ANTHONY.R L Friends of the Earth. DSB 835 84/07/31 2pp. 25940 257 24X Fiche 50-352,84/07/31,

- 840806053 First set of interrogatories & request for production of documents to city of Philadelphia re offsite emergency planning Contentions City-18 & City-19 Certificate of Svc encl Related correspondence RABER, R.M. Philadelphia Electric Co. RABER, R.M. Conner & Wetterhahn DSB 743 84/08/01 Philadelphia, PA 12pp 25933 197 24X Fiche 50-352,84/08/01.8408060053
- B408040170 Second errata to 840726 proposed findings of fact & conclusions of law on Linerick Ecology Action Contentions DES-1, DES-2, DES-3 & DES-4 Certificate of Svc encl ELLIDIT, C W Limerick Ecology Action DSB 742 84/08/01 3pp 25932 194 24X Fiche 50-352,84/08/01,8408060170
- 8408060182 Confirms points discussed in 840727 telcon.agreements reached & matters in dispute re Limerick Ecology Action answers to Applicant first set of interrogatories & request for production of documents Related correspondence RADERIR M Conner & Wetterhahn DSB 745 84/08/01 MULLIGAN.M Limerick Ecology Action 8pp 25932 175 24% Fiche 50-352. 84/08/01.8408060182
- B408060228 Forwards applicant 840727 answer to CEPA safety contentions W/o encl Related correspondence WETTERHAHNIM J Philadelphia Electric Co DSB 744 84708/01 HERSHEY, S P CEPA HERSHEY, S P Hershey, S F 1p 25933 335 24X Fiche 50-352,84708/01,8408060228
- B40B070350 Discusses RJ Sugarman correspondence & concerns re ex parte communications Motters raised by RJ Sugarman w/o merit & will be addressed formally by director in decision per 100FR2 206 Related correspondence CONNER. T B Conner & Wetterhahn CONNER. T B Philadelphia Electric Co DSB 777 84/08/02 CHILK. S J Office of the Secretary of the Commission 3pp 25944 167 24X Fiche 50-352.84/08/02.8408070350
- 8408070363 Motion to compel answers to first set of interrogatories, to compel production of withheld documents & for related relief re destroyed documents Certificate of 8vc encl Related correspondence RADER, R M Philadelphia Electric Co RADER, R M Conner & Wetterhahn DS8 780 84/08/02 Atomic Safety and Licensing Board Panel 16pp 25745 158 24X Fiche 50-352,84/08/02,8408070363
- 8408070366 Transmittal of VS Boyer 840802 affidavit re schedule for fuel loading.per ASL8 840620 order Certificate of Bvc encl Related correspondence METTERHAHNM J Philadelphia Electric Co DSB 781 84/08/02 6pp 25745.152 24X Fiche 50-352,84/08/02,8408070366
- 8408070412 Forwards answer to second set of interrogatories & request for production of documents an Limerick Ecology Action admitted offsite emergency planning contentions (Discovery 39) Related correspondence RABER.R M Conner & Wetterhahn RABER.R M Philadelphia Electric Co D8H 782 84/08/02 MULIOAN.M Limerick Ecology Action 1p 25942 033 24X Fiche 50-352.84/08/02,8408070412
- --8408070415 Answer to second set of Interrogatories & request for production of documents on Limerick Ecology Action admitted offsite emergency planning contentions (Discovery 35)
  Certificate of Svc encl
  \* Philadelphia Electric Co 84/07/31 Limerick Ecology Action 91pp 23942 094 24X Fiche 50-352,84/08/02,8408070412
- 8408070287 Forwards signature page of 840802 motion to compel answers to first set of interrogatories to compel production of withheld documents & for related relief re destroyed documents

  CONNER, T B Conner & Wetterhahn CONNER, T B Philadelphia Electric Co D9B 803 84/08/03 Docketing & Gervices Branch lp 25948 218 24% Fiche 50-332,84/08/03,8408070287
- --B408070291 Signature page of 840802 motion to compel answers to first set of interrogatories
  CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn 84/08/02 Atomic Bafety and Licensing Board Panel ip 25948 219 24% Fiche 50-352,84/08/03,8408070287
- 8408070429 Forwards V8 Boyer 840802 affidavit re schedule for fuel loading Related correspondence WETTERHAHN,M J Conner & Wetterhahn WETTERHAHN,M J Philadelphia Electric Co DSB 802 84708703 Docketing & Services Branch ip. 25940 049 24X Fiche 50~352,84708703,8408070429
- --8408070433 Affidavit of VS Boyer re schedule for fuel loading BOYER, V B Philadelphia Electric Co 84/08/02 2pp 25940 050 24X Fiche 50-332.84/08/03,8408070429

- 8408090226 Forwards motion before ASLAB to set aside partial initial decision based on new evidence SUGARMAN.R J Del-Aware Unlimited. Inc DSB 858 84/08/03 Office of the Secretary of the Commission 1p 25971 (14 24% Fiche 50-352,84/08/03,8408090226
- --8408090233 Motion to set aside partial initial decision based on new evidence & circumstances Ceitificate of Svc encl BUGARMAN.R J Del-Auare Unlimited, Inc BUGARMAN,R J Sugarman & Demonth 84/07/31 Atomic Safety and Licensing Appeal Panel 52pp 25971 115 24X Fiche 50-352,84/08/03,8408090226
- 8408070372 Reply to City of Philadelphia & Limerick Ecology Action 840726 proposed findings of fact & conclusions of law reserve accident risk assessment contentions Certificate of Svc encl WETTERHAHN.M J. NICHOLS, N.N. Philadelphia Electric Co. WETTERHAHN.M J. Conner & Wetterhahn DSB 795 84/08/06 29pp 25944 170 24X Fichs 50-352.84/08/06.8408070372
- 8408070444 Forwards answer to Limerick Ecology Action second set of interrogatories & request for production of documents re admitted offsite emergency planning contentions Encl replaces 840802 answers Related correspondence RADER: R M Conner & Wetterhahn RADER: R M Philadelphia Electric Co D88 789 84708706 MULLIGAN: M Limerick Ecology Action ip 25942 268 24X Fiche 50-352,84/08/06,8408070444
- ---8408070490 Revised ansuer to second set of interrogatories & request for production of documents on Limerick Ecology Action admitted offsite emergency planning contentions BOYER.V S Philadelphia Electric Co 84/08/03 Limerick Ecology Action 88pp 25742 267 24x Fiche 50-352,84/08/06,8408070444
- B408070495 Informs that applicant does not intend to respond to Sugarmon 840713 ltr purporting to update earlier ltrs of 840523 & 0605 to ASLAB & ASLE or to any future ltrs to ASLAB or ASLAB correspondence CONNER.T B Conner & Wetterhahn CONNER.T B Philadelphia Electric Co DSB 794 B40806 BRENNER.L MORRIS, P A . COLE.R F Atomic Safety and Licensing Board Panel 2pp 25941 191 24X Fiche 50-352.84/08/04.8408070495
- 8408090197 Reply to Limerick Ecology Action & City of Philadelphia proposed findings of fact & conclusions of law re severe accident risk assessment contentions VDGLER, B H , HUDGDUN, A P Hearing Branch 2 DSB 871 84/08/06 Atomic Safety and Licensing Board Panel 14pp 25972 001 24X Fiche 50-352,84/08/06,8408090197
- --8408090205 Proposed corrections to transcript of hearings on Limerick Ecology Action DES contentions & City of Philadelphia Contentions 13,14 & 15 Certificate of Svc encl \* Hearing Branch 2 84/08/06 Atomic Safety and Licensing Board Panel 13pp 25972 015 24X Fiche 50-352,84/08/06,840000197
- 8408090298 Forwards supplemental info re interrogatories, per util 840727 phone call & 840801 ltr Related correspondence MULLIGAN.M Limerick Ecology Action DS8 857 84708/06 RADER Philadelphia Electric Co 7pp 25972 114 24X Fiche 50-352,84/08/06,8408090258
- --8408090263 Amended answers to util first set of interrogatories re offsite emergency planning Contention LEA/FDE 24 Certificate of Svc encl ANTHONY,R L Anthony, R L 84/07/23 Philadelphia Electric Co App 25772 121 24X Fiche 50-352,84/08/06,8408090258
- 8408080399 Joint rept of parties on schedule proposal for offsite emergency planning matters filed in response to 840723 order Certificate of Svc encl CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn D8B 837 84/08/07 Atomic Safety and Licensing Board Panel 14pp 25974 087 24X Fiche 50-352,84/08/07,8408080399
- 8408080404 Motion to strike Air & Water Pollution Patrol (AWPP)
  pleading & reply to AWPP motion re Contention VI-1 Motion
  filed late & w/o hasis Certificate of Svc encl
  WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner &
  Wetterhahn DBB 838 84/08/07 Atomic Safety and Licensing Board
  Panel 7pp 25974 080 24X Fiche 50-352,84/08/07,8408080404
- 8408090238 Forwards NRC 840727 Amend 1 to License SNM-1926 & SER in support of amend Related correspondence VDGLER, B H Hearing Branch 4 DSB 872 84/08/07 DRENNER, L , MORRIS, P A , CULER F - A tomic Safety and Licensing Board Panel 14pp. 25972 152 24X Fiche 50-352,84/08/07,8408090238

- 840Bi30368 Replies to 840705 ltr re 840523 ltr to Chairman Palladino All encis to itr possibly not included to all recipients Comments on encis inconsistent w/practice followed for some time w/o objection
  SUGARMAN,R J Sugarman & Denworth SUGARMAN,R J Del-Aware Unlimited, Inc. DSB 897 84/08/07 MALSCH,M O Office of the General Counsel Ip 260II 127 24X Fiche 30-332,84/08/07,8408130368
- B408140450 Forwards new contention re evacuation ROMANO,FR Air and Water Pollution Patrol DSB 015 84/08/08 Atomic Safety and Licensing Board Panel App 26061-001 24X Fiche 50-332.84/08/08.8408140450
- --8408140452 New contention that applicant must provide fully testable & capable emergency evacuation plan prior to receipt of OL ROMAND, F R Air and Water Pollution Patrol 84/08/08 Atomic Safety and Licensing Board Panel 5pρ 26061 092 24X Fiche 50-352,84/08/08,8408140450
- 8408130158 Order establishing filing date of 840806 for motion to set aside based on new evidence received on 840807 Motion & 1tr bear postmark date of 840806 Served on 840810 SHOEMAKER,C J Atomic Safety and Licensing Appeal Panel D58 928 B4/08/07 Del-Aware Unlimited, Inc. 2pp. 26007 352 24X Fiche 50-352.84/08/09,8408130158
- B408140484 forwards amended Certificate of Svc of appellant motion to set aside based on new evidence Amend reflects svc of motion on 840806 LOCKE, R T Sugarman & Danworth LOCKE, R T Del-Aware Unlimited, Inc. DSB 013 84/08/09 KOHL, C N . EDLES, G . GOTCHY, R L Atomic Safety and Licensing Board Panel 3pp 26060 276 24% Fiche 50-352,84/08/09,8408140484
- 8408140840 Reply to applicant & staff anguers to CEPA safety contentions Contentions should be admitted Certificate of Svc encl HERSHEY, S P CEPA DSB 027 84/08/09 Atomic Safety and Licensing Board Panel 7pp 26041 220 24% Fiche 50-352,84/08/09,8408140840
- 8408150404 Forwards correspondence & documents between applicant.staff, Commonwealth of PA & responsible govt agencies re emergency planning Helated correspondence CULLEN.E.J. Philadelphia Electric Co. DSB 064 84/08/10 MULLIGAN.M Limerick Ecology Action 24pp 26068 196 24X Fiche 50-052.84/08/10, 8408150404
- 8409150477 Responds to B40806 ltr forwarding Limerick Ecology Action supplemental responses to applicant discovery requests Supplemental answers addressed individually Related correspondence RABER.R M Conner & Wetterhahn RADER.R M Philadelphia Electric Co D88 062 84/08/10 MULLIGAN.M Limerick Ecology Action 4pp 26068 160 24X Fiche 50-352.84/08/10.8408150477
- 8408150183 Order approving proposed transcript corrections as listed Served on 840814 BRENNER,L Atomic Safety and Licensing Board Panel DSB 047 84/08/13 2pp 26066 245 24X Fichs 50-352,84/08/13,8408150183
- B40B150387 Answer in opposition to Friends of the Earth B40731 petition for review of ALAB-778 No substantial conflict between ASLB & ASLAB presented Certificate of Svc encl WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn DSB 061 84/08/13 Commissioners 10pp 26068 285 24X Fiche. 50-352, B4/08/13, B408150387
- 8408170381 Forwards supplemental info re Limerick Ecology Action 840806 response to util discovery request on admitted offsite emergency planning contentions Certificate of Svc encl MULLIGAN.H Limerick Ecology Action DSB 102 84/08/13 RADER Philadelphia Electric Co 280pp 26137 181 24X Fiche 50-352.84/08/13.8408170381
- 8408200433 Forwards response to applicant motion re Contention VI-I & further support for reopening Contention VI-I re welding & welding insp infractions ROMANO, FR Air and Water Pollution Patrol D98 164 84/08/14 1p 26136
- --8408200442 Response to applicant motion to strike Air & Water Pollution Patrol (AWPP) pleading & reply to AWPP motion re Contention VI-I Contention VI-I must be litigated ROMANO,FR Air and Water Pollution Patrol 84/08/10 Atomic Safety and Licensing Board Panel 1p. 26136 293 24X Fiche 90-352,84/08/14,8408200433

- ~~8408200447 Further support for reopening Contention VI-I re welding & welding insp infractions Air & Water Pollution Patrol calls for full-scale reinsp re lack of fusion & Broomstick Affair revelations
  ROMAND,F R Air and Hater Pollution Patrol 84/08/13 Atomic Safety and Licensing Board Panel 2pp 26136 294 24X
  Fiche 50-352,84/08/14,8408200433
- 840B150425 Response opposing Friends of the Earth & R Anthony 840731 getition for review & request for stay of ALAB-77B Motion fails to establish existence of important issues of fact law or policy & should be denied Certificate of Svc encl VOLGER.B H . WRIGHT.N A Hearing Branch 2 DSB 067 84/08/15 Commissioners 15pp 26060 220 24X Fiche 50-352,84/08/15, 8408150425
- 8408170305 Order establishing schedule for admitted offsite emergency planning issues Schedule for deferred contentions will be established Courtesy notification entl Served on 840816 BRENNER, L Atomic Safety and Licensing Board Panel DSB 095 84/08/15 Office of the Executive Legal Director App 26115 246 24x Fiche 50-352,84/08/15,8408170305
- 8408200286 Forwards correspondence & documents among NRC, applicant & Commonwealth of PA re emergency planning, per ASLB 820601 order Matl suppls 840810,0712 & 30 submittals Related correspondence CULLEN.E J Philadelphia Electric Co DBB 142 84/08/15 MULLIGAN.M Limerick Ecology Action 30pp 26131 085 24X Fichs 30-352,84/08/15,8408200286
- 8408210341 Forwards order establishing schedule for offsite emergency planning issues W/o enel Related correspondence VOILER, B.M. Hearing Branch 2 DSB 186 84/08/16 PERRY, S Federal Emergency Management Agency 2pp 26179 361 24X Fiche 50-332,84/08/16,8408210341
- 8408220354 New info contention re health hazard via polyvinyl chloride fill used in reactor cooling towers W/svc list ROMANO.FR Air and Water Pollution Patrol DSB 196 84/08/16 Atomic Safety and Licensing Board Panel 4pp 26189 318 24X Fiche 50-352.84/08/16.8408220354
- 840B220379 Informs of errors in City of Philadelphia record citations re statement of NRC witness Acharya Also forwards Commenwealth of PA Public Utility Commission 840B07 order to show cause Related correspondence BUSH.M W Philadelphia, PA DSB 179 84/0B/16 ERENNER, L Atomic Safety and Licensing Board Panel 5pp 26191 349 24X Fichs 50-352.84/08/16,8408220379
- 8408240240 Provides addendum to Air & Water Pollution Patrol 840816 new info contention re polluting! chloride Fifth criterion re breakdown of polyving! chloride inadvertantly omitted Small delay in proceedings ack for large public good ROMAND.FR Air and Water Pollution Patrol DSB 271 84/08/20 Atomic Safety and Licensing Board Panel 1p 26R22 361 24X Fichs 50-352,84/08/20,8408240240
- 8408240262 Forwards correspondence & documents among applicant, NRC & other parties re emergency planning Documents suppl mat1 forwarded in 840815 ltr & provide add1 correspondence dtd 840611-0808 Related correspondence CULLEN.E J Philadelphia Electric CO DSB 264 84/08/20 MULLIONN.M Limerick Ecology Action 652pp 26223 214 24X Fiche 30-352,84/08/20,8408240262
- 8408240236 Answer opposing late-filed Air & Hater Pollution Patrol B40808 new contention re evacuation Contention lacks basis & specificity & fails to show good cause for late filing Cartificate of Sec enci CONNERT B Philadelphia Electric Co CONNERT B Conner & Wetterhahn D89 269, 84/08/21. Atomic Safety and Licensing Board Panel 18pp. 26222.239 24X Fiche 30-352,84/08/21,8408240234
- 8408240241 Answer opposing Del-Aware Unlimited, Inc 840806 motion to set aside ASLB 830308 partial initial decision resupplementary cooling water sys, based on new evidence Motion should be denied Cartificate of Sov encl
  CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn DSB 270 84/08/21 Atomic Safety and Licensing Appeal Panel 46pp 26223 066 24X Fiche 30-332,84/08/21,8408240241
- 8408240236 Forwards util comments on Del-Aware request under 10CFR2 206.per 840523 & 0713 requests for relief Metters repetitions & inappropriate under 10CFR2 206 & fail to raise significant environ concern CONNER.T B Conner & Hetterhahn CONNER.T B Philadelphia Electric Co B4/08/21 DENTON, HR Office of Nuclear Reactor Regulation, Director 17pp 26223 001 24% Fiche 50-352,84/08/21,8408240236

- 8408230200 Memorandum & order denying Citizens Action in Northeast 840625 & Consumers Educ & Protective Assoc 840716 motions to admit or certify financial qualifications contentions Served on 840822 BRENNER. Atomic Safety and Licensing Board Panel DSB 254 84708722 Office of the Executive Legal Director 11pp 26209 198 24X Fiche 50-352.84708722.8408230200
- B40B280415 Motion for reconsideration of ASLB 840B15 order establishing schedule for offsite emergency planning issues FEMA should not be required to distribute draft rept by 840901 Certificate of Svc encl VOGLER, B H, WRIGHT, N A Hearing Branch 2 DSB 344 84/08/23 Atomic Safety and Licensing Board Panel 4pp 26280 290 24X Fiche 50-352,84/08/23,8408280415
- 8408280162 Memorandum & order rejecting Friends of the Earth & Air & Water Pollution Patrol (AWPP) late-filed contentions & denying AMPP second request for reconsideration of asbestos contention Courtesy notification encl Served on 840827 BRENNER.L. Atomic Safety and Licensing Board Panel DSB 326 84/08/24 Friends of the Earth 27pp 26275 116 24X Fiche 50-352.84/08/24.8408280162
- 8408280388 Confirms 840824 teleon informing of 840830 meeting in Philadelphia.PA to discuss matters covered by ASLB scheduling order Related correspondence RADER, R M Conner & Wetterhahn RADER, R M Philadelphia Electric Co DBB 354 84/08/24 VOCLER, B H Hearing Branch 2 FERNIN, Z G Pennsylvania, Commonwealth of, SMOLLEN, H Philadelphia, PA 2pp 26280 032 24X Fiche 50-352.84/08/24.8408280388
- 8408280237 Order extending time until 840921 for Commission to act to review ALAB-778 Served on 840827 CHILK:5 J Office of the Secretary of the Commission DSB 319 84/08/27 Commissioners ip 26262 278 24X Fiche 50-352.84/08/27.8408280237
- 8408300170 Response opposing Del-Aware 840806 motion to set aside ASLB 830308 partial initial decision on environ effects of supplemental cooling water sys based on new evidence Certificate of Svc encl VOOLER.B H Hearing Branch 2 DSB 381 84/08/27 Atomic Safety and Licensing Appeal Panel 23pp 26305 320 24X Fiche 50-352.84/08/27.8408300170
- 8408300119 Response opposing admission of Air & Water Pollution Patrol 840808 new contention re evacuation, filed by FR Romano Certificate of 8vc encl HRIGHT, N A Hearing Branch 2 DSB 379 84/08/28 Atomic Safety and Licensing Board Panel 12pp 26305 171 24X Fiche 50-352,84/08/28,8408300119
- 8408300168 Second Partial Initial Decision LBP-84-31 on listed issues in controversy in favor of applicant Courtesy notification encl Served on 840827

  BRENNER.L. COLE.R.F. MORRIS.P.A. Atomic Safety and Licensing Board Panel DSB 386

  84/08/297 325pp 26303 158 24X

  Fiche 50-352.84/08/29,8408300168
- 8408310223 Response opposing Air & Water Pollution Patrol 840814 pleading on reopening Contention VI-1 re welding & welding insp infractions Certificate of Svc encl WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn DSB 423 84/08/27 Atomic Safety and Licensing Board Panel 8pp 26319 244 24% Fiche 50-352,84/08/29,8408310223
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8408020058 Forwards Rev 34 to F9AR BRADLEY,E J Philadelphia Electric Co 84/07/31 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 25704 001 24X Fiche 50-352,84/07/31,8408020058
- --8408020084 Rev 34 to FBAR

  \* Philadelphia Electric Co 84/07/31 272pp 25904 014 24X
  Fiche 50-352,84/07/31.8408020058
- 8408210074 Forwards Affidavit of Svc certifying distribution of Rev 34 to FSAR & Rev 19 to environ rept on 840809 BRADLEY, E J Philadelphia Electric Co 84/08/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 26184 327 24X Fiche 50-352,84/08/14,8408210076
- M Antitrust carrespondence
- 8408020136 Forwards FR notice of finding of no significant antitrust changes & time for filing requests for reevaluation REGAN,W H Siting Analysis Branch 84/07/20 STUCKY,S W Docksting & Services Branch 3pp 25898 095 24X Fichs 50-352,84/07/20,8408020136

- Q Inspection reports. IE Bulletins & correspondence
- 8408080523 Forwards IE Insp Rept 50-352/84-25 on 840516-25 & 30 & notice of violation
  MARTIN.T T Division of Engineering & Technical Programs 84.
  KEMPER.JS Philadelphia Electric Co 2pp 25975 277 24X
  Fiche 50-352,84/07/17.8408080523 B4/07/17
- --B408080526 Notice of violation from imag on 840516-25 & 30 \* Region 1, Office of Director 84/07/17 ip 25975 ; Fiche 50-392,84/07/17,8408080523 25975 279 248
- --B408080530 IE Insp Rept 50-352/84-25 on 840516-25 & 30 Violation noted failure to place jurisdictional & boundary tags on RHR svc water sys turned over for startup BRIGGS, L E , OREGG, H , DETTENHAUSEN, L Region 1, Office of Director 84/07/13 8pp 25975 280 24X Fiche 50-352,84/07/17, 8408080523
- 8408310124 Forwards response to NRC 840620 ltr re violations noted in Insp Repts 50-352/84-24 & 50-352/84-08 on 840501-31 Seismic classifications of three piping isometric drawings & four piping field sketches corrected Related correspondence KEMPER.J 5 Philadelphia Electric Co DSS 002 84/07/17 MURLEY.T E Region 1. Defice of Director 4pp 26352 028 24% Fiche 50-352,84/07/19,8408310124
- 8407250229 IE Info Natice 84-57, "Operating Experience re Maisture 407250229 IE Info Natice 89-57. "Uperating Experience re Maisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24% Fiche 30-000,84/07/27,8407250229
- 8408210368 Forwards IE Insp Repts 50-352/84-26 & 50-353/84-09 on 840601-30 & notice of violation 8TAROSTECKI:R Division of Project & Resident Programs 84/01 KEMPER:JS Philadelphia Electric Co 2pp 26183 109 24X Fiche 50-352,84/08/02,8408210368 84/08/02
- --8408210373 Notice of violation from insp on 840401-30 \* Region 1, Office of Director 84/08/02 4pp 5 Fiche 50-352,84/08/02,8408210368 26183 111 24X
- --B40B2103B1 IE Insp Repts 50-352/B4-26 & 50-353/B4-09 on 840601-30 Violations identified inadequate diesel generator test program implementation & inadequate calibr procedure for valve position indicating sys CHAUDHARY, 8 K , WIGGINS, J T , BAUNACK, W Region I, Office of Director 84/07/24 15pp 261B3 115 24X Fiche 50-352,84/08/02,840B21036B
- -8408210374 Responds to NRC 840321 itr re violations noted in IE Insp Repts 50-352/84-19 & 50-353/84-06 Corrective actions notice issued to include info on P&ID M-42 & Procedure GADP-27 1 revised to include into on factor and account of the control of th
- 8408100028 Discusses concerns expressed in IE Insp Rept 50-352/84-29 on timely resolution of NDE van insp findings re lack of fusion indications on pipe welds identified during ASME Code. Section XI preservice exams MARTIN.T T Division of Engineering & Technical Programs 84/08/03 KEMPER.J S Philadelphia Electric Co 4pp 25989 045 24X Fiche 50-352,84/08/03,8408100028
- 8408230153 Forwards IE Insp Rept 50-352/84-35 on 840702-03 & 05-06 No violations noted MARTIN, T T Reg violations noted MARTIN, T T Region 1, Office of Director 84/08/03 KEMPER, J 8 Philadelphia Electric Co 4pp 26214 047 24X Fiche 50-352, 84/08/03, 8408230153
- --8408230157 IE Insp Rept 50-352/84-35 on 840702-03 & 05-06 No violations HOBESOIS IE INSPIREDT 50-352/84-35 on H40702-03 & 05-05 No violati noted Major areas inspected chemistry.radioactive effluent control & radiation protection programs MILLER.M T , KOTTAN.J J , CARSON.B H Region 1, Office of Director 84/08/03 App 26214 OS1 24X Fiche 50-352,84/08/03, 8408230153
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 24067 156 24X Fiche 50-000,84/08/06,8408010337

- 840B130296 Forwards relief requests from ASME Code.Section XI preservice insp requarements to resolve BER Confirmatory Issue 12 KEMPER. J S Philadelphia Electric Co 84/08/07 SCHWENCER, A Liconsing Branch 2 7pp 26008 349 24X Fiche 50-352,84/08/07-8408130276
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consulidated Edison Go 26129 118 24X Fiche 50-000,84/08/08,8408070120 120pp
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Pattents Undergoing Co-60 Teletherapy Treatments " Svc list encl list enc. ORACE.J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 30-000,84/08/10,8408070376
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " tOB10000P IE into mutice at Soc.

  Svc 114t enc!

  JORDAN:E L Division of Emergency Preparedness & Engineering

  Response (Post 830103) 84/08/13 Consolidated Edison Co of New

  York, Inc. 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408210420 Ack receipt of 840709 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-352/84-16
  MARTIN.T T Division of Engineering & Technical Programs 84/08/1
  KEMPER.J S Philadelphia Electric Co 4pp 26177 248 24X
  Fiche 50-352.84/08/14.8408210420 84/08/14
- --8408210427 Responds to NRC 840604 itr re violations noted in IE Insp Rapt 50-352/84-16 Corrective actions min requirements needed to start diesel generator documented in checklist for appropriate plant operating personnel KEMPER, J Philadelphia Electric Co 84/07/07 MURLEY, T E Region 1, Office of Director Spp 26177 252 24X Fiche. 50-352, 84/08/14, 8408210420
- 8408100038 IE Info Notice 84-64, "BWR MPCI Initiation Seal-In & Indication "Syc list enc!
  JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26178 093 R4X Fiche 50-000,84/08/15,8408100038
- 84081000#1 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl list enci JDRDAN, E.L. Division of Emergency Proparedness & Engineering Response (Post 830)03) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26198 QOI 24X Fiche 30-000,84/08/16,8408100021
- 8408310417 Responds to Insp Rept 50-352/84-25 Corrective actions, sys startup engineer walked down equipment within boundaries of RHR svc water sys Turbover 1-16A-1(F) & assured valves, instruments & components tagged Related correspondence CODNEY, M J Philadelphia Electric Co DSB 289 84/08/16 MARTIN, T T Division of Engineering & Technical Programs 3pp 26350 218 24% Fiche 50-352,84/08/16,8408310417
- 840B100059 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consulidated Edison Co York, Loc 1908 24274 004 247 544 500 Consulidated Edison Co 26276 001, 24% Fiche 50-000.84/08/17,8408100055
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates" Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York Inc 122pp 26276 122. 24X Fiche 50-000.84/08/17.8408140208
- 8408310058 Responds to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc " Strong GE & Bechtel quality programs provide homogeneous network of vendor surveillance scrutiny No fraudulent products in use KEMPER, J S Philadelphia Electric Co 84/08/17 MURLEY, T E Region 1, Office of Director 2pp 26323 204 24X Fiche 50-352,84/08/17,8408310058
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc 11st encl, JDRDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26327 008 24X Fiche, 50-000, 84/08/21, 8408210142
- B408240013 Confirms B40824 telcon re 840827-31 insp concerning sissmic design of structures, pipe break analysis & south stack blast load calculations
  ZECH.0 G. Vendor Program Branch 84/08/21. STRATTON, C D Bechtel Corp. 19 26228, 248 24% Fiche. 50-352, 84/08/21, 8408240013.

- 8408270374 Forwards addl info re SER Confirmatory Issue 12 concerning preservice insp program, per 840817 request KEMPER, J S Philadelphia Electric Co 84/08/23 SCHWENCER, A Licensing Branch 3 62pp 26240 258 24% Fiche 50-352.84/08/23, 8408270376
- 8408150619 Notification of Licensee Meeting 84-299 on 840809 in King of Prussia:PA to resolve preservice exam findings
  DURR.JP Region 1: Office of Director 84/08/31 Region 1:
  Office of Director 1p 26102 358 24x Fiche 50-352.84/08/31.

# R Periodic operating reports & related correspondence

- 8408060419 Forwards fourth status rept re independent design review of core spray sys for 840701-15 Related correspondence CARPENTER:F D Torrey Pines Technology DSB 717 B4/07/16 BUYER.V S Philadelphia Electric Co 7pp 25951
- 8408310023 Forwards "Independent Design Review of Limerick Generating Station 1 Core Spray Sys, Di-Monthly Status Rept 5 for Period Ending 840731 " Related correspondence CARPENTER: F D Torrey Pines Technology BSB 234 84/08/01 BGYER: V S Philadelphia Electric Co 7pp 26350 102 24X Fiche 50-352,84/08/01.8408310023
- 8 Reportable occurrences, LERs & related correspondence
- 8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated SMERWOOD. G Coneral Electric Co 84/04/13 DEYOUNG. R C Director's Office. Office of Inspection and Enforcement 3pp 26222 255 24X Fiche 50-000.84/04/13.8408240348
- 8408240332 Submits annotated requests for follows on potentially generic problem in encl Part 21 rept from Basler Electric re SGRs on nuclear exciters mounted witton much pressure NORELIUS.C E Division of Project & Resident Programs 84/04/25 JORDAN.E L Director's Office. Office of Inspection and Enforcement ip 26223 303 24X Fiche 50-000,84/04/25,8408240332
- 8408200307 Suppl 7 to Part 21 rept re possible thermostatic valve malfunction fail safe to full cooling position Lower overrun assemblies in Robertshau valves installed on diesel generator sets replaced u/cotter pins to lock nut to stem MORIARTY, J M Colt Industries, Inc. 84/08/08 KEPPLER, J C Region 3, Defice of Director 1p 26/33 017 24X Fiche 50-352,84/08/08,8408200307
- 840B310110 Significant Deficiency Rept 148 re design calculations made by WJ Hoolley Co for doors specified to meet tornadogenerated missile criteria Door reanalysis underway Previously reported under Part 21 by WJ Woolley Co KEMPER. J S Philadelphia Electric Co 84/08/23 MURLEY. T E Region 1. Office of Director 1p 26322 239 24X Fiche 50-352.84/08/23.8408310110

# T Hearing transcripts on non-antitrust matters

- B40B090205 Proposed corrections to transcript of hearings on Limerick Ecology Action DES contentions & City of Philadelphia Contentions 13,14 & 15 Certificate of Svc encl \* Hearing Branch 2 84/08/06 Atomic Bafety and Licensing Board Panel 13pp 25972,015 24X Fiche 50-352,84/08/06,8408090197
- 3408070227 Forwards dated & signed copy of Page 11 of proposed corrections to transcript of hearings on Limbrick Ecology Action DES contentions & City of Philadelphia Contentions 13, 14 & 15 VOCLER, B H Hearing Branch 2 DSB 84/7 84/08/07. BRENNER, L, MORRIS, P A, COLE, R F. Atomic Safety and Licensing Board Panel 2pp. 25971 167 24% Fichs 50-352,84/08/07,8408090229
- -8408070236 Executed Page 1; of corrections to transcript of hearings on Limerick Ecology Action DES contentions & City of Philadelphia Contentions 13, 14 & 15.

  VQCLER, B H, HDORDON, A P Hearing Branch 2 84/08/06 ip 25971 167 24X Fiche 50-352,84/08/07.8408070227
- 408240254 Proposed corrections to transcript of evidentiary hearings on NEPA severe accident contentions. Certificate of Svc encl HETTERHAHN.H J , NICHOLS, N N Philadelphia Electric Co HETTERHAHN.H J , Conner & Netterha

### U Congressional/Executive Correspondence

- 8408170094 Responds to 840712 ltr re 840502 Pottstown Mercury article & related petition Low level normal operation releases expected to be well within recognized safety limits Excerpts from DES encl
  DIRCKS, W. J. Office of the Executive Director for Operations 84/08/08 WALFER, R. S. House of Rep. 1p. 26135-322 24X
  fichs 50-352,84/08/08.8408170094
- 8408200449 Responds to 840712 request for consideration of constituent H Mayerson 840407 ltr w/840502 Pottstown Mercury article & encl petition Low level normal operation releases expected to be well within recognized safety limits DIRCKS.W J Office of the Executive Director for Operations 84708708 WALKER.R S House of Rep Spp 26182 313 24X Fiche 50-352.84708/08.8408200449
- --B40B200454 Forwards constituent H Mayerson 840607 ltr w/840502
  Pottstown Mercury article, "Limerick to Release Very Small
  Amounts of Radioactivity" & petition & requests
  investigation of statements
  HALKER, R S House of Rep 84/07/12 KAMMERER, C Office of
  Congressional Affairs Spp 26182 332 24X Fiche 50-352,
  84/08/208,84882000479

#### V Operator Examinations

- 8408230258 Responds to 840531 request for operating shift staffing info Five-shift rotation, staffing schemes, qualifications & training programs encl
  DALTROFF, S. L. Philadelphia Electric Co. 84/08/21 & ISENHUT, D. O. Division of Licensing 45pp 26208 037 24X Fiche 50-352,84/08/21,8408270228
- DUCKET 50-353 LIMERICK GENERATING STATION, UNIT 2

  A. Application/construction stage documents & correspondence
- 8408010199 Netification of 840731 meeting w/util in Pottstown,PA to discuss electrical separation criteria,based on Wyle Labs test results MARTIN,R E Licensing Branch 2 84/07/23 SCHWENCER,A Licensin Branch 2 App 25873 280 24X Fiche 50-352,84/07/23,8408010199
- B40B080204 Notification of B40B07 meeting w/util in Bethesda, MD to discuss outstanding items in detailed control room design review HARTIN.R E Licensing Branch 2 84/07/26 BCHWENCER, A Licensing Branch 2 5pp 25978 329 24X Fiche 50~352 84/07/26, 8408080204
- 8408020030 Forwards requested info on NUREG-0737. Item II F i re interim procedures for quantifying high level accidental radioactive releases Info re Item III D i i will be furnished in Sept 1984 KEMPER, J 8 Philadelphia Electric Co 84/07/27 SCHWENCER, A Licensing Branch 2 14pp 25883 218 24X Fiche 50-352,84/07/27,8408020030
- 8408060268 Notification of 840806 meeting w/util in Bethesda, MD to discuss applicant analysis of tornado missile effects on UHS Date changed MARFIN, E Licensing Branch 2 84/07/27 SCHWENCER, A Licensing Branch 2 1p 25750
- --B40B060273 Notifies of B40B03 meeting w/util to discuss applicant B40322 analysis of tornado missile effects on UHS SCHMENCER.A Litensing Branch 2 B4/07/26 DAUER, E G Philadelphia Electric Co App 25950 303 24X Fiche 50-352,84/07/27,840B06026B
- 8408020058 Forwards Amend 68 to OL application consisting of Rev 34 to FSAR (Category K). Rev 19 to environ rept OL stage (Category C). Rev 9 to design assessment rept (DAR). Vols 1.2 & 3 W/p Vol 2 DAR, Vol 3 withheld (ref 10CFR2 790) BRADLEY. E J Philadelphia Electric Co 84/07/31 DENTON, H R Office of Nuclear Reactor Regulation. Director 4pp 25904 001 24X Fiche 50-352,84/07/31,8408020058
- --B40B020075 Amend 6B to OL application, consisting of Rev 34 to FSAR, Rev 19 to environ rept -- OL stage & Rev 9 to design assessment rept (DAR). Vols 1 & 2 & proprietary Rev 9 to DAR, Vol 3 W/o Vol 2 DAR, Vol 3 uithheld (ref 10CFR2 790)
  BOYER, V S Philadelphia Electric Co B4/07/31 App 25904 004 24X Fiche 50-352, 84/07/31, 8408020058
- --8408020090 Nonpreprietary Rev 9 to Vel 1 of "Design Assessment Rept" \* Philadelphia Electric Co 84/07/31 9pp 25904 286 24X Fiche 50-352,84/07/31.8408020058

- 840B220333 A REVIEW OF THE LIMERICA GENERATING STATION SEVERE ACCIDENT RISK ASSESSMENT Review of Core Melt Frequency AZARM.M A . BARIAR A . BOCCIG-J L Brookhaven National Laboratory FIN A-3393 NUREG/CR-3493 84/07/31 Division of Safety Technology 192pp Available at NRC ±6 00 26200 205 24X Fiche 90-352,84/07/31.8408220333
- 8408070033 Forwards revised FSAR pages reflecting increase of reactor encl design inleakage rate from 50 to 100% free vol/day & doubling standby gas treatment sys fan Flow during draudoun of Unit 1 encl FSAR rev scheduled for Avg 1984 BRADLEY.E J Philadelphia Electric Co. 84/08/02 SCHWENCER,A Licensing Branch 2 39pp 25949 289 24% Fiche 50-352.84/08/02.8408070033
- 8408070037 Forwards response to Procedures & Sys Review Branch queries re emergency procedures & selection of containment vent pressure KEMPER, J. B. Philadelphia Electric Co. B4/08/02 SCHWENCER, A. Licensing Branch 2 App. 23949-329 24X Fiche 50-352, B4/08/02, B4/08070037
- B40B140334 Notification of B40B14 meeting w/util in Bethesda, MD to discuss analysis of tornade missile effects on UHS MARTIN,R E Licensing Branch 2 84/08/05 SCHWENGER,A Licens Branch 2 4pp 26051 281 24X Fiche S0-352,84/08/05,840B140334
- B40B070110 Generic Ltr B4-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Buppl I to NUREO-0933, "Prioritization of Generic Safety Issues " Syc list encl EIGENHUT.D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000-84/08/06-8408070110
- B40Bi30317 Advises that Preoperational Test 100 3, "Mechanical Enubber Testing," will be deleted from preoperational test program, per B40716 & telcons Insp.exam & testing personnel will be qualified for snubber test per AMSI N45 2 6-1978
  KEMPER, J S Philadelphia Electric Co 84/08/07 ECHMENCER, A Licensing Branch 2 9pp 26010 329 24X Fiche 50-352,84/08/07,8408130317
- 8408140477 Informs that all comments re risk evaluation rept received & incorporated into final version Rept ready for transmittal to applicant ACRS & ASLO EISENHUT.D & Division of Licensing 04/08/09 SPEIS.T NRC No Detailed Affiliation Given ip 26/08/351 24% Fiche 50-352-84/08/09.040816047/
- 8408210051 Notification of 840815 meeting w/util in Dethosda.MD to discuss further development of Tech Specs MARTIN:R E Liconsing Branch 2 84/08/14 SCHWENCER:A Licensing Branch 2 5pp 26175 171 24X Fiche 50-352:84/08/14.8408210051
- 8408210303 Forwards draft changes to FSAR, Section 15 7 4 & response to Request for Add1 Into 410 37 or light loads/fuel handling accident Drop of object would not result in consequences in excess of revised fuel handling accident KEMPER, J S Philadelphia Electric Co 84/08/14 SCHHENCER, A Licensing Branch 2 28pp 26179 278 24X Fiche 50-352, 84/08/14, 8408210303
- 8408220165 Forwards response to NRC 840716 request for addl info re offsite dose calculation manual & revised offsite dose calculation manual Related correspondence KEMPER.J S Philadelphia Electric Co 84/08/15 SCHWENCER.A Licensing Branch 2 7pp 26197 168 24X Fichs 50~392,84/08/15,8408220165
- --8408220168 Revised "Offsite Dosp Calculation Manual" # Philadelphia Electric Co 04/08/10 41pp 261 Fiche 50-352,84/08/15,8408220165 26197 175
- 8408210513 Forwards Hyle test rept. "Electrical Separation Verification Testing on Terminal Blocks & Panel Meters." raceway separation criteria & design analysis documenting separation criteria rationale KEMPER. J S Philadelphia Electric Co 84/08/16 SCHWENCER, A Licensing Branch 2 3pp 26178 294 24X Fiche 50-352.84/08/16, 8408210513,
- --8408210518 "Test Rept on Electrical Separation Verification Testing on Terminal Blocks & Panel Meters for Limerick Generating Station Units 1 & 2" HAZELTINE.J., JOHNSON,P R., ROBERTS.W B. Wgle Laboratories 46960-4 84/05/15 62pp 26178 257 24X Fiche 80-352,84/08/16, 8408210513
- -8408218520 Rev O to "Adceway Separation Criteria" Receway separation test program discussion encl \* Philadelphia Electric Co 84/08/09 46pp 26178 316 24X Fiche 30-352,84/08/16.8408210513

- 8408220119 Requests that License Condition 2 re fuel rod pressure limit be closed, based on recent resolution of generic issue between GE & RRC Evaluation demonstrates that bundles meet GE limit for fuel rod internal pressure KEMPER. J S Philadelphia Electric Co 84/08/17 SCHWENCER, A Licensting Branch 2 2pp 26193 307 24X Fishe 50-352.84/08/17, 8408220119
- B408310012 Forwards response to Meteorological & Effluent Treatment Branch 840815 request for addl info re wide-range accident monitor callor factors Related correspondence KEMPER.J S Philadelphia Electric Co DSB 291 B4/08/17 SCHWENCER.A Licensing Branch 2 3pp 26350 194 24X Fiche 50-352.84/08/17,8408310012
- 8408310018 Requests that License Condition 2 re fuel rod pressure limit be closed based on resolution of issue between GE & NRC Related correspondence
  KEMPER.J 5 Philadelphia Electric Co BSB 292 84/08/17
  SCHWENCER.A Licensing Branch 2 2pp 26350 192 24X
  Fiche 50-352.84/08/17.8408310018
- 8408310007 Responds to 840206 ltr on SER License Condition 7 re compliance w/NUREO-0612 control of heavy loads Phase II "Limerick Overhead Handling Sys Final Rept (Rev 3)" revised per 840206 request Related correspondence KEMPER. J.S. Philadelphia Electric Co. DSB 293 84/08/18 SCHWENCER.A. Licensing Branch 2 3pp 26350 197 24X Fiche 50-352, 84/08/18, 8408310007
- 840B200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for DLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions 8vc list encl EISENHUT, D 9 Division of Licensing B4/08/20 Consulidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 59-000, 84/08/20, 8408200275
- 8408220453 Board Notification 84-142 forwards R Starostecki 840731 memo re alleged inadequate design of reactor encl vent stack Stack has no or limited safety significance NOVAK.TH Division of Licensing 84/08/20 BRENNER.L. COLE.R.F., MORRIB.FA Atomic Safety and Licensing Board Panel. 2pp 26261 316 24X Fiche 50-352.84/08/20,8408220463
- --8409280101 Informs that on 840710.NRC interviewed confidential alleger NOGEWOOD INFORMS that On 840/10.NKC Interviewed confidential re concerns relative to response of reactor encl vent stacks to blast lunds following railroad accident STARUSTECKI, R Division of Project & Resident Programs 84. ETBENHUT.D Q Division of Litensing 1p 26261 318 24X Fiche 50-352.84/08/20,8408220463
- 8408270161 Forwards revised response to Procedures & Sys Review Branch Question 430 72 re diesel oil storage tank lines to include addl info discussed in 840810 telcon KEMFER, J & Philadelphia Electric Co 84/08/21 SCHHENCER, A Licensing Branch 2 4pp 26245 259 24X Fiche 50-332,84/08/21. nement of 8 Philade Licensing Branch 2 8408270161
- 8408310413 Forwards revised response to Procedure & Sys Review Branch Question 430 72 re diesel oil storage tank vent lines.In response to 840810 request for addl info Related carrespondence
  KEMPER-J S Philadelphia Electric Co DSB 288 84/08/21
  SCHMENCER.A Licensing Branch 2 App 26350 224 24X
  Fiche 50~352.84/08/21.8408310413
- 8408280130 Forwards Rev I to "Solid Radwaste Sys Process Control Program." in response to Meteorological & Effluent Treatment Sys Branch request for addl info.per 840808 telcon Preoperational testing of sys scheduled for end of month MEMPER, J S Philadelphia Electric Co 84708/23 SCHWENCER, A Licensing Branch 2 2pp 26299 064 24X Fichs 50-352.84708/23.8408280130
- --8408280132 Rev i to "Bolid Radwaste Bys Process Control Program" \* Philadelphia Electric Co 84/08/31 11pp 26259 046 24X Fiche 50-352,84/08/23,8408280130
- 8408310146 Forwards response to 840509 request for additinfo re NURE9-0737. Item III D 1 i, "Primary Coolant Dutside Containment" Info will be incorporated in Sept 1984 FSAR rev KEMPER.J 8 Philadelphia Electric Co 84/09/24, SCHWENCER,A Licensing Branch 2 Ppp. 26322 208 24X Ficha 50-352,84/08/24, 84083[0]46
- 8408270158 REVIEW INBIGHTS ON THE PROBABILISTIC RIGK ASSESSMENTS FOR THE LIMERICK GENERATING STATION.UNIT I AND 2 CHELLIAH.E Division of Safety Technology NUREO-1068 84/08/31 126pp Avaiiable at NRC \$5 00 26309 151 24x Fiche 50-332,84/08/31,8408290158

- C Utility Environmental Report (ER), amends & correspondence
- 8408020058 Forwards Rev 19 to environ rept CL stage BRADLEY,E J Philadelphia Electric Co 84/07/31 DENTON.H R Office of Nuclear Reactor Regulation, Director 4pp 25904 O 24X Fiche 30-352,84/07/31,8408020058
- --84090200B0 Rev 19 to environ rept DL stage \* Philadelphia Electric Co 84/07/31 4pp 25904 010 Fiche 50-352,84/07/31,8408020058 24X
- 8408210076 Forwards Affidavit of Svc certifying distribution of Rev 34 to FBAR & Rev 19 to environ rept on 840809 BRADLEY,E J Philadelphia Electric Co 84/08/14 DENTON,H R Office of Nuclear Reactor Regulation. Director Spp 26184 327 24X Fiche 50-352,84/08/14,8408210076
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8408060232 Forwards responses to questions & comments re 840322 analysis of tornado missile effects on UHB, supporting resolution of SER Open Issue 2 Responses do not affect results of prior analysis KEMPER.J 8 Philadelphia Electric Co 84/07/27 SCHWENCER.A Licensing Branch 2 19pp 25934 117 24% Fiche 50-352,84/07/27, Licensing Branch 2 8408060232
- B408070289 Informs that upgrading & mods to RCIC turbine assembly completed, except for installation of threaded taper pins.in response to BER Open Item 6 Justification for interim operation of Unit 1 encl
  KEMPER.J S Philadelphia Electric Co B4/0B/01 SCHWENCER, A Licensing Branch 2 5pp 25948 220 24X Fiche 50-352,84/0B/01,8408070289
- B408070813 Forwards info to support resolution of SER proposed License Conditions 8.9.10 & 12 & to assist in preparation of License Condition 14 Info withheld (ref 100FR2 790 & 73 21) Affidavit of withhelding encl
  KEMPER.J S Philadelphia Electric Co 84/08/01 SCHWENCER.A
  Licensing Branch 2 5pp 25941 167 24K Fiche 50-352.84/08/01.
  8408070513
- 8408130296 Forwards relief requests from ASME Code, Section XI preservice insp requirements to resolve SER Confirmatory Issue 12 KEMPER J S Philadelphia Electric Co 84/08/07 SCHWENCER. A Licensing Branch 2 7pp 26008 349 24X Fiche 50-352.84/08/07. 8408130296.
- 840B140303 Forwards responses to 840611 request for add1 info re SER Confirmatory Issues 3.5 & 6 & BER Open Issue 29 Related traft FBAR & design assessment rept page changes also encl KEMPER.J S Philadelphia Electric Co 84/08/08 SCHMENCER.A Licensing Branch 2 27pp 26111 127 24X Fiche 50-352,84/08/08,840B140303
- --8408140314 "Spec for Test Requirements for Hot Deflection Testing of ASME Section III.Nuclear Class 1.2.3 & ANSI 831 1.Bechtel Piping, for Limerick Generating Station, Units 1 & 2 " # Bechtel Corp 84/05/29 189pp 24111 196 24X Fiche 50-352,84/08/08,8408140303
- --8408140320 "Spec for Test Requirements for Steady State Vibration Testing of ASME Section III. Nuclear Class 1.2.3 & ANSI B31 i. Bechtel Piping, for Limerick Generating Station, Units 1 & 2"
  - \* Bechtel Corp 84/05/25 280pp 26111 317 24X Firhe 50-352,84/08/08,8408140303
- --9408i40326 "Spec for Test Requirements for Dynamic Transient Testing of ASNE Section III, Nuclear Class 1.2.3 & ANSI B31 1.Bechtel Piping, for Limerick Generating Station, Units 1 & 2 " « Bechtel Corp 84/05/29 127pp 26
- 840E200262 Forwards responses to add1 questions raised by Chemical Lnyineering Branch re structural steel survivability evaluation info supports final resolution of SER Open Item 14 KENPER, J 8 Philadelphia Electric Co 84/08/08 SCHWENCER, A Liconsing Branch 2 26pp 26133 211 24X Fiche.50-352,84/08/08,8408200262
  - 1379 Forwards draft FSAR pages in response to NRC 820825 request ddl info re instrument setpoint methodology for reactor sys & ESF instrumentation setpoints Info should Confirmatory Issue 26
    Philadelphia Electric Co 84/08/10 SCHWENCER, A Iranch 2 3pp 24092 173 24X Fiche 30-352,84/08/10,

- 8408230292 Forwards Rev 3 to "Overhead Handling Sys Review " Rept TOBESURTE FORWARDS REV 3 to "Querhead Handling Sys Review " Rept revised per NUREO-O612, to address concerns identified in draft technical evaluation rept on control of heavy loads & support resolution of SER License Condition 7

  KEMPER, J S Philadelphia Electric Co 84/08/13 SCHWENCER, A Licensing Branch 2 3pp 26207 001 24X Fiche 50-352,84/08/13,8408230292
- --B408230297 Rev 3 to final rept "Overhead Handling Sys Review "

  \* Philadelphia Electric Co B4/06/30 175pp 26207 004 24x
  Fiche 50-352,84/08/13,8408230292
- 8408210031 Forwards add1 info requested in NRC 840430 ltr re exceptions to conformance to Rev 2 to Reg Quide 1 97 Encls should close Open Item 12 of SER (NUREC-0991)
  KEMPER.J S Philadelphia Electric Co 84/08/16 SCHWENCER.A Licensing Branch 2 ijpp 26181 337 24X Fiche 50-352.84/08/16, 8408210031
- 8408270376 Forwards addl info re SER Confirmatory Issue 12 concerning preservice insp program, per 840817 request KEKPER, J S Philadelphia Electric Co 84/08/23 SCHWENCER, A Licensing Branch 3 62pp 26240 258 24X Fiche 50-352,84/08/23,8408270376
- 840B300215 Requests assistance in reviewing encl app to SER re identification of vital areas Response requested within 10 days of memo data to meet review 340707 completion date App withheld (ref 10CFR79 21) THOMAS.C O Standardization & Special Projects Branch 84/0 PARR.O D Auxiliary Systems Branch 1p 26307 054 24X Fiche 50-352,84/08/24,8408300215
- F Security, medical, emergency & fire protection plans
- 8408160355 Forwards public version of Emergency plan implementing procedures, including EP-101 re classification of emergencies, EP-102 re unusual event response, EP-103 re alert response & EP-104 re site emergency response COUNEY, M J Philadelphia Electric Co 84/07/09 MURLEY, T E Region 1, Office of Director SCHMENCER, A Licensing Branch 2 5pp 26127 001 24X Fiche 50-352,84/07/09,8408160355
- --B40B160360 Public version of revised emergency plan implementing procedures, including EP-101 re classification of emergencies. EP-102 re unusual event response & EP-103 re alert response HJM Felton B40B07 release memb # Philadelphia Electric Co B4/06/08 450pp 26127 006 24 Ficha 50-352,84/07/09,840B160355
- 8408070336 Emergecy plan exercise manual \* Philadelphia Electric Co 84/07/25 426pp 25946 001 Fiche 50-352,84/07/25,8408070336
- 8408020047 Forwards JL Patton 840723 itr responding to RC Claypool 840607 ltr to Thornburgh re resources for radiological semergency response planning Related correspondence FERKIN, Z Q Pennsylvania, Commonwealth of, DSB 704 84/07/27 BRENNER, L Atomic Safety and Licensing Board Panel 2pp 25883 273 24X Fiche 50-352,84/07/27,8488020047
- B40B070513 Forwards info to support resolution of SER proposed License Conditions 8,9,10 & 12 & to assist in preparation of License Condition 14 Info withheld (ref 10CFR2 770 & 73 21) Affidavit of withhelding encl KEMPER, J S Philadelphia Electric Co 84/08/01 BCHWENCER, A Licensing Branch 2 3pp 28941 167 24X Fiche 50-352,84/08/01, B40B070513
- 8408070037 Forwards response to Procedures & Sys Review Branch queries re emergency procedures & selection of containment vent pressure

  KEMPER, J S Philadelphia Electric Co 84/08/02 SCHWENCER, A KEMPER, J S Philadelphia Electric Co 84/08/02 SCHWENCER, A Licansing Branch 2 App 25949 329 24X Fiche 50-352, 84/08/02, 8408070037.
- 8408130637 Revised notification of 840807.07 & 10 meetings w/util in Bethesda, MD & Linfield, PA to discuss outstanding Items in detailed control room design review MARTIN, R.E. Licensing Branch 2 84/08/07 SCHWENCER, A Licensing Branch 2 5pp 26102 339 24X Fiche 50-352,84/08/07,8408150637
- B408220497 Forwards public version of revised emergency plan implementing procedures including EP-105, "General Emergency Response" & EP-304, "Partial Plant Evacuation " Release memo dtd 840820 encl DALTROFF, S. L. Philadelphia Electric Co 84/08/07 MURLEY, T E Region I, Office of Director SCHMENCER, A Licensing Branch 2 7pp 26210 213 24X Fiche 50-352,84/08/07,8408220497

- --8408220501 Public version of revised emergency plan implementing procedures, including EP-105, "General Emergency Response" & EP-304, "Partial Plant Evacuation" & Philadelphia Electric Co. 84/08/07 25pp 26210 219 24X Fiche 50-352,84/08/07,8408220497
- 8408200147 Informs of review of schedule for sprinkler design & installation in conjunction w/possible temporary protective measures Installation of permanent sprinkler sys should be expedited

  KEMPER.J S Philadelphia Electric Co 84/08/08 SCHWENCER, A Licensing Branch 2 3pp 26133 283 24X Fiche 50-352, 84/08/08, 8408200147
- 8408200206 Forwards info re 4-kV penetrations, resolving item questioned during 840407-12 fire protection sys & documentation site audit Info will be incorporated into next rev to fire protection evaluation rept KEMPER, J S Philadelphia Electric Co 84/08/08 SCHWENCER, A Licensing Branch 2 30pp 26/33 067 24% Fiche 50-352,84/08/08,8408200206
- 8408150404 Forwards correspondence & documents between applicant, staff, Commonwealth of PA & responsible govt agencies re emergency planning Relabed correspondence CULLEN.E J Philadelphia Electric Co DSB 064 84/08/10 MULLIGAN.M Limerick Ecology Action 24pp 28068 196 24X Fichs 50~332.84/08/10,8408150404
- 8408170381 Forwards supplemental info re Limerick Ecology Action 840806 response to util discovery request on admitted offsite emergency planning contentions Certificate of Svc encl MULLIGAN, M Limerick Ecology Action DSB 102 84/08/13 RADER Philadelphia Electric Co 200pp 26137 181 24X Fiche 50-332,84/08/13,8408170381
- B40B2002B6 Forwards correspondence & documents among NRC, applicant & Commonwealth of PA re emergency planning per ASLB 820601 order Matl suppls 840B10,0712 & 30 submittals Related carrespondence CULLEN,E J Philadelphia Electric Co DSB 142 84/0B/15 MULLIGAN,M Limerick Ecology Action 50pp 26131 0B5 24X Fiche 50-352,84/0B/15,84082002B6
- 8408210452 Responds to concerns discussed in 840720 telcon re control room design review final rept final validation will be performed prior to fuel load Results will be submitted by 841031 KEMPER, J 9 Philadelphia Electric Co 84/08/16 SCHWENCER, A Licensing Branch 2 4pp 26177 200 24X Fiche 50-352,84/08/16,8408210452
- 840B240262 Forwards correspondence & documents among applicant,NRC & other parties re emergency planning Documents suppl matl forwarded in 840B15 itr & provide add1 correspondence dtd 840616-10B08 Related correspondence CULLEN.E J Philadelphia Electric Co DSB 264 84/08/20 MULLIGAN.M Limerick Ecology Action 652pp 26223 214 24X Fiche 50-352,84/08/20,8408240262
- 8408280177 Provides resolution of concerns re fusible links on fire doors identified during 840407-12 site audit of fire protection sys & documentation Fusible links provided on hold open mechanisms for hollow metal doors KEMPER, J S Philadelphia Electric Co 84/08/22 SCHWENCER, A Licensing Branch 2 2pp 26275 088 24X Fiche 50-352,84/08/22,8408280177
- 8408300215 Requests assistance in reviewing encl app to SER re identification of vital areas Response requested within 10 days of memo date to meet review 840907 completion date App withheld (ref 10CFR73 21) THOMAS.C O Standardization & Special Projects Branch 84/08/24 PARR.O D Auxiliary Systems Branch ip 26307 054 24X Fiche 50-352,84/08/24,8408300215
- 8408310008 Rev i to Emergency Plan Implementing Procedure EP-316, "Cumulative Population & Near Real-Time Emergency Dose Calculations for Airborne Releases Manual Method." W/840824 ltr
  DALTROFF, S L Philadelphia Electric Co 84/08/24 MURLEY, T E Region I. Office of Director SCHWENCER, A Licensing Branch 2 74pp 26323 206 24% Fiche 50-352,84/08/24,8408310008

#### G Adjudicatory correspondence

8408310096 Brief of RL Anthony & Friends of the Earth in support of appeal from ABLB 840306 & 21 verbal orders & 840316 written order & request for hearing ANTHONY, R. L. ANTHONY, R. L. Friends of the Earth DSB 4103128 4pp 26322 227 24X Fiche 50-352,84/03/28,840831094

- 8408280491 Suppl to RL Anthony & Friends of the Earth motion vs applicant motion for partial decision & low power license & submission of 840518 contentions on new matter ANTHONY, R L Anthony, R L ANTHONY, R L Friends of the Earth DSB 358 84/05/30 Atomic Safety and Licensing Board Panel 2pp 26280 336 24X Fichs 50-352,84/05/30,8408280491
- B40B160112 Forwards intervenor Exhibits 3.4,47-135 & 136 Related correspondence RILEY.8 L Tayloe Associates 84/05/31 PLEASANT,E Administrative & Logistical Support Branch 1p 26126 325 243 Fiche 50-352.84/05/31.8408160112
- 8408160079 Forwards applicant Exhibits 137-151 Related correspondence RILEY, S.L. Tayloe Associates 84/06/08 PLEASANT.E Administrative & Logistical Support Branch 1p 26126 328 24X Fiche 50-352, 84/06/08, 8408160099
- 8408160103 Forwards NRC staff Exhibit 29 & intervenor Exhibits 1 & 2 Related correspondence RILEY, B. L. Taylor Associates 84/06/15 PLEASANT, E Administrative & Logistical Support Branch 1p 26126 327 24X Ficho 50-352.84/06/15.8408160103
- 8408160079 Forwards applicant Exhibits 153-173 Related correspondence RILEY, S.L. Tayloe Associates 84/06/26 PLEASANT, E. Administrative & Logistical Support Branch 1p 26126 346 24X Fiche 50-352,84/06/26,8408160079
- 8408010223 Forwards suppl to 840523 ltr to ASLB & ASLAB rs NRC duties concerning supplemental water Related correspondence SUGARMAN.R J Sugarman & Denworth SUGARMAN.R J Del-Aware Unlimited, Inc. DSB 659 84/07/13 PALLADING.N Commissioners 2pp 23836 022 24X Fiche 50-352.84/07/13,8408010223
- --8408010228 Submits follows to 840523 & 0705 ltrs reposition that NRC exhibits pro-applicant bias Position based on Denton 840629 ltr & util 840417 notes Board action requested W/o sncls
  SUGARMAN.R J Sugarman & Denworth SUGARMAN.R J Del-Aware Unlimited. Inc 84/07/13 BRENNER,L , CDLE.R F , MORRIS,P A Atomic Safety and Licensing Board Panel 2pp 25856 024 24X Ficha 50-332,84/07/13.8408010223
- 8408010233 Response to NRC response to Air & Water Pollution Patrol 840626 contention re gross alpha W/svc list ROMANO,FR Air and Water Pollution Patrol DSB 658 84/07/25 4pp 25856 014 24% Ficher 50-352,84/07/25,8408010233
- 8408040179 Informs that borough participated in 840725 evacuation drill per Mayor recommendation Drill not sanctioned by borough council & evacuation per Draft 5 of emergency evacuation plans disapproved Served on 840803 AUGUST, BK Phoenixville, PA DSB 735 84/07/25 BRENNER Atomic Safety and Licensing Board Panel 2pp 25932 183 24X Fiche 50-392,8407/25,8408040179
- 8408010248 Forwards suppl to 840523 Itr to ASLB & ASLAB re NRC duties concerning supplemental mater Certificate of Svc encl Related correspondence 800ARMAN,R J Sugarman & Denworth SUCARMAN,R J Del-Aware Unlimited, Inc. 1958 663 84/07/26 PALLADINO,N Commissioners 2pp 25855 341 24% Fiche 50-352,84/07/26,8408010248
- 8408010190 Errata to 840726 proposed findings of fact & conclusions of law on Limerick Ecology Action Contentions DES-1, DES-2, DES-3 & DES-4 Proposed transcript corrections & Certificate of Svc encl ELLIOTT.C W Limerick Ecology Action DSS 680 84/07/27 5pp 23855 163 24X Fiche 50-352,84/07/27,8408010190
- B40B010233 Answer to Consumer Educ & Protective Assoc 840717 safety contentions Contentions lack basis, concern ratemaking matters outside NRC Jurisdiction & should be denied Certificate of Bvc encl.

  GUNNER, T B Philadelphia Electric Co CONNER, T B Conner & Westerhahn DBS 670, 84/07/27 Atomic Safety and Licensing Board Panel. 9pp 25854 315 24X Fiche 50-352,84/07/27,8408010255
- 8408020047 Forwards JL Patton 840723 ltr responding to RC Claypool 840607 ltr to Thornburgh re resources for radiological amergency response planning Related correspondence FERKIN. Z G Pennsylvania, Commonwealth of, D88 704 84/07/27 BRENNER, L, COLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel 2pp 25883 273 24X Fiche 50-352,84/07/27,8408020047
- B408070302 Response to Consumer Educ & Protective Assoc (CEPA) safety contentions received on 840716 CEPA contentions provide inadequate basis for concerns & should not be admitted Certificate of Syc encl
  WRIGHT.N A Hearing Branch 2 DS8 807 84/07/31 Atomic Safety and Licensing Board Panel 9pp 25947 231 24X
  Fiche. 50-352.84/07/31,8408070302

- 8408080191 Appeal to Commission from ASLAB 840723 Memorandum & Order ALAB-778 re contentions on nuclear fuel Immediate stay requested W/Svc list
  ANTHONY.R L Anthony. R L ANTHONY.R L Friends of the Earth DS 8315 84/07/31 2pp 25960 257 24% Fiche 50-352.84/07/31.
  8408080191
- 840B040053 First set of interrogatories & request for production of documents to city of Philadelphia re offsite emergency planning Contentions City-18 & City-19 Certificate of Svc encl Related correspondence RADER.R M Philadelphia Electric Co RADER.R M Conner & Hetterhahn DS 743 84/08/01 Philadelphia, PA 12pp 25933 177 24X Fiche 50-352.84/08/01.8408060053
- 840B060170 Second errata to B40726 proposed findings of fact & conclusions of law on Linerick Ecology Action Contentions DES-1.DES-2.DES-3 & DES-4 Certificate of Svc encl ELLIOTT. CW Limerick Ecology Action DSS 742 84/08/01 3pp 25932 194 24% Fiche 50-352,84/08/01.8408060170
- 8408060182 Confirms points discussed in 840727 telcon, agreements reached & matters in dispute re Limerick Ecology Action answers to Applicant first set of interrogatories & request for production of documents Related correspondence RADER, R M Conner & Wetterhahn DSB 745 84/08/01 MULLIGAN, M Limerick Ecology Action 8pp 25932 175 24X Fiche 50-352, 84/08/01.8408040182
- 8408060228 Forwards applicant B40727 answer to CEPA safety contentions W/o encl Related correspondence HETTERHAHN, M J Philadelphia Electric Co DSB 744 84/08/01 HERSHEY, B P CEPA HERSHEY, B P Hershey, B P ip 25933 335 24X Fishe 50-352,84/08/01,8408060228
- 8408070350 Discusses RJ Sugarman correspondence & concerns re ex parte communications Matters raised by RJ Sugarman w/a merit & will be addressed formally by director in decision per ICCFR2 204 Related correspondence CONNER.T B Conner & Wetterhahn CONNER.T B Philadelphia Electric Co D88 777 84/08/02 CHILKS J Office of the Secretary of the Commission 3pp 25944 147 R4X Fiche 50-352,84/08/02,8408070350
- 8408070363 Motion to compel answers to first set of interrogatories, to compel production of withheld documents & for related relief re destroyed documents Certificate of Svc encl Related correspondence
  RADER, R M Philadelphia Electric Co RADER, R M Conner & Westerhahn DSB 780 84/08/02 Atomic Safety and Licensing Board Panel 16pp 25945 158 24X Fiche 50-352.84/08/02.8408070353
- 8408070366 Transmittal of VS Boyer 840802 affidavit re schedule for fuel loading.per ASLB 840620 order Certificate of Svc encl Related correspondence WETTERHANN.M J Philadelphia Electric Co DSB 781 B4/08/02 6pp 25945 152 24X Fiche 50-352,84/08/02,8408070366
- 8408070412 Forwards answer to second set of interrogatories & request for production of documents on Limerick Ecology Action admitted offsite emergency planning contentions (Discovery 33) Related correspondence RADER, R M Conner & Hetterhahn RADER, R M Philadelphia Electric Co D89 782 84/08/02 MULLIGAN.M Limerick Ecology Action 1p 25742 053 24X Fiche 30-332,84/08/02,8408070412
- -8408070415 Answer to second set of interrogatories & request for production of documents on Limerick Ecology Action admitted offsite emergency planning contentions (Discovery 35)
  Cartificate of Bvc ancl
  # Philadelphia Electric Co 84/07/31 Limerick Ecology Action 91pp 25942 054 24X Fiche 50-352,84/08/02,8408070412
- IOBO70287 Forwards signature page of 840802 motion to compel answers to first set of interrogatories, to compel production of withheld documents & for related relief re destroyed documents

  CONNER.T B Conner & Wetterhahn CONNER.T B Philadelphia Electric
- documents CONNER.T B Conner & Wetterhahn CONNER.T B Philadelphia Electric Co DBB 903 84/08/03 Docketing & Services Branch 1p 25948 218 24% Fiche 50-352,84/08/03,8408070287
- N408070291 Signature page of B40802 motion to compel answers to first set of interrogatories CONNER.T B Conner & CONNER.T B Conner & Wetterhahn 84/08/02 Atomic Safety and Licensing Board Panel ip 25948 219 24% Fishe 50-352,84/08/03,8408070287
- 8070429 Forwards VS Boyer 840802 affidavit re schedule for fuel oading Related correspondence ETTERHAHN.M J Conner & Wetterhahn WETTERHAHN,M J Philadelphia lectric Co D88 802 84/08/03 Docketing & Services Branch ip 25940 049 24X Fiche 50-352,84/08/03,8408070429

- --B408070433 Affidavit of VS Boyer re schedule for fuel loading B0YER.V S Philadelphia Electric Co 84/08/02 2pp 25940 050 24X Fiche 50-352,84/09/03,8408070429
- 8408090226 Forwards motion before ASLAB to set aside partial initial decision based on new evidence SUGARMAN.R J Del-Aware Unlimited. Inc DSB 838 84/08/03 Office of the Secretary of the Commission ip 25971 114 24X Fiche 50-352,84/08/03,8408090226
- --8408090233 Motion to set aside partial initial decision based on new evidence & circumstances Certificate of Svc encl SUGARMAN, R. J. Del-Aware Unlimited, Inc. SUBARMAN, R. J. Sugarman & Denworth 84/07/31 Atomic Safety and Licensing Appeal Panel 52pp 25971 115 24X Fiche 50-392,84/08/03.8408090226
- 8408070372 Reply to City of Philadelphia & Limerick Ecology Action 840726 proposed findings of fact & conclusions of law reserver excident risk assessment contentions Certificate of Svc encl WETTERHAHN, M J. NICHOLS, N N Philadelphia Electric Co WETTERHAHN, M J. Conner & Wetterhahn DSB 795 84/08/06 29pp 25944 170 24X Fiche 50-352,84/08/06,8408070372
- 8408070444 Forwards answer to Limerick Ecology Action second set of interrogatories & request for production of documents readmitted offsite energency planning contentions Encl replaces 840802 answers Related correspondence RADER, R M Conner & Wetterhahn RADER, R M Philadelphia Electric Co DSI 789 84/08/04 MULLIGAN, M Limerick Ecology Action ip 25742 268 24X Fiche 50-952,84/08/06,8408070444
- ---8408070450 Revised answer to second set of interrogatories & request for production of documents on Limerick Ecology Action admitted offsite emergency planning contentions BOYER: V S Philadelphia Electric Co 84/08/03 Limerick Ecology Action 88pp 25942 267 24X Fiche 50-352:84/08/06, B408070444
- 8408070475 Informs that applicant does not intend to respond to Sugarman 840713 ltr purporting to update earlier ltrs of 840523 & 0605 to ASLAB & ASLB or to any future ltrs to ASLAB or ASLAB CONSERT B CONSERT Atomic Safety and Licensing Board Panel 2pp 25941 191 24X Fiche 50-352,84/08/06.8408070475
- 8408090197 Reply to Limerick Ecology Action & City of Philadelphia proposed findings of fact & conclusions of law re severe accident risk assessment contentions VOGLER, B H . HODOBON, A P Hearing Branch 2 DSB 871 84/08/06 Atomic Safety and Licensing Board Panel 14pp 25972 001 24X Fiche 50-352,84/08/06,8408090197
- 8408090238 Forwards supplemental info re interrogatories.per util 840727 phone call & 840801 ltr Related correspondence MULLIGAN:M Limerick Ecology Action DS8 859 84/08/06 RADER Philadelphia Electric Co 7pp 25972 114 24X Fiche 50-352,84/08/06.8408090258
- --B408090263 Amended ensuers to util first set of interrogatories re offsite emergency planning Contention LEA/FOE 24 Certificate of Svc encl ANTIONY:R L Anthony. R L 84/07/23 Philadelphia Electric Co 6pp 25972 121 24X Fiche 50-352.84/08/06.8408090258
- 8408080379 Joint rept of parties on schedule proposal for offsite emergency planning matters filed in response to 840723 order Certificate of Svc oncl CONNER.T B Philadelphia Electric Co CONNER.T B Conner & Wetterhahn DSB 837 84/08/07 Atomic Safety and Licensing Board Panel 14pp 23974 087 24% Fiche 50-352,84/08/07,8408080399
- 8408080404 Motion to strike Air & Water Pollution Patrol (AMPP)
  pleading & reply to AMPP motion re Contention VI-1 Motion
  filed late & w/o basis Certificate of Bvc encl
  METTERHAHNI, M J Philadelphia Electric Co METTERHAHNI, M J Conner &
  Hetterhahn DSB 83B 84/08/07 Atomic Safety and Licensing Board
  Panel 7pp 25974 080 24X Fiche 50-352, 84/08/07,8408080404
- B408090238 Forwards NRC B40727 Amend 1 to License SNM-1926 & SER in support of amend Related correspondence VOGLER, B H Hearing Branch 4 DSB B72 B4/08/07 BRENNER, L, MORRIB, P A, COLE, R F Atomic Safety and Licensing Board Panel 14pp 25972 152 24X Fiche 50-352,84/08/07,8408090238

- 840B13036B Replies to 840705 ltr re 840523 ltr to Chairman Palladino All encis to itr possibly not included to all incipients Comments on encis inconsistent w/practice followed for some time w/o objection
  SUGARMAN, R J Sugarman & Denworth SUGARMAN, R J Del-Aware
  Unlimited, Inc DSB 897 84/08/07 MALSCH.M 0 Office of the General Counsel ip 26011 127 24X Fiche 50-352,84/08/07,840B13036B
- B40B140450 Forwards new contention re evacuation RDMAND:F R Air and Water Pollution Patrol DSB 015 84/08/08 Atomic Safety and Licensing Board Panel 6pp 26061 001 24X Fiche 50-352.84/08/08.8408140450
- --8408140452 New contention that applicant must provide fully testable & capable emergency evacuation plan prior to receipt of GL ROMANO,F R Air and Water Pollution Patrol 84/08/08 Atomic Safety and Licensing Board Panel Spp 2606( 002 24% Fiche 80-332,84/08/08,8408140450
- 8408130158 Order establishing filing date of 840804 for motion to set aside based on new evidence received on 840809 Motion & Itr bear postmark date of 840804 Served on 840810 SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel D68 928 84/08/09 Del-Aware Unlimited, Inc. 2pp 26007 352 24X Fiche 50-352,84/08/09.8408130158
- 8408140484 Forwards amended Certificate of Svc of appellant motion to set saide based on new evidence Amend reflects svc of motion on 840806 LOCKE, R T Sugarman & Denworth LOCKE, R T Del-Aware Unlimited, Inc. DSB 013 84/08/09 KOPH., C N , EDLES, G , GOTCHY, R L Atomic Safety and Licensing Board Panel Spp 26060 276 24X Fiche 80-352.84/08/09.8408140484
- B40Bi40540 Reply to applicant & staff answers to CEPA safety contentions Contentions should be admitted Certificate of Svc encl
  HERBHEY, S P CEPA DSB 027 B4/08/09 Atomic Safety and Licensing Board Panel 7pp 26061 220 24X Fiche 50~352,84/08/09,840Bi40540
- 8408150404 Forwards correspondence & documents between applicant, staff.
  Commonwealth of PA & responsible govt agencies re emergency
  planning Related correspondence
  CULLEN.E J Philadelphia Electric Co D88 064 84/08/10
  MULLIOAN.M Limerick Ecology Action 24pp 26068 196 24X
  Fiche 50-332,84/08/10,8408150404
- 8408150477 Responds to 840806 ltr forwarding Limerick Ecology Action supplemental responses to applicant discovery requests gupplemental answers addressed individually Related correspondence RADER:R M Conner & Wetterhahn RADER:R M Philadelphia Electric Co DSB 062 84/08/10 MULLIGAN.M Limerick Ecology Action 4pp 26068 160 24% Fichs 50-352,84/08/10,8408150477
- 0408190183 Order approving proposed transcript corrections as listed Served on 840814
  BRENNER, L Atomic Safety and Licensing Board Panel DS8 047
  84/08/13 2pp 26066 245 24X Fithe 50-352,84/08/13,8408150183
- 8408190387 Answer in opposition to Friends of the Earth 840731 petition for review of ALAB-778 No substantial conflict between ABLB & ABLAB presented Certificate of Svc encl WETTERHARIN.M J Philadelphia Electric Co WETTERHARIN.M J Conner & Wetterhahn DBB 061 84/08/13 Commissioners 10pp 26048 285 24X Fiche 50-332.84/08/13,8408150387
- 8408170381 Forwards supplemental info re Limerick Ecology Action 840806 response to util discovery request on admitted offsite swergency planning contentions Certificate of Svc encl MULLIOAN, M Limerick Ecology Action DS8 102 84/08/13 RADER Philadelphia Electric Co 280pp 26137 181 24X Fiche 50-352,84/08/13,8408170381
- 8408200433 Forwards response to applicant motion re Contention VI-I & further support for respening Contention VI-I re welding & welding insp infractions
  ROMAND, F.R. Air and Mater Pollution Patrol DSB 164 84/08/14
  Ip 26136 292 24X Fiche 50-352.84/08/14.8408200433
- --8408200442 Response to applicant motion to strike Air & Water Pollution Patrol (AWPP) pleading & raply to AWPP motion re Contention VI-1 contention VI-1 must be litigated ROMANO.FR Air and Water Pollution Patrol 84/08/10 Atomic Safety and Licensing Board Panel ip 26136 293 24X Fiche 50-352,84/08/14.8408200433

- --8408200447 Further support for reopening Contention Vi-I re welding & welding ansp infractions Air & Water Pollution Patrol calls for full-scale reinspire lack of fusion & Broomstick Affair revelations
  ROMANO,FR Air and Hater Pollution Patrol 94/08/13 Atomic Safety and Licensing Board Panel 2pp 26136 294 24%
  Fithe 50-332.84/08/14,8408200433
- 8408150425 Response opposing Friends of the Earth & R Anthony 840731 patition for review & request for stay of ALAD-778 Motion fails to establish existence of important issues of fact, law or policy & should be denied Certificate of Svc encl VOLOCR.B H. WRIGHT, N A Hearing Branch 2 DSB 067 84/08/15 Commissioners 15pp 26068 220 24% Fiche 50-352.84/08/15. RADRISO425
- 8408170305 Order establishing schedule for admitted offsite emergency planning issues Schedule for deferred contentions will be established Countesy notification encl Served on 840836 GRENNER, L Atomic Safety and Licensing Board Panel DSB 095 8408715 Office of the Executive Legal Director 6pp 26115 246 24X Fiche 50-352,84/08/15,8408170305
- 8408200286 Forwards correspondence & documents among NRC, applicant & Commonwealth of PA re emergency planning, per ASLB 820601 order Matl suppls 840810,0712 & 30 submittals Related correspondence CULLEN.E J Philadelphia Electric Co DSB 142 84/08/15 MULLIGAN.M Limerick Ecology Action 50pp 26131 085 24X Fiche 50-352.84/08/15.8408200286
- B40B210341 Forwards order establishing schedule for offsite emergency planning issues W/o encl Related correspondence VOGLER, B H Hearing Branch 2 DBJ 186 B4/08/16 PERRY, S Federal Emergency Management Agency 2pp 26179 361 24X Fiche 50-352,84/08/16,8408210341
- 8408220354 New info contention re health hazard via golyvinyl chloride fill used in reactor cooling towers W/svc list ROMAND,F R Air and Water Pollution Patrol DBB 196 84/08/16 Atomic Safety and Licensing Board Panel 4pp 26189 318 24X Fiche 50-352,84/08/16,8408220354
- 8408220379 Informs of errors in City of Philadelphia record fitations re statement of NRC witness Acherya Also forwards Commonwealth of PA Public Utility Commission 840807 order to show cause Related correspondence
  DUSHIM W Philadelphia, PA DSB 177 84/09/16 BRENNER, L Atomic Safety and Licensing Board Panel 5pp 26191 347 24X
  Fiche 80-332.84/08/16,8408220379
- 8408240240 Provides addendum to Air & Water Pollution Patrol 840816 new info contention re polyvinyl chloride Fifth criterion re breakdown of polyvinyl chloride inadvertantly omitted Small delay in proceedings ack for large public good ROMAND,F R Air and Water Pollution Patrol DSB 271 84/08/20 Atomic Safety and Licensing Board Panel ip 26222 361 24X Fiche 50~352,84/08/20,8408240240
- 840B240262 Forwards correspondence & documents among applicant.NRC & other parties re emergency planning Documents suppl matiforwarded in 840B15 ltr & provide addl correspondence dtd 84061i-0808 Related correspondence CULLEN.E J Philadelphia Electric Co D88 264 84/08/20 MULLIGAN.M Limerick Ecology Article 252pp 26223 214 24X Fiche 50-352.84/08/20,8408240262
- B40B240236 Answer opposing late-filed Air & Water Pollution Patrol B40B0B new contention re evacuation Contention lacks basis & specificity & fails to show good cause for late filing Cartificate of Svc encl CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn D80 247 B4/08/21. Atomic Safety and Licensing Board Panel 18pp 26222 259 24X Fiche 50-352,84/08/21,8408240236
- B40B240241 Answer opposing Del-Aware Unlimited. Inc B40B06 motion to set aside ASLB 830308 partial initial decision re supplementary cooling water systhased on new evidence Motion should be denied Certificate of Bvc ancl CONNER.T B Philadelphia Electric Co CONNER.T B Conner & Wetterhahn DSB 270 B4/0B/21 Atomic Safety and Licensing Appeal Panel 46pp 26223 066 24X Fiche 50-352,84/0B/21, B40B240241
- 8408240256 Forwards util comments on Del-Aware request under 10CFR2 206. per 840523 & 0713 requests for relief Matters repetitions & inappropriate under 10CFR2 206 & fail to raise significant anviron concern CONNER. T B Conner & Watterhahn CONNER. T B Philadelphia Electric Co 84/09/21 DENTON. H R Defice of Nuclear Reactor Regulation. Director 17pp 26273 001 24% Fichs 50-352.84/08/21.8408240256

- B408230200 Memorandum & order denying Citizens Action in Northeast B40625 & Consumers Educ & Protective Assoc B40716 motions to admit or certify financial qualifications contentions Served on B40822
  - Served on 840822
    BRENNER.L Atomic Safety and Licensing Board Panel DSB 254
    84/08/22 Office of the Executive Legal Director 11pp
    26207 198 24% Fiche 50-352,84/08/22,8408230200
- 840B280415 Kation for reconsideration of ASLB 840B15 order establishing schedule for offsite energency planning issues FEMA should not be required to distribute draft rept by 840901 Cartificate of Svc encl VDQLER.B H . WRIGHT.N A Hearing Branch 2 DSB 344 84/08/23 Atomic Safety and Licensing Board Panel 4pp 26280 290 24X Fiche 50-332.84/08/23,8408280415
- 8408280162 Memorandum & order rejecting Friends of the Earth & Air & Water Pollution Patrol (AMPP) late-filed contentions & denying AMPP second request for reconsideration of asbestos contention Courtesy notification encl Served on B40827 BRENNER.L Atomic Safety and Licensing Board Panel DSB 326 84/08/24 Friends of the Earth 27pp 26275 116 24X Fiche 50-352.84/08/24.8408280162
- 8408280388 Confirms 840824 telcon informing of 840830 meeting in Philadelphia.PA to discuss matters covered by ASLB scheduling order Related correspondence RADER.R M Conner & Wetterhahn RADER.R M Philadelphia Electric Co DSB 334 84/08/24 VUGLER.8 H Hearing Dranch 2 FERKIN.Z G Pennsylvania, Commonwealth of. SMOLLEN.H Philadelphia, PA 2pp 26280 032 24% Fiche 50-332.84/08/24.8408280338
- 8408280237 Order extending time until 840921 for Commission to act to review ALAB-778 Served on 840827 CHILK.8 J Office of the Secretary of the Commission DSB 319 84/08/27 Commissioners ip 26262 278 24X Fiche 50-352.84/08/27.8408280237
- B40B300170 Response opposing Del-Aware B40B06 motion to set aside ASLB B3030B partial initial decision on environ effects of supplemental cooling water sys based on new evidence Certificate of Svc encl VOQLER.B H Hearing Branch 2 DSB 381 B4/08/27 Atomic Safety and Licensing Appeal Panel 23pp 26305 320 24X Fiche 50-352.B4/08/27.B40B300170
- B40B300i17 Response apposing admission of Air & Water Pollution Patrol 840B08 new contention re evacuation filed by FR Romano Certificate of Svc encl HRIQHT, N A Hearing Branch 2 DSB 379 84/08/28 Atomic Safety and Licensing Board Panel 12pp 26305 171 24X Fichs 30-352,84/08/28,8408300117
- 840830016B Second Partial Initial Decision LBP-84-31 on listed issues in controversy in favor of applicant Courtesy notification encl Served on B40827
  BRENNER, L. COLE, R. F., MORRIS, P. A. Atomic Safety and Licensing Board Panel D8B 386 84/08/27 329pp 26303 158 24X
  Fiche 80-352,84/08/29,8408300168
- 8408310223 Response opposing Air & Water Pollution Patrol 840814 pleading on reopening Contention VI-1 re welding & welding insp infractions Certificate of Svc encl WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn DBB 423 84/08/29 Atomic Safety and Licensing Board Panel Spp 26319 244 24X Fiche 50-352,84/08/29,8408310223

## ( Utility Final Safety Analysis Report (FSAR) & amends

- 3408020059 Forwards Rev 34 to FSAR BRADLEY,E J Philadelphia Electric Co 84/07/31 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 25904 001 24X Fiche 30-32.84/07/31.8408020058
- -8408020084 Rev 34 to FBAR \* Philadelphia Electric Co 84/07/31 272pp 259D4 014 24X Fiche 50-352,84/07/31,8408020058
- MOB210076 Forwards Affidavit of Svc certifying distribution of Rev 34 to FSAR & Rev 19 to environ rept on 840807 BRADLEY,E J Philadelphia Electric Co 84/08/14 DENTON, H R Office of Nuclear Resouter ton, Director 5pp 26184 327 24X Fiche, 50-332,84/08/14,8408210076

- O Inspection reports: IE Bulletins & correspondence
- 8408310124 Forwards response to NRC 840620 ltr re violations noted in Insp Repts 30-332/84-24 & 50-353/84-08 on 840501-31 Seismic classifications of three piping isometric drawings & four piping field sketches corrected Related correspondence KEMPER.J S Philadelphia Electric Co DS8 002 84/07/19 MURLEY.T E Region 1. Office of Director 4pp 26352 028 24X Fiche 50-352.84/07/19.8408310124
- 8407250229 IE Info Notice 84-57. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24% Fiche 50-000,84/07/27,8407250229
- B408210368 Forwards IE Insp Repts 50-352/84-26 & 50-353/84-09 on 840601-30 & notice of violation STAROBTECKI.R Division of Project & Resident Programs 84/08/02 KEMPER.J S Philadelphia Electric Co 2pp 26183 109 24X Fiche 50-352,84/08/02,8408210368
- --8408210373 Notice of violation from Insp on 840601-30 \* Region 1, Office of Director 84/08/02 4pp 26183 111 24X Fiche 50-352,84/08/02,8408210368
- --8408210381 IE Insp Repts 50-352/84-26 & 50-353/84-07 on 840601-30 Violetions identified inadequate diesel generator test program implementation & inadequate calibr procedure for valve position indicating sys CHAUDHARY, 5 K , WIGGINS, J T , BAUNACK, W Region 1, Office of Director 84/07/24 15pp 26183 115 24X Fiche 50-352,84/08/02,8408210368
- ~~B40B210394 Responds to NRC 840321 ltr re violations noted in IE Insp Repts 50-352/84-19 & 50-353/84-06 Corrective actions notice issued to include info on P&ID M-42 & Procedure QADP-27 1 revised GALLAGHERJ W Philadelphia Electric Co 84/06/20 MURLEY, T E Region 1, Office of Director 5pp 26183 130 24X Fiche 50-352,84/08/02:8408210368
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JCRDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp 24068 001 24% Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- 8408130296 Forwards relief requests from ASME Code, Section XI preservice insprequirements to resolve SER Confirmatory Issue 12
  KEMPER.J 5 Philadelphia Electric Co 84/08/07 SCHWENCER.A Licensing Branch 2 7pp 26008 349 24X Fiche 50-332,84/08/07,8408130296
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Cansolidated Edison Ca of New Yark, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" 8vc list snc1 QRACE.J N Division of QA Safeguerds & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24x Fiche 80-000/84/08/10,8408070376
- 8408100009 IE Info Notice 84-43, "Defective RHR Replacement Piping " 8vc list enci JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc. 119pp 26197 218 24X Fiche 50-000.84/08/13,8408100009
- B40B10003B IE Info Notice B4-64. "BWR HPCI Initiation Seal-In & Indication " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103). 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
  - list encl
    JORDAN, E.L. Division of Emergency Preparedness & Engineering
    Response (Post 830103) 84/08/16 Consolidated Edison Co. of New
    York, Inc. 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021
- B40B100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train" Svc list enci JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/08/17 Consolidated Edison Co of New York, Inc. 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- 840B14020B IE Info Notice 84-67, "Recent Gnubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York. Inc 122pp 26276 122 24X Fiche 30-000.84/08/17.840B14020B
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Bolenoid Valves " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Conselldated Edison Co of New York, Inc 115pp 26329 008 24X Fichs 50-000,84/08/21,8408210142
- 8408240013 Confirms 840824 telcon re 840827-31 insp concerning sissmic design of structures, pipe break analysis & south stack blast load calculations ZECH. 6 6 Vendor Program Branch 84/08/21 STRATTON, C D Bechtel Corp ip 26228 248 24% Fiche 50-392,84/08/21,8408240013
- 8408270376 Forwards add1 info re SER Confirmatory Issue 12 concerning preservice insp program, per 840817 request KEMPER. J S Philadelphia Electric Co 84/08/23 SCHWENCER. A Licensing Branch 3 62pp 26240 238 24X Fiche 50-352, 84/08/23, 8408270376
- R Periodic operating reports & related correspondence
- 8408050419 Forwards fourth status rept re independent design review of core spray sys for 840701-15 Related correspondence CARPENTER, D. Torrey Pines Technology DSB 719 84/07/16 80YER, V.S. Philadelphia Electric Co. 7pp 25951 123 24X Fiche 50-352,84/07/16,8408060419
- B408310023 Forwards "Independent Design Review of Limerick Generating Station 1 Core Byray Sys. Bi-Monthly Status Rept 5 for Period Ending 840731 " Related correspondence CARPENTER, F D Torrey Pines Technology DSB 234 84/08/01 BOYER, V S Philadelphia Electric Co 7pp 26350, 102 24X Fiche 50-352, 84/08/01,8408310025
- S Reportable occurrences. LERs & related correspondence
- 8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated.
  SHERHOUD. 6 O General Electric Co 84/04/13 DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26222 236 24X Ficha 50-000,84/04/13,8408240348
- 8408240332 Submits annotated requests for followup on potentially generic problem in enc1 Part 21 rept from Basier Electric re SCRs on nuclear exciters mounted w/too much pressure.

  NORELIUS.C E Division of Project & Resident Programs 84/04/25 JORDAN.E L Director's Office, Office of Inspection and Enforcement 1p 26225 303 24X Fiche 50-000.84/04/25,8408240332
- 8408310110 Significant Deficiency Rept 148 re design calculations made by MJ Woolley Co for doors specified to moet tornadogenerated missile criteria Door reanalysis underway Previously reported under Part 21 by MJ Moolley Co KEMPER. J S Philadelphia Electric Co 84/08/23 MURLEY, T E Region 1, Office of Director 1p 26322 237 24X Fiche 50-332.84/08/23.8408310110
- T Hearing transcripts on non-antitrust matters
- 8408070205 Proposed corrections to transcript of hearings on Limerick Ecology Action DES contentions & City of Philadelphia Contentions 13,14 & 15 Certificate of Svc encl \* Hearing Branch 2 84/08/06 Atomic Safety and Licensing Board Panel 13pp 25772 015 24X Fiche 50-352,84/08/06,8408090197
- 8408090229 Forwards dated & signed copy of Page 11 of proposed corrections to transcript of hearings on Limerick Ecology Action DES contentions & City of Philadelphia Contentions 13,14 & 15
  VOGLER, B H Hearing Brench 2 DSB 867 84/08/07 BRENNER, L. MORRIS, P A , COLE, R F Atomic Safety and Licensing Board Panel 2pp 25971 167 24X Fiche 50-352,84/08/07.8408090229

- --8408090236 Executed Page 11 of corrections to transcript of hearings on Limerick Ecology Action DES contentions & City of Philadelphia Contentions 13, 14 & 15 VOGLER, B H , HODODON, A P Hearing Branch 2 84/08/06 ip 25971 169 24% Fiche 50-352,84/08/07,8408090229
- B40B240254 Proposed corrections to transcript of evidentiary hearings on NEPA severe accident contentions Certificate of Svc encl WETTERHANN, M J. NICHOLS, N N Philadelphia Electric Co WETTERHANN, M J. Conner & Metterhahn DSE 268 94/08/21 5pp 26222 350 24X Fiche 50-352,84/08/21,8408240254
- U Congressional/Executive Correspondence
- 840B170094 Responds to 840712 ltr re 840502 Pottstown Mercury article & related petition Low level normal operation releases expected to be well within recognized safety limits Excerpts from DES enci
  DIRCKS.W J Office of the Executive Director for Operations 84/08/08 WALKER.R B House of Rep ip 26135 322 24X
  Fiche 50-352.84/08/08.8408170094
- 840B20B449 Responds to 840712 request for consideration of constituent H Mayerson 840407 ltr w/840502 Pottstown Mercury article & encl petition Low level normal operation releases expected to be well within recognized safety limits
  DIRCKS.H J Office of the Executive Director for Operations
  84/08/08 WALKER.R S House of Rep 5pp 26182 313 24X
  Fiche 50-352.84/08/08.8408200449
- ---8408200454 Forwards constituent H Mayerson 840607 ltr w/840502
  Pottstown Mercury article, "Limerick to Release Very Small
  Amounts of Radioactivity" & petition & requests
  investigation of statements
  WALKER, R S House of Rep 84/07/12 KAMMERER, C Office of
  Congressional Affairs 6pp 26182 332 24X Fiche 50-352,
  RA/OR/OR, RA/ORDODA48
- DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

  A Application/construction stage documents & correspondence
- 8408010212 Notification of time change for 840731 meeting w/util in Bethesda: MD to discuss riverborne missiles during PHH HAGNER.D H Licensing Branch 2 84/07/17 SCHWENCER.A Licensing Branch 2 3pp 25872 360 24X Fiche 50-354.84/07/17.8408010212
- 8408010227 Requests add1 info needed to complete FSAR review,including info re fire protection for solid waste product in storage area & justification for departure from/Reg Guide 1 32 Response should be provided by 840813 SCHWENCER,A Licensing Branch 3 84/07/24 MITTL.R L Public Service Electric & Gas Co of New Jersey 3pp 25873 277 24X Fiche 50-334,84/07/24.8408010227
- 84080B0344 Forwards nonproprietary "Use of Code Case N-192 " & proprietary repts, including "Documentation of Compliance of MBC P/N 73989" " & "Hose Assembly " qualification test procedures, per Reg Guide 1 84 Proprietary repts withheld MITTLIR L Public Service Electric & Gas Co of New Jersey 84/07/30 SCHMENCERIA Licensing Branch 2 10pp 23763.276 24X Fiche 50-354,84/07/30.8408080344
- --8408080345 Nonproprietary "Use of Code Case N-192 (Compliance H/Add1 Requirements of Reg Guide 1 84) " \* Public Bervice Electric & Gas Co of New Jersey 84/06/30 3pp 25963,284 24X Fiche 50-354,84/07/30.8408080344
- 8408130201 Provides procedures for developing plant-specific Tech Specs 8GHWENCER.A Licensing Branch 2 84/08/01 MITTL.R L Public Service Electric & Gas Co of New Jersey 2pp 24058 359 24X Fiche 50-354.84/08/01.8408130201
- 8408060279 Forwards responses to QA Branch open items discussed at B40718 QA meeting Nods to FBAR.Sections i 8 % 17 2, Table 3 2-1 % 260 series question/responses will be incorporated into FBAR.Amend 8 MITTLIR L Public Bervice Electric & Oas Co of New Jersey 84/08/03 SCHMENCER.A Licensing Branch 2 170pp 25926'003 24% Fiche 50-354.84/08/03,8408060279
- 8408070110 Generic Ltr 84-17 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of Buppl 1 to NUREO-0933; "Prioritization of Generic Safety Issues" Svc list encl EISENHUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26127 23B 24X Fiche 50-000,84/08/06,8408070110

- B408130170 Summary of B40718 meeting w/util in Bethesda,MD re QA program List of attendess, agenda & licensee responses to outstanding QA issues enci WAGNER,D H Licensing Branch 2 B4/08/07 Licensing Branch 53pp 26104 139 24X Fiche 50-354.84/08/07.8408150170 Licensing Branch 2
- 8408160336 Forwards FSAR commitment status through June & Jvl 1984 & responses to NRC request for addl info re FSAR Amend 7 MITTLER L Public Service Electric & Gas Co of New Jersey 84/08/13 SCHWENCER.A Licensing Branch 2 51pp 26090 283 24x Firhe 50-354,84/08/13,8408160336
- 8408200463 Summary of 840626-28 meetings w/wtil & Bechtel in San Francisco.CA re Instrumentation & Control Sys Branch open items not resolved since Jan 1984 meeting Summary of Di review status encl D Licensing Branch 2 84/08/13 Licensing Branch 2 26182 014 24% Fiche 50-354.84/08/13.8408200463 WAGNER, D
- 8408210442 Forwards Pages 19 & 41 omitted from master listing of saismic & dynamic quelification summary & status of safety-related equipment submitted w/840705 1tr Meeting requested MITTL.R L Public Service Electric & Gas Co of New Jersey 84/08/13 SCHWENCER.A Licensing Branch 2 4pp 26181 258 24x Fiche 50-354.84/08/13, 8408210442
- B40B170337 Forwards mods to FSAR Chapter 13 & Section 1 10 discussed at 840723-25 meetings Mods will be included in future FSAR amend MITTL.R L Public Service Electric & Oas Co of New Jersey B4/08/15 SCHWENCER,A Licensing Branch 2 115pp 26114 115 24X Fiche: 50-354, 84/08/15, 8408170337
- 3408200275 Generic Ltr 84-20 to all licenses of operating reactors & applicants for QLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list enc; EISENNUT.D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 50-000,84/08/20,8408200275
- 408230332 Forwards Amend 7 to FSAR (filed in PDR Category K) & Amend 4 to environ rept OL stage (filed in PDR Category C) MITTL-R L Public Service Electric & Gas Co of New Jersey 84/08/20 SCHWENCERA Licensing Branch 2 3pp 26323 298 24X Fiche. 50-354, 84/08/20, 8408230352
- 408310276 Notification of Significant Licensee Meeting 84-76 on 841022 w/util at site to discuss status of const & preoperational testing (Module 303018)
  KELLY.E Division of Project & Resident Programs 84/08/21
  Division of Project & Resident Programs 2pp 26351 335 24X
  Fiche 50-354,84/08/21,8408310276
- 108290098 Forwards Rev O to "Environ Qualification Summary Rept." per FBAR Question 270 2 MITTL.R L Public Service Electric & Qas Co of New Jersey 84/08/24 SCHMENGER.A Licensing Branch 2 2pp 24271 307 24X Fichs 50-354.84/08/24.8408290098
- 8408290102 Rev O to "Environ Qualification Summary Rept "

  \* Public Service Electric & Oas Co of New Jersey 84/08/02
  501pp 26291 309 24% Fiche 90-394.84/08/24.8408290098
- 08290513 Notification of 840906 & 07 meetings w/util in Bethesda,MD to discuss Power Sqs Branch mechanical issues WARNER,D H Licensing Branch 2 84/08/24 SCHWENCER,A Licensing Branch 2 3pp 26299 335 24% Fiche 50-394.84/08/24.8408290513
- OB300101 Notification of 840830 meeting w/util in Bethesda.MD to discuss gestechnical issues 4AQNER.D H Licensing Branch 2 84/08/24 SCHNENCER.A Licens Branch 2 3pp 26327 360 24X Fiche 50-354.84/08/24.8408300101
- 18300153 Forwards correction to FSAR Figure 13 1-9 re organization & vev to FSAR Page 1 10-21 re TMI Item 1 C 6. resulting from feanese Qualifications Branch 840723, 24 & 25 meetings HITTL.R L Public Service Electric & Gas Co of New Jersey 14/08/24 SCHMENCER A Licensing Branch 2 1340p 26304 123 24) iche 50-354.84/08/24.84/8300153 26304 123 24X
- Utility Environmental Report (ER), amends & correspondence
- 8230352 Forwards Amend 4 to environ rept QL stage filed in PDR Category C)
  IITL.R L Public Service Electric & Gas Co of New Jersey
  4/08/20 SCHMENCER.A Licensing Branch 2 3pp 26325 298 24X
  iche 50-354,84/08/20,8408230352

- --B408230365 Amend 4 to environ rept OL stage (filed in PDR Category c) \* Public Service Electric & Gas Co of New Jersey 84 65pp 26325 301 24% Fiche 50-354,84/08/20,8408230352 84/08/31
- B408280448 Forwards "Environ Qualification Summary Rept " Related correspondence CONNER.T B Conner & Wetterhahn CONNER.T B Public Service Electric & Gas Co of New Jersey DSB 363 84/08/22 MILLER.M E , MORRIS.P A , SCHINK, D R Atomic Safety and Liconsing Board Panel 143pp 26281 123 24X Fiche 50-354.84/08/22:8406280448
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- B40B060070 Requests 60-day extension to allow public advocate to review & comment on DES Extension necessary due to delay in assigning new counsel REMISS C New Jersey, State of 84/07/31 SCHWENCER, A Licensing Branch 2 App 25922 007 24% Fiche 50-354,84/07/31,8408060070
- 9408080019 Responds to S Remis 840730 request for 60-day extension of deadline for comments on DES S Remis has not shown basis or identified particular matter of concern to warrant extension extension CONNER.T B Conner & Wetterhahn 94/08/06 SCHWENCER,A Division of Licensing 1p 25970 308 24X Fiche 50-354.84/08/06,8408/90019
- 8408160486 Comments on DES Operation of facility will have no major impact upon agriculture in area BRANCO.J C Agriculture. Dept of 84/08/08 SCHMENCER.A Licensing Branch 2 ip 26107 311 24X Fichs 50-354,84/08/08,8408160486
- B40B160454 Comments on DES re benthic & fish populations, endangered & threatened species, aquatic, water, terrestrial & aquatic resources & exposure pathways HIGOINS, B E Commerce, Dept of, Natl Queanographic & Atmospheric Administration B4/0B/10 WAGNER, D H Office of Nuclear Reactor Regulation, Director 2pp 26107 278 24X Fiche 50-354, 84/08/10, administration B4/0B/10 440
- 8408200386 Forwards DES (NUREG-1074).per 840810 telcon w/D Wagner W/o enci SCHWENCER, A Licensing Branch 2 84/08/10 ALS, E Environmental Protection Agency 3pp 26141 217 24x Fiche 50-354, 84/08/10, 8408200386
- 8408210205 Requests 30-day review period be established for DEB soon to be released in entirety due to printing errors in original documents Review period of 30 days believed appropriate in view of familiarity w/original WALKA,R M Environmental Protection Agency 84/08/14 SCHWENCER,A Licensing Branch 2 ip 26184 236 24% Fiche 50-354,84/08/14.
- 8408210326 Requests 30 days from date of receipt to review & comment on
- 8408220432 Denies 840731 request for 60-day extension of DES comment period State of NJ desire to obtain consultants for DES review not sufficient justification SCHHENCER.A Licensing Branch 2 84/08/14 REMIS,S C New Jørse
- 8408240165 Offers no comment on DES re transportation aspects
  KESSLER.J J. LARIVIESE.P Transportation. Dept of Federal Highway
  Administration 84/08/14 Division of Licensing 1p 26236 317 24X Fiche 50-354,84/08/14,8408240165
- 8408210213 Recommends that groundwater monitoring during plant operation be addressed more thoroughly.per review of DES transmitted on 840629 Statement should indicate which aquifers monitored at wells listed BLANCHARD.B Interior, Dept of 84/08/15 SCHWENCER, A Lice Branch 2 1p 26184 012 24X Fiche 50-354,84/08/15,8408210213

- 8408270005 Forwards comments on DES W/o encl MODD, J M Commerce, Dept of Natl Decanographic & Atmospheric Administration 84/08/15 WAGNER, D H Office of Nuclear Reactor Regulation, Director 1p 26291 243 24% Fiche 50-354,84/08/15. 8408270005
- 8408230083 Confirms 840817 telcon informing that Bournia would grant Dept of Public Advocate 2-day extension for filing comments on DES Comments will be submitted by 840822 REMIS,S C New Jersey, State of 84708/17 SCHWENCER A Licens Branch 2 ip 26209 039 24X Fiche 50-354,84/08/17,8408230083 L. I Censina
- --8408230090 Requests 2-day extension for response to DES.based on continuing effort to complete review & provide appropriate comments
  REMIS.S.C. New Jersey. State of 84/08/16 SCHWINCER, A
  Licensing Branch 2 1p 26209 040 24% Fiche 50-354, 84.
  8408230083 24X Fiche 50-354,84/08/17,
- 8408240293 Comments on DES (NUREG-1074) Water treatment intake sys, cooling water sys, power transmission sys, groundwater, water use, terrestrial resources, aquatic resources & historical use, terrestrial resources, aquatic resources & mistorical & archaeological sites discussed MITTL.R L Public Service Electric & Qas Co of New Jersey 84/08/17 BCHWENCER.A Licensing Branch 2 8pp 26236 271 24X Fiche 50-354.84/08/17,8408240293
- 8408270136 Comments on DES DES fails to evaluate cumulative risks & overall environ impacts of Hope Creek & Salem Nuclear Generating Stations Certificate of Svc encl Related correspondence RODRIOUEZ, J H . REMIS, S . SHAPIRO, R E New Jersey, State of 84/08/21 SCHMENCER, A Licensing Branch 2 App 26257 284 24X Fithe 50-354,89/08/21,8408270136
- B408300304 Ack receipt of DES (NUREG-1074) Future submissions should be sent to Commissioner.State of NJ.Dept of Environ Protection SILVER, N S New Jersey. State of 84/08/24 SCHWENCER.A Licensing Branch 2 1p 26306 359 24X Fiche 50-354,84/08/24. 8408300304.
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8408060204 Notification of rescheduled 840802 meeting w/util in Bethesda, MD to discuss draft SER items to seismology
  WAGNER, D H Licensing Branch 2 84/07/09 SCHWENCER, A Licens
  Branch 2 3pp 25936 198 24X Fiche 50-354,84/07/09,8408060204
- 8408010124 Summary of 840531 meeting w/util. Bechtel, MES, Inc. Dames & Moore & AD Little, Inc. in Bethesda. MD re riverborne missiles identified as open item in Section 3 5 1 4 of draft SER MAGNER, D H Licensing Branch 2 302pp 25873 317 24X Fiche 50-354.84/07/18 8408010126
- 8408010124 Summary of 840713 meeting w/util.Bechtel & GE in Bethesda,MD re draft SER open items identified by Core Performance Branch List of attendees oncl WAONER.D H Liconsing Branch 2 84/07/24 Licensing Branch 2 7pp 25897 134 24% Fiche 50-354.84/07/24,8408010124
- --8312020277 Forwards proprietary description of fuel performance verification program Description withheld (ref 10CFR2 770) CHARMLEY, J & General Electric Co 83/11/23 BERLINGER, C H Power Systems Branch 5pp 25877 141 24X Fiche 50-354.84/0//24. 8408010124
- --8402020372 Responds to 831123 ltr proposing substitution of generic vendor surveillance on lead test assemblies for routine licensee surveillance Proposal considered inadequate due to possibility of short- & long-term fuel damage RUBENSTEINL S Assistant Director for Care & Plant Systems 84/01/18 GRIDLEY.R L General Clactric Co 3pp 29897 146 24X Fiche 30-354.84/07/24.8408010124
- 8408010219 Forwards resolution to draft SER open items in Sections 2 4 5.3 4 1 % 3 5 1 4 re floating missiles, for review % approval Repts supporting resolution encl MITTL, R L Public Service Electric & Gas Co of New Jersey 84/07/27 SCHMENGER, A Licensing Branch 2 4pp 25855 075 24% Fiche 50-354.84/07/27,8408010219
- -8408010224 "Analysis of Likelihood of Waterborne Traffic on Delaware River Impacting Hope Creek Generating Station in Severe Storms " Btorms " \* Arthur D Little, Inc C-50918 84/07/31 43pp 25855 079 24X Fichs 50-354,84/07/27,8408010219
- --8408010231 "Hose Creek Generating Station Extreme Event Site Flooding Meteorology "

  BMITH.M E : CASTELLI, F P Meteorological Evaluation Services, Inc 84/07/06 23pp 25855 122 24% Fiche 50-354.84/07/27. 8408010219

- --8408010234 "Storm Surge Calculations, Hope Creek Generating Station. Louer Alloways Creek.NJ" \* Public Service Electric & Gas Co of New Jersey 84/07/27 14pp 23835 145 24X Fichs 50-334, 84/07/27, 8408010219
- 8408080290 Forwards status update of open items identified in Graft SER. Section 1 7. current list of items not yet addressed & responses to other open items
  HITTLIR L Public Service Electric & Gas Co of New Jersey
  84/07/27 SCHMENCER.A Licensing Branch 2 Hipp 25765 329
  Fiche 50-354,84/07/27,8408080290 25965 329 24
- 8408080149 Summary of 840428 meeting w/util.Bechtel & Dames & Moore in Bethesda:MD re hydrology open items addressed in draft SER MAONER,D Licensing Branch 2 84/07/30 Licensing Branch 2 16pp 25979 027 24X Fiche 50-354.84/07/30.8468080149
- 8408030069 Forwards status of open issues identified in draft SER Section i 7.1ist of draft SER sections not provided & resolution of open items & comments received during Power Sys Branch 840417-18 meeting MITTLIR L Public Service Electric & Oas Co of New Jersey 84/08/01 SCHMENCER.A Licensing Branch 2. 504pp 25707 246 Fiche 50-354,84/08/01.8408030069
- 8408080140 Summary of 840724 meeting w/util, Bechtel, GE, Intl Energy Assoc & Conner & Wetterhabn in Bethesda:MD re draft SER open items identified by Matls Engineering Branch HAGNER:D Licensing Branch 2 84/08/01 Licensing Branch 2 22pp 25979 083 24% Fiche 50-354.84/08/01.8408080140
- 8408130050 Summary of 840711 meeting w/util & Bechtel in Bethesda.MD redraft SER open items identified by Reactor Sys Branch HAGNER,D Licensing Branch 2 84/08/01 Licensing Branch 2 12pp 26038 317 24% Fichs 50-334.84/08/01,8408130050
- 8408060176 Forwards status of open items identified in Section 1 7 of draft SER & current list identifying draft SER sections not grant ben a torrise the service service and service and service service and service services of the Jersey BAY/08/03 SCHMENCER. A Licensing Branch 2 297pp 25927 331 24X Fiche 50-354,84/08/03,8408060176
- 8408090452 Forwards draft SER Sections 17 1-17 5 re GA Updated version of util 840718 ltr re draft SER outstanding sections encl SCHMENGER.A Licensing Branch 2 84/09/03 MITTLER L Public Service Flectric & Oas Co. of New Jersey 11pp 25983 198 24 Fiche 50-334.84/08/03.8408070452
- 8408150173 Summary of 840712 meeting w/util & Hechtel in Bethesda.MD re Radiological Assessment Branch draft SER open items HAGNER,D H Licensing Branch 2 84/08/07 Licensing Branch 2 21pp 26104 118 24X Fiche 30-354.84/08/07,8408150173
- 8408160170 Forwards listed draft SER sections resulting from review of OL application, per 840305 ltm Remaining open items listed SCHWENCER, A Licensing Branch 2 84/08/07 MITTL/R L Public Service Electric & Gas Co of New Jersey 48pp 26126 277 24X Fichs 50-354,84/08/07,8408140170
- 840B160487 Summary of 840717 meeting w/util & GE in Bethesda, MD redraft SER open items identsfied by Matls Engineering Branch in Sections 5 3 i 2.5 3 i 3 & 5 3 4 tist of attendees encl MAGNER, D H Licensing Branch 2 84/08/07 Licensing Branch 2 25pp 2610B 302 24X Fiche 50~354,84/08/07,840B160487
- 8408140336 Forwards status rept of draft SER Bection 1 7 open items, draft BER spections not yet provided, draft SER open items & resolutions to items ltems identified as complete considered closed Description of unresolved issues requested MITTL-R L Public Bervice Electric & Gas Co. of New Jersey 84/08/10 SCHMENCER.A Licensing Branch 2 182pp 26042 117 24X Fiche 50-354.84/08/10,8408140336
- 8408170403 Summary of 840801 meeting w/util, Bechtel, NUTECH & Impell in Bethesda, MD re Structural & Geotechnical Engineering Branch structural audit open items identified in draft SER List of attendees & draft responses encl WAGNER.D H Licensing Branch 2 84/08/10 Licensing Branch 2 140pp 26134-013 24X Fiche 50-354,84/08/10,8408170403
- 840BL60348 Forwards status of open items in Section 1.7 of draft SER, list of draft SER sections not provided, resolutions of open items & FSAR question responses HITTLER L Public Service Electric & Das Co of New Jersey B4/08/13 SCHMENCER, A Licensing Branch 2 150pp 260F0 001 2 Fiche 50-354,84/08/13,8408160348

- B40B170336 Forwards GE Design Memos 170-107 & 170-107 & Bechtel Stress Rept Calculation SR10B55-SS27 re stiff pipe clamps described in 1E Info Notice 83-80 Submittal addresses draft SER Open Item 96 MITTLIR L. Public Service Electric & Gas Co. of New Jersey 84/08/14 SCHWENCER.A Licensing Dranch 2 2pp 26114 062 24X Fiche 50-354.84/08/14.8408170336
- --840B170339 "Clamp Induced Stress on Hope Creek Recirculation Piping "FARRELL,C A , ZALIZNYAK,M , THOMPSON,J L General Electric Co 170-107 84/07/27 18pp 26114 064 24X Fiche 50-354.84/08/14, 840B170334
- --840B17034E "Clamp Induced Stress on Hope Creek Main Steam Piping Lines C & D " ZALIZNYAK, H A , FARRELL, C A , THOMPSON, J L General Electric Co 170-109 84/07/27 22pp 26114 082 24X Fiche 50-354,84/08/14, 8408170336
- --840B170343 "Btudy Calculation for Stiff Pipe Clamp Calculation BRI0835-8327 " HU.C K., CHOI,K., KHLAFALLAH.M Z Bechtel Corp 84/07/31 £Opp 26114 104 24X Fiche 50-354.84/08/14.8408170334
- 8408170103 Forwards resolutions to draft SER open items & responses to FBAR questions\_List identifying draft SER sections not yet provided encl
  HITTL.R L Public Service Electric & Gas Co of New Jersey
  84/08/15 SCHMENCER.A Licensing Branch 2 578pp 26119 130 24X
  Fiche 50-354.84/08/15.8408170103
- 8408240273 Forwards "Basis for Cable Sys Design Power Generating Stations" Rept provides basis for IB-inch vertical & 12-inch horizontal cable tray separation criteria, in response to Question 430 51 & draft SER Open Item 245 MITTLER L Public Service Electric & Gas Co of New Jersey 84708/15 SCHMENCER. A Licensing Branch 2 2pp 26225 146 24X Fiche 50-354.84708/15.8408240273
- --8408240288 "Basis for Cable Sys Design, Power Generating Stations "

  \* Public Service Electric & Gas Co of New Jersey 71/07/16.

  80pp. 26225 148 24X Fiche 50-354,84/08/15.8408240273
- B408280201 Forwards status of open items identified in draft SER Section 1 7.1ist of sections not provided resolutions to open items & FSAR responses to questions W/64 oversize drawings Aperture cards a variable in PDR MITTL.R L Public Service Electric & Gas Co of New Jersey 84/08/20 BCHMENCER.A Licensing Branch 2 412pp 26270 264 24X Fiche 50-0354.84/08/20.04408280201
- 8408290134 Forwards "Cold Shutdown/Power flus Failure Analysis Rept."
  "High Energy Line Break/Control Sys Failure Analysis."
  "Common Power/Control Sys Failures Evaluation Rept" &
  "Common Sensor Failure ," per draft SER open items
  MITTL.R L Public Service Electric & Oas Co of New Jersey
  84/08/24 SCHMENGER.A Licensing Branch 2 57pp 26290 001 24X
  Fiche, 50-354,84/08/24,8408290134
- --8408270138 "Cold Shutdown/Power Bus Failure Analysis Rept "
  # Public Service Electric & Gas Co of New Jersey 84/08/31
  24pp 26290 058 24X Fiche 50-354,84/08/24,8408290134
- -8408290144 "High Energy Line Break/Control Sys Failure Analysis "
  \* Public Service Electric & Gas Co of New Jersey 84/08/31
  100pp 26290 082 24% Fiche 50-354,84/08/24,8408290134
- B40B290149 "Common Power/Control Sys Failures Evaluation Rept" \* Public Service Electric & Cos Co of New Dersey B4/08/31 53pp 26290 194 24X Fithe 50-354,84/08/24,8408290134
- 408270160 "Common Sensor Failure Evaluation Rept "

  # Public Service Electric & Gas Co of New Jersey 84/08/31
  60pp. 26270 247 24X Fiche 50-354,84/08/24,8408290134
- lecurity, medical, emergency & fire protection plans
- 1100065 Forwards revised emergency plan, incorporating resolution of C comments from 840621 emergency preparedness meeting fidavit enci
  TTL.R L Public Service Electric & Oas Co of New Jersey.
  /07/20 BCHWENCER.A Licensing Branch 2 2pp 25989 053 24X che 50-334.84/07/20.8408100065
- OBIOGO67 Revised "Hope Creek Generating Station Emergency Plan." # Public Service Electric & Gas Co of New Jersey 84/07/20 OBpp 25989,055 24X Fiche 50-354,84/07/20.8408100065

- B40B010227 Requests addl info needed to complete FSAR review including info re fire protection for solid waste product in storage area & justification for departure from/Reg Guide I 52 Response should be provided by B40B13 SCHWENCER. A Licensing Branch 3 84/07/24 MITTL.R L Public Service Electric & Gas Co of New Jersey 3pp 25B73 277 24X Fiche 50-354,84/07/24.8408010227
- B40B070147 Advises that 840921 Rev 2 to security plan re proposed vital area identification program does not satisfy criteria contained in encl Review Guidelines 17 Amended plan should be submitted by 840810 SCHWENCER. A Licensing Branch 2 84/08/01 MITTL. R L Public Service Electric & Oas Co of New Jersey 14pp 25957 120 24X Fiche 50~334,84/08/01,8408070147
- 8408200151 Notification of 840822 meeting w/util in Silver Spring.MD to discuss vital areas submittal & safeguards matl Meeting clused to public MAGNER.D H Licensing Branch 2 84/08/10 SCHWENCER.A Licensing Branch 2 4pp 26142 325 24X Fiche 50-354.84/08/10.8408200151
- 8408210408 Informs that FEMA does not intend to conduct full-scale evaluation of Hope Creek 1985 exercise Since Salem Unit 1 dL issued prior to 820713, full participation in 1985 not required by NRC or FEMA rules
  KRIMM.R W Federal Emergency Management Agency 84/08/13
  JORDAN.E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 2pp 26177 256 24X Fiche 50-000, 84/08/13, 8408210408
- 8408170052 Forwards "Control Room Design Review Summary Rept Hope Creek Generating Station," in response to Generic Ltr 82-33, Item 5 (NUREG-0737, Suppl 1) Meeting requested MITIL.R L Public Service Electric & Gas Co of New Jersey 84/08/14 SCHMENCER.A Licensing Branch 2 2pp 26118 133 24X Fiche 50-354,84/08/14.8408170052
- --8408170056 "Control Room Design Review Summary Rept Hope Creek Denerating Station" \* Essex Corp 84/08/04 210pp 26118 135 24X Fiche 50-334,84/08/14,8408170052
- 8408270002 Updates status of safety parameter display sys.per 840402 commitment re generic Ltr 82-33 Plant-specific displays & analysis will be available for NRC review in Dec 1984 MITTL.R L Public Bervice Electric & Gas Co of New Jersey 84/08/24 SCHMENCER.A Licensing Branch 2 2pp 26338 164 24X Fiche 50-334.84/08/24.8408290002

# G Adjudicatory correspondence

- 8408010246 Motion to compet designation of witnesses & availability for depositions &/or to dismiss proceeding ASLB should set date for Public Advocate to furnish info re expert witnesses Certificate of Svc encl Related correspondence CONNER.T B Public Service Electric & Gas Co of New Jersey CDNNER.T B Conner & Metturhahn DSB 671 84/07/30 Atomic Safety and Licensing Board Panel 20pp 25855 347 24X Fiche 30-354.84/07/30.8408010246
- 8408090255 Motion for extension of time to respond to applicant motion to compel designation of witnesses & availability for depositions b/or dismiss proceeding Certificate of Svc encl Related correspondence
  REMIS-S C New Jersey, State of DSB 857 84/08/03 Atomic Safety and Licensing Board Panel 5pp 25972 280 24X
  Fiche 50-354.84/08/03.8408090255
- B4080803B9 Answer opposing Public Advocate motion for extension of time to respond to applicant 840730 motion to compel Public Advocate to designate expert witnesses & make available for depositions H/Certificate of Svc Related correspondence RADER, R M Public Service Electric & Gas Co. of New Jersey RADER, R M Commer & Metterhahn DSD 836 84/08/07 Atomic Bafety and Licensing Board Panel 132pp 25974 103 24X Fiche 50-394,84/08/07,84080803B9
- 8408140543 Confirms 840807 telcon re Superior Court of NJ opinion authorizing Public Advocate of NJ to Intervene in OL proceeding Related correspondence REMIS.6 C New Jersey. State of DSB 023 84/08/07 MILLER.M E Atomic Safety and Licensing Board Panel 9pp 26061 227 24X Fiche 50-334.84/08/07.8408140543
- 8408130102 Response to intervenor 840803 motion for extension of time to respond to applicant 840730 motion to compel designation of dithesses Extension of 30 days sufficient Certificate of 8vc ancl DEWEY.L 5 Hearing Branch 3 DSB 707 84/08/08 Atomic Safety and Licensing Board Panel 4pp 26007 327 24X Fiche 30-354:84/08/08.8408130102

- 8408140024 Order denying Public Advocate of NJ 840730 request for 60-day extension of time to respond to applicant 840730 mution Public Advocate of NJ witnesses must be identified by 840820 Served on 840813 MILLER.M E Atomic Safety and Licensing Board Panel DSD 951 84/08/10 New Jessey, State of Spp 24044 191 24X Fiche 50-334.84/08/10.8408140024
- 8408280447 Response to ASLB 840810 order establishing 840820 as date to (dentify withesses & to make withesses available for depositions within 2 wks Addl time requested Certificate of 8vc entl SHAPIRO, R E , REMIS.S C New Jersey. State of DSB 359 84/08/20 4pp 26280 330 24% Fiche 50-354.84/08/20.8408280447
- B408270014 Petition for add1 time to make expert witnesses available for depositions Scheduling of depositions in Oct requested Certificate of Gvc encl Related correspondence SHAPIRD.R E , REMIS.S C New Jersey, State of DSB 360 84/08/20 Atomic Safety and Licensing Board Panel 18pp 26271 217 24% Fiche 50-354,84/08/20,8408270014
- 8408280448 Forwards "Environ Qualification Summary Rept " Related correspondence CONNER, T B Public Service CONNER, T B Conner & Wetterhahn CONNER, T B Public Service Electric & Gas Co of New Jersey DSB 363 84/08/22 MILLER, M E , MORRIS, P A , SCHINK, D R Atomic Safety and Licensing Board Panel 143pp 26281 123 24% Fiche 50-354.84/08/22,8408280448
- 8408280447 Notice of appearance in proceeding SHAPIRO,R E New Jersey, State of D88 355 84/08/23 ip 26280 346 24% Fiche 50-354,84/08/23,8408280449
- B408280223 Mation to dishiss proceeding as result of default by public advocate in not complying w/ASLB 840810 order to identify witnesses by 840820 & answer opposing Intervenor motion for add1 delay Certificate of Svc encl RADER, R M Public Service Electric & Qas Co of New Jersey RADER, R M Conner & Wetterhahn D8B 323 84/08/24 Atomic Safety and Licensing Board Panel 17pp 26274 347 24X Fiche 50-354.84/08/24.8408280223

## H General correspondence

- 840B0702B4 Submits change of address & telephone numbers for documentation of accility UTYO.H W Delaware, State of 84/07/31 WAGNER.D H Division of Licensing Ip 25748 109 24X Fiche 50-354.84/07/31.84080702B4
- 840B100003 Requests that author & FM Parkowski be removed from facility svc list & RJ Touhey be added VASUKI.N C Delaware Solid Waste Authority 84/08/08 WAGNER.D Licensing Branch 2 ip 25987 307 24% Fiche 50-354,84/08/08,840B100003
- 8408280393 Requests deletion of deputy atty general, State of NJ, from mailing list to eliminate redundant copies KIMMELMAN, I , ENGEL, R F New Jersey. State of 84/08/20 NRC No Detailed Affiliation Given 1 p 26282 232 24X Fiche 50-354.84/08/20.8408280353
- K Utility Final Safety Analysis Report (FBAR) & amends
- 8408230352 Forwards Amend 7 to FBAR (filed in PDR Category K) MITTL.R t. Public Service Electric & Gas Co of New Jersey 84/08/20 BCHMENCER.A Licensing Branch 2 3pp 26325 298 24X Fiche 50-354,84/08/20.8408230352
- --B408230371 Amend 7 to FSAR for Hope Creek Cenerating Station (Filad in PDR Category K) H/167 oversize drawings Aperture cards available in PDR \* Public Service Electric & Gas Co of New Jersey 84/08/20 357pp 26326 006 24X Fiche 50-334,84/08/20,8408230332
- 8408310198 Forwards affidavit certifying distribution of Amend 7 to FSAR for Hope Creek Generating Station & Amend 4 to environ rept OL stage, per 10CFRR 101 Environ rept OL distribution | 1st & ack receipt forms encl MITTLIR L. Public Service Electric & Oas Co of New Jersey 84/09/28 Office of Nuclear Reactor Regulation, Director SCHMENCER, A Licensing Branch 2 14pp 26318 272 24X Fichs 50-354,84/08/28.8408310178
- Q Inspection reports, IE Bulletins & correspondence
- B40B150650 Forwards IE Insp Rept 50-354/84-08 on B40605-08 No violations noted MARTIN, T. Division of Engineering & Technical Programs, B4/07/24 MARTIN, T T Public Service Electric & Gas Co of New Jersey 2pp. 26077 092 24X Fiche 50-354,84/07/24,8408150650

- --8408:50.653 IE Insp Rept 50-354/84-08 on 840605-08 No violations noted Major areas inspected power block heave/settlement measurement program records & review of corrective actions associated w/previously identified const deficiency VARELAAAA, DURR.JP Region 1. Office of Director 84/07/06 5pp 26079 094 24X Fichs 50-394.84/07/24,8408150650
- 8407250227 IE Info Notice 84-57. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24% Fiche 50-000,84/07/27,8407250229
- B40B200364 Forwards IE Insp Rept 50-334/84-05 on B40514-0624 & notice of violation STAROSTECKI, R Division of Project & Resident Programs B4/07/31 MARTIN, T J Public Service Electric & Oas Co of New Jersey 2pp 26140 001 24X Fiche 50-354, 84/07/31, 840B200364
- --8408200365 Notice of violation from inso on 840514-0624 \* Region i, Office of Director 84/07/31 2pp 26140 003 24X Ficha 50-354,84/07/31,8408200364
- --8408200366 IE Insp Rept 50-334/84-05 on 840314-0624 Noncompliance noted improper tie-wrapping of safety-related cable, unauthorized mod of torquing of anchor bolts for conduit support & improper installation of control room shims BATEMAN.W H. MCCABE,E C. Region I. Office of Director 11pp 26140 003 24X Fiche 50-354,84/07/31,8408200364
- 8408070323 Ack receipt of 840629 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-354/84-06 Corrective actions will be examined during future insp MARTIN.T T Division of Engineering & Technical Programs 84/08/01 MARTIN.T J Public Service Electric & Gas Co of New Jersey 4pp 25745 238 24X Fiche 50-354,84/08/01,8408070323
- --B408070326 Responds to NRC 840531 ltr re violations noted in IE Insp Rept 50-354/84-06 Corrective actions rear bracket attachments on pipe supports reinspected & GC engineers given add1 training in spec requirements MARTIN:T J Public Service Electric & Oas Co of New Jersey 84/06/29 MURLEY:T E Region 1: Office of Director 2pp 25945 242 24X Fiche 50-354:84/08/01:8408070323
- 8408200475 Forwards IE Insp Rept 50-354/84-09 on B40611-15 No viglations noted, MARTIN.T T Division of Engineering & Technical Programs 84/08/01 MARTIN,J T Public Service Electric & Gas Co of New Jersey App 26138-290 24X Fiche 50-354.84/08/01,8408200495
- --8408200504 IE Insp Rept 50-354/84-09 on 840611-15 No violations noted Hajor areas inspected previously identified (tems.electrical cables, termination, HVAC & related GA/GC activities FINKEL, A. CHEH, U. CHEUNGL. Region I. Office of Director 84/07/19 8pp 26138 294. 24X Fiche 30-354,84/08/01,8408200495
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830(03) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp. 26068 001 24X Fiche 50-000,84/08/06.8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067:158 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/08/08 Consolidated Edison Co of New York, Inc. 120pp 26127 118 24X Fiche 50-000,84/08/08,8408070120
- 8408280066 Responds to IE Bulletin 83-07 re fraudulent products from Ray Miller Inc Procedures for assuring quality of vendor-supplied items outlined MARTIN, T. J. Public Service Electric & Oas Co. of New Jersey 84/08/08 MURLEY, T. E. Region 1, Office of Director. Spp. 26261, 217 24X Fichs 50-334, 84/08/08, 8408R80066
- B40B2B00B9 Responds to B40312 IE Bulletin 84-02, "Failures of GE Tupe HFA Relays in Use in Class 1E Bafety Bys " Century series relays used Magnetic coil assemblies replaced w/Tefral coil specie MARTIN. T T Public Service Electric & Gas Co of New Jersey. B4/08/0B MURLEY. T E. Region 1. Office of Director. 3pp 26261.184 24X Fiche 50-334.84/08/0B.8408280089

- B408070376 IE Info Notice B4-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc
  - list encl GRACE.J.N Division of QA. Safeguards & Inspection Programs (Post 830103) 84/08/10 Cansolidated Edison Co. of New Yo 125pp 26130 001 24x Fiche 50-000, 84/08/10, 8408070376
- 8408100009 IE Info Notice 84-63. "Defective RHR Replacement Piping "
- Svc list encl
  JURDAN.E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000.84/08/13.8408100009
- 8408170336 Forwards GE Design Memos 170-107 & 170-109 & Bechtel Stress NOBITO 336 Forwards GE Design Memos 170-107 & 170-109 & Becker Berrys Rept Calculation SRIOB35-8827 re stiff pape clamps dascribed in IE Info Notice 83-80 Submittal addresses draft SER Open Itom 96 MITTL.R L Public Service Electric & Gas Co of New Jersey 84/08/14 SCHWENGER A Licensing Branch 2 2pp 26114 062 24X Fiche 50-354,84/08/14,8408170336
- --B408170339 "Clanp Induced Stress on Hope Creek Recorculation Piping "FARRELL,C A , ZALIZNYAK.M , THOMPSON.J & General Electric Co 170-107 84/07/27 18pp 26114 064 24x Fiche 50-354.84/08/14.8408170336
- --8408170342 "Clamp Induced Stress on Hope Creek Main Steam Piping Lines C & D " ZALIZNYAK.M A , FARRELLIC A , THOMPSON.J L General Electric Co 170-109 B4/07/27 22pp 26114 082 24X Fiche 50-354.84/08/14. 170-109 B4/07/27 B40B170336
- --8408170343 "Study Calculation for Stiff Pipe Clamp Calculation ER10855-5927 8H1-C K , CHOI, K , KHLAFALLAH, M Z Bechtel Corp 84/07/31 10pp 26114 104 24X Fiche 50-354,84/08/14,8408170336
- 8408100038 IE Info Notice 84-64, "BWR HPC1 Initiation Seal-In & Indication "Svc list encl
  JORDAN, E.L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/15 Consolidated Edison Co of New
  York, Inc 104pp 26198 093 24X Fiche S0-000,84/08/15,8408100038
- B40B100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Syc list and JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000.84/08/16.8408100021
- 8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consoli
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates "Svc list encl
  JQRDAN.E L Division of Emergency Preparadness & Engineering
  Response (Post 830103) B4/0B/17 Consolidated Edison Co of New
  York, Inc 122pp 26276 122 24X Fiche 50-000.84/08/17.8408140208
- 9408210142 IE Info Notice 84-66. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/08/21 Consolidated Edison Co of New York. Inc 115pp 26329 008 24X Fiche 50-000.84/08/21.8408210142
- I Reportable occurrences, LERs & related correspondence
- |408240332 Submits annotated requests for followup on potentially generic problem in encl Part 21 rept from Basler Electric re SCRs on nuclear exciters mounted w/too much pressure NORELIUS.C E Division of Project & Resident Programs 84/04/25 JORDAN.E L Director's Office, Office of Inspection and Enforcement ip 26225 303 24X Fiche 50-000.84/04/25.8408240332
- OB1000B5 Interim deficiency rept re cracked bosses on Colt Industries dissel generator lube oil pump discharge nozzies initially reported on 840425 Design for tapered thread adapter changed Next rept expected by 840807 Reportable per Part 21 MARTIN.T J. Public Bervice Electric & Oas Co. of New Jersey 84/07/18 MURLEY.T E. Region 1. Office of Director 2pp 25990 198 24X Fiche 50-354.84/07/18.8408100085
- D8100140 Final deficiency rept me economizing resistors supplied by Basler Electric on emergency diesel generator exciters [Initially reported on 840627 Corrective actions implemented by supplier & documented in Nonconformance Rept 4040 (ARTIN.T J Public Service Electric & Gas Co. of New Jersey 184007124 MURLEY.T E Region 1. Office of Director Spp 25788 267 24% Fiche 50-354.84/07/24.8408100140

- 8408100076 Interin deficiency rept re defective ITT Grinnell capstan springs in mechanical shock arrestors Initially reported on 831024 Springs replaced in 25 of 86 snubbers at Pacific Beientific Final rept will be submitted on 840831 MARTIN, T J Public Service Electric & Gas Co of New Jersey 84/07/25 MURELY.T E Region 1. Office of Director 2pp 25970 278 24X Fiche 50-354.84/07/25,8408100096
- 8408300342 Significant const deficiency rept re cracked bosses on NOADULAR SIGNIFICANT CONST DEFICIENCY PRICE TO TAKEN DISSES diesel generator lube dii pump discharge norzies Initially reported on 840425 Colt Industries rescheduled onsite insp of diesel generators Next rept expected by 840728 MARTIN.T J Public Service Electric & Gas Co of New Jørsey 84/08/07 MURLEY,T E Region 1, Office of Director 2pp 26308 340 24X Fiche 50-354.84/08/07,8408300342
- DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2 S Reportable occurrences, LERs & related correspondence
- 8408240332 Submits annotated requests for followup on potentially generic problem in encl Part 21 rept from Basler Electric re SCRs on nuclear exciters mounted withou much pressure NORELIUS, C E Division of Project & Resident Programs 84/04/25 JORDAN, E 4 Director's Office, Office of Inspection and Enforcement 1p 26225 303 24% Fiche 50-000,84/04/25,8408240332
- 8408100D85 Interim deficiency rept re cracked bosses on Colt Industries diesel generator lube oil pump discharge nozzles Initially reported on 840425 Dosign for tapered thread adapter changed Next rept expected by 840807 Reportable per Part 21 MARTIN.T J Public Service Electric & Gas Co of New Jersey 84/07/18 MVRLEY.T E Region 1. Office of Director 2pp 25990 198 24X Fiche 50-954.84/07/18,8408100085
- DOCKET 50-356 UNIV OF ILLINOIS RESEARCH REACTOR F Security, medical, emergency & fire protection plans
- 8408010302 Forwards IE Inap Repts 50-151/84-01 & 50-356/84-01 on 840619-22 No noncompliance noted NORELIUS:CE Region 3, Office of Director 84. Illinois, Univ of, Urbana, IL 2pp 25866 117 Fiche 50-151,84/07/19,8408010302 84/07/19 MILEY, G H
- control practices & emergency planning TAUBLING: TN Region 3, Office of Director 84/07/18 10pp 28866-117 24x Fiche 30-151,84/07/19.8408010302
- 8408030276 Certifies nuclear reactor committee formal approval of additions & changes to energency plan on 840723 Last sentence in Section 3 4 3 changed for clarity

  BECK, G.P., HOPKE, P.K., MILEY, G.H. Illinois. Univ of, Urbana, IL 84/07/24 THOMAS, C.O. Standardization & Special Projects Branch 1p 25917 258 24X Fiche 50-151,84/07/24,8408030276
- Q Inspection reports: IE Bulletins & correspondence
- 8408010302 Forwards JE Insp Repts 50-151/84-01 & 50-396/84-01 on 840619-22 No noncompliance noted NORELIUS, G E Region 3. Office of Director 84/07/19 MILEY, G H Illinois, Univ of, Urbana, IL 2pp 25866 117 24X Fiche 50-131
- --B408010308 IE Insp Repts 30-151/84-01 & 50-356/84-01 on 840619-22
  No noncompliance noted Major areas insected requalification training fuel handling & surveillance activities radiation control gractices & emergency planning
  TAUBLING. T N Region 3, Office of Director THOMAS, C C.
  HYBER, J E Los Alamos Scientific Laboratory 84/07/18 10pp
  25846 119 24X Fiche 50-151,84/07/19,8408010302
- V Operator Examinations
- 8408140426 Provides address for transmitting all operator licensing correspondence to Region III off.except info for examiners MALKER, R D Region 3. Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000. 84/08/10,8408140426

- DOCKET 50 358 WILLIAM H ZIMMER NUCLEAR STATION, UNIT L

  A Application/construction stage documents & correspondence
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933, 'Prioritization of Generic Safety Issues " Svc list enc! EISENHUT.D © Division of Licensing 84/08/06 Consolidated Edison Co of New York Inc 18pp 26129 238 24X Fichs 50-000.84/08/06.8408070110
- B40B2002/5 Generic Ltr 84-20 to all licensees of operating reactors & applicants for CLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list enc? EISENHUT.D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fich 50-000,84/08/20.8408200275

#### G Adjudicatory correspondence

- 8408070461 Transmittal of info re util 840320 motion for withdrawal of OL application Fuel removed from site, steam supply sys modified & CRD mechanisms removed Certificate of Svc encl WETTERHAHN, M J Cincinnati Oas & Electric Co WETTERHAHN, M J Conner & Notterhahn DSB 775 84/08/02 4pp 25940 296 24X Ficha 50-358,84/08/02,8408070461
- 8408080201 Ack receipt of 840802 info re motion for withdrawal of application in proceeding ASLB will act promptly on motion upon receipt of staff recommendations Served on 840807 FRYE.J H Atomic Safety and Licensing Board Panel D88 822 84/08/07 WETTERHAHN, M J Conner & Wetterhahn ip 25940 265 24X Fiche 50-358.84/08/07.8408080201
- 8408210366 Further answer in support of applicant 840320 motion for withdrawal of application Termination order conditioned an implementation of applicant 840601 restoration plan, recommended Insp summary encl
  TREBY.S A Hearing Branch 1 DSB 185 84/09/17 Atomic Saféty and Licensing Board Panel 11pp 26181 001 24X
  Fiche 50-358.84/08/17.8408210366
- --8408210374 Affidavit of OE LaRoche in support of NRC further answer to applicant 840320 motion for withdrawal of application Certificate of Svc ancl LAROCHE. 6 Environmental & Hydrologic Engineering Branch 84/08/14 App 26181 012 24X Fiche 50~358,84/08/17.8408210364
- B40B310104 Memorandum & order granting applicant B40320 motion to withdraw application for QL & to dismiss proceeding subj to implementation of util B40401 site restoration plan Berved on B40B30

  LINENBERGER, G., FRYE, J. H. Atomic Safety and Licensing Board Panel DBB 393 B4/0B/27 Cincinnati Gas & Electric Co Spp 24322 234 24X Fiche 50-338,84/08/27,8408310104

# H General correspondence

- 8403180145 Responds to 840314 ltr to Chairman Palladino which encl W & V Smelser concern re Marble Hill & Bailly cancellation, withdrawal of util application for Zimmer & denial of license for Byron facility DIRCKS,W J Office of the Executive Director for Operations 84/05/04 LUGAR.R & Senate 7pp 24524 325 24X Fiche 50-000,84/05/04,8405180145
- --8405180152 Requests response to encl W & V Smelser 840210 inquiry into NRC attitude toward utils Concerns include Marble Hill & Bailly cancellation, withdrawal of util application for Zimmer & dental of license for Byron facility LUGAR, R G Sonate 84/03/14 PALLADINO, N Commissioners 3pp 24524 331 24X Fiche 30-000,84/05/04,8405180145

### Q Inspection reports: IE Bulletins & correspondence

- 8407250229 IE Info Notice 84-37, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants "Svc list encl JORDAN, E L Division of Emergency Preparedhess & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,840/250229
- 8408230474 Forwards IE Insp Rept 50-358/84-05 on 840427-0716 No noncompliance noted WARNICK,R F Region 3, Office of Director 84/08/03 SGHOTT, J R Gincinnati Gas & Electric Co 2pp 26212 206 24X Fiche 50-358,84/08/03,8408230474

- --8408230480 IE Insp Rept 50-358/84-05 on 840427-0716 No noncompliance or deviations noted Major areas inspected verification of actions re-proposed withdrawal of application to transfer, packaging & shipment of irradiated fuels GRANT, V B. FQRNEY, W L. Region 3, Defice of Director 84/08/02 App. 26212 208 24X Fichs 50-358.84/08/03.8408230474
- 8408010333 IE Info Notice 84-59. "Beliberate Circumventing of Station Health Physics Procedures" Svc list encl JORDAN, E. L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26068 001 24% Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24% Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24% Fiche 50-000,84/08/09,8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list encl GRACE, J N Division of GA. Safeguards & Inspection Programs (Post 830103) 8408/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24% Fiche 50-000.84/08/10.8408070376
- 8408100009 IE Info Notice 84-63, "Defective RMR Replacement Piping "
  Svc list encl
  JDRDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408100038 IE Info Notice 84-64, "BWR MPCI Initiation Seal-In & Indication "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24% Fiche 50-000.84/08/15,8408100038
- 840810002: JE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24% Fiche 50-000,84/08/16,8408100021
- B40B100055 IE Info Notice B4-66. "Underected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24% Fichs 50-000,84/08/17,840B100055
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list enc! JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 820109) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- B408210366 Further answer in support of applicant 840320 motion for withdrawal of application Termination order conditioned on implementation of applicant 840601 restoration plan, recommended Insp summary encl
  TREDV.S A Hearing Branch 1 DSB 183 84/08/17 Atomic Safety and Licensing Board Panel tipp 26181 001 24X
  Fiche 30~338.84/08/17.8408210366
- 8408210142 IE Info Notice 84~68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JDRDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26327 008 24X Fiche 50~000.84/08/21.8408210142
- 8 Reportable occurrences. LERs & related correspondence
- B4QB24034B Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on B40413 New thread locking devices investigated SHERWODD, O G General Electric Co 64/04/13 BEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000.84/04/13.8408240348

- DOCKET 50-361 SAN UNDERE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- B40B130220 Forwards list of open items requiring resolution before low power operation can be endorsed by region ENGELKEN,R K Region 5. San Francisco. Office of the Director (81/03/01) 82/01/04 EISENWIT.D G Division of Licensing 9pp 2600B 185 24x Fiche 50-361.82/01/04.8408130220
- F Becurity, medical, emergency & fire protection plans
- 8408030123 Forwards Rev 2 to physical security plan & description of changes Encls withheld (ref 10CFR73 21) HAYNES, J Q Southern California Edison Co 84/07/25 MARTIN, J B Region 5, Office of Director 1p 25916 119 24X Fiche 50-206,84/07/25,8408030123
- 8408170130 Forwards Amends 78,23 & 12 to Licenses DPR-13,NPF-10 & NPF-15, respectively & safety evaluation Amends approve security plan revs which consolidate & reduce size of adjacent vital areas PAULSON. H A Operating Reactors Branch 5 84/08/07 BASKIN.K Southern California Edison Co 5pp 26134 302 24X Fiche 50-206,84/08/07.8408170130
- ---B408170143 Amends 78,23 & 12 to Licenses DPR-13, NPF-10 & NPF-15, respectively, approving security plan revs which consolidate & reduce size of adjacent vital areas & move equipment not required for safety outside vital boundary PAULEON. WA Operating Reactors Branch 5 84/08/07 6pp 26134 307 24X Fiche 50-206,84/08/07.8408170130
- ---8408170155 Safety evaluation supporting Amends 78.23 & 12 to Licenses DRR-13,NPF-10 & NPF-15, respectively \* Office of Nuclear Reactor Regulation, Director 84/08/07 5pp 26134 313 24x Fiche 50-206.84/08/07.8408170130
- BAOB200335 Forwards responses to IE Emergency Appraisal Repts 50-361/B4-08 & 50-362/B4-07 Documents re verification of computer dose projection program available for exem Encl describes test sequence & parameters, hand calculations RAY, H B Southern California Edison Co B4/08/07 MARTIN, J B Region S. Office of Director 16pp 26133 357 24X Fiche 50-361,84/08/07,8408200335
- 8408130450 Advises that 840523 Revs 1-13 to physical security plan consistent w/provisions of 10CFR30 54(p) & acceptable MCQUEEN, A D Region 5, Office of Director 84/08/08 HAYNES, J G Southern California Edison Co 4pp 26004 357 24X Fiche 50-206.84/08/08.8408130450
- 8408230306 Advises that 840131 submittel on detailed control room design review does not meet all requirements of Suppl 1 to NUREO-0737 Review did not include task analysis Addi significant concerns listed XNIQHTON, 0 W Licensing Branch 3 84/08/09 BASKIN, K P Southern California Edison Co MOLOCHBE, J C San Diego Gas & Electric Co 3pp 26236 102 24X Fiche 50-361.84/08/09,8408230306
- 8408310285 Forwards Safeguards Insp Repts 50-206/84-18, 50-361/84-23 & 50-362/84-23 on 840723-27 No violations noted Repts withheld traf 100FR2 790 & 79 21)

  8CHUBTER: M D Region 5, Office of Director 84/08/15 BASKIN.K B Southern California Edison Co 2pp 26333 288 24X

  Ficks 50-206:84/08/15.8408310285
- B408230114 Informs that B40613 ray to emergency plan compatible W/provisions of IOCFR50 47.App E & Rev 1 to NUREG-0654 BCHUSTER:N D Region 5. Office of Director 84/08/16 MEDFORD:N D Southern Callfornia Edison Co 3pp 26347 274 24X Fiche 50-206:84/08/16:8408230114
- P Operating license stage documents & correspondence
- 8408210042 Notification of contract execution, Mod 4, to "Followon Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station " Contractor MIT HOPER: A Administrative Contracts Branch FIN 8-6898 84/06/12 VOLLMER: R Division of Engineering JACKSON: R NRC No Detailed Affiliation Given 19 26195 176 24X Fiche: 50-206, 84/06/12, 8408210042
- --B408210046 Mos 4, deobligating unliquidated fee remaining in contract.
  to "Followon Simulation of Earthquake Ground Notions for
  San Onofre Nuclear Generating Station "
  AKI.K Massachusetts Institute of Technology. Cambridge, MA
  HAGAN,T F Division of Contracts FIN B-6898 B4/06/12 ip
  26195 177 24X Fichs 50-206,84/06/12,8408210042

- B40B010240 Forwards C-E nonproprietary & proprietary "Safety Analysis & CPC Methodology Changes for San Onofre Nuclear Generating Station Units 2 & 3" & "CPC/CEAC Software Mods" Proprietary repts withheld (ref 10CFR2 790) MEDFORD, M O Southern California Edison Co 84/07/20 KNIGHTON, 6 W Licensing Branch 3 13pp 25955 001 24X Fiche 50-361,84/07/20,8408010240
- --B40B010247 Nonproprietary "Safety Analysis & CPC Methodology Changes for San Onofre Nuclear Generating Station.Units 2 & 3 " Info deleted \* Combustion Engineering, Inc CEN-284(S)-NP 84/06/30 35pp 25855 014 24X Fiche 50-361,84/07/20,8408010240
- --8408010256 Nonproprietary "CPC/CEAC Software Mods for San Onofre Nuclear Generating Station Units 2 & 3 " Info deleted \* Combustion Engineering. Inc CEN-281(5)-NP 84/07/31 24pp 28855 050 24X Fichs 50-361.84/07/20.8408010240
- B40B09020B Forwards draft memo re boron injection test, which will be finalized after comments received Final memo will satisfy final milestone defined in 189, "Boron Mixing & Cooldown Under Accident Conditions"
  PRATT.W T Brockhaven National Laboratory FIN A-3368 84/07/30 LIANO, C Y Reactor Systems Branch 18pp 25971 193 24X Fiche 50-206.84/07/30.8408090208
- 8408060080 Forwards response to questions re Proposed Change NPF-10/15-138 re CEA position & insertion limits CEA software rhanges conducted per Rev 2 to CEM-39(A) MEDFORD.M O Southern California Edison Co 84/08/01 KNICHTON.O W Licensing Branch 3 6pp 25933 209 24X Fiche 50-361.84/08/01.8408060080
- B40B070424 Forwards request for addl info re procedures generation package KNIGHTON.G W Licensing Branch 3 84/08/01 BASKIN,K P Southern California Edison Co HOLCONGE.J C San Diego Gas & Electric Co Spp. 25984 308 24X Fiche 50~351.84/08/01.8408090424
- B408270409 Forwards progriptary & nonproprietary Rev 2 to "CPC/CEAC Sys Phase I Software Verification Test Rept." Rev 0 to "CPC/CEAC Sys Phase II ," & Rev 0 to "SONOS-2 Cycle 1 " Proprietary repts withheld (ref lOCFR2 790) MEDFORD.M O Southern California Edison Co 04/08/01 KNIGHTON.0 & Licensing Branch 1 2pp 26236 001 24X Fithe 50-361,84/08/01,8408270409
- --B408270412 Nonproprietary version of Rev O to "CPC/CEAC Bys Phase II Boftware Verification Tost Rept " A Combustion Engineering, Inc. CEN-269(S)-NP ROO 84/03/31 23pp 26238 003 24% Fiche 50-361.84/08/01.8408270409
- --8408270416 Nonproprietary version of Rev O to "SONGS-2 Cycle 1,CPC & CEAC Data Base "

  \* Combustion Engineering, Inc CEN-266(8)~NP ROO 84/03/31
  66pp 26238 029 24X Fiche 50-361,84/08/01,8408270409
- --8408270418 Nonproprietary version of Rev 2 to "CPC/CEAC Sys Phase I Software Verification Test Rept "

  \* Combustion Engineering, Inc CEN-176(8)-NP RO2 84/03/31 27pp 26238 096 24% Fiche 50-361,84/08/01,8408270409
- 840B070110 Generic Ltr 84-19 to all licensess of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Generic Bafety Issues" "Svc list encl EISENHUT.D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche: 50-000.84/08/06.8408070110
- B408090187 Forwards application for Amends 27 & 13 to Licenses NPF-10 & NPF-15, respectively, revising Tech Specs re refueling machines, reactor protective instrumentation & ECGS subsys BARKIN, K P Southern California Edison Co B4/08/07 DENTUN, H R Office of Nuclear Reactor Regulation, Director 4pp 25971 245 24X Fiche 50-361,84/08/07,8408090187
- --B408090194 Application for amends to Licenses NPF-10 & NPF-13, revising Tech Specs re refueling machine reactor protective instrumentation.ECGS subsys & steam generators BASKIN.K P Southern California Edison Co HOLCOMBE.J C San Diego Gas & Electric Co HOVI,0 W Anaheim, CA 84/08/02 14pp 25971 249 24X Fiche 50-361,84/08/07.8408090187
- --8408090201 Proposed Tech Spec changes, adding note which exempts use of refueling machine for coupling/uncoupling & verification of coupling/uncoupling of control element assemblies # Southern California Edison Co 84/08/07 100pp 25971 264 24X Fiche 50-361,84/08/07,8408090187

- 8408100091 Resubmits info re proposed changes to Licenses NPF-10 & NPF-15 Tech Specs in form specified by NRC 840416 request for addlinfo Info extracted from original submittels MEDFORD, M D Southern California Edison Co 84/08/0/ KNIGHTOR. G K Licensing Branch 3 73pp 25990 202 24X Fiche 50-361-84/08/07 8408100091
- 840B170130 Forwards Arends 78.23 & 12 to Licenses DPR-13.NPF-10 & NPF-15, respectively & safety evaluation Amends approve security plan revs which consolidate & reduce size of adjacent vital areas PAULSON.W A Operating Reactors Branch 5 81/08/07 BASKIN.K Bouthern California Edison Co HOLCOMBE.J C San Diego Gas & Electric Co Spp 26134 302 24% Fiche 50-206.84/08/07.8408170130
- --8408170143 Amends 78.23 & 12 to Licenses DPR-13.NPF-10 & NPF-15, respectively, approving security plan revs which consolidate & reduce size of adjacent vital areas & move equipment not required for safety outside vital boundary PAULSDN, WA Operating Reactors Branch 5 84/08/0/ 6pp 26134 307 24% Fiche 50-206.84/08/07.8408170130
- --8408170155 Safety evaluation supporting Amends 78,23 % 12 to Licenses DPR-13,NPF-10 & NPF-15, respectively \* Office of Nuclear Reactor Regulation, Director 84/08/07 5pp 26134 313 24% Fichs 50-206,84/08/07.8408170130
- 840B100115 Documents 840723 discussion re design of proposed gravity-feed auxiliary feedwater pump motor lube oil cooling sys as alternate to forced-feed design described in util 830307 ltr Formal endorsement requested by 840821 MEDFORD, M D. Southern California Edison Co. 84/08/08 KNIGHTUN, G W. Licensing Branch J. 3pp. 25988-262 24X Fiche 50-361.84/08/08,8408100115
- B408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 50-000.84/08/20.8408200275
- 840B240267 Forwards fee balance to complete required remittance for 840125 Proposed Change NPF-10/13-144 MEDFORD.M D Southern California Edison Cp 84/08/21 MILLER,W D License fee Management Branch Lp 26222 358 24X Fiche 50-361,84/08/21,8408240267
- 8408240294 Application for amend to License NPF-10 revising Tech Spect re refueling water storage tank vol required in Modes 5 & 6 & boric acid storage tank concentration/vol required in Modes 1-6 Fee paid MEDFORD.M O Southern California Edison Co 84/08/21 KNIGHTUN.6 & Licensing Branch 3 4pp 26226 019 24X Fiche 50-361.84/08/21.8408240294
- --B408240297 Proposed Tech Specs revising refueling water storage tank vol required in Modes 5 % 6 % boric acid storage tank concentration/vol required in Modes 1-6
  # Southern California Edison Co 84/08/21 10pp 26226 023 24% Fiche 50-261.84/08/21.8408240294
- 8408270325 Advises that Amend 7 to Topical Rept SCE-1-A, "GA Program," consistent w/provisions of 10CFR50 94(a) & acceptable BISHDP-1 W Division of Residents Reactor Project & Engineering Programs 84/08/21 BASKIN, K P Southern California Edison Co 1p 26244 187 24X Fiche 90-206,84/08/21,8408270325
- 8408300163 Application for amend to Licenses NPF-10 & NPF-15, revising Tech Specs re reactivity control sys Fee paid MEDFORD.M O Southern California Edison Co 84/08/27 KNIGHTON.G W Licensing Branch 3 1p 26305 29t 24X Fiche 50-361.84/08/27.8408300163
- --8408300165 Proposed Tech Specs re reactivity control sys \* Southern California Edison Co. 84/08/27 28pp 26305 297 24X Fiche 50-361,84/08/27,8408300163
- O Inspection reports, IE Bulletins & correspondence
- B408130293 Forwards recommended additions/revs to license conditions & comments on draft low power license re results of inspectations to implement GA program adequate ENGELKEN.R H Region 5, San Francisco, Office of the Director (B1/03/01) B2/02/10 EISENHUT.D & Division of Licensing 3pp 26010 004 24X Fichs 50-361,82/02/10,8408130293

- 840809000: Forwards IE Insp Repts 50-361/84-20 & 50-362/84-20 840618-21 No violations noted WEMBLAWSKI.F A Region 5. Office of Director 84/07/25 BASKIN K P Southern California Edison Co 2pp 25994 330 Fishe 50-361.84/07/25.8408090001
- --8408070004 IE Insp Repts 50-361/84-20 & 50-362/84-20 on 8406 violations noted Major areas inspected confirmatory measurements for radioactivity HAMADA, O. NORTH.H. V. VUHAS.G Region 5, Dffice of Director 84/07/24 9pp 25994 332 24X Fiche 50-361,84/07/25.8408
- 8407250229 It Info Notice 84-57, "Operating Experience re Mois Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineerin Response (Post 830103) 84/07/27 Consolidated Edison Co Vork. Inc. 119pp 25845 047 24X Fiche 50-000,84/07/27,840
- 8408090043 Forwards IE Insp Repts 50-361/84-19 & 50-362/84-19 a B40605-08 No violations noted BIBHOP.T W Region 5. Orfice of Director 84/07/27 BASKIf Bouthern California Edition Co 1p 25992 123 24X Ficha 50-361,84/07/27,8408090043
- --B408090045 IC insp Repts 90-361/B4-19 & 50-362/B4-19 on B4060 violations noted Major areas inspected precritical, low powe & power ascension test results data PEREIRALD B. PATE. R. J. Region 3. Office of Director B4/8pp 25992 124 24% Fiche 50-361.84/07/27,8408090043
- B40B140056 Forwards latest facility attachment prepared by IAEA including all review 5 insp results Encis withheld (ref iOCFR2 790)
  KNIOHTON, G W Licensing Branch 3 84/07/27 BASKIN, K F S California Edison Co HOLCOMBE, J C San Diego Gas & Electri 2pp 26061 264 24X Fiche 50-361, 84/07/27, 840B140056
- 8408070411 Responds to IE Bulletin 84-02. "Failures of GE Type Relays in Use in Class IE Safety Sys "Thirty-one relays Found at Unit 1 will be replaced by 860312 MEDFORD, M O Southern California Edison Co 84/07/30 MART Region 5. Office of Director 3pp 25942 170 24X Fiche 50-204.84/07/30.8408070411
- 8408040112 Proposes method of insp of low pressure turbine disc ultrasonic indications Discs will be inspected prior to startup following second refueling outage, per License Condition 2 C (15) & 2 C (13) MEDFORD.M O Bouthern California Edison Co 84/08/01 KNIGHTON.O W Licensing Dranch 3 2pp 25925 307 24X Ficho 50-341.84/08/01.8408060112
- 8408140260 Provides add1 response to JE Insp Repts 50-361/84-14 50-362/84-14 on 840506 & 07 Evaluation & actions taken as result of 840503 increase in RCS radioactivity described RAY.H B Southern California Edison Co 84/08/01 MARTIN, J Region 5. Office of Director 3pp 26055 330 24% Fiche 50-361.84/08/01.8408140260
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of St Health Physics Procedures" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co York, Inc. (122p) 26068 001 24X Fiche 50-000, 84/08/06, 8408
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respi Filters to Meat Efficiency Requirement " Svc list encl JORDAN, E. L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/06 Consolitated Edison Co York, Inc. 123pp 26067 198 24X Fiche 50-000.84/08/06,8408
- 8408200335 Forwards responses to IE Emergency Appraisal Repts 50-361/84-09 & 30-362/84-07 Documents re-verification of computer dose projection program available for exam Encl describes test sequence & parameters hand calculations RAY, H B Southern California Edison Co 84/08/07 MARTIN. J Region 5. Office of Director 16pp 26133 357 24X Fiche 50-361.84/08/07.8408200335
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PHR Refueling Cavity " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408
- 8408070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl ORACE.J N Division of QA. Safeguards & Inspection Programs ( 830103) 84/08/10 Consolidated Edison Co of New York, In 125pp 26130 001 24x Fiche 30-000.84/08/10.8408070376

- 8408100009 IE Info Notice 84-63, 'Defective RHR Replacement Piping "
  - Sec list encl

    JORDANNE L Division of Emergency Proparedness & Engineering
    Response (Post 830103) 84/08/13 Consolidated Edison Co of New
    York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009
- 8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc. 104pp 26198 093 24x Fiche 50-000.84/08/15.8408100038
- 8408310285 Forwards Safeguards Insp Repts 50-206/84-18,50-361/84-23 & 50-362/84-23 on 840723-27 No violations noted Repts withheld (ref 10CFR2 790 & 73 21)
  SCHUSTER, M D Region 5, Office of Director 84/08/15 BASKIN, K B Southern California Edison Co 2pp 26333 288 24X
  Fiche 50-206,84/08/15,8408310285
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl list encl
  JORDAN, E. L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/16 Consolidated Edison Co. of New
  York, Inc. 118pp 26198 001 24% Fiche 50-000,84/08/16,8408100021
- 840Bi00055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl URBAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/
  High Failure Rates " Svc list encl
  JORDAN.E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/17 Consolidated Edison Co of New
  York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 8408230223 Ack receipt of 840801 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-361/84-14 & 50-362/84-14 Ltr dtd 840801 adequately responds to NRC 840725 request SCARAND.R A Division of Radiological Safety & Safeguards Program 84/08/17 BASFUN.K P Southern California Edison Co 1p 86207 183 24% Fiche 50-361.84/08/17,8408230223
- OBZ10142 IE Info Notice 84-6B. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/08/21 Consolidated Edison Co of New York, Inc 115pp 26327 008 24% Fiche 50-000.84/08/21,8408210142
- ₹ Periodic operating reports & related correspondence
- 340B220078 Forwards monthly rept describing occurrences resulting in degradation of auxiliary funduater sys covering 840616-0715, per License Condition 2 C(26) Next rept will cover 840716-0815 840716-0815 MEDFORD.M O Southern California Edison Co B4/08/17 KNIGHTON.G W Licansing Branch 3 4pp 26193 301 ; Fiche 50-361.84/08/17.8408220098
- S Reportable occurrences. LERs & related correspondence
- 8408010304 Revised LER 84-009-01 on 840214, analysis of startup test data for Units 2 & 3 established that calculated thermal power may become decalitr relative to secondary calometric power Procedure S023-5-1 revised W/840723 ltr HAYNEB J G Southern California Edison Co 84/07/23 3pp 25866 099 24X Fiche 50-361,84/07/23,8408010304
- 8408060034 Forwards LER 84-041-00 On 840724, discrepancies discovered during updated fire hazards analysis Corrective actions described in 840425 ltr implemented HAYNEG, J C Southern California Edison Co 84/07/25 Record Services Branch (Document Control Desk) 2pp 29735 275 24X Fiche 50-361.84/07/25,8408060034
- 8408060223 LER 84-035-00 on 840625 containment area radiation monitor 2RE-7804(EIIS Identifier RT) reached alarm setpoint % initiated train A containment purge isolation sys Cause under investigation. New setpoint installed W/840725 ltr HAYNES.J O Southern California Edison Co 84/07/25 2pp 25936 178 24X Fiche 50-361.84/07/25,8408060223

- 8408080489 LER 84-037-00 on 840627 spurious actuation of toxic gas isolation sys occurred Caused by Overly conservative alarm setpoints Tech Spec amend submitted 840427 requesting more appropriate settings W/840727 ltm
  HAYNES. J G Southern California Edison Co 84/07/27 3pp
  25975 185 24X Fiche 50-361,84/07/27,8408080489
- B40B0603B7 "Design Review of Elliott Hodel 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
  \* Failure Analysis Associates FAAA-84-6-56 B4/07/31 62pp 25927 066 24% Fiche 50-000, 84/08/01, 840B060324
- 840B170059 LER 84-038-00 on 840708.23 t 26.control room isolation systrain A spuriously actuated from noise spike on control room airborne radiation monitor 213RE-7824 Caused by electrical noise spikes of unknown origin W/840B02 ltr MAYNES.J G Southern California Edison Co 84/08/02 2pp 26130 056 24X Fiche 50-361.84/08/02.8408170059
- 8408240084 LER 84-039-00 on 840712 Inservice insp test of Unit 2 & 3 rogarous Lex 84-039-00 an 840/22 (nservice inspired colong uster outlet valves (MV-6500 & HV-6501) missed Caused by administrative oversight Procedural controls validated W/840813 ltm
  HANNES, J Southern Callfornie Edison Co 84/08/13 3
  26237 034 24X Fiche 50-361,84/08/13,8408240084 B4/0B/13 3cc
- 8408220139 PNO-V-84-050 on 840815, influx of seaweed caused reduction in circulating water flow Power reduced as condenser vacuum degraded High differential pressure observed on train () component cooling water HX while train A inoperable KIRSCH.D. HAIST.D. Region 5, Office of Director 84/08/15 ip 26194 048 24X Fiche 50-361,84/08/15,8408220139
- 8408280225 Special Rept on 840804.purge/vent stack wide range monitor 2RE-7865 removed from svc for performance of 92-day surveillance Monitor not restored to operable status within 72 h to permit corrective maint on sys valve HAYNES.J & Southern California Edison Co 84/08/17 MARTIN, J 8 Region 5, 06fice of Director 2pp 26274 307 24X Fichs 50-341.84/08/17,8408280225
- 8408280276 LER 84-035-00 on 840629.HPSI isolation valve 34V9327 failed to stroke during surveillance on HPSI check valves Caused by excessive wear on stem & retaining ring Valves showing free stem movement repaired & returned to svc W/840817 ltr HAYNES, J G Southern California Edison Co 84/08/17 Spp 26282 133 24% Fiche 50-361,84/08/17,8408280276
- 8408300492 LER 84-040-00 on 840723 main steam isolation sys inadvertently actuated Caused by technician error & weakn w/procedural precautions Procedure 8023-II-1 6 amended W/840822 itr MANNES, J G Southern California Edison Co 84/08/22 3pp 26314 083 24X Fiche 50-361,84/08/22,8408300472
- DOCKET SO-362 SAN ONOTHE NUCLEAR STATION, UNIT 3 F Security, medical, emergency & fire protection plans
- 8408030123 Forwards Rev 2 to physical security plan & description of changes Encls withheld (ref 10CFR73 21) HAYNEBJ O Bouthern California Edison Co 84/07/23 MARTIN, J B Region 5, Office of Director 1p 25916 119 24X Fiche 50-206,84/07/25,8408030123
- 8408170130 Forwards Amends 78,23 & 12 to Licenses DPR-13, NPF-10 & NPF-15, respectively & safety evaluation Amends approve security plan revs which consolidate & reduce size of adjacent vital areas PAULBON. & A Operating Reactors Branch 5 84/08/07 BASKIN, K Southern California Edison Co 5pp 26134 302 24% Fiche 50-204.84/08/07.8408170130
- --8408170143 Amends 78.23 & 12 to Licenses DPR-13.NPF-10 & NPF-15. respectively, approving security plan revs which consolidate a reduce size of adjacent vital areas & move equipment not required for safety outside vital boundary PAMLBON.W A Operating Reactors Branch 5 84/08/07 App 26134 307 24X Fiche 50~206.84/08/07.8408170130
- --8408170155 Eafaty evaluation supporting Amends 78,23 & 12 to Licenses PPR-13,NPF-10 & NPF-15, respectively \* Office of Nuclear Reactor Regulation. Director 84/08/07 5pp 26134 313 24X Fiche 50-206,84/08/07,8408170130
- 8408200335 Forwards responses to IE Emergency Appraisal Repts 50-361/84-08 t 50-362/84-07 Documents re verification of computer dose projection program available for exam Encl describes test sequence to parameters; hand calculations RAY.H B Southern California Edison Co 84/08/07 MARTIN. Region 5, Office of Director 14pp 26134 001 24% Fiche 50-361,84/08/07,8408200335 MARTIN. J B

- 8408130450 Advises that 840523 Revs 1-13 to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable MCGUEEN.AD Region 5. Office of Director 84/08/08 HAYNES, J G Bouthern California Edison Co. 4pp. 26004 359 24X Fiche 50-206,84/08/08.8408130450
- 8408230306 Advises that 840131 submittal on detailed control room design review does not nect all requirements of Suppl 1 to NUREO-0737 Review did not include task analysis Addl significant concerns listed KNIGHTON, 6 W Licensing Branch 3 84/08/09 BASKIN, K P Southern California Edison Co HOLCOMBEJ C San Diego Gas 5 Electric Co Spp 26236 102 24X Fiche 50-361,84/08/09,8408230306
- 8408310285 Forwards Safeguards Insp Repts 50-206/84-18,50-361/84-23 & 50-362/84-23 on 840723-27 No violations noted Repts withheld (ref 100FR2 790 & 73 21)
  8CHUSTCR.M D Region 5, Office of Director 84/08/15 BASKIN.K 8 Southern California Edison Co 2pp 26333 288 24X
  Fiche 50-206,84/08/15.8408310285
- 8408230114 Informs that 840613 rev to emergency plan compatible w/provisions of 10CFR50 47, App E & Rev 1 to NUREC-0654 SCHUSTER, M D Region 5, Office of Director 84/08/16 MEDFORD, M C Southern California Edison Co 3pp 26/347 274 24X Fichs 50-206,84/08/16,8408230114
- P Operating license stage documents & correspondence
- 8408210042 Notification of contract execution Mod 4, to "Followon Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station " Contractor MIT HOPPER A Administrative Contracts Branch FIN B-6898 84/06/12 VOLLMER R Division of Engineering Ip 26193 176 24X Fiche 50-362,84/06/12,8408210042
- --8408210046 Mod 4.deobligating unliquidated fee remaining in contract.
  to "Followon Simulation of Earthquake Ground Motions for
  San Dnofre Nuclear Generating Station"
  AKI,K Massachusetts Institute of Technology, Cambridge, MA FIN
  B-6878 84/06/12 ip 26195 177 24X Fiche 50-362.84/06/12,
  B408210042
- 8408010240 Forwards C-E nonproprietory & proprietory "Safety Analysis & CPC Methodology Changes for San Onofre Nuclear Generating Station Units 2 & 3" & "CPC/CEAC Software Mods"
  Proprietory repts withheld (ref IOCTR2 770)
  MEDFORD, M O Sputhern California Edison Co 84/07/20
  KNIGHTON, G & Licensing Branch 3 13pp 25855 001 24X
  Fiche 50-361,84/07/20,8408010240
- --8408010247 Nonproprietary "Bafety Analysis & CPC Methodology Changes for San Onofre Muclear Generating Station, Units 2 & 3 " Info delected \* Combustion Engineering, Inc. CEN-284(S)-NP 84/06/30 35pp 25855 014 24X Fiche 50-361,84/07/20,8408010240
- --8408010256 Nonproprietary "CPC/CEAC Software Mods for San Onofre Nuclear Generating Station Units 2 & 3 " Info deleted \* Combustion Engineering, Inc CCN-281(6)-NP 84/07/31 24pp 25859 050 24% Fiche 30-361.84/07/20.8408010240
- 840B09020B Forwards draft name re boron injection test, which will be finalized after comments received Final mema will satisfy final nalestone defined in 189, "Boron Mixing & Cooldown Under Accident Conditions"
  PRATT.W T Brookhaven National Laboratory FIN A-336B 84/07/30 LIANG, C Y Reactor Systems Branch 18pp 25971 193 24X Fiche 50-206,84/07/30,8408090208
- B408040080 Forwards response to questions re Proposed Change NPF-10/15-138 re CEA position & insertion limits CEA suftwar changes conducted per Rey 2 to CEN-39(A) MEDFORD, M O Southern California Edison Co 84/08/01 KNIGHTON, G W Licensing Branch 3 6pp 25933 209 24X Fiche 50-341,84/08/01,8408060080
- 8408070424 Forwards request for add1 info re procedures generation package KNIGHTON,O W Licensing Branch 3 84/08/01 BASKIN,K P Southern California Edison Co HOLCOMBE,J C San Diego Gas & Electric Co 5pp 25984 305 24X Fiche 50-361,84/08/01,8408090424
- 8408270409 Forwards proprietary & nonproprietary Rev 2 to "CPC/CEAC Sys Phase I Software Verification Test Rept," Rev 0 to "CPC/CEAC Sys Phase II "," & Rev 0 to "SONGE-2 Cycle 1 " Proprietary repts withheld (ref 10CFR2 790) MEDFORD M 0 Southern California Edison Co. 84/08/01 KNIGHTON G W Licensing Branch 1 2pp 26238 001 24X Fiche 50-361.84/08/01,8408270409

- --8408270412 Nonproprietary version of Rev O to "CPC/CEAC Sys Phase II Software Verification Test Rept" \* Combustion Engineering, Inc CEN-269(S)-NP ROO 84/03/31 25pp 26238 003 24% Fiche 50-361/84/08/01/8408270409
- --8408270418 Nunproprietary version of Rov 2 to "CPC/CEAC Sys Phase I Software Verification Test Rept " \* Combustion Engineering, Inc CEN-176(5)-NP RO2 84/03/31 27pp 26238 096 24X Fiche 50-361,84/08/01.8408270409
- B40B070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933. "Prioritization of Generic Safety Insues "Svc list encl EISENHUT. D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26127 238 24X Fichs 50-000,84/08/06,8408070110
- B408090187 Forwards application for Amends 27 & 13 to Licenses NPF-10 & NPF-15, respectively, revising Tech Specs re refueling machines, reactor protective instrumentation & ECCS subsys BASKIN, K P Southern California Edison Co B4/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 23971 245 24X Fiche 50-361,84/08/07,8408090187
- ---B408090194 Application for amends to Licenses NPF-10 & NPF-15, revising Tech Specs re refueling machine, reactor protective instrumentation. ECCS subsys & steem generators HASKIN.K P Southern California Edison Co HOLCOMBE. J C San Diego Gas & Electric Co HOYT.6 H Anabeim. & 84/08/02 14pp 25971 247 24X Fiche 50-361.84/08/07.8408090187
- --8408070201 Proposed Tech Spec changes, adding note which exempts use of refueling machine for coupling/uncoupling & verification of coupling/uncoupling of control element assemblies

  \* Southern California Edison Co 84/08/07 100pp 25971 264
  24% Fische 50-361,84/08/07,8408090187
- 8408100091 Resubmits info re proposed changes to Licenses NPF-10 & NPF-15 Tech Spacs in form specified by NRC 840416 request for add info info extracted from original submittals MEDFORD.M D Southern California Edison Co 84/08/07 KNIGHTUN.O W Licensing Branch 3 73pp 25990 202 24x Fiche 50-361.84/08/07.84081000091
- B408170130 Forwards Amends 78,23 & 12 to Licenses DPR-13, NPF-10 & NPF-15, respectively & safety evaluation Amends approve security plan revs which consolidate & reduce size of adjacent vital areas PANLSON: WA Operating Reactors Branch 5 84/08/07 BASKIN, K Southern California Edison Co HOLCOMES, J C San Diego Cas & Electric Co 5pp 26134 302 24X Fiche 50-206.84/08/07,8408170130
- --8408170143 Amends 78.23 & 12 to Licenses DPR-13.NPF-10 & NPF-15, respectively, approving security plan revs which consolidate a reduce size of adjacent vital areas & move equipment not required for safety outside vital boundary PAULSON.WA Operating Reactors Branch 5 84/08/07 App 26134 307 24X Fichs 50-206.84/08/07.8408170130
- --8408170155 Safety evaluation supporting Amends 78,23 & 12 to Licenses DPR-13.NPF-10 & NPF-15, respectively \* Office of Nuclear Reactor Regulation, Director 26134 313 24X Fiche 30-206,84/08/07,8408170130
- E40Bi00115 Documents 840723 discussion re design of proposed gravityfeed auxiliary feedwater pump motor lube oil cooling sys as alternate to forced-feed design described in util 830307 ltr Formal endorsement requested by 840821 MEDFORD.M O. Sauthern California Edison Co. 84/08/08 KNIOHTUN.G W. Licensing Branch 3 3pp 25788 262 24X Fiche 50-361.84/08/08.8408100115
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidence for licensee submittals of reloads that involve unreviewed safety questions Svc list enci.

  EISENHUT.D 0 Division of Licensing 84/08/20 Consulidated Edison Co of New York, Inc. 17pp. 26276 244 24X

  Fiche 50-000,84/08/20,8408200275
- B408240267 Forwards fee balance to complete required remittance for B40185 Proposed Change NPF-10/15-144
  MEDFORD,M O Southern California Edison Co. 84/08/21 MILLER,W O License Fee Management Branch 1p 26222 358 24X
  Fiche 50-361,84/08/21,8408240267.

- 8408270325 Advises that Amend 7 to Topical Rept SCE-1-A, "GA Program, consistent w/provisions of 10CFR50 34(a) & acceptable BISHDP.T W Division of Resident Reactor Project & Engineering Programs 84/08/21 BASKIN.K P Southern California Edison Co ip 26244 187 24% Fiche 50-206.84/08/21.8408270325
- B40B300163 Application for amend to Licenses NPF-10 & NPF-15, revising Tech Specs re reactivity control sys Fee paid MEDF08D.M O Southern California Edison Co B4/08/27 KMIGHTON.G W Licensing Branch 3 ip 26305 291 24X Fiche 50-361.B4/08/27.B40B300163
- --8408300165 Proposed Tech Specs re reactivity control sys \* Southern California Edison Co 84/08/27 28pp 26305 297 24x Fiche 50-361,84/09/27,8408300163
- ⊕ Inspection reports, IE Bulletins & correspondence
- 9408090001 Forwards IE Insp Repts 50-361/84-20 & 50-362/84-20 on 840618-21 No violations noted WENSLAMSKI.F A Region 5. Office of Director 84/07/25 8ASKIN.K P Southern California Edison Co 2pp 25994 330 24X Fiche 50-361.84/07/25.8408070001
- --B408090004 IE Insp Repts 50-361/84-20 & 50-362/84-20 on 840618-21 No violations noted Hajor areas inspected confirmatory measurements for radioactivity HAMADA,G, NORTH,H, YUHAS,G Region 5. Office of Director 84/07/24 9pp 25994 332 24X Fiche 50-361.84/07/25,8408090001
- 8407250229 IE Info Notice 84-37, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, Et. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc. 119pp 25865-047 24X Fiche 50-000,84/07/27,8407250229
- 8408090043 Forwards IE insp Repts 50-361/84-19 % 50-362/84-19 on 840605-08 No violations noted 816HOP, T W. Region 5. Office of Director 84/07/27 DASKIN, K B Southern California Edison Co. 1p. 25992 123 24X Fiche 30-361.84/07/27.8408090043
- --8408070045 IE insp Repts 50-361/84-19 & 50-362/84-19 on 840605-08 No violations noted Major areas inspected precritical, low power & power ascension test results data PEREIRA,D B. PATE, R. J. Region 5. Office of Director 84/06/27 8pp 25992 124 24% Fiche 50-361.84/07/27.8408090043
- 3408140036 Forwards latest facility attachment prepared by IARA, including all review & inspiresults Encls withheld (ref. 10CFR2 790)
  WNIGHTUN, 0 W Licensing Branch 3 84/07/27 BASKIN, K P Southers California Edison Co. HDLCOMBE, J.C. San Diego Gas & Electric Co. 2pp. 26061 264 24% Fiche 50-361,84/07/27,8408140056
- 8408070411 Responds to FE Bulletin 84-02, "Failures of GE Type MFA Relays in Use in Class IE Safety Sys " Thirty-one relays found at Unit 1 util be replaced by 860312 MEDFORD, M D Southern California Edison Co 64/07/30 MARTIN, J B Region 5. Office of Director 3pp 23942 170 24X Fiche 50-206,84/07/30,8408070411
- 8408060112 Proposes method of insp of low pressure turbine discs for ultrasonic indications Discs will be inspected prior to startup following second refueling outage, per License Condition 2 C (13) & 2 C (13)

  MEDFORD.4 O Southern California Edison Co 84/08/01

  KNIGHTON.6 W Licensing Branch 3 2pp 25925 307 24X

  Fiche 50-361,84/08/01.8408060112
- 840B140260 Provides add1 response to IE Insp Repts 50-361/84-14 & 50-362/84-14 on 840506 & 07 Evaluation & actions taken as result of 840505 increase in RCS radioactivity described RAY.H B Southern California Edison Co B4/08/01 MARTIN.J B Region 5. Office of Director 3pp 26055 330 24X Fiche 50-361-84/08/01.8408140260
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JORBAN E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/04 Consolidated Edison Co. of New York: Inc. 122pp 26069 001 24X Fiche 30-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list encl JORDAN, Et. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc. 123pp 26067 158 24X Fithe 50-000.84/08/06.8408010337

- 8408200J35 Forwards responses to IE Emergency Appraisal Repts 50-361/84-08 & 50-362/84-07 Documents re verification of computer duse projection program available for exam Encl describes test sequence & parameters, hand calculations RAY.H B Southern California Edison Co 84/08/07 MARTIN.J B Region 5. Office of Director 16pp 26133 359 24X Fiche 50-361,84/08/07.8408200335
- B408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity ' Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4708708 Consolidated Edison Co. of New York, Inc. 120pp 26129 118 24X Fiche 50-000.84/08/08,8408070120
- 8408070376 JE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc IIst encl QRACE.J N Division of QA Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 129pp 26130 001 24x Fiche 50-000.84/08/10,8408070376
- 8408100009 IE info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JURDAN,E L Division of Emergency Preparedness & Engineering
  Response (Past 830103) 84/09/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- B408210479 Provides addl response to notice of violation & proposed imposition of civil penalties Systematic mgt monitoring & feedback program implemented to identify & correct deficiencies
  FOGARTY, D.J. Southern California Edison Co. 84/08/13. DEYGUNG, R.C. Director's Office. Office of Inspection and Enforcement 6pp 24181 137. 24X Fiche 50-362, 84/08/13, 8408210479
- 8409100038 IE info Notice 84-64, "BWR HPCI initiation Beal-In & Indication " Svc list encl JARDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038
- 8408310285 Forwards Safeguards Insp Repts 50-204/84-18,50-361/84-23 & 50-362/84-23 on 840723-27 No violations noted Repts withheld (ref 100FR2 790 & 73 21)
  SCHUSTER, M D Region 5, Office of Director 84/08/15 BASKIN, K B Southern California Edison Co 2pp 26333 288 24X
  Fiche 50-206,84/08/15,8408310285
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 30-000, 84/08/16, 8408100021
- 8408100055 IE Info Notice 84-66, "Undeterted Unavailability of Turbine-Driven Auxiliary Foodwater Train " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- 8408140208 JE Info Notice 84-67, "Recent Shubber Inservice Testing H/ High Failure Rates " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- B40B230223 Ack receipt of B40B01 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-361/84-14 & 50-362/84-14 Ltr ets B40B01 adequately responds to NRC B40725 request SCARAND.R A Division of Radiological Safety & Safeguards Program B4/0B1/17 BASKIN.K P Southern California Edison Co ip 26207 183 24X Fiche 50-361,84/0B/17,840B230223
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves "Svc list enci JORDAN, E.L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York Inc 1159p 26329 008 24X Fiche 50-000.84/08/21,8408210142
- R Periodic aperating reports & related correspondence
- 8408220078 Forwards monthly rept describing occurrences resulting in degradation of auxiliary feedwater sys covering 840616-0715, per License Candition 2 C(26) Next rept will cover 840716-0815 MEDFORD, M O Southern California Edison Co 84/08/17 MNIGHTUN-6 W Licensing Branch 3 4pp 26193 301 24X Fiche 50-361,84/08/17,8408220098

- B Reportable occurrences, LERs t related correspondence
- 8408060397 Design Reliew of Elliott Hodel 650 Turbochanger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets '

  Failure Analysis Associates FAAA-84-6-56 B4/07/31 62pp 25927 066 24% Fiche 50-000/B4/08/01.8408060324
- 8408090418 LER 84-020-01 on 840527.8 h grab sample due at 0800 not taken until 0945 Lourrange flow at sample conditioning slid diverted from filter A to filter B.causing blown fuse Alternate flow path established W/840801 ltr HAYNES.J G Sauthern California Edison Co 84/08/01 3pp 25993 244 24% Fiche 50-362.84/08/01.8408090418
- 8498240200 LER 84-029-00 on 840709, high level excursion occurred resulting in closure of extraction steam valves % isolation of second & first point heaters from steam supply Caused by steam loss W/840814 ltr
  HAYNES, J G Southern California Edison Co 84/08/14 3pp 26236 283 24X Fiche 50-362.84/08/14,8408240200
- 8408220139 PND-V-84-050 on 840815.influx of seaweed caused reduction in circulating water flow Power reduced as condenser vacuum degraded high differential pressure observed on train B component cooling water HX while train A inoperable KIRSCH.D. HAIST.D Region 5. Office of Director 84/08/15 ip 26194 048 24% Fiche 50-361.84/08/15,8408220139
- 8408280078 PNO-V-84-052 on 84082i.licensee determined that HPSI patentially degraded due to component conling water HX mini flow bypass open for subgroup relay testing Formal investigation being conducted MORRILLP. HAIST. D. Region 5. Office of Director 84/08/22 26261 206 24X Fiche 50-362.84/08/22.8408280078
- DOCKET 50-364 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 2

  F Security, medical, emergency & fire protection plans
- B40Bi70386 Requests meeting to discuss detailed control room design review w/respect to Nuclear Util Task Action Committee documents
  VAROA, 5 A Operating Reactors Branch 1 B4/05/24 MCDDNALD, R P Alabama Power Co 3pp 26134 193 24% Fiche 50-348,84/05/24,840Bi70384
- B408300364 Forwards summary of 840530 meeting w/Alabama Power Co, Florida Power Corp.Florida Power & Light, Georgia Power Co & TVA re selected emergency preparedness issues O'REILLY, J P Region 2. Office of Director 84/06/08 MCDDMALD, R P Alabama Power Co 4pp 26308 216 24X Fiche 50-348, 84/06/08, 8406300364
- 8408060070 Temporary change notices for Rev 7 to Procedure GC-EIP-111. "Corporate Activation & Notification " W/840727 ltr MUDD.C H Alabama Power Co 84/07/27 21pp 25933 104 24X Fiche 50-348.84/07/27.8408060070
- 8408070469 Forwards interin shutdown meaures re App R Eleven sys discussed which could potentially be impacted by cable spreading room fire Mods required to establish compliance w/App R MCDONALD, C E Alabama Power Co 84/07/27 VARQA, S A Dffice of Nuclear Reactor Regulation. Director 5pp 25940 336 24x Fiche 50-348.84/07/27,8408070469
- 8408130374 Submits add1 info re 10CFR5D. App R schedular exemption for alternative shutdown mods Bases for schedular exemption until Unit 1 seventh & Unit 2 fourth refueling outages to completed mods provided MCDONALD, R P Alabama Power Co 84/08/06 VARQA, S A Office of Nuclear Reactor Regulation, Director 2pp 26005 337 24% Fiche 50-348,84/08/06.8408130374
- 8408210417 Rev 13 to Emergency Plan Implementing Procedure FNP-D-EIP-16. "Emergency Equipment & Supplies " W/840814 1th HUDSPETH.J B Alabara Power Co 84/08/14 MCKNJCHT.J Record Services Branch (Document Control Desk) 7pp 26177 241 24X Fiche 50-364:84/08/14.8408210417
- 8408240227 Summary of 840725 meeting w/util re detailed control room design review per NUREG-0737. Suppl 1 REEVES,E A Operating Reactors Branch 1 84/08/16 Operating Reactors Branch 1 6pg 26251 227 24X Fiche 50-348. 84/08/16, 8408240229

- 8408230326 Rovised emergency plan implementing procedures.including OD-EIP-101 re corporate emergency organization.GD-EIP-135 re emergency plan review % rev & GO-EIP-120 re ref guidance for recovery manager W/840817 ltr MUDD.C H Alabama Power Co 84/08/17 36pp 26206 018 24X Fiche 50-348.84/08/17.8408230326
- M Antitrust correspondence
- B40B130075 Ack receipt of B40629 petition for enforcement action under 10CFR2 206 re antitrust license conditions Petition will be held in abeyance pending further Commission direction DENION R Office of Nuclear Reactor Regulation, Director 84/07/30 BDSKEY, B volps, Buskey & Lyons 7pp 26034 353 24x Fiche 50-348,84/07/30,8408330075
- 8408080197 Reiterates 840702 request for notes, memoranda or transcripts of mattings between NRC & util as referenced in Palladina 840626 memo BOBKEY, B., MACGUINEAS, D.B. Volpo, Boskey & Lyons BOBKEY, B. Alabama Electric Cooperative. Inc. DSB 833 84/08/06 DIRCKS, H.J. Office of the Executive Director for Operations 2pp. 25760 259 24X Fiche 50-348, 84/08/06, 8408080197
- 8408080202 Resterates 840/02 request for notes.memoranda or transcripts of neetings between NRC & util as referenced in Palladino 840626 memo BOSKEY.B., MACGUINEAS.D.B. Volpe, Boskey & Lyons BOSKEY.D. Alabama Electric Cooperative, Inc. DBB 831 84/08/06 DERNTHAL.F.M. Commissioners 20p 25959 022 24X Fiche 50-348.84/08/06.8408080202
- 8408080241 Reiterates 840702 request for any notes or memoranda or transcripts of neetings u/util near end of June 1984 Certificate of Svc enc1
  BIGKEY, B. MACGUINEAS, D. B. Volpe: Boskey & Lyons BIGKEY, B. Alabama Electric Cooperative, Inc. DSB 832 84/08/06
  ASSELSTINE, J. K. Commissioners 2pp 25966 291 24X
  Fiche 50-346,84/08/06,8408080241
- 8408150120 Responds to 840806 ltr to MJ Direks requesting any notes, memoranda or transcripts made of meetings between NRC & util No notes taken & no memoranda or transcripts of 840626 meeting prepared Related correspondence CUNNINGHAM, O H Office of the Executive Legal Director D90 038 84/08/10 808KEY, B . MACQUINEAS, D B Volpe, Boskey & Lyons 2pp 24066 352 24% Fiche 50-348,84/08/10,8408150120
- B40B2004B6 Responds to 840806 request for Commission records re 840625 meeting w/util Chairman Palladino 840624 memo accurately reflects conversation H/svc list Served on 840817 BERNTHAL.F. Commissioners DSB 166 B4/08/16 BCSMEY.B Volpe, Boskey & Lyons 3pp 26136 318 24X Fiche 50-348.84/08/16, 8408200486
- P Operating license stage documents & correspondence
- 8408060277 Requests add1 info needed for continuing review of 840203 license amend request per Generic Ltr 83-42 Deficiencies noted in Tech Spors re deletion of ROs VAROA. S A Operating Reactors Branch 1 84/07/25 McDONALD.R P Alabama Power Co 2pp 25950 294 24X Fichs 50-348.84/07/25, 8408060277
- 8408130233 Forwards safety evaluation 5 technical evaluation rept recontrol of heavy loads. Phase 1 VARGA. 8 A Operating Reactors Branch 1 84/07/25 HCDGNALD.R P. Alabama Power Co 29p 26060 027 24X Fishe 50-348,84/07/25,
- --8408100298 SER re control of heavy loads. Phase 1 Acceptable # NRC - No Detailed Affiliation Given 84/07/25 2pp 26060 029 24% Fiche 50-348,84/07/25,8408130233
- 8408100034 Forwards updated status of 1984 licensing items identified in 840702 ltr Util ready to discuss mod of licensing status to address all licensing issues MCDONALD, R P Alabama Power Co 84/08/01 VAROA, 8 A Office of Nuclear Reactor Regulation, Director 7pp 25790 041 24X Fiche 50-348.84/08/01,8408100036
- 84080701tO Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Buppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues" Svr list encl EISENMUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp. 26129 238 24X Fiche: 50-000,84/08/06,8408070110

- 8408090317 Forwards monthly status rept to plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
  - Jul 1984
    TREMBLAY, P P Operating Reactors Assessment Branch
    HOLAHAN, G K Operating Reactors Assessment Branch
    25791 350 24X Fiche 50-000, 84/08/06, 8408090317 84/08/06
- 8408210412 Forwards list of accident monitoring equipment to be replaced within extended schedule of IOTER50 49.per Reg Quide 1 97
  - replaced within extended schedule or lournou 44.per Reg Quide 197 MCDBNALD.R P Alabama Power Co 84/08/17 VARGA, S A Nuclear Reactor Regulation, Director 4pp 26179 211 Fiche 50-364,84/08/17.8408210412 Office of 24X
- 8408230378 Application for amend to Licenses NPF-2 & NPF-8, deleting words during shutdown from Tech Spec 4 7 1 2 2 b 1 re auxiliary feedwater sys Fee encl MCDDNALD, R P Alabama Power Co 94/08/17 VARGA, S A Office of Nuclear Reactor Regulation, Director 3pp 26205 304 24X Fiche 50-348,84/08/17,8408230398
- --8408230399 Proposed Tech Spec 4 7 1 2 2 5 1.deleting words during
  - snucoum \* Alabama Power Co 84/08/17 2pp 26705 307 24X Fiche 50-348,84/08/17,8408230398
- B40B200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for DLs re-scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Syc list enci EISENHUT, D G Division of Licensing B4/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 50-000.84/08/20.840B200275
- G Inspection reports. IE Bulletins & correspondence
- 8408280176 Discusses results of diesel generator check valve integrity insp.per IE Bulletin 83-03.during fifth refueling outage on BA0210-0424 Inservice testing requirements for valves will be modified as listed MCDONALD, R.P. Alabama Power Co. 84/06/01 D'REILLY, J.P. Regio Office of Director Spp. 26279 196 24X Fiche 50-348, 84/06/01. 8408280176
- B40B2B004B Forwards response to IE Builetin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Bys " Unit 1 relays replaced w/GE Century Series HFA relays Thirty-three Unit 2 relays require replacement MCDDNALD,R P Alabama Power Co 84/07/12 O'REILLY, J P Regio Office of Director 3pp 26261 230 24X Fiche 50-348,84/07/12,840028004B Region 2.
- 8407250229 IE info Notice 84-37, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc. 119pp 25865-047 24X Fiche 50-000,84/07/27,8407250229
- B408130345 Requests revised relief from ASME Code. Section XI requests revised relief from ARME Code, Section XI requirements re volumetric exam of charging pump casing welds to hydrostatic test of Class 2 portions of steam generators, per review of inservice insp program Fee encl MCDDNALD, R P Alabama Power Co 84/07/27 VARGA, S A Office of Nuclear Reactor Regulation, Director 5pp 25010 312 24X Fiche 50-364,84/07/27,8408130345
- 8408010333 IE Info Notice 84-59. "Deliberate Circumventing of Station Health Physics Procedures " Syc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24% Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consollidated Edison Co of New York, Inc 123pp 26047 158 24X Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Info Notice 84-61. "Giverexposure of Diver in PWR Refueling Cavity " Svc list encl JDRDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Cansolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000-84/08/08/8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc JN Division of GA. Safeguards & Inspection Programs (Post 3) 84/08/10 Consolidated Edison Co of New York, Inc 26130 001 24X Fiche 50-000.84/08/10.8408070376

- 8408100009 IT Info Notice 84-63. Defective RHR Replacement Piping " HOBIDOON IT THIS SECTION OF EMERGENCY Preparedness & Engineering JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/10 Consolidated Edison Co. of New York, Inc. 119pp 26197 218 24X Fiche 50-000,84/08/10,8408100009
- 8408)0038 IE Info Natice 84-64. "BWR HPCI Initiation Seel-In & Indication " Svc list encl JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co. of New York: Inc. 104pp 26198 093 24X Fiche 50-900:84/08/19,8408100038
- 84081000€1 IE info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc
- B40B100055 IE. Info Notice B4-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svt list encl JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 262/6 001 24% Fiche 50-000.84/08/17,8408100055
- 840B14020B IE Info Natice 84-67. "Recent Snubber Inservice Testing W/ High Failure Rates " Svt list encl JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208 122pn
- 8408210142 IE info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 consolidated Edison Co of New York, Inc 115pp 26327 008 24X Fiche 50-000.84/08/21.8408210142
- V Operator Examinations
- 8408070314 Forwards response to Generic Ltr 84~14 re replacement & requalification training program Encl provides outline & description of simulator utilized in training & requalification program MCDCNALD.R P Alabama Power Co 84/07/26 VARGA.S A Office of Nuclear Reactor Regulation. Director 3pp 25948 002 24X Fiche 50~348.84/07/26.8408070314 Office of
- DDCKET 50-366 EDWIN I HATCH NUCLEAR PLANT, UNIT 2 F Security, medical, emergency & fire protection plans
- 8408308436 Forwards FEMA exercise rept for 831013 exercise DANCE.H C Region 2. Office of Director 84/05/07 KELLY.R Georgia Power Co 1p 26314 247 24X Fiche 50-321,84/05/07,
- --8404040322 Forwards FEMA 840124 ltr forwarding FEMA Region IV rept of 831013 joint exercise Recommends exercise rept be transmitted to licensee & coordination w/FEMA Region IV be continued to ensure deficienties identified corrected JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/13 810HRJ P Division of Emergency Preparedness & Engineering Emergency Preparedness & Materials Safety 2pp 26314 248 24X Fiche 50-321,84/05/07,8408300436
- 8408300352 Confirms arrangements made on 840524 between JT Beckham & HC Dance re 840531 enforcement conference in Region II ofc to discuss 840522 security event rb access controls & events leading to inoperability of HPCI Agenda encl D'REILLY, J P Region 2, Office of Director 84/05/25 KELLY, R J Georgia Power Co 2pp 26314 147 24X Fiche 30-321,84/05/25,8408300352
- 8408300.374 Forwards surmary of 840530 meeting w/utils & INPO re selected emergency preparedness issues Attendance list also O'REELLY, J P Region 2, Office of Director 84/06/08 KELLY, Co 4pp 26308 257 24% Fiche 50-000,84/06/08, Georgia Power Co 8408300376
- B408310057 Documents training & experience for evaluation team members, per B40723 ltr re training requirements for NRC & contract personnel observing B40802 emergency exercise DANCE.H C Region 2, Office of Director B4/07/24 KELLY,R J Georgia Power Co 2pp 26333 332 24X Fiche 50-321.84/07/24, 8408310057

- 8408030163 Revs to emergency plan implementing procedures consisting of Rev 4 to HNP-8024. 'In-Plant Radiation Level Monitoring" & Rev 1 to HNP-8061. Eberline Model PCM-1 Portal Monitor Operation & Calibr ' W/840731 1tr SORRELL.E C Georgia Power Co 84/07/31 38pp 25912 022 24Y Fiche 50-321.84/07/31.8408030163
- 8408130302 Responds to 840302 ltr.supplemented by 840413 ltr.requesting exemption from App E to 10CFR50.excluding state & county participation in 840802 exercise Requested exemption unnecessary New rule requires participation every 2 yrs STOLZ.JF Operating Reactors Branch 4 84/08/01 BECKHAM.J T Georgia Power Co. 3pp 26040 334 24X Fiche 50-321,04/08/01. 8408130302
- B40B090207 Notification of 840B08 meeting w/util in Bethesda.MD to discuss approach for interim measures associated w/schedular exemption request for implementation of App R mods RIVENBARK, C Operating Reactors Branch 4 84/08/03 STOLZ.J F Operating Reactors Branch 4 2pp 25984 360 24X Fiche 50-321.84/08/03.8408090207
- B40B130377 Responds to B40717 request for addl info re submittal of safety parameter display sys info Foxboro Procedures GDAAAO4 & QOAAB44.containing isolation devices pass/fail acceptance criteria.encl GUCWA.L T Georgia Power Co 84/08/07 STOLZ.J F Operating Reactors Branch 4 3pp 26008 203 24x Fiche 50-321,84/08/07. B408130379
- ©408170258 Rev 7 to Emergency Implementing Procedure HNP-4852, "Dffsite Dose Estimations" W/840814 1tr # Georgia Power Co 84/08/14 46pp 26115 297 24X Fiche 50-321.84/08/14.8408170258
- E408210472 Revised emergency plan implementing procedures including Rev 2 to HKP-2-4205 re turbing lube oil reservoir Rev 4 to HKP-4212 re emergency diesel generator bldg & Rev 3 to HKP-1-4216 re reactor bldg Elevation 203 fires W/640816 ltr NIX.H. SORRELL.& C. Georgia Power Co. 94/08/16 246pp 26149 084 24X Fiche 50-321.84/08/16.8408210472
- B40B280233 Revised emergency plan implementing procedures, including Rev 1 to HNP-1-4261 re south CRD & essential MCC area fires & Rev 1 to HNP-1-4263 le reactor water cleanup pump room fire W/B40B24 ltr
  NIX.H : SDRRELL,E C Georgia Power Co 84/08/18 75pp 26269 125
  24X Fiche 50-321.84/08/18.8408280233
- EH408270301 Rev 21 to Emergency Plan Implementing Procedure HNP-8008, "Radiation Work Permit" W/840821 itr SORRELL, C.C. Georgia Power Co. 84/08/21 28pp 26240 337 24X Fiche 30-321,84/08/21,8408270301

#### I Financial information

- EIAOB300072 Forwards draft in furtherance certificate Approval requested in order to meet Internal Revenue Svc requirements for tax-exempt pollution control revenue bonds OUCMAL T Georgia Power Co 84708/20 STOLZ JF Operating Reactors Branch 4 App 25305 357 24% Fiche 50-321.84/08/20, R40830072
- a. Operating license stage documents & correspondence
- 3.408310378 Forwards summary of 840424 meeting re feedwater notife ultrason; c test indications & corrective action necessary for future unit operations Meeting beneficial & provided better understanding of issues.

  LEMIS, R C Region 2: Office of Director 84/05/15 KELLY, R J Georgia Power Co 7pp 26333 321 24X Fiche 50-366.84/05/15, 8408310398
- 408310021 Confirms 840514 telcon re 840521 meeting in Region II ofcs to discuss planned mod to rod block monitoring sys at facility
  LEMIS.R C Region 2. Office of Director 84/05/16 KELLY.R J Georgia Power Co ip 86335 014 24X Fiche 50-321.84/05/16.
  8408310021
- 408300320 Confirms 840522 talcon between J Badgett 5 H Dance re arrangements nade for R Hartin, Region II, Deputy Regional Administrator, to attend 840628 presentation of certificates to licensed operators
  LEMIS, R C Region 2, Office of Director 84/05/27 KELLY, R J Georgia Power Co 1p 26308 328 24X Fiche 50-321, 84/05/27, 84/08300320

- 8408300238 Forwards BRL-NJREG-34709 re cracked vent header pipe Rept supports conclusion that failure caused by impingement of torus inerting nitrogen un vent header Wo encl DANCE.H C Region 2. Office of Director 84/06/19 KELLY.R J Georgia Power Co 1p 26307 014 24X Fiche 50-366,84/06/19. 8408300238
- 8408300421 Forwards summary of 840521 meeting w/util in Region II ofc re APRM sys black monitor sys % Tech Spec activities proposed for Licenses DPR-57 & NPF-5 Attendance list encl LEWIS, R C Region 2. Office of Director 84/06/22 KELLY, R J Georgia Power Co 4pp 26314 217 24% Fiche 50-321,84/06/22, 8408300421
- 8408010122 Returns fee submitted w/840712 license amend application reoperation w/recirculation loop out of svc Only \$130 due under revised fee rule.per 10CFR170 Remittance of \$150 requested DIGGS.R M. License Fee Management Branch 84/07/23 BECKHAM, J.T. Georgia Power Co. 2pp. 25873 267 24% Fiche 50-366.84/07/23, 8408010122
- 8408080178 Informs of review of responses to Generic Ltr 83-02 re Tech Specs for NUREO-0737 items which were to be implemented by 811231 Tech Specs for Item 11 E 4 2 7 have not been provided Response requested within 30 days 870LZ.J F Operating Reactors Branch 4 84/08/01 BECKHAM.J T Georgia Power Ca 2pp 29978 342 24Y Fiche 50-321,84/08/01. 8408080178
- B40B130561 Application for amend to Licenses DPR-57 & NPF-5, revising radiological effluent Tech Specs (RETS) by transferring RETS from App B to App A 2 including editorial & administrative changes & changes based on NRC comments BECKHAM. J T Operating Reactors Branch 4 3pp 26031 001 24X Fiche 50-321.84/08/01, B408130561
- ~-8408130367 Proposed Tech Spec changes, transferring radiological seffluent Tech Specs from App B to App A

  # Georgia Power Co 84/08/01 190pp 26031 004 24X
  Fichs 50-321,84/08/01,8408130561
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl EISENHUT, D @ Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000.84/08/06.8408070110
- 840B090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1784
  TREMBLAY: P P Operating Reactors Assessment Branch 84/08/06
  HDLAMAN: G M Operating Reactors Assessment Branch 13pp 25991 350 24X Fiche 30-000.84/08/06.8408090317
- B40B100045 Application for amend to License NPF-3, revising Tech Spacs to change isolation actuation setpoint for six valves Fee encl
  BECKHAM. J T Georgia Power Co 84/08/06 SYOLZ, J F Operating Reactors Dranch 4 opp 25790 044 24% Fichs 50-346, 84/08/06.
- --8408100049 Proposed Tech Spec Table 3 & 3-1 re primary containment isolation valves, changing isolation actuation setpoint for six valves

  + Quargia Power Co 84/08/05 3pp 25990 050 24X
  Fiche 50-386,84/08/06,8408100045
- 840B130242 Grants extension for qualification of H202 analyzer sysuntil 850331 & for qualification of valves & operations until 851130

  DENTON, H R Office of Nuclear Reactor Regulation, Director 84/06/06 BECKHAM, J T Georgia Power Co App 26040 354 24K Fiche 50-366.84/08/06/8408130242
- 8408140106 Application to amend Licenses BPR-87 & NFF-5, changing Tech Bpecs to reflect implementation of TMI Item II B 3, "Post-Accident Sampling Capability "Fme encl BECKHAM, J T Georgia Power Co 84/08/07 BTOLZ, J F Operating Reacture Branch 4 2pp 26051 252 24% Fiche 50-321,84/08/07,

- BAOBI50242 Responds to 840806 request for add1 info re change to isolation actuation setpoint in Tech Specs for Six valves Proposed among revises Tech Spec isolation setpoint for each valve making setpoint consistent w/original design of plant GUCWA. I T Georgia Power Co 84/08/10 STOLZ. J F Operating Reactors Branch 4 5pp 26067 061 24x Fichs 50-366.84/08/10, 8408150242
- 8408210474 Provides info in support of 840806 request for proposed Tech Spec change re containment isolation valves Request should be treated as energoncy request to avoid under delay in unit startup GUCHA.L T Georgia Power Co 84/08/14 STCLZ.JF Operating Reactors Branch 4 2pp 26181 125 24X Fiche 90-321,84/08/14. 8408210474
- B40B210175 Application for amend to License NPF-5, consisting of corrected pages to Tech Specs on containment isolation valves submitted w/840806 amend request Reactor water level isolation signal changed GUCHA, L. T. Georgia Power Co. 84/08/16. SYCLY, J. F. Operating Reactors Branch 4. 19. 26147-121. 24X Fiche 50-366, 84/08/16, 8408/10175
- --8408210235 Corrected proposed Tech Spec Table 3 & 3-1 re primary containment isolation valves w Georgia Power Co 84/08/16 2pp 26147 122 24X Fiche 50-366,84/08/16,8408210175
- 8408210357 Responds to 840801 itr re NUREO-0737. Item II E 4 2(7), "Purge & Vent Valve Isolation" Revs to Unit 2 Tech Specs expected to be submitted by 840705 Unit 1 mods will be completed during scheduled Fall 1984 refueling outage GUCHAL T Georgia Power Co 84/08/16 \$TOLZ, JF Operating Reactors Branch 4 2pp 26180 241 24% Fiche 50-321,84/08/16,8408210357
- B40B230251 Requests extension until B41107.to respond to request for info re reliability & upgrading of diesel generators.per Generic Ltr 84-15 Extension due to workload at site for Unit 2 recirculation pipe replacement outage CUCWA.L T Georgia Pouer Co B4/0B/16 STGLZ.J F Operating Reactors Branch 4 2pp 26207 293 24X Fiche 50-321.84/08/16, 8408230251
- B40B200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for QLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EIBENHUT. D © Division of Licensing B4/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 50-000.84/08/20.840B200275
- 40B300024 Requests mod to distribution for all plant correspondence Distribution page of recent Tech Spec amond w/requested change encl GUCWA.L.T Georgia Power Co 84/08/22 STGLZ, J F Operating Reactors Branch 4 2pp 26305 183 24X Fiche 50~321,84/08/22, 8460830024
- B408300197 Forwards Amend 40 to License NPF-5, safey evaluation & initial & final NSHC determinations NSHC determinations available in Central Files
  BTGLZ-V F Operating Reactors Branch 4 84/08/22 BECKHAM, J T Georgia Power Co 2pp 26331 307 24X Fiche 50-366, 84/08/22, 8408300197
- --8408300217 Amend 40 to License NPF-5, requiring certain containment isolation values to automatically close upon receipt of lo-lo-lo reactor water level signal, rather than upon receipt of low reactor water level signal SIGILZ.JF Operating Reactors Branch 4 84/08/22 7pp 26331 315 24% Fiche 50-366,84/08/22,8408300197
- --8408300219 Safety evaluation supporting Amend 40 to License NPF-5 PICKETT.D., BUTCHEN.E. Office of Nuclear Reactor Regulation. Director 84/08/22 4pp 26331 322 24X Fiche 50-366.84/08/22.8408300197
- 8408300115 Informs that during startup following current recirculation pipe replacement outage, util will invoke special test exception Tech Spec 3 10 4 re operability of recirculation loop OUCHAL T Georgia Power Co. 84/08/23 BTDLZ.J F Operating Reactors Branch 4 2pp 26305 169 24X Fiche 50-366,84/08/23.8408300115

- Q Inspection reports. IE Bulletins ! correspondence
- B4082B01B3 Responds to JE Bulletin 80-13. "Cracking in Core Spray Sbargers" No cracking observed in spangers or in-vessel priping during 1984 maint/refueling outage insp GUCHAL T Georgia Power Co. 84/05/07 O'REILLY, J.P. Region 2 Office of Director ip 26269-359 24X Fiche 50-366,84/05/07, mann2801B3
- 8408240356 Forwards Insp Repts 50-321/84-21 to 50-366/84-21 on 840611-15 No violations or deviations noted DANCE.H C Region 2. Office of Director 84/07/10 KELLY.R J Georgia Power Co 2pp 26237 040 24% Fiche 50-321,84/07/10,8408240354
- --8409240357 Insp Repts 50-321/84-21 & 50-364/84-21 on 840611-15 No violations or deviations noted Major areas inspected worker concerns re Newport News Industries recirculation pipe replacement project MERRIMEATHER.N. C
- 8408240364 Forwards Insp Repts 50-321/84-23 & 50-366/84-23 on 840618-22 No violations or deviations noted Unresolved items identified will be pursued during future imaps DANCE, H C Region 2. Office of Director 84/07/11 KELLY, R J Ogorgia Power Co 2pp 26237 080 24X Fiche 50-321,84/07/11.
- --8409240366 Insp Repts 30-321/84-23 & 50-366/84-23 on 840618-22 No violations or deviations noted Major areas inspected evaluation of ultrasonic test indications in feedwater weld 2821-1FW-12AA-12 (Unit 2) CROWLEY, B R, COLEY, J L, BLAKE, J J, Region 2, Office of Director 84/07/10 12pp 26237 OB2 24x Fiche 50-321,84/07/11, 8408240364
- B408280239 Advises of plans & schedules for replacing HFA relays in reactor protection & safety system IE Bulletin 84-02 GUCWALL T Georgia Power Co 94/07/13 0'REILLY.J P Region 2. Office of Director 4pp 26262 237 24X Fiche 50-321.84/07/13.
- 8408270241 Ack receipt of 840709 itr informing NRC of steps taken to correct violations noted in Insp Repts 50-321/84-13 & 50-364/84-13 LEWIS.R C Division of Project & Resident Programs 84/07/20 KELLY.R J Georgia Power Co ip 26258 086 24% Fiche 50-321,84/07/20,8408270241
- --8408270247 Responds to NRC 840607 ltr rg violations noted in Insp Repts 50-321/84-13 & 50-366/84-13 Corrective actions GC dept will witness significant activities for safety-related major maint GUCWA, L T Georgia Power Co 84/07/09 D'RCILLY, J P Region 2, Office of Director 3pp 26258 087 24X Fiche 50-321,84/07/20,8408270024
- --BA08270255 Forwards Insp Repts 50-321/84-13 & 50-366/84-13 on B40321-0420 & notice of violation LEMIB.R C Division of Project & Resident Programs 84/06/07 KELLY.R J Georgia Power Co 2pp 26258 090 24X Ficha 50-321,84/07/20,8408270241
- --8408270269 Insp Repts 50-321/84-13 & 50-366/84-13 on 840321-0420 Violation moted failure to restore sys to original design requirements CRLENJAK.R V , RAY-HOLMES.P , GARNER.L. Region 2. Office of Director 84/06/05 7pp 26258 094 24X Fiche 50-321,84/07/20,8408270241
- --8408270261 Notice of vialation from insp on 840321-0421 \* flegion 2, Office of Director 84/06/07 2pp 26258 092 24X Fiche 50-321,84/07/20,8408270241
- B40B270334 Forwards Insp Repts 50-321/B4-25 & 50-366/B4-25 on B40619-22 No violations or deviations noted DANCE-H C Region 2. Office of Director B4/07/20 KELLY.R J Georgia Power Co 2pp 26257 206 24X Fiche 50-321.84/07/20, B40B270334
- --B40827093B Insp Repts 50-321/84-25 & 50-366/84-25 on 840619-22 No violations or deviations noted Major areas inspected review of local leak rate test program & followup of previous violation WHITENER. H L , JAPE, F Region 2. Office of Director 84/07/19. 6pp 26257 208 24X Fiche 50-321,84/07/20,8408270334

- 8407250229 IE Info Notice 84-97, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York Inc 119pp 25865 047 244 Fichs 50-000.84/07/27.840/250229
- 8408070141 Forwards discussion of exams conducted on six inlet & outlet notiles & safe-end & recirculation sys jet pump instrumentation inconel 182 notiles Exams prompted by cracking problems discussed in 1E info Notice 84-41 GUCHA.L T Georgia Power Co 84/07/27 STOLZ.JF Operating Reactors Branch 4 Spp 23950 029 24% Fiche 50-366,84/07/27, 8408070141
- 8408010333 IC Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830107) 84/08/00 Consolidated Edison Co. of New York, Inc. 122pp 26068 001 24% Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Natice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list enci JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc. 123pp 26067 158 24X Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York Inc. 120pp 26129 118 24X Fichs 50-000.84/08/08,8408070120
- 8408070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list enc: ORACE.J N Division of QA. Safeguards & Inspection Programs (Post B30103) 84/08/10 Consolidated Edison Co of New York. Inc 125p 26130 001 24x Fiche 50-000.84/08/10.8408070376
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list end! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc. (19pp. 26197-218 24% Fiche 30-000,84/08/13,8408100009
- 8408100038 IE Info Notice 84-64. "BUR HPCI Initiation Seal-In & Indication " Svc list enc]
  JORDANIC L Division of Emergency Proparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 104pp 26178 093 24X Fiche 50-000,84/08/15,8408100038
- 8408100021 IE Info Notice 84~65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl
  JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 1188p 26198 001 24X Fiche 50-000, 84/08/16,8498100021
- 840B100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list and JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 OOI 24X Fiche 30-000,84/08/17,8408100055
- 8408140208 IE Info Notice 84-67, "Recent Bnubber Inservice Testing W/ High Failure Rates" Svc list encl JORDAN E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/17, Consolidated Edison Co. of New York, Inc. 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-A8, "Potential Deficiency in Improperly Rated Field Wiring to Solonoid Valves " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 630103) 84/08/21 Consolidated Edison Co of New York, Inc (13pp 26329 008 24X Fiche 50-000.84/08/21.8408210142
- R Periodic operating reports & related correspondence
- 8408200001 Monthly operating repts for Jul 1784 W/840802 ltr NIX:H C Georgia Power Co 84/07/31 15pp 26140 266 24X Fiche 50-321.84/07/31.8408200001
- 8 Reportable occurrences, LERs & related correspondence
- 8408240348 Part 21 rept re presente of Loctite-242 in CRD hydravlic control unit scram pilot solemoid valve plunger Initially reported on 840413 New thread locking devices investigated SHERWOOD. G @ General Electric Co 84/04/13 DEYOUNG. R C Director's Office. Office of Inspection and Enforcement 3pp 26222 236 24% Fiche 50-000.84/04/13.8408240348

- 8408070076 Advises of completion of review of AEUD/C403, "Case Study Rept for EI Hatch.Unit 2 Plant Sys Interaction Event on 820825" Case study recommends event be considered in developing final positions relative to MUREC-0803 DENTON.H R Office of Nuclear Reactor Regulation. Director 84/07/30 H&LTEMES.C U Director's Office 2pp 25935 272 249 Fiche 50-366.84/07/30.8408070076
- --840&010162 Forwards case study rept of 820825 plant sys interaction event Comments requested M/o encl
  HELTEMES, C. J. Director's Diffice 84/05/18 DENTON, H.R. Office of Nuclear Reactor Regulation, Director DEYDUNG, R.C. Director's Office, Office of Inspection and Enforcement 2pp 25955 273 24X Fiche 90-366, 84/07/30, 8408070076
- 8408200438 LER 84-009-00 on 840711, unplanned automatic activation logic of more than one ESF occurred Caused by defective rev to NNP-2-3191 Procedure revised to prevent unplanned logic actuation N/840810 ltr ELTON.T L. NIX.H C Georgia Power Co 64/08/10 3pp 26139 060 24X Fiche 50-366,84/08/10,8408200438
- 8408220491 LER 84-006-00 on 840716, control rod hoist operation performed w/o demonstration operation of hoist interiock All hoist use suspended Procedure revised W/840814 ltr ELTON, T L , NIX.H C Georgia Power Co 84/08/14 3pp 26196 026 24X Fiche 50-366,84/08/14,8408220491
- 8408310196 Part 21 rept re torus-to-reactor bidg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
  VILLA.R General Electric Co 84/08/21 ROSSI.C E Director's
  Office, Office of Inspection and Enforcement 3pp 26318 327 24x
  Fiche 50-000.84/08/21,8408310186
- 8408300517 LER 84-008-01 on 840327, personnel found turbine bldg area temp FT&C Procedure HNP-2-3725 inadequate in meeting monthly channel functional test in Tech Specs Caused by procedural inadequacy due to personnel error H/B40823 ltr TIPPB, S B , NIX.H C Qeorgia Power Co 84/08/23 3pp 26313 348 24X Fiche 30-366, 84/08/23, 8408300517

### POCKET 50-347 BAILLY GENERATING STATION

## 0 Adjudicatory correspondence

0408280194 Requests response re resolution of 820604 application for fees & expenses under Equal Access to Justice Act Payment clearly authorized by 3080504(d)(1) No issue exists to Commission granting petition Related correspondence WHICHER. J M Businessmen for the Public Interest WHICHER. J M Whicher, J M DSB 329 84/08/22 CRANE, P Defice of the General Counsel 2pp 26275 192 24X Fiche 50-367.84/08/22.8409280194

## H General correspondence

- 8405180145 Responds to 840314 ltr to Chairman Palladino which encl W & V Smelser concern re Marble Hill & Bailly cancellation, withdrawal of util application for Zimmer & denial of license for Ilyron facility DIRCKS,W J Office of the Executive Director for Operations 84/05/04 LUQAR,R Q Senate 70p 24524 325 24X Fiche 50-000,84/05/04,8405180145
- --B405180152 Requests response to encl W & V Emelser B40210 inquiry into NRC attitude toward utils Concerns include Marble Hill & Bailly cancellation, withdrawal of util application for Zimmer & denial of license for Byron facility LUGAR, R O Emnate B4/03/14 PALLADIND. N Commissioners 3pp 24524 331 24X Fiche 50-000,84/05/04.8405180145

#### DOCKET 50-368 ARKANSAS NUCLEAR DNE. UNIT 2

#### F Security, medical, emergency & fire protection plans

- 8408160498 Forwards IE Insp Repts 50-319/84-20 & 50-368/84-20 on 840619-22 No violations or deviations noted HUNTER, D R Region 4. Office of Director 84/07/23 GRIFFIN, J M Arkansas Power & Light Co 2pp 26107 318 24X Fiche 50-313,84/07/23.8408160498
- --8408160504 IE Insp Repts 50-313/84-20 & 50-368/84-20 on 840619-22 No violations or deviations noted Major areas inspected security program audit & physical barriers Details withheld (ref 10CFR73 21)
  EVANB/C A Region 4. Office of Director 84/07/23 lp. 26107 320 24X Fiche 50-313.84/07/23.8408160498

- 8408280184 Forwards "Reanalysis Against 10CFR30. App R. Sections III G.J & O." per 830328 & 0712 requests for exemption from 10CFR30 48(c) schedule for barriers, penetrations & suppression/detection sys for approx 1 yr MARSHALL.JR Arkansas Power & Light Co 84/08/15 STCLZ,JF Operating Reactors Branch 4 MILLER.JR Operating Reactors Branch 3 2pp 26287 144 24X Fiche 50-313,84/08/15,8408280184
- --8409280188 "Reanalysis Against 10CFR50, App R. Sections 111 G.J & O "

  \* Arkansas Power & Light Co 84/08/15 120pp 25287 146 24X
  fiche 50-313, 84/08/15, 8408280184
- 8408230401 Revised Emergency Procedures 1903 72 re St Marys Hosp, 1903 73 re Millard-Menry clinic & 1903 74 re Pope County ambulance svc \* Arkansas Power & Light Co 84/08/16 7pp 24206 001 24X Fiche 50-313,84/08/16 8408230401
- B408230417 Deletion of Rev O to Procedure 1903 34, "Administration of Potassium Indide"

  \* Arkansas Power & Light Co 84/08/29 3pp 26204 011 24X
  Fithe 50-313.84/08/29,8408230417
- P Operating license stage documents & correspondence
- 8408020031 Informs of planned nod to C-E control element assembly guide tube wear sleeve Hod includes relocation of sleeve flare-sleeve expansion over full length of sleeve & relocation of crimp.providing resistance to axial motion BCHERER.A E Combustion Engineering. Inc 84/07/27 RUBENSTEIN.L E Assistant Director for Core & Plant Systems 2pp 25880 298 24% Fiche 50-000,84/07/27,8408020031
- B408070483 Forwards Rev & to QA manual operations Return receipt requested MARBHALL, J Arkansaa Power & Light Co B4/07/31 Retord Services Branch (Document Control Desk) ip 25941 215 24X Fiche 50-313:84/07/31.8408070483
- --8408070485 Rev 6 to GA manual operations # Arkansas Power & Light Co 84/05/30 15Bpp 25941 216 24X Fiche 50-313,84/07/31,8408070483
- 840B130367 Summarizes 840712 meeting w/NRC. Technology for Energy Corp & Boan Power in Bethesda, MD re inadequate core cooling instrument installation Supporting documentation encl MARSHALL.J R Arkansas Power & Light Co 84/08/01 MILLER, J R Operating Reactors Branch 3 35pp 2605 302 24X Fiche 50~368,84/08/01,840B130367
  - JB200219 Denies B30927 request to revise Tech Space re containment hydrogen analyzers Present calibr requirement preferred because of more accurate hydrogen concentration measurement MILLER. J. R. Gperating Reactors Branch 3 84/08/01 GRIFFIN, J. M. Arkansas Power & Light Co. 2sp. 26142 286 24X Ficha 50-368,84/03/01.8408200219
- 408070110 Opneric Ltr 84-19 to all licensess of operating reactors, applicants for DLs & holders of CPs re availability of Suppl 1 to NUREO-0939, "Prioritization of Generic Safety Issues" Byt list encl EISENHUT,D 6 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24% Fiche 50-000,84/08/06,8408070110
- 8408140328 Documents resolution of environ qualification deficiencies identified in SER & discussed at 840426 meeting Matrix of qualification deficiencies & proposed resolution & justification for continued operation encl MARSHALL.JR Arkansas Power & Light Co 84/08/06 MILLER, JR Operating Reactors Branch 3 80pp 26043 317 24% Fiche 50-368,84/08/06.8408140328
- 8408140355 Forwards corrected cover sheets for Copies i-6 of Rev 6 to "QA Manual Operations" MARSHALL, J R Arkansas Power & Light Co 84/09/06 Record Services Branch (Document Control Desk) 7pp 26041 037 24X Fiche 50-313,84/08/06,8408140355
- B40B170061 Forwards corrected coversheet for Rev & to QA manual operations Revised coversheet reflects Control Copy 7 MARSHALL, J R Arkansas Power & Light Co 84/08/06 ANKRUM, 0 T GA Brench. 4pp 26119 018 24X Fiche 30-313-84/08/06,840B170061
- 8408200303 Informs that response to Recommendation GL-2 re inadvertent closure to condensate storage tank isolation valve (NUREO-0737: Item II E i i) will be delayed until E40824 due to dutage greparation work:
  MARSHALL, J R Arkansas Power & Light Co 84/08/10 8TGLZ, J F, Operating Reactors Branch 4 ip 26133 358 24X Fiche 50-313,84/08/10-8408200303

- 8408280033 Summary of 840712 meeting w/wtil. Technology for Energy Corp & Scandpower in Bethesda. MD re inadequate core cooling manitoring sys.installation schedule.praject status & preliminary test results Viewgraphs encl

  LEE.R S Deerating Reactors Branch 3 84/08/17 Operating Reactors Branch 3 35pp 26293 121 24X Fiche 50-368.84/08/17, 8408280033
- B40B200275 Generic Ltr B4-20 to all licensees of operating reactors & applicants for GLs re schoduling guidance for licensee submittals of reloads that involve unreviewed safety questions Bvc list encl EISENHUT.D 9 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000.84/08/20.840B200275
- 8408310231 Forwards revs to proposed Tech Spec changes for NUREG-0737 items re containment radiation monitors & post-accident sampling, per Oeneric Ltr 83-37 GRIFFIN.J M Arkansas Power & Light Co 84/08/22 STOLZ, J F Operating Reactors Branch 4 12pp 26020 314 24x Fiche 50-313.84/08/22.8408310231
- O Inspection reports. IE Bulletins & correspondence
- 8408130372 Forwards IE Insp Repts 50-313/84-11 & 50-369/84-11 on 840326-29 & notice of violation One unresolved item re maint program identified in Paragraph 2 of insp rept should be addressed in detail JOHNSON,E H Region 4, Office of Director 84/05/16 GRIFFIN,J M Arkansas Power & Light Co 2pp 26/05/18 24X Fiche 50-313,84/05/16,8408150372
- --B408150375 IE Insp Repts 50-313/84-11 & 50-368/84-11 on 840324-30 Violations noted failure to document & follow procedures for maint of MSIVs & HPCI valves BOARDHAN, JR., JOHNSON, W.D., JAUDON, J.P. Region 4, Office of Director 84/05/16 App 26075 185 24X Fiche 50-313,84/05/16,8408150372
- 8408090150 Forwards IE Insp Repts 50-313/84-18 & 50-368/84-18 on 840601-30 No violations or deviations identified JOHNSON, E H Region 4, Office of Director 84/07/11 GRIFFIN, J M Arkansas Power & Light Co. 2pp. 25993 178 24X Fiche 50-313,84/07/11,8408090150
- --B408090160 IE Insp Repts 50-313/84-18 & 50-368/84-18 on 840601-30 No violations identified Major areas inspected maint, surveillance, operational safety verification & Followup on IE bulletins & Generic Ltr 83-28

  JOHNSON, D , HARRELL, P H , MARTIN, L E Region 4, Diffice of Director 84/07/11 | 11pp | 25993 180 | 24% Fiche 50-313,84/07/11,8408090150
- 8408090121 Forwards IE Insp Repts 50-313/83-35 & 50-369/83-35 on 831205-08 & notice of violation W/a natice of violation HUNTER,D R Region 4. Office of Director 84/07/17 GRIFFIN,J M Arkansas Fower & Light Ca 2pp 25973 148 24X Fiche 50-313.84/07/17.8408090121
- ~-B408090130 IE Insp Repts 50~319/83~35 & 50~368/83~35 on 831205~08 Noncompliance noted failure to verify that matls conform to procurement documents ELLERSHAW, L E. JOHNSON, W D. BARNES, I Region 4. Office of Director B4/02/21 9pp 25993 150 24X Fiche 50~313,84/07/17. B408090121
- 840Bi30312 Ack receipt of B40619 ltr informing NRC of steps taken to correct violations noted in IE Inap Repts 50-313/B4-11 & 50-36Bi48-11 Future insp will determine if corrective actions achieve compliance
  JOHNSON,E H Region 4, Office of Director B4/07/23 GRIFFIN, J M Arkansas Power & Light Co. ip. 24074, 350 24X
  Fiche 50-313.84/07/23.840Bi50312
- --B408150317 Responds to NRC B40516 ltr re violations noted in IE Insp Repts 50-313/84-11 & 50-368/84-11 Requests add1 time to complete response to items noted in rept Response will be forwarded by 840629 MARSHALLJR Arkansas Power & Light Co 84/06/15 DENISE,R P Division of Resident, Reactor Project & Engineering Programs ip 26074 351 24X Fiche 50-313,84/07/23,8408150312
- 8408160498 Forwards IE Insp Repts 50-313/84-20 & 50-368/84-20 on 840619-22 No violations or deviations noted HUNTER, D.R. Region 4, Office of Director 84/07/23 GRIFFIN, J.M. Arkansas Power & Light to 2pp 26/07 318 24X Fiche: 50-313,84/07/23,8408160498

- --8408160504 IE Insp Repts 50-313/84-20 & 50-368/84-20 on 840619-22 No violations or deviations noted Major areas inspected security program audit & physical barriers Details withheld (ref 104F73 21)

  EVANS.C A. HULL.R E , MARTIN.L C Region 4, Dffice of Director 84/07/23 1p 26107 320 24% Fiche 50-313,84/07/23,8408160498
- 8408090022 Discusses IE insp on 831205-08 & forwards notice of violation & proposed imposition of civil penalty Util failed to apply controls for procurement & installation of safety-related fasteners, per App B to 10CFR50 W/o encl COLLINS.J T Region 4, Office of Director 84/07/25 GRIFFIN.J M Arkansas Power & Light Co 5pp 25992 089 24X Fiche 50-313.84/07/25.8408090022
- 8407250227 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants "Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/407/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000.84/07/27, 8407250227
- B408080055 Forwards summary statement of IAEA insplactivities from Oct 1983 to Mar 1984, for review Requests confirmation in 30 days concerning proprietary status of documents Info withheld (ref 10CFR2 790)
  MILLER, J R Operating Reactors Branch 3 84/07/27 GRIFFIN, J M Arkansas Power & Light Co 2pp 25981 070 24X
  Fiche 50-368,84/07/27,8408080055
- 8408290113 Forwards exam rept of exam administered on 840718 HUNTER,D R Region 4. Office of Director 84/08/01 GRIFFIN,J M Arkansas Power & Light Co. Zpp. 26297-250 24X Fiche 50-368,84/08/01,8400290113
- --B408270115 Exam rept administered on 840718 Exam results senior reactor operator & reactor operator passed MCCRORY,S L. COOLEY,R A Region 4, Office of Director 84/08/01 22pp 26297 252 24X Fiche 50-368,84/08/01,8408270113
- 8408270172 Forwards exam rept administered on 840614-15 HUNTER, D.R. Region 4. Office of Director 84/08/01 CRIFFIN, J.M. Arkansas Power & Light Co. 2pp. 26277 001 24X Fiche 50-368,84/08/01.8408270172
- --8408270176 Exam rept administered on 840614-15 Exam results all candidates passed MCGRORY.S L , COULEY.R A Region 4. Office of Director 84/08/01 17pp 26277 003 24X Fiche 50-368.84/08/01.8408270172
- 8408010333 IC Info Natice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/04 Consolidated Edison Co. of New York, Inc. 122pp 26068 001 24% Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Byo list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York Inc. 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84~61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering R#sponse (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- 8408070374 IE Info Notice 84-62, "Therapy Misedministrations to Pattants Undergoing Co-60 Teletherapy Treatments" Svc list enc! ORACE.J N Division of OA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000 84/08/10,8408070376
- 840Bi00007 IE Info Notice 84-63, "Defective RHR Replacement Piping " 8vc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/08/13 Consolidated Edison Co of New York, Inc. 119pp 26197 21B 24X Fiche 50-000,84/08/13,8408100009
- 8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication "Sec list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Cansolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 30-000,84/08/15,8408100038

- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl
  JURDAN, C. L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/16 Consolidated Edison Co of New
  York, Inc. 118pp 26198 001 24X Fiche 50-000,04/08/16,8408100021
- 8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Drivem Auxiliary Feedwater Train " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276, 001 24% Fichs 50-000,84/08/17,8408100055
- 8408140208 IE Info Nutice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24% Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solemoid Valves " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24% Fiche 50-000,84/08/21,8408210142
- 8408300154 Requests withdrawal of 840725 notice of violation & proposed imposition of civil penalty Corrective actions initiated prior to enforcement action, including augmenting GA staff.retraining GC staff & increasing vendor surveys MARSHALL.JR Arkansas Fower & Light Co 84/03/24 DEYQUNO.R C Director's Office, Office of Inspection and Enforcement 3pp. 26304 257 24X Fiche 50-313,84/08/24.8408300154
- --8408300160 Licensee response to 840725 notice of violation Violation admitted & corrective actions outlined \* Cammissioners 84/08/24 12pp 26304 260 24% Fiche 50-313,84/08/24,8408300154
- --8408300166 Licenses ansuer protesting 840725 civil penalty Notice of violation fails to allow for corrective actions initiated prior to enforcement action

  \* Commissioners 84/08/24. 10pp 26304 272 24X
  Fichs 50-313,84/08/24.8408300154
- 8 Reportable occurrences, LERs & related correspondence
- 8408040187 LER 84-014-00 on 840618, reactor turbine trip occurred at approx 8% full power due to high level in steam generator A Caused by main feedwater bypass regulating valve E/P converter malfunction W/840717 ltr
  MARSHALL, J R. ROGERS, P.C. Arkansas Power & Light Co. 84/07/17 3pp 25935 187 24% Fiche 50-348,84/07/17,8408040187
- 8408080528 LER 84-013-00 on 840617 reactor tripped from full power on low DNBR due to penalty factors generated by core protection calculators Caused by dropped control element assembly W/840717 ltr RUGERB, P. C., MARSHALL, J. R. Arkansas Power & Light Co. 84/07/17 3pp 25975 295 24X Fiche 50-366.84/07/17:8408080528
- 840808080 LER 84-016-00 on 840621 penetration fire barrier damper mfg by American Warming & Ventilating, Inc. failed to completely close upon fusible link removal Caused by metal shaving on pivot section of damper blades W/840723 ltr LOMAX D B , MARSHALL. J R Arkansas Fower & Light Co 84/07/23 3pp 25975 237 24X Fiche 50-368,84/07/23,8408080500
- 8408080512 LER 84-015-00 on 840302, breach of required fire barrier identified Add1 breach identified on 840622 Caused by inadequate evaluation during priginal review Fire watches established Repairs underway W/840723 ltr CAMPDELL.P L , MARSHALL, J. R Arkansas Power & Light Co 84/07/23 3pp 25775 264 24X Fiche 50~368,84/07/23,8408080512
- 8408080493 Updated LER 80-026/03X-1 on 800514, control room emergency air canditioner compressor trip occured on freeze protection Caused by insufficient load when providing cooling from core protection calculator room W/840724 ltr ROGERS, P. MARSHALL, J. R. Arkansas Power & Light Co. 84/07/24 3pp 25975 202 24X Fiche 50-368.84/07/24,8408080493
- 8408240077 LER 84-017-00 on 840713, fire barrier penetration 2124-0004 discovered degraded by engineering personnel while working on HVAC mods Fire watch established Barrier repaired W/840813 ltr CAMPBELL.P L, MARSHALL.J R Arkansas Power & Light Co 84/08/13 2pp 26236 139 24X Fiche 50-368.84/08/13.8408240077

- 8408240080 LER 79-086/037-2 on 791013 during Mode 6 shutdown cooling HX 2E358 radiation monitor increased & small vol tube leak indicated in HX Cause not stated HX examined & plugged W/ 840815 ltr MARSHALL.J R Arkansas Power & Light Co 84/08/15 5pp 26237 018 24X Fiche 50-368, 84/08/15, 8408240080
- 8408300475 LER 84-018-00 on 840718 operator discovered train B sodium hydroxide pump (2P136B) nanual discharge isolation valve (288-118) in locked closed position Caused by failure to reposition valve following 840618 surveillance W/840820 ltr LOMAX D B , MARSHALL, J R Arkansas Power & Light Co 84/08/20 3pp 26314 006 24% Fiche 50-368.84/08/20,8408300475
- B40B300496 LER 84-019-00 E40720, manual reactor trip initiated from 100% full power following spurious half-leg trip Caused by operator inadvertently pressing alternate source to load button instead of reset button W/B40B20 ltr RGGERS, P. MARSHALL, J. R. Arkansas Power & Light Co. 84/08/20 2pp 26314 069 24% Fiche 50-368.84/08/20.840B300496
- V Operator Examinations
- 8408290113 Forwards stam rept of exam administered on 840718 HUNTER, D. R. Region 4, Office of Director 84/08/01 GRIFFIN, J. M. Arkansas Power & Light Co. 2pp. 26297-250 24X Fiche 50-368, 84/08/01. 8408290113
- --8408290115 Exam rept administered on 840718 Exam results senior reactor operator 5 reactor operator passed MCCRORY,9 L., COOLEY,R A Region 4, Office of Director 84/08/01 22pp 26297 252 24X Fiche 50~348, 84/08/01, 8408290113
- 8408290172 Forwards exam rept administered on 840614-15 HUNTER,D R Region 4. Office of Director 84/08/01 GRIFFIN,J M Arkansas Fower & Light Co 2pp 86297 001 24X Fiche 50-368,84/08/01.8408290172
- --8408290176 Eram rept administered on 840614-15 Exam results all candidates passed MCCRORY. 6 L. COOLEY, R. A. Region 4, Office of Director 84/09/01 19pp 24297 003 24X Fiche 50-368,84/08/01,8408290172
- POCKET 50-369 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 1

  Security, medical, emergency & fire protection plans
- 18300193 Forwards 840612 ltr detailing overall planning for 840620 Tench security team visit to facility Biographica) info for each team member included LEWIS.R C Region 2. Office of Director 84/06/13 TUCKER.H B Duke Power Co 1p 26300 139 24X Fiche 50-000.84/06/15.
- B40B300204 Requests authorization for six French security experts hosted by NRC to visit McGuire facility on B40620 & Sequoyah facility on B40620 Biographical info & itinerary encl LAPLEUR. J D Office of International Programs. Director B4/06/12 TUCKER. H B Duke Power Co PARRIS. H G Tennessee Valley Authority Spp 26300 140 24X Fiche 50-000.84/06/15.8408300173
- 3408270444 Forwards Insp Repts 50-369/84-19 & 50-370/84-16 on \$40709-13 No violations or deviations noted DANCE.H C Region 2. Office of Director 84/07/24 TUCKER.H B Duke Power Cn 2pp 26236 353 24% Fiche 50-369.84/07/24, 8408270444
- --8408270447 Insp Repts 50-369/84-19 & 50-370/84-16 on 840709-13 No violations or deviations noted Major areas inspected health physics organizations, staff qualifications solid radwaste mgt, transportation of radioactive matls & ALARA program WRAY, J. R. JENKINS, G. R. Region 2, Office of Director 84/07/24 App. 26256 355 24X Fiche 50-369,84/07/24,8408270444
- 8408070278 Informs that requested info re detailed control room design review provided in licensee 840409.0525 & 0216 submittals, per Suppl i to NUREG-0737 Task analyses for inadequate cone cooling & ATMS event conducted during control room review TUCKER.H B Duke Power Co 84/07/27 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENBAM.E G Licensing Branch 4 2pp 25947 275 24X Fiche 50-369.84/07/27.8408070278
- 8408200100 Forwards deviations & technical justifications from App R criteria.per fire protection program review TUCKER.H B Duke Power Co 84/08/03 DENTON.H R. Office of Ucclear Reactor Regulation, Director ABENBAME G Licensing Branch

- 8408300357 Confirms 840806 telcon w/JP O'Reilly re 840815 meeting in Region II ofc to discuss design & operation of standby shutdown facility concerning App R to 10CFR50. fire protection % 10CFR73. physical protection Agenda encl LEWIS.R C Region 2. Office of Director 84/08/08 TUCKER, R B Duke Power Co 3pp 26314 222 24X Fiche 50-000.84/08/08, BA08300357
- 8408300014 Forwards public version of Rev 13 to crisis mgt plan & revised emergency plan implementing procedures
  TUCKER.H B Duke Power Co 84/08/10 Record Services Branch
  (Document Control Desk) 21pp 26332 353 24X
  Fiche 50~000.84/08/10.8408300014
- --8408300021 Public version of Rev 13 to "Crisis Mgt Plan for Nuclear Stations"

  # Duke Power Co 84/08/15 30pp 26333 010 24X
  Fiche 50-000,84/08/10,8408300014
- --B408300028 Public version of revised crisis mgt plan implementing procedures including 5 3 1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group W/Felton 840823 memb buke Power Co 84/08/15 170pp 26333 040 24x Fiche 50-000,84/08/10,8408300014
- I Financiel information
- B40B240224 Forwards Duke Power Co & North Carolina Municipal Power Agency 1 1983 annual repts
  TUCKER.H D Duke Power Co B4/0B/16 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E G Licensing Branch 4 2pp 26237 137 24x Fiche 50-000.84/0B/16.8408240224
- --8408240239 "1983 Annual Rept "
  CLAY, G W . SHAW, R W North Carelina Municipal Power Agencies
  83/12/31 27pp 26237 139 24X Fiche 50-000, 84/08/16, 8408240224
- --8408240242 "1983 Annual Rept " LEE,W S , BOOTH.D W Duke Power Co 83/12/31 47pp 26237 167 24X Fiche 50-000,84/08/16,8408240224
- J Insurance & indomnity information
- 8408220148 Forwards Endorsement 13 to NEL1A Policy NF-281 & Endorsement 7 to MAELV Policy MF-112 DUBMAL.A Marsh & McLennan, Inc. 84/08/14 DINITZ, I Assistant Director for State & Licensee Relations 3pp 26188 071 24X Fiche 50-369,84/08/14.8908220148
- P Operating license stage documents & correspondence
- 8408160425 Summary of 840720 meeting w/utils & Westinghouse re containment analysis & superheat effects on environ qualification WIGGINTON, D. L. Operating Reactors Branch i 84/07/30 Operating Reactors Branch i 4pp 26143 265 24X Fithe 50-000, 84/07/30, 8400160425
- B40B030130 Application for amend to Licenses NPF-9 & NPF-17, changing Tech Specs to provide operability & surveillance requirements for add1 subcooling margin monitor sys channel & reactor vessel level instrumentation sys than to the control of t
- --8408030139 Proposed Tech Specs providing operability & surveillance requirements for addl subcooling margin monitor sys channel & reactor vessel level instrumentation sys # Puke Power Co 84/07/31 4pp 29916 132 24X Fiche 50-369,84/07/31,8408030130
- 8408130169 Forwards description & justification for proposed piping seismic analysis changes, adopting damping values & spectra shifting methods for piping sys.per HRC recommendations, for review/approval TUCKCR: H B Duke Power Co 84/08/01 DENTON. H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 3pp 26010 027 24% Fiche 50-369,84/08/01.8408130169
- B40B070468 Forwards proprietary add1 info re spent fuel pool two region rerack mods, addressing concerns raised during B40731 meeting Affidavit uill be submitted by Westinghouse Info withheld (ref 10CFR2 790)
  TUCKER.H B Duke Power Co B4/0B/02 DENTON,H R Office of Nuclear Reactor Regulation. Director ADENSAM,E O Licensing Branch 4 1p 25941 194 24x Fiche 50-369.84/0B/02,84/0B/07,84/0B/07488

- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933. 'Profit in a Generic Safety Issues " Svc list encl EISENHUT, D © Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fichs 50-000.84/08/04.8408070110
- 8408160050 Forwards summary evaluation of main steam line break analysis for both inside containment & in doghouse Plant safety would not be adversely affected in event of design basis main line break in doghouse or inside containment TUCKER.H B Duke Power Co 84/08/08 DENTON.H R Diffice of Nuclear Reactor Regulation, Director ADENSAM.E G Licensing 4 7pp 26092 068 24X Fiche 50-369,84/08/08,8408160050 Licensing Branch
- 8408160174 Forwards corrected page to 840802 addl info attachment respent fuel pool two region remark mods Only Page 1 of attachment considered proprietary to Uestinghouse TUCKER.H B Dyke Power Co 84/08/13 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENBAM.E 9 Licensing Branch 4 2pp 26092 034 24X F; the 50-369,84/08/13,8408160174
- 8408230527 Forwards payment for application fee re 840802 & 08 Tech 408230327 Forwards payment for uppression.

  Spec changes

  BARR, S Duke Power Co 84/08/15 DENTON, H R Office of Nuclear

  Reactor Regulation, Director 1p 26236 286 24x

  Fiche 50-000,84/08/15,8408230527
- 8408270160 Forwards Rev 4 to "Offsite Dose Calculation Manual," incorporating Catawba calculation info Rev submitted prior to submittel of semiannual radioactive effluent release rept for Jul-Dec 1984 TUCKER, H B Duk for Jul-Dec 1984 TUCKER, H B Duke Power Co 84/08/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26279 112 24X Fiche 50-000.84/08/16.8408270160
- --8409270169 Rev 4 to "Offsite Dose Calculation Manual"
  BIRCH: M L Doke Power Co 64/07/18 39pp 26279 114 24X
  Fiche 50-000,84/08/16,8408270160
- 8408210396 Forwards info documenting results of review & implementation of required changes & mods, per Generic Ltr 81-07, "Control of Heavy Loads" & NUREO-0612 Minor error noted in 801222 ltr corrected
  TUCKER.H B Duke Power Co. 84/08/17 DENTON.H R Office of
  Nuclear Reactor Regulation, Director ADENSAM.E G Licensing Branch
  4 36pp 26180 271 24X Fiche 50-369.84/08/17.8408210396
- 840BR00275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling goodance for licensee submittals of reloads that involve unreviewed safety quastions Svc list enc! EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000,84/08/20.8408200275

# Q Inspection reports: IE Bulletins & correspondence

- 8408300356 Confirms 840502 telcon between QE Vaughn & HC Dance re BHOSON enfortement meeting to discuss improper restoration of centrifugal charging pump & failure to perform local independent veptification at site Proposed agenda encl O'REILLY, J.P. Region 2. Office of Director B4/05/07 TUC Duke Power Ca 2pp 26308 201 24% Fiche 50-269,84/05/07,8408300356 TUCKER, H B
- 8408380230 Forwards rept required by Action Item 4 of 1E Bulletin 82-02 providing info re Action Items 1 & 2 IE Insp Repts 50-349/84-06 & 50-370/84-06 addressed work on threaded Office of Director 2pp
- 8408270383 Forwards Insp Repts 50-367/84-18 & 50-370/84-15 un 840709-11 No violations or deviations noted DANCE,H C Region 2, Office of Director 84/07/20 TUCKER Duke Power Co 2pp 26236 271 24X Fiche 50-369,84/07/20, 8408270383 TUCKER.H B
- --8408270386 Insp Repts 50-369/84-18 & 50-370/84-15 on 840709-11.No NOBLIVISED INSPIRED SOUNDSY/EAR-18 & 50-370/84-15 on 840709-11, No violations or deviations noted Major areas inspected; gaseous & liquid waste sus-radiological effluent accountability & reactor coolant & secondary water Tech Spec requirements KUZOLG B , WRAY, J R , MONTGOMERY, D M Region 2, Office of Director 84/07/18 5pp 26256 273 24X Fiche 50-969,84/07/20,8408270383

- 8408270444 Forwards Insp Repts 50-369/84-19 & 50-370/84-16 on 840709-13 No violations or deviations noted

  DANCE, H C Region 2, Office of Director 84/07/24 TUCKER. H B

  Duke Power Co 2pp 26256 353 24% Fiche 90-369,84/07/24.
- ~-B408270447 Insp Repts 50~369/84-19 & 50~370/84-16 on 840709-13 No violations or deviations noted Major areas inspected health physics organizations, staff qualifications solid radwaste mgt, transportation of radioactive matls & ALARA program WRAY, J. R., JENKING, G. R. Region 2, Diffice of Director 84/07/246pp 26256 355 24X Fiche 50~369.84/07/24.8408270444 94/07/24
- 8407230229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc. 119pp 25865-047 24X Fiche 50-000.84/07/27.8407250229
- B40B010333 IE Info Notice B4-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/0B/06 Consolidated Edison Co of New 122pp 25068 001 24% Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York, Inc. 120pp 26127 118 24X Fishe 50-000,84/08/08,8408070120
- 8408270249 Ack receipt of 840729 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-367/84-11 & 50-370/84-09 PLEMIS, R C Region 2, Office of Director 84/08/09 TUCKER, H B Duke Power Co ip 26288 108 24x Fiche 50-369, 84/08/09, 8408270249
- --8408270259 Responds to NRC 840625 ltr re violations noted in Insp Repts 30-369784-11 & 50-370784-09 Corrective actions containment integrity reviewed at end of each outage to assure mode have not affected containment integrity TUCKER.H B Duke Power Co 84/07/25 D'REILLY, J.P. Region 2, Dffice of Director 4pp 26258 109 24X Fiche 50-349, 84/08/09, 8408270249
- --8408270266 Forwards Insp Repts 50-367/84-11 & 50-370/84-09 on 840820-0420 & notice of violation LEWIS.R C Region 2, Office of Director 84/06/25 TUCKER.H B Duke Power Co 2pp 26258 i13 24X Fishs 50-369.84/08/09. B408270249
- --8408270270 Notice of violation from insp on 840220-0420 \* Region 2, Office of Director 84/06/25 2pp 26258 115 24X Fiche 50-369.84/08/09.8408270249
- --8408270279 insp Repts 50-369/84-11 & 50-370/84-09 on 840220-0420 Noncompliance noted one procedure for ESF test inadequate & one procedure not followed resulting in inadvertent Train A blackout & failure to perform required testing ORDERS,W. PIERSON.R., BROWNLEE.V.L. Region 2, Office of Director 84/04/21 12pp 26258 117 24X Fiche 50-369,84/08/09,8408270249
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc
- Patients Unbergoing at all list encl list encl ORACE, J N Division of QA, Safeguards & Inspection Programs (Post B30103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24x Fiche 50-000.84/08/10.8408070376
- 8408100009 IE Info Notice 84-43, "Defective RHR Replacement Piping " OBTIONOUT INTO NOTICE OF CL. STREET OF CL. STREET OF CL. STREET OF CL. STREET OF CO. STREET OF CO. OF New York, Inc. 117pp 26197 218 24X Fiche 50-000, G4/OB/13, B40B100009
- 840B280234 Submits supplemental response to IE Bulletin 84-02 refailure of GE Type HFA relays in use in Class IE safety sys Relays not in use in safety-related sys TUCKER: H B Duke Power Co 84/08/13 O'REILLY, J P Region 2, Office of Director ip 26262 286 24X Fiche 50-369,84/08/13,840803034

- 108100038 IE Info Notice 84-64. "BWR HPCI Institution Seal-In & Indication " Svc list encl JURDAN,E L Division of Emergenty Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24% Fiche 50-000,84/08/15,8408100038
- 408100021 IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JGRDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Ca of New York, Inc ii8pp 24198 001 24X Fiche 50-000,84/08/16.8408100021
- 408100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 248 Fiche 50-000,84/08/17,8408100055
- |40B14020B | E Info Notice 84-67, "Recent Snubber Inservice Texting W/ High Failure Rates" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 1408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24% Fiche 50-000.84/08/21.8408210142
- . Periodic operating reports & related correspondence
- 3408220465 Monthly operating repts for Jul 1984 W/840815 ltr REAVIG.J A . TUCKER.N B Duke Power Co 84/07/31 19pp 26194 050 24X Fiche 50-349.84/07/31.8408220465
- Reportable occurrences. LERs & related correspondence
- B40B150E21 LER 84-021-00 on 840702, reactor trip breaker of train A (RTB-A) inadvertently opened during testing Caused by misreading of instrumental & electrical procedure & deficiency in instructions Procedure rewritten W/B40B07 ltr OEWENR.S . TUCKER.H B Duke Power Co. B4/08/07 3pp 26073 32 24% Fiche 50-369.B4/08/07.B40B150221 24073 361
- 8408240329 PNd-II-84-054: on 840821, after Unit 1 reactor tripped, operators manually isolated MSIVs to prevent overcooling, resulting in water hammer in secondary sys Damage being assessed
  - 10NATONIS,A J. DROWNLEE,V L. Region 2, Office of Director 84/08/22 2pp 26223 306 24% Fiche 30-369,84/08/22,8408240329
- 8408280389 LER 84-023-00 on 840723, unit tripped from 100% power on 10-lo steam generator level indication Caused by feedwater sys solenoid valve failure Chart recorder added to feedwater valves by hydraulic pump motor M/840882 ltr CEWEHR, 5, TUCKER, H B Duke Power Co. 84/08/22 4pp 26282 104 24% Fiche 50-369,84/08/22,8408280389
- 8408280158 PNO-II-84-054A on 840821, reactor trip occurred due to partial loss of offsite power Caused by inequenting of switchyard computer operated breakers Reactors restarted IGNATONISA J BROWNLEE V.L. Region 2, Office of Director 84/08/23 ip 26259 212 24X Fiche 90-349,84/08/23:8408280158
- U Congressional/Executive Correspondence
- 8408200225 Discusses Tech Spec errors discovered subsequent to NRC approval Susquehanna Tech Spec mends had no safety significance McOuire Tech Spec amends had no safety significance McOuire Tech Specs still under review w/no identified safety significance thus far ASSELBTINE, J K Commissioners. 84/08/10 MARKEY, E J Rep , Interior & Insular Affairs 4pp 26141 244 247 Fiche: 30-000, 84/08/10, 8408200225 MARKEY,E J House of 141 244 24X
- ---B408200279 Requests further info re Tach Spac errors for specs approved since IMI-2 apisode Info re near-term OL activities also requested MARKEY.E J. House of Rep., Interior & Insular Affairs B4/07/12
  - requested
    MARKEY,E J House of Rep , Interior & Insular Affairs
    PALLADINO.N J Commissioners ip 26142 002 24X
    Fiche 50-000,84/08/10,8408200225

- DOCKET 50-970 WILLIAM B MAGUIRE NUCLEAR STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8408300193 Forwards 840612 itr detailing overall planning for 840620 French security team visit to facility Biographical info for each team member included LEWIS,R C. Region 2. Office of Director 84/06/15 TUCKER,H B Duke Power Co. ip 26300 139 24x Fiche 50-000,84/06/15,8408300193
- --8408300204 Requests authorization for six French security experts hosted by NRC to visit McOuire facility on 840620 & Sequeyah facility on 840628 Biographical info & itinerary encl LAFLEUR, J D Office of International Programs, Director 84/06/12 TUCKER, H B Duke Power Co Spp 26300 140 24% Fiche 50-000, 84/06/15, 8408300193
- 8408270444 Forwards Insp Repts 50-369/84-19 & 50-370/84-16 on 840709-13 No violations of deviations noted

  DANCE.H C Region 2, Office of Director 84/07/24 TUCKER.H B

  Duke Pawer Co 2pp 26256 353 24X Fishe 50-369,84/07/24. B408270444
- --8408270447 Insp Repts 50-369/84-19 & 50-370/84-16 on 840709-13 No togg/2044/ insp Repts 50-347/04-17 & 30-37/04-1-18 on 840/09-1 violations or deviations noted Major areas inspected health physics organizations staff qualifications solid radwaste mgt. transportation of radioactive matis & ALARA program WRAYJ, R Region 2. Office of Director 84/07/24 App 26256 355 24X Fiche 50-369,84/07/24,8408270444
- B408070278 Informs that requested info re detailed control room design review provided in licensee B40409.0329 & 0216 submittals, per Buppl 1 to NUREO-0737 Task analyses for inadequate core cooling & ATMS event conducted during control room review TUCKER.H B Duke Power Co B4/07/27 DENTON.H R Office of NUCLEAR Reactor Regulation, Director ADENSAM, E O Licensing Branch 4 2pp 25947 295 24X Fiche 50~369,84/07/27.8408070298
- 8408200100 Forwards deviations & technical justifications from App R criteria, per fire protection program review
  TUCKER.H B Duke Power Co 84/08/09 DENTON, H R Office of
  Nuclear Reactar Regulation, Director ABENBAM, E G Licensing Bran
  4 4pp 26133 311 24% Fiche 50~369,84/08/03.8408200100 Licensing Branch
- 8408300357 Confirms 840806 telcon w/JP O'Reilly re 840815 mgeting in Region II oft to discuss design & operation of standby shutdown facility concerning App R to 100FR50. fire protection & 100FR73, physical protection Agenda enci LEWIS, R C Region 2, Office of Director 84/08/08 TUCKER. H B Duke Power Co 3pp 26314 222 24X Fiche 50-000,84/08/08, 8408300357
- 840B300014 Forwards public version of Rov 13 to crisis mgt plan & revieted emergency plan implementing procedures
  TUCKER: H B Duke Power Co B4/08/10 Record Services Branch
  (Document Control Desk) 21pp 26332 353 24X
  Fiche B0-000, 84/08/10, 8408300014
- --8408300021 Public version of Rev 13 to "Crisis Mgt Plan for Nuclear # Duke Power Co 84/08/15 30pp 26333 010 24X Fiche 50-000, 84/08/10, 8408300014
- --B408300028 Public version of revised crisis mgt plan implementing procedures, including 5 3 1 re recovery manager & immedi-staff group plan & 5 3 4 re scheduling/planning support group K/Felton 840823 memo. \* Duke Power Cn 84/08/15 170pp 26333 040 24X 170pp 26333 040 24X Fiche 50-000, 84/08/10, 8408300014
- I Financial impormation
- 8408240224 Forwards Duke Power Co & North Carolina Municipal Power 408240224 Forwards Duke Power Co α North Carollina Houle.
  Agency I 1983 annual repts
  TUCKER, H B Duke Power Co 84/08/16 DENTÜN, H R. Of
  Nuclear Reactor Regulation, Director 2pp 26237 137
  Fiche 50-000,84/08/16,8408240224 Office of
- --8408240237 "1983 Annual Rept " CLAY, G W North Carolina Municipal Power Agencies 93. 27pp 26837 139 24X Fiche 50~000,84/08/16,8408240284 83/12/31
- --B40B240242 "1983 Annual Rept " LEE.W & Duke Pover Co 83/12/31 47pp 26237 167 24X Fiche 50-000,84/08/16,8408240224

- P Operating license stage documents % correspondence
- BAOBI60425 Summary of B40720 meeting w/utils & Westinghouse re containment analysis & superheat effects on environ qualification WIGGINTON D. L. Operating Reactors Branch 1 84/07/30 Operating Reactors Branch 1 4pp 26143 265 24X Fiche 50-000.84/07/30. 8408160425
- B40B030130 Application for amend to Licenses NPF-9 % NPF-17. changing Tech Specs to provide operability & surveillance requirements for addl subcooling margin monitor sys channel & reactor vessel level instrumentation sys TUCKER, H B Duke Power Ca 94/07/31 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E.G. Licensing Dranch 4 3pp 25916 129 24% Fiche 50-369, 84/07/31, 8408030130
- --B408030135 Proposed Tech Specs providing operability & surveillance requirements for add) subcooling margin monitor sys channel & reactor vessel level instrumentation sys # Duke Power Co # 84/07/31 4pp # 25916 132 24% Fiche 50-369,84/07/31,8408030130
- 8408130169 Forwards description & justification for proposed piping seismic analysis changes, adopting damping values & spectra shifting methods for piping sys.per WRC recommendations, for review/approval TUCKER. H B Duke Pouer Co 84/08/01 DENTON. H R Office of Nuclear Reactor Regulation, Director ADENSAM. E O Licensing Branch 4 3pp 26010 027 24x Fiche 50-369,84/08/01.8408130169
- 8408070468 Forwards proprietary add1 info re spent fuel pool two region rerack mods, addressing concerns raised during 840731 meeting Affidavit will be submitted by Wastinghouse Info withheld (ref 10CFR2 790)
  TUCKER, H B Duke Power Co 84/08/02 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 1p 25941 194 24% Fiche 50~369,84/08/02,8408070468
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Generic Bafety Issues " Svc list encl EISENHUT, D © Division of Licensing 84/08/06 Consolidated Edison Co of New York Inc 18pp 26129 238 24X Fiche 50-000.84/08/06.8408070110
- 8408160050 Forwards surmary evaluation of main steam line break analysis for both inside containment & in doghouse Plant safety would not be adversely affected in event of design basis main line break in doghouse or inside containment TUCKER.H B Duke Power Co 84/08/08 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAME C Licensing Branch 4 7pp 26092 068 24% Fiche 50-369,84/08/08.8408160050
- 8408160174 Forwards corrected page to 840802 add1 info attachment re spent fuel pool two region rerack mods Only Page 1 of attachment considered proprietary to Westinghouse TUCKER, H B Duke Power Co 84/08/13 DENTON: H R Office of Nuclear Reactor Regulation, Director ADENSAM.E G Licensing Branch 4 2pp 26092 034 24X Fiche 50-369,84/08/13,8408160174
- 9408230527 Forwards payment for application fee re 940802 & 08 Tech Spec changes BARR, B Duke Power Co 94/08/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 26236 286 24X Fiche 50~000,84/08/15,8408230527
- B40B270160 Forwards Rev 4 to "Offsite Dose Calculation Menual." incorporating Catawba calculation info Rev submitted prior to submitted of semiannual radioactive effluent release rept for Jul-Dec 1984
  TUCKER.H B Duke Power Co B4/08/16 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 26279 112 24X
  Fiche 50-000.84/08/16.8408270160
- --8408270169 Rev 4 to "Offsite Dose Calculation Manual " BIRCH, M L Duke Power Co 84/07/18 39pp 26279 ii4 24X Fiche 50-000,84/08/16,8408270160
- B40B210396 Forwards info documenting results of review & implementation of required changes & mods, per Generic Ltr 81-07, "Control of Heavy Loads" & NURFO-0612 Minor error noted in 801222 ltr corrected TUCKER. H B Duke Power Co 84/08/17 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM. E G Licensing Branch 4 34pp 26180 271 24X Fiche 50-369,84/08/17,8408210396

- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT.D C Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000.84/08/20.8408200275
- O Inspection reports: IE Bulletins & correspondence
- 8408270383 Forwards Insp Repts 50-369/84-18 & 50-370/84-15 on 840709-11 No violations or deviations noted DANCE.H & Region 2: Diffice of Director 84/07/20 TUCKER.H B Duke Power Co 2pp 26256 271 24X Fiche 50-369.84/07/20.8408270383
- ~~8408270386 Insp Repts 50~369/84-18 & 50~370/84-15 on 840709-11 No violations or deviations noted Major areas inspected gaseous & liquid waste sys radiological effluent accountability & reactor coolant & secondary water Tech Spec requirements KUZD, G B . WRAY, J R . HONTGOMERY, D M Region 2. Office of Director 84/07/18 Spp 26256 273 24X Fiche 50~369.84/07/20, 8408270383
- 8408270444 Forwards Insp Repts 50-369/84-19 & 50-370/84-16 on 840709-13 No violations or deviations noted DANCE: H C Region 2. Office of Director 84/07/24 TUCKER, H B Duke Power Co 2pp 26256 353 24X Fichs 50-369.84/07/24.
- --B40B270447 Insp Repts 50-369/B4-19 & 50-370/B4-16 on 840709-13 No violations or deviations noted Major areas inspected health physics organizations, staff qualifications solid radwaste mgt. transportation of radioactive matis & ALARA program MRAY. J. R. JENKINS. G. R. Region 2. Office of Director 84/07/246pp 26256 355 24X Fiche 30-369.84/07/24.8408270444
- 8407280227 IE Info Notice 84-57, "Operating Experience of Holsture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, E L Division of Emergency Pragaredness & Engineering Response (Post 820103) 84/07/27 Consolidated Edison Co of New York, Inc. 117pp 25865 047 24X Fiche 50-000.84/07/27, 8407250229
- 8408010333 IE info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Medt Efficiency Requirement " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp. 26067 138. 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Cansolidated Edison Co. of New York, Inc. 120pp 26129 118 24X Fiche, 50-000,84/08/08,8408070120
- 8408270249 Ack receipt of 840725 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-369/84-i1 & 50-370/84-09 LEHIS,R C Region 2, Office of Director 84/08/09 TUCKER.H B Duke Power Co ip 26258 108 24X Fich# 50-349,84/08/09,8408270249
- --8408270299 Responds to NRC 840625 ltr re violations noted in Insp Repts 50-369/84-11 & 50-370/84-09 Corrective actions: containment integrity reviewed at end of each outage to assure mods have not affected containment integrity TUCKER.H B Duke Pauer Co. 84/07/25 O'REILLY.J P Region 2, Office of Director 4pp 26838 109 24X Fiche 30-369,84/08/09, 8408270249
- --8408270266 Forwards Insp Repts 50-369/84-11 & 50-370/84-09 on 840220-0420 & notice of violation LEMIB.R C Region 2, Office of Director 84/06/25 TUCKER, H & Duke Power Co. 2pp 26258 113 24X Fiche 50-369,84/08/09, 8408270249
- ---8408270270 Notice of violation from insp on 840220-0420. \* Region 2, Office of Director 84/04/25 2pp. 26258-115 24) Ficha 50-369,84/08/09,8408270249

- 8408270279 Insp Repts 50-349/81-11 / 50-370/84-09 on 840220-0420 Noncompliance noted one procedure for ESF test inadequate & one procedure not followed, resulting in inadvertent Train A blackout & failure to perform required testing GRDERS.W., PIERSON.R., BROWNLEE, V.L. Region 2. Office of Director 84/06/21 12pp 26258 117 24X Fiche 50-369.84/08/09.
- .08070376 IE Info Notice B4-62, "Therapy Misadoinistrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl GRACE: J N Division of GA, Bafeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24% Fiche 50-000.84/08/10,8408070374
- 108100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " OBTIONOGY as hims described by the state of the state of
- 108280234 Submits supplemental response to IE Bulletin 84-02 re failure of GE Type HFA relays in use in Class 1E safety sys Relays not in use in safety-related sys TUCKER.H B Duke Pouer Co 84/08/13 O'REILLY, J P Region 2. Office of Director ip 26262 286 24X Fiche 50-369.84/08/13.
- 408100038 1E Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication "Svc list encl
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/15 Consolidated Edison Co of New
  York, Int 104pp 26198 093 24X Fiche 50-000.84/08/15.8408100038
- 40B100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " 8vt list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc. 118pp. 26198 001 24X Fiche 50-000,84/08/16,8408100021
- 40B100055 IE Info Notice B4-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feeduater Train" Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 803003) 84/08/17 Consolidated Edison Co of New York, Inc. 120pp 26276 001 24% Fiche 50-000,84/08/17,8408100055
- 408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JDRDAN E L Division of Emergency Preparedness & Engineering Response (Post B30103) 94/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000.84/08/17.8408140208
- |408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rates Field Wiring to Bolenoid Valves " Svc list encl JORDANSE L Division of Emergency Preparedness & Engineering Response (Post 800103) 84/08/21 Consolidated Edison Co of New York, Inc. 115pp 26/329 008 24% Fiche 50-000,84/08/21,8408210142
- Periodic operating reports & related correspondence
- |408220445 Monthly operating repts for Jul 1984 W/840815 ltr | REAVIS.J A . TUCKER.H B | Duke Power Co | 84/07/31 | 15pp | 26196 050 | 24X Fiche 50-369.84/07/31,8408220465
- 408300309 Corrected monthly operating rept for Jul 1984 W/840823 ltm REAVIS.J A. TUCKER.H B. Duke Power Co. 84/07/31 3pp. 26313 308 24X Fiche 50-370,84/07/31,8408300509
- Reportable occurrences. LERs & related correspondence
- 408090274 LER 84-015-00 on 840703, test indicator lamp on MSIV failed to light, leading to inadvertent MSIV closure & automatic ESF actuation Caused by personnel error Personnel cautioned W/840802 ltr GEWEHR, 8 , TUCKER, H B Duke Power Co 84/08/02 3pp 25974 148 24X Fiche 50-370, 84/08/02, 8408090274
- 408140324 PNG-II-84-046 on 830806.w/unit in cold shutdown, packing ring blew out from chemical & vol control sys letdown line velve connected to RRR sys Line break occurred in auxiliary bldg room socket weld, discharging 3,500 gallons water IONATONIS, A , BROWNLEE, V L. Region 2, Office of Director 84/08/06 2pp 26042 351 24X Fiche 50-370,84/08/06,8408140324
- 408230001 PNC-II-84-052 on 840820, leak developed inside containment while upper head injection sys filled & checked for air entrapment Caused by glass on upper head injection sys ng pressurization No environ release occurred BRDWMLEE.V L Region 2. Office of Director 24209 158 24X Fiche 50-370,84/08/20,8408230001

- B408290094 LER 84-016-00 on 840719, reactor tripped during testing Caused by operation of reactor trip breaker from control room rather than test cabinet Test procedure to be rowritten Event reviewed by personnel N/840817 ltr OEWERR, S. TUCKER, H. B. Duke Power Co. 84/08/20 4pp. 26298 (24X Fiche 50-370,84/08/20,8408290094 24298 001
- 8408240290 PNO-II-84-052A on 840820,4,800 gallons reactor coolant inventory spilled into reactor bldg sump area Caused by sight glass being blown out of upper head injection sys Alarm printer reviewed & sight glass replaced IONATONIS,A J. BROWNLEE,V L. Region 2. Office of Director 84/08/21 2pp 26223 191 24X Fiche 50-370,84/08/21,8408240290
- 8408240329 PNO-II-84-054 on 840821.after Unit 1 reactor tripped. operators manually isolated MSIVs to prevent overcooling. resulting in water hammer in secondary sys Damage being assesed
- 8408280[58] PNO-II-84-054A on 840821. reactor trip occurred due to partial loss of offsite power Caused by inadvertent opening of switchyard computer operated breakers Reactors restarted IGNATONIS,A J. BROWNLEE,V L. Region 2, Office of Director 84/08/23 ip 26259 212 24% Fiche 50-369.84/08/23,8408280158
- U Congressional/Executive Correspondence
- 8408200225 Discusses Tech Spec errors discovered subsequent to NRC approval Susquehanna Tech Spec amends had no safety significance McGuire Tech Specs still under review w/no identified safety significance thus far ASSELSTINE, J K Commissioners 84/08/10 MARKEY.E J Rep . Interior & Insular Affairs 4pp 26141 244 24% Ficha 50-000,84/08/10.8408200225
- --8408200279 Requests further info to Tech Spec errors for specs approved since TMI-2 episode Info to near-term OL activities also rooussted requested
  MARKEY, E. J. House of Rep., Interior & Insular Affairs 84/07/12
  PALLADING, N. J. Commissioners 1p 26142 002 24x
  Fiche 50-000,84/08/10,8408200225
- DOCKET 50-373 LABALLE COUNTY STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- numumunty Forwards exercise repts for Laballe & Dresden offsite radiological emergency preparedness exercises conducted 820414-15 & 0.647-30, respectively KRIMM,R W Federal Emergency Management Agency 84/03/26 JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 22863 122 24X Fiche 50-000, 84/03/26, 8404040169 8404040169 Forwards exercise repts for LaSalle & Dresden offsite
- --8404040172 Evaluation of State of IL Pull-scale emergency preparedness \* Federal Emergency Management Agency 82/03/31 68pp 22883 124 24% Fiche 50-000,84/03/26,8404040169
- 8408010289 Forwards IE Insp Repts 50-373/84-14 & 50-374/84-18 on 840312-0618 & notice of violation BHAFER, W D Region 3, Office of Director 84/07/10 REED.C Commonwealth Edison Co 2pp 25866 103 24X Fiche 50-373,84/07/10. 8408010289
- --B40B010274 IE Insp Repts 50-373/B4-14 & 50-374/B4-18 on B40512-0618 Noncompliance noted failure to control access to high radjation area & failure to follow reactor vessel lo-lo water level recirculation pump trip calibr test procedure CHRIBGOTIMOS,N Region 3, Office of Director 84/07/02 lopp 25866 107 24X Fiche 50-373,84/07/10,840B010289
- B40B140179 Rev 4 to Offsite Emergency Procedure LZP-1550~2. "Environs Sampling Supplies Inventory " Revised index & 840808 transmittal form enc! # Commonwealth Edison Co 84/07/25 16pp 26044 332 24X Fiche 50-373,84/07/25,8409140179
- B408060075 Ack receipt of scope & objectives for 841010 emergency preparedness exercise Objectives acceptable & unchanged from 840718 scenario development meeting PAPERIELLO.C J. Region 3. Office of Director 84/08/01 REED.C Commonwealth Edison Co ip 25922 001 24X Fiche 50-373,84/08/01. 8408060095

- --8408060101 Forwards scope % objectives for 841010 emergency preparedness exercise, per NRC/FEMA requirements GREENE.7 R Commonwealth Edison Co 84/07/25 HIND.J Division of Energency Preparedness & Operational Support 5pp 25922 002 24% Fiche 50-373.84/08/01.8408060095
- B40Bi40139 Forwards listed rovs to security plans Revs address fence height requirements Revs withheld (ref 100FR73 21) FARRAR, D. L. Commonwealth Edison Co. 84/08/03 Region 3, Office of Director 1p. 26044 252 24X Fiche 50-000, 84/08/03, 8408140139
- 840B130401 Responds to 840705 clarification of info re util means of satisfying annual regulatory requirement to review emergency action levels w/offsite emergency support organizations info acceptable PAPERIELLO.C J Region 3, Office of Director 84/08/07 REED.C Commonwealth Edison Co ip 26010 130 24X Fiche 50-000,84/08/07,8408130401
- --8408i304i3 Responds to 840604 ltr re means for satisfying requirements of 10CFR50.App E.Paragraph JV 8 Proposal for satisfying requirements to review amergency action levels by offsite agencies clarified FARRAR.D L Commonwealth Edison Co 84/07/05 PAPERIELLO,C J Region 3, Office of Director 8ρρ 26010 131 24X Fiche 50-000.84/08/07,8408i30401
- B40B200230 Advises that B40B03 Rev 19 to physical security plan consistent w/provisions of 10CFR30 54(p) % acceptable AXELSON.W L Region 3, Office of Director B4/0B/14 FARRAR, D L Commonwealth Edison Co. 2pp 26133 i88 24X Fiche 50-373, B4/08/14, B40B200230
- 8408310233 Rev 1 to Emergency Plan Implementing Procedure LZP-1510-1. "Generating Station Emergency Procedure Operational Readiness" W/840824 transmittal memo \* Commonwealth Edison Co. 84/08/17 10pp 26322 269 24X Fiche 50-373,84/08/17,8408310233
- 8408270358 Forwards "Technical Basis of LaSalle County Station Fire Damper Surveillance Program." per 840328 agreement RYBAK.B Commonwealth Edison Co 84/08/21 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 26239 228 24X Fiche 50-373,84/08/21,8408270358
- --8408270362 "Technical Basis of LaSalle County Station Fire Damper Surveillance Program " \* Commonwealth Edison Co 84/08/31 326pp 26239 229 24X Fiche 50-373,84/08/21,8408270358
- P Operating license stage documents & correspondence
- 8408080148 Forwards Amends 17 & 2 to Licenses NPF-11 & NPF-18, respectively & safety evaluation Amends change Tech Specs re main line temp difference trip setpoints & allowable values SCHWENGER, A Licensing Branch 2 84/07/03 FARRAR, D Commonwealt Edison Co 2pp. 25979 043 24X Fiche 50-373,84/07/03,8408080148
- --8408080155 Amends 17 & 2 to Licenses NPF-11 & NPF-18, respectively, changing Tech Specs re main steamline temp difference trip setpoints & allowable values SCHMENCER, A Licensing Branch 2 84/07/03 8pp 25979 045 24X Fiche 50-373, 84/07/03, 8408080148
- ~~8408080159 Safety evaluation supporting Amends 17 & 2 to Licenses NPF-il & NPF-iS, respectively \* Office of Nuclear Reactor Regulation. Director 25979 053 24X Fiche 50-373,84/07/03,8408080148
- B40B280360 Ack receipt of B40710 ltr re author criticism of NRC present rules & practices Reponse to NRC seven stages of discussion listed Past tests should be reviewed & leak rate be retested Related info enc. REYIBLATT, Z V Warren Wilson College, Swannanoa, NC B4/07/22 ROSS, D F Office of Nuclear Regulatory Research, Director Epp 26293 001 24% Fiche 50-000, 84/07/22, 8408280360
- --B40B2B0366 Lists basic deficiencies & errors of present leak rate testing methodology as regulated by faulty stds REYTBLATT. 2 V Extran. Inc. 84/03/15 ACR6 Advisory Committee on Reactor Safeguards 3pp 26293 009 24X Fiche 50-000, 84/07/22, 8408280340
- --8408280373 Requests documents re RFP RS-RES-84-101, submitted on 840110 Author 840220 ltr to EM Gogol Citizens Against Nuclear Power encl REYTBLATT, Z V Extran, Inc. 84/03/02 Division of Rules and Records 6pp 26293 012 24X Fiche 50-000 84/07/22.8408280360

- --8408280380 Discusses author presentation on 840315 G Arndt & ORNL should be heard before committee on faulty leak rate test Requests add opportunity to present point of view REYTBLATT, Z Extran. Inc 84/05/18 ACRS -- Advisory Committee on Reactor Safeguards ip 26293 023 24% Fiche 50-000,84/07/22,8408280360
- 8408010107 Forwards request for add1 info re NUREG-0737. Item II D 1, including basis for application of findings of NEDE-24988-P, "Analysis of Generic Bur Safety I Relief Valve Operability Test Results," submitted by Bur Owners Group SCHMENCER, A Licensing Branch 2 84/07/24 FARRAR, D L Commonwealth Edison Co 4pp 258/3 355 24X Fiche 90-373,84/07/24,8408010107
- B4Q8060145 Application for amend to Licenses NPF-11 & NPF-18, changing Tach Space re-accident nonitoring instrumentation (NUREO-0737, Items II F 1 1, I] F 1 3 & II F 1 6) Fee encl MARSHALL, J G Commonwealth Edison Co 94/07/25 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 25725-285-24X Fiche 50-373,84/07/25,8408060145
- --B408060153 Proposed Tech Spec changes re accident monitoring instrumentation limiting conditions for operation for noble gas effluent nonitors, containment high radiation monitors & containment hydrogen monitor # Commo
- B40B30050B Forwards radinactive effluent monitoring rept for Jan-June 1984 & revised process control procedure DIEDERICH 9 J Commonwealth Edison Co 64/07/25 KEPPLER, J Q Region 3, Office of Director 1p 26313 311 24X Fichs 50-373,84/07/25,8408300508
- --8408300516 Rev 2 to LAP-200-6, "LaSalle County Station Process Control Program" \* Commonwealth Edison Co 83/12/29 15pp 26313 325 24x Fiche 50-373,84/07/25,8408300508
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for GLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Generic Safety Issues" Svc list enci EISEMHUT.D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26/29 238 24X Fiche 50-000,84/08/06.8408070110
- B408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
  TREMBLAY.P P Operating Reactors Assessment Branch B4/08/06
  HOLAMAN.O M Operating Reactors Assessment Branch 13pp
  25991 350 24X Fiche 50-000, B4/08/06, 8408090317
- 8408160364 Requests authorisation to use ASME Code Case N-389 Licenses will use ASME Code 1980 edition. Winter 1980 &/or Winter 1981 addends for uork during upcoming outage MARSHALL.JO Commonwealth Edison Co 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 26091 236 24X Fiche 50-373.84/08/07.8408160364
- 8408140387 Forwards revised pump & valve inservict testing plans, reflecting Relief Requests RI-19 & RV-38 from certain ABME Section XI Code requirements for containment isolation & RCIC injection outboard valves MARSHALL, J G Commonwealth Edison Co 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 26085 350 24X Fiche 50-373,84/08/07,8408160387
- 8408170227 Forwards Amend 18 to License NFF-1; & safety evaluation Amend changes Tech Specs, in response to util 840113,0322 & 0405 ltms, to reflect changes incorporated into Unit 2 Tech Specs SCHWENCER.A Licensing Branch 2 84/08/08 FARRAR, D L Commonwealth Edison Co 3pp 26135 001 24X Fiche 50-373,84/08/08,8408170227
- --8408170243 Amend 18 to License NPF-11, reflecting changes incorporated into Unit 2 Tech Specs SCHMENOER, A Licensing Branch 2 84/07/27 172pp 26135.004 24X Fiche 50-373.84/08/08.8408170227
- --8408170247 Safety evaluation supporting Amend 18 to License NPF-11 \* Office of Nuclear Reactor Regulation, Director 84/08/08 10pp 26135 176 24% Fiche 50-373.84/08/08.8408170227

- 8408140323 Informs that util no longer participating in instrument setpoint methodology program conducted by SWR Licensing Review Group MARSHALL, J G Commonwealth Edison Co 84/08/09 DENTON. H R Office of Nuclear Reactor Regulation. Director 1p 26042 350 24% Fiche 50-373,84/08/09.8408140323
- 8408270479 Forwards request for addl info re safety relief valve (SRV) bloudown test Util rept re SRV test & evaluation of suppression good temp neasurements fails to satisfy NUREO-0487 & NUREO-0789 criteria SCHUENCER, A Licensing Branch 2 84/08/17 FARRAR, D L Componencealth Edison Co 4pp 26277 194 24X Fiche 50-373,84/08/17,8408270479
- 8408200275 Deneric Ltr 84-20 to all lirensees of operating reactors & applicants for DLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT, D & Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276-244 24X Fiche 50-000,84/08/20,8408200275
- 8408310439 Forwards errata to Amend 18 to License NPF-11, consisting of corrected Tech Specs SCHLENGER, A Licensing Branch 2 84/08/27 FARRAR, D L Commonwealth Edison Co 2pp 26350 135 24X Fiche 50-373,84/08/27,8408310439
- --8408310442 Errata to Amend 18 to License NPF-11.consisting of corrected Tech Specs \* NBC - No Detailed Affiliation Given 84/08/21 3pp 26350 137 24X Fiche 50-373.84/08/27.8408310439
- 840B310490 Responds to 840807 request for authorization to use ASME Code Case N-389, "Alternate Rules for Repairs Replacements or Mods Section XI.Div 1 " Use of Code Case N-389 acceptable Next update to F8AR should document usage SCHWENCER.A Licensing Branch 2 84/08/28 FARRAR, D L Commonwealth Edison Co 2pp 26350 127 24X Fiche 50-373,84/08/28,8408310450
- O Inspection reports. IE Bulletins & correspondence
- 8408010289 Forwards IE Insp Repts 50-373/84-14 & 50-3/4/84-18 on 840512-0618 & notice of violation SHAFER, W D Region 3, Office of Director 84/07/10 REED, C Commonwealth Edison Co 2pp 25866 103 24X Fiche 50-373,84/07/10,8408010289
- --9408010291 Notice of Violation from insp on 840512-0618 SHAFER.W D Region 3, Office of Director 84/07/05 2pp 23864 103 24X Fiche 50-373.84/07/10.8408010289
- --B408010294 IE Insp Repts 50-373/84-14 & 50-374/84-18 on 840512-0618
  Noncompliance noted failure to control access to high
  radiation area & failure to fullow reactor vessel lo-lo
  water level recirculation pump trip calibr test procedure
  CHRISSOTIKOS,N Region 3, Office of Director 84/07/02 10pp
  25866 107 24X Fiche 50-373,84/07/10,8408010289
- 8407250229 lE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24% Fiche 50-000,84/07/27,8407250229
- 8408060085 Forwards revs to baseline insp rept (ASME Bection XI)

  Beficiencies noted during util audit corrected W/o encl

  MARSHALL.V G Commonwealth Edison Co 84/07/30 DENTON, H R

  Office of Nuclear Reactor Regulation, Director 1p 25922 Oli 24X

  Fiche 50-373,84/07/30.8408060085
- 840B070066 Notifies of 840823 meeting w/util at Region III ofc to review findings of SALP assessment re util performance Encourages mgt representation to ensure mutual understanding of issues & findings presented by NRC NORELIUS.C E Region 3. Office of Director 94/08/03 REED.C Commonwealth Edison Co 2pp 25749 337 24% Fiche 50-000.84/08/03.8408070066
- 8408070401 Informs that new sys of atknowledging receipt of licensee correspondence re noncompliance found during inspiratituted.effective 840820 Preprinted form will be used rather than itr
  KEPPLER, J G Region 3, Office of Director 84/08/03
  Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000,84/08/03,8408070401

- B40B010333 (E Info Notice B4-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JURDAN, E L Division of Emergency Proparedness & Engineering Response (Post 830103) B4/08/06 Consolidated Edison Co of New York Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 840B010333
- B40B010337 IE Info Notice B4-60, "Failuje of Air Pulifying Respirator Filters to Meet Efficiency Requirement 'Svc list encl JORBAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York Inc 123pp 26067 158 24X Fiche 50-000.84/08/06.8408010337
- 8408230293 Forwards IE Insp Repts 50-373/84-17 & 50-374/84-25 on 840724-26 No noncompliance noted MALKER, R D Region 3, Office of Director 84/08/06 REED, C Cummunusalth Edison Co 2pp 26213 251 24X Fiche 50-373,84/08/06,8408230293
- --8408230298 IE Insp Repts 50-373/84-19 & 50-374/84-25 on 840724-26 No nuncompliance or deviations noted Major areas inspected previous insp findings & startup testing audit program CHOULES,N C , HANKINS,F C Region 3, 0ffice of Director 84/08/06 4pp 26213 253 24X Fiche 90-373,84/08/06,8408230293
- 8408070120 IE info Notice 84-61. "Overexposure of Diver in PUR Refueling Cavity " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York Inc 120pp 26127 118 24% Fiche 50-000.84/08/08.8408070120
- 8408140344 Confirms 840803 plans to meet w/util on 840707 in Glen Eliyn. IL to discuss regulatory improvement program NORELIUS, C E Region 3. Office of Director 84708708 REED, C Communicate Edison Co 2pp 26041 050 24X Fiche 50~000.84/08/08,
- 8408130098 Suppls 840711 response to 1E Bulletin 84-02 re visual insp during monthly functional tests to verify proper contact on reactor trip sys & primary containment isolation sys relays Exemptions requested for limited relays ALEXANDER, 0 L Commonwealth Edison Co 84/08/08 KEPPLER, J G Region 3, Office of Director 3pp 26067 053 24X Fiche 50-000,84/08/08.8408130098
- 840820033i Suppls response to 1E Bulletin 84-02 to failure of GE Type HFA relays Exemption requested from commitment for visual insp verifying proper relay contact during monthly functional check for listed relays ALEXANDER.O L Commonwealth Edison Co 84/08/08 KEPPLER, J O Region 3. Dffice of Director 3pp 26132 318 24% Fichs 50-000,84/08/08.8408200331
- 8408070374 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list encl GRACE.J N Division of QA. Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125p 26130 001 24X Fiche 50-000.84/08/10.84080703/6
- 8408160198 Discusses IE Insp Repts 50-373/84-14 & 50-374/84-18 on 840512-0618 & forwards corrected notice of violation Response within 30 days requested SHAFER.N D Region 3, Office of Director 84/08/10 REED, C Commonwealth Edison Co ip R6092 133 24X Fiche 50-373,84/08/10,8408160198
- --8408160206 Cerrected notice of violation from insp on 840512-0618
  Violations identified surveillance of unlocked high
  radiation area inattentive & failure to adhere to
  instrument surveillance procedures
  SHAFER.W D Region 3, Office of Director 84/08/10 2pp
  26092 134 24X Fiche 50-373,84/08/10,8408160198
- B40B100009 IC Info Notice 84~63. "Defective RHR Replacement Piping "
  Bvc list encl

  JURDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50~000,84/08/13,8408100009
- 8408100038 IE Info Notice 84~64. "BWR HPCI Initiation Seal-In & Indication " Svc list encl
  JORDAN E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York. Inc 104pp 26198 093 24X Fiche 50-000.84/08/15.8408100038
- 8408100091 IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" 8vc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26198 001 24X Fiche 30-000,84/08/16,8408100021

- 8408100055 IE Info Nutice 84-66. Undetected Unavailability of Turbine-Priven Auxiliary Feedwater Train " Sv. list encl JCRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Cansolidated Edison Co. of New York, Inc. 120pp 26276 001 24% Fiche 50-000.84/08/17,8408100055
- 8408140208 IE Info Notice 84-67. "Recent Shubber Inservice Testing W/ High Failure Rates." Syc. List enc] JORDAN.É L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17. Consolidated Edison Co. of New York, Inc. 122pp 26276 122 24% Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves' Svc list end JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc. 113pp 26329 008 24% Fiche 50-000,84/08/21,8408210142
- R Periodic operating reports & related correspondence
- B40B30038B Forwards errata to "Rept of Radioactive Effluents." Jul-Dec 1983 Part 1 of 1984 operating rept for Jan-June 1984 will be submitted in Aug 1984 DIEDERICH, G.J. Commonwealth Edison Co. 84/07/23 KEPPLER, J. G. Region 3, Office of Director 1p. 26308 151 24x Fiche 50-373,84/07/23.8408300388
- 8408300908 Forwards radioactive effluent monitoring rept for Jan-June 1984 & revised process control procedure DIEDERICH, G.J. Commonugalth Edison Co. 84/07/25 KEPPLER, J.G. Region 3. Office of Director ip. 26313 311 24x Fiche 50-373,84/07/25,8408300508
- --8408300513 "Rept of Radioactive Effluents," Jan-June 1984 \* Commonwealth Edison Co 84/06/30 13pp 26313 312 24X Fishe 50-373, 84/07/25, 8408300508
- --8408300516 Rev 2 to LAP-200-6, "LaSalle County Station Process Control Program" Commonwealth Edison Co 83/12/29 15pp 26313 325 24X Fiche 50-373,84/07/25,8408300508
- B408160140 Monthly operating repts for Jul 1984 W/840806 ltr DUS.R S . DIEDERICH.O J Commonwealth Edison Co 84/07/31 27pp 26108 081 24x Fiche 50-373,84/07/31,8408160140
- 6 Reportable occurrences, LERs & related correspondence
- 8408240348 Part 21 ropt re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 Now thread locking devices investigated SHERWOOD. G General Electric Co 84/04/13 DEYDNOR, R C Director's Office, Office of Inspection and Enforcement Jpp 26222 256 24X Fiche 50-000.84/04/13,8408240348
- B40B0A0063 LER B4-040-00 on B40625 in startup mode reactor water cleanup sys isolated on high differential flow Caused by tamp & pressure differences between startup operations & instrument calibr Procedure revised W/B40719 ltr SHIELDS.J M. DIEDERICH.G. J. Commonwealth Edison Co. 84/07/15 3pp 25939 283 24X Fishe 50-373.84/07/19.8408040063
- 8408060099 LER 84-041-00 on 840629 three mechanical penetrations on fire-rated walls/floors not sealed properly Caused by personnel not identifying on sleeve schedule Fire watch established Penetration sealed W/840723 1tr MCVEY, E.A. DIEDERICH. G. J. Commonwealth Edison Co. 84/07/23 3pp 25935 263 24X Fiche 50-373,84/07/23.8408060055
- B40B060255 LER 84-043-00 on 840627 during reactor water cleanup filter deisolation, reactor water cleanup sys isolated on high differential flow Possibly caused by draining of demineralizer Investigation underway W/840725 ltr ARAND, J. DIEDERICH, O. J. Commonwealth Edison Co. 84/07/25 3pp 25935 150 24X Fichs 50-373, 84/07/25, 8408060255
- 8408060207 LER 84-044-00 om 840702.HPCS quarterly inservice test check valve 1E22-F006 & stop check valve 1E22-F007 failed to prevent reverse flow Caused by scoring of disc seats Valves repaired W/840727 ltr MASTERSON, V. DIEDERICH, C. J. Commonwealth Edison Co. 84/07/27 4pp 25723 355 24% Fiche 50-373,84/07/27.8408060207

- B40B070324 LER 84-042-00 on 840703 reactor water cleanup outboard isolation valve room area dverlooted in joutine surveys up to 840703 Posting on entrance dour 463 upgraded to "Danger High Radiation Area" & security level upgraded W/840730 Itr ALDRICH.L R. DIEDERICH.O J Gommonwealth Edison Co 84/07/30 3pp 25994 069 24% Fiche 50-373, B4/07/30, 8408090324
- 8408310361 Forwards "Excessive Cooldown Rate Event at La Salle Unit 1." technical review rept No further evaluation of problem considered nucessary SALAH, S. Reactor Operations Analysis Branch 84/08/02 SEYFRIT.K V. Reactor Operations Analysis Branch 1p 26350 265 24X Fiche 50-373,84/08/02,8409310361
- --8408310362 "Excessive Cooldown Rate Event at La Salle Unit 1." technical review rept SALAMIS Reactor Operations Analysis Branch 84/08/02 Spp 26350 266 24X Fiche 50-373,84/08/02.8408310361
- 8408200526 LER 84-023-01 on 840415, reactor water cleanup sys isolated due to high differential flow Caused by Losses through open relief valve on shell side of regenerative HX HX A string isolated W/840803 ltr
  SHIELDS.J M. DIEDERICH, O. J. Commonwealth Edison Co. 84/08/03 4pp 26138 321 24X Fiche 50-373,84/08/03.8408200526
- 8408200323 LER 84-045-00 on 840715.while deisolating reactor water cleanup filter/demineralizer during precoat cycle reactor water cleanup sys isolated Action Item Record i-84-67]13 issued for further investigation W/840809 ltr
  8HYTHE, D.R., DIEDERICH, B.J. Commonwealth Edison Co. 84/08/09 3pp 26140 082 24X Fiche 50-373,84/08/09,8408200323
- 8408310160 Part 21 rept re ground fault failures of actuation solenoids for Crosby safety relief valves PRC 84-24 Problem still considered germane condition Memo of 840808 telcon updating BAOA15 interim rept encl GIAMBALVOLE W General Electric Co 84/08/21 ROSSIC E Director's Office, Office of Inspection and Enforcement 4pp 26322 220 24X Fiche 50-373,84/08/21.8408310160
- 8408310047 LER 84-046-00 on 840727 & 28 reactor water cleanup system isolated on high differential flow while delisolating filter demineralizer C caused by partial loss of sys flow through open filter drain valves Valves closed W/840823 ltm SHYTHE.D R. DIEDERICH, J. Commonwealth Edison Co. 84/08/23 4pp 26334 360 24X Fiche 50-373,84/08/23,8408310047

# V Operator Examinations

- 8408140372 Forwards proposed rev to "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited): "in response to NUREG-0737, Item 1 A 3 1 MARSHALL.J G Commonwealth Edison Co 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation Director 2pp 26051 240 24X Fiche 50-000, 84/08/07, 8408140372
- --8408140389 "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited) " \* Commonwealth Edison Co 84/07/19 10pp 26051 242 24X Fiche 50-000, 84/08/07,8408140372
- 8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners WALKER, R D Region 3. Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051
- DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2

  F. Becurity, medical, emergency & fire protection plans
- 8404040169 Forwards exercise repts for LaSalle & Dresden offsite radiological emergency preparedness exercises conducted B20414-15 & 0629-30, respectively KRIMN,R W Faderal Emergency Management Agency 84/03/26 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 2pp 22883 122 24X Fiche 50-000,84/03/26,8404040169
- --B404040172 Evaluation of State of IL full-scale emergency preparedness exercise plan, final rept
  # Federal Engrency Management Agency 82/05/31 68pp
  # 28BB 124 24X Fiche 50-000, 84/03/26, 8404040169
- 8408010289 Forwards IE Insp Repts 50-373/84-14 & 50-374/84-18 on 840512-0618 & notice of violation SMAFER.W D Region 3, Office of Director 84/07/10 REED.C Commonwealth Edison Co 2pp 25866 103 24% Fiche 50-373,84/07/10.84

- 0294 IE Insp Repts 50-373/84-14 \* 50-374/84-18 on 840512-0418 out of the second series of the series of th
- 79 Rev 4 to Offsite Emergency Procedure LZP~1550-2. "Environs ng Supplies Inventory ' Revised Index & 840808 sittal form encl monwealth Edison Co 84/07/25 16pp 26044 332 24X 50-373.84/07/25.8498140179
- 195 Ack receipt of scope & objectives for 841010 emergency edness exercise Objectives acceptable & unchanged from scenario development meeting IEELLO, C. J. Region 3. Office of Director 84/08/01 REED, C. Quealth Edison Co. 1p. 25922 001 24X Fiche 30-373,84/08/01.
- 0101 Forwards scope & objectives for B41010 emergency paredness exercise, per NRC/FEMA requirements NRE.Y R Commonwealth Edison Co 84/07/25 HIND, J Division Energency Preparedness & Operational Support 5pp 25922 002 Fiche 50-373,84/09/01,8408060095
- 139 Forwards 1)sted revs to security plans Revs address fence a requirements Revs withheld (ref 10CFR73 21) t.D L Commonwealth Edison Co 84/08/03 Region 3. Office rector 1p 26044 252 24X Fiche 50-000, 84/08/03, 8408140139
- 101 Responds to 840705 clarification of info re util means of fying annual regulatory requirement to review emergency i levels w/offsite emergency support organizations Info IELLO, C J Region nuealth Edison Co Region 3, Office of Director 84/09/07 REED.C ison Co 1p 26010 130 24X Fiche 50-000.84/09/07.
- 30413 Responds to 840604 ltr re means for satisfying requirements 10CRR50.App E.Paragraph IV B Proposal for satisfying uirements to review emergency action levels by offsite notes clarified RAR.D L Commonwealth Edison Co 84/07/05 PAPERIELLO,C J ion 3. Offsice of Director 8pp 26010 131 24X hs 50-000.84/08/07.8408130401
- 230 Advises that 840803 Rev 19 to physical security plan stent w/provisions of 10CFR50 54(p) & acceptable ON,W L Region 3, Office of Director 84/08/14 FARRAR,D L nucelth Edison Co 2pp 26133 188 24X Fiche 50-373,84/08/14
- 233 Rev ) to Emergency Plan Implementing Procedure LZP-1510-1, rating Station Emergency Procedure Operational ness " W/840824 transmittal memo mmonwealth Edison Co 84/08/17 10pp 26322 269 24X 50-373,84/08/17,8408310233
- ISSB Forwards "Technical Basis of LaSalle County Station Fire r Surveillance Program," per 840328 agreement .B Communusalth Edison Co 84/08/21 DENTON,H R Office of ar Reactor Regulation, Director ip 26237 228 24X 50-373,84/08/21.8408270358
- '70362 "Technical Basis of LaSelle County Station Fire Damper veillance Program"

  Commonwealth Edison Co 84/08/31 326pp 26239 229 24X he 30-373.84/08/21.8408270358
- ating license stage documents & correspondence
- 1148 Forwards Amende 17 & 2 to Licenses NPF-11 & NPF-18. ctively & safety evaluation Amends change Tech Specs in line temp difference trip setpoints & allowable
- NCERIA LI ticensing Branch 2 84/07/03 FARRAR, D. Commonwea pp. 25979 043 24% Fiche 50-373.84/07/03.8408080148
- GO155 Amends 17 & 2 to Licenses NPF-11 & NPF-18, respectively, nging Tech Specs re main steamline temp difference trip points & allowable values MENCER, A Licensing Granch 2 84/07/03 Bpp 25979 045 24X he 50-373,84/07/03,8408080148
- BOIDY Bafety evaluation supporting Amends 17 & 2 to Licenses -11 & NPF-18, respectively Office of Nuclear Reactor Regulation, Director 979 053 24X Fiche 50-373, 84/07/03, 8408080148 84/07/03 2pp

- 8408280360 Ack receipt of 840710 ltr le author criticism of NRC present rules % practices Reponse to NRC seven stages of discussion listed Past tests should be reviewed % leak rate olgcussion listed past tests should be reviewed a leak rate be retested Related info enci REYTBLAIT 7 V Warren Wilson College, Swannanoa NC 84/07/22 ROSS.D F Office of Nuclear Regulatory Research, Director App 26293 OO: 24X Fiche 50-000 84/07/22,8408280360
- 840B010107 Forwards request for add1 info re NUREG-0737, Item II D 1. including basis for application of findings of NEDE-24988-P. "Analysis of Generic BRR Safety 1 Relief Valve Operability Tast Results." submitted by LNR Owners Group SCHWENGER, A Licensing Branch 2 84.07/24 [ARRAR, D L Communicath Edison Co 4pp 25873 355 24% Fishe 50-373,84/07/24, B40B010107
- 8408080314 Forwards Amend 3 to License NFF-18 & safety evaluation Amend deletes License Condition 2 c (7) & changes Toth Spocs to incorporate reactor scram on low CRD pump discharge pressure
  - mod SCHWENCER, A Li Licensing Branch & 84/07/24 FARRAR, D. Commonwealth Jpp. 25978 208 24X Fiche 50-374,84/07/24,8408080314
- ~-B408080319 Amend 3 to License NPF-18, deleting license Condition 2 c (7) & changing Tech Specs to incorporate reactor scram on low GRD pump discharge pressure mod SCHMENCER. A Licensing Branch 2 B4/07/24 lipp 25978 213 24% Fiche 50-374,84/07/24,8408080314
- --8408080322 Safety evaluation supporting Amend 3 to License NPF-18

  \* Office of Nuclear Reactor Regulation, Director 84/07/24 25978 224 24% Fiche 50-374,84/07/24,8408080314
- 8408060145 Application for amend to Licenses NPF-11 & NPF-18, changing 408060145 Application for amend to Licenses NPF-11 & NPF-18,ch Tech Specs re accident nonitoring instrumentation (NUREG-0737, Items II F 1 1.11 F 1 3 & [I F 1 6] Fee encl MARSHALL,J G Commonwealth Fdison Co 84/07/25 DENTON, H R Office of Nuclear Reactor Regulation, Director App 25925 ( 24X Fiche 50-373, 84/07/25, 8408060145
- --8408060153 Proposed Tech Spec changes re accident monitoring instrumentation limiting conditions for operation for noble gas effluent nonitors, containment high radiation monitors & containment highragen monitor \* Commonwealth Edison Co 84/07/25 9pp 25925 289 24% Fiche 50-373,84/07/25,8408060145
- 8408300508 Forwards radioactive effluent monitoring jept for Jan-June 1984 & revised process control procedure DIEDERICH G J Commonwealth Edison Co 84/07/25 KEPPLER, J G Region 3, Office of Director ip 26313 311 24x Fiche 50-373,84/07/25,8408300508
- --8408300516 Rev 2 to LAP-200-6, "LaSalle County Station Process Control Program \*

  \* Commonwealth Edison Co 83/12/29 15pp 26313 325 24X
  Fich# 50-373,84/07/25,8408300508
- 840B060144 Application for amend relaxing requirements of Amend 3 to License NPF-19, to meet requirements of License Condition 2 C (7) re effective amend date before completion of startup test program for CRD discharge pressure mod Fee encl RYBAK, B Commonwealth Edison Co 84/07/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 23723 302 24X Fiche 50-374,84/07/31,8408060144 Office of
- 8408060168 Requests NRC varate Amend 3 to License NPF-18 to allow licensee time to deternine proper low discharge setpoint on law CRD pump Setpoint setting mandated by Amend 3 may be too conservative RYBAK, B Commonwealth Edison Co 84/08/01 DENTON, H R O Nuclear Reactor Regulation, Director 2pp 23932 192 24X Fiche 50-374,84/08/01,8408040168 Office of
- B40B140405 Application to amend License NPF-1B, changing Tech Specs re reactor scram on low CRD pump discharge pressure mod Requests for emergency amend, dtd 840731 & 0801. unwarranted in that deracing or shutdown not imminent RYBAK.B Commonwealth Edison Co 84/08/02 DENTON, H R Office of Nuclear Reactor Regulation. Director 3pp 26050 356 24X Fiche 50-374.84/08/02.8408140405 Office of
- B40B070110 Generic Ltr 84-19 to all licenses of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization or Generic Safety Issues" Svc list encl EISENHUT.D 0 Division of Cicensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24x Fiche 50-000.84/08/06.8408070110

- 8408090J17 Forwards monthly status rept re plant-specific backfitting activities for operating reactors  $^{\P}$  license applicants for Jul 1984
  - Jul 1984
    TREMBLAY, P.P. Operating Reactors Assessment Branch 84/08/06
    HOLAHAN, G.H. Operating Reactors Assessment Branch 13pp
    25991 350 24X Fithe 50-000,84/08/06,8408090317
- 8408160345 Advises that QA program applicable to all nutlear generating stations & satisfies provisions of 10CFR71 Fee remitted per 10CFR170 31
  - per locker/o 31 FARRAR: D.L. Commonwealth Edison Co. 84/08/06. Office of Nuclear Material Safety & Safeguards, Director ip 26092 184 24X Fiche 50-000,84/08/06/8408160345
- B408160364 Requests authorization to use ASME Code Case N~389 Licensee will use ASME Code 1980 edition. Winter 1980 E/or Winter 1981 addenda for work during uptoming outage MARSHALL. J. G. Commonwealth Edison Co. 84/08/0/ DENTON. H. R. Office of Nuclear Reactor Regulation. Director 1p. 26091 236 24X Fiche 50-373, 84/08/0/ 200180364
- B40B160JB7 Forwards rovised pump \* valve inservice testing plans, reflecting Relief Requests RI-19 \* RV-3B from certain ASME Section XI Code requirements for containment isolation & RCIC injection outboard valves MARSHALL J G Commonwealth Edison to 84/08/07 DENTON H R Office of Nuclear Reactor Regulation. Director opp 26085 35: 24X Fiche 50-373,84/08/07.8408160387
- 8408140323 Informs that util no longer participating in instrument setpoint methodology program conducted by BWR Licensing Review Group MARSHALLIJ G Gomounwealth Edison Co 84/08/09 DENTON.H R GFFice of Nuclear Reactor Regulation, Director 1p 26042 350 24X Fiche 30-3/3,84/08/09,8408140383
- 8408220435 Forwards paid public notice re licensee 840802 application to amend GL Time constraints preclude FR publication Comment period express 840827 SCHMENCER.A Licensing Branch 2 84/08/13 FARRAR, D L Connonwealth Ed
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re schoduling guidance for licensee submittals of reloads that involve unreviewed safety questions 5vc list encl EISENNUT.D 0 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24% Fiche 50-000.84/08/20.8408200275
- 8408310450 Responds to 840807 request for authorization to use ASME Code Case N-389, "Afternate Rules for Repairs, Replacements or Mods, Section XI, Div 1" Use of Code (ase N-389 acceptable Next update to FSAR should document usage SCHMENGER, A Licensing Branch 2 84/08/28 FARRAR, D L Commanumealth Edison Co. 2pp. 26350 127 247 Fiche 50-373,84/08/28, D408310450
- @ Inspection reports, IE Bulletins & correspondence
- 8408010287 Forwards IC Insp Repts 50-373/84-14 & 50-374/84-18 on 840512-0618 & notice of violation SHAFER.W D Region 3. Office of Director 84/07/10 REED, C Commonucalth Edison Co 2pp 25866 103 24% Fiche 50-373,84/07/10,8408010287
- --8408010291 Notice of violation from insp on 840512-0618 SHAFER,W D Region 3. Office of Director 84/07/05 2pp 25866 105 24X Fiche 50-373,84/07/10,8408010289
- --8408010294 IE Insp Repts 50-373/84-14 & 50-374/84-18 on 840512-0618
  Noncompliance noted failure to control access to high
  radiation area & failure to follow reactor vessel lo-lo
  water level recirculation pump trip callbr test pracedure
  CHRISSOTIMOS, N Region 3, Office of Director 84/07/02 10pp
  25866 107 24X Fiche 50-373,84/07/10,8408010289
- B40B010312 Forwards IE Insp Rept 50-374/84-23 on 840606-22 & notice of vialation NORELIUS.C E Region 3, Office of Director 84/07/13 REED.C Commonwealth Edison Co 2pp 25866 151 24X Fiche 50-374,84/07/13. 8408010312
- --8408010314 Notice of violation from insp on 840604-22 NORELIUS, C.E. Region 3, Office of Director 84/07/13 ip 29866 153 24X Fiche 50-374.84/07/13,8408010312

- 8408010316 IE Insp Rept 50-374/84-23 on 849606-22 Noncompliance noted reactor water cleanup isolation functions for temp, differential temp or differential flow inoperable & sys not isolated for approx 7 5 h CHRISBOTIMOS, N Region 3, Office of Director 84/07/10 Spp 25866 154 24X Fiche 50-374.84/07/13.8408010312
- B407250229 IE Info Notice 84-57. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commencial Power Plants " Syr list encl JURDAN.E L Division of Emergency Proparedness & Engineering Response (Post 830,107) B4/07/27 Consolidated Edison Co of New York, Inc 117pp 25845 047 24X Fiche 50-000,84/07/27,8407250229
- 8408050085 Forwards levs to baseline insp rept (ASME Section XI)
  Deficiencies noted during util audit corrected W/o encl
  MARSHALL, J G Commonwealth Edison Co 84/07/30 DENTON, H R
  Office of Nuclear Reactor Regulation, Director 1p 25922 011 24X
  Fiche 50-373.84/07/30.840806/085
- 8408070066 Notifies of B40823 meeting w/util at Region III ofc to review findings of SALP assessment re util performance Encourages mgt representation to ensure mutual understanding of issues & findings presented by NRC NORELIUS, C E Region 3, Office of Director B4/08/03 REED, C Commonwealth Edison Co. 2pp. 25949 337 24X Fiche 50-000,84/08/03,8408/03/046
- 8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted.effective 840820 Preprinted form will be used rather than ltr

  KEPPLER. J O Region 3, Office of Director 84/08/03

  Commonwealth Edison Co 3pp 25942 188 24% Fiche 50-000,84/08/03.8408070401
- 8408010333 IE Info Notice 84-39, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York Inc 122pp 26068 001 24X Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Natice 84-60. "Failure of Air Purifying Respirator Filters to Maet Efficiency Requirement " Svc list encl JGNDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Cansolidated Edison Co of New York, Inc. 123pp 26067 158 24X Fiche 50-000,84/08/06.8408010337
- 8408230293 Forwards IE Insp Repts 50-373/84-19 & 50-374/84-25 on 840724-26 No noncompliance noted WALKER.R D Region 3. Office of Director 84/08/06 REED,C Commonwealth Edison Co 2pp 26213 251 24X Fiche 50-373.84/08/06. 8408230293
- -8408230298 IE Insp Repts 50-373/84-19 & 30-374/84-25 on 840724-26 No noncompliance or deviations noted Major areas inspected previous insp findings & startup testing audit program CHULLESN C . HAWKINS, F C Region 3, Office of Director 84/08/06 4pp 26213 253 24X Fichs 50-373,84/08/06,8408230293
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN. E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fichp 50-000,84/08/08,8408070120
- B40B140344 Confirms B40B03 plans to meet w/util on B40907 in Glen Fllyn IL to discuss regulatory improvement program NORELIUS, C E Region 3, Office of Director, B4/0B/08 REED C Commonwealth Edison Co 2pp 26041 050 24% Fiche 50-000.84/0B/0B.B40B140344
- 8408150078 Suppls 840711 response to IE Bulletin 84-02 re visual insp during monthly functional tests to verify proper contact on reactor trip sys & primary containment isolation sys relays Exemptions requested for listed relays ALEXANDER.O L Commonwealth Edison Co 84/08/08 KEPPLER.J 9 Region 3, Office of Director 3pp 24067 053 24X Fiche 50-000.84/08/08.8408150098
- 8408200331 Suppls response to IE Bulletin 84-02 re failure of GE Type HFA relays Exemption requested from commitment for visual insp verifying proper relay contact during monthly functional check for listed relays ALEXANDER: 6 L Commonwealth Edison Co 84/08/08 KEPPLER: J G Region 3. Office of Director 3pp 26132 318 24X Fiche 50-000:84/08/08:8408200331
- 8408140156 Ack receipt of 840803 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-374/84-04 LITTLE, M S Region 3, Office of Director 84/08/09 REED, C Commonwealth Edison Co 1p 26048 322 24X Fiche 50-374,84/08/07 8408140156

- --8408140169 Documents connitment made during meeting re Item 2 C of 840424 ltr on colors of control indicating lights (IE Insp Rept 50-374/84-04) Procedure & training program revs will be completed by 841001 FARAR, D & Comnonwealth Edison Co. 84/08/03 XEPPLER, J G Region 3. Office of Director 4pp 26048 323 244 Fiche 50-374,84/08/09,8408140156
- --8408140180 Suppls 840522 response to violations noted in IE Insp. Rept 50-374/84-04 Corrective actions Aperture Card M-5444 corrected & station Procedure LAP-810-5 revised FARRAR, D.L. Cammanuealth Edison Co. 84/06/14 KEPPLER, J.G. Regian G. Office of Director 4pp 26048 327 24X Fiche 50-374,84/08/09,8408140156
- ~-B408140170 Responds to NRC B40424 ltr re violations noted in 1E Insp. Rept 50-374/84-04 Corrective actions jumper added to drawing relay cleaned & labeled & wirring of indicating control lights verified FARRAR.D L Commonwealth Edison Co. B4/08/03 KEPPLER.J G Region 3. Office of Director 3pp 26048 331 24% Fiche 50-374,84/08/07,8408140156
- 8408070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list encl GRACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376
- 8408140198 Discusses IE Insp Repts 50-373/84-14 & 50-374/84-18 on 840512-0618 & forwards corrected notice of violation Response within 30 days requested SHAPER: W D Region 3. Office of Director 84/08/10 REED, C Commonwealth Edison Co ip 24092 133 24X Fiche 50-373,84/08/10.8408140198
- --B408160206 Corrected notice of violation from insp on 840512-0618
  Violations identified surveillance of unlocked high
  radiation area inattentive & failure to adhere to
  instrument surveillance procedures
  BHAFER.W D Region 3. Office of Director B4/08/10 2pp
  24092 134 24% Fichs 50-373,84/08/10,8408160198
- 840B100007 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list enct
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,840B100009
- 8408210193 Ack receipt of 840731 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-374/84-23 Corrective actions will be examined during subsequent inap NORELIUS.C E Region 3, Office of Director 84/08/14 REED.C Commonwealth Edison Co ip 26181 316 24X Fiche 30-374,84/08/14.8408210193
- -9408210203 Respunds to MRC 840713 its re-violations noted in IE Insp. Rept 50-374/84-23 Corrective actions personnel counseled, reactor water cleanup sys revised & efficient Tech Spec timeclock tracking method researched FARRAR.D L Commonwealth Edison Co 84/07/31 KEPPLER, J G Region 3. Office of Director 3pp 26181 317 24X Fiche 50-374.84/08/14,8408210193
- 840B10003B IE Info Notice 84-64. "BWR HPCI Initiation Seal-In & Indication "Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000.84/08/15.8408100038
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Syc list enc! JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24% Fiche 50~000,84/08/16,8408100021
- 8408100055 IE Info Notice 84-66. "Undetected Unavoilability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 800103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000.84/08/17.8408100055
- 840B14020B IE Info Notice 84~67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post \$20103) \$440B/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000.84/08/17.8408140208

- 8408210142 IE Info Notice 84-68. Patential Deficiency in Improperly Rated Field Wiring to Solenoid Valves "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York Inc 119pp 26329 008 24% Fiche \$0-000.84/08/21.8408210142
- R Periodic operating reports & related correspondence
- 8408300388 Forwards strata to "Rept of Radioactive Effluents," Jul-Dec 1983 Part I of 1988 operating rept for Jan-June 1984 will be submitted in Aug 1984 DIEDERICH, G. J. Commonwealth Edison Co. 81/07/23 KEPPLER, J. G. Region 3. Office of Director 1p. 26308 151 24X Fiche 50-373, 84/07/23. 8408300388
- --8408300393 Errata to "Rept or Radioactive Effluents," Jul-Dec 1983 \* Commonwealth Edison Co 83/12/31 8pp 26308 152 24X Fiche 50-373,84/07/23,8408300388
- B408300508 Forwards radioactive effluent monitoring rept for Jan-June 1984 & revised process control procedure DIEDERICH G J Commonwealth Edison Co 84/07/25 KEPPLER, J G Region 3, Office of Director 1p 26313 311 24X Fiche 50-373.84/07/25.8408300508
- --8408300513 "Rept of Radioactive Effluents." Jan-June 1984 \* Commonwealth Edison Co 84/06/30 13pp 26313 312 24 Fiche 50-373,84/07/25,8408300508
- 8408160140 Manthly operating repts for Jul 1984 W/840806 ltr DUS.R S , DIEDERICH.G J Commonwealth Edison Co 84/07/31 27pp 26108 081 24X Fiche 50-373.84/07/31.8408160140
- S Reportable occurrences, LERs & related correspondence
- 8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devires investigated SHERMCOD. G @ Oeneral Electric Co 84/04/13 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 3pp 26222 256 24% Fiche 50-000.84/04/13.8408240348
- B408060283 LER B4-032-00 on B40626, reactor water cleanup sys isolated on spurious high differential temp Div I leak detection (JM) trip Caused apparently by induced signal while performing RCIC functional test Isolation reset W/840719 ltr WITTENBURG.K C , DIEUERICH, G J Commanuealth Edison Co 84/07/19 4pp 25936 092 24% Fiche 50-374.84/07/19.8408060283
- 8408050042 LER 84-033-00 on 840608, during Startup Test 2-31, containment isolation valve did not close upon receipt of containment isolation signal Caused by solenoid valve improperly positioned Solenoid valve repositioned W/840723 ltr BRUCIAK.J D. DIEDERICH.O. J. Componwealth Edison Co. 84/07/23 4pp 25935 266 24X Fiche 50-374.84/07/23.8408060042
- 8408060107 LER 84-035-00 on 840709, while troubleshooting problem w/ electrohydraulic sys signal, technician probe slipped causing momentary loss of 30-volt power supply to sys High pressure scram occurred Trouble shooting stopped W/840724 ltr HAMMERICH, T. DIEDERICH, O. J. Commonwealth Edison Co. 84/07/24 4pp 25938 204 24X Fiche 50-374,84/07/24,8408060107
- 8408060227 LER 84-034-00 on 840703, survey of offgas carbon bed vault identified high radiation area Warning signs posted on Door 565 & security status level upgraded to high radiation status WJ840724 ltr
  ALDRICH.L R , DIEDERICH, G J Commonwealth Edison Co 84/07/24
  App 25938 137 24X Fiche 50-374,84/07/24,8408060227
- 8408070391 LER 84-036-00 on 840706, alarm received when reactor water cleanup sys isolated on high differential flow Caused by leakage past valve seat Valve 2933-2001-378 closed W/840730 ltm
- SPRUNDER.C K , DIEDERICH.G J Commonwealth Edison Co 84/07/30 4pp 25945 24B 24X Fiche 50-374.84/07/30.840807039;
- B40B070490 LFR B4-037-00 on B40718, reactor water cleanup sys isolated on high differential flow Caused by damaged sys boundary valve operator & improper fill & vent of vessel Valve operator will be repaired W/B40731 ltr
  SHIELDS, J. DIEDERICH, G. J. Commonwealth Edison Co. B4/07/31 4pp 25940 343 24X Fiche 50-374,84/07/31,8408070490
- 8408230524 LER 84-038-00 on 840717. Door 430 to reactor water cleanup HX B room left open Security alorted but checked wrong door Door immediately secured on 840718 Engineering controls investigated W/840B10 ltr EISELE.K F. DIEDERICH, G J Commonwealth Edison Co 84/08/10 4pp 26212 334 24X Fiche 50-374.84/08/10.8408230524

- B408230533 LER 84-037-00 on 840719, at 80 power, presoure switches ZE31-M022A, B, C & D found out-of-tolerance in nonconservative direction Cause not determined Switches recalibr & will be replaced during environ qualification W/840813 ltr BRUCIAK, J D . DIEDERICH, G J Commonwealth Edison Co 84/08/13 4pp 26212 344 2}% Fithe 50-374,84/08/13.8408230933
- 8408240044 LER 84-040-00 on 840725 during review of procedures, discovered drywell crane circuits not included in lech Specs Caused by circuits not being included in Tech Specs & erraneous investigation Procedure revised W/840814 ltr KLIKA.J C., DIEDERICH.G J. Commonwealth Edison Co. 84/08/14 4pp 26236 354 24X Fiche 50-374.84/08/14.8408240044
- 8408310053 LER 84-042-00 on 840728 rod sequence control sys declared inoperable & reactor manually scrammed Primary containment isolation sys Croup ! isolation also occurred Caused by failure of pressure transmitter & vacuum W/840815 ltr KALMON,K J, DIEDERICH,G J Commonwealth Edison Co 84/08/15 4pp 26335 004 24% Fiche 50-374,84/08/15,8408310053
- B408240179 LER 84-043-00 on B40812.primary containment vent & purge exceeded allowable time by 1 3 h Unit in hot shutdown at 300 F throughout purge Caused by personnel error Purge secured when violation observed W/840816 ltr
  SMIHART.O L . DIEDERICH.C J Commonwealth Edison Co 84/08/16
  4pp 26248 222 24X Fiche 50-374.84/08/16.8408240179
- 8408240114 PND-III-84-066 on 840818 RHR 8 loop full flow test valve 008240114 PND-111-84-066 on 840818,kmk B loop FULL flow tes failed to completely close manually rendering low pressure injection, shutdown cooling & suppression pool cooling inoperable Unit in cold shutdown pending repairs & maint CHRISBOITMOS, N. SHAFER, W. Region 3. Office of Director ip 26228 216 24% Fiche 50-374,84/08/20,8408240114 84/08/20
- U Congressional/Executive Correspondence
- 8408200225 Discusses Tech Spec errors discovered subsequent to NRC approval discovers run apec errors discovers subsequel approval discovers run approval discovers significance McGuire Tech Specs still under review w/no identified safety significance thus far ASBELSTINE, J K Commissioners 84/08/10 MARKEY, E J Rep : Interior & Insular Affairs 4pp 26141 244 24) Fiche 50-000,84/08/10.8408200225 Hause of 4pp 26141 244 24X
- V Operator Examinations
- 840B140372 Forwards proposed rev to "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," in response to NURECO-0737.1tom I A 3 1 MARSHALL, J C Comnonwealth Edison Co 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26051 24 24X Fiche 30-000.84/08/07,840B140372
- --8408140387 "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited) "
  \* Commenwealth Edison Co 84/07/19 10pp 26081 242 24X Fiche 30-000, 84/08/07.8408140372
- 840B140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners MALKER.R D Region 3. Office of Director 84/08/10 Michigan. Univ of. Ann Arbor, MI 2pp 26091 198 24X Fiche 50-000. 84/08/10.8408140426
- DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3 A Application/construction stage documents & correspondence
- 8408020033 Forwards revised program for resolution of 23 issues described in NRC 840613 ltr Plan examines cause generic implications & significance of issues & programmatic & mgt changes designed to preclude recurrence CAIN, J M Louisiana Pourr > Light Ca 84/07/27 EISENHUT, D G Division of Licensing 2pp 25883 232 24% Fiche 50-382, 84/07/27, 840802033 Division of Licensing 8408020033
- ~-8408020035 Revised program plan & schedule for resolution of 23 issues described in NRC 840413 ltr \* Louisiana Power & Light Co 84/07/23 28pp 25883 234 24X Fiche 50-382,84/07/27,8408020033
- 8408070iiO Generic Ltr 84-i9 to all licenses of operating reactors, applicants for CLs & holders of CPs re availability of Buppi I to NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl EISENHUT, D © Division of Licensing B4/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000,84/08/06.8408070i10

- 8408140401 Forwards resumes for NUS personnel involved u/preliminary issues task force support group inspector & auditor certificates also encl UNDD.P V NUS Corp 84/08/09 CRUTCHFIELD.D NRC - No Detailed Affiliation Given 128pp 26050 034 24x Fithe 50-382,84/08/09, RECORD 128pp 26050 034 24x Fithe 50-382,84/08/09, R 8408140401
- 8408230179 Forwards update re taxic chemical survey of industries surrounding plant Protective features will provide adequate protection for control room operators Probability of immediately dangerous levels being reached unlikely COOK.KW Louisiana Power & Light Co 84/08/09 KNIGHTON,GW Licensing Branch 3 lipp 26209 302 24% Fiche 50-382,84/08/09,8408230179
- 8408140284 Forwards response to NRC 840613 ltr Ta missing Ni instrument line documentation, instrumentation expansion loop separation, visual sxam of shop welds during hydrostatic testing & surveys & exit interviews of GA personnel CAIN.J M Louisiana Fower & Light Co 84/08/10 £ISENHUT, D G Division of Licensing 73pp 26055 001 24X Fiche 50-382,84/08/10,8408440846 8408140284
- 8408230334 Notification of 840817 meeting w/util in Bethosda.MD to discuss status & schedule of program plan for resolving 23 areas of concern identified in NRC 840613 ltr re Prelicensing issues
  WILBON.J Licensing Branch 3 84/08/10 KNIGHTON, G W Licensi
  Branch 3 3pp 26230 359 24X Fiche 50-382,84/08/10,8408230334
- 8408210378 Application to amend CPPR-103, extending completion date to LEDDICK,R S Louisiana Power & Light Co 84/08/15 EISENHUT,D @ Division of Licensing 3pp 26180 245 24X Fiche 50-382.84/08/15,8408210378
- 8408210403 Forwards "NUS Project Plan for Prelicensing Issues Task JUDD. P V NUS Corp 84/08/15 CRUTCHFIELD, D NRC - No Detailed Affiliation Given 2pp 26180 308 24% Fiche 50-382, 84/08/15,
- --8408210409 "NUS Project Plan for Prolicensing Issues Task Force Support Oraup "

  \* NUS Corp 84/08/14 7pp 26180 310 24X
  Fiche 50-382,84/08/15,8408210403
- 840B230374 Ack receipt of 840725 comments re 840428 proposed program plan Comments will be considered during evaluation of util responses to 23 areas of concern EISEN4UT,D O Division of Licensing 84/08/15 BERNABEL,L Government Accountability Project 2pp 24230 342 24X Fiche 50-382,84/08/15.8408230374
- B408210305 Submits addl info re radwaste solidification process control programs NUS Process Svcs Corp will perform initial solidification Expeditious review requested to facilitate interim approval to process wet radwastes COOK, X W Louisiana Power & Light Co 84/08/16 KNIOHTON, G W Licensing Branch 3 Spp 26181 018 24X Fiche 50-382, 84/08/16, 8408210305
- ---8408210361 Rev 1 to Surveillance Procedure RW-2-210, "Radwaste Solidification" ALLEN,J A. BARKHURST,R P. Louisiana Power & Light Co. 84/ 20pp 26181.023 24X Fiche 30-382,84/08/16,8408210305
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for DLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl LISENHUT.D 0 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24% Fiche 50-000,84/08/20,8408200275
- 8408270303 Forwards revised program plan for resolution of prelicensing issues, formalizing changes discussed during 840817 meeting LEDDICKURS Louisiana Power & Light Co 84/08/20 EISENHUT, D 9 Division of Licensing 27pp 26239 127 24X Fiche 50-382,84/08/20,8408270303
- 8408310234 Responds to request for addl info re shutdown cooling sys relief valve operability Valves will operate correctly, providing required pressure relief capacity & reclosing under actual ave conditions COOK, K W Lauistars Power & Light Co 84/08/27 KNIGHTON, O. W Licensing Branch 3 4pp 26320 330 24X Fiche 50-382, 84/08/27, 8408310236

- Security, medical, emergency & fire protection plans
- 408030266 Forwards IE Insp Rept 50-382/84-19 on 840430-0504 No violations or deviations noted GAGLIARDO, J E Region 4, Office of Director 84/05/31 LEDDICH R S Louisiana Power & Light Co 2pp 25917 251 24X Fiche 50-382,84/05/31.8408030266
- -8408030275 IE Insp Rept 50-382/84-19 on 840430-0504 No violations or deviations noted Major areas inspected security plan & implementing procedures, records & repts & physical barriers Details withheld (ref 10CFR73 21)

  EVANS, C A . KELLY, J A , CROSSMAN, W A Region 4, Office of Director 84/05/29 ip 25917 253 24X Fiche 50-382,84/05/31,8408030266
- 3408050054 Ferwards IE Insp Rept 50-382/84-22 on 840508-11 No violations or deviations noted GAGLIARDO, J E Region 4, Office of Director 84/06/12 LEDDIGK, R S Louisiana Power & Light Co 3pp 25935 278 24X Fiche 50-382,84/06/12,8408060054
- --8408060057 IE [nsp Rept 50-382/84-22 on 640508-11 No violations or deviations noted Major areas inspected security-related testing & maint, communications, contingency response & emergency power supply Details withheld (ref 10CFR73 21) KELLY, J. HALL, R. E., CROSSMAN, W. A. Region 4. Office of Director 84/06/12 1p 25735 280 24X Fiche 50-382,84/06/12,8408060054
- B408050317 Forwards IE Insp Rept 50-382/84-20 on 840409-13 & notice of deviation Proposed corrective actions & completion milestones to bring plant into conformance w/10CFR50, App R acceptable, per B40502 meeting Commitments listed GAOLIARDO, J E Region 4, Office of Director B4/07/09 LEDDICK, R S Louisiana Power & Light Co 5pp 25935 131 24X Fiche 50-382,84/07/09,8408060317
- --84080&0320 Notice of deviation from insp on 840409-13 \* Region 4, Office of Director 84/07/09 2pp 25936 136 24X Fiche 50-382,84/07/09,8408060317
- --B408060325 IE Insp Rept 50-382/84-20 on 840409-13 Deviations noted failure to provide adequate surveillance procedure to ensure min inventory of personnel protective equipment verified MURPHY.M E Region 4. Office of Director ANAND.R Office of Nuclear Reactor Regulation, Director MAURA.F Region 3. Office of Director B4/07/06 24pp 25936 138 24X Fiche 50-382,84/07/09,8408026317
- 8408070230 Forwards revised procedures generation package.per 840507 & 30 requests Submittal completes requirements of NUREO-0737.

  Suppl 1 re upgrade of emergency operating procedures COOK.K W Louisiana Power & Light Co 84/07/31 KNIGHTON.0 W Licensing Branch 3 2pp 25948 228 24X Fiche 50-382.84/07/31, 8408070230
- 340B220494 Forwards IE Insp Rept 50-382/B4-28 on 840611-15 No violations or deviations noted GAOLIARDO, J & Region 4, Diffice of Director B4/07/3; LEQDICK, R & Louisiana Power & Light Co 2pp 26196 015 24X Fiche 50-382.84/07/31,8408220494
- --8408220300 IE insp Rept 50-382/84-28 on 84061i-15 No violations or deviations noted Major areas inspected actions taken on previously identified insp findings re fire protection/prevention HARBUCK, C C , MURPHY, M E , JAUDON, J P Region 4, Office of Director 84/07/19 9pp 26196 017 24% Fiche 50-382,84/07/31,8408220494
- 3408100117 Forwards transportation support ltrs of agreement between 8tate of LA.Ofc of Emergency Preparedness, util & state support svcs Encl withheld (ref 10CFR2 790) COUK, K W Louisiana Power & Light Co 34/08/01 KNIGHTON, G W Licensing Branch 2 3pp 25988 201 24X Fiche 50-382,84/08/01,8408100117
- B40B070109 Notifies of intention to move location of backup emergency operations facility from Gretna to New Orleans, LA during Oct 1984
  CDOK, K W Louisiana Power & Light Co 84/08/02 EISENHUT, D Q Division of Licensing 3pp 25949 277 24X Fiche 50-382, 84/08/02, 84/08/0109
- B40B230295 Forwards request for add1 into re proposed safety parameter display sys Response requested 30 days prior to exceeding 5% rated power
  KNIGHTON-8 W Licensing Branch 3 B4/08/06 LEDDICK, R B
  Louisiana Power & Light Co 7pp 26236 119 24X
  Fiche 50-382,84/08/06,840B230295

- 8408130342 Discusses installation, testing 5 associated training for diesel generator panel isolation switches Commits to complete installation prior to 3% power Commitment obviates need for App R exemption requests COOK.K W Louisiana Pouer 5 Light Co 81,08/09 KNIGHTON,G W Licensing Branch 3 2pp 26010 220 24% Fiche 50-382.84/08/09, 8408130342
- B40B310225 Forwards detailed response to Question 420 01 reverification of adequate safety parameter display systematics from safety-related sys No Tech Spec changes needed NUREG-0737, Suppl i requirements met CODK.K W Louisiana Power & Light Co B4/09/27 KNIGHTON, G W Licensing Branch 3 Spp 26319 276 24x Fiche 50-382,84/08/27, B408310225

#### G Adjudicatory correspondence

- 8408070299 Discusses facts re Harstead Engineering Assoc. Inc. consultants on basemat issues at facility C Harstead participated as member of staff structural audit team during 1-wk audit at Haterford in Apr 1981
  TURK, S E Hearing Branch I D88 813 84/08/02 KOHL, C N, JOHNSON, W R, WILDER, H A Atomic Safety and Licensing Appeal Panel 9pp 25947 286 24X Fiche 50-382,84/08/02,8408070299
- B40809017B Forwards SE Turk B40802 ltr re Harstead Engineering Assoc.
  Inc evaluation of foundation basemat Possibility of conflict
  of interest arises in light of Harstead acting as consultant
  to util t NRC
  KCHL.C N , JOHNSON, W R , WILBER, H A Atomic Safety and Licensing
  Appeal Panel DSD 850 B4/0B/07 PLAINE, H H Dffice of the
  General Counsel 2pp 23973 172 24X Fiche 50-382,84/0B/07,
  B408090178
- 8408130248 Answer opposing Joint Intervenor 831212 amended & supplemental motion to reopen Contention 22 re adequacy of foundation basenat Joint Intervenor motion fails to raise significant safety or environ issue
  TURK.5 E Hearing Branch 1 DSB 900 84/08/07 Atomic Safety and Licensing Appeal Panel 9pp 26009 154 24x
  Fiche 50-382.84/08/07.8408130248
- --840B130251 Affidavit of DM Crutchfield ro NRC review & evaluation of adequacy of foundation basemat Concreto cracks & related allegations do not present significant safety or environ issue Prof qualifications encl CRUTCHFIELD.D Assistant Director for Safety Assessment 84/08/07 Lipp 26009 163 24% Fiche 50-382,84/08/07,8408130248
- ~~8408130236 Affidavit of RE Shewmaker re insp efforts technical assessment & conclusions reached concerning April/May 1984 insp Allegations re foundation basemat do not raise significant safety/environ issue Prof qualifications encl SHEWMAKER.R E Englineering & Generic Communications Branch 84/08/07 17pp 26009 174 24X Fichs 50-382,84/08/07,8408130248
- ~-8408130260 Affidavit of JP Knight re design adequacy & structural integrity of common foundation basemat Cracking observed does not affect safety of facility Prof qualifications, supporting documents & Certificate of Svc encl
  KNIGHT.JP Assistant Director for Comp & Structures Engineering (Post 830201) 84/08/07 73pp 26009 191 24X
  Fiche 50-382.84/08/07,8408130248
- B40B100001 Requests affidavit in response to listed questions re violation of federal conflict-of-interest regulations by 0 Harstead Response by 840B27 requested Served on 840B07 MALSCH, M © Office of the General Counsel DSB 88 84/08/09 CUNINGHAM, 0 H Office of the Executive Legal Director 2pp 25990 040 24X Fiche 50-3B2, 84/08/09, 840B100001
- 8408100011 Requests affidavit in response to listed questions re violation of federal conflict-of-interest regulations by G Harsteed Response by 840827 requested Served on 840809 MALSCHIM O Difice of the General Counsel DSB 887 84/08/09 CHURCHILL, B Shaw, Pittman, Potts & Trowbridge 2pp 25990 iog 24X Fiche 50-382,84/08/09,8408i00011
- B408130319 Forwards memo re transcript of meeting between Commissioner Asselstine & util.for svc on parties Served on 840810 DAVIS.P Commissioners BSB 933 84708709 CLEMENTS.W Docketing & Services Branch ip 26010 142 24X Fiche 50-382,84708709,8408130319
- --840813D324 Informs that transcript of meeting between Commissioner Asselstime & util available in PDR & LPDR DAVIS:? R Commissioners 84/08/09 Atomic Safety and Ltremsing Board Panel 1p 26010 143 24X Fiche 50~382,84/08/09, 8408130319

- --8408130328 Responds to 840723 request for review of enci transcript of briefing w/charnoff t Vane Svc of transcript recommended MALSCH./I G Office of the General Coursel 84/08/08 ASSELSTINE./ IX Commissioners 1p 26010 144 24X Fiche 50-382.84/08/09.8408130319
- --B40B130333 Forwards transcript of meeting w/Charnoff & Mane Svc on parties unnecessary Review & opinion re svc on parties requested ASSELSTINE, J. K. Office of the General Counsel B4/07/23 PLAINE, H. Office of the General Counsel 1p 26010 145 24X Fiche 50-3B2, B4/08/09, B40B130319
- ---8408130339 Transcript of 840716 meeting in Washington,DC re-plan for responding to allegations about problems at plant Pp 1-21 \* Commissioners 84/07/16 22pp 26010 146 24X Fiche 50-382,84/08/09,8408130319
- 8408150081 Forwards revised Page 22 of JP Knight 840807 affidavit Proper elecuted affidavit confirming clarification will be submitted to ASLAB upon JP Knight return Related correspondence
  TURK, S.E. Hearing Bianch 1 DSB 045 84/08/09 KOHL, C.N., JOHNSON, P.R., HILBER, H.A. Atomic Safety and Licensing Appeal Panel 3pp 26067 047 24% Fiche 50-382,84/08/09,8408150081
- 840B2B0219 Responds to 840B09 ltr re work done by Cunnar Harstead at facility Affidavits of KM Cook & G Harstead & svc list encl CHURCHILL.B W Shaw, Pittman, Potts & Trowbridge CHURCHILL.B W Louisiana Power & Light Co DSB 325 84/08/24 MALSCH.M G Office of the General Counsel Bpp 26274 335 24X Fiche 50-382,84/08/24.840820219
- 8408310106 Requests Commission act immediately in oversight of Ofc of Investigations, to ensure no further disclosure of info about targets & substance of investigation to util Svc list encl BERNABELL Government Accountability Project BERNABELL Sterra Club BERNABEL, L Citizens for Safe Energy DSB 390 84/08/29 PALLADINO, N J. ROBERTS, T M. ASSELSTING. J K Commissioners 18pp 26322 183 24% Fiche 30-382,84/08/29,8408310106
- Q Inspection reports, IE Bulletins & correspondence
- 8408030266 Forwards IE Insp Rept 50-382/84-19 on 840430-0504 No violations or deviations noted GAGLIARDO, J E Region 4, Office of Director 84/05/31 LEDDICH: R S Louisiana Power & Light Co 2pp 25917 251 R4X Fichs 50-382,84/05/31,8408030266
- --8408030275 IE Insp Rept 50-382/84-19 on 840430-0504 No violations or deviations noted Major areas inspected security plan & implementing procedures, records & repts & physical barriers Details withheld (ref 10CFR73 21)
  EVANS, C A. KELLY, J A. CRUSSMAN, W A. Region 4, Office of Director 84/05/29 ip 28917 253 24X Fiche 50-382,84/05/31,8408030266
- 8408100006 Informs of changes to 830902 commitment on IE Bulletin 83-05 rs control of Hayward Tyler Pump Co supplied spars parts
  Only parts ordered on Purchase Orders A84407-D.A84244-D or
  A84406-D affected
  COOK, K. W. Louisiana Poust & Light Co. 84/06/08 COLLINS. J. T.
  Region 4. Office of Director 2pp 25990 099 24X
  Fichs 50-382.84/06/08.8408100006
- 8408060054 Forwards IE Insp Rept 50-382/84-22 on 840508-11 No violations or deviations noted GAGLIARDO.J E Region 4, Office of Director 84/06/12 LEDDIGK R S Louisiana Power & Light Co 3pp 25935 278 24X Fiche 50-382,84/06/12,8408060054
- --8408060007 IE Insp Rept 50-382/84-22 on 840508-11 No violations or deviations noted Major areas inspected security-related testing & mainticommunications.contingency response & emergency power supply Details withheld (ref 10CFR/3 21) KELLY.J. HALL.R E. CROSSMAN,W A Region 4. Office of Director 84/06/12 ip 25735 280 24X Fiche 50-382,84/06/12,8408060054
- 8408160220 Forwards IE Insp Rept 50-382/84-21 on 840514-18 No violations or deviations noted GAGLIARDOJ E Region 4, Diffice of Director 84/06/28 LEDDIGK,R S Louisiana Power & Light Co 2pp 26106, 237 24X Fiche 50-382,84/06/28,8408160220
- ---B40B160224 IE Insp Rept 50-3B2/B4-21 on B40514-18 No violations or deviations noted Major areas inspected previously identified insp findings & selected YMI action plan requirements CHANEY.H D, MURRAY.B, CROSSMAN.W A Region 4, Office of Director B4/06/28 9pp 26106 239 24X Fiche 50-3B2.B4/06/28, B40B160220

- 8408060317 Forwards IE Insp Rept 50-382/84-20 on 840409-13 & notice of deviation Proposed corrective actions & completion milestones to bring plant into conformance w/10CFR30, App R acceptable.per 840302 meeting Commitments listed GAGLIARDD.J E Region 4. Office of Director 84/07/09 LEDDICK/R S Louisiana Power & Light Co 5pp 25936 131 24X Fiche 50-382.84/07/09.8408060317
- --8408060320 Notice of deviation from insp on 840409-13 \* Region 4, Office of Director 84/07/09 2pp 25936 136 24X Fiche 50-382,84/07/09,8408060317
- --8408060329 IE Insp Rept 50-382/84-20 on 840409-13 Deviations noted failure to provide adequate surveillance procedure to ensure min inventory of personnel protective equipment verifled MURPHY.M E Region 4, Office of Director ANAND.R Office of Nuclear Reactor Regulation. Director MAURA.F Region 3, Office of Director 84/07/06 24pp 25936 138 24X Fine 50-382, 84/07/09.8408060317
- 8408100007 Discusses IE Oulletin 84-02 re failure of OE Type HFA relays Bulletin concerns inapplicable to facility relays, based on manufacturer review util will replace Lexan coil spools COOK.K W Louisiana Power & Light Co 84/07/19 COLLING.J T Region 4. Office of Director 4pp 25990 053 24X Fiche 50-382.84/07/13.8408100007
- B40B090070 Forwards exam rept of exam administered during wk of B40624 JDHNBON.E H Region 4, Diffice of Director 84/07/20 LEDDICK.R S Louisiana Power & Light Co 2pp 25992 147 24X Fiche 50-3B2.84/07/20.8408090070
- --8408090073 Exam rept of exam administered during wk of 840624 Exam results all five candidates passed exam PELLET.JL. COULEY.R A Region 4. OPPice of Director 84/07/16 63pp 25992 149 24X Fiche 50-382.84/07/20.8408090070
- B408150510 Forwards Naterford 3 Task Force Insp Rept 50-382/84-34 on 840402-13.0423-0504 & 14-25 executive summany, potential enforcement actions & unresolved items Insp conducted to examine adequacy of GA program activities GAGLIARDO. J E Region 4. Office of Director 84/07/20 LEDDICK.R 8 Louisiana Power & Light Co 9pp 26079 234 24X Fiche 50-382,84/07/20,8408150510
- --840B150515 Waterford 3 Task Force Insp Rept 90-3B2/84-34 on 840402-13, 0423-0504 & 14-25 Insp conducted to examine allegations re adequacy of GA program activities Potential enforcement actions include failure to maintain GA records PERANICH, M Director's Office, Office of Inspection and Enforcement MULLIKIN, R, TOMLINGON, D Region 4, Office of Director 84/07/17 133pp 26077 243 24X Ficher 50-3B2, 84/07/20,8408150510
- B407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JURDAN, E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/0//27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229
- 8408220247 Forwards IE Insp Rept 50-382/84-25 on 840404-08 & notice of violation GAGLIARDUJ E Region 4, Office of Director 84/07/31 LEDDICK,R S Louisiana Power & Light Co 2pp 26189.202 24X Fiche 50-382,84/07/31,8408220247
- --8408220252 Notice of violation from insp on 840604-08 \* Region 4, Office of Director 84/07/31 2pp 26189 204, 24X Fiche 50-382,84/07/31,8408220247
- ---B408220256 IE Insp Rept 50-382/84-25 on 840604-08 Violations nated, failure to require procedures to be issued to assure Ebasco review 5 to approve vendor manuals & technical data prior to use BOARDMAN, J. R. JAUDON, J. P. Region 4, Office of Director 64/07/30 10pp 26189 206 24X Fiche 50-382,84/07/31,8408220247
- 8408220474 Forwards IE Insp Rept 50-382/84-28 on 840611-15 No violations or deviations noted GAGLIARDS, J E Region 4. Office of Director 84/07/31 LEDDICK, R 8 Louisians Power & Light Co. 2pp 26176.015 24X Fiche 50-382.84/07/31.8408220494.
- ---8408220500 IE Insp Rept 50-388/84-28 on 840611-15 No violations or deviations noted Major areas inspected actions taken on previously identified insp findings re fire protection/prevention HARBUCK/C C , MURPHY, M E , JAUDDN, J, P Region 4, Office of Director 84/07/19 9pp 26196 017 24% Fiche 30-382,84/07/31,8408220494

- B40B010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list and JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B470B/06 Consolidated Edison Co of New York, Inc. 122pp 26049 001 24X Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of Naw York, Inc. 123pp 26047 158 24X Fiche 50-000.84/08/06.8408010337
- 8408100131 Forwards vendor insp repts for evaluating significance of reported findings re quality b acceptability of product or svc provided by vendor Ack of receipt requested W/o encl JOHNSON, E H. Region 4, Office of Director 84/08/06 LEDDICK, R.S. Louisiana Power & Light Co. 2pp. 25988-281 24X
  Fiche 50~382,84/08/06/8408100131
- 8408100141 Discusses IE Insp Rept 50-382/84-34 re insp on 840402-13, 23-0304 & 14-25 Info re eight unresolved items requested to allow resolution prior to fuel load COLLING. J T Region 4. Office of Director 84/08/07 LEDDICK.R S Louisiana Power & Light Co 2pp 25988 270 24X Fiche 30-382.84/08/07.8408100141
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York, Inc. 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- B408070374 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Syc list ench ORACE.J N Division of OA. Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000.84/08/10.8408070376
- 8408100009 IE Info Notice 84-43, "Defective RHR Replacement Piping "
  Syc list encl
  JORDAN: EL Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc. 119pp 26197 218 24% Fiche 50-000.84/08/13,8408100009
- B40Bi0003B IE Info Notice 84-64. "BWR HPCI Initiation Seal-In & Indication "Svc list encl JCRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Piche 50-000.84/08/15,8408100038
- 840B100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Syc list encl JORDAN. E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc. 118pp 26198 001 24X Fiche 50-000.84/08/16,8408100021
- 408240021 Forwards Grand Oulf 1984 IE insp repts.per 840705 request NRC repts on allegations of falsification of training records forwarded to DOJ Rept contents withheld from public disclosure W/o enci
  DEYQUING.R D Director's Office. Office of Inspection and Enforcement 84708/16 WALDRUM.R L Alaska, State of 4pp 24255 353 24X Fichs 50-000.84/08/16,8408240021
- -8408240026 Requests NRC safety investigation repts for past 8 months & notification of current investigations Info needed to determine possible financial effect on State of AK, which may need to fund b buy energy from facilities.

  HALDRUMR L Alaska, State of 84/07/05 PALLADIND N Commissioners ip 26255 354 24X Fiche 50-000,84/08/16,8408240031
- 8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc. 120pp 26276 001 24X Fiche 50-000.84/08/17, 8408100055
- 8408140208 IE Info Notice 84-67, "Recent Shubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN: E L Division of Emergency Preparadness & Engineering Résponse (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000.84/08/17, 8408140208
- B408230275 Ack receipt of 840808 ltr informing NRC of steps taken to correct deviation noted in IE Insp Rept 50-382/84-20 Corrective actions will be reviewed during future insp GAGLIARDO. JE Region 4, Office of Director B4/08/17 LEDDICK.R S Louisiana Power & Light Co 2pp 26206 135 24X Fiche 50-382.84/08/17.8408230275

- --8408230284 Responds to NRC 840709 ltr re violations noted in IE Insp Rept 30-382/84-20 Corrective actions Procedure MM-7-010 revised to add check for hydrostatic tests of for fire brigade operations equipment supplied CODK.K W Louisiana Power & Light Co 84/08/08 COLLINS.J T Region 4. Office of Director 2pp 26206 137 24X Fiche 50-382,84/08/17.8408230275
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JDRDANLE L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000.84/08/21,8408210142
- S Reportable accurrences. LERs & related correspondence
- 8408010399 Second interim rept of Significant Const Deficiency 105 re electrical separation defects (Reg Guide 1 75) Next rept will be submitted on 840817 GERRETS.T F Louisiana Power & Light Co 84/07/19 COLLINS, J T Region 4, Office of Director 2pp 25866 051 24X Fiche 50-382,84/07/19.8408010399
- 8408030296 Ninth Interim Significant Const Deficiency 60 rept re turnover documentation & inadequate hanger wold problems Addi walkdowns, engineering evaluations & misor rework scheduled for completion by Aug 1784 Next rept by 840810 GERRETH.TF Louisiana Power & Light Co 84/07/19 COLLINS, J T Region 4. Office of Director 2pp 25917 287 24X Fiche 50-382,84/07/19.8408030296
- B408040032 Second interim rept of Significant Const Deficiency 108 re potential failure to comply w/FSAR safe shutdown commitment RCS pressure indication cabling rerouted from containment penetration to LCP-43 Final rept expected by 840810 OERRETS.TF Louisiana Power & Light Co 84/07/19 Region 4. Office of Director 2pp 25735 270 24X Fiche 50-382.84/07/19, 8408040032
- 8408040061 Tenth interim Bignificant Const Deficiency 88 rept re American Gridge structural steel Investigation incomplete Next rept will be submitted by 840810 OERRETS, T F Louisiana Power & Light Co 84/07/20 COLLINS, J T Region 4. Office of Director 2pp 25735 281 24x Fichs 50-382,84/07/20,8408060061
- B408090029 Supplemental rept of Potentially Reportable Deficiency 172 re changes to emergency feedwater control sys not supporting Chapter 15 of FBAR Initially reported on 840711 Final rept will be submitted by 840803 GERRETS. TF Louisiana Power & Light Co 84/07/25 COLLING, J T Region 4. Defice of Director 2pp 25992 257 24% Fiche 50-382.84/07/25.8408090029
- 8408160221 Interim Deficiency Rept 112 re design changes Contractors reviewing design Final rept to be submitted 840823 GERRETS. I F Louisiana Power & Light Co 84/07/31 COLLINS, J T Region 4. Office of Director 2pp 26106 235 24x Fiche 50-382,84/07/31,8408160221
- 8408160180 Interim potentially reportable Deficiency 172 re changes t emergancy feedwater control sys that may not support FSAR Chapter 15 Initially reported on 840611 Condition not reportable per 10CFR50 55(e)

  GERRETS T Louisiana Power & Light Co 84/08/02 COLLINS, J T Region 4, Office of Director 2pp 26106 308 24X Fiche 50-382,84/08/02,8408160180
- 8408160228 First interim Deficiency Rept 114 re possible damage to safety-related equipment due to water hammers Guestionable or damaged seismic restraints reworked Final rept will be submitted by 840831 GERRETS, T. Louisiana Power & Light Co. 84/08/02 COLLINS, J. T. Region 4. Office of Director Spp. 26106 230 24X Fiche 50-382,84/08/02.6408160228
- 8408240407 Amended final Bignificant Const Deficiency Rept 96 re failure of Charging Punp A to start on sefety injection actuation signal All relays subj to prerequisite & preoperational functional tests OERRETS.TF Louisiana Power & Light Co 84/08/09 COLLINS, J T Region 4. Office of Director 7pp 26237 106 24X Fiche 50-382,84/08/09,8408240407
- 8408290131 Eleventh interim Significant Const Deficiency Rept 7B re American Bridge structural steel defects Initially reported on 840720 Corrective action incomplete Final rept will be submitted by 840831 GERRETS, T.F. Louisiana Power & Light Co. 84/08/10 COLLINS, J.T. Region 4. Office of Director 2pp 26297 344 24X Fiche 50-382.84/08/10.8408290131

- 8408290139 Third interim Significant Const Deficiency Rept 108 re failure to comply u/FSAR safe shutdown commitment Initially reported on 840719 Verification of corrective action supporting documentation incomplete Final rept by 840831 GERRETS.T F Louisiana Power & Light Co. 84708710 COLLINS, J T Region 4. Office of Director 20p 26297 346 24X Fiche 50-382.84708710.8408290139
- 8408290145 Tenth interim Significant Const Deficiency Rept 60 returnover documentation & inadequate hanger weld Problems T & B Initially reported on 840717 Walkdowns & rework incomplete Final rept will be submitted by 840831 GERRETS, I F Louisiana Power & Light Co 84/08/13 COLLINS, J T Region 3, Office of Director 2pp 26297 348 24x Fiche 50-382,84/08/13,8408290145
- B40B280440 Fourth interio Significant Const Deficiency Rept 90 re overstressed electrical conduit Initially reported on B40716 Corrective action incomplete Final rept will be submitted by 840830 GERRETS. TF Louisiana Power & Light Co 84/08/16 COLLINS, J T Region 4. Office of Director 2pp 26282 132 24X Fiche 50-382.84/08/16.8408280440
- 8408280436 Third interim Significant Const Deficiency Rept 105 re electrical separation defects (Reg Guido 1 75) Initially reported on 840719 Rework generated by evaluations of walkdown results incomplete Next rept expected by 840831 GERRETS. TF Louisiana Power & Light Co 84708/17 COLLINS, J T Region 4. Office of Director 2pp 26282 130 24X Fiche 50-382.84/08/17,8408280436
- 8408300521 Final rept. Significant Const Deficiency 115 re unacceptably high fluoride levels in Micro-Lok insulation supplied by Johns-Manville Condition not reportable under 10CFR50 55(e) Apparently reported under Part 21 by Johns-Manville GERRETS. TF Louisiana Power & Light Co 84/08/20 COLLINS, J T Region 4, Office of Director 3pp 26313 359 24X Fiche 50-382.84/08/20 8408300521
- T Hearing transcripts on non-antitrust matters
- 8408130319 Forwards meno re transcript of meeting between Commissioner Asselstine & util.for svc on parties Served on 840810 DAVIS,P Commissioners DBB 933 B4/08/09 CLEMENTS,W Docketing & Services Branch 1p 26010 142 24X Fiche 50-382,84/08/09, 8408130319
- --8408130339 Transcript of 840716 meeting in Washington, DC re plan for responding to allegations about problems at plant Pp 1-21 \* Commissioners 84/07/16 22pp 26010 146 24X Fiche 50-382,84/08/09,8408130319
- V Operator Examinations
- 8408090070 Forwards exam rept of exam administered during wk of 840624 JDHN30N.E II Region 4. Office of Director 84/07/20 LEDDICK,R S Louisiana Power & Light Co 2pp 25992 147 24X Fiche 30-382.84/07/20.8408090070
- --8408090073 Exam rept of exam administered during wk of 840624 Exam results all five candidates passed exam PELLET, J L , COULEY.R A Region 4. Office of Director 84/07/16 Adap 25992 149 24% Fiche 30-382,84/07/20.8408090070
- BOCKET 50-387 SUBQUEHANNA STEAM ELECTRIC STATION, UNIT 1
- 8406190069 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF BUSQUEHANNA STEAM ELECTRIC STATION. UNITS 1 AND 2 Docket Nos 50-387 And 50-388 (Pennsylvania Power And Light Company, Allegheny Electric Cooperative, Incorporated) # Division of Licensing NUREG-0776 B07 84/05/31 19pp Available at NRC \$3 00 25025 253 24X Fiche 50-387,84/05/31, 8406190069
- F Security, medical, emergency & fire protection plans
- 8408200032 Forwards IE Insp Repts 50-387/84-22 & 50-388/84-28 on 840609-0715 & notice of violation STAROSTECKI:R Division of Project & Resident Programs 84/07/31 KENYON, B D Pennsylvania Power & Light Co 2pp 26140 292 24X Fichs 50-387,84/07/31.8408200032
- --8408200036 Notice of violation from insp on 840609-0715 \* Region I, Office of Director 84/07/31 1p 26140 294 24X Fiche 50-387,84/07/31.8408200032

- 840820004: IE Insp Repts 50-387/84-22 % 50-388/84-28 on 840609-0715
  Noncompliance noted two chemistry grab samples missed & fire
  detection instrumentation surveillance not performed within
  Tech Spec limits
  JACOBS.R H , PLISCO.L R Region 1. Office of Director
  MCCABE.E C Division of Project & Resident Programs 84/07/23
  26pp 26140 295 24% Fiche 50-387.84/07/31.8408200032
- 8408100125 Revs to Emergency Plan Implementing Procedures EP-IP-002 re emergency mgt notifications, EP-IP-028 re downgrade & termination & EP-IP-030 re actuation & functional operation of emergency operations facility W/840807 ltr KENYON, B D Pennsylvania Power & Light Co B4/08/07 34pp 25991 166 24x Fiche 50-387, B4/08/07, 8408100125
- 8408130127 Responds to 840602 SER re safety parameter display sys, per Buppi 1 to NUREO-0737 Secondary displays may be called up temporarily, but display always returns to primary display automatically CURTIS, N W Pennsylvania Power & Light Co 84/08/08 SCHWENCER, A Licensing Branch 2 7pp 26007 335 24X Fiche 50-387, 84/08/08, 8408130129
- G408310214 Revised emergency implementing procedures, including EP-IP-007 re personnel assembly & accountability. EP-IP-003 re dose assessment & protective actions & tables of content W/840824 ltr
  KENYON, B D Pennsylvania Power & Light Co 84/08/24 114pp 26318 170 24% Fiche 50-387, 84/08/24, 8408310214

#### I Financial information

- 8408060143 Forwards Allegheny Electric Cooperative, Inc audited financial statements for FY ending Oct 1983 CURTIS:N W Pennsylvania Power & Light Co 84/07/31 DENTON,H R Office of Nuclear Reactor Regulation. Director 16pp 25933 353 24X Fiche 50~387,84/07/31.8408060143
- P Operating license stage documents & correspondence
- B408010099 Forwards request for add1 info re applicability of generic test results for safety/relief valves submitted in NEDE-24988-P by BWR Comers Group Info needed for review of response to NUREC-0737. Item II D I YOUNGBLOOD, B J Licensing Branch 1 84/07/20 CURTIS, N W Pennsylvania Power & Light Co 3pp 25897 057 24X Fiche 50-387, 84/07/20, 8408010099
- 8408070342 Forwards viewgraphs used during 840719 meeting W/NRC refifth diesel generator project CURTIS,N & Pennsylvania Power & Light Co 84/08/02 SCHWENCER,A Licensing Branch 2 19pp 25945 210 24X Fiche 50-387,84/08/02,8408070342
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of Suppl 1 to NUREO-0933. "Prioritization of Generic Safety Issues " Svc list encl EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129,238 24X Fich 50-000,84/08/06.8408070110
- B40B200273 Generic Ltr B4-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions EVs list encl EISENHUT.D 0 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp. 26276 244 24X Fiche 50-000.84/08/20.8408200275
- 8408310426 Requests publication of FR notice of consideration of issuance of amends to Licenses NPF-14 & NPF-22 & proposed NBHC determination & opportunity for hearing resecutity SCHMENCER.A Licensing Branch 2 84/08/27 MILLER.J R Operating Reactors Branch 3 4pp 26350 178 24X Fiche 50-387,84/08/27,8408310426
- G Inspection reports, IE Bulletins & correspondence
- 8408010375 Forwards IE Insp Repts 50-387/84-23 & 50-388/84-29 on 840620 No violations moted MARTIN.T T Division of Engineering & Technical Programs 84/07/09 KENYON.B D Pennsylvania Power & Light Co 2pp 25866 056 24X Fiche, 50-387, 84/07/09, 8408010395
- --8408010398 IE Insp Repts 50-387/84-23 & 50-388/84-29 on 840620 No Violations noted Major areas inspected results of whole body counting phantom analysis comparison. Procedures & GA & calibr data for bloassay whole body counting program KOTTAN, J J , JANG, J C , PASCIAK. W J Region I, Office of Director 84/07/05 4pp 29864 058 24X Fiche 50-387,84/07/09,8408010395

- 8408080157 Forwards IE Insp Repts 50-387/84-21 & 50-388/84-26 on 840611-14 No violations noted Three nanconformance repts issued in 1982 & 1983 renain resolved MARTIN.T T Division of Engineering & Technical Programs 84/07/18 KENYON,B D Pennsylvania Pouer & Light Ca 2pp 25974 300 24% Fiche 50-387.84/07/18.8408080157
- --8408080166 IE [nsp Repts 50-387/84-21 & 50-388/84-26 on 840611-14 No violations noted Major areas inspected previous insp findings, nonlicensed technical training & GA program review
  BISSETT,P, CLIVERIA,H, SHAUB,E Region 1, Office of Director 84/07/13 12pp 25974 302 24X Fiche 50-387,84/07/18,8408080157
- 8408090040 Forwards IE Insp Repts 50-387/84-18 & 50-388/84-22 on 840508-0608 & notice of violation Insp covered Unit 1 840221 ercessive heatup rate & Unit 2 840528 turbine bypass transfent STAROBTECKIR Division of Project & Resident Programs 84/07/19 KENYON, B D Pennsylvania Power & Light Co 2pp 25994 005 24X Fiche 50-387.84/07/19.8408090040
- --8408070048 Notice of violation from insp on 840508-0608.

  \* Region 1, Office of Director 84/07/17 2pp 25994 007 24X
  Ficha 50-387,84/07/19,8408090040
- --8408090053 IE Insp Repts 50-387/84-18 & 50-388/84-22 on 840508-0608 Violations noted RCIC flow controller on Unit 2 not returned to automatic following surveillance & secondary containment integrity on Unit 1 not maintained for 2 days JACO85.R , PLISCO, L , HANGLY, K Region 1, Office of Director 84/06/28 23pp 25994 009 24X Fiche 50-387.84/07/19,8408090040
- 8408030173 Ack receipt of 840320 ltr informing NRC of stops taken to correct violations noted in 1E Insp Repts 50-387/83-30 & 50-386/83-25

  MARTIN.T T Division of Engineering & Technical Programs 84/07/24

  KENYON:B D Pennsylvania Power & Light Co 2pp 25915 317 24X

  Fiche 50-387.88/07/26.8408030173
- ~~B40B030178 Responds to NRC 840126 ltr reviolations noted in IE Insp Repts 50-387/83-30 & 50-388/83-25 Corrective actions G-list revised & 8-list will be revised by 840428 to provide programmatic control for safety impact item program KENYON.8 D Pennsylvania Power & Light Co 84/03/20 MARTIN.7 T Division of Engineering & Technical Programs 6pp 25915 319 24% Fiche 50-387.84/07/26.8408030173
- B407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, E. L. Divísion of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229
- 8408200032 Forwards IE Insp Repts 50-387/84-22 & 50-388/84-28 on 840609-0715 & notice of violation STAROSTECKIR Division of Project & Resident Programs 84/07/31 KENYON. B D Pennsylvania Power & Light Co 2pp 26140 272 24X Fiche 50-387.84/07/31.8408200032
- --8408200036 Natice of violation from insp on 840609-0715 \* Region i, Office of Director 84/07/31. 1p. 26140 294 24X Fiche 50-387,84/07/31,8408200032
- --8408200041 IE Imap Repts 50-387/84-22 & 50-388/84-28 on 840609-0715 Noncompliance noted two chemistry grab samples missed & fire detection instrumentation survaillance not performed within Tech Spec limits JACO85:R H , PLISCOLL R Region 1, Office of Director MCCABE,E C Division of Project & Resident Programs 84/07/23 26pp 26140:295 24X Fiche 50-387,84/07/31,8408200032
- 8408080257 Forwards response to Enforcement Action 84-5 & payment in amount of \$75.000 Corrective actions HPCI topa: inverter energized & HPCI steam supply valves & drain valves repositioned M/o check

  KENYON, B D Pennsylvania Power & Light Co 84/08/03 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 11pp 25765 314 24x Fiche 50-387, 84/08/03, 8408080269
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24% Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Mest Efficiency Requirement." Svc list encl lorDAN. E. L. Division of Emergency Preparedness & Engineering esponse (Fost 830103) 84/08/06 Consolidated Edison Co. of New ork. Inc. 123pp 24067 158 24X Fichs 50-000.84/08/06.8408010337

- B408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- G40B0703/6 IE Info Notice B4-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments' Svc list encl GRACE.J N Division of QA. Safeguards & Inspection Programs (Post B30103) B4/0B/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24% Fiche 50-000.
- 840B100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Ewe list encl
  JORDANA E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co. of New York, Inc. 104pp 26198 093 24X Fiche 50-000.84/08/15,8408100038
- 840B100021 IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021
- 8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York Inc 120pp 26276 001 24X Fiche 50-000.84/08/17.8408100055
- B40B14020B IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24% Fiche 50-000.84/08/17.8408140208
- 8408240108 Ack receipt of 840803 itr & payment of \$75,000 for civil penalty proposed on 840704 Corrective actions will be examined during future insps
  AXELRAD.J A Enforcement Staff 84/08/17 CALHOUN, J Pennsylvania Power & Light Co 2pp 26255 348 24X Fiche 50~387,84/08/17,8408240108
- B40B31011B Responds to request for add1 info re IE Bulletin 83-07.

  "Apparently Fraudulent Products sold by Ray Miller. Inc "
  Fraudulent practices by natl suppliers will not adversely
  affact safe rigorous GA program
  KENYON. B D Punnsylvania Power & Light Co 84/0B/17 EBNETER, S D
  Region 1. Office of Director & Opp 26322 132 24X
  Ficha 50-387.84/08/17.8408310118
- 8408210142 IE Info Notice 84~68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000.84/08/21,8408210142
- 8 Reportable occurrences, LERs & related correspondence
- B40B090395 LER 84-030-00 on 840627, boron concentration in standby liquid control tank fell to 0 4% below Tech Spec limit Cause unknown Tank level & concentration returned to within limits W/840B03 ltr KUCZYNSKI.L A, KEISER, H W Pennsylvania Power & Light Co 84/08/02 3pp 25993 278 24X Fiche 50-387,84/08/02,840B090395
- 8408090394 LER 84-031-00 on 840703, HPCI sys declared inoperable for 15 minutes Method used to seat check valve not adequate Procedural changes being evaluated W/840802 Itr RUCZYNSKI, L. A. KEISER, H. W. Pennsylvania Power & Light Co 84/08/02 3pp 25993 275 24X fiche 50-387, 84/08/02, 8408090396
- 8408070421 LER 84-029-00 on 840703, startup transformer T-10 isolated, causing trip in Unit 1 & Unit 2 reactor protection sys A. Caused by lightning strike on 230-kV transmission line. W/ 840802 ltr BTANLEY, R W , KEISER, H W Pennsylvania Power & Light Co 84/08/02 4pp 25993 228 24X Fiche 50-387,84/08/02,8408090421

- 8408210290 LER 83-046/03x-1 on 830319 during monthly surveillance on diesel generator D. fuel oil leak developed on cylinder IL. Diesel shut down Caused by fuel oil leaking around injection pump whetering shaft Pump replaced W/840802 ltr WILKS, B. L. KEISER, H. W. Pennsylvania Power & Light Co. 84/08/02 MRNLEY, T. E. Region I. Office of Director. 2pp. 26180 347—24X Fiche 50-387,84/08/02.8408210290
- 8408090439 LER 84-032-00 on 840323, staff determined that surveillance testing of immization fire detectors not performed within time allowed by Tech Specs Caused by inconsistency between Unit 1 % 2 Tech Specs Tests performed W/840803 ltr BALLEYS.T P. KEISER.H W. Ponnsylvania Power & Light Co. 84/08/03 3pp 25993 236 24% Fiche 50-387,84/08/03.8408090439
- 8408200283 LER 84-034-00 on 840715, while operating at 100% power, 230-tv transmission line experienced phase-to-phase fault resulting in generator load rejection & turbino trip Caused by line sagging into tree W/840814 ltr KUZCYNBKI.L A , KEISER, W Pennsylvania Power & Light Co 84/08/14 3pp 26139 331 24% Fiche 50-387,84/08/14.8408200283
- 8408240246 LER 84-033-00 on 840716 reactor scrammed on turbine valve fast closure Caused by loss of condenser vacuum breaker valve HV-10742C Operation procedures revised W/840815 ltr STANLEY, R W. REISER, H W. Pennsylvania Power & Light Co. 84/08/15 3pp 26236 280 24% Fiche 50-387,84/08/15,8408240246
- 8408240063 LER 84-035-00 on 840718, turbine control valve fast closure initiated by low condenser vacuum pressure resulting in reactor trip Gaused by actions taken to established valve lineup to transfer water fuel pool tank W/840817 ltr WILKE, B L . KEISER, H W Pennsylvania Power & Light Co 84/08/17 3pp 26234 360 24% Fiche 50-387.84/08/17.8408240065
- 8408300489 LER 84-036-00 on 840724, short circuit to ground developed, tripping motor-generator set & resulting in start of standby gas treatment sys Caused by grease buildup in motor of reactor protection sys A motor-generator set W/840821 ltr KUCZYNBKIL A , KEISER, H W Pennsylvania Power & Light Co 84/08/21 3pp 26314 080 24X Fiche 50-387,84/08/21 8408300489
- 8408300340 NPDES noncompliance notification on B40818-22.total suspended solids (188) in cooling tower blowdown exceeded 200 mg/! limit Caused by high 189 levels in Susquehanna River & effects of cooling sys FIELDS, J S Pennsylvania Power & Light Co 84/08/23 KOVAL, P Pennsylvania Commonwealth of. 2pp 26308 335 24X Fiche 50-387,84/08/23,8406300340

### U Congressional/Executive Correspondence

- B40B200225 Discusses Tech Spec errors discovered subsequent to NRC approval Susquehanna Tech Spec amends had no safety significance McQuire Tech Specs still under review w/no identified safety significance thus far ASBELSTINE. J K Commissioners 84/08/10 MARKEY, E J House of Rep , Interior & Insular Affairs 4pp 26141 244 24X Fiche 50-000.04/08/10.0408200225
- --8408200279 Requests further info re Tech Spec errors for specs approved since TMI-2 episode Info re near-term OL activities also requested MARKEY.E J House of Rep , Interior & Insular Affairs 84/07/12 PALLADINO.N J Commissioners ip 26142 002 24X Fiche 50-000,84/08/10.8408200225
- DOCKET 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- B404190049 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SUSQUEHANNA STEAM ELECTRIC STATION UNITS 1 AND 2 Docket Nos SO-387 And 50-388 (Pennsylvania Power And Light Company, Allegheny Electric Cooperative, Incorporated)

  \* Division of Licensing NUREO-0774 SO7 84/05/31 19pp Available at NRC \$3 00 25025 253 24X Fiche 50-387,84/05/31,8404190049
- F Security, medical, emergency & fire protection plans
- 8408200032 Forwards IE Insp Repts 50-387/84-22 & 50-388/84-28 on 840609-0715 & notice of violation BTARDSTECKLIR Division of Project & Resident Programs 84/07/31 KENYON, D Pennsylvania Power & Light Co 2pp 26/40 292 24X Fiche 50-387,84/07/31.8408200032

- --8408200041 1E Insp Repts 50-387/84-22 & 50-388/84-28 on 840409-0715 Noncompliance nated two chemistry grab samples missed & fire detection instrumentation surveillence not performed within Tech Spec limits JACOBS: R H Region 1. Office of Director 84/07/23 26pp 26140 275 24X Fiche 50-387.84/07/31.8408200032
- 8408100125 Revs to Emergency Plan Implementing Procedures EP-IP-002 re emergency mgt notifications. EP-IP-02B re downgrade & termination & EP-IP-030 re actuation & functional operation of emergency operations facility H/840807 ltr KENYON. B D Pennsylvania Power & Light Co 84/08/07 34pp 25991 166 24X Fiche 50-387,84/08/07,8408100125
- B40B130129 Responds to B40602 SER re safety parameter display sys,per Suppl 1 to NUREO-0737 Secondary displays may be called up temporarily, but display always returns to primary display automatically CURTIS, N W Pennsylvania Power & Light Co B4/0B/08 SCHWENCER, A Licensing Branch 2 9pp 26007 335 24X Fiche 50-387.84/0B/08, 8408130129
- 8408310214 Revised emergency implementing procedures, including EP-IP-007 re personnel assembly & accountability.EP-IP-003 re dose assesment & protective actions & tables of content W/840824 ltr KENYON, B D Pennsylvania Power & Light Co 84/08/24 114pp 26318 170 24X Fiche 50-387.84/08/24,8408310214

#### I Financial information

- 8408060143 Forwards Allegheny Electric Cooperative, Inc audited financial statements for FY ending Oct 1983 CURIIS,N W Pennsylvania Fower & Light Co 84/07/31 DENION,H R Office of Nuclear Reactor Regulation, Director 16pp 25933 353 24X Fiche 50-387,84/07/31,8408060143
- P Operating license stage documents & correspondence
- 8408010099 Forwards request for addl into re applicability of generic test results for safety/relief valves submitted in NEDE-24988-P by BWR Owners Group Into needed for review of response to NUREO-0737. Item II D 1 YOUNGBLOOD, B J Licensing Branch 1 84/07/20 CURTIS.N W Pennsylvania Power & Light Co 3pp 25897 057 24X Fiche 50-387.84/07/20.8408010099
- 8408070342 Forwards viewgraphs used during 840719 meeting w/NRC refifth diesel generator project CURTIS,N W Pennsylvania Power & Light Co 84/08/02 SCHWENCER,A Liconsing Branch 2 19pp 25945 210 24% Fiche: 50-387,84/08/02,
- 8408070110 Generic Ltr 84-19 to all licenses of operating reactors, applicants for GLs & holders of CPs re availability of Buppi 1 to NUREO-0933. "Prioritization of Generic Bafety Issues " Svc list encl EISENHUT-D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York. Inc. 18pp 26129 238 24X Fiche 50-000.84/08/06.8408070110
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions 8vc list encl EISENHUT.D 0. Division of Licensing 84/08/20. Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 50-000,84/08/20.8408200275
- 8408310426 Requests publication of FR notice of consideration of issuance of amends to Licenses NPF-14 & NPF-22 & proposed NBHC determination & opportunity for hearing re-security BCHWENCER. A Licensing Branch 2 84/09/27 MILLER. J. R. Operating Reactors Branch 3 4pp 26350 178 24X Fiche: 50-387. 84/08/27, 84/08310426
- Q Inspection reports. IE Bulletins & correspondence
- 8408010375 Forwards IE Insp Repts 50-387/84-23 & 50-388/84-29 on 840420 No violations noted. MARTIN,T.T Division of Engineering & Technical Programs 84/07/09. KENYON,B D Pennsylvania Power & Light Co 2pp 25866 056 24X Fiche 50-387/89/07/09.8408010395
- --8408010398 IE Insp Repts 50-387/84-23 & 50-388/84-29 on 840620 No violations noted Major areas inspected results of whole body counting phantom analysis comparison procedures & GA & calibr data for bioassay whole body counting program KOTTAN, J. J., JANG, J. C., PASCIAK, W. J., Region i. Defice of Director 84/07/05 4pp 25866 058 24X Fiche 50-387/84/07/09,8408010395

- 8408080157 Forwards IE Insp Repts 50-387/84-21 & 50-388/84-26 on 840611-14 No violations noted Three nanconformance repts issued in 1982 & 1983 renain resolved MARTIN,T T Division of Engineering & Technical Programs 84/07/18 KENYON.B D Pennsylvania Power & Light Co 2pp 25974 300 24X Fiche 50-387.84/07/18.8408080157
- --B408080166 IE Insp Repts 50-387/84-21 & 50-388/84-26 on 840611-14 No violations noted Major areas inspected previous insp findings, nonlicensed technical training & QA program review

  BISSETT,P , OLIVERIA,W , SHAUB,E Region 1, Office of Director 84/07/13 12pp 25974 302 24x Fiche 50-387,84/07/18,8408080157
- 8408090040 Forwards IE Insp Repts 50-387/84-18 & 50-388/84-22 on 840508-0608 & notice of violation Insp covered Unit 1 840221 excessive heatup rate & Unit 2 840528 turbine bypass transient STAROSTECKI.R Division of Project & Resident Programs 84/07/19 KENYON, B D Pennsylvania Power & Light Co 2pp 25994 005 24X Fiche 30-387.84/07/19.8408090040
- --B408090048 Notice of violation from insp on 840508-0608 \* Region 1, Office of Director 84/07/19 2pp 25994 007 24X Fiche 50-387,84/07/19,8408090040
- ~-8408090053 IE Insp Repts 50-387/84-18 & 50-388/84-22 on 840508-0608 Violations noted RCIC flow controller on Unit 2 not returned to automatic following surveillance & secondary containment integrity on Unit 1 not maintained for 2 days JACOBS,R : PLISCO.L : MANOLY,K Region 1. Office of Director 84/06/28 23pp 25994 009. 24X Fiche 50-387,84/07/17,8408090040
- 8408030173 Ack receipt of 840320 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/83-30 & 50-388/83-25

  MARTIN.T T Division of Engineering & Technical Programs 84/07/26 KENYON.B D Pennsylvania Pouer & Light Co 2pp 25915 317 24X Fiche 50-387.84/07/26.8408030173
- --8408030178 Responds to NRC 840126 ltr re violations noted in IE Insp Repts 50-387/83-30 & 50-388/83-25 Corrective actions Q-list revised & S-list will be revised by 840428 to provide programmatic control for safety impact item program KENYON.8 D Pennsylvania Power & Light Co 84/03/20 MARTIN.T T Division of Engineering & Technical Programs App 25915 319 24X Fiche 50-387.84/07/26.8408030173
- B407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York: Inc 1179p 25865 047 24X Fiche 30-000.84/07/27, B407250229
- 8408010162 EN-84-050 on 840727, confirmatory order issued to util confirming commitment for immediate cold shut down Action taken because of loss of ac power due to diesel generators not recieving start signal FARRON.P. AXELRAD.J Director's Office, Office of Inspection and Enforcement 84/07/30 ip 25853 304 24X Fiche 50-388,84/07/30,
- 3408200032 Forwards IE Insp Repts 50-387/84-22 & 50-388/84-28 on 840609-0715 & notice of violation STAROSTECKI: Division of Project & Resident Programs 84/07/31 KENYON: B D Pennsylvania Power & Light Co 2pp 26140 272 24X Fiche 50-387:84/07/31:8408200032
- --8408200041 IE Insp Repts 50-387/84-22 & 50-388/84-28 on 840609-0715 Noncompliance noted two chemistry grab samples missed & fire detection instrumentation surveillance not performed within Tech Spec limits

  JACOBS, R H , PLISCO, L R Region 1, Office of Director MCCABE, E C Division of Project & Resident Programs 84/07/23

  26pp 26140 295 24X Fiche 50-387,84/07/31,8408200032
- H408080269 Forwards response to Enforcement Action 84-5 & payment in amount of \$75,000 Corrective actions HPCI topaz inverter energized & HPCI steam supply valves & drain valves repositioned W/o check KENYON. B D Pennsylvania Power & Light Co 84/08/03 DEYOUNG, R C Director's Office. Office of Inspection and Enforcement 11pp 25965:314 24X Fiche 50-387,84/08/03,8408080267
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

- 8408010337 IE Info Notice 84-60. "Fallure of Air Purifying Respirator Filters to Meet Efficiency Requirement." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York. Inc. 123pp 26067 158 24% Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PHR Refunding Cavity " Svc list encl JORBAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fiche 50-000.84/08/08.8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list encl ORACE.J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York. Inc 125pp 26130 001 24X Fiche 50-000.84/08/10,8408070376
- 840B100CO7 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list encl.
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13.8408100009
- 8408100D38 IE Info Notice 84~64. "BWR HPCI Initiation Seal-In & Indication "Svc list encl JORDAN, E. L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24% Fiche S0-000.84/08/15,8408100038
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26198 001 24% Fiche 50-000.84/08/16,8408100021
- 8408100055 IE Info Notice 84-65, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 COI 24% Fiche 50-000.84/08/17,8408100055
- 8408140208 IE Info Notice 84~67, "Recent Snubber Inservice Testing W/ High Failure Rates " Bvc list and JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/09/17 Consolidated Edison Co. of New York, Inc. 122pp 26276 122 24X Fiche 50~000,84/08/17,8408140208
- 8408240108 Ack receipt of 840803 ltr & payment of \$75,000 for civil penalty proposed on 840706 Corrective actions will be examined during future insps AXECRAD. J A Enforcement Staff 84/08/17 CALHOUN, J Pennsylvania Power & Light Co 2pp 26253 348 24X Fiche 50-387,84/08/17.
- 8408310118 Responds to request for add1 info re IE Bulletin 83-07,
  "Apparently Fraudulent Products sold by Ray Miller, Inc "
  Fraudulent practices by natl suppliers will not adversely affect safe rigorous GA program
  KENYON, B D Pennsylvania Pouer & Light Co 84/08/17 EGNETER, S D
  Region 1. Office of Director 6pp 26322 132 24X
  Fiche 50-387,84/08/17.8408310118
- 8408210142 IC Info Notice 84-68, "Patential Deficiency in Improperly Rated Field Wiring to Solempid Valves " Svc list enci JDRDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24% Fiche 50-000.84/08/21,8408210142
- S Reportable occurrences. LERs & related correspondence
- 8408090269 Confirmatory action ltr rs 840726 telcon w/J Calhoun on loss of ac power during certain tests Actions should include taking unit to cold shutdown & thorough investigation into causes & implications
  MURLEY. T E Region I. Dffice of Director 84/07/26 CALHOUN, J Pennsylvania Power & Light Co. 2pp 23994 202 24X
  Fiche 50-388.84/07/26.8408090265
- 8408030197 PNG-I-84-062A on B40726 during planned loss of offsite ac power startup test at 30% reactor power backup emergency diesel generators did not automatically start Caused by incorrectly positioned dc power switches ESELGROTH-P. GREENIAN, E Region 1. Dffice of Director 84/07/27 ip 25412,018, 24% Fiche 50-388,84/07/27,8408030157

- 8408080142 LER 84-010-00 on 840627. HPCI sys doctared inoperable for 22 h to facilitate removal of startup strainer Caused by blockage in startup during heatup plateau review Startup strainer removed & ring spacer installed 4//840730 ltr STANLEY.R W. KEISER.H W. Pennsylvabia Fower & Light Co. 84/07/30 3pp 29974 334 24% Fiche 50-388,84/07/30,8408080142
- 8408090393 LER 84-011-00 on 840705 & Ob, four spurious actuations of standby gas treatment sys & control room emergency outside air supply sys experienced Caused by malfunctioning output breaker Breaker replaced M/840803 ltr KUCZYNSKI. L A , KEISEN, H W Pennsylvania Power & Light Co 84/08/03 3pp 25993 281 24X Fiche 50-388.84/08/03,8408090393
- 8408160164 LER 84-012-00 840709.core spray logic control power fuses removed since fuses thought to be possible blocking point for personnel protection Removal affected listed equipment Fuses reinstalled W/840809 ltr STANLEY, R W , REISER, H W Pennsylvania Power & Light Co 84/08/09 5pp 26108 060 24X Fiche 50-388,84/08/09,8408160164
- 8408300189 Special rept on 840528, during Startup Test 14 2, "Reactor Vessel Injections," two RCIC sys actuations resulted in injection of vater into RCS Current vsage for affected nozzles less than 0 70 KEISER. H W Pennsylvania Power & Light Co 84/08/15 MURLEY, T E Region 1. Office of Director 1p 26308 028 24% Fiche 50-388,84/08/15,8408300189
- 8408230077 Summary of 840807 operating reactor events meeting re occurrences since 840719 meeting List of attendees, significant elements & status of previous assignments encl CRUTCHFIELD. D. Assistant Director for Safety Assessment 84/08/16 EISENHUT. D. G. Division of Licensing 20pp 26233 249 24X Fiche 50-000,84/08/16.8408230077
- 8408300484 LER 84-014-00 on 840723, reactor water cleanup inlet outboard board isolation valve (2F004) closed due to high temp in filter demineralizer room Caused by problems w/reactor bldg chilled water sys W/840822 ltr
  STANLEY, R W , KEISER, H W Pennsylvania Power & Light Co 84/08/22 3pp 26314 089 24% Fiche 50-388,84/08/22,8408300484
- B40B300340 NPDES noncompliance notification on B40B18-22, total suspended solids (TSB) in cooling tower blowdown exceeded 200 mg/l limit Caused by high TSB levels in Susquehanna River & effects of cooling sys FIELDB. J S Pennsylvania Fower & Light Co B4/0B/23 KOVAL, Pennsylvania Componwealth of. 2pp 2630B 335 24X Fiche 50-387.84/0B/23.8408300340
- 840B300399 LER 84-013-00 on 840726, during scram due to turbine control valve fast closure & deenergization of 13 8 kV & 14 16 kV buses, control rods did not fully insert Caused by failure of diesel generators to start automatically W/840B24 ltr STANLEY, R W. KEIBER, H I! Pennsylvania Power & Light Co 84/08/24 57pp 26314 158 24X Fiche 50-388, 84/08/24,840B300399

## U Congressional/Executive Correspondence

- 8408200225 Discusses Tech Spec errors discovered subsequent to NRC approval Susquehanna Tech Spec amends had no safety significance tech Specs still under review w/no identified safety significance thus far ABBELSTINE, J K Commissioners 84/08/10 MARKEY, E J House of Rep. Interior & Insular Affairs 4pp 26141 244 24X Fiche 50-000,84/08/10,8408200225
- --BA08200235 Forwards technical evaluation rept re Tech Spec audit Cally discrepancy involved lack of quantitative criteria for limit switch setting & calibr for suppression chamber vacuum breakers Util should resolve rept recommendations BTAROSTECKI, R Division of Project & Resident Programs 84/04/10 EISENHUT, D 0 Division of Licensing 3pp 26141 262 24X Fiche 50-000, 84/08/10,8408200225
- --8404040095 Forwards "Audit of Susquehanna Unit 2 Tech Specs." technical evaluation rept
  PANDEV, S Franklin Institute/Franklin Research Center
  NRC-03-81-130 84/03/30 CARRINSTON,M NRC No Detailed
  Affiliation Given ip 26141 265 24X Fiche 50-000,84/08/10,8408200229
- --8404040098 "Audit of Susquehanna Unit 2 Tech Specs»" technical evaluation rept BACANSKAS,V P., MURPHY, J.A. Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-524 84/03/30 BETYENHAUSEN,L., MCCABE,E NRC - No Detailed Affiliation Given 26pp 26141 266 24x Fiche 50-000,84/08/10,8408200225

~~840B200279 Requests further info re Tech Spec errois for specs approved since TWI-2 episode Info re near-term OL activities also requested MARKEY.E J House of Rep. Interior & Insular Affairs 84/07/12 PALLADINO.N J Commissioners ip 26142 002 24% Fiche 50-000.8470B/10.840820225

DOCKET 50-389 ST LUCIE PLANT, UNIT 2

- F Security, medical, emergency & fire protection plans
- 8408010091 Forwards request for add1 info re procedures generation package for energency operating procedures Response requested within 30 days of ltr receipt MILLER.J R Operating Reactors Branch 3 84/07/17 WILLIAMS.J W Florida Power & Light Co 3pp 25897 064 24X Fiche 50-335,84/07/17.8408010091
- B408020123 Rev 1 to Off-Normal Operating Procedure 2-0970031, "Loss of SUPS Nonsafety Vital AC or Fire & Security Inverters " H/B40724 ltr WETHY.C M Florida Power & Light Co 84/07/24 5pp 25891 025 24X Fiche 50-389.84/07/24.8408020123
- 8408030126 Forwards IE Safeguards Insp Repts 50-335/84-24 & 50-389/84-26 on 840709-13 No violations or deviations noted DANCE-H C Region 2. Office of Director 84/07/30 WILLIAMS.J W Florida Power & Light Co 2pp 25916 120 24X Fiche 50-335.84/07/30.8408030126
- --8408030127 IE Safeguards Insp Repts 50-335/84-24 & 50-389/84-26 on 840709-13 No noncompliance noted Major areas inspected changes to physical security plan & implementing procedures Details withheld (ref 10CFR2 790 & 10CFR73 21) TILLMAN A Region 2, Office of Director 84/07/27 ip. 25916 122 24X Fichs 50-335.84/07/30.8408030126
- B408090009 Forwards response to 840605 request for add1 info re Rev 8 to physical security plan Response withheld (ref 10CFR73 21)
  WILLIAMS, J W Florida Power & Light Co 84/08/06 MILLER, J, R Operating Reactors Branch 1 p 25973 113 24X Fiche 50-335, 84/08/06.84308090009
- B40Bi0Q0i6 Forwards Emergency Plan Implementing Procedure EPIP-1301, "Emergency Roster Offsite Emergency Organization "WILLIAMS, J W Florida Power & Light Co B4/08/08 O'REILLY, J P Region 2. Office of Director ip 25987 006 24X Fiche 50-000.84/08/08.8408100016
- ~~\$408100054 Emergency Plan Implementing Procedure EPIP-1301. "Emergency Roster - Offsite Emergency Organization " JDHN3QN,H D Florida Power & Light Co 84/08/08 13pp 25987 007 24X Fiche 50-000.84/08/08.8408100016
- 8408130215 Notifies that responses to 840717 questions re procedure generation package for emergency operating procedures.will be provided w/assistance of C-E Owners Group Procedure Bubcommittee at 840827 meeting w/NRC reviewers WILLIAMS.J W Florida Power & Light Co 84/08/08 MILLER.J R Operating Reactors Branch 3 ip 26005 360 24X Fiche.50-335,84/08/08.8408130215
- 8408300303 Forwards FEKA "Exercise Rept on St Lucie Nuclear Power Plant Exercise on 840306 " DANCE, H C Region 2. Office of Director 84/08/14 WILLIAMS, J W Florida Power Corp 3pp 26306 151 24X Fiche 50-335.84/08/14. 8408300303
- P Operating license stage documents & correspondence
- 8408070110 Generic Ltr 84-i9 to all licenses of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0733, "Prioritization of Generic Safety Issues" Swc list encl.
  EISENHUT.D G. Division of Licensing 84/08/04 Consolidated Edison Co of New York, Inc. 18pp. 26129 238 24% Fiche 50-000.84/08/06.8408070110
- 8408070076 Forwards addl info re crack growth rates & Westinghouse methodology for determining temps for calculating crack growth rates in response to NRC 840407 request Info will be included in hext FSAR update WILLIAMS. J W Florida Power & Light Co 84/08/06 MILLER. J R. Operating Reactors Branch 3 4pp 25972:295 24X Fiche 50-387.84/08/06.8408070076

- 8408160319 Forwards "Maint & Surveillance Program Plan," revised following 840706 NRC/NUMARC meeting RUSSELL, W T Division of Human Factors Safety 84/08/07 WDDDY, C D Florida Power & Light Co ip 26126 019 24X Fiche 50-000
- B408170013 Notifies ut Class I & II fees due for 840515 & 21 Tech Spec organizational change requests Discussion of fee requirements enci MILLER.W D License Fee Management Branch 84/08/10 WILLIAMS.J W Flerida Power & Light Co 3pp 26/135 347 24X Fichs 50-335.84/08/10.8408170013
- B40B1703B9 Responds to util 840329 ltr arguing for Class II rather than Class III fee Class (II charge still holds as technical review effort was expended MILLER.W O License Fee Management Branch B4/08/10 WILLIAMS, J W Florida Power & Light Co ip 26134 196 24X Fiche 50-389.84/08/10.84081703B5
- 8408170054 Forwards info re Cycle 2 reload, per 840621 request WILLIAMS, J W Florida Power & Light Co 84/08/14 MILLER, J R Operating Reactors Branch 3 10pp 26119 006 24X Fiche 30-389, 84/08/14, 8408170054
- 8408200143 Advises that permanent refueling canal sump pump will not be installed, per 821008 commitment Mod determined unnecessary HILLIAMS, J W Florida Power & Light Co 84/08/14 EISENHUT, D G Division of Licensing ip 24133 282 24% Fiche 50-389, 84/08/14, 8408200143
- 840820200 Submits results of recalculated figures of offsite doses for fuel handling accident Calculations remain same as presented in Table 5-7 of spent fuel pool refack SAR except no credit taken for filters
  WILLIAMS.J W Florida Power & Light Co 84/08/14 MILLER, J R Operating Reactors Branch 3 ip 26/31 080 24% Fiche 50-389, 84/08/14, 8408200200
- 8408230564 Notification of 840906 & 07 meetings w/util in Bethesda, MD to discuss tentrol room design reviews
  MCDONALD, D. Q. Dperating Reactors Branch i 84/08/16 VARQA, S. A. Dperating Reactors Branch i 22p 26230 260 24x
  Fiche 50-000, 84/08/16, 8408230564
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for CLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions 8vc list enci EISENHUT.D © Division of Licensing 84/08/20 Consulidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 50-000,84/08/20.8408200275
- 8408310143 Forwards addi info re spent fuel rack submittal & summary of 840816 meeting re fuel rack structural analysis in response to 840713 request WILLIAMS, JW Florida Power & Light Co 84/08/29 MILLER, JR Operating Reactors Branch 3 63pp 26318 337 24X Fiche 50-387, 84/08/27, 8408310143

# G Inspection reports. IE Bulletins & correspondence

- 8408280236 Submits results of Ebasco Svcs review of Ray Miller, Inc supplied matls, in response to 1E Bulletin 83-07, per util 840404 1tr Ray Miller products not installed at facilities MILLIAMS, J W Florida Power & Light Co 84/06/01 0'REILLY, J P Region 2, Office of Director 2pp 26262 279 24x Fiche 50-335,84/06/01.8408280236
- 8408300395 Informs of incorrect rept number on 840530 rept.Rept 50-389/84-18 should read 50-389/84-22 DANCE.H C Region 2. Office of Director 84/06/22 WILLIAMS.J W Florida Power 2 Light Co 1p 26308 207 24% Fiche 50-335. 84/06/22.8408300395
- 840B280106 Responds to Item 2 of IE Bulletin 83-08 re electrical circuit breakers w/undervoltage trip feature Design margin available to open breakers sufficient to Justify current maint & surveillance program WILLIAMS, J W Florida Power & Light Co 84/07/02 O'REILLY, J P Region 2, Office of Director 6pp 26261 270 24x Fiche, 50-289, 84/07/02, 8408280106
- 8408280038 Responds to IE Bulletin 84-02 re failure of QE HFA relays in Class IE safety sys All Unit i relays replaced w/Tefrei series relays & spare part specs upgraded Unit 2 relays mfg w/Tefrei spools
  WILLIAMS.J W Florida Power & Light Co 84/07/18 D'REILLY, J P Region 2. Office of Director 3pp 26261 224 24X
  Fiche 50-338,84/07/18.8408280058

- 8407250227 IE Info Notice 84-57. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JURBAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229
- 8408270192 Ack receipt of 840702 ltr informing NRC of steps taken to carrect violations noted in Insp Repts 50-335/84-12 & 50-389/84-14 LENIS,R C Division of Project & Resident Programs 84/07/27 WILLIAMS,J W Florida Power & Light Co ip 26258 001 24% Fiche 50-335,84/07/27,6408270192
- --8408270200 Responds to NRC 840601 lti re violations noted in Insp Repts 50-335/84-12 & 50-387/84-14 Corrective actions calibr program under review & GA auditor counseled WILLIAMS, J W Florida Power & Light Co 84/07/02 D'REILLY, J P Region 2, Office of Director 3pp 26258 002 24x Fiche 50-335,84/07/27,8408270192
- --8408270209 Forwards Insp Repts 50-335/84-12 & 50-389/84-14 on 840423-27 & notice of violation LEWIS.R C Division of Project & Resident Programs 84/06/01 WILLIMMS.J W Florida Power & Light Co 2pp 26258 005 24X Ficho 50-335,84/07/27,8408270192
- --840B270214 Notice of violation from insp on 840423-27 \* Region 2, Dffice of Director 84/06/01 2pp 26258 007 24X Fiche 30-335, 84/07/07, BA08270192
- --8408270221 Insp Repts 50-335/84-12 & 50-389/84-14 on \$40423-27 Violations noted failure to include gauges in calibi program & failure to audit calibi program sufficiently BELISLE, G A , FOSTER, L C , UPRIGHT, C M Region 2, Office of Director 84/05/25 15pp 26258 009 24X Fiche \$0-335,84/07/27,8408270192
- 8408270340 Forwards Insp Repts 50-335/84-21 & 50-389/84-23 on B40410-0714 No violations or deviations noted DANCE, II C Region 2. Office of Director 84/07/27 WILLIAMS, J W Florida Power & Light Co 2pp 26257 221 24X Fichs 50-335,84/07/27,8408270360
- --840B270363 Insp Repts 50-335/84-21 & 50-389/84-23 on 840610-0714 No violations noted Major areas inspected plant, surveillance & maint observations FEIERABEND.C D , BIBB, H E Region 2, Office of Director ELROD, S A Division of Project & Resident Programs 84/07/27 4pp 26257 223 24X Fiche 50-335,84/07/27,8408270360
- B408030126 Forwards IE Bafeguards Insp Repts 50-335/84-24 & 50-389/84-26 on 840709-13 No violations or deviations noted BANCE.II C Region 2, Office of Director 84/07/30 WILLIAMS, J W Florida Power & Light Co 2pp 25916 120 24X Fiche 50-335,84/07/30,8408030126
- ---B408030127 IE Bafeguards Insp Repts 50-335/84-24 & 50-389/84-26 on B40709-13 No noncompliance noted Major areas inspected changes to physical security plan & implementing procedures Details withheld (ref 10CFR2 790 & 10CFR73 21) TILLMAN.A. MCGUIRE.D R Region 2. Office of Director B4/07/27 ip 25916 122 24X Fiche 50-335.84/07/30.8408030126
- B40B270291 Ack receipt of 840709 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-335/B4-18 & 50-397/84-19

  DANCE H C Region 2. Office of Director B4/08/02 WILLIAMS J W Florida Power & Light Co ip 24258 178 24X Fichs 50-335. B4/08/02. B40B270291
- --8408270298 Responds to NRC 840408 ltr re violations noted in Insp Repts 50-335/84-18 & 50-387/84-19 Corrective actions installed detectors will be replaced & two spare detectors properly calibr WILLIAMS, J W Florida Power & Light Co 84/07/09 O'REILLY, J P Region 2, Office of Director 2pp 26258 179 24x Fiche 50-335, 84/08/02, 8408270291
- --8408270306 Forwards Insp Repts 50-335/84-18 & 50-389/84-19 on 840814-18 & notice of violation DANCE:H C Region 2: Office of Director 84/06/08 WILLIAMS, J W Floride Power & Light Co 2pp 26258 181 24X Fiche \$0-335,84/08/02:8408270291
- ---8408270310 Natice of violation from insp on 840514-18 \* Region 2, Office of Director 84/06/08 1p 26258 183 24X Ficha 50-335,84/08/02,8408270291

- --8408270317 Insp Repts 50-335/84-18 \* 50-389/84-19 on 840514-18
  Noncompliance noted failure to certify proper vendor
  calib\* of containment high-range radiation monitors prior
  to initial use
  WRAY, J R . JENKINS, G R Region 2. Office of Director 84/06/08
  6pp 26298 184 244 Fiche 50-335,84/08/02,8408270291
- 840B010333 IE Into Notice 84-59, 'Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN, & L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26058 001 24% Fiche 50-000.84/08/06,8408010333
- 8408010037 IE info Notice 84-60, "Failule of Alt Purifying Respirator Filters to Meet Efficiency Requirement' Svc list encl JORDAN & L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 26067 158 24X Fiche 50-000,84/08/06.8408010337
- 8408070120 IE Info Notice 84-61, "Diverexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York, Inc. (20pp. 26129 118 24X Fiche 50-000,84/08/08,8408070120
- B408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list ent!
  GRACE,U N Division of QA. Safeguards & Inspection Programs (Post 830103) B4708/10 Consulidated Edison Co of New York, Inc 125pp 26130 001 24x Fiche 30-000: 84708/10:8408070376
- B408100007 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408100038 IE Info Notice 84-64, "BNR HPCI Initiation Seal-In & Indication "Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24% Fiche 50-000,84/08/15,8408100038
- 840B100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50~000,84/08/16,8408100021
- 8408100059 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Syc list ancl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830107) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000.84/08/17,8408100055
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84~68, "Patential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc. 1199p 26329 008 24X Fiche 50~000.84/08/21.8408210142
- 8 Reportable occurrences, LERs & related correspondence
- B40B220317 Part 21 rept re failure of ITE-27N undervoltage relay to drap out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diade must be added Affected units listed DUVALI.D D Broun Boveri Corp (subs of Brown Boveri & Co., Ltd.) B4/03/13 DEYGUNG.R C Director's Office, Office of Inspection and Enforcement Jpp 26191 357 24X Fiche 50-000.84/03/13.8408220317
- V Operator Examinations
- 8408300392 Confirms that operator who failed Section 7 of NRC senior reactor operator upgrade written exam, administered on 840619; has been prohibited from performing licensed duties O'REILLY, J P Region 2, Office of Director 84/08/13 WILLIAMS, J W Fiche 10 Page 12 Light Co 2pp 26308 120 24% Fiche 50-335,64/08/13,6408300392

- DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8408010172 Forwards updated environ info re electrical equipment qualification Evaluation assessing addl equipment qualification in progress & info will be provided by 840803, for review MILLS,L M Tennessee Valley Authority 84/07/24 ADENSAM,E Licensing Branch 4 1780pp 29875 168 24X Fiche 90-390,84/07/24, 8408010172
- 8408030128 Requests meeting to discuss proposed mod to draft App A Tech Specs Mod changes Tech Specs to increase allowable RCS isolation valve leakage from current draft Tech Spec limitation of 1 gpm to 9 gpm MILLS.L M Tennessee Valley Authority 84/07/27 ADENSAM, & Licensing Branch 4 2pp 25916 123 24X Fiche 50-390,84/07/27, 8408030128
- 8408130375 Forwards summary rept of util intent to use add1 diesel generator, including info me design & const of diesel generator & associated structure MILLS.L M Tennessee Valley Authority 84/07/30 O'REILLY.J P Region 2. Office of Director 2pp 26010 305 24X Fiche 50-390,84/07/30,8408130375
- 8408160425 Summary of 640720 meeting w/utils & Westinghouse recontainment analysis & superheat effects on environ qualification
  WIGGINTON, D.L. Operating Reactors Branch 1 84/07/30 Operatin
  Reactors Branch 1 4pp 26143 265 24X Fiche 50-000, 84/07/30, 8408160825
- B408090428 Notification of 840807-08 meetings w/util in Bethesda.MD to discuse util comments on Tech Specs KENYON.T J Licensing Branch 4 84/08/03 ADENSAM,E 0 Licensing Branch 4 3pp 25984 302 24X Fiche 50-390.84/08/03.8408090428
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREC-0933, "Prioritization of Generic Safety Issues "Svc list enci EISENHUT.D © Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000.84/08/06.8408070110
- 8408130275 Forwards "Reactor Bldg Containment Integrated Leak Rate Test, Suppl," conducted on 830519-20 Info fulfills 830818 commitment & completes requirement to provide summary rept to NRC re leak rate testing MILLS,L M Tennessee Valley Authority 84/08/07 ADENSAM.E Licensing Branch 4 1p 26008 272 24X Fiche 30-390, 84/08/07, 8408130275
- --B408130280 "Reactor filds Containment Integrated Leak Rate Test, Suppl." conducted on 830519-20 \* Tunnesses Valley Authority 84/08/07 9pp 26008 273 24X Fiths 50-390.84/08/07.8408130275
- 8408300424 Confirms 840712 telcon re NRR & Region II mgt visit to site on 840816 to evaluate const & readiness for operation of plant LEWIS,R C Region 2, Office of Director 84/08/08 PARRIS,H G Tennessee Valley Authority 2pp 26313 305 24X Fiche 50-390,84/08/08.8408300424
- 8408210435 Forwards environ qualification of nonsafety-related aquipment.per iOCFR50 49(b)(2), for incorporation into 840724 submittal of updated environ qualification of safety-related electrical equipment MILLS, L M Tannesses Valley Authority 84/08/14 ADENSAM.E Licensing Branch 4 47pp 26181 208 24x Fiche 50-390,84/08/14,840821035
- B408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EIBENHUT.D 0 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche: 50-000.84/08/20.8408200275
- 8408290250 Forwards marked-up Table 3 4-1 indicating add1 RC8 pressure isolation valves & corresponding functions for use in development of Unit 1 Tech Specs MILLSI. H Tennessee Valley Authority 84/08/23 ADENSAM.E Licensing Branch 4 4pp 26270 347 24X Fiche 50-390.84/08/23 8408270250

- 8408290355 Discusses results of radiological analysis Acceptance criteria specified by SRP 15-7 4 inappropriate for application to fuel handling accident Proposed mods to Tech Specs encl HILLB.L M Tennessee Valley Authority 84/08/23 ADENSAM.E Licensing Branch 4 8pp 26289 239 24X Fiche 50-390.84/08/23,8408290355
- F Security, medical, emergency & fire protection plans
- 8408240360 Forwards Insp Repts 50-390/84-46 & 50-391/84-38 on 840619-22 No violations or deviations noted Unresolved items identified in insp rept will be pursued during feture insps VERRELLI.0 M Region 2. Office of Director 84/07/13 PARRIS.H G Tennessee Valley Authority 2pp 26237 052 24X Fiche 50-390.84/07/13.8408240360
- --B408240362 Insp Repts 50-390/B4-46 & 50-391/B4-38 on 840619-22 No violations or deviations noted Major areas inspected licensee action on previous enforcement items, permanent plant fire protection features & licensee identified items MADDEN.P M , MILLER.W H , CONLON.T E Region 2. Office of Director 84/07/11 lipp 26237 054 24X Fiche 50-390.84/07/13, B408240360
- 8408030032 Confirms that Westinghouse has completed review of listed power ascension & smargency procedures, per 810914 ltr Util reviewed Westinghouse comments & appropriate revs will be made before Unit 1 stantup MILLS,L M Tennessee Valley Authority 84/07/27 ADENSAM,E Licensing Branch 4 2pp 25907 068 24X Fiche 50-390,84/07/27,8408030032
- 8408300519 Confirms 840726 telcom re 840803 mgt meeting to discuss development & implementation of 10CFR50, App R program at Watts Bar & status of Sequoyah program O'REILLY, J P Region 2. Office of Director 84/07/30 PARRIS, H O Tennessee Valley Authority 2pp 26313 300 24X Fiche 50-000, 84/07/30, 8408300519
- B408070405 Forwards IE Insp Rept 50-370/84-54 on 840707-13 No violations or deviations noted VERRELLI.D M Region 2. Office of Director 84/08/03 PARRIS, H G Tennessee Valley Authority 2pp 25942 174 24X Fiche 50-370.84/08/03.8408070405
- ---8408070409 IE Insp Rept 50-390/84-54 on 840709-13 No violations ordeviations noted Major areas inspected security plan & implementing procedures security organization & physical barriers Details withheld (ref 100FR2 790 & 73 21)

  HALL, B L , McGUIRE, D R Region 2. Office of Director 84/07/26
  1p 25942 176 24X Fiche 50-390,84/08/03,8408070405
- Q Inspection reports. IE Bulletins & correspondence
- 8408270417 Forwards Insp Repts 50-390/84-47 & 50-391/84-37 on 840617-22 No violations or deviations noted VERRELLI.D M Region 2. Office of Director 84/07/09 PARRIS, H G Tennessee Valley Authority 2pp 26256 348 24X Fiche 50-390.84/07/09.8408270417
- --8408270419 Insp Repts 50-390/84-47 & 50-391/84-39 on 840619-22 No violations or deviations noted Major areas inspected preoperational test results review followup on previous enforcement items & plant tour THOMAS.M. JAPE.F. Region 2. Office of Director 84/07/03 3pp 26256 350 24X Fiche 50-390.84/07/09.8408270417
- B408300353 Confirms B40706 telcon between R Shell & P Fredrickson re B40713 mgt meeting in Region II ofc to discuss implementation of IE Bulletin 79-02 concerning pipe support base plate designs using concrete expansion anchor bolts LEWIS.R C Region 2. Office of Director 84/07/07 PARRIS.H G Tennessee Valley Authority ip 26314 149 24X Fiche 50-390.84/07/09.8408300353
- 8408280030 Forwards Insp Rept 50-390/84-49 on 840619-22 No violations or deviations identified VERRELLI,D M Region 2, Office of Director 84/07/11 PARRIS,H 0 Tennessee Valley Authority 2pp P6282 009 24% Fiche 50-390/84/07/11
- --8408280049 Insp Rept 50-390/B4-49 on 840619-22 No violations or deviations noted Major areas inspected preoperational test performed after fuel load, review of proposed startup tests & review of preoperational tests of crames BURNETI.P T. JAPE.F Region 2. Office of Director 84/07/10 5pp 26282 011 24X Fiche.50-390.84/07/11.8408280030

- 8408240360 Forwards Insp Repts 50-390/84-46 & 50-391/84-38 on 840619-22 No violations or deviations noted Unresolved items identified in insp rept will be pursued during future insps VERRELLI,D M Region 2, Office of Pirectur 84/07/13 PARRIS,H @ Tennessee Valley Authority 2pp 26237 052 24% Fiche 50-390,84/07/13,8408240360
- --B408240362 Insp Repts 50-390/B4-46 % 50-391/B4-38 on B40619-22 No violations or deviations noted Major areas inspected licensee action on previous enforcement items permanent plant fire protection features & licensee identified items MADDEN.F M , MILLER.W H , CONLON.T E Region 2, Office of Director B4/07/11 lipp 26237 054 24X Fiche 30-390,84/07/13,8408240360
- 8408270463 Forwards Insp Rept 50-390/84-48 on 840626-29 No violations or deviations identified VERRELLI, D M Region 2. Office of Director 84/07/13 PARRIB, H & Tennessee Valley Authority 2pp 26256-222 24% Fiche 50-390,84/07/13,8408270463
- --8408270469 Insp Rept 50-390/84-48 on 840626-29 No violations or deviations identified Major areas inspected safety-related pipe support & restraint sys & licensee action on previous enforcement matters LIU.W.C., YORK.J.W., BLAKE.J.J. Region 2. Office of Director 84/07/12 App 26255-224 24X Fiche 50-390.84/07/13,8408270463
- 8407230229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc. 119pp 25865-047 24X Fiche 50-000.84/07/27,8407250229
- B408070405 Forwards IE Inso Rept 50-390/B4-54 on 840709-13 No violations or deviations noted VERRELLI.D M Region 2. Office of Director 84/08/03 PARRIS.H G Tennessee Vallya Authority 2pp 25942 174 24X Fiche 50-390.84/08/03.8408070405
- --840B070409 IE Insp Rept 50-390/84-54 on 840709-13 No violations ordeviations noted Major areas inspected security plan & inplementing procedures, security organization & physical barriers Details withheld (ref 10CFR2 790 & 73 21)
  HALL.8 L. MCQUIRE.D R Region 2. Office of Director 84/07/26
  1p 25942 176 24X Fiche 50-390.84/08/03.8408070403
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 24048 001 24% Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 24047 138 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of Neu York, Inc. 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- 8408070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list enc! ORACE, J N Division of QA, Bafeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125p 26130 001 24X Fiche 50-000.84/08/10.8408070376
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JDRDAN.E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc. 119pp 26197 218 24X Fiche 50-000.84/08/13,8408100009
- B40B10003B IE Info Notice B4-64, "BWR HPCI Initiation Seal-In & Indication " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,840B100038
- 8408100021 IE Info Notice 84~65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26178 001 24X Fiche 50-000,84/08/16,8408100021

- 8408100055 IE Info Notice 84-66. Undetected Unavailability of Turbine-Driven Auriliary Feeduater Train "Svc list encl JORDAN,E L Drivision of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co Vork. Inc 120pp 26276 001 24% Fiche 50-000.84/08/17,8408 17 Consolidated Edison Co of New 24x Fiche 50-000,84/08/17,8408100055
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates" Svc list encl JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000.84/08/17,8408140208
- B408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list enci JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26327 008 24X Fiche 50-000,84/08/21,8408210142
- 840B280215 Forwards GA [Insp Rept 999000255/83-01 re defective capstan spring tangs in PSA-1 & PSA-3 mechanical snubbers mfg by Pacific Scientific Co Process requiring vendor to form spring before age hardening specified ZEGH, G G Vendor Program Branch 84/08/22 LEWIS, R C Division of Project & Resident Programs App 26274 301 24% Fiche 30-000.84/08/22,8408280215

#### S Reportable occurrences LERs & related correspondence

- 8408090065 Final deficiency rept for Unit 1 & first interim deficiency rept for Unit 2 re RMR pump miniflow low flow rate Initially reported on 840618 Caused by design error Two 3 to 2-inch reducers & 2-inch control valves replaced MILLS,L M Tennessee Valley Authority 84/07/18 O'REILLY,J P Region 2. Office of Director 2pp 25992 143 24X Fiche 50-390,84/07/18 8408090065
- 8408090078 First interim deficiency rept re thermal overload relay heater elements for fan notois failing to start Initially reported on 840622 Investigation continuing Next rept will reported on MADASS Investigation continuing Next repose submitted by 840815
  MILLS,L M Tennessee Valley Authority 84/07/20 (
  Region 2. Office of Director 2pp 25992 360 24x
  Fiche 50-390.84/07/20.8408090078 D'REILLY, J P
- 8408140173 Final deficiency rept re generic implication reviews for const projects Rev 4 te QAP 16 1 issued to mare clearly define intra-ofc responsibility for determining generic implications of nonconformance MILLS.L M Tonnessee Valley Authority 84/07/24 O'REILLY, J P Region 2, Office of Director 2pp 26108 045 24% Fiche 50-000.84/07/24.8408160173
- 8408140154 Final deficiency rept for Unit 1 % third interim rept for Unit 2 re moisture intrusion into safety-related equipment Initially reported on 840229 Devices in Unit 1 sealed Next rept for Unit 2 will be submitted by 850124 MILLS,L M Tennessee Valley Authority 84/07/27 D'REILLY,J P Region 2, Office of Director 2pp 26108 065 24X Fiche 50-390,84/07/27.8408140154
- 8408030023 PND-11-84-045 on 840729, senior resident inspector W Swan fatally injured in traffic accident Funeral svcs held 840801 in Athens, TN JULIAN, C A. VERRELLI, D M Region 2, Office of Director 84/07/30 ip 25907 086 24% Fiche 50-390,84/07/30,8408030023
- B40B160179 Final deficiency rept re retriavability of GA records Initially reported on B40301 GA procedures revised on B4060B to incorporate handling requirements for supplier
- OC records

  MILLS,L M Tennessee Valley Authority 84/08/4

  Region 2, Office of Director 2pp 26108 042

  Fiche 50-000.84/08/01.8408160179 84/08/01 O'REILLY, J. P. 24X

#### V Operator Examinations

8408300378 Forwards summary of 840405 meeting w/util in Region II ofc re individual candidate licensing requirements & cold license candidate training program LEWIS,R C Region 2. Office of Director 84/05/08 PARRIS.H G Tennessee Valley Authority 3pp 26308 261 24X Fiche 50-390.84/05/08.8408300378

- 8408300354 Confirms 840803 conversation between HT Cuttle & DM Verrelli re 840808 mgt meeting in Region II ofc to discuss results of perator licensing exams
  LENIS-R C Region 2. Office of Director 84/08/07 PARRIS.H 0
  Tennessee Valley Authority 1p 26314 221 24X
  Fiche 50-390.84/08/07.8408300354
- DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8408010172 Forwards updated environ info re electrical equipment qualification Evaluation assessing add) equipment qualification in progress & info will be provided by 840803. for review
  MILLS.L M Tennessee Valley Authority 84/07/24 ADENSAM,E
  Licensing Branch 4 1780pp 25875 168 24X Fiche 50-390,84/07/24,
  8408010172
- 8408030128 Requests meeting to discuss proposed mod to draft App A Tech Specs Mod changes Tech Specs to increase allowable RCS isolation valve jeakage from current draft Tech Spec limitation of 1 gpm to 9 gpm MILLS, L M Tennessec Valley Authority 84/07/27 ADENSAM, E Licensing Branch 4 2pp 25916 123 24X Fiche 90-390, 84/07/27, PROPERSORS 8408030128
- 8408130375 Forwards summary rept of util intent to use addl diesel generator.including info re design & const of diesel generator & associated structure MILLS,L M Tennessee Valley Authority 84/07/30 O'REILLY,J P Region 2, Office of Director 2pp 26010 305 24K Fiche 50-390.84/07/30.8408130375
- 8408140425 Summary of 840720 meeting w/utils & Westinghouse re Containment analysis & superheat effects on environ containment annayare - 2000. qualification WIGGINTON,D L Operating Reactors Branch 1 84/07/30 Opera Pagetark Branch 1 4pp 26143 265 24X Fiche 50-000,84/07/30, Coerating Reactors Branch 1 8408160425
- 8408090428 Notification of 840807-08 meetings w/util in Bethesda.MD to discuss util comments on Tech Specs KENYUN.T J Licensing Branch 4 84/08/03 ADENBAM.E 0 Licensing Branch 4 3pp 25784 302 24X Fiche 50-390.84/08/03,8408090428
- 8408070110 Generic Ltv 84-17 to all licensees of operating reactors. applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933. "Prioritization of Generic Safety Issuee " Svc list enc! EISENHUT.D 0 Division of Licensing 84/08/04 Cunsolidated Edison Co of New York, Inc. 18pp 26127 238 24X Fiche 50-000,84/08/04.8408070110
- 8408130275 Forwards "Reactor Bldg Containment Integrated Leak Rate Test, Suppl." conducted on 830519-20 Info fulfills 830818 commitment to completes requirement to provide summary rept to NRC re leak rate testing MILLS, L M Tennessee Valley Authority 84/08/07 ADENSAM, E Licensing Branch 4 1p 26088 272 24% Fiche 30-390, 84/08/07, 8408130275
- --8409130280 "Reactor Bldg Containment Integrated Leak Rate Test, Buppl, conducted on 830519-20 \* Tennessee Valley Authority 84/08/07 9pp 26008 273 24X Fiche 50-390, 84/08/07, 8408130275
- 8408210439 Forwards environ qualification of nonsafety-related equipment, per 10CFRSO 49(b)(2), for incorporation into B40724 submittal of updated environ qualification of safety-related electrical equipment MILLS, L. M. Tennessee Valley Authority 84/08/14 ADENSAM, E. Licensing Branch 4 47pp 26181 208 24X Fiche 50-390,84/08/14, page 2016/08/14 Licensing Branch 4 47pp 8408210435
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs To scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions EVE list enci EISENHUT.D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 50-000.84/08/20.8408200275
- 8408290250 Forwards marked-up Table 3 4-1 indicating addit RCS pressure isolation valves & corresponding functions, for use in development of Unit 1 Tech Specs
  MILLES, L.M. Tennessee Valley Authority 84/08/23 ADENSAM, E. Licensing Branch 4 4pp 26290 347 24% Fiche 50-390,84/08/23, MILLS, L M Tennesse Licensing Branch 4 8408270250

- 8408290355 Discusses results of radiological analysis Acceptance criteria specified by SQP 15 7 4 inappropriate for application to fuel handling accident Proposed mods to Tech Specs encl MILLS.L M Tennessee Valley Authority 84/08/23 ADENSAM.E Licensing Branch 4 8pp 26289 239 24X Fiche 50-390.84/08/23.8408270355
- F Security, medical, emergency & fire protection plans
- B40B240360 Forwards Insp Repts 50-390/B4-46 & 50-391/B4-38 on B40619-22 No violations or deviations noted Unresolved items identified in insp rept util be pursued during future insps VERRELLI.D M Region 2. Office of Director B4/07/13 PARRIS.H G Tennessee Valley Authority 2pp 26237 052 24X Fiche 50-390.B4/07/13 B408240360
- --8408240362 Insp Repts 50-370/84-46 & 50-391/84-38 on 840619-22 No violations or deviations noted Major areas inspected licensee action on previous enforcement thems.permanent plant fire protection features & licensee identified items MADDEN.P M Region 2, Office of Director 84/07/11 lipp 26237 054 24X Fiche 50-390.84/07/13.8408240360
- 8408030032 Confirms that Westinghouse has completed review of listed power ascension & emergency procedures, per 810914 ltr Util reviewed Westinghouse comments & appropriate revs will be made before Unit i startup MILLS,L M Tennessee Valley Authority 84/07/27 ADENSAM.E Licensing Branch 4 2pp 25907 068 24X Fiche 50-390.84/07/27, 8408030032
- B408300519 Confirms 840724 telcon re B40803 mgt meeting to discuss development & inplementation of 10CFR50.App R program at Watts Bar & status of Seguoyah program O'REILLY.JP Region 2. Office of Director 84/07/30 PARRIS,H G Tennessee Valley Authority 2pp 26313 300 24X Fichs 50-000.84/07/30.8408300519
- @ Inspection reports, IE Bulletins & correspondence
- 8408270417 Forwards Insp Repts 50-390/84-47 ½ 50-391/84-39 on 840619-22 No violations or deviations nated VERRELLI.D M Region 2. Office of Director 84/07/09 PARRIS.H G Tennessee Valley Authority 2pp 26256 348 24x Fichs 50-390.84/07/09.8408270417
- --B40B270419 Insp Repts 50-390/B4-47 & 50-391/B4-39 on B40619-22 No violations or deviations noted Major areas inspected preoperational test results review followup on previous enforcement items & plant tour THONAS.M , JAPE.F Region 2, Office of Director 84/07/03 3pp 26256 350 24X Fiche 50-390,84/07/09,8408270417
- B408300353 Confirms 840705 telcon between R Shell & P Fredrickson re 840713 mgt meeting in Region II ofc to discuss implementation of IE Bulletin 79-02 concerning pipe support base plate designs using concrete expansion anchor bolts LEMIS.R C Region 2. Office of Director 84/07/09 PARRIS.H Q Tennessee Valley Authority ip 26314 149 24X Fiche. 50-390. 84/07/09. 8408300353
- 8408240360 Forwards Insp Repts 50-370/84-46 & 50-371/84-38 on 840619-22 No violations or deviations noted Unresolved items identified in insp rept will be pursued during future insps VERRELLI, D M Region 2, Office of Director 84/07/13 PARRIS, H G Tennessee Valley Authority 2pp 26237 052 24x Fiche 50-370,84/07/13,8408240360
- ---8408240362 Insp Repts 50-390/84-46 & 50-391/84-38 on 840619-22 No violations or deviations noted Major areas inspected licensee action on previous enforcement items.permanent plant fire protection features & licensee identified items MADDEN.P M . MILLER.W H . CONLON, T E Region 2. Office of Director 84/07/11 ilpp 26237 054 24X Fiche 50-390.84/07/13.8408240360
- 8407250229 IE Info Notice 84-57. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants "Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000.84/07/27,8407250229
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84708/06 Consolidated Edison Co of New York: Inc 122pp 26068 001 24% Fiche 50-000:84/08/06.8408010333

- 840B31033/ IE Info Notice 84-60. Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement "Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 26057 158 24X Fiche 50-000.84/08/06, 0408010337
- 8408070120 IE Info Notice 84-61, 'Overexposure of Diver in PWR Refueling Cavity " Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84708/08 Consolidated Edison Co. of New York, Inc. 120pp 26127 118 24% Fiche 50-000,84708/08,8408070120
- B408070376 IE Info Notice 84-62. Therapy Misadministrations to Patients Undergoing Co-60 Telethorapy Treatments ' Svc list encl CRACE,J N Division of OA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24% Fiche 50-000.84/08/10.8408070376
- 8408100009 IE Info Notice 84-63, "Detective RHR Replacement Piping "
  Svc list encl
  JORDAN.E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Cn of New
  York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408100038 IE Info Notice 84-64, "BWR HPCI initiation Scal-In & Indication " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000.84/08/15,8408100038
- 840B100021 IE Info Notice 84-69, 'Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment' Syc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc. 118pp. 26198 001 24X Fiche 50-000,84/08/16,840B100021
- B40Bi00095 IE Info Notice B4-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24% fiche 50-000.84/08/17.8408100055
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York Inc 122pp 26276 122 24% Fiche 50-000.84/08/17,8408140200
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc. 115pp 26327 008 24X Fiche 50-000,84/08/21,8408210142
- 8408280215 Forwards QA Insp Rept 997000255/83-01 re defective capstan spring tangs in PSA-1 & PSA-3 mechanical snubbers mfg by Pacific Scientific Co Process requiring vendor to form spring before age hardening specified ZECH. Q G Vendor Program Branch 84/08/22 LEWIS.R C Division of Project & Resident Programs 6pp 26274 301 24X Fiche 50-000.84/08/22.8408280215
- S Reportable occurrences, LERs & related correspondence
- 8408220317 Part 21 rept re failure of ITE-27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diode must be added Affected units listed DUVALL.DD Brown Boveri Corp (subs of Brown Boveri & Co , Ltd ) 84/03/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26191 397 24X Fiche 50-000.84/03/13,8408220317
- 8408090065 Final deficiency rept for Unit 1 & first interim deficiency rept for Unit 2 re RHR pump miniflow law flow rate Initially reported on 840618 Caused by dosign error Two 3 to 2-inch reducers & 2-inch control valves replaced MILLB.L M Tennessee Valley Authority 84/07/18 B'REILLY, J P Region 2. Office of Director 2pp 25992 143 24X Fiche 50-390.84/07/18.8408090065
- B408090078 First interim deficiency rept re thermal overload relay heater elements for fan notors failing to start Initially reported on 840622 investigation continuing Next rept will be submitted by 840815 MILLS.L M Tennessee Valley Authority 84/07/20 0'REILLY.J P Region 2. Defice of Director 2pp 25992 360 24X Fiche 50~390.84/07/20.8408090078

- 8408160173 Final deficiency tept re géneric implication reviews for const projects Rev 4 to GAP 16 i issued to nore clearly define intra-ofe responsibility for determining generic implications of nonconformance.

  MILLS.L M Tennessee Valley Authority 84,07/24 O REILLY.J P Region 2. Dffile of Director 2pp 26:08 045 24X
  Fiche 50-000.84/07/24.8408160173
- 8408160154 Final deficiency rept for Unit 1 % third interim rept for Unit 2 ie moisture intrusion into safety-related equipment Initially reported on 840229 Devices in Unit 1 sealed Nest rept for Unit 2 will be submitted by 850124 MILLS,L M Tennessee Valley Authority 84/07/27 O'REILLY,J P Region 2. Office of Director 2pp 26108 065 24X Fiche 50-390.84/07/27 8108160154
- 8408030023 PND-II-84-045 on 840729, senior resident inspector W Swan fatally injured in traffic accident Funeral secs held 840801 in Athens, TN JULIAN, C A. VERRELLI.D M Region 2, Office of Director 84/07/30 1p 25907 086 24% Fiche 50-390, 84/07/30, 8408030023
- 8408160177 Final deficiency rept re retrievability of QA records
  Initially reported on 840301 GA procedures revised on
  840408 to incorporate handling requirements for supplier
  QC records
  MILLS.L M Tennessee Valley Authority 84/08/01 O'REILLY, J P
  Region 2. Office of Director 2pp 26108 042 24X
  Fiche 50-000.84/08/01.8408160179
- DOCKET 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8408100002 Forwards emergency operating procedure generation package, in response to requirements of Generic Ltr 82-33, "Suppl 1 to NUREO-0737 Requirements for Emergency Response Capability," Section 7
  DIXON.O W South Carolina Electric \* Gas Co 84/07/30 DENTON.H R Office of Nuclear Reactor Regulation, Director 11pp 25989 310 24X Fiche 50-395,84/07/30,84081000002
- --8408100012 Rev O to Station Administrative Procedure SAP-207, "Development of Emergency Operating Procedure" \* South Carolina Electric & Gas Co 84/04/02 77pp 25989 321 24% Fiche 50-399,84/07/30,8108100002
- B40Bi30194 Forwards IE Insp Rept 50-395/84-19 on B40723-27 No violations or deviations noted VERRELLI.D M Region 2. Office of Director 84/08/07 DIXON.O W South Carolina Electric & Gas Co 2pp 26008 294 24X Fiche 50-395.84/08/07.8408130194
- ~-8408130204 IE Insp Rept 50-395/84-19 on 840723-27 No violations or deviations noted Major areas inspected security organization, security program audit & physical barriers Details withheld (ref 10CFR2 790 & 73 21) ENNIG.J D. MCGUIRE.D R. Region 2. Office of Director 84/08/03 ip 26008 296 24% Fiche 50-399.84/08/07.8408130194
- 8408130364 Revs to smergency plan procedures, including EPP-002, "Communication % Notifications," EPP-003, "In-Plant Radiological Surveying" & EPP-004, "Dut-of-Plant Radiological Surveying " W/840809 ltr DIXON,O W South Carolina Electric & Gas Co 84/08/09 O'REILLY,J P. Region 2, Office of Director 279pp 26005 001 24X Fiche 50-395,84/08/09,8408130364
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8408080187 Forwards updated FSAR for VC Summer, incorporating all procedure changes, safety evaluations & license amends DIXON, O W South Carolina Electric & Oas Co 84/08/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 26012 001 24X Fichs 50-393,84/08/02,8408080187
- --8408080192 Updated FSAR for VC Summer \* Bouth Carolina Electric & Gas Co 84/08/02 6.389pp 26012 004 24% Fiche 50-395.84/08/02.8408080187
- --8408080196 Chapter 1 to VC Summer updated FSAR. "Introduction & General Description of Plant"

  \* South Caroline Electric & Cas Co 84/08/02 213pp 26012 005 24% Fiche 50-395.84/08/02.8408080187
- --8408080200 Chapter 2 to VC Summer updated FSAR, "Site Characteristics" \* Bouth Carolina Electric & Cas Co 84/09/02 1,311pp 26012 218 24% Fiche 50-375,84/08/02,8408080187

- --8408080207 Chapter 3 to VC Summer updated FSAR, "Design of Structures, Components, Equipment 5 Sys '

  \* South Carolina Electric ' Gas Co 84/08/02 1, 201pp 26016 089 24X Fiche 50-395,84/08/02,8408080187
- --B4080B0214 Chapter 1 to VC Summer updated FSAR, "Reactor "
  # South Carolina Electric & Oas Co 84/08/02 287pp 26019 210
  24X Fiche 50-395,84/08/02,8408080187
- --8408080221 Chapter 5 to VC Summer updated FSAR, "RCS ½ Connected Sys \* South Carolina Electric ½ Gas Co 84/08/02 313pp 26020 139 24X Fiche 50-395,84/08/02,8408080187
- --8408080226 Chapter 6 to VC Summer updated FSAR, "ESF" \* South Carolina Electric & Cas Co 84/08/02 405pp 26021 092 24X Fiche 50-395,84/03/02,8408080187
- --8408080228 Chapter 7 to VC Summer updated FSAR, "Instrumentation & Controls"

  \* South Carolina Electric & Gas Co B4/08/02 J28pp 26022 337 24% Fiche 50-395,84/09/02,8408080187
- --8408080232 Chapter 8 to VC Summer updated FSAR, "Electric Power" \* South Carolina Electric & Gas Co 84/08/02 251pp 26023 305 24X Fiche 50-395.84/08/02,8408080187
- --8408080237 Chapter 9 to VC Summer updated FSAR. "Auxiliary Sys " \* Bouth Carolina Electric & Oas Co 84/08/02 486pp 26024 196 24X Fiche 50-395,84/08/02,8408080187
- --8408080240 Chapter 10 to VC Summer updated FSAR, "Steam & Power Conversion Sys " \* South Carolina Electric & Oas Co 84/08/02 163pp 26025 322 24X Fiche 50-395,84/08/02,8408080187
- --8408080244 Chapter ii to VC Summer updated FSAR, "Radwaste Mgt " \* South Carolina Electric & Gas Co 84/08/02 208pp 26026 125 24X Fiche 50-395,84/08/02,8408080187
- --8408080248 Chapter 12 to VC Summer updated FSAR, "Radiation Protection" \* Bouth Carolina Electric & Oas Co 84/08/02 227pp 26026 333 24X Fiche 50-395.84/08/02.8408080187
- --8408080251 Chapter 13 to VC Summer updated FSAR, "Conduct of Operations" \* South Carolina Electric 1 Gas Co 84/08/02 101pp 26027 200 24X Fiche 50-395, 84/08/02, 8408080187
- --8409080294 Chapter 14 to VC Summer updated FSAR, "Initial Tests & Operation"
  \* South Carolina Electric & Oas Co 84/08/02 101pp 26027 313 24X Fiche 50-395,84/08/02,8408090187
- --8408080260 Chapter 15 to VC Summer updated FSAR. "Accident Analyses" \* South Carolina Electric & Oas Co 84/08/02 437pp 26028 102 24% Fiche 50-395,84/08/02,8408080187
- --8408080262 Chapter 16 to VC Summer updated FSAR, "Tech Specs"

  \* South Carolina Electric & Gas Co 84/08/02 101pp 26029 179
  24X Fiche 50-375,84/08/02.8408080187
- --8408080265 Chapter 17 to VC Summer updated FSAR, "GA" \* South Carolina Electric & Gas Co 84/08/02 101pp 26027 180 24% Fiche 50-395,84/08/02,8408080187
- P Operating license stage documents & correspondence
- 8408060103 Advises that 820929 summary of analysis to justify continuing operation w/thermal sleeves removed from selected noizles in RCS sufficient to meet requirements of License Conduction 2 C 7
  DIXON.O W South Carolina Electric & Gas Co 84/07/31 DENTON.H R Office of Novicer Reactor Regulation, Director 2pp 25933 180 24X Fiche 50-395,84/07/31,8408060103
- 8408050140 Submits response to NRC question re effect of extended burnup fuel in postulated fuel handling accident outlined in Section 15.7.4 of SRP, as result of review of proposal to rerack spent fuel pool DIXGN.0 W South Carolina Electric & Gas Co 84/07/31 DENTON.H R Dffice of Nuclear Reactor Regulation, Director 2pp 25932 248 24X Fiche 50-395,84/07/31.8408060140

- 8408970373 Submits add1 analysis & clerifications re spent fuel pool remark structural mode, in response to concerns raised at 840725 meeting DIXON.O W South Carolina Electric & Gas Co 84/07/31 DEMTON.H Office of Nuclear Reactor Regulation. Director Spp 25947 171 24X Piche 50-395,84/07/31,8408070373
  - DENTON H R
- 840B060134 Requests relief from ASME Code, Section XI hydrostatic testing requirements for feedwater sys Relief needed to support baffle-plate insp performed during refueling outage currently scheduled for Sept 1984 Fee and DIXON, O W Gouth Carolina Electric & Qas Co 84/08/01 DENIGN, H R Office of Nuclear Reactor Regulation, Director 5pp 26067 056 24X Fiche 50-395,84/08/01,8408960134
- B408080124 Forwards updated FSAR Pages 12 1-72.13 1-17.13 1-18.13 1-19 & 13 1-20 FSAR updated as of 840301.to include facility or procedure changes. licensee performed safety evaluations & analyses of heu safety issues
  DIXON.O W South Carolina Electric & Gas Co 84/08/02 DENTON:H R
  Office of Nuclear Reactor Regulation. Director App 26276 270
  24X Fiche 50-395,84/08/02.8408080124
- B408070110 Generic Ltr 84-17 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Generic Safety Issues" Svc list encl EISENHUF, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000,84/08/06.8408070110
- 840B140265 Forwards response to NRC request for add) numerical analysis to support info contained in 840731 ltr re effect of increased fuel burnup on fuel handling accident Requests NRC resolution so Sept 1984 refueling schedule can be met DIXON.O W South Carolina Electric & Gas Co 84/08/08 DENTON.H R Dffice of Nuclear Reactor Regulation. Director 5pp 26055 239 24X Fiche 50-395,84/08/08.8408140265
- 8408220427 Summary of 840725 meeting w/util & J Oat Corp in Bethesda.MD re structural analysis performed for rerack of spent fuel pool HOPKINS, J Licensing Branch 4 84/08/15 Licensing Branch 4 78pp 26211 001 24X Fiche 50-395,84/08/15,8408220427
- 8408240002 Clarifies present fuel storage capabilities using high density racks, per 840123 application to amend License NPF-12 to modify spent fuel gool rerack hod would accommodate higher initial enrichment DIXON.O W South Carolina Electric & Gas Co 84/08/17 DENTON, Office of Nuclear Reactor Regulation, Director 2pp 26228 254 24X Fithe \$0-375,84/08/17,8408240002
- B200275 Generic Ltr 84-20 to all licensees of operating reactors & pplicants for OLs re scheduling guidance for licensee ubmittals of reloads that involve unreviewed safety juestions Bvc list encl
  EISENHUT.D 0 Division of Licensing B4/08/20 Consolidated Edison Co of New York, Inc. 17pp 2A276 244 24X
  Fiche 50-000.84/08/20.8408200275
- 408280104 Application for amend to License NPF-12, revising Tech Spec Tables 2 2-1 & 3 3-4 re reactor trip sys instrumentation trip setpoints & ESF actuation sys instrumentation trip setpoints respectively Fee paid
  DIXON.O W South Caralina Electric & Gas Co 84/08/24 DENTON, H I Office of Nuclear Reactor Regulation, Director 2pp 26239 036
  24X Fiche 50-395,84/08/24,8408280104 DENTON, H #
- --8408280114 Proposed Tech Specs, revising Tables 2 2-1 & 3 3-4 re reactor trip sys instrumentation trip setpoints & CSF actuation sys instrumentation trip setpoints, respectively

  \* South Carolina Electric & Gas Co 84/08/24 3pp 26259 058 24X Fiche 50-375,84/08/24,8408280104
- @ Inspection reports, IE Bulletins & correspondence
- 8408280287 Responds to IE Bulletin 84-02. "Failure of GE Type HFA
  Relays in Use in Class IE Sarety 8ys " Switchgoar relays
  replaced w/GE Century Series HFA relays Failure potential of
  other safety-related relays reviewed
  DIXON.O W South Carolina Electric & Gas Co 84/07/09
  D/REILLYJ P Region 2. Diffice of Director 3pp 26274 332 24X
  Fiche 50-395,84/07/09,8408280287
- 8408270561 Forwards Insp Rept 50-395/84-20 on 840801-30 No violations or deviations identified VERRELLI.D M Region 3, Office of Director 84/07/23 DIXON, Q W 80uth Carbline Electric & Ras Co 2pp 26256 103 24X Fiche 50-395

- --B408270572 Insp Rept 50-395 61-20 on 840401-30 No violations of deviations identified Hajor areas inspected operational safety verification, nonthly surveillance & maint observations, followup items, design mods thraining HEILLC W. BEMIS.P. CANTRELL.F.S. Region 2, Office of Director B4/07/20 9pp 26256 105 24X Fiche 50-395, 84/07/23, 8408270561
- 8407290229 IE Into Notice B4-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
- 8408060134 Requests relief from ABMC Code, Section XI hydrostatic testing requirements for feedwater sys Relief needed to support baffle-plate inspired med during refueling outage currently scheduled for Sept 1984 Fee encl
  DIXON, 0 W South Carolina Electric & Gas Co 84/08/01 DENTON, b
  Office of Nuclear Reactor Regulation, Director 5pp 26067 056
  24X Fiche 50-395, 84/08/01, 8408060134
- 8408070402 Forwards changes to valve inservice insp program Non-ASME Code valves added to program as Category 8 valves Relief request to perform stroke testing of valves during cold shutdown in lieu of quarterly encl
  DIXDN,O W South Carolina Electric & Gas Co 84/08/02 DENTON,H
  Office of Nuclear Reactor Regulation, Director 4pp 25942 184
  24X Fiche 50-395,84/08/02,8408070402 DENTON: H R
- 8408010333 IE Info Notice 84-99, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fishe 50-000,84/08/06.8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement." Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/05 Consoltdated Edison Co. of New York, Inc. 123pp 26057 158 24X Fiche 50-000,84/08/06,8408010337
- 8408130194 Forwards IE Insp Rept 50-395/84-19 on 840723-27 No violations or deviations noted VERRELLI,D M Region 2, Office of Director 84/08/07 DI South Carolina Electric 2 Gas Co 2pp 26008 294 24X Fiche 50-395,84/08/07,8408130194 DIXON, O. W
- --8408130204 IE Insp Rept 50-375/B4-19 on 840723-27 No violations or deviations noted Major areas inspected security organization, security program audit & physical barriers Details withheld (ref 10CFR2 790 & 73 21) ENNIS, J D. MCOURE, D R. Region P. Defice of Director 84/08/03 1p 26008 296 24% Fiche 50-395,84/08/07,8408130194 84/08/03
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR ROBO/0120 It into MACLE 144-61. Uverexposure or Diver In PWK Refueling Cavity "Svc list encl JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc. 120pp 26129 IIB 24X Fiche 50-000.84/08/08.8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc
- 840827016B Ack receipt of 840724 ltr informing NRC of steps taken to correct violations noted in Insp Rept 30-395/84-12 VERRELLID M Division of Project & Resident Programs 84/08/10 DIXON O W South Carolina Clettric & Gas Co 1p 26237 306 24 Fiche 50-395,84/08/10,8408270168
- --8408270174 Responds to NRC 840629 ltr re violetions noted in Insp Rept 50-395/84-12 Corrective actions Area Radiation Monitors RMG-2,3 & 12 included in preventive maint program & calibr completed completed
  DIXDN:O W South Carolina Electric & Gas Co 84/07/24
  O'REILLY, J.P. Region 2. Office of Director 2pp 262
  Fiche 50-395,84/08/10,8408270168 26257 307 244
- --8408270178 Forwards Insp Rept 50-395/84-12 on 840501-31 & notice of deviation VERRELLI, D M Division of Project & Resident Programs
  DIXON, D W South Carolina Electric & Qas Co 2pp 20
  24X Fiche 50-395,84/08/10,8498270168 84/05/29 26257 309
- --8408270182 Notice of deviation from insp on 840501-31 \* Region 2, Office of Director 84/06/27 ip 26257 311 24X Fiche 50-395,84/08/10,8408270168

- --8408270187 Insp Rept 56-395/84-12 on 840501-31 Deviation noted failure to incorporate area radiation monitors in routine calibr
  - to incorporate error in program HEML.C W . CANTRELL F Region 2. Office of Director in 10pp 26257 312 24X Firme 50-395 84/08/10.8408270168
- 8408100009 IE Into Notice 84-63. 'Defective RHR Replacement Piping "
  - NOB100009 it into Muvice . .

    Svc list encl

    JORDAN E L Division of Emergency Preparedness & Engineering

    Response (Post 830103) 84/08/13 Consolidated Edison Co of New

    York, Inc 119pp 26197 218 24X Fiche 50-000.84/08/13,8408100009
- 8408100038 IE info Notice 84~64. BWR HPCI Initiation Seal-In & Indication 'Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 30-000.84/08/15.8408100038
- 8408100021 IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
  - list encl JORDAN, E.L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26198 001 24X Fiche 50-000.84/08/16.8408100021
- B40B100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/09/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,840B100055
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates ' Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 122pp 26276 122 24X Fiche 50-000.84/08/17.8408140208
- 84G8210142 IE Info Notice 84-68, "Potential Deficiency in Inproperly Rated Field Wiring to Solonoid Valves "Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc. (15pp. 26327 008 24X Fiche 50-000.84/08/21.8408210142
- S Reportable occurrences, LERs & related correspondence
- 8408090143 Special Rept SPR 84-610 on 831204, groaves found etched into topper recording plates of seismic instrument IYM 01787 by diamond stylus Caused by vibration of pressurizer surge line piping instrument relocated DIXON.O W South Carolina Electric & Gas Co 84/07/16 O'REILLY.J P. Region 2, Office of Director 2pp 25993 163 24X Fiche 50-395, 84/07/16, 8408090143
- 8408090241 NPDES noncompliance notification on 840725 total suspended solids for Discharge Points ODS & 010 exceeded 45-mg/P limit Caused by loss of power to aerator at Point 005 & clogged aerator diffuser at Point 010 Conditions corrected DIXDN, 0 W South Carolina Electric & Gas Co 84/08/01 STANLEY, A South Carolina Electric & Gas Co 84/08/01 STANLEY, A Fiche 50-395,84/08/01.8408090241
- 8408130340 Special Rept SPR 84-011 on 840703 & 11, invalid failures experienced on diesel generator XEG-0001A, unit A Caused by high jacket water temp resulting from control valve malfunction Cooling sys drained, disassembled & cleaned DIXON, 0 & South Carolina Electric & Qas Co 84/08/02 GPREILLY, J P. Region 2, Office of Director 3pp 24010 320 24X Fiche 50-395,84/08/02,8408130340
- 8408200340 LER 84-029-00 on 840713, three speed & transfer switch hinge stud assemblies on svc water pump torqued to recommended valve failed, Util contacting Brown Boveri for corrective action W/840810 ltr CLARK, N E , DIXON, O W South Carolina Electric & Gas Co 84/08/10 3pp 28139 130 24% Fiche 50-395,84/08/10,8408200340
- 8408200344 LER 84-030 00 on 840421. ESF cooling unit 1DB found w/o coil V-brace structural nember Coil V-brace installed on 840418 W840810 its
  - 840418 W/840810 1t; CLARK,N E , DIXON O W South Carolina Electric & Gas Co Spp 26139 120 24x Fiche 50-395,84/08/10,8408200344
- 8408230507 LCR 84-031-00 on 840717, seven electrical circuits identified tobalouse the 89-031-00 on B40/1/, seven electrical circuit that penetrate conteinment which are not included in Tech Spec Table 3 8-1 Surveillance satisfactory Plant mod to install overcurrent protection initiated W/840816 ltr KOON, A R . DIXON, O M South Carolina Electric & Oas Co Spp 26212 274 24% Fiche 50-395.84/08/16,8408230507 84/09/16

- 8408300514 LER 84-034-00 on 840774 discovered that Electrical Maint Procedure 300 012. 'Agastat Relay Replacement." did not requite delay time callor of relays in installed position Related event on 840821 Procedure revised W/640823 ltr KDDN, A R. DIXON, O U. South Carolina Electric & Gas Co. 84/08/21 5pp 26313 343 24% Fiche 50-395,84/08/23,8408300514 84/08/23
- V Operator Examinations
- 8408170308 Forwards instruction lesson plans for simulator training fo senior reactor operators to reactor operator transitor transitor reactor operators to reactor operators and selectric flow of the se 26113 057
- --B40B170313 "Instructor Lesson Plan Simulator Training For Senior Reactor Operators Operating Practices Training Accident Analysis/Assessment Training " \* South Carolina Electric & Gas Co 84/05/18 3App 26113 058 24X Fiche 50-395.84/08/10,840B170308
- --B408170318 "Instructor Lesson Plan Simulator Training for Reactor Operators "

  \* South Carolina Electric & Gas Co 84/07/18 240pp 26113 094
  24X Fiche 50-395,84/08/10.8408170308
- DOCKET 50-396 UNIV OF VIRGINIA CAVALIER REACTOR F Security, medical, emergency & fire protection plans
- 8408010391 Forwards revised emergency plan,incorporated addl info.per PUBLICATE INFO Should resolve plan prior deficiencies Univ request Info should resolve plan prior deficiencies Univ of Virginia reactor safety cormittee will review plan Approval expected MULDERAR U Virginia Univ of Charlottesville VA 84/07/12 THOMAS.C O Standardijation & Special Projects Branch 1p 25866 063 24X Fiche 30-062.84/07/12.8408010391
- 8408010350 Resubmits 840712 request for approval of emergency plan Ltr notarized por request Univ of Virginia reactor safety committee revieued & approved emergency plan on 840725 MULDER:R V Virginia: Univ of Charlottesville, VA 84/07/26 THOMAS.C O Standardization & Special Projects Branch ip 25866-307 24x Fische 50-062.84/07/26.8408010350
- P Operating license stage documents & correspondence
- 8408060445 Forwards notice of consideration of renewal of License R-123 for 20 yrs from issuance date, based on 840622 application THUMAS.C O Standardization & Special Projects Branch 84/07/24 MULDER R U Virginia, Univ of Charlottesville, VA 3pp 25937 095 24X Fiche 50-396,84/07/24,8408060445
- --B40B070011 Notice of consideration of application for renewal of License R-123 for 20 yrs from date of issuance THOMAS.C O Standardization & Special Projects Branch 84/07. 4pp 25937 098 24% Fiche 50-39&84/07/24.6408060445 84/07/24
- DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2 F Security, medical, emergency & fire protection plans
- 8408080119 Advises that 840515 revs to guard training & qualification plan consistent w/provisions of 10CFR30 54(p) & acceptable 8CHUSTER:M D Region 5. Office of Director 84/08/03 SCRENESK. G C Nashington Public Power Supply System 2pp 25764 361 24X Ficha 50-397, 84/08/03.840808019
- P Operating license stage documents & correspondence
- 8408090262 Forwards emergency operating procedures generation package requested at ngt meeting re 840716 insp Quidelines will be used for addityerification of response to TMI Item I C 1 redevelopment of procedures for transients & accidents SURENSEN.G C Hashington Public Power Supply System 84/07/26 BISHOP.T W. Region 5. Office of Director 1p 25994 204 24X Fiche 50-397.84/07/26.8408090262
- 8408090407 Forwards Amend 3 to License NPF-21, safety evaluation, notice of environ assessment & exemption Amend changes Tech Spec Special Test Requirement 3 10 5 to allow suspension of containment incerting during test program SCHWENCER. A Licensing Branch 2 84/07/27 SORENSEN, 0 C Washington Public Power Supply System 2pp 25984 310 24X Fiche 50-397.84/07/27,8408090407

- --8408090409 Exemption from requirements of iOCFR50 44, allowing continued operation w/noninerted containment during balance of initial startup test program
  EISENHUT, D G Division of Licensing 84/07/26 Washington Public Power Supply System 5pp 25984 312 24x
  Fiche 50-397, 84/07/27, 8408090407
- --B408090410 Amend 3 to license NPF-21 changing Tech Spec Special Test Requirement 3 to 5 to allow suspension of containment inerting during power ascension test program SCHMENCER, A Licensing Branch 2 B4/07/27 4pp 25984 317 24X Fiche 50-397.84/07/27.8408090407
- --8408090412 Safety evaluation supporting Amend 3 to License NPF-21 \* Office of Nuclear Reactor Regulation. Director 84/07/26 5pp 25984 321 24% Fiche 50-397.84/07/27.8408090407
- --8408090414 Notice of environ assessment & finding of no significant impact re Amend 3 to License NPF-21 EISENUIT.0 & Division of Licensing 84/07/19 5pp 25984 326 24X Fiche 50-397.84/07/27.8408090407
- B40B070325 Forwards fee for review of util B40717 application re anhancement of control room flour SORENBEN.G C Washington Public Power Supply System B4/0B/0: BCHWENGER.A Licensing Branch 2 1p 25945 237 24X Fiche 50-397.84/08/01.8408070325
- B408070333 Requests confirmation of CRGR review re specific uncertainties conservatively treated in OE instrument setpoint methodology for DWRs Concern should be treated as generic SORENSEN,O C Washington Public Power Supply System 84/08/02 SCHWENCER,A Licensing Dranch 2 3pp 25945 189 24X Fiche 50-397,84/08/02.8408070333
- B40B070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933. "Prioritization of Generic Safety Issues " Svc list encl EISEN-NUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26127 238 24x Fiche 50-000.84/08/06.8408070110
- 840B2B0339 Forwards request for addl info re safety parameter display sys Response requested within 60 days of ltr receipt BCHWENCER. A Licensing Branch 2 84/08/10 SDRENSEN. G C Washington Public Power Supply System 5pp 26294 043 24X Fiche 50-397.84/08/10.8408280339
- B40B270498 Forwards Amend 4 to License NPF-21 & safety evaluation Amend modifies Tech Specs as listed SCHWENCER, A Licensing Branch 2 84/08/14 SORENSEN, G C Washington Public Pouer Supply System 3pp 26277 042 24X Fiche 50-397, 84/08/14, 8408270498
- --8408270506 Safety evaluation supporting Amend 4 to License NPF-21 \* Office of Nuclear Reactor Regulation, Director 84/08/14 4pp 26277 057 24% Fiche 50-397.84/08/14.8408270498
- 840B270073 Application to amend License NPF-21, revising Condition 2 C(11) re shield uall deferral Change would allow ongoing ALARA revisus to identify need for add1 shielding SDRENSEN.6 C Hashington Public Power Supply System B4/08/15, SCHWENCER, A Licensing Branch 2 Spp 26247 183 24X Fiche. 50-397, B4/08/15, B408270073
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for GLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list enc!
  EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of Neu York, Inc 17pp 26276 244 24X
  Fichs 50-000,84/08/20,8408200275
- B40B270153 Concurs w/clarification re piping failures outside primary containment, allowing credit for offsite power to mitigate consequences of pipe failure causing scram or turbine trip Offsite power assumed tost when undervoltage occurs SCRENSEN.6 C Washington Public Power Supply System 84/08/20 SCHMENCER.A Licensing Branch 2 ip 26245 153. 24X Fiche 50-397, 84/08/20, 8408270153

- O Inspection reports: IE Bulletins & correspondence
- 8408070016 Forwards IE Insp Rept 50-397/84-15 on 840529-0608 No violations noted Deaknesses or opportunities for improvements observed Assessment of observations requested within 30 days
  BISHOP.T W Region 5. Office of Director 84/07/24 SORENSEN.G C Washington Public Power Supply System 2pp 25993 001 24X
  Fiche 50-397.84/07/24.8408090016
- --B408090019 IE Insp Rept 50-397/84-15 on 840529-0408 No violations noted Major areas inspected operating crews, awareness of plant/sys status & adherence to procedures & administrative controls Identified weaknesses listed WILLETT.D J. JOHNSON.A D., WAITC.R Region 5. Office of Director B4/07/24 8pp 25995 003 24% Fiche 50-397/84/07/24,8408090016
- 8408070247 Responds to NRC 840629 ltr re violations noted in IE Insp Rept 50-397/84-13 Corrective actions specific instructions provided to operating crews to ensure airlock operation performed per regulatory requirements SOREMSEN.G C Washington Public Power Supply System 84/07/26 BISHD\*1 W Region 5. Office of Director 4pp 25949 020 24X Fiche 50-397.84/07/26.8408070247
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc. 119pp 25865-047 24X Fiche 50-000,84/07/27,8407250229
- B40B010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN, E. L. Division of Emergency Proparedness & Engineering Response (Post B30103) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333
- B40B010337 IE Info Notice B4-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- --8408300451 Notice of violation from insp on 840606-0706 DDDBS R T Region 5, Office of Director 84/08/07 2pp 84314 100 24X Fiche 50-397,84/08/07,8408300446
- --8408300464 Insp Rept 50-397/84-18 on 840606-0706 Nancompliance noted shift manager not notified prior to installation & removal of jumpers & prompt corrective action not taken re malfunctions & deficiencies in ECCS logic TOTH.A D . MATTER S . DODDS.R T Region 5. Office of Director 84/07/27 25pp 26314 102 24X Fithe 50-397.84/08/07.8408300446
- B408070120 IE Info Notice 94-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN, E L Divisson of Emergency Preparedness & Engineering Response (Post 830103) B4/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- B40B070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list encl GRACE, J N Division of QA, Safeguards & Inspection Programs (Post B30103) B4/0B/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/0B/10.8408070376
- 8408100009 IE Info Notice 84-43, "Defective RHR Replacement Piping Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication "Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000.84/08/15,8408100038
- 8408100021 IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" 8vc list encl SONDAN, E. Division of Emergency Preparedness & Engineering
  - list enci JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26198 001 24% Fiche 50-000,84/08/16,8408100021

- 8408100055 IE Info Notice 84-66, 'Undetected Unavailability of Turbino-Driven Auxiliary FeedLater Train " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830107) 84/09/17 Consolidated Edison Co. of New York, Inc. 120pp 262/6 OOt. 24X Fiche 50-000.84/08/17.8408100055
- B40B14020B IE Info Notice 84-67, "Recent Shubber Inservice Testing W/ High Failure Rates" Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B470B/17 Consolidated Edison Co. of New York, Inc. 122pp 26276 122 24% Fiche 50-000.84708/17.8408140208
- 8408210142 IE Info Notice 84-68, 'Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list enc! JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consulidated Edison Co. of New York, Inc. 115pp 26329 008 24X Fiche 50-000.84/08/21,8408210142
- 8408290168 Ack receipt of 840726 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-397/84-13 Reply disagrees w/citation re undocumented approval of clearance order based on rigt purposes & intentions BISHOP. TW Region 5. Office of Director 84/08/24 SORENSEN. 9 C Hashington Public Power Supply System 1p 26291 302 24X Fiche 50-397.84/08/24.8408290168
- A Periodic operating reports & related correspondence
- B406070192 Monthly operating rept for Apr 1984 W/840515 ltr COWAN,K D . MARTIN,J D Washington Public Fower Bupply System 84/04/30 4pp 24747 050 24X Fiche 50-397,84/04/30,8406070192
- B40B2B0320 "Semiannual Effluent Rept. Jan-June 1984 " W/840B16 ltr MARTIN. J D Washington Public Power Supply System 84/06/30 MARTIN. J B Region 5. Office of Director Sopp 26282 279. 24X Ficho 50-397, 84/06/30, 84082B0320
- S Reportable occurrences, LERs & related correspondence
- B40B220317 Part 21 rept re failure of ITE-27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diode must be added Affected units listed DUVALL,D D Brown Bover; Corp (subs of Brown Bover; & Co , Ltd } 84/03/13 DE\UNDO,R C Olirector's Office, Office of Inspection and Enforcement 3pp 26191 357 24X Fiche 50-000,84/03/13,8408220317
- 8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot selemeid valve plunger Initially reported on 840413 New thread locking devices investigated SHERWOOD, G G Ceneral Electric Co 84/04/13 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement Jpp 26222 236 24X Fiche 50-000.84/04/13.8408240348
- B40B030280 LER 84-034-01 on B40703, drywell temp monitor CMS-TI-55 indicated temps above 150 F in upper drywell area return duct for over 8 h initially identified in 840511 LER No corrective action initiated W/840728 ltr PDWERS. CM . MARTIN. J D Washington Public Power Supply Bystem 84/07/26 3pp 25917 259 24% Fiche 50-397.84/07/26.8408030280
- B408040233 LER 84-072-00 on 840705-04, reactor water cleanup sys (RWCU) isolations occurred Caused by erroneous RWCU high delta flow trips Reactor vessel transmitter replaced & blowdown flow transmitter sensing lines refilled & vented W/840726 ltr POWERS.C M . MARTIN.J D Washington Public Power Bupply Bystem 84/07/24 3pp 25935 135 24X Fiche 50-397,84/07/26.8408060233
- 8408060235 LER 84-061-01 on 840614. spen floor drain found on 522-ft elevation of reactor bidg Flant walkdown revealed two other drains fire watches instituted Drains will be piped into floor drain sys & not sealed as first planned W/840726 ltr POMERS, C M . MARTIN. J D . Washington Public Power Supply System 84/07/26 3pp 25939 144 24% Fiche 50-397.84/07/26.8408060235
- 8408060301 LER 84-071-00 on 840716, loss of power to partion of failsafe relaying resulted in 1/2 80P containment isolation Caused by inadvertent shorting of reactor protection system circuit Containment isolation reset W/840726 ltr POWERS, C M , MARTIN, J D Washington Public Power Supply System 84/07/26 3pp, 25936 041 24X Fiche 50-397, 84/07/26,8408040301
- 8408070135 PNS-V-84-012 on 840727, routine safety patrol discovered suspictous-looking device near control room Device determined not explosive Technician identified device as slectrical test equipment SCHHAN. C A . SCHWSTER. M D Region 5. Office of Director 84/07/3 ip 25949 342 24X Fiche 50-397,84/07/30,8408070135

- 840B070443 LER B4-075-00 on B40709 & 13, standby diesel generator 1B incurred high vibration alarm Caused by slip ring end bearing turning on shaft insulation Bearing insulation modified W/B40802 ltr KOENIGS.R L. MARTIN.J D. Washington Public Power Supply System 84/08/02 4pp 25793 232 24% Fiche 50-097,84/08/02,8408070443
- 8408090450 LER 84-074-00 on 840712 results of sample from radwasts tan EDR-TK-4B inadvertently recorded on FDR-TK-9 data sheet & FDR-TK-9 released Caused by contractor error Discharge stapped Procedure for tank release mudified W/840802 ltr KOENIOS R L . MARTIN J D Washington Public Puwer Supply Bystom 84/08/02 3pp 25993 221 24X Fiche 50-397,84/08/02,8408090450
- 8408090458 LER 84-073-00 on 840308 spurious bi chlorine alarm from MDA-SR-15 caused control room emergency filtration sys to auto start Caused by component failure in electronics module on chlorine analyzer Alarm reset W/840802 ltr KOENIOS.R t. MARTIN.J D. Washington Public Power Supply System 84/08/02 3pp 25973 214 24X Fiche 50-397,84/08/02.8408090458
- 8408200132 LER 84-076-00 on 840728, during declaration of unusual event subsequent to finding possible bomb hourly fire watch tour not performed Tours resumed immediately upon termination of unusual event status Only one tour missed M/840808 ltr KCEN105,R L. MARTIN.J D Washington Public Power Supply System 84/08/08 3pp 26139 117 244 Fiche 50-397,84/08/08,8408200132
- 8408200341 LER 84-077-00 on 840720 & 21, control room emergency filtration unit automatically actuated. Caused by spikes on corresponding control room outside air radiation monitor Emergency filtration unit reset W/440808 ltr KOENIGE, R L , MARTIN. D Washington Public Power Supply System 84/08/08 3pp 26139 123 24% Fiche 50-397,84/08/08,8408200341
- 8408170369 PNO-V-84-049 on 840812 unusual event declared when prairie brush fire led to potential for loss of offsite 230-kV startup powerlines & 115-kV backup power lines Plant diesel generators started as contingency 10TH.A D . DODDS,R T Region 5. Office of Director 84/08/13 ip 26112 358 24X Fiche 50-397,84/08/13,8408170369
- 8408290036 PNO-V-84-053 on 840822; thermal transient occurred in reactor feedwater sys downstream of high pressure feedwater heaters 6A & 6B Transient caused pipe hanger & support damage resulting in leakage of approx 20 gallons water DDDDS.R T . TOTH.A D Region 5. Office of Director 84/08/23 ip 26291 213 24X Fiche 50-397.84/08/23.8408290036
- 8408290017 LER 84-034-02 on 840804.drywell temp monitor CMS-TI-55 indicated temps above 150 F in uppor drywell area return duct Cause not stated Hods to design of drywell heating & vertication being completed M/840824 ltr
  KDENIGS.R L . MARTIN.J D Washington Public Power Supply System 84/08/24 3pp 26291 270 24X Fiche 50-397.84/08/24.8408290017
- 8408290024 LER 84-080-00 on 840801 turbine stop valve closure reactor trip occurred as result of pressurizing turbine first-stage shell above 307 power Plant recovered per Operating Procedure PPM 3 3 1 W/840824 ltr MOEN109,R L. MARTIN.J D. Washington Public Power Supply System 84/08/24 3pp 26291 267 24X Fichs 50-397,84/08/24,8408290024
- 8408290030 LER 84-079-00 on B40809, reactor scram occurred automatically on low reactor water level after reactor feed water pump tripped due to loss of control power Reactor water level restored using RCIC sys W/840824 ltr KQENIGS R L , MARTIN, J D Washington Public Power Bupply System 84/08/24 3pp 26291 214 24X Fiche 50-397, 84/08/24, 8408290030
- 8408290116 LER 84-078-00, on 840801.07 & OB, control room emergency filtration units automatically actuated Coused by spikes on corresponding control room autoide air radiation monitors Filtration units & radiation monitors reset W/840824 ltr. MCEN105,R L . MARTIN.J D Washington Public Power Supply System 84/08/24 3pp 26271 286 24X Fichs 50-377.84/08/24,8408290116
- 8408290143 LER 84-072-01 on 840705 & 06, reactor water cleanup sys (RMCU) isolations occurred Caused by erromeous reactor water cleanup sys high delta flow trips Isolation signals reset & RMCU returned to svc W/840824 ltr POWERS, C M , MARTIN, J D Washington Public Power Supply System 84/08/24 4pp 26291 209 24X Fiche 50-397,84/08/24,8408290143
- U Congressional/Executive Correspondence
- 8408200926 Discusses Tech Spec errors discovered subsequent to NRC approval Susquehanna Tech Spec amends had no safety significance McOuire Tech Specs still under review w/no identified safety significance thus far ASSELSTINE. J K Commissioners 84/08/10 MARKEY, E J House of Reg , Interior & Insular Affairs 4pp 26141 244 24X Fiche 50-000.84/08/10,8408200225

- DOCPET 90-400 SHEARON HARRIS NUCLEAR POWER PLANT. UNIT 1

  A Application/construction stage documents & correspondence
- 8408020012 Forwards info in response to Eddleman Contention 9 re environ qualification program FSAR will be emended to provide description of program MATSON.R A. Carolina Power & Light Co. 84/07/25 DENTON.H R Office of Nuclear Reactor Regulation. Director 15pp 25883 100 24X Fiche 30-400.84/07/25,840802012
- 840B040192 Forwards "Class IE Equipment Environ Qualification Master List:" containing safety-related equipment in locations w/total integrated dose greater than stated rads ZIMMERMAN.S R Carolina Power & Light Co 84/07/27 DENTON, H R Office of Nuclear Reactor Regulation. Director ip 25930 268 24X Fishe 30-400.84/07/27.840B060192
- --8408060196 "Class IE Equipment Environ Qualification Master List" \* Carolina Power & Light Co 84/07/27 588pp 25930 269 24) Fiche 50-400, 84/07/27, 8408050192
- 8408080271 Submits restatement of cold license training program to meet NRC guidance for combined observation/simulator training in response to Generic Ltr 84-10 Request for exemption from IOCRR93 23(b) uill be submitted ZIMHERMAN.S R Carolina Power & Light Co 84/07/27 DENTON,H R Office of Nuclear Rescular Regulation, Director 2pp 25966 289 24X Fiche 30-400,84/07/27,8408080271
- 8408060257 Forwards marked-up Tech Specs.based on Rev 4 to NUREQ-0452, "STS for Hestinghouse Pressurized Reactors " Offsite dose calculation manual will be submitted by 840831 Future submittels will address listed subjs CUTTER:A B Caroline Power & Light Co 84/07/30 DENTON,H R Office of Nuclear Reactor Regulation, Director 636pp 25924 001 24X Fiche 50-400.84/07/30,8408060257
- 8408090497 Summary of 840717 meeting w/Westinghnuse Owners Steam Gamerator Tube Rupture Subgroup in Bethesda: MD re proposed steam generator tube rupture generic program List of attendees & vieugraphs encl
  SINOH, B K Licensing Branch 3 84/07/31 Licensing Branch 3 18pp 25983 130 24% Fiche 50-000.84/07/31, 8408090497
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for GLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues" Bvc list encl EISENHUT, D & Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24x Fiche 50-000,84/08/06,8408070110
- B408230364 Notification of 840817 meeting w/util in Bethesda,MD to discuss functional capability of Class I auxiliary piping sys BUCKLEY,B Licensing Branch 3 84/08/06 KNIGHTON,Q W Licensin Branch 3 4pp 26230 354 24X Fiche 50-400,84/08/06,8408230364
- 8408200273 Generic Ltr 84-20 to all licenses of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT, D & Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000.84/08/20.8408200275
- 8408280207 Clarifies 840723 response to Eddluman Contention 9 re environ qualification program Response to 9B refs verification performed by unsite GA organization Commitment to ensure required equipment installed not diminished ZIMMERMAN. S R Carolina Power & Light Co 84/08/24 DENTON. H R Office of Nuclear Reactor Regulation. Director ip 26279 191 24X Fiche 50-400.84/08/24.8408280207
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 840B0703B1 Forwards Amend 16 to FSAR describing environ qualification program & providing add1 info re BER Open Item 5 MCDUFFIE, M A Carolina Power & Light Co 84/07/27 DENTON, H R. Office of Nuclear Reactor Regulation, Director ip 25747.085 24) Fiche 50~400,84/07/27,84080703B1
- --8408070384 Amend 16 to FSAR

  \* Carolina Power & Light Co 84/07/27 7ipp 25947 086 24X
  Fiche 30-400, 84/07/27, 8408070381

- 8408080285 Forwards replacement pages for emergency planning public info brochure, in response to SER Open Item 12 Pages correct minor editorial errors
  ZIMMERMAN, S.R. Carolina Power \* Light Co. 84/07/27 DENTON, H.R. Diffice of Nuclear Reactor Regulation, Director. 4pp. 25965-325-24X Fiche 50-400,84/07/27 8408080285
- 8408080337 Forwards add1 info to turbine hldg vent radiation munitors, in response to SER Confirmatory Item 26.1dentified by Meteorological & Effluent Treatment Sys Branch ZIMMERMAN, S.R. Carolina Power & Light Co. 84/07/27 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 3pp 25964 078 24X Fiche 50-400,84/07/27,8408080337
- F Security, medical, emergency & fire protection plans
- 8408080285 Forwards replacement pages for emergency planning public info brochure; in response to SER Open Item 12 Pages correct minor editorial eriors ZIMMERMAN, S.R. Carolina Power & Light Co. 84/07/27 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 4pp. 25765-325-24X Fiche 50-400,84/07/27,8408080285
- B40B090473 Notification of 840B14 meeting w/util in Bethesda.MD to discuss resolution of emergency preparedness issues BUCKLFY.B Licensing Branch 3 B4/07/27 KNIOHTUN.G W Licensing Branch 3 4pp 25983 174 24% Fiche 50-400.84/07/27,840B090473
- 8408280026 Forwards Insp Rept 50-400/84-20 on 840709-12 No violations or deviations identified VERRELLI.D M Region 2. Office of Director 84/07/27 UTLEY.E E Carolina Power & Light Co 2pp 26281 344 24X Fiche 50-400.84/07/27.8408280026
- ---8408280028 Insp Rept 50-400/84-20 on 840707-12 No violations or deviations noted Major areas inspected fire protection WISEMAN, G R , CONLON, T E Region 2, Office of Director 84/07/24 4pp 26281 346 24X Fiche 50-400, 84/07/27, 8408280026
- B40B150137 Forwards NRC comments on design evaluation rept program plan elements for detailed control room design review, including info re control room inventory & selection of design improvements Response by B50101 requested KNICHTON, G W Litensing Branch 3 B4/0B/01 UTLEY, E Carolina Power & Light Co 11pp 26104 203 24X Fiche 50-400, 84/0B/01, B4/0B150137
- --8404230171 Audit rept, "Human Factors Engineering Detailed Control Room Design Review In-Progress Audit " ELAYATH Laurence Livermore National Laboratory 84/03/28 33pp 26104 214 24X Fiche 50-400,84/08/01.8408150137
- 840B300297 Confirms 840B02 telcon between DB Waters & PR Bemis re 840B09 mgt meeting in Atlanta, GA to discuss emergency plans, action levels & emergency operating procedures LEWIS.R C Region 2, Office of Director 84/08/07 UTLEY, E E Carolina Power & Light Co 1p 26306 353 24X Piche 80-400.84/08/07.840B300297
- 8408240316 Forwards SALP Repts 50-261/84-24,50-324/84-16,50-325/84-16 & 50-400/84-18 for Feb 1983 Apr 1984 LEHIS,R C Region 2, Office of Director 84/08/21 UTLEY,E E Carolina Power & Light Co 2pp 26225 230 24% Fiche 50-000,84/08/21,8408240316
- --8408240319 SALP Repts 50-261/84-24,50-324/84-16,50-325/84-16 & 50-400/84-18 for Feb 1983 Apr 1984 \* Region 2, Office of Director 84/04/30 71pp 26225 232 24% Fichs 50-000,84/08/21,8408240316
- O Adjudicatory correspondence
- 840B160128 Forwards NRC staff Exhibits 1-3 & intervenor Exhibit 1 Related correspondence RILEY,6 L Taylor Associates 84/06/25 PLEAGANT,C Administrative & Logistical Support Branch 1p 26126 167 24X Fiche 50-400,84/06/23,840B160128
- 840B010264 Joint Intervenors findings of fact on Joint Contentions II(a) re concentration of radionuclides through interaction W/fine particles & II(c) re calculations of radiological doses from normal releases Certificate of Svc encl RUNKLE, J Joint Intervenors Shearon Harris DSB 655 B4/07/24 13pp 25854 036 24X Fiche 30-400.84/07/24.8408010264

- 8408030070 Response opposing applicant motion for econsideration or clarification of Joint Contention IV Certificate of Svc encl
  EDDLEMAN.W Eddleman, H EDDLEMAN.W Joint Intervenors Shearon Harris DSB 727 84/07/30 BRIGHT.G Q . CARPENTER, J H ,
  KELLEY, J L Acomic Safety and Licensing Board Panel App
  25904 275 24X Fiche 50~400.84/07/30,8408030070
- 840B020054 Provides requested info ro schedule for testing & insps of two TDI diesel generators for standby emergency power Operational testing scheduled for Last Quarter 1984 & early 1985 Svc list encl Related correspondence O'NEILL.JH Shaw, Pitsman, Potts & Troubridge O'NEILL.JH Carolina Power & Light Co DSB 700 84/07/31 KELLY,JL BRIGHT: G O. CARPENTER,JH Atomic Safety and Licensing Board Panel 5pp 25891 330 24% Fiche 50-400.84/07/31.8408020054
- 8408070397 Response in support of applicant 840718 motion for reconsideration or clarification of ASLB 840413 memorandum & order on Joint Contention IV Certificate of Svc encl MDORC. J E Hearing Branch 1 DSB 811 84/07/31 Atomic Safety and Licensing Board Panel 9pp 25942 237 24X Fiche 50-400.84/07/31.8408070397
- 8408070459 Informs of agreement to negotiate w/applicant counsel D Hollar re adequacy of various responses in applicant 840725 discovery responses on emergency planning, including document identification Related correspondence EDDLEMAN. W Eddleman. U DSB 762 84/08/01 KELLEY, J Atomic Safety and Licensing Board Panel 1p 25940 295 24X Fiche 50-400.84/08/01.8408070459
- 8408090224 Informs that NRC consultant T Urbanik will not be available until 840813 to respond to interrogatories re Contentions 213 & 224 Related correspondence BARTHA.C A Hearing Branch I DSB 865 84/08/01 EDDLEMAN.W Eddleman. W ip 25971 243 24X Fiche 50-400.84/08/01.84080902224
- 8408070293 Order providing final set of rulings on admissibility of offsite emergency planning contentions, ruling on petition for waiver of need for power rule & notice of epcoming telcon call Beryed on 840806
  BRIGHT, G O , CARPENTER, J H , KELLEY, J L Atomic Safety and Licensing Board Panel DSB 771 84/08/03 62pp 25948 011 24X Fiche 50-400,84/08/03.8408070293
- 8408090170 Further response to 840327 interrogatories re Joint Intervenor Contention 1 concerning mgt qualifications Affidavits of FS Cantrell & PR Bemis & Certificate of Bvc encl Related correspondence
  BARTH.C A Hearing Branch 1 DSB 866 84/08/03 Atomic Safety and Licensing Beard Panel 43pp 25973 129 24X
  Fiche 30-400,84/08/03,8408090170
- 8408070455 Response to applicant motion to establish procedure for requesting extensions of time Certificate of Svc and RUNKLE, J Conservation Council of North Carolina DSB 884 84/08/05 Atomic Safety and Licensing Board Panel Spp 25982-224 24X Fiche 50-400,84/08/05,8408070455
- 8408080217 Proposed findings of fact in reply to proposed findings of fact & conclusions of law submitted by W Eddleman on Contention 8F(1) & by Joint Intervenors on joint Contentions II(E) & (C) Certificate of Svc encl

  8AUSER, D B Carolina Power & Light Co BAUSER, D B Shaw, Pittman, Potts & Troubridge DBB 821 84/08/06 10pp 25967 053 24X

  Fiche 50-400,84/08/06,8408080217
- 8408070172 Reply Findings re Eddleman Contention BF(1) & Joint Contention II(e) & II(c) Eddleman proposed Findings 11 & 14 & portions of Joint Intervenor Findings 8,7,22 & 27 should not be adopted Certificate of Syr encl MODRE. J E Hearing Branch 1 DSB 864 84/08/06 Atomic Safety and Licensing Board Panel 7gp 25773 010 24X Fiche 50-400,84/08/06,8408070172
- 8408130288 Supplemental answer to Eddleman Interrogatory
  57-C-10~3(a)-(d) requesting identification of all documents,
  methodologies, data, equations, calculations & info
  Certificate of Svc encl Related correspondence
  HOLLAR, D E Carolina Power & Light Co BSB 904 84/08/08
  Eddleman, W 6pp 26008 356. 24X Fiche 50~400,84/08/08,8408130288
- 8408140002 Proposed Eddleman exhibits on Contention 114 re fire protection Certificate of Syc encl EDDLEMAN.W Eddleman, W DBD 943 84/08/09 33pp 26052 304 24X Fiche 50-400,84/08/09,8408140002
- 8408140004 First set of emergency planning interrogatories & request for production of documents Certificate of Svc encl.Related correspondence RIDOMAY, D.A. Carolina Power L. Light Co. RIDOMAY, D.A. Shaw, Pittman, Potts Troubridge. DBB 945 84/08/09 Wilson, R lipp 24050 322 24X Fiche 50-400,84/08/09,8408140004

- 8408140008 First set of emergency planning interrogatories & request for production of documents Certificate of Svc entl Related correspondence RIDGWAY.D A Carolina Power & Light Co RIDGWAY.D A Shaw, Pittman. Potts x Troubridge DSB 747 84/08/09 Conservation Council of North Carolina 14pp 26044 064 24x Fiche 50-400.84/08/09.8408140008
- B40B140022 First set of emergency planning interrogatories & request for production of documents Certificate of Svc encl Related correspodence RIDGMAY.D A Carolina Power & Light Co RIDGMAY.D A Shaw, Pittman, Potts & Troubridge DS3 949 B4/0B/09 Chapel Hill Anti-Nuclear Oroup Effort 21pp 26044 168 24X Fiche 50-400,84/0B/09.849B140022
- B408140049 First set of emergency planning interrogatories & request for production of documents Certificate of Svc encl Related correspondence RIDGWAY, D.A. Carolina Power & Light Co. RIDGWAY, D.A. Shaw, Pittman, Potts & Troubridge DSB 946 84/08/09 Joint Intervenors Shearon Harris 16pp 26044 209 24X Fishs 50-400,84/08/09,8408140048
- 8408140057 First set of embrgency planning interpogatories & request for production of documents Certificate of Svc encl Related correspondence RIBGWAY.D A Carolina Power & Light Co RIDGWAY.D A Shaw, Pittman, Potts & Trowbridge DSD 948 84/08/09 Eddleman, W 27pp 26060 216 24% Fiche 50-400.84/08/09,8408140057
- B40B140119 Notice of documents relied upon & previously served as testimony in chief & case in chief of joint Contention I remgt & Contention 65 Related correspondence EDDLEMAN. W Eddleman, W D5B 942 B4/08/09 Atomic Safety and Licensing Board Panel 2pp 26051 259 24X Fiche 50-400.84/08/09. B40B140119
- --8408140122 Fifth set of interrogatories.Related correspondence EDDLEMAN, W. Eddleman, W. 84/08/09 Diffice of the Executive Lagal Director 12pp 26051 260 24X Fiche 50-400.84/08/09. 8408140119
- ~-8408140125 Tenth set of general interragotories Related correspondence EDDLEMAN.W Eddleman, W 84/08/09 Carolina Power & Light Co 119pp 26051 272 24X Fiche 50~400,84/08/09,8408140119
- 8408160105 Eddleman contentions on emergency plan bruchure. "Bafety Info for Shearon Harris Nuclear Power Plant " Certificate of Svc enct EDDLEMAN-W Eddleman, U DSS 077 84/08/10 Atomic Safety and Licensing Board Panel 750pp 26086 001. 24X Fiche 50-400, B4/08/10.8408160105
- 8408280186 Affidavit of BJ Furr stating that answers to Interrogatory 57-C-10-3(a) (d) correct & true to best of info & knowledge Notice of appearance of EM Roach & Certificate of Bvc encl FURR.B J Carolina Power & Light Co DSB J21 84/08/13 4pp 26279 199 24X Fiche 50-400.84/08/13.8408280186
- B40B200470 Forwards FEMA responses to 840627 interrugatories Certificate of Syc encl Related correspondence MODRE, J. E. Hearing Branch I. DBB 174 84/08/14 EDDLEMAN, W. Eddleman, W. 3pp. 26136-321 24x Fiche 50-400,84/08/14,840B290490
- --8408200497 Response to interrogatories propounded by intervenor H Eddleman Related correspondence HAHKINS T I , ROCHLIS, S M Federal Emergency Management Agency, 84/08/07 EDDLEMAN, W Eddleman, W 31pp 26/36-324 24X Fiche 50-400,84/08/14,8408200490
- B40B200498 Forwards subposes forms for listed witnesses not called by util & NRC re Contentions 41 & 45 Subposes should be issued under provisions of 10CFR2 790 W/o forms Certificate of Byc entl Related correspondence EDDLEMAN.W Eddleman. W DSB 145 84/08/17 3pp 26136 355 24X Fiche 50-400.84/08/17:8408200498
- 8408210323 Request for subposens for listed withesses on joint Contention I re mgt capability Certificate of Byt encl Related correspondence. RUNCKLE, J Joint Intervenors — Shearon Harris DSB 181, 84/08/17 Atomic Safety and Licensing Board Panel 4pp 26179 132 24X Fiche 50-400,84/08/17.8408210323
- B40B270122 Forwards SER re TDI Diesel Generator Gwners Group program plan Rept discussed during 840B10 conference call Related correspondence MODREJ E Hearing Branch 1 DSB 30B 84/08/21 KELLEY, J L , CARPENTER, J H , BRIGHT, G O Atomic Safety and Licensing Board Panel 50pp 2624B 002 24X Fiche 50-400,84/08/21,840B270122

- B408230160 Notice of evidentially hearing on Joint Contention 1.

  commencing on 840905 in Raleigh.NC Served on 840822

  KELLEY. J L Atomic Safety and Licensing Board Panel DSB 210

  840822 Office of the Executive Legal Director 1p 26209 298

  24X Fiche 50-400.84/08/22.8408230160
- 8408280439 Forwards SALP rept for 800701-811231 & NRC Manual Chapter NRC-0516 Page 9 of Cleuitt prefiled testimony refers to SALP rept Figures on Page 9 of Cleuitt attachment came from Page 2 of rept Related correspondence BARTH.C A Hearing Branch 1 DSS 342 84/08/22 PAYNE.T Affiliation Not Assigned 1p 26280 275 24% Fiche 50-400, 84/08/22,8408280439
- J Insurance & indemnity information
- 8408210027 Forwards Endorsements 1-5 to NELIA Policy NF-288 BARHAM, C D Carolina Power & Light Co 84/08/15 SALTZMAN, J Assistant Director for State & Licensee Relations 13pp 26:181 351 24X Fiche 50-400, 04/08/15, 8408210027
- K Utility Final Safety Amalysis Report (FSAR) & amends
- 8408070381 Forwards Amend 16 to FSAR describing environ qualification program & providing add1 info re SER Open Item 5 MCDUFFIE.M A Carolina Power & Light Co 84/07/27 DENTON.H R Dffice of Nuclear Reactor Regulation. Director 1p 25947 085 24X Fiche 30-400.84/07/27.8408070381
- --8408070384 Amend 16 to FSAR

  \* Carolina Power & Light Co 84/07/27 71pp 25747 086 24X
  Fiche 50-400,84/07/27,8408070381
- 8408090509 Forwards affidavit certifying distribution of Amend 16 to FSAR on 840727 THYERMAN.S R Carolina Power & Light Co 84/08/02 EISENHUT, D G Division of Licensing App 25993 012 24X Fiche 50-400.84/08/02.8408090509
- G Inspection reports. IE Builetins & correspondence
- B40B300347 Act receipt of B31110 supplemental ltr informing NRC of steps taken to correct violations noted in lnsp Rept 50-400/03-29 LEMIS.R C Division of Project & Resident Programs 84/06/08 UTLEY.E E Carolina Power & Light Co 1p 26308 350 24X Fiche 50-400.84/06/08.840B300347
- -8409300350 Provides add1 response to NRC 831110 ltr re violations noted in Insp Rept 50-400/83-29 Corrective actions procedure for control of non-ASME bolting matls will be implemented by mid-June
  PARSONS,R M Carolina Power & Light Co 84/06/01 D'REILLY, J P
  Region 2, Office of Director 2pp 26308 351 24X
  Fiche 50-400,84/06/08,8408300347
- B40B280088 Forwards Insp Rept 50-400/84-19 on 640710-13 No violations or deviations identified VERRELLI,D M Region 2, Office of Director 84/07/24 UTLEY,E E Carolina Power & Light Co 2pp 26282 028 24X Fiche 50-400,84/07/24
- --9409280091 Insp Rept 50-400/84-19 on 840710-13 No violations or deviations noted Major areas inspected action on previous enforcement natters; const progress; RCPD piping; visual exam, safety-related components & IE bulletins KLEINSORGE, W P. BLAKE, J J. Region 2. Office of Director 84/07/20 10pp 26282 030 24% Fiche 50-400; 84/07/24, 8408280088
- 8407250229 IE Info Notice 84-57. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25845 047 24X Fiche 50-000.84/07/27,8407250229
- 8408280026 Forwards Insp Rept 50-400/84-20 on 840709-12 No violations or deviations identified VERRELLI,D M Region 2. Office of Director 84/07/27 UTLEY,E E Carolina Power & Light Co 2pp 26281 344 24X Fiche 50-400.84/07/27.8408280026
- --8408280028 Insp Rept 50-400/84-20 on 840709-12 No violations or deviations noted Major areas inspected fine protection WISEMAN, G.R., CONLON.T.E. Region 2, Office of Director. 84/07/24, 4pp 26281 346 24X Fichs 50-400,84/07/27,8408280028

- B408010333 IE Info Notice 84-59. Deliberate Circumventing of Station Health Physics Fincedures " Svt list encl JORDAN,C L. Division of Emergency Preparedness & Engineering Response (Post B30103) 81/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26068 001 24X Fiche 50-000,84/08/06.8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24% Fiche 50-000,84/08/08,8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl GRACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10.8408070376
- 8408280456 Act receipt of 840726 supplemental response informing NRC of steps taken to correct violations noted in Insp Repts 50-400/83-25.50-400/83-26 & 50-400/83-29 LEWIS,R C Region 2. Office of Director 84/08/10 UTLEY,E E Carolina Power & Light Co ip 26282 141 24X Fiche 50-400.84/08/10.8408280436
- --8408280460 Responds to NRC B31019 ltr re violations noted in Insp Rept 50-400/83-25 Corrective actions evaluation performed to identify fasteners in noter control ctrs under scope of Reg Ovide i 29 PARSONS,R M Carolina Power & Light Co 84/07/26 D'REILLY,J P Region 2. Office of Director 3pp 26282 142 24X Fiche 50-400,84/08/10.8408280436
- --8408280465 Responds to NRC 830922 ltr re violations noted in Insp Rept 50-400/83-26 Corrective actions implementation of FCR-P-1366 rerouted pipe & resolved interference problem PARSONS,R M Carolina Power & Light Co 84/07/26 O'REILLY,J P Region 2. Office of Director 3pp 26282 145 24X Fiche 50-400,84/08/10,8408280456
- --8408280467 Updates 840601 response to NRC 830922 ltr re violations noted in Insp Rept 50-400/83-27 Corrective actions site administrative procedure governing identification of bolting matl issued PARSONS, R M Carolina Power & Light Co 84/07/25 O'REILLY, J P Region 2. Office of Director 2pp 26282 148 24X Fiche 30-400,84/08/10,8408280456
- 840B100009 IE info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 630103) 64/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000.84/08/13,840B100009
- 8408100038 IE Info Notice 84-64, "BWR HPCI Instration Seal-In & Indication " Svc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26178 073 24X Fiche 50-000,84/08/15,8408100038
- B40Bi00021 IC Info Notice B4-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26198 001 24X Fiche 50-000,84/08/16,840B100021
- B408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/17 Consolidated Edison Co of New York Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- 8408140208 IE Info Notice 84-67, "Recent Shubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Cp of New York, Inc 122pp 26276 122 244 Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-66, "Potential Deficiency in Improperly Rated Field Wiring to Bolenoid Valves " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York: Inc 115pp 26327 008 24X Fiche 50-000.84/08/21,8408210142

- B408240316 Forwards SALP Repts 50-261/84-24,50-324/84-16,50-325/84-16 & 50-400/84-18 for Feb 1983 - Apr 1784 LEMIS.R C Region 2. Office of Director 84/08/21 UTLEY,E E Carolina Power & Light Co 2pp 26225 230 24X Ficho 50-000.84/08/21,8408240316
- --8408240319 SALP Repts 50-261/84-24.50-324/84-16.50-325/84-16 & 50-400/84-18 for Feb 1983 Apr 1984 Region 2, Office of Director 84/04/30 71pp 26225 232 24X Fichs 50-000,84/08/21.8408240316
- 8408280215 Forwards GA Insp Rept 999000255/83-01 re defective capstan spring tangs in PSA-1 & PSA-3 mechanical snubbers mfg by Pacific Scientific Co Process requiring vendor to form spring before age hardening specified ZECH. 8 G Vendor Program Branch 84/08/22 LEWIS,R C Division of Project & Resident Programs App 26274 301 24X Fiche 30-000.84/08/28.8408280215
- 8408280439 Forwards SALP rept for 800701-811231 & NRC Manual Chapter NRC-0516 Page 9 of Cleuitt prefiled testimony refers to SALP rept Figures on Page 9 of Cleuitt attachment came from Page 2 of rept Related correspondence BARTH-C A Hearing Branch 1 D58 342 84/08/22 PAYNE, T Affiliation Not Assigned 1p 26280 275 24X Fiche 50-400, 84/08/22,8408280437
- 8408300243 Forwards responses to Unitten & Verbal questions raised by Equipment Gualification Branch reviewers during Insp Conducted on 840809 & 10
  ZIMMERMAN.S R Carolina Power & Light Co 84/08/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 26300 129 24X Fiche 90-400, 84/08/24, 8408300243
- S Reportable occurrences, LERs & related correspondence
- 8405270062 Forwards "Investigation of Types AF & AE Piston Skirts "
  Rept supercedes 840227 submittal
  RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group 84/05/24
  DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp
  24690 045 26X Fiche 50-000,84/05/24.8405290062
- --8405290075 "Investigation of Types AF & AE Piston Skirts" \* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp 24X Fiche 50-000,84/05/24,8405290062
- 8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations" RAY.C L 7DI (Transamerica Delaval, Inc.) Dwners Group 84/05/2: DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 24692 090 24X Fiche 50-000.84/05/24,8405290179
- 8408040405 Forwards repts received by BNWL & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts, Analysis & Recommendations re Main Propulsion Engines M/V Columbia" oncl
  ALZHEIMER.J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER.M Division of Licensing 158pp 25726 173 24X Fiche 50-000.84/06/28,840806040405
- B40B050050 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Cenerator Gwners Group B40622 meeting RAY, C L TDI (Transamertra Belaval, Inc.) Dwners Group B4/07/10 BERLINGER. C Director's Office. Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50-000,84/07/10,
- B40B090291 Second interim deficiency rept. Item 162 re inadequate tack welds in fire barrier panels Initially reported on 840314 Sections of cable tray will be protected by covers by 850531 Final rept will be issued by 830531 Final rept will be issued by 830531 PARSQNS,R M Carolina Power & Light Co 84/07/11 D'REILLY, J P Region 2. Office of Director 4pp 25974 032 24X Fiche 50-400,84/07/11.8408090291
- 8408090018 Second interim deficiency rept. Item 160 re defective shop welds on seismic restraint structures Initially reported on 840306 Next rept anticipated by 850331 PARSONS R M Carolina Power & Light Co 84/07/13 O'REILLY, J P Region 2. Office of Director 4pp 25993 250 24X Fiche 50-400.84/07/13.8408090018
- 8408070131 Interin deficiency & Part 21 repts. Item 178 re stainless stoel sockolettes & weldolettes supplied by Guyon Alloys.
  Inc not in accordance U/NCA 3800 Initially reported on 840517 Next rept by 840715
  PAREDNS.R M Carolina Power & Light Co 84/07/16 D'REILLY, J P Region 2. Office of Director 4pp 25974 320 24X
  Fiche 50-400,84/07/16.8408090131

- 8408090031 Interin deficiency rept. Item 176 rg Kerite Co single conductor power cables damaged but undetected by insp to testing Initially reported on 840619 Final rept by 841215 PARSINES, R M Carolina Power & Light Co 84/07/19 O'REILLY, J F Region 2, Office of Director 4 pp 25992 251 24X Fiche 50-400, 84/07/19, 8408090031
- B409070066 Deficiency & Part 21 repts, Item 17° re Westinghouse not considering interaction scenario when postulating in-core flux mapping sys Initially reported on B40622 Reportability to be determined by B40930 PARSONS, R M Carolina Power & Light Co B4/07/19 O'REILLY, J P Region 2, Office of Director 1p 25792 146 24% Fiche 50-400, B4/07/19, 8408090066
- 8408160438 Interim deficiency rept. Item 175 re exceeding max bolt handness values Initially reported on 840517 Corrective action & submission of final rept will be accomplished by 840926 Also reportable per Part 21 PARBUNS.R M Carolina Power & Light Co 84/07/24 D'REILLY. J P Region 2. Office of Director 4pp 26106 343 24X Fiche 50-400.84/07/24.8408160438
- 8408160416 Interin deficiency rept. Item 180 re welds in emergency air cleaning units Initially reported on 840628 Analysis of weld connections underway Next rept will be submitted by 840628 PARSONS.R M Carolina Power & Light Co 84/07/25. O'REILLY, J P Region 2, Office of Director ip 26106 073 24x Fiche 50-400.84/07/25.8408160416
- 8408040102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNML RAY.C L FDI (Transamerica Delaval, Inc.) Quiners Group 84/07/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 29732 137 24X Fiche 50-000,84/07/27,8408060102
- --8408060138 "Energency Dissel Generator Auxiliary Module Control Hiring & Termination Gualification Review "
  \* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139
  24% Fiche 50-000.84/07/27, 840806102
- 8408160168 Fifth inturim rept. Item 41 re potentially significant failure of reactor protection sys following high energy line rupturs initially reported on 800707 Steam generator reflegs will be insulated. Final rept to be issued 841002 PARSINNS, R M Carolina Power & Light Co 84/07/30 O'REILLY, J Region 2, Office of Director 4pp 26108 036 24X Fiche 50-400.84/07/30.8408160168
- 8408160408 Interim deficiency rept. Item 104 re defective welds on 480-volt switchgear, purchase order NY-435171 Initially reported on 830304 Major defective welds repaired Final rept will be submitted by 850401 PARSONS, R M Carolina Power & Light Co 84/07/30 O'REILLY, J P Region 2, Office of Director 4pp 26106 126 24X Fiche 50-400, 84/07/30, 8408160408
- 840B16D443 Interim deficiency rept. Item 168 re & 9-kV switchgear circuit breakers Initially reported on 840420 Corrective action & submission of final report will be accomplished by 841001 Also reportable per Part 21 PARBINS, R M Carolina Power & Light Co 84/07/30 O'REILLY, J P Region 2. Office of Director 3pp 26107 268 24X Fiche 50-400.84/07/30.8408160443
- 8408160437 Interim deficiency rept. Item 165 re reactor vessel support anchor bolt nuts Initially reported on 840312 Procedure TPP-28 rewritten Corrective action & submission of final rept will be accomplished by 841002 PARSONS,R M Carolina Power & Light Co 84/07/31 0'REILLY, J P Region 2, Office of Director 5pp 26106 347 24x Fiche 50-400,84/07/31,8408160437
- B408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DERV-12-4 & DERV-20-4 Emergency Diesel Generator Bets "
  RAY.C L TDI (Transamerica Delaval, Inc.) Dumers Group 84/08/01
  DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 25927 064 24% Fiche 50-000, 84/08/01,8408060324
- 8408160374 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines " RAY,C L f01 (Transamerica Delava), Inc.) Duners Group 84/08/10 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26091 147 24X Fiche. 50-000, 84/08/10, 8408160394
- --B408160403 "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diosel Engines." \* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp 26091 149 24X Fiche 50-000.84/08/10.8408160394

- 840B240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program, testing & insp. maint & surveillance & sets forth requirements for operation prior to completion of program plan EIBENHUT.D 0 Division of Licensing B4/08/13 GEORGE.J B TDI (Transamerica Delaval, Inc.) Owners Group 1p 26255 194 24X Fiche 50-000.84/08/13, 84080240115
- --8408240157 Safety evaluation of TDI Owners Group program plan Based on BNML evaluation plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc \* NRC - No Detailed Affiliation Given 84/08/13 21pp 26255 195 24% Fiche 50-000.84/08/13,8408240115
- 8408160395 Forwards "Design Review of Elliott Model 900 Turbotharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets." representing final QA verified rept Addl copy forwarded to INML.per NRC request RAY.C L TDI (Transamerica Delaval, Inc.) Dwners Group 84/08/14 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 26088 163 24X Fiche 50-000.84/08/14,8408160395
- --840Bl60397 "Design Revieu of Elliott Model 909 Turbocharger Used on TOL DSR-48 & DSRV-16 Emergency Diesel Cenorator Sets " \* Failure Analysis Associates FAAA-94-5-7 84/07/31 61pp 260BB 165 24X Fiche 30-000.84/08/14.8408160395
- 8408200196 Advises that item re-possible linear type indications on surface of 8A-500 Grade B mati pipe hangers mfg by Bergen Paterson closed w/o action Item considered not reportable per 10GRB0 55(e) & Part 21
  ZECH. 9 G Vondor Program Branch 84/08/16 LEWIS.R C Region 2, Office of Director 1p 26/33/068 24X Fiche 50-400, 84/08/16, 840820194
- 8408210399 Informs that VITS 83-048 & 83-099 re possible defective welds in C&D battery racks closed w/o action based on util 830418 final rept Items not reportable per 10CFR50 55(e) or Part 21

  ZECH.9 G Vendor Program Branch 84/08/16 LEWIS.R C Region 2, Office of Director DANIELSON.D H Region 3, Office of Director 1p 26180 307 24X Fiche 50~400.84/08/16,8408210399
- 8408290179 Forwards response to 840723 request for addl info on repts submitted by TDI Diesel Generator Coners Group RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group 84/09/23 BERLINGER.C Opfice of Nuclear Reactor Regulation, Director 12pp 26289 221 24X Fiche 50-000.84/08/23,8408290179

# T Hearing transcripts on non-antitrust matters

- 8408140014 Forwards testimony & exhibits to be offered into evidence at hearings on safety contentions, to begin on 840905 & 1010
  Related correspondence
  BAXTER, T A Shaw. Pittman, Potts & Trambridge BAXTER, T A
  Carolina Power & Light Co BSB 950 84/08/09 KELLEY, J L,
  BRIGHT, O J, CARFENTER, J H Atomic Safety and Licensing Board Panel
  3pp 26082 130 24X Fiche 50-400,84/08/09,8408140014
- --8408140018 Testimony of MJ Hitchier on Joint Intervenor Contention
  VII (4) re steam generator tube rupture analysis Related
  correspondence
  HTCHLER.M J Carolina Power & Light Co HITCHLER.M J
  Westinghouse Electric Corp 84/08/09 Atomic Safety and
  Licensing Board Panel 27pp 26/082 133. 24X
  Fiche 50-400,84/08/09,8408140014
- --8408140023 Testimony of JF Nevill, AG Fuller, DR Timberlake & KV Hate on Eddleman Contention 41 re pipe hanger welding Related correspondence
  NEVILL, J F, FULLER, A G, TIMBERLAKE, D.R. Carolina Power & Light
  Co 84/08/09 Abomic Safety and Licensing Board Panel 35pp
  26082 160 24% Fiche 50-400,84/08/09,8408140014
- --B408140027 Testimony of GA Kanakaris, RM Parsons & LF Garner on Eddleman Contention 65 re contrate containment structure Related correspondence KANAKARIS, O A . PARSONG, R M Carolina Power & Light Co KANAKARIS, O A . Ebasco Bervices, Inc (subs of Enserch Corp ) B4/08/09 Atomic Safety and Licensing Board Panel 156pp 26082 195 24X Fiche 50-400,84/08/09,840B140014
- --8408140031 Testimony of MA Serbanescy on Eddleman Contention 116 re fire protection Prof qualifications enci Related correspondence BERBANESCU.M A Consumers Power Co SERBANESCU.M, A Ebasco Services, Inc. (subs of Enserch Corp.) 84/08/09 Atomic Safety and Licensing Board Panel 42pp 26082 351 24X Fiche 30-400,84/08/09,8408140014

- --8408140036 Testimony of DB Waters on Eddleman Contention 116 re fire protection Related correspondence WATERS:D B Carolina Power & Light Co 84/08/09 Atomic Bafet, and Licensing Board Panel 200pp 26083 031 24X Fiche 50-400:84/08/09.8408140014
- 8408140044 Forwards listed NRC testimony on safety issues of hearings on 840905 % 1010 SER & SSER 1 Related correspondence BARTH, C A Hearing Branch i DSB 941 84/08/07 KELLEY, J L , BRIGHT, G C , CAMPENTER, J H Atomic Safety and Licensing Board Panel 2pp 26052 029 24% Fiche 50-400.84/08/09.8408140044
- ~-8408140070 Testimony of PR Bemis an Jaint Intervenor Contention 1 re mgt qualifications Related correspondence BEMIS,P R Region 2, Office of Director 84/08/09 43pp 26052 031 24X Fiche 50-400,84/08/09,8408140064
- --B40Bi40075 Testimony of LB Marsh & HF Conrad re Joint Contention VII, Part (4) Prof qualifications encl Related correspondence MARSH.L B Reactor Systems Branch CONRAD, HF Materials Engineering Branch 84/08/09 9pp 26052 074 24x Fiche 50-400,84/08/09,840Bi40064
- ~~B40B1400B1 Testimony of PR Bemis.GA Hallstrom & JJ Blake on Eddleman Contention 41 re pipe hanger welds Related correspondence BEMIS.PR R HALLSTROM.O A . BLAKE.J J Region 2. Office of Director B4/08/09 57pp 26052 083 24X Fiche 50-400.84/08/09.8408140064
- --B40B1400B4 Testimony of JR Harris, JJ Lenahan & PR Bemis on Eddleman Contention 65 rs concrete placement Related correspondence HARRIS, J R., LENAMAN, J J. BEMIS, PR Region 2, Office of Birector 84/08/07 Sipp 26052 140 24X Fiche 50-400, 84/08/09, 840B140064
- --B408140073 Testimony of R Eberly & RL Ferguson on Eddleman Contention 116 re fire protection program Related correspondence EDERLY R. FERGUSON.R L Chemical Engineering Branch 84/08/09 74pp 26082 191 24X Fiche 50-400,84/08/09,8408140064
- 840B140146 Forwards joint testimony re Joint Intervenor Contention I concerning mgt capability FBAR sections, as exhibits, encl Related correspondence FLYNN, 8 F Carolina Power & Light Co DSB 936 84/08/07 KELLEY, J L , BRIGHT, 9 D , CARPENTER, J H Atomic Safety and Licensing Board Panel 2pp 26046 001 24% Fiche 50-400,84/08/09,8408140146
- --B40B140151 Joint testimony of EE Uiley.MA McDuffie,T Elleman.HR Banks, PW Howe, CR Dietz, GP Deatty, RC Morgan.RA Watson.JL Willis, JM Davis & AM Powell on Joint Intervenor Contention I remgt capability FSAR exhibits encl Related correspondence UTLEY, E s. MCDUFFIE.M A . ELLEMAN.T B Carolina Power & Light Co B4/08/09 365pp 26046 003 24X Fiche 50-400, B4/08/09, B40B140146
- 840Bi40478 Testimony of J Clewett re joint Contention i Svc list enci Related correspondence CLEWETT, J Joint Intervenors - Shearon Harris DSB 025 38pp 26060 294 24% Fiche 30-400.84/08/09,8408i40478
- B40B140273 Transcript of B40B10 telcon in Bethesda:MD w/util & North Carolina Eastern Municipal Power Agency Pp 2, 205-2, 277 \* Atomic Safety and Licensing Board Panel B4/08/10 72pp R4043 073 24% Fiche 50-400;84/08/10,840B140273
- 8408300158 Transcript of 840827 hearing in Bethesda, MD Pp 2,278-2,345 \* Atomic Safety and Licensing Board Panel 84/08/27 70pp 26305 221 24% Fiche 50-400,84/08/27,8408300158

# V Operator Examinations

8408310014 Confirms 840605 telcon re 840612 mgt meeting in Region II ofcs to discuss upcoming operator exams & requalification of licensed operators following steam generator outage Q'REILLY, J P Region 2, Office of Director 84/06/08 UTLEY, E Carolina Power & Light Co 1p 26333 357 24X Fiche 50-000,84/06/08,8408310014

DOCKET 50-401 SHEARDN HARRIS NUCLEAR POWER PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8408300277 Confirms 840802 telcon between DB Waters & PR Bemis re 840809 mpt meeting in Atlanta, GA to discuss emergency plans, action levels & emergency operating procedures LEWIS.R C Region 2, Office of Director 84/08/07 UTLEY, E E Carolina Power & Light Co 1p 26304 353 24X Fiche: \$0-400,84/08/07,8408300297

- G Adjudicatory correspondence
- 8408160128 Forwards NRC staff Exhibits 1-3 & intervenor Exhibit 1 Related correspondence RILEY.S L Tayloe Associates 84/06/25 PLEASANT.E Administrative & Logistical Support Branch 1p 26126 167 24X Fiche 50-400.84/06/25.8408160128
- 8408070397 Response in support of applicant 840718 motion for reconsideration or clarification of ASLB 840413 memorandum & grder on Joint Contention IV Certificate of Svc prc1 MODRE, J E Healing Branch I DSB 811 84/07/21 Atomic Safeti and Licensing Board Panel 9pp 25942 237 24X Fiche 50-400.84/07/31.84080/0397
- 8408090224 Informs that NRC consultant T Urbanak will not be available until 840813 to respond to interrogatories re Contentions 215 t 224 Related correspondence 8ARTH, C A Hearing Branch 1 DSB 865 84/08/01 EDDLEMAN, W Eddleman, U 1p 25971 243 24X Fiche 50-400,84/08/01.8408090224
- 8408070293 Order providing final set of rulings on admissibility of affaite emergency planning contentions, ruling on petition for maiver of need for power rule & notice of upcoming telcon call Served on 840806 BRIGHT.0 O CARPENTER, J H , KELLEY, J L Atomic Safety and Licensing Board Panel DSB 771 84/08/03 62pp 25748 011 24X Fiche 50-400.84/08/03.8408070293
- B408090170 Further response to 840329 interrogatories re Joint Intervenor Contention i concerning mgt qualifications Affidavits of FS Cantrell & PR Bemis & Certificate of Svc encl Related correspondence
  BARTH, C A Hearing Branch i DSB 846 84/08/03 Atomic Safety and Licensing Board Panel 43pp 25973 129 24%
  Fiche 50-400.84/08/03.8408090170
- 8408070172 Reply findings re Eddleman Contention 8F(1) & Joint Contention II(e) & II(c) Eddleman proposed Findings 11 & 14 & portions of Joint Intervenor Findings 8,7:22 & 27 should not be adopted Certiricate of Svc encl MODRC. J E Hearing Branch I DSB 864 84/08/06 Atomic Bafety and Licensing Board Panel 7pp 25773 010 24X Fiche 50-400.84/08/06,84080970172
- 8408200470 Forwards FEMA responses to 840627 interrogatories Certificate of Svc encl Related correspondence MOCRE.J E Hearing Branch i DSB 174 84/08/14 EDDLEMAN.W Eddluman, W 3pp 26125 321 24% Fiche 50-400,84/08/14.8408200470
- --8408200497 Response to interrogatories propounded by intervenor W Eddleman Related correspondence HAPKINS.T I, ROCHLIS.S M Federal Emergency Management Agency 84/08/07 EDDLEMAN.W Eddleman W Sipp 26136 324 24X Fiche 50-400.84/08/14.8408200490
- 8408270122 Forwards SER re TD1 Diese) Generator Owners Group program plan Rept discussed during 840810 conference call Related correspondence MODRC, J E Hearing Granch 1 DSB 308 84/08/21 KELLEY, J L , CARPENTER, J H , DRIGHT, G O Atomic Safety and Licensing Board Panel 50pp 26248 002 24X Fichs 50-400,84/08/21,8408270122
- 8408230140 Notice of evidentiary hearing on Joint Contention 1, commencing on 840905 in Raleigh, NC Served on 840822 KELLEY, J.L. Atomic Safety and Licensing Board Panel DSB 210 84/08/22 Office of the Executive Legal Director 1p 26209 298 24X Fiche 50-400,84/08/22,8408230160
- 8408280439 Forwards SALP rept for B00701-811231 & NRC Manual Chapter NRC-0516 Page 9 of Clewitt prefiled testimony refers to SALP rept Figures on Page 9 of Clewitt attachment came from Page 2 of rept Related correspondence BARTH.C A Hearing Branch 1 D5B 342 84/08/22 PAYNE, TAFfiliation Not Assigned 1p 26280 293 24X Fiche 50-400.84/08/22.84089.0439
- G Inspection reports, IE Bulletins & correspondence
- 8408280215 Forwards QA Insp Rept 999000255/83-01 re defective capstan spring tangs in PSA-1 & PSA-3 mechanical snubbers mfg by Pacific Scientific Co Process requiring vendor to form spring before age hardening specified ZECH-0 G Vendor Program Branch 84/08/22 LEWIS,R C Division of Project & Resident Programs 6pp 26274 301 R4X Fiche 50-000,84/08/22,8408280215

- 8408280439 Forwards SALP rept for 800701-811231 & NRC Manual Chapter NRC-0516 Page 9 of Clewitt prefiled testimony refers to SALP rept Figures on Page 9 of Clewitt attachment came from Page 2 of rept Related correspondence BARTH, C A Hearing Branch 1 DSB 342 84/08/22 PAYNE, F Affiliation Not Assigned 1p 26280 295 24X Fiche 50-400, 84/08/22, 8408280439
- S Reportable occurrences. LERs & related correspondence
- 8405290062 Forwards "Investigation of Types AF & AE Piston Skirts "
  Rept supercedes 840227 submittel
  RAY.C L TD1 (Transamerica Delaval, Inc.) Owners Group 84/05/24
  DENTON:H R Office of Nuclear Reactor Regulation, Director 2pp
  24690 045 24X Fiche 50~000.84/05/24,8405290062
- --8405270075 "Investigation of Types AF & AE Piston Bkirts "
  \* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp
  24X Fiche 50-000,84/05/24,8405270062
- 8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations" RAY.C L TDI (Transamerica Delaval, Inc.) Dwners Group 84/05/24 DENION, H R Defice of Nuclear Reactor Regulation, Director 2pp 24692 090 24X Fiche 50-000,84/05/24,8405290179
- 8408060405 Forwards repts received by BNML & consultants directly from FaAA & TDI Owners Group at 840682 meeting Draft "Overview of Repts, Analysis & Recommendations re Main Propulsion Engines MVV Columbia" encl ALZHEIMER, J M Battelle Memorial Institute, Pacific Northwest Laboratories 84706/28 MILLER, M Division of Licensing 158pp 25926 173 24X Fiche 50-000,84/06/28,840806040405
- B408060050 Forwards info addressing open items identified in NRC/BNHL/TDI Dissel Generator Cumprs Group 840622 meeting RAY.C t TDI (Transamerica Delaval. Inc.) Cumers Group. 84/07/10 IERLINGER.C Director's Office. Office of Inspection and Enforcement 43pp 25933 133 24X Fichs 50-000, 84/07/10, 84/0826090
- 8408060102 Forwards "Emergency Diesel Generator Auxiliary Modula Control Wiring & Termination Qualification Review " Addl copies sent to DNML RAY, C.L. TDI (Transamerica Delaval: Inc.) Owners Group 84/07/2 DENTON: H.R. Office of Nuclear Reactor Regulation, Director 2pp 25932 137 24X Fiche 50-000.84/07/27,8408040102
- --8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review"
  # Stone & Webster Engineering Corp 84/07/31 36pp 25932 139
  24X Fiche 50-000, 84/07/27,8408060102
- 8408040324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TOI DSRV-12-4 & DBRV-20-4 Emergency Diesel Generator Bats "
  - RAY.C L TD1 (Transamerica Delaval, Inc.) Guners Group 84/08/01
    DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
    25927 064 24X Fiche \$0-000.84/08/01,8408060324
- 8408160394 Forwards "Design Review of Engine Base & Bearing Caps For TDI DERV-16 Diesel Engines"

  RAY.C. L TDI (Transamerica Dolaval, Inc.) Owners Group 84/08/10 DERTON, HR Office of Nuclear Reactor Regulation, Director 2pp 26091 147 24X Fiche 50-000, 84/08/10,8408160394
- --8408160403 "Design Revieu of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines " \* Failure Analysis Associates FAAA-84-6-53 64/08/31 44pp 26091 149 24% Fiche 50-000,84/08/10,8408160394
- 8408240115 Forwards SER re TDI Owners Group program plan, SER addresses design review/quality revalidation program testing & insp. maint & surveillance & sets forth requirements for operation prior to completion of program plan EISENHUT.D @ Division of Licensing 84/08/19 GEGROE, J B TDI (Transamerica Delaval. Inc.) Owners Group ip 26255-174 24X Fiche 50-000,84/08/13,8408240115
- --8408240157 Bafety evaluation of TDI Owners Group program plan Based on BNWL evaluation, plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc \*\*NRC No Datailed Affiliation Diven 84/08/13. 2ipp 26258 195 24X Fiche: 50-000, 84/08/13, 8408240115.

160395 Forwards "Design Review of Elliott Hodel 906 Turbocharger ed on TDI DSR-48 & DSRV-16 Emergency Diesel Generator ts." representing final QA verified rept Addi topy rwarded to BNML, per NRC request Y.C L TDI (Transamerica Delaval. Inc.) Owners Group 84/08/14 NTDN.H R Dffice of Nuclear Reactor Regulation, Director 2pp 088 163 24X Fiche 50-000.84/08/14.8408160395

O8160397 "Design Review of Elliott Model 908 Turbocharger Used on TOI DBR-48 & DSRV-16 Energency Diesel Generator Sets "-Failure Analysis Associates FAA-84-5-7 84/07/31 61pp 26088 165 24X Fiche 50-000.84/08/14.8408160395

210399 Informs that VITS 83-048 & 83-099 re possible defective lds in C&D battery racks closed w/o action based on util 3418 final rept Items not reportable per 10CFR50 55(e) or rt 21
2H. 0 G Vandor Program Branch 84/08/16 LEMIS.R C Region 2, fice of Director DANIELSON.D H Region 3, Office of Director 26180 307 24X Fiche 50-400.84/08/16.8408210399

290179 Forwards response to 840723 request for additinfo on repts imitted by TDI Diesel Generator Gumers Group (r.C.L. TDI (Transamerica Delaval, Inc.) Gumers Group 84/08/23 LINGER, C. Office of Nuclear Reactor Regulation, Director 12pp 221 84X Fiche 50-000.84/08/23,8408290179

## aring transcripts on non-antitrust matters

;

40C44 Forwards listed NRC testimony on safety issues of hearings 840905 & 1010 SER & SSER I Related correspondence ITH.C A Hearing Branch I DSB 941 84/08/09 KELLEY,J L , GHT.C O , CARRENTER,J H Atomic Safety and Licensing Board Panel p 26052 029 24X Fiche 50-400.84/08/09.8408140064

8140070 Testimony of PR Benis on Joint Intervenor Contention 1 re gt qualifications Related correspondence EMIS, P R Region 2, Office of Director 84/08/09 43pp 6052 031 24% Fiche 50-400.84/08/09.8408140084

8140075 Testimony of LB Marsh & HF Conrad re Joint Contention VII, art (4) Prof qualifications encl Related correspondence ARSH, L B Reactor Systems Branch CONRAD-H F Materials ngineering Branch 84/08/09 9pp 26052 074 24X iche 50-400.84/08/09,8408140044

B140081 Testimony of PR Demis, 9A Hallstrom & JJ Blake on Eddleman antention 44 re pipe hanger welds Related correspondence EMIS, PR. HALLSTROM, CA., BLAKE, JJ. Region 2. Office of irector 84/08/09 57pp 26052 083 24X Fiche 50-400,84/08/09,408140064

\$140086 Testimony of JR Harris, JJ Lenahan & PR Bemis on Eddleman intention 65 re concrete placement Related correspondence MRRIS, JR, LENAMAN, JJ, BEMIS, PR Region 2, Office of Irector 84/08/09 51pp 26052 140 24X Fiche 50-400,84/08/09,108140064

1140093 Testimony of R Eberly & RL Ferguson on Eddleman Contention 6 re fire protection program Related correspondence. IERLY, R., FERGUSON, R. C. Chemical Engineering Branch 84/08/09 pp 26032 191 24% Fiche 50~400,84/08/09.840814064

0478 Testimony of J Clewett re joint Contention 1 Svc list encl ted correspondence ETT. J Joint Intervenors - Shearon Harris DSB 025 26060 294 24% Fiche 30-400.84/08/09.8408140478

0293 Transcript of 840810 telcon in Bethesda, MD w/util & North lina Eastern Municipal Power Agency Pp 2, 205-2, 277 tomic Safety and Licensing Board Panel 84/08/10 72pp 3 073 24% Fichw 50-400, 84/08/10, 8408140293

158 Transcript of 840827 hearing in Bethesda, MD Pp 2, 278-2, 345 omic Safety and Licensing Board Panel 84/08/27, 70pp 221 24X Fich® 50-400, 84/08/27, 8408300158

#### ator Examinations

Ol4 Confirms 840605 telcon re 840682 mgt meeting in Region II to discuss upcoming operator exams & requalification of sed operators following steam generator outage LLY, J.P. Region 2, Office of Director 84/06/08 UTLEY, E.E. ina Power & Light Co. ip 26333 357 24% 50-000,84/06/08.8408310014

DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

F Security, medical, emergency 2 rire protection plans

B40B010297 Forwards IE Insp Rept 50-409/84-06 on 840618-19 No noncompliance noted however energency plan weaknesses identified List of weaknesses end! PAPERIELLO.C J Region 3. Office of Director 84/07/10 LINDER,F W Dairyland Power Cooperative App 25866 162 24) Fiche 50-409,84/07/10.8408010297

--8408010299 IE Insp Rept 50-409/84-06 on 840618-19 No noncompliance noted, however weaknesses identified in emergency preparedness eiercise conducted on 840619 Natrablye summary of instial plant conditions encl SNELLW G , GLOERSEN, W B , LERS.L L Region 3, Office of Director 84/07/10 9pp 25866 166 24% Fiche 50-409,84/07/10,8408010297

B40B220105 Forwards response to 830517 comments on Sections 5 2 2 & 1 4 1 of security plan & Section 1 12 of guard training & qualification plan Reeting requested w/RRC on 840920-21 Response withheld LINDER.F Dairyland Power Cooperative 84/08/08 Office of Nuclear Reactor Regulation. Director 2pp 26193 305 24X Fiche 50-409, 84/08/08.8408220105

840B210333 Submits safety analysis of safety parameter display sys & operational support ctr as required by Generic Ltr 82-33 re emergency response capability (Suppl 1 to NUREG-0737) LINDER.F Dairyland Power Cooperative 84/08/13 CRUTCHFIELD.D Operating Reactors Branch 5 Gpp 26179 332 24X Fiche 50-409.84/08/13.8408210333

### P Operating license stage documents & correspondence

B408070099 Forwards Opneric Ltr 84-13, "Tech Specs for Snubbers," unitted from 840503 ltr to all SEP licensees NRC position that issue of Tach Specs for snubbers will be resolved on generic basis restated CRUTCHFIELD.D Assistant Director for Safety Assessment B4/07/31 KAY, J A Yankee Atomic Electric Co LINDER, F Dairyland Power Cooperative FIEDLER, PB General Public Utilities - GPU Service Corp 4pp 29755 227 24X Fiche 50-000.84/07/31.8408070099

8408150212 Requests exemption from NUREG-0737, Table II f 1-2, design basis shielding envelope criteria of 100 uCi/cc of gaseous radiododine & particulates deposited on sampling media LINDER, F Dairyland Pouer Cooperative 84/08/01 CRUTCHFIELD, D Operating Reactors Branch 5 4pp 26066 241 24X Fiche 50-409.84/08/01.8408150212

8408140287 Submits add3 info supporting 800714 request for relief from performing inservice testing on alternate core spray sys chack valves & boron injection outlet check valve, per IOCFRSO 55 adg)(6)(1)
LINDER, F Dairyland Power Cooperative 84/08/02 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 26054 357 24%
Fiche 50-409,84/08/02.8408140287

34080701i0 Owneric Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holdons of CPs le availability of Buppl 1 to NUREO-0933, "Prioritization of Generic Safety Issues" Svc list encl EISENHUT.D O Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp. 26129 238 24% Fiche 50-000,84/08/06.8408070110

840B14009B Informs that 840306 GA program description not in accordance w/Paragraph (3)(ii) of 10CFR50 54(a) Requests revised submittal within 30 days of ltr receipt, incorporating listed info SPESSARD,R L. Region 3, Office of Director 84/08/09 LINDER,F W Dairyland Power Cooperative 2pp 26044 355 24X Fiche 50-409,84/08/07.8408140098

8408270080 Forwards fees for 840716 & 20 applications for amend to License DPR-45 LINDER:F Dairyland Power Comperative 84/08/14 MILLER:W D License Fee Management Branch 1p 26246 361 24% Fichs 50-409.84/08/14.8408270080

8408210547 Requests remittance of Class II fee for 830404 application to amend License DPR-45, changing Tech Specs re reporting requirements for safety valve operations & overtime restrictions Changes considered administrative DIGGSR M License Fee Hanagement Dranch 84/08/16 LINDER.F Dairyland Power Cooperative ip 26195 263 24% Fiche 50-407,84/08/16:8408210547

- 8408210029 Advises that node to conteinment pressure manitoring systo increase systange & sys mod to measure Actum up to 5 psig satisfy NUREO-073/ requirements & are acceptable PAULSON, v.A. Operating Reactors Branch 5 84/08/17 LINDER, F. Dairyland Power Cooperative 2pp 26181 335 24X Fiche 50-409,84/08/17,8408210029
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling quidance for licensee submittals or reloads that involve unroviewed safety questions Svc list encl EISENBUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pu 26276 244 24X Fiche 50-000.84/08/20,8408200275
- B408220093 Forwards notice of environ assessment & finding of no significant impact re 800926 request for exemption from 10CFRSO, App J requirements concerning reactor containment bidg airlock door seal testings PAULSON, W A Operating Reactors Branch 5 84/08/20 LINDER, F Dairyland Power Cooperative 4pp 24193 293 24X Fiche 50-409,84/08/20.8408220093
- --8408220099 Notice of environ assessment & finding of no significant impact re 800926 request for exemption from 10CrR30,App J requirements concerning reactor containment bidg airlock door seal testings
  EISENHUT,D @ Division of Licensing 84/08/20 4p 26193 297 24X Fiche 90~409.84/08/20,8408220093
- 8408230418 Informs that original approval of program re NUREG-0737. Item I A 1 I, "Shift Technical Advisor," remains unchanged All new hires must neet training requirements specified in 790913 & 1030 ltrs PAULSON,W A Operating Reactors Branch S 84/08/22 LINDER,F Dairyland Power Cooperative 2pp 24204 009 24X Fiche: 50-409, 84/08/22, 8408230418
- B408310176 Application for amend to License DPR-45, changing Tech Specs to modify overtime spec LINDER, F Dairyland Power Cooperative 84/08/23 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 26318 333 24X Fiche 30-409, 84/08/23,8408310176
- --B408310179 Proposed Tech Spec re overtime

  \* Dairyland Power Cooperative 84/08/23 1p 26318 336 g4X
  Fiche 50-409,84/08/23,8408310176
- Q Inspection reports, IE Bulletins % correspondence
- 8408010297 Forwards IE Insp Rept 50-409/84-06 on 840418-19 No moncompliance noted houseer energency plan weaknesses identified List of weaknesses encl PAPERIELLO, C. J. Region 3, Office of Director 84/07/10 LINDER; F. W. Dairyland Power Cooperative 4pp 25846 162 24X Fiche 50-409,84/07/10,840801029.
- --8408010299 [E Insp Rept 50-407/84-06 on 840618-19 No noncompliance noted, however weaknesses identified in emergency preparedness exercise conducted on 840619 Narrative summary of initial plant conditions encl SNCLL, W 9, GLOERSEN, W B, LERB, L L. Region 3, Office of Director 84/07/10, 9pp 25866-166 24X Fiche 30-409, 84/07/10, 8408010297
- B408060004 Responds to IE Bulletin B4-02 re failures of GE Type HFA relays in use in Class IE safety sys Relays tested annually No deterioration or malfunctions noted Replacement of all six HFA relays uill be completed within 2 yrs LINDER; F Dairyland Power Cooperative B4/07/17 KEPPLER, J G Region 3, Office of Director 3pp 25933 187 24% Fiche 50-409,84/07/17,8408060004
- B407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants "Svc list encj JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/07/27 Constitated Edison Co. of New York, Inc. 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229
- B408230227 Forwards IE Insp Rept 50-409/84-07 on B40516-0715 & notice of violation BHAFER, W D Region 3, Office of Director B4/07/31 LINDER, F W Dairyland Power Cooperative 2pp 26213 177 24X Fichu 50-409, 84/07/31, 8408230227
- --8408230234 Notice of violation from insp on 840516-0715 SHAFER,W D Region 3, Office of Director 84/07/31 1; 26213 179 24X Fiche 50-407,84/07/31,8408230227

- --8408230238 IE Insp Rep\* 50-409/84-07 on 840516-0719 Noncompliance noted failure to provide positive control over area w/ radiation levels greater than 1.000 mrem/h BDVD, D C Region 3. Office of Director 84/07/31 lipp 26213 180 24X Fiche 50-409.84/07/31.8408230227
- 8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during inspiristituted effective 840820 Preprinted form will be used rather than ltr
  KEPPLER.J G Region 3, Office of Director 84/08/03
  Commonwealth Edison Co. 3pp. 25742 188 24X Fiche 50-000.84/08/03, 8408070401
- 8408010333 IE Info Notice 84-39, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JOROAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24x Fiche 50-000,84/08/06,8408010337
- 8408230146 Forwards IE Inap Rept 50-407/84-10 on B40717-25 No noncompliance noted WALKER, R D Region 3, Office of Director 84/08/06 LINDER, F W Dairyland Power Cooperative 2pp 26214 028 24X Fiche 50-409,84/08/06,8408230146
- --B408230149 IE Insp Rept 50-409/B4-10 on B40717-25 No noncompliance or deviations noted Major areas inspected licensee actions re unusual events LANKSBURY.R D , BROWN.C H , REYES.L A Region 3, Office of Director B4/08/06 Spp 26214 030 24X Fiche 50-409,84/08/06, 8480-2014
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- 8408070374 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list enc! GRACE.J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26/30 001 24% Fiche 50-000.84/08/10,8408070376
- 8408100009 IE Info Notice 84~63. "Defective RHR Replacement Piping "
  Bvc list encl
  JDRDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc. 119pp 26197 218 24X Fiche 50~000,84/08/13,8408100009
- 8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication "Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038
- 8408100021 IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021
- 840B100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list enc! JURDAN, E L Division of Emergency Preparedness & Engineering Response (Past 800103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- B408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering R#spense (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc. 11580 26327 008 24X Fiche 50-000,84/08/21,8408210142

- 8408270287 Ack receipt of 840801 ltr informing NRC of steps taken to comply w/840717 confirmatory action itr NORELIUS, C E Region 3. Office of Director 84/08/21 LINDER, F W Dairyland Power Cooperative 1p 26241 008 24% Fiche 50-409.84/08/21.8408270287
- --8408270294 Responds to NRC 840717 confirmatory action ltr Corrective actions lower mechanism from CRD 29 removed tested to replaced after mormal functioning determined & CRD 13 lower mechanism repaired
  LINDER.F Dairyland Power Cooperative 84/08/01 KEPPLER, J G Region 3, Dffice of Director opp 26241 009 24%
  Fiche 50-409.84/08/21.8408270287
- R Periodic operating reports & related correspondence
- 8408220190 "Semiannual Radioactive Effluent Rept for LACBWR, Jan-June 1984 " W/840810 ltr LINDER,F Dairyland Power Cooperative 84/06/30 KEPPLER,J G Region 3, Office of Director 25pp 26188 184 24X Fiche 50-409,84/06/30,8408220190
- S Reportable occurrences, LERs & related correspondence
- B40B1601B6 LER 84-011-00 on 840716, switchyard potential transformer sharted out; causing protective devices to operate & apeniae breakers, resulting in loss of offsite power Emergency diesel generator 1B output breaker failed to close W/840B0B ltr GODDMAN, L 9, LINDER, F. Dairyland Power Cooperative 84/08/08 Spp 26106 329 24X Fichs 50-409,84/08/08.840B1601B6
- 8408160307 LER 84-010-00 on 840716, during reactor shutdown, control rod 29 found unable to insert electrically or hydraulically from fully withdrawn position Caused by rod jamming due to loosely assembled roller bearing assembles W/840808 ltr GDODMANL S . LINDER, F Dairyland Power Cooperative 84/08/08 7pp 26106 156 24X Fiche 50-409,84/08/08.8408160309

### V Operator Examinations

- B408140426 Provides address for transmitting all operator licensing Correspondence to Region III ofc.except info for examiners WALKER.R D Region 3. Office of Director B4/08/10 Michigan. Univ of. Ann Arbor. MI 2pp 26051 198 24% Fiche 50-000. 84/08/10.8408140426
- DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- B408060260 Forwards certification of compliance w/State of NY coastal mgt program.per Section 307(C)(3)(A) of Coastal Zone Mgt Act of 1972 & 15CFR930 57
  MANGAN.C V Niagara Mohawk Power Corp B4/07/31 EIBENHUT.D G Division of Licensing 13pp 25933 336 24X Fiche 50-410.84/07/31.
- B408060284 Forwards response to B40521 request for info re GA program Revised FSAR writeups & updated organizational charts will be incorporated in next FSAR amend HANGAN.C V Niagara Mohawk Power Corp 84/07/31 SCHWENCER, A Licensing Branch 2 50pp 25733 254 24X Fiche 50-410.84/07/31, 8408060284
- 8408130632 Notification of Significant Licensee Meeting 84~65 on 840807 in Ming of Prussia.PA to discuss NRC involvement in monitoring preoperational program at facility COLLINGS J Region 1. Office of Director 84/08/02 Region 1. Office of Director 50-410,84/08/02,8408150632
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for CLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl EISENHUT.D © Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 24129 238 24x Fiche 50-000.84/08/06.8408070110
- 8408070317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
  TREMBLAY,P P Operating Reactors Assessment Branch KOLAHAN,O M Operating Reactors Assessment Branch 13pp 24x Fiche 50-000, 84/08/06, 8408070317

- 8408170079 Informs of review of 840610 % 11 QA ploglam description changes Changes acceptable Concerns in unrevised portions of program noted MARTIN.T Division of Engineering \* Technical Programs 84/08/09 HODTEN.B J Niagara Mohawk Power Corp 2pp 26119 022 24X Fiche 50-220.84/08/09.8408170079
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re-scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list enci EISENHUT.D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276-244 24X Fiche 50-000,84/08/20.8498200275
- 8408310267 Natification of 840912 meeting w/util in Bothesda,HD to discuss instrumentation & control HAUGHEY,M F Licensing Branch 2 84/08/20 SCHWENCER,A Licensing Branch 2 3pp 26350 327 24% Fiche 50-410,84/08/20,8408310267
- 8408300300 Forwards EM Rodgers affidavit of svc indicating that FBAR Amend 13 & Suppl 7 to environ rept OL stage provided to appropriate parties Svc List encl MANGAN, C V Naggara Mohawk Power Corp B4/08/23 CISENHUT.D @ Division of Licensing 5pp 26306 354 24X Fithe 50-410.84/08/23, RADRAGORGO
- C Utility Environmental Report (ER), amends & correspondence
- B40B0B0054 Forwards updated distribution list for environ rept.deleting DOT 5CHMENCER,A Licensing Branch 2 84/08/01 HOOTEN,B J Niagara Mohawk Power Corp 5pp 25981 079 24X Fiche 50-410,84/08/01, 8408080054
- 8408300300 Forwards SM Rodgers affidavit of svc indicating that FBAR Amend 13 & Suppl 7 to environ rept CL stage provided to appropriate parties Svc list encl MANGAN.C V Niagara Mohawk Power Corp 84/08/23 EIBCNHUT,D G Division of Licensing 5pp 26306 354 24% Fiche 90-410,84/08/23,8408300300
- D NRC Draft/Final Environmental Statements, supply & correspondence
- 8408220318 DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF NINE MILE POINT NUCLEAR STATION UNIT NO 2 Docket No 90-410 (Niagara Mohauk Power Corporation Rochester Gas & Electric Corporation and Central Hudson Gas & Electric Corporation) \* Division of Licensing 84/07/31 313pp 26201 037 24X Fiche 50-410.84/07/31.8408220318
- B40B160163 Forwards DES (NUREG-1085) & FR notice of availability W/o DES BCHWENCER, A Licensing Branch 2 B4/08/09 HIRSCH, A Environmental Protection Agency 2pp 26124 355 24X Fichs 50-410,84/08/09,840B160163
- --8408160166 Notice of availability of DEG (NUREC-1085) SCHWENCER, A Licensing Branch 2 84/08/07 2pp 26124 357 24x Fiche 50-410,84/08/09,8408160163
- 8408160431 Forwards DES (NUREG-1085) & FR notice of availability W/o DE8 SCHWENCER.A Licensing Branch 2 84/08/09 HOOTEN.B J Niagara Mohawk Power Corp 2pp 26122 355 24X Fiche 50~410,84/08/09, 8408160431
- 840B170104 Forwards FR notice of availability of DES (NUREG-1085) Svc list enc! SCHMENCER.A Licensing Branch 2 84/08/09 Library of Congress 3pp 26134 355 24X Fiche 30-410.84/08/09.8408170104
- 8408170107 Forwards DES (NUREC-1085) Comments due 49 days after publication of FR notice of availability W/o encl SCHMENCER, A Licensing Branch 2 84/08/09 New York, State of 1p 26134 352 24% Fiche 50-410,84/08/09,8408170107
- 840Bi70110 Forwards DES (NUREQ-10B5) Comments due 45 days after publication of FR notice of availability W/o encl SCHWENCER, A Licensing Branch 2 B4/08/09 WOOD, J M Commerce, Dept of Natl Oceanographic & Atmospheric Administration 5pp 26134 345 24X Fiche 50-410, B4/08/09, B40BI70110
- 8408230024 Ack receipt of DES Review produced no comments MIRANDWSKI.J A Agriculture, Dept of, Research Center SCHWENCER, A Licensing Branch 2 ip 24209 035 24X Fiche 50-410,84/08/17,8408230024

- E NRC Safety Evaluation Report (SER) suppls & correspondence
- B408080164 Summary of 840320-22 meetings w/vtil in Dethesda.MD re draft SER open items HAUGHEY.MF ticensing Branch 2 84/07/30 Licensing Branch 2 9ap 25978 353 24X Fiche 50-410.84/07/30.8408080164
- 8408200148 Summary of 840705 & 06 meetings w/util in Bethesda,MD re open items in draft SER Summary of items discussed encl HANGHEY,M F Licensing Branch 2 84/08/02 Licensing Branch 2 Spp 26142 330 24% Fiche 50-410.84/08/02.8408200148
- 8408280001 Forwards responses to listed BER open items Info will be included in next FSAR amend MANGAN, C V Niggara Mohawk Power Corp 84/08/24 BCHWENCER, A Licensing Branch 2 49pp 26261 241 24X Fiche 50-410,84/08/24, 8408280001
- B40B310351 Summary of B40719 meeting w/util re open items in draft SER & revs to format of FSAR Chapter i4.Rev 12
  HAUGHEY, M F Licensing Dranch 2 84/08/27 Licensing Branch 2
  8pp 26350 333 24% Fiche 50-410.84/08/27,8408310351
- F Security, medical, emergency & fire protection plans
- B408030188 Forwards IE Insp Rept 50-410/84-10 on 840521-24 No viplations noted
  JUYNER, J H Region 1. Office of Director 84/07/13 SUNBER, J
  Niagara Mohauk Power Corp 2pp 25917 293 24X
  Fithe 50-410,84/07/13,8408030188
- --B408030192 IE Insp Rept 50-410/84-10 on 840521-24 No violations noted Major areas inspected evaluation of progress at site, site orientation, physical security plan & implementing procedures & security organization BAILEY,R J. DUNLAP,J M., KEIMIG,R R. Region 1. Office of Director 84/07/12 7pp 25917 295 24X Fiche 50-410,84/07/13,8408030188
- 8408060409 Summary of 840508 meeting w/util & S&W in Bethesda,MD reemergency preparedness
  HAUGHEY,M F Licensing Branch 2 84/07/20 Licensing Branch 2 12pp 25951 142 24% Fiche 50-410.84/07/20.8408060409
- B40B210447 Requests that updated emergency plan & procedures be withheld from public disclosure due to unlisted telephone numbers & communications radio frequencies provided, per Generic Ltr Bi-27
  MANGAN. C V Niagara Mohawk Power Corp 84/08/17 BCHWENCER, A Licensing Branch 2 ip 26177 199 24X Fiche 50-410,84/08/17,8408210447
- 8408310292 Forwards request for additinfore 840619 revs to physical security plan Response to comments should be made by amending plan within 30 days of receipt of ltr Encl withheld (ref 10CFR73 21)
  SCHWERCER, A Licensing Branch 2 84/08/17 BUNSER, J J Niagara Mohawk Power Corp 1p 26333 296 24X Fiche 50-410.84/08/17.8408310292
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8407070212 Amend 12 to FSAR W/840621 ltr MANGAN.C V Niagara Mohawk Power Corp 84/06/30 EISENHUT.D 0 Division of Licensing 1034pp 25446 001 24X Fiche 50-410.84/06/30.8407090212
- G Inspection reports, IE Bulletins & correspondence
- 840803018B Forwards IE Insp Rept 50-410/84-10 on 840521-24 No viglations noted
  JOYNER, J H Region 1, Office of Director 84/07/13 SUNSER, J Niagara Mohawk Pouer Corp 2pp 25917 293 24X
  Ficha 50-410.84/07/13.8408030188
- ~-8408030192 IE Insp Rept 50-410/84-10 on 840521-24 No violations noted-Major areas inspected evaluation of progress at site, site orientation, physical security plan & implementing procedures & security organization BAILEY, R J, DUNLAP, J M, KEIMIO, R R. Region 1, Office of Director 84/07/12 7pp 25917 295 24X Fiche 50-410,84/07/13, 8408030188

- B407250229 IE Info Notice 84-57, "Operating Experience to Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc. 119pp 25865-047 24X Fichs 50-000.84/07/27, 8407250229
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Past 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26068 001 24X Fichs 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60. "Fasilure of Air Purifysng Respirator Filters to Moet Efficiency Requirement " Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Poet 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 30-000,84/08/06,8408010337
- 8408240233 Forwards Insp Rept 50-410/84-07 on 840514-0615 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 84/08/06 H00TEN N G Niagara Mohauk Power Corp 2pp 26236 254 24X Ficha 50-410.84/08/06.8408240233
- ---8408240237 Notice of violation from insp on 840514-0615 \* Region 1, Office of Director 84/08/06 2pp 26236 256 24X Fiche 50-410,84/08/06,8408240233
- --8408240253 Insp Rept 50-410/84-09 on 840514-0415 Noncompliance noted inadequate corrective action for OC-identified deficiencies & failure to perform requisite NDE of electrical genetration welds
  GRAMM.R A . CHAUDHARY, S K . COLLINS, S J Region 1, Office of Director 84/08/03 13pp 26236 258 24X Fiche 50-410.84/08/06.84/08240233
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR
  Refueling Cavity " Svc list encl
  JURDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/08 Consolidated Edison Co of New
  York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- B408270234 Forwards Insp Regt 50-410/84-08 on 840430-0525 & notice of violation MARTIN, T Division of Engineering & Technical Programs 84/08/08 HDDTEN, B G Niagara Mohawk Power Corp 2pp 26258 056 24X Fiche 50-410,84/08/08
- --8408270237 Notice of violation from insp on 840514-25 \* Region 1, Office of Director 84/08/08 2pp 26258 058 24% fiche 50-410,84/08/08,8408270234
- ---8408270242 Insp Rept 50-410/84-08 on 840430-0525 Violations noted unacceptable radiographs & min weld thickness requirements KERCH, H W , HARRIS, R H , CAMPBELL, R M Region 1, Defice of Director 84/08/02 26pp 26258 060 24X Fiche 50-410,84/08/08,8408270234
- 8408070374 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " 8vc list encl GRACE.J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 128pp 26130 001 24X Fiche 50-000.84/08/10.840870374
- B408100007 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Byc list encl
  JURDAN,E L Division of Emergency Preparadness & Engineering
  Response (Post 830103) B4/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24% Fiche 50-000.84/08/13, 8408100009
- 8408100038 IE Info Notice 84-64. "BWR HPCI Initiation Seal-In & Indication " Syc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 073 24X Fichs 50-000.84/08/15.8408100038
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Syc list encl JGRDAN,E L D(vision of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000.84/08/16,8408100021
- 8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auriliary Feedwater Train " Svc list encl JORDAN, E. L. Division of Emergency Freparedness & Engineering Response (Post 830107) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates Svc list entl JORDAN,E L. Division of Emergency Preparedness & Engineering Rasponse (Post B30103) 84/08/17 Consolidated Edison Co. of New York, Inc. 122pp 26276 122 244 Fiche 50-000,84/08/17,8408140208
- B408310235 Provides add1 info to Item 4 of IE Bulletin B3-07 re apparently fraudulent products sold by Ray Miller. Inc Approved vendor list & suiveillance program reduce probability of receipt of fraudulent product MANGAN.C V Niagara Mohawk Power Corp B4/0B/17 STARDSTECKI.R Division of Project & Resident Ptograms 2pp 26320 328 24X Fiche 50-410.84/08/17.8408310235
- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York Inc 115pp 26329 008 24X Fiche 50-000.84/08/21.8408210142

#### 8 Reportable occurrences, LERs & related correspondence

- 840B100071 Final Deficiency Rept 55(e)-84-16 be std swing check valve in RCIC turbine exhaust Valves will be replaced w/special design lift check valve grior to preoperational testing MANGAN.C V Niagara Mohawk Power Corp 84/07/30 STAROSTECKI.R Division of Project & Resident Programs 2pp 25989 308 24X Fiche 50-410,84/07/30.840B100071
- 840B100118 Final deficiency rept re excessive wear on Pacific Air Products linear converters [Initially reported on 840213 Design of converters satisfactory for dampers Also reportable per Part 21 Not reportable per 10cFR50 55(e) MANGAN,C V Niagara Mohawk Power Corp 84/07/30 STAROSTECKI,R Division of Project & Resident Programs 2pp 25988 253 24X Fiche 50-410,84/07/30,840B100118
- 8408210437 Final deficiency rept re qualification of 40 mil 1,000-volt fire resistant control cable supplied by Kerite Initially reported on 830827 Use of control cable prohibited for safety-related circuits in primary containment MANDAN.C V Niagara Mohawk Power Corp 84/08/02 STAROSTECKI,R Division of Project & Resident Programs 2pp 26181 275 24X Fiche 50-410,84/08/02.8408210437
- 8408300365 Final Deficiency Rept (55(e)-84-24) re sizing of RMR sys safety valves Initially reported on 840706 Pressure control valve internals will be nodified Mod will be completed by 841203 MANGAN.C V Niagara Mohawk Power Corp 84/08/06 STAROSTECKI.R Division of Project & Resident Programs 2pp 26308 192 24X Fiche 50-410.84/08/06.8408300365
- B40B300345 Final Deficiency Rept (55(e)-B4-14) re power generation control complex separation Initially reported on B40323 StM will rework panel wiring Corrective actions expected to be completed by 841231 MANGAN.C V Niagara Nohawk Power Corp 84/08/07 STAROSTECKI,R Division of Project & Resident Programs 3pp 24308 347 24X Fithe 50-410.84/08/07.8408300345
- B40B300362 Final Deficiency Rept (55(e)-84-21) re svc life of relays in safety-related sys Initially reported on 840613 Replacement parts program will be developed to replace relays in interval based on svc life determined by GE & Amerace MANOAN.C V Niagara Mohauk Power Corp B4/08/10 STAROBTECKI.R Division of Project & Resident Programs 2pp 26308 214 24X Fiche 50-410,84/08/10.8408300362

## X Onsite Storage of Low Level Waste

B40B230237 Forwards certificate repollution control facilities for NRC signature per Internal Revenue Svc requirements Info re radwaste solidification & storage bldg, radioactive solid waste & spent fuel storage encl for approval MANCAN.C V Niagara Mohawk Power Corp 84/08/21 DENTON,H R Office of Nuclear Reactor Regulation. Director 7pp 26207 278 24X Fiche 30-220.84/08/21,8408230237

DOCKET 50-412 REAVER VALLEY POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

8408090497 Summary of 840717 meeting w/Westinghouse Owners Steam Ownerator Tube Rupture Subgroup in Sethesdai/ID re proposed steam generator tube rupture generic program List of attendees & viewgraphs encl
81NOH.8 K Licensing Granch 3 84/07/31 Licensing Branch 3 18pp. 25983 130 24X Fiche 50-000.84/07/31.8408090497

- B408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders or CPs rc availability of Suppl 1 to NUREC-0933. "Prioritization of Generic Safety Issues" Svc list encl
  EISENHUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26189 238 24x
  Fiche 50-000.84/08/06.8408070110
- B408090317 Forwards monthly status rept re plant-specific backfitting activaties for operating reactors & license applicants for Jul 1984
  TREMBLAY,P P Operating Reactors Assessment Branch B4/08/06
  HOLAHAN,G M Operating Reactors Assessment Branch 13pp 25991 350 24X Fiche 50-000 84/08/06.8408090317
- B40B230373 Notification or 840816 meeting w/util in Bethesda.MD to discuss seismology open items LEY.M Licensing Branch 3 84/08/06 KNIGHTDN.G W Licensing Branch 3 4pp 26230 344 24X Fiche 50-412.84/08/06,8408230373
- B40B210437 Forwards State of PA Dept of Environ Resources permits for facility effective Jul 1984 & various permits issued for const activities Withree oversize drawings Aperture cards in PDR MODLEVER, E J Duquesne Light Co 84/08/13 KNIGHTON, G W Licensing Branch 3 154pp 26148 026 24X Fiche 50-412,84/08/13,8408210437
- B408230377 Forwards request for add1 info re internally generated missile protection inside & outside containment, per 830518 application for OL Info requested within 30 days of ltr receipt KNIOHTON, G W Licensing Branch 3 84/08/14 WOOLEVER, E J BUQUESNE Light Co 4pp 26230 338 24X Fiche 50-412,84/08/14,8408/230377
- 8408200275 Generic Ltr 84-20 to all licenses of operating reactors & applicants for GLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
  EISENHUT.D 6 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 262/6 244 24X
  Fiche 50-000.84/08/20.8408200275
- 8408230246 Recommends that NRC formally submit specifically defined concerns in order to receive equally defined responses & to facilitate productive neetings Lack of communication cited as cause for NRC dissatisfaction w/FSAR Amends & & 7 WOOLEVER,E J Duquesne Light Co 84/08/20 KNIGHTON, 0 W Licensing Branch 3 3pp 26207 285 24x Fiche 50-412.84/08/20, 8408230246
- 8408270336 Forwards agenda for 840830 meeting at site w/NRR. IE & S&W Engineering Co re electrical separation & Rev 2 to Reg Guide 1 75 implementation program HOOLEVER.E J Duquesne Light Co 84/08/24 KNIGHTON, 0 W Licensing Branch 3 2pp 24289 234 24X Fiche 50-412.84/08/24. 8408270336
- E. NRC Safety Evaluation Report (SER), supply & correspondence
- B408020011 Forwards responses to draft SER Outstanding Issues 65,72,115 & 120 re IC Bulletins 80-06 & 79-27,regional climatology & containment vacuum sys exhausts, respectively WOOLEVER,E J Duquesne Light Co 84/07/27 KNIGHTON, C W Licensing Branch 3 12pp 25883 088 24X Fiche 30-412,84/07/27,840820011
- 8408020019 Forwards responses to outstanding draft SER Issues 65,72, 115 & 120 Ltr originally issued on 840727 w/o date or 1tr numbers MODLEVER, E J Duquesne Light Co 84/07/30 KNIGHTON, 6 H Licensing Dranch 3 12pp 25883 136 24X Fiche 30-412,84/07/30,8408020019
- B40B070432 Forwards responses to Ceotechnical Engineering Section draft BER Open Items 180 & 181 re soils effective strength parameters & accuracy of SIDES program, respectively WOOLEVER,E J Duquesne Light Co 84/08/01 KNIGHTON, 8 W Licensing Branch 3 4pp 20939 217 24% Fiche 50-412,84/08/01, B408070432
- B40B130005 Forwards responses to Geotochnical Engineering Section draft SER Open Item 177 re settlement monitoring program & FSAR Section 2.5 4 13 re surface & subsurface instrumentation HODLEVER,E J Duquesne Light Co 84/08/08 KNIGHTON, G W Licensing Branch 3 7pp 26010 049 24X Fiche 50-412,84/08/08,8408130005

- B40Bl30J12 Forwards response to draft SER Open Item 150, "Seismic & Dynamic Qualification" & Open Item 151, "Fump & Valve Operability Assurance"

  WD0LEVER F J Duquesne Light Co B1/08/08 DEHTCH, H R Office Nuclear Reactor Regulation, Director MNIGHTON G W Licensing Dranch 3 App 26010 118 C4X Fich, 50-412,84/08/08 B408130312 Office of
- B408140088 Forwards addl info on draft SER Dutstanding Issue 36 on TMI Item II K 3 12 Issue 58 to undotected failure of on-line ESF relays & Issue 77 on control sys failures caused by relays & lisue 77 on control sys fallures caused by malfunction of instrument line WDQLEVER,E ) Duquesne Light Co d1/08/09 KNIGHTON,O W Licensing Branch 3 Spp 24045 354 24% Fiche 50-412,84/08/09,8408140088
- B40B140127 Forwards responses to draft Matls Engineering Branch SER Open Item 196 re weld cladding of ferritic steel components & Confirmatory Item 22 re RCPB components of austernitic
  - ### WDQLEVER.E J Duquesne Light to 84/08/10 KNIGHTON.G W Licensing Branch 3 3pp -26045 359 24% Fiche 50-412-84/08/10. 8408140127
- B40B150199 Forwards responses to draft SER Open Items 103,108-111. 15B-143 & 200-203, per Reactor Sys Branch B40530 & 0608 Itrs WIDLEVER.E J Duquesne Light Co 84/08/10 KNIGHTON, 9 W Liternsing Branch 3 9pp 26066 217 24X Fiche 50-412,84/08/10, B40B150199
- 8408160333 Forwards responses to Parts 2 / 3 of Accident Evaluation Branch draft SER Open Them 53 re control room habitability WOOLEVER.E J Duquesne Light Co 84/08/13 KNIGHION.G W Likensing Branch 3 3pp 26085 338 24X Fiche 50-412.84/08/13, 8408160333
- B40B160399 Forwards responses to Auxiliary Sys Branch draft SER Open Teems 125:127-130,133,135,139 & 148 WDDLEVER,E J Duquesno Light Co 84/08/13 KNIGHIGN.9 W Licensing Branch 3 7pp 26092 136 24X Ficho 50-412,84/08/13. 840B160399
- 8408230327 Forwards current list of putstanding & confirmatory issues identified in Tables 1 2 / 1 3 of draft SER Requests any differing opinion of status described on attached list MODLEVER.E J Duquesne Light Co 84/08/17 KNIGHTON.G & WDDLEVERIE J Duquesne tight Co 84/ Licensing Branch 3 10pp 24204 000 8408290329 24% Fiche 50-412, 84/08/17,
- 8408270165 Forwards responses to draft GER Dutstanding Issues 3 & 165. list of emergency plan changes % instructions & evacuation maps for public Responses to FSAR questions will be incorporated in future arend MODLEVER.E J Duquesne Light to 84/08/21 KMIGHTON, 6 W Licensing Branch 3 17pp 26242 186 24X Fiche 50-412,84/08/21,6408270165
- 8408280200 Forwards "ASME Code Haseline Document" re NRC Unresolved Item 83-07-02 % draft SER Open Item 42, presented to NRC at 840726 meeting in Bethesda. MD Document will be referenced in sections of future FSAR amend WOOLEVER, E. J. Duquesne Light Co. 84/08/21 KNIGHTON, G. W. Licensing Dranch 3. 2pp. 26275 248 24% Fishe 50-412,84/08/21,84/08/280200
- --B408280203 "ASME Code Baseline Document" BLAKE, R. CHAMBERLAIN, D. FIGRENTA, A. J. Engineering Corp. 20VM-179 B4/08/21 Fiche 50-412,84/08/21,8408280200 Stone & Webster 76pp 26275 250 24x
- B408270141 Forwards responses to Containment Bys Branch draft SER Open Items 166-171 All draft open items addressed WOOLEVER.E J Duquesne Light Co 84/08/22 KNIGHTON.O W Licensing Branch 3 17pp 26243 345 24X Fiche 50-412.84/08/22, B408270141
- --8408270147 "Experimental Evaluation of Reactor Containment Sump PENNING, B J , HECKER, C C Alden Research Laboratory 03/08/3 θ2ρρ 26244 001 24% Γιche 50-412.84/08/22,8408270141
- 8408290222 Forwards response to Geotechnical Engineering Section draft SER Open Item 179 re soil damping values Variations of soil properties & dampings discussed WOOLEVER, E. J. Duquesne Light Co. 84/08/24 KNIGHTON, G. W. Litensing Branch 3. 2pp. 26290 344 24X Fiche 50-412,84/08/24, 8408290222

- F Security, medical, emergency & fire protection plans
- 8408010151 Forwards "Procedures Generation Package For Beaver Valley Fouer Station, Unit 2 ' in response to Generic Ltr 82-33, describing methods for developing function oriented emergency operating procedures.psr NUREG-0737, Item II C 1 MODLEVER: E J puquesne Light to 84/07/26 EISENHUT.D G Division of Licensing 3pp 25855 184 244 Fiche 50-412.84/07/26, gangologis. of Licensing 8408010154
- --8409010156 "Procedures Generation Package For Beaver Valley Power Station, Unit 2" CLEMENTS R H , JUMES D T Dequeshe Light Co 84/08/01 116pp 25855 187 21X Fiche 50-412,84/07/24.8408010154
- 8408020011 Forwards responses to draft SER Outstanding Issues A5.72.115 & 120 re IE Bulletins 80-04 & 79-27.regional climatology & constainment vacoum siys exhaust respectively MODLEVER, E J Duquesne Light Co 84/07/27 MMIGHTON, 6 W Licensing Branch 3 12pp 25883 088 24X Fiche 50-412,84/07/27. 8408020011
- B40B070414 Forwards nonproprietary Rev O to WCAP-10170, "Key Safety Parameter Selection " & pioprietary Rev I to WCAP-10170; "Yey Safety Parameter Selection " (Generic Ltr 82-33) Proprietary rept withheld (ref 10CFR2 790) WOOLEVER,E J Duquesne Light Co 84/08/01 EISENHUT,D G Division of Litensing 4pp 2593B 001 249 Ficho 50-412,84/08/01.
- --84080/0419 Nonproprietary Rev O to App C to Suppl 1 to "Key Safety Parameter Selection for Beaver Valley,Unit 2 Safety Parameter Display Sys (SPDS) " MORLEY,R C Westinghouse Electric Corp WCAP-10170 APC S1 RO 84/07/30 11pp 25933 005 24% Fiche 50-412.84/08/01.8408070414
- 8408270165 Forwards responses to draft SER Outstanding Issues 3 & 165, list of emergency plan changes & instructions & evacuation maps for public Responses to FBAR questions will be incorporated in future amend WOOLEVER.E J Duquesne Light Co 84/08/21 KNIGHTON, 0 W Licensing Branch 3 19pp 26242 186 24X Fiche 50-412,84/08/21, nearly 2015
- 8408310208 Forwards Anend 2 to 'Fire Protection Evaluation Rept for Beaver Valley Power Station, Unit 2"

  ### MODLEVER, E. J. Duquesne Light to 84/08/27 KNIGHTON, 6 W
  Licensing Branch 3 2pp 26324 206 24X Fiche 50-412.84/08/27, 6408310208
- ---8408310213 Amend 2 to 'Fire Protection Evaluation Rept for Beaver Valley Power Station Unit 2 ' \* Stone & Webster Engineering Colp 84/03/31 209pp 26324 2 24X Fiche 30-412,84/03/2/,8408310208 84/03/31 209pp 26324 20B
- P Operating license stage documents & correspondence
- B40B270071 Forward» responses to Action Items 1,2,3,4,6 & 7, per environ site visit meeting summary ltr WDULLVER.E J Duquesne Light Co B4/08/21 KNIGHTON, 9 W Licensing Branch 3 17pp 26247 150 24X Fiche 50-412,84/08/21,840B270071
- @ Inspection reports. IE Bulletins & correspondence
- 8408240275 Informs that addl info re pipe-to-fitting wolds requested at B40522 meeting re Violation 82-01-01 will be provided by B40706 Clarification ef Item 5 provided WOOLEVER, E J Diquesne Light Co 84/06/27 STAROSTECKI, R Division of Project & Resident Programs 3pp 26223 187 24X Fiche 50-412, 84/06/27, 8408240275
- 8407250229 IE Info Notice 84-57. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JOROAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24% Ficha 50-000,84/07/27,8407250229
- 8408020011 Forwards responses to draft SER Outstanding Issues 65,72,115 & 120 re IE Bulletins 80-06 & 79-27, regional climatology & containment vacuum sys exhaust respectively MODLEVER,E J Duquesne Light Co. 84/07/27 KNIGHTON, 0, W Licensing Branch 3 12pp 25883 088 24X Fiche 50-412,84/07/27, 8408020011
- 8408070393 Ack receipt of 840625 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-412/84-04 MARTIN,T T Division of Engineering & Technical Programs 84/08/0 WODLEVERS J Deques tight Co 2pp 25744 199 24X Fiche 30-412.84/08/01.8408070353 B4/08/01

- --8408070355 Responds to NRC 840531 ltr re violations noted in IE Insp. Rept 50-412/84-04 Corrective actions completion of electrical encl/barrier scheduled for Fourth Quarter 1985 WOOLEVER.E. J. Duquesne Light Co. 84/06/25 STAROSTECKI.R. Division of Project & Resident Programs App. 25744 201 24X Fiche 50-412,84/08/01.8408070353
- 8408010333 [E Info Notice 84-99, Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26068 001 24X Fiche 50-000.84/08/06.8408010333
- 8408010337 [E Info Notice 84-60, "Failure of Air Pullifying Respirator Filters to Meet Efficiency Requirement "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/04 Consolidated Edison Co of Neu York, Inc 123pp 26067 158 24% Fiche 50-000.84/08/06.8408010337
- 8408370120 IE Info Notice 84-61, 'Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN.E t. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Ficha 50-000.84/08/08.8408070120
- 8408070374 IE Info Notice 84-42. "Therapy Misadministrations to Pattents Undergoing Co-60 Teletherapy Treatments " Syc list encl ORACE.J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York. Inc 125p 26130 001 24% Fiche 30-000.84/08/10.8408070376
- 8408100009 IE Info Notice 84-63, "Defective RKR Replacement Paping "
  Svc list encl
  JDROAN.E L Division of Emergency Preparedness & Engineering
  Response (Post 83010'3) 84/08/13 Consolidated Edison Co of New
  York Inc 119pp 26197 218 24X Fiche 50-000.84/08/13,8408100009
- 840810003B IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication "Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc. 104pp 26198 093 24% Fiche 50-000,84/08/15,8408100038
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORBAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc (18pp 26198 001 24X Fiche 50-000,84/08/16,8408100021
- 8408100055 IE Info Notice B4-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JURDANLE L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/17 Consolidated Edison Co of New York Inc 120pp 26276 001 24X Fiche 50-000.84/08/17.8408100055
  - DB140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing H/
    digh Failure Rates " Svc list encl
    JORDAN, E L. Division of Emergency Preparedness & Engineering
    tesponse (Post 830103) 84/08/17 Consolidated Edison Co of New
    fort, Inc 122pp 26274 122 24X Fiche S0-000,84/08/17,8408140208
  - )8210142 IE Info Notice 84-68, "Potential Deficiency in Improperly lated Field Wiring to Solonoid Valves "Svc list enc)
    JORDAN, E L Division of Emergency Preparedness & Engineering lesponse (Post 830103) 84/08/21 Consolidated Edison Co of New fork, Inc 115pp 26327 008 24X Fiche 50-000,84/08/21,8408210142
  - )8270335 Discusses 840612 meeting w/util re encl BALP Repts 10-334/84-13 & 50-412/84-06 Overelt assessment of erformance for Unit 1 acceptable Lack of mgt control for Init 2 identified List of meeting attendess encl TURLEY, T E Region 1. Office of Director 84/08/21 CAREY, J J Juquesne Light Co 6pp 26244 205 24X Fiche 50-334, 84/08/21, 8408270335
- -8408270341 Summarizes discussion at 840612 meeting re SALP Repts 50-334/84-13 & 50-412/84-06 Constructability review group for reviewing engineering output & organizational changes established CAREV.J J Duquesne Light Co 84/06/29 STAROBTECKI.R Division of Project & Resident Programs 22pp 26244 285 24X Fiche 30-334.84/08/21,8408270335

- S Reportable occurrences, LFRs / related correspondence
- 8408040259 Interin Significant Deficiency Rept 81-05 re removed, dismantled or partially dismantled pipe supports Rework control program under development to assure QC insp status reflects most recent changes Addl rept expected by 840831 MODLEVER.E J Duquesne Light Co 84/07/12 MURLEY.T E Region 1, Office of Director 3pp 25935 153 24X Fiche 50-412.84/07/12, 8408040259
- 8408210476 Final Deficiency Rept 84-04 re potential for undetectable failure of Westinghouse solid state protection sys Hardware changes described in encl Westinghouse technical bulletin will be incorporated prior to 840701 WOLLEVER.E J Duquesne Light Co 84708/13 MURLEY.T E Region 1 Office of Director 10pp 26181 127 24X Fiche 50-412.84/08/13.8408210476
- DOCKET 50-413 CATAMBA NUCLEAR STATION, UNIT (
  A. Application/construction stage documents / correspondence
- 8408310428 Forwards summary of NRC 840418 meeting w/util in Region II ofc & 840419 meeting at facility re followup to 840313 meeting concerning welding irregularity findings LEWIS.R C Region 2. Office of Director 84/05/01 TUCKER.H B Dute Power Co 5pp 26335 029 24X Fiche 50-413.84/05/01.
- 8408300440 Confirms 840517 arrangements between JU Hampton, VL Brownlee & NA Rutherford re 840524 mgt meeting w/util in Region II off to discuss readiness for operation of facility Proposed agenda encl
  LEWIS.R C Region 2. Office of Director 84/05/22 TUCKER, H B
  Duke Power Co 3pp 26314 244 24X Fiche 50-413, 84/05/22.
  8408300440
- 8408060072 Requests exemption from GDC 4 re fuel load & precritical testing activities Exemption would allow completion of RHR pump/motor analyses & seismic qualification of electrical isolation syspion to initial criticality
  THIES.A C Duke Power Co 84/D7/11 DENTON, H R Office of Nuclear Resactor Regulation, Director 3pp 25922 012 24X
  Fiche 50-413.84/07/11.8408060072
- E NRC Safety Evaluation Report (SER), supply & correspondence
- B40B0B0275 Forwards proprietary & nonproprietary "Westinghouse Setpoint Methodology for Protection Sys.Catawba Station," in response to Section 7 3 24 of SER Application for withholding proprietary rept encl TUCKER.H B Duke Power Co B4/07/30 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAN.E G Licensing Branch 4 2pp 25944 228 24% Fiche 50-413.84/07/30.8408080275
- --8408080280 Requests withholding of proprietary "Westinghouse Setpoint Methodology for Protection Sys.Catawba Station" (ref 10CR2 790) WIESEMANN.R A Westinghouse Electric Corp. 84/07/20 DENTON.H Office of Nuclear Reactor Regulation. Director 8pp. 23964 230 24X Fishe 50-413.84/07/30.8408080275
- --B408089284 Nonproprietary "Westinghouse Setpoint Methodology for Protection Sys, Catawba Station " Two oversize tables encl Aperture cards available in PDR JANSEN, R L , TULETY, C R Westinghouse Electric Corp 84/06/30 71pp 25964 238 24X Fiche 50-413,84/07/30,8408080275
- 8408070009 SAFETY EVALUATION REPORT RELATED TO THE DPERATION OF CATANDA NUCLEAR STATION, UNITS 1 AND 2 DOCKET Nos 50-413 And 50-414 (Duke Power Company, et al) # Division of Licensing NURGE-0954 S03 84/07/31 140pp Available at NRC \$5 50 25954 334 24% Fiche 50-413,84/07/31.
- F Security, medical, emergency & fire protection plans
- B40B30035B Forwards FEMA "Exercise Rept.Catawba Nuclear Station, B40215-16" DANCE,H C Region 2, Office of Director 84/06/25 TUCKER,H B Duke Power Co Ip 26308 264 24% Fiche 50-413,84/06/25, B40B30035B
- 8408070487 Forwards Rev 1 to storage & in-transit security plan for SNM of low strategic significance Rev withheld (ref 10CFR73 21)
  TUCKER.H B Duke Power Co 84/07/02 O'REILLY, J P Region 2, Office of Director ip 25941 193 244 Fiche 50-413,84/07/02,8408070487

- B408370367 Forwards Insp Repts 53-413/84-77 : 50-414/84-33 on B40625-29 No deviations or violations inted DANCE H.C. Division of Project : Resident Programs 84/07/17 TUCKER.H B. Duke Fouer Co. 2pp 2625/227 24% Fiche 50 413/84/07/17-8408270367
- --84082/0371 Insp Repts 50-413/84-77 % 50-414/84-33 on 840625-29 No violations or deviations noted Major areas inspected fire protection WISEMAN, G. R., CONLON, T. E. Region 2, Office of Director 84/07/13 600 26257 229 24X Fiche 50-413,84/07/17,8408270367
- 8408090042 Forwards States of NC / SC responses to regional assistance committee findings on offsite radiological emergency response preparedness & exercise on 840215-16 State & local emergency plans adequate RRIMM.R W Federal Emergency Management Agency 84/07/27 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 8pp 25992 324 24X Fiche 50-413,84/07/27,8409809042
- B40B020050 Motion for changes to transcript of emergency planning hearing to correct matternors ASLB requested to issue order directing that evidentiary record be amended incorporating enclichanges MCGARRY. JM Duie Power Co. DSB 702 84/07/30 Atomic Safety and Licensing Board Panel. ip. 25892 271 24% Fiche 50-413,84/07/30,8408020060
- 840B090007 Forwards safeguards implementation ltrs Ltrs withheld fref 10CFR73 21) TUCKER.H B Duke Power Co 84/07/30 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 25973 005 24X Fiche 50-413,84/07/30.840B090
- 8408070322 Responds to NRC concern re false opening of MSIVs or steam generator PDRVs for Steam Generators A, B & D due to fire Mod will be implemented on Unit 1 prior to entry into Mode 3
  TUCKER, H B Duke Power Co 84/08/02 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 1p 25945 129 24% Fiche 50-413,84/08/02,8408070322
- B40B070331 Advises that sufficient manpower available ensite to perform required manual operations in timely manner to achieve safe hot standby conditions u/o reliance on fire brigade members, per NRC request during App R review TUCKER, H B Duke Power Co 84/08/03 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Litensing Branch 4 ip 25944 149 244 Fiche 50-413, 84/08/03,8408070351
- B408280972 forwards public version of revised emergoncy plan implementing procedures, including HP/O/B/1009/07 re in-plant particulate & rodine monitoring under accident conditions % HP/O/B/1009/05 te personnel monitoring TUCKER.H B Duke Fouer Co 84/08/06 Record Services Branch (Document Control Desk) 2gp 26293 049 24X Fiche 50-413. B4/08/06. B408280372
- --8408280377 Public version of revised emergency plan implementing procedures, including HP/O/B/1009707 re in-plant particulate & indine monitoring under accident conditions % HP/O/B/1009705 re personnel monitoring W/Fulton 840821 memo TUCKER, H B Duke Power Co 84/08/06 74pp 26293 051 24X Fishe 50-413,84/08/06,8408280372
- 840830035/ Confirms 849804 telcon w/JP O'Reilly re 840815 meeting in Region II ofc to discuss design & operation of standby shutdown facility concerning App R to 100FR30, five protection & 100FR30, physical protection Appnda encl LEWIS.R C Region 2. Office of Director 84/08/08 TUCKER.H B Duke Power Co 3pp 26314 222 24X Fiche 50-000,84/08/08.
- B408300014 Forwards public version of Rev 13 to crisis mgt plan & revised emergency plan implementing procedures
  TUCKER, H B Duke Power Co 84/08/10 Record Services Branch (Document Control Desk) 21pp 26332 353 24X
  Fiche 50-000,84/08/10,8408300014
- --B408J00021 Public version of Rev 13 to "Crisis Mgt Plan for Nuclear Stations" \* Duke Power Co B4/08/15 30pp 26333 010 24X Fiche 50-000,84/08/10,8408300014
- --8408300028 Public version of revised crisis mgt plan implementing procedures, including 5 3 i re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group W/Felton 840833 nemo
  \* Duke Power Co 84/08/15 170pp 26333 040 24X
  Fiche 50-000,84/08/10,8408300014

- 8408290041 Board Notification 84-151 forwards FEMA interim findings on offsite radiological emergency response preparedness; State of SC 840424 It. 'State of NC 840522 Itm NDVAK.T M Assistant Director for Licensing 84/08/29 MARGULIES,M , LAZD,R , HOOPER,F Atomic Safety and Licensing Board Panel 4pp 26322 IIS 24X Fiche 50-413,84/08/29,8408290041
- --8406140090 Requests add1 info 5 supplemental interim findings restatus of offsite radiological plans % preparedness Statement indicating adequacy of state & local emergency plans should be provided by 840515

  JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84705/07 KRIMM,R W Federal Emergency Management Agency 1p 26322 127 24X Fiche 50-413.84/08/29.

#### G Adjudicatory correspondence

- 8408150524 Forwards applicant Exhibits EP 18-20.intervenor Exhibits EP 42.43.44.45.46.47.50.48 t 49 t NRC Exhibit EP 5 re emergency planning Related correspondence EYSTER.R Tayloe Associates 84/05/31 PLEASANT.E Administrative t Logistical Support Branch 1p 26105 363 24x Fiche 50-413.84/05/31.8408150524
- 8408160109 Forwards intervenor Exhibits 51-54 & 19,NRC staff Exhibit 3A & applicant Exhibits 21A & 21 Related correspondence RILEY, 5 L. Tayloe Associates 84/06/15 PLEASANT, E Administrative & Logistical Support Branch 1p 26126 326 24X Fiche 50-413,84/06/15,8408160109
- B40B0102ti Responds to Judgo Kelley B40716 request for applicant B40222 responses to NRC questions on emergency diesel generators W/o encis Releted correspondence J0HNBON.0 E Hearing Branch 4 DSB 678 84/07/27 KELLY, J L , PURDOM, P W , FOSTER, R F A tomic Safety and Licensing Board Panel ip 25856 052 24X Fiche 50-413,84/07/27,840B010211
- 840B020062 Forwards Ofc of Investigation Rept 2-83-038, "Catawba Nuclear Station Alleged Harassment & Intimidation of GC Welding Inspectors" KELLEY, J L Atomic Safety and Licensing Board Panel DSB 693 B4/07/27 Diffice of the Executive Legal Director ip 25898 201 24X Fichs 50-413,84707/27,840B020062
- --8408029068 Investigation Rept 2-83-038, "Duke Power Co Catawba Nuclear Station Harassment > Intimidation of GC Welding Inspectors " WILLIAMSON E L Office of Investigation 64/07/11 808pp 202 24x Fiche 50-413,84/07/27.8408020062
- 8408070443 Joint proposed findings of fact & conclusions of law in form of partial initial decision re emergency planning contentions Certificate of Svc encl QUILD: R Palmetto Alliance GUILD: R Quild: R GUILD: R Carnlina Environmental Study Group DSB 776 84/07/27 195pp 25943 206 24X Fiche 50-413,84/07/27,8408070443
- 840BD20060 Motion for changes to transcript of emergency planning hearing to correct mati errors ASLB requested to issue order directing that evidentiary record be amended incorporating encl changes MCGARY.J M Bishop, Liberman, Cook, Purcell & Reynolds DEB 702 B4/07/30 Atomic Safety and Licensing Board Panel 16 25892 271 24x Fiche 50-413.84/07/30, 840B020060
- --8408020066 Errata to transcript of 840501-0608 emergency planning hearing, correcting math errors Certificate of 8vc encl \* Duke Power Co 84/07/30 23pp 25892 272 24% Fiche 50-413,84/07/30,8408020060
- 8408020013 Order extending time until 840904 for Commission to act to rayiou Director's Decision DD-84-14 Served on 840801 CHILP'S J Diffice of the Secretary of the Commission DBB 472 84707/31 Commissioners 1p 25883 115 24X Fiche 50-413, 84/07/31.8408020013
- 8408060035 Response to Palmetto Alliance & Carolina Environ Study Group seven interrogetories for which ASLB granted motion to compel Certificate of Svc encl Related correspondence CARR.A V Duke Pouer Co 098 746 84/08/01
- 8408200548 Expresses opinion that ASLB 840720 order imposes burdens on Palmette Alliance & Carolina Environ Study Group solely as consequence of util & staff tardiness in discovery of safety problems w/diesel generators Related correspondence QUILD, R Quild, R GUILD, R Palmette Alliance GUILD, R Carolina Environmental Study Group DSB 159 84/08/01 KELLEY, J. L, FOSTER, R. F., PURDOM-P M. Atomic Safety and Licensing Board Panel 2pp 26137 028 24X Fiche 50-413, 84/08/01.8408200549

- 8408070422 Summariics BROSD, agreement is Intropertient on to serve diesel generator technical calcultion rept Related correspondence
  - correspondence
    JOHNBON, G. E. Hearing Diar F. 4. DSB 912 F1708 03 KELLEY, J. L.
    Atomic Safety and Licensing Buard Panel 1p. a4942 025 24y
    Fiche 50-413.84708703.8408070422
- B40B0B0339 Forwards util 'Investigation or Issues Raised by NRC in Insp Repts 50-113/B4-31 & 50-114/B1-17, in Lesponse to NRC concerns re-allegations or Uelder B Related correspondence CARR.A V Duke Power Co DGB 826-84/08/03 #ELLY, J L . FOSIER.R F , PURDDA P Atomic Sufety and Cicensing Board Panel 120pp 25963-311 24x Fichs 50-113-84/08-03-8408080339
- B408090191 Forwards technical evaluation right, per ASLB 840720 order astablishing schedule leading to 840827 hearing on diesel generator contention H/o cncl Related correspondence JOHNSON, G.E. Hearing Branch 4 DSB 863 84708707 RELLEY, J.L., PURDOM, P.W., FOSTER, R.F. Atomic Safety and Licensing Board Panel 1500p 26130 189 244 Fiche 50-413.84768, 07,8408090191
- 8408130270 Proposed findings of Fact ? conclusions of law in form of supplemental partial initial decision on emergency planning Certificate of Svc enci
  MCGURREN, H. J. Hearing Branch 1 JUHNSTVI, G. E. Hearing Branch 4
  DSB 910 84/08/09 149pp 26009 001 214 Fiche 50-413.84/08/08. 8408130270
- 8408140103 Supplemental response to joint interrogatories & requests to produce documents on dissel generator contentions & to Carolina Environ Study Group interrogatories Prof qualifications encl Related correspondence CARR.A V Duke Pauer Co. D58 957 84/08/10 Palmetto Alliance 17pp 26048 334 24% Fiche S0-413.84/08/10.8408140103
- --B408140110 Forwards interrogatories to Palmetto Alliance & Carolina Environ Study Group re identity of eigert witness on dissel genp, ator problems CARR, A V Dute Power Co 84/08/10 KELLEY, J L , PURDON, P W , FOSTER, R F , Moonic Safety and Licensing Board Panel 1p 26048 351 24% Fichy 50-413 84/08/10.8408140103
- --8408140115 Interrogatories re identification qualifications & role of expert on diesel generator contention Certificate of Sic antl Related correspondence CARR. A V Duke Power Co. 84'08/10 Palmetto Alliance 7pp 26048 352 24X Fiche 50-113,84/08/10.6408140103
- 8408160121 Forwards Attachment A to Section VII. "Repair of Brill Holes." of 810803 transmittal Corrections to errors listed Related correspondence
  CARR.A V Duke Power Co DSB 067 84/08/13 KELLEY.J L ,
  FOSTER.R F , PURDOM.R Atomic Safety and Licensing Board Panel
  4pp 26083 180 24% Fiche 50-413.84/08/13.8408160121
- 840820048! Forwards SER re reliability of diesel generators Related correspondence
  JOHNSON, G E Hearing Branch 4 DSB 175 84/08/14 GUILD, R
  Palmette Alliance RILEY, J L Carelina Environmental Study (
  11pp 26136 307 24% Fiche 50-413.84/08/14.840820048)
- OS20050B Forwards SER re reliability of diesel generators Technical evaluation rept, which forms part of SER, previously forwarded W/o encl Related correspondence JOHNSON, G E Hearing Branch 4 DSB 176 04/08/14 KELLY, J L , FOSTER, R F , PURDOM, P N Atomic Safety and Licensing Board Panel ip 26136 360 24% Fiche 50-413,84/08/14,8408200508
- #08200499 Forwards addt info re NRC witnesses on intervenor disselgenerator contention & two addl comments Related correspondence
  UDHNSUN G E Hearing Branch 4 DS8 172 84/08/15 QUILD, R
  Palmetto Alliance RIEEY, J. Carolina Environmental Study Graup
  ip 26137 001 24X Fishe 50-413,84/08/15,8408200499
- -8408200511 Supplemental responses to Palmetto Alliance & Carolina Environ Study Group 840318 general interrogatories Certificate of Syc encl Related correspondence JOHNSON, G E Hearing Branch 4 84/08/15 Palmetto Alliance 15pp 26137 002 24x Fiche 50-413,84/08/15,8408200459
- 8408310203 Expresses disagreement w/conclusions expressed in util.ENWL & NRC staff repts re reliability of TDI emergency diesel generators Pattern of deficiencies exists which precludes generators access of percentages exists unjust precisions findings Related correspondence GUILD.R Guild, R GUILD.R Palmetto Alliance GUILD.R Carol Environmental Study Group DSG 430 64/08/16 MELLEY, J L. PURDOM, P W. FOSTER.R F Atomic Safety and Licensing Board Panel 193pp 26317 228 E4X Fiche 50-413.84/08/16,8408310205

- 84082/0116 Discusses intervenets intention to rely on prefiled testimony as statement of detailed technical position per AULB 810/20 order \* 840810 teleon P. Lausecky odded to staff ASLE BYO'CO orner : Regard thron P. Courtery added to stark panel Rilated correspondence
  JOHNSON, 6 E Hearing Branch 4 DSB 303 84/08/17 GUILD.R
  Palnetto Millance RILEY, 1 Carolina Environmental Study Group
  App 26247 340 23X fiche 50-413/84/08/17,8408270119
- 8408220347 Reply to proposed findings of fact conclusions of law of Palmetto Alliance.Carolina Environ Study Group \* NRC Certificate of Sv. encl MCGARRY, I M Bishop, Liberman, Cook, Purcell & Reynolds DSD 188 84/08/20 Atomic Safety and Licensing Board Panel 125pp 26192 001 24% Fiche 50-413, assets and page 125pp 26192 001 24% Fiche 50-413, D4/08/20, 8108/20347
- B408270109 Forwards SER re TDI Diesel Generator Dwneis Group program plan W/o entl Related correspondence JOHNBURG E Hearing Branch 4 DBB 310 D4/08/20 KELLEY, J L . PURDOM, P W . FOSTER, R F Atomic Safety and Licensing Board Panel 1p 26247 325 24% Fiche 50-413.84/08/20.8408270109
- 8408230280 Order dismissing diesel generator contention & canceling 840827 cyclentiary hearing Intervenor submission % staff & applicant testimony accepted as proof of positions had contention gone to hearing Served on 840822 KELEV.J L Atomic Safety and Licensing Board Panel D58 225 84708722 Palmetto Alliance 2pp 20205 360 24x Fiche 50-413.84708722 8408230280
- 8408280455 Forwards License NPF-24 \* SSER 3, including pertinent FR notice, envison protection plan, Amend I to Indomnity Agreement B-100 & antitrust conditions W/o encls Related correspondence
  JOHNBOR, G.E. Hearing Branch 4 B9B 341 B4/0B/24 ROSENTHAL, A.S.,
  MOUREL S. UILBER, H.A. Atomic Safety and Licensing Appeal Panel
  2pp 26280 334 J4x Fiche 50-413, 84/08/24, 8408280495
- I Financial information
- 9408240224 Forwards Dule Power Co . North Carolina Municipal Power Agency i 1983 annual repts
  TUCKER, H B Duke Power Co 84/08/16 DENTON, H R Office of
  Nuclear Reactor Regulation, Director ADENSAM E G Licensing Branch
  4 2pp 76237 137 24% Fiche 50-000, 84/08/16, 8408240224
- --B408240239 "1983 Annual Rept "
  CLAY. G W , SHAW R W North Carolina Municipal Power Agencies
  83/12/31 27pp 26237 137 21% Fiche 50-000.84/08/16.8408240224
- --8408240242 '1983 Annual Rept ' LCE.W 5 , BODIH.D W Duke Power Co 83/12/31 47pp 26237 167 24% Fiche 50-000,84/08/16,8408240P24
- J Insurance & Indennity information
- 8408060218 Unexpected Amend 1 to Indemnity Agreement B-100 SALTZMAN.J Assistant Director for State 7 ticensee Relations 84/07/04 2pp 29950 253 24% Fiche 50-413,84/07/06,8408060218
- 8408130164 Forwards License NPF-24, notice of issuance, Amend 1 to Indemnity Agreement 8-100, SSER 3 t environ protection plan (nonreducing scal) W/o SSER 3 t environ protection plan EISENHUT. D G Division of Licensing 84/07/18 TUCKFR. H B Dust Power Co 4pp 26059 314 P4X Fiche 50-413, 84/07/18, 8408130164
- 8408140344 Forwards Endorsement | to NELIA Certificate N-97 & MAELU Certificate M-97
  HOFFMAN, J Marsh ? McLennan, Inc. 84/08/13 DINITY, I Assistant
  Director for State & Licensee Relations 3pp 26092 181 24X Fiche 50-413,84/03/13,8408160344
- P Operating license stage documents \* correspondence
- 8408130161 Forwards License NPF-24, notice of issuance, Amend 1 to Indemnity Agreement B-100, SSER 3 % environ protection plan (nonradicalogical) W/o SSER 3 EISENHUT, D G DIVISION of Licensing 84/07/18 TUCKER, H B ogical woo seek 3 9 G Division of Licensing 84/07/18 TUCKER.H B Du 4pg 26057 314 24Y Fiche 50-413,84/07/18.8408130144

- --8408130168 Eicense NPF-24 for racility DENTUN.H fc Office of Nuclear Reactor Regulation Director 84/07/18 18pp 26059 317 247 Fiche 50-413 84/07/18,8408130164
- --8408130177 Notice of issuance of License NPF 24 ABENSAM, E. G. Licensing Brunch 1 84/07/18 5pp 26059 335 24X Fiche 50-413,84/07/18 8408130164
- ~-B408130174 Environ protection plan (nonradiologial) for facilities \* Office of Nuclear Reactor Regulation, Director 84/07/18 22pp 26059 340 24x Fiche 50-113,84/0\*/18 8408130164
- 8408060117 forwards Rev 5 to pump % valve inservice testing program TUCKER.H B Duke Power Co 84/07/27 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E G Licensing Branch 4 lp 25930 053 24/ Fiche 50-413.84/07/27.8408060117
- 8408160425 Summary of 840720 meeting w/utils & Westinghouse recontainment analysis 5 superheat effects on environ qualification WIGGINTON.D.L. Operating Reactors Branch 1 84/07/30 Operating Reactors Branch 1 4pp 26143 265 247 Fiche 50-000.84/07/30.8408160425
- 8408060097 Application for amend to License NPF-24.changing Tech Specs to revise surveillance requirement & acceptance criteria for auxiliary feeduater pumps
  TUCKER, H B Duke Power Co 84/07/31 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM. E G Licensing Branch
  4 Jpp 25925 309 24X Fiche 50-413.84/07/31,8408060097
- --8408060104 Proposed Tech Specs, changing surveillance requirement & acceptance criteria for auxiliary feedwater pumps # Duke Power Co 84/07/31 3pp 25925 312 24X Fiche 50-413, 84/07/31, 8408060097
- 8408090497 Summary of 840717 meeting w/Westinghouse Owners Steam Generator Tube Rupture Subgroup in Nothesda. MD re proposed steam generator tube rupture generic program List of attendees & vieugraphs enci SINCH-N K Liconsing Dranch 3 84/07/31 Licensing Branch 3 18pp 23983 130 24X Fiche 50-000.84/07/31,8408090497
- 8408130011 YECHNICAL SPECIFICATIONS FOR CATAWBA NUCLEAR STATION Unit I Docket No 50-413 ANDERSON, F D Division of Licensing NUREO-1072 84/07/31 525pp Available at NRC \$10 00 26039 001 24X Fiche 50-413.84/07/31, 8408130011
- B40B070263 Forwards add1 changes to 840625 revised FSAR Chapter 14 test abstracts, consisting of auxiliary feedwater sys functional test to rod control sys alignment test Changes will appear in Rev 12 to FSAR
  TUCKER, H B Duke Power Co 84/08/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E 9 Licensing Branch 4 App 25949 240 24X Fiche 50-413,84/08/01,8408070263
- 8408140430 Submits info re load history associated w/operation of Diesel Engine 18 TUCKER, H B. Duke Power Co. 84/08/03 DENTON, H R. Office of Nuclear Reactor Regulation, Director ADFNBAM, E. G. Licensing Branch 4 3pp 26051 184 24X Fiche 30-413,84/08/03,8408140430
- 8408070110 Ceneric Ltr 84~19 to all licensees of operating reactors, applicants for OLs & holders or CFs re availability of Suppl 1 to NUREO-0933. "Prioritization of Generic Safety Issues" Svo List encl
  EISENHUT.D 9 Division of Licensing 84/08/06 Consolidated Edison Co of Neu York, Inc. 18pp 26129 238 24x
  Fiche 50-000,84/08/06.8408070110
- 8408310016 Forwards listed documents re facilities, per 840515 stipulation of parties in proceeding W/o encl LEWIS.R C Region 2, Office of Director 84/08/06 PURDOM.P W Atomic Safety and Licensing Board Panel 2pp 26335 012 24X Fiche 50-413.84/08/06.8408310016
- 8408310028 Forwards listed documents re facilities, per 840515 stipulation of parties in proceeding W/o encls LEWIS.R C Region 2. Office of Director 84/08/06 RILEY, J L. Carolina Environmental Study Group 2pp 26335 015 24X Fiche 50-413.84/08/06.8408310028

- BAOB310241 Advises of decision to include individuals who receive copy under 840515 stipulation on collist Documents covered by stipulation and N/o encl LEWIS.6 C Region & Orfice of Director 84/08/06 FOSTER.8 F Affiliation Not Assigned 2pp 26333 334 24% Fichs 50-413.84/08/06/8408310211
- B40B310742 Advises of decision to include individuals who receive copy under 840515 signilation on collist Documents covered by stipulation encl W/o encl LEWIS R C. Region 2. Office of Director B4/08/06 KELLEY, J. L. Atomal Safety and Licensing Board Panel 2pp 26333 336 24% Fishe 50-413.84/08/06.840B310242
- 840823005: Forwards response to TDI emergency diesel generator issues raised by NRC / Battelle personnel during 840726 visit Edentification of cylinder heads addressed TUCKER.H B Duke Power Co 84/08/08 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E G Licensing Branch 4 App 26204 014 24X Fiche 50-413,84/08/08.8408230051
- 8408210365 Forwards "Torsiograph Tost of Emergency Diesel Generator 1A at Catawba Nuclear Power Station." in response to 840809 telcon request Start & should show run duration of 35 h rather than 43 TUCKER. H B Duke Power Co 84/08/14 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAME 6 Licensing Branch 4 3pp 26178 175 24X Fiche 50-413, 84/08/14.8408210365
- --8408210370 "Tersiograph Test of Emergency Diesel Generator 1A at Catawba Nuclear Power Station " \* Failure Analysis Associates FAAA-84-5-23 84/05/29 19pp 26178 178 247 Fiche 50-413.84/08/14.8408210365
- B40B220303 Forwards Rev 12 to FSAR Table 14 2 12-1. "Heat Tracing Sys Test " Test method & acceptance criteria revised to verify proper operation of heat tracing sys under current conditions TUCKER: H B Duke Power Co B4/08/14 DENTEN, H R Office of Nuclear Reactor Regulation, Director ADENSAMLE G Licensing Branch 4 3pp 26194 069 24X Fiche 50-413, 84/08/14,8408220303
- 8408270160 Forwards Rev 4 to "Offsite Dose Calculation Manual," incorporating Catabba calculation info Rev submitted prior to submitted of semiannual radioactive effluent release rept for Jul-Dec 1984
  TUCKER,H B Duke Fower Co 84/08/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26279 112 24X Fiche 50-000,84/08/16.8408270160
- ~~B408270169 Rev 4 to "Offsite Dose Calculation Manual"
  BIRCH:M L Duke Power Co B4/07/18 39pp 26279 114 24X
  Fiche 50~000,84/08/16,8408270160
- 8408210362 Application for amend to License NPF-24, revising Tech Specs 4 6 2 & 4 6 5 6 2 re containment pressure control sys Marked-up Tech Specs encl TUCKER, H B Duke Power Co 84/08/17 DENTON, H R Office of NUCKER, Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 14pp 26180 227 24% Fiche 50-413,84/08/17,8408210362
- 8408280281 Requests that amend to License NPF-24 re Tech Spec surveillance requirements for auxiliary feedwater pumps be granted by 840905 Belay may result in startup schedule for facility & have substantial financial impact TUCKER: H B Duke Power Co 84/08/17 DENTON. H R Defice of Nuclear Reactor Regulation. Director ADENBANE G Licensing Branch 4 Spp 86274 327 24X Fiche 50-413.84/08/17.8408280281
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for DLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT.D 0 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276-244 24X Fiche 50-000.84/08/20.8408200275
- G Imspection reports: IE Builetins & correspondence
- 8408270184 Forwards Insp Repts 50-413/84-71 & 50-414/84-31 on 840612-15 No violations or deviations identified DANCE, H C Region 2, Office of Director 84/07/09 TUCKER, H B Duke Power Co 2pp 26257 322 24% Fiche 50-413,84/07/09, 84.097/1184
- --B408270191 Insp Repts 50-413/84-71 & 50-414/84-31 on 840612-15. No violations or deviations noted Major areas inspected action on previously identified enforcement matters & 10CFR50 55(e) itsus RUFF. A B . CONLON-T E Region 2. Office of Director 84/07/03 5pp 26257 324 24X Fishe 50-413-84/07/09.8408270184

- B408280JH6 Forwards Insp Repts 50-413/84-73 b 50-414/84-32 on 840619-20 b 28 No violations or deviations noted DANCE, H C Region 2. Office of Director B4/07/11 TUCKER.H B Duke Power Co 2pp 26294 353 24X Fiche 50-413,84/07/11,
- --8408280393 Insp Repts 50-413/84-73 & 50-414/84-92 on 640619-20 & 28 No violations or deviations noted Major areas inspected corrective actions re worker concerns on socket weld fabrication & unauthorized removal of aic strikes ECCNOMOS:N. BLAKE.J. J. Region 2: Office of Director 84/07/10 3pp 26294 355 24x Fiche 50-413.84/07/11.8408280386
- 8408270367 Forwards Insp Repts 50-413/84-77 & 50-414/84~33 on 840623-29 No deviations or violations nated DANCE.H C Division of Project & Resident Programs 84/07/17 TUCKER.H B Dake Power Ca 2pp 26257 227 24x Fichs 50-413
- --8408270371 Insp Repts 50-413/84-77 & 50-414/84-33 on 840625-29 No violations or deviations noted Major areas inspected fire protection
  HISEMAN, G R , COMLON, T E Region 2, Office of Director 84/07/13
  6pp 26257 229 24X Fiche 50-413.84/07/17.8408220367
- 8408270474 Forwards Insp Rept 50-413/84-75 on 840625-29 No violations or deviations identified DANCE.H C Region 2, Diffice of Director 84/07/17 TUCKER,H B Duke Power Co 2pp 26256 211 24X Fithe 50-413,84/07/17.
- --8408270480 Insp Rept 50-413/84-75 on 840625-29 No violations or deviations noted Major areas inspected licensee action on previous insp findings b preoperational test results evaluation for solid-state protection sys functional test TAYLOR,P.A. JAFE,F. Region 2. Office of Director 84/07/12 4pp 26256 213 24x Fiche 50-413.84/07/17.8408270474
- 8408280327 Forwards Insp Rept 50-413/84-74 on 840426-28 No violations or deviations identified DANCE.H C Region 2. Office of Director 84/07/19 TUCKER.H B Dute Power Co 2pp 26282 261 24% Fiche 50-413.84/07/19.
- --8409280329 Insp Rept 50-413/84-76 on 840626-29 No violations or deviations noted Major areas inspected review of counting room & chemistry procedures, review of chemistry lab facilities & results of capability tests MUZD. G B , MONTGOMERY. D M Region 2. Office of Director 84/07/16 10pp 26282 263 24% Fiche 50-413,84/07/19,8408280327
- B408270484 Forwards Insp Rept 50-413/84-72 on 840618-22 No violations or deviations identified BANCE.H C Region 2. Office of Director 84/07/23 TUCKER.H B Duke Power Co 3pp 26256 188 24X Fiche 50-413.84/07/23.
- -8408270492 Insp Rept 50-413/84-72 on 840618-22 No violations or deviations identified Major areas inspected actions on previous enforcement natters & previously identified insp findings
  BELISLE, O A , FOSTER, L E , UPRIGHT, C M Region 2, Defice of Director 84/07/18 12pp 26236 191 24X Fiche 50-413,84/07/23,8408270484
- 07250227 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc. 119pp 25865 047 24% Fiche 50-000,84/07/27,8407250229
- 08020062 Forwards Ofc of Investigation Rept 2-83-038, "Catawba Nuclear Station Alleged Harassment & Intimidation of QC Helding Inspectors"

  KELLEY-J L. Atomic Safety and Licensing Board Panel DSB 693
  84/07/27 Office of the Executive Legal Director 1p 25898 201
  24% Fichs 50-413-84/07/27,8408020062
- --8408020068 Investigation Rept 2-89-038, "Duke Power Co Catawba Nuclear Station Harassent & Intimidation of GC Welding Inspectors " WILLIAMSON E L Office of Investigation 84/07/11 808pp 23898-202 24X Fiche 30-413,84/07/27,8408020062
- 8408080339 Forwards util "Investigation of Issues Raised by NRC in Insp Repts 50-413/84-31 & 50-414/84-17," in response to NRC concerns re allegations of Welder B Related correspondence CARR.A V Dute Power Co DSB 826 84/08/03 KELLY, L., FOSIER.R F , PURDUM.P Atomic Safety and Licensing Board Panel 120pp 25763 311 24x Fiche 50-413.84/08/03,8408080339

- 8408010333 IE Info Notice 84-59, 'Deliberate Circumventing of Static Health Physics Procedures Svc list encl JORDAVIE L Division of Emergency Preparedness 'C Engineering Response (Post 83010'3) 84708/06 Consolidated Edison Co of N York, Inc 122pp 26068 001 24% Fiche 50-000.84/08/06.84080100
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirato Filters to Meet Efficiency Requirement" Svc list enc! JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of N York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,84080103
- 8408300408 Forwards listed insp repts & related correspondence per 840819 stipulation of parties in proceeding W/o encls LEWIS,R C Region 2. Office of Director 84/08/06 GUILD,R Palmetto Alliance 2pp 26314 242 24X Fiche 50-413,84/08/06,8408300408
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of N York, Inc. 120pp 26129 118 24% Fiche 50-000.84/08/08.84080701
- 8408070376 IE info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list enci ORACE.J N Division of QA, Safeguards & Inspection Programs (Post B30103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24% Fiche S0-000,84/08/10.8408070376
- B40B100009 IE Info Notice 84-63, "Defettive RHR Replacement Piping " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 94/08/13 Consolidated Edison Co of M York, Inc 119pp 26197 218 24X Fiche 50-000-84/08/13,840810000
- B40B100038 IE Info Natice 84-64, "BWR HPC! Initiation Seal-In & Indication " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/08/15 Consolidated Edison Co of Ni York, Inc. 104pp 26198 093 24% Fiche 50-000,84/08/15,840B1000C
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adverse! Affect Operation of Essential Electrical Equipment " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/08/16 Consolidated Edison Co of No York, Inc. 118pp. 26198-001 24X Fiche 50-000.84/08/16, 840810002
- 840Bi00055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of Ne York, Inc 120pp 26276 001 24X Fiche 50-000.84/08/17,840810003
- 8408140208 IC Info Notice 84-67. "Recort Snubber Inservice Testing W/ High Failure Rates " Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post E03103) 84/08/17 Consolidated Edison Co of Ne York, Inc 122pp 26276 122 24X Fiche 50-000.84/08/17,840814020
- 8408270391 Provides status of actions taken re Diesel Engine 1A component revalidation insp TUCKER, H B Duke Power Co 84/08/17 DENTON, H R Office of Nuclear Reactor Regulation, Director ADEMSAM, E C Licensing Bran 4 5pp 26238 282 24% Fiche 50-413,84/08/17,8408270391
- 8408210142 IE Info Notice 84-48, "Potential Deficiency in Improperly Rated Field Wiring to Solemoid Valves " Svc list enc? JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of Ne York, Inc 115pp 26327.008 24X Fithe 50-000,84/08/21,840821014.
- R Periodic operating reports & related correspondence
- 8408300406 Monthly operating rept for Jul 1984 W/840823 ltr REAVIS,J A , TUCKER, H B Duke Power Co 84/07/31 3pp 26313 30 24X Fiche 50-413,84/07/31,8408300406
- 8 Reportable occurrences, LERs & related correspondence
- 8405290042 Forwards "Investigation of Types AF & AE Piston Skirts "
  Rept supercedes 840227 submittal
  RAY, C L TDI (Transamerica Delaval, Inc.) Owners Group 84/05/24
  DENTON, R Office of Nuclear Reactor Regulation, Director 2pp
  24690 045 24X Fiche 50-000.84/05/24,8408270062

- --8405290075 "Investigation of Types AF & AE Piston Skirts a Failure Analysis Associates FAAA-84-2-14 84/05/ 24% Fiche 50-000.84/05/24.8405290062 12000
- B405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Guif Nuclear Power RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group

84/05/24 NAY, C. IDI (Transamenica Delaval, Inc.) Jumers Group 84/05/2 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 24692 090 24% Fiche 50-000,84/05/24,8405290179

- 8408060405 Forwards repts received by BNWL & consultants directly from FaAA & TDI Quiners Ordup at 840622 meeting Draft "Overview of Repts Analysis & Recommendations re Main Propulsion Engines M/V Columbia" enc?
  ALTHEIMER. J M Battelle Memorial Institute. Pacific Northwest Laboratories 84/06/28 MILLER.M Division of Licensing 198pp 25926 173 24X Fiche 50~000.84/06/28.8408060405
- 8408060050 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Generator Cwners Group 840622 meeting RAY, C. t TDI (Transamentica Delaval. Inc.) Cwners Group 84/07/10 BERLINGER. C. Director's Office. Office of Inspection and Enforcement 43pp 25933 133 24% Fiche 50-000.84/07/10, 8408060050
- 8408090278 Final significant deficiency rept re seismic design criteria not applied to fire protection piping serving ESF filters Initially reported on 840628 fire protection spray water piping upgraded to Class F piping TUCKER. H B Duke Power Co 84/07/18 O'REILLY, J.P. Region 2, Office of Director 3pp 26030 200 24X Fiche 50-413,84/07/18,8408090278
- 8408160159 Interim deficiency rept re testing of valves modified by Borg-Warner Testing temporarily halted until electric motor operated valves nodified Corrective action will be completed by 841001
  TUCKER, H B Duke Power Co 84/07/25 O'REILLY, J P Region 2, Office of Director Ip 26106 342 24% Fiche 50-413,84/07/25,8408160159
- 8408160468 Interim Deficiency Rept SD 413/84-01 re add1 vibration testing Next rept will be provided by 841101
  TUCKER.H B Duke Power Co 84077/26 O'RCILLY.J P Region 2.
  Office of Director ip 26107 285 24X Fiche 50-413.84707/26. 8408160468
- 8408060102 Forwards "Emergency Diosel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Add1 copies sent to BNWL RAY, C. L. TDI (Transamerica Dølaval, Inc.) Owners Group 8/ DENTON.H R. Office of Nuclear Reactor Regulation, Director 25932 137 24X Fiche 50-000,84/07/27,8408040102 84/07/27
- ~-B408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review" # Stone & Webster Engineering Corp 84/07/31 36pp 25932 139 24X Fiche 50-000.84/07/27.8408060102
- 8408160429 Interin deficiency rept re cracking of two cast iron TUCKER, HB Director 3pp 26106 066 24X Fiche 50-413,84/07/27, Office of Director 8408140427
- 8408160517 Bignificant Deficiency Rept SD 413-414/84-18 re residual stress in Type AN piston skirts of TDI diesels Initially reported on 840628 Skirt cracks being evaluated Next rept by 850115
  TUCKER, H. B. Duke Power Co. 84/07/27 O'REILLY, J.P. Region 2. TUCKER, H B Duke Power Co 84/07/27 O'REILLY, J P Region 2.
  Office of Director 3pp 26108 012 24X Fiche 50-413.84/07/27,
  8408160517
- 8408060324 Forwards "Design Review of Elliott Model 650 Turbockarger Used on TDI DSRV-12-4 & DBRV-20-4 Emergency Diesel Generator Sets "

RAY, C. L. TDI (Transamerica Delaval, Inc.) Owners Group. 84, DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 25927 064 24% Fiche 50-000, 84/08/01,8408060324

8408070445 Forwards response to several TDI emergency diesel engine issues raised during NRC & Battelle 840726 visit Jacket water sys parameters show no evidence of flow water sys parameters snow no eventual resistance increase
TUCKER, H B Duke Power Co 84/08/01 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENBAM, E G Licensing Branch
4 Spp 25942 263 24X Fiche 50-413, 84/08/01, 8408070445

- 8408160183 Supplemental deficiency rept to evaluation of const flushing program Flush boundary for upper head injection pipe incomparated into const flushing program TUCKER.H B Duke Power Co 84/08/03 O'REILLY, J.P. Region 2, Office of Director 3pp 26106 316 24X Fiche 50-413.84/08/03. B4081A0183
- 8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines" RAY,C L. TDI (Transamerica Delaval, Inc.) Owners Group 84/08/10 DENIGN,H R. Office of Nuclear Reactor Regulation. Director 2pp 26091 147 24X Fiche 50-000.84/08/10.8408160394
- --8408160403 "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines" # Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp 26091 149 24% Fiche 50-000.84/08/10.8408160394
- 840B240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program, testing & insp, maint & surveillance & sets forth requirements for operation prior to completion of program plan ETSENHUT.D G Division of Licensing B4/08/13 GEORGE.J B TDI (Transamerica Delavel) Inc.) Owners Group ip 26255 174 24% Fiche 50-000.84/08/13.8408240115
- --B409240157 Safety evaluation of TDI Dwners Group program plan Based on BNML evaluation, plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc \* NRC No Detailed Affiliation Given 84/08/13 21pp 26255 195 24X Fiche 50-000,84/08/13,8408240115
- 8408160395 Forwards "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sats," representing final GA verified rept Addl copy forwarded to ENML, per NRC request RAY, C L TDI (Transamerica Delaval, Inc.) Owners Group 84/08/14 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 26088 163 24X Ficha 50-000,84/08/14,8408160395
- --8408160397 "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Energency Diesel Generator Sets." # Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp 26088 165 24X Fiche 50-000.84/08/14.8408160395
- B40B300501 LER B4-001-00 on B40721, boric acid transfer pumps 1A & 1B discovered danaged & inoperable due to extended operation w/o suction or discharge flow path Caused by improper valve lineup Procedure will be revised M/840B22 ltr OUELLETYE.R W. TUCKER.H B Duke Power Co 84/08/22 4pp 26314 064 24X Fiche 50-413,84/08/22,8408300501
- B408290179 Forwards response to 840723 request for add1 info on repts submitted by TDI Diesel Cenerator Owners Group RAY.C L TDI (Transamerica Delaval. Inc.) Dwners Group 84/08/23 BERLINDER.C Office of Auclear Reactor Regulation, Director 12pp 26289 221 24% Fiche SD-COO.84/08/23,8408290179
- T Hearing transcripts on non-antitrust matters
- 8408020060 Motion for changes to transcript of emergency planning hearing to correct matl errors ASLB requested to issue order directing that evidentiary record be amended incorporating encl changes
  MCGARRY.J M Duke Power Co MCGARRY.J M Bishop, Liberman, Cook,
  Purcell & Reynolds DSB 702 84/07/30 Atomic Safety and
  Licensing Goard Panel 1p 25892 271 24X Fiche 50-413, 84/07/30,
  8408020060
- --8408020046 Errata to transcript of 840501-0408 emergency planning hearing correcting math errors Certificate of 8vc encl # Duke Power Co #4/07/30 23pp 25892 272 24X Fiche 30-413.84/07/30.8408020060
- 8408140243 Transcript of 840810 telcon in Bethesda, MD Pp 12, 808-\*\* Atomic Safety and Licensing Board Panel 84/08/10 31pp 24055-355 24X Fiche 50-413,84/08/10,8408140243
- 8408280205 Testimony of ON Hallman.RP Muschick.SR Ward.JA Gorman. CA Wells.LA Swanger.SK Chen.JO Barbour.JM Curtis & RC Oamberg re problems encountered in diesel generator qualification program.Related correspondence HALLMAN.G W. MUSCHICK.R P. WARD.S R. Duke Power Co. DSB 322 B4/08/18 444pp 26271 314 24X Fiche 50-413.84/08/18.8408280205

#### U Congressional/Elecutive Correspondence

- 8408090508 Responds to 840706 ltr re NRC reply to R Guild.atty for Palmetto Alliance.840627 ltr concerning mod or suspension of facility CP DIRCMS.W J Office of the Executive Director for Operations 84/07/31 MARTIN.J G House of Rep 2pp 25982 334 24X Fiche 50-413.84/07/31.8408090506
- --8407100397 Informs of R Outld of Palmetto Alliance request urging NRC to provide Alliance U/expeditious response to 840627 ltr Progress update & response requested MARTIN.J G House of Rep., Ways and Means 84/07/06 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 4pp 25982 341 24X Fiche 50-413,84/07/31, auggraphog

#### V Operator Examinations

- 8408300375 Forwards summary of 840916 meeting w/util in Region II ofc re info developed by NRC re conduct of reactor/senior operator training & recent written license exam Attendance list also enci O'REILLY, J P Region 2. Office of Director 84/05/09 TUCKER, H & Duke Power Co Spp 26308 167 24X Fiche 50-413,84/05/09, 8408300375
- DOCKET 50-414 CATANDA NUCLEAR STATION: UNIT 2
- A Applacation/construction stage documents & correspondence
- 8408310428 Forwards summary of NRC 840418 meeting w/wtil in Region II oft & 840419 meeting at facility re followup to 840313 meeting concerning welding irregularity findings LEWIS.R C Region 2. Office of Director 84/05/01 TUCKER.H B Duke Power Co 5pp 26335 027 24% Fiche 50-413.84/05/01.
- B408130164 Forwards License NPF-24.notice of issuance.Amend 1 to Indemnity Agreement B-100.6SER 3 & environ protection plan (nonradiological) W/o SSER 3 E18EM-NUT.D G Division of Licensing 84/07/18 TUCKER.H B Duke Power Co 4pp 26059 314 24X Fiche 50-413.84/07/18,8408130164
- --8408130179 Environ protection plan (nonradiologial) for facilities # Office of Nuclear Reactor Regulation, Director #4/07/18 #28p 26059 340 24X Fiche 50-413,84/07/18,8408130164
- B408160425 Summary of B40720 meeting w/utils & Westinghouse re containment analysis & superheat effects on environ qualification WIGGINTON.D L. Operating Reactors Branch : 84/07/30 Operating Reactors Branch : 4pp 26143 265 24X Fiche 50-000,84/07/30, B408160425
  - OBO90497 Summary of 840717 meeting w/Westinghouse Owners Steam Generator Tube Rupture Subgroup in Bethasda: HD re proposed steam generator tube rupture generic grogram List of attendees & vieugraphs encl BINOH.8 K Licensing Branch 3 84/07/31 Licensing Branch 3 18pp 25783 130 24X Fiche 50-000.84/07/31.8408070497
  - OB070263 Forwards add1 changes to B40625 revised FBAR Chapter 14 test abstracts.consisting of auxiliary feedwater sys functional test & rod control sys alignment test Changes will appear in Rev 12 to FBAR TUCKER.H B Duke Power Co 84/08/01 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E G Licensing Branch 4 4pp 25949 240 24X Fiche 50-413.84/08/01.8408070263
- 8408140430 Submits info re load history associated u/operation of Diesel Engine 18 TUCKER,H B Duke Power Co 84/08/03 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM.E Q Licensing Branch 4 3pp 26051 184 24X Fiche 50-413,84/08/03,8408140430
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREQ-0933. "Prioritization of Generic Safety Issues" Svc list enci EISENHUT.D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26189 238 24X Fiche 50-000.84/08/06.8408070110
- 8408310016 Forwards listed documents re facilities.per 840515 stigulation of parties in proceeding W/o encl LEWIS.R C Region 2. Office of Director 84/08/06 PURDOM.P W Atomic Safety and Licensing Board Panel 2pp 26335 012 24X Tiche. 90-413.84/08/06.8408310016

- 8408310028 Forwards listed documents refacilities.per 840515 stipulation of parties in proceeding W/o encis LEWIS.R C Region 2. Office of Director 84/08/06 R[LEY.J L Carolina Environmental Study Group 2pp 26335 015 24X Fires 50-413.84/08/06.8408310028
- 8408310241 Advises of decision to include individuals who receive copy under 840515 s+spulation on cc list Documents covered by stipulation encl LEMIS.R C Region 2. Office of Director 84/08/06 FOSTER.R F Affiliation No+ Assigned 2pp 26333 334 24X Fiche 30-413.84/08/06.8408310241
- 8408310242 Advises of decision to include individuals who receive copy under 840915 stipulation on cc list Documents covered by stipulation encl W/o encl LEWIB.R C Region 2. Office of Director 84/08/06 KELLEY.J L Atomic Safety and Licensing Board Panel 2pp 26333 336 24% Fiche 50-413.84/08/06.0480310242
- 8408230051 Forwards response to TDI emergency diesel generator issues raised by NRC t. Dattelle personnel during 840726 visit Identification of cylinder heads addressed TUCKER. H B Duye Power Co 8408/08 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAME G Licensing Branch 4 App 26204 014 24X Fiche 50-413,84/08/08,8408230051
- 8408210365 Forwards "Torsiograph Test of Emergency Diesel Generator 1A at Catawba Nuclear Power Station." in response to 840805 telcon request Start & should show run duration of 35 h rather than 43 TUCKER.H B Duke Power Co 84/08/14 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E & Licensing Branch 4 3pp 26178 175 24% Fiche 50-413.84/08/14.8408210365
- --B40B210370 "Torsiograph Test of Emergency Diesel Generator 1A at Catamba Nuclear Power Station "
  • Failure Analysis Associates FAAA-84-5-23 84/05/29 19pp 26178 178 24X Fiche 50-413,84/08/14,8408210365
- 340B220303 Forwards Rev 12 to FSAR Table 14 2 12-1, "Heat Trecing Sys Test " Test method & acceptance criteria revised to verify proper operation of heat tracing sys under current conditions FUCKER.H B Duke Power Co 84/08/14 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM.E G Licensing Branch 4 3pp 26194 067 24% Fiche 50-413,84/08/14,8468220303
- B40B270160 Forwards Rev 4 to "Offsite Dose Calculation Manual," incorporating Catawba calculation info Rev submitted prior to submitted of seniannual radioactive effluent release rept for Jul-Dec 1984
  TUCKER, H B Duke Power Co 84/09/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26279 112 24X
  Fiche 50-000,84/08/16,8408270160
- --8408270169 Rev 4 to "Offsite Dose Calculation Manual" BIRCH.M.L. Duke Pouer Co. 84/07/18 37pp 26279 114 24X Fiche 50-000,84/08/16.8408270160
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions SVc list encl EISENKUT.D G Division of Licensing 84/08/20 Consolidated Edison Co of New York Inc 17pp 26276 244 24X Fiche 50-000.84/08/20.8408200275
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8408080275 Forwards proprietary & nonproprietary "Mestinghouse Setpoint Methodology for Protection Sys,Catawba Station." in response to Section 7 3 24 of SER Application for withholding proprietary rept encl
  TUCKER.H B Duke Power Co 84/07/30 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAH.E O Licensing Branch 4 2pp 25964 228 24% Fiche 50~413,84/07/30,9408080275
- --8408080284 Nonproprietary "Westinghouse Setpoint Methodology for Protection Sys.Catawba Station " Two oversite tables encl Aperture cards available in PDR
  JANSEN,R L., TULEY.C R. Westinghouse Electric Corp. 84/06/30
  71pp 25964 238 24X Fiche 50-413.84/07/30.8408080275

- 8408070009 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CATAMBA NUCLEAR STATION.UNITS 1 AND 2 DOCKET Nos 50-413 And 50-414 (Duke Power Company, et al) 
  # Division of Licensing NUREG-095% SO3 84/07/31 140pp Available at NRC \$5 50 2595% 334 24% Fiche 50-413,84/07/31, 8408070009
- F Security, medical, emergency & fire protection plans
- 8408300358 Forwards FEMA "Exercise Rept, Catawba Nuclear Station, 840215-16" DANCE, H C Region 2, Office of Director 84/06/25 TUCKER, H B Duke Power Co Ip 26308 264 24X Fiche 50-413,84/06/25, 8408300358
- B40B270367 Forwards Insp Repts 50-413/B4-77 & 50-414/B4-33 on B40625-29 No deviations of violations noted DANCE-H C Division of Project & Resident Programs 84/07/17 TUCKER H B Duke Power Co 2pp 26257 227 24% Fiche 50-413
- --8408270371 Insp Repts 50-413/84-77 % 50-414/84-33 on 840425-29 No violations or deviations noted Major areas inspected fire protection WISEMAN.6 R Region 2, Office of Director 84/07/13 App 24257 229 24X Fiche 50-413.84/07/17.8408270367
- 8408070042 Forwards States of NC & SC responses to regional assistance committee findings on offsite radiological emergency response preparedness & exercise on 840215-16 State & local emergency plans adequate KRIMM: RW Federal Emergency Management Agency 84/07/27 JORDAN. E. Division of Emergency Preparedness & Engineering Response (Post 830103) Bpp 25792 324 24X Fiche 50-413,84/07/27,8408000042
- 8408020060 Motion for changes to transcript of emergency planning hearing to correct matl errors ASLB requested to issue order directing that evidentiary record be amended incorporating encl changes
  MCOARRY.J M Duke Power Co DSB 702 84/07/30 Atomic Safety and Licensing Board Panel ip 25872 271 24X
  Fiche 50-413.84/07/30.8408020060
- --8408020066 Errata to transcript of 840501-0608 emergency planning hearing.correcting matl errors Certificate of 8vc encl w Duke Power Co 84/07/30 23pp 25892 272 24X Fiche 50-413,84/07/30,8408020060
- B408090007 Forwards safeguards implementation ltrs Ltrs withheld (ref 10CFR73 21) TUCKER, H B Duke Power Co 84/07/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 25973 005 24X Fiche 50-413,84/07/30,8408090007
- B40B070322 Responds to NRC concern re false opening of MSIVs or steam generator PORVs for Steam Generators A, B & D due to fire Mad will be implemented on Unit I prior to entry into Mode 3

  TUCKER: H B Duke Power Co 84/08/02 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM. E Q Licensing Branch 4 1p 25745 127 24x Fiche 50-413, 84/08/02, 8408070322
- 8408070351 Advises that sufficient manpower available onsite to perform required manual operations in timely manner to achieve safe hot standby conditions w/o reliance on fire brigade members, per NRC request during App R review TUCKER.H B Duke Power Co 84/08/03 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAME G Licensing Branch 4. 1p. 25744 147 24X Fiche 50-413,84/08/03.8408070351
- B408280372 Forwards public version of revised emergency plan implementing procedures, including HP/O/B/1009/07 re in-plant particulate & indine monitoring under accident conditions & HP/O/B/1009/05 re personnel monitoring TUCKER; H B Duke Pouer Co 84/08/06 Record Services Branch (Document Control Desk) 2pp 26293 049 24X Fiche 50-413, 84/08/06,8408280372
- --B4082B0377 Public version of revised emergency plan implementing procedures including HP/0/B/1009/07 re in-plant particulate & lodine monitoring under accident conditions & HP/0/B/1009/05 re personnel monitoring W/Felton 840821 memo TUCKER.H B Duke Power Co 84/08/06 74pp 26293 051 24X Fiche 50-413,84/08/06,84082800372
- 8408300357 Confirms 840806 telcon w/JP D'Reilly re 840815 meeting in Region II ofc to discuss design & operation of standby shutdown facility concerning App R to 10CFR50, fire protection & 10CFR50, physical protection Agenda encl LEWIS, R C Region 2. Office of Director 84/08/08 TUCKER, H B Duke Power Co 3pp 26314 222 24X Fiche 50-000,84/08/08, 8408300357

- 840B300014 Forwards public version of Rev 13 to crisis mgt plan & revised emergency plan implementing procedures
  TUCKER.B B Duke Power Co. 84/08/10 Record Services Branch
  (Document Control Desk) 21pp 26332 353 24X
  Fiche 50-000.84/08/10.8408300014
- --8408300021 Public version of Rev 13 to "Crisis Mgt Plan for Nuclear Stations" # Duke Power Co 84/08/15 30pp 26333 010 24X Fiche 50-000,84/08/10,8408300014
- --8408300028 Public version of revised crisis mgt plan implementing procedures including 5 3 1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group W/Felton 840823 nemo

  \* Duke Power Co 84/08/15 170pp 26333 040 24X Fiche 50-000.84/08/16,8408300014
- 840B290041 Board Notification 84-151 forwards FEMA interim findings on offsite radiological emergency response preparedness, 8tate of 8C 840424 1+r & State of NC 840522 1tr NDVAK.T M Assistant Director for Licensing 84/08/29 MARQULIES, M , LAZO.R , HQOPCR, F Atomic Safety and Licensing Board Panel 4pp 26322 115 24X Fische 50-413, 84/08/29, 8408290041
- --8406140090 Requests add1 info & supplemental interim findings re status of offsite radiological plans & preparedness Statement indicating adequacy of state & local emergency plans should be provided by 840615

  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/06/07 KRIMM, R W Federal Emergency Management Agency ip 26322 127 24X Fiche 50-413.84/08/29, 8408290041

#### G Adjudicatory correspondence

- 840B150524 Forwards applicant Exhibits EF 18-20 intervenor Exhibits EF 42.43,44.45.46,47.50,48 & 49 & NRC Exhibit EF 5 re emergency planning Related correspondence EYBTER.R Tayloe Associates 84/05/31 PLEASANT.E Administrative & Logistical Support Branch ip 26105 363 24% Fiche 50-413.84/05/31.8408150524
- 8408160109 Forwards intervenor Exhibits 31-54 & 19.NRC staff Exhibit 3A & applicant Exhibits 21A & 21 Related correspondence.
  RILEY.S L. Tayloe Associates 84/06/15 PLEASANT.E
  Administrative & Logistical Support Branch 1p 26126 326 24X
  Fiche 50-413.84/06/15.8408160109
- 8408010211 Responds to Judge Kelley 840716 request for applicant 840822 responses to NRC questions on emergency diesel generators W/o encis Related correspondence UDHN80N.0 E Hearing Branch 4 DSB 678 84/07/27 KELLY,J L , PURDOM,P W , FOSTER.R F Atomic Safety and Licensing Board Panel Ip 25836 052 24X Fiche 50-413.84/07/27, 8488010211
- 8408020062 Forwards Ofc of Investigation Rept 2-83-038, "Catauba Nuclear Station Alleged Harassment & Intimidation of QC Welding Inspectors" KELLEY, J L Atomic Safety and Licensing Board Panel D88 673 84/07/27 Office of the Executive Legal Director ip 25898 201 24X Fiche 50-413.84/07/27, 8408020062
- 8408070443 Joint proposed findings of fact & conclusions of law in form of partial initial decision re emergency planning contentions Certificate of Svc encl GUILD.R Palmetto Alliance GUILD.R Guild, R GUILD.R Carolina Environmental Study Group DSB 776 84/07/27 195pp 25943 206 24X Fiche 50-413,84/07/27,8408070443
- 8408020060 Motion for changes to transcript of emergency planning hearing to correct matl errors ASLB requested to issue order directing that evidentiary record be amended, incorporating encl changes
  MCGARRY, JM Duke Power Co MCGARRY, JM Bishop, Liberman, Cook, Purcell & Reynolds DSB 702 84/07/30 Atomic Safety and Licensing Board Panel 1p 25892 271 24X Fiche 50-413.84/07/30, 840802060
- --8408020066 Errata to transcript of 840501-0608 emergency planning hearing, correcting matl errors Certificate of 8vc encl \* Duke Power Co 84/07/30 23pp 25892 272 24X Fiche 50-413,84/07/30,8408020060
- 8408020013 Order extending time until 840904 for Commission to act to review Director's Decision DD-84-16 Served on 840801 CHILK.8 J Office of the Secretary of the Commission DSB 692 84/07/31 Commissioners ip 25883 115 24X Fiche 50-413.84/07/31.8408020013

- 8408060033 Response to Palmetto Alliance & Carolina Environ Study Group seven interrogatories for which ASLB granted motion to compel Certificate of Syc enci Related correspondence CARR. A V Duky Pouer Co DSB 746 84/08/01 Palmetto Alliance 53pp 25928 087 24X Fiche 50-413,84/08/01,8408060035
- 8408200548 Expresses opinion that ASLB 840720 order imposes burdens on Palmetto Alliance & Carolina Environ Study Group solely as consequence of util & staff tardiness in discovery of safety problens widiesel generators Related correspondence QUILD.R Guild.R GUILD.R Palmetto Alliance GUILD.R Carolina Environmental Study Group DSD 159 84/08/01 KELLEY.J L. FOSTER, F. F. PURDOM.P II Atomic Safety and Licensing Roard Panel 2pp 26137 028 24X Fiche 50-413.84/08/01.6408200548
- 8408070422 Summarizes 840802 agreement to 2-day extension to serve dissel generator technical evaluation rept Related correspondence
  JOHNSON.G E Hearing Branch 4 DSB 818 84/08/03 KELLEY. J L Atomic Safety and Licensing Board Panel 1p 25742 025 24X Fiche 50-413,84/08/03,8408070422
- 8408080339 Forwards util "Investigation of Issues Raised by NRC in Insp Repts 50-413/84-31 & 50-414/84-17." in response to NRC concerns re allegations of Welder B Related correspondence CARR.A V Duke Power Co DSB 826 84/08/03 KELLY, J L , FOBTER.R F , PURDOM.P Atomic Safety and Licensing Board Panel 120pp 25963 311 24X Fiche 50-413.84/08/03.8408080339
- 8408090191 Forwards technica) evaluation rept.per ASLB 840720 order stablishing schedule leading to 840827 hearing on diesel generator contention W/o encl Related correspondence JOHNSON.9 E Hearing Branch 4 DSS 863 84/08/07 KELLEY, J. E., PURDOM.P W., FOSTER.R F. Atomic Safety and Licensing Board Panel 150pp 26130 189 24X fiche 50-413.84/08/07.8408090191
- 8408130270 Proposed findings of fact & conclusions of law in form of supplemental partial initial decision on emergency planning Certificate of Svc encl MCGUBREN.H J Hearing Branch 1 JOHNSON,G E Hearing Branch 4 DSB 910 84/08/08 149pp 26009 001 24X Fiche 50-413,84/08/08,8408130270
- 8408140103 Supplemental response to joint interrogatories & requests to produce documents on diesel generator contentions & to Carolina Environ Study Group Interrogatories Prof qualifications encl Related correspondence
  CARRA V Duke Power Co DES 937 84/08/10 Palmetto Alliance
  17pp 26048 334 24% Fiche 50-413,84/08/10.8408140103
- --8408140110 Forwards interrogatories to Palmetto Alliance & Carolina Environ Study Group re identity of expert witness on diesel generator problems
  CARR.A V Duke Power Co 84/08/10 KELLEY, J L , PURDOM, P W , FOBTER, R F Atomic Safety and Licensing Board Panel 1p 26/048 351 24% Fiche 50-413,84/08/10.8408140103
- --8408140115 Interrogatories re identification qualifications & role of expert on diesel generator contention Certificate of Svc encl Related correspondence CARR.A V Duke Power Co 84/08/10 Palmetto Alliance 7pp 26/048 352 24X Ficha 50-413.84/08/10.8408140103
- 108160121 Forwards Attachment A to Section VII, "Repair of Drill Holes," of 840803 transmittal Corrections to errors listed Related correspondence CARR. A V Duke Power Co DSB 069 84/08/13 KELLEY, J.L., FOSTER.R F. PURDOM.R Atomic Safety and Licensing Board Panel App 26085 180 24% Fiche 50-413,84/08/13,8408160121
- 108200481 Forwards SER re reliability of diesel generators Related correspondence
  JOHNSON, 0 E Hearing Branch 4 DSB 175 84/08/14 GUILD, R
  Palmetto Alliance RILEY, J.L. Carolina Environmental Study Group
  11pp 26136 307 24X Fiche 50-413, 84/08/14, 8408200481
- OB200508 Forwards SER re reliability of diesel generators Technical evaluation rept, which forms part of SER, previously forwarded W/o encl Related correspondence JOHNSON, 0 E Hearing Branch 4 DSB 176 84/08/14 KELLY, J L , FOSTER, R F , PURDOM, P W Atomic Safety and Licensing Board Panel Ip 26136 360 24% Fiche 50-413, 84/08/14, 8408200508
- 408200499 Forwards additinfoire NRC witnesses on intervenor diesel generator contention & two additionments Related correspondence
  UCHNSCN:0 E Hearing Branch 4 DSB 172 B4/08/15 QUILD.R
  Palmetto Alliance RILEY.J L Carolina Environmental Study Group
  19 26/37 001 24% Fiche 50-413.84/08/15,8408200499

- --B40B200513 Supplemental responses to Palmetto Alliance & Carolina Environ Study Group 840318 general interrogatories Centificate of Svc encl Related correspondence JUHNSON, G E Heating Branch 4 84/08/15 Palmetto Alliance 15pp 26137 002 24X Fiche 50-413, 84/08/15, 8408200499
- 8408310205 Expresses disagreement w/conclusions expressed in util, ENML & NRC staff lepts re reliability of TDI emergency diesel generators Pattern of deficiencies exists which precludes findings Related correspondence GUILD.R Guild, R GUILD.R Palmetto Alliance GUILD.R Carolina Environmental Study Group DS8 430 84/08/16 KELLEY.J L , PURDOM,P W , FOSTER.R F Atomit Safety and Licensing Board Panel 193pp 26317 228 24% Fiche 50-413-84/08/16-8408310205
- 8408270119 Discusses intervenors intention to rely on prefiled testimony as statement of detailed technical position, per ASLB 840720 order \$ 840810 telcon PJ Louiecky added to staff panel Related correspondence
  JOHNSON, G E Hearing Branch 4 DSB 303 84/08/17 GUILD, R
  Palmetto Alliance RILEY, J L Carolina Environmental Study Group
  4pp 26247 340 24X Fiche 50-413,84/08/17,8408270119
- 8408220347 Reply to proposed findings of fact & conclusions of law of Palmetto Alliance.Carolina Environ Study Group & NRC Certificate of Svc encl MCGARRY, J M Duke Power Co MCGARRY, J M Dishop, Liberman, Cook. Purcell & Reynolds DSB 188 84/08/20 Atomic Safety and Licensing Board Panel 125pp 26192 001 24X Fiche 30-413, 84/08/20,8408220347
- 8408270092 Forwards transcript of NRC staff testimony of CH Berlinger, BJ Kirkwood, PJ Louzecky & JF Nesbitt re operability & reliability of facility emergency diesel generators Certificate of Svc enci Related correspondence
  JOHNSON, O E Hoaring Branch 4 DSB 207 84/08/20 KELLY, J L , FOSTER, R F , PURDOM, P W Abomic Safety and Licensing Board Panel
  46pp 26247 004 24X Fiche 50-413.84/08/20.8408270092
- B408270109 Forwards SEK re TDI Diesel Generator Owners Group program plan W/o encl Related correspondence JONNEDN, 0 E Hearing Branch 4 DSB 310 84/08/20 KELLEY, J L , PURDOM, P W , FOSTER, R F Atomic Bafety and Licensing Board Panel 1p 26247 325 24% Fiche 50-413,84/08/20,8408270109
- 8408230280 Order dismissing diesel generator contention & canceling B40827 evidentiary hearing Intervenor submission & staff & applicant testimony accepted as proof of positions had contention gone to hearing Served on 840822 KELLEY. J L Atomic Safety and Licensing Board Panel DSB 225 B4/08/22 Palmetto Alliance 2pp 26205 360 24X Fiche 50-413.84/08/22.8408230280
- 8408280495 Forwards License NPF-24 & SBER 3, including pertinent FR notices environ protection plan. Amend i to Indemnity Agreement B-100 & antitrust conditions Was encls Related correspondence
  JOHNSON.9 E Hearing Branch 4 DSB 341 84/08/24 ROSENTHAL, A S , MDORE, T S , WILBER, H A Atomic Safety and Licensing Appeal Panel 2pp 26280 334 24% Fiche 50-413,84/08/24,8408280495
- I Financial information
- B408240224 Forwards Duke Power Co & North Carolina Municipal Power Agency I 1983 annual repts TUCKER.H B Duke Power Co 84/08/16 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch A 2pp 26237 137 24X Fiche 50-000,84/08/16.8408240224
- --8408240239 "1983 Annual Rept " CLAY, G W , SHAW, R W North Carolina Municipal Power Agencies 83/12/31 27pp 26237 139 24X Fiche 50-000,84/08/16,8408240224
- --8408240242 "1983 Annual Rept " LEE.W 6. BOOTH.D W Duke Power Co 83/12/31 47pp 26237 167 24% Fiche 50-000.84/08/16.8408240224
- J Insurance & indensity information
- B408160344 Forwards Endorsement 1 to NELIA Certificate N-97 & MAELU Certificate M-97 HOFFMAN,J Harsh & McLennan, Inc 84/08/13 DINITZ,I Assistant Director for State & Licensee Relations 3pp 26092 181 24X Fiche, 50-413,84/08/13,8408160344

- q Inspection reports: IE Bulletins \* correspondence
- 8408270184 Forwards Insp Repts 50-413/84-71 \$ 50-414/84-31 on 840612-15 No violations or deviations identified DANCE.H C Region 2. Office of Director 84/07/09 TUCKER.H B Dute Power Co 2pp 26257 322 24% Fiche 50-413,84/07/09, 8408279184
- --8408270191 Insp Repts 50-413/84-71 / 50-414/84-31 on 840612-15 No violations or deviations noted Major areas inspected action on previously identified enforcement matters & 10CFR50 55(e) items

  RUFF.A B. CONLUM: E. Region 2. Office of Director 84/07/03 566 26257 324 24% Fichs 50-413-88/07/09.8408270184
- 8408280386 Forwards Insp Repts 50-413/84-73 % 50-414/84-32 on 840619-20 & 28 No violations or deviations noted DANCE. H C Region 2. Office or Director 84/07/11 TUCKER, H B Duke Power Co 2pp 26294 353 24% Fiche 50-413/84/07/11, R408280386.
- ~~B408280373 Insp Repts 50-413/84-73 & 50-414/84-32 on B40619-20 & 28 No violations or deviations noted Major areas inspected corrective actions re worker concerns on socket weld fabrication & unauthorized removal of arc strikes ECONOMOS: N. BLAXE. J J Region 2. Office of Director 84/07/10 3pp 26294 355 24X Fiche 50-413,84/07/11.8408280386
- 8408270367 Forwards Insp Repts 50-413/84-77 & 50-414/84-33 on 840625-29 No deviations or violations noted BANCE. H C Division of Project & Resident Programs 84/07/17 TUCKER, H B Duke Pouer Co 2pp 26257 227 24X Fiche 50-413,84/07/17,8408270367
- --8408270371 Insp Repts 50-413/84-77 & 50-414/84-33 on 840625-29 No violations or deviations noted Major areas inspected fire protection WISEMAN.G R , CONLON.T C Region 2, Office of Director 84/07/13 &pp 26237 229 24X Fiche 50-413,84/07/17.8408270367
- 8407250229 IE Info Notice 84-97. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commorcial Power Plants " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc. 1199p 25845 047 24X Fiche 50-000,84/07/27,8407250229
- 8408020062 Forwards Ofc of Investigation Rept 2-83-038, "Catauba Nuclear Station Alleged Harassment & Intimidation of GC Heliding Inspectors " KELLEY, J Atomic Safety and Licensing Board Panel DSB 693 84/07/27 Office of the Executive Legal Director ip 25898 201 24% Fiche 50-413,84/07/27,8408020062
- --8408020068 Investigation Rept 2-83-038, "Duke Power Co Catawba Nuclear Station Harassment & Intimidation of GC Welding Inspectors " WILLIAMSON,E L. Office of Investigation 84/07/11 808pp 25978 202 24% Fiche 50-413,84/07/27,8408020062
- B4080B0339 Forwards util "Investigation of Issues Raised by NRC in Imap Repts 50-413/84-31 & 50-414/84-17," in response to NRC concerns re allegations of Helder B Related correspondence CARR.A V Duke Power Co D58 826 84/08/03 KELLY.J L Atomic Safety and Licensing Buard Panel 120pp 25963 311 24X Fiche 50-413.84/08/03.8408080339
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26068 001 24X Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN, E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- B40B3004QB Forwards listed insp repts & related correspondence per B40B15 stipulation of parties in proceeding W/o encls. LEMIB.R C Region 2. Office of Director B4/0B/06 GUILD.R Palmetto Alliance 2pp 26314 242 24X Fiche 50~413,84/0B/06, B40B30040B
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Syr list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fiche 50-000,84/08/08,8408070120

- 840B070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl ORACE. J N Division of GA, Bareguards & Inspection Programs (Post B30103) 84/08/10 Consolidated Edison Co of New York. Inc 125pp 26130 00: 24% Fiche 50-000, 84/08/10.8408070376
- 8408100009 IC Info Notice 84~63. "Defective RHR Replacement Piping " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co. of New York, Inc. 119pp 26197 218 24X Fiche 30-000.84/08/13.8408100009
- 8408100038 IE Info Notice 84-64. "BWR MPC| Initiation Seal-In & Indication " Syc list enc! JURDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co. of New York, Inc. 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038
- 840810002: IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26178 001 24X Fiche 50-000.84/08/16.8408100021
- 8408100055 IE Info Notice 84-64, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 001 24X Firbe 50-000.84/08/17,8408100055
- 8408140208 IE Info Notice 84-67. "Recent Enubber Inservice Testing W/
  High Failure Rates " Svc list encl
  JURDAN E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/17 Consolidated Edison Co of New
  York, Inc 122pp R6276 122 24X Fiche 50-000.84/08/17.8408140208
- 8408270391 Provides status of actions taken to Diesel Engine 1A component revalidation insp TUCKER.H B Duke Power Co 84/08/17 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM.E 0 Licensing Branch 4 5pp 26238 282 24X Fiche 50-413, 84/08/17, 8408270391
- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list entl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc. 115pp 26327 008 24X Fiche 50-000.84/08/21.8408210142
- S Reportable occurrences, LERs & related correspondence
- 8405290062 Forwards "Investigation of Types AF & AE Piston Skirts"
  Rept supercedes 840277 submittal
  RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group 84/05/24
  DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp
  24690 045 24X Fiche 50-000,84/05/24,8405290062
- --8409290075 "Investigation of Types AF & AE Piston Skirts "
  \* Failure Analysis Associates FAAA-64-2-14 84/05/23 120pp
  24% Fiche 30-000.84/05/24,8405290062
- 8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations " RAY.C L TDI (Transamerica Delaval, Inc.) Dwners Group 84/05/24 DENTON; H R Office of Nuclear Reactor Regulation, Director 2pp 24692 090 24% Fiche 50-000,84/05/24,8405290179
- 8408060403 Forwards repts received by BNWL & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts, Analysis & Recommendations re Main Propulsion Engines M/V Columbia" enci
  ALZHEIMER.J M Battelle Memorial Institute, Pacific Northwest
  Laboratories 84/04/28 MILLER.M Division of Licensing 138pp 23926 173 24x Fiche 50-000.84/06/28.8408060405
- 8408050050 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Generator Owners Group 840522 meeting RAY,C L TDI (Transamerica Delaval, Inc.) Gwners Group 84/07/10 BERLINGER,C Director's Office, Office of Inspection and Enforcement 43pp 25933 133 24% Fiche 50-000,84/07/10,8408060050
- 8408090278 Final significant deficiency rept re seismic design criteria not applied to fire protection piping serving ESF filters. Initially reported on 840628 Fire protection spray water piping upgraded to Class F piping TUCKER. H B Duke Power Co. 84/07/18 D'REILLY, J P Region 2, DFfire of Director 3pp. 26030 200 24X Fiche 50-415, 84/07/18, 8408090278

- B40B160159 Interin deficiency mept me testing of valves modified by Borg-Harmer Testing temporarily halted until electric motor operated valves modified corrective action will be completed by 841001 TUCKER, H B Duke Power Co 84/07/25 O REILLY, J P Region 2, Office of Director 1p 26106 342 24X Fishs 50-413, 84/07/25, 8400160139
- 8408040102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Jermination Qualification Review " Addl capies sent to BNNL RAY.C L TDI (Transamerica Delaval. Inc.) Quiners Group 84/07, DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2; 25932-137 24X Fiche 50-000.84/07/27,8408040102
- --8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review" \* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139 24X Fichs 50-000.84/07/27.8408060102
- 8408140427 Interin deficiency rept re cracking of two cast iron subcovers in pedestal at junction of intake rocker arm shaft & subcover initially reported on 840624 Cracked subcovers replaced Final report uill be provided on 850il5 TUCKER.H B Duke Power Co 84/07/27 D'REILLY, J.P. Region 2, Office of Director 3pp 26106 066 24% Fiche 50-413,84/07/27. 8408160429
- B408160517 Significant Dericiency Rept SD 413-414/84-18 re residual stress in Type AN piston skirts of TDI diesels Initially reported on 840628 Skirt cracks being evaluated Neit rept by B50115
  TUCKER.H B Duke Pouer Co 84/07/27 O'REILLY.J P Region 2, Office of Director 3pp 26108 012 24X Fiche 50-413.84/07/27, B408160517
- 8408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Bets "
  RAY.C L TDI (Transamerica Delaval, Inc.) Gwners Group 84/08/01
  DENION.H R Office of Nuclear Reactor Regulation, Director 2pp 25927 064 24X Fiche 50-000.84/08/01.3408060324
- 8408070445 Forwards response to several TDI emergency diesel engine issues raised during NRC & Battelle 840726 visit Jacket water sys parameters show no evidence of flow resistance increase FUCKER. H B Duke Power Co 84/08/01 DENTON, H R Defice of Nuclear Reactor Regulation, Director ADENSAM E Q Licensing Branch 4 5pp 25942 263 24% Fiche 50-443,84/08/01.8408070445
- 840Bi601B3 Supplemental deficiency ropt re evaluation of const flushing program Flush boundary for upper head injection pipe incorporated into const flushing program TUCKER: H B Duke Power Co 84/08/03 O'REILLY. J P Region 2, Office of Director 3pp 26106 316 24X Fiche 50-413.84/08/03, 8808160183
- 8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines " Engines " Dimers Group B4/08/10 RAY: C L TDI (Transamerica Delaval, Inc.) Duners Group B4/08/10 DENTON: HR Office of Nuclear Reactor Regulation, Director 2pp 26091 147 24% Fiche 50-000.84/08/10.8408160394
- --8408160403 "Design Revieu of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines " \* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp 26091 149 24X Fiche 50-000,84/08/10,8408160394
- 8408240115 Forwards SER re TDI Owners Group program plan SER addresses design revisw/quality revalidation program testing & insp. maint & surveillance & sets forth requirements for operation prior to completion of program plan EISENHUT, D @ Division of Licensing 84/08/13 GEORGE, J B TDI (Transamorica Delaval, Inc.) Owners Group 1p 26255.194 24X Fiche 50-000,84/08/13,840824015
- --8408240157 Safety evaluation of TDI Duners Group program plan Based on BNML evaluation, plan incorporates essential elements needed to resolve outstanding concerns re rollability of TDI engines for nuclear svc # NRC - No Detailed Affiliation Given 84/08/13 21pp 26255 175 24X Fiche 50-000.84/08/13.8408240(15
- 8408160375 Forwards "Design Review of Elliott Model 900 Turbocharger Used on TDI DER-88 & DERV-16 Emergency Diesel Generator Sets," representing final GA verified rept. Addl copy forwarded to BNML.per NRC request RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group 84/08/14 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 26088 163 24X Fiche 30-000,84/08/14.8408160395

- --8408160397 "Design Review of Elliott (node) 906 Tuibacharger Used on TDI DSR-48 & DSRV-16 Energency Dicsel Generator Sets " \* Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp 26088 165 24X Fiche 50-000,84,08/14,8408160395
- 8408270179 Forwards response to 840723 request for addl info on repti submitted by TDI Diesel Cenerator Owners Group RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group 84/08/23 BERLINGER, C Office of Nuclear Reactor Regulation, Director 12pp 26289 221 24x Fiche 50-000.84/08/23.8408290179
- T Hearing transcripts on non-antitrust matters
- B40B020060 Motion for changes to transcript of emergency planning hearing to correct math enjoys ASLB requested to issue order directing that enjdentiary record be amended, incorporating enclichanges

  MC04RRY.J M Duke Power Co DSB 702 B4/07/30 Atomic Safety and Licensing Board Panel 1p 25892 271 24X
  Fiche 50-413,84/07/30. B40B020060
- --8408028066 Errata to transcript of 840501-0608 emergency planning hearing correcting math errors Certificate of Syc encl \* Duke Power Co 84/07/30 23pp 25892 272 24X Fiche 50-413,84/07/30,8408020060
- 8408130360 Transcript of 840808 telcon conference in Bethesda, MD Pp 12:771-12:807 
  \* Atomic Safety and Licensing Board Panel 84/08/08 41pp 26010 074 
  24X Fithe 50-413:84/08/08, 8408130360
- B40B140243 Transcript of 840B10 telcon in Bethesda, MD Pp 12, 808-12, 836 \* Atomic Safety and Licensing Board Panel 84/08/10 3lpp 26055 355 24X Fiche 50-413, 84/08/10, 840B140243
- 8408280205 Testimony of Oil Hallman, RP Muschick, SR Ward, JA Gorman, CA Mells, LA Swanger, SK Chen JO Barbour, JM Curtis & RC Camborg re problems encountered in diesel generator qualification program Related correspondence HALLMAN, 0 W. MUSCHICK, R.P. WARD, S.R. Duke Power Co. DSB 322 84/08/18 444pp 26271 316 24X Fiche 30-413, 84/08/18, 8408280205
- U Congressional/Executive Correspondence
- 8408090508 Responds to 840706 ltr re NRC reply to R Guild.atty for Palmetto Alliance.840527 ltr concerning mod or suspension of facility CP
  DIRCKS,W J Office of the Erecutive Director for Operations 84/07/31 MARTIN.J O House of Rep 2pp 25782 334 24X
  Fiche 50-413.84/07/31.8408090508
- --B407100397 Informs of R Quild of Palmetto Alliance request urging NRC to provide Alliance w/expeditious response to 840627 ltr Progress update & response requested MARTIN.J G House of Rep., Ways and Means 84/07/06 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement App. 25982 341 24X Fiche 50-413.84/07/31.8408990508
- V Operator Examinations
- 8408300375 Forwards summary of 840416 meeting w/util in Region II oft re info developed by NRC re conduct of reactor/senior operator training & recent written license exam Attendance list also enc! O'REILLY, J P Region 2. Office of Director 84/05/09 TUCKER, H E Duke Power Co 5pp 26308 167 24X Fiche 50-413, 84/05/09, 8408300375
- DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1

  F. Becurity, medical, energency & fire protection plans
- 8408280143 Revised emergency plan procedures, including 10-8-01-23 re emergency plan training & drills safety-related.6 2 re alert nonsafety-related & 6 3 re site emergency nonsafety-related W/840820 ttr MURLEY.J Mississippi Power & Light Co 84/07/27 U'REILLY, J P Region 2, Defice of Director 27pp 26279 153 24X Fiche. 50-416, 84/07/27, 8408280143
- 8408080138 Forwards "Orand Gulf Nuclear Power Station Exercise," of offsite radiological emergency conducted on 840411 Meeting held on 840531 u/util & State of MS to discuss deficiency recoordination of issuance of public info KRIMM:R W Federal Emergency Management Agency 84/07/30 URDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 3pp 25960 266 24X Fiche 50-416,84/07/30.84080800138

- --- GAOBC80141 Grand Gulf Nuclear Foust Station Exercise, " conducted on 840411
- B408130335 Advises that 840511 Re. 10 to physical security plan Consistent wyprovisions of 100FR50 51(p) V acceptable L在MIS R C Region 2. Office of Director 84/08/07 DALE, L F 性ississippi Power % Light Co 2pp 26010 323 24X Fiche 50 416 84/08/07.8408130335
- B40B210151 Rev 1 to Vol 10 to Procedure 10-S-01-25. "Onsite Personnel Response" W'840813 ltr
  DALE\_L F Mississippi Power ! Light Co 84/09/13 D'REILLY, J P
  Region 2. Office of Director 9pp 26181 307 24X
  Fiche 50-116 84/08/13.8408210151
- 8408210484 Submits revised commitments & proposed changes to Tech Specs & emergency procedures re-meteorological system NUREG-0654.

  App 2 Quarterly meteorological sensor callor should be performed semiannually

  DALE; LF Hississippi Power & Light Co 84/08/14 DENTON: H R

  Office of Nuclear Reactor Regulation, Director 2pp 26177-358

  24× Fishe 50-416.84/08/14 8408210484
- Ad Judicatory correspondence
- 8408130150 Forwards add1 info re Commission 840717 responses to Guestions 1(B) % 1(F) of EJ Harkey 840313 ltr Add1 info on development of Tech Specs encl
  RICHARD, J.B. Mississippi Power % Light Co. DSB 929 84/07/23 PALLADINO.N J. Commissioners. 20pp. 26010 338 24X Fiche 50-416,84/07/23.8408130150
- 3408010196 Expresses official position of State of LA that decision to lineanse facility should be made by NRC based on safety rules & regulations & scientific findings Representations by EDWARDS.EW Louisiana, State of DSB 483 84/07/2/
  PALLADING, N J Commissioners 1p 25854 353 24X PALLADINO, N J Commissioners | 1 Fiche 50~416,84/07/27,8408010196
- 3408020027 First set of interrogatories to Jacksonians United for Livable Energy Policies Certificate of Svc encl Related

CONTROSPONDENCE
RNOTTG-UB Mississippi Power & Light Co DSB 703 B4/07/30
Jack sonians United for Livable Energy Policies 12pp 25682:
24x Fiche 50-414,84/07/30.8408020027

- 3408030081 Informs that discovery requests not received from Jack sonians United for Livable Energy Policies, per ASLB 840423 order Intervenor withdrawing request for hearing Related correspondence REYNOLDS.NS Bishop Liberman. Cook. Purcell & Reynolds
  REYNOLDS.NS Bishop Liberman. Cook. Purcell & Reynolds
  REYNOLDS.NS Bississipp Power & Light Co. DSB 722 84/08/01
  GROSSMAN.H. CARPENTER.J H. NORRIS.P A Atomic Safety and Licensing
  Board Panel 2pp 25905 361 248 Fiche 50-416.84/08/01.8408030081
- 4080704/7 Status rept advising ASLP of all unresolved matters preparatory to hearing & suggesting date for scheduling final prehearing conference & hearing.in response to 840423 order Certificate of Svc encl Related correspondence YOUNG.fl A Hearing Branch 4 DSB 812 84/08/01 App 28524X Fiche 50-416,84/08/01.84080704/7 25741 200
- 408090145 Responds to 840630 ltr indicating decision against filing formal petition in proceeding Commission authorized issuance of full power license for util at Commission 840731 meeting Served on 840808 MALSCH.M C Office of the General Counsel D88 862 84/08/07 OUSTE.M J Louisiana, State of 1p 25972 292 24X Fichs: 50 416,84/08/07,8408090145
- -8408090154 Informs of decision not to file formal petition THE Ceipt of NRC decumentation of licensee resolution of all safety items Response to MK Udali 840726 ltr requested CUSIE W J Louisiana, State of 84/07/30 PALLADINO, N J Commissioners 2pp 25972 293 24X Fiche 50-416.84/08/07. EL4 OB090145

# General correspondence

408070041 Discusses HRC actions taken to resolve concerns expressed in constituent HC Smith 840518 ltr re NRC licensing procedures, in response to 840531 inquiry Licensing proceeding as expeditiously as possible DIRCKS, NJ Office of the Executive Director for Operations 844077/26 JUNINSTON. J B Senate 5pp 25955 340 24X Fiche 50-416,84/07/26,8408070041

- --B408070048 Forwards constituent UC Smith 840518 ltr unging expeditious licensing of facility Response > comments requested by
  - 84G826 JDNNSTON J B Senate 84/05/31 KAMMERER, C Office Congressional Affairs 7pp 25955 314 24% Fiche 50-84/07/26.8408070041 ex, C Office of 24% Fiche 50-416,
- P Operating license Stage documents & correspondence
- B40B300413 Confirms B40503 telcon re 840510 mgt meeting in Region II oft to discuss depth // scope of GA audit // nuclear plant engineering review or safety issues
  LEWIS, R C Region 2, Office or Director B4/05/04 RICHARD, J B
  Mississippi Pawer & Light Co ip 26308 206 24%
  Fiche 50-416,84/05/04 8408300413
- 8408300371 Forwards summary of 840510 mgt meeting u/util in Region II off he depth % scope of GA audits % safety-helatod engineering evaluations by nuclear plant engineering Attendance list encl D'REILLY, JP Region 2. Office of Director 84/05/25 RICHARD, JB Mississippi Power & Light Co 4pp 26308 240 24X Fiche 50-416, 84/05/25, 8408300371
- 8408300435 Confirms 840606 telcom w/SH Hobbs re 840608 mgt meeting in Region II oft to discuss resolution of Tech Spec questions LEWIS,R C Region 2. Office of Director 84/06/07 RICHARD, J B Hississippi Power & Light Co ip 26314 307 244 Fichs 50-416,84/06/07.8408300435
- B408060174 Forwards results of DBA test & detailed comparison of GE Nine Mile Point qualification requirements vs requirements for util GE safety relief valve solenoid failure inapplicable to Grand Gulf DALE, L.F. Mississippi Power & Light Co. 84/07/30 EISENHUT, D.G. Division of Licensing 7pp 25932 185 24X Fiche 50-416, 84/07/30, RADBOOK 174
- 8408080216 Staff requirements memo re 840731 discussion/possible vate on full power OL in Washington.DC Commission voted 4-0 to outhorize staff to issue full power OL amend CHILK, S.J. Office of the Secretary of the Commission 84/08/01 DIRCKS.W.J. Office of the Executive Director for Operations 1p 25978 326 24X Fiche 50-416.84/08/01,8408080216
- 8408030075 Submits supplemental info in support of util 840728 request for schedular exemption from 10CFR50.App A.GDC 17 for Items II C.D & Ere Divs 1.II it III diesol generators DALE.L F Mississippi Power & Light Co 84/08/02 DENTON.H R Office of Nuclear Reactor Regulation. Director 3pp 25904 355 24X Fiche 50-416.84/08/02.8408030075
- 8408030075 Provides schedule for submittal of turbucharger inlet temp info Installation of temp measuring instrumentation & data retrieval & evaluation uitl be completed by Aug 1984 Results will be submitted uithin 30 days DALE/L F Mississippi Power & Light Co B4/08/02 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 25904 358 24X Fiche 50-416,64/08/02.8408030095
- 8408030103 Forwards addl info re design of combustion air intake & exhaust sys for standby diesel generators Design provides assurance that sys copable of performing function DALE.L F Mississippi Power & Light Co B4/08/02 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 25904 339 24X Fiche 50-416,84/08/02.8408030103
- 8408060249 Forwards supplemental info re standby diesel generator combustion air intake & exhaust system 840802 discussions, superseding info in 840802 itr (AECM-84/0389)

  DALE, L. F. Mississippi Power & Light Co. 84/08/03 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 25933 350 24X Fiche 30-416,84/08/03,8408060249
- 8408070404 Forwards supplemental info re qualification of safety relief valves (SRV). Seitz solenoid valves Interim operation justified until SRV solenoid valves fully qualified per NURGO-0588 % 10CFR50 49

  PALE-L F Mississippi Power & Light Co 84/08/05 DENTGN,H R

  Office of Nuclear Reactor Regulation, Director 5pp 25942 177

  24X Fiche 30-416,84/08/05,8408070404
- 8408070436 Submits clarification re procedural changes concerning diesel generator loading Standby diesel generators will be loaded in excess of 5.740/kW only if action necessary to achieve or maintain plant in safe shutdown condition DALC.L F Mississippi Power & Light Co 84/08/05 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 25742 359 24X Fiche 50-416,84/08/05.8408070436

- 8408070486 Forwards comments on draft Amend 13 to Tech Specs re voorvoord forwards comments on traft Amend 13 to lech Specs re principal gamma emitters.in response to B40803 request for review Amend acceptable RICHARD.J B Mississippi Power & Light Co 84/08/05 DENTON.H Dffice of Nuclear Reactor Regulation. Director 4pp 25940 327 24X Fiche 50-416,84/08/05,8408070486
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of Buppl 1 to NUREO-0933. "Prioritization of Generic Safety Issues " Svc list enci EISENHUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000.84/08/06.8408070110
- B408070430 Submits add1 into requested in NRC 840604 ltr re review assignments & responsibilities for senior reactor operators & description of steps \*aken during Tech Spec review program
  DALE.L F Mississippi Power & Light Co 84/08/06 DENTON.H R
  Office of Nuclear Reactor Regulation, Director 4pp 25940 05:
  R4X Fiche 50-416.84/08/06.8408070430 25940 052
- 8408140116 Forwards "Potential Environ Impact Associated W/Requested Exemptions" re 840728 & 0802 App J & diosel generator electrical protection exemption requests DALE.L F Mississippi Power & Light Co 84708707 DENTON.H R Office of Nuclear Reactor Regulation. Director 11pp 26065 134 24X Fiche 50-416.84708707.8408140116
- 8408230077 Forwards draft Industry Degraded Core Rujemaking Program Technical Rept 23 1. "Sequoyah Nuclear Plant Containment Analysis." For Keeting 3B Rept inconsistent w/four encl repts previously sent FONTANA.M H. Technology for Energy Corp. 84/08/07 DENTON.H R. Office of Nuclear Reactor Regulation. Director 2pp. 26234 001 24X Fichs 50-000.84/08/07.8408230097
- --9408230112 Draft "Evaluation of Containment Bupass & Failure to 108230112 Draft "Evaluation of Containment Bypass & Failut Isolate Sequences for Industry Degraded Core Rulemaking Program Ref Plants." technical rept
  \* Industry Degraded Core Rulemaking Program FAI/84-9 [
  84/07/31 114pp 26234 231 24% Fiche 50-000,84/08/07,8408230097 FAI/84-9\_DRFT
- --8408230119 Draft "Grand Gulf Nuclear Station Integrated Containment Analysis," technical rept # Industry Degraded Core Rulemaking Program 84/08/07 175pp 26235 094 24% Fiche 50-000,84/08/07.8408230097
- 8408300428 Grants 840727 request for extension to 841029 for correction of inproper use of words should & must in plant administrative procedures LEMIS.R C Region 2. Office of Director 84/08/10 DALE.L F Mississippi Power & Light Co 2pp 26314 333 24X Fiche 50-416.84/08/10.8408300428
- 9408150160 Responds to 840808 request for review of proposed Amend 13 to License NPF-13 Schedules consistant w/previous commitments Lists three add) comments RICHARD, J B Mississippi Power & Light Co 84/08/11 NOVAK, T M Assistant Director for Licensing 2pp 26066 314 24X Fiche 50-416.84/08/11.8408150160
- B40BI\$0201 Requests schedular exemption from 10CFR\$0, App J Justification & environ assessment encl DALE.L F Mississippi Power & Light Co 84/08/13 DENTON.H R Office of Nuclear Reactor Regulation, Director 17pp 26066 119 24X Fiche 50-416,84/08/13,840BI\$0201
- 8408150151 Forwards additions to Tech Spec Table 3 8 4 1-1 re primary containment penetration conductor overcurrent protective devices, per 840805 final draft of Amend 13 to License NPF-13
  DALE, L F Mississippi Power & Light Co 84/08/
  Office of Nuclear Reactor Regulation, Director
  Fiche 50-414,84/08/14,8408150151 84/08/14 DENTON.H R rector 1p 26066 316 AIE AADAG 24X
- -8408180154 Additions to Tech Spec Table 3 8 4 i-1 re primary containment penetration conductor overcurrent protective \* Mississippi Power & Light Co 84/08/14 2pp 26066 317 24X Fiche 50-416, 84/08/14, 8408150151
- B40B200275 Generic Ltr 84-20 to all licensess of operating reactors & applicants for OLs re scheduling gustance for licenses submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT, D © Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 179p 26276 244 R4X Fiche: 50-000,84/08/20,8408200275

- 8408310222 Withdraws 840813 request for exemption from requirements of App J to 10CFR50 Updated feedwater isolation valve leak rate test results neet requirements of App J for Types 8 & C DALE, L F Mississippi Power y Light Co 84/08/30 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 26319 257 24X Fiche 50-416.84/08/30.8408310222
- Q Inspection reports: IE Bulletins & correspondence
- 8407950999 JE Info Notice 84-57, "Operating Experience re Moisture Untrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list enc!

  JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24% Fiche 50-000,84/07/27,8407250229
- 8408280137 Responds to IE Bulletin 84-02 re failures of GE Type HFA relays in Class iE safety sys All normally energized safety-related HFA relays w/Lexan coil spools replaced w/Tefrel spools
  MCGAUGHY, J.P. Mississippi Power A. Light Co. 84/07/27
  O'REILLY, J.P. Region 2, Office of Director 3pp. 26279 184 24X
  Fiche 30-416,84/07/27,8408280137
- 8408270257 Ack receipt of 840706 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-417/84-04 LEMISAR C Region 2. Office of Director 84/08/01 DALE.L F Mississippi Power & Light Co 1p 24258 143 24X Fiche 50-417.84/08/01.8408270257
- --8408270268 Forwards Insp Repts 50-416/84-19 & 50-417/84-04 on 840515-16 Lewis, RC Region 2. Office of Director 84/06 Mississippi Power & Light Co 2pp 26258 146 Fiche 50-417, 84/08/01.8408270257 84/04/08 RICHARD J B
- --8408270275 Insp Repts 50-416/84-19 & 50-417/84-04 on 840515-18
  Violation noted failure to control welding in accordance
  w/applicable specs.criteria & other special requirements
  CRONLEY.B R. BLAKE.J J Region 2. Dfice of Director 84/06/04
  10pp 26258 149 24X Fiche 50-417,84/08/01.8408270237
- 8408270313 Ack receipt of 840713 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-416/84-16 LEMIS.R C Division of Project & Resident Programs 84/08/02 DALE.L F Missiasippi Power & Light Co 1p 26257 235 24X Fiche 50-416.84/08/02.8408270313
- --B408270321 Responds to NRC 840614 ltr re violations noted in Insp Rept 50-416/84-16 Corrective actions safety & environ evaluation performed, procedures for work control to be revised & site QA audit rept reviewed DALE.L F Mississippi Power & Light Co 84/07/13 O'REILLY, J P Region 2. Office of Director 10pp 26297 236 24X Fiche 50-416,84/08/02,8408270313
- --8408270326 Forwards Insp Rept 50-416/84-16 on 840326-0427 & notices of violation & deviation LEWIS.R C Division of Project & Resident Pingrams 84/06/14 RICHARD.J B Mississippi Power & Light Co 2pp 26237 246 247 Fiche 50-416,84/08/02.8408270313
- --8408270333 Notice of violation from insp on 840326-0427 \* Region 2, Office of Director 84/06/14 2pp 26 Fiche 50-416,84/08/02,8408270313 26257 24B 24X
- --B408270340 Notice of deviation from insp on 840326-0427.

  \* Region 2, Office of Director 84/06/14 1P 2625
  Fiche 50-416,84/08/02,8408270313 2A257 250 24X
- --B40B270347 Insp Rept 30-416/84-16 on 840326-0427 Violations noted failure to perform procedure change safety evaluation, to follow procedures to provide implementing procedure. to conduct audit & to train technician WAGNER, A G , CALDMELL, J L . CARROLL, R Region 2, Office of Director 84/05/31 12pp 26257 251 24X Fiche 50-416,84/08/02,8408270313
- 840B010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 8470B/06 Consolidated Edison Co. of New York, Inc. 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Mest Efficiency Requirement." Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York. Inc 123pp 24067 158 24X Fiche 50-000.84/08/06.8408010337

- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity 'Sec list encl JORDAN, E. L. Division of Emergency Pieparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York, Inc. 120pp 26127 118 24X Fiche 50-000.84/08/08.8408070120
- 8408070376 IE Into Notice 84-62, "The apy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list encl GRACE, J. N. Division of OA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co. of New York, Inc 125pp 26130 001 24X Fiche 50-000.84/08/10,0408070376
- 8408200225 Discusses Tech Spec errors discovered subsequent to NRC approval Susquehanna Tech Spec amends had no safety significance McGuire Tech Specs still under review w/no identified safety significance thus far ABBELSTINE.J K Commissioners 84/08/10 MARKEY.E J House of Rep. Interior & Insular Affairs 4pp 26141 244 24% Fiche 50-000.84/08/10.8408200225
- --8408200263 Forwards IE Insp Rept 50-416/84-11 on 840328-30 & notice or deviation LEMIS.R C Division of Project & Resident Programs 84/04/24 RICHARD.J B Mississipp. Power & Light Co 2pp 26141 330 24X Fiche 50-000,84/08/10.8408200225
- --B40B200267 Notice of deviation from insp on 840328-30 + Region 2, Office of Director 84/04/24 ip 26141 332 24X Fiche 50-000,84/08/10,8408200225
- --B409200271 IE Insp Rept 50-416/84-11 on 840328-30 Deviation noted no surveillance procedure established to periodically test remote shutdown control components & components not bested since preoperational testing CALDWELL.J L , HEHL.C W , JULIAN.C A Region 2, Office of Director 84/04/24 7pp 26141 333 24X Fiche 50-000,84/08/10,8408200225
- B408280196 Provides supplemental response to IE Bulletin 81-01 Six snabbers reported as having excessive noise during stroke or requiring above average force to complete stroke functionally tested on Bergen-Paterson test machine RICHARD. J B Mississippi Power & Light Co 84/98/10 O'REILLY, J P Region 2. Office of Director 5pp 26275 221 24X Fiche 30-416.84/08/10.8498280196
- 840B100009 IE Info Notice 84~43, "Defective RHR Replacement Piping "

  8vc list enc!
  JURDAN, E. L. Division of Emergency Proparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co. of New
  York, Inc. 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- B408100038 IE Info Notice B4-64. "BWR MPCI Initiation Seal-In & Indication " Svc list encl JBBDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26178 073 24% Fiche 50-000,84/08/15,8408100038
- B408100021 IE Info Notice 84~45, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Syc list encl JURDAN, E.L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021
- 8408240021 Forwards Grand Culf 1984 IE insp repts, ser 840705 request NRC repts on allegations of falsification of training records forwarded to DDJ Rept contents withheld from public disclosure W/o encl
  DEYDUND, R D Director's Office, Office of Inspection and Enforcement 84/08/16 WALDRUM, R L Alaska, State of 4pp 26235 353 24X Fiche 50-000,84/08/16,8408240021
- --B408240026 Requests NRC safety investigation repts for past 8 months & notification of current investigations Info needed to determine possible financial effect on State of AK, which may need to fund & buy energy from facilities WALDRUM, R L Alaska, State of 84/07/05 PALLADIND, N Commissioners ip 26255 354 24X Fiche 50-000,84/08/16, 8408240021
- B40B100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JARDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 consolidated Edison Co of New York, Inc 120pp 26276 001 24% Fiche 50-000.84/08/17.8408100055
- B40B14020B IE Info Notice B4-67, "Recent Snubber Inservice Testing W/ High Failure Rates" Svc list enc! JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/08/17 Consolidated Edison Co. of New York, Inc. 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

- B40B210142 IE info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JGRDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/08/21 Consolidated Edison Co. of New York, Inc. 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142
- R Periodic operating reports & related correspondence
- B40B210105 Monthly operating rept for Jul 1984 W/840B13 ltr CESARE, J G , DALE, L F Mississippi Power & Light Co 84/07/3i DEYQUNG, R C Director's Office Office of Inspection and Enforcement 7pp 261B4 202 24X Fiche 50-416.84/07/31.840B210105
- S Reportable occurrences, LERs & related correspondence
- 8405290062 Forwards "Investigation of Types AF & AE Piston Skirts "
  Rept supercedes 840227 submittal
  RAY.C L TDI (Transamerica Delaval. Inc.) Cwners Group RAY.C L
  Duke Power Co 84/05/24 DENTON.H R Office of Nuclear Reactor
  Regulation. Director 2pp 24690 045 24X Fiche 50-000.84/05/24,
  8405290062
- --8405270075 "Investigation of Types AF & AE Piston Skirts "
  # Failure Analysis Associates FAAA-84~2-14 84/05/23 120pp
  24X Fiche 50-000,84/05/24,8405270062
- 8405270179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations " RAY, C.L. TDI (Transamerica Delaval, Inc.) Guners Group RAY, C.L. Duke Power Co. 84/05/24 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 250 24692 090 24X Fiche 50-000,84/05/24,8403290179
- --8405270271 "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations " \* Failure Analysis Associates FAAA-84-3-16 84/05/22 89pp 24692 092 24% Fiche 50-000.84/05/24.8403270179
- B408060405 forwards repts received by BNML & consultants directly from FaAA & TDI Owners Group at B40622 meeting Draft "Overview of Repts, Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
  ALZHEIMER, J M Battelle Memorial Institute. Pacific Northwest Laboratories 84/06/28 MILLER, M Division of Licensing 158pp 25926 173 24X fiche 50-000,84/06/28,8408060405
- 8408060050 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Generator Duners Group 840622 meeting
  RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group RAY.C L
  Duke Power Co 84/07/10 BERLINGER.C Director's Office, Office of
  Inspection and Enforcement 43pp 25933 133 24X
  Fiche 50-000.84/07/10.8408060050
- 8408090163 Special Rept 84-026/0 on 840613 & 0616-0703, upper control room temp exceeded Tech Spec 11mit of 77 F for 8 h Control room equipment suffered no effects

  DALE.L F Mississippi Pawer & Light Co 84/07/12 D'REILLY, J P Region 2. Office of Director 2pp 25994 324 24X Fiche 50-416,84/07/12,8408090163
- 8408090137 Special Rept 84-027/0 on 840515, fire-rated penetrations AE-2580, AE-2570 & AE-6D opened to implement design change package Seven-day limiting condition for operation time limit exceeded Fire watch established DALE, L.F. Mississippi Power & Light Co. 84/07/18 O'REILLY, J.P. Region 2. Office of Director 1p 25993 162 24X Fiche 50-416.84/07/18.8408090137
- B408060030 LER 84-032-00 on 840628, during reactor vessel nuclear heatup, data taken to determine condensate pot movement on vessel level instrumentation Revised calibr procedures found three transmitters outside Tech Spec limits W/840727 ltr BYRD, R W , DALE, L F Missiasippi Power & Light Ca B4/07/27 3pp 2535 272 24% Fiche 50-414, 84/07/27, 8408060030
- 8408060102 Porwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNWL. RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group RAY.C L Duke Power Co B4/07/27 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 25932 137 24X Fiche 50-000,84/07/27,8408060102
- --840806013B "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review"

  \* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139
  24X Fiche 50-000,84/07/27.8408060102

- 8408060185 Forwards LER 84-031 01 & Rept on Investigation Performed to Determine Unit 1 Dependence on Unit 2 Sys, Structures \$ Concentration
  - DALE/L F Mississippi Pawer / Light Co 84/07/27 Record Services Branch (Document Control Desk) 1p 25935 178 24X Fiche 50-416.84/07/27.8408060185
- --8408060193 LER 84-031-01 on 840601, plant shutdown commenced following notification to NRC or deficiency re low flow rate in standby see water sys due to higher than anticipated frictional pressure drops through component loop BYRD, R W Mississippi Power & Light Co. 84/07/27 2pp 25935 179 24x Fiche 50-416.84/07/27.8408060185
- --8408060200 Rev 2 to "Rept on Investigation Performed to Determine Unit 1 Dependence on Unit 2 Sigs.Structures & Components ' BLACK.K M Mississippi Power & Light Co. 84-N-004 R02 84/07/17 opp 25735 181 24% Fiche 50-416.84/07/27 84080&0185
- 8408130371 Special Rept 84-028/0 on 840627. Div 1 diesel generator tripped of 50% load Caused by grounding of Phase B linear reactor of voltage transformer Div 1 diesel generator A.B & C phase reactors replaced DALE/L F (lississippi Power & Light Co 84/07/27 D'REFLLY, J P Region 2. Office of Director 2pp 26005 300 24% Fiche 50-416/84/07/27.8408130371
- 9408030120 Supplemental RO on 940726, while performing routine maint on Div 1 TDI diesel engine, water observed coming from open cylinder cock on left bank cylinder head 7 Caused by 2-inch crack in right enhaust port casting Head replaced DALE, L.F. Mississippi Power & Light Co. 84/07/30 DENTON, H.R. Office of Nuclear Reactor Regulation. Director 2pp 25916 110 24X Fithe 50-416,84/07/30,8408030120
- 8408130365 Updated Sperial Rept 84-022/1 on 840429.auxiliary main steam tunnel temps exceeded 125 F limit of Tech Spec 3 7 8 Task cards will be issued to track new qualified life of each affected component DALE.L F Mississipp Power & Light Co 84/07/30 O'REILLY, J P Region 2. Office of Director 2pp 26011 089 24X Fiche 50-416.84/07/30,8408130365
- B4080B053B LER 84-033-00 on B40702 reactor scram % secondary containment isolation occurred Caused by closed air dryer outlet valve P53-F496 instructions will be revised to require locked open valve W/840731 ltr BYRD.R W. P84E.L F Nassissapp. Power & Light Co. 84/07/31 3pp 25975 313 24X Fiche 50-416.84/07/31.8408080538
- 8408160421 Final Deficiency Rept PRD-81/17 re flow rate in standby svc water sys loops A & B & loss of standby svc water basin transfer capability Initially reported on 810303 Also reportable per Part 2!

  RICHARD.J B Mississippi Power & Light Co 84/07/31 O'REILLY.J P Region 2. 0ffice of Director Spp 26106 076 24X

  Fiche 50-416.84/07/31.8408160421
- 8408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Bets "
  RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group RAY.C L
  Duke Power Co. 84/08/01 DENIGN.H R. Office of Nuclear Reactor
  Regulation, Director 2pp. 25927-064 24X Fiche 50-000,84/08/01,8408860324
- 8408040189 Confirms completion of listed 840720 & 26 commitments re TDI diesel generators Correction of deficiencies noted during confirmatory walkdown of engine fuel oil lines completed DALE, L. F. Mississippi Power & Light Co. 84/08/03 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 25932 286 24X Fiche 50-416.84/08/03,8408060189
- 8408160061 Final Deficiency Rept PRD-84/10 re possible swelling of QH Bettis valve actuator ethylene propylene rubber elastomer seals in contact u/hydrocorbon lubricant Initially reported on 840730 Reportable under Part 21 for Unit 1
  RICHARD. J B Mississippi Power & Light Co 84/08/03 O'REILLY, J P Region 2. Office of Director Spp 26108 219 24X
  Fiche 50-416,84/08/03,8408160061
- 8408140175 LER 84-024-01 on 840502, shutdown occurred Caused by inoparability of both independent containment spray loops of RHR sys Operating procedures changed & two pipe supports reworked W/840808 ltr
  BYRD.R W. DALE, F Mississippi Power & Light Co 84/08/08 4pp 26108 051 24X Fiche 50-416,84/08/08,8408160175
- 8408160374 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
  RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group RAY.C L
  Duke Power Co 84/08/10 DENTON, H R Office of Nuclear Reactor
  Regulation, Director 2pp 26091 147 24X Fiche 30-000, 84/08/10, 8408160394

- --8408160463 'Design Review of Engine Base's Beating (aps for TDI DSRV-16 Diesel Engines a Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp 26091 149 244 Fiche 50 (CO.84 UB/10.8408160394
- 8408240115 Forwards SEK to [NI Gwners Group program plan SER addresses design review/quality revalidation program testing 5 insp. Maint & surverliance 5 sets forth requirements for operation prior to completion of program plan EISCHHUTLE G Division of Licenting 84/08/13 GEORGE J B 101 (Transamerica Delaval, Inc.) Cuners Group GEORGE J B 101as Utilities Electric Co. Frommitty Trans Utilities Generating Co.) 1p. 26255-194 247 Fichs 50-000,84/08/13.8408240115
- --8408240197 Eafe+y evolvation of TDI Owners Group program plan Based on BNWL evaluation.plan incorporates assential elements mended to resolve outstanding concerns re reliability of TDI engines for nuclear syc some NRC No Detailed Arfiliation civen 84/08/13 Pipp 26255 198 24X Fiche 50-000.84/08/13.8408240115
- 8408160395 Forwards 'Design Review of Elliatt Hodel 908 Turbochardel Used on TDI DSR-48 / DSRV-16 Emergency Diesel Generator Sets." representing final GA verified rept Addl copy forwarded to SNHL, per NRC request RAY, C L TDI (Transamerica Delaval Inc.) Dwneis Group RAY, C L Duke Power Co. 84/0914 DENON.H R Office of Nuclear Reactor Regulation. Director 2pp 26088 163 24X Fiche 50-000.84/08/14, 8808160395
- ~-8408160397 "Design Review of Elliott Model 700 Turbocharger Used on TDI DSR-48 & DSRV-16 Energency Diesel Generator Sets" # Failure Analysis Associates FAAA 84-5-7 84/07/31 6lpp 26088 165 24X Fiche 50-000.68/08/14.8408160395
- 8408240210 LER 84-034-00 on 840719 during nonroutine test reactor protection sys notor generator set A output breake; tripped, resulting in isolation of both shufdown cooling loops Caused by personnel clumsiness Power restored W840820 ltr BYRD.R W. DALE.L.F. Mississippi Power & Light to 84/08/20 3pp 26236 294 24X Fiche 59-416.84/08/20,8408240210
- 8408290179 Forwards response to 840723 request for addl info on repts submitted by TDI Diesel Generator Guners Group RAY, C L. TDI (Transamerica Delaval, Inc.) Owners Group RAY, C L. Duke Power Co. 84/08/23 BERLINGER, C. Defice of Nurlear Reactor Regulation. Director 12pp 26289 221 24X Fiche 50-000, 84/08/23, 8408290179
- 8408300490 LER 84-035-00 on 840519 analyses performed on radioactive gaseous waste samples discovered to be inadequate causing surveillance test frequency to be exceeded Caused by personnel error Software to be modified W/840824 lt; DALELL F. BYRD:R W. Hississippi Power & Light Co. 84/08/24 3pg 26314 086 24x Fiche 50-416.84/08/24,8408300490
- T Hearing transcripts on non-antitrust matters
- 8406220259 Board Notification 84-120 forwards transcripts of 840425, 0502 & 24 meetings w/TDI Owners Group re status of program to establish diesel generator reliability EISENHUT.D C Division of Licensing 84/06/20 PALLADING, OILINSKY, ROBERTS Commissioners 54pp 25206 099 24X Fiche 50-000,84/06/20,8406220259
- B40B130013 Transcript of B40731 open meeting in Washington DC to discussion % vate on full power OL Pp 1-114 Supporting documentation encl # Commissioners 84/07/31 129pp 26059 102 24X Fiche 30~416.84/07/31.8408130013
- U Congressional/Executive Correspondence
- B40B0B0430 Responds to B40B31 ltr Paising concerns re NRC B40522 order & continued lop power operation in spite of outstanding issues of compliance w/ODC 17 Asselstine opinion encl PALLADINO:N J Commissioners B4/07/23 MARKEY,E J House of Rep. Interior & Insular Affairs 3pp 25977 184 24X Fiche 50-416.84/07/23.8408080430
- --B40B0B0432 Expresses concern re NRC apparent abandonment of agency regulations u/licensing of plant Overwhelming weight of evidence treates impression that operation of plant constitutes violation of NRC regulations MARKEY,E J House of Rep Interior & Insular Affairs 84/05/31 PALLADINO. N J Commissioners 2pp 29977 187 24X Fiche 50-416,84/07/23,8408080430

- 8408070201 Responds to 840522 ltr replant problems % estimate of when plant fully operational Commission meeting for briefing 5 possible vote on full-power OL scheduled on 840731
  DIRCKS.W J. Office or the Executive Director for Operations 84/07/27 BETHUNE.E. House of Rep. 3pp. 25937 066—24X
  Fiche 50-416.84/07/27 8408070201
- --B408070207 Requests encl Insert A is minor plant problems not delaying full power licensing be placed in Dircks B40727 ltm dra+t SCINTO. J NRC No Detailed Affiliation Given 84/07/02 ADENSAM, E NRC No Detailed Affiliation Given 3pp 25957 071 24X Fiche 90-416,84/07/27,8408070201
- --8408070215 Requests info re spec > surveillance problems at plant > estimate of when plant will be fully operational BETHUNE.E House of Rep. 84/03/22 PALLADIND.N Commissioners ip 25957 075 24% Fiche 50-416.84/07/27.8408070201
- B40B130202 Responds to B40330 ltm re deficiencies at facility NRC unaware of serious defects at plant Enforcement action still pending re matl false statements in operator records DIRCVS.W J Office of the Executive Director for Operations 84/07/31 ANTHONY, B House of Rep 46pp 26060 166 24X Fiche 50-416.84/07/31.8408130202
- --8408130210 Requests info re deficiencies in design & const of plant & in qualification / training of staff Raises concerns on possibility of higher costs being passed on to constituents ANTHONY, B. Howse of Rep. 84/03/30 PALLADIND, N. J. Commissioners. 4pp. 26060-213 24X Fiche 50-416,84/07/31, BA08130202
- 8408200225 Discusses Tech Spec errors discovered subsequent to NRC approval Susquehanna Tech Spec amends had no safety significance McGuire Tech Specs still under review w/no identified safety significance thus far ASSELSTINE. J K Commissioners 84/08/10 MARKEY. C J House of Rep. Interior & Insular Affairs 4pp 26141 244 24X Fiche 50-000,84/08/10.8408200225
- DDCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2

  A Application/construction stage documents & correspondence
- 8408030104 Forwards summary of environ protection program re const of station for 2-month period ending 840630, per Exhibit 2-A referenced in Subsection 3 C i of CPPR-119

  DALE/L F Mississippi Power & Light Co 84/07/30 DENTON.H R
  Office of Nuclear Reactor Regulation. Director 3pp 25916 084
  24X Fiche 50-417.84/07/30.8408030106
- B4080601/4 Forwards results of DBA test & detailed comparison of OE Nine Hile Point qualification requirements vs requirements for util OF safety relief valve sciencid failure inapplicable to Grand Gulf DALE.L F Mississippi Power & Light Co 84/07/30 EISENHUT, D G Division of Licensing 7pp 25932 185 24X Fiche 50-416.84/07/30.8408060174
- 8408030075 Submits supplemental info in support of util 840728 request for schedular exemption from 10CFR30. App A. GDC 17 for Items II C.D & E re Divs I.fl & III diesel generators DALE.L F Mississippi Power & Light Co 84/08/02 DENTON.H R Office of Nuclear Reactor Regulation. Director 3pp 23904 335 24X Fiche 50-416.84/08/02.8408030075
- B40B030095 Provides schedule for submittal of turbocharger inlut temp info Installation of tomp measuring instrumentation & data retrieval & evaluation uill be completed by Aug 1984 Results will be submitted within 30 days

  DALE.L F Mississippi Power & Light Co 84/08/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 25904 358 24X Fiche 50-416,84/08/02,8408030095
- 8408030103 Forwards addl info re design of combustion air intake & exhaust sys for standby diesel generators Design provides assurance that sys capable of performing function DALE.L. F. Mississippi Power & Light Co. 84/08/02 DENTON, H. R. Office of Nuclear Reactor Regulation. Director 3pp 25904 339 24X Fiche 50-416.84/08/02.8408030103
- 840BO&D249 Forwards supplemental info re standby diesel generator combustion air intake & exhaust sys.per 840BO2 discussions. superseding info in 840BO2 ltr (AECM-84/03B9)
  DALELL F Mississippi Power & Light Co 84/08/03 DENTON.H R
  Office of Nuclear Reactor Regulation. Director 3pp 25933 350
  24X Fiche 50-416.84/04/03.840BO&D249

- 8408370404 Forwards supplemental into re qualification of safety relief valves (ERV). Sett solenoid valves interim operation justified until SRV solenoid valves fully qualified per NUREO-0588 % 10CFR50 49

  DALE-L F Mississippi Power \* Light Co 84/08/05 DENTON, H R Office or Nuclear Reactor Regulation. Director 5pp 25942 177

  24X Fiche 50-416.84/08/05.8408070404
- 8408070436 Submits clarification re procedural changes concerning diesel generator loading Standby diesel generators will be loaded in excess of 5.740/kW only if action necessary to achieve or maintain plant in safe shutdown condition DALE.L F Mississippi Power & Light Co 84/08/05 DENIGN.H R Office of Nuclear Reactor Regulation, Director 2pp 25942 359 24X Fiche 50-416.84/08/05.8408070456
- B40B070486 Forwards commen+s on draft Amend 13 to Tech Specs re principal gamma enitters. In response to 840803 request for review Amend acceptable RICHARD. J B Mississippi Power & Light Co 84/08/05 DENTON.H R Defice of Nuclear Reactor Regulation, Director 4pp 25940-327 24X Fiche 50-416.84/08/05.8408070486
- 8408070110 Generic Ltr 84-19 to all licenses of operating reactors, applicants for DLs & holders of CPs re availability of Suppl I to NUREO-0939. "Prioritization of Generic Bafety Issues "Svc list encl EISENHUT.D G Division of Licensing 84/08/04 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000.84/08/04.8408070110
- B408070430 Submits add1 info requested in NRC 840604 ltr re review assignments & responsibilities for senior reactor operators & description of steps taken during Tech Spec review program

  DALE: L F Mississippi Power & Light Co B4/08/06 DENTON, H R
  Office of Nuclear Reactor Regulation, Director 4pp 25940 052 24X Fiche 50-416,84/08/06,8408070430
- 8408140116 Forwards "Potential Environ Impact Associated W/Requested Exemptions" re 840728 & 0802 App J & dissel generator electrical protection exemption requests DALE, L F Mississippi Power & Light Co 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 11pp 26065 134 24% Fiche 50-416,84/08/07,8408140116
- 8408230097 Forwards draft Industry Degraded Core Rulemaking Program Technical Rept 23 i. "Sequoyah Nuclear Plant Containment Analysis," for Meeting 3B Rept inconsistent w/four encl repts previously sent FONTANAIM H Technology for Energy Corp 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26234 001 24X Fiche 30-000.84/08/07,8408230097
- --B40B230112 Draft "Evaluation of Containment Bypass & Failure to Isolate Sequences for Industry Degraded Core Rulemaking Program Ref Plants." Sechnical rept industry Degraded Core Rulemaking Program FAI/84-9 DRFT B4/07/31 114pp 26234 231 24X Fiche 50-000.84/08/07, B40B230097
- --8408230119 Draft "Grand Gulf Nuclear Station Integrated Containment Analysis." technical rept \* Industry Degraded Core Rulemaking Program 84/08/07 175pp 26235 094 24% Fiche 50-000.84/08/07.8408230097
- 8408300428 Grants 840727 request for extension to 841029 for correction of improper use of words should & must in plant administrative procedures

  LEWIS.R C Region R. Office of Director 84/08/10 DALE.L F Mississippi Power & Light Co 2pp 26314 333 24X

  Ficha 50-416.84/08/10.8408300428
- 8408150201 Requests schedular exemption from 10CFR50.App J Justification & environ assessment encl DALC.L F Mississippi Power & Light Co 84/08/13 DENYON, H R Office of Nuclear Reactor Regulation, Director 17pp 26066 119 24X Firhe 30-416.84/08/13,8408190201
- B408200127 Application to amend CPPR-119, extending latest const completion date to 910430 Fee for Class II CP amend encl RICHARD, J B Mississippi Power & Light Co B4/08/15 DENTON, H R Defice of Nuclear Reactor Regulation
- 8408200275 Deneric Ltr 84-20 to all licensees of operating reactors & applicants for OLs re-scheduling guidance for licensue submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 50-000.84/08/20.8408200275

- 8408310222 Withdraws 840813 request for gremption from requirements of App J to 104FR50 Updated feedwater isolation valve leak rate test results meet requirements of App J for Types 8 & C testing Exemption unnecessary DALE.L F Mississippi Power & Light Co 84/08/30 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 26319 257 24X Fiche 50-416.84/08/30.8408310282
- F Security, medical, emergency & fire protection plans
- 8408280143 Revised emergency plan protedures, including 10-8-01-23 re emergency plan training & drills safety-related, 6 2 re alert nonsafety-related & 6 3 re site emergency nonsafety-related W/840820 itr HURLEY, J Mississippi Power & Light Co 84/07/27 O'REILLY, J P Region 2, Office of Director 27pp 26279 153 24X Ficha 50-416.84/07/27,8408280143
- 8408080130 Forwards "Grand Gulr Nuclear Power Station Exercise," of offsite radiological grergency conducted on 840411 Meeting held on 840531 Jutati & State of MS to discuss deficienty recoordination of issuance of public info KRIMM, R W Federal Emergency Hangsment Agency 84/07/30 JORDAN, EL Division of Emergency Proparedness & Engineering Response (Post 830103) 3pp 25760 266 24% Fiche 50-416,84/07/30,8440800138
- --8408080141 "Grand Gulf Nuclear Power Station Exercise." conducted on 840411 \* Federal Emergency Management Agency 84/04/24 49op 25760 269 24x Fiche 50-416,84/07/30,8408080138
- 8408210151 Rev 4 to Vol 10 to Procedure 10-9-01-25, "Onsite Personnel Response" W/840813 Itr DALE:L F Mississippi Power & Light Co 84/08/13 D'REILLY, J P Region 2. Office of Director 9pp 26181 307 24X Fiche 50-416.84/08/13.8408210151
- G Adjudicatory correspondence
- 840Bi30150 Forwards add1 info re Commission 840717 responses to Guestions 1(B) & 1(F) of EJ Markey 840313 ltr Add1 info on development of Tech Specs encl RICHARD. J B Mississippi Power & Light Co DSE 929 84/07/23 PALLADIND.N J Commissioners 20pp 26010 338 24% Fiche 50-416.84/07/23.840Bi30150
- 840B010196 Expresses official position of State of LA that decision to license facility should be made by NRC based on safety, rules a regulations a scientific findings Representations by state atty general should be disregarded EDNARDS.E W Louisiana, State of DSB 683 84/07/27 PALLADINO.N J Commissioners ip 25054 353 24X Fiche 50-416.84/07/27.8408010196
- B408070477 Status rept advising ASLP of all unresolved matters preparatory to hearing & suggesting date for scheduling final prebearing conference & hearing in response to B40423 order Certificate of Svc encl Related correspondence YOUNG.M A Hearing Branch 4 DSB 812 84/08/01 App 25741 200 24X Fiche 30-416.64/08/01.8408070477
- 8408090145 Responds to 840630 itr indicating decision against filing formal petition in proceeding Commission authorized issuance of full power license for util at Commission 840731 meeting Gerved on 840808
  MALSCHIM 9 Office of the General Counsel DSB 862 84/08/07 GUSTEN J Louisians, State of 1p 25972 292 24X
  Fiche 50-416,84/08/07,8408090145
- --8408090154 Informs of decision nut to file formal petition until receipt of NRC documentation of licensee resolution of all safety items Response to MK Udail 840726 itr requested QUSTE.K J Louisiana, State of 84/07/30 PALLADING, N J Commissioners 2pp 25972 293 24X Fiche 50-416,84/08/07,8408090145
- O Inspection reports, IE Bulletins & correspondence
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc. (1988 25845 047 24X Fiche 50-000, 84/07/27, 8407250229

- B40B2B0137 Responds to IF Bulletin 84-02 re railures of GE Type HFA relays in Class IE safety sys All normally energized safety-related HFA relays w/Lexan coil spools teplaced w/Tefzel spools MCGAUCHY.J F Mississippi Power & Light Co 84/07/27 O'REILLY.J P Region 2, Office of Director 3pp 26275 184 24X Fiche 50-416:184/07/27.8408280137
- 8408270257 Act receipt of 840706 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-417/84-04 LEWIS,R C Region 2. Office of Director 84/08/01 DALE,L F Mississippi Power & Light Co 1p 26258 143 24% Fiche 50-417.84/08/01.8408270257
- --B408270263 Responds to NRC 840608 ltr re violations noted in Insp Rept 50-417/84-04 Corrective actions Bechtel Field Welding Engineering 3: 0C halted work on Field Weld 31 Nonconformance Rept NRC 6784 initiated to track cited condition DALE LF Mississipp Power 2: Light Co. 84/07/06 D'REILLY, J P Region 2: Office of Director 2pp 26258 144 24X Fiche 90-417,84/08/01,8408270257
- --84082/0268 Forwards Insp Repts 50-416/84-19 \$ 50-417/84-04 on 840515-18 & notice of violation
  LEWIS.R C Region 2. Office of Director 84/06/08 RICHARD, J B Mississippi Power & Light Co 2pp 26258 146 24% Fiche 50-417,84/08/01,8408270257
- ~-B408270272 Natice of violation from insp on B40515-18 \* Region 2, Office of Director 84/06/08 ip 26258 148 24Y Fishe 50-417,84/08/01.8408270257
- --840B270275 Insp Repts 50-416/81-19 % 50-417/84-04 on B40515-18
  Violatson noted failure to control welding in accordance
  w/applicable space, criteria & other special requirements
  CROWLEY:0 R . DLAKE. J J Region 2: Office of Director 84/06/04
  10pp 26298 149 24X Fiche 50-417.84/08/01.8408270257
- 8408010333 IE Info Notice 84-99, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN.E L. Division of Emergency Preparedness \* Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of Neu York, Inc. 122pp 26068 001 24X Fiche 50-000,84/08/06.8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list encl JORDAN.C. L. Division of Emergency Preparedness & Engineering Responso (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Natice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Conselidated Edison Co. of New York. Inc. 120pp 26127 118 24X Fiche 50-000,84/08/08.8408070120
- B40B070376 IE Info Notice B4-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list encl ORACE,J N Division of QA, Sareguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24x Fiche 50-000,84/08/10.8408070376
- 840B100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN, E. L. Division of Emergency Preparedness & Engineering
  Response (Post 830[03) 84/08/13 Consolidated Edison Co. of New
  York, Inc. 119pp 26197 218 24X Fiche 50-000,84/08/13,840B100009
- 8408100038 IE Info Natice 84-64, "BUR HPCI Initiation Seal-In & Indication "Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Int 104pp 26198 093 24Y Fiche S0-000,84/08/15,8408100038
- 8408100D21 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list enct JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84708/16 Consolidated Edison Co of New York, Inc. (18pp. 26198 CO) 24X Fiche 50-000,84708/16,8408100021
- 8408240021 Forwards Grand Gulf 1784 IE insp repts, per 840705 request NRC repts on allegations of falsification of training records forwarded to DGJ Rept contents withheld from public disclusure W/o encl
  DEYDUNGER D Director's Office Office of Inspection and Enforcement 84/08/16 WALDRUMER L Alaska, State of App 26255 353 24X Fiche 50-000,84/08/16,8408240021

- --8408240026 Requests MAC sarcty investigation repts for past 8 months & notification of current investigations. Info needed to determine possible financial effect on State of AK, which may need to fund beby onergy from facilities.

  WALDRUM, R. L. Alaska State of 84/07/05 PALLADINO, N. (ammissioners ip 26255 354 24x Fiche 50-000, 84/08/16, 840440021
- 8408100055 IE Into Notice 84-66. 'Undetected Unavailability of Turbing-Driven Auxiliary Feedwater Train " Svt list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 262/6 001 24X Fiche 50-000.84/08/17.8408100055
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list enc! JORDAN,E L Divisson of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24% Fiche 50-000,84/08/17.8408140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc. 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142
- S Reportable occurrences, LERs & related correspondence
- 8405290062 Forwards 'Investigation of Types AF & AE Piston Skirts "
  Rept supercedes 840227 submittal
  RAY.C L TDI (Transamerica Delaval) Inc ) Owners Group 84/05/24
  DENTON, H R Office or Nuclear Reactor Regulation, Director 2pp
  24690 045 24x Fiche 50-000.84/05/24.8405290062
- --8405290075 "Investigation of Types AF & AE Piston Skirts "
  # Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp
  24X Fiche 50-000.84/05/24.8405290062
- 8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shorehar & Grand Gulf Nuclear Power Stations" RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group 84/05/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 24692 090 24% Fiche 50-000,84/05/24,8405290179
- --8408290271 "Evaluation of Emergency Diesel Generator Crankshafts at Shordham & Orand Gulf Nuclear Power Stations " \* Failure Analysis Associates FAAA-84-3-16 84/05/22 89pp 24692 092 24% Fiche 50-000,84/05/24,8403290179
- 8408060405 Forwards repts received by GNHL & consultants directly from FAAA & TDI Owners Group at 840822 meeting Draft "Overview of Repts.Analysis & Recommendations re Main Propulsion Engines M/V Columbta" enci ALZHEIMER.J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER.M Division of Licensing 158pp 25926 173 24x Fiche 50-000.84/06/28.8408060405
- B408060000 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Generator Oungrs Group 840622 meeting RAY.C L TDI (Transamenta Delaval, Inc.) Owners Group B4/07/10 BERLINGER.C Director's Office Office of Inspection and Enforcement 43pp 25903 133 24% Fiche 50-000.84/07/10.
- B408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to DNML RAY.C L. TDI (Transamerica Delayal, Inc.) Owners Group 84/07/27 DENTDN.H R. Office of Nuclear Reactor Regulation, Director 2pp 25932 137 24% Fiche 50-000,84/07/27,8408040102
- --8408060138 "Energency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review "
  \* Stone & Nebster Engineering Corp 84/07/31 36pp 25932 139 24X Fiche 50-000.84/07/27.8408060102
- 8408060185 Forwards LER 84-031-01 & "Rept on Investigation Performed to Determine Unit 1 Dependence on Unit 2 Sys. Structures & Components "

  DALE.L F Mississippi Power & Light Co 84/07/27 Record Services Bianch (Document Control Desk) 1p 25935 178 24X Fiche 50-416.84/07/27.8408060183
- ---8408060200 Rev. 2 to "Rept on Investigation Performed to Determine Unit 1 Dependence on Unit 2 Sys. Structures & Components " BLACK, K M Mississippi Power & Light Co. 84-M-004 RO2 84/07/17 6pp 23935 181 24% Fiche 50-416,84/07/27,8408060185

- 8408030120 Supplemental RO on 840726 while performing rautine maint on Div I 1DI diesel engine, water observed coming from open cylinder cock on left bank cylinder head 7 Caused by 2-inch crack in right exhaust poit casting Head replaced DALE/L F Mississippi Power 2 Light Co 84/07/30 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 25916 110 24X Fiche 50-416,84/07/30,8408030120
- 840B160421 Final Deficiency Rept PRD-81/17 re flow rate in standby svc water sys loops A 5 B & loss of standby svc water basin transfer capability initially reported on 810303 Also reportable per Part 21 RICHARD. J B Mississippi Power & Light Co 84/07/31 D'REILLY, J P Region 2, Office of Director 5pp 26106 076 24X Fiche 50-416,84/07/31.840B160421
- 8408050324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DERV-12-4 % DERV-20-4 Emergency Diesel Generator Bets " RAY, C L TDI (Transamerica Delaval, Inc.) Gwners Oroup 84/08/01 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 25727 064 264 Fiche 50-000.84/08/01.8408060324
- 8408060189 Confirms completion of listed 840720 & 26 commitments re TDI diesel generators Correction of deficiencies noted during confirmatory walkdown of engine fuel oil lines completed DALE, L.F. Mississippi Power & Light Co. 84/08/03 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 25732 286 24X Fiche 50-416,84/08/03,8408060187
- 8408160061 Final Deficiency Rept PRD-84/10 re possible swelling of OH Bettis valve actuator ethylane propylene rubber elastomer seals in contact Whydrocarbon lubricant Initially reported on 840730 Reportable under Part 21 for Unit i RICHARD. J B Mississippi Power & Light Co 84/08/03 D'REILLY. J P Region 2. Office of Director Spp 26108 217 24X Fiche 50-416.84/08/03.8408160051
- B40B160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines " RAY, C L TDI (Transamerica Delava), Inc.) Owners Group B4/08/10 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 26091 147 24X Fiche 50-000, B4/08/10, 840B160394
- ~-8408160403 "Design Revieu of Engine Base & Bearing Caps for TDI DBRV-16 Diesel Engines " \* Failure Analysis Associates FAAA-84~6-53 84/08/31 44pp 26071 149 24X Fiche 30-000,84/08/10.8408160394
- 8408240115 Forwards SER re TD1 Owners Group program plan SER addresses design review/quality revalidation program testing & insp. maint & surveillance & sets forth requirements for operation prior to completion of program plan EISENHUT, D © Division of Licensing 84/08/13 GEORGE, J B TDI (Transamerica Delavai, Inc.) Owners Group 1p 26255 194 24X Fiche 30-000,84/08/13,8408240115
- --840B240157 Safety evaluation of TDI Owners Group program plan Based on BNWL evaluation.plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc 4 NRC No Detailed Affiliation Given 84/08/13 21pp 26255 193 24% Fiche 50-000.84/08/13.8408240115
- B40Bi40375 Forwards "Design Review of Elliott Model 900 Turbocharger Used on TDI DER-48 & DERV-16 Emergency Diesel Generator Sets," representing final QA verified rept Addl copy forwarded to BNNL.per NRC request RAY, C.L. IDI (Transamerica Delaval. Inc.) Quiners Group B4/OB/14, DENTON:HR Office of Nuclear Reactor Regulation, Director 2pp 26088 163 24X Fiche 50-000,84/08/14,840B160375
- --8408160397 "Design Revieu of Elliott Model 906 Turbocharger Used on TDI DSR-48 & DSRV-16 Energency Diesel Generator Sets " \* Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp. 26088 165 24X Fiche 50-000.84/08/14.8408160395
- B40B290179 Forwards response to 840723 request for additinfo on repts aubmitted by TDI Diesel Generator Owners Group RAY, C.L. TDI (Transamerica Delaval, Inc.) Owners Group 84/08/23 BERLINDER.C. Office of Nuclear Reactor Regulation, Director 12pp 26289 221 24X Fiche 50-000.84/08/23.8408290179
- U Congressional/Executive Correspondence
- 8408080430 Responds to 840531 ltr raising concerns re NRC 840522 order & continued law power operation in spits of outstanding issues of compliance w/oDC 17 Asselstine opinion encl PALLADINO.N J Commissioners 84/07/23 MARKEY.E J House of Rep , Interior & Insular Affairs 3pp 25977 184 24X Fiche 50-416.84/07/23.8408080430

- ~-8408080432 Expresses concern re NRC apparent abandonment of agency regulations u/licensing of plant Overwhelming weight of evidence creates impression that operation of plant constitutes violation of NRC regulations

  MARKEY.E J House of Ref Interior 5 Insular Affairs PALLADIMO.N J Commissioners 2pp 25777 187 24X

  Fiche \$0-416.84/07/23.8408080430
- 840807020; Responds to 840922 ltr re plant problems & estimate of when plant fully uperational Commission meeting for briefing & possible vote on full-power (N. scheduled on 840731 DIRCKS.W J Office of the Executive Director for Operations 84/07/27 BETHUNE. House of Rep. 3pp. 25957 066 24X Fiche 50-416.84/07/27.8408070201
- ~-8408070215 Requests info re spec & surveillance problems at plant & estimate of when plant will be fully operational BETHUNE.E House of Rep 84/03/22 PALLADING.N Commissioners 1p 29757 075 24X Fiche 50-416.84/07/27.840807020;
- DOCKET 50-423 MILLSTONE NUCLEAR POWER STATION. UNIT 3

  A Application/construction stage documents / correspondence
- 8408070220 Forwards FSAR Table 3 98-98 he loading combinations for ASME III Class i,2 & 3 component supports, per 840713 telcon commitment to provide add1 info Table will be incorporated in FSAR amend COUNSIL, 8 G. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNSIL, W.G. Northeast Utilities Service Co. (subs. of Northeast Utilities) 84/07/20 YOUNGBLOOD, B.J. Licensing Branch 1 3pp. 25948 323 24X Fiche 50-423,84/07/20,8408070270
- 840B090082 Forwards add1 info in response to NRC 840619 request re Amend 2 to probabilistic safety study CDUNSIL.W G . SEARS, C F . Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G . Northeast Utilities 84/07/31 YDUNG9L00D.B J Licensing Branch 1 50pp 25973 017 24X Fiche 50-423.8407/31.8408090032
- ~-B408090092 "Sensitivity of Seismic Hazard Results at Millstone to LLL Study Assumptions on Attenuation & Seismicity Final Rept to Northeast Utils " \* Dames & Hoare 84/06/15 45pp 25973 067 24X Fiche 50-423,84/07/31,8408090082
- 840B090497 Summary of 840717 meeting w/Hestinghouse Owners Stram Opnerator Tube Rupture Subgroup in Bethesda MD re proposed steam generator tube rupture generic program List of attendees & vieugraphs encl SINGH, B K Licensing Branch 3 84/07/31 Licensing Branch 3 18pp 25983 130 24% Fichs 50-000.84/07/31,8408090497
- 8408070438 Notification of 840807 meeting w/util & SMA in Bethesda, MD to discuse confirmatory program status re setsmic capability beyond design basis DODLITTLE.E L. Licensing Branch 1 84/08/02 YOUNGBLOOD, B J Licensing Branch 1 4pp 25982 356 24X Fiche 50-423, 84/08/02,
- 8408070110 Generic Ltr 84-19 to all licensess of operating reactors, applicants for CLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Generic Safety Issues " Svc list encl EISENHUT,D 9 Division of Licensing 84/08/04 Conselidated Edison Co of New York, Inc 18pp 24127 238 24X Fiche 50-000.84/08/06.8408070110
- 8408200533 Forwards request for add) info re equipment qualification program Completed master equipment list should be submitted 6 w/s before audit & 85% of all safety-related equipment installed & qualified 70UN08LOD,8 J Licensing Branch i 84/08/07 CDUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 27pp 26143 291 24X Fiche 50-423,84/08/07,8408200533
- 1408200306 Requests plans for assuring that facility designed & constructed in accordance w/FSAR commitments Response requested within 60 days of itr date EISENHUT. DG Division of Licensing 84/08/13 COUNSIL, WG Northeast Nuclear Energy Co (subs of Northeast Utilities) 2p. 26141 242 24X Fiche 50-423,84/08/13,8408200306
- 8408240222 Forwards request for info to be included in program to determine capability of facility to withstand seismic excitation above design SSE YOUNOSLOOD, B. J. Licensing Branch 1 84/08/15 COUNSIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 52pp 26251 233 24X Fiche 50-423,84/08/15,8408240222

- 8408200275 General Lit 84-20 to all licensees of operating reactors & applicants for OLs re-scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions S c list end EISENHUT, D G Division of Licensing 84/08/20 Consulidated Edison Co of they work inc 17pg 26276 244 21X Fiche 50-000,84/08/20 8108200275
- B40B30001/ Requests add1 into be design of ASME Code.Class 1.2 & 3 component supports Enri evaluation describes review of component support design & clarities staff position on issues that require fulther justification of YOUNOBLOOD.B J Licensing Blanch 1 84/08/23 COUNSIL.W 0 Northeast Muclear Energy Co (subs of Northeast Utilities) 13pp 24331 327 24x Fiche 50~423 04/08/23,8408J00017
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8408010129 Forwards DES (NJREG-1064) % notice of availability for Millstone 3 Comments due within 45 days after publication of FR notice of issuance W/o NUREG YOUNGBLOOD, B J Licensing Branch 1 84/07/24 Connecticut, State of 2pp 25873 313 24x Fiche 50-423.84/07/24.8408010129
- --8408010131 Notice of availability of DES (NUREG-1064) for Millstone 3 YDUNGBLODD O J Licensing Branch ! 84/07/24 2pp 25873 315 24X Fiche 50-423,84/07/24,8408010129
- B408010197 Forwards DES (NURIG-1064) & FR notice of issuance W/o NUREC YQUNGBLOOD, B J Licensing Branch ! B4/07/24 COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp 25873 272 24x Fiche 50-423 84/07/24.8408010197
- B40B010252 Forwards DES (NUREO-1064) » FR notice of availability, for review & comment Comments due within 45 days after publication in FR W/o NUREG YOUNGBLOOD. B J Licensing Branch 1 84/07/24 WOOD, J K Commerce, Dept nf, Natl Oceanographic Admospheric Administration 6pp 25872 331 24% Fichs 50-423,83/07/24,840B010252
- 8408020140 Forwards FR notice of issuance 2 DES (NUREC-1064 )W/o DES YOUNGBLOOD, B J Licensing Branch 1 84/07/24 HIRSCH, A Environmental Protection Agency 2pp 25898 091 24X Fiche 50-423.84/07/24,8408020140
- 8408010148 DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF MILLSTONE NUCLEAR POWER STATION UNIT 3 DOCKET NO 50-423 (NORTHEAST NUCLEAR ENERGY COLMANY st al)

  \* Division of Licensing NUREG-1064 84/07/31 339pp Available at NRC 48 00 25871 012 24% Fiche 50-423,84/07/31.8408010148
- 8408230187 Orfers no comments on DES re CL issuance MIRANGSWALJ A Agriculture, Dept of 84/08/17 YOUNGBLOOD, B J Licensing Branch i 1p 26209 214 24X Fiche 50-423, 84/08/17, 8408230189
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8408140242 SAFETY FVALUATION REPORT RELATED TO THE OPERATION OF MILLBIONE NUCLEAR POWER STATION. UNIT NO 3 Docket No 50~424 (Northeast Nuclear Energy Company) \* Division of Licensing NUHED-1031 84/07/31 591pp Available at NRC \$11 00 26121 001 24% Fichs 50~423.84/07/31.8408140242
- 8408090323 Forwards SER re util application for OL Fewer than 20 open items; summarized in SER, remain unresolved W/g entl NDVAK, T M Assistant Director for Licensing 84/08/01 EBERSULE, J C ACRS Advisory Committee on Reactor Safeguards 3pp 25984 344 24% Fiche 50-423,84/08/01,8408090323
- 8408190526 Forwards NURFO-1031, "SER re Operation of Millstone Nuclear Power Station, Unit 3" YOUNGBLOOD, B.J. Licensing Blanch 1 84/08/02 COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 454pp 26094,167 24X Fiche 50-4F2,84/08/02,8408150526
- 8408200469 Forwards SEN (NUREG 1031) re operation & FR notice of availability W/o SER
  YOUNGBLOOD.B J Licensing Branch 1 94/08/13 COUNSIL, W G
  Northeast Nuclear Energy Co (subs of Northeast Utilities) 3ps
  26143 336 24% Fiche 50-423.84/08/13,8408200469
- --8408200471 Notice of availability of SER (NURCO-1031)
  YOUNGBLOOD, D. J. Licensing Branch 1 84/08/13 2pp 26143 357
  24% Fiche 50-423,84/09/13,8408200469

- 8401210339 Forward Interpolation of FR open little ne internally generated missile from insafety-related equipment \* effect on safety-related equipment interpolated little COUNSIL. No. Northeast Nuclear Energy to tooks of Northeast Utilities) COUNSIL N.G. Northeast Utilities 84/08/14 YOUNCHLOOP 8 J. Licensing Branch 1 Spp. 26177 258 24X Fiche 50-423 84/02/14 8408210339
- B408280258 Forwards plant-specific procedures for estimating core damage as required by NUREG-0737. Hem II B 3 Criterion 2, per SER confinatory item.
  COUNSIL W G. FEE. W.F. him theas: Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL W G. Northeast Utilities. 84/08/16.
  YDUNGBLOOD, B. J. Licensing Branch 1 Pep. 26.62 070 24X
  Fiche 50-423,84/08/16.8408287278
- ---8408280262 Re. O to Emergency Plan Implementing Procedure EPIP 4226:
  "Unit 3 Core Damage Estimate Procedure"

  MRCCZMA.C J Northeast Nuclea: Energy Co (subs of Northeast Utilities) 84/08/16 26pp 26262 072 24X

  Fithe 50-423 84/08/16.8408280258
- 8408280159 Forwards response to SER Open Item 2 re adequacy of tornado missile protection for emergency diesel generator stacks, per NRL 840802 submittal COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities 84708/20 YOUNGELOUDS J Licensing Branch 1 7pp 262/5 081 24X Fiche 50-423.84 08/20.8408280159
- F Security, medical, emergency & fire protection plans
- 8408280258 Forwards plant-specific protedures for estimating core damage as required by NUREC-0707. Item II B 3.Critorion 2. per EER confirmatory item COUNSIL W 6. FEE,W F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL W 6. Northeast Utilities 84/08/16 YOUNGBLOOD, B J. Licensing Branch 1. 2pp. 26262 070 24X Fiche 50-423,84/08/16,8408280258
- --8408280262 Re O to Emergency Plan Implementing Procedure EPIP 4226.
  "Unit 3 Core Danage Estimate Procedure"
  MRDCZMA.E J Northeast Nuclear Energy Co (subs of Northeast
  Utilities) 84/08/16 26pp 26262 072 24X
  Fiche 50-423
- D Advisory Committee on Reactor Safeguards reports & correspondence
- 8408310227 Transcript of ACRG Subcommittee on Reliability & Probabilistic Assessment 840827 weeling in Windson Locks, CT Pp 1-230 Supporting documentation enci \* ACR6 Advisory Committee on Reactor Sateguards 84/08/28 321pp 26319 281 24X Fiche 50-423, 84/08/28, 8408310327
- O Inspection reports: IE Bull-tims & correspondence
- 8407250229 IE Into Notice 81-57. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JDRDAN.C L. Division of Emergency Preparedness % Engineering Response (Post 830103) 94-07-27 consolidated Edison Co. of New York, Inc. 119pp 25865-047 24% Fische 50-000.84/07/27.8407250229
- B40B100116 Responds to IC Bulletin B3-07, "Apparently Flaudulent Products Sold by Ray Miller, Inc " Entry & engineering avaluation for Millstone Unit 2 will be done by Feb 1985 refueling outage No Ray Miller products supplied at Haddam COUNSIL. & G , SEARS.C F Northeast Nuclear Energy Co (subs of Northeast Utilities) SEARS.C F Connecticut Yankee Atomic Power Co 84/07/31 MURLEY.T E Region 1, Office of Director 3pp 25788 247 24% Fiche 50-000, H4/07/31, 840B100116
- 8408010333 IE Info Notice 84-59. 'Deliberate Circumventing of Station Health Physics Procedures '5 vc list encl JURDAN, E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 12-2pp 26048 001 24% Fiche 50-000,84/08/06,8408010333
- 8408310337 IE Info Notice 81-60, 'Failure of Air Purifying Respirator Filters to Mest Efficiency Paquirement " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26057 158 24% Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR
  Refueling Cavity " Svc list encl
  JORDAN.E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/08 Cansolidated Edison Co of New
  York, Inc 120pp 26127 118 24X Fishe 50-000,84/08/08.8408070120

- 84087/03/6 IE Info Notice 84-62 Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments 'Svc list enc) GRACLUTI Division of QA Sareguards & Inspection Programs (Post 830103) 84/08/10 Compolidated Edison Co of New York, Inc 125pp 26130 031 24x Fishe 50-000/84/08/10,8408070376
- 8408290003 Forwards lnsp Rept 50-423/84-08 on 840520-0707 No violations noted STARGSIECKI,R Division of Piaject / Resident Piograms 84/08/10 COUNSIL.W Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26298 241 24X Fiche 50-423.84/08/10.8408290003
- --8408270007 insp Rept 50-423/84-08 on 640520-0707 No vielations noted Major areas inspected document control.plant maint, training of test personnel.observation of electrical & hydrostatic testing & flushing program & unauthorized duct mod REBELOURI, T.A. ROBERISON, J. Region 1. Office of Director ELSASER, T. Division of Project & Resident Programs 84/08/07 13pp 26278 243 24X Fiche 50-423,84/08/10.8408270003
- 8408100009 IE Info Notice 84-63. "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84708/13 Consolidated Edison Co of New
  York Inc 119pp 26197 218 24X Fiche 50-000.84708/13.8408100009
- 8408100038 IE Info Notice 84-64. "BWR HPC1 Initiation Seal-In & Indication " Svc list encl JCRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York. Inc 104pp 26/98 093 24X Fichs 50-000,84/08/15,8408100038
- 8408100021 IE Info Notice 84-45, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list enci JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc. 118pp 26198 001 24X Fiche 50-000.84/08/16, 8408100021
- 8408100055 IE Info Notice 84-66. "Undotected Unavailability of Turbine-Driven Auxiliary Foedwater Train " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post E330103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276-001 24X Fiche \$0-000.84/08/17.8408100055
- 8408140208 IE Info Notice 84-6/, "Recent Snubber Inservice Testing W/ High Failure Rates " Syc list encl JORDAN,C L Division of Emergency Preparedness & Engineering Rosponse (Post 833103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Into Notice 84-68, "Potential Deficiency in Improperly Rated Field Hiring to Bolenoid Valves " Svt list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc. 113pg 26327-008 24X Fiche 30-000,84/08/21,8408210142
- S Reportable occurrences, LERs & related correspondence
- 8408100064 Patential significant deficiency mept re NAMCO Model EA-180 limit switches provided as accessories on valves supplied by Pacific Valves & Fisher Controls Initially reported on 840131 Next mept expected by 841023 COUNBIL, W.G. SEARS, C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities.) COUNBIL, W.G. Northeast Utilities. 84707/17 MURLEY, T.E. Region 1. Office of Director. 3pp. 20790 172 24X Fiche 50-423,84707/17,8408100064
- T Hearing transcripts on non-antitrust matters
- B40B310227 Transcript of ACRS Subcommittee on Reliability & Probabilistic Assessment B40B27 meeting in Windsor Locks.CT Pp 1-230 Supporting documentation encl \* ACRS Advisory Committee on Reactor Safeguards 84/08/28 321pp 26319 281 24X Fiche 50-423.84/08/28.8408310227
- DOCKET 50-424 VOOTLE ELECTRIC GENERATING PLANT

  A Application/construction stage documents & correspondence
- 8408300346 Forwards summary of 840627 meeting w/util in Atlants,OA reprogram to acquire operating experience for cold license candidates Attendance list & agenda encl LEWIS.R C Region 2. Office of Director 84/07/23 KELLY,R J Consumers Power Co 10pp 26308 220 24X Fiche 50-474 84/07/23,8408300366

- 8408090497 Summary of 840717 meeting w/Westinghouse Cumers Steam Generator Tube Rupture Subgroup in Bethesda.MD re proposed steam generator tube rupture generic program List of attendees & vieugraphs encl SINGN.B K Licensing Branch 3 84/07/31 Licensing Branch 3 18pp 25983 130 24X Ficha 50-000.84/07/31.8408090497
- 8408130412 Responds to request for info re archaeological & historical resources Repts identify sites which may be eligible for nomination for inclusion in Natl Register of Historic Places Rept withheld (ref 10CFR2 790) FOSTER D 0 Georgia Power Co 84/08/03 ADENSAM E C Licensing Branch 4 2pp 26011 097 24% Fiche 50-424.84/08/03.8408130412
- 8408070;10 Generic Ltr 84-19 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of Suppl 1 to NUREG-0933. "Prioritization of Generic Safety Issues " Svc list encl EISENHUT.D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26/29/238 24X Fiche 50~000.84/08/06.8408070110
- B40B130494 Advises that util in process of developing evaluation of environ impact of routing transmission line across Ebenezer Creek area Evaluation util be submitted by 840B22 Clearing in area util not be done until evaluation reviewed FOSTER, D G Georgia Power Co B40B708 ADENSAM, E G Licensing Branch 4 2pp 26079 186 24X Fiche 50-424.84/08/06.840B150494
- 8408170301 Forwards results of confirmatory lab testing program for Category 1 backfill.described in util 840613 ltr & results of onsite soil testing FOSTER.D O Georgia Power Co 84/08/10 ADENSAM.E G Licensing Branch 4 106pp 26115 130 24X Fiche 50-424.84/08/10.6408170301
- 8408200275 Generic Ltr 84-20 to all litensees of operating reactors & applicants for GLs re scheduling guidance for licensee submittals of reloads that involve Unreviewed safety questions Svc list encl
  EISENHUT, D @ Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
  Fiche 50-000.84/08/20.8408200275
- 840B2B0208 Forwards "Vogtle Electric Generating Plant Units 1 & 2. Ebenezer Creek Swamp - Evaluation of Transmission Line Crossing "NRC review of evaluation requested within 30 days FOSTER.D D Occupia Power Co 84/08/24 ADENSAM.E 0 Licensing Branch 4 2pp 26264 037 24X Fiche 50-424.84/08/24.8408280208
- --84082802i3 "Vogtle Electric Generating Plant Units i & 2.Ebenezer Creek Swamp - Evaluation of Transmission Line Crussing " \* Georgia Power Co 84/08/24 27pp 26264 039 24X Fiche 50-424,84/08/24.8408280208
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8408310448 Advises that draft SER input due to project manager by B41001 as indicated in review schedule attached to D Eisenhut 831127 meno Input to project manager must include vehicle for CRESS to access SER mat! ADERISAM. E G Licensing Branch 4 84/08/24 BOSNAK, R Machanical Engineering Branch REITER. L Geosciences Branch BALLARD. R Environmental & Hydrologic Engineering Branch 2pp 26348 358 24% Fiche 30-424.84/08/24.8408310448
- F Security, medical, emergency & fire protection plans
- 8408300376 Forwards summary or 840530 meeting u/utils & INPO re selected emergency preparedness issues Attendance list also ancl O'REILLY, J P Region 2, Office of Director 84/06/08 KELLY, R J Georgia Power Co 4pp 26308 257 24X Fiche 50-000, 84/06/08, 8408300376
- 8408300344 Ack receipt of 840703 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-424/84-09 & 50-425/84-09

  DANCE P C Division of Project & Resident Programs 84/07/19

  KELLY R J Georgia Power Co ip 26308 343 24X
  Fiche 50-424.84/07/19,8408300344
- --8408300346 Responds to NRC 8406il ltr re violations noted in Insp Repts 50-424/84-09 & 50-425/84-09 Corrective actions procedure for documentation of surveillance insp on fire uater protection sus uill be revised/implemented by 840801 FOSTER.D D Georgia Power Co 84/07/03 LEWIS.R C Region 2, Office of Director 3pp 26308 344 24X Fiche 50-424.84/07/19, 8408300344

- 8408060003 Forwards Amend 1 to physical security plan & nuclear training & qualification plan Amends withheld (ref 10CFR2 790)
  FOSTER, D 0 Georgia Power Co 84/07/31 ADENSAM, E G Licensing Branch 4 1p 25933 185 24% Fiche 50-424,84/07/31,8408060003
- G Adjudicatory correspondence
- 8408010189 Forwards Encl 2 to staff response to ASLB 840712 ltrentitled. "Interin Position on Charleston Earthquake for Licensing Proceeding "accidentally omitted from original submitted Related correspondence PERLIS.R O Hearing Branch 2 DSB 686 84/07/26 MARGULIES,M B . LINENBERGER.G. PARIS.O H Atomic Safety and Licensing Board Panel 4pp 25855 159 24% Fiche 50-424.84/07/26.8408010189
- 8408010253 Response to ASLB 840712 inquiry whether NUREG/CR-3756 constitutes substantial new info to lead to redatermination of adequacy of seismic design Inquiry fully warranted Certificate of Syc encl
  JOHNBON.T Campaign for Prosperous Georgia DSB 664 84/07/26
  17pp 25854 324 24X Fiche 50-424,84/07/26,8408010253
- 8408010267 Informs of withdrawal of Contention CPO-9, based upon review of Westinghouse proprietary rept re mod of primary loop sys Related correspondence FOWLER, L. Legal Environmental Assistance Foundation FOWLER, L. Campaign for Prosperus Ocorgia DSB 657 B4/07/26 MARQULIES, M. B., LINENBEROER, G., PARIS, D.H. Atomic Safety and Licensing Board Panel 2pp 29854 069 24X Fiche 50-424, 84/07/26, 8408010267
- H General correspondence
- 8408010336 Authorizes WT Nickerson to sign future NRC correspondence which does not require signature of duly authorized util officer
  FDSTER.D 0 Ceargia Power Co 84/07/23 ADERSAM, E 0 Licensing Branch 4 1p 25866 074 24x Fiche 50-424, 84/07/23, 8408010336
- G Inspection reports, IE Bulletins & correspondence
- 8408310419 Confirms 840507 telcon re 840518 meeting to discuss status of insp program for diesel generators LEWIS.R C. Region 2. Office of Director 84/05/16 KELLY.R J. Georgia Power Co. lp. 26335 023 24X Fiche 50-424,84/05/16,8408310419
- 8408310405 Forwards summary of 840918 meeting re insp program for diasel generators Meeting beneficial & provided better understanding of issues LEWIG.R C Region 2: Office of Director 84/06/12 KELLY, R J Ocorgia Power Co 3pp 26333 315 24X Fiche 50-424,84/06/12,8408310405
- B408270408 Forwards Insp Repts 50-424/84-15 & 50-425/84-15 on 840619-22 No violations or deviations DANCE.H C Division of Project & Resident Programs 84/07/12 KELLY,R J Georgia Power Co 2pp 26256 275 24X Fichs 50-424.84/07/12,8408270408
- --B40B270414 Insp Repts 50-424/84-15 & 50-425/84-15 on 840619-22 No violations or deviations noted Major areas inspected unresolved items, licensee identified items, It bulletin, electrical components & sys work & work activities GIBBONS, T D. CONLON, T E. Region 2. Office of Director 84/07/10 5pp 26236 297 24% Fiche 50-424,84/07/12,8408270408
- 8408270342 Forwards Insp Repts 50-424/84-16 & 50-425/84-16 on 840514-0625 No violations or deviations noted DANCE.H C Division of Project & Resident Programs 84/07/1 KELLY.R J Georgia Power Co 2pp 26257 214 24X Fiche 50-424.84/07/17.8408270342
- --B40B27035; Insp Repts 50-424/84-16 & 50-425/84-16 on B40514-0625 No violations or deviations noted Major areas inspected diesel generator verification program kVAC support program & Unit 2 primary containment & Unit ; containment BANDERS.W F. PANCIERA,V Region 2. Office of Director 84/07/16 5pp 26257 216 24X Fiche 50-424.84/07/17,8408270342
- 8408300344 Ack receipt of 840703 ltr informing NRC of steps taken to correct violations noted in lnsp Repts 50-424/84-09 & 50-425/84-09 DANCE, H C Division of Project & Resident Programs 84/07/19, KELLY, R J Georgia Power Co ip 26508 343 24X Fiche 30-424,844/07/19,8408300344

- --8408300346 Responds to NRC 840511 ltr re violations noted in Insp Repts 50-424/84-09 & 50-425/84-09 Corrective actions procedure for documentation of surveillance insp on fire water protection sys uill be revised/implemented by 840801 FOSTER.D 0 Georgia Power Co 84/07/03 LEMIS,R C Region 2, Office of Director 3pp 26308 344 24X Fiche 50-424,84/07/19, 8408300344
- 8408240365 Ack receipt of 840711 ltr informing NRC of steps taken to correct violations noted in Insp Repts 30-424/84-11 % 50-425/84-11 LEWIS.R C Region 2. Office of Director 84/07/24 KELLY.R J Georgia Power Co ip 26237 094 24X Fiche 50-424,84/07/24, 8408240365
- --8408240367 Responds to NRC ltr re violations noted in Insp Repts 50~424/84-11 & 50~425/84-11 Corrective actions sys being developed for areas of plant which will provide controls as implemented in control room area FOSTER, D.O. Georgia Power Co. 84/07/11 LEWIS, R.C. Region 2, Office of Director 2pp. 26237 095 24X Fiche 50~424, 84/07/24, 84/08240365
- --8408240368 Forwards Insp Repts 50-424/84-11 & 50-425/84-11 on 840413-0514 & notice of violation LEWIS,R C Region 2, Office of Director 84/06/14 KELLY,R J Georgia Power Co 2pp 26237 097 24X Fichs 50-424,84/07/24, 8408240365
- --8408240370 Notice of violation from insp on 840413-0514 \* Region 2, Office of Director 84/06/14 ip 26237 099, 24X Fiche 50-424,84/07/24,8408240365
- --8408240371 Insp Repts 50-424/84-11 & 50-425/84-11 on 840413-0514 Violation noted failure to protect electrical equipment during installation SANDERS, W.F., PANCIERA, V.W. Region 2, Office of Director 84/06/07 Spp 26237 100 24X Fiche 50-424,84/07/24,8408240365
- 8408270429 Ack receipt of 840710 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-424/84-10 & 50-425/84-10 DANCE.H C Region 2. Office of Director 84/07/25 KELLY,R J Georgia Power Co ip 26257 031 24X Fiche 50-424,84/07/25,840H27829
- --8408270430 Responds to NRC 840511 ltr re violations noted in Insp Repts 30-424/84-10 & 50-425/84-10 Corrective actions formal training program for contract QC inspectors developed & implemented in Apr 1984
  FOSTER, D O Quergia Power Co 84/07/10 LEWIS, R C Region 2, Office of Director 3pp 26237 032 24X Fiche 50-424,84/07/25, 8408270429
- --8408270433 Forwards Insp Repts 50-424/84-10 & 50-425/84-10 on 840501-04 & notice of violation DANCE,H C Division of Project & Resident Programs 84/06/11 KELLY,R J Georgia Pouer Co 2pp 26257 035 24X Fiche 50-424,84/07/25,8408270429
- --B408270436 Notice of violation from insp on 840501-04 \* Region 2, Office of Director 84/06/11 2pp 26257 037 24X Fiche 50-424.84/07/25,8408270429
- --840B270440 Insp Repts 50-424/84-10 & 50-425/84-10 on 840501-04 Violation noted training provided electrical contract GC inspectors informal & did not assure that suitable proficiency achieved on site procedures RUFF, A B , MERRIWEATHER, N , CONLON, T E Region 2, Dffice of Director 84/06/07 9pp 26257 039 24X Fiche 50-424,84/07/25,8408270429
- 8407250229 IE Info Notice 84-57. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc. 119pp 25865-047 24X Fiche 30-000/84/07/27,8407250229
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JURDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/04 Consolidated Edison Co of New York, Inc 123pp 26067 158 24% Fiche 50-000,84/08/06,8408010337

- 8408070120 IE Info Notice 84-61, "Gverexposure of Diver in PWR Refueling Cavity ' Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fiche 50-000,84/08/08,8408070120
- 840B070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list encl GRACE.J N Division of GA. Safeguards & Inspection Programs (Post S33103) 84/08/10 Consolidated Edison Co of New York. Inc 125pp 26130 031 24x Fiche 50-000.84/08/10.8408070376
- 840B100009 IE Info Natice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN,E L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc. 119pp 26197 218 24X Fiche 50-000.84/08/13,8408100007
- 8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl JDRDAN,E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc. 104pp 26178 093 244 Fiche 50-000,84/08/15,8408100038
- B40B100021 IE Info Notice B4-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/08/16 Consolidated Edison Co of New York, Inc. 118pp 26178 001 24X Fiche 50-000.84/08/16.840B100021
- B40B100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list ancl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- B408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc 122pp 26274 122 24X Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000.84/08/21,8408210142
- S Reportable occurrences, LERs & related correspondence
- 8405290062 Forwards "Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal RAYLC L TDI (Transamerica Delaval, Inc.) Owners Group 84/05/24 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 24690 045 24X Fiche 50-000,84/05/24,8405290062
- --8405290075 "Investigation of Types AF & AE Piston Skirts "
  \* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp
  24X Fiche 50-000,84/05/24,8405290062
- 8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Noclear Power Stations" RAY.C.L TDI (Transmerica Delaval, Inc.) Dwners Group 84/05/24 DENTON:HR Office of Nuclear Reactor Regulation, Director 2pp 24692 090 24X Fiche 50-000:84/05/24,8405290179
- 8408040405 Forwards repts received by BNWL & consultants directly from FAAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts, Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
  ALZHEIMER. J M Battelle Memorial Institute, Facific Northwest
  Laboratories 84/06/28 MILLER.M Division of Licensing 158pp
  25726 173 24X Fiche. 50-000.84/06/28,8408060405
- B40B060030 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Generator Guners Group B40622 meeting RAY.C. L TDI (Transamentca Delaval, Inc.) Owners Group B4/07/10 BERLINGER,C Director's Office. Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50-000,84/07/10, B40B0600000
- 8408090023 Interim significant deficiency rept re lack of full penetration welds on Pullman Const Industries duct supports Initially reported on 840614 Next rept will be submitted by 840829 FOSTER, D.O. Georgia Power Co. 84/07/13 O'REILLY, J.P. Region 2. Office of Director 2pp. 25992 094 24% Fiche 50-424, 84/07/13. 8408090023

- B40B 360102 Forwards Energency Clearl Manetator Auxiliary Module Control Mining / Terrinarion Gual fication Review " Addl copies sint to DMM RAYLO L TOL (Transamenica Detain) Inc. / Duners Group B4/07/27 DENTON-HR Office or Moulous Reactor Regulation Dijector 2pp 25932 137 264 Fiche 50-Co. 24 077 B445040102
- --8408060138 'Energency Diest) Generator Austliary Module Control Uiting & Termination Qualification Review '
  \* Stone 'Nubsker Engineering Gorp 64 0''31 36pp 25932 139 24X Fiche 50-000 84/07/27 8408060102
- B408060324 Forwards 'Design Reliew of Elliatt Model 656 Turbocharger Used on TDI DBRV-12-4 | DBRV-23-4 Emergency Diesel Generator Bets "
- Bets "RAY,C L TDI (Transamerica Delaval: Inc.) Guners Group 84/08/01 BENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 25727-064 24% Firhe 50-000 84/08/01.8408060324
- B408160394 Forwards "Design Review of Engine Base ? Bearing Caps for TDI DSRV-16 Diesel Engines " RAY, C. L. TDI (fransarerica Delaval Inc.) Owners Group B4/0B/10 DENTON, H. Office or Nuclear Reactor Regulation, Director 2pp 26091 147 24X Fiche 50-000,84/0B/10.B408140394
- --8408160403 Design Review of Engine Base A Bearing Caps for TDI DBRV-16 Diesel Engines ' \* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp 26091 149 24X Fiche 50-000.84/08/10.8408160394
- 8408240115 Forwards SEN re TDI Owners Group program plan SER addresses design review/quality revalidation program testing & insp. maint & surveillance 'sets Forth requirements for operation prior to completion of program plan EISENHUT, D.G. Division of Licensing 84/08/13 GEORGE, J. B. TDI (Transamerica Delaval, Inc.) Gwners Group ip 26255 194 24X Fiche 50-Cuv.84/08/13.8408240115
- --8408240157 Safety evaluation of TDI Owners Oroup program plan Based on BNML evaluation.plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc.

  \* NRC No Detailed Affiliation Given 84/08/13 2ipp 26255 175 24X Fiche 50-003.84/08/13.8408240115
- 840B160395 Forwards "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets." representing final GA verified rept Addi copy forwarded to BIML.per NRC request RAY.C L TDI (Transamerica Delaval, Inc.) Dwners Group 84/08/14 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 260B6 163 24X Fiche 50-000,84/08/14.8408160395
- --8408160397 "Design Revieu of Elliatt Model 900 Turbocharger Used on TDI DSR-48 % DSRV-16 Energency Diesel Generator Sets " \* Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp 26088 165 24X Fiche 50-000.84/08/14.8408160395
- 8408270179 Forwards response to 840723 request for addition on repts submitted by TDI Diesel Generator Dwners Group RAY.C L TDI (Transamerica Delaval) Inc J Dwners Group 84/08/23 BERLINGER.C Office of Nuclear Reactor Regulation, Director 12pp 24289 221 24X Fiche 50-000.84/08/23/8408270179
- 840B2B0152 PNO-II-84-055 on B40B23.util announced that seven employees dismissed due to alleged unauthorized bid disclosures in procurement of small tools / expendable const supplies Dealings w/one vendor terminated PANCIERA, V , DAYGE. H C Region 2. Office of Director 84/08/24 ip 26274 309 24X Fiche 50-424.84/08/24,840B280152
- JCKET 50-425 VOGILE ELECTRIC GENERATING PLANT
  Application/construction stage documents & correspondence
- B408090497 Summary of B40717 meeting w/Westinghouse Owners Steam Generator Tube Rupture Subgroup in Bethesda.MO re proposed steam generator tube rupture generic program List of attendees & viewgraphs encl BINOH.B K Licensing Branch 3 84/07/31 Licensing Branch 3 18pp 25983 130 24X Fiche 50-000,84/07/31,8408090497
- 840B130412 Responds to request for info re archaeological & historical resources Repts identify sites which may be eligible for numination for inclusion in Natl Register of Historic Places Rept withheld (rer 10CFR2 790)
  FOSTER.D D Georgia Power Co 84/08/03 ADENSAM.E G Licensing Branch 4 2pp 26011 087 24X Fiche 50~424,84/08/03,840B130412

- 84083/0110 Deneric Lit 84-19 to all linemaces of operating reactors, applicants for OLs tholous of Price anisolity of Supplit to Describe Price intration of Genetic Satety Issue: 'L. listent EISFMHUT to Division of Licensing 84/08/06 Consolidated Edison Color New York Inc. 18pp. 26129-238 24X Fiche 50 000-84/08/06
- 8408150491 Advises that uril in process or developing evaluation of environ impact of routing transmission line across Ebenezer Creek area Evaluation will be submitted by 840822 Clearing in area will not be done until evaluation reviewed FOSTER, D.O. Georgia Power to 84708706 ADEMSAM.E.G. Licensing Branch 4 app. 24077186 24X Fiche 50-421,84708706.8408150494
- B40B170J01 Forwards results of confirmatory lab testing program for Category 1 backfill, described in util 840613 ltr % results of onsite soil testing FOSTER, D.O. Georgia Power (o. B1/08/10 ADENSAM, E.G. Licensing Branch 4 106pp 20115 130 24X Fiche 50-424,84/08/10,8408170301
- 84082002/5 Generic Ltr 84-20 to all licensees of operating reactors & applicants for QLs re-scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encil EISCNHUT.D G Division of Licensing 84/08/20 Consolidated Edison Co of New York Inc. 17pp 26276-244 24X Fichs 50-000 84/08/20 8498200275
- 8408280208 Forwards "Vogtle Circtric Generating Plant Units 1 & 2, Ebeneze: Croek Swamp Evaluation of Transmission Line Crossing 'NRC review of evaluation requested within 30 days FDSTEK, D O Georgia Power Cu 84/08/24 ADENSAM.E G Licensing Branch 4 2pp 26/24/03/ 24/Fiche 50-424.84/08/24,8408280208
- --8408260213 "Voqtie Electric Generating Plant Units 1 & 2.Ebenezer Creek Suamp - Evaluation of Transmission Line Crossing " # Georgia Poue; Co 84/08/24 2/pp 26264 037 24X Fithe 50-421,84/08/24.8408280808
- E NRC Safety Evaluation Report (SER), suppls % correspondence
- 840B310448 Advises that draft SER input due to project manager by B41001 as indicated in review schedule attached to D Eisenhut 83129 meno input to project manager must include vehicle for CRESS to access SER matl ADENSAM.EG Licensing Branch 4 84/08/24 BOSNAK,R Mechanical Engineering Branch REITER.L Geosciences Branch BALLARD.R Environmental & Hydrologic Engineering Branch 2pp 26348 358 24% Fiche 50-424.84/08/24.8408310448
- F Security, medical, emergency \* fire protection plans
- 8408300376 Forwards summary of B40530 meeting w/utils & INPO re selected emergency preparedness issues Attendance list also enc! O'REILLY, J P Region P, Office of Director 84/06/08 KELLY, R J Georgia Power Co 4pp 26308 257 24X Fiche 50-000, 84/06/08, 8408300376
- 8408300344 Ack receipt of 840703 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-424/84-09 % 50-425/84-09 DANCE-IR C Division of Project % Resident Programs 84/07/19 KELLY, R J Georgia Power Co ip 26308 343 24X Fiche 50-424.84/07/19.8408300344
- --8408300346 Respunds to NRC 840611 ltr re violations noted in Insp Repts 50 424/64-09 % 50-425/84-09 Corrective actions procedure for documentation of surveillance insp on fire water protection sys will be revised/implemented by 840801 FOBTER.D D Georgia Power Co 84/07/03 LEWIS,R C Region 2, Office of Director 3pp 26308 344 24X Fiche 50-424,84/07/19, 8408300344
- 8408060003 Forwards Amend i to physical security plan & nuclear training A qualification plan Amends withheld (ref 10CFR2 790) FOSTCR: D O Georgia Power Co 84/07/31 ADENSAM, E Q Licensing Branch 4 1p 25933 185 24X Fiche 50-424.84/07/31,8408060003
- G Adjudicatory correspondence
- 840B010189 Forwards Encl 2 to staff response to ASL8 B40712 ltr entitled, "Interin Position on Charleston Earthquake for Licensing Proceeding," accidentally mmitted from original submittal Related correspondence PERLIS.R G Hearing Branch 3 D88 686 84/07/26 MARGULIES,M B , LINENBERGER, G , PARIS.O H Atomic Safety and Licensing Board Panel 4pp 29855 159 24% Fiche 50-424,84/07/26,840B010189

33

## DOCKETED ITEMS

- 8408010253 Response to ASLB 840/12 inquiry whether NUREG/CR-3756 constitutes substantial new info to lead to redetermination of adequacy of seismic design Inquiry fully warranted Certificate of Sic encl JOHNSON, T. Campaign for Piosperous Georgia DSD 664 84/07/26 17pp 25854 324 244 Fiche 50-424, 84/07/26, 8408010253
- 8408010267 Informs of withdrawal of Contention CPG-9, based upon review of Westinghouse proprietary rept re mod of primary loop sys Related correspondence FOWLER.L Legal Environmental Assistance Foundation FOWLER.L Campaign for Prosperous Georgia DSB 657 84/07/26 MARGULIES.M B , LINENGERGER G , PARIS.D H Atomic Safety and Licensing Board Panel 2pp 25854 069 24X Fiche 50-424.84/07/26.8408010267

#### H General correspondence

- B40B010336 Authorizes MT Nickerson to sign future NRC correspondence which does not require signature of duly authorized util officer FDSTER.D 0 Georgia Pouer Co 84/07/23 ADERSAM; E G Licensing Branch 4 ip 23866-074 24X Fiche 50-424.84/07/23,8408010336
- G Inspection reports: IE Bulletins & correspondence
- B40B310419 Confirms B40507 telcon re 840518 meeting to discuss statum of insp program for diesel generators
  LEWIS.R C Region 2. Office of Director B4/05/16 KELLY.R J
  Georgia Power Co 1p 26335 023 24X Fiche 50-424,84/05/16,
  B40B310419
- 8408310405 Forwards summary of 840518 meeting re insp program for diese) generators Meeting beneficial & provided better understanding of issues LENIEs C Region 2. Office of Director 84/06/12 KELLY, R J Georgia Power Co 3pp 26333 315 24X Fiche 50-424,84/06/12,8400210008
- 8408270408 Forwards Insp Repts 50-424/84-15 & 50-425/84-15 on 840619-22 No violations or deviations DANCC.H C Division of Project & Resident Programs 84/07/12 KELLYR J Georgia Pouer Co Zpp 26256 295 24X Fiche 50-424,84/07/12 8408270408
- --B40B270414 Insp Repts 50-424/84-13 & 50-425/84-15 on B40619-22 No violations or deviations noted Major areas inspected unresolved items. Licensee identified items. Eb bulletin, electrical components & sys work & work activities GIBBONS.T D . CONLON.T E Region 2. Office of Director 84/07/10 5pp 26256 297 24X Fiche 50-424.84/07/12.840B270408
- 8408270342 Forwards Insp Repts 50-424/B4-16 & 50-425/B4-16 on B40514-0625 No violations or deviations noted DANCE.H C Division of Project & Resident Programs B4/07/17 KELLY,R J Georgia Power Co Rpp 26257 214 24X Fiche 50-424,84/07/17,8408270342
- --8408270351 Insp Repts 50-424/84-16 & 50-425/84-16 on 840514-0625 No violations or deviations noted Major areas inspected diesel generator verification program, NUAC support program & Unit 2 primary containment & Unit 1 containment SANDERS, W. F., PANCIERA, V. Region 2, Office of Director 84/07/16 Spp 26257 216 24% Fiche 50-424,84/07/17,8408270342
- 8408300344 Ack receipt of 840703 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-424/84-09 & 50-425/84-09

  BANCE:H C Division of Project & Resident Programs (KELLY:R J Georgia Pouer Co 1p 26308 343 24X Fichs 50-424:84/07/19.8408300344
- --8408300346 Responds to NRC 840611 ltr re violations noted in Insp Repts 50-424/84-07 & 50-425/84-09 Corrective actions procedure for documentation of surveillance insp on fire water protection sys will be revised/implemented by 840801 FOSTER.D O Georgia Fower Co 84/07/03 LEWIS.R C Region 2, Office of Director 3pp 26308 344 24X Fiche 50-424,84/07/19, 8408700344
- B408240365 Atk receipt of 840711 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-424/84-11 & 30-425/84-11 LEWIS.R C Region 2. Office of Director 84/07/24 KELLY.R J Georgia Power Co ip 26237 094 24X Fiche 50-424.84/07/24, 8408240365

- --B40B240367 Responds to NRC ltr re violations noted in Insp Repts 50-424/84-11 & 50-425/84-11 Corrective actions sys being developed for areas of plant which will provide controls as implemented in control room area FOS1ER.D O Georgia Power Co 84/07/11 LEWIS.R C Region 2. Office of Director 2pp 26237 095 24X Fichs 50-424, 84/07/24, 8408240365
- --8408240368 Forwards Insp Repts 50-424/84-11 & 50-425/84-11 on 840413-0514 & notice of violation LEMIS.R C Region 2. Office of Director 84/06/14 MELLY.R J Georgia Power Co 2pp 26237 097 24X Fiche 50-424,84/07/24,8408240365
- --B40B240371 Insp Repts 50-424/84-11 & 50-425/84-11 on B40413-0514 Violation moted failure to protect electrical equipment during installation SANDERS.W F., PANCIERA.V W. Region 2, Office of Director B4/06/07 5pp 26237 100 24% Fiche 50-424.84/07/24/8408240365
- 8408270429 Ack receipt of 840710 ltr informing NRC of steps taken to correct violations noted in lnsp Repts 30-424/84-10 & 50-425/84-10
  DANCE,H C Region 2, Office of Director 84/07/25 KELLY,R J Georgia Power Co 1p 26257 031 24% Fiche 50-424,84/07/25, 8408270429
- --8408270430 Responds to NRC 840611 lkr re violations noted in Insp Repts 50-424/84-10 & 30-425/84-10 Corrective actions formal training program for contract GC inspectors developed & implemented in Apr 1984 FOSTER, D D Georgia Power Co 84/07/10 LEWIS, R C Region 2, Office of Director 3pp 26257 032 24X Fiche 50-424, 84/07/25, 8408270429
- --8408270433 Forwards Insp Repts 50-424/84-10 & 50-425/84-10 on 840501-04 & notice of violation DANCE.H C Division of Project & Resident Programs 84/06/11 KELLY.R J Georgia Power Co 2pp 26257.035 24X Ficho 50-424,84/07/25,8408270429
- --8408270436 Notice of violation from insp on 840501-04 \* Region 2, Office of Director 84/06/11. 2pp 26257 037 24X Fichs 50-424,84/07/25,8408270429
- --8408270440 insp Repts 50-424/84-10 & 50-425/84-10 on 840501-04 Violation noted training provided electrical contract GC inspectors informal & did not assure that suitable proficiency achieved on site procedures RUFF.A B / MERRIWEATHER.N / CONLON.T E Region 2, Office of Director 84/05/07 9pp 26257 039 24X Fiche 50-424.84/07/25, 8408270429
- B407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commencial Poucer Plants "Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/07/27 Consolidated Edison Co of New York, Inc 119pp 25845 047 24X Fiche 30~000.84/07/27.8407250229
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures "Svc list enc!
  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/04 Consolidated Effson Co. of New York, Inc. 122pp 24068 001 24X Fiche 30-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PHR Refueling Cavity " Svc list encl, JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York Inc 120pp 26129 118 24X Fiche 50~000,84/08/08.8408070120
- 8408070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Syc list encl GRACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fichs 50-000.84/08/10.8408070376
- 8408100009 IE Info Notice 84-53, "Defective RHR Replacement Piping "
  Bvc list encl
  JDHDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009.

- 8408100038 IE Info Notice 84-64. "BWR HPCI Initiation Seal-In & Indication "Syc list encl JORDAN,E & Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 25193 093 24% Fiche 50-000.84/08/15.8408100038
- 840Bi00021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl

- 8408100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc. 120pp 26276 001 24X Fiche 50-000:84/08/17.8408100055
- 8408140208 IE Info Notice 84-67. "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- BAOB210142 IE Info Notice BA-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York Inc 115pp 26329 008 24X Fiche 50-000.84/08/21.8408210142

#### S Reportable occurrences. LERs & related correspondence

- 8405270062 Forwards "Investigation of Types AF & AE Piston Skirts"
  Rept supercedes 840227 submittal
  RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group 84/05/24
  DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp
  24690 045 24X Fiche 50-000,84/05/24,8405290062
- ---8405290075 "Investigation of Types AF & AE Piston Skirts "
  Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp 24% Fiche 50-000,84/05/24,8405290062
- 84Q5290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shorehan & Grand Gulf Nuclear Power Stations" RAY.C L TDI (Transamerica Delaval, Inc.) Duners Group 84/05/2 DENTONH R Office of Nuclear Reactor Regulation, Director 2pp 24692 090 24% Fiche 50-000.84/05/24,8405290179
- 8408060405 Forwards repts received by BNWL & consultants directly from FaAA & TDI Gwners Group at 840622 meeting Draft "Overview of Repts. Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
  ALZHEIMER.J M Battelle Memorial Institute, Pacific Northwest
  Laboratories 84/06/28 MILLER.M Division of Licensing 198pp
  25926 173 24X Fiche 50-000.84/06/28.8408060405
- 840B060050 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Generator Owners Group 840622 meeting RAY.C L TDI (Transamerica Delaval. Inc.) Owners Group 84/07/10 BERLINGER.C Director's Office. Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50-000.84/07/10.
- 8408090023 Interim significant deficiency rept re lack of full penetration welds on Pullman Const Industries duct supports Initially reported on 840614 Next rept will be submitted by 840829 FOSTER, D.O. Georgia Power Co. 84/07/13 O'REILLY, J.P. Region 2, Office of Director 2pp 25992 094 24% Fiche 50-424, 84/07/13, 8408090023
- 8408060102 Forwards "Emergency Diesel Generator Auxiliary Module
  Control Wiring & Termination Qualification Review " Addl
  copies sent to BNNL
  RAY.C L TDI (Transamerica Delavel, Inc.) Owners Group 84/07/27
  DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
  25938 137 24X Fiche 50-000.84/07/27.8408060102
- --B408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review"

  \* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139 24X Fiche 50-000.84/07/27.8408060102
- B4OB060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets " RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group B4/08/01 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 25927 064 24% Fiche 50-000.84/08/01.8408060324

- 8408160394 Forwards 'Design Review of Engine Base ' Hearing Caps for TDI DERV-16 Diesel Engines " RAY.C.L. TDI (Transamerica Delaval, Inc.) Owners Group 84/08/10 DENTON.H R. Diffice of Nuclear Reactor Regulation, Director 2pp 26091 (47 24x Fiche 30-000.84/08/10,8408160394
- --8408160403 'Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines " \* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp 26091 149 24X Fiche 30-000.84/08/10.8408160394
- 8408240J15 Forwards SER TO TO Comers Group program plan SER addresses design review/quality revalidation program, resting & insp. maint & surveillance & sets forth requirements for operation prior to completion of program plan EISENHUT, D © Division of Licensing 84/08/13 GEGROE, J B TDI (Transamentica Delaval, Inc.) Omers Group 1p 26255 194 24X Fiche 50-000,84/08/13,8408240115
- --B408240157 Safety evaluation of TDI Comers Group program plan Based on BNM. evaluation, plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc \* NRC - No Detailed Affiliation Given 84/08/13 21pp 26255 195 24% Fiche 50-000,84/08/13,8408240115
- 8408160375 Forwards "Design Review of Elliott Model 906 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets." representing final GA verified rept Addl Copy forwarded to BMHL per NRC request RAY.C L TDI (Transamerica Delaval. Inc.) Owners Group 84/08/14 DENTON.H R Dfire of Nuclear Reactor Regulation, Director 2pp 26088 163 24X Fiche 50-000,84/08/14,8408160375
- --B408160397 "Design Review of Elliott Model 906 Turbocharger Used on TDI DBR-48 & DBRV-16 Energency Diesel Generator Sets " \* Failure Analysis Associates FAAA-84-5-7 B4/07/31 6ipp 26088 165 24% Fiche 50-000,84/08/14,8408160395
- 8408290179 Forwards response to 840723 request for add) info on repts submitted by TDI Diesel Generator Owners Group RAY.C.L. TDI (Transamerica Delaval. Inc.) Duners Group 84/08/23 BERLINGER, C. Office of Nuclear Reactor Regulation, Director 12pp 26289 221 24X Fiche 50-000.84/08/23,8408290179
- 8408280152 PNO-II-84-055 on 840823, util announced that seven employees dismissed due to alleged unauthorized bid disclosures in procurement of small tools & expendable const supplies Dealings w/one vendor terminated PANCIERA, V, DANCE, H C, Region 2. Office of Director 84/08/24 ip 26274 309 24% Fiche 50-424.84/08/24.8408280152
- DOCKET 50-433 UC-SANTA BARBARA RESEARCH REACTOR

  G Inspection reports, IE Bulleting & correspondence
- 840Bi30091 Ack receipt of 840713 ltr informing NRC of steps taken to correct violations noted in JE insp rept
  WENSLAMSKI.F A Region 5. Office of Director 84/08/07 KROES.R J
  California. Univ of. Santa Barbara. CA 1p 26010 040 24X
  Fiche 50-433.84/08/07.8408130091
- --8408130094 Responds to NRC 840706 ltr re violations noted in IE insprept Corrective actions application for operator requalification submitted 2 written 5 operating exam will be administered in Aug KRCES.R J California, Univ of Santa Barbara, CA 84/07/13 YUHAS.G P Region 5, Dffice of Director 1p 26010 041 24X Fishe 50-433, 84/08/07, 8408130091

## V Operator Examinations

- 8408130091 Ack receipt of 840713 ltr informing NRC of steps taken to correct violations noted in IE insp rept
  WENSLAWSKIF A Region 5. Office of Director 84/08/07 KRUES,R J
  California. Univ of. Santa Barbara. CA lp 26010 040 24X
  Fiche 50-433.84/08/07.8408130091
- --B408130094 Responds to NRC B40706 ltr re violations noted in IE insp rept Corrective actions application for operator requalification submitted & written & operating exam will be administered in Aug KRDES.R J California, Univ of, Santa Barbara, CA 84/07/13 YUHABI.0 P Region 5, Office of Director ip 26010 041 24X Fiche 50-433,84/08/07,8408130091

DOCKET STM-50 437 FLOATING NUCLEAR PLANT

- A Application construction stage documents & correspondence
- B40B370i10 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders or CPs re availability of Suppl 1 to NUREO-0933. Prioritifation of Generic Bafety Issues "Svc list encl EISENHUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York. Inc. 189p 26129 238 24% Fiche 50-000 84/08/06 8408070110
- 8408200275 Generic Lir 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT.DG Division of Licensing 84/08/20 Consolidated Edison Co of New York. Inc. 17pp 26276-244 24% Fiche 50-000.84/08/20,8408200279
- @ Inspection reports. IE Dulletins & correspondence
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, EL Division of Emergency Pieparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24% Fiche 50-000,84/07/27,8407250229
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24% Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/04 Consolidated Edison Co of New York, Inc 123ep 26057 158 24X Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list enc! JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York: Inc 120pp 26129 118 24X Fiche 50-000.84/08/08.8408070120
- B408070376 IE Info Notice 84-42. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list encl GRACE.J N Division of QA, Safeguards & Inspection Programs (Post B30103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000.B4/08/10.B408070376
- 8408100009 IE Info Notice 84-63. "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830109) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000.84/08/13,8408100009
- ### B40B100038 | F. Info Notice 84-64, "BWR HPC! Initiation Seal-In & Indication "Syc list encl

  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) ### 84/08/15 Consolidated Edison Co. of New York, Inc. 104pp 26198 093 24% Fiche 50-000,84/08/15,8408100038
- B40B100021 IE Inro Notice B4-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021
- 8408100053 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Syc list encl JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York: Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- 8408140208 IE Info Notice 84-67. "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New Yor: Inc 122pp 24276 122 24% Fiche 50-000.84/08/17.8408140208
- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Salenoid Valves " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21. Consolidated Edison Co. of New York, Inc. 115pp 26327 008 24X Fiche 50-000,84/08/21,8408210142

- DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

  A Application/construction stage documents & correspondence
- 8408030155 Uncoments K Mali 840628 telcon w/C Stable advising that review of tube rupture analysis using RELAP 5 computer code, per TMI Action Item (I K 3 5. "Automatic Trip of Reactor Computer Pump," unli be delayed (info expected by 841115 MILLS, L M Tennessee Valley Authority 84/07/27 ADENSAM, E Operating Reactors Branch 4 1p 25912 015 24X Fiche 50-438,84/07/27,8408030155
- B408080288 Summary of 840712 meeting w/B&W Owners Group to non-nuclear instrumentation sys status Attendance list & viowgraphs encl KADAMBI.P Operating Reactors Branch 4 84/07/27 Operating Reactors Branch 4 84/07/27 Operating Reactors Branch 4 36pp 25978 228 24X Fiche 50-000.84/07/27, RADRORDERS
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for QLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl EISENHUT.D © Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26127 238 24X Fichs 50-000,84/08/06,8408070110
- Fichs 30-000,84/08/06.8408070110

  8408270098 Forwards response to MRC B31229 1tr re TDI emergency diesel
- produzivoro rorwands response to NRC B31229 ltr re TDI emergency diese generators includes procurement & performance specs & insp results SHELL.R H Tennessee Valley Authority B4/0B/17 ADENSAM,E O Licensing Branch 4 167pp 26248 052 24X Fiche S0-438,84/08/17, B408270098
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT, D 0 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 50-000.84/08/20,8408200275
- Q Inspection reports. IE Bulletins & correspondence
- 8408280100 Forwards supplemental response to 18 Bulletin Bi-O3 re flow blockage of cooling water to safety sys components by Corbicula Sp (Asiatic clam) & Mytlius Sp (mussel) MILLS;L M Tennessee Valley Authority 84/07/23 0'REILLY, J P Region 2, Office of Director 2pp 26261 305 24X Fiche 50-438,84/07/23,8408280100
- 8408270232 Forwards Insp Repts 50-438/84-13 & 50-439/84-13 on 840709-10 No violations of deviations noted VERRELLI.D M Division of Project & Resident Programs 84/07/26 PARRISH G Tennessee Valley Authority 2pp 26288 048 24X Fiche 50-438,84/07/26.8408270232
- --8408270240 Insp Repts 50-438/84-13 & 50-439/84-13 No violations or deviations noted Major areas inspected licensee action on previous enforcement natters, safety-related components & licensee identified items OIRARD.C H. DLAKE, J. J. Region 2, Office of Director 84/07/20 Spp 26/258 05D 24X Fiche 50-438,84/07/26.8408270232
- 8408270460 Ack receipt of 840713 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-438/83-05 & 50-439/83-05 Response neets requirements of 10CFR2 20i Corrective actions will be examined during future insps VERRELLI.D M Region 2, Office of Director 84/07/26 PARRIS.H @ Tennessee Valley Authority 1p 26256 235 24X Fiche 50-438.84/07/26.8408270460
- --8408270468 Forwards supplemental response to NRC 830412 ltr reviolations nated in Insp Repts 50-438/83-05 & 50-439/83-05 Corrective actions BNP-QCP-63 revised to clarify listing of attributes inspected on thermal expansion devices.

  MILLS.L M Tennesses Valley Authority 84/07/13 O'REILLY, JP Region 2, Office of Director 3pp 26256 236 24X Fiche 50-438,84/07/26,8408270460
- --8408270475 Supplemental response to violations noted in Insp Repts 50-439/83-05 & 50-439/83-05 Corrective action const QC unit waiting for computer printout to verify insp of all affected equipment under Revs 0 & i ta GCP 6 3.
  MILLS, L M Tennessee Valley Authority 84/01/04 O'REILLY, J P Region 2. Office of Director ip 26256 239 24% Fiche 50-438,84/07/26,8408270460

- --8408270483 Supplemental respanse to violations noted in Insp Repts
  - KOME/10483 Supplemental response to violations noted in insp Repts 50-438/83-05 & 50-439/83-05 Corrective actions will be completed by 83/216
    MILLS.L M Tennessee Valley Authority 83/09/12 O'REILLY, J P Region 2, Office of Director 1p 26256 240 24x
    Fiche 50-438,84/07/26.8408270460
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants' Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 8301031 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000.84/07/27,8407250229
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Past 830103) B4/08/06 Consolidated Edison Co. of New 26069 001 24X Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc. 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61: "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York: Inc 120pp 26129 118 24X Fiche 50-000.84/08/08.8408070120
- 8408070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc
- B40B100007 IE Info Notice B4-63, "Defective RHR Replacement Piping "
  Bvc list encl
  JORDAN.E L Division of Emergency Preparedness & Engineering
  Response (Post B30103) B4/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100007
- 8408100038 IE Info Notice 84-64, "SWR HPCI Initiation Seal-In & Indication "Svc list encl JORDAN.E L Division of Emorgency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24% Fiche 50-000.84/08/15,8408100038
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " 8vc list encl JORRON.E L Division of Emergency Proporedness & Engineering JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New Yurk, Inc 118pp 26198 001 244 Fiche 50-000,84/08/16,8408100021
- 840Bi00035 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train." Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York: Inc 120pp 26276 001 24X Fiche 50-000:84/08/17.840B100055
- B408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24% Fiche 50-000.84/08/17,8408140208
- 8408210142 IE Info Notice 84-68. "Patential Deficiency in Improperly Rated Field Wiring to Solenoid Valves." Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of No 24X Fiche 50-000,84/08/21,8408210142 26327 008
- 8 Reportable occurrences, LERs & related correspondence
- 8408220317 Part 21 rept re failure of ITE-27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diode must be added Affected units listed DUVALL.D D Brown Boveri Corp (subs of Brown Boveri & Co., Ltd.) 84/03/13 DEYBUNG.R C Director's Office, Office of Inspection and Enforcement 3pp 26191 357 24X Fiche 50-000.84/03/13.8408220317
- 8405290062 Forwards "Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal RAY,C L TDI (Transamerica Delaval, Inc.) Owners Group B DENTON.HR Office of Nuclear Reactor Regulation, Director 24490 045 24X Fiche 50-000,84/05/24,8405270062 84/05/24

- --8405290075 Investigation of Types AF / AE Piston Skirts "
  \* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp
  24X Fiche 50-000,81/05/24,8405290062
- B405290179 Forwards 'Evaluation of Emergency Diesel Generator Cranksharts at Shoreham % Grand Gulf Nuclear Power Stations Stations " RAY,C L TDI (Transamerica Dela/al, Inc.) Owners Group B DENTON.H R Office of Nuclear Reactor Regulation, Director 24492 090 24x Fiche 50-000,84/05/24,8405290179 84/05/24
- 8408060405 Forwards repts received by BNML & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts.Analysis & Recommendations re Main Propulsion Engines M/V Columbia" and Battelle Mcmorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER.M Division of Licensing 158pp 25926 173 24% Fiche 50-000,81/06/28,8408060405
- 8408060000 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Generator Ouners Group 840622 meeting RAY.C.L. TDI (Transamerica Delaval, Inc.) Owners Group 84/07/10 BERLINGER.C. Director s Office, Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50~000,84/07/10. E40B060050
- 8408070025 Third interim deficiency rept re backflow not considered for ERCN sys booster pump shutoff Initially reported on 821230 Engineering change notice issued Next rept by 850215 MILLS,L M Tennessee Valley Authority 84/07/16 O'REILLY,JP Region 2, Office of Director 2pp 25972 264 24X Fiche 30-438,84/07/16.8498070025
- 8408090028 Third interim deficiency rept re B&W reactor bldg sump pH values not considering dead vol Initially reported on B30623 Analysis underway Next rept will be submitted by HS112/ MILLS, L M Tennessee Valley Authority 84/07/16 Region 2. Office of Director 2pp 25992 255 2 Fiche 50-438,84/07/16,8408090028
- B40809026B Final deficiency rept re contaminated makeup & purification piping Initially reported on 840405 Caused by water flushed into auxiliary bldg 2-inch diameter equipment drain piping sys NV sys piping will be reflushed by 840912 MILLS.L M Tennessee Valley Authority 84/07/16 O'REILLY.J P Region 2. Office of Director 2pp 25994 040 24X Fiche 30-438.84/07/16.840809026B
- 840B090024 Supplemental deficiency rept re defect in steam generator support bolts Initially reported on 820723 Thirty-six bolts still need to be pulled out & shims remachined Corrective actions will be completed by 840829 MILLS.L M Tennessee Valley Authority 84/07/17 D'REILLY, J P Region 2. Office of Director 1p 25992 096 24X Fishe 50-438,84/07/17,8408090024
- 8408090057 Fifth interim deficiency ropt to incorrect installation of pressure relief & safety valves Initially reported on 830305 Caused by waste disposal header not sized to accommodate both relief valves Next rept expected by 860114 MILLS.L.M. Tennessee Valley Authority 84/07/18 0'REILLY.J.P. Region 2. Office of Director 2pp 25992 139 24X Fiche 50-438.84/07/18.8408090057
- 8408090033 Fifth interim deficiency rept re environ qualification of safety-related electrical components Initially reported on B11021 Caused by util failure to develop procedural controls on qualification program Next rept expected by 850621 MILLS.L M Tonnessee Valley Authority 84/07/20 0'REILLY.J P Region 2. Office of Director 21pp 25992 102 24X Fiche 50-438.84/07/20.8408090033
- 8408090279 Fourth interio deficiency rept re makeup HPI pump vibration Initially reported on 880622 Cause not stated Pumps balanced & vibration level measured Next rept expected by 841119 Also reportable per Part 21
  MILLS.L M Tennessee Valley Authority 84/07/20 O'REILLY, J P
  Region 2. Office of Director 2pp 25994 161 24X
  Fiche 50-438.84/07/20.8408090279
- 8408090416 First interim deficiency rept re incomplete review of design change requests for piping analyses Initially reported on 840822 Investigation continuing Next rept will be submitted be 650419 ay about 7 MILLS,L M Tennessme Valley Authority 84/07/20 O'REILLY,J P Region 2. Office of Diractor 2pp 25993 261 24X Fiche 50-438,84/07/20,8408090416

ļ

- 840816017.3 Final deficiency re, regineric implication reviews for const projects Rev 4 to GAP 16 1 issued to more clearly define intra-ord responsibility for defermining generic implications or nonconformance MILLS.L M Tennessee Valley Authority 84/07/24 O'REILLY, J P Region 2. Office or Director 2pp 26108 045 24% Fiche 50-000 84/07/24 8408160173
- 8408160434 First interim deficiency rept re control room pressurization boundary loss through diain ' vent lines Initially reported on 840629 Seismic support mods will be made Next rept will be provided on or about 850215 MILLS.L K Tennessee Valley Authority 84/07/25 O'REILLY, J P Region 2. Office of Directol 2pp 26106 352 24% Fiche 50-138.84/07/25.8408160434
- 8408060102 Forwards 'Emergency Diesel Generator Auxiliary Module Control Wiring 5 Termination Qualification Review " Addi copies sent to BNML RAY, C. L. TDI (Transamerica Delaval, Inc.) Duners Group 84/07/27 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 25732 137 24X Fiche 50-000,84/07/27,8408060102
- ~-B408040138 "Energoncy Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review" # Stone & Webster Engineering Corp 84/07/31 36pp 25932 139 24X Fiche 50-000.84/07/27.81080040102
- 8408160200 Final deficiency rept re field cables not terminated in penetrations properly Initially reported on 830614 Personnel trained to splice cables per manufacturer instructions Corrective actions will be completed by 841001 MILLS, L M Tennessee Vailey Authority 84/07/30 O'REILLY, J Region 2, Office of Director 5pp 26106 303 24X Fiche 50-438,84/07/30,8408160200
- B408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Bets " RAY, C L TDI (Transamerica Delaval, Inc.) Cuneis Group 84/08/01 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 25927 064 244 Fiche 50-000.84/08/01.8408060324
- 8408160058 Final deficiency rept re water damage to reactor bldg normal sump isolation valve motor operator Initially reported on 830609 Motor operator shipped to vendor for repair Reinstallation expected by 850419 MILLS.L M Tennessee Valley Authority 84/08/01 O'REILLY, J P Region 2. Office of Director 2pp 26108 217 24% Fichs 50-438,84/08/01,8408160058
- B40Bi60179 Final deficiency rept to retrievability of GA records
  Initially reported on B40301 GA procedures revised on
  B40508 to incorporate handling requirements for supplier
  GC records
  MILLS.L M Tennessee Valley Authority B4/08/01 O'REILLY.J P
  Region 2. Office of Director 2pp 26108 042 24X
  Fiche 50-000.84/08/01.8408160179
- 8408160066 Final deficiency rept re loose drive hubs on overspeed governor drive shaft on TDI diesel engines Initially reported on 840203 Hubs acceptable Also reportable under Part 21 MILLS, L.M. Tennessee Valley Authority 84/08/03 0'REILLY, J.P. Regian 2. Office of Director 2pp 26108 224 24X Fiche 50-438.84/08/03.8408160066
- 8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DERV-16 Diesel Engines" RAY.C L TDI (Transamerica Delaval, Inc.) Dwners Group 84/08/10 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 26091 147 24X Fichs 50-000.84/08/10.8408160394
- --8408160403 "Design Revieu of Engine Base & Bearing Caps for TDI DBRV-16 Diesel Engines " \* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp 26071 149 24X Fiche 50-000,84/08/10.8408160394
- 8408240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program testing & insp. maint & surveillance & sets forth requirements for operation prior to completion of program plan EISENHUT.D G Division of Licensing 84/08/13 GEORGE,J B TDI (Transamerica Delaval, Inc.) Daners Group 1p 26255 194 24X Fiche 50-000,84/08/13.8908240115
- --8408240157 Safety evaluation of TDI Owners Group program plan Based on BNML evaluation, plan incorporates essential elements needed to resolve outsfanding concerns re reliability of TDI engines for nuclear svc \* NRC No Detailed Affiliation Given 84/08/13 21pp 26255 175 24X Fiche 50-000,84/08/13,8408240115

- 8408160395 Forwards Design Review of Elliott Model 906 Turbocharger Used on TDI DBR-43 & DBRV-16 Emergency Diesel Generator Sets: representing final GA verified rept Addl copy forwarded to BNML per NRC request RAY.C L TDI (Transamerica Delaval, Inc.) Quners Group 84/08/14 DENTON H R Office or Nuclear Reactor Regulation, Director 2pp 26088 163 24X Fiche 50-000,84/08/14,8408160395
- --8408160377 "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Energency Diesel Generator Sets " # Failure Analysis Associates FAAA-84-5-7 E4/07/31 61pp 26088 165 24X Fiche 50-000.09/08/14,0408160395
- 8408290179 Forwards response to 840723 request for add1 info on repts submitted by TDI Diesel Generator Gumers Group RAY.C L TDI (Transamerica Delaval, Inc.) Gumers Group 84/08/23 BERLINGER.C Office of Nuclear Reactor Regulation, Director 12pp 26289 221 24% Fiche 50-000.84/08/23,8408290179
- DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 8408030155 Documents K Mali 840628 telcon w/C Stable advising that review of tube rupture analysis using RELAP 5 computer code, per TMI Action Item II K 3 5. "Automatic Trip of Reactor Coolant Pump." will be delayed info expected by 841113 MILLS.L M Tennessee Valley Authority 84/07/27 ADENSAM.E Operating Reactors Branch 4 ip 25912 015 24x Fiche 50-438.84/07/27.8408030155
- 8408070110 Generic Ltr 84-19 to all licenses of operating reactors, applicants for DLs & holders of CPs re availability of Suppl 1 to NUREO-0733. "Prioritization of Generic Safety Issues" Svc list encl ETSENHUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000,84/08/06,8408070110
- B40B27009B Forwards response to NRC 831229 ltr re TD1 emergency diesel generators Includes procurement & performance specs & insp results BHELL.R H Tennessee Valkey Authority 84/08/17 ADENBAM.E 9 Licensing Branch 4 167pp 26248 052 24X Fiche 50-438.84/08/17, 840B270098
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for QLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl LISENHUT.D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276-244 24X Fiche 50-000.84/08/20.8408200275
- Q Inspection reports, IE Builetins & correspondence
- 8408280100 Forwards supplemental response to IE Bulletin 81-03 re flow blockage of cooling water to safety sys components by Corbicula 8p (Asiatic clam) & Myttlus Sp (mussel) MILLG:L. K. Tonnessee Valley Authority 84/07/23 O'REILLY:J P Region 2. Office of Director 2pp 26261 305 24X Fiche 50-438:84/07/23.8408280100
- B408270232 Forwards Insp Repts 50-438/84-13 & 50-439/84-13 on 840709-10 No violations or deviations noted VERRELLI.D M Division of Project & Resident Programs 84/07/26 PARRIS.H G Tennessee Valley Authority 2pp 26238 048 24X Fiche 50-438,84/07/26,8408270232
- --B40B270240 Insp Repts 50-43B/B4-13 & 50-43B/B4-13 No violations or deviations noted Major areas inspected licensee action on previous enforcement natters, safety-related components & licensee identified items GIRARD, E.H., BLAKE, J.J. Region 2, Office of Director. B4/07/20 Spp. 26258 050 24X Fiche 50-438, B4/07/26, B40B270232
- 8408270460 Ack receipt of 840713 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-438/83-05 & 50-439/83-05 Response neets requirements of 10CFR2 201 Corrective actions uill be examined during future insps VERRELLI.D M Region 2. Office of Director 8/07/26 PARRIS.H Q Tennessee Valley Authority in 26256 235 24x Fiche 50-438,84/07/26.8408270460
- --8408270468 Forwards supplemental response to NRC 830412 ltr re violations noted in Insp Repts 50-438/83-05 & 50-439/83-05 Corrective actions BNP-GCP-6 3 revised to clarify listing of attributes inspected on thermal expansion devices MILLS, L M Tennesses Valley Authority 84/07/13 O'REILLY, J P Repion 2, Office of Director 3pp 26256 236 24X Fiche 50-438,84/07/26,8408270460

- 8408270475 Supplemental response to violations noted in Insp Repts 50-438/83-05 % 50-439/83-05 Corrective action const GC unit waiting for computer printout to verify insp of all affected equipment under Revs O % 1 to GCP 6 3 MILLS,L M Tennessee Valley Authority 84/01/04 O'REILLY,J P Region 2. Office of Director 1p 26256 239 24% Fiche 50-438,84/07/26,8408270460
- B40B2704B3 Supplemental response to violations noted in Insp Repts 50-438/83-05 % 50-439/83-05 Corrective actions will be completed by 831216
  MILLS.L M Tennessee Valley Authority 83/09/12 0'REILLY.J P Region 2. Diffice of Director ip 26256 240 24x
  Fiche 50-438,84/07/26.8408270460
- NO7250229 IE Info Notice 84-57, "Operating Experience ra Moisture
  Intrusion in Safety-Related Electrical Equipment at
  Commercial Power Plants " Svc list encl
  JORDAN, E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) B4/07/27 Consolidated Edison Co of New
  York, Inc 119pp 25865 047 24% Fiche 30-000,84/07/27,8407250229
- 108010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JORDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333
- 408010337 IE Info Nutice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 83013) B 4708/06 Cansolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 30-000.84/08/06,8408010337
- 408070120 IE Info Natice 84-61. "Gverexpasure of Diver in PWR Refueling Cavity " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Respanse (Post 83013) 94/09/08 Consolidated Edison Co of New Yark, Inc 120pp 26:27 1:8 24X Fiche 50-000.84/08/08.8408070120
- 408070376 IE Info Notice 84-62, "Therapy Hisadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Syc list encl GRACE,J N Division of QA, Gafeguerds & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24x Fiche 50-000.84/08/10.8408070376
- 408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
- 408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 83013) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26178 093 24X Fiche 50-000.84/08/15,8408100038
- 408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list enc!

  JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,840810002!
- 408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- 108140208 IE Info Notice 84-67, "Recent Enubber Inservice Testing W/ High Failure Rates " 8vc list ancl JURDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 108210142 IE Info Notice 84-58, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/09/21 Consolidated Edison Co of New York, Inc 115pp 26/329 008 24X Fiche 50-000,84/08/21,8408210142

- S Reportable occurrences, LER- \* related correspondence
- 8408220317 Part 21 rept re failure of ITE-27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diode must be added Arfected units listed DUVALL,D D Brown Boveri Corp (subs of Brown Boveri & Co., Ltd.) 84/03/13 DEvOUNG,R & Director's Office of Inspection and Enforcement 3pp 26/91/357 24% Fiche 50-000.84/03/13.8408220317
- 8405290062 Forwards Investigation of Types AF & AE Piston Skirts "
  Rept supercedes 840227 submittal
  RAY.C L TVI (Transamerica Delaval. Inc.) Owners Group 84/05/2:
  DENTON:HR Office or Nuclear Reactor Regulation, Director 2pp
  24690 045 24x Fiche 50-000.84/05/24.8405290062
- --8405270075 "Investigation of Types AF & AE Piston Skirts \* Failure Analysis Associates FAAA-84-2-14 84/05/ 24X Fiche 50-000.84/05/24 8405270062 84/05/23 120pp
- 8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shorehan & Grand Gulf Nuclear Power Stations TDI (Transamerica Delaval, Inc.) Owners Group 84 DENTON, HR Office of Nuclear Reactor Regulation, Director 24672 090 24% Fiche 50-000,84/05/24,8405290179
- 8408060405 Forwards repts received by BNWL & consultants directly from FAAA & TOI Gwners Group at 840622 meeting Draft "Coverview of Repts, Analysis & Recommendations re Main Propulsion Engines M/V Columbia" enci
  ALZHEIMER, J M Battelle Memorial Institute, Pacific Northwest
  Laboratories 84/06/28 MILLER, M Division of Licensing 158pp
  25926 173 24% Fiche 50-000,84/06/28,8408060405
- 8408050050 Forwards info addressing open items identified in NRC/BNHL/TDI Diesel Generatur Cuners Grupp 840622 meeting RAY.C. L. TDI (Transamenica Delaval. Inc.) Cuners Group 84/07/10 HERLINGER.C. Director's Office. Office of Inspection and Enforcement 43pp 25933 133 24% Fiche 50-000, 84/07/10, 8408050030
- 8408090025 Third interim deficiency rept re backflow not considered for ERCW sys booster pump shutoff Initially reported on 821230 Engineering change notice issued Noit rept by 850215 MILLS.L M Tennessee Valley Authority 84/07/16 Q'REILLY, J P Region 2, Office of Director 2pp 25992 244 24X Fiche 90-438,84/07/16,8408090025
- B408090028 Third interim deficiency rept re BLW reactor bldg sump pH values not considering dead vol Initially reported on B30423 Analysis underway Next rept will be submitted by MILLS, L M Tennessee Valley Authority 84/07/16 O'REILLY, J P Region 2, Office of Director 2pp 28992 285 24X Fiche 50-438,84/07/16,8408090028
- 8408090024 Supplemental deficiency lept re defect in steam generator support bolts Initially reported on 820723 Thirty-six bolts still need to be pulled out % shims remachined Corrective actions will be completed by 840829 MILLS,L M Tennessee Valley Authority 84/07/17 D'REILLY,J P Region 2. Office of Director 1p 29792 096 24X Fiche 50-438,84/07/17,8408090024
- 8408090057 Fifth interim deficiency rept re incorrect installation of pressure relief & safety valves [nitially reported on 830305 Caused by waste disposal header not sized to accommodate both relief valves Next rept expected by 860114 MILLS,L M Tennessos Valley Authority 84/07/18 O'REILLY,J P Region 2. Office of Director 2pp 25972 139 24X Fiche 50-438,84/07/18,8408090057
- 8408090033 Fifth interim deficiency rept re environ qualification of safety-related electrical components Initially reported on Bi1021 Caused by util failure to develop procedural controls on qualification program Next rept expected by B50621 MILLS.L M Tennessee Valley Authority 84/07/20 0'REILLY, J F Region 2, Office of Director 2ipp 25972 102 24X Fiche 50-438.84/07/20,8408090033
- 840B090416 First interim deficiency rept re incomplete review of design change requests for piping analyses Initially reported on 840B22 Investigation continuing Next rept will be submitted 840622 Investigation continuing Next rept will be submitted by 850419 MILLS.I. M Tennessee Valley Authority 84/07/20 O'REILLY, J P Region 2, Office of Director 2pp 25993 261 24X Fiche 50-438.84/07/20.8408090116

- 840Bi601/3 Final deficiency rept re generic implication reviews for const projects Rev 4 to 9AF 16 1 issued to more clearly define intra-oft responsibility for determining generic implications of nonconformance MILLS.L M Tennessee Valley Authority 84/07/24 0'REILLY, J P Region 2. Defice of Director 2pp 2610B 045 24X Fiche 50-000.84/07/24.840B160173
- 8408160434 First interim deficiency rept re control room pressurization boundary loss through drain 5 vent lines [initially reported on 840625 Seisnic support mods will be made Next rept will be pravided on or about 850215 MILLS,L M Tennessee Valley Authority 84/07/25 0'REILLY, J P Region 2. Office of Director 2pp 26106 352 24X Fiche 50-438,84/07/25 8408160434
- 8408060102 Forwards "Energency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNML RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group 84/07/27 DENTON.H P Office of Nuclear Reactor Regulation, Director 2pp 25932 137 24% Fiche 50-000,84/07/27,8408060102
- --8408060138 "Energency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review "
  \* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139
  24X Fiche 30-000.84/07/27.8408060102
- 8408160200 Final deficiency rept re field cables not terminated in penetrations properly initially reported on 830614 Personnel trained to splice cables per manufacturer instructions Corrective actions will be completed by 841001 MILLS,L M Tennessee Valley Authority 84/07/30 O'REILLY, J Region 2. Office of Director 5pp 26106 303 24X Fichs 50-438.84/07/30.8408160200
- 84080&0324 Forwards "Design Review of Elliott Model 659 Turbocharger Used on TDI DERV-12-4 & DERV-20-4 Emergency Diesel Generator Sots " RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group 84/08/01
- Bets "
  RAY,C L TDI (Transamerica Delaval, Inc.) Owners Group 84/08/09
  DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
  25927 064 24% Fiche 50-000,84/08/01,8408060324
- 8408160179 Final deficiency rept re retrievability of QA records Initially reported on 840301 2A procedures revised on 840608 to incorporate handling requirements for supplier QC records MILLB, L M Tennessee Valley Authority 84/08/01 O'REILLY, J P Region 2. Office of Director 2pp 26108 042 24X Fiche 50-000,84/08/01.8408160179
- 8408160066 Final deficiency rept re loose drive hubs on overspeed governor drive shaft on TDI diesel engines Initially reported on 840203 Hubs acceptable Also reportable under Part 21 MILLS,L M Tennessee Valley Authority 84/08/03 O'REILLY,J P Region 2. Office of Director 2pp 26108 224 24X Fiche 50-438.84/08/03.8408160066
- 840Bi40394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines " RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group 94/08/10 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 26091 147 24X Fiche 50-000,84/08/10,840Bi60394
- --8408160403 "Design Review of Engine Base & Bearing Caps for TDI DBRV-16 Diesel Engines " \* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp 26091 149 24X Fiche 50-000.84/08/10.8408160394
- 8408240ii5 Forwards SER re TDI Dwners Group program plan SER addresses design review/quality revalidation program, testing & insp. maint & surveillance & sets forth requirements for operation prior to completion of program plan EISENHUT, D G Division of Licensing 84/08/13 GEORGE, J B TDI (Transamerica Delaval, Inc.) Owners Group ip 26255 194 24X Fiche 50-000.84/08/13.8408240113
- --8408240157 Safety evaluation of TDI Owners Group program plan Based on BNWL evaluation, plan incorporates essential elements needed to resulve outstanding concerns re reliability of TDI angines for nuclear svc \* NRC No Detailed Affiliation Given 84/08/13 21pp 26255 195 24X Fiche 50-000,84/08/13,8408240115
- B40Bi60395 Forwards "Design Review of Elliott Model 900 Turbocharger Used on TDI DRR-48 & DBRV-16 Emergency Diesel Generator Bets." representing final CA verified rept Addi copy forwarded to BNNL.per NRC request RAY.C L TDI (Transamerica Delaval. Inc.) Dwners Group 84/08/14 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 24088 163 24% Fiche 50-000,84/08/14,8408140395

- --840Bi60397 "Design Revieu of Elliott Model 900 Turbocharger Used on TDI DSR-48 \* DSRV-16 Energency Diesel Generator Sets " \* Failure Analysis Associates FAAA-84-5-7 84/07/31 6ipp 26088 165 24X Fiche 50-000.84/08/14.8408160395
- 8408290179 Forwards response to 840723 request for add1 info on repts submitted by TDI Diesel Generator Owners Group RAY.C L TDI (Transamerica Delaval. Inc.) Owners Group 84/08/23 BERLINGER.C Office of Nuclear Reactor Regulation, Director 12pp 26289 221 24% Fiche 50-000.84/08/23,8408290179
- DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

  A Application/construction stage documents & correspondence
- 8408030145 Forwards summary forms on equipment for SORT & pump & valve operability review team audits by Equipment Gualification Branch Floor response spectra & valve qualification program description encl EDELMAN.M R Cleveland Electric Illuminating Co 84/07/25 YOUNOBLOUD.B J Licensing Branch 1 400pp 25912 061 24X Fiche 50-440.84/07/25.8408030145
- 8408070137 Forwards request for add1 info & forms for use in preparation for 840813-17 audits by pump & valve operability review team & SQRT Opening & closeout meetings open to public YOUNOBLOOD, B J Licensing Branch i 84/07/25 EDELMAN, M R Cleveland Electric Illuminating Co 18pp 25957 138 24% Fiche 50-440-84/07/25.8408070137
- 8408070184 Forwards summary forms for one NSSS & one balance-of-plant item identified for upcoming SSRT audit Forms provide supplemental info to 840725 itr EDELMAN.H R Cleveland Electric Illuminating Co 84/08/02 YOUNOBLO
- 840B070110 Generic Ltr 84-19 to all licensess of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933. "Prioritization of Generic Safety Issues" Svc list encl EISENNUT.D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York Inc 18pp 26129 238 24X Fiche 50-000,84/08/06,8408070110
- B40B100005 Requests rev to QA program submitted on B30A02, to fully comply w/requirements of Paragraph (3)(iii) of 10CFR50 55(f) Response requested within 30 days of 1tr receipt BPESSARD, R L. Region 3, Office of Director B4/0B/06 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 25790 101 24% Fiche 50-440, B4/0B/06, B40B100005
- 840Bi30492 Forwards lists of equipment selected for onsite audit of pump & valve operability assurance & seismic qualification of mechanical & electrical equipment programs scheduled for uk of 840Bi3 Forms requested by 840B08 YOUNOBLOOD B J Licensing Branch 1 84/08/07 EDELMAN; M R Cleveland Electric Illuninating Co 6pp 26058 346 24% Fiche 50-440,84/08/07,8408130492
- B40B200275 Generic Ltr B4-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve Unreviewed safety questions Svc list encl
  EISENHUT.D 0 Division of Licensing B4/0B/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X
  Fichs 50-000.84/08/20.8408200275
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8408270320 Forwards addl clarifications to Rev 3 to Emergency Plan OM-15A submitted on 840428 Clarifications include changes to plan per 98ER 4 & will be incorporated into Rev 4 EDELMAN,N R Cleveland Electric Illuminating Co 84/08/20 DENTON,H R Office of Nuclear Reactor Regulation, Director. 12pp 26243 266 24X Fiche 50-440,84/08/20,8408270320
- 8408290396 Summary of 840619 meeting w/util.TERA.Illinois Power Co & Govt Accountability Project in Bethesda.MD re plant-specific responses to hydrogen control SER License Condition 5 List of attendees & viewgraphs encl
  STEFAND.J J Licensing Branch i 84/08/20 YGUNGBLOGD.B J Licensing Branch i 13pp 26310 001 24X Fiche: 50-440.84/08/20.8408290396

- F Security, medical, emergency \* fire protection plans
- B40B1503B0 Forwards 1E insp Rept 50-440/84-13 on 840709-12 No moncompliance noted PAPERIELLO,C J. Region 3. Orrice of Director 84/07/27 EDELMAN,M R. Cleveland Electric Illuminating Co. 2pp. 26078-002 24X Fiche 50-440.84/07/27.8408150380
- --8408150381 IE Insp Rept 50-440/84-13 on 840709-12 No violations or deviations noted Major areas inspected radiation protection program, including organization b staffing, training & procedures & radiography incident on 840616
  MILLER.D. E. (REGER.L. R. Region 3. Office of Director 84/07/27 App. 24078-004 24X Fiche 50-440,84/07/27,8408150380
- B408270320 Forwards addl clarifications to Rev 3 to Emergency Plan OM-15A submitted on B4042B Clarifications include changes to plan per SSER 4 & uill be incorporated into Rev 4 EDELMAN.M R Cleveland Ejectric Illuminating Co B4/08/20 DENTON.H R Office of Nuclear Reactor Regulation, Director 12pp 26243 266 24x Fiche 50-440,84/08/20,8408270320
- BAOR31017: Forwards IV Hoven, NDAA, comments re emergency meteorological capabilities Comments based on review of NUS-4336, "Description of Perry Nuclear Power Plant Emergency Offsite Dase Calculations "Comments should be reviewed YOUNGBLOOD, B.J. Licensing Branch 1 FIN B-7527 84/08/22 EDELMAN, M.R. Cleveland Electric Illuminating Co. 10pp. 26351 340 24X Fiche 50-440,84/08/22,8408310171
- Q Adjudicatory correspondence
- 8408140482 Informs that Jefferson Township Trustees request & support installation & naint of independent monitoring facilities & procedures at & around facility Served on 840814 WISE.C L Ashtabula County, OH DSB 028 B4/07/18 NRC No Detailed Affiliation Given ip 26060 279 24X Fiche 50-440.84/07/18.8408140482
- B40B0i0229 Forwards State of OH emergency response plan & attached 1tr from governor Ltr pertains to B407i6 opposition to particularization of Issue 1 W/o encls W/svc list Related correspondence
  SILBERG.J E Shaw, Pittman, Potts & Trombridge SILBERG.J E Sunflower Alliance DSB 653 84/07/25 BLOCK.P B , KLINE,J R , BRIGHT, O O Atomic Bafety and Licensing Duard Panel 3pp 25856 019 24% Fiche 50-440,84/07/25,8408010229
- 8408010214 Answer in opposition to Ohio Citizens for Responsible Emergy 840706 motion for summary disposition of Issue & reinstallation of automated standby liquid control sys Related correspondence
  BILBERG, J E Cleveland Electric Illuminating Co BILDERG, J E Shaw, Pittman, Potts & Troublidge DSB 672 84/07/30 Atomic Safety and Licensing Board Panel Spp 25836 032 24%
  Fiche 50-440.84/07/30.8408010214
- --B408010217 Statement of natl facts as to which there is no genuine issue Certificate of Svc encl

  \* Cleveland Electric Illuminating Co B4/07/30 Atomic Bafety and Licensing Board Panel 3pp 25856 037 24X
  Fiche 50-440,84/07/30,8408010214
- 8408070478 Response opposing Dhio Citizens for Responsible Energy 840706 motion for summary disposition of Issue 6 Motion based on misinterpretation of 10CFR50 62(c)(4) Certificate of St.c encl Related correspondence HOODMEAD.C P Hearing Branch 4 DSB 806 84/07/30 Atomic 84fety and Licensing Board Panel 6pp 25941 185 24X Fiche 90-440.84/07/30.8408070478
- 8408090231 Thirteenth set of interrogatories pertaining to Issue 8 re hydrogen control Interrogatories concern generation.release & combustion of hydrogen gas in degraded core accident Certificate of Svc encl Related correspondence HIATT.5 L Ohio Citizens for Responsible Energy DSB 835 84/07/730 Cleveland Electric Illuminating Co 20pp 25971 170 24X Fiche 50-440,84/07/30,8408090231
- 840B090249 Motion to reopen discovery on Issue B re hydrogen control Gentificate of Svc encl Related correspondence
  MIATT, S L Ohio Clairens for Responsible Energy DSB B54
  84/07/30 Atomic Safety and Licensing Board Panel 15pp
  23972 170 24X Fiche 50-440.84/07/30,8408090245
- 8408090196 Motion for leave to reply to applicant & NRC responses to Ohio Citizens for Responsible Energy 840706 motion for summary disposition of Issue 6 Related correspondence HIATTS L Uhio Citizens for Responsible Energy DSB 851 84/08/03 Atomic Safety and Licensing Board Panel 1p 25972 028 24X Fiche 50-440,84/08/03,8408090196

- --B408090202 Reply to applicant \* NRC responses to Ohio Citizens for Responsible Energy B40706 motion for summary disposition of Issue 6 re automated liquid control sys W/svc list HIATLS L. Ohio Citizens for Responsible Energy 84/08/03 Atomic Safety and Licensing Board Panel 9pp 25972 029 24X Fiche 50-440,84/08/03.8408090196
- B40B150467 Answer opposing Chip Citizens for Responsible Energy B40730 motion to reopen discovery on Issue 8 re hydrogen control Applicant will discuss specific discovery needs at 840905 meeting Certificate of Sic encl Related correspondence SWIGER.M A Cleveland Electric Illuminating Co SWIGER.M A Shaw. Pittman. Potts & Troubridge DSB Od6 B4/08/14 Atomic Safety and Licensing Board Panel 5pp 2606B 249 24X Fiche 50-440.84/08/14.8408150467
- 8408270057 Response opposing Dhio Citizens for Responsible Energy 840730 motion to reopen discovery on Issue 8 Motion should be denied in light of applicant duty to suppl responses to requests W/Certificate of Svc Related correspondence WDODHEAD, C.P. Hearing Branch 4 DSB 300 84708720 Atomic Safety and Licensing Board Panel 4pp 26247 064 24X Fiche 50-440,84708/20,8408270057
- 8408280437 Particularized objections to proposed emergency plan supporting Issue tiper ASLB 840726 memorandum % order ASLB urged to waylay action on emergency preparations as contention & dismiss application for DL Svc list encl LOGG.T J Sunflower Alliance D58 361 84/08/20 30pp 26280 183 24X Fiche 50~440.84/08/20,8408280437
- I Financial information
- B408020118 Forwards Annual Financial Repts 1983 for Duquesne Light Co.
  Ohio Edison Co.Pennsylvania Power Co.Toledo Edison Co.
  Cleveland Electric Illuminating Co.
  EDELMANIA R. Cleveland Electric Illuminating Co. 84/07/27
  DENTON.H. Office of Nuclear Reactor Regulation, Director 1p.
  25886-041 24X Fiche 50-440.84/07/20.8408020118
- --8408020126 Annual Financial Rept 1983 ROSERS.J T , COLE.A W Pennsylvania Power Co 83/12/31 27pp 25886 170 24X Fiche 50-440.84/07/20.8408020118
- G Inspection reports: IE Bulletins & correspondence
- B40B090293 Forwards IE Insp Repts 50-440/B4-09 % 50-441/B4-09 on B40501-0630 & notice of violation MARNICK.R F Region 3, Office of Director 84/07/18 EDELMAN.M R Cleveland Electric Illuminating Co 2pp 25994 173 24X Fiche 50-440.84/07/18.8408090293
- --8408070298 Notice of violation from insp on 840501-0630 WARNICK,R F Region 3. Office of Director 84/07/18 19 25994 175 24X Fiche 50-440.84/07/18.8408090293
- --8408090304 IE Insp Repts 50-440/84-07 & 50-441/84-09 on 840501-0630 Noncompliance nated failure to follow tagging procedure KNDP.R C Region 3. Office of Director 84/07/18 Bpp 25974 176 24X Fiche 50-440.84/07/18.8408090293
- 8407250229 IE Info Notice 84-57. "Uporating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229
- B408150380 Forwards IE Insp Rept 50-440/84-13 on B40709-12 No noncompliance noted PAPERIELLO,C J Region 3, Office of Director 84/07/27 EDELMAN.M R Cleveland Electric Illuminating Co 2pp 26078 002 24X Fiche 30-440.84/07/27,8408150380
- --840Bi50C81 IE Insp Rept 50-440/B4-13 on 840709-12 No violations or deviations noted Major areas inspected radiation protection program, including organization 5 staffing, training & procedures & radiography incident on 840616 MILLER, D. E., ORECER, L. R. Region 3, Office of Dijector 84/07/27 6pp 26078 004 24X Fiche 50-440,84/07/27,8408150380
- 8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during inspirative defective 840820 Preprinted form will be used rather than ltr
  KEPPLER, J O Region 3, Office of Director 84/08/03
  Commonwealth Edison Co 3pp 25742 188 24X Fiche 50-000,84/08/03.8408070401

- 8408010333 IE Info Notice 81-59. Deliberate Circumventing of Station Health Physics Procedures: Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26068 001 24% Fiche 50-000,84/08/06,8408010333
- 8408010337 IC Info Notice 84-60, 'Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JURDANLE L Division of Emergency Preparedness & Engineering Response (Post 83)1071 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24/ Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61. 'Overexposure of Diver in PWR 408070120 IE Info Notice 84-5). 'U/erexposure of Diver in PWR Refueling Cavity "Svc Ists encl JQRDAN.E t. Division of Emergency Pieparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120p 26129 118 24X Fiche 50-000.84/08/08.8408070120
- 8408070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl Division of OA, Safequards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24x Fiche 50-000.84/08/10.8408070376
- B40B270278 Forwards Insp Repts 30-440/84-16 / 50-441/84-15 on B40717-20 No mancompliance noted PAPERIELLO.C J Region 3. Office of Director 84/08/10 EDELMAN.K R Cleveland Electric Illuminating Co 2pp 26: 24% Fiche 50-440.84/08/10.8408270278 26258 159
- --8408270288 Insp Repts 50-440/84-14 & 50-441/84-15 on B40717-20 No NOBEZOCEME Insp. Repts 50-440/84-16 & 50-441/84-15 on BAO7/-20 No violations or deviations norbed Major areas inspected preoperational radiological environ monitoring program & review of chemistry & radiochemistry program CESTMANN.M J , SCHUMACHER, M C Region 3, Office of Director B4/08/10 6pp 26258 161 24% Fiche 50-440.84/08/10.8408270278
- 8408100009 IE Info Notice 84-63, 'Defective RHR Replacement Paping " Bvc list encl DORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/08/13 Consolidated Edison Co of New York, Inc. 119pp 26197 218 24X Fiche 50~000 84/08/13,840B100009
- 8408300179 Forwards Insp Repts 50~440/84-07 & 50-441/84-07 on 4083001/9 Formaros insp Repts 30-440/24-0/ & 30-441/84-0/ o 840409-12 & 0604-07 & notice of violation Requests audit o records to assure insp repts contain adequate info re identification of item inspected & results of insp LITLE-W S Region 3. Office of Director 84/08/14 EDEI Cleveland Electric Illuminating Co 2pp 26313 271 24X Ficho 30-440.84/08/14.8408300179 EDELMAN, M. R.
- --8408300186 Notice of violation from insp on 840409-12 & 0604-07 LITILE,W 5 Region 3, Office of Directot 84/08/14 2pp 26313 273 24% Fiche 50-440,84/08/14,8408300179
- --8409300196 Insp Repts 53-440/84-07 & 50-441/84-07 on 840409-12 & 0604-07 Noncompliance noted failure to assure that Gilbert Assoc adequately reviewed & verified safety-related schematic & wiring diagrams re standby liquid control NAIDU.K R , CHRISTNOT, E , FALEVITS, Z Region 3, Office of Director 84/08/14 25pp 26313 275 24X Fiche 50-440.84/08/14, 840830179
- 8408100038 IE Info Notice 84-64, "BWR MPCI Initiation Seal-In & Indication "Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co 26198 093 24x Fiche 50-000 84/08/15 8408100038 York, Inc 104pp
- 8409100021 IE Info Notice 84-65, "Underrated Foses Which May Adversely Affect Operation of Essential Electrical Equipment " list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, B4/08/16, 8408100021
- B40B100055 IE Into Notice 84-66, "Undetected Unavailability of Torbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24% Fiche 50-000,84/08/17,8408100055
- 8408140208 IE Info Notice 84-67, "Recent Snubbar Inservice Testing W/ High Failure Rates "Svc list end University Reservice (esting W/High Failure Rates "Svc list end JORDAN E L Division of Emergency Proparedness & Engineering Response (Post 830109) 84/08/17 Consolidated Edison Co of New York Inc 122pp 26276 122 24X Fichs 50-000.84/08/17,8408140208

- 8408210142 JE Info Notice 84-68. Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves "Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 820103) 84/08/21 Consolidated Edison Co. of New York: Inc. (15pp. 26329.008 24% Fichs 50-000.84/08/21,8408210142
- 8408280129 Ack receipt of 840817 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/84-09 & 50-441/84-09 & 889ion 3. Office of Director 84/08/23 Cleveland Electric Illuminating Co 1p 26274 343 24X Fiche 50-440.84/08/23.
- --8408280131 Responds to NRC 840718 ltr re violations noted in 1E Insp Repts 50-440/84-09 & 50-441/84-09 Corrective actions mechanical foreign items identified w/properly initiated tag & placement of tag documented in log book EDELMAN.M R Cleveland Electric Illuminating Co 84/08/17 WARNICK.R F Region 3. Office of Director 3pp 26274 344 24x Fiche 50-440,84/08/23,8408280129
- S Reportable occurrences, LERs & related correspondence
- 8403290062 Forwards "Investigation of Types AF & AE Piston Skirts " 903290062 Forwards "Investigation or Types Ar & Att Piston 5x17 Rept supercedes B40227 submittal RAY.C L TDI (Transamerica Delavel, Inc.) Cwmers Group 84, DENTON, H R Deffice of Nuclear Reactor Regulation, Director 24690 045 24% Fiche 30-000.84/05/24.8405290062 84/05/24
- --8405270075 "Investigation of Types AF & AE Piston Skirts \* Failure Analysis Associates FAAA-84-2-14 84/05/ 24% Fiche 50-000.84/03/24,8405270062 84/05/23 120ap
- B403290179 Forwards "Evaluation of Emergency Diesel Generator Cranksbafts at Shoreham & Grand Gulf Nuclear Power Stations ' RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group 84. DENTON, HR Dffice of Nuclear Reactor Regulation, Director 24692 090 24x Fiche 30-000, 84/03/24,8402290179 H4/05/24
- 8408060405 Forwards repts received by BNML & consultants directly from FAAA & TDI Gwners Group at 840622 meeting Draft "Overview of Repts, Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
  ALZHEIMER, J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 HILLER, M Division of Licensing 158pp 25926 173 24X Fishe 50-000,84/06/28,8408060405
- 8408050050 Forwards info addressing open items identified in NRC/BNHL/TDL Diesel Generator Oungers Group 840522 meeting RAY.C L TDL (Transanerica Delaval. Inc.) Owners Group 84/07/10 HERLINGER.C Director's Office Office of Inspection and Enforcement 43pp 25933 133 24% Fichs 50-000.84/07/10, 8408050050
- B408070261 Final Deficiency Rept [RDC 81(83)] re Westinghouse Class IE penetrations (1872) Initially reported on 830824 Engineering Change Notice 21802-363-05 initiated to revise procurement spec to permit use of ASHE Code Case N242 EDELMAN.M R Cleveland Electric Illuminating Co 84/07/26 KEPPLER, J Q Region 3, Office of Director 2pp 25794 283 24X Fichs 50-440,84/07/26,8408070261
- 8408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNML RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group 84/0 DENTON, H R Office of Nuclear Reactor Regulation, Director 2 25932 137 24X Fiche 50-000,84/07/27,8408060102
- --8408060138 "Energency Diese) Generator Auxiliary Module Control Wiring & Termination Qualification Review" & Stone & Mebster Engineering Corp 84/07/31 36pp 25932 139 24X Fiche 50-000.84/07/27.8408060102
- 8408070148 Final Deficiency Rept [ROC 92(84)] re potential problem w/standby diesel generator loose flexible coupling drive hubs supplied by TDI Initially reported on 940120 Also reported per Part 21 EDELMAN, M R Cleveland Electric Illuminating Co 84/07/27 KEPPLER, J O Region 3, Office of Director 2pp 25993 176 24 Fichs 50-440,84/07/27.8408070148 25993 176 24X
- 8408060324 Forwards "Design Review of Elliott Model 459 Turbotharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Bets " RAY.C L TDI (Transamerica Delaval, Inc.) Quiners Group & DENTON, H & Diffice of Nuclear Reactor Regulation, Director 25927 064 24% Fiche 50-000,84/08/01,8408060324 64/08/01

- B40B130393 Final Deficiency Rept (RDC 49(B2)) re GE water level transmitters of incorrect range in reactor pressure vessels Initially reported on B20312 GE issued field disposition instructions to change to narrow-range transmitters EDELMAN.M R Cleveland Electric Illuminating Co B4/0B/01 KEPPLER.J G Region 3. Office of Director 2pp 26011 106 24) Fiche 50-440.84/08/01.840B130393
- 8408220498 Final deficiency rept re condition of Div 1 Class 1E bus during loss of effsite power Initially reported on 840709 Design change providing contacts closed in remote position agen in local position initiated EDELMAN.M R Cleveland Electric Illuminating Co 84/08/07 KEPPLERI, G Region 3, 07fice of Director 2pp 26196 013 24) Fiche 50-440.84/08/07.8408220498
- 840B220502 Supplemental final deficiency rept re poor workmanship in two HPCS diesel generator local panels Discrepancies in nonconformance repts will be resolved by B40B30 EDELMAN,M R Cleveland Electric Illuminating Co 84/08/09 KEPPLER.J G Region 3, Office of Director ip 26196-012 24X Fiche 50-440.84/08/09.840B220302
- B40B160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DBRV-16 Diesel Engines " RAYLO L. TDI (Transamerica Delaval, Inc.) Owners Group B4/08/10 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 26091 147 24X Fiche 50-000,84/08/10,8408160394
- --8408160403 "Design Revieu of Engine Base & Bearing Caps for TDI DERV-16 Diesel Engines " \* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp 26091 149 24% Fiche 50-000.84/08/10.8408160394
- 840B240115 Forwards SER re TDI Gwners Croup program plan SER addresses design review/quality revalidation program testing & insp. maint & surveillance & sets forth requirements for operation prior to completion of program plan EIBENHUT.D G Division of Licensing 84/08/13 GEORGE.J B TDI (Transamerica Delayal, Inc.) Owners Group ip 26235 194 24% Fiche 50-000.84/08/13.8408240115
- ---8409240197 Safety evaluation of TDI Guners Group program plan Based on BNMC evaluation, plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc \* NRC No Detailed Affiliation Given 84/08/13 2ipp 22255 193 224 Fiche 50-000.84/08/13,8408240115
- 8408160395 Forwards "Design Review of Elliott Model 906 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Bets." representing final GA verified rept Addl copy forwarded to BMM.per NRC request RAY.C L TDI (Transamerica Delaval Inc.) Owners Group 84/08/14 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 24088 143 24X Fiche 50-000.84/08/14.8408160395
- --B40B160377 "Design Revieu of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Energency Diesel Generator Sets "
  Failure Analysis Associates FAAA-64-5-7 B4/07/31 61pp 2608B 165 24X Fiche 50-000.84/08/14,840B160395
- 840B300054 Interim deficiency rept re concave 2 1 unequal leg filler welds installed in reactor bldg by Johnson Controls. Inc.
  Initially reported on B40718 Inductrination & training given to personnel Final rept expected by 850fill EDELMAN. M R Cleveland Electric Illuminating Co 84/08/17 KEPPLER. J G Region 3. Office of Director 2pp 26307 238 24X Fiche 50-440.84/08/17.8408300054
- 8408290179 Forwards response to 840723 request for addl info on repts submitted by TDI Diesel Generator Owners Group RAY.C L TDI (Transamerica Delaval. Inc.) Owners Group 84/08/23 BERLINGER.C Office of Nuclear Reactor Regulation, Director 12pp 24289 221 24X Fiche 50-000.84/08/23.8408290179

## V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of. Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10.8408140426

- DOCKET 50-441 PERRY NUCLEAR POWER PLANT UNIT 2

  A Application/construction stage documents & correspondence
- B40B030145 Forwards summary forms on equipment for SQRT & pump & valve operability review tean audits by Equipment Qualification Branch Floor response spectra & valve qualification program description encl EDELMAN.M R Cleveland Electric Illuminating Co 84/07/25 YDUNGBLODD, B J Licensing Branch I 400pp 25912 061 24X Fiche 50-440.84/07/25.8408030145
- 8408070184 Forwards summary forms for one NSSS & one balance-of-plant item identified for upcoming SQRT audit Forms provide supplemental info to 840725 ltr EDELMAN,M R Cleveland Electric Illuminating Co 84/08/02 YOUNGILOOD, B J Licensing Branch 1 15pp 25950 001 24X Fiche 50-440,84/08/02,8408070184
- 8408070110 Generic Ltr 84-19 to all licensum of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933. "Prioritization of Generic Safety Issues" Svc list enci EISENHUT.D C Division of Licensing 84/08/06 Consolidated Edison Co of New York. Inc. 18pp 26129 238 24X Fiche 50-000.84/08/06.8408070;10
- B40B100005 Requests rev to QA program submitted on B30502, to fully comply w/requirements of Paragraph (3)(11) of OCFR50 55(f) Response requested within 30 days of ltr receipt SPESBARD, R L. Region 3, Office of Director 84/08/06 EDELMAN, M R Cleveland Electric Illuminating Co. 2pp 25970 101 24X Fiche 50-440,84/08/06,840B100005
- B408200275 Generic Ltr 84-20 to all licenses of operating reactors & applicants for GLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
  EISENHUT.D 0 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
  Fiche 50-000,84/08/20,8408200275
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8408270320 Forwards add1 clarifications to Rev 3 to Emergency Plan OM-15A submitted on 840428 Clarifications include changes to plan per SSER 4 & will be incorporated into Rev 4 EDELMAN.M R Cleveland Electric Illuminating Co 84/08/20 DENTON.H R Office of Nuclear Reactor Regulation, Director 12pp 26243 266 24% Fiche 50-440.84/08/20.8408270320
- 8408290394 Summary of 840519 meeting w/util, TERA, Illinois Power Co & Govt Accountability Project in Bethesda, MD re plant-specific responses to hydrogen control SER License Condition 5 List of attendees & viewgraphs encl
  STEFANG, J J Licensing Branch 1 84/08/20 YOUNGBLOOD, B J Licensing Branch 1 13pp 26310 OOI 24X Fiche 50-440,84/08/20,8408290396
- F Security, medical, emorgency & fire protection plans
- B408270320 Forwards add1 clarifications to Rev 3 to Emergency Plan OM-15A submitted on B1042B Clarifications include changes to plan per BSER 4 & uill be incorporated into Rev 4 EDELMAN, M R Cleveland Electric Illuminating Co B4/08/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 12pp 26243 266 24X Fiche 50-440,84/08/20,8408270320
- B408310171 Forwards IV Hoven, NGAA, comments re emergency meteorological capabilities Comments based on review of NUS-4336, "Description of Perry Nuclear Power Plant Emergency Offsite Dose Calculations "Comments should be reviewed YDUNGBLOID, B J Licensing Branch 1 FIN B-7527 B4/0B/22 \_EDELMAN.M R Claveland Electric Illuminating Co 10pp 26351 340 24% Fiche 50-440.84/0B/22,8408310171
- G. Adjudicatory correspondence
- B40Bi404B2 Informs that Jefferson Township Trustees request & support installation & naint of independent monitoring facilities & procedures at & around facility Served on 840BI4 HISE.C L Ashtabula County, OH DSB 028 B4/07/18 NRC No Detailed Affiliation Given ip 26060 279 24X Fiche 50-440,84/07/18,840BI404B2

- --8408020126 Annual Financial Rept 1983 RUGERS.J T., CCLE.A W. Pennsylvania Power Co. 83/12/31 27pp 23886 U70 24X Fiche 50-440,84/07/20,8408020118
- G Inspection reports, IE Bulletins & correspondence
- 8408090293 Forwards IE Insp Repts 50-440/84-09 % 50-441/84-09 on B40501-0630 % notice of violation WARNIC/.RF Region 3, Office of Director 84/07/18 EDELMAN,N R Cleveland Electric Illuminating Co 2pp 25994 179 24X Fiche 50-440,84/07/18,8408090293
- --8408090304 IE Insp Repts 50-440/84-07 \$ 50-441/84-07 on 840501-0430 Noncompliance nuted failure to follow tagging procedure KNDP.R C Region 3. Office of Director 84/07/18 8pp 25994 176 24X Fiche 50-440,84/07/18,8408090293
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc fist encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 30-000,84/07/27,8407250229
- 8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during inspiristituted effective 840820 Preprinted form will be used rather than ltr
  KEPPLER.J G Region 3. Office of Director 84/08/03
  Commonwealth Edison Co 3pg 25742 188 24X Fiche 50-000,84/08/03,8408070401
- B40B010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26058 001 24X Fiche 50-000,84/08/06, 840B010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York Inc 123pp 26067 158 24X Fiche 50-000,84/08/06.8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- 8408070376 IC Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list enc! GRACE,J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc. 125p 26130 CO1 24X Fiche 30-000:84/08/10.8408070375
- 8408270278 Forwards Insp Repts 50-440/84-16 & 50-441/84-15 on 840717-20 No noncompliance noted PAPERIELLO,C J Region 3. Office of Director 84/08/10 EDELMAN.MR Cleveland Electric Illuminating Co 2pp 26258 159 24X Fiche 50-440.84/08/10.8409270278
- --8408270288 Insp Repts 30-440/84-16 & 30-441/84-15 on 840717-20 No violations or deviations noted Major areas inspected; preoperational radiological environ monitoring program & review of chemistry & radiochemistry program GESTMANN, M J , SCHUMACHER, M C Region 3, Office of Director 84/08/10 & App 26258 161 24X Fiche 50-440,84/08/10,8408270278
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc. 117pp 26197.218 24% Fiche 50-000,84/08/13,8408100009
- 8408300179 Forwards Insp Repts 50-440/84-07 \$ 50-441/84-07 on 840409-12 & 0604-07 & notice of violation Requests audit of records to assure insp repts contain adequate info re identification of item inspected & results of insp LITLE.N S Region 3. Office of Director 84/08/14 EDELMAN,M R Cleveland Electric Illuminating Co 2pp 26313 271 24X Fiche 50-440/84/08/14,8408300179
- --8408300186 Natice of violation from insp on 840409-12 & 0604-07 LITTLE,W S Region 3. Office of Director 84/08/14 2pp 26313 273 24X Fiche 50-440,84/08/14,8408300179

- --B40830019a Insp Repts 53-449/84-07 \* 50-441/84-07 on 840409-12 & 0504-07 Noncompliance nated failure to assure that Gilbert Assoc adequately reviewed \* verified safety-related schematic & unring diagrams re-standby liquid control NAIDU & R. CHRISTYUT & FALEVITS Z Region 3 Office of Director 84/08/14 25pp 26313 2/5 24X Fiche 50-440,84/08/14,8408300179
- 8408100038 IE Info Notice 84-64. BWR HPC| Initiation Seal-In & Indication "Sec list encl JURBAN.E L Division of Emergency Preparedness 'Engineering Response (Post 833103) 84/08/15 Consolidated Edison Co of New York Inc 104pp 26198 093 24% Fiche 50-000.84/08/15,8408100038
- 8408100021 IE Info Notice 84-o5. Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment' Svc
  - list encl

    JORDAN E L Division of Emergency Preparedness & Engineering

    Response (Post 830103) 84/03/16 Consolidated Edison Co of New

    Yari, Inc 118pp 26178 001 24X Fiche 50-000.84/08/16.8408100021
- 8408100095 IE Info Notice 84-66, Undetected Unavailability of 108100055 IE Info Notice 84-66. Undetected Unavailability of Turbine-Driven Auviliary Feeduater Train Svc list entl JORDAM.E L Division of Energency Preparedness / Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc. 120pp 26276 001 24X Fiche 50-000.84/08/17.8408100055
- 840B14020B lE Info Notice 84-67. "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Editor Co of New York. Inc 122pp 26276 122 24X Fiche 50-000.84/08/17,8408140208
- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Suc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 800103) 84/08/21 Consolidated Edison Co of New York, Inc. 115pp 26527 008 24X Fiche 50-000,84/08/21,8408210142
- 8408280129 Ack receipt or 840817 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/84-09 & 30-441/84-09 & Region 3. Office of Director 84/08/23 Cleveland Electric
  - fice of Director 84/08/23 Cleveland Elec 1p 26274 343 24x Fiche 50-440,84/08/23. Illuminating Co 8408280129
- --8408280131 Responds to NRC 840718 ltr re violations noted in IE Insp Repts 50-440/84-0° & 50-441/84-09 Corrective actions mechanical foreign items identified w/properly initiated tag & placement of tag documented in log book EDELMAN.M R Cleveland Electric Illuminating Co 84/08/17 WARNIGH.R Fegion 3. Office of Director 3pp 26274 344 24X Fiche 50-440,84/08/23.8408280129
- S Reportable occurrences. LERs > related correspondence
- 8405290062 Forwards "Investigation of Types AF & AE Piston Skirts"
  Rept supercedes 840927 submittal
  RAY.C L TOI (Transamerica Delaval, Inc.) Owners Group 84/05/2
  DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp
  24690 045 244 Fiche 50-000,84/05/24,8405290062
- --B405290075 "Investigation of Types AF & AE Piston Skirts "
  # Failure Analysis Associates FAAA-84-2-14 84/05/20 # Failure Analysis Associates FAA 24X Fiche 50-000,84/05/24,8405270062 84/05/23 120pp
- B405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shorehan & Grand Gulf Nuclear Power
  - Stations "
    RAY,C L TDJ (Transamerica Delaval, Inc ) Cwners Group 84
    DENTON,H R Office of Nuclear Reactor Regulation, Director
    24692 090 24X Fiche 50-000,84/05/24,8405290179 84/05/24
- 8408060405 Forwards repts received by BNHL & consultants directly from FaAA & TDI Quners Group at 840822 meeting Draft "Overview of Repts.Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
  ALZHEIMER.J M Battelle Memorial Institute, Pacific Northwest
  Laboratories 84/06/28 MILLER.M Division of Licensing 158pp Laboratories 84/06/28 MILLER M DIVISION OF Licensing 25926 173 24% Fiche 50-000.84/06/28,8408060405
- 8408360050 Forwards info addressing open items identified in NRC/BNWL/
  TDI Diesei Generator Owners Group 840622 meeting
  RAY-C L TDI (Transamerica Delaval, Inc.) Owners Group 84/07/10
  BERLINGER, C Director's Office, Office of Inspection and
  Enfercement 43pp 25933 133 24X Fiche 50-000,84/07/10,

- 8408090261 Final Deficiency Rept [RDC 81(85)] Te Destinghouse Class If penetrations (1872) Initially reported on 8308 4 Engineering Change Notice 21802-363-05 initiated to revise procurement spec to permit use of ASME Code Case N242 EDELMAN M R Cleveland Electric Illuminating to 84/07/26 KEPPLER, J Q Region 3, Office of Director 2pp 25994 283 24% Fiche 50-440,84/07/26,8408090261
- B40B060102 Furwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNNL RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group 84/0, DENTON, R.R. Office of Nuclear Reactor Regulation, Director 25932 137 24/ Fiche 50-000 84/07/27/840B060102 84/07/27
- --8408060138 "Emergency Diesel Generator Auriliary Module Control Wiring A Termination Gualification Review " \* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139 24X Fiche 50-000,84/07/27 8108060102
- 8408090148 Final Deficiency Rept ERDC 92(84)] Te potential problem w/standby diesel generator loose flexible coupling drive hubs supplied by TDI Initially reported on 840120 Also reported per Part 21 EDELMAN.M R Cleveland Electric Illuminating Co 84/07/27 KEPPLER.J G Region 3, Office of Director 2pp 25993 176 2/ Fiche 50-440.84/07/27,8408090148 24 X
- 8408060324 Forwards 'Design Review of Elliott Model 659 Turbocharger Used on TD1 DSKV-12-4 & DSRV 20-4 Limergency Diesel Generator RAY, C.L. TDI (Transamerica Pelaval, Inc.) Guners Group. 8. DENTON, H.R. Office of Nuclear Reactor Regulation, Director 25927-064. 24% Fiche 59-000.84/08/01.8408060324
- 8408130393 Final Deficiency Rept (RDC 49(82)) re GC water level transmitters of incorrect range in reactor pressure vessels initially reported on 820312 GE issued field disposition instructions to change to narrow-range transmitters
  EDELMAN. If R Cleveland Electric Illuminating Co 04/08/01
  KEPPLER J G Region 3, Office of Director 2pp 26011 t06
  Fiche 50-440.84/08/01.8408130393 24X
- 8408220498 Final deficiency rept re condition of Div 1 Class 1E bis during loss of offsite power Initially reported on 840709 Design change providing contacts closed in remote position & open in local position initiated EDELMAN.M R Cleveland Electric Illuminating Co 84/08/07 KEPPLER.J G Region 3, Office of Director 2pp 24196 013 24) Fiche 50-440.84/08/07,8408220498
- 8408220502 Supplemental final deficiency tept re poor workmanship in two HPCS diesel generator local panels Discrepancies in nonconformance repts will be resolved by B40830 EDECMAN.M R Cleveland Electric Illuminating Co B4708709 KEPPLER.J G Region 3. Office of Director ip 26196-012 24X Fiche 30-440.84708709.8408220502
- 840B160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSMV-16 Diesel Engines " RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group 84/08/10 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 26091 147 24X Fiche 50-000,84/08/10,8408160394
- ---8408160403 "Design Review of Engine Base & Bearing Caps for TDI DBRV-16 Diesel Engines " " Fastbure Analysis Associates FAAA-84 6-53 84/08/31 44 26091 149 24X Fiche 50-000.84/08/10.8408160394 84/08/31 44pp
- 8408240115 Forwards SER re TDI Dumers Group program plan BER addresses design review/quality revalidation program, testing & insp. maint & surveillance 's sets forth requirements for operation prior to completion of program plan
  EISENHUT.D G Division of Licensing 84/08/13 GEOROF, J B TDI tTransamerica Delaval, Inc.) Dumers Group 1p 26255 194 24X
  Fiche 50-000,84/08/13,8408240115
- --B408240157 Safety evaluation of TD1 Owners Group program plan Based on BNWL evaluation, plan incorporates essential elements nueded to resolve outstanding concerns re reliability of TD1 engines for nuclear svc \* NRC No Detailed Affiliation Given 84/08/13 21pp 26256 195 24X Fiche 50-000,84/08/13,8408240115
- 8408160395 Forwards "Design Review of Elliott Model 900 Turbocharger Used on TDI DER-48 t DERV-16 Emergency Diesel Generator Sets: "representing final OA verified rept Addl copy forwarded to BNML-per NRC request RAY.C L TDI (Transamerica Delaval, Inc.) Dwneis Group 84/08/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26088 163 24% Fiche 50-000, 84/08/14, 8408160375

- --8408160377 'Design Re leu of Elliott Model 960 Turbochanger Used on TDI DSR-48 ', DSRV-16 Emergency Diesel Generator Sets " # failure Analysis Associates FAAA-84-5-7 84/07/31 61pp 26088 165 24X Fiche 56-000 84/08/14 8408160395
- 8408290179 Forwards response to 810723 request for add1 info on repts submitted by TDI Diesel Generator Curets Group RAY.C L TDI (Transamerica Delava). Inc.) Dumers Group 84/08/23 BERLINGER.C Defice of Nuclear Aeactor Regulation, Director 12pp 26289 221 24x Fiche 50-000.84 08/23,8408290179

#### V Operator Examinations

B408140426 Provides address for transmitting all operator licensing correspondence to Region III ordinescept into for examiners HALLERIR D. Region 3. Orfice of Director. 84/08/10. Michigan. Univ. of. Ann. Arbor. MI. 2pp. 26051 198. 24% Fiche 50-000. 84/08/10.8408140426

## DOCKET 50-443 SEABROOK NUCLEAR STATION: UNIT 1

- A Application/construction stage documents & correspondence
- B408070332 Forwards correspondence from two cable manufacturers re apparent deviation from FSAR concerning cable tray loading criteria foi heavy power cables Effect on ampacity insignificant Proposed FSAR change encl
  DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 84/07/12 KNIGHTON.0 W Licensing Branch 3 10pp 25945 179 24X Fiche 50-443.84/07/12.8408070332
- BAOBI30217 Accepts conditionally util B40622 request to use ASME Code Case N-368 for application in pressure testing of piping associated w/discharge side of Code Classes 2 t 3 centrifugal pumps Case should be documented in FSAR KNIOHTON, G W Licensing Branch 3 84/07/30 HARRISON, R J Public Service Co of New Hampshire 5pp 26058 325 24X Fiche 50-443,84/07/30,8408130217
- B408090497 Summary of 840717 meeting w/Mestinghouse Dwners Steam Generator Tube Rupture Subgroup in Bethesda.MD re proposed steam generator tube rupture generic program List of attendees & vieugraphs encl
  BINGH B K Licensing Branch 3 04/07/31 Licensing Branch 3 18pp 25983 130 24X Fiche 50-000.84/07/31.8408090497
- 8408370110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933. "Prinritization of Generic Safety Issues " Svc list encl EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of Now York Inc 18pp 26129 238 24X Fiche 50-000.84/08/04.8408070110
- 84081603/1 Forwards honoropiietary WCAP-10566 & proprietary WCAP-10567.

  "Tachnical Bases for Eliminating Laige Primary Loop Pige
  Rupture ," per Generic Ltr 84-04 % application for
  withholding info Proprietary rapt withheld (ref 100FR2 790)
  DE VINCENTIS.J Yankee Atomic Electric Co DF VINCENTIS.J Public
  Bervice Co of Neu Hampshire 84/08/07 KNT0HTDN:0 W Licensing
  Granch 3 2pp 26091 099 24X Fiche 50-443,84/08/09.8408160371
- --8408160373 Requests withholding of stated proprietory rept from public disclosure (ref 1905R2 790) Affidavit CAW-83-80 encl NICSEMANN.R A Westinghouse Electric Corp 84/06/07 DENTON,H R Office of Nuclear Reactor Regulation, Director 6pp 26091 101 24X Fiche 50-443.84/03/09.8408160371
- --8408160378 Nonproprietary "Technical Bases For Eliminating Large Primary Loop Pipe Rupture as Structural Design Hasis for Beabrook Units 1 & 2 " Info deloted (ref 100FR2 770) SWAMY, B A , CLARK, H F , LCE, Y B Westinghouse Electric Corp WGAP-10366 84/06/30 40pp 26071 107 24X Fiche 50-443,84/08/07,8408160371
- 8408230381 Summary of 840939 mgt meeting w/util in Bethesda. MD re status of facility engineering.const licensing.startup. operations & OA Viewgraphs & attendence list encl NERSES: V Licensing Branch 3 84/08/16 Licensing Branch 3 67pp 26230 268 24X Fiche 50-443,84/08/16,8408230381
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re schoduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT, D 0 Division of Licensing 84/08/20 Consolidated Edison Co of Haw York, Inc. 17pp 26276 244 24% Fiche 50-000.84/08/20.8408200275

- E NRU Swfety Evaluation Report (SER), suppls / correspondence
- 840807036I Responds to NRC review of util conformance to NUREG-0737.

  Suppl I SER Outstanding Issue 19 NRC concerns re sys
  function, task analysis 5 control room inventory addressed
  Emergency response procedure program encl
  DEVINCENTIS. J. Yankee Atomic Electric Co. DEVINCENTIS. J. Public
  Service Co. of Neu Hampshire 84/07/30. NNIGHTON. G.W. Licensing
  Branch 3 202pp 25944 284 24X Fiche 50-443,84/07/30.8408070362
- F Security, medical, emergency there protection plans
- 8407300087 Summary of 840711 meeting w/util in Bethesda. MD re revs to fire protection rept Meeting Hotice & attendance roster encl SINOH.8 K Licensing Branch 3 84/07/19 Licensing Branch 3 5pp 25816 333 24K Fiche 50-443.84/07/19,8407300089
- B40B070362 Responds to NRC review of util conformance to NUREO-0737.

  Suppl 1.SER Qutstanding Issue 19 NRC concerns re sys
  function, task analysis & control room inventory addressed
  Emergency response procedure program encl
  DEVINCENTIS.J Yankee Atomic Electric Co DEVINCENTIB.J Public
  Service Co of New Hampshire B4/07/30 KNIGHTUN 6 W Licensing
  Branch 3 202pp 25944 284 24% Fiche 50-443,84/07/30.8408070362
- --8408070365 Rev 1 to Emergency Response Procedure 091300, "Reactor Tr or Safety Injection" \* Yankee Atonic Electric Co 84/06/05 25pp 25945 100 24X Fiche 30-443,84/07/30.8408070362
- Q Adjudicatory correspondence
- 8408010201 Ack receipt of 840723 ltr inviting comments on rept describing visit to racility Staff will not file comments on rept PERLIS.R O Hearing Branch 3 DSB 684 84/07/31 ASSELSTINE, J K Commissioners 2pp 25854 354 24X Fiche 50-443,84/07/31.
- 8408070403 Informs that NRC will not be filing any comments on rept describing Asselstine visit to util PERLISER G Hearing Branch 3 DSB 808 84/07/31 ASSELSTINE, J K Commissioners 2pp 25942 182 24X Fiche 50-443,84/07/31. 8408070403
- 8408140456 Informs that Town of Durham will not file comments on rept describing visit to facility Related correspondence BTILES.N N Durham NH DSB 022 84/08/06 ASSECSTINE, J K Commissioners ip 26060 360 24X Fiche 50-443,84/08/06, 8408140456
- 8408240234 Petition for enforcement to motion for suspension of const Commission cannot find that const at plant can be conducted w/reasonable assurance of safety to must suspend authority for const until owners abtain amend to CP CURRAN.D. JURDAN.W 5 New England Coalition on Nuclear Pollution JURDAN.W 5 Harmon & Weiss DSB 262 84/08/22 Office of Nuclear Reactor Regulation, Director 23pp 26227 331 24X Fiche 50-443.84/08/22.8408240234
- Q Inspection reports: IE Bulletins & Correspondence
- B40B170109 Forwards IE Const Appraisal Team Insp Rept 50-443/B4-07 on B40423-0504 & 14-25 Communication deficiencies resulting from ineffective mgt of interfaces demonstrated Executive summary & list of potential enforcement actions encl DEYGUNG.8 C Director's Office. Diffice of Inspection and Enforcement 84/07/IB HARRIESON.8 J Public Service Co of New Hampshire 9pp 26130 078 24X Fiche 50-443.84/07/18.8408170109
- --8408170117 IE Const Appraisa) Team Insp Rept 50-449/84-07 on 840423-0504 & 14-25 Violations noted failure to identify nonconformances that corrective action for control of cable identification & markings BEACH, A B, GEORGIEV. O B, ROHRBACHER, R A Reactor Construction Branch 84/06/28 101pp 26130 087 24X Fiche 50-443.84/07/18.8408170109
- --8408170117 IE Const Appraisal Team Insp Rept 50-443/84-07 on 840423-0904 & 14-25 Violations noted failure to identify nonconformances & take corrective action for control of cable identification & markings BEACH, A B , PHILLIPS, H W , NONG, H J Reactor Construction Branch 84/06/28 101pp 26130 087 24X Fiche 30-443,84/07/18, 8408170109

- --840B170:17 IE Const Appraisal Team Insp Rept 50-443/84-07 on 840423-0504 & 14-25 Violations noted failure to identify nonconformances & take corrective action for control of cable identification & markings BEACH.AB Reactor Construction Branch GRAY.EH Region 1. Diffice of Director NIGHTINGALE.E Region 3. Office of Director 84/06/28 101pp 26130 087 21% Fiche 50-143.84/07/18.
- 8408150256 Forwards IE Insp Repts 50-443/84-08 & 50-444/84-03 on 840529-0625 % notice of violation STAROSIECKI.R Division of Project / Resident Piograms 84/07/24 HARRISON.R J Public Service Co of New Hampshire 2pp 26076 352 24X Fiche 50-443,84/07/24,8408150256
- ~-8408150258 Notice of vialation from insp on 840527-0425 \* Region 1, Office or Director 84/07/24 ip 26076 354 24X Fiche 50-443.84/07/24.8408150256
- -8409150262 IE Insp Repts 50-443/84-08 ( 50-444/84-03 on 840529-0625 Violation noted inadequate storage f preservation of NSSS components at Unit 2 CERNE.A C , WESCOTT.H M Region 1. Office of Director GALLO,R ( Division of Project & Resident Programs 84/07/11 9pp 26076 355 244 Fichs 30-443.84/07/24.8408150256
- B407250229 IE Info Notice 84-57, "Operating Expellence re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants "Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30107) 84/07/27 Consolidated Edison Co of New York, Inc. 117pp 25865 047 24X Fiche 50-000,84/07/27,8407250229
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JURDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/04 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000.84/08/06,8408010333
- 8408010337 IE Info Notice 84-60, 'Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in FWR
  Refueling Cavity " Syc list encl
  JORDAN.E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/08 Consolidated Edison Co of New
  York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- 8408070376 IE Info Notice 84-82. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl ORACE,J N Division of OA. Safeguards & Inspection Programs (Post 830103) 84/09/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 30-000,84/08/10.8408070376
- 840B100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Bvc list enc!
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) B4/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 30-000,84/08/13,840B100009
- 8408100038 IE Info Notice 84-64, "BWR MPCI Initiation Seal-In & Indication "Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York. Inc 104pp 26198 093 24% Fichs 50-000.84/08/15,8408100038
- 408100021 IE Into Nutice 84-65, "Underlated Fuses which May Adversely Affect Operation of Essential Electrical Equipment" Sectifist end.

  JORDAN, E. L. DIVISION of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26198 001 24X Fichs 50-000.84/08/16,8408100021
- 8408100055 IE Info Notice 84-64. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc. 120pp 26276 001 24% Fiche 50-000,84/08/17,8408100055
- 8408140208 IE Info Notice 81-67, "Recent Snubber Inservice Testing W/ High Failure Rates" Svc Isst enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 630103) 84708/17 Consulidated Edison Co of New York, Inc. 122pp 26274 122 24% Fiche 50-000.84/08/17.8408140208

- B408210142 IF Jefo Notice 84-68 Potential Deticienty in Improperty Rated field Wiring to Solenoid Valves Svr list end: JORDAN, F. L. Pittston of Emergency Preparedness V Engineering Response (Post 835103) B4798 21 Consolidated Edison Co. of New York, Inc. 115pp 26327 0 at 244 finhs 50-000,84708/21,8408210142
- S Reportable occurrences, LER. . related correspondence
- 8408240332 Submits annotated requests for followup on potentially generic problem in enc) fact 21 rept from Basier Electric re SCRs on nuclear excitors mounted without much pressure NDRELIUS, C.C. Division of Project & Resident Programs 84/04/25 JDRDAN, E.L. Director's Office of Inspection and Enforcement ip 26225-303 24% Fich 650-000.84 04 25.8408240332
- B40B100013 Interin deficiency inpt re clacked concrete pedestals supporting diesel generator exhaust silencer tank Initially reported on B40702 Support sys for exhaust silencers & diesel generator trains redesigned DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hompshire. 84/07/30 STAROSTECKI, R. Division of Project & Resident Programs. 3pp. 25990 105 24% Fiche 50-443,84/07/30,8408100013
- 840B100136 Interim dericiency rept re Limitorque motor operators
  Initially reported on 840525 Limitorque improved design by
  replacing fiber shims w/neta) shims Next rept will be
  submitted by 841031
  DEVINCENTIS, J. Jankes Aromic Electric Co. DEVINCENTIS, J. Public
  Service Co. of New Hampshire 84/07/30 STAROBTECKI, R. Division of
  Project & Resident Programs App. 25996-344 24X
  Fiche 50-443,84/07/30,8408100126
- 8408100083 Interin deficiency rept to cracked capstan springs in Pacific Scientific mechanical shock arresters Initially reported an 831024 Caused by improper forming of spring tangs during rifg Suppert shock airesters returned for exam DEVINCENTIS, J. Public Service Co. of New Hampshire 84/07/31 STAROSTECKI, R. Division of Project 9 Resident Programs 4pp 25990 184 24x Fiche 50-443,84/07/31,8408100089
- DOCKET 50-444 GEABROOK NUCLEAR STATION, UNIT 2

  A Application/construction stage documents & correspondence
- 840B370332 Forwards correspondence from two cable manufacturers re apparent deviation from FSAR concerning cable tray loading criteria for heavy power cables Effect on ampacity insignificant Proposed FBAR change encl DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 84/07/12 KNIGHTON, 0 W Licensing Branch 3 10pp 25745 177 24X Fiche 50-443.84/07/12.8408070332
- B40B130717 Accepts conditionally util 840627 request to use ASME Code Case N-368 for application in pressure testing of piping associated w/discharge side of Code Clases 2 & 3 centrifugal purps Case should be documented in FSAR KNIGHTUN, G W Licensing Branch 3 84707/30 HARRISON, R J Public Service Co of New Hampshire 5pp 26058 325 24X Fiche 50-443,84/07/30.8408130217
- B408090497 Summary of 840717 meeting w/Westinghouse Owners Steam Generator Tube Rupiure Subgroup in Bethesda, MD re proposed steam genorator tube rupture generic program List of attendees & vieugraphs encl
  SINCH.B X Licensing Branch 3 84/07/31 Licensing Branch 3 18pp 25983 130 24X Fiche 50-000,84/07/31,8408090497
- B40B370iio Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl I to NUREO-0933, 'Prioritization of Generic Safety Issues" Svc list encl EISENHUT.D G Division of Licensing 84/08/06 Consolidated Edigon Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000,84/08/06.8408070110
- 8408160371 Forwards nonproprietary MCAP-10566 & proprietary WCAP-10567.
  "Technical Bases for Eliminating Large Primary Loop Pipe
  Rupture ," per Generic Ltr 84-04 & application for
  withholding info Proprietary rept withheld (ref 100FR2 790)
  DE VINCENTIS, J Yankee Atomic Electric Co DE VINCENTIS, J Public
  Service Co of Neu Hampshire 84/08/09 KNIGHTON, 0 W Licensing
  Branch 3 2pp 26091 099 244 Fiche 50-443,84/08/09,8408160371
- --8408160373 Requests withholding of stated proprietary rept from public disclosure (ref 10CFR2 790) Affidavit CAW-83-80 encl HIRSEMANN,R A Westinghouse Electric Corp 84/06/07 DENTON,H R Office of Nuclear Reactor Regulation, Director App 26091 101 24X Fiche 50-443,84/08/09,8408160371

1

- --BA)8160378 Nonproprietary Technical Pases For Eliminating Large Primary toop Pipe Rupture as Structural Design Basis for Seabrook Units 1 \* 2 " Inic deleted (ref 100FR2 790) SWAMY S A CLARK H F., LEE,Y S. Westinghouse Electric Corp WCAP-10566 84706730 40pp 26091 107 24X Fichs 50-443 84708709,8408169371
- B408200275 General Lit 84-20 to all licensees of operating reactors & applicants for (Us re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT, D C Division of Licensing 84/08/20 Consolidated Edison Co. of New York, Inc. 17pp 26276 243 244 EISENHUT, D G DIVISION OF LICEN-Edison Co of New York, Inc 17 Fiche 50-000,84/09/20,8408200275
- E NRC Safety Evaluation Report (SER), supply t correspondence
- 84080/0342 Responds to NRC review of util conformance to NUREG-0737, Suppl 1.5ER Dutstanding Issue 19 NRC concerns to sys function, task analysis & control room inventory addressed Emergency response procedure program encl DEVINCENTIS, J. Yankee Atomic Electric Co. 84/07/30 KNIGHTON, G. W. Licensing Branch 3. 202pp. 25744 284. 24% Fiche 50-443,84/07/30, addressed to the control of the control Licensing Branch 3 8408070362
- F Security, medical, emergency & fire protection plans
- 8407300089 Summary of 840711 meeting w/util in Bethesda, MD re revs to fire protection rept Meeting notice & attendance roster enc 1 SINOHUUK Licensing Branch 3 84/07/19 Licensing Branch 3 333 24% Fiche 50-443,84/07/19,8407300089
- B408070362 Responds to NRC review of util conformance to NUREO-0737, Suppl 1.8ER Dutstanding Issue 19 NRC concerns re sysfunction, task analysis & control loom inventory addressed Emergency response procedure program and
- --B408070365 Rev 1 to Emergency Response Procedure OS1300, "Reactor Trip
  - or Safety Injection "
    \* Yankee Atomic Electric Co B
    Fishu 50-443,84/07/30,8408070362 84/06/05 25pp 25945 100 24X
- @ Adjudicatory correspondence
- 8408010.201 Ack receipt or 840723 ltr inviting comments on rept describing visit to facility Staff will not file comments on PERLIS.R G Hearing Branch 3 DSB 684 84/07/31 ASSELS? Commissioners 'Cp 25814 354 24X Fiche 50-443,84/07/31. ASSELSTINE, J K
- 8408070103 Informs that RRC will not be filing any comments on rept describing Asselstine visit to util PERLES.R G Hearing Branch 3 DSB 808 84/07/31 ASSELSTINE, J K Commissioners Ppp 25942 182 24X Fiche 50-443,84/07/31,
- B40B140456 Informs that Tourn of Durham will not file comments on rept describing visit to facility Related correspondence STILES,N W Durham, NH DGB 022 84/08/06 ASSELSTINE, J K Commissioners Ip 26060 369 24X Fiche 50-443,84/08/04,
- 8408240234 Petition for enforcement & motion for suspension of const Commission cannot find that const at plant can be conducted w/reasonable assurance of safety & must suspend authority for const until ouners obtain amend to CP CURRAN, D., JORDAN, W.S. New England Coalition on Nuclear Pollution JORDAN, W.S. Harmon & Weiss D90 262 84/08/22 Office of Nuclear Reactor Regulation, Director 23pp 26227 331 24X Fiche 50-443,84/08/22,8408240234
- Inspection reports IE Bulletins & correspondence
- 8408150256 Forwards IE Insp Rofts 50-443/84-08 % 50-444/84-03 on 840529-0625 & notice of violation 8TAROSTECKLR Division of Project & Resident Programs 84/07/24 HARRISTON.R J Public Service Co of New Hampshire 2pp 26076 3 24X Fiche 50-443-84/07/24,8408150256
- --B408150258 Notice of violation from insp on 840529-0625 \* Region 1. Office of Director 84/07/24 ip 260 Fiche 50 443,84/07/34,8408150256 26076 354

- --8409150242 1E Inso Repts 50-443/84-08 & 50-444/84-03 on 840529-0425 NUMBER OF THE PROPERTY OF A STATE OF A STATE
  - CALLD.R M
- 8407290229 IE Info Notice B4-57. "Operating Experience re Moisture Intrusion in Bafety Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post B30103) 84/07/27 Consolidated Edison Co of 03) 84/07/27 Consolidated Edison Co of New 25865 047 24% Fiche 30-000,84/07/27,8407250229
- 8408010333 IC Info Notice 84-39, "Deliberate Circumventing of Station Health Physics Procedures "Syc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc (22pp 26068 001 24X Fiche 50-000,84/08/06.8408010333
- 8408010337 IE Into Notice 84-60. 'Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JURDANIE L Division of Emergency Proparadness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Respelling Cavaty "Svc list encl
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Respense (Post 830:03) 84/08/08 Consolidated Edison Co 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120 York, Inc
- 84080703/6 IE info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co~60 Teletherapy Treatments " Syc list encl list encl
  ORACL.J N Division of QA, Safeguards & Inspection Programs (Pr 830103) 84/08/10 Consolidated Edison Co. of New York, Inc 125pp 26130 001 24% Fiche 50-000,84/08/10.8408070376
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
- 840B10003B IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication "Sec list enc! JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 833107) 84708/15 Consolidated Edison Co of New York, Inc 104pp 2619B 093 24X Fishe 50-000,84708/15,840B10003B
- 8408100021 IC Info Notice 84-45. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl list enci JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26198 001 24X Fiche 50-000.84/08/16,8408100021
- 8408100055 JE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/09/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 001 24X Fiche 50-000.84/08/17, 8408100055
- 8408140208 IE Info Notice 84-67. "Recent Snubber Inservice Testing H/ High Failure Rates " 8xc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/09/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list enci JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of N York, Inc. 115pp 26329 008 24X Fiche 80-000.84/08/21, 84082101 24X Fiche 50-000,84/08/21,8408210142
- B Reportable occurrences, LERs & related correspondence
- 8408240332 Submits annotated requests for followup on potentially generic problem in enc. Part 21 rept from Basier Electric re SCRs on nuclear exciters mounted w/too much pressure NORELIUS.C E Division of Project & Resident Programs 84/04/25 UGRDAN,E L Director's Office, Office of Inspection and Enforcement 1p 26225 303 24x Fiche 50-000,84/04/25.8408240332

- 840B100013 Interin dericiency rept re clacked concrete pedestals supporting diesel generator echaust silencer tank Instially reported on 840702 Support sys for echaust silencers & reportee on advoca support 14, and diesel generator trains redesigned DEVINCENTIS. J Yankee Atomic Electric Co DEVINCENTIS Servire Co of New Hampshire B4 07/20 STAROSTECKI, R Project 'Resident Programs 3pp 25990 105 24X DEVINCENTIS, J Public Project \* Resident Programs | 34 Project \* Resident Programs | 3pp Fiche 90-443,84/07/30,8403100013
- 8408100136 Interin deficiency rept re Limitorque motor operators Initially reported on 840525 Limitorque improved design by replacing fiber shims u/netal shims Next rept will be replacing fiber shims oviness.
  submitted by 841031
  DEVINCENTIS. J. Janker Atomic Electric Co. DEVINCENTIS.
  DEVINCENTIS. J. Janker Atomic Electric Co. DEVINCENTIS.
  Service Co. of New Harpshire. 84/07.30 STAROSTECKI.R
  Person A. Resident Programs. 4pp. 35996.344.24X DEVINCENTIS, J Public iche 50-443, 84/07/30, 8408100136
- 8408100083 Interin deficiency rept re cracked capstan springs in Pacific Scientific mechanical shock airesters Initially reported on 831024 Caused by improper forming of spring tangs during infg Suspect shock airesters returned for exam DEVINCENTIS. J. Public Service Co. of New Hampshire 84/07/3i STARGSTECKI, R. Division of Project & Resident Programs 4pp 25990 184 24% Fiche 50-443.84/07/31.8408100083
- DOCKET 50-445 COMANCHE PEAN SFEAM ELECTRIC STA . UNIT 1 A Application/construction stage documents \* correspondence
- 8309130110 Forwards FR notice & Director's Decision DD-83-11 denying CASE 830128 100FR? 206 petition for show cause order re ITT Orinnell & NPS Industries Inc design criteria for pipe DEVICE Supports

  DEVOUNG: R C Director's Office. Office of Inspection and
  Enforcement 83/08/18 ELLIS.J Citizens Association for Sound
  Energy 2pp 25975 323 24x Fiche 50-445.83/08/18.8309130110
- --8307130112 Notice of denial of CASE 10CFR2 206 petition requesting util 309130112 Notice of cental of Labs 101-M2 206 perition reque be required to provide documents re ITT Grinnel & NPA Industries, Inc design criteria for pipe supports DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 83/08/19 1p 25975 325 24% Fiche 50-445, 83/08/18,8309130110
- --B309130117 Director's Decision DD-83-11.denying CASE 830128 10CFR2 206 petition for show cause order re-production of ITT Grinnell & NPS Industries. Inc design criteria for pipe supports DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 83/08/19 8pp 25975 326 24X Fiche 50-445,83/08/18,8309130110
- 8311020513 Ack receipt of 830928 response to notice of violation & proposed imposition of civil penalty dtd 830829 Final determination re imposition of civil penalty deferred until resolution of DOL Case 82 ERA-9 DEVOUNG: R Darector's Office. Office of Inspection and Enforcement 83/10/17 GARY, R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 3pp 25975 334 24X Fiche 50-445,83/10/17,8311020513
- 8303300734 Act receipt of Citizens Assoc for Sound Energy petition for show cause order or, in alternative why util should not provide requested documents re component design DEYGUNO, R C Director's Office, Office of Inspection and Enforcement 83/03/03 ELLIS, J Citizens Association for Sound Energy 1p 25951 358 244 Fiche 50-445,84/03/03,8303300734
- --8303300736 Notice of receipt of petition under 10CFR2 206 for order to shou cause or in alternative, why util should not provide requested documents re component design DEVOUNG R C Director's Office, Office of Inspection and Enforcement 83/03/03 2pp 2595i 359 24X Fiche 50-445,84/03/03.8303300734
- 8408010078 Informs that licensee responses to NUREG-0737. Item II F 2. "Instrumentation for Detection of Inadequate Core Caoling." acceptable SSER input & nilestones encl YGUNGBLOD, B J Licensing Branch 1 8407/19 SPENCE.M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 12pp 25897 225 24% Fiche 50-445.84/07/19.8408010078
- B40B010112 Informs that licensee updates to GA organization documented in FEAR Amends 42-49 acceptable Evaluation rapt for inclusion in SER, prior to Unit 1 licensing, enci YOUNOBLOOD. B J Licensing Branch 1 84/07/19 SPENCE, M D Texas Ubilities Electric Co (formerly Texas Utilities December Co ) 5pp 25873 336 24% Fichs 30-445.84/07/19.8408010112

- 8408360155 Notification of DAO a meeting whotil in Bethesda, MD to discuse studies is protective coatings inside containment & impact of custing failures on sump performance under acciding conditions BURNELL 5 B Livensing Blanch 1 84/07/26 YOUNGBLOOD B J Licensing Blanch 1 4pp 25/76 320 24% Fiche 50-445.84/07/26. Licensing Branch 1 B408060155
- 8408130447 Furwards "Control of Heavy Loads (Phase II-NUREG-0612) for Commanche Peak,Units t & 2 " draft technical evaluation rept YouNoBULDO, B J Licensing Branch 1 84'07/26 SPENCE, M D Te Utilities flectric Co (formerly Teras Utilities Generating Co ) Jpp 26059 271 24X Fiche 50-445, 84'07/26, 8408130449
- --B40B130455 Control of Heavy Loads (Phase II-NUREG-0612).Commanthe Peak,Units i \* 2.\* draft technical scaluation rept YEN,I C EQ\*U. Inc FIN A-6457 84/04/30 FIRC No Detailed Affiliation Given 40pp 26059 274 24X Fiche 50-445, 84/07/26.
- B408040145 Responds to Generic Ltr 83-10° re resolution of NUREG-0737, Item II K 3 5, 'Automatic Trip of Reactor Coolant Pumps " Facilities bound by results of Westinghouse Owners Group manual pump trip justification rept
  SCHMIDT.H C Yoxas Utilities Electric Co (formerly Texas Utilities
  Generating Co ) 84/07/27 YCU-980.005.0 J Licensing Branch 1
  1p 25932 197 21X Fiche 50 445,84/07/27.8408060165
- 840809047° Notification of 840803 meeting w/BNL in Glen Rose.TX to discuss util responses to allegations to protective coating practices coating practices VIEITI, A Licensing Branch 3 84/07/27 IPPOLITO.T A Division Licensing 14pp 25983 160 24% Fiche 50-449,84/07/27,8408090479 Division of
- 8408030153 Responds to agenda for 840808 meeting at site re protective coatings practices Requests permission to respond to NRC questions in uniting by 840813 GEORGE, J B Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 84/07/31 IPPOLITO, J A Division of Licensing ip 25912 014 24% Fiche 50-445,84/07/31,8408030153
- 8408090497 Summary of 840717 meeting w/Westinghouse Dunets Steam Oenerator Tube Rupture Subgroup in Dethesda.MD re proposed steam generator tube rupture generic program List of attendees & vieugraphs encl SINGH, B K Licensing Branch 3 84/07/31 Licensing Branch 3 18pp 25983 130 24X Fiche 50-000.84/07/31.84080990497
- 8408090445 Notification of cancellation of 840808 meeting w/BNL in Bethesda MD to discuss util responses to allegations re protective coating practices VIETILA Licensing Branch 3 84/08/01 IPPDLITD.T A Division Licensing 3pp 25983 215 24X Fiche 50-445.84/08/01.8408070445
- 8408090505 Ack receipt of 840/31 request for opportunity to respond to 840727 meeting notice on 840808 meeting w/util re protective coating practices in writing by 840813 Meeting schedule canceled canceled
  IPPOLITO TA Division of Licensing 84/08/02 GEORGE JB T
  Utilities Electric Co (formerly Texas Utilities Generating Co )
  1p 25983 127 24% Fiche 50-445 84/08/02 8408090505
- 8408070455 Board Notification 84-124 forwards info re allegations of improper const practices on main condensers EISENHUT,D G Division of Licensing 84/08/03 BLOCH,P, JORDAN,W, MCCOLLON,K Atomic Sarety and Licensing Board Panel 2pp 25971 001 24X Fiche 50-445,84/08/03,8408070455
- --B408090105 Responds to NRC B40419 ltr re alleged improper const practices involving main condensers QA program not invoked because main condenser not safety-related, but activities monitored closely Leakage testing & detection discussed CLEMENTS.B R Texas Utilities Electric to (formerly Texas Utilities Generating Co ) B4/07/09 BANQART.R L Region 4, Dffice of Director 2pp 25971 032 24X Fiche 50-449.84/08/03, 84/08/070455
- B40B1403B3 Discusses confirmatory measurements performed by util radiachemistry lab on liquid "unknown" sample supplied to NRC ref lab w/known isotopic activities Isotopic activities in liquid sample traceable to NBS lab intercomparison BANGATIR L. Region 4, Office of Director B4/0B/04 SPENCE.M D Texas Utilities Electric Co. (formerly Texas Utilities Onerating Co.) 3pp 26052 343 24X Fiche 50-445,84/08/04,84081403B3
- 8408070110 Generic Ltr 84-19 to all licensess of operating spacetors, applicants for OLs & holders of CPs ro availability of Suppl 1 to NURCO-0933. "Prioritization of Generic Bafety Issues" Svc list encl EISENNUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000,84/08/06,8408070110

- 8408090451 Board Natification 84-132 transmits NRC Special Review Team
- ROBINOPPI Board Maintestor And Section No. Special Review rept to 840403-15 site relied of mot control of const.insp & test programs
  EISENHUT D.G. Division of Licensing 8408/06 PALLADINO
  Consolidated Edison Co. of New York inc. ROBERTS, ASSELSTINE
  Commissioners 72pp 26031-214 24% Fiche 50-445,84/08/06,
- 8408100050 Informs that documents re Mar 1984 T-shirt incident returned to T Vega on 840720 following reproduction BANDART.R L Region 4. Office of Director 84/08/06 SPENCE,M D Texas Utilities Flectric Co (+ormerly Texas Utilities Generating Co) 2pp 25990 038 24X Fiche 50-445.84/08/06,8408100050
- B40Bi601S7 Forwards table providing description of Amend 51 to FSAR MARSHALL.J S Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 84/08/08 BURWELL.S B Office of Nuclear Reactor Regulation Director 3pp 26085 169 24% Fiche 50-445, 84/08/08. Regulation, Director
- 8408170138 Forwards evaluation te resolution of SER Confirmatory Issue 5.7MI action plan items 2 status of review of steam generator tube rupture event generator tube rupture event YDUNGBLODD, B J Licensing Branch 1 84/08/07 SPENCE, M D Te Utilities Electric Co (formerly Texas Utilities Generating Co ) 10pp 26:134 335 24X Fiche 30-445.84/08/09.8408170138
- 8408160335 Responds to 840809 request for add1 info re environ qualification concerning FSAR data for M5-78 M5-76 ESE-27 & ESE-40 & forwards "Radiation Analysis of Barton Model 288A Differential Pressure Indicating Switch , " test rept SCHMIDT.H C Texas Utilities Electric Co (formerly Texas Utilities Cenerating Co) 84/08/10 YOUNGBLOOD, B J Litensing Branch 1 2pp 26085 341 24% Fiche 50-445,84/08/10,8408160335 Texas Utilities
- --B408160340 "Radiation Analysis of Parton Model 28BA Differential Pressure Indicating Suitch for Texas Utils Generating Co " RIEOL.T J Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) E0/185(84)-164 84/08/10 7pp 26085 343 24 Fiche 50-445,84/08/10,8408160335
- B40B160412 Submits list of items for which cable spliting in raceways justified per requirement of Rev 1 to Reg Guide 1 75
  SCHMIDT.H C Texas Utilities Electric Co (Formerly Texas Utilities Oenerating Co ) 8470B/10 YOUNGRC
- 8408200156 Notification of 840814 & 15 meetings w/util in New York, NY to conduct audit review of structural analysis on upper lateral restraint beam prepared for motions for summary disposition
  BURNELL,S B Licensing Branch 1 B4/08/13 YOUNGBLOOD, B J
  Licensing Branch 1 3pp 26142 322 24X Fiche 50-445, B4/08/13,
- 8408280342 Forwards SSER re deferral of listed preoperational tests Proposed deferrals acceptable
  YOUNGBLOOD, B J Licensing Blanch | 84/08/17 SPENCE, M D Te
  Utilities Electric Co (formerly Texas Utilities Generating Co)
  3pp 26294 031 24% Fiche 50-445, 84/08/17, 8408280342
- --8408280346 88ER re deferral of listed preoperational tests Proposed # NRC - No Detailed Affiliation Given 84/08/17 3pp 26294 034 24X Fiche 50-445,84/08/17,8408280342
- 8408200279 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENNUT, D 9 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 50-000,84/08/20,8408200275
- 8408270030 Advises of adoption of Westinghouse generic core damage assessment methodology, in response to NUREO-0737. Item II B 3, "Post-Accident Sampling Capability "
  SCHMIDT.H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 84/08/20 YUUNOBLOOD, B J Licensing Branch 1
  Ip 26245 058 24X Fiche 50-445.84/08/20,8408270030
- 8408270075 Application to amend CPPR-126, reflecting partial exemption from 10CFR50, App A requirements (GDC-4) Fee paid Affidavit enci BPENCE.M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) B4/08/20 YOUNGBLOOD.B J Licensing Branch 1 Spp 26247<sup>1</sup>88 24X Fiche 50-445,84/08/20,8408270073

- 8408270965 Notification of 840823 & 24 meetings w/util in Glen Rose, TX to discuss detailed technical data supporting motions f summary dispositions BURWELLS B Licensing Branch 1 84/08/20 YOUNGBLOO BURNELL, S B Licensing Branch 1 84/08/20 YOUNGBLOOD, B Cicensing Branch 1 5pp 26277 248 24% Fiche 50-449 84/08270565 24X Fiche 50-445, 84/08/20
- 8408270067 Informs that qualification maint program described in FSAR Section 2 4.App 3A will be fully implemented prior to Unit 1 fuel load SCHMIDT.H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co > 84/08/21 YOUNGBLOOD.B J Licensing Branch 1 1p 26247 149 24% Fiche 50-445.84/08/21,8408270067
- 8408270123 Forwards response to NRC 840613 questions re reactor vessel heatup & cooldown Tech Specs
  SCHMIDT.H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/22 vOUNGBLOOD.B J Licensing Branch 1
  11pp 26247 344 24X Fichs 50-445,84/08/22,8408270123
- 8408270132 Informs that steam generator tube rupture reevaluation will include calculations to determine margin to overfill & equilibrium breakflow showing time to overfill is greater than time to equalization.per NRC 840409 requestly state of SCHMIDT.H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) B4/08/22 YOUNGBLOOD,B J Licensing Branch 1 2pp 26245 059 24X Fiche 50-445.84/08/22,8408870132
- B40B280218 Forwards B30216 memo of telcon between util, NRR & BNL reaction required to close out Specifit Item 12,MS34 concerning diesel generator control panel SCHMIDT.H C Toxas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/22 Y0UNGBLODD.B J Licensing Branch 1 3pp 26279 188 24X Fiche 50~445.84/08/22.840B280218
- B40B280461 Notifies that CAW-B9-9 re setpoint methodology for reactor protection sys is proprietary & will be withheld from public disclosure per 10CFR2 790 YOUNGBLOOD, B. J. Licensing Branch 1 B470B/22 HIESEMANN.R A, Westinghouse Electric Corp. 3pp 26292 397 24X Fiche 50-445.B470B/22.B49B280461
- 8408270124 Requests exemption from Section III D 2 b ii of App J to 10CFR50 requiring leakage testing of airlock Overall airlock leakage rate will be measured every 6 months regardless of airlock operating or maint history SCHMIDT.H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/23 (OVINGBLOOD) J Licensing Branch 1 2pp 26246 359 24X Fiche 50-445.84/08/23,8408270124
- 8408280142 Advises that concerns re radiation of BIW silicone insulated cable resolved Calculations examined show lower postulated dose acceptable FSAR will be updated to reflect new valves in next amend
  SCHMIDT.H C Texas Utilities Electric Co (formerly Texas Utilities
  Generating Co ) B4/08/23 YOUNGBLOOD,B J Licensing Branch 1
  1p 26259 077 24X Fiche 50-445,84/08/23,8408280142
- 8408280190 Forwards response to NRC 840807 request for add1 info re 108280190 Forwards response to MMC 840807 request for add1 into resafety parameter display sys List of parameters available in each mode of operation (normal/heat up/cool down &/or cold shutdown) encl
  SCHMIDT.H C Texas Utilities Electric Co (formerly Texas Utilities
  Gunerating Co) 84/08/24 YOUNOBLOOD.B J Licensing Branch 1
  24pp 26275 197 24X Fiche 50-445.84/08/24.8408280190
- 8408300239 Forwards response to 940827 request for info re status of human engineering deficiencies & clarifications to control room design review implementation audit SCHMIDT.H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 84/08/24 YOUNGSLOOD,B J Licensing Branch 1 6pp 24300 123 24% Fiche 50-445.84/08/24, 8408300239
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- 8408140066 Advises of delay in schedule for submitting SBER, per plan for completion of outstanding regulatory actions SBER addresses resolution of outstanding const quality issues from late Aug to end of Sept 1984 IPPOLITO, TA Division of Licensing 84/07/27 BLOCH, PB. JORDAN, W H., MCCOLLOM, K.A. Atomic Sefety and Licensing Board Panel. 5pp 26061 276 24% Fiche 50-445,84/07/27,8408140066
- 8408170138 Forwards evaluation re resolution of SER Confirmatory Issue 5. TMI action plan items & status of review of steam generator tube rupture event YOUNOBLOOD. B. J. Licensing Branch 1 84/08/09 SPENCE, M. D. Ter. Utilities Electric Co. (formerly Texas Utilities Generating Co.) 10pp 26134-335 24X Fiche 50-445, 84/08/09, 8408170138

## F Security, medical, emergency & fire protection plans

- 8408230257 Forwards Gibbs & Hill, Inc "Evaluation of Paint & Insulation Debris Effects on Containment Emergency Sump Performance" Related correspondence REYNOLDS.N S Bishop. Liberman. Cook. Purcell & Reynolds REYNOLDS.N S Teias Utilities Electric Co (formerly Texas Utilities Generating Co ) DSG 222 84/07/05 BLOCH.P B. MCCOLLOM.K A., JORDAN. 44 Atomic Safety and Licensing Board Panel 130pp 26206 166 24X Fiche 50-445.84/07/05.8408230257
- 8408230147 Forwards IE Sareguards Insp Rept 50-445/84-19 on 840529-0606 No violations of deviations noted BANGART.R L. Region 4. Defice of Director 84/07/20 SPENCE.M D Teras Utilities Electric Co (formerly Teras Utilities Generating Co ) 2pp 26213 359 24% Fiche 50-445,84/07/20,8408230147
- "-8408230152 IE Safequards Insp Rept 50-445/84-19 on 840529-0606 No violations noted Major areas inspected security plan & inplementing procedures, mgt effectiveness & security organization Details withheld (ref 10CFR2 790) CALDWELL/R A , HALL/R E , HUNNICUTT, D Region 4, Office of Director 84/07/19 lp 26213 361 24% Fiche 50-445/84/07/20, 8408230147
- B40B090451 Notification of 840B03 meeting ω/util in Bethesda,MD to discuss fire protection program BURNELLS B Licensing Branch 1 84/08/02 YOUNGBLOOD B J Licensing Branch 1 4pp 25983 209 24X Fiche 50-449,84/08/02.
- 8408130267 Forwards request for addl info re Suppl 1 to NUREG-0737 concerning safety parameter display sys Project manager should be prepared to address info request within 5 days of litr receipt YOUNGBLOOD, B. J. Licensing Branch 1 84/08/07 SPENCE, M. D. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.) 5pp 26040 345 24% Fiche 50-445,84/08/07,8408130267
- 8408210158 Forwards status rept re control room design review, per Suppl 1 to NUREO-0737 If plan not fully resolved by fuel load, licensing uill be accomplished on PDA basis VBUNGBLODD B J Licensing Branch 1 84/08/13 SPENCE M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 20pp 26195 287 24X Fiche SO-445.84/08/13.8408210138
- 8408210148 Forwards exercise rept for joint offsite radiological emergency preparedness 831214 exercise Cooperation w/state & local offsiclas to correct deficiencies requested BANGART, R. Region 4. Offsice of Director 84/08/16 SPENCE, M.D. Texas Utilities Electric Co. (Formerly Texas Utilities Generating Co.) ip 26/147-077 24% Fishe 50-445.84/08/16,8408210148
- 8408230390 Forwards "Commanche Peak Steam Electric Station Fire Protection Program Deviations," RBV 1 to "Design Basis Decument Commanche Fire Hazard Analysis" & FSAR Section 9 5 1 U/40 oversize drawings Aperture cards in PDR SCHMIDT.H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 84/08/16 VOUNGELODD, B J Licensing Branch i 2pp 26204 069 24% Fiche 50-445.84/08/16.8408230390
- --8408230397 "Conanche Peak Steam Electric Station Fire Protection Program Deviations " \* Texas Utilities Electric Co (formerly Texas Utilities Generating Co.) 64/08/15 248pp 26204 071 24X Fiche 50-445,84/08/16,8408230390
- --8408230400 Rev 1 to "Design Dasis Document, Comanche Peak Steam Electric Station Firm Hazard Analysis"

  # Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) DBD-8y-1 RO1 84/08/15 287pp 26204 319 24X Fiche 50-445,84/08/16.8408230390
- 8408270368 Forwards marked-up proposed Tech Spec changes re remote shutdown instrumentation, fire detection instrumentation, fire suppression sys & liquid effluents CLEMENTS, B.R. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 84/08/20. YOUNGBLOOD, B.J. Licensing Branch 1 521pp. 26241 028. 24% Fiche 50-445, 84/08/20, 8408270368

# G Adjudicatory correspondence

8408230257 Forwards Gibbs & Mill.Inc "Evaluation of Paint & Insulation Debris Effects on Containment Emergency Sump Performance "Related correspondence REYNOLDS.N S Bishop, Liberman, Cook, Purcell & Reynolds REYNOLDS.N S Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSD 222 84/07/05 ELDCH-P B. MCCOLLOM-K A. JORDAN.W H Atomic Safety and Licensing Board Panel 150pp 26206:166 24X Fiche 50-445.84/07/05.8408230257

- 8408090200 Forwards 840301 ltr re breach or confidentiality involving CASE witness who gave deposition in proceedings under protective order Name of witness openly available to public in FDR for at least 6 days Related correspondence ROISMAN.A Z Trial Lauyers to, Public Justice ROISMAN.A Z Citizens Association for Sound Energy DSB 652 84/08/01 BLOCH.P B Athory Sizely and Licensing Board Panel ip 25971 190 24X Fiche 50-445.84/08/01.8408090200
- --8408090206 Requests info re breach of confidentiality involving CASE witness who gave deposition in proceedings under protective order Name of witness openly available to public in PDR for at least 6 days Related correspondence ROISMAN.A Z Trial Lauyers for Public Justice ROISMAN.A Z Citizens Association for Sound Energy 84/08/01 CHILK Office of the Secretary of the Commission 2pp 25971 191 24X Fiche 50-445,84/08/01,8408090200
- B408090435 Notification of 840808 \* 09 meetings w/util in Bethesda, MD to discuss detailed technical data in motions for summary disposition filed by applicant BURMELL, S.B. Licensing Branch 1 84/08/02 YOUNGBLOOD, B.J. Licensing Branch 1 4pp 25984 275 24X Fiche 50-445, 84/08/02, 8408090435
- B40B130093 Forwards sixth biweekly update on status of important schedule related issues for fuel loading Related correspondence REYMOLDS,N S Bishop. Liberman, Cook. Purcell & Reynolds REYNOLDS,N S Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) DSB 894 84/08/03 BLOCH.P B , MCCOLLOH.K A , JORDAN, M H Atomic Safety and Licensing Roard Panel 12pp 26007 317 24X Fiche 50-445,84/08/03,8408130093
- 8408130305 Submits info in response to discovery lequests re applicant motion for summary disposition Pertinent documentation re ASOO steel pleading encl N/a encl Related correspondence HORIN, WA Bishop. Liberman. Cook. Purcell & Reynolds HORIN, WA Texas Utilities Electric Ca (formerly Texas Utilities Generating Co) DSB 895 84/08/04 ELLIS, J Cittlens Association Found Energy 2pp 26010 257 24% Fiche 50~445.84/08/04,8408130305
- B408090408 Forwards answers to applicant motion for summary disposition re alleged errors made in determining damping factors, allegations re AHS % ASME Code pravisions & frittion force in pipe design Related correspondence ELLIS.J Citizens Association for Sound Energy DSB 877 84/08/06 BLOCH,P B . MCCGLLOM.K A . JORDAN.H H Atomic Safety and Licensing Board Panel ip 25982 231 24% Fiche 50-445,84/08/06.8408090408
- --8408070420 Answer opposing applicant 840316 motion for summary disposition rg alleged errols made in determining damping factors for OBE & SSE loading conditions Related correspondence ELLIS.J Citizens Association for Sound Energy 84/08/06 Atomic Safety and Livensing Board Panel 2pp 25982 232 24% Fiche 50-445,84/08/06.8408070408
- --8408070426 Affidavit of M Walsh in support of CASE answer to applicant statement of natl facts as to which no genuine issue exists re consideration of damping factors for DBE & SSF loading conditions WALSHIM Citizens Association for Sound Energy 84/08/04 13pp 29982 234 24X Fiche 50-445.84/08/04.8408090408
- --B408090434 Forwards M Walsh affidavit on CASE 840806 answer to applicant mution for summary disposition re alleged errors made in determining damping factors for OBE & SSE loading conditions W/o encl Certificate of Svc encl ELLIS.J Citizens Association for Bound Energy B4/08/06 Docketing & Bervices Branch 3pp 25982 247 24X Fiche 50-445.84/08/06.8408090408
- --8408090463 Answer opposing applicant 840517 motion for summary disposition of certain CASE allegations on AMS & ABME Code provisions re design issues Related correspondence ELLIS, J Citizens Association for Sound Energy 84/08/06 Atomic Safety and Licensing Board Panel 2pp 25982 250 24% Fiche 50-445,84/08/06,8408090408
- --B408090471 Affidavit of M Walsh in support of CASE answer to applicant statement of natl facts as to which no genuine issue exists on certain CASE allegations re AWS & ASME Code provisions related to design issues WALBH M Citizens Association for Sound Energy 84/08/04 33pp 23982 232 24X Fiche 50-445,84/08/06,8408090408
- --B408090480 Forwards M Walsh affidavit on CASE 840806 answer to applicant motion for summary disposition of certain CASE allegations on AWS & ASME Code provisions re design issues W/o encl Centificate of Svc encl ELLIS.J Citizens Association for Sound Energy 84/08/06 Docketing & Services Branch 3pp 25982 287 24X Fiche 50-445,84/08/06,8408090408

- IO-90488 Ansuer apposing explicant motion for summary disposition representation of friction forces in design of pipe supports semall thermal novements Related correspondence LIS.J Criticens Association for Sound Energy 84/08/06 omic Safety and Licensing Board Panel 2pp 25982 270 24X che 50-445 84/08/06.8408070408
- O 90512 Forwards J Doyle? M Walsh affidavit re CASE 840806 answer applicant notion for surmary disposition re consideration friction forces in design of pipe supports w/small friction forces in design of pipe supports w/small frield. Citizens Association for Sound Energy 84/08/06 fice of the Secretary of the Commission 3pp 25982 331 24% the 50-445.84/08/06.8408090408
- ICT 162 Motion for authorization to issue license to load fuel & Uct certain precritical testing ICLOS.N S Teras Utilities Electric Co (formerly Teras Utilities rating Co) REYNOLDS.N S Dishop, Liberman, Cook, Purcell & DSI 827 84/08/07 Atomic Safety and Licensing Board 1. 12pp 25960 208 24% Fiche 50-445.84/08/07.8408080162
- CE0168 Affidavit of E Alarcon in support of applicant motion for thereign to issue license to load fuel & conduct train precritical testing Prof qualifications & tificate of Svc encl ARCON.E Texas Utilities Electric Co (formerly Texas Utilities electric Co) and Svc encl Sv
- D413 Forwards correction sheet to affidavit of JC Finneran, o tti & RP Deubler re design of Richmond inserts & ication to support design Related correspondence
  N, N A Bishop, Liberman, Cook, Purcell & Reynolds HORIN, W
  Utilities Electric Co (formerly Texas Utilities Generating D88 846 84/08/07 BLOCH, PB, MCCOLLOM, KA, JDRDAN, W P
  ic Safety and Licensing Board Panel 2pp 25974 052 24X
  2 90-445,84/08/07,8408080413 HORTN. W. A.
- ○470 Forwards copy of list re CASE requests for documents arising of depositions taken in Olen Rose, TX Related 24/00/19
- espondence
  PANIA Z Trial Lawyers for Public Justice DBB 026
  PARIA Dishop, Libernan, Cook, Purcell & Regnolds 3
  Paria 24x Fiche 50-445.84/08/13,840B140475
- O 106 Forwards affidavit of M Walsh 840813 answer to applicant cen for summary disposition to effects of gaps on to tural behavior under seismic loading conditions Related E Spondence
- ES, J. Citizens Association for Sound Energy Ocketing & Services Branch 1p 26085 197 e: 50-445.84/08/13.8408160106 DED 074 84/08/13
- 1 ± 0113 Ansuer to applicant motion for summary disposition reflects of gaps on structural behavior under seismic loading and itions Related correspondence
  LIS.J. Citizens Association for Sound Energy, 84/08/13
  amic Safety and Licensing Board Panel 2pp 26085 198 24:
  Che 50-445,84/08/13,8408160106
- 1 & 0:31 Affidavit of H Walsh in support of answer to applicant a tement of natl facts re effects of gaps on attructural a avior under seismic loading conditions W/Certificate of Related correspondence
- に、Rela L包H, M C. Related correspondence
  LSH,M Citizens Association for Sound Energy
  Omic Bafety and Licensing Board Panel 114pp
  Cho 50-445,84/08/13,8408160106 B470B/13 26085 200 24X
- O 114 Confirms recent discussions re info requested by CASE for in answering various applicant motions for summary O ition Folion exchanges were in response to ASLB 840726 T. Related correspondence S. J. Citizens Associati S. J. Citizens Association for Sound Energy DSB 071 B4.
  IN.W A. Bishop, Liberman, Cook, Purcell & Reynolds 13pp
  5: 184 24x Fiche 50-445.84/09/13.8408160114. B4/08/13
- O 141 Forwards answers to applicant 840518 motion for summary The forwards answers to applicant 840518 motion for sum Osition of CASE allegations resection property values & 15h affidavit Related correspondence

  J. Citizens Association for Sound Energy DBB 072

  Cketing & Services Branch 1p 26071 243 24X

  Ct 50-445,84/08/13.8408160141 DEB 072 84/08/13

- --B408160153 Answer to applicant 840518 motion for summary disposition o 40B160153 Answer to applicant 840014 motion for summary disposit: CASE allegations re section property values ASLB should decide in CASE favor Related correspondence ELLIS, J. Citizens Association for Sound Energy 84/08/13 Atomic Safety and Licensing Board Panel 2pp 26091 244 24X Fiche 50-445,84/08/13.8408140141
- --B408160158 Affidavit of H Walsh in support of CASE answer to applicant statement of mati facts as to which no genuine issue exists on CASE allegations re-section property values Certificate of Svc encl Related correspondence
  WALSHIM Citizens Association for Sound Energy 84/08/12 13pp 26091 246 24X Fiche 50-445,84/08/13,8408160141
- B40B16017: Forwards CASE 840B13 motion for add1 time to respond to applicant motions for summary disposition on design/design GA issues N Walsh affidavit enc? Related correspondence ELLIS. J Citizens Association for Sound Energy DSB 073 84/08 Docketing & Services Oranch 1p 26092-015 24X Fiche 30-445.84/08/13.840B160171 DSB 073 84/09/13
- --8408160178 Motion for add1 time to respond to applicant motions for summary disposition of design/design GA issues Related Correspondence
  EULIS, J Citizens Association for Sound Energy 84/08/13. Atomic Safety and Licensing Boar Fiche 50-445,84/08/13,8408160171
- --8408160187 Affidavit of M Waish in support of CASE motion for add1 time to respond to applicant motions for summary disposition on design/design GA issues Certificate of Svc encl Relat≢d correspondence
  WALSH M Citizens Association for Bound Energy 84/08/12. 8pp
  26092 026 24X Fiche 50-445.84/08/13.8408160171
- 84083i0102 Provides promised info re applicant motion for summary disposition on gaps Related correspondence ELLIS.J Citizens Association for Sound Energy DSB 406 84/08/14 MIZUND.G S Hearing Dranch 1 2pp 26322.281 24% Fiche 50-445.84/08/14.8408310102
- --8408310105 Motion for admission of encl ANI documents into record of proceedings Certificate of Syc encl Related correspondence ELLIG.J Citizens Association for Sound Energy. 84/08/14 Atomic Safety and Licensing Board Panel 276pp. 26322,283. 24X Fiche 50-445,84/08/14,8408310102
- 8408200605 Forwards list of documents necessary for adequate answer to 840703 motion for summary disposition re allegations concerning GA program for design of píping & piping supports.per 849806 telcon Related correspondence.

  ELLIS.J Citizens Association for Sound Energy DBB 144 84/08/15 HORINN A Bishop, Liberman, Cook, Purcell & Reynolds 10pp.

  26137 161 24X Fiche 50-445.84/08/15,8408200605
- 8408210561 Forwards transcripts of 840806.08 & 09 meetings re-motions for summary dispositions, per request W/o encl BURNELL, B B Licensing Branch i 84/08/15 ELLIG, J Citizens Association for Sound Energy ip 26/195-256 24X Fiche 50-445.84/08/15.8408210561
- 8408220331 Responds to 840813 ltr re CASE document requests. R Tolson B00131 memo to T Vega & R Klimist 800206 ltr to R Tolson forwarded Transcript of neeting between util & JJ Lipinsky expected shortly W/o encls Related correspondence BELYER. L W Bishop. Liberman. Cook. Purcell & Reynolds BELTER. L Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 197 84708/16 ROISMAN.A Z Trial Lawyers for Public Justice 2pp 26194 060 24% Fiche 50-445,84/08/16,8408220331
- 8408230187 Forwards seventh biweekly update of important schedulerelated issues for fuel load Related correspondence
  REYNOLDG.N 8 Bishop, Liberman. Gook, Purcell & Reynolds.
  REYNOLDS.N S Texas Utilities Electric Co. (Formarly Texas Utilities
  Generating Co.) D88 215 84/08/16 BLOCKH.P B. JORDAN.W H.,
  MCCDLLOM.K A. Atomic Safety and Licensing Board Panel. 12pp.
  26209 232 24X Fiche 50-445.84/08/16.8408230187
- 8408270065 Forwards Insp Repts 50-445/84-17 re disassembly.insp & reassembly of TDI emergency dissel generator, 50-445/84-05 re allegations on fabrication of pipe supports & restraints & 50-445/84-10 re walkdown Related correspondence.
  MIZUNG 6 S Hearing Branch 1 DBB 304 B4/08/16 BLQCH, PB , JDRDAN, W H , MCCQLIOM, K A Atomic Safety and Licensing Board Panel.
  1p 26247 069 24X Fiche 50-445,84/08/16,8408270065
- 8408270097 Forwards 840621 Insp Repts 50-445/84-11 & 50-446/84-05, consisting of title page & summary portion of Ofc of Investigation Rept 4-84-006 Related correspondence. MIZUND, G. 5 Hearing Branch 1 DSB SOZ 84/08/16 BLOCH, P.B., GROSSHAN, H., JORDAN, W.H. Atomic Safety and Licensing Board Panel. 1p 26247 358 24X Fiche 50-445.84/08/16.8408270097

- 8408220336 Forwards 791218 memo re Item 3 of list of items due omitted from 840816 package (1/o encl Related correspondence BELIER, L W 31shop Liberman, Cook Purcell 8 Reynolds DSB 198 84/08/17 ROISMAN, AZ Trial Lawyers for Public Justice 1p 26194 063 24X Fiche 50-445,84/08/17,8408220336
- B40B230311 Informs of 840817 docketing & in camera filing of ML Speckter 840815 ltd to M Davidson re documents request from Hitness F Lukarhibit containing 15 documents CLEMENTS, H L Docketing / Services Branch DSB 251 84/08/17 Docketing & Services Branch DSB 251 84/08/17 B408230311
- 8408280232 Forwards Insp Repts 50-445/84-12 & 50-446/84-06 on H40320-0518 re status of 10CFR50 55(e) repts & 50-445/84-08 & 50-445/84-08 on B31114-84031 re polar crane shim gaps Related correspondence MIZUND. 6 S Hearing Branch 1 DSB 318 84/08/17 BLOCH. P B , MCCOLLON, K A , JORDAN, W H Atomic Safety and Licensing Board Panel 62pp 26262 287 24x Fiche 50-445,84/08/17,8408280232
- B408240244 Partial answer in apposition to applicant 840807 motion for authorization to issue license to load fuel & conduct certain precritical testing Insp repts & Certificate of Svc encl
- ELLIS.J Citizens Association for Sound Energy DSB 267 84/08/18 Atomic Safety and Licensing Board Panel 54pp 26222 277 24X Fiche 50-445.84/08/18.8408240244
- 8408230319 Submits math re cinching of U-bolts, axial restraints, Richmond inserts & stability.per 840806 telcon between util. GASE & NRC staff HORIN.WA Bishop. Liberman. Couk. Purcell & Reynolds HORIN.WA Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 213 84/08/20 ELLIS.J Citizens Association for Bound Energy 2pp 26205 357 24X Fiche 50-445.84/08/20.8408230319
- B408270179 Forwards testimony of D Hunnicutt re T-shirt incident Hunnicutt testimony provided by agreement of counsel, to suppl deposition of Commins Related correspondence TREBY.S A Hearing Branch 1 DSB 301 84/08/20 BLOCH P B , JORDAN W H , GROSSMAN H Atomic Safety and Licensing Board Panel 23pp 26243 317 24x Fiche 50-445.84/08/20.8408270179
- --8408270186 Motion to strike testimony of D Hunnicutt & JE Cummins as being beyond scope of harassnent & intimidation issue & therefore not relevant to proceeding Certificate of Svc encl Related correspondence
  BACHMANN.R O Hearing Branch 1 84/08/20 Atomic Safety and Licensing Board Panel 5pp 26243 340 24% Fiche 50-443, 84/08/20, 8408270179
- 8408280336 Forwards M Walsh 840819 statement & CASE 840820 answer to applicant motion for surnary disposition of CASE allegations re U-bolts acting as too-way restraints Related correspondence ELLIS.J Citizens Association for Sound Energy DSB 275 84/08/20 Docketing & Services Branch 1p 26275 146 24x Fiche 50-443,84/08/20.8408280136
- --8408280141 Answer to applicant 840523 motion for summary disposition of CASE allegations re U-bolts acting as two-way restraints Applicant statements should be considered as matl false statements
  ELLIS.J Citizens Association for Sound Energy 84/08/20
  Atomic Safety and Licensing Board Panel 2pp 26275 147 24X
  Fithe 50-445,84/08/20.8408280136
- --8408280146 Answer to applicant statement of motl facts as to which there is no genuine issue re CASE allegations regarding U-boits acting as two-way restraints Statement in form of affidavit of M Walsh Certificate of Svc encl MALSH.M Citizens Association for Sound Energy 84/08/19 Atomic Safety and Licensing Board Panel 35pp 26275 149 24% Fiche 50-445,84/08/20.8408280136
- B40B230173 Requests Hartnan be informed of error in interpretation re filing of documents in proceeding Documents should be filed per procedures established by ASLB Related correspondence RUISHAN.A Z Trial Lawyers for Public Justice RDISMAN.A Z Citizens Association for Sound Energy DSB 223 B4/08/21 CLEMENTS, W L Docketing & Services Branch 2pp 26207 271 24X Fichs 50-445,84/08/21.8408230173
- B40827005B Documents receipt & docketing on 840820 of in camera deposition taken on 840815 CLEMENTS, W. Docketing & Services Branch DSB 272 84/08/21 Docketing & Services Branch 1p 26238 141 24X Fiche 50~445-84/08/21.8408270058

- 840B230305 Intonss or 840B22 in camera filing of ML Speckter 840B20 response to M Davidson 840B20 lti CLEMENTS.W.L. Directing 7 Services Branch 1958 252 84708722 Docketing 9 Services Branch 1p 26209 334 24X Fiche 50-445.84708722 840B230305
- 840B270094 Response supporting util 840B0/ motion for authorization to issue license to conduct fuel load / product tical testing MIZUND, G.S. Hearing Branch 1 D58 306 B4/08/22 Atomic Safety and Licensing Board Panel 9pp 26217 305 24X Fiche 50~445;84/08/22,840B270094
- --8408270103 Response supporting util 840802 motion for directed certification of ASLB 840723 order ruling on util motions for summary disposition of Phases I \* 11 Certificate of Svc encl PERLIS.R G Hearing Branch 3 84/08/17 Commissioners 10pp 26247 314 24X Fiche 50-445.84/08/22.8408270094
- 840B2800B3 Forwards not? requested in 840B06 conference call reapplicant motions for surmary disposition Mat1 identified as litem 3 in 840B20 ltr re drawing & calculations for Support FW-1-18-703-C52R W/o Brolls HORIN, W A Bishop, Liberman, Cook, Purcell & Reynolds HORIN, W A Toxas Utilities Electric Co (formerly Toxas Utilities Generating Co) D88 285 84708722 ELLIS, J Citizens Association for Sound Energy 2pp 26261 197 24% Fiche 50-445.84708722, 840B2800B3
- 8408270194 Forwards response to item 6 of things due re transcript of plant personnal meeting U/JJ Lipinsky Travelers requested during S Nowheyer deposition expected shortly M/o enci Related correspondence BELTER.L W Dishop. Liberman, Cook, Purcell & Reynolds DELTER.L W Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSD 282 84/08/23 ROISMAN.A Z Trial Lawyers for Public Justice ip 26245 145 24X Fiche 50-445.84/08/23,8408270154
- B408280221 Exhibit to G Purdy deposition re GC personnel interview PURDY. G Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) DSB 299 84/08/23 (2pp 26269 342 24X Fiche 50-445.84/08/23.8408280321
- 8408280157 Motion to strike listed portions of applicant testimony as impermissible redirect of witnesses Certificate of Svc enc.)
  Related correspondence
  ROISMAN, A Z Trial Lawyers for Public Justice DSB 336 84/08/24
  Atomic Safety and Licensing Board Panel 6pp 26275 075 24X
  Fiche 50-445,84/08/24,8408280157
- 8408280255 Memorandum directing util to supply requested evidence to facilitate further consideration of 840807 motion for authorization to issue license to load fuel % conduct certain precritical testing Served on 840827 BLOCH,P B Atonic Safety and Licensing Board Panel DSB 327 84/08/24 Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 3pp 26261 342 24% Fiche 30-445,84/08/24,8408280255
- B40B2B0265 Response to ASLB B40615 request for additinfo re TDI diesal generators ASLB should conclude that TDI GA program adequate at all times Related correspondence REYMOLDS, N S Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) REYMOLDS, N S Bishop, Liberman, Cook, Purcell & Reymolds DSB 334 B4/08/25 29pp 26262 008 24x

  Fiche 50-445,84/08/25,8408280265
- --8408280268 Affidavit of EJ Kreh re evaluation of TDI GA program TDI GA program acceptable prior to Jul 1980 discovery of auxiliary skid deficiency Prof qualifications & Certificate of Byc encl Related correspondence KREH.E J O'Donnell & Associates. Inc 84/08/24 10pp 26242 037 24X Fiche, 50-445, 84/08/25, 8408280245
- 8408280196 Motion to strike testimony of IL Goldstein Testimony Unreliable, incompetent & w/o foundation to resolve issues Certificate of Svc encl Related correspondence DDWNEY.B L Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) DDWNEY.B L Dishop, Liberman, Cook, Purcell & Reynolds DBB 331 64/08/27 Atomic Safety and Licensing Board Panel 9pp 26275 066 24% Fische 90-449,84/08/27,8408280156
- 8408280165 Motion to open record to receive into evidence, matls rereasons for & circumstances surtounding termination of
  R Hamilton employment Certificate of Svc encl
  WATKINS.M Taxas Utilities Electric Co (formerly Texas Utilities
  Oenerating Co ) WATYINS.M Bishop, Liberman, Cook, purceil &
  Reynolds DSB 332 84708/27 Atomic Safety and Licensing Board
  Panel 10pp 26262 351 24x Fiche 50-445.84/08/27.8408280165

- 8:08280251 Response opposing staff 84:820 motion to strike testimony of D Hunnicutt 7 JE Cummins Testimony relevant to questions re T-shirt incident 'intervenor contentions concerning incident Certificate of 8/c encl Related correspondence DOWNEY, B L leas Utilities Electric Co (formerly Texas Utilities Generating Co) DOWNEY, B L Bishop, Liberman, Cook, Purcell & Reynolds DSB 323 84/08/27 Atomic Safety and Licensing Board Panel 8pp 26261 348 24% Fiche 50-445,84/08/27,8408280251
- 8408280398 Lists documents redocketed in Docketing & Syc Branch on 840821 Served on 840827 CHILFS J Office of the Secretary of the Commission DSB 349 84/08/27 Atomic Safety and Licensing Board Panel 1p 26280 031 24X Fishe 50-415.84/08/27,8408280398
- 8408290319 Notion to strike listed portions of applicant testimony Certificate of Svc encl Related correspondence ROISMAN.A Z Citizens Association for Sound Energy ROISMAN.A Z Trial Lawyers for Public Justice DSB 377 84/08/27 Atomic Safety and Licensing Board Panel 6pp 26289 349 24X Fiche 90-445,84/08/27,8408290319
- 8408300139 Forwards original % Rev 2 to Reg Guide 1.75,per Q Berry commitment Rev 1 to Reg Guide 1.75 bound in Disposition Exhibit Distlosure F-9a H/o encl Related correspondence HIZUNO.0 S Hearing Branch 1 DSB 382 84/08/27 SPEKTER, M L Affiliation Not Assigned to 26304 362 24X Fiche 50-443, 84/08/27. 8408300139
- 840B310216 Forwards transcript of 83(110-1) meetings at facility reprotective coatings & Lipinsky memorandum W/o encl Related correspondence
  HDRIN, W A Dishop. Liberman Cook, Purcell & Reynolds HORIN, W A Texas Utilities Electric Co (formerly Texas Utilities Generating Co) B80 8470B/279 BLOCH. PB A thonic Safety and Licensing Board Panel 1p 26318 116 24X Fiche 50-445,84708/29,840B310216
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8408140393 Amend 51 to FSAR for Comarche Peak W/840810 ltr SPENCE.M D Faxas Utilities Electric Co Generating Co ) 84/08/08 DENTGN. H R Office of Nuclear Reactor Regulation. Director 80pp 26048 019 24X Fiche 30~445,84/09/08, 8408140393
- 840B290208 Forwards Amend 52 to FSAR Affidavit encl CLEMENTS,B R Texas Util) thes Electric Co (formerly Texas Utilities Generating Co ) 84/08/27 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 26287 254 24X Fiche 50-445,84/08/27, 8408290208
- --8408290211 Amend 52 to FSAR \* Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 84708/27 681pp 26287 260 24X Fiche 50-445,84708/27,8408290208
- O Inspection reports: IE Bulletins & correspondence
- 8408010098 Discusses 830827-0902 insp of BIW Cable Sys.Inc (BIW) equipment qualification testing program Environ qualification of silicone insulated cable inadequate Requests verification of BIW qualification matl YOUNGULOOD B J Licensing Branch is 84/07/19 SPENCE.M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 4pp 25897 040 24% Fiche 50-445.84/07/19.8408010098
- 8408230147 Forwards IE Safeguards Insp Rept 50-445/84-19 on 840529-0606 No violations or deviations noted 8ANGART.R L Region 4, Office of Director 84/07/20 SPENCE,M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 26213 359 24X Fiche 50-445,84/07/20.8408230147
- --B40B230152 IE Safeguards Insp Rept 50-443/84-17 on 840529-0606 No violations noted Major areas inspected security plan & inplementing procedures, mgt effectiveness & security organization Details withheld (ref 100FR2 790)
  CALDMELL, R A. HALL, R E. HUNNICUTT, D. Region 4, Office of Director 84/07/19 lp 26213 361, 24X Fiche 50-445,84/07/20, 8408230147
- B40B150647 Forwards IE Insp Rept. 50-445/84-12 & 50-446/84-06 on B40320-0518 No violations or deviations noted BANCART.R L Region 4, Office of Director 84/07/23 SPENCE,M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 26079 188 24% Fiche 50-445.84/07/23,8408150649

- 8408130633 IE Insp Repts 30-445/84-12 & 30-446/84-06 on 840320-0518 Noviblations noted Major areas inspected plant status, licensee action on previous Findings, 10CFR30 55(e) rept followup. IE bulletin followup & plant toors CUMMINS.JE , MCNEILL.W M , TOMLINSON,D P Region 4, Office of Otrector 84/06/21 18pp 26079 190 24X Fiche 50-445.84/07/23, 8408150649
- 8408160201 Ack receipt of 840527 response to 840430 ltr re insp techniques for assessing extent of unauthorized weld repairs Response inadequate Requests detailed sampling plan & precedure within 20 days BANOART.R L Region 4. Office of Director 84/07/23 SPENCE.M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 26106 300 24% Fiche 50-445.84/07/23.8408160201
- --B408160204 Responds to 840430 ltr re plug welds in spread room Visual into will be performed using methods similar to those described in addendum to 840424 testimony Program requiring repair instructions & OC insp followed CLEMENTS, 8 R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/05/29 BANQART, R L Region 4. Office of Director 1p 26106 302 24X Fiche 50-445, 84/07/23, 84/08160201
- 8408150071 Forwards IE Insp Repts 50-445/84-08 & 50-446/84-04 on 831114-840331 & notices of violation & deviation Major areas inspected Part 21 follows & training of protective coatings inspectors

  BANGART.R L Region 4. Office of Director 84/07/26 SPENCE.M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pp 26073 304 24% Fichs 50-448,84/07/26,8408150091
- --8408150094 Notice of Violation from insp on 831114-840331 4 Region 4, Office of Director 84/07/26 2pp 26073:307 24) Fishe 50-445,84/07/24,8408150091
- --8408150097 Notice of deviation from insp on 831114-840331 \* Region 4. Office of Director 84/07/26 2pp 26073.311 24X Fithe 50-445,84/07/26,8408150091
- ---E408150102 IE Insp Repts 50-445/84-08 & 50-446/84-04 on 831114-840331 Violations & deviations noted unshimmed gaps exceed 1/16 inch on polar crane bracket & seismic connections & licensee did not incorporate objectives of ANSI N45 2 f1 into design CUMMING.J E , SMITH.W F , MARTIN.L E Region 4, Office of Director 84/07/26 10pp 26073 313 24X Fiche 50-445.84/07/26, 8408150091
- 8408130414 Forwards IE Insp Rept 30-445/84-18 on 84050;-31 & notice of violation Areas inspected include preoperational test witnessing, followup of TDI diesel generator insp & plant tours
  BANOARTIR L Region 4, Office of Director 84/07/26 SPENCE, M :
  Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 26077 252 24% Fichs 50-445.84/07/26.8408150414
- --8408150417 Notice of violation from insp on 840501-31 \* Region 4. Office of Director 84/07/26 2pp 26077 254 24) Fiche 50-445,84/07/26,8408150414
- --B408150440 IE Insp Rept 50-445/84-IB on B40501-31 Violations noted failure to follow procedure during Traim A emergency diesel generator auxiliary aye retest & hold tags improperly removed from Traim A diesel engine KELLEV, D L . SMITH.W F . HUNNICUTT.D M Region 4. Office of Director B4/07/06 10pp 26077 256 24X Fiche 50-445,84/07/26,8408150414
- 8408160026 Forwards IE Insp Rept 50-445/84-20 on 840503-0619 No violations or deviations identified BANOART,R L Region 4. Office of Director 84/07/26 SPENCE,M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 26108 150 24% Fishe 50-445,84/07/26,8408160026
- --840816003/ IE Insp Rep+ 50-445/84-20 on 840503-0619 No violations ors deviations noted Major areas inspected work & documentation associated w/site portion of recertification program inplemented on Train B 701 emergency diesel generator SMITH.W F. HUNNICUTT.D II Region 4. Office of Director. 84/07/05 9pp 26108 152 24X Fiche 50-445.84/07/26.8408160026
- 8407250229 IE Info Notice 84-57. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Flants " Syc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc. 11980 25865 047 24X Fiche 30-000,84/07/27,8407250229

- T Hearing transcripts on non-antitrust matters
- 8407310383 Transcript of 840723 Felcon in Glen Rose, TX Pp 38, 567-84/07/23 91pp

28.654 \* Atomic Safety and Licensing Board Panel 84/025830 173 24% Fiche 50-445.81/07/23.8407310383

- B408080027 Transcript or L Barnes B40728 deposition in Glen Rose, TV, re harassment & Intinidation at Facility Pp 59:000-59, 246 Supporting documentation encl \* Atomic Safety and Licensing Board Panel BARNES, L Brown & Root, Inc (subs of Hallburton Co) B4/07/28 269pp 25969 066 24X Fiche 50-445, 94/07/28, 8408080027
  - Brown & Root,
- 8408070273 Transcript of M Rhodes,W Sims,M Todd & S Burns 840730 deposition Pp 72:000-72:160 m Atomic Safety and Licensing Board Panel RHDDRS,M L Ebasco Services, Inc. (subs of Enserch Corp.) SIMS,W T Brown & Root, Inc. (subs of Halliburton Co.) 84/07/30 175pp 25949 024 24X Fiche 50-445.84/07/30.8408070273
- E408080237 Transcript of C Biggs, C Fanning, R Whitman & J Uehlein 840730 depositions in Olen Rose, TX Pp 71.500-71, 659 Supporting documentation encl + Atomic Safety and Licensing Board Panel BIGGS, C., FANNING, C Brown & Root, Inc. (subs. of Halliburton Co.) E4/07/30 170pp 23967 237 24X Fiche 50-445,84/07/30,8408080257
- B408070105 Vol II of transcript of M Gregory B40731 deposition in Glen Rose.TX Pp 54.559-54.718 Supporting documentation enci Atomic Bafety and Licensing Board Panel GREGORY.M Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) OREGORY.M Broun & Root, Inc (subs of Halliburton Co ) 204pp 25950 045 244 Fiche 50~445.84/07/31,8408070105
- 8408080051 Transcript of J Pitts 840731 deposition in Glem Rose, TX Pp 73,500-73,553
- Pp 73.500-73.553

  \* Atomic Safety and Licensing Board Panel PITTS, J Texas
  Utilities Electric Co. (formerly Texas Utilities Generating Co.)
  PITTS, J Ebasco Services, Inc. (subs. of Enserch Corp.) 84/07
  55pp 25960 333 24% Fiche 50-445,84/07/31,8408080051 84/07/31

- 8408080245 Transcript or D Anderson, S Spencer & A Boren 840731 depositions in Clen Rose, TX Pp 72, 500-72, 681 Supporting focumentation encl # Atomic Safety and Licensing Board Panel SPENCER, 9, BOREN, A Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/07/31 1889p 25967 065 24% Fiche S0-445, 84/07/31, 8408080245
- B40B0B0023 Transcript of ST Hoggard 840B01 deposition in Glen Rose, TX Pp 74.000-74.016 Supporting documentation encl # Atomic Safety and Licensing Board Panel HUGGARD, S T Brown & Root. Inc (subs of Halliburton Co ) 84/08/01 24pp 25761 337 24X Fiche 30-445.84/08/01.840B080023
- 8408080032 Transcript of HF Gunn 840801 deposition in Glan Rose, TX Pp 75.000-75.008
- Pp 75.000-75.008

  \* Atomic Safety and Licensing Board Panel GUNN, H F Texas
  Utilities Electric Co (formerly Texas Utilities Generating Co)
  GUNN. H F Brown & Root, Inc (subs of Halliburton Co) 84/08/01
  11pp 25967 023 24% Fiche 50-445.64/08/01.8498880032
- 8408080089 Transcript of JN Scarbrough & D Ethridge depositions in Glen Rose, TX Pp 74,500-74.521 Supporting documentation encl & Atomic Safety and Licensing Board Panel SCARBROUGH, J N . ETHRIDGE, D Brown & Roof, Inc (subs of Halliburton Co) 84/08/01 26pp 25965 167 24% Fiche 50-445.84/08/01.8408080089
- 8408080272 Transcript of S4 Neumeyer 840801 deposition in Glen Rose, TX Pp 59.500-59.683 Supporting documentation enc!

  \* Atomic Safety and Licensing Board Panel NEUMEYER, S A Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/01 207pp 25966 080 24% Fichs 50-445.84/08/01.8408080272
- 8408080146 Transcript of DN Chapman 840802 deposition in Glen Rose, TX Ps 76.500-76.631 Supporting documentation encl \* Atomic Safety and Licensing Board Panel CHAPMAN, D N Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/02 280pp 25959 278 24% Fiche 50-445.84/08/02.8408080146
- 8408080296 Transcript of 840862 telcon in Glan Rose, TX pp 38,690-39.726

  \* Atomic Safety and Licensing Board Panel 84/08/02 39pp
  25764 321 24% Fiche 50-445,84/08/02,8408080296

- 8408160501 Forwards transcript or #10727 meching in Bethesda MD re
- --B408160502 Transcript of B40°27 moeting in Bellic da, MP re containment sump performance Pp 1-113 Supporting documentation encl \* Commistances 84/07/27 123pp 26124 180 24% Fiche 50 145,89 08/02.8408160501
- B40B0B0026 Transcript of the coats B40B03 deposition in Olth Rose, TX Pp 77,500-77,558 Supporting documentation encl # Atomic Safety and Licensing Board Panul (HATS.II L. Texas Utilities Electric Co. (Eurmerly locas Utilities Generating Co.) B470B703 B1pp 25966 302 P4X fiche 50-445, H470B703, B40B0B0026
- 8408080294 Transcript of J. Keller 840H03 deposition in Glen Rose.TX Pp 78.000-78.026 Supporting document, it on whit ( \* Atomic Safety and Licensing Board Pamel KELLER, J C Texas Utilities Electric Co (formerly lears Willities Genorating Co) KELLER, J C Westinghouse Electric corp 84/08/03 36pp 25965-270 24X Fiche 50-445.04 000/03, 8408080294
- 8408220173 Board Motification 84-137 forwards transcript of 840607 meeting w/applicant to 840604 proposed FSAR amend on protective coatings EISENNUT.D G Division of Licensing 84/08/1/ BLOCH,P, JORDAN, W. HCCOLLO4, U. Atomic Safety and Licensing Board Panel 3pp 26262 098 24% Fiche 50 445,84/08/1/,8408720173
- --8408280266 Transcript of 840607 meeting w/applicant in Bethesda.MD reprotective coating inside containment Pp 1-100
  \* tommissioners 84/06/07 120pp 26262 101 24X
  Fichs 50-445.84/08/1/.8408/2/01/7
- 8408230432 Notice of filing in Docketing 3.5 or Blanch of O Purdy in camera deposition in Gien Rose, 1%.
  PURDY, D. Teias Utilities [Lectric Co. (formerly leias Utilities Generating Co.) DSG-707 84708718 2pp 26204 007 24X
  Fiche 50-445,84708/19,8408230432
- B40B2203A7 Forwards prefiled testimony of RM Duncan, RD HeBee, R Simpson, DR Hright, JE Zwahr, bt Willerding & JF Grown, depositions of JN Starbough of all A affidavit of DR Egbert Certificate of Sv. entil HARTHAN, S.L. Birhop, Liberman, Cook, Purcell & Roynolds HARTMAN, S.L. Texas Utilities Electric (o. (formerly texas Utilities Generating Co.) DSB 206 84/08/20 (LEMENTS, W.L. Ducketing & Services Branch 1pp 26192 126 247 Fiche 30-440, 04/08/20, 840820347
- ~~8408220371 Profiled testimony of AD Justice on 840816 in Olen Rose.TX Pp 1-20
  JUSTICE: A B Texas Utilities Electric Co (formerly Taxas
  Utilities Generating Co) JUSTICE: A B Brown & Root, Inc (subs
  of Halliburton Co) B4/08/16 20pp 26172 130 24X
  Firhs 30-445,64/08/20,8408220167
- --8408220374 Prefiled testimony of RM Duncan on 040815 in Olen Rose, TX 1082203/4 Prefitor vestimony of the Company Profitor Pp 1-17

  PUNCAN.R M Toxas Utilities Electric Co (formorly Texas Utilities Generating Co ) DUNCAN.R M Brown / Roat, Inc (subs of Halliburton Co ) 84/08/15 23pp 26197 150 24X

  Fichs 50-445,84/08/20.840822036/
- --8408220380 Profiled testimony of RD McBee on 840816 in Glen Rose, TX Pp 1-24
  MCNEC.R D Toxas Utilities Electric Co (formerly Texas Utilities
  Generating Co ) MCDEE.R D Brown & Root, Inc (subs of
  Halliburton Co ) 8-7-08-16 dSpp 26192 173 24X
  Fight 50-445, 84-08/20. 840822036/
- --8409220381 Prefiled testimony of RW Simpson on 840815 in Glen Rose,TX Pp 1-38
  SIMPSON,R W Texas Utilities Electric Co (formorly Texas
  Utilities Generating Co ) SIMPSON,R W Brown & Root. Inc (subs
  of Hallburton Co ) 84/08/15 42pp 26192 208 24X
  Fiche 50-445,84/08/20.8408220367
- --8408220385 Prefiled testimony of DR Wright on 840816 in Glen Rose, TX Pp 1-9
  HRIGHT, D.R. Texas Utilities Electric Co. (formerly Texas Utilities
  Generating Co.) HRIGHT, D.R. Brown & Root, Inc. (subs. of
  Halliburton Co.) 84/08/16 9pp 26192 260 24X
  Fiche S0-445,84/08/20,840822036/
- ~-B408220388 Prefiled testimony of UE Zwahr / DT Wilterding on B40815 in Glen Rose, TX Pp 1-21
  ZWAMR.J E , WILTERDING, D T Texas Utilities Electric Co (formerly Texas Utilitys Generating Co ) ZWAMR.J E Brown & Root, Inc (subs of Halliburton Co ) 84.08/15 29pp 26192 269 24X
  Fiche 30-445, G4.08/20, B40822036/

- --B408220393 Prefiled testimony of JE Brown on 840815 in Olen Rose.TX Pp 1-21 BROWN.J E Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) BROWN.J E Brown & Root. Inc (subs of Halliturton Co ) 84/08/15 27pp 26192 298 24X Fiche 50-445.84/08/20.8408220367
- --8408220396 Deposition of ST Hoggard on 840801 in Glen Rose,TX Pp 74,000-74,016 Personal resume encl HOGGARD,S T Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 84/08/01 23pp 26192 327 24) Fiche 50-445,84/08/20,8408220367
- --8408220399 Affidavit of DK Egbert re discussion ω/DK Stiner in Oct 1982 concerning employee benefits EGBERT.D K Broun & Root. Inc (subs of Halliburton Co ) 84/08/01 7pp 26192 350 24X Fiche 50-445,84/08/20,8408220367
- --8408220403 Deposition of JN Scarbrough & D Ethridge on 840801 in Olen Rose, TX Pp 74, 500-74, 521

  SCARBROUGH, J N . EIHRIDGE, D Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) SCARBROUGH, J N Brown & Root, inc (subs of Halliburton Co ) 84/08/01 27pp 26192 357 24X Fiche 50-445,84/08/20,8408220367
- --8408220405 Deposition of HF Gunn on 840801 in Glen Rose,TX Pp 75.000-75.008 QNNN HF Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) GUNN HF Brown & Root, Inc (subs of Hallburton Co ) 84/08/201 | 10pp 26193 022 24X Fiche 50-445,84/08/20,8408220367
- 8408240247 Forwards CASE 840820 prefiled testimony of IL Goldstein re harasament & intimidation ROISMAN.A Z Trial Lawyers for Public Justice ROISMAN.A Z Citizens Association for Sound Energy D88 257 84/08/20 BLOCH.P B , GROSSMAN.H , JORDAN.W H Atomic Bafety and Licensing Board Panel 1p 26223 119 24X Fiche 50-445,84/08/20,8408240247
- ---8408240248 Written testimony of IL Goldstein re harassment & intimidation
  GOLDSTEIN, I L. Citizens Association for Sound Energy
  GOLDSTEIN, I L. Maryland, Univ of, College Park, MD 84/08/20
  45pp 26223 120 24X Fiche 50-445,84/08/20,8408240247
- 8408240302 Transcript of 840822 hearing in Bethesda, MD Pp 13, 945-14,014 \* Abomic Safety and Licensing Board Panel 84/08/22 51pp 26225 321 24X Fiche 50-445, 84/08/22, 8408240302
- 8408300103 Transcript of 840827 hearing in Bethesda, MD Pp 14, 015-14, 180 \* Atomic Safety and Licensing Board Panel 84/08/27 168pp 26305 001 24X Fiche 50-445, 84/08/27, 8408300103

#### V Operator Examinations

- 8408140266 Lists ref matl required for administration of written exams scheduled for 840910 & operator exams scheduled for wks of 840909 & 16 Matl should be submitted by 840815 HUNTER, D R Region 4, Office of Director 84/08/08 CLEMENTS, B R Texas Utilities Electric Co (formerly Texas Utilities Omnerating Co ) 6pp 26055 333 24X Fichs 50-445,84/08/08,8408140266
- X Onsite Starage of Low Level Waste
- 8408270271 Advises of executed Contract DE-GR01-84RW00012 w/DDE for disposal of spent nuclear fuel from facilities Related info enc!

  8CHMIDT.H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 84/08/21 YOUNGBLOOD,B N Licensing Branch 1 3pp 26241 015 24X Fiche 50-445.84/08/21,8408270271
- DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA . UNIT 2

  A Application/construction stage documents & correspondence
- 8309130110 Forwards FR notice & Director's Decision DD-83-11 denying CASE 830128 10CFR2 206 petition for show cause order re ITT Grinnell & NPS Industries. Inc design criteria for pipe supports
  DEYGUNG.R C Director's Office. Office of Inspection and
  - DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 83/08/18 ELLIB,J Citizens Association for Sound Energy 2pp 25975 323 24% Fiche 50-445,83/08/18,8309130110

- --B309130112 Notice of denial of CASE 10CFR2 206 petition requesting of 11 be required to provide documents re ITT Grinnol & NPA industries. Inc design criteria for pape supports DEYOUNG R C Director's Office of fine pertian and Enforcement B3/09/19 1p 25975 325 24% Fiche 50-445. B3/08/16. B309130110
- --B309130117 Director's Decision DD-83-11, denying CASE 830128 locFR2 206 petition for show cause order to production of ITT Grinnell & NPS Industries, Inc design criteria for pipe supports DEYOUNG.R C Director's Office Office of Inspection and Enforcement B3/09/19 8pp 25975 326 24X Fiche 50-445, 83/08/18, 8309130110
- 8311020513 Ack receipt of 830928 response to notice of violation & proposed imposition of civil penalty dtd 830827 Final determination re imposition of civil penalty deformed until resolution of DDL Case 82 ERA-9 DEYOUND, R Director's Office, Office of Inspection and Enforcement 83/10/17 GARY, N Texas Utilities Electric Co (formerly Texas Utilities Cenerating Co) 3pp 25975 334 24X Fiche 50-445,83/10/17,8311020513
- 8303300734 Ack receipt of Citizens Assoc for Sound Energy petition for show cause order or in alternative, why util should not provide requested documents re component design DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/03 ELLIS, J Citizens Association for Sound Energy 1p 25751 338 24x Fiche 50-445.84/03/03.8303300734
- --8303300736 Notice of receipt of petition under 10CFR2 206 for order to show cause on, in alternative, why util should not provide requested documents re component dosign DEYOUNO.R C Director's Office. Office of Inspection and Enforcement 83/03/03 2pp 29951 359 24X Fiche 50-445,84/03/03,8303300734
- 8408010078 Informs that licensee responses to NUREQ-0737, Item II F 2. "Instrumentation for Detection of Inadequate Core Cooling." acceptable 868R input & nilestones enc! YOUNOBLOOD. B J Licensing Branch 1 84/07/19 SPENCE.M D Texas Utilities Electric Co. (formerly Texas Utilities Cenerating Co.) 12pp 23897-225 24X Fiche 50-445.84/07/19.8408010078
- 8408010112 Informs that licensoe updates to GA organization documented in FSAR Amends 42-49 acceptable Evaluation rept for inclusion in SSER prior to Unit i licensing.encl YOUNGBLODD, D. Licensing Branch I 84/07/19 SPENCE, M.D. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.) 5pp 25873 336 24% Fiche 50-445.84/07/19.8408010112
- 840B130449 Forwards "Control of Heavy Loads (Phase II-NUREG-0612) for Commanche Peak, Units 1 & 2," draft technical evaluation rept youNoBLOOD, 3 J Licensing Branch 1 B4/07/26 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Cenerating Co) 3pp 26059 271 24% Fiche 50-445,84/07/26,840B130449
- --B40Bi30455 "Control of Heavy Loads (Phase II-NUREO-0612), Commanthe Peak, Units i \$2." diaft technical evaluation rept YEN.T C EGG. Inc FIN A-6457 B4/04/30 NRC - No Detailed Affiliation Givon 40pp 26059 274 24X Fiche 50-445,844/07/26, 880Bi30469
- B40B060165 Responds to Generic Ltr B3-10C re resolution of NUREG-0737, Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps" Facilities bound by results of Westinghouse Owners Group manual pump trip justification rept SCHMIDT.H C Texas Utilities Electric Co (formerly Toxas Utilities Generating Co) B4/07/27 YUUNOBLOOD, B J Liconsing Branch 1 ip 25932 197 24X Fiche 50-445.84/07/27.8408060165
- 8408090479 Notification of 840808 meeting w/BNL in Olen Rose, TX to discuss util responses to allegations re protective coating practices VIETTI.A Licensing Branch 3 84/07/27 IPPOLIFO, TA Division of Licensing 14pp 25983 160 24X Fiche 50-445,84/07/27,8408090479
- 8408030153 Responds to agenda for 840808 meeting at site re protective coatings practices Requests permission to respond to NRC questions in writing by 840813 GEORGE. J B Texas Utilities Electric Co (formerly Texas Utilities Contrating Co ) 84/07/31 IPPDLITGLJ A Division of Licensing ip 25912 014 24% Fiche 50-445,84/07/31,8408030153
- B408090497 Bummary of 840717 meeting w/Westinghouse Gwners Steam Conerator Yube Rupture Subgroup in Bethesda, MD re proposed steam generator tube rupture generic program List of attendees & vieugraphs encl SINON, B K Licensing Branch 3 84/07/31 Licensing Branch 3 18pp 25983 130 24X Fiche 50-000,84/07/31,8408090497

- 8408090449 Notification of cancellation of 840808 meeting w/BNL in Bethesda.ND to discuss util responses to allegations re protective coating practices VEETLA Licensing Branch 3 84/08/G1 IPPOLITO.T A Division of Licensing 3pp 25983-215 24x Fiche 50-445.84/08/G1.8408090445
- 8408090505 Act teceipt of 840731 request for apportunity to respond to 840727 merting notice on 840803 meeting w/util re-protective coating practices in writing by 840813 Meeting schedule canceled iPPBLITO.TA Division of Licensing 84/08/02 GEORGE.JB Texas Utilities Flectric Co (formerly Texas Utilities Generating Co) ip 25983 127 24% Fiche 30-445.84/08/02.8408090505
- 8408070455 Board Notification 84-124 forwards info re allegations of improper const practices on main condensers EISENHUT.D @ Division of Licensing 81/08/03 BLOCH,F., JORDAN.W., MCCCLLON.W. Atomic Safety and Licensing Board Panel 2pp 25971 001 24X Fiche 50-445/84/08/03.8408070485
- --B408090105 Responds to NRC 840619 ltr re alleged improper const practices involving nain condensers QA program not invoked because main condenser not safety-related, but activities monitored closely Leakage testing & detection discussed CLEMENTS.B R Texas Utilities Electric Co (formerly Texas Utilities Generaling Co) 84707/09 BANGART.R L Region 4, Office of Dire to. 2pp 25971 032 24% Fiche 50-445.84/08/03,8408070483
- B40B0701iO Generic Ltr B4-i9 to all licensees of operating reactors, applicants for GLs % holders of CPs re availability of Suppl 1 to NUREO-0733. "Prioritization of Generic Safety Issues "Syc list enc! EISENHUT.D 0 Division of Licensing B4/08/06 Consolidated Edison Co of Neu York. Inc. 18pp 26129 238 24X Fiche 50-000.84/08/06.840B070110
- 8408080454 Board Notification 84-132 transmits NRC Special Review Team rept re 840403-13 site review of mgt control of const.insp & test programs
  FISENHULD 6 Division of Licensing 84/08/06 PALLADINO
  Consolidated Edison Co. of New York, Inc. ROBERTS, ASSELSTINE
  Commissioners /...2 24031 214 24X Fiche 50-445,84/08/06.
  840F070455
- 8408100050 informs that documents re Mar 1984 T-shirt incident returned to Y Vega on 840720 following reproduction BANGARTIR L. Region 4. Office of Director 84/08/06 SPENCE.M D Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.) 2pp 25990 038 24X Fiche 50-445.84/08/06.8408100050
- G408140157 Forwards table providing description of Amend 51 to FSAR MARGHALL.J S Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 84/08/08 BURWELL,S B Office of Nuclear Reactor Regulation, Director 3pp 26085 169 24X Fiche 30-445.84/08/08,8408160157
- 8408170138 Forwards evaluation re resolution of SER Confirmatory
  Issue 5.TM1 action plan items & status of review of steam
  generator tube rupture event
  YOUNOBLOOD, B. J. Licensing Branch 1 84/08/09 SPENCE, M.D. Texas
  Utilities Electric Co. (formerly Texas Utilities Generating Co.)
  10pp 26134 335 24X Fiche 50-445.84/08/09.8408170138
- 8408160335 Responds to 840809 request for add1 info re environ qualification concerning FSAR data for MS-78.MS-74.ESE-27 & ESE-40 & forwards "Radiation Analysis of Barton Model 288A Differential Pressure Indicating Switch ," test rept SCHMIDT.H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/10 YOUNGELOOD.B J Licensing Branch 1 2pp 24085 341 24X Fiche 30-445.84/08/10.8408160335
- --8409160340 "Radiation Analysis of Barton Model 288A Differential Pressure Indicating Switch for Texas Utils Generating Co " RIEDL.T J Texas Utilities Electric Co (Formerly Texas Utilities Generating Co ) E0/LES(84)-144 84/08/10 7pp 26085 343 24X Fiche 50-445,84/08/10,8408160335
- 840B160412 Submits list of items for which cable splicing in raceways justified, per requirement of Rev 1 to Reg Guide 1 75 SCHMIDT.H C Tevas Utilities Electric Co (formerly Texas Utilities Generating Co) 8470B100 ,000RBL00D, 8 J Licensing Branch 1 2pp 260B3 356 24% Fiche 50-445.84/08/10.840B160412
- 8408200156 Notification of 840814 & 15 meetings w/util in New York,NY to conduct audit review of structural analysis on upper lateral restraint beam prepared for motions for summary disposition

  8URMELL,S B Licensing Branch 1 84/08/13 YOUNGBLOOD,B J Licensing Branch 1 3pp 26142 322 247 Fichs 50-445.84/08/13,8408200156

- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re-scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENBUT D G Division of Licensing 84/08/20 Consolidated Edison Co of Neu York, Inc 17pp 26276 244 24X Fiche 50-000.84/08/20.8408200275
- 8408270030 Advises of adoption of Nestinghouse generic core damage assessment methodology, in response to NUREG-0737. Item II B 3, "Post-Accident Sampling Capability "
  SCHMIDT.H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/20 YOUNORLOOD.B J Licensing Branch I 1p 26245 038 24X Fiche 30-445,84/08/20,8408270030
- 8408270565 Notification or 840823 & 24 meetings w/util in Glen Rose,TX to discuss detailed technical data supporting motions for summary dispositions
  BURWELLS B Licensing Branch i 84/08/20 YOUNGBLOOD.B J
  Litensing Branch i 5pp 26277 248 24X Fiche 50-445,84/08/20,840827055
- 8408270067 Informs that qualification maint program described in FBAR Section 2 4.App 3A will be fully implemented prior to Unit 1 fuel load SCHMIDT.H C Texas Utilities Electric Co (formerly Texas Utilities Oenerating Co ) 84/08/21 YOUNGBLOOD.B J Licensing Branch 1 p 24247 149 24% Fiche 50-445.84/08/21.8408270067
- 8408270123 Forwards response to NRC 840613 questions re reactor vessel heatup & cooldown Tech Specs
  SCHMIDT.H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) B4/08/22 YOUNGBLOOD, B J Licensing Branch 1
  11pp 26247 344 24X Fiche 50-443,84/08/22,8408270123
- 8408270132 Informs that steam generator tube rupture reevaluation will include calculations to determine margin to overfill & equilibrium breakflow showing time to overfill is greater than time to equalization.per NRC 840407 request SCHMIDT.H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/22 YOUNGBLODD,B J Licensing Branch 1 2pp 26245 059 24% Fiche SO-445.84/08/22,8408270132
- 8408280218 Forwards 830216 memo of telcon between util, NRR & BNL re action required to close out Specific Item 12.MS34 concerning disest generator control panel SCHMIDT.H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 84/08/22 YQUNGBLODD,B J Licensing Branch 1 3pp 26279 188 24% Fichs 50-445.84/08/22.8408280218
- 8408280461 Notifies that CAM-84-9 re setpoint methodology for reactor protection sys is proprietary & will be withhold from public disclosure per 10CFR2 790
  YOUNDBLOOD, B. J. Licensing Branch i 84/08/22 WIESEMANN, R. A. Westinghouse Electric Corp. 3pp. 26292 357 24X
  Fiche 30-445,84/08/22.8408280451
- 8408280142 Advises that concerns re radiation of BIW silicone insulated cable resolved Calculations examined show lower postulated dose acceptable FSAR will be updated to reflect new valves in mext amend SCHMIDT. H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 84/08/23 YDUNOBLODD, B J Licensing Branch 1 ip 26259 077 24X Fiche 50-445.84/08/23.8408280142
- 8408280190 Forwards response to NRC 840807 request for addl info re safety parameter display sys List of parameters available in each mode of operation (normal/heat up/cool down &/or cold shutdown) encl SCHMIDT.H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 84/08/24 YOUNGBLOOD, B J Licensing Branch i 24pp 26275 197 24X Fiche 50-445.84/08/24.8408280190
- 8408300239 Forwards response to 840827 request for info re status of human engineering deficiencies & clarifications to control room design review implementation audit SCHMIDT, H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 84/08/24 YOUNGBLOOD, B J Licensing Branch 1 opp 26300 123 24X Fichs 50-445,84/08/24,8408300239
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8408140066 Advises of delay in schedule for submitting 8BER, per plan for completion of outstanding regulatory actions SSER addresses resolution of outstanding const quality issues from late Aug to end of Sept 1984
  IPPOLITOR A Division of Licensing 84/07/27 BLOCH, P.B., JURDAN, W.H., MCCOLLOM, K.A. Atomic Safety and Licensing Board Panel 5pp 26061

- F Security medical, emergency ? fire protection plans
- B408230257 Forwards Cibbs \* Hill, Inc "Evaluation of Paint \* Insulation Debris Effects on Containment Emergency Sump Performance "Related correspondence"
  REYNOLDS, N.S. Bishop, Libertan, Look Pulcell & Reynolds DSB 222
  B4/07/05 BLOCH, P.B. Atomic Safety and Licensing Board Panel
  150pp 26206 166 24x Fiche 50-115,84/07/05,8408230257
- B408090451 Notification of 840803 meeting w/util in Bethesda, MD to discuss fire protection program BURNILL, S.B. Licensing Branch 1 84/08, V2 YOUNGBLOOD, B.J. Licensing Branch 1 4pp 25983 209 24X Fiche 50-445, 84/08/02, 8408090451
- B40B130267 Forwards request for additinforce Supplite NUREG-0737 concerning safety parameter display sys Project manager should be prepared to address into request within 5 days of litreceipt YOUNGBLOOD, B.J. Licensing Branch 1 B4/08/07 SPENCE, M.D. Texa Utilities Electric Co. (formerly Texas Utilities Generating Co.) 3pp. 26040-349 24% Fiche 50-445,84/08/07,840B130267
- 8408210198 Forwards status rept re control room design review.per Suppl 1 to NUREG-0737 If plan not fully resolved by fuel load licensing unli be accomplished on PPA basis YQUNOBLOOD. 8 J Licensing Branch 1 84/08/13 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 20pp 26195 287 24X Fische 59-445, 84/08/13.8408210158
- 840B210148 Forwards exercise rept for joint offsite radiological emergency preparedness 831214 gxercise Cooperation Wistate & local afficials to correct deficiencies requested BANGART.R L. Region 4. Office of Director 84/08/16 SPENCE,M D Toxas Utilities Electric Co. (formally Travas Utilities Generating Co.) Ip 26147 07/ 24X Fiche 50-445,64/08/16.8408210148
- B408270368 Forwards marked-up proposed Tech Spec changes re remote shutdown instrumentation. Fire detection instrumentation, fire suppression sys & liquid effluents CLEMENTS, B R Texas Utilities Electric Co (formerly Texas Utilities Generating (c) 84/08/20 YOUNGBLOOD, B J Licensing Branch 1 521pp 26211 025 24% Fishe 50-145, 84/08/20, 84/08270368

#### G Adjudicatory correspondence

- 840823025/ Forwards Gibbs & Hill Inc "Evaluation of Paint & Insulation Debris Effects on Containment Emergency Sump Performance "Related correspondence REYNOLDE N S Bishop Liberman. Cook, Purcell & Reynolds REYNOLDS N S Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) DSR 222 84/07/05 BLOCK P B , MCCOLLOM K A , JONDAN N H Atomic Safety and Cicensing Board Panel 150pp 26206 166 24X Fiche 50-445,84/07/05,8408230257
- 8408070200 Forwards 840801 ltr re breach of confidentiality involving CASE witness who gave deposition in proceedings under protective order Name of witness openity available to public in PDR for at least 6 days Related corrospondence ROISMAN.A Z Trial Lawyers for Public Justice ROISMAN.A Z Citizens Association for Sound Energy DSB 852 84/08/01 BLOCH.P B Atonic Safety and Licensing Board Panel in 25971 190 24% fiche 50-445,84/08/01,8408090200
- --8408070206 Requests info re breach of confidentiality involving CASE witness who gave deposition in proceedings under protective order Name of witness openly available to public in PDR for at least 6 days Related correspondence ROISMAN. A Z Trial Lawyers for Public Justice RDISMAN. A Z Citizens Association for Jound Energy 84/08/01 CHILK Office of the Becretary of the Commission 2pp 25971 191 24X Fiche 50-445.84/08/01.8108090200
- 8408;30093 Forwards sixth biweekly update on status of important schedule related issues for fuel loading Related correspondence REYNGLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds REYNGLDS, N S Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) DSB 894 B4/08/03 BLOCK.P B . MCCDLLOM, K A . JDRDAN W H ./bomic Safety and Licensing Board Panel 12pp 26007 317 24% Fiche 50-445,84/08/03,8408130093

- 8408130305 Submits info in response to discovery requests re-applicant motion for summary disposition Pertinent documentation re-ASOO steel pleading encl Wo encl Related correspondence HORIN. W.A. Bishop, Liberman. Cook, Purcell & Reynolds HORIN. W.A. Texas Utilities Electric Co. (rurmerly Texas Utilities Electric Co. (rurmerly Texas Utilities Generating Co.) DSB 895 84/08/04 ELUES. J. Citizens Association for Sound Energy 2pp 26010 257 24x Fiche 50-445.84/08/04.8408130305
- 8408090408 Forwards answers to applicant motion for summary disposition re alleged errors made in determining damping factors allegations re AUS 2 ASME Code provisions & friction force in pipe design Related correspondence ELLIS.J. Citizens Association for Sound Energy DSB 877 84/08/06 BLOCK, P. 3 MCCOLLDIL, A. JORDAN, W. H. Atomic Safety and Licensing Board Panel 19 25782 231 24% Fiche 50-445,84/08/06,8408090408
- --8408090420 Answer apposing applicant 840516 motion for summary disposition re alleged errors made in determining damping factors for OBE & SSE leading conditions Related correspondence ELLIS. J. Citizens Association for Sound Energy 84/08/06 Atomic Safety and Licensing Board Panel 2pp 25982 232 24% Fiche 50-445,84/08/06,8408090408
- --8408090426 Affidavit of M Wajsh in support of CASE answer to applicant statement of matl facts as to which no genuine issue exists re consideration of damping factors for OBE & SSE loading conditions
  WALSH.M Citizens Association for Sound Energy 84/08/04 13pp 25982 234 24X Fiche 50-445,84/08/06,8408090408
- --8408090434 Forwards M Walsh affidavit on CABE 840806 answer to applicant motion for summary disposition re alleged errors made in determining damping factors for OBE & SSE loading conditions N/o encl Cortificate of Svc encl ELLIS.J Citizens Association for Sound Energy 84/08/06 Docketing & Services Branch 3pp 23982 247 24X Fiche 50-445,84/08/06,8408090408
- --8408090463 Answer opposing applicant 840517 motion for summary disposition of certain CASE allegations on AMS & ABME Code provisions re design issues Related correspondence ELLIS.U Citizans Association for Sound Energy 84/08/04 Atomic Safety and Licensing Doard Panel 2pp 25982 250 24X Fichs 50-445,84/08/06.8408090408
- --8408090471 Affidavit of M Walsh in support of CASE answer to applicant statement of natl facts as to which no genuine issue exists on certain CASE allegations re ANS 4 ASME Code provisions related to design issues W4LEH,M Citizena Association for Sound Energy 84/08/04 35pp 25782 252 24X Fiche 50-445,84/08/06,8408090408
- ~-8408070480 Forwards M Walsh affidavit on CASE 840804 answer to applicant motion for summary disposition of certain CASE allegations on AMS & ASME Code provisions re design issues M/o encl Certificate of Svc encl ELLIS.J Citizens Association for Sound Energy 84/08/04 Docketing & Bervices Branch 3pp 25782 287 24X Fiche 50-445.84/08/04.8408070408
- --8408090188 Answer opposing applicant motion for summary disposition re consideration of friction forces in design of pipe supports w/small thermal novements Related correspondence ELLIB, J Citizens Association for Sound Energy 84/08/04 Abomic Safety and Litensing Board Panel 2pp 25982 270 24X Fiche 50-445,84/08/04,8408090408
- --8408090503 Affidavit of J Doyle & M Walsh in support of CASE answer to applicant statement of mat! facts as to which no genuine issue gxists re consideration of friction forces in design of pipe supporta w/small thermal movements
  DOVLC.J WALSH.M Citizens Association for Sound Energy
  84/08/04 39pp 25982 292 24X Fiche 50-445.84/08/06.8408090408
- --8408070512 Forwards J Doyle t M Walsh affidavit re CASE 840806 answer to applicant notion for summany disposition to consideration of friction forces in design of pipe supports w/small thermal movement W/o encl Certificate of Svc encl ELLIB. J Citizens Association for Sound Energy 84/08/06 Office of the Secretary of the Commission 3pp 25782 331 24X Fiche 50-445,84/08/06.8408070408
- 8408080162 Motion for authorization to issue license to load fue) & conduct certain precritical testing
  REYNOLUS.N S Texas Utilities Electric Co (formerly Teras Utilities Generating Co) REYNOLOS.N S Bishop, Liberman, Cook, Purcell & Reynolds DSD 825 84/08/07 Atomic Safety and Licensing Board Panel 12pp 25960 208 24% Fiche 50-445,84/08/07.8408080162

- --B408080168 Affidavit of E Alarcon in support of applicant motion for authorization to issue license to load fuel & conduct certain precritical testing Prof qualifications & Certificate of Svc encl
  ALARCON.E Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/03 18pp 25960 220 24x
  Fiche 30-448, 84/08/07-8408080162
- 8408080413 Forwards correction sheet to affidavit of UC Finneran, RC lotti & RP Daubler re design of Richmond inserts & application to support design Related correspondence HCRIN, M A Bishop, Liberman, Cook, Purcell & Reynolds HORIN, M A Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) DSB 846 84/08/07 BLOCH.PB, MCCOLLOM.K A , UDROAN, W H Atomic Safety and Licensing Board Pane) 2pp 25974 052 24X Fithe 50-445,84/08/07.8408080413
- 8408140495 Forwards copy of list re CASE requests for documents arising out of depositions taken in Glen Rose, TX Related correspondence
  ROISMAN.A Z Trial Lawyers for Public Justice DSB 026 84/08/13
  BELTER.L Bishop, Liberman, Cook, Purcell & Reynolds 3pp
  24080 246 24x Fiche 50-445.84/08/13,8408140495
- 8408160106 Forwards affidavit of M Walsh 840813 answer to applicant motion for summary disposition re effects of gaps on structural behavior under seismic loading conditions Related correspondence
  ELLIS, J Citizens Association for Sound Energy DSB 074 84/08/13 Docketing & Services Branch 1p 26085 197 24X
  Fiche 50-445.84/08/13.8408160106
- --B408160113 Answer to applicant motion for summary disposition re effects of gaps on structural behavior under seismic loading conditions Related correspondence ELLIG. J Citizens Association for Bound Energy 84/08/13 Atomic Bafety and Licensing Board Panel 2pp 26085 178 24X Fiche 50-445,84/08/13,8408160106
- --8408160131 Affidavit of H Walsh in support of answer to applicant statement of natl facts re effects of gaps on structural behavior under seismic loading conditions W/Certificate of Svc Related correspondence
  HALSH.M Citizens Association for Sound Energy 84/08/13
  Atomic Safety and Licensing Board Panel 114pp 26085 200 24
  Fiche 50-445,84/08/13.8408160106
- 8408140114 Confirms recent discussions re info requested by CASE for use in answering various applicant motions for summary disposition Telcon exchanges were in response to ASLB 840726 order Related correspondence ELLIS.J Citizens Association for Sound Energy DSB 071 84/08/13 HORIN.W A Bishop, Liberman. Cook, Purcell & Reynolds 13pp 26085 184 24X Fiche 30-445.84/08/13,8408160114
- 8408160141 Forwards answers to applicant 840518 motion for summary disposition of CASE allegations resection property values & M Walsh affidavit Related correspondence ELLIS.J Citizens Association for Sound Energy DSB 072 84/08/13 Docketing & Bervices 18 Pranch ip 26091 243, 24X Fiche 50-445,84/08/13,8408160141
- --B408160153 Ansuer to applicant B40518 motion for summary disposition of CASE allegations re-section property values ASLB should decide in CASE favor Related correspondence ELLIG. J Citizens Association for Sound Energy 84/08/13 Atomic Safety and Licensing Board Panel 2pp 26091 244 24X Fiche 30-445,84/08/13,8408160141
- --8408160158 Affidavit of H Walsh in support of CASE answer to applicant statement of natl facts as to which no genuine issue exists on CASE allegations re section property values Certificate of Svc encl Related correspondence
  WALEH, M Citizens Association for Sound Energy 84/08/12 13pp 26091 246 24% Fiche 50-445,84/08/13,8408160141
- B408160171 Forwards CASE B40B13 motion for add1 time to respond to applicant motions for summary disposition on design/design GA issues M Walsh affidavit encl Related correspondence. ELLIST Citizens Association for Sound Energy DSB 073 B4/08/13 Docketing & Services Branch ip 26072 015 24X Fiche, 30-445, B4/08/13, B40B160171
- ~~8408160178 Motion for add1 time to respond to applicant motions for summary disposition of design/dusign QA issues Related Correspondence ELLIS.J Citizens Association for Sound Energy 84/08/13 Atomic Safety and Licensing Board Panel 10pp 26092 016 24X Fiche 50-445.84/08/13.8408160171

- ~-8408160187 Affidevit of M Walsh in support of CASE motion for add1 time to respond to applicant motions for summary disposition on design/design GA issues Certificate of Svc ancl Related correspondence (WALSH.M Citizens Association for Sound Energy 84/08/12 8pp 28092 026 24X Fiche 50-443.81/08/13.8408160171
- B40B310102 Provides promised into 18 applicant motion for summary disposition on gaps Related correspondence ELLIS.J Citizens Association for Sound Energy DSB 406 B4/0B/14 MIZUND, G S. Hearing Branch 1 2pp 26322 281 24x Fiche 50-445,84/0B/14.840B310102
- ~-8408310105 Motion for admission of encl ANI documents into record of proceedings Certificate of Svc encl Related correspondence ECLIS.J. Citizens Association for Sound Energy 84/08/14 Atomic Safety and Licensing Board Panel 276pp 26322 283 24% Fiche 50-445,84/08/14 8408310102
- 8408200605 Forwards list of documents necessary for adequate answer to 840703 motion for summary disposition re allegations concerning AB program for design of piping & piping supports, per 840806 telicon Related correspondence ELLIG. J Citizens Association for Sound Energy DSB 144 84/08/15 HORINN WA Bishop, Liberman, Cook, Purcell & Reynolds 10pp 26137 161 24X Fiche 50-449.84/08/15.8408200605
- B40B220331 Responds to B40B13 ltr re CABE document requests R Tolson B00131 memo to T Vega & R Klimist B00206 ltr to R Tolson forwarded Transcript of neeting between util & JJ Lipinsky expected shortly W/o encls Related correspondence BELTER.L W Bishop, Liberman. Cook, Purcell & Reynolds BELTER.L W Texas Utilities Electric Co (formerly Texas Utilities Generating Co) D80 197 84/08/16 R01SMAN.A Z Trial Lawyers for Public Justice 2pp 26194 060 24X Fiche 50-445.84/08/16.8408220331
- 8408230187 Forwards seventh biwerkly update of important schedule-related issues for fuel load Related correspondence REYNOLDS, N B Bishop, Liberman, Cook. Purcell & Reynolds REYNOLDS N S Texas Utilities electric Co (formerly Texas Utilities Generating Co) DSB 215 84/08/16 ELOCH, P B, JORDAN, W H, MCCOLLOM, K A, Atomic Safety and Licensing Board Panel 12pp 26209 232 24X Fiche 50-445,84/08/16,8408230187
- 8408270065 Forwards Insp Repts 50-445/84-17 re disassembly.insp & reassembly of TDI emergency dissel generator, 50-445/84-05 re allegations on fabrication of page supports & restraints & 50-445/84-10 re walkdown Related correspondence
  MIZUNO, 0 5 Hearing Branch 1 998 304 84/08/16 BLOCH, P B ,
  JORDAN, W H , MCCOLLOM, K A Atomic Safety and Licensing Board Panel ip 26247 069 24% Fiche 50-445,84/08/16,8408270065
- 8408270077 Forwards 840621 Insp Repts 50-445/84-11 & 50-446/84-05, consisting of title page & summary portion of Ofc of Investigation Rept 4-84-006 Related correspondence MIZUNO.6 & Hearing Branch 1 DSB 302 84/08/16 BLOCH.P B , GROBSMAN.H , JORDAN.W H Atomic Safety and Licensing Board Panel ip 26247 358 24X Fiche 50-445.84/08/16.8408270097
- B40B220334 Forwards 771218 memo re Item 3 of list of items due omitted from 840816 package W/o encl Related correspondence BELITRIL W Bishop, Liberman, Cook, Purcell & Reynolds DSB 198 84/08/17 ROISMAN, A Z Trial Lawyers for Public Justice Ip 26194 063 24X Fiche 50-445,84/08/17,8408220336
- 8408230311 Informs of 840817 docketing & in camera filing of ML Speckter 840815 ltr to M Davidson re documents request from Witness F w/exhibit containing 15 documents CLEMENTS.W L Docketing & Services Branch DSB 251 84/08/17 Docketing & Services Branch 1p 24209 335 24X Fiche 50-445,84/08/17.8408230311
- 8408280232 Forwards Insp Repts 50-445/84-12 & 50-446/84-06 on 840320-0518 re status of 10CFR50 55(e) repts & 50-445/84-08 & 50-446/84-04 on 831114-840331 re polar crane shim gaps Related correspondence MIZUND.9 S Hearing Branch 1 DSB 318 84/08/17 pLOCH.PB, MCCOLLON.K A, JORDAN, H Atomic Safety and Licensing Board Panel 62pp 26262 287 24X Fiche 50-445,84/08/17,8408280232
- 8408240244 Partial answer in opposition to applicant 840807 motion for authorization to issue license to load fuel & conduct certain precritical testing Inspirepts & Certificate of Svcenc!
  ELLIS, J. Citizens Association for Sound Energy DS9 267 84/08/18
  Atomic Safety and Licensing Board Panel 54pp 26222 277 24X
  Fiche 50-445,84/08/18,8408240244

- 8408230317 Submirs matter clinibing of U-builts axial restraints, Richmond inserts A stability per 840805 telcon between util, CASE & NRC staff
  - CASE & ARC Staff HORIN.W A Bishop Liberman Cook Furcell & Reynolds HORIN.W A Terms Utilities Electric Co. (formerly Texas Utilities Generating Co.) DSR 213 84/08/20 FLLIS.J Citizens Association for Sound Energy 2pp 26205 357 344 Fiche 50-445.84/08/20.8408230319
- 84082701/9 Forwards testimony or D Hummicutt re T-shirt incident Hummicutt testimony provided by agreement of counselite suppl deposition of Curmins Related correspondence TREBY.S A Hearing Branch 1 DSD 301 B4/08/20 BLOCH, P B , JURUAN, W H , GRUSSMAN, H Atomic Safety and Licensing Board Panel 23pp 26243 317 244 Fichs 50-445 84/08/20.8408270179
- ---8408270186 Notion to strike testimony of D Hunnicutt & JE Cummins as being beyond scope of harassment & intimidation issue & therefore not relevant to proceeding Ceitificate of Svc encl Related correspondence
  BACHMANN.R O Healing Branch 1 84/08/20 Atomic Safety and Licensing Board Panel 5pp 26243 340 24% Fiche 50-445, 84/08/20,8408270179
- 8408280136 Forwards M Walsh 840919 statement & CASE 840820 answer to applicant motion for summary disposition of CASE allegations is U-bults acting as tuo-way restraints Related correspondence ELLIS.J Citizens Association for Sound Energy DSB 275 84/08/20 Docketing \* Services Branch 1p 26275 146 24X Fiche 50-447,84/08/20.8408280136
- --B408280141 Answer to applicant 840523 motion for summary disposition of CASE allegations re U-bolts acting as two-way restraints Applicant statements should be considered as matl false statements

  ELLIS, J. Citirens Association for Sound Energy B4/08/20

  Atomic Safety and Licensing Board Panel 2pp 26275 147 24X

  Fiche 50-449,64/08/20,8408280136
- --8409280146 Answer to applicant statement of matl facts as to which there is no genuine issue re CASE allegations regarding U-bolts acting as two-way restraints Statement in Form of affidavit of M Walsh Certificate of Sve enc!
  WALSH.M. Cirizens Association for Sound Energy 84/08/19
  Atomic Safety and Licensing Board Panel 35pp 26275 149 24x
  Fiche 50-445,84/08/20,8408280136
- B408230173 Requests Hartran be informed of error in interpretation re filing of documents in proceeding Documents should be filed per procedures established by ASLB Related correspondence ROISMAN, A Z Trial Lawyers for Public Justice ROISMAN, A Z Citizens Association for Sound Energy DSB 223 84/08/21 CLEMENTS.W L Bocketing & Services Branch 2pp 26209 271 24X Fiche 50-445,84/08/21,8408230173
- 840827005B Documents receipt % docketing on 840820 of in camera deposition taken on 840815 CLEMENTB, W L. Docketing % Services Branch DSB 272 84/08/21 Docketing % Services Branch 1p 25238 141 24% Fiche 50-445.84/08/21,8408270058
- 8408230305 Informs of 840822 in camera filing of ML Speckter 840820 response to M Davidson 840820 ltr CLEMENTS, W L Docketing \*\* Services Branch DSD 252 84/08/22 Docketing \*\* Services Branch 1p 26207 334 24% Fiche 30-445
- 8408270094 Response supporting util 840807 motion for authorization to issue license to conduct fuel load & precritical testing MIZUND.6 S Hearing Branch I DSB 306 84/08/22 Atomic Bafety and Licensing Board Panel 9pp 26247 305 P4X Fiche 50-445.84/08/29.8408270094
- --B408270103 Response supporting util 840802 motion for directed certification of ASLB 840783 order ruling on util motions for summary disposition of Phases I \* II Certificate of 8vc encl PERLIS.R G Hearing Branch 3 84/08/17 Commissioners 10pp 2427 314 24X Fishe 50-445,84/08/22.8408270094
- 8408280083 Forwards matl requested in 840806 conference call reapplicant motions for summary disposition Matl identified as Item 3 in 840820 for re drawing % calculations for Support FW-1-18-703-652R W/o encis
  HORIN.W A Bishop. Liberman. Cook. Purcell & Reynolds HORIN.W A Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 285 84/08/22 ELLIS.J Citizens Association for Sound Energy 2pp 26/261 197 24X Fiche 50-445,84/08/22.8408280083

- 8408270154 Forwards response to Item 6 of things due re transcript of plant personnel meeting U/JJ Lipinsky Travelers requested during 5 Neumeyer deposition expected shortly W/o encl Related correspondence BELTER! W Bishop, Liberman, Cook, Purcell & Reynolds BELTER.L W Texas Utilities Electric Co. (Formerly Texas Utilities Generating Co.) DSB 282 B4/08/23 ROISMAN.A Z Trial Lawyers for Public Justice ip 26245-145 24x Fiche 50-445,84/08/23,8408270134
- 8408280221 Exhibit to G Purdy deposition re GC personnel interview PURDY, G Texas Utilities Electric Co (folmerly Texas Utilities Generating Co) DBB 299 B4/08/23 12pp 26267 342 R4X Fiche 50-445.84/08/23.8408280221
- 840828015/ Motion to strike listed portions of applicant testimony as impermissible redirect of witnesses Cortificate of Svc encl Related correspondence ROISMAN.A Z Trial Lawyers for Public Justice DSB 336 84/08/24 Atomic Safety and Licensing Board Famel 6pp 26275 075 24X Fiche 50-445.84/08/24.8408280157
- 8408280255 Memorandum Sirecting util to supply requested evidence to facilitate further consideration of 840807 motion for authorization to issue license to load fuel & conduct certain precritical testing Served on 840827

  BLOCH-P B Atomic Safety and Licensing Board Panel DSB 327

  84708724 Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 3pp 26261 342 24X Fiche 50-445,84708724,84087
- 8408280265 Response to ABLR 840615 request for add1 info re TDI diesel generators ABLB should conclude that TDI QA program adequate at all times Related correspondence REYNOLDS,N S Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) REYNOLDS,N S Bishop, Liberman, Cook, Furcell & Reynolds DSB 334 84/08/25 29pp 26262 008 24% Fiche 50-445,84/08/25,8408280265
- --8408280268 Affidavit of EJ Kreh re evaluation of TD1 GA program TD1 GA program acceptable prior to Jul 1980 discovery of auxiliary skid deficiency Prof qualifications & Cortificate of Svc encl Related correspondence RREH, EJ 0/Johnell & Associates, Inc 84/08/24 10pp 26262 037 24X Fiche 50-445.84/08/25.8408280265
- 8408280156 Metion to strike testimony of IL Goldstein Testimony unreliable, incompetent & w/o foundation to resolve issues Certificate of Evr encl Related correspondence DDWNEY, B L Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) DDWNEY, B L Bishop, Liberman, Cook, Purcell & Reynolds D88 331 84/08/27 Abomic Safety and Licensing Board Panel 7pp 26275 056 24% Fiche 50~445,84/08/27,8408280156
- 8408280165 Motion to open record to receive into evidence, matis re reasons for & circumstances surrounding termination of R Hamilton employment Certificate of Svc encl WATKINS.M Texas Utilities Electric Co (formorly Texas Utilities Generating Co ) WATKINS,M Bishop, Liberman, Cook, Purcell & Reynolds DSS 332 84/08/27 Atomic Safety and Licensing Board Panel 10pp 26262 351 24% Fiche 50-445,84/08/27,8408280165
- 8408280251 Response opposing staff 840820 motion to strike testimony D Hunnicutt & JE Cummins Testimony relevant to questions re T-shirt incident & intervenor contentions concerning incident Certificate of Svc enci Related correspondence DCMNEY, B L Texas Utilities Electric Co (formerly Texas Utilities Concerning Co) DDMNEY, B L Bishop, Liberman, Cook, Purcell & Reynolds DSB 333 84/08/27 Atomic Safety and Licensing Bc Panel 8pp 26261 348 24% Fiche 50-445.84/08/27,0408280251

- 8408310216 Forwards transcript or 831110-11 meetings at facility reprotective coatings? Lipinsky memorandum W/o cncl Related correspondence
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8408140393 Amend 51 to FSAR for Committe Peak W/840810 ltr SPENCE M D Te, as V+11+1es Electric Co (formerly Texas Utilities Generating Co ) 64/08/08 DENTON.H R Office of Nuclear Reactor Regulation, Director 40pp 24048 019 24X Fiche 50-445,84/08/08, 8408140393
- B408290208 Forwards Amend 52 to FSAR Affidavit encl CLEMENTS. 8 R Texas Utilities Electric Co (formerly Texas Utilities Generating Co \ 84/08/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 26287 254 24X Fiche 50-445, 84/08/27, 8408290208
- --8408270211 Amend 52 to FSAR

   Toras Utilities Electric Co (formerly Texas Utilities Generating Co ) 84/08/27 &88pp 26287 260 24x
  Fiche 50-445,84/08/27.8408270208
- Q Inspection reports: IE Bulletins & correspondence
- 8408010098 Discusses 830827-0902 insp of BIW Cable Sys.Inc (BIW) equipment qualification testing program Environ qualification of silicone insulated cable inadequate Requests verification of BIW qualification metl YOUNGBLOOD B J Licensing Branch I 84/07/17 SPENCE.M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) App 25897 040 24% Fiche 50-445.84/07/19.8408010098
- 8408150649 Forwards IE Trisp Repts 50-445/84-12 & 50-446/84-06 on 840320-0518 No violations or deviations noted BANDART.R L Region 4. Office of Director 84/07/23 SPENCE,M D Texas Utilities Flectric Co (formerly Texas Utilities Generating Co) 2pp 26079 188 24% Fiche 50-445,84/07/23,8408150649
- --8408150655 IE Insp Repts 50-445/84-12 t 50-446/84-06 on B40320-0518 No violations noted Major areas inspected plant status, licensee action on previous findings, IOCFR50 55(e) rept followup, IE bulletin followup t plant tours
  CUMMINS, J E . MCNEILL, W M . TOMLINSON, D P Region 4, Office of Director 84/06/21 18pp 26079 190 24X Fiche 50-445,84/07/23,8408150649
- 8408160201 Ack receipt of 840527 response to 840430 ltr re insp techniques for assessing extent of Unauthorized weld repairs Response inadequate Requests detailed sampling plan & procedure within 20 days BANGARTIR L Region 4. Office of Director 84/07/23 SPENCE, M D Texas Utilities Electric CO (formerly Texas Utilities Generating Co) 2pp 26106 300 24% Fiche 30-445.84/07/23.8408160201
- B408150091 Forwards IE Insp Repts 50-445/84-08 & 50-446/84-04 on B3ii14-840331 & notices of violation & deviation Major areas inspected Part 21 followup 3 training of protective coatings inspectors
  BANDART.R L. Region 4. Office of Director B4/07/26 SPENCE.M D Texas Utilities Generating Co 1 Spp 26073 306 24% Fithe 50-445.84/07/26.8408150091
- --B408150102 IE insp Repts 50-445/84-08 & 50-446/84-04 on B31114-B40331 Violations & deviations noted unshimmed gaps exceed 1/16 inch on polar crane bracket & seismic connections & licensee did not incorporate objectives of ANSI N45 2 11 into design CUMMINB.J E , SMITH.W F , MARTIN.L E Region 4. Office of Director B4/07/26 10pp 26073 313 24X Fiche 50-443,84/07/26,840815009;
- B407250229 IE Info Notice B4-57. "Operating Experience re Moistura Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 04/ 24% Fiche 50-000,84/07/27,8407250227
- 840B100042 Advises that IE Insp Repts 50-445/83-42 & 50-446/83-20 canceled No insp rept will be issued for listed numbers BANGART, R. Region 4. Office of Director 84/08/01 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 25990 048 24% Fiche 50-445.84/08/01.8408100042

- 8408100097 Forwards GA Program Insp Repts 97700387/84-01 & 97900404/84-02 Requests evaluation of significance of reported findings requality & acceptability of product or svc provided by vendor N/o encl HUNTCR, D.R. Region 4. Office of Director 84/08/03 SPENCE, M.D. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.) 2pp 25991 014 24X Fiche 50-445.84/08/03.8408100097
- 8408010333 IE (nto Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list end JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 833103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26069 001 24X Fiche 50-000,84/08/06,8408010333
- 8408010337 IE info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post E30103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 26047 158 24X Fiche 50-000.84/08/06.8408010337
- B40B090454 Board Notification B4-132 transmits NRC Special Review Team rept re 840403-13 site review of mpt control of constinsp & test programs
  EISENHUT, D G Division of Licensing B4/08/06 PALLADING Consolidated Edison Co of New York, Inc 72pp 26031 214 24X Fiche 50-445.84/08/06.8408070435
- 840Bi60313 Board Notification 84-136 forwards util 840622 responses to protective coating BNL 840613 ltr forwarding draft "Status Rept on Protective Coatings Allegations" & 840624 ltr forwarding IE Insp Repts 50-445/84-03 & 50-446/84-01 EISENHUT, D 9 Division of Licensing 84/08/07 BLOCH, P, JORDAN W, MCCOLLOM K Atomic Sefety and Licensing Board Panel 2pp 26190 001 24X Fiche 50-445/84/08/07/8408160313
- --B40B220412 Forwards responses to 840518 & 23 ltrs re 60 allegations concerning protective coating practices at facility Responses based on technical knowledge & review of existing documentation Supporting documentation encl
  FIXAR.L F Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/06/22 BANDART.R L Region 4, Office of Director 320pp 24190 003 24X Fiche 50~445.84/08/07, B408140313
- --8408220415 Forwards draft "Status Rept on Protective Coatings Allegations" TAYLOR,J H Brockhaven National Laboratory 84/06/13 BANGART,R L Region 4, Office of Director 50pp 26190 323 24x Fiche 50-445.84/08/07,8408160313.
- --B408220419 Forwards IE Insp Repts 90-445/84-03 & 50-446/84-01 on B40130-0203 LETTIERI.V Brookhaven National Laboratory 84/02/24 HUNNICUTT. D M Region 4. Office of Director 1p 26191 010 24X Fiche 50-445,84/08/07.8408160313
- --8408220424 IE Insp Repts 50-445/84-03 & 50-446/84-01 on 840130-0203 No violations or deviation identified Major areas inspected protective coatings programs HIGGINS, J C , LEITIERI, V Region A, Office of Director 84/02/23 12pp 2619 011 24% Fiche 50-445,84/08/07,8408160313
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fiche 50~000,84/08/08,8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " 8vc list onc! GRACE, J N Division of GA, Bafeguards & Inspection Programs (Post B30103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376
- 8408160330 Forwards summaries of two addl BIW cable environ qualification repts, per 840719 request to address concerns resulting from NRC insp Cable adequately qualified BCHMIDT, HC Teras Utilities Electric Co (formerly Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.) 84/08/10 YOUNGBLODD, BJ Licensing Branch 1. 16pp 26085 322 24% Fiche 50-445,84/08/10,8408160330
- B40B100009 IE Info Notice B4-63, "Defective RHR Replacement Piping "
  Bvc list encl
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc. 119pp 26197 218 24X Fiche 50-000,84/08/13,840B100009
- B40B10003B IE Info Notice 84-64, "BWR HPCI Initiation Beal-In & Indication "Syc list encl JURDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New Yorf: Inc 104pp 26198 093 24X Fiche 50-000,84/08/15.840B160038

- 8408100021 IE Info Notice 84-65, 'Undernated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Syc
  - Affact Operation or Essential III
    List encl
    Division of Emergency Preparedness \* Engineering
    JORDAN,E L Division of Emergency Preparedness \* Engineering
    Response (Post 830103) 84/08.16 Consolidated Edison Co of New
    York Inc. 1180p 26198 001 24X Fiche 50-000,84/08/16,8408100021
- 8408270065 Forwards Insp Repts 50-445/84-17 re disassembly, insp & reassembly of TDI emergency diesel generator, 50-445/84-05 re allegations on fabrication or pipe supports & restraints & 50-445/84-10 re walkdown Related correspondence MIZUND, G S Hearing Branch ! DSS 304 84/08/16 BLOCH, P B Atomic Safety and Licensing Board Panel 1p 26247 069 24X Fiche 50-445,84/08/16,8408270065
- 8408270077 Forwards 840621 Insp Repts 50-445/84-11 & 50-446/84-05, consisting of title page A summary portion of Ofc of Investigation Rept 4-84-006 Related correspondence MIZUNO, G B Hearing Branch 1 DSB 302 84/08/16 BLOCH, P B Atomic Safety and Licensing Board Panel 1p 26247 358 24% Fiche 50-445.84/08/14.8408270097
- 8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 001 24% Fiche 50-000.84/08/17.8408100055
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24% Fiche 50-000,84/08/17,8408140208
- 8408280232 Forwards Insp Repts 50-445/84-12 & 30-446/84-06 on 840320-0518 re status of 10CFR50 55(e) repts & 50-445/84-08 & 50-446/84-04 on 831114-840331 re polar crane shim gaps Related correspondence MIZUNO.0 S Hearing Branch 1 DSB 318 84/08/17 BLOCK. Atomic Safety and Licensing Board Panel 62pp 26262 287 Fichs 50-445,84/08/17,8408280232
- 8408240244 Partial answer in opposition to applicant 840807 motion for authorization to issue license to load fuel & conduct certain precritical testing Insp repts & Certificate of Svc
  - enci ELLIS, J Citizens Association for Sound Energy DSB 267 8-Atomic Safety and Licensing Board Panel 54pp 26222 277 Fiche 50-445,84/08/18,8408240244 84/08/18
- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves "Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000.84/08/21,8408210142
- A Periodic operating reports & related correspondence
- 8408060184 Submits sixth biweekly update on status, through 840721, of important schedule-related issues for fuel load in late Bept 1984 Control room HVAC testing incomplete Schedule slippage of 3 uks cannot be recovered GEORGE, J B Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/07/30 EISENHUT, D O Division of Licensing COLLINS. J T Region 4, Office of Director 11pp 25723 324 24X Fiche 50-445,84/07/30,8408060184
- 8408170063 Provides seventh biweekly status rept re schedular issues for fuel load info current through 840804 Project approx 3 for fuel load info current through 840804 Project approx 3 wks behind schedule
  GEORGE. J B Texas Utilities Electric Co (formerly Texas Utilities
  Generating Co) 84/08/13 GISENNUT. D O Division of Licensing
  COLLING. J T Region 4. Office of Director lipp 26:19:112 24X
  Fiche 50-445,84/08/13,8408170065
- B Reportable occurrences, LERs & related correspondence
- 8405270062 Forwards "Investigation of Types AF & AE Piston Skirts " Rept supercedes 840277 submittal RAY, C.L. TDI (Transamerica Delaval, Inc.) Owners Group 84 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 24670-045 24% Fiche 30-000, 84/05/24, 8405290062 84/05/24
- --8405290075 "Investigation of Types AF & AE Piston Skirts \* Failure Analysis Associates FAAA-84-2-14 84/05/2 24X Fiche 50-000.84/05/24,8405290062 84/05/23 120pp

- B409270177 forward\* Evaluation of Emergency Diesel Generator Crankshuffs ut Shorchar \* . i and Golf Muclear Power
  - CrankEnders 31 300 cms. This most focus to the Station Park C L TDI (Transamers a Delaval, Inc.) Duncts Group 84 DENTON, H Défice of Nucles Reactor Regulation, Director 24597 090 24; Fiche 50-000 04/05/24, 8005/2901/9 84/05/24
- 8408060405 Furwards repts icces ed by BNUL \* consultants directly from FaAA \* TDI Owners Group at D40622 meeting Diaft "Overview of Repts Analysis 5 Recommendations re Nain Propulsion Engines MV Colombia" entl
  ALZHEIMER.J II Battelle Honorial Institute, Pacific Northwest
  Laboratories 84.06/28 MILLER.N Division of Licensing 158pp 25926 173 244 Fiche 50-000.84/06/28 8408060405
- B408050050 Forwards into addressing open items identified in NRC/BNNL/TDI Diesel Generator Ouneis Group 840622 meeting RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group 84/07/10 BERLINGER.C Director's Offic. Office of Inspection and Enforcement 43pp 2593u 133 24% Fiche 50-000.84/07/10. 8408060050
- 8408930115 Responds to 840529 ltr re-problems identified at Bahnson (or-Winston-Salem facility No HVAC equipment leceived from subj-facility Bahnson Co-solicited to assess or to take any needed actions to improve GA program CLEMENIS.3 R Texas Utilities Electric Co-(furmerly Texas Utilities Generating Co-) 84/07/23 BEYOUNG.R C Director's Office of Inspection and Enforcement 2pp 23916 104 24X Fiche 50-445.84/07/23.8408030115
- 8408050102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring ' Termination Qualification Review " Addl copies sont to BNNL RAY.C L TDI (Transamerica Delaval, Inc.) Quiners Group 84/0 84/07/27 DEFITION.H R Office of Nuclear Reactor Regulation, Director 25932 137 24% Fiche 50-000 84/07/27,8408060102
- --8409060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " # Stone ! Webster Engineering Corp 84/07/31 36pp 29932 139 24X Fiche 50-600.84/07/27,8408060102
- 8408090044 Interin Significant Deficiency Rept SDAR-129 re arror in tolerances used in calibr or adhesion tester Evaluation continuing Completion anticipated by 840901 CLEMENTS B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 84/07/31 JOHNSON.E H Region 4 Office of Director 1p 25992 132 F4x Fiche 50-445,84/07/31,8408090044
- 8408040324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DGRV-12-4 & DGRV-20-4 Emergency Diesel Generator Sets " TDI (Transamerica Delaval, Inc.) Gunera Group
  - B4/08/01 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 25927 064 24% Fiche 50-000,84/08/01,8408060324
- 8408160510 Final Deficiency Rept SDAR-129 re error in tolerances used in calibr of adhesion tester Initially reported on 840116 Investigation complete Matter not reportable under 10CFR50-55(e) CLEMENTS, B R Texas Utilities Electric Co (formorly Texas Utilities Generating Co ) 84/08/04 JOHNSON-E H Region 4, Office of Director 1p 26107-350 24X Fiche 50-445, 84/08/06, 8408160510
- 8408160185 Interim Deficiency Rept SDAR-140 re qualification of main steam relief valves for actual loading conditions Initially reported on 840710 Evaluation in progress? should be completed by 840831 CLEMENIS.B R Terms Utilities Electric Co (formerly Texas Utilities Generating Co.) 84/08/08 JOHNBON.E H Region 4, Office of Director 1p 26106 328 24x Fiche 50-445.84/08/08,8408160185
- 8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DERV-16 Diesel Engines" RAY, C. L. TDI (Transamerica Delavel, Inc.) Owners Group 84/08/10 DENTON, H R R Office of Nuclear Reactor Regulation, Director 24x Fiche 50-000,84/08/10,8408160394
- --8408160403 "Design Review of Engine Base & Bearing Caps for TDI BBRV-16 Diesel Engines "

  \* Failure Analysis Associates FAAA-84-6-53 84/08/31 44p 26091 149 24X Fiche 50-000.84/08/10.8408160394 84/08/31 44pp
- 8408200295 Interim Significant Deficiency Rept SDAR-132 re installation of curtain fire dampers u/o proper provisions for thermal expansion initially reported on 840330 Review revealed 50 dampers required remote or mod Next rept by B40817

  FIXAR.L F Texas Utilities Electric Co (formerly Texas Utilities electric Co)

  Generating Co) B4/0B/13 JOHNSON, E H Region 4, Office of Director Spp 26140 101 24X Fiche 50-445, 84/08/13, 8408200275

- B40B310216 Forwards transcript of Billio-li meetings at facility re protective coatings? Lipinsky memorandum W/o encl Related correspondence HORRIN, W A Bishop Liberman, Coor, Purcell & Reynolds HORIN, W A Toxas Utilities Electric Co. (formerly Texas Utilities Generating Co.) DSB 420 B470B279 BLOCH-P B Atomic Safety and Licensing Board Panel 1p 26318 116 24x Fiche 50-445.84708/27.8408310216
- K Utility Final Safety Analysis Report (FSAR) & Amends
- 8408140393 Amend 51 to FSAR for Comanche Peak W/840810 ltr SPENCE.M D Teras Utilities Electric Co (formerly Teras Utilities Generating Co ) 84/08/08 DENTON.H R Office of Nuclear Reactor Regulation, Director 60pp 26048 019 24X Fiche 50-445,84/08/08. 8408140393
- B40B29020B Forwards Amend 52 to FSAR Affidavit encl CLEMENTS.B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/27 DENTON.H R Office of Nuclear Reactor Regulation, Director 4pp 262B7 254 24X Fithe 50-445,84/08/27, 8408270208
- --84082902)1 Amend 52 to FSAR \* Texas Utilities Electric Co (formerly Texas Utilities Omerating Co ) 84/08/27 681pp 26287 260 24X Fiche 50-445,84/08/27.8408290208
- O Inspection reports. IE Bulletins & correspondence
- 8408010098 Discusses 830929-0902 insp of BIW Cable Sys, Inc (BIW) togolouve Discusses sacues/-uvgz insp or blw cable Syd, inc (Blw) equipment qualification testing program Environ qualification of silzcone insulated cable inadequate Requests verification of Blw qualification mail YOUNGBLOOD, B J Licensing Branch 1 84/07/17 SPENCE, M D Ter Utilities Electric Co (formerly Teres Utilities Generating Co) 4pp 23897 060 24% Fiche 50-445,84/07/19,8408010098
- B40B150649 Forwards IE Insc Repts 50-445/84-12 & 50-446/84-06 on Add320-0518 No violations or deviations noted
  BANGART, R.L. Region 4, Office of Director B4/07/23 SPENCE, M.D.
  Texas Utilities Electric Co (Formerly Texas Utilities Generating
  Co) 2pp 26079 188 24X Fiche 50~443, B4/07/23, B408130649
- --8408150655 IE Insp Repts 50-445/84-12 & 50-446/84-06 on 840320-0518 No violations noted Major areas inspected plant status, licensee action on previous findings, 10CFR50 55(e) rept followup, IE bulletin following & plant tours CUMMINS.J E. MCNEILL.W M. TOMLINSON.D P Region 4. Office of Director 84/06/21 18pp 26079 190 24X Fiche 50-445.84/07/23. 8408150649
- 408160201 Ack receipt of 840527 response to 840430 ltr re insp techniques for assessing extent of unauthorized weld repairs Response inadequate Requests detailed sampling plan & procedure within 20 days BANDARTIR L. Region 4. Defice of Director 84/07/23 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 26106 300 24X Fiche 50~445,84/07/23.8408160201
- 8408150091 Forwards IE Insp Repts 50-445/84-08 % 50-444/84-04 on 831114-840331 % notices of violation & deviation Major areas inspected Part 21 followup ? training of protective Inspected Part 2: Tollady - Canning - Part 2: Tollady - Castings inspectors
  BANOART.R L. Region 4, Office of Director B4/07/26 SPENCE.M [
  Texas Utilities Electric Co (formerly Texas Utilities Generating
  Co ) 3pp 26073 306 24X Fiche 50-445.84/07/26.8408150091
- HUBIDUIUZ IE Insp Repts 50-445/84-08 & 50-446/84-04 on B31114-840331 Violations & deviations noted unshimmed gaps exceed I/16 inch on polar crane bracket & seismic connections & licensee did not incorporate objectives of ANSI N45 2 11 into design CUMNINS, J E., SMITH, W F., MARTIN, L E. Region 4, Office of Director B4/07/26 10pp 26073 313 24X Fichs 50-445,84/07/26,8408150091 --8408150102 IE 1map Repts 50-445/84-08 & 50-446/84-04 on 831114-840331
- 8407250227 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safaty-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 630103) 84/07/27 Consolidated Edison Co of New York, Inc. 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229
- 8408100042 Advises that IE Insp Repts 50-445/83-42 & 50-446/83-20 canceled No insp rept will be issued for listed numbers BANDART.R L Region 4. Office of Director 84/08/01 BPENCE, M D Texas Utilities Electric Co (formerly Toxas Utilities Generating Co ) 2pp 25990 068 24% Fiche 50-445,84/08/01,8408100042

- B40B100097 Forwards GA Program Insp Repts 999003B7/84-01 & 99900404/84-02 Requests evaluation of significance of reported findings re quality & acceptability of product or see provided by vendor N/o encl HUNTER, D.R. Region 4. Office of Director 84/08/03 SPENCE, M.D. Texas Utilities Electric Co. (formerly Toxas Utilities Generating Co.) 2pp 23991 014 24% Fiche 50-44%, 84/08/03, 840B100097
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830)03) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26069 001 24% Fiche 50-000,84/08/06,8408010333
- B408010337 IE Info Notice B4-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JURDAN, E.L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 26067 158 24X Fiche 50-000.84/08/06.8408010337
- 8408080494 Board Notification 64-132 transmits NRC Special Review Team rept re 840403-13 site review of mgt control of const,insp & test programs & test programs EIBENHUT.D G Bivision of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 72pp Fiche 30-445,84/08/06,8408070455 PALLADINO
- 8408160313 Board Notification 84-136 forwards util 840622 responses to protective coating, BNL 810613 ltr forwarding draft "Status Rept on Protective Coatings Allegations" & 840624 ltr forwarding IE Insp Repts 50-445/84-03 & 50-446/84-01 EISENHUT. D G Division of Licensing 84/08/07 BLOCH.P, JORDAN.W. MCCQLLOM.K. Atomic Safety and Licensing Board Panel 2pp 26190 001 24X Fiche 50-445.84/08/07,8408160313
- ---8408220412 Forwards responses to 840518 & 23 ltrs re 60 allegations concerning protective coating practices at facility Responses based on technical knowledge & review of existing documentation Supporting documentation encl FIKAR.L F Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 84/06/22 BANDART.R L Region 4. Dffice of Director 320pp 26190 003 24X Fiche 50-445,84/08/07, 8408160313
- --8408220415 Forwards draft "Status Rept on Protective Coatings Allegations "
  TAYLOR: J H Brookhaven National Laboratory 64/06
  BANGART, R Region 4. Office of Director 50pp
  Fichs 50-445, 84/08/07, 8408160313 84/06/13 26170 323. 24X
- --8408220419 Forwards IE Insp Repts 50-445/84-03 & 50-446/84-01 on 840130-0203 LETTIERI.V Brookhaven National Laboratory 84/02/24 HUNDIOUTT.D M Region 4, Office of Director 1p 26191 010 Fiche 50-445,84/08/07,8408160313 26191 010 24X
- --8408220424 IE Insp Repts 50-445/84-03 & 50-446/84-01 on 840130-0203 No violations or deviation identified Major areas inspected protective coatings programs HIGGING.J C . LETTIERI,V Region 4, Office of Director 84/02/23 12pp 26191 011 24X Fiche 50-445,84/08/07,8408160313
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svr list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York, Inc 120pp 26127 118 24X Fishe 50-000,84/08/08,8408070120
- 8408070376 IC Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Syc list encl GRACE.J N Division of GA, Safeguards & Inspection Programs (Post 830103) B4/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24x Fiche 50-000:84/08/10.8408070376
- B408160330 Forwards summaries of two add1 BiW cable environ qualification repts,per 840719 request to address concerns resulting from NRC insp Cable adequately qualified SCHMIDT. H C Texas Utilities Electric Co (formerly Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 84/08/10 YOUNGBLOOD, B J Licensing Branch 1 14pp 24085 322 24X Fiche 50-445,84/08/10,8408160330
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping." AOBIOU009 IE INTO NOTICE CO. STATE OF THE PROPERTY PROPERTY PROPERTY & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co. of New York, Inc. 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009
- B408100038 IE Info Notice 84-64, "BWR HPCI Initiation Beal-In & Indication "Syc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc. 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

- E Info Notice 83-65. "Underrated fuses Which May Adversely reation of Essential Electrical Equipment " Syc
- Division of Emergency Preparedness & Engineering
  Post 830103) 84/08/16 Consolidated Edison Co of New
  t 1 &pp 26178 001 24X Fiche 50-000.84/08/16.8408100021

ortwards Insp Repts 50-445/84-17 re disassembly, insp & of TDI energency diesel generator, 50-445/84-05 re S on fabrication of pipe supports 5 restraints & 10 re walkdown Related correspondence Hearing Branch 1 DSB 304 84/08/16 BLOCK, P B ety and Licensing Board Panel 1p 26247 069 24X 45. 84/08/16,8408270045

Orwards 840421 Insp Repts 50-445/84-11 & 50-446/84-05, of title page % summary portion of Dfc of ion Rept 4-84-006 Related correspondence Hearing Branch 1 D58 JO2 84/08/16 BLOCH, P B ety and Licensing Board Panel 1p 26247 358 24X 43.84 4/08/16.8408270097

E Info Notice 84-66, "Undetected Unavailability of 1 ven Auxiliary Feedwater Train " Svc list encl Division of Emergency Preparedness & Engineering Post 830103) 84/08/17 Consolidated Edison Co of New 12Opp 26276 001 24X Fiche 50-000.84/08/17, 8408100055

E Info Notice 84-67, "Recent Snubber Inservice Testing W/re Rates " Svc list enc!
Division of Emergency Preparedness & Engineering
Post 630103 84/08/17 Consolidated Edison Co of New
122pp 26276 122 24X Fiche 50-000.84/08/17.8408140208

Drwards Insp Repts 50-445/84-12 8 50-446/84-06 on B re status of 100FR50 55(e) repts & 50-445/84-08 4-04 on B31114-840331 re polar crane shim gaps rrespondence

Trespandence
Hearing Branch ( DSB 318 84/08/17 BLOCH, P B
sty and Licensing Board Panel 62pp 26262 287 2
\$5.84/08/17.8408280232

artimal answer in opposition to applicant 840807 motion for iona to issue license to load fuel & conduct
acritical testing Insp repts & Certificate of 8vc

litizens Association for Sound Energy D88 267 84/08/18 Safety and Licensing Board Panel 54pp 26222 277 24X 15.84/08/18/8408240244

Info Notice 84-48. "Potential Deficiency in Improperly Uliring to Solenoid Valves" Svc list encl Division of Emergency Preparedness & Engineering Post 830103 84/08/21 Consolidated Edison Co. of New 115pp 26327 008 24X Fichs 50-000.84/08/21.8408210142

perating reports & related correspondence

bmits sixth biweekly update on status, through 840721, of checkule-related issues for fuel load in late on trol room HVAC testing incomplete Schedule 3 wks cannot be recovered

Texas Utilities Electric Co (formerly Texas Utilities Co ) 84/07/30 EISENHUTID 9 Division of Licensing Region 4, Office of Director 11pp 25923 324 24X 5, 84/207/30,8408060184

ovides seventh biweekly status rept re schedular issues ad. Info current through 840804 Project approx 3 schedule Texas Utilities Electric Co (formerly Texas Utilities Co.) 84708/13 EISENHUY.Do Division of Licensing Region 4, Office of Director lipp 26119 112 24X 5.614/08/13.8408170045

occurrences, LERs & related correspondence

rwards "Investigation of Types AF & AE Piston Skirts "
edes 840227 submittal
DI {Transamerica Delaval, Inc } Cumers Group 84/05/2pffice of Nuclear Reactor Regulation, Director 2pp
24× Fiche 50-000,84/05/24,8405270062 84/05/24

"Investigation of Types AF & AE Piston Skirts a Analysis Associates FAAA-84-2-14 84/05/2 50-000.84/05/24.8405270062 84/05/23 120pp 8405290177 Firmards - Evaluation of Emergency Diesel Generator Cranksharful at Shureha - 1 Crand Gulf Muclean Power

Chamster variations Stations S 84/05/24

8405060404 Forwards repts recei ed by BN/L \* consultants directly from FaAA & TDI Owners Group at 840522 meeting Draft "Overview of Repts.Analysis & Recommendations re Main Propulsion Engines 

B408050050 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Cenerator Ouncis Group 840622 meeting RAV. C. L. TDI (Transamerica Delaval. Inc.) Owners Group 84/07/10 BERLINGER. C. Director's Office of Inspection and Enforcement 43pp 25734 133 24X Fiche 50-000,84/07/10.

8408330115 Responds to 840529 ltr re problems identified at Bahnson Co. Winston-Salem facility No HVAC equipment received from sub; facility Bahnson Co solicited to assess or to take any facility Bahmson Co solicited to assess or to take any meeded actions to improve GA program CLEMENTS.BR Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/07/23 DEYOUNO.R C Director's Office Office of Inspection and Enforcement 2pp 25916 104 24x Fiche 50-445,84/07/23.8408030115

8408050102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Fermination Qualification Review " Add1 copies sent to BNNL RAY.C L TDI (Transamerica Delaval, Inc.) Duners Group 84/07 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2 25932 137 24X Fichs 50-000,84/07/27,8408060102

84/07/27

--8408040138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " \* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139 24X Fiche 50-000,84/07/27,8408060102

8408090044 Interio Significant Deficiency Rept SDAR-129 re error in ### WHINDOW | Interin Significant Dericiency Rept Span-129 re error in tolerances used in calibr of adhesion tester Evaluation continuing Completion anticipated by 84090:
CLEMENTS.B R Toxas Utilities Electric Co (formerly Texas Utilities Generating Co ) 84/07/31 JOHNSON,E H Region 4, Office of Director Ip 25992 132 24X Fiche 50-445,84/07/31,8408090044

8408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets " Sets "
RAY, C L TDI (Transamerica Delaval, Inc.) Owners Oraup 8'
DENTON: H R Office of Nuclear Reactor Regulation, Director
25927 064 24( Fiche 50-000.84/08/01,8408060324

B40B160510 Final Deficiency Rept SDAR-129 re error in tolerances used in calibr of adhesion tester Initially reported on 840;16
Investigation complete Matter not reportable under 10CFR50 55(e) CLEMENTS.B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 64/08/06 JOHNSON.E H Region 4, Office of Director 1p 26107 350 24% Fiche 50-445.84/08/06.8408160310

8408160185 Interim Deficiency Rept SDAR-140 re qualification of main steam relief valves for actual loading conditions Initially regorded on 840710 Evaluation in progress & should be reported on e40710 evaluation in progress a should be completed by 840831 CLEMENTS, BR Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84708708 JOHNSCH, E H. Region 4. Office of Director ip 26106 328 24X Fiche 50-445,84708708,8408160185

B40B160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DERV-16 Diesel Engines " RAY, C L. TDI (Transamerica Delaval, Inc.) Owners Group B4/08/10 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 26091 147 24X Fiche 50-000,84/08/10,840B160394

--8408160403 "Design Revieu of Engine Base & Bearing Caps for TD1 DBRV-16 Diesel Engines " \* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp 26091 149 24X Fiche 50-000.84/08/10.8408160394

8408200295 Interim Significant Deficiency Rept SDAR-132 re installation of curtain fire dampers u/o proper provisions for thermal expansion initially reported on 840330 Review revealed 30 dampers required reuor) or mod Mext rept by 840817 FIXAR-L F Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 84/08/13 JOHNSON E M Region 4, Office of Director 5pp 26140 101 24X Fiche 50-445,84/08/13.8408200295

- 8408240115 Forwards SER re TDI Coners Group program plan SER addresses design review/quality revalidation program testing & insp. maint & surveillance? sets torth requirements for operation prior to completion of program plan EISENHUT, D.G. Division of Licensing 84/08/13 GEORGE, J. B. TDI (Transamerica Delavai, Inc.) Quiners Group 1p 26295 174 24X Fishe 50-000.84/08/13.8408240115
- --8493240197 Safery evaluation of TD1 Owners Group program plan Based on BRML evaluation.plan incorporates essential elements needed to resolve outstanding concerns re reliability of TD! engines for nuclear svc a NRC No Detailed Aftiliation Given 84/08/13 21pp 26255 195 24X Fiche 50 000.84/08/13.8408240115
- 8408160375 Forwards "Design Review of Elliott Model 906 Turbocharger Used on TDI DSR-48 2 DSRV-16 Emergency Diesel Generator Sets." representing rinal GA verified rept Addl copy forwarded to BMAL.per NRC request RAY,C L TDI (Transarerica Delaval, Inc.) Owners Gloup 84/08/14 DENTON,HR Office of Nuclear Reactor Regulation, Director 2pp 26088 163 24X Fiche 59-000,84/08/14,8408160395
- ~~8408160397 "Design Revieu of Elliott Model 906 Turbocharger Used on TDI DSR-48 & DSRV-16 Energency Diesel Generator Sets " \* Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp 26088 165 24% Fiche 50-000,84/08/14,8408160395
- 8408280468 Final deficiency rept re flooding levels in electrical control bldg resulting from fire suppression Initially reported on 840717 Engineering resolutions to isolate affected drains uill be implemented by 840830 CLEMENTS.B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co.) 84708164 JOHNSON,E H Region 4, Defice of Director 2pp 26282 078 24X Fiche 50-445,84708/16,8408280468
- 8408290125 Interim Daficiency Rapt SDAR-142 re unqualified Limitorque electric motors Initially reported on 840720 Evaluation will be completed by 840921 CLEMENTS.B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84708716 JOHNSON.E H Region 4. Office of Director 1p 26277 343 24X Fiche 50-443.84708/16.8408290125
- 408380375 Final deficiency rept re defective diesel generator valve springs Initially reported on 840720 Condition not reportable under 100FR30 55(e)
  CLEMENTS.B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/20 JOHNSON.E H Region 4. Office of Director 1p 26/82/278 24(Fiche 50-445.84/08/20.8408280375
- 8408280384 Interim deficiency rept re math defect in diesel generator fuel injection pump delivery valve holder initially reported on 840720 Evaluation will be completed by 840921 CLEMENTS.B R Texas Utilities Electric Co fformerly Texas Utilities Generating Co ) 84708720 JUHNSUN.E H Region 4 Office of Birector ip 26282 (03 24% Fiche 30-443.84708/20.8408280384
- 8408290179 Forwards response to 840723 request for add1 info on repts submitted by TDI Diesel Generator Dwners Group RAY, C L TDI (Transamerica Delaval, Inc.) Owners Group 84/08/23 BERLINOER.C Office of Nuclear Reactor Regulation. Director 12pp 26289 221 24X Fiche 50-000, 84/08/23, 8408270179
- T Hearing transcriots on non-antitrust matters
- 8407310383 Transcript of 840723 telcon in Glen Rose, TX Pp 38,567-38,651 
  \* Atomic Safety and Licensing Board Panel 84/07/23 91pp 25830 173 24% Fiche 50-445 84/07/23,8407310383
- 8408080027 Transcript of L Barnes 840728 deposition in Glen Rose, TX, re harassment & intimidation at racility Pp 59,000-59, 244 Supporting documentation encl
  - supporting cocumentation encl # Atomic Safety and Licensing Board Panel # BARNES.L Brown & Root. Inc (subs of Halliburton Co ) 84/07/28 267pp 25767 066 24X Fiche 50-445,84/07/28.8408080027
- 8408070273 Transcript of M Rhodes W Sims, M Yodd & S Burns 840730 deposition Pp 72.000-72.i60

  \* Atomic Safety and Licensing Board Panel RHODES, M L Ebasco Services, Inc. (subs. of Enserch Corp.) SIMS, W T Brown & Root, Inc. (subs. of Halliburton Co.) 84/07/30 175pp 25949 024 24; Fiche 50-445.84/07/30.8408070273
- 8408080257 franscript of C Biggs.G Fanning.R Whitman & J Uehlein 840730 depositions in Olen Rose, TX Pp 71,500-71,659 Supporting documentation encl \* Atomic Safety and Licensing Board Panel Biggs.C., FANNING, G Broun & Root. Inc. (subs. of Halliburton Co.) 84/07/30 170pp 25967 257 24X Fiche 50-445,84/07/30,8408080257

- B40B070105 vol 11 of transcript of M Gregory B40731 deposition in Glen Rose, TX Pp 54, 559-54, 718 Supporting documentation encl \* About Safety and Licensing Board Panel OREOGRY, M Texas Utilities Electric Co (Formerly Texas Utilities Generating Co ) OREGORY, M Brown ? Root, Inc (Subs of Halliburton Co ) 84/07/31 204pp 25950 045 244 Fiche 50-445, 84/07/31.840B070105
- 8408080051 Transcript of J Pitts 840731 deposition in Glen Rose,TX Pp 73.700-73.553 \* Atomic Safety and Licensing Board Panel PITTS, J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) PITTS, J Ebasco Services, Inc (subs of Enserch Corp) 84/07/31 55pp 25960 338 24X Fiche 53-445.84/07/31.8408080051
- 8408080100 Transcript of D. Anderson 840731 deposition in Glan Rose, TX re intimidation by GA personnel Pp 73,000-73,042 Supporting documentation enci \* Atomic Safety and Licensing Board Panel ANDERSON, D. L. Texas Utilities Flectric Co. (formerly Texas Utilities Generating Co.) 84/07/31 48pp 25965 117 24 (Fiche 50-445,84/07/31,8408080100
- B40B0B0245 Transcript of D Anderson, S Gpencer & A Boren B40731 depositions in Clen Rose. Tx Pp 72,500-72,681 Supporting documentation enci

  \* Atomic Safety and Licensing Board Panel SPENCER, S., BOREN, A Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/07/31 188pp 25967 065 24% Fiche 50-445,84/07/31.
- 8408080023 Transcript of ST Hoggard 840801 deposition in Glen Rose,TX Pp 74.000-74.016 Supporting documentation encl # Atomic Safety and Licensing Board Panel HDGOARD, S T Root. Inc (subs of Halliburton Co ) 84/08/01 24pp 25961 339 24X fiche 50-445.84/08/01.8408080023
- 8408080032 Transcript of HF Gunn 840801 deposition in Glen Rose, TX Pp 75,000-75,008 \* Abomic Safety and Licensing Board Panel GUNN, HF Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) GUNN, HF Brown & Root, Inc (subs of Halliburton Co ) 84/08/01 ilpp 25967 023 24% Fichs 50-445.84/08/01.8408080032
- B40808089 Transcript of JN Scarbrough & D Ethridge depositions in Glen Rose, FX Pp 74,500~74,521 Supporting documentation encl # Atumic Safety and Licensing Board Panel SCARBROUGH, J N , ETHRIDGE, D Brown & Root, Inc (subs of Halliburton Co) B4/08/01 26pp 25765 167 24% Fichs 50~445,84/08/01,8408080089
- B40B090272 Transcript of S4 Neumeyer 840B01 deposition in G1en Rose, TX Pp 59.500-59.683 Supporting documentation encl # Atomic Safety and Licensing Board Panel NEUMEYER, S A Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 84/08/01 207pp 25965 080 24X Fiche 50-445.84/08/01.8408080272
- 8408080146 Transcript of DN Chapman 840802 deposition in Glan Rose, TX Pp 76.500-76.631 Supporting documentation encl \* Atomic Safety and Licensing Board Panel CHAPMAN, D N. Texas Utilities Electric Co. (formerly Texas Utilities Operating Co.) 84/08/02 280pp 25959 278 24X Fiche 50-445.84/08/02.8408080146
- B40B0B0276 Transcript of 840802 telcon in Olen Rose, TX Pp 38,690-38,725

  \* Atomic Safety and Licensing Board Panel 84/08/02 37pp
  25764 321 24X Fiche 50-445,84/08/02,8408080276
- 8408080026 Transcript of M. Coats 840803 deposition in Glen Rose, TX Pp 77,500-77,558 Supporting documentation encl \* Atomic Safety and Licensing Board Panel COATS, M L Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/03 Sipp 25966 302 24% Fiche 50-445,84/08/03,8408080026
- 8408080294 Transcript of JC Keller 840803 deposition in Glen Rose,TX Pp 78,000-78,025 Supporting documentation encl s Atomic Safety and Licensing Board Panel KELLER,J C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) KELLER,J C Westinghouse Electric Corp 84/08/03 36pp 25965 270 247 Fichs 50-445,64/08/03,8408080294
- 8408220173 Board Notification 84-139 forwards transcript of 840607 meeting w/applicant re 840604 proposed FSAR amend on protective coatings EISENHUT.D Q Division of Licensing 84/08/17 BLOCH.P, JORDAN.W. MCCCLLON.W Atomic Safety and Licensing Board Panel 3pp 26262 098 24X Fiche 50-445.84/08/17.8408220179
- --8408280266 Transcript of 840607 meeting w/applicant in Bethesda, MD re protective coating inside containment Pp 1-100 \* Commissioners 84/06/07 120pp 26262 101 24X Fiche 50-445, 84/08/17, 8408220173

- 8408230432 Notice of filing in Docketing & Svc Branch of G Purdy in camera deposition in Glan Rose.TX PURDV.G Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) DSB 207 84/08/18 2pp 26204 007 24X Fiche 50-445.84/08/18 8408230432
- 8408220367 Forwards prefiled testimony of RM Duncan, RD McBee, R Simpson, DR Height, JE Zuahr DT Wilterding 5 JE Brown, depositions of JN Scarbough et al 5 affidavit of DK Eghert Certificate of Soc encil HARTMAN, S L Bishop, Liberman, Cook, Purcell & Reynolds HARTMAN, S L Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 206 64/08/20 CLEMENTS, W L Docketing & Services Branch 4pp 26192 126 24x Fiche 50-445, 84/08/20,
- --840822037; Preriled testimony of AD Justice on 840816 in Glen Rose, TX Pp 1-20 JUSTICE A D Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) JUSTICE, A D Brown & Root Inc (subs of Halliburton Co ) 84/08/16 20pp 26192 130 24X Fiche 50-445, 84/08/20, 8408220367
- --8408220374 Prefiled testimony of RM Duncan on 840815 in Glen Rose,TX Pp 1-17 DUNCAN.R M Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) DUNCAN.R (1 Brown & Root, Inc (subs of Hallburton Co ) 84/08/15 23pp 26192 190 24X Fiche 50-445,84/08/20.8408220367
- --B40B22O3BO Prefiled testimony of RD McDee on 840B16 in Glen Rose,TX Pp 1~24 MCDEE.R D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) MCDEE.R D Brown & Root, Inc (subs of Halliburton Co) 84/0B/16 35pp 26192 173 24X Fiche 50-445,84/0B/20,840B22O367
- --8408220381 Prefiled testimony of RW Simpson on 840815 in Glen Rose,TX Pp 1-38 SIMPSON,R W Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) SIMPSON,R W Brown & Root, Inc (subs of Halliburton Co ) 84/08/15 42pp 26192 208 24X Fiche 50-445,84/08/20,8409220367
- --8408220385 Prefiled testimony of DR Wright on 840816 in Glen Rose,TX Pp 1-9 WRIGHT,D R Texas Utilities Electric Co (formerly Taxas Utilities Generating Co ) WRIGHT,D R Brown & Root, Inc (subs of Halliburton Co ) 84708716 9pp 26192 260 24X Fiche 50-445,84708/20,8408220367
- --8408220388 Prefiled testimony of JC Zwahr & DT Wilterding on 840815 in Glen Rose, TX Pp 1-21
  ZWAHR, J C . WILTERDING, D T Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) ZWAHR, J E Brown & Root, Inc (subs of Halliburton Co ) 84/08/15 29pp 26192 269 24X
  Fiche 50-445, 84/08/20, 8408220367
- --B40B220393 Prefiled testimony of JE Brown on B40B15 in Glen Rose,TX Pp 1-21 BROWN,J E Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) BROWN,J E Brown & Root, Inc (subs of Halliburton Co ) 84/08/15 29pp 26192 298 24X Fiche 50-445,84/08/20,8408220367
- --8408220394 Deposition of ST Haggard on 840801 in Glen Rose,TX Pp 74.000-74.016 Personal resume encl HOGOARD,8 T Taxas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/01 23pp 26192 327 24X Fiche 50-445,84/08/20,8408220367
- --B408220399 Affidavit of DK Egbert re discussion w/DK Stiner in Oct 1982 concerning employee benefits EOBERT.D K Brown y Root. Inc (subs of Halliburton Co ) 84/09/01 7pp 26192 350 24X Fiche 50-445.84/08/20.8408220367
- --8408220403 Deposition of JN Scarbrough & D Ethridge on 840801 in Olen Rose, TX Pp 74,300-74,521 SCARBROUGH, J N , E HRIDGE, D Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) SCARBROUGH, J N Brown & Root, Inc (subs of Halliburton Co ) 84/08/01 27pp 26192 357 24X Fiche 50-445,84/08/20,8408220367
- --B408220405 Deposition of HF Gunn on 840801 in Glen Rose.TX Pp 75,000-75.008

  GUNN.H F Texas Utilities Electric Co (formerly Texas Utilities
  Generating Co ) GUNN.H F Brown & Root, Inc (subs of
  Halliburton Co ) 84/08/01 10pp 26193 022 24X

  Fiche 50-445,84/08/20,8408220367

- B408240247 Forwards CASE 84/32/0 prefiled testimony of IL Goldstein re harassment / intimidation RGISMAN.A Z Trial Lawyers for Public Justice RGISMAN.A Z Citizens Association for Sound Energy DSB 237 84/08/20 BLOCH.P B GPOSTIAN.H., JORDAN W H Atomic Safety and Licensing Board Panel 1p 26/23 119 24/Fiche 50-445,84/08/20.8408240247
- --8409240248 Written testinony of IL Goldstein re harassment & intimidation
  OULDSTEIN.I L. Citizens Association for Sound Energy
  OULDSTEIN.I L. Maryland, Univ. of, College Park, MD. 84/08/20
  43pp 26223 120 24X Fiche 50-445,84/08/20,8408240247
- B408240302 Transcript of B40822 hearing in Bethesda, MD Pp 13, 945-14, 014 \* Atomic Safety and Licensing Board Panel B4/08/22 51pp 26225 321 24% Fiche 55-445 64/08/22, 8408240302
- 8408300103 Transcript of 840827 hearing in Bethesda, MD Pp 14, 015-14, 180 \* Atomir Safety and Licensing Board Panel 84/08/27 168pp 26305 001 24X Fiche 50-445, 84/08/27, 8408300103
- X Unsite Storage of Low Level Waste
- 8408270271 Advises of executed Contract DE-CR01-84RW00012 w/DDE for disposal of spent nuclear fuel from facilities Related info enc!

  8CHMIDT.H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/21 y0UN08LQDD,B N Licensing Branch 1 3pp 26241 015 24X Fichs 55-445.84/08/21,8408270271

#### DOCKET STN-50-447 GESSAR-238

- A Application/construction stage documents & correspondence
- B40B010324 Notification of B40B01 meeting w/GE in Bethesda,MD to discuss status of CESSAR II severe accident review & to focus attention on remaining issues re review SCALEITI.D C Standardization & Special Projects Branch B4/07/26 THOMAS.C O Standardization & Special Projects Branch 3pp 25B72 314 24X Fiche 50-447,84/07/26,8408010324
- B408090203 Notification of 840808 meeting w/GE in San Jose CA to discuss seismic hazard analysis for GESSAR II 8CALETTI D C Standardization & Special Projects Branch 84/08/02 THDMAS C O Standardization & Special Projects Branch 3pp 23991 200 24X Fiche 50-447.84/08/02,8408090203
- 8408090429 Reissued notification of 840809 meeting w/GE & JBA in Bethesda,MD to discuss seismic hazard analysis of GESSAR II 9CALETTI.D C Standardization & Special Projects Branch 84/08/02 THOMAS.C D Standardization / Special Projects Branch 3pp 25984 299 24Y Fiche 90-447.84/08/02,8408090429
- 840B160339 Forwards BNL 830727 review of GESSAR PRA W/o encl NIEMCZYK,S J Union of Concerned Scientists 84/08/06 QUIRK, J General Electric Co 1p 26/059 361 247 Fiche 50-447, 84/08/06, 840B160339
- B408230209 Forwards draft amend to GESSAR II Sections 16 12 & 16 21, in response to 10CFR50 34(f), Items (1)(xii) & (2)(ix) re evaluation of alternate hydrogen control sys (HCS) & HCS preliminary design, respectively SHERWIOD.6 9 Ceneral Electric Co 84/08/20 EISENHUT, D G. Division of Licensing 10pp 26209 218 24X Fiche 50-447,84/08/20,8408230209

### H General correspondence

- 8408070025 Responds to 840705 ltr to W Dircks requesting info re QESBAR-II meeting notifications Practice identified in OH Cunningham 840620 ltr renains intact GESBAR-II meeting notices will be posted shortly after receipt by PDR DENTON, H R Office of Nuclear Reactor Regulation, Director 84/07/25 NIEMCZYK, S J Union of Concerned Scientists 2pp 25956 188 24X Fiche 50-447,84/07/25,8408070025
- --B408070027 Informs of difficulty in obtaining scheduling info re OE/NRC meetings concerning OESSAR-II All applicant/NRC meetings should be announced to days in advance by posting notices in PDR & including notices in NRC tapes NIEMCZYK.S J Union of Concerned Scientists B4/07/05 DIRCKS.W DPfice of the Executive Director for Operations 4pp 25956 190, 24X Fiche 50-447.84/07/25.8408070025

# P Operating license stage documents \* correspondence

B40B270155 Requests exemption to revise 10CFx170 license fee schedule re GESSAR II review Elemption to schedule appropriate since review of GESSAR II design committed under regulations & policies in existence in early 1982 BHERWDOD, G. G. General Electric Co. 84/08/10. DIRCKS, N.J. Office of the Executive Director of Operations. 2pp. 26245-222. 24X Fichs. 50-447,84/08/10,84/8770/155

#### DOCKET SIN-50-454 BYRON STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 8408130409 Forwards for review & comment, marked-up preliminary test procedure re functional & spring rate testing of steam generator snubbers in response to 840308 concerns in IE Insp Repts 50-435/84-06 SUARTZ.E D Commonwealth Edison Co 84/04/26 KEPPLER.J G Region 3, Office of Director 23pp 26010 192 24X Fiche 50-454,84/04/26.8408130409
- 8408010116 Forwards request for add1 info re Tech Specs on relief valves & ESF response time Response requested within 7 days of its date YOUNGBLOOD, D J Licensing Branch 1 84/07/19 FARRAR, D L Commonwealth Edison Co 7pp 25873 327 24% Fiche 50-454,84/07/19,8408010116
- 8408070034 Requests add1 info to support rescheduled fuel load date of B40915 Response requested within 10 days of ltr receipt YOUNGBLOOD B J Licensing Branch 1 B4/07/25 FARRAR, D L Commonwealth Edison Co App 25955 336 24X Fiche 50-494,84/07/25,8408070034
- 8408060136 Forwards response to 840719 request for add1 info re Tech Specs Complete package of comments A suggestions to Section 3/4 8 of proof & review version of Unit 1 Tech Specs also encl
  SHARTZ, E.D. Commonwealth Edison LO 84/07/26 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 65pp 25934 013 24X Fiche 30-454,84/07/26,8408060136
- B40B1403B0 Forwards responses to FSAR Questions 10 57,10 63,10 64, 10 65 & 10 66 Revised response to Question 10 57 based on revised safe shutdoun analysis Info will be included in next FSAR amend SWARTZ, E D Commune-eith Edison Co 84/08/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 32pp 26041 132 24X Fiche 50-000,84/08/02,8408140380
- 8408070110 Generic Ltr 84-17 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Generic Safety Issues " Svc list encl EISENHUT.D 6 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000.84/08/06.8408070110
- 840Bi&0345 Advises that GA program applicable to all nuclear generating stations & satisfies provisions of 10CFR71 Fee remitted per 10LFR170 31 FARRAR.D t Communuealth Edison Co 84/08/06 Office of Nuclear Material Safety & Safeguards, Director 1p 26092 184 24X Fiche 50-000.84/08/06.8408160345
- B40B160415 Advises that main hook % lower load block on fuel handling bldg crane will be temporarily replaced to meet requirement of replacing Unit 1 reactor colant pump motor assembly; per B30426 commitment
  ALEXANDER, G Commonwealth Edison Co 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26085:358 24X Fiche 50-454.84/08/07.8408160415
- 8408170069 Application to amend CPPR-30, extending permit to 850101 to cover time for OL hearings 1 issuance FARRAR, D L Commonwealth Edison Co 84/08/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 86119 031 24X Fiche 50-934,84/08/13,8408170069

- 8408220239 Discusses post-accident sampling sys being installed to address NRC requirements in NUREG-0737. Item II 0 3 High radiation sampling sys described in FSAR will be aperational on each unit prior to initial criticality TRAMM. T R Commonwealth Edison Co 84/08/13 DENTON. H R Office Ruclear Reactor Regulation. Director 1p 26193 139 24X Fiche 50-000.84/08/13.4480820239
- 8408220368 Supple 931216 comments re proof & review Tech Spece Refithree loop operation during Modes 1~4 should be removed due to lack of Westinghouse analyses
  SWARTZ.E D Commonwealth Edison Co 84/08/15 DENTON, H R Off of Muclear Reactor Regulation, Director 1p 26191 346 24X
  Fiche 50 454.84/08/15.8408220368
- 8408270113 Informs of schedule for resolving concerns re provisions for sampling gaseous radiolodine OL should be conditioned to require resolution of NUREG-0737 requirements for sampling gaseous effluent steam prior to refueling outage TRAMM.T R Commonwealth Edison Co 84/08/17 DENTON.H R Offor Nuclear Reactor Regulation, Director 1p 26247 329 24X Fiche 50-454.84/08/17,8408270113
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors applicants for QLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT. D © Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24x Fich 50-000.84/08/20.8408200275
- 8408270118 Submits add1 inro re basis for proposed Tech Spec requirements on availability of Diesel Generator 2A during time Unit 2 under const TRAMM.T R Componuealth Edison Co 84/08/21 DENTON,H R OF of Nuclear Reactor Regulation, Director 2pp 26247 338 24X Fiche 50-000.84/08/21.8408270118
- 8408290365 Forwards request for add1 info re answer to Question 12 concerning reactor sys areas Due to lack of clarity in original response response should be revised Revised response requested within 15 days of 1tr receipt YOUNGBLOOD, B J Licensing Branch 1 84/08/22 FARRAR, D L Commonwealth Edison Co 2pp 26310 359 24X Fiche 30-454,84/0 8408290365
- B408310163 Provides addl info to support proposed Tech Spec change diesel oil sampling containment pressure Hi-1 & detector plateau curves, per NRC, vitl 840913-16 meetings TRAMM.T R Commonwealth Edison Co 94/08/23 DENTON, H R Off of Nuclear Reactor Regulation, Director 3pp 26319 173 24X Fiche 50-454,84/08/23,8408310163
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8408010185 Forwards request for addl info for review of vol reduct sys (Autstanding Item 15 of Byron SER) Response requested within 30 days of ltr date OLSHAN, L N Licensing Branch 1 84/07/19 FARRAR, D L. Commonwealth Edison Co 10pp 25873 292 24X Fiche 50-000, 84/07/19,8408010185
- 8408140371 Forwards compliance review against GDC 51 for reactor containment pressure boundary components Review for Braidwood Station should resolve SER Outstanding Item 4 SWARTZ.E D Commonwealth Edison Co 84/08/09 DENTON, H R Of Nuclear Reactor Regulation, Director 17pp 26042 279 24) Fiche 50-000.84/08/09.8498140371
- 8408270265 Forwards add1 documentation re preliminary site work fiplacement & composition in Area of Concern 12 Info should close SER Dutstanding Item 1 Test results encl TRAMN, TR Commonwealth Edison Co 84/08/10 DENTON, HR Off of Nuclear Reactor Regulation, Director Spp. 26240, 202 24x Fiche 50-454,84/08/10,8408270265
- --8408270276 "Field Density Test Results "
  NELSON,R E H H Holmes Testing Laboratories, Inc 20 75/(
  ip 26240 207 24x Fiche 50-454.84/08/10.8408270265
- ----B4082702B4 "Rept of Field Compaction Tests " | HOLMES, H H H H Holmes Testing Laboratories, Inc 37 75// ip 26240 208 24x Fiche 50-454, 84/08/10, 8408270265
- --B408270292 "Rept of Field Compaction Tests."

  HOLMES.H H H H Holmes Testing Laboratories, Inc 81 75/(2pp 26240 209 24% Fiche 50-454,84/08/10.8408270265

75/

--8408270296 "Rept of Field Compaction Tests "
HOLMES.H H H H Holmes Testing Laboratories, Inc 97.
4pp 26240 211 24X Fiche 50-454,84/08/10,8408270265.

8408270204 Forwards addl info re monitoring of leakage from sys outside containment used to transport highly radioactive fluid & gases in post-accident condition Info should close SER Confirmatory Issue 28(a) Office

TRAMM, T R Commonwealth Edison Co 84/08/11 DENTON, H R Of Nuclear Reactor Regulation, Director 7pp 26245 103 24x Fiche 50-000,84/08/11.8408270204

- 8408220306 Forwards proprietary & nonproprietary responses to NRC ltr re improved thermal design procedure Response should close Byron SER Outstanding Item 8 Info deleted Proprietary response wisthald (ref 10CFR2 790)
  TRAMM.T R Commonwealth Edison Co 84/08/13 DENTUN, H R Office of Nuclear Reactor Regulation. Director 20pp 26193 053 24X
  Fiche 50-000.84/08/13.8408220306
- --B408220321 Requests withholding proprietary response to NRC questions on inproved thermal design procedures & rod bow, per 10CFR2 790 Affidavit AW-76-60 encl WIEBEMANN, R A Westinghouse Electric Corp B3/12/27 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E Q Licensing Branch 4 Bpp 26193 073 24X Fiche 50-000, 84/08/13, 8408220306
- 84082703/3 Forwards add1 info re instrumentation being installed for detection of inadequate core cooling Info should close SER Outstanding Item 7 u/o any license conditions TRAMM.T R Commonwealth Edison Co 84/08/20 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 26240 254 24X Fiche 50-000.84/08/20.8408270373 Office
- 8408280301 Requests additinfo to complete review of environ qualification of equipment (SER Dutstanding Item 7) Response expected within 10 days of itr date YOUN0810000. D Licensing Branch 1 84/08/22 FARRAR, D L Commonwealth Edison Co 3pp 26274 083 24X Fiche 50-454, 84/08/22, 200000000.
- 8408310226 Forwards add1 info re vol reduction sys, in response to B40710 request NRC review of info necessary to close SER Outstanding Item 15
  TRAMM, T R Commonwealth Edison Co 84/08/24 DENTON, H R Offor Nuclear Reactor Regulation, Director 27pp 26322 138 24) Fiche 50-000.84/08/24.8408310226 Office
- F Security, medical, emergency & fire protection plans
- 8408150386 Forwards IE Insp Repts 50-454/84-46 & 50-455/84-31 on PAPERIELLO, C J Region 3, Office of Director 84/07/27 RECD, C Commonwealth Edison Co 2pp 26077 387 24X Fiche 50-454,84/07/27,
- --8408190394 IE Insp Repts 50-454/84-46 & 50-455/84-31 on 840711-13 No noncompliance or deviations identified Major areas inspected selected open & improvement items identified during emergency preparedness implementation appraisal PLOSKI, T J, CHRISTOFFER, Q, SMITH, M J Region 3, Office of Director 84/07/27 5pp 26077 359 24X Fiche 50-454,84/07/27,8408150386
- B408220243 Summary of 840731 meeting w/util in Silver Spring, MD resecurity plan implementation
  \* NRC No Detailed Affiliation Given B4/07/31 NRC No Detailed Affiliation Given 2pp 26203 311 24X
  Fiche 50-000,84/07/31.8408220243
- 8408080198 Forwards Amend 4 to "Fire Protection Rept," including detailed comparison of design, const. testing & maint practices against NFPA stds SHARTZ, E D Commonwealth Edison Co 84/08/02 DENTON, H R (of Notlear Reactor Repulation, Director 3pp 25985 001 24) Fiche, 50-000, 84/08/02, 8408080198 DENTON H R OF
- --8408080205 Amend 4 to "Fire Protection Rept" \* Commonwealth Edison Co 84/07/31 125pp Fichs 50-000,84/08/02,8408080198 25985 004 24X
- 8408140234 Revised emergency plan implementing procedures, including BZP 100-T2, "Operations Director-Checklist," BZP 100-T3, "Technical Director-Checklist" & BZP 100-T4, "Maint Director-Checklist" W/transmittal & receipt form # Commonwealth Edison Co 84/08/03 252pp 26056 077 24X Fiche 50-454,84/08/03.8408140234
- 840Bi3040i Responds to 840705 clarification of info re util means of satisfying annual regulatory requirement to review emergency action levels w/offsite emergency support organizations info acceptable action levels w/offsite emergency support organizations Info acceptable
  PAPERIELLO.C J Region 3, Offsice of Director 84/08/07 REED.C Commonwealth Edison Co ip 26010 130 24X Fiche 50-000,84/08/07.8408130401

- --8408130413 Responds to 840404 ltr re means for satisfying requirements of IOCFR50.App E.Paragraph IV B Proposal for satisfying requirements to review emergency action levels by offsite agencies clarified Region 3, Office of Director Spp. 26010 131 24x
  Fiche 50-000,84/08/07,8408133401
- 8408240139 Rev i to Emergency Plan Implementing Procedure BZP 500-T7, "Checklist Operational Support Ctr " W/840817 transmittal form \* Commonwealth Edison Co 84/08/15 App 26228 168 24X Fichs 50-454,84/08/15,8408240139
- 8408220104 Forwards evacuation time estimates incorporating changes re employment ctr shutdown times.per ASLB 840113 initial decision Review of addl info should obviate need for license DENTON, H. R. O. 24% TRAMM, T.R. Commonwealth Edison Co. 84/08/16 DENTON, H of Nuclear Reactor Regulation, Director 1p. 26191 194 Fiche 50-454,84/08/16,8408220106
- --8408220112 "Evacuation Time Estimates Within Plume Exposure Pathway Emergency Planning Zone for Byron Nuclear Generating Station " \* Commonwealth Edison Co 84/06/30 113pp 26191 195 Fiche 50-454,84/08/14,8408220106
- B408240173 Rev i to Procedure BZP 380-A3, "Locations of Fixed Environ Radiological Monitoring Station Air Samplers " W/840907 \* Commonwealth Edison Co 84/08/17 3pp 26228 165 24X
- Fiche 50-454,84/08/17,8408240173
- 8408270218 Forwards advanced revs to fire protection rept included in Amend 5 & add1 info re other rire protection issues for station Resumes of fire protection engineers involved in program will be included in Amend 5 TRAMM.TR Commonwealth Edison Co 84/08/20 DENTON, HR Office of Nuclear Reactor Regulation, Director 35pp 26245 110 24X Fichs 50-454.84/08/20.8408270218

### 9 Adjudicatory correspondence

- 8405280241 First set of interrogatories to intervenors, requesting list of witnesses to be presented on intervenors behalf at reopened hearings & summary of testimony Certificate of Syc reopened nearings & summary of testimony Certificate of Syc encl Related correspondence BECKER.B D Commonwealth Edison Co BECKER.B D Isham, Lincoln & Beale DSB 311 84/05/18 3pp 24456 202 24X Fiche 50-454.84/05/18.8405250241
- 8406260276 Submits partial response to 840619 itr Transparent effort not being made to stall proceeding Method of responding to discovery request prohibits orderly discovery of case Cartificate of Svc encl Related correspondence WHICHER.J M Businessmen for the Public Interest WHICHER.J M Whicher.J M DSB 862 84/06/20 MILLER.M I Isham Lincoln & Beale MILLER.M I Commonwealth Edison Co 3pp 25130 041 24) Fiche 50-454.84/06/20,8406260276
- 8408010177 Notice of appearance in proceeding Certificate of Svc encl LEARNER, HA League of Women Voters of Rockford, IL LEARNER, HA DeKalb Area Alliance for Responsible Energy LEARNER, HA Sinnissippi Alliance for the Environment (SAFE) DBB 669 84/07/2 4pp 25855 322 24% Fiche 50-454,84/07/24,8408010177 84/07/24
- 8408010181 Notices of appearance in proceeding Certificate of Svc encl JUDSON,V A , WRIGHT,T W. League of Momen Voters of Rockford, IL. JUDSON,V A DeKalb Area Alliance for Responsible Energy DBB 660 84/07/24 6pp 25854 356 24X Fiche 50-454,84/07/24,8408010181
- 8408070463 Order extending time until 840810 for Commission to act to raview ALAB-770 Served on 840805 CHILK: B J Office of the Secretary of the Commission DSB 753 84/08/03 Commissioners 1p 25940 331 24X Fichs 50-454:84/08/03:8408070463
- 8408080390 Request for suppls to util amended responses t Interrogatories il & 12 Certificate of Svc encl Related JUBBON: V A
  JUBBON
- 8408080395 Forwards request for suppls to util amended responses to Interrogatories 11 & 12 of intervenor first set of interrogatories W/o encl Related correspondence
  JUDSON,V A Businessmen for the Public Interest DSB 841
  84/08/06 MILLER,N I I Isham, Lincoln & Geale 2pp 25974 101
  24X Fichs 50-484/84/08/06,8408080395

- 8408090164 Forwards 640421 deposition of VD Nard W/o encl Related correspondence MILCOVE, M N Hearing Branch 2 DSB 670 84/08/07 WESTHALL, M Taylog Associates 1p 25473 128 244 Fiche 50-454,84/08/07.
- 8408130297 Forwards six documents for proposed inclusion w/board notification Documents include RL Spessard 840723 itr to C Reed W/o encl Related correspondence LEWIS:S H Hearing Blanch 2 DSB 908 84/08/08 DLSHAN, L N Licenting Blanch 1 2pp 26010 279 24X Fiche 50-454.84/08/08.8408130299
- 8408270303 Expresses concern & opposition to licensing of plant ASLB should listen to concern of workers Facilities not needed & being put on line for convenience \* profit of util SCHRADER, D. Affiliation Not Assigned DSB 372 84/08/09 SMITH, Atomic Safety and Licensing Board Fanel 2pp 26287 360 24X fiche 50-494,84/08/09.8408290303
- B408290308 Requests NRC review of outstanding items re licensing of plant PETERSON, T Affiliation Not Assigned DSB 365 84/08/11 SMITH Atomic Safety and Licensing Board Panel 1p 26289 362 24X Fiche 50-454,84/08/11,8408290308
- B40B140454 Informs that Commission declined to review ALAB-770 Time within which Commission may act to review has expired & decision becare final agency action on B40B10 Served on B40B13

  CHILK, S. J. Office of the Secretary of the Commission DSB 011

  B4/0B/13 Atomic Sefety and Licensing Appeal Panel 1p

  26060 361 24X Fiche 50-454.84/08/13.840B140454
- 8408170382 Forwards corrections A attachments to CC Stokes written testimony W/o encis Related correspondence RIOHT.T W Businessmen for the Public Interest DSO 101 84/08/15 SMITH,I W . COLE,R F . CALLIHAN.A D Atomic Safety and Licensing Board Panel 1p 26128 257 24X Fiche 50-454.84/08/15.8408170382
- B408290310 Expresses concern that plant will go on line before proven safe Performance of NRC has caused puzzlement & disappointment NRC supports whil position even in face of serious allegations re-plant safety PEWBLE, J. A. Affiliation Not Assigned DSB 366 84/08/15 BMITH, I.W. Atomic Safety and Licensing Board Panel 2pp 26289 355 24% Fiche 20-454,84/08/15,8408290310
- 840821033A Memorandum opposing intervenor 840813 motion for leave to file testimony of WH Blevel Blevel qualifications not of expert caliber to assist ASLB Related correspondence MILLER.M Connonwealth Edison Co MILLER.M Isham, Lincoln & Beale DSB 182 04/08/16 Atomic Safety and Licensing Board Panel Bpp 24179 342 24% Fiche 50-454,84/08/16,8408210336
- ~840821034^ Affidavit of GT Klopp re WH Bleuel proposed testimony concerning need for failure modes & effects analysis Certificate of Svc & svc list entl Related correspondence KLOPP.6 T Commonwealth Edison Co. 84/08/16 8pp 26179 350 24X Fiche 50-454-84/08/16.8408210336
- 8408280443 Forwards 840718 Ofc of Investigation (OI) Rept 3-83-006, transmitted for placement in PDR OI reviewed document & made deletions to protect confidentiality & privacy Related correspondence
  LEMIS S H Office of the Executive Legal Director DSB 337 84/08/16 CLEMENTS W L Docketing & Services Branch 138pp 26280 347 24% Fiche 30-454,84/08/16,8408280443
- B40B290307 Expresses concern re licensing of plant & 6,000 discrepancies in bldg of plant labeled nonsignificant Review of NRC outstanding itens requested GRUMLEY, J E Affiliation Not Assigned DSB 364 B4/0B/16 SMITH, I W Atonic Safety and Licensing Board Panel ip 26290 341 24X Fiche 50-454,84/0B/16,8408290307
- B408290313 Expresses concern re licensing of plant ABLB should listen to concerns of workers wishing to testify Facilities not needed & being put on line for convenience of util STILES.J M Mount Morris Times, Mount Morris, IL DSB 368 84/08/16 SMITH Atomic Safety and Licensing Board Panel ip 26270 336 24X Fichs 30-454.84/08/16.8408270313
- B40B290275 Expresses concerns re safety of facility & citizens paying for util misralculation
  DANIELSEN,D C Affiliation Not Assigned DSB 370 84/08/17
  SHITH,I W Atonic Safety and Licensing Board Panel ip 26270 357
  24X Fiche 30-454,84/08/17,8408270275

- 8408270163 Notion to exclude portions of prefiled testimony of CC Stokes, filed on 840816 Polated correspondence GALLO, J Formorrealth Edison Co GALLO, J Isham, Lincoln & Beale D88 286 84 03/19 Atomic Safety and Licensing Board Panel 9pp 26245 263 74x Fiche 50 454 84,08/19,8408270163
- --B408270172 A+fidavit of K1 Kostal re prefiled testimony of C Stokes Certi+icate of Sic encl Related correspondence KCBTAL.F T Commonwealth Edison Co KOSTAL.F T Sargent & Lundy, Inc B4/08/18 Atomic Serety and Licensing Board Panel Spp 26245 272 24x Fiche 50 154,84/08/19,8408270163
- 8408270305 Questions sanity \* political persuation of members of Sinnissippi Alliance for uppusing start up of facilities Delays cost millions Urges startup LIGHTCAP J B Affiliation Not Assigned DSB 3/1 84/08/20 SMITH. I Atomic Safety and Circhising Board Panel 2pp 26270 337 24X Fichs 50-484,84/08/20,8408290305
- 8408290328 Expresses concerning licensing of plant Urges NRC to review outstanding points of contention about safety & make sure reinspley idence not merely testimony convincing of safety EMMETT. J. Affiliation Not Absigned DSB 373 84/08/20 SMITH Atomic Safety and Licensing Board Panel 2pp 26289 347 24X Fiche 50-454.84/08/20.8408290328
- 8408290309 Commends IW Snith for decision to withhold licensing of plant until safety issues resolved Open discussion re addl safety concerns requested HOLMBERG. J. Illinois, State of DSB 367 84/08/22 SMITH.1 W Atomic Safety and Licensing Board Panel ip 26290 360 24% Fiche 50-454,84/08/22,8408290339
- 8408270281 E.presses concerns re licensing % opening of plant In Jan 1984, when util was denied license, ruling considered final NRC issuance of license to plant so obviously defective as to be beyond belief POZODLSKI. A Affiliation No\* Assigned DSB 374 84/08/28 SMITH, I Aton; Safety and Licensing Board Panel 4pp 26290 329 24X Fiche 50-454.84/08/28.8408270281
- 840831020) Notice of withdrawal of appearance in proceeding Related correspondence WHICHER, J M Businessmen for the Public Interest DBB 421 84/08/20 SMITH, I W. COLE, R.F., CALLIHAN, A.D. Atomic Safety and Licensing Board Panel 1p 26318 311 24X Fiche 50-454, 84/08/28, 8408310201
- H General correspondence
- B405180145 Responds to 840314 ltr to Chairman Palladino which oncl
  W & V Smelser concern re Marble Hill & Bailly cancellation,
  withdrawal of util application for Zimmer & denial of
  license for Byron facility
  DIRCKS,W J Office of the Executive Director for Operations
  84/05/04 LUCAR,R 0 Senatc 7pp 24524 325 24V
  Fiche 50-000.84/05/04.8405180145
- ---B405180152 Requests response to encl W & V Smalser B40210 inquiry into NRC attitude toward utils Concerns include Marble Hill & Bailly cancellation. withdrawal of util application for Zimmer & denial of license for Byron facility LUOAR, R G Sonate B4703714 PALLADINO, N Commissioners 3pp 24524 331 24X Fichs 50-000, 84705704, 8405180145
- K Utility Final Safety Analysis Report (FSAR) & amends
- B40B300033 Forwards affidant t attesting to distribution of FBAR Amends 44 & 45 TRAMM.T R Commonwealth Edison Co 84/08/16 DENTON, H R Office of Nuclea, Reactor Regulation, Director 2pp 26307 236 24X Fiche 50-000.81/08/16
- G Inspection reports. IE Bulletins & Correspondence
- 8408130415 Forwards, for review, Rev 1 to "Evaluation of Energy Absorbing Hatl for Pipe Uhip Restraints," in response to IE Insp Repts 50 454/83-06 & 50-455/83-05 SWARTZ, E.D. Commonwealth Edison Co. 84/04/13 KEPPLER, J. G. Region 3. Office of Director 2pp 26011 938 24X Fiche 50-000, 84/04/13, 8408130415
- --8408130420 Rev 1 to "Evaluation of Energy Absorbing Mat1 for Pipe Whip Restraints " KAD 6 C : YANO,M S : SU.T Y Sargent & Lundy, Inc SAD-431 RO1 84/04/30 47pp 26011 040 24X Fiche 50-000/84/04/13.8408130415

- B40B130409 Furwards, for review 'comment murked-up preliminary test procedure re functional % spring rate testing of steam generator smobbers.in response to 84030B concerns in IE Insp Repts 50 154.84-08 & 50-495,81-04 SB1-05 SWARTZ.E D Commonwealth Edison Co 84/04/26 KEPPLER.J G Region 3. Office or Director 23pp 26010 192 24% Fiche 50-454.84/04/26. B408130409
- 8408010332 Forwards IE Insp Repts 50-454/84-33,50-455/84-26 & 30-17034/84-01 on 840521-23,29-31 \* 0601 % 05-06 No noncompliance noted PAPERIELLO,C J Region 3, Orrice of Director 84/07/10 REED.C Commonwealth Edison Co 2pp 25866 077 24X Fiche 50-454,84/07/10,8408010332
- --B40B010341 IE Insp Repts 50-454/B4 33.50-455/B4-26 & 30-17034/B4-01 on B40521-23,27-31 & 0501 / 05-06 No noncompliance noted Major areas inspected preoperational radiation protection program & status of preoperational sys demonstrations HUETER.L J. GILL.C F., GREGER.L R. Region 3, Office of Director B4/07/10 20pp 25866 079 24X Fiche 50-454.84/07/10,8408010332
- B40B0B0188 Forwards IE Insp Repts 50-454/84-25, 50-455/84-1B, 50-454/84-11 /r. 50-457/84-11 on 840425 & 0522-23 No nancompliance noted SPESSARD, R L Region 3. Office of Director 84/07/18 REED, C Commitmeelth Edison Co. 2pp. 25974 327 24X Fiche 50-000, 84/07/18, 8408700188
- --8408080195 IE lnsp Repts 50-454/84-25, 50-455/84-18, 50-456/84-11 & 50-457/84-11 on 840425 & 0522-23 No noncompliance noted Major areas inspected design calculations re primary shield wall \* reactor pressure shield wall \* region 3. Office of Director 84/07/18 4pp 25974 329 24X Fiche 50-000, 84/07/18, 8408080188
- 8408090212 Forwards IE Insp Repts 50-454/84-29 & 50-455/84-21 on 840514-0710 No noncompliance identified SPESSARD, R L Region 3, Office of Director 84/07/23 REED, C Commonwealth Edison Co 2pp 25994 165 24X Fiche 50-454,84/07/23,8408090212
- --8408090217 IE Insp Repts 30-454/84-27 & 50-455/84-21 on 840514-0710 No noncompliance identified Major areas inspected licensee action on IOCFR50 55(e) (tem re butt splices in electrical conductors

  CHRISTNOT.E.F. MENDEZ.R. HILLIAMS, C.C. Region 3, Office of Director 84,07/23 App. 25994 167 24X Ficha 50-454,84/07/23,8408090212
- 8407250227 IE Into Notice B4-57. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants." Svc list encl.
  JORDAN, E. L. Division of Lmeigency Preparedness & Engineering Response (Post 630103) 84/07/27. Consolidated Edison Co. of New York, Inc. 119pp 25845 047 24X Fiche 50-000, 84/07/27, 8407250229
- 8407310032 Board Notification 84-135 forwards SALP Repts 50-454/84-22 & 50-455/84-15 for Jan 1983 Apr 1984 Any util comments on rept will be forwarded for review NOVAK:1 M Assistant Director for Licensing 84/07/27 SMITH, I W. CALLIMAN.D Atomic Safety and Licensing Board Panel RDSENTHAL.A S Atomic Safety and Licensing Board Panel RDSENTHAL.A S Fiche 50-454.84/07/27.8407310032
- 8408150386 Forwards IE Insp Repts 50-454/84-46 \* 50-455/84-31 on 840711-13 No noncompliance noted PAPERIELLO.C J Region 3, Office of Director 84/07/27 REED.C Commonwealth Edison Co 2pp 26077 357 24% Fiche 50-454,84/07/27,8408150386
- --8408150394 IE Insp Repts 50-454/84-46 & 50-455/84-31 on 840711-13 No noncompliance or deviations identified Major areas inspected selected open & improvement items identified during emergency preparedness implementation appraisal PLOSKI,T J, CHRISTOFFER,G, SMITH,M J, Region 3, Office of Director 84'07/27 5pp 26077 359 24X Fiche 50-454,84/07/27,8408150386
- 840B150482 Forwards IE Insp Rept 50-454/84-48 on 840713,16 & 17 No honcompliance nated SPESSARD,R L Region 3, Office of Director 84/07/27 REED,C Commonwealth Edison Co 2pp 26078 171 24X Fiche 50-454,84/07/27,8408130482
- ~~8408130487 IE Insp Rept 50-454/84-48 on 840713,16 \$ 17 No noncompliance of deviations noted Major areas inspected followup on previous insp findings is testing of pipe support \$ restraint sqs RAUFMAN.F D. DANIELSON.D H Region 3. Office of Director 84/07/27 4pp 26078 173 24X Fichs 50-454,84/07/27,8408150482

- 8408070213 Forwards IE Insp Repts 50-454/84-32 & 50-455/84-25 on B4042/.-0717 % notice of violation STREETER. J F Region 3, Office of Director 84/07/30 REED. C Commonwealth Edison Co. 2pp 25948 337 24X Fiche 50-454.84/07/30, 8408070213
- --8408070216 Notice of violation from insp on 840426-0717 STRFETER, J.F. Region 3, Office of Director 84/07/30 3pp 25948 339 24% Fiche 50-454,84/07/30,8408070213
- --8408070221 IE insp Repts 50-454/84-32 & 50-455/84-25 on 840426-0717 Noncompliance noted failure to document nonconforming conditions failure to control nonconforming items & failure to take effective corrective actions re weld problems HAYES, 0 W COMMAUOUTON, X . STREETER, J F Region 3, Office of Director 84/07/30 lipp 25948 342 24X Fiche 50-454,84/07/30,8408070213
- 8408160212 Forwards IE Insp Rept 50-454/84-44 on 840611-15,22 & 25-28 & notice of violation
  SPESSARD.R L Region 3, Office of Director 84/07/30 REED.C Commonwealth Edison Co 2pp 26106 248 24X Fiche 50-454,84/07/30,8408160212
- --8408160216 Notice of violation from insp on 840611.22 & 25-28 BPESBARD, R L Region 3. Office of Director 84/07/30 2pj 26106 250 24% Fiche 50-454,84/07/30,8408160212
- --8408160217 IE Insp Rept 50-454/84-44 on 840611-15,22 & 25-28

  Moncompliance noted Failure to implement corrective action on nonconfornance identified during receipt insp & failure to store components per supplier instructions

  KROPP, W. HAMKING: F Region 3. Office of Director 84/07/26

  10pp 26106 252 24X Fichs 50-454,84/07/30.8408160212
- B40B070204 Ack receipt of 8407;2 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-454/84-23 & 50-459/84-16 SPESSARD, R L Region 3, Office of Otrector 84/08/01 REED, C Commonwealth Edison Co 2pp 25749 262 24X Fiche 50-454.84/08/01, 840B070204
- --8408070212 Responds to NRC 840612 ltr re violations noted in IE Insp Repts 50-454/84-22 & 50-455/84-16 Corrective actions 60 equipment installation repts w/o ref to rev researched Rev dates determined & attached to repts FARRAR, D L Communealth Edison Co 84/07/12 KEPPLER, J G Region 3, Office of Director 4pp 25949 264 24x Fiche 50-454,84/08/01.8408070204
- 8408090528 Notification or 840814 public meeting w/util in Bethesda, MD to discuss util response to integrated design insp rept CLSHAN, LN Licensing Branch i 84/08/02 YQUNOBLOOD, B J Licensing Branch i 4pp 25983 336 24X Fiche 50-454, 84/08/02, 84/08/08/08
- 8408070401 Informs that new sys of acknowledging receipt of licensee Correspondence re nonconpliance found during inspiristituted effective 840820 Preprinted form will be used rather than ltr

  KEPPLER, J G Region 3, Office of Director 84/08/03
  Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000,84/08/03,8408070401
- 8408200221 Forwards IE Insp Rept 50-454/84-37 on 840314-0713 No noncompliance noted SPESBARD,R L Region 3, Office of Director 84/08/03 REED,C Comnonwealth Edison Co 2pp 26137 142 R4X Fiche 50-454.84/08/03, 8408200221
- ---8408200227 IE Insp Rept 50-454/84-37 on 840514-0713 No noncompliance noted Major areas inspected as-built program & installation of electrical & instrumentation equipment to es-built drawings & review of hanger & conduit tray installation.

  MENDEZ.R. CHRISTNOT.E. WILLIAMS.C.C. Region 3, Office of Director 84/07/31 15pp 26137 144 24X Fiche 30-454,84/08/03,8408200221
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc. 122pp 26068 001 24X Fiche 50-000.84/08/06, 8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post \$30103) 84/08/06 Consolidated Edison Co. of New York, Inc 123pp 26067 138 24X Fiche 50-000.84/08/06.8408010337

- 840B130103 Ack receipt or 840B03 ltr informing NRC of steps taken to correct open items noted in IE Insp Repts 50-454/83-14. 50-455/83-12. 50-455/83-12. FAPERIELLD.C J Region 3. Office of Director 84/08/06 REED.C Commonwealth Edison Co. 1p. 26010-042 24% Fiche 50-454.84/08/06. 840B130103
- ---B40813010B Responds to ARC 840426 itr re open items noted in IE Insp. Repts 50-454/83-14, 50-455/83-12, 50-454/83-46 & 50-455/83-34 Revised page to Teledyne analytical procedures mahual encl. MEAVER, X T. Communication Co. B4/08/03 KEPPLER, J. G. Region 3, Defice of Director App. 26010 043 24X Fiche 50-454, 84/08/06, 8408130103
- 8408230245 Forwards 1E Insp Repts 50-454/84-38 & 50-455/84-33 on 840605-07:3 No noncompliance noted SPESSARD:R L Region 3. Office of Director 84/08/06 REED.C Commonwealth Edison Co Epp 26213 2/3 24X Fiche 50-454.84/08/06.
- --B408230252 IE Insp Repts 50-454/84-38 & 50-455/84-33 on 840605-0713 No noncompliance or deviations noted Major areas inspected action on previous insp findings, preoperational test procedures & results & surveillance tracking RING, Mr. DUNLOP.A. NILLIAMS, D. Region 3. Gffice of Director 84/07/28 ypp 26213 275 24X Fichs 50-454,84/08/06,8408230245
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York
- 84081403144 Confirms 840803 plans to meet w/util on 840707 in Olen Ellyn.IL to discuss regulatory improvement program NORELIUS, C E Region 3, Office of Director 84/08/08 REED, C Commonwealth Edison Co 2pp 86041 050 24x Fiche 50-000,84/08/08/8408140344
- B40B15009B Supple 840711 response to IE Bulletin 84-02 re visual insp during monthly functional tests to verify proper contact on reactor trip sys & prinary containment isolation sys relays Exemptions requested for listed relays ALEXANDER.G C Commonwealth Edison Co 84/08/08 KEPPLER.J G Region 3, Office of Director 3pp 26067 053 24X Fiche 50-000.84/08/08.8408150098
- 8408200331 Supple response to IE Bulletin 84-02 re failure of GE Type MFA relays Exemption requested from commitment for visual insp verifying proper relay contact during monthly functional check for listed relays ALEXANDER.G L Commonwealth Edison Co 84/08/08 KEPPLER.J G Region 3. Dffice of Director 3pp 26:32 318 24X Fiche 50-000.84/08/08/08/08
- B40B140227 Ack receipt of B40723 ltr informing NRC of steps taken to correct mencorpliance noted in IE Insp Repts 50-454/84-27 & 50-455/84-19

  SPEBSARD, R L. Region 3, Office of Director B4/08/09 REED, C Commonwealth Edison Co. ip 26055 310 24% Fiche 50-454, 84/08/09, 840B140229
- --8408140241 Supple response to NRC 840606 ltr re noncompliance noted in IE Insp Repts 50~494/84-27 & 50~495/84-19 Changes to Pages 5 & 6 of 840710 ltr re deficient hangers listed FARRAR.D L Commonwealth Edison Co 84/07/23 XEPPLER.J G Region 3. Diffice of Director 2pp 26095 311 24X Fiche 50~454.84/08/09.8408140229
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc list and GRACE.J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24% Fiche 50-000, 84/08/10, 8408070376
- 8408170039 Forwards IE insprept on 840611-0713 No noncompliance identified W/o encl SPESSARD, R. Region 3. Office of Director 84/08/10 REED, C. Commonwealth Edison Co. 2pp. 26119 083 24X Fiche 50-454,84/08/10.
- 8408270245 Forwards Insp Repts 50-454/84-53 & 50-455/84-36 on 840724-24 No noncompliance noted SPESSARD, R L Region 3, Office of Director 84/08/10 REED, C Commonwealth Edison Co 2pp 26258 101 24X Fiche 50-454,84/08/10,8408270245

- --840827027/ Insp Repts 50 454/64-50 \* 50-455/64-36 on 840724-26 No noncompliance noted Major areas inspected licensee action on proviously identified itsm If bulletins 5 10(FR50 55(e) items MENDET.R., CHMISINTI.E. BUILER D. Region 3. Office of Director 84/08/09 5pp 26258 103 24X Fiche 50-454,84/08/10.8408270245
- 8408100009 IE Into Notice 84 63, "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN,E L Division of Emergency Proparedness & Engineering
  Response (Past 833103) 84.08/13 Consolidated Edison Co of New
  York, Inc. 119pp 26197 218 244 Fiche 50-000,84/08/13,8408100009
- 8408220079 Documents schedule for submitting inservice insp (ISI) programs Commitment will be incurporated into FSAR in next amend ISI program will be submitted within 6 months after issuance of OLs

  TRAIM, 7 R Commonwealth Edison Co. 84/08/13 DENTON, H R. Office of Nuclear Reactor Regulation, Director 1p. 26193-251 24X

  Fiche 50-000,84/08/13-8408220079
- B40B240196 Notifies of 840715 potential date for first use of respiratory projective equipment for fuel load Program complete & ready for insp
  SHARTZ.E D Commonwealth Edison Co 84/08/14 KEPPLER.J G Region 3, Office of Director ip 26228 104 24% Fiche 50-454,84/08/14,8408240196
- 8408100021 IE Info Notice 84-45. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list enc!

  JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 
  04708/16 
  Consolidated Edison Co. of New York, Inc. 118pp 26198 001 
  24X Fiche 50-000,84/08/16.8409100021
- 8408280443 Forwards 640718 Off or Investigation (DI) Ropt 3-83-004, transmitted for placement in PDR DI reviewed document & made deletions to protect confidentiality & privacy Related correspondence
  LEMIS, B H Office of the Evecutive Legal Director DBB 337 84/08/16 CLEMENTS, W L Docketing & Services Branch 138pp 26280 347 24% Fiche 50-454, 84/08/16, 8408280443
- 8408100055 IE Info Notice 81-65. "Undetected Unavailability of Turbine-Driven Auxiliary Foodwater Train " Svc list and JORDAN,E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 001 24X Fiche 30-000.84/08/17,8408100055
- B40B14020B IC Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list enc! JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830107) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-46, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000.84/08/21.8408210142
- B40B230247 Board Notification 84-140 ferwards NRC 840B01 ack of response to Insp Repts 50-454/84-23 & 50-455/84-16 & util 840712 response to Insp repts NOVAK,1 M Assistant Director for Licensing 84/08/22 SMITH,I W, CALLIHAN,D. COLE,R F Atomic Safety and Licensing Board Panel 3pp 26261 307 24% Fiche 50-454,84/08/22,8408230247
- B40B2B0274 Submits clarifying info to 840703 ltr ro results of QC inspector reinsp program.per Insp Repts 50-454/82-05 & 50-455/82-04 Reinsps of equipment setting & equipment mod clarified DELOEDRGE.L O Commonwealth Edison Co 84/08/22 KEPPLR.J G Region 3. Office of Director 2pp 26274 325 24x Fiche 50-454.84/08/22.8408280274
- 8408300155 Forwards Attachnents 1.2.3.4 & 6 omitted from Board Notification 84-140 \* NRC - No Detailed Affiliation Given 84/08/22 NRC - No Detailed Affiliation Given 1p 26304 282 24X Fiche 50-454,84/08/22,8408300155
- 8 Reportable occurrences, LERs & related correspondence
- 8407310030 Board Notification 84-134 forwards JF Streeter 840711 memo to DG Eisenhut re stran generator snubbar testing failures
  Insp repts documenting results of testing & applicant recaluation efforts will be forwarded to Board NOVAK: I M Assistant Director for Licensing 84/07/27 SMITH, J W . CALLIHAN, D . CDLER F A tomic Safety and Licensing Board Panel 2pp 25936 033 24% Fiche 50-000,84/07/27,8407310030

- --8408040341 Discusses steam generator snubber tosting failures Shubbers made by Baeing Co Mendor Program Branch will be notified Results or testing 2 applicant reevaluation efforts will be documented in 16 insp repts STRECTLR JF Region 3, Orrice of Director 84/07/11 SISCNIVIT.D 6 Diritsion of Licensing ip 29936 035 24X Fiche 50-000 84/07/27,8407510030
- 840Bi30231 Interin Deficiency Repts 84-05 / 84-11 re unsatisfactory operation during qualification testing of steam generator snubbers supplied by Boeing Co Initially reported on 840628 Next rept expected by 840901 SWART/.C D. Commonwealth Edison Co. 84/07/31 KEPPLER.J Q. Region 3. Genically for the Supplication of S 8408130231

#### T Hearing transcripts on non-antitrust matters

- 8408020023 Transcript of 840727 hearing in Rockford, JL Vol II Pp 9,401-9,438 Supporting ducumentation encl \* Atomic Safety and Licensing Board Panel 84/07/27 280pp 25980 305 24% Fiche 50-454,04/07/27,8408020023
- 8408020135 Transcript of 840727 heating in Rockford, IL Vol I Pp 9,226-9,400 Supporting documentation encl \* Atomic Safety and Licensing Board Panel 84/07/27 249pp 25891 034 24\* Fiche 59-494.84/07/27,8408020135
- 8408010249 Forwards testimony filed during 840724 hearings in Rockford, LL W/o encis Related correspondence
  GAYLEY, J. Ishan, Lincoln \* Beater USB 660 84/07/30 Dock
  & Services Branch 1p 25835 340 24% Fiche 50~454,84/07/30,
  8408010249 Docketino
- 8408060133 Transcript of 840730 hearing in Rockford, IL Pp 9,439-9,674 Supporting documentation encl
  \* Atomic Safety and Licensing Board Panel 84/07/30 84pp
  25928 140 24% Fiche 50-454.84/07/30,8408060133
- 8408060198 Transcript of 840731 hearing in Rockford 1L Pp 9,675-9,915 \* Atomic Safety and Licensing Board Panel 84/07/31 242pp 25923 059 24x Fiche 50-145.84/07/31,8408060198
- 8408080043 Transcript of 840801 hearing in Rockford, IL Pp 9, 916-10, 145 8upporting documentation encl \* Atomic Safety and Licensing Board Panel 84/08/01 254pp 25962 154 24x Fiche 50-454, 84/08/01, 8408080043
- 8408080022 Transcript of 840802 hearing in Rockford, IL Pp 10, 146-10, 350 \* Atomic Safety and Licensing Board Panel 84/08/02 25948 046 24x Fiche 50-454,84/08/02,8408080022 360pp
- 8408100030 Forwards Pranscript of KD Ward 840621 deposition in Glen Ellyn, IL Related correspondence RILEY/A Taylog Associates DSB 890 84/08/07 PLEASANT, E Docketing & Services Branch 1p 25997 086 24v Fiche 50-454.84/08/07/8408100030
- --8408100040 Transcript of KD Ward 840621 deposition in Olen Ellyn, IL Related correspondence
  # Atomic Safety and Licensing Board Panel WARD.K D
  Commonwealth Edison Co 84/06/21 175pp 25997 087
  Fichs 50-434,84/08/07,8408100030
- 8408190119 Forwards surmary of testimony 9 testimony of NRC re equipment by Sys Control Corp. to be presented on 840820 Related correspondence MILCOVE.M N. Hearing Branch 2 DSB 046 84/08/13 SMITH.I W., CALLIHAN.A D., COLE.R F. Atomic Safety and Licensing Board Panel 2pp 26066 322 24K Fiche 50-454.84/08/13.8408150119
- --8408150127 Summary of testimony of NRC staff re equipment supplied to facility by Sys Control Corp Testimony discusses info acquired since Aug 1983 ra corrective actions & steps taken to establish adequacy Related correspondence # Office of the Executive Legal Director 84/08/13 2pp 26066 324 24X Fiche 50-454.84/08/13,8408150119
- --B408150132 Testimony of NRC re equipment supplied to facility by Sys Control Corp Related correspondence \* Office of the Executive Legal Director 84/08/13 22pp 26066 326 24% Fiche 50-454,84/08/13,8408150119
- 8408170319 Motion for leave to file testimony of WH Biguel on Contention i me reinsp program Related correspondence CASSEL,D W Devalb Area Alliance for Responsible Energy D 84/08/13 Atomic Safety and Licensing Board Pane! App 26114 317 P4x Fiche 50-454,84/08/13,8408170319 DSB 085

- --8408170321 Summary of testimony & testimony of WH Bleuel on Contention i re reinsp program Resume entl Related correspondence BLEUEL WH Afriliation Not Assigned 84/08/13 47pp 26114 321 24X Fiche 50-454,84/08/13,8408170319
- --8408170326 Summary Or testimony & testimony of EP Erickson on Contention I re reinsp program-inspector qualification & work quality Resume & Certificate of Svc enci Related correspondence ERICKSEN.E P Temple Univ , Philadelphia PA ERICKSEN.E P Businessaen for the Public Interest 84/08/13 33pp 2611: 24X Fiche 50-454,84/08/13,8408170319 26115 007
- 840B170278 Forwards corrected Pages 6.11 & 17 to EP Erickson testimony re reinsp program Related correspondence
  JUDSON, VA Businessmen for the Public Interest DSB 070
  84/08/14 SMITH.JW COLLE, F, CALLINAN, A D Atomic Safety and
  Licensing Board Panel 4pp 26115 124 24X Fiche 50-454,84/08/14.
- 8408170307 Bummary of testimon, % testimony of DS Kochhar on Contention i re reinsp program Certificate of Svc encl Related correspondence KOCHHAR, DS Michigan, Univ of, Ann Arbor, MI DSB 091 84/08/14 24pp 26115 040 24X Fichs 50-454.84/08/14,8408170307
- 8408170296 Direct testimony of CC Stokes re engineering evaluations performed & use of engineering judgement by Sargent & Lundy Suggests need for independent engineering analysis of safety significance of reinsp program Related correspondence STOKES, C C Affiliation Not Assigned DSS 084 84/09/16 36pp 26115 073 24X Fiche 50-434,84/08/16,8408170276
- 840B1703B0 Summary of testimony & direct testimony of CC Stokes on reinsp program Related correspondence STOVES, C C. STOMES, C C Businessmen for the Public Interest 100 B4/08/17 98pp 26128 260 24X Fiche 30-454.84/08/17
- 8408200446 Forwards transcript of CC Stokes 840817 deposition Related currespondence
  MESHMALL M Ann Riley & Associates DSB
  PLEASANT, E Docketing & Services Brench
  Fiche 50-454,84/08/20,840B200446 DSB 177 84/08/20 anch ip 26136 114 24X
- --8408200438 Transcript of CC Stokes 840817 deposition in Chicago. PL Pp 1-173 Vol II Related correspondence STOKES.C C Commonwealth Edison Co 84/08/17 175pp 26136 115 24% Fiche 50-454.84/08/20.8408200446
- 8408270023 Transcript of 840820 hearing in Rockford, IL Pp 10,351-10,458 10.455 \* Atomic Safety and Licensing Board Panel 84/08/20 108pp 26#47 195 24X Fiche 50-454,84/08/20,8408270023
- B40B270025 Transcript of hearing in Rockford IL Pp 10.459-10.692 \* Atomic Bafety and Licensing Board Panel 84/08/21 264pp 26246 093 24X Fiche 50-454.84/08/21.8408270025
- 8408280228 Transcript of 840822 hearing in Rockford. IL Pp 10.683-10.931 Supporting documentation encl \* Atomic Safety and Licensing Board Panel 84/08/22 396pp 26263 001 24% Fiche 50-454.84/08/22.8408280328
- 8408280153 Transcript of 840823 hearing in Rockford, IL # Atomic Safety and Licensing Board Panel 84/0 26270 001 24X Fiche 50-454.81/08/23,8408280153 84/09/23 263so
- 8408280138 Transcript of 840824 hearing in Rockford, IL Pp 11,140-# Atomic Safety and Licensing Board Panel 84/08/24 124pp 26257 088 24% Fiche 50-454,84/08/24,8408280138
- 8408310192 Robuttal testimony of 8 Erier re Stokes allegations concerning evaluations of discrepancies in calculated actual stress performed by Sargent & Lundy Related correspondence ERLER, 8 Sargent & Lundy, Inc. DSB 387 84/08/30 10pp 26319 043 24x Fiche 50-454,84/08/30,8408310192
- ---840B3[0194 Summary of rebuttal testimony & testimony of ML Somsag. EB Branch.D DeMoss.MR Frankel.DF Maurer & JK Buchanan re plant GC Inspector reinsp program & C Stokes allegations re pients to inspector reints program & C Stokes alleguelds Related correspondence
  BRANCH.E B. DEMOSS.D M Sargent & Lundy. Inc. f
  College of New York 84/08/30 B3pp 24319 053
  Fiche 50-454, 84/08/30, 8408310192 FRANKEL, M.R. City

--8408310199 Rebuttal testimony of RW Hooks re validity of info in Attachment 7 to Stokes testimony concerning design assumption for plant Stokes (info inapplicable to plant Related correspondence HOOKS, R W Sargent & Lundy Inc 84/08/30 5pp 26319 136 24% Fiche 50-454,84/08/30,8408310192

#### V Operator Examinations

- 8408140372 Forwards proposed rev to "Requalification Program for NOSIANOZZ FORWATOS PROPOSEO FEY to "Requalification Program Fol Litensed Operators Senior Operators 5 Senior Operators (Limited)," in response to NUREG-0737, Item I A 3 1 MARSHALL, J G Commonwealth Edison Co 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26051 2 24X Fiche 50-000, 84/08/07, 8408140372
- --8408140389 "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited) "

  \* Commonwealth Edison Co 84/07/19 10pp 26051 242 24X Fiche 50-000, 84/08/07, 8408140372
- 8408140426 Provides address for transmitting all operator licensing correspondence to Région III ofc.except info for examiners HALFER, R.D. Region 3, Office of Director 84708/10 Michigan. Univ of. Ann Arbur. MI 2pp 26051

DOCKET STN-50-455 BYRON STATION, UNIT 2

A Application/construction stage documents & correspondence

- B40Bi30409 Forwards for review & comment, marked-up preliminary test procedure re functional & spring rate testing of steam generator snubbers in response to 840030B concerns in IE Insp Repts 50-454/84-08 & 50-455/84-06 SWARTZ.ED Commonwealth Edison Co 84/04/26 KEPPLER, J G Reg 3, Office of Director 23pp 26010 192 24X Fiche 50-454.84/04/840Bi30409 Region 24X Fiche 50-454, 84/04/26
- 9408010116 Forwards request for addl info re Tech Specs on relief valves & ESF response time Response requested within 7 days of itr date YOUNGELOOD, B J Licensing Branch 1 84/07/19 FARRAR, D L Commanuealth Edison Co 7pp 25873 327 24X Fiche 50-454,84/07/19.
- 8408060136 Forwards response to 840719 request for add1 info re Tech Specs Complete package of comments & suggestions to Section 3/4 8 of proof & review version of Unit 1 Tech Specs also
- SMARTZ, E D Commonwealth Edison Co 84/07/26 DENTON, H R Of of Nuclear Reactor Regulation, Director 65pp 25934 013 24% Ficho 50-454,84/07/26,8408060136
- 8408140380 Forwards responses to FSAR Questions 10 57.10 63.10 64. 10 65 & 10 66 Revised response to Question 10 57 based on revised safe shutdown analysis Info will be included in next FSAR amend

  SWART/, E D Commonwealth Edison Co B4/08/02 DENTON, H R Of

  of Nuclear Reactor Regulation. Director 32pp 26041 132 24X

  Fiche 50-000,84/08/02.8408140380 Medice
- B40B070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of SUppl 1 to NUMEO-0933. "Prioritization of Generic Safety Issues " Svc list encl EISENHUT,D 6 Division of Licensing B4/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 23B 24X Fiche 50-000-84/08/06-8408070110
- 8408160345 Advises that QA program applicable to all nuclear generating stations & satisfies provisions of 10CFR71 Fee remitted per 10CFR170 31 FARRAR.D L. Commonwealth Edison Co. 84/08/06 Office of Nuclear Material Safety & Safeguards, Director 1p. 26092 184 24X fiche 30-000.84/08/06.8408160345
- 8408i60415 Advises that main hook & lower load block on fuel handling bldg crame will be temporarily replaced to meet requirement of replacing Unit 1 reactor coolant pump motor assembly, per B30426 commitment ALEXANDER, G. Commonuealth Edison Co. 84/08/07 DENTON, H.R. of Nuclear Reactor Regulation, Director 2pp 26085 358 24X Fiche 50-454,84/08/07,8408160415
- 8408220239 Discusses post-accident sampling sys being installed to address NRC requirements in NUREG-0737. Item II B 3 High radiation sampling sys described in FSAR will be operational on each unit prior to initial criticality THAMM.T R Commonwealth Edison Co 84/08/13 DENTON, H R Offiof Nuclear Reactor Regulation. Director 1p 26193137 24X Fiche 50-000:84/08/13:8408220239 Office

- B408220368 Supple 031216 comments to proof 3 review Tech Specs Refs to three loop operation during Modes 1-4 should be removed due to lack of Westinghouse analysms
  SWARTZ.E D Commonwealth Edison Co 64/08/19 DENTON, H.R. Office of Nuclear Reactor Regulation Director [p 26191 346 24X Fiche 50-454,84/08/15,8408220348
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors by applicants for DLs re-scheduling quidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl. EISENHUT.D G. Division of Licensing 84/08/20 Consolidated Edison Co of New York. Inc. 17pp. 26276-244 24X Ficha 50-000.84/08'20.84082002'5
- 8408270118 Submits addl into re basis for proposed Tech Spec requirements on availability of Diesel Generator 2A during time Unit 2 under const TRAMH.T R Commonusalth Edison Co 84/08/21 DENTON.H R of Nuclear Reactor Regulation. Director 2pp 26247 338 Fiche 30~000.84/08/21.8498270118 DENTON, H. R. Office
- 8408310163 Provides add1 info to support proposed Tech Spec changes re diesel oil sampling containment pressure Hi-1 & detector plateau curves, per NRC/util 840813-16 meetings TRAMM. T R Commonuealth Edison Co 84/08/23 DENTON, H R Defice of Nuclear Reactor Regulation, Director 3pp 26319 173 24X Fiche 50-454.84/08/23,8408310163
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- BAOSO10185 Forwards request for addl into for review of vol reduction sys (Dutstanding Item 15 of Byron SER) Response requested within 30 days of itr date ULSHAN,L N Licensing Branch 1 B4/07/19 FARRAR,D L. Commonwealth Edison Co 10pp 25873 292 24X Fiche 50-000, 84/07/19,8408010185
- 8408270265 Forwards add1 documentation re-preliminary site work fill placement & composition in Area of Concern 12 Info should close SER Outstanding Item 1 Test results encl TRAMM.TR Commonwealth Edison Co 84/08/10 DENTON,HR Office of Nuclear Reactor Regulation. Director Spp 26240-202 24X Fiche 50-454.84/08/10.8408270265 Office
- --8408270274 "Field Density Test Results "
  NELBON, R E H H Holnes Testing Laboratories, Inc 20
  1p 26240 207 24% Fiche 50-454.84/08/10,8408270265 75/05/30
- --B408270284 "Rept of Field Compaction Tests " HOLMES.H R H H Holmes Testing Laboratories, Inc. 3 ip 26240 208 24% Fiche 50-454.84/08/10,8408270265 75/04/20
- 75/07/22
- --8408270294 "Rept of Field Compaction Tests"

  HOLMES.H H H H Holmes Testing Laboratories. Inc 97
  4pp 26240 211 24% Fiche 50-454,84/08/10:8408270265 75/08/11
- B408270204 forwards add1 info re monitoring of leakage from system outside containment used to transport highly radioactive fluid & gases in post-accident condition Info should close SER Confirmatory Issue 28(a) TRAMM, T.R. Commonwealth Edison Co. 194/08/11 DENTON, H.R. (of Nuclear Reactor Regulation, Director 7pp. 26245-103 2/Fiche 50-000.84/08/11.8408270204
- B40B220306 Folwards propiletary 3 nonproprietary responses to NRC ltr re improved thermal design procedure Response should close Byron SER Outstanding Item & Info deleted Proprietary response withheld cref 10CFR2 790)
  TRAMM.1 R Commonwealth Edison Co 84/08/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 20pp 26193 053 24X Fiche 50-000,84/08/13,8408220306
- --B408220321 Requests withholding proprietary response to NRC questions nequests withholding proprietary response to NRC question on improved thermal design procedures & rod bow.per 100FR2 790 Affidavit AM-76-60 encl WIESEMANN.R A Westinghouse Electric Corp 83/12/27 DENTON.H I Office of Nuclear Reactor Regulation. Director ADENSAM.E 0 Licensing Branch 4 8pp 24173 073 24x Fiche 50-000.84/08/13,8408220306

- 8408270J/3 Forwards addl info is institumentation being installed for detection of inadequate cure cooling info should close SER dutstanding Item 9 u/o any license conditions TRAMM I 8 Componealth Edison to 64/08/20 DENION, H.R. Office of Nuclear Reactic Regulation, Director 4pp 26240-254 24X Fiche 50-000-84/08/29 8498270373
- 8408310226 Forwards addl info to volteduction systin response to 840/10 request NPC review of info necessary to close SER Outstanding It.s. 15
  TRAMM.T R Componwealth Edison Co 84/08 24 DENION.H R Defice of Nuclear Reactor Regulation. Director 27pp 26322 138 24X
  Fiche 50-000.84/08/24.8408310226
- F Security, medical, emergency & fire protection plans
- B40B150386 Forwards IE Insp Repts 50-454/84-46 & 50-455/84-31 on 840711-13 No noncompliance noted PAPER[ELLO, C. J. Pegion 3. Office of Director 84/07/27 REED.C Commonwealth Edison Co. 24p. 26077 357 24% Fiche 50-454,84/07/27, pages 148-324.
- --8408150394 IE Insp Rep's 50-454/84-46 & 50-455/84-31 on 840711-13 No noncompliance or deviations identified Major areas inspected selected open & improvement items identified during emergency preparedness implementation appraisal PLOSKI.T J , PHILLIPS M P Region 3. Office of Director 84/07/27 Spp 26977 359 24X Fiche 50-454,84/07/27,8408150386
- 8408220243 Summary or 840731 meeting w/util in Silver Spring.MD resecutity plan implementation

  \* NRC No Detailed Affiliation Given 84/07/31 NRC No Detailed Affiliation Civen 200 311 24X
  Fiche 50-000.84/07/31.8408220243
- 8408080198 Forwards Amend 4 to "Fire Protection Rept." including detailed comparison of design, const. tosting & maint practices against NFPA stds SWARTZ, C.D. Commonwealth Edison Co. 84/08/02 DENTON.H R. Office of Nuclear Reartor Regulation. Director Spp. 25985-001 24X Fiche 50-000.84/08/02.8408080198
- --8408080205 Amena + to Fire Protection Rept "
  \* Commonwealth Edison Co 84/07/31 125pp 25985 004 24X
  Fiche 50-000,84/08/02,8408080198
- 8408140234 Revised energency plan implementing procedures including BZP 100-T2. "Operations Director-Checklist." BZP 100-T3. "Technical Director-Checklist." B BZP 100 T4. "Malint Director-Checklist." W/transmittal & receipt form & Commonwealth Edison Co. 84/08/03 252pp 26056 077 24X Fiche 30-134.84/08/03.8408140231
- 8408130401 Responds to 840705 clarification of info re util means of satisfying annual regulatory requirement to review emergency action levels w/offsite emergency support organizations Info acceptable PAPERIELLO.C J. Region 3. Office of Director 84/08/07 REED.C Commonwealth Edison Co. ip 26010 130 24% Fithe 50-000,84/08/07.8408130401
- --B408130413 Responds to B40604 ltm re means for satisfying requirements of LOCFR50.App E.Paragraph IV B Proposal for satisfying requirements to review emergency action levels by offsite agencies clarified FARRAR.D L Commonwealth Edison Co 84/07/05 PAPERIELLO.C J Region 3, Office of Director Bpp 26010 131 24x Ficha 50-000.84/08/07.8408130401
- 8408240139 Rev 1 to Emergency Plan Implementing Procedure BZP 500-T7, "Checklist Operational Support Ctr " W/840817 transmittal for: \* Commonwealth Edison Co 84/08/15 6pp 26228 168 24X Fiche 50-454,84/08/15,8408240139
- 8408220106 Forwards evacuation time estimates incorporating changes re employment ctr shutdown times, per ASLB 840113 initial decision Review of add1 info should obviate need for license conditions
  TRANM.TR Commonwealth Edison Co 84/08/16 DENTON.HR Office of Nuclear Reactor Regulation, Director 1p 26191 194 24X
  Fiche 50-454.84/08/16.8408220106
- --8408220112 "Evacuation Time Estimates Within Plume Exposure Pathway Emergency Planning Zone for Byron Nuclear Generating Station "

- 8408240173 Rev 1 to Procedure BZP 380+A3, "Locations of Fixed Environ Radiological Monitoring Station Air Samplers " H/840907 transmittal memo \* Commonwealth Edison Co 84/08/17 3pp 26228 165 24X Fiche 50-454-84/08/17.8438240173
- B40B27021B Forwards advanced revs to fire protection rept included in Amend 5 % add1 info re other fire protection issues for station Resumes of fire protection engineers involved in program will be included in Amend 5 TRAPM. I R Commonwealth Edison Co 84/08/20 DENTON. H R Office of Nuclear Reactor Regulation. Director 35pp 26245 110 24X Fiche 50-494.84/08/20.8408270218
- G Adjudicatory correspondence
- 8405250241 First set of interrogatories to intervenors, requesting list of witnesses to be presented on intervenors behalf at reopened hearings & summary of testimony Certificate of Svc encl Related correspondence
  BECKER.B D Commonwealth Edison Co BECKER.B D Isham, Lincoln & Beale DSB 311 84/05/18 3pp 24656 202 24x
  Fiche 50-454.84/05/18.8405250241
- 8406260276 Submits partial response to 840619 ltr Transparent effort not being made to stall proceeding Method of responding to discovery request prohibits orderly discovery of case Certificate of Svc encl Related correspondence WHICHER, J M Businessmen for the Public Interest WHICHER, J M Whicher, J M DSB 862 84/06/20 MILLER, M I Isham, Lincoln & Beals MILLER, M I Commonwealth Edison Co 3pp 25150 04( 24x Fiche 50-454,84/06/20,8404260276
- 8408010177 Notice of appearance in proceeding Certificate of Svc encl LEARNER, H A League of Homen Voters of Rockford, IL LEARNER, H A Dekalb Area Alliance for Responsible Energy LEARNER, H A Binnissippi Alliance for the Environment (SAFE) DEB 669 84/07/24 4pp 25855 322 24% Fiche 50-454,84/07/24,8408010177
- 8408070463 Order extending time until 840810 for Commission to act to review ALAB-770 Served on 840804 CHILK.8 J. Office of the Secretary of the Commission 1888 753 84/08/03 Commissioners ip 25940 331 24X Fiche 50-454.84/08/03.8408070463
- 8408080390 Request for supply to will amended responses to Interrogatories 11 & 12 Certificate of Svc encl Related correspondence
  JUDSON, V A DeKalb Area Alliance for Responsible Energy
  JUDSON, V A Simissippi Alliance for the Environment (SAFE)
  JUDSON, V A League of Homen Voters of Rockford, IL D88 840
  84/08/06 Atomic Safety and Licensing Board Panel 4pp
  25973 284 24% Fiche 30-454,84/08/06,8408080390
- B408080395 Forwards request for suppls to util amended responses to Interrogatories 11 & 12 of intervenor first set of interrogatories W/o enc! Related correspondence JUDSON.V A Businessmen for the Public Interest DSB B41 84/08/06 MILLER.M I Isham, Lincoln & Beale 2pp 25974 101 24% Fiche 50-454.84/08/06.8400800393
- 8408090164 Forwards 840521 deposition of KD Ward W/o encl Related correspondence WILCOVE.N N Hearing Branch 2 DSB 870 84/08/07 WESTHALL.M Taylog Associates Ip 23973 128 24X Fiche 50-454,84/08/07,8408090164
- 8408130279 Forwards six documents for proposed inclusion w/board motification Documents include RL Spessard 840723 itr to C Reed W/o encl Related correspondence LEWIB:8 H Hearing Branch 2 DSB 908 84/08/08 DL8HAN, L N Li
- 8408270303 Expresses concern % opposition to licensing of plant ASLB should listen to concern of workers Facilities not needed & being put on line for convenience & profit of util SCHRABER, D Affiliation Not Assigned D88 372 84/08/07 SMITH, I Atomic Safety and Licensing Board Panel 2pp 26287 360 24X Fiche 30-454,84/08/07.8408270303
- 8408290308 Requests NRC review of outstanding items relicensing of plant PETERSON.T Affiliation Not Assigned DSB 365 84/08/ii SMITH Atomic Safety and Licensing Board Panel 1p 26289 362 24X Fiche 50-454,84/08/ii.8408290308

- 8408140454 Informs that Commission declined to review ALAB-770 Time within which Commission may act to review has expired to decision became final agency action on 840810 Served on 840813
- B40B170982 Forwards corrections A attachments to CC Stoyes unittentestimony W/o encis Related correspondence WRIGHT, T W Businesamen for the Public Interest DBB 101 B4/0B/15 SMITH, T W COLE, R F . CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 26128 259 24% Fiche 50-454, 84/0B/15, BAORITORE?
- 8408270310 Expresses concern that plant will go on line before proven safe Performance of NRC has caused purplement & disappointment NRC supports will position even in face of serious allegations he plant safety
  PEWBLE. J A Affiliation Not Assigned DSB 366 84/08/15
  SMITH. W Atonic Safety and Licensing Board Panel 2pp
  26289 355 24X Fiche 50-454,84/08/15,8408290310
- B40B210336 Memorandum opposing intervenor B40B13 motion for leave to file testimony of tH Blauel Bleuel qualifications not of expert caliber to assist ASLB Related correspondence MILLER, M Commonwealth Edison Co MILLER, M Isham, Lincoln & Beale DSB 182 84/0B/16 Atomic Safety and Licensing Board Panet 8pp 26179 342 24x Fiche 50-454, B4/0B/16, 840B210336
- --8408210344 Affidavit of OT Klopp re WH Blevel proposed testimony concerning need for failure nodes \* effects analysis Centificate of Svc & svc list encl Related correspondence KLOPP.O T Commonwealth Edison Co 84/08/16 Bpp 26179 350 24X Fiche 50-454.84/08/16.8408210336
- 8408280443 Forwards 840718 Ofc or Investigation (OI) Rept 3-83-006transmitted for placement in PDR OI leviewed document 5 made deletions to protect confidentiality 5 privacy Related correspondence LEWIS,8 H Office of the Exerctive Legal Director DSB 337 84/08/16 CLEMENTS:W L Docketing 5 Services Branch 138pp 26280 347 24x Fiche 50-434,84/08/16,8408280443
- 8408290307 Expresses Concern re licensing of plant & 6,000 discrepancies in bldg of plant labeled nonsignificant Review of NRC outstanding items requested GRUMLEY. JE Affiliation Not Assigned DSB 364 84/08/16 SMITH, I W Atomic 9afety and Licensing Board Panel ip 26290 341 24X Fiche 50-454.84/08/16.8408290307
- 1408270313 Expresses concern re licensing of plant ASLB should listen to concerns of workers wishing to testify Facilities not needed & being put on line for convenience of util STILES, J M Hount Morris Times. Mount Morris, IL DSB 368 B4/08/16 SMITH Atomic Safety and Licensing Board Panel ip 26270 336 24X Fiche 50-454,84/08/16,8408270313
- 8408270275 Expresses concerns to safety of facility & citizens paying for util miscalculation DANIELSEN,D C Affiliation Not Assigned DSS 370 84/08/17 SMITH, I W Atonic Safety and Licensing Board Panel ip 26290 357 24X Fiche 50-454,84/08/17,84082902/5
- 8408270163 Motion to exclude portions of prefiled testimony of CC Stokes, filed on 849816 Related correspondence GALLO, J Commonwealth Edison Co GALLO, J Isham, Lincoln & Beale DSB 286 84/09/19 Atomic Safety and Licensing Board Panel 9p 26245 263 24X Fiche 50-454,84/08/19,8408270163
- --9408270172 Affidavit of KT Kostal re prefiled testimony of C Stokes Certificate of Svt enci Related currespondence KQSTAL.K T Commonwealth Edison Co KCSTAL.K T Sargent & Lundy, Inc. 84/08/18 Atonic Safety and Licensing Board Panel Spp 26245 272 24X Fiche 50-454,84/08/19,8408270163
- 8408290303 Questions sanity & political persuasion of members of Sinnissippi Alliance for opposing start up of facilities Delays cost millions Urges startup
  LIGHTCAP,J R Affiliation Not Assigned DSB 371 84/08/20
  SMITH, I Atomic Bafety and Licensing Board Panel 2pp 26290 339
  24X Fiche 50-454,84/08/20,8408290305
- B408290328 Expresses toncern relicensing of plant Urges NRC to review outstanding points of contention about safety 2 make sure reinspleyidence not merely testimony convincing of safety EMMETT. J. Affiliation Not Assigned DSD 373 B4/08/20 SMITH Atonic Safety and Licensing Board Panel 2pp 26289 347 24X Fiche 50-454,84/08/20,8408290328

- B408290407 Commends IW Shith this decision to withhold licensing of plant until safety issues resolved Open discussion re-addl safety concerns requested HOLMBERG, J. Illinois State or DSB 367 84/08/22 SMITH, I.W. Atomic Safety and Licensing Roard Panel 1p 26290-360 24X Fiche 50-454,84/08/22,8408/90309
- 8408290281 Expresses concerns to licensing \* opening of plant In Jan 1994, when util was denied license, ruling considered final NRC issuance of license to plant so obviously defective as \*o be beyond belief PDZDULEWI.A Affiliation Not A.signed DSB 3/4 84/08/28 SMITH.I Atomic Sarety and Licensing Board Panel App 26270 327 24X Fiche 50-434 84/08/28,8408290281
- 840B310201 Notice of withdrawal of appearance in proceeding Related correspondence WHICHER, M Businessnen for the Public Interest DSB 421 84/08/28 SMITH I W COLE R F . CALLIHAN A D Atomic Bafety and Licensing Board Panel ip 26318 31; 24% Fiche 50-454,84/08/28,840B310201
- H Ceneral correspondence
- 8405180145 Responds to 847314 ltr to Chairman Palladino which encl W & V Shelser concern re Narble Hill & Bailly cancellation, withdrawal of util application for Zimmer & denial of license for Byron facility DIRCES.N J Office of the Executive Director for Operations 84/05/04 LUGAR.R G Senate 7pp 24524 325 24% Fiche 50-000.84/05/04.8105180145
- --8409180152 Requests response to encl W.P. V Smelser 840210 inquiry into NRC attitude toward utils Concerns include Maible Hill & Bailly cancellation.uthdrawal of util application for Zimmer & denial of license for Byron facility LUGAR, R.O. Sonate 84/03/14 PALLADIND.N. Commissioners 3pp 24524 331 24x Fiche 30-000.84/05/04.8405180145
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8408300033 Forwards arridavit attesting to distribution of FSAR Amends 44 & 45 TRAMM,T R Commonwealth Edison Cu 84/08/16 DENIGN,H R Office of Nuclear Reactor Regulation, Director 2pp 2630/234 24X Fiche 50-000,84/08/16,8408300053
- Q Inspection reports: IE Bulletins & correspondence
- B40B130415 Forwards for review.Rev 1 to "Evaluation of Energy Absorbing Mat; for Pipe Whip Restraints," in response to IE Insp. Repts 50-454/83-06 & 50-455/83-06

  SMARTZ.E D Commonwealth Edison Co 84/04/13 KEPPLER.J 0 Region 3. Office of Directol Ppp 26011 038 P4Y Fiche 50-000.84/04/13.840B130415
- --B408130420 Rev 1 to "Evaluation of Frengy Absorbing Mat1 for Pipe Whip Restraints " KAO, Q C , YANG, N S , Sy. T Y Sargent # Lundy. Inc SAD-431 R01 B4/04/30 47pp 24011 040 24< Fiche 50-000,84/04/13,8408130415
- B408130409 Forwards for review 5 commont, marked-up preliminary test procedure re functional 5 spring rate testing of steam generator snubbers in resconse to 840308 concerns in IE Insp. Repts 30-454/84-08 & 50-455/84-06 SWARTZ.E D Commonwealth Edison Co. 84/04/26 KEPPLER.J G Region 3, Office of Director 23pp 26010 192 24X Fiche 50-454.84/04/26, 8408130409
- B40B010732 Forwards IE lnsp Rept, 50-494/84-33,50-455/84-26 & 30-17034/84-01 on 840521-29,79-31 % 0601 % 05-06 No noncompliance noted PAFERIELLO.C J Region 3, Office of Director B4/07/10 REED.C Commonwealth Edison Co 2pp 25866 077 24X Fiche 50-454,84/07/10,8408010332
- --8408010341 IE Insp Repts 90-454/84-33, 90-455/84-24 / 30-17034/84-01 on 840521-23, 29-31 & 0601 & 05-06 No honcompliance noted Major areas inspected preoperational radiation protection program & status of preoperational sys demonstrations HUCTER.L J., OILL.C F., ORCOER L R. Region 3, Office of Director 84/07/10 20pp 25865 079 24X Fiche 50-454,84/07/10,8408010332

- --8408080195 IE Insp Repts 50 154/61-25.50 455/84-18.50-456/84-11 & 50-457.84-11 on 840425 \* 05/2-23 No noncompliance noted Major areas inspected design calculations re-primary shield wall \* reactor pressure shield wall MUFFLTY.J W. RAUFFAN.F D. NORTON J.F. Region 3. Office of Director 84/07/18 4pp 25974 3/9 24X Fiche 50-000.84/07/18.8400480188
- 8408090212 Forwards [E Insp Repts 50-454/84-29 % 50-455/84-21 on 840514-0710 No noncompliance identified SPESSARD, R L. Region 3, Office of Director 84/07/23 REED, C Commonwealth Edison Co. 2pp. 25994 165 24X Fiche 50~454,84/07/23, again 90.01.2
- --8408090217 IE Insp Repts 50-454/84-F9 \* 50-455/84-21 on 840514-0710 No noncompliance identified Mijol orcas inspected licensee action on 100FR50 55(e) item re-hult splices in electrical conductors CHRISTNOT.E F . MENDEZ.R . HILLIAMS C C Region 3. Office of Director 84/07/23 App 25974 16/ 247 Fiche 50-454.84/07/23. 8408090212
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list cncl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc. 119pp 25855-047 24% Fiche 50-000,84/07/27,8407250229
- B40731003P Board Notification 84-135 forwards SALP Repts 50-454/84-22 & 50-459/84-15 for Jan 1983 Apr 1984 Any util comments on rept will be forwarded for review NOVAK.T M Assistant Director for Licensing 84/07/27 SMITH.I W., CALLIHAN, D. Atomic Safety and Licensing Board Panel ROSENTHAL, A S. Atomic Safety and Licensing Appeal Panel 25926-334 24X Fiche 50-454,84/07/27.8407310032
- 8408190384 Forwards IE Insp Repts 50-454/84-46 & 50-455/84-31 on 840711-13 No noncompliance noted PAPERICLLO.C J Region 3. Office of Director 84/07/27 REED.C Commonwealth Edison Co. 2pp. 26077 357 24X Fiche 50-454,84/07/27,8408150784
- --8408150:394 IE Insp Reats 30-454/84-46 & 50-495/84-31 on 840711-13 No noncompliance or deviations identified Major areas inspected selected apen & improvement items identified during emorgency preparedness implementation appraisal PLOSKI, T J. CHRISTOFFER, G. SMITH M J. Region 3, Office of Director 84/07/27 5pp 26077 359 24X Fichs 50-454,84/07/27,8408150386
- 8408070213 Forwards (F Insp Repts 50-454/81-32 & 50-459/84-25 on 840424-0717 / natice of violation STRETER. J F Region 3. Office of Director 84/07/30 REED. C Cammondealth Edison Co. 2pp. 25748 337 24X Fiche 50-454.84/07/30.8408070213
- --84080/0216 Notice of violation from insp on 840426-0717 STREETER, J. F. Region 3, Office of Director 84/0//30 3pp 25948 339 24% Fiche 50-454,84/07/30.8408070213
- --8408070221 IC Insp Repts 50-454/84-32 & 50-455/84-25 on 840426-0717 Noncompliance noted failure to document nonconforming conditions, failure to control nonconforming items & failure to take efficiive corrective actions re weld problems MAYES, D W. COMMAUCHTON, K. STREETER, J F. Region 3, Office of Director 84/07/30 | 11pp | 25948 342 | 24X Fiche 50-454,84/07/30,8408070213
- B40B070204 Ark scelpt or B10712 ltt informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/84-23 & 50-455/84-16 SPESSARD.R L. Region 3, Office of Director 84/08/01 REED.C Commonwealth Edison Co. 2pp 25947 262 24X Fiche 50-454,84/08/01,84080/0204
- --8408070212 Responds to NRC 840512 ltr reviolations noted in TE Insp Repts 50-454/84-23 & 50 455/84-16 Corrective actions 60 equipment installation repts w/o ref to rev researched Rev dates determined & attached to repts FARRAR. D L Commonwealth Edison Co 84/07/12 KEPPLER. J G Region 3, Office of Director 4pp 25949 264 24X Fiche 50-454.84.08/01.8408070204
- 8408090928 Notification of 840814 public meeting w/util in Bethesda.MD to discuss util response to integrated design inspirept OLSHANL N Licensing Branch 1 84/08/02 YDUNGBLOOD.B J Licensing Branch 1 4pp 25983 336 24% Fiche 50-454.84/08/02.8408090528

- 8408076401 Informs that new sym of acknowledging receipt of licensee correspondence re noncompliance found during inspiristituted effective 840820 Preprinted form will be used mather than lit MEPPLER, J. G. Region 3. Office of Director 84/08/03 Commonwealth Edison Co. 3pp. 25742 188 24% Fiche 50-000, 84/08/03, 8408070401
- 8408310333 IE Info Notice 84-59, 'Deliberate Circumventing of Station Health Physics Procedures Svc list encl JORDAN, E. D. 111500 of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co or New York, Inc. 122pp 26068 001 24% Fiche 50-000.84/08/06.8408010333
- B40B010337 IE Info Notice B1-60. 'Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement 'Syc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 26067 158 24X Fichs 50-000.84/08/06.8408010337
- 8408130103 Ack receipt of 840803 ltr informing NRC of steps taken to correct open items noted in IE Insp Repts 50-454/83-14, 50-455/83-12, 50-454/83-45 & 50-455/83-34 PAPERIELLO, C. J. Region 3, Office of Director 84/08/06 REED, C. Componwealth Edison Co. 1p 26010 042 24X Fiche 50-454, 84/08/06, 8408130103
- --B408130108 Responds to NRC B40426 ltr re open items noted in 1E insp. Repts 50-454/83-14.50-455/83-12.50-454/83-46 t 50-455/83-34 Revised page to Teledyne analytical procedures manual encl. MEAVER, K T Commonwealth Edison Co B4/08/03 KEPPLER, J G Region 3. Office of Director 4pp 26010 043 24X Fiche 50-454,84/08/06,8408130103
- B40B230245 Forwards 1E Insp Repts 50-454/B4-38 & 30-455/B4-33 on B40605-0713 No noncompliance noted SPESSARD, R L Region 3. Dffice of Director B4/08/06 REED.C Commonwealth Edison Co 2pp 26213 273 24X Fiche 50-454.84/08/06, B40B230245
- --B408230252 IE Insp Repts 50-454/84-3B & 50-455/84-33 on B40605-0713 No noncompliance or deviations noted Major areas inspected action on previous imsp findings.preoporational test procedures & results & surveillance tracking RING.M. DUNLOP.A. WILLIAMS,D Region 3, Office of Director 84/07/28 9pp 26213 275 24X Fiche 50-454.84/08/06.8408230245
- B40B070120 IE Info Notice 84-61, "Decresposure of Diver in PWR Refueling Cavity " Syc list end JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York, Inc. 120pp 26129 11B 247 Fiche 50-000.84/08/08.8408070120
- ## 8408140744 Confirms 840803 plans to meet w/util on 840907 in Olen Ellyn.1L to discuss regulatory improvement program NORELIUS.C C. Region 20, Office of Director 94/08/08 REED.C. Componwealth Edison Co. 2pp 26041 050 24X Fiche 50-000, 84/08/08. ### 8408140344
- 8408150098 Supple 840711 response to RE Bulletin 84-02 re visual insp during monthly functional tests to verify proper contact on reactor trip sys 2 primary containment isolation sys relays Exemptions requested for listed relays ALEXANDER C L Commonwealth Edison Co 84/08/08 KEPPLER, J G Region 3, Office of Director 3pp 26067 053 24X Fiche 50-000.84/08/08.8408150098
- B40B20033; Supple response to IE Bulletin B4-02 re failure of GE Type MFA relays Exemption requested from commitment for visual insp verifying proper relay contact during monthly functional check for listed relays ALEXMIDER. G L Commonwealth Edison Co 84/08/08 KEPPLER. J G Region 3. Office of Director 3pp 26/32 318 24X Fichs 50-000.84/08/08.8408200331
- 840B140229 Ack receipt of 840723 itr informing NRC of steps taken to correct noncompliance noted in IE Insp Repts 50-454/84-27 & 50-455/84-19 SPESBARD, R L Region 3. Office of Director 84/08/09 REED, C Commonwealth Edison Co ip 26055 310 24X Fiche 50-454,84/08/09,8408140229
- --8408140241 Suppls response to NRC 840606 ltr re noncompliance noted in IE Insp Repts 50-454/84-27 & 50-455/84-19 Changes to Pages 5 & 6 of 840710 ltr re deficient hangers listed FARRAR D L Commonwealth Edison Co 84/07/23 PIPPLER J Q Region 3, Office of Director 2pp 26055 311 24X Fichs 50-454,64/08/09,8408140229

- 8408070376 IE Info Notice 84-62, 'Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments "Svc list encl
  - 11st enci GRACE, J.N. Division of QA, Safeguards ! Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co. of New York, Inc. 125pp 26130 031 24% Fiche 50-000.84/08/10,8408070376
- 8408270245 Forwards Insp Repts 30-454/84-53 % 50-455/84-36 on 840724-26 % onecompliance noted SPESSARD.R L Region 3. Office or Director 84/08/10 REED.C Componue@ith Edison Co. 2pp. 26258 101 24% Fiche 50-454,84/08/10, 8408270245
- --84082/0277 Insp Repts 50-454/84-53 / 50-155/84-36 on 840724-26 No noncompliance noted Hajor areas inspected licensee action on previously identified item. IE bulletins % 100FR50 55(e) items

  MENDEZ.R , CHRISTHOT,E , BUILER.D Region 3. Office of Director 84/08/09 Spp 26258 103 24% Fichs 50-454.84/08/10.8408270245
- B40B100007 IE Info Notice B4-63, "Defective RHR Replacement Piping "
  Byc list encl
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post B30103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000.84/08/13.8408100009
- 8408220079 Documents schedule for submitting inservice insp (ISI) programs Commitment will be incorporated into FSAR in next amend ISJ program vill be submitted within 6 months after issuance of DLs
  TRAMM.T R Commonwealth Edison Co. 84/08/13 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p 26173 251 24X
  Fiche 50-000.84/08/13.8408220079
- B40B240194 Notifies of 840915 potential date for first use of respiratory protective equipment for fuel load Program complete X ready for insp SWARTZ.ED Commonwealth Edison Co 84/08/14 KEPPLER.J Q Region 3, Office of Director 1p 26228 104 24X Fiche 50-454.84/08/14. B40B240194
- 8408100021 IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26178 001 24x Fiche 30-000.84/08/16,8408100021
- 8408280443 Forwards 840718 Ofc of Investigation (OI) Rept 3-83-006, transmitted for placement in PDR OI reviewed document & made deletions to protect confidentiality & privacy Related correspondence
  LEWIS.8 H Office of the Executive Legal Director DSB 337
  84/08/16 CLEMENTS.W L Ducketing % Services Branch 138pp
  26280 347 24% Fiche 50-454,84/08/16,8408280443
- 8408100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- B40B140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc 11st encl JORDAN.E Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000.84/08/17,8408140208
- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26327 008 24X Fiche 50-000.84/08/21,8408210142
- 8408230247 Board Notification 84-140 forwards NRC 840801 ack of response to Insp Repts 50-454/84-23 % 50-455/84-16 % util 840712 response to insp repts NOVAK:T M Assistant Director for Licensing 84/08/22 SHITH, I W . CALLIHAN, D . COLE, R F Atomic Safety and Licensing Board Panel 3pp 26241 307 24X Fichs 50-454/84/08/22,8408230247
- 8408280274 Submits clarifying info to 840703 ltr re results of QC inspector reinsp program.per Insp Repts 50-454/82-05 & 50-455/82-04 Reinsps of equipment setting & equipment mod clarified DELOEURGE.L. O Commonwealth Edison Co. 84/08/22 KEPPLR.J G Region 3, Office of Director 2pp 26274 325 24X Fiche 50-454.84/08/22.8408280274

- 8408300195 Fulwards Affachments 1.2.3.3.1 9 6 omitted from Board Notification 84-147 \* NIKC - No Detailed Affiliation Given 81/08/22 NRC - No Detailed Affiliation Given 1p 2c304 CR2 24X Fiche 50-454.34/08/22/8408300155
- B Reportable occurrences LFHs ? related correspondence
- B407310030 Board Notification 84-134 forwards UF Streeter B40711 memoto D6 Fisenhut re stear generator shubber testing failures Inspirepts documenting results of testing & applicant reevaluation efforts will be rorwarded to Board NDVAK.T M Assistant Director for Licensing 84/07/27 SMITH.I W CALLINAN.D. CO E.R.F. Atomic Safety and Licensing Board Panel 2pp 25936 033 24% Fiche 50-000.84/07/27.8407310030
- --8408060344 Discusses steam generator snubber testing failures Snubbers made by Boeing Co Vendoi Program Branch will be notified Results of testing b applicant reevaluation efforts will be documented in IE inspirepts
  STREETER, J. F. Region 3. Office of Director 84/07/11
  EISENBUT, D. G. Division of Licensing ip 25936 035 24X
  Fiche 50-000, 84/07/27, 8407310030
- B40B130231 Interin Deficienty Repts 84-05 % 84-11 re unsatisfactory operation during qualification testing of steam generator snubbers supplied by Boeing Co Initially reported on 84062B Next rept expected by 840901 BHART7.E D Commonwealth Edison Co 84/07/31 KFPPLER.J G Region 3, Office of Director 4pp 2600B 174 24X Fiche 50-000.84/07/31. B408130231
- T Hearing transcripts on non-antitrust matters
- 8408020023 Transcript of 840727 hearing in Rockford, IL Vol II Pp 7,4019,488 Supporting documentation encl
  \* Atomic Safety and Licensing Board Pancl 84/07/27 280pp
  25820 305 24x Fiche 50-454,84/07/27,8408020023
- 8408020135 Transcript of 840727 hearing in Rockford, IL Vol I Pp 9,226-9,400 Supporting documentation encl # Atumic Safety and Liconsing Board Panel 84/07/27 249pp 25891 034 24% Fiche 50-454.84/07/27.8408020135
- 8408010249 Forwards testimony filed during 840724 hearings in Rockford, IL W/o encls Related correspondence GAYLEY, J. Isham, Lincoln & Beale DSB 660 84/07/30 Docketing & Services Branch lp 29855 340 24X Fiche 50-454,84/07/30,8408010249
- B408060133 Transcript of 840730 hearing in Rockford IL Pp 9,439-9,674 Supporting documentation enc! \* Atomic Safety and Licensing Board Pans! 84/07/30 84pp 25928 140 24X Fiche 50-454,84/07/30,8408060133
- 8408040178 Transcript of 840/31 hearing in Rockford IL Pp 9.675-9.915 \* Atomic Bafety and Licensing Board Panel 84/07/31 242pp 23923 059 24x Fiche 50-454 84/07/31.8408060178
- 840B080U43 Transcript of 840801 hearing in Rockford, IL Pp 9, 916-10, 145 Supporting documentation encl \* Atomic Safety and Licensing Board Panel 84/08/01 254pp 25962 154 24% Fiche 50-454, 84/08/01, 8408080043
- 8408080022 Transcript of 840802 hearing in Rockford, IL Pp 10.146-10.250 \* Atomic Safety and Licensing Board Panel 84/08/02 360pp 25968 066 24X Fiche 50-454,84/08/02,8408080022
- 840Bi00030 Forwards transcript of KD Ward 840621 deposition in Glen Ellyn, IL Related correspondence RILEY, A Taylor Associates DSR 890 84/08/07 PLEABANT, E Bocketing & Services Branch ip 25997 086 24Y Fiche 50-454,84/08/07.840Bi00030
- --840B100040 Transcript of KD Ward 840621 deposition in Glen Ellyn, IL Related correspondence \* Atomic Bafety and Licensing Board Panel WARD, K D Commonwealth Edison Co. 84/06/21 175pp. 25997 087 24X Fiche 50~454, 84/08/07. 8408100030
- 840Bi90119 Forwards summary of testimony & testimony of NRC re equipment by Sys Control Corp, to be presented on 840820 Related correspondence HILCOVE.M N. Hearing Branch 2 DSH 046 84/08/13 SMITH, I W., CALLIMAN.A D., CD.E.R F. Atomic Safety and Licensing Board Panel 2pp 26066 322 24% Fiche 50-454.84/08/13,8408150119

1

- --840815012/ Summary of testimony of NRC staffire equipment supplied to facility by Sys Control Corp Testimony discusses info acquired since Aug 1983 re corrective actions & steps taken to establish adequacy Related correspondence

  Office of the Fierutive Legal Director 84/08/13 2pp 24066 324 24x Fiche 50-45184 08/13,8408150119
- --B408150132 Testimony of MRC to equipment supplied to facility by Sys Control Corp Related correspondence
  \* Office of the Evecutive Legal Director 84/08/13 22pp
  26066 326 24% Fiche 30-454.81/08/13,8408150119
- ### 408170319 Notion for leave to file testimony of WM Blevel en Contention i re reinsplongram Related correspondence CASSEL, DW Dekalb Area Ailitance for Responsible Energy DSB 085 84/08/13 317 Atomic Bafety and Liconsing Board Panel 4pp 26114 317 264 Fiche 50-454,84/08/13,8408170319
- --8408170321 Summary of testimony % testimony of UH Blevel on Contention 1 re reinsp program Resume encl Related correspondence BLEUEL,W H Affiliation Not Assigned 84/08/13 47pp 24114 321 24% Fiche 50-454,84/08/13,8408170319
- --8408170326 Surmary of testimony / testimony of EP Erickson on Contention I is reinsp program-inspector qualification & work quality Resume & Certificate of Svc encl Related correspondence
  ERICKSEN.E P Temple Univ , Philadelphia PA ERICKSEN.E P
  Businessmen for the Public Interest 84/08/13 33pp 26115 007
  24X Fiche 50-454:84/03/13,8408170317
- 8408170298 Forwards corrected Pages 6.11 \* 17 to EP Erickson testimony re retnsp program Related correspondence
  JUD901N.V A Dusinessmen for the Public Interest DSB 090
  84/08/14 SMITH.J W. COLE.R F. CALLIHAN.A D Atomic Safety and
  Licensing Board Panel App 26115 124 24X Fiche 30-454,84/08/14,8408170299
- 8408170307 Summary of testimony & testimony of DS Kochhar on Contention 1 re reinsp program Certificate of Svc encl Related correspondence KOCHHAR, D. S. Hichigan, Univ. of, Ann Arbor, MI 1980 091 84/08/14
  - ROCHHAR, D S Hichigan, Univ of, Ann Arbor, MI DSB 091 84/08/14 24pp 26115 040 24x Fiche 50-454.84/08/14.8408170307
- 8408170274 Direct testimony of CC Stokes re engineering evaluations performed 1 use of engineering judgement by Sargent 1 Lundy Suggests need for independent engineering analysis of safety significance of reinsp program Related correspondence STOVEG, C C Affiliation Not Assigned DS8 084 84/08/16 34pp 26115 073 247 Fiche 50-454.84/08/16,8408170276
- B4OB1703B0 Summary of testimony & direct testimony of CC Stokes on reinsp program Related correspondence
  BTOMEG.C C. STOKES.C C Businessmen for the Public Interest DSB
  100 B4/08/17 98pp 26128 260 24X Fiche 50-454,84/08/17
- E408200446 Forwards Franscript of CC Stokes 840817 deposition Related correspondence
  WESTHALL M Ann Riley 3 Associates DSB 177 84/08/20
  PLEASANTIE Docketing & Services Blanch 1p 26136 114 24X
  Fiche 50-454.84/08/20.8108200446
- 8408270023 Transcript of 840820 hearing in Rockford. IL Pp 10.351-10.458 \* Atomic Safety and Licensing Board Panel 84/08/20 108pp 26247 195 24x Fiche 50-454.84/08/20,8408270023
- B408270025 Transcript of hearing in Rockford, IL Pp 10,459-10,682 \* Atomic Safety and Licensing Board Panel B4/08/21 266pp 26246 093 24% Fiche 50-454,84/08/21,8408270025
- ©408280228 Transcript of 840822 hearing in Rockford, IL Pp 10,683-10,931 Supporting documentation encl \* Atomic Safety and Licensing Board Panel 84/08/22 396pp 26263 001 24X Fiche 50-454.84/08/22,8408280228
- 8408280153 Transcript of 840823 hearing in Rockford, IL Pp 10. 932-11.139 \* Atomic Safety and Licensing Board Panel 81/08/23 263pp 26270 001 24X Fiche 50-454,84/08/23,8408280153
- B4Q8280138 Transcript of 840824 hearing in Rockford. IL Pp 11,140-11,177 Supporting documentation encl \* Atomic Safaty and Licensing Board Panel 84/08/24 124pp 26259 088 24X Fiche 50-454.84/08/64,8408280138

- 8408310192 Rebuttal Festimony or B Erler re Stokes allegations concerning evaluations of discrepancies in calculated actual stress performed by Sargent / Lundy Related correspondence ERLER B Sargent & Lundy, Inc. DS 369 84/08/30 10pp 26319 043 24x Fiche 50-454.84/08/30,8408310192
- --8408310174 Summary of rebuttal testimony & testimony of ML Somsag.

  EB Branch.D DeMoss.MR Frankel.BF Maurer & JK Buchanan re
  plant QC inspector reinsp program & C Stokes allegations re
  welds Related correspondence
  BRANCH.E B , DEMOSS.D M Sargent & Lundy. Inc FRANKEL.M R City
  College of Neu York 84/08/30 83pp 26319 053 24X
  Fiche 50-454.84/08/30.8408310192
- ~-8408310199 Rebuttal testimony of RW Hooks re validity of info in Attachment 7 to Stokes testimony concerning design assumption for plant Stokes info inapplicable to plant Related correspondence HOOKS.R W Sargent & Lundy, Inc 84/08/30 3pp 26319 136 24X Fiche 50-454,84/08/30,8408310192

### V Operator Examinations

- 84081403/2 Forwards proposed rev to "Requalification Program for Licensed Operators, Benior Operators & Senior Operators (Limited)," In response to NUREO-0737, Item I A 3 1 MARSHALL./G Commonwealth Edison Co 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation Director 2pp 28051 240 24% Fiche 50-000-84/08/07,8408140372
- --8408140389 "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited) "
  \* Commonwealth Edison Co. 84/07/19 10pp 26051 242 24% Fiche 50-000, 84/08/07, 8408140372
- 8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners. WALKER:R D Region 3. Office of Director 84/08/10 Michigan. Univ of. Ann Arbor. MI 2pp 26051
- DOCKET SIN-50-454 BRAIDHOOD STATION. UNIT 1

  Application/construction stage documents & correspondence
- B40B010185 Forwards request for add1 info for review of vol reduction sys (Outstanding Item 15 of Byron SER) Response requested within 30 days of itr date OLSHAN, I. M. Licensing Branch 1 84/07/17 FARRAR, D. Commonwealth Edison Co. 10pp. 25873 272 24X Fiche 50-000, B4/07/19, B408010185
- B40Bi40376 Informs that Archaeological Site 11Kai79 retains integrity & expected to yield evidence sufficient for inclusion in Natl Register, in response to B40713 inquiry Recommends delay until revised form re std of significance received SCULLE.K A Illinois. State of 84/07/23 YOUNOBLOOD, B J Licensing Branch i 1p 26042 316 24X Fiche 50~456, 84/07/23, B408140376
- 840B0B0539 Forwards review of proposed const assessment plan Plan acceptable, subj to incorporation of NRC comments Buggested protacol for communication between Independent Expert Overview Group & util contractors encl
  KEPPLER, J 9 Region 3, Defice of Director B4/07/27 O'CONNOR, J J Commonwealth Edison Co Spp 25975 316 24X Fiche 50-456, 84/07/27,840B0B0539
- B408140380 Forwards responses to FSAR Questions 10 57.10 63.10 64.

  10 65 & 10 66 Revised response to Question 10 57 based on revised safe shutdour analysis Info will be included in next FSAR amend
  BMARTZ.E D Commonwealth Edison Co 84/08/02 DENTON.H R Office of Nuclear Reactor Regulation, Director 32pp 26041 132 24X Fiche 50-000.84/08/02.8408140380
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Generic Bafety Issues" Svc list encl EISENHUT, D G Division of Licensing 84/08/04 Consolidated Edison Co of Neu York, Inc. 18pp 26127 236 24X Fichs, 50-000, 84/08/06, 8408070110
- 8408160345 Advises that QA program applicable to all nuclear generating stations & satisfies provisions of 10CFR71 Fee remitted per 10CFR170 31 FARRAR, D L Commonwealth Edison Co 84/08/06 Office of Nuclear Material Safety & Safeguards, Director 1p 26092 184 24X Fiche 50-000,84/08/04,8408160345

- 8408140386 Advises of decisin to organize // implement project startup organization Transfer of precperational testing responsibilities util be implemented gradually FBAR Chapters 13 \* 14 will be amended SMARTZLED Commonwealth Edison to 84/08/07 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 20pp 26053-328 24X Fishe 50-456.84/08/07.8408140386
- 8408140335 Forwards revised Natl Register nomination for Archaeological Site 11KA179 Cause for designating 11KA179 based on revised nomination Nomination satisfies Natl Register evaluation documentation 12/2 encl SCULLE.K A Illinois, State of 84/08/08 YOUNGBLOOD, B J Licensing Branch 1 1p 26042 355 24X fiche 50-456.84/08/08. B408140335
- 8408220239 Discusses post-accident sampling sys being installed to address NRC requirements in MUREG-0737. Item I( B 3 High radiation sampling sys described in FSAR will be operational on each unit prior to Initial criticality TRAMM. T R Commonwealth Edison Co. 84/08/13 DENTON. H R Office of Murlear Reactor Regulation Director ip 26193 139 24X Fiche 50-000.84/08/13.8498220239
- B40B220306 Forwards proprietary & nonproprietary responses to NRC 1tr re inproved thermal design procedure Response should close Byron SER Outstanding Item 8 Info deleted Proprietary response withheld (ref 10CFR2 790)
  TRAMM.TR Commonwealth Edison Co 84/08/13 DENTON.HR Office of Nuclear Reactor Regulation. Director 20pp 26193 053 24X
  Fiche 50-000:84/08/13.8408220306
- --8408220321 Requests withholding proprietary response to NRC questions on inproved thermal dasign procedures & rod bow,per 10CFR2 790 Affidavit AU-76-60 encl HIESEMANN.R A Vestinghouse Electric Corp 83/12/27 DENTON,H R Office of Nuclear Reactor Regulation. Director ADENBAM.E 9 Licensing Branch 4 8pp 26193 073 24X Fiche 50-000.84/08/13, 8408220306
- B408200275 Generic Ltr B4-20 to all licensees of operating reactors & applicants for CLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl ELSENHUT.D 0 Division of Licensing B4/08/20 Consplidated Edison Co of Neu York. Inc. 17pp 26276 244 24X Fiche 50-000.84/08/20.8408200275
- 8408270118 Submits addl into re basis for proposed Tech Spec requirements on availability of Diesel Generator 2A during time Unit 2 under const TRAMM.T R Commonwealth Edison Co 84/08/21 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26247 338 24X Fiche 50-000.84/08/21.840827018
- B408300230 Requests determination of eligibility of Site likal79 for inclusion in Natl Register of Historic Places Detailed info provided on encl Natl Register of Historic Places inventory monination forms W/o encl YQUNOBLODD. B J Licensing Branch 1 84/08/22 RUCERS. J Interior. Dept of, National Park Service 2pp 26330 360 24X Fiche 50-456.84/08/22.8408300230
- / NRC Draft/Final Environmental Statements, suppls & correspondence
- B408220151 Comments on FES for facilities Sport islands in cooling pand should be revegetated if agreement between util & Field Museum of Natural History not renewed FRANZ.W D Environmental Protection Agency 84/08/14 YDUNGBLOOD, B J Licensing Branch i 2pp 26/188 074 24X Fiche 50-456.84/08/14.8408220151
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8408140371 Forwards compliance review against GDC 51 for reactor containment pressure boundary components Review for Braidwood Station should resolve SER Dutstanding Item 4 SWARTZ.E D Connonuealth Edison Co 84/08/09 DENTON.H R Office of Nuclear Reactor Regulation. Director 17pp 26042 299 24X Fiche 50-000.84/09/09.8408140371
- B408270204 Forwards add1 info re monitoring of leakage from sysoubtside containment used to transport highly radioactive fluid & gases in post-accident condition Info should close SER Confirmatory Issue 28(a) TRAMM. TR Comnonuealth Edison Co 84/08/11 DENTON. HR Office of Nuclear Reactor Regulation. Director 7pp 26245 103 24X Fiche 50-000.84/08/11.8408270204

- BAOB2703/3 Forwards add1 into in instrumentation being installed for detection of inadequate cure cooling Info should close SER Outstanding Item 9 to any livense conditions TRAMM. I R. Connocusealth Firm to 84/08/20 DENTON, H.R. Office of Noticeal Reartor Regulation Director App. 26240-254 24X Fiche 50-000.84/38/20.84082/08/3
- B40B310226 Forwards add1 info 'A out reduction sys in response to B40710 request NRC review if info heressary to close SER Outstanding Iten 15
  TRAMM-1 R Commonwealth Edison to B4.08/24 DENTON HR Office of Nuclear Reactor Regulation, Director 2/pp 26322 138 24X
  Fiche 50~000 B1/0B/24.840B310726
- F. Security, medical, emergency \* fire protection plans
- 8406140101 forwards IE Insp Reptx 50-456/84 08 % 50-457/84-08 on 840401-30 % notice of violation WARNICK, R.F. Region 3, Office of Director 84/05/22 REED, C Commonwealth Edison Co. 3pp. 24928 284 24X Fiche 50-456,84/05/22,8406140101
- --8405140104 IE Insp Rep's 50-456'34 OB / 50-457/84-08 on 840401-30 Noncompliance noted failure to perform required fit-up insp y take corrective action is welding insp FORNEY.W Region 3. Office of Director 84/05/22 15pp 24928 289 24% Fiche 50-456.84/05/22.8406140101
- 8408050210 Notification of 840<sup>7</sup>31 meeting u/util in Silver Spring,MD to discuss safequards info \* security plan STEVENS. J.A. Licensing Branch 1 84/07/26 YOUNGBLOOD. B. J. Licensing Branch 1 4pp 25936 183 24% Fiche 50-456.84/07/26.8408060210
- 8408220243 Summary of Bio73i meeting w/util in Bilver Spring.MD re security plan implementation # NRC - No Detailed Artiliation Oisen B4/07/31 NRC - No Detailed Affiliation Given 2pp 26203 311 24Y Fiche 50-000.84/07/31.8408220243
- B408080198 Forwards Amend 4 to "Fire Protection Rept," including detailed comparison of design, const. testing % maint practices against NFPA stds
  SWARTZ.E D Commonwealth Edison to B4/08/02 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 25985 001 24%
  Fiche 50-000,84/08/02,8408080198
- ---8408080205 Arend 4 to 'Fire Protection Rept "
  \* Commonwealth Edison Co 84/07/31 125pp 25985 004 24X
  Fiche 50-000,84/08/02,8408080198
- B408130401 Responds to B40/05 clarification of info me util means of satisfying annual regulatory requirement to review emergency action levels w/offsite emergency support organizations Info acceptable PAPERIELLO.C J. Region 3. Office of Director 04/08/07 REED.C Commonwealth Edison Co. 1p. 26010 130 24% Fiche 50-000,84/08/07,8408130401
- --B40B130413 Responds to 840604 ltr re means for satisfying requirements of 10CFR90.App E.Paragraph IV & Proposal for satisfying requirements to review emergency action levels by offsite agencies clarified FARRAR, D L. Comnonwealth Edison Co. 84/07/05 PAPERIELLO, C. J. Region 3, Office of Director Bop. 26010 131 24X Fiche 50-000,84/08/07,8408140401

#### G Adjudicatory correspondence

- 8408010200 Responds to request for listing of all attys not presently engloyed by NRC but who once worked for Commission & had responsibilities be facilities J Gallo was chief hearing counsel during CP process Rolated correspondence KARMAN.M Hearing Branch 1 050 689 84/07/25 80CK.C A Affiliation Not Assigned 1p 25834 352 24X Fiche 50~456. 84/07/25,8408010200
- 840Bi40028 Motion for leave to file response to Intervenor B Neiner Farms, Inc 840705 status rept re Contention 4 concerning transport of hazardous natl near facility Contention admissibility still pending before ASLB COPELAND, V G Commonwealth Edison Co COPELAND, V G Isham, Lincoln & Beale DSB 938 84/08/09 Atomic Safety and Licensing Doard Panel 1p 26044 194 24X Fiche 50-456,84/08/09,840B140028
- --8408140034 Response to Neinel Farms 840705 status rept re Contention 4 concerning transport of halardous mati near facility Intervenor offers no new substantial info Contention 4 should be dismissed COPELAND, V G Commonicalth Edison Co COPELAND, V G Isham, Lincoln & Baale 84/03/09 Atomic Safety and Liconsing Board Panel 6pp 26044 195 24X Fiche 50-456,84/08/09,8408140028

- K Utility Final Safety Analysis Report (FSAR) % amends
- 8408300053 Forwards afridanit attesting to distribution of FSAR Amends 44 & 45 TRAMM,T R Commonwealth Edison Co. 84/08/16 DENTON,H R Office of Nuclear Reactor Regulation. Director Rpp 26307-236 24X Fiche 56-000-84/08/16,8408300353
- Q Inspection reports: IE Bulletins & Correspondence
- 8408130415 Forwards, for review, Rev 1 to "Evaluation of Energy Absorbing Mat1 for Pipe Whip Restraints," in response to IE Insp Repts 50-454/83-06 t 50-455/83-05 SWARTZ.E D Commonwealth Edison Co 84/04/13 KEPPLER.J G Region 3, Office of Director 2pp 26011 038 24% Fiche 50-000,84/04/13,8408130415
- --8408130420 Rev 1 to "Evaluation of Energy Absorbing Mat1 for Pipe Whip Restraints ' KAO,G C : YANG,M G : SU,T Y Sargent & Lundy, Inc SAD-431 R01 84/04/30 47pp 26011 040 24X Fiche 50-000,84/04/13,8408130415
- 8406140101 Forwards IE Insp Repts 50-456/84-08 \$ 50-457/84-08 on B40401-30 \$ notice of violation HARNICK.R F Region 3, Office of Director 84/05/22 REED.C Camonuvalth Edison Co 3pp 24928 284 24X Fiche 50-456,84/05/22. B406140101
- --8406140102 Notice of violation from Insp on 840401-30 NARNICK, R F Region 3, Office of Director 84/05/22 2pj 24928 287 24X Fiche 50-456.84.05/22.8406140101
- --B405140104 IE inap Repts 50-456/84-08 λ 50-457/84-08 on 840401-30 Noncompliance noted failure to perform required fit-up insp & take corrective action re welding insp FORMEY.W. Region 3. Office of Director 84/05/22 15pp 24928 289 24X Fiche 50-456/84/05/22/8406140101
- 8408070338 Forwards IE Insp Repts 50-456/84-14 / 50-457/84-14 on B40612,19,20 & 21 No noncompliance noted LITTLE W 9 Region 3. Office of Director 84/07/18 REED,C Commonwealth Edison Co 2pp 25953 093 24X Fiche 50-456,84/07/18,8408070338
- --8408070340 iE Insp Repts 50-456/84-i4 % 50-457/84-i4 on 840612.15,20 & 21 No noncompliance or deviations noted Major areas inspected allegations re deficiencies in design & installation of HVAC sys KEY.W J , DANIELSON.D M Region 3. Office of Director 84/07/17 14pp 25953 095 24x Fiche 50-456.84/07/18,8408070338
- 8408080188 Forwards IE Insp Repts 30-454/84-25.50-455/84-18. 50-45b/84-11 & 50-457/84-11 on 840425 & 0522-23 No nancompliance noted SPE8BARD.R L Region 3. Office of Director 84/07/18 REED.C Commanwealth Edison Co 2pp 25974 327 24X Fiche 50-000,84/07/18.
- ---8408080195 IE Insp Repts 30-454/84-25,30-455/84-18,50-456/84-11 & 50-497/84-11 on 840425 % 0522-23 No noncompliance noted Hayar areas inspected design calculations re primary shield wall & reactor pressure shield wall & reactor pressure shield wall MUFFCTT.J W., KAUFMAN,P.D., NORTON,J.F. Region 3, Office of Director 84/07/18 4pp 25974 329 24X Fiche 50-000,84/07/18,8408080188
- 8408060302 Forwards IE Insp Repts 50-496/84-07 & 50-497/84-07 on 840326-0531 & notice of violation WALKER, R D Region 3. Office of Director 84/07/20 REED, C Commonwealth Edison Co 2pp 25936 036 24% Fiche 50-456,84/07/20, 8408060302
- --8408060303 Notice of violation from insp on 840326-0531 WALKER,R D. Region 3, Office of Director 84/07/20 2p 25936 058 24X Fiche 50-454,84/07/20,8408060302
- --8408060309 IE Insp Repts 30-456/84-07 % 50-457/84-07 on B40326-0531 Noncompliances noted failure to establish % implement personnel training failure to provide adequate training & failure to identify & correct nonconforming conditions SCHUZ,R, MALLOY,J, KROPP,W Region 3, Opfice of Director 84/07/20 9pp 25936 060 24X Fiche 50-456.84/07/20 8408060302

- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25845 047 248 Fighe 50-000.84/07/27, 8407250229
- B40B090049 informs that 840730 const appraisal team insp postponed NRC will notify licensee of new insp date
  NDRELIUS.C Region 3. Office of Director 84/07/27 REED.C
  Commonwealth Edison Co ip 25992 332 24X Fiche 50-456.84/07/27.
  R40R090049
- 8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during inspirations of the second structure of the second form will be used rather than itr

  KEPPLER.J G Region 3, Office of Director 84/08/03

  Commonwealth Edison Co 3pp 25742 188 24X Fiche 50-000, 84/08/03, 84/08/07/401
- 8408100112 Ack receipt of 840723 ltr informing NRC of steps taken to correct noncompliance noted in IE Inap Repts 50-455/83-09 & 50-457/83-09 WARNICK, F Region 3, Office of Director 84/08/03 REED, C Commonwealth Edison Co
- ---8408100119 Responds to NRC 840507 ltr re nonconformance noted in IE
  Insp Repts 50-455/83-09 & 50-457/83-09 Corrective actions
  nonconformance rept will be unitten, requesting engineering
  disposition of lack of fit-up insp of duct hanger welds
  SHART7,E D Commonwealth Edison Co 84/07/23 KEPPLER, J O
  Region 3. Office of Director 2pp 25991.031 24x
  Fiche 50-456,84/08/03,8408100112
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidate Edison Co of New York, Inc 122pp 26068 001 24X Fichs 50-000.84/08/06.8408010333
- B40B010337 IR Info Notice B4~60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Bvc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 24067 158 24X Fiche 50-000.84/08/06.8408010337
- 8408290549 Forwards Insp Repts 50-456/84-13 & 50-457/84-13 on 840605-0706 & notice of violation WARNICK:R F Region 3. Diffice of Director 84/08/07 REED.C Commonwealth Edison Co 2pp 26296 156 24X Fiche 50-456:84/08/07, ganegonae
- ~~8408290553 Notice of violation from insp on 840405-0704 WARNICK,R F Region 3, Office of Director 84/08/07 2pp 24294 158 24X Fiche 50-456,84/08/07,8408290549
- ---8409290561 Insp Repts 50-456/84-13 & 50-457/84-13 on 840605-0706
  Noncompliance noted procurement documents £id not specify
  that provisions of Part 21 apply for heat shrink tubing &
  failure to control weld rod for cable pan welding
  FARNEY.W L Region 3, Office of Director 84/08/06 28pp
  26296 160 24X Fichs 50-456,84/08/07,8408290549
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- B40Bi40344 Confirms B40B03 plans to meet w/util on B40907 in Olen Ellyn:IL to discuss regulatory improvement program NGRELIUS.C E Region 3, Office of Director 84/08/08 REED,C Commonwealth Edison Co 2pp 26041 030 24X Fiche 30-000.84/08/08.8408140344
- 8408150078 Supple 840711 response to 1E Bulletin 84-02 re visual insp during monthly functional tests to verify proper contact on reactor trip sys & primary containment isolation sys relays Exemptions requested for listed relays ALEXANDER, G L Commonwealth Edison Co 84/08/08 KEPPLER, J G Region 3, Office of Director 3pp 26067 053 24X Fiche. 50-000, 84/08/08, 8408150098
- 8408200331 Supple response to IE Bulletin 84-02 re failure of GE Type HFA relays.Examption requested from commitment for visual insp verifying proper relay contact during monthly functional check for listed relays ALEXANDER.O L Commonwealth Edison to 84/08/08 KEPPLER, J G. Region 3, Dfftce of Director 3pp 26132 318 24X Fiche 50-000,84/08/08,8408200331

- 840B070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl GRACE,J N Division of OA, Safeguards : Inspection Programs (Post B30103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24% Fiche 50-000,84/08/10,840B0703726
- B40B100009 IE Info Notice 84-63, "Defective RHR Replacement Paping"
- Bvc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000.84/08/13.8408100009
- 8408220079 Documents schedule for submitting inservice insp (ISI) programs Commitment will be incorporated into FSAR in next amend ISI program uill be submitted within 6 months after issuance of OLs

  TRAMM.T R Commonwealth Edison Co 84/08/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 26193 251 24X Fishe 50-000.84/08/13 8488220079
- 8408300118 Forwards Insp Repts 30-456/84-19 & 50-457/84-18 on 840711-12 No noncompliance noted 8PESSARD, R L Region 3, Office of Director 84/08/14 REED, C Commonwealth Edison Co 2pp 26307 215 24X Fiche 30-456.84/08/14, 8408300118
- --8408300121 Insp Repts 30-456/84-17 % 50-457/84-18 on 840711-12 No noncompliance or deviations noted Major areas inspected licensee action on previously identified items GAUTAMA S . TANI.K . HANKINES F Region 3. Diffice of Director 84/08/14 8pp 26307 217 24X Fiche 50-456.84/08/14.8408300118
- 840Bi0003B IE Info Notice B4-64, "BWR HPCI Initiation Seal-In & Indication "Svc list entl JORDAN E. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000.84/08/15,8408100038
- B40B210342 Ack receipt of B40731 ltr informing NRC of steps taken to currect violations noted in IE Insp Repts 50-456/B4-09 & 30-457/B4-09 WARNICK/R F Region 3, Office of Director B4/08/15 REED,C Commonwealth Edison Co 2pp 26180 1B9 24X Fiche 50-456/B4/0B/15, B408210342
- --8408210358 Responds to NRC 840702 ltr re violations noted in IE Insp Repts 50-456/84-09 & 50-457/84-07 Corrective actions util & Bargent & Lundy developing qualitative & quantitative clearance info to be included in contractor spec FARRAR. b L Commonwealth Edison Co 84/07/31 KEPPLER, J G Region J, Dffice of Director &pp 26180 171 24X Fiche 50-456,84/08/15,8408210342
- 8408100021 TE Info Notice 84-63, "Underrated Fuses Which May Adversely Affact Operation of Essential Electrical Equipment " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc. 118pp. 26178 001 24X Fiche 50-000,84/08/16,8408100021
- B40B100055 |E info Notice B4-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Bvc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- 8408140209 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/
  High Failure Rates " Svc list encl
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/17 Consolidated Edison Co of New
  York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves "Syc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830109) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000.84/08/21,8408210142
- S Reportable occurrences, LERs & related correspondence
- 8407100002 Final Deficiency Rept 84-07 re concrete expansion anchor installation Initially reported on 840511 Deficiencies will be reworked, per Sargent & Lundy requirements & contractors will contact company for installation instructions SHARTZ.E D Commonwealth Edison Co 84/06/11 KEPPLER.J Q Region 3. Office of Director 2pp 25512 146 24X Fiche 50-456.84/06/11.8407100002

- B407310030 Board Notification 84~134 forwards JF Streeter 840711 memo to DO Eisenhut re steam generator snubber testing failures Insp repts documenting results of testing 9 applicant reevaluation efforts will be forwarded to Board NOVAK.T M Assistant Director for Licensing 84/07/27 SMITH, I W. CALLIHAN.D. COLLER F. Atomic Safety and Licensing Board Panel 2pp 25736 033 24% Fiche 50~000.84/07/27.8407310030
- ~~8408060344 Discusses steam generator snubber testing failures Snubbers made by Boeing Co Vendor Program Branch will be notified Results of testing & applicant reevaluation efforts will be documented in IE insprepts
  STREETER.J F Region 3, Office of Director 84/07/11
  EISENHUT, D Q Division of Licensing 1p 25936 035 24%
  Fiche 50-000,84/07/27,8407310030
- 840Bi30231 Interim Deficiency Repts 84~05 & 84-11 re unsatisfactory operation during qualification testing of steam generator snubbers supplied by Boeing Co Initially reported on 840628 Next rept expected by 840901 SMARTZ.E D. Commonwealth Edison Co. 84/07/31 KEPPLER, J. G. Region 3, Office of Director. App. 2600B 194 24X Fiche 50~000,84/07/31,840Bi30231
- 8408300044 Interim Deficiency Rept 84-04 re out of tolerance radiographic film densities Initially reported on 840306 Pipe welds w/radiographic film records exceeding density requirements are being reradiographed & repaired SMARTZ.E D Commonwealth Edison Co 84/08/16 KEPPLER, J 9 Region 3, Office of Director 3pp 26307 067 R4X Fiche 50-456.84/08/16, 8408300044
- 8408300214 Final rept of Deficiency 84-06.NCR 604 re leak in recycle holdup tanks DABDITA & DABDITB Initially reported on 840413 Rev of tank design procedures to utilize butt weld const for tank bottom underway BWARTZ, E D Commonwealth Edison Co 84/08/16 KEPPLER, J G Region 3, Office of Director 2pp 26307 052 24X Fiche 50-456,84/08/16,8408300214

#### V Operator Examinations

- B40B140372 Forwards proposed rev to "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)." in response to NURGE-0737, Item I A 31 MARSHALL, J 9 Commonwealth Edison Co 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26051 240 24X Fiche 50-000 84/08/07, 840B140372
- --8408140389 "Requalification Program for Licensed Operators, Senior Operators & Benior Operators (Limited) "
  \* Commonwealth Edison Co 84/07/19 10pp 26051 242 24x
  Fiche 50-000, 84/08/07, 8408140372
- 8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners WALKER, R D Region 3. Office of Director 84/08/10 Michigan. Univ of, Ann Arbor, MI 2pp 26031 198 24X Fiche 50-000, 84/08/10.8408140426
- DOCKET STN-50-457 BRAIDWOOD STATION: UNIT 2
- A Application/construction stage documents & correspondence
- 8408010185 Forwards request for add1 info for review of vol reduction sys (Qutstanding Item 15 of Byron SER) Response requested within 30 days of 1tr date GLEHAN,L N Licensing Branch 1 84/07/19 FARRAR,D L Commonwealth Edison Co 10pp 25873 292 24X Fiche 30-000, 84/07/19,8408010185
- 840B140376 Informs that Archaeological Bite 11Ka179 retains integrity to expected to yield evidence sufficient for inclusion in Nati Register, in response to 840713 inquiry Recommends delay until revised form re std of significance received.

  8CULLE, K. A. Illinois, State of 84/07/23 YOUNGBLOOD, B. J. Licensing Branch 1 ip 26042 316 24X Fiche 50-456, 84/07/23, 8408140376
- 8408080539 Forwards review of proposed const assessment plan Plan acceptable, subj to incorporation of NRC comments Suggested prototol for communication between Independent Expert Overview Group & with contractors enci
  KEPPLER. J G Region 3, Office of Director 84/07/27 O'CONNOR, J J Communeaith Editor Co 5pp 25975 316 24X Fiche 50-456, 84/07/27,8408080539

- B40B1403B0 Forwards responses to FSAR Questions 10 57,10 63,10.64, 10 65 & 10 66 Revised response to Question 10 57 based on revised safe shutdown analysis Info will be included in next FSAR amend SWARTZ, E D Commonwealth Edison Co 84/08/02 DENTON, H.R. OF
  - SWARTZ, E D Commonwealth Edison Co 84/08/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 32pp 26041 132 24X Fiche 50-000,84/08/02,8408140380
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for GLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Generic Safety Issues "Svc list encl EISCHHUT, D & Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26127 238 24X Fithe 50-000.84/08/06.8408070110
- 840Bi60345 Advises that QA program applicable to all nuclear generating stations & satisfies provisions of 10CFR71 Fee remitted per 10CFR170 31 FARRAR D L Commonwealth Edison Cu 84/08/06 Office of Nuclear
- per 100FR1/0 31 FARRAR, D.L. Commonwealth Edison Co. 84/08/06 Office of Nuclear Material Safety & Safeguards, Director 1p 26092 184 24x Fiche 50-000, 84/08/06, 8408160345
- 840B1403B6 Advises of decison to organize & implement project startup organization Transfer of preoperational testing responsibilities will be implemented gradually FBAR Chapters 13 & 14 will be amended SMARTI.E D Commonwealth Edison Co 84/08/07 DENTON.H R Office of Nuclear Reactor Regulation. Director 20pp 26053 328 24x Fiche 50-456,84/08/07,8408140386
- 840B140335 Forwards revised Natl Register nomination for Archaeological Site likAl79 Cause for designating likAl79 based on revised nomination Nonination satisfies Natl Register evaluation documentation W/o enci SCULLE.K A Illinois, State of 84/08/08 YOUNGBLOOD, B J Licensing Branch i 1p 26042 355 24X Fiche 50-436,84/08/08,8408140335
- B408220306 Forwards proprietary & nonproprietary responses to NRC 1tr re improved thermal design procedure Response should closs Byron SER Outstanding Item B Info deleted Proprietary response withheld (ref 10CFR2.790)
  TRAMM, T R Commonwealth Edison Co 84/08/13 DENTON, H R Office of Nuclear Reactor Regulation. Director 20pp 26193 053 24X
  Fiche 50-000.84/08/13.8408220306
- --8408220321 Requests withholding proprietary response to NRC questions on improved thermal design procedures & rad bow, per IOCFR2 790 Affidavit AH-76-60 enc1
  WIESEMANN.R A Mestinghouse Electric Corp 83/12/27 DENTON.H R
  Office of Nuclear Reactor Regulation. Director 8pp 26193 073
  24X Fichs 50-000.84/08/13,8408220306
- 8408220239 Discusses post-accident sampling sys being installed to address NRC requirements in NUREO-0737. Item II B 3 High radiation sampling sys described in FEAR will be operational on each unit prior to initial criticality TRAMM. T R Commonwealth Edison Co 84/08/13 DEMYON. H R Défice of Nuclear Reactor Regulation. Director ip 26193 139 24% Fiche. 50-000.84/08/13.8408220239
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for DLs rescheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT,D 0 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Ficha 50-000.84/08/20.8408200275
- 840B270118 Submits add1 info re basis for proposed Tech Spec requirements on availability of Diesel Generator 2A during time Unit 2 under const TRAMM.T R Commonwealth Edison Co 84/08/21 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 26247 338 24X Fichs 50-000:84/08/21,8408270118
- 8408300230 Requests determination of eligibility of Site 11Ka179 for inclusion in Natl Register of Historic Places Detailed info provided on encl Natl Register of Historic Places inventory nomination forms W/o encl. YOUNOBLOOD, B J Licensing Branch i, 84/08/22 ROGERS, J Interior, Dept of National Park Service 2pp 26330,360 24X Fiche 50-456,84/08/22,8408300230
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8408220151 Comments on FES for facilities Spoil islands in cooling pand should be revegetated if agreement between util & Field Museum of Natural History not renewed FRANZ.W D. Environmental Protection Agency 84/08/14 YDUN

- E NRC Safety Evaluation Report (SER), supple & correspondence
- B40B140371 Forwards compliance review against QDC 51 for reactor containment pressure boundary components Review for Braidwood Station should resolve SER Dutstanding Item 4 SWARTZ,ED Commonwealth Edison Co 84/08/09 DENTON,H R Dffice of Nuclear Reactor Regulation, Director 17pp 26042 299 24X Fiche 50-000.84/08/09.8408140371
- 8408270204 Forwards addl info re monitoring of leakage from sysoutside containment used to transport highly radioactive fluid & gases in post-accident condition Info should close SER Confirmatory Issue 28(a)
  TRAMN-TR Commonwealth Edison Co 84/08/11 DENTON.H R Office of Nuclear Reactor Regulation. Director 7pp 26245 103 24X
  Fiche 50-000.84/08/11.8408270204
- 8408270373 Forwards add1 info re instrumentation being installed for detection of inadequate core cooling Info should close BER Gutstanding Item 9 m/o any license conditions.

  TRAMM.T.R. Commonwealth Edison Co. 84/08/20 DENTON.H.R. Office of Nuclear Reactor Regulation, Director App 26240 254 24X Fiche 50-000.84/08/20.8408270373
- 8408310226 Forwards add1 info re vol reduction sys.in response to 840710 request ARC review of info necessary to close SER Outstanding Item 15 TRAMM.TR Commonwealth Edison Co 84/08/24 DENTON.HR Office of Nuclear Reactor Regulation, Director 27pp 26322, 138 24X Fiche 50-000.84/08/24.8408310226
- F Security, medical, emergency & fire protection plans
- B406140101 Forwards IE Insp Repts 50-456/84-08 & 50-457/84-08 on B40401-30 & notice of violation WARNICK, R.F. Region 3, Office of Director 84/05/22 REED, C Commonwealth Edison Co. 3pp 24928 284 24X Fiche 50-456,84/05/22,8406140101
- --8406140104 lE Insp Repts 50-454/84-08 & 50-457/84-08 on 840401-30 Noncompliance noted failure to perform required fit-up insp & take corrective action re welding insp. FORNEY.W Region 3, Office of Director 84/05/22 15pp 24928 289 24X Fiche 50-456,84/05/22,8406140101
- B40B060210 Notification of B40731 meeting u/util in Silver Spring. MD to discuss safeguards info & security plan STEVENS. J A licensing Branch 1. B4/07/26 YOUNGBLOOD. B J Licensing Branch 1 4pp. 25936\*183 24X Fiche 50~456.B4/07/26, B40B060210
- 8408220243 Bummary of 840731 meeting w/util in 8ilver Spring.MD re security plan implementation \* NRC - No Detailed Affiliation Given 84/07/31 NRC - No Detailed Affiliation Given. 2pp 26203 311 24X Fiche:50-000.84/07/31:8408220243
- 8408080178 Forwards Amend 4 to "Fire Protection Rept," including detailed comparison of design, constituting & maint practices against NFPA stds
  8WARTILE D. Commonwealth Edison Co. 84/08/02 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 3pp 25985:001, 24X
  Fiche: 30-000,84/08/02,8408080178
- --8408080205 Amend 4 to "Fire Protection Rept."

  \* Commonwealth Edison Co 84/07/31 125pp, 25985 004, 24%
  Fiche, 50-000, 84/08/02, 8408080198
- 8408130401 Responds to 840705 clarification of info re util means of satisfying annual regulatory requirement to review amergency action levels w/offsite emergency support organizations Info acceptable PAPERIELLO.C. J. Region 3. Office of Director 84/09/07. REED.C Commonwealth Edison Co. ip 26010 130 24% Fiche 50-000,84/08/07,8408130401
- --B40Bi304i3 Responds to 840404 ltr rs means for satisfying requirements of 10CFR50, App E.Paragraph IV.B Proposal for satisfying requirements to review emergency action levels by offsite agencies clarified FARRAR.D L. Commonwealth Edison Co 84/07/05 PAPERIELLO, C J Ragion 3, Offsice of Director. Spp 24010 131 24X Fichs 50-000, 84/08/07, 8408130401.

# Q Adjudicatory correspondence

- B40B010200 Responds to request for listing of all attys not presently employed by NRC but who once worked for Commission & had responsibilities re facilities J Oallo was chief hearing counsel during CP process Related correspondence KARMAN,M Hearing Branch 1 DSB 659 B4/07/25 BOCK.C A Affiliation Not Assigned 1p 25854 352 24X Fiche 50-456, B4/07/25, B40B010200
- 8408140028 Motion for leave to file response to Intervenor B Neiner Farms. Inc 840705 status rept re Contention 4 concerning transport of hazardous matl near facility Contention admissibility still pending before ASLS COPELAND, V C Commonwealth Edison Co COPELAND, V G Isham, Lincoln & Beale DSB 958 84/08/09 Atomic Safety and Licensing Board Panel 1p 26044 174 24X Fiche 50-456,84/08/09,8408140028
- --8408140034 Response to Neinor Farms 840705 status rept re Contention 4 concerning transport of hazardous matl near facility Intervenor offers no new substantial info Contention 4 should be dismissed COPELAND.V G Commonwealth Edison Co COPELAND.V G Isham, Lincoln & Beals 84/08/07 Atomic Safety and Licensing Doard Panel 6pp 26044 193 24X Fiche 50-456,84/08/07,8408140028
- --8408140038 Affidavit of D Demos re possible future reactivation of Joliet Army Ammunitions Plant Notics of appearance & Certificate of Syc encl DEMOS, D Commonwealth Edison Co 84/08/08 App 26044 201 24X Fiche 50-456,84/08/09,8408140028
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8408300053 Forwards affidavit attesting to distribution of FSAR Amends
  44 & 45
  TRANN,T R Commonwealth Edison Co 84/08/16 DENTON,H R Office
  of Nuclear Reactor Regulation, Director 2pp 26307 236 24x
  Fiche 50-000,84/08/16,8408300053
- Q Inspection reports: IE Bulletins & correspondence
- B408130415 Forwards for review Rev i to "Evaluation of Energy
  Absorbing Matl for Pipe Whip Restraints." in response to
  IE Insp Repts 50-454/83-06 & 50-455/83-05
  SWARTZLE D Commonwealth Edison Co B4/04/13 KEPPLER. J G Regior
  1. Office of Director 2pp 26011 038 24X Fiche 50-000.84/04/13.
  8408130415
- ---B408130420 Rev 1 to "Evaluation of Energy Absorbing Mat1 for Pipe Whip Restraints " KAD.9 C Bargent & Lundy, Inc SAD-431 R01 84/04/30 47pp 26011 040 24% Fiche 50-000.84/04/13.8408130415
- 8406140101 Forwards IE Insp Repts 50-456/B4-08 & 50-457/84-08 on B40401-30 & notice of violation WARNICK, R F Region 3, Office of Director B4/05/22 REED, C Commonwealth Edison Co. 3pp 24928 284 24X Fichs 50-456,84/05/22,8406140101
- --8406140102 Notice of violation from insp on 840401-30 WARNICK,R F Region 3, Office of Director 84/05/22 2pp 24928 287 24X Fiche 50-456,84/05/22,8406140101
- ---B406140104 IE Insp Repts 50-456/84-08 & 50-457/84-08 on 840401-30 Noncompliance noted failure to perform required fit-up insp & take corrective action re-welding insp FORNEY.W Region 3. Dffice of Director 84/05/22 15pp 24728 289 24X Fiche 50-456,84/05/22,8406140101
- 8408070338 Forwards IE Insp Repts 50-456/84-14 & 50-457/84-14 on 840612.15.20 & 21 No noncompliance noted LITTLE.W 8 Region 3. Office of Director B4/07/18 REED.C Commonwealth Edison Co. 2pp 25953.093 24X Fichs 50-456.84/07/18.
- --B408070340 IE Insp Repts 50-456/84-14 & 50-457/84-14 on B40612, 15, 20 & 21 No noncompliance or deviations noted Major areas inspected allegations re deficiencies in design & installation of HVAC sys KEY, M J, DANELESON, D H Region 3, Office of Director 84/07/17 14pp 25953 075 24X Ficher 50-456, 84/07/18, 8408070338
- 8408080188 Forwards IE Insp Repts 50-494/84-25, 50-455/84-18, 50-455/84-11 & 50-457/84-11 on 840425 & 0522-23 No noncompliance noted SPESSARD.R L Region 3, Office of Director 84/07/18 REED, C Commonwealth Edison Co 2pp 25974 327 24X Fiche 50-000,84/07/18, 8408080188

- --8408080195 IE Insp Repts 50-454/84-25.50-455/84-18.50 456/84-11 & 50-457/84-11 on 840425 & 0522-23 No noncompliance noted Major areas inspected design calculations re primary shield wall & reactor pressure shield wall MUFFETT.J W. DANIELSON.D H. Region Q. Office of Director 84/07/18 4pp 25974 329 24X Fiche 50-000,84/07/18.8408080188
- 8408060302 Forwards IE Insp Repts 50-456/84-07 & 50-457/84-07 on 840326-0531 & notice of violation HALKER,R D Region 3. Office of Director 84/07/20 REED.C Commonwealth Edison Co 2pp 25936 056 24% Fiche 50-456,84/07/20,8408060302
- --8408060303 Notice of violation from insp on 840326-0531 WALKER,R D Region 3. Office of Director 84/07/20 2pp 25936 058 24% Fiche 50-456,84/07/20.8408060302
- --8408060309 IE Insp Repts 50-456/84-07 & 50-457/84-07 on B40326-0531 Noncompliances noted failure to establish & implement personnel training. failure to provide adequate training & failure to identify & correct nanconfurming conditions SCHULZ,R, MALLOY, J, KROPP, N Region 3, Office of Director 84/07/20 9pp 25936 060 24X Fiche 50-456,84/07/20,8408060302
- 8407250229 IE Info Notice 84-57, "Operating Experience re Meisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229
- B408090049 Informs that 840730 const appraisal team insp postponed NRC will notify licensee of new insp date
  NDRELIUB, C Region 3. Office of Director 84/07/27 REED, C
  Commonwealth Edison Co ip 25992 332 24X Fiche 50-456,84/07/27,
  B408090049
- 8408070401 Informs that new sys of acknowledging receipt of licenspe correspondence re noncompliance found during insp instituted effective 840820 Preprinted form will be used rather than 1tr

  KEPPLER. J G Region 3, Office of Director 84/08/03
  Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000.84/08/03.8408070401
- B408100112 Ack receipt of B40723 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Repts 50-456/83-09 & 50-457/83-09 MARNICK, R F Region 3, Office of Director B4/08/03 REED, C Commonwealth Edison Co ip 25991 030 24X Fiche 50-456, 84/08/03, B408100112
- --8408100119 Responds to NRC 840507 ltr re nonconformance noted in IE Inap Repts 50-455/83-09 & 50-457/83-09 Corrective actions nonconformance rept will be written, requesting engineering disposition of lack of fit-up insp of duct hanger welds SWARTZ, E D Commonwealth Edison Co 84/07/23 KEPPLER, J G Region 3, Office of Director 2pp 28991 031 24X Fichs 50-456,84/08/03,8408100112
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Bvc list encl.

  JORDAN E L. Division of Emergency freparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26068 001 24X Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche. 50-000, 84/08/06, 8408010337
- 8408270549 Forwards Insp Repts 50-454/84-13 & 50-457/84-13 on 840605-0706 & notice of violation MARNICK, F F Region 3, Office of Director 84/08/07 REED, C Commonwealth Edison Co 2pp 26276'156 24X Fiche 50-456,84/08/07.
- --8408290953 Notice of violation from insp on 840605-0706 MARNICK, R F Region 3. Office of Director 84/08/07 26276 158 24X Fiche 50-456,84/08/07,8408290549
- --8408290561 Insp Repts 50-456/84-13 & 50-457/84-13 on 840605-0706 Noncompliance noted procurement documents did not specify that provisions of Part 21 apply for heat shrink tubing & failure to control weld rod for cable pan welding FORNEY, W. L. Region 3, Office of Director 84/08/06 28pp 26276 160 24X Fiche 50-456,84/08/07,8408290549

- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list enc! JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York, Inc. 120pp 26127 118 24X Fiche 50-000.84/08/08,8408070120
- ## 840Bi40344 Confirms ## 840B03 plans to meet w/util on ## 840907 in Glen Ellyn. IL to discuss regulatory improvement program NORELIUS.C E Region 3. Defice of Director ## 840B/08 REED.C Commonwealth Edison Co 2pp 26041 050 24X Fiche 50-000, ## 940B10344
- 8408150098 Suppls 840711 response to 1E Bulletin 84-02 re visual insp during monthly functional tests to verify proper contact on reactor trip sys & primary containment isolation sys relays Exemptions requested for listed relays ALEXANDER. G L Commonwealth Edison Co 84/08/08 KEPPLER, J G Region 3, Office of Director 3pp 26067 053 24X Fiche 50-000,84/08/08,8408150098
- 8408200331 Supple response to 1E Bulletin 84-02 re failure of 0E Type HFA relays Exemption requested from commitment for visual insp verifying proper relay contact during monthly functional check for listed relays ALEXANDER. C. Commonwealth Edison Co. 84/08/08 XEPPLER, J. G. Region 3, Office of Director 3pp. 26132 318 24X Fiche 50-000,84/08/08,8408200331
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl ORACE,J N Division of QA, Safeguards & Inspection Programs (Post B30103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 30-000.84/08/10.8408070376
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JDRDAN.E L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc. 117pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408220079 Documents schedule for submitting inservice insp (ISI) programs Commitment will be incorporated into FSAR in next amend ISI program will be submitted within 6 months after issuance of QLs
  TRAMM, T R Commonwealth Edison Co 84/08/13 DENTON, H R Offi of Nuclear Reactor Regulation, Director ip 26193 251 24X Fiche 50-000,84/08/13,8408220079
- 8408300118 Forwards Insp Repts 50-454/84-19 & 50-457/84-18 on 840711-12 No noncompliance noted SPESSARD, L Region 3, Office of Director 84/08/14 REED, C Commonwealth Edison Co 2pp 26307 215 24X Fichs 50-456,84/08/14,8408300118
- --B40B300121 Insp Repts 50-456/84-19 & 50-457/84-18 on 840711-12 No noncompliance or deviations noted Major areas inspected licensee action on previously identified items GAUTAM.A S., TANI.K., MAHKINS.F. Region 3, Office of Director 84/08/14 Bpp 26307 217 24X Fiche 50-456.84/08/14.840B300118
- B40Bi0003B IE Info Notice B4-64, "BWR HPCI Initiation Seal-In & Indication "Syc list ent!
  JDRDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/15 Consolidated Edison Co of New York, Inc. 104pp 26198 093 24X Fiche 50-000.84/08/15, B40B10003B
- B40B210342 Ack receipt of B40731 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-436/B4-07 & 50-437/B4-09 MARNICK.R F Region 3. Office of Director B4/0B/15 REED, C Communwealth Edison Co 2pp 261B0 1B9 24X Fiche 50-456.84/08/15, 840B210342
- --B408210358 Responds to NRC 840702 ltr re violations noted in IE Insp Repts 50-456/84-09 & 50-457/84-09 Corrective actions util & Sargent & Lundy developing qualitative & quantitative clearance info to be included in contractor spec FARRAR.D L Commonwealth Edison Co 84/07/31 KEPPLER.J & Region 3. Office of Director App 26180 191 24X Fiche 50-456,84/08/15.8408210342
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Rasponse (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26198 001 24% Fiche 50-000,84/08/16,8408100021

- 84G8100055 IE Info Notice 84-66. "Undetected Unavailabl):ty of Turbine-Driven Auxiliary Foedwater Train " Svc list enci-JORDAN E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York Inc 120pp 26276 001 24X Fiche 50-000,84/08/17.8408100055
- 8408140208 IE Info Notice 84-67. "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice B4-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list enci JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50~000.84/08/21,8408210142
- S Reportable occurrences. LERs & related correspondence
- 8407100002 Final Deficiency Rept 84-07 re concrete expansion anchor installation Initially reported on 840511 Deficiencies will be reworked per Sargent & Lundy requirements & contractors will contact company for installation instructions SWARTZ. E D Commonwealth Edison Co 84/06/11 KEPPLER. J Q Region 3, Office of Director 2pp 25512 146 24X Fiche 50-456,84/06/11. 8407100002
- 8407310030 Board Notification 84-134 forwards JF Streeter 840711 memo to DQ Eisenhut re steam generator snubber testing failures Insp repts documenting results of tosting & applicant reevaluation efforts will be forwarded to Board NOVAKIT M Assistant Director for Licensing 84/07/27 BMITH.I W Atomic Safety and Licensing Board Panel 2pp 25934 033 24X Fichs 50-000.84/07/27,8407310030
- --84080603044 Discusses steam generator snubber testing failures Snubbers made by Boeing Co Vendor Program Branch will be notified Results of testing & applicant reevaluation efforts will be documented in IE insp rapts STREETER.J F Region 3. Office of Director 84/07/11 EISENHUT.D 0 Division of Licensing ip 25936 035 24X Fiche 50-000.84/07/27.8407310030
- 840Bi30231 Interim Deficiency Repts 84-05 & 84-11 re unsatisfactory operation during qualification testing of steam generator snubbers supplied by Bowing Co Initially reported on 840628 Next rept expected by 840901 SWARTZ.C D Commonwealth Edison Co 84/07/31 KEPPLER, J G Region 3, Office of Director 4pp 2600B 194 24X Fiche 50-000.84/07/31, 8408130231
- 8408300044 Interim Deficiency Rept 84-04 re out of tolerance radiographic film densities Initially reported on 840306 Pips welds w/radiographic film records exceeding density requirements are being reradiographed & repaired SMARTZ,E D Commonwealth Edison Co 84/08/16 KEPPLER,J Q Region 3, Office of Director 3pp 26307 069 24X Fiche 50-456.84/08/16, 8408300044
- 8408300214 Final rept of Deficiency 84~06.NCR 604 re leak in recycle holdup tanks OABDITA & DABOITD Initially reported on 840412 Ray of tank design procedures to utilize butt weld const for tank bottom underway SWARTZ.E D Commonwealth Edison Co 84/08/16 KEPPLER.J 9 Region 3, Office of Director 2pp 26307 052 24% Ficha 50~456.84/08/16.8408300214

### V Operator Examinations

- 840Bi40372 Forwards proposed rev to "Requalification Program for Licensed Derators, Benior Operators & Senior Operators (Limited)," in response to NUREO-0737, Item I A 3 i MARCHALL, J 0 Commonwealth Edison Co 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26051 240 24X Fiche 50-000.84/08/07,8408140372
- --8408140389 "Requalification Program for L(censed Operators, Benior Operators & Senior Operators (Limited),"
  \* Commonwealth Edison Co. 84/07/19 10pp 26051 242 24X Fishs 30-000,84/08/07,8408140372
- 8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for staminers WALKER, R.D. Region 3, Office of Director 84/08/10 Michigan, Univ. of. Ann Arbor. MI 2pp. 26051 198 24% Fiche 50-000, 84/08/10,8408140426

- DECKET 50-458 RIVER BEND STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 840B030043 Ack receipt of 840621 ltr transmitting current description of QA program
  JDHNBON.E H Region 4. Office of Director 84/07/30 CAHILL.W J
  Gulf States Utilities Co ip 23907 030 24X Fiche 50~458,
  84/07/30, 8408030043
- B408060028 Notifies that final submittal re-containment issues raised by Humphreys will be provided by 841015 BCDMER. J E Oulf States Utilities Co 84/07/31 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 29933 182 24X Fiche 50-458,84/07/31,8408060028
- 8408160386 Forwards master lists for categories of NSBS & balance-ofplant equipment, including NSBS electrical equipment requiring qualification per 100FRSD 49 & Salsmic Category I safety-related NSBS equipment BODMER. J E Oulf States Utilities Co 84/07/31 DENTON, H R Defice of Nuclear Reactor Regulation. Director 88pp 26089 036 24X Fichs 50-458,84/07/31,8408160386
- ---B40B160390 "QE Plant Piping Analysis 11.Design Memo 150-96 " NGUYEN.H., YEH.N., SIMHA,U N. Genaral Electric Co. 84/01/13 223pp 26089 124 24x Fiche 50-458,84/07/31,8408160386
- 8408140421 Forwards final response to Sections 1 1.2 1.2 2 & 4 5 of Generic Ltr 83-28. "Required Actions Based on Generic Implications of Salem ATMS Events " Response to Sections 3 1 & 3 2 will be provided prior to fuel load BOOKER.J E Gulf States Utilities Co 84/08/03 EISCNHUT.D G Division of Licensing 21pp 26051 081 24X Fiche 50-458.84/08/03.8408140421
- --8408140423 "Vendor Equipment Technical Info Program," on Generic Ltr 83-28, Section 2 2 \* Nuclear Utility Task Action Committee 84/03/3i 47pp 24051 102 24X Fichs 50-458,84/08/03.8408140421
- 8408070110 Generic Ltr 84-19 to all licensess of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Generic Safety Issues" Syc list encl EISENHUT,D 9 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 30-000,84/08/06,8408070110
- 8408210490 Forwards operating shift experience tables, per DO Eisenhut 840531 request Info updates 840306 itr Shift advisors will not be used to augment operating staff BOOKER. J E Gulf States Utilities Co 84/08/13 DENTON, H R Office of Nuclear Reactor Regulation. Director 6pp 26/148 020 R4X Fiche 50-458,84/08/13,8408210490
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Bwc list and!
  RIBENHUT.D Q Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp. 26276 244 24X
  Fiche 50-000,84/08/20,8408200275
- 8408290338 Forwards request for addl info re 840416 application for license to store unirradiated fuel onsite Attempt will be made to process application by 841201 if info reviewed by 840724
  BIDINGER, G. H. Uranium Fuel Licensing Branch 84/08/22 BOOKER, J. E. Oulf States Utilities Co. 2pp. 26311 300 24X
  Fiche 50-458,84/08/22,8408290338
- B40B310132 Ack receipt of ltr re design & const problems at facility Addl info needed to investigate problems completely Telcon requested.

  JOHNSON,E H. Region 1, Office of Director 84/08/24 TAYLOR,H P Affiliation Not Assigned 1p 26322 108 24X Fiche 50-458, 84/08/24,8408310132
- C Utility Environmental Report (ER), amands & correspondence
- 8408240426 Interim Deficiency Rept DR-220 re license indications on Valve seats of cyclinder leads in standby diesel generators supplied by TDI Interim or final status rept will be submitted by 841101

  800KER, J E Gulf States Utilities Co 84/08/13 COLLINS, J T Region 4, Office of Director ip 26237 120 24X

  Fiche 50-458,84/08/13,8408240426

- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8408220325 DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF RIVER BEND STATION Docket No. 50-458 (Gulf States Utilities Company & Cajun Electric Power Cooperative)

  \* Division of Lirensing NUREG-1073 84/07/31 249pp 26199 001 24X Fiche 30-458.84/07/31,8408220325
- 8408200540 Forwards DES (NUREO~1073) & FR notice of availability W/o DES SCHWENCER, A Licensing Branch 2 84/08/09 CAHILL, W J Gulf States Utilities Co 2pp 26143 285 24X Fiche 50-498,84/08/09,8408200940
- --8408200546 Notice of availability of DES (NUREG-1073) Related correspondence SCHWENCER.A Licensing Branch 2 84/08/09 2pp 26143 287 24% Fiche 80-458,84/08/09,8408200540
- B40B200B52 Forwards DES (NUREC-1073) & FR notice of issuance & availability W/o DES

  GCHMENGER, A Licensing Branch 2 84/08/09 HIRSCH, A Environmental Protection Agency 2pp 26143 277 24X

  Fiche 50-458,84/08/09 8408200552
- 8408220164 Forwards DES & FR notice re facility operation for review & comment W/o DES
  SCHMENCER, A Licensing Branch 2 84/08/09 WDDD, J M Commerce,
  Dept of, Natl Desanographic & Atmospheric Administration 5pp
  26212 001 24X Fiche 50-458,84/08/09,8408220164
- 8408220434 Forwards DES (NUREG-1073) & FR notice of issuance Comments due 45 days after FR publication W/o DES SCHWENCER, A Licensing Branch 2 84/08/09 Louisiana, State of 1p 26209 336 24% Fiche 50-458,84/08/09,8408220434
- 8408230412 Ack recuipt of DES & submits no comment MIRANDMSKI.J A Agriculture, Dept of 84/08/17 SCHWENCER, A Licensing Branch 2 lp 26205 248 24% Fiche 90~458, 84/08/17, 8408230412
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8408070208 Notification of 840807-09 meetings w/util in St Francisville, LA to discuss instrumentation & controls SER open & confirmatory items MEIKAM, E. J. Licensing Dranch 2 84/07/24 SCHWENCER, A Licensing Branch 2 4pp 25757 050 24X Fiche 50-458,84/07/24,8408070208
- 8408080249 Notification of location change for 840807-09 meetings w/util % GE in San Jose, CA to discuss instrumentation % controls 8ER open & confirmatory items Meeting originally scheduled to be held in 8t Francisville, LA WEINKAM, E. J. Licensing Branch 2 84/07/24 SCHWENCER, A Licensing Branch 2 3pp 25978 316 24X Fiche 50-458, 84/07/24, 8408080249
- 8408060147 Forwards response to close out Item 17 of SER. Table 1 3, "Listing of Outstanding Issues" Changes will be incorporated in future FSAR amend BOOKER, J.E. Gulf States Utilities Co. 84/07/30 DENTON, H.R. Office of Nuclear Reactor Regulation Director 4pp 25923 304 24X Fiche 30-458.84/07/30,8408060147
- 8408140340 Forwards suppl to 840622 response to SER Confirmatory
  Item 3 re svc water tunnel Changes to FBAR. 8sction 2 5 4 11
  & Table 2 5-16 to be included in future amend encl
  BOOKER. J E Gulf States Utilities Co 84/08/09 DENTON, H R
  Office of Nuclear Reactor Regulation, Director 5pp 26042 319
  24X Fichs 50-458,84/08/09,8408140340
- 8408310172 Forwards responses to SER Outstanding Issue 18 & Confirmatory Item 59 & 840620 ltr re emergency action levels & emergency medical assistance program BOOKER.J E Oulf States Utilities Co 84/08/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 271pp 26316 001 24X Fiche 50-458,84/08/14,8408310172
- F Security, medical, amorgancy & fire protection plans
- 8408160511 Forwards IE Insp Rapt 50-458/84-12 on 840604-08 No violations or deviations noted JOHNSON,E H. Region 4. Office of Director 84/07/30 CAHILL.W J Gulf 8tates Utilities Co 2pp 26108 001 24X Fiche 50-458.84/07/30

- --8408160515 IE Insp Rept 50-458/84-12 on 840604-08 No violations or deviations noted Major areas inspected radiological environ monitoring program, including organization & mgt controls, training & qualifications & equipment % supplies BAER, R E , WISE, R , MURRAY, B Region 4, Office of Director 84/07/30 8pp 26108 003 24X Fiche 50-458,84/07/30,8408160511
- 8408310172 Forwards responses to SER Outstanding Issue 18 & Confirmatory Item 59 & 840620 ltr re emergency action levels & emergency medical assistance program BOGKER, J E Gulf States Utilities Co 84/08/14 DENTON, H R Office of Nuclear Reactor Regulation. Director 291pp 26316 001 24X Fiche 50-458,84/08/14.8408310172
- 8408240194 Forwards comments on Rev 2 to physical security plan submitted on 840907 Comments identify concerns re upgrading or changes to plan to satisfy regulatory requirements Encl withheld (ref 10CFR73 21) SCHMENGER: A Licensing Branch 2 B4/08/20 CAHILL, W. J. Gulf States Utilities Co. lp. 26227 354 24X Fiche 50~458,84/08/20. 8408240194
- B408270003 Forwards Insp Rept 50-458/84-20 on 840717-20 No violations or deviations observed JDHNSON, E H Region 4, Office of Director 84/08/20 CAHILL, W J Gulf States Utilities Co 2pp 26247 001 24X Fiche 50-458,84/08/20,8408270003
- --8408270007 Insp Rept 50-458/84-20 on 840717-20 No violations or deviations identified Major areas inspected security plan & implementing procedures, mgt. personnel & access control Details withheld (ref 10CFR73 21) EVANS, C A . HALL.R E . JAUDON J P Region 4, Office of Director 84/06/20 ip 26247 003 24X Fichs 50-458.84/08/20,8408270003

# @ Adjudicatory correspondence

- 8408010241 Forwards FSAR & environ rept OL stage.updated through 840701.per 840622 request W/o encls Related correspondence correspondence
  BOOKER, J. E. Gulf States Utilities Co. DSB 661 B4/0
  COTTER, B. P. Atomic Safety and Licensing Board Panel,
  25856 009 24X Fiche 50-458,84/07/12,8408010241
- B408010210 Notice of appearance in proceeding Certificate of Svc encl DAVIS,N G Louisiana, Btate of DSB 666 84/07/24 3pp 25856 053 24X Fiche 50-458,84/07/24,8408010210
- 8408010249 Requests that HJ Guste & ID Lindsey be removed from svc DAVIS.W G Louisiana, State of DSB 667 84/07/24 Dock Services Branch 1p 25856 005 24% Fiche 50-458,84/07/24, Branch 1 p Services B 8408010245
- 8408010238 Answers to first set of interrogatories & response to request for production of documents Certificate of Svc encl Related correspondence WATKINS, L B Joint Intervenors River Bend WATKINS, L B Wa L B DSS 634 84/07/24 Gulf States Utilities Co 10pp 25854 148 24X Fiche 50-458.84/07/24, 8408010258 Watkins
- 8408070390 Responds to 840706 questions re NRC board notification procedures, specifically Board Notification 84-062 Info contained in notification will be included in 88ER Related correspondence
  DEWEY, L S Hearing Branch 3 DSB 815 84/08/02 MCNEILL, J D Louisiana, State of 2pp 25945 267 24X Fiche 50-458.84/08/02, 8408070390
- B40B140458 Answers to applicant first set of interrogatories re Contentions I & 2 Related correspondence MCNELLIJ D Louisiena, State of D88 014 B4/08/13 Gulf States Utilities Co 7pp 26060 353 24X Fiche 50-458,84/08/13, States Uti 8408140458

# M Antitrust correspondence

- 8408270342 Forwards updates & suppls to 830715 ltr providing info showing significant changes since CP antitrust review which render info provided by util in 1781 outdated & deficient.

  SPIEGEL, G., GUTIMAN, D. Spiegel & McDiarmid 84/02/03 REGAN, W. 81te Analysis Branch 88pp 26289 247 24X Fiche 50-458, 84/02/03, 8408290342
- 8408090519 Expresses appreciation for assistance in antitrust DL review re dealings among bulk power suppliers in State of LA LA LAMBE, W. Site Analysis Branch 84/08/01 WILLIS, E. H. St Martinville, LA. 1p. 25983 107 24X Fichs 50-458, 84/08/01, Martinville, LA 8408090519

- 8408130488 Summary of 840802 telcon w/L Campisi re status of antitrust discussions/negotiations between city of Abbeville.LA & Gulf States Utils concerning possible transmission agreement Between two sys LAMBE.W Site Analysis Branch 84/08/07 Site Analysis Branch Ip 26040 361 24% Fiche 50-458,84/08/07,8408130488
- 8408130580 Expresses appreciation for insight into various relationships among power sys in State of LA re NRC antitrust OL review
  LAMBER W Office of Nuclear Reactor Regulation, Director 84/08/07
  CAMPIS. L Abbeville, LA 1p 26038 314 24X
  Fiche 50-458.84/08/07.8408130580
- 8408130609 Ack telcon in which insight into various relationships among power supply sys in State of LA helpful to antitrust CL review
  LAMBERW Site Analysis Branch 84/08/07 CAMPISICA J Abbeviller
  - 9ite Analysis Branch 94/08/07 CAMPISI.L J 26036 357 24% Fiche 50-498,84/08/07,8408:30607
- 8408150390 Discusses telcon w/Mayor E Willis of 8t Martinville.LA re allegations of util anti-competitive behavior City had difficulty obtaining wheeling rights over util transmission lines flower delivery agreement recently negotiated LAMBE.W Site Analysis Branch 84/08/07 Site Analysis Branch 1p 26105 010 24X Fiche 30-458,84/08/07,8408150390
- Q Inspection reports: IE Bulletins & correspondence
- B40B10010B Provides status rept rs IE Bulletin 83-06, "Noncenforming Matls Supplied by Tube Line Corp Facilities at Long Island City, Ny:Houston, TX & Caral Stream: IL" Stub ends found on flex houses for main steam & relief valve sys BOCKER, J E Gulf States Utilities Co 84/04/16 COLLINS, J T. Region 4, Office of Director 3pp 25991 011 24X Fiche 50-458,84/04/16,840B100108
- 8408160455 Ack receipt of 840525 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-458/84-08 Correctives actions will be reviewed during future insp JOHNSON,E H Region 4, Office of Director 84/06/20 CAHILL.W J Gulf States Utilities Co 1p 26107 280 24X Fiche 50-458, 84/06/20,8408160455
- --8408160457 Responds to NRC 840514 ltr re violations noted in IE Insp Rept 50-458/84-08 Corrective actions Procedure RBPP-8 1 amended to clearly state that reviewer w/a comments need not sign & return control form to licensing group WEIGAND.J 0 Gulf States Utilities Co 84/05/25 COLLINS.J T Region 4, Optice of Director 4pp 26107 281 24X Fiche 50-458,84/06/20,8408160455
- 8408100048 Submits final response to IE Bulletin B3-06. "Nonconforming Matls Supplied by Tube-Line Corp Facilities at Long Island City,NY,Houston,TX & Carol Stream,IL "No Tube Line matl supplied through TVA BODKER, J.E. Quif States Utilities Co. 84/07/02 COLLINS, J.T. Region 4, Office of Director 2pp 25990 182 24X Fiche 50-458,84/07/02,8408100068
- 8408070070 Forward IE Insp Rept 50-458/84-10 on 840501-31 No violations or deviations identified JOHNSON,E H Region 4. Defice of Director 84/07/10 CAR Quif States Utilities Co 2pp. 25972 227 24% Fiche 50-458,84/07/10,8408070070 84/07/10 CAHILL.W J 24X
- --B40B090095 IE Insp Rept 50-458/84-10 on B40501-31 No violations or deviations identified Major areas inspected reactor pressure vessel sys hydro activities, punch list program, IE bulletin followup & dishel generator testing CHAMBERLAIN, D. JAUDON, J. P. Region 4, Office of Director B4/07/05 10pp 25992 229 24X Fiche 50-458, 84/07/10, 8408090090
- 84082R0152 Forwards IE Insp Rept 50-458/84-04 on 840430-0504 No violations or deviations noted JOHN8DN.E H Region 1, Office of Director 84/07/17 CAHILL,W J Quif 8tates Utilities Co 2pp 86188 076 24X Fiche 50-458.84/07/19
- --8408220157 IE Insp Rept 50-458/84-06 on 840430-0504.No violations noted Major areas inspected radiation protection program
  including organization, mpt controls, staffing, qualifications,
  training programs & selected NUREG-0737 action items
  (CHANEY, H D , MURRAY, B. , JAUDON, J P Region I, Office of Director
  84/07/18 26pp 26188 078 24X Fiche 50-458, 84/07/19, 8408220152
- 8407250227 IE Inso Notice 84-57, "Operating Experience re Moisture Intrusion in Sefety-Related Electrical Equipment at Commercial Power Plants " Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/07/27. Consolidated Edison Co. of New York, Inc. 119pp. 25865-047. 24X Fiche 50-000,84/07/27.8407250229.

- 8408060412 Summary of 840501 meeting w/util.Rockwell & EG&G Idaho in Betheada.MD re recording of ultrasonic indications in piping sys susceptible to IGSCC & exams of reactor vessel feedwater inlet noriles

  WEINKAM.E J Licensing Branch 2 84/07/30 Licensing Branch 2

  12pp 25951 130 24X Fiche 50-458.84/07/30.8408060412
- 8408140230 Forwards IE Insp Rept 50-458/84-11 on 840625-29 No violations or deviations noted
  JOHNSON,E H Region 4, Office of Director 84/07/30 CAHILL,W J
  Gulf States Utilities Co 2pp 26106 220 24X
  Fiche 5D-458,84/07/30,8408160230
- --8408160237 IE Insp Rept 50-458/84-11 on 840625-29 No violations or deviations noted Major areas inspected operational staffing, personnel qualification & training MURPHY, M E , HARBUCK, C C , IRELAND, R E Region 4, Office of Director 84/07/27 8pp 26106 222 24X Fiche 50-458,84/07/30,8408160230
- 8408140511 Forwards IE Insp Rept 50-458/84-12 on 840404-08 No violations or deviations noted
  JCHNBON.E H Region 4, Office of Director 84/07/30 CAHILL, W J
  Gulf States Utilities Co 2pp 26108 001 24X
  Fiche 50-458.84/07/30.8408160511
- ---B408160513 IE Insp Rept 90-458/84-12 on 840404-08 No violations or deviations noted Major areas inspected radiological environ monitoring program, including organization & mpt controls, training & qualifications & equipment & supplies BAER, R E , NIBE, R , MURRAY, B Region 4, Office of Director 84/07/30 8pp 24108 003 24X Fiche 50-458.84/07/30,8408160511
- 8408270103 Forwards Insp Rept 50-458/84-17 on 840625-29 No violations or deviations noted
  JOHNSON,E H Region 4, Office of Director 84/07/31 CAHILL,W J
  Gulf States Utilities Co 2pp 26298 005 24X
  Fiche 50-458,84/07/31,8408290103
- --B408270108 Insp Rept 50-458/84-17 on 840625-29 No violations or deviations noted Major areas inspected const site tour, electrical terminations. GC personnel training records & GA procedures re pulling & termination of electrical cable BESS. JE. JAUDON. J.P., HUNNICUTT. D.M. Region 4, Office of Director 84/07/27 6pp 26278 007 24X Fiche 50-458,84/07/31,8408270103
- 8408200290 Forwards IE Insp Rept 50-458/84-13 on 840517-0616 No violations noted VIDIATIONS NOTED

  JOHNSON, E. H. Region 4, Office of Director B4/08/02 CAHILL, W.J.

  Gulf States Utilities Co. 2pp. 26140 092 24X

  Ficha 50-458,84/08/02,8408200290
- ---B408200292 IE Imsp Rept 50-458/84-13 on 840517-0614 No violations noted Major areas inspected licensee actions on previous findings, deficiency repts, site tours, electrical cable qualification, safety concern program & allegation review FARRELLAR E., JAUDON, J P. Region 4, Office of Director 7pp 26140 094 24X Fiche 50-458,84/08/02,8408200270 84/08/02
- 8408200316 Forwards IE Insp Rept 50-458/84-16 on 840709-15 & notice of Violation
  JOHNSON.E H Region 4, Office of Director 84/08/02 CAHILL, W J
  Quiff States Utilities Co 2pp 26140 114 24X
  Fiche 50-458,84/08/02,8408200316
- ---8408200321 Notice of violation from insp on 840709-15 \* Region 4. Office of Director 84/08/02 2pp 26140 116 24X Fiche 50-458,84/08/02,8408200316
- --8408200326 IE Insp Rept 50-458/84-16 on 840709-13 Noncompliance noted failure to effectively control design drawings & specs MCNETLL.W H. JAUDON, J. P. Region 4, Office of Director 84/08/02 App 24140 il8 24X Fiche 50-456,84/08/02.8408200316
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26068 001 24% Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Nutice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 24067 158 24X Fiche 50-000,84/08/06,8408010337
- 8408100033 Forwards GA Program Insp Rept 99700743/84-01 on 840821.for info & action Return receipt requested W/o encl.

  JCHNSON.E H Region 4, Office of Director 84/08/06 CAHILL,W J Gulf States Utilities Co 2pp 25970 168 24X

  Fiche 50-458.84/08/06.8408100033

- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Syc list encl JORDANIE L Division of Emergenry Preparedness & Engineering Response (Post 830103) 84/08/08 Cansolidated Edison Co of New York, Inc 120pp 26127 118 Q4X Fiche 50-000.84/08/08,8408070120
- 8408070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc B30103) B4/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24% Fiche 50~000.84/08/10.8408070376
- B40Bi40091 Ack receipt of B40A04 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-458/B4-02
  JOHNBON.E H Region 4, Office of Director B4/0B/10 CAHILL, W J
  Gulf States Utilities Co Ip 24044 338 24X Fiche 50-458.
- --8408140095 Responds to NAC 840522 itr re violations nated in IE Insp Rept 50-458/84-02 Corrective actions add1 review of other GC radiographs performed No discrepancies identified Util in full compliance as of 840664 CAHILL.W J Oulf States Utilities Co 84/06/04 COLLINS.J T Region 4, Office of Director 4pp 26044 359 24X Fichs 50-458.84/08/10,8408140091
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " JOBIODOOP IE Info Notice en 20.

  Svc list encl

  JURDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408100038 IE Info Notice 84-64. "BWR HPC1 Initiation Seal-In & Indication " Svc list encl Indication " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,840810003B
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl DRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/14 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021
- 840B100055 IE Info Notice 84~64. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JDRDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 R4X Fiche 50~000,84/08/17,8408100055
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 840B270003 Forwards Insp Rept 50-458/B4-20 on B40717-20 Ne violations or deviations observed
  JDHNSDN.E H Region 4, Office of Director B4/0B/20 CAHILL.W J
  GUIF States Utilities Co 2pp 26247 001 24X
  Fichs 50-49B.84/0B/20,8408270003
- --B408270007 Insp Rept 50-458/84-20 on 840717-20 No violations or deviations identified Major areas inspected security plan & implementing procedures, mgs. personnel & access control Details withheld (ref 10CFR73 21)

  EVANS.C A. HALL.R E., JAUDON.J P. Region 4, Office of Director B4/06/20 1p 26247 003 24X Fiche 30-458.84/08/20.8408270003
- 8408210142 IE Info Notice 84-68. "Patential Deficiency in Improperly Rated Field Hiring to Solenoid Valves " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc. 115pp 26329:008 24X Fiche 50-000,84/08/21,8408210142
- 9 Reportable occurrences, LERs & related correspondence
- 8408220317 Part 21 rept re failure of ITE-27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diode must be added Affected units listed DUVALL.D D Brown Boveri Corp (subs of Brown Boveri & Co . Ltd ) 84/03/13, DEYDUNG,R C Director's Office, Office of Inspection and Enforcement 3pp 26191 357 24X Fiche 50-000.84/03/13,8408220317
- 8405290062 Forwards "Investigation of Types AF & AE Piston Skirts "
  Rept supercedes 940227 submittal
  RAY.C L TDI (Transamerica Delaval, Inc.) Dwners Group 84/05/24
  DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp
  24690 045 24% Fiche 50-000.84/05/24.8405270062

- 'Investigation of Types AF & AE Piston Skirts " Analysis Associates FAAA-84-2-14 84/05/23 120pp 50-000, 84/05/24, 8405270062
- wards "Evaluation of Emergency Diesel Generator at Shoreham & Grand Gulf Nuclear Power
- II (Transamerica Delaval, Inc.) Owners Group 84/05/24 Office of Nuclear Reactor Regulation, Director 2pp 24X Fiche 50-000,84/05/24,8405290179
- wards repts received by BNWL & consultants directly from whers Group at 840622 meeting Draft "Overview of is & Recommendations re Main Propulsion Engines" encl
- " encl
  M Battelle Memorial Institute, Pacific Northwest
  84/06/28 MILLER, M Division of Licensing 158pp
  24X Fiche 50-000,84/06/28,8408060405
- wards info addressing open items identified in NRC/BNWL/ enerator Owners Oroup 840622 meeting I (Transamerica Delaval: Inc.) Owners Group 84/07/10 Director's Office Office of Inspection and 43pp 25933 133 24X Fiche 50-000.84/07/10,
- al Deficiency Rept DR-146 re multipole circuit breakers Electrical Products Initially reported on rout breakers supplied were determined ndition not reportable under 10CFR50 55(e) Gulf States Utilities Co 84/07/16 COLLINS
- al Deficiency Rept DR-171 re flow adjustment subassembly 4 Robertshaw thermostatic flow control valves on cooling sys for TDI standby diesel generators t reportable under 10CPR30 35(e) Quif States Utilities Co 84/07/16 COLLING. J T fice of Director 1p 25866 267 24X 184/07/16.8408010012
- Jards program plan for evaluating & testing TDI standby stors Program includes all recommended actions a Group & TDI Changes to number of start tests & ts requested Gulf States Utilities Co 84/07/19 DENTON, H R clear Reactor Regulation, Director 43pp 25882 229 -458,84/07/19,8408020025
- erim Deficiency Rept DR-153 re orifice plates supplied abrols Co & mfg by Allegheny Ludlum Steel Corp minless Steel Co Next rept will be provided by
- Gulf States Utilities Co 84/07/24 COLLINS, J T fice of Director. ip 25974 333 24X 84/07/24-8408080199
- al Deficiency Rept DR-165 re traceability of copper bus by Southern Metals Corp & Gulf Coast Supply f to Category I & acceptable in Class IE idition not reportable under 10CFR50 55(e) Gulf Btates Utilities Co 84/07/25 COLLINS.J T fice of Director ip 25975 163 24X 84/07/25.8408080471
- irim Deficiency Rept DR-184 re shop weld on support lied by BF Shaw Next rept will be supplied by
- Oulf States Utilities Co 84/07/26 COLLINS, J T Fire of Director. 1p. 25752 038 24X 84/07/26-8408070529
- Jards "Emergency Diesel Generator Auxiliary Module ig & Termination Qualification Review " Addl .o BNHL
- .0 SNM. ((Transamerica Delaval, Inc.) Owners Group B4/07/27 Office of Nuclear Reactor Regulation, Director 2pp '4X Fiche 50-000,84/07/27,8408060102
- mergency Diesel Generator Auxiliary Module Control Wiring on Qualification Review." Hebster Engineering Corp 84/07/31 36pp 25932 139 RO-000.84/07/27.8408060102
- rim Deficiency Rept DR-212 re battery cell spacer matl Pould Co Next rept will be provided by B40824 Gulf States Utilities Co 84/07/27 COLLINS, J T Tice of Director 1p 25953 032 24X B4/07/27,8408070520

- 8408080236 Interim Deficiency Rept DR-140 re TDI standby diesel generator fuel oil piping & header assembly Next rept will be pravided by 841011 Field GC insp of generator IEGS#E0IB will be performed in near future BODKER. J E Gulf States Utilities Co 84/07/27 COLLINS, J T Region 4. Office of Director ip 25974 358 24X Fiche 50-458.84/07/27.8408080236
- 8408140554 Interim Deficiency Ropt DR-215 re uninterruptible power supply inverters supplied by Elgar Corp Interim or final rept will be submitted by 840913 BODKER. J E Gulf States Utilities Co 84/07/30 COLLINS. J T Region 4. Office of Director 1p 24064 121 24X Fiche 50-458,84/07/30,8408140554
- B40Bi50177 Interim Deficiency Rept DR-188 re hubs on socket-weld flanges supplied by Guyon Alloys for instrument lines on main steam isolation sys Next rept will be provided by B40B27 B40KER, J E Gulf States Utilities Co B4/07/30 COLLINS, J T Region 4, Office of Director 1p 26073 353 24X Fiche 50-458,84/07/30.840Bi50177
- 8408150385 Final Deficiency Rept DR-137 re defective springs in Pacific Scientific Models PSA-1 & PSA-3 mechanical shock arrestors Testing indicated sufficiently sound springs Item not reportable under 10CFR50 55(e) BODKER, J E Gulf States Utilities Co 84/07/30 COLLINS, J T Region 4, Office of Director ip 26078 001 24X Fiche 50-458,84/07/30,8408150385
- 8408130704 Interim Deficiency Rept DR-213 re pressure setting on safety relief valves for air start sys air receivers on HPCS dissel generator supplied by GE Next rept will be provided by 841030 BOUKER, JE Gulf States Utilities Co 84/07/30 COLLINS, JT Region 4, Office of Director ip 26079 007 24X Fiche 50-458,84/07/30,8408150704
- 8408190707 Interim Deficiency Rept DR-214 re gauges on seating surface in stainless steel overlay of cover on feed check valve supplied by Atwood & Morrill Next rept will be provided by 840705 BDOKER. J E Gulf States Utilities Co 84/07/30 COLLING, J T Region 4, Office of Director 1p 26079 101 24X Fiche 50-458.84/07/30.8408150707
- 840B220504 Corrected final Deficiency Rept DR-137 re potentially defective springs in Pacific Scientific PSA-1 & PSA-3 mechanical shock arrestors Snubbers rotated & requalified by vendor Condition not reportable under 10CFR50 55(e) BOOKER. J E Gulf Blates Utilities Co E4/07/30 COLLINS. J T Region 4, Office of Director ip 26196-011 24X Fiche 50-458.84/07/30.840B220504
- 8408150152 Interim Deficiency Rept DR-186 re conduit plugs in transmitters supplied by Rosemount Next rept will be provided by 840815 BOOKER, J E Gulf States Utilities Co 84/07/31 COLLINS, J Region 4, Office of Director 1p 26075 358 24X Fiche 50-458,84/07/31,8408150152
- 8408190162 Interim Deficiency Rept DR-187 re CRD hydraulic lines Next rept will be provided by 840919 BOOKER, J.E. Gulf States Utilities Co 84/07/31 COLLINS, J.T. Region 4. Office of Director 1p 26075 354 24X Fichs 90-458,84/07/31,8408130162
- 8408060324 Forwards "Design Review of Elliott Model 650 Turbockarger Used on TD DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sots " RAY, C L TDI (Transamerica Delaval, Inc.) Dwhers Group 84/08/01 DENTUN, H R Defice of Nuclear Reactor Regulation, Director 2pp 25927 064 24% Fiche 50-000,84/08/01.8408060324
- 8408150308 Interim Deficiency Rept DR-154 re high voltage cable terminations Next rept will be provided by 840920 BOOKER, J E Gulf States Utilities Co 84/08/02 COLLINS, J T Region 4, Defice of Director 10 26075 360 24K Ficher 50-458.84/08/02.8408150308
- B40B150491 Final Deficiency Rept DR-149 re groundwire defect in switchgear supplied by Brown-Boveri Electric Single undetected ground would not affect do sys operation Item not reportable per 10CFR30 55(a) BOCKER, J E Gulf States Utilities Co 84/08/03 COLLINS, J T Region 4, Office of Director 19 26079, 099 24X Fiche 50-458,84/08/03.8408150491
- 8408160194 Interim Deficiency Rept DR-216 re electrical genetrations supplied by Conax Corp Next rept will be provided by 841009 BCOMER.J E Gulf States Utilities Co 84/08/06 COLLINS.J T Region 4. Office of Director ip 26106 337 24% Fiche 50-458.84/08/06.8408160194

- 60242 Interim Deficiency Rept DR-145 re design mod to reactor g beam welded to embedment plate Next rept will be sydded by 840928
  NKER.J.E. Quif States Utilities Co. 84/08/06 COLLINS.J.T. iion 4. Defice of Director 1p. 26106 208 24x
  the 50-458.84/08/06,8408160242
- 220511 Interim Deficiency Rept DR-218 re piston rods in Brown veri Electric Type 5HK circuit breakers Next rept will be hmitted by 841024
  DKER J.E. Gulf States Utilities Co. 84/08/08 COLLINS, J.T. gion 4. Office of Director ip 26196 008 24X
  che 50-458.84/08/08.8408220511
- 230538 Interim Deficiency Rept DR-217 re bolting matts supplied by rdinal Industrial Products Next rept will be submitted by 1017
- 1017
  IOMER, J E Gulf States Utilities Co. 84/08/08, COLLINS, J T gion 4, Diffice of Director 19 26212 352 24X che. 80-458, 84/08/08, 8408230538
- 3160394 Forwards "Design Review of Engine Base & Bearing Caps for of DBRV-14 Diesel Engines"

  Ay.C.L. TDI (Transamerica Delaval. Inc.) Guners Group 84/08/10 ENTON.H R DPfice of Nuclear Reactor Regulation, Director 2pp 5091
- 408140403 "Design Review of Engine Dase & Bearing Caps for TDI DSRV-16 Diesel Engines "
- # Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp. 26091:149. 24X Fiche 50-000,84/08/10,8408160394
- 8220305 Interim Deficiency Rept DR-148 re interpretation of M3 alding procedure, Next rept will be submitted by 841018 DOMER, J E gulf States Utilities Co. 84/08/10 COLLING, J T agion 4. Office of Director. 1p 26196 010. 24X iche. 50-458.84/08/10.8408220505
- is240115 Forwards SER re TDI Owners Group program plan. SER addresses esign review/quality revalidation program testing & insp. isint & surveillance & sets forth requirements for operation rior to completion of program plan ISENHUT. D. G. Division of Licensing 84/08/19 GEORGE, J. B. TDI 'Transamerica Delavai, Inc., ) Gwners Group 1p. 26255 194 24X Fiche 50-000,84/08/13,8408240115.
- 3408240157 Safety svaluation of TDI Duners Group program plan Based on BNML avaluation.plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI angines for nuclear svc.

  \*\*\* NRC ~ No Detailed Affiliation Given 84/08/13 21pp 26255.175. 24X Fiche: 50-000.84/08/13.8408240115.
- OS240310 Interim Deficiency Rept DR-221 re cylinder head fire dack wall thickness of standby diesel generators Interim or final status rept will be provided by S41101 BOOKER.J E Gulf States Utilities Co 84/08/13 COLLINS.J T Region 4. Office of Director ip 26236 321 24X Fiche.50-458.84/08/13.8408240310
- OB240404 Interim Deficiency Rept DR-219 re design loads of conduit supports Interim or final status rept will be provided by 84:101
  BOOKER, J E Quif States Utilities Co. 84/08/13 COLLINS, J T. Region 4. Office of Director Ip. 26:237.105 24X
  Fiche: 50-458.84/08/13:8408240404.
- 108240426 Interim Deficiency Rept DR-220 re license indications on valve seats of cyclinder leads in standby diesel generators supplied by TDI Interim or final status rept will be submitted by 891101 BOOKER.JE. Quif States Utilities Co. 84/08/13 Region 4. Office of Director ip 26237 120 24X Fiche.80~458.84/08/13:8408240426 COLLINB, J T.
- 408140375 Forwards "Design Review of Elliott Model 909 Turbocharger Used on TDI D8R-48 & D8RV-16 Emergency Diesel Generator Sets," representing final GA verified rept Addl copy forwarded to BNML, per NRC request.
  RAY: C.L. TDI (Transamerica Delaval: Inc.) Dwners Group 84/08/14 DENTON: HR Office of Nuclear Reactor Regulation, Director. 2pp 26088'163. 24X Fiche 50-000:84/08/14.8408160395
- -8408160397 "Design Review of Elliott Model 900 Turbocharger Used on TBI DBR-48 & DBRV-16 Emergency Diesel Generator Sets "Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp. 26088 165. 24% Fiche: 50-000.84/08/14:8408160395

- 8408280408 Interim Deficiency Rept DR-126 re standby 480-valt load ctrs supplied by Powell Electric Next rept will be provided by 841030
  - BOOKER, J. E. Oulf States Utilities Co. 84/08/13 COLLINS, J. T. Region 4, Office of Director 1p. 26282 [08 24X] Fiche 50-488,84/08/15,8408280408
- 8408280458 Final Deficiency Rept DR-183 re contact configurations of 94AX relays supplied by Oould-Brown Boveri Condition not reportable under 10CFR50 55(e) requirements BOOKER, J E Gulf States Utilities Co 84/08/15 COLLING, J T Region 4. Office of Director ip 26282 040 24X Fiche 50-458,84/08/15,8408280458
- B40B280414 Interim Deficiency Rept DR-186 re Rosemount Model 1153 series transmitters Next rept will be provided by 840713 BODKER, JE Bulf States Utilities Co. 84/08/16 COLLINS, JT Region 4, Office of Director ip 26282 113 24X Fichs 50-458,84/08/16:8408280414
- 8408280416 Interim Deficiency Rept DR-222 re relocation of Div III 125-volt panel Next rept will provided by 841025 BOOKER, J E Gulf States Utilities Co 84/08/16 COLLING, J T Region 4, Office of Director ip 26282 114 24X Fiche 50-458,84/08/16,8408280416
- 8408280446 Interim Deficiency Rept DR-184 re shop weld in support trunion supplied by BF Shaw Next rept will be submitted by 840849. J E Gulf States Utilities Co 84/08/16 ( Region 4. Office of Director 1p 26282 140 24x Fiche 50-458.84/08/16.8408280446 COLLINS, J T
- 8408280428 Interim Deficiency Rept DR-177 re neutron monitoring systable supplied by Rockbestos Cable Co.Next rept will be provided by 840928
  BOOKER, J E Gulf States Utilities Co 84/08/17 COLLINS, J T Region 4. Office of Director 1p 26282 127 24X
  Fiche 50-458,84/08/17,8408280428
- 8408300343 Final Deficiency Rept DR-138 re ITE-Gould Type 2150 overload relays initially reported on 840720 W/o stated encl BOOKER, J E Gulf States Utilities Co 84/08/20 COLLINS. J T Region 4. Office of Director 1p 26308 342 24X Fiche 50-458.84/08/20,8408300343
- B40B3100B7 Interim Deficiency Rept DR-223 re installation of mechanical anubbers supplied by Pacific Scientific Next rept will be provided by 841024 BOOKER, J E Gulf States Utilities Co 84/08/20 COLLINS, J T BOOKER, J E Gulf Btates Utilities Co 84/08. Region A. Office of Director 1p 26334 242 Fiche: 30-458.84/08/20:8408310087 244
- 8408300494 Interim Deficiency Rept DR-224 re main steam piping thermal movement analysis supplied by GE Next rept will be provided by 841115 by 841115 BOOKER.J E Gulf States Utilities Co 84/08/22 Region 4. Office of Director 1p 26314 009 2 Fichs 50-458.84/08/22.8408300494 COLLINB, J T
- 8408300307 Interim Deficiency Rept DR-225 re motor torque for motor operated valves supplied by Velan Engineering, Ltd Next rept will be provided by 841026.
  BOOKER, J E Gulf States Utilities Co 84/08/22 COLLINS, J T Region 4, Office of Director ip 26314 068 24X Fichs 50-458,84/08/22,8408300507.
- 8408290179 Forwards response to 840723 request for add1 info on repts submitted by TDI Diesel Generator Owners Group. RAY, C. L. TDI (Transamerica Delaval, Inc.) Owners Group 84/08/23. BERLINGER, C. Office of Nuclear Reactor Regulation, Director 12pp 26289:221 24X Fiche 50-000,84/08/23,8408290179
- DOCKET 30-459 RIVER BEND STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8408030043 Ack receipt of 840621 ltr transmitting current description of GA program
  JOHNBON E H Region 4. Office of Director 84/07/30 CAHILL.W J
  QUIF States Utglittee Co ip 25907 030. 24% Fiche 50-458.
  84/07/30,8408030043

- F Security, medical, emergency & fire protection plans
- @408240174 Forwards comments on Rev 2 to physical security plan submitted on 840307 Comments identify concerns re upgrading or changes to plan to satisfy regulatory requirements Encl withheld (ref 10CFR73 21) SCHMENCER, A Licensing Branch 2 84/08/20 CAHILL, W J Gulf States Utilities Co 1p 26227 354 24X Fiche 50-458,84/08/20,8408240174

#### G Adjudicatory correspondence

- 8408010210 Notice of appearance in proceeding Certificate of Svc encl DAVIS.W 0 Louisiana. State of DSB 666 84/07/24 3pp 25856 053 24X Fiche 50-458,84/07/24.8408010210
- B408010245 Requests that MJ Guste & ID Lindsey be removed from svc list
  DAVIB, W G Louisiana, State of DSB 667 84/07/24 Ducketing & Services Branch 1p 25836 003 24X Fiche 50-458,84/07/24, 8408010245
- 8408010258 Answers to first set of interrogatories & response to request for production of documents Certificate of Svc encl Related correspondence MATKINS.L B Joint Intervenors River Bend WATKINS.L B Watkins.L B D98 654 84/07/24 Gulf States Utilities Co 10pp 25854 168 24x Fiche 50-458.84/07/24.8408010258
- B40B070390 Responds to 840706 questions re NRC board notification procedures, specifically Board Notification 84-062 Info contained in notification will be included in SSER Related correspondence DEWEY.L S Hearing Branch 3 DSB 815 B4/08/02 MCNEILL,J D Louisiana, State of 2pp 25945 267 24X Fiche 50-458.84/08/02, 8408070390
- 8408140458 Answers to applicant first set of interrogatories re Contentions 1 & 2 Related correspondence MCNEILL.J D Louisiana, State of DSB 014 64/08/13 Gulf States Utilities Co 7pp 26060 353 24X Fiche 50-458.84/08/13, 8408140449

### M Antitrust correspondence

- 8408290342 Forwards updates & suppls to 830915 ltr providing info showing significant changes since CP antitrust review which render info provided by util in 1981 outdated & deficient BPIEGEL, G, GUTIMAN, D Spiegel & McDiarmid 84/02/03 REGAN, W Site Analysis Branch 88pp 26289 247 24X Fiche 50-458, 84/02/03, 8408290342
- 8 Reportable occurrences, LERs & related correspondence
- B405290062 Forwards "Investigation of Types AF & AE Piston Bkirts"
  Rept supercedes B40227 submittal
  RAY, C L TDI (Transamerica Delaval, Inc.) Owners Group B4/05/2
  DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp
  24690 045 24X Fiche 50-000,84/05/24,8405290062
- --8405270075 "Investigation of Types AF & AE Piston Skirts "
  \* Failure Analysis Associates FAAA-84~2-14 84/05/23 120pp
  24X Fiche 50-000,84/05/24,8405270062
- 8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations" RAY, C L TDI (Transamerica Delaval, Inc.) Owners Group 84/05/24 DENTON, M R Office of Nuclear Reactor Regulation, Director 2pp 24692 090 24% Fiche 50-000,84/05/24.8405270179
- B408060405 Forwards repts received by BNUL & consultants directly from FAAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts. Analysis & Recommendations re Main Propulsion Engines M/V Columbia" oncl
  ALZHEIMER, J M Gattelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER.M Division of Licensing 158pp 25926 173 24X Fiche 50-000.84/06/28,8408060405
- 8408050050 Forwards info addressing open items identified in NRC/BNML/TDI Diesel Generator Owners Oroup 840622 meeting RAY.C. TDI (Transamerica Delaval, Inc.) Owners Group 84/07/10 BERLINGER,C Director's Office, Office of Inspection and Enforcement 43pp 25935 133 24% Fiche 50-000.84/07/10, 84080400590

- B40B060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNML RAY.C L TDI (Transmerica Delaval, Inc.) Dwners Group 84/07/27 DENTON:H R Office of Nuclear Reactor Regulation, Director 2pp 25932 137 24X Fiche 50-000.84/07/27.8408060102
- ~-8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review" s Stone & Webster Engineering Corp 84/07/31 36pp 25932 139 24% Fiche 50-000 84/07/27. 8408060102
- 8408060324 Forwards "Design Review of Elliott Model 65G Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Dissel Generator Sets "
  RAY.C L TDI (Transamerica Delaval, Inc.) Gunera Group 84/08/01 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 23927 044 24x Fiche 50-000,84/08/01,8408060324
- 8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DBRV-16 Diesel Engines" RAY.C L TDI (Transamerica Delava). Inc.) Owners Group 84/08/10 DENTON.R R Office of Nuclear Reactor Regulation, Director 2pp 26091 147 24X Fiche 50-000,84/08/10,8408160394
- --B408160403 "Design Review of Engine Base & Bearing Caps for TDI DERV-16 Diesel Engines " \* Failure Analysis Associates FAAA-84-6-53 84/08/31 44p 26091 147 24X Fiche 50-000,84/08/10,8408160374
- B408240115 Forwards SER re TDI Owners Oroup program plan SER addresses design review/quality revalidation program testing & insp. maint & surveillance & sets forth requirements for operation prior to completion of program plan EISENHUTD 0 Division of Licensing 84/08/13 GEORGE, J B TDI (Transamerica Delaval, Inc.) Owners Group 1p 26255 174 24X Fiche 50-000,84/08/13,8408240115.
- --B40B240157 Safety evaluation of TDI Owners Group program plan Based on INNL evaluation, plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc \* NRC No Datailed Affiliation Given B4/08/13 21pp 26255 175 24X Fiche 50-000,84/08/13,840B240115
- 8408160395 Forwards "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DBRV-16 Emergency Diesal Generator Sets." representing final OA verified rept Addl copy forwarded to BMAL.per NRC request RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group 84/08/14 DENTON.HR Office of Nuclear Reactor Regulation. Director 2pp 26088 163 24X Fiche 50-000.84/08/14.8408160395
- --8408160397 "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DBRV-16 Energency Dissel Generator Sets "Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp 26088 165 24X Fiche 30-000.84/08/14,8408160395
- 8408290179 Forwards response to 840723 request for add1 info on repts submitted by TD1 Diesel Generator Duners Group RAY: C. TD1 (Transamerica Delaval. Inc.) Duners Group 84/08/23 DERLINGER, C. Office of Nuclear Reactor Regulation, Director 12pp 26289 221 24X Fiche 50-000, 84/08/23, 8408290179
- DOCKET 50-460 WPPSB NUCLEAR PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- 8408080288 Summary of 840712 meeting w/B&W Gwners Group re non-nuclear instrumentation sys status Attendance list & viewgraphs encl KADAMBI.P Operating Reacturs Branch 4 84/07/27 Operating Reacturs Branch 4 84/07/27 Operating Reacturs Branch 4 34pp 25978 228 24X Fiche 50-000.84/07/27, 8400806288
- B40B0B01/5 Forwards proposed agenda for 840906 meeting to discuss status & project completion plans.per B40711 telcon Proposed supply sys role, ongoing programs & activities & concepts for acceptance of work will be discussed SORENGEN, 0 C Washington Public Power Supply System B4/07/31 EISENHUT, D O Division of Licensing 3pp 25959 001 24X Fichs 50-460.84/07/31.8408080175
- 840B170031 Forwards supplemental response to Generic Ltr 83-28 re Salem ATMS events Util investigating possibility of modifying existing GE AK breakers or replacing breakers oddifferent device SORENSEN.9 C Hashington Public Power Supply System 84/08/10 ADENBAN.E G Licensing Branch 4 4pp 26119 079 24X Fiche 50-460.84/08/10.8408170031

# Adjudicatory correspondence

- B02000B Advises that time for Commission to review ALAB-771 expired ammission declined review Decision became final agency ction on 840725 Served on 840801 HILK, S J Defice of the Secretary of the Commission DS8 706
- 4/08/01 Atomic Safety and Licensing Board Panel 24% Fiche 50-460,84/08/01,8408020008 5883 059

# Reportable occurrences. LERs & related correspondence

- 15290062 Forwards "Investigation of Types AF & AE Piston Skirts "
  lept supercedes 840227 submittal
  RAY.C L. TDI (Transamerica Delaval, Inc.) Duners Group B4/05/2:
  JENTON.H R Dffice of Nuclear Reactor Regulation, Director 2pp
  24690.045 24X Fiche 50-000,84/05/24,8405270062
- 3405270075 "Investigation of Types AF & AE Piston Skirts \* Failure Analysis Associates FAAA-84-2~14 84/05/ 24X Fiche 50-000-84/05/24, 8405270062 84/05/23 120no
- 05290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Bhoreham & Grand Gulf Nuclear Power
- Stations
  RAY, C. L. TDI (Transamerica Delaval, Inc.) Owners Group B4
  DENTON, H.R. Office of Nuclear Reactor Regulation, Director
  24692 090 24% Fiche 50~000.84/05/24.8405290179 B4/05/24
- 08060405 Forwards repts received by BNML & consultants directly from FaAA & TD1 Owners Group at 840622 meeting Draft "Overview of Repts Analysis & Recommendations to Main Propulsion Engines
- NAV Columbia" encl ALZHRIMER.J M Battelle Hemorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER,M Division of Licensing 1 25726 173 24% Fiche 50-000,84/06/28,8408060405
- |OBO60000 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Generator Duners Group 840622 meeting RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group 84/07/10 BERLINGER.C Director's Office, Office of Inspection and Enforcement. 43pp 25933 133 24X Fiche 50-000,84/07/10, 8408060000
- 408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNM. RAY.C L TDI (Transamerica Delaval, Inc.) Duners Group 84/07/27 DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 25932 137 24% Fiche 50-000.84/07/27,8408060102
- -8408060138 "Emergency Diesel Generator Auxiliary Modula Control Wiring & Termination Qualification Review" \* Stone & Webster Engineering Corp 84/07/31 36pp 25932:139 24X Fiche 50-000.84/07/27.8408040102
- 408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DRRY-12-4 & DRRY-20-4 Emergency Diesel Generator Sets " RAY.C L TDI (Transamerica Delaval, Inc.) Dwners Group 84/08/01
- DENTON: H R Office of Nuclear Reactor Regulation, Director 24X Fiche 50-000, 84/08/01, 8408060324
- 140B200317 Interim deficiency rept re defective welds on Kaman Instrumentation redisation monitor display panels Initially reported on 840710 Caused by insufficient spot welds on some local indication & control units ROUT.R W Washington Public Power Supply System 84/08/07 HARTIN, J B Region 5. Office of Director 2pp 26140 085, Fiche 50-460.84/08/07.8408200317 2pp 26140 085, 24X
- 340B160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines" RAY.C L TDI (Transamerica Delaval, Inc.) Guners Group 84/08/10 DENTEN, HR Office of Nuclear Reactor Regulation, Director 2pp 26091 147 24X Fiche. 50-000, 84/08/10, 840B160394
- --B408160403 "Design Review of Engine Base & Bearing Caps for TD1 DSRV-16 Diesel Engines" \* \* Failure Analysis Associates FAAA-84-6-53 84/08/31, 44|26091 149, 24% Fiche 50-000.84/08/10,8408160394 64/08/31, 44pp
- B408240ii5 Forwards BER re TDI Owners Group program plan SER addresses design review/quality revalidation program testing & insp. maint & surveillance & sets forth requirements for operation prior to completion of program plan EIBENHUT.D © Division of Licensing 84/08/13 GEORGE.J B TDI (Transamerica Delayal. Inc.) Owners Group ip 26255-194. 24X Fichs: 50-000-84/08/13, 8408240115

- --8408740157 Safety evaluation of TDI Clumers Group program plan Based on BNWL evaluation, plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc \* NRC - No Detailed Affiliation Given 84/08/13 26255 195 24X Fiche 50-000,84/08/13,8408240115
- 840Bi60395 Forwards "Design Review of Elliott Model 906 Turbocharger Used on TDI DBR-48 & DBRV-16 Emergency Diesel Generator Sets." representing final GA verified rept Addl copy forwarded to BNWL.per NRC request RAY.C L TDI (Transamerica Delaval, Inc.) Dwners Group 84/08/14 DENTON, HR Dffice of Nuclear Reactor Regulation, Director 2pp 26088 163 24X Fiche 50-000,84/08/14,8408160395
- --B408160397 "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets " \* Failure Analysis Associates FAAA-84-5-7 B4/07/31 61pp 260BB 165 24X Fiche 50-000.84/0B/14,8408160395
- 8408290179 Forwards response to 840723 request for addl info on repts submitted by TDI Diesei Generator Guners Group RAY, C. L. TDI (Transamerica Delaval, Inc.) Guners Group 84/0 BERLINGER.C. Office of Nuclear Reactor Regulation, Director 26287 221 24X Fiche 50-000.84/08/23,8468290179

### DOCKET SO-461 CLINTON POWER STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 8408310156 FQIA request that SECY-94-29 & encl of PL William 840303 ltr re functional description of safety parameter display sys be placed in PDR DDVE.K Affiliation Not Assigned 84/04/12 FELTON, J M Division of Rules and Records ip 26352 001 24X Fiche 50-461.84/04/12. of Rules and Records ip 8408310156
- 8408130152 Summary of 840628 meeting w/util.Bechtel,Schiff Hardin, Sargent & Lundy,Newman & Holtringer & State of IL in Bethesda,MD re proposed IDVP Forwards transcript of meeting minutes .B L Licensing Branch 2 84/08/01 Licensi 26034 154 24X Fiche 50-461,84/08/01,8408130152
- --8408130156 Transcript of 840628 open meeting in Washington.DC refacility IDVP Pp 1-131 Supporting documentation encist Commissioners 84/06/28 175pp 26034 158 24X Fiche 50-461.84/08/01.8408130152
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Buppl i to NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl EIEENHUT.D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26127 238 24X Fiche 50-000,84/08/06,8408070110
- B40B1000B9 Forwards "Generic 300 Start Tests for Electro-Mative Div of General Motors (EMD) Model EMD-649E4 Diesels" & "Production Test," to substantiate HPCS diesel generator reliability, per B40613 ltr I Illinois Power Co 64/08/05 SCHWENCER, A Licens 2pp 25995 025 24% Fiche 50-461,84/08/06.8408100089 HERBORN, D I
- --B40B100101 "Generic 300 Start Tests for Electro-Motive Div of General Motors (EMD) Model EMD-64564 Diesels "
  FALTER, H W Morrison-Knudsen Co , Inc 84/05/10 152pp 25975 027 24% Fiche 50-461,88/08/06.8408100089.
- --8408100106 "Production Test "

  \* Stewart & Stevenson Services FTR-75744-1 | 25975 178 24X Fiche \$0-461,84/08/06.8408100089 84/08/06 175pp
- 8408130120 Requests rev to 840606 GA program submittal to comply w/paragraph (3)(ii) of 10CFR50 55(f) requirement to identify each change.reason for change 5 basis for concluding that change satisfies 10CFR50.App B criteria SPESSASD.R L Region 3. Office of Director 84/08/06 GERSTNER.W C lows Electric Light & Power Co 2pp 26007:333 24X Fiche 50-461,84/08/06.8408130120
- 8408240303 Forwards request for addl info re safety parameter display sys Response requested within 60 days to allow adequate time to perform onsite audits before plant licensing SCHWENCER.A Licensing Branch 2 84/08/17 HERBORN D I Illinois Power Co 8pp 26237 352 24X Fiche 50-461.84/08/17.8408240303

- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re-scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl questions 5vc 11st encl EISENHUT.D & Division of Licensing 84/08/20 Edison Co of New York. Inc 17pp 26276 244 Fiche 50-000.84/08/20.8408200275 84/08/20 Consolidated 24 Y
- 8408270135 Forwards Bechtel response to NRC comments re Rev 1 to independent design review program plan Concurs w/Bechtel suggestion that response be considered as immediately effective amend to plan HALL. D P Illinois Power Co. 84/08/22 SCHWENCER, A Licensing Branch 2 Sp. 26245 205 24X Fishe 50-461,84/08/22,8408270135

- 8408280074 Application to amend CPPR-137, extending latest completion date for const of facility to 861001, per 10CFR30 55(b)

  Beries of stop work orders & recovery programs initiated to implement corrective action constitutes basis for request HALL, D P Illinois Power Co 84708/22 DENTON, H R Dffice of Nuclear Reactor Regulation, Director 4pp 26261 180 24X Fiche 50-461.84/08/22.8408280094
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- 8406190045 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CLINTON POWER STATION, UNIT NO 1 Docket No 50-461 (Illinois Pawer Company, et al)

  \* Division of Licensing NUREG-0853 803 84/05/31 40 25025 274 24X Fiche 50-461,84/05/31,8406190043
- 8408140351 Forwards response to NRC 840522 request for add1 info re SER Outstanding Issue 7 & Confirmatory Issues 13 & 71 re suppression pool hydrodynamics HERBORN:D I Illinois Power Co 84/08/08 SCHWENCER, A Licensing Branch 2 6pp 26041 044 24X Fiche 50-461,84/08/08,8408140351
- F Security, medical, emergency & fire protection plans
- 8408210470 Forwards Preoperational Physical Protection Insp Rept 50-461/84-22 on B40724-27 No noncompliance identified AXELSON, W L. Region 3. Office of Director 84/08/17 GERSTNER, W C 11111ndis Power Co 2pp 26177 196 24X Fiche 50-461, 84/08/17,
- --B408210471 Preoperational Physical Protection Insp Rept 50-461/B4-22 on B40726-27 No noncompliance identified Major areas inspected planning & implementation of security program Details withheld (ref 10CFR73 21) PIRTLE, G L., CREED, J R. Region 3, Office of Director 84/08/16 1p 26177 198 24X Fiche 50-461,84/08/17,8408210470

### G Adjudicatory correspondence

- B408130294 Forwards NRC response to util Ray 1 to independent design GODDARD, R J Hearing Branch 3 DSB 877 84/08/07 SAMEL80N.A Illinois, State of lipp 26010 268 24x Fiche 50-461,84/09/09. 8408130294
- 840B170314 Notice of appearance in proceeding Certificate of Svc encl BIEDDR, O R Illinois, State of DBB 088 B4/08/13 CLARK, H K , FEROUBDN, O A , PARIS.O H Atomic Safety and Licensing Board Panel 5pp 26114 232 24X Fiche 50-461,84/08/13,8408170314
- correspondence
  SIEDOR, OR R Illinois, State of DSB 089 84/08/13 Dock
  Services Branch ip 26113 334 24X Fiche 50~461,84/08/13,8408170323 8408170323 Forwards notice of appearance W/o encl Related Dacketing &
- G Inspection reports. IE Bulletins & correspondence
- 8407250227 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Syc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229
- 8408130502 Forwards IE Insp Rept 50-461/84-17 on 840611-15 & notice of violation
  WALKER, R D Region 3, Office of Director 84/07/27 GERSTNER, W C
  Illinois Power Co 2pp 26079 109 24% Fiche 30-461,84/07/27.
- --8408150507 Notice of violation from insp on 840611-15 MALKER, R D Region 3, Office of Director 84/07/27 26079 111 24X Fiche 50-461,84/07/27,8408150502

- --8408150511 IE Insp Rept 50-461/84-17 on 840611-15 Violation noted const contractor fulled to follow up outstanding document control transmittals as required by Baldwin Assoc procedures
  VANDEL.T E , SMEENSE.R J , HAHKINS.F C Region 3, Office of
  Director 84/07/26 13pp 26079 112 24X Fiche 50-461.84/07/27. Director 84/07/26 8408150502
- 8408070452 Ack receipt of 840726 Itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-461/84-15 Corrective actions will be examined during subsequent insp MALKERIR D Region 3. Office of Director 84/08/02 OERSTNER, W C Illinois Power Co ip 25940 292 24% Fiche 50-461.84/08/02.
- ---8408070460 Responds to NRC 840612 ltr re violations noted in IE Insp Rept 50-461/84-15 Corrective actions nonconforming piping speels will be resolved by Nonconformance Repts 18443, 18462, 18643 & 18609 HALL, D.P. Illimois Pawer Co. 84/07/26 KEPPLER, J.G. Region 3, Office of Director 2pp. 25940 293 24X Fiche 50-461, 84/08/02, 8408070452
- 8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during inspiratituted, effective 840820 Preprinted form will be used rather than itr KEPPLER, J G Region 3, Office of Director 84/08/03 Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000,84/08/03,8408070401
- 8408240314 Forwards Insp Rept 50-461/84-14 on 840529-31,0601,28-29 & 0711-13 No noncompliance noted WARNICK,R F Region 3, Office of Director 84/08/03 GERBINER,W C Illinois Power Co 2pp 26236 330 24X Fiche 50-461,84/08/03,8408240314
- --8408240321 Insp Rept 50-461/84-14 on 840527-31,0401,28-27 & 0711-13 No noncompliance noted Hajor areas inspected allegations reequipment installation including intimidation qualification & training of personnel & quality of hanger matls

  JABLONSKI,F J , KNOP,R C Region 3, Office of Director 84/08/03
  13pp 26236 332 24X Fiche 50-461,84/08/03,8408240314
- 8408010333 IE Info Notice 84~59, "Deliberate Circumventing of Station Health Physics Procedures "Svc list encl JOHANN E L Division of Emergency Proparedness & Engineering Response (Post 830103) B4/08/06 Consolidated Edison Co 26068 001 24% Fiche 50-000, 84/08/06, 8408010333 122pp
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New 123pp 26067 158 24% Fiche 50~000,84/08/06,8408010337
- 8408070120 IE Info Natice 84-61. "Dverexposure of Diver in PWR Refueling Cavity " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Ficha 30-000.84/08/08.8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Syc RACE, J.N. Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co. of New York, Inc 128pp 26/30 001 24% Fiche 50-000,84/08/10,8408070376
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping" iOBIO0009 IE into Novice 2.2.—
  Byc list encl
  JORDAN.E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408100039 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication "Svc list encl.

  JORDANNE L Division of Emergency Preparedness & Engineering

  Response (Post B30103) B4/08/15 Consolidated Edison Co of

  Yark, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 84081 104pp
- 8408100021 IE info Notice 84-65, "Underrated Fuses Which May Adv Affect Operation of Essential Electrical Equipment " Syc list encl JDRDAN.E L. Division of Emergency Preparedness & Engineeri Response (Post 830103) 84/08/16 Consolidated Edison C York: Inc. 118pp. 26178 001 24X Fiche 50-000,84/08/16. E
- B40B100055 IE Info Notice B4-66, "Undetected Unavailabilit Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN.E L Division of Emergency Preparedness & Enginy Response (Post B30103) B4/0B/17 Consolidated Edis York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/

- B14020B IE Info Notice 84-67, "Recent Snubber Inservice Testing W/igh Failure Rates" 8vc list encl
  ORDAN.E L Division of Emergency Preparedness & Engineering
  seponse (Post 830103) 84/08/17 Consolidated Edison Co of New
  ork, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 18210470 Forwards Preoperational Physical Protection Insp Rept 30-461/84-22 on 840726-27 No noncompliance identified XCLL9DN. W L Region 3. Office of Director 84/08/17 GERSTNER W C Illinois Power Co 2pp 26177 196 24X Fithe 50-461.84/08/17,
- B408210471 Preoperational Physical Protection Insp Rept 50-461/84-22 on 840726-27 No noncompliance identified Major areas inspected planning & implementation of security program Details withheld (ref 10CFR73 21) PRTLE, 0 L., CREED, J. R. Region 3, Office of Director 84/08/16 1p 26177 198 24% Fiche 50-461/84/08/17,8408210470
- OB210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JDRDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc. 113pp 26329 008 24% Fiche 50-000,84/08/21.8408210142
- Periodic operating reports & related correspondence
- 108070219 Provides quarterly update re const schedule in response to HR Denton 840529 ltr Critical path schedule analysis shows that limiting sys schedule for reactor water cleanup approx 53 days behind schedule HALL, D P Illinois Power Co 84/07/30 DENTON, HR Office of Nuclear Reactor Regulation, Director ip 25949 261 24X Fiche 50-461.84/07/30.8408070219
- Reportable occurrences, LERs & related correspondence
- 408060366 Interim Potential Deficiency Rept 55-84-14 re Baldwin Assoc OA vendor surveillance program Initially reported on 84068; Investigation incomplete Update on investigation will be submitted in approx 70 days HALL. P Illinois Power Co 84/07/20 KEPPLER, J G Region 3, Office of Director 3pp 25936 097 24% Fiche 50-461,84/07/20, Office of Director 3pp 25936 097 24% Fiche 50-461,84/07/20,
- 3408080340 Interim Deficiency Rept 55-84-15 re installation of skewed auxiliary steel connections w/o required approved design details Initially reported on 840827 Investigation plan will be implemented to determine extent of problem HALL, D.P. Illinois Power Co. 84/07/26 KEPPLER, J.O. Region 3, Office of Director 2pp. 25975 321 24X Fiche 50-461,84/07/26,840890840
- 8408130238 Part 21 Rept 21-84-10 re potential functional problem w/transmitter amplifier board supplied by Rosemount, Inc. as spare part or part within complete Model 1153, Beries 8 transmitter Rosemount 840718 ltr informing of defect encl HALL, D.P. Illinois Power Co. 84/07/30 KEPPLER, J.O. Region 3: Office of Director Spp. 26008 198 24X Fithe 50-461.84/07/30, 8408130238
- B408200332 Part 21 rept re tension wires on Titus Grille, Model 272, not remaining in place when deflection blades closed Affected job sites identified in encl Products being tested provide acceptable fix for retention SCHNEIDER.B L Phillips Industries. Inc 84/08/07 Director's Office, Office of Inspection and Enforcement 3pp 24/133 315 24 Fiche 50-000.84/08/07.8408200332
- 8408200338 Part 21 rept re tension wires used for adjustment of blades on Orille Model 272 not remaining in place when blades closed Review & testing conducted to identify total number of grilles & rework methods.

  BCHNEIDER: S.L. Phillips Industries: Inc. 84/08/07 USINGER: R Zack Co. ip. 26132 356 24X Fiche 50-461:84/08/07.8408200338
- 8408300022 Final deficiency rept re damage to Conax cable penetrations through containment wall initially reported on 840328 Measures taken to practice recurrence of similar damage/ deficiencies during replacement operations HALL-D F Illinois Power Co. 84/08/15 KEPPLER, J. G. Region 3, Defice of Director App. 24307 083 24X Fiche 50-461.84/08/15, 8408300022
- 8408300224 Interim rept of Deficiency 55-84-07 re improperly certified pipe penetration head fitting matts supplied by Rockwell Engineering & Carbon Steel Products Initially reported on 840828. Class i shear lugs replaced HALL.D.P. Illinois Power Co. 84/08/15. KEPPLER, J. G. Region 3, Office of Director 3pp. 26307-004. 24X Fiche 50-461.84/08/15, page 2020.

- 6408270318 Interim Deficiency Rept 55-84-16 re internal wiring workmanship in Electrical Panels HPCS-DO Initially reported on 840720 Investigation plan implemented Final rept will be submitted within 90 days MALL.D P Illinois Power Co 84/08/17 KEPPLER, J G Region 3. Office of Director 3pp 26244 184 24X Fiche 50-461,84/08/17.84/08/20318
- 8408300076 Final rept of Deficiency 55-84-10 re loose metallic debris found in yower supplies of NSFS panels Initially reported on 840403 Emphasis given to training courses in housekeeping for future work involving slectronic panels HALL, D.F. Illinois Power Co. 84/08/17 KEPPLER, J.Q. Region 3, Office of Director. 4pp. 26/307 183 24X Fiche 50-461,84/08/17,8408300076
- 8408300210 Interim rept of Deficiency 55-84-07 re possible use of GE generic vs plant-specific design specs in developing preoperational test procedures Initially reported on 840328 Training conducted on proper use of GE documentation HALL, DP Illinois Power Ca 84/08/17 KEPPLER, J G Region 3, Office of Director 4pp 26307 048 24X Fiche 50-461,84/08/17, 840920210
- T. Hearing transcripts on non-antitrust matters
- 8408130152 Summary of 840628 meeting w/util, Bechtel, Schiff Hardin, Sargent & Lundy, Newman & Holtzinger & State of IL in Bethesda, MD re proposed IDVP Forwards transcript of meeting minutes SIEGEL, B L Licensing Branch 2 84/08/01 Licensing Branch 2 4pp 26034 154 24X Fiche 50-461.84/08/01.8408130152
- --8408130156 Transcript of 840628 open meeting in Washington.DC re facility IDVP Pp 1-131 Supporting documentation encl \* Commissioners 84/06/28 175pp 26034 158 24X Fichs 50-461.84/08/01.8408130152
- V Operator Examinations
- 8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners MALKER, R D. Region 3, Office of Director 84/08/10 Michigan. Univ of, Ann Arbor, MI 2pp 26051
- DOCKET 50-462 CLINTON POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8408310156 FOIA request that SECY-84^27 & encl of PL William 840303 ltr re functional description of safety parameter display sys be placed in PDR BOVE.K Affiliation Not Assigned 84/04/12, FELTON, J M Division of Ruiss and Records 1p 26332 001 24X Fiche 50-461,84/04/12,
- 8408130120 Requests rev to 840606 GA program submittal to comply w/paragraph (3)(11) of 10CFR50 55(f) requirement to identify each change reason for change & basis for concluding that change satisfies 10CFR30 App B criteria SPESSASD, R L Region 3, Defice of Director 84/08/06 GRRSTNER, W C 10wa Electric Light & Power Co 2pp 26007 333 24) Fiche 50-461,84/08/06,8408130120
- V Operator Examinations
- 8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners WACKER,R D Region 3. Office of Director 84/08/10 Michigan. Univ of. Ann Arbor. MI 2pp 26051 198 24X Fiche 50-000. 84/08/10.8408140426
- DOCKET STN-50-470 CESBAR SYSTEM 80
- A Application/construction stage documents & correspondence
- 8408140390 Responds to 840327 request for info re potential single failure in auxiliary pressurizer apray sys C-E completed preliminary review of info requested info expected to be provided by 8ept 1984
  8CHERER, A E Combustion Engineering, Inc. 84/08/03 EISENHUT, D & Division of Licensing ip 26052:361 24X Fiche 50-470,84/08/03.8408140390

- E NRC Safety Evaluation Report (SER), supplis & correspondence
- B40B140230 Forwards items for updating when SER generated to close out remaining issues Items include steam generator tube rupture, radiological consequences of DDA & shutdown cooling (RHR) sys
  SCHERTER, A E Combustion Engineering, Inc. 84/08/03 EISENHUT, D.G.
  Division of Licensing 2pp 26055-313 24X Fiche 50-470,84/08/03,84/08140230
- G Inspection reports, IS Bulletins & correspondence
- 8408310044 Forwards Exam Rept 50-470/OL-84-06 of exam administered during wk of 840618
  STAROSTECKI, R Division of Project & Resident Programs 84/08/01
  SCHERER, A E Combustion Engineering, Inc 2pp 26334 184 24X
  Fiche 50-470,84/08/01,8408310044
- ~~8408310048 Exam Rept 50-470/QL-84-06 administered on 840617-18 Exam results not listed DUDLEY.N F Region i, Office of Director 84/07/26 41pp 26334 186 24X Fiche 50-470,84/08/01.8408310044

#### V Operator Examinations

- 8408310044 Forwards Exam Rept 50-470/UL-84-06 of exam administered during wk of 840618
  STARUSTECKI.R Division of Project & Resident Programs 84/08/0
  SCHERER.A E Combustion Engineering Inc 2pp 26334 184 24X
  Fiche 50-470,84/08/01,8408310044
- --8408310048 Exam Rept 50-470/OL-84-06 administered on 840617-18 Exam results not listed DUDLEY,N F Region 1, Office of Director 84/07/26 41pp 26334 186 24% Fiche 50-470,84/08/01,8408310044

# DOCKET STN-50-402 WOLF CREEK GENERATING STATION

- A Application/construction stage documents & correspondence
- 8408010187 Notification of 840730 meeting w/util in Bethesda,MD to discuss util proposed dual function shift technical advisor O'CONNOR.P W Licensing Branch 1 84/07/20 YOUNGBLOOD, B J Licensing Branch 1 4pp 25873 288 24X Fiche 50-482,84/07/20,8408010187
- 8408070394 Notification of rescheduled 840801 meeting w/util in Bethesda, MD to discuss util proposed dual function shift technical advisor Date & time of meeting changed O'CONNOR.P W Licensing Branch 1 84/07/20 YOUNGBLOOD, B J Licensing Branch 1 3pp 25956 256 24X Fiche 50-482,84/07/20, 8408070394
- 8407310144 Forwards proprietary WCAP-10621, "Westinghouse Thermocouple/Core Cooling Monitor Sys Isolation Tests " Rept withheld (ref 10CFR2 790) PETRICK:N A Standardized Nuclear Unit Power Plant System 84/07/26 DENTON:H R Office of Nuclear Reactor Regulation, Director 3pp 25835 258 24X Fiche 50-000,84/07/26,8407310144
- 8408060399 Forwards request for addl info re seismic & dynamic qualification Response should be received by 840731 to support schedule for full power operation at Callaway YOUNOBLOOD. D J. Licensing Branch 1 84/07/26 SCHNELL. D F Union Electric Co KOESTER, G L Kansas Gas & Electric Co Spp 25951 169 24X Fichs 50-000.84/07/26.8408060399
- B408070028 Summarizes Caseload Forecast Panel 840524 tour & confirms util commitment to provide updated milestone schedule every 2 wks Nov-Dec const completion date achievable Tour attendance list & milestone sheet encl YOUNGBLOOD, B J Licensing Branch 1 84/07/26 KOESTER, C L Kanss Cas & Electric Co 7pp 25956 180 24X Fiche 50-482, 84/07/26, 8408070028
- 8408060834 Responds to 840726 request for add1 info re seismic qualification of thermocouple/core cooling monitor sys acceptance criteria Termination of Justification for interim operation maintained PETRICK,N A Standardized Nuclear Unit Power Plant System 84/07/27 DENTON.H R Office of Nuclear Reactor Regulation. Director 3pp 25934 i12 24X Fiche 50-000,84/07/27,8408060234
- --8408060240 Requests add) info re seismic & dynamic qualification of thermocouple/core cooling monitoring sys,per review of info concerning 100% power amend YOUNGBLOOD, B. J. Licensing Branch ! 84/07/26 SCHNELL, D.F. Union Electric Co. KOESTER, G.L. Kansas Gas & Electric Co. 2pp. 25934 115 24X Fiche 30-000,84/07/27,8408060234

- 8408030159 Forwards revised Figure 5 1-4 to Tech Specs re boundary for liquid affluents Info incorporated into OL application KOESTER G L Kansas Gas & Electric Co 84/07/30 DENTON.H R Office of Nuclear Reactor Regulation. Director 3pp 25912 019 24% Fiche 50-482,84/07/30.8408030159
- B40B030012 Forwards update of B10905 & 18 inservice testing programs for pumps & valves Original inservice testing program developed in compliance w/Section XI of ABME Boiler & Pressure Vessel Code KDESTER.G L. Kansas Oas & Electric Co 84/07/31 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 25907 124 24X Fiche 50-482,84/07/31.8408030012
- --8408030016 "Inservice Testing Program for Pumps & Valves "
  \* Kansas Qas & Electric Co 84/Q7/31 117pp 25907 126 24X
  Fiche 50-482,84/07/31,8408030012
- B408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for GLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Generic Safety Issues" "Svc list enci EISEMHUT, D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000,84/08/06,8408070110
- 8408140350 Forwards one oversize milestone schedule as of 840801 Aperture card available in PDR KDESTER.6 L Kansas Gas & Electric Co 84/08/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 24X Fiche 50-482
- B40B200119 Forwards updated "Wolf Creek Unit 1 Environ Protection Plan (Nonradiological)," reflecting current regulatory conditions & revising refs
  KDESTER.0 L Kansas Qas & Electric Co B4/0B/13 DENTON,H R
  Office of Nuclear Reactor Regulation, Director 2pp 26133 237
  24X Fiche 30-482.84/08/15.8408200119
- --8408200123 "Wolf Creek Unit 1 Environ Protection Plan (Nonrediological) " \* Kansas Gas & Electric Co 84/07/31 15pp 26133 239 24x Fiche 50-482,84/08/15,8408200119
- 8408220387 Forwards add1 info re Bargent & Lundy design verification activities concerning three UHB-related items Info documents that UHS design calculations reflect as-built conditions & design info controlled & coordinated among organizations KOESTER. G L Kansas Oas & Electric Co 84/08/15 DENTON. H R Office of Nuclear Reactor Regulation. Director 38pp 26:191 308 24X Fiche 50-482,84/08/15,8408220389
- 840B210313 Forwards revised F8AR App 7A pages addressing NRC 840A25-26 requests for add1 info re Reg Guide 1 97 As-built plant dssign info.not included in original submittal, incorporated Design provides info required to satisfy Rev 2 to reg guide PETRICK, N A Standardized Nuclear Unit Power Plant System 84/08/16 DENTON, HR Office of Nuclear Reactor Regulation. Director 45pp 26177 060 24X Fiche 50-000,84/08/16,8408210313
- B40B200275 Generic Ltr B4-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
  EISENHUT, D 0 Division of Licensing B4/0B/20 Consulidated Edison Co of New York, Inc 17pp 26276 244, 24X
  Fiche 50-000,84/0B/20,840B200275
- 8408270377 Forwards one oversize milestone schedule as of 840815 Aperture card available in FDR KDESTER, 6 L. Kansas Gas & Electric Co. 84/08/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp. 26240 195 24X Fiche 50-482,84/08/22,8408270377
- 8408310101 Confirms transmittal of preservice insp program plan to PN G/Connor Document updated to incorporate approved field changes & to reflect as-built plant condition Relief request will be submitted BEIKEN.8 J Standardized Nuclear Unit Power Plant System 84/08/28 DENTON, HR Office of Nuclear Reactor Regulation, Director 1p 26322 233 24X Fiche 50-482,84/08/28,8408310101
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 840B100046 Submits commitments to close out SER. Open Item I A 1 1 re shift technical advisor program Academic training for sonior reactor operators will be provided Commitment incorporated into OL application KOESTER. OL Kansas Oas & Electric Co 84/08/07 DENTON, H Office of Nuclear Reactor Regulation. Director 7pp 25790 175 24X Fiche 50-482.84/08/07.840B100066

- B40B160063 Clarifies SNUPPS design & procedural controls for mitigation of postulated control room fires.per SSER 3 (NUREG-0830) Requests meeting w/NRC, per procedures for disposition of bacifitting requirements implemented by IE & NRR PETRICK.N A Standardized Nuclear Unit Power Plant System B4/0B/10 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 260B5 313 24X Fiche 30-000.84/08/10.840B160063
- 8408270389 Requests that new regulatory position re control room fires be reviewed per 10CFR50 109 Meeting W/appropriate NRC mgt re procedures for disposition of backfitting requirements implemented by 16 k NRR also requested PETRICK.N A Standardized Nuclear Unit Power Plant System 84/08/10 DENTON.H R Office of Nuclear Reactor Regulation, Director 4pp 26238 124 24X Fiche 50-482.84/08/10.8408270389
- F Security, medical, emergency & fire protection plans
- B40B060175 Forwards IE Insp Rept 50-482/84-13 on 840501-04 Nq violations or deviations noted UDHNSON: EH Region 4, Office of Director 84/05/25 KORSTER.G t. Kansas Gas & Electric Co. 2pp 25935 172 24X Fiche 50-482,84/05/25,8408060175
- --84080A01B0 IE Insp Rept 50-482/B4-13 on B40501-04 No violations or deviations noted Major areas inspected interim security plan for protection of SNM of low strategic significance Details withheld (ref IOCRY3 21)
  KELLY.J A Region 4, Office of Director HALL,R E. JOHNSON.W D Region 2, Office of Director B4/05/25 4pp 25935 174 24X
  Fiche 50-482,84/05/25.8408060175
- 840B160520 Forwards IE Insp Rept 50-482/84-17 on B40626-29 No violations or deviations noted HUNIER D R Region 4. Office of Director 84/07/27 KOESTER, G L Kansas Gas & Electric Co 2pp 26108 015 24X Fiche 50-482,84/07/27,840B160520
- --8408160523 IE Insp Rept 50-482/84-17 on 840626-29 No violations or deviations noted Major areas inspected physical security plan & implementing procedures & mgt effectiveness-security program Details withheld (ref 10CFR73 21) KELLY.J A : HALL.R E : MARTIN.L E Region 4. Office of Director 84/07/27 1p 26108 017 24X Fiche 50-482.84/07/27.8408140520
- 8408020105 Forwards "State of KB Annex A.Nuclear Facilities Incidents Response Plan to Assistance R.Nuclear Emergencies of State Disaster Emergency Plan" & "Coffey County Contingency Plans for Incidents Involving Commercial Nuclear Power" KDESTER.0 L Kansas Gas & Electric Co 84/07/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 25892 306 24X Fiche 30-482.84/07/31.8408020105
- --8408020114 "State of K9 Annex A. Nuclear Facilities Incidents Response Plan to Assistance R. Nuclear Emergencies of State Disaster Emergency Plan " MANNELL-L Kansas, State of 84/06/30 354pp 25892 307 24X Fiche 50-482
- ~8408020117 Rev 3 to "Coffey County Contingency Plan for Incidents Involving Commercial Nuclear Power" \* Coffey County, KB 84/06/30 300pp 25893 303 24x Fiche 50~482,84/07/31.8408020105
- 8408140337 Submits add1 info to 840404 response to NRC questions re procedures generation package Technical content of procedures in accordance w/Rev 1 (840791) to Westinghouse high pressure emergancy response guidelines KOESTER.G L Kansas Gas & Electric Co 84/08/10 DENTON, H R Defice of Nuclear Reactor Regulation, Director 2pp 26042 317 24X Fiche 50-482,84/08/10,8408140337
- 8408140063 Clarifies SNUPPE design & procedural controls for mitigation of postulated control room fires, per SBER 3 (NUREG-0830) Requests meeting w/NRC, per procedures for disposition of backfitting requirements implemented by IE & NRR PETRICK, N A Standardized Nuclear Unit Power Plant System, 84/08/10 DENTON, HR Office of Nuclear Reactor Regulation, Director 3pp 26085 313 24X Fiche 50-000,84/08/10,8408160063
- B408270387 Requests that new regulatory position re control room fires be reviewed per 10CFR50 109 Meeting w/appropriate NRC mgt re procedures for disposition of backfitting requirements implemented by IE & NRR also requested PETRICK: N A Standardized Nuclear Unit Power Plant System B4/08/10 DENTON.H.R Office of Nuclear Reactor Regulation. Director 4pp 26238 124 24X Fiche 50-482.84/08/10.8408270389
- 8408210558 Notification of 840815 meeting w/utile & SNUPPS in Bethesda, MD to discuss fire protection review HOLONICH, J J, O'CONNOR, P W Licensing Brench 1 B4/08/15 YOUNOBLOOD, B J Licensing Branch 1 Rpp 26175-257 24X Fiche 50-000, 84/08/15, 8408210558

- 8408220207 Forwards Rev 4 to physical security plan Plan withheld (ref 10CFR73 21) KDESTER, E. Kansas Gas & Electric Co. 84/08/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26194 049 24X Fiche 50-482,84/08/15,8408220207
- 8408280037 Notification of 840822 meeting w/utils & SNUPPS in Bethesda, MD to discuss SNUPPS fire protection review HOLOMICH, J J , O'CONNOR, P W Licensing Branch 1 84/08/20 YOUNGBLOOD, B J Licensing Branch 1 5pp 26294 152 24X Fiche 50-000.84/08/20.8408280037
- B408270033 Forwards Rev 4 to safeguards contingency plan Rev withheld (ref 10CTR73 21)
  KOESTER.G L Kansas Gas & Electric Co B4/08/22 DENTON.H R
  Dffice of Nuclear Reactor Regulation, Director 13pp 26291 254
  24X Fiche 50-482.84/08/22.8408270033
- 8408300075 Summary of 840815 meeting w/utils, SNUPPS & Bechtel re SNUPPS fire protection program & safe shutdown analysis Attendees list encl O'CONNOR, P. W., HOLONICH, J. J. Licensing Branch i 84/08/22 Licensing Branch i 6pp 26329 354 24X Fiche 50-000.84/08/22, 8408300075
- B40B300090 Forwards results of evaluation re control room fire & summary of response plan necessary to ensure achievement & maint of hot standby w/postulated fire damage PETRICK.N A Standardired Nuclear Unit Power Plant System 84/08/23 DENTON,H R Office of Nuclear Reactor Regulation, Director 15pp 26306 120 24X Fiche 50-000.84/08/23,8408300090
- 8408280227 Board Notification 84-145 provides info re fire protection concern discovered during insp Based on preliminary insp. NRC determined safety evaluation for alternate shutdown capability incorrect CISENHUT, D G Division of Licensing 84/08/24 PALLADINO Consolidated Edison Co of New York, Inc. ROBERTS, ASSELSTINE Commissioners 3pp 26392 128 24% Fiche 30-000,84/08/24.408280229
- 8408280229 Board Notification 84-145 provides info re fire protection concern discovered during insp. Based on preliminary insp. NRC determined safety evaluation for alternate shutdown capability incorrect EISCNNUT, D. G. Division of Licensing 84/08/24 PALLADINO Consolidated Edison Co. of New York, Inc. 3pp. 26322 128 24X Fiche 50-000.84/08/24.8408280229
- Q Adjudicatory correspondence
- B40B060221 Order determining that ASLB B40702 initial decision not final until completion of ASLAB sua sponte review Served on H40B03
  BHMEMAKER,C J Atomic Safety and Licensing Appeal Panel DSB 741
  B4/0B/03 Office of the Executive Legal Director 1p 25923 361
  24X Fiche 50-4B2, B4/0B/03, B40B060821
- @ Inspection reports, IE Bulletine & correspondence
- 8408040175 Forwards IE Insp Rept 50-482/84-13 on 840501-04 No vielations or deviations noted JOHNSON,E H Region 4. Office of Director 84/05/25 KOESTER,G L Kansas Gas & Electric Co 2pp 25935 172 24X Fiche 50-482.84/05/25.8408040175
- --B40B0A01B0 IE Insp Regt 50-482/84-13 on B40501-04 No violations or deviations noted Major areas inspected interim security plan for protection of SMM of low strategic significance Details withheld (ref iOcFR73 21) KELLY, J A Region 4, Office of Director HALL, R E, JOHNSON, W D Region 2, Office of Director B4/05/25 4pp 23935 174 24X Fiche 50-482,84/03/23,8408060175
- 8408060092 Forwards exam rept of initial operator exams administered in May 1984
  JOHNBON,E H Region 4, Office of Director 84/07/03 KOESTER, G L
  Kansas Gas & Electric Co 2pp 25935 309 24X
  Fiche 50-482,84/07/03.8408060092
- --B408060077 Exam rept of initial exams administered in May 1984 Exam results 18 of 23 senior operator candidates & all four operator candidates passed written, oral & simulator exams PELLET, J L , CODLEY, R A Region 4, O
- 8407250227 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list enci JORDANNEL. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250227

- Forwards [E Insp Rept 50-482/84-17 on 840626-29 No sor deviations noted Region 4. Office of Director 84/07/27 KOESTER, G L & Electric Co 2pp 26108 015 24x 462,84/07/27.8408160520
- IE Insp Rept 50-482/84-17 on 840424-29 No violations or one noted Major areas inspected physical security
  Implementing procedures & mgt effectiveness-security
  Details withheld (ref 10CFR73 21)
  A. HALLIR E., MARTIN-L E. Region 4, Office of Director ip 26108 017 24X Fiche 50-482-84/07/27.8408140520
- AC & receipt of 840601 ltr informing NRC of steps taken to 1 to 1 ations noted in IE Inap Rept 50-482/84-00
  Repjon 4, Office of Director 84/07/31 KOESTER.O L
  S & Electric Co ip 25987 027 24% Fiche 50-482,
  8408100049
- Responds to NRC 840504 ltr re violations noted in IE Insp. 482/84-08 Corrective actions Daniel Intl Corp has Nonconformance Rept ISN17097P, requiring corrected that rept for Spool EJ-044-5016 obtained from vendor to rept for Spool EJ-044-5016 obtained from vendor to C. Kaness Cas & Electric Co. 84/06/01 JUHNSDN.E H. Office of Director Spp. 25987 029 24X 10-482,84/07/31,8408100069
- Forwards QA Program Insp Repts 99900519/84-01,99900387/84-01
  14/84-02 for action Requests signature on
  to ack receipt of repts W/o encls
  Region 4. Office of Director 84/08/03 KOESTER, O L
  18 & Electric Co 2pp 25988 265 24X
  -482,84/08/03,8408100139
- TE Info Notice 84-59, "Deliberate Circumventing of Station
  Usics Procedures "Svc list enc!
  L Division of Emergency Preparedness & Engineering
  (Post 830103) 84/08/06 Consolidated Edison Co of New 122pp 26048 001 24% Fiche 50-000,84/08/06,8408010333
- IE Info Notice 84-60. "Failure of Air Purifying Respirator

  Mest Efficiency Requirement " Svc list encl

  Division of Emergency Preparedness & Engineering

  Chost 8301031 84/08/06 Consolidated Edison Co of New

  123pp 24067 158 24X Fiche 50-000.84/08/06.8408010337
- IE Info Notice 84-61, "Overexposure of Diver in PWR Cavity" Svc list encl
  L. Division of Emergency Proparedness & Engineering
  (Past 830103) 84/08/08 Consolidated Edison Co of New 120pp 26129 118 24% Fiche 50-000,84/08/08,8408070120
- t∈ Info Notice 84-62, "Thorapy Misadministrations to Undergoing Co-60 Teletherapy Treatments " Syc
- 1. Division of QA, Bafeguards & Inspection Programs (Post ⊟4/08/10 Consolidated Edison Co of New York, Inc ≥4130 001 24% Fiche 50-000.84/08/10.8408070376
- TE Info Notice 84-63, "Defective RHR Replacement Piping "

  CTSC 1

  L. Division of Emergency Preparedness & Engineering

  (Post 830103) 84/08/13 Consolidated Edison Co of New
  119pp 26197 218 24% Fichs 50-000.84/08/13,8408100009
- IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Pn." Svc list encl
  L. Division of Emergency Preparedness & Engineering (Post 830103) 84/08/15 Consolidated Edison Co of New 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038
- IE Info Notice 84-65, "Underrated Fuses Which May Adversely , gration of Essential Electrical Equipment " Svc
- Division of Emergency Preparedness & Engineering CP ost 830103) 84/08/16 Consolidated Edison Co of New 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021
- IE Info Notice 84-66. "Undetected Unavailability of priven Auxiliary Feedwater Train " Svc list encl L. Division of Emergency Preparedness & Engineering CPOst 830103) 84/08/17 Consolidated Edison Co of New 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- IE Info Notice 84-67, "Recent Snubber Inservice Testing W/
  ure Rates " Svc list enc!
  L. Division of Emergency Preparedness & Engineering
  (Post 830103) 84/08/17 Consolidated Edison Co of New
  122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

- 8408210142 IE Info Notice B4-6B. "Potential Deficiency in Improperly Rated Field Wiring to Bolenoid Valves " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142
- 8408280227 Board Notification 84-145 provides info re fire protection concern discovered during insp Based on preliminary insp,NRC determined safety evaluation for alternate shotdown capability incorrect EISENHUT,D 0 Division of Licensing 84/08/24 PALLADING Consolidated Edison Co of New York, Inc. ROBERTS, ASSELSTINE Commissioners 3pp 26322 128 24X Fiche 50-000,84/08/24,408280227
- B Reportable occurrences, LERs & related correspondence
- 8408010386 Supplemental final deficiency rept re generic defects in Gould/Rundel 4-position to 2-position selector switches failure Initially reported on 840209 Failed units to be replaced from alternate supplier
  SEIKEN.8 J Standardized Nuclear Unit Power Plant System 84/07/2:
  COLLING.J T Region 4, Office of Director 2pp 25866 284 24X Fiche 50-000.84/07/20.8408010386
- 8408030235 Interim Significant Deficiency Rept SDR 84-04 re Limitorque operator motor pinion/worm shaft clutch gear failure Limitorque uill conduct cycle testing & Westinghouse uill conduct metallurgical tests Next rept expected by 840930 SEIKEN.S J Standardized Nuclear Unit Power Plant System 84/07/20 KEPPLER.J G Region 3, Office of Director COLLINS.J T Region 4. Office of Director 3pp 25917 234 24X Fiche 50-000.84/07/20.
- B40Bi40001 Deficiency rept re Anchor Darling 10-inch gate valve in essential svc water sys Initially reported on B40223 Valve failed in open position & does not represent safety concern Condition not reportable per 10CFR30 55(e)
  KDESTER.G L. Kansas Oas & Electric Co 84/08/06 HUNTER.D R Ragion 4, Dffice of Director 1p 26044 357 24X
  Fiche 50-482.84/08/Q6,8408140001
- 840B140020 Final deficiency rept re compromised Level II welding inspector exams Intially reported on B20712 Inspectors retested & welds reinspected MOESTER, © L. Kansas Gas & Electric Co. 84/08/06 HUNTER, D.R. Region 4, Office of Director 2pp. 26044 189 24X Fiche 30-482,84/08/06,8408140020
- 8408140237 Final deficiency rept re improper fittings on low pressure switch of nitrogen accumulator for MBIV Initially reported on 831025 Transition piece installed in low pressure switch assembly of each affected valve KOESTER, G. L. Kansas Gas & Electric Co. 84/08/06 HUNTER, D.R. Region 4, Office of Director 1p. 26055-315 24X Fiche 50-482,84/08/06,8408140237
- 8408140308 Final deficiency rept re butterfly valves Supplied by Fischer Control Initially reported on 840110 Valves w/loose or missing pins repaired per manufacturer instructions, including cleaning of tapered holes KOESTER, Q L Kansas Gas & Electric Co 84/08/06 HUNTER, D R Region 4, Office of Director 7pp 26042 324 24X Fiche 50-482,84/08/06.8408140308
- 8408160905 Final deficiency rept re insufficient torque on structural stuel bolted connections Connections reworked & reverified to assure quality & procedures revised to complete corrective actions
  KOESTER. O L Kansas Gas & Electric Co 84/08/06 JOHNSON, E H
  Region 4, Office of Director 5pp 26107 321 24X
  Fiche 50-482,84/08/06,8408160305
- 8408140514 Final deficiency rept re component failures in safety-related battery charges Initially reported on 830309 Chargers inspected upgraded & tasted Corrective action completed KDEBTER, O. L. Kansas Qas & Electric Co. 84/08/06 JOHNSON, E. H. Region 4, Office of Director ip 26108 011 24X Fichs 50-482.84/08/06.8408160514
- 8408220158 Supplemental final deficiency rept re auxiliary faedwater turbine control circuit Field rework plan altered vendor supplied circuitry to be compatible w/facility circuitry KOESTER.G L. Kansas Gas & Electric Co 84/08/08 HUNTER.D P. Region 4. Dffice of Director ip 26188 110 24% Fiche 50-482.84/08/08.8408220159

- 8408220217 Final deficiency rept re ducting installation in torsion restraint area Initially reported on 831110 Damaged bolts replaced & single modified duct piece inspected & found to be welded satisfacturily to flange KOESTER. O L. Kansas Gas & Electric Co. 84/08/08 HUNTER. D R Region 4. Office of Director 2pp 26188 264 24X Fiche 50-482.84/08/08.8408220217
- 8408220248 Final deficiency rept re Beta Products, Inc isolation relay cards Initially reported on 840426 Affected cards modified so that card failure would not cause loss of cuntrol power KDESTER, G. L. Kansas Gas & Electric Co. 84/08/08 HUNTER, D. R. Region 4, Office of Director ip. 26189 216 24X Fiche 50-482.84/08/08.8408220248
- 8408220479 Final deficiency rept re incorrect differential pressure correction in reactor vessel level instrumentation sys initially reported on 840427 Input circuitry into Process Cabinet 7300 reworked KDESTER. © L. Kansas Gas & Electric Co. 84/08/08 HUNTER. D.R. Region 4. Office of Director ip. 26196-032 24X Fishe 50-482.84/08/08.8408220479
- 8408280435 Interin deficiency rept re lubricating all piping sys for safety injection & centrifugal charging pumps Initially reported on 840717 As-built drawings of sys developed to assess work performed w/o gA program approval KDEBTER: © L. Kansas Gas & Electric Co. 84/08/17 HUNTER. D.R. Region 4. Office of Director 2pp 26282 128 24x
  Fiche 50-482.84/08/17.8408280433

#### V Operator Examinations

- 8408060092 Forwards exam rept of initial operator exams administered in May 1784
  JOHN80N.E H Region 4. Office of Director 84/07/03 KOESTER.O L
  Kansas Gas & Electric Co 2pp 25935 309 24X
  Fiche 50-482.84/07/03.8408060092
- --B408060099 Exam rept of initial exams administered in May 1984 Exam results 18 of 23 senior operator candidates & all four operator candidates passed written onal & simulator exams PELLET, J L. CODLEY, R A Region 4. Office of Director 84/07/02 78pp 25935 311 24X Fiche 50-482,84/07/03.8408060092
- 8408280173 Advises that requested matls made available for use in developing license exams for reactor/senior operators per NRC 840627 request Training will be provided for cold licensed operators on plant procedure changes KDESTER: 0 L Kansas Gas & Electric Co 84/07/23 HUNTER, D R Region 4, Office of Director 1p 26267 358 24% Fiche 50-482,84/07/23,8408280193

#### DECKET STN-50-483 CALLAWAY PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 3406140221 Forwards marked-up Tech Specs changed since 840531 ltr Tech Specs accurately reflect design & operating program described in FSAR SCHNELL, D.F. Union Electric Co. 84/06/11 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 21pp 24924 280 24X Fiche 50-483,84/06/11,8406140221
  - NRC Bafety Evaluation Report (SER), suppls & correspondence
- 8408160063 Clarifies SNUPPS design & procedural controls for mitigation of postulated control room fires.per SSER 3 (NUREQ-0830)
  Requests meeting W/NRC,per procedures for disposition of backfitting requirements implemented by 16 & NRR PETRICK.N A Standardized Nuclear Unit Power Plant System 84/08/10 DENFOR.H R Office of Nuclear Reactor Regulation. Director 3pp 26085 313 24% Fiche 50-000.84/08/10.8408160063
- B408270389 Requests that new regulatory position re control room fires be reviewed per iOCFR50 109 Meeting Wappropriate NRC mgt re procedures for disposition of backfitting requirements implemented by IE & NRR also requested PETRICK:N A Standardized Nuclear Unit Power Plant System B4/08/10 DENTON.H R Office of Nuclear Reactor Regulation, Director 4pg 26238 124 24% Fiche 50-482.84/08/10.8408270389
- F Security, medical, emergency & fire protection plans
- 8408130397 Discusses six items from Attachment 1 to License NPF-25, covering emergency lighting in safe shutdown areas & communications outside control room, per App R requirements SCHMELL.D F Union Electric Co 84/07/27 KEPPLER, J O Region Office of Director 4pp 26011 /13 24X Fiche 50-483,84/07/27.8408150397

- 84.8060148 Requests LERs 81-002-00 ' 81-005-00 re malfunction of plant security hardware be reroyed from PDR, per 10CFR73 21 Util now considers LERs as safeguards info MILTENBERGER, S Union Electric Co 84/07/30 Record Services Branch (Document Control Desk) 2pp 25923 308 24x Fiche 50-483,84/07/30.8408060148
- 8408100026 Ack receipt of 840706 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Rept 50-483/84-10 PAFERIELLO, C J Region 3. Office of Director 84/08/06 SCHNELL.D F Union Electric Co ip 25990 159 24X Fiche 50-483.84/08/06.8408100026
- --8408100034 Responds to NRC 840525 ltr re improvement items noted in 1E Energency Preparedness Appraisal Rept 50-483/84-10 Corrective actions role of shift advisors, as county emergency operation ctr technical representative, evaluated SCHNELL, D.F. Union Electric Co. 84/07/06 PAPERIELLO, C.J. Region 3. Office of Director Bpp. 25990 160 24X Fiche 50-483,84/08/06,8408100026
- 840B140127 Forwards Rev 4 to physical security plan Rev withhold (ref 10CFR73 21)
  SCHNELL,D F Union Electric Co 84/08/07 KEPPLER,J G Region 3.
  Office of Director 3pp 26047 008 24X Fiche 50-483,84/08/07,8408140129
- 8408210402 Rev 3 to Emergency Plan Implementing Procedure EIP-ZZ-00102, "Emergency Implementing Actions" & revised index W/840814 transmittal memo MUTTENBERGE. S Union Electric Co 84/08/09 25pp 26179 215 24x Fiche 50-483,84/08/09,8408210402
- 8408270393 Revised emergency plan implementing procedures, including EIP-22-00201 re notifications. EIP-22-00203 re addl assistance & EPIP-22-00211 re field monitoring direction & assessment W/840815 transmittal ltr \* Union Electric Co B4/08/09 200pp 24238 287 24X Fiche 50-483.84/08/09,8408270393
- 840B160063 Clarifies SNUPPS design & procedural controls for mitigation of postulated control room fires.per 9SER 3 (NUREG-0930)
  Requests meeting w/NRC.per procedures for disposition of backfitting requirements implemented by IE & NRR PETRICK.N A Standardized Nuclear Unit Power Plant System 84/0B/10 DENTON.H R Office of Nuclear Reactor Regulation.
  Director 3pp 24085 313 24X Fiche So-000.84/0B/10,8408160063
- 8408270389 Requests that new regulatory position re control room fires be reviewed per 10CFR50 109 Meeting w/appropriate NRC mgt re procedures for disposition of backfitting requirements implemented by IE & NRR also requested PETRICUS, A A Standardized Nuclear Unit Power Plant System 84/08/10 DENTON.H R Office of Nuclear Reactor Regulation, Director 4pp 26238 124 24X Fiche 50-482,84/08/10,8408270389
- 8408210558 Notification of 840815 meeting w/utils & SNUPPS in Dethesda. MD to discuss fire protection review HDLONICH.JJ, O'CONNOR.PW Licensing Branch 1 84/08/15 YOUNOBLOOD.BJ Licensing Branch 1 2pp 26195 257 24X Fiche 50-000.84/08/15.8408210558
- 8408280037 Notification of 840822 meeting w/utils & SNUPPS in Bethesda, MD to discuss SNUPPS fire protection review HOLLONICH. J J, G'CONNOR, P W Licensing Branch 1 84/08/20 YOUNOBLOOD. B J Licensing Branch 1 5pp 26294 152 24X Fichs 50-000,84/08/20,8408280037
- 8408300075 Summary of 840815 meeting w/utils.SNUPPS & Bechtel re SNUPPS fire protection program & safe shutdown analysis Attendees list encl D'CONNOR.P W , HOLONICH.J , J Licensing Branch 1 84/08/22 Licensing Branch 1 6pp 26329 394 24% Fiche 50-000,84/08/22. 8408300075
- B408300090 Forwards results of evaluation re control room fire & summary of response plan necessary to ensure achievement & maint of hot standby w/postulated fire damage PETRICK,N A Standardized Nuclear Unit Power Plant System B4/08/23 DENTON.H R Office of Nuclear Reactor Regulation, Director 15pp 26306 120 24% Fiche 50-000,84/08/23,8408300090
- 8408280227 Board Notification 84-145 provides info re fire protection concern discovered during insp Based on preliminary insp.NRC determined safety evaluation for alternate shutdown capability incorrect EISENHUT, D G Division of Licensing 84/08/24 PALLADINO Consolidated Edison Co of New York, Inc ROBERTS, ASSELSTINE Commissioners 3pp 26322 128 24X Fiche 50-000,84/08/24,408280227

- G Adjudicatory correspondence
- 8408150431 Informs that Commissioner Zech will tour emergency offsite facility on 840823 & corporate ofc on 840824 Served on 840815
  - Commissioners DSB 059 84/08/14 Atomic Safety and pard Panel 1p 26068 261 24% Fiche 50-483,84/08/14, Licensing Board Panel B40B150431
- B40B200567 Informs of Chairman Palladino B40B27 site visit No more than one representative of each party invited to attend Requests notification to util re attendance plans GARNER, D. J. Commissioners DSB 153 B4/OB/17 Office of the Executive Legal Director ip 26137 050 24Y Fiche 50-483. U4/OB/17, B40B200567
- P Operating license stage documents & correspondence
- 8408010082 Forwards SER re response to Generic Ltr 83-28. Item 4 3.

  "Reactor Trip Sys Reliability (Automatic Actuation of Shunt
  Trip Attachment for Westinghouse Plants) " Shunt trip mod
  acceptable Util should submit proposed Tech Specs
  YOUNDILCOD, B J Licensing Branch 1 84/07/18 SCHNELL, D F Union
  Electric Co 3pp 23897 071 24X Fiche 50-483.84/07/18,8408010082
- --B408010085 SER supporting licensee response to Generic Ltr 83-28. Item 4 3 re reactor trip breaker automatic shunt trip \* NRC No Detailed Affiliation Given B4/07/18 1ipp 25897 074 24% Fiche 50-483.84/07/18.8408010082
- 8407310144 Forwards proprietary WCAP-10621, "Wastinghouse
  Thermocouple/Core Cooling Monitor Sys Isolation Tests " Rept
  withheld (ref 10CFRZ 790)
  PETRICK,N A Standardized Nuclear Unit Power Plant System
  84/07/26 DENTON.H R Office of Nuclear Reactor Regulation,
  Director 3pp 25835 258 24X Fiche 30-000, 84/07/26, 8407310144
- 8408060399 Forwards request for add1 info re seismic & dynamic qualification Response should be received by 840731 to support schedule for full power operation at Callauay YOUNGBLOOD, B J Licensing Branch I 84/07/26 SCHWELL, D F Electric Co KDESTER, G L Kansas Gas & Electric Co 5pp 2991 169 24% Fiche 50-000, 84/07/26, 8408060399 SCHNELL, D F Union
- 8408060234 Responds to 840726 request for add1 info re sgismic AUBIOUS24 Responds to 840/26 request for addi info re seismic qualification of thermocouple/core cooling monitor sys acceptance criteria Termination of justification for interim operation maintained
  PETRICK.N A Standardized Nuclear Unit Power Plant System
  84/07/27 DENYON.H R Office of Muclear Reactor Regulation,
  Director 3pp 25934 t12 24X Fiche 50-000.84/07/27,8408060234
- --8408060240 Requests addl info re seismic & dynamic qualification of thermocouple/core cooling monitoring sys.per review of info concerning 100% power amend YOUNGBLOOD, B J Licensing Branch I 84/07/26 SCHNELL, D F Union Electric Co KOESTER, G L Kansas Gas & Electric Co 2pp 25934 115 24% Fiche 50-000,84/07/27,8408060234
- 8408030098 Requests partial exemption from 10CFR90.App J. to allow reduced pressure leakage testing of containment air locks following periods when air locks open & containment integrity not required by Tech Specs
  8CHNCLL.D F Union Electric Co 84/07/31 DEHTON.H R Office Nuclear Reactor Regulation, Director 12pp 23916 043 24X Fiche 50-483.84/07/31.8408030098 Office of
- 8408060286 Application for amend to License NPF-25, revising Tech Spec Table 3 3-1 re source range neutron flux monitors during shutdown conditions Fee gncl SCHNELL,D F Union Electric Co 84/08/01 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 25733 306 24X Fiche 50-483.84/08/01.8408060286
- --8408060287 Proposed Tech Spec changes re source range neutron flux monitors during shutdown conditions \* Union Electric Co 84/08/01 6pp 23733 310 24X Fiche 50-483,84/08/01,8408060286
- 8408070480 Confirms 840809 meeting at Region III ofc to discuss util plans to have operating staff work 12 h shifts in four shift-crew rotation, for remainder of post-fuel load target schedule, per 840785 telcon
  KEPPLER, J Q Region 3, Office of Director 84/08/03 SCHNELL, D F Union Electric Co 1p 25741 210 24x Fiche 50-483,84/08/03,8408070480

- 8408070110 General Ltr B4-19 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of Suppl 1 to NUREO-0933. "Prioritization of Generic Safety Issues "Svc list encl EISENHUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 236 24X Fiche 50-000,84/08/06,8408070110
- 8408169067 Forwards SER re util 840726 request for permission to exclude cold rod drop testing outlined in Reg Guide I 68.App A.2 b Request acceptable YOUNDBLOOD, B J Licensing Branch I 84/08/07 SCHNELL, D F Union Electric Co 3pp 26126 350 24X Fiche 30-483,84/08/07,8408160067
- --8408160072 SER re deletion of cold control rod drop test Repuest accentable \* Division of Licensing 84/08 Fiche 50-483,84/08/07,8408160067 84/08/07 1p 26126 353 24X
- 8408140385 Discusses 840509 briefing for NRR & Region III mgt personnol re operation w/four 12 h shift rotations distributing personnel from six creus among rotations Chert portraying interim schedule on wk-to-wk basis encl
  SCHNELL.D F Union Electric Co 84/08/08 DENTON.H R Office of Nuclear Reactor Regulation. Director 15pp 26052 346 24X Fiche 30-483,84/08/08.8408140385
- 8408220278 Requests extension to 841031 for submittal of response to Generic Ltr 84-15, "Proposed Staff Actions to Improve & Maintain Diesel Generator Reliability "
  SCHNELL, DF Union Electric Co 84/08/14 EISENHUT, D G Division of Licensing 2pp 26194 078 24% Fiche 50-483,84/08/14. 8409920278
- 8408210313 Forwards revised FSAR App 7A pages addressing NRC 840625-26 requests for add1 info re Reg Oulde 1 97 As-built plant design info not included in original submittal incorporated Design provides info required to satisfy Rev 2 to reg guide PETRICK, N A Standardized Nuclear Unit Power Plant System 84/08/16 DENTON, H R Office of Nuclear Ceator Regulation. Director 65pp 26179 060 24X Fiche 50-000.84/08/16.8408210313
- 8408230170 Confirms 840820 meeting to discuss proposed escalated anforcement action of Tech Specs violation re facility being in operational Mode 4 w/both containment spray sys trains incoerable inoperable KEPPLER.J G Region 3, Office of Director B4/09/17 SCHNELL Union Electric Co ip 26209 276 24% Fiche 30-483.84/08/17. SCHNELL, D F 8408230170
- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for GLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT. D 0 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000.84/08/20.8408200275
- 8408280279 Informs of 840815 conference call between Containment Sys Branch & ut(1 to discuss Tech Spec 3/4 6 3 re surveillance requirement for MSIVS Passive sys (steam generators & associated piping) considered blind flange HOLONICH: J J Licensing Branch 1 84/08/23 LITTLE.B NRC No Datailed Affiliation Given 1p 26274 089 24X Fiche, 50-483, 84/08/23, 8408280279
- G Inspection reports: IE Bulletins & correspondence
- 8408230220 Forwards IE Insp Rept 50-483/84-21 on 840516-9630 No noncompliance noted
  WARNICK.R F Region 3, Office of Director 84/07/26 SCHNELL,
  Union Electric Co. 2pp 26213 339 24X Fiche 50-483,84/07/26. 8408230220
- --8408230233 IE Insp Rept 50-483/84-21 on 840516-0630 No noncompliance or deviations noted Major areas inspected SER items, licensee events, OA for startup test program, initial fuel load witnessing & plant tours FORNEY, Will Region 3, Office of Director 84/07/25 iOpp 26213 341 24X Fiche 50-483.84/07/26,8408230220
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Syr list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc. 119pp 23865 047 24% Fiche 30-000,84/07/27,8407250229
- 8408160184 Forwards 1E Insp Rept 50-483/84-31 on 840611-0713 & notice of violation SPESSARD, R L Region 3. Office of Director 84/07/30 SCHNELL, Union Electric Co 2pp 26106 319 24% Fiche 50-483.84/07/30, 8408160184 BCHNELL D. F.

- --B408160190 Notice of violation from insp on 840611-0713 SPESBARD.R L Region 3, Office of Director 84/07/30 1; 26106 321 24% Fiche 50-483.84/07/30.8408160184
- --8408i&0193 IE Insp Rept 50-483/84-31 on 840411-0713 Noncompliance noted failure to adhere to approved properational test procedure & failure to adequately review presperational test results FARBER.M J , MCCORMICK-BARGE, WOHLD, P R Region 3, Dffice of Director 84/07/30 Δpp 26106 322 24X Fiche 50-483,84/07/30,8408160184
- 8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during inspiratived effective 840820 Preprinted form will be used rather than ltr

  KEPPLER.J G Region 3. Office of Director 84/08/03
  Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000,84/08/03,8408070401
- B40B010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JGRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000.84/08/06.8408010337
- 8408100026 Ack receipt of 840706 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Rept 50-483/84-10 PAPERIELLO,C J Region 3. Office of Director 84/08/06 SCHNELL,D F Union Electric Co ip 25990 159 24X Fiche 50-483.84/08/06.8408100026
- --B408100034 Responds to NRC 840525 ltr re improvement items noted in IE Emergency Preparedness Appraisal Rept 30-483/84-10 Corrective actions role of shift advisors as county emergency operation ctr technical representative evaluated SCHNELL.D F Union Electric Co 84/07/04 PAPERIELLO.C J Region 3. Defice of Director. 8pp 25970 140 24X Fiche 30-483,84/08/06.8408100026
- 8408070120 IR Info Notice 84-61, "Overexposure of Diver in PWR
  Refueling Cavity " Svc list enci
  JORDAN.E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/08 Consolidated Edison Co of New
  York
- B40B070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Syz list enc! ORACE. J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125p 26130 CO1 24X Fiche 50-000.84/08/10.8408070376
- 8408140402 Ack receipt of 840724 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/89-23 Emergency buration flow adequacy of scaling Meters BG-FI-183A & B will be examined during future insp SPE8BARD, R L Region 3, Office of Director 84/08/10 BCHNELL, D Union Electric Co 1p 26052 337 24X Fiche 50-483,84/08/10,840814062
- --BA08140404 Responds to NRC 840625 itr re violations noted in IE Insp Rept 50-483/B4-23 Corrective actions util & Westinghouse performing review of startup field repts w/use-as-is dispositions Full compliance should be achieved by 840803 SCHNELL,D F Union Electric Co 84/07/24 SPESSARD,R L Region 3, Office of Director 5pp 26052 338 24X Fiche 50-483, 84/08/10,8408140402
- 8408100009 IF Info Notice 84-43. "Defective RHR Replacement Piping "

  Byc list encl
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000.84/08/13.8408100009
- 840B100038 IE Info Notice B4-64, "IWR HPCI Initiation Seal-In & Indication " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,840B100038

- 8408100021 IE Info Natice 84+65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl
  JDRDAN: E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc. 11889 26198 001 244 Fiche 50-000:84/08/16,8408100021
- 8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 OOI 24X Fiche 50-000.84/08/17.8408100055
- 8408140208 IE Info Notice 84-67. "Recent Snubber Inservice Testing W/ High Failure Rates" Svc list enc! JORDAN, E. Division of Emergency Proparedness & Engineering Response (Post 830107) 84/08/17 Consolidated Edison Co. of New York, Inc. 122pp 26276 122 24X Fiche 50-000.84/08/17.8408140208
- 8408210142 IE Info Notice 84-68, "Patential Deficiency in Improperly Rated Field Wiring to Solenoid Valves "Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 24329 008 24X Fiche 50-000.84/08/21,8408210142
- 8408280227 Board Notification 84-145 provides info re fire protection concern discovered during insp Based on preliminary insp.NRC datermined safety evaluation for alternate shutdown capability incorrect EISEN-RUT, D G Division of Licensing 84/08/24 PALLADING Consolidated Edison Co of New York. Inc 3pp 26322 128 24X Fiche 50-000,84/08/24.8408280227
- S Reportable occurrences, LERs & related correspondence
- 8408010386 Supplemental final deficiency rept re generic defects in Gould/Rundel 4-position & 2-position selector switches failure Initially reported on 840209 Falled units to be replaced from alternate supplier
  SEIKEN.S J Standardized Nuclear Unit Power Plant System 84/07/20 COLLING.J T Region 4. Office of Director 2pp 25866 284 24X Fiche 50-000.84/07/20.8408010386
- 8408030255 Interim Significant Deficiency Rept 8DR 84-04 re Limitorque operator motor pinion/worm shaft clutch gear failure Limitorque will conduct cycle tosting & Hestinghouse will conduct metallurgical tests Next rept expected by 840930 BEIKEN.E J Standardized Nuclear Unit Power Plant System 84/07/20 KEPPLER.J O Region 3. Office of Director CDLLINS.J T Region 4. Office of Director 3pp 25917 234 24X Fiche 50-000,84/07/20, 8408030255
- B408070123 LER B4-006-01 on B40618, sample pump for vent wide range gas monitor turned off, causing alarm Caused by operator error Alarm response procedure issued for RM-11 & RM-23 radiation monitor control & display modules W/840725 ltr DAVIS, J. E., MILTEMBERGER: 8. Union Electric Co. 84/07/25 4pp 25953 109 24X Fiche 50-483, 84/07/25, 8408070123
- 8408060148 Requests LERs 84-002-00 & 84-005-00 re malfunction of plant security hardware be removed from PDR, per 10CFR73 21 Util now considers LERs as safeguards info MILTENBERGER, 8 Union Electric Co 84/07/30 Record Services Branch (Document Control Desk) 2pp 25923 308 24X Fiche 50-483,84/07/30,8408060148
- 8408090271 LER 84-019-00 on 840719, fuel bldg ventilation isolation signal actuated by fuel bldg radiation monitor alarm Caused by monitor not powered & feeder breaker accidentally opened Radiation monitor restored W/840730 ltr DAVIS, J E , MILTENBERGER, 8 Union Electric Co 84/07/30 4pp 25994 144 24X Fiche 50-483, 84/07/30, 8408090271
- 8408160174 LER 84-015-00 on 840716, pressure transient occurred in RCS as result of loss of instrument air To reduce pressure, PCRV cycled Manuelly Instrument air lost again & PCRV actuated automatically M/840810 ltr
  TAYLOR, Mr E. MILTENBERCER, S. Union Electric Co. 84/08/10 4pp
  26108 047 24X Fiche 50-483, 84/08/10,8408160176
- B40B160256 LER 84-014-00 on 840714, high flux at shutdown alarm received from source range monitor SE-NT-31B Caused by dirt & moisture on source range monitor cable connectors Connectors cleaned & dried Unit functioned satisfactorily W/840810 ltr TAYLOR, M E . MILTENBERGER, S Union Electric Co 84/08/10 4pp 26106 184 24X Fiche 50-483, 84/08/10, 8408160256
- 8408200324 PNO-III-84-064 on 840813,1,200 gallons of water from refueling water storage tank injected into primary sys via baron injection tank No release of radioactivity occurred Caused by faulty electrical channels FORNEY, W. WARNICK, Region 3, Office of Director 84/08/13 ip 26133-001 RAX Fiche 50-483,84/08/13,8408200324

- 8408240193 LER 84-016-00 on 840717, RCS depressurized to 0 psig & OBB240173 LER 84-016-00 on 84071/: ACS depressurizes to Upsig Sprimary seal on reactor coolant pump C damaged Caused by improper sequence of valve operation on RHR pump A procedure restoration Seal replaced W/840816 ltr TAYLOR, ME , MILTENBERGERS Union Electric Co 84/08/16 dpp 26236 234 24X Fiche 50-483,84/08/16,8408240193
- 8408230427 LER 84-021-00 on 840719. Train A of SSPS found in inhibit mode w/Train B in test Train B returned to normal Surveillance procedure changed w/B40817 ltr NASLUND.C D . MILTENBERGER.S Union Electric Co 84/08/17 5pp 26213 044 24% Fiche 50-483. 84/08/17. 8408230427
- 8408230546 LER 84-018-00 on 840718, fuel bldg isolation & control room ventilation isolation signals initiated from radiation monitoring elements Caused by brief voltage abnormality during bus realignment Design change requested W/840817 ltr NASLUND.C D., MILTENBERGER,S Union Electric Co. 84/08/17 4pp 26213 001 24X Fiche 50-483.84/08/17,8408230546
- 8408240315 Special Rept 84-01 on 840718, PGRVs BB-PCV-439 & BB-PCV-456 lifted while starting reactor coolant pump B w/RCS in solid plant condition Administrative limit established for Delta T before starting reactor coolant pump MILTENBERGER, S Union Electric CO 84/08/17 KEPPLER, J G Region 3, Defice of Director 3pp 26236 327 24X Fiche 30-483,84/08/17. 3. Office of Director 8408240315

#### V Operator Examinations

- 8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners WALKER, R D Region 3. Office of Director 84/08/10 Michigan. Univ ef. Ann Arbor. MI 2pp 26051 84/08/10,8408140426
- 8408170089 Forwards list of ref matl required for operator/senior operator licensing exam & administration of operator licensing written exam, in preparation for 841106-08 exam Matl requested by 840924 MALKER, R D Region 3, Office of Director 84/08/14 SCHNELL, D F Union Electric Co 5pp 26119 067 24% Fiche 50-493, 84/08/14, BACKER, CORP.

### DOCKET STN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1

- I Financial information
- 8408240224 Forwards Duke Power Co & North Carolina Municipal Power Agency 1 1983 annual repts TUCKER,H B Duke Power Co 84/08/16 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 26237 137 24X Fiche 50-000,84/08/16,8408240224
- --8408240242 "1983 Annual Rept " LEE:W 5 Duke Power Co 83/12/31 47pp 26237 167 24X Fiche 50-000,84/08/16,8408240224

### DOCKET STN-50-492 CHEROKEE NUCLEAR STATION, UNIT 2

- Financial information
- 8408240224 Forwards Duke Power Co & North Carolina Municipal Power Agency 1 1983 annual repts TUCKER.H B Duke Power Co 84/08/16 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 26237 137 24X Fiche 50-000.84/08/16.8408240224
- --8408240242 "1983 Annual Rept "
  LEE,W 9 Duke Power Co 83/12/31 47pp 26237 167 24X
  Fiche 50-000,84/08/16,8408240224

### DOCKET STN-50-493 CHEROKEE NUCLEAR STATION, UNIT 3

- I Financial information
- 8408240224 Forwards Duke Power Co & North Carolina Municipal Power Agency 1 1983 annual repts
  TUCKER, H B Duke Power Co 84/08/16 DENTON, H R Di
  Nuclear Reactor Regulation, Director 2pp 26237 137
  Fiche 50-000,84/08/16,8408240224 Office of
- --8408240242 "1983 Annual Rept " LEE.W S Duke Power Co 83/12/2 Fiche 50-000,84/08/16.8408240224 83712731 47pp 26237 167

- DOCKET 50-496 MONTAQUE NUCLEAR POWER STATION: UNIT 1 O Inspection reports. IE Bulletins & correspondence
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intruston in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN.E t. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co 7/27 Consolidated Edison Co of New 24X Fiche 50-000.84/07/27.8407250229 25865 047
- 840B010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list end!

  JORDAN E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000.84/08/06.8408010233
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN: EL Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 138 24X Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list enc! JURDAN E L Division of Emergency Preparedness & Engineering Response (Post 630103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Ficho 50-000,84/08/08,8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc Patients Undergoing Compositions of Patients and Inspection Programs (Post B30103) 84/08/10 Consolidated Edison Co. of New York, Inc. 125pp. 26130 001 24X Fiche 50-000:84/08/10.8408070376
- B408100009 IE info Notice 84-63, "Defective RHR Replacement Piging "
  Svc list enc!
  JURDAN:E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fichs 50-000,84/08/13,8408100009
- 8408100039 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication "Syc list and URDANE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York Inc 104pp 26198 093 24X Fiche 50-000.84/08/15.8408100038
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021
- 8408100055 IE Info Notice 84-46, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100085
- 8408140208 IE Info Notice 84~47, "Recent Shubber Inservice Testing H/ High Failure Rates " Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc 122pp 24276 122 24X Fiche 50~000.84/08/17,8408140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves." Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Cansolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142
- DOCKET 50-497 MONTAGUE NUCLEAR POWER STATION, UNIT 2 G Inspection reports. IE Bulletins & correspondence
- 8407250229 IE Info Notice 84-57, "Operating Experience re Maisture IO72D022? IE Info Notice 84-97, "Operating Experience re Maisture
  Intrusion in Safety-Related Electrical Equipment at
  Commercial Power Plants " Svc list encl
  JORDAN, E.L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/07/27 Consolidated Edison Co. of New
  York, Inc. 119pp 25865.047 24X Fiche 50-000,84/07/27,8407250229
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list and JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc 122pp. 26068 001. 24X Fiche 50-000.64/08/06, 8408010333

- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp. 26067 158 24% Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDÁNIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York Inc. 120pp 26129 118 24X Fiche 50-000.84/08/08.8408070120
- 8408070376 tE Info Notice 84-62. "Therapy Misadmanistrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc
  - Patients Undergoing Co-60 Teletherapy Treatments "Syc list enc! GRACF, J N Division of QA, Safeguerds & Inspection Programs (Post B30103) 84/08/10 Consolidated Edison Co of New York, Int 125pp 26130 001 24X Fiche 50-000
- 840B100009 IE Info Natice 84-63, "Defective RKR Replacement Piping "
  Svc list encl
  JGRDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fichs 50-000,84/08/13,8408100009
- 8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Syc list encl JDRDAN E L Division of Emergency Preparednass & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24x Fiche 50-000,84/08/15,8408100038
- B40B100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Syc list encl
  - list encl
    JORDAN.E L Division of Emergency Preparedness & Engineering
    Response (Post 830103) 84/08/16 Consolidated Edison Co of New
    York, Inc. 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021
- 840B100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17.8408100055
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ Migh Failure Rates " Svc list encl JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York Inc 122pp 26276 122 24X Fiche 30-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-6B, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/08/21 Consolidated Edison Co. of New York, Inc 115pp 26327 008 24X Fiche 50-000.84/08/21,8408210142
- DCKET SIN-50-498 SOUTH TEXAS PROJECT, UNIT 1
- Application/construction stage documents & correspondence
- B40B210311 Forwards Rev 5 to GA program description for design & const phases includes revs to Bechtel & Ebasco programs OFREA:0 W Houston Lighting & Power Co B3/11/01 COLLING.J T Region 4, Office of Director 5pp 26179.001 24X Fiche 50-498.83/11/01.8408210311
- -8408210317 Rev 5 to GA program for design & const of South Texas Project
  \* Houston Lighting & Pawer Co 83/11/01. 54pp 26179 006 24X
  Fiche 50-498,83/11/01.8408210311
- 8408210500 Forwards Rev 4 to 6A program description for design & const phase of facilities Changes clarify definition of Dechtel div quality policies & defines responsibilities for trend
- OPREA, G W OFREA,G W Houston Lighting & Power Co 84/04/02 COLLING.J T Region 4, Office of Director 3pp 26148 175 24x Fiche 50-498.84/04/02:8408210500
- facilities
  - \*\* Houston Lighting & Pawer Co. 84/04/02 190pp 26148 178 24X Piche 50-498,84/04/02,8408210500
- B40B07044& Requests exemption from 10CFR50. App A, GDC 4 re elimination of postulated circumferential & longitudinal breaks in RCB main loop piping & WCAP-10359 & WCAP-10360 Repts withheld (ref 10CFR2 790)

  GCLDBERG, J H Houston Lighting & Power Co B4/07/17 DENTON, H R Office of Nuclear Regulation. Director 4pp 25940 347 24X Fiche 50~498.84/07/17, 2408D70446

- --B408070456 'Safety Balance for Elimination of RCS Main Loop Pipe Break Protective Devices, South Texas Project, Units 1 & 2 " Response to NRC request for addl info re leak before break # Bechtel Corp 84/04/05 14pp 25940 353 24x
  Fiche 50-498, 84/07/17, 8408070446
- --B408070465 Requests withholding of WCAP-10559 & WCAP-10560, "Technical Bases for Eliminating Large Primary Loop Pipe Rupture as Structural Design Basis for South Texas Project, Units 1 & 2" (ref 10CFR2 790) er tree 100,482 7907 WIESEMANN, R A Wostinghouse Electric Corp 84/06/01 Office of Nuclear Reactor Regulation, Director App 24X Fiche 30-498,84/07/17,8408070446 DENTON, H. R.
- B408090497 Summary of B40717 meeting w/Westinghouse Owners Steam Generator Tube Rupture Subgroup in Bethesda, MD re proposed steam generator tube rupture generic program List of attendees & viewgraphs enci STNOH, B K Licensing Branch 3 84/07/31 Licensing Branch 3 18pp 25983 130 24X Fiche 50-000,84/07/31.8408090497
- 840B070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933. "Prioritization of Generic Safety Issues" Svc list enci EISENHUT,D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26127 238 24% Fichs 50-000,84/08/06.8408070110
- B40Bi70282 Responds to 840727 submittal of Rev 7 to GA progrem for design & const phase Submittal satisfies requirements of iOCFR50, App B Rev 7 acceptable
  JOHNSON, E H Region 4, Office of Director 84/08/14 IPREA, G W Houston Lighting & Power Co 2pp 26/14 230 24X
  Fiche \$0-498,84/08/14,8408170282
- 8408220161 Forwards draft "in furtherance" certificate re issuance of pollution control revenue bonds, for review Necessary mods & signed certificate requested by 840715
  GOLDBERG, J H Houston Lighting & Power Co 84/08/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 26174 042 24% Fithe 50-478,84/08/14.8408220161
- 8408200275 Generic Ltr 84~20 to all licensees of operating reactors & applicants for Ols re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Syc list encl EISENHUT.D C Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000,84/08/20,8408200275
- B40B270355 Opposes requirement re designing for arbitrary intermediate breaks Approval for listed alternative pipe break criteria requested, excluding RCB primary loop Addl info supporting request entl
  GOLDBERG, J. H. Houston Lighting & Power Co. 84/08/20
  Office of Nuclear Reactor Regulation, Director. 19pp.
  24X Fiche 50-498, 84/08/20, 8408270355

### G Adjudicatory correspondence

- 8408080186 Motion for enlargement of page limitation for appellate brief in response to Citizens Concerned About Nuclear Fawer. Inc 840708 brief on appeal of partial initial decision Certificate of 8vc encl Related correspondence QUTTERMAN.A H Houston Lighting & Power Co GUTTERMAN.A H Newman & Holtzinger DSB 824 84708706 Atomic Safety and Licensing Appeal Panel App 25960 243 24X Fiche 50-498,84708/06,8408080186
- 8408i50077 Response to applicant 840808 motion for enlargement of page limitation of appellate brief to 90 pages No objection offered Centificate of Svc encl PIRFO, O R Hearing Branch 3 DSB 043, 84/08/10 Atomic Safety and Licensing Appeal Pamel 3pp 26067 018 24X Fiche 50-498.84/08/10.8408i50077
- 8408130138 Motion for enlargement of page limitation of appellate brief to 90 pages Certificate of Svc encl Related correspondence FIRFO.O R Hearing Branch 3 DSB 039 84/08/11 Atomic Safety and Licensing Appeal Panel 3pp 24067 013 24X Fiche 50-498.84/08/11.8408150138
- 8408190176 Motion for enlargement of page limitation of appellate brief to 90 pages Oranted for ASLAB on 840813 PIRFO O R Hearing Branch 3 DSB 054 84/08/11 Atomic Safety and Licensing Appeal Panel ip 26066 313 24X Fiche 50-498.84/08/11.8408150176

- 8408160196 Response opposing Citizens Concerned About Nuclear Power, Inc 840708 brief on appeal from ASLB 840314 partial initial decision Request for de novo review & ab initio opinion w/o ment Certificate of Svc enci NEWMAN.J R Houston Lighting & Power Co NEWMAN.J R Newman & Holtzinger DSB 075 84708713 Atomic Safety and Licensing Appeal Panel 94pp 26091 004 24X Fiche 50-498.84/08/13.
- 8408280376 Brief in response to Citizens Concerned About Nuclear Power brief on appeal from ASL8 840314 partial initial decision Centificate of Svc encl REIS.E J. PIRFO.O R Hearing Branch 3 DSB 340 84/08/23 Atomic Safety and Licensing Appeal Panel 85pp 26280 046 24X Fiche 50-498.84/08/23.8408280376
- B408280452 Response to ABLB 830622 memorandum & order re reportability of Quadrex rept Quadrex rept should be examined under 10CFR50 55(e) Applicants should have provided rept to ABLB in May 1981 Certificate of Svc encl PERLIS.R G Hearing Branch 3 DSB 338 84/08/24 43pp 26281 266 24% Fiche 30-498.84/08/24 8408280452
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B408010222 Forwards Amend 39 to Bouth Texas Project.Units i & 2 FBAR, incorporating revised response to NRC questions & miscellaneous FBAR text revs & editorial changes GDLDBERG, J H Houston Lighting & Power Co 84/07/27 DENTON, H Office of Nuclear Reactor Regulation. Director 8pp 25901 017 24X Fiche 50-498,84/07/27,8408010222
- --8408010225 Amend 39 to South Texas Project, Units 1 & 2 F6AR \* Houston Lighting & Power Co 84/07/27 1,350pp 25901 025 24X Fiche 50-498.84/07/27.8408010222
- Q Inspection reports, IE Bulletins & correspondence
- 8407250229 IE Info Notice 84-57. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229
- 8408270212 Forwards refinements & changes to 840221 response to notice of violation in Insp Rept 83-22 re improvements to matl control program Current program provides adequate control of safety-related matls

  OPREA.6 W Houston Lighting & Power Co 84/07/30 COLLINS, J T Region 4, Office of Director 4pp 26240 244 24X

  Fiche 50-498.84/07/30.8408270212
- 8408200277 Forwards IE Insp Repts 50-498/84-10 & 50-499/84-10 on 840625-29 No violations noted JOHNSON,E H Region 4, Office of Director 84/08/02 OPREA.O W Houston Lighting & Power Co 2pp 26140 106 24% Fiche 50-498,84/08/02,8408200297
- --8408200304 IE Insp Repts 50-496/84-10 & 50-499/84-10 on 840625-29 No violations noted Major areas inspected safety-related structural steel JOHNSON,C E. JAUDON, J P. Region 4, Office of Director 84/08/02 App 26140 108 24X Fiche 50-498,84/08/02,8408200299
- B408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 OOI 24X Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc J23pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- 8408100132 Forwards QA vendor imap repts for info & evaluation Util should evaluate significance of findings Ack of receipt requested W/o encl
  JOHNSON.E H Region 4, Office of Director 84/08/06 OPREA.G W Houston Lighting & Power Co 2pp 25788 283 24%
  Fiche 50-498,84/08/06,8408100132
- B408070120 IE Info Notice B4-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list enci JORDAN: E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York: Inc 120pp 26127 118 24% Fiche 50-000:84/08/08.8408070120

- B40B070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list enc! GRACE.J N Division of GA, Safeguards & Inspection Programs (Post B30103) 84/08/10 Consolidated Edison Co of New York. Inc 123pp 26130 001 24x Fiche 50-000.84/08/10.8408070376
- 840B100009 (E Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JDRDAN.E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 94/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000.84/08/13, 840B100009
- 840B10D03B IE Info Notice 84-64, "BWR HPC! Initiation Seal-In & Indication " Svc list encl DBD0AN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26178 073 24% Fiche 50-000.84/08/15,8408100038
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26178 001 24X Fiche 50-000,84/08/16,8408100021
- B40B210070 Ack receipt of 840716 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/84-04 & 50-499/84-04 Corrective actions will be reviewed during future insp JOHNBON,E H Region 4, Office of Director 84/08/16 OPREA,Q W Houston Lighting & Power Co 2pp 26147 071 24X Fiche 50-498.84/08/16.8408210090
- --B40B210096 Responds to NRC B40614 ltr re violations noted in IE Insp Repts 50-49B/B4-04 & 50-499/B4-04 Corrective actions situstd for nonconformance reporting revised OPREA, GW Houston Lighting & Power Co B4/07/16 COLLING, J T Region 4, Office of Director 4pp 26147 073 24X Fiche 50-49B, B4/0B/16, 840B210090
- 8408100055 IE Info Notice 84-64. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of Net York, Inc 120pp 26276 001 24X Fiche 50-000.84/08/17.8408100055
- B40B14020B IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates." Svc list smrl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 30-000.84/08/17, 8408140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Bolenoid Valves " 8vc list encl URDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc 115pp 26329 008 24X Fiche 50-000.84/08/21.8408210142
- B Reportable occurrences, LERs & related correspondence
- 8408220i30 Third interim deficiency rept recorrosion in safety injection sys weld Initially reported on 831020 Weld removed for analysis to determine defects & insp of stainless steel tanks initiated Next rept will be submitted by 841116 CPREA.0 W Houston Lighting & Power Co 84/07/31 COLLINS.J T Region 4. Office of Director Spp 26189 038. 24X Fiche 50-498.84/07/31.8408220130
- 8408150389 Final deficiency rept re rear brackets for snubbers supplied by Nuclear Power Svcs Initially reported on 840704 B rear brackets will be replaced within 5 months OPREA:6 W Houston Lighting & Power Co 84/08/03 COLLINS: J T Region 4. Office of Director 5pp. 26077:352 24X Fiche 80-498:84/08/03.8408150389
- 8408240312 Third interim deficiency rept re corrosion in safety injection sys pipe weld Initially reported on 831020 Next rept will be submitted by 841116 OPREA:0 W Houston Lighting & Power Co. 84/08/10 COLLING.J T Repi
- 8408300370 Final Deficiency Rept DER 84-016 re ABTM A-194 Grade 2H & ABTM A363 Grade A nuts Initially reported on 840713 ABTM A363 Grade A std hex nuts will be purged from site. Item considered not reportable per 1007850 556:

  OPREA.6 W Houston Lighting & Power Co 84/08/20 COLLING.J T Region 4. Office of Director. 9pp 26308 231 24X Fiche: 50-498.84/08/20.84083000370

- TN-50-499 SOUTH TEXAS PROJECT, UNIT 2 lcation/construction stage documents & correspondence
- \*11 Forwards Rev 5 to GA program description for design & const Includes revs to Bechtel & Ebasco programs G W Houston Lighting & Power Co B3/1i/O1 COLLINS, J T . 4, Office of Director 5pp 26179 001 24X 50-498.83/11/01.8408210311
- 10317 Rev 5 to GA program for design & const of South Texas ject douston Lighting & Power Co 83/11/01 54pp 26179 006 24X ls 50-498,83/11/01,8408210311
- SOO Forwards Rev 6 to GA program description for design & const of facilities Changes clarify definition of Bechtel uality policies & defines responsibilities for trend
- sis Houston Lighting & Power Co 84/04/02 CDLLING.J T 14. Office of Director 3pp 26148 175 24X 50-498.84/04/02.8408210500
- 10503 Rev & to GA program description for design & const of ilities Hauston Lighting & Fower Co 84/04/02 190pp 26148 178 24X he 30-498.84/04/02.8408210900
- 446 Requests exemption from 10CFR30, App A, ODC 4 re elimination stulated circumferential & longitudinal breaks in RCS loop piping & WCAP-10559 & WCAP-10560 Repts withheld 10CFR2 790)
- ERO, J H Houston Lighting & Power Co 84/07/17 DENTON, H of Nuclear Reactor Regulation, Director 4pp 25940 349 iche 50-498,84/07/17,8408070446
- 70456 "Safety Balance for Elimination of RCS Main Loop Pipe Break tective Devices, South Texas Project, Units 1 & 2 " panse to NRC request for add1 info re leak before break lysis enci
  lysis enci
  B4/04/05 i4pp 25740 353 24X
  he 50-498.84/07/17,8408070446
- 70465 Requests withholding of WCAP-10559 & WCAP-10560, "Technical es for Eliminating Large Primary Loop Pipe Rupture as uctural Design Basis for South Texas Project/Units 1 & (ref 10CFR2 790)

  SEMANN,R A Hestinghouse Electric Corp 84/06/01 DENTON,H R fice of Nuclear Reactor Regulation, Director 6pp 25941 005

  Fiche 50-498.84/07/17.8408070446
- 497 Summary of 840717 meeting w/Westinghouse Owners Steam ator Tube Rupture Subgroup in Bethesda, MD re proposed generator tube rupture generic program List of dees & viewgraphs encl Licensing Branch 3 84/07/31 Licensing Branch 3 3 130 24% Fiche 50-000,84/07/31,8408090497 25983 130
- :110 Generic Ltr 84-19 to all licensees of operating reactors, cants for GLs & holders of CPs re availability of 1 to NUREG-0933, "Prioritization of Generic Safety 5." Svc list encl HUT.D 0 Division of Licensing 84/08/06 Consulidated n Co of New York, Inc. 18pp 26129 238 24X 50-000,84/08/06,8408070110
- 1282 Responds to \$40727 submittal of Rev 7 to GA program for n & const phase Submittal satisfies requirements of 150.App B Rev 7 acceptable 150.App B Rev 7 acceptable 160N.E H Resion 4. Office of Director 84/08/14 OPREA. 0 Won Lighting & Power Co 2pp 26114 230 24X 50-498.84/08/14.8408170282
- 161 Forwards draft "in furtherance" certificate re issuance of tion control revenue bonds, for review Necessary mods ned certificate requested by 840915
  ERG.J H Houston Lighting & Power Co 84/08/14 DENTON, H R of Nuclear Reactor Regulation, Director App 26194 042 iche 50-498,84/08/14,8408220161
- 275 Generic Ltr 84-20 to all licensees of operating reactors & cants for OLs re scheduling guidance for licensee ttals of reloads that involve unreviewed safety ions Svc list enr!
  HUT.D 0 Division of Licensing B4/0B/20 Consolidated in Co of New York, Inc 17pp 26276 244 24X 50-000.84/08/20:8408200275

- 8408270355 Opposes requirement re designing for arbitrary intermediate breaks Approval for listed alternative pips break criteria requested.excluding RCS primary loop Addl info supporting requested.excluding KUS primary 100p Audu. 1110 00pp. request encl
  ODLDBERG.J H Houston Lighting & Power Co. 84/08/20
  Office of Nuclear Reactor Regulation. Director 19pp.
  24X Fiche 50-498,84/08/20,8408270355 26245 021
- G Adjudicatory correspondence
- 8408080186 Motion for enlargement of page limitation for appellate brief in response to Citizens Concerned About Nuclear Power. Inc 840708 brief on appeal of partial initial decision Certificate of Eye encl. Related correspondence GUTTERMAN.A H Houston Lighting & Power Co GUTTERMAN.A H Newm & Holtzinger DSB 824 84/08/06 Atomic Safety and Licensing Appeal Panel 4pp 25960 243 24% Fiche 50-498.84/08/06.8408080186
- B4QB150077 Response to applicant B40B08 motion for enlargement of page limitation of appellate brief to 90 pages No objection offored Centificate of Svc encl PIRFO.OR Hearing Branch 3 DSB 043 84/08/10 Atomic Safety and Licensing Appeal Panel 3pp 26067 018 24% Fiche 50-498,84/08/10,8408150077
- 840Bi50i38 Motion for enlargement of page limitation of appellate brief to 90 pages Certificate of Svc encl Related correspondence PIRFO.O R Hearing Branch 3 DSB 039 84/08/11 Atomic Safety and Licensing Appeal Panel 3pp 24067 013 24X Fiche 50-498,84/08/11:8408150138
- 8408150176 Motion for enlargement of page limitation of appellate brief to 90 pages Granted for ASLAB on 940813 PIRFD.O R Hearing Branch 3 D80 054 84/08/11 Atomic Safety and Licensing Appeal Panel ip 26066 313 24X Fiche 50-498.84/08/11.8408150176
- 840B160196 Response opposing Citizens Concerned About Nuclear Power, Inc 84070B brief on appeal from ASLB 840314 partial initial decision Request for de novo revisus & ab initio opinion w/o merit Certificate of Svc encl NEWMAN, J. R. Houston Lighting & Power Co. NEWMAN, J. R. Newman & Holtinger DBB 075 84/08/13 Atomic Safety and Licensing Appeal Panel 94pp 26091 004 24X Fiche 50-498,84/08/13, 8408160196
- 8408280376 Brief in response to Citizens Concerned About Nuclear Power brief on appeal from ABLU 840314 partial initial decision Certificate of Svc encl REIS.E J. PIRFO.O R Hearing Branch 3 DSB 340 84/08/23 Atomic Safety and Licensing Appeal Panel 85pp 26280 046 24% Fiche 50-478,84/08/23,8408280376
- 8408280452 Response to ASL8 830622 memorandum & order re reportability of Guadrex rept Guadrex rept should be examined under 10CFR50 55(e) Applicants should have provided rept to ASL8 in May 1981 Certificate of Svc encl PERLIS.R G Hearing Dranch 3 DSB 338 84/08/24 43pp 26281 266 24X Fiche 50-498,84/08/24,8408280452
- K Utility Final Safety Analysis Report (FSAR) & amonds
- 8408010222 Forwards Amend 39 to South Texas Project. Units 1 & 2 FBAR. OBCIO422 Forwards Amend 39 to Bouth Texas Project, Unit: incorporating revised response to NRC questions & miscellaneous FBAR text revs & editorial changes GOLDBERG, J H Houston Lighting & Power Co 84/07/27 Office of Nuclear Reactor Regulation, Director 8pp 24X Fiche 50-498,84/07/27,8408010222
- --8408010225 Amend 37 to South Texas Project.Units 1 & 2 FSAR \* Hauston Lighting & Power Co 84/07/27 1:350pp 257 24% Fiche 50-498.84/07/27,8408010222 25701 025
- G Inspection reports: IE Bulletins & correspondence
- 8407250827 IE Info Notice 84-57. "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Byo list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc. 119pp 25865-047 24X Fiche 50-000.84/07/27,8407250229
- 8408270212 Forwards refinements & changes to 840221 response to notice of violation in Insp Rept 83-22 re improvements to mat) control program Current program provides adequate control of safety-related matis
  OPREALO W Houston Lighting & Power Co 84/07/30 COLLINS, J T Region 4, Office of Director 4pp 26240 244 24X
  Fiche 50-498,84/07/30.8408270212

- 8408200299 Forwards IE Insp Repts 50-498/84-10 & 50-499/84-10 on #840625-29 No violations noted
  JOHNSON,E H Region 4, Office of Director 84/08/02 OPREA.G W
  Houston Lighting & Power Co 2pp 26140 106 24X
  Fiche 30-498,84/08/02.8408200299
- ~-8408200304 IE Insp Repts 50-498/84-10 & 50-499/84-10 on 840625-27 No violations noted Major areas inspected safety-related structural steel JOHNSON,C E . JAUDON, J P Region 4, Office of Director 84/08/02 6pp 26140 108 24X Fiche 50-498.84/08/02,8408200299
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JOROAN, E. D. vision of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York (No. 840801033) 247 Etchs 50-000, 84/08/08, 840801033 Yark, Inc 122pp 26068 001 24x Fiche 50-000, 84/08/06, 8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/04 Consolidated Edison Co of New York, Inc 123pp 26067 138 24X Fiche 30-000,84/08/06,8408010337
- 840B100132 Forwards QA vendor insp repts for info & evaluation Util should evaluate significance of findings Ack of receipt requested M/a enci
  JOHNSON.E H Region 4. Office of Director 84/08/06 OPREA.G N
  Houston Lighting & Power Co 2pp 25788 283 24Y
  Fiche 50-498.84/08/06.8408100132
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24% Fiche 50-000,84/08/08,8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl list encl
  GRACE, J. N. Division of GA, Bafeguards & Inspection Programs (Post
  B30103) 84/08/10 Consolidated Edison Co. of New York, Inc
  125pp 24130 001 24% Fiche 50-000,84/08/10,8408070374
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping ' Svc list encl

  JORDAN, E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co Response (Post 830103) 84/08/13 Consollidated Edison Co of New York, Inc. 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408100038 IE Info Notice 84-64, "IWR HPCI Initiation Scal-In & Indication " Svc list encl 
  URBAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000.84/08/15.8408100038
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Syc list encl
- list ancl
  JORDAN.E L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/16 Consolidated Edison Co. of New
  York, Inc. 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021
- 8408210090 Ack receipt of 840716 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-498/84-04 & 50-499/84-04 Corrective actions will be reviewed during future insp JOHNBON,E H Region 4, Office of Director 84/08/16 OPREA.O W Houston Lighting & Pawer Co 2pp 26147 071 24X Fiche 50-498,84/08/16,8408210090
- --840B210096 Responds to NRC 840614 ltr re violations noted in IE Insp Repts 50-498/84-04 & 50-499/84-04 Corrective actions site std for nonconformance reporting revised OPREAG W Houston Lighting & Power Co 84/07/16 COLLINS, J T Region 4, Office of Director 4pp 26147 073 24X Fiche 50-498,84/08/16,8408210090
- 8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fichs 50-000,84/08/17,8408100055
- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperty Rated Field Wiring to Bolenoid Valves " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 1:55p 26329 008 24x Fiche 50-000.84/08/21.8408210142
- S Reportable occurrences, LERs & related correspondence
- 8408220130 Third interim deficiency rept to corrusion in safety injection sys wold Initially reported on 831020 Weld removed for analysis to determine defects & insp of stainless steel tanks initiated Next rept will be submitted by 841116 OPREA 0 W Houston Lighting & Power Co 84/07/31 CDLLINB J T Region 4, Office of Director Spp 26189 058 24X Fichs 50-498,84/07/31.8408220130
- 8408150389 Final deficiency rept re rear brackets for snobbers supplied by Nuclear Power Sycs Initially reported on 840706 8 rear brackets will be replaced within 6 months OPREA. 9 W Houston Lighting & Power Co 84/08/03 COLLINS. J T Region 4. Office of Director 5pp 26077 352 24X Fichs 50-498.84/08/03.8408150389
- 8408240312 Third interim deficiency rept re corrosion in safety injection sys pipe wold Initially reported on 831020 Next rept will be submitted by 841116 OPREAG W Howston Lighting & Power Co. 84/08/10 CCLLINS.J T Region 4. Office of Director 5pp 26236 322 24X Fiche 50-498.84/08/10.8408240312
- B40B300370 Final Deficiency Rept DER 84-016 re ABIM A-194 Orade 24 & ABIM A563 Grade A nuts Initially reported on 840713 ASIM A563 Grade A std hex nuts will be purged from site Item considered not reportable per 100CR350 S5(e) OPREA.0 W Houston Lighting & Power Co 84/OB/20 COLLING.J T Region 4, Office of Director 9pp 26308-231 24X Fichs 50-498,84/OB/20,8408300370
- DOCKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3 A Application/construction stage documents & correspondence
- B40B0B0175 Forwards proposed agenda for 840704 meeting to discuss status & project completion plans.per 840711 telcon Proposed supply sys role.ongoing programs & activities & concepts for acceptance of wark will be discussed SDREMSEN.O C Washington Public Power Supply System 84/07/31 E1BENHUT.D 0 Division of Licensing 3pp 25959 001 24X Fichs 50-440.84/07/31.8408080175
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREO-0933, "Prioritization of Generic Bafety Issues" Svc list enc! EISEMHUT, D 0 Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 R38 24X Fiche 50-000.84/08/06.8408070110
- 8408160404 Forwards "Juan De Fuca/North American Plate Convergence Beismic or Assismic Subduction" & "Study of Western Hashington Margin & Adjacent" "Weight oversize drawings Aperture cards in PDR GORENSEN. 0 C Washington Public Power Supply System 84/08/08 KNIGHTON, 0 W Licensing Branch 3 2pp 26084 157 24X Fiche 50-508.84/08/08,8408160404
- --B40Bi60405 "Juan De Fuca/North American Plate Convergence Beismic or Assismic Subduction " DAVIG.® A. Bouthern California: Univ. of: Los Angeles; CA COMMBS.H A., CROBSON.R S. Washington: Univ. of: Seattle: WA B4/08/31 60pp 26084 160 24X Fiche 50~508;84/08/08;8408160404
- --8408160407 "Study of Western Washington/Oregon Margin & Adjacent Juan De Fuca Plate," final rept KULM, V. Kulm, V 83/07/22 81pp 26084 221 24X Fiche 50-508,84/09/08,8408160404
- --8408160411 "Finite Element Investigation of Uplift & Strain in Puget Sound Region," final rept MELOSH, H J Melosh, H J 83/06/01 34pp 26084 304 24X Fiche 50-508, 84/08/08, 8408160404
- --8408160413 "Juan De Fuca Plate Comparison Task JFP-2 " W/five oversite tables Aperture cards in FDR. " Woodward-Clyde Consultants: Inc. 84/02/27 52pp 26084 337. 24X Fiche 50-508,84/08/08,8408160404.
- --8408160414 "JFP-3A Analysis of Geodetic Data " W/two oversize graphs OBIO0414 "OFF-3A - Analysis of Geografic Data Arthur Green, Apprior Cards in PDR PELTON, J.R. 83/05/25 150pp 26085 029 24X Fiche 50-508,84/08/08,8408160404

- 8408200275 Generic Ltr 84-20 to all licensees of operating reactors to applicants for DLs re scheduling guidance for licensee submittals of reloads that invalve unreviewed safety questions Svc list encl CIBCM-MVT.D 0 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 50-000,84/08/20,8408200275
- G Inspection reports. IE Bulletins & correspondence
- 8407250227 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants" Byc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24% Fiche 50-000.84/07/27.8407250229
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Int. 122pp 24068 001 24X Fiche 30-000.84/08/06.8408010333
- 8408010337 IE Info Natice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 8301031 84/08/06 Cansolidated Edison Co of New York, Inc 123pp 26067 188 24X Fiche 50-000,84/08/06,8408010337
- B408170255 Responds to IE Bullotin 84-02, "Failures of GE Type HFA Relays in Use in Class iE Safety Sys " Future use of GE Type HFA relays in safety-related sys not planned KOHLERA D Washington Public Power Bupply System 84/08/06 MARTIN, J Region 5, Office of Director 3pp 26/15 271 24X Fiche 50-505.84/08/06,8408170255
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Bvc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fiche 50-000,84/08/08,8408070120
- 8408070376 IE info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Byo list and GRACE, J N Division of QA, Bafeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24% Fiche 50-000,84/08/10.8408070376
- 840Bi00009 IE Info Notice 84-63, "Defective RHR Replacement Piping"
  Svc list encl
  JURDAN.E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) B4/0B/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000,84/0B/13,8408100009
- B40Bi0003B IE Info Notice 84-64. "BWR HPCI Initiation Seal-In & Indication " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " 8vc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp. 26178 001 24X Fiche 30-000.84/08/16.8408100021
- B408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list enc! JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- 8408140208 IE Info Notice 84~67, "Recent Snubber Inservice Testing W/
  High Failure Rates" Svc list encl
  JORDAN,E L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/17 Consolidated Edison Co of New
  York, Inc 122pp 26276 122 24X Fiche 50-000.84/08/17.8408140208
- 8408D10142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc. 115pp 26327 008 24X Fiche 50-000.84/08/21,8408210142

- 5 Reportable occurrences. LERs & related correspondence
- 8408200332 Part 21 rept re tension wires on Titus Grille, Model 272, not remaining in place when deflection blades closed Affected job sites identified in oncl Products being tested provide acceptable fix for retention SCHNEIDER.S L. Phillips Industries, Inc. 84/08/07 Director's Office, Office of Inspection and Enforcement 3pp 26/33 315 24x Fichs 50~000.84/08/07.8408200332
- Q Inspection reports, IE Bulletins & correspondence
- 8408170255 Responds to IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class iE Safety Sys " Future use of GE Type HFA relays in safety-related sys not planned KOHLER, A D Washington Public Power Supply System 84/08/06 MARTIN. J Region 5. Office of Director 3pp 26115 271 24X Fiche 50-508/84/08/06/8408170255
- DOCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1

  A Application/construction stage documents & correspondence
- 8408230318 Requests remittance of fee for 830121 application for extension of const completion dates
  DIGGS.R M License Fee Management Branch 84/08/16 PARRIS.H 9
  Tennessee Valley Authority 2pp 26236 078 24X
  Fiche 50-000.84/08/16.8408230318
- DOCKET 8TH-90-320 HARTSVILLE NUCLEAR PLANT, UNIT 3

  A Application/construction stage documents & correspondence
- B40B230318 Requests remittance of fee for 930121 application for extension of const completion dates DIGGS.R M License Fee Management Branch 84/08/16 PARRIS.H 9 Tennessee Valley Authority 2pp 26236 078 24X Fiche 50-000
- DOCKET 50-522 SKAGIT NUCLEAR POWER PROJECT, UNIT 1

  A Application/construction stage documents & correspondence
- 8408070110 Generic Ltr 84-19 to all litensues of operating reactors, applicants for DLs & holders of CPs re availability of Buppl 1 to NUREO-0933. "Prioritization of Generic Safety Issues" Svc list encl
  EISEMHUT, D G Division of Licensing B4/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24x
  Fithe 50-000.84/08/06.8408070110
- 840B200275 Generic Ltr 84-20 to all licensess of operating reactors & applicants for OLs re scheduling guidance for licenses submittals of reloads that involve Unravioued safety questions 8vc list enci EIBENHUT,D 0 Division of Licensing 84/08/20 Consolidated Edison Co of Now York, Inc 17pp 26276 244 24X Fiche 50-000,84/08/20,8408200275
- O Inspection reports, IE Bulletins & correspondence
- B407250229 IE Info Notice B4~57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants" Byc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc. 119pp. 25865 047 24X Fiche 50-000,84/07/27,8407250229
- B408010333 IE Info Notice B4-57, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JORDAN.E L Division of Emergency Proparedness & Engineering Response (Post 630103) B4/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24% Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notite 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " 8vc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 94047 158 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830107) 84/08/08 Consolidated Edison Co. of New York, Inc. 120pp 26127 118 24X Fiche 50-000.84/08/08.8408070120

- 8408070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " S/c list encl
  - IIST encl GRACE, J.N. Division of GA. Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co. of New York, Inc 125pp 26130 001 24% Fishe 30-000.84/08/10.8408070376
- 8408100007 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN.E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc. 119pp 26197 218 24X Fiche 50-000.84/08/13,8408100009
- 8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl UCRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Syclist encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc. 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021
- 8408100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Fredwater Train " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc. 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- 8408140208 IE Info Notice 84-67, "Recent Shubber Inservice Testing W/ High Failure Rates " Byc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84~68. "Potential Deficiency in Improperly Rated Field Wiring to Solenald Valves " Svc list encl JORDAN,E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc. 115pp 26329 008 24X Fichs 50~000,84/08/21,8408210142
- DOCKET 50-523 SKAOIT NUCLEAR POWER PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- B40B070110 Generic Ltr 84-19 to all licenses of operating reactors, applicants for OLs & holders of CPs re availability of Suppl I to NUREQ-0933, "Prioritization of Generic Safety Issues "Svc list encl EISENHUT, D G Division of Licensing 84/08/04 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000.84/08/06,8408070110
- B40B200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT, D 0 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 50-000.84/08/20.8408200275
- Q Inspection reports: IE Bulletins & correspondence
- 8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865.047 24X Fiche 50-000.84/07/27,8407250229
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" 8vc list encl JURDAN, E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc 122pp. 24068 001 24X Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Maet Efficiency Requirement" Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/08/06. Consolidated Edison Co. of New York, Inc. 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp. 26129 118 24X Fiche 50-000,84/08/08,8408070120

- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list onct GRACE.J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York. Inc 125pp 26130 001 24% Fiche 30-0000.84/08/10.8408070376
- B40B100007 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) B4/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 840Bi00038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication "Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 073 24X Fiche 50-000,84/08/15,8408100038
- B40B100021 IE Info Notice 84-65. "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24% Fiche 30-000,84/08/14,8408100021
- B408100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl. JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 001 24% Fiche 50-000,84/08/17. 8408100055
- 840B14020B IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " 8vc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24% Fiche 50-000.84/08/17,8408140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Bolenoid Valves " Svc list encl JORDAN.E L. Division of Emergency Proparedness & Engineering Response (Post \$30103) 84/08/21 Consolidated Edison Co of New York, Inc. 115pp 26329 008 24X Fiche 50-000,84/08/21.8408210142
- DOCKET STN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1

  A Application/construction stage documents & correspondence
- B408090483 Forwards request for add1 info re isolation devices used in reactor protective sys Response requested within 2 wks of ltr receipt KNIOHTON, O W Licensing Branch 3 84/07/25 VAN BRUNT, E E Arizona Public Service Co 7pp 25983 153 24X Fiche 50-528,84/07/25,8408090483
- 8408090523 Summary of 840705 & 06 mgt meetings u/util.sechtel & C-E at site & in Phoenix.AZ.respectively.re actions that need to be taken prior to puel load Attendance list & viewgraphs encl LICITRALE A Licensing Branch 3 84007/27 Licensing Branch 3 80pp 25983 340 24X Fiche 50-528.84/07/27, 8408090523
- B408060317 Notifies that response to 840702 request for info re surveillance requirements for ESF actuation sys will be provided by 840901 VAN BRUNT,E E Artzona Public Service Co 84/07/31 KNIGHTON,G Licensing Branch 3 2pp 25936 036 24X Fichs 50-528,84/07/31, 8408040319
- 8408030144 Forwards table of Type A variables & revs & updates of compliance to Rag Guide 1 97, Rev 2, Types B, C & D variable requirements in response to 831203 request.

  VAN HRUNT, E E Arizona Public Service Co 84/08/01 KNIGHTON, G Licensing Branch 3 28pp 25911, 161 24X Fiche 50-528, 84/08/01, 8408030144
- 8408080048 Informs that response to NRC 840627 info request re control element assembly shroud will be be submitted by 840815 VAN BRUNT, E.E., Arizona Public Service Co. 84/08/02 KNIOHTON, Q.W. Licensing Branch 3. 1p. 25761 036 24% Fiche 50-528, 84/08/02, 840808048
- 840B100127 Forwards "Calculation of Trip Betpoint Values, Plant Protection Sys," in response to 830820 ltr VAN BRUNT,E E Afizona Public Servica Co 84/08/02 KNIGHTON, G Licensing Branch 3 lp 25791'042 24X Fiche 50-328,84/08/02,
- ---8408100137 Rev 0 to "Calculation of Trip Setpoint Values.Plant Protection Bys." \* Combustion Engineering. Inc CEN-286(V) R00 84/07/31 123pp 25791 043 24X Fiche 30-528.84/08/02.8408100127

- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of Suppl 1 to NUREG-0933. "Prioritization of Generic Safety Issues " Svc list enci EISENHUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X Fiche 50-000.84/08/06.8408070110
- 8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for JUI 1934
  TREMBLAY.P P Operating Reactors Assessment Branch 84/08/96
  HQLAHAN.Q M Operating Reactors Assessment Branch 13pp 23991 350 24% Fiche 50-000.84/08/06.8408090317
- B408200255 Informs of launching of new program to seek out concerns reconst & safe operation Ltr to all const workers inviting rept of concerns for investigation encl
  TURLEY, K Arizona Public Service Co B4/08/06 MARTIN. J Region
  5. Office of Director 3pp 26133 208 24X Fiche 50-528, 84/08/06, 840820255
- 840B130274 Forwards solid radwaste process control program in response to OH Knighton 840403 ltr to EE Van Brunt Solid radwaste process control program incorporates 830630 response to 830415 request for addl info VAN BRUNT.E E Arizona Public Service Co 84/08/07 KNIOHTON.G Licensing Brench 3 2pp 26010 008 24X Fiche 50-528.84/08/07.8408130274
- --8408130277 Solid raduaste process control program
  \* Arizona Public Service Co 84/08/07 9pp 26010 010 24X
  Ficho 50-528,84/08/07,8408130274
- 840B140227 Advises that GE Willer medical problem disclosed on NRC Form 396, will not impair ability to perform assigned job tasks Evaluation based on examining physician statement & mgt observation of past performance VAN BRUNT.E E Arizona Public Service Co 84/08/07 MARTIN, J B Region 5, Office of Director 1p 26055 309 24% Fiche 50-528,84/08/07.8408140227
- 8408150207 Forwards supply to util 840702 ltr re organizational structure; based on 840716 discussion Supply include removal of Note b ref from FSAR Page 13 1-28, Note b from Fage 13 1-28, Note b WAN BRUNT, E E Arizona Public Service Co 84/08/13 KNIGHTON, O Licensing Branch 3 App 26067 125 24X Fiche 50-528, 84/08/13, 8408150207
- 8408230367 Notification of 840822 & 23 meetings w/util.Bechtel & DDE at site to discuss evaluation of effects of water leaks on foundation stability LICITRA:E A Licensing Branch 3 84/08/14 KNIOHTON, Q W Licensing Branch 3 4pp 26230 350 24X Fiche 50~528.84/08/14, 8408230367
- B40B230369 Forwards proof & review Tech Specs for review & comments
  Final draft will be submitted 30 days prior to CL
  issuance W/o encl
  KNIQHTON,O W Licensing Branch 3 84/09/14 VAN DRUNT,E E
  Arizona Public Bervice Co 2pp 26230 348 24X
  Fiche 50-528,84/08/14,8408230369
- 840Bi7034B Forwards add1 fabrication info on Unit 1 control element assembly shroud assembly.per 840627 request Seventeen proprietary oversize drawings encl Drawings withheld (ref 10CFR2 790) Aperture card available in Central Files VAN BRUNT.R E Arizona Public Service Co 84/08/15 KN10HTON.G Licensing Branch 3 App 26145 001 24X Fiche 50-528,84/08/15,840Bi70348
- B408200275 Generic Ltr B4-20 to all licensees of operating reactors & applicants for DLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Bvc list enci EIBENMUT, D 0 Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24x Fiche 50-000.84/08/20.8408200275
- 8408240261 Forwards Rev 2 to "Pump & Valve Inservice Testing Program" & proposed changes to Rev 2 W/46 oversize drawings Aperture cards available in PDR VAN BRUNT.E E Arizona Public Service Co 84/08/21 KNIGHTON.G Licensing Branch G 3pp 26227 018 24X Fiche 50-528,84/08/21,8408240261
- --8408240263 Rev 2 to "Pump & Valve Inservice Testing Program"

  \* Arizona Public Service Co 84/07/16 20App 26227 021 24X

  "1- 50-528,84/08/21,8408240261

- 8408240289 Forwards mod to deviation request in FSAR Amend 13. Sections 98 2 1.98 2 2 5 Figures 98-8.9.10 & 11 Updated response to FSAR Question 9A-98 Part (2) also encl Changes will be incorporated in next FBAR amend VAN BRUNT.E E Arizona Public Service Co 84/08/21 KNIOHTON, Q ilicensing Branch 3 15pp 26223 199 24X Fiche 50-528, 84/08/21, 8408240289
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8407120136 Appeals denial of FOIA request for 27 documents referenced in 1975 EIB re faculity & all EIS supplemental EIS or similiar environ documents & FOIA fee walver decision RYAN.J A Streich, Lang, Weeks & Cardon 84/03/27 Office of the Executive Director for Operations 4pp 25557 018 24x Fiche 30-328.84/03/27, 8407120136
- B407120142 Responds to appeal re denial of FOIA request for 27 documents referenced in 1975 EIS re facility & all EIS, supplemental EIS or similar environ documents Appeal granted DIRCKB,W J Diffice of the Executive Director for Operations B4/05/21 RYAN,J A Streich, Lang. Weeks & Cardon ip 25557 022 24X Fiche 50-528, B4/05/21, 8407120142
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8408130331 Forwards update to 830127 description of natural circulation test program & "Evaluation of Natural Circulation Coolidown Test Performed at Sen Onofre Nuclear Concerning Station "Confirmatory Item 7 in NUREG-0857.8SER 5 closed VAN BRUNT.E E Arizona Public Service Co 84/08/07 KNIGHTON.G Licensing Branch 3 23pp 26006 170 24X Fiche 50-528,84/08/07.
- 8408270133 Forwards "Containment Ultimate Capacity Analysis," per NUREQ~0857, "SER re Operation of Palo Verde Nuclear Generating Station, Units 1,2 & 3 " Analysis should close license condition discussed in Section 3 8 1 VAN BRUNT,C E Arizona Public Service Co 84/08/20 KNIGHTUN,G Licensing Branch 3 3pp 26245 061 24X Fishe 50-528,84/08/20, B408270133
- --B408270140 "Containment Ultimate Capacity Analysis "
  # Arizona Public Bervice Co B4/08/31 38pp 26245 064 24X
  Fiche 50-528,84/08/20,8408270133
- F Security, medical, emergency & fire protection plans
- B40B09044B Notification of 840730-31 & 0801 meetings w/util & Comex in Phoenix.AZ & site.respectively.to discuss open issues in onsite emergency planning LICITRA.E A Licensing Branch 3 84/07/25 KNIGHTON,O W Licensing Branch 3 2pp 25983 213 24X Fiche 50-528.84/07/25, 8408070448
- 8408090523 Summary of 840703 \$ 06 mgt meetings w/util.Bechtel & C-E at site & in Phoenix.AZ.respectively.re actions that need to be taken prior to fuel load Attendance list & viewgraphs encl LICITRA.E A Licensing Branch 3 84/07/27 Licensing Branch 3 800pp 28983 340 24% Fiche 50-528.84/07/27,8408090523
- 8408130182 Forwards request for add1 info re evatuation time estimate analysis for emergency plan Response requested within 2 wks of ltr receipt KNIGHTON,G W Licensing Branch 3 84/07/27 VAN DRUNT,C E Arizona Public Service Co 3pp 26011 351 24X Fiche 50-528,84/07/27.8408130182
- 8408130160 Confirms 840625 teicon re outcome of 840531 appeal meeting re alternate shutdown capability Appeal granted, based on listed design features for plant & commitment to perform confirmatory PRA analysis
  NDVAK.T M Assistant Director for Licensing 84/07/30 VAN BRUNT, E Arizona Public Service Co 2pp 26034 351 24X
  Fichs 50-528,84/07/30,8408130160
- 8408030097 Forwards response to NRC 840605 comments re emergency procedure generation package Steps to verify adequate instruments & controls available for aperator to perform assigned task incorporated into validation procedure VAN BRUNT. E Arizona Public Service Co 84/08/01 KNIGHTON, O Licensing Branch 3 7pp 25704 342 24X Fiche 50-528,84/08/01,840800097
- 8408230310 Confirms 840822-24 audit of emergency operating procedures (EOPs) Five sets of current EOPs, along w/procedure generation package rev. should be provided to NRC by 840813 KNIGHTON, 6 W Licensing Branch 3 84/08/02 VAN BRUNT, E E Arizona Public Service Co 2pp 26236 100 24X Ficha 50-528,84/08/02,8408230310

- 8408300125 Forwards Insp Rept 50-528/84-26 on 840716-20 No violations or deficiencies noted SCHUSTER/M D Region 5. Office of Director 84/08/03 VAN BRUNT, E Arizona Public Service Co 2pp 26307 225 24X Fiche 50-528.84/08/03.8408300125
- --8408300127 Insp Rept 50-528/84-26 on 840716-20 No violations or deficiencies noted Major areas inspected open & improvement items identified during emergency preparedness preoperational 83041-22 insp TEMPLE.G M , FISH,R F , PRENDERGAST, K Region 5, Office of Director 84/08/03 9pp 26307 227 24X Fiche 50-528,84/08/03,8408300125
- B408300383 Forwards Insp Repts 50-528/84-25,50-529/84-19 & 50-530/84-12 on 840709-13 & notices of violation & deviation BISHOP, I W Region 5, Office of Director 84/08/08 VAN BRUNT, E Arizona Public Bervice Co 2pp 24308 122 24X Fiche 50-528,84/08/08,8408300383
- --8408300390 Notice of violation from insp on 840709-13 MILLER, L. Region 5, Office of Director 84/08/08 2pp 24308 124 24X Fiche 50-528,84/08/08,8408300383
- --840B300397 Notice of deviation from insp on 840709-13 MILLER, L. Region 5, Office of Director 84/08/08 1 2430B 126 24% Fiche 50-528,84/08/08,840B300383
- --B40B300407 Insp Repts 50-528/84-25,50-529/84-19 & 50-530/84-12 on B40709-13 Violations noted fire protection sys not designed to retain structural integrity during seismic event CLARK,C, NARBUT.P P, MILLER,L. Region 5, Office of Director 84/08/03 24pp 26308 127 24X Fiche 50-528,84/08/08,8408300383
- B408200599 Submits Rev 4 to emergency plan Rev addresses NRC comments, is aligned more concisely w/current operating procedures & clarifies barrier approach to emergency action levels VAN BRUNT, E E Arizona Public Service Co 84/08/15 KNIGHTON. Q Licensing Branch 3 3pp 26137 052 24X Fiche 50-528,84/08/15, 8408200599
- --9408200600 Rev 4 to emergency plan % Arizona Public Service Co 84/05/31 83pp 26137 055 24X Fiche 30-528,84/08/15,8408200599
- 8408200112 Forwards "Evaluation Time Analysis, 10-Mile Emergency Planning Zone, Arizona Div of Emergency Svcs" & response to 840727 request for addl info VAN BRUNT, E E Arizona Public Service Co 84/08/14 KN19HTON, O Licensing Branch 3 App 26132 321 24X Fiche 50-528, 84/08/16, 8408200112
- --8408200334 "Evacuation Time Analysis, 10-Mile Emergency Planning Zone, Arizons Div of Emergency Svcs "

  \* Arizons, State of BLUHM, R B Maricopa County, AZ 64/01/31 22pp 26132 325 24X Fiche 50-528,84/08/16,8408200112
- 8408200217 Forwards Rev 5 to emergency action levels Rev addresses comments raised at 840731 meeting re security, external events & challenge/failure of flaston product barriers VAN BRUNTLE Arizona Public Service Co 84/08/16 KNIGHTON.Q Licensing Branch 3 3pp 26133 099 24X Fiche 50-328,84/08/16.8408200217
- ---8408200224 Rev 5 to emergency action levels \* Arizona Public Service Co 84/08/31 86pp 26133 t02 24X Fiche 50-528,84/08/16,8408200217
- B40B270260 Requests approval of two temporary deviations in emergency preparedness plan from goals for augmentation of emergency response organization in Buopl 1 to NUREG-0737 Nature & duration of deviations encl VAN BRUNT.E E Arizona Public Service Co B4/08/20 KNIGHTON, Q Licensing Branch 3 27pp 26243 131 24x Fiche 50-528,84/08/20,640B270260
- K Utility Final Safety Analysis Report (FSAR) & amends
- B40B030102 Forwards page change list for Amend 13 to FSAR Replacement of original pages requested # Bechtel Corp 84/07/31 Office of Nuclear Reactor Regulation, Director 3pp 25904 336 24X Fiche 50-328,84/07/31,8408030102

- B408030093 Forwards page change list for Palo Verde Nuclear Generating Station FSAR. Amend 13. Pages A through J GILMORE. T Backtel Corp 84708/01 Defice of Nuclear Reactor Regulation. Director App 25916 031 24X Fiche 50-528. 84708/01. 8408030093
- 8408050075 Forwards info revising Insert 1 to FSAR.Page 14 2-3 reinitial test program
  VAN DRUNT.E E Arizona Public Service Co 84/08/01 KNIGHTON.O W
  Licensing Branch 3 7pp 25933 215 24X Fiche 50-528.84/08/01,
  840805075
- 8408010215 Amend 13 to FSAR for Palo Verde Nuclear Generating Station, Units 1.2 & 3 W/34 oversize figures Aperture cards available in PDR WAGO801 ltr VAN BRUNTLE E Artizona Public Service Co 84/08/31 1408pp 25797 122 24X Fiche 50-528.84/08/31.8408010215
- @ Inspection reports, IE Bulletins & correspondence
- 8406230210 "Region V Dutstanding Items Rept Open & Closed " \* Region 5, Office of Director 84/06/12 57pp 25129 101 24X Fishe 50-528.84/06/12.8406230210
- 8407250229 IE Info Notice 84-57. "Operating Experience re Maisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Comsolidated Edison Co of New York. Inc 119pp 23865 047 24X Fiche 50-000.84/07/27.8407250229
- 8408300187 Forwards Insp Repts 50-528/84-23 & 50-529/84-17 on 840402-0701 No honcompliance noted BISHOP, T W Division of Resident Reactor Project & Engineering Programs 84/08/02 VAN BRUNTE E Arizona Public Service Co 2pp 26308 014 24% Fiche 50-528.84/08/02.8408300187
- --B40B300195 Insp Repts 50-328/84-23 & 50-529/84-17 on B40402-0701 No violations noted Major areas inspected preoperational testing activities maint, review of maint & follows on TMI Lessons Learned implementation ZIMMERMAN R , FIORE LI.0 , BOSTED, C Region 5, Office of Director 84/08/01 12pp 26308 016 24X Fiche 50-528,84/08/02, 8408300187
- 8408300125 Forwards Insp Rept 50-528/84-26 on 840716-20 No violations or deficiencies noted SCHUSTER, M D. Region 5, Office of Director 84/08/03 VAN BRUNT, E. E. Arizona Public Service Co. 2pp. 26307-225 24X Fishe 50-528
- --8408300127 Insp Rept 50-528/84-26 on 840716-20 No violations or deficiencies noted Major areas inspected open & improvement items identified during emergency preparadness presperational 83041-22 insp
  TEMPLE.C M , FISH.R F , PRENDEROAST.K Region 5, Office of Director 84/08/03 9pp 26307 227 24X Fiche 30-528,84/08/03,8408300123
- B408010333 IE Info Notice 84-89. "Deliberate Circumventing of Station Health Physics Procedures " Svc list enc! JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 consolidated Edison Co. of New York, Inc. 122pp 26068 001 24X Fiche 50-000.84/08/06.8408010333
- B40B010337 IE Info Notice B4-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl UORDAN.E L Bivision of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 198 24X Fiche 50-000.84/08/06.8408010337
- 8408306094 Forwards Insp Repts 50-528/84-21, 50-529/84-16 & 50-530/84-10 on 840402-0931 & notice of violation BISKOP.T W Division of Resident, Reactor Project & Engineering Programs 84/08/07 VAN BRUNTLE Arizona Public Service Co 2pp 26306 141 24X Fiche 50-528,84/08/07,8408300094
- ---B408300100 Notice of violation from insp on 840402-0531. YDUNO.T Region 5. Office of Director 84/08/07 ip 26306 143 24% Fiche 30-528:84/08/07.8409300094
- --B408300103 Insp Repts 50-528/84-21.30-529/84-16 & 50-530/84-10 on B40402-0531 Violation noted failure to control mods on Units 1 & 2 diesel generator bldg wall mounted instruments VORDERIRRUGGEN, YOUNG, T Region 5. Office of Director 84/08/07 7pg 26306 144 24x Fiche 30-528,84/08/07,8408300094

- B40B070120 IE Info Notice B4-61, "Overesposure of Diver in PWR Refueling Cavity " Svc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/0B/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08.8408070120
- 8408300383 Forwards Insp Repts 50-528/84-25.50-529/84-19 & 50-530/84-12 on 840709-13 & notices of violation & deviation BISHOP.T W Region 5. Office of Director 84/08/08 VAN BRUNT.E Arizona Public Service Co 2pp 26308 122 24X Fiche 30-528.84/08/08.8408300383
- --8408300390 Notice of violation from insp on B40709-13 MILLER.L Region 5: Office of Director 84/08/08 2p 26308 124 24X Ficha 50-528.84/08/08.8408300383
- --B40B300397 Notice of deviation from insp on B40709-13 MILLER, L Region 5, Office of Director B4/08/08 1 2630B 126 24X Fiche 50-528,84/08/08,8408300383
- --B40B300407 Insp Repts 50-52B/84-25,50-529/84-19 & 50-530/84-12 on B40709-13 Violations noted fire protection sys not designed to retain structural integrity during seismic event CLARK,C, SORENSEN,R,C, HOLLENBACH,D, Region 5, Office of Director 84/08/03 24pp 26308 127 24X Fiche 30-52B,84/08/08, B40B3003B39
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list Enci GRACE.J N Division of GA. Bafeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 123pp 26130 001 24x Fiche 30-000.84/08/10.8408070376
- B408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN.E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 30-000,84/08/13,8408100009
- 9408100038 IE Info Nutice 84-64, "BWR HPCI Initiation Seal-In & Indication "Seal-In & Indication Seal-In & Indicated I
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " 8vc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 30-000,84/08/16,8408100021
- B408220051 Ack receipt of B40720 ltr informing NRC of steps taken to correct violations noted in IE lasp repts conducted between B40501-0601
  BISHOP, T W Region 5, Office of Director B4/08/16 VAN BRUNT, E E Arizona Public Service Co 1p 26193 237 24X ichs 50-528,84/08/16,8408220051
  - 3408220071 Responds to NRC 840722 ltr re violations noted in IE insprepts conducted between 840501-0601 Corrective actions Pump A disassembled & defective seal replaced w/new seal Walkdown team established VAN BRUNT, E E Arizona Public Service Co 84/07/20 BISHOP.T W Region 5, Office of Director 10pp 26193 238 24X Fiche 50-528,84/08/16,8408220051
- |408100055 IE Info Notice 84~66, "Undatected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276-001 24X Fiche 50-000.84/08/17.8408100055
- 840B14020B IE Info Natice 84-67, "Recent Enubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 122pp 26276 122 24X Fiche 50-000,84/08/17,840B140208
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York. Inc 115pp 24329 008 24X Fiche 50-000.84/08/21.8408210142

- S Amportable occurrences, LERs % related correspondence
- B40803004B Final Deficiency Rept DER 83-56, Rev 1 re discrepancies w/ Anchor-Darling MBIVs Initially reported on 83080B Larger hydraulic reservoir w/baffles installed in each MSIV & feedwater isolation valve VAN BRUNT.E E Arizona Public Service Co B4/04/13 BISHOP, 7 W Region 5, Office of Director 7pp 25917 330 24X Fiche 50-528,84/04/13,840803004B
- 8408020232 Corrected Rev i to Final Deficiency Rept DER 93-56 rp discrepancies w/MSIV mfg by Anchor-Darling Initially reported on 830808 Vendor Instruction Manual E7023-9 revised Also reported per Part 21 VAN BRUNT,E E Arizona Public Service Co 84/07/13 BISHOP,T W Division of Resident, Reactor Project & Engineering Programs 7pp 25898 046 24X Fiche 50-528,84/07/13,8408020232
- 8408030302 Final Deficiency Rept DER 84-02 re rust, scale & pitting in clevis & arm of several safety injection & CH valves Rust insignificant Deficiency determined not reportable under 10CFR50 55(e)

  VAN IRUNT, E E Arizona Public Service Co 84/07/13 BISHOP, T W Region 3. Office of Director 2pp 25917 115 24X Fiche 50-528, 84/07/13, 8408030302
- B408010377 Interin Deficiency Rept DER 84-18 re wiring error on LPSI pump B switch CS-3 Initially reported on 840326 Final rept will be submitted by 840822 VAN BRUNT, E E Arizona Public Service Co B4/07/16 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 25866 288 24X Fiche 50-528, 84/07/16, 8408010377
- 8408010381 Interin Deficiency Rept DER 84-09 rg ITT/Darton Model 763 transmitters not meeting specs Initially reported on 840229 Final rept will be submitted by 840824 VAN BRONT.E E Arizona Public Service Co 84/07/16 BISHOP, T W Division of Resident.Reactor Project & Engineering Programs 2pp 25866 290 24% Fiche 50-528.84/07/16,8408010381
- 8408010384 Interim Deficiency Rept DER 83-80 re main feedwater isolation valves closing in 20 s instead of Tech Spec required 5 s Initially reported on 831122 Final rept will be submitted by 840823 VAN BRUNT, E E Arizona Public Service Co 84/07/16 BIBHOP, T W Division of Resident Reactor Project & Engineering Programs 2pp 25866 286 24% Fiche 50-528,84/07/16,8408010384
- B408030240 Interim Deficiency Rept DER B3-63 re HPSI isolation valves mfg by Borg-Warner failing to open against pump A & B flows Initially reported on B30923 Time extension requested due to extensive investigation Next rept by B40831 VAN BRUNT.E E Arisona Public Bervice Co B4/07/16 BISHOP,T W Division of Resident Reactor Project & Engineering Programs 2pp 25917 221 24X Fiche 50-528,84/07/16,8408030240
- 8408010346 Final Deficiency Rept DER 82-37.Rev i.re Class 1E wiring termination crimped w/less pressure than specified Work Plant Procedure/QC Instruction 255 O revised to require maint program VAN BRUNT.E E Arizona Public Service Co 84/07/18 BISHOP.T W Division of Resident.Reactor Project & Engineering Programs 12pp 25866 310 24X Fiche 50-528.84/07/18,8408010346
- B408010388 Interim Deficiency Evaluation Rept 84-43 re HPSI 3-inch gate valve failing to open Initially reported on 840622 Conditions not reportable per 10CFR90 55(s) VAN DRUNT.E E Arizona Public Service Co 84/07/18 BISHOP.T W Division of Resident Reactor Project & Engineering Programs 2pp 25866 281 24% Fiche 50-528,84/07/18,8408010388
- 8408030053 Interin Potential Deficiency Rept DER 84-42 re replacement of environmentally qualified torque switches w/unqualified switches Initially reported on 840618 Final rept expected by 840820 VAN BRUNT, E.E. Arizona Public Bervice Co. 84/07/18 BISHOP, T.W. Region 5, Office of Director 3pp 25917 327 24X Fiche: 50-528,84/07/18,8408030053
- 8408080499 Final Deficiency Rept DER 83-75 re improper torquing of bolts on two D01268A panel filler assemblies Bolts retorqued Deficiency Not reportable under 100FR50 55(e) VAN BRUNT.E E Arizona Public Bervice Co 84/07/24 BISHOP,T W Division of Resident Reactor Project & Engineering Programs 5pp 25975 232 24% Fiche 50-528,84/07/24,8408080499
- 8408080527 Rev 1 to final Deficiency Rept DER Bi~49 re erroneous readings on NSBS water level transmitters due to variations of water leg Condensate pets for steam generator & pressurizer level measurements installed on root valves VAN BRUNT,E E Arizona Public Bervice Co. 84/07/24 BISHDP,T W Division of Resident/Reactor Project & Engineering Programs 4pp 25975 298 24X Fiche 50-528,84/07/24,8408080529,

- 8408090012 Final Deficiency Rept DER 84-08 re failure of ITT/Barton Model 763 transmitters to meet specs PPS setpoints revised on existing transmitters & Barton working on physical mod to meet specs Also reportable under Part 21 VAN BRUNTLE E Arizona Public Service Co 84/07/24 BISHOP,T W Division of Resident, Reactor Project & Engineering Programs App 25995 011 24X Fiche 50-528.84/07/24,8408090012
- 8408130172 Interim Deficiency Rept DER 83-81 re manufacturing defect in Gulfally Schedule (40 SS pipe Initially reported on 831128 Due to extensive investigation & evaluation required, final regt will be delayed until 840830 VAN BRUNT, E.E. Apricona Public Service Co. 84/07/27 BISHDP, T.W. Division of Resident, Reactor Project & Engineering Programs 2pp 24010 034 24% Fiche 50-528.84/07/27.8408130172
- 840Bi30332 Interin Deficiency Rept DER B4-09 re CAD welding for cathodic protection ground connection Initially reported on 840239 Final rept will be submitted by B40830 VAN BRUNT,E E Arizona Public Service Co 84/07/27 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 26010 303 24X Fithe 50-928,84/07/27,8408130372
- 840B130303 Final Deficiency Rept DER BA-19 re improperly tagged or marked blind flanges removed from piping sys Instially reported on B40430 Deficiency not reportable per 10CFR50 55(e) or Part 21 VAN BRUNT, E Arizona Public Service Co 84/07/30 BIBHOP, T W Division of Resident, Reactor Project & Engineering Programs 4pp 24010 251 24X Fiche S0-528,84/07/30.8408130303
- 8408130344 Interim Deficiency Rept DER 82-80 re low insulation resistance values or terminal blocks supplied by Conax Corp Initially reported on 821217 Final rept by 840817 VAN BRUNT.E E Arizona Public Service Co 84/07/30 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 26010 222 24X Fiche 50-528,84/07/30,8408130344
- B408160192 Final Deficiency Rept DER 84-10 re resistance tump detectors Caused by torsional twisting of element & sheath during honing operation, resulting in broken internal wire Item not reportable per 10CFR50 55(e)

  VAN BRUNT, E Arizona Public Service Co 84/08/01 BISHDP, T W Region 4, Office of Director 3pp 26106 334 24X Fiche 50-528,84/08/01,8408160192
- 8408170384 Final Deficiency Rept DER 84-22 re control element assembly shroud support contaminated w/oil Initially reported on 840420 Shroud cleaned & inspected & drip pan installed to contain possible leakage Also reported per Part 21 VAN IRUNT, E E Arizona Public Service Co 84708/01 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs App 26129 099 24X Fiche 50-528,84/08/01.8408170384
- 840B160480 Final Deficiency Rept DER 84-16 re EBF actuation sys relay cabinet baseplates Initially reported on 840321 Cabinet backs will be reinforced w/3/8-inch thick vortical stiffener plate Also reportable under Part 21 VAN BRUNT.E E Arisona Public Service Co 84/08/02 BISHUP, T W Division of Resident. Reactor Project & Engineering Programs App 26107 272 24X Fiche 50-528,84/08/02,840B160480
- B408160506 Final Deficiency Rept DER 83-78 re lack of users test documentation & controlling procedure for rock bolt expansion anchors Initially reported on B31107 Item not reportable under 10CFR50 55(e) & Part 21 VAN BRUNT.E E Artiona Public Service Co 84/08/02 DISHOP, T W Division of Resident, Reactor Project & Engineering Programs 9pp 26107 326 24% Fiche 50-528, 84/08/02, 8408160506
- 840822012B Interim Deficiency Rept DER 84-33 re incorrectly installed hanger support assembly Initially reported on 840504 Due to extensive investigation, final rept will be available 840831 instead of 840810 VAN DRUNT.E E Arisona Public Service Co 84/08/06 BISHDP, T W Division of Resident.Reactor Project & Engineering Programs 2pp 26188 348 24X Fithe 50-528,84/08/06.8408220128
- B40B220143 Interim Deficiency Rept DER 84-44 re fatigue failures of Gaulin charging pumps Initially reported on 840706 Dechtel investigating Final rept to be completed by 840927 Reported under Part 21 by Northeast Utils

  VAN BRUNT.E E Artiona Public Service Co 84/08/06 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 3pp 26188 065 24X Fiche 50-528, 84/08/06, 8408220143
- 8408200332 Part 21 rept re tension wires on Titus Orille, Model 272, not remaining in place when deflection blades closed Affected job sites identified in encl Products being tested provide acceptable fix for retention SCHNEIDER: S L. Phillips Industries, Inc. 84/08/07 Director's Office, Office of Inspection and Enforcement Jpp. 26133-315 24: Fichs 50-000,84/08/07,8408200332

- B408200333 Part 21 rept re tension wires used for adjustment of blades on Grille Model 272 not remaining in place when blades closed Review & testing conducted to identify number of grilles & rework methods to be utilized SCHNEIDER. S. L. Phillips Industries, Inc. 84/08/07 STRAIT,R Arizina Public Service Co. 1p. 26132-360 24X Fiche 50-528,84/08/07,8408200333
- B408200297 Interim Deficiency Rept DER 84-34 re critical friction-type high strength connectors Due to extensive evaluation, next rept delayed until 840904 VAN BRUNTLE E Arizona Public Service Co 84/08/09 BISHOP.T W Region 5, Office of Director 2pp 26140 090 24X Fiche 50-528.84/08/09.8408200297
- 8408200322 Final Deficiency Rept DER 63-61 re C-E low pressure safety injection pump failure to start & produce required head Case wear rings replaced & clearance between impeller & casing increased Proprietary CEM-285 (V)-P encl VAN BRUNT.E E Arizona Public Service Co 84/08/09 BISHOP, TW Division of Resident Reactor Project & Engineering Programs 40pp 26193 318 24X Fiche 50-528.84/08/09,8408200322
- 9408200285 Final Deficiency Rept DER 83-82 re improper bend radius in diesel generator control cabinets Initially reported on 840103 Forwards "Technical Rept for Palo Verde Nuclear Station-Bechtel Power Corp on Returned Cable NCR E63619 "VAN BRUNT, E E Arizona Public Service Co 84/08/10 BI9HOP, T W Region 3. Office of Director 13pp 26139 307 24% Fiche 50-528,84/08/10,8408200285
- ---9408200288 "Technical Rept for Palo Verde Nuclear Station-Bechtel Power Corp on Returned Cable NCR E63617 " MONTGOMERY:R , BEASLEY.B Anaconda Co (subs of Atlantic Richfield Co ) 84/01/24 11pp 26139 320 24X Fiche 50-528,84/08/10,8408200285
- 8408280302 Interim Deficiency Rept DER 83-57 re cracks in control element assembly shroud Initially reported on 830729 Requests extension until 840915 for submittal of final rept to allow for post-demonstration test insp evaluation VAN BRUNTLE E Arizona Public Service Co 84/08/13 BISHOP,T W Division of Resident Reactor Project & Engineering Programs 2pp 26282 161 24X Fichs 50-528,84/08/13,8408280302
- 8408280317 Interin Deficiency Rept DER 83-49 re broken impeller blades & diffuser bolts broken/loose in reactor coolant pumps Initially reported on 830715 Time extension until 840915 for final rept requested for post-demonstration test insp VAN BRUNTE E Arizona Public Service Co 84/08/13 BISHOP, Y W Division of Resident Reactor Project & Engineering Programs 2pp 26282 257 24X Fiche 50-528,84/08/13,8408280317
- 8408280325 Interim Deficiency Rept DER 83-5% re auxiliary feedwater pump failure to meet requirements of hot functional test Initially reported on 840802 Extension until 840915 requested for submittal of post-demonstration test rept VAN BRUNTLE E Arizona Public Service Co 84/08/13 BISHOP, T W Region 5, Defice of Director 2pp 26282 273 24X Fiche 50-528.84/08/13.8408280325
- 8408280335 Interim Deficiency Rept DER 63-42 re thermowells in RC8 Initially reported on 830629 Extension for submittal of final rept from 840815 to 840915 requested due to need for evaluation of post-demonstration test insp VAN BRUNTLE Entrana Public Service Co 84/08/13 BISHOP.T W Division of Resident Reactur Project & Engineering Programs 2pp 26282 259 24% Fiche 50-528,84/08/13,8408280335
- B408280357 Interim Deficiency Rept DER 84-26 re improperly tested or adjusted plunger interlock Initially reported on 840510 Final rept will be submitted by 840915 VAN BRUNT, E E Arizona Public Service Co 84/08/13 BISHOP, T W Division of Resident Reactor Project & Engineering Programs 2pp 26282 250 24X Fiche 50-528,84/08/13.8408280357
- 8408280204 Interim Deficiency Rept DER 84-25 re containment supply register failure to cycle Initially reported on 840501 Galvanized wire will be replaced w/stainless steel wire to gain higher tensile strength Next rept expected by 840921 VAN BRUNTLE E Arizona Public Service Co 84/08/16 BISHDP, T W DIVISION of Resident Reactor Project & Engineering Programs 3pp 26282 166 24X Fiche 50-528.84/08/16.8408280204
- B408280263 Interim Deficiency Rept DER 84-45 re spot wolding on skid mounted indication & control Initially reported on 840717 Kaman Instrumentation will perform torque test for site testing of stud welds Next rept expected by 840928 VAN BRUNT,E E Arizona Public Service Co 84/08/16 BISHOP,T W Division of Resident Reactor Project & Engineering Programs. Spp 26282 169 24x Fiche 50-528,84/08/16,8408280263

- 8408280275 Rev i to interim Deficiency Rept DER 82-24 re Limitorque valve operators found loose on valve bodies Valves will be stroked to full open bex bolts loosened & retorqued per vendor requirements Next rept by 840918
  VAN BRUNT, E. E. Arizona Public Service Co. 84/08/16 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 4pp 24282 172 24X Fiche 50-528, 84/08/16, 8408280275
- B408280297 Interim Deficiency Rept DER B4-44 re refueling water tank penetration sleeves Initially reported on 840717 Dechtel evaluation of reportability & corrective action in progress VAN BRINTLE & Artiona Public Service CO 84708/16 BISHOP,T W Division of Resident Reactor Project & Engineering Programs 3pp 24X Fiche 50-528,84/08/16,8408280297
- 8408280283 Interim Deficiency Rept DER 82-80 re low insulation resistance values for terminal blocks supplied by Conax Corp Initially reported on 821217 Final rept expected by
  - BAGYUS VAN BRUNT,E E Arizona Public Service Co 84/08/17 BISHOP,T W Division of Resident Reactor Project & Engineering Programs 2pp 86282 17B 24x Fiche 50-528,84/08/17,8408280283
- DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8408090483 Forwards request for add1 info re isolation devices used in reactor protective sys Response requested within 2 wks of ltr receipt
  - ltr receipt
    wnIGHTUN.G W Licensing Branch 3 84/07/25 VAN BRUNT.E E
    Arizona Public Service Co 7gp 25783 183 24X
    Fiche 50-528,84/07/25,8408090483
- 8408060319 Notifies that response to 840702 request for info re surveillance requirements for ESF actuation sys will be provided by 840901 VAN DRUNT, E E Arizona Public Service Co 84/07/31 KNIGHTON, G Licensing Branch 3 2pp 25936 036 24X Fiche 50-528.84/07/31, 8408060319
- 8408030144 Forwards table of Type A variables & revs & updates of compliance to Reg Guide 1 97, Rev 2. Types B.C & D variable requirements; in response to 631203 request VAN DRUNT. E E Artiona Public Service Co 84/08/01 KNICHTON, G Licensing Dranch 3 20pp 25911 161 24X Fiche 30-528, 84/08/01, 8408030144
- 840808004B Informs that response to NRC 840627 info request re control slement assembly shroud will be be submitted by 840815 VAN BRUNT.E E Arizona Public Service Co 84/08/02 KNIGHTON.G W Licensing Branch 3 ip 25961 036 24X Fiche 50-52B 84/08/02, 8408080004B
- B40B10D127 Forwards "Calculation of Trip Setpoint Values, Plant Protection Sys," in response to 830620 ltr VAN BRUNTLE Arizona Public Service Co 84/08/02 KNIGHTON, G Licensing Branch 3 lp 25991 042 24X Fiche 50-528, 84/08/02, 840B100127
- ---B40Bi00137 Rev 0 to "Calculation of Trip Setpoint Values, Plant Protection 8ys " \* Combustion Engineering, Inc CEN-286(V) R00 84/07/31 123pp 25791 043 24% Fiche 50-528.84/08/02.8408100127
- B408070110 Generic Ltr B4-19 to all licensess of operating reactors, applicants for DLs & holders of CPs re availability of Buppl 1 to NUREO-0933. "Prioritization of Generic Safety Issues" Bvt list encl EIEENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Int. 18pp 26127 238, 24X Fichs 50-000.84/08/06,8408070110
- 3408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
  TREMBLAY.P P Operating Reactors Assessment Branch 84/08/06
  HOLAHAN.O M Operating Reactors Assessment Branch 13pp
  25791 350 24% Fiche 50-000,84/08/06,8408090317
- MOB200255 Informs of launching of new program to seek out concerns re const & safe operation Ltr to all const workers inviting rept of concerns for investigation encl TURLEY, M. Aprican Public Service Co 84/08/06 MARTIN, J Region 5, Office of Director 3pp 26133 208 24x Fiche 50-528,84/08/06, 8408200255

- 8408130274 Forwards solid radwaste process control program in response to GW Knighton 840403 itr to EE Van Brunt Solid radwaste to um Knighton 840403 ltr to EE Van Brunt Solid radwaste process control prugram incorporates 830630 response to B30415 request for add1 info VAN BRUNT.E E Arizona Public Service Co 84/08/07 KNIGHTON, G Licensing Branch 3 2pp 26010 008 24X Fiche 50-528,84/08/07,8408130274 KNZ GHTON, G
- --8408130277 Solid radwaste process control program \* Arizona Public Service Co 84/08/07 9pp 26010 010 24X Fiche 50-528,84/08/07,8408130274
- 8408140227 Advises that OE Willer medical problem, disclosed on NRC Form 396, will not impair ability to perform assigned job tasks Evaluation based on examining physician statement & mgt observation of past performance VAN BRUNT, E E Arizona Public Service Co 84/08/07 MARTIN, J F Region 5, Office of Director 1p 26055 309 24X Fichs 50-528,84/08/07,8408140227
- 8408150207 Forwards suppls to util 840702 ltr re organizational structure, based on 840716 discussion Suppls include removal of Note b ref from FSAR Page 13 1-28, Note b from Page 13 1-27 & update to response to Question 13A 18 VAN BRUNTLE E Arizona Public Service Co 84/08/13 KNIGHTON, G Licensing Branch 3 6pp 26067 125 24X Fiche 50-528, 84/08/13, 8408150207
- 8408230367 Notification of 840822 & 23 meetings w/util, Bechtel & DDE at site to discuss evaluation of effects of water leaks on foundation stability LICITRA, E A Licensing Granch 3 84/08/14 KNIGHTON, G W LICITRA, E A Licens Licensing Branch 3 8408230367 4pp 26230 350 24% Fiche 50-528,84/08/14.
- 8408170348 Forwards add1 fabrication info on Unit i control element assembly shroud assembly, per 840627 request Seventeen proprietary oversize drawings entl Drawings withheld (ref 10CFR2 790) Aperture card available in Central Files VAN BRUNT,E E Arizona Public Service Co 84/08/15 KNIGHTON,O Licensing Branch 3 App 26145 001 24X Fiche 50-528,84/08/15. Licensing Branch 3 App 8408170348
- B408200275 Ceneric Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT.D 0 Division of Licensing B4/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276-244 24X Fiche 50-000.84/08/20.8408200275
- 8408240261 Forwards Rev 2 to "Pump & Valve Inservice Testing Program" & proposed changes to Rev 2 W/46 eversize drawings Aperture cards available in PDR VAN BRUNT, E E Arizona Public Service Co 84/08/21 KNIGHTON, C Licensing Branch 3 3pp 26227 018 24X Fiche 50-528,84/08/21, 0000247021 8408240261
- --8408240263 Rev 2 to "Pump & Valve Inservice Testing Program" \* Arisona Public Service Co 84/07/16 206pp 26227 021 Fiche 50-528,84/08/21,8408240261
- 8408240289 Forwards mod to deviation request in FSAR Amend 13, Sections 98 2 1,98 2 2 & Figures 98-8,9,10 & 11 Updated response to FSAR Question 9A-98 Part (2) also encl Changes will be incorporated in next FSAR amend VAN BRUNT, E E Arizona Public Service Co 84/08/21 KNIGHTON, G Licensing Branch 3 13pp 26223 199 24X Fiche 50-328,84/08/21, Licensing Branch 3 15pp 8408240289
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8407120136 Appeals denial of FOIA request for 27 documents referenced in 1975 EIS re facility & all EIS supplemental EIS or similiar environ documents & FOIA fee waiver decision RYAN, J.A. Stretch, Lang, Weeks & Cardon 84/03/27 Office of the Executive Director for Operations App 25557 018 24X Fiche 50-528.84/03/27.8407120136 Office of the
- 8407120142 Responds to appeal re denial of FDIA request for 27 documents referenced in 1975 EIS re facility & all EIS, supplemental EIS or similar environ documents Appeal granted DIRCKS,W J Office of the Executive Director for Operations 84/05/21 RYAN,J A Streich, Lang, Weeks & Cardon 1p 25557 022 24X Fiche 50-528,84/05/21.8407120142

- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8408130351 Forwards update to 83012/ description of natural circulation test program & "Evaluation of Natural Circulation Cooldown Test Performed at San Gnofre Nuclear Generating Station "Confirmatory Item 7 in NUREG-0857. SEER 5 closed VAN BRUNT.E E Arizona Public Service Co 84/08/07 KNIGHTON.G Licensing Branch 3 23pp 26006 170 24X Fiche 50-528.84/08/07.8408130351
- B40B270133 Forwards "Containment Ultimate Capacity Analysis," per NUREO-0857, "SER re Operation of Palo Verde Nuclear Generating Station, Units i, 2 & 3 " Analysis should close license condition discussed in Section 3 9 1
  VAN BRUNT, E E Arizona Public Service Co 84/08/20 KNIGHTON, O Licensing Branch 3 3pp 26245 061 24X Fiche 50-528, 84/08/20. 8408270133
- --8408270140 "Containment Ultimate Capacity Analysis" \* Arizona Public Service Co 64/06/31 38pp 26245 064 24X Fiche 50-528,84/08/20,8408270133
- F Security, medical, emergency & fire protection plans
- 8408070448 Notification of 840730-31 & OBO1 meetings w/util & Comex in Phaenix. AZ & site. respectively, to discuss open issues in onsite emergency planning LICITRALE A Licensing Branch 3 84/07/25 KNIGHTON, G W Licensing Branch 3 2pp 25983 213 24X Fichs 50-528.84/07/25.
- 8408130182 Forwards request for add1 info re evacuation time estimate analysis for emergency plan Response requested within 2 wks of ltr receipt KNIGHTON, G W Licensing Branch 3 84/07/27 VAN BRUNT, E E Arizona Public Service Co 3pp 26011 351 24X Fiche 50-528,84/07/27.8408130182
- B408130160 Confirms B40625 telcon re outcome of B40531 appeal meeting re alternate shutdown capability Appeal granted, based on listed design features for plant & commitment to perform confirmatory PRA analysis NOVAK.TM Assistant Director for Licensing B4/07/30 VAN BRINTLE Arizona Public Service Co 2pp 26034 351 24X Fiche 50-528.84/07/30,8408130160
- 8408030097 Forwards response to NRC 840605 comments re emergency procedure generation package Steps to verify adequate instruments & controls available for operator to perform assigned task incorporated into validation procedure VAN BRUNT, E.E. Arizona Public Service Co. 84/08/01 KNIGHTON, Q. Licensing Branch 3. 7pp. 25704 342 24X Fiche 30-528, 84/08/01, 8408030097
- 8408230310 Confirms 840822-24 audit of emergency operating procedures (EDPs) Five sets of current EDPs, along w/procedure generation package rev, should be provided to NRC by 840813 KNIOHTGN, G W Licensing Branch 3 84/08/02 VAN DRUNT, E E Arizona Public Service Co 2pp 26236 100 24X Fiche 50-528,84/08/02,8408230310
- 8408300383 Forwards Insp Repts 50-528/84-25,50-529/84-19 & 50-539/84-12 on 840709-13 & notices of violation & deviation & BISHOP,T W Region 5, Office of Director 84/08/08 VAN BRUNT,E E Arizona Public Service Co 2pp 24308 122 24X Fiche 50-528,84/08/08,8408300383
- --8408300390 Notice of violation from insp on 840709-13 MILLER,t. Region 5, Office of Director 84/08/08 2p 24308 124 24X Fiche 50-528,84/08/08,8408300383
- ---8408300397 Notice of deviation from insp on 840709-13 MILLER,L. Region 5, Office of Director 84/08/08 ip 86308 126 24X Fiche 50-528,84/08/08,8408300383
- --8408300407 Insp Repts 50-528/84-25, 50-529/84-19 & 50-530/84-12 on 840709-13 Violations noted fire protection sys not designed to retain structural integrity during seismic event. CLARK.C. NARBUT,P P. MILLER.L. Region 5. Office of Director 84/08/03 24pp 26308 127 24X Fiche 50-528,84/08/08,8408300383
- 8408200599 Submits Rev 4 to emergency plan Rev addresses NRC comments, is aligned more concisely w/current operating procedures & clarifies barrier approach to emergency action levels VAN BRUNT.E E Arixona Public Service Co 84/08/15 KNIOHTON, G Licensing Branch 3 3pp 26137 032 24X Fiche 50-528.84/08/15, 8408200599

- --8408200600 Rev 4 to emergency plan \* Ariiona Public Service Co 84/05/31 83pp 26137 055 24X Ficha 50-528,84/08/15,8408200599
- 8408200112 Forwards "Evaluation Time Analysis, 10-Hile Emergency Planning Zone, Arizona Div of Emergency Svcs" & response to 840727 request for add1 info VAN BRUNT, E.E. Arizona Public Service Co. 84/08/16 KNIGHTON, G. Licensing Branch 3. 4pp. 26132-323 24X Fiche 50-528,84/08/16,8408200112
- --8408200334 "Evacuation Time Analysis.io-Mile Emergency Flanning Zone, Artiona Div of Emergency Svcs " \* Artiona, State of BLUHM.R B Maricopa County, AZ 84/01/31 22pp 26132 325 24X Fiche 50-528,84/08/16,8408200112
- 8408200217 Forwards Rev 5 to emergency action levels Rev addresses comments raised at 840731 meeting re security, esternal events & challenge/failure of fission product barriers VAN BRUNT, E E Arisona Public Service Co 84/08/16 KNIGHTON. C Licensing Branch 3 Spp 26133 099 24X Fiche 50-528, 84/08/16, 8408200217
- --8408200224 Rev 5 to emergency action levels

  \* Artiona Public Service Co 84/08/31 86pp 24133 102 24X
  Fiche 50-528,84/08/16,8408200217
- 8408270260 Requests approval of two temporary deviations in emergency preparadness plan from goals for augmentation of emergency response organization in Suppl 1 to NUREO-0737 Nature & duration of deviations encl
  VAN BRUNT, E E Arizona Public Service Co 84/08/20 KNIGHTON, G
  Licensing Branch 3 27pp 26243 131 24% Fiche 50-528,84/08/20,8408270260
- K Utility Final Safety Analysis Report (FSAR) & amends
- B40B030102 Forwards page change list for Amend 13 to FBAR Replacement of original pages requested # Bechtel Corp B4/07/31 Office of Nuclear Reactor Regulation. Director 3pp 25704 336 24X Fiche 50-528.84/07/31.8408030102
- B408030142 Forwards corrected Pages 3 & 4 to list of effective pages for Palo Verde FBAR Amend 13 \* Bechtel Corp B4/07/31 Office of Nuclear Reactor Regulation, Director 3pp 25915 325 24X Fiche 50-528.B4/07/31,B408030142
- 8408030073 Forwards page change list for Palo Verde Nuclear Generating Station FBAR, Amend 13, Pages A through J Olffice of Nuclear Reactor Regulation, Director 6pp 84/08/01 Office of Nuclear Reactor Regulation, Director 6pp 85916 031 24% Fiche 50-528, 84/08/01, 8408030093
- 8408060075 Forwards info revising Insert 1 to FBAR, Page 14 2-3 re initial test program VAN BRUNT, E E Arizona Public Service Co 84/08/01 KNIGHTON, G W Licensing Branch 3 7pp 25933 215 24X Fiche 50-528,84/08/01, 8408060075
- 8408010215 Amend 13 to FBAR for Palo Verde Nuclear Generating Station. Units 1.2 & 3 W/34 oversize figures Aperture cards available in PDR W/840801 ltr VAN BRUNT,E E Arizona Public Service Co 84/08/31 1408pp 25797 122 24
- Q Inspection reports: IE Bulletins & correspondence
- 8406230213 "Region V Dutstanding Items Rept Open & Closed "
  # Region 5. Office of Director 84/06/12 25pp 25127 076 24)
  Fichs 50-529,84/06/12,8406230213
- 8407230229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Bafety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229
- 8408300187 Forwards Insp Repts 50-528/84-23 & 50-529/84-17 on B40602-0701 No noncompliance noted BISHOP.T W Division of Resident-Reactor Project & Engineering Programs 84/08/02 VAN DRUNTLE E Arizona Public Service Co 2pp 26308 014 24X Fiche 50-528.84/08/02.8408300187

- --8408300195 Insp Repts 50-528/84-23 & 50-529/84-17 on 840802-0701 No violations noted Major areas inspected preoperational testing activities maint. review of maint & followp on TMI Lessons Learned implementation & IMMERMAN, R., FIGRELLIAG., BOSTED, C. Region 5, Office of Director 84/08/01 12pp 26308 016 24X Fiche 50-528.84/08/02, 8408300187
- 8408010333 IE info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list end! JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333
- B4080i0337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/05 Consolidated Edison Co of New York, Inc 123pp 26067 158 24% Fiche 50-000:84/08/06.8408010337
- 8408300094 Forwards Insp Repts 50-528/84-21, 90-529/84-16 & 90-530/84-10 on 840402-0531 & notice of violation BISHOP.T w Division of Resident, Reactor Project & Engineering Programs 84/08/07 VAN BRUNT E & Antiona Public Service Co 2pp 26306 141 24X Fiche 50-528, 84/08/07, 8408300094
- --8408300100 Notice of violation from insp on 840402-0531 YDUNG.T Region 5. Diffice of Director 84/08/07 ip 26304 i43 24X Fiche 50-528,84/08/07,8408300094
- --8408300105 Insp Repts 50-528/84-21.50-529/84-16 & 50-530/84-10 on 840402-0531 Violation mated failure to control mods on Units 1 & 2 diesel generator bldg wall mounted instruments VARDER BRUEGOEN YOUNG T Region 5. Office of Director 84/08/07 7pp 86306 144 24X Fiche 50-528.84/08/07.8408300094
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PNR Refueling Cavity " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York, Inc. 120pp 26129 118 24X Fiche 50-000.84/08/08.8408070120
- 8408300383 Forwards Insp Repts 50-528/84-25,30-529/84-19 & 50-530/84-12 on 840709-13 & notices of violation & deviation & sisHOP.T H Region 5. Office of Director 84/08/08 VAN BRUNT, E E Arizona Public Service Ca 2pp 26308 122 24X Fiche 50-528.84/08/08.8408300383
- --8408300390 Notice of violation from insp on 840709-13 MILLER, L Region 5. Office of Director 84/08/09 2pp 26308 124 24X Fiche 50-528.84/08/08.8408300383
- --8408300397 Notice of deviation from insp on 840709-13 MILLER, L Region 5, Office of Director 84/08/08 1: 24308 126 24X Fiche 50-528.84/08/08.8408300383
- --8408300407 Insp Repts 30-328/84-25,50-529/84-19 & 50-530/84-12 on 840707-13 Violations noted fire gratection sys not designed to retain structural integrity during seismic event CLARK.C. SORENSEN.R C. HOLLENBACH.D Region 5. Office of Director 84/08/03 24pp 26308 127 24X Fiche 50-528,84/08/08.
- 9408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Svc List enci GRACE, J N Division of QA, Safeguerds & Inspection Programs (Post B30103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26/30 001. 24X Fiche 50-000.84/08/10.8408070376
- 8408100009 IE Info Notice 84~63, "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84708/13 Consolidated Edison Co of New
  York, Inc. 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408100038 TE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl Indication " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000.84/08/15.8408100038
- 840B100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc (18pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

- 8408220051 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in IE insp repts conducted between 840501-04601 BISHOP.T N Region 5. Defice of Director 84/08/16 VAN BRUNT.E E Artiona Public Service Co. ip 26193-237 24X Fiche 50-528.84/08/16.8408220051
- --8408220071 Responds to NRC 840722 ltr re violations noted in IE insp repts conducted between 840501-0601 Corrective actions Pump A disassembled & defective seal replaced w/new seal Walkdown team established VAN BRURT. E Aritona Public Service Co 84/07/20 BISHOP, T W Region 5, Office of Director 10pp 26193 238 24X Fichs 50-528,84/08/16,8408220051
- 8408100033 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auriliany Feedwater Train " Svc list encl JORDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8400100055
- 8408140208 IE Info Notice 84-67. "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN,E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26274 122 24X Fiche 50-000.84/08/17.8408140208
- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc. 115pp 26329 008 24X Fiche 80-000.84/08/21.8408210142
- B Reportable occurrences, LERs & related correspondence
- 840803004B Final Deficiency Rept DER 83-96.Rev i re discrepancies w/ Anchor-Darling MSIVs Initially reported on 63080& Larger hydraulic reservoir w/baffles installed in each MSIV & feedwater isolation valve VAN DRUNT, E E Arizona Public Service Co 84/04/13 BISHOP, T W Region 5. Office of Director 7pp 25917 330 24X Fiche 50-528.84/04/13.8408030048
- 8408020232 Corrected Rev 1 to Final Deficiency Rept DER 83-94 re discrepancies w/MSIV mfg by Anchor-Darling Initially reported on B30808 Vendor Instruction Manual E9023-9 revised Aiso reported per Part 21 VAN BRUNT,E E Arizona Public Service Co 84/07/13 BISHOP,T W Division of Resident Reactor Project & Engineering Programs 7pp 25898 046 24X Fiche 50-528.84/07/13.8408020232
- B40B030041 Final Deficiency Rept DER 83-77 re concrete pour containing honeycombed concrete Instially reported on 831109 Honeycombed concrete removed & repaired Item not reportable per 10CFR80 55(e)

  VAN BRUNTLE E Arizona Public Service Co B4/07/13 BISHDP, T W Region 5, Office of Director 4pp 25917 323 24X Fiche 50-529.84/07/13.8408030061
- 8408030302 Final Deficiency Rept DER 84-02 re rust, scale & pitting in clevis & arm of several safety injection & CH valves Rust insignificant Deficiency determined not reportable under iOCFRSD 55(e)

  VAN BRUNT, E E Arizona Public Service Co 84/07/13 BISHOP, T W Region 5. Office of Director 2pp 25917 115 24X Fiche 50-528, 84/07/13, 8408030302
- 8408010377 Interim Deficiency Rept DER 84-18 re wiring error on LPS1 pump B switch CS-3 Initially reported on 840326 Final rept will be submitted by 840822 VAN BRUNT.E E Arizona Public Service Co 84/07/16 B18HOP.T W Division of Resident.Reactor Project & Engineering Programs 2pp 25864 268 24X Fiche 50-528.84/07/16.8408010377
- 8408010381 Interim Deficiency Rept DER 84-08 re ITT/Barton Hodel 743 transmitters not meeting specs Initially reported on 840827 Final rept will be submitted by 840824 VAN BRUNT, E. E. Artiona Public Service Co. 84/07/16 BISHOP, T. W. Division of Resident Reactor Project & Engineering Programs 2pp 25866 290 24x Fiche 50-528.84/07/16.8408010381
- 8408010384 Interim Deficiency Rept DER 83-80 re main feedwater isolation valves closing in 20 s instead of Tech Spec required 5 < Initially reported on 831122 Final rept will be submitted by 840823.

  VAN BRUNTLE E Arizona Public Service Co 84/07/16 BIGHDP, T W Division of Resident Reactor Project & Engineering Programs 2pp 25866 286 24x Fiche 50-528.84/07/16,8408010384

- 8498030240 Interim Deficiency Rept DER 83-63 re HPSI isolation valves mfg by Borg-Warner failing to open against pump A & II flows Initially reported on 830923 Time extension requested due to extensive investigation Next rept by 840831 VAN BRUNTLE E Arizona Public Service Co 84/07/16 BISHOP,T W Division of Resident Reactor Project & Engineering Programs 2pp 26917 221 24X Fiche 50-528,84/07/16,8408030240
- 8408010346 Final Deficiency Rept DER 82-37, Rev 1, re Class iE wiring termination crimped w/less pressure than specified work Plant Procedure/9C Instruction 255 0 revised to require maint program VAN BRUNT, E E Arizona Public Service Co 84/07/18 BISHOP, TW Division of Resident Reactor Project & Engineering Programs 12pp 25866 310 24X Fiche 50-528,84/07/18,8408010346
- 840B0103BB Interin Deficiency Evaluation Rept 84-43 re HPS1 3-inch gate valve failing to open Initially reported on 840622 Conditions not reportable per 10CFR90 55(e) VAN BRUNT, E E Arizona Public Service Co 84/07/18 BISHOP, T W Division of Resident Reactor Project & Engineering Programs 2pp 25865 281 24X Fiche 50-528, 84/07/18, 8408010388
- 8408020229 Final Deficiency Rept DER 83-59.Rev 1.re IEEE-384 separation criteria violated by wiring in post-accident control room & safety radiation monitoring cabinets Sheet metal barriers added between terminal blocks Not reportable per 10CFR50 55 VAN BRUNT.E E Arizona Public Service Co 84/07/18 BISHOP.T W Division of Resident.Reactor Project & Engineering Programs Spp 25898 041 24X Fiche 50-929.84/07/18.8408020229
- 840B030053 Interim Potential Deficiency Rept DER 84-42 re replacement of environmentally qualified torque switches w/unqualified switches initially reported on 840618 Final rept expected by 840B20 VAN BRUNT, E.E. Arizona Public Service Co. 84/07/18 BISHOP, T.W.
- 840820 VAN BRUNT,E E Arizona Public Service Co 84/07/18 BISHOP,T | Region 5, Office of Director 3pp 25917 327 24X Fiche 50-528,84/07/18,8408030053
- 8408090479 Final Deficiency Rept DER 83-75 re improper torquing of bolts on two D01268A panel filler assemblies Bolts retorqued Deficiency not reportable under 10CFR50 55(e) VAN BRUNT.E E Arizona Public Service Co E4/07/24 BISHOP.T W Division of Resident Reactor Project & Engineering Programs Spp 25975 232 24X Fiche 50-528.84/07/24.8408080499
- 8408080529 Rev 1 to final Deficiency Rept DER 81-49 re erroneous readings on NSSS water level transmitters due to variations of water leg Condensate pots for steam generator & pressurizer level measurements installed on root valves VAN BRUNT.C E Arizona Public Service Co 84/07/24 BISHOP.T W Division of Readedont Reactor Project & Engineering Programs 4pp 25975 298 24X Fiche 50-528.84/07/24.8408080929
- 8408070012 Final Deficiency Rept DER 84-08 re failure of ITT/Barton Model 763 transmitters to meet specs PPS setpoints revised on existing transmitters % Darton working on physical mod to meet specs Also reportable under Part 21 VAN BRUNT.E E Arizona Public Service Co 84/07/24 BISHOP,T W Division of Regident.Reactor Project & Engineering Programs 4pp 257975 011 24X Fiche 50-528.84/07/24.8408070012
- 8408130172 Interim Deficiency Rept DER 83-81 re manufacturing defect in Gulfally Schedule 160 85 pipe Initially reported on 831128 Due to extensive investigation & evaluation required, final rept will be delayed until 840830 VAN BRUNT, E E Arizona Public Service Co E4/07/27 BISHOP, T W Division of Resident. Reactor Project & Engineering Programs 2pp 26010 036 24% Fiche 50-528,84/07/27.8408130172
- B408130332 Interim Deficiency Rept DER 84-09 re CAD welding for cathodic protection ground connection Initially reported on B40229 Final rept will be submitted by 840830 VAN BRUNT, E E Arizona Public Service Co B4/07/27 B19H0P, T W Division of Resident, Reactor Project & Engineering Programs 2pp 26010 303 24X Fiche 50-528, 84/07/27, 8408130532
- 8408130344 Interim Deficiency Rept DER 82-80 re low insulation resistance values or terminal blocks supplied by Comax Corp Initially reported on 821217 Final rept by 840817 VAN BRUNT,E E Arizona Public Service Co 84/07/30 BISHOP,T W Division of Resident, Reactor Project & Engineering Programs 2pp 26010 222 24X Fiche 50-528,84/07/30,8408130344
- B40Bi30429 Interim Deficiency Rept DER 84-15 re welds attaching pipe restraint supports less than design calculated dimensions Initially reported on 840321 Final rept will be submitted by 840914

  VAN BRUNT, E & Arizona Public Service Co 84/07/30 BISHDP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 24004 354 24% Tiche 50-529, 84/07/30, 840Bi30429

- 8408160192 Final Deficiency Rept DER 84-10 re resistance temp detectors Caused by torsional tuisting of element & sheath during honing operation resulting in broken internal wire Itom not reportable per 10CFR50 55(e) VAN DRUNT.E E Arizona Public Service Co 84/08/01 BISHOP, T W Region 4. Office of Director 3pp 26106 334 24X Fiche 50-528,84/08/01.8408160192
- 840Bi60480 Final Deficiency Rept DER 84-16 or ESF actuation sys relay cabinet baseplates Initially reported on 840321 Cabinet backs will be reinforced w/3/B-inch thick vertical stiffener plate Also reportable under Part 21 VAN BRUNT,E E Arizona Public Service Co 84/08/02 BISHOP,T W Division of Resident Reactor Project & Engineering Programs 4pp 26107 292 24X Fiche 50-528,84/08/02,8408160480
- B40B160506 Final Deficiency Rept DER B3-78 re lack of users test documentation & controlling procedure for rock bolt expansion anchors initially reported on B31107 Item not reportable under 10CFM50 55(s) & Part 21 VAN BRUNT. E E Arizona Public Service Co 84/08/02 BIBHOP, T W Division of Resident. Reactor Project & Engineering Programs 9pp 26107 326 24X Fiche 50-528.84/08/02,8408160506
- 8408220128 Interim Deficiency Rept DER 84-33 re incorrectly installed hanger support assembly Initially reported on 840504 Due to extensive investigation, final rept will be available 840831 instead of 840810 VAN BRUNT, E E Arizona Public Service Co 84/08/06 BISHOP, TW Division of Resident Reactor Project & Engineering Programs 2pp 26188 348 24X Fiche 50-528,84/08/06,8408220128
- 8408220143 Interim Deficiency Rept DER 84-44 re fatigue failures of Gaulin charging pumps Initially reported on 840706 Bechtel investigating Final rept to be completed by 840927 Reported under Part 21 by Northeast Utils
  VAN BRUNTLE E Arixona Public Service Co 84/08/06 BIBHOP.T W Division of Resident Reactor Project & Engineering Programs 3pp 26188 065 24X Fichs 50-528.84/08/06.8408220143
- 8408200332 Part 21 rept re tension wires an Titus Grille, Madel 272, not remaining in place when deflection blades closed Affected job sites identified in encl Products being tested to provide acceptable fix for retention SCHNETDER, 5 L. Phillips Industries, Inc. 84/08/07 Director's Office, Office of Inspection and Enforcement 3pp 26133 315 24% Fiche 50-000.84/08/07,8408200332
- 8408200333 Part 21 rept re tension wires used for adjustment of blades on Orille Model 272 not remaining in place when blades closed Review & testing conducted to identify number of grilles & rework methods to be utilized SCHNEIDER. S. L. Phillips Industries. Inc. 84/08/07 STRAIT. R Arizona Public Service Co. 1p. 24132 360 24X Fiche 50-528,84/08/07,8408200333
- B40B200297 Interin Deficiency Rept DER 84-34 re critical friction-type high strength connectors Due to extensive evaluation.next rept delayed until B40904 VAN BRUNT, E E Arizona Public Service Co B4/08/09 BISHOP, T W Region 5. Office of Director 2pp 26140 090 24X Fiche 30-52B.84/08/09,8408200297
- 8408200322 Final Deficiency Rept DER 83-61 re C-E low pressure safety injection pump failure to start & produce required head Case wear rings replaced & cloarance between impeller & casing increased Proprietary CEN-285 (V)-P encl VAN DRUNTLE E Ariona Public Service Co 84/08/07 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 40pp 26133 318 24X Fiche 50-528,84/08/07,8408200322
- 8408200285 Final Deficiency Rept DER 83-82 re improper bend radius in diesel generator control cabinets Initially reported on 840103 Forwards "Technical Rept for Palo Verde Nuclear Station-Bechtel Power Corp on Returned Cable NCR E63617 "
  VAN BRUNT, E. E. Arizona Public Service Co. 84708/10 818H0P, T W Region 5, Office of Director 13pp 26139 307 24x Fiche 50-528,84708/10,8408200285
- --B408200288 "Technical Rept for Palo Verde Nuclear Station-Bethtel Power Corp on Returned Cable NCR E43619" MONTGOMERY, R. BEASLEY, B. Anaconda Co. (subs. of Atlantic Richfield Co.) 84/01/24 | 11pp 26139-320 24X Fiche 50-528,84/08/10.8408200283
- B40B2B0302 Interim Deficiency Rept DER 83-57 re cracks in control element assembly shroud Initially reported on B30729 Requests extension until 840915 for submittal of final rept to allow for post-demonstration test insp evaluation VAN SRUNTE E Aricona Public Service Co 84/09/13 BIBHOP, T. W Division of Resident Reactor Project & Engineering Programs 2pp 26282 161 24X Fiche 50-528,84/08/13,8408280302

- B4081280317 Interin Deficiency Rept DER 83-49 rs broken impeller blades & diffuser bolts broken/loase in reactor cuolant pumps Instituting reported on 830715 Time extension until 840915 for final rept requested for post-demonstration test insp VAN BRUNT, C E. Artiona Public Service Co. B4/08/13 BISHOP, TW Division of Resident, Reactor Project & Engineering Programs 2pp 26282 257 24X Fiche 50-528 84/08/13, 8408280317
- 0408200335 Interim Deficiency Rept DER 83-42 re thermowells in RCS Initially reported on 830829 Extension for submittal of final rept from 840815 to 840915 requested due to noed for evaluation of post-demonstration test insp WAN BROWT E Acizona Public Service Co 84/08/13 BISHOP, TW Division of Resident, Reactor Project & Engineering Programs 2pp 26282 259 24X Fiche 50-528 84/08/13,8408280335
- 8408280357 Interim Deficiency Rept DER 84-26 re improperly tested or Rejusted plunger interlock Initially reported on 840510 Pinal rept will be submitted by 840915 VAN BRUNTLE E Arizona Public Service Co 84/08/13 BISHOP, T w Givision of Resident, Reactor Project & Engineering Programs 2pp 26282:250 24X Fiche 50-528,84/08/13,8408280357
- 8408280204 Interim Deficiency Rept DER 84-25 re containment supply register failure to cycle Initially reported on 840501 Galvantred wire will be replaced w/stainless steel wire to gain higher tensile strength Next rept expected by 840721 VAN BRUNT.E E Arizona Public Service Co 84/08/16 BISHOP.TW Division of Resident. Reactor Project & Engineering Programs Spp 26802 166 24% Fiche 50-328.84/08/16.8408280204
- 8409280263 Interim Deficiency Rept DER 84-45 re spot welding on skid maunted indication & control Initially reported on 840717 Kaman Instrumentation will perform torque test for site testing of stud welds Next rept expected by 840928 VAN DRUNT.E E Arizona Public Service Co 84/08/16 BISHOP,T W Division of Resident.Reactor Project & Engineering Programs Spp 26202, 169 24% Fiche 50-528,84/08/16,8408280263
- 8408280297 Interim Deficiency Rept DER 84-46 re refueling water tank penetration sleeves Initially reported on 840717 Bechtel evaluation of reportability & corrective action in progress VAN BRUNTLE E Arizona Public Service Co 84/08/16 BISHOP, FW Division of Resident, Reactor Project & Engineering Programs 3pp 26292 150 24% Fiche 50-528,84/08/16,8408280297
- 8408280283 Interim Deficiency Rept DER 82-80 re low insulation resistance values for terminal blocks supplied by Conax Corp Initially reported on 821217 Final rept expected by 640903 VAN BRUNTLE E Arizona Public Bervice Co 84/08/17 BISHOP, T W Division of Resident.Reactor Project & Engineering Programs 2pp 26282 178 24x Fiche 30-328.84/08/17.8408280289
- DOCKET 81N-50-530 PALO VERDE NUCLEAR STATION, UNIT 3

  A Application/construction stage documents & correspondence
- - BO60319 Notifies that response to 840702 request for info reurvaillance requirements for ESF actuation sys will be rovided by 840901 AN BRUNTLE C Arizona Public Service Co 84/07/31 KNIGHTON, 6 itemsing Branch 3 2pp 25936 036 24X Fiche 50-528, 84/07/31, 3408040319
- DBDSO144 Forwards table of Typo A variables & revs & updates of compliance to Reg Ouide 1 97, Rev 2. Types B.C & D variable requirements in response to B31203 request.

  VAN BRUNT, E E Arizona Public Bervica Co 84/08/01, KNIGHTON, O Licensing Branch 3 28pg 25711 161 24X Fiche 50-528,84/08/01. 8408030144
- DBDBOO48 Informs that response to NRC B40627 info request re-control element assembly shroud will be be submitted by 840815 VAN BRUNT, E E Arifons Public Service Co B4/08/02 KN10HTQN, 0 W Licensing Branch 3 ip 25961 036 24X Fiche 50-528,84/08/02,84080800048.
- MOBIO0127 Forwards "Calculation of Trip Setpoint Values, Plant Protection Bys," in response to 830620 ltr VAN BRUNT.E E Artiona Public Service Co 84/08/02 KNIGHTON, G Licensing Brench 3 ip 25991 042 24X Fiche 50-528, 84/08/02, 8408100127

- --8408100137 Rev 0 to "Calculation of Trip Setpoint Values, Plant Protection Sys" \* Combustion Engineering, Inc. CEN-286(V) ROO 84/07/31 123pp 25991 043 24X Fichs 50-528.84/08/02,8408100127
- 8408070110 Generic Ltr 84-17 to all licensees of operating reactors, applicants for OLs % holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl EiseNHUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24% Fiche 50-000.84/08/06.8408070110
- 8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1784
  TREMBLAY.P P Operating Reactors Assessment Branch 84/08/06
  HDLAHAN.G M Operating Reactors Assessment Branch 13pp 25991 350 24X Fiche 50-000,84/08/04,8408090317
- 8408200255 Informs of launching of new program to seek out concerns re const & safe operation Ltr to all const workers inviting rept of concerns for investigation encl TURLEY, K. Arizona Public Service Co. 84/08/04 MARTIN. J. Region 5. Office of Director 3pp. 24133 208 24X Fiche 50-528.84/08/06, 8408200255
- 8408130274 Forwards solid radwaste process control program: in response to OW Knighton 840403 ltr to EE Van Brunt Solid radwaste process control program incorporates 830530 response to 830415 request for add info VAN BRUNT.E E Arizona Public Service Co 84/08/07 KNIGHTON, O Licensing Branch 3 2pp 26010 008 24X Fiche 50-528,84/08/07,8408130274
- --8408130277 Solid radwaste process control program

  \* Arizona Public Service Co 84/08/07 9pp 26010 010 24X
  Fiche 50-528,84/08/07,8408130274
- B40B140227 Advises that GE Willer medical problem disclosed on NRC Form 396, will not impair ability to perform assigned jub tasks Evaluation based on examining physician statement & mgt observation of past performance
  VAN BRUNT.E E Arizona Public Service Co 84/08/07 MARTIN, J B Region B. Office of Director 1p 24055 309 24%
  Fiche 50-528,84/08/07,8408140227
- B40B150207 Forwards suppls to util 840702 ltr re organizational structure, based on 840716 discussion Suppls include removal of Note b ref from FBAR Page 13 1-28. Note b from Page 13 1-29 & Update to response to Question 13A 18 VAN IRUNT.E E Arizona Public Bervice Co 84/08/13 KNIGHTON.G Licensing Branch 3 App 26067 125 24X Fiche 50-528,84/08/13,8408150207
- B408230367 Notification of 840822 & 23 meetings w/util, Bechtel & DOE at site to discuss evaluation of effects of water leaks on foundation stability
  LICITRA, E A Licensing Branch 3 84/08/14 KNIGHTON, G W
  Licensing Branch 3 4pp 26230 350 24% Fiche 50-528.84/08/14, 8408230367
- 8408170348 Forwards add1 fabrication info on Unit 1 control element assembly shroud assembly; per 840627 request Seventeen proprietary oversize drawings encl Drawings withhold (ref 10CFR2 770) Aperture card available in Central Files VAN BRUNT.E E Arizona Public Service Co 84/08/15 kNIGHTON, Q Licensing Branch 3 App 26145 001 24x Fiche 50-528,84/08/15,8408170348
- B408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for DLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Gvc list encl EIBENHUT.D D Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276-244 24X Fiche 50-000.84/08/20,8408200275
- 840824026: Forwards Rev 2 to "Pump & Valve Inservice Testing Program" & proposed changes to Rev 2 W/46 oversize drawings Aperture cards available in PDR VAN BRUNT.E E Arizona Public Service Co 84/08/21 KNIGHTON.G Licensing Branch 3 3pp 26227 018 24X Fiche 50-528,84/08/21.8408240261
- --8408240263 Rev 2 to "Pump & Valve Inservice Testing Program " \* Arizona Public Service Co 84/07/16 206pp 26227 021 24% Ficha 50-528,84/08/21,8408240261

- 8408240289 Forwards mod to deviation request in FSAR Amend 13.5ections 98 2 1.98 2 2 & Figures 98-8.9.10 & 11 Updated response to FSAR Question 9A-98 Part (2) also encl Changes will be incorporated in next FSAR amend VAN BRUNT.E E Arizona Public Service Co 84/08/21 KNIGHTON.G Licensing Branch 3 15pp 26223 199 24X Fiche 50-528.84/08/21.8408240289
- D NRC Draft/Final Environmental Statements, supply & correspondence
- 8407120136 Appeals denial of FOIA request for 27 documents referenced in 1975 EIS re facility & all EIS, supplemental EIS or similiar environ documents & FOIA fee waiver decision RYAN, J.A. Streich, Lang, Weeks & Cardon 84/03/27 Office of the Executive Director for Operations 4pp 25557 018 24X Fiche 50-528,84/03/27.8407120136
- B407120142 Responds to appeal re denial of FOIA request for 27 documents referenced in 1975 EIS re facility & all EIS, supplemental EIS or similar environ documents Appeal granted DIRCKS,W J Defice of the Executive Director for Operations B4/05/21 RYAN,J A Streich, Lang. Weeks & Cardon 1p 25557 022 24X Fiche 30-528, B4/05/21, B407120142
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- B40Bi30351 Forwards update to B30127 description of natural circulation test program & "Evaluation of Natural Circulation Cooldown Test Performed at San Onofre Nuclear Generating Station" Confirmatory Item 7 in NUREG-CS57. SSER 5 closed VAN DRUNT, E E Arizona Public Service Co B4/08/07 KNIGHTON. G Licensing Branch 3 23pp 26006 170 24X Fiche 50-528. 84/08/07. 8408130351
- B408270133 Forwards "Containment Ultimate Capacity Analysis," per NUREG-0857, "SER re Operation of Palo Verde Nuclear Generating Station, Units 1,2 & 3" Analysis should close license condition discussed in Section 3 B 1 VAN BRUNT, E E Arizona Public Service Co 94/08/20 KNIOHTON, G Licensing Branch 3 3pp 26245 061 24X Fiche 50-528, 84/08/20, 8408270133
- --B408270140 "Containment Ultimate Capacity Analysis "
  \* Arizona Public Service Co 84/08/31 38pp 26245 064 24X
  Fiche 50-528.84/08/20.8408270133
- F Security, medical, emergency & fire protection plans
- B40B09044B Notification of 840730-31 & 0801 meetings w/util & Comex in Phoenix.AZ & site.respectively.to discuss open issues in onsite emergency planning LICITRA.E A Licensing Branch 3 B4/07/25 KN10HTON.6 W Licensing Branch 3 2pp 25983 213 24X Fiche 50-528.84/07/25, 840B09044B
- 8408130182 Forwards request for add1 info re evacuation time estimate analysis for emergency plan Response requested within 2 wks of ltr receipt KNIOHTON.G W Licensing Branch 3 84/07/27 VAN BRUNT.E E Arizona Public Service Co 3pp 26011 351 24X Fiche 50-528,84/07/27,8408130182
- 8408130160 Confirms 840625 telcon re outcome of 840531 appeal meeting re alternate shutdown capability Appeal granted, based on listed design features for plant & commitment to perform confirmatory PRA analysis
  NOVAK,T M Assistant Director for Licensing 84/07/30 VAN BRUNT,E E Arizona Public Service Co 2pp 26034 351 24X Fiche,50-528.84/07/30.8408130160
- 8408030097 Forwards response to NRC 840605 comments re emergency procedure generation package Steps to verify adequate instruments & controls available for operator to perform assigned task incorporated into validation procedure VAN BRUNT, E E Arizona Public Service Co 84/08/01 KNIGHTON, C Licensing Branch 3 7pp 25904 342 24X Fiche 50-528, 84/08/01, 8408030097
- 8408230310 Confirms B40822-24 audit of emergency operating procedures (EOPs) Five sets of current EOPs, along w/procedure generation package rev, should be provided to NRC by 840813 KNIGHTON, 0 W Licensing Branch 3 84/08/02 VAN BRUNT, E E Arizona Public Service Co. 2pp 26236 100 24% Fiche 50-528,84/08/02,8408230310
- 8408300383 Forwards Insp Repts 50-528/84-25,50-529/84-19 & 50-530/84-12 on 840709-13 & notices of violation & deviation BISHOP.T W Region 5. Office of Director 84/08/08 VAN BRUNT, E Arizona Public Service Co 2pp 26308 122 24Y Fiche; 50-528,84/08/08,8408300383

- --8408300390 Notice of violation from insp on 840709-13 MILLER.L. Region 5. Office of Director 84/08/08 2pp 24308 124 24X Ficha 50-528.84/08/08.8408300383
- --8408300397 Notice of deviation from insp on 840709-13 MILLER,L Region 5. Office of Director 84/08/08 1p 26308 126 24% Fiche 50-528,84/08/08,8408300383
- --8408300407 Insp Repts 50-528/84-25.50-529/84-19 & 50-530/84-12 on B40709-13 Violations noted fire protection sys not designed to retain structural integrity during seismic event CLARK.C Region 5. Office of Director 84/08/03 24pp 26308 127 24X Fiche 50-528.84/08/08.8408300363
- 8408200599 Submits Rev 4 to emergency plan Rev addresses NRC comments, is aligned more concisely w/current operating procedures & clarifies barrier approach to emergency action levels VAN BRUNT.E E Arizona Public Service Co 84/08/15 KNIGHTON.G Licensing Branch 3 3pp 26137 052 24X Fiche 50-528,84/08/15,8408200599
- --8408200600 Rev 4 to emergency plan \* Arizona Public Service Co 84/05/31 83pp 26137 055 24X Fiche 50-528,84/08/15,8408200599
- 8408200112 Forwards "Evaluation Time Analysis,10-Mile Emergency Planning Zone,Arizona Div of Emergency Svcs" & response to 840727 request for addl info VAN BRUNT, E E Arizona Public Service Co 84/08/16 KNIGHTON, O Licensing Branch 3 4pp 26132 321 24X Fiche 50-528,84/08/16, 8408200112
- ~~8408200334 "Evacuation Time Analysis, 10-Mile Emergency Planning Zons, Arizona Div of Emergency Bvcs " \* Arizona, Stata of DLUHM,R B Maricopa County, AZ 84/01/31 22pp 26138 325 24X Fichs 50-528, 84/08/16, 8408200112
- B40B200217 Forwards RBv 5 to emergency action levels Rev addresses comments raised at B40731 meeting re security, external events & challenge/failure of fission product barriers VAN BRUNT.E E Arizona Public Service Co B4/08/16 KNIGHTON.G Licensing Branch 3 Jap 26133 099 24X Fiche 50-52B:B4/08/16,B40B20217
- --8408200224 Rev 5 to emergency action levels \* Arizona Public Service Co 84/08/31 84pp 26133 102 24X Fiche 30-528,84/08/16,8408200217
- B40B270260 Requests approval of two temporary deviations in emergency preparedness plan from goals for augmentation of emergency response organization in Buppl 1 to NUREG-0737 Nature & duration of deviations encl VAN BRUNTLE E Arizona Public Bervice Co B4/0B/20 KNIGHTON, G Licensing Branch 3 27pp 26243 131 24X Fiche 50-528, 84/08/20, 840B270260
- K Utility Final Safety Analysis Report (FSAR) & amends
- B40B030102 Forwards page change list for Amend 13 to FSAR Replacement of original pages requested # Bechtel Corp 84/07/31 Office of Nuclear Reactor Regulation. Director 3pp 25704 336 24X Fiche 50-528.84/07/31.8408030102
- 840B030142 Forwards corrected Pages 3 & 4 to list of effective pages for Palo Verde FSAR.Amend 13 # Bechtel Corp 84/07/31 Office of Nuclear Reactor Regulation. Director 3pp 25915 325 24X Fiche 50-528.84/07/31.8408030142
- B408030093 Forwards page change list for Palo Verds Nuclear Generating Station F8AR, Amend 13, Pages A through J OILMORE, T Bechtel Corp 84/08/01 Office of Nuclear Reactor Regulation, Director App 25916 031 24X Fichs 50-528, 84/08/01, pages 2007.
- 8408060075 Forwards info revising Insert 1 to FSAR,Page 14 2-3 re initial test program VAN BRUNT.E E Arizona Public Service Co 84/08/01 KNIGHTON,G W Licensing Branch 3 7pp 25933 215 24X Fiche 50-528,84/08/01, 8408060075
- 8408010215 Amend 13 to FBAR for Palo Verde Nuclear Generating Station, Units 1,2 & 3 W/34 oversize figures Aperture cards available in PDR W/840801 ltr VAN BRUNT, E E Arizona Public Service Co 84/08/31 1408pp. 25999 122 24X Fiche 50-528.84/08/31,8408010215

# pection reports: [E Bulletins & carrespondence

Region 5, Office of Director 84/04/12 te 50-530,84/04/12,8404230218

50229 IE Info Notice 84-57. "Operating Experience re Moisture rusion in Safety-Related Electrical Equipment at nercial Power Plants " Svc list end DAN.E.L. Division of Emergency Preparedness & Engineering ponse (Post 830103) 84/07/27 Consolidated Edison Co of New I. Inc. 1179p 25865 047 24X Fiche 50-000.84/07/27, 8407250229

10333 IE Info Notice B4-59, "Deliberate Circumventing of Station 1th Physics Procedures " Svc list encl
DANLE L Division of Emergency Preparedness & Engineering ponse (Post 830103) 84/08/06 Consolidated Edison Co of New k, Inc 122pp 24068 001 24% Fache 50-000.84/08/08.8408010333

10337 IE Info Notice 84-60: "Failure of Air Purifying Respirator ters to Meet Efficiency Requirement " Svc list encl
DAN.E L Division of Emergency Preparedness & Engineering younge (Post 830103) 84/08/06 Consolidated Edison Co of New k, Inc 123pp 26067 158 24X Fiche 50-000.84/08/06.8408010337

00094 Forwards Inso Rents 50-528/84-21,50-529/84-1A & 50-530/84-10 00004 Forwards Insp Repts 50-328/04-21, 50-324/84-16 & 50-33 840402-053; & notice of violation HDP.T W Division of Resident Reactor Project & Engineering grams 84/08/07 VAN BRUNT,E E Arizona Public Service Co 26306 141 24X Fiche 50-528,84/08/07,8408300094

8300105 Insp Repts 50-528/84-21,50-529/84-14 & 50-530/84-10 on 140402-0531 Violation noted failure to control mods on nits I & 2 diesel generator bldg wall mounted instruments (ORDERBRUEGEEN, VOUNG, T Region 5, Office of Director 84/08/6pp 24306 144 24% Fiche 50-528.84/08/07,8408300094

)70120 IE Info Notice 84-61, "Overexposure of Diver in PWR ueling Cavity " Svc list encl DAN.E L Division of Emergency Preparedness & Engineering ponse (Post 830103) 84/08/08 Consolidated Edison Co of New k, Inc 120pp 26127 118 24X Fiche 50-000,84/08/08,8408070120

300383 Forwards Insp Repts 50-528/84-25,50-529/84-19 & -530/84-12 on 840709-13 & notices of violation & /Lation

MACHON
MIDP,T W Region 5. Diffice of Director 84/08/08
izona Public Service Co 2pp 26308 122 24X
he 50-528.84/08/08.8408300383 VAN DRUNT, E E

08300370 Notice of violation from insp on 840709-13 11LLER,L Region 5, Office of Director 84/08/08 26308 124 24% Fiche 50-528,84/08/08,8408300383

DB300397 Notice of deviation from insp on 840709-13 HLLER, L Region 5, Office of Director 84/08/08 26308 126 24% Fiche 50-528,84/08/08,8408300383

38300407 Insp Repts 50-528/84-25.50-529/84-19 % 50-530/84-12 on 340709-19 Violations noted fire protection tys not designed to retain structural integrity during setamic event LLARK.C - SCREMBEN.R C - MOLLENBACH.D Region 5, Office of 3408/093 24pp 26308 127 24X Fichs 50-528,84/08/08.

070376 IE Info Notice 84-62, "Therapy Misadministrations to tients Undergoing Co-60 Teletherapy Treatments " Svc

st encl ACE.J N Division of QA. Bafaguards & Inspection Programs (Post 0103) B4/0B/10 Consolidated Edison Co of New York, Inc 5pp 26130 001 24% Fichs 50-000.84/0B/10.8408070376

i00009 lE Info Notice 84-63, "Defective RHR Replacement Piping "
c list enc!
RDAN,E t. Division of Emergency Preparedness & Engineering sponse (Post 830103) 84/08/13 Consolidated Edison Co of New rk. Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

100038 IE Info Notice 84-64, "BMR HPCI Initiation Seal-In & dication " Svc list encl RDAN,E L Division of Emergency Preparedness & Engineering sponse (Post 830103) 84/08/15 Consolidated Edison Co of New rk, Inc. 104pp 26178 093 24X Picke 50-000,84/08/15,8408100038

100021 1E Info Notice 84-65, "Undermated Fuses Which May Adversely fect Operation of Essential Electrical Equipment" Svc

st encl RDAN,E L Division of Emergency Preparedness & Engineering sponse (Post 830102) 84/08/16 Consolidated Edison Co of New rk, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408220051 Act receipt of 840720 ltr informing NRC of steps taken to currect violations noted in IE insp repts conducted between 840501-0601
BISHOP, T W Region 5, Office of Director 84/08/16 VAN BRUNT, E E Arizona Public Service Co 1p 26193 237 24%
Fiche 50-528,84/08/16,8408220051

-8408220071 Responds to NRC 840722 lt; re violations noted in IF insp repts conducted between 840501-0401 Corrective actions Pump A disassembled & defective seal replaced w/new seal Walkdown team established

e Co 84/07/20 BISHOP, T W 26193 23B 24X van Brunt,E E Arizona Public Servic Region 5. Office of Director 10pp Fiche 50-528,84/08/16,8408220051 Arizona Public Service Co

8408100055 [E Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORBAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000.84/08/17,8408100055

B40B14020B IS Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 90-000,84/08/17,8408140208

8408210142 IE Info Notice 84-48. "Potential Deficiency in Improperly Rated Field Wiring to Bolenoid Valves " Svc list oncl JORDAN. E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc. 115pp 26327 008 24% Fiche 50-000.84/08/21.8408210142

S Reportable occurrences, LERs & related correspondence

B408030048 Final Deficiency Rept DER 83-56.Rev i re discrepancies w/ Anchor-Darling MSIVs Initially reported on 830808 Larger hydraulic reservoir w/baffles installed in each MSIV & feedwater isolation valve readwater isolation valve VAN BRUNT, E E Arizona Public Service Co 84/04/13 818HOP, T W Region 5, Office of Director 7pp 25917 330 24X Fiche 50-528,84/04/13,8408030048

8408020232 Corrected Rev 1 to Final Deficiency Rept DER 83-56 re discrepancies w/MSIV mfg by Anchor-Darling Initially reported on 830808 Vendor Instruction Manual E9023-9 revised Also reported per Part 21 VAN BRUNT.E E Arizona Public Service Co 84/07/13 BISHOP.T Division of Resident.Reactor Project & Engineering Programs 7 25898 046 24X Fiche 50-528,84/07/13,8408020232

8408030061 Final Deficiency Rept DER 83-77 re concrete pour containing homeycombed concrete Initially reported on 831109 Homeycombed concrete removed & repaired Item not reportable per 10CFRSO 55(e) VAN BRUNT, E E Arizona Public Service Co 84/07/13 BISHDP, T W Region 5, Office of Director 4pp 25917 323 24X Fiche 50-529,84/07/13,8408030061

8408030302 Final Deficiency Rept DER 84-02 re rust scale & pitting in clevis & arm of several safety injection & CH valves Rust insignificant Deficiency determined not reportable under Insignations Deficiency obsermines not reportable under 100CR980 55(e)

VAN BRUNT, E E Arizona Public Service Co 84/07/13 BISHOP, T W Region 5, Office of Director 2pp 25917 115 24X

Fiche 50-528.84/07/13.8408030302

8408010377 Interim Deficiency Rept DER 84-18 re wiring error on LPSI pump B switch CS-3 Initially reported on 840326 Final rept will be submitted by 840822 VAN BRUNT, E E Artiona Public Service Co 84/07/16 BISHOP, T W Bi

8408010381 Interim Deficiency Rept DER 84-08 re ITT/Barton Model 763 transmitters not meeting specs Initially reported on 840827 Final rept will be submitted by 840824 VAN BRUNT.E E Arizona Public Service Co 84/07/16 BIBHDP.T W Division of Resident Reactor Project & Engineering Programs 2pp 25866 290 24% Fiche 50-528.84/07/16.8408010381

8408010384 Interim Deficiency Rept DER 83-80 re main feedwater isolation valves closing in 20 s instead of Tech Spec required 5 s Initially reported on 831122 Final rept will be submitted by B40823 VAN BRUNT,E E Arizona Public Service Co 64/07/16 BISHOF Division of Resident, Reactor Project & Engineering Programs 25866 286 24% Fiche. 50-528, 84/07/16, 8408010384

- 8408030240 Intain Deficiency Rept DER 83-63 re HPSI isolation valves mfg by Sorg-Warner failing to open against pump A & B flows Initially reported on 830923 Time extension requested due to extensive investigation Next rept by 840831 VAN BRUITLE E Arizona Public Service Co 84/07/16 BISHOP, T W Division of Resident Reactor Project & Engineering Programs 2pp 25917 221 24X Fiche 50-528,84/07/14,8408030240
- 8408010346 Final Deficiency Rept DER 82-37, Rev 1, re Class 1E wiring termination crimped w/less pressure than specified Mork Plant Procedure/OC Instruction 295 0 revised to require maint program VAN BRUIT, E E Ariona Public Service Co 84/07/18 BISHOP, T W Division of Resident Reactor Project & Engineering Programs 12pt 25866 310 24% Fiche 50-528,84/07/18,8408010346
- 8408010388 Interin Deficiency Evaluation Rept 84-43 re HPSI 3-inch gate valve failing to open Initially reported on 840622 Conditions not reportable per 10CFRSO 35(e) VAN BRUNT, E & Arizona Public Service Co 84/07/18 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 25866 281 24X Fiche 50-528, 84/07/18, 8408010388
- 8408030053 Interim Potential Deficiency Rept DER 84-42 re replacement of environmentally qualified torque switches w/unqualified switches Initially reported on 840618 Final rept expected by 840820

  VAN BRUNT, E E Arizona Public Service Co 84/07/18 BISHOP, T W Region 5, Office of Director 3pp 25917 327 24X Fiche 50-528, 84/07/18, 8408030053
- 8408080499 Final Deficiency Rept DER 83-75 re improper torquing of bolts on two DD1268A panel filler assemblies Bolts retorqued Deficiency not reportable under 10CFR30 53(e) VAN BRUNT.E E Arizona Public Selvice Co 84/07/24 BISHCP,T W Division of Resident. Reactor Project & Engineering Programs 5pp 23975 232 24x Fiche 50-528.84/07/24,8408080499
- 8408080529 Rev I to final Deficiency Rept DER 81~49 re erroneous readings on NSSS bater level transmitters due to variations of water leg Condensate pots for Steam generator & pressurizer level measurements installed on root valves VAN BRUNT,E E Arizona Public Servite Co 84/07/24 BISHOP,T W Division of Resident Reactor Project & Engineering Programs App 25975 298 24X Fiche 50-528,84/07/24,8408080529
- 8408070012 Final Deficiency Rept DER 84-0B re failure of ITT/Darton Model 763 transmitters to meet specs PPS setpoints revised on existing transmitters & Barton working on physical mod to meet specs Also reportable under Part 21 VAN BRUNT.E E Arisona Public Service Co 84/07/24 BISHOP, T W Division of Resident Reactor Project & Engineering Programs 4pp 25995 011 24X Fiche 50-528.84/07/24,8408070012
- B40Bi30172 Interim Deficiency Rept DER B3-B1 re manufacturing defect in Gulfally Schedule 160 SS pipe Initially reported on B3112B Due to extensive investigation & evaluation required final rept will be delayed until 840B30 VAN BRUNT.C E Apriona Public Service Co B4/07/27 DISHOP.T W Division of Resident.Reactor Project & Engineering Programs 2pp 26010 036 24X Fiche 50-52B.B4/07/27,840B130172
- 8408130332 Interin Deficiency Rept DER 84-09 re CAD welding for cathodic protection ground connection Initially reported on 840829 Final rept will be submitted by 840830 VAN BRUNT.E E Arizona Public Service Co 84/07/27 BIBHOP.T W Division of Resident.Reactor Project & Engineering Programs 2pp 26010 303 24X Fiche 50-528.84/07/27.8408130332
- 8408130344 Interim Deficiency Rept DER 82-80 re low insulation resistance values or terminal blocks supplied by Conax Corp Initially reported on 821217 Final rept by 840817 VAN BRUNT, C E Arizona Public Service Co 84/07/30 BISHOP, T W Division of Resident Reactor Project & Engineering Programs 2pp 26010 222 24X Fiche 50-528,84/07/30,8408130344
- 8408160192 Final Deficiency Rept DER 84-10 re resistance temp detectors Caused by torsional twisting of element & sheath during horing aperation, resulting in broken internal wire Item not reportable per 10CFR90 55(a) VAN DRUNT.E E Arisona Public Service Co 84/08/01 BISHOP, T W Region 4. Office of Director 3pp 26106 334 24X Fiche 50-528,84/08/01.8408160192
- 840B160480 Final Deficiency Rept DER 84-16 re ESF actuation sys relay cabinet baseplates Initially reported on 840321 Cabinet backs will be reinforced w/3/8-inch thick vertical stiffener plate Aiso reportable under Part 21
  VAN BRUNT, E E Arizona Public Service Co 84/08/02 BISHOP, T W Division of Resident. Reactor Project & Engineering Programs 4pp 26107 292 24% Fiche 50-528,84/08/02,8408160480

- 3408160506 Final Deficiency Rept DER B3-78 re lack of users test documentation & controlling procedure for rock bolt expansion anchors initially reported on B31109 Item not reportable under 10CFR50 55(e) & Part 21 VAN BRUNT E E Arizona Public Service Co B4/08/02 BISHDP.T W Division of Resident. Reactor Project & Engineering Programs 9pp 26107 326 24X Fiche 50-528.84/08/02,8408160506
- 8408220128 Interim Deficiency Rept DER 84-33 re incorrectly installed hanger support assembly Initially reported on 840504 Due to extensive investigation, final rept will be available 840831 instead of 840810

  VAN BRUNTLE E Arizona Public Service Co 84/08/06 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 26188 348 24% Fiche 50-528.84/08/06, 8408220128
- 8408220143 Interim Deficiency Rept DER 84-44 re fatigue failures of Oaulin charging pumps Initially reported on 840706 Bechtel investigating Final rept to be completed by 840927 Reported under Part 21 by Northeast Utils

  VAN BRUNT, E E Arizona Public Service Co 84/08/06 BISHDP, T W Division of Resident Reactor Project & Engineering Programs 3pp 26188 065 24% Fiche 50-528,84/08/06,8408220143
- B40B200332 Part 21 rept re tension wires on Titus Grille, Model 272, not remaining in place when deflection blades closed Affected job sites identified in encl Products being tested to provide acceptable fix for retention SCHNEIDER, S. t. Phillips Industries, Inc. B4/08/07 Director's Office, Office of Inspection and Enforcement 3pp 26/33 315 24X Fiche 50-000.84/08/07.8408200332
- 8408200333 Part 21 rept re tension wires used for adjustment of blades on Grille Model 272 not remaining in place when blades closed Review & testing conducted to identify number of grilles & rework methods to be utilized SCHNCIDER.8 L Phillips Industries, Inc 84/08/07 STRAIT, R Aprisona Public Service Co 1p 26/32/360 24X Fiche 50-528,84/08/07,8408200333
- 8408200297 Interim Deficiency Rept DER 84-34 re critical friction-type high atrength connectors Due to extensive evaluation.next rept delayed until 840904 VAN BRUNT,E E Arizona Public Service Co 84/08/09 BISHOP,T W Region 5. Office of Director 2pp 26140 090 24X Fiche 90-328,84/08/09,8408200297
- 8408200322 Final Deficiency Rept DER 83-61 re C-E low pressure safety injection pump failure to start & produce required head Case wear rings replaced & clearance between impeller & casing increased Proprietary CFN-285 (V)-P encl VAN BRUNT.E E Arizona Public Service Co 84/08/09 BISHOP.T W Division of Resident.Reactor Project & Engineering Programs 40pp 26133 318 24X Fiche 50-528.84/08/09.8408200322
- 8408200285 Final Deficiency Rept DER 83-82 re improper bend radius in diesel generator control cabinets Initially reported on 840103 Forwards "Technical Rept for Palo Verda Nuclear Station-Bechtel Power Corp on Returned Cable NCR 665419 "
  VAN DRUNT, E E Arizona Public Service Co 84/08/10 DISHOP, T W Region 5. Office of Director 13pp 26139 307 24x
  Fiche 50-528,84/08/10.8408200285
- --8408200288 "Tochnical Rept for Paio Verde Nuclear Station-Bechtel Power Corp on Returned Cable NCR E63619" " MUNIGOMERY,R, BLABLEY,B Anaconda Co (subs of Atlantic Richfield Co ) 84/01/24 11pp 26139 320 24X Fiche 50-528,84/08/10,8408200289
- B40B2B0302 Interim Deficiency Rept DER 83-87 re cracks in control element assembly shroud Initially reported on B30729 Requests extension until 840915 for submittal of final rept to allow for pust-demonstration test inspeculation VAN BRUNT.E E Arizona Public Service Co 84/08/13 BISHOP.T W Division of Resident.Reactor Project & Engineering Programs 2pp 24282 161 24X Fiche 50-528.84/08/13.8408280302
- 8408280317 Interim Deficiency Rept DER 83-49 re broken impeller blades & diffuser bolts broken/loose in reactor coclant pumps
  Initially reported on 830715 Time extension until 840915 for final rept requested for post-demonstration test insp
  VAN BRUNT, E Arizona Public Service Co 84/08/13 BISHOP, T W
  Division of Resident. Reactor Project & Engineering Programs 2pp
  26282 257 24X Fiche 50-528.84/08/13.8408280317
- B40B2B0335 Interim Deficiency Rept DER 83-42 re thermowells in RCS Initially reported on B30629 Extension for submittal of final rept from B40B15 to B40915 requested due to need for evaluation of post-demonstration test insp VAN BRUNT, E E Arizona Public Service Co 84/0B/13 BISHOP, T W Division of Resident/Reactor Project % Engineering Programs 2pp 26282 259 24X Fiche 50-528.84/08/13,8408280335

- 8408280357 Interm Deficiency Rept DFR 84-26 to improperly tested or adjusted plunger interinck Initially reported on 840510 Final rept will be submitted by 840715

  VAN BRUNTLE Ariona Public Service Co 84/08/13 BISHOP, T W Division of Resident-Reactor Project & Engineering Programs 2pp 26202 250 24% Fiche 50-528.84/08/13,8408280357
- 84082802004 Interim Deficiency Rept DER 84-25 re containment supply register failure to cycle Initially reported an 840301 Galvanized wire will be replaced w/stainless steel wire to gain higher tensile strength Next lept expected by 840721 VAN BRUNT, E. (Arizona Public Service Co. 84/08/16. BISHOP, T. W. Division of Resident Reactor Project & Engineering Plagrams. 3pp 26282 166. 24X Fiche 30-528,84/08/16.8408280204
- 8408280297 Interim Deficiency Rept DER 84-46 re refueling water tany penetration sleaves Initially reported on 840717 Bechtel evaluation of reportability & corrective action in progress VAN BRUNT, C. Arizona Public Service Co. 84/08/16 BISHOP, T. W. Division of Resident Reactor Project & Engineering Programs. Spp. 26282 150 24% Fichs 50-528,84/08/16,8408280297
- 8408280283 Interim Deficiency Rept DER 82-80 re low insulation resistance values for terminal blocks supplied by Conax Corp Initially reported on 821217 Final rept expected by 840903 VAN BRUNT, E.C. Arizona Public Bervice Co. 84/08/17 BISHOP, T.W. Division of Resident/Reactor Project & Engineering Programs 2pp 26282 178 24% Fiche 50-528,64/08/17,8408280283
- DOCKET 90-539 MEMPHIS STATE UNIV RESCARCH REACTOR
  P Security, modical, emergency & fire protection plans
- 8408170286 Revised "Emergency Plan Memphis State Univ. AON-201 Reactor Facility " W/840809 ltr JONES, D W Memphis State Univ. Memphis, TN 84/08/01 THOMAS, C O Standardization & Special Projects Branch 35pp 26114 282 24X Fiche 50-838,84/08/01.8408170286
- DDCKET STN-90-946 MARBLE HILL NUCLEAR STATION, UNIT 1

  A Application/construction stage documents & correspondence
- 8408070ii0 Generic Ltr 84-i9 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of Guppl 1 to NUREG-0933, "Prioritization of Generic Bafety Issues "Swc list encl EIEENHUT.D O Division of Licensing 94/08/04 Consolidated Edison Co of New York, Inc. 18pp 24129 238 24X Fichs 50-000.84/08/04.84080/0110
- B40B200275 Quaeric Ltr 84-20 to all licensees of operating reactors & applicants for OLs re-schoduling guidance for licensee submittals of reloads that involve unreviewed safety questions Eve list enci E18EMHUT, D.O. Bivision of Licensing B4/0B/20 Consolidated Edison Co. of New York. Inc. 17pp. 26276-244 24X Fiche 50 000.84/0B/20.840B200275
- ii General correspondence
- 0405180145 Responds to 840314 ltr to Chairman Palladino which encl W & V Smelser concern re Marble Hill & Bailly cancellation, withdrawal of util application for Zimmer & denial of license for Byron facility DIRCKS, W J Office of the Executive Director for Operations 84/05/04 LUGAR, R O Senate 7pp 24524 325 24X Fichs 50-000,84/05/04,8405180145
- --B409180152 Requests response to encl & & V Smelser 840210 inquiry into NRC attitude toward utils Concerns include Marble Hill & Bailly cancellation, withdrawal of util application for Zimmor & donial of license for Hyron facility LUGAR.R G Bonate 8470374 PALLADING.N Commissioners 3cp 24524 331 24X Fiche 50-000,84705704,8405180145
- Q Inspection reports, IL Bullatine & correspondence
- B407250227 IE Info Notice 04-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JDRDAN FL Division of Emergency Preparedness & Engineering Response (Post B30103) 84/07/27 Consolidated Edison Co of New York, Inr 119pp 25845 047 24X Fiche 50-000.84/07/27.8407250229

- B40B070401 Informs that new sys of acknowledging leceipt of licensee correspondence re honcompliance found during inspinstituted effective B40B20 Preprinted form will be used rather than ltr
  KEPPLER, J G Region 3. Office of Director B4/0B/03
  Commonwealth Edison Co 3pp 25942 188 24% Fiche 50-000,84/0B/03,840B070401
- 8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/04 Consolidated Edison Co of New York, Inc 122pp 26059 001 24X Fiche 50-000,84/08/06,8408010333
- B408010337 IC Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Weet Efficiency Requirement" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 123pp 26067 158 24X Fiche 50-000.84/08/06.8408010337
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/09 Consolidated Edison Co. of New York, Inc. 120pp 26129 118 24X Fiche 90-000,84/08/08,8408070120
- B408070376 IE Info Notice 84-62. "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list enci ORACE.J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York Inc 125pp 26130 001 24% Fiche 50-000.84/08/10.8408070378
- 840B100009 IE info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN, E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc. 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038
- 840B100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc. 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021
- B40B100055 IE Info Notice B4-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svt list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp 26276 001 24X Fichs 50-000.64/08/17,8408100055
- 8408140208 IE Info Notice 84-67. "Recent Shubber Inservice Testing W/ High Failure Rates" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 850103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140209
- 840B210142 IC Info Notice 84-68, "Potential Deficiency in Inproperty Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc. 115pp 26327 008 24X Fiche 50-000,84/08/21,8408210142
- 8 Reportable occurrences, LERs & related correspondence
- B407310030 Board Notification 84-134 forwards JF Streeter 840711 memoto DO Eisenhut restean generator snubber testing failures Insp. repts documenting results of testing bapplicant reevaluation efforts will be forwarded to Board NOVAK,T M. Assistant Director for Licensing 84/07/27 SMITH.I W. Atomic Safety and Licensing Board Panel 2pp 29936-033 24X Fiche 50-000.84/07/27.8407910030
- ~-B408060344 Discusses steam generator snubber testing failures Snubbers made by Boeing Co Vendor Program Branch will be notified Results of testing & applicant reevaluation efforts will be documented in IE insp repts STREETER.J F Region 3. Office of Director B4/07/11 EIBENHUT.D G Division of Licensing ip 25736 035 24X Fiche 50-000,84/07/27,8407310030

- DDCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

  A Application/construction stage documents 5 correspondence
- 8408070110 Generic Ltr 84-19 to all licensess of operating reactors, applicants for GLs & holders of CPs re availability of Suppl 1 to NUREG-0933. "Prioritization of Generic Safety Issues." Svc list encl
  EISENHUT.D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc. 18pp 26129 238 24X
  Fiche 50-000.84/08/96.8408070110
- 8408200279 Generic Ltr 84-20 to all licensees of operating reactors & applicants for CLs is scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT.D & Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc. 17pp 26276 244 24X Fiche 50-000.84/08/20.8408200275
- H General correspondence
- 8405180145 Responds to 840314 ltr to Chairman Palladino which encl W & V Smelser concern re Marble Hill & Bailly cancellation, withdraual of util application for Zimmer & denial of license for Byran facility Director for Operations 84705704 LUGAR.R C Senate 7pp 24524 325 24X Fiche 50-000.84705/04.8405180145
- --8405180152 Requests response to encl W & V Smelser 840210 inquiry into NRC attitude toward otals Concerns include Marble Hill & Bailly cancellation, withdrawal of util application for Zimmer & denial of license for Byron facility LUGAR.R O Benate 84/03/14 PALLADIND.N Commissioners 3pp 24524 331 24X Fiche 50-000,84/05/04,8405180145
- Q Inspection reports: IE Bulletins & correspondence
- 8407250229 IE Info Notice 84-37, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc. 119pp 25865-047 24X Fiche 50-000.84/07/27,8407250229
- B40B070401 Informs that new sys of acknowledging receipt of licensee correspondence re nonconpliance found during insp instituted, effective 840B20 Proprinted form will be used rather than ltr KEPPLER.J G Region 3, Office of Director 84/08/03 Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000,84/08/03.840B070401
- B40B010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) B4/0B/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24% Fiche 50-000,84/08/06,8408010333
- 8408010337 IE Info Notice 84-40, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list enci JGRDAN, E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/04 Consolidated Edison Co of New York, Inc 123pp 24047 158 24X Fiche 50-000,84/08/04,8408010337
- 8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list enc! JORDAN, E.L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York, Inc. 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- 8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Toletherapy Treatments" Svc list encl GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000.84/08/10.8408070376
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JORDAN E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fichs 30-000,84/08/13,8408100009
- B40810003B IE Info Notice 84-64, "BWR HPCI Initiation Seal~In & Indication "Svc list and!

  JURDAN,E L Division of Emergency Proparedness & Engineering Response (Post B30103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26178 093 24% Fiche 50-000.84/08/15,8408100038

- 840B10002) IE Info Notice B4-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc. 118pp 26198 001 24X Fiche 50-000,84/08/16,840B100021
- 8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JCRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055
- B40B14020B IE Info Notice B4-67. "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/08/17 Consolidated Edison Co of New York, Inc 122pg 26276 122 24X Fiche 50-000,84/08/17,8408140208
- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York. Inc 115pp 26329 008 24X Fiche 50-000.84/08/21,8408210142
- 8 Reportable occurrences, LERs & related correspondence
- 8407310030 Doard Notification 84-134 forwards JF Streeter 840711 memo to DG Eisenhut re steam generator snubber testing failures Insp repts documenting results of testing & applicant reevaluation efforts will be forwarded to Board NDVAX.T M Assistant Director for Licensing 84/07/27 SMITH.I W Atomic Safety and Licensing Board Panel 2pp 25936 033 24X Fiche 50-000.84/07/27.8407310030
- --B408060344 Discusses steam generator snubber testing failures Enubbers made by Boeing Co Vendor Program Branch will be notified Results of testing & applicant reevaluation efforts will be documented in IE insp repts
  STREETER.J F Region 3, Office of Director 84/07/11
  EISENHUT.D G Division of Licensing 1p 25936 035 24X
  Fiche 50-000,84/07/27,8407310030
- DOCKET STN-50-546 YELLOW CREEK NUCLEAR PLANT. UNIT 1
  A Application/construction stage documents & correspondence
- 8408230318 Requests remittance of fee for 830321 application for extension of const completion dates DIGGS.R M License Fee Hanagement Branch 84/08/16 PARRIS.H Q Tennessee Valley Authority 2pp 26236 098 247 Ficho 50-000.84/08/16.8408230318
- DOCKET SYN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 8408230318 Requests remittance of fee for 830121 application for extension of const completion dates DIGOS.R M License Fee Hanagement Branch 84/08/16 PARRIS.H G Tennessee Valley Authority 2pp 26236 098 24X Fiche 50-000.84/08/16.8408230318
- DDCKET 50-601 RESAR SP/90
- A Application/construction stage documents & correspondence
- 8408090321 Informs that REBAR-SP/90 Preliminary Design Approval Module 4. "RCB." will be withheld from public distlosure, per raview of application to withhold mat! (ref 10CFR2 790) Westinghouse reasons for exemption listed THOMAS.C O Standardization & Special Projects Branch 84/08/01 MIESEMANNR A Westinghouse Electric Corp 3pp 25984 347 24X Fiche 50-601,84/08/01,8408090321
- 8408140278 Forwards table of contents illustrating integrated Modules 6 | & 8 re secondary side safeguards sys & steam & power : conversion sys RAHE, E P Westinghouse Electric Corp 84/08/02 DENTON, H R Office of Nuclear Reactor Regulation Director ipp 26055-344, 24X Fiche 50-601,84/08/02,8408140278
- B408230467 Notifies that 840731 request to withhold REBAR-SP/90 preliminary design approval application from public disclosure under 105R2 790 granted Matl will be treated as proprietary info THOMAS.C O Standardization & Special Projects Branch 84/08/16 WIESEMAN.R A Westinghouse Electric Corp 3pp 26230 251 24X Fichs 50-601.84/08/16.8408230467

- F Security, medical. emergency & fire protection plans
- 8408140278 Forwards table of contents illustrating integrated Modules 6
  - 00140278 Forwards table of contents illustrating integrated Modul & 8 re secondary side safeguards sys & steam & power conversion sys RAHE.E P Westinghouse Electric Corp 84/08/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 11pp 26055 344 24X Fiche 50-601.84/08/02.8408140278
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8408080278 Forwards proprietary & nonproprietary Vols 1 & 2 of REBAR~SP/90 Westinghouse Advanced PWR, Module 5. "Reactor Sys " Proprietary rept withheld (ref 10CFR2 790) RAHE.E P Westinghouse Electric Corp 84/07/31 DENTON.H R Office of Nuclear Reactor Regulation. Director ECCLESTON.K T Standardisation & Special Projects Branch 2pp 25985 129 Fiche 50-601.84/07/31,8408080278
- --B408090286 Requests withholding proprietary Vols 1 & 2 of RESAR-SP/90 Westinghouse Advanced PWR. Module 5. "Reactor Sys" (ref 10CFR2 790) Affidavit AM-92-57 enci HIEGEMANN.R A Westinghouse Electric Corp 84/07/31 DENTON.H R Office of Nuclear Reactor Regulation, Director 9pp 25985 131 248 Fishe 50-601,84/07/31,8408080278
- --8408080289 Nonproprietary Vols i & 2 of RESAR-SP/90 Westinghouse Advanced PWR Module 5, "Reactor Sys " # Westinghouse Electric Corp 84/07/31 562pp 25985 140 24X Fiche 50-601.84/07/31.8408080278
- --8408080292 Nonproprietary Chapter 1 of RESAR-SP/90 Westinghouse Advanced PWR Module 5, "Reactor Sys," "Introduction 5 General Description of Plant" \* Westinghouse Electric Corp 84/07/31 34pp 25983 175 Fiche 50-601,84/07/31.8408080278 84/07/31 34pp 25985 175 24X
- --B40B0B0295 Nongroprietary Chapter 2 of RESAR-SP/90 Westinghouse Advanced PWR Module 5, "Reactor Sys," "Site Characteristics" \* Westinghouse Electric Corp 84/07/31 1p 25985 209 2 Ficha 50-601,84/07/31,8408080278
- --B40B080278 Nongropristary Chapter 3 of RESAR-SP/90 Westinghouse Advanced PWR Moduls 5, "Reactor Bys," "Design of Structures, Components, Equipment & Sys " \* Westinghouse Electric Corp 84/07/31 5ipp 25985 210 Fiche 50-601,84/07/31,8408080278 84/07/31 51pp 25985 210 24X
- --8408080301 Nonproprietary Chapter 4 of RESAR-SP/90 Westinghouse Advanced PWR Module 5. "Reactor 8ys." "Reactor " \* Westinghouse Electric Corp 84/07/31 296pp 25985 261 Fithe 50-601.84/07/31.8408080278 25985 261 24%
- --B408080304 Nonproprietary Chapter 5 of RESAR-SP/90 Westinghouse Advanced PWR Module 5, "Reactor Sys." "RCS & Connected Sys." \* Westinghouse Electric Corp. 84/07/31 1p. 25786 197 24X Fiche 50-601,84/07/31,8408080278
  - 8408080307 Nonproprietary Chapter 5 of RESAR-SP/90 Westinghouse Advanced PMR Module 5, "Reactor Sys," "ESF " \* Westinghouse Electric Corp 84/07/31 1p 25985 198 24X Fiche 50-601,84/07/31,8408080278
- 8408080307 Nonproprietary Chapter 7 of RESAR-SP/90 Hestinghouse Advanced PWR Module 5, "Reactor Sys," "Instrumentation & Controls" Controls "
  \* Westinghouse Electric Corp (
  Fiche 50-601,84/07/31.8408080278 84/07/31 1o 25986 199 24Y
- B4080B0312 Nonproprietary Chapter 8 of RESAR-SP/70 Westinghouse Advanced PMR Module 5, "Reactor Sys," "Electric Power" \* Westinghouse Electric Copp 84/07/31 ip 25986 200 24X Fiche 50-601,84/07/31,8408080278
- -8408080315 Nonproprietary Chapter 9 of RESAR-8P/90 Westinghouse Advanced PRR Module 5, "Reactor Sus," "Auxiliary Sys " of the Stinghouse Electric Corp 84/07/31 ip 25986 201 24X Ficks 50-601,84/07/31,8408080278
- ---8408080318 Nonproprietary Chapter 10 of RESAR-SP/90 Westinghouse Advanced PWR Module 5, "Reactor Sys," "Steam & Power Conversion " \* Westinghouse Electric Corp ( Fiche 50-601,84/07/31,8408080278 84/07/31 1p 25986 202 24X
- --8408080320 Nongroprietary Chapter 11 of RESAR-SP/90 Westinghouse Advanced PMR Module 5. "Reactor Sys." "Radwaste Mgt " \* Westinghouse Electric Corp 84/07/31 ip 23486 203 24X Fiche 50-601,84/07/31, 8408080278

- --8408080323 Nonproprietary Chapter 12 of RESAR-SP/90 (Jestinghouse Advanced PNR Module 5, "Reactor Sys," "Radiation Protection"
  - Westinghouse Electric Carp 84/07/31 1p 25986 204 24% Fiche 50-601, 84/07/31, 8408080278
- --B40B0B0330 Nonproprietary Chapter 13 of RESAR-8P/90 Westinghouse Advanced PNR Module 5, "Reactor Sys," "Conduct of Operations"
  - 84/07/31 1p 25986 205 24X \* Westinghouse Electric Corp Fiche 50-601, 84/07/31, 8408080278
- --8408080342 Nonproprietary Chapter 14 of RESAR-SP/90 Westinghouse Advanced FWR Module 5, "Reactor Sys," "Initial Test
  - Program "

    \* Westinghouse Electric Corp 84/07/31 ip 25986 206 24x
    Fiche 50-601, 84/07/31.8408080278
- --B40B0B0343 Nonproprietary Chapter 15 of RESAR-SP/90 Westinghouse Advanced PWR Module 5. "Reactor Sys." "Accident Analyses " \* Westinghouse Electric Corp 84/07/31 133pp 25986 207 Fiche 50-601.84/07/31.84080880278
- ~-B40B0B0345 Nonproprietary Chapter 16 of RESAR-SP/90 Westinghouse Advanced PWR Module 5. "Reactor Sys." "Tech Specs" \* Westinghouse Electric Corp B4/07/31 ip 25986 340 24X Fiche 50-601, 84/07/31, 840B080278
- --8408080347 Nonproprietary Chapter 17 of RESAR-89/90 Westinghouse Advanced PWR Module 5. "Reactor Sys." "9A" \* Westinghouse Electric Corp 84/07/31 1p 25986 341 24x Fiche 50-601,84/07/31,8408080279

#### DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-0008 BATTELLE HEMORIAL INSTITUTE, COLUMBUS, OH

- 8408020220 Forwards IE Insp Rept 70~0008/84-02 on 840611-14 No noncompliance noted
  PAPERIELLO,C J Region 3, Office of Director 84/07/06 UNGAR.E W
  Battelle Memorial Institute, Columbus Laboratories 2pp
  25898-012
- --B40B020223 IE Insp Rept 70-0008/84-02 on 840411-14 No noncompliance noted Major areas inspected litensing status operations review radiation protection, safety committees & nuclear FRANCE, O M. MILLER, D E., GREGER, L. R. Region 3, Office of Director 84/07/06 10pp 25898 014
- --8408020225 Forwards ANL rept re technical review of Region III Insp Repts 70-0008/83-03 & 70-0008/84-01 ANL work confirms NRC conclusions re metabolic data & body radioactivity BERGER.J D Oak Ridge Associated Univs 84/05/03 GREGER.R Region 3. Office of Director 7ap 25898 024
- 8408170016 Application for amend to License SNM-7, authorizing incineration of low level radwaste at West Jefferson Nuclear Sciences area Response to list of questions following initial NRC review will be furnished by 840930 TOY.H L Battelle Memorial Institute, Columbus Laboratories 84/07/30 ROUSE, L Advanced Fuel & Spent Fuel Licensing Branch 2pp 26135 345
- DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP., CANOGA PARK, CA
- 8408130964 Forwards revised Pages 12.16 & 17 of E8G-80-17, "Physical Security Plan for Protection of Moderate Strategic Quantities of SNM at Hot Labs of Energy Sys Group of Rockwell Intl " Rev withheld (ref 10CFR2 790 & 9 5) REMLEY, M E Rockwell International Corp 84/07/24 MARTIN, J B Region 5. Office of Director 2pp 24080 306
- DUCKET 70-0027 BABCOCK & WILCOX CD / LYNCHBURG/ VA
- 8408300367 Forwards summary of NRC 840531 meeting w/B&W in Region 11 ofc re activities authorized by License SNM-42 List of meeting attendees also encl STOHRJJP Region 2. Office of Director 84/06/07 ECKERT.JP Babcock & Wilcox Co 3pp 26308 189
- 840B130454 Application for amend to License SNM-42, forwarding changes to fundamental nuclear natis control plan, per 100FR70 32
  Encls withheld (ref 100FR2 790)
  REGANN A Babcock & Hilcox Co. 84/06/22 O'REILLY, J.P. Region 2:
  Office of Director 1p. 26040 362

- 8408300391 Forwards Insp Rept 70-0027/84-12 on 840611-15 No violations or deviations identified STOHR.JP Region 2. Office of Director 84/06/28 ECKERT.JP Babcock & Wilcox Co 2pp 26314 357
- --8408300394 Insp Rept 70-0027/84-12 on B40611-15 No violations or deviations identified Major areas inspected limit of error associated wi/inventory difference Details withheld (ref 10CFR2 790 & 73 21) JONES, D.W.; MCALPINE, E.J. Region 2, Office of Director 84/06/27 ip 26314 339
- 8408310031 Ack receipt of 840617 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-0027/84-09 STDHR.J P Region 2. Office of Director 84/07/12 ECKERT.J P Babcock & Wilcox Co ip 26335 165
- --8408310037 Responds to NRC 840524 ltr re violation noted in Insp Rept 70-0027/84-07 Corrective actions measurement control coordinator shall investigate exceeded control data limits within established time interval ECKERT.J P Babcock & Wilcox Co 84/06/17 O'REILLY.J P Region 2. Office of Director 3pp 26335 166
- 8408300398 Forwards Insp Rept 70-0027/84-14 on 840627-0702 No violations or deviations identified STOHR, J P Region 2. Office of Director 84/07/18 ECKERT, J P Babcock & Wilcox Co 2pp 26314 360
- --8408300401 Insp Rept 70-0027/84-14 on 840627-0702 No violations or deviations identified Major areas inspected storage & internal control, physical inventory, records & repts Details withheld (ref 10CFR2 790 & 73 21)
  TODD, 0 A , RATES, J W , JONES, D W Region 2, Dffice of Director 84/07/18 1p 26314 362
- 8408210483 Application to amend License SNM-42, adding Cs-137 to possession limits & allouing nuclear safety evaluations & consultations to be made by nuclear criticality safety engineer Fee encl REGANIN A Babco Licensing Branch Babcock & Wilcox Co 8 ranch 23pp 26195 264 84/07/27 PAGE, R.G. Uranium Fuel
- 8408270524 Forwards Insp Rept 70-0027/84-16 on 840626-27 No violations or deviations identified STOHR.JP Region 2, Office of Director 84/07/27 ECKERT.JP Babcock & Wilcox Co 2pp 26256 136
- --8408270531 Insp Rept 70-0027/84-16 on 840626-29 No violations or deviations identified Major areas inspected radiation protection raduaste mgt.periodic maint of packaging & PEERY.W W. JENKINS.G.R. Region 2. Office of Director 84/07/25 5pp 26256 138
- 8408270254 Ack receipt of 840621 & 0726 Itrs informing NRC of steps taken to correct violations noted in Insp Rept 70-0027/84-10 STOLKI, J.P. Region 2. Office of Director 84/08/01 ECKERT, J.P. Babcock & Wilcox Co. ip. 26258 129
- --8408270288 Submits add1 response to NRC 840523 ltr re violations noted in Insp Repts 70-0027/84-10 Corrective actions proposed changes of organizational structure will be reviewed for licensing impact ECKERTJP Babcock & Wilcox Co 84/07/26 O'REILLY(JP Region pact Babcock & Wilcox Co - 84/0 Director - 2pp - 26258 130 84/07/26 O'REILLY, J P Ragion 2. Office of Director
- --8408270274 Responds to NRC 840523 ltr re violations noted in Insp Rept 70-0027/84-10 Corrective actions amend will be submitted to renewed license indicating present organization reporting scheme for health & safety function ECKERT.JP Babcock & Wilcox Co 84/06/21 O'REILLY,JP Region 2, Office of Director 29p 26298 132
- --8408270280 Forwards Insp Rept 70-0027/84-10 on 840424-27 & notice of STORK JP Region 2, Office of Director 84/05/23 ECKERT, JP Babcock & Wilcox Co 2pp 26258 134
- ---8408270282 Notice of Violation from insp on 840424-27 \* Region 2, Office of Director 84/05/23 1p 2 26258 136
- --B40B270286 Insp Rept 70-0027/B4-10 on 840424-27 Violation noted failure to conform to required health & safety organizational structure KAHLE.J B . MCALPINE,E J Region 2. Office of Director 84/05/21 6pp 26298 137

- 8408270116 Ack receipt of 840716 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-0027/84-11 STCHRJ J P Region 2. Office of Director 84/08/09 ECKERT, J P Babcock & Wilcax Co Ip 26288 235
- --9408270121 Responds to NRC 840622 ltr re-violation noted in IE Insp. Rept 70-0027/84-11 Corrective actions period data for control chart limits tested & data shown to be statistically different not used in computing new limits ECKERT.JP Babcock & Wilcox Co 84/07/16 D'REILLY.JP Regio 2. Office of Director Spp 26298 236 84/07/16 D'REILLY, J.P. Regian
- ~-8408270125 Forwards IE Insp Rept 70-0027/84-11 on 840604-07 & notice of vacilation Encls withheld (ref 196FR2 790 & 73 2))
  STOHR.JP Region 2, Office of Director 84/06/22 ECKERT, JP Babcock & Wilcox Co 2pp 26258 241
- DOCKET 70-0036 COMBUSTION ENGINEERING, INC., WINDSOR, CT
- 8408210183 Forwards application to renew License SNM-33 Fee encl ESKRIDGE.H E Combustion Engineering, Inc. 82/02/24 PAGE.R G Uranium Fuel Licensing Branch 2pg 26194 081
- --8408210190 Informs of withdrawal of proprietary designation from Chapters II 9 0 & II 10 0 of license renewal application ESKRIDEE,H E Combustion Engineering, Inc. 82/07/21 CRDW.W Uranium Fuel Licensing Branch 3pp 26174 082 CROW, W. T.
- --8408210197 Application for renewal of License SNM-33 Five oversize drawings encl Aperture cards are available in PDR \* Combustion Engineering, Inc 82/01/29 232pp 26194 087
- 8408020205 Application for amend to License SNM-33 providing proposed decommissioning plan required by License Condition 10 Proposed plan & fee encl ESKRIDOE-H E Combustion Engineering, Inc 84/05/3: PAGE,R Q Uranium Fuel Licensing Branch 1p 25878 170
- --8408020207 "Proposed Decommissioning Plan for Evaporation Ponds." \* Combustion Engineering, Inc. 84/05/31 App. 25898 171
- --B408020209 Ack receipt of 840531 request for approval of decommissioning plan Request classified as requiring minor amend to License SMM-33 Amend fee required, per 10CFR170 31 WEISS, D. License Fee Management Branch 8406/28 ESKRIDGE, H E Combustion Engineering, Inc. 2pp 25898 177
- DOCKET 70-0143 NUCLEAR FUEL SERVISE INC . ERWIN, TN
- 8408150154 Forwards "Environ Rept," per 840524 ltr IDEKER, R.L. Nuclear Fuel Services. Inc. (subs. of Getty Oil Co.) 84/07/27 Materials Licensing Branch 2pp. 26105-068
- --8408150161 "Environ Rept"

  \* Nuclear Fuel Services, Inc (subs of Getty Oil Co ) 84/07/31
  175pp 26105 070
- 8408170012 Forwards Rev 14 to physical safeguards plan,including updated drawings Rev withhold (ref 10CFR2 790) HENBLEY,K D. Nuclear Fuel Services, Inc. (subs of Getty Oil Co ) 84/03/29 BROWN,W B. Fuel Facility Safeguards Licensing Branck 24135 350
- 8408170392 Application for amend to License SNM-124, to include specific nuclear criticality safety controls on scrubber sys at 200 & 300 complexes, per NRC request IDEKCR, R L. Nuclear Fuel Bervices. Inc. (subs. of Getty Oil Co.) 84/03/30 PAGE, R G. Uranium Fuel Licensing Branch. 6pp. 26134 185
- --8408170393 Notifies of fee due for review of 840330 application for Amend 25 to License BNH-124 HEISS,D License Fee Management Branch 84/07/ 9 IDEKER,R Nuclear Fuel Services. Inc. (subs. of Getty Oil Co., ip
- --B40B170394 Notifies of fee due for review of B40B30 application to amend License SNM-124 NRC will recompute fee after review complete & make refund, if necessary WEIBS.D License Fee Management Branch 84/04/27 IDEKER.R L. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) ip 24134

- 8408280174 Respands to MRC 840503 ltr re violations noted in Insp Rept 70-0143/84-13 No proprietary info found GUINN.F K. Nuclear Evel Services. Inc. (subs. of Getty Dil Co.) 84/08/29 STDMR.J P. Division of Emergency Preparedness & Materials Safety ip 26274-300
- B408020154 Requests extension until 840704 for shutdown of process ventilation sys identified in B40611 ltr IDEXER,R t. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 84407/02 PAGE,R G. Uranium Fuel Licensing Branch. 3pp 25898-079
- 8408080393 Forwards findings & recommendations from 840618-2; site visit re review of upgraded physical protection program Massures suggested assential to provide required level of performance Comments requested within 30 days BROWN.W B Fuel Facility Sareguards Licensing Branch 84/07/17 HENSLEY.K Nuclear Fuel Services, Inc. (subs. of Getty Q11 Co.) ip 25978-082
- B408300284 Confirms arrangements made during B40716 telcon w/KP Barr re B40719 mgt meeting to discuss safeguards issues
  BTOHR, J.P. Region 2. Office of Director 84/07/17 GUNN,F K
  Nuclear Fuel Services, Inc. (subs. of Getty Gil Co.) 2pp
  26306-360
- 8408150545 Forwards Rev 65 to fundamental nuclear math control plan. Section 3 Rev withhold (ref 10CFR2 790 & 9 5) HENSLEY, K D. Nuclear Fuel Services, Inc. (subs of Getty Oil Co.) 84/07/25 D'REILLY, J P. Region 2, Office of Director 2pp 24080 304
- 8408280051 Ack receipt of 840710 ltr informing NRC of steps taken to correct violation noted in [nsp Rept 70-0143/84-18 STOHR, J P Region 2. Defice of Director 84/07/26 GUINN, F K Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.) 1p 26281 309
- --8408280053 Responds to NRC 840613 ltr re violation noted in Insp Rept 70-0143/84-18 Corrective actions withheld (ref 10CFR2 790) QUINN.F K Nuclear Fuel Services. Inc (subs of Getty Oll Co.) 84/07/10 STORR,P Division of Emergency Preparedness & Materials Safety ip 26281 310
- 8408280298 Ack receipt of 840711 ltr informing NRC of steps taken to correct violation moted in Insp Rept 70-0143/84-19
  Implementation of corrective actions will be examined during future insp
  8TOHR, J P Region 2: Office of Director 84/07/26 GUINN, F K Nuclear Fuel Services: Inc (subs of Getty Oil Co) lp
- --B408280297 Responds to NRC 840619 ltr re violation noted in Insp Rept 70-0143/84-19 Corrective actions seal inventory prepared for central seal storage area & defective seals storage area & defective seals discarded QUINN.F K Nuclear Fuel Services, Inc (subs of Getty Oil Co ) 84/07/11 SIGNR.F Division of Emergency Preparedness & Materials Safety 2pp 26281 312
- --8408280300 Forwards Insp Rept 70-0143/84-19 on 840529-0601 & notice of violation Notice of violation & insp rept withheld (ref IOCFR2 770 & IOCFR3 21)
  STOHR. J P Region 2. Office of Director 84/06/19 GUINN, F K Nuclear Fuel Services. Inc (subs of Cetty Oil Co.) 2pp
- 8408030029 Forwards IE Safeguards Insp Rept 70~0143/84-22 on 840611-0705 No violations or deviations observed STORM.J P Region 2. Office of Director B4/07/27 GUINN.F K Nuclear Fuel Services, Inc. (subs. of Getty Qil Co.) 2pp 25907 070
- --8408030033 IE Safeguards Insp Rept 70-0143/84-22 on 840411-0706 No violations or deviations noted Major areas inspected plant operations, nuclear criticality safety t radiation t environ protection Portion of details withheld (ref 10CFR2 790) LEE, T D . MCALPINE, E J Region 2. Office of Director 84/07/26 Spp 25907 072
- 840B300280 Confirms arrangements made during 840726 telcon re 840B08 mgt meeting to discuss safeguards issues STORH3 P Region 2. Office of Director 84/07/30 GUINN,F K Nuclear Fuel Services, Inc (subs of Getty 611 Co ) 19, RASJOA 302
- 8408270411 Ack receipt of 840718 ltr informing NRC of steps taken to correct violations noted in Insp Rept 70-0143/84-20 STOHR, J P Region 2. Office of Director 84/08/02 GUINN,F K Nuclear Fuel Services, Int (subs of Getty Qil Co ) 1p 26286 334

- --84082/0413 Responds to NRC 840619 ltr re violations noted in Insp Rept 70-0143/84-20 Corrective actions nail pattern modified to permit use of add! nails w/o splitting crate stud frame & cement nails implemented GUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) 84/07/18 Region 2. Office of Director 3pp 26256 335
- --8408270415 Forwards Insp Rept 70-0143/84-20 on 840529-0601 & notice of Violation STOMR, J P Region 2, Office of Director 84/06/19 GUINN, F K Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 2pp 26254 338
- --8408270421 Notice of violation from insp on 840929-0601 # Region 2. Office of Director 84/06/19 ip 26256 340
- ---8408270423 Insp Rept 70-0143/84-20 on 840529-0601 Violation noted failure to transport package of radioactive matl to burial site in strong, tight container WARY, J. R., VENNINS, G. R. Region 2. Office of Director 84/06/13 Apr. 26296 341
- B408160310 Forwards IE Saleguards Mgt Meeting Rept 70-0143/B4-28 on 840719 STDHR,J P Region 2. Office of Director 84/08/03 GUINN,F K Nuclear Fuel Services, Inc. (subs. of Getty Qil Co.). 2pp 24104 148
- --8408160317 IE Safeguards Mgt Meeting Rept 70-0143/84-28 on 840719 Major areas discussed improved safeguards control of maint & mod activities re matl access area barrier penetrations Details withheld (rof IOCFR95) TOBIN, M J , MCGUIRE, D R Region 2. Office of Director 84/08/02 ip 26106 147
- 840B140136 PNG-II-84-047 on 840806 licensus reported inventory difference from 840703 physical inventory Difference was accounting loss & within associated limit of error & other regulatory requirements State of TN informed MCALPINE: 6 J Region 2: Office of Director 84/08/07 ip 26084 321
- B40B130297 Ack receipt of check in amount of \$18.750 for payment of civil penalties proposed on B40809 Corrective actions will be examined during subsequent inspe AXELRAD.J A Director's Office Office of Inspection and Enforcement B4/0B/0B TAYLOR C W Nuclear Fuel Services, Inc (subs of Getty Dil Co ) ip 26040 353
- 8408130380 Ack receipt of 840723 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-0143/84-17 STORR, J P Region 2. Office of Director (84/08/09 QUINN,F K Nuclear Fuel Bervices, Inc. (subs of Getty Oil Co.) ip
- --8408130381 Responds to NRC 840622 itr re violations noted in IE Insp. Rept 70-0143/84-17 Corrective actions posting instructions reviewed w/administrative & secretarial personnel GUINN.F K. Nuclear Fuel Services. Inc. (Aubs. of Optty Oil Co.) 84/07/23 STOHR.J.P. Region 2. Office of Director 2pp 26010 169
- --8408130382 Forwards IE lnsp Rept 70-0143/84~17 on 840504-0608 & notice of violation Notice of violation & rept details withheld (ver 106FR2 790 & 73 21)
  STOHR.J P Region 2. Office of Director 84/06/22 GUINN.F K Nuclear Fuel Services. Inc. (subs. of Getty Dil Co.) 2pp 26010 172
- --B40Bl303B3 IE Insp Rept 70-0143/B4-17 on B40504-0608 Violation noted failure to post notice of violation re radiological working conditions & groposed imposition of civil penalty & response to NRC betails withheld (ref IOCR2 790 & 73 21)
  LEE, T D , MCALPINE, E J Region 2, Defice of Director 84/06/22
  1p 26010 174
- 9408270420 Forwards Bafeguards Insp Rept 70-0143/84-27 on 840723-27 Renorcompliance noted
  STORR.J P Region 2. Office of Director 84/08/09 QUINN.F K
  Nuclear Fuel Services. Inc (subs of Getty Oil Co ) 2pp
  26238 243
- --B40B270427 Bafeguards insp Rept 70-0143/84-27 on B40723-27 No violations or deviations noted Major areas inspected measurements, measurement verification, internal controls & physical inventory Details withheld (ref 10CFR2 790) BATES, J W , TODD. O A , MCALPINE, E J Region 2, Office of Director 84/08/07 1p 26258 245

- B40B230055 Submits items of interest re Whittaker Corp. Greenville, PA, EIAs & Kerr-McGee - Oklahoma PAGE, RG Uranium Fuel Licensing Branch 84/08/16 DAVIS, JG Office of Nuclear Material Safety & Safeguards, Director 2pp
- 8408280034 Submits review schedule for application to renew License SNM-124 Comments & recommendations re scheduled insp dates requested CROW. W T Uranium Fuel Licensing Branch 84/08/17 BARR, K.P. Region 2, Office of Director ip 26274 137
- B408230281 Atv receipt of 840527 ltr transmitting Rev &1 to fundamental nuclear matl control plan & forwards proprietary changes to plan Changes withheld (ref 10GFR2 790)
  STOHRJ P Region 2. Office of Director B4/08/20 QUINN,F K
  Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 2pp
- B40B290351 Forwards environ assessment schedules for Westinghouse & NFB license renewals Site visits tentatively scheduled on B40919 for Westinghouse & B41024 for NFS W/o encl HYNOGROEN, S D Uranium Fuel Licensing Branch B4/0B/22 MCLEAN, R Dak Ridge National Laboratory 19 26310 362
- B408280189 Forwards Mgt Meeting Rept 70-0143/84-32 on B40808-09 Meeting provided better understanding of NRC policy as found in Bafeguards License Guidance Group Bulletin 38 BTDMR.J P Region 2. Office of Director B4/08/23 GUINN.F K Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.) 2pp 2229-203
- --8408280192 Mgt Meeting 70-143/84-32 on 840808-09 Items discussed NRC policy as found in Safeguards License Bulletin 38 & procedures re matl access area barrier penetrations Details withheld (ref ioCFR95)
  TOBIN.W. MCQUIRE.D R Region 2, Office of Director 84/08/22
  ip 26279 205

## DOCKET 70-0221 GENERAL DYNAMICS CORP , GROTON, CT

- 8408310320 Ack receipt of 840207 itr informing NRC of steps taken to correct violations noted in Insp Repts 30-03772/83-01 & 70-0221/83-01 Natice of violation justified Corrective actions due in 20 days
  MARTIN.T T Division of Engineering & Technical Programs 84/08/13
  TOVAR, F G General Dynamics Corp 2p 24333 300
- DOCKET 70-0303 CARNEGIE-MELLON UNIV , PITTSBURGH, PA
- 8408210189 Discusses IE insp of Licenses 37-00602-03 & 8NM-281 on 840523-25 & forwards notice of violation Civil penalty not issued since corrective action prompt & extensive MURLEY,T E Region 1. Office of Director 84/07/25 ROOERS,F Carnegic-Mellon Univ , Pittsburgh, PA 3pp 26184 221
- --8408210176 Notice of violation from insp on 840523-25 Violations noted failure to adequately control access to rooms containing radioactive matl & failure of radiation safety committee to meet quarterly during 1983 MURLEY.T E Region 1. Office of Director 84/07/25 4pp 2648 224

#### DOCKET 70-0364 BABCOCK & WILCOX CD , APOLLO, PA

- B40B010020 Forwards administrative amend fee for B40608 revs to Chapter XIII, "Environ Monitoring Program" of License SNM-414 AUBTIN,M A Babcock & Wilcox Co B4/06/25 ELASSER,T C Region 1, Office of Director 1p 28866 361
- 8408040439 Summary of 840712 meeting w/B&W re plan for mod of existing Parks Township site facility for refurbishment of PWR control rod guide tubes Vendor will submit application to amend License SMM-414 LOYSCN.P Advanced Fuel & Spant Fuel Licensing Branch 19 28937 313
- 8408080443 Ack receipt of 840608 ltr re changes to environ monitoring program No license amend required Submittal meets requirements of License Condition 25 Amend fee will be returned Revised pages to environ monitoring program encl GREENMAN.E O Division of Project & Resident Programs 84/07/31 AUSTIN.M A Babcock & Wilcox Co 10pp 25977 164

- 8408150667 Application for amend to License SNM-414.increasing possession limit to 1.000 Ci isotopes in Condition 8 H 2 & 5.000 Ci in Condition 8 H 4 AUSTIN.M A Babcock & Wilcox Co 84/08/03 MCCABE.E C Region 1. Office of Director 50pp 26103 309
- 8408220427 Discusses B&W request to amend License SNM-414 to increase mat1 possession limits Application meets criteria of 10CFR51 22(c)(ti) for categorical exclusion & no environ assessment required CUNNINGHAM.R E Division of Fuel Cycle & Material Safety 84/08/17 STAROSTECKI,R Division of Project & Resident Programs 3pp 24209 350

#### DOCKET 70-0371 UNC NAVAL PRODUCTS: INC . UNCASVILLE, CT

- 8408300134 "Effluent Monitoring Rept. Jan-June 1984 " W/840817 ltr KIRK, W F United Nuclear Corp 84/06/30 MURLEY, T E Region 1. Office of Director 2pp 26307 317
- B40B0B0324 Responds to B40601 comments on NRC 840503 regulatory effectiveness review rept Response on each item withheld (ref 10CFR2 770) Comments by B4082B requested BROWN, W B Fuel Facility Safeguards Licensing Branch 84/07/13 AMY, G O United Nuclear Corp 1p 25978 204
- 8408150398 Forwards IE Safeguards Insp Rept 70-0371/84-07 on 840618-22 No violations observed MARTIN.T T Division of Engineering & Technical Programs 84/07/27 AMY.G O United Nuclear Corp 2pp 26077 331
- --8408150407 IE Safeguards Insp Rept 70-037i/84-07 on 840418-22 No noncompliance noted Major areas inspected measurement controls inventory difference & associated limit of error varification & records & repts SMITH.G C . DELLA RATIA,A . KEIMIG.R R Region i. Office of Director 84/07/26 3pp 26077 333
- B40B030146 Responds to 840717 ltr requesting copy of closeout rept on United Nuclear Corp bldg in New Haven.CT Survey results indicate max identified fixed contamination level less than 25% of allowable limit STAROSTECKI.R Division of Project & Resident Programs 84/07/31 HOUSMAN,J J HAP Associates 3pp 25915 328
- --8408030147 Forwards IE Insp Rept 70-0371/76-06 on 760308-10 No noncompliance noted NELSDN,P R Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 76/04/02 GAISE.G D United Nuclear Corp 3pp 20915 330
- --840B03014B IE Insp Rept 70-0371/76-06 on 76030B-10 No noncompliance noted Major areas inspected licensee final survey rept after decontamination of H-tract facility PLUMLEE,K E, KNAPP,P J Region 1. Philadelphia, Office of the Director 76/04/02 6pp 25915 333
- 8408230055 Submits items of interest re Whittaker Corp.Oreenville.PA. EIAs & Kerr-McGee - Oklahoma PAGE.R O Uranium Fuel Licensing Branch 84/08/16 DAVIS.J O Office of Nuclear Material Safety & Safeguards.Director 2pp 26233 288

### DOCKET 70-0398 COMMERCE, DEPT OF WASHINGTON, DC

- 840B230095 Submits items of interest re Whittaker Corp,Greenville,PA, EIAs & Kerr-McGee - Oklahoma PAGE.R G Uwantum Fuel Licensing Branch 84/08/16 DAVIS,J G Office of Nuclear Material Safety & Safeguards,Director 2pp 2A
- DUCKET 70-0466 MAINE MARITIME ACADEMY, CASTINE, ME
- 8408010397 Discusses IE insp of Licenses SNM-493 & SUD-283 on 840614 & forwards notice of violation MARTIN:T T Region 1. Office of Director 84/07/19 CUKIERSKI,M W Maine Maritime Academy, Castine, ME 2pp 25866,053
- --8408010400 Notice of violation from insp on 840614, Violation noted yearly calibr of survey meters undocumented, monthly exchange of film badges not performed & sealed sources not tested for leakage \* Region 1. Office of Director 84/07/19 1p 25866 055.

- DOCKET 70-0487 UNION CARRIDE CORP TOXEDO, NY
- B408090856 Forwards SNM-637 license submittal & updated pages, per 840713 telcon Updates address license conditions, safety demonstration & leak testing guidelines Annual rept also eng! MCGGVERN, J. Union Carbide Corp. 84/07/16 ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. 243pp. 25988-082
- 8408180247 Forwards info re License SNH-639 submittal.per 840713
- telcon MCGOVERN, J.J. Union Carbide Corp. 84/07/16 ROUSE, L.C. Division of Fuel Cycle & Material Safety 245pp 26103 001
- 8408270510 Forwards Insp Repts 30-054/84-02 & 70-0687/84-02 on 840709-11 No violations observed STAROSTERKIR Division of Project & Resident Programs 84/08/07 MCG0VERN.J J Union Carbide Corp 2pp 26256 162 24X Fichs 50-054,84/08/01.8408270510
- --B408270518 insp Repts 50-054/84-02 & 70-0687/84-02 on 840709-11 No deviations of violations identified Major areas inspected organization, facility changes & mods, safety committees, nuclear criticality safety & radiation protection ROTH, J Region to Office of Director ELBASSER, T C Division o Project & Resident Programs 84/08/02 App 26256 164 24X Fiche 50-054,84/08/07.8408270510
- DOCKET 70-0734 GA TECHNOLOGIES, INC. BAN DIEGO. CA
- BAQB020253 Forwards Rev 4 to "Part II Specs Vol.SNM-696 Matl License Renawal," in response to NRC questions MUMRY.W R GA Tachnologies, Inc /General Atomic Co 84/06/28 CROW.W T Office of Nuclear Material Safety & Safeguards, Director Ip 25898 112
- --8408020256 Rev 4 to "Part II Specs Vol.SNM-696 Matl License Renewal "

  \* GA Technologies, Inc /General Atomic Co 84/06/30 Spp
  25898 113
- BAOBOBOA25 Requests comments on encl review of commitments of upgraded Category I physical protection plan Response requested in 30 days Encl withheld BIRDINN B Fuel Facility Safeguards Licensing Branch BA/07/14, MOMRY.R GA Technologies, Inc./General Atomic Co ip 25977 190
- 8408080147 Forwards IE Insp Rept 70-0734/84~07 on 840604~08 No violations noted WENSLAMBKI.F A Region 5, Office of Director 84/07/18 COLANDREA.T R GA Technologies. Inc /General Atomic Co 26p 25974 314
- --B4080B0151 IE Insp Rept 70-0734/84-07 on B40604-08 No violations noted Major areas inspected organization facility changes & mods, internal review & audit, radiation protection, training & emergency planning BROCK, B t. ZURAKOMSKI, P R , THOMAS, R D Region 5, Office of Director 84/07/13 11pp 25974-316
- 8408080371 Notifies that License Condition 9 i C to License SNM-696 re safeguards contingency plan.corrected to read License Condition 9 I B BROWN.W B Fuel Facility Safeguards Licensing Branch 84/07/23 MOURY.W R QA Technologies, Inc /General Atomic Co 1p 25976\*083
- 8408230216 Forwards IE Bafeguards Insp Rept 70-0734/84-09 on 840716-20 & 31 & notice of violation Encls withheld (ref 10CFR73 21) 8CHUBIER: M D Region 5. Office of Director 84/08/17 COLANDREA: T R GA Technologies. Inc /General Atomic Co 2pp
- B408270337 Forwards Bafeguards Insp Rept 70-0734/84-08 on 840709-13 & 19-27 No violations noted SCHUBTER.M D Region 5. Office of Director B4/08/21 COLANDREA, T R GA Technologies. Inc /General Atomic Co 2pp 26288 148
- --BA08270346 Safeguards Insp Rept 70-0734/84-08 on 840709-27 No violations noted Major areas inspected physical inventory, inventory verification & records & repts Details withheld (ref 100FR2 790)
  NELBUN 0 B , WIEDER A V , HAMADA 0 H Region 5, Office of Director 84/09/17 1p 26238 150

- 8408270311 Forwards ltrs documenting cooperation w/local law anforcement agencies & medical facilities re radiological contingency plan MOWRY.W R GA Technologies, Inc /General Atomic Co 84/08/22 LUNNINGHAM.R Division of Fuel Cycle & Material Safety THOMAS.C O Standardistion & Special Projects Branch App 26241 004 24% Fiche 80-089.84/08/22.8408270311
- DOCKET 70-0820 UNITED NUCLEAR CORP , WOOD RIVER JUNCTION, RI
- 8408010024 Forwards final survey data sheets for third floor columns room ceiling for insertion in final survey rept HELGESON.K A United Nuclear Corp 84/06/27 CROW,W T Division of Fuel Cycle & Material Safety 7pp 25897 098
- 8408020096 Forwards revised discussion page to replace existing page in final survey repticovering ceiling of third floor columns room Page located in Vol II. Section I. Subsection 3 4 1 HELGEBONK A United Nuclear Corp 84/07/05 CROW, W T Office of Nuclear Material Safety & Safeguards Director 3pp 25898 107
- DOCKET 70-0824 BABCOCK & WILCOX CO , LYNCHBURG, VA
- --8408300194 Respands to NRC 840808 ltr re violations noted in Insp Rept 70-0824/84-01 Corrective actions support brackets on drum gripper modified to remove sharp corners & all fork truck operators in waste shipment loading will be trained ENGLDER: T C Babcock & Wilcox Co 84/06/06 STDHR: J P Region 2. Office of Director 4pp 26308 002
- --8408300200 Forwards Insp Rept 70-0824/84-01 to 840418-19 & notice of violation SIDHR.J P Region 2, Office of Director 84/05/08 ENGELDER.Y C Babcock & Wilcox Co 2pp 24308 006
- ---8408300202 Notice of Violation from insp on 840418-19
  \* Region 2, Office of Director 84/05/08 2pp 26308 008
- --B40B300206 Insp Rept 70-0824/84-01 on 840418-19 Violations noted unauthorized transfer of radioactive math, failure to label radwaste package & failure to meet BOT requirements for shipment of radioactive math ALIRIOHT,R H., JENKINB, G.R. Region 2, Office of Director 84/05/07 4pp 26308 010
- B408020203 Application for Amend 7 to License SNM-778 revising Section A 9 4 1 to permit postings other than caution radiation area signs where appropriate Fee onci CLSEN.AF Babecock & Wilcox Co 84/06/20 PAGE.R G Uranium Fuel Licensing Branch App 25898 179
- DOCKET 70-0929 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK
- 8408300322 "Radipactivity in Gaseous Effluents & Particulates Elevated & Total Release, No Batch Mode, Jan-June 1984 " W/840821 ltr 81NKE G J Kerr-McGee Corp 84/06/30 3pp 26308 329
- DOCKET 70-0938 MASSACHUSETTS INSTITUTE OF TECHNOLOGY, CAMBRIDGE, MA
- 840B130205 Forwards Rev 1 to 820728 application for renewal of License SMM-985. Rev Includes responses to NRC comments received on B30301 re renewal application CLARK, L. Massachusetts Institute of Technology, Cambridge, MA 84/07/13 PAGE, R & Uranium Fuel Licensing Branch 2pp 24040 053
- ---B40B130212 Rev 1 to 820728 application for renewal of License SNM-985, authorizing possession of listed licensed matl CLARK, L. POWELL, P.C. Massachusetts Institute of Technology, Cambridge, MA 84/07/13, 110pp 26060 056
- 8408280351 Requests review & comments on 840713 application for renewal of License BNM-986 Review schedule listed CROWLW T Uranium Fuel Licensing Branch 84/08/17 WENZINGER,E. Region 1, Office of Director 1p 26292 364

- DOCKET 70-0984 BATTELLE PHORIAL INSTITUTE RICHLAND, WA
- B408090120 Forwards IE Insp Rept 70-0984/84-03 on 840620 No noncompliance noted WENSLAMSKI.F A Region 5. Office of Director 84/07/23 SIMPBON.C L Battelle Hemoria) Institute, Pacific Northwest Laboratories 2pp 25992 245
- --8408070122 IE Insp Rept 70-0984/84-03 on 840620 No violations noted Major areas inspected emergency planning (fire prevention & protection test & drills, facilities, equipment & procedures) & radiation protection BRCCK, B L. THOMAS, R D Region 5, Office of Director 84/07/23 4pp 25992 247

### DUCKET 70-1048 FLORIDA, UNIV OF, GAINESVILLE, FL

- B40B130261 Application to renew Litense SNM-1050, extending expiration date to B50930 DIAZ,N J Florida, Univ of, Gainesville, FL 84/07/19 PAGE,R G Uranium Fuel Licensing Branch 3pp 26040 331
- DOCKET 70-1113 GENERAL ELECTRIC CO , WILMINGTON, NO
- 8405300764 Responds to 840406 telcon Internal & external radiation exposure data encl
  VAUGHAN.C M General Electric Co 84/04/11 SDUNG.A L NRC No Detailed Affiliation Given 2pp 24732 317
- --8405300762 Personnel monitoring of total wholebody exposure for 1982 VAUGHAN, C.M. General Electric Co. 82/12/31 Office of Management and Program Analysis 2pp. 24732 319
- ~~8405300763 Personnel monitoring of total wholebody exposure for 1981 VAUGHAN.C M General Electric Co 81/12/31 Office of Management and Program Analysis (ipp 24732 321
- 8408280111 Ack receipt of NRC 840712 ltr re results of Insp Rept 70-1113/84-07 on 840618-21 Rept contains no proprietary info VAUGHAN.C M General Electric Co 84/07/17 STOHR.J P Region 2, Office of Director ip 26261 112
- ~-8408280118 Forwards Insp Rept 70-1113/84~07 on 840618-21 No violations or deviations identified STOHR.JP Region 2. Office of Director 84/07/12 LONG.JA General Electric Co 2pp 26261 113
- --8408280123 Insp Ropt 70-1113/84-07 on 840618-21 No violations or deviations identified Hajor areas inspected radwaste mgt & environ monitoring STODDART,P G., MUNTGDMERY.D M. Region 2, Office of Director 84/07/09 10pp 26261 115
- 8408270534 Forwards Insp Rept 70-1113/84-10 on 840709-13 No violations or deviations identified 8TUHR, J P Region 4: Office of Director 84/07/27 LONG, J A Ceneral Electric Co 2pp 26256 129
- --8408270540 Insp Rept 70-1113/84-10 on 840709-13 No viplations or deviations noted Major areas inspected maint, training, nuclear criticality safety,Part 21 operations review, procedures control & independent effort KAHLE.J B , MCALPINE.E J Region 2, Office of Director 84/07/25 5pp 26256 131
- 8408280362 Forwards Insp Rept 70-1113/84-09 on 840716-20 No noncompliance noted STORK, J P Region 2. Office of Director 84/09/09 LONG, J A General Electric Co 2pp 26281 316
- --8408280367 Insp Rept 70-1113/84-09 on 840716-20 No noncompliance noted Major areas inspected measurement & statistical controls, organization & physical inventory preparations Details withheld (ref 10CFR2 790) CLAY, E. L., MCALPINE, E. J. Region 2. Office of Director 84/08/08 1p 26281 318
- B40Bi40199 Ack receipt of 840214 & 0321 revs to fundamental nuclear mat1 control plan Portions of plan described in enc1 not consistent w/10CFR70 32(c) Enc1 list of inconsistent changes withheld (ref 10CFR2 790)

  STOHR, J P Region 2. Office of Director 84/08/10 LONG, J A General Electric Co 2pp 26042 361

- DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA
- 8406260175 Forwards IE Insp Rept 70-1143/84-02 on 840507-12 No violations noted STAROBJECKI.R Division of Project & Resident Programs 84/06/06 SLEMBER.R Westinghouse Electric Corp 2pp 25164 343
- --8406260179 IE Insp Rept 70-1143/84-02 on 840507-12 No violations noted Major areas inspected confirmatory survey of licenses decommissioned site located at Cheswick PA ROTH, J. ELSASSER, T. C. Region 1. Defice of Director 84/06/05 7pp 25164 345
- --B4062601B4 "Guidelines for Decontamination of Facilities & Equipment Prior to Release for Unrestricted Use of Termination of Licenses for Bygroduct. Source or SNM "

  \* Division of Fuel Cycle & Material Safety 76/11/30 7pp 25144 352
- DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP . PITTSBURGH. PA
- 8408310254 Forwards Insp Rept 70-1151/B4-07 on 840514-18 No noncompliance noted STCHR.J P Region 2. Office of Director 84/05/31 BRITTON, W H Hestinghouse Electric Corp 2pp 26335 169
- --8408310255 Inap Rept 70-1151/84-07 on 840514-18 No noncompliance noted Major areas inspected physical inventory observation Details withheld (ref 10CFR2 790 & 73 21)
  TIDD.O A . JONES,D W . BATES,J W Region 2, Office of Director 84/05/30 ip 26335 171
- 8408280148 Ack receipt of 840531 ltr re Safeguards Insp Rept 70-1151/84-07 on 840514-18 SANDERS,CF Wastinghouse Electric Corp 84/06/13 O'REILLY,JP Region 2. Office of Director 19 26267 357
- 8408010040 Requests limited exemption to regulations & fundamental nuclear matl control plan Request described in App A to ltr Fee encl App A withheld NARDI.A J Hestinghouse Electric Corp 84/06/28 BRDMN.H D Fuel Facility Safeguards Licensing Branch 1p 25866 349
- B408160352 Application for amend to License SNM-1107, changing license condition to nuclear mat) control plan, per encl App A Fee encl App A withheld (ref 10CFR2 7790)

  NARDIA J Westinghouse Electric Corp 84/07/12 BROWN, W B Fuel Facility Safeguards Licensing Branch 1p 26126 247
- 840B160064 Responds to 840628 ltr requesting limited exception to requirements of 10CFR70 58(e) Unnumbered license condition to Amond 89-1 issued BROWN, W B Fuel Facility Safeguards Licensing Branch 84/07/16 BANDERS, C F Westinghouse Electric Corp 2pp 26126 354
- 84080803B6 Approves 840712 request for mod to unnumbered license condition issued on 840527 for License SNM-1107 BROWN.W D Fuel Facility Safeguards Licensing Branch 84/07/23 BANDERB.C F Westinghouse Electric Corp ip 25978 084
- B408150583 Forwards Rev 4 to Columbia site emergency plan Rev effective B40430 FISCHER.R E Wastinghouse Electric Corp 84/07/24 Division of Fuel Cycle & Material Safety 2pp 26106 001
- --B4081505B9 Rev 4 to Columbia sits emergency plan \* Westinghouse Electric Corp 84/04/30 22pp 26106 003
- 8408270222 Forwards Insp Rept 70-1151/84-09 on 840723-27 No violations or deviations identified STDHR, J P Region 2: Office of Director 84/08/09 D'AMORE, M Westinghouse Electric Corp 2pp 24258 232
- --8408270225 Insp Rept 70-1151/84-07 on 840723-27 No violations or deviations identified Major areas inspected statistical controls associated w/nuclear matl control & accounting measurements Details withheld (ref 10CFR2 790) JUNES D W. MCALPINE, E J Region 2, Office of Director 84/08/08 ip 26258 234
- 8408230055 Submits items of interest re Whittaker Corp. Greenville, PA. EIAs & Kerr-McGee - Oklahoma PAGE.R G Uranium Fuel Licensing Branch B4/08/16 DAVIS. J G Office of Nuclear Material Safety & Safeguards, Director. 2pg

- 8408270360 Effluent monitoring rept for Jan-June 1984 GDDDMIN W.L. Westinghouse Electric Corp. 84/08/17 Director's Office, Office of Inspection and Enforcement 1p. 26295-353
- 8408290351 Forwards environ assessment schedules for Westinghouse & NFS license renewals Site visits tentatively scheduled on 840917 for Westinghouse & 841024 for NFS W/o encl HYNOARDEN.S D Uranium Fuel Licensing Branch 84/08/22 MCLEAN.R Cak Ridge National Laboratory 1p 26310 362
- DOCKET 70-1193 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK
- 8408300322 "Radioactivity in Gaseous Effluents & Particulates Elevated & Total Release.No Batch Mode, Jan-June 1984 " W/840821 ltr SINKE.G J Kerr-McGee Corp 84/06/30 3pp 26308 329
- DOCYET 70-1201 BABCOCK & WILCOX CO , LYNCHBURG, VA
- 8408300296 Forwards Insp Rept 70-1201/84-04 on 840521-22 No violations or deviations noted STOHR.J P Region 2. Office of Director 84/06/06 ALTO.R A Babcot & Wilcox Co 2pp 26306 347
- --8408300307 Insp Rept 70-1201/84-04 on 840521-22 No violations or deviations noted Major areas inspected nuclear criticality safety, operations review, 10cFR21, safety committees, facility changes & mods.training & internal audits KAHLE, JB , MCALPINE,E J Region 2, Diffice of Director 84/06/06 4pp 26306 349
- B4082B0090 Ack receipt of B40618 & 0/25 ltrs informing NRC of steps taken to correct violation noted in Insp. Rept 70-1201/84-02 STOHR, J P Region 2. Office of Director B4/0B/03 ALTO,R A Babcock & Wilcox Co ip 262B2 225
- --8408280270 Responds to NRC 840529 ltr re violation noted in Insp Rept 70-1201/84-02 Corrective actions revised pages of License SMM-1168 reflecting organizational changes submitted on 840504 for approval ZEFF.D W Babcock & Hilcor Co 84/06/18 STOHR.J P Region 2. Office of Director 3pp 26282 226
- --8408280277 Supplemental response to violations noted in Insp Rept 70-1201/84-02 Corrective actions health & safety reporting chain restructured to report to regulatory control mgt ZEFF.D W Babcock & Wilcox Co 84/07/25 STOHR.J P Region 2. Office of Director 2pp 26282 229
- --8408280282 Forwards Insp Rept 70-1201/84-02 on 840417-20 & notice of violation BTOHR, J.P. Region 2, Office of Director 84/05/23 ALTO,R A Babcock & Wilcox Co. 2pp. 26282 231
- --8408280285 Notice of violation from insp on 840417-20 \* Region 2. Office of Director 84/05/23 ip 26282 233
- --B408280289 Insp Rept 70-1201/84-02 on B40417-20 Violation noted reorganization implemented w/o license condition change ALBRIGHT.R H. JENKINS, C R. Region 2, Office of Director B4/05/23 Spp 26282 234
  - KET 70-1257 EXXON NUCLEAR CO , INC , RICHLAND, WA
  - BOB0435 Approves 840712 request to download 10 encapsulated fuel ods containing up to 600 g U-235 BROWN. W B Fuel Facility Safeguards Licensing Branch 84/07/16 SCHNEIDER:R A Exton Nuclear Co , Inc (subs of Exxon Corp ) 1
- IOBI30502 Forwards IE Insp Rept 70-1257/84-05 on 840618-22 & notice of violation SCARAND.R A Division of Radiological Safety & Safeguards Program 84/07/27 NILSON.R Exxon Nuclear Co , Inc (subs of Exxon Corp ) 200 26032 340
- -8408130507 Notice of violation from insp on 840618-22 THOMAS.R D Region 5. Office of Director 84/07/27 2pp 26032 342
- --8408130511 IE Insp Rept 70-1257/84-05 on 840618-22 Violations identified containers not labeled w/mass & enrichment of content & continuous fissile inventory sheet not maintained dROCK, B L , ZURAKOMSKI.P R , THOMAS, R D Region 5, Office of Director 84/07/20 9pp 26032 344

- 8408080273 Forwards IE Reactive Safeguards Insp Rept 70-1257/84-06 on 840627-29 No violations noted Rept withheld (ref 10CFR2 790)
  SCHUBTER, M.) Region 5. Diffice of Director 84/08/02 NILSON, R
  Exton Nuclear Co., Inc. (subs. of Exton Corp.) 1p. 25966 079
- Exign Nuclear Co , Inc. (subs. of Exion Corp.) 1p. 25966-079
- 8408220340 Forwards proprietary IE Safeguards Insp Rept 70-1257/84-07 on 840801-03 No violations noted Rept withheld (ref 10CFR2 790) SCHUSTER.M D Region 5. Office of Director 84/08/16 NILSON, R Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 2pp 26191 395
- 8408300007 Ack receipt of 840314 1tr transmitting Rev 6 to physical protection plan for matl of low strategic significance Changes acceptable Rev withheld (ref 10CFR2 770) SCHUBTER. M D Safeguards & Materials Program Branch 84/08/22 SCHNEIDER. R A Exxon Nuclear Co , Inc (subs of Exxon Corp ) in 12031
- DDCXET 70~1308 GENERAL ELECTRIC CO , SAN JOSE, CA
- 8408130033 Responds to 840711 request for clarification of items identified during review of new rev to consolidated EAR. NEDO-21326 D Revised pages encl HERRINGION.C C General Electric Co 84/07/24 CUNNINGHAM.R E Division of Fuel Cycle & Material Safety 15pp 26058 330
- 8408130570 Summary of 840726 meeting w/GE in Silver Spring, MD re GE response to comments on update of consolidated SAR for Morris Operation
  ROBERTS, J. P. Advanced Fuel & Spent Fuel Licensing Branch ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch 1p. 26038-313
- B40B160461 Dockets Rev 7 to NEDO-20776. "Spent Fuel Sycs Operation & GE U Mgt Corp QA Plan." u/WC Wheadon & DM Dawson 830329 & 0210 ltrs.respectively.to assure docket file complete due to rev & resubmittal of rept as Rev B ROBERTS.JP Advanced Fuel & Spent Fuel Licensing Branch B4/08/14 Advanced Fuel & Spent Fuel Licensing Branch ip 26126 078
- --8408160466 Forwards Rev 7 to NEOD-20776, "Spent Fuel Svcs Operation & GE U Mgt Corp GA Plan " Rev due to organizational change within spent fuel svcs operation & GE U Mgt Corp HHEADON, W C General Electric Co 83/03/29 ROBERTS, J P NRC No Detailed Affiliation Given Ip 26126 079
- ---8408160472 Forwards Rev 7 to NEDO-20776, "Spent Fuel Svcs Operation & GE U Mgt Corp GA Plan," referenced in License SNM-2500 for GE Morris Operation & incorporated in NEDO-21326, App B-B DAMSON, D M General Electric Co 83/02/10 ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 1p 26126 080
- 8408310268 PNO-III-84-067 first of several spent reactor fuel shipments from Cooper Station arrived safely Rail shipment consisted of three NRC-centified shipping casks, each containing i8 spent fuel assemblies LOVENDALE, P., PAPERIEI LD, C.J. Region 3, Office of Director 84/08/24 ip 26333 329
- DOCKET 70-1342 CORATOMIC, INC , INDIANA, PA
- B40B310061 Insp Findings & Licensee Ack on 840B17 of License 8NM-1317
  Insp findings no violations observed Steps taken to
  correct violations identified during last insp verified
  LUDUN,R H Region i. Office of Director 8470B/17 ip 26334 23B
- DOCKET 70-1362 HAHNEMANN MEDICAL COLLEGE & HOSP , PHILADELPHIA, PA
- 8408060373 Ack receipt of 840207 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-1362/83-01 & 30-02997/83-01 Addl info requested within 30 days MARTIN, T T Division of Engineering & Technical Programs 84/07/10 MILLS, L C Hahnemann Univ Hosp, Philadelphia, PA (formerly Hahnemann Medical Coll & Hosp) 3pp 25736 100
- --B408060378 Forwards response to NRC 831223 ltr re violations noted in IE Insp Repts 70-1362/83-01 & 30-02757/83-01 MILLS.L C Hahnemann Univ Hosp Philadelphia, PA (formerly Hahnemann Medical Coll & Hosp) B4/02/07 MARTIN, T T Division of Engineering & Technical Programs 1p 25936 103

--2498060382 Responds to MRC B31223 ltr re violations noted in IE Insp Repts 70-1362/B3-01 & 30-02959/B3-01 Corrective actions security guards posted at all street entrances to bing & members of housekeeping staff attended training sessions DAY, J Hahnenann Univ Mosp. Philadelphia. PA (formerly Hahnemann Medical Coll & Hosp) 84/01/30 MARTIN.T T Division of Engineering & Technical Programs 27pp 25936 104

DOCKET 70-1450 BERKSHIRE MEDICAL CENTER, PITTSFIELD, MA

8408230183 Ack receipt of 840417 ltr informing NRC of steps taken to correct violations noted in IE insp of Licenses 20-12009-01. 20-02009-03 & SNM-1439 on 840213 MARTIN.T T Division of Engineering & Technical Programs 84/08/15 PRYER.K Berkshire Medical Center, Pittsfield, MA 1p 26209 273

--B408230196 Responds to NRC B40321 ltr re violations nated in IE insp of Licenses 20-12009-01, 20-12009-03 & SNM-1439 on B40213 Corrective actions thyroid monitoring required 3 days after administration of radiolodine WU, R. R. Berkshire Medical Center, Pittsfield, MA B4/04/17 MARTIN, T. T. Division of Engineering & Technical Programs 2pp 24209 274

DOCKET 70-1941 PASSAIC GENERAL HOSP , PASSAIC, NJ

8408100041 Discusses JE insp of Licenses SNM-1525 & 27-01040-01 & forwards notice of violation MARTIN.T J Division of Engineering & Technical Programs 84/08/07 KORNETT, M Passaic General Hosp , Passaic, NJ 2pp 25970 057

--840810005; Notice of violation from insp on 840718 Violation noted no security personnel received training in radiation safety procedures & surveys of hands, feet & clothing not monitored by personnel before leaving area \* Region I, Office of Director 84/08/07 ip 25970 059

DOCKET 70-2377 DENTSPLY INTERNATIONAL, INC , YORK, PA

8408060084 IE Insp Findings & Licensee Ack dtd 840718 of License SNM-1669 Insp findings records of sealed source leak tests not properly maintained & NRC-3 form not posted MCFADDEN J Region 1: Office of Director 84/07/18 ip 25935 284

DOCKET 70-2571 YALE-NEW HAVEN HOSP , NEW HAVEN, CT

84083i0i40 Discusses insp of Licenses SNM-1734 & 06-00819-03 on B40605 & 21 & forwards notice of violation MARTIN.T T Division of Engineering & Technical Programs B4/08/2: MCINTYRC,D Vale-New Haven Hosp. New Haven, CT 2pp 26322 203

--8408310144 Notice of violation from insp on 840605 \$ 21 Violation noted individual working in restricted areas received whole body radiation dose of 1 39 rems during fourth calendar quarter of 1983 \* Region 1, Office of Director 84/08/22 3pp 26322 205

DOCKET 70-2838 CINCINNATI GAS & ELECTRIC CO . CINCINNATI, OH

8408210491 Forwards proprietary IE Safeguards Matl Control & Accountability Insp Rept 70-2838/84-06 on 840731 No noncompliance noted Rept withheld (ref 10CFR2 770 & 73 21) AXELSON,W L. Region 3, Office of Director 84/08/16 SCHOTT,J R Cincinnati Gas & Electric Co. 2pp 26177 231

DOCKET 70-2872 RS HOLDING, INC , CLEVELAND, OH

840B1301B0 Ack receipt of enc1 B40727 ltr informing NRC of steps taken to correct noncompliance mated in IE Insp Repts 70-2872/84-01 & 70-2872/84-02 Enc1 withheld (ref 10CFR2 790)
AXELBUN, W. L. Region 3, Office of Director 84/08/08 PALKO.9 Reuter-Stokes, Inc. 1p. 26006-334

DOCKET 70-2884 LONG ISLAND LIGHTING CO . HICKSVILLE. NY

B40B070259 Advises of issuance of Amend 2 to License SNM-1837.extending expiration date to 85:231 or upon conversion of CPPR-95 to DL. per 840417 application All other conditions of license remain unchanged SER encl PAGE.R G Uranium Fuel Licensing Branch 84/07/31 Long Island Lighting Co 1 p 28957 034

B40B070266 SER supporting issuance of amond to License SNM-1857, extending expiration date to 851231 or upon conversion of CPPR-95 to OL KETZLACH, N Uranium Fuel Licensing Branch 84/07/31 ip 33957.035

DOCKET 70-2988 PHILADECPHIA ELECTRIC CO . PHILADELPHIA: PA

8408050368 Issues Amend 1 to License SNN-1926 Amend authorizes using Pu-239, depleted U & Th-230, revises License Conditions 17 rephysical security & adds License Conditions 17 & 18 Safety evaluation encl PAGE.R G Uranium Fuel Licensing Branch B4/07/27 BAUER.E G Philadelphia Electric Co 3pp 25951 007

--8408060371 SER supporting Amend 1 to License SNM-1926 SERINI.B L Uranium Fuel Licensing Branch 84/07/27 9pl 25951 010

--8408060375 Grants categorical exclusion from EIA/EIS re 840607 request to receive & use Pu-237, deplated U & Th-230 as plated calibr sources PAGE:R G Uranium Fuel Licensing Branch 84/07/27 Uranium fuel Licensing Branch ip 25751 019

840809023B Forwards NRC B40727 Amend 1 to License SNM-1926 & SER in support of amend Related correspondence VIGLER, B H Hearing Branch 4 DSB 872 84/08/07 BRENNER, L. MORRIS, P A. COLE, R F. Atomic Safety and Licensing Board Panel 14pp 25972 152 24X Fiche 30-352,84/08/07,8408090232

DOCKET 70-2998 GULF STATES UTILITIES CO , BEAUMONT, TX

8408270338 Forwards request for add1 info re 840416 application for license to store unirradiated fuel onsite Attempt will be made to process application by 841201 if info reviewed by 840924
BIDINGER. O H Uranium Fuel Licensing Branch 84/08/22 BOOKER. J E Oulf States Utilities Co 2pp 26311 300 24X
Fiche 50-458.84/08/22:8408270338

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0008 COMMONWEALTH EDISON CO

8408040427 Informs of expiration of GA program approval for radioactive package on 840630 Application fee & renewal request required for continuation of program MACDUNALD, CE Transportation Certification Branch 84/07/30 Commonwealth Edison Co 1p 25937 334

DOCKET 71-0011 ARROW TANK & ENGINEERING CO

8408080268 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDONALD, C E Transportation Certification Dranch 84/08/01 SOLTIS, L R Arrow Tank & Engineering Co 1p 25978 310

DOCKET 71-0014 ADTRONDACK STEEL CASTING CD

8408080139 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired.NRC should be so notified MACDONALD.C E Transportation Certification Branch 84/08/01 HOLLANDER.W D Advinopack Steel Casting Co.Inc ip 25979 105

DOCKET 71-0015 CHICAGO BRIDGE & IRON CO

8408080175 Advises that GA program approval for redicactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired.NRC should be so motified MACDINALD, C E Transportation Certification Branch 84/08/01 MRUZIC, R W Chicago Bridge & Iron Co ip 25978 351

DOCKET 71-0016 NORTHWEST AIRLINES, INC

8408080264 Advises that Q4 program approval for radioactive packages expires on 840930 Removal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDUNALD.C E Transportation Certification Branch 84/08/01 HUSKINS, W.F. Northwest Airlines, Inc. [p. 25978-312

B40B310436 Forwards GA program approval for radioactive matl package 0016/Rev 2 MACDBALLD.C E Transportation Certification Branch 84/08/20 LIGHTFOOT:8 H Northwest Airlines: Inc 1p 26350 (40

--B40B31043B QA program approval for radioactive mat1 package 0016.Rev 2 MACDONALD.C E Transportation Certification Branch 84/08/28 1p 26390 141

### DOCKET 71-0020 INTERNATIONAL TESTING LABS

0408080126 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not dosired.NRC should be so notified MACDONALD.C E Transportation Certification Branch 84/08/01 MARANS.M P International Testing Laboratories. Inc 19 25979 116

### DOCKET 71-0022 NEWPORT NEWS INDUSTRIAL CORP

B40B080270 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration if renewal not desired NRC should be so notified MACDONALD, C E Transportation Certification Branch 84/08/01 MORIN, E U Newport News Industrial Corp (subs of Newport News Bhipbuilding) in 25978 309

DOCKET 71-0029 BORG-WARNER CORP

8408080136 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so notified MACDONALD, C.E. Transportation Cortification Branch 84/08/01 BUDTH, J.H. Borg-Warner Corp. Ip. 25979 107

DOCKET 71-0032 PANHANDLE EASTERN PIPE LINE CO

1408080220 Advises that GA program approval for radioactive packages expires on 840920 Renewal must be requested within 30 days of syniration If renewal not desired NRC should be so notified MACOUNALD. C E Transportation Certification Branch 84/08/01 DDHRMN.K F Panhandle Eastern Pipe Line Co ip 25978 324

DOCKET 71-0033 IND TEST LAD SERVICES CORP

840BD80137 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDONALD. C.E. Transportation Certification Branch 84/08/01 MAMDRAHAN.E. Industrial Testing Laboratory Services Corp. 1p. 25779 106

DOCKET 71 0031 BADCOCK & WILCOX CD

8408080401 Advises that QA program approval for radioactive packages expires on 840930 Reneval must be requested within 30 days of expiration if renewal not desired.NRC should be so notified MACDUNALD.C E Transportation Certification Branch 84/08/01 LONEJ R Babcock & Wilcox Co. ip 29978 078

DOCKET 71-0034 ITT GRINNELL CORP

B408080283 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so notified MACDDNALD.C E Transportation Certification Branch 84/08/01 KDMALSKIJ 0 ITT Orinnell (subs of ITT) ip 25978 305

DOCKET 71-0037 NAVY, DEPT OF

8408080444 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDUNALD.C E Transportation Certification Branch 84/08/01 Navy, Dept of 1p 29977 182

DOCKET 71-0038 CRANE CO

B408060421 Informs that 9A program approval for radioactive packages expired on B40831 Request for renewal & fee required for continuation of 9A program MACDDNALD,C E Transportation Certification Branch B4/07/30 Crane Co 1p 25937 340

DOCKET 71-0039 WALWORTH CO

8408080279 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired. NRC should be so notified MACDONALD. C E Transportation Certification Branch 84/08/01 SHIELDS.R R Walworth Co (subs of IV International Corp.) ip 25978 307

8408210073 Informs that QA program approval for radioactive package no longer needed Facility in Greensburg.PA not operational AHTREY.P H Walworth Co (subs of IV International Corp.) 84/08/01 MACDONALD.C E Transportation Certification Branch 1p. 26195 351

DOCKET 71-0044 UNITED AIRLINES, INC.

B40B0B0071 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired. NRC should be so notified HACDDNALD.C E Transportation Certification Branch 84/08/01 KABTENSIJ W United Airlines. Inc. 1p. 25981 101

DOCKET 71-0047 CAPITOL INTERNATIONAL AWYS , INC

B408080076 Advises that QA program approval for radioactive packages appires on B40930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so notified MACDDNALD, C E Transportation Certification Branch B4/08/01 SPARKS, E Capitol International Airways Inc ip 25981 097

DOCKET 71-0051 HARRISON STEEL CASTINGS CO

8408080447 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDDNALD, C E Transportation Certification Branch 84/08/01 WILLIAMSON, G Harrison Steel Cast 1p 83977 150

## DUCKET 71-0055 H R INSPECTION SERVICE

8408080225 Advises that GA program approval for radioactive packages expires on 810930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDUNALD.C E Transportation Certification Branch 84/08/01 H R Inspection Service 1p 25978 323

### DOCKET 71-0056 PHILADELPHIA ELECTRIC CO

8408060433 Informs that QA program approval for redicactive packages expired on 840630 Request for renewal & fee required for continuation of QA program MACDDNALD,C E Transportation Certification Branch 84/07/30 COUNEY,J J Philadelphia Electric Co ip 25937 324

#### DOCKET 71-0057 EXXON CO . USA

8408090081 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired.NRC should be so notified MACDONALD, C E Transportation Certification Branch 84/08/01 SWARTZ, J H Exxon Corp [p 25979 143]

#### DOCKET 71-0059 GENERAL ELECTRIC CO

840808041B Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired.NRC should be so notified MAGDDNALD.C C Transportation Certification Branch 84/08/01 LABRANCHE.F R General Electric Co 10 25977 337

### DOCKET 71-0061 NAVY, DEPT OF

8408080411 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDUNALD.C & Transportation Certification Branch NAVY, Dept of, Naval Weapons Station Concord, CA. 1p 25978 074

### DOCKET 71-0063 DZARK AIRLINES, INC

8408080135 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired.NRC should be so nutified MACDDNALD. E Transportation Certification Branch 84/08/01 YOUND.R E Orark Airlines 1p 25979 109

# DOCKET 71-0066 CERTIFIED TESTING LABS . INC

8408080143 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired.NRC should be so notified MACDUNALD.C C Transportation Certification Branch PULMSTEAD.P F Certified Testing Laboratories. Inc 1p 25979 082

B40B310354 Forwards GA program approval for radioactive matl package 0046.Rev 2 MACDONALD,C E Transportation Certification Branch 84/08/28 PLUMBTEAD.R F Certified Testing Laboratories, Inc. 1p 26350-323

---8408310358 QA program approval for radioactive matl package 0066.Rev 2 MACDUNALD.C E Transportation Certification Branch 84/08/28 ip 26390 324

#### DOCKET 71-0068 YANKEE ATOMIC ELECTRIC CO

8408070056 Informs that QA program approval for radioactive packages expires on 840731 Request for renewal & fee should be submitted to provide for continuation of QA program MACDONALD, C E Transportation Certification Branch 84/07/30 HEIDER, L H Yankee Atomic Electric Co 1p 25995 332

### DOCKET 71-0070 GAMMA FIELD RADIOGRAPHIC FACILITY

8408080132 Advises that QA program approval for radioactive packages expires on 840930 Remewal must be requested within 30 days of expiration If renswal not desired, NRC should be so notified MACDONALD, C E Transportation Certification Branch ABRAMB, C J Gamma Field Radiographic Facility 1p 25979 110

8408310443 Forwards GA program approval for radioactive matl package 0070 Rev 2 MACDONALD.C E Transportation Certification Branch B4/08/28 ABRAMS.C J Gamma Field Radiographic Facility 1p 24350 133

--B408310457 QA program approval for radioactive mat1 package 0070, Rev 2 MACDUNALD.C E Transportation Certification Branch B4/08/28 1p 26350 134

### DOCKET 71-0074 NUCLEAR WELDING, INC

8408080065 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDUNALD.C E Transportation Certification Branch 84/08/01 HANEB.T S NWI International (Nuclear Welding, Inc.) ip 25981 085

#### DOCKET 71-0075 NORFOLK SHIPBUILDING & DRY DOCK CO

B40B0B0079 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration [f renewal not desired, NRC should be so nutified HACDUNALD, C Transportation Certification Branch 84/08/01 EURE, C H Norfolk Shipbuilding & Drydock Corp 1p 25981 098

### DOCKET 71-0077 MIDSTATE TESTING LABORATORY

8408090078 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired.NRC should be so natified MACDUNALD.C E Transportation Certification Branch 84/08/01 KEILMAN.T J Midstate Testing Laboratory, Inc. 1p 25981 096

#### DOCKET 71-0080 TRANSWORLD AIRLINES, INC

8408080096 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so notified MACDDNALD.C E Transportation Certification Branch 84/08/01 SCENEN.E A Trans World Airlines. Inc. 1p 25981 072

# DOCKET 71-0081 ITT GRINNELL INDUSTRIAL PIPING, INC

B4080B0210 Advises that QA program approval for radioactive packages expires on B40930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDDNALD, C E Transportation Certification Branch B4/08/01 HARRIS, D C ITT Grinnell (subs of ITT) ip 25978 328

### DOCKET 71-0083 NORTHERN STATES POWER CO

840Bi30020 Requests addi 5-yr extension of GA program approval for radioactive mati packages GA requirements of 10CFR71 will be satisfied through NRC approved program Forwards Rev 9 to "Operational GA Plan" Fee encl MUSCLF.D Northern States Power Co 84/06/28 MACDONALD,C E Transportation Certification Branch 25p 24011 128

--8408130021 Rey 9 to "Operational GA Plan"

\* Northern States Power Co 84/04/12 93pp 26011 130

--8408130024 Forwards fee for 840428 request for renewal of radioactive mat1 transport package GA program.per 840718 request MUSOLF, D Northern States Power Co 84/07/24 CABELL, A S License Fee Management Branch 1p 26011 223

--8408130027 Requests remittance for 840628 request for renewal of radioactive mail transport package QA program.per 10CFR:70 M/o stated encl CABELL.A S License fee Management Branch 84/07/18 MUSOLF.D Northern States Power Co 1p 26011 224

DOCKET 71-0087 NAVY, DEPT OF

8408080281 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so notified MACDUNALD, C E Transportation Certification Branch 84/08/01 Navy, Dept of ip 25978 306

DOCKET 71-0089 NAVY, DEPT OF

8408080185 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration [f renewal not desired-NRC should be so notified AACDENALD, C E Transportation Certification Branch 84/08/01 Navy, Dept of 1p 23978 340

DOCKET 71-0093 HUNTINGTON TESTING

8408080063 Advises that QA program approval for radioactive packages expires on 840930 Renowal must be requested within 30 days of expiration [f renewal not desired.NRC should be so notified MACDDNALD.C E Transportation Certification Branch 84/08/01 YEOMAN.W Huntington Testing 1p 25981 084

DUCKET 71-0095 UNITED STATES TESTING CO . INC

8408080079 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDINALD, C E Transportation Certification Branch 84/08/01 YODER, C B United States Testing Co, Inc. 1p. 25979 145

DOCKET 71-0099 FOSTER WHEELER ENERGY CORP

8408080469 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDGNALD, C E Transportation Certification Branch 84/08/01 KDVACS, B Foster Wheeler Corp ip 23976 C65

DOCKET 71-0100 VENEGAS IND TEST LABS , INC

'408080325 Advises that GA program approval for radioactive packages expires on 840730 Renewal must be requested within 30 days of expiration of renewal not desired NRC should be so notified IACDONALD. C. E. Transportation Certification Branch 84/08/01 ENEGUS.W. Venegas Industrial Testing Laboratories Inc. 1p. 1978 199

CHET 71-0103 THIN CITY TESTING & ENGR LAB

40B080328 Advises that QA program approval for radioactive packages expires on 840730 Renewal must be requested within 30 days of expiration If renewal not desired. NRC should be so notified MACDONALD. C E Transportation Certification Branch 84/0B/01 SCHULZE. H T Twin City Testing & Engineering Laboratory. Inc. 19

DOKET 71-0104 CHICAGO BRIDGE & IRON CO

25978 200

3408080145 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested uithin 30 days of expiration If renewal not desired NRC should be so notified MACDONALD.C E Transportation Certification Branch 84/08/01 HERRLE.R R Chicago Bridge & Iron Co ip 25979 055

DOCKET 71-0105 UNIVERSAL TESTING LABORATORIES

B408090163 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration if renewal not desired.NRC should be so notified MACDUNALD.C E Transportation Certification Branch 84/08/01 JOHNSON.W R Universal Technical Testing Laboratories. Inc. 1p 25978 342

DOCKET 71-0110 BUCKEYE STEEL CASTINGS

6408030313 Advises that OA program approval for radioactive packages expires on 840930 Reneual must be requested within 30 days of expiration if renewal not desired NRC should be so notified MACDDNALD. C. E. Transportation Certification Branch 84/08/01 KRANER. J. F. Buckeye Steel Castings (subs of Buckeye International) 19 25778 224

POCKET 71-0111 MATERIAL TESTING LAB OF VIRGINIA, INC

8408310421 Advises that GA program approval for radioactive packages expines on 841030 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACBONALD, C.E. Transportation Certification Brench 84/08/28 STEELC, W.F. Material Testing Laboratory of Virginia, Inc. 1p. 26350-214

DOCKET 71-0113 NOOTER CORP

8408080156 Advises that GA program approval for radicactive packages expires on 840930 Renewal must be requested within 30 days of expiration if renewal not desired.NRC should be so notified MACDENALD, C E Transportation Certification Branch 84/08/01 FRAZIER, D L Nooter Corp 1p 25979 009

DOCKEF 71-0119 INGERSOLL-RAND CO

8408080107 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired.NRC should be spinotified MACDINALD, C E Transportation Certification Branch 84/08/01 MORGANELL.M M Ingersoll-Rand Co ip 25979 130

DOCKET 71-0120 DANIEL INTERNATIONAL CORP

8408080122 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so notified MACDONALD.C E Transportation Certification Branch 84/08/01 PREWITTER N Daniel International (subs of Fluor Corp.) ip 25979 118

DOCKET 71-0123 HERRON TESTING LABS , INC

8408080287 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration if renewal not desired,NRC should be so natified MACBUNALD,C E Transportation Certification Branch 84/08/01 THERET.H T Herron Testing Laboratories, Inc. 1p 23978 304

DOCKET 71-0124 HOUSTON INSPECTION LABS . INC

9408310418 Advises that GA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDONALD, C E Transportation Cortification Branch 84/08/28 BALLARD, B R Houston Inspection Laboratories, Inc. 1p 26/330 217

+

### DOCKET 71-0125 TESTCO, INC

B40B0B0125 Advises that QA program approval for radioactive packages expires on B40930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so notified MACDONALD.C E Transportation Certification Branch 84/08/01 FOUSHEE.JR Testco.Inc 1p 25979 117

## DOCKET 71-0127 NATIONAL ANNEALING BOX CO

8408080045 Advises that QA program approval for radioactive packages expires on 840930 Renewal most be requested within 30 days of expiration If renewal not desired NRC should be so notified MACDDNALD, C.E. Transportation Certification Branch 84/08/01 FRANTZ. J.R. National Annealing Dos Co. 1p. 25981 046

### DOCKET 71-0128 AMOCO DIL CO

8408080017 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so natified MACDONALD. C C Transportation Certification Branch 84/08/01 KLIEGER. (P American 0:1 Co (subs of Standard 0:1 Co of Indiana) ip 25981 036

#### DOCKET 71-0130 CHICAGO BRIDGE & IRON CO

8408080015 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notifized MACBDNALD, C. Transportation Certification Branch 84/08/01 STULL.D.J. Chicago Bridge & Iron Co. ip. 25981 035

### DOCKET 71-0132 ADVANCED RADIATION SERVICE

B4080B0112 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so notified MACDDNALD, C Transportation Certification Branch 84/08/01 KURTZ.A S Advanced Radiation Service. Inc. 1p. 25979 121

## DOCKET 71-0133 NAVY, DEPT DF

8408080111 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDUNALD, C E Transportation Certification Branch 84/08/01 Navy, Dept of, Pearl Harbor Naval Shipyand ip 25979 122

### DOCKET 71-0134 LABARGE, INC

8408090117 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDONALD.C C Transportation Certification Branch 84/08/01 DIGGERS.S LaBarge, Inc ip 25979 120

# DOCKET 71-0137 METALS TESTING CO : INC

8408080128 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDONALD, C E Transportation Certification Branch 84/08/01 LEINS, J H Metals Testing Co , Inc 1p 25979 114

#### DOCKET 71-0140 WALWORTH CO

8408080092 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration if renewal not desired. NRC should be so notified MACDUNALD. C. E. Transportation Certification Branch 84/08/01 NICHOLS. G. Walworth Co. (subs. of IV International Corp.) ip 25979 139

#### DOCKET 71-0145 THAYER INSPECTION SERVICE, INC.

B408090088 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration if renewal not desired, NRC should be so notified MACDDNALD, C E Transportation Certification Branch 84/08/01 MOSS.J C Thayer Inspection Service, Inc. (p. 25979 140

#### DOCKET 71-0148 UNITED ENGINEERS & CONSTRUCTORS, INC.

8408080075 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration if renewal not desired. NRC should be so notified MACDONALD. C.E. Transportation Certification Branch 84/08/01 RABERGLD. C.F. United Engineers & Constructors, Inc. (subs. of Raytheon Co.) ip 25779 136

### DOCKET 71-0151 HESS OIL VIRGIN ISLANDS CORP

8408080069 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration if renewal not desired, NRC should be so notified MACDONALD, C E Transportation Certification Branch 84/08/01 COMUS. L D Hess Oil Virgin Islands Corp 1p 25481 087

#### DOCKET 71-0152 VIRGINIA, COMMONWEALTH OF

B40B0B0273 Advises that GA program approval for radioactive packages expires on B40930 Renewal must be requested within 30 days of expiration if renewal not destred, NRC should be so notified MACDONALD, C.E. Transportation Certification Branch B4/08/01 VIA, W.F. Virginia, Commonwealth of, ip 2578 302

#### DOCKET 71-0154 GENERAL DYNAMICS CORP

8408080291 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration if renewal not desired.NRC should be so notified MACDUALLD, C E Transportation Certification Branch 84/08/01 ALCRN.L B General Dynamics Corp ip 25978 303

#### DOCKET 71-0156 INDUSTRIAL FADRICATING CO

8408080058 Advises that OA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so notified MACDONALD, C & Transportation Certification Dranch 84/08/01 80ZARTH N Industrial Fabricating ip 25981.079

### DOCKET 71-0157 FROEHLING & ROBERTSON. INC.

840B0B0101 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDONALD, C E Transportation Certification Branch 84/08/01 BRODY, W R Froehling & Robertson, Inc. 1p. 25979 133

#### DOCKET 71-0158 X-RAY INDUSTRIES, INC

8408310289 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDONALD.C E Transportation Certification Branch 84/08/28 SHIPLET, M J X-Ray Industries, Inc. 1p. 26350-285

#### DOCKET 71-0161 CURTISS-WRIGHT CORP

B40B0B0154 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDONALD, C E Transportation Certification Branch B4/08/01 JACKBON, C Curtiss - Uright Corp 1p 25779 010

#### DOCKET 71-0162 EBASCO SERVICES. INC

8408080406 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired.NRC should be so notified MACDONALD.C E Transportation Certification Branch 84/08/01 BULLEN.H C Ebasco Services. Inc (subs of Enserch Corp ) 1p 25078 075

### DOCKET 71-0166 NEW YORK TESTING LABS. INC

8408080451 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired.NRC should be so notified MACDUNALD.C E Transportation Certification Branch 84/08/01 MARVEY.6 J Neu York Testing Laboratories. Inc 1p 25977 148

### DOCKET 71-0167 FINLAY TESTING LABORATORIES

8408310287 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified AACOUNALD, CE Transportation Certification Branch 84/08/28 FINLAY, GW Finlay Testing Laboratories ip 26350 294

### DOCKET 71-0168 QUALITY ASSURANCE LABS

8408080462 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDONALD.C E Transportation Certification Branch 84/08/0] TRAUTVETTER.C Quality Assurance Laboratories, Inc (formerly Jannetti Corp.) 1p 25976-067

### ICKET 71-0169 FLORIDA POWER & LIGHT CO

108070010 Informs of expiration of QA program approval for radioactive packages on 840831 Application fee & renewal request required 30 days prior to expiration MACDONALD.C E Transportation Certification Branch 84/07/30 WETHY.C W Florida Power & Light Co 1p 25754 207

IAOB310435 Forwards QA program approval for radioactive matl package Old9,Rev 2 HACDQNALD.C E Transportation Certification Branch 84/08/28 WILLIAMS.J W Florida Power & Light Co ip 26930 124

--8408310436 QA program approval for radioactive mat1 package 0169.Rev 2 MACDONALD.C E Transportation Certification Branch 84/08/28 1p 26350 125

### DOCKET 71-0171 INDUSTRIAL INSPECTION INDUSTRIES

8408080247 Advises that OA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDONALD, C E Transportation Certification Branch 84/08/01 HOPKING, S M Industrial Inspection Industries, Inc. 1p 25978 311

### DOCKET 71-0172 EMPIRE STEEL CASTINGS, INC.

8408310293 Advises that GA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired. NRC should be so notified MACDONALD. C Transportation Certification Branch 84/08/28 GAUMER, G R Empire Stee! Castings. Inc. 1p 240350 293

#### DOCKET 71-0174 SOUTHERN CALIFORNIA EDISON CO

B40B070064 Advises that request for renewal of GA program should be submitted 30 days prior to B40B31 expination date MACDUNALD,C E Transportation Certification Brench 84/07/30 BRIDENBECKER,R Southern California Edison Co. ip 25955 322

#### DOCKET 71-0175 GC SERVICES, INC.

8408080465 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so notified MACDUNALD.C E Transportation Certification Branch 84/08/OFFILL KS QC Services, Inc. 1p. 25974-046

### DOCKET 71-0181 CONSOLIDATED Y-RAY SERVICE CORP

B408080274 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so notified MACDONALD.C E Transportation Certification Branch 64/08/Ot CULLINGTON.R F Consolidated X-Ray Service Corp. ip 29978 308

## DOCKET 71-0183 GAMMA SONICS EX LABS

B408080231 Advises that Q4 program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified IMACDONALD, CE Transportation Certification Branch 84/08/01 SANDERS, HA Gamma Sonics Examination Laboratories, Inc. 1p. 28978 321

# DOCKET 71-0184 PULLMAN POWER PRODUCTS

B408130278 Requests that previously Commission approved GA program, which satisfies applicable criteria of IOCFR50, App B, be accepted for continuous use BAIR, A Pullman, Inc B4/07/10 Office of Nuclear Material Safety & Safoguards, Director 2pp 26040 338

--8408130283 Remits renewal fee for Rev O to GA program, per 840720 ltr BAIR.A Pullman. Inc 84/07/26 JACKSUN.G License Fee Management Branch 1p 26040 339

--B40B130292 Requests remittance of fee for 840710 application for renewal of GA program Revised 10CFR170 encl W/o encl JACKBON.0 License Fee Management Branch 84/07/20 BAIR.A Pullman, Inc. ip 26040 340

#### DOCKET 71-0184 HIGH STEEL STRUCTURES: INC

8408310444 Advises that GA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDUNALD, E Transportation Certification Branch 84/08/28 KRESB.C R High Steel Structures, Inc. 1p. 26350 132

### DOCKET 71-0188 MAYNARD STEEL CASTING CO

8408080247 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so notified MACDENALD.C E Transportation Certification Branch 84/08/01 FAIST,C A Maynard Electric Steel 1p 25978 319

DOCKET 71-0195 TOLEDO EDISON CO

8408070151 Informs of expiration of QA program approval for radioactive packages on 840831 Application fee & renewal request required 30 days prior to expiration MACDDNALD.C E. Transportation Centification Branch 84/07/30 MURRAY, 1 Toledo Edison Co 10 25957 119

DOCKET 71-0202 PACIFIC GAS & ELECTRIC CO

840B010036 Notifies of util intent to apply previously approved corporate QA program to \*ransportation activities at Diablo Cangon, Unit 1
SCHUYLER, J 0 Pacific Cas & Electric Co 84/07/05 DAVIS, J 0
Office of fuciear Material Safety & Safeguards, Director 2pp 25873 361

DOCKET 71-0205 QUALITY TESTING, INC.

8408080258 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so MACDONALD,C E Transportation Certification Branch BECKER,C A Quality Testing, Inc. 1p 25978 314 84/08/01

DOCKET 71-0207 CONNECTION YANKEE ATOMIC POWER CO.

8408060374 Informs that QA insp program for radioactive packages expires on 840831 To continue QA program to be applied to packaging & transportation activities, renewal request should be made at least 30 days prior to expiration date MACDDNALD.C E Transportation Certification Branch 84/07/30 GRAVES, R H Connecticut Yankes Atomic Power Co 1 p 25951 235

DOCKET 71-0208 NORTHEAST NUCLEAR ENERGY OF

840B030098 Informs of expiration of GA program approval for radioactive packages on B40831 Application fee & renewal request required within 30 days prior to expiration MACDDNALD, C & Transportation Certification Branch 84/07/30 CHEATHAM, A & Northeast Nuclear Energy Co (subs of Northeast Utilities) 1p 25979 134

DOCKET 71-0211 BOSTON EDISON CO

B408070159 Informs that GA program approval for radioactive packages expired G40531 Renewal of GA program recommended in order to provide for continuation of program to be applied to packaging & transportation activities Fee required MACDIDNALD.C E Transportation Certification Branch 84/07/30 MACHON.R Boston Edison Co 1p 25987 117

DOCKET 71-0212 GENERAL ELECTRIC CO

8408080293 Advises that QA program approval for radioactive packages expires on 640930 Reneual must be requested within 30 days of expiration If renewal not desired NRC should be so MACDDNALD,C C Transportation Certification Branch 84/08/01 ENGEL.J D General Electric Co 1p 25978 315

DOCKET 71-0213 INTERMOUNTAIN TESTING CO

8408080263 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so MACDONALD,C E Transportation Certification Branch 84/09/01 CHANDLER.J W Intermountain Technologies, Inc. 1p. 25978 313 CHANDLER, J W

DOCKET 71-0214 GAS RENTALS, INC

8408080460 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so natified MACDONALD.C E Transportation Certification Branch 84/0 C C Transportation Certification Branch 84/08/01 Gas Rentals (p 25976 O&B LUDWIG, T

DOCKET 71-0215 SPACE SCIENCE SERVICES, INC.

8408080103 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so MACDONALD.C E Transportation Certification Branch 84/08/01 sace Science Services, Inc. ip 25979 [32 GEIGER, D. A. Space Science Services, Inc.

DOCKET 71-0216 NUCLEAR ENERGY SERVICES, INC.

8408080452 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired. NRC should be so notified MACDGMALD.C E Transportation Certification Branch 84/08/01 9AMBLE.O C Nuclear Energy Services. Inc 1p 25977 147

8408310449 Forwards GA program approval for radioactive matl package 021A. Rev 2 0216.Rev 2 MACDONALD.C E Transportation Certification Branch SLACK.R J Nuclear Energy Services, Inc. ip. 263

--8408310453 QA program approval for radioactive matl package 0216, Rev 2 MACDUNALD,C E Transportation Certification Branch 84/08/28

26350 129

DOCKET 71-0217 PULLMAN, INC.

26350 130

8408080084 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so MACDONALD, C E E Transportation Certification Branch Pullman Inc ip 25979 141 84/0B/01 TURNER J E

DOCKET 71-0218 CUMBERLAND BRIDGE CO

8408080459 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so MACDDNALD, C E Transportation Certification Branch HARRIS, W I Cumberland Bridge Co 1p 25976 069 B4/08/01

DOCKET 71-0219 TEREX CORP

84080B0470 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so MACDDNALD,C E Transportation Certification Branch 84/08/01 HEINTZELMAN.K TEREX Corp 1p 25976 063

DOCKET 71-0220 GENERAL DYNAMICS CORP

8408080468 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDONALD.C E Transportation Certification Branch SURPRENANT,R H General Dynamics Corp. 1p. 25976 84/08/01 25976 064

DOCKET 71-0221 ALLIB-CHALMERS CORP

8408070500 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so MACDONALD, C E E Transportation Certification Branch 84/08/01 Allis-Chalmers Corp ip 25956 255 NAYLOR, C. A.

DOCKET 71-0222 ST LOUIS TESTING LABORATORIES, INC.

8408070504 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration if renewal not desired NRC should be so MACDONALD, C E Transportation Certification Branch
TROWBRIDGE.C D St Louis Testing Laboratories, In example tation Certification Branch 84/08/01 8t Louis Tosting Laboratories, Inc. ip

#### DOCKET 71-0223 BENJAMIN F SHAW CO

8408080074 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration if renewal not desired NRC should be so notified MACDONALD, C.E. Transportation Certification Branch 84/08/01 SMEALL P. Benjamin F. Shaw Co. (subs. of Blount, Inc.) ip 25981 099

# DOCKET 71-0224 GUYON POWER & PROCESS PIPING

8408070507 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration if renewal not desired, NRC should be so notified MACDONALD.C E Transportation Certification Branch 84/08/01 BURCHOFFER.J M Guyon Alloys, Inc. 1p. 25956 239

### DOCKET 71-0225 NAVY, DEPT OF

8408070803 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDONALD, C E Transportation Certification Branch 84/08/01 Navy, Dept of, Naval Research Laboratory 1p 25956 238

## DOCKET 71-0229 WORD INDUSTRIES PIPE FABRICATING, INC

8408080446 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired/NRC should be so notified MACDONALD.CE Transportation Certification Branch 84/08/01 #0001878.R W Word Industries Pipe Fabricating. Inc. ip 25977 151

### DOCKET 71-0232 LAMEHEAD TESTING LAB , INC.

B408080072 Advises that GA program approval for radioactive packages epires on B40930 Renewal must be requested within 30 days of expiration If renewal not desired.NRC should be so notified MACDUNALD.C E Transportation Certification Branch 84/08/01 WIRTZ.G L Lakehead Testing Laboratory. Inc 1p 25981 100

### DOCKET 71-0233 D'NEILL TANK CO : INC

B40B0B0104 Advises that Q4 program approval for radioactive packages expires on B40930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified MACDDNALD.C E Transportation Certification Branch B4/08/01 ADAMS.K O'Neill Tank Co., Inc. 1p. 25779 131

#### DOCKET 71-0234 X-RAY, INC

B40B0B00B3 Advises that GA program approval for radioactive packages expires on B40930 Renewal must be requested within 30 days of expiration If renewal not desired.NRC should be so notified MACDUNALD.C E Transportation Certification Branch B4/0B/01 CONNELL 0 X-Ray, Inc ip 25979 142

### DOCKET 71-0237 COLUMBIA GAS TRANSMISSION CORP

B4080B0378 Advises that QA program approval for radioactive packages expires on B40930 Renewal must be requested within 30 days of expiration If renewal not desired.NRC should be so notified MACDUNALD.C E Transportation Certification Branch 84/08/01 WHITE.D C Columbia Gas Transmission Corp (subs of Columbia Oas Sys. Inc.) ip 25978 089

### DOCKET 71-0240 POWER AUTHORITY OF STATE OF NEW YORK

B4OB;5014/ Forwards payment for renewal of QA program approval for radioactive matl packages BAYNE, J P Power Authority of the State of New York NACDENALD, C C Transportation Certification Branch 25:04 199

B408200084 Forwards QA program approval for radioactive mat) package C240. Rev 2 MACDGNALD.C E Transportation Certification Branch 84/08/1.3 BAYNE J.P. Power Authority of the State of New York 1p

--8409200070 GA program approval for radioactive matl package 0240.Rev 2 MACDONALD.C E Transportation Certification Branch 84/08/13 1p 26142 336

#### DOCKET 71-0242 LAW ENGINEERING TESTING CO

8408080381 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so notified MACDENALD.C E Transportation Certification Branch 84/08/01 ERWIN.R 0 Law Engineering Testing Co 1p 25978 087

#### DOCKET 71-0245 NAVY, DEPT OF

8408310415 Advises that Q4 program approval for radioactive packages expires on 841030 Renowal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDUNALD, C E Transportation Certification Branch 84/08/28 Navy, Dept of ip 26350 221

### DDCKET 71-0247 IRT CORP

8408080424 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration if renewal not desired NRC should be so notified MACDUNALD, C.E. Transportation Certification Branch 84/08/01 CROSBIE, K.L. IRT Corp. ip 25977 191

## DOCKET 71-0253 TWIN PORTS TESTING, INC

B40B090379 Advises that GA program approval for radioactive packages expires on B40930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so notified MACDDNALD, C.E. Transportation Certification Branch 84/08/01 MCKEEVER.R.D. Twin Ports Testing, Inc. 1p. 25978 088

# DOCKET 71-0254 GENERAL ELECTRIC CO

8408310407 Advises that QA proram approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so notified MACDUNALD. C E Transportation Certification Branch 84/08/28 VAUGHAN.C M General Electric Co ip 26352 044

# DOCKET 71-0256 DMAHA PUBLIC POWER DISTRICT

8408150136 Requests renewal for QA program approval for radioactive muti parkages Fee encl ANDREWS, R L. Omaha Public Power District 84/07/13 MACDONALD, C f Transportation Certification Branch 2pp 26104 247

# DOCKET 71-0257 INDUSTRIAL LABS, INC

8408080479 Advises that GA program approval for radioactive packages expires on 840930 Rengual must be requested within 30 days of expiration If renewal not desired NRC should be so notified MACDONALD.C E Transportation Certification Branch 84/08/01 MELLS.8 R Industrial Laboratories, Inc. 1p. 25976-061

#### DOCKET 71-0261 NAVY, DEPT OF

B40B310403 Advises that GA program approval for ladioaltive packages expires on 841030 Renewal must be requested within 30 days of expiration [f renewal not desired NRC should be so notified MACDDNALD.C C Transportation Certification Branch 84/08/28 Navy. Dept of 1p 26350-277

#### DOCKET 71-0268 NAVY, DEPT OF

8408310393 Advises that GA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDONALD, C E Transportation Certification Branch 84/08/28 Navy, Dept of 1p 26350 291

# DOCKET 71-0269 LEHIGH TESTING LABORATORIES, INC.

B408310399 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDONALD, C E Transportation Certification Branch 84/08/28 RECCHIA: R Lehigh Testing Laboratories, Inc. 1p. 26350-278

### DOCKET 71-0270 FACTORY MUTUAL ENGINEERING CORP

B408080310 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired/NRC should be so notified MACDDNALD.C E Transportation Certification Branch 84/08/01 RICHARDS.C A Factory Mutual Engineering Corp ip 25978 227

#### DOCKET 71-0272 CRANE CO

E408080127 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration if renewal not desired/NRC should be so notified MACDONALD, C E Transportation Certification Branch 84/08/01 ESTERT, G W Crane Co ip 25979 115

### DOCKET 71-0274 NAVY, DEPT OF

B40B3i03B7 Advises that GA program approval for radioactive packages expires on 84103D Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDDNALD, C E Transportation Certification Branch 84/08/28 Navy, Dept of 1p 26350 274

### DOCKET 71-0275 DUGUESNE LIGHT CO

8408060326 Informs that QA insp program for radioactive packages expires on 840831 To continue QA program to be applied to packaging \*\* transportation activities\* renewal request should be made at least 30 days prior to expiration date MACDUNALD.C C Transportation Certification Branch 84/07/30 KDSMALJA Duguesne Light Co 1p 25937 360

#### DOCKET 71-0276 NAVY, DEPT OF

B408310382 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDUNALD.C E Transportation Certification Branch 84/08/28 Navy, Dept of ip 26350 273

#### DOCKET 71-0279 UNIVERSAL TESTING. INC

## DOCKET 71-0280 ABCO PERFORATORS, INC

B40B310377 Advises that dA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDDNALD, C E Transportation Certification Branch 84/08/28 COOK, C L Abro Perforators, Inc. 1p. 26350-271

### DOCKET 71-0281 DELTA AIRLINES. INC

8408080474 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired.NRC should be so notified MACDONALD.C E Transportation Certification Branch 84/08/01 EDHARDS.A D Delta Air Lines, Inc. ip 25976 062

### DOCKET 71-0282 WKM WELLHEAD SYSTEMS, INC.

8408310369 Advises that GA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired.NRC should be so notified MACDUNALD.C E Transportation Certification Branch 84/08/28 CANNON E WMM Wellhead Systems, Inc. 1p. 26350-353

#### DECKET 71-0283 MCMANUS INSPECTION SERVICE

840B080050 Advises that GA program approval for redicactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired. NRC should be so notified MACDONALD.C E Transportation Certification Branch 84/08/01 MCMANUS 6 McManus Inspection Service 1p 29981 082

#### DOCKET 71-0284 ULTRASONIC SPECIALISTS, INC.

8408080234 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired. NRC should be so notified MACDONALD.C E Transportation Certification Branch 84/08/01 SOUTHERS.L Ultrasonic Specialists, Inc. 1p. 25978 320

#### DUCKET 71-0205 BELL GEOPHYSICS

840B31034B Advises that GA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDONALD, C E Transportation Certification Branch 84/08/28 BELL.J A Bell Geophysics ip 26030 348

### DOCKET 71-0204 BPB INSTRUMENTS. INC

8408310364 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired. NRC should be so notified MACDONALD, C Transportation Certification Branch 84/08/28 GRACE, J 0 BPB Instruments, Inc. 1p 26350-355

### DOCKET 71-0287 CARSON NON-DESTRUCTIVE TESTING

8408310357 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDINALDIC E Transportation Certification Branch 84/08/28 MCVAUGH, R W Carson Nan Destructive Testing ip 26350 334

# DOCKET 71-0288 NORTH DAKOTA, STATE OF

840B310352 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so notified ACDONALD, CE Transportation Certification Branch B4/08/28 BURKE, P A North Dakota, State of 10 26350 349

#### DOCKET 71-0289 TERRADATA GEOPHYSICAL, INC.

8408310356 Advises that GA program approval for reducactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified

MACDDNALD, C E Transportation Certification Branch 84/08/28 MCBRIDE, G E Terradata Geophysical, Inc. 1p. 26350 279

### DOCKET 71-0290 UNITED TESTING SERVICES. INC.

8408310350 Advises that GA program approval for radioactive packages expires on B41030 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified

C E Transportation Certification Branch 84 United Testing Services, Inc. lp. 26350 307 MACDONALD, C.E.

# DOCKET 71-0291 BJ INSPECTION BERVICES, INC.

840B310346 Advises that QA program approval for radioactive packages expires on 841030 Remeual must be requested within 3D days of expiration If renewal not desired NRC should be so

MACDONALD,C E Transportation Certification Branch 84. JOHNSON,M DJ Inspection Services, Inc. 1p. 26350 308

### DOCKET 71-0292 INDUSTRIAL GAMMA INSPECTION

8408080215 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired.NRC should be so

notified MACDONALD,C E Transportation Certification Branch SMITH:R Industrial Gamma Inspection Ip 25970 327 84/08/01

### DOCKET 71-0293 BRAND X PERFORATORS. INC.

8408310278 Advises that GA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration if renewal not desired NRC should be so

MACDONALD, C E Transportation Certification Branch 84/08/28 Brand X Perforators in 26350 272

#### DOCKET 71-0294 APPLIED ENGINEERING CO

8408080074 Advises that GA program approval for radioactive packages expires on 840930 Reneual must be requested within 30 days expiration if renewal not desired. NRC should be MACDONALD, C E Transportation Certification Branch

R4/08/01 GOODWIN, J Applied Engineering Co ip 25979 137

### DOCKET 71-0295 ACUREX CORP

3408310283 Advises that GA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration if renewal not desired.NRC should be so

MACDONALD.C E Transportation Certification Branch 84/08/28 FENTON, N J Acurex Corp 1p 26350 284

# DOCKET 71-0296 (OWA ELECTRIC LIGHT & POWER CO

8408050374 Informs that QA insp program for radioactive gackages expired on 840630 To continue QA program to be applied to packaging & transportation activities, renewal request should be made & fee paid 30 days prior to expiration MACDONALD.C E Transportation Certification Branch 84/07/30 YDUNG,K Iowa Electric Light & Power Co 1p 25951 236

#### DOCKET 71-0297 & LEWIS COOK & ASSOCIATES

8408310300 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so notified

MACDOMALD, C E Transportation Certification Branch 84/08/28
"UABEE, K W E Lewis Cook & Associates 1p 26350 299

### DOCKET 71-0298 STEEL TANK CONSTRUCTION CO

8408080044 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so MACDONALD, C E

: E Transportation Certification Branch Steel Tank Construction Co 1p 2598) PADGETT, G 25981 045

#### DOCKET 71-0299 QUALITY CONTROL SERVICES

B40B310371 Advises that GA program approval for radioactive packages expires on B41030 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so MACDONALD, C. E. Transportation Certification Branch 84/08/28 SACHSE J. QC Services, Inc. 1p. 26350 262

#### DUCKET 71-0300 INDEPENDENT TESTING LABORATORIES

84080B0040 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so 84/08/01

notified MACDONALD.C & Transportation Certification Branch 84/08/0 SHAIN.H E Independent Testing Laboratories ip 25981 064

#### DOCKET 71-030! CTL ENGINEERING, INC

8408310366 Advises that GA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days expiration If renewal not desired NRC should be so MACDONALD, C. E. Transportation Certification Branch 84/08/20 CROWLEY, J L CTL Engineers, Inc. 1p 26350 263

#### DOCKET 71-0302 ASSOCIATED PIPING & ENGINEERING CORP

B408086457 Advises that GA program approval for radioactive packages expires on B40930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so MACDDNALD, C & Transportation Certification Branch 84/08/01. JONES.K C Associated Piging & Engineering Corp (subs of Johnson Controls, Inc.) ip 29976 070

## DOCKET 71-0303 MEMPHIS TESTING SERVICES, INC

840831039: Advises that GA program approval for radioactive packages expires on B41030 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so notified notified
MACDONALD.C E Transportation Certification Branch
REID.R E Memphis Testing Services. Inc. ip. 2635 84/08/20 26350 356

# DOCKET 71-0304 TELEDYNE BROWN ENGINEERING CO

8408080080 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so notified MACDONALD, C E E Transportation Certification Blanch 8 Taledyne Broun Engineering ip 25979 144

#### DOCKET /1-0305 AMERICAN X-RAY & INSPECTION, INC.

8408080057 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration, If renewal not desired NRC should be so notified MACCOUNALD,C E Transportation Certification Branch 84/08/01 GRASHAW,T D American X-Ray & Inspection 1p 2598; 078

#### DOCKET 71-0306 SNYDER DRILLING & WELL SERV

8408080066 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be lequested within 30 days of expiration if renewal not desired NRC should be so notified MACDUNALD.C E Transportation Certification Branch 84/08/01 SNYDER,H L Snyder Drilling-Well Servicing ip 25981 086

### DOCKET 71-0307 TEXAS PIPE BENDING CO OF PUERTO RICO

8408080062 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so notified MACDDNALD Transportation Certification Branch 84/08/01 WARREN.M C Texas Pipe Bending Co 1p 25981 063

### DOCKET 71-0310 BUCYRUS-ERIE CD

8408080229 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDONALD, C E Transportation Certification Branch 84/08/01 MERTZ, J M Bucyrus-Erie Co ip 28978 322

#### DOCKET 71-0311 LOGWELL, INC

8408310388 Advises that GA program approval for radioactive packages expires on 841030 Remaual must be requested within 30 days of expiration If renewal not desired NRC should be so notified MACDONALD, C E Transportation Certification Branch 84/08/28 BAILEY, F G Loguell 1p 26352 042

#### DOCKET 71-0312 METALFORMS, INC

B40B3103B4 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired.NRC should be so notified MACQDNALD.C E Transportation Certification Branch 84/08/28 DENNETT.C Metalforms, Inc. 1p 24352 045

### DOCKET 71-0313 PRECIBION INSPECTION, LTD

8408310380 Advises that QA program approval for radioactive packages expires on 841030 Renswal must be requested within 30 days of expiration If renewal not desired NRC should be so notified MACDUNALD, C E Transportation Certification Branch 84/08/28 SINK, J E Precision Inspection Ltd 1p 26332 046

#### DOCKET 71-0314 SMITH-EMERY CO

8408080182 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDONALD, C & Transportation Certification Branch 84/08/01 DUNHAM, M S @mith-Emery Co ip 25978 341

### DOCKET 71-0317 HUDBON PRODUCTS CORP

B40B310375 Advises that GA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired.NRC should be so notified MACDDNALD, C E Transportation Certification Branch 84/08/28 BENEFIELD, W E Hudson Products Corp ip 26352 047

## DOCKET 71-0318 MARATHON DIL CO

B408310372 Advises that GA program approval for radioactive packages expires on B41030 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MAGDONALD, C E Transportation Certification Branch B4/08/28 BARRE, C H Marathon Oil Co 1p 26332 043

#### DOCKET 71-0319 GENERAL TESTING & INSPECTION CO

B408080169 Advises that QA program approval for radioactive packages expires on B40930 Renewal must be requested within 30 days of expiration If renewal not desired.NRC should be so notified MACDUNALD C E Transportation Certification Branch 84/08/01 KRUEGEL R E General Test & Inspection 1p 25978 352

### DOCKET 71-0320 PITTSBURGH-DES MOINES STEEL CO

B40B0B0450 Advises that GA program approval for radioactive packages expires on B40930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDDNALD, C E Transportation Certification Branch B4/0B/01 STIGER, M H Pittsburgh-Des Moines Corp ip 25977 149

#### DOCKET 71-0322 BABCDCX & WILCOX CO

8408080097 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired.NRC should be so notified MACDDNALD.C E Transportation Certification Branch 84/08/01 LAWRENCE,M Babcock & Wilcox Co ip 25979 139

#### DOCKET 71-0325 CONSUMERS POWER CO

B408060327 Informs that QA insp program for radioactive packages expires on B40831 To continue QA program to be applied to packaging & transportation activities, renewal request should be made at least 30 days prior to expiration date MACDONALD.C E Transportation Certification Branch B4/07/30 NEAL.T P Consumers Power Co ip 25937 359

#### DOCKET 71-0326 INDUSTRIAL NOT SER DIVISION

8408080093 Advises that GA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDUNALD.C E Transportation Certification Branch 84/08/01 THOMPBON.J M Industrial NDT Co ip 25979 138

#### DOCKET 71-0327 PORTLAND GENERAL ELECTRIC CO

B40B06032B Informs that QA insp program for radioactive packages expires on 840B31 To continue QA program to be applied to packaging & transportation activities, renewal request should be made at least 30 days prior to expiration date MACDENALD, C E Transportation Certification Branch 84/07/30 NEAL.T P Portland General Electric Co 1p 25937 358

#### DOCKET 71-0328 PUBLIC SERVICE ELECTRIC & GAS CO

8408060370 Informs that QA insp program for radioactive packages expires on 840831 To continue QA program to be applied to packaging & transportation activities, renewal request should be made at least 30 days prior to expiration date MACDONALD.C & Transportation Certification Branch 84/07/30 MIDURA.H J Public Service Electric & Gas Co of New Jersey ip

### DOCKET 71-0329 HOWMET TURBINE COMPONENTS CORP

B40B310297 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDONALD. C E Transportation Certification Branch 84/08/28 BRANDBETTER. C Hounet Turbine Components Corp (subs Pechiney Ugine Kuhlmann Corp ) ip 26350 292

DOCKET 71-0330 ALLIED INSPECTION SERVICES, INC.

840B310350 Advises that GA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified MACDONALD.C & Transportation Certification Branch 84/08/28 ORASHAM, T D Allied Inspection Barvices, Inc. 1p. 26350-280

DOCKET 71-0522 CALIFORNIA, UNIV OF, LOS ANGELES, CA

8408150141 Forwards hardcopy of "GA Program for Shipment of Irradiated Fuel." confirming facsinise transmission on 840702 MEOST. W F California, Univ of, Los Angeles, CA 84/07/10 MACDUNALD,C E Transportation Certification Branch 1p 26104 178

--8408150143 "GA Program for Shipment of Unitradiated Fuel "

& California, Univ of, Los Angeles, CA 84/07/10 3pp

DOCKET 71-5805 MODEL CNS 3-55, CHEM-NUCLEAR SYSTEMS, INC

8408280324 Notification of registration as user of Model CNS 3-55, in response to 840731 request MACDONALD,C E Transportation Certification Branch 84/08/21 VDGEL.A K Baltimore Gas & Electric Co ip 26274 052

DOCKET 71-5926 MODEL GE-100, GENERAL ELECTRIC CO

840Bi&0290 Requests registration as user of Model GE-1000
MILLER, R I Sacramento Municipal Utility District 84/08/02
MAGDUNALD, C E Transportation Certification Branch 1p 26124 346

B408240202 Notification of registration as user of Model GE-100, in response to 840802 request MACDDNALD.C E Transportation Certification Branch B4/08/20 MILLER.R I Sacramento Municipal Utility District ip 26255 251

DOCKET 71-6244 MODEL 6244, CHEM-NUCLEAR SYSTEMS, INC

8408170021 Forwards response to request for add1 info & updated safety analysis in support of renewal of Contificate of Compliance \$244. Model 4-85
POPPE.L K Chem-Nuclear Systems, Inc 84/08/03 MACDUNALD, C E Transportation Certification Branch 10pp 26134 178

---B40B170023 Revised "SAR for Chem-Nuclear Sys. Inc Model 6244 (Model CNS 4-85) " \* Chem-Nuclear Systems. Inc 84/07/3! 11pp 26134 208

DOCKET 71-6346 MODEL FSV-1, GA TECHNOLOGIES, INC

IOBISO109 Forwards response to NRC 840619 request for add1 info re structural analysis of lead shielded canister within cask Failure at top flange region in skirt joining flange to canister body would not adversely affect canister shielding HUHRY, W R GA Technologies, Inc /General Atomic Co 84/07/27 MACBONALD. CE Transportation Certification Branch 15pp 24:104 392

--8408130114 Speech entitled, "Selection of Analytic Solutions & Experimental Results for Verification of Large Deformation Inslastic Dynamic Computer Programs," presented at Sept 1983 meeting in Poople's Republic of China KEY.8 W Re/Spec. Inc 83/08/31 21pp 26104 297

8408150542 Requests registration as user of Model FSV-1 OARRISON,R F Energy, Dept of 84/07/30 MACDONALD,C E Transportation Certification Branch 1p 26080 302

B408310073 Notification of registration as user of Model FSV-1 in response to 840730 request MACDONALD,C E Transportation Certification Branch 84/08/22 QARRISON,R F Energy, Dept of 1p 26350 185 DUCKET 71-6591 MODEL 51032-1 & 1A. EXXON NUCLEAR CO , INC

8408310170 Advises that Model 51032-1 % la packages meet requirements of 1973 IAEA for AF package, per 831130 request, Exxon Nuclear Co.Inc 830930 application & NRC 840529 approval MACDONALD, C E Transportation Certification Branch 84/08/24 RAML, R R Transportation, Dept of 1p 26351 350

DOCKET 71-6717 MODEL 6717-B, GAMMA INDUSTRIES

8408150122 Requests registration as user of Models 6717-8 & 20.204.50 & 504 504 SAMMONS.R J Dayton X-Ray Co 84/07/20 Division of Fuel Cycle & Material Bafety ip 26104 236

8408150607 Requests registration as user of Models 6717-8.20.20A.50 t 50A SAMMONS,R J Dayton X-Ray Co 84/07/20 Office of Nuclear Material Safety & Safeguards, Director 2pp 26098 362

8408310376 Notification of registration as user of Models 6717-8,20, 20A,30 & 50A, in response to B40720 request MACDDNALD,C E Transportation Certification Branch 84/08/22 SAMMONS,R J Dayton X-Ray Co ip 26350 264

DOCKET 71-9001 MODEL IF-300, GENERAL ELECTRIC CO

8408060420 Summary of 840726 maeting w/GE in Silver Spring.MD re renewal of Certificate of Compliance 9001 for Model IF-300 Agenda encl ODEGAARDEN.R H Transportation Certification Branch 84/07/27 Transportation Certification Branch 3pp 25937 341

DOCKET 71-9016 MODEL TN-9, NO USERS

8408140469 Forwards Rev O to "TN-8 & TN-9 SAR,First Addendum for TN-9 Packaging " GOLDMANN,K Transmuclear, Inc 84/06/26 MACDUNALD,C E Transportation Certification Branch 2pp 26061 297

--8408140476 Forwards fee for 840526 request for amond to Certificate of Compliance 9016 GCLDMANN, K Transnuclear, Inc 84/07/27 JACKSON, G License Fee Management Branch ip 26061 300

--8408140480 Requests amend fee for review of 840626 application to amend Centificate of Compliance 7016 JACKSON, G License Fee Management Branch 84/07/16 GOLDMANN, K Transnuclear, Inc. ip 26061 301

--8408140485 Rev 0 to "TN-8 & TN-9.First Addendum for TN-9 Packaging " \* Transnuclear, Inc 84/06/26 12pp 26061 302

8408150647 Forwards second addendum to TN-8 & TN-9 SAR Requests issuance of revised certificate of compliance for Model TN-9 packaging GULDMANN.K Transnuclear, Inc. 84/07/30 MACDUNALD,C E Transportation Certification Branch 2pp 26098 344

--8408150654 Rev O to "TN-8 & TH-9 SAR, Second Addendum for TN-9 Packaging " \* Transnuclear, Inc 84/07/30 12pp 26098 347

840Bi50594 Forwards "TN-8 & TN-9 SAR.Third Addendum for TN-9 Packaging " GOLDMANN,K Transnuclear, Inc 84/07/31 MACDONALD,C E Transportation Certification Branch 2pp 26:05 330

--8408150600 "TN-8 & TN-9 SAR, Third Addendum for TN-9 Packaging " \* Transnuclear, Inc 84/07/31 16pp 26105 333

8408310169 Advises that Certificate of Compliance 9016 amended to authorize shipment of 18 Comm Ed Dresden Unit 1 thoria spent fuel rods in modified D-1 canister placed inside Model TN-9 Approval record encl MACDONALD.C E Transportation Certification Branch 84/08/27 GDLDMANN.K Transportation 2pp 26351 351

- DOCKET 71-9021 MODEL 750, TECHNICAL OPERATIONS, INC.
- 8408020201 Application for renewal of Certificate of Compliance 9021 for Model 790 Type B parkage Fee encl MUNRD.J J Tech/Ops B4/07/09 MACDONALD.C E Transportation Certification Branch 2pp 28898 185
- DOCKET 71-9073 HODEL 04-142 SERIES \$ NUS 10-135, NUCLEAR PACKAGING,
- 8408130598 Requests registration as user of Model CH-142 SMEDIRA.C Neutron Products, Inc. 84/07/31 MACDONALD.C E Transportation Certification Branch 2pp 26080 359
- 8408150733 Application for amend to Certificate of Compliance 9073, adding design for Type B radwaste shipping cask Revs to Procedures WM-013, WM-022, WM-021, WM-021 & two oversize drawings enc. Aperture cards available in PDR Fee enc. VOIT, R E MUS Corp 84/07/31 MACDONALD, C E Transportation Certification Branch 3pp 26103 244
- ---8408190736 Rev E to Procedure WM-013, "Gamma Scanning of Lead Shielding for NUS Type Casks"

  MCCAY:S B NUS Corp 84/04/19 7pp 26103 247
- --8408150739 Rev A to Procedure W1-022. "NUS 10-135 Type B Maint " REAGAN.E E NUS Corp 84/07/31 13pp 26103 254
- --8408150742 Rev A to Procedure WM-021, "Operational Instructions for Loading & Unloading NUS 10-135 Type B Cask " REAGAN,E E NUS Corp 84/07/31 20pp 26103 267
- ---B408150744 Rev A to Procedure WM-023. "NUS PSC Halogen Leak Test Procedure for NUB 10-135 Type B Cask " REAGAN,E E NUS Corp 84/07/31 11pp 24103 287
- 8408240325 Notification of registration as user of Models OH-142 OH-142 MKI,OH-142 MKIB,OH-142 MKII in response to 840731 request MACDONALD,C & Transportation Certification Branch 84/08/20 TURKANIS,M Neutron Products, Inc. ip 26253 339
- B40B270580 Notification of registration as user of Models OH-142 & OH-142 kKK, MKIB & MKII, in response to 840808 request MACDONALD.C E Transportation Certification Branch 84/08/21 WITHERS.B D Portland General Electric Co Ip 26258 360
- DOCKET 71-9092 HODEL 1N-300, HITTMAN NUCLEAR & DEVELOPMENT CORP
- 8408020258 Withdraws 830930 application for renewal of Certificates of Compliance 9092. Rev I & 9093. Rev I due to type & activity of matls to be shipped in casks
  LEDUC, R J Hittman Nuclear & Development Corp (subs of Hittman Corp) 84/07/06 MACDONALD.C Transportation Certification
  Branch 2pp 25898 iio
- DOCKET 71-9093 MODEL HN-400, HITTMAN NUCLEAR & DEVELOPMENT CORP
- 8408020258 Withdraws 830933 application for renewal of Certificates of Compliance 9092.Rev 1 & 9093.Rev 1.due to type & activity of matls to be shipped in casks LEDUC.R J Hittman Nuclear & Development Corp (subs of Hittman Corp) 84/07/06 MACDUMALD.C Transportation Certification Branch 2pp 25898 10.
- DOCKET 71-9111 MODEL CNS 4-80-2 & CNS 4-80-24, CHCM-NUCLEAR SYS, INC
- 8408150602 Requests registration as user of Models CN5 6~80-2 & CNS 6-80-2A FLEISCHMANN.R Philadelphia Electric Co 84/07/27 MACDONALD.C & Transportation Certification Branch 2pp 26080 361
- B408240323 Notification of registration as user of Model CNS 6-80-2A in response to 840727 request MACDUNALD,C C Transportation Certification Branch 84/08/20 KNAPP,W J Philadelphia Electric Co 1p 26253 347

- DOCKET 71-9126 MODEL 20, 20A, 50, 50A, GAMMA INDUSTRIES
- 8408150122 Requests registration as user of Models 6717-B & 20,20A.50 & 50A SAMMONS,R J Dayton X-Ray Co 84/07/20 Division of Fuel Cycle & Material Safety 1p 26104 256
- 8408150607 Requests registration as user of Models 6717-B.20.20A.50 & 50A 50A SAMMONS.R J Dayton X-Ray Co 84/07/20 Office of Nuclear Material Safety & Saføguards.Director 2pp 26098 362
- 8408310376 Notification of registration as user of Models 6717-8.20, 204.50 % 504.in response to 840720 request MACDENALD.C E Transportation Certification Branch 84/08/22 SAMMONS.R J Dayton X-Ray Co 1p 26350 264
- DOCKET 71~9143 MODEL 920, TECHNICAL OPERATIONS, INC
- 8408310078 Notification of registration as user of Models 850 & 920 in response to 840724 request MACDDNALD.C E Transportation Certification Branch 84/08/22 BRITGII.D Atlas Foundry & Machine Co 1p 24050 184
- DOCKET 71-9147 MODEL BSO, TECHNICAL OPERATIONS, INC
- 8408150592 Requests registration as user of Model 850 MEHRER, R Atlas Foundry & Machine Co 84/07/24 MACDONALD, C E Transportation Certification Branch 2pp 26080 355
- 840831007B Notification of registration as user of Models B30 & 920 in response to B40724 request MACDCMALD.C E Transportation Certification Branch B4/08/22 BRITBILD Atlas Foundry & Machine Co ip 26330 184
- DOCKET 71-9151 MODEL HN-100 SERIES 3, CNS 14-170 SERIES III & NUS
- 8408160525 Requests registration as user of Model CNS 14-170 DIXON.O W South Carolina Electric & Gas Co B4/07/31 MACDONALD.C E Transportation Certification Branch ip 26122 353
- 8408270470 Notification of registration as user of Model CNS 14-170 III in response to 840731 request MACDDNALD: C E Transportation Certification Branch 84/08/20 NICHDLS: T C South Carolina Electric & Gas Co ip 26277 062
- DOCKET 71-9163 MODEL GNO-20, GULF NUCLEAR, INC
- 8408010025 Forwards Page 1 of Rev 2 to Type 8 GNG-20 container certification Requests amend so transportation of other model number sources can be made BEVILL.M Gulf Nuclear, Inc. 84/05/07 MACDDNALD,C E Transportation Certification Branch 3pp 25866 355
- --8408010028 Advises that unless fee for 840521 application for amend to Certificate of Compliance 9163 received within 30 days, NRC will consider application abandomed JACKSBON, G. License Fee Management Branch 84/07/12 BEVILL, M Gulf Nuclear, Inc. ip 25864 359
- --B408010031 Advises that minor amend fee required re B40507 application for amend to Certificate of Compliance 9163
  JACKSON, G License Fee Management Branch 84/05/21 BEVILL.M
  Gulf Nuclear, Inc. 1p 25866 360
- DDCKET 71-9184 MODEL PAS-1, NUCLEAR PACKAGING, INC
- 8408270970 Notification of registration as user of Model PAS-i in response to 840709 request MACDONALD, C E Transportation Certification Branch 84/08/21 YOUNG.K Iowa Electric Light & Power Co ip 26277 243
- DOCKET 71-9186 MODEL S-6213, ENERGY, DEPT OF
- 8408060269 Forwards request for add1 info re 840i13 application, as supplemented 840305, requesting approva) of Model UX-30 Revised affidavit for withholding should be submitted Response within 30 days of date of ltr requested MACDONALD, C E Transportation Certification Branch 84/07/26 TEMUS.C J Nuclear Packaging. Inc 3pp 25950 299

# DOCKET 71-9188 MODEL AP-300, ANEFCO. INC

8408030072 Return4 unreviewed 840309 application requesting approval of Model AP-300 Application incomplete & no response to NMSS 840321 ltr received MACDUNALD.C E Transportation Certification Branch 84/07/25 MURPHY.J D Anefco. Inc. 1p. 25917-345

#### DOCKET 71-9192 MODEL AP-300, ANEFCO, INC

B40B170070 Forwards response to questions re Model AP-300.Type A package & revised pages to BAR Comments requested MURPHY.J D Anafco. Inc 84/07/31 MCDDNALD.C NRC - No Detailed Affiliation Given 73pp 26/35 251

8408170204 Forwards revised pages to SAR for Model AP-300. Type A package, inadvertently omitted from 840731 response MURPHY, S Anefco. Inc. 84/08/03 MCDDNALD, C NRC - No Detailed Affiliation Given 7pp 26134 319

DOCKET 71-9193 MODEL NES-5, NUCLEAR ENERGY SERVICES, INC

84080/6020 Forwards request for addl info re 840618 application for approval of Model NES-5 Submittal date requested within 30 days MACDUNALD, C E Transportation Certification Branch 84/07/27 MAY, J R Nuclear Energy Services, Inc. 4pp. 25956 197

#### LICENSING OF INDEPENDENT SPENT FUEL STORAGE

## DOCKET 72-0001 MORRIS OPERATIONS, GENERAL ELECTRIC CO

8408130033 Responds to 840711 request for clarification of items identified during review of new rev to consolidated SAR. NEDO-21326 D Revised pages encl HERRINGTOM.C C General Electric Co 84/07/24 CUNNINGHAM.R E Division of Fuel Cycle & Material Safety 15pp 26058 330

B40B130590 Summary of 840726 meeting w/GE in Silver Spring, MD re GE response to r, onto an update of consolidated SAR for Morris Opera. P. ROBERTS, J.P. Agvanced Fuel & Spent Fuel Licensing Branch ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch 1p 2603B 313

8408160461 Dockets Rev 7 to NEDO-20776. "Spent Fuel Svcs Operation & GE U Mgt Corp QA Plan." u/WC Wheadon & DM Dawson 830329 &

0210 ltrs, respectively, to assure docket rile complete due to rev & resubmittal of rept as Rev 8 RØBERTS.JP Advanced Fuel & Spent Fuel Licensing Branch 84/00/10 Advanced Fuel & Spent Fuel Licensing Branch ip 26/26 078

--8408160466 Forwards Rev 7 to NEDD-20776, "Spent Fuel Svcs Operation & OE U Mgt Corp GA Plan " Rev due to organizational change within spent fuel svcs operation & GE U Mgt Corp WHEADON, W C General Electric Co 83/03/29 ROBERTS, J P NRC - No Detailed Affiliation Given ip 26/126/079

--B40B160472 Forwards Rev 7 to NEDO-20776. "Spent Fuel Svcs Operation & GE U Mgt Corp GA Plan." referenced in License SNM-2900 for GE Morris Operation & incorporated in NEDO-21326. App B-8 DAMSOUND M General Electric CO 83/02/10 ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 1p 26126 080

8408310269 PND-III-84-067 first of several spent reactor fuel shipments from Cooper Station arrived safely Rail shipment consisted of three NRC-certified shipping casks, each containing 18 spent fuel assemblies LOVENDALE. P. PAPERIELLO, C. J. Region 3, Office of Director 84/08/24 ip 26333 387

#### DUCKET 72-0002 VIRGINIA ELECTRIC & POWER CO

8408240009 Summary of 840810 meeting w/util.Bechtel & SAI in Silver Spring.MD re dry cask spent fuel storage application Meeting agenda & attendees list encl RGBERTS.JP Advanced Fuel & Spent Fuel Licensing Branch RDUSE.L C Advanced Fuel & Spent Fuel Licensing Branch 26252 353 24X Fiche 50-280,84/08/20,8408240009

1

# 10CFR COMMISSION MELTING RECORDS

- 8408010133 Staff requirements memo ro 840516 Commission vote determining that 10CFR90 97(c) should not be read to make GDC 17 inapplicable to low power operation CHILK-8 J Gffice of the Secretary of the Commission M8405168 Office of the Secretary of the Commission P4/05/19 Uffice of the Secretary of the Commission Ip 23873 312 24X Fiche 50-322, 84/05/18, 8408010133
- B40B06D417 Staff requirements memo re 840724 affirmation session in Washington.DC on review of ALAB-729 CHILF.S J Office of the Secretary of the Commission B40724C B407727 PLAINE.H H Office of the General Counsel 1p 25980
- 8408060434 Staff requirements memo re 840725 meeting on interpretation of Decision CLI-84-8 & reeram of exemption process CHILK/S J Office of the Secretary of the Commission M840723A 84/07/24 DIRCKS,N J Office of the Executive Director for Operations 2pp 25937 322 24X Fiche 50-322,84/07/26,8408040434
- B408080437 Revised staff requirements memo re 840725 discussion on interpretation of Decision CLI-84-8 & reexam of exemption process
  CHILK.S J Office of the Secretary of the Commission M840725A B407/27 DIRCKS,W J Office of the Executive Director for Operations PLAINE.H H Office of the Executive Legal Director 1p 25937 316 24X Fiche 50-322,84/07/27.8408060437
- B408040446 Staff requirements memo re B40726 discussion in Washington. DC requesting rept on role of NRC in contested licensing proceedings & status of effort to resolve ex parte & separation of function regulations CHILK.B J Office of the Secretary of the Commission MB40726A B4/07/26 DIRCKB.W J Office of the Executive Director for Operations PLAINE. H H Office of the Executive Legal Director TOURTELLOTTE, J Regulatory Reform Task Force 1p 25937 314
- 9408080024 Staff requirements memo re 840731 meeting in Washington, DC on industry views on terms important to safety & safety-related CHILV.6 J Office of the Secretary of the Commission N840731C 84/09/01 Office of the Secretary of the Commission 1p 25981 037
- 8408080216 Staff requirements memo re B40731 discussion/possible vote on full power OL in Washington, DC Commission voted 4-0 to authorize staff to issue full power OL amend CHILK, BJ Office of the Sucretary of the Commission MB40731B B470B701 DIRCKS, WJ Office of the Executive Director for Operations in 2597B 326 24X Fiche 50-416,84/0B/01,84080B0216
- 840B100150 Transcript of 840726 Commission public meeting in Washington DC re discussion of role of staff/ex parte Bupporting documentation encl # Commissioners 84/07/26 100pp 25796 348
- E408130004 Transcript of Commission 840726 affirmation/discussion & vote in Washington.DC re SECY-84-232 & ALAB-729 on TM1 hardware Pp 1-4 \* Commissioners ALAB-729 84/07/26 7pp 26011334
- B40B130013 Transcript of B40731 open meeting in Washington.DC rediscussion & vote on full power OL Pp 1-i14 Supporting documentation encl
  R Commissioners 84/07/31 129pp 26059 102 24x
  Fiche 50-416,84/07/31,840B130013

- 8408200407 Transcript of 840803 Commission meeting in Washington, DC rediscussion/possible vote on order concerning earthquakes & emergency planning Pp 1-8 \* Commissioners 84/08/03 12pp 26141 178 24X Fiche 50-275,84/08/03
- B40B200502 Transcript of 840731 Commission meeting in Washington.DC re industry views on "important to safety" & "safety-related " Pp 1-74 Industry presentations & viewgraphs encl \* Commissioners B4/07/31 106pp 26144 210
- 8408220338 Transcript of B40802 open meeting in Washington, DC re discussion/possible vote on full power DL Pp 1-195 Supporting documentation entl + Commissioners B4/08/02 222pp 26211 083 24x Fiche 50-275,84/08/02,8408220338
- #408240113 Transcript of 840816 Commission meeting in Washington, DC rediscussion/possible vote on final rolemaking on financial qualifications Pp 1-45

  \* Commissioners 84/08/16 47pp 26255 276
- 8408240424 Staff requirements memo re affirmation/discussion & vote danying 2 206 relief (SECY-84-203) approving order responding to petitions for review of ALAB-763 (SECY-84-254) & approving order denying LILCO 840717 motion (SECY-84-276) CHILY.5 J Office of the Secretary of the Commission M840817C 84/08/20 Office of the Secretary of the Commission 3pp 26248 269 24% Fiche 50-000, 84/08/20, 8408240424
- 8408280020 Transcript of 840814 Commission meeting in Washington,DC re affirmation/discussion & vote Pp 1-7 \* Commissioners 84/08/16 10pp 26294 013 24X Fiche 30-000.84/08/16.8408280020
- 8408280025 Transcript of 840816 Commission meeting in Washington DC recontinuation of 840723 discussion of adjudicatory proceeding Pp 1-76
  \* Commistioners 84/08/16 78pp 26273 169 24X
  Fiche 50-003.84/08/16.8408280025
- 8408280333 Staff requirements memo re 840816 continuation of 840723 discussion of issues requiring resolution prior to issuance of order in proceeding Commission requested briefing on PRA including discussion of uncertainties & basts of comparison CHILK.S J Office of the Secretary of the Commission B4/08/21 DIRCKS.W J Office of the Executive Director for Operations ZERBE.J E Office of Policy Evaluations 2pp 26294 050 24X Fiche 50-003.84/08/21.6408280333
- 8408300043 Staff requirements memo re 840816 discussion/possible vote on financial qualification rule Ofc of General Counsel should circulate final version prior to signature by secretary Expedition of decommissioning rule requested CHILK.B J Diffice of the Secretary of the Commission MB40816A 84/08/22 PLAINE.H H Office of the General Counsel DIRCKB,W J Office of the Executive Director for Operations ip 26/31/345
- 8408310423 Staff requirements memo summarizing 840815 oral presentations by parties re restart Commission requested Ammout provide names of individuals appropriate to carry out epidemiological study CHILK-S J Office of the Secretary of the Commission M840815 84708/27 DIRCKS-W J Office of the Executive Director for Operations 2pp 26363 047 24X Fiche 50-289,84/08/27,8408310423
- ACRE ADVISORY COMMITTEE ON REACTOR SAFEGUARDS
- 8408010009 Summary of ACRS Maint Practices & Procedures Subcommittee 840508 meeting in Washington, DC re NRC maint plan & R Borkowski presentation on in-plant reliability data program \* ACRS - Advisory Committee on Reactor Safoguards 84/07/11 ACRS - Advisory Committee on Reactor Safeguards 12pp 25897 122

- 8408010011 Summary of ACRS Reactor Operations Subcommittee 840503 meeting in Washington, DC re review of ACOD trends & patterns program plan # ACRS Advisory Committee on Reactor Safeguards 84/06/18 ACRS Advisory Committee on Reactor Safeguards 11pp 25871 25871 350
- 8408010015 Summary of ACRS Class-9 Accidents Subcommittee 840427 meeting in Washington.DC redreft NUREG-1070. "NRC Policy on Future Reactor Design Decisions on Severe Accident Issues in Nuclear Power Plant Design"

  # ACRS ~ Advisory Committee on Reactor Safeguards 84/07/02 ACRS Advisory Committee on Reactor Safeguards 17pp 25877
- 8408010017 Summary of ACRS Advanced Reactors Subcommittee 840612 meeting in Washington.DC re review of NRC/RES activities concerning LMFBR & advanced reactors research \* ACRS Advisory Committee on Reactor Safeguards 84/04/18 ACRS Advisory Committee on Reactor Safeguards 13pp 25897
- 8408010033 Summary of ACRS Electrical Sys Subcommittee 840501 meeting in Washington, DC re NSC programs in areas of electrical instrumentation & control for ACRS rept to Commission on
  - Therromentation of the PROCESS of Reactor Safeguards BACRS Advisory Committee on Reactor Safeguards Spo 25844 350
- 8408610111 Summary of ACRS Subcommittee on Air Sys 840426 meeting in Washington.DC re review of general design of essential chilled water sys & analysis & prioritization of new Generic Safety Issue 43, "Contamination of Instrument"

  \* ACRS Advisory Committee on Reactor Safeguards 84/06/15
  ACRS Advisory Committee on Reactor Safeguards 11pp 25873 341 25973 341
- 8408020170 Comments on ACRS 840604-05 consultant rept re modular test facility proposed by RES Analytical model improvements needed in several areas SULLIVAN.H ACRS Advisory Committee on Reactor Safeguards 84/06/11, BOEHNERT.P A ACRS Advisory Committee on Reactor Bafeguards 4pp 25898 072
- 8408020211 Comments on ACRS ECCS Subcommittee 840404 meeting he review of proposal of new modular test facility New facility if or proposal of new modular test facility New facility, if constructed/must have capability of allowing both integral & separate effects tests TIEN, C California Univ of, Berkeley, CA TIEN, C ACRS – Advisory Committee on Reactor Safeguards 84/06/29 BOCHNERT, P A ACRS – Advisory Committee on Reactor Safeguards 2pp 25898 168
- 8408020213 Comments on Metal Components Subcommittee 840517 & 18 meetings re pressurized thermal shock BENDER: M Affiliation Not Assigned BENDER: M ACRS-Committee on Reactor Safeguards 84/06/13 AXTMANN.R Advisory Committee on Reactor Safeguards 4pp 29898 ACRS - Advisoru TMANN, R ACRS 25898 164
- 8408020235 Forwards written comments on NUREO-1070, per Class-9 Accident Subcommittee meeting NUREO should state precisely whether new generation std plants will be safer than current
  - plants CORRADINI,M L. CORRADINI,M L. Michigan, Univ of Ann Arbor, NI CORRADINI,M L. ACRS - Advisory Committee on Reactor Safeguards 84/06/11 KERR,W ACRS - Advisory Committee on Reactor Safeguards KERR,W Michigan, Univ of Ann Arbor, MI 4pp 25898 189
- 8408020237 Comments on 840528 & 0702 meth re disposal of nuclear waste in unsaturated zone in comparison w/disposal in saturated zone in demonstrably impervious rock Math does not change validity of 840320 comments on NUREG-1046 PHILBRICK, S.S. Philbrick, S.S. PHILBRICK, S.S. ACRB Advisory Committee on Reactor Bafeguards 84/07/04 MOELLER, b.W. ACRB Advisory Committee on Reactor Safeguards 1p 25898 188
  - O8020242 Forwards comments on ACRS 840523 tour of plant site, in response to 840515 ltr MYSINGER.E D Tennessee Valley Authority 84/08/01 MCKINLEY response to 640313 itr MYSINGER.E D Tennessee Valley Authority 84/08/01 MCKINLEY.J C ACRS - Advisory Committee on Reactor Safeguards App 25878 157 24X Fiche 50-275,84/08/01,8408020242
- 8408020244 Forwards addl comments on 840498 draft severs accident policy statement, based on 840531 Class 9 accident BENDER: M Affillation Not Assigned. DENDER: M ACRS Advisory Committee on Reactor Safeguards 8406/07 KERR, W ACRS Advisory Committee on Reactor Safeguards 10pp 25898 147
- 8408020248 Summarizes DHR Subcommittee 840605 meeting re Unresolved Safety Issue A-45. "Shutdown DHR Requirement "Various studies do not contain all elements along heat flow path from heat source to heat sink CATTON. I ACRS Advisory Committee on Reactor Safeguards 84706/11 BOEHNERT,P ACRS Advisory Committee on Reactor Safeguards 2pp 23878 145

- 8408020250 Proposed minutes of ACRS Extreme External Phenomena 840404 meeting in Washington.DC re review of generic methodology for developing design basis severe winds for SEP plants & specific applications for Ginna Nuclear Power Plant # ACRS Advisory Committee on Reactor Safeguards 84/05/17 ACRS Advisory Committee on Reactor Safeguards 25pp 25898 120 24% Fiche 50-244,84/05/17,8408020250
- 8408020252 Summarizes ACRS ECCS Subcommittee 840604 meeting re voluce232 Summarizes ACRS ECCS Subcommittee 840,604 meeting re experimental resolution of issues # multi-party agreements w/vendors & others Facility dedicated to NRC needs & operated by NRC as necessary Committee on Reactor Safeguards CATTON, I ACRS - Advisory Committee on Reactor Safeguards 84/06/11 BOEHNERT, P ACRS - Advisory Committee on Reactor Safeguards 2pp 25898 118
- B408030091 Transcript of ACRS Subcommittee on ECCS 840731 meeting in Washington, DC Pp 1-272 Supporting documentation encl \* ACRS Advisory Committee on Reactor Safeguards B4/07/31 400pp 25909 030
- 8408030101 Attachments for transcript of ACRS Subcommittee on Gualification Program for Safety-Related Equipment 840730 meeting in Washington.DC Pp 1-326 # ACRS Advisory Committee on Reactor Safeguards 84/07/30 344pp 23906 024
- B408030204 Transcript of ACRS Subcommittee on Qualification Program for Safety-Rolated Equipment 840730 meeting in Washington DC Pp 1-326 \* ACRS - Advisory Committee on Reactor Safeguards 328pp 23916 146
- 8408140133 Transcript of ACRS 292nd meeting on 840810 in Washington DC Pp 210-576
  - ACRS Advisory Committee on Reactor Safeguards 84/08/10 358pp 26047 019
- 8408140203 Transcript of ACRS Subcommittee on Reactor Radiological Effects % Waste Mgt 840808 meeting in Washington, DC Pp 247-327 Supporting documentation encl # ACRS Advisory Committee on Reactor Safeguards 84/08/08 104pp 26045 207
- B408140206 Transcript of ACRS 292nd meeting on 840809 in Washington.BC Pp 187-217 Supporting documentation encl \* ACRS Advisory Committee on Reactor Safeguards 84/08/09 43pp 26045 311
- 8408140210 Transcript of ACRS Subcommittee on Reactor Radiological Effects & Waste Mgt 840807 meeting in Washington DC Pp 1-248 Supporting documentation encl \* ACRS Advisory Committee on Reactor Safeguards 84/08/07 276pp 26096 329
- 8408140212 Transcript of ACRS 292nd meeting on 840809 in Washington.DC Pp 1-188 Viewgraphs encl \* ACRS Advisory Committee on Reactor Safeguards 84/08/09
- 26054 001
- 8408140306 Attachments to transcript of ACRS 292nd meeting on 840810 in Washington.DC \* ACRB - Advisory Committee on Reactor Safeguards B4/08/10 26043 17
- 8408170287 Forwards summary of comments from ACRS 292nd meeting on 840809-11 in Washington, DC re draft DDE mission plan for civilian radwaste mgt program EBERGOLE, J C ACRS - Advisory Committee on Reactor Safeguards 84/08/13 DIRCKS, W J Office of the Executive Director for Operations Spp 26115 112
- B408170316 Summarizes ACRS 292nd meeting on 840809-11 re Task Action Plan A-43. "Shutdown DHR Requirements " Effort to apportion quantitative reliability goals among plant subsys endorsed EBERBOLE.J C ACRS Advisory Committee on Reactor Safeguards B4/08/14 DIRCKG/H J Office of the Executive Director for Operations 2pp 26114 280
- 8408170373 Summarizes ACRS 292nd meeting on 840809-11 re proposed amends to 10CFR60 concerning disposal of high level raduastes in geglogical repositaries Disposal in Unsaturated zone recognized as possible alternative EDERECLE. J C ACRB Advisory Committee on Reactor Safeguards 84/08/14 PALLADINO, N J Commissioners 2pp 26112 359

- 8408170378 Summarizes ACRS 292nd meeting on 840809-11 re NRC proposal to designate Ceneric Issue 23. Reactor Coolant Pump Seal Ceakage, as unresolved safety issue Higher priority rating should expedite satisfactory resolution EDERSOLE J C ACRS Advisory Committee on Reactor Safeguards 84708744 DIRCKS.W J Office of the Executive Director for Operations 2pp 26113 353
- 8408200074 Transcript of ACRS Subcommittee on ECCS 840604 meeting in Washington, DC Pp 1-263

  \*\* ACKS - Advisory Committee on Reactor Safeguards 84/06/04

  265pp 26143 001
- 840B200240 Corrected transcript of ACRS Subcommittee on DHR Sys 840605 meeting in Washington.DC Pp 1-234 \* ACRS Advisory Committee on Reactor Safeguards 84/06/05 235pp 26142 015
- B408270323 Summary of ACRS Subcommittee on ECCS 840502 meeting in Washington.DC re joint NRC/ISW Cuners Oroup/BEW/EPRI integral test program # ACRS Advisory Comnittee on Reactor Safeguards 84/07/12 ACRS Advisory Committee on Reactor Safeguards 37pp 24312 240
- 8408270333 Summary of ACRS Subcommittee on Safety Research Program 840509 meeting in Washington,DC ru proposed NRC safety research program & budget for FYB6 & B7 Viewgraphs encl # ACRS Advisory Committee on Reactor Safeguards 84/07/12 ACRS Advisory Committee on Reactor Safeguards 36pp 26311 36 24311 324
- 8408270335 Summary of ACRS Subcommittee on Metal Components 840517-18 meetings in Washington.DC re status of LNR water chemistry & effect on metal degradation & progress in pressurized thermal shock research program \* ACRS Advisory Committee on Reactor Safeguards 84/07/13 ACRB Advisory Committee on Reactor Safeguards 22pp 26311 302
- 8408290368 Summary of ACRS Subcommittees on Reactor Radiological Effects. Air Sys & Waste Mgt 840531-0601 meetings in Washington. DC re NRC proposed research programs & budget for FY86 & 87 & INPO rept on ALARA program implementation # ACRS Advisory Committee on Reactor Safeguards 84/07/13 ACRS Advisory Committee on Reactor Safeguards 18pp 26310 293
- 8408290369 Summary of ACRS Subcommittee on ECCS 840424 meeting in Washington.DC re OE BAFER/GESTR ECCS EM Code \* ACRB Advisory Committee on Reactor Safeguards 84/06/21 ACRS Advisory Committee on Reactor Safeguards 34pp 26310 259
- 8408290370 Summary of ACRS Subcommittee on Waste Mgt 840711 meeting in Washington DC re DDE draft mission plan for civilian radwaste mgt program NRC High Level Waste Oversight Cormittee rept & proposed amends to 10CFR60 \* ACRS Advisory Committee on Reactor Safeguards 84/07/23 ACRS Advisory Committee on Reactor Safeguards 13pp 26309 348
- 8408270371 Summary of ACRS 289th meeting on 840510-12 in Washington, DC Apps and Apps Advisory Committee on Reactor Bafeguards 210pp 84/05/12 26310 014
- 8408290534 Summary of ACRS 287th meeting on 840315-17 in Washington, DC Apps encl \* ACRS - Advisory Committee on Reactor Safeguards 84 ACRS - Advisory Committee on Reactor Safeguards 40pp 84/03/17 24312 344
- B408270342 Summary of ACRS Subcommittee on DHR Sys 840605 meeting in Washington.DC re resolution effort for Unresolved Safety Issue A-45, "Shutdoun DHR Sys" \* ACRS Advisory Committee on Reactor Safeguards 84/05/21 ACRS Advisory Committee on Reactor Safeguards 27pp 24310 232
- 8408270567 Summary of ACRS Subcommittee on Regulatory Activities 840612 meeting in Washington DC \* ACRE Advisory Committee on Reactor Safeguards 84/07/11 ACRE Advisory Committee on Reactor Safeguards 18pp 26309 330
- 8408300051 Summary of ACRS 288th meeting on 840405-07 in Washington DC Apps enc1 \* AGRS - Advisory Committee on Reactor Safeguards 84/4 AGRS - Advisory Committee on Reactor Safeguards 200pp 84/04/05
- 8408300245 Summary of 284th ACRS meeting on 840209-11 in Washington, DC Apps encl \* ACRB - Advisory Committee on Reactor Safeguards 84/0 ACRB - Advisory Committee on Reactor Safeguards 200pp 84/08/30

- 8408330286 Summary of ACRS Subcommittee on ECCS 840604 meeting in Washington,DC re review of NRC/RES thermal-hydraulic research program for rept to Commission on FY86-B7 budget a ACRS Advisory Committee on Reactor Safeguards 84/06/21 ACRS Advisory Committee on Reactor Safeguards 30pp 26330 24330 303
- 8408310227 Transcript of ACRS Subcommittee on Reliability & Probabilistic Assessment 840827 meeting in Windsor Locks.CT Pp 1-230 Supporting documentation enci \* ACRS Advisory Committee on Reactor Safeguards 84/08/2321pp 26319 281 24X Fiche 50-423.84/08/28.8408310227 84708728

#### NRC ADVISORY COMMITTEE ADVCM

- 8408020046 Transcript of 840712 meeting in Harrisburg.PA Pp i-113 Supporting documentation enci \* Advisory Council for Decontamination of TMF Unit 2 B4/07/11 183pp 25883 316 24% Fiche 50-320.84/07/12.8408020046
- B40B220444 Accepts resignation from Advisory Panel on Decontamination of TM1-2 Expresses approclation for & recognition of contributions made to activities of panel while serving as member since 1980
  PACLADINO.N J Commissioners B4/08/16 WAGNER, H N Johns Hopkin 80 Commissioners 84/08/16 WAGNER, HN Johns Hopkin tions: Baltimore, MD 3pp 26201351 24X Medical Institutions, Baltimore, MD Fiche 50-320, 84/08/16, 8408220444
- --B40822044B Submits ltr of resignation from Citizen Advisory Panel on Decontamination of TMI-2 WAGNER.H N Johns Hopkins Medical Institutions, Baltimore, MD WAGNER.H N Advisory Council for Decontamination of TMI Unit 2 B4/07/09 PALLADING.N J Commissioners ip 26201 354 24X Fiche 50-320, 84/08/16, 8408220444
- 8408270076 Transcript of THI Advisory Panel on TMI Unit 2 Decontamination on 840807 public meeting in Harrisburg, PA PP 1-33 Supporting documentation enci # Advisory Council for Decontamination of TMI Unit 2 84 138pp 26257 048 24% Fiche 50-320,84/08/09,8408270076 84/08/09
- 8408290154 Accepts resignation as member of Advisory Panel for Decontamination for TMI-2 Certificate of appreciation encl PALLADINO,N J Commissioners 84708/16 WAGNER,H N Affi Not Assigned 2pp 26311 360 24% Fiche 50-320,84708/16, 8408290154 Affiliation

#### COMMISSION NRC COMMISSIONERS

- 8403180145 Responds to 840314 ltr to Chairman Palladino which encl W & V Smelser concern re Marble Hill & Bailly cancellation, withdrawal of util application for Zimmer & denial of license for Byron facility
  DIRCKS, W J Office of the Executive Director for Operations 84405704 LUGAR.R G Senate 7pp 24524 325 24X
  Fiche 50-000,84/05/04,8405180145
- --8405180152 Requests response to each W & V Smelser 840210 inquiry in NRC attitude toward utils Concerns include Marble Hill & Bailly cancellation, ulthdrawal of util application for Zimmer & denial of license for Byron facility LUGAR:R G Benate 84/03/14 PALLADING.N Commissioners 3pp 24524°331 24X Fiche 50~000,84/03/04.8405180145
- B40B010061 Further response to F01A request for 16 categories of records refacility Documents identified by J Goolf & H Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing FELTON.J H Oivision of Rules and Records BX14 000 B4/07/18 RICE.C M Kirkland & Ellis 2pp 26500 001
- --B204060008 Summarizes 266th ACRS meeting on 820603-05 Subj to satisfactorily completion of const & staffing & if due regard given to ACRS comments, plant can operate at 5% power w/o undue risk to public Full power recommendation deterred SHEMMON,P ACRS Advisory Committee on Reactor Safeguards 6004 82/06/08 PALLADINO,N Commissioners 6pp 26500 028
- 8408010275 Responds to 840208 itr re concerns over perceived tendency by staff to assume that margins of safety established by criteria need not be adhered to for sys not pivotal to DIRCKS, W J Office of the Executive Director for Operations 84/07/20 PANEITAL House of Rep 9pp 25872 342 24X
- --8408010277 Requests preparation of response to Panetta 840208 ltr on concerns to GA hearing PALLADIND.N J Commissioners 84/04/19 DIRCKS.H J Office of the Executive Director for Operations ip 25872 351, 24X Fiche 50-275,84/07/20,8408010275

- IOBO70201 Responds to 840522 ltr re plant problems & estimate of when plant fully operational Commission meeting for briefing & possible vote on full-power OL scheduled on 840731
  DIRCKS W J Office of the Executive Director for Operations 84/07/27 SETHUNE E House of Rep 3pp 25957 066 24% Fichs 50-416.84/07/27.8408070201
- -8408070207 Requests encl Insert A re minor plant problems not delaying full power licensing be placed in Dircks 840727 ltr draft SCINTO. J NRC No Detailed Affiliation Given 84/07/02 ADENBAM. E NRC No Detailed Affiliation Given 3pp 25957 071 24X Fiche 30-416, 84/07/27. 8408070201
- -8408070215 Requests info re spec & surveillance problems at plant & stimate of when plant will be fully operational BETHUNE:E House of Rep 84/03/22 PALLADINO, N Commissioners ip 25957 075 24X Fiche 50-416.84/07/27,8408070201
- 408070211 Ack receipt of 840622 ltr to Palladine requesting infore safety questions raised by JN Huber Concerns highlighted in Huber 830309 list, encompassing design, const & testing, involve no violations of NRC regulations DIRCKS.W J Office of the Executive Director for Operations 84/07/25 CARLEY.W House of Rep 4pp 29937 054 24X Fiche 50-322,84/07/25,8408070211
- -8408070217 Forwards JW Huber 840612 ltr re safety questions noted during employment by util Info addressing Huber contentions requested t/840611 telcon record CARNEY,W House of Rep. 84/06/22 PALLADING.N J Commissioners 3pp 25957 057 24% Fiche 50-322,84/07/25,8408070211
- 408080034 Ack receipt of 840612 ltr re NRC assistance to State of TX on programs for developing low level radwaste disposal capacity NRC uill provide State of TX to ther Agreement States w/technical assistance appropriate to needs PALLADING.N J Commissioners 84/07/20 WHITE.M Texas, State of 2pp 25781 061
- -8408080038 Encourages NRC to ensure adequate resources for assistance to states in complying w/iOCFR61 re low level radwaste disposal WHITE. M Texas. State of 84/06/12 PALLADIND, N Commissioners ip 20961 063
- I408080082 Responds to 840514 ltr to Palladino commenting on 100FR30 34 permitting deviations from Tech Specs in emergency & requesting regulation be canceled Lists circumstances which must exist before rule can be used DENTON.H R Defice of Nuclear Reactor Regulation. Director 84/07/26 YOUNG.C Affiliation Not Assigned 14pp 25978 264 24X Fiche 50-320,84/07/26,8408080882
- -8408080087 Reaffirms recommendations stated in B40503 ltr re canceling regulations permitting licensee to deviate from Tech Specs in emergency & ensuring that president of facility implement policy to operate in accordance 4/OL & Tech Specs YOUNG, C Affiliation Not Assigned 84/06/14 PALLADING, N J Commissioners 8pp 25978 276 24x Fiche 50-320,84/07/26,8408080082
- MOBOBO384 Discusses Jurisdictional issue re EPA proposed environ stds for Mgt & disposal of spent nuclear fuel & NRC regulation 10CFR40 Mod to 10CFR40 appropriate to incorporate EPA proposed assurance requirements ROBERTS.T M Commissioners 84/07/19 RUCKELSHAUS, W Environmental Protection Agency 2pp 25978 085
- 408080427 Regrets to learn of death of Z Bartolome PALLADING.N J Commissioners 84/07/29 VER ALBANG.A Philippines. Govt of 1p 25977 189
- IAGROBO430 Responds to 840531 ltr raising concerns re NRC 840522 order & continued log power operation in spite of outstanding issues of compliance w/ODC 17 Asselstine opinion encl PALLADINO.N J Commissioners 84/07/23 MARKEY.E J House of Rep. Interior & Insular Affairs 3pp 25977 184 24% Fiche 50-416,84/07/23,8408080430
- ~8408080432 Expresses concern re NRC apparent abandonment of agency regulations w/licensing of plant Overwhelming weight of evidence creates impression that operation of plant constitutes violation of NRC regulations MARMEY,E J. House of Rep. Interior & Insular Affairs 84/05/31 PALLADIND,N J. Commissioners 2pp 25977.187 24X Fiche 50~416,84/07/23,8408080430
- 408080486 Weekly info rept for whending 840727.
  REHM.T A Office of the Executive Director for Operations
  84/08/02 41pp 23976 013

- 8408090102 Responds to 840514 request for Commission generic resolution of safety equipment classification issue Issue addressed in Commission 840606 Order CLI-84-9 Rulemaking proceeding initiated PLAINE. H H Office of the General Counsel CLI-84-9 84/07/25 HARGNEL, B L Utility Safety Classification Group 2pp 25991 237
- --8403070106 Comments on MRC 840511 briefing re-safety classification issue \*\* requests opportunity to discuss issue \*\*/Commission HARSHE, B L Utility Safety Classification Group 84/06/14 PALL4DINO.N Commissioners 3pp 25791 249
- 8408070109 Forwards "Annual Rept for 1983 on Administration of Govt in Sunshine Act of 1974 ' PALLADINO.N J Commissioners 84/07/25 O'NEILL,TP House of Rep Speaker of the Mouse Ip 25991 214
- --8409070111 Forwards "Annual Rept for 1983 on Administration of Govt in Sunshine Act of 1976 ' PALLADIND, N J Commissioners 84/07/25 BUSH, G Senate, President of the Senate in 25991 215
- --8408090113 "Annual Rept for 1983 on Administration of Govt in Bunshine Act of 1976 "
  \* Commissioners 84/07/25 Zipb 25991 216
- 840B070216 Forwards NRC comments re DDE draft "Mission Plan for Civilian Radwaste Mgt Program " NRC objections based on regulatory info needs establishment of performance goals & need for add1 consultation w/NRC Asselstine comments encl PALLADINO.N J Commissioners 84/07/31 RUSCHE, B C Energy, Dept of 57pp 25792 013
- 8408130202 Responds to 840330 ltr re deficiencies at facility NRC unaware of serious defects at plant Enforcement action still pending re natl false statements in operator records DIRCKS,W J Office of the Executive Director for Operations 84/07/31 ANTHONY, B House of Rep 46pp 26060 166 24X Fiche 50-416.84/07/31.8408130202
- --8409130210 Requests info re deficiencies in design & const of plant & in qualification & training of staff Raises concerns on possibility of higher costs being passed on to constituents ANTHONY. B House of Rep 84/03/30 PALLADING. N J Commissioners 4pp 26060 213 24% Fiche 50-416.84/07/31, 8408130202
- 8408160030 Weekly info rept for wk ending 840803 REHM,T A Office of the Executive Director for Operations 84/08/10 35pp 26128 175
- 8408200225 Discusses Tach Spec arrors discovered subsequent to NRC approval Susquehanna Tech Spec amends had no safety w/no significance itcOuire Tech Specs still under review w/no identified safety significance thus far ASSELBTINE. J K Commissioners 84/08/10 MARKEY. E J House of Rep. Interior & Insular Affairs 4pp 26141 244 24X Fiche 50-000.84/08/10.8408200225
- --B408200235 Forwards technical evaluation rept re Tech Spec audit Only discrepancy involved lack of quantitative criteria for limit switch setting & calibr for suppression chamber vacuum breakers Util should resolve rept recommendations STARIOSTECKI.R Division of Project & Resident Programs B4/04/10 E1SENHUT. D D Division of Licensing Spp 24141 242 24X Fiche 50-000,84/08/10,8408200225
- --8404040095 Forwards "Audit of Susquehanna Unit 2 Tech Specs," technical evaluation rept FANDEY,5 Franklin Institute/Franklin Research Center NRC-03-B1-130 84/03/30 CARRINGTON,M NRC No Detailed Afriliation Oliven 1p 26141 265 24% Fiche 50-000,84/08/10,8408200225
- ---B40404009B TER-C5506-524

  "Audit of Susquehanna Unit 2 Tech Specs." technical evaluation rept
  BACANBKAB,V P. MURPHY,J A Franklin Institute/Franklin Research Center NRC-03-B1-130 B4/03/30 BETTENHAUSEN.L., MCCABE,E NRC-No Detailed Affiliation Given 26pp 26141 266 24X
  Ficho 50-000,84/08/10.8408900225
- --8408200263 Forwards IE Insp Rept 50-416/84-11 on 840328-30 & notice of deviation LEWIB,R C Division of Project & Resident Programs 84/04/24 RICHARD, J B Mississippi Power & Light Co 2pp 26141 330 24X Fiche 50-000,84/08/10.8408200225
- --8408200267 Notice of deviation from insp on 840328-30 \* Region 2, Office of Director 84/04/24 ip 26141 332 24x Fiche 50-000,84/08/10.8408200225

- -B+U32:10271 IE Insp Rept 50-416/84-11 on 840328-30 Deviation noted no surveillunce procedure established to periodically test renote shutdown control components t components not tested since preoperational testing CALDWEIL J.L., HEHL.C.W., JULIAN.C.A. Region 2, Office of Director 84/04/24 7pp 26141-333 24X Fiche 50-000.84/08/10.84082/0225
- --B408200279 Requests further info re Tech Spec errors for specs approved since TMI-2 episode Info re near-term OL activities also requested MARKEY.E J. House of Rop. Interior ? Insular Affairs B4/07/12 PALLADING.N J. Commissioners ip 26112 002 24X
- 8408220444 Accepts resignation from Advisory Panel on Decontamination of IMI-2 Expresses appreciation for & recognition of contributions nade to activities of panel while serving as member since 1980 PALLADIND, N. J. Commissioners 84/08/16 WAGNER, H. N. Johns Hopkins Medical Institutions, Baltimore, MD. 3pp. 26201 351 24 X. Fichs 50-320,84/08/16,8408220444
- --8409220448 Subnits ltr of resignation from Citizen Advisory Panel on Decontamination of TMI-2
  WAONER:H N Johns Hopkins Medical Institutions, Baltimore, MD WAONER:H N Advisory Council for Decontamination of TMI Unit 281/07/09 PALLADINO,N J Commissioners ip 26201354 24X Fiche 50-320.84/08/16.8408220444
- 8408280467 Ack receipt of 840/02 ltr & invitation to observe 840819 energency electise Tentative arrangements made for NRC representatives to attend exercise at Kori II in Sept in lieu of personal attendance by Chairman PKLLADINO.N J Commissioners 84/08/13 JUNG-KI,P Korea Electric Co ip 26294 113
- --8408260471 Expresses thanks for meeting during recent visit & extends invitation to observe 840819 emergency response exercise against radioactive ratl leakage in Korea JUNG-KI,P Korea Electric Co 84/07/02 PALLADING,N J Commissioners 2pp 26294 114
- B408290154 Accepts resignation as member of Advisory Panel for Decontamination for TMI-2 Cortificate of appreciation and PALLADINO.N J Commissioners B4/08/16 WAGNER.H N Affiliation Not Assigned 2pp 26311 360 24X Fiche 50-320.84/08/16. B408290154
- 8408270348 Responds to 840703 request for suggestions re preparation of fifth Natl Energy Policy Plan Addressing of future matl electricity supply & projected mix of coal & nuclear power in supply recommended PALLADINO.N J Commissioners 84/08/15 HDDEL.D P Energy, Dept of 1p 26313 267
- ---8408270330 Requests proposals for strategies, programs & initiatives for consideration during preparation of fifth Natl Energy Policy Plan (NEPP) Input requested by 840701 Fourth NEPP encl HODEL, DP Energy, Dept of 84/07/03 PALLADING, N J Commissioners 1p 26311 268
- --8408290352 DUE/S-0014/L
  "Natl Energy Palicy Plan"
  \* Energy, Dapt of 83/10/31 27pp 26311 269
- 8408290336 Forwards 20th joint quarterly status rept re emergency preparedness covering period through 840630 No delay in current licensing proceedings due to emergency preparedness issues

  BERNTHAL.F M Commissioners GIUFFRIDA.L O Federal Emergency Management Agency 84/08/07 SIMPSON.A K Senate. Environment & Public Works 1p 26310-311
- --8408270359 "NRC/FEMA Joint Quarterly Rept to Congress on Emergancy Preparedness, Through 840630 " \* NRC - No Detailed Affiliation Given \* Federal Emergency Management Agency 84/06/30 46pp 26310 312
- 8408300290 Weekly info rept for wk ending 840817 REHM,TA Office of the Executive Director for Operations 84/08/23 40pp 26329 313

- CONTRACT NRC CONTRACTS AND MODIFICATIONS
- 8408010041 Notification of contract execution Mod 3, to "Support Sycs for Research & Evaluation of Severe Accident Phenomenon & Mitigation "Contractor Battelle Columbus Labs WILLETI'S Technical Assistance Contracts Branch FIN B-7499 NRC-04-84-127 84/07/24 BATSON W Office of Nuclear Regulatory Research, Director LARKINS, J NRC No Detailed Affiliation Given ip 28866 347
- --8408010048 Mod 3.providing incremental funding to "Support Svcs for Evaluation of Severe Accident Phenomenon & Mitigation " \* Bittelle Memorial Institute, Columbus Laboratories SMITH.P A Division of Contracts FIN 8-7499 NRC-04-84-127 84/07/24 ip 25866-348
- 8408010175 Notification of contract execution, Mod 7, to "Geotechnical Assistance" Contractor VS Army Corps of Engineers FLEENOR. C Technical Assistance Contracts Branch NRC-02~Bi-036 84/05/14 DAVIS. J Office of Nuclear Material Bafety & Safeguards, Director RESTURDOY, K NRC No Detailed Affiliation Oiven 1p 25873 302
- --8408010182 Mod 7, designating NRC project officer to replace project officer identified under agreement to "Geotechnical Assistance"

  \* Army, Dept of Corps of Engineers SMITH,P A Division of Contracts NRC-02-81-036 84/05/14 1p 25873 303
- 8408040014 Notification of contract execution, Mod 2, to "Maint & Operation of LPDRs " Contractor Clermont County, OH Public Library HOPPER.A Administrative Contracts Branch NRC-10-83-740
  - Library HOPPER, A Administrative Contracts Branch NRC-10-83-740 84/07/20 FELTON, J M Division of Rules and Records SDUDER, J NRC - No Detailed Affiliation Given 1p 29936 352
- --8408060017 Mod 2.extending period of performance until 850921 & increasing funds, to "Maint & Operation of LPDRs "

  \* Clermont County, OH HAGAN,T F Division of Contracts NRC-10-83-740 84/07/20 2pp 25936 353
- B40B060918 Notification of contract execution Mod 2 to "Maint & Operation of LPDRs" Contractor Rochester.NY Public Library HOPPER.A Administrative Contracts Branch NRC-10-83-729 B4/07/24 FELTCR.J M Division of Rules and Records EDUDER. NRC No Detailed Affiliation Given 1p 28936 355
- --8408060025 Mod 2.extending goriod of performance until 850916 & increasing funding to "Maint & Operation of LPDRs"

  \* Rochester, NY HAGAN,T F Division of Contracts
  NRC-10-83-729 84/07/24 2pp 25936 356
- 8408060031 Notification of contract execution, Mod 2, to "Maint & Operation of LPDRs" Contractor WH Abel Memorial Library, Montesano, MA HOPPER, A Administrative Contracts Branch NRC-10-83-753 84/07/24 FELTON, J M Division of Rules and Records BOUDER, J L NRC No Detailed Affiliation Given ip 25937 071
- --8408060037 Mod 2, extending period of performance until 850727 & increasing funding to "Maint & Operation of LPDRs" # Hontesano, WA HAGAN, T F Division of Contracts NRC-10-83-765 84/07/24 2pp 25737 072
- 8408060038 Notification of contract execution Med 2, to "Maint & Operation of LPDRs" Contractor Merris, IL Public Library HOYLE.A Administrative Contracts Branch NRC-10-83-735 84/06/19 FELTON.J II Division of Rules and Records 80UDER.J NRC No Detailed Affiliation Given 1p 25937 074
- --8408060040 Mod 2 extending period of performance until 850505 & increasing funds to "Haint & Operation of LPDRs "

  Horris, IL HAGAN, TF Division of Contracts NRC-10-83-735 B4/06/19 ip 25937 075
- 8408060041 Notification of contract execution. Mod 2. to "Maint & Operation of LPDRs" Contractor Indian River Community College HOPPER, A Administrative Contracts Branch NRC-10-83-750 84/07/24 FELTON, J M Division of Rules and Records BOUDER, J L NRC No Datailed Affiliation Given 1p 25937 092
- --8408060048 Mod 2.extending period of performance until 850914 & increasing funding to "Maint & Operation of LPDRs"

  \* Indian River Community College, Ft Pierce, Ft HADAN, T F
  Division of Contracts NRC-10-83-750 84/07/24 2pp 25937 093

- 8408040P11 Notification or contract execution Mod 2 to 'Maint & Operation of LPDRs ' Confractor Madison-Jefferson County Public Library
  - PODIC LIBRARY
    HDPPER, A Administrative Contracts Branch NRC-10-83-741
    84/07/24 FELTON, J M Division of Rules and Records SDUDER, J L
    NRC No Detailed Affiliation Given 1p 25936 180
- --8409060214 Mod 2.extending period of performance to 850916 & increasing funds.to "Kaint & Operation of LPDRs "
  BABBITT.D L Madison. IN HAGAN.T F Division of Contracts
  NRC-10-83-741 84/07/24 2pp 25936 181
- 8408060424 Notification of grant execution Mod 1.to 'Preliminary Analysis of Procedures for Calibr of Short Circuit Currents in Electrical Penetration Assemblies ' Grantee Tuskegee
- unse UMBEL.D Technical Assistance Contracts Branch FIN G-1059 NRC-G-04-84-003 84/07/24 BATSON.W Office of Nuclear Regulatory Research. Director SULI IVAN.D NRC No Detailed Affiliation Given ip 25937 336
- --84080&042& Mod i.extending period of performance to 841114.to
  "Preliminary Analysis of Procedures for Calibr of Short
  Circuit Currents in Electrical Penetration Assemblies" WILLIAMS, L A Tuskegee Institute Tuskegee AL Technical Assistance Contracts Branch FIN 0-1059 NRC-0-04-84-003 84/07/24 1p 25937 337 MERTON, K V
- 8408070047 Notification of contract execution, Mod 1.to "Technical Assistance to Support IE Personnel in Integrated Design Insps" Contractor Wester Sycs, Inc. MOLLETT. 6. Technical Assistance Contracts Branch FIN 8-8719 NRC-05-84-151 94/07/25 MURRA Director's Office, Office of Inspection and Enforcement MILHOAN, J NRC No Detailed Affiliation Given 1p 25955 338
- --B408070053 Mod 1, providing incremental funding & specifying period of performance, to "Technical Assistance to Support IE Personnel in Integrated Design Insps "

  \* NEGREC Services, Inc. SMITH.P A Division of Contracts FIN B-B719 NRC-05-B4-151 B4/07/25 1p 25955 339
- 8408070080 Notification of contract execution, Mod 1, to "Hydrogeologic Evaluations of U Recovery Facilities " Contractor Williams Assoc, Inc & Assoc.inc BAISDEN.L Technical Assistance Contracts Branch FIN B-8505 NRC-31-84-501 84/07/26 ROSE.H Uranium Recovery Field Office HILDENBRAND,P NRC - No Detailed Affiliation Given 1p 25957 093
- --8408070087 Mod i, changing contract number & obligation amount, to "Hydrogeologic Evaluations of U Recovery Facilities "

  \* Williams & Associates MORION.K V Division of Contracts FIN B-8505 NRC-31-84-501 84/07/26 2pp 25957 094
- B408070101 Notification of contract execution, Mod 3, to "Low Level Nuclear Waste Processing & Shallow Land Burnal Trench Isolation "Contractor Univ of Artiona UMBELD Technical Assistance Contracts Branch FIN 8-7072 NRC-04-81-220 84/07/25 BATSON.W Office of Nuclear Reactor Regulation, Director O'DDNNEL, E NRC No Detailed Affiliation Given 1p 25955 224
- -8408070104 Mod 3.changing co-principal investigator, to "Low Level Nuclear Waste Processing & Shallow Land Burial Trench Isolation " lablation " WHEELER, J T Arizona, Gtate of SMITH,P A Technical Assistance Contracts Branch FIN 8-7072 NRC-04-81-220 84/07/25 2pp Contracts Branch
- 8408080005 Notification of grant execution "American Statistical Assoc Conference on Radiation & Health," awarded to American Statistical Assoc UMBEL. D Technical Assistance Contracts Branch FIN 0-1072 NRC-0-04-84-008 84/07/31 BATSON.W Office of Nuclear Regulatory Research, Director GINEVAN.M E NRC No Detailed Affiliation Given. 2pp 25982 170
- --8408080008 Grant "American Statistical Assoc Conference on Radiation & Health." awarded to American Statistical Assoc DENENDERS, E American Statistical Association MORTON, K V Research Contracts Branch FIN G-1072 NRC-G-04-84-008 84/07/31 ip 25982 172
- 8408080020 Notification of contract execution "Region IV Data Entry Bvcs," awarded to AIC Analysts Corp HAGEY.H Administrative Contracts Branch NRC-33-84-383 84/07/06 BASSET,H S Division of Data Automation & Management Information KAY.B NRC No Detailed Affiliation Given ip 25781 038
- --8408080025 Ltr Contract NRC-33-84-383 "Region IV Data Entry Svc." awarded to AIC Analysts Corp MATTIA:M J Division of Contracts NRC-33-84-383 84/07/05 DOMERTY,M J AIC Analysts Corp 15pp 23981 039

- 8408080052 Nutification of confract execution, Mod 2, to Nuclear Power Plant Operations Courses "contractor Chattanooga State Technical Community College UMBEL D Technical Assistance Contracts Branch FIN B-1279 NRC-05-81-251 84/07/31 BLAHALJ Program Support Analysis Staff ROESSLER, S D NRC No Detailed Affiliation Givon 1p 259B1 067
- --B40B0B0004 Mod 2, extending period of performance % obligating funds to "Nuclear Power Plant Operations Course" BRANCH,C W Chattanooga State Technical Community College, Chattanooga, TN SHITH,PA Technical Assistance Contracts Branch Flw 8-1277 NRC-08-81-251 84/07/31 2pp 25981 068
- 8408080059 Notification or contract execution.Mod 2.to "Maint & Operation of LPDRs" Contractor Wheeler Basin Regional HOPPER, A Administrative Contracts Branch NRC-10-8: 84/07/26 FELTON, J M Division of Rules and Records NRC - No Detailed Affiliation Given 1p 25981 080 NRC-10-83-751
- --8408080067 Mod 2.extending period of performance to 850916 & increasing funding to "Maint & Operation of LPDRs"

  \* Wheeler Basin Regional Library, Decatur, AL HAGAN, T F
  Division of Contracts NRC-10-83-751 84/07/26 ip 25981 081
- 8408080317 Notification of contract execution, Mod 1, to "Hydrogeologic Evaluations" Contractor INTERA Technologies, Inc UMBEL.D Technical Assistance Contracts Branch Fin B-7384 NRC-02-83-041 84/08/01 BRCWN, R S Program Support Branch WIDMAYER, D NRC No Detailed Affiliation Given 1p 25978 205
- --0408080321 Mod 1.adding FY84 funds & changing company name & principal investigator to, "Hydrogeologic Evaluations" PANHA.S 8 INTERA Technologies, Inc SMITH,P A Division of Contracts FIN 8-7384 NRC-02-83-041 84/08/01 2pp 25978 206
- 8408080476 Natification of contract execution, Mod 6, to "Shuttle Bus Svc " Contractor Beltway Limousine Svc BROMBERG, B J Administrative Contracts Branch NRC-10-82-378 84/08/01 CORLEYJ Division of Facility Operations GRANT, L No Detailed Affiliation Given 1p 25976 059
- --8408080480 Mod 6.deobligating funds to enable contract closeout.to "Shuttle Bus Svr" Contractor Beltway Limousine Svc ROBERTSON.J Beltway Limousine Service, Inc HAGAN,T F Division of Contracts NRC-10-82-378 B4/08/01 1p 25976 040
- 8408090502 Notification of contract execution.Mod 24, Task 62, to "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents " Contractor Parameter, Inc MDLLETT, S Technical Assistance Contracts Branch FIN B-1302 NRC-05-82-247 84/07/18 BLAHA, J Director's Office, Office of Inspection and Enforcement LAUDAN, W NRC No Detailed Affiliation Given 1p 25976 008
- --8408080507 Mod 24 Task 62 adding RCS leak rate for PWRs, to "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents" Incidents " LOFY,R A Parameter, Inc SMITH.P A Division of Contracts FIN B-1302 NRC-05-82-249 84/07/18 4pp 28976 009
- 8408090041 Notification of grant execution.Mod 7.to "Experimental Phase of Development of Noninvasive Liquid Level & Density Gauge for Nuclear Power Reactor Vessels " Grantee Pennsylvania State Univ UMBEL.D Technical Assistance Contracts Branch FIN G-1029 NRC-G-04-81-024 84/07/31 BATSON.W Office of Nuclear Regulatory Research, Director CHEN.Y NRC No Detailed Affiliation Given ip 20991 290
- --8408070044 Mod 7, providing addl funds & extending period of performance to 850531, to "Experimental Phase of Development of Noninvasive Liquid Level & Density Gauge for Nuclear Power Reactor Vessels " Reactor Vessels "
  BAKER,R H Pennsylvania State Univ. University Park, PA
  HORTON,K V Research Contracts Branch FIN 9-1029
  NRC-0-04-81-024 84/07/31 ip 25991 291
- 8408090072 Notification of contract execution "Technical Assistance 40B09VD/2 Notification of contract execution "lechnical Assistance for Support of Const Appraisal Team (CAT) Insps " Contractor Parameter: Inc WIGOING, E. Technical Agsistance Contracts Branch FIN B-8718 NRC-05-84-132 B4/07/31 DEYCUNG.R C Director's Office: Office: Inspection and Enforcement LOFY, R NRC - No Detailed Affiliation Given 1p 25991 257
- --8408070074 Contract "Technical Assistance for Support of Const Appraisal Team (CAT) Insps," awarded to Parameter.inc LOFY,R Parameter, Inc MORTON,K V Division of Contracts FIN B-8718 NRC-05-84-152 84/07/31 32pp 25991 258

- 8408090119 Currected notification of Contract execution, Mod 2.to
  "Nuclear Paper Plant Operation Courses" Cuntractor
  Chattanooga State Technical Community College
  UMBEL. D. Technical Assistance Contracts Branch FIN B-1279
  NRC-03-81-251 84/07/31 BLAMA. J. Director's Office. Office of
  Inspection and Enforcement ROESBLER. S. D. URC No Detailed
  Affiliation Given. 1p. 25991-213
- 8408090135 Notification of contract execution Mod 3. to "Integral Sys Test Program Once-Through Integral Sys & Multiloop Integral Sys Test Components 'Contractor B&W MOLLETI.S Technical Assistance Contracts Branch FIN 8-8909 NRC-04-83-168 84/07/24 BATSON.W Office of Nuclear Regulatory Research, Director YOUNG,M NRC No Detailed Affiliation Given in 25991 211
- --8408090142 Ltr Contract NRC-04-83-168, Mod 3, providing incremental funding, to 'Integral Sys Tast Program Cince-Through Integral Sys & Multiloop Integral Sys Test Components "SMITH:P A Technical Assistance Contracts Branch FIN B-8709 NRC-04-83-168 B4/06/27 LUKASIK:M Babcock & Wilcox Co ip
- B40B070504 Notification of contract execution, Mod 5, to "Safety Aspects of Industrial Radiography Courses" Contractor GAMMA
  Industries
  GILDENHURRI, A.J. Administrative Contracts Branch NRC-05-82-251
  B4/0B/01 MUIR, A.P. Program Support & Analysis Staff
  HASSELBERG, R. NRC No Detailed Affiliation Given 1p 25983 128
- --8408070510 Mod 5,deleting dates for third course in entirety,to "Safety Aspects of Industrial Radiography Courses" RIDDLE,R R. Nuclear Bystem HAGAN.T F. Division of Contracts NRC-05-82-251 84/08/01 ip 25983 127
- 840B090S4B Notification of contract execution.Mod 5,to "Radionuclide Migration Around U Ore Bodies Analogue of Radwaste Repositories " Contractor Australian Atomic Energy Commission WOLLETT'S Technical Assistance Contracts Branch FIN B-4661 NRC-04-B1-172 B4/07/31 DATSON.W Office of Nuclear Regulatory Research, Director BIRCHARD.O NRC No Detailed Affiliation Given ip 2598-229
- --8408090551 Mod 5, extending period of performance to 840930 at no add1 cost.to "Radionuclide Migration Around U Ore Bodies -Analogue of Raduaste Repositories " RATCLIFF, W H Australia, Govt of SMITH,P A Division of Contracts FIN 0-6561 NRC-04-81-172 84/07/31 ip 25983 230
- 8408130308 Notification of contract execution, Mod 3, to "New Madrid/Miduest Continent Goological & Seismological Research Program "Contractor Univ of Michigan MACE.M Technical Assistance Contracts Branch FIN 8-8080 NRC-04-81-195 84/08/01 BATSON.W Office of Nuclear Regulatory Research, Director MURPHY.A NRC No Detailed Affiliation Given 1p 26040 331
- --B40B130314 Mod 3,adding requirements to statement of work & obligating add1 funds to "New Madrid/Midwest Continent Geological & Setsmological Research Program"
  MATTHEWS.C IJ Michigan, Univ of, Ann Arbor, MI SMITH.P A Division of Contracts FIN B-8080 NRC-04-81-195 84/08/01 2pp 26040 332
- 8408130435 Notification of contract execution, Mod 3, to "Licensing Technical Assistance" Contractor Science Applications, Inc SILVIS, R M Technical Assistance Contracts Branch FIN B-6947-0 NRC-02-80-035 84/08/02 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director LOYSEN, P NRC No Detailed Affiliation Given 1p 26058 356
- --B408130437 Mod 3, incorporating final overhead rates for FY81 & 82 & deabligating balance of funds, to "Licensing Technical Assistance"
  FINDLEY, D E Science Applications, Inc. SMITH, P.A. Division of Contracts FIN B-6947-0 NRC-02-80-035 84/08/02 ip
- 8408130440 Notification of contract execution, Mod 2, to "Licensing Technical Assistance" Contractor Science Applications, Inc SILVIB.R M Technical Assistance Contracts Branch FIN B-6955-0 NRC-02-80-035 84/08/02 DAVIB.J G Office of Nuclear Material Bafety & Safeguards, Director LOYSEN, P NRC No Detailed Affiliation Given 1p 26058 354
- --8408130442 Mod 2,incorporating final overhead rates for FY81 & 82.to
  "Licensing Technical Assistance"
  FINDLEY,D E Science Applications, Inc SMITH,P A Division of
  Contracts FIN B-6955-0 NRC-02-80-035 84/08/02 1p
  26038 335

- 8408130444 Notification or contract execution, Mod 4, to "Licensing Technical Assastance" Contractor Science Applications, Inc SILVIS, RM Technical Assistance Contracts Branch FIN 8-6953-0 NRC-02-80-0.35 84/08/02 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director LOYSEN, P NRC No Detailed Affiliation Given 1p 26058 332
- --B408130445 Mod 4.incorporting final overhead rates for FY81 & 82.to
  "Licensing Technical Assistance"
  FINDLEY.D E Science Applications. Inc SMITH.P A Division of
  Contracts FIN B-6933-0 NRC-02-80-035 84/08/02 ip
  24058 353
- 8408130572 Notification of contract execution. Mod 4, to "Technical Assistance in Hydrogeology" Contractor Law Engineering Testing Co FLEENOR, C Technical Assistance Contracts Branch NRC-02-82-028-0184/08/06 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director JDHNSDN, R NRC No Detailed Affiliation Given 1p 26036-361
- --8409130597 Mod 4.extending period of performance until 850107,to "Tachnical Assistance in Hydrogeology" STEINBRENNER,F Law Engineering Testing Co SMITH,P A Division of Contracts NRC-02-82-028-01 84/08/06 1p 26036 362
- 840B140510 Notification of contract execution.Hod i.to "QA Congressional Study " Contractor NC Kist & Assoc.Inc HIGGINS,E Technical Assistance Contracts Branch WOLLETT,S Division of Contracts NRC-05-84-155 84/07/26 BLAHA,J Program Support & Analysis Staff BRACH,W NRC - No Detailed Affiliation Given ip 26061 294
- --B40B140517 Mod 1, adding procedures for replacement of task orders & identifying names of individuals to receive monthly repts, to "GA Congressional Study"
  HEIDERREICH, J N C Kist & Associates, Inc MORTON, K V Division of Contracts NRC-05-84-155 84/07/26 1p 24061 295
- 8408200590 Notification of contract execution Mod 2.to "Maint & Operation of LPDRs" Contractor Plymouth, MA Public Library TDINNSEND, D Administrative Contracts Granch NRC-10-83-748 84/08/14 FELTON, J M Division of Roles and Rocords SOUDER, J NRC No Detailed Affiliation Given ip 26143 273
- --8408200597 Mod 2.extending period of performance to 850916 & increasing funds, to 'Maint & Operation of LPDRs' \* Plymouth, MA HAGAN,T F Division of Contracts NRC-10-83-748 84/08/14 1p 26143 274
- 8408200602 Notification of contract execution, Mod 2, to "Maint & Operation of LPDRs" Contractor Crystal River, FL Public Library
  TONNSEND, 8 Administrative Contracts Branch NRC-10-83-747
  84/08/14 FELTON, JM Division of Rules and Records SOUDER, J
  NRC No Datailed Affiliation Given 1p 26143 281
- --8408200606 Mod 2, extending period of performance to 850916 & increasing funding to "Maint & Operation of LPDRs "

  \* Crystal River, FL HAGAN.T F Division of Contracts
  NRC-10-83-747 84/08/14 1p 26143 282
- B40B210024 Notification of contract execution Mod 1.to "Maint & Operation of LPDRs" Contractor Russell Library, Middletown.CT
  TOWNSEND, B Administrative Contracts Branch NRC-10-83-731
  B4/0B/14 FELTON.J M Division of Rules and Records EdUDER.J
  NRC No Datalied Affiliation Given 1p 26195 IB2
- ---8408210032 Mod 1.exercising option to extend period of performance for 1 yr to 850921 & increasing funding to "Maint & Operation of LPDRs"

  \* Middletoun, CT HAGAN T F Division of Contracts
  NRC-10-83-731 84/08/14 ip 26195 183
- 8408210040 Notification of contract execution, Mod 2, to "Maint b Operation of LPDRs " Contractor Perry, CH Public Library TOUNGEND. B Administrative Contracts Branch NRC-10-83-736 B4/08/14 FELTON, J M Division of Rules and Records SOUDER, J NRC - No Detailed Affiliation Given 1p 26195 179
- --B40B210047 Mod 2, exercising option to extend period of performance for 1 yr to 850916 & increasing funding, to "Maint & Operation of LPDRs" \* Perry, OH HAGAN, T F Division of Contracts NRC-10-83-736 84/08/14 ip 26195

- 8408210042 Notification or contract execution, Mod 4. to 'Followon Simulation of Earthquake Ground Motions for San Onofre Muclear Generating Station "Contractor MIT HOPPER, A Administrative Contracts Branch FIN 8-6898 NRC-03-80-144 84/06/12 VQLLMER; R Division of Engineering JACKSON, R NRC ~ No Detailed Affiliation Given 1p 26195 176 24X Fiche 50-206.84/06/12.8408210042
- --B408210046 Mod 4.deobligating unliquidated fee remaining in contract.
  to "Followon Simulation of Earthquake Ground Motions for
  San Onofre Nuclear Generating Station "
  AKI.K Massachusetts Institute of Technology. Cambridge. MA
  HAOAN.TF Division of Contracts FIN B-6878 NRC-03-80-144
  84/06/12 1p 26195 177 24X Fiche 30-206.84/06/12,8408210042
- 8408220075 Notification of contract execution, Med 2 to "IMS/IDAS Bys Support " Contractor SBA Subcontractor Wilson Hill Associnc GILDENHORN, A J Administrative Contracts Branch FIN D-1211 NRC-3D-84-378 84/08/02 BASSETT, HS Division of Data Automation & Management Information BADINI, J B NRC No Detailed Affiliation Given Ip 24210 353
- --B408020080 Mod 2 increasing funding & extending period of performance to B40830,to "IMS/IDAS Bys Support " THOMAS,M E Small Business Administration HILL,P W Wilson Hill Associates, Inc HA0AN,T F Division of Contracts FIN D-1211 NRC-33-84-378 84/08/02 4pp 26210 354
- B408220150 Notification of contract execution. Mod 10, to "Central Virginia Regional Selsaic Network " Contractor " Virginia Polytechnic Inst & State Univ PAGE.M Technical Assistance Contracts Branch FIN 8-6249 NRC-04-177-134 B4/08/10 BATSON.W Office of Nuclear Regulatory Research, Director MURPHY.A NRC " No Detailed Affiliation Given ip 26212 179
- --8408290156 Mod 10, increasing funding & extending period of performance to 850731, to "Central Virginia Regional Seismic Network"
  STEISS.A W Virginia Polytechnic Institute & State Univ,
  Blacksburg, VA SMITH.P A Division of Contracts FIN 8-6249
  NRC-04-77-134 84/08/10 4pp 26212 180
- B408220384 Notification of contract execution.Mod 6, to "Residuel Stress at Girth Butt Welds in Pipes or Pressure Vessels"
  Contractor BMI
  BILVIS.R M Research Contracts Branch FIN B-5608 NRC-04-76-293
  B4/08/02 BATSON.W Office of Nuclear Regulatory Research,
  Director LYNN.E K NRC No Detailed Affiliation Given Ip
  26209 360
- --B4082203E7 Mod 6, incorporating final overhead rate for FY76-78, to
  "Residual Stress at Girth Butt Welds in Pipes or Pressure
  Vessels"

  LUKZ, F J Battelle Menorial Institute, Columbus Laboratories
  BMITH, P A Division of Contracts FIN B-5608 NRC-04-76-273

  84/08/02 ip 26209 361
- B40B220377 Notification of contract execution "Photographic Reproduction Bycs," awarded to SBA Subcontractor Domus Design Studios, Inc HAWKINS D A Administrative Contracts Branch NRC-10-84-270 B4/07/18 BEBAN, H J Division of Technical Information & Document Control DEHN, D NRC - No Detailed Affiliation Given 1p 26210 277
- --8408220400 Contract "Photographic Reproduction Svcs," awarded to Domus Design Studios. Inc HOMAS, M E Small Business Administration NRC-10-84-270. B4/07/18 2pp 22210 276
- --B408220404 Contract "Photographic Reproduction Svcs," awarded to SBA Bubcontractor Domus Design Studios. Inc THOMAS M E Small Business Administration \* Domus Design Studios. Inc. HAGAN. T F Division of Contracts NRC-10-84-270 84/07/18 56pp 26210 280
- 8408230330 Notification of contract execution. Hod 4, to "Reviewing Hydrogeologic Investigations of Bodded & Dome Balt Basins Project B " Contractor Golder Assoc. Inc FLEENOR. C Administrative Contracts Branch NRC-02-83-034 84/08/03 DAVIS. J Diffice of Nuclear Material Safety & Safeguards. Director COUKE, B NRC No Detailed Affiliation Given is 26236 074
- --8408230336 Mod 4, terminating contract, to "Reviewing Hydrogeologic Investigations of Bedded & Dome Salt Basins - Project II " PENTI.D L. Golder Associates SMITH, P. A. Division of Contracts NRC-02-83-034, 84/08/03 2pp 26236 077

- 8408230484 Notification or contract elecution, Mod 3, to "Mod of Elisting Air Pathuay Model for Low Level Waste Assessment & Training Course " Contractor NOAA
  PAGE, M Technical Assistance Contracts Branch FIN 0-7359-3
  NRC-02-83-031 84/08/16 BROWN R 5 Program Support Branch
  NEUDER, S NRC No Detailed Affiliation Given 1p 26230 256
- --8408230506 Mod 3.extending period of performance to 841030.to "Mod of Existing Air Pathway Model for Low Level Waste Assessment Training Course "MAHLER.R J Communec. Dept of Natl Oceanographic & Atmospheric Administration SMITH.P A Division of Contracts FIN 8-7359-3 NRC-02-83-031 84/08/16 lp 26230 259
- 8408240399 Notification of contract execution,Mod ii,to "Computer Time-Sharing & Related Sycs " Contractor NIH BROMBERG.B Administrative Contracts Branch FIN B-1666 NRC-25-82-312 84/08/17 BASSETT.H S , SHIELDS.J Office of Resource Management, Director ip 26255 325
- --B408240094 Mad 11.adding funding to "Computer Time-Sharing & Related Svcs " \* HMS, Dept of, U.S. Public Health Service HAGAN, T.F. Division of Contracts FIN 8-1666 NRC-25-82-312 84/08/17 ip 28055 324
- B408270497 Notification of contract execution "Stenographic Reporting Syes Throughout Contiguous US Excluding Mashington, DC Metropolitan Area," awarded to Ace-Federal Reporters, Inc DAVIS. K. Administrative Contracts Branch FIN 8-8183 NRC-21-84-392 B4/08/04 COTTER, BP Atomic Safety and Licensing Board Panel LEINS, E. MORAN, D. NRC No Detailed Affiliation Given ip 26277 066
- --8408270903 Contract "Stenographic Reporting Svcs Throughout Contiguous US Excluding Nashington, DC Metropolitan Area," awarded to Ace-Federal Reporters, Inc \* ACE Federal Reporters, Inc MATTIA, M J Division of Contracts FIN D-8183 NRC-21-84-352 84/08/06 ip 26277 067
- --8408270308 Selicitation, offer & award of "Stenographic Reporting Sycs Throughout Contiguous US Excluding Washington, DC Metropolitan Area," to Ace-Federal Reporters, Inc MONICK,R J. ACE Federal Reporters, Inc. \* Division of Contracts FIN B-8183 NRC-21-84-352 84/06/29 130pp 26277 068
- B40B270547 Notification of contract execution, Mod 12, to "Memphis Area Regional Seismic Network — New Madrid " Contractor Memphis State Univ PAGE,M Technical Assistance Contracts Branch FIN B-6276 NRC-04-78-200 B4/08/20 BATSON,W Office of Nuclear Regulatory Research, Director MURPHY,A NRC - No Detailed Affiliation Given ip 26277 033
- --8408270552 Mod 12; ravising statement of work to add cooperative effort w/Univ of Kentucky, to "Memphis Area Regional Seismic Network New Madrid "
  CARPENTER. T O Memphis State Univ , Memphis, TN SMITH, P A Division of Contracts FIN B-6276 NRC-04-78-200 84/08/20 4pp 26277 034
- 8408270557 Notification of contract execution, Mod 13, to "In-Process Control of BMM" Contractor Science Applications, Inc WDLLETT, S Technical Assistance Contracts Branch FIN B-7315-4 NRC-02-81-040 84/08/13 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director MILLER, M NRC No Detailed Affiliation Given ip 26277 266
- --8408270558 Mod 13, revising period of performance to end 840815 in lieu of 841031 & providing for decrease to scape of work to reflect shortened performance period to "In-Process Control of SMM"

  MCDDMALD,R Science Applications, Inc SMITH,P A Division of Contracts FIN 8-7315-4 NRC-02-81-040 84/08/13 2pp
- 8408270574 Notification of contract execution.Mod 8, to "Maint of Data Oeneral Computers & Peripheral" Contractor Data Consultants.Inc
  HAHKINB, D. A. Administrative Contracts Branch FIN 8-1663
  NRC-25-82-311 84/07/33 BASEETT.H Division of Data Automation & Management Information JOHNSDN, C NRC No Detailed Affiliation Given ip 26258 361
- --8408270576 Mod 8.extending period of performance from 840526 to 840613 at no cost, to "Maint of Data General Computers & Peripheral "
  BONNIES, G Data Consultants, Inc HOGAN, T F Administrative Contracts Branch FIN 8-1663 NRC-25-82-311 84/07/30 ip 26258 362

- 8408270981 Nutification or contract execution, Mod 3, to 'Consulting Svcs of E Hodabaugh to Investigate Nozzle Load Design Linits, Overall Design Margins & Loading Rate Effects "Contractor EC Rodabaugh Assoc. Inc Proc. III Technical Assistance Contracts Branch FIN 8-8690 NRC-03-84-071 84/08/20 DENTON, HR Office of Nuclear Reactor Regulation, Director SULLIVAN, E NRC No Detailed Affiliation Given 1p 26238-357
- --8408270582 Mod 3 revising statement of work for contractor participation on pipelock review panel, to "Consulting Svcs of Rodabaugh to Investigate Norrie Load Design Limits, Overall Design Margins & Loading Rate Effects "RODABAUGH, E.C. E.C. Rodabaugh Associates, Inc. SMITH, P.A. Division of Contracts FIN 3-8690 NRC-03-84-071 B4/08/20 7pp 26258 398
- B408290347 Notification of contract execution, Mod 2, to "Processing & Packaging Documents for Transmittal to LPDRs " Contractor Maxima Corp HAMKINS.D A Administrative Contracts Branch NRC-10-84-247 B4/08/14 FELTON, J M Division of Rules and Records SOUDER, J NRC No Detailed Affiliation Given 1p 26311 296
- --8408290349 Mod 2 revising contract to incorporate administrative corrections & computer costs, to "Processing & Packaging Bocuments for Transmittal to LPDRs "
  ZUTOVSKY, L E Maxima Corp HILL, D Small Business Administration HAOAN, T F Division of Contracts NRC-10-B4-247
  B4/08/14 3pp 26311 297
- B40B300233 Notification of contract execution, Mod 2.to "Clinical Response to Chronic Stress in TMI" Contractor Uniformed Bycs Univ of Health Sciences
  HOYLE.A Administrative Contracts Branch FIN B-BOOB
  NRC-03-B1-135 B4/08/14 VOLLMER.R H Division of Engineering CLEARY.D P NRC No Detailed Affiliation Given ip 26315 361 24X Fiche 50-289.B4/08/14.B408300233
- --8408300237 Mod 2.extending period of performance to 840915, to "Clinical Response to Chronic Stress in TMI"

  BAUM.A Uniformed Services Univ of Health Sciences HAGAN.T F Division of Contracts FIN B-8008 NRC-03-81-325 B4/08/14 1(26315 362 24X Fiche 50-289:84/08/14.8408300233
- 840B310082 Notification of contract execution, Mod 1 to "Career Counseling for NRC Participants in Region IV" Contractor RB Clark
  MURPHY,L G Administrative Contracts Branch NRC-10-B3-721
  84/08/23 GOLDMAN,P J Management Development & Training Staff VAN SANTEN.L NRC No Detailed Affiliation Given 1p 24332 OSB
- --8408310088 Mod 1.extending period of performance to 858630 & increasing monetary amount to "Career Counseling for NRC Participants in Region IV"
  CLAW.R Clark, R B HAGAN.T F Division of Contracts
  NRC-10-83-721 84/08/23 2pp 26352 039
- B40B310232 Requests that completion date for Contract NRC-05-83-215, "Insp Model for Environ Qualification of Electrical Equipment." be extended from Aug 1784 to Feb 1785 POTAPOUS,U Vendor Program Branch 84/08/27 LAUDAN,W Engineering & Generic Communications Branch 2pp 26320 326
- B40B310260 Notification of contract execution.Mod 5, to "Assay of Long-Lived Radionuclides in tow Level Wastes From Power Reacturs " Contractor Science Applications.Inc PAGE.M Technical Assistance Contracts Branch FIN 0-7356-4 NRC-02-82-043 84708716 DAVIS.J Office of Nuclear Material Safety & Safeguards.Director JOHNSON.T NRC - No Detailed Affiliation Given 1p 26350 282
- --8408310262 Mod 5, extending period of performance until 841031 & providing addl funds, to "Assay of Long-Lived Radionuclides in Low Level Wastes From Power Reactors" ARCHER, C D Science Applications. Inc SMITH, P A Division of Contracts FIN 8-7356-4 NRC-02-82-043 84/08/16 2pp
- B40B310363 Notification of contract execution, Mod 1, to "Regional Economic Impacts of Accidents" Contractor Dept of Commerce PAGE.M Technical Assistance Contracts Branch FIN D-967B NRC-03-984-065 84/08/23 VOLLMER.R H Division of Engineering RICHTER.B NRC No Detailed Affiliation Given 1p 26350 330
- --8408310368 Mod i, revising completion date for Task 6 at no add1 cost, to "Regional Economic Impacts of Accidents "
  TROTTLE A Commerce, Dept of SMITH.P A Division of Contracts FIN B-8678 NRC-03-84-065 84/08/23 2pp 26350

- 8408310385 Notification or contract execution Mod 4, to "Panel Member & Documentation Review for Selected Meetings of Peer Review Oroup" Contractor AB Reynolds
  TOWNSEND.B L. Administrative Contracts Branch FIN B-8985
  NRC-04-83-010 84708/27 BASSETT.O E Division of Accident
  Evaluation JANKOMBKI, N W. REYERS.R NRC No Detailed Affiliation Given 1p 26350 275
- --B10B310390 Med 4.extending period of performance until B40501,to
  "Panel Member & Documentation Review for Beletted Meetings
  of Peer Review Group"

  \* Virginia, Univ of, Charlottesville, VA HALMAN,E L. Division
  of Contracts FIN B-8985 NRC-04-83-010 84/08/27 ip
  26350 276
- FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES
- 8407120136 Appeals denial of FOIA request for 27 documents referenced in 1975 EIS re facility & all EIS. supplemental EIS or similiar environ documents & FOIA fee waiver decision RYAN. J A Streich Lang, Weeks & Cardon 84/03/27 Office of the Erocutive Director for Operations App 25537 018 24X Fiche 50-528.84/03/27.8407120136
- 8407:20142 Responds to appeal re denial of FOIA request for 27 documents referenced in 1975 EIS re facility & all EIS, supplemental EIS or similar environ documents Appeal pranted DIRCKS,W J Office of the Executive Director for Operations 84/05/21 RYAN,J A Streich, Lang, Weeks & Cardon ip 25557 022 24X Fiche 50-528,84/05/21,8407:20142
- 8407130037 Further response to FOIA request for numerous categories of records be issues discussed in IE Info Notices 81-29,83-52,83-57 & 83-72 & Board Notifications 83-128 & 83-1284 Forwards Apps C & D decuments Search continuing FELTON.J II Division of Rules and Records 84/04/13 JORDAN.W S Harmon & Weiss 7pp 25584 078 24X Fiche 50-000.84/04/13.8407130037
- 840B010061 Further response to FDIA request for 16 categories of records re facility Documents identified by J Goold & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing FELTON. J M Division of Rules and Records BX14 000 84/07/18 RICE. C M Kinkland & Ellis & 2pp 26900 001 24X Fiche 50-329.84/07/18.8408010061
- --8408020188 Responds to Mooney concept theory re SRP 2 5 4 & PSAR review Suggestion to GELD re Mooney testimony encl HOOD, D NRC No Detailed Affiliation Given BX17 027 83/11/22 HABBEL, D M NRC No Detailed Affiliation Given 4pp 26519 153 24X Fiche 50-329,84/07/16,840801006i
- --7812070142 Discusses IE Insp Repts 50-329/78-12 & 50-330/78-12 Contributing factors to settlements of diesel generator bldg foundation & generator pedestals include variable properties of random fill math supporting structure & cooling pand KEPPLER.J G Region 3, Chicago. Office of the Director BX16 001 78/11/01 TMORNBURG.H D Division of Reactor Construction Inspection 2pp 26506 211 24X Fiche 50-329,84/07/18,
- --7709290117 Forwards outline history of geotechnical engineering problems re plant fill Lists pertinent PSAR & FSAR criteria & summarizes foundation conditions & remedial measures for all Category I structures founded on plant fill GILLEN.S M Geosciences Branch 8X14 015 77/08/28 JACMSDN.R E Geosciences Branch 10pp 26510 309 24X Fiche 50-329,84/07/18,8408010061
- --B004040738 Summary of B00227 & 28 meeting & site visit w/util in Hidland.MI re soil settlement problems & related investigation program GONZALES.R O Hydrology Meteorology Branch DX16 032 80/03/10 BIVINS.W S Hydrology Meteorology Branch 9pp 26511 i19 24X Fichs 50-329,84/07/18.8408010061
- --8008130764 Summarizes status of seismological input parameters re geosciences & geotechnical review of facilities as discussed at 800702 & 22 meetings KIMBALL.J Geosciences Branch BX16 029 80/08/07 JACKSON.R E Geosciences Branch App 26511 095 24X Fiche 50-329.84/07/18, 8408010061
- --8010160005 Submits questions in response to request for interrogatory input re hearing
  LEAR, GE Hydrologic & Geotechnical Engineering Branch BX17 013
  80/10/04 MIRACLIA,F Licensing Branch 3 2pp 26518 144 24X
  Fiche 50-329,84/07/18.8408010061

- --B011240409 Forwards Hydrologic Engineering Section interrogatories re permanent dewatering sys at facilities LEAR.G E Hydrologic & Geotechnical Engineering Branch BX17 008 B0/11/10 TEDESCO.R L Assistant Director for Licensing 3pp 26517 244 24X Fiche 50-329.84/07/18.840801006:
- --8104230479 Submits comments on applicant response to NRC
  Interrogatories 1-3 No results available for review of
  Interrogatories 1 & 2 since no consolidation tests on
  samples were obtained from surchanged area of plant fill
  MCCALLISTER.P Army, Dept of, Corps of Engineers BX17 014
  B1/03/27 LEAR.0 Hydrologic & Geotechnical Engineering Branch
  2pp 26518 150 24X Fiche 50-329,84/07/18,8408010061
- --B103070480 Responds to request re Geosciences Branch estimate of time required to complete site review Approx 30 days are needed to review add1 info requested for Part 1 & 3 months are needed for review of Part 2 submittal KNIGHT, J P Assistant Director for Comp & Structures Engineering (Pre B30201) BXI6 0578 B1/04/24 PATON, W D Office of the Executive Legal Director ip 26513 189 24X Fiche 30-329,84/07/18,8408010061
- --8110190801 Forwards topic discussions for inclusion in 1981 annual rept.per 810902 commitment Discussions of technical assistance program for licensing OETR review & Midland remedial repair info encl
  HELLER.L W Hydrologic & Geotechnical Engineering Branch 8X16 Branch
- --8110260082 Informs that licensee taking position that IEEE 279
  jurisdiction starts u/transmitter Jurisdiction should start
  at sensing line connection to process piping
  HENDERSUN, J B Reactor Projects Sections (Regions 1 & 3) BX17
  024 81/10/01 WILLIAMS, C C Plant Systems Section 1p
  26533 050 24X Fiche 50-327,84/07/18,8408010061
- --8111240064 Informs of Bil016 conference call w/util to discuss revised schedule for soils hearing requests revision to better accommodate const schedule Agreed schedule for hearings will be 811201-04 & 1214-18 be 811201-04 & 1214-18 MODD, D Licensing Branch 4 BX19 036B 81/10/30 TEDESCO,R L Assistant Director for Licensing 3pp 26535 252 24X Fiche 50-329,84/07/18,8408010061
- -8201050063 Summarizes Bil207 telcon re 820105 soils hearing HDDD.D. Licensing Branch 4 8818 032 Bi/12/14 ADENBAM.E 0 Licensing Branch 4 2pp 26526 099 24% Fiche 50-329,84/07/18. 8408010061
- --B201220049 Advises of i-nonth delay in meeting R Tedesco 811214 schedule in support of facility hearing & review Viable schedule must recognize need for iteration w/applicant following each significant submittal VOLLMER.R H Division of Engineering BX14 074 81/12/28 EISENIUT, D & Division of Licensing 3pp 26514 188 24X Fiche 50-329.84/07/18.8408010061
- --8202040352 Informs that certain SER sections, especially soil remedial actions, will not be complete by 820406 deadline ADENSAM, R. G. Licensing Branch 4 8X16 055 82/01/19 EIECHNUT, D. G. Division of Licensing 3pp 26512 266 24X Fiche 50-329,84/07/18,8408010061
- --B203020050 Summary of 811006-07 meeting w/util.Bechtel & consultants in Bethesda, MD re underground piping in inadequately compact plant fill HOOD.D 6 Licensing Branch 4 8X2; 002 GM 82/02/05 DENTON,H R NRC ~ No Datailed Affiliation Given 37pp 26549 084 24X Fiche 50-329,84/07/18,8408010061
- --B205050209 Forwards listing of issues to be resolved prior to start of Phase 2 underpinning operations for auxiliary bldg LEAR.O Hydrologic & Ocotechnical Engineering Branch BX16 035 B2704/28 ADENBAM.E Licensing Branch 4 2pp 26511 200 24X Fiche 50-329,84/07/18,8408010061
- --B205120033 Summarizes technical comments from ACRS subcommittee 820429 meeting re ramedial activities for deficient soils ADENBAM,E G Licensing Branch 4 0X18 035 82/05/04 BOSNAK,R NRC No Detailed Affiliation Oiven 4pp 26527 183 24X Fiche 50-329,84/07/18,8408010061
- --B203210467 Notifies that util submittal re Phase 2 of underpinning repair work at facility acceptable; provided that encl mods & requirements are incorporated into Phase 2 program KNIGHT, J P Assistant Director for Comp & Structures Engineering (Pre 830201) BXI6 033 B2/05/10 TEDESCO.R L Assistant Director for Licensing 34pp 26511 203 24X Fiche 50-929,84/07/18,8408010061

- --B205240603 Advises that ad hoc ACRS subcommittee recommendations refoundation problems & rolated remedial actions at facilities acceptable.per B20429 & 0506-08 meetings Discussion of seismic-related issues tentatively scheduled for B20520-21 FRALEY.R F ACRS Advisory Committee on Reactor Safeguards 8X 003 :1879 B2/05/14 DIRCRS.W J Uffice of the Executive Director for Operations 1p 26500 027 24X Director for Operations 1p 26 Fiche 50-329,84/07/18,8408010061
- --8206020051 Comments on draft of acceptance provisions for Phase 2 Final transmittal to applicant should move through DE for transmitter to applicant anomalisms of the concurrence KN16H7.J P Assistant Director for Comp & Structures Engineering (Pre 830201) BX16 036 B2/05/13 KANE, J Assistant Director for Comp & Structures Engineering (Pre 830201) 1p 26511 202 24X Fiche 50-329,84/07/18,8408010061
- --8206060008 Summarizes 266th ACRS meeting on 820603-05 Sub, to satisfactorily completion of tonst & staffing & if due regard given to ACRS comments, plant can operate at 37 power w/o undue risk to public Full power recommendation deterred SHEMMON, P ACRS Advisory Committee on Reactor Safeguards [004 82/06/08 PALLADINU, N Commissioners 5pp 26500 028 24X Fiche 50-329,84/07/18.8408010061
- --8204240401 Forwards comments on 820422 response to NRC request for add1 info re borated water storage tank & underpinning of svc water pump structure Contact W/applicant to resolve differences recommended LEAR. G. Hydrologic & Geotechnical Engineering Branch 82/06/16 ADENSAM, E. Licensing Branch 4 103pp 66129 031 24X Fiche 50-329, 84/07/18, 8408010061
- --8206290161 Submits proposed schedule for facility soils review ADENSAM E G Licensing Branch 4 8x10 036 82/06/25 EISENHUT D G Division of Licensing 2pp 26527 187 24X Fiche 30-329, 84/07/18,8408010061
- --8207140330 Forwards request for add1 info from Structural Engineering Branch re applicant proposed remedial actions SCHAUER,F P Structural Engineering Branch BX19 029 B2/06/15 ADENSAM,E Licensing Branch 4 5pp 26533 206 24X Fiche 50-329,84/07/18.8408010061
- --8209230536 Forwards discussion of deficiencies noted in Supplemental BER 2 Requests mod to attached draft be provided addressing CONCERNS
  NOVAK.T M Assistant Director for Licensing BX18 040 82/08/27
  KNIGHT, JP Assistant Director for Comp & Structures Engineering
  (Pre 830:201) 3pp 26527 243 24X Fiche 30-327,84/07/18,
  8408010061
- --8210130322 Forwards info re location of data on underpinning dimensions & load transfer procedures POULOB,8 J Geotechnical Engineers, Inc BX16 060 81907-17 82/10/07 KARLJ Division of Engineering App 24513 234 Fiche 50-329,84/07/18,8408010061
- --8210150698 Clarifies NRC/util interaction re OL review Maint of proper control by licensing property managers necessary to manage licensing activities properly Reviewers requested to follow Itemsing activities project and a gradelines ADENSAM, E G Liconsing Branch 4 8xi6 0/0 82/09/29 TOMLINSON, E NRC - No Detailed Affiliation Given 2pt 26514 109 24X Fiche 50-329,84/07/18,8408010061
- --8210270124 Forwards input for testimony for 821027-1104 ASLB hearings Stamir;s Contention 4 C b re dewatering & svc water pump structure should be addressed by Structural Engineering Branch LEAR, G Hydrologic & Opotechnical Engineering Branch BX17 & 82/10/15 ADENBAM.E Licensing Branch 4 4pp 26519 005 Fiche 50-329,84/07/18,8408010061
- --8211030222 Forwards Hydrdological & Geotechnical Engineering Branch input for testimony at ASLB 821027-1104 hearings re bearing capacity beneath diesel generator bldg.piping svc water pump structure & permanent dewatering LEAR. G Hydrologic & Osotechnical Engineering Branch BX17 017 82/10/14 ADENSAM. E G Licensing Branch 4 7pp 26518 358 24X Fiche 30-329,84/07/18,8408010061
- --8301190487 Assigns NRC sponsors for each of M Sinclair rewritten contentions for OL hearing Schedule for filing of testimony Forthcoming HD0D, DS Licensing Branch 4 8X17 024 83/01/14 NOVAK, T M Assistant Director for Licensing 1p 24519 072 24X Fiche 50-329,84/07/18,8408010061

- ~~8309270222 Forwards trip rept of 830510-13 site visit re underpinning contract Other topics discussed include cracks in svc water pump structure heave over freeze wall need to stop laying back soil along underpinning drifts to settlements POULOS.5 J Geotechnical Engineers, Inc 8418 022 81907-23 83/05/23 KANE.J Division of Engineering 19pp 26524 317 247 Fiche 50-327,84/07/18.8408010061
- --8306060397 Trip rept of 830511 \$ 12 site visits to view pier load test installation & results

  KANE.J D Structural & Geotechnical Engineering Branch 8X18 02;

  TAC 5134 83705727 LEAR,G Structural & Geotechnical

  Engineering Branch 2pp 26524 315 24X Fiche 50-329,84707/18,
  8408010061
- --8307130423 Forwards paper entitled "Use of Site Dependent Spectra" to be presented at workshop on "Site-Specific Effects of Soil & Rock on Ground Mation & Implications for Earthqawake-Resistant Design" on 830726-28 KIMBALL.J Geosciences Branch 8X17 039 83/06/27 JACKSON.R E Geosciences Branch 1p 26520 069 24X Fiche 50-329,84/07/18. 8408010041
- --8307130425 Speech entitled "Use of Site Dependent Spectra," to be presented at B30726-28 workshop on "Site-Specific Effects of Soil & Rock on Ground Mation & Implications for Earthquake-Resistant Design" in Santa Fe.NM KIMBALL.J Geosciences Branch BX17 040 B3/06/27 25pg 26520 070 24X Fiche 50-327.84/07/18.8408010061
- ~~8307130017 Discusses IE insp on 821012-1125 & 830117-21 & forwards order imposing civil monetary penalties in amount of \$120,000 for violation re breakdown in implementation of QA program per lOCFRSO.App B
  DEYDUNG.R C Director's Office, Office of Inspection and Enforcement BX21 018 EA-83-003 83/08/29 SELBY, J D
  Consumers Power Co 3pp 26554 045 24X Fiche 50~329, 84/07/18, 8408010061
- --B309270366 Responds to B30523 & 0810 requests for assistance in reviewing util proposed fundings of fact & conclusions of law on remedial soils issues Agrees w/findings Recommends paragraph re occurence of laquefaction be revised BALLARD, R L Environmental & Hydrologic Engineering Branch BX17 037 B3/09/14 PATON, W D Office of the Executive Legal Director 2pp 26320 062 24X Fiche 50-329,84/07/18,8408010061
- --8310050136 Discusses structural engineering review of "Applicants Proposed Findings of Facts & Conclusions of Law on Remedial Soil Issues" along w/related info on seismic models & borated water storage tanks resulting from ASLD hearings LEAR, G Structural & Gentechnical Engineering Branch BX17 035 83/09/22 PAYON, W Office of the Executive Legal Director 5pt 24520 091 24X Fiche 50-329,84/07/18,8408010061
- --8310070101 Forwards comments on applicant proposed findings of fact & conclusions of law on remedial soil issues

  LEAR.O Structural & Geotechnical Engineering Branch BX17 035A

  B3/07/29 PATON.W Office of the Executive Legal Director 4pp

  26520 052 24X Fiche 50-329.84/07/18.8408010061
- ~~B310070262 Forwards second phase of Geotechnical Engineering input on findings of fact & conclusions of law in response to OELD request Several areas of significant differences crist re diesel generator bidg LCAR.0 Structural & Geotechnical Engineering Branch BX17 032 B3/09/30 PATCH.W D Office of the Executive Legal Director App 26519 246 24X Fiche 50-329.84/07/18.8408910061
- --8310240291 Informs that structural review of document "Applicant Proposed Findings of Facts & Conclusions of Law on Remedial Buil Issues;" completed Structures adequate Comments encl LEAR.0 Structural & Ocotechnical Engineering Branch 2017 036 83/10/14 PATON.W Diffice of the Executive Legal Director. Spj 26520 056 24X Fiche 50-329,84/07/18.8408010061
- --8312080185 Forwards technical evaluation of HVAC structural design adequacy, based on findings of Mechanical Engineering Branch design review & audit KNIOHT, J.P. Assistant Director for Comp. & Structures Engineering (Post 830201) BXIB 051 TAC 52311 B3/11/25 NDVAK, T.M. Assistant Director for Licensing 27pp. 26528 206 24 X Fiche 50-329, 84/07/18, 8408010061
- --8312120393 Requests requisite info re followup action to be taken by Region III to 831108 recommendation for board notification EIEENHUT, D @ Division of Licensing BX21 014 DM 83/11/30 WARNICK, R F Region 3, Office of Director | Ip 26583 204 24X Fichs 50-329, 84/07/18, 8408010061

- --8406020280 Trip rept or 840504 site visit to participate in public meeting on mg\* appraisal program to be performed on util Comments on independent mgt appraisal encl MCIAUGHLIN.P Licensee Gualifications Branch 8X20 010 84/05/22 BOOHER.H R Licensee Gualifications Branch 5pp 26539 045 24X Fiche 50-329,84/07/16.8408010061
- --8408010132 Forwards TERA Corp 830815 ltr describing four conceptual options for independent quality verification program methodologies Option 1 integral part of IDCVP at Midland FISCHER, D ACRS Advisory Committee on Reactor Safeguards 8X14 OO1 83/11/15 ACRS Advisory Committee on Reactor Safeguards 2pp 24500 O12 24X Fiche 50-327,84/07/18,8408010061
- --8409010135 Forwards QA/GC project status rept presented at ACRS 274th meeting on B30210 FISCHER.D C ACR9 Advisory Committee on Reactor Safeguards BX14 002 B3/03/03 ACR8 Advisory Committee on Reactor Safeguards App 26500 021 24% Fiche 50-327, B4/07/18, B409010061
- --8408010143 Forwards summary & conclusion of overall effectiveness portion of Region III rept on design & const problems Lack of aggressive GA attitude & everreliance on AE contribute to GA problems
  FISCHER, D C ACRS Advisory Committee on Reactor Safeguards
  BX14 005 82/12/09 ACRS Advisory Committee on Reactor Safeguards
  5afeguards App 26500 034 24X Fiche 50-329.84/07/18,
- --8403010147 Forwards JW Cook 810430 ltr & executive summary re GA program update, per 830215 request 50MMERS. D A Consumers Fower CO BX14 006 DAS 9-83 83/02/16 FISCHER. D C ACRS Advisory Committee on Reactor Safeguards 1p 24500 038 24X Fiche 50-329, 84/07/18,8408010061
- --8408010149 Forwards executive summary re GA program update, per Bi0331 meeting compitment & NRC 810402 ltr Apps will be transmitted by Bi0522 COCK, J W Consumers Power Co BX14 007 11980 81/04/30 KEPPLER, J G Region 3, Chicago, Office of the Director (81/03/01) 19ps 26500 039 24X Fiche 30-329,84/07/18,8408010061
- --8408010192 Forwards status rept re QA/QC activities at facility to be presented at ACRS 274th meeting on 830210
  FISCHER D C ACRS Advisory Committee on Reactor Safeguards
  BX14 008 B3/02/07 ACRS Advisory Committee on Reactor Safeguards
  7pp 26500 058 24X Fiche 50-329,84/07/18,8408010061
- --8408010193 Discusses major reduction in safety-related work at Midland ACRS comments to NJ Palladino encl FISCHER D ACRS Advisory Committee on Reactor Safeguards BX14 O09 B2/12/09 ACRS Advisory Committee on Reactor Bafeguards 3pp 26500 Q65 24% Fiche 50-329,84/07/18,8408010061
- --B40B010160 Forwards interim 10CFR80 95(e) rept re QA program & mfg deficiencies affecting radiation monitoring equipment supplied by Victoreen, Inc FISCHER.D ACRS - Advisory Committee on Reactor Safeguards BX14 011 B2/11/15 DKRENT,D ACRS - Advisory Committee on Reactor Safeguards 1p 26500 072 24X Fiche 50-329,84/07/18,8408010061
- --8408010163 Forwards cost estimate for once through steam generator overfill protection modiper request DREHODLIK E Consumers Power Co BX14 012 18457 82/08/17 FISCHER.D C ACRS Advisory Committee on Reactor Safeguards 2pp 26500 073 24% Fishe 50-329.84/07/18.8408010061
- --8408010168 Forwards SSER 1, addressing ACRS recommendations contained in 820508 interin rept Operating license rovious project status repts for 820520-21 & 0.602 encl W/o BSER FISCHER.D ACRS Advisory Committee on Reactor Safeguards 11X14 013 82/07/19 UKRENT.D ACRS Advisory Committee on Reactor Safeguards 12pp 26500 075 24X Fiche 50-329,84/07/18, 8408010041
- --B408010173 Discusses Util approach for satisfying safety review requirements at Big Rock Point Palisades & Midland Summary of B20504 meeting & viewgraphs encl FISCHER.D C ACR8 Advisory Committee on Reactor Bafaguards BX14 014 82/05/17 ACR8 Advisory Committee on Reactor Safaguards 43pp 26500 087 24X Fiche 50-327,84/07/18,8409010061
- --B408010178 Forwards surmary of ad hoc Subcommittee on Midland Units 1 & 2 820429 meeting Related info encl FIECHER.D ACRS - Advisory Committee on Reactor Safeguards BX14 016 82/05/06 SIESS.C ACRS - Advisory Committee on Reactor Safeguards 32pp 26500 133 24X Fiche 50-329.84/07/18, 8409010061

- --8408010183 Discusses acceptability of Midland feactor pressure vessel anchor bolts.per uti) Bili23 ltr / attached rept Expresses concern re rept sufficiency SHEUMON.P G ACRS Advisory Committee on Reactor Safeguards BX14 017 82/02/03 VOLLMER.R H Division of Engineering 1p 26500 173 24X Fiche 50-327,84/07/18.8408010061
- --B40B01018B Forwards will B00522 itr identifying one of many QA problems at facility Incident re fill math under vital structures noted in P Tam B00316 ltr Incidents should be considered in evaluation of need for subcommittee meeting YDUNG. G G ACRS Advisory Committee on Reactor Safeguards BX14 O1B B0/06/03 SMEM.YON.P ACRS Advisory Committee on Reactor Safeguards BX14 O1B B0/06/03 SMEM.YON.P ACRS Advisory Committee on Reactor Safeguards BX14 O1B B0/06/04 SMEM.YON.P ACRS Advisory Committee on Reactor Safeguards DX SAFEGUARD SAFEGUAR
- --9408010191 Summary of 800523 meeting w/util in Bethesda. MD re reactor vessel holddour stud failures at facility YOUND, G G ACRS - Advisory Committee on Reactor Safeguards BX14 019 80/05/28 SHEH/ON.P ACRS - Advisory Committee on Reactor Safeguards 3pp 26500 184 24X Fiche 50-329.84/07/18, 8408010061
- ~-B408010195 Recommends review of foundation problems at facility Poor quality fill hatt used under containment & other vital structures TAH.P ACRS - Advisory Committee on Reactor Bafeguards 8X14 020 80/05/16 SHEHMOV.P ACRS - Advisory Committee on Reactor Safeguards 1p 24500 187 24X Fiche 50-329,84/07/18,8408010061
- ~-B40B01019B Advises that unresolved safety issue exists in poor quality of fill math under containment & other vital structures as evidenced by diesel generator bldg settlement MCKINLEY.J C ACRS Advisory Committee on Reactor Safeguards BX14 O21 B0/05/09 TAM, P ACRS Advisory Committee on Reactor Safeguards ip 2650 201 24X Fire 50-029, 84/07/18, 8408010061
- --8408010202 Forwards portions of FSAR for review of soil/foundation problems Site visit & subcommittee meeting will be arranged MCKINLEV.J C ACRS Advisory Committee on Reactor Sefeguards BX14 022 80/03/21 03\*ERRERGO.J D Northwestern Univ . Evanston. IL ip 26500 202 24% Fiche 50-329,84/07/18,8408010061
- --B40B010204 Discusses facility safe shutdown boration capability B&W Mater Reactors Bubcommittee review to explore proposed fires suggested MULLER.R ACRS Advisory Committee on Reactor Bafeguards BX14 D23 79/11/14 ETHERINGTON,H ACRS Advisory Committee on Reactor Safeguards ip 26500 207 24X Fiche 50-329,84/07/18,
- --8408010206 Summary of 790718 meeting w/util onsite re abnormal settlement of fill & structures Agenda & vieugraphs encl ZUVOR: D J ACRS Advisory Committee on Reactor Safeguards BX14 O24 79707/31 ACRS Advisory Committee on Reactor Safeguards 78pp 26500 210 24X Fiche 50-329.84/07/18:8408010061
- --8408020038 Lists questions asked of util during FSAR & 10CFR80 54(f) review.including questions re geological & seismological matters & intake & discharge structures for svc water sys KANE. J NRC -No Petaligd Affiliation Given 817 001 84/07/18 17gp 24514 273 24X Fiche 50-329,84/07/18 8408010061
- --8408020043 Lists questions & responses re condition of sails onsite, correction to foundation problems & risk in allowing const to continue.

  \* NRC No Detailed Affiliation Given BX17 002 79/03/05
  15pp 26514 322 24X Fiche 50-327,84/07/18,8408010061
- --8408020071 Forwards draft answers to util interrogatories re definition of acceptance criteria of 791206 order on mod Opinion as to whether items in brackets should be deleted requested KANE. J NRC No Detailed Affiliation Given 3X17 OO6 81/02/24 HOOD. D NRC No Detailed Affiliation Given ip 26515 058 24X Fiche 50-329,84/07/18,8408010061
- --B403020074 Draft answers to util interrogatories re definition of acceptance criteria on Page 3 of 791206 order on mod

  \* NRC No Detailed Affiliation Given BX17 006A DM 84/07/18
  Consumers Power Co. 87pp 26515 059 24X
  Fiche 50-329, 84/07/18, 8408010061
- --B40B020086 Marked-up copy of Rev 1.Vol 4 to FSAR re stability of subsurface matls & foundations questions re response to Interrogatories 13-16 & interpretations of intent of Interrogatory 13

  KANE.J NRC No Detailed Affiliation Given BX17 QOP 77/11/30
  12pp 26517.309 24X Fiche 50-329.84/07/18.8408010061

- --B408000099 Answers to util interlogatories le starf requests directed on determination \* justification of acceptance criteria applied to various renedial measures taken on pagr 3 of Order PANS, J. NRC - No Detailed Affiliation Given BX(7-010 OM B4/07/18 Consumers Power Co. 31pp. 24517-331 24X Fiche 50-329, 84/07/18, 8408010041
- --8408020107 Forwards motions, 1980 audit repts & input re upcoming util gA decision Applicant acceptance of poor quality performance by Bechtel criticised STAMIRIS, B Stamiris, B BX17 011 81/05/26 KEPPLER. J G Region 3, Office of Director 2pp 26518 [32 24X Fichs 50-329, 84/07/18, 8408010061
- --8408020112 Guestion re distrepanty in magnitude of loading stress on Fig 2 of 800914 rept & info on Tables 4-1A & 2 5-14 NRC - No Detailed Affiliation Given BX17 012 84/07/18 ip 26518 143 24X Fiche 90~329,84/07/18.8408010061
- --8408020122 Provides trip rept for /81107 meeting in Urbana, IL resettlement of far east bay of diesel generator bldg List of correction action options provided CODME.T C Consumers Power Co 8X17 D15 CSC-3474 78/12/12 Consumers Power Co 4pp 26518 264 24X Fiche 50-329, 84/07/18, 8408010061
- --8408020127 Summary of NRC recommendations of ASLB position re Stamiris Contention 2 including draft ASLB proposed findings t input into NRC testimony re Peck 790810 statement on electrical penetration area structures KANE, J NRC - No Detailed Affiliation Given BX17 016 B1/10/19 91pp 26518 268 24X Fiche 50-329,84/07/18.8408010061
- --B40B020171 Summarizes issues to be covered at ASLB 830214-18 hearing, including Standris contentions. Warren contention & seismic shakedown for all structures other than diesel generator bldg

  \* NRC No Detailed Affiliation Given BX17 019 83/01/05 9pp 24519 009 24X Fiche 50-329,84/07/18,8408010061
- --8408020177 Suggests schedule for testimony to answer Warren Contentions
  1-3,8tamiris Contention 4,8inclair Contention 24 5 Marhaall
  Contention 2 in Feb & Mar hearings Test of contentions encl
  Suggests inclusion of rebuttals to contentions
  BLYME. M NRC Ro Detailed Affiliation Given BX17 020
  B2/01/27 HODD.D , MANE, J , RINALDI.F NRC ~ No Detailed
  Affiliation Civen 7pp 26519 020 24X Fiche 50-329,84/07/18,
  8408010061
- --B408020178 Testimony of DS Hood & J Kane re matl false statement identified in NRC 791204 mod order HDGD, D S , HANE, J NRC - No Detailed Affiliation Given BX17 021 B3/01/31 3pp 26519 027 24X Fiche 50-329,84/07/18,8408010061
- --B408020180 Forwards input to staff testimony in preparation for ASLB 821115-23 hearings in response to W Paton verbal request & M Hilcove request Structural Engineering Branch input applicable only to see water pump structure SCHAUBER.F P Structural Engineering Branch BY17 022 82/10/22 ADENBAM.E G Litensing Branch 4 5pp 26517 050 24% Fiche 50-329,84/07/18,8408010061
- --8408020181 Comments on applicant 840805 proposed findings of fact conclusions of law on remedial soils issues. Including items re auxiliary bldg & svc water pump structure POULDES & J. Geotechnical Engineers. Inc. BX17 031 81907-29 83/09/23 KANE.J. Division of Engineering 4pp 26519 242 24X Fiche 50-329.84/07/18.8408010061
- --8408020182 Responds to N Wilcove verbal request Structural Engineering Branch area of concern identified by Judge Harbour applies only to consideration of structure-to-structure interaction Outstanding contentions encl
  SCHAUER, F P Structural Engineering Branch 0X17 023 OL 82/10/28 ADENBAM.E O Licensing Branch 7pp 26517 055 24X Fiche 50-329, 84/07/18,8408010061
- ~~8408020183 Forwards response to applicant proposed findings of fact & conclusions of law on remedial soil issues Pagination needed Findings will be filed 831115
  PATON.W D Hearing Branch 2 BX17 093 83/11/11 KANE, J NRC ~ No Detailed Affiliation Given 1p 26519 315 24X
  Fiche 50-329, 84/07/18, 8408010061
- --8408020184 Forwards marked-up input to staff testimony in preparation for ASLB 821027-1104 hearings re bearing capacity & Underground piping.in response to verbal request of W Paton & M Hilcove Response to Stamiris contention enci LEAR.0 E Hydrologic & Gootechnical Engineering Branch BX17 023A 632/10/14 ADENSAM.E Q Licensing Branch 4 10pp 24519 062 24X Fiche 50-329.84/07/18.8408010061

- --B408020185 Responsive findings to applicant proposed findings of fact & conclusions of law on remedial soil issues PATON.W D. WILCOVE.M N. Hearing Branch 2 BX17 034 OM 83/11/15 100pp 26519 316 24X Fiche 50-329.84/07/18. 8408010061
- --8408020186 Response to R Landsman B30106 questions re B Stamiris
  Request 4(b) re excavation of deep "Q" duct bans in
  Freezewall Pit 4 & Tech Spec for static core penetrometer
  KANE, J NRC No Detailed Affiliation Given BX17 026 83/01/06
  2pp 26519 146 24% Fiche 50-329,84/07/18,8408010061
- --B408020187 Forwards updated version of Stamiris contentions, including add1 Stamiris examples for Contentions 1.2 & 3 & changed wording of Contention 4C NRC testimony must address entl additions & changes
  BROWN.E M NRC No Detailed Affiliation Given BX17 025
  B1/05/19 Consumers Power Co 19pp 26519 124 24X
  Fiche 50-329, 84/07/18, 8408010061
- --B408020189 Forwards applicant testimony re alleged violation of ASLB B2043D order for determination of cross-examination List of questions re excavations & fineline piping provided HILCOVE.M N Hearing Branch 2 BX17 042 83/05/13 LANDBMAN.R. CODK.R. HOOD,D NRC No Detailed Affiliation Given 2pp 24520 114 24X Fiche 50-329.84/07/18.8408010061
- --8408020190 IE Investigation Rept 3-82-061 on 830103-0330 No noncompliance noted Major areas investigated allegations that util violated ASLB 820430 order re NRC approval for excavating in remedial solis program Investigation closed WEIL.C H. PANLICK.E T Region 3, Office of Director 8X17 028 83/06/02 17pp 26519 178 24X Fiche 50-329.84/07/18.8408010061
- --8408020192 Forwards applicant advance copy of meeting notes for 820727-30 design audit of soils renedial activities in Ann Arbor. MI Guestions should be referred to J Kane LEAR. G Hydrologic & Ceotechnical Engineering Branch 8X17 043 GL 82/09/17 ADENBAN.E Licensing Branch 4 22pp 26520 224 24X Fiche 50-329,84/07/18,8408010061
- --8408020193 Informs that Structural Mechanics Assoc seismic margin review studies indicate soil layering profiles & soil properties differ from properties previously addressed KANE, J. Structural & Ocotechnical Engineering Branch BX17 044 82/05/11 LEAR, O. Structural & Ocotechnical Engineering Branch 2pp 26320 247 24X Fiche 50-329,84/07/18,8408010061
- --840B020194 IE Investigation Rept 3-82-061 on 830711-0808. No noncompliance noted Major areas investigated allegations that util violated ABLB 820430 order re NRC approval for excavating in remedial soils program Investigation reapened WEIL.C H. PAWLICK.E T. Region 3. Office of Director WARD.W J. Office of Investigation BXI7 027 83/09/12 20pp 26519 199 24X Fiche 50-329.84/07/18.6408010061
- --8408020195 Summary of 840417 meeting w/TERA. Btructural Mechanics Assoc (SMA) & util in Chicago, IL to discuss SMA seismic margins evaluation & potential applicability to disposition of outstanding civil/structural issues
  RINALDI.F Structural & Seotechnical Engineering Branch BX17
  045 84/07/18 LEAR, 0 Structural & Geotechnical Engineering
  Branch 2pp 26520 249 24X Fiche 50-329.84/07/18.8408010061
- --8408020196 Provides Supplemental Ofc of Investigation Rept 3-82-061 re util alleged violation of ASLB order HAYES.B D Office of Investigation BX17 030 83/09/12 KEPPLER.J G Region 3, Office of Director 3pp 26519 221 24X Fiche 50-329, 84/07/18,8408010061
- --B408020199 Forwards request for add1 structural engineering info needed to continue OL review of NPP application as applicable to seismic marpins review, syc water pump structure & diesel generator blig LEAR, 0 Structural & Geotechnical Engineering Branch BX17 046 B4/05/03 ADENSAM Licensing Branch 4 5pp. 26521 042 24X Fiche 50-329, 84/07/18, 8408010061
- --8408020202 Discusses status of efforts re NRC Midland findings due 831115 Requests meeting at earliest date HODD, D. NRC - No Detailed Affiliation Given BX17 041. 83/09/23 PATON, W. D., WILCOVE, N. N. Hearing Branch 2 7pp 24520 095 24: Fiche 50-329, 84/07/18, 840801006i
- --B40B030001 Handwritten notes & outline of conference call w/Bechtel & util re review of buried piping.monitoring program & future settlement MEIBERHEIMER, J. NRC No Detailed Affiliation Given BX17 047 B1/12/15 dpp 26515, 146 24X Fiche 30-329,84/07/18,8408010061

- --8408030004 Summary of 811004-07 meeting w/util in Bethesda.MD reunderground piping in inadequately compacted plant fill Meeting agenda.attendance list & const hydro test viewgraphs encl HCCD.P S Licensing Branch 4 8X17 048 CM 82/02/05 Licensing Branch 4 35pp 26515 241 24X Fiche 50-329,84/07/18. 8408010061
- --8403030009 Summary of 810721 meeting w/applicant in Sethesda.MD resummary of Ban Onofre neuting on confirmatory analysis of piping sys design Confirmatory analysis encl ROOD.H Licensing Branch 3 BX17 049 81/08/19 Licensing Branch 3 29pp 26515 277 24X Fiche 50-329,84/07/18,8408010061
- --8408030013 Notification of B20416 meeting w/util in Bethesda, MD to discuss bursed piping & related applicant 820316 submittal H/handwritten notes of B20407 conference call & outline of outstanding issues in geatechnical engineering area HODD, D S Licensing Branch 4 BX17 050 DM B2/04/13 ADENSAM, E Q Licensing Branch 4 22pp 26515 306 24X Fische 50-329, 84/07/18,8408010061
- --B40B030020 Handwritten notes on B10120 meeting re stress analysis for underground piping Outline of discussion topics for pipe stress analysis encl KANE.J NRC No Detailed Affiliation Given BX17 052 81/01/20 NRC No Detailed Affiliation Given 18pp 24515 355 24X Fiche 50-329.84/07/18.8408010061
- --8408030028 Agenda for 820121-22 meeting to discuss underground piping concerns W/handuritten summary of 820107 conference call re underground piping & 820120 availation of sand settlement due to earthquake

  KANE.J NRC No Detailed Affiliation Given 8X17 055 82/01/22

  NRC No Detailed Affiliation Given 23pp 26516 017 24X

  Fiche 50-329.84/07/18.8408010061
- --8408030042 Agenda for Bii00A mesting w/Bechtel.util & Army Corps of Engineers to discuss underground piping reprofiling.proposed demonstration solution & 1981 measurement results \* NRC No Detailed Affiliation Given BX17 058 81/10/06 Office of Nuclear Reactor Regulation, Director lipp 26516 045 24X Fiche 90-329.84/07/18,8408010061
- --8408030051 Handwritten notes re add1 boring logs at buried dissel generator fuel oil storage tank location Calculation sheets & boring logs encl MEISENHEIMER.J NRC - No Detailed Affiliation Given BX17 060 82/03/29 KANE,J NRC - No Detailed Affiliation Given 13pp 26516 057 24X Fiche 50-329,84/07/18,8408010061
- --8408030056 Handwritten notes to 810120 meeting w/applicant on settlement of Category I underground piping KANE, J NRC No Detailed Affiliation Given BX17 061 81/02/09 CAPPUCCI.T NRC No Detailed Affiliation Given 4pp 26516 070 24X Fichs 50-329,84/07/18,8408010061
- --B408030058 Forwards evaluation of general acceptability of effects of settlement in several buried svc piping sys Rept partial response to FSAR Questions 16 through 20 & 34 KLEIN, II R Dechtel Corp BX17 062 80/08/01 CURTIS, L H Bechtel Corp 7pp 26516 074 24X Fiche 50-329,84/07/18, 8408010961
- --8408030064 Forwards analysis of buried piping background info.in support of proposed demonstration solution & in response to NRC concern re underground piping Addl angineering info and KEELEY, 9 S. Consumers Power Co 8X17 063 15093 81/12/15
  - enci KEELEY, 9 8. Consumers Power Co BX17 063 15093 81/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 76pp 26516 081 24X Fiche 50-329, 84/07/18, 8408010061
- --8408030068 Forwards stress analysis of several underground pipe lines as profiled in Rev 6 of "Responses to NRC 10CFR30 54(f) Requests re Plant Fill" dtd 800401 BATES, JO Rockwell International Corp BX17 064 80ETEC-DRF-4220 B0/10/01 B08NAK, R J Mechanical Engineering Branch 32pp 26516 162 24X Fiche 50-329,84/07/18,8408010061.
- --8408130227 Contract for consulting svcs between util & Mgt Analysis Consupering to perform technical svcs/including consulting & QA svcs Purchase requisition, internal memos & supporting documentation encl CDDK.J M Consumers Power Co BX15 001 82/01/15 350pp 26500 316 24X Fiche 50-329,84/07/18.8408010061
- --B40Bi30230 Discusses 830118 & 26 mertisgs in Qien Eliyn, IL re Region III insp of dissel generator bldg & independent design review program, respectively Midland project manager will attend 830126 public meeting ADENBAM.E Q Licensing Branch 4 BX15 002 83/01/05 NOVAK, T M. Assistant Director for Licensing 19pp 26502 089 24X Fiche 50-329,84/07/18,840B010061

- --8403130234 Draft nemo re issues of potential impact on Hearing Board considerations concerning QA program KEPPLER, J G Region 3, Office of Director 3x15 003 82/04/02 EISENHUT, D G Division of Licensing 7pp 26502 121 24x Fiche 50-329,84/07/18.8408010061
- ~~8408130241 Notification of 821207 mgt meeting w/Region [II to discuss inplementation of 8A & IDVPs
  HERNAN,R W Licensing Branch 4 8X15 004 82/11/01 NGVAK,T M
  Assistant Director for Licensing 2pp 24502 131 24X
  Fiche 50-329,84/07/18.8408010061
- --8408130244 Forwards SALP 3 schedule Internal memos, handwritten in-process insp notices, program notes & supporting documentation encl
  TAMBLING: T N Region 3, Office of Director 8:15 005 82/11/0 Region 3, Office of Director 33pp 26502 133 24X Fiche 50-329,84/07/18,8408010061
- --B40B130235 Forwards response to draft BALP rept Requests meeting w/ Peppler to review detailed contents of response Internal nemos & handwritten notes encl COOK.J W Consumers Power Co BXIS 006 174B5 B2/05/17 KEPPLER.J G Region 3, Office of Director 91pp 26502 18B 24X Fiche 50-329,84/07/18,840B010061
- --B408130269 "Const Project Evaluation of Consumers Power Co.Midland Energy Ctr Project.Units 1 & 2 (Observations) " # Management Amalysis Co BXIS 007 B3/01/31 16Opp 26502 311 24X Fichs 50-329,84/07/18,8408010061
- --8408130290 Forwards Mgt Analysis Co assessment of Midland GA program Rept endorses program W/o encl CODK. J W Consumers Power Co BX15 008A 12715 81/06/01 KEPPLER. J G Region 3. Chicago, Office of the Director (81/03/01) 40pp 26503 178 24X Fiche 50-329.84/07/18.8408010061
- --B40Bi303Di Submits changes to be implemented prior to util resuming remedial soils work Draft list of noncompliances & deviations, handwritten notes & list of events since Jul 1981 hearings encl
  MARNICK, R F Region 3, Office of Director BXIS 010 B2/09/20
  KEPPLER, J G Region 3, Office of Director 70pp 26504 031 24X Fiche 30-029, 84/07/18, 8408010061
- --840Bi30306 "Biennial QA Audit of Midland Plant.Units 1 & 2 " Opening remarks of NRC 830208 neeting w/util & independent review sncl 
  \* Management Analysis Co BX15 011 B3/03/01 75pp 26504 131 24X Fiche 50-329.84/07/18.8408010061
- --8408130311 Notification of significant licensee 830315 meeting in Glen Ellyn. IL to present IMPO findings

  \* Region 3, Office of Director BX15 012 B3/03/09 Region 3
  Office of Director 1p 26504 261 24X Fiche 50-329, 84/07/18, 8408010064
- --B408130315 Testimony of JO Keppler re GA problems at facility & corrective actions taken
  KEPPLER.J C Region 3. Office of Director BX15 012A B4/07/18
  25pp 26504 262 24X Fiche 50-329:84/07/18:8408010061
- --8408130320 Forwards status rept for Midland Project for Jan 1983 W/o encl HARNICK,R F Region 3, Office of Director BX15 013 83/02/14 KEPPLER.J G Region 3, Office of Director 1p 24504 293 24X Fiche 50-327,84/07/18,8408010061
- --8409130323 Forwards status rept for Jan 1983 Rept contains input from each member of insp site team of Oft of Special Cases CODA: R J Region 3. Office of Director DX15 014 B3/02/10 SHAFER; W D Region 3. Office of Director 3pp 26504 294 24X Fiche 50-329,84/07/18.8408010061
- --8408130327 Forwards monthly status repts for Aug-Oct 1982 HARNICK.R F Region 3. Office of Director DX15 013 82/12/20 KEPPLER.J G Region 3. Office of Director 10pp 26504 303 24X Fiche 50-329,84/07/18,8408010961
- --8408130336 Requests approval not to perform SALP 3 assessments, due to widespread recognition of mgt.QA & const problems Draft notice of violation, insprept & handwritten notes re diesel generator bldg monorail encl KEPPLER.J O Region 3. Office of Director BX15 017 83/04/01 DEVOUNG.R C Director's Office, Office of Inspection and Enforcement 98pp 26505 043 24x Fiche 50-329.84/07/18. 8408010061

- --8409130348 Submits issues to be addressed at forthcoming evidentiary session on QA & GC matters
  PATCH, W D Consumers Power Co BX15 019 82/08/10 ADENSAM, E G ARC No Detailed Affiliation Given App 24505 276 24X Fiche 50-329, 84/07/18, 8408010061
- --840813J356 Forwards monthly status rept for Midland Project for Jan 1983 CDDK,R J. Region 3. Office of Director BX15 022 83/02/10 SHAFER,W D. Region 3. Office of Director 3pp 26505 302 24X Fiche 50-329,84/07/18,8408010061
- --B408140039 Dra+t IE Insp Repts 50-329/78-20 & 50-330/78-20 from insp an 781211-20 & 790104-25 Violations noted inadequate control & supervision of plant fill mall placement & const specs not followed PHILLIP.G A. GALAGHER, E. J. MAXWELL.G F. Røgian G. Office of Director RV16 002 50-330/78-20 84/07/18 60pp 26507 112 24X Fiche 50-329,84/07/18,8408010061
- ---B40B140050 Summary of NRC 790607 site tour & menting on differential settlement of plant bldgs TC Cooke 790706 ltr to Bechtel restainless steel pipe deficienty ental COOKE.T C Consumers Power Co BX16 003 CSC-4138 79706/13 Consumers Power Co 4pp 26507 311 24% Fithe 50-329. B4/07/18. B40B010061
- --8408140055 Preliminary "Discussion of NRC Insp Facts Resulting From NRC Investigation of Diesel Generator Bldg Settlement" + Consumers Power Co. 8416 004 79/03/09 39pp 26507 315 24% Fiche 50-329,84/07/18.8408010061
- --B40B140060 Forwards synopsis of B00228 presentation. "Remedial Measures for Electrical Penetration Wings of Control Bldg & Isolation Valve Pits" conducted before NRC representatives in Midland, MI GOULD, C.H. Affiliation Nat Assigned BX16 005 B0/03/17 AFIFIS S. Bechtel Corp. 22pp. 26507 350 24X Fiche 50-329,84/07/18,8408010061
- --B409140065 Forwards general procedures & details employed by contractor to underpin fine arts bldg Sketches enci MARR.G Bechtel Corp BX16 006 79/04/25 AFIF1.S Bechtel Corp 6pp 26508 010 24X Fiche 30-329,84/07/18,8408010041
- --8408140069 Lists areas to be clarified %/or amplified,in responses to 10CFR50 54(f) questions Summary of soils chronology % 790807 internal meno re pre-neeting W/consultants encl COOKE,T C Consumers Power Co B&16 007 CBC-4763 BO/01/25 ROTHWELL,M O Bechtel Corp 14pp 26508 016 24X Fiche 50-329,84/07/18,8408010061
- --8408140071 Submits const QC response to 790329 questions re diesel generator bldg No variance exists from QA program requirements
  JUHNSON, D. R. Bechtel Corp. BX16 008 2-CQC-402679 79/04/09
  RICHARDSON, O. L. Bechtel Corp. 9pp. 26508 030 24X
  Fiche 50-329,84/07/18,8408010061
- --8408140076 Comments on recommendations given in soils repts prepared by Dames ? Moore as compared to Bechtel earthwork specs Plant area fill supporting surrounding structures, Category I slopes & berm fill discussed AFIFI.5 S Bechtel Corp BX16 009 74/09/13 CABILEBERRY, R Bechtel Corp 5pp 26508 039 24x Fiche 50-329, 84/07/18, 8408010061
- --B408140079 Recommends issuance of revised TPO atd specs re large settlement due to incorrectly placed backfill Addl correspondence on problem alert & summary of soils chronology encl RUMBAUGH. E Dechtel Corp 3Y16 010 79/12/27 JOHNSON, T E Bechtel Corp 39p 26508 044 24X Fiche 50-3R9, 84/07/18, 8408010061
- --8408140102 Forwards tomplete set of all abstracts of transcripts of hearings conducted on 811231-830630 W/listing of entire set of abstracts HAMPTON.L Isham. Lincoln & Beale BX16 012 83/07/18 PATON.W D Hearing Branch 2 425pp 26508 097 24X Fiche 30-329,84/07/18,8408010061
- ---8408140134 Handwritten notes re borings in area of svc water piping that have indicated potential for liquefaction W/Dept of Army memo re feb 1980 visit to util & review of FBAR KANE. J NRC -- No Detailed Affiliation Given 8416 014 82/10/14 19pp 26510 227 24X Fiche 50-329.84/07/18.8408010061

- --8408140144 Testimony of HN Singh re unresolved geotechnical engineering safety issues, including reactor bldg foundation, diesel generator bldg settlenent & svc water bldg foundation & borated water tanks
  SINGH.H N Army. Dept of, Corps of Engineers BX16 016
  84/07/18 13pp 26510 319 24X Fiche 50-329,84/07/18,8408010061
- --B408140152 Handuritten notes on admission of facts re plant fill problem % cracking of certain safety-related structures resulting from inadequately compacted fill matis W/handuritten notes re discussion w/B Paton on hearings % NRC No Detailed Affiliation Given BX16 017 81/03/06 2pp 26510 331 24X Fiche 50-329.84/07/18.8408010061
- --8408140158 Notifies of plan to take depositions of Bechtel employees in Ann Arbor beginning on 801207 Depositions will address errors made in soil placement PATON, W D Office of the Executive Legal Director BX16 018 80/11/17 DLMSTEAD, U J Regulations Division 2pp 26510 333 24X Fiche 50-327,84/07/18,8408010061
- --B408140163 Presents reasons why Phase II const will not be detrimental to foundation support of auxiliary bldg Phase II primary consists of 3x6 ft hand dug piers & 7x6 ft wide access drifts for access to pier KANE.J., DARTLETT, D. HRC No Detailed Affiliation Given 8x16 019 82/01/19 1ipp 26510 335 24X Fiche 50-329,84/07/18,84/8010061
- --8408140170 Handwritten notes re general description of extent of plant fill problem Proposed remedial measures, list of viewgraphs & viewgraphs for ACRS presentation encl KANE, J NRC -- No Detailed Affiliation Given BY16 020 82/04/26 37pp 26510 346 24X Fiche 50-329,84/07/18,8408010061
- ---B40B140185 Confirms comments previously provided re Item E on Page 5 of B30715 ltr concerning slope layback during underpinning Item E expresses concern by StW inspectors that slope layback is greater than in design POULDS,8 J Gentechnical Engineers, Inc. BX16 022 B10707-28 B3/09/22 KANE.J Office of Nuclear Reactor Regulation, Director 20p 26511 029 24x Fiche 50-329,84/07/18,8408010061
- --8409140196 Summarizes comments re B30914-15 audit of facility underpinning Purpose of audit was to gather info from applicant re effect on design & const of reducing modulus of hard clay foundation from 3000 Ksf to 5000 Ksf P0ULDS,S J Geotechnical Engineers, Inc BX16 O23 B1907-27 B3/07/22 KAME. J Dffice of Nuclear Reactor Regulation, Director 3pp 26511 031 24X Fiche 50-329,84/07/18,8408010061
- --8408140207 Handwritten notes re design details for borated water storage tanks & util position on cause of cracking KANE. J NRC - No Detailed Affiliation Olven 8X16 024 81/07/28 2pp 2651 050 24X Fiche 30-327.84/07/18.8408010061
- --8408140213 Handwritten summary of B10805 meeting in Ramada Central Inn re borated water storage tank W/B1072B handwritten memo re status of revieu on borated water storage tank KANE.J NRC - No Detailed Affiliation Given BX16 025 81/0B/05 NRC - No Detailed Affiliation Given 2pp 26511 032 24X Fiche 50-329, B4/07/18, 8408010061
- --B408140218 Handuritten notes re discussion w/G Gallagher about surcharging of valve pits near borated water tanks Record of telcon w/util Bechtel & Geotechnical Engineering on B10715 re surcharging valve pits encl

  \*\*NRC No Detailed Affillation Given BX16 026 B1/07/01 4pp 26511 054 24X Fiche 50-329,84/07/18,8408010061
- --B40B140223 Handuritten notes reviswing comments on borated water storage tanks & valve pit settlements KANE.J NRC - No Detailed Affiliation Given BX16 027 B1/07/28 ip 26511 074 24% Fiche 50-327.84/07/18.8408010061
- --8408140232 Forwards draft comments on info received from applicant through Amend 85 to DL request & Rev 10 to 10CFRSO 54(f) requests re borated water tanks Info received addresses all questions raised in 800707 ltr MCCALLISTER: P Army, Dept of. Corps of Engineers BX16 028 81/03/26 JACKSON.R E NRC No Detailed Affiliation Given 14pp 26910 079 24X Fiche 50-929,84/07/18.8408010061
- --8408140242 Forwards branch position re seismological input parameters
  Position necessary to resolve differences between applicant
  4, NRC on seismological issues & to provide guidance for
  inputing vibratory motion in evaluations
  JACKSDN.R E Geosciences Branch BX16 030 80/07/08
  SCHMENICER, A Licensing Branch 3 6pp 26511 101 24X
  Fiche 90-329,84/07/18,8408010061

- --8408140218 Urges studies evaluating soil liquefaction & stability under dynamic loading & using values of acceleration in range of 0 17g to 0 17g at ground surface Also forwards list of strong motion records RUTHMAILE Coesciences Branch BX16 031 80/02/11 JACKSON, R E Geosciences Branch 9pp 26511 107 24X Fiche 50-329,84/07/18.8408010061
- --8408140258 Handuritten notes re ASLB actions on 800527 motion to consolidate for discovery, evidentiary presentation & fact finding purposes issues concerning soil conditions for safety-related structures & sys KANEJ NRC No Detailed Affiliation Given EX16 033 80/06/09 ip 26511 158 24X Fiche 50-329.84/07/18,8408010061
- --B40Bi40263 Motion to consolidate for discovery, evidentiary presentation & fact finding purposes issues relating to soil conditions for safety-related structures & sus Founded in & on plant fill math in hearing considering 791266 order FARNELL, A S Consumers Power Co FARNELL, A S Isham, Lincoln & Beale BXI6 034 DM 80/05/27 Atomic Safety and Licensing Board Panel 15pp 26511 159 24x Fiche 30-329,84/07/18, B408010061
- --B40B1402B6 Testimony of H Singh re origin remedial measures proposed by applicant for auxiliary bldg & Corps of Engineers evaluation of remedial measures SINGH.H NRC - No Detailed Affiliation Given BX16 03BB B1/11/12 3pp 26511 242 24X Fiche 50-329.84/07/18.8408010061
- ~~8408140296 Draft testimony of SJ Poulos re remedial underpinning of svc water pump structure PCULDS.S J Geotechnical Engineers, Inc BX16 040 82/03/30 11pp 26511 271 24% Fiche 50-329,84/07/18.8408010061
- --8408140300 Testimony of HN Singh re svc water pump structure SINOH.H N Ocotechnical Engineers, Inc. BX16 041 OK 82/04/08 7pp 26511 282 24X Fiche 50-329,84/07/18,8408010061
- --8408140319 Summary of 810917 meeting w/CPC,US Army Corps of Engineers, NRC.Bechtel & Mueser,Rutledge,Wentworth & Johnson in Bethesda.MD re-preliminary design of proposed remedial measures for svc water pumping structure SINGH.H N Army, Dept of, Corps of Engineers BX16 044 81/09/18 Army, Dept of, Corps of Engineers 3pp 26511 341 24X Fiche 50-329,84/07/18,8408010061
- --8408140347 Summary of 820422 meeting w/CPC, consisting of answers to GES questions re permanent dewatering sys. soil stabilization, jacking procedure & draft SER KANE. J. NRC No Detailed Affiliation Given BX16 046 82/06/25 NRC No Detailed Affiliation Given 4pp 26511 348 24X Fiche 50-329, 84/07/18, 8408010061
- --8408140352 "Dynamic Core Penetrometer" Sketchs & design calculations of underprinning & settlement analysis study encl ANDERSON, J NRC No Detailed Affiliation Given BX16 047 BZ/03/17 42pp 26512 036 24X Fichs 50-327.84/07/18, 8408010061
- --8409140359 Handwritten notes re settlement monitoring programs, classification of fines, instrumentation & agenda for 781204 meeting re diesel generator bldg \*\* NRC No Detailed Affiliation Gives BX16 049 84/07/18 10pp 26512 210 24X Fiche 50-329,84/07/18,8408010061
- ---8408140367 Draft ltr re Interagency Agreement NRC-03-76-167. Task 1.
  Subtask 3 concerning comment on Amend 85 List of specific
  discregancies re settlement evaluations encl
  SINGH, H Army, Dept of, Corps of Engineers BX16 051 81/02/26
  XANE.J. JACKBON, R E NRC No Detailed Affiliation Given 13pp
  26512 221 24X Fiche 50-329, 84/07/18,8408010061
- ---B409140313 Bummary of R Landsman B10925-27 & 0407-09 insps conducted to verify 9A program for util soil borings conducted in response to Corps of Engineers request for addl soil info \* NRC No Detailed Affiliation Given BX16 054 B4/07/18 4pp 26512 259 24X Fiche 50-329.B4/07/18 8408010061
- --8408140522 Informs that, in preparation for issuance of draft SER in mid-late Jan, section by section review of which sections of draft received by Div of Licensing to date complete HERNAN, R W Licensing Branch 4 BX16 055A 82/01/12 ADENSAM, E O Licensing Branch 4 3pg 26512 267 24X Fiche 50-329,84/07/18,8408010061
- --B40Bi40526 Summarizes Bi060B stipulation filed by util & NRC re QA aspects of hearing on soils settlement scheduled to begin 810707 MODD. D. Licensing Branch 4 BX16 056 OM, Bi/06/OB DENTON:H. CARTER.J. Office of Nuclear Reactor Regulation, Director EISENHUT.D G. Division of Licensing 1p 26512 272 24X Fichs 50-329.84/07/16.840B010061

- B40B140530 Draft nemo providing estimate for completing review & preparing testimany on proposed remedial actions in response to DELD request for schedule for review LEAR, J NRC No Detailed Affiliation Given BX16 057 B1/06/19 KMIGHT.J NRC No Detailed Affiliation Given 3pp 26513 1B5 24% Fishe 50~327,84/07/18,8408010061
- -B408140537 Requests estimate of time required to complete review & prepare tostimony re proposed remedial actions Testimony by F Rimaidi.T Cappucci & J Kane needs to be filed by 810915 PATON.H D Office of the Executive Legal Director BXI& 057A 81/07/18 KNIGHT.JP Assistant Director for Comp & Structures Engineering (Pre 830201) ip 26513 188 24X Fiche 50-329,84/07/18,8408010061
- -8408140553 Util news ltr re lifting of part of series of stop work orders that halted const of plant \* Consumers Power Co 8x16 Odl 84/01/20 1p 26513 249 24x Fiche 50-329,84/07/16,8408010061
- -8408140556 Documents contacts by Kirkland & Ellis attys representing Dow Chemical in suit against CPC Summary of meeting by Geotechnical Engineering Inc encl RANE, J D Structural & Geotechnical Engineering Branch BX16 062 84/01/23 Structural & Geotechnical Engineering Branch 14pp 26513 263 24X Fiche 50-329,84/07/18,8408010061
- --8408140357 forwards comments re applicant submissions concerning cracks in diesel generator fixation of cracks in borated water storage tanks underplinings & effects or cracks on serviceability of structures

  MCGALLISTER.P Army, Dept of Corps of Engineers BX16 063
  82/06/15 LEAR. O Division of Engineering 14pp 26513 277
  24X Fiche 50-329,84/07/18
- --B408140562 Handwritten document summarizing util response to NRC Guestions 24,45 & 47 on permanent dewatering re geotechnical angineering issues Meeting summaries encl # Consumers Power Co BX16 064 B1/10/12 32pp 26513 291 24X Fiche 50-329.84/07/18.8408010061
- --8408140565 Handwritten document re liquefaction analysis
  KANE.J C NRC No Detailed Affiliation Given BX16 065
  82/08/16 5pp 26513 323 24X Fiche 50-329.84/07/18,8408019061
- --8408140566 Requests analysis of possible enforcement action reapplicant failure to inform NRC of settlement of disabl generator bldg PALLADIMO, NRC -- No Detailed Affiliation Given BX16-066 84/05/24 DIRCHS, W Office of the Executive Director for Operations ip 26514-031 24X Fiche 50~327,84/07/18,8408010061
- --8408140570 "Administrative Bldg Foundation Settlements Along Column Line 0 4" \* Bechtol Corp DX16 068 77/12/31 21pp 26914 033 24X Fichs 50-329,84/07/18.8408010061
- --BA09140973 Forwards Bechtel rept. "Administrative Bldg Foundation Bettlements Along Column Line O 4 " BRUNNER.J E Consumers Power Co BX16 067 B1/09/14 PATON.H NRC - No Detailed Affiliation Given 1p 26514 032 24X Fiche 50-329.84/07/18.8408010061
- --8408140575 Handwritten summary of 781204 site meeting re excessive settlement of dissel generator bldg 5 foundations & other Category I structures OALLAGHER. O Region 3. Office of Director BX16 069 78/12/07 HDDD. D NRC No Detailed Affiliation Given Spp 26514 068 24x Fiche 50-327,84/07/18,8408010061
- --8408190019 Requests add1 borings & existing soil data Revised Encl i to 800327 ltr encl MCCALLISTER,P Army, Dept of, Corps of Engineers BX16 071 84/07/18 JACKBON.R E NRC - No Detailed Affiliation Given 6pp 26314·140 24X Fiche 50-D29.84/07/18.8408010061
- --8408150019 Handwritten notes re status of ASLB hearings First session, completed 810707-17, covered items re Stamtris Contention I, QA breakdown, NRC-util stipulation on QA managerial attitude & FSAR false statement KANE. J NRC No Detailed Affiliation Given BX16 072 B1/0B/18 11pp 26514 146 R4X Fiche 50-329,84/07/18,8408010061
- --8408150022 Handwritten notes re location of sources of important util submittals prior to 791204 Topics outlined include auxiliary bldg, diesel generator bldg, borated water storage tank & permanent deuatering KANE, J NRC No Detailed Affiliation Given BX16 073 81/05/18 31pp 26514,157 24X Fiche 50-329,84/07/18,8408010061

- --8408190027 Summary of 840304 meeting w/util re schedules & topics for instant hearing on soils matters Hearing schedule resulting in inefficient reviews due to changing const priorities by applicant HOOD.D Licensing Branch 4 BX16 075 82/03/11 TEDESCO.R L Assistant Director for Licensing 43pp 26514 191 24% Fiche 50-329,84/07/18.8408010061
- --8408150029 Task Interface agreement re plant remedial soils issue
  IPPOLITO,T Region 3. Office of Director NORELIUS.C Director's
  Office, Office of Inspection and Enforcement VOLLMER,R Defice
  of Nuclear Reactor Regulation, Director BX16 076 TAC 31241
  83/04/18 5pp 26514 234 24X Fiche 50-329.84/07/18.8408010061
- --8408150033 Discusses 830929 conference call during which D Hood gave verbal approval to allow licenses to proceed w/underpinning through UATs
  LANDSMAN,R B Region 3, Office of Director BX16 077 B3/09/30
  Region 3, Office of Director Ip 26514 241 24X
  Fiche 50-329,84/07/18,8408010061
- --8408150042 Handwritten hotes commenting on Peck 810807 transcript re compaction criteria KANE.J NRC - No Detailed Affiliation Given BX16 079 81/08/10 2pp 26514 264 24X Fiche 50-327.84/07/18.8408010061
- --8408150046 Handwritten notes re electrical penetration area w/comments of H Singh on unresolved issues prior to 791206 & underground utils SINOH.H NRC No Detailed Affiliation Given 8X14 080 81/05/20 2ρρ 26514 266 24X Fiche 50-329.84/07/18.8408010061
- --8408130360 Comments on licensee draft commitments to improve implementation of quality program in remedial soils area & remaining const activities.per 820907 request Noted changes should be made in program
  WARNICK.R F Region 3, Office of Director BX21 001 B2/09/24
  WEPPLER.J G Region 3, Office of Director 4pp 26349 080 24X
  Fiche 50-329,84/07/18,8408010061
- --8408150566 "Pier Load Test Data Load by Carlson vs Load by Jacks " Related info encl HUNT: 5 W Bechtel Corp. BX21 003 83/04/29 200pp. 26549 215 24X Fiche 50-329,84/07/18.8408010061
- --8408150571 "Well OB9-4 Subsidence Rept " HUNT: 8 N Bechtel Corp BX21 004 82/06/11 50pp 26550 120 24X Fiche 50-329,84/07/18,8408010061
- --8408130377 Forwards recent audit repts by Midland GA dapt, per request BHUNNER, J E. Consumers Power Co BX21 005 DM 82/01/15 BECHMOEFER, C. | | IARBOUR, J Atomic Bafety and Licensing Board Panel COUMAN, F P Affiliation Not Assigned Rapp 26550 222 24X Fiche 50-329, 84/07/18, 8408010061
- --8408190386 Forwards recent audit repts by Midland QA dept.per request Related info encl.including notes of CPC/NRC 830208 public meeting re-const completion program BRUNNER.J E Consumers Power Co BX21 006 OM 82/02/05 BECCH-HOEFER, C, HARBOUR, J Atomic Safety and Licensing Board Panel COMMAN.F P Affiliation Not Assigned 106pp 26550 248 24X Fichs 50-329,84/07/18,8408010061
- ---B40B150395 Opposes issuance of fuel license (10CFR70) for applicant, based upon extensiveness of remedial soils work & potential for work to impact auxiliary bldg Related info encl COOK, R J Region 3, Office of Director BX21 007 B3/01/25 BHAFER, W D Ragion 3, Office of Director 19pp 26551 001 24X Fiche 50-329, 84/07/18, 8408010061
- --8408150603 Forwards Midland monthly status repts for Aug-Sept & Nov 1982 Related info encl WARNICK,R F Region 3, Office of Director BX21 008 82/12/20 KEPPLER.J G Region 3, Office of Director. 23pp 26551 256 24X Fiche 50-329,84/07/18,8408010061
- --\$408150608 Rev 4 to "Guality Plan for Underpinning Activities." Relateinfo enci BIRD,W , BOOB, A J , MODNEY, J Consumers Power Co BX21 007 82/10/12 59pp 24551 316 24X Fiche 50-329,84/07/18,840801006i
- --8408150612 Draft final SSER re geotechnical engineering Related info encl KANE, J D Hydrologic & Geotechnical Engineering Branch BX21 010 82/08/12 78pp 26553 002 24X Fiche 50-327,84/07/18, 8408010061

- --B408150616 Enumerates QA issues to be addressed at evidentiary session in Midland proceeding.per and 820707 memorandum & order W/o enci
  PATON,W D Office of the Executive Legal Director BX21 011
- encl
  PATON, W D Office of the Executive Legal Director BX21 011
  B2/08/10 ADENSAM.E C NRC No Detailed Affiliation Given 201
  26553 087 24X Fiche 50~329.84/07/18.8408010061
- --8408150617 Forwards further response to FOIA-84-96.consisting of records selected from files of Harrison & Norelius during 840628 visit
  RDV.Q W Office of Resource Management, Director 8X20 001 84/07/06 RICE,C M Kirkland & Ellis 3pp 26537 339 24X Fiche 50-329, 84/07/18,8408010061
- --8408150622 Discusses basis for recommendation to extend SALP III evaluation period from 820630 to 821231, per 820719-20 discussions Related info encl CODM, R J Region 3. Office of Director 8X21 012 82/08/06 SPEEBARD, R L Division of Project & Resident Programs 13pp 26553 145 24X Fiche 50-329,84/07/18,8408010061
- --B408130624 Draft summary of NRC B40229 meeting w/util at Region III ofc re results of NRC HVAC insps & investigation of allegations & expansion of QA training qualification & certification activities Viewgraphs encl # Region 3. Office of Director BX20 002 B4/02/29 Region 3. Office of Director 21pp 26537 342 24X Fiche 50-329,84/07/18, 8408010064
- --8408150626 Forwards HR Denton B31219 itr distinguishing between terms "important to safety" & "safety-related " Related info encl KEPPLER, J G Region 3, Office of Director BX21 013 83/12/29 Region 3, Office of Director 5pp 26553 163 24X Fiche 50-329,84/07/18,8408010061
- --B40B130630 Forwards addl info re Region III inquiries into Ofc of Special Cases concerning Midland & Zimmer Nuclear Power Plant problems in implementing GA programs Nonconformance rept also encl
  HARNICK.R F Region 3, Office of Director BX20 003 83/09/16
  BOULDEN.H Office of Inspector & Auditor 18pp 2653B 001 24
  Fiche 50-329,84/07/18,8408010061
- --8408130633 Forwards Rev 4 to "Region III SALP Schedule " Schedule changes to listed facilities explained in remarks sections of schedule Addl handwritten notes also encl NORELIUS, C E Region 3, Office of Director IX20 004 84/06/04 KEPPLER, J G , DAVIS, A B , SPESSARD, R L Region 3, Office of Director 22pp 24538 025 24X Fiche 50-329,84/07/18,8408010061
- --8408130635 Notifies that commercial operation date of Unit 2 may be delayed until mid-1986 Const schedule for Unit 1 will be revised based on cashflow requirements, need for power, final cost estimates & schedule for Unit 2
  KOSCHIK.M 0 Consumers Power Co BX21 015 83/11/09 STRASMA, J
  Region 3, Office of Director 2pp 26553 216 24X
  Fiche 50-329,84/07/18,8408010061
- --8408130439 Discusses Ofc of Special Cases special insp on 821012-1125 & forwards draft notice of violation re significant breakdown in implementation of GA program Handwritten NRR comments also encl
  KEPPLER, J G Region 3, Office of Director BX20 005 EA-83-003 83/01/05 CODK, J W Consumers Power Co 84pp 26538 049 24X Ficha 50-329, 84/07/18,8408010061
- --8408130640 Ack receipt of 830926 ltr & payment in amount of \$116,500 for civil penalty imposed by 830829 order AXELRAD, J A Enforcement Staff BX21 016 EA-83-003 83/10/04 SELBY, J D Consumers Power Co 2pp 26553 305 24X Fiche 50-329,84/07/18,8408010061
- --8408150443 Forwards listed documentation in response to FOIA 83-397 for reproduction WARNICK/R F Region 3, Office of Director BX20 004 83/07/20. SMIDTH/P T Region 3, Office of Director ip 26538 156 24% Fiche 50-329,84/07/18,8408010061
- --B408130644 Forwards payment in amount of \$116,500 in response to 830827 ltr imposing civil penalty for violations found during Insp 83-23 (EA 83-03). Related info encl. including metl on 83081 public meeting BX21 017 25714 83/09/26 DEYGUNG, R C Director's Office, Office of Inspection and Enforcement 27pp 26534.005 24X Fiche 50-329,84/07/18,840810041
- ---B408150648 Draft summary of NRC Caseload Forecast Panel 830419-21 meeting w/util at plant site re basis for util revised estimates of Oct 1984 & Feb 1985 for Unit 2 & 1, respectively Rept on Rev 12 schedule encl NOVAK.T M Assistant Director for Licensing BX20 007. B3/05/25 COOK.J W Consumers Power Co. 32pp 26538 157 24X Fiche 50-329,84/07/18,8408010061

- --8408150651 Requests NRC approval to postpone yellowbook update due to imadequate work experience enabling development of definitive project schedule.per B31014 ltr GUAME,D L Consumers Power Co BX20 008 CSC-7161 84/01/12 HARTFIELD.R A Management Information Branch ip 26537 002 24X Fiche 50-327,84/07/18,8408010061
- --B40B150652 Notifies of intent to continue const of plant following recent notification from Dow Chemical Co of decision to terminate agreement to purchase energy Related info encl FITZPATRICK, R Consumers Power Co BX21 019 B3/07/15 STRASMA, J Region 3, Office of Director 72pp 26554 061 24X Fiche 50-329,84/07/18,840B010061
- --B40B130656 Responds to 840409 comments re util proposed plan to conduct independent mgt appraisal of Midland Nuclear Project Affidavits of independence of individuals working on audit encl
  REHM.T A Diffice of the Executive Director for Operations. BX20 OOP 84/06/08 GARDE, B P Government Accountability Project 31pp 26539 014 24% Fiche 30-329, 84/07/18:8408010061
- --840815045B Recommends issuance of board notification for encl potential Part 21 rept from Zack Co (HVAC subcontractor) re accuracy of welder records WARNICK,R F Region 3, Office of Director BX21 020 OM 82/09/01 EIGENHUT.D O Division of Licensing 2pp 26534 179 24X Fiche 50-329,84/07/18,8408010061
- --8408150662 Enumerates agreements/understandings reached at 820823 meeting w/NRC re approval for portions of Phase II underpinning work Related info encl HILLER, D B Consumers Power Co BX21 021 CSC-6266 82/08/25 SHAFER, W D Region 3, Office of Director 14pp 26554 241. 24X Fiche 50-329,84/07/18,8408010061
- --8408150665 Comments on util 840307 proposed independent mgt plan Plan does not indicate how Cresap.McCormick & Paget & TERA will function & interface Roles, authorities & responsibilities should be identified Handwritten comments entl DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 8X20 011 84/03/27 KEPPLER.J 9 Region 3, Office of Director 4pp. 26539 052 24X Fiche 50-329.84/07/18, 8408010041
- --BA08130666 Summary of NRC BA0314 meeting w/D Bridenbaugh of MAB Technical Assocs in Region III re info on Midland & Zimmer plants Util B40124 1tr to Atty General of State of MI and WARNICK, R F. Region 3, Office of Director. BX20 012 B4/03/20 Region 3, Office of Director 7pp 26539 136 24X Fiche 50-329,84/07/18,8408010061
- --8408150669 Corrects Page 3-1 of Attachment 3 to util 820517 response to dwaft SALP rept for Jul 1980 June 1981; clarifying stop work order on drilling COOK.J W Consumers Power Co 8821 024 17249 82/05/21 KEFPLER,J G Region 3, Office of Director 31pp 26554 313, 24X Fiche 50-329,84/07/18,8408010061
- --8408130672 Forwards response to draft SALP rept for Jul 1980 June 1981 discussed at B20426 meeting w/NRC CODK.J W Consumers Power Co BX21 025 17485 82/05/17. KEPfLER.J G Region 3. Office of Director 38pp 26534 344. 24X Fiche 50-329, 84/07/18, 8408010061
- --B408150676 Forwards will testimony on cable pulling incident Requests cumments Lists questions to be addressed WILCOVE,M N Office of the Executive Legal Director 8X20 014, 83/05/13 LANDSMAN.R, COCK,R., GARDNER,R NRC No Detailed Affiliation Given 7pp 26539 306 24X Fiche 50-329,84/07/18, 8408010061
- --BA0B150677 Discusses BALP appraisals for Zimmer & Midland Buggests limited BALP-3 appraisal for Midland to cover remedial soils work B&W work & HVAC activities MEPPLER.J G Region 3. Office of Director BX21 026 83/04/18 HNDJJA Division of Radiological & Materials Safety Programs ip 26555 066 24% Fichs 50-329.84/07/18.8408010061.
- --8408150681 Discusses policy & procedure changes re communications w/
  licenses Related info encl
  HARNICK,R F. Region 3. Office of Director BX21 027. 82/09/17
  SPE8SARD,R L. Division of Project & Resident Programs
  NORELIUB,C E. Division of Engineering HIND,J.A. Division of
  Rediological & Materials Safety Programs. Spp. 26555:067 24X
  Fiche 50-329,84/07/18,8408010061
- --8408150682 Advises that FOIA Request B2-616 received Math requested must be submitted to director by 840103 Nonconformance repts & Interim Rept 3 re cable tray support const welding discrepancy encl SMIDTH.P T Region 3, Office of Director 8X20 015 82/12/22 Region 3, Office of Director 20p. 26939,359 24X Fiche 50-329,84/07/18,8408010061.

- --940B1306B5 Discusses GA program re underpinning instrumentation installation Lists steps to follow to implement reclassification of underpinning activities CCGN, J W Consumers Power Co BX21 028 16779 92/03/31 NURELIUS, C E Division of Engineering 2pp 26535 110 24x Fiche 50-329,84/07/18,8408010061
- --8409190686 Advises that allegations received from Dow Chemical & util are treated equally Forwards & Driker 940504 ltr re Dow Chemical vs CFC lawsuit
  BERKOVITZ, D M Office of the General Counsel 8X20 016
  884/03/11 LEWIS, S H Region 3, Office of Director 1p
  26540 094 24X Fiche 50-329,84/07/18,8408010061
- --8408150687 Submits summary of views re regulatory status of plant Illegible handwritten notes encl KEPPLER.J G Regibn 3. Office of Director BX20 016A 84/06/06 FISCHER.R Michigan, State of 12pp 26540 075 24X Fiche 50-327.84/07/18.8408010061
- --8408150490 Lists reasons why SALP III evaluation period should be extended to 821231.psr 820719-20 discussion Related info encl CODK.r J. Region 3. Office of Director BX21 029 82/08/06 SPESGARD, R L. Division of Project & Resident Programs 21pp 26555 112 24X Fiche 50-329.84/07/18.8408010061
- --8408130492 Forwards hewspaper stories indicating representives of Dow Chemical met L/NRC to discuss matters in litigation pending in County Circuit Court w/util JD Selby B40608 ltr to FJ Kelley encl DRIKER/E Barris, Sott, Denn & Driker BX20 017 84/05/04 BERKOVITZ.D Office of the General Counsel 18pp 26540 160 24X Fiche 50-329,84/07/18.8408010061
- --B409190694 PNO-77-035 on 770226, bulge discovered in containment liner plate Caused by water coming through tears in liner plate Addl holes cut in plate to facilitate draining Related info encl

  MARNICK.R F , ROY.G W , THOMPSON.D Office of Inspection & Enforcement, Office of the Director BX21 030 77/03/01 7pp 26555 154 24X Fiche 50-329.84/07/18.8408010061
- --8408150695 "Site Visit to Evaluate Crack Reported 830218 in Roof of Feedwater Isolation Valve Pit Unit I. Midland Nuclear Power Plant " Draft confirmatory orders, handwritten notes & RF Warnick memo re FOIA Request 84-24 encl CDRLEY, & G Construction Technology Laboratories 8X20 019 83/02/28 111pp 26540 178 24X Fiche 50-329,84/07/18, 8408010061
- ~-8408150698 Forwards monthly status rept for Dec 1983, containing input from insp site team of Ofc of Special Cases COUK.R J Region 3. Office of Director BX21 031 83/01/12 WARNIGK.R F Region 3. Office of Director 2pp 26555 161 24X Fiche 50-329,84/07/18,8408010061
- ~-8408130700 Forwards draft confirmatory order prepared by IE re plan for independent appraisal of wite & corporate mgt organizations Requests review prior to meeting LIEBERMAN, 8 NRC NO Detailed Affiliation Given 8X20 020 83/12/30 KEPPLER, WARNICK, HARRISON NRC No Detailed Affiliation Given 10pp 26540'335 24X Fiche 50-327,84/07/18,8408010061
- ~-8408150702 Advises that Region III has no document re discovery request for info concerning alleged violation of ASLB under concerning remedial soils Handwritten notes.internal memos & list of repts.i977 1983.encl
  HARRIBON.J J Region 3. Office of Director BX20 021 83/10/25
  WRIGHT, N Office of the Executive Legal Director 199pp
  26540 345 24X Fiche 50-329.84/07/18.8408010061
- ~-8408150706 Advises that 9 Lewis leaving Region III to assume position of Deputy Assistant Chief Hearing Counsel in DELD B Berson replacement Chronological list of reactor holddown bult encl
  encl
  MEPPLER, J O Region 3, Office of Director BX20 022 84/05/14
  Region 3, Office of Director 12pp 24541 263 24X
  Fiche 50~329,84/07/18,8408010061
- ~-8408150709 Summary of 800523 meeting w/util,88W,8echtel & Teledyne in Bethesda,MD re preservice failure of three reactor vessel halddown studs List of attendees.agenda & viewgraph slides encl Sketches for underpinning auxiliary bldg encl HOOD,8 S Licensing Branch 3 8280 023 80/07/07 Licensing Branch 3 82pp 26541 328 24X Fiche: 50-329,84/07/18,8408010061
- ~-8408150710 Assessment rept GA program, performed during Mar & Apr 1981 # Management Analysis Co BX21 033 B1/06/01 400pp 26555 182 24X Fiche 50-229,84/07/18,840810061

- --8409150712 "Quality Program for Underpinning Activities" \* Consumers Power Co BX20 024A 82/04/05 22pp 26542 132 24X Fiche 50-329,84/07/18,8408010061
- ---8408150714 'Independent Assessment of Underpinning 90-Day Rept "
  KILBER.W E Stone & Webster, Inc 8X21 034 83/04/30 250pp
  26556 194 24X Fiche 50-329,84/07/18,8408010061
- --8408150716 "Tast Program Status & Rev 12 Test Schedule "
  # Consumers Power Co | BX21 035 | 83/04/12 | 100pp | 26557 091 | 24X Fiche | 50-329, 84/07/18, 8408010961
- --8408150718 Documents conclusions & commitments made at 820330 meeting & 820402 telcons re OA applied to remedial foundation work Expansion of GA program recognized in overall success of project "Guality Program for Underpinning Activities" encl CODK, J W Consumers Power Co 8X20 0248 16161 82/04/05 KEPPLER, J G Region 3, Office of Director 4pp 26542 154 24X Fiche 50-327,84/07/18,8408010061
- --8408150720 "Electrical Raceway Support Tests Rept.Part 1 "
  NOWAK,A S Bechtel Corp BX21 034 B1/11/25 100pp 26557 192
  24X Fiche 50-329.84/07/18.8408010061
- --BA0B150723 Forwards CPC testimony on alleged violation of Board order Investigation of violation coming in future Requests analysis of testimony & comments Handwritten notes encl WILCOVE.M N. Office of the Executive Legal Director BX20 026 OM 83/05/13 LANDSMAN.R, COOK.R, HODD.D. NRC No Detailed Affiliation Civen 99pp 26542 165 24X Fiche 50-329,84/07/18.8406010061
- --B408150725 Requests review of attached draft BALP rept in preparation for 830706 SALP Board meeting
  WARNICK,R F Region 3, Office of Director BX20 027 B3/07/01
  HIND,J A , NORELIUS,C E , SPEBSARD,R L NRC No Detailed
  Affiliation Given 149pp 26542 28B 24X Fiche 50-329,84/07/18,8408010061
- --B408150727 Summarizes B00227-28 meeting at site re soils settlement issue & effects Handwritten note encl
  GALLACHER, E. Region 3. Chicago, Office of the Director BX20 034
  B0/03/03 FIGRELI, O. Region 3. Chicago, Reactor Construction & Engineering Support Branch A6pp 26544 306 24X
  Fithe 30-329,84/07/18,8408010061
- --8408150728 Forwards advance copy of proposed rev to Manual Chapter 0916, SALP, for review NORELIUS, C E Division of Project & Resident Programs BX20 035 84/04/13 Region 3. Office of Director 2pp 26545 069 24x Fishe 50-329,84/07/18,8408010061
- --8408150729 Advises of problems concurring w/proposed response to M Cherry 770427 1tr as noted by detailed comments provided Requests redraft be considered REINMITH.6 W Division of Reactor Construction Inspection 8220 027 77/06/10 HOEFLING.R K Office of the Executive Legal Director 7pp 26543 234 24% Fiche 50-327,84/07/18,8408010061
- --B408150731 Advises of possible ex parte contact in facility proceeding Requests memo & attached summary of discussion be served to all parties in proceeding & PDR GIBBON, T R NRC - No Detailed Affiliation Given BX20 030 CM B0/12/24 CHILK: S J Office of the Becretary of the Commission Rpp 26343 280 24X Piche 30-327,84/07/18.8408010061
- --840B150732 Notifies that incorrect target dates entered in 830219
  SALP schedule Correct target dates provided
  NORELUS.C E Division of Project & Resident Programs BX20 038A
  B4/03/08 HIND.J A Division of Radiological & Materials Safety
  Programs SPESBARD.R L Division of Engineering DOUGHERTY.D J
  Office of Resource Management Director 2pp 26545 117 24X
  Fiche 50-329.84/07/18.8408010061
- --B408150734 Revises previously issued BALP 4 schedule dtd B31004.by extending assessment to 18 months Rev incorporates addl milestone dates
  NORELIUS.C E Division of Project & Resident Programs BX20 0358
  B3712/19 Region 3. Office of Director. 2pp 26545 117 24X
  Fiche 50-327.84/07/18.8408010061
- --8408150735 Requests concurrence on proposed auxiliary bldg guideline.
  "Guidelines for Bldg Movements During Temporary
  Underpinning " Handwritten notes & communications record
  W/Harnick re withdrawal of potential 10CFR50 35(e) encl
  MODNEY.J A Consumers Power Co BX20 031. CSC-7807 84/05/25
  HARRISON.J J Region 3. Office of Director 25pp 26543 252
  24X Fiche 50-329.84/07/18.8408010061

- --B409150737 Forwards NRC Manua) Chapter O516.5ALP Evaluation criteria published in FR on 820322 for public comments Comments due by 820701
  - By BEOVEL TAMBLING, T.N. Region 3, Diffice of Director DX20 039C 82/05/04 AXELSON, W.L., BARRETT, P.A., BOYD, D.C. NRC - No Detailed Affiliation Given 3pp 26545 123 24X Fiche 50-329,84/07/18, 8408010061
- --B408150738 Forwards summary of B40229 meeting in Region III ofc re results of HVAC ineps & investigation of allegations & expansion of training, qualification % certification activities Handuritten notes encl
  WELLS.R A Consumers Power Co BX20 032 28921 84/03/29 HARRISON, J J Region 3. Office of Director 169pp 26544 014 24X Fiche 50-329.84/07/18.8408010061
- --8409130740 "Chapter 0516 BALP," describing basis structure & overall procedures for implementation of NRC program to assess licensee performance MA Miller marked-up memo re evaluation of SALP enc!

  \* Director's Office, Office of Inspection and Enforcement BX20 0350 B2/03/23 47pp 26545 126 24X Fiche 50-329,84/07/18,
- --8409190741 Forwards "Structural Evaluation of Diesel Generator Bldg Assessment of Structural Penformance Capability & Serviceability as Potentially Affected by Settlement Induced Cracking " LEVIN:H A TERA Corp BX20 033 DM 83/01/04 KEPPLER.J G . EISENHUT.D 0 Region 3, Office of Director CODK.J H Consumers Power Co 4pp 26544 212 24X Fiche 50-329.84/07/18.8408010061
- --8400150743 Submits reasons for extending SALP III evaluation period to 821231 Rept contains issues being resolved between NRC & licensee Extension can be used as performance motivator Handuritten note & supporting documentation encl COOK.R J Region 3. Office of Director BX20 036 82/08/06 SPESSARD.R L Division of Project & Resident Programs 350pp 26545 173 24X Fiche 50-329.84/07/18.8408010061
- --B409150745 "Structural Evaluation of Diesel Generator Bldg Assessment of Structural Performance Capability & Berviceability as Potentially Affected by Settlement Induced Cracking " Handuritten notes enci \* TERA Corp BX20 033A 83/01/04 B9pp 26544 216 24X Fiche 30-329,84/07/18.8408010061
- --8408150747 Submits supplemental SALP input for facility Changes required to provide overall Div of Engineering & Technical Insp rating for QA functional area & consolidate comments for recommended increased insp frequency PIRTLE.0 Region 3. Office of Director BX20 037 83/10/01 BOVD. Region 3. Office of Director Ip 26547 011 24X Fiche 50-329,84/07/18,8408010061
- --B408150749 Forwards list of items reviewed by util & determined ready for review & closure by NRC Handwritten notes & supporting documentation encl

  NELLS.R A Consumers Power Co BX20 038A 25261 83/10/04

  KEPPLER.J G Region 3. Office of Director 147pp 26547 165
  24X Ficho 50-329,84/07/18.8408010061
- --B408150750 Forwards SALP input except for Matls & Processes Section PIRTLE.0 Division of Engineering & Technical Inspection BX20 OJB 81/09/22 B0yD.D Division of Engineering & Technical Inspection 137pp 24547 O12 24X Fiche 50-329,84/07/18.
- --B40B150751 Forwards const status rept as of 791001 Handwritten notes re diesel generator bldg & soil settlement & errata to NUREG-0834 encl FIGRELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch B&20 041A 79/10/05 KNDP,R C. HAYES,D W., DANIELSON,D H. NRC - No Detailed Affiliation Given 107pp 2654B 359 24X Fichs 30-329,84/97/18,8408010061
- --B408150792 Submits QA issues to be addressed at evidentiary session in facility proceeding Summary rept % oral communications record re reinsp requirements based on results of centification testing and PATUN. W D NRC No Detailed Affiliation Given BX20 041 B2/08/10 ADENBAME G O, NRC No Detailed Affiliation Given 18pp 26548 075 24X Fiche 50-327,84/07/18,8408010041
- --B408170081 "Response to NRC Staff Review Concerns for Underpinning of Auxiliary Bidg " \* Consumers Power Co 8X19 001 82/06/03 40pp 26529 122 24X Fiche 50-329,84/07/18/8408010061

- --8408170090 Discusses util 820428 telcon notifying that, while drilling well in R area, electric duct bank struck Drawings indicated duct bank elsewhere Investigation continuing SHAFER.W D Region 3. Office of Director 8X19 001A 82/04/28 RILLIAMS.C C. C. LANDSMAN,R B NRC No Detailed Affiliation Given 1p 26529 285 24X Fiche 50-329,84/07/18.8408010061
- --B408170098 Testimony of RB Landsman in Glen Ellyn, iL re GA criteria & proredures to renedial foundation work underway at site LANDGMAN.R B NRC ~ No Detailed Affiliation Given BX19 002 B2/04/19 2pp 26529 332 24X Fiche 90-329.B4/07/18.B408010061
- --8408170102 Forwards add1 documents re facility soils issue, in response to request for info DREHOBL. X E Consumers Power Co BX19 003 16625 82/04/12 FISCHER.D C ACRS Advisory Committee on Reactor Safeguards 7pp 26530 009 24X Fiche 50-329.84/07/18.8408010061
- --B408170119 Confirms that underpinning instrumentation installation will be suspended until procedures & drawings developed & plans & schedules established to inspect & audit activities, per 820319 telcon KEPPLER, J O Region 3. Office of Director BX19 007 CAL 82/03/19 CODK, J W Consumers Power Co 2pp 24530 037 24X Fiche 50-329,84/07/18,8408010061
- ---8408170141 Requests review of files to determine documents withholdable under FDIA, per FDIA-84-96
  LEWIS,S H NRC No Detailed Affiliation Given 8X19 009
  B4/05/08 HARRISON,J J, GARDNER,R , LANDSMAN,R NRC No Detailed Affiliation Given 19 24530 064 24X
  Fiche 50-329,84/07/18,8408010041
- --B408170145 Forwards draft ltr to util re review of licensee 830310.0624 & 0712 responses to 830208 & 0523 notice of violation & proposed imposition of civil penalty Recommends imposition of \$120.000 civil penalty SCHULTZ.W H Region 3. Office of Director BX19 010 83/07/28 AXELRAD.J A Director's Office. Office of Inspection and Enforcement 165pp 26530 067 24X fiche-50-329.84/07/18, 8408010061
- --8408170182 Forwards redrafted insp rept Rept has been reviewed w/NRC for format & content Rept covers insp made 821129-1210 CHARAK.I Argunne National Laboratory 8X19 011 NAP-83-55 82/01/07 WARNICK.R Region 3. Office of Director 7pp 26530 233 24X Fiche 50-329.84/07/18.8408010061
- ---8408170157 Forwards draft insp rept re findings of personnel who participated in routine insps on 821129-1203 & 1208-10 CHARAK, I Argonne National Laboratory BX19 012 82/12/22 HARNICK.R Region 3, 0ffice of Director 14pp 26530, 240 24X Fiche 50-329, 84/07/18, 8408010061
- --B40B170166 Testimony of RN Gardner re allegations concerning qualification of personnel employed by Camstock GARDNER, RN Region 3, Office of Director DX19 012A 84/07/18 100pp 26530 321 24% Fiche 30-329,84/07/18,8408010061
- --B40B170174 Forwards IE Mgt Meeting Repts 50-329/82-09 & 50-330/B2-09 on B20514 NORELIUS, C.E. Region 3, Office of Director BX19 013 B2/06/28 COOK, J.W. Consumers Power Co. 2pp. 26531 039 24X Fichs 50-329, 84/07/18, 8408010061
- --840817018: IE Mgt Meeting Repts 50-329/82-09 & 50-330/82-09 on 820514 Major areas discussed licensee disposition of results of electrical overview insps GARDNER, R N , WILLIAMS, C C Region 3, Office of Director BX19 0134 50-330/82-09 82/06/24 3pp 26531 035 24X Fiche 50-329,84/07/18,8408010061
- --B408170187 Forwards rept results re special electrical overinsp requested by ARC to support testimony concerning adequacy of certification/qualification process of Bechtel electrical QC inspectors

  SHAEFFER, M J Consumers Power Co BX19 015 B2/02/25 CDDKE, R

  NRC No Detailed Affiliation Given BIRD, M R , CDDK, J W

  Consumers Power Co 14pp 26331 04B 24X Fiche 50-329, 84/07/18, B408010061
- --8408170195 Draft "Rept on Cable Installation "

  \* Consumers Power Co BX19 014 82/05/14 111pp 26531 038
  24X Fiche 50-329,84/07/18,8408010061
- --B40B170205 Forwards IE Insp Repts 50-327/82-07 & 50-330/82-07 on B20421-23 No noncompliance noted Schedule for reinsp program of piping suspension sys requested within 25 days from receipt of ltr \*\* Region 3, Dffice of Director BX19 017 B2/07/15 Consumer Power Co 2pp 26531 071 24X Fiche 50-327,84/07/18,840B010061

- --8408170223 Requests Commission review Director's Decisions DD-83-16 & DD-84-02 to require all ongoing activity be included under order of mod of CP & remove util from managerial responsibility of QA/QC function CARDE. B P Obvernment Accountability Project 8x19 022 2 206 84/02/10 PALADINO, N, GILINSKY, V, ASSELSTINE, J Commissioners 72pp 26532 090 24X Fiche 50-329,84/07/18,8408010061
- --8408170232 Forwards SALP Repts 50-329/82-14 & 50-330/82-14 for period Jul 1980 - June 1981 KEPPLER:J G Region 3, Office of Director BX19 026 84/07/18 CCOK:J W Consumers Power Co 2pp 26533 158 24X Fiche 50-329,84/07/18,8408010061
- --B40B170236 Ack receipt of B20114 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-329/81-12 & 50-330/81-12 NGRELIUS.C E Division of Engineering DX19 028 B2/02/03 CCDX,J W Consumers Power Co 4pp 26533 188 24X Fiche 50-329,84/07/18,8408010061
- --8408170253 Discusses W Harshal telcon re permanent dewatering well being drilled at northeast corner of diesel generator bldg on 820519 Drilling mud flushed into line when drilling line broke No further comment necessary LANDSMAN.R B Region 3, Office of Director 8X19 031 82/06/14 PATON.W Office of the Executive Legal Director 2pp 26533 325 24X Fiche 50-329,84/07/18.8408010061
- --8408170257 Summary of ACRS Subcommittee on Midland Units 1 & 2 820520 & 21 meetings w/util in Midland, MI re review of DL application
  FISCHER.D ACRS -- Advisory Committee on Reactor Safeguards. BX19
  032 82/08/07 DXRENT, D ACRS -- Advisory Committee on Reactor
  Safeguards 13pp 26533 357 24X Fiche 50-327,84/07/18,
  8408010061
- --8408170260 Informs of review of encl allegations re Comstock QC at site Ofc of Investigations responsible for continuing investigation WARNICK, R. F. Region 3. Diffice of Director 8X19 033 82/11/16 FOBIER, J. E. Office of Investigation 125pp 24524 010 24X Fiche 50-329,84/07/18,8408010061
- --8408170268 Discusses 830722 off-the-record meeting w/Bechtel employee re allegations concerning inadequacy of plant fire detection sys Concerns raised re copyright laws concerning App R to 100fR30
  BURGESS, B L Region 3, Office of Director BX19 034 B3/09/26 R0Y, 0 W Region 3, Office of Director 39pp 26534 246 24X Fichs 50-329,84/07/18.8408010061
- --B408170271 Requests Ofc of Investigations provide investigator to assist Ofc of Special Cases in closeout of unresolved item in Insp. Rept 329/82-22-27 re use of unofficial documents for recording nonconformances & deficiencies WARNICK.R F NRC No Detailed Affiliation Oiven BX19 035 83/01/27 PAMILIK.E T Repion 3. Defice of Director 1p 24534 293 24X Fiche 50-329,84/07/18,8408010061
- --B408170274 Discusses B31021 interview w/A Gautam & unnamed individual re allegations concerning Comstock, Bechtel & Zack const activities at plant Details of issues referred to Ofc of Investigation & Ofc of Inspector & Auditor HANKINS.F C Region 3. Office of Director BX19 036 B3/10/26 Region 3. Office of Director BX19 036 B3/10/26 Fiche 50-329,84/07/18,8408010061
- --B408170276 Forwards util repts to auxiliary bldg seismic analysis & cracks in borated water storage tank foundation.per util BI0121-22 notifications Const deficiency info may aid in resolution of matter NGRELIUS.C E Division of Engineering BX19 O36AD 81/11/24 EIBENHUT.D O Division of Licensing 1p 26535 165 24X Fiche 50-329,84/07/18,8408010061
- --8408170279 "Btructural Stresses Induced by Differential Settlement of Diesel Generator Bidg " \* Consumers Power Co | BX19 037 | 84/07/18 | 51pp | 26535 | 255 24X Fiche | 50-329, 84/07/16, 8408010061
- --840B1702B4 Summary of 810502-04 meeting w/util & Bechtel in Bethesda,MD re remedial actions & update of soils deficiencies & to review Amend 85 to application LANDSMAN.R B Region 3, Office of Director BX19 039 B1/05/12 WILLIAMS.C C Region 3, Office of Director 65pp 26536 043 24X Fiche 50-329,84/07/18,840B010061
- --8408170292 Transcript of B Stamiris 840425 statement re soil settlement problems at plant STAMIRIS.O G Stamiris. B 8X19 041 84/04/25 3pp 24536 134 24X Fiche 50-329,84/07/18,8408010061

- --8408170297 Transcript of M Sinclair 840425 statement re problems w/util announced Dec 1986 const completion date Documentation entl SINCLAIR.M 8inclair, M 8x19 042 84/04/25 10pp 26536 137 24X Fiche 50-929,84/07/18,8408010061
- ~-B408170304 Transcript of T Hearron 840425 statement opposing completion, licensing & operation of plant HEARRON T Lone Tree Council BX19 043 B4/04/25 App 26536 147 24X Fiths 50-329.84/07/18.8408010061
- --8408170312 Transcript of BP Garde 840425 statement re Govt
  Accountability Project 840210 supplemental 10CFR2 206
  petition.mgt breakdown.NRC action problems & adequate
  Commission review of complex project
  OARDE.B P Government Accountability Project BX19 044
  84/04/25 19pp 24536 151 24X Fiche 50-329.84/07/18.8408010061
- --8408170320 Summary of 840202-05 meeting w/util, Bechtel & consultants in Ann Arbor, MI re discussion & audit of preparations for underpinning southern part of auxiliary bldg Viewgraphs entl HOOD, D. Licensing Branch 4 BX19 045 84/02/22 Licensing Branch 4 81pp 24534 189 24X Fiche 50-329, 84/07/18, 8408010061
- --8408170358 S&W 840209 public meeting re cracking criteria & cracking mapping program \* Consumers Power Co BX19 046 84/02/09 Consumers Power Co 2pp 26536 349 24% Fiche 50-329,84/07/18,8408010061
- --8408170360 Submits list of documents supplied or withheld by JJ Harrison & RB Landsnan.in response to FOIA Request 84-24 MARNICK:R F Region 3. Office of Director BX19 047 84/01/18 SMITH.P T Region 3. Office of Director 2pp 26536 351 24X Fiche 50-329,84/07/18,8408010061
- ~-B40B170365 Handwritten summary of 840104 public meeting w/util, S&W Bechtel re monthly activities, crack rept, crack mapping & open items Supporting documentation & attendance list encl \* Consumers Power Co BX19 048 B4701/13 Consumers Power Co 74pp 26536 396 24X Fiche 50-329, 84/07/18, 840B010061
- --8408170367 Crack mapping monitoring status rept for 831031-1130, including handuritten status rept of 831208 85W meeting & info re grillage acceptance criteria \* Consumers Rower Co BX19 049 84/08/01 10pp 26537 107 24X Fiche 50-329,84/07/18,8408010061
- ---B40B170372 Handwritten summary of B31110 public meeting Re tracking open items of new crack monitoring procedures B31009-1105

  \* Consumers Power Co BX19 050 B3/11/10 Consumers Power Co 3pp 26537 127 244 Fiche 50-329, B4/07/18, B40B010061
- --8408170374 Rev 44 & 47 to FSAR Response to Audit Point 1 & handwritten swmmaries of S&W 831013 public meeting encl \* Consumers Power Co 8X19 051 84/08/01 34pp 26537 170 24X Fiche 50-329, 84/07/18, 8408010061
- --8408170377 Handuritten notes re auxiliary bldg & underpinning design including settlement stress, results of areas of max stress & rigid body rotation # Consumers Power Co BX19 053 84/08/01 76pp 26537 253 24X Fiche 50-329,84/07/18,8408010061
- --8408210367 Agenda for 780502 site visit w/util Bechtel & NUB Agenda for 781204 meeting u/util & Bechtel on site encl # NRC No Detailed Affiliation Given BX18 001 78/05/02 NRC No Detailed Affiliation Given App 26521 047 24X Fiche 50-329,84/07/18,8408010061
- --8408210377 Notification of 780907 meeting w/Midland Technical Reviewers in Washington, DC to discuss project status of facility safety review Reviewers will be asked to summarize review status on problem areas affecting review schedule HODO, D Light Water Reactors Branch 4 BX18 003 78/09/06 NRC No Detailed Affiliation Given 7pp 26521 091 24X Fiche 50-329,84/07/16,8408010061
- ---8408210379 Provides into in response to B Garde FOIAs 83-451,-452,-454 ½ -449 HODD, D Licensing Branch 4 BX18 029 B3/08/19 WILSON,V NRC - No Detailed Affiliation Given 2pp 26324 336 24X Fiche 50-329,84/07/18,8408010061
- --8408210384 Notification of rescheduled 790718 meeting w/util & Bachtel in Bathesda, MO to discuss abnormal settlement of fill & structures at site Agenda & attendance list encl HOOD, D Light Water Reactors Branch 4 BX18 004 79/06/13 VARGA: S A Light Water Reactors Branch 4 7pp 26521 100 24X Fiche 50-329,84/07/16,8408010061

- --8408210386 Forwards B Garde FOIA request for documents re meetings between NRC.TERA & util on 830518.0608 & 23 concerning independent design verification W/draft ltr to util re implementation of Ford Amenó WIL50N.V H Hanagement Analysis Branch 8X18 024 83/08/09 Hanagement Analysis Branch 2pp 26524 338 24X Fiche 50-329.84/07/18.8408010061
- --840B21039; Notice of W Ferris,S Afifi & J Wanzeck B0102B-29 deposition in Ann Arbor,MI re 791206 order modifying const permits Related info encl PATON,W D Office of the General Counsel BX18 005 DM B0/10/06 68pp 26521 126 24X Fiche 50-329,84/07/18,840B010061
- --8408210392 Forwards B Garde FDIA 63-452 request for documents re 830615 Commission briefing WILSON.V H Management Analysts Branch BX18 025 83/08/09 Management Analysis Branch 2pp 26524 354 24X Fiche 50-329,84/07/18,8408010061
- --8408210397 Forwards B Garde FDIA 83-454 request for documents re re-review of structural adequacy of diesel generator bldg WILBON V H Hanagement Analysis Branch BX18 026 83/08/10 LEAR O Hydrologic & Octochnical Engineering Branch BOSNAK, F Mechanical Engineering Branch 2pp 26524 358 24X Fiche 50-329,84/07/18,8408010061
- ---B408210398 Notice of B Dahr B01217 deposition in Ann Arbor, MI re issues set forth in Licensing Board 791206 order modifying const permits & contentions of intervenors Stamiris & Warren.

  Resume of IR Thiruvengadam encl + Atomic Safety and Licensing Board Panel BXIB 006 DM 80/12/11 Spp 26521 199 24X Fichs 50-329:84/07/18,8408010061
- --8408210401 Forwards B Garde FOIA Request 83-449 for documents submitted by util re consideration of candidate companies or methodologies to perform const implementation overview of const completion plan WILBON.V H Management Analysis Branch BX18 027 84/08/09 Management Analysis Branch 2pp 26525 001 24X Fiche 50-329,84/07/18,6408010061
- --8408210404 Determines that info transmitted by 830721 memo should be issued as Board Notification 83-106 EISFNHUT.D 0 Division of Licensing DX18 028 84/07/18 NUVAK.T Assistant Director for Licensing ip 26325 152 24X Fiche 50-329,84/07/18.8408010061
- --8408210410 Board Notification 83-016 forwards notice of violation & proposed imposition of civil penalties, based on util failure to implement adequate QA program for installation of electrical.mechanical & civil components
  NOVAK, T M Division of Licensing BX18 027 OM 84/02/15
  Atomic Safety and Licensing Board Panel 1p 26325 160 24X
  Fiche 50-329,84/07/18.8408010061
- --8408210411 Handwritten questions for RB Peck re consultant responsibilities & settlement monitoring Handwritten deposition of RB Beck encl \* NRC - No Detailed Affiliation Given BX18 008 81/01/31 NRC - No Detailed Affiliation Given 36pp 26521 228 24X Fiche 50-329,84/07/18,8408010061
- --8408210414 Forwards Board Notification 83-14 which supersedes 830215 notification NDVAK, T M MRC No Detailed Affiliation Given 8X18 030 84/02/18 Atomic Safety and Licensing Board Panel 1p 24525 184 24X Fiche 30-329,84/07/18,8408010061
- --8408210418 Bubmits package received from 8 Junes from H Singh, consisting of questions of Dr Pack by H Singh, J Dunnicliff 800208 Itr to S Afifi & summary of J Kane deposition SINGH, H NRC No Detailed Affiliation Given BXIB 009 84/07/18 JUNES, B NRC No Detailed Affiliation Given JApp 26521 269 24X Fiche 50-329,84/07/18,8408010061
- --8408210421 "Questions for Davisson 810114-15 Deposition " Questions of Dr Pack on testimony, dtd 810725 ent1 \* NRC No Detailed Affiliation Olyan BX18 010 81/01/11 34pp 26521 305 24X Fiche 50-327,84/07/18,8408010061
- --8408210425 "Guestions for Davisson 810114-15 Deposition "

  \* NRC No Datailed Affiliation Given BXIB 011 81/01/11 43pp 26522 070 24X Fiche 50-329,84/07/18,8408010061.
- --8408210430 Draft memo informing of status of NRC-03-79-16T.Task 1.

  8u8task 3 Index of Davisson deposition encl.

  SINGH: H NRC No Detailed Affiliation Given BXIS 012

  80/10/16 LEAR: O Hydrologic & Geotechnical Engineering Branch
  17pp 26522 116 24X Fiche 50-329.84/07/16.8408010061

- --B408210433 Recommends issuance of encl matl as Board Notification 84-083 re update on stop work status & NRC staffing changes Related info encl EISENHUT.D O Division of Licensing BX18-016 84/04/18 NOVAK.T Division of Licensing 2pp 26522-350 24X Fiche 50-329, 84/07/18.8408010061
- --B408210446 Summary of 820202-05 meeting w/util & Bechtel in Ann Arbor, MI re audit preparations for underpinning southern portion of auxiliary bldg Bechtel meeting notes & viewgraphs encl HUDO.D Licensing Branch 4 8818 019 B4/02/22 Licensing Branch 4 79pp 26523 232 24X Fiche 50-329,84/07/18,8408010061
- --8408210450 Determines that encl rept on review of diesel generator bldg should be issued as Board Notification 83-165 EIBENHUT.D O Division of Licensing 8X18 020 B3/10/28 NDVAK.T Assistant Director for Licensing 4pp 26524 302 24X Fiche 50-329,84/07/18,8408010061
- ---8408210453 "Observed Sattlements (Inches) of Structures, 790930 to Present "Summary of soil properties & summary of soils info encl WANZEC.T NRC - No Detailed Affiliation Given BX18 037 80/08/27 10pp 26527 199 24X Fiche 50-329, 84/07/18, 8408010061
- --8408210454 Submits marked-up ltr re program for plant soils remedial uark, in response to draft SER open items
  COOK, J W Consumers Power Co BXIB 047 82/09/07 DENTON, H R
  Office of Nuclear Reactor Regulation, Director 47pp 26528 039
  24X Fiche 50-329, 84/07/18, 8408010061
- --8408210455 Agends for 800930 meeting w/util on site for appeal of NRC position 4 NRC No Detailed Affiliation Given BX18 03B 84/07/18 NRC No Detailed Affiliation Given ip 26527 209 24X Fiche 50-329,84/07/18,8408010061
- --B408210461 Trip rept of 831005-07 site visit re design review & audit of HVAC sys TERAO. D Mechanical Engineering Branch BX18 052 83/10/28 BDSNAK.R J Mechanical Engineering Branch 17pp 26528 234 24X Fiche 50-329,84/07/18.8408010061
- --B408210463 Draft notes recommending that listed actions be considered by Region III in effort to improve licensee regulatory attitude & performance & increase assurance that completed & ongoing const work acceptable \* NRC - No Detailed Affiliation Given BXIS 046 BR/08/06 4pp 2652B 034 24X Fiche 50-329,04/07/18.0408010061.
- --8408210464 Notifies of 830708 meeting to discuss NRR SALP III assessment based on recent hearing testimony by Region III & several third-party reviewers NOVAK, I M. Assistant Director for Licensing BXIR 055 B3/07/07 JOHNSTON, W. KNIGHT, J.P., RUBENSTEIN, L. NRC No Detailed Affiliation Given 11pp 26528 262 24X Fiche 50-329,84/07/18,84080 10061
- --8408220059 Responds to 830829 ltr re imposition of civil penalty for violations noted during Insp 83-23 Penalty reduced because of prompt corrective actions Check encl COCK. J H Consumers Power Co. 8X19 052 25914 83/09/26 DEYDUNG.R C Director's Office Office of Inspection and Enforcement 2pp 26537 208 24X Fiche 50-329,84/07/18,8408910061
- --8408220064 Testimony of RN Gardner re qualification of Bechtel GC personnel Certificate of Svc & related info encl GARDNER:R N Region 3, Office of Director BN19 023. OL 82/01/22 120pp 26532 292 24X Fiche 50-329,84/07/18, 8408010061
- --B408220070 Delineates Control Sys Branch position on identification of protection sys instrument sensing lines & requests position be transmitted to near-term OL applicants EPEIS.TP Assistant Director for Reactor Safety BX19 025 84/07/18 TEDESCO.R L Assistant Director for Licensing. Spp 26533 051 24X Fiche 50-329.84/07/18.8408010061
- --8408220078 SALP Repts 50-329/82-14 & 50-330/82-14 for Jul 1980 June 1981. # Region 3, Office of Director BX19 027. 50-330/82-14 82/03/31 28pp 26533 160 24X Fiche 50-329.84/07/18.8408010061
- --8408220085 Attandance list of 820223 meeting w/util, chronological list events before & after issuance of NRC order modifying CPs, plant underpinning questions re svc water pump structure & review of 1981 technical rept on underpinning \*\* NRC No Detailed Affillation Given BX19 036A 82/02/23. 38pp 26534 327 24% Fiche 50-329,84/07/18,8408010061.

- --8408220090 "Observed Cracks in Walls of Midland Plant Structures"
  CORLEY, W G , FIORATO, A E Portland Coment Association BX19 031A
  82/06/14 32pp 26533 327 24X Fiche 50-329,84/07/18,
  8408010061
- --8408270315 Draft itr informing of decision re addl sail borings & testing NRC request for sampling & testing coaling pand enhankments reconsidered & relocation of certain borings determined VOLLMER,R H Division of Engineering BXIB 010A B0/11/03 CODX.J W Consumers Pawer Co ip 26522 022 24X Fiche 50-329,84/07/18,8408010061
- --8408270323 Submits listed items that inspectors consider to be indicative of questionable licensee performance CODM.R J Region 3. Orfice of Director BX19 019 82/07/23 WARNICM.R F Region 3. Office of Director 11pp 26331 271 24: Fiche 50-329,84/07/18.8408010061
- --8408270330 Forwards surmary of 840229 meeting w/Region III & util in Region III Te results of inaps & investigation into allegations re HVAC work WELLS,R A Consumers Power Co BX19 020 28921 84/03/24 HARRISON, J Region 3, Office of Director 17pp 26532 023 24X Fiche 50-329,84/07/18,8408010061
- --8408270336 Testimony of 8P Garde re Midland Nuclear Power Plant GARDE, B P Government Accountability Project BX19 021 84/02/13 22pp 26532 040 24X Fiche 50-329,84/07/18,8408010061
- --8309270518 Forwards comments on util proposed findings of fact & conclusions of law on remedial soils issues
  JACKSON.R E Geosciences Branch BX17 038 B3/09/21 PATON.W D
  Hearing Branch 2 5pp 26520 064 24X Fiche 50-329.84/07/18.
  B408010061
- 8408140311 Summary of 810717 meeting w/CPC re preliminary design of mods to svc water pump structure to resolve concerns resulting from inadequate compaction of site fill KANE.J NRC No Detailed Affiliation Given BX16 043 81/10/30 NRC No Detailed Affiliation Given BP 26511 339 24X Fiche 50-329,84/07/18.84080a0061
- 8408310135 Responds to FOIA request for all documents made publicly available per R Belair FOIA Request 84-250 Documents available in PDR FELTON, JM DIVision of Rules and Records 84/05/30 SAYLOR, N 8 Hunton & Williams Ip 26352 016
- B40B3i0i37 FOIA request for ail documents made publicly available per R Belair FOIA Request 84-250 BAYLOR,N S Hunton & Williams B4/05/15 FELTON,J M Division of Rules and Records 2pp 26352 017
- B40B31013B F01A request for positive identification of Mothers for Peace of San Luís Obispo & calculations performed by P0&E re earthquake on Nacimiento fault & one equal to 1906 San Francisco earthquake CALBOYAS,C D Affiliation Not Assigned 84/04/07 NRC No Detailed Affiliation Givan 4pp 26352 011 24X Fiche 50-275.84/04/07.840831013B
- 8408310142 Responds to FOIA request for positive identification of Mothers for Peace of San Luis Obispo & calculations performed by POSE re earthquake Forwards printout of documents re Mothers for Peace Other documents in PDR FELTON. J M Division of Rules and Records 84/06/01 CALSOYAB. C D Affiliation Not Assigned 1p 26352 015 24% Fiche 50-275.84/06/01.8408310142
- 3408310147 Partial response to FOLA request for detailed instruction reuse of risk assessment techniques & analysis & calculations on which ground accelerations for design & max hypothetical earthquake based Documents available in PDR FELTON, J. M Division of Rules and Records 84/06/01 CALSOYAS, L D Affiliation Not Assigned 1p 26331 338 24X Fiche 50-344, 84/06/01, 8408310147
- MOB310149 FOIA request for datailed instructions re use of risk assessment techniques & analysis & calculations on which ground accelerations for design & max hypothetical earthquake based CALSOYAS, C D Affiliation Not Assigned 84/05/12 NRC No Detailed Affiliation Given 4pp 26351 359 24X Fiche 50-344, 04/05/12, 04008310149
- 408310151 Responds to FOIA request for documents between UCLA & NRC recurrent reactor shutdown & records repropased work to be performed during shutdown Forwards HF Wegst 840213 ltr to NRC RELTON, J M Division of Rules and Records 84/06/04 HIRSCH, D Committee to Bridge the Cap ip 26351 355 24X Fichs 50-142.84/06/04.8408310151

- #108310152 FOIA request for all correspondence of other documents between UCLA & NRC re incident occurring in early Feb 1984, which led to current shutdown of UCLA research reactor HIRSCH, D. Committee to Bridge the Gap 84/04/24 Office of Administration ip 26351 355 24X Fiche 50-142.84/04/24, 840830152
- 8408310155 Final response to FDIA request for documents re suppression pool scrubbing experiments conducted by GE ½ Battelle No further documents located subj to request FELTON.J M Division of Rules and Records 84/05/30 BHOLLY.S Union of Concerned Scientists 1p 26351 353
- 8408310196 FOIA request that SECY-84-29 % encl of PL William 840303 ltr re functional description of safety parameter display sys be placed in PDR DDVE.K Affiliation Not Assigned 84/04/12 FELTON.J M Division of Rules and Records ip 26352 001 24% Fiche 50-461.84/04/12.8408310156

#### GEN TEC IS GENERIC TECHNICAL ISSUES

- 8404230301 NUREO/CR-3704
  THREE-DIMENSIONAL CALCULATIONS OF TRANSIENT FLUID-THERMAL
  MIXING IN THE DOWNCOMER OF THE CLAVERT CLIFFS-1 PLANT USING
  SOLA-P1S
  DALY, B J Los Alanos Scientific Laboratory FIN A-7306
  LA-10039-MS 84/04/30 Division of Accident Evaluation 86
  25131 319 24X Fiche 50-317,84/04/30,8406230301
- B407170313 Requests review of draft NUREO-1032. App A re loss of offsite power frequency & duration relationship & of ORNL draft rept on loss of offsite power operating experience Comments requested by 840801 W/o encl
  DARANGUSAY, F W Reactor Risk Branch 84/07/11 KNIEL, K Generic (saues Branch 2pp 26068 061
- --8407170316 Forwards draft loss of offsite power frequency & duration analyses Results indicate significant reduction in estimated frequency & duration of loss of power transient & contradict previous EPRI findings Review requested for 840731 meeting BARANOWSKY, P. W. Reactor Risk Branch 84/07/11 BERGER, W. E. Sargent & Lundy, Inc. 96pp 26068 063
- B40B010042 Summary of CROR Meeting 66 on 840711 re status of long-range plans to address BNR pipe cracking due to IGSCC & review of proposed resolution of Unresolved Safety Issue A-43 re containment emergency sump STELLO, V Committee to Review Generic Requirements B4/07/24 DIRCKS, W J Office of the Executive Director for Operations 2pp 25884 038
- 8408010199 Forwards summary of CROR activities for Jul 1984 Summary will be included in END weekly rept to Commission for wk ending 840803 SNIEZEK. J. Regional Operations & Generic Requirements 84/07/30 Committee to Review Operic Requirements 4pp 25854 040
- 8408010161 Notification of 840727 meeting w/util at site to discuss questions re control of heavy loads (Multi-Plant Action C-15)
  NETOHBORG D Operating Reactors Branch 1 84/07/20 VARQA, 8 A Operating Reactors Branch 1 2pp 25873 304 24X
  Fiche 50-280,84/07/20,8408010161
- B40B020213 Comments on Metal Components Subcommittee B40517 & 18 meetings re-pressurized thermal shock BENDER, M Affiliation Not Assigned BENDER, M ACR8 - Advisory Committee on Reactor Bafeguards 84/06/13 AXTMANN,R ACR8 -Advisory Committee on Reactor Safeguards 4pp 25898 164
- 8408020248 Summarizes DHR Subcommittee 840603 meeting re Unresolved Safety Issue A-45. "Shutdown DHR Requirement "Various studies do not contain all elements along heat flow path from heat source to heat sink CATTON, I ACRS Advisory Committee on Reactor Safeguards 84/06/11 BUEHNERT, P ACRS Advisory Committee on Reactor Safeguards 2pp 23898 145
- 8408030019 Forwards responses to J Singh 840522 verbal questions re control of heavy loads MILLG.L M Tennessee Valley Authority 84/07/27 ADENSAM.E Licensing Branch 4 2pp 25907 092 24X Fiche 50-327.84/07/27, 8408030019
- --8408030025 Rev 3 to Procedure MI-6 22, "Control of Heavy Loads in Critical Lifting Zones - NUREC-0612" DOTY,J W Tennesses Valley Authority 84/05/21 23pp 25907 044 24X Fiche 50-327,84/07/27,8408030019

- 8408070075 Forwards request for addl info re pressurized thermal shock flux reduction program Response requested within 3 wks of its receipt W/o encl VARGA.8 A Operating Reactors Branch 1 84/07/26 WILLIAMS.J W Florida Power & Light Co 2pp 25955 317 24X Fiche 50-250.84/07/26.8408070075
- 8408370076 Advises of completion of review of AEOD/C403, "Case Study Rept for EI Hatch.Unit 2 Plant Sys Interaction Event on 820825" Case study recommends event be considered in developing final positions relative to NUREG-0803
  DENTON.H R Office of Nuclear Reactor Regulation, Director 84/07/30 HELTEMES.C J Director's Office 2pp 25955 272 24X Fiche 50-366.84/07/30.8408070076
- 8408070446 Requests exemption from 10CFR50. App A.GDC 4 re elimination of postulated circumferential & longitudinal breaks in RC5 main loop piping & NCAP-10559 & NCAP-10560 Repts withheld (ref 10CFR2 790)
  - OCLDBERG, J H Houston Lighting & Power Co GL-84-04 84/07/17 DENTON, H R Office of Nuclear Reactor Regulation, Director App 25940 349 24X Fiche 50-498,84/07/17,8408070446
- 8408070515 Forwards "NUREC-0612, Control of Heavy Loads," final rept Subnittal contains evaluation results & resolutions of open items since 840326 submittal KDBER,R W Rochester Oas & Electric Corp 84/07/31 PAULSON, W A Deprating Reactors Branch 5 ip 25941 172 24X Fiche 50-244.84/07/31,8408070315
- --B408070516 "NUREG-0612.Control of Heavy Loads," final rept 4 Rochester Cas & Electric Corp 84/08/31 12pp 25941 173 24X Fiche 50-244.84/07/31.8408070515
- 8408080472 NUREG/CR-3840
  COBT ANALYSIS FOR POTENTIAL MODIFICATIONS TO ENHANCE THE
  ADILITY OF A NUCLEAR PLANT TO ENDURE STATION BLACKOUT
  CLARK, R A, THOMAS, W R Science & Engineering Associates, Inc
  RIGRODN, B J MATHTECH, Inc FIN B-8838 84/07/31 Division of
  Budget & Analysis 167pp Available at NRC \$5 50 25980 160
- 8408090530 Forwards request for additinfo for review of 840214 submittal recontrol of heavy loads Tech Spec change Response requested within 45 days of itr receipt VARGA, 8 A Operating Reactors Branch 1 84/08/01 0'TOOLE, J Consolidated Edison Co of New York, Inc. 4pp 25783 332 24; Fiche 50-247,04/08/01,8408090530
- 8408130233 Forwards safety evaluation & technical evaluation rept re control of heavy loads. Phase 1 VARGA. S. A. Operating Reactors Branch 1 84/07/25 MCDONALD, R. P. Alabama Power Co. 2pp. 26060-027 24X Fiche 50-348, 84/07/25, 8408130233
- --8403130258 SER re control of heavy loads.Phase 1 Phase 1 acceptable \* NRC - No Detailed Affiliation Given 84/07/25 2pp 26060 029 24X Fiche 50-348,84/07/25,8408130233
- 840Bi30447 Forwards "Control of Heavy Loads (Phase II-NUREG-0612) for Commanche Peak, Units i & 2," draft technical evaluation rept YOUNGBLOOD, B. J. Licensing Branch 1 84/07/26 SPENCE, M. D. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.) 3pp 26059 271 24X Fiche 50-445, 84/07/26, 840Bi30449
- --8408130495 "Control of Heavy Loads (Phase II-NUREG-0612), Commanche Peak, Units 1 & 2," draft technical evaluation rept YEN, T C EG&G, Inc FIN A-6457 84/04/30 NHC No Detailed Affiliation Civen 40pp 26059 274 24X Fiche 50-445, 84/07/26, 8408130449
- 8408160035 Informs that util plans to prepare general safety evaluation to expand safe load path boundaries in reactor bldg Evaluation will be submitted for review by 841101 KANGA.B K General Public Utilities GPU Service Corp 4410-84-L-0131 84/08/10 SNYDER.B J TMI Program Office 2pp 26092 050 24X Fiche 30-320,84/08/10,8408160035
- 8408160248 NUREQ/CR-3761
  RELAPS THERMAL-HYDRAULIC ANALYSES OF PRESSURIZED THERMAL
  SHOCK SEQUENCES FOR THE OCONEE-1 PRESSURIZED WATER REACTOR
  FLETCHER, C D , BOLANDER, M A , BTITT, B D EG&G, Inc FIN A-6047
  EGG-2310 84/07/31 Division of Accident Evaluation 165pp.
  26125 001 24X Fiche 50-269,84/07/31,8408160248
- 8408170316 Summarizes ACRS 292nd meeting on 840809-11 re Tesk Action Plan A-45, "Shutdown DMR Requirements " Effort to apportion quantitative reliability goals among plant subsys endorsed EDERSOLE, J C ACRS Advisory Committee on Reactor Safeguards 84/08/14 DIRCKS, W J Office of the Executive Director for Operations 2pp 26114 280

- 8408210376 Forwards info documenting results of review & implementation of required changes & mods.per Generic Ltr 81-07. "Control of Heavy Loads" & NUREC-0612 Minor error noted in 801222 ltr corrected TUCKER.H B Duke Power Co QL-81-07 84/08/17 DENTON,H R Defice of Nuclear Reactor Regulation, Director 36pp 26180 271 24X Fiche 50-369, 84/08/17.8408210376
- 8408220326 Forwards safety evaluation & technical evaluation rept re NUREO-0612, "Control of Heavy Loads at Nuclear Power Plants Phase I "Ections 5 1 1 & 5 3 satisfied Phase I acceptable PAULSON.N A Operating Reactors Branch 5 LEOS-84-08-026 B4/08/20 COUNSIL, W G Connecticut Yankee Atomic Power Co 2pp. 26193 111 24% Fische 50-213,84/08/20,8408220326
- --8408220330 Safety evaluation re NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants - Phase I " \* Operating Reactors Branch 5 84/08/20 2pp 26193 113 24X Fiche 50-213,84/08/20,8408220326
- --8407300136 TER-C5506-358

  "Control of Heavy Loads.Connecticut Yankee Atomic Power Co.
  Haddam Neck Plant," technical evaluation rept
  BDMBERGER.C Franklin Institute/Franklin Research Center
  NRC-03-61-130 TAC 07993 84/07/25 91NOH.A NRC No Detailed
  Affiliation Given 24pp 26193 115 24X Fiche 50-213.84/08/20,
- B40B220363 Forwards response to request for addl info re control of heavy loads mods, per NUREO-0612, resulting from discussions w/Franklin Research Ctr & Rev O to Procedure 140B-6, "Procedure for Insp of Wire Rope or Synthetic Blings "HUKILL, H D Oeneral Public Utilities GPU Service Corp 5211-84-2200 B4/0B/16 EIESHMUT.D G Division of Licensing 6pg 26189 324 24x Fiche 50-289,84/08/16,840B220363
- 8408230172 Forwards GRNL draft "Chapter 5 Probabilistic Fracture-Mechanics Analysis of Calvert Cliffs Unit 1 Bequences." of pressurized thermal shock rept Comments requested by 840822 JUHNSON.C NRC No Detailed Affiliation Given 84/07/30 WOODS, R NRC No Detailed Affiliation Given 26230 028 24X Fiche 50-317.84/07/30.8408230172
- --B40B230184 Forwards ORNL draft "Chapter 5 Probabilistic Fracture-Mechanics Analysis of Calvert Cliffs Unit 1 Sequences," of pressurized thermal shock rept Comments requested by 840B22 SELBY.D L Dak Ridge National Laboratory 84/07/30 JGHNBON,C E NRC No Detailed Affiliation Given KGENIG.J E Los Alamos Scientific Laboratory MIRSKY.5 M Baltimore Gas & Electric Co 1p 26230 029 24% Fiche 50-317.84/07/30.8408230172
- 8408230272 Forwards Rev 3 to "Overhead Handling Sys Review " Rept revised, per NURES-0612, to address concerns identified in draft technical evaluation rept on control of heavy loads & support resolution of SER License Condition 7 KEMPER, J S Philadelphia Electric Co 84/09/13 SCHWENCER, A Licensing Branch 2 3pp 26207 001 24X Fiche 50-352, 84/09/13, 8408230292
- --8408230297 Rev 3 to final rept "Overhead Handling Sys Review "

  + Philadelphia Electric to 84/06/30 173pp 26207.004 24X
  Fiche 50-352, 84/08/13,8408230272
- 8408280199 Documents closeout of several issues raised by NRC during review of responses to requirements of Generic Ltr 81-14, "Seismic Qualification of Auxiliary Feedwater Bys " Any mods will be made per Osneric Issue A-46
  ZIMMERMAN.S R Carolina Power & Light Co NLS-84-258 84/08/23.
  VARQA.B A Operating Reactors Granch 1 ip 26275 362 24X
  Fiche.50-261,84/08/23,8408280199
- 8408280238 Forwards add1 neutron source data for NRC review of pressurized thermal shock flux reduction program,per 840726 request HILLIAMS.J N Florida Power & Light Co L-84-216 84/08/22 VAROA.S A Operating Reactors Branch 1 36pp 26262 243. 24X Fiche 50-250,84/08/22.8408280238
- 8408280270 Forwards draft technical evaluation rept re control of heavy loads, for review & comment Project manager should be contacted within 3D days to discuss outstanding items W/o encl VARQA.5 A Operating Reactors Branch 1 84/08/20 0'TQQLE,J D Consolidated Edison Co. of New York, Inc. 1p 26274 086 24X Fiche: 50-247, 84/08/20, 8408280270
- 8408280319 Forwards draft technical evaluation rept. "Control of Heavy Loads - Phase II.Davis-Besse Nuclear Power Station Unit 1." for review STOLZ.JF Operating Reactors Branch 4 TAC 32271 84/08/17 CROUSE.R P Toledo Edison Co 2pp 26294 053 24X Fiche 50-344.84/08/17.8408280319

- --B40B2B0321 TER-C5506-489 DRFT

  Draft "Control of Heavy Loads Phase II. Davis-Besse Nuclear
  Power Station Unit 1.' technical evaluation rept

  BUMBERGER.C R , WALTER.R J , SARGENT, I H Franklin
  Institute/Franklin Research Center NRC-03B1-130 TAC 52271

  B4/07/10 SINGN.A NRC ND Detailed Affiliation Given 26pt
  26294 055 24X Fiche 50-346.84/08/17.84082B0319
- 8408290562 Summary of ACRB Subcommittee on DHR Sys 840605 meeting in Mashington, DC re resolution effort for Unresolved Safety Issue A-45, "Shutdown DHR Sys" \* ACRB - Advisory Committee on Reactor Safeguards 84/06/21 ACRB - Advisory Committee on Reactor Safeguards 27pp 26310 232
- 8408310007 Responds to 840206 itr on SER License Condition 7 recompliance w/NUREG-0612.control of heavy loads.Phase II
  "Limerick Overhead Handling Bys Final Rept (Rev 3)" revised per 840206 request Related correspondence KEMPER, J 8 Philadelphia Electric Co DSB 293 QL 84/08/18 SCHWENCER, A Licensing Branch 2 3pp 26350 197 24X Fiche 50-352.84/08/18,8408310007
- B408230191 Draft "Pressurized Thermal Shock Evaluation of Calvert Cliffs Unit 1 Nuclear Power Plant.Chapter 3 Probabilistic Fracture-Mechanics Analysis of Calvert Cliffs Unit 1 Bequences "

  \* Oak Ridge National Laboratory B4/07/27 NRC ~ No Detailed Affiliation Given 169pp 26230 030 24X Fiche 50-317.B4/07/30.7408230172

## INSPECTION AND ENFORCEMENT

- 840710250 EN-84-039 on 840710, notice of violation & proposed imposition of civil penalties in amount of \$500 will be issued to licensee Action based on failure to comply w/ requirements re mpt oversight & control of radiation safety FLACK.E. AXELRAD.J Director's Office of Finspection and Enforcement 84/07/03 ip 25524 310
- 8407250229 IE Info Notice 84-57. "Operating Experience to Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants" Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc. 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229
- 8408010061 Further response to FOIA request for 16 categories of records refacility Documents identified by J Goold & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing FELTON.JM Division of Rules and Records BX14 000 84/07/18 RICE.C M Kirkland & Ellis 2pp 26500 001
- --8408150694 PNO-77-035 on 770226, bulge discovered in containment liner plate Caused by water coming through toars in liner plate Add holes cut in plate to facilitate draining Related info encl WARNICK, R Office of Inspection & Enforcement, Office of the Director 8221 030 77/03/01 7pp 26555 154
- 8408010162 EN-84-050 on 840727; confirmatory order issued to util confirming commitment for immediate cold that down Action taken because of loss of ac power due to diesel generators not recisiving start signal FARRON, P. AXELRAD, J. Director's Office, Office of Inspection and Enforcement 84/07/30 sp. 25855.304, 24X Fiche 50-388,84/07/30,8408010162
- 8408010164 EN-84-049; on 840730; notice of violation & proposed imposition of civil penalties in amount of \$40,000 will be issued to licenses Action involves failure to adequately implement svc life monitoring program for snubbers KLINGLER. 9. AXELRAD, J Director's Office, Office of Inspection and Enforcement 84/07/25 ip 25855 305 24X Fiche 50-280,84/07/25,8408010164
- B408D10170 PNO-TMI-B4-008B on B40724: reactor vessel closure head set down on storage stand Placement accomplished by use of pry har & winch attached to containment wall NRC will be supplied w/24 h/day coverage until fixture in place FABANO.A ORANT.P. TMI Program Office B4/07/25 Ip 25855 320 24X Fiche 50-320,84/07/25,8408010170
- B40B010174 PNO-TMI-84-008A on 840724. reactor vessel closure head lifted clear of reactor vessel flange Licenses devising means of aligning vessel head w/storage stand guide pins in preparation for lowering head to stand COOK.R., FASANO.A., GRANT, P. TMI Program Office 84/07/25 1p 25855 321 24X Fiche 50-320.84/07/25.8408010174

- B4080;0220 PND-TMI-B4-00BD on B40726, lead shield platform put in place over top of internals indexing fixture While lowering shielding, crame failed Licensee manually unscrewed lifting turnbuckles until platform made contact CODK, R. FABAND, A. GRANT, P. TMI Program Office 84/07/26 ip 25956 026 24% Fiche 30-320,84/07/26,8408010220
- B40BD10230 PND-TMI-84-COBC on 840726, licensee lifted internals indexing fixture w/poiar crame & lowered fixture into place on reactor vessel flange Containment purging initiated CODK, R. FASAND. A. GRANT.P. TMI Program Office B4/07/26 ip 25856 018 24% Fiche 50-320, B4/07/26, B408010230
- B408010251 EN-84-048 on 840730 notice of violation & proposed imposition of civil benalty issued in amount of \$4,000. based on licensee failure to implement effective mgt control over radiation safety program & falsification of records FLACK.E. AXELRAD.J Director's Office. Office of Inspection and Enforcement 84/07/25 ip 28854 341
- B408030333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures" Svc list encl JORDAN.Et. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26067 278 24X Fiche 50-000.84/08/06.8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 30-000.84/08/06.8408010337
- B40B020052 PNG-III-84-0A; on B40726, insp of shipments found Tc-99m apparently contaminated u/Mo-97 Caused by mfg defect Confirmatory action ltr sent to licensee for commitment to notify all customers of potentially contaminated Tc-99m HIEDEMAN, D. AXELSON, W.L. Region 3. Office of Director 84/07/27 2pp 25872 258
- 8408030002 PMD-1-84-064 on 840731, determined licensee radiographer received quarterly whole body radiation exposure of 4 37 rem for Becond Guarter 1984 Investigation to evaluate exposure will be conducted NICCLOBI.J. JOYNER.J. Region 1. Office of Director 84/07/31 tp 28906 023
- B40B030023 PND-II-84-045 on B40729, senior resident inspector W Swan fatally injured in traffic accident Funeral svcs held B40B01 in Athens,TN
  JULIAN.C A , VERREULI,D M Region 2, Office of Director 84/07/30 ip 25907 084 24% Fiche 50-390,84/07/30.8408030023
- 8408030137 PNO-1-B4-062A on 840726, during planned loss of offsite ac power startup test at 30% reactor power, backup emergency diesel generators did not automatically start Caused by incorrectly positioned dc power switches EBELGROTH.P. ORECNMAN.E. Region 1. Office of Director 84/07/27 ip 25912 018 24% Fiche 50-368, B4/07/27, B408030137
- B40B060013 PNO-V-B4-046 on B4072B, w/unit in hot standby, inadvertent safety injection actuation occurred Caused by high steam flow signal resulting from surveillance testing in progress JOHNBON, P. MENODNCA, M. M. Region 5, Office of Director 84/07/30 p. 25933 183 24% Fichs 50-275, 84/07/30, 840B060013
- B40B0b0123 PND-V-B4-045 on B40710, licensee began evaporating highly purified liquid radwaste to dryness, resulting in airborne release of radioactive tritium Approx 5,800 gallons water processed resulting in release of 1 39 Ci to atmosphere YUHAB, 0, WENSLAMBKI, F Region 5, Office of Director B4/07/27 ip 25733 193 24X Fiche 50-312,84/07/27,8408060123
- 8408060156 PNO-V-E4-044 on E40723, licensee learned that highly radioactive 2 x 0 6 x 0 1-inch metal object removed from steam generator 8 primary side inlet Source of metal or extent of personnel exposures not identified YUHAS, 0 , WENSLAWSKI, F Region 5, Office of Director 84/07/27 ip 23932 198 24x Fiche, 50-312, 84/07/27, 8408060156
- 8408070120 IE Info Natice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120
- 840B070135 PNS-V-B4-012 on 840727, routing safety patrol discovered suspicious-looking device near control room Device determined not explosive. Technician identified device as electrical test equipment SCHWAN.C A , SCHUBTER.M D Region 5, Office of Director 84/07/30 1p 25949 342 24X Fiche. 50-397, 84/07/30, 8408070135

- 8408070205 PNO-I-84-065 on 840802 personnel noted smoke coming from cubicle in suitchgear room Caused by tripped breater due to electrical fault during surveillance testing Damaged bus deemergized Licensee decreasing power for plant shutdown ELBASSER I GREENMAN.E Region i Office of Director 84/09/02 2pp 25749 288 24% Fiche 50-027 84/08/02.8408070205
- 8408070329 PNO-III-84-052 on 840801.fire broke out in lab fume handeventually destroying four Mo-99/TC-99m generators Low level contamination found in hallway near fire 2 removed Caused by electrical malfunction fire estinguished HIEDEMAN.D G . AXELSON.W L Region 3. Office of Director 84/08/03 lp 25945 143
- 8408070376 IE Info Notice 84-62, "Therapy Hisadministrations to Patients Undergoing Co-60 Teletherapy Treatments' Evo list enci ORACE UN Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26129 235 24x Fiche 50-000.084/08/10.8408070376
- B40B070416 PNO-V-B4-047 on B40731, temporary work stoppage occurred following misunderstanding re alleged contamination of const workers on B40730 No contamination found on workers or vehicles Issue resolved by contractor vehicles Issue resolved by contractor NGRTH.H. JENSLAHSKI F Region 5. Office of Director B4/07/31 p 25742 052 24X Fiche 50-312.84/07/31,8408070416
- 8408090176 PNO-IV-84-015 on 840720, liquid release from reactor bldg exceeded Tech Spec gross beta limits by factor of 2 24 Violation not recognized until 840726 Investigation ongoing Special insp of event scheduled for wh of 840730 MURRAY. B. HALL.R. Region 4. Office of Director 84/07/27 1p 25994 362 24X Fiche 50-267.84/07/27.8408090176
- 8408100007 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc list encl
  JURDAN,E L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc. 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Syc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc. 118pp 26177-337 24X Fiche 50-000,84/08/16,8408100021
- 8408100035 PNO-I-84-065A on 840802.plant shut down following switchgear fire Cause unidentified Extensive bus & switchgear damage found Corrective actions will be monitored ASARS.A . FERLIG.K Region i, Office of Director 84/08/03 ip 25990 060 24x Fiche 50-029.84/08/03.8408100035
- 840B10D03B 1E Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication "Syc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24% Fiche 50-000.84/08/15, 840810003B
- 8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000.84/08/17.8408100055
- 8408100072 PNO-I-84-067 on 840806 indication detected in reactor vessel wall during ultrasonic test Evaluation & review of const records & photographs continuing Startup From 10-yr inservice insp outage scheduled for late Sept 1984 DURR. J P., NORRHOLH.L. Region 1, Office of Director 84/08/08 1p 25990 043 24% Fiche 50-247,84/08/08,8408100072
- 8408100109 PND-III-84-0588 on 840718 litensee successfully completed integrated leak rate test following 840718 shutdown for failure to demonstrate integrity of containment Unit expected to start up by 840816 SUERMANN, J. HRIGHTIG , REYES, L. Region 3, Office of Director 84/08/02 jp 25990 362 24% Fiche 50-295.84/08/02,8408100109
- 840Bi0012? PNO-I-84-066 on 840807.NRC notified that 5 mC: Kr-85 source stolen during Jan 1984 break-in at Fort Richardson.FL facility Personnel responsible for failure to rept theft immediately reprimanded JOHANBEN J. OLENNIJ. JOYNER, J. Region 1. Office of Director 84/08/08 ip 25988 278
- B40B140l36 PNO-II-84-047 on 840B06.licenses reported inventory difference from 840703 physical inventory Difference was accounting loss & within associated limit of error & other regulatory requirements State of TN Informed MCALPINE, E. J. Region 2. Office of Director 84/08/07 ip 260B18 321

- 8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates" Svc list and JDRDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc. 122pp 26276 122 24X Fiche 50-000.84/08/17.8408140208
- 8408140324 PMO-II-84-045 on 830805.w/unit in cold shutdown.packing ring blew out from chemical & vol control sys letfown line valve connected to RHR sys Line break occurred in auxiliary bldg room sacket weld discharging 3.500 gallons water IGNATONIS.A . BROWNLEE, VL Region 2, Office of Director 84/08/06 2pp 26042 351 24X Fiche 50-370.84/08/06.8408140324
- 840B140346 PNO-V-84-048 during present outage for steam generator tube plugging repairs, two suagelok fitting leaks identified in process piping installed during 1983 outage All swagelok fittings undergoing insp Outage extended MYERS, C., ECKHARDT, J. Region 5. Office of Director 84/09/09 ip 26042 325 24X Fiche 50-312,84/08/08,8408140346
- B408150466 Forwards draft IE info notice, "Defective Replacement GE Tubes for Eberline Instrument Model 61128 folebectors" Verification of facts requested by 840815 for consideration in final version BAER.R L Engineering & Generic Communications Branch 84/08/06 LND. Inc 3pp 26105 232
- B408160003 PNO-I-84-068 on 840808, received notification that during routine bicassay on 840803, worker had thyroid burden of approx 500 CCI I-123 Worker performed indination using 7 mCI I-125 on 840729 Investigation ongoing DARDEN.T. KINNEMAN.J., JUYNER.J. Region 1. Office of Director 84/08/09 ip 26128 214
- 8408160130 PNS-I-84-016 on 840807, employee discovered box marked "Bomb" adjacent to front door of bldg Local police & fire personnel responded Bonb squad supplied small explosive charge which detonated Bldg searched for addl packages JOYNER, J. MARTIN, T. Region 1. Office of Director 84/08/09 1p. 26126 166
- 840B170369 PNO-V-B4-049 on B40B12 unusual event declared when prairie brush fire led to potential for loss of offsite 230-ky startup gowerlines & 115-ky backup power lines Plant dissel generators started as contingency TOTH, A D . DDDDS,R T Region 3. Office of Director 84/08/13 ip 26112 358 24X Fiche-50-397,84/08/13.8408170369
- 8408200308 PND-III-84-063 on 840810. Unusual event declared due to leakage from primary coolant sys pressure sensing line isolation valve NV-1019A Held cracked Piping & weld to be cut out & replaced Startup scheduled by 840816 HRIGHT, G. SHAFER, W. Region 3. Office of Director 84/08/13 ip 26133 018 24X Fiche. 50-255, 84/08/13, 8408200308
- 8408200324 PNO-III-84-064 on 840813.1.200 gailons of water from refueling water storage tank injected into primary sys via boron injection tank No release of radioactivity occurred Caused by faulty electrical channels FORNEY.W. WARNICK.R. Region 3. Office of Director 84/08/13 ip 26133 001 24X Fiche 50-483.84/08/13.8408200324
- 8408210142 IE Info Notice 84-68. "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26327 008 24X Fiche 50-000;84/08/21.8408210142
- 840B210269 PNO-III-84-065 on 840B14. Unit 1 tripped from 100% due to failure of control room instrument distribution panel Failure caused reactor protection sys to lose filow in one coolant loop Panel reptaced Tests performed for operability MRIGHT, G., SHAFER, M. Region 3, Office of Director 84/08/15 1p 26180 344 24% Fiche 50-315, 84/08/15, 840B210269
- 8408210280 PND-I-84-069A on BA080S individual working at facility had thyroid burden of 300 mCi I-123 Licenses believes loding accidently swallowed Contamination levels ranging from 1.000 to 20.000 counts per minute found in apartment DARDEN, T. KINNEMAN, J. JUNNER, J. Region 1. Office of Director 84/08/13 2pp. 24180-345
- B408210383 PNO-1-84-069 on 840716.licenses reported five missing lower head steam generator plugs Licenses working u/ Westinghouse to develop method of testing plugs Evaluation continuing CONNER.E Region 1. Office of Director 84/08/15 19 26180:251 24X Fiche 50-287,84/08/15,8408210383

- 8408210407 EH-84-051 on 840817 notice of violation & proposed imposition of civil penalties in amount of \$500 mill be issued Action based on unauthorited individuals storing source holder in unrestricted area FLACK,E , AXELRAD,J Director's Office, Office of Inspection and Enfarcement 84/08/14 ip 26180 338
- B40B210483 PNO-II-84-050 lung cancer patient received dose of 3,060 rads to portion of lung instead of prescribed dose of 1,300-1,800 rads Caused by failure to insert new filter block in teletherapy device Rept will be submitted within 15 days CHAMBLESS.P M , POTTER, J P Region 2, Office of Director B4/0B/13 2pp 26181 121
- B408220139 PNO-V-84-050 on 840815, influx of seawed caused reduction in circulating water flow Power reduced as condenser vacuum degraded High differential pressure observed on train B component cooling water HX while train A inoperable KIRSCH.D. HAIST, D. Region 5, Office of Director 84/08/15 ip 26194 048 24X Fiche 50-361,84/08/15,8408220139
- 840B230001 PNO-II-84-052 on 840B20 leak developed inside containment while upper head injection sys filled & checked for air entrapment Caused by glass on upper head injection sys blown out during pressurization No environ release occurred IGNATONIS.A J. BROWNLEC, V L. Region 2, Office of Director 84/08/20 2pp 26207 158 24% Fiche 50-370.84/08/20.8408230001
- 8408230040 PND-II-84-049 on 840814.possible overpressurization of one core spray sys loop occurred Caused by backflow of primary containt into loop because outboard isolation valve & inboard isolation check valve leaked

  BUTCHER.R C , CANTRELL,F S Region 2, Office of Director 84/08/11

  2pp 26204 018 24X Fiche 50-259,84/08/15,8408230-040
- B408230392 PND-II-84-051 on B40817, earth tremor measuring 3 B on Richter scale occurred Tremor did not trip plant seismic monitoring equipment ELROD, 5 A. DANGE, H C. Region 2. Office of Director B4/08/17 ip 26205 303 24X Fiche 50-338,84/08/17,8408230392
- 8408240114 PNO-III-B4-066 on B40818.RHR B loop full flow test valve failed to completely close manually, rendering low pressure injection, shutdown cooling & suppression pool cooling inoperable Unit in cold shutdown pending repairs & maint CHRISSOTIMOS.N. SHAFER, W. Region 3. Dffice of Director 84/08/20 ip 26228 216 24% Fiche 50~374.84/08/20.8408240114
- 8408240283 PND-I-84-071 on B4082), reactor automatically scrammed due to low water level caused by feedwater control sys failure Scram resulted in primary containment isolation sys Group 1 isolation tripped rectrculation pumps GALLO.R Region 1, Office of Director 5D-278840821 84/08/21 ip 26283 196 24X Fiche 50-278,84/08/21,8408240283
- B408240286 PNO-II-84-053 on 840820.unit shut down after pressure surge caused opening of ice condensor doors, causing relief tank pressure drop & containment pressure rise Caused by relief tank disc rupture or broken safety valve tailpipe FREDERICKEDN.P. CONTRELL.F B Region 2, Office of Director 84/08/21 2pp 26223 194 24X Fiche 50-328.84/08/21,8408240286
- 8408240287 PND-V-84-051 on 84081B.control rod L-3 bank D, stuck at almost fully withdrawn position during rolf rod drop tests Seal weld for control rod guide mechanism will be cut to determine if latching mechanism at fault DODDS.R T , RICHARDS. 3 A Region 5. Office of Director 84/08/20 ip 26223 i86 24X Fiche 50-344.84/08/20,8408240287
- 8408240270 PNO-II-84-052A on 840820.4.800 gallons reactor coolant inventory spilled into reactor bidg sump area Caused by sight glass being blown out of upper head injection sys Alarm printer reviewed & sight glass replaced IGNATONIS.A J. BROWNLES, V L. Region 2, Office of Director 84/08/21 2pp 26273 171 24X Fiche 50-370.84/08/21.8408240270
- 8408240329 PNO-II-84-034 on 840821.after Unit 1 reactor tripped, operators manually isolated MBIVs to prevent overcooling, resulting in water hammer in secondary sys Damage being assessed IGNATONIS, A J. BROWNLEE, V L. Region 2, Office of Director 84/08/22 2pp 26225 306 24% Fiche 50-367.84/08/22,8408240329
- 8408240397 EN-84-052 on 840822, notice of violation & proposed imposition of civil penalty in amount of \$1,600 will be issued Action based on use of unauthorized matl & failure to calibr survey maters at required intervals FLACK, E. AXELRAD. J Director's Office. Office of Inspection and Enforcement 84/08/17 ip 26225 312

- 8408280048 En-84-016A on 810330, notice of violation & proposed imposition of civil penalties in amount of \$2,500 issued Action based on unauthorized transfer of licensed math & failure to perform required leak tests
  FLACY.E. AXELRADIJ Director's Office. Office of Inspection and Enforcement 84/08/20 ip 26261 216
- 8408280073 EN-84-053 on 840823, notice of violation & proposed imposition of civil penalties in amount of \$8.500 will be issued Action based on distribution of radiopharms by Blue Ash facility contaminated w/Mo-99 FLACV.E , AXELRAD. Director's Office, Office of Inspection and Enforcement 84/08/20 ip 26261 215
- 840B2800/8 PND-V-84·052 on B40B2(,) Licensee determined that HPSI potentially degraded due to component cooling water HX mini flow bypass open for subgroup relay testing Formal investigation bying conducted MCRRILL.P. HAIST.D Region 5, Office of Director 84/08/22 128261 206 24X Fiche 50-362,84/08/22,840B280078
- 840B280107 PND-1-84-070 on 840B21, reactor vessel cavity seal failed when initially filled Caused by trip in containment sump pump under reactor vessel Licensee evaluating situation Notification of state & local authorities undertaken BWETLAND, P. MCCABE. E Region 1. Office of Director 84/08/21 1 26261 301 24x Fiche 50-213,84/08/21,8408280107
- 8408280152 PND-II-84-055 on 840823, util announced that seven employees dismissed due to alleged unauthorized bid disclosures in procurement of small tools & expendable const supplies Dealings w/one vendor terminated PANCIERA.V., DANCE.H.C. Region 2. Office of Director 84/08/24 1p 26274 309 24% Fiche 50-424,84/08/24,8408280152
- 8408280158 PND-II-84-054A on 840821, reactor trip occurred due to partial loss of offsite power Caused by inadvertent opening of switchyard computer operated breakers Reactors restarted IGNATONIS, A J , BROWNLEE, V L Region 2, Office of Director 84/08/23 1p 26259 212 24X Fiche 50-369, 84/08/23, 8408280158
- 8408280267 PNO-II-84-056 Nuclear Safety Review Staff rept assessing TVA actions re 840419 in-core probe seal table break received Inspectors will investigate event further on 840827 Util & NRC responding to media inquiries FREDERICKSON.P. y. WEISE.S. Region 2. Office of Director IEIN-84-55 84/08/24 ip 26261 341 24% Fiche 50-327.84/08/24.8408280267
- 840829036 PNO-V-84-053 on 840822, thermal transient occurred in reactor feedwater sys downstream of high pressure feedwater heaters 6A & 68 Transient caused pape hanger & support damage resulting in leakage of approx 20 gallons water DDDDS,R T . TOTH A D Region 5. Office of Director 84/08/23 ip 26291 213 24% Fiche 50-397,84/08/23,8408290036
- 8408270120 EN-84-094 notice of violation & proposed imposition of civil penalties in amount of \$500 to be issued for license Action based on storage of 450 nct Ca-137 contained in density gauge in unrestricted area & failure to monitor lab areas ROBINSON.P. AXELRAD.J. Director's Office, Office of Inspection and Enforcement 84/08/23 ip 26287 233
- 8408300146 EN-84-009A notice of violation & proposed imposition of civil penalty in amount of \$30,000 issued re failure to follow procedures for entry into locked high radiation area FLACK.E. AXELRAD.J Director's Office. Office of Inspection and Enforcement 84/08/28 ip 26304 357 24X Fiche 50-261,84/08/28,8408300146
- 840831004; PND-1-84-072 on 840823 Southwest Nuclear found to be in violation of license by storing biomodical & low level waste in warehouse in Beltsville. MD No leakage or contamination found Waste to be shipped within 30 days

  BRENNEMAN.F. Region 1, Office of Director 84/08/24 lp
  26322 131
- 840B310065 PNS-I-84-017 on 840B27, unidentified male telephoned security post at Elevation 100 ft of Unit 1 on internal line & told security guard that bonb planted in containment Bomb search teams deployed No bomb found No explosion occurred DUNLAP.J. KEIMIG.R., JOYNER.J. Region 1. Diffice of Director 84/08/27 1p 26323 203 24x Fiche 50-272,04/08/27,840B310065
- 84083100/4 PNO-I-84-073 on B40824.offsite power lost Emergency diesel A started but did not close to bus & RHR flow for shutdown reactor lost until RHR pump supplied by emergency diesel placed on-line Tripped transformer placed on-line SHETLAND, P. MCCABE, E. Region i. Office of Director 84/08/24 ip 26322 201 24X Fiche 50-213,84/08/24,8408310074

- 8408310980 PNO-1-84-074 on 840824, Accuray Model O-2 gauging device containing 55 mCi Sr-90 lost Gauge removed from storage on 840425 to perform routine leak test Gauge apparently disposed of w/other equipment in refuse bin or compactor TAYLOR.M KINNEMAN.J. JOYNER,J Region 1, Office of Director 84/08/27 ip 26323 202
- 8408310111 PNO-I-84~070A on 840823, refueling cavity to reactor vessel seal failure identified during fuel transfer Cavity-to-vossel inflatable boot seal unique in US Failure Wfuel transfer tube upen would result in high radiation SWETLAND.P. HCCAUE.E Region 1. Office of Director 84/08/24 ip 26322 ii3 24% Fiche 50-213 84/08/24, 8408310111
- 8408310248 PND-III-84-047 first of several spent reactor fuel shipments from Cooper Station arrived safely Rail shipment consisted of three NRC-certified shipping casks, each containing 18 spent fuel assemblies LOVENDALE.P., PAPERIE LD.C. J. Region 3, Office of Director 84/08/24 ip 26333 329

## PUBLIC DOCUMENT ROOM MISCELLANEOUS

- 8408010157 Requests attendance at 840727 & 30 training sessions on Inspector Rept Form 766 TROTTIER,E Vendor Program Branch 84/07/26 Branch 1p 29855 303 Vendor Program
- 8408030277 Responds to 840703 ltr re seismic safety of nuclear reactors in Mississippi Valley states Forwards responses to specific questions Info re seismic design contained in SER for each plant available in POR DENTON, HR Office of Nuclear Reactor Regulation, Director 84/07/24 TOTTEN, M Critical Mass Energy Project 7pp 25935 125
- ---8408030282 Requests clarification of 840531 ltr re seismic safety of nuclear leactor in Mississippi Valley states
  TOTTER.M Critical Mass Energy Project 84/07/03 DIRCKB.W J
  Office of the Executive Director for Operations 2pp 25935 133
- 8408060069 Forwards case study rept, "Steam Binding of Auxiliary Feeduater Pumps " Backleakage represents potential common cause failure for auxiliary feeduater sys HELTEMEG.C J Director's Office 84/07/23 ROSSIN,D Nuclear Bafety Analysis Center ip 25937 005 1 p
- --B40B060073 Forwards case study rept. "Steam Binding of Auxiliary Feedwater Pumps" Backleakage represents potential common cause failure for auxiliary feedwater sys HELTEMES.C J Director's Office B4/07/23 PATE.Z Institute of Nuclear Power Operations ip 25937 006
- --8408060077 Forwards case study rept. "Steam Binding of Auxiliary Feedwater Punps " NRR considering interim measures to reduce putontial for steam binding of auxiliary feedwater pumps at operating PWRs until generic issue resolved HELTEMES.C J Director's Office 84/07/23 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 25937 007
- --B408060081 Forwards case study rept. "Steam Binding of Auxiliary Feeduater Pumps" Backleakage represents potential common cause failure for auxiliary feedwater sys
  HELTEMES.C J Director's Office 84/07/23 RAHE,E P
  Hestinghouse Electric Corp SHEPPARD.J Hestinghouse Operating Plants Owners Group SHEPPARD.J Carolina Power & Light Co 2, 29737 009
- --8408060083 "Steam Binding of Auxiliary Feedwater Pumps " LANNING,W Reactor Operations Analysis Branch AEOD/C404 84/07/31 60pp 25737 Oll
- 8408040389 Forwards AEOD "Steam Dinding of Auxiliary Feedwater Pumps," final rept Rept reflects peer review process AEOD recommendations re study previously forwarded to NRR for appropriate action
  DIRKES W J Dffice of the Executive Director for Operations
  84/07/26 PALLADING ROBERTS ASSELSTINE Commissioners, 1
  25951 174
- B40B07000B Summary of B40719 operating reactor events meeting w/div directors re events occurring since 84062B meeting List of attendees t viewgraphs encl CRUICHFIELD, D Assistant Director for Safety Assessment 84/07/27 EISENHUT, D G Division of Licensing 12pp 25956 208
- B408070057 Notification of 840815 meeting w/8M Stoller Corp in Bethesda.MD to hear presentation on OPEC-2 computer sys MORRIS.C Reliability & Risk Assessment Branch 64/07/30 THADANI.A Reliability & Risk Assessment Branch 2pp 25955 330

- 8408160439 Forwards evaluation of Generic Issue 49 re interlocks & limiting conditions for operation for Class 1E tie breakers Schedule for resolving generic issue should be in accordance w/NRR Ltr 40 w/NRR Ltr 40 DENTON, H R Office of Nuclear Reactor Regulation, Director 84/07/31 MULLER, D R Division of Systems Integration (post B11005) 11pp 26108 353
- 8408170280 Requests removal of J Hard from distribution list for listed repts or documents
  LEINS,E Atomic Safety and Licensing Board Panel 84/08/09
  SCHAEFFER,C Document Management Branch 1p 26115 255
- 8408220441 Forwards errata sheet for AEOD Special Study Rept AEOD/9402 re pressure locking of flexible disk wedge-type gate valves, previously transmitted as attachment to 840706 memo HELTEMESIC J. Director's Office 84/08/03 DEVOUND, R.C. Director's Office, Office of Inspection and Enforcement 2pp
- 8408240369 Forwards FR notice re issuance of amend to OL Amend involves NBHC not withstanding pendency before Commission of hearing request W/o soci DENTON.H R Office of Nuclear Reactor Regulation. Director B4/08/01 SIMPSON.A Benate. Environment & Public Works 2pp 26254 345
- 840824040) Forwards monthly status rept on plant-specific backfits through Jul 1984 Table depicting status of appeal items for operating reactors & OL applicants provided Supplemental tables also enci
  EISENHUT. D G Division of Licensing 84/08/14 DENTON, H R OF tables also enci EISENHUT.D G Division of Licensing 84/08/14 DENTON. of Nuclear Reactor Regulation, Director 4pp 26248 324 DENTON: H R Office
- 8408240425 Forwards comments & updates on AEGD second semiannual rept of unresolved recommendations DEM/ON-HR Office of Nuclear Reactor Regulation. Director DEM/OB/16 HELLENBES.C J Director's Office 7pp 26248 2
- 8409300143 Outlines qualification requirements for OL personnel assigned to Div of Reactor Safety Training & qualification manual encl SPESSARD.R L Region 3. Office of Director 84/08/22 Office of Director 30pp 26331 268
- 8408310410 Responds to 840731 memo re analysis of nonpower reactor sabotage Criteria of 10CFR100 inapplicable for assessment of radiological consequences of sabotage at nonpower reactors Study should evaluate sabotage consequences EISENHUT.D G Division of Licensing 84/08/20 BURNETT, R F Office of Nuclear Material Safety & Safeguards, Director 3pp 26350 345

#### NURSE REPORTS AND RELATED CORRESPONDENCE NUREO

- 8405210578 NUREC/CR-3633 V02 TRAC-BDI/MODI AN ADVANCED BEST ESTIMATE COMPUTER PROGRAM FOR BOILING WATER REACTOR TRANSIENT ANALYSIS Volume 2 Users euige BCHUMMAY,R 44 , MOHR.C M EGLO, Inc FIN A-6052 EGG-2294 B4/O4/30 Division of Accident Evaluation 117pp 2452
- 8405210579 NUREO/CR-3633 V03 405210579 NUREO/CR-3433 V03
  TRAC-BDI/KQDI AN ADVANCED BEST ESTIMATE COMPUTER PROGRAM
  FOR BOILING WATER REACTOR TRANSIENT ANALYSIS Volume 3 Code
  Structure and Programming Information
  SINGER, 8 L, MDMR, C M EG&D, Inc FIN A-6052 E0G-2294 84/04/30
  Division of Accident Evaluation 110pp 24528 357
- 8405190049 NUREO-0953 SO3 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CLINTON POWER STATION, UNIT NO 1 Docket No. 30-461 (Illinois Power Formal Station, Opt. The Property of 33-451 (Tittles Fore)

  \* Division of Licensing 84/05/31 40pp 25025 274 24X

  Fiche 50-461.84/05/31.8406190045
- 840A1900A9 NUREG-0776 507 406190069 NUREO-0776 SO7 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SUBGUEHANNA STEAM ELFCTRIC STATION, UNITS 1 AND 2 Docket Nos 50-087 And 50-388 (Fennsylvania Pawer And Light Company, Allegheny Electric Cooperative, Incorporated) \* Division of Licensing 84/05/31 17pp Available at NRC, \*3 00 25025:253 24X Fiche 50-387,84/05/31,8406190069
- 840.6220100 Requests notification of analyses utilizing methodology not providusly approved in NUREO-0.651, "Mark I Containment Long-Term Program" in determining need for logic changes RIVENBARK.Q W Operating Reactors Branch 2 84/06/11 BAUER.E G Philadelphia Electric Co 3pp 25100 343 24X Ficha 50-277.84/06/11.8406220100

8406230301 NURED/CR-3704 THREE-DIMENSIONAL CALCULATIONS OF TRANSIENT FLUID-THERMAL MIXING IN THE DOWNCOMER OF THE CLAVERT CLIFFS-! PLANT USING A-ris 7.8 J Los Alamos Scientific Laboratory FIN A-7306 10039-MS 84/04/30 Division of Accident Evaluation 31 319 24% Fiche 50-317,84/04/30,8406230301 86ap 25131 319

8407130502 NUREQ-1020LD V01

OPU V BEW LAWBUIT REVIEW AND ITS EFFECT ON TMI-1 General Public Utilities Corporation, et al v The Babcock & Wilcox Company, et al Three Hile Island Nuclear Station, Unit 1, Dacket 50-289

\*\* Office of Nuclear Reactor Regulation, Director 84/06/30 152pp 25579 089 24X Fiche 50~289,84/06/30,8407130502

8407170313 Requests review of draft NUREG-1032. App A re loss of offsite power frequency & duration relationship & of DRNL draft rept on loss of offsite power operating experience Comments requested by 840801 W/o encl BARANOWSKY.P W Reactor Risk Branch 84/07/il KNIEL.K Generic Issues Branch 2pp 24048 061

--B407170316 Forwards draft loss of offsite power frequency & duration analyses Results indicate significant reduction in estimated frequency & duration of loss of power transient & contradict previous EPRI findings Review requested for 840731 meeting BARANOWSKY.P W Reactor Risk Branch 84/07/11 BERGER.W E Sargent & Lundy, Inc. 76pp 26068 063

8407230153 Comments on NUREO-1055. "Improving Quality & Assurance of Quality in Design & Const of Nuclear Power Plants "Comprehensive third-party audits should be used to periodically confirm effectiveness of mgt GA/QC programs MARRISON.S F National Board of Boiler & Pressure Vessel Inspectors, 84/07/18 GRACE,N Office of the Becretary of the Commission 9pp 26041 236

B40B010005 Request correction to date of ltr.forwarded on B40602, requesting info on NUREO-0737, Item II D 1 re performance testing of relief & safety valves Correct date is B40702 VARQA.8 A Dperating Reactors Branch i B4/07/23 MCDONALD.R Alabama Power Co 2pp 25867 361 24X Fiche 50-250, B4/07/23, MCDONALD, R. P. 8408010005

8408010015 Summary of ACRS Class-9 Accidents Subcommittee 840427 meeting in Washington DC re draft NUREO-1070. "NRC Policy on Future Reactor Design Decisions on Severe Accident Issues in Nuclear Power Plant Design "

\* ACRS - Advisory Committee on Reactor Safeguards 84/07/02 ACRS - Advisory Committee on Reactor Safeguards 17pp 25897

8408010018 Forwards SER & EG&O technical evaluation rept re response to Generic Ltr 81-04 (Rev 1 to NUREO-0313) concerning BWR coolant pressure boundary piping VASSALLO,D B Operating Reactors Branch 2 GL-81-04 84/07/23 PILANT,J M Nebraska Public Power District 3pp 25867 305 24) Fiche 50-278.84/07/23.8408010018

--8408010022 Safety evalution re IOSCC in RCPB piping sys,per Generic Ltr 81-04 Licensee response does not meet NUREG-0313 guidelines Further action will depend upon responses to Generic Ltrs 84-07 & 84-11 + Office of Nuclear Reactor Regulation, Director QL-81-04 84/07/23 4pp 23867 308 24X Fiche 30-298,84/07/23,8408010018

--8408010027 EGQ-FM-6521

"Tachnical Evaluation of Integrity of Cooper Nuclear Station Reactor Coolant Boundary Piping Sys " NAGATA,P K EQ&Q, Inc FIN A-6429 TAC 46657 B3/07/31 KOO,W H Division of Engineering 40pp 25867 312 24X Fiche 50-298,84/07/23,8408010018

8408010030 Forwards SER re containment hydrogen monitor (NUREG-0737, Item II F 1 6) Monitor neets all criteria of NUREG-0737 oxcept requirement for redundancy Response requested within 30 days PAULSON, W A Operating Reactors Branch 5 84/07/30 COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 7pp 25855 326 24X Fiche 50-245.84/07/30,8408010030

8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Goold & M Stebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing FELTON.J M Division of Rules and Records BX14 000 84/07/18, RIGE, C M Kirkland & Ellis 2pp 26500 001

--8408150751 Forwards const status rept as of 791001 Handwritten notes re diesel generator blog & soll settlement & errata to NVREC-0834 encl FIGRELLI-G Region 3, Chicago, Reactor Construction & Engineering Support Branch BX20 041A 79/10/05 KNDP.R C NRC - No Detailed Affiliation Given 107pp 26548 359

840B010078 Informs that licensee responses to NUREG-0737. Item 11 F 2. "Instrumentation for Detection of Inadequate Core Cooling." acceptable SSER input & nilestones encl YCUNOBLOOD. B J Licensing Branch 1 84/07/19 SPENCE.M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 12pp 25897 225 24X Fiche 50-445.84/07/19.8408010078

8408010099 Forwards request for addl info re applicability of generic test results for safety/relief valves submitted in NEDE-24988-P by BKR Owners Group Info needed for review of response to NURRO-0737, Item II D 1 YOUNGBLOOD, B J Licensing Branch 1 B4/07/20 CURTIS, N W Pennsylvania Power & Light Co 3pp 29897 057 24X Fiche 50-387,84/07/20,8408010099

8408010107 Forwards request for add1 info re NUREG-0737, Item II D 1, including basis for application of findings of NEDE-24988-P.
"Analysis of Openetic BKR Safety 1 Relief Valve Openability
Tast Results." submitted by BWR Owners Group
BCHMENCER,A Licensing Branch 2 84/07/24 FARRAR,D L
Commonwealth Edison Co 4pp 25873 355 24X Fiche 50-373,84/07/24, 8408010107

8408010129 Forwards DES (NUREG-1054) & notice of availability for Millstone 3 Comments due within 45 days after publication of FR notice of issuance U/O NUREG YOUNGBLOOD, B J Licensing Branch 1 84/07/24 Connecticut, of 28p 25873 313 24X Fiche 50-423.84/07/24.8408010129

--8408010131 Notice of availability of DES (NUREG-1064) for Millstone 3 YOUNOBLOOD: B J Licensing Branch 1 84/07/24 2pp 25873 315 24X Fiche 50-423.84/07/24.8408010129

8408010148 NUREO-1064
DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF MILLSTONE NUCLEAR POWER STATION UNIT 3 DOCKET NO 50-423 (NORTHEAST NUCLEAR ENERGY COMPANY.et al)

\* Division of Licensing 84/07/31 335pp Available at 84 00 25871 012 24% Fiche 50-423.84/07/31,8408010148 Available at NRC

8408010151 NUREO/CR-3841 OBCIOISI NUREO/CR-3844
CHARACTERITATION OF THE RADIOACTIVE WASTE PACKACES OF THE
MINNESOTA MINING AND MANUFACTURING COMPANY
KEMPF,C R. SISKIND. O. BARLETTA.R E Brookhavon National
Laboratory FIN A-3172 BNL-NARC-51787 84/07/31 Division of
Waste Management 93pp Available at NRC \$4 50 25872 001

B40B010154 Forwards "Procedures Generation Package For Beaver Valley Power Station. Unit 2." in response to Generic Ltr 82-33. describing methods for developing function oriented emergency operating procedures, per NURCO-0737. Item II C 1 WD0LEVER, E J Duquesne Light Co QL-82-33 84/07/26 E18CNUTU. D Q Division of Licensing Jpp 25655 184 24X Fiche. 30-412, 84/07/26, 8408010154

-8408010156 "Procedures Generation Package for Beaver Valley Power Btation, Unit 2 "
CLEMENTS, R H , JONES, D T Duquesne Light Co 8
25855 187 24X Fiche 50-412,84/07/26,8408010154 84/08/01 11600

8408010155 NUREG/CR-3826

RECOMMENDATIONS FOR PROTECTING AGAINST FAILURE BY DRITTLE FRACTURE IN FERRITIC STEEL SHIPPING CONTAINERS GREATER THAN FOUR INCHES THICK SCHIARTZ M W Lawrence Livermore National Laboratory FIN A-UCRL-53338 84/07/31 Division of Engineering Technology Available at NRC \$5 50 25872 087

8408010158 NUREG/CR-3897

ROBLING MUREL/CR-387/
EVALUATION OF ECOBYSTEM SIMULATION MODELS AS TOOLS FOR ASSESSMENT OF POWER PLANT IMPACTS ON FISH POPULATIONS Final Rept SWARTZMAN, G L SHARTZMAN,G L Washington, Univ of, Seattle, WA FIN 8-7 84/07/31 Division of Health, Siting & Waste Management Available at NRC \$3 00 25847 292

840B010161 Notification of B40727 meeting w/util at site to discuss questions re control of heavy loads (Multi-Plant Action C-15) Operating Reactors Branch 1 84/07/20 VARGA, B, A Operating Reactors Branch 1 2pp 25873 304 24X Fiche 50-280,84/07/20,8408010161

8408010164 NUREG/CR-3518 VOI BLIM-MAUD AN APPROACH TO ASSESSING HUMAN ERROR PROBABILITIES UBING STRUCTURED EXPERT JUDGEMENT Volume I Overview of EMBREY D E , HUMPHREYB, P , ROSA, E A

Brookhaven National Laboratory /3i Division of Facility FIN A-3219 BNL-NUREO-51716 84/07/31 Operations 36pp 25867 253 Operations

- 3010179 NUREC/CR-2331 VO3 N3 AFETY RESEARCH PROGRAMS SPONSORED BY OFFICE OF NUCLEAR EVOLATORY RESEARCH Guarterly Progress Report, July-September 2013 EISS, A J Brockhaven National Laboratory FIN A-30[[ 4L-NUREG-5:454 84/07/31 Division of Accident Evaluati 34pp 25870 181
- .-ISS.A J Brookhaven National Laboratory FIN A-30() .-NUAEG-51454 84/07/31 Division of Accident Evaluation App 25870 181
- 3010197 Forwards DES (NUREG-1064) & FR notice of issuance W/o
- JUNGBLOOD,B J Licensing Branch 1 84/07/24 COUNSIL,W G >htheast Nuclear Energy Co (subs of Northeast Vt:]ities) 3873 272 24X Fiche 50-423,84/07/24,8408010197
- 3010216 Discusses control room design review open items status per R (NUREG-0798) Encls identify human engineering Priciancias status & where possible ref document to

- 3010252 Forwards DES (NUREG-1064) & FR notice of availability, for 'view & comment Comments due within 45 days after iblication in FR W/o NUREO 'VINOBLOOD, B J Licensing Branch | 84/07/24 WOOD, J M Commerce, pt of Natl Decanographic & Atmospheric Administration App 1872 331 24X Fiche 50-423,84/07/24,8408010252
- 1010233 Response to ASL8 840712 inquiry whether NUREC/CR-3756 institutes substantial new info to lead to redetermination advances of setsmic design Inquiry fully warranted rificate of 8vc enci.
  HNSDN-T Campaign for Prosperous Georgia DSB 664 CL /07/26 17pp 25854 324 24% Fiche 30-424,84/07/26,8408010253
- IOLO319 Forwards application to amend License DPR-59, changing Tach ecs re NUREG-0737. Item II K 3 iB, "Mod of Automatic pressurization Sys Logic Feasibility for Increased versity for Some Event Sequences"

  INNE. J P Power Authority of the State of New York JPN-84-50

  JO7/25 VASSALLO, D B Operating Reactors Branch 2 2pp

  866 129 24X Fiche 50-333.84/07/25,8408010319
- OB010321 Application to amend License DPR-39, changing Tech Specs re NUREO-0737, Item II X 3 i8. "Mod of Automatic Depressurization Sys Logic Feasibility for Increased Diversity for Some Event Sequences "BAYNE, J P Power Authority of the State of New York 84/07/24 Power Authority of the State of New York 84/07/24 131 24% fiche 50-333.84/07/25,8408010319
- OB01032P Proposed Tech Spec changes re NUREG-0737, Item II K 3 1B tovering implementation of automatic depressurization syslogic mods

25866 131

- O20014 Advises that util Board of Directors ordered shutdown of sign const & testing activities for facilities on O716 CP & OL applications for both units will be intained Issuance of 88ER 4 (NUREO-0773) requested OK.J W Consumers Power Co 31636 84/07/27 DENTON, H R fice of Nuclear Reactor Regulation, Director 4pp 25883 116 X Fiche 50-329,84/07/27,8408020014
- O20030 Forwards requested info on NUREO-0737. Item II F 1 re interim occurres for quantifying high level accidental radioactive leases Info re Item III D 1 L will be furnished in Sept
- Philadelphia Electric Co 84/07/27 SCHWENCER.A anch 2 14pp 25883 218 24% Fiche 50-352.84/07/27. MPER J S censing Branch 2 08020030
- O20072 Comments on NUREQ-1055, "Improving Quality & QA in Design Const of Commercial Auglear Power Plants " Proposed audits reviews unnecessary, if sys ensures adequate mgt team sembled griop to CP issuance
  ANGLER, R G Texas Utilities Electric Co (formerly Texas Utilities nerating Co ) TXX-4234 84/07/19 Office of the Secretary of a Commission 3pp 25891 031
- D20079 Comments on NUREG-1035 re improving quality & GA in design & nst of nuclear power plants (Ford Amend Study) Programs ould be developed which maximize mgt ability by optimizing
- guilatory environ.

  TEN, D G Niagara Mohawk Power Corp 84/07/23 CHILK, S J Pice of the Secretary of the Commission 3pp 25871.285
- D2009: Comments on NUREQ-1055, "Improving Quality & QA in Design & nst of Commercial Nuclear Power Plants" Further analysis discussion of issues necessary prior to implementation of apposed NRC actions

  TE, Z T Institute of Nuclear Power Operations 84/07/25 

   keting & Bervices Branch 3pp 25892 260

- 8408020106 Package of two comments on NUREG-1055, "Improving Quality & GA in Design & Const of Nuclear Power Plants "CRONE, D M Southern Co Services, Inc CODK, J H Consumers Power Co 49FR14898 84/07/30 Docketing & Services Branch 5pp
- 8408020130 Clarifies util positions re NUREO-0737. Item I C & concerning tagging authorization independent verification post-maint configuration verification & ALARA concerns in response to NRC 840614 itr Revised procedures encl
  HARRINGTON, N D Boston Edison Co 84-114 84/07/27 VASBALLO, D D Operating Reactors Branch 2 4pp 25885 268 24X
  Fiche 50-293.84/07/27.8408020130
- 8408020138 Advises that Tech Spec change requests per Generic Ltr 83-37. "NUREG-0737 Tech Specs." will be submitted by 841231, per 840615 telcon request D'TOOLE.J D Consolidated Edison Co of New York, Inc OL-83-37 84/07/26 EISEMHUT D O Division of Licensing 1p 25892 305 24% Fiche 50-247.84/07/26.8408020138 QL-93-37
- 8408020140 Forwards FR notice of issuance & DES (NUREG-1064 )W/o DES YOUNGBLOOD, B J Licensing Branch i 84/07/24 HIRSCH, A Environmental Protection Agency 2pp 25898 091 24X Fichs 50-423,84/07/24,8408020140
- 8408020237 Comments on 840628 & 0702 mathine disposal of nuclear waste in unsaturated zone in comparison w/disposal in saturated zone in demonstrably impervious rock Math does not change validity of 840320 comments on NUREO-1096
  PHILBRICK. S & Philbrick. S & PHILBRICK. S & ACRS Advisory Committee on Reactor Safeguards 84/07/06 MOELLER, D W ACRS Advisory Committee on Reactor Safeguards 1p 25899 188
- 8408030019 Forwards responses to J Singh 840522 verbal questions recentral of heavy loads
  MILLS.L H Tennessee Valley Authority 84/07/27 ADENSAM, E
  Licensing Branch 4 2pp 25907 092, 24% Fiche 50-327, 84/07/27,
  8408030019
- --8408030025 Rev 3 to Procedure MI-6 22, "Control of Heavy Loads in Critical Lifting Zones NUREO-0612"

  DDTV.J W. NHEELER.L J Tennessee Valley Authority 84/05/21
  23pp 25907 094 24x Fiche 50-327.84/07/27.8408030019
- 8408030032 Confirms that Hestinghouse has completed review of listed power ascension & emergency procedures, per 810914 ltr Util reviewed Westinghouse comments & appropriate revs will be made before Unit i startup MILLS.L M Tennessee Valley Authority 84/07/27 ADENSAM, E Licensing Branch 4 2pp 25907 068 24X Fiche 50-390,84/07/27, 8408030032
- 8408030096 Application for amend to License DPR-23, revising Tech Specs re reactor vessel level instrumentation sys Revs will include instrumentation sys.per NURS-0-037 requirements CUTTER.A B Carolina Power & Light Co NLS-84-318 84/07/20 VARQA, S A Operating Reactors Branch 1 2pp 25904:349 24X Fiche 50-261.84/07/20.8408030096
- --8408030100 Proposed Tech Spacs re reactor vessel level instrumentation \* Carolina Power & Light Co QL-83-37 84/07/20. App 25904 351 24X Fiche 50-261.84/07/20.8408030096
- B408030104 Act receipt of B40703 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-289/84-03 Corrective actions will be examined during future insp MARTIN.T T Division of Engineering & Fechnical Programs B4/07/3 HUKILL.H D General Public Utilities GPU Service Corp App. 25904 303 24X Fiche 50-289,84/07/30.8408030104 84/07/30
- 24X Fiche 30~289,84/07/30,8408030104
- 8408030144 Forwards table of Type A variables & revs & updates of compliance to Reg Ouids 1 97.Rev 2.Types B.C & D variable requirements, in response to 831203 request VAN BRUNTLE E Arizona Public Service Co ANPP-30092-EEVB 84/08/01 KNIOHTON 9 Licensing Branch 3 28pp 25911:161 24X Fichs 50-528,84/08/01.8408030144
- 8408030167 Forwards Rev O to "Control Room Design Review Program Plan." in partial fulfillment of Generic Ltr 82-33, "Suppl i to NUREO-0737 Requirements for Emergency Response Capability "
  FAY: CW Wisconsin Electric Power Co GL-82-33. 84/07/31.
  DENTON, H R Office of Roclear Reactor Regulation, Director
  25911 193 24X Fiche 50-266,84/07/31.8408030167

- B40B060145 Application for amend to Licenses NPF--11 & NPF-18, changing Tech Specs re accident monitoring instrumentation (NUREO-0737), thems II F 1 1, II F 1 3 & II F 1 4) Fee encl MARBHALL, J G Commonwealth Edison Co 90101 B4/07/25 DENTON H R Office of Nuclear Reactor Regulation. Director 4pp 25925 285 24x Fichs 50-373, 84/07/25, 8408060143
- B4DB060165 Responds to Generic Ltr B3-10C re resolution of NUREG-0737, Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps "Facilities bound by results of Westinghouse Dumers Group manual pump trip justification rept SCHMIDT.H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) CL-83-5CC B407/27 Y (QUINGBLOOD.B ) Licensing Branch 1 1p 25932 197 24X Fiche 30-445.84/07/27,8408060165
- B408060190 Forwards IE Insp Rept 50-213/84-06 on 840509-11 No violations noted Items of concern noted in App A MARTIN.T T Division of Engineering & Technical Programs 84/07/09 CDUNSIL.R & Connecticut Yanke Atomic Power Co
- --8408060208 JE Insp Rept 50-213/84-06 on 840509-11 No violations noted Major areas inspected status of previously identified inspitems & IE Insp Procedures 82206,82207 & 82208 SMITH, R H . CROCKEN, H W Region 1: Office of Director 84/06/26 5pp 25935 194 24X Fiche 50-213:84/07/09.8408060190
- 8408060257 Forwards marked-up Tech Specs, based on Rev 4 to NUREG-0452, "STS for Westinghouse Pressurized Reactors " Offsite dose calculation manual will be submitted by 840815 Future eubmittals will address listed subjs CUTTER. A B Carolina Power & Light Co NLS-84-338 84/07/30 DENTON. H R Office of Nuclear Reactor Regulation, Director 634pp 25924 001 24% Fiche 50-400.84/07/30,8408060257
- 8408060295 Forwards J Buckley 840705 memo re typographical error in App V,Vol 2 of NUREG-0960 HRIGHT.R J Repository Projects Branch (Post 931001) 00916 84/07/23 (DLSON,O L Energy, Dept of 1p 25950 349
- 8408060386 NUREO/CR-3896
  SIMULATION EXPERIMENTS COMPARING ALTERNATIVE PROCESS
  FORMULATIONS USING A FACTORIAL DESIGN
  KALUZNY, S P , BHARTZMAN, O L. Washington, Univ of, Seattle, WA FI
  B-7018 84/07/31 Division of Health, Siting & Waste Management
  29pp available at NRC \$3 50 25937 282
- 8408040413 NUREG-0480 805
  TMI-1 RESTART An Evaluation Of The Licensee's Management
  Integrity As It Affects Restart Of Three Mile Island Unit i
  Docket 30-289
  \* Division of Licensing 84/07/31 179pp Available at NRC
  \$6 00 25937 102 24% Fichs 50-289.84/07/31,8408060413
- 8408070007 NUREQ/CR-2000 VO3 N6
  LICENSEE EVENT REPORT (LER) COMPILATION For Month of June
  1984

  \* Oak Ridge National Laboratory FIN A-9135 ORNL/NSIC-200
  84/07/31 Director's Defice 87pp 25955 [12]
- ## B408070009 NUREG-0954 S03

  ## BAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CATAMBA NUCLEAR STATION.UNITS 1 AND 2 DOCKET Nos 50-413 And 50-414 (Duke Power Company, et al)

  ## Division of Licensing 84/07/31 140pp Available at NRC \$5 50 25954 334 24% Fichs 50-413.84/07/31,8408070009
- B408070014 NUREO/CR-3834

  ON THE THRESHOLD SULFUR AND LITHIUM TO SULFUR RATIO IN STRESS CORROSION CRACKING OF SENSITIZED ALLOY 600 IN BORATED THIOSULFATE SOLUTION
  BANDY, R. KELLY, K. Brookhaven National Laboratory FIN A-3380 BNL/NUREG-51785 84/07/31 Division of Engineering 35pp Available at NRC \$3.75 25954 296
- 8408070015 Advises that 800930 description of proposed mods to ensure containment isolation single failure proof during purging satisfies requirements of Item II E 4 1 of NUREC-0737, based on completion of mods by 850701 VASSALLO, D B Operating Reactors Branch 2 84/07/26 BAYNE, J P Power Authority of the State of New York 3pp 25956 204 24X Fiche 50-333,64/07/26,8408070015
- 3408070037 Forwards response to Procedures & Sys Review Branch queries re emergency procedures & selection of containment vent pressure
  KEMPER.J S Philadelphia Electric Co 84/08/02 SCHWENGER.A
  Licensing Branch 2 opp 25949 329 24X Fiche 50-352,84/08/02.
  8408070037

- 8408070045 Forwards corrected page to 840612 confirmatory order, confirming Dec 1985 schedule for implementation of Suppl 1 to NUREG-0737 & Generic Ltr 82-33 re completion of structural mods to technical support ctr W/o encl VAROA.S A Operating Reactors Branch I GL-82-33 84/07/26 UDERITZ RA Public Service Electric 5 (3s Co of New Jersey 3pp 25955 319 24% Fiche 50-272,84/07/26.8408070065
- 8408070974 Advises of completion of review of AEOD/C403, "Case Study Rept for EI Hatch.Unit 2 Plant Sys Interaction Event on B20825" Case study recommends event be considered in developing final positions relative to NUREG-0803 DENTON.H R Office of Nuclear Reactor Regulation. Director B4/07/30 HELTEMES.C J Director's Office 2pp 25955 272 24X Fichs 50-364.84/07/30.8408070076
- --B406010162 Forwards case study rept of 820B25 plant sys interaction event Comments requested W/o encl
  HELTEMES, C. J. Director's Office B4/05/1B DENTON, H.R. Office of Nuclear Reactor Regulation. Director DEYOUNG, R.C. Director's Office. Office of Inspection and Enforcement 2pp 25955 273
  24X Fiche 50-366,84/07/30,8408070076
- 8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Buppi 1 to NUREG-0933, "Prioritization of Generic Safety Issues "Byc list encl EISENNUT.D © Division of Licensing 84/08/06 Consolidated Edison Co of Neu York, Inc. 18pp 26129 238 24% Fiche 50-000.84/08/06.8408070110
- 8408070114 Provides schedule info re NUREG-0737. Suppl 1 on emergency response commitment & clarifies schedular error in 840612 confirmatory order Amend to order prior to Sept 1985 suggested O'TOOLE, J D Consolidated Edison Co of New York, Inc GL-82-33 84/07/31 DENTON. H R Office of Nuclear Reactor Regulation, Director 2pp 28950 034 24X Fiche 50-247.84/07/31,8408070114
- 8408070142 Forwards request for addl info to continue review of 831028 submittal re safety parameter display sys safety analysis, per Suppl 1 to NUREO-0737 Response requested within 40 days MILLER, J R Operating Reactors Branch 3 84/07/24 JONES,W C Dmaha Public Pouer District 4pp 25957 134 24X Fiche 50-285,84/07/24,8408070142
- 8408070230 Forwards revised procedures generation package.per 840507 & 30 requests Submittal completes requirements of NUREO-0737. Suppl 1 re upgrade of emergency operating procedures COOK.K W Louisiana Power & Light Co N3P84-2062 84/07/31 KNIOHTON.G W Licensing Branch 3 2pp 25748 228 24X Fiche 50-382.84/07/31.8408070230
- 8408070271 Responds to 840604 request for NRC concurrence in plans to train & qualify six senior control room operators as shift technical advisors Personnel entering program must be degreed or equivalent per NUREG-0737, Item 1 A 1 1 MILLER, J R Operating Reactors Branch 3 84/07/26 LUNDVALL, A E Baltimore Gas & Electric Co 3pp 25956 261 24X Fiche 30-317,84/07/26,8408070271
- B40B070298 Informs that requested info re detailed control room design review provided in licensee B40409.0528 & 0216 submittals, per Suppl 1 to NUREG-0737 Task analyses for inadequate core coaling & ATWB event conducted during control room review TUCKER.H B Duke Power Co GL-83-23 84/07/27 DENTON.H R Office of Nuclear Reactor Regulation. Director ADENSAM,E G Licensing Branch 4 2pp 25947 295 24X Fiche 50-369.84/07/27.8408070298
- 8408070343 Forwards plant-specific technical guidelines, required by Suppl 1 to NUREC-0737, to aid NRC in completing review of emergency procedures generation package, in response to 840614 request LUNDVALL.A E Baltimore Gas & Electric Co 84/08/03 MILLER, J R Operating Reactors Branch 3 App 25944 134 24X Fische 50-317.84/08/03.8408070343
- B40B070362 Responds to NRC review of util conformance to NUREO-0737, Buppl 1.SER Outstanding Issue 19 NRC concerns re sysfunction, task analysis & control room inventory addressed Emergency response procedure program encl
  DEVINCENTIS, J Yankee Atomic Electric Co SBW-701 84/07/30 KNIGHTON, 6 W Licensing Branch 3 202pp 25944 284 244 Fiche 50-443,84/07/30.8408070362
- 8408070393 Submits info on schedule for implementing upgraded emergency operating procedures per Suppl 1 to NUREG-0737 Schedule outline prepared to perform listed actions Upgraded procedures will be implemented prior to Cycle 19 operation KAY, J A Yankee Atomic Electric Co FYR 84-82 84/07/27 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 25745 246 24X Fiche 50-029.84/07/27.8408070393

6400

25979 344

ORNL-6006

---8408080449 Safety evaluation supporting continued implementation o∉ safety parameter display sys.per Suppl 1 to NUREG-0737 + NRC - No Detailed Affiliation Given 84/07/27 Bpp 25977 156 24X Fiche 50-312,84/07/27.8408080445

```
8408070376 Forwards comments on NUREG-1055. 'Improving Quality & QA in
Design & Const of Nuclear Power Plants " All future CP
applicants should not be required to contract for third
                                                                                                                                                                                                                      -8409090303 Speech entitled "Disciplined Approach for Introducing
Certainty & Inproving Quality in Nuclear Pawer Plant Const."
presented at 840320 reeting of AIF & ANEC boards
SIERN.T Atomic Industrial Forum 84/03/20 4pp 25964 317
       applications and the second sec
                                                                                                                                                                                                                    8408090355 NUREC/CR-3744 VOI
                                                                                                                                                                                                                         OBGBOOSS NUMEC/CR-3744 VOI
HEAVY-SECTION STEEL TECHNOLOGN PROGRAM SEMIANNUAL PROGRESS
REPORT FOR OCTOBER 1983 - MARCH 1984
PUGHLC E Dat Ridge National Laboratory FIN 8-0119
ORNL/TM-9154/VI 84/07/31 Division of Engineering Technology
200pp 25979 144
  8408070404 Forwards supplemental info re qualification of safety relief valves (SRV). Seitz solenoid valves Interim operation justified until SRV solenoid valves fully qualified, per NURSE-0588 b 10CFR30 49
DALE, L F Massissippi Power & Light Co AECM-84/0394 84/08/05
DENTON HR Qffice of Nuclear Reactor Regulation, Director 5pp 25742 177 24X Fichs 50-416,84/08/05,8408070404
                                                                                                                                                                                                                    8408080357 NUREG/CR-3679
                                                                                                                                                                                                                         CALIBRATION AND QUALIFICATION OF THE LOS ALAMOS FAILURE
                                                                                                                                                                                                                         MODEL (LAFA)

BAARS: R E Los Alamos Scientific Laboratory FIN A-7015

LA-10041-MS 84/07/31 Division of Accident Evaluation
 8408070421 Responds to manual reactor coolant pump trip issue Upgraded energency operating plocedures & integrated operator training being implemented, per Suppl 1 to NURE9-0737 & Generic Etr 83-10D 0/10DLE, J D Consolidated Edison Co of New York, Inc GL-83-10D 84/08/01 EISENHUT, D 9 Division of Licensing 2pp 25942 026 24X Fiche 50-247,84/08/01,8408070421
                                                                                                                                                                                                                          25980 329
                                                                                                                                                                                                                   8408080359 NUREG/CR-2643
HETEROGENEOUS DISTANTIVE DEGRADATION IN IRRADIATED
                                                                                                                                                                                                                          POLYMERS
                                                                                                                                                                                                                         CLOUGHR L , OILLER, K T , QUINTANA, C A Sandia Laboratories
A-1051 SAND83-2493 84/07/31 Division of Engineering
Technology 43pp 25978 153
 B40B070431 Application for amend to License DPR-20. adding Section 3 0 limiting conditions for operation applicability in response to B31031 radiological effluent Tech Specs transmitting Draft 7 of Rev 3 to NUREO-0472 VANOEWALLE D J Consumers Power Co B4/07/31 CRUTCHFIELD, D Operating Reactors Branch 5 10pp 25939 221 24Y Fiche 50-255.84/07/31.8408070431
                                                                                                                                                                                                                    8408080363 NUREG-0748 VO4 NO6
OPERATING REACTORS LICEPBING ACTIONS SUMMARY Data As Of June
30,1984
                                                                                                                                                                                                                         * Office of Resource Management, Director 84/07/31 400pp 25981 129
 8408070435 Forwards Rev 3 to milestone commitments on Suppl 1 to NURE9-0737 & "PSAR, Safety Parameter Display Sys." per 830713 & 16 submittals
                                                                                                                                                                                                                   8408080347 NUREQ/CR-3777 CAPAGILITIES AND DIAGNOSTICS OF THE BANDIA FELLETRON-RABTER
      JOHNBON. B D Consumers Power Co 84/07/31
Operating Reactors Branch 5 App 25942 36
Fiche 50-255.84/07/31.8408070435
                                                                                                   84/07/31 CRUTCHFIELD, D
25942 361 24X
                                                                                                                                                                                                                         BUCKALEW. H H , LOCKWOOD, G J , LUKER, S M Sandia Laboratories
A-1051 SAND84-0712 84/07/31 Division of Engineering
Tachnology 61pp 25978 090
 8408070440 Advises of plans to implement Option 4 of NUREC-0737. Item
II K 3 iB. "Mod of Automatic Depressurization Bys Logic."
per NRC approval Plans include installation of sys manual
inhibit switch
                                                                                                                                                                                                                    8408080370 NUREG-1075
                                                                                                                                                                                                                         DECENTRALIZATION OF OPERATING REACTOR LICENSING REVIEWS NRR Pilot Program
                                   Detroit Edison Co EF2-66712 84/07/31 YDUNGBLOOD, B J
Branch 1 2pp 25942 357 24X Fiche 50-341,84/07/31,
       JENS.W H
                                                              2pp
      Licensing Branch 1
8408070440
                                                                                                                                                                                                                          HANNON, J. L.
                                                                                                                                                                                                                                                         Division of Licensing 84/07/31 26pp 25981 102
                                                                                                                                                                                                                   B40B0B0371 NURED/BR-0018 R02
THE HONOR LAW GRADUATE PROGRAM
* NRC - No Detailed Affiliation Given 84/09/01 12pp
 8408070489 Forwards hot license simulator reactor startup certification program.per NUREG-0094 Program limits student to instructor ratio to four-to-one conforming to INPO Guide 82-005 W/o
      enci
STEHART, W.L. Virginia Electric & Power Co. 365 84
PERSENSKY, J.J. NRC - No Detailed Affiliation Given
25940 347 24X Fiche 50-000,84/06/04,8408070489
                                                                                                                                                                                                                   8408080374 NUREO/CR-3804 VO1
PHYSICS OF REACTOR SAFETY Guarterly Report January - March
                                                                                                                                           84/06/06
                                                                                                                                                                                                                           Argonne National Laboratory FIN A-2015 ANL-84-35 84/07/31
Division of Accident Evaluation 1p 25979 356
 8408070515 Forwards "NUREO-O612, Control of Heavy Loads," final rept
Subnittal contains evaluation results & resolutions of open
items since 840326 submittal
KOBER:R W Rochester Oss & Electric Corp 84/07/31, PAULSON, W.
Operating Reactors Branch 5 ip 25941 172 24X
Fiche 50-244.84/07/31,8408070515
                                                                                                                                                                                                                    8408080407 NUREO/CR-3678
                                                                                                                           84/07/31, PAULSON # A
                                                                                                                                                                                                                         ESTIMATION METHODS FOR PROCESS HOLDUP OF SPECIAL NUCLEAR MATERIALS
                                                                                                                                                                                                                         MATEKINLS
FILLAY.K S., PICARD.R R., MARSHALL.R S. Los A:
Laboratory FIN A-7226 LA-1003B 84/07/31
Facility Operations 121pp 25980 028
                                                                                                                                                                                                                                                                                                                               Los Alamos Scientific
 --8408070516 "NUREG-0612, Control of Heavy Loads," final rept
* Rochester Cas & Electric Corp 84/08/31 12pp 25941 173
24X Fiche 50-244,84/07/31,8408070515
                                                                                                                                                                                                                    B408080415 NUREO/CR-3618
                                                                                                                                                                                                                         CCA-P, A DETERMINISTIC AND PROBABILISTIC FRACTURE-MECHANICS
                                                                                                                                                                                                                        CODE FOR APPLICATION TO PRESSURE VESSELS
CHEVERTON.R 9. BALL.D 0 Oak Ridge National Laboratory FIN
B-0119 CRNL-5991 84/07/31 Division of Engineering Technology
105pp 25977 338
B408080178 Informs of review of responses to Generic Ltr 83-02 re Tech Specs for NUREO-0737 items which were to be implemented by Bi1231 Tech Specs for Item II £ 4 2 7 have not been provided Response requested within 30 days STOLZ.JF Operating Reactors Branch 4 0L-83-02 84/08/01 BECKHAM.JT Georgia Power Co 2pp 25978 342 24X Fiche 50-321,84/08/01,8408080178
                                                                                                                                                                                                                   8408080419 NUREO/CR-3671
ASSESSAN TO FRADIATION EFFECTS RELATING TO REACTOR PRESSURE
                                                                                                                                                                                                                         VESSEL CLADDING
                                                                                                                                                                                                                         vessel Clauding
CORWIN.W R Dak Ridge National Laboratory FIN B-0119 DRNL-6047
84/07/31 Division of Engineering Technology 70pp 25977 271
8408080232 Responds to 840513 request for info re analyses used in determining if setpoint logic changes needed to reduce water clearing thrust loads associated disecond safety relief valve actuations Analyses conducted per NUREG-0561 CUTIER: A B Carolina Power & Light Co NtS-84-309 84/08/01, VASSALCO. B Operating Reactors Branch 2 2pp 25966.300 2: Fiche 50-324.84/08/01. B408080252
                                                                                                                                                                                                                   B40B080422 NUREO/CR-3714
ON THE DEVELOPMENT OF ENVIRONMENTAL RADIATION STANDARDS FOR OECLOGIC DISPOSAL OF HIGH-LEVEL RADIOACTIVE WASTES
NUCHER, D C Oak Ridge National Laboratory FIN A-9041 ()
B4/07/31 Division of Health, Siting & Waste Management
                                                                                                                                                                                                                         25977 192
8408080235 Forwards comments on NUREC-1035 re improving quality & GA in const of commercial nuclear power plants Supports Ford amend as objective & useful GER/IDSIMO.R R American Society of Guality Control 84/08/01 Docketing & Services Branch 7pp 25765 307
                                                                                                                                                                                                                  8408080443 Forwards request for addl info re tafety parameter display sys (8PDB) Continued implementation of SPDB acceptable. Response requested within 60 days of itr receipt RIVENBARK.O Operating Reactors Branch 4 84/07/27 RDDRIGUEZ.R Sacramento Municipal Utility District 4pp 23977 152 24X Fiche 50-312.84/07/27.8408080445
```

Docketino

8408090277 Forwards comments on NUREO-1055 re improving quality & QA in design & const of nuclear power plants AEs & NRC should clearly define stable acceptance criteria before const started

\* American Society of Mechanical Engineers 84/07/30 & Services Dranch App 25764 31:

OBCSD472 NURED/CR-3840
COST ANALYSIS FOR POTENTIAL MODIFICATIONS TO ENHANCE THE
ABILITY OF A NUCLEAR PLANT TO ENDURE STATION BLACKOUT
CLARK, R A , THOMAS, W R Science & Engineering Associates, Inc
RIGRION, J J MATHTECH, Inc FIN R-8838 84/07/31 Division of
Budget & Analysis 167pp Available at NRC \$5 50 25980 160

108070099 Summarizes appraisal procedure re emergency response facilities: per NUREG-0737. Suppl 1 PAULSON. W.A. Operating Reactors Branch 5 84/07/31 Operating Reactors Branch 3 3pp 25991 232

408090149 Providet upgraded in-core thermocouple implementation schedule, per 840221 commitment Util proposes to complete Reg Ouide 1 97 (ref NUREG-0737, Item II F 2) mads prior to or during 1986 refueling outages
STEWART, W L Virginia Electric & Power Co 447 84/08/03 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D Q Division of Licensing 2pp 25973 122 24X Fiche 50-338, 84/08/03, 8408090149

IA08090272 NUREO/CR-3795
CLOBCOUT OF 1E BULLETIN 92-04 DEFICIENCIES IN PRIMARY
CONTAINMENT ELECTRICAL PENETRATION ASSEMBLIES
FOLEY,W J. HENNICK, A Parameter, Inc FIN B-8714 IEB-82-04
84/07/31 Division of Emergency Preparedness & Engineering
Response (Post 830103) 53pp Available at NRC \$4,50 25983 001

1408070282 Summary of 840520 meeting w/util & Bechtel in Bethesda,MD re implementation of Reg Ouids 1 97 requirements by licensee Util will provide supplemental rept to 850715 submission to address separation problems Viewgraphs encl MINER.8 Operating Reactors Branch 4 84/08/01 Operating Reactors Branch 4 84/08/01 Operating Reactors Branch 4 12pp 25972 001 24X Fiche 50-312,84/08/01.

B40B070311 Forwards application for amend to License DPR-34, revising Tech Specs to comply w/NUREO-0737. Items II B 3.II F i 3 & III B 3 4 LEE, D R Public Service Co of Colorado P-84242 84/07/31 UOHNSON,E H Region 4, Office of Director 3pp 25794 114 24X Fiche 30-267, 84/07/31,840807031i

--8408090316 Application for amend to License DPR-34, revising Tech Specs to comply w/NURE0-0737, Items Il B 3, II F 1 3 & II D 3 4 Fee enci LEE, O R Public Bervice Co of Culorado 84/07/31 App 25994 117 24X Fiche 50-267,84/07/31,8408090311

-8408090327 Proposed revs to Tech Spec limiting conditions re control room temp.area radiation monitors.sejamic instrumentation, primary cooland, maisture instrumentation, suitchgear room temp.emargency ventilation sys & fire suppression sys. # Public Service Co. of Colorado 84/07/31 Pipp 25994 123 24X Fiche 30-227,84/07/31,8408090311

8408070530 Forwards request for add1 info for review of 840214 submittal re control of heavy loads Tech Spec change Response requested within 45 days of ltr receipt VARGA B A Operating Reactors Branch 1 84/08/01 0'TOOLE.J Consolidated Edison Co of New York. Inc 4pp 25783 332 24 Fiche 50-247.84/08/01.8408070530

|408100002 Forwards emergency operating procedure generation package in response to requirements of Generic Ltr 82-33, "Suppl 1 to NUREG-0737 - Requirements for Emergency Response Capability," Section / DIXON.O W South Carolina Electric & Oas Co QL-82-33 B4/07/30 DENTON.H R 09:12-36 Nuclear Reactor Regulation, Director 11pp. 25989, 310 24X Fiche 30-395, 84/07/30, 8408100002

--8408100012 Rev O to Station Administrative Procedure SAP-207,
"Development of Emergency Operating Procedure"
4 South Carolina Electric & Qas Co OL-82-33 84/04/02 77pp
25989 321 24X Fiche 50-395,84/07/30,8408100002

B40B100074 Forwards responses to NRC 840508 request for add1 info re detailed control room design review (DCRDR) Encls include functions of DCRDR teams, control room instrumentation & smeryancy response capability integration plan ALEXICH.M P Indiana & Michigan Electric Co AEP NRC 0773H 84/08/04 DETON.H R Office of Nuclear Reactor Regulation, Director 26pp 25988 204 24X Fiche 50-315,84/08/04,8408100094

---B405010079 Bummarizes 840329 meeting w/Westinghouse Owners Oroup re task analysis requirements of Buppl 1 to NUREO-0737 (Oeneric Ltr 88-33) CLAYTON, N 3 Procedures & Systems Review Branch GL-82-33 84/04/05 ZIEMANN, D L. Procedures & Systems Review Branch 17pl 25988, 230 24% Fiche: 50-315, 84/08/06, 8408100094. 840B100103 Forwards application for amend to License DPR-43, per Generic Ltr 83-19 Fee encl MANDAN.C V Niegara Mohawk Power Corp GL-83-19 84/08/07 VASSALLO.D B Operating Reactors Branch 2 1p 25990 355 24X Fiche 50-220.84/08/07.8408100103

--8408100111 Application for amend to License DPR-63, changing Tech Specs by deleting "all" from review & audit section, to be consistent w/Rev 2 to BVR Tech Specs (NUREG-0123) MANGAN, C V Niagara Tohawk Power Corp 84/08/07 5pp 25970 356 24X Firsh 50-220,84/08/07.8408100103

8408100147 NUREO/CR-3820 VO1
THERMAL/HYDRAULIC ANALYSIS RESEARCH PROGRAM Quarterly
Report.January-March 1984
THOMPSON.5 L Sandia Laboratories FIN A-1205 SAND84-1025/1
84/07/31 Division of Accident Evaluation 62pp 25996 280

8408100149 NUREG-0936 VO3 NO2 NRC REGULATORY AGENDA Guarterly Report, April-June 1984 \* Division of Rules and Records 84/07/31 201pp 25998 112

8408100151 NUREG/CR-3689 VO1
MATERIAL SCIENCE AND TECHNOLOGY DIVISION LIGHT-WATERREACTOR SAFETY RESEARCH PROGRAM Guarterly Progress Report,
January-March 1983
SHACK, U.J. Argonne National Laboratory FIN A-2016 ANL-83-85
84/07/31 Office of Nuclear Regulatory Research, Director 1699

8408100152 NUREC/CR-3734

LIGHT WATER REACTOR BAFETY RESEARCH PROGRAM Semiannual
Report: Detober 1982 - Harch 1983
BERMAN,M Sandia Laboratories FIN A-1019 SAND84-0688 84/07/3
Division of Accident Evaluation 276pp 25996 001

840B100153 NUREG/CR-9742
BUCKLING OF STEEL CONTAINMENT SHELLS UNDER TIME-DEPENDENT
LOADINO
BABCOCK, C D , BAKER, W E , FLY, J Los Alamos Scientific Laboratory
FIN A-7221 LA-10087-MB 84/07/31 Division of Engineering
Tachnology 38pp 25997 268

840B100155 NUREO/CR-3273
COMBUSTION OF HYDROGEN AIR MIXTURES IN THE VGES
CYLINDRICAL TANK
BENEDICK. H B , CUMMINOS, J C , PRABSINOS, P Q Sandia Laboratories
FIN A-1246 BANDB3-1022 84/07/31 Division of Accident
Evaluation 165pp 25997 309

8408130001 NUREG/CR-3492 V04
HIGH-TEMPERATURE 0AS-COOLED REACTOR SAFETY STUDIES FOR THE
DIVISION OF ACCIDENT EVALUATION QUARTERLY PROGRESS REPORT,
October-December 1983
BALL-R J , CLEVELAND, J C , HARRINOTON, R M Oak Ridge National
Laboratory FIN 8-0122 ORNL/TM-8921/V4 84/07/31 Division of
Accident Evaluation 27pp 26011 225

8408130002 NUREG-0675 824

SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 & 2 Docket Nos 50-275 & 50-323 (Pacific Oas & Electric Company) \* Division of Licensing 84/07/31 16pg 26038 293 24X Fiche 50-275,84/07/31 8408130002

8408130006 NUREC/CR-3369
AN UNCERTAINTY STUDY OF PWR STEAM EXPLOSIONS
BERMAN, M., SWENSON, D.V., WICKETT, A.J. Sandia Laboratories FIN
A-1030 SAND83-1438 84/07/31 Division of Accident Evaluation
91pp 26040 238

8408130007 NUREO/CR-3139
BCENARIOS AND ANALYTICAL METHODS FOR UF6 RELEASES AT
NRC-LICENSED FUEL CYCLE FACILITIES
81MAN-TOV.M , DYRSTRA, J , HOLT, D D Oak Ridge National Laboratory
FIN B-0495 ORNL/ENG/TM-25 84/07/31 Division of Risk Analysis
& Operations (post 840429) 97pp 26038 203

8408130009 NUREC/CR-3346
BIDASBAY DATA AND A REYENTION-EXCRETION MODEL FOR SYSTEMIC
PLUTONIUM
LEGGETT, R W Dak Ridge National Laboratory FIN B-0480-2
DRNL/TH-8795 84/07/31, Division of Facility Operations 96pg
26038.108

8408130011 NUREO-1072
TECHNICAL SPECIFICATIONS FOR CATAMBA NUCLEAR STATION, Unit 1
Docket No 50-413
ANDERSON F D Division of Licensing 84/07/31 525pp Available
at NRC \$10 00 26039 001 24% Fiche 50-413,84/07/31,8408130011

B40B130041 NUREG/CR-3599
SOURCES OF UNCERTAINTY IN THE CALCULATIONS OF LOADS ON SUPPORTS OF PIPING SYSTEMS
\* Dak Ridge National Laboratory RDDABAUGH, E C E C Rodabaugh Associates, Inc FIN B 0474 84/07/31 Division of Engineering Technology 73pp 26040 166

B40B130043 NUREC/CR-3751

EFFECTS OF ROCK RIPRAP DESIGN PARAMETERS ON FLOOD PROTECTION

COSTS FOR URANIUM TAILINOS IMPOUNDMENTS

ECKER.R M Battelle Memorial Institute, Pacific Northwest

Laboratories FIN B-2370 PNL-306B B4/07/31 Division of

Radiation Programs & Earth Sciences (post 840429) 98pp Available

at NRC \$4.75 24011 254

840B130049 NUREG-0540 VO5 NO5 TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE May 1-31, 1984 \* Division of Technical Information & Document Control 84/07/31

8408130129 Responds to 840602 SER re safety parameter display sys, per Suppi 1 to NUREC-0737 Secondary displays may be called up temporarily, but display always returns to primary display automatically CURTIE.N W Pennsylvania Power & Light Co PLA-2258 84/08/08 SCHNENCER.A Licensing Branch 2 9pp 26007 335 24X Fiche 50-387,84/08/08.8408130129

8408130169 Forwards description & justification for proposed piping seismic analysis changes, adopting damping values & spectra shifting methods for piping sys, per WRC recommendations, for review/approval

TUCKER, H B Duke Power Co 84/08/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E 0 Licensing Branch 4 3pp 26010 027 24% Fiche 50-369,84/08/01,8408130169

8408130186 NUREO-0040 VOB NO2 LICENSEE CONTRACTOR AND VENDOR INSPECTION STATUS REPORT Quarterly Report.April-June 1984 (White Book) # Division of QA, Safeguards & Inspection Programs (Post 830103) 84/07/31 433pp 26037 001

8408130191 Informs of error in 840627 correspondence re NUREQ-0737, Item I C 1. Table 2 Phase 1 emergency operating procedures (EOPs) not in place in Nov 1983 EOPs will be implemented prior to restart from Cycle 10 refueling outage FIEDLER, P B General Public Utilities - OPU Service Corp 84/08/06 CRUTCHFIELD, D Operating Reactors Branch 5 ip 26006 362 24% Fiche 50-219,84/08/06,8408130191

8408130218 Forwards "PRA of Offsite Releases Initiated by Toxic Chemical Release," per NUREO-0737. Item III D 3 4
Transportation of offsite chemicals in vicinity of facility will not pose undue risk to control room operator HUKILL.H D General Public Utilities - GPU Service Corp 5211-84-2197 84/08/09 STGLZ.J F Operating Reactors Branch 4
2pp 26008 065 24X Fichs 50-289.84/08/08.8408130218

--8408130225 PLG-0370
"PRA of Offsite Releases Initiated by Toxic Chemical
Release," final rept
FENSTERMACHER, HUBBARD, F.R., CALABRESE, R.V. Pickerd, Lowe 8
Garrick, Inc. PLO-0370 84/07/30 118pp 26008 067 24%
Fiche 50-289,84/08/08,8408130218

840B130233 Forwards safety evaluation & technical evaluation rept re control of heavy loads, Phase 1 VARGA: B A Operating Reactors Branch 1. 84/07/25 MCDONALD, R P, Alabama Power Co 2pp 26060 027 24X Fiche 50-348, 84/07/25, 840B130233

--8408130258 SER re control of heavy loads, Phase 1 Phase 1 acceptable. 4 NRC - No Detailed Affiliation Given 84/07/25 2pp 26060 029 24X Fiche 50-348.84/07/25.8408130233

8408130269 NUREG/CR-3053
CLOBEOUT OF IE BULLETIN 80-08 EXAMINATION OF CONTAINMENT
LINER PENETRATION WELDS
DEAN,R S , FOLEY, N J , HENNICK, A Parameter, Inc FIN 8-1013
IEB-80-08 84/07/31 Division of Emergency Preparedness &
Engineering Response (Post 830103) Sipp Available at NRC \$3.75

8408130267 Forwards request for addl info re Suppl 1 to NUREG-0737 concerning safety parameter display sys. Project manager should be prepared to address info request within 5 days of ltr receipt YOUNGBLOOD, B J Licensing Branch 1 GL-82-33 B4/08/07 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 5pp 26040 345 24X Fiche 50-445, 84/08/07, 8408130267

840B130325 Submits schedule info on detailed control room design review summary rept.per Suppl 1 to NUREG-0737 Clarifies schedular error in 840612 confirmatory order Amend to order requested prior to Sept 1985
O'TDDLE.J D Consolidated Edison Co of New York, Inc OL-82-33
84/08/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26010 057 24X Fiche 50-247,84/08/06,8408130325

8408130349 Responds to 840702 request for add1 info on CEN-268 re resolution of NUREG-0737. Item II K 3 5, "Study Need for Automatic Trip of Reactor Coolant Pumps " Response will be discussed at 840920 meeting WELLS.R W C-E Operating Plants Owners Group WELLS.R W Northeast Utilities Service Co (subs of Northeast Utilities) RWW-84-60 84/08/07 MILLER.J R Operating Reactors Branch 3 2pp 24010 224

B40Bi30351 Forwards update to B30127 description of natural circulation test program & "Evaluation of Natural Circulation Cooldown Test Performed at San Onders Nuclear Generating Station" Confirmatory Item 7 in NuREG-0897, SSER 5 closed VAN BRUNT, E E Arizona Public Bervice Co ANPP-30141-EEVB B4/08/07 KNIGHTON, C Licensing Branch 3 23pp 26006 170 24X Fiche 30-528, B4/0B/07. 840Bi30351

8408130357 Forwards response to 840604 request for add1 info re NUREO-0737. Item II F 2 concerning inadequate core cooling instrumentation. KOBER.R W Rochester Gas & Electric Corp 84/08/07 PAULSON, W A Operating Reactors Branch 5 7pp 26010 060 24X Fiche 50-244. 84/08/07. 8408130357

8408130449 Forwards "Control of Heavy Loads (Phase II-NUREQ-0612) for Commanche Peak, Units 1 & 2," draft technical evaluation rept YOUNDBLOOD, B J Licensing Branch 1 84/07/26 SPENCE, H D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pg 26059 271 24X Fiche 50-445.84/07/26,8408130449

--8408130455 "Control of Heavy Loads (Phase II-NUREG-0612), Commanche Peak,Units 1 & 2." draft technical evaluation rept YEN.I C E0&G, Inc FIN A-6457 84/04/30 NRC - No Detailed Affiliation Given 40pp 26059 274 24X Fiche 50-445,84/07/26,

8408130530 Forwards Amend 73 to License NPF-3 & safety evaluation Amend revises Tech Specs to add new Sections 3 3 2 3 & 4 3 2 3 & Tables 3 3-15 & 4 3-15 to reflect final anticipatory reactor trip sys RIVENBARK.9 W Operating Reactors Branch 4 CL-82-16 84/07/25 CROUSE, P Folsoo Edison Co 3pp 26038 341 24x Fiche 50-346,84/07/25,8408130530

--8408130545 Safety evaluation supporting Amend 73 to License NPF-3 Evaluation of licensee 821115 response to Generic Ltr 82-16 also included \* Office of Nuclear Reactor Regulation, Director QL-82-16 84/07/25 8pp 26038 355 24% Fiche 50-346,84/07/25,8408130530

840B130595 Notifies that any permanent changes to new fuel container
lifting rig will be made per ANSI N14.6-1978 requirements &
NUREO-0612
STEMART W L Virginia Electric & Power Co 364 B4/08/03
DENTON, H R Office of Nuclear Reactor Regulation, Director
EISENHUT, D G Division of Licensing 1p 26031 359 24X
Fiche 30-280.84/08/03.8408130585

840Bi40029 Forwards corrected Page 2 to attachment to 840614 order confirming licensee connitments to implement post-TMI related items in Buppl I to NUREO-0737. "Requirements for Emergency Response Capability" (Generic Ltr 82-33) MILLER, J R Operating Reactors Branch 3 OL-82-33 84/07/24 STEMART, N L Virginia Electric & Power Co 3pp 26061 259 24X Fiche 80-338,84/07/24,8408140029

--8408140033 Correction to 840614 order confirming licenses commitments to Suppl 1 to NUREO-0737 Completion data for technical support ctr to be fully functional changed to 850731 HILLER.J R Operating Reactors Branch 3 84/07/24 Virginia Electric & Power Co 1p 26061 263 24% Fiche 50-338,84/07/24,8408140029

840814008B Forwards add1 info on draft BER.Outstanding Issue 56 on TMI/ Item II K 3 12. Issue 58 re undetected failure of on-line ESF relays & Issue 77 on control sys failures caused by maifunction of instrument line WOLEVER.E J Dequesne Light Co 2NRC-4-119 84/08/09 KNIGHTON.G W Licensing Branch 3 5pp. 26045 334 24X Fiche 50-412.84/08/09,8408140088

- B40B140239 Application for amend to License DPR-35 changing Tech Specs to provide redundant temp monitoring sys for suppression pool 2 responding to partions of TMI action plan requirements of NUREO-0737

  MARRINCTON.U D Boston Edison Co BECO 84-128 B4/08/09 VASSALLO.D B Operating Reactors Branch 2 1p 26055 316 24X

  Fiche 50-293.84/08/09.8408140239
- --8408140245 Proposed Tech Spec changes providing redundant temp nonitoring sys for suppression pool 2 responding to portions of THI action plan requirements of NUREO-0737 \* Boston Edison Co 84/08/09 13pp 26055 317 24X Fiche 50-293,84/08/09,8408140239
- 840B140250 Responds to NRC 840613 request for info re analysis & methodology for Mark I long-term program for safety relief valve actuation not in conformance w/NUREG-0661 Review of procedures reveals complete conformance HARRINOTON.4 D Boston Edison Co BECO 84-127 84/08/07 VASBALLO.D B Operating Reactors Branch 2 1p 26053 358 24% Fiche 50-293,84/08/09.8408140250
- B40Bi40295 Provides editorial changes to 840731 cover ltr & Attachment i re Suppl 1 to NUREG-0737.safety parameter display sys PSAR & implementation schedule.per Reg Guide 1 97 variables JOHNSON.B D Consumers Power Co 84/08/09 CRUTCHFIELD.D Operating Reactors Branch 5 opp 26043 144 24X Fiche 50-255.84/08/09.8408140275
- 840B140372 Forwards proposed rov to "Requalification Program for Licensed Operators. Senior Operators & Senior Operators (Limited)," in response to NUREO-0737. Item I A 3 I MARSHALL.J G Commonwealth Edison Co 9034N 84/08/07 DENTON HR Office of Nuclear Reactor Regulation. Director 2pp 26051 240 24X Fiche 50-000.84/08/07.8408140372
- 8408140408 Forwards request for add1 info to complete evaluation of util 830311 response to Generic Ltr 82-28 re inadequate core cooling instrument sys. NUREG-0737. Item II F 2 CRUTCHFIELD, D Assistant Director for Bafety Assessment L905-84-08-008 84/08/05 CDUNSIL.W O Connecticut Yanker Atomic Power Co App 26030 347 24% Fiche 50-213,84/08/06,8408140408
- B40B140411 Forwards corrected Tech Spec Section 6 16. "Post-Accident Bampling Programs" & Table 4 1-1 re instrument surveillance requirements, in response to NRC request for changes to B40604 Tech Spec Change Request i15
  HUKILL.H D Oeneral Public Utilities GPU Service Corp 5211-B4-219B & B40B/0B STGLZ.J F Gperating Reactors Branch 4 ip 26048 359 24X Fiche 50-289, 84/0B/08,8408140411
- ---8408140415 Corrected Tech Spec Change Request 115, adding phrases to clarify Tech Spec Section 6 16. "Post-Accident Sampling Programs." (NMFE0-0737.51 B 3 & 11 F 1 2) & Table 4 1-1 reinstrument surveillance requirements

  \* Oeneral Public Utilities 0-0V Service Corp 84/08/08 2pp 26048 360 24X Fiche 50-289,84/08/08,8408140411
- 840B140417 Comments on NUREG-1055 re Ford Amend Study on improving quality & GA in design & const of nuclear power plants Rept should be sent to intervenors who participated as full parties to CP & OL proceedings

  BELL.# Nuclear Information & Resource Service 84/06/27

  ANKRUM.9 T QA Branch 1p 26050 333
- 408140431 Responds to NRC B40604 review of detailed control room design review program plan, per Suppl 1 to NUREG-0737 Summary rept will be submitted by Dec 1984
  PILANT, J M Nebraska Public Power District NLS8400226 84/08/07 VASSALLO, D B Operating Reactors Branch 2 3pp 26050 337 24X
  Fiche 50-298,84/08/09,8408140431
- 840B140358 Forwards Amend 7 to License R-70.SER.EIA & notice of issuance & availability Amend renews license until June 29.2000
  EISENHUT.D G Division of Licensing 84/08/07 XERR,F Maryland, Univ of College Park, MD 3pp 26065 236 24X
  Fiche 50-166.84/08/07.840B140558
- \_408190087 Responds to NRC 820807 ltr re guidelines developed to facilitate revieu following implementation of NUREO-0737. Item II B 3 re post-accident sampling sys Info submitted to assist in SER preparation HARRINOTON B Boston Edison Co BECO 84-122 84/08/09 VASSALLO, B B Operating Reactors Brench 2 9pp 26066 236 24X Fiche-50-293.84/08/09.8408150087
- 8408150137 Forwards NRC comments on design evaluation rept program plan elements for detailed control room design review.including info re control room inventory & selection of design improvements Response by 850101 requested KNIOHTUN.9 W Licensing Branch 3 84/08/01 VTLEY, E E Carolina Power & Light Cg 11pp 26104 203 24X Fiche 50-400, 84/08/01, 9408150137

- B40B150212 Requests exemption from NUREG-0737. Table II f 1-2, design basis shielding envelope criteria of 100 uCi/cc of gaseous radioiodine / particulates deposited on sampling media LINDER. F Dairyland Power Cooperative LAC-10104 B4/0B/01 CRUTCHFIELD. D Operating Reacture Branch 5 App 26066 241 24X Firms 50-409 B4/0B/01.840B150212
- 8408150223 Folwards responses to 840504 ltr re INEL rept on util conformance to Reg Guide i 97 requirements for emergency response capability & Suppl 1 to NUREG-0737 Changes to 830921 implementation pian listed LIDEN.C A Public Service Electric & Gas Co of New Jersey 84/08/09 vARQA.S A Operating Reactors Branch 1 9pp 26066 OBI 24X Fiche 50-272,84/08/09,8408150223
- 8408150269 Forwards "Evaluation of Detailed Control Room Design Review Summary Rept for Dyster Creek Nuclear Generating Station." technical evaluation rept, per Suppl 1 to NUREG-0727 SALP input also encl PAULSON, W.A. Operating Reactors Branch 5 LSD5-84-08-016 84/08/14 FIEDLER, P. & General Public Utilities OPU Bervice Corp 14pp 26067 066 24X Fiche 50-219,84/08/14,8408190269
- 8408130310 Forwards SER re TMI Items II F 1 i, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor" & II F 1 6, "Containment Mydrogen Monitor " Design acceptable VASSALLO.D B Operating Reactors Branch 2 84/07/30 UTLEY, E E Carolina Power & Light Co 12pp 26099 341 24X Piche 50-324,84/07/30,8408150310
- 8408150320 Forwards, for review & concurrence, NUREO/BR-0051. "Power Reactor Events, Jan-Fob 1984" Concurrence requested by 840713 HELTEMES, C. J. Director's Diffice 84/07/11 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 1p 24099 284
- 8408150380 Forwards IC Insp Rept 50-440/84-13 on 840709-12 No nancompliance nated PAPERIELLO,C J Region 3, Office of Director 84/07/27 EDELMAN,M R Cleveland Electric Illuminating Co 2pp 26078 002 24X Fiche 50-440,84/07/27,8408150380
- --8409150381 IE Insp Rept 50-440/84-13 on 840709-12 No violations or deviations noted Major areas inspected radiation protection program, including organization & staffing training & procedures & radiography incident on 840416
  MILLER, D. E., OREGER, L. R. Region 3, Office of Director 84/07/27 opp 240/8 004 24% Fiche 50-440,84/07/27,8408150380
- 8408150526 Forwards NUREG-1031. "SER to Operation of Millstone Nuclear Power Station, Unit 3 " YDUNGBLOOD, B J Licensing Branch 1 84/08/02 COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 454pp 26094
- B40B150544 Forwards IE Insp Rept 50-263/84-14 on 840625-29 & notice of violation PAPERIELLO, C J Region 3, Office of Director 84/07/26 LARSON, C E Northern States Power Co 2pp 26079 222 24X Fiche 50-263, 84/07/26, 8408150544
- --840B150547 IE Insp Rept 50-263/B4-14 on B40625-29 Violation noted solid radwaste contained free standing liquid GRANT.W B , NICHOLSON,N A , GREGER,L R Region 3, Office of Director 84/07/26 9pp 26079 225 24X Fiche 50-263.B4/07/26, B40B150544
- 8408160921 Requests justification of emergency operating guidelines by ref to Oconee guideline approved by NRC Response by 840914 requested STOLZ.J F Operating Reactors Branch 4 84/08/08 CROUSE.R P Toledo Edison Co 2pp 26128 210 24x Fiche 50-346,84/08/08,3400140021
- 840Bi60035 Informs that util plans to prepare general safety evaluation to expand safe load path boundaries in reactor bldg Evaluation will be submitted for review by 841101 KANGA.B K General Public Utilities GPU Service Corp 4410-94-L-0131 84/08/10 SNYDER.B J TMI Program Office 2pp 26092 050 24X Fiche 50-320.84/08/10.8408160035
- 8408160039 Advises that upgraded in-core thermocouple sys schedule will be completed by 1986 refueling outage.per 840221 commitment & uili meet requirements of NUREO-0737.Item II F 2 STEMART.W L Virginia Electric & Power Co 448 84/08/01 DENTON.H R Office of Nuclear Reactor Regulation, Director EISENHUT.D & Division of Licensing 1p 26092 052 24X Fiche 50-280.84/08/01.8408160039

- 8408160046 Forwards request for add1 info re procedures generation package (PGP) Review or PGP conducted per Generic Ltr 82-33 (Suppl 1 to NUREO-0737) VASSALLO.D B Operating Reactors Branch 2 GL-82-33 84/07/27 UTLEY.E E Carolina Power & Light Co 9pp 26128 162 24X Fiche 50-324.84/07/27.8408160046
- 8408160263 Clarifies SNUPPS design & procedural controls for mitigation of postulated control room fires.per SSER 3 (NUREO-0830)
  Requests meeting u/NRC, per procedures for disposition of backfitting requirements implemented by IE & NRR
  PETRICK, N A Standardized Nuclear Unit Power Plant System SLNRC
  84-0106 84/08/10 DENTON, H R Dffice of Nuclear Reactor
  Regulation, Director 3pp 26085 313 24X Fiche 50-000, 84/08/10, 84/08/06.
- 8408160080 NUREO-0675 S25
  SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 AND 2 Docket Nos 50-275
  And 50-323 (Pacific Gas And Electric Company)
  # Division of Licensing 84/07/31 122pp Available at NRC \$5 50 26124 033 24X Fiche 50-275,84/07/31,8408160080
- 8408160092 Forwards safety parameter display sys (SPDS) preimplementation audit results Schedule for submittal of addl SPDS info due within 60 days of ltr receipt NUREG-0737. Suppl I guidelines require resolution VASSALLO, D B Operating Reactors Branch 2 84/08/03 PILANT, J M Nebraska Public Power District 12pp 26126 329 24X Fiche 50-278.84/08/03,8408160092
- 8408160102 Forwards IE Insp Repts 50-317/84-16 & 50-318/84-16 on 840604-08 % notice of violation MARTIN.T T Division of Engineering & Technical Programs 84/07/24 LUNDVALL.A E Baltimore Gas & Electric Co 2pp 26108 135 24X Fiche 50-317.84/07/24.8408160102
- --B40B160113 IE Insp Repts 50-317/B4-16 & 50-318/B4-16 on B40604-Q8 Violation noted failure to establish procedures for incomplete work followup on safety-related mod to auxiliary feedwater sys BLUMBERG. N , BETTENHAUBEN. L Region 1, Office of Director 50-318/B4-16 B4/07/12 12pp 26108 138 24% Fiche 50-317, 84/07/24, 8408160102
- B40B160125 NUREO/CR-3B70
  RADIATION DOSE EBTIMATES AND HAZARD EVALUATIONS FOR INHALED AIRBORNE RADIONUCLIDES Annual Progress Rept July 1982 June 1983
  MEMHINNEY, J A Inhalation Toxicology Research Institute FI A-1031 LMF-109 B4/07/31 38pp Available at NRC \$3 75 26122 313
- 8408160146 NUREO/CR-3735
  ACCIDENT-INDUCEO FLOW ANN MATERIAL TRANSPORT IN NUCLEAR
  FACILITIES--A LITERATURE REVIEW
  BOLSTAD.J W , GREGORY, W S , MAGTIN, R A Los Alamos Scientific
  Laboratory FIN A-7029 LA-100079-MS 84/07/31 45pp 26122 266
- B40Bi60i53 Forwards SEK on NUREO-0737. Item II K 3 22 re automatic switchover of RCIC sys suction Manual switchover of RCIC suction on low water level in condensate storage tank acceptable VABBALLO, D B Operating Reactors Branch 2 B4/07/27 PARRIS. H Q Tennessee Valley Authority 9pp 26126 154 24X Fiche 30-239.84/07/27.8408160153
- 8408160163 Forwards DES (NUREO-1085) & FR notice of availability W/o DES SCHWENCER, A Licensing Branch 2 84/08/09 HIRSCH, A Environmental Protection Agency 2pp 26124 355 24X Fiche 50-410,84/08/09,8408160163
- --8408160166 Notice of availability of DES (NUREG-1085) SCHWENCER, A Licensing Branch 2 84/08/09 2pp 26124 357 24X Fichs 30-410,84/08/09.8408160163
- 8408160167 Informs of review of 840615 ltr re auxiliary feedwater sys (AFW) (TMI Item II E i i) Requests Tech Spec for monthly surveillance testing of AFW sys pumps MILLER, J R Operating Reactors Branch 3 84/08/01 RANDAZZA, J B Maine Yankee Atomic Pawer Co 2pp 26124 350 24X Fiche 50-307,84/08/01,8408160167
- B40B16018B Forwards results of review of NJREG-0737. Item II B 3 open items re post-accident sampling sys Mods will be completed & sys operational by Sept 1984
  ALEXICH.M P Indiana & Michigan Electric Co AEP NRC 0678H
  B4/08/02 DERITON.H R Office of Nuclear Reactor Regulation,
  Director 4pp R6092 036 24X Fiche 50-315,84/08/02,840B1601BB

- 8408160191 NUREG-0020 VOB NO6 LICENSED OPERATING REACTORS STATUS SUMMARY REPT Data As Of May 31.1984 (Gray Book) \* Division of Budget & Analysis 84/07/31 394pp 26123 001
- 8408160215 Forwards add1 info re current alternate post-accident sampling sys methods.completion schedules for procurement of components.const & operator training & justification for deferral to Cycle IX refueling outage MEDFORD,M O Southern California Edison Co 84/08/14 PAULSON,W A Operating Reactors Branch 5 17pp 26090 334 24X Fiche 50-206.84/08/14.8408160215
- 8408160220 Forwards IE Insp Rept 50-382/84-21 on 840514-18 No violations or deviations noted GAGLIARDO.J E. Region 4. Office of Director 84/06/28 LEDDICK:R S. Louisiana Power & Light Co. 2pp. 26106-237 24X Fiche 50-382.64/06/28.8408160220
- --8408160226 IE Insp Rept 50-382/84-21 on 840514-18 No violations or deviations noted Major areas inspected proviously identified insp findings & selected TMT action plan requirements CHANEY, H D , MURRAY, B , CROSSMAN, W A Region 4, Office of Director 84/06/28 9pp 26106 239 24X Fiche 50-382,84/06/28,8408160220
- 8408160248 NUREG/CR-3761
  RELAP5 THERMAL-HYDRAULIC ANALYSES OF PRESSURIZED THERMAL
  SHOCK SEQUENCES FOR THE OCCNEE-1 PRESSURIZED WATER REACTOR
  FLETCHER:C D , BOLANDER:M A , STITT.B D E0&0. Inc FIN A-6047
  E0G-2310 84/07/31 Division of Accident Evaluation 165pp
  26129 001 24X Fiche 50-269.84/07/31.8408160248
- 8408160249 Notification of 840829 meeting w/C-E Comers Group Operations Subcommittee in Bethesda, MD to discuss task analysis requirement of Suppl 1 to NUREG-0737 & Generic Ltr 82-33 & portions of CCR-152.Rev 2 re inadequate core cooling CLAYTON, H B Procedures & Systems Review Branch GL-82-33 84/08/09 / IEMANN, D L Procedures & Systems Review Branch 5pp 26126 248
- 8408160250 NUREO-0675 S27

  BAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 AND 2 Docket Nos 50-275 And 50-323 (Pacific Qas And Electric Company)

  \* Division of Licensing 84/07/31 31pp Available at NRC \$3 50 26122 235 24X Fiche 30-275 84/07/31,8408160250
- 840B160262 NUREO-1031
  SAFETY EVALUATION REPORT RELATED TO THE OPERATION GF
  MILLSTOME NUCLEAR POWER STATION.UNIT NO 3 Docket No
  50-423 (Northeast Nuclear Energy Company)
  Division of Licensing 84/07/31 591pp Available at NRC
  \$11 00 26121 001 24X Fiche 50-423.84/07/31,8408160262
- B40B160333 Forwards responses to Parts 2 & 3 of Accident Evaluation Branch draft BER Open Item 53 re control room habitability WOOLEVER.E J Duquesne Light Co 2NRC-4-124 84/08/13 KNIGHTUN.6 W Licensing Branch 3 3pp 26085 338 24X Fiche 50-412,84/08/13,840B160333
- B40B16036B Forwards Rev 1 to "Detailed Control Room Design Review Program Plan," per NUKEO-0737. Item I D 1 & Suppl 1 to NUREO-0737 HARRINGTON, H D Boston Edison Co BECO 84-134 B4/08/14 VASSALLO, D B Operating Reactors Dranch 2 1p 26090 159 24X Fiche 30-273.84/08/14 B40B160355
- --8408160369 Rev 1 to "Detailed Control Room Design Review Program Plan " \* Boston Edison Co 84/06/30 120pp 26090 160 24% Fiche 50-293,84/08/14,8408160368
- B40B160374 Forwards proprietary "Conceptual Design Description for Pilgrim Nuclear Power Station Emergency & Plant Info Computer (EPIC) Safety Parameter Display Sys (SPDS)." per 331026 commitment & TMI Action Item I D 2 Rept withheld. HARRINGTON.W D Boston Edison Co BECO 84-133 84/08/10 VASBALLO, D B Operating Reactors Granch 2 1p 26091:192 24X Fiche 50-293,84/08/10,8408160374
- B40B160431 Forwards DES (NURE9-1095) & FR notice of availability W/o DES SCHWENCER, A Licensing Branch & B4/OB/OF HOOTEN, B J. Niagara Mohawk Power Corp 2pp 26122 355 24X Fiche 50-410,84/OB/OF, 840B160431
- 8408160511 Forwards IE Insp Rept 50-458/84-12 on 840604-08 No violations or deviations noted JOHNSON,E H Region 4. Office of Director 84/07/30 CAHILL,W J Quif States Utilities Co 2pp 26108 001 24X Fiche 50-458,84/07/30,8408160511

- B40B170052 Forwards "Control Room Design Review Summary Rept Mope Creek Generating Station," in response to Generic Ltr 82-33, Item 3 (NUREG-0737, Suppl 1) Meeting requested MITTL. R L Public Service Electric & Gas Co of New Jersey GL-82-33 B4/08/14 SCHWENCER, A Licensing Branch 2 2pp 26118 133 24X Fiche 50-354,84/08/14,8408170052
- B40B170094 Responds to B40712 ltr re 840502 Pottstown Mercury article & related petition Low level normal operation releases expected to be well within recognized safety limits Excerpts from DES encl DIRCKS, W. J. Office of the Executive Director for Operations 84/08/08 WALKER, R. S. House of Rep. 1p. 26135-322 24x Fiche 30~352, 84/08/08,8408170094
- B4GB170104 Forwards FR nutice of availability of DEG (NUREO-1085). Svc list encl BCHMENGER: A Licensing Branch 2 84/08/07 Library of Congress 3pp 26134 355 24X Fiche 50-410, 84/08/07, 8408170104
- 8408170107 Forwards DES (NUREC-1085) Comments due 45 days after publication of FR notice of availability W/o encl SCHWENGER, A Licensing Branch 2 84/08/09 New York, State of 1p 26134 352 24X Fiche 50-410,84/08/09,8408170107
- B40B170110 Forwards DEB (NUREG-1085) Comments due 45 days after publication of FR notice of availability W/o encl BCHWENGER.A Licensing Branch 2 84/08/09 WDDD.J M Commerce, Dept of Natl Oceanographic & Atmospheric Administration 5pp 26134 345 24X Fiche 50-410,84/08/09,8408170110
- 8408170138 Forwards evaluation re resolution of SER Confirmatory Issue 5.TMI action plan items & status of review of steam generator tube rupture event YOUNGBLOOD, B J. Licensing Branch 1 8408/09 SPENCE, M.D. Texas Utilities Cenerating Co.) 10pp. 26134 335 24X Fichs 50-445.84/08/09,8408170138
- 8408170277 Forwards info on NUREC-0737. Item II B 3 re post-accident sampling sys. supplementing 831026,1202 & 840323 submittals Results of engineering evaluation of post-accident airborne particulates will be sent by June 1985

  84YNE-J P Power Authority of the State of New York IFN-84-31.

  84Y08/13 VARGA-8 A Operating Reactors Branch i 3pp 26115 252 24X Fiche 50-286.84Y08/13,8408170277
- 8408170386 Requests meeting to discuss detailed control room design review w/respect to Nuclear Util Task Action Committee documents
  VARGA.8 A Operating Reactors Branch 1 84/05/24 MCDDNALD.R.P Alabama Power Co 3pp 26134 173 24X Fiche 50-348,84/05/24,8404170386.
- 3408200018 Doard Notification 84-143 forwards Dfc of Investigation Rept 1-83-010 on alleged felsification of TMI-2 leak rate surveitlance test data. Rept consistent w/80ppl 5 to MURCG-0680 re TMI-1 restart EISENHUT, D 0 Division of Licensing 84/08/15 PALLADING, ROBERTS, ABSELBTINE Commissioners 5pp 26300 145 24X Fiche 50-289,84/08/15,8408200018
- #408200135 Forwards add1 info concerning NREG-0737. Item II B 3 re post-accident sampling, per 840719 request Rexnord Model 340 portable oxygen monitor used to determine dissolved oxygen in reactor coolant sample. CROUSE.R P Toledo Edison Co 1066 84/09/14 9TOLZ.J F Operating Reactors Branch 4. 179p 26133 260 24X Fiche 50~346,84/08/14.8408200135
- 8408200172 Forwards response to 840709 request for additinfo re inadequate core cooling instrumentation, er Generic Ltr 82-28 Comments re subcooled margin monitor, core exit thermocouples & heated junction thermocouples encl COUNBIL, W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNBIL, W.O. Northeast Utilities A04089 84/08/14 MILLER, J.R. Depreting Reactors Branch 3 34pp 26133 025 24X Fiche 50-336, 84/08/14, 8409800172
- 8408200190 Forwards SER on proposed resolution for integrated plant SAR (NUREO-0824), Section 4 28.3 rp gas turbine preventive maint program, Program acceptable SHEA, J. Operating Reactors Branch 5 L805-84-019 84/08/16 COUNSIL, W.C. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 4pp 26133 064, 24X Fiche 50-245,84/08/16,8408200190

- 8408200219 Denies 830727 request to revise Tech Specs re containment hydrogen analyzers Present calibr requirement preferred because of more accurate hydrogen concentration measurement MILLER. J R Operating Reactors Branch 3 84/08/01 ORIFFIN, J M Arkansas Power & Light Co 2pp 26142 286 24X Fiche 50-346.84/08/01.8408200219
- 8408200303 Informs that response to Recommendation QL-2 re inadvertent closure to condensate storage tank isolation valve (NVREG-0737, Item II & I 1) will be delayed until 840824 due to outage preparation work MARSHALL, J R Arkansas Power & Light Co OCANO80409 84/08/10 STOLZ, J F Operating Reactors Branch 4 lp 26133 358 24X Fiche 50-313,84/08/10,8408200303
- 8408200311 Advises that Energency Operating Procedure QP-404, "DHR Sys," addresses concern raised at 840215 meeting re boron precipitation decay heat sys flow into reactor hot leg HESTAFER, G R Florida Power Corp 3F0884-03 84/08/08 RIVENBARK, O W Operating Reactors Branch 4 Ip 26133 019 24X Fichs 50-302,84/08/08,8408200311
- 8408200330 Provides excerpts from Missile Impact Analysis Rept E/L 20622 re turbine-driven emergency feedwater pump missile potential in response to NUREG-0737. Item II E 1 1 Response satisfiles Item 2b of 840901 8ER HESTAFER, G R Florida Power Corp 3F0884-02 84/08/08 RIVENBARK, O W Deprating Reactors Branch 4 2pp 26133 002 24x Fiche 30-302.84/08/08.8408200330
- 8408200359 Forwards Amend 82 to License DPR-40 & safety evaluation Amend adds operability & surveillance requirements for containment hydrogen water & pressure monitors TOURIONY.E G Operating Reactors Branch 3 84/08/02 JONES.W C Omaha Public Power District 1p 26141 220 24X Fichs 30-285.84/08/04.8408200359
- --8408200361 Safety evaluation supporting Amend 82 to License DPR-40 \* Office of Nuclear Reactor Regulation, Director GL-83-37 84/08/02 4pp 26141 226 24X Fiche 50-285,84/08/02,8408200359
- 8408200384 Forwards DES (NUREG-1074), per 840810 telcon w/D Wagner H/o encl BCHMENCER, A Licensing Branch 2 84/08/10 ALS, E Environmental Protection Agency 3pp 26141 217 24X Fiche 50-354, 84/08/10, 8408200386
- B408200387 Advises that program plan for conducting detailed control room design review meets intent of Suppl 1 to NVREO-0737 Listed areas should be described in summary rept expected 850830 VARQA, 8 A Licensing Branch 1 84/08/10 STEWART, W.L. Virginia Electric & Power Co 2pp 26141 215 24X Fiche 50-000,84/08/10,8408200387
- B408200414 Forwards draft safety evaluation of procedures generation package for emergency operating procedures Response to open items re writers guide & validation/verification programs requested within 30 days of itr receipt.

  RIVENBARK. G K Operating Reactors Branch 4 B4/08/09 TUCKER. H B Duke Power Co 2pp 26182 001 24X Fiche 50-269.84/08/09.
- B408200449 Responds to 840712 request for consideration of constituent H Mayerson B40607 ltr w/840802 Pottstoom Mercury article & encl petition Low level normal operation releases expected to be well within recognized safety limits
  DIRCKG.W J Office of the Executive Director for Operations
  B4/08/08 WALKER.R B House of Rep 5pp 26182 313 24X
  Fiche 50-352.84/08/08.8408200449
- --B408200454 Forwards constituent H Mayerson 840607 ltr w/840502 Pottstown Mercury article, "Limerick to Release Very Small Amounts of Radioactivity" & petition & requests investigation of statements MALVER.R 8 House of Rep 84/07/12 KAMMERER.C Office of Congressional Affairs App 26182 332 24X Fiche 50-352, 84/08/08,8408200449
- 8408200469 Forwards SER (NUREG-1031) re operation & FR notice of availability W/o SER YOUNGBLOOD, B J Licensing Branch 1 84/08/13 CDUNSIL, W o Northeast Nuclear Energy Co (subs of Northeast Utilities), 3pp 26143 356 24X Fiche 50-423,84/08/13,8408200469
- --8408200471 Notice of availability of SER (NUREO-1031)
  YOUNGBLGDD: D. Licensing Branch I 84/08/13 2pp 24143 339
  24% Fiche 30-423, 84/08/13, 8408200449

- 8408200321 Protests ref to author in Suppl 3 to NUREQ-0680 as one of five util mgt personnel involved or implicated in indictment Staff accusation improper & damaging to author reputation Requests withdrawal of findings KUNDER. 6 A Affiliation Not Assigned DSB 162 SP 84/08/13 PALLADINO.N J Commissioners 2pp 26136 361 24X Fiche 50-289.84/08/13.8408200321
- 840820053: Protests treatment of author in Suppl 9 to NURE9-0680 re leak rate tests at TMI-2 US Atty conclusions in statement of fact misleading out of context or erroneous Requests refusal of staff conclusions FLOYD, J R Affiliation Not Assigned DSB 161 SP 84/08/13 PALLADINO.N J Commissioners 2pp 26137 026 24X Fiche 50-289,84/09/13.8408200531
- 8408200540 Forwards DES (NUREG-1073) & FR notice of availability W/o DES SCHWENCER, A Licensing Branch 2 84/08/09 CAMILL, W J Gulf States Utilities Co 2pp 26143 285 24X Fiche 50-458,84/08/09, 8408200540
- --840BR00546 Notice of availability of DES (NUREO-1073) Related correspondence SCHWENCER, A Licensing Branch 2 84/08/09 2pp 26143 287 24X Fiche 50~458,84/08/09,840B20D540
- 8408200352 Forwards DES (NUREO-1073) & FR notice of issuance & availability W/o DES SCHWENGER: A Licensing Branch 2 84/08/09 HIRSCH, A Environmental Protection Agency 2pp 26143 277 24X Fiche 50-458,84/08/09,8408200552
- B408200580 Expresses dissatisfaction w/staff conclusions re author in Suppl 5 to NUREC-0480 concerning RCS leak rate tests Conclusion that author involved or implicated in indictment misleading & unfair NRC conclusions should not be adopted SEELINGER.J L Affiliation Not Assigned DBS 163 SP 84/08/09 PALLADINO.N J Commissioners 2pp 26137 138 24X Fiche 50-289.84/08/09.8408200580
- B40B210002 Forwards BAR for safety assessment sys/safety parameter display sys,per NUREG-0737.Suppl 1 & B30415 & B40312 ltrs.

  D'TODLE.J D Consolidated Edison Co of New York, Inc B4/0B/15 EISCH-NUT.D O Division of Licensing 13pp 26183 054 24X Fiche 50-247.B4/0B/15.B40B210002
- 8408210029 Advises that mode to containment pressure monitoring systo increase sys-range & sys-mod to measure vacuum up to 5 psig satisfy NUREO-0737 requirements & are acceptable PAULBUN.W A Operating Reactors Branch 5 LE05-84-08-021 84/08/17 LINDER,F Dairyland Power Cooperative 2pp 26181 335 24X Fiche 50-409,84/08/17,8408210029
- 8408210031 Forwards add1 info requested in NRC 840430 ltr re exceptions to conformance to Rev 2 to Reg Guide 1 97 Encls should close Open Item 12 of BER (NUREG-0991) KEMPER. J 5 Philadelphia Electric Co 84/08/16 SCHWENCER. A Licensing Branch 2 11pp 26181 337 24X Fiche 50-352, 84/08/16, 840821031
- 8408210054 Forwards Amend 71 to License DPR-72 & safety evaluation Amend revises format of physical security plan to be compatible w/NUREO-0908 & changes number of operational & administrative requirements SILVER.H Operating Reactors Branch 4 84/08/13 WILGUB.W 8 Florida Power Corp 3pp 26195 163 24X Fiche 50-302.84/08/13.8408210034
- --8408210061 Amend 71 to License DPR-72, revising format of physical security plan to be compatible w/NUREG-0908 & changing number of operational & administrative requirements BTOLZ-J F Operating Reactors Branch 4 B4/08/13 2pp 24195 166 24X Fiche 50-302,84/08/13,8408210054
- B408210125 Forwards 840627 QA review plan.per 840725 request Package includes transmittal ltr.QA review plan & NUREG-1055 M/o encl LINCHAN, J J Repository Projects Branch (Post 831001) 626 84/07/30 NEFF, J O Energy, Dept of 1p 26195,319
- 8408210158 Forwards status rept re control room design review, per Suppl 1 to NUREO-0737 If plan not fully resolved by fuel load, licensing uill be accomplished on PDA basis YOUNOBLOOD, B J Licensing Branch 1 84/08/13 SPENCE, M D Texa Utilities Electric Co (formerly Toxas Utilities Generating Co) 20pp 26195 287 24X Fichs 50-445,84/08/13,8408210158

- B408210313 Forwards revised FSAR App 7A pages addressing NRC B40625-26 requests for addition on Reg Guide 1 97 As-built plant design info.ne\* included in original submittal incorporated Design provides info required to satisfy Rev 2 to reg guide PETRICK.? A Standardized Nuclear Unit Power Plant Bystom SLNRC 84-107 84/08/16 DENTON.N R Office of Nuclear Reactor Regulation, Director 45pp 26179 060 24X Fiche 50-000,84/08/16,8408210313
- 8408210333 Submits safety analysis of safety parameter display sys & operational support ctr as required by Generic Ltr 82-33 re amergency response capability (Suppl 1 to NUREQ-0737) LINDER.F Dairyland Power Cooperative LAC-10124 84/08/13 CRUTCHFIELD.D Operating Reactors Branch 5 Spp 26179 332 24x Fiche 50-409.84/08/13.8408210333
- 8408210338 Informs that no add1 post-accident sampling sys required to meet guidance of NURFO-D737. Item II B 3 Item complete. High-range containment radiation monitors acceptable method of providing indication of core damage PAULSON. WA Operating Reactors Branch 5 LB05-84-08-021 84/08/17 VANDEWALLEF D J Consumers Power Co 3pp 26179 358 24X Fiche 50-155,84/08/17,8408210338
- 8408210346 Forwards "Crystal River Nuclear Power Plant Exercise"
  Few specific NUREO-0654/FEMA-REP-1.Rev 1.deficiencies
  abserved during 840425 emergency exercise State of FL &
  Citrus & Levy counties participated
  KRIMIN.R W Federal Emergency Management Agency 84/08/13
  JORDAN.E L Division of Emergency Preparedness & Engineering
  Response (Post 830103) 2pp 26179 136 24X Fiche 50-302,84/08/13,8408210346
- --8408210334 "Crystal River Nuclear Power Plant Exercise"

   Federal Emergency Management Agency 84/05/11 42pp
  26179 138 24X Fiche 50-302,84/08/13,8408210346.
- 8408210357 Responds to 840801 ltr re NUREQ-0737. Item II E 4 2(7), "Purgs & Vent Valve Isolation " Revs to Unit 2 Tech Specs expected to be submitted by 840905 Unit 1 mods will be completed during scheduled Fall 1984 refueling outage GUCWALL T Georgia Power Co NED-84-425 84/08/16 STOLZ, J F Operating Reactors Branch 4 2pp 26160, 241 24X Fiche 50-321.84/08/16.8408210357
- 840821036B Forwards IE Insp Repts 50-352/84-26 & 50-353/84-09 on 840601-30 & notice of violation STAROSTECKIR Division of Project & Resident Programs 84/08/02 KEMPER. J S Philadelphia Electric Co 2pp 26183 109 24X Fiche 50-352.84/08/02.8408210368
- --B409210381 IE Insp Repts 50-352/84-26 & 50-353/84-07 on B40601-30 Violations identified inadequate diesel generator test program implementation & inadequate calibr procedure for valve position indicating sys CHAUDHARY, S.K., MIGGINS.J.T., BAUNACK, M. Region 1, Office of Director 50-353/84-09 B4/07/24 13pp 26183 115, 24X Fiche 50-352,84/08/02,8408210368
- 8408210396 Forwards info documenting results of review & implementation of required changes & mods.per Generic Ltr Bi-O7. "Control of Heavy Loads" & NUREO-0612 Minor error noted in 801222 ltr corrected TUCKER.H B Duke Power Co gL-81-O7. 84/08/17 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E 0 Licensing Branch 4 36pg 26180 271 24X Fichs 50-369.84/08/17.8408210396
- B40B210415 Requests extension for implementation of upgraded emergency operating procedures from Third Quarter 1785 until Fourth Quarter 1985 Extension uill allow all licensed operators to receive training in use of new procedures at simulator HITHERS.8 D Portland General Electric Co QL-82-33 84/08/15 EISENHUT.D Q Division of Licensing 5pp 26180:339 24X Fiche 50-344,84/08/15,8408210415
- 8408210419 Forwards Rev O to CYGNA rept, "Main Steam/Feedwater Piping Analysis Rept " Rept addresses SEP Topic III-6 re safe shutdown sys piping outside vapor container KAY, J A Yankee Atomic Electric Go FYR 84-87 84/08/16 CRUTCHFIELD. D. Operating Reactors Branch 5 ip 26178 196 24X Fiche 50-029,84/08/16,8408210419
- BA08210484 Submits revised commitments & proposed changes to Tech Specs & emergency procedures re meteorological sys.per NUREG-0654, App 2 Querterly meteorological sensor calibr should be performed semiannually.

  DALE, L. F. Mississippi Power & Light Co. AECM-8410354, B4/08/14 DENTON, H. R. Office of Nuclear Reactor Regulation, Director, 29p. 26177, 358 24X Fiche 50-416, 84/08/14, 8408210484

8408210564 Forwards draft safety evaluation of NUREG-0737. Item II F 2 re inadequate core cooling instrumentation sys Evaluation identifies open 1\*ems Addi info requested within 2 wks W/o encl VARGA. S A Operating Reactors Branch 1 84/08/14 WILLIAMS. J W Florida Power & Light Co Ip 26175 255 24X Fiche 50-250. 84/08/14.8408210564

B40B220107 NURE9-0420 506
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SHOREHMAN NUCLEAR REPORT STATION.UNIT NO 1 Docket No 50-322 (Long Island Lighting Conpany)

\* Division of Licensing B4/07/31 33pp Available at NRC \$3 75 26197 304 24% Fiche 50-322.84/07/31,8408220107

8408220192 Forwards IE Insp Rept 50-458/84-06 on 840430-0304 No violations or deviations noted JOHNSON, E H Region I. Office of Director 84/07/19 CAHILL, W J Oulf States Utilities C on 2pp 26188 076 24X Fiche 50-458,84/07/19,8408220152

--B408220157 IE Insp Rept 50-458/84-06 on B40430-0504 No violations noted Major areas inspected radiation protection program including organization, mgt controls, staffing, qualifications, training programs & selected NNREG-0737 action items CHANEY, H D, MURRAY, B, JAUDON, J P Region I, Office of Director 84/07/18 26pp 26183 078 24X fiche 50-458,84/07/19,8408220152

8408220239 Discusses post-accident sampling sys being installed to address NRC requirements in NUREG-0737, Item II B 3 High radiation sampling sys described in FSAR will be operational on each unif prior to initial criticality TRAMM.TR Commonwealth Edison Co 9072N 84/08/13 DENTON.H R Office of Nurear Reactor Regulation, Director ip 26193 139 24: Fichs 50-000.84/08/13,8408220239

8408220265 NUREG-0933 801 A PRIDRITIZATION OF GENERIC SAFETY ISSUES ERRIT.R. MINNERS.W. VANDER MOLEN.W. Division of Safety Technology 84/07/31 120pp 26212 062

9408220308 NUREG-0940 V03 NO2 ENFORCEMENT ACTIONS SIGNIFICANT ACTIONS RESOLVED Quarterly Progress Report.April-June 1984 \* Enforcement Staff 84/07/31 363pp 26202 001

8408220318 DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF NINE MILE POINT NUCLEAR STATION.UNIT NO 2 Docket No 50-410 (Niagara Mohawk Power Corporation, Rochester Oas & Electric Corporation And Central Hudson Gas & Electric Corporation) \* Division of Licensing 84/07/31 313pp 26201 037 24X Fiche 50-410,84/07/31.8408220318

8408220325 NUREO-1073
DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF RIVER BEND STATION Docket No 50-458 (Gulf States Utilities Conpany & Cajun Electric Power Cooperative) \* Division of Licensing 84/07/31 249pp 26199 001 24X Fichs 50-458.84/07/31.8408220325

1408220326 Forwards safety evaluation & technical evaluation rept re NUREG-0612. "Control of Heavy Loads at Nuclear Power Plants - Phase I " Sections 9 : 1 & 5 3 satisfied Phase I acceptaibe PAULSON, WA Operating Reactors Branch 5 L805-84-08-026 84/08/20 COUNSIL, WG Connecticut Yankee Atomic Power Co 2pp 26193 111 24X Fiche 50-213.84/08/20.8408220328

--840822030 Safety evaluation re NUREC-0612, "Control of Heavy Loads at Nuclear Power Plants - Phase I "

\* Operating Reactors Branch 5 84/08/20 2pp 26193 113 24X Fiche 50-213,84/08/20,8408220326

--8407300136 TER-C5506-358
"Control of Heavy Loads: Connecticut Yankee Atomic Power Co,
Haddan Neck Plant: 'technical evaluation rept
BOMBERGER: C Franklin Institute/Franklin Research Center
NRC-03-81-130 TAC 07973 84/07/25 SINGH: A NRC - No Detailed
Affiliation Given 24pp 26193 115 24X Fiche 50-213,84/08/20,
8408220326

8408220327 NUREG/CR-3874 NEAR-GROUND TORNADO WIND FIELDS MCDDNALD.J R Texas Tech Univ. Lubbock, TX FIN 8-8097 84/07/S Division of Radiation Programs & Earth Sciences (post 840429) 164pp Available at NRC \$5.50 26198 197 8408220332 Comments on NURCG-1055 re ford Amend rept Study of human behavioral factors as applied to UA should be recognized. evaluated? developed as constructive mgt effort of nuclear industry MANNING. HA Calbert/Commonwealth, Inc. (formerly Gilbert Associates, Inc.) 84/08/16 CHILK.S J. Office of the Secretary of the Commission 1p 26194-062

B408220333 NUREO/CR-3493
A REVIEW OF THE LIMENICK GENERATING STATION SEVERE ACCIDENT
RISK ASSESSKENT Review of Core Melt Frequency
AZARM, M A. BARI.R A., BOCCIO.J.L. Brookhaven National Laboratory
FIN A-3393 BNL-NUREG-51711 84/07/31 Division of Safety
Technology 192pp Available at NRC \$6 00 26200 205 24X
Fiche 50-352,84/07/31,8408220333

8408220346 NUREC-0675 S26
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO
CARYON NUCLEAR POWER PLANT, UNITS 1 AND 2
# Division of Licensing 84/07/31 204pp Available at NRC
\$6 50 26200 001 24X Fiche 50-275,84/07/31,8408220346

B408220363 Forwards response to request for add1 info re control of heavy loads mode, per NUREG-0612, resulting from discussions w/Franklin Research Ctr & Rev O to Procedure 1408-6.
"Procedure for Insp of Wire Rope or Synthetic Slings "
HUKILL, H D General Public Utilities - OPU Service Corp
5211-84-2200 B4/08/16 EISENHUT, D D Division of Licensing opp
26189 324 24X Fiche 50-289, 84/08/16, 8408220363

8408220370 NUREO/CR-3869
ANALYSIS OF THE IMPACT OF INSERVICE INSPECTION USING A
#IFING RELIABILITY MODEL
SIMONEN,F A. MOD. H W Battelle Memorial Institute, Pacific
Northwest Laboratories FIN E-2289 PNL-5149 84/08/31
Division of Engineering Technology 55pp Available at NRC \$4.25

B408220375 Responds to request far add1 info re analysis to determine gas 2 water clearing thrust loads concerning second safety relief valve actuations in discharge lines, per NUREG-0641 Containment adequate for five b add1 five valve actuation FIEDLER.P B General Public Utilities - GPU Service Corp 84/08/15 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 26/91 347 24X Fiche 50-219,84/08/15.8408220375

8408220434 Forwards DES (NUREG-1073) & FR notice of issuance Comments dug 45 days after FR publication W/o DES 9CHMENCER.A Licensing Branch 2 84/08/09 Louisiana, State of 1p 26209 336 24% Fithe 50-458,84/08/09,8408220434

8408230033 Advises that Nuclear Packaging, Inc topical rept on FL-50 container acceptable Rept in Po should include list of solid traste species & source which might be incompatible w/container matl Info should meet NUREG-0800 guidance GAMHILL, W P Heteorology & Effluent Treatment Branch 84/07/15 BARRETT, L H Engineering Branch (Post 931001) 1p 24233 353

8408230046 Forwards selected major comments re draft Umbrella Site technical position for salt geology groundwater geochemistry, design & waste package Comments developed considering need to minimize efforts to make revs
MILLER.H J Repository Projects Branch (Post 831001) 84/08/07
KNAPP, M R Geotechnical Branch (Post 831001) BARRETT.L
Engineering Branch (Post 831001) 15pp 26233 316

8408230054 Responds to 840727 ltr transmitting SL Genavidez 840627 concerns re failure of reactor trip sys of nuclear plants NRC established 10CFK50 62, which requires addl features be installed at each reactor to assure shutdown if sys fails DIRCKS.W J Office of the Executive Director for Operations 84/08/15 DOMENICLP V Senate 6pp 26233 275 24X Fiche 50-000,84/08/15,8408230054

840B230078 Forwards IE Insp Rept 90-312/84-08 on 840521-25 No violations noted Matters re post-accident sampling program & offsite dose projection errors unresolved GCARAND.RA Division of Radiological Safety & Safeguards Program 84/07/30 RODRIGUEZ.R J Sacramento Municipal Utility District 3pp 26213 189 24% Fiche 50-312,84/07/30,840B230078

--B408230087 IE Insp Rept 50-312/84-08 on 840521-25 No viblations or deviations noted Major areas inspected unresolved items (NUREG-0737,II B 3 re post-accident sampling sys) & offsite dose calculation code errors NORTH.H S , YUHAS.9 P Region 5. Office of Director 84/07/06 16pp 26243 161 24X Fiche 30-312.84/07/30.840823078

- 8408130JB4 Forwards responses to questions re BAW-10155 "FOAH2." submifted on behalf of BAN Owners Group as part of small break LOCA methods program response to NUREG-0565 & NUREG-0737, Item II K 3 30 TAYLOR.J H Babcock & Milcox Co ESC-555 84/08/15 THOMAS, Standardization & Special Projects Brench 14pp 26209 041
- 8408230125 NUREG-0386 DO3
  UNITED STATES NUCLEAR REGULATORY COMMISSION STAFF PRACTICE
  AND PROCEDURE DIGEST
  \* Office of the Erecutive Legal Director \* Aspen Systems, Inc
  84/07/31 569pp 26232 033
- 8408230132 Informs of review of 840705 itr which clarified interpretation of on-shift training requirements Util will be required to provide documentation that senior reactor operator upgrade candidates comply w/listed requirements WALMER.R D Region 3. Office of Director 84/08/20 LARSON, C & Northern States Power Co. 2pp. 26209 061 24X Fiche 50-000.84/08/20.8408230132
- 8408230292 Forwards Rev 3 to 'Overhead Handling Sys Review " Rept revised.per NUREG-0612, to address concerns identified in draft technical evaluation rept on control of heavy loads & support resolution of SER License Condition 7 KEMPER.J S Philadelphia Electric Co 84/08/13 SCHHENCER.A Licensing Branch 2 3pp 26207 001 24X Fiche 50-352,84/08/13, 8408230272
- --8408230297 Rev 3 to final rept "Overhead Handling Sys Review "
  \* Philadelphia Electric Co 84/06/30 175pp 26207 004 24X
  Fiche 50-352,84/08/13,8408230292
- 8408230295 Forwards request for add1 info re proposed safety parameter display sys Response requested 30 days prior to exceeding 5% rated power
  KMICHTUNN G W. Licensing Brench 3 84/08/06 LEBDICK, R 8
  Louisiana Pewer & Light Co 7pp 26236 119 24%
  Fiche 50-382.84/08/06,8408230295
- 8408230294 Forwards Rev i to Radiation Chemistry Procedure 78 000 15, "Determination of Extent of Core Damage," to resolve SSER 3 (NUREO-0798) agen items Procedure supports deletion of license condition proposed in SER

  JENS,N H Detroit Edison Co EFF-72758 84/08/16 YOUNOBLODD, B J Licensing Branch 1 4pp 26208 005 24X Fiche 50-341,84/08/16, 8408230296
- 8408230306 Advises that 840131 submittal on detailed control room design review does not neet all requirements of Suppl 1 to NUREG-0737 Review did not include task analysis Addl significant concerns listed KNIOHION,0 & Licensing Branch 3 84/08/07 BASKIN,K P Southern California Edison Co HOLCOMOE, J C San Diego Gas & Electric Co 3pp 26236 102 24X Fiche 50-361,84/08/09,8408230306
- B40B230340 Forwards groprietary draft answers to questions in NRC Request 2 for add1 info on WCAP-10054(P) & WCAP-10054, Addundum 1 to "Questinghouse Small Break ECCS Evaluation Model Using NOTHUMP Code for C-E NESS"

  RAHGE P Westinghouse Electric Corp NS-EPR-2940 84/08/10 THOMAS, C O NRC No Detailed Affiliation Given 3pp 26205 350
- 8408230379 Forwards SSERs 24-27 (NUREG-0675) Distribution of svc list includes SSERs 25-27 since Board Notification 84-137 issued SSER 24 W/o encl KNIOHTON,G W Litersing Branch 3 84/08/10 SCHUYLER,J O Pacific Oas & Liectric Co 4pp 26230 334 24X Fiche 50-275,84/08/10.
- B408230384 Forwards SEK re util resolution of integrated plant SAR Section 4 id re thermal overload protection of motor operated valves Program described in B40730 ltr acceptable PAULSON. W. A. Operating Reactors Branch 5 LSD5-84-OB-O24 B4/08/20 FIEDLER, P. B. Jersey Central Power & Light Co. 2pp 26205 315 24% Fichs 50-219, 84/08/20, B408230384
- ---8408230305 Safety evaluation re integrated plant SAR Section 4 14 re thermal overload protection of motor operated valves Program proposed in 840730 ltr acceptable \* Operating Reactors Branch 5 84/08/20 2pp 26205 317 24X Fiche 50-219,84/08/20,8408230384
- B408230389 Forwards, for review, "Control Room Design Review Program Plan for Fermi 2," per Suppl 1 to NUREG-0737 & Generic Ltr 82-33

  JENS.N H Detroit Edison Co EF2-72747 B4/0B/16 Y0UNOBLOOD, B J Licensing Branch 1 2pp 26205 249 24X Fiche 50-341,84/0B/16,8408230389

- --8409230371 "Control Room Design Review Program Plan fo Fermi 2 " > Detroit Edison Co EFE-72747 84/08/04 48pp 26205 251 24/ Fiche 30-341.84/08/16.8408230387
- 8408230418 Informs that original approval of program re NURE9-0737. Iten I A i i. "Shift Technical Advisor." remains unchanged All new hires nust most training requirements specified in 790913 t 1030 ltrs
  PAULSON.W A Operating Reactors Branch 5 LSO5-84-08-027
  84.00722 LINDER.F Dairyland Power Cooperative 2pp 26204 00 24X Fiche 50-409.84/08/22.8408230418
- B408230420 Comments on groundwater STP for Palo Duro & Paradox hedded sait basins Program inconsistent in treating prewaste emplacement phenomenon u/post-emplacement phenomenon.per IOCFR60 113

  JOHNSON. T C Engineering Branch (Post 831001) 436 B4/08/07
  POHLE, J Geotechnical Branch (Post 831001) 2pp 26230 241
- 8408230502 Forwards IE Insp Repts 50-329/84-24 & 50-330/84-25 on 840611-15 & 25-29 No noncompliance hoted WARNICK, R F. Region 3. Office of Director 84/08/03 CDOK, J W. Consumers Power Co 2pp 26212 264 24X Fiche 50-329,84/08/03.
- --8408230512 IE Insp Repts 50-329/84-24 & 50-330/84-25 on 840611-15 & 25-29 No noncompliance or deviations noted Major areas inspected licensee action on 100FR50 55(e) items MARRISON.J J Region 3. Office of Director 50-330/84-25 84/08/03 8pp 26212 266 24X Fiths 50-329/84/08/03.8408230502
- 8408240155 Forwards description of how Rev 3 to Reg Guide 1 97,
  "Instrumentation for LWR Nuclear Power Plants to Assess
  Plant & Environs Condition During & Following Accident," per
  Suppl 1 to NUREO-0737 Mods will be implemented by 871231
  BAYNARD.P V Florida Power Corp 3F0684-07 84708/21
  RIVENSARK.G W Operating Reactors Branch 4 85pp 26228 001 24X
  Fiche 50-302.84/08/21.8408240155
- 8408240187 NUREG-0750 VI9 NO3
  NUCLEAR REGULATORY COMMISSION ISSUANCES March 1984 Pages
  555-936
  # Division of Technical Information & Document Control 84/08/31
  38606 26250 001
- 8408240188 Forwards status rept on inadequate core cooling instrumentation sys.per 831219 request Rept addresses reactor vessel instrumentation sys.core exit thermocouples, subcooling margin monitor & NUREO-0737, Item II F 2 ALEXICH.M P Indiana & Michigan Electric Co AEP NRC 0761C 84/08/20 DENTON.H R Office of Nuclear Reactor Regulation. Director 5pp 26227 355 24X Fiche 50-315.84/08/20,8408240188
- 8408240229 Summary of 840725 meeting w/util re detailed control room design review, per NUREG-0737, Suppl 1
  REEVES.E A Operating Reactors Branch 1 84/08/16 Operating Reactors Branch 1 6pp 26251 227 24X Fiche 50-346, 84/08/16, 8408240229
- 8408240249 NUREO/CP-0053
  PROCEEDINGS OF THE NINTH ANNUAL STATISTICS SYMPOSIUM ON
  NATIONAL ENERGY ISSUES, October 19-21, 1983
  BRYSON, M C Los Alamos Scientific Laboratory FIN A-7225
  LA-10127-C 84/08/91 Division of Risk Analysis & Operations
  (post 840429) 200pp 26251 027
- B408240266 Forwards order correcting administrative error in B40612 order re licensee commitments on emergency response capability Order requires implementation to meet criteria of Table 1 of Suppl 1 to NUREO-0737 by 850701 PAULSON.W A Operating Reactors Branch 5 LSO5-84-08-030 B4/08/23 KAV, A Yankee Atomic Electric Co 3pp 26223 112 24X Fiche 50-029,84/08/23.8408240266
- --8408240281 Order confirming further licensee commitment on emergency response capability Licensee required to complete inplementation of upgraded emergency operations facility to meet criteria of Table 1 of Suppl 1 to NUREG-0737 by 850901 HIRAGLIA.F J. Division of Licensing 84/08/23 Yankee Atomic Electric Co 4pp 26223 115 24% Fiche 50-027,84/08/23.
- 840B240293 Comments on DES (NUREG-1074) Water treatment intake sys. cooling water sys.pouer transmission sys.groundwater.water use, terrestrial resources aquatic resources & historical & archaeological sites discussed MITTL.R L Public Service Electric & Gas Co. of New Jersey 84/08/17 8CHMENGER, A Licensing Branch 2. Bpp 26236 271 24X Fiche 50-354.84/08/17.8408240293

- 8408240320 NUREO/CR-3818
  REPORT OF RESULTS OF NUCLEAR POWER PLANT AGING WORKSHOPS
  CLARK, N H. BERRY, D L. Sandia Laboratories FIN A-1357
  SAND-84-0374 84/08/31 Division of Engineering Technology
  64Pp 26237 284
- 8408240322 NUREO/CR-3894

  ULTRASONIC AND METALLURGICAL EXAMINATION OF A CRACKED TYPE
  304 STAINLESS STEEL BMR PIPE WELDHENT
  PARK, J Y . KUPPERMAN, D Argonne National Laboratory FIN A-2212
  ANL-84-1 84/07/31 Division of Engineering Technology 22pp
  26255 169
- 840824032B Confirms 840827 meeting in Bethesda, MD to discuss task analysis requirements of NUREO-0737. Suppl 1 & SER open items on CEN-152 re inadequate core cooling & reactor vessel lavel monitoring sys
  THOMPSON, H L Division of Human Factors Safety 84/08/13
  BARROH, J Florida Power & Light Co 1p 26R53 336 24X
  Fiche 50-250.84/08/13.8408240328
- --8408240330 Notification of 840829 meeting w/util in Betherda,MD to discuss task analysis requirements of NUREO-0737, Suppl 1 & SER open items om CEN-152 re inadequate core cooling & reactor vessel level monitoring sys CLAYTON.H 8 Procedures & Systems Review Branch 84/08/09 ZIEMAN.D L Procedures & Systems Review Branch 20p 26253 337 24X Fiche 50-250.84/08/13.8408240328
- 8408240364 Forwards Insp Repts 50-321/84-23 & 50-366/84-23 on 840618-22 No violations or deviations noted Unresolved items identified will be pursued during future insps DANCE.H C Region 2, Office of Director 84/07/11 KELLY.R J Oporgia Power Co 2pp 26237 080 24% Fiche 50-321,84/07/11,840824034
- ---B408240366 Insp Repts 50-321/84-23 & 50-366/B4-23 on B4061B-22 No violations or deviations noted Major areas inspected evaluation of ultrasonic test indications in feedwater weld 2021-IFW-12AA-12 (Unit 2)
  CROMLEY, B R, COLEY, J L, BLAKE, J J Region 2, Office of Director 50-366/84-23 84/07/10 12p 26237 082 24X
  Fiche 50-321,84/07/11 8408240364
- 8408240379 NUREO/CR-3708 LMR SPENT FUEL DRY STORAGE BEHAVIOR AT 229 C EINZIGER, R E Westinghouse Electric Corp COOK: J A EG&G. Inc FIN B-2435 84/07/31 Division of Engineering Technology 134pp 26255 COI
- 8408240382 NUREO/CR-1740 ROI
  DATA SUMMARIES OF LICENSEE EVENT REPORTS OF SELECTED
  INSTRUMENTATION AND CONTROL COMPONENTS AT U S COMMERCIAL
  NUCLEAR POMER PLANTS JANUARY 1,1976 TO DECEMBER 31,1981
  TROJOUSKY,M , BROWN,S R. EO&O, Inc FIN A-6393 EQO-2307
  84/07/31 Division of Risk Analysis & Operations (post 840429),
  344pp 26249,001
- 8408240428 Forwards Insp Rept 50-305/84-07 on 840709-13 % notice of violation Licensee should address emergency preparedness wasknesses identified in App B Shift staffing also questioned W/o notice of violation & App B HIND J A Region 3. Office of Director 84/08/04 GIESLER, C Wisconsin Public Service Corp 3pp 26237 121 24X Fichs 50-303.84/08/06.8408240428
- 8408270019 Forwards remittance for 840615 request for amends in response to Generic Ltr 83-37 re NUREG-0737 Tech Specs, per 10CFR170 22 HILLIAMS.J W Florida Power & Light Co. L-84-215 84/08/21 EISENHUT.D 0 Division of Licensing 1p 26247 194 24X Fiche 30-290.84/08/21.8408270019
- B408270030 Advises of adoption of Westinghouse generic core damage assessment methodology. In response to NUREC-0737. Item II B. 3, "Post-Accident Sampling Capability "
  SCHMIDT. H C Texas Utilities Electric Co (formerly Texas Utilities Control of Contro
- 8408270084 Forwards Insp Rept 50-341/84-27 on 840709-13 & 25 No moncompliance noted PAPERIELLO,C J Region 3, Office of Director 84/08/10 JENS,W H Detroit Edison Co 2pg 26258 210 24X Fiche 50-341,84/08/10,8408270084
- --8408270090 Insp Rept 50-341/84-27 on 840709-13 & 25 No noncompliance noted Major areas inspected preoperational radiation protection program facilities, equipment, NUREG-0737 items: atatus of preoperational sys & drain sys HUETER, L. J. GILL, C. F. GREGER, L. R. Region 3, Office of Director 84/08/10 20pp 26258 212 24X Fiche 50-341,84/08/10.8408270084

- B40B270113 Informs of schedule for resolving concerns re provisions for sampling gaseous radiolodine OL should be conditioned to require resolution of NUREQ-0737 requirements for sampling gaseous effluent steam prior to refueling outage TRAMM. T R Commonwealth Edison Co 9097N 84/08/17 DENTON. H R Office of Nuclear Reactors Regulation. Director 1p 26247 329 247 Fiche 50-454.84/08/17.8408270113
- 8408270114 Provides supplemental response to Generic Ltr 83-36.

  "NUREO-0737 Tech Specs " Mods to Guad Cities radiological
  ETS will not be complete until Fall 1984 Complete
  response w/Tech Spec amend requests expected by 841115

  ALEXANDER. C L Commonwealth Edison Co GL-83-36 84/08/15

  DENION HR GPFice of Nuclear Reactor Regulation, Director 2pp
  26247 330 24X Fiche 50-000.84/08/15.8408270114
- B408270133 Forwards "Containment Ultimate Capacity Analysis," per NUREG-0857. "SER re Operation of Palo Verde Nuclear Generating Station. Units 1.2 & 3 " Analysis should close license condition discussed in Section 3 8 1

  VAN BRUNT, E E Arizona Public Service Co ANPP-30284-EEVB B4/08/20 KNIGHTON.0 Licensing Branch 3 3pp 26245 061 24X Fiche 50-528.84/08/20.8408270133
- B408270204 Forwards addl info re monitoring of leakage from sysgutside containment used to transport highly radioactive fluid & gases in post-accident condition Info should close BER Confirmatory Issue 28(a) TRAMM.T R Commonwealth Edison Co 9045N 84/08/11 DENTON.H Office of Nuclear Reactor Regulation, Director 7pp 26245 103 24% Fiche 50-000.84/08/11.8408270204
- 8408270260 Requests approval of two temporary deviations in emergency preparedness plan from goals for augmentation of emergency response organization in Suppl 1 to NUREG-0737 Nature & duration of deviations enci
  VAN BRUNTLE E Arizona Public Service Co ANPP-30234-EEVB 84708/20 KNIGHTON, 6 Licensing Branch 3 27pp 26243 131 24x Fiche 50-528,84708/20,8408270260
- B40B270289 Forwards Technical Data Rept 580 re repair & failure analysis data for isolation condenser sys piping cracked welds, per 840628 request concerning SER of Rev I to NUREO-0313 implementation FIEDLER.P B Ceneral Public Utilities GPU Bervice Corp B4/08/22 PAULBON.W A Operating Reactors Branch 5 ip 26243 158 24X Fiche 50-219.84/08/22.8408270285
- B408270289 Forwards Insp Repts 50-250/64-19 & 50-251/84-19 on B40604-08 No violations or deviations nated DANCE.H C Region 2. Office of Director 84/07/09 WILLIAMS, J W Florida Power & Light Co 2pp 26258 167 24X Fichs 50-250.84/07/09.8408270289
- --8408270295 Insp Repts 50-250/84-19 & 50-251/84-19 on 840404-0B No violations or deviations noted Major areas inspected emergency preparedness MARSTON: R Region 2. Office of Director 50-251/84-19 84/07/06 9pp 26258 169 24X Fiche 50-250.84/07/09.8408270269
- B40B270291 Ack receipt of 840709 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-335/84-18 & 50-387/84-19 DANCE,H C Region 2, Office of Director 84/08/02 WILLIAMS,J W Florida Power & Light Co
- --8408270298 Responds to NRC 840608 ltr re violations noted in Insp Repts 50-333/84-18 & 50-389/84-19 Corrective actions installed detectors will be replaced & two spare detectors properly calibr WILLIAMS, J W Florida Power & Light Co L-84-173 84/07/09 C/REILLY, J P Region 2, Office of Director 2pp 26258 179 24X Fiche 50-335,84/08/02,8408270291
- --8408270310 Notice of violation from insp on 840514-18 \* Region 2, Office of Director 50-389/84-19 84/06/08 ip 26258 183 24X Fiche 50-335,84/08/02,8408270291
- ---8408270317 Insp Repts 50-335/84-18 & 50-389/84-19 on 840514-18
  Noncompliance noted failure to certify proper vendor
  calibr of containment high-range radiation monitors prior
  to initial use
  WRAY.J R. JENKING.9 R Region 2. Office of Director
  50-389/84-19 84/06/08 6pp 26258 184 24X
  Fiche 50-335,84/08/02,8408270291
- 8408270293 Forwards Rev 1 to 840403 application for amend to License DPR-22 Rev modifies surveillance requirements for emergency filtration train charcoal absorber & filters & toxic gas monitoring requirements for control room MUSOLF, D. Northern States Power Co. 84/08/17 Office of Nuclear Reactor Regulation, Director 1p 26242 313 24X Fiche 50-263,84/08/17,8408270293

```
8408280258 Forwards plant-specific procedures for estimating core damage as required by NAREO-0737, Item II B 3.Criterion 2. per SER confirmatory item COUNSIL.H G. FEE.H F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.H G. Northeast Utilities F0540A 84708/16 YOUNGBLOOD B J. Licensing Branch i 2pp 26262 070 24X Fiche 50-423.84708/16.8408280258
 8408280270 Forwards draft technical evaluation rept re control of heavy loads for review & comment Project manager should be contacted within 30 days to discuss outstanding items
        W/n encl
      W/o encl
VARGA.B A Operating Reactors Branch 1 84/08/20 D'TOOLE.J D
Consolidated Edison Co of New York. Inc 1p 26294 086 24X
Fiche 50-247.84/08/20.8408280290
8408280319 Forwards draft technical evaluation rept. "Control of Heavy Loads - Phase II. Davis-Besse Nuclear Power Station Unit 1." for review STOLZ, J.F. Operating Reactors Branch 4 TAC 52271 84/08/17 CROUSE, R.P. Toledo Edison Co. 2pp. 26294 053 24X Fiche 50-346,84/08/17,8408280319
 --B40B280321 TER-C5504-489 DRFT
             408280321 TER-C5506-489 DRFT

Draft "Control of Heavy Loads - Phase II, Davis-Besse Nuclear
Power Station Unit 1," technical evaluation rept
BOMDERGER,C R , WALTER,R J , BARGENT,I H Franklin
Institute/Franklin Research Center NRC-03-81-130 TAC 5227
84/07/10 SINOH,A NRC - No Detailed Affiliation given 26
26294 055 24X Fiche 50-346,84/08/17,8408280319
                                                                                                                                                                               TAC 52271
 8408280488 Confirms util 840808 commitment to submit by 841001, revised Tach Specs re instrumentation for containment sump level & containment pressure & equipment for RCS high point vents. per Generic Ltr 83-37 & NUREG-0737 STOLZ.J f Operating Reactors Branch 4 CL-83-37 84/08/17 CRRUSE.R P Toledo Edison Co 2pp 26292 335 24X Fiche 50-346.84/08/17.8408280488
 8408290001 Advises that Multi-Plant Action 8-59 re masonry well design complete Plant structures will be seismically evaluated for weak links, per NUREO-0828 PAULSON, W.A. Operating Reactors Branch 5 LSD5-84-08-035 84/08/27 VANDEWALLE, D.J. Consumers Power Co. Spp. 26291 289 24X Fiche 50-155,84/08/27,8408290001
 8408290158 NUREG-1068
REVIEW INSIGHTS ON THE PROBABILISTIC RISK ASSESSMENTS FOR
THE LIMERICK GENERATING STATION, UNIT 1 AND 2
CHELLIAH, E Division of Bafety Technology 84/08/31 12App
Available at NRC $5 OD 26309 151 24X Fiche 50-352,84/08/31.
8408290158
        #0827017: NUREO/CR-3569

SPECIAL AND DIBINETRIC MEASUREMENTS OF PHOTON FIELDS AT COMMERCIAL NUCLEAR SITES

ROBERSON:P L , FOX.R A , HOLBROOK.K L Battelle Memorial Institute.

Pacific Northusst Laboratories FIN B-2419 PNL-4915 84/08/31

Division of Facility Operations 182pp Available at NRC $6 00 26297 119
  8408270171 NUREG/CR-3569
  8408290185 NUREG/CR-3884
        408290185 NUREO/CR-3884
EVALUATION OF NUCLEAR FACILITY DECOMMISSIONING PROJECTS
PROGRAM - THREE MILE ISLAND UNIT 2 POLAR CRANE RECOVERY
DDEROE,D H. MILLER,R L. United Nuclear Corp. FIN 8-7568
84/08/31 Division of Engineering Technology 63pp A
NRC $4 3D 26309 267
                                                                                                                                                                                     Available at
   8408290190 NUREG/CR-3591 VOI
        408290190 NUREO/CR-3091 VO1
PRECURBORS TO POTENTIAL SEVERE CORE DAMAGE ACCIDENTS
1980-1991 A Status Report
COTTRELL,W B , MINARICK,J W , AUBTIN,P N Dax Ridge National
Laboratory FIN B-0435 84/07/31 Division of Risk Analy:
Operations (post 840429) 262pp 26312 001
                                                                                                                                Division of Risk Analusis &
   8408290198 NUREG/CR-3591 VOZ
PRECURSORS TO POTENTIAL SEVERE CORE DAMAGE ACCIDENTS
         1980-1981 A Status Report
COTTRELL.W B , MINARICK.J W , AUSTIN, P N Oak Ridge National
Laboratory FIN B-0435 84/07/31 Pivision of Risk Analysis &
Operations (post 840429) 266pp 26311 001
   8408290353 NUREO-0090 VOT ROI
REPORT TO CONGRESS ON ABRORMAL DCCURRENCES January-March
          1784
                 Director's Office 84/07/31 32pp 26299 305
   8408290478 Forwards Insp Rept 50-322/84-23 on 840528-0701 No violations
          noted.
STAROSTECKI,R Division of Project & Resident Programs
LEONARD.J L Long Island Lighting Co 4pp. 26294 189
Fiche 50-322,84/08/08.8408290478
```

- --8408270483 Insp Rept 50-322/84-23 on 840528-0701 No violations noted Major areas inspected discharge of security guard weapon, status of Colt diesel generator project, storage of emergency equipment lockers & IE Bulietin 80-06 PETRONE, C & ESELGROTH, P , SHEDLOSKY, J Region 1, Office of Director IEB-80 04 84/07/19 12pp 26294 193 24X Fiche 50-322,84/08/08,8408290478
- B408300156 Follwards Insp Rept 50-255/84-06 on 840322-23 & 0427 W/o notice of violation MEPPLER.J & Region 3, Office of Director 84/07/11 DEWITT.R B Consumers Power Co 2pp 26307 333 24X Fiche 50-255.84/07/11, 8408300154
- --8408300164 Insp Rept 30~255/84-06 on 840322-23 & 0427 Noncompliance noted dose to worker exceeded 10CFR20 101 limits failure to provide proper monitoring for high radiation area access & failure to follow radiation protection procedures LOVENDALE, P C , GREGER, L R Region 3, Office of Director 84/07/10 13pp 26307 335 24X Fiche 50-255.84/07/11,8408300156
- 8408300187 Forwards Insu Repts 50-528/84-23 & 50-529/84-17 on 840602-0701 No noncompliance noted BIEHOP.T W Division of Resident.Reactor Project & Engineering Programs 84/08/02 VAN BRUNT.E E Arizona Public Service Co 2pp 26308 014 24X Fiche 50-526.84/08/02.8408300187
- --8408300175 Insp Repts 50-528/84-23 & 50-529/84-17 on 840602-0701 No viplations noted Major areas inspected preoperational testing activities.maint.review of maint & followup on TMI Lessons Learned implementation ZIMMERMAN.R. FIDREILI.G. BOSTED.C Region 5, Office of Director 50-529/84-17 84/08/01 12pp 26308 016 24X Fiche 50-528,84/08/02,8408300187
- 8408300208 Forwards FEMA findings on State of FL & associated local emergency plans re plant DANCE. H C Region 2. Office of Director 84/06/05 WILGUS, W S Florida Power Corp 1p 26307 044 24% Fiche 50-302,84/06/05,8408300208
- --84083002:1 Approves State of FL & local plans & preparedness for alerting & protecting public in event of radiological emergency Approval conditional on verification of alert & notification per App 3 of NUREG-0654/FEMA-REP-1/Rev | 8FECK/S W Federal Energency Management Agency 84/02/15 DIRCKS.W J Defice of the Executive Director for Operations | 26307 045 24K Fiche 50-302.84/06/05.8408300208
- 840B300272 NUREO/CR-3590
  EVALUATION OF ISOTOPE DILUTION MASS SPECTROMETRY FOR
  BIGASSAY MEASUREMENT OF URANIUM PLUTONIUM, AND THORIUM IN
  URINE
  DYER: F F MAY, M P , WALKER, R L Oak Ridge National Laboratory FIN
  B-0494 ORNL/TM-9006 84/08/31 Division of Facility Operations
  79pp 26330 224
- 8408300279 NUREG-0304 V09 NO2 REGULATORY AND TECHNICAL REPORTS Compilation for Second Quarter 1784 \* Division of Technical Information & Document Control 84/08/31 180pp 26331 346
- B40B300202 NUREO/CR-3851 V01
  PROORESS IN EVALUATION OF RADIONICLIDE GEOCHEMICAL
  INFORMATION DEVELOPED BY DOE HIGH-LEVEL NUCLEAR WASTE
  REPOSITORY SITE PROJECTS Report for October-December 1983
  KELMERS, A D . KESBLER, J H . ARNOLD, W D Oak Ridge National
  Laboratory QRNL/TM-9191/VI B4/08/31 Division of Waste
  Management 4Bpp Available at NRC \$4 00 24331 224
- 840B300297 NUREO/CR-2000 VO3 N7 LICENSEE EVENT REPORT (LER) Compilation for Month of July 1984 \* Dak Hidge National Laboratory FIN A-7135 DRNL/NSIC-200 84/08/31 Director's Office 101pp 26331 123
- 8408300289 NUREO/BR-0025 VIO N& IMPORMATION REPORT ON STATE LEGISLATION KERR.0 W : MCQUADE.J Office of State Programs, Director 84/07/27 9pp 26030 333
- 940B300272 NUREC-1054
  BIMPLIFIED ANALYSIS FOR LIQUID PATHWAY STUDIES
  CODELL.R B Division of Engineering 84/08/31 106pp Available
  at NRC \$5 00 26331 001
- 8408300304 Ack receipt of DES (NUREO-1074) Future submissions should be sent to Commissioner, State of NJ. Dept of Environ Protection SILVER, N S Now Jersey, State of 84/08/24 SCHWENCER, A Licensing Branch 2 ip 24306 359 24X Fiche 50-354,84/08/24,840830304

- 840B3003BJ Furwards Insp Repts 50-528/84-25 50-527/84-17 & 50-530/84-12 on 840/09-13 / notices of violation t deviation notices of violation to the state of the state of Birector S4/08/08 VAN BRUNT, E FARIZONA Public Service Co. 2pp. 2630B 122 24X Fiche 50-528.84/08/09.8408300383
- --840830040/ Insp Repts 50-528/84-25 50-527/84-19 ( 50-530/84-12 on B40709-13 Violations noted fire protection sys not designed to retain structural integrity during seismic event CLARK, C Region 5. Unfice of Director 50-530/44-12 B4/08/03 24pp 26308 127 24 ( Fiche 50-528.04/08/08.8408300383
- 8408310003 Forwards request for add1 info re safety parameter display sys implementation plan % parameter selection rept submitted in 840801 response to Generic Ltr 82-33 (NURE9-073). Suppl 1) Response requested within 45 days VARGA. S A Operating Reactors Branch 1 OL-82-33 84/08/15 WILLIAMS, J & Florida Power & Light Co 4pp 26350 202 24% Fiche 50-250.84/08/15.8408310003
- B40B310007 Responds to 840206 ltr on SER License Condition 7 re compliance w/NUREC-0612.control of heavy loads.Phase II "Limerick Overhead Handling Sys Final Rept (Rev 3)" revised per 840204 request Related correspondence KEMPER.J S Philadelphia Electric Co DSB 293 DL 84/08/18 SCHMENCER.A Licensing Branch 2 3pp 26350 197 24X Fiche 50-352.84/08/18.8408310007
- 8408310030 Forwards comments on equivalent cold license training program Requests addl info re hat license program Hot license program equivalent to cold license training for determining eligibility DANCE.H C Region 2. Office of Director 84/06/07 WILLIAMS, J W Florida Fouer & Light Co 3pp 26335 017 24X Fiche 50-250.84/06/07.8408310030
- 8408310075 NUREG/CR-3798
  CHARACTERIZATION OF CEMENT AND BITUMEN MASTE FORMS
  CONTAINING SIMULATED LOW-LEVEL MASTE INCINERATOR ASH
  MESTBIK, J. H. BUSCHBOM, R. L., DIVINE, J. R. Battelle Memorial
  Institute, Pacific Northwest Laboratories FIN B-2401 PNL-5153
  84/08/31 Division of Radiation Programs & Carth Sciences (post
  8408429) 100pp Available at NRC \$4.75 26347 319
- B40B310077 NUREO/CR-3687 VO3
  MATERIALS SCIENCE AND TECHNOLOGY DIVISION LIGHT-WATER
  REACTOR SAFETY RESEARCH PROGRAM Quarterly Progress Report,
  July-September 1983
  RESEL Argonne National Leboratory FIN A-2016 ANL-83-85
  B4/07/31 Division of Engineering Technology 40pp 26347 277
- 8408310083 NUREC/CR-3689 VO2
  MATERIALS SCIENCE AND TECHNOLOGY DIVISION LIGHT-WATER
  REACTOR SAFETY RESEARCH PROGRAM Quarterly Progress Report,
  April-June 1983
  SHACK, W J Argonne National Laboratory FIN A-2016 ANL-83-85
  84707/31 Division of Engineering Technology 141pp 26348 215
- 8408310694 NURLO/CR-3792
  CLOSEOUT OF TE BULLETIN 79-11 FAULTY OVERCURRENT TRIP
  DEVICE IN CIRCUIT BREAKFRS FOR ENGINEERED SAFETY SYSTEMS
  FOLEY, W J., DEAN, R S., H-NNICK, A. Parameter, Inc. FIN B-8714
  IEB-79-11 84/08/31 Division of Emergency Preparedness &
  Engineering Response (Post 830103) 34pp Available at NRC \$4.00
  26348-057
- 8408310089 NUREO/CR-3690
  RELAPS ASSESSMENT SEMISCALE NATURAL CIRCULATION TESTS
  S-NC-3, S-NC-4, AND S-NC-8
  WONG, C c , KMETY, K L Sandia Laboratories FIN A-1205 SAND-0402
  84/07/31 Division of Accident Evaluation 115pp 26348 099
- 8408310093 Requests extension of schedule for implementation of upgraded emergency operating procedures until 850601, due to need to complete operator training on procedures, per Suppl 1 to NUREG-0737 MURPHY. W P Vermont Yankee Nuclear Power Corp FVY 84-105 84/08/22 VABSALLO.D B Operating Reactors Branch 2 2pp 26323 200 24x Fiche 50-271,84/08/22,8408310093
- 8408310121 Requests extension of time to respond to 840720 ltr re util plans for establishing energency operations facility design consistent w/requirements of Suppl 1 to NVRCO-0737 Extension requested due to judicial review of util appeal TUCKER.H B Duke Power Co 84/08/24 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 26322 243 24X Fiche 50-269.84/08/24.8408310121

1

- B408310146 Forwards response to B40509 request for addl info re NuREG-073/. Iten III D 1 i. "Primary Coolant Dutside Confainment ' Info will be incorporated in Sept 1984 FSAR rev KEMPER. J S Philadelphia Electric Co B4/08/24 SCHWENCER. A Licessing Granch 2 9pp 26322 208 24X Fiche 50-352,84/08/24,8408310146
- 8408310300 Discusses PRA of proposed mod to auxiliary feedwater sys.per NUREG-0737.item II E 1 Efforts on mod stopped as result of PRA conclusion that installation of addl check valves will not significantly improve availability of sys CASCARAND.R N Commonwealth Edison Co 9113N 84/08/23 DENTON.H R Defice of Nuclear Reactor Regulation. Director 3pp 26318 308 24% Fiche 50-295.84/08/23.8408310200
- B40B310225 Forwards detailed response to Question 420 01 re verification of adequate safety parameter display sys isolation from safety-related sys No Tech Spec changes needed NUREG-0737, Buppl 1 requirements met CODK, K W Louisiana Pouer & Light Co W3PB4-2366 B4/08/27 KNIOHTON. C W Licensing Branch 3 5pp 26319 276 24X Fiche 50-3B2,84/08/27,8408310225
- 8408310231 Forwards revs to proposed Tach Spec changes for NUREG-0737 items re containment radiation monitors & post-accident sampling.per Generic Ltr 83-37 GRIFFIN.J M. Ariansas Power & Light Co. GL-83-37 84/08/22 STULZ.JF Operating Reactors Branch 4 12pp 26320 314 24x Fiche 50-313.84/08/22,8408310231
- B40B310315 Advises that Amend 4 to radiological emergency response plan acceptable.per 10CFR50 47 & Rev 1 to NUREG-0454 BCHUBIER,M D Region 5. Office of Director 84/08/17 WITHERB, B D Portland General Electric Co 2pp 26333 298 24X Fiche 50-344.84/08/17,8408310315

#### ORG CORRESPONDENCE WITH OTHER ORGANIZATIONS

- 8405240290 Responds to 840424 memo for FEMA review of util request for delay in scheduling next full-scale emergency preparedness secretise at site until 841130 Delay acceptable KRIMM.R Federal Emergency Management Agency 84/05/18 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 8pp 24614 336 24X Fiche 50-003,84/05/18,8405240290
- 8407250229 IC Info Notice 84-57, "Operating Experience re Moisture Intrusion in Bafety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865-047 24X Fiche 50-000,84/07/27,8407250229
- 8408010746 Forwards "FES Remedial Actions at Former Vitro Chemical Co Bite, South Salt Lake City, Salt Lake County, UT" MDRLEY, J A Energy, Dept of 84/07/13 Affiliation Not Assigned 1p 25868 ODI
- --8408010053 DDE/EIS-0079-F "FES Remedial Actions at Former Vitro Chemical Co Site.South Salt Lake.Salt Lake County.UI Vol I - Text " \* Energy. Dept of 84/07/31 501pp 25868 002
- --8408010063 DGE/E18-0079-F "FCB Remedial Actions at Former Vitro Chemical Co.South Balt Lake Salt Lake County, UT Vol II - Apps " \* Energy, Dept of 84/07/31 398pp 25869 143
- 8408010064 Forwards revised "UMTRA Project Environ.Health & Safety Plan." incorporating NRC comments MCRLEY,J A Energy Dept of B4/07/17 HIGGINDOTHAM Low-Level Waste & Uranzum Recovery Projects Branch 2pp 25897 238
- ~~8408010072 "UMTRA Project Environ Health & Safety Plan "
  \* Energy, Dept of 84/06/30 Ppp 25897 240
- 8408010333 IE Info Notice 84-59, "Duliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc. 122pp 26058 001. 24X Fiche 50-000.84/08/06,8408010333
- 8408010337 IE Info Notice 84-60. "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidates Edison Co. of New York, Inc. 123pp 26057 158 24% Fiche 50-000,84/08/06.8408010337

- 8408060019 Responds to approval request for info collection re limiting use of highly enriched U in research reactors MACRAE. J B Office of thanagement & Budget QMB 3150-0011 84/07/24 SCOTT.S Document Management Branch 2pp 23934 358
- 8408060059 App 7 to MBU between NRC & DOE re repository projects in site suitability & planning phase \* NRC No Detailed Afriliation Given \* Energy, Dept of 00324 84/07/27 3pp 25937 083
- 8408060106 Forwards draft processing site & disposal site characterization repts for Salt Lake City.UT Repts contain current data re conceptual design analysis Comments requested by 840824 MATHEWS.M L Energy, Dept of 84/07/20 MARTIN.D Uranium Recovery Licensing Branch 1p 29952 001
- --B40B040111 UMTRA-D0E/AL-050102

  Draft "Disposal Site Characterization Rept for U Mill
  Tailings Site at Salt Lake City,UT " Two oversize maps
  encl Aperture cards available in PDR
  # Energy, Dept of 84/06/30 155pp 25952 003
- --8408060122 UMTRA-DDE/AL-050102
  Review draft of "Processing Site Characterization Rept for U
  Mil) Tailings Site at Salt Lake City, UT "Six oversize maps
  encl Aperture cards available in PDR
  \* Energy, Dept of 84/06/30 236pp 25952 156
- B4080&0114 Responds to approval request for info collection re 10CFR51, "Licensing & Regulatory Policy & Procedures for Environ Protection" & Reg Guide 4 2, "Preparation of Environ Repts for Nuclear Power Plants "

  MACRAE, J B Office of Management & Budget. OMB 3150-0021

  84/07/24 SCOTT, B Document Management Branch 2pp. 25736 350
- 8408060219 Responds to approval request for info collection re survey of users of gauges under general license MACRAE, J B Office of Management & Budget CMS 3150-0124 B4/07/24 SCDTT,S Document Management Branch 2pp 25950 251
- 8408070026 Forwards draft "Fifth Semiannual Staff Evaluation of Status of MPRDS" Final rept & associated Commission paper will be submitted to EDO on 840725, for forwarding to Commission HEBDDN: FJ Program Technology Branch 84/07/19 ROSEN, 8 Institute of Nucleer Power Operations 1p 25937 074
- --8407250575 Draft "Fifth Semiannual Staff Evaluation of Status of NPRDS " \* Director's Office 84/07/31 15pp 25957 077
- 8408070031 Responds to approval request for info collection re personnel security questionnaire MACRAE, J B Office of Management & Budget OMB 3150-0048 84/07/24 SCOTT.S. Document Management Branch 2pg 25956 178
- 8408070103 Forwards request for CMB review & supporting statement re proposed revs to 10CFR30 & 10CFR73, "Insider Safeguards Rules " NORRY,P 0 Office of Administration 84/07/30 MCRAS.J.B Office of Management & Budget ip 25735 197
- 8408070120 IE Info Notice 84-61. "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consultdated Edison Co. of New York, Inc. 120pp 26127 118 24X Fiche 50-000,84/08/08,8408070120
- 8408070368 Advises of FEMA 840706 completion of analysis of alert notification sys Sys adequate eliminating caveat in FEMA 830316 finding FEMA rept encl Related correspondence OUDDARO, R J Hearing Branch 3 DSB 817 DLA 84/08/02 BLOCKH P B . PARIS, D H . SHON, F J Atomic Safety and Licensing Board Panel 72pp 25944 210, 24% Fiche 50-155,84/08/02,8408070368
- B408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments" Bvc list encl ORACE. J N Division of QA, Safeguards & Inspection Programs (Post B30103) B4/08/JO Consolidated Edison Co of New York, Inc. 125pp 26130 001. 24% Fiche 50-000,84/08/10,8408070376
- 8408080024 Staff requirements memo re 840731 meeting in Washington, DC on Industry views on terms important to safety & safety—related CHILK, SJ Office of the Secretary of the Commission M840731C 84/08/01 Office of the Secretary of the Commission. 1p 25981 037

- 8408080138 Forwards "Grand Gulf Nuclean Power Station Exercise," of offsite radiological energency conducted on 840411 Meeting held on 840431 Wittl & State of MS to discuss deficiency re coordination of issuance of public info KRIMM.R & Federal Emergency Management Agency 84/07/30 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 3pp 25760 266 24% Fiche 50-416,84/07/30, 8408080138
- --8408080141 "Grand Gulf Nuclear Power Station Exercise," conducted on 840411

  \* Federal Energency Management Agency 84/04/24 69pp 23940 269 24% Fiche 50-416,84/07/30.8408080138
- 8408080177 Forwards request for CMB review & supporting statement re revised (OCFR110, "Export & Import of Nuclear Equipment & Hatls " NORRY.P O Office of Administration 84/08/03 MACRAE, J B Office of Management & Budget 1p 25778 345
- 8408080277 Forwards comments on NUREO-1055 re improving quality & GA in design & const of nuclear power plants AEs & NRC should clearly define stable acceptance criteria before const started

  \* American Society of Mechanical Engineers 84/07/30 Docketing & Services Branch 6pp 25964 311
- & Services Branch 6pp 25964 311
  ---B408080303 Speech entitled "Disciplined Approach for Introducing
- --B408080303 Speech entitled "Disciplined Approach for Introducing Certainty & Improving Quality in Nuclear Power Plant Const," presented at 840320 meeting of AIF & ANEC boards STERN.T Atomic Industrial Forum B4/03/20 4pp 25964 317
- 840B080384 Discusses jurisdictional issue re EPA proposed environ stds for mgt & disposal of spent nuclear fuel & NRC regulation 10CFR60 Mod to 10CFR60 appropriate to incorporate EPA proposed assurance requirements ROBERTB.T M Commissioners 84/07/19 RUCKELSHAUS, W Environmental Protection Agency 2pp 25978 085
- 8408070042 Forwards States of NC & SC responses to regional assistance committee findings on offsite radiological emergency response preparedness & exercise on 840215-16 State & local waters with the second state of the second
- 8408090056 Clarifies addl issues raised by NRC in 840626 telcon re New York PIRG petition to suspend DLs due to emergency planning inadequaties FEMA rept & State of NY response to FEMA 840611 It rencl KRIMM.R W Føderal Emergency Management Agency 84/07/31 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) ip 25992 335 24X Fiche 30-247.84/07/31, 8408090056
  - 3408090059 "Evaluation of Addl Issues Raised by NRC re New York PIRG Patition to Suspend Operation of Indian Point Units 2 & 3 " \* Federal Emergency Management Agency 84/07/26 10pp 25992 336 24X Fiche 50-247,84/07/31,8408090056
- --B408070061 "Addl Info Obtained From NY State on New York PIRO Petition Which Supple FEMA Rept to NRC dtd 840608 " \* Federal Emergency Hanagement Agency B4/07/26 Bpp 25992 346 24X Fiche 30-247,84/07/31,8408090036
- 8408090216 Forwards NRC comments re DDE draft "Mission Plan for Civilian Radwaste Mgt Program " NRC objections based on regulatory info needs, establishment of performance goals & need for additional consultation w/NRC Asselstine comments encl PALLADIND.N J Commissioners 84/07/31 RUSCHE.B C Energy. Dept of 59pp 25992 013
- 8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
  Svc 11st enc1
  JURDAN,E L pivision of Emergency Preparedness & Engineering
  Response (Post 830103) 84/08/13 Consolidated Edison Co of New
  York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13.6408100009
- 8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Cansolidated Edison Co of New York, Inc 118pp 26178 001 24x Fiche 50-000,84/08/16,8408100021
- 8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication "Syc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000.84/08/15,8408100038

- B40B100055 IE Info Notice 84-66. "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of N York Inc 120pp 26276 001 24X Fiche 50-000.84/08/17,840B1000
- B40B100060 Determines that, based on evaluation, State of WI & local plans for radiological emergencies adoquate BPECK. B W Federal Emergency Management Agency 84/08/02 DIRCKS, W J Office of the Executive Director for Operations 1p 25987 052 24X Fiche 50-293, B4/08/02, B40B100060
- B408130373 Testimony on training Contentions 39,40,41,44,98,99 & 100 Pp 101-111 Certificate of Svc enc! Related correspondence \* Federal Emergency Management Agency D9D 903 OL-3 84/08/06 14pp 26011 001 24X Fiche 50-322,84/08/06,8408130373
- 8408140208 IE Info Notice 84-67. "Recent Snubber Inservice Testing W High Failure Rates " Sc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of N Yors, Inc 122pp 26276 122 24X Fiche 50-000.84/08/17.84081403
- 8408190443 Response to Suffolk County motion for directed certificatiof ABLB 840710 order which denied Suffolk County request for production of documents dealt win ASLAB 840613 Order ALAB-773 Certificate of Syc encl Related correspondence OLASS, B M Federal Emergency Management Agency DBB 063 OL-3 84/08/10 Atomic Safety and Licensing Appeal Panel 14pp 26068 235 24X Fiche 50-322,84/08/10,8408130443
- 8408150535 Forwards request for CMB review & supporting statement re 10CFR50 concerning domestic licensing of production & utilization facilities NORRY,P G Office of Administration 84/08/09 MACRAE,J B Offi of Management & Budget 1p 26080 294
- 840Bi6004B Forwards draft interagency grogrammatic agreement re U mil tailings disposal sites Redroft contains new provisions re problems concerning low level radwaste mgt & language which commits NRC & EPA to seek legislative relief DAVIS.J G Office of Nuclear Material Safety & Safeguards, Director 84/07/25 CANNON.J. THOMAS.L Environmental Protection Agency 16pp 26128 146
- 8408140257 Forwards 840328,0419,0604 & 08 ltrs between EPA & NRC re EPA proposal to develop federal guidance &/or stds for decontamination & decommissioning of radioactively contaminated sites & facilities HARMON,D F Health Effects Branch (post 840429) 84/06/29 HARHARD,D Atomic Industrial Forum 1p 26125 174
- --8408160264 Requests participation in interagency working group B406 neeting re guidance &/or stds for decontamination & decommissioning of radioactively contaminated sites & facilities Minutes of 840625 meeting and SUBLOM. O L. Environmental Protection Agency 84/06/08 HARMON, D F. Office of Nuclear Regulatory Research, Director 15pp 26125:175
- --B408160271 Expresses approciation for opportunity to participate in B40430 meeting re decommissioning Confirms NRC view that decommissioning guidelines urgently needed WA Mills designated NRC representative to EPA interagency work group MINOOUE, R B Office of Nuclear Regulatory Research, Director B4/06/04 CANNUN, J A Environmental Protection Agency 2pp 26125 190
- --8408160275 Ack receipt of 840328 ltr inviting NRC to 840430 meeting development of criteria & guidance for decontamination & decommissioning of facilities NRC engaged in establishing residual radioactive contamination limits MINOOUE, R B Office of Nuclear Regulatory Research, Director 84/04/19 CANNON J A Environmental Protection Agency 2pp 26125 192
- --B408160280 Forwards proposed rule, changing Commission regulations i 10CFR20 to specify residual radioactive contamination limits for decommissioning; for comment MINCOUE, R B Office of Nuclear Regulatory Research, Director B4/02/23 FRALEV, R F ACRB - Advisory Committee on Reactor Bafeguards 41pp 26125 194
- --8408160288 Defers concurrence on proposed EPA guidance, "Federal Radiation Guidance on Dose Limits for Persons Exposed to Transuranium Elements in General Environ " Broader need exists for uniform & consistent guidance DIRCKG.W J Office of the Executive Director for Operations 83/09/09 ELKINS,C L Environmental Protection Agency 2pp 26125 235

- B408160292 Discusses need for stds.cliteria & guidelines to protect
  public? to direct decontamination & decommissioning
  programs Rulenaking investigation on problem initiated
  Requests 840430 meeting w/designee to discuss matters
  CANNON J A Environmental Protection Agency 84/03/28
  DIRCKS.W | Office of the Executive Director for Operations 2pp
  20125-237
- 8408160278 Forwards "Project Licensing Plan For UMTRAP Sites" For leview 5 concurrence MORLEY, J. A. Energy Dept or 84/08/07 HIGGINBOTHAM, L. Low-Level Waste 5 Uranium Recovery Projects Branch ip 26126-043
- --8408160283 "Project Licensing Plan for UMTRAP Sites \* Energy, Dept of 84/07/31 37pp 26126 044
- B40B160289 Discusses status of Fails City,TX inactive U mill site & plan of action Since current contractor due to lose license, DCE prepared to begin remedial action BAUBLITZ. J E Energy, Dept of 84/08/06 HJGGINBOTHAM, L Low-Level Waste & Uraniun Recovery Projects Branch 2pp 26124 348
- B40B200490 Forwards FEMA responses to 840629 interrogetories Certificate of Svc oncl Related correspondence MDCRF.J E Hearing Branch 1 DSB 174 UL B4/08/14 EDDLEMAN.H Eddleman. U Jpp 26135 321 24% Fiche 50-400,84/08/14,8408200490
- --8408200497 Response to interrogatories propounded by intervenor W Eddleman Related correspondence HANKINS.T I. RUCKLIS.S M Federal Emergency Management Agency GL 84/08/07 EDDLEMAN.W Eddleman, W 31pp 26136 324 24X Fiche 50-400.84/08/14.8408200490
- 8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26327 008 24X Fiche 50-000,84/08/21,8408210142
- 8408210341 Forwards order establishing schedule for offsite emergency planning issues W/o encl Related correspondence VOCLER, B H Hearing Branch 2 DBB 186 OL 84/09/16 PERRY, S Federal Emergency Hanagenent Agency 2pp 26179 361 24X Fiche 50-352-84/08/16,8408210341
- B40B210346 Forwards "Crystal River Nuclear Power Plant Exercise"
  Few Specific NURCO-0654/FEMA-REF-1.Rev 1.deficiencies
  abserved during B40425 emergency exercise State of FL &
  Citrus Levy counties participated
  KRIMM,R W Federal Emergency Management Agency B4/0B/13
  JONDAN,E L Division of Emergency Preparedness & Engineering
  Response (Post B33103) 2pp 26179 136 24X Fiche 50-302,84/0B/13,8408210346
- ~-8408210354 "Crystal River Nuclear Power Plant Exercise," # Federal Emergency Management Agency 84/05/11 42pp 261/7 138 24X Fiche 50-302,84/08/13,8408210346
- B408210408 Informs that FEMA does not intend to conduct full-scale evaluation of Hope Creek 1985 exercise Since Salem Unit 1 OL. issued prior to 820713, full participation in 1985 not required by NRC or FEMA rules KRIMMR W Federal Emergency Hanagement Agency 84/08/13 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 26177-256 24X Fiche 50-000, 84/08/13, 8408210408
- 84083202/4 Responds to 840716 ltr re NRC data on reactor scrams during 1983 that may conflict u/INPO data NRC figures viewed as entirely consistent u/INPO findings DIRCKS,W J. Office of the Frecutive Director for Operations 84/08/15 PATE,Z T. Institute of Nuclear Power Operations 2pp 26212 008
- --8409220302 Forwards 1963 reactor trip statistics compiled by Operating Reactors Assessment Branch Automatic trip frequency of 4 3 trips/plant/yr consistent w/industry study.
  EIEFNHUT.D G Division of Licensing 84/08/09 THOMPSON.H L
  Division of Human Factors Safety SPEIS.T Division of Safety
  Technology BERNERO,R M Division of Systems Integration (post 811005) 18pp 26212 010
- --8409220310 Expresses concern re NRC statistics showing increase in scrams for 1983, whereas INPO study showed decrease Clarification requested as discrepancy may have adverse affect on INPO crodibility PATE, Z T Institute of Nuclear Power Operations 84/07/16 DIRCKS, W J Office of the Executive Director for Operations 10pp 26212 028

- --8408230315 INPO 84-013
  'Reactor Trips in US Nuclear Power Plants "
  \* Institute of Nuclear Power Operations 84/03/31 19pp 26212 038
- 8408230300 Forwards RW Kremm 840711 ltr transmitting FEMA interim finding in State of CA emergency response plan Plan adequate Areas for improvement identified including protective action guideline doses KNIGHTON.G W Licensing Branch 3 84/08/16 SCHUYLER.J D Pacific Oas V Electric Co 3pp 26235 105 24X Fichs 50-275,84/08/16,8408230300
- 8408240354 Forwards "Nevada Nuclear Haste Storage Investigations Project.Monthly Rept.May 1984" VIETH.D.L. Energy, Dept. of 84/07/10 BENNETT.JW Energy, Dept. of ip 26253 205
- --8408240355 "Nevada Nuclear Waste Storage Investigations Project.Monthly Rept.May 1984 " \* Energy: Dept of 84/05/31 75pp 26253 207
- B408270050 Discusses concerns re "Determination of Radionuclide Solubility in Orounduater for Assessment of High Level Radwaste Isolation " Marked-up draft repts encl KELMERS.A D Oak Ridge National Laboratory FIN 8-0287 1409 84/08/15 BRODKS.D J Geotechnical Branch (Post 831001) 65pp 26258 246
- 8408270309 Informs of FEMA approval of State of WI emergency response & local plan Adequacy of public alerting & notification sysmust be verified per FEMA/NRC joint criteria in App 3 of NUREC-0654/FEMA-REF-1 PAPERIELLO, C. J. Region 3, Office of Director 84/08/22 REED, C. Commonwealth Edison Co. 2pp. 26239 197 24% Fiche 50-295,84/08/22,
- 8408270197 Informs that NRC representative will not be available to attend FEMA pressertise briefing W Shell will contact FEMA after NRC 840910 entrance & attend 840913 public critique Region III representation at FYS5 public critiques unlikely PAPERIELLO, C J Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/24 WEAVER W J Federal Emergency Management Agency 1p 26291 176 24% Fiche 50-266,84/08/24, 8408270197
- --8408270206 Forwards schedule for 1984 emergency exercise NRC representation at pre & post-exercise briefings requested WEAVER.W J Federal Energency Management Agency 84/08/16 KEPPLER.J G Region 3, Office of Director 33p 26271 177 2: Fiche 50-266.84/08/24.8408290197
- 8408270348 Responds to 840703 request for suggestions re preparation fifth Natl Energy Policy Plan Addressing of future natl electricity supply t projected mix of coal & nuclear power in supply recommended PALLADINO, N J Commissioners 84/08/15 HODEL.D P Energy, Dept of 1p 24311 247
- --8408290350 Requests proposals for strategies, programs & initiatives fo consideration during preparation of fifth Natl Energy Policy Plan (NEPP) Input requested by 840901 Fourth NEPP encl HOBEL. P February Dept of 84/07/03 PALLADING, N J Commissioners ip 26311 268
- --8408290352 DDE/S-0014/L
  "Natl Energy Policy Plan "
  \* Energy, Dept of 83/10/31 27pp 26311 269
- 8408270356 Forwards 20th joint quarterly status rept re emergency preparedness covering period through 840530 No delay in current licensing proceedings due to emergency preparedness issues
  BERNYHAL.F N Commissioners GIUFFRIDA.L D Federal Emergen Management Agency 84708/07 SIMPSON, A K Senate Environm Public Works ip 26310 311
- --8408290359 "NRC/FEMA Joint Quarterly Rept to Congress on Emergen. Preparedness, Through 840630 " \* NRC - No Detailed Affiliation Given \* Federal Emergency Management Agency 84/06/20 46pp 26310 312
- 8408300208 Forwards FEMA findings on State of FL & associated local emergency plans re plant DANCE. H C Region 2. Office of Director 84/06/05 WILGUB, W B Florida Power Corp 1p 26307 044 24% Fiche 50-302,84/06/05,8408300208

- J408300211 Approves State of FL / local plans & preparedness for aborting // protecting public in event of radiological emotigency Approval conditional on verification of alert & notification per App 3 of NUREG-0654/FEMA-REF-1, Rev 1 BPECV.S W Federal Energency Management Agency B4/02/15 DIRCKS.W J Diffice of the Executive Director for Operations 1p 24307 045 24X Fiche 50-302,84/06/05,8408300208
- 8408300222 Forwards request for QMB review & supporting statement re NRC Form 482, "Registration Cartificate, Medical Use of Bygroduct Matj Under General License" NDRRY, P. G. Office of Administration 84/08/21 MACRAE, J. B. Office of Management & Budget 1p 26331 298
- 8408300303 Forwards FERA "Cremise Rept on St Lucie Nuclear Power Plant Exercise on 840306" DANCE, H C Region 2. Office of Director 84/08/14 WILLIAMS, J W Florida Power Corp 3pp 26306 151 24X Fiche 50-335.84/08/14, 840830303
- 8408300315 Forwards correspondence from FEHA remarding evaluation of offsite emergency preparedness for 830517 exercise LEWISHR C Region 2. Office of Director 84/07/19 UTLEY.E E Carolina Power & Light Co 2pp 26/313 213 24X Fiche 50-324.84/07/19.8408300315
- --8408300319 Forwards "Brunswick Nuclear Power Plant Exercise on 830517."
  final rept
  KRIMM,R W. Federal Emergency Management Agency 84/06/19
  UDRDAN,E L. Division of Emergency Preparedness % Engineering
  Response (Post 830103) 8pp 26313 215 24X
  Fiche 50-324,84/07/19,8408300315
- --8408300323 "Brunswick Nuclear Power Plant Exercise on 830517," final rept \* Federal Emergency Management Agency 84/06/03 40pp 26313 223 24X Fiche 50-324,84/07/19,8408300315
- B40B30030B Forwards FEMA "Exercise Rept, Catawba Nuclear Station, B40215-16" DANCE:H C Region 2, Dffice of Director 84/06/25 TUCKER, H B Duke Fower Co 1p 2630B 264 24X Fishe 50~413,84/06/25, A40830035B
- 8408300427 Forwards FEMA "Ocones Nuclear Power Plant Full-Scale Local Exercise Conducted on 830406." Final rept DANCE.H C Region 2. Office of Director 84/07/11 TUCKER.H B Duke Power Co ip 26315 205 24% Fiche 50-269.84/07/11.

#### PR PROPOSED RULE

- 8408310247 Comments on proposed rule 10CFR70 re changes to StM mat1 control h accounting requirements for certain licensed facilities Requests extension of comment period by at least 3 months
  MCMRY,W R GA Technologies, Inc /General Atomic Co. 49FR4091
  84/05/25 Docteting & Services Branch 3pp 24716-358
- 8408020081 Comments on proposed rule IOCFR50 re limiting use of highly enriched U in domestic research & test reactors Requests &Orday extension of 840904 closing date for comments HANGC R Oregon State Univ . Corvallis. GR 49FR27769 84/07/26 Docksting & Servic Granch 2pp 25891 283
- 8408020085 Comments of proposed rule 10CFR50 re high entiched U/low entiched U Opposed rule due to lack of regard to formal comments received from listed companies Requests 40-day extension of comment period MLLSGN. HE Washington State Univ. Pullman. WA 49FR27749 OQ1 84/07/25 Docketing & Services Branch ip 25891 288
- 8408020088 Comments on proposed rules iOCFR2 & 90 re elimination of review of financial qualifications of electric Utils in OL reviews & hearing for nuclear power plants RASMUSERN, LC Kansas City Power & Light 49FR13044 039 84/07/26 Docketing & Services Branch 5pp 25891 325
- B4080P0110 Comments on proposed rules 10CFR30.40.70,71 % 73 re atatement of policy concerning response to accidents involving transportation of radioactive matl Type of on-scene assistance NRC uill provide not clear LACKER,D K Texas State of 49FR12335 006 B4/07/24 Office of the Secretary of the Commission ip 25891 030
- 8408020111 Comments on proposed rules 10CFR30.40.70.71 % 73 re statement of policy on MRC response to accidents occurring during transportation of radioactive matl Opposes statement LEWIS.M I Lewis.M 49FR12335 008 84/07/30 Office of the Secretary of the Commission 2pp 25892 259

- 840802012U Comments on proposed rules 10CFR30.40.70 71 % 73 restatement of policy on MRC response to accidents occurring during transportation of redioactive matl Statement ensures NRC coordination U/a++ected state agencies.DDE % FEMA TROSTEN.L II. LeBoeuf. Lamb. Leiby % MacRae 19FR12335 007 84/07/27 CHILK.S J Doc/eting % Services Branch 5pp 25892 300
- 8408070268 forwards chart reflecting NRR input to public comments received in response to 49FR16900, "Rev of Backfitting Process for Power Reactors"

  DENION.H R Office of Ruclear Reactor Regulation, Director 84/07/27 STELLO.V Regional Operations 5 Generic Requirements 15pp 25937 019
- --B405C00226 Requests consideration \* repts to changes designed to backfit procedures by B40706 SJ Chilks B40208 mano, public comments received in response to 48FR16900 \* list of oublic comments enci

  STELLO,\*\*\* Regional Operations & Generic Requirements B4706/10 BENTON.H R Office of Nurlear Reactor Regulation, Director DEVOUNG, R C Director's Office. Office of Inspection and Enforcement DAVIS.J C Office of Nuclear Material Safety & Bafeguards.Director 1p 25756 268
- --B404250191 Advises of Commission approval of NRC plan for mgt of plant-specific backfitting of operating power reactors (SECY-B3-321)
  CHILK.S J Office of the Secretary of the Commission 84/02/0E DIRCKS.W J Office of the Executive Director for Operations MESSENGER.G Diffice of Investigation 1p 25956-269
- --8404280010 Forwards add1 public comments on proposed rule 10CFR50 re consideration of revs to backfit procedures & revised list of comments SFELLO, V Regional Operations & Generic Requirements B4/06/20 DENTUN. HR Office or Nuclear Reactor Regulation, Director DEYOUNO, R C Director's Office, Office of Inspection and Enforcement OAVIS. J C Office of Nuclear Material Safety & Safeguards, Director 1p 25756-374
- 8408070284 Forwards UCS comments on proposed rules 10CFR2 & 50 re regulatory reform proposal concerning rules of practice. licensing of production & utilitation facilities NRC should sponsor round of depositions of all witnesses for hearings JORDAN W S Harmon & Weiss 49FR14698 031 84/07/30 CHILK, & Office of the Secretary of the Commission 24pp 25948 192
- 8408070344 Comments on proposed rule 10CFR50 re environ qualification Requests UCS comments be given full consideration due to deadline discrepancy CURRAN, D., JORDAN, H.S. Harmon & Welss. 47FR8445 84/07/31 PALLADINO, N.J., ASSELSTINE, J.K., BERNTHAL, F.M. Commissioners. 4pp.
- 8408070343 Comments on proposed rule toCFK50 re limiting use of highly enriched U in demestic research & test reactors Opposes rule due to cost to taxpayers & lack of commitment for funding proposed fuel changos
  HILBUR, L.C. Horcester Polytechnic Institute, Worcester, MA
  45FR27769 003 84/07/31
  Commission 2pp 25945 192
- 8408070346 Comments on proposed rule iOCFRSO re limiting use of highly enriched U in domestic research & test reactors Requests 30-day extension of comment period to allow discussion at training research & test reactor meeting RICHARDS.W.J. American Nuclear Society 49FR27769 84/07/27 Docketing & Services Branch ip 25945 194
- B40B070349 Comments on proposed rule 10CFR50 re use of low shriched U in research reactors Use of highly enriched U unnecessary & dangerous Switching to low enriched U will reduce danger LEWIS.M I Lewis, M 49FR27749 002 B4/07/29 Docketing & Services Branch ip 25945 199
- 8408070383 Advises that comment period extended to 840813 for proposed rule 10CFR50 re environ qualification of electrical equipment FR notice encl (HILK,8 J Office of the Secretary of the Commission 94/08/02 BELLIN Nuclear Information & Resource Service RUNKLE.J Conservation Council of North Carolina O'NEIL.J O'Neill, J 3pp 25947 068
- --8408070398 Proposed rule 10CFR50; "Environ Gualification of Electrical Equipment:Removal of 820630 Deadline " Rule extends comment period to 840813 CHILK, 5 J. Office of the Secretary of the Commission 84/08/02 3pp 25947 071

- B408070407 Comments on proposed rules 10/FR30.40 70 '1 \* 73 re NRC general statement of policy on response to accidents accurring during fransportation of radioactive matl Supports rules
  ZIMMERMAN S R Carolina Power 2 Light Co 49FR12335 007 84/07/27 CHILV.5 J Docketing J Services Branch 1p 25942 173
- 8408070413 Comments on proposed rule 10CFRP re-production or disclosure in response to subpoenss or demands of court of other authorities Rule would prohibit NRC employees or Former employees from producing info in files to General Counsel HANAUFR S.H. Interstate Amiesite Corp. 49FR28073 001 84/07/30 Office of the Secretary of the Commission 2pp. 29942 150
- B408080333 Comments on proposed rule 10CFR60 re disposa) of high level radwaste in geologic repositories Disagrees w/MRC re contents of site characterization plan MH Humphrey 840525 comments encil KALITOMSPI I Minnesota, State of 49FR5934 015 84/08/01 BROWNING.R Division of Waste Management App 25964 091
- --8408080334 Comments on suggestions for procedural changes in nuclear power plant licensing process Supports creation of ABLU screening boards
  HUMPHREY.H H . OLGON, J F . SENECHAL, M E Minnesota, State of 49FR11698 B46
- 8408080335 Comments on proposed rule 10CFR50 re limiting use of highly enriched U in domestic research // test reactors Rule should be redrafted after input from all affected parties obtained SPINRAD.B I Tous Wesleyan College, fit Pleasant IA 49FR27769 004 84/07/31 Docketing & Services Branch 9pp 25944 082
- 8408080340 Comments on proposed rule 10CFR73 re mod of protection requirements for spent fivel shipments Concurs w/conclusion that relaxation of rigorous safeguards on shipments warranted LEUNARD, J D Long Island Lighting Co 49FR23867 004 84/08/01 CHIL//8 J Office of the Secretary of the Commission 10pp 25963 301
- 8408090337 Requests comment period be extended until 841104 for proposed rule 10CFR50 re limiting use of highly enriched U in domestic research & test reactors DIMEGIOLO, A F Robod Island, State of 49FR27769 005 84/08/06 Office of the Secretary of the Commission 2pp 25971 041
- B40B130346 Comments on proposed rule 10CFH50 re-conversion of research reactors from highly enriched U fuel to low enriched U fuel Supports rule Conversion should be implemented as soon as possible RUGIN. J Venice Alliance for Survival 49FR27769 006 B4/0B/06 Docketing & Services Branch 1p 26010 317
- B40B130398 Package of two comments opposing proposed rule 10CFR9 re-production or disclosure in response to subportace or demands of courts or other authorities.

  CONNER.T B Conner & Hetterhahn \* LeBoeuf, Lamb, Leiby & MacRae 49FR2B073 B470B709 CHILK.S J Office of the Secretary of the Commission 7pp 26011 120
- 8408130402 Comments on proposed rule 10CFR9 re production or disclosure in response to subportas or demands of courts or other authorities Supports proposed rule. w/exception of minor change to delete "or forner employee" in Section 9 201
  BENNETH.J P Baltinore Cas & Electric Co 49FR28073 002
  Bocketing & Services Branch 1p 26010 188
- 8408140377 Comments on proposed rule 10CFR50 re conversion of research reactors from highly enriched U fuel to low enriched U fuel Bupports rule & requests implementation as soon as possible COHENI.D A Cohen. D A IND 49FR27769 007 84/08/05 Office of the Secretary of the Commission 1p 26041 164
- 8408140419 Submits second comment on proposed rule 10CFR50. "Environ Qualification of Electric Equipment Removal of 820630 Deadline "Comment based exclusively on info re Pilgrimm! Deadline should not be removed DDHERTY.JF Doherty.JF 49FR8445 022 84/08/10 Office of the Secretary of the Commission 15pp 26050 334
- 8408140420 Comments on proposed rules 10CFR2 & 50 re elimination of review of financial qualifications of electric utils in operating reviews & hearings for power plants Analysis of financial qualifications & operational safety encl 81LBERQ, J E Shaw, Pittnan, Potts & Trowbridge 49FR13044 040 84/08/10 Docketing & Services Branch 1p 26051 001
- --B40B140422 "Statistical Analysis of Financial Qualifications & Operational Safety for Electric Utils Operating Nuclear Power Reactors "
  \* CYGNA Energy Services 84/08/09 79pp 26051 002

- B40Bi603B2 Comments on proposed rules 10CFR2 % 30 re elimination of review of financial qualifications Opposes rule O'NEILL J Affiliation Not Assigned 49FR13044 041 84/08/13 Docketing % Services Branch 1p 26092 172
- 8408210314 Comments on proposed rule 10CFR73 re mod of protection requirements for spent rue! Supports any rule which would reduce transport & manpower costs, but unclear that proposed rule will accomplish that goal MANGUSI. J Transnuclear, Inc. 49FR23867 004 84/08/13 Docketing & Services Branch 2pp 26179 125
- 8408210349 Comments on proposed rule 10CFR50 re sufficiency of justification for continued operation for Misconsin Electric Power Co. Point Beach Nuclear Plant 1 & 11 Streamlining NRC licensing & regulatory roles inadequate in solving problems PRDUDMAN, 9 Wisconsin's Environmental Decade 49FR8445 023 84/08/10 Docketing & Services Branch 12pp 26179 183
- 8408210359 Comments on proposed rule 10CFR50 re limiting use of highly enriched V in domestic research / test reactors Urges MRC reconsideration due to absence of any indication of realistic threat of diversion
  WEOBT, W F California, Univ of Los Angeles, CA 49FR27769 008
  84/08/09 Docketing & Services Branch 2pp 26180 243
- 8408210432 Comments on proposed rules 10CFR2 & 50 re elimination of review of financial qualifications Discusses several instances of safety improvements not made because cost judged to be excessive O'NEILL, J O'Neill, J 49FR13044 042 84/08/12 NRC No Detailed Affiliation Given 1p 26181 297
- 8408220322 Comments on proposed rule 10CFR50 re use of highly enriched U in domestic research & test reactors Requests 60-day extension on connent period, to conduct careful analysis CQLLINS.PF KHC, Inc 47FR27647 84/08/15 Ducketing & Services Branch 1p 26194 054
- 8408220337 Comments on proposed rule 10CFR50 re limiting use of highly enriched U in domestic research & test reactors Recommends rule state exemptions from conversion to low enriched U may not be reason or excuse to add addl security requirements BRUGGER.R M Los Alamos Scientific Laboratory 49FR27769 009 84/06/07 Orfice of the Secretary of the Commission 3pp 26194 064
- 8408220343 Package of two comments on proposed rule 10CFR50 re conversion of nuclear research reactors from highly enriched U to low enriched U Supports rule MAHAFFEY, II Detroit, MI CAMPBELL, B End Nuclear Dumping in the Pacific 49FR27769 84/08/20 Docketing & Services Branch 2p; 26189 347
- 8408220348 Comments on proposed rule 10CFR50 re limiting use of U enriched to greater than 20% U-235 in domestic nonpower reactors Rule discourages all new nonpower reactor development in US NELSON G W Affiliation Not Assigned 49FR27769 011 84/08/08 Docketing % Services Branch 2pp 26189 349
- 8408220350 Comments on proposed rule 10CFR50 re conversion of research reactors from high enriched U to low enriched U fuel Supports rule CUSHNIR.H CEIP Fund, Inc. 49FR27769 010 84/08/14 Docketing Services Branch 1p 26189 317
- 8408230387 Comments on proposed rule 10CFR73 re vital islands policy NRC should stop uasting taxpayer & ratepayer dollars for politically motivated projects & concentrate on streamlining regulations

  CAPANG-DOLANDL Affiliation Not Assigned 49FR30735 001 84/09/17

  Office of the Secretary of the Commission 2pp 26205 310
- 8408270319 Comments on proposed rule IOCFR30 re rev of backfitting process for power reactors Supports rule Statutory basis would add dimension of policy stability & predictability to NRC administrative proposals GRIFFITH.J D Energy. Dept of 49FR16900 023 84/06/07 CHILK.S J Office of the Secretary of the Commission App 26242 307
- 8408270328 Comments on proposed rule 10CFR50 re highly enriched U conversion rule Supports conversion Conversion should be taken before fuel stolen & used to build atomic upapon DEGOLT, R Affiliation Not Assigned 4FR27769 014 84/08/23 Docketing & Services Branch 1p 26239 227

- i408270390 Comments on proposed rules 100FR2 t \$0 ie Nati Association of Util Regulators financial qualifications study Proposed rule raises genuine problems t should be weighed carefullu & deliberately \$0071.N Coalition for Responsible Energy Education 49FR13044 0438408/10 Docketing & Services Branch 1≥pp 26245 008
  - 49FR13044 043
- 8409280073 Package of two comments supporting proposed rule 10CFR50 re high enriched U conversion BLUMENTHAL.A Affiliation Not Assigned M18CHEL.A National Lawyers Guild, Los Angeles Chapter 47FR27769 84/08/24 Bocketing & Services Branch 29p 26261 126
- 8408290290 Decision in matter of rulemaking on storage & disposal of nuclear waste (waste confidence rulemaking) Served on 840827
  - Office or the Secretary of the Commission DSB 376 84/08/22 160pp 26291 001 CHILF, S J 445861372
- --8408270297 "Requirements for Licensee Actions to Disposition of Spent Fuel Upon Expiration of Reactor DLs," 10CFR50 & 51 final rule Discussion of environ impact of spent fuel storage not required CHILY,S J Defice of the Secretary of the Commission 44FR61372 B4/0B/42 37pp 26291 124 required
- 8408310139 Comments on proposed rule 10CFR73 re mod of protection requirements for spant fuel shipments Recommends that in absence of research on shipment no easing of requirement should be contemplated andulo de concemplateo KGCERA, R Kissouri, State of 49FR23867 005 84/08/22 Docketing & Gervices Branch 1p 26322 262
- B40B310141 Forwards comments on proposed rule 10CFR50 re limited use of highly enriched U in domestic research & test reactions. WEOST.N F California, Univ of Los Angeles, CA 49FR27769 008 84/08/21 PALLADING.N J Commissioners ip 26322 266
- 8408310154 Parkage of three comments supporting proposed rule OUBLIDISH Parkage of three comments supporting proposed rule
  10CFR59 re conversion of domestic research reactors from
  highly enriched to low enriched V fuels
  BOURAGSAL California, Univ of, San Francisco, CA RICE,R A
  California, Univ of, Berkeley, CA RUZ,R R California, Univ of,
  Riverside, CA 49FR27769 B4/08/27 Docketing & Bervices Branch
  3pp 26322 217
- 8408310212 Comments on proposed rule 10CFR5D re conversion of domestic research reactors from highly enriched to low enriched U fuels Supports rule Testimony presented to ACRS on 840612 enc l 49FR27769 020 HARFUE ISTER. D B4/0B/1A
  - D Affiliation Not Assigned 4 the Secretary of the Commission
- --8408310215 Testimony of DK Hafemeister re need to convert domestic research reactors from highly enriched to low enriched U fuels
  - · ACRS Advisory Committee on Reactor Safeguards Affiliation Not Assigned E4/06/12 App 26318 HAP EMEISTER, D SP318 110
- 8408310217 Comments on proposed rule 10CFR30 re conversion of research reactors using highly enriched U to non-weapons-grade fuels Supports rule Tastimony presented to ACRS on 840127 encl TAYLOR.T B Affiliation Not Assigned 49FR27769 018 84/08/24 Docketing & Services Branch ip 26318 158 Docketing & Services Branch 2431B 158 1 p
- ~-B40B310221 Testimony of TB Taylor re need to convert domestic research reactors from highly enriched to low enriched U fuels TAYLOR.T B Affiliation Not Assigned 84/01/27 11pp 2631B 139

#### PETITION FOR HULEMAKING

- 3408070312 Advises that on 840621.NRC approved petition for rulemaking PRM-50-83 governing emergency exercise frequency Expressus approciation for participation & assistance provided during cHLLK,S J Office of the Secretary of the Commission 47FR292 84/07/31 Office A National Emergency Management Association 25947 362
- 8408070319 Advises that on 840621, NRC approved petition for rulemaking PRM-50-34 governing emergency exercise frequency Expresses appreciation for participation & assistance provided during rulemaking CHILK,S J Office of the Secretary of the Commission 47FR907 84/07/31 Miller,R South Carolina, State of 1p 25944 160 47FR50918

- 8408370451 Petition for rulemaking PRM-7-2 requesting NRC institute rulemaking to amend 10CFR/9 to establish formal procedure For petitioning Commission to reconside decisions NAUTZ. J.L. Hanti. J.L. 84,07/25 Office of the Secreta Commission 8pp. 20942-251 Office of the Secretary of the
- 0408070153 Forwards petition for fulrmaking PRM-20-15 re disposal of raduaste oil from nuclear power plants below regulatory
- EduSER.M A Neuman & Holtringer 84/0//31 Docketing & Services Branch 2pp 25940 097
- --B40B07045/ Petition for rulemaking PRM-20-15 re disposal of low level raduasts oil from huclear power plants requesting radionuclide concentrations in waste oil be disposed of w/o regard to radioactive mati content # Edison Clectric Institute # Utility Nuclear Waste Management Group 84/07/31 Commissioners 20pp 25940 099
- B408130555 Forwards comments re staff review & proposed resolution of Nuclear Util Backfitting \* Reform Group petition for rulemaking PRM 50-36 DENTON, HR Defice of Nuclear Reactor Regulation, Director 84/08/03 HORRY, P G Office of Administration 7pp 26059 231
- ~~B408130560 Forwards Nuclear Util Backfitting & Reform Group potition For rulemaking PRM 50~36. summaries of staff comments, status of sulemakings & proposed resolutions NURRY.P C Office of Administration CL~B3-43 84/06/26 NORMY, P.C. Office of Administration GL-83-43 84/00 HELTEMES, C.J. Director's Office DAVIS, J.C. Office of Material Safety & Sareguards, Director DENTON, H.R. Of Nuclear Reactor Regulation, Director 7pp 24039 238 Office of Nuclear HR Office of

# PROJ PROJECTS - PREDOCKET LICENSING

- 8408070036 Summary of 840718-19 meetings w/LLL.Swanson.Chem-Nuclear. Fracture Control.TVA.VEPCO.Gesellschaft Nuclear Svc & BNWL In Livermore CA re rev to CASTOR It dry spent fuel storage cask ISFSI topical rept
  ROBERTS J P Advanced Fuel & Spent Fuel Licensing Branch
  ROUSE C Advanced Fuel & Spent Fuel Licensing Branch B4/07/30
- 8408090552 Forwards Rev 1 to "QA Handbook for Dry Spent Fuel Storage Cask," per 831221 request re 830929 submittal of Rev 2 to "Topical SAR for Gastor IC Cask ISFSI (Dry Storage)" "AATX,H, RITISCHER.D Gesellschaft fuel Nukloar Service, mbH 23891 84/07/23 ROUSE,L C Advanced Fuel & Spent Fuel Licensing BAATZIN , KITTSCHER, D 23891 84/07/23 ROUS Branch 1p 25983 054
- --B40B090364 Rev I to "GA Handbook for Dry Spent Fuel Storage Cask " BITTNER.R Gesellschaft fuer Nuklear Service, mbH 23B91 B4/06/27 52pp 25983 055
- NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE PT21
- 8408020232 Corrected Rev 1 to Final Deficiency Rept DER 83-55 re OBOQUOS: Corrected Nev 1 to Finel Deficiency Rept DER 83-56 re discrepancies w/MSIV Mig by Anchor-Darling Initially reported on 830808 Vendor Instruction Manual E9023-9 revised Also reported per Part 21 VAN BRUNT.E E Artzona Public Bervice Co DER 83-56 84/07/13 BISHOP.T W Division of Resident-Reactor Project & Engineering Programs 7pp 25898 046 24% Fiche 50-598.84/07/13,8408020232 VAN BRUNI, BISHOP, T W Di
- 8408070233 Potential Part 21 rept re defective threaded rod me supplied by Texas Golt Co on 840618 Rods returned to vendor for replacement Nonconformance Repts 84-187 t. 84-205 enci LEE,O R Public Service Co of Colorado P-84244 84/07/5 Director's Office, Office of Inspection and Enforcement 15 23948 304 24% Fiche 50-267, 81/07/30, 8408070233 84/07/30
- B408070012 Final Deficiency Rept DER 84-08 re failure of ITT/Barton Model 743 transmitters to meet specs PPS setpoints revised on existing transmitters & Barton working on physical mod to meet specs Also reportable under Part 21
  VAN BRUNT, E E Aritona Public Service Co DER 84-08 84/07/24 8138HDP, T W Division of Resident, Reactor Project & Engineering Programs 4pp 28979 Oit 24% Fiche 50-528,84/07/24.8408090012

- 8408090055 Interin deficiency rept. Item 13; re weldolets lacking complete chemical analysis documentation Initially reported on 840827 Fornective action to be determined upon completion of three-tigation Reported under Part 21 by Goyon Alloys JENS.N H Detroit Edison Co 131 84/07/24 MEPPLER.J G Region 3. Office of Director 2pp 25992 333 24X Fiche 50-341.84/07/24.8408070055
- 8408090366 Deficiency t Part 21 repts. Item 179 re Westinghouse not considering interaction scenario when postulating in-core flux mapping sys [nitially reported on 840622 Reportability to be determined by 840930 PARSONS, R M Carolina Power & Light Co NRC-241 84/07/19 O'REICLY J P Region 2. Office of Director 1p 25992 146 2/ Fiche 50-400.84/07/19.8408090066
- B40B0901i4 Part 21 rept re twisted shielded pair cable in Nutherm Intl, Inc Analog Trip Cabinets C222BA1, C222BA2, C222BB1 & C2229B2 Initially reported on 840713 Caused by poor workmanship Cables exhibiting defects replaced MARRINGTON, W D Boston Edison Co BECO 84-105 84/07/13 MURICY, T E Region 1, Office of Director 3pp 25992 242 24X Ficne 50-293, 84/07/13, 8408090114
- 840B090131 Interim deficiency & Part 21 repts. Item 178 re stainless steel sockolettes & weldolettes supplied by Guyon Alloys. Inc not in accordance u/MCA 3800 Initially reported on 840A19 Next rept by 840915 PARBONS.R M Carolina Power & Light Co NRC-239 84/07/16 0'RCCLUY.J P. Region 2. Office of Director 4pp 25994 320 24: Fiche 50-400.84/07/16.8408090131
- 8408090148 Final Deficiency Rept ERDC 92(84)] re potential problem w/standby diesel generator loose flexible coupling drive hubs supplied by TDI Initially reported on 840120 Also reported per Part 21 EDELMAN, II R Cleveland Electric Illuminating Ce ERDC 92(84)] 84707/27 KEPPLER. J G Region 3. Office of Director 2pp 25993 176 24% Fiche 50-440.84/07/27.8408090148
- 8408090279 fourth interin deficiency rept re makeup HPI pump vibration Initially reported on 830622 Cause not stated Pumps balanced A vibration level measured Next rept expected by 841119 Also reportable per Part 21 cll.65.L M Tennessee Valley Authority 84/07/20 O'REILLY.J P Region 2, Office of Director 2pp 25994 161 24X Fiche 50 430.84/07/20.8408090279
- 840B100C()<sup>5</sup> Interim derictency rept re Cracked bosses on Colt Industries diesel generator lube oil pump discharge noziles Initially reported on G404E<sup>5</sup> Design for tapered thread adapter changed Nest rept expected by 840B07 Reportable per Part 21 MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey 84/07/18 MMREY.T.E. Region 1. Office of Director 2pp 25940 198 24x Fiche 50-354,84/07/18,840B1000B5
- 8408100118 Final deficiency rept re excessive wear on Pacific Air Praducts Thear converters Initially reported on 840213 Dosign of converters satisfactory for dampers Also reportable per Part 21 Not reportable per 10CFR30 58(e) MANOAN, C V Niagara Mohawk Power Corp NIP2L 0115 84/07/30 BTAR081FCKLR Division of Project & Resident Programs 2pp 29488 253 24x Firms 50-410,84/07/30,8408100118
- 0408(3019/ Updated Part 21 rept re calculational errors in original design initially reported on 840705 More detailed & less conservative analysis being performed to verify compliance w/specified allowables Waxt rept expected by 840901 GODFREY, D.A. M.J. Woolley Co. 84/08/01 KEPPLER, J.G. Region 3, Office of Director. 1p. 26010 026
- D408130210 Part 21 Rept 21-84-10 re potential functional problem w/transmitter amplifier board supplied by Rosemount Inc as spare part or part within complete Model 1153. Series Bitansmitter Rosemount 840718 itr informing of defect encl IMALL.D P Illinois Power Co U-10184 84/07/30 KEPPLER.J G Region J. Office of Director 5pp 26008 198 24X Fiche 50-461.84/07/30.840813023B
- 0400140461 Ack receipt of Part 21 rept re-potentially defective personnel neutron destretors Requests resolution of problem, plans to disseminate info to potentially affected customers & steps planned or taken to prevent recurrence BAER, R. | Engineering & Conent. Communications Branch 84/08/03 TODD.W.C. Sienons Commasonics, Inc. 3pp. 26061-286 24X Fiche 50-077,84/08/03.8498140461
- 8408160061 Final Deficiency Rept PRD-84/10 re possible swelling of OH Battis valve actuator ethylene propylene rubber elastomer seals in contact u/hydrocarbon lubricant Initially reported on 840/30 Reportable under Part 21 for Unit 1 RICHARD, J B Mississippi Power & Light Co PRD-84/10 84/08/03 0/RFILLY, J P Region 2, Office of Director 5pp 26108 217 24) Fiche 50-416,04/08/03,8408160061

- 8408160066 final deficiency rept re loose drive hubs on overspeed governor drive shaft on TDI diesel engines Initially reported on 840203 Hubs acceptable Also reportable under Part 21 HILLS.L M Tennessee Valley Authority 84/08/03 O'REILLY.J P Regio. 2 Office of Director 2pp 26108 224 24% Fiche 50~438.84/08/03.8408160086
- 8408160421 Fina) Deficiency Rept PRD-81/17 re flow rate in standby svc water sys loops A & B & loss of standby svc water basin transfer capability Initially reported on 810303 Also reportable per Part 21 RICHAYD. J B Mississippi Power & Light Co AECM-84/0341 84/07/31 0'REILLY. J P Region 2. Office of Director 5pp 26106 076 24X Fiche 50-416.84/07/31.8408160421
- 8408160438 Interin deficiency rept. Item 175 re exceeding max bolt hardness values initially reported on 840517 Corrective action \* submission of final rept will be accomplished by 840926 Also reportable per Part 21 PARSONS R Carolina Power & Light Co NRC-243 B4/07/24 UREILLY.J P Region 2. Office of Director 4pp 26106 343 24X Fiche 50-400.84/07/24.8408160438
- B40B160443 Interim deficiency rept. Item 168 re 6 9-kV switchgear circuit breakers Initially reported on 840420 Corrective action 2 submission of final report will be accomplished by 841001 Also reportable per Part 2: PARSONS.R M Carolina Power & Light Co NRC-246 84/07/30 0'REILLY.J P Region 2. Office of Director 5pp 26107 268 24X Fiche 50-400.84/07/30.8408160443
- 8408160480 Final Deficiency Rept DER 84-16 re ESF actuation sys relay cabinet baseplates Initially reported on 840321 Cabinet backs will be reinforced w/3/8-inch thick vertical stiffener plate Also reportable under Part 21 VAN BRUILT, E Arizona Public Service Co ANPP-30105-TDS/84/08/02 BISHOP, TW Division of Resident, Reactor Project & Engineering Programs 4pp 26107 272 24X Fiche 50-528.84/08/02, 8408160480
- 840B1703B4 Final Deficiency Rept DER 84-22 re control element assembly shroud support contaminated w/oil Initially reported on 840420 Shroud cleaned & inspected & drip pan installed to contain possible leakage Also reported per Part 21 VAN BRUNT.E E Arizuna Public Service Co DER 84-22 84/08/01 BISHDP.T W Division of Resident, Reactor Project & Engineering Programs 4pp 26127 079 24X Fishe 30-328, 84/08/01, 840B170384
- 8408200307 Suppl 7 to Part 21 rept re possible thermostatic valve malfunction fail safe to full cooling position Lower overrun assemblies in Robertshau valves installed on diesel generator sets replaced U/cotter pins to lock nut to stem MORIARTY. JM Colt Industries, Inc 84/08/08 KEPPLER. J O Region 3. Office of Director 1p 26133 017 24X Fiche 50-352,84/08/08. 8408200307
- B408200332 Part 21 rept re tension wires on Titus Grille, Model 272, not renaining in place when deflection blades closed Affected job sites identified in encl Products being tested to provide acceptable fix for retention SCHNEIDER.S L Phillips Industries. Inc B4/08/07 Director's Office, Office of Inspection and Enforcement 3pp 26133 315 24X Fiche 50-000.84/08/07.8908200332
- 8408200333 Pert 21 rept re tension wires used for adjustment of blades on Orille Model 272 not remaining in place when blades closed Review & testing conducted to identify number of grilles & rework methods to be utilized SCHNEIDER, S. L. Phillips Industries, Inc. 84/08/07 STRAIT, R Artiona Public Service Co. 19. 26132 360 24X Fiche 50-528,84/08/07,8408200333
- 8408200338 Part 21 rept re tension wires used for adjustment of blades on Orille Model 272 not remaining in place when blades closed Review & testing conducted to identify total number of grilles & rework methods SCHNEIDER.S L. Phillips Industries, Inc. 84/08/07 USINGER.R Zack Co. 1p. 26132 356 24% Fiche 50-461,84/08/07,8408200338
- 8408210278 Part 21 rept re separation of rod eye connected to piston rod from threaded portion of piston rod at apprex 750,000 lb stress load Caused by insufficient matl thickness to withstand faulted load that certification encl MILLS.C.R. Chicago Fluid Power Co. 84708/16 Director's Office. Office of Inspection and Enforcement 4pp 26180 347 24X Fiche 50-282,84/08/16,8408210278

- 8408220143 Interin Deficiency Rept DER 84-44 re fatigue failures of Gaulin charging pumps Initially reported on 840706 Bechtel investigating Final rept to be completed by 840927 Reported under Part 21 by Northeast Utils

  VAN BRUNT E E Arijona Public Service Co ANPP-30128-TDS/
  84/G8/06 BISMOP.T W Division of Resident, Reactor Project & Engineering Programs 3pp 26188 065 24x Fiche 50-528-84/08/06, 8408220143
- B40B2Q0317 Part 21 rept re failure of ITE 27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diode must be added Arfected units listed DUVALL.D D Brown Bover: Corp (subs of Brown Bover: % Co., Ltd.) PT21 84-170-000 B4/03/13 DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 3pp 26191 357 24x Fiche 50-000.84/03/13.8408220317
- 8408240313 Part 21 rept re fitting leaks at incore probe seal tables at PWRs.per 16 info Notice 84-55 Subj fittings not used as instructed HILSON, 8 Crauford Fitting Co [EIN-84-55 84/08/13 JORDAN, E L Division of Energency Preparadness & Engineering Response (Post 830103) 2pp 26725 313 24% Fiche 50-327, 84/08/13, 8408240313
- 8408240332 Submits annotated requests for followup on potentially generat problem an encl Part 21 rept from Basier Electric re SCRs on nuclear exciters mounted w/too much pressure NORELIUS.C E Division of Project 3 Resident Programs 84/04/25 JORDAN.E L Director's Office, Office of Inspection and Enforcement 19 26225 303 24X Fiche 50-000.84/04/25,8408240332
- 8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scran pilot solehold valve plunger Initially reported on 840413 New thread locking devices investigated SHERHOOD. G General Electric Co MFNM 041 84/04/13 DEVOUNG.R C Director's Office Office of Inspection and Enforcement 3pp 26222 236 24% Fiche 50-000.84/04/13 8408240348
- 8408280127 Part 21 rept re defects in 18-inch SA-333 RHR pipe Samples of defective pipe matt being shipped to Techninat Corp.per request Defects located in one length of SA-333 Gradp 6 pipe CROSBY, GE Northern States Power Co SPLM-794 84/08/22 COLLINS.J NRC - No Detailed Affiliation Given ip 26275 144 24% Fithe 50-263,84/08/22,8408280127
- 8408300521 Final rept. Significant Const Deficiency 115 to unacceptably AUSGOUGE Final reptibignisticant const pericipacy 115 to una high fluoride levels in Micro-Lok Insulation supplied by Johns-Manville Condition not reportable under IOCFR50 55(e) Apparently reported under Part 21 by Johns-Manville GERRETS, I F Louisiana Power & Light Co. 115 84/08/20 COLLING, J T. Region 4, Office of Director. 3pp. 26313-33 26313 359 24% Fiche 50-382,84/08/20,8408300521
- 8408310110 Significant Deficiency Rept 14B re design calculations made by NJ Moolley Co for doers specified to meet tornado-generated missile criteria Door reanalysis underway Previously reported under Part 21 by NJ Moolley Co KEMPER, J S Philadelphia Electric Co (SDR #14B) B4/08/23 MURLEY, T E Region 1. Office of Director 1p 24322 239 24X Fiche 50-352,84/08/23,8408310110
- B408310160 Part 21 rept re ground fault failures of actuation scienoids for Crosby safety relief valves PRC 84-24 Problem still considered germans condition Memo of 840808 telcon updating
- 8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Hemo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition VILLA-R Gameral Electric Co MFN# 117-84 84/08/21 R0881, C E Director's Office. Office of Inspection and Enforcement 3pp 26318 327 24% Fiche 50-000,84/08/21,8408310186
- **GA999** QUALITY ASSURANCE INSPECTIONS
- 8405300191 Ack receipt of 840503 ltr informing NRC of steps taken to correct nenconformance noted in QA Program Insp Rept 97900833/84-01 Corrective actions will be reviewed during Puture insp POTAPOVS.U Region 4. Office of Director 84/05/22 MEISSNER, F N Electro Switch Corp 1p 24699 257
- 8408010364 Forwards GA Program Insp Rept 99900823/83-01 on 830613-17 & notices of violation t nonconformance PDTAPOVS.U Vendor Program Branch 83/11/18 THOMAS.A Diversified Threaded Products Co. 3pp 25866 272

- --8408010364 Nutsice or lipidation from inspire 830613-17

  \* Vendor Program Blanch #3/11/18 1p 25866 69
- --8408010369 Notice or noncontermence from insp on 830813-17 Safe4 \*\* '
  into deleted (ref 100FR2 790)
  \* Vendor Program Branch 83/11/18 4pp 25866 296
- --840B010372 GA Program Insp Rept 99900823/83-01 on 83C613-17 Noncompliance noted posted Part 21 guidance outdated (B21230 / procedures to evaluate deviations did not exist Safeguards into deleted (ref 10CFR2 790) CCNNAY, J T BARNES, I Vendor Program Branch 83/08/20 5pp 25866 200
- 8408030021 Forwards Updating Status Memo 20 for Nuclear GA Program Manual ETR 1001, summarizing changes made
  TENZER, B E Ebasco Services, Inc. (subs. of Enserch Corp.
  84/07/24 POTAPOVS, U Vendor Program Bianch 4pp. 259
- B408030037 Responds to NRC 840413 ltr rc nonconformance noted in GA Program Insp Rept 97900831/84-01 Corrective actions random review of patrol insps to be conducted patrol insp items listed \* parts assembled at work station inspected CHRISTOPHER.T Nestinghouse Electric Corp 04/0//09 POTAPOVS U Vendor Program Branch 5pp 25907 043
- B40B030U41 Responds to NRC 840618 ltr re nonconformance noted in GA program insp rept Corrective actions annual review 1 rev of Natl Technical Sys GC nanual will be completed by 840B01 HARTMAN.W C National Technical Systems 84/0//17 PDTAPDVS.U Vendor Program Branch 3pp 25907 031
- B408030089 Responds to violation & nonconformance noted in QA program insp on B40417-19 Corrective actions drawing forms revised to conform to practice of one signoff on lev block & testers instructed on proper operation of ITE 27 relays
  DVVALL,D D Brown Boveri Coip (subs of Brown Bover; & Co., Ltd.)
  B4/07/16 POTAPOVS,U Vendor Program Branch 2pp 25910 074
- B408030115 Responds to 840529 ltr reproblems identified at Bahnson Co Winston-Salom Facility (to HVAC equipment received from subj facility Bahnson to solicited to assess or to take any needed actions to improve GA program CLEMEN15.8 R Texas Utilities Electric Co (formerly Texas Utilities Congrating Co) TYX-4238 84/07/23 DEYCUNNO.R ( Director's Office Office of Inspection and Enforcement Ppp 25916 104 24x Fiche 50-445.84/07/23.8408030115
- 8408930133 Responds to NRC 84061B lir re nonconformances noted in QA Program Insp Rept 97900500/84-01 Corrective actions new Procedure 18-2 9 issued to consolidate & enhance requirements for tracking.closing & mgt actions REINSCREACO Bechtel Corp 84/0//10 POTAPOVS.U Vendor Program Branch 2pp 25916-141
- 8408030136 Responds to 840527 Fir re 840504 response to nonconformances noted in GA Program Insp. Rept 99900809/04 Ot on 040606-10 Nonconformances do not indicate failure of program to comply w/Reg Outde 1 144 & ANSI N45 2 12-1977
  KELLY,R B Stone & Nebster Engineering Corp. 84/07/20 POTAPOVS, U Vendor Program Branch 4pp. 25916-137
- 8408030143 Responds to NRC 040628 lti re nonconformance noted in QA Program Insp Rept 99700507/84-02 Corrective artions Mechanical Std MAS-22 revised on 840625 to \*pecifically address use & documentation re engineering judgment TAYLOR: N S Sargent & Lundy, Inc. 0047-00 (14707/27 POTAPOVS. U Vendor Program Branch 8pp 25915 307
- B408030165 Responds to NRC notice of nonconformance noted in QA programinap at Bland Operation on 040307 10 Corrective actions QAP 2 3 revised to indicate 2-wk training session by QA supervisor X experienced QC personnel DUVALL.B D Brown Bovert Corp (subs of Brown Bovert & Co. Ltd.) B4707/18 POTAPOVS.U Vandor Program Stanch 4pp 25915 345
- 8408030175 Responds to NRC 840530 ltr re deviations noted in QA Program Insp Rept 99900884/83-01 Corrective actions Texas Flange Dividence requested to invoke Code Case N 242-1 for deficiencies identified in NRC 840530 ltr BLANKLEY. OF Amelek. Inc. 84/07/71 POTAPOVS. U Vendor Program Branch 26pp 25916 005
- 8408050043 Ack receipt of 840426 & 0706 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp. Rapt 79700911/84-01 Another insp. necessary to resolve outstanding findings from NRC 840330 ltr ZECH.O G Vendor Program Blanch 84/08/02 BRUGGEMAN,W H Gene Clectric Co 1p 25933 102 84/08/02 BRUGGEMAN,W H General

- onfirms Ge program insplat San Jose CA plant on 840813-17 יים ארורה שא program insp ar San Jose CA plant on B40B13-17 אלט Si telson יים endor Program Br, nch האלט SHIRLEY.N C General אור ביים וף ב-1925 31B
- 3 31 Act receipt or 840214.0329.0615 & 0713 ltrs informing NRC PP, taken to correct de lation noted in GA Program Insp 74900277/83-04 + 99900277/83-04 PEED, E Rockbestos
- (7) Pesponds to URC 840709 ltr re nonconformance noted in QA im Inep Rept 99900053/84-Di Corrective actions all nes in-house nodified to install new gaskets there is notified of problem CP.G W. Anchor/Darling Valve Co. (subs. of Anchor/Darling Eller, Inc.) 84/07/20 POTAPOVS, U. Vendor Program Branch mers notified CP, CW Ancho diles, Inc.) 25/49 339
- ,117 Responds to Item G of QA Program Insp Rept 99700617/84-01 active actions program implemented to require weekly gulation of data tron data repts to provide electronic fer of info on two dissettes
  SDN:SF National Board of Boiler & Pressure Vassel Inspectors 7/17 PUTAPOVS.U Region 4. Office of Director ip
- p 170 Forwards announcement of organizational changes, per 831019; hanges will be incorporated in next amend to √R-17A; [Si.N.N. Olbbs & Hill, Inc. (subs. of Dravo Corp.) 84/07/25 ≠CVS.U. Region 4, Office of Director 3pp. 25949 270
- Oibbs & Hill. Inc. (subs. of Dravo Corp.) 64 Region 4. Office of Director 3pp. 25949 270
- Amends response to 840716 ltm re nonconformance noted in QA 7331 Amends response to 840/16 ftr re nohconformance noted in Gram Insp Rept 99900743/84-01 Relay identified as ITE-27 Ld be ITE-32D LLD Brown Bover: Corp (subs of Brown Bover: & Cor, Ltd ) 7/23 POTAPO/S.U Region 4. Office of Director 1p 7/30°
- D-334 Responds to NRC B31205 ltr re-nonconformance noted in GA nam insp Repts 99903277/83-02 / 83-04 Extension of price date to 840215 requested Cable classifications will equalified LEHALTS 0 Rockbestos Co 83/12/27 PDTAPOVS U Region 4-C+ of Director 2pp 25945-233
- ODBY Confirms QA program insp at Pagenizville.PA plant on 200-24, per 840802 telcon , G G Vendor Program Branch 84/08/03 MEIDER,P Phoenix 1 Corp ip 25747 067
- O466 Suppls 840214 response to NRC ltr re nonconformance noted in rugram lnsp Ropt 99900277/83-02 Corrective actions carting data qualification rept organized by file to be ity letrievable
  LEHALCS 0 Rockbestos Co 84/03/29 POTAPOVS V Rogion 4. Ce of Director 2pp 25940 334
- IC 946 Ack receipt of 840716 request for extension of time to 117 for Power Breakers.Inc to respond to NRC 840611 ltr IA Program Rept 979703832/84-01 Extension acceptable I. 0 0 Vendor Program Branch 84/08/03 FLOOD.R W General tric Co 1p 25961 338
- NO.350 Folwards QA Program Insp Rept 99900387/84-01 on 840423-27 re rmittent lock-up problems in RM23 radiation monitoring display channel Item AITS F02700335 closed W/o encl 4, 9 G Vendor Program Branch VITS 83-075 84/08/06 IS.R C Division of Project & Resident Programs ip 25964 360
- 30114 Ack receipt of 840706 ltr informing NRC of steps taken to sect nonconformance & violations noted in QA Program Insp t 9990841/84-01 Addl info requested re failure to use - ,,,,oudri/OH-VI Add 1 )Rfo requested re Paillore to use
  Jest for deviation form
  1, 0 G Vendor Program Branch 84/08/03 RICHARDS, A C GNB
  Leries, Inc. 2pp 25962 001
- 30130 Ack receipt of 840412 & 0712 ltrs informing NRC of steps #10130 Ack receipt of 840412 & 0712 ltms informing Nic or En to correct nonconformance noted in GA Program Insp \$ 99900404/84-02 Responses to violations require add1 % aw / will be covered in future insp % 4,0 G Vendor Program Branch 84/08/03 GALLAGHER, J L % inghouse Electric Corp 1p 67473 144
- BO21B Forwards GA Program Insp Rept 999003B7/84-01 on 840423-27 & tice of nonconformance Description of steps taken to heat? prevent recurrence of deficiencies in GA program trested W/o encl APD/S, V. Region 4. Office of Director B4/06/11 BIJARCHI, 1 heathnologies. Inc /Oeneral Atomic Co. 2pp. 25975 014

- 8408080287 Contirms GA program insplat Streamwood, (L plant on 840877-31 per 840803 telcon ZECH.G., Vendor Program Branch 84/08/06 FRANZEN,J Chicago Fluid Power Co. 1p. 25765-267
- B40BD30306 Ack receipt of B40713 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900387/84-01 Implementation of corrective actions will be reviewed during future insp ZECH. G 6 Vendor Program Breach 84/08/03 BIJARCHI. 1 GA Technologies, Inc /General Atomic Co 1p 25964 114
- 8408080308 Act receipt of 840113 & 0402 ltrs informing NRC of steps taken to correct inconsistency noted in QA Program Insp. Rep. 79900283/83-02 List of customer audits & list of customers supplied w/safety-related cable requested ZECH.O.G. Vender Program Branch 84/08/06 MANCHESTER.E BIW Cable Systems, Inc. 2pp. 25964 112
- 8408080311 Ack receipt of 840606 ltr informing NRC of steps taken to correct nonconformance hoted in QA Program Insp Rept 99790821/83-02 Addl info re setanic qualification b documentation of dedication process required ZECH.O O Vendor Program Branch 84/08/03 HINKLEMAN, L. O Bachtel Corp ip 25964 111
- 8408080336 Confirms GA program insp at Sam Jose,CA on 840827-31.per BAGBUG telcon
  ZECH O G Vendor Program Branch 84/08/06 SHIRLEY,N C General
  Electric Co ip 25964 081
- 8408080341 Ack receipt of 840525 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99700403/84-01 QA Program Insp Rept 99700291/84-01 Of Johnson Controls, Inc Should be referenced ZECH-Q O Vendor Program Branch 84/08/06 BRUGGENMAN, W M General Electric Co 1p 25963 289
- B408090002 Informs that corrective steps taken re nonconformance noted in GA Program Insp Rept 99900399/84-01 Test program completed w/satisfactory results MADDIAN.A Anerican Insulated Wire Corp B4/07/30 POTAPOVS.U Region 4. Office of Director ip 25973 112
- B408070006 Confirms OA program insplat Wilmington NC plant on 840813-17. per 840723 telcon ZECH, O G Vendor Program Branch 64/08/07 LONG, J.A. General Electric Co. (p. 25973 007
- 8408090063 Ack receipt or 840627 ltr informing NRC of steps taken to correct nonconformance & violations noted in QA Program Insp Rept 79700786/84-01
  ZECH.O G Vendor Program Branch 84/08/Q7 DEVAULT, E N General Electric Co Lp 25972 299
- 8408090174 Confirms GA program insp at Wrentham, MA plant on 840910-14. per 840803 telcon ZECH, D G Vender Program Branch 84/08/07 GREEN, J J Crosby Valve & Goge Co 1p 25972 285
- 8408090181 Ack receipt of 840621 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900259/83-02 Corrective actions will be examined during between teen future insp ZECH,O O Vendor Program Branch 84/08/07 POTEEY,W R Combustion Engineering, Inc. lp 25973 183
- B408090190 Ark receipt of B40622 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900300/84-01 Listed info requested within 25 days of ltr date ZECH, C G Vender Program Branch 84/08/08 MGRIARTY, J M Colt Industries, Inc. 19 29973 184
- 8408100033 Forwards QA Program Insp Rept 99900743/84-01 on 840821, for info & action Return receipt requested W/o entl JOHNSON, E H Region 4. Office of Director 84/08/06 CAHILL, H J Guif States Utilities Co 2pp 25990 168 24X Fiche 50-458,84/08/06,8408100033
- 8408100097 Forwards QA Program Insp Repts 79900387/84-01 & IOBLODGY Forwards GA Program Insp Repts 79700347784-01 & 9790040784-02 Requests evaluation of significance of reported fundings re quality & acceptability of product or svc provided by vendor I//o encl HUNTER, D. R. Region 4. Office of Director 84/08/03 SPENCE, M. D. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.) Rep. 2597) 014 247 Fiche 50-445,84/08/03,8408100097

- B40B10010<sup>T</sup> Forwards On Program Insp Repts 95900911.B4 01.99900715/B4-01 & 99900325/84-01 Requests evaluation of significance of reported findings requality & acceptability of vendor product or svc W/o entils

  JOHNSUN,E H Region 4. Office of Director B4/0B/03 PILANT, J M
  Nebraska Public Power District 2pp 25990 200 24X

  Fithe 50-278 B4/0B/03.B10B100107
- B408100124 Responds to NRC 840723 ltr re nonconformance noted in GA program insp rept Corrective actions subcontractor validation/surveillance program underway % effort to verify certification of products accelerated FIEDLERED C Cardinal Industrial Products Corp 84/08/08 ZECH.G G Vendor Program Branch 13pp 25984-343
- 8408100128 Ack receipt or 840717 lti informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99700911/84-01 implementation of corrective actions will be revisuad during future insp ZECH.0 G Vendor Progran Branch 84/08/09 ISON.W J National Technical Systems ip 25988 277
- 8408100131 Forwards vendor inspirepts for evaluating significance of reported findings requality & acceptability of product or syc provided by vendor Ack or receipt requested W/o enci JUHNSCN.E H. Region 4. Orfice of Director 84/08/06 LEDDICK.R Stausiana Power & Light Co. 2pp. 25788 281 24% Fiche 50-382.84/08/06.8408100131 LEDDICK R S
- 8408100132 Forwards QA vendor insp repts for info t evaluation Util should evaluate significance of findings Ack of receipt requested W/o encl
  JOHNSON,E H Region 4, Office of Director 84/08/06 GPREA,G W Houston Lighting & Power Co 2pp 25988 283 24X
  Fiche 50-498,84/08/06,8408100132
- 840B100139 Forwards OA Program Insp Repts 99900519/84-01,99900387/84-01 & 99900404/84-02 for action Requests signature on endorsement to ack receipt of repts W/o encls HUNTER, D R Region 4. Office of Director 84/08/03 KOESTER, G L Kansas Oas & Electric Co 2pp 25988 265 24X Fiche 50-482.84/08/03.8408100139
- 8408140270 Ack receipt or 840720 ltr informing NRC of steps taken to correct violation/nonconformance noted in GA Program Insp. Rept 97900053/84-01 Corrective actions will be reviewed during future insp ZECH.0 O Vendor Program Branch 94/08/13 CARON.A E Anchor/Darling Valve Co (subs of Anchor/Darling Industries. Inc ) ip 26034 346
- 8408140278 Ack receipt or 840423 ltr informing NRC of steps taken to correct violation/nonconformance noted in QA Program Insp. Rept 79790379/84-01 Cable qualification data will be reviewed on case-by-case basis by customers ZECH.0 G Vendor Program Branch 84/08/08 GALKIN, I S American Insulated Wirg Corp. ip 26042 359
  - '18150001 Responds to NRC ltr re nonconformance noted in GA Program nsp Rept 97900837/84-01 Requests extension to 840710 for plementation of corrective action RNEMOO. 8 Need Instrument Co., Inc. 84/08/08 FOTAPOVS, U gion 4. Office of Director ip 26067-052
  - J150057 Ack receipt of B40412.0513.0B08 & GB09 ltrs informing NRC of ceps taken to correct nonconformance noted in GA Program .nsp Rept 99900840/B3-01 implementation of corrective action uill be reviewed during future insp DEYOUNG.R C Director's Office, Office of Inspection and nforcement 84/08/10 DCNOVAN.M J Cardinal Industrial Products orp 2pp 26066 349
  - B160071 Advises that completion date for five new procedures is 40721, in response to Nonconformances B.Item 8 of NRC & .nsp on 840116-20 JANDL-J C Lone Star Screw Co B4/D8/O7 POTAPOVS, U Region 4, Jffice of Director POTAPOVS, U Vendor Program Branch 2pp
- 408160077 Responds to 840629 itr re whether NRC requires preamand evaluations & post-award audits for calibr svcs procured from NBS-certified state agencies Evaluation & audits not Pagetree ORACE.J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/09 AMIONICH, P. KESEL, O. P. Dravo Coro 2002
- 3408160156 Notifies that name change to Gilbert/Commonwealth, Inc & organizational changes acceptable, per NRC QA requirements Changes should be incorporated in next topical rept rev & issued to all topical rept holders QRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/09 SAILER, W F Gilbert/Commonwealth, Inc (formerly Gilbert Associates, Inc.) 2pp 26124 362

- 840817092); interms wA program insplit East Grandby CT plant on 840830 will per 840809 telcon. ZECH G. Under Program Branch 84/08/13 JONES G. Rockbestos Co. 10 Poll8 350
- 840817095° Curriems GA program insplat Wickliffe GH plant on 840820-24 per B408(10 telcon ZECH.Q S Vendor Program Branch 84/08/16 KEYES.M A Bas Controls Co (subs of Babcock & Milcos Co ) 2pp 26119 016
- 8408170105 Ack receipt de 840504 & 0720 ltrs informing NRC of steps NOBIVUIUS Ack receipt of 840904 % 0/20 Itrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp.
  Rept 99900509/84-01 Corrective actions & preventive measures will be reviewed during future insp.
  ZECH, G G Vendor Program Branch 64/08/13 KELLEY, R B Stone & Webster Engineering Corp. Ip. 26119 076
- 8408200315 Ack receipt of 840727 ltr Informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900507/84-02 אסטטטער, נארט Strong Program Branch 84/08/16 ACKMANN, L E Sargent & Lundy, Inc. וף 26:133 020
- 8408200351 Informs that GH Bettis Co notified all affected customers NOBEUGGG Infores that OA uptils to notified all affected custo re swelling of ethylene propylene seals in contact w/ actuator lubricant Mobilegrease-28 % possible degradation of actuator stroke time Lubricant changed to Molykote-44 ZECH.O G Vendor Program Branch 84/08/16 JORDAN,E L Div of Emergency Preparedness % Engineering Response (Post 830103) NORELIUS.C E Region 3, Office of Director 5pp 20132 347 Division
- 8408210390 Ack receipt or 840808 ltr requesting 1-month extension for implementing corrective action for App B nonconformance of GA Program Insp Rept 99900837/84-01 ZECH.6 G Vendor Program Branch 84/08/14 MILLER, W O Weed Instrument Co , Inc 1p 26179 240
- B408220320 Forwards QA Insp Repts 99900224/B3-02.99900224/B4-01 & 99900B51/B4-01 re insps on 830912-16.840416-1B & 0214-17 Safety significance of cracks in connectors low due to seismic qualification conducted w/connectors w/cracks ZECH.9 G Vendor Program Branch 84/0B/20 LEWIS.R C Region 2, Office of Director 1p 24193 095
- 8408220340 Ack receipt of 840612 ltr informing NRC of steps taken to correct nonconformance noted in GA Program lisp Rept 99900049/84-01 Addl into response to Nonconformances A & D requested
  ZECH.G G Vendor Program Branch 84/08/20 COVE Morrill Co , Inc (subs of Foster Wheeler Corp ) COVEY, J
- 8408220383 Ack receipt of 831223 & 840627 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900347/83-01 Implementation of corrective actions will be reviewed during future insp ZECH.O G Vendor Program Branch 84/08/20 MURPHY, T A Gulf & Western Industries, Inc. 1p 26189 335
- 8408230215 Responds to NRC 840805 request for addl info re GA Program Insp Rept 57900283/83-02 Rept B915A will be modified to audit repts available in Boston, MA ofc JEANMUNDD, J BIM Cable Systems, Inc. 84/08/16 ZECH, 9 9 Vendor Program Branch 9pp 26209 160
- B40B230229 Responds to NRC 840711 ltr re nonconformance noted in QA Program Insp Repts 99903334/83-02 % 99900334/83-03 Corrective actions QA manual revised & assembly drawings DOVER.R E Transamorica Delaval, Inc. 84/08/08 POTAPOVS.U Region 4. Office of Director 2pp 26207 298
- 8408240125 Forwards QA Program Insp Rept 99900861/84-01 on 840521-25 & notices of noncomformance & violation ZECH-0 Q Vendor Program Branch 84/07/27 BENNETT, W DuBose Steel. Inc 2pp 26226 L65
- --8408240128 Notice of Violation from insp on 840521-25 \* Vendor Program Branch 84/07/27 1p 26234 16 1p 26234 167
- --8408240131 Notice of honconformance from insp on 840521-25 \* Vendor Program Branch 84/07/27 10pp 26236 168
- --B40B240140 OA Program Insp Rept 99900861/84-01 on 840521-25 Violation noted failure to report defective matl within 2 days of receipt of notification that matl defective BAKCR, E. MERSCHOFF, E. N. Vendor Program Branch 84/07/19 15pp

|

1

- 847824025: Intrines of 618 ltt it Itoms A / B noted in GA Insp Rept 99700710:14 I (utrent) e action, GA Procedure II I revised on 847222: high / low voltige GC switchgear checklists will be intrinit or GA Procedure IO 7 for sample sic DUVALLIC I Broom Bovers Corp (subs of Brown Bovers & Co., Ltd.) 84708713: 'ECH C.G. Vendor Program Branch. 2pp. 26222-359
- 840824027 hispands to monconformance noted to GA Program Insp Rept 9990083,786 (1 Corrective actions procedures to instructions applicable to quality program prepared to maintained to training acasions for administering elements conducted JERBE. J. C. Power Breakers, Inc. 84/08/07 IECH. G. G. Vendor Program Pranch 14pp 24222 334
- 840824027, tubesis requested adult info to 840601 ltr re-training of personnel on control crimping tool calibiling in engineering review of stds / misunderstanding or intep of crimped wire terminal.

  DUVALLI II Brown Bovers torp (subs. of Brown Bovers & Co., Ltd.)

  84/00/13 /iCH, 0 % Vendos Program Bronch 2pp 26223 197
- 84082/035; Consises QA pingiam insplat Philadelphia, PA plant on 840827-31, per 840820 telcon ZECH. 4 O Gendar Pingiam Branch 84/08/22 VICKERY, D Tinga Pipe Supply Co., Inc. 1p. 26245-020
- 840828006.' Forwards response to NRC 840727 Itr re nonconformance noted in GA Program Inop Rept 99900522/84-02 Corrective actions now control form dbd 840320 issued as cover sheet to current user/theoretical nanual for BSAP CE800 STATION.C D Bochtel Corp 84/08/20 ZECH,0 G Vendor Program Branch 4pp 26/861 F20
- 8408280120 forwards ASME responses re-code inquiry concerning 840530 notice of nonconformance in 9A Program Insp Rept 97900/51/84 01 Add1 into requested within 25 days ZCCI.0 G Vendor Program Branch 84/08/22 DOWICKI.W J MCC Pacific Valves 1p 26259-051
- --8408280125 Responds to 840419 inquiry re requirements for completion of data rept forms for parts when alternative marking method employed? when certificate holder is mfg replacement parts for components originally mrg & stamped ENNIS, P. American occupty of Mechanical Engineers 84/07/26 BAKLER F. Vendor Program Branch 1p 26259 062
- ---8408.83) 19 Nosponds to 840419 inquiry re requirements for completion of data stams for parts when alternative marking mothed orphiogid 'alternative identification maskings traceable to required data rept form
  EINITY, P. Annuitan Society of Mechanical Engineers 84/07/26
  BAKER.I I Vendor Program Branch ip 26259 063
- 8408230314 Forwards QA Insp Rept 99900285/83-01 re defective capstan aprind longs in PBA-1 A PBA J mechanical shubbers mfg by Partit intentific Co Process requiring vendor to form spring hirote age hardening specified ZFCH-0 C Vendor Program Branch 84708/22 LEMBAR C Division of Project & Resident Programs 6pp 36274-301 24X Fiche 50 000.84708/22 8408280215
- 8408290201 Act receipt of 840730 ltm informing NRC of steps taken to correct nonconformance noted in QA Program Insp. Rept 99900401784 02 ILING G. Vendor Program Branch 84708/27 ETHERIDGE, M.R. Cambustion Engineering, Inc. 1p. 26290 338
- 840877031") Ack receipt or 840/09 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900871/44-01 Requests addl info re listed items in notice of nonconformance & status of previous insp findings ZICH+0 & Vendor Program Branch 84/08/27 CHRISTOPHER+T Westinghouse Electric Coip 2pp 26290 358
- REGGD REGULATORY GUIDES
- 840802010. Comments on propused Reg Guide 1 8. Task R8 807-5, resulection 3, training of nuclear plant personnel Shift aperating opportunce requirements should reflect position outlined in Chairman Palladine 840614 Jtr MILLER, J II Institute of Nuclear Power Operations 84/07/25 DIRCKE, W J Office of the Executive Director for Operations 1, 258092 (A.)
- 840803027; Req Guide 1 147.Rev 3. "Inservice Insp Code Case Acceptability ABME Section XI, Div 1 " \* Office of Nuclear Regulatory Research, Director 84/07/31 Ap 25720 0.44

- h40bJ60114 f spands to approval request for info collection re 10CFR51.
  Licensing ' Regulatory Policy ' Procedures for Environ
  Protection ' Reg Guide 4 2 "Preparation of Environ Repts
  for Nuclean Power Plants "
  MACRAE, J B Ortice of Management & Budget OMB 3150-0021
  B4707/24 50TTS Document Management Branch 2pp 23736 350
- B408070114 Fruvides schedule info re NUREG-0737. Suppl L on emergency response commitment & clarifies schedular error in 840612 confirmatory order Arend to order prior to Sept 1985 suggested 0/TDDLE. J D Consolidated Edison Co of New York, Inc QL-82-33 B4/07/31 DENTON. H R Office of Nuclear Reactor Regulation, Director 2pp 23950 034 24% Fiche 50-247. B4/07/31, 8408070114
- 8408080344 Forwards nonproprietary "Use of Code Case N-192" & proprietary repts, including "Documentation of Compliance of MBC P/N 73987 " & "Hose Assembly " qualification test procedures, per Reg Guide : 84 Proprietary repts withheld MITTL/R L Public Service Electric & Oas Co of New Jersey 84/07/30 SCHEMCER-A Licensing Branch 2 10pp 25963 274 24X Fiche 50-394.84/07/30.8408080344
- --8408080346 Nonproprietary "Use of Code Case N-192 (Compliance W/Add1 Requirements of Reg Guide 1 84) " # Public Service Electric & Gas Co of New Jersey 84/06/30 3pp 25963 284 244 Fiche 50-334, 84/07/30, 84080803344
- E40B0902B2 Summary or B40520 meeting w/util & Bechtel in Bethesda.MD re implementation of Reg Ouide i 97 requirements by licensee Util will provide supplemental rept to 840715 submission to address separation problems Viewpraphs encl MINER.S Operating Reactors Branch 4 B4/08/Oi Operating Reactors Branch 4 B4/08/Oi Operating Reactors Branch 4 12pp 25992 001 24X Fiche 50-312.84/08/Oi. B408070282
- 840B13021/ Accepts conditionally util 840622 request to use ASME Code Case N-369 for application in pressure testing of piping associated w/discharge side of Code Classes 2 & 3 centrifugal pumps Case should be documented in FSAR KNIGHTUNG W Licensing Branch 3. 84/07/30 HARRISON,R J Public Bervice Co of New Hampshire 5pp 26058 325 24X
- B408140293 Provides editorial changes to B40731 cover 1tr & Attachment 1 re Suppl 1 to NUREO-0737, safety parameter display sys PBAR & implementation schedule, per Reg Guide 1 97 variables JOHNSON, B D Consumers Power Co 84/08/09 CRUTCHFIELD, D Operating Reactors Branch 5 6pp 26043 144 24X Fiche 50-255, 84/08/09, 8408140295
- 840B160485 Forwards IE Insp Rept 50-445/84-15 on 840301-0430 & notice of deviation
  HANDART,R L Region 4, Office of Director 84/07/30, SPENCE,M D
  Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pp 26107 276 24X Fichs 50-445,84/07/30,8408160485
- --8408160475 No+1cs of deviation from insp on 840301-0430
  \* Region 4, Office of Director 84/07/30 ip 26107 299 24)
  Fichs 50-445,84/07/30,8408160485
- --B408140500 [E Insp Rept 50-445/B4-15 on B40301-0430 Deviation noted failure to provide review & approval for safety-related maint instructions.per Rey 2 to Reg Coide | 33 KELLEY.D L , SMITHAW F , KUNNICUTT.D M Region 4, Defice of Director 84/07/27 lipp 26107 300 24% Fiche 50-445.B4/07/30.B408160485
- 8408210031 Forwards add1 info requested in NRC 840430 ltr re exceptions to conformance to Rev 2 to Reg Guide 1 97 Encls should close Open Item 12 of SCR (NUREG-0971) KEMPCR. J Philadeiphia Electric Co 84/08/16 SCHWENCER. A Licensing Branch 2 lipp 26181 337 24X Fiche 50-352,84/08/16,8408210031
- B40B210199 Notification of B40B30 meeting w/util in Bethesda, MD to discuss implementation of Reg Guide 1 97 requirements MINER: 5 Operating Reactors Branch 4 B4/0B/15 STOLZ, J F Operating Reactors Branch 4 2pp 26198 223 24x Fiche 50-312,84/0B/15,840B210159
- 840B210313 Forwards revised FSAR App 7A pages addressing NRC 840625-26 requests for addition re Reg Guide 1 97 As-built plant design info.not included in original submittal.incorporated Design provides info required to satisfy Rev 2 to reg guide PETRICK,N A Standardized Nuclear Unit Power Plant Bystem SLNRC 84-107 84/08/16 DEMIGN.H R Diffice of Nuclear Reactor Regulation. Director 65pp 26179 060 24X Fiche 50-000.84/08/16, 8408210313

- 8408810412 Forwards list or accident monitoring equipment to be replaced within eitended schedule of 1007850 49, per Reg Guide 1 97 MCDONALD.R P Alabama Power Co 84/08/17 VARGA,S A Office of Nuclear Reactor Regulation. Director 4pp 26179 211 24X Fiche 50-364.84/08/17.8408210412
- 8408210416 Comments on Rev 1 to Reg Ouide i 58, "Qualification of Nuclean Power Plant Insp Exam / Testing Personnel " SMAIN.H W Georgia Power Co 84/08/10 Docketing & Services Oranch 2pp 24460 128
- B408280113 Responds to B40717 ltm requesting extension of completion dates for submitting final rept re Reg Guide I 97 requirements of Suppl 1 to NUREG-0737 Extension granted Adaquate justification provided EIBENHUT.D G Division of Licensing LS05-84-08-032 B4/08/23 VANDEMALLE,D J Consumers Power Co 4pp 26261 276 24X Fiche 50-255,84/08/23 8408280113
- 8408280436 Third interim Significant Const Deficiency Rept 105 re electrical separation defects (Reg Guide 1 75) Initially reported on 840719 Rework generated by evaluations of walkdown results incomplete Next rept expected by 840831 ØERRETS.TF Louisiana Power & Light Co 105 84708717 COLLING.JT Region 4. Office of Director 2pp 26282 130 24X Fiche 50-382,84708/17.8408280436
- B40B300104 Forwards Insp Rept 50-247/84-18 on 840717-20 No violations noted MARTIN.T T Division of Engineering & Technical Programs 84/08/14 O'TOULC, J D Consolidated Edison Co of New York, Inc 2pp 2630B 100 24X Fishe 50-247.84/08/14,840B300106
- --B40B300113 Insp Rept 30-247/84-18 on 840717-20 No violations noted Major areas inspected inservice activities including program review observations of work in progress NDE procedure & licensee actions re Reg Guide i 150 MCBREARTY. R A Region 1 Office of Director DURR, J P Division of Engineering & Technical Programs B4/08/06 Spp 26308 102 24X Fiche 30-247,84/08/14,8408300106
- 8408300139 Forwards original & Rev 2 to Reg Guide i 75, per G Berry commitment Rev 1 to Reg Guide 1 /5 bound in Disposition Exhibit Disclosure F-7a W/o encl Related correspondence MIZUNO.G S Hearing Granch 1 DSB 382 QL-2 84/08/27 SPEKTER.M L. Affiliation Not Assigned 1p 26304 362 24X Fiche 50-445.84/08/27.8408300139
- VIEW GRP NRC RESEARCH REVIEW GROUPS
- IAD7020341 Suggests CROR meeting be acheduled during wk of 840701 for rereview of proposed IE bulletin re undervaltage trip attachments of reactor trip breakers Burden of add1 testing imposed by bulletin miniscule DEYQUNG.R C Director's Office of fise of inspection and Enforcement 84/05/27 STELLOV Committee to Review Generic Requirements 8pp 26136 001
- --8405180433 Informs that listed analysis performed in order to be responsive to V Stello concern that add1 monitoring of garameters could be detrimental to safety re proposed IE bulletin on UV trip HQLAHAN. O M Operating Reactors Assessment Branch 84/05/04 ROSSI.C E Events Analysis Branch 2pp 26136 009
- --B407020544 Forwards safety impact analysis of proposed IE bulletin re undervoltage trip attachments of reactor trip breakers No clear net quantifiable safety benefit from proposed bulletin for Westinghouse plants considered in analysis SPEIS.T P Division of Safety Technology 84/06/19 JDRDAN.E C Division of Emergoncy Preparedness & Engineering Response (Post 830103) 14pp 26136 011
- --8407030011 SECY-84-215
  Informs Commission of status of licensee responses to
  Ceneric Ltr 83-28 re Salem ATMS events
  DIRCKG.4 J Office of the Executive Director for Operations
  OL-83-28 84/05/24 9pp 26134 085
- B407200109 Forwards for review & comment, draft generic ltr on required GA actions associated w/ATMS rule Comments due by 840720 as guidance to be issued by 840801 DEYOUND, R C Director's Office of Inspection and Enforcement 84/07/13 DENTON, H R Office of Nuclear Reactor Regulation, Director #INDOUE, R B Office of Nuclear Regulatory Research Director MURLEY, T Region 1, Office of Director 24pp 26136 093

- 840801004e burnary or LRGR Neeling &b on 840711 re status of long-range plans to address BUP pipe cracking due to IGSCC \* review of proposed to Jibtion at Unitsolved Safety Issue A-43 re containment energency sump STELLO. Franchitee to Review Generic Requirements 84/07/24 DIRCKS.M. J. Office of the Executive Director for Operations 2pp 28854 Old
- 8408010159 Forcards sunnery or CRGR activities for Jul 1984 Summary will be included in EPO weekly rept to Commission for wk ending 840803 SNIFZEK, J. Regional Operations & Generic Requirements 84/07/30 Committee to Review Generic Requirements 4pp 25854 040
- 840802011a Notification of date & location change for 840802 meeting w/Regulatory Response Group in Betheada, MD to discuss licensee efforts to quantity superheat steam releases resulting from main steam line break WIGGINTON Di Operating Reactors Branch 1 84/07/23 VARGA. S A Operating Reactors Branch 1 194/07/23 VARGA. S A
- 8408070081 Notification or CRGR Meeting 68 on 840808 in Betheede, MD to review revised version of proposed tule amends redecommissioning criteria for factilities STELLOV Committee to Review Generic Requirements 84/07/26 EISENHUT, D Division of Licensing JORDAN, E L Director's Office, Office of Inspection and Enforcement CONTINOMAN, E Office of Nuclear Material Safety & Safeguards, Director 2pp 25785 257
- B408070149 Forwards revised "Document Accessions List.Jul 1984." for Rockwell Hanford Operations \* Basalt Maste Isolation Project 920 84/07/26 WRIGHT,R J Division of Maste Hanagement 1p 25957 210
- --8408070153 Q04-30~84
  Revised "Document Accessions List Jul 1984," for Rockwell
  Hanford Operations
  \* Basalt Maste Isolation Project 84/07/31 512pp 25937 21i
- 8408230396 Summary of CROR 640808 Meeting 68 re revised version of RES proposed amends to 10CFR. Parts 30. 40.50.51.70. & 72 to incorporate "Decomissioning Criteria for Nuclear Facilities" Proposal revised per CROR 840425 Meeting 62 STELLO.V Committee to Review Generic Roquirements 84/08/14 DIRCKS.N J Office of the Executive Director for Operations 2pp 26204 026
- B40B270102 Forwards summaries or proposed Apr 1784 bulletin entitled, "Undervoltage Trip Attachments of Reactor Trip Breakers" & of briefing regeneric ltr specifying OA requirements for nonsafety-related ATMS equipment Encls withheld STELLO, V Committee to Review Generic Requirements STELLO, V Regional Operations & Operations & 04/08/03 DIRCKS, W J Office of the Executive Director for Operations 2pp R6258 208
- 8408270343 Notifies of CROR Meeting 49 on 840905 to discuss proposed IE bulletin te cracking in BUR Mark I & II containments caused by inerting sys failure W/o stated ancl STELLO, Committee to Review Generic Requirements 84/08/24 BERNERO, R Office of Nuclear Reactor Regulation, Director JORDAN, C. L. Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R & Office of Nuclear Material Safety & Safegwards, Director 2pp 26238 142
- 8408270446 Advises that exemption of proposed final rule 10CFR53 from CRGR review will be granted providing CRGR offers no objection Rule not significantly changed from proposed rule reviewed at CRGR Meeting 33 on 830307 M/o stated encl
  STELLO,V Regional Operations & Generic Requirements 84/08/24
  BERNERD,R Office of Nuclear Reactor Regulation, Director JORDEAN,C i Director's Office of Fingettion and Enforcement CUNNINGHAM,R E Office of Nuclear Material Bafety & Safeguards, Director ip 26238 127
- 8408300020 Submits list of current CRGR members
  DIRCKS.N J Office of the Executive Director for Operations
  84/08/28 PALLABINO, ROBERTS, ASSELSTINE Commissioners Ip
  26/300 138
- SECY POSITION PAPERS DEFORE THE COMMISSION
- 8407300105 SECY-84-270A
  Relates recent exemption ducision to Section 185 of Atomic Energy Act requiring NRC to find plant in conformity w/provisions & rules & regulations of Commission before issuing OL
  PLAINE-II H Office of the General Counsel 84/07/24 27 25920 001 24% Fiche 80-322,84/07/24,8407300105

- 340807013P | Fight Commission paper on NRC actions re GA in design implementation
  DIRCHS, P. Office of the Executive Director for Operations
  84/06/15 | App. 25991 207
- 3408090406 SFC/-04-301
  Informs Commission of lung-range plan for dealing w/stress corruston (racking in BHR piping / discussed progress made re execution of plan
  DIRCKS.W J Office of the Executive Director for Operations
  84/07/30 45pp 25991 304
- 3408240110 SECY-84-329
  Recommends adoption of encl draft final financial qualification rule Rule eliminates financial qualification reviews from GL proceedings but reinstates such reviews for CP applications
  MALSCHIR G Office of the General Counsel B4/08/14 33pp 26256 001
- B40B310156 F01A request that SECY-B4·29 % encl of Pt William B40303 ltr re functional description of safety parameter display sys be placed in PTR DOVE.K. Affiliation Not Assigned 84/04/12 FELTON, J.M. Division of Rules and Records 1p 26352 001

#### STATE PRUG STATE PRUGRAMS

- 8406210504 Agenda for Nuclear Waste Board 840509 meeting in Olympia. WA Map onc! \*\* Washington, State of 800 84/05/09 Washington, State of 4pp 25093 005
- 8408010334 Responds to NRC 840919 ltr offering technical comments & recommendations on State of ND radiation control program Program ustablished procedures for handling uscalated enforcement cases.per state statutes & rules MOUNT, D F North Dakota, State of 84/07/19 COLLINE, J T Region 4, Office of Director 2pp 29866 079
- B40B020109 Forwards "State of KS Annex A. Nuclear Facilities Incidents Response Plan to Assistance R. Nuclear Emergencies of Blate Disaster Emergency Plan" 7. "Coffey County Contingency Plans for Incidents Involving Commercial Nuclear Power" (KDESTER, G | Kansas Gas / Electric Co KMLNRC B4-124 B4/07/31 DENIGN.H R Office of Nuclear Reactor Regulation, Director ip 25892 306 24X Fiche 50-482, B4/07/31, 840B020105
- --B40B020114 "State of KS Annex A Nuclear Facilities Incidents Response Plan to Assistanco R Nuclear Emergencies of State Disaster Emergency Plan " MANNELL: L Kansas State of 84/06/30 356pp 25892 307 24X Fiche 50-482,84/07/31.8408020105
- 040803008? Forwards Mod A003 to Cooperative Agreement DE-FC04-81AL16309 w/8tate of UI Agreement supports UMTRAP in State of UT.per Public Law 95-604 HILL: T. V. Fnergy, Dept. of 04/06/13 HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch 84pp 25920 242
- 8408030084 Forwards "Cooperative Agreement Between DDE & State of DR " HILL.T V Energy, Dept of 84/07/03 HIGGINBOTHAM, L Low-Level Waste & Ulanium Recovery Projects Branch 58pp 23934 136
- B408030092 Forwards, for review & comment.minutes of 840931 meeting w/Salt state representatives re land acquisition, transportation & environ assessments Minutes of 840329-30 meetings w/Salt representatives in Columbus, OH also enci TAYLOR, T J Energy, Dept of IN 412-84 84/07/17 LINEHAN, J J Repository Projects Blanch (Post 831001) 284pp 25921 001
- 8408030177 Confirms 840619 discussion w/P Lahaus following review & avaluation of Dept of Hoelth radiation control program Application of guidelines for NRC review of Agreement State radiation control programs, comments & recommendations encl MURLTY.T E Region 1, Office of Director 84/07/12 SENCER,D J New York, NY 3pp 25917 310
- 8408060338 Forwards listed documents re docision on DDE guidelines, including transcript of 840622 Commission meeting & three written testimonies from Commission 840622 meeting W/o encl RUSSCLL.C F Division of Waste Management 84/07/03 STEVENS, D Washington, State of 1p 25937 353
- E408060341 Forwards listed documents re decision on DDE guidelines, including transcript of Commission 840622 meeting 8 three written testimonies from Commission 840622 meeting W/a encl MATTBON,D R Policy & Program Control Branch (Post 831001) 612 84/07/03 BOHLINGER, H Louisiana, State of 1p 25937 352

- 8408070315 Ack receipt of 840719 response to technical comments & recommendations re review of State of ND radiation control program Commends efforts to improve quality of agreement matls functions & improve license & insp programs COLLING.J T Region & Office of Director 84/08/01 MOUNT, D North Dakota. State of ip 25947 306
- B40B070319 Advises that on B40621.NRC approved petition for rulemaking PRM-50-34 governing emergency exercise frequency Expresses appreciation for participation 5 assistance provided during rulemaking CHILK.S J Office of the Secretary of the Commission 47FR50918 B4/07/31 MILLER.R South Carolina, State of 1p 25944 160
- 8408070339 Confirms recent orientation meeting RS Heyer & RJ Doda held w/K Alkema to discuss agreement matls program for new Agreement States Development of insp schedule & short-term action plan encouraged COLLINS. J T Region 4. Office of Director 84/08/02 ANDERSON. L Utah. State of 1p 25945 229
- 8408070434 Forwards rev to "NV State Radiological Emergency Preparedness Plan" MANGAN,C V Niagara Mohawk Power Corp 84/08/03 Record Services Branch (Document Control Dosk) 2pp 25938 016 24X Fiche 50-220,84/08/03.8408070434
- --8408070439 Rev to "NY State Radiological Emergency Preparedness Plan" \* New York, State of 84/07/12 559pp 25938 018 24X Fiche 50-220,84/08/03,8408070434
- 8408080034 Ack recuipt of 840612 ltr re NRC assistance to State of TX on programs for developing low level radwaste disposal capacity NRC will provide State of TX to other Agraement States w/technical assistance appropriate to needs PALLADINO,N J Commissioners 84/07/20 WHITE,M Texas, State of 2pp 25981 061
- --8408080038 Encourages NRC to ensure adequate resources for assistance to states in complying w/10CFR61 re low level radwaste disposal WHITE, M Texas, State of 84/06/12 PALLADINO, N Commissioners ip 25981 063
- 8408080227 Forwards response to 840705 ltr re review & evaluation of State of NV radiation control program Response contains specific actions to be taken w/respect to each NRC recommendation

  JACKA, B Nevada, State of 84/07/23 MARTIN, J B Region 5, Office of Director 2pp 25975 012
- B408080333 Comments on proposed rule 10CFR60 re disposal of high level radwaste in geologic repositories Disagrees w/NRC re contents of site characterization plan HH Humphrey B40525 comments encl KALITOHSKI, T Hinnesota, State of 49FR5934 015 B4/08/01 BROWNING, R Division of Waste Management opp 25964 091
- --8408080334 Comments on suggestions for procedural changes in nuclear power plant licensing process Supports creation of ABLB screening boards
  HUMPHREY, H. H. OLSON, J.F., SENECHAL, M.E. Minnesota, State of 49FR14698 84/05/25
  OPFICE of the Secretary of the Commission Bpp 25964 097
- 8408090042 Forwards States of NC & SC responses to regional assistance committee findings on offsite radiological emergency response preparedness & exercise on 840215-16 State & local omergency plans adequate KRIMM, R W Federal Emergency Management Agency 84/07/27 JORDAN, E & Division of Emergency Preparedness & Engineering Response (Post B30103) Bpp 25992 324 24X Fiche 50-413,84/07/27,84080900042
- 84080903R8 Summary of 840717 meeting w/State of CO.EPA.DGE & DOE contractors in Denver.CO re Durango Els Attendes list encl PENNIFILL.R A Lou-Level Waste & Uranium Recovery Projects Branch 84/07/24 HIGGINBOTHAM.L Lou-Level Waste & Uranium Recovery Projects Branch 3pp 25984 341
- 8408090331 Comments on study of soil samples from Beatty,NV disposel site Questions raised re plans for further testing for TC-99, I-129 & H-3 & use of results by State of NV HIGGINBOTHAN.L Low-Level Waste & Uranium Recovery Projects Branch B4/03/27 NUSSBAUMER.D A Assistant Director for State Agreements Programs ip 25984 340
- B40B130077 Forwards marked-up draft Beatty site closure plan submitted by US Ecology, for review & comments Comments requested by B40B08 NUSBBAMMER, D. Assistant Director for State Agreements Programs 84/07/13 HI00INB0THAM, L. Low Level Waste Licensing Branch 35pp 24059 001

- 8408130130 Forwards 'Geology'; Mineral Deposits of Southern Nye County," 'Nevada Statistical Abstract," 'Annual Rept 1981-82: "Nevada Map Arlas-Fourth Edition & "Financial Statement," per C Johnson 840613 request W/a enci LOUX R R Nevada, State of 328 84/07/25 RVSSELL,C F Policy & Program Control Branch (Post 831001) 1p 26034 330
- B40B130140 Concurs w/reredial action plan for State of CO tailings repository HIGGINBOTHAM.L. Low-Level Waste & Uranium Recovery Projects Branch B4/07/27 CREW.M & Energy. Dept of 2pp 26034-326
- B40B160479 Submits cornents on draft 'Mission Plan for Civilian Raduaste Mgt Program," per Nuclear Waste Policy Act, Section 301(b) FRISHMAN, S. Telas, State of 84/07/09 RUSCHE.B.C. Energy, Dept of 20pp 26108 334
- 8408210477 Forwards Rev 1 to Commonwealth of MA "Comprehensive Energency Response Plan " Marked-up changes indicated BOULAY,R J Massachusetts, Commonwealth of 84/06/15 NRC - No Detailed Affiliation Given 2pp 26181 143
- --B408210478 Rev 1 to "Comprehensive Emergency Response Plan " \* Massachusetts, Commonwealth of 84/06/15 50pp 26181 145
- 8408220061 Forwards State of NV comments on draft mission plan LQUX.R R Nevada. State of 84/08/10 BROWNING.R E Division of Waste Management 36pp 26211 305
- 8408230027 Summary of 840730 meeting w/DOE & Colorado Dept of Health preliminary findings for Gunniaon.CO site HAIBFIELD,M . PENNIFILL,R A Low-Level Waste & Uranium Recovery Projects Granch 84/08/06 HIGGINBOTHAM,Ł Low-Level Waste & Uranium Recovery Projects Branch 2pp 26233 361
- B40B230031 Forwards comments on draft Beatty site closure plan Plan inadequate for effecting proper closure of facility Major deficiencies include lack of documentation re geology & hydrelogy & support for cost & financial data H109INBOTHAMIL Low-Level Waste & Uranium Recovery Projects Branch B4/0B/15 NUSSBAUMER, D.A. Assistant Director for State Agreements Programs 5pp 26233 354
- 8408230253 Submits response to Category II indicators noted during NRC review of State of CO radiation control program HOZLE:A J Colorado, State of 84/08/01 COLLING.J Region 4. Office of Director 2pp 26213 271
- 8408230259 Submits list of actions taken in response to 840711 ltr re NRC review of State of CO radiation control program VERNON, T.M. Colorado: State of 84/07/31 COLLINS, J.T. Region 4. Office of Director ip 26213 270
  - DB230362 Forwards request for add1 info to continue review of Nuclear Packaging, Inc topical rept on FL 50 Ferralium 225 high Integrity container Response requested within 45 days of Itr receipt W/o enci (USBBAUMER: D A Assistant Director for State Agreements Programs 34/08/15 #IRNER: N P Washington, State of, Dept of Social & Health Services Ip 26230-358
- 408290223 Ack receipt of 840723 response to 1984 review of Agreement State radiation control program Changes satisfactory MARTIN.J B Region 5. Office of Director 84/08/24 JACKA.S B Navada. State or 1p 26290 308
- 408290229 Ack receipt or 840724 response to 1984 review of Agreement State radiation control program Changes acceptable, pending rev of state regulations MARTIN, J B Region 5, Office of Director 84/08/24 TEDFORD, C F Arizona, State of 1p 26290 346
- 8408300289 NUREO/8R-0025 VIO NA INFORMATION REPORT ON STATE LEGISLATION KERR.G W . MCGUADE.J Office of State Programs. Director 84/07/27 9pp 26330 333
- 8408300520 Confirms 840622 discussion between RL Hoodruff & SK Moore, J Brown & E Fuente concerning 840622 review & evaluation of State of MS radiation control program Program for regulation of agreement natis adequate O'REILLY, JP Region 2. Office of Director 84/08/09 COBB, A B Mississippi. State of 5pp 26313 354

- TOPHER PERIOD REPORTS AND RELATED CORRESPONDENCE
- 8405270062 Forwards 'Investigation of Types AF & AE Piston Skirts "
  Rept supercedes 840227 submittal
  RAY.C L TE! (Transamerica Delavali Inc.) Owners Group OGTP-41
  84/05/24 DENION.H R Dffice of Nuclear Reactor Regulation.
  Director 2pp 24490 045 24x Fiche 50-000,84/05/24,8405270062
- --8405990075 FAAA-84-2-14 'Investigation of Types AF 1 AE Piston Skirts " • Failure Analysis Associates 84/05/23 120pp 24X Fichs 50 000, 84/05/24 0405290062
- 8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shorehar \* Grand Gulf Nuclear Power Stations RAY, C. L. IDI (Transamerica Delaval, Inc.) Gwners Group OGYP~39 84/05/24 DENTON, H.R. Diffice of Nuclear Reactor Regulation, Director 2pp 24492 070 24X Fiche 50-000, 84/05/24, 8405290179
- --B405290271 FAAA-B4-3-16
  "Evaluation of Emergency Diesel Generator Crankshafts at
  Shoreham \* Grand Gulf Nuclear Power Stations "
  \* Failure Analysis Associates 84/05/22 89pp 24692 092 24X
  Fichs 50-000,84/05/24,8405290179
- 8407130037 Further response to FOIA request for numerous categories of records re issues discussed in IE Info Notices 81-29,83-52,83-57 & 83-72 & Board Notifications 83-128 & 83-128A Forwards Apps C & D documents Search continuing FELTON, J M Division or Rules and Records 84/04/13 JORDAN, W S Harmon & Weiss 7pp 25584 078 24X Fiche 50-000,84/04/13,8407130037
- B407230200 Forwards request for withholding proprietary viewgraphs entitled. 'Consistency Between Safety-Analysis & Tech Specs iOCFR50 36 Number of Operating Loops Mode 3 "RAHELE P Westinghouse Electric Corp NS-TA-84-003 84/07/09 EISENHUT.D Division of Licensing 5pp 25704 174
- --8407230203 Requests withholding proprietary viewgraphs entitled.
  "Consistency Between Safety Analysis & Tech Specs 10CFR50 06
  Number of Operating Loops Mode 3"
  ULESEMANN, R.A. Westinghouse Electric Corp. AN-84-63 84/07/09
  EISENHUT, D. Division of Licensing 10pp. 25704 179
- 8407.300143 Forwards proprietary XN-NF-84-67(P), "Stability Evaluation Methodology for BWR Cores " Rept withheld (ref 10CFR2 790) Affidavit for uithhelding encl CHANDLER, J C Exxon Nuclear Co, Inc (subs of Exxon Corp ) 84/07/02 THOMAS, C O Standardisation & Special Projects Branch 400 25806 149
- 8407310144 Forwards proprietary WCAP-10621. "Westinghouse Thermocouple/Core Cooling Monitor Sys Isolation Tests " Rept withheld (ref 10CFR2 790)
  PETRICK.N A Standardized Nuclear Unit Power Plant System SLNRC 84-0104 84/07/26 DENICN.H R Office of Nuclear Reactor Regulation, Director 3pp 25835 258 24% Fiche 50-000,84/07/26,8407310144
- 840B010012 Final Deficiency Rept DR-171 re flow adjustment subassembly on Model 1284 Robertshau thermostable flow control valves on jacket water cooling sys for TDI standby diesel generators Condition not reportable under 10CFR30 55(e) 80OKER.J E Gulf States Utilities Co RB0-18228 84/07/16 CDLLING, JT Region 4, Office of Director 1p 25866 267 24X Fiche 50-458.84/07/16.8408010012
- 8408010038 Informs of review of 840627 ltr on operating experience, insp & analysis results re reliability of TDI V-20 diesels Lead engine testing disassembly & insp not required before restart CRUTCHFIELD.D Assistant Director for Safety Assessment LSD5-84-07-027 84/07/26 BABKIN.K P Southern California Edison Co 7pp 25855 333 24X Fiche 50-206.84/07/26.8408010038
- 8408010141 Submits schedule to provide add1 info requested in NRC 840725 ltr re \AEC-1300P, "RELAPSYA ~ Computer Program for LHR Sys Thermal-Hydraulic Analysis," submitted in response to TMI Action Item II K 3 3D KAY, J A Yankee Atomic Electric Co FYR 84-80 84/07/25 CRUTCH/IELD D Operating Reactors Branch 5 2pp 25855 182 24X Fiche 50-029,84/07/25,8408010141
- 8408010240 Forwards C-E nonproprietary & proprietary "Safety Analysis & CPC Methodology Changes for San Onofre Nuclear Generating Station Units 2 & 3" & "CPC/CEAC Software Mods Proprietary repts withheld (ref 10CFR2 790)
  MEDFORD,M O Southern Callfornia Edison Co 84/07/20, KNIOHTON,G W Licensing Branch 3 13pp 25855 001 24X
  Fiche 50~361.84/07/20,8408010240

- --8408010217 (EN-284(S)-No
  Nonpruprietary "Safety Analysis" CPC Methodology Changes
  for San Ondere Nuclear Generating Station, Units 2 ( 3 )
  Info deleted
  W Combustion Engineering Inc 84,06/30 35pp 25855 014 24X
  Fiche 50-361,84/07/20.8408010240
- --8408010256 CEN-281(S)-NP Nonproprietary "CPC/CEAC Software Mods for San Onofre Nuclear Generating Station Units 2 % 3 " Info deleted \* Combustion Engineering, Inc. 84/07/31 24pp 25855 050 24x Fiche 50-361,84/07/20,8408010240
- B40B020025 Forwards program plan for evaluating & testing TDI standby dissel generators Program includes all recommended actions of TDI Quiners Group & TDI Changes to number of start tests & overload tests requested BIONER. J E Oulf States Utilities Co RBG-18.244 B4/07/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 43pp 25882 249 24% Fiche 50-458.84/07/19.840B020025
- 8408020031 Informs of planned mod to C-E control element assembly guide tube wear sleeve Mod includes relocation of sleeve flare. Sleeve expansion over full length of sleeve & relocation or crimp. providing resistance to axial motion SCHERER, A E Combustion Engineering. Inc LD-84-039 84/07/27 RUBENSICIN.L S Assistant Director for Core & Plant Systems 2pt 25880 238 24x Fichs 50-000.84/07/27.8408020031
- B408020034 Provides requested info re schedule for testing & insps of two TDI diesel generators for standby energency power Operational testing scheduled for Lest Quarter 1984 & early 1985 Svc list encl Related correspondence O'NETLL.J H Shaw. Pittnan. Potts & Trowbridge O'NETLL.J H Carolina Power & Light Co DSB 700 DL 84/07/31 KELLY.J L, BRIGHT, O O. CARPENTER.J H Atomic Safety and Licensing Board Panel Spp 25891 330 24% Fiche 50-400.84/07/31,8408020054
- 8408020129 Joint direct testimony of RN Anderson. 80 Christensen. 9D Eley, A Gakshi, DO Bridenbaugh & RB Hubbard re Suffolk County emergency diesel generator contentions Certificate of Bvc encl Related correspondence
  ANCERBUN, R N San Jose State Univ. San Jose, CA CHRISTENSEN, S
  U S Marchant Marine Academy, Kings Point, NY ELEY, 6 D Grean Fleet Consultancy Service DSB 709 D. 84/07/31 1326pp 23886 223 24% Fiche 50-322, 84/07/31, 8408020129
- 8408030120 Supplemental RO on 840726, while performing routine maint on Div 1 101 diesel engine, water observed coming from open cylinder cock on left bank cylinder head 7 Caused by 2-inch crack in right exhaust port casting Head replaced DALE.L F Mississippi Power % Light Co AECM-84/0401 84/07/30 DENTON-N R Office of Nuclear Reactor Regulation, Director 2pp 25716 110 24X Fishe 50-416,84/07/30,8408030120
- 840B350345 Forwards corrected Page 46 from App A to "ENVIROBTONE Gypsum Coment 10CFR61 Compliance Testing Topical Rept" (USG-684-1P & USG 684-1NP) re mix ratios for ion exchange bead resins solidified w/ENVIROBTONE Gypsum cement LANGE R G US Gypsum Co 84/07/19 HIGGINBOTHAM, L Low Level Waste Licensing Branch 2pp 25937 089
- --8408060047 USO-684-INP CRP Corrected Page 46 from App A to "ENVIROBTONE Gypsum Cement 10CFR61 Compliance Testing Topical Rept" \* U S Gypsum Co 84/07/19 1p 25937 091
- 8408050030 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Generator Ouners Group 849522 meeting RAY,C L TDI (Transamerica Delaval, Inc.) Dwners Group GGTP-108-N 84/07/10 BERLINGER,C Director's Office, Office of Inspection and Enforcement 43pp 28933 133 24X Fiche 50-000,84/07/10,8408050050
- 8408050102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNWL RAY,C L TDI (Transamerica Delaval, Inc.) Owners Group OOTP-140-N-28 84/07/27 DENIGN.H R Office of Nuclear Reactor Regulation, Director 2pp 25932 137 24% Fiche 50-000,84/07/27,8408060102
- --B40306013B "Emergency Diesel Generator Auxiliary Module Control Wiring & Fermination Qualification Review "

  § Stone & Nebster Engineering Corp 84/07/31 36pp 25932 139 24% Fiche 50-000.84/07/27.8408060102
- 8408050116 Forwards proprietary responses to NRC second round questions on CONDOR Topical Rept MCAP-10107 & application for withholding Responses withheld (ref 10CFR2 790(a)) RAHE, E.P. Westinghouse Electric Corp. NS-EPR-2939 84/07/23 THOMAS, C.O. Standardization & Special Projects Branch 2pp 25936 038

- --8403060125 Requests withholding of proprietary responses to NRC second round questions on COMDOR Topical Rept WCAP-10107, per 10CFR2 790
  WIESEMAIN, R A Westinghouse Electric Corp AW-84-68 84/07/23
  TMOMAS, C D Standardi
- 8408060189 Confirms completion of listed 840720 & 26 commitments on TDI dissel generators Correction of deficiencies noted during confirmatory walkdows of engine fuel oil lines completed DALG.L F Mississippi Power & Light Co. ACEM-8470392 84/08/03 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 25932 286 24x Fiche 50-446.84708/03.8408060189
- 8408340220 Forwards rinal summary Rept MCAP-10509, "Analysis of Capsule T From TVA Sequoyah, Unit 2 Reactor Vessel Radiation Surveillance Program " Change in capsule withdrawal schedule in Tech Spec Table 4 4-5 not required MILLS.L M Tennessee Valley Authority 84/07/31 ADENSAM.E Licensing Branch 4 2pp 25929 109 24X Fiche 50-328.84/07/31, 8408060220
- --B40B060231 WCAP-10509

  "Analysis of Capsule T From TVA Sequoyah,Unit 2 Reactor
  Vessel Radiation Surveillance Program "
  B0908.R S . VANICHKO.S E . CHENEY.C A Hestinghouse Electric Corp
  B4'04/30 S5pp 25929 111 24X Fiche 50-328,B4/07/31,
  B40B060220
- 8408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Dietel Generator Sets "
  RAY. C L TDI (Transamerica Delaval, Inc.) Guners Group OGTP-147-N-29 84/08/01 DENION, H R Office of Nuclear Reactor Regulation, Director 2pp 25927 064 24% Fiche 50-000, 84/08/01, 8408060324
- ~-8408060387 FAAA-84~6-56
  "Design Revieu of Elliott Model 690 Turbocharger Used on
  TDI DSRV-12~4 & DSRV-20~4 Emergency Diesel Geherator Sets "
  # Failure Analysis Associates 84/07/31 62pp 25927 066 24%
  Fiche 50~000.84/08/01.8408060324
- 8408060405 Forwards repts received by BNML & consultants Girectly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts, Analysis & Recommendations re Main Propulsion Engines M/V Columbia" and All Holling State of Licensing 1989 ALL Laboratories 84/06/28 MILLER, M Division of Licensing 1989 25926 173 244 Fiche 50-000.84/06/28,8408060405
- 8408070193 Forwards request for add1 info re AECC-4 (P/NP), "Mobile Vol Reduction Sys " Response by 840817 requested THOMAS:C O Standardization & Special Projects Branch 84/07/24 GARCIA R Aerojet Energy Conversion Co (subs of General Tire & Rubber Co ) 12pp 25937 100
- 8408070222 Informs that based on GE 840525 details GE fuel surveillance program complies U/SRP Section 4 2 II D 3 & acceptable Increased on-line surveillance per SRP Section 4 2 II D 2 still required RUBENSIEIN.L S Assistant Director for Core & Plant Systems 84706/27 GRIDLEY.R L General Electric Co 2pp 25957 051
- 8408070236 Forwards "Failure of Access Door Between Drywell & Wetwell." technical review rept Review concludes that no similar access design exists between foreign & domestic Mark II containments MDLF.1 R Reactor Operations Analysis Branch AEOD/T412 84/06/18 SEYFRIT.K V Reactor Operations Analysis Branch ip 25957 044
- --8408070242 "Failure of Access Door Between Drywell & Wetwell," technical review rept MDLF,T Director's Office AEOD/T412 84/Q6/18 3pp 25957 045
- B40B070275 Forwards add1 info on safety parameter display sys in response to B40326 request 5 suppl to SAR Bys scheduled for implementation by end of Spring 1985 refueling outage Rev 1-A to WCAP-7819 & WCAP-7685A encl HINTZ.D C Washington Public Power Supply System NRC-84-123 B4/0B/01 E15ENHVIT.D 0 Division of Licensing 25pp 25948 123 24X Fiche 50-305,84/0B/01.8408070275
- --8408070282 WCAP-7819 R01A
  Rev 1-A to "Muclear Instrumentation Sys Isolation
  Amplifier "
  LIPO-MAK.J B , BARTHOLOMEW.R Westinghouse Electric Corp
  75/04/30 33pp 25948 149 24X Fiche 50-305.84/08/01.8408070275

- --B408070288 M2AP-7685-A
  "Test Rept on Isolation Amplifiers '
  "GREER, I Westinghouse Circtric Corp 75/05/31 10pp
  25949 183 24X Fiche 50-305 84/08/01.8408070275
- 8408070401 Interms that new sys of acknowledging receipt of licensee correspondence re noncompliance found during imaginational effective 840820 Preprinted form will be used rather than ltr
  KEPPLER.J G Region 3. Office of Director 84/08/03
  Commonwealth Edison Co 3pp 25742 188 24X Fiche 50-000.84/08/03.8408070401
- B408070414 Forwards nonproprietary Rev 0 to MCAP-10170, "Key Safety Parameter Selection" % proprietary Rev 1 to MCAP-10170, "Key Safety Parameter Selection" (Generic Ltr 82-03) Proprietary Rept uithheld (ref 100FR2 790) MDCLEVER, E J Duquesne Light Co GL-82-03 84/08/01 EISENHUT, D G Division of Licensing 4pp 25938 001 24X Fiche 50-412.84/08/01 8408070414
- --8408070419 MCAP-10170 APC S1 R0

  Nonproprietary Rev O to App C to Suppl I to "Key Safety Parameter Selection for Beaver Valley,Unit Z Safety Parameter Display Bys (SPDS)"

  MORLEY,R C Hestinghouse Electric Corp 84/07/30 11pp 25938 005 24% Fiche 50-412,84/08/01.8408070414
- 8408070445 Forwards response to several TDI emergency diesel engine issues raised during NRC 5 Battelle 840726 visit Jacket water sys parameters show no evidence of flow resistance increase TUCKER, H B Dyke Power Co. 84/08/01 DENTON, H R Diffice of Nuclear Reactor Regulation, Director ADENBAM, E G Licensing Branch 4 5pp 25942 263 24X Fiche 50-413,84/08/01.8408070445
- 8408070446 Requests exemption from 10CFR50.App A. GDC 4 re elimination of postulated circumferential & longitudinal breaks in RCS main loop piping & WCAP-10559 & WCAP-10560 Repts withheld (ref 10CFR2 790)

  ODLDBERG, J H Houston Lighting & Power Co ST-HL-AE-1096
  84/07/17 DENTON-H R Office of Nuclear Reactor Regulation, Director 4pp 25940 249 24% Fiche 50-498.84/07/17,8408070446
- B408080016 Informs that B&W plans to use BMC correlation for licensing analyses to be performed w/CHATA & TEMP core thermal hydraulic analysis codes for reload repts supporting upcoming cycles of Oconce, Unit 1 & Rancho Seco TAYLON, J H Dabcock & Wilcox Co 84/08/02 THOMAS, C D Standardization & Special Projects Branch 29p 25970 306
- 8408080236 Interim Deficiency Rept DR-140 re TDI standby diesel generator fuel oil piping & header assembly Next rept will be provided by 841011 Field GC insp of generator IEGSeEGID will be performed in near future BOOKER. J E Gulf States Utilities Co RED-18318 84/07/27 CDLLINS. J T Region 4. Office of Director ip 25974 358 24X Fiche 50-458.84/07/27.8408080236
- 408030275 Forwards proprietary & nonproprietary "Mestinghouse Setpoint Methodology for Piotection Sys.Catawba Station," in response to Section 7 3 24 of SER Application for withholding proprietary rept enci
  TUCKER-H B Duke Power Co 84/07/30 DENTON:H R Office of Nuclear Reactor Regulation, Director ADENSAM.E G Licensing Branch 4 2pp 25964 228 24x Fiche 50-413,84/07/30.8408080275
- --9409080280 Requests withholding of proprietary "Hestinghouse Setpoint Methodology for Protection Sys.Catawba Station" (ref 10CFR2 790)
  WIESEKANN.R A Wastinghouse Electric Corp CAW-84-69 84/07/20
  DENTON.H Office of Nuclear Reactor Regulation. Director 8pp 23764 230 24% Fiche 50-413.84/07/30,8408080275
- --8408080284 Nonproprietary "Westinghouse Setpoint Methodology for Protection Sys. Catawba Station " Two oversize tables encl Aperture cards available in PDR JANSENR L . TULEY. C R Westinghouse Electric Corp 84/06/30 71pp 25964 238 24% Fiche 50-413,84/07/30,8408090275
- 3408080288 Summary of 840712 meeting w/B&W Owners Group re non-nuclear instrumentation sys status Attendance list & viewgraphs encl
  KADAMBI,P Operating Reactors Branch 4 84/07/27 Operating
- enci KADAMBI.P Operating Reactors Branch 4 84/07/27 Operating Reactors Branch 4 3App 25978 228 24% Fiche 50-000.84/07/27, 8408080288
- 8408070148 Final Deficiency Rept [RDC 92(84)] re potential problem w/standby diesel generator loose flexible coupling drive hubs supplied by TDl Initially reported on 840120 Also reported per Part 21 EDELMANN R Cleveland Electric Illuminating Co [RDC 92(84)] 84/07/27 KEPPLER. J C Region 3, Office of Director 2pp 25993 176 24% Fiche 50-440.84/07/27,8408090148

- 8408070179) Figured independent of the state of Rev 2 to XN-NF-84-21.

  "DC Cod Unit 2 (q.1e 5 5 Feed Generator Tube Plugging Limiting Break LOTA/ErCS Analysis," per American Electric Pager Syc Correquest CHAMBLER, J C Frien Nuclear Lo. Inc. (subs. of Exam Curp.)

  JCC 110 84 84708/77 DENTUN: HR Office of Nuclear Reactor Regulation, Director 1p 25972-0382-24X Fiche 50-316,04/08/07,84080/0178
- --B4080V0209 XN-NF-84-21 (NP) ROE
  Nunpruprietary version of Re 2 to "DC Cook,Unit 2 Cycle
  5.54 Steam Genera'or Tube Plugging Limiting Break LOCA/ECCS
  Analysis
  KAYSER:N V , CHANDLER, U , B10UT, R B Exxon Nuclear Co , Inc
  (subs of Exxon Corp ) 84/08/07 /5pp 259/2 039 24Y
  Fiche 50-314,04/08/07,8108090198
- 8408070230 Forwards proprietary Rev 1. Suppl 4 to XN-NF-82-20(P), "Exxon Nuclear Co Evaluation Model EXCII.PUR ECCS Model Updates Adjustments to FLECHT Based Heat Transfer Correlations " Rept withheld (ref 10CFR2 770) CHANDLER. J C Exxon Nuclear Co , linc (subs of Exxon Corp.) JCC 105-84 84707/27 THOMAS.C D Standardization \* Special Projects Branch 1p 25971-113
- 840807034/ Discusses alternatives for responding to NRC 840424 request for add1 into re XN-NF-82-49(P), "Exxon Nuclear Co Evaluation Model EXEM/PMR Small Brook Hodels " Exxon should respond by \$41001 to maintain current schedule THOMAS.C O Standardization / Special Projects Branch 84/07/30 CHANDLER.J C Exxon Nuclear Co , Inc (subs of Exxon Corp.) 3pp 25984 337
- 8408070353 Forwards requests for add1 info to CENPD 199, Rev ( (P/NP), "C-E Set Point Methodology " Response to questions requested by 840624 THOMAS.C O Standardization & Special Projects Branch 04/07/30 SCHERFR.A E Combustion Engineering. Inc. 5pp 25984 331
- 8408090433 Notification of 840808 meeting w/88N Owners Group in Bethesda.MD to discuss potential application of leak-before-break concept to B&N reactors KADAMBI.P Operating Reactors Branch 4 84/08/06 STOLZ.JF Operating Reactors Branch 4 2pp 25988 360
- 840B100n63 Forwards Vols I % II of "NUSCo Thermal Hydravlic Model Qualification," for RETRIAN & VIPRE COUNSIL, W G Connecticut Vankee Atomic Power Co COUNSIL, W G Northeast Ruclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities Bil27B 84/07/30 MILLER, J R Operating Reactors Branch 3 CRUICHFIELD, D Operating Reactors Branch 3 CRUICHFIELD, D Departing Reactors Branch 5 2pp 25987 0/2 24X Ficha 50-213,84/07/30.840B100063
- --8408100070 NUECO 140-1 Vol I of "NUSCo Thernal Hydraulic Model Qualification (RETRAN)" \* Northeast Utilities 84/07/30 262pp 2598/ 074 24 Fiche 50-213.84/07/30,8408100063
- --8408100077 NUSCO 140-2
  Vol II of "NUSCo Thermal Hydraulic Model Qualification (VIPRE) "

  \* Northeast Utilities 84/07/30 229pp 25987 336 24X
  Fiche 50-213,84/07/30,8108100063
- 8408100121 Responds to 040723 request for add1 info on AECC-2-P(NP) & Amend 1 Draft response discussed w/NRC.util & Sangent & Lundy on 840731 Info will be provided as Amend 2 on 840810 GARCIA.R Aerojet Energy Conversion Co (subs of General Tire & Rubber Co) 0500 4210 RG AB 84/08/08 THOMAS,C D
  Standardization & Special Projects Branch 2pp 25988 255
- 8408100127 Forwards "Calculation of Tilp Setpoint Values, Plant Protection Sys." in response to 830620 ltr VAN BRUNT, E E Arizona Public Service Co ANPP-30109-REVB 84/08/32 KNIGHTON, 0 Licensing Branch 3 ip 25991 042 24X Fiche 50-528.84/03/02.8108100127
- --8409100137 CEN-286(V) ROO Rev O to "Calculation of Trip Setpoint Values, Plant Protection Sys " 4 Combustion Engineering, Inc 84/07/31 118pp 25991 043 24X Fiche 50-528, 84/08/02, 8408100127
- B40B130170 Forwards GE rept, "Reduced RHR Svc Water Flow & Buppression Pool Temp Response Licensing Ltr Ropt " Encl replaces proprietary rept MCGAUGHY, R W Inwa Fiectric Light & Power Co NG-84-3270 B470B70B DENTION, H Office of Nuclear Reactor Regulation, Director 1p 26010 030 24X Fiche 50-331.84/08/08.8408130170

- -840813317. Feduced RHR S.c Pater Flow ? Supplies 1101 Pool Temp Response Licen ing Err Rept ' GRID Enrit L General Electric Co 81/07/18 5pp 24010 031 24% Fiche 50-331.84/03/08.8408130170
- 840813018: furwards details of items to be included in future util submittels re TDI diesel generator reliability veri+ication YOUNGBLOTU.F J. Licensing Branch 1 84/08/02 SPENCE.M D. Texas Utilities Flectric Co. (Former), Texas Utilities Generating Co.) 7pp. 26036 285 247 Fiche 50-445.84/08/02.8408130181
- 840Bi30349 Responds to 840702 request for addl info on CEN-268 re resolution of NUREG-0737. Item [1 F 3 5, 'Study Need for Automatic Trip of Reactor Coolant Pumps " Response will be discussed at 840920 neeting WELLS,R W C-E Operating Plants Guners Group WELLS,R W Northeast Utilities Service Co (subs of Northeast Utilities) RWW-84-60 84/08/07 MILLER, J R Operating Reactors Branch 3 2pp 26010 ±24
- B40B140191 Furwards xN-NF-691(P)(A). 'Stability Evaluation of BWR Core Sensitivity Analyses ' Rept withheld (ref IOCFR2 790) CHANDLER: J C Erson Nuclear Co . Inc (subs of Esson Corp ) JCC 109 84 G4/08/7/ THOMAS.C D Standardization & Special Projects Branch 1p 26042 360
- 840B140200 Forwards proprietary Amend 2 to AECC-2-P & nonproprietary Amend 2 to AECC-2-NP. 'Radwaste Vol Reduction Sys," per NRC 8407P3 request Proprietary version withheld (ref 10CFR2 790) Affidavit encl GARCIA,R Aerojet Energy Conversion Co (subs of General Tire & Rubber Co) 84/08/10 THOMAS.C D Standardization & Special Projects Branch 5pp 26043 001
- --8409140204 AECC-2-NP AO2 Nonproprietary Amend 2 to 'Radwaste Vol Reduction Sys " 4 Aerojet Energy Conversion Co (subs of General Tire & Rubber Co ) 84/08/10 Abpp 26043 OOA
- 840B140356 Forwards Suppl 1 to Rev 2 to XN-NF-83-/2, "HB Robinson, Unit 2. Cycle 10 SAR Disposition of Chapter 15 Events " Rept provides confirmatory analyses results for SAR Remainder of analyses will be submitted by 840B17 ZIMMERMAN.S R Carolina Power & Light Co NLS-84-352 84/08/08 VARGA.S A Operating Reactors Branch 1 2pp 26041 001 24X Fiche 50-261 84/08/09.840B140356
- --B40B140363 (N-NF-B3-72 S01 R02 Suppl 1 to Rev 2 to 'HR Robinson, Unit 2. Cycle 10 SAR --Disposition of Chapter 15 Events " LEACH, C.E., KAYSER, W.V., CHANDLER, J.C. Exxon Nuclear Co., Inc. (subs of Exxon Corp.) B4/07/20 33pp 26041 003 24X Fiche 50-261, 84/08/08, 840B140396
- B40B140396 Forwards Rev 2 to XN NF-B1-21(p), 'Generic Mechanical Design for Exxon Nuclear Jet Pump BWR Reload Fuel " Rept withheld (ref 10CFR2 /90) CHANDLER, J C Exxon Nuclear Co, Inc (subs of Exxon Corp ) JCC 107 84 B4/08/0.7 THOMAS, C O Standardization & Special Projects Branch 7pp 24049 078
- B40B140410 Forwards "Analyses of Capsule TE1-B. Toledo Edison Co. Davis-Bosse Nucleor Power Station. Unit I Reactor Vessel Matl Surveillance Program" "CRDUSE, IR P Toledo Edison Co 1069 84/08/10 EISENHUT, D 0 Division of Licensing 1p 26049 001 24X Fiche 50-346, 84/08/10, 8408140410
- --8408140413 BAW-1834

  "Analyses of Capsule TE1-B.Toledo Edison Co.Davis-Besse
  Nuclear Power Station. Unit : Reactor Vessel Hatl
  Surveillance Program "
  LOWE, A. COLLINS.L L., EWINO.J W. Babcock & Wilcox Co. 84/05/31
  75pp 26049 002 24% Fiche 50-346,84/08/10.8408140410
- 840B140426 Provides address for transmitting all operator licensing correspondence to Region III ofc.except info for examiners MALKER R D Region 3. Office of Director 84/08/10 Michigan. Univ of, Ann Arbor. MI 2pp 26051 198 24X Fiche 50-000, 84/08/10.8408/140426
- 840814042? Forwards "Analyses of Capsule ANI-A.Arkansas Power & Light Co.Arkansas Nuclear One.Unit i.Reactor Vessel Matl Burveillance Program "
  MARSHALL.JR Arkansas Power & Light Co iCAN088407 84/08/06 STOLZ.JF Operating Reactors Branch 4 ip 26049 301 24X Fiche 50-313.84/08/06.8408140429

- --8408140423 Enti-1836
  'Analyses of Capsule AM1-A, Arxansas Power & Light Co.
  Arkansas Nuclear Dne, Unit 1. Reactor Vessel Mati Surveillance
  Program
  LOWE.A.L. ANDLAND.J.D., COLLINS.L.L. Babcock & Milcox Co.
  84/07/31 93pp 26049 302 24/ Fiche 50-313,84/08/06,8408140429
- 840815008/ Forwards proprietary response to NRC 840713 request for add1 info on Special Rept MFN-068-84, "Generic Licensing of 1984 Lead Test Assemblies ' Encl Lichheld (ref LICER2 790) CHARNLEY, JS General Electric Co MFN-102-84 84/07/24 THOMAS.C O Standardization t Special Projects Branch 1pp 24042-121
- B408130180 Application to amend License DPR-31, modifying designation of areas in steam generator imperfections found & allowing sleeking of tubes Proprietary affidavit & BAM-1823P. "Once-Through Steam " encl Fee encl ORIFFIN.J M Arkansas Power & Light Co ICAN088404 B4/08/13 STOLZ.J F Operating Reactors Branch 4 6pp 26067 132 24X Fiche 50-313.84/08/13.8408150180
- 8408150414 Forwards IE Insp Rept 50-445/84-18 on 840501-31 & notice of violation Areas inspected include preoperational test witnessing followup of TDI diesel generator insp & plant tours
  BANGART, R & Region 4, Office of Director 84/07/26 SPERCE, M D
  Toxas Vtilities Electric Co (formerly Texas Vtilities Generating Co > 2pp 26077 252 24X Fiche 30-445,84/07/26.8408150414
- --8408150417 Notice of Violation from Insp on 840501-31 \* Region 4, Office of Director 84/07/26 2pp 26077 254 24X Fiche 50-445,84/07/26,8408150414
- --8408150440 IE Insp Rept 50-445/84-18 on 840301-31 Violations noted failure to foliou procedure during Train A emergency diesel generator auxiliary sys retest % hold tags improperly removed from Train A diesel engine KELLEY.D L , SMITH.W F , HUNNICUIT.D M Region 4, Office of Director 84/07/04 10pp 26077 256 24X Fiche 50-445,84/07/26,8408130414
- B408180438 Motion for leave to make restricted svc of certain documents, for protective order & for in camera cross-examination re documents Certificate of Svc encl Related correspondence
  FARLEY,E M Long Island Lighting Co FARLEY,E M Hunton & Williams DSB 057 OL 84/08/14 Atomic Safety and Licensing Board Fanel 9pp 26068 262 24% Fiche 50-322.84/08/14,8408150438
- 840B150473 Forwards direct testimony & supporting exhibits on adequacy & reliability of TDI emergency diesel generators W/o motion for protective order Certificate of Svc enc.) Related correspondence TAR&ETZ-D B Hunton & Williams TAR&ETZ-D B Long Island Lighting Co DSB 045 DL 84/08/14 BRENNER.L. FERGUSOR G A , MDRRIS.P A Atomic Safety and Licensing Board Panel 4pp 24048 295 24X Fiche 50-322.84/08/14.8408150473
- --8408150476 Testimony of CH Wells.DP Johnson.HF Wachob.C Seaman.D Cimine & NK Burrell re shotpsening of replacement crankshafts
  Related correspondence
  WELLS,C H. JQHNSON.D P., WACHOB.H F. Long Island Lighting Co
  OL 84/08/14 36pp 26068 299 24X Fiche 50-322.84/08/14,
  DAGGISA472
- ---B408150485 Testimony of RL McCarthy, PR Johnson, EF Montgomery & SK Chen on Suffelk County contention re replacement crankshafts on diesel generators Related correspondence MCCARTHY, R. L. JOHNSON, P. R. MONTGOMERY, E. F. Long Island Lighting Co. CL. 84/08/14 62pp 26058 337 24% Fiche 50-322,84/08/14,8408150473
- --BAOSISO47B Testimony of EJ Youngling & FF Pischinger on Suffolk County contention re replace ent crankshafts on diesel generators Exhibits enci Related correspondence YOUNGLINGE J. PIBCHINGER.FF Long Island Lighting Co OL B4/08/14 600pp 26069 036 24X Fiche 50-322.84/08/14, B408150473
- --B40B1S0505 Vols 1, 2 % 3 of testimony of RL McCarthy, CA Rau, CH Wells, HF Wachob, D Johnson, RK Taylor, CK Beaman, EJ Youngling, CS Mathews, MH Lowey, JF Wallacs & MH Schuster on Suffalk County contention recylinder blocks Related correspondence MCCARTHY, R L , RAU, C 4 , WELLS, C H Long Island Lighting Co GL B4/08/14 300pp 26070 313 24X Fiche 50-322, 84/08/14.

- --8408150514 Vols 1 & 2 of testimony of DO Harris DP Johnson, RL McCarthy, FF Pisthinger, CK Searan LA Swanger & EJ Yaungling on Suffolk County contention re AE piston skirts Related correspondence
  HARRIS, D O , JOHNSON, D P , MCCARTHY, R L Long Island Lighting Co
  OL 84/08/14 450pp 260/1 200 24X Fiche 50-322, 84/08/14, 8408150473
- --B408150530 Vols 1 & 2 or testimony of CK Seaman.EJ Youngling.
  JC Kammeyer.CH Hells.LA Swangor.JF Wallace.CB Mathews &
  FC Pischinger on Suffolk County contention re cylinder
  heads Exhibits 1-26 encl Related Correspondence
  BEAMAN.C K , \UNGLING.E J , KAMMEYER.J C Long Island Lighting
  Co DL 84/08/14 300pp 26072 327 24% Fiche 50-322.84/08/14,
  8408150473
- B40816001B Discusses revised draft maint t surveillance program plan Revs include five-phase approach to program mpt to identification of relevant industry programs to approx schedules Meeting scheduled for 840822 to address plan RUSSELL.N T Division or Human Factors Safety 84/08/07 TAYLOR.J H Babcock & Wilcox Co ip 26128, 213
- 8408160026 Forwards IE Insp Rept 50-445/84-20 on 840503-0619 No violations or deviations identified BANGART, R L Region 4, Office of Director 84/07/26 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co ) 2pp 26108 150 24% Fiche 50-445,84/07/26,8408160026
- --8408160037 IE Insp Rept 50-445/84-20 on 840503-0619 No violations or deviations noted Major areas inspected work & documentation associated w/si\*e portion of recertification program implemented on Train B TDI emergency diesel generator SMITH, N F HUNNICUIT, D M Region 4, Office of Director 84/07/05 9pp 24108 152 24X Fiche 50-445,84/07/26,8408160026
- 8408160066 Final deficiency rept re louse drive hubs on overspeed governor drive shaft on TDI diesel engines Initially reported on 840203 Hubs acceptable Also reportable under Part 21
  MILLS.L. M. Tannessee Valley Authority 84/08/03 O'REILLY, J.P. Region 2. Office of Director 2pp 26108 224 24X
  Fiche 50-438.84/08/03.8408160066
- 8408160249 Notification of 840827 meeting w/C-E Owners Group Operations Subcommittee in Bethesda, MD to discuss task analysis requirement of Suppl 1 to NUREG-0737 & Generic Ltr 82-33 & portions of CEN-192. Rev 2 re inadequate care conting CLAYTON. H B Procedures & Systems Review Branch GL-82-33 84/08/09 ZIEHANN. D L Procedures & Systems Review Branch 5pp 24124 248
- B40B160371 Forwards nonproprietary WCAP-10566 & proprietary WCAP-10567.
  "Technical Bases for Eliminating Large Primary Loop Pips
  Rupture ." per Generic Ltr 84-04 & application for
  uithholding info Proprietary rept withheld (ref 10CFR2 790)
  DE VINCENTIS. J Yankes Atomic Electric Co DE VINCENTIS. J Public
  Bervice Co of New Hampshire QL-84-04 84/08/09 KNIOHTON, 6 W
  Licensing Branch 3 2pp 26091 099 24X Fiche 50-443,84/08/09,
  3408160371
  - 3408160373 Requests withholding of stated proprietary rept from public disclosure (ref 10CFR2 790) Affidavit CAM-83-80 entl WIESEMANN; R A Hestinghouse Electric Corp CAM-84-34 84/06/07 DENTON, H R Office of Nuclear Reactor Regulation, Director App 26091 101 24X Fichs 50-443,84/08/09,8408160371
- -8408160378 WCAP-10566
  Nonproprietary "Technical Bases For Eliminating Large
  Primary Loop Pipe Rupture as Structural Design Basis for
  Seabrook Units 1 & 2 " Info deleted (ref 10CFR2 790)
  SHAMYA A . CLARKJA F F. LEE. Y 8 Westinghouse Electric Corp
  84/06/30 40pp 26091 107 24X Fiche 50~443,84/08/09,8408160371
- 1408160374 Forwards proprietary "Conceptual Design Description for Pilgrim Nuclear Power Station Emergency & Plant Info Computer (EPIC) Safety Parameter Display Sys (SPDS)." per 831026 commitment & TM1 Action Item 1 D 2 Rept withheld HARRINGTON W D Buston Edison Co DECO 84-133 84/08/10 VASSALLO, D B Operating Reactors Branch 2 1p 24091 192 24X Fiche 50-293.84/08/10,8408160374
- 8408160377 forwards proprietary NEDE-24284-PA & nonproprietary NEDD-24284-A. "Assessment of Fuel Rod Dowing in GE BNRs " Affidavit for uithholding proprietary version encl TP2 790)
  - 7707 General Electric Co MFN-104-84 84/07/27 THOMAB,C Cl tion & Special Projects Branch 5pp 26088 225

8408160271 Firwards 'Design Re lew of Engine Bast' Bearing Caps for TDI DBRV-16 Diesel Engines'
RAY.C L IDI (Transamelica Pelavel, Inc.) Gwners Group
GGTP-181-11 31 84/08/10 DENTON-HR Office of Nuclear Reactor
Regulation

--8408160403 FAAA-84-6-93
"Design Review of Engine Base \* Rearing Caps for TD1
DSRV-L6 Diesel Engines "
# failure Analysis Associates PAO7976 84/08/31 44pp
26071 149 24% Fiche 50-000,84/08/10,8408160374

8408160395 Forwards "Design Review of Elliott Model 909 Turbocharger Used on 701 DSR-48 & DSRV-16 Emergency Dissel Generator Sets," representing +inal QA verified rept Addl copy forwarded to BNML, per NRC request RAY.C L TDI (Transamerica Delaval, Inc.) Owners Group OGTP-170-N-33 84/08/14 DENION.H R Office of Nuclear Reactor Regulation, Director 2pp 26088 163 24X Fiche 50-000, 84/08/14, 8408160395

--B40B160397 FAAA-84-5-7
"Design Review of Elligtt Model 90G Turbocharger Used on TDI D5R-48 & D5RV-16 Emergency Diesel Generator Sets "
# failure Analysis Associates B4/07/31 61pp 260BB 165 24X
Fiche 50-000, B4/08/14, B408160395

8408160409 Ack receipt of 840703 ltr denying C-E Owners Group 840509 request for relief from IRC review fee on CEN-152 Addl info re further actions on review fee will be forwarded following C-E Owners Group 840720 meeting WELLS.R W C-E Operating Plants Owners Group WELLS.R W Northeas Utilities RWM-84-61 84/08/09 MILLER.W O License Fee Management Branch 1p 26085-360

B40Bi60441 Dockets Rev 7 to NEDO-20776, "Spent Fuel Svcs Operation & OE U Mgt Corp QA Plan," u/WC Wheadon & DM Dawson 830329 & O210 ltrs, respectively, to assure dacket file complete due to rev & resubmittal of rept as Rev 8
ROBERYS, J P Advanced Fuel & Spent Fuel Licensing Branch 84/08/10 Advanced Fuel & Spent Fuel Licensing Branch ip 26126 078

- --8408160466 Forwards Rev 7 to NEDO-20776. "Spent Fuel Sycs Operation & CE U Mgt Corp GA Plan " Rev due to organizational change within spent fuel sycs operation & GE U Mgt Corp WHADDON, W C Operal Electric Co 83/03/27 ROBERTS, J P NRC No Detailed Affiliation Given ip 26/26/079
- --8408160472 Forwards Rev 7 to NEDO-20776. "Spent Evel Svcs Operation & GE U Mgt Corp QA Plan." referenced in License SNM-2500 for GE Morris Operation & incusporated in NEDO-21326. App B-8 DAMSD, D M General Electric Co DMD-709 83/02/10 ROUSE, L C Advanced fuel & Spent Evel Licensing Granch 1p 26126 080
- B40Bi60485 Forwards IE Insp Rept 50-445/84-i5 on 840301-0430 & notice of deviation
  BANGART, R L Region 4, Office of Director 84/07/30 SPENCE, M D
  Texas Vtilities Electric Co (formerly Texas Utilities Generating
  Co ) Jpp 26107 296 24X Ficha 50-443,84/07/30,8408160485
- --840B160300 IE Insp Rept 50-445/84-15 on 840301-0430 Deviation noted failure to provide review & approval for safety-related maint instructions, per Rev 2 to Reg Guide 1 33 KELLEY, D. L., SMITH.W.F., HUNNICUTT, D.M. Region 4. Office of Director 84/07/27 lipp 26107 300 24X Fiche 50-445.84/07/30, 8408160485
- 8408160517 Significant Deficiency Rept SD 413-414/84-18 re residual stress in Tupe AN piston skirts of TDI diesels Initially reported on 840628 Ekrrt cracks being evaluated Next rept by 850115
  TUCKER: H B Duke Power Co 84/07/27 Q'REILLY. J P Region 2, Office of Director 3pp 26108 012 24X Fiche 50-413,84/07/27,8408160517
- 8408170292 Forwards Rev 1 to NEDO-30477, "Safety Analysis of RHR Intertie Line, Monticello Nuclear Generating Plant " Rev suppls 840927 application to amend License DPR-22 MUSOLF, D. Northern States Power Co. 84/08/16. Office of Nuclear Reactur Regulation, Director 1p. 26118 103 24x
  Fiche 50-263.84/08/16.8408170292
- ~-8408170262 NEDO-30477 RO1 Rev 1 to. "Garety Analysis of RHR Intertie Line, Monticello Nuclear Generating Plant " BRANDON, R J , ORIOLET, R L General Electric Co 84/06/30 27pp 26118 104 24X Fiche 50-263,84/08/16.8408170282

63pp 26088 230

- 8406170735 Furwards OE Design Memos 170-107 \* 170-109 \* Bechtel Stress Rept Calculation SRIDRS5-9527 re stiff pipe clamps owscribed in IE Info Notice 93-80 Submittal addresses draft SER Upen Item 96 MITTL R I Public Service Electric \* Cas Co of New Jersey IEIN-83-80 84/08/14 SCHWENCER.A Licensing Branch 2 2pp 26114 062 24X Fiche 50-254.84/08/14.8409170336
- --B408170337 170-107

  "Clamp Induced Stress on Hope Creek Recirculation Piping"

  FARRELL, C A , ZALIZNIAK, M , THDMPSON, J L General Electric Co
  B4/07/27 18pp 25114 064 24% Fiche 50-354,84/08/14,8408170336
- --8408170342 170-109
  Clamp Induced Stress on Hope Creek Main Steam Piping Lines
  C & D
  7ALIZNYAK, N A , FARRELL, C A , THOMPSON, J L General Electric Co
  84/07/27 22pp 26114 082 24X Fiche 50-354,84/08/14,8408170336
- B408200322 Final Deficiency Rept DER 83-61 re C-E low pressure safety injection pump failure to start & produce required head Case wear rings replaced 5 clearance between impeller & casing increased Proprietary CEN-285 (V)-P enci VAN BRUNT.E E Ariona Public Service Co ANPP-30134-TDS/B4/QB/O9 BISHOP,T W Division of Resident, Reactor Project & Engineering Programs 40pp 26133 318 24% Fiche 50-528,84/08/09,8408200322
- 8408200481 Forwards SEX re reliability of diesel generators Related correspondence JOHNSUN G E Hearing Branch 4 DSB 175 DL 84/08/14 GUILD.R Palmatto Alliance RILEY.J L Carolina Environmental Study Group lipp 26136-307 24X Fiche 50-413.84/08/14.8408200481
- B40B200497 Forwards additinfo re NRC witnesses on intervenor diesel generator contention & two additionments Related correspondence
  JOHNEGON G E Hearing Branch 4 DSB 172 OL B4/08/15 GUILD, R
  Palnetto Alliance RILEY, J L Carolina Environmental Study Group ip 26137 001 24X Fiche 50-413.84/08/15, 840B200499
- --8408200511 Supplemental responses to Palmetto Alliance & Carolina Environ Study Group 840318 general interrogatories Cortificate of Svc encl Related correspondence JOHNSON, G E Hearing Branch 4 UL 84/08/15 Palmetto Alliance 15pp 26137 002 24% Fichs 50-413,84/08/15,8408200499
- B40B210311 Forwards Rev 5 to GA program description for design & const phases includes revs to Bechtel & Ebasco programs OPREA:0 & Houston Lighting & Power Co ST-HL-AE-1019 B3/11/01 CDLLINS.J T Region 4, Office of Director 5pp 26179 001 24X Fiche 50-498.83/11/01.8408210311
- --8408210317 Rev 5 to QA program for design & const of South Texas Project \* Houston Lighting & Power Co 83/11/01 54pp 26179 006 24X Fiche 50-498,83/11/01.8408210311
- B40B210365 Forwards "Torsiograph Test of Emergency Diesel Generator 1A at Catawba Nuclear Power Station." in response to 840B09 telcon request Statt 61 should show run duration of 35 h rather than 43 TUCKER.H B Duke Power Co 84/08/14 DENTON.H R Office of Nuclear Reactior Regulation, Director ADENSAM.E G Licensing Branch 4 3pp 26178 175 24% Fiche 50-413,84/08/14.8408210363
- --8408210370 FAAA-84-5-23
  "Torsiograph Test of Energency Diesel Generator IA at Catawba Nuclear Power Station"
  \* Failure Analysis Associates PA07702 84/05/29 19pp 26178 178 24X Fiche 50-413.84/08/14.8408210365
- 84082103/5 Forwards 85W summary technical repts of first capsule from reactor vessel surveillance program.por App H of 10CFR50 Repts delayed due to administrative oversight STEMART.FL Virginia Electric & Power Co 479 84/08/16 DENTON.H R Office of Nuclear Reactor Regulation. Director Ip 26178 001 24x Fiche 50-338.84/08/16.8408210375
- --8408210387 BAN-1794
  "Analysis of Capsule V,VEPCO,North Anna Unit 2,Reactor
  Vessel Matis Surveillance Program "
  LOWC.A L. COLLINS.L L. PAVINICH.N A Babcock & Wilcox Co
  83/10/31 173pp 24178 002 24X Fiche 50-338,84/08/16,8408210375
- --8408210393 BAW-1638
  "Analysis of Capsule V.VEPCO.North Anna Unit 1, Reactor
  Vessel Matls Surveillance Program "
  LOMEA L. PAVINICH & A. SCHMOTZER, J.K. Babcock & Wilcox Co.
  81/05/31 76pp 26178 099 24X Fiche 50-338.84/08/16.8408210375

- 8408210376 Furwards final Containment Issue Review Panel rept
  "Assessment of Humphrey Concerns." technical memo
  ENOLAND.L A Containment Issues Dumers Group ENOLAND.L A Gulf
  States Utilities Co LAF-OG-121 84/07/27 DENION.H R Office of
  Nuclear Reactor Regulation. Director 2pp 26180 001
- --8408210382 TM-928
  "Assessment of Humphrey Concerns." technical memo
  PATEL.B R Containment Issues Owners Group PATEL.B R Creare,
  Inc HENNESSY.N P Stone & Wabster Engineering Corp 84/07/31
  186pp 26180 003
- B408210484 Forwards 'Emergency Response Guidelines Comparison of Rev 1 W/Basic." per NRC 840620 request for addl info SHEPPARD. J J Westinghouse Operating Plants Guners Group SHF7PARD. J J Carolina Power & Light Co. 06-132 84/08/15 EISENHUT.D G Division of Licensing 4pp 26177 206
- --8408210489 "Emergency Response Guidelines Comparison of Rev 1 W/Basic "
  \* Westinghouse Electric Corp 84/08/15 21pp 26177 210
- 8408210500 Forwards Rev 6 to QA program description for design & const phase of facilities Changes clarify definition of Bechtel div quality policies & defines responsibilities for trend analysis

  OPREA:0 W Houston Lighting & Power Co ST-HL-AE-1077 B4/04/02

  COLLINS.J T Region 4, Office of Director 3pp 26:48 175 24X

  Fiche 90-498.84/04/02.8408210500
- --8408210503 Rev 6 to GA program description for design & const of facilities + Houston Lighting & Puwer Co 84/04/02 190pp 26148 178 24X Fiche 50-498,84/04/02,8408210500
- 8408220544 Summary of 840831 meeting w/BWR Gwners Group Subcommittee on Energency Procedures & GE re open items in SER concerning energency procedure Suidelines List of attendees encl MCCGY, M A Procedures & Systems Review Branch 84708716 ZIEMANN.D L Procedures & Systems Review Branch 12pp 26199 342
- 8408230041 Ack receipt of nongroprietary & proprietary STD-R-03-008, "Hittman RADLOK High Integrity Containers," transmitted on 840428 Tentative schedule for review of rept encl TIKTINEKY,D H Engineering Branch (Post 831001) 84/08/14 LEOUC.R J Westinghouse Hittman Nuclear, Inc. 2pp. 26233 331
- B40B230051 Forwards response to TDI emergency diesel generator issues raised by NRC & Dattelle personnel during 840726 visit Identification of cylinder heads addressed TUCKER, H B Duke Power Co B4/0B/0B DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E G Licensing Branch 4 4pp 26204 014 24x Fiche 50-413.84/08/08,8408230051
- 8408230049 Requests review & comments on encl Westinghouse Hittman STD-R-03-008, "Mittman RADLOK High Integrity Containers," by 84102 Encl withheld BARRETIL H Engineering Branch (Post 831001) 84/08/15 COSTANZI,F A Division of Waste Management 1p 26233 272
- 8408230084 Forwards responses to questions re BAW-10155 "FDAM2," submitted on behalf of BtW Quners Group as part of small break LOCA methods program response to NUREG-0365 & NUREG-0737. Item II K 3 30 TAYLOR. J H Babcock & Wilcox Co ESC-835 84/08/15 THOMAS. C Standardization & Special Projects Branch 14pp 26209 041
- 8408230073 Forwards VN NF-84-72, Suppl 1, "Large Break LOCA-ECCS Analysis W/Increased Enthalpy Rise Factor Break Spectrum" Info submitted to suppl request for license amend for Cycle 10 operation CUTIER: A B Carolina Power & Light Co NLS-84-378 B4/08/20 VARGA: S A Operating Reactors Branch 1 2pp 26208 082 24X Fiche 50-261,84/08/20.8408230073
- --B408230103 XN-NF-84-72 801
  "Large Breat LDCA-ECCS Analysis W/Increased Enthalpy Rise
  Factor Break Byectrum"
  TAHVILI.T, KAYSER W V, CHANDLER J C Exxon Nuclear Co, Inc
  (subs of Exxon Corp.) B4/08/31 102pp 26208 084 24X
  Fichs 50-261,84/08/20,8408230093
- 8408230107 Forwards discussion of containment thermal insulation safety issues considered for Cwens-Corning NUKON insulation (Topical Rept OCF-!) Issues should be included in NRC review process
  PINSKY.9 P Gwens-Corning Fiberglas Corp 84/08/17 DENTON, H R Office of Nuclear Reactor Regulation, Director THOMAS, C O NRC No Obtailed Affiliation Ofven 6pp 26209 055

- 8408230117 Forwards XN-NF-94-74, "Plant Transient Analysis for HB Robinson Unit 2 at 2.300 KWt W/Increased FN(Delta)H " CUTTER.A B Carolina Power & Light Co NLS-84-381 84/08/20 VARGA.S A Operating Reactors Branch 1 2pp 26208 187 24X Fiche 50-261.84/08/20.8408230117
- ---9408230122 XN-NF-84-74

  "Plant Transient Analysis for HB Robinson Unit 2 at 2,300

  Mit U/Increased FN(Delta)H "

  LEACH, C E , ADAMS, F T , KILLGURE, M R Erxon Nuclear Co , Inc

  (subs of Erxon Corp > 84/08/16 200pp 26208 189 24X

  Fiche 50-261,84/08/20,8408230117
- B40B230263 Forwards XR-NF-B3-61, "DC Cook Unit 1 LOCA-ECCS Analysis for Extended Exposure" & proprietary XN-NF-B4-25(P), "Mechanical Design Rept Suppl for DC Cook Unit 1 Extended Burnup Fuel Assemblies "Proprietary rept withheld CHANDLER: J C Exon Nuclear Co , Inc (subs of Exxon Corp ) B4/08/21 DENTON: A Defice of Nuclear Reactor Regulation. Director 5p 26204 028 24X Fiche 30-315,84/08/21,8408230263
- --B408230266 XN-NF-83-61

  "DC Cook Unit i LOCA-ECCS Analysis for Extended Exposure "
  TAHVILI.T, HAYSER,W V. STOUT,R B Exron Nuclear Co. Inc (subs of Exxon Corp.) B3/03/03 33pp 26204 033 24x
  Fiche 50-315,84/08/21.8408230263
- 840B230340 Forwards proprietary draft answers to questions in NRC Request 2 for add1 info on WcAP-10054(P) & WCAP-10054, Addendum 1 to "Westinghouse S-all Break ECCS Evaluation Model Using NOTRUMP Code for C-E NSSS " RAMEC P Westinghouse Electric Comp NS-EPR-2940 84/08/10 THOMASIC D NRC - No Detailed Affiliation Given 3pp 26205 350
- --8408230346 Requests proprietary draft answers to questions in NRC Request 2 for add1 info on WCAP-10054(P) & WCAP-10054, Addendum : "Westinghouse Small Break ECCS Evaluation Model Using NOTRUMP Code." be withheld (ref 100FR2 790) WIESEMANN, R A Westinghouse Electric Corp AM-84-74 84/08/10 THOMAS.C O NRC - No Detailed Affiliation Given ip 26205 35:
- B40B240115 Forwards SEM re TDI Owners Group program plan BER addresses design review/quality revalidation program testing & insp. maint & surveillance & sets forth requirements for operation prior to completion of program plan EISENHUT.D G Division of Licensing B4/08/13 GEORGE, J B TDI (Transamerica Delavat. Inc.) Owners Group 1p 26255 174 24X Fiche 50-000.84/08/13.8408240115
- --8408240157 Safety evaluation of TDI Owners Group program plan Based on BRNL evaluation.plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc 4 NRC No Detailed Affiliation Given 84/08/13 21pp 26255 175 24X Fiche 50-000.84/08/13.8408240115
- '408240122 Forwards proprietary responses to 840326 request for addition re NEDE-22148 concerning extended burnup application Responses withheld (ref 100FR2 790)
  CHARNLEY J S General Electric Co MFN-120-84 84/08/16
  THOMAS C D Standardization & Special Projects Branch 19
  DADO7 313
- 40824026B Forwards proprietary responses to four technical questions re XN-NF-75-21(P), "XCDBRA-IIIC Computer Code to Determine Distribution of Coolant During Steady State & Transient Core Operation " Response withheld (ref 10CFR2 790) CHANDLER, J C Exxon Nuclear Co . Inc (subs of Exxon Corp ) 84/08/17 THOMAS, C O Standardization & Special Projects Branch ip 26223 185
- |408240426 Interin Deficiency Rept DR-220 re license indications on valve seats of cyclinder leads in standby diesel generators supplied by TDI Interin or final status rept will be submitted by 84:101
  BEDKER.JE Gulf States Utilities Co DR-220 84/08/13
  COLLINS.JT Region 4. Office of Director ip 26237 120 24X Fiche 50-458.84/08/13.8408240426
- 8408270065 Forwards Insp Repts 50-445/84-17 re disassembly, insp & reassembly of TDI emergency diesel generator. 50-445/84-05 re allegations on fabrication of pipe supports & restraints & 50-445/84-10 re walkdown Related correspondence
  MIZUNDLG S Hearing Branch 1 DSB 304 CL 84/08/16 BLOCH.P B Atomic Safety and Licensing Board Panel 1p 26247 069 24X
  Fiche 50-445,84/08/16.8408270065
- 8408270098 Forwards response to NRC 831229 ltr re TDI emergency diesel generators Includes procurement & performance specs & inspresults

  BHELL-R H Tennessee Valley Authority 84/08/17 ADENBAM.E Q Licensing Branch 4 167pp 26248 032 24X Fiche 50-438.84/08/17, 8408270098

- B408270109 Forwards SEM re TD1 Diesel Generator Owners Group program plan W/o encl Related correspondence
  JOHNSON, G E Hearing Branch 4 DSB 310 DL 84/08/20
  KELLEY, J L , PURDOM, P M , FOSTER, R F Atomic Safety and Licensing
  Board Panel tp 26247 325 24% Ficha 50-413.84/08/20.8408270109
- 8408270122 Forwards SEK re TDI Diesel Generator Gwners Group program plan Rept discussed during 840810 conference call Related correspondence MOGRE JF Hearing Branch 1 DSB 308 GL 84/08/21 KELLEY, JL, CARPENTER, JH, BRIGHT, O O Atomic Safety and Licensing Board Panel 50pp 26248 002 24X Fiche 30-400.84/08/21.8408270122
- 8408270137 Mation for extension of time until 840831 to file direct testimony as apposed to presently scheduled date of 840821 Related correspondence GODDARD.R J Hearing Branch 3 DSB 314 CL 84/08/17 Atomic Safety and Licensing Board Panel 2pp 26245 213 24X Fiche 50-322.84/08/17.8408270137
- --8408270143 Affidavit of R Caruso supporting NRC motion for extension of time to file testimony by TDI emergency diesel generators Certificate of Svc ent! Related correspondence CARUSOR Division of Licensing DL 84/08/17 7pp 26245 215 24X Fiche 50-322,84/08/17.8408270137
- B40B270195 Requests exemption to revise iOCFR170 license fee schedule re GESSAR II review Exemption to schedule appropriate since review of GESSAR II design committed under regulations & policies in existence in early 1982 SHERMOOD, 0 G Deneral Electric CO MFNN115-84 B4/08/10 DIRCKS. W J Office of the Executive Director for Operations 2pp 26245 222 24X Fiche 50-447.84/08/10.8408270155
- 8408270159 Informs that fee sent to Licensing Fee Mgt Branch for review & acceptance of 840724 request to extend use of burnable poison rod assembly retainers for four 18-month fuel cycles
  TAYLOR, JH Bapcock & Hilcox CO ESC-537 84/08/20 THOMAS, C Standardisation & Special Projects Branch 1p 26245 258
- 8408270167 Application to amend License DPR-49, revising Teth Specs to allow power uprate to 1,658 M/t Approval requested prior to startup for Cycle 8 Forwards N/EDD-30603 5 NEDC-30603-P NEDC-30603-P uithheld (ref 10CFR2 790) Fee paid MCOAUGHYAR W lows Electric Light 3 Power Co NG-84F-2518 84/08/17 DENIGN. HR Defice of Nuclear Reactor Regulation. Director 20pp 26244 081 24% Fiche 50-331,84/08/17.8408270167
- --8408270175 NEDD-30603 "D Arnold Power Uprate " BRANDON:R J. GRIDLFY.R L. General Electric Co 84/07/31 33pp 26244 153 24X Fithe 50-331,84/08/17,8408270167
- B40B270312 Documents changes to computer codes compromising 1981 ECCS evaluation model described in Rev 1 to WCAP-9220-P-A Impacted computer codes are BATAN. COCO & LOCTA Nestinghouse plants need reanalysis, per 10CFRSO 46
  RAHE.E P Westinghouse Electric Corp NS-EPR-2952 84/08/14
  THOMAS. CO Standardization & Special Projects Branch 8pp
- B40B270409 Forwards proprietary & nonproprietary Rev 2 to "CPC/CEAC Sys Phase I Software Verification Test Rept." Rev 0 to "CPC/CEAC Sys Phase II ." & Rev 0 to "SONOSE-2 Cycle I " Proprietary repts withheld (ref 10CFR2 790) MEDFORD.M O Southern California Edison Co 84/08/01 KNIOMION.G W Licensing Branch I 2pp 26238 001 24X Fiche 50-361.84/08/01.8408270409
- --84082/0412 CEN-269(8)-NP ROO
  Nonproprietary version of Rev O to "CFC/CEAC Sys Phase II
  Software Verification Test Rept "
  + Combustion Engineering, Inc. 84/03/31 25pp 26238 003 24X
  Fiche 50-361,84/08/01.8408270409
- ~-8408270416 CEN-266(S)-NP ROO
  Nonproprietary version of Rev O to "SONOS-2 Cycle 1, CPC & CEAC Data Base "
  4 Combustion Engineering, Inc 84/03/31 66pp 26238 027 24% Fiche 50-361, p4/08/01.8408270409
- --8408270418 CEN-176(S)-NP RO2

  Monproprietary version of Rev 2 to "CPC/CEAC Sys Phase I Software Verification Test Rept "

  « Combustion Engineering, Inc. 84/03/31 27pp 26238 096 24X Fiche 50-361,84/08/01,8408270409

OB280109 Forwards outline of actions required to insure reliability of TDI V-20 diesel engines prior to restatt, in response to B40629 summary of operating experience, they results & analysis results
BERLINGER.C H Division of Licensing B4/08/20 GRIMES.C I Systematic Evaluation Program Branch 11pp 26294 141 24X
Fiche 50-206.84/08/20.8408280109

OBEB0122 Forwards application fee for XN-NF-84-67(P), "Stability Evaluation Methodology for BUR Cores," per 10CFR170 CHANDLER, J C Exxon Nuclear Co , Inc (subs of Exxon Corp.) JCC 112 B4 84/08/15 MILLER, N O License Fee Management Branch 1p 26261 125

OB280202 Application for amend to License DPR-49, revising Tech Specs re operating limits of new bundle types, LQCA design basis, MAPLHOR & min critical power ratio for Cycle 8 reload MCGAUGHY, R W I now Electric Light & Power Co NG-84-3525 S4/08/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 26264 057 24X Fiche 50~331,84/08/17,8408280202

B408260209 NEDD-21082-03 APP A
App A to "LOCA Analysis Rept for Dwane Arnold Energy Ctr
(Lead Plant) "
" General Electric Co B4/06/30 46pp 26264 091 24X
Fiche 50-331,84/08/17,8408280202

B408280211 23A1739 R00
Rev O to "Supplemental Reload Licensing Submittal for Duane Annold Atonic Energy Ctr. Unit 1, Reload 7 "
LAMBERT.P A General Electric Co 84/06/30 22pp 26264 138 24X Fiche 50-331, 84/08/17, 8408280202

OB280205 Testimony of OH Hallman.RP Muschick.SR Ward, JA Gorman. CA Mplls.LA Swanger.SK Chen.JD Barbour, JH Curtis & RC Camberg re problems encountered in diesel generator qualification program Related correspondence HALLMON.G W. MUSCHICK.R P., WARD.S R Duke Power Co DSB 322 OL 84708/18 444pp 26271 316 24X Fiche 50-413,84708/18,8408280205

OB280212 Forwards proprietary responses to Round Two questions on Rev 2 to XN-74-5, "Description of Exxon Nuclear Plant Transient Simulation Model for PWRs. (PTSPWR) " Responses withheld (ref 100FR2 790) CHANDLER, J C Exxon Nuclear Co , Inc (subs of Exxon Corp.) JCC 111 84 84/08/14 THOMAS. C O Standardization & Special Projects Branch 1p 26264 066

IOB280220 Application for amend to License DPR-52, changing Tech Specs to accommodate Unit 2, Cycle 6 operation & reflecting plant mods to be performed during refueling outage MILLS, L.M. Tennessee Valley Authority 84/08/23 DENTON, H.R. Office of Nuclear Reactor Regulation. Director 3pp 26249 201 24% Fiche 50-260,84/08/23,8408280220

8408280226 TVA RLR-002
"Relead Licensing Rept for Browns Ferry Unit 2,Cycle 6 "
Determination of no significant hazards encl
\* Tennessee Valley Authority 84/07/3; 38pp 26269 282 24X
Fiche 50-260,84/08/23.8408280220

IOBEB0259 Forwards "Westinghouse Position on Damping Values for Nuclear Power Plant Piping "Provides Justification for use of higher damping values defines intended applications for values 5 requests NRC approval of position RAIRE, E P Westinghouse Electric Corp NS-EPR-84-2955 84/08/16 KNIGHIJ P Assistant Director for Comp & Structures Engineering (Post 830201) 2pp 26262 047

-8409280260 "Westinghouse Position on Damping Values for Nuclear Power Plant Piping " \* Westinghouse Electric Corp. 84/08/16 21pp. 26262-049

NOB280265 Response to ASLB 840615 request for add1 info re TDI diesel generators ASLB should conclude that TDI QA program adequate at all times Related correspondence REYNOLDS.N S Texas Utilities Electric Co (formerly Texas Utilities Concrating Co) REYNOLDS.N S Bishop. Liberman, Cook. Purcell & Reynolds DSB 334 OL 84708/25 27pp 26262 008 24X Fiche 90-445,84708/25,8408280265

--8408280268 Affidavit of EJ Kreh te e aluation of TDI GA program TDI GA program acceptable prior to JUL 1980 discovery of auxiliary skid deficiency Prof qualifications & Certificate of Syc encl Related correspondence KREH, EJ 0'Donnell & Associates, Inc QL 84/08/24 10pp 26262 037 24X Fiche 50-445,84/08/25,8408280265

8408280424 informs that staff proposed witnesses include C Berlinger, BJ Bush, AJ Henriksen, Wil Laity & A Sansten, per ASLB 840821 menorandum & order Prof qualifications of uitnesses & Certificate of Svc enci Related correspondence GDDDARD R J Hearing Branch 3 DSB 337 DL 84/08/24 BRENNER L. MORRIS-P A , FERGUSON, G A Atomic Safety and Licensing Board Panel 72pp 26280 218 24X Fiche 50-022, 84/08/24, 8408280424

8408280461 Notifies that CAM-84-9 re setpoint methodology for reactor profection sys is proprietary & will be withheld from public disclosure per 100FR2 790
YOUNGBLOOD, B. J. Licensing Branch 1 84/08/22 WIESEMANN, R. A. Westinghouse Electric Corp. 3pp. 26292 337 24X
Fiche 30-445,84/08/22,8408280461

B40B270179 Forwards response to B40723 request for add1 info on repts submitted by TDI Diesel Generator Cuners Group RAY.C L TDI (Transamenica Delaval, Inc.) Cuners Group GGTP-218-N-34 B4/08/23 BERLINGER,C Office of Nuclear Reactor Regulation, Director 12pp 26289 221 24X Fiche 50-000,84/08/23,8408270179

8408290288 Forwards responses to 840131 questions re TDI diesel generators Renaining responses will be delayed until completion of TDI Dumers Group site-specific BR/GR repts.

Phase 1 disassembly & insp.Phase 2 testing & Phase 3 insp. RODRIGUEZ.R J. Sacramento Municipal Utility District. RJR 84-336.

84/08/24 SIDLZ.J F. Operating Reactors Branch 4 15pp. 26291 161 24X Fiche 50-312,84/08/24,8408290288

8408300141 Requests formal withdrawal of Rev 3 to BAW-10084, "Program to Determine In-Reactor Performance of B&W Fuels Cladding Creep Collapse " Rept will) be revised to include info on small gap collapse & new modeling techniques
TAYLOR, J H Babcock & Wilcox Co ESC-559 84/08/27 THOMAS, C D
Standardization & Special Projects Branch ip 26300 137

8408300232 Forwards description of program to implement TDI diesel insprequirements for restart & methods used to determine ESF loads, per 640726 request Program covers insps. tests & maint & surveillance activities
MEDFORD, M D. Southern California Edison Co. 84/08/28 PAULSON, W A. Operating Reactors Branch S. 12pp 26300 111 24X
Fiche 50-206.84/08/28,8408300232

B40B3i010B Concurs in implementation of criteria for evaluating personnel capability in siring IGSCC.per 840B07 ltr Meeting to review application of criteria & addl results appropriate DEYQUNO.R C Director's Office Office of Inspection and Enforcement B4/08/R4 NEILS.G H Northern States Power Co 2pp 26392 032

--B408310112 Forwards proposed grading criteria for (GSCC depth sizing course developed & affered by EPRI NDE Ctr Concurrence requested NEILS, G.H. Northern States Power Co. 84/08/07 DEYQUNG, R.C. Director's Office. Office of Inspection and Enforcement. App. 2008.

8408310195 Forwards proprietary Rev 2. Suppl 4 to XN-74-5(P),
"Description of Erron Nuclear Plant Transient Simulation
Model for PRRs " Rept withheld (ref 10CFR2 790)
CHANDLER.J C Exxon Nuclear Co. Inc (subs of Erxon Corp.)
JUC-119-84 84/08/29 THOMAS.C D Standardization & Special
Projects Branch 19 26316 292

8400310205 Expresses disagreement w/conclusions expressed in util, BNHL & NRC staff repts re reliability of TDI emergency diesel generators Pattern of deficiencies exists which precludes findings Related correspondence GUILD.R Guild. R OUILD.R Palmetto Alliance GUILD.R Carolina Environmental Study Group DSB 430 OL 84/08/16 KELLEY.J L , PVRDDM, P W , FOSTER.R F Atomic Safety and Licensing Board Panel 193pp 26317 228 24% Fiche 50-413,84/08/16.8408310205

8408310345 Advises of completion of review & forwards evaluation re BAW-10129, "Lynx 1 - Reactor Fuel Assembly Thermal Hydraulic Analysis Code " Rept acceptable for referencing in license applications to extent specified THOMAB.C O Standardisation & Special Projects Branch 84/08/23 TAYLOR, J H Babcock & Wilcox Co 4pp (... 2048

-9408070124 Topical rept evaluation of BMM-10129, 'LYNK 1 - Reactor Fuel Assembly Thernal Hydraulic Analysis Code" & BAM-10130, "LYNX 2 - Subchahnel Thermal Hydraulic Analysis Program Repts acceptable Core Performance Branch TAC 4338 84/07/31 6pp 26352 052

WASTE MGT NUCLEAR WASTE MANAGEMENT

8406190514 Trip rept of 840418-19 site visit re DDE UMTRAP mid-ur region of the rept of souther's site visit to be diment and ye review the graphs end of the resident Recovery Projects Branch 84/04/27 HIGGINBOTHAML Low-Level Waste & Uranium Recovery Projects Branch 85pp 25037 001 Projects Branch

8406210504 Agenda for Nuclear Waste Board 840509 meeting in Olympia. WA Map enci # Washington, State of 800 84/05/09 Washington, State of # App 25093 005

840B010043 Submits cormen's on Science Advisory Board review of proposed EPA stds for ngt & disposal of spent mutlear fuel, high level & transuranit radwastes NRC does not consider increased proposed release limits necessary GROWNING, R E Division of Waste Management 84/07/06 Environmental Profection Agency App 25866 341

B40B0i0046 Forwards "FES Remedial Actions at Former Vitro Chemical Co Bite South Salt Lake City, Salt Lake County, UT " MORLEY, J A Energy Dept of 84/07/13 Affiliation Not Assigned 1p 25868 001

--8408010053 DOE/EIS-0099-F "FES Remedial Actions at Former Vitro Chemical Co Site, South Salt Lake, Salt Lake County, UT Vol I - Tert " # Energy, Dept of 84/07/3! 501pp 25868 002

--8408010063 DDE/EIS-0099-F "FES Remedial Actions at Former Vitro Chemical Co.South Salt Lake.Salt Lake County.UT Vol II - Apps " \* Energy, Dept of 84/07/31 398pp 25869 143

8408010064 Forwards revised "UMTRA Project Environ Health & Safety Plan." incopporating NRC comments MORLEY, J A Energy. Dept of 84/07/17 HIGGINBOTHAM Low-Level Waste & Uranium Recovery Projects Branch 2pp 25897 238

--8408010072 "UMTRA Project Environ, Health & Safety Plan" \* Energy, Dept of 84/06/30 2pp 25897 240

18010070 Provides Salt Repository Project site rept for wk of 840709 IRMALT R NRC - No Detailed Affiliation Given 610 84/07/16 ROHNING.R E Division of Waste Management 1p 25897 237

B010079 Forwards, for review, draft Paradox STP-1 O. "Site Technical osition Grounduater Issues for Paradox Bedded Salt Basin" & draft Palo Duro STP-1 O. "Site Technical Position Grounduater Issues for Palo Duro Bedded Salt Basin "
KNAPP, M R Geotechnical Branch (Post 831001) 511 84/07/19
BROWNING, R E Division of Waste Management 1p 25897 176

-B408010083 PARADOX STP-1 0 DRFT Draft "Site Technical Position Groundwater Issues for Parador Bedded Salt Basin " Division of Waste Management 84/07/31 14pp 25897 197

--8408010088 PALO BURD STP-1 Q DR Draft "Site Technical Posttion Groundwater Issues for Palo Duro Dedded Salt Basin " # Division of Haste Hanagement 84/07/31 14pp 25897 211

8408310k14 Submits comments tomprising Confederated Tribes of Unatilla Indian Reservation input on draft mission plan PATAHA,E H Confederated Tribes of Umatilla Indian Reservation 906 84/07/16 HEAD:C R Energy, Dept of 2pp 25873 334

8408010123 Forwards viewgraphs from Attachment 4 to summary meeting notes of 840107-12 workshop on geochemistry DDE sources & refs requested for each viewgraph WRIOHTR J Repository Projects Branch (Post 831001) 909 84/07/13 0L50N.O L Energy, Dept of 266pp 25873 001

B40B310193 Summary of 840716 meeting w/DQE re establishment of contact w/& briefing by DDE on plans for project decision echedule Copies of advanced draft provided DDE plans to issue uraft project decision schedule in late Jul NUMARK.N J Policy & Program Control Branch (Post 831001) 84/07/16 Policy & Program Control Branch (Post 831001) 258773 PAA 25873 284

840801037° Trip rept of 840618-20 vi its to Edgement SD for meetings W/fown (concil thineoungis on DOE remodial action program FLDRV.6 A Lou-Level Haste / Uranium Recovery Projects Branch 84706/28 HIGGIN80THAM.L. Low-Level Waste tUranium Recovery Projects Branch Spp 25872-312

B40B010361 Forwards Title I review documentation for Salt Lake City, Shipport \* Canonsburg remedial action plans W/o encis MAQ11N:D E Low-Level Haste & Uranium Recovery Projects Branch S4/07/10 SMITH.D Uranium Recovery Field Office ip 25872 350

B408020217 Notifies of time change to Mitsubishi 840712 high integrity container meeting in Bethesda.MD Time changed to 3 pm rether than 2 pm as stated in 840702 memo JohnsGul, T C Engineering Branch (Post 831001) B4/07/04 BROWNING, R E Division of Waste Management BARRETT, L Engineering Branch (Post 831001) HigG/RBOTHAHLL Low-Level Waste & Uranium Recovery Projects Branch 2pp 25878 199

8408020236 DDE/NE-SHOI ERR Errata to "UMTRAP Radiological Survey of Shippock Vicinity Property SHOI, Shiprock, NK " Argonne National Laboratory 81/07/05 2pp 25898 161

--- 8408020237 DOE/NE-SHG2 ERR Errata to "UNTRAP Radiological Survey of Shiprock Vicinity Property SHO2, Shiprock, NM " \* Argonne National Leboratory 94/07/05 1p 25998 143

8408030045 Forwards modeling strategy document for high level waste performance assessment
LINEHAN, J J Repository Projects Branch (Post 831001) 84/0
MILLER, H J Repository Projects Branch (Post 831001) 71pp 25920 171

B408030082 Forwards Hod ACO3 to Cooperative Agreement DE-FC04-81AL16309 w/State of UT Agreement supports UMTRAP in State of UT, per Public Law 95-604 HILL: T V Energy, Dept of B4/06/13 HIOGINBOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch B4pp 25920 242

B40B030084 Forwards "Cooperative Agreement Between DOE % State of OR " HILL.I V Energy, Dept of B4/07/03 HIGGINBOTHAM, L Low~Level Waste & Uranium Recovery Projects Branch 38pp 25934 136

8408030092 Forwards, for review! comment, minutes of 840931 meeting w/8alt state representatives reland acquisition, transportation & environ assessments Minutes of 840329-30 meetings w/Salt representatives in Columbus, OH also encl TAYLOR, T J Energy, Dapt or IN 412-84 84707/17 LINEHAN, J J Repository Projects Branch (Post 831001) 284pp 25921 001

8408030197 Forwards draft "Radiological & Engineering Assessment for Property ED-00270-RS," for review.comment.rev &/or concurrence RODERIB.N A Energy, Dept of 84/07/23 HIGOINDOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch ip 25934 193

--B408030197 REA00270 REA-E-D-7DR Draft "Radiological & Engineering Assessment for Property ED-00270-R8 "

\* Bendix Corp 84/07/31 21pp 25934 194

8408030243 Forwards drafts "Radiological 5 Engineering Assessment for Property GJ~08742-MR." "Radiological 5 Engineering Assessment For Property GJ-13716-MR" 5 "Radiological 5 Engineering Assessment for DJ-00119-MR." for conturrence TUCKER, M K Energy, Dept of 84/07/16 HIGGINBOTHAM, L Low-Leve Waste 5 Uranium Recoverd Projects Branch 1p 25920 068

--B40B030264 REA0B742 REA-104/LS
Draft "Radiological & Engineering Assessment for Property
GJ-08742-MR" W/Four oversize figures Aperture cards available in PDR \* Bendix Corp 84/06/30 33pp 25920 069

--840803026B REA13716 REA-7 DRFT
Draft "Radiplogical & Engineering Assessment for Property
GJ-13716-MR" W/Five oversize figures Aperture rards
available in PDR
\* Bendix Corp 84/07/31 34pp 25920 104

--B408030270 REA00119 RFA-7 DRFT Draft "Radiological & Engineering Assessment for Property GJ-00119 MR " Bendix Corp 84/06/30 33pp 25920 138

- 8408030277 \*\*\*Commany of DQE/IRC 840612 \*\*\* 13 meetings in Gaithersburg, MD re BMIP hydrologic characterilation Attended comments encl WRIGHT.R J NRC No Betailed Affiliation Given MECCA.J E Energy, Dept of OQFIR 84/06/14 NRC No Detailed Affiliation Given 13pp 25920 050
- 8408030293 Forwards Hest Valley Nuclear Svcs. Inc security & safeguards plan Plan should be returned to DDE within 1 yr % should not be duplicated OE uill allow Fluor to view plan at Sunnyvale facility

  MUNDERLICH R C Energy, Dept of OO615 84/07/18 MALLONEE. F OF Fluor Corp 3pp 25919 360
- 8408060045 Furwards corrected Page 46 from App A to 'ENVIROSTONE Gypsum Cement 10CFR61 Compliance Testing Topical Rept" (U5G-684-1P & U5G-684-1P) re ni) ratios for ion exchange bead resins solidified w/ENVIROSTONE Gypsum cement LANGE.R G U S Gypsum Co 84/07/19 HIGGINBOTHAM, L Low Level Waste Licensing Branch 2pp 25737 089
- --B408060047 USG-684-INF ERR Corrected Page 46 from App A to "ENVIROSTONE Gypsum Cement 10CFR41 Compliance Testing Topical Rept" \* U S Gypsum Co 84/07/19 ip 25937 091
- 8408040051 Folwards proposed agenda & list of topics beneficial to address in Salt Repository Project Ofc info mgt sys 840803 briefing NRC becoming familiar W/sys in use LINEHAN, J. Repository Projects Branch (Post 831001) 00618 84/07/24 NEFF, J.D. Energy, Dept of 3pp 25937 086
- B408060059 App 7 to MDU between NRC \* DDE re repository projects in site suitability & planning phase \* MRC - No Detailed Afriliation Given \* Energy, Dept of OOG24 84/07/27 3pp 25937 OB3
- B408060047 Informs of upcoming meetings w/NRC for Jul-Nov 1984 Meeting announcement will be updated weekly
  TAYLOR: T J Energy Dept or 00617 84/07/20 LINEHAN, J NRC No Detailed Affiliation Civen FRISHMAN, 5 Texas, State of
  FDRBYTHE: R Mississippi. State of 2pp 25937 076
- 8408060106 Forwards draft processing site & disposal site characterization repts for Salt Lake City, UT Repts contain current data re conceptual design analysis Comments requested by 840824 MATTHEWS, M.L. Energy, Dept. of 84/07/20 MARTIN, D. Uranzum Recovery Licensing Branch ip 25952 001
- --8408060111 UMTRA-DUE/AL-050102

  Draft "Disposal Site Characterization Rept for U Mill Tailings Site at Sal\* Lake City, VT " Two oversize maps encl Aperture cards available in PDR # Energy, Dept of 84/06/30 195pp 25952 003
- --B408060122 UMTRA-DUE/AL 050102 Review draft of "Processing Site Characterization Rept for U Mill Tailings Site at Salt Lake City, UT " Six oversize maps encl Aperture cards available in PDR \* Energy, Dep\* of 84/04/30 236pp 25752 154
- 8408060149 Forwards final summary of hydrology data review on 840514-18 in Columbus.OH Summary will be sent to representatives from Silt states % USOS Agenda, attendance list & related info encl LINFMAN.J J. Repository Projects Branch (Post 831001) 614 84/07/09 NEFF.J D. Energy. Dept of 20pp 25936 324
- 8408050163 Forwards revised modeling strategy document for high level wasta performance assessment
  BROWIING, R E Division of Waste Management 84/07/23 DAVIS, J O Office of Nuclear Material Safety & Sateguards, Director 70pp 25936 204
- 8408050173 Suggests that Nevada Nuclear Waste Storage Investigation geology data review be held during wks of 840820 & 27 Requested data listed including calibr of current seismic velocity crustal nodel COPLAN-S Repository Projects Branch (Post 831001) 323 84/07/05 VIETH-D Energy, Dapt of 2pp 25936 202
- 8408060178 Comments on Page 82 of House Rept 98-795, agreeing that DDE should have capability to destructively evaluate glass meited at PNNL to deternine quality HICKLE A Engineering Branch (Post 831001) 84/07/14 JOHNSON, T C Engineering Branch (Post 831001) 1p 25936 201

- 8409350186 Trip rep\* of Nevada Nuclear Waste Storage Investigation
  8.0710-12 geochemistry workshop 840713 geochemistry/
  ninerology-petrology workshop visit & 840709 program review
  of Project A7150
  STARMER,R J. FOLACH, E. A. Geotechnical Branch (Post 831001) FIN
  A-7150 00325 84/07/26 KNAPP,M R. Geotechnical Branch (Post
  831001) 38pp 25950 256
- 8408050225 Forwards listed documents.including NUREG-0170. NUREG-0743, NUREG-03194 & proposed rule for mod of protection requirements for spent fuel shipment.per request W/o encl RUSSELL. CF Policy & Program Control Brench (Post 831001) 00327 84/07/19 LOUK,R R Novada. State of 1p 25950 249
- B408060242 Forwards K Westbrook B40511 & 0605 memos re 840313-15 BMIP/NRC workshops on geology M/e encls MRICHI.R J Repository Projects Branch (Post 831801) 911 B4/07/03 OLEON.O L Energy, Dept of 1p 23937 342
- 8408060252 "Geo\*echnical Investigation for Bodo Canyon V Mill Tailings Remedial Action Program Durango Site Durango CO " \* Dames & Moore 83/10/20 43pp 25751 298
- B408060256 Clarities response to question re results of drop tests
  Under conditions consistent w/iOCFR61, no evidence of water
  leakage after drop tests existed
  EPSTEIN, G Mitsubishi International Corp (subs of Mitsubishi
  Corp ) WSH-219 B4/07/19 JOHNSON, T Division of Waste
  Management 2pp 25950 345
- 8408060264 Forwards revised final agenda for seventh bimonthly 840801-02 meetings w/Salt states & NRC in Columbus.CH TAYLOR.T J Energy. Dept of 84/07/26 LINCHAN.J J Repository Projects Branch (Post 831001) 4pp 25950 341
- 8408040246 Forwards engineering fact sheet for Alternative 5.
  reprocessing.per 840717 meeting re forthcoming Durango EIS
  PARKER.G E Jacobs Engineering Group. Inc 84/07/19 PENNIFILL.R
  Low Level Waste Licensing Branch 32pp 25950 309
- 8408060274 Discusses proposed alternative sites for disposal of Durango mill tailings Based on field observations major engineering design measures will be needed at Long Hollow & Bodo Canyon sites to satisfy groundwater protection requirements HIGGINBOTHANL Low-Level Waste & Uranium Recovery Projects Branch 84/07/23 MORLEY, J A Energy, Dept of 2pp 25950 276
- 8408060295 Forwards J Buckley 840705 memo re typographical error in App V.Vol 2 of NUREG-0760 WRIGHT,R J Repository Projects Branch (Post 831001) 00916 8407723 DESON D L Energy, Dept of tp 25950-349
- 8408040338 Forwards listed documents re decision on DDE guidelines, including transcript of 840622 Commission meeting 8 three written testimonies from Commission 840622 meeting W/o encl RUSSELL, C F Division of Waste Management 84/07/03 STEVENS, D Washington. State of 1p 25937 353
- 840806034: Forwards listed documents re decision on DGE guidelines, including transcript of Commission 840622 meeting & three uritten testimonies from Commission 840622 meeting W/o encl MATSON, D R Policy & Program Control Branch (Post 831001) 612 84/07/03 BOHLINGER, H Louisiana, State of 1p 25937 352
- 8408060431 "Bodo Canyon (Area E) Site Geomorphic Evaluation " SCHUMM, S A : HARVEY, M D Water Engineering & Technology, Inc 83/11/10 9pp 25937 325
- 8408070063 Responds to S Copian 840607 memo re Nevada Nuclear Haste Bite Investigations proposed data reviews w/NRC for two of three upcoming neetings Public will not be invited FREI.M W Energy, Dept of 84/07/03 BENNETY.W J Energy, Dept of 2pp 25905 323
- 8408070136 Forwards "Overview of Low Temp Sensitization," prepared by LLL as part of waste package evaluation for Nevada Nuclear Waste Storage Investigations
  BARRETI, L H Engineering Branch (Post 831001) 00326 B4/04/24 CONTI, E F Division of Waste Management 1p 28957 156
- --8408070140 UCRL-19619
  "Qvervigu of Law Temp Sensitisation"
  FGX,M J , MCCRIGHT.D R Lawrence Livermore National Laboratory
  83/12/31 41pp 25937 157
- B408070149 Forwards revised "Document Accessions List.Jul 1984." for Rockwell Hanford Dperations \* Baselt Waste Isolation Project 920 84/07/26 WRIGHT.R J Division of Waste Management 1p 25957 210

- --B408070153 006-30 84
  Revised Document Aucessions List Jul 1984, for Rockwell
  Hanford Operations
  - Basalt Waste Isolation Project 84/07/31 512pp 25957 211
- B40B070i61 'Radiological' Engineering Assessment for Salt Lake City
- B408070276 Advises that NRC cannot concur w/interagency agreement between DDE & TVA re disposal of residual radioactive matls from vicinity properties in Edgemont. SD. as presently worded Agreement should be revised HIGSINBOTHAM. Low-Level Waste & Uranium Recovery Projects Branch
  - HILL: TV Energy Dept of 2pp 25954 259
- 8408070523 Trip rept of 840720 meeting at EPA.Athens.GA re metal speciation & transport modeling List of attendees & 840831 telion record encl
  - tellenn record enc! KELLEY, W.R. Geotechnical Branch (Post 831001) 84/07/24 STACHER, R.J. Geotechnical Branch (Post 831001) 4pp 2 25954 220
- B40B0B0322 Confirms 840B16 neeting in Silver Spring,MD to discuss 61TRAK & WASTETRAM, w/primary emphasis on scaling factor modeling contained in 61TRAM.per B40727 telcon WANCE.J N Impell Corp B4/07/27 ROLES.G Low-Level Waste & Uranium Recovery Projects Branch 1p 25976 007
- 8408070297 Forwards DOE comments re proposed amend to 10CFR60 for
  - disposal of high level waste in unsaturated zone & alternatives
    alternatives
    QCHNSON.C Policy & Program Control Branch (Post 831001)
    84/07/27 JOHNSON.C Nevada, State of 1p 25984 352
- --8408070303 Forwards suggested alternate performance objective re amend to 10CFR60 for disposal of high level waste in unsaturated rones Proposal related to geologic setting of sites within zone RUSCHE.B C Energy, Dept of 84/07/11 GHILK.S J Docketing & Services Branch 7pp 25984 353
- B408070328 Summary of 840717 meeting w/State of CO.EPA.DOE & DOE contractors in Denver.CO re Durango EIS Attender list encl PERMIFILL.R A Lou-Level Waste & Uranium Recovery Projects Branch 84/07/24 HIGGINBOITHAM, L. Low-Level Waste & Uranium Recovery Projects Branch 3pp 25784 341
- B408070331 Comments on study or soll samples from Beatty, NV disposal site Guestions raised re plans for further testing for Tc-97: 1-129 ½ H-3 & Use of results by State of NV HIGGINBOTHAM.L. Low-Level Haste ½ Uranium Recovery Projects Branch 84/03/27 NUSBRAUTER, D.A. Assistant Director for State Agreements Programs ip 25784 340
- 8408130077 Forwards narked-up draft Beatty site closure plan submitted by US Ecology, for review & comments Comments requested by 840808
  - BAOBOO IUSSBAUMER, D. Assistant Director for State Agreements Programs 4/07/13 HIGGINBOTHAM,L. Low Level Waste Licensing Granch 35pp
  - 408130079 "Geohydrological Studies Beatty, NV Disposal Facility" Law Engineering Testing Co 81/08/13 54pp 26059 038
  - 340913008: "Gravel Cap Design Analysis Beatty Low Level Radwaste Disposal Site, Beatty, NV "
    HODMER.R L U S Ecology, Inc (formerly Nuclear Engineering, Inc.) 84705704 11pp 26037 071
  - 00130083 Summary of NRC hydrology data orientation & data review 840514-18 meetings in Columbus.OH Agenda.notes & attendee PEARRING.J R Engineering Branch (Post B31001) 621 GREEVES.J T Engineering Branch (Post B31001) 20pp 621 84/06/06 2000 26036 310
- .408130079 Forwards draft umbrella site technical position on BWIP Geology, to fulfill Operating Plan Milestone 5314215 12 geology, to fulfill Operating Plan Milestone 5314215 12 Comments requested KNAPP.M R Geotechnical Branch (Post 831001) 923 84/07/30 BROUNING.R E Office of Nuclear Material Safety & Safeguards.Director 1p 26036 293
- ---8408133101 "Site Technical Position Geologic Issues for BHIP"

  \* Geotechnical Branch (Post 831001) 84/07/31 16pp 26036

- B40813010b Discusses impact of neat cement zone on basaline head distribution in bortholes whested plerometers used to collert downhole pressure data Problems w/piezometer design identified \* modeling methods discussed Addl work needed GCRDOLLM Gratholical Branch (Post 831001) V21 84/07/10 KNAPPH Geotechnical Branch (Post 831001) WRIGHT.R Repost Projects Branch (Fost 831001) 16pp 26034 335
- B40B130116 Raturns DDE-TVA interagency agreement transmitted by L Higginbotham B40725 1+r.per B40730 telcon M/o enci MARQUEZ.R A Energy Dept of 84.07/30 GNUGNDLI.G NRC No Detailed Affiliation Given ip 26034 334
- 8408130122 Act secupt of 840705 data inventory & forwards list of data that would be useful during 840724-27 hydrology data review COPLANS M Repository Projects Branch (Post 831001) 330 84/07/20 VIETH.D.L Freigy, Dept of 3pp 24034 331
- B40Bi30i30 Forwards 'Geology & Mineral Deposits of Southern Nye County," 'Nevada Statistical Abstract," "Annual Rept 1981-82.' "Nevada Map Atlas-Fourth Edition" t 'Financial Statement," per C Johuson 8405i3 request M/o enci LOUX R R Navada, State of 328 B4/07/25 RUSSELL, C F Program Control Branch (Post 831001) 1p 26034 330 RUSSELL, C F Policy &
- 8408130137 Notifies of upcoming meetings during 840801-1129 Updates will be submitted ueekly
  TAYLOM,T J Energy, Dept of 620 84/07/27 LINCHAN,J NRC - No
  Detailed Affiliation Given HINCHMAN,J Utab, State of
  FORSYTHE,R Texas, State of 2pp 26034 328
- B40Bi30140 Concurs w/remedial action plan for State of CO tailings repository
  HIGGINBOTHAM.t. Low-Level Waste & Uranium Recovery Projects Branch CREW, M E Energy, Dept of 200
- 840Bi30144 Forwards cutaway diagram of Hanford basalt units showing interbeds & basalts being considered for repository host rock MRIGHT,R J. Repository Projects Branch (Post 831001) 908 84/07/19 FARROW,M J. Confederated Tribes of Umatilla Indian Reservation 2pp 26034-324
- 8408130577 "Codes That May Be Used in Nevada Nuclear Waste Site Investigations Performance Assessment" \* Sandia Laboratories 329 84/08/08 2pp 26038 315
- 8409140358 Approves DOE renedial action plan for removal of math from former White Truck site in Salt Lake City Requests future submissions allow 1 month rather than 10 days for review & concurrence NRC concurrence should not be assumed HIGGINBOTHAM.L Low-Level Waste & Uranium Recovery Projects Branch 84/07/25 MORLEY, J A Energy, Dept of 1p 24061 285
- B40B150144 Forwards "DES Remedial Actions at Former Vanadium Corp of America Site, Durango, La Plata County, CO," per B40717 meeting Evaluation should be concentrated in four listed areas Comments requested by 840817 MDRLEY, J.A. Energy, Dept. of 84/08/01 PENNIFILL, R Waste & Uranium Recovery Projects Branch ip 26100 ( Law-Level 26100 001
- --8408150149 "DES Reredial Actions at Former Vanadium Corp of America Site.Durango, La Plata County, CO " \* Dames & Moore 84/07/31 1,000pp 26100 003
- 8408150252 Forwards comments on geotechnical engineering issues in "Processing Site Characterization Rept for U Mill Tailings Site at Riverton. HV." per 840719 request SIYKOMSKI.S Engineering Branch (Post 831001) 84/08/01 PENNIFILL: R Low-Level Waste & Uranium Recovery Projects Branch 3pp 26099 355
- 8408150337 Forwards "SRP for Draft Environ Assessment Developed by DOE, per Section [12(b) of Nuclear Maste Policy Act," for NRC use NRC will not comment on DDE methodology to compare sites,per 10CRA60 BROWNING.R E Division of Waste Management 84/07/05 DAVIB, J G Défice of Nuclear Material Safety & Safeguards Director 2pp
- --8408150341 Advises of major inconsistency between position taken in environ assessment review plan & DDE siting guidelines remethodology used by DDE to compare or select sites & relative merits of one site against another SURMCIER, J. HRC No Detailed Affiliation Given 84/07/03 JUHNSON, B. NRC No Detailed Affiliation Given 2pp. 26098 300
- ---8408150344 "SRP for Draft Environ Assessment Developed by DOE,per Section 112(b) of Nuclear Waste Policy Act " \* Division of Waste Managerent 84/06/22 41pp 26098 302

- d405150351 fratt' Peradia) Artion Flan / Site Conceptual Design for Stabilitation is in a trace with Tailings Site at Gunnison, CO "
  - Energy 1 ept it 84706 30 250pp 26098 038
- 840B1503A5 Praft "Francissing Eite Characteritation Rept for U Mill Tailings Bite at Connison CD " \* Energy, Pept or 84 U4/30 300pp 26097 069
- 8408150400 "Disposal Site Characterization Rept for Alternate U Mill Tailings Disposal Site in East Gold Basin near Gunnison.CO " MDRLEY, J.A. Energy, Dept. or 84/05.31 34pp 26104 338
- B408150403 'Disposal Site Characterization Rept for Alternate U Mill Tailings Disposal Site in Chance Gulch Near Gunnison.CO " MORLEY, J.A. Energy, Dept. or 84/05/31 34pp 24105-235
- 8408150419 Environ Assessment of Remedial Action at Gunnison U Mill Tailing Site Gunnison CO \* Energy, Dept of 84/06/30 400pp 26096 038
- 8408130°31 Forwards "Radiological \* Engineering Assessment for Property ED-00005-RS " ED-00005-RS
- ED-00005-RS " ROBERTS.V A Energy, Dept of 84/08/01 HIGGINBOTHAM.L Low-Level Wasre " Uranium Recovery Projects Branch ip 26080 272
- --84081505J3 "Radiological \* Engineering Assessment for Property ED-00005-RS "
  - Bendix Corp 84/07/31 21pp 26080 273
- 8408190368 Forwards "NRC Review Plan QA Program for Site Characterization of High Level Nuclear Waste Repositories "Discusses steps taken to establish early agreement on QA program Site visits for Jul & Aug proposed BROWNING.R E Division of Waste Management 84/06/29 BENNETT.W J Energy, Dept of App 26080 316
- --8409150572 "NRC Review Plan QA Program for Site Characterization of High Level Nuclear Waste Repositories" Repository Projects Branch (Post 831001) 84/06/30 33pp
- B40B150664 Forwards NRC comments re DDE draft "Mission Plan for Civilian Radwaste Mgt Program," per MJ Lawrence B4050B request NRC/DDE interaction to ensure timely preparation of final mission plan continuing PALL/DIND N Commissioners B4/07/31 RUBCHE, B C Energy, Dept of 57pp 26104 009
- 8408160J4B Forwards draft interagency programmatic agreement re U mill tailings disposal sites Redraft contains new provisions re problems concerning lou level radwaste mgt & language which commits NRC % EPA to speek legislative relief DAVIS,J G Office of Nuclear Material Safety & Safeguards, Director 84/07/25 CANNON, J. THOMAS,L Environmental Protection Agency 26128 146
- 9409160051 Informs of review of radiological & engineering assessment NOBLEWOOD INTERPRETARY OF TRAILINGICAL & ENGINEERING ASSESSMENT for vicinity property listed in encl ? concurrence w/planned remedial action Concurrence based on listed items HIGGINDOTHAM. L. Low-Level Waste & Viantum Recovery Projects Branch 84/07/27 CREW,E Energy, Dept of 2pp 26126-361
- 8408160055 Forwards ducuments re NRC efforts in defining high level raduaste under Nuclear Waste Policy Act of 1982 & NRC comments to EPA on high level waste std BELL-N J Bivision or Naste Management 84/08/03 BENNETT, J W
- 84081602/8 Forwards "Project Licensing Plan for UMTRAP Sites" for review % concurrence MORLEY, J.A. Energy, Dept of 84/08/07 HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch 1p 26126 043
- --8408160283 "Project Licensing Plan for UMTRAP Sites " \* Energy, Dept of 84/07/31 37pp 26126 044
- 8408160289 Discusses status of Falls City,TX inactive U mill site & plan of action gince current contractor due to lose license. DOE prepared to begin renedial action BAUBLII?.J E Energy. Dapt of 84/08/06 HIGGINGOTHAM, L Lou-Level Waste & Uranium Recovery Projects Branch 2pp 2
- B40B160297 Discusses Barrier-55 high integrity container for low level raduaste Barrier fully complies w/10CFR61 & approved for use at Barnwell site HIPSHER.N M MUS Corp B4/08/07 JOHNSON.T Low-Level Waste & Uranium Recovery Projects Branch 3pp 26124 342

- 8408160460 Attises that briefing by Impell Corp re waste classification computer programs (61 TRAK & WASTETRAK) shifted from 840809 to 840921
  - to 840721 RDLES:O N Lou-Level Waste > Unanium Recovery Projects Branch 84/08/02 GAMMILL. Meteorology > Effluent Treatment Branch MACDONALD.C E Transportation Certification Branch GRELLA, A W Safeguards > Materials Program Branch ip 26124 341
- 8408160467 Comments on topical rept to ENVIROSTONE gypsum tement Approval of rept should be limited to formulae which give acceptable product Long-term performance of gypsum cement needs further s+udy CDSTANZI.F.A. Waste Management Branch (post 840429) 84/08/0 BARRETT L. Engineering Branch (Post 831001) 1p 26120 348
- 8408160470 Forwards "Draft Generic Technical Position on Licensing Assessment Methodology for High Level Waste Geologic Repositories" for guidance to DOE MILLER.H J Repository Projects Branch (Post 831001) BROWNING,R E Division of Waste Management ip 261 10 26124 298
- --8408160475 "Draft Generic Technical Position on Licensing Assessment Methodology for High Level Waste Geologic Repositories " ◆ Division of Waste Management 64/07/31 39pp 26124 299
- 840Bi60479 Submits comments on draft "Mission Plan for Civilian Raduaste Mgt Program," per Nuclear Waste Policy Act.Section FRISHMAN, S Teyas, State of 84/07/09 RUSCHE.B C Energy, Dept of 20pp 26108 331
- 8408170413 Forwards draft "Rajiological & Engineering Assessment & Final Design for Salt Lake City Property, SL-044 "
  # Morrison-Knudsen Co . Inc 84/07/27 FLORY, C NRC - No Detailed
  Affiliation Given 1p 26135 186
- --8408170415 Draft "Radiological & Engineering Assessment & Final Design for Salt Lake City Property:SL-044 " 4 Morrison-Knudsen Co , Inc 84/07/25 62pp 26135 187
- 8408170427 Forwards draft umbrella site technical position on geology for Nevada Nuclear Waste Site Investigations Document distributed to Engineering Branch for technical comments & Repository Projects Branch for general review KNAPP.17 R Geotechnical Branch (Post 831001) 84/07/27 BROWNING.R E Division of Waste Management 14pp 26134 278
- 8408200154 Forwards draft "Radiological & Engineering Assessment for Salt Lake City Property SLC-019 " Comments requested by December 19 Morrison-Knudsen Co , Inc. 84/07/26 FLORY, C NRC - No Detailed Affiliation Given 1p 26141 CBB
- ---B403200157 Prart "Radiological & Engineering Assessment for Salt Lake City Property SLC-019 " + Morrison-Knudsen Co , Inc B4/07/24 45pp 26141 0B9
- 840820018? Advises that testing of cement solidified activated carbon as stable mix meeting stability requirements of IOCFR61, in process Appropriate data & formulation for review will be submitted at conclusion of testing LEDUC.R J Westinghouse Hittman Nuclear, Inc WHNI-E-792 84/08/09 PERSSN.L S Low-Level Waste & Uranium Recovery Projects Branch 2pp 26142 293
- B408200197 Forwards list of inadequacies based on brief raview of draft US Ecology, Inc. clasure plan proposal for Beatty low level waste disposal facility Addl info re hydrology, geology & waste disposal facility new ..... geochemistry warranted KNAPF,M R Geotechnical Branch (Post 831001) 84/08/08 HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 2pp 26142 293
- 8408200208 Advises of conpletion of review of radiological & engineering assessments for TVA millsite at Edgemont.SD & concurrence w/planned renedial actions HIGOINBOTHAM. Low-Level Waste & Uranium Recovery Project 64/08/08 CREM.M E Energy, Dept of 2pp 26442 288
- 8408200229 "Lateview Activity Status Rept,840619" \* Oregon, State of 84/06/19 5pp 26142 281 26142 281
- 8408200232 Notification of 840710 meeting w/Engineers Intl & US Bureau of Mines in Silver Spring.MO to prepare for Nevada Nuclear Haste Site Investigations repository design data review scheduled for 840716-20 Proposed agenda encl \* Engineering Branch (Post 831001) 84/07/10 Engineering Branch (Post 831001) 19pp 26142 262

- 8408200234 Lakeview U mill Site Remedial Action Project Status Rept. May-June 1984 "

  \* Oregon, State of 84,06,30 lipp 26:42 251
- 8408200242 'Lakevieu Activity Sfatus Rept,840915 '
  a Oregon, State of 84/09/15 10pp 26142 005
- 8408200245 "Lake.lew U Mill Site Remedial Action Project Status Rept. eb 1984 '
  Oregon, State of 84/02/29 Epp 26142 003
- 8408200252 "Lakeview U Mill Site Remodial Action Project Status Rept.
  - Mar-Apr 1984 " \* Oregon, State of 84/04/30 App 26143 323
- 8408200342 "Draft Radiological & Engineering Assessment, Vicinity Property SLC-050 " \* Morrison-Knudsen Co , Inc 84/07/25 60pp 26141 020
- 8408200404 Forwards proposed agenda for 840827 meeting to discuss issue & mgt info tracking sys used by repository program ofcs HRIGHT.R J Repository Projects Branch (Post 831001) 84/08/01 OLSON.O L Energy, Dept of 4pp 26141 190
- 8408200407 Forwards comments on Riverton processing site characterization rept (PSCR) PSCR fails to achieve purpose of containing inventory of data relevant to remedial actions
  - Geotechnical Branch (Post 831001) 84/08/07 FEORY.C WEBER, M F Law-Level Waste & Uranium Recovery Projects Branch 15pp 26141 162
- 8408200425 Trip rept of 840723-27 visit to USGS in Denver.CO re Nevada Nuclear Maste Site Investigations hydrology data
- review RICE,B J Geotechnical Branch (Post 831001) 332 84/08/09 JUSTUS.P S Centechnical Branch (Post 831001) 3pp 24144 358
- 8408200426 Forwards draft 'Site Technical Position Geochemistry Issues for BWIP." in response to OPS Plan Milestone 3314215 52 Comments requested by 840815 STARMER.R J Ceotechnical Branch (Post 831001) 930 84/07/30 WRIGHT.R J Repository Projects Branch (Post 831001) 0REEVES.J T . JOHNSDN.T C Engineering Branch (Post 831001) 1P 26183 007
- --8408200432 Draft 'Site Technical Position Geothemistry Issues for BWIP NRC - No Detailed Affiliation Given 84/07/30 31pp \$4183 008
- 840B200430 Confirms that geology data review schoduled for 2-wk period commencing on 840917 at Yucca Mountain site VIETH.O L Energy, Dept of 334 84/08/07 CGPLAN, S M Repository Projects Branch (Post 831001) 2pp 26144 352
- 3408200435 Forwards for signature summary of 840710-12 geochemistry workshop Summary should be returned so encls can be added & distribution completed distribution completed VIETH, DL Energy, Dept of 337 84/08/14 COPLAN, S M Repository Projects Branch (Post 831001) 10pp 26144 33:
- 408200437 Forwards for review aquifer analysis paper re Gunnison, CO site Paper concludes that aquifer restoration not economically feasible & no addl field data required MDRLEY, J A Energy. Dept of 84/08/13 HAISFIELD, M NRC -- No Detailed Affiliation Given 32pp 26182 337
- 8408200444 Points out error in NRC 840705 comment ltr on "Repository Horizen Identification Rept," RHO-BW-ST-28F Comment 3 should read "performance function is paramount" WRIOHI, R J Repository Projects Branch (Post 83100) 932 84/08/02 GLSOM, O L Energy, Dept of 1p 26144 328
- 8408200452 Responds to DDE 840703 request for concurrence in Cooperative Agreement DE-FC04-844L20534 between DDE & State of UR Concurrence granted w/concern re failure to mention NRC as cooperating agency W/o encl HIGOINSOTHAM, L iow-Level Waste & Uranium Recovery Projects Branch 84/07/24 MILL, T V Energy, Dept of 1p 26143 362
- 8408200459 Trip rept of 8407(2-19 site visit to U recovery operation in Mydming re review of environ assessment & remedial action plan & preparation for U recovery roll-making DAM, M Geotechnical Branch (Post 831001) 84/08/07 STARMER, R U Geotechnical Branch (Post 831001) 5pp 26144 322

- 84082304/0 fillwords draft Pevice of Geochemical Condition Info at BWIF Site (1979-82). In response to OPS Plan Milestone
  - 53(1217.63) BRODKS, D J Geotechnical Branch (Post 831001) 727 84/07/31 KNAPP M R Geotechnical Branch (Post 831001) 1p 26182 227
- -8408200475 Draft 'Review of Geochemical Condition Info at BWIP Site (1979-82)
  - NRC No Detailed Affiliation Given 82/12/31 66pp 26182 228
- 8408200474 Submits Nevada Nuclear Waste Storage Investigations site rept for wk of 840730 Agenda for 840801-02 project manager-technical project officers meeting encl PRESHOLT:P T Division of Waste Management 339 84708706 BROWNING, R F Division of Waste Management 19pp 26182 294
- 8408200490 Forwards draft "Groundwater Issues for BWIP," site technical
  - position KNAPP.M R Geotechnical Branch (Post 831001) 84/07/31 MILLER.H Repository (Projects Branch (Post 831001) 1p 26143 340
- --8408200471 BWIP STP 1 0 DRFY
  Draft "Grounduater Issues for BWIP," site technical position
  4 Division of Maste Management 84/07/31 15cc
  - Division of Waste Nanagement 84/07/31 15pp 26143 341
- 84082005)6 Forwards draft data locations list & topical bibliography re HUB2UD306 torwards draft data locations list & topical biblingraphy thermonechanical properties of rock for 840820 meeting w/NRC Lists will be updated as necessary CASEY.L Energy, Dept of 629 84/08/08 JOHNSON,R NRC - No Detailed Affillation Given 79pp 26144 132
- 8408200314 Notities of upcoming meetings w/NRC re info systunderground testing & rock mechanics data review
  TAYLON.I J Energy, Dept or 624 84/08/03 HINCHMAN.J,
  FRISHMAN.F, FORSYTHE,R Energy, Dept of 2pp 26143 321
- 8408200517 Requests transmittal of well summary repts & characterization status repts to R Johnson of NMSs. Div of Characteritation, solution of 423 84/08, SHERWIN, J.A. Energy, Dopt of 423 84/08, Texas, Univ. of, Austin, TX. 1p. 26143-320
- 8408210038 Agrees to 840827 scheduled maeting in Richland. WA to discuss DOE/BWiP info sys.per 840801 ltr Proposed agenda accepted w/a comments DLSON, O'L Energy Dept of 925 84/ Repository Projects Branch (Post 831001) 84/08/10 WRIGHT.R J 001) 1p 26195 181
- B408210044 Agenda of State of NA Nuclear Waste Board 840618 meeting in Lacey, NA to discuss status of federal actions & defense waste project proposal \* Washington, State of 927 84/06/18 Washington, State of 1p 26195 15
- 8408210071 Corrected agenda of State of WA Nuclear Waste Board 840817 meeting in Lacey.WA to discuss status of federal actions & defense waste project proposal \* Washington, State of 928 84/08/17 Washington, State of
- 26175 149
- 8408210087 Forwards state comments on draft mission plan for civilian raduaste mgt program (except MM), per C Russell request State of MN comments will be sent directly by state OERVERS.J R Latir Energy Consultants 84/08/10 BROWNING.R E Division of Waste Management 88pp 26194 319
- 84082:0115 Forwards "Draft Umbrella Site Technical Position on OBSERVATOR OF THE PROPERTY OF GREEVES, J T
- --8408210124 "Draft Umbrella Site Technical Position on Geochemical Issues for High Level Naste Disposal Facility in Tuff " # Division of Naste Management 84/07/30 24pp 26195 321
- 8408210125 Forwards 840629 QA review plan,per 840725 request Package includes transmittal ltr. QA review plan & NUREG-1055 W/o LINEHAN, J J Repailtory Projects Branch (Post 831001) 84/07/30 NEFF, J O Energy, Dept of to 26195 31
- 84082:0130 Ack receipt of topical rept of CYTRAK computer program Computer code listing requested ROLES-G W Lou-Level Haste & Uranium Recovery Projects Branch 84/08/07 SHULMAN, M N CYGNA Energy Services ip 26195-318

- 840821013' Privies's meeting w.DDE / Science Applications. Inc on 840830 \* 31 to discuss info mgt sys currently in use / planned by Novade Nuclear Haste Storage Investigation Proposed agenda & list or topics encl COPLAN S M. Repository Projects Branch (Post 831001) 335 84/88/09 \* (JETH.D.L. Energy, Dept. of 4pp. 26195-314
- 8408210171 Requests color prints of Yocca Hountain core boxes for DDE Waste Mgt Project Gfc VIETH.D L Energy. Dept of 336 84/08/08 REED,R C Pan American World Airways. Inc. 1p. 26195-220
- 8408210180 'Group Visit Info Sheet " for upcoming Nevada Test Bite Visit GLORA.M Science Applications. Inc 333 84/08/06 5pp 26187 351
- 840B220C61 Forwards State of NV comments on draft mission plan LDUX.R R Nevada. State of 84708710 BROWNING.R E Division of Waste Management 36pp-26211-305
- 8408220055 Requests copy of official version of CHEMTRN transport model KERRISK.J I' Los Alamos Scientific Laboratory WX-4-6492 84/08/08 STARMER,R J NRC - No Detailed Affiliation Given ip 26209 359
- 8408220076 Folwards comments on DUE draft Apr 1984 "Mission Plan for Civilian Radwaste Mgt Program " Comments based on discussion at ACRS Subcommittee on Naste Mgt 840807 meeting EBERSDLE, J C ACRS ~ Advisory Committee on Reactor Safeguards 84/08/13 DIRCKS.N J Defice of the Executive Director for Operations 2pp 26210 358
- --8408220081 Connents on DDE draft Apr 1984 "Mission Plan for Civilian Radwaste Mgt Program" + ACRS - Advisory Connittee on Reactor Safeguards 84/08/08 3pp 24210 340
- B408220122 Forwards revised site-specific procedural agreement, incorporating changes agreed to at 840731 meeting, for NRC signature BENNETI, J K Energy, Dept of 84/08/09 BROWNING, R E Division of Waste Management 17pp 26211 341
- 8408220167 Discusses DOE 810625 responses to NRC 840416 comments re
  "Slope Stability & Seisric Risk Evaluation" of Dec 1983
  draft Shiprock renedtal action plan Seismological aspects
  adequate & Chapter 3 statements accurate
  BLACKIGRD, M MRC No Detailed Affiliation Given 84/08/07
  PENNIFILL R MRC No Detailed Affiliation Given 1p 26203 362
- 8408220215 Forwards fully executed Interagency Agreement
  DE-AID4-84AL27241 between DDE & TVA NRC concurrence
  conditioned upon satisfactory resolution of NRC concerns by
  appropriate mod to agreement by 841002
  HILL T V Energy, Dept of 84/08/10 DDNUVAN T K Tennessee
  Valley Authority 12pp 26210 336
- --B408220219 Concurs in interagency agreement between DOE & TVA re disposal of radioactive matis from vicinity properties in Edgenont: SD Concurrence conditioned upon satisfactory resolution of NRC concerns HIOGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch 84/08/03 MARQUEZ, R. Energy, Dept of 3pp 26210 350
- 8408220223 Submits notice of upcoming meetings, per 830719-20 meeting Notice will be updated weekly TAYLON, T J Energy, Dept of 537 84/08/10 LINEHAN, J NRC - No Detailed Affiliation Given HINCHMAN, J Utah, State of FRISHMAN, S Tevas, State of 2pp 26203 360
- 8408220227 Confirms BA0921 meeting in Denver.CO re comments on revised preliminary DES Proposed approach on groundwater analysis will be transmitted by 840813 for inclusion in DES MORLEY, JA Energy, Dept of 84/08/10 PENNIFILL, R NRC No Detailed Affiliation Given 9pp 26203 351
- 8408220232 Informs of publication of FE9 for UMTRA project in Salt Lake City. UT, per 840412 ltr FES modified to incorporate statements re unconfined aquifer into Sections D 3 6 5 & D 89 BAUBLITZ, J E Energy, Dept of 84/08/08 HIGGINBOTHAM, L Low Level Waste Licensing Branch 15pp 26203 336
- B40B220234 Submits June 1984 highlights re remedial action plan Highlights include signing of MOU w/TVA re tailings disposal for Edgemont vicinity property & completion of Shiprock final EIA MORLEY, J A Energy, Dept of 84/08/13 HIGGINBOTHAM, L Low Level Waste Licensing Branch 7pp 26203 329

- B408220338 Annotated "Mono on Hater Supply Investigation at Shiprock School Makaja Indian Reservation San Juan County NM " CALLAHAN JP , HARSHBARGER J Interior, Dept of Geological Survey 55/03/31 16pp 26203 313
- 8408220240 Agenda for 840817 meeting in Lacey.WA to discuss description of grant proposal status of C3C agreement & DDE presentation of mission plan

  \* Washington, State of 926 84/08/17 Washington, State of 1p 26203 312
- 8408220324 Trip rept of B40717 visit to State of NV tockmechanics waste test site & 840718-20 visit to Sandia Natl Labs in Albuquerque.Nf re design test review Viewgraphs encl GREEVES, J T. DUTTA, P. TANIOUS, N. Engineering Branch (Past 831001) 343 84/08/07 COPLAN, S. Repository Projects Branch (Post 831001) 310pp 26203 001
- B40B220496 Agenda for 840726 meeting w/listed attendees in Silver Spring, MD to discuss site characterization plan format & content MILLER. H J. COOLEY, C. NRC No Detailed Affiliation Given 84/07/26 NRC No Detailed Affiliation Given 3ipp 26210 245
- 8408230027 Summary of 640730 meeting w/DDE & Colorado Dept of Health prelininary findings for Gunnison CO site HAISFICLD.M. PENNIFILL,R A Low-Level Waste & Uranium Recovery Projects Branch 94/08/06 H10901NBOTHAM.L Low-Level Waste & Uranium Recovery Projects Branch 2pp 26233 361
- B40B230D3( Forwards comments on draft Beatty site closure plan Plan inadequate for effecting proper closure of facility Major deficiencies include lack of documentation re geology & hydrology & support for cost & financial data H1931NBDTH4ML Low-Level Waste & Uranium Recovery Projects Branch B4/0B/15 NUSSBAUMEN, D A Assistant Director for State Agreements Programs 5pp 26233 354
- 8408230033 Advises that Nuclear Packaging, Inc topical rept on FL-50 container acceptable Rept info should include list of solid waste species & source which might be incompatible w/container math Info should meet NUREO-0800 guidance GAMMILL, WP Meteorology & Effluent Treatment Branch 84/07/15 GARRETT, LH Engineering Branch (Post 831001) 1p 26233 353
- 8408230034 Trip rept of 840729-0802 visit to Hanford Reservation,WA re review of geologic maps & field work performed since 1979 publication of ST-4 CULLER,J M Ogotechnical Branch (Post 831001) 937 84/08/14 JUSTUS.P S Ogotechnical Branch (Post 831001) 2pp 26233 351
- 8409230234 Forwards Geotechnical Engineering review comments & questions re Shiprock renedial action plan BARRETT, L. H. Engineering Branch (Post 831001) 84/08/10 HIGGINBGTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch App. 26233 345
- 8408230038 Submits BWIP site rept for wks of 840708-0810 re transportation safety & review of issue tracking sys & data/records mgt sys CQCV,F R Division of Waste Management 84/08/11 DRCWNING.R E Division of Waste Management 4pp 24233 333
- --B408230043 Advises that request for limited access to BNWL documents re MCC-D2 data package, in support of Matls Review Board review of data package, honored WHIE.J D Energy. Dept of B4/08/03 COOK, FR NRC - No Detailed Affiliation Civen Spp 24233 337
- 8408230041 Ack receipt of nonproprietary & proprietary STD-R-03-008, "Hittman RADLOK High Integrity Containers," transmitted on 840628 Tentative schedule for review of rept encl TIKTINBKY,D M Engineering Branch (Post 831001) 84/08/14 LEDUC,R J Westinghouse Hittman Nuclear, Inc 2pp 26233 331
- 8408230046 Forwards selected major comments re draft Umbrella Site technical position for salt, geology, groundwater geochemistry, design & waste package Comments developed considering need to minimize efforts to make revs MILLER, HJ Repository Projects Branch (Post B31001) 84/08/07 KNAPP, M R Geotechnical Branch (Post B31001) BARRETT, L. Engineering Branch (Post B31001) 15pp 26233 316
- 8408230053 Trip rept of attendance at American Geophysical Union Spring conference on 840514 in Cincinnati.OH re presentation of paper on flow parameters of partly saturated soils & spatial variability Viewgraphs encl CONKE.B A Geotechnical Branch (Post 831001) 84/08/02. KNAPP.N R Geotechnical Branch (Post 831001) 26pp 26233 290

- 8408230062 Comments on revised modeling strategy document for high level uaste performance assessment Piscrepancies exist between document & DOE siting guidelines FERRINGER.D J. Repository Projects Branch (Post 831001) 84/08/04 PFLUNC G. Repository Projects Branch (Post 831001) 2pp 26232 273
- B408230069 Requests review b comments on encl Westinghouse Hittman STD-R-03-008, "Hittman RADLOK High Integrity Containers," by \$41102 Encl withheld BARRETICL H Engineering Branch (Post 831001) 84/08/15 COSTANZI, F.A. Division of Waste Management ip 26233 272
- B40B230079 forwards comments on BMI/QNWI-513. "Salton Sea Geothermal Field.California as Near-Field Natural Analog of Radwaste Repository in Salt " NRC supports use of natural analogs for DDE assessment of high level waste site LINEMAN.J.J Repository Projects Branch (Post 831001) 633 B470B/ID NEFF.J.D Energy. Dept of 5pp 26233 244
- 8408230085 Concurs u/planned remedial actions for vicinity property identified in enclobased on review of radiological & engineering assossments HIGGINBOTHAM.L Low-Level Waste & Uranium Recovery Projects Branch 84/08/01 MCREEY, J A Energy. Dept of 2pp 26233 242
- B40B230100 Provides clarification of NRC position re revised procedure for extending & documenting NRC concurrence in vicinity property remedial actions.per recipient 840711 comments HIGOINBOTHAM. Low-Level Waste & Uranium Recovery Projects Branch 84/08/04 MORLEY, J A Energy, Dopt of 2pp 26236 129
- 8408230362 Forwards request for addl info to continue review of Nuclear Packaging. Inc topical rept on FL 50 Ferralium 225 high integrity container Response requested within 45 days of litreceipt W/o encl NUSSBAUMER. D A Assistant Director for State Agreements Programs 84/08/15 MIRMER, N P Hashington, State of, Dept of Social & Health Services 19 26230 358
- 8408230394 Forwards list or documents needed to allow commont on 840601 preliminary draft environ assessment for Nevada Nuclear Waste Storage Investigations Project W/o encl COPLAN.8 In Repository Projects Dranch (Post 831001) 345 84/08/10 VIETH.D L Energy, Dept of 1p 26230 257
- 8408230393 Forwards draft generic technical position of licensing assessment methodology for high level waste geologic repositories W/o entl MILLER.H J. Repository Projects Branch (Post 831001) 84/08/10 BENNETIJU W. Energy Dept of 2pp 26230 255
- 8408230420 Comments on groundwater STP for Palo Duro & Paradox bedded salt basins Program inconsistent in treating prewaste emplacement phenomenon u/post-emplacement phenomenon, per 10CFA60 113

  JOHNSON, T C Engineering Branch (Post 831001) 636 84/08/07
  POHLE, J Geotechnical Branch (Post 831001) 2pp 26230 241
- 8408230423 Comments on draft site technical position on groundwater issues for Palo Duro & Paradox bedded salt basins Emphasis on groundwater & exclusion of waste package interactions urgod
  PETERSON.C H Division of Waste Management 632 84/08/03
  TOKARM Division of Waste Management 2pp 26230 227
- 8408240005 Agenda of B40710-12 geochemistry workshop w/Nevada Nuclear Waste Site Investigations at Los Alamns Natl Lab to discuss geochemical issues Viewgraphs oncl \* NRC - No Datalled Affiliation Given 340 84/07/12 NRC - No Datailed Affiliation Given 354pp 26252 001
- 8408240103 Ack receipt of ltr re high level repository sites in UT Paradox Basin NRC preparing to review site environ assessments from DOE US Park Svc views will be considered in review LINEHAN.D J Repository Projects Branch (Post 831001) 637 B4/08/06 HINTOMYER.L Interior. Dept of. National Park Service ip 26253 332
- 8408240119 Comments on Jun 1984 progress rept for Contract NRC-02-84-002 Task Orders OD1 & 002 complete Remaining work under Task Orders OO3-006 noted BUCKLEY, J T Engineering Branch (Post 831001) NRC-02-84-002 1420 84/08/07 CUMINOS, R Engineers International, Inc 2pp 26255 274
- 8408240214 "Geochemical Sensitivity Analysis." monthly rept for Jul 1984 SIEGEL.M D Sandia Laboratories FIN A-1756 1429 84/08/15 KRLLY.W NRC - No Detailed Affiliation Given 5pp 26254 351.

- 8408240221 Forwards cumments on NRC review of DDE 840111 response to NRC 830615 concerns on exploratory Shart const % sealing methods

  CUMMINGS R A Engineers International, Inc. FIN D-1004
  1148-003-04C 84/08/13 BUCKLEY, J High Level Waste Technical Development Stranch 200p 26255 137
- B40B240260 "Monitor/Review Aspects of DOE / Other Natl 1. Intl Waste Mgt Programs" ! "Short-Term Technical Assistance," summary of activitie, for Jul 1984
  CRANWILLER II Sandia Laboratories FIN A-1165 1423 84/08/15
  PEETERS.L A Repository Projects Branch (Post 831001) 3pp
- 8408240265 "Technical Assistance in Seismo-Tectonic Impacts in Repositories." Monthly Mgt Ltt Progress Rept 16 for Jul 1984 CHUNG, D. H. Laurenco Livermore National Laboratory FIN A-0294 EG-84-065/03264 84/08/09 BLACKFORD, M. E. Geotechnical Branch (Post 831001) 6pp 26251 266
- B408240284 "(oupled Thermal-Hydrological-Mechanical Assessments & Site Characterization Activities for Geologic Repositories," monthly rept for Jul 1984 CHU.M S Sandia Laboratories FIN A-1755 1425 84/08/15 NATARAJA.M S Engineering Branch (Post 831001) 2pp 26252 359
- B408240291 "Benchmarking of Computer Codes & Licensing Assistance," monthly itr progress rept for Juli 1984
  VDGT.D K CorSTAR Research, Inc FIN 8-6985 1410 84/08/10
  BROCKB.P Division of Haste Management 44pp 26251 319
- 8408240275 "Geological Stability Issues for BWIP." site technical rept CHUNO.D H Lawrence Livermore National Laboratory FIN A-0274 1430 84/08/10 Division of Waste Management 34pp 26251 285
- 8408240335 Requests technical assistance in reviewing encl list re-salt environ assessments & corrosion & failure of 1025 wrought steel overpack Comments requested by 840810 MICK, E A Engineering Branch (Post 831001) FIN A-3167 1413 84/08/03 SGO. P Brookhaven National Laboratory 7pp 26253 325
- 8408240354 Forwards "Nevada Nuclear Waste Starage Investigations Project Monthly Rept May 1984 ' VIETH,D L Energy, Dept of 84/07/10 BENNETT,JW Energy, Dept of 19 26253 205
- ---8409240J55 "Nevada Nuclear Waste Storage Investigations Project:Monthly Rept:May 1984 " \* Energy, Dept of 84/05/31 75pp 26253 207
- 8408240372 Informs that mend on thermodynamic relations in magnetite hematite water sys reviewed in lespanse to 840720 mend Inconsistent use of sign conventions by BOR in draft SCR created confusion KNAPP, M R Geotechnical Branch (Post 831001) 84/08/10 BARRETT, L M Engineering Branch (Post 831001) ip 26234 344
- 8408240374 Revieus rept of investigation for AML Project 7.Part III outlining proposed reclamation plan for several abandoned mines near Baggs.WY Points requiring discussion at 840705 meeting listed BEACH,0 Wyoming, State of 01254 84/06/19 ANSELMIK, VORELERLY Wyoming, State of 4pp 26284 336
- 840B240376 Recommends that work backfill be changed to engineered barrier sys in performance Issues 3 % 8 from App C of BWIP BCA.per 840724 neeting U/J Greeves
  TIKTINSKY.D Engineering Branch (Post 831001) 84/08/06
  JOHNEON.R Repository Projects Branch (Post 831001) 1p
  26/284 334
- 840B240378 Forwards details of concerns about DDE treatment of waste package environ re thermodynamic relations in magnetite water sys as set forth in BWIP SCR of Nov 1982 W/o encl BARRETI,L H Engineering Branch (Post 831001) 84/07/20 KNAPP,M R Geotechnical Branch (Post 831001) 1p 26254 332
- 8408240388 Discusses evaluation of seismogenic hazard concepts at Pelo Duro Basin salt sites developed from recent work along Meers Fault near Lauton, DK Possible connection of neatectonic activity needs assessment Lists tests CHWNO, D H Laurence Livermore National Laboratory FIN A-0294 EO-88-066 84/08/09 JUSTUS, P S Geotechnical Branch (Post 831001) 2pp 26249 360
- B408240390 "BWIF Hydrogeology," Ltr Rept 88 for Jul 1984 RDM2,J Golder Associates FIN B-7373 823-1033 84/08/08 GORDON, M Division of Waste Management 2pp 26248 360

- 8408240392 Summary or 840714 meeting w/BNL in Silver Spring MD re BNL final rept on data review in support of environ assessment rept analysis (FIN x-3164 re review of D1 of Engineering waste package program)
  - WHICH E A Engineering Branch (Post B31001) FIN A-3164 1412 84/08/07 EARRETT: L H Engineering Branch (Post B31001) 4pp 26249 151
- 8408270750 Discusses concerns to "Determination of Radionuclide Solubility in Grounduster for Assessment of High Level Raduaste Isolation Marked-up draft repts encl KELMERS, A D. Oak Ridge National Laboratory FIN 8-0287 1409 84/08/15 2R00kS, D.J. Ceptechnical Branch (Post 831001) 63pp 26258 246
- 8408270070 Comments on review or thermal analysis of environ assessment for Swisher repository in salt Two components of uncertainty in prediction of temps erist NRC should request code listings u/sample problems & documentation SASTRF, C Brogyhaven National Laboratory 1426 84/08/10 Brochaven National Laboratory 1727 325
- 8408270J74 Forwards review comments for repository site design & rock mechanics sections of draft Nevada Nuclear Waste Storage
  Investigation Project rept
  MCLLO\*.E E Interior. Dept of Bureau of Mines 1422 84/08/10
  AMEV.E B Interior. Dept of Bureau of Mines ip 26278 318
- --84082/0078 Forwards review comments for draft Nevada Nuclear Waste Storage Investigation Project environ assessment HOLIOP.E E Interior, Dept of Bureau of Mines 84/08/10 TIKTINSKY.D Engineering Branch (Post 831001) 6pp 26278 319
- 8408270250 Forwards draft radiological & engineering assessment repts for Properties 0J-12761 MR.GJ-34247-RS.GJ-06318-VL.GJ-00153-CS.GJ-03142-CE.GJ-03785-C5 & GJ-09566-VL.TUCKER,M K Energy. Dept of 84/08/01 HIGGINBOTHAM.L Low-Level Waste & Uranium Recovery Projects Branch 1p 26278 001
- ~~8408270253 Draft "Radiological & Engineering Assessment for Property QJ-12261-MR \* \* Bendix Corp 84/07/31 36pp 26278 002
- --B40B270256 REA-GJ-34247-RS REA-Draft "Radiological & Engineering Assessment for Property GJ-34247-RS " \* Bendix Corp 84/07/31 28pp 26278 036
- --8408270262 REA06318-GJ REA-108/ Draft "Radiological & Engineering Assessment for Property GJ-06318-VL "
- # Bendix Corp #4/07/31 30pp 26278 064
- --8408270264 REA00153A03142 REA-5
  Draft "Rediological & Engineering Assessment for Property gJ-00153-05 & GJ-03142-05 " W/one oversize map Aperture card available in PDR \* Bendix Corp 84/07/31 24pp 26278 094
- --84082/0267 REA05785-GJ REA-112A Drart "Radiological & Engineering Assessment for Property GJ-05785-GS & Property GJ-09364-VL " \* Bendix Corp 84/07/31 27pp 26278 119
- B408280005 Forwards marked-up "Progress in Evaluation of Radionuclide Geochemical Info Developed by DDE ," BMIP rept & M Siegel rept, "Calculations of Radioelement Solubilities in Basait Ground Waters "
  BRADBURY, J W Geotechnical Branch (Post 831001) FIN B-0270 BA/08/13 WHATLEY, S X Dak Ridge National Laboratory 77pp 26293 248
- --B4002B0007 SD-BHI-DP-QO; RA-O
  Rev A-O to "BNIP Data Package for Ref Solubility & Kd
  Values"
  SALTER,P F., JACOBS,O K. Rockwell International Corp. 83/01/06
  9pp 26293 327
- --8403280009 "Calculations of Radioelement Solubilities in Basalt Ground Waters," ltr rept SIEGEL.M Sandia Laboratories 83/10/31 15pp 24273 336
- 840B280031 Summarizes comments & recommendations, per review of revised rept. "Benchmark Problems for Repository Siting Models," (NUREO/CR-3097) Addl paragraphs on ground rules using benchmark problems needed BROO'S, P Repository Projects Branch (Post 831001) FIN B-6985 84/08/06 VOOT, D K CorSTAR Research, Inc. 13pp 26293 156

- B408280112 'Shiprock Well Completions "
  PRICE J Jacobs Engineering Group, Inc. 84/08/13 NEBER,M F NRC.
   No Detailed Affiliation Given 15pp 26294 124
- B408280121 'Comments on Double-Porosity Models for Fissured Groundwater Reservoir w/Fracture Skin ' WILLJAMS.R E Idaho, Univ of Moscow, ID FIN 8-7377 1431 84/08/27 Division of Waste Management 8pp 26294 116
- B408280338 Informs of review of process control program section of Chem-Nuclear CNSI-MF C-OI-MP, "Maste Form Centification" Chen-Nuclear requested to provide written description of causes & corrective actions taken GAMMILL, V P Heteorology & Effluent Treatment Branch 64/08/15 HIGGINDOTHAM. Low-Level Waste & Uranium Recovery Projects Branch 2pp 26294 048
- 8408280340 Forwards comments on "Design Criteria for Stabilization of Inactive U Kill Tailings Bites," per 840717 request SMYKOMSKI, S. ofLLFN.D M Engineering Branch (Post 831001) B4/08/01 FENNIFILL.R Low-Level Waste & Uranium Recovery Projects Branch 2pp 26274 041
- B40B270275 Activities of Contract NRC-02-B4-001, Monthly Progress Ltr Rept 4, advising that no task order commitments assigned for or in state of assignment MURPHY. V J Weston Geophysical Corp FIN D-1003 MGC-R531 84/08/14 RICE, B J Geotechnical Branch (Post 831001) 1p 26309 009
- 8408290337 "Maint & Validation of Computer Programs," monthly rept for Jul 1984 CRANHELL,R M Sandia Laboratories FIN A-1166 84/07/31 CODELL.R Geotechnical Branch (Post 831001) 3pp 26927 005
- B408300178 "Maint & Violation of Computer Programs," revised monthly rapt for Feb 1984 ORTIZ.N R Sandia Laboratories FIN A-1166 1073 84/02/29 CODELL,R Geotechnical Branch (Post 831001) 18pp 26330 342
- B408310263 Forwards C Jacobs trip rept of B40822 visit to ONWI WHATLEY, B K Dak Ridge National Laboratory FIN B-0287 1445 B4/08/23 BRQOKS, D J Geotechnical Branch (Post 831001) 75pp 26381 259
- B408310270 Forwards response to 840612 comments on UMTRA Salt Lake City FEG & on B40606 meeting groundwater issues FR notice of FES availability published on 840803 Comment period closes on 840903 MCRLEY.J A Energy, Dept of B4/08/24 HIGOINBOTHAM.L Low-Leve Waste & Uransum Recovery Projects Branch 5pp 26350 318
- 8408310273 Confirms 840831 info mgt sys meeting in Las Vegas,NV.per 840809 request VIETH.D L Energy. Dept of 84/08/20 COPLAN.S M Repository Projects Branch (Post 831001) 1p 26350 317
- 8408310331 Forwards results of radium & radon emanation coefficient tests on four U tailings samples received 840213 from Riverton, kY site Encl completes Task 35 deliverables Lab test procedure described in 830603 memo NIELSON, K K Rogers & Associates Engineering Corp 84/03/27 DZAACK D D Jacobs Engineering Group, Inc 8pp 26351 001
- --8408310335 UMTRA-DDE/AL-0230
  "Data for Geochenical Investigation of UMTRAP Designated
  Site at Riverton,WY"
  MARMOS, G. BUSH, K. J., MBRLEY, J. A. Energy, Dept. of 83/09/30
  70pp 26391 009
- --8408310339 UMTRA-DDE/AL-0229
  "Geochemical Investigation of UMTRAP Designated Site at
  Riverton.WY"
  MARKOS,O . BUSH, K J . MORLEY, J A Energy. Dept of 83/09/30
  83pp 26351 079
- --8408310344 "Hydrogeochemical Studies of U Mill Tailings at Riverton, Wi & Maybell.CO," quarterly progress rept. Jul-Sept 1982 Undated Riverton Mill radiological contamination survey encl NARASIMAN.T N Lawrence Berkeley Laboratory 82/09/30 112pp 26351 162

#### WASTE RES WASTE MANAGEMENT RESEARCH REPORTS

B40B240119 Comments on Jun 1984 progress rept for Contract NRC-02-84-002 Task Orders 001 & 002 complete Remaining work under Task Orders 003-004 noted BUCKLEY, J T Engineering Branch (Post 831001) FIN D-1004 1420 84/08/07 CUMMINGS R Engineers International, Inc 2pp 24255 274

- 8408240214 "Geochemical Sensitivity Analysis." monthly rept for Jul
  - 1784
    BIFOGL M D Sandia Laboratories FIN A-1756 1424 84/08/15
    KELLY, W NRC No Detailed Afriliation Given 5pp 26254 351
- 8408240221 Forwards comments on NRC review of DOE 84011; response to MRC 830619 concerns on exploratory shaft censt & sealing methods
- Engineers International, Inc. FIN 0-1004 1421 KLEY, J. High Level Waste Technical Development Branch CUMMINOS, R A Engine 84/08/13 BUCKLEY, J 04/08/13 BUCKLE 9000 26255 137
- B40B240260 "Monitar/Revieu Aspects of DDE & Other Natl & Inti Waste Mgt Programs" & "Short-Term Technical Assistance," summary of activities for Jul 1984 CRANHELL.R M Sandia Laboratories FIN A-1165 1423 B4/08/15 PETERS.L A Repository Projects Branch (Post B31001) 3pp
- 8408240265 "Technical Assistance in Seismo-Tectonic Impacts in Repositories." Monthly Mgt Ltr Progress Rept 16 for Jul 1984
  - CHUNO, D H Laurence Livermore National Laboratory FIN A-0274 1427 84/08/09 BLACKFORD, M E Geotechnical Branch (Post 831001) 6pp 26254 266
- 8408240284 "Coupled Thermal-Hydrological-Mechanical Assessments & Site Characterization Activities for Goologic Repositories." monthly rept for Jul 1984 CHU-M S Sandia Laboratories FIN A-1755 1425 84/08/15 NATARAJA, M S Engineering Branch (Post 831001) 2pp 26252 359
- 8408249291 "Benchmarking of Computer Codes & Licensing Assistance," monthly ltr progress rept for Jul 1984 VQGT.D K CorSTAR Research, Inc. FIN 8-6985 NRC-02-81-026 84/08/10 ERGOAS,P Division of Waste Management 44pp 26251
- B40B240275 "Geological Stability Issues for BMIP." site technical rept CHUNG.D H Laurence Livermore National Laboratory FIN A-0274 L-75 84/08/10 Division of Waste Management 34pp 26251 285
- 840B240390 "BWIP Hydrogeology," Ltr Rept 88 for Jul 1984 ROWE, J Golder Associates FIN B-7373 NRC-02-82-045 84/08/08 GORDON:# Division of Waste Management 2pp 26248 360
- 8408270050 Discusses concerns re "Determination of Radionuclide Solubility in Oroundwater for Assessment of High Lovel Radwaste Isolation "Marked-up draft repts enci KELHERS.A D. Oak Ridge National Laboratory FIN 8-0287 1409 84/89/15 \$RODKB.D J. Geotechnical Branch (Post 831001) 65pp 26298-246
- 8408280031 Summarises comments & recommendations, per review of revised OBSENUED Symmetries comments & recommendations, per review of respt. "Genchmark Problems for Repository Siting Models,"
  (NUMEO/CR-3097) Addl paragraphs on ground rules using benchmark problems needed BROOKS, PP Repository Projects Branch (Post 93100)) FIN B-84/08/06 VQOT.D K CorSTAR Research, Inc 13pp 26293 156 FIN B-6985
- 8408280121 "Comments on Double-Porosity Models for Fissured Groundwater Reservoir w/Fracture Skin " HILLIAMS.R E Idaho. Univ of Moscow. ID FIN 8-7377 1431 84/08/27 Division of Waste Management Spp 26294 116
- 8408290295 Activities of Contract NRC-02-84-001.Monthly Progress Ltr Rept 4. advising that no test order commitments assigned for or in state of assignment MURPHY.V J. Waston Geophysical Corp. FIN D-1003 WGC-R531 84/08/14 RICE, B. J. Geotechnical Branch (Post 831001) ip 26307 007
- 8408290337 "Maint & Validation of Computer Programs," monthly rept for Jul 1989 CRANWELL:R M Sandia Laboratories FIN A-1166 84/07/31 CODELL:R Geotechnical Branch (Post 831001), 3pp 26329 005
- 8408300178 "Maint & Violation of Computer Programs." revised monthly rept for Feb 1984 ORTIZ.N R Sandia Laboratories FIN A-1166 1073 84/02/29 CODELL.R Geotechnical Branch (Post 831001) 18pp 26330 342
- 8408310265 Forwards O Jacobs trip rept of 840822 visit to ONWI HHATLEY.8 K Dak flidge National Laboratory FIN 8-0287. 1445 84708/23 BROOMS.D J Geotechnical Branch (Post 831001) 75p 26351.259

- XPORTLIC EXPORT AND IMPORT LICENSES
- 8405160213 Ltr or assurance re export of 302 kg U-235, contained in 10.066 kg U.to Japan SHIRAKAWA.T Japan Gost of 84/04/20 RAYMOND.JF Energy, Dept of 1p 24487 247
- 8405140242 License for Natl Nuclear Corp to export 2 58 mg Cf-252, contained in one neutron source to United Kingdom ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards BNFL-C-720 84704/30 ip 24491 004
- 8408010134 Amend 2 to Westinghouse export license, extending expiration date from 850101 to 701231 for export of licensed matls to Snain
  - ZIMMERMAN, J V SPEIN OF THE STATE OF THE SPECIAL STATE OF THE SPECIAL STATE OF THE SPECIAL SP
- 840BD1013B Executive Branch position re DDE application to export 2 kg Pu & 12 kg depleted U to Japan License should be granted Assurance ltr enci DEVINE. J B State. Dept of 84/05/18 SHEA. J R Office of International Programs, Director 2pp 25873 309
- 8408010142 Application for license to export Zircalou-4 double thimble tubes to Japan
  ASTLEY E R Sandvik Special Metals Corp SSM-41135 84/05/17 1p
- 8408060064 Forwards application to amend export license, adding Blayais 3 as addl ultimate consignee Ltr of assurance Blagars & as a control of the state of the s 25937 078
- 8408050350 License for GE to export 3 085 kg U-235, contained in 85 kg U.to Spain MODRE R N Assistant Director for Export/Import & International Bafeguards 8DW-83-006 84/07/27 2pp 25937 350
- 8408040351 License for Westinghouse to export 10 g U-235, contained in NOBORES N Assistant Director for Export/Import & International Safeguards MMH-361 84/07/27 2pp 25937 348
- 8408050393 License for GE to export U densitometer to Spain MOORE,R N Assistant Director for Export/Import & International Safeguards BDW-84-114 84/07/27 1p 25937 345
- 8408040359 License for Elgar Intl Corp to export one lot inverters. converters, frequency changers & generators, having multiphase electrical power output within range of 600 to 2,000 Hz, to France MOORE, R N Assistant Director for Export/Import & International Safeguards I-206A 84/07/27 Ip 25937 344
- 8408040402 Application for license to export 15.327 kg U. as UFA to Japan OKADA,5 Mitsui & Co (USA), Inc (subs of Mitsui & Co , Ltd ) NBK-F5-R7(A) B4/07/24 ip 25950 362
- 8408040406 Application for license to export 11,139 kg U, as UF6, to Japan OKADA,8 Mitsui & Co (USA), Inc (subs of Mitsui & Co , Ltd ) MBK-F5-R7 (B) B4/07/19 1p 25950 361
- 8408060432 Application for license to export 789 mg U-238, enriched to 93% U-235 to Italy HEIMAN D Reactor Experiments, Inc ITAL-42695 84/07/18 ip 25937 333
- 8408050435 Requests Executive Branch position re Mitsui & Co (USA), intapplication for license to export 351 kg U-235, as UF6, to TIMMERMAN, J V Assistant Director for Export/Import & International Bafaguards 84/07/27 THORNE, C E Energy, Dept. of 1p 25937 320
- -- B408060438 Application for license to export 351 kg U-235, as UFA, to Japan OKADA, S Mitsui & Co (USA), Inc (subs of Mitsui & Co , Ltd.)
  MBK-F5-R7 (B) 84/07/19 ip 25937 321
- 8408070049 License for GE to export 1.000 kg natural U. as UD2 powder, to Spain
  MODRER N Assistant Director for Export/Import & International
  Safeguards 84/07/27 2pp 25755 336

- B40B370171 Application for license to export Model B48TCM-3-4-1-2 oscillator  $\ell$  inverters, converters  $\hbar$  frequency changers. Uselliatury inverters converters " requency changers, to Fiance California Instruments 20326 84/06/19 3pp 25957 114
- 8408070175 Requests Executive Branch postion re 810210 & 0506 applications for license to export reloads of low entiched
- U ZIMHERMAN,U V Assistant Director for Export/Import & International Safeguards 84/07/31 THORNE.C E Energy, Dept of 1p 25957 113
- B40B0701B1 Amend 1 to Vestinghouse export license, adding Westinghouse Nuclear Japan as add1 intermediate consignee ZIhMERMAN,J V Assistant Director for Export/Import & International Safeguards B4/07/30 1p 25757 112
- 8408070202 Amend 1 to Mitsui Air Intl. Inc export license, increasing
- value of equipment ZIMMERMAN, J V As ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/07/31 1p 25957 099
- 8408070206 Amend 2 to Mitsul Air Intl. Inc export license, increasing value of equipment adding Hamaoka 3 power reactor as addl facility & adding Electrolizing Inc as new supplier ZIMMERMAN.J V Assistant Director for Export/Import & International Sareguards 84/07/31 1p 25957 098
- 8408070209 Amend 3 to Mitsui Air Intl. Inc export license, adding
- Fukushima 4 to Hitsul Alt Intl. Inc export license, agoing
  Fukushima 4 to 2 facilities
  ZIMMERMAN.J V Assistant Director for Export/Import & International
  Safeguards 84/07/31 ip 2595/097
- 8408070214 Amend 3 to Mitsu: Air Intl. Inc export license, adding
- OBBOOKER Among 3 to miss. An annual specific process of the second of th
- 8408070504 License for Carpenter Technology Corp to export 210 Zircaloy-Bur fuel channels to Italy ZIMMERMAN.JV Assistant Director for Export/Import & International Safeguards SPD 5732 84/07/31 ip 25956 236
- B40B070510 License for Elgar Intl Corp to export inverters, converters, frequency changers? generators, to Gueden ZIKMERMAN.J V Assistant Director for Export/Import & International Safeguards 18364 SWEDEN 84/07/31 1p 25956 223
- 8408070512 License for Elgar Intl Corp to export inverters, converters, frequency changers ? generators to The Netherlands ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 84/07/31 tp 25956 224
- 8408080013 Informs that Australian govt not prepared to give prior consent to export of all Australian gove not prepared to give people to consent to export of all Australian origin nuclear matl specified in License (SN:1-0740 & XSNM-1472 Govt exercising prior consent over retransfer on case-by-case basis CEJA:5 N Energy, Dept of B4/07/26 ZIMMERMAN, J V As: Director for Export/Import ' International Safeguards 2pp 25781 033 Assistant
- 8408090108 License for Signa Chemical Corp to export 5 0 kg deuterium oxide to Spain ZIMBERHAN.J V Assistant Director for Export/Import & International Safeguards D-115 84/08/01 1p 25777 108
- 8408090118 License for Westinghouse to export 440 zirconium tubes, 2,800 zirconium plugs,1,400 stainless steel springs,100 thimble screws & 14 inconel,grids to Spain ZIMICRIAN,J V Assistant Director for Export/Import & International Safeguards MMH-523 84/08/01 lp 25979 119
- 8408080219 Application for license to export spare parts, consisting of P/N NV23-1 & P/N NV23-2 check valves, to Canada SMITH-N Brunsuick Co N42150 84/07/26 ip 25978 325
- 8408080532 Application to amend import license adding addl isotope of Pu Renewal of license also requested BAGBY.L A Amersham Corp 84/07/26 MUDRE.N Office of International Programs, Director 2pp 25975 338
- 8408080534 License for General Motors Saginaw Steering Gear Div.to export spare parts for loading & unloading fuel elements to Canada vanada ZIMMERMAN,J V Assistant Director for Export/Import & International Bafeguards 84146 84/08/02 1p 25975 357 Safeguards

- 8408150112 Litense for Transnuclear. Inc to export 12,380 kg U-235 to West Germany ZIMMERMAN J V Assistant Director for Export/Import & International Safeguards NUV-451 B4/08/08 2pp 26104 280
- 8408150128 Ltr of assurance re export of 208 kg U-235, contained in HOBIOTED LET OF ASSURED TE EXPOSE OF MEDICAL STREET OF ASSURED LAND AS JA104 255
- 8408150131 Advises that govt or Australia will require fabricator (UPAEA) to dilute high enriched U to at least BOX BAVAGE.E N. Australia, Oovt of 208/14/8 84/07/31 HRIGHT, B Office of International Programs, Director ip 26104 254
- 8408150135 Application to amend export license extending expiration 108150135 Application of ements applied to 871001 date to 871001 BRYAN, D.C. Texas Nuclear Div. (subs. of Ramsay Engineering Co.) 84/07/27 WRIGHT, B. Assistant Director for Export/Import & International Safeguards 1p. 26104-250
- 8408130143 License for Westinghouse to export 70 pieces of Inconel-600 steam generator tubing to United Kingdom ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards MMH-529 84/08/06 1p 26104 001
- 8408130166 Amend 3 to import license for Edlow Intl Co for British Nuclear Fuels, Ltd. extending expiration date until 870101 & increasing quantity to 230 kg U ZIMMERMAN, J V Assistant Director for Export/Import & International Bafeguards 84/08/08 2pp 26103 361
- 8408150169 License for Erxon Nuclear Co.Inc to export 1.035 % U-235, contained in 30.491 kg U.to Hest Germany ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 84/08/08 2pp 26103 359
- 8408150179 Ltr of assurance re export of 749 kg U-235, contained in (OBIODI/7 EU O. S.) 24,229 kg U. to Japan BHIRAVAWA.T Japan. Govt of 84/07/27 TKORNE,C E Energy. Dept of 1p 26102 362
- B40B1501B2 Informs that License XBNM-2150 may be issued No matl changed corcumstances wince issuance of License XSNM-1975 MODRE:R N Assistant Director for Export/Import & International Safeguards 84/08/0B Assistant Director for Export/Import & International Safeguards ip 26102 361
- 8408150237 Application for lacense to import may of 27,830 kg V as uro, From France
  HERSCH, M M (Hestinghouse Electric Corp MMH-536 84/08/07
  MOURE, R N Assistant Director for Export/Import & International
  Safeguards 2pp 26102 359 UF6 from France
- 8408150246 Requests Executive Branch position re Harnischfeger Corp application for license to export two electric overhead traveling cranes to China for use in Ginshan Nuclear Power Reactor Zimmerman.J V Assistant Director for Export/Import & International Safeguards 84/08/08 STOIBER.C R State. Dept of Bureau of Oceans & Intl Environ & Scientific Affairs 1p 24099 358
- --8408:50290 Application for license to export two electric overhead traveling crames to Chima for use in Gimshan Nuclear Power Reactor CHERONES, W.J. Harnischfeger Corp. CMEC-84 84/07/25 1p
- B408150270 License for Exxon Nuclear Co, Inc to export 1,380 kg U-235, contained in 44,530 kg U, to West Germany ZIMMERNAN, J V Assistant Director for Export/Import & International Bafeguards 84/08/08 2pp 26099 353
- B408150359 Application for license to export 10 Ci spher(cal microshell glass or plastic pollets, containing elementary deuterium & tritium, to France
  HIDMAN J C KMS Fusion, Inc (Subs of KMS Industries, Inc )
  EMSF-0684-EP 84/08/06 3pp 26099 360
- --8409150361 Forwards application for license to export 10 Ci spherical microshell glass or plastic pellets, containing elementary deuterium & tritum, to France HIDMAN.J C KMS Fusion, Inc (Subs of KMS Industries, Inc.) R50-396-JCM 84/08/06 Assistant Director for Export/Import & International Safeguards 1p 26097 363
- 8408150402 Informs that License XSNM-2153 may be issued No math changed circumstances since issuance of License XSNM-1975 MDDRE.R N Assistant Director for Export/Import & International Safeguards 84/09/09 Assistant Director for Export/Import & International Safeguards 1p 26105 269

- 8408150642 Application for license to export two electric overhead traveling cranes to China CHERONES,W J. Harnischfeger Corp. CMEC-84 84/08/03 24102 338
- 8408150703 Informs that License XSNI-2154 may be issued No matl changed circumstances since issuance of License XSNM-1973 MODRE.R N Assistant Director for Expert/Import & International Safeguards 84/08/0R Assistant Director for Expert/Import & International Safeguards 12 26102 355
- 8408150705 Informs that Ahend I to License (SNM-2124 may be issued No 408150705 Informs that Amend I to License KSMM-2124 may be issued matl changed circumstances since issuance of License XSMM-2126
  MODRERR N Assistant Director for Export/Import & International Safeguerds 84/08/08 Assistant Director for Export/Import & International Safeguerds 1p 26102 354

- B40Bi5070B Amend 1 to Braunkohle Transport USA expert license, authorizing increase from 15 kg U-235.contained in 307 kg U, to 77 kg U-235.contained in 1,533 kg U ZIMMERHAN.J V Assistant Director for Export/Import & International Safeguards HEX-EX-4 84/08/08 ip 26102 353
- 840Bi507iJ Amend 2 to Delegation of Commission of European Communities export license, adding listed countries to license ZIMMERMAN, V Assistant Director for Export/Import & International Safeguards A0/1576 84/08/08 ip 26102 352
- 8408150717 License for Exxon Nuclear Co. Inc. to export 1,130 kg U-235, contained in 32.273 kg U, to Belgium
  ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 8408/08 2pp 26102 350
- 8408150719 Application for license to export 47.108 kg U.containing 1.743 kg U-233,to France HERSCH.M M Nes\*inghouse Electric Corp MMH-532 84/Q8/02 ip 24102 349
- 8408150722 Application for license to export packing to South Korea BUTLER.D L Borg-Warner Corp P6043kN 84/08/07 ip 26102 3 26102 34R
- 8408150724 Application for license to export mechanical, hollow core, helix urapped cable & slip ring assembly to Taiwan HINKLE,K A Teleflex, Inc. 019110 84/07/02 ip 26102 347
- 8408150726 Application for license to export 500 liters deuterium to Matheson Gas Products NSK 73184 84/07/31 1p 26102 346
- 8408150730 Application for license to export two fission chambers to France HERSCH.M M Restinghouse Electric Corp MMH 533 84/08/03 ip 24102 349
- 108170220 Application to amend export license, extending period of performance for 2 addl yrs
  MORGENSTERN, A Sigma Chemical Co 84/08/06 HEMBY, E Assistant Director for Except/Import & International Safeguards ip Director for Esport/Import & International Safeguards 26134 318
- 6408170405 License for Mitsui & Co to export 749 kg U-235, contained in 24.229 kg U.to Japan ZimHERMAN.J V Assitant Director for Export/Import & International Safeguards (BP-01-R2 84/08/13 2pp 26134-300
- 8408170405 Forwards application to export enriched UF6 to Japan SHIBATA.Y Mitsubishi International Corp (subs of Mitsubishi Corp ) HBA-5484-02 84/08/03 Assistant Director for Export/Import & International Safeguards 2pp 26:34 297
- -8408170408 Application for license to export 585 kg V-235, contained in 16.467 kg Urto Japan SHIBATA,Y Hitsubishi International Corp (subs of Mitsubishi Corp ) HSA-5484-02 84/08/03 1p 26134 299
- 8408170411 License for Mitsui & Co. Inc to export 208 kg U-235, contained in 7,206 kg U.to Japan ZIM:(ERMAN,J V Assistant Director for Export/Import & International Safeguards иВК-T2-R7 84/08/13 2pp 26134 295
- 8408170423 License for Edis Corp to export digital analog programmer having multi-phase electrical power output within range of 600 to 2,000 Herts, to Italy ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards S 0 51667 84/08/09 1p 26134 294

- 840B17042: Intorms that License XSIM-2127 may be issued No matt changed (i) (unstances since issuance of License /SIM-2131 MODRE,R N Assistant Director for Export/Import / International Safeguards 84/08/13 Assistant Director for Export/Import & International Safeguards ip 26134 293
- 840B170425 Informs that License XSNM-2137 may be issued No matl changed circumstances since issuance of License XSNM-2131 MODRE.R N. Assistant Director for Export/Import & International Safeguards 84/08/13 Assistant Director for Export/Import & International Safeguards 1p 26134-292
- 8408200150 License for Nuclear Valve Div of Borg-Warner Corp to export miscellaneous spare parts for use in valves to South Korea ZIMHERNAN.JV Assistant Director for Export/Import & International Safeguards P60431 N 04/08/09 1p 26/14/2 327
- 8408200160 License for Reactor Experiments. Inc. to export 789 mg U-235. contained in 848 mg U.to Italy ZIMMERMAN, JV Assistant Director for Export/Import & International Safeguards ITAL-42895 84/08/09 2pp 26142 361
- 8408200189 Discusses 840807 application for license to export spare valve parts to South Korea License issued w/o normal i5-day waiting period ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 84/08/09 Assistant Director for Export/Import & International Safeguards ip 26142 292
- 8408200314 Forwards end use statement re export of remote control measuring device to Taluan 84/08/04 HEMBY.E NRC - No Detailed HiNKLE.F Teleflex Inc 84/08/04 HEMBY.E NRC - No Detailed Affiliation Given 2pp 26141 240
- 8408200450 License for California Instruments to export one Model 848FCM-3-4-1-2 oscillator & instruction manual to France ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 28326 84/08/14 ip 26144 327
- 8408200457 Application for license to export 503T ac power source & B30T~3 plug-in oscillator to France LANE,M California Instruments 28439 84/08/09 1p 26143 361
- 8408200485 Requests Executive Branch position re Westinghouse application for license to export 47,108 kg enriched U to France CIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 84/08/14 GTOIBER.C R State. Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs Ip 26143 329
- --8409200493 Application for license to export 1.743 kg U-235.contained in 47.108 kg U.to France
  HERSCK.K.M. Mestinghouse Electric Corp. MMH-932 84/08/02 ip 26143 330
- B40B200537 Application for license to export power source escillator & frequency changers to United Kingdom LANE. M California Instruments 28915 84/08/08 2pp 26143 289
- 8408200541 Application for license to export Model 850T-3-2467 plug-in oscillator & CCL4569B frequency changer to Austria LANE.M California Instruments 28380 84/08/08 2pp 26143 283
- 8408200543 Forwards application to export sirconium tubing to BAUMGARD, R W Cabot Corp 1127V 84/08/09 HEMBY, E A Director for Export/Import & International Safeguards ip 26143 275 Assistant
- --8408200566 Application for license to export zirconium tubing to BAUMOARD, R W Cabot Corp B4494-00 84/08/09 1p 26143 274
- 8408200596 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
  ZIMMERHAN.J V Assistant Director for Export/Import & International Safeguards 84/08/14 THORNE.C E Energy, Dept of 1p Safeguards 84/08/14 2614J 269
- 8408210084 Informs that polishing compound matls will be shipped to Iran.per recent telcon PICIOCCHI.J H Gerard Kluyskens Co , Inc 84/08/08 MOORE,N NRC No Detailed Affiliation Given 1p 26175 148
- 8408210164 Application for license to export 12 Type WX 33080 CO-SPN detectors to West Germany HEEFHER.W Westinghouse Electric Corp ZE 10627 84/08/10 ip 26195 222

- 8408210169 Application for license to export 51x Type WX 33080 CO-9PN detectors to West Germany HERTHER.W Destinghouse Electric Corp. ZE 10628 84/08/10 1p. 26.195 C21
- 8408220420 Amend 1 to Signa Chemical Co export license, extending expiration date from 840901 to 860901 ZIMMERMA: J V Assistant Director for Export/Import & International Safeguards D-96 84/08/16 Ip 26211 080
- B408220421 License for Westinghouse to export two WL-8073 fission chambers to France
  ZIMMERMAN.JV Assistant Director for Export/Import & International Safeguards Mim 533 84/08/20 ip 26211 082
- B408220422 License for California Instruments to export power source, oscillator / instruction manuals to France ZIMHERMAN. J V Assistant Director for Export/Import & International Safeguards 28046 B4/08/17 ip 26211081
- 8408220430 Requests Executive Branch Views on KMS Fusion, Inc application to export deuterium & trictium to France ZIMMERMAILJ V Assistant Director for Export/Import & International Safeguards 84/08/17 STOIGER.CR State, Dept of, Bureau of Oceans & Intl. Environ & Scientific Affairs ip 26209 246
- 8408230464 Application for amend to export license, adding Blayais 3 reactor to end use of SRM in original application DUBOIS, D European Concusties, Commission of 84/08/13 THORNE, C E Energy, Dept of 1p 26230 254
- 8408230468 Application for amend to export license requesting increase in max enrichment from 3 8% to 4 0% & providing intermediate consignee WILSON 8 D General Electric Co BDW-123-84 84/08/14 WRIGHT, B L Office of International Programs. Director 1p 20-20 250
- 8408230469 Application for license to export 121 8 kg U to France & 81 2 kg U to West Germany MCDDNDUGH.N D Energy, Dept of 84-63 84/08/06 7pp 26231 263
- B40B230473 Application for incense to export power systoscillator & other electrical equipment to Brazil
  LANE.H California Instruments 27733 84/03/01 2pp 26230 217
- 8408230495 Application for license to export inverters, converters, generator, power source & oscillators to Brazil
  LANE.M California Instruments 28131 84/03/29 2pp 26230 214
- 8408230488 Application for license to expart zirconium fuel tubes & end plugs & stainless steel springs to Belgium HERSCH.M M Westinghouse Electric Corp MMH-539 84/08/13 ip 26/20 213
- 8408230493 Application for license to export invertors, converters, frequency changers, generators & oscillator to Switzerland LANE,M California Instruments 27967 84/01/19 ip 26230 212
- 8408230498 Application for license to import 38,377 kg U as UF6, containing 1.344 kg U-235 from Belgium
  HERSCH.M M Westinghouse Electric Corp MMH-540 84/08/13
  MODRE.R N Assistant Director for Export/Import & International
  Bafeguards 2pp 26230 210
- 8408230500 Application for license to export inverters, converters, frequency changers, generators, power source & oscillator to France LANE, M California Instruments 28045 84/03/01 ip 26230 207
- 8408230505 Application for license to export 830T-4-2-4-1973 oscillator to United Kingdom LANE, M California Instruments 28542 84/08/13 2pp 26230 207
- 8408230510 Application for license to export 38,377 kg U.containing 1,344 kg U-235.to Belgium HERBCH. MM Westinghouse Electric Corp MMH-543 84/0B/15 ip 26230 206
- 8408230513 Application for amend to export license, requesting increase in max enrichment from 3 95% to 4 0% & amending 840503 request WILSON, B D General Electric Co BDW-122-84 84/08/14 WRIGHT, B L Office of International Programs, Director 1p

- 8408230516 Amend I to Amersham Corp import license, adding 2 micrograms Pu-236 authorized for inport from United Kingdom & extending expiration date from 840901 to 870901 ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 84/08/17 Ip 26230 204
- 8408230519 License for Brunswick Corp to export one NV 23-1 & one NV 23-2 check valve to Canada III/HERMAN.J V Assistant Director for Export/Import & International Safeguards NA2150 84/08/16 ip 26230 203
- B408230525 License for Transnuclear.Inc to export 4 879 kg U-235, contained in 10 747 kg U.to Switterland ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards NUX-441 86/08/15 2pp 26230 201
- 8408230530 License for Matheson Gas Products.Inc to export 90 g deuterium, to Japan ZIMHERMAN.J V Assistant Director for Export/Import & International Safeguards NSK-73184 84/08/17 ip 26230-200
- 8408230535 Amend 2 to Ransey Engineering Co export license.extending expiration date from 841001 to 871001 ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 84/08/17 ip 26230 179
- B408230560 Issues license to export frequency changers to France w/o customary 15-day waiting period
  ZIMMERMANU V Assistant Director for Export/Import & International Bafeguards 84/08/17 Assistant Director for Export/Import & International Safeguards 1p 26230 265
- 8408230362 Forwards application for export license to ship 623,939 kg U.containing 22.141 kg U-235,to Sweden HANNETT,B A Transnuclear, Inc TNH-433 84/08/16 MOORE,N Office of International Programs, Director 1p 26230 262
- --8408230563 Application for license to export 623,939 tg U.containing 22,141 kg U-235.to Sueden HANNET(.D A Transnuclear, Enc TNH-433 84/08/16 2pp
- 8408310001 Requests ltr of assurance be obtained re DDE application for license to export low enriched U fuel to Federal Republic of Germany ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/08/21 THORNE, C E Energy, Dept of 1p

26330 206

- --8408310005 Application for license to export 203 kg U metal to Federal Republic of Germany MCDDNOUGH.M D Energy, Dept of 84-63 84/08/06 7pp
- 8408310006 Requests 1tr of assurance be obtained re Westinghouse application for license to export 1,344 kg U-235, contained in 38,37 kg U-6. to Belgium
  ZIMMERHAN, J V Assistant Director for Export/Import & International Sareguards 84/08/20 THORNE, C E Energy, Dept of 2pp 26350 200
- B40B310019 Forwards Dupont NEN Products application for export license for nihor nuclear export Ltr of assurance required ZIMMERMAN, J V Assistant Director for Export/Import & International Bafeguards B4/0B/24 STOIBER, C R Energy, Dept of 1p 26350 190
- --8408310025 Application for license to export tritium gas net 092 in breakseal tubes to Chile DUMAS.D El du Pont de Nemours & Co., Inc. 84/08/08 ip 26350 191
- 8408310178 License for Thorn EMI Gencom, Inc to import 30 mg Pu-238 from United Kingdom ZIMMERMAN.J V Assistant Director for Expert/Import & International Safeguards 84/08/24 ip 26351 339
- 8408310180 Application for license to export inverters, converters, frequency changers & generators to Switzerland HALUB,P Elgar Corp 17176 84/08/21 1p 26352 041
- 8408310303 Application for license to export K-3 gas in breakseal tube to Australia DUMAS,D E I dw Pont de Nemours & Co , Inc 84/08/08 ip 24350 300

#### NONDOCKETED ITEMS

- 8408310307 Application to amend export license, extending expiration date until 870831 % increasing amount to 100 kg
  880MN,L R Ediow International Co. 84/08/21 WRIGHT, 8 Assistant Director for Export/Import & International Safeguards ip 26350 501
- 8408310310 Application for license to export 42 tubes.made from Zirconia.to Canada AERRI, B L Teledyne Gentech 1107 (RFH) 84/08/15 ip 24350 306
- B40B310317 Requests Executive Branch position re Transnuclear,Inc application for license to export 22,141 170 kg U-239,in form of UF6 to Sweden ZIMMERMAN,J V Assistant Director for Export/Import 3 International Safeguards B4/08/21 THORNE,C E Energy, Dept of 19 24350 302
- --B408310321 Application for license to export 22.141 170 kg U-235, in form of UF6, to Sweden HANNETT. B A Transnuclear, Inc. TNH-453 84/08/16 2pp
- --8409310325 Forwards application to export 22:141 (70 kg U-235 to Sweden HANNETI.B a Transnuclear, Inc TMH-453 84/08/16 MOORE,N Assistant Director for Export/Import & International Safeguards 1p 26390 305

- 8408310336 License for Telefley, Inc to export 1 cable,mechanical,follow core hell: wrapped P.N 22695-164-9 & 3 slip ring assemblies P.N 80095-1 fo Tailant ZIMMEMHU, J. Assistant Director for Export/Import & International Safeguards 019110 84/08/21 ip 26350 312
- B40B310337 Application for license to export Pu-239 in Model CS-1 alpha check source Pu-239 % Model S94-4 alpha callbr std set, to Republic of Korea
  EBPIND5A:6 Eberline Instrument Corp 50 ND 809B04 B4/08/14 1p 26350 311
- 8408310341 License for DDE to export 2 kg Pu & 12 kg depleted U to Japan ZIMMERMAN J V Assistant Director for Export/Import & International Safeguaris 83-74 84/08/21 2pp 26350 309
- 8408310146 Application for license to export 24 Ci tritium gas.in glass break seal ampoulo, to Japan DUMAS.D E I du Pont de Nemours \* Co , Inc 84/08/08 1p 26350 131

ï

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	CATEGORY
AARI AND I D	B408140433*	50-313 P	ANDERSON, R N	8408020129	50-322 T	AXELRAD, J A	8408150540*	50-329
AADLAND, J D ABELSON, H I	B408010140	50-313 P	ANDERBON R N	8408140017*	50-322 T	AXELRAD, J A	8408230070	50-277
ADELSON, H I	8408150409	50-333 P	ANDREWS, R L	8408060289	50-285 6	AXELRAD, J A	8408240104	50-289
	840827 <b>0</b> 290*	50~219 P	ANDREWS, R L	B408070128	50-285 P	AXELRAD, J A	8408240108	50-387
ABRAMOVICI, J D ADAMS, F T	8408270270*	50-261 P	ANDREWS, R L	8408090401	50-285 S	AXELRAD, J A	B408240343	50-331
Whyle I	0400630122*	20-EDI P		· · · · · ·	_	•		
ADENSAM, E G	8202040352*	50-329 A	ANDREWS R L	8409090405	50-2B5 S	AXELRAD, M	8408310247 8408020020	50-275 50-315
ADENBAM, E G	8205120033*	50-329 A	ANDREWS, R L	E408100104	50-285 P	AXELSON, W L	8408020052	331
ADENBAH, E G	8206270161*	50-329 A	ANDREWS, R L	8408150136	71-256	AXELSON, H L	8408060024	50-341
ADENSAM, E G	8210150698*	50-329 A	ANDREWS R L	8408200589	50-285 R	AXELSON, W L AXELSON, W L	8408070050	50-315
ADENSAM.E G	8408130177#	50-413 P	ANDREWS, R L	8408240230	50~285 g	MARCIONIA	8400078030	_
ADENSAM, E G	8408130230*	50-329 A	ANDREHS, R L	8408270244	50-285 P	AXELSON, H L	8408070329	18E 50-331
ADENSAM, E G	8408300385	50-328 P	ANDREWS, R L	8408280288	50-285 8	AXELSON: W L	8408070464	
ADENSAM, E Q	8409300387*	90-328 P	ANDREHB,R L	8408280343	50-285 S	AXELSON, H L	8408100029	50-282
ADENBAM, E G	8408310448	50-424 E	L M. BURDNA	8408270361	40-4492	AXELSON, W L	8408130153	50-341 70~2872
AERNI,8 L	B40B310310	XPORTLIC	ANDRUS, N J	640831 <b>0</b> 338	40-4492	AXELSON, W L	8408130180	/U~28/2
AFIFI.S S	8408140076*	50-329 A	B,YNDHTMA	8408130210*	50-416 U	AXELSON, W L	8408130370	50-155 ,
AKI, K	8408210044#	50-206 P	ANTHONY, R L	8408080191	50-352 G	AXELSON, W L	6408170198	50-266
ALARCON, E	8408080168*	50-445 Q	ANTHONY, R L	8408080191	50-352 G	AXELSON, W L	8408200230	50-373
ALBRIGHT, R H	8408280289*	70-1201	ANTHONY, R L	8408090263*	50~352 G	AXELSON, W L	8409200248	50~254 <b>,</b>
ALBRIGHT, R H	8408300206#	70-824	ANTHONY, R L	8408280491	50~352 Q	AXELSON, W L	B40B200281	50-10 .
ALDRICH, L R	8408040227	50-374 S	ANTHONY, R L	8408280491	50-352 0	AXELSON, W L	8409200319	50-255 ,
ALDRICH L R	8408090324	50-373 8	ANTHONY, R L	8409310076	50-352 G	AXELSON, W L	8408200345	50-295 ,
ALESIO, W G	84080B0144	40-8691	ANTHONY, R L	8408310096	50-352 6	AXELSON, W L	8408210470	50~461 t
ALEXANDER, G	8408160415	50-454 A	ARAND, J	8408040255	50~373 B	AXELSON.W L	8408210491	70-2838
ALEXANDER, G L	8408150098	50-237 Q	ARCHER, G D	8408310262*	CONTRACT	AZARMI H. A	8409220333	50~352
•							DAGGOGGET	NUREO
ALEXANDER G L	8408200331	50-237 Q	ARMBRUST, A J	8408060026	27-39	BARS, R E	8408080357 8408090552	PROJ
ALEXANDER G L	8408270087	50-275 G	ARNOLD, K D	8408060197*	50-70 G	DAATIH	8408040352	CONTRACT
ALEXANDER, G L	8408270114	50-237 P	ARNOLD W D	B408300282	NUREG	BABBITT, D L		NUREO
ALEXANDER G L	8408280119	50-295 P	ASARS_A	8408100035	50-29 S 50-317 B	BABCOCK, C D BACANSKAS, V P	8408100153 8404040079*	50~369 I
ALEXICH, M P	8408060076	90-315 P	ASHE, F	8408310345	20-317 8	I'ACANONADI V P	D404040078#	
ALEXICH M P	8408060118	50~315 F	ASHE, F	8408310370*	50-317 S	BACHMANN R G	8408270186*	50-445
ALEXICH M P	6408060348	50−315 F	ASSELSTINE, J K	8408130 <b>33</b> 3*	50~382 G	BAER.R L	B40B140461	50-27
ALEXICH M P	8408080084	50-315 G	ASSELSTINE, J K	8408200225	50-369 U	BAER, R L	B40B150466	I&E
ALEXICH M P	8408100074	50-315 F	ASTLEY, E R	B408010142	XPORTL IC	BAER, R L	B40B160515*	50-458 (
ALEXICH M P	8408140164	50~315 P	AU, T Y	8408140131	50-289 G	BAGBY, L A	8408080532	XPORTLIC
ALEXICH M P	8408140188	50-315 P	AUGUST, B K	8408040179	50-352 0	BAILEY, M W	8408130456	50-304
ALEXICH, M P	8408170322	50-315 F	AUSMUS, B B	8408020070*	50-133 P	BAILEY, R J	8408030192*	50~410 (
ALEXICH M P	8408240121	50-314 P	AUSTIN. G	8408140122	50-295 R	BAILEY.R J	8408060352	50-277 r
ALEXICH M P	8408240188	50~315 P	AUSTIN, M A	8408010020	70-364	BAILEY, R J	8408150424*	50-277
ALLEN, J A	8408210361*	50-382 A	AUSTIN, M A	8408150657	70-364	BAILEY, R J	8408150721*	50~317 c
ALLEN, H H	8408080498	50-219 S	AUSTIN, P N	8408290190	NUREG	BAILEYS, T P	8408090439	50-387
ALZHE IMER, J M	8408060405	50-206 S	AUSTIN P N	8408290198	NUREO	BAIR. A	8408130276	71-184
ANAND, R	8408060325*	50-382 0	AWTREY, P H	8408210093	71-39	BAIR, A	#£650£18048	71-184
ANDERSON, C D	8408300108*	50-10 G	AXELRAD, J	8407110250	I&E	BAIR. G G	8408280147	50-344
ANDERSON, C J	8408080256*	50-289 Q	AXELRAD, J	8408010162	50-368 Q	BAISDEN, L.	8408070080	CONTRACT
ANDERSON, C J	B40807 <b>0</b> 330#	50-322 g	AXELRAD, J	B408010164	50-280 G	BAKER, E	8408240140*	QA999
ANDERSON, C J	B408150110*	50~336 G	AXELRAD: J	8408010251	I&E	BAKER, K R	8408040151	50-316
ANDERSON, C J	B40B160246*	50-245 G	AXELRAD, J	8408210407	I&E	BAKER K R	8408160127	50-316
ANDERSON, C J	8408200504*	50-354 Q	AXELRAD, J	8408240357	1&E	DAKER, K R	8408220486	50-315
ANDERSON, C J	8408210501*	50~245 G	AXELRAD, J	8408280068	186	BAKER R H	8408090016*	CONTRACT
ANDERBON, D. L.	8408090100	50-445 T	AXELRAD, J	8408280073	I&E	DAKER, W E	8408100153	NUREG :
ANDERSON F D	8408130011	50-413 P	AXELRAD, J	8408270120	186	BAKSHIA	8408020129	20-325
ANDERSON, J	8408140352*	50~329 A	AXELRAD, J	B408300144	50-261 Q	BALL, D G	8408080415	NUREG
ANDERSON, J. J.	8408010317	50-286 8	AXELRAD, J A	B40B130257	70-143	BALL, B J	8408130001	NUREO
ANDERSON, J J	B408240048	50-286 8	AXELRAD, J A	8408130431	50-275 G	BALLARD, R L	8309270366*	50-329
		_						

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR
BALLINGER, P L BANDHAUER, W K BANDHAUER, W K BANDHAUER, W K BANDHAUER, W K	B408240072 B408060306 B408160247 B408200346 B408230424	50-298 S 50-302 S 50-302 S 50-302 S 50-302 S	BAUSER, M A BAUSER, M A BAUSER, M A BAUSER, M A BAUSER, M A	8409140253* 6409140253* 6409140271* 6408140271* 6408140277*	50-250 G 50-250 G 50-250 G 50-250 G 50-250 G	HERNABEI, L GCRNABEI, L BERNABEI, L BERNABEI, L BERNABEI, L	84080602244 8408060201 8408060201 8408060224# 8408070408	50-287 9 50-287 9 50-287 9 50-287 9
BANDHAUER, W K BANDY, R BANGART, R L BANGART, R L BANGART, R L	8408230430 8408070014 840818042 840818050 840818083	50-302 S NUREG 50-445 Q 50-445 A 50-445 A	BAUSER, M A DAUSER, M A BAXTER, T A BAXTER, T A DAYLESS, R S	8408140277* 8408140277* 8408140014 8408140014 8407100420	50-250 0 50-250 0 50-400 T 50-400 T 50-263 8	BERNABEI, L BERNABEI, L BERNABEI, L DERNABEI, L BERNABEI, L	8408070108 8408140479 8408140479 8408220298 8408220298	50-289 9 50-289 9 50-289 9 50-289 9
DANGART, R L BANGART, R L BANGART, R L BANGART, R L BANGART, R L	8408150091 8408150414 8408150649 8408160026 8408160201	50-445 Q 50-445 Q 50-445 Q 50-445 Q 50-445 Q	DAYNARD, PY DAYNARD, PY DAYNE, JP DAYNE, JP DAYNE, JP	8408240155 8408270211* 8408010319 8408010321* 8408070364	50-302 F 50-302 G 50-333 P 50-333 P 50-333 P	BERNABEI, L BERNABEI, L BERNABEI, L BERNABEI, L BERNABEI, L	8408220263* 8408270263* 8408270366 8408220366 8408240251	50-287 9 50-287 9 50-287 9 50-287 9
BANGART:R L BANGART:R L DANGART:R L BANKB:H R, BARANOWSKY:P W	8408140485 8408210148 8408230147 8408140151# 8407170313	50-445 G 50-445 F 50-445 G 50-400 T NUREG	DAYNE, JP DAYNE, JP DAYNE, JP DAYNE, JP	8408070417 8408070423* 8408100087 8408130309 8408180147	50-333 P 50-333 P 50-333 F 50-286 F 71-240	DERNABEI, L DERNABEI, L BERNABEI, L BERNABEI, L BERNABEI, L	8408240251 8408310106 8408310106 8408310106 8408070382	50-287 G 50-282 G 50-382 G 50-387 G
BARANOWSKY.P W BARBDUA.J C BARHAM.C D. BARI.R A BARKHURST.R P	8407170316* 8408280205 8408210027 8408280333 8408210361*	NUREG 50-413 T 50-400 J 50-352 A 50-382 A	BAYNE, J P BAYNE, J P BAYNE, J P BAYNE, J P DAYNE, J P	8408150230 8408170277 8408210436* 8408210443 8408210447*	50-286 F 50-286 P 50-333 Q 50-286 P 50-286 P	BERNABEI, L BERNHOFT, S BERNHOFT, S BERNTHAL, F BERNTHAL, F M	8408070332 8408060244 8408980510 8408200496 8408270356	50-287 <b>Q</b> 50-305 9 50-305 9 50-348 M COMMISSION
BARLETTA, R E BARLON, G BARLON, G BARLON, G BARLON, G	8408010151 8408060183 8408060191* 8408060197* 8408060206*	NUREG 50-70 G 50-70 G 50-70 G 50-70 G	BAYNE, J P BAYNE, J P BAYNE, J P BAYNE, J P BEACH, A D	8408220224 8408230164 8408240145 8408310095 8408170117*	50-333 P 50-286 F 50-333 P 50-333 P 50-443 Q	HERRY, D L HERRY, J A HESS, J HESS, J E	8408240320 8408080466* 8408220307 8408150515* 8408270108*	NUREG 50-245 0 50-269 0 50-362 0 50-458 0
DARNES, I BARNES, I BARNES, I BARNES, L BARR, S	8408010372* 8408070130* 8408230013* 8408080027 8408230527	GA999 50-313 G 50-298 G 50-445 T 50-269 P	BEACH, A B BEACH, A B BEACH, D L BEACH, G BEAGLEY, D	8408170117* 8408170117* 8408310165* 8408240374 8408200288*	50-443 Q 50-443 Q 50-255 Q WASTE MGT 50-528 S	BETHUNE, E BETTENHAUSEN, L BETTENHAUSEN, L BETTENHAUSEN, L BETTENHAUSEN, L	8408070215* 8408080461* 8408080476* 8408080470* 8408080530*	50-415 U 50-220 U 50-222 U 50-252 U
BARRETT, L H BARRETT, L H BARRETT, L H BARRETT, L H BARTH, C A	8408070134 8408230036 8408230067 8408240378 8408090170	WASTE MOT WASTE MOT WASTE MOT WASTE MOT 50-400 G	BEATTY,0 P BEATTY,0 P BEAVER.J BEAVER.J R BECK.O P	8408030234 8408140151* 8408300031 8408140197 8408030276	50-261 P 50-400 T 50-320 P 50-320 F 50-151 F	BETTENHAUSEN, L GETTENHAUSEN, L GETAN, R GEVAN, R GEVAN, R GEVAN, R	8408130410* 8408160115* 8408160432* 8408060425 8408150588	50-287 0 50-287 0 50-249 0 50-237 P 50-254 P
DARTH,C A DARTH,C A BARTH,C A BARTHOLOMEN,R BARTLETT,D	8408070224 8408140064 8408280437 8408070282* 8408140163*	50-400 G 50-400 T 50-400 G 50-305 F 50-329 A	DECK. Q P BECKER, B D BECKER, B D BECKHAN, D BECKHAN, J T	8408300184 8405250241 8405250241 8408150431 8408100045	50-151 S 50-454 O 50-454 G 50-483 O 50-366 P	GEVILL, M BEYEA, J BIBB. H E BICEHOUSE, H J	8408010025 8408310157* 8408310239* 8408270363* 8408230136*	71-9163 50-289 P 50-289 P 50-335 Q 50-277 Q
BARZANO,W J BARZANO,W J BARZANO,W J BASKIN,K P BASKIN,K P.	8408070311 8408130329 8408130337* 8408070187 8408070194*	40-2061 40-2061 40-2061 50-361 P 50-361 P	BECKHAM, J T BECKHAM, J T BEHREMB, P A BELANGER, J L BELCHER, R L	8408130561 8408140106 8408300308* 8408100037* 8408220172	50-321 P 50-321 P 50-254 R 50-262 Q 50-164 R	31DINGER, G H 31GGS, C 31RCH, M L 31RD, N 31SHOP, E	8408270338 8408080297 8498270169* 8408150408* 8408210268*	50-458 A 50-445 1 50-267 P 50-329 A 50-331 I
BABKIN,K P BATEMAN,W H DATES,J Q BATES,J W BATES,J W	8408130203 8408200366* 8408030066* 8408270427* 840826011*	90-204 G 50-354 G 50-327 A 70-143 70-27	DELISLE.Q.A BELISLE.Q A BELL.J BELL.J BELL.J	8408270221* 8408270472* 8408150515* 8408200023* 8408160055	50-335 Q 50-413 Q 50-382 Q 50-289 Q WASTE MOT	318HOP, T W 318HOP, T W 318HOP, T W 318HOP, T W 018HOP, T W	8408010278 8408030242 8408070324 8408070531 8408070532*	50-344 0 50-344 0 50-275 0 50-275 P
BATEB.J W BATSEL.J BAUBLITZ.J E BAUDLITZ.J E BAUM,A	8409310255* 8409060197* 8409160289 8409220232 8409300237*	70-1151 50-70 0 WASTE MOT WASTE MOT 50-289 P	DELL.N DELLAMY.R DELLAMY.R R DELTER.L H BELTER.L W	8408140417 8408030209 8408030234 8408220331 8408220331	NUREO 50-333 G 50-272 G 50-445 G 50-445 G	BISHOP, T W BISHOP, T W BISHOP, T W BISHOP, T W BISHOP, T W	8408080491 8408080494 8408090014 8408090043 8408200313	50~275 q 50~344 q 50~397 q 50~361 q 50~275 q
BAUMGARD, R W BAUMGARD, R W BAUNACK, W BAUNACK, W BAUSER, D D	8408200563 8408200566* 8408150271* 8408210381* 8408080217	XPORTLIC XPORTLIC 50-287 0 50-352 0 50-400 0	BELTER, L W BELTER, L W BELTER, L W BEMIS, P BEMIS, P R	8408220336 8408270154 8408270154 8408270572* 8408140070*	50-445 G 50-445 G 50-445 G 50-395 G 50-400 T	BISHOP, T W BISHOP, T W BISHOP, T W BISHOP, T W BISHOP, T W	8408220051 8408270325 8408270349 8408270168 8408300094	50-528 Q 50-206 P 50-206 G 50-397 G 50-528 Q
BAUSER.D B BAUSER.D B BAUSER.D B BAUSER.D B BAUSER.D B	8408080217 8408130300 8408130300 8408200448 8408200448	50-400 G 50-287 G 50-287 G 50-289 G 50-289 G	DEMIS, PR BEMIS, PR. DEMIS, PR. DEMIS, PR. DENDER, M BENDER, M	84081400B1* 84081400B4* 8408270536* 8408020213	50-400 T 50-400 T 50-261 G ACRS ACRS	BISHOP,T W BISHOP,T W BISHOP,T W BISHOP,T W BISHOP,T W	8408300110 8408300140 8408300187 8408300248 8408300373	50-312 q 50-275 q 50-528 q 50-312 q 50-344 q
BAUSER, D B BAUSER, D B BAUSER, D B BAUSER, D B BAUSER, D B	8408200515 8408200515 8408270115 8408270115 8408310207	50-289	BENDER, M BENDER, M BENNETT, J O BENNETT, J P	8408020244 8408020244 8408100155 8408100153 8408130402	ACRE ACRE NUREG NUREG PR	DISHOP,T W DISHOP,T W DISSETT,P DISSETT,P DITTNER,R	8408300393 8408300446 8408080166* 8408070330* 8408070364*	50~528 q 50~397 q 50~387 q 50~322 q PROJ
DAUBER, D B BAUSER, M A BAUSER, M A BAUSER, M A	8408310207 8408070453 8408140214 8408140214 8408140220*	50-289	BENNETT, J W BERG, R E BERGAN, Q W DERGAN, Q W DERGER, D	8408220122 8408270028 8408040100 8408200519 8408310238	WASTE MOT 40-8585 50-237 8 50-249 8 50-289 P	BLACK,K M BLACKFORD,M BLAKE,E L BLAKE,E L BLAKE,E L	8408040200* 8408220147 8408020042 8408020042 8408150458	50-416 S WASTE MOY 50-269 O 50-269 O 50-269 O
BAUSER, M A BAUSER, M A BAUSER, M A BAUSER, M A BAUBER, M A	8408140220* 8408140236* 8408140236* 8408140236* 8408140253*	50-250	BERGER, J D BERKOVITZ, D M BERLINGER, C H BERMAN, M BERMAN, M	8408020225* 8408150686* 8408280109 8408190152 8408130006	70-8 50-327 A 50-206 G NUREG NUREG	BLAKE,E L Blake,e L Blake,u J Blake,u J Blake,u J	8408200557 8408200557 8408140081* 8408240342* 8408240346*	50-289 d 50-289 d 50-400 t 50-299 d 50-321 d

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BLAKE, J J BLAKE, J J BLAKE, J J BLAKE, J J	8408270240* 8408270275* 8408270388* 8408270469* 8408280046*	50-438 Q 50-417 G 50-338 Q 50-370 Q 50-261 Q	BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B M	8408010254 8408070375 8408070161 8408070210 8408150070	50-322 0 50-322 0 50-322 0 50-322 0 50-322 0	BROWN, E M BROWN, J E BROWN, J E BROWN, L R BROWN, N D	8408020187* 8408220393* 8408220393* 8408220397 8408280179	50-327 0 50-445 T 50-445 T XPORTLIC 50-289 F
BLAKE, J J BLAKE, J J BLAKE, R BLANCHARD, B	8408280091* 8408280393* 8408290039* 8408280203* 8408210213	50~400 Q 50~413 Q 50~261 Q 50~412 E 50~354 D	BORDINE, T C BORDINE, T C BORDINE, T C BOREN, A BOSKEY, B	8408270127 8408270130 8408280003* 8408080245 8408080197	50-255 S 50-255 S 50-255 G 50-445 T 50-348 M	BROWN, S R BROWN, W B BROWN, W B BROWN, W B	8408240382 8408080324 8408080386 8408080391 8408080393	NUREQ 70-371 70-1151 70-734 70-143
BLAND.J 8 BLANKLEY,W 8 BLATT.M BLEUEL,W H	8408070462* 8408030175 8408200539 8408220214 8408170321*	PRM GA999 50-247 8 50-247 9 50-454 T	BOSKEY, B BOSKEY, B BOSKEY, B BOSKEY, B	8408080197 8408080202 8408080202 8408080241 8408080241	50-348 M 50-348 M 50-348 M 50-348 M 50-348 M	BROWN, W B BROWN, W B BROWN, W B BROWN, W L BROWNING, R E	8408080425 8408080435 8408160064 8408240375 8408010043	70-734 70-1257 70-1151 40-8829 WASTE MGT
BLIND, A A BLOCH, P B BLOCH, P B BLOUGH, A R BLUBAUGH, R E	8408130307 8408280255 8408280391 8408150244* 8408240054	50-314 B 50-445 Q 50-155 Q 50-277 Q 40-3453	BOSTED, C BOULAY, R J BOURASSA, L BOWERS, H BOYD, D C	8408300195* 8408210477 8408310154 8408310035* 8408010402*	50-528 Q State Prog PR 50-275 P 50-263 Q	IROWNING, R E BROWNING, R E BROWNLEE, V L BROWNLEE, V. L	8408040163 8408150337 8408150568 8408140324 8408230001	WASTE MOT WASTE MOT WASTE MOT 50-370 S 50-370 S
BLUHM,R B BLUMBERG,N BLUMBERG,N BLUME,M BLUMENTHAL,A	8408200334* 8408080478* 8408160115* 8408020177* 8408280093	50-528 F 50-322 G 50-317 G 50-327 G PR	BOYD, D C BOYD, D C BOYER, R E BOYER, V S	8408030179* 8408230238* 8408230497* 8408230229 8408020075*	50-155 Q 50-409 Q 50-263 Q GA979 50-352 A	BROWNLEE, V L	8408240270 8408240327 8408240421* 8408270277* 8408260158	50-370 S 50-369 S 50-269 G 50-369 G 50-369 B
BOARDMAN, J R BOARDMAN, J R BOARDMAN, J R BOCCIO, J L BOGDEN, O	8408150375* 8408220256* 8408270500* 8408220333 8408270038	50-313 G 50-382 G 50-298 G* 50-352 A 40-8684	BOYER, V S BOYER, V S BOYLE, L A BOYLE, M L	8408070433* 8408070450* 8408210389 8408210071 8408210573	50-352	BRUCIAK, J D BRUCIAK, J D BRUGGER, R M BRUNNER, J E BRUNNER, J E	8408050042 8408230533 8408220337 8408140573* 8408150577*	50-374 8 50-374 8 PR 50-327 A 50-329 A
BOODEN, O BOGOS, R S BOLANDER, M A BOLSTAD, J, W BOMBERGER, C	8408270131 8408060231* 8408160248 8408160146 8407300136*	40-1142 50-328 P 50-249 P NUREG 50-213 P	BRADBURY, J W BRADFORD, L BRADLEY, E J BRADLEY, E J BRADLEY, E J	8408280005 8408140010 8408020058 8408070033 8408210076	WASTE MGT 50-289 G 50-352 A 50-352 A 50-352 K	BRUNNER, J E BRUND, G E BRYAN, D C BRYANT, J BRYSDN, M C	8408150586* 8408140273 8408150135 8408240421* 8408240249	50-329 A 50-275 D XPORTLIC 50-249 G NUREG
BOMBEROER, C R BONNIES, O BOOKER, J E BOOKER, J E BOOKER, J E	8408280321* 8408270574* 8408010004 8408010012 8408010241	50-346 P CONTRACT 50-458 S 50-458 S 50-458 G	BRADLEY,E J BRADLEY,E J BRANCH,E B BRANCH,E B	8408280272 8408280273* 8408080044* 8408310194* 8408160486	50-278 P 50-278 P CONTRACT 50-454 T 50-354 D	BUCHANAN, J K BUCKALEY, M H BUCKLEY, B BUCKLEY, B, BUCKLEY, J T	8408310194* 8408080347 8408090473 8408230364 8408240119	50-454 T NUREG 50-400 F 50-400 A WASTE MANA
BOOKER, J E BOOKER, J E BOOKER, J E BOOKER, J E	8408020025 8408040028 8408060147 8408070520 8408070529	50-458 9 50-458 A 50-458 E 50-458 9 50-458 9	BRANDENBURG, B BRANDENBURG, B BRANDON, R J BREDEE, N	8408140493 8408170270 8408170262* 8408270175* 8408020002	50-247	BURDOIN, J F. BURDOIN, J F BURGER, F J BURGESS, B L BURKE, D J	8408080513* 8408300133* 8408270152 8408170266* 8408270456*	50-275 G 50-312 G 50-271 R 50-329 F 50-280 G
BOOKER, J E BOOKER, J E BOOKER, J E BOOKER, J E	8408080199 8408080234 8408080471 8408100048 8408100108	50-458 9 50-458 9 50-458 9 50-458 0 50-458 0	BREEN, W BRENNEMAN, F BRENNER, L BRENNER, L BRENNER, L	8408130405 8408310041 8408030085 8408070490 8408150142	50~304 S 1&E 50-322 G 50-322 G 50-322 G	T 9.TT3NRUB L C.ENRUB C.ENRUB S.ENRUB G.ENRUB G.ENRUB	8408280049* 8309220342* 8408280400* 8408070273 8408150062	50-390 Q 50-295 P 50-295 P 50-445 T 40-2061
BOOKER'N E BOOKER'N E BOOKER'N E BOOKER'N E	8408140340 8408140421 8408140554 8408150152 8408150162	50-458 E 50-458 A 50-458 S 50-458 S 50-458 S	BRENNER: L BRENNER: L BRENNER: L BRENNER: L BRENNER: L	8408150155 8408150183 8408170305 8408170332 8408220342	50-322 0 50-352 0 50-352 0 50-322 0	BURRELL, N K BURWELL, S B BURWELL, S B BURWELL, S B BURWELL, S B	8408150476* 8408060155 8408070435 8408070451 8408160501	50-322 T 50-445 A 50-445 Q 50-445 F 50-445 T
BOOKER, J E, BOOKER, J E, BOOKER, J E BOOKER, J E BOOKER, J E	8408150177 8409150308 8408150385 8408150491 8408150704	50-458 8 50-458 8 50-458 8 50-458 8 50-458 8	BRENNER, L BRENNER, L BRENNER, L BRENNER, L BRICH, R F	8408230200 8408270364 8408280162 8408300168 8408240371	50-352 0 50-322 0 50-352 0 50-352 0 40-1341	BURWELL, 8 B BURWELL, 6 B BURWELL, 6 B BUBCHBOM, R L BUSH, K J	8408200156 8408210561 8408270565 8408310075 8408310335*	50-445 A 50-445 G 50-445 A NUREG WASTE MOT
BOOKER, JE BOOKER, JE BOOKER, JE BOOKER, JE	8408150707 8408160194 8408160242 8408160386 8408210490	50-458 8 50-458 8 50-458 8 50-458 A 50-458 A	RICH, F D, HOUBENBAURE D, L, ITAGENB D, L, ITAGENB D, L, ITAGENB	8409270056 8409020127 8408130341 8408210388 8408210388	40-1341 50-322 T 50-322 G 50-322 G 50-322 G	BUSH, K J BUSH, M W BUTCHER, E BUTCHER, R. G BUTCHER, R. C	B408310339* B408220379 B408300219* B408230040 B408310114*	WASTE MOT 50-352
BOOKER, JE BOOKER, JE BOOKER, JE BOOKER, JE BOOKER, JE	8408220304 8408220305 8408220311 8408230338 8408240310	50-458 8 50-458 8 50-458 8 50-458 8 50-458 6	BRIGOS, L E BRIGHT, Q O BRINKMAN, D S BRITT, R W BRITT, R W	8408080530* 8408070293 8408270559 8408020155* 8408060127	50~352 Q 50~400 G TOPREP 50~266 F 50~266 P	BUTLER, D BUTLER, D BUTLER, D BUTLER, S D BYRD, R W	8408230252* 8408270277* 8408150722 8408270382* 8408040030	50-454 Q 50-454 Q XPORTLIC 50-327 Q 50-416 B
BOOKER, JE BOOKER, JE BOOKER, JE BOOKER, JE BOOKER, JE	8408240404 8408240426 8408280408 8408280414 8408280416	50-458 S 50-458 C 50-458 S 50-458 S 50-458 S	BRITTIR W BRITTIR W BRITTIR W BROCKIB L BROCKIB L	8408070030 8408070245 8408070328 8408080151* 8408090122*	50~266 P 50~266 P 50~266 P 70~734 70~784	BYRD.R W BYRD.R W. BYRD.R W. BYRD.R W. BYRD.R W	8408060193* 8408080538 8408160175 8408240210 8408300490	50-416 8 50-416 8 50-416 8 50-416 8 50-416 8
BOOKER, J E BOOKER, J E BOOKER, J E BOOKER, J E BOOKER, J E	8408280428 8408280446 8408280458 8408300343 8408300494	50-458 8 50-458 9 50-458 8 50-458 8 50-458 8	BROCK, B L BROMBERG, B BROMBERG, B J BRONS, J C BRONS, J C	8408130511* 840824089 8408080476 8408010317 8408230428	70-1257 CONTRACT CONTRACT 50-286 8 50-286 R	CABELL, A B CAHILL, W J, CAIN, J M CAIN, J M CALABRESE, R V.	8408130027* 8408140075* 8408020033 8408140284 8408130225*	71-83 50-458 Q 50-382 A 50-382 A 50-287 P
BOOKER, JE BOOKER, JE BOOKER, JE. BOOTH, DW	8408300507 8408310087 8408310172 8408150608* 8408240242*	50-458 8 50-458 8 50-458 E 50-329 A 50-413 I	BRONS, J C BROOKS, D J BROOKS, P P BROWN, C H	8408240048 8408310177 8408200470 8408280031 8408230149*	50-286 8 50-286 9 WABTE MOT WASTE MANA 50-407 9	CALDHELL.J L CALDHELL.J L CALDHELL.R A CALDHELL.R A CALLAHAN.J P.	8408200271* 8408270347* 8408230152* 8408230464* 8408220238	50-416 G 50-416 G 50-445 G 50-285 G WARTE MOT

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCE851ON NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CALSOYAS, C D CALSOYAS, C D CAMPBELL, B CAMPBELL, P L CAMPBELL, P L	8408310138 8408310149 8408220343 8408080512 8408240077	50-275 P 50-344 P PR 50-348 S 50-348 S	CHAPMAN, D N CHARAK, I CHARAK, I CHARNLEY, J S CHARNLEY, J S	8408080146 8408170152* 8408170157* 8312020279* 8408150084	50-329 G	CHRIBTMAN, W T CHRIBTNOT, E CHRIBTNOT, E CHRIBTNOT, E CHRIBTNOT, E CHRIBTNOT, E F	8408090417 8408280227* 8408270277* 84083702176* 8408070217*	50-322 G 50-454 G 50-454 G 50-440 G 50-454 G
CAMPBELL,R M CANNON,J A CANTRELL,F CANTRELL,F S CANTRELL,F S	8408270242+ 8408140292+ 8408270187+ 8408230040 8408230240+	50-410 G ORG 50-375 G 50-259 S 50-259 G	CHARNLEY, 5 K CHAUDHARY, 5 K CHEH. U CHEH. E	8408240122 8408210381# 8408240253# 8408200504# 8408290158	50-410 Q	CHRIBTOFFER.G CHRIBTOFFER.G CHRIBTOPHER.T CHU.H 8. CHUNG.D H	8408150394 <b>+</b> 840815044 <b>+</b> 8408030037 8408240284 8408240265	50-454 Q 50-341 Q QA999 WASTE MANA WASTE MANA
CANTRELL,F S CAPAND-DOLAN,L CAPSTICK,R W CAREY,J J	8408270572* 8408310114* 8408230387 8408310279 8408130436	50-395 0 50-259 0 PR 50-271 H 50-334 P	CHERONES, W J CHERDYES, W J CHERDYES, W J CHERONES, W J	8408150485* 8408280205 8408060231* 8408150250* 8408150642	50-322 T 50-413 T 50-328 P XPORTLIC XPORTLIC	CHURCHILL.B M CHUNG: D H CHUNG: D H CHUNG: D H	8408240275 8408240388 8408130410* 8408130417* 8408070437	WASTE MANA WASTE MOT 50-289 Q 50-289 Q 50-289 Q
CAREY, J J CAREY, J J CAREY, J J CARNEY, W	8408130439* 8408150499 8408230299 8408270341* 8408070217*	50-334 P 50-334 P 50-334 Q 50-334 Q 50-322 H	CHILK, B J CHEVERTON, R D CHEVER, L CHEUNG, L	8408070330* 8408200504* 8408080415 8408010340* 8404250171*	50-322 Q 50-354 Q NUREQ 50-335 H PR	CHURCHILL,B W CHURCHILL,B W CHURCHILL,B W CHURCHILL,B W CHURCHILL,B W	8408070437 8408230272 8408230272 8408280219 8408280219	50-287 0 50-287 0 50-287 0 50-382 0 50-382 0
CARPENTER.D CARPENTER.D C CARPENTER.F D CARPENTER.F D CARPENTER.J H	8408070019* 8408150371 8408060419 8408310023 8408070293	50-397 Q 50-59 R 50-352 R 50-352 R 50-400 Q	CHILK.S J CHILK.S J CHILK.S J	8408010133 8408020008 8408020008 8408020013 8408020044	40-B027 50-322	CILIMBERG,R L CILLIS,M CILLIS,M CIMINO,D CINGUEMANI,D K	8408160341* 8408070021* 8408070080* 8408150476* 8408140449	50-341 Q 50-344 Q 50-344 Q 50-322 T 50-217 Q
CARPENTER, T 9 CARR, A V CARR, A V CARR, A V CARR, A V	8408270552* 8408060035 8408080339 8408140103 8408140110*	CONTRACT 50-413 0 50-413 0 50-413 0 50-413 0	CHILK'S J CHILK'S J CHILK'S J CHILK'S J	8408020197 8408020206 8408060417 8408060434 8408060437	50-275 G 50-275 G 10CFR 50-322 G 50-322 G	CIOFFI.J CIPOLLA.A J CIPOLLA.A J CIPOLLA.A J CLARK.B L	8408200023* 8408130240 8408130273 8408170395 8408080533	50-289 G 40-3392 40-3392 40-3392 50-277 8
CARR.A V CARR.A V CARROLL.R CARGON.B H CARTER.B	8408140115* 8408160121 8408270347* 8408230157* 8408070020	50-413	CHILK'S J CHILK'S J CHILK'S J CHILK'S J	8408060446 8408070265 8408070312 8408070319 8408070361	10CFR 50-275	CLARK, B L CLARK, B L CLARK, B, L CLARK, B W CLARK, C	84080B0535 8408130601 8408270107 8408300183* 8408300407*	50-277 8 50-277 8 50-277 8 50-277 8 50-263 F 50-528 q
CARUSO,R CASCARANO,R N CASCARANO,R N CASCARANO,R N CASCARANO,R N	8408270143* 8408010165 8408100015 8408220086 8408270372	50-322 G 50-295 F 50-295 P 50-295 Q 50-295 P	CHILK, S J CHILK, S J CHILK, S J CHILK, S J	8408070383 8408070396* 8408070463 8408070467 8408070491	PR PR 50-454 G 50-275 G 50-293 G	CLARKIH F CLARKIJ R CLARKIL CLARKI CLARKIN E	8408160378* 8408070341 8408130205 8408130212* 8408200340	50-443 A 50-259 S 70-938 70-938 50-395 B
CASCARAND, R N CASCARAND, R N CASCARAND, R N CASEY, L CASHWELL, R J	8408310115 8408310200 8408310202 8408200506 8408140521	50-304 P 50-295 P 50-295 P HASTE MGT 50-156 F	CHILK, B J CHILK, B J CHILK, B J CHILK, B J	8408080024 8408080216 8408140006 8408140009 8408140454	10CFR 50-416 P 50-275 G 50-275 O 50-454 G	CLARK, N. E. CLARK, N. H CLARK, P. R CLARK, P. R GLARK, R.	8408200344 8408240320 8408270145 8408310153 8408310088*	50-395 S NUREQ 50-289 Q 50-289 P CONTRACT
CASSEL.D W CASSIDY.T J CASTELLI.F P CASTIGLIONE, L CASTIGLIONE, L	8408170319 8408170203* 8408010231* 8408290067 8408290251	50-454 T 50-244 G 50-354 E 50-155 S 50-155 S	CHILK, B J CHILK, S J CHILK, S J CHILK, S J	8408140486 8408140486 8408209573 8408200608 8408210352	50-275 0 50-275 0 50-229 0 50-293 0 50-322 0	CLARK, R. A CLARK, R. J. CLARK, R. J CLARK, R. J CLARK, R. J	8408080472 8408030110 8408130026 8408160424 8408200264	NUREQ 50-296 P 50-259 P 50-259 P 50-259 P
CATCHPOLE.G J CATCHPOLE.G J CATION.E M CATION.I CATION.I	8408240050 8408240079 8408300272 8408020248 8408020252	40-8745 40-8745 NUREG ACRS ACRS	CHILK'S J CHILK'S J CHILK'S J CHILK'S J CHILK'S J	8408220251 8408220323 8408220358 8408240424 8408270046	50-275 Q 50-275 Q 50-287 Q 50-275 Q 50-289 Q	GLARKIR J GLARKIR J, GLARKIR J GLARKIR J GLARKIR J	8408210003 8408280257 8408280282 8408310414 8408310420	50-257 P 50-259 P 50-259 P 50-259 P 50-259 P
CEJA: S N GERNE: A C CERZOSIMO, R R CESARE: J G CHAMBENLAIN: D	8408080013 8408150262* 8408080255 8408210105 8408070095*	XPORTLIC 50-443 Q NUREQ 50-416 R 50-458 Q	CHILK'S J CHILK'S J CHILK'S J CHILK'S J	8408280168 8408280175 8408280217 8408280237 8408280333	50-289 0 50-289 0 50-275 0 50-352 0 50-3	CLARK, R. J. CLAWSON, C. A CLAY, E. L. CLAY, O. W. CLAYTON, H. B	8408310424 8408020048 8408280367* 8408240239* 8405010079*	50-260 P 50-382 T 70-1113 50-413 I 50-315 F
CHAMBERLAIN, D CHAMBLESS, P M CHAN, T L CHAMBLER, J C CHAMBLER, J C	8408280203* 8408210485 8408170117* 8407300143 8408090178	50-412 E 1&E 50-443 Q TOPREP 50-316 P	CHILK.B J CHILK.B J CHILK.B J CHILK.B J	8408280378 8408270270 8408270277* 8408300043 8408300161	50-445 0 PR PR 10CFR 50-322 0	CLAYTON, H B GLAYTON, H, B CLEMENTS, B R GLEMENTS, B R GLEMENTS, B R	8408160249 8408240330 * 8408030115 8408090044 8408090105*	TOPREP 50-250 F 50-445 B 50-445 B
CHANDLER, J C CHANDLER, J C CHANDLER, J C CHANDLER, J C CHANDLER, J G	8408070209* 8408070230 8408140171 8408140363* 8408140376	50-316 P TOPREP TOPREP 50-261 P TOPREP	CHILK.B J CHILK.B J CHOI.K CHOI.K CHOKBHI.N C	8408310079 8408310423 8408070404 8408170343* 8408270170*	50-287 0 50-287 0 50-275 8 50-354 0 50-155 0	CLEMENTO, B R CLEMENTO, B. R CLEMENTO, B R CLEMENTO, B R CLEMENTO, B R	8408140204# 8408140204# 8408140510 8408270368 8408280375	50-445 S 50-445 Q 50-445 S 50-445 F 50-445 S
CHANDLER.J C CHANDLER.J C CHANDLER.J C CHANDLER.J C CHANDLER.J C	8408230103* 8408230263 8408240268 8408280122 8408280212	30-241 P 50-315 P TOPREP TOPREP	CHOULES, N C CHOULES, N C CHRISSOTIMOS, N CHRISSOTIMOS, N CHRISSOTIMOS, N	8408230278* 8408300179* 8408010274* 8408010316* 8408230355*	50-373 0 50-305 0 50-373 0 50-374 0 50-254 0	CLEMENTS, B R CLEMENTS, B, R CLEMENTS, B R CLEMENTS, R, H	8408280384 8408280448 8408270125 8408270208 8408010154#	50-445 B 50-445 B 50-445 B 50-445 K 50-412 F
CHANDLER, J C CHANDLER, L J CHANDLER, L J CHANDLER, L J CHANDLER, L J	8408310175 8408010207 8408020227* 8408020227*	TOPREP 50-320 G 50-275 G 50-275 G 50-275 G	CHRISSOTIMOS, N CHRISSOTIMOS, N CHRISTENSEN: S CHRISTMAN, J N CHRISTMAN, J N	8408240114 8408300108* 8408020129 8408010261 8408010261	50-374 8 50-10 9 50-322 T 50-322 9 50-322 9	CLEMENTO, W. L.	8408070388 8408140548 8408230305 8408230311 8408270058	50-322 Q 50-275 Q 50-445 Q 50-445 Q
CHANDLER, L. J CHANDLER, L. J CHANEY, H D CHANEY, H D CHAPLIN, S D	8408020233* 8408160226*	50-275 Q 50-275 Q 50-382 Q 50-458 Q 50-320 S	CHRISTMAN, J N GHRISTMAN, J N CHRISTMAN, J N CHRISTMAN, J N CHRISTMAN, W T	8408080408 8408080408 8408300124 8408300124 8408080417	50-322	CLEMONS, P CLEMONS, P CLEMONS, P E. CLEVELAND, J. C. CLEWETT, J	8408200023# 8408240231# 8408010286#	50-289 0 50-213 0 50-247 0 NUREO 50-400 T

AUTHOR	ACCESSION NUMBER	SUBJE - CATEGUE,	s, InDR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJEC CATECO
CLINE, W CLINE, W E CLINE, W E CLINE, W E CLOUGH, R L	8408270227* 8408270295* 8408270432* 8408280370* 8408080359	50-302	600k' 1 M 600k' 1 M 600k' 1 M 600k' 1 M	8408020315 8408020104 8408070183 8408070227 8408070284	50-329 A NUREO 50-329 Q 50-329 G 50-329 S	COUNSIL.W G COUNSIL.W G COUNSIL.W G COUNSIL.W G	8409070321 8409070321 8409070321 8409070341 8408070341	50-213 50-213 50-213 50-336 50-336
COATS.M L CODELL.R B COHEN.D A COHEN.I COHEN.I	8408080026 8408300292 8408140377 8408030221* 8408230235*	50-445 T NUREG PR 50-333 G 50-220 G	СФВК'Я М СФВК'Я М СФВК'Я М СФВК'Я М СФВК'Я М	8408130227* 8408130255* 8408130270* 8408130644* 8408130667*	50-329 A 50-329 A 50-329 A 50-329 G 50-329 G	COUNSIL,W G COUNSIL,W G COUNSIL,W G COUNSIL,W G	8408080414* 8408080414* 8408070082 8408070082 8408070180	50-245 50-245 50-423 50-423 50-213
COLARULLI,P F COLARULLI,P F GOLBURN,T G GOLE,A W COLE,R F	8408140488 8408140488 8408070514 8408020126* 8408300168	50-247	600K'1 M 600K'1 M 600K'1 M 600K'1 M 600K'1 M	8408150472* 8408150685* 8408150718* 8408210454* 8408220055*	50-329 Q 50-329 A 50-329 A 50-329 E 50-329 Q	CDUNSIL.W G CDUNSIL.W G CDUNSIL.W G CDUNSIL.W G	8408100063 8408100063 8408100063 8408100064 8408100064	50-213 50-213 50-213 50-423 50-423
COLLIN A COLLIN A COLLIN A	8408240366* 8408270039* 8408070397 8408070397	50~321	COOK'R M COOK'R M COOK'R M COOK'R M	8408310054 8408310259 8408070109 8408070230 8408100006	50-327 8 30-329 9 50-382 F 50-382 F 50-382 0	COUNSIL, W G COUNSIL, W G COUNSIL, W G COUNSIL, W G	8408100102 8408100102 8408100116 8408100116 8408100116	50-245 50-245 50-213 50-213 50-213
COLL, N A COLLINS, J T COLLINS, J T COLLINS, J T COLLINS, J T	8408070437 8408070315 8408070339 8408070022 8408100141	50-250 G State Prog State Prog 50-313 G 50-382 G	CODK,K W CODK,K W CODK,K W CODK,K W	8408100007 8408100117 8408130342 8408210305 8408230179	50-382 @ 50-382 F 50-382 F 50-382 A 50-382 A	CONNEIL'M O CONNEIL'M O CONNEIL'M O CONNEIL'M O	8408130314 8408130314 8408150232 8408150232 8408160328	50-336 50-336 50-336 50-336 50-213
COLLING, EL COLLING, EL COLLING, EL COLLING, PF COLLING, 8	8408140413* 8408140433* 8408210387* 8408270322 8408310271	50-346 P 50-313 P 50-338 P PR 50-333 Q	COOK, K W COOK, K W COOK, R COOK, R	840823028 4* 8408310225 8408310234 8408010174 8408010220	50-382 G 50-382 F 50-382 A 50-320 S 50-320 S	CONNEIL'M C CONNEIL'M C CONNEIL'M C CONNEIL'M C	8408160350 8408200172 8408200172 8408210306 8408210306	50-213 50-336 50-336 50-245 50-245
COLLING, S J COLLING, S J COLLING, S J COLLING, T R COLMAR, R	8408150432 8408240253* 8408270541* 8408280082* 8408220245	50-410 A 50-410 Q 50-333 Q 50-302 Q NUREG	COOK'S 7 COOK'S 7 COOK'S 7 COOK'S 6 COOK'S	8408010230 8408300381* 8408130323* 8408130356* 8408150395*	50-320 B 50-320 G 50-327 A 50-329 A 50-329 A	COUNSIL, W G COUNSIL, W G COUNSIL, W G COUNSIL, W G	8408210339 8408210339 8408210469* 8408210469* 8408210480	50-423 50-423 50-336 50-336 50-213
COLOMBO,R W COLOMBO,R W CONLON,T E CONLON,T E CONLON,T E	8408280240 8408310176 8408240359* 8408240362* 8408270191*	50-312 P 50-312 S 50-321 Q 50-370 Q 50-413 Q	CON'S Y COOK'S Y COOK'S Y COOK'S Y COOK'S Y	8408150622* 8408150690* 8408150698* 8408150743* 8408270323*	50~329 Q 50~329 Q 50~329 R 50~329 A 50~329 A	CONNEIL! M C CONNEIL! M C CONNEIL! M C COUNEIL! M C	8408210480 8408210480 8408270222 8408280157 8408280157	50-213 50-213 50-213 50-423 50-423
CONLON, T E	8408270371* 8408270414* 8408270440* 8408280028* 8408280140*	50-413	COOKE, B A COOKE, T C COOKE, T C COOKE, T C	8408230953 8408020122* 8408140050* 8408140067* 8408220496	Waste Mgt 50-329 A 50-329 A 50-329 A Waste Mgt	COUNBIL, W. G COUNBIL, W. G COUNBIL, W. G COUNBIL, W. G	8408280258 8408280258 8408290298 8408290298 8408290298	50-423 50-423 50-213 50-213 50-213
CONNAUGHTON, K CONNELL, K CONNER, E CONNER, E CONNER, E L	8408070221* 8408310191* 8408150271* 8408210383 8408280293*	50-454 G 50-341 F 50-287 G 50-287 5 50-219 G	COOLEY, R A COOLEY, R A COOLEY, R A COOLEY, R A	8408040097* 8408090037* 8408090073* 8408290115* 8408290142*	50-482 0 50-298 0 50-382 0 50-388 0 50-285 0	COUNSIL, W. G COUNSIL, W. G COUNSIL, W. G COUNSIL, W. G	8408300135 8408310107 8408310187 8408310187 8408310187	50-213 50-213 50-213 50-213 50-213
CONNER, E L CONNER, T B CONNER, T B CONNER, T B CONNER, T B	8408300096* 8408010246 8408010246 8408010255 8408010255	50-217	COOLEY, R A COOMBB, H A COONEY, M J COONEY, M J COONEY, M J	8408270174* 8408140405* 8408140355 8408230185 8408310004	50-348 q 50-508 A 50-352 F 50-277 P 50-277 Q	COVILL.D W COMMOTILL.C.J COMOTILL.C.J COVILL.C.J	8409270290* 8406070192 8408280293* 8408300096* 8408060203	50-219 50-397 50-219 50-219 50-237
CONNER, T B CONNER, T B CONNER, T B CONNER, T B CONNER, T B	8408070287 8408070287 8408070291* 8408070291* 8408070350	50-352	CODNEY, M J CODPER, M R CODPER, M R COOPER, M R COPELAND, V G	8408310417 8408070156 8408160473 8408160522 8408010260	50-352 0 50-327 8 50-327 9 50-327 8 50-155 0	COYLE, L COYLE, L COYLE, L Cracker, H W Crane, P A	8409200501 8409240218 8408270455 8408230235* 8408300482	50-10 50-237 50-249 50-220 50-275
CONNER, T B	8408070350 8408070495 8408070495 8408080019 8408080399	50-352	COPELAND, V G COPELAND, V G COPELAND, V G COPELAND, V G	8408010260 8408080224 8408080224 8408140028 8408140028	50-155 Q 50-155 Q 50-155 Q 50-456 Q 50-456 Q	CRANWELL, R. M CRANWELL, R M CREED, J R CREED, J R CREED, J R	8408240260 8408290337 8408060036* 8408100037* 8408210471*	HASTE   HASTE   50-341 50-282 50-461
CONNER, T B CONNER, T B CONNER, T B, CONNER, T B CONNER, T B	8408080379 8408130378 8408240236 8408240236 8408240241	50-352	COPELAND, V G COPELAND, V G COPLAN, S M COPLAN, S M	8408140034* 8408140034* 8408050173 8408130122 8408210135	50-456 Q 50-456 Q WASTE MOT WASTE MOT WASTE MOT	CRLENJAK, R. V CROCKER, H. W CROCKER, H. W CROCKER, H. W CROCKER, H. W	8408270269# 8408030221# 8408040208# 8408130380# 8408140272#	50-321 50-333 50-213 50-27 50-334
CONNER, T B CONNER, T B CONNER, T B CONNER, T B, CONNER, T B	8408240241 8408240236 8408240236 8408280448 8408280448	50-352 0 50-352 0 50-352 0 50-354 0 50-354 0	COPLANIS M CORDAROIM C CORDAROIM C CORLEYIM O CORLEYIM O	8408230394 8408020048 8408130332* 8408130693* 8408220090*	HABTE MOT 50-322 T 50-329 A 50-329 A	CROCKER, H W CROBBY, Q E CROSEMAN, H CROSEMAN, H A CROSEMAN, H A	8408270465# 8408280127 8408130515# 8408030275# 8408060057#	50-271 50-263 50-382 50-382
CONRAD, H F CONTE, R. CONTRELL, F 9 CONWAY, J T COOK, D B	8408140075* 8408150271* 8408240286 8408010372* 8408230496	50-400 T 50-287 G 50-328 S GA777 50-254 S	CORRADINI, M L CORRADINI, M, L CORNIN, W R COSTANZI, F A COSTELLO, F	8408020235 8408020235 8408080419 8408160467 8408200023*	ACRE MUREC MUREC 50-289 Q	CROSEMAN, W A CROSEMAN, W A CROSEMAN, W A CROSEON, R E CROUCH, D. B.	8408040325* 8408160226* 8408220500* 8408160405* 8408280365	50-382 50-382 50-382 50-508 40-843
COOK, F. R. COOK, J. A. COOK, J. H. COOK, J. W.	8408230038 8408140311 8408240379 8408010149# 8408020014	WASTE MOT 50-333 R Nureg 50-327 A 50-327 A	COTTER, # P COTTRELL, W B COTTRELL, W B COUNSIL, W, G COUNSIL, W Q	8408070475 8408270170 8408270178 8408070220 8408070220	50-322 Q NUREQ NUREQ 50-423 A 50-423 A	CROUSE, R P CROUSE, R P, CROUSE, R. P CROUSE, R. P CROUSE, R. P	8408070301 8408070335 8408130390* 8408130395* 8408130411*	50-344 50-344 50-344 50-344 50-344

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGURY
CROUSE, R P	8408130421 8408130428* 8408140410 8408170214 8408200135	50-346 P 50-346 P 50-346 P 50-346 Q 50-346 P	DALE, L F DALE, L F DALE, L F DALE, L F DALE, L F	8408150201 8408160175 8408210105 8408210151 8408210484	50-416 S 50-416 S 50-416 R 50-416 F	DAVIS,M J DAVIS,P DAVIS,P R DAVIS,W G DAVIS,W G	8408270456* 8408130319 8408130324* 8408010210 8408010245	50-280 q 50-382 g 50-382 q 50-458 q 50-458 q
CROUSE, R P CROUSE, R P CROUSE, R P CROW, W T CROW, W T	8408210345 8408210456 8408280197 8408090319 8408280034	50-346 P 50-346 P 50-346 K 40-6940 70-143	DALE, L F DALE, L F DALE, L F DALE, L F DALE, L F	8408240210 8408270263* 8408270321* 8408300490 8408310222	50-414 S 50-417 Q 50-416 Q 50-416 S 50-416 P	DEAGATIO'V DE AINCENTIS'A DE AINCENTIS'A DEAGATIO'V	8408160472* 8408060382* 8408160371 8408160371 8408170002	70-1308 70-1362 50-443 A 50-443 A 50-346 P
CROW, W T CROWE, D M CROWLEY, D R CROWLEY, B R CRUTCHFIELD, D	8408280351 8408020106 8408240366* 8408270275* 8408010038	70-938 NUREG 50-321 G 50-417 G 50-206 P	DALTROFF,S L DALTROFF,S L DALTROFF,S L DALTROFF,S L DALTROFF,S L	8407160090 8408040321 8408070303 8408220497 8408230258	50-277 F 50-277 P 50-278 P 50-352 F 50-352 V	DEAGAZIO,A DEAGAZIO,A DEAGAZIO,A W DEAN,R E DEAN,R B	8408270471 8408280345 8408070499 8408130265 8408310084	50-346 F 50-346 F 50-346 P NUREQ NUREQ
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8408060388 8408070008 8408070079 8408130251* 8408140188	50-341 A M190 50-29 P 50-382 Q 50-206 P	DALTROFF, S L DALY, B J DAM, W DANCE, H C DANCE, H C	8408310008 8406230301 8408290459 8408030126 8408130149	50-352 F 50-317 P WASTE MGT 50-335 Q 50-269 Q	DEBOLT, B DEBOLT, R DECKER, T R DECKER, T R DEFAYETTE, R W	8408040197* 8408270328 8408270227* 8408280370* 8408030179*	50-70 G PR 50-302 G 50-269 G 50-155 G
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CULLEN, E J	0408140408 8408160172 8408200114 8408230077 8408150404	50-213 P 50-155 P 50-204 P 50-29 S 50-352 G	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8408230392 8408240356 8408240364 8408240416 8408270184	50-338 S 50-321 G 50-321 G 50-249 G 50-413 G	DELGAIZA, T J DELGEORGE, L O DELLA RATTA, A DEMOGR, D E DEMOGR, D	8204150347* 8408280274 8408150407* 8408230239 8408140038*	50-293 P 50-454 Q 70-371 50-155 S 50-456 Q
CULLEN, E J CULLEN, E J CUMMINGS, G E CUMMINGS, G E	8408200286 8408240242 8408080515* 8408080517* 8408080521*	50-352 G 50-352 G 50-275 G 50-275 G 50-275 G	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8408270219* 8408270289 8408270291 8408270306* 8408270334	50-302	DEMOSS, D M DENENBERG, E DENTON, H R DENTON, H R DENTON, H R	8408310174* 8408080008* 8408030215* 8408030218* 8408030223*	50-454 T CONTRACT 50-320 P 50-320 P 50-320 P
CUMMINGS, J C CUMMINGS, R A CUMMINS, J E CUNNINGHAM, G E	8408100153 8408240221 8408150102* 8408150655* 8408070335	NUREG WASTE MANA 50-445 Q 50-445 Q 50-73 P	DANCE, H C DANCE, H. C DANCE, H C DANCE, H C DANCE, H C	8408270342 8408270360 8408270367 8408270383 8408270387	50-424	DENTON, H R	8408030277 8408070025 8408070076 8408070268 8408080082	MISC 50~44/ H 50~366 B PR 50~320 H
CUNNINGHAM, G H CUNNINGHAM, G H CUNNINGHAM, R E CUNNINGHAM, R E CUNNINGHAM, R E	8408070029* 8408150120 8408010244 8408030183 8408060023	50-447 H 50-348 M 40-2061 40-2061 40-2061	DANCE.H C DANCE.H C DANCE.H C DANCE.H C DANCE.H C	8408270408 8408270428 8408270429 8408270433* 8408270443	50-424 Q 50-302 Q 50-424 Q 50-424 Q 50-280 Q	DENTON.H R DENTON.H R DENTON.H R DENTON.H R	8408130022 8408130075 8408130148* 8408130242 8408130555	50-295 P 50-348 M 50-413 P 50-366 P PRM
CUNNINGHAM, R E TUNNINGHAM, R G DCD, L M TRAN, D RAN, D	8408220427 8408230267 8408150062 8408070344 8408240234	70-364 50-5 P 40-2061 PR 50-443 G	DANCE, H C DANCE, H C. DANCE, H C DANCE, H C DANCE, H C	8408270444 8408270452* 8408270474 8408270484 8408280061	50-349 0 50-280 0 50-413 0 50-413 0 50-302 0	DENTON: H R	8408150611 8408160161 8408160439 8408170007 8408200274	50-254 P 50-271 P MISC 50-344 P 50-209 H
H'81WH M N'SIL M N'SIL M C'SIL	8408280205 8408040143 8408070342 8408130127 8408220350	50-413 T 50-387 I 50-387 P 50-387 F PR	DANCE.H C DANCE.H C DANCE.H C DANCE.H C DANCE.H C	8408280072* 8408280152 8408280327 8408280361 8408280384	50-302 Q 50-424 S 50-413 Q 50-267 G 50-413 Q	DENTON: H R	8408230355 8408230434 8408240367 8408240425 8408300175*	50-302 H 50-289 H M180 M180 50-219 F
JTLER, J M JTSHALL, N H UTTER, A B CUTTER, A B CUTTER, A B	8408230034 8408300282 8408030074 8408030076 8408030162	WABTE MOT NUREG 50-261 F 50-261 P 50-261 P	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8408270330 8408300208 8408300238 8408300244 8408300303	50-33B	DEAINCENTIE' N DEAINCENTIE' N DERTUNCENTIE' N DENTON'E E	8408070074 8408080531 8408070332 8408070332 8408070362	50-317 0 50-336 8 50-443 A 50-443 A 50-443 F
CUTTER, A B CUTTER, A B CUTTER, A B CUTTER, A B CUTTER, A B	8408060257 8408070374 8408080252 8408160129 8408220126	50-400 A 50-261 P 50-324 P 50-324 Q 50-261 F	DANGC: H C DANGE: H C DANGE: H, C DANGE: H C DANGE: H C	8408300344 8408300358 8408300375 8408300417 8408300427	50-424 G 50-413 F 50-335 G 50-250 P 50-267 F	DEAINCENLIB' N DEAINCENLIB' N DEAINCENLIB' N DEAINCENLIB' N	8408070362 8408100013 8408100013 8408100083 8408100136	50-443 F 50-443 B 50-443 B 50-443 B 50-443 B
CUTTER, A B CUTTER, A B CUTTER, A B CUTTER, A B DAHLEN, D	8408220229 8408230093 8408230117 8408280166 8408240042	50-261 P 50-261 P 50-261 P 50-324 Q 50-295 B	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8408300429 8408300433 8408300436 8408310030 8408310057	50-280 F 50-280 F 50-321 F 50-250 V 50-321 F	DEVINCENTIS, J DEVINE, T DEVINE, T DEWEY, L &	8408100136 8408010138 8408010235 8408020152 8408070370	50-443 S XPORTL10 50-275 0 50-275 0 50-458 0
DALE, L F DALE, L, F DALE, L F DALE, L F DALE, L F	8408030075 8408030095 8408030103 8408030106 8408030120	50-416 P 50-416 P 50-416 P 50-417 A 50-416 S	DANCE.H C DANGE.H C DANIELSEN.D C DANIELBON.D H DANIELSON.D H	8408310060 8408310425 8408270275 8408070340* 8408080195*	50-280 F 50-280 V 50-484 Q 50-484 Q 50-484 Q	DEYOUNG.R DEYOUNG.R DEYOUNG.R C DEYOUNG.R C	8408130102 8311020513 8303300734 8303300736* 8307130017*	50-354 G 50-445 A 50-445 A 50-445 A 50-327 G
DALE, L F DALE, L F DALE, L F DALE, L F DALE, L F	8408060030 8408060174 8408060185 8408060189 8408060247	50-416 S 50-416 P 50-416 S 50-416 S 50-416 P	DANIELSON, D H DANIELSON, D H DANIELSON, D H DANIELSON, D H	8408070189* 8408070195* 8408150487* 8408160327* 8408160341*	50-266 Q 50-255 Q 50-454 Q 50-346 Q 50-341 Q	DEYOUNG,R C DEYOUNG,R C DEYOUNG,R C DEYOUNG,R C DEYOUNG,R C	8307130110 8307130112* 8307130117* 8407020541 8407200107	50-445 A 50-445 A 50-445 A REVIEW GRP REVIEW GRP
DALE, L F DALE, L F DALE, L F DALE, L F	8408070404 8408070430 8408070436 8408080538 8408090137	50-416 P 50-416 P 50-416 P 50-416 S 50-416 S	DANIELBON, D H DARDEN, T DARDEN, T DARLING, S B DAVIS, G A	8408310394* 8408140003 8408210280 8408150395 8408140405*	50-341 G 1&E 1&E 50-318 8 50-508 A	DEYDUNG, R C DEYDUNG, R C DEYDUNG, R C DEYDUNG, R C DEYDUNG, R C	8407300142 8407300151* 8407300156* 8408150057 8408150665*	50-329 Q 50-329 Q 50-329 Q GA999 50-329 A
DALE, L F DALE, L F DALE, L F DALE, L F DALE, L F	8408090163 8408130365 8408130371 8408140116 8408150151	50-416 S 50-416 S 50-416 S 50-416 P 50-416 P	DAVIS, J E DAVIS, J E, DAVIS, J G DAVIS, J, M DAVIS, K,	8408070123 8408070271 8408160048 8408140151* 8408270497	50-483 B 50-483 B WASTE MGT 50-400 T CONTRACT	DEYDUNG,R C DEYDUNG,R C DEYOUNG,R D DEYOUNG,R D DIAZ,N J	8408170109 8408220431 8408310108 8408240021 8408130261	50-443 Q 50-307 F TOPREP 50-382 Q 70-1068

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DICK, G F DICK, G F DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J	8408080029 8408300027 8408060042 8408060055 8408060053	50-244 F 50-244 F 50-374 S 50-373 S	DIXON'O M DIXON'O M DIXON'O M DIXON'O M	8408100002 8408130340 8408130364 8408140265 8408160525	50-395 F 50-395 S 50-395 F 50-395 P 71-9151	DUNLAP, J M DUNLOP, A DUPONT, S G DURR, J P DURR, J P	8408190424* 8408230252* 8408150475* 8408100072 8408150419	50-277
DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J	8408060107 8408060207 8408060227 8408060255 8408060283	50-374 S 50-373 S 50-374 S 50-373 S 50-374 S	DIXON, O W DIXON, O W DIXON, O W DIXON, O W	8408170308 8408200340 8408200344 8408230507 8408240002	50-395 V 50-395 S 50-395 S 50-395 S 50-395 P	DURR.J P DURR.J P DURR.J P DURR.J P	8408150534* 8408150553* 8408160260* 8408210317* 8408230145*	50~272
DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J	8408070371 8408070470 8408070324 8408160140 8408200323	50-374 8 50-374 8 50-373 9 50-373 R 50-373 S	D'EWAT'Y DIXON'O M DIXON'O M DIXON'O M	8408270174* 8408280104 8408280287 8408300514 8408220148	50-375 G 50-375 P 50-375 G 50-375 B 50-367 J	DURRIJ P DURRIJ P DURRIJ P DUBIR S	8408230285* 8408270242* 8408300113* 8408300116* 8408160140	50-293 Q 50-410 Q 50-247 Q 50-29 Q 50-373 R
DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J	8408200526 8408230524 8408230533 8408240044 8408240179	50-373 S 50-374 S 50-374 S 50-374 S 50-374 S	DJEMAL, A DODDS, R T DODDS, R T DODDS, R T DODDS, R T	8408270004 8408080477* 8408070019* 8408170369 8408240287	50-269 J 50-344 Q 50-397 Q 50-397 S 50-344 S	DUTTA, P DUVALL, D D DUVALL, D D DUVALL, D D	8408220324 8408030089 8408030165 8408070317 8408220317	WASTE MGT GA799 GA999 GA799 50-245 S
DIEDERICH. G J DIEDERICH. G J DIEDERICH. G J DIEDERICH. G J DIENEB. A F	8408300388 8408300508 8408310047 8408310253 8408160255	50-373 R 50-373 R 50-373 S 50-374 S 50-255 R	DODD8.R T DODD8.R T DODD8.R T DODD8.R T DODD8.R T	8408290036 8408300250* 8408300377* 8408300380* 8408300451*	50-397 8 50-312 0 50-344 0 50-344 0 50-397 0	DUVALL, D D DUVALL, D D DYER, F F DYKGTRA, J DYNNER, A R	8408240259 8408240274 8408300272 8408130007 8408140013	0A999 0A999 NUREG NUREG 50-322 T
DIETZ, CR DIETZ, CR DIETZ, CR DIETZ, CR DIETZ, CR DIETZ, CR	8408060128 8408070032 8408070370 8408070432 8408100037	50-325 S 50-325 S 50-324 B 50-325 S 50-325 S	DODDS.R T DOERFLEIN.L T DOHERTY.J F DOMENICI.P V	8408300464* 6408270541* 8408270185 8408140417 8408230063*	50-397 Q 50-333 Q NUREQ PR 50-272 H	DYNNER, A R DYNNER, A R DYNNER, A R DYNNER, A R DYNNER, A R	8408140013 8408140466 8408140466 8408230264 8408230264	20-355 6 20-355 6 20-355 6 20-355 1
DIETZ, CR DIETZ, CR DIETZ, CR DIETZ, CR DIETZ, CR DIETZ, CR	8408130338 8408140151* 8408160075 8408160133 8408240227	50-324 8 50-400 T 50-325 8 50-325 8 50-324 8	DOMER, J A DOMER, J A DOMER, J A DOMER, J A DOMER, J A	8408140331 8408140375 8408150213 8408200131 8408240107	50-259 S 50-259 P 50-296 Q 50-259 P 50-259 Q	DZENIS,E A DZENIS,E A EAPEN,P K EARLE,D K	8408140262* 8408140262* 8408060251 8408090051* 8408020029	50-250 Q 50-250 Q 50-265 E 50-277 Q 50-341 K
DIETZ,C R DIGGS,R M DIGGS,R M DIGGS,R M DIGGS,R M	8408270431* 8408010122 8408070040 8408070154 8408070491	50-324 Q 50-366 P 50-159 P 50-219 P 50-250 P	DOKOZHOM Y DOKOZHOM Y DOKOZHOM Y DOUCZHOM Y DOUCZHOM Y	8408070438 8408060201 8408060201 8408060224* 8408060224*	50-423 A 50-289 G 50-289 G 50-289 G 50-289 G	EARLE, D K EBERLY, R EBERBOLE, J C EBERBOLE, J C EBERBOLE, J C	8408140474 8408140093* 8408170287 8408170316 8408170373	50-341 A 50-400 T ACRE ACRE ACRE
DIGOS.R M DIGOS.R M DIGOS.R M DIGOS.R M DIGOS.R M	8408140073 8408140295 8408160494 8408170017 8408210547	50~344 P 50~255 P 50~315 P 50~237 P 50~409 P	DOBOBHOM Y DOBOBHOM Y DOBOBHOM Y DOBOBHOM Y	8408070382 8408070382 8408070408 8408070408 8408140449	50-289	EBERBOLE, J C EBERBOLE, J C ECKERT, J, P ECKERT, J P	8408170378 8408270076 8408130043 8408270121* 8408270258*	ACRS WASTE MOT NUREG 70-27 70-27
DIGOS,R M DIGOS,R M DIGOS,R M DIGOS,R M DIGOS,R M	8408210550 8408210552 8408210525 8408230271 8408230318	50-266 Q 50-304 P 50-206 P 50-307 P 50-518 A	DOUGHERTY, D DOTY, J W DOROSHOW, J DOROSHOW, J	8408140479 8408140479 8408240250 8408030025* 8408010151	50-287 G 50-289 G 50-219 G 50-327 P MUREG	ECKERT, J P ECKERT, J P ECKHARDT, J ECKHARDT, J H ECONOMOB, N	8408270274* 8408310039* 84083140346 8408300254* 8408280393*	70-27 70-27 50-312 8 50-312 0 50-413 0
DIIANNI,D C DIMEGLIO,A F DIMEGLIO,A F DIMMOCK,L DIRCKS,W J	8408160482 8408070332 8408210328 8408300060* 8405180145	50-244 P PR 50-173 8 50-263 9 50-358 H	DOWNEY, B L DOWNEY, B L DOWNEY, B L	8408010250 8408010250 8408310154 8408280156 8408280156	50-338	EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W	8408030070 8408030070 8408070457 8408140002 8408140117	50-400 Q 50-400 Q 50-400 Q 50-400 Q
DIBCKR'N J DIBCKR'N J DIBCKR'N J DIBCKR'N J	8407030011* 8407120142 8408010275 8408010338 8408060389	REVIEW GRP 50-528 D 50-275 U 50-335 H MISC	DOWNEY, B L DOYLE, J DRAGOUN, T DRAGOUN, T	8408280251 8408280251 8408090503* 8408030267* 8408240076*	50-445 G 50-445 G 50-445 G 50-272 G 50-334 Q	EDDLEMAN; W EDDLEMAN; W EDDLEMAN; W EDDLEMAN; W EDELMAN; M	8408140122* 8408140125* 8408140105 8408200478 8408020118	50-400 0 50-400 0 50-400 0 50-400 0 50-440 I
DIRCKP'M N DIRCKP'M N DIRCKP'M N DIRCKB'M N	8408070041 8408070201 8408070211 8408070138 8408090404	50-416 H 50-416 U 50-322 H SECY SECY	DRAGOUN.T F DREHOBL,K E DREHOBL,K E DREIFUB,D DREIFUB,D	8408230136* 8408010163* 8408170102* 8408070218 8408070218	50-277 Q 50-329 O 50-329 A 50-322 Q 50-322 Q	EDELMAN, M R	8408030145 8408070184 8408070148 8408070261 8408130393	50-440 A 50-440 A 50-440 B 50-440 B 50-440 B
DIECKE'M N DIECKE'M N DIECKE'M N DIECKE'M N	8408070508 8408130202 8408130547 8408160288* 8408170094	50-413 U 50-416 U 50-322 A 0R0 50-352 U	DREIFUB, D DREIFUB, D DRIKER, E DRUGA, R J DRUGA, R J	8408070223* 8408070223* 8408150672* 8408100072 8408100113	50-322 0 50-322 0 50-329 A 50-334 8 50-334 8	EDELMAN, M R EDELMAN, M R EDELMAN, M R EDELMAN, M R EDELMAN, M R	8408220498 8408220502 8408270320 8408280131* 8408300054	50-440 8 50-440 8 50-440 F 50-440 9 50-440 9
DIRCKB'M N DIRCKB'M N DIRCKB'M N DIRCKB'M N	8408200449 8408220274 8408230036 8408280054 8408300020	50-352 U DRG 50-272 H 50-322 H REVIEW GRP	DRUGA,R J DRUGA,R J DURDIS,D DUBDIS,D L DUDLEY,N F	8408210016 8408210023 8408230464 8408270500* 8408310048*	50-334 B 50-334 B XPORTLIC 50-298 G 50-470 G	EDWARDS, E W EQBERT, D K EICHENHOLZ, H EICHENHOLZ, H EINZIOER, R E	8408010194 8408220399* 840826082* 8408270579* 8408240379	50-416 Q 50-445 T 50-29 Q 50-29 Q NUREQ
DIVINE, J R DIXON, O W DIXON, O W DIVINE, J R	8408310075 8408060103 8408060134 8408060140 8408070373	NUREQ 50-375 P 50-375 P 50-375 P 50-375 P	DUGGIN, G DUGGIN, G DUGGIN, G E DUMAB, D DUMAB, D	8408170053 8408230509 8408310050 8408310025* 8408310303	50-328 9 50-327 8 50-327 S XPORTLIC XPORTLIC	EISELE,W F EISENHUT,D O EISENHUT,D O EISENHUT,D G	8408230524 8312120393* 8405160470 8405160473* 8406820259	50-374 S 50-327 A 50-87 P 50-89 P 50-322 T
DIXON, O W DIXON, O W DIXON, O W DIXON, O W	8408070402 8408080124 8408080187 8408070143 8408070241	50-375 Q 50-375 P 50-375 K 50-375 B 50-375 B	DUMAS, D DUNCAN, R DUNCAN, R DUNLAP, J DUNLAP, J M	8408310446 8408220374* 8408220374* 8408310065 8408030172*	XPORTLIC 50-445 T 50-445 T 50-272 S 50-410 G	EISENHUT, D. G EISENHUT, D. G EISENHUT, D. Q EISENHUT, D. Q EISENHUT, D. Q	8407310035 8407310035 8408040161* 8408040408 8408070038*	50-275 Q 50-275 E 50-293 P 50-206 P 50-170 P

AUTHOR	ACCESSION NUMBER	SUB : 1 CATEGORI	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G	8408070059 8408070110 8408070127* 8408070309* 8408070455	50-311 P 50-3 P 50-166 P 50-219 P 50-445 A	ELSASSER, T ELSASSER, T C ELSASSER, T C ELSASSER, T C ELSASSER, T C	8408270007* 8406260179* 8408080403* 8408090141* 8408150255*	50-423	FARRAR, D L	8408140139 8408140169* 8408140180* 8408140190* 8408140241*	50-237 F 50-374 q 50-374 q 50-374 q 50-454 q
EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G	8408080037* 8408080454 8408090409* 8408090414* 8408090517*	50-346 F 50-445 A 50-397 P 50-397 P 50-334 P	ELSASSER, T C ELSASSER, T C ELTON, T L ELTON, T L ELTON, T L	8408270486* 8408270518* 8408200438 8408220491 8408270229	50-184 Q 50-54 Q 50-366 S 50-366 S 50-321 S	FARRAR, D L	8408140397 8408160145* 8408160345 8408170369 8408210203*	50-237 F 50-10 Q 50-237 P 50-454 A 50-374 Q
EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G	8408070524* 8408070533 8408070534* 8408130164 8408130278*	50-334 P 50-170 P 50-170 P 50-413 P 50-10 F	ELTON, T L EMBREY, D E EMCH, R L EMCH, R L EMMETT, J	8408300333 8408010166 8408160343 8408160346 8408290328	50-321 S NUREG 50-155 P 50-155 P 50-454 G	FARRAR, D L FARRELL, C A FARRELL, C A FARRELL, E V FARRELL, R E	8408210358* 8408170339* 8408170342* 8408150188 8408200292*	50-454 q 50-354 q 50-354 q 50-317 s 50-458 q
EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G	8408130559* 8408140558 8408140561* 8408150228* 8408150585*	50-334 P 50-166 P 50-166 P 50-219 P 50-271 P	EMRIT.R ENDRES.G W ENG.P ENGEL.R F ENGELDER.T C	8408220265 8408290171 8408230252* 8408280353 8408300194*	NUREG NUREG 50-454 G 50-354 H 70-824	FARRON, P FASAND, A FASAND, A FASAND, A	8408010162 8408010170 8408010174 8408010220 8408010230	50-369 q 50-320 s 50-320 s 50-320 s 50-320 s
EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8408160313 8408160477 8408170046* 8408200018 8408200275	50-445 @ 50-352 A 50-334 F 50-289 @ 50-3 P	ENGELKEN, R H ENGELKEN, R H ENGELMANN, R ENGELMANN, R ENGLAND, L A	8408130220 8408130293 8408240404 8408270104 8408210376	50-361 A 50-361 G 40-8584 40-4492 TOPREP	FASANO, A FAUBER, J FAUBER, J FAUBER, J FAW, R E	8408300381* 8408270031 8408270069 8408270138 8408310117	50-320 @ 40-8502 40-8502 40-8502 50-188 F
EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G	8409200304 8409200441* 8409200499* 8409210005* 8409210011*	50-423 A 50-240 P 50-282 F 50-10 F 50-219 P	ENGLAND.L A ENGLE.L B ENGLE.L B ENGLE.L D ENNIS.J D	8408210376 8408090441 8408210575 8408130204* 8408130418*	TOPREP 50-338 P 50-338 P 50-395 G 50-338 G	FAY.C W FAY.C W FAY.C W FAY.C W FAY.C W	8407310166 8408030147 8408100052* 8408210232 8408270233	50-266 K 50-266 F 50-266 G 50-266 R 50-266 P
EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G	8408210307* 8408210494* 8408210433* 8408210450* 8408270097*	50-255 P 50-329 A 50-329 A 50-329 A 50-409 P	ENNIS, K ENNIS, K EPSTEIN, G ERDMAN, C ERICKSEN, E P	8408280126* 8408280139* 8408060256 8408150371 8408170326*	QA999 QA999 Waste mgt 50-59 R 50-454 T	FAY.C W FAY.C W FAY.C W FAY.C W FEE,W F	8405280128 8408280216 8408300311 8408300518 8408280258	50-266 P 50-266 P 50-266 S 50-266 S 50-423 E
EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8408220173 8408220302* 8408220469 8408230374 8408240115	50-445 T ORG 50-289 P 50-382 A 50-206 S	ERICKSEN, E P ERLER, B ESCH, H E ESELGROTH, P ESELGROTH, P	8408170326* 8408310192 8408310165* 8408030157 8408290483*	50-454 T 50-454 T 50-255 Q 50-388 8 50-322 Q	FEE.W F FEHRINGER.D J FEIERABEND.C D FELTON.J M FELTON.J M	8408280258 8408230062 8408270353* 8407130037 8408010061	50-423 E WASTE MOT 50-335 G FOIA 50-327 A
EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G	8409240401 8409270478* 8409280113 8409280171 8409280229	MISC 50-346 F 50-255 F 50-213 F 50-482 F	ESKRIDGE, H E ESKRIDGE, H E ESKRIDGE, H E ESPINDSA, G ETHRIDGE, D	8408020205 8408210183 8408210190* 8408310337 8408080089	70-36 70-36 70-36 XPORTLIC 50-445 T	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8408310135 8408310142 8408310147 8408310151 8408310155	FOIA 50-275 P 50-344 P 50-142 P FOIA
EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8409280348* 8409300515* 8409310284 8409310374 8409310410	50~346 F 50~261 F 50~266 P 50~305 P MISC	ETHRIDGE, D ETHRIDGE, D EVANS, C A EVANS, C A EVANS, C A	8408270403* 8408220403* 8408930275* 8408160804* 8408230522*	50-445 T 50-445 T 50-382 Q 50-319 Q 50-267 Q	FENSTERMACHER FERGUSON, R L FERKIN, Z O FERLIC, K FERLIC, K	8408130225* 8408140093* 8408020047 8408100035 8408270410*	50-289 P 50-400 T 50-352 G 50-29 G 50-309 G
ELAM, B D ELAYAT, H ELEY, G D ELIN, J O ELLEMAN, T S	8408270270* 8404230171* 8408020129 8408310244* 8408140151*	50-219 P 50-400 F 50-322 T 50-206 G 50-400 T	EVANS,C A EVERETT.R J EWING,J W EYSTER.R FALCONER,D P	8408270007* 8408200052* 8408140413* 8408150524 8408230166*	50-458 @ 50-272 @ 50-346 P 50-413 @ 50-251 @	FERNANDEZ,C FEY,F L FEY,F L FEY,F L FIEDLER,D C	8307010039* 8408300176 8408300180* 8408300183* 8408100124	50-277 P 50-263 F 50-263 F 50-263 F GA999
ELLERSHAW,L E ELLIOTT.C W ELLIOTT.C W ELLIS.D W ELLIS.D W	8408090130* 8408010190 8408040170 8408090104 8408230540	50-313	FALEVITS, Z FALEVITS, Z FALEVITS, Z FALLIN, J F FALTER, H W	8408150293* 8408300196* 8408300220* 8408160234 8408100101*	50-255 G 50-440 G 50-341 G 50-275 G 50-461 A	FIEDLER.P B FIEDLER.P B FIEDLER.P B FIEDLER.P B FIEDLER.P B	8408010293 8408040142* 8408070152 8408070300 8408070348	50-219 B 50-219 Q 50-219 P 50-219 P 50-219 P
ELLIS, J ELLIS, J ELLIS, J ELLIS, J	8408070 408 8408070 420* 8408070 434* 8408070 463* 8408070 480*	50-445 G 50-445 G 50-445 G 50-445 G 50-445 G	FANNING, G FARBER, M J FARLEY, E M FARLEY, E M FARLEY, E M	8408080257 8408160173* 8408010169 8408010169 8408090411	50-445 T 50-483 G 50-322 G 50-322 G 50-322 G	FIEDLER,P B FIEDLER,P B FIEDLER,P B FIEDLER,P B FIEDLER,P B	8408070454 8408080498 8408090250 8408130191 8408220356	50-219 P 50-219 B 50-219 P 50-219 F 50-219 P
ELLIS, J ELLIS, J ELLIS, J ELLIS, J	8408090488* 8408090512* 8408160106 8408160113* 8408160114	50-445 G 50-445 G 50-445 G 50-445 G 50-445 G	FARLEY, E M FARLEY, E M FARLEY, E M FARLEY, E M FARLEY, E M	8408090411 8408090431 8408090431 8408150438 8408150438	20-355 0 20-355 0 20-355 0 20-355 0	FIEDLER,P B FIEDLER,P B FIEDLER,P B FIEDLER,P B FIEDLER,P B	8408220375 8408230078* 8408270285 8408270381 8408310128	50-219 P 50-219 G 50-219 P 50-219 P 50-219 G
ELLIS.J ELLIS.J ELLIS.J ELLIS.J	8408160141 8408160153* 8408160171 8408160178* 8408200605	50-445 G 50-445 G 50-445 G 50-445 G 50-445 G	FARLEY, E M FARLEY, E M FARLEY, E M FARLEY, E M FARLEY, E H	8408230231 8408230231 8408280492 8408280492 8408290317	50-322	FIELDB, J S FIKAR, L F FIKAR, L F FINDLEY, D F FINDLEY, D E	8408300340 8408200275 8408220412* 8408130437* 8408130442*	50-387 S 50-445 S 50-445 G CONTRACT CONTRACT
ELLIS, J ELLIS, J ELLIS, J ELLIS, J	8408240244 8408280134 8408280141* 8408310102 8408310105*	50-445 Q 50-445 Q 50-445 Q 50-445 Q 50-445 Q	FARLEY, E M FARLEY, E M, FARLEY, E M FARLEY, E M FARLEY, E M	8408270317 8408310218 8408310218 8408310224 8408310224	50-322 G 50-322 G 50-322 G 50-322 G	FINDLEY.D E FINKEL.A FINKEL.A FIORATO.A E	8408130445* 8408080490* 8408090330* 8408200504* 8408220070*	CONTRACT 50-287 @ 50-322 @ 50-354 @ 50-327 A
	8408270454* 8408230392 8408270329* 8408270343* 8408270205	50-280 0 50-338 S 50-250 0 50-335 0 50-29 S	FARNELL, A S FARNELL, A S FARRAR, D L FARRAR, D L FARRAR, D L	8408140263* 8408140263* 8408030252* 8408070212* 8408130413*	50-329 A 50-329 A 50-10 G 50-454 G 50-10 F	FIORELLI, G FIORELLI, O FIORENTA, A J FISCHER, B S FISCHER, D	8408150751* 8408300195* 8408280203* 8408200455 8408010132*	50-327 A 50-528 Q 50-412 E 50-289 Q 50-329 O

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FISCHER.D	8408010153*	50-329 0	FUNCHES, J L	8408200182	50-255 O	GEWEHR, S	8409280387	50-369 8
FISCHER.D	8408010160*	50-329 8	FURR. B J	8408280184	50-400 G	GEWEHR, S	8408290094	50-370 8
FISCHER.D	8408010168*	50-329 0	GAGLIARDO, J E	8408030264	50-382 Q	GIAMBALVO, E W	8408310160	50-373 8
FISCHER.D	8408010178*	50-329 0	GAGLIARDO, J E	8408060054	50-382 Q	GIBBON, T R	8408150731*	50-329 A
FISCHER.D	8408170257*	50-329 A	GAGLIARDO, J E	8408060317	50-382 Q	GIBBONS, T D	8408270414*	50-424 G
FISCHER, D C FISCHER, D C FISCHER, D C FISCHER, D C FISCHER, D C	8408010135* 8408010143* 8408010152* 8408010173* 8408220428	50-329 0 50-329 0 50-329 0 50-329 0 50-272 F	GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E	8408150510 8408160220 8408220247 8408220494 8408230275	50-382 Q 50-382 Q 50-382 Q 50-382 Q	GIBSON, J GIESLER, C W GIESLER, C W GILDENHORN, A J	8408200574 8407260161 8408020073 8408310122 8408070504	50~336 R 50-305 K 50-305 P 50~305 P CONTRACT
FIBCHER,R E	8408150583	70-1151	GAHM, J W	8408210462	50-267 P	GILDENHORN, A J	8408220075	CDNTRACT
FIBH,R F	8408300127*	50-528 e	GAHM, J W	8408230456	50-267 R	GILL, C F	8408010341*	50~454 G
FIBH,R F	8408300504*	50-312 e	GAHM, J W	8408280480	50-267 F	GILL, C F	8408270090*	50-341 G
FISICARD,J J	8408040287	50-285 E	GALLAGHER, E	8408150727*	50-329 A	GILLEN, D M	7909290119*	50-329 A
FITZPATRICK,R	8408150452*	50-327 A	GALLAGHER, E J	8408140039*	50-329 A	GILLEN, D M	8408280340	WASTE MGT
FLACK, E FLACK, E FLACK, E FLACK, E FLACK, E	8407110250 8408010251 8408210407 8408240357 8408280048	18E 18E 18E	GALLAGHER. G GALLAGHER. J W GALLAGHER, J W GALLO, J GALLO, J	8408140575* 8408070228 8408210394* 8408270163 8408270163	50-329 A 50-352 A 50-352 Q 50-454 Q 50-454 Q	GILLER.K T GILMORE.T GIRARD.E H GIRARD.E H GIUFFRIDA.L O	8408080359 8408030093 8408240342* 8408270240* 8408270356	NURE9 50-528 K 50-259 Q 50-438 Q COMMISSION
FLACK, E FLACK, E FLEENOR, C FLEENOR, C FLEENOR, C.	8408280073 8408300146 8408010175 8408130592 8408230330	I&E 50-261 G CONTRACT CONTRACT CONTRACT	GALLO,R GALLO,R GALLO,R M GALLO,R M GALLO,R M	8408230091* 8408240263 8408030229* 8408130262* 8408210381*	50-293 G 50-278 B 50-271 G 50-443 G 50-352 G	GLASS, B M GLASS, B M GLENN, J GLOERSEN, W B GLOERSEN, W B	8408070427 8408150443 8408100127 8408010299* 8408240429*	50-322
FLEIBCHMANN,R	8409150602	71-9111	GAMBERG,R C	8408280205	50-413 T	OLDRA, M	8408210180	WASTE MGT
FLETCHER,C D	8408160248	30-269 P	GAMMILL,W P	8408230033	WASTE MQT	GNUGNOLI, G N	8406190514	WASTE MGT
FLORY,C A	8408010327	HASTE MOT	GAMMILL,W P	8408280338	WASTE MGT	GODDARD, R J	8408070368	50-155 G
FLOYD,J R	8408200531	30-289 G	GARBER,I	8408070288*	50-305 F	GODDARD, R J	8408130294	50-441 G
FLOYD,J R	8408220390	30-289 H	GARCIA,P J	8408210120*	40-2259	GODDARD, R J	8408200250	50-322 G
FLUEHR, J FLUEHR, J J FLY, J FLYNN, S F FOGARTY, D J	8408280343 8408240230 8408100153 8408140146 8408210479	50-285 8 50-285 8 NUREQ 50-400 T 50-342 Q	GARCIA,P J GARCIA,P J GARCIA,P J GARCIA,P J GARCIA,P J	8408210143* 8408240116 8408240163 8408240185 8408240380	40-4492 40-299 40-299 40-299 40-299	GODDARD, R J GODDARD, R J GODDARD, R J GODDARD, R J GODDARD, R J	B408270082 B408270088* B408270137 B408270164 B408280424	50-322 G 50-322 G 50-155 G 50-155 G
FOLEY, H J FOLEY, H J FOLEY, W J	8408010300* 8408240363* 8408070272 8408130265 8408310084	50-247 0 50-317 0 NUREG NUREG NUREG	GARCIA, P J GARCIA, P J GARCIA, P J GARCIA, R GARCIA, R	8408270037 8408270058 8408270228 8408100121 8408140200	40-279 40-279 40-8084 TOPREP TOPREP	GODFREY.D A GODY.A GODY.A T GODY.A T GODY.A T	8408130157 8408080166* 8408080242* 8408070051* 8408150455*	PT21 50-387 G 50-244 G 50-277 G 50-333 G
FONTANA, M H FORD, E J FORNEY, W FORNEY, W FORNEY, W L	8408230077 8408270382* 8406140104* 8408200324 8408230233*	50-327 P 50-327 Q 50-456 Q 50-483 S 50-483 Q	GARDE, B P GARDE, B P GARDE, B P GARDNER, R N GARDNER, R N	8408170223* 8408170312* 8408270336* 8408170166* 8408170181*	50-329 G 50-329 T 50-329 T 50-329 A 50-329 G	H C'6baed706 H C'6baed706 H C'6baed706 B C'6baed706	8408100110 8408010222 8408070446 8408220161 8408270355	50-275 P 50-478 K 50-478 A 50-478 A 50-498 A
FORNEY, W L	8408230480*	50-358 G	GARDNER, R N	8408220064*	50-329 T	R CLDBERG.J R CDLDBERG.J R R CDLDBERG.J R R CDLDBERG.J R R CDLDBERG.J R	8408010194	50-287 0
FORNEY, W L	8408270561*	50-456 G	GARLAND, W	8408240040	40-8727		8408090415	50-287 0
FORTUNA, R	8408020174*	FOIA	GARNER, D J	8408200567	50-483 G		8408270072	50-287 0
FORTER, D O,	8408010336	50-424 H	GARNER, L	8408270269*	50-321 G		8408280409	50-289 0
FORTER, D O	8408040003	50-424 F	GARNER, L	8408270536*	50-261 G		8408290012	50-289 0
FOSTER, D O	8408070023	50-424 8	GARNER, L F	8408140027*	50-400 T	ODLDEN, M P	8408150129	50-244 J
	8408130412	50-424 A	GARRISON, R F	8408150542	71-6346	GOLDMANN, K	8408140469	71-9016
	8408130474	50-424 A	GAUTAM, A	8408300196*	50-440 G	GOLDMANN, K	8408140476*	71-9016
	8408170301	50-424 A	GAUTAM, A	8408300220*	50-341 G	GOLDMANN, K,	8408150594	71-9016
	8408240367*	50-424 Q	GAUTAM, A B	8408300121*	50-456 G	GOLDMANN, K	8408150647	71-9016
FOSTER.D O	8408270430*	50-424 Q	GAYLEY, J	8408010249	50-454 T	GOLDBTEIN, I L	8408240248*	50-445 T
FOSTER.D O	8408280208	50-424 A	GEARS, G	8408210237	50-278 P	GOLDBTEIN, I L	8408240248*	50-445 T
FOSTER.D O	8408300346*	50-424 Q	GEARS, G E	8408220527	50-277 P	GONZALES, R O	8604040738*	50-327 A
FOSTER.L C	8408270221*	50-335 Q	GEKAS, G W	8408020208	50-289 G	GOODMAN, L S	8408140184	50-407 S
FOSTER.L E	8408270492*	50-413 Q	GEORGE, J B	8408030153	50-445 A	GOODMAN, L S	8408140309	50-407 S
FOWLER, L FOWLER, L FOX, M J FOX, R A FRALEY, R F	8408010267 8408010267 8408070140* 8408270171 8205240603*	50-424 0 50-424 0 WASTE MGT NUREG 50-327 0	GEORGE, J B GEORGE, J B GEORGIEV, G B GERDEMAN, F W GERDEMAN, F W	8408040184 8408170065 8408170117* 8408130272 8408240047	50-445 R 50-445 R 50-443 G 40-8674 40-8674	GONTD'C H GONTD'C H GOLWAN'N W GOLDMIN'M F	8408290360 8408130105 8408280205 8408140060* 8408070376	70-1151 WARTE MOT 50-413 T 50-329 A 50-3 G
FRANCE, Q M	8408020223*	70-8	GERDEMAN, F W	8408240351	40-7867	GRACE, J N	8408160077	GA777
FRANCE, G M	8408200241*	50-155 G	GERDEMAN, F W	8408240410	40-8678	GRACE, J N	8408160156	GA777
FRANKEL, M. R	8408310194*	50-454 Y	GERRETS, T F	8408010399	50-382 8	GRADY, W D	8408020132	50-280 F
FRANKEL, M R	8408310194*	50-454 T	GERRETS, T F	8408030296	50-382 8	GRAEBBER, K L	8408060270	50-304 S
FRANZ, W D	8408220151	50-456 D	GERRETS, T F	8408040032	50-382 8	GRAEBSER, K L	8408070047	50-304 S
FREDERICKSON, P	8408240286	50-328 B	GERRETS, T F	8408040061	50-382 B	GRAESSER, K.L.	8408070326	50-304 S
FREDERICKSON, P	8408280267	50-327 B	GERRETS, T F	840807027	50-382 B	GRAESSER, K.L.	8408070404	50-275 B
FREEMAN, M D	8408240339	40-8768	GERRETS, T F	8408140180	50-382 B	GRAESSER, K.L.	8408130405	50-304 S
FREEMAN, M D	8408240377	40-8768	GERRETS, T F	8408140221	50-382 B	GRAESSER, K.L.	8408130456	50-304 S
FREI, M W	8408070063	WASTE MOT	GERRETS, T F,	8408140228	50-382 B	GRAESSER, K.L.	8408130604	50-275 S
FRISCH.R R	8408070378	50-255 8	GERRETS: T F	8408240407	50-382 8	GRAESSER, K. L	8408160122	50-275 R
FRIBHMAN,B	8408140477	WASTE MOT	GERRETS: T F	8408280436	50-382 8	GRAESSER, K. L	8408140150	50-275 B
FRYE,J H	8408080201	50-358 9	GERRETS: T F	8408280440	50-382 8	GRAESSER, K. L	8408200547	50-304 B
FRYE,J H	8408080237	50-142 0	GERRETS: T F.	8408270131	50-382 8	GRAESSER, K. L	8408230514	50-275 B
FRYE,J H	8408220288	50-70 9	GERRETS: T F	8408270137	50-382 8	GRAESSER, K. L	8408240042	50-275 B
FRYE, J H	8408310104	50-358 0	GERRETB.T F	8408270145	50-382 6	GRAEBBER: K L	8408300093	50-295 8
FUHRMAN, G R.	8408270535	50-317 R	GERRETB.T F	8408300521	50-382 8	ORAEBBER: K L	8408300136	50-295 R
FULLER, A G	8408140023*	50-400 T	GERVERB.J H	8408210087	WASTE MOT	GRAEBBER: K L	8408310168	50-295 F
FULLER, C	8408230457*	50-267 R	GEWEHR.B	8408070274	50-370 8	GRAHAM: D	8408160526	50-302 R
FULLER, C.	8408230459*	50-267 R	GEWEHR.B	8408150221	50-367 8	GRAMM: R A	8408240253*	50-410 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGURY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
GRANELEY. G W	8408080144	40-8681	QUO, J S	8408150569*	50-346 P	HARDGROVE, T W	8408270093	40-2259
GRANT, P	9408010170	50-320 s	QUSTE, W J	8408070154*	50-416 G	HARE, S M	8408280085*	50-254 q
GRANT, P	8408010174	50-320 s	QUTHR IE, S	8408030179*	50-155 G	HARMON, D F	8408160257	DRG
GRANT, P	8408010220	50-320 s	QUTTERMAN, A H	8408080186	50-498 G	HARPSTER, T L	8408150455*	50-333 q
GRANT, P	8408010230	50-320 s	QUTTERMAN, A H	8408080186	50-498 G	HARRAN, G	8408230431	50-245 R
GRANT, P J	8408010055	50-320 R	GUTTMAN, D	8408270342	50-458 M	HARRELL,P H HARRINGTON,R M HARRINGTON,T E HARRINGTON,W D HARRINGTON,W D	8408070160*	50-313 Q
GRANT, P J	8408010090	50-320 P	HAFEMEISTER, D	8408310212	PR		8408130001	NUREQ
GRANT, P J	8408010100	50-320 P	HAFEMEISTER, D	8408310215*	PR		8408100008	50-293 Q
GRANT, P J	8408010105	50-320 P	HAGAN, T F	8408060017*	CONTRACT		8408020130	50-293 P
GRANT, P J	8408010242	50-320 P	HAGAN, T F	8408060025*	CONTRACT		8408030022	50-293 B
GRANT, P J GRANT, P J GRANT, P J GRANT, W B GRANT, W B	8408070252 8408070555 8408230425 8408150547# 8408230480*	50~320 R 50~320 R 50~287 R 50~263 G 50~358 G	HAGANIT F. HAGANIT F. HAGANIT F. HAGANIT F HAGANIT F	8408060037* 8408060040* 8408060048* 8408060214* 8408080067*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	HARRINGTON, W D	8408060005 8408080503 8408070114 8408070248 8408190046	50-273 P 50-273 R 50-273 S 50-273 P 50-273 B
GRAVES:R H	8408230482	50-213 8	HAGAN, T F	8408080480*	CONTRACT	HARR ENGTON, W D	8408100099	50-293 8
GRAY:E H	8408150370*	50-272 0	HAGAN, T F	8408090510*	CONTRACT		8408140239	50-293 P
GRAY:E H	8408170117*	50-443 0	HAGAN, T F	8408200597*	CONTRACT		8408140230	50-293 P
GRAY:E H	8408210517*	50-336 0	HAGAN, T F	8408200506*	CONTRACT		8408140231	50-293 P
GRAY:E H	8408270410*	50-309 0	HAGAN, T F	8408210032*	CONTRACT		8408130033	50-293 Q
GREENE.T R GREENMAN, E GREENMAN, E GREENMAN, E C GREEVES, J T	8408040101* 8408030157 8408070205 8408080443 8408220324	50-373 F 50-388 B 50-27 B 70-364 HASTE MOT	HAGAN, T.F. HAGAN, T.F. HAGAN, T.F. HAGAN, T.F. HAGAN, T.F.	8408210044* 8408210047* 8408270080* 8408270404* 8408240094*	50-206 P CONTRACT CONTRACT CONTRACT CONTRACT	HARRINGTON, W D	8408150087 8408160033 8408160041 8408160074 8408160368	50-293 P 50-293 P 50-293 P 50-293 R 50-293 F
GREGERAL R	8408010341*	50-454 0	HAGAN, T.F.	8408270349*	CONTRACT	HARRINGTON,W D HARRINGTON,W D HARRINGTON,W D HARRINGTON,W D HARRINGTON	8408160374	50-293 F
GREGERAL R	8408020223*	70-8	HAGAN, T.F.	8408300237*	50-289 P		8408220133	50-293 P
GREGERAL R	8408080494*	50-275 0	HAGAN, T.F.	8408310088*	CONTRACT		8408300198	50-293 P
GREGERAL R	8408150381*	50-440 0	HAGEN, E.W.	8408270190	MUREO		8408300348	50-293 S
GREGERAL R	8408150406*	50-244 0	HAGEN, E.W.	8408270198	MUREO		8408150514#	50-322 T
GREGER.L R	8408150547*	50~263	HAGEY, H	8408080020	CONTRACT	HARRIS,J D	8408270170	NUREQ
GREGER.L R	8408200241*		HAGGARD, D. L	8408290171	MUREO	HARRIS,J D	8408270178	NUREQ
GREGER.L R	8408270070*		HAISFIELD, H	8408230027	WASTE MOT	HARRIS,J R	8408140084#	50~400 T
GREGER.L R.	8408300164*		HAIST, D	8408220139	50-361 B	HARRIS,M B.	8408240172	50~331 S
GREGG.H	8408080530*		HAIST, D	8408280078	50-362 B	HARRIS,R H	8408270242#	50~410 Q
OREGORY, M OREGORY, M GREGORY, W B ORIDLEY, R L ORIDLEY, R L	8408070105 8408070105 8408140146 8408130173* 8408170262*	50~445 T 50~445 T NUREO 50~331 P 50~243 P	HAIST, D P HALL, B L HALL, B L HALL, D P HALL, D P	8408080497* 8408070409* 8408130446* 8408060366 8408070219	50-344 G 50-370 G 50-338 G 50-461 B 50-461 R	L L,NOEIRRAH U L,NOEIRRH U L,NOEIRRH U L,NOEIRRH U L,NOEIRRH	8408030074* 8408070173 8408130399 8408130702* 8408230312*	50-329 G 50-329 A 50-329 A 50-329 G
GRIDLEY, R L.	8408270175*	50-331 P	HALL, D P	8408070460*	50-461 G	HARRIBON, J J	8408240144*	50-329 Q
GRIFFIN, J M	8408150180	50-313 P	HALL, D P	8408080540	50-461 S	HARRIBON, B F	8407230153	NUREQ
GRIFFIN, J M	8408220313	50-313 P	HALL, D P	8408130238	50-461 S	HARRIBON, B F	8408070117	GA999
GRIFFIN, J M	8408310231	50-313 P	HALL, D P	8408270135	50-461 A	HARROLD, K	8408060197*	50-70 Q
GRIFFITH, J D	8408270319	PR	HALL, D P	8408270318	50-461 S	HARBHBARGER, J	8408220238	WASTE MOT
ORDTENHUIS, M	8408070218	50-324 P	HALL: D P	8408280094	50-461 A	HARBHE, B L	8408070106*	COMMISSION
GROTENHUIS, M	8408210009	50-325 P	HALL: D P	8408300022	50-461 B	HART, R D.	8408010311	50-251 B
GROVES, D N.	8408300040*	50-263 Q	HALL: D P	8408300076	50-461 B	HART, R D	8408030237	50-250 B
GRUMLEY, J E	8408270307	50-454 Q	HALL: D P.	8408300210	50-461 B	HART, R D	8408080230	50-250 B
GUCWA, L T	8408070141	50-366 Q	HALL: D P.	8408300224	50-461 B	HART, R. D	8408270203	50-250 B
GUCHA, L T	8408070148	50-32! P	HALL, R	8408090174	50-267 8	HARTMAN; 8 L	8408220367	50-445 T
GUCHA, L T	8408130379	50-32! F	HALL, R E.	8408060057*	50-382 9	HARTMAN; 8, L	8408220367	50-445 T
YCHA, L T	8408150242	50-366 P	HALL, R E.	8408060180*	50-482 9	HARTMAN; W C	8408030041	GA999
CHA, L T	8408210175	50-366 P	HALL, R E	8408160523*	50-482 9	HARVEY; C D	8408310075	NUREG
CHA, L T	8408210357	50-32! P	HALL, R. E	8408200052*	50-272 9	HARVEY; M D	8408060431	WASTE MOT
CHALL T	8408210474	50-321 P	HALL.R E. HALL.R E. HALL.R E. HALL.R E. HALL.R E	8408230466*	50-445 Q	HABBE,R.	8408010285*	50-341 Q
CHALL T	8408230251	50-321 P		8408230466*	50-265 G	HABBELL,D.F	8408270151	50-322 Q
CHALL T	8408270247+	50-321 Q		8408230522*	50-267 Q	HABBELL,D.F.	8408300129	50-338 Q
CHALL T.	8408280183	50-366 Q		8408270007*	50-458 Q	HATE,K.V	8408140023*	50-400 T
CHALL T	8408280239	50-321 Q		8408270104*	50-296 G	HAUQHEY,M.F	8408060409	50-410 F
JCHA.L T	8408300024	50-321 P	HALL, W. J	6408140194*	50-206 P	HAUGHEY,M F	8408080164	50-410 E
UCHA.L T	8408300072	50-321 I	HALLMAN, O W	6408280205	50-413 T	HAUGHEY,M F	8408200148	50-410 E
GUCHA.L T	8408300115	50-366 P	HALLBTROM, G A	6408140081*	50-400 T	HAUGHEY,M F	8408310267	50-410 A
GUEY.C N	8408010287*	50-206 P	HALMAN, E L	6408310390*	CONTRACT	HAUGHEY,M F	8408310351	50-410 E
GUILD.R	8408070443	50-413 Q	MALUB, P	6408310160	XPORTLIC	HAUKINB,D A	8408220397	CONTRACT
GUILD, R GUILD, R GUILD, R GUILD, R GUILD, R	8408070443 8408070443 8408200548 8408200548 8408200548	50-413	HAMADA, Q HAMADA, Q. HAMADA, Q. H HAMILTON, P HAMILTON, P. J	840807000 4* 840807007 1* 8408270346* 8408160074 8408100046	50-341	HANKINB,D.A HANKINB,D.A. HANKINB,EF HANKINB,EF HANKINB,EF	8408270374 8408270347 8408240177 8408240180* 8408240183*	CONTRACT CONTRACT 40-8722 40-8748 40-8748
GUILD, R	8408310205	50-413 Q	Hamilton: P. J.	8408100099	50-273 E	HAWKINS,E.F	8408240207	40-8478
GUILD, R	8408310205	50-413 Q	Hamilton: P. J	8408300348	50-273 E	HAWKINS,EF	8408270040	40-8481
GUILD, R	8408310205	50-413 Q	Hammerich: T	8408060107	50-374 E	HAWKINS,EF	8408270048	40-8768
GUINN, F K.	8408130361*	70-143	Hampton: J. H	8408270169*	50-267 P	HAWKINS,EF	8408270099	40-8827
GUINN, F K	8408270413*	70-143	Hampton: L	8408140102*	50-329 A	HAWKINS,EF	8408270100	40-8678
GUINN, F K.	0409280053*	70-143	HANAN, M	8408220333	50-352 A PR XFORTLIC XFORTLIC XPORTLIC	Hawking.e f.	8408270117	40-8481
GUINN, F K	8409280174	70-143	HANAUER, S. H	8408070413		Hawking.e f	8408270197	40-8064
GUINN, F K	8408280299*	70-143	HANNETT, B. A	8408230562		Hawking.e f.	8408270205	40-8728
GULDEMOND, W G	8408080181*	50-263 Q	HANNETT, B. A	8408230563*		Hawking.e f.	8408280334	40-8768
GULDEMOND, W G.	8408140331*	50-266 Q	HANNETT, B. A	8408310321*		Hawking.f	8408010285*	50-341 G
OULDEMOND, W G	8408280085*	50-254 Q	HANNETT, B. A	8408310325*	XPORTLIC	Hawking.f.	8408060309*	50-456 @
GUNN, H F	8408080032	50-445 T	HANNON, J. L	8408080370	NUREQ	Hawking.f.	8408160217*	50-454 @
GUNN, H F	8408080032	50-445 T	HARBUCK, C. C	8408160237*	50-458 Q	Hawking.f	8408300121*	50-456 @
GUNN, H, F	8408220405*	50-445 T	HARBUCK, C. C	8408220500*	50-362 Q	Hawking.f.c	8408150511*	50-461 @
GUNN, H F	8408220405*	50-445 T	HARDOROVE, T. W	8408240413	40-2259	Hawking.f.c.	8408170274*	50-329 @

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HAWKINB, F C HAWKINB, F C HAWKINB, T I HAWKHURET, J HAWXHURET, J	8408230278* 8408300197* 8408200497* 8408230235* 8408230221*	50-373 Q 50-305 Q 50-400 Q 50-220 Q 50-333 Q	HIATT, B L. HIGGINBOTHAM, L HIGGINBOTHAM, L HIGGINBOTHAM, L HIGGINBOTHAM, L HIGGINBOTHAM, L	8408070245 8408060274 8408070276 8408070331 8408130140	50-440 G WASTE MGT WASTE MGT WASTE MGT WASTE MGT	HOPOVICH'A A HOPOVICH'A A HOPOVICH'A A HOPOVICH'A A	8408210558 8408280037 8408280277 8408300075 8408130007	50-482 50-482 50-483 50-482 NUREG
HAYES, B B HAYES, B B HAYES, B B HAYES, D W HAYES, J G	8408020194* 8408020196* 8408170311 8408070221* 8408010304	FOIA 50-327 G 50-287 G 50-454 G 50-361 S	HIGGINBOTHAM, L HIGGINBOTHAM, L HIGGINBOTHAM, L HIGGINBOTHAM, L HIGGINBOTHAM, L	8408140358 8408160051 8408200208 8408200452 8408220219*	TOM STEAM TOM STEAM TOM STEAM TOM STEAM TOM STEAM	HDN, A HDOB, D HDOB, D HOOD, B	8408080497* 8111240044* 8201050063* 8408020188* 8408020202*	50-344 50-327 50-327 50-327 50-327
HAYNES, J G HAYNES, J G HAYNES, J G HAYNES, J G HAYNES, J G	8408030123 8408060034 8408060039* 8408060223 8408070379	50~204 F 50~361 B 50~361 B 50~361 B 50~361 B	HIGOINBOTHAM, L HIGOINBOTHAM, L HIGOINBOTHAM, L HIGOINBO E HIGOINBO C	8408230031 8408230085 8408230100 8408140454 8408220424*	MASTE MOT MASTE MOT MASTE MOT 50-354 D 50-445 Q	ноор, р наор, р наор, р наор, р наор, р	8408140526* 8408150027* 8408170320* 8408210377* 8408210379*	50-327 50-327 50-327 50-329 50-329
HAYNES, J G HAYNES, J G HAYNES, J G HAYNES, J G	8408080487 8408070418 8408140216 8408170057 8408240084	50-361 8 50-362 8 50-206 8 50-361 9 50-361 8	HIGGINB.R L HILDEBRAND.J E HILDENBRAND.P HILDENBRAND.P HILDENBRAND.P	8408310302* 8408070203 8408240180* 8408240183* 8408240333*	50-255 0 50-320 0 40-8768 40-8768 40-8584	HOOD, D S HOOD, D S HOOD, D S HOOD, D S	8408210384* 8408210446* 8203020030* 8301190487* 8408020178*	30-329 50-329 50-329 50-329 50-329
HAYNEB, J G HAYNEB, J G HAYNEB, J G HAYNEB, J G HAXELTINE, J	8408240200 8408280225 8408280274 8408300472 8408210518*	50-362 \$ 50-361 \$ 50-361 \$ 50-361 \$ 50-352 A	HILDENBRAND, P HILDENBRAND, P HILDENBRAND, P HILDENBRAND, P HILDENBRAND, P	8408240385 8408270040 8408270048 8408270117 8408280334	40-8674 40-8681 40-8768 40-8681 40-8768	HOOD, D 8 HOOD, D 8 HOOD, D B HOOKS, R. W HOOPER, R L	8408030004* 8408030013* 6408150709* 8408310179* 8408130081*	50-329 50-329 50-329 50-454 Waste Mot
HEARRON, T HEBDON F J HECKER, G E HEETHER, W KEETHER, W	8408170304* 8408070026 8408270147* 8408210164 8408210169	50-327 T DRQ 50-412 E XPORTLIC XPORTLIC	HILL.C Z HILL.C Z. HILL.D HILL.D. HILL.P.W	8408240417 8408270238 8408090019* 8408290349* 8408220080*	40-8584 40-8584 50-397 @ CONTRACT CONTRACT	HODTEN, B G HOPKE, P K HOPKINS, J HOPPER, A HOPPER, A	8408020079 8408030276 8408220427 8408060014 8408060018	NUREQ 50-151 50-375 CONTRACT CONTRACT
HEHL, C W HEHL, C W HEHL, C W HEIDENREICH, J HEIDER, L H.	8408200271* 8408270187* 8408270572* 8408140517* 8408100053	50-416 G 50-395 G 50-395 G CONYRACT 50-29 G	HILL, T V HILL, T. V. HILL, T. V HILL, T. V HILL, T. V	8408030082 8408030084 8408150193 8408270215 8408240211	WASTE MOT WASTE MOT 40-6500 WASTE MOT 40-1341	HOPPER, A HOPPER, A HOPPER, A HOPPER, A HOPPER, A	8408060031 8408060041 8408060211 8408080057 8408210042	CONTRACT CONTRACT CONTRACT CONTRACT 50-206
HEIMAN, D HEINE, J HEIBHMAN, R HELGEGON, K A	8408060432 8408230301* 8408220276 8408170117* 8408010024	XPORTLIC 50-341 E 50-287 G 50-443 G 70-820	HILLE, D E HIND, J. A. HINKLE, K HINKLE, K A HINTZ, D C	8409150475* 8409240429 8409200314 8409150724 8409060244	50-341 G 50-305 G XPDRTLIC XPORTLIC 50-305 S	HORIN.W A HORIN.W A HORIN.W A HORIN.W A HORIN.W A	8408080413 8408080413 8408130305 8408130305 8408230317	50-445 50-445 50-445 50-445 50-445
HELDEBON, K. A. HELLER, J. K. HELLER, L. W. HELTEMEB, C. J. HELTEMEB, C. J.	8408020074 8408300188* 8110170801* 8404010162* 8408040067	70-820 50-315 G 50-327 A 50-366 S MISC	HINTZ,D C. HINTZ,D C HINTZ,D C HINTZ,D C HINTZ,D C	8408070275 8408070272 8408080033 8408080510 8408100017	50-305 F 50-305 F 50-305 8 50-305 8 50-305 F	HORIN.W.A HORIN.WA HORIN.WA HORIN.WA HORIN.WA	8408230319 8408280083 8408280083 8408310216 8408310216	50-445 50-445 50-443 50-445 50-445
HELTEMES, C. J. HELTEMES, C. J. HELTEMES, C. J HELTEMES, C. J HELTEMES, C. J	8408050073* 8408050077* 8408050081* 8408150320 8408220441	MISC MISC NUREO MISC	HINTZ,D C HINTZ,D C HINTZ,D C HINTZ,D C. HINTZ,D C.	8408100078 9408160211 8408220284 8408240199 8408280144	50-305 P 50-305 R 50-305 P 50-305 P 50-305 F	HDRVATH, E HDWARD, J E HDWARD, K E HDWATH, E A HOWE, P W	8409200073 8409030121 8408080083 8408280087 8408140151*	50-346 50-293 50-331 50-346 50-400
HENNICK'Y HENNICK'Y HENDEUBA'M B HENDEUBON'Y D	8110260082* 8408210382* 8408070272 8408130265 8408310084	50-329 8 TOPREP NUREO NUREO NUREO	HINTZ, D.C. HIPSHER, W.M HIRSCH, D. HIRSCH, D HIRSCH, D	8408280475 8408140297 8408070386 8408070474 8408310132	50-305 P WABTE MGT 50-142 G 50-142 G 50-142 P	HOYLE,A HOYLE,A HOYL,G H HOYL,G H	8408280235 8408040038 8408300233 8408070174* 8408230253	50-324 CONTRACT 50-289 50-361 State Pr
HENRIEB, WE HENRY, L. O HENBHAW, E. HENBLEY, KD	8408070182* 8408060162 8406130217 8408080455 8408150545	50-309 P 50-57 F 40-8027 40-8027 70-143	HIRSCH.D HITCHLER.M.J HITCHLER.M.J HOCHBRUECKNER HOCHENDONER.L	8408310209 8408140018* 8408140018* 8406040336 8408140449	50-142 0 50-400 T 50-400 T 50-322 0 50-219 0	HSU, C. HBU, C HU, C K. HUBBARD, F R HUBBARD, R B	8408310355 8408310359* 8408170343* 8408130225* 8408020129	50-278 50-278 50-354 50-287 50-322
HENBLEY, K.D. HERBERT, R.J. HERBORN, D.I. HERBORN, D.I.	8408170012 8408070340 8408070340 8408100087 8408140381	70-143 50-245 8 50-245 8 50-461 A 50-461 E	HODEL, D.P. HODODON, A.P. HODODON, A.P. HODBON, J. HODBON, J.	8408270350* 8408070197 8408070236* 8408070330* 8408200504*	COMMISSION 50-352 0 50-352 T 50-322 G 50-354 G	HUDSDN: G HUDSPETH: J. B. HUETER: L. J. HUETER: L. J. HUGHES: E. A	8408300180* 8408210417 8408010341* 8408270070* 8408010276*	50-263 50-364 50-454 50-341 50-206
HERING, R.F. HERING, R.F. HERMANN, R.A. HERMANN, R.A. HERMANN, R.A.	8405140248 8404080107 8408040278 8408040332 8408150423*	50-315 Q 50-316 P 50-220 P 50-220 P 50-273 P	HOPFMAN, J. HOPMAN, L. A HODAN, R HODAN, R. T. HODAN, R. T.	8408160344 8408020070# 8408150541# 8408150305# 8408200544#	50-413 J 50-133 P 50-333 Q 50-317 Q 50-247 Q	HUGHEG,E A HUKILL,H D HUKILL,H D HUKILL,H D. HUKILL,H D	8408010287* 8408020137 8408030004 8408030088 8408030107*	50-206 50-289 50-289 50-289 50-289
HERNAN, R. W HERNAN, R. W. HERRICK, R. C HERRINOTON, C. C, HERBGH, M. M.	8408130241* 8408140322* 8407090037* 8408130033 8408150237	50-329 A 50-329 A 50-219 P 70-1308 XPORTLIC	Hogan, T. F. Hoggard, B. T Hoggard, B. T Holahan, G. M Holbrook, K. L	8408270376# 8408080023 8408220396# 8408180433# 8408290171	CONTRACT 50-445 T 50-445 T REVIEW GRP NUREO	HUKILL, H. D. HUKILL, H. D. HUKILL, H. D. HUKILL, H. D. HUKILL, H. D.	8408070238 8408070280 8408080300 8408070144 8408130218	50-289 50-289 50-289 50-289
HERBCH; M M. HERBCH; M M. HERBCH; M. M. HERBCH; M. M. HERBCH; M M.	8408150717 8408150730 8408200493* 8408230488 8408230498	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	MOLCOMBE, J C HOLDEN, C. HOLLAR, D E HOLLENBACH, D. HOLLOP, E. E	8408070194# 8408270410# 8408130288 8408300407# 8408270074	50-361 P 50-309 Q 50-400 G 50-528 Q HASTE MOT	HUKILL, H D HUKILL, H D HUKILL, H D, HUKILL, H D, HUKILL, H, D	8408130343 8408140406 8408140411 8408160182 8408220218	50-289 50-289 50-289 50-289 50-289
HERBCH, M. M HERBHEY, B P HIATT, B L. HIATT, B. L. HIATT, S. L	8408230510 8408140540 8408070176 8408070202* 8408070231	XPORTLIC 50-352 0 50-440 0 50-440 0 50-440 0	HOLLOP, E E HOLMBERO, J HOLMEB, H. H HOLMEB, H. H HOLMEB, H. H	8408270078* 8408270309 8408270284* 8408270292* 8408270296*	HASTE MOT 50-454 Q 50-454 E 50-454 E 50-454 E	HUKILL, H B HUKILL, H B HUKILL, H B HUKILL, H B	8408220363 8408240066 8408240167 8408270195 8408300503	50-289 50-289 50-289 50-289 50-289

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
HULL, R E HUMPHREY, H H HUMPHREYS, P HUNNICUTT, D HUNNICUTT, D	8408160504* 8408080334* 8408010166 8408230152* 8408150102*	50-313 G PR NVREG 50-445 G 50-445 G	T L, NOOUAL 9 C, NOOUAL 9 C, NOOUAL 9 C, NOOUAL 9 C, NOOUAL	8408070095* 8408150375* 8408160237* 8408160515* 8408200292*	50-458	JOHNSON, D P JOHNSON, D R JOHNSON, E H JOHNSON, E H	8408150514# 8408140071# 8408030043 8408030044 8408060092	50-322 T 50-329 A 50-458 A 50-298 Q 50-482 Q
HUNNICUTT, D M	8408150440* 8408150555* 8408160037* 8408160500* 8408270108*	50-445 Q 50-445 Q 50-445 Q 50-445 Q 50-458 Q	9 L. ADDUAL 9 L. ADDUAL 9 L. ADDUAL 9 L. ADDUAL 9 L. ADDUAL	8408200304* 8408200326* 8408220157* 8408220256* 8408220500*	50-49B	Н 3 ИОВИНОГ Н 3 ИОВИНОГ Н 3 ИОВИНОГ Н 3 ИОВИНОГ	8408040175 8408040202 8408040307 8408070225 8408070034	50~482 Q 50~298 Q 50~285 Q 50~267 P 50~298 Q
HUNSTAD, A HUNT, S W HUNT, S H HUNTER, D R HUNTER, D R	8408240238 8408150566* 8408150571* 8408070121 8408100057	50-282 S 50-329 A 50-329 A 50-313 Q 50-285 Q	9 tindduau 9 tindduau 9 tindduau 9 tindduau 9 tindduau	8408230013* 8408270007* 8408270500* 8408270104* 8408270108*	50-298	оричаом, Е Н оричаом, С Н оричаом, Е Н оричаом, Е Н	8408090070 8408090090 8408090150 8408100033 8408100107	50-382 Q 50-458 Q 50-313 Q 50-458 Q 50-278 Q
HUNTER, D R	8408100067 8408100097 8408100137 8408140266 8408160498	50-482 0 50-445 0 50-482 0 50-445 V 50-313 0	JENK INS' O B JENK INS' O B JENK INS' O B JEVM INS' O B	8408230215 8408270317* 8408270423* 8408270447* 8408270531*	GA979 50-335 G 70-143 50-369 G 70-27	н эмовинос н эмовинос н эмовинос н эмовинос н эмовинос	8408100131 8408100132 8408140091 8408150312 8408150372	50-382 0 50-498 0 50-458 0 50-313 0 50-313 0
HUNTER, DR HUNTER, DR HUNTER, DR HUNTER, DR HUNTER, DR	8408160520 8408230451 8408280075 8408290113 8408290140	50-482 Q 50-285 Q 50-285 V 50-368 Q 50-285 Q	TENEIM H TENKINSIG K TENKINSIG K TENKINSIG K	8408280082* 8408280289* 8408280495* 8408300206* 8406010037	50-302	H 3 MOSNHOL H 3 MOSNHOL H 3 MOSNHOL H 3 MOSNHOL H 3 MOSNHOL	8408160230 8408160455 8408160507 8408160511 8408170282	50-458 Q 50-458 Q 50-267 Q 50-458 Q 50-498 A
HUNTER, DR HURLEY, J HUSAIN, A HUXTABLE, WP HYDER, JE	8408290172 8408280143 8408070478* 8408130007 8408010308*	50-368 Q 50-416 F 50-29 P NUREG 50-151 Q	76N2° M H 76N2° M H 76N3° M H 76N3° M H	8408010216 8408060082 8408070356* 8408070440 8408080277	50-341 E 50-341 G 50-341 G 50-341 A 50-341 F	H 3 YOSUHOC H 3 YOSUHOC H 5 YOSUHOC H 5 YOSUHOC	8408200290 8408200299 8408200316 8408200381 8408210090	50-458 Q 50-478 Q 50-458 Q 50-267 P 50-498 Q
IDEKER,R.L IDEKER,R.L IDEKER,R.L IGNATONIE,A IGNATONIE,A J	8408020154 8408150156 8408170392 8408140324 8408230001	70-143 70-143 70-143 50-370 8 50-370 S	76N8' # # 76N8' # # 76N8' # # 76N8' # #	8408080305 8408080311 8408080316 8408090033 8408090062	50-341 F 50-341 S 50-341 S 50-341 S 50-341 S	H 3 MOBUHOL H 3 MOBUHOL H 3 MOBUHOL H 3 MOBUHOL H 3 MOBUHOL	8408220152 8408230010 8408230471 8408270003 8408270489	50-458 Q 50-298 Q 50-267 Q 50-458 Q 50-298 Q
IGNATONIE, A J IGNATONIE, A J IGNATONIE, A J IMERO, E IMBRO, E V	8408240290 8408240329 8408280158 8408010345* 8408010343	50-370	JENS'M H JENS'M H JENS'M H JENS'M H	8408070071 8408130163* 8408140016 8408160444 8408810077	50-341 8 50-341 9 50-341 8 50-341 8 50-341 A	H 3 MOENHOL H 3 MOENHOL H 3 MOENHOL H 3 MOENHOL	8408270500* 8408270101 8408270103 8408310040 8408310132	50-298 G 50-298 G 50-458 G 50-267 F 50-458 A
IPPOLITO, T IPPOLITO, T A IPPOLITO, T A IRELAND, R E IRELAND, R E	8408150027* 8408070505 8408140066 8408060325* 8408160237*	50-327 A 50-445 A 50-445 E 50-382 O 50-458 G	76 M 27 M 4 76 M 27 M 4 76 M 27 M 4 76 M 27 M 4 76 M 27 M 4	6408220135 6408220175 6408220193 6408220209 6408230274	50-341 8 50-341 8 50-341 8 50-341 9 50-341 F	JOHNBON, FR JOHNBON, OE JOHNBON, OE JOHNBON, OE JOHNBON, OE JOHNBON, O, E	8408210518* 8408010211 8408070422 8408070171 8408130270	50-352 A 50-413 Q 50-413 Q 50-413 Q 50-413 Q
IRELAND,R E IRELAND,R E IRWIN,D P RWIN,D P RWIN,D P	8408160516* 8408270500* 8408070274 8408070274 8408070442	50-267 Q 50-392 Q 50-322 Q 50-322 Q 50-322 Q	JENS, H H JENS, H H JENS, H H JENS, H H	8408230274 8408230387 8408270352* 8408300045 8408300061	50-341 E 50-341 F 50-341 Q 50-341 B 50-341 B	3 6 YOSHHOC 3 6 YOSHHOC 5 9 YOSHHOC 6 9 YOSHHOC 7 9 YOSHHOC	8408200481 8408200497 8408200508 8408200511* 8408270092	50-413 Q 50-413 Q 50-413 Q 50-413 Q 50-413 Q
RWIN.D P RWIN.D P RWIN.D P RWIN.D P RWIN.D P.	8408070442 8408070448* 8408070448* 8408080428 8408080428	50-322	NENS' M H NENS' M H NENS' M H NENS' M H	8408300069 8408300207 8408300216 8408300223 8408300251	50-341 8 50-341 8 50-341 8 50-341 8 50-341 8	70HN80M, 7 0 NOBNHOL 10 NOBNHOL 2 NOBNHOL 10 NOBNHOL	8408270109 8408270119 8408280455 8408100054* 8408230091*	50-413 0 50-413 0 50-413 0 50-250 F 50-293 0
IRWIN.D P IRHIN.D P IBLEY.T. JABLONGKI.F J JACKA.B	8408140003 8408140003 8408160497 8408240321* 84080808227	50-322 Q 50-322 G 50-344 S 50-461 Q State Prog	JERREE, C JERSE, J L JERSEN, C M JERSEN, C M	84083300257 8408310188 8408030066 8408240270 8408210120*	50-341 B 50-341 F 50-112 F GA999 40-2259	70 T VOURON 1 C 70 T VOURON 1 C 70 T VOURON 1 C 70 T VOURON 1 C	8408040013 8408150485* 8408010253 8408020217 8408230420	50-275 B 50-322 T 50-424 G WASTE MGT WASTE MGT
JACKIH, I N JACKSON, G. JACKSON, G. JACKSON, G	8408290370* 8408010028* 8408010031* 8408130292* 8408140480*	50-286 Q 71-9163 71-9163 71-184 71-9016	JIERREE, C C JIERREE, C C JIERREE, C C JIERREE, C C JIERREE, C C	8408210143* 8408230481* 8408240192 8408240197* 8408240207	40-4492 40-8102 40-299 40-299 40-8084	201408041 H. R D HOBOHADO D HOBOHADO D HOBOHADO D HOBOHADO	8408040180* 8408070130* 8408070160* 8408150375* 8408070178	50-482 0 50-313 0 50-313 0 50-313 0 50-382 0
JACKSON, R. E JACKSON, R. E JACOBS, G. K JACOBS, R.	8309270518* 8408140242* 8408280007* 8408300282 8408970053*	50-329 C 50-329 A WASTE MGT NUREC 50-387 C	JIERREE, C C JOHNBON, A D JOHNBON, B D JOHNBON, B D JOHNBON, B D	8408270049 8408100129 8408090019* 8408040263 8408070435	40-8452 1&E 50-397 Q 50-255 S 50-255 F	0 (1994) 10 (1994) 10 (1994) 10 (1994) 10 (1994)	8408300390* 8408070048* 8408070187* 8408070175* 8408160327*	50-344 Q 50-414 H 50-266 Q 50-255 Q 50-346 Q
JACOBS, R. H JAFFE, D H JAFFE, D H JARDL, J C	8408200041* 8403290354 8408200320 8408240015 8408160071	50-397 G 50-317 8 50-317 P 50-317 P GA999	JOHNSON, B. D. JOHNSON, B. D. JOHNSON, B. D. JOHNSON, B. D.	8408080331 8408140295 8408140388 8408160279 8408170364	50-255 P 50-255 F 50-255 P 50-255 8 50-255 F	JONES, D T, JONES, D W JONES, D, W JONES, D, W	8408010156* 8408170286 8408270225* 8408300374* 8408300401*	50-412 F 50-538 F 70-1151 70-27 70-27
L,00AC C,00AC C,00AC C,00AC C C,00AC C C	8408240074* 8408010398* 8408080447* 8408150305* 8408080284*	50-334 0 50-387 0 50-219 0 50-317 0 50-413 E	JOHNSON, B D JOHNSON, B D JOHNSON, B D JOHNSON, B D	8408230201 8408310054 8408310059 8408310161 8408070279	50~255 P 50~255 S 50~255 S 50~255 Q WABTE MGT	JONES, O. W JONES, O. T JONES, G. T JONES, G. T JONES, G. T	8408310255* 8408030257 8408040113 8408080518 8408090020	70-1151 50-259 8 50-259 8 50-259 8 50-259 9
JAPE, F JAPE, F JAPE, F, JAUDON, J, P	8408270338* 8408270419* 8408270480* 8408280049* 8408060313*	50-321 G 50-390 G 50-413 G 50-390 G 50-285 G	JOHNSON, C, JOHNSON, C E JOHNSON, D JOHNSON, D, M JOHNSON, D P	8408230172 8408290304* 8408150305* 8408080448* 8408150476*	50-317 P 50-498 G 50-322 T 50-324 G 50-322 T	JONES, O. T JONES, O. T JONES, O. T JONES, O. T	8408070341 8408160308 8408160318 8408160317 8408200300	50-257 8 50-257 8 50-257 9 50-257 8 50-257 6

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESS ION NUMBER	SUBJECT CATEGORY
JONES, G T JONES, G T JONES, G T JONES, G T JONES, V H	8408200412 8408270150 8408270366 8408280349 8408220171	50-296 S 50-296 S 50-259 R 50-259 S 50-259 S	AANE, J KANE, J KANE, J KANE, J KANE, J	8408140209* 8408140213* 8408140223* 8408140258* 8408140311*	50-327 A 50-329 A 50-329 A 50-329 G 50-329 A	KELLY, J KELLY, G KELLY, G KELLY, G KELLY, J KELLY, J KELLY, J KELLY, J KELLY, J KELLY, J KELLY, J	8408070523 8408310276 8408070053* 8408060057* 8408030275*	WASTE MGT 50-354 A 50-387 G 50-382 G 50-382 G
JONES, W C JORDAN, E L JORDAN, E L JORDAN, E L JORDAN, E L	8408100062* 8404040322* 8406140070* 8407250227 8408010333	50~285 Q 50-321 F 50-413 F 50-3 Q 50-3 Q	KANE, J KANE, J KANE, J KANE, J KANE, J C	840B140347* 840B150019* 840B150022* 840B150042* 840B140565*	50-329 A 50-329 A 50-329 A 50-329 A 50-329 A	KELLY, J A KELLY, J A KELLY, K KELLY, K	8408040180* 8408160523* 8408270104* 8408070014 8408230428	50-482 Q 50-482 Q 50-298 Q NUREQ 50-286 R
JORDAN, E L JORDAN, E L JORDAN, E L JORDAN, E L JORDAN, E L	8408010337 8408070120 8408100007 8408100021 8408100038	50-3 Q 50-3 Q 50-3 Q 50-3 Q 50-3 Q	KANE, J D KANE, J D KANE, R S KANGA, B K	8306060387* 8408140556* 8408150612* 8408170407 8408030141	50~327 A 50~327 A 50~327 E 50~177 I 50~320 P	KELMERS'Y D KELTA'M J KELTA'M J KELTA'M J	8408030136 8408070369 8408310038 8408270030 8408300282	QA999 50-275 8 50-275 8 WABTE MANA NUREG
JORDAN, E L JORDAN, E L JORDAN, W S JORDAN, W S	8408100055 8408140208 8408210142 8408070286 8408070344	50~3 G 50~3 G 50~3 G PR PR	KANGA, B K KANGA, B K KANGA, B K KANGA, B K KANGA, B K	8408040146 8408040310 8408100130 8408140279 8408140035	50-320 F 50-320 S 50-320 G 50-320 P 50-320 P	KEMPER, J KEMPER, J S KEMPER, J S KEMPER, J S KEMPER, J S	8408210427# 8408020030 8408040232 8408070037 8408070289	50-352 Q 50-352 A 50-352 A 50-352 E
JORDAN, W S JORDAN, W S JORDAN, W S JORDAN, W S JORDAN, W S	8408130396 8408130396 8408140035 8408140035 8408240234	50-289 G 50-289 G 50-289 G 50-289 G 50-443 G	KANGA, B K KANGA, B K KANGA, B K KANGA, B K KANTOR, F	840B200115 840B240225 840B280076 840B310129 840B150646*	50-320 5 50-320 H 50-320 0 50-320 P 50-341 0	KEMPER, J S KEMPER, J S KEMPER, J S KEMPER, J S KEMPER, J S	B408070513 B408130276 B408130317 B408140303 B408160377	50-352 E 50-352 Q 50-352 A 50-352 E 50-352 E
JOYNER, J JOYNER, J JOYNER, J JOYNER, J JOYNER, J	8408240234 8408030002 8408100127 8408160003 8408160130	50-443 G I&E I&E I&E I&E	KAO.G C KARAM.R A KARMAN.M KARR.J E KARR.J E	8408130420* 8408280175 8408010200 8404010038 8408240148*	50-454 0 50-160 F 50-456 G 50-327 S 50-329 R	KEMPER, J S KEMPER, J S KEMPER, J S KEMPER, J S KEMPER, J B	8408200147 8408200206 8408200262 8408210031 8408210303	50-352 F 50-352 F 50-352 E 50-352 A
JOYNER, J JOYNER, J JOYNER, J JOYNER, J H JUDN	8408210280 8408310045 8408310080 8408030188 8408140401	1&E 50-272	KARRIJ E KARRIJ E KASSNERIG KASSNERIG KATTANIJ	8408240152* 8408240159* 8408130604 8408140428 8408230569*	50-329 R 50-329 R 50-295 S 50-295 F 50-293 Q	EMPER, J S KEMPER, J S KEMPER, J S KEMPER, J S	8408210452 8408210513 8408220119 8408220145 8408230292	50-352 F 50-352 A 50-352 A 50-352 A 50-352 E
JUDBON, V A JUDBON, V A JUDBON, V A	8408210403 8408010181 8408010181 8408010181 8408080390	50-382 A 50-454 G 50-454 G 50-454 G 50-454 G	KAUFMAN, P D KAUFMAN, P D KAUFMAN, P D KAUFMAN, P D KAY, J A	8408080175* 8408150497* 8408160341* 8408310374* 8408010141	50-454	8 L, ABAMBA B L, ABAMBA B L, ABAMBA B L, ABAMBA B L, ABAMBA	8408270161 8408270376 8408280130 8408280177 8408310007	50-352 A 50-352 E 50-352 A 50-352 F 50-352 A
ANTIVN'C V ANDBON'A V ANDBON'A V ANDBON'A V	8408080390 8408080390 8408080395 8408170298 8408030023	50-454 G 50-454 G 50-454 G 50-454 T 50-370 S	A L.YAX A L.YAX A L.YAX A L.YAX A L.YAX	8408020039 8408070373 8408140312 8408210419 8408230162	50-29 P 50-29 F 50-29 P 50-29 P 50-29 P	KEMPER, J S KEMPER, J S KEMPER, J S KEMPER, J S KEMPER, J S	8408310012 8408310018 8408310058 8408310110 8408310124	50-352 A 50-352 G 50-352 S 50-352 G
JULIAN.C A JULIAN.C A JULIAN.C A JUNG-KI,P JUST.R A	8408200271* 8408270347* 8408270382* 8408280471* 8409130007	50-416 G 50-416 G 50-327 G COMMISSION NUREG	KAYBER, H V KAYBER, W V KAYBER, W V KAYBER, W V KEATING, D E	8408090209* 8408140363* 8408230103* 8408230266* 8408160341*	50-316 P 50-261 P 50-261 P 50-315 P 50-341 Q	KEMPER, J G KEMPER, J G KEMPF, C R KENYON, B D KENYON, B D	8408310144 8408310413 8408010151 8408030178# 8408080269	50-352 A 50-352 A NUREG 50-387 Q 50-387 Q
JUSTICE, A D JUSTICE, A D KADAK, A C KADAMBI, P KADAMBI, P	8408220371* 8408220371* 8408280055 8408080288 8408070433	50~445 T 50~445 T 50~271 P 50~269 P TOPREP	KEDDIB, N N KEELEY, G B KEIMIG, R KEIMIG, R KEIMIG, R R	0408070170 0408030064* 0408160002* 0408310065 0408030192*	GA999 50-329 A 50-29 G 50-272 S 50-410 G	KENAON'B D KENAON'B D KENAON'B D KENAON'B D	8408100125 8408310118 8408310214 8408090428 7812070142*	50-387 F 50-387 G 50-387 F 50-390 A 50-329 A
KAFKA,A KAHLE,J B KAHLE,J B KAHLE,J B	8408220333 8408270284* 8408270540* 8408300307* 8408080333	50-352 A 70-27 70-1113 70-1201 PR	KEIMIG.R R KEIMIG.R R KEIMIG.R R KEIMIG.R R KEIMIG.R R,	8408150407* 8408150424* 8408150693* 8408150721* 8408200487*	70-371 50-277 G 50-245 G 50-317 G 50-29 G	KEPPLER,J G KEPPLER,J G KEPPLER,J G KEPPLER,J G	8408070401 8408070480 8408080539 8408130234# 8408130315#	50-10 G 50-483 P 50-456 A 50-327 A 50-329 T
KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N	8408060251 8408210068 8408230435 8408230496 8408300275	50-265 S 50-254 R 50-254 R 50-254 S 50-254 R	KEISER, H W KEISER, H W KEISER, H W KEISER, H W KEISER, H W	8408090142 8408090393 8408090395 8408090396 8408090421	50-388 8 50-388 8 50-387 8 50-387 8 50-387 8	KEPPLER.J G KEPPLER.J G KEPPLER.J G KEPPLER.J G	8408130336* 8408150299* 8408150626* 8408150639* 8408150677*	50-329 A 50-255 G 50-329 A 50-329 G 50-329 G
KALMON,K J KALUZNY,S P KAMMEYER,J C KANAKARIS,G A	8408310053 84080A0386 8408300469* 8408150530* 8408140027*	50-374 S NUREG 50-327 G 50-322 T 50-400 T	KEISER,H W KEISER,H W KEISER,H W KEISER,H W KEISER,H W	8408070439 8408160164 8408200283 8408210290 8408240065	50~387 8 50~388 8 50~387 8 50~387 9 50~387 6	KEBBIEWIN G KEBBIEWIN G KEBBIEWIN G KEBBIEWIN G	8408150689* 8408150706* 8408170119* 8408170232* 8408170263	50-329 A 50-329 A 50-329 G 50-329 G 50-275 G
KANAKARIB, Q A KANE, J KANE, J KANE, J KANE, J	8408140027* 8408020038* 8408020071* 8408020086* 8408020099*	50-400 T 50-329 A 50-329 G 50-329 G 50-329 A	KEISER,H W KEISER,H W KEISER,H W KEISER,H W KEISER,H W	8408240246 8408300189 8408300399 8408300484 8408300489	50-397 8 50-399 5 50-398 8 50-398 8 50-397 8	KEPPLER, J G KEPPLER, J G KEPPLER, J G KERPLER, J G	B408230170 B408240296 B408280147 8408300156 B408270242*	50-493 P 50-315 V 50-315 G 50-255 G 50-410 G
KANE, J KANE, J KANE, J KANE, J	8408020127* 8408020178* 8408020186* 8408020193* 8408030020*	50-329 G 50-329 T 50-329 G 50-329 A 50-329 A	KEITH, H N KEITH, W R KELLER, J C KELLER, J C KELLEY, D L	8408240243 8408140261 8408080294 8408080294 8408150440*	50-333 8 50-331 S 50-445 T 50-445 T 50-445 Q	KERRIG W KERRIGK, J F KESSEL, R KESSLER, J H KESSLER, J J,	8408300287 8408270065 8408010077 8408300282 8408240165	Mureo Maste Mot 50-322 t Mureo 50-354 d
KANE, J KANE, J KANE, J KANE, J	8408030028* 8408030056* 8408140134* 8408140163* 8408140170*	50-329 A 50-329 A 50-329 A 50-329 A 50-329 A	KELLEY, J L	8408160500* 8408020062 8408070273 8408230160 8408230280	50-445 Q 50-413 Q 50-400 Q 50-400 Q 50-413 Q	KETZLACH, N KEV, B W KEY, W J KHLAFALLAH, M Z	8408070266 8408230237 8408150114* 8408070340* 8408170343*	70-2884 50-155 8 71-6346 50-456 0 50-354 0

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION	SUBJE		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
KILBER,WE KILLGORE,MR KILLGORE,MR KIMBALL,J KIMBALL,J	84081307144 84082301224 8408240309 80081307644 83071304234	50-241 P 50-241 P 50-329 A	KOENIOS.R L KOENIOS.R L KOESTER.G L KOESTER.G L KOESTER.G L	8408270330 8408270116 8408020105 8408030012 8408030157	50-397 50-397 50-482 50-482 50-482	? 5 ? F ? A	KUSEKIL T KUSEKIL T KUSHNERIW L KUSHNERIW L KUZCYNSKIIL A	8408090401 8408090405 8408150628 8408170179 8408200283	50-285 S 50-285 S 50-317 F 50-293 F 50-387 S
KIMBALL, J KIMERY, A L KIMLER, D KIMMELMAN, I I KIMNEMAN, J	83071304254 8408020103 8408230435 8408280353 8408160003	50-329 A 40-8027 50-254 R 50-354 H I&E	KOESTER.G L KOESTER.G L KOESTER.G L KOESTER.G L KOESTER.G L	8408100066 8408100075 8408140001 8408140020 8408140237	50-482 50-482 50-482 50-482 50-482	9 9 9 8	KUZD, G B KUZD, G B KUZD, G B LACEY, W S LACEY, W S	8408270386* 6408270439* 8408280329* 8408100092 8408100113	
KINNEMAN.J KINNEMAN.J KINNEMAN.J KINTNER.L KIRK.Q B	8408210280 8408270297# 8408310090 8408310244 8408060241	1&E 40-672 1&E 50-341 A 50-327 S	KOESTER, G L KOESTER, G L KOESTER, G L KOESTER, G L KOESTER, G L	8408140308 8408140337 8408140350 8408160505 8408160514	50-482 50-482 50-482 50-482 50-482	F A S	LACEY,W S LACEY,W S LACKER,D K LAFLEUR,J D LAMBE,W	8408210316 8408210023 8408020110 8408300204* 8408070517	50-334 8 50-334 8 PR 50-369 F 50-456 M
Kirk, Q B Kirk, W F Kirsch, D Kirsch, D F Kirwan, B	8408160269 8408300134 8408220139 8408300149* 8408010166	50-328 S 70-371 50-361 8 50-275 G NUREG	KOESTER.G L KOESTER.G L KOESTER.G L KOESTER.G L KOESTER.G L	8408200119 8408220158 8408220207 8408220217 8408220248	50-482 50-482 50-482 50-482 50-482	5	LAMBE, W LAMBE, W LAMBE, W LAMBE, W LAMBERT, H E	8408130488 8408130590 8408130609 8408150390 8408010287*	50-458 M 50-458 M 50-458 M 50-458 M 50-206 P
KLEIN, B R KLEIN, T J KLEIN, T J KLEINSMITH, M E KLEINSORGE, W P	8408030056* 8408240408 8408270157 8408160132* 8408280046*	50-329 A 40-8584 40-8584 50-324 G 50-261 G	KOESTER, O L KOESTER, O L KOESTER, C L KOESTER, C L KOESTER, C L	8408270389 8408270479 8408270377 8408280193 8408280435	50-482 50-482 50-482 50-482 50-482	A S A V S	LAMBERT, PA LANDSMAN, RB LANDSMAN, RB LANDSMAN, RB LANDSMAN, RB	8408280211* 840815003* 8408170078* 8408170253* 8408170284*	50-331 P 50-329 A 50-329 T 50-329 A 50-329 A
KLEINBORGE,W P KLIKA,J C KLINGLER,G KLOPP,G T KMETY,K L	8408280071* 8408240044 8408010144 8408210344* 8408310087	50-400 g 50-374 s 50-280 g 50-454 g Nureg	KDESTER: © L KDHL, C N KOHLER: A D KOLTAY: P KONWINSKI: Ø R	8408270033 8408070178 8408170255 8408010300* 8408240324	50-482 50-382 50-508 50-247 40-1142	F G G	LANDSMAN,R B LANE,M LANE,M LANE,M	8408240144* 8408200457 8408200537 8408200541 8408230473	50-329 & XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
KNAPP.M R KNAPP.M R KNAPP.M R KNAPP.M R KNAPP.M R	8408010079 8408130099 8408170427 8408200197 8408200480	WASTE MOT WASTE MOT WASTE MOT WASTE MOT	KONWINSKI, G R KONWINSKI, G R KONWINSKI, G R	8408240373 8408270033 8408270041 8408270047 8408270053	40-8698 40-1162 40-2239 40-1162 40-8584	! } !	LANE, M LANE, M LANE, M LANE, M LANE, M	8409230485 8409230493 8409230500 8408230505 8408070171	XPORTLIC XPORTLIC YPORTLIC XPORTLIC XPORTLIC
KNAPP,M R KNAPP,P J KNIGELEY,J R ANIEBER.G W KNICHT,J P	8408240372 8408030148* 8408100037* 8408070094 8105070480*	TOM STEAW 70-371 0 282-00 999AD A 926-00	KONWINSKI, G R KONWINSKI, G R KONWINSKI, G R KONWINSKI, G R KOON, A R	8408270043 8408270044 8408270235 8408270248 8408230507	40-1162 40-277 40-3453 40-8584 50-395		LANE, R C LANGE, R G LANKSBURY, R D LANNING, N LARIVIESE, P	8408230514 8408040045 8408230149* 8408040083* 8408240145	50~295 S WASTE MOT 50~409 Ø MISC 50~354 D
9 С,ТНОІЛИ 9 С,ТНОІЛИ 9 С,ТНОІЛИ 9 С,ТНОІЛИ Я М.ТНОІЛИ	8205210467* 8206020051* 8312080163* 8408130260* 8408270195	50-329 A 50-329 A 50-329 A 50-382 G 50-289 B	KOON,A R KOSCHIK,M Q KOSTAL,K T KOSTAL,K T KOTTAN,J	8408300514 8408150435# 8408270172* 8408270172* 8408200023*	50-395 50-329 50-454 50-454 50-289	5 A G G	LARIZZA, G F LARDCHE, G E LARSON, C E LARSON, D E LARBON, D E	8408290112 8408210374* 8408070197* 8408300180* 8408080099	50~244 8 50~358 9 50~282 9 50~263 F 50~263 5
H 6 'NOTHBIN'S H 6 'NOTHBIN'S H 6 'NOTHBIN'S H 6 'NOTHBIN'S H	8408070424 8408070483 8408130182 8408130217 8408140036	50-361 P 50-528 A 50-528 F 50-443 A 50-361 Q	KOWINSKI, G KOTTAN, J KOVACH, L KOVACH, L KOVACH, L KOVINSKI, G R	8408010378* 8408230157* 8408310166 8408060186 8408270220	50-367 50-352 50-289 WASTE MG 40-1162	Q G F ST	LATHWELL, M J LAURENSON, J A LAURENSON, J A LAURENBON, J A LAZARUS, M	8408130376* 8408070213 8408070242 8408150073 8408070258*	50~155 F 50~322 O 50~322 O 50~322 O 50~324 P
116HIOW'S M 116HIOW'S M 116HIOW'S M 116HIOW'S M	8408150137 8408230295 8408230300 8408230304 8408230310	50-400 F 50-382 F 50-275 F 50-361 F 50-528 F	KRASOPOULOB, A KRAUSE, D KRAUSE, D KREH, E J KREH, J L	8408210901* 8408210232 8408070272 8408280268* 8408270432*	50~245 50-246 50-315 50-445 50-302	0 R F 0	LEACH, C E LEACH, C E LEAHY, M LEAHY, M LEAR, Q	8408140343* 8408230122* 8408230104 8408230067 8205050207*	50~261 P 50~261 P 50~249 S 50~237 S 50~329 A
MIGHTON, G W MIGHTON, G W KNIGHTON, G W KNOP, R C KNOP, R C	8408230349 8408230377 8408230379 8408030207* 8408090304*	50-528 A 50-412 A 50-275 E 50-341 Q 50-440 Q	KRICH,R M KRICH,R M KRICH,R M KRIESEL,T A KRIMM,R	8408040115* 8408210287 8408210478 8408300505 8405240290	50-155 50-155 50-155 50-315 50-3	4 & 4 & 0	LEAR, Q LEAR, Q LCAR, Q LEAR, Q LEAR, Q	8206240401* 8210270126* 8211030272* 8310050136* 8310070101*	50-329 A 50-329 O 50-329 O 50-329 O 50-329 O
KNOP.R C KNOTTS,J B KOBER.R W KOBER.R W KOBER.R W	8408240321* 8408020027 8408030014* 8408070178* 8408070178	50-461 0 50-416 6 50-244 0 50-244 0 50-244 0	KRIMM,R W KRIMM,R W KRIMM,R W KRIMM,R W KRIMM,R W	8404040167 8408080138 8408070042 8408070036 8408210346	50-10 50-416 50-413 50-247 50-302	F F F	LEAR, Q LEAR, G LEAR, G LEAR, G LEAR, G	8310070262* 8310240271* 8408020172* 8408020179* 8010140005*	50-327 A 50-327 Q 50-327 A 50-327 A 50-327 Q
KOBER, R W KOBER, R W KOBER, R W KOBER, R W KOBER, R W	8408070248 8408070315 8408070524 8408080091 8408100032*	50-244 P 50-244 P 50-244 P 50-244 P 50-244 G	KRIMM,R W KRIMM,R W KROEB,R,J KROPP,W KROPP,W	8408210408 8408300319* 8408130094* 8408060309* 8408160217*	50-272 50-324 50-433 50-456 50-454	F G G	LEAR, Q E LEAR, Q E LEAR, J LEARNER, H A LEARNER, H A	8011240409* 8408020184* 8408140530* 8408010177 8408010177	50-329 A 50-329 G 50-329 A 50-454 G
XOBER,R W KOBER,R W KOBER,R W KOBER,R W	8408100036* 8408130357 8408140161 8408170047 8408170058	50-244 q 50-244 p 50-244 F 50-244 p 50-244 p	KRUO, H E KUCHARSKI, S KUCZYNSKI, L A KUCZYNSKI, L A	8408230146# 8408310139 8408080478* 8408090393 8408090393	50-251 PR 50-322 50-388 50-387	0 G S	LEARNER, H A LEDDICK, R G LEDDICK, R G LEDUC, R J LEDUC, R J	8408010177 8408210378 8408270303 8408020258 8408200187	50-454 Q 50-382 A 50-382 A 71-7092 WASTE MOT
KOBER, R W KOCHER, D C KOCHHAR, D S KDENIGS, R L KOENIGS, R L	8408270112 8408080422 8408170307 8408070443 8408070450	50-244 S MUREO 50-454 T 50-397 S 50-397 S	KUCZYNSKI, L A KUCCHUE, C KUEMIN, J L KUEMIN, J L	8408070374 8408300487 8408160150 8408160181 8408270067	50-387 50-387 50-295 50-155 50-155	क द क क	LEE.O R LEE.O R LEE.O R LEE.O R	8408030168 8408070233 8408080320 8408080525 8408070311	50-267 F 50-267 S 50-267 G 50-267 F 50-267 F
KOENIGS.R.L KOENIGS.R.L KOENIGS.R.L KOENIGS.R.L KOENIGS.R.L	8408070458 8408200132 8408200341 8408270017 8408270024	50-397 8 50-397 8 50-397 9 50-397 9 50-397 8	KUEMIN, J L KUEMIN, J L KULM, V KUNDER, G A KUPPERMAN, D	8408270251 8408300084 8408140407* 8408280521 8408240322	50-155 50-155 50-508 50-289 NUREG	8 8 A 0	LEE, DR LEE, DR LEE, R.S LEE, SY LEE, T, D	8408090316* 8408290256 8408280033 8408300282 8408030033*	50-247 P 50-267 P 50-368 P MUREO 70-143

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESS 10H NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
LEE, T D LEE, W S LEE, Y S LEECH, P H LEECH, P H	8408130383* 8408240242* 8408160378* 8408150520 8408310396	70-143 50-413	LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C	8408300297 8408300315 8408300320 8408300347 8408300353	50-400 F 50-324 F 50-321 P 50-400 G 50-390 G	LITTLE: W S LITTLE: W S LITTLE: W S LITTLE: W S LITTLE: W S	8408070338 8408090184 8408090192 8408140130 8408140136	50-456 G 50-266 G 50-255 G 50-155 G 50-374 G
LEOGETT, R W LEINS, E LEMPOES, T E LEMPOES, T E LEMPOES, T E	8408130007 8408170280 8408020115 8408030201 8408080257	NUREG MISC 50-220 R 50-220 S 50-220 S	LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C	8408300354 8408300357 8408300360 8408300363 8408300366	50-390 V 50-269 F 50-250 V 50-327 F 50-424 A	LETTLE, WS LETTLE, WS LETTLE, WS LETTLE, WS LETTLE, WS	8408150290 8408160324 8408160329 8408280080 8408300179	50-255 G 50-346 G 50-254 G 50-254 G
LEMPGES, T E LEMPGES, T C LENAHAN, J J LENTSCH, J W LENTSCH, J W	8408080483 8408280248* 8408140096* 8408020050 8408020059*	50-220 S 50-220 Q 50-400 T 50-344 K 50-344 P	LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C	8408300349 8408300378 8408300408 8408300413 8408300421	50-280 P 50-370 V 50-413 G 50-416 P 50-321 P	LITTLE,W S LITTLE,W S LITTLE,W S LITTLEHALES,G LITTLEHALES,G	8408300186* 8408300203* 8408300207* 8408070334 8408070466	50-440 Q 50-341 Q 50-341 Q QA999 QA999
LEONARD. J D LEONARD. J D LEONARD. J D LEONARD. J D LEONARD. J D	8408040323 8408070385 8408080340 8408200328 8408270224	50-322 V 50-322 V PR 50-322 A 50-322 A	LEWIS,R C LEWIS,R C LEWIS,R C LEWIS,R C LEWIS,R C	8408300424 8408300426 8408300435 8408300440 8408310016	50-390 A 50-414 P 50-416 P 50-413 A 50-413 P	LIU.L LIU.W C LLOYD.R L LOCKE.R T LOCKE.R T	8408210263* 8408270469* 8408170117* 8408140484 8408140484	50-331 [ 50-390 @ 50-443 @ 50-352 @ 50-352 @
LEONARD.J D LEONARD.J D LERS.E L LETSCHE.K J LETSCHE.K J	8408280187* 8408300123 8408010279* 8408010239 8408010239	50-322	LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C	8408310021 8408310028 8408310052 8408310062 8408310069	50-321 P 50-413 P 50-321 P 50-302 P 50-280 F	LDCKWOOD,G J LDDGE,T J LDFY,R LOFY,R A LDGUE,R H	8408080367 8408280437 8408090074* 8408080507* 8408080533	NUREQ 50-440 Q CONTRACT CONTRACT 50-277 B
LETSCHE.K J LETSCHE.K J LETSCHE.K J LETSCHE.K J LETSCHE.K J	8408140470 8408140470 8408140477* 8408140477* 8408140210	50-322 0 50-322 0 50-322 0 50-322 0 50-322 0	LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C	8408310241 8408310242 8408310378 8408310401 8408310405	50-413 P 50-413 P 50-366 P 50-280 F 50-424 G	LOMEN, R D LOMEN, R D LOMEN, R D LOMAX, D B	8408080535 8408130601 8408290258 8408310075 8408080300	50-277 8 50-277 8 50-317 8 NUREG 50-368 8
LETSCHE.K J LETSCHE.K J LETSCHE.K J LETSCHE.K J LETSCHE.K J	8408160210 8408230194 8408230194 8408280249 8408280249	50-322 G 50-322 G 50-322 G 50-322 G	LEHIS,R C LEWIS,R C LEWIS,R C LEWIS,S H LEWIG,S H	8408310411 8408310419 8408310428 8408130299 8408170141*	50-261 F 50-424 G 50-413 A 50-434 G 50-329 A	LOMAX, D B LOMBARDO, J J LODMIS, J N LOUX, R. R LOUX, R. R	8408300475 8408150227 8408070478* 8408130130 8408220061	50-368 S 50-219 P 50-27 P WASTE MOT WASTE MOT
LETSCHE.K J LETTIERI.V LETTIERI.V LETTIERI.V	8408280405 8408280405 8408220419* 8408220424* 8408150741*	50-322	LEWIS, S H LEWIS, S H LEWIS, S H LEY, M LICITRA, E A	8408200587 8408200593* 8408280443 8408230373 8408090448	50-338 G 50-338 G 50-454 G 50-412 A 50-528 F	LOVELL, J LOVELL, J LOVENDALE, P LOVENDALE, P C LOVENDALE, P C	8409160521 8409200273 8409310268 8408080496* 840820024[*	50-250 S 50-250 S 70-1308 50-295 G 50-155 G
LEWIS, D R LEWIS, D R LEWIS, D R LEWIS, D R LEWIS, M I	8408200551 8408200561 8408230207 8408230207 8408020111	50-289 G 50-289 G 50-289 G 50-289 G PR	LICITRA, E A LICITRA, E A LIDEN, E A LIDEN, E A LIDEN, E A	8408090523 8408230367 8408020180 8408030247* 8408130362	50-528 A 50-528 A 50-272 K 50-272 G 50-311 P	LOVENDALE, P C LOWE, A LOWE, A L LOWE, A L LOWE, A L	8408300164* 8408140413* 8408140433* 8408210387* 8408210393*	50-255 0 50-346 P 50-313 P 50-338 P 50-338 P
LEWIS, M I LEWIS, M I LEWIS, M I LEWIS, R C LEWIS, R C	8408070349 8408140445 8408280412 8408130335 8408130394	PR 50-289 G 50-289 G 50-416 F 50-338 G	LIDEN,E A LIDEN,E A LIDEN,E A LIDEN,E A LIDEN,E A	8408150223 8408150245 8408160142 8408200343 8408210335	50-272 F 50-272 P 50-272 R 50-272 P 50-272 P	FORES'Y R FOREINSKI'W FORES'H H FORES'H H	8409150505* 8409040439 8409220351 8409220351 8409240132	50-322 T 70-364 40-2061 40-2061 50-329 R
LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	8408130408* 8408130433 8408130443* 8408200263* 8408230148	50-338	LIDEN,E A LIEBERMAN,J A LIEBERMAN,S LIGHTCAP,J B LINDER,F	8408240117 8408070462* 8408150700* 8408270305 8408060004	50-272 P FRM 50-329 A 50-454 G 50-409 G	LUCKB, A B LUCKB, A B LUDUN, R H LUGAR, R G	8408240134* 8408240138* 8408240143* 8408310051 8405180152*	50-329 R 50-329 R 50-329 R 70-1342 50-367 H
LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	8408230151 8408230158* 8408230167 8408230180* 8408230217*	50-25t 0 50-25t 0 50-259 0 50-259 0 50-259 0	LINDER, F LINDER, F LINDER, F LINDER, F LINDER, F	8408140287 8408150212 8408160186 8408160309 8408210333	50-409 P 50-409 P 50-409 S 50-409 B 50-409 F	LUKER, S M LUKZ, F J LUNDVALL, A E LYDELL, B O LYNCH, J L	8408080367 8408220387* 8408070343 8408010276* 8408010374	NUREG CONTRACT 50-317 F 50-206 P 40-8842
LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R, C LEWIS, R C	8408240316 8408240363 8408240368* 8408270192 8408270206	50-261	LINDER, F LINDER, F LINDER, F LINDER, F LINDER, F	8409270105 8408220170 8409270080 8409270274* 8409310176	50-409 F 50-409 R 50-409 F 50-409 G 50-409 P	FAONE'S T FAONE'S T FAONE'S T FAOUE'S T FAOUE'N D	8408070468 8408230386 8407230131 8408060383 8408240018	50-341 F 50-213 P 40-277 40-277 40-277
LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	8408270209* 8408270241 8408270249 8408270255* 8408270257	50-335 Q 50-321 Q 50-367 Q 50-321 Q 50-417 Q	LINDSEY, D J LINDSEY, D J LINEHAN, D J LINEHAN, J J LINEHAN, J J	8408030256 8408270144 8408240103 8408030045 8408060051	SO-303 B SO-333 S WASTE MOT WASTE MOT WASTE MOT	FAONS' b 7 FAONS' b 7 FAONS' b 7 FAONS' b 7	8408240344 8409240384 8409240396 8409240412 8409270077	40-297 40-297 40-297 40-297 40-297
LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R. C	8408270246* 8408270248* 8408270313 8408270314 8408270322*	50-369 G 50-417 G 50-416 G 50-250 G	LINEHAN, J J LINEHAN, J J LINEHAN, J J LINENBERGER, G LINENBERGER, G	8408060149 8409210125 8409230079 8409270288 8409310104	WASTE MOT WASTE MOT WASTE MOT 50-70 G 50-358 G	LYONB.P J LYONB.P J LYONB.P J MACDONALD MACDONALD.C E	8408270120 8408270186 8408280379 8408080052 8408030072	40-299 40-299 40-299 71-307 71-9188
LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C	8408270326* 8408270365 8408270375* 8408270513 8408270528*	50-416 Q 50-327 Q 50-327 Q 50-261 Q 50-261 Q	LINVILLE, J C LINVILLE, J C LINVILLE, J C LIPCHAK, J B LIPINSKI, D	8408030031* 8408070237* 8408150370* 8408070282* 8408230091*	50-272	MACBONALD, C E	8408060269 8408060326 8408060327 8408060328 8408060370	71-9184 71-275 71-325 71-327 71-328
LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	8408280454 8408280472 8408280479* 8408290031* 8408300193	50-400	LIPINSKI.D R LIPINSKI.D R LISEND,R T LITTLE.W S	8408080403* 8408140492* 8408030254 8408230354 8408060325*	50-245	MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E	8408060374 8408060376 8408060421 8408060429 8408060433	71-296 71-207 71-38 71-8 71-54

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E	8408070010 8408070020 8408070056 8408070054 8408070151	71-167 71-9193 71-68 71-174 71-195	MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E	8408080283 8408080287 8408080291 8408080273 8408080310	71-36 71-123 71-134 71-152 71-270	MACDONALD, C E	8408310443 8408310444 8408310449 8408310453* 8408310455	71-70 71-186 71-216 71-216 71-169
MACDONALD, C E	8409070159 8409070500 8408070503 8408070504 8408070507	71-21 1 71-22 1 71-22 5 71-22 2 71-22 4	MACDONALD, C E	8408080313 8408080325 8408080328 8408080378 8408080379	71-110 71-100 71-103 71-237 71-253	MACDUNALD, C E MACDUNALD, C E MACE, M MACE, M MACGUINEAS, D B MACGUINEAS, D B	8408310456* 8408310457* 8408130308 8408080197 8408080197	71-169 71-70 CONTRACT 50-348 H 50-349 H
MACDONALD, C E	8408080015 8408080017 8408080040 8408080044 8408080045	71-130 71-128 71-300 71-298 71-127	MACDONALD, C E	8408080381 8408080401 8408080406 8408080411 8408080418	71-242 71-34 71-142 71-61 71-59	MACQUINEAS, D B MACQUINEAS, D B MACQUINEAS, D B MACQUINEAS, D B MACRAE, J B	8408080202 8408080202 8408080241 8408080241 8408040019	50-348 M 50-348 M 50-348 M 50-348 M 0R0
HACDONALD.C E HACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E	8408080056 8408080057 8408080058 8408080050 8408080063	71-80 71-303 71-154 71-283 71-93	MACDONALD, C E	8408080424 8408080444 8408080446 8408080447 8408080447	71-247 71-37 71-229 71-51 71-320	MACRAE.J B MACRAE.J B MACRAE.J B MADDEN.P M MADDEN.P M	8408050219 8408050219 8408070031 8408240352* 8408280140*	080 080 080 50-390 0 50-259 0
MACDONALB.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E	8408080045 8408080044 8408080049 8408080071 8408080072	71-74 71-306 71-151 71-44 71-232	MACDUNALD, C E	8408080451 8408080452 8408080457 8408080459 8408080460	71-166 71-216 71-302 71-218 71-214	MADDEN, W MADDEN, W MADEDA, T MADDIAN, A MAHAFFEY, M	8408150493* 8408200487* 8408040034* 8408070002 8408220343	50-245 g 50-29 q 50-341 q GA999 PR
MACDUNALD, C E	8408080074 8408080075 8408080076 8408080078 8408080079	71-223 71-75 71-47 71-77 71-95	MACDONALD, C E	8408080462 8408080465 8408080468 8408080469 8408080470	71-168 71-175 71-220 71-99 71-219	MAHLER, R J MALLOY, J MALLOY, J MALSCH, M. G MALSCH, M. G	8408230504* 8408010285* 8408060309* 8408070145 8408100001	CONTRACT 50-341 g 50-454 q 50-416 g 50-382 g
MACDONALD, C E	8408080080 8408080081 8408080085 8408080086 8408080088	71-304 71-57 71-234 71-217 71-145	MACDONALD, C E	8408080474 8408080475 8408090038 8408200086 8408200090*	71-281 71-257 71-279 71-240 71-240	Malbch, M G Malbch, M G Malbch, M G Malbch, M G Mangan, C V	8408100011 8408100133 8408130328* 8408240110 8407070212	50-382 Q 50-289 Q 50-382 Q 88CY 50-410 X
MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E	8408080072 8408080073 8408080074 8408080075 8408080077	71-140 71-326 71-294 71-148 71-322	MACDONALD, C E	8408240202 8408240323 8408240325 8408270490 8408270570	71-5926 71-9111 71-9073 71-9151 71-9184	Hangan, C V Hangan, C V Hangan, C V Hangan, C V Hangan, C V	8408060134 8408060171 8408060248 8408060260 8408060284	50-220 P 50-220 F 50-220 P 50-410 A 50-410 A
MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E	8408080078 8408080101 8408080103 8408080106 8408080107	71-208 71-197 71-215 71-233 71-119	MACDONALD, C E MACDDNALD, C E MACDDNALD, C C MACDDNALD, C E MACDDNALD, C E MACDONALD, C E	8408270580 8408280324 8408310073 8408310078 8408310169	71-7073 71-5805 71-6346 71-7143 71-9016	MANGAN, C. V MANGAN, C. V MANGAN, C. V MANGAN, C. V MANGAN, C. V	8408070434 8408090077 8408100071 8408100074 8408100076	50-220 F 50-220 P 50-410 S 50-220 P 50-220 F
MACDUNALD.C E MACDUNALD.C E MACDUNALD.C E MACDUNALD.C E ACDUNALD.C E	8408080111 8408080112 8408080117 8408080122 8408080125	71-133 71-132 71-134 71-120 71-125	MACDDNALD.C E MACDDNALD.C E MACDDNALD.C E MACDDNALD.C E MACDDNALD.C E	8408310170 8408310278 8408310283 8408310287 8408310287	71-6581 71-293 71-295 71-167 71-158	Mangan, C V Mangan, C V Mangan, C, V Mangan, C V Mangan, C V	8408100081* 8408100103 8408100111* 8408100118 8408160367	50-220 P 50-220 P 50-220 P 50-410 8 50-220 P
ACDONALD.C E ACDONALD.C E ACDONALD.C E ACDONALD.C E JACDONALD.C E	8409080126 8409080127 8409080128 8408080132 8408080135	71-20 71-272 71-137 71-70 71-63	MACDONALD, C E	8408310293 8408310297 8408310300 8408310346 8408310348	71-172 71-329 71-297 71-291 71-285	Hangan, C. V Hangan, C. V Hangan, C. V Hangan, C. V Mangan, C. V	8408200535 8408210439 8408210447 8408230237 8408280001	50-220 6 50-410 8 50-410 F 50-220 X 50-410 E
MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E	8408080136 8408080137 8408080139 8408080143 8408080143	71-28 71-33 71-14 71-44 71-104	MACDONALD, C E	8408310350 8408310352 8408310354 8408310356 8408310357	71-270 71-288 71-66 71-289 71-287	Mangan, C. V Mangan, C. V Mangan, C. V Mangan, C. V Mangan, C. V	8408280163 8408300035 8408300037* 8408300300 8408300345	50-410 ε 50-220 ρ 50-220 ρ 50-410 A 50-410 S
MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E.	8408080154 8408080155 8408080163 8408080169 8408080174	71-141 71-113 71-105 71-319 71-13	MACDONALD, C E	8408310358# 8408310360 8408310364 8408310366 8408310369	71-66 71-930 71-286 71-301 71-282	MANGAN, C V MANGAN, C V MANGAN, C, V MANGUELI, J MANNELLI, L	8408300362 8408300365 8408310235 8408210314 8408020114*	50-410 S 50-410 S 50-410 G PR 50-482 F
MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E	8408080182 8408080185 8408080210 8408080215 8408080220	71-314 71-89 71-81 71-292 71-32	MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C, E MACDONALD, C, E	8408310371 8408310372 8408310375 8408310376 8408310377	71-299 71-318 71-317 71-4717 71-280	MANNING:H A MARCHI:M MARKEY:E J MARKEY:E J MARKEY:E J	8408270332 8408070053* 8408080033 8408080432* 8408200279*	NUREO 50-387 @ 50-305 8 50-416 U 50-369 U
MACDONALD, C E	8408080225 8408080229 8408080231 8408080234 8408080247	71-55 71-310 71-183 71-284 71-188	MACDONALD, C E MACDONALD, C E MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E	8408310380 8408310382 8408310384 8408310387 8408310388	71-313 71-276 71-312 71-274 71-311	MARKOB, Q MARKOB, Q MARLOW, J MARQUEZ, R. A. MARR, Q	8408310335* 8408310337* 8408140449 8408130116 8408140065*	Waste Not Waste Mot 50-219 0 Waste Mot 50-329 A
MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E	8408080253 8408080258 8408080263 8408080264 8408080267	71-212 71-205 71-213 71-16 71-171	MACDDNALD, C E MAGDDNALD, C E MAGDDNALD, C E MACDDNALD, C E MACDDNALD, C E MACDDNALD, C E,	8408310391 8408310373 8408310399 8408310403 8408310407	71-303 71-248 71-269 71-261 71-254	Marsh, l 8 Marshall, J Marshall, J G Marshall, J G Marshall, J G	8408140075* 8408070483 8408060085 8408060145 8408140323	50-400 T 50-313 P 50-373 G 50-373 P 50-373 P
MACDONALD, C E MACDONALD, C E CDONALD, C E CDONALD, C E CDONALD, C E	8408080258 8408080270 8408080274 8408080279 8408080281	71-11 71-22 71-181 71-39 71-87	MACDDNALD, C E MACDDNALD, C E MACDDNALD, C E MACDDNALD, C E MACDDNALD, C E	8408310415 8408310418 8408310421 8408310436 8408310438*	71-245 71-124 71-111 71-16 71-16	Marshall, j g Marshall, j g Marshall, j g Marshall, j r Marshall, j r	8408140372 8408160364 8408160387 8408060187 8408080493	50-237 V 30-373 P 50-373 P 50-368 8 50-368 8

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R	8408080500 8408080512 8408080528 8408130170 8408130326	50-368 S 50-368 S 50-368 S 50-313 S 50-313 S	MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T	8408080456 8408080463 8408080473 8408080481 8408080523	50-220 q 50-217 q 50-322 q 50-352 q	MATTIA, M J MATTIA, M J MATTSON, D R MAUPIN, M W MAUPIN, M W	8408080025* 8408270503* 8408060341 8408150464	CONTRACT CONTRACT TOM STEAM TOMBLE OF TOMBLE OF TOMBLE OF
MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R	8408130357 8408140328 8408140355 8408140403 8408140429	50-36B P 50-36B P 50-313 P 50-313 P 50-313 P	MARTIN,T 1 MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T	8408090034 8408090088* 8408090315 8408100022 8408100028	50-277 0 50-271 0 50-322 0 50-244 0 50-352 0	MAUPIN, M W MAUPIN, M W MAUPIN, M W MAUPIN, M W MAUPIN, M W	8408200477 8408200477 8408300177 8408300177 8408310150	50-339 0 50-339 0 50-339 0 50-339 0
MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R	8408150317* 8408170061 8408200303 8408240053 8408240077	50-313 G 50-313 P 50-313 P 50-313 S 50-348 S	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8408100041 8408100043 8408100073 8408130385 8408130404	70-1941 50-244	MAUPIN, M W MAURA, F MAURER, B F MAXWELL, G F MAY, E L	8408310150 8408060325* 8408310194* 8408140039* 8408160529	50-338 G 50-382 G 50-454 T 50-329 A 50-29 8
MARSHALL, J R	8408240080	50-368 8	MARTIN,T T	8408150107	50-336 Q	MAY:M P	8408300272	NUREQ
MARSHALL, J R	8408280184	50-313 F	MARTIN,T T	8408150238	50-217 F	MAYS:W M	8408280018	40-8857
MARSHALL, J R	8408300154	50-313 9	MARTIN,T T	8408150298	50-317 Q	MAYS:W M	8408280022*	40-8857
MARSHALL, J R	8408300475	50-368 8	MARTIN,T T	8408150398	70-371	MCALPINE:E J	8408030033*	70-143
MARSHALL, J R	8408300496	50-368 8	MARTIN,T T	8408150409	50-277 Q	MCALPINE:E J	8408130383*	70-143
MARSHALL, J S MARSHALL, R S MARSTON, R R MARTIN, D E MARTIN, J B	8409160157 8408080409 8408270275* 8408010361 8408130304	50-445 A MUREG 50-250 G WASTE MST 50-344 Q	MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T	8408150453 8408150537 8408150573 8408150631 8408150650	50-333	MCALPINE,E J MCALPINE,E J MCALPINE,E J MCALPINE,E J MCALPINE,E J	8408140134 8408270223* 8408270284* 8408270427* 8408270540*	70-143 70-1151 70-27 70-143 70-1113
MARTIN, J B MARTIN, J D MARTIN, J D MARTIN, J D MARTIN, J D	8408270223 8408270229 8406070192 8408030280 8408060233	State Prog State Prog 50-397 R 50-397 S 50-397 S	MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T	8408150598 8408150597 8408150711 8408150715* 8408160102	50-245 G 50-286 G 50-317 G 50-317 G 50-317 G	MCALPINE.E J MCALPINE.E J MCALPINE.E J MCALPINE.E J	8408280367* 8408300307* 8408300394* 8408300401* 8408310255*	70-1113 70-1201 70-27 70-27 70-1151
MARTIN, J D	8408050235 8408060301 8408070443 8408070450 8408070458	50-397 8 50-397 8 50-397 8 50-397 8 50-397 8	MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T	8408160235 8408160251 8408160266 8408160428 8408170079	50~245	MCBEE.R D MCBEE.R D MCBREARTY,R A MCBREARTY,R A MCBREARTY,R A	8408270380* 8408220380* 8408130434* 8408230145* 8408390113*	50-445 T 50-445 T 50-272 Q 50-271 Q 50-247 Q
MARTIN, J D	8408200132	50-397 S	MARTIN,T T	8408170168	50-244 P	McDride, m	8408230071*	50-293 0
MARTIN, J D	8408200341	50-397 S	MARTIN,T T	8408200014	50-289 Q	McCabe, e	8408280107	50-213 8
MARTIN, J D	8408280320	50-397 R	MARTIN,T T	8408200043	50-272 Q	McCabe, e	8408290483*	50-322 0
MARTIN, J, D	8408290017	50-397 S	MARTIN,T T	8408200476	50-27 Q	McCabe, e	8408310074	50-213 8
MARTIN, J D	8408290024	50-397 S	MARTIN,T T	8408200495	50-354 Q	McCabe, e	8408310111	50-213 8
MARTIN, J D	8408270030	50-397 S	MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T	8408200510	50-247 Q	MCCABE, E C	8408090053*	50-387 @
MARTIN, J D	8408270116	50-397 S		8408210238	50-247 Q	MCCABE, E C	8408200041*	50-387 @
MARTIN, J D	8408270143	50-397 S		8408210277	50-333 Q	MCCABE, E C	8408200366*	50-354 @
MARTIN, J G	8407100377*	50-413 U		8408210420	50-352 Q	MCCALLISTER, P	8104230479*	50-327 @
MARTIN, L E	8408070160*	50-313 Q		8408210424	50-333 Q	MCCALLISTER, P	8408140232*	50-327 A
MARTIN,L E MARTIN,L E MARTIN,L E MARTIN,L E MARTIN,L E	8408150102* 8408160504* 8408160523* 8408230466* 8408160146	50-445 G 50-313 G 50-482 G 50-285 G NUREG	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8409210468 8408210494 8408210515 8408230094 8408230130	50-336 0 50-245 0 50-336 0 50-219 0 50-277 0	MCCALLISTER, P MCCALLISTER, P MCCANN, M MCCARTHY, R MCCARTHY, R MCCARTHY, R	8408140557* 8408150015* 8408220333 8408150485* 8408150505*	50-329 A 50-329 A 50-352 A 50-322 T 50-322 T
MARTIN,R E	8408010199	50-352 A	MARTIN,T T	8408230137	50-271 @	MCCARTHY.R L	8408150514*	50-322 T
MARTIN,R E	8408060268	50-352 A	MARTIN,T T	8408230153	50-352 @	MCCARTY.C	8408240375	40-8768
MARTIN,R E	8408080206	50-352 A	MARTIN,T T	8408230183	70-1450	MCCAY.S B	8408150736*	71-9073
MARTIN,R E	8408140334	50-352 A	MARTIN,T T	8408230173	40-791	MCCLESKEY.K	8408230409	50-322 C
MARTIN,R E	8408150637	50-352 F	MARTIN,T T	8408230224	50-220 @	MCCLESKEY.K	8408230409	50-322 C
MARTIN.R E MARTIN.R E MARTIN.T MARTIN.T MARTIN.T J	8408210091	50-352 A	MARTIN,T T	8408230242	50-322 G	MCCLESKEY, K E	8408020024	50-322 0
	8408270548	50-352 A	MARTIN,T T	8408230276	50-293 G	MCCLESKEY, K E	8408020024	50-322 0
	8408160130	1&E	MARTIN,T T	8408230487	50-309 G	MCCLESKEY, K E	8408070256	50-322 0
	8408070326*	50-354 G	MARTIN,T T	8408230566	50-293 G	MCCLESKEY, K E	8408070256	50-322 0
	8408100085	50-354 S	MARTIN,T T	8408240071	50-334 G	MCCORMICK-BARGE	8408160193*	50-483 0
MARTIN,T J	8408100076	50-354 S	MARTIN, T T	8408240220	50-213 Q	MCCORMICK-BARGE	8408300188*	50~315 G
MARTIN,T J	8408100140	50-354 S	MARTIN, T T	8408240272	50-317 F	MCCOY, M A	8408220544	TOPREP
MARTIN,T J	8408280066	50-354 Q	MARTIN, T T	8408240272	50-271 Q	MCCRIGHT, D R	8408070140*	WASTE MGT
MARTIN,T J	8408300342	50-354 S	MARTIN, T. T	8408270230	50-273 F	MCCRORY, B L	8408270115*	50~368 G
MARTIN,T T	8408010282	50-247 Q	MARTIN, T T	8408270234	50-410 Q	MCCRORY, B L	8408270142*	50~285 G
MARTIN,T T	8408010288	50-245 G	MARTIN,T T	8408270263	40-472	MCCRORY, B L	8408270176*	50-368 G
MARTIN,T T	8408010395	50-387 G	MARTIN,T T	8408270327	50-5 P	MCDERMOTT, J L	8408010237*	50-275 G
MARTIN,T T	8408010397	40-6499	MARTIN,T T	8408270461	50-271 G	MCDIARMID, R C	8408030154	50-275 G
MARTIN,T T	8408030005	50-244 G	MARTIN,T T	8408270470	50-333 G	MCDONALD, C E	8408070469	50-348 F
MARTIN,T T	8408030104	50-289 G	MARTIN,T T	8408280099	50-354 G	MCDONALD, D G	8408060436	50-250 P
MARTIN, T T	8408030122	50-289 G	MARTIN, T T	8408280245	50-220 @	MCDDNALD.D G MCDDNALD.D G MCDDNALD.D G MCDDNALD.D G MCDDNALD.J R	8408070032	50-250 P
MARTIN, T T	8408030173	50-387 G	MARTIN, T T	8408300106	50-247 @		8408280546	50-250 P
MARTIN, T T	8408030259	50-272 G	MARTIN, T T	8408300107	50-27 @		8408230477	50-250 P
MARTIN, T T	8408040139	50-279 G	MARTIN, T T	8408310131	50-272 @		8408230564	50-250 P
MARTIN, T T	8408040190	50-219 G	MARTIN, T. T	8408310140	70-2571		8408220327	NUREO
MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8408060373 8408070174 8408070320 8408070323 8408070353	70-1362 50-244	MARTIN, T T MASTERSON, V MATHEWS, C S MATHEWS, C S MATHIASE, C D	8408310320 8408040207 8408150305* 8408150530* 8408160169	70-221 50-373 B 50-322 T 50-322 T 50-263 F	MCDONALD.R MCDONALD.R P MCDONALD.R P MCDONALD.R P MCDONALD.R P	8408270558* 8408070314 8408100036 8408130345 8408130374	CONTRACT 50-348 V 50-348 P 50-344 G 50-349 F
MARTIN, T T	8408080157	50-387 Q	MATHIS, C. J	84080B0503	SO-293 R	MCDONALD, R P	8408200611	50-348 R
MARTIN, T T	8408080204	50-220 Q	MATTHENS. C W	840B130314*	CONTRACT	MCDONALD, R P	8408210412	50-344 P
MARTIN, T T	8408080233	50-244 Q	MATTHENS. M L	840B040104	WASTE MGT	MCDONALD, R P	8408230378	50-348 P
MARTIN, T T	8408080243	50-289 Q	MATTHENS. P	840B220253	NUREG	MCDONALD, R P	8408230515	50-348 S
MARTIN, T T	8408080244	50-289 Q	MATTHENS. T P	840B200589	SO-285 R	MCDONALD, R P	8408280048	50-348 Q

AUTHOR	ACCESSION NUMBER	CATEGORY CATEGORY	AUTHDR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MCDONALD, R P MCDONALD, R P MCDONOUGH, M D MCDONOUGH, M D MCDUPF1E, M A	8408280176 8408300167 8408230469 8408310005# 8408070381	50-348 Q 50-348 Q XPORYLIC XPORTLIC 50-400 K	MEDFORD. M O MEDFORD. M O MEDFORD. M O MEDFORD. M O MEDFORD. M O	8408160215 8408210165 8408220078 8408230178 8408240148	50-206 P 50-204 P 50-361 R 50-206 P 50-206 P	MILLER, M E MILLER, M M MILLER, M S MILLER, M S MILLER, M G	8408230168 8408010286* 8408030086 8408030086 8408030105	50-322
MCDUFFIE, M A MCFADDEN, J MCGARRY, J M MCGARRY, J M MCGARRY, J M	8408140151# 8408060084 8408020060 8408020060 8408220347	50-400 T 70-2377 50-413 G 50-413 G	MEDFORD, M O	8408240247 8408240274 8408270409 8408300143 8408300232	50-361 P 50-361 P 50-361 P 50-361 P 50-206 S	MILLER, M S MILLER, M S MILLER, M S MILLER, M T MILLER, R I	8408030105 8408070424 8408070424 8408230157* 8408160290	50-322 6 50-322 6 50-322 6 50-352 6 71-5926
MCGANRY, J M MCGAUGHY, J P MCGAUGHY, R W MCGAUGHY, R W MCGAUGHY, R W	8408220347 8408280137 8408020006 8408030038 8408040001	50-413 0 50-414 0 50-331 P 50-331 P 50-331 F	MEDLOCK, R L. MEEK & B MEHRER, R MEISENHEIMER, J MEISENHEIMER, J	8408080429 8408060197* 8408150592 8408030001* 8408030031*	40-8452 50-70 G 71-9147 50-329 A 50-329 A	MILLER, R L MILLER, W H MILLER, W H MILLER, W J MILLER, W D	8408270185 8408240362* 8408280140* 8408160471 8408060212	NUREG 50-390 q 50-259 q 50-331 s 50-305 p
MCGAUGHY, R W MCGAUGHY, R W MCGAUGHY, R W MCGAUGHY, R W MCGAUGHY, R W	8408080083 8408130170 8408140247 8408140435 8408150004	50-331 P 50-331 P 50-331 P 50-331 P	MELOSH.H J. MENDEZ.R MENDEZ.R MENDEZ.R MENDONCA.M M	8408160411* 8408070217* 8408200227* 8408270277* 8408060013	50-508 A 50-454 G 50-454 G 50-454 G 50-275 S	MILLER,W O MILLER,W O MILLER,W O MILLER,W O MILLER,W O	8408080405 8408070139 8408160165 8408160279 8408160473	50-267 P 50-275 P 50-287 F 50-247 F 50-335 P
MCGAUGHY, R. W. MCGAUGHY, R. W. MCGAUGHY, R. W. MCGAUGHY, R. W. MCGAUGHY, R. W.	8408210256 8408210499 8408240105 8408240118 8408270167	50-331 I 50-331 P 50-331 P 50-331 P	MERRITT, 8 MERRITT, 8 MERRITHER, N MERRIWEATHER, N MERRYMAN, R G	8408060293 8408310062 8408240359* 8408270440* 8408160146	50-237 S 50-237 S 50-321 Q 50-424 Q NUREG	MILLER, W O MILLER, W O MILLER, W O MILLER, W. O MILLER, W O	8408170011 8408170013 8408170385 8408270493 8408280330	50-293 F 50-335 P 50-387 P 50-320 P 50-272 P
MCGAUGHY,R W MCGAUGHY,R W MCGGVERN,J J MCGGVERN,J J MCGUIRE,D R	8408280202 8408310228 8408070556 8408150247 8408030127*	50-331 P 50-331 E 70-687 70-687 50-335 Q	MERBCHOFF,E W MESERVE,R A MEBERVE,R A MEBERVE,R,A MESERVE,R A	8408240140* 8408070274 8408070482 8408070482 8408080235	9A999 40-2041 40-2041 40-2061 40-2061	MILLB,CR MILLB,LC, MILLB,LM MILLB,LM MILLB,LM	8408210278 8408040378* 8408010172 8408010344 8408020145	50-282 8 70-1342 50-390 A 50-259 P 50-259 F
MCGUIRE, DR MCGUIRE, DR MCGUIRE, DR MCGUIRE, DR MCGUIRE, DR	8408070409* 8408130166* 8408130204* 8408130418* 8408130446*	50-390 G 50-269 G 50-395 G 50-338 G	MEBERVE, R A MEBBENGER, G H MEBBENGER, G H MEWHINNEY, J A MEYER, G W	8408080235 8408310032 8408310035* 8408160125 8408150244*	40-2061 50-275 P 50-275 P NUREG 50-277 G	MILLB, L M MILLB, L M MILLB, L M MILLB, L M	8408030015 8408030017 8408030026 8408030032 8408030128	50-259 F 50-327 P 50-327 P 50-390 F 50-390 A
MCGUIRE, DR MCGUIRE, DR MCGUIRE, DR MCGUIRE, DR MCGURREN, HJ	8408150317* 8408230235* 8408240010* 8408280192* 8408130270	70-143 50-324 0 50-261 0 70-143 50-413 0	MEYER, R E MILBROT, W E MILBROT, W E MILEY, G H MILLER, D B	8408300282 8408160193# 8408160331# 8408030276 8408130662#	NUREG 50-483 G 50-266 G 50-151 F 50-327 A	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8408030155 8408060021 8408040220 8408060254 8408070133	50-438 A 50-257 P 50-328 P 50-327 F 50-327 P
MCKENNA: E MCKENNA: E MCKENNA: E MGKENNA: E MGKENA: C	8408200593* 8408160359 8408160375 8408280173 8408010198*	50-338 Q 50-206 P 50-206 P 50-206 P 50-329 O	MILLER, DE MILLER, DE MILLER, GE MILLER, HJ MILLER, HJ	8408020223* 8408150391* 8408270091 8408160470 8408220496	70-8 50-440 Q 50-326 F WASTE MGT WASTE MGT	MILLS,L,M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8408070370 8408070376 8408070024 8408070025 8408070028	50-259 P NUREO 50-438 S 50-438 S 50-438 S
MCKINLEY, J C MCLAUOHLIN, P MCMANUS, A MCMILLEN, J, I MCMILLEN, J I	8408010202# 8406020280# 8408100144# 8408300060# 8408310302#	50-329 D 50-329 A 50-289 G 50-243 Q 50-255 Q	MILLER, H J MILLER, H J MILLER, H L MILLER, J, H MILLER, J, R	8408230096 8408230375 8408020132 8408020102 8408010071	WASTE MOT WASTE MOT 50-280 F REGOD 50-335 F	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8408070033 8408070057 8408070045 8408070078 8408070248	50-438 8 50-438 8 50-370 8 50-370 8 50-438 8
CMURRAY, C M MURRAY, C M MURRAY, C M MURRAY, C M MURRAY, C M	8408020021 8408030074 8408030074 8408070308 8408070308	50-322 T 50-322 0 50-322 0 50-322 0	MILLER, J R MILLER, J R MILLER, J. R. MILLER, J R MILLER, J R	8408010120 8408010303 8408070082 8408070142 8408070271	50-266 P 50-335 F 50-344 P 50-285 F 50-317 P	MILLB,L M MILLB,L M MILLB,L M MILLB,L M	8408070279 8408070416 8408100024 8408130275 8408130375	50-438 8 50-438 8 50-327 F 50-390 A 50-390 A
MURRAY.C M MURRAY.C M .MURRAY.C M .CMURRAY.C M .CMURRAY.C M	8408080338 8408080338 8408080410 8408080410 8408230179	50-322 0 50-322 0 50-322 0 50-322 0	MILLER, J R MILLER, J R. MILLER, J R MILLER, J R MILLER, J R	8408070472 8408070308 8408070311* 8408080035 8408130223	50-264 P 50-344 P 50-344 P 50-368 G 50-338 P	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8408140532 8408160058 8408160066 8408160154 8408160173	50-327 F 50-438 8 50-438 8 50-390 8 50-390 6
MCMURRAY,C M MCNEILL,C A MCNEILL,C A MCNEILL,C A MCNEILL,C A	8408230199 8408030254 8408030256 8408030287 8408140311	50-322 0 50-333 8 50-333 8 50-333 R 50-333 R	MILLER.J R MILLER.J R MILLER.J R MILLER.J R MILLER.J R	8408140029 8408140033* 8408140063 8408160167 8408170036	50-338 F 50-338 F 50-338 P 50-309 P 50-309 P	MILLS.L M MILLS.L M MILLS.L M MILLS.L M MILLS.L M	8408140179 8408140200 8408160434 8408210435 8408220137	50-370 8 50-438 8 50-438 8 50-370 A 50-257 P
MCNEILL,C A MCNEILL,C A MCNEILL,C A MCNEILL,C A MCNEILL,J D	8408210281* 8408230356 8408240243 8408270144 8408140458	50-333 0 50-333 8 50-333 8 50-333 8 50-458 0	MILLER, JR MILLER, JR MILLER, JR MILLER, JR	8408170147* 8408200002 8408200164* 8408200219 8408200325*	50-344 P 50-266 P 50-336 P 50-348 P 50-317 P	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8408230192* 8408230208* 8408270199* 8408270370* 8408270448*	50~257 G 50~257 G 50~257 G 50~257 G 50~327 G
MCNEILL, W M MCNEILL, W M MCGUADE, J MCGUEN, A D MCVEY, E A	8408130655* 8408200326* 8408300289 8408130450 8408060055	50-445 Q 50-458 Q NUREQ 50-204 F 50-373 B	MILLER, J R MILLER, J R MILLER, J R MILLER, L MILLER, L	8408200360* 8408200484 8408240017* 8408300390* 8408300397*	50-285 P 50-282 F 50-317 P 50-528 @ 50-528 @	Mille, L M Mille, L M Mille, L M Mille, L M Mille, L M	8408270475* 8408270483* 8408280086 8408280100 8408280116*	50-438 Q 50-438 Q 50-328 P 50-438 Q 50-259 Q
MECCA, J E MEDFORD, M. O MEDFORD, M. O MEDFORD, M. O MEDFORD, M. O	8408030279 8408010226 8408010240 8408010272 8408030166	WASTE MOT 50-206 P 50-341 P 50-204 P 50-206 P	MILLER,L MILLER,L F MILLER,L K MILLER,M MILLER,M	8408300407* 8408310244* 8408200276 8408200023* 8408210336	50-528	Mills, L M Mills, L M Mills, L M Mills, L M Mills, L M	8408280220 8408270245 8408270250 8408270355 8408300477*	50-260 F 50-259 F 50-390 A 50-390 A 50-327 Q
MEDFORD, M O MEDFORD, M O MEDFORD, M O MEDFORD, M O MEDFORD, M O	8408050000 8408050112 8408070411 8408100091 8408100115	50~361 P 50~361 G 50~204 G 50~361 P 50~361 P	MILLER, M MILLER, M E MILLER, M E MILLER, M E MILLER, M E	8408210336 8408130109 8408140024 8408150192 8408210351	50-454 G 50-322 G 50-354 G 50-322 G 50-322 G	MILSTEAD, W MILTENBERGER, S MILTENBERGER, S MILTENBERGER, S MILTENBERGER, S	8408220245 8408040148 8408070123 8408070271 8408140174	NUREG 50-483 8 50-483 8 50-483 8

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MILTENDERGER, S MILTENBERGER, S MILTENBERGER, S MILTENBERGER, S MILTENBERGER, S	8408160256 8408230427 8408230546 8408240173 8408240315	50-483 S 50-483 S 50-483 S 50-483 S 50-483 S	MOORE, R N MOORE, R N MOORE, R N MOORE, R N MOORE, R N	8408150402 8408150703 8408150705 8408170424 8408170425	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	MURPHY,W E  MURPHY,V J  MURPHY,W P  MURPHY,W P	8408220500* 8408170204 8408270295 8408080041 8408070085	50-382 Q 71-9192 HASTE MANA 50-271 F 50-271 Q
MINARICY, J P MINARICK, J W MINECK, D L MINECK, D L MINECK, D L	8408290190 8408290198 8408060141 8408160261 8408160471	NUREG NUREG 50-331 S 50-331 S 50-331 S	MORGAN,R C MORGAN,R E MORGAN,R E MORGAN,R E MORGAN,R E	8408140151* 8408060315 8408100004 8408160144 8408170188	50-400 T 50-261 8 50-261 F 50-261 R 50-261 8	MURPHY.W P MURPHY.W P MURPHY.W P MURRAY.B MURRAY.B	6406240004 6406270152 6406310093 8406090176 6406140226*	50+271 P 50-271 R 50-271 F 50-267 S 50-382 G
MINECK.D L MINECK.D L MINECK.D L MINER.S MINER.S	8408270202 8408230429 8408240172 8408040282 8408210159	50-331 S 50-331 R 50-331 S 50-312 F 50-312 P	MORGAN,R E MORGAN,R E MORGAN,R E MORGAN,R E MORGAN,R E	8408240095* 8408270521* 8408280035* 8408280133 8408290025*	50-261 0 50-261 0 50-261 0 50-261 0 50-261 0	MURRAY, B MURRAY, B MURRAY, T D MURRAY, T D MURRAY, T D	8408140515* 6408220157* 8408010313 8408080504 8408090026	50-458 0 50-458 0 50-344 8 50-346 8 50-346 8
MINICHIELLO, J MINNERS, W MINOGUE, R B MINOGUE, R B MINOGUE, R B	8408210426* 8408220265 8408160271* 8408160275* 8408160280*	50-29 P NUREG ORG ORG ORG	MORGANIR E MORGANIT A MORGENSTERNIA MORIARTYIJ M MORLEYIJ A	8408290028* 8408010276* 8408170220 8408200307 8408010046	50-261 Q 50-206 P XPURTLIC 50-352 S WASTE MOT	MUSCHICK.R P MUSCLF.D MUSCLF.D MUSCLF.D MUSCLF.D	8408280205 8407100420 8408080099 8408090011 8408130020	50-413 T 50-243 B 50-263 S 50-263 F 71-83
MINOR.G C MIRAGLIA.F J MIRANDBUKI.J A MIRANDWSKI.J A	8408030112* 8408030112* 8408240281* 8408230187 8408230024	50-322 G 50-322 G 50-27 F 50-423 D 50-410 D	MORLEY, J A MORLEY, J A MORLEY, J A MORLEY, J A MORJEY, J A	8408010064 8408150144 8408150400 8408150403 8408160278	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT	MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D	8408130024* 8408160222 8408160227* 8408170252 8408240238	71-83 50-263 P 50-263 P 50-263 P 50-262 S
MIRANDWBKI,JA MISCHEL,A MITTL,R L MITTL,R L MITTL,R L	8408230412 8408280073 8408010219 8408030069 8408040174	50-458 D PR 50-354 E 50-354 E 50-354 E	MORLEY, J A MORLEY, J A MORLEY, J A MORLEY, J A MORLEY, J A	8408200439 8408220227 8408220234 8408310270 8408310335*	HASTE MOT HASTE MOT HASTE MOT HASTE MOT	MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D MUTTENBERGE, S	8408270293 8408270299* 8408280160 8408280164* 8408210402	50-263 P 50-263 P 50-263 P 50-263 P 50-483 F
MITTL.R L MITTL.R L MITTL.R L MITTL.R L MITTL.R L	8408060279 8408080270 8408080344 8408100065 8408140336	50-354 A 50-354 E 50-354 A 50-354 F 50-354 E	MORLEY, J A MORLEY, R C MORRILL, P MORRIS, C MORRIS, P A	6408310339* 8408070419* 8408280078 8408070057 8408300148	WASTE MOT 50-412 F 50-342 S MISC 50-352 G	MYERB.C MYERB.C J MYERB.D O MYSINGER.E D NAGATA.P K	8408140346 8408300254* 8408270456* 8408020242 8408010027*	50-312 8 50-312 0 50-280 0 50-275 0 50-278 P
MITTL,R L MITTL,R L MITTL,R L MITTL,R L MITTL,R L	8408160336 8408160348 8408170052 8408170103 8408170336	50-354 A 50-354 E 50-354 F 50-354 E 50-354 G	MORRIS,T W MORTON,H W MORTON,K V MORTON,K V MORTON,K V	8409220301 9409070462* 8409060426* 8409070037* 8409080008*	50-322 G FRM CONTRACT CONTRACT CONTRACT	NAIDU, K NAIDU, K NAPUDA, G NAPUDA, G NAPUDA, G	8408300220* 8408300176* 8408080242* 8408070330* 8408150455*	50-341 0 50-440 0 50-244 0 50-322 0 50-333 0
MITTL.R L MITTL.R L MITTL.R L MITTL.R L MITTL.R L	8408170337 8408210442 8408230352 8408240273 8408240273	50-354 A 50-354 A 50-354 A 50-354 E 50-354 D	MORTON, K V MORTON, K V MOUNT, D K MOUNT, D R	8408070016* 8408070074* 8408140517* 8408010334 8405310267	CONTRACT CONTRACT CONTRACT State Preg PR	NARASIMHAN,T N NARBUT,P NARBUT,P P NARDI,A J NARDI,A J	8408310344* 8408300195* 8408300407* 8408010040 8408140352	WASTE MGT 50-528 G 50-528 G 70-1151 70-1151
MITTL.R L MITTL.R L MITTL.R L MITTL.R L MITTL.R L	8408280201 8408290002 8408290098 8408290134 8408300153	50-354 E 50-354 F 50-354 A 50-354 E 50-354 A	MOURY, W R MOURY, W R MOURY, W R MOXLEY, M MROCZKA, E J	8408020253 8408150109 8408270311 8408240399 8408070112	70-734 71-6346 50-89 F 40-4492 50-245 S	NARROW, L NARROW, L NARUS, G E NARUS, G E NASLUND, C D	8408230285* 8408300116* 8408010313 8408160179 8408230427	50-293
MITTL.R L MIZUNO.Q S MIZUNO.Q S MIZUNO.G S MIZUNO.G S	8408310198 8408270055 8408270094 8408270097 8408280232	50-354 K 50-445 G 50-445 G 50-445 G 50-445 G	MROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J	8408070112 8408080531 8408200574 8408200574 8408230431	50~245 S 50~336 S 50~336 R 50~336 R 50~245 R	NASLUND,C D NAUTZ,J L NEIGHBORB,D NEIGHBORB,D NEIGHBORB,D	8408230546 8408070451 8408010161 8408010208 8408040407	50-483 8 PRM 50-280 P 50-305 P 50-305 P
MIZUNO, G S MIZUNO, G M M M M M M M M M M M M M M M M M M M	8408300139 8405210578 8405210579 8408280433 8408280433	50-445 G NUREG NUREG 50-322 G 50-322 G	MROCZKA,E J MROCZKA,E J MROCZKA,E J MROCZKA,E J MUDD,C H	8408230431 8408280262* 8408270004 8408270004 8408060070	50-245 R 50-423 E 50-245 8 50-245 8 50-348 F	NELSON, PR NELSON, GH NELSON, MA NELSON, PR	8408310112* 8408270346* 8408270348 8408220365* 8408030147*	TOPREP 70-734 PR 50-289 P 70-371
MONICK,R J HONTGOMERY,D M MONTGOMERY,D M MONTGOMERY,D M MONTGOMERY,D M	8408270508* 8408270386* 8408270439* 8408280123* 8408280329*	CONTRACT 50-369 Q 50-324 Q 70-1113 50-413 Q	MULDER, R J MUFFETT, J W MUFFETT, J MUDD, C H	6408230324 6408280288 6408140341* 8408080175* 8408010350	50-348 F 50-265 8 50-341 0 50-454 Q 50-62 F	NELBON,R E NERBEB,V NEUMEYER,B A NEVILL,J F NEWMAN,J R	8408270276* 8408230381 8408080272 8408140023* 8408140176	50~454 E 50~443 A 50~445 T 50~400 T 50~498 0
MONTCOMERY, E F MONTCOMERY, J MONTCOMERY, R MOONEY, C MOONEY, C	8409150495* 8409150499 8409200288* 8409270042 8408270424	50~322 T 50~289 G 50~528 S 40~8502 40~8502	MULDER: R U MULLER: R MULL TOAN: M MULL TOAN: M MULL TRIN: R	8408010371 8408010204* 8408070258 8408170381 8408150515*	50-62 F 50-327 D 50-352 G 50-352 G 50-382 G	NI CHOLAB! H NGOYEN! H NGOYEN! H	8408160176 8408160370* 8408210426* 8408080470* 8408070330*	50-498 G 50-458 A 50-27 P 50-267 G 50-322 G
MOONEY, J MOONEY, J A MOONEY, J A MOORE, D E MOORE, J E	8408150408* 8408070180* 8408150735* 8408130144* 8408070397	50-327 A 50-327 A 50-329 A 50-269 G 50-400 G	WANTEA'L E WANTEA'L E WANTEA'L E WANTEA'L E WANTEA'L P	8408020201 8408010293 8408030177 8408090265 8408210189	71-9021 50-219	NICHOFR'N N NICHOFR'N N NICHOFR'N N NICHOFR'N N	64080B0256# 8408070372 8408070372 8408240254 8408240254	50-289 Q 50-352 Q 50-352 Q 50-352 T 50-352 T
MOORE, J E MOORE, J, E MOORE, J E MOORE, J E MOORE, R N	8408070172 8408150111 8408200470 8408270122 8408060350	50-400 G 50-247 G 50-400 G 50-400 G XPORTLIC	MURLEY, T E	840821019&* 8408230290 8408230304 8408270335 8408280180	70-303 50-277 F 50-309 F 50-334 Q 50-322 Q	NIEMCIAK'R Y NICHOTADN'R Y NICHOTADN'R Y NICHOTADN'R Y	8408080496# 8408150547# 8408030002 8408310331 8408070027#	50-295 G 50-263 G I&E HASTE MOT 50-447 H
MOORE, R. N MOORE, R. N MOORE, R. N. MOORE, R. N MOORE, R. N	8408060351 8408060353 8408060359 8408070049 8408150182	XFORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	MURPHY, J. A MURPHY, J. D MURPHY, L. Q MURPHY, M. E. MURPHY, M. E.	8404040078* 8408170070 8408310082 8408040325* 8408160237*	50-38B U 71-9192 CONTRACT 50-382 G 50-438 G	NIEMCZYK,S J NIGHTINGALE,E NIMITZ,R L NIMITZ,R L NIMITZ,R L	8408160339 8408170117* 8408010286* 8408010272* 8408210244*	50-447 A 50-443 Q 50-247 Q 50-245 Q 50-247 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
NIMITZ,R L NIX,H NIX,H NIX,H C NIX,H C	8408230246 * 8408210472 8408280233 8408090287 8408200301	50-322 Q 50-321 F 50-321 F 50-321 S 50-321 R	O'NEILL, J O'NEILL, J O'NEILL, J O'NEILL, J O'NEILL, J O'NEILL, J	8408210330# 8408210337* 8408210432 8408020054 8408020054	50-155 G 50-155 G PR 50-400 G 50-400 G	PAGE.R G PAGE.R G PAGE.R G PAGE.R G PAGE.R G	8408050358 84080603758 8408070259 8408170310 8408230055	70-2988 70-2988 70-2884 40-2061 40-2061
NIX'H C NIX'H C NIX'H C NIX'H C	8408200438 8408220491 8408270229 8408300333 8408300517	50-366 S 50-366 S 50-321 S 50-321 S 50-366 S	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8408280244 8408070357 8408070360* 8408300352 8408300356	50-155 G 50-280 G 50-280 G 50-321 F 50-369 G	PAHWA, S B PALLADINO, N PALLADINO, N PALLADINO, N J PALLADINO, N J	8408080321* 8408140566* 8408150654 8408010277* 84080800334	CONTRACT 50-329 A WASTE MGT 50-275 U COMMISSION
NOTODIN R NORĐERHAUG, L. R NORELIUS, C NORELIUS, C NORELIUS, C	8408150293* 8408210167* 8408090049 8408150029* 8408010302	50-255 Q 50-142 Q 50-456 Q 50-329 A 50-151 Q	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8408300354 8408300371 8408300375 8408300376 8408300392	50-348 F 50-416 P 50-413 V 50-321 F 50-250 P	PALLADIND, N J	8408080427 8408080430 8408090109 8408090111* 8408090214	COMMISSION 50-416 U COMMISSION COMMISSION COMMISSION
NGRELIUS, C E NORELIUS, C E NORELIUS, C E NORELIUS, C E NGRELIUS, C E	8408010312 8408010314* 8408070056 8408140344 8408150433*	50-374 0 50-374 0 90-10 0 50-10 0 50-329 0	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8408300392 8408300402 8408300417 8408300434 8408300519	50-335 V 50-259 F 50-302 F 50-259 P 50-327 F	PALLADINO,N J PALLADINO,N J PALLADINO,N J PALLADINO,N J PALOMINO,F G	8408220444 8408280467 8408290154 8408290348 8408010239	50-320 P COMM15810H 50-320 U COMM15810H 50-322 Q
NORELIUBJC E NORELIUBJC E NORELIUBJC E NORELIUSJC E NORELIUSJC E	8408150728+ 8408150732+ 8408150734+ 8408170174+ 8408170236+	50-327 A 50-327 A 50-327 A 50-329 Q 50-329 Q	O'REILLY, J P	8408300520 8408310014 8408310036 8408310054 8408310107	State Prog 50~261 V 50~259 V 50~250 V 50~259 e	PALOMINO,F G PALOMINO,F G PALOMINO,F G PANCIERA,V PANCIERA,V	8409140005 8409140470 8409140477* 8409270269* 8409270351*	50-322
NORELIUB: C E NORELIUB: C E NORELIUB: C E NORELIUS: C E NORELIUS: C E	8408170276* 8408210193 8408230549 8408230551* 8408240332	50-329 S 50-374 G 50-254 G 50-254 G 50-352 S	0.100FE'1 D 0.100FE'1 D 0.100FE'1 D 0.100FE'1 D	B408020138 6408060349 B408070114 B408070421 B408070425	50-247 P 50-3 F 50-247 F 50-247 F 50-247 G	PANCIERA, V PANCIERA, V W PANDEY, S PANGBURN, G C PANGBURN, G C	8408280152 8408240371* 8404040075* 8408230481* 8408240212	50-424 8 50-424 0 50-388 U 40-8102 40-8452
NORELIUS C E NORMAN C R NORMAN C R NORRHOLM L NORRHOLM L	8408270287 8408010269* 8408010269* 8408010300* 8408100072	50-409 0 50-155 0 50-155 0 50-247 0 50-247 S	O'TOOLE.J D O'TOOLE.J D O'TOOLE.J D O'TOOLE.J D	8408130211 8408130325 8408130398# 8408150121 8408200309	50-247 P 50-247 F 50-247 Q 50-3 F 50-247 Q	PANGBURN, G C PANGBURN, G C PANGBURN, G C PANGBURN, G C PAGELING, R J	8408240216 8408270035 8408270055 8408270106 8408080256*	40-8402 40-8102 40-8102 40-8452 50-269 Q
NORRHOLM: L NORRHOLM: L J NORRHOLM: L J NORRHOLM: L J NORRIS: J	8408310251 8408030031* 8408070237* 8408150370* 8408280284	50-286 0 50-272 0 50-272 0 50-272 0 50-275 P	0.100TE'7 D 0.100TE'7 D 0.100TE'7 D 0.100TE'7 D	8408200539 8408210002 8408220214 8408240164 8408290279	50-247 5 50-247 F 50-247 5 50-247 P 50-247 Q	PAPAZOGLOU, I A PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J	8408220333 8408010297 8408010332 8408020150 8408020140	50-352 A 50-409 G 50-454 G 50-266 F 50-266 F
A C.SIRRON A C.SIRRON A C.SIRRON D G.YRRON O G.YRRON	8408040335 8408130047 8408170033 8408070103 8408080177	50-295 P 50-295 P 50-295 P DRG DRG	OBERG, C R ODEGAARDEN, R H OESTMANN, M J OESTMANN, M J DGLE, K M	8408150102* 8408060420 8408150401* 8408270288* 8408240402	50-445	PAPERIELLO,C J PAPERIELLO,C J PAPERIELLO,C J PAPERIELLO,C J PAPERIELLO,C J	8408020220 8408030251 8408040095 8408040110 8408080485	70-8 50-10 Q 50-373 F 50-155 Q 50-295 Q
NDRRY.P C NORRY.P G NORRY.P G NORTH.H NORTH.H	8408130560* 8408150535 8408300222 8408070416 8408070004*	PRM DRG DRG 50-312 8 50-361 0	DGLE.K M DKADA.S DKADA.S OKADA.S OKRENT.D	8408270550 8408060402 8408060406 B408060438* 8408270142	40-8502 XPORTL1C XPORTL1C XPORTL1C 50-142 P	PAPERIELLO.C J PAPERIELLO.C J PAPERIELLO.C J PAPERIELLO.C J PAPERIELLO.C J	8408080488* 8408100026 8408130103 8408130401 8408150380	50-295 G 50-483 G 50-454 G 50-10 F 50-440 G
NORTH, H ORTH, H RTH, H S 'TON, J TON, J F	8408070080* 8408070071* 8408230087* 8408230144* 8408080175*	50-344	OLIVEIRA, W OLIVEIRA, W OLIVERIA, W OLSEN, A F OLSEN, A F	8408080242* 8408090330* 8408080166* 8408020203 8408150115	50-244 @ 50-322 @ 50-387 @ 70-824 50-13 P	PAPERIELLO,C J PAPERIELLO,C J PAPERIELLO,C J PAPERIELLO,C J PAPERIELLO,C J	8408150386 8408150392 8408150399 8408150544 8408150546#	50-494 Q 50-254 Q 50-246 Q 50-263 Q
ACHEK, F AK, T M AK, T M JAK, T M VAK, T M	8408080514 8209230534* 8407310030 8407310032 8408090323	50~267 B 50~329 E 50~454 S 50~454 Q 50~423 E	OLSHAN, L N OLSHAN, L N OLSON, J F OLSON, D L OPEKA, J F	8408010185 8408090528 8408080334* 8408210038 8408070220	30-454 E 50-454 Q PR WASTE MGT 50-423 A	PAPERIELLO.C J PAPERIELLO.C J PAPERIELLO.C J PAPERIELLO.C J PAPERIELLO.C J	8408150638 8408200233 8408270084 8408270278 8408270309	50-341 0 50-155 0 50-341 0 50-440 0 50-295 F
IDVAKIT M NOVAKIT M NOVAKIT M NOVAKIT M	8408130160 8408130548* 8408210410* 8408210414* 8408210464*	50-528 F 50-329 A 50-329 A 50-329 A 50-329 Q	OPEKA, J F OPEKA, J F OPEKA, J F OPREA, G W OPREA, G W	8408070220 8408100043 8408100063 8408150387 8408210076*	50-423 A 50-213 P 50-213 P 50-498 S 50-498 Q	PAPERIELLO,C J PAPERIELLO,C J PAPERIELLO,C J PAPERIELLO,C J PAPERIELLO,C J	8408270348 8408270370 8408270177 8408310173 8408310268	50-341 G 50-155 G 50-266 F 50-262 F 70-1308
NOVAK,T M NOVAK,T M NOVAK,T M NOVAT,J NOWAK,A S,	8408270463 8408230247 8408270041 8408160146 8408150720#	50-352 A 50-454 Q 50-413 F NUREG 50-329 A	OPREA, O N OPREA, O W OPREA, O W OPREA, O W OPREA, O W	8408210311 8408210500 8408220130 8408240312 8408270212	50-498 A 50-498 B 50-498 S 50-498 S 50-498 G	PAPERIELLO,C J PARK.J Y PARKER,Q E PARKS.R D PARBONS,G E	8408310288 8408240322 8408060266 8408220373* 8408230178*	50-305 G NUREG WASTE MGT 50-289 G 40-791
NUGENT, E L NUGENT, E L NUMARK, N J NUSSDAUMER, D NUSSDAUMER, D A	8408200400 8408240414 8408010193 8408130077 8408230362	40-2257 40-2257 WASTE MGT WASTE MGT WASTE MGT	OPREA, G N ORDERS, W ORTIZ, N R OSBORNE, D B OSTER, J	8408300370 8408270279* 8408300178 8408200161 8408290038	50-498 S 50-369 G WASTE MANA 50-336 P 50-10 J	PARSONB, R M PARSONG, R M PARSONS, R M PARSONS, R M PARSONG, R M	8408070018 8408070031 8408070066 8408070131 8408070271	50-400 S 50-400 S 50-400 S 50-400 S 50-400 S
NYKIRK, J NYKIRK, J D'CONNOR, P W D'CONNOR, P W G'CONNOR, P W	8408070239 8408070240 8408010[87 8408070394 8408210558	50-295 F 50-295 F 50-482 A 50-482 A 50-482 F	OSTRANDER, N C OTTO, H W OTTO, S M QUELLETTE, R W PAGE, M	8408300109 8408070284 8408090144 8408300501 8408290150	50-142 R 50-354 H 50-289 S 50-413 S CONTRACT	PARSONS.R M PARSONS.R M PARSONS.R M PARSONS.R M PARSONS.R M	8408140027* 8408160168 8408160408 8408160416 8408160437	50-400 T 50-400 S 50-400 S 50-400 S 50-400 S
D'CGNNOR:P W D'CGNNOR:P W D'DWYER:8 O'NEILL:J G'NEILL:J	8408280037 8408300075 8408150475* 8408160392 8408210327	50-482 F 50-482 F 50-341 G PR 50-155 G	PAGE, M PAGE, M PAGE, M PAGE, M PAGE, M	8408230484 8408270547 6408270591 8408310240 8408310343	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	PARBONS, R M PARSONS, R M PARSONS, R M PARSONS, R M PARSONS, R M	8408160438 8408160443 8408280460* 8408280465* 8408280465*	50-400 S 50-400 S 50-400 Q 50-400 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
PAREONS,R M PARVIN,M J PARVIN,M J PABCIAK,W PASCIAK,W J	8408300350* 8408140224* 8408140224* 8408240231* 8408010398*	50-400	PAULSON, W A	8408300102 8408300111* 8408300128 8408300148 8408300172	50-237 P 50-237 P 50-255 Q 50-219 P 50-219 F	PETTENOILL, H J	8408270041 8408270044 8408270047 8408270053 8408270055	40-2259 40-3453 40-1162 40-8584 40-8102
PASCIAK, W J PASCIAK, W J PASCIAY, W J PASCIAK, W J	9408080209# 8408080457# 8408150305# 8408150541# 8408150701#	50~220	PAULSON,W A PAULTON,B R PAVINICH,W A PAVINICH,W A PAWLICY,E T	8408310125 8408020065 8408210387* 8408210393* 8408220190*	50-213 S 50-297 P 50-338 P 50-338 P 50-329 Q	PETTENDILL, H J	8408270062 8408270064 8408270068 8408270106 8408270228	40-3453 40-297 40-297 40-8452 40-8084
PASCIAK, W J PASCIAK, W J PASCIAK, W J PASCIAK, W J	8408200544* 8408230157* 8408230248* 8408230495* 8408270473*	50-247 Q 50-352 Q 50-322 Q 50-309 Q 50-333 Q	PAWLICF,E T PEARRING,J R PECK,S PEEBLES,T A PEEBLES,T A	8408020194* 8408130085 8408020228 8408210441 8408270329*	50-327 @ WASTE MGT 40-8724 50-250 # 50-250 @	PETTENGILL,H J PEWBLE,J A PFAFF,S J PHILBRICK,S S PHILBRICK,S S	8408270248 8408290310 8408240346 8408020237 8408020237	40-8584 50-454 G 40-6659 ACR8 ACRS
PASTVA, M J PASTVA, M J PASTVA, M J PASTVA, M J D M, AVTBAP	8408040128 8408090032 8408090390 8408090432 8408160075	50-325	PEERY,W W PELIZZA,M 6 PELLET,J L PELLET,J L PELLET,J L	8408270531* 8408240353 8408040099* 8408090037* 8408090073*	70~27 40-8786 50~482	PHILLIPS, A PHILLIPS, H W PHILLIPS, M P PHILLIPS, M P	8408140039* 8408170117* 8408070478* 8408010279* 8408130374*	50-329 A 50-443 Q 50-29 P 50-409 Q 50-454 Q
PASTVA,M J PASTVA,M J PATAWA,E H PATE,R J PATE,R J	8408140133 8408240227 8408010114 8408070045 8408070479	50-325 8 50-324 \$ WASTE MOT 50-323 V 50-275 V	PELLETIER, J P	8408230534 8408230542 8408280307 8408300478 8408300488	50-271 8 50-271 8 50-271 8 50-271 8 50-271 8	PHILLIPS,M P PHILLIPS,M P PICARD,R R PICIDCCHI,J H PICKETT,D	8408150646* 8408240429* 8408080409 8408210084 8408300219*	50-341 Q 50-305 Q NUREG XPORTLIC 50-366 P
PATE, R J PATE, R J PATE, Z T PATE, Z T PATEL, B R	8408070045# 8408310243 8408020091 8408220310# 8408210382#	50-361 G 50-204 G NUREG ORG TOPREP	PELROY,R A PELTON,J R PENNIFILL,R A PENNIFILL,R A PENNIND,B J	8408310075 8408140414* 8408070328 8408230027 8408270147*	NUREO 50-508 A WASTE MGT WASTE MGT 50-412 E	PIERINGER,P PIERSON,R PILANT,J M PILANT,J M PILANT,J M	8408310042 8408270279* 8408030011 8408070267 8408070275	50-318 S 50-369 G 50-298 G 50-298 F 50-298 P
PATEL, B R PATON, W D PATON, W D PATON, W D PATON, W D	8408210392* 8408020183* 8408020185* 8408070377 8408130348*	TOPREP 50-329	PENTZ.D L PEPIN.J O PERANICH.M PEREIRA.D B PEREZ.Q P	8408230336* 8408200154 8408150515* 8408070045* 8408300254*	CDNTRACT HASTE MOT 50-382	PILANT, J M PILANT, J M PILANT, J M PILANT, J M PILANT, J M	8408070316 8408100014 8408100145 8408140431 8408150447	50-278 R 50-278 R 50-278 P 50-278 F 50-278 I
PATONIN D PATONIN D PATONIN D PATONIN D PATONIN D	8408140158* 8408140539* 8408150616* 8408150752* 8408210391*	50-327 A 50-327 A 50-327 A 50-327 A 50-327 G	PERKINS,A J PERKINB,L K PERLIS,R G PERLIS,R G PERLIS,R G	8408140449 8408240393 8408010189 8408010201 8408070403	50-219	PILLAY, % S PINSKY, Q P PIRFO, O R PIRFO, O R	8408080409 8408230109 8408130077 8408130138 8408130176	NUREO TOPREP 50-498 Q 50-498 Q 50-498 Q
PATTERSON, C A PATTERSON, J P PATTON, J D PAUL, R A PAULITZ, F P	8409230240# 8409130646# 8408060277 8408150406# 8408080256#	50-259	PERLIS.R G PERLIS.R G PERLIS.R G PETERS.R J	8408200607 8408270103* 8408270111 8408280452 8408210639	50-322	PIRFO,OR PIRTLE,O PIRTLE,O PIRTLE,O PIRTLE,O PISCHINGER,F	8408280394 8408150747* 8408150750* 8408210471* 8408150498*	50-498 G 50-329 A 50-329 A 50-461 G 50-322 T
PAULKIG L PAULSON,W A PAULSON,W A PAULSON,W A	8408230240# 8408010030 8408070052 8408070210 8408070251	50-257 G 50-245 P 50-217 P 50-213 P 50-244 P	PETERSON, C H PETERSON, K A PETERSON, T PETRICK, N A PETRICK, N A	8408230423 8408280016* 8408270308 8407310144 8408040234	WASTE MOT 40-8502 50-454	PISCHINGER,F F PISCHINGER,F F PITTMAN,J PITTE,J PITTE,J,	8408150514* 8408150530* 8408220265 8408080051 8408080051	50-322 T 50-322 T NUREG 50-445 T 50-445 T
PAULSON, W A	8408070255* 8408070304 8408070331 8408070099 8408070179	50-244 P 50-217 P 50-204 P NUREG 50-255 F	PETRICK,N A PETRICK,N A PETRICK,N A PETRICK,N A PETRONE,C	8408160063 8408210313 8408270387 6408300070 8408270483*	50-482 F 50-482 A 50-482 F 50-482 F 50-322 Q	PLAINE, H H PLAINE, H H PLIML, G PLIML, G PLISCO, L	8407300105 8408070102 8408140428 8408310148 8408070053#	50-322 A COMMISSION 50-295 F 50-295 F 50-387 Q
PAULSON, W A	8408070275 8408070281* 8408070307 8408130282 8408130287	50-244 P 50-244 P 50-155 P 50-29 P 50-10 F	PETROWSKI,6 PETROWSKI,6 E PETTENGILL,H J PETTENGILL,H J PETTENGILL,H J	8408200547 8408040270 8408210110 8408210120* 8408210129	50-304 8 50-304 8 40-2259 40-2259 40-4492	PLISCOLL R PLUMLEE, K E POINDEYTER, T C	8408200041# 8408150394# 8408160516# 8408030148# 8408010328	50-387 Q 50-454 Q 50-267 Q 70-371 50-320 P
PAULSON, W A	8408130358 8408130366 8408150225 8408150267 8408160062	50-27 P 50-255 D 50-217 P 50-217 F 50-237 P	PETTENGILL.H J PETTENGILL.H J PETTENGILL.H J PETTENGILL.H J PETTENGILL.H J	8408210143* 8408230472 8408230481* 8408240142 8408240163	40-4492 40-8102 40-8102 40-3453 40-299	POLK, P J POLK, P J POLLOCK, M S POPPE, L K POTAPOVB, U	8408070055 8408070545 8408270486* 8408170021 8405300171	50-286 P 50-286 P 50-322 G 71-6244 GA999
PAULSON, W A	8408160070* 8408160147 8408160353 8408160356* 8408170130	50-237 P 50-29 P 50-244 P 50-244 P 50-206 P	PETTENGILL.H J PETTENGILL.H J PETTENGILL.H J PETTENGILL.H J PETTENGILL.H J	8408240174 8408240182 8408240185 8408240187 8408240170	40-4492 40-4492 40-299 40-299 40-3453	POTAPOVS.U POTAPOVS.U POTAPOVS.U POTTER.J P POULOS.B J	8408010364 8408080218 8408310232 8408210485 8210130322*	GA999 GA999 CONTRACT I&E 50-329 A
PAULBON, W A	8408170143# 8408210001 8408210008 8408210029 8408210307	50-204 P 50-10 F 50-219 P 50-409 P 50-255 P	PETTENGILL.H J PETTENGILL.H J PETTENGILL.H J PETTENGILL.H J	8408240192 8408240197* 8408240207 8408240209 8408240212	40-299 40-299 40-8698 40-8084 40-8452	001.03,8 J 9001.03,8 J 9001.03,8 J 9001.03,8 J	8305270222* 8408020181* 8408140185* 8408140196* 8408140296*	50-329 A 50-329 G 50-329 A 50-329 A
PAULBON, W A	8408210338 8408210371 8408220073 8408220326 8408230384	50-155 P 50-204 P 50-409 P 50-213 P 50-219 P	PETTENGILL, H J	8408240216 8408240340 8408240345 8408240347 9408240373	40-8602 40-6622 40-1162 40-6622 40-8698	POWELL, A. W POWELL, P. C POWERS, G. M POWERS, C. M POWERS, C. M.	8408140151* 8408130212* 8408030280 8408040233 8408040235	50-400 T 70-938 50-397 8 50-397 8 50-397 8
PAULSON, W A	8408230418 8408240266 8408270001 8408270136 8408300048	50-407 P 50-29 F 50-155 P 50-206 P 50-255 F	PETTENGILL.H J PETTENGILL.H J PETTENGILL.H J PETTENGILL.H J PETTENGILL.H J	8408240380 8408270022 8408270033 8408270035 8408270037	40~279 40~6659 40~1162 40~8102 40~299	POWERS,C M POWERS,C M POZDOLSKI,A PRASSINOS,P G PRATT,W T	8408040301 8408270143 8408270281 8408170155 8408070208	50-397 8 50-397 8 50-454 0 NUREG 50-206 P

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PRELL.JA PRENDERGASI,K PRENDERGASI,K PRESTHOLT,P T PRICE,J	84080900514 84083001274 84083005044 8408200474 8408280112	50-\$28 G	RAY,C L Ray,C L Ray,C L Ray,C L Ray,C L	8408160394 8408160395 8408160395 8408290179 8408290179	50-206 5 50-206 5 50-206 6 50-206 5 50-206 5	REYTBLATT, Z REYTBLATT, Z REYTBLATT, Z REYTBLATT, Z REYTBLATT, Z	8408280391* 8408280407* 8408280411* 8408280411* 8408280422*	50-295 P 50-295 P
PROBST.JR PROTO.NT PROTO.NT PROTO.NT PROTO.NT	8408220202 8408080173 8408080173 8408080180 \ 8408080180 \		RAY.H B RAY.H B RAY-HDLMES.P RAYMDND.W J RAYNOR.J	8408140260 8408200335 8408270269* 8408030229* 8408200512		REYTBLATT, Z V REYTBLATT, Z V REYTBLATT, Z V REYTBLATT, Z V REYTBLATT, Z V	8408280340 8408280346* 8408280373* 8408280383* 8408280387*	50-295 P 50-295 P 50-295 P 50-295 P 50-295 P
PROUDMAN. 6 PUGH. C E PULLANI. S V PURDY. O PURDY. G	8408210349 8408080355 8408210501* 8408230432 8408280221	PR NUREG 50-245 Q 50-445 T 50-445 Q	RAYNDR, J W REA. K REAGAN, E E REAGAN, E E REAGAN, E E	8408200492 8408010166 8408150739* 8408150742* 8408150744*	71-9073	RHODES,M L RIANI,L RICE.B J RICE.B B RICE.R A	8408070273 8408220265 8408200425 8408200603 8408310154	50-445 T NUREQ WASTE MOT 40-2061 PR
PUTMAN.K 8 PUTNAM.K 6 PUZEY.A M PUZEY.A M PUZEY.A M	8408230427 8408040141 8408040058 8408100058 8408210272	50-331 R 50-331 S 50-344 F 50-344 F 50-344 F	REAVIS, J A REAVIS, J A REAVIS, J A REBELOWSKI, T A	8408220465 8408220468 8408300406 8408300509 8408290007*	50-369 R 50-269 R 50-413 R 50-370 R 50-423 G	RICHARD, J B RICHARD, J B RICHARD, J B RICHARD, J B RICHARD, J B	8408070496 8408130130 8408130160 8408160061 8408160421	50-416 P 50-416 P 50-416 P 50-416 B 50-416 B
QUAMME, D L QUENNOZ, S M QUENNOZ, S M QUENNOZ, S N QUINTANA, C A	8408150651* 8408160497 8408230104 8408160199 8408080259	50-329 A 50-346 S 50-346 R 50-346 S NUREQ	REED, J REEVES, E A REGAN, N A REGAN, N A REGAN, H H	8408270333 8408240227 8408130454 8408210483 8408020135	50-35원 A 50-34청 F 70-27 70-27 50-35운 M	RICHARD. J B RICHARD. J B RICHARDB. B A RICHARDB. B A RICHARDB. W J	8408200127 8408280194 8408240287 8408300380* 8408070344	50-417 A 50-416 G 50-344 B 50-344 G PR
GUIRK.J F RADER.R M RADER.R M RADER.R M RADER.R M	8408140377 8408040053 8408040053 8408040182 8408070343	TOPREP 50-352 G 50-352 G 50-352 G 50-352 G	REHM, T A REHM, T A REHM, T A REID, K	8408080486 8408150656* 8408160030 8408300290 8408310042	COMMISSION 50-327 A COMMISSION COMMISSION 50-318 S	RIDDLE,R R RIDGWAY,D A RIDGWAY,D A RIDGWAY,D A RIDGWAY,D A	8408070510* 8408070418 8408070418 8408070470 8408070470	CONTRACT 50-320 0 50-320 0 50-320 0 50-320 0
RADER, R M RADER, R M RADER, R M RADER, R M RADER, R M	8408070363 8408070412 8408070412 8408070444 8408070444	50-352 Q 50-352 Q 50-352 Q 50-352 Q 50-352 Q	REINMUTH, O W REINSCH, M D REIS, E J REIS, H F REIS, H F	8408150729* 8408030133 8408280374 8408210347 8408210347	50-327 A QA999 50-498 G 50-250 G 50-250 G	RIDGWAY,D A RIDGWAY,D A RIDGWAY,D A RIDGWAY,D A RIDGWAY,D A	8408140004 8408140004 8408140008 8408140008 8408140022	50-400 G 50-400 G 50-400 G 50-400 G
RADER,R M RADER,R M RADER,R M RADER,R M RADER,R M	8408080389 8408080389 8408150477 8408150477 8408280223	50-354 G 50-354 G 50-352 G 50-352 G 50-354 G	REIS.H F REIS.H F REMIS.S REMIS.S C REMIS.S C	8408210380 8408210380 8408270136 8408040070 8408090255	50-250	RIDGWAY, D A RIDGWAY, D A RIDGWAY, D A RIDGWAY, D A RIDGWAY, D A	8408140022 8408140048 8408140048 8408140057 8408140057	50-400 G 50-400 G 50-400 G 50-400 G
RADER,R M RADER,R M RADER,R M RADFORD,E P RADFORD,E P	8408280223 8408280388 8408280388 8408020021 8408020021	50-354 Q 50-352 Q 50-352 Q 50-322 T 50-322 T	REMIS.S C REMIS.S C REMIS.S C REMIS.S C REMIS.S C	8408140543 8408230093 8408230090* 8408280447 8408290014	50-354	RIEDL,T J RIGERT,J A RIGEB,R RILEY,A RILEY,S L	8408160340* 8408130357* 840820265 840810030 840810076	50-445 A 50-322 G NUREQ 50-454 T 50-322 G
RAHE, E P Rahe, E P Rahe, E P Rahe, E P Rahe, E P	8407230200 8408060116 8408080278 8408140278 8408230340	TOPREP TOPREP 50-601 K 50-601 A TOPREP	REMLEY, M E REGUA, G REGUA, G REGUA, O RESSLER, W C	84081 50564 <i>8408030248</i> 8408070444 8408270074 8408070334	20-582 k 20-591 b 20-591 b 20-521 b	RILEY,S L RILEY,S L RILEY,S L RILEY,S L	8408160079 8408160099 8408160103 8408160109 8408160112	50-352 Q 50-352 Q 50-352 Q 50-413 Q 50-352 Q
PAHE, E P AHE, E P AHE, E P ANDALL, R ANDALL, R	8408270312 8408270449 8408280259 8408030201 8408080259	TOPREP TOPREP TOPREP 50-220 9 50-220 8	REST.J REYES.L REYES.L A REYES.L A REYES.L A	8408310077 8408100109 8408150475* 8408160193* 8408230149*	NUREG 50-275 8 50-341 9 50-483 0	RILEY,8 L RILEY,8 L RILEY,8 L RINALDI,F RING,M	8408140118 8408140123 8408160128 8408020175* 8408230252*	50-322 Q 50-322 Q 50-400 Q 50-327 A 50-454 Q
ANDALL,R ANDALL,R (ANDAZZA,J 8 RANDEN,L RANGE,J J	8408080483 8408200535 8408020121 8408240040 8408280394	50-220 8 50-220 6 50-309 K 40-8727 50-322 T	REANOFDR'N B REANOFDR'N B REARRY Y BEAER'F Y	8408230252* 8408300188* 8408060046 8408060046 8408060217	50-454 G 50-315 G 50-275 G 50-275 G 50-275 G	RIDRDON, B. J RITNER, T H RITTSCHER, D RIVENBARK, G RIVENBARK, G	8408080472 8408240347 8408090362 8408080397 8408080445	NUREO 40-8502 PROJ 50-312 F 50-312 F
RANGE, J J RAPKIN, A RAPKIN, A RAPKIN, A RAPKIN, A	8408280394 8408070311 8408130329 8408130337* 8408170383	50-322 T 40-2061 40-2061 40-2061 40-2061	REYNOLDS, J R REYNOLDS, J R REYNOLDS, J R REYNOLDS, J R	8408060217 8408070297 8408130389 8408130389 8408140464	50-275	RIVENBARK, G RIVENBARK, G W RIVENBARK, G W RIVENBARK, G W RIVENBARK, G W	8409090207 8406220100 8408020172 8408020173* 8408070502*	50-321 F 50-277 P 50-346 P 50-346 P
Rapkin, a Rapkin, a Rapkin, a Rapkin, a Rasmursen, L C	8409170387* 8409170389* 8409170374 8409270008 8408020088	40-2061 40-2061 40-2061 40-2061 PR	REYNOLDB, J R REYNOLDB, J R REYNOLDB, J R REYNOLDB, J W REYNOLDB, J W	8408140464 8408310210 8408310210 8408030113# 8408030151#	50-275	RIVENBARK, Q W. RIVENBARK, G W RIVENBARK, G W RIVENBARK, Q W RIVENBARK, Q W	8408080031 8408080070 8408080152 8408080158* 8408080441	50-944 F 50-902 P 50-913 P 50-913 P 50-913 F
RATCLIFF, W H RATHBUN, L A RAU, C A RAVAL, J RAY, C L	8408070551* 8408270171 8408150505* 8408070330* 8403270062	CONTRACT NUREQ 50-922 T 50-922 B 50-206 B	REYNDLDS, N S REYNDLDS, N S REYNDLDS, N S REYNDLDS, N S REYNOLDS, N S	8408030091 8408030091 8408080162 8408080162 8408130093	50-416 0 50-416 0 50-445 0 50-445 0 50-445 0	RIVENBARK, G W RIVENBARK, G W RIVENBARK, G W RIVENBARK, G W ROBER, R W	8408070010 8408130530 8408130537* 84081301414 8408150108	50-313 P 50-346 P 50-346 P 50-269 P 50-244 P
RAY, C. L RAY, C. L RAY, C. L RAY, C. L RAY, C. L	8405270062 8405270179 8405270179 840806050 840806050	50-206 8 50-206 8 50-206 8 50-206 8 50-206 8	REYNOLDS, N S	8408130093 8408230187 8408230187 8408230257 8408230257	50-445 G 50-445 G 50-445 G 50-445 G	ROBERSON, P. L ROBERTS, H. R ROBERTS, J. P ROBERTS, J. P ROBERTS, J. P	8408270171 8408280110 8408070036 8408130570 8408160461	NUREO 1 40-8675 PROJ 70-1308 70-1308
RAY, C. L RAY, C. L RAY, C. L C. L	8408040102 8408040102 8408040324 8408040324 8408140394	50-206 S 50-206 S 50-206 S 50-206 S 50-206 S	REYNOLDS, N. S REYNOLDS, N. S REYNOLDS, S REYTBLATT, Z. REYTBLATT, Z	8408280265 840828055 8408210381* 8408280378* 8408280380*	50-445 Q 50-445 Q 50-352 Q 50-295 P 50-295 P	ROBERTS. J P ROBERTS. T M ROBERTS. W A ROBERTS. W A ROBERTS. W A	8408240009 8408080384 8408030187 8408150531 8408140518	50-280 Y COMMISSION WASTE MOT WASTE MOT WASTE MOT SO-259 B

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ROBERTS, W A ROBERTS, W B ROBERTSON, J ROBERTSON, J ROBINSON, P	8408200300	50-259 S	ROTH, J	8408270518*	50-34 Q	SAUNDERS.R F	8408010076*	50-280 S
	8408210518*	50-352 A	ROTHMAN, R	8408140248*	50-329 A	SAVAGE.E N	8408150131	XPORTLIC
	8408080480*	CONTRACT	ROTMAN, M	8408060197*	50-70 Q	SAYLOR.N S	8408310137	FOIA
	8408290007*	50-423 G	ROHE, C	8408270297*	40-672	SCALETTI.D C	8408010324	50-447 A
	8408290120	I&E	ROHE, J	8408240390	UASTE MANA	SCALETTI.D C	8408070203	50-447 A
ROBKIN, M A	8408170340	50-139 F	ROY. G W	8408150517*	50-327 A	SGALETTI.D C	8408070429	50-447 A
ROCHLIS, S M	8408200477*	50-400 G	ROY. G W	8408150594*	50-329 S	SCALICE, J A	8408130355*	50-322 G
RODABAUGH, E C	8408130041	NUREG	ROZAK, S	8408150401*	50-254 G	SCARAND, R A	8408130502	70-1257
RODABAUGH, E C	8408270582*	CONTRACT	ROZAK, S	8408310294*	50-305 G	SCARAND, R A	8408230078	50-312 G
RODRIGUEZ, J H	8408270136	50-354 D	ROĐENSTEIN, L S	8402020372*	50-354 E	SCARAND, R A	8408230223	50-361 Q
RODRIGUEZ,R J	8408060006	50-312 V	RUDENSTEIN.L S	8408070222	TOPREP	SCARBROUGH, J N	8408080089	50-445 T
RODRIGUEZ,R J	8408060011	50-312 G	RUBIN.J	8408130344	PR	SCARBROUGH, J N	8408220403*	50-445 T
RODRIGUEZ,R J	8408060177	50-312 P	RUFF.A B	8408270191*	50-413 G	SCARBROUGH, J N	8408220403*	50-445 T
RODRIGUEZ,R J	8408130207	50-312 F	RUFF.A B	8408270440*	50-424 G	SCHAEFER, D	8408210167*	50-142 G
RODRIGUEZ,R J	8408140259	50-312 P	RUGER.C	8408220333	50-352 A	SCHAUER, F P	8207140330*	50-327 A
RODRIGUEZ,R J RODRIGUEZ,R J RODRIGUEZ,R J RODRIGUEZ,R J RODRIGUEZ,R J	8408170362 8408200337 8408240111 8408240112 8408270061	50-312 P 50-312 S 50-312 P 50-312 P	RUGGLES, L E RUITER, G H RUMBAUGH, E RUNCKLE, J RUNKLE, J	8408080367 8408160211 8408140079* 8408210323 8408010264	NUREG 50-305 R 50-329 A 50-400 G 50-400 G	SCHAUER, F P SCHAUER, F P SCHEIDT, D J SCHEIDT, D J SCHERER, A E	8408020180* 8408020182* 8408170315 8408170315 8408020031	50-329 0 50-329 0 50-322 0 50-322 0 50-317 P
RODRIGUEZ,R J	8408270401	50-312 P	RUNKLE, J	8408070455	50-400 G	SCHERER, A E	8408140230	50-470 E
RODRIGUEZ,R J	8408270288	50-312 S	RUPP, J L	8408090076	50-311 8	SCHERER, A E	8408140390	50-470 A
RODRIGUEZ,R J	8408310113	50-312 P	RUPP, J L	8408130588	50-311 6	SCHERRER, J S	8105130143*	50-293 P
RODRIGUEZ,R J	8408310176	50-312 S	RUPP, J L	8408160276	50-272 8	SCHINK, A B	8408100144*	50-289 G
RODRIGUEZ,R J	8408310217	50-312 P	RUPP, J L	8408230501	50-272 8	ECHMIDT, H C	8408050165	50-445 A
RODRIGUEZ.R J	8408310234	50-312 P	RUPP.J L	8408300349	50-311 S	SCHMIDT, H C	8408140330	50-445 Q
RODRIGUEZ.R J	8408310245	50-312 P	RUPP.J L	8408300400	50-311 S	SCHMIDT, H C	8408140335	50-445 A
ROGAN.R E	8408010327#	50-320 P	RUSCHE.B C	8408090303*	WASTE MGT	SCHMIDT, H C	8408140412	50-445 A
ROGERS,D W	8408060263	50-255 8	RUSLINO.D H	8408200121	50-274 F	SCHMIDT, H C	8408230370	50-445 F
ROGERS,D W	8408070378	50-255 8	RUSSELL.C F	8408040225	WASTE MGT	SCHMIDT, H C	8408270030	50-445 A
RDGERS.D W	8408160279	50-255 8	RUSSELL.C F	8408060338	WASTE MGT	SCHMIDT, H C	8408270067	50-445 A
ROGERS.D W	8408270127	50-255 8	RUSSELL.J E	8408080326	40-6622	SCHMIDT, H C	8408270123	50-445 A
ROGERS.D W	8408270130	50-255 8	RUSSELL.J E	8408240334	40-6622	SCHMIDT, H C	8408270124	50-445 A
ROGERS.D W	8408310056	50-255 8	RUSSELL.L B	8408150188	50-317 8	SCHMIDT, H C	8408270132	50-445 A
ROGERS.D W	8408310059	50-255 8	RUSSELL.L B	8408150395	50-318 8	SCHMIDT, H C	8408270271	50-445 X
Adgers, J T	8408020126*	50-440 I	RUSSELL.L B	8408200492	50-318 8	SCHMIDT, H C	8408280142	50-445 A
Adgers, P	8408080473	50-368 S	RUSSELL.L B	8408200512	50-318 8	SCHMIDT, H C	8408280170	50-445 A
Rogers, P	8408130170	50-313 S	RUSSELL.L B	8408290258	50-317 \$	SCHMIDT, H C	8408280218	50-445 A
Rogers, P	8408130324	50-313 S	RUSSELL.L B	8408310042	50-318 \$	SCHMIDT, H C	8408300237	50-445 A
Rogers, P	8408240053	50-313 S	RUSSELL.U T	8408160018	TOPREP	SCHMOTZER, J K	8408210373*	50-336 P
ROGERS, P ROGERS, P C ROGERS, P C ROGGE, J ROGGZINSKI, R M	8408300494 8408040187 8408080528 8408270269* 8408230482	50-368 5 50-368 9 50-368 8 50-321 0 50-213 9	RUSSELL, W T RUTLEDOS, C RUTLEDOS, C RUTLEDOS, C RUTLEDOS, C	8408140319 8408240381 8408240397 8408240409 8408240427	50-250 P 40-8502 40-8502 40-8502 40-8502	SCHNEIDER, S L SCHNEIDER, S L SCHNEILL, D F SCHNELL, D F	8408200332 8408200333 8408200338 8406140221 8408030078	50-441 8 50-528 8 50-441 8 50-483 A 50-483 P
ROHDE, J E	8408070047	50-304 8	RUTLEDGE, C	8408270032	40-6502	BCHNELL, DF	8408040284	50-483 P
ROMBBACHER, R A	8408170117*	50-443 0	RUTLEDGE, C	8408270177	40-6502	SCHNELL, DF	8408100034*	50-483 G
ROISMAN, A Z	8408070200	50-445 0	RUTLEDGE, C	8408270562	40-6502	BCHNELL, DF	8408130397	50-483 F
ROISMAN, A Z	8408070200	50-445 0	RUTLEDGE, C	8408270564	40-6502	BCHNELL, DF	8408140129	50-483 F
ROISMAN, A Z	8408070204*	50-445 0	RUTLEDGE, C	8408270571	40-6502	BCHNELL, DF	8408140385	50-483 P
ROISMAN, A Z	8408070206#	50-445 G	RUZ,R R	8408310154	PR	SCHNELL, D F	8408140404*	50-483 P
ROISMAN, A Z	8408140495	50-445 G	RYAN,J A	8407120136	50-528 D	SCHRADER, D	8408220278	50-454 P
ROISMAN, A Z	8408230173	50-445 G	RYBAK,B	8408060365	50-254 Q	SCHRADER, B	8408270303	50-454 P
ROISMAN, A Z	8408230173	50-445 G	RYBAK,B	8408060071	50-249 P	SCHROEDER, B A	8408130271	50-237 R
ROISMAN, A Z	8408230173	50-445 T	RYBAK,B	8408060108	50-254 G	SCHULTZ, W H	8408170145*	50-329 A
ROISMAN, A Z	8408240247	50-445 T	Rybak, B	8408060144	50-374 P	SCHULZ,R	8408060309*	50-456 Q
ROISMAN, A, Z	8408280197	50-445 G	Rybak, B	8408060168	50-374 P	SCHULZ,R	8408150515*	50-382 Q
ROISMAN, A Z	8408270319	50-445 G	Rybak, B	8408060276	50-237 P	SCHUMACHER,M C	8408150401*	50-254 Q
ROISMAN, A Z	8408270319	50-445 G	Rybak, B	8408140317	50-254 P	SCHUMACHER,M C	8408270288*	50-440 Q
ROLES, G W	8408140440	Waste Mgt	Rybak, B	8408140405	50-374 P	SCHUMACHER,M C	8408310296*	50-305 Q
ROLES, G W ROLFE, R M ROLFE, R M ROLFE, R M ROLFE, R M	8409210130 8408030070 8408030070 8408070377 8408070377	MASTE MOT 50-322 0 50-322 0 50-322 0 50-322 0	RYBAK.B RYBAK.B RYBAK.B SAEGERT.B C	8408150113 8408270358 8408310203 8408310211 8408020021	50-237 P 50-373 F 50-254 P 50-237 P 50-322 T	SCHUMM, B A SCHUMWAY, R, W SCHUSTER, M D SCHUSTER, M, D SCHUSTER, M D	8408060431 8405210578 8408070135 8408080117 8408080273	WASTE MOT NUREO 50-397 8 50-397 F 70-1257
ROLFE.R M ROLFE.R.M ROMAN.T W ROMANO.F R. ROMANO.F R	8408160100 8408160100 8408020119* 8408010233 8408140450	50-322	SAEGERT, SC SALAH, S SALAH, S SALTER, PF SALTZMAN, J	8408020021 8408310361 8408310362* 8408280007* 8408060218	50-322 T 50-373 B 50-373 B WASTE MOT 50-413 J	SCHUSTER, M D	8408210161 8408210167* 8408220340 8408230114 8408230216	50-142 Q 50-142 Q 70-1257 50-206 F 70-734
ROMANO, F R ROMANO, F R ROMANO, F R ROMANO, F R ROMANO, F R	8408140452* 8408200433 8408200442* 8408200447* 8408220354	50-352	BAMMONB.R. J SAMMONB.R J SANDERB.C F SANDERB.W F SANDERB.W F	8408150182 8408150607 8408280148 8408240371* 8408270351*	71-6717 71-6717 70-1151 50-424 Q 50-424 Q	SCHUSTER, M D SCHUSTER, M D SCHUSTER, M D SCHUSTER, M D. SCHUSTER, M D.	8408270337 8408270346* 8408300007 8408300125 8408300127*	70-734 70-734 70-1257 50-528 G 50-528 G
ROMANO.F R RODD.H RODNEY.V L RODNEY.V L RODNEY.V L	8408240240 8408030009* 8408040425 8408150261 8408270314	50-352	Sanderbon, 5 a Bargent, 1 H Sasser, K Sabtre, C Sauer, D W	8408160234 8408280321* 8408240421* 8408270070 8408060073	50-275	SCHUSTER, M D	8408300483 8408300498* 8408300504* 8408310285 8408310315	50-312 0 50-312 0 50-312 0 50-206 0 50-344 F
RODT, R W.	8408200317	50-460 B	BAUER, RE SAUM, MA SAUNDERS, RF SAUNDERS, RF SAUNDERS, RF	8408010034	27-48	SCHUSTER, H H	8408150505*	50-322 T
ROBA, E A	8408010166	NUREG		8408160327	50-315 8	SCHUYLER, J O	8406150149	50-275 P
ROSS, D F	8408280390#	50-275 P		8408010036	50-280 8	SCHUYLER, J O	8408010036	71-202
ROSS, W J	8408270388#	50-338 G		8408010060*	50-280 8	SCHUYLER, J O	8408020056	50-133 P
ROTH, J	8406260179#	70-1143		8408010069*	50-280 8	SCHUYLER, J O	8408020063*	50-133 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CHUAFEK' O CHOAFEK' O CHOAFEK' O CHOAFEK' O CHOAFEK' O CHOAFEK' O CHOAFEK' O	8408060120 8408040126 8408070278 8408070327* 8408080453	50-323 A 50-323 A 50-323 A 50-275 G 50-275 F	SCOTT.R SCOTT.T G SCULLE.K A SCULLE.K A SEAMAN.C	8408100061 8408300272 8408140335 8408140374 8408150476*	50-344 F NUREG 50-456 A 50-456 A 50-322 T	SHERWOOD, G G SHEWMAKER, R C SHEWMON, P SHEWMON, P G SHIBATA, Y	8408270155 8408130256* 8204040008* 8408010183* 8408170404	50-447 P 50-382 Q 50-329 D 50-329 D XPORTLIC
CHUYLER.J D CHUYLER.J D CHUYLER.J D CHUYLER.J D	8408080458* 8408130003 8408130188 8408130291 8408140011	50-275 F 50-275 P 50-275 P 50-275 Q 50-275 P	Seaman, C k Seaman, C k Seaman, C k Sears, C f Sears, C f	84081 50505 # 84081 5051 4 # 84081 5053 0 * 84080 70082 84080 70082	50-322 T 50-322 T 50-322 T 50-423 A 50-423 A	SHIBATA, Y SHIELDS, J SHIELDS, J M SHIFFCR, J D	8408170408* 8408070490 8408060063 8408200926 8408070369	XPERTLIC 50-374 S 50-379 S 50-373 S 50-275 S
CHUYLER, J O CHUYLER, J O CHUYLER, J O	8408140341 8408160267 8408200318* 8408210406 8408230008	50-323 P 50-275 F 50-275 Q 50-275 P 50-275 P	SEARS, C F SEARS, C F SEARS, C F SEARS, C F SEARS, C F	8408100064 8408100064 8408100116 8408100116 8408100116	50-423 8 50-423 8 50-213 0 50-213 0 50-213 0	SHIFFER. J D SHIFFER. J D SHIFFER. J D SHIFFER. J D SHIFFER. J D	8408140491 8408210224 8408230476 8408270112 8408310038	50-275 S 50-275 S 50-275 S 50-275 S 50-275 S
CHUYLER, J D CHUYLER, J D CHUYLER, J D CHUYLER, J D	8408230012* 8408230333 8408270376 8408300482 8408310230	50-275 P 50-275 F 50-323 A 50-275 P 50-275 F	SEARS, C F SEARB, C F SEARB, C F SEELINGER, J L SEGE, Q	8408210480 8408210480 8408210480 8408200580 8408220245	50-213 Q 50-213 Q 50-213 Q 50-289 Q MUREG	SHIFFER, J D SHIRAKAWA, T SHIRAKAWA, T SHIRAKAWA, T SHIV, K	8408310143 8405140213 8408150128 8408150179 8408220333	SO-275 S XPORTLIC XPORTLIC XPORTLIC SO-352 A
CHWAN.C A CHWARTZ.M W CHWARTZ.S A CHWENCER.A CHWENCER.A	8408070135 8408010155 8408070352 8408010107 8408010227	50-397 B NUREG 50-322 T 50-373 P 50-354 A	Setba'd C Setken's a Setken's a Setken's a	B408010386 8408030255 8408310101 8408200173* 8408230184*	50-482 S 50-482 S 50-482 A 50-336 P 50-317 P	SHOEMAKER.C J SHOEMAKER.C J SHOEMAKER.C J SHOEMAKER.C J SHOEMAKER.C J	8408020219 8408030099 8408060221 8408070358 8408090183	50-275 0 50-322 0 50-482 0 50-322 0 50-275 0
CHWENCER. A CHWENCER. A CHWENCER. A CHWENCER. A CHWENCER. A	8408060273* 8408070147 8408080054 8408080148 8408080155*	50~352 A 50~354 F 50~410 C 50-373 P 50-373 P	SENECHAL, M E SERBANESCU, M A SERBANESCU, M A SERINI, B L SEYFRIT, K V	8408080334* 8408140031* 8408140031* 8408060371* 8408220067	PR 50-400 T 50-400 T 70-2968 50-275 G	SHDEMAKER, C J SHDEMAKER, C J SHDLLY, S C SHDLLY, S C SHDN, F J	8408130158 8408150418 8408140448 8408230325 8408280371	50-352
CHWENGER: A CHWENGER: A CHWENGER: A CHWENGER: A CHWENGER: A	8408080314 8408080319# 8408070213# 8408070407 8408070410#	50-374 P 50-374 P 50-322 G 50-397 P 50-397 P	SHACK,W J SHACK,W J SHAEFFER,M J SHAFER,W SHAFER,W	8408100151 8408310083 8408170187* 8408200308 8408210269	NUREG NUREG 50-329 A 50-255 8 50-315 8	ЗКОРЕИИ: И М ЗКОРЕИИ: И М ЗКОРЕИИ: И М ЗКОРЕИИ: И М	8408210143* 8408240189 8408240190 8408240195 8408240207	40-4492 40-299 40-3453 40-8698 40-8698
CHWENCER. A CHWENCER. A CHWENCER. A CHWENCER. A CHWENCER. A	8408070452 8408130201 8408160163 8408160166* 8408160170	50-354 E 50-354 A 50-410 D 50-410 D 50-354 E	SHAFER.W SHAFER.W D SHAFER.W D SHAFER.W D SHAFER.W D	8408240114 8408010289 8408010291* 8408010401 8408030176	50-374 8 50-373 Q 50-373 Q 50-263 Q 50-155 Q	SHOPENN'N W SHOPENN'N W SHOPENN'N W	8408270044 8408270062 8408270100 8408240142 8408140449	40-3453 40-3453 40-8678 40-3453 50-219 G
CHWENCER. A CHWENCER. A CHWENCER. A CHWENCER. A CHWENCER. A	8408160431 8408170104 8408170107 8408170110 8408170227	50-410 D 50-410 D 50-410 D 50-410 D 50-373 P	SHAFER, W D SHAFER, W D SHAFER, W D SHAFER, W D SHAFER, W D	8408070189 8408090169 8408130387 8408130391 8408130407	50-282 q 50-295 q 50-346 q 50-346 q 50-346 q	SIEBER.J D SIEDOR,G R SIEDOR,G R SIEGEL,B L SIEGEL,M	8408150124 8408170314 8408170323 8408130152 8408280009#	50-334 P 50-461 G 50-461 G 50-461 A WASTE MGT
CHWENCER, A CHWENCER, A CHWENCER, A CHWENCER, A CHWENCER, A	8408170243* 8408200384 8408200540 8408200546* 8408200552	50-373 P 50-354 D 50-458 D 50-458 D 50-458 D	SHAFER, W D SHAFER, W D SHAFER, W D SHAFER, W D SHAFER, W D	8408160139 8408160198 8408160206* 8408170090* 8408230204	50-10 @ 50-373 @ 50-373 @ 50-329 B 50-315 @	BIEGEL, M D BILBERG, J E BILBERG, J E BILBERG, J E	8408240214 8408010214 8408010214 8408010229 8408010229	WASTE MANA 50-440 G 50-440 G 50-440 G
CHWENCER, A CHWENCER, A CHWENCER, A CHWENCER, A CHWENCER, A	8408220164 8408220432 8408220434 8408220435 8408240174	50-488 D 50-354 D 50-458 D 50-374 P 50-458 F	SHAFER, W D EHAFER, W D SHAFER, W D SHAFER, W D SHAFER, W D	8408230227 8408230234* 8408230489 8408240082 8408240083*	50-407 0 50-407 0 50-263 0 50-255 0 50-255 0	SILBERG, J E SILVER, H BILVER, H SILVER, H SILVER, H	8408140420 8408090097 8408200418 8408210054 8408210567	PR 50-289 F 50-302 P 50-302 P 50-302 P
CHWENCER, A CHWENCER, A CHWENCER, A CHWENCER, A )HWENCER, A	8408240303 8408270479 8408270478 8408270501* 8408280339	50-461 A 50-373 P 50-397 P 50-397 P 50-397 P	SHAFER, W D SHAFER, W D SHAFER, W D SHANBAKY, M, SHANBAKY, M	8408270353 8408300073 8408300079* 8408010286* 8408030267*	50-266 0 50-10 0 50-10 0 50-247 0 50-272 0	SILVER, H SILVER, N S BILVIS, R M SILVIS, R M SILVIS, R M	8408220203 8408300304 8408130435 8408130440 8408130444	50-302 P 50-354 D CONTRACT CONTRACT CONTRACT
CHWENCER, A CHWENCER, A CHWENCER, A CHWENCER, A CHWENCER, A	8408310426 8408310426 8408310439 8408310450 8408070207*	50-410 F 50-387 P 50-373 P 50-373 P 50-416 U	SHANBAKY, M SHANBAKY, M SHANBAKY, M SHANBAKY, M SHANBAKY, M SHANBAKY, M	8408200023# 8408010272# 8408210244# 8408230136# 8408230569#	50-289 G 50-245 G 50-247 G 50-277 G 50-293 G	SILVIS, R M SIMAN-TOV, I SIMAN-TOV, M SIMONEN, F A SIMPSON, R W	8408220384 8408130001 8408130007 8408220370 8408220381*	CONTRACT NUREG NUREG NUREG 50-445 T
D 0.7700 U 0.7700 U 0.7700 U 0.7700 U 0.7700	8408140144 8408050100 8408060293 8408090052 8408090151	50-261 R 50-237 S 50-237 S 50-237 S 50-237 S	SHANBAKY,M M SHAPIRO,R E SHAPIRO,R E SHAPIRO,R E SHAPIRO,R E	8408240076* 8408270136 8408280447 8408280449 8408290014	50-334 G 50-354 D 50-354 G 50-354 G 50-354 G	SIMPSON,R W SIMB,W T SINCLAIR,J B SINCLAIR,J B SINCLAIR,J B	8408220381* 8408070273 8408020082 8408040226 8408160052	50-445 T 50-445 T 60-271 G 50-271 G 50-271 P
OTT, B J OTT, D J OTT, D J OTT, D J	8408130144 8408130271 8408130330 8408200501 8408200519	50-249 8 50-237 R 50-237 S 50-10 S 50-249 S	SHAUB, E SHAUB, E SHAH, R W SHEA, J SHEA, K H	8408090166# 8408070330* 8408240239* 8408200190 8408030087	50-387	SINCLAIR, M SINGER, G L SINGH, B K SINGH, B K SINGH, H	8408170297* 8405210579 8407300089 8408090497 8408140286*	50-329 T NUREG 50-443 F 50-244 P 50-329 A
D G.TTG: U G.TTG: U G.TTG: U G.TTG: U G.TTG: U	8408210104 8408230283 8408240218 8408270455 8408300368	50-249 8 50-10 F 50-237 8 50-249 8 50-10 R	SHEA,K H SHEDLDSKY,J SHEDLOSKY,J T SHELL,R H SHELL,R H	8408030129 6408290483* 6408080403* 8408270098 6408270154	50-331 J 50-382 Q 50-245 Q 50-438 A 50-327 P	BINGH, H BINGH, H BINGH, H BINGH, H	8408140357* 8408130046* 8408210418* 8408210430* 8408140144*	50-329 A 50-329 A 50-329 A 50-329 A 50-329 A
OTT.D J. OTT.D J. OTT.L OTT.L OTT.N	8408310063 8408310067 8408310071 8408060203 8408270350	50-237 S 50-237 S 50-247 S 50-237 S PR	SHEPPARD, J J SHERWIN, J A SHERWIN, J A SHERWOOD, G SHERWOOD, G	8408210484 8408210484 8408200517 8408230209 8408240348	TOPREP TOPREP WASTE MOT 50-447 A 50-195 S	SINGH, H N BINGH, H N BINKE, G J BISK, D P	8408140300* 8408140319* 8408140370* 8408300322 8408140491	50-329 A 50-329 A 50-458 A 70-925 50-275 8

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR,	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
5(5k, D P 815k, D P 515k, D P 519k, D P 819kIND, B	8408210226 8408230476 8408270112 8408310143 8408010151	50-275 5, 50-275 S 50-275 S 50-275 S MJREG	JM (THE, D R SMYTHE, D R SNELL, W G SNELL, W G SNIEZEK, J	8408200323 8408310047 8408010279* 8408240429* 8408010159	50-373 5 50-373 5 50-409 0 50-305 0 REVIEW GRP	ST LAURENT, N N STAMIRIS, B STAMIRIS, B G STANG, J STANLEY, R W	8408300441 8408020107* 8408170292* 8408040325* 8408080142	50-29 8 50-327 0 50-329 T 50-382 Q 50-388 S
SJOBLOM, G I SMEDIRA, C SMEENGE, R J SMIDTH, P T SMITH, D F	8408160264* 8408150598 8408150511* 8408150682* 8408240169	ORG 71-9073 50-461 G 50-329 A 40~8102	SNYDER, B J SNYDER, B J SNYDER, B J SNYDER, B J	8408010049 8408030211 8408060253 8408070083 8408160042	50-320 P 50-320 P 50-320 P 50-320 P 50-320 P	STANLEY, R W	8408070421 8408140164 8408240246 8408300377 8408300484	50-387 S 50-388 S 50-387 S 50-388 S 50-388 S
SMITH, D. L. SMITH, D. L. SMITH, D. L. SMITH, D. L.	8408060113 8408080518 8408160519 8408200412 8408270150	50-259 8 50-259 8 50-259 8 50-276 8 50-276 8	SNYDER, B J SOMERVILLE, K G SOMMERS, D A SOMSAG, K L SORDILL, P	8408280341 8408240341 8408010147* 8408310174* 8408140447	50-320 P 40-8783 50-329 G 50-454 T 50-219 G	STANSBERRY, W W STARKEY, R B STARKEY, R B STARKEY, R B STARKEY, R B	8409280370* 8406070060 8409010295 8409060088 8409300312	50-247 0 50-325 S 50-325 S 50-325 S 50-325 S
SMITH, D L SMITH, G C SMITH, G C SMITH, G L SMITH, G L	8408280349 8408150407* 8408150424* 8408070052 8408070151	50-259 S 70-371 50-277 G 50-237 S 50-237 S	SORENSEN, O C SORENSEN, O C SORENSEN, O C SORENSEN, O C SORENSEN, O C	8408070247 8408070325 8408070333 8408080175 8408090262	50-397 @ 50-397 P 50-397 P 50-460 A 50-397 P	STARMER.R J STARMER.R J STARMER.R J STAROSTECKI.R STAROSTECKI.R	8408060186 8408200426 8408210115 8406260175 8408010296	HABTE MGT HABTE MGT HABTE MGT 70-1143 50-247 G
SMITH, I W SMITH, M E SMITH, M J SMITH, N GMITH, P A	8405250251 8408010231* 8408150374* 8408080219 8408010048*	50-344 G 50-354 E 50-454 G XPORTLIC CONTRACT	SDRENSEN, G C SDRENSEN, G C SDRENSEN, G C SDRENSEN, G C SDRENSEN, R C	8408160404 8408170031 8408270073 8408270153 8408300407*	50-508 A 50-460 A 50-397 P 50-397 P 50-528 G	STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	8408030027 8408030146 8408030222 8408070232 8408080212	50-272
SMITH,PA SMITH,PA SMITH,PA SMITH,PA	8408010182* 8408070053* 8408070104* 8408080064* 8408080321*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	SORRELL, E C SORRELL, E C SORRELL, E C SORRELL, E C SPANG, J R	8408030163 6408210472 8408270301 8408280233 8408270265	50-321 F 50-321 F 50-321 F 50-321 F 50-289 T	STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	8408080353 6408080464 8408070040 8408070133 8408100123	50-245 @ 50-245 @ 50-387 @ 50-213 @ 50-289 @
SMITH,PA SMITH,PA SMITH,PA SMITH,PA	8408080507* 8408070142* 8408070551* 8408130314* 8408130437*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	SPANO, J R SPANOLER, R G SPECK, S H SPECK, S W SPE18, T P	8408290269* 8408020072 8408100060 8408300211* 8407020544*	50-289 T NUREG 50-295 F 50-302 F REVIEW GRP	STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	84081 30350 84081 50233 84081 50251 84081 50256 84081 50264	50-29 G 50-277 G 50-213 G 50-443 G 50-289 G
SMITH,P A SMITH,P A SMITH,P A SMITH,P A SMITH,P A	8408130442# 8408130445* 8408130597* 8408220156* 8408220387*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	SPE18, T P SPENCE, F D SPENCE, M D SPENCE, M D SPENCER, S	8408220070* 8408280056* 8408140393 8408270375 8408080249	50~327 A 50~322 H 50~445 K 50~445 A 50~445 T	STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	8408150366 8408160073 8408160270 8408200032 8408200235#	50-272 Q 50-29 Q 50-311 Q 50-387 Q 50-388 U
SMITH, PA SMITH, PA SMITH, PA SMITH, PA	8408230334* 8408230594* 8408270552* 8408270558* 8408270582*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L	8408070204 8408070354 8408080171 8408080174* 8408080188	50-454	STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	8408200354 8408210368 8408230082 8408240233 8408240351	50-354 Q 50-352 Q 50-293 Q 50-410 Q 50-317 Q
SMITH, PA SMITH, PA SMITH, RD SMITH, RD SMITH, RD	8408310252* 8408310358* 8408070226 8408240158 8408240166*	CONTRACT CONTRACT 40-8786 40-8084 40-299	SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L	8408070212 8408100005 8408100044 8408130372 8408140078	50-454 Q 50-440 A 50-246 Q 50-305 P 50-409 P	STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R	8408270406 8408270477 8408270510 8408270538 8408270577	50-307 0 50-184 0 50-34 0 50-333 0 50-29 0
SMITH, R D SMITH, R D SMITH, R D SMITH, R D	8408240175 8408240178* 8408240181 8408240186 8408240198*	40-8768 40-8768 40-2259 40-1162 40-8698	SPESSARD.R L SPESSARD.R L SPESSARD.R L SPESSARD.R L SPESSARD.R L	8408140229 8408140402 8408150471 8408150492 8408160184	50-454	STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R	8408280101* 8408280291 8408290003 8408290478 8408300097	50-352 A 50-219 Q 50-423 Q 50-322 Q 50-219 Q
SMITH, R D SMITH, R D SMITH, R D SMITH, R D SMITH, R D	8408240201* 8408240213 8408240331 8408270026 8408270331	40-299 40-299 40-8586 40-8786 40-8452	SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L	8408160190* 8408160212 8408160216* 8408160334 8408160338*	50-483 Q 50-454 Q 50-454 Q 50-341 Q 50-341 Q	STAROSTECKI.R STAROSTECKI.R STABEK.S STATTON.C D STAUTER.J C	8408300374 8408310044 8408300108* 8408280062 8408020153	50-320 G 50-470 G 50-10 G GA999 40-8027
SMITH,R D SMITH,R D SMITH,R D SMITH,R D SMITH,R D	8408270354 8408270482 8408270487 8408280004 8408280014	40-277 40-3453 40-277 40-277 40-8502	SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L	8408170322 8408170039 8408170099 8408200221 8408230141	50-155 P 50-454 Q 50-331 P 50-454 Q 50-341 Q	STAUTER, J C STAUTER, J C STEFANO, J J STEINSRENNER, F STEISS, A W	84081 \$0571 84081 \$0575* 8408270396 84081 \$0597* 84082 20156*	40-8027 40-8027 50-440 E CONTRACT CONTRACT
SMITH, R D SMITH, R H SMITH, R M SMITH, R W	8408280023 8408060208* 8408160272* 8408310035* 8408270465*	40-3453 50-213	SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L	8408230142* 8408230245 8408270245 8408300118 8408300143	50-341 G 50-454 G 50-454 G 50-456 G MISC	STELLO, V. STELLO, V STELLO, V STELLO, V	8404200226* 8404280010* 8408010042 8408070081 8408230376	PR PR REVIEW GRP REVIEW GRP REVIEW GRP
SMITH, 8 P SMITH, W F SMITH, W F SMITH, W F SMITH, W F	8408030272 8408130102* 8408130440* 8408140037* 8408140500*	50-307 8 50-445 0 50-445 0 50-445 0 50-445 0	SPESSARDIR L SPESSARDIR L SPIECELIG SPIELESIP SPIELESIP R	8408310381 8408130120 8408270312 8408240031 8408240102	50-341	STELLO, V STELLO, V STELLO, V STELLO, V STERGAKOS, E P	8408270102 8408270102 8408270343 8408270446 8408130359*	REVIEW GRP REVIEW GRP REVIEW GRP REVIEW GRP 50-322 G
SWITH, W G SMITH, W G SMITH, W G SMITH, W G	8408060151 8408080536 8408130307 8408160127 8408160327	50-316 S 50-315 S 50-316 S 50-316 S 50-315 S	SPINRAD, B I SPITIBERG, D B SPITIBERG, D B SPIVEY, H, L SPRUNGER, C K	8408080335 8408090127 8408210120* 8408230360* 8408070371	PR 40-8822 40-2259 50-302 H 50-374 E	STERN,T STEVENS.JA STEWART.DL STEWART.WL STEWART.WL	8408040210 8408310075 8408020028 8408020041	NUREQ 30-456 F NUREQ 50-338 F 50-280 G
SMITH, W C SMITH, W C, SMYKOWSKI, S SMYTH, C W	8408220486 8408300505 8408150252 8408280340 8408240066	50-315 B 50-315 B WASTE MGT WASTE MGT 50-289 R	ST LAURENT, N ST LAURENT, N N ST LAURENT, N N ST LAURENT, N N ST LAURENT, N N	8408160529 8408090104 8408210350 8408230540 8408240153	50-29 6 50-27 5 50-29 6 50-27 8 50-29 F	STEWART, W L STEWART, W L STEWART, W L STEWART, W L STEWART, W L	8408020132 8408070039 8408070400 9408070489 8408090149	50-280 F 50-280 F 50-338 F 50-280 V 50-338 P

AUTHOR	ACCESSION NUMBER	SUBJE( CATEGO		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
STEWART, W L STEWART, W L STEWART, W L STEWART, W L STEWART, W L	8408070235 8408100078 8408130400* 8408130403* 8408130438*	50-338 50-338	P F G G	STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F	8408280488 8408300197 8408300217* 8408310305 8408310308*	50-346 P 50-366 P 50-366 P 50-287 P 50-287 P	TANIOUS, N TAPLEY, J TARLETZ, D B TARLETZ, D B TAUBLING, T N	8408220324 8408100061 8408150473 8408150473 8408010308*	WASTE MOT 50-346 F 50-322 T 50-322 T 50-151 G
STEWART, W L STEWART, W L STEWART, W L STEWART, W L	8408130585 8408140037 8408140406 8408170222 8408170300	50-280 50-280 50-280 50-280 50-338	P F F F	STOLZ.J F STOUT.R B STOUT.R B STREETER.J F STREETER.J F	8408310404 8408070207* 8408230264* 8408060344* 8408070213	50-302 P 50-316 P 50-315 P 50-454 S 50-454 G	TAYLOR.F Z TAYLOR.H S TAYLOR.J A TAYLOR.J H TAYLOR.J H	8408200282* 8408030143 8408290193 8408070389 8408080016	50-289 H GA999 50-338 S 50-269 P TOPREP
STEWART, W L STEWART, W L STEWART, W L STEWART, W L	8408210132 8408210375 8408220171 8408240280 8408270448*	50-280 50-338 50-280 50-280 50-280	P R P Q	STREETER, J F STREETER, J F STREIER, O STRUCKMEYER, R STRUCKMEYER, R	8408070216* 8408070221* 8408310302* 8408150305* 8408150701*	50-454 Q 50-454 Q 50-255 Q 50-317 Q 50-286 Q	TAYLOR, J H TAYLOR, J H TAYLOR, J H TAYLOR, J H TAYLOR, M	8408220415* 8408230084 8408270159 8408300141 8408310080	50-445 G TUPREP TOPREP TOPREP I&E
STEWART.W L STIETZEL.J F STIJOEREN.E V STILES.J M STILES.N W	8408280150 8408080536 8408210426# 8408290313 8408140456	50-280 50-315 50-29 50-454 50-443	G S P G	STRUCKMEYER, R STRUCKMEYER, R STURBINB, J F BU, T Y SUERMANN, J	8408200544* 8408230495* 8408300184 8408130420* 8408100109	50-247 Q 50-309 Q 50-151 B 50-454 Q 50-295 B	TAYLOR, M E TAYLOR, M E TAYLOR, P A TAYLOR, P A TAYLOR, R K	8408140174 8408140254 8408240193 8408270480* 8408150505*	50-483 8 50-483 8 50-483 8 50-413 9 50-322 T
STITT.B,D STODDART.P G STODDART.P G STOHR.J P STOHR,J P	8408140248 8408270227* 8408280123* 8408030029 8408130380	50-269 50-302 70-1113 70-143 70-143	P Q	SUGARMAN, R J SUGARMAN, R J SUGARMAN, R J SUGARMAN, R J SUGARMAN, R J	8408010223 8408010223 8408010228* 8408010228* 8408010248	50-352	TAYLOR,T B TAYLOR,T B TAYLOR,T J TAYLOR,T J TAYLOR,T J	8408310219 8408310221* 8408030092 8408040047 8408040244	PR PR HASTE MOT HASTE MOT HASTE MOT
PRIOTRIJP STOHRIJP PROHRIJP STOHRIJP STOHRIJP	8408130382* 8408140179 8408140310 8408230281 8408270114	70-143 70-1113 70-143 70-143 70-27		EU RAMRADUB BURAMRADUB BURAMRADUB BURAMRADUB URAMRADUB BURAMRADUB	8408010248 8408070226 8408070226 8408070233* 8408070233*	50-352	TAYLOR, T J TAYLOR, T J TAYLOR, T J TEMPLE, G M TENZER, B. E.	8408130137 8408200514 8408220223 8408300127* 8408030021	HABTE MOT HABTE MOT 50-528 G GA999
STOUR, J P STOUR, J P STOUR, J P STOUR, J P STOUR, J P	8408270125* 8408270222 8408270254 8408270280* 8408270411	70-27 70-1151 70-27 70-27 70-143		SUQARMAN,R J SUQARMAN,R J SULLIVAN,H SULLIVAN,H SUMMER,J T	8408130358 8408130358 8408020170 8408020170 8408130410*	20-325 G 20-325 G 20-325 G 20-325 G	TERAU, D THADANI,M C THADANI,M C THATCHER, D THAYER, J K	8408210461* 8408060270 8408060425 8408220265 8408070472	50-329 A 50-331 F 50-237 P NUREQ 50-29 P
STOHR, J P STOHR, J P STOHR, J P STOHR, J P STOHR, J P	8408270415* 8408270420 8408270524 8408270534 8408280051	70-143 70-143 70-27 70-1113 70-143		SUMMERBIR J SUNDINIR SURMEIERIJ SWALNIH W	8408150370# 8408140132# 8408240040 8408150341# 8408210414	50-272 G 50-324 G 40-8727 WASTE MGT REGOD	THIES, A. C. THOMAS, C. C.	8408060072 8408010308* 8405160476* 8405300696 8407110379	50-413 A 50-151 G 50-69 P 50-284 F 50-172 F
4 C.SHOTS 4 C.SHOTS 5 C.SHOTS 6 C.SHOTS 7 C.SHOTS 7 C.SHOTS	8408280070 8408280118* 8408280187 8408280282* 8408280278	70-1201 70-1113 70-143 70-1201 70-143		SWAMY:S A SWANGER:F SWANGER:L A SWANGER:L A	8408160378* 8408080308 8408070026 8408150514* 8408150530*	50-443 A 50-346 8 50-346 8 50-322 T 50-322 T	THOMAB, C. O.	8408010045 8408010259 8408030205 8408030301 8408040144	50-156 F 50-140 P 50-5 P 50-179 V 50-134 F
9 С.ЯНОТВ ВТОНК.Ј Р ВТОНК.Ј Р О С.ЯНОТВ ВТОНК.Ј Р	8408280300* 8408280362 8408300170 8408300200* 8408300280	70-143 70-1113 70-824 70-824 70-143		SWANDER,L A SWARTZ,E D SWARTZ,E D SWARTZ,E D SWARTZ,E D	8408280205 8407100002 8408060136 8408080178 8408100117*	50-413 T 50-454 S 50-454 A 50-454 F 50-456 Q	THOMAB, C O. THOMAB, C O. THOMAB, C O. THOMAB, C O. THOMAB, C O	8408060369 8408060445 8408070011* 8408070035 8408070097	50-223 P 50-396 P 50-396 P 50-170 P 50-225 F
4 C'SHOLS STOHE'Y 6 STOHE'Y 6 STOHE'Y 6 STOHE'Y 6 STOHE'A 6 STOHE STOHE'A 6 STOHE'A 6 STOHE STOHE STOHE STOHE STOHE STOHE STOHE STOHE STOHE STOHE STOHE STOHE STOHE ST	8408300284 8408300296 8408300367 8408300391 8408300398	70-143 70-1201 70-27 70-27 70-27		GWARTZ,E D GWARTZ,E,D GWARTZ,E D GWARTZ,E D GWARTZ,E D	8408130231 8408130409 8408130415 8408140371 8408140380	50-454 8 50-454 Q 50-454 Q 50-454 E 50-454 A	THOMAB, C O THOMAB, C O, THOMAB, C O THOMAB, C O THOMAB, C O	8408070124 8408070193 8408090321 8408090347 8408090353	50-166 P TOPREP 50-601 A TOPREP TOPREP
STOHR, J P. STOHR, J P STOKELY, J R STOKELY, J R	8408310031 8408310068 8408310254 8408300272 8408170296	70-27 50-13 70-1151 NUREG 50-454	f T	SWARTZ, E D BWARTZ, E D BWARTZ, E D BWARTZ, E D SWARTZ, E D	8408140386 8408220368 8408240196 8408300044 8408300214	50-454 A 50-454 A 50-454 Q 50-456 B 50-456 B	THOMAB,C O THOMAB,C O THOMAB,C O THOMAB,C O THOMAB,C O	8408090525 8408090536# 8408140569* 8408200461 8408210097	30-252 F 50-170 P 50-166 P 50-188 F 50-97 F
STOKES, C C STOKES, C C STOLZ, J F STOLZ, J, F,	8408170380 8408200458* 8408080161 8408080178 8408080438	50-454 50-454 50-312 50-321 50-289	T P P	SWARTZMAN, O L SWARTZMAN, O L SWARTZWELDER, R SWENSON, A, SWENSON, D V	8408010158 8408040384 8408040310 8408140449 8408130004	NUREG NUREG 50-320 8 50-219 G NUREG	THOMAS, C O THOMAS, C O THOMAS, C O THOMAS, C O, THOMAS, C O,	8408210101 8408210141 8408210427 8408230447 8408240107	50-116 F 50-274 V 50-30 P 50-601 A 50-30 W
STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F	8408080477 8408080524 8408080527* 8408130302 8408130565	50-289 50-346 50-346 50-321 50-346	P P F P	SWETLAND, P SWETLAND, P SWETLAND, P SWETLAND, P, D, SWETLAND, P D	8408280107 8408310074 8408310111 8408070141* 8408150233*	50-213 6 50-213 8 50-213 8 50-213 9 50-213 9	THOMAS, C. C.	8408270462 8408270466* 8408270277 8408270286* 8408300215	50-166 P 50-166 P 50-163 P 50-163 P 50-352 E
STOLZ, J F. STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F	8408160021 8408160060 8408160285 8408210061* 8408210062	50-346 50-289 50-289 50-302 50-312	F P P	BWIGER, M. A BWIGER, M. A BWIHART, G L BICZECH, R A TAHVILI, T	8408150467 8408150467 8408240179 8408160182 8408230103*	50-440 G 50-440 G 50-374 B 50-287 B 50-261 P	THOMAS, C. O. THOMAS, M. THOMAS, M. E. THOMAS, M. E. THOMAS, M. E.	8408310345 8408270417* 8408220080* 8408220400* 8408220404*	TOPREP 50-390 G CONTRACT CONTRACT CONTRACT
STOLZ, J F, STOLZ, J F STOLZ, J F STOLZ, J F	8408210070* 8408210152 8408210576* 8408220530* 8408230463	50-312 50-312 50-302 50-277 50-344	면 면 면 면 면	TAHVILI, T. TAM, P. TAM, P. TAMBLING, T. N TAMBLING, T. N	8408230266* 8408010195* 8408210058 8408030179* 8408130244*	50-315 P 50-329 D 50-334 P 50-155 Q 50-329 A	THOMAS, R. D. THOMAS, W. R	8408080151* 8408070122* 8408130507* 8408130511* 8408080472	70-734 70-784 70-1257 70-1257 NURE9
STOLZ, J. F. STOLZ, J. F STOLZ, J. F STOLZ, J. F STOLZ, J. F	8408230554 8408270464 8408270467 8408270499 8408280319	50-346 50-269 50-289 50-269 50-346	Р Р Р Р	TAMELING, T, N TANG, F K TANI, K TANI, K, TANI, K,	8408150737* 8408160146 8408300121* 8408300176* 8408300220*	50-329 A NUREQ 50-454 G 50-440 G 50-341 G	THOMASON, P. V. THOMPSON, D. THOMPSON, J. L. THOMPSON, J. L.	9408240072 8408150694* 8408240328 8408170339* 8408170342*	50-298 8 50-329 8 50-250 F 50-354 Q 50-354 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
THOMPSON, R D THOMPSON, R D THOMPSON, R H THOMPSON, B L THOMPSON, T	8408280375* 8408280404* 8408300341 8408100147 8408270297*	50-295 P 50-295 P 50-295 P 50-302 S NUREG 40-672	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8408070298 8408070322 8408070351 8408070445 8408070468	50-369 F 50-413 F 50-413 F 50-413 S 50-369 P	VAN BRUNT, E E	8408010381 8408010384 8408010388 8408020229 8408020232	50-528 9 50-528 8 50-528 8 50-529 8 50-528 8
THONUB.L THULL.T S THULL.T S THULL.T S	8408300381* 8408230558* 8408070112 8408070340 8408070340	50-320 G 50-275 F 50-245 S 50-245 S 50-245 S	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8409070487 8409080275 8409070007 8409070274 8409070278	50-413 F 50-413 E 50-413 F 50-370 B 50-413 S	VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E	8408030048 8408030053 8408030041 8408030097 8408030144	50-528 8 50-528 8 50-529 8 50-529 F 50-528 A
THULL, T S TIEN, C TIEN, C TIEN, C TIEN, C	8408270004 8408020211 8408020211 8408240376 8408230041	50-245 8 ACRS ACRS WASTE MGT WASTE MGT	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8408130167 8408140430 8408150221 8408150326 8408140050	50-369 P 50-413 P 50-369 8 50-269 F 50-369 P	VAN BRUNT,E E	8408030240 8408030302 8408060975 8408060319 8408080348	50-528 8 50-528 8 50-528 K 50-528 A 50-528 A
TILLMAN,A TILLMAN,A TILMAN,A TIMBERLAKE,D R TIPPB,G B	8408030127* 8408230255* 8408240010* 8408140023* 8408300517	50-335 G 50-324 G 50-261 G 50-400 T 50-366 B	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8408160157 8408160174 8408160183 8408160417 8408160427	50-413 8 50-367 P 50-413 8 50-269 S 50-413 8	VAN BRUNT,E E	8408080479 8408080529 8408090012 8408100127 8408130172	50-528 S 50-528 S 50-528 S 50-528 A 50-528 S
TODD, G A	8408280192* 8408160317* 8408270427* 8408300401* 8408310255*	70-143 70-143 70-143 70-27 70-1151	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8409140469 8409140517 8409170329 8409200059 8409200100	50-413 8 50-413 8 50-269 F 50-269 P 50-369 F	VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E	8408130274 8408130303 8408130332 8408130344 8408130351	50-528 A 50-528 8 50-528 9 50-528 9 50-528 £
TODD, M. R TOMLINSON, D TOMLINSON, D P TOMLINSON, D P. TONOUE, T M	8408070273 8408130515* 8408040313* 8408150455* 8408300108*	50-445 T 50-382 Q 50-285 Q 50-445 Q 50-10 Q	TUCKER, H B TUCKER, H B. TUCKER, H B. TUCKER, H B TUCKER, H, B	8408200149 8408210362 8408210365 8408210396 8408270091	50-269 P 50-413 P 50-413 P 50-369 P 50-269 F	VAN BRUNT,E E	8408130429 8408140227 8408150207 8408160172 8408160480	50-527 B 50-528 A 50-528 A 50-528 S 50-528 B
TOOLE, R TOSTE, A P TOTH, A. D TOTH, A D TOTH, A D.	8408220365* 8408310075 8408170369 8408270036 8408300464*	50-287 P NUREG 50-397 S 50-397 S 50-397 G	TUCKER,H B TUCKER,H B TUCKER,H B TUCKER,H B TUCKER,H B	8408220201 8408220292 8408220303 8408220465 8408220468	50-269 K 50-269 P 50-413 P 50-369 R 50-269 R	VAN BRUNT,E E	8408160506 8408170348 8408170384 8408200112 8408200217	50-528 8 50-528 A 50-528 8 50-528 F 50-528 F
TOTTEN, M TOURIGNY, E. G TOWNSEND, B TOWNSEND, B TOWNSEND, B	8408030282# 8408200359 8408200590 8408200402 8408210024	MISC 50-285 P CONTRACT CONTRACT CONTRACT	TUCKER, H B TUCKER, H B. TUCKER, H, B TUCKER, H B TUCKER, H B	8408230031 8408240224 8408270160 8408270259# 8408270339	50-413 P 50-413 I 50-269 P 50-369 Q 50-269 P	VAN BRUNT,E E	8408200285 8408200297 8408200322 8408200599 8408220071*	50-528 9 50-528 8 50-528 8 50-528 F 50-528 Q
TOWNSEND.B TOWNSEND.B L TDY.H L TRAGER.J. TRAMM.T R	8408210040 8408310385 8408170016 8408060197* 8408220079	CONTRACT CONTRACT 70-8 50-70 G 50-454 G	TUCKER, H B TUCKER, H B TUCKER, H B. TUCKER, H B TUCKER, H, B	8408270391 8408280230 8408280234 8408280241 8408280281	50-413 G 50-369 G 50-369 G 50-269 G 50-413 P	VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E	8408220128 8408220143 8408240241 8408240289 8408270133	50-528 8 50-528 8 50-528 A 50-528 A 50-528 E
TRAMM, T R. TRAMM, T.R TRAMM, T R TRAMM, T R TRAMM, T R TRAMM, T, R	8408270106 8408270237 8408270306 8408270113 8408270118	50-454 F 50-454 A 50-454 E 50-454 A 50-454 A	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H, B TUCKER, H, B	8408280372 8408280377* 8408280389 8408280476* 8408270094	50-413 F 50-413 F 50-369 S 50-269 G 50-370 S	VAN BRUNT,E E	8408270240 8408280204 8408280243 8408280275 8408280283	50-528 F 50-528 8 50-528 8 50-528 8 50-528 8
TRAMM, T R TRAMM, T R TRAMM, T R. TRAMM, T R TRAMM, T R	8408270204 8408270218 8408270265 8408270373 8408300053	50-454 E 50-454 F 50-454 E 50-454 E 50-454 K	TUCKER, H B TUCKER, H, B TUCKER, H B. TUCKER, H B TUCKER, H B	8408300014 8408300404 8408300497 8408300501 8408300509	50-269 F 50-413 R 50-287 S 50-413 S 50-370 R	VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E.E	840 8280277 840 8280302 840 8280317 840 8280325 840 8280335	50-528 8 50-528 8 50-528 8 50-528 8 50-528 8
TRAMM,T R TRAMM.T R. TRAMMELL,C M TRAVERS,H D TREAT,R L	8408310163 8408310226 8408170144 8408240374 8408310075	50-454 A 50-454 E 50-344 P 50-320 R NUREG	TUCKER, H B TUCKER, M, K TUCKER, M, K TUCKMAN, M S TULEY, C R	8408310121 8408030263 8408270250 8408150335* 8408080284*	50-269 F WASTE MOT WASTE MOT 50-269 F 50-413 E	VAN BRUNTIE E VAN DENBERGID VAN VLIETIJ VAN VLIETIJ VAN WAGNERIB V	8408280357 8408160255 8408080131 8408070179 8408310165*	50-328 8 50-255 R 50-287 F 50-287 F 50-285 G
TREBY, S. A. TREBY, S. A. TREMBLAY, P. TRIMBLE, D. C. TRIMBLE, D. C.	8408210366 8408270179 8408090317 8408240363* 8408270486*	50-358	TURK, J. TURK, B E TURK, B E TURK, B E TURK, B E TURLEY, K.	8408050209 8408070279 8408130248 8408130081 8408200255	50-70	VANCE, J. N VANDEL, T E VANDENBURGH, D VANDER MOLEN, H VANDEWALLE, D	8408080522 8408150511* 8408130354* 8408220265 8408130353	WASTE MOT 50-461 0 50-29 0 NUREO 50-255 F
TRINOSKEY,P A TRIPP,L E. TRIPP,L E TROJOUSKY,M TROSKOSKI,W M,	8408020070* 8408080448* 8408150244* 8408240382 8408080448*	50-133 P 50-334 Q 50-277 Q NUREQ 50-334 Q	TURBHIF.A UEHLEIN,J ULIE,J ULIE,J M ULLRICH,W T	8408010263* 8408080257 8408060325* 8408080181* 8408270107	50-155 Q 50-445 T 50-382 Q 50-243 Q 50-277 8	VANDEWALLE, D J VANDEWALLE, D J VANDEWALLE, D J VANDEWALLE, D J VANDEWALLE, D J	8409030109 8409030150 8409070431 8409090144 8409090171*	50-105 P 50-255 P 50-255 P 50-155 P 50-155 P
TROSTEN,L M TROTT,E A. TROTTIER,E TROWBRIDGE,G F. TROWBRIDGE,G F	8408020120 8408310368* 8408010157 8408090423 8408090423	PR CONTRACT MISC 50-287 0 50-287 0	UMBEL, D. UMBEL, D. UMBEL, D. UMBEL, D. UMBEL, D	8408040424 8408070101 8408080005 8408080052 8408080317	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	VANDEWALLE, D J VANDEWALLE, D J VANDEWALLE, D J VANICHKO, B E	8408100134 8408240161 8408270281* 8408270372* 8408060231*	50-255 P 50-255 P 50-255 Q 50-155 Q 50-328 P
TROWBRIDGE, G F TROWBRIDGE, G F TROWBRIDGE, G F TROWBRIDGE, G F TROWBRIDGE, G, F	8408140007 8408140007 8408170325 8408170325 8408170330*	50-289 G 50-289 G 50-289 G 50-289 G 50-289 G	UMBEL, D UMBEL, D UPRIGHT, C. M UPRIGHT, C M UTLEY, E E.	8408070041 8408070113 8408270221* 8408270492* 8407240111	CONTRACT CONTRACT 50-335 G 50-413 G 50-324 K	VANTERPOOL:E C VARELA:A A VARELA:A A VARQA:B A VARQA:B A	8408130410* 8408150453* 8408140240* 840814020 8408010005	50-287 G 50-354 G 50-322 G 50-247 P 50-250 P
TROMBRIDGE, G. F TUCKER, H. B. TUCKER, H. B. TUCKER, H. B. TUCKER, H. B.	8408170330* 8408030130 8408040097 8408040117 8408070243	50-289	UTLEY,E E VALIGUETTE,J C VAN BRUNT,E E VAN BRUNT,E E. VAN BRUNT,E E.	8408140151* 8408060300 8408010215 8408010346 8408010377	50-400 T 40-8722 50-528 K 50-528 S 50-528 S	VARGA: S A VARGA: S A VARGA: S A VARGA: S A VARGA: S A	8408010109 8408010119 8408010218 8408060277 8408060422	50-250 F 50-250 P 50-334 P 50-348 P 50-305 F

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
VARGA,S A VARGA,S A VARGA,S A VARGA,S A VARGA,S A	8408070045 8408070075 8408070515 8408070521 8408070530	50-272 F 50-250 P 50-334 P 50-334 P 50-247 P	VERRELLI, D M	8408270435* 8408270460 8408270463 8408270561 8408280026	50~324 Q 50~43B Q 50~390 Q 50~395 Q 50~400 Q	HALKER, J B WALKER, J B HALKER, R D WALKER, R D WALKER, R D	8408030257 8408140508 8408010283 8408040302 8408040303*	50-259 S 50-259 S 50-341 Q 50-456 Q
VARGA, S A	8408130233	50-348 P	VERRELLI, D M	8409280027	50-261 G	WALKER,R D	8408070452	50-461 Q
VARGA, S A	6408130554	50-334 P		8409280030	50-390 G	WALKER,R D	8408140426	50-2 V
VARGA, S A	6408160528	50-286 P		8408280039*	50-261 G	WALKER,R D	8408150502	50-461 Q
VARGA, S A	6408170041	50-334 F		8408280038	50-400 G	WALKER,R D	8408150507*	50-461 Q
VARGA, S A	6408170386	50-348 F		8408280076	50-259 G	WALKER,R D	8408170050	50-255 V
VARGA,S A	8408200387	50-280 F	VERRELLI, D M	8408280124*	50-259 G	WALKER, R D	8408170089	50-483 V
VARGA,S A	8408210554	50-272 P		8408290021	50-261 G	WALKER, R D	8408230132	50-263 V
VARGA,S A	8408210554	50-250 P		8408270034*	50-261 G	WALKER, R D	8408230144	50-409 0
VARGA,S A	8408210434	50-250 P		8408300316	50-327 F	WALKER, R D	8408230273	50-373 0
VARGA,S A	8408230073	50-261 F		8408300361	50-261 F	WALKER, R D	8408230521	50-266 V
VARGA: 5 A	8408280290	50-247 P	VERRELLI, D M	8408300459	50-327 G	WALKER,R D	8408230526	50-282 V
VARGA: 5 A	8408300312	50-261 F	VERRELLI, D M	8408310051	50-261 F	WALKER,R D	8408280002	50-255 Q
VARGA: 5 A	8408310003	50-250 F	VIETH, D L	8408200430	Waste Mot	WALKER,R D	8408300058	50-263 Q
VARGA: 5 A	8408310136	50-247 P	VIETH, D L	8408200435	Waste Mot	WALKER,R D	8408300181	50-315 Q
VARGA: 5 A	8408310189	50-250 Q	VIETH, D L	8408210171	Waste Mot	WALKER,R D	8408300172	50-305 Q
VARQA.S A VASELIN.J VASEALLO.D B VASEALLO.D B VASEALLO.D B	8408310451 8408270545 8407100322 8408010018 8408030052	50-305 P 40-8502 50-259 Q 50-298 P 50-271 F	VIETH, D L VIETH, D L VIETTI, A VIETTI, A VILLA, R	8408240354 8408310273 8408070445 8408070479 8408310186	WASTE MOT Waste mot 50-443 a 50-445 a 50-219 b	WALKER,R D WALKER,R L WALKER,R S, WALLACE,J F WALLACE,J F	8408310299 8408300272 8408200454* 8408150505* 8408150530*	50-255 Q NUREG 50-352 T 50-322 T
VASSALLOD B VASSALLOD B VASSALLOD B VASSALLOD B VASSALLOD B	8408030080 8408030125* 8408030180 8408040157 8408070015	50-333 P 50-296 P 50-220 P 50-293 P 50-333 F	VINCELETTE, M D VINCELETTE, M D VITO, D VITO, D	8408280010 8408290216 8408290366 8408210381* 8408080461*	40-8675 40-8681 40-8681 50-352 G 50-220 G	WALLACE, PR WALLACE, PR WALLACE, PR WALLACE, PR WALLACE, PR	8408060241 8408090156 8408160269 8408160453 8408160493	50-327 8 50-327 8 50-328 8 50-327 8 50-327 8
VASSALLO, D B	8408070016	50-324 P	VITO, D J	8408160432*	50-245 Q	WALLACE,PR WALLACE,PR WALLACE,PR WALLACE,PR WALSH,M	8408140322	50-327 8
VASSALLO, D B	8408070129	50-273 P	VOGLER, B H	8408090197	50-352 G		8408170033	50-328 8
VASSALLO, D B	8408130032*	50-259 P	VOGLER, B H	8408090229	50-352 T		8408230309	50-327 8
VASSALLO, D B	8408140024	50-259 P	VOGLER, B H	8408090234*	50-352 T		8408310030	50-327 8
VASSALLO, D B	8408180310	50-324 P	VOGLER, B H	8408090238	50-352 G		8408070424*	50-445 0
VASSALLO, D B	8408150513	50-263 P	VDGLER.B H	8408130310	50-275 M	WALSH, M	8408070471*	50~445 0
	8408150575	50-259 P	VDGLER.B H	8408150425	50-352 G	WALSH, M	8408070503*	50~445 0
	8408150578	50-271 P	VDGLER.B H	8408210341	50-352 G	WALSH, M	8408160131*	50~445 0
	8408150593*	50-254 P	VDGLER.B H	8408280415	50-352 G	WALSH, M	8408160158*	50~445 0
	8408150599	50-271 P	VDGLER.B H	8408280442	50-275 M	WALSH, M	8408160187*	50~445 0
VASSALLO, D B	8408150404*	50-271 P	VOGLER, BH	8408300170	50-352 G	WALSH,M	8409280146*	50-445 0
VABSALLO, D B	8408150413*	50-333 P	VOGT, DK	8408240291	WASTE MANA	WALTER,R J	8409280321*	50-346 P
VASSALLO, D B	8408140046	50-324 F	VOIGT, HH	8408070420	50-244 O	WAMBACH,P C	8409140449	50-217 0
VASSALLO, D B	8408140097	50-293 P	VOIGT, HH	8408070420	50-244 G	WAMBACH,T	8408060325*	50-382 0
VASSALLO, D B	8408160090	50-271 P	VOIGT, HH	8408200307	50-244 G	WANG,C H	8408020081	PR
VASSALLO, D B	8408160092	50-298 F	VOIGT, H H	8408200507	50-244 G	WANZEC, T	8408210453*	50~329 A
VASSALLO, D B	8408160137	50-331 P	VOIT, R E	8408150733	71-9073	WARD, K D	8408100040*	50~454 T
VASSALLO, D B	8408160135	50-259 P	VOLGER, B H	8408150425	50-352 G	WARD, 9 R	8408280205	50~413 T
VASSALLO, D B	8408160426*	50-259 P	VOLLMER, R,	8408150029*	50-329 A	WARD, W J	8408020194*	50~329 Q
VASSALLO, D B	8408160465	50-254 P	VOLLMER, R H	8201220049*	50-329 A	WAREMBOURG, D	8408010006	50~267 R
VASSALLO, D D	8408200269*	50-259 P	VOLLMER, R H	8408270315*	50-327 A	WAREMBOURG, D	8408020198	50-267 P
VASSALLO, D B	8408200390	50-260 P	VORDERBRUEGGEN	8408300105*	50-328 G	WAREMBOURG, D	8408070313	50-267 F
VASSALLO, D B	8408200393*	50-260 P	WACHOB, H F	8408130476*	50-322 T	WAREMBOURG, D	8408080514	50-267 S
VASSALLO, D B	8408200423	50-263 P	WACHOB, H F	8408130505*	50-322 T	WAREMBOURG, D	8408150304	50-267 Q
VASSALLO, D B	8408200437	50-260 P	WADDLE, J W	8408220400*	CONTRACT	WAREMBOURG, D	8408210428	50-267 Q
VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D B	8408210004* 8408210012* 8408280261* 8408290287* 8408290324*	50-257 P 50-325 P 50-257 P 50-259 P 50-263 P	WADE, W O WADE, W O WADE, W O WAGNER, A G WAGNER, A W	8408080515* 6408080517* 8408080521* 8408270347* 8408200271*	50-275 G 50-275 G 50-275 G 50-275 G 50-414 G COMMISSION	WAREMBOURG, D W WAREMBOURG, D W WAREMBOURG, D W WAREMBOURG, D W WARNER, D L	8408140207 8408200559 8408290181 8408290264 8408020161	50-267 Q 50-267 P 50-267 F 50-267 F 40-8027
VABSALLO, D B	8408310430*	50-293 P	WAGNER, D	8408080140	50-954 E	WARNICK,R.	8408200324	50-483 8
VASSALLO, D B.	8408310431*	50-260 P	WAGNER, D	8408080147	50-954 E	WARNICK,R F	8406140101	50-456 0
VASUKI, N C	8408100003	50-354 H	WAGNER, D	8408130050	50-354 E	WARNICK,R F	8406140102*	50-456 0
VAUGHAN, C M	8405300761	70-1113	WAGNER, D,	8408200463	50-354 A	WARNICK,R F	8408030071	50-327 0
VAUGHAN, C M	8405300762*	70-1113	WAGNER, D H	8408010124	50-954 E	WARNICK,R F	8408030203	50-341 0
VAUGHAN, C M VAUGHAN, C M VERMA, T R VERNENGO, B VERNON, T M	8405300763* 840828011! 8408010070 8408150001 8408230259	70-1113 70-1113 WASTE MGT GA999 State Prog	WACNER, D. H WAGNER, D. H WAGNER, D. H WAGNER, D. H WAGNER, D. H	8408010126 8408010212 8408060204 8408150170 8408150173	50-354 E 50-354 A 50-354 E 50-354 A 50-354 E	WARNICK,R F WARNICK,R F WARNICK,R F WARNICK,R F WARNICK,R F	8408070273 8408070278* 8408100112 8408130301* 8408130320*	50-440 Q 50-440 Q 50-454 Q 50-329 A
VERRELLI, D M	8408030023	50-370 8	WAGNER, D H	8408140487	50-354 E	WARNICK,R F	8408130327*	90-327 A
VERRELLI, D M	8408070405	50-370 0	WAGNER, D H	8408170403	50-354 E	WARNICK,R F	8408150360*	30-327 A
VERRELLI, D M	8408130194	50-375 0	WAGNER, D H	8408200151	50-354 F	WARNICK,R F	8408150603*	50-327 R
VERRELLI, D M	8408200271*	COMMISSION	WAGNER, D H	8408290513	50-354 A	WARNICK,R F	8408150630*	50-327 A
VERRELLI, D M	8408230249	50-324 0	WAGNER, D H	8408300101	50-354 A	WARNICK,R F	8408150643*	50-327 A
VERRELLI, D M VERRELLI, D M VERRELLI, D M VERRELLI, D M	8408240007 8408240091 8408240338 8408240340 8408270148	50-261 G 50-261 G 50-259 G 50-390 G 50-395 G	WAGNER, H N WAGNER, H N WAGNER, M E WAGNER, M C WAGNER, W J	8408220448* 8408270448* 8408270176 8408270183* 8408300149*	50-320 P 50-320 P 50-289 Q 50-289 Q 50-275 Q	WARNICK:R F WARNICK:R F WARNICK:R F WARNICK:R F WARNICK:R F	8408150458* 8408150444* 8408150481* 8408150494* 8408150725*	50-329 8 50-329 A 50-329 A 50-329 8 50-329 A
VERRELLI, D M	8408270178*	50-395 Q	WAITE,R	8408070017*	50-397 Q	WARNICK,R F	8408170260*	50-329 A
VERRELLI, D M	8408270194	50-259 Q	WAITE,R B	8408300464*	50-397 Q	WARNICK,R F	8408170271*	50-329 G
VERRELLI, D M	8408270232	50-438 Q	WALDRUM,R L	8408240026*	50-382 Q	WARNICK,R F	8408170360*	50-329 A
VERRELLI, D M	8408270417	50-370 Q	WALKA,R M	8408210205	50-354 D	WARNICK,R F	8408210342	50-456 G
VERRELLI, D M	8408270424	50-324 Q	WALKA,R M	8408210326	50-354 D	WARNICK,R F	8408230220	50-483 G

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WARNICK,R F WARNICK,R F WARNICK,R F WARNICK,R F WARNICK,R F	8408230474 8408230502 8408240136 8408240314 8408270239	50-358 • 50-329 q g g g g g g g g g g g g g g g g g g	WENZINGER, C WENZINGER, F WENZINGER, E WENZINGER, E C WESCOTT, H M	8408160382* 8408270410* 8408270579* 8408240363* 8408150262*	50-29	WIESEMANN.R A WIESEMANN.R A WIESEMANN.R A WIESEMANN.R A WIESEMANN.R A	8408160373* 8408220321* 8408230346* 8408270246* 8408070072	50-443 A 50-454 E TOPREP 50-266 P CONTRACT
WARNICK,R F WARNICK,R F WASTLER,S L WASTLER,S L WASTLER,S L	8408270549 8408270553* 8408240149 8408240154 8408270079	50-456	WEST.D WESTAFER.G R WESTAFER.G R WESTAFER.G R WESTAFER.G R	8408030235 8408020010 8408040199 8408040304 8408080189	50-335 S 50-302 P 50-302 P 50-302 S 50-302 S	WIGGINS, E WIGGINTON, D L WIGGINTON, D L WIGGINTON, D L	8408140510 8408210391* 8408010310 8408020114 8408160425	CDNTRACT 50-352 Q 50-315 P REVIEW GRP 50-315 P
WASTLER, S L WASTLER, S L WATERMAN, M E WATERS, D B WATKING, L B	8408270197 8408270205 8408160248 8408140036* 8408010258	40-8064 40-8728 50-269 P 50-400 T 50-458 G	WESTAFER, G R WESTAFER, G R WESTAFER, G R WESTAFER, G R WESTAFER, G R	8408160238 8408160247 8408160410 8408160526 8408200278	50-302 8 50-302 S 50-302 S 50-302 R 50-302 P	WILBER.H A WILBORN.L WILBUR.L C WILCOVE.M N WILCOVE.M N	8408090178 8408090157 8408070345 8408020185* 8408020187*	50-382 G 40-8769 PR 50-329 G 50-329 G
WATKINS,L B WATKINS,M WATKINSTON,B E WATSON,R A	8408010258 8408280145 8408280145 8408080472 8408020012	50-458 G 50-445 G 50-445 G NUREG 50-400 A	WESTAFER.G R WESTAFER.G R WESTAFER.G R WESTAFER.G R WESTAFER.G R	B40820031 1 B408200330 B408200316 B408230424 B408230430	50-302 F 50-302 P 50-302 S 50-302 S	WILCOVE,M N WILCOVE,M N WILCOVE,M N WILHITE,M	8408090164 8408150119 8408150676* 8408150723* 8408300093	50-454 G 50-454 T 50-329 A 50-329 A 50-295 S
WATBON.R A WATTS,R J WEAVER,K T WEAVER,W J WEBER,M F	8408140151* 8408020048 8408130108* 8408270204* 8408200407	50-400 T 50-322 T 50-454 Q 50-266 F Waste Mgt	WESTAFER, G R WESTAFER, G R WESTAFER, G R WESTAFER, G R WESTHALL, M	8408280069* 8408280154 8408280170 8408300341 8408200446	50-302 Q 50-302 P 50-302 Q 50-302 S 50-454 T	WILLIAMS, C C WILLETT, D J WILLETT, D J WILLIAMS, C C	8408070162 8408210270 8408240065 8408070017* 8408070217*	50-294 V 50-387 S 50-387 S 50-397 Q 50-454 Q
WECHBELBERGER WECHBELBERGER WEDDINGTON, R E WEGST, W F WEGST, W F	8408280273* 8408300076* 8408280485* 8408010339 8408150141	50-219 0 50-219 0 50-269 0 50-142 P 71-522	MESTBIY, J H METHY, C M METHY, C M WETTERHAHN, M J WETTERHAHN, M J	8408310975 8408020123 8408280097 8408040228 8408040228	NUREC 50-389 F 50-335 F 50-352 G 50-352 G	WILLIAMS.C C WILLIAMS.C C WILLIAMS.C C WILLIAMS.C C	8408150293* 8408170181* 8408200227* 8408230144* 8408270277*	50-255 G 50-329 G 50-454 G 50-341 G 50-454 G
WEGST.W F WEGST.W F WEIKAM.E J WEIL.C H	8408210359 8408310141 8408160457* 8408070208 8408020190*	PR PR 50-458 Q 50-458 E 50-327 Q	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	8408070366 8408070372 8408070372 8408070429 8408070429	50-352	WILLIAMS,C C WILLIAMS,C C WILLIAMS,D WILLIAMS,D WILLIAMS,D L	8408300121* 8408300174* 8408300220* 8408230252* 8408160193*	50-456 Q 50-440 Q 50-341 Q 50-454 Q 50-483 Q
WEIL.C H WEINKAM.E J WEINKAM.E J WEISE.S WEISE.8	8408020194* 8408040412 8408080249 8408270536* 8408280247	50-329 G 50-458 G 50-458 E 50-261 G 50-327 S	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	8408070461 8408070461 8408080404 8408080404 8408130387	50-358	G.RAMILLING G H.RAMILLING J W.L.RAMILLING J W.L.RAMILLING J W.L.RAMILLING J	8408160169 8408150244* 8407260218 8408010311 8408030164	50-263 F 50-277 G 50-250 K 50-251 S 50-335 P
WEISS, A J WEISS, D WEISS, D WEISS, E R	8408010179 8408020209* 8408170393* 8408170394* 8408020040	NUREG 70-36 70-149 70-149 50-289 G	METTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	8408150387 8408240254 8408240254 8408310223 8408310223	50-352 G 50-352 T 50-352 T 50-352 G 50-352 G	W L.SMAILLIW W L.SMAILLIW W L.SMAILLIW W L.SMAILLIW W L.SMAILLIW	8408030235 8408030239 8408080230 8408090009 8408090094	50-335 8 50-250 8 50-250 8 50-335 F 50-387 P
Weiss, e R Weiss, e R Weiss, e R Weiss, e R Weiss, e R	8408140474 8408140474 8408150145 8408170335 8408220342	50-289 G 50-289 G 50-289 G 50-289 G	M E.YELAHW W G.WOGASHW T. W.RSLISSHW W C.RSLISSHW W C.RSHOINW	8408310265 8408140466* 8408070104* 8408030025* 8406260276	WASTE MANA 70-1308 CONTRACT 50-327 P 50-454 Q	M F'SHVITTIN A C'SHVITTIN A C'SHVITTIN AL'SHVITTIN	8409090243 8408100016 8408130215 8408160521 8408170054	50-335 P 50-250 F 50-335 F 50-250 B 50-387 P
Weiss, e R Weiss, e R Weiss, e R Weiss, e R Weiss, e R	8408220362 8408240245 8408240245 8408270359 8408270359	50-287	D CALIHM W C'USHOIHM W C'USHOIHM W C'USHOIHM	8406260276 8408280194 8408280194 8408310201 8408230043#	50-454 G 50-367 G 50-367 G 50-454 G WASTE MOT	A F'SWYITIN A P'SWYITIN A P'SWYITIN AIFTIWS'Y M	8408170384 8408170233 8408200143 8408200200 8408200273	50-250 P 50-335 G 50-389 P 50-389 P 50-250 S
WEISS,E R WELLS, B L WELLS, G A WELLS, C H	8408280493 8408280493 8408010342* 8408280205 8408150476*	50-289 G 50-287 G 50-335 H 50-413 T 50-322 T	WHITE, J R WHITE, J R WHITE, M WHITENER, H L WHITMAN, D	8408200023* 8408230549* 8408080038* 8408270338* 8408070247	50-289 0 50-293 0 COMMISSION 50-321 0 50-298 F	H F'SWYITIM H F'SWYITIM H F'SWYITIM HIFTHWS'T H	8408270155* 8408270015 8408270019 8408270200* 8408270203	50-251 G 50-250 P 50-250 P 50-335 G 50-250 S
WELLS,C H WELLS,C H WELLS,R A WELLS,R A WELLS,R A	8408150505* 8408150530* 8408150736* 8408150749* 8408270330*	50-322 T 50-322 T 50-327 A 50-327 A 50-327 Q	WHITMAN,J H WHITMAN,R WHITMORE,H L WHITTEMORE,J WHITTIER,G D	8408240336 8408080257 8408160146 8408310302* 8408030008	40-6457 50-445 T NUREG 50-255 G 50-307 F	MITTIWE'N M MITTIWE'N M MITTIWE'N M MITTIWE'N M MITTIWE'N M	8408270298* 8408270314* 8408270344 8408270384 8408280058	50-335 G 50-250 G 50-250 P 50-250 G 50-335 G
WELLS.R W WELLS.R W WELLS.R W WELLS.R W WEN.P	8408130349 8408130349 8408140409 8408140409 8408080490*	TOPREP TOPREP TOPREP TOPREP 50-287 G	WRITTIER, G D WHITTIER, G D WHITTIER, G D WHITTIER, G D WHITTIER, G D	8408030272 8408070367 8408090173 8408280210 8408280227	50-307 S 50-307 P 50-307 P 50-307 F 50-307 P	WILLIAMS, J W WILLIAMS, J W WILLIAMS, J W W T. SMAILIAM W T. SMAILIAM	8408280106 8408280182 8408280236 8408280238 840810133	50-389 Q 50-335 Q 50-335 Q 50-250 P 50-250 F
WEN,P WEN,P C WENGER,N W WENSLAWSKI,F	8408090330* 8408080236* 8408130410* 8408230440* 8408060123	50-322	WICK.E A WICK.E A WICKETT,A J WIDMAN,J C	8408040178 8408240335 8408240372 8408130006 8408150359	WASTE MOT WASTE MOT WASTE MOT NUREO XPORTLIC	WILLIAMB.J W WILLIAMB.L A WILLIAMB.R E WILLIAMB.R J WILLIAMB.W R	8408310145 8408040426* 8408280121 8408140384* 8408130007	WASTE MANA TOPREP NUREO
MENSTAMSKI'L V MENSTAMSKI'L V MENSTAMSKI'L V MENSTAMSKI'L V MENSTAMSKI'L V MENSTAMSKI'L V MENSTAMSKI'L V MENSTAMSKI'L V MENSTAMSKI'L V	8408060156 8408070416 8408080147 8408070001 84080700017	50-312 8 50-312 S 70-734 50-361 G 50-344 G	WIDMAN, J C WIEDEMAN, D WIEDEMAN, D G WIEDER, A V WIESEMANN, R A	8408150361* 8408020052 8408070329 8408270346* 8407230203*	XPORTLIC ILE ILE 70-734 TOPREP	WILLIAMSON, E L WILLSEY, W B WILLSEY, W B WILSON, B	8408020068* 8408140151* 8408130341 8408210546 8408240313	50-400 Y 50-277 P 50-171 R 50-327 S
MENSLAWSKI.F A WENSLAWSKI.F A WENSLAWSKI.F A WENSLAWSKI.F A	8408070075 8408070086 8408070120 8408130071 8408130318	50-344	WIESEMANN,R A WIESEMANN,R A WIESEMANN,R A WIESEMANN,R A WIESEMANN,R A	8408040125* 8408070257* 8408070445* 8408080280* 8408080284*	TOPREP 50-244 P 50-498 A 50-413 E 50-601 K	WILSON, B D WILSON, J H WILSON, J, H WILSON, K R	8408230468 8408230513 8408230334 8408130091 8408160238	XPORTLIC XPORTLIC 50-382 A NUREC 50-302 S

AUTHGR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
WILSON, R F WILSON, V H WILSON, V H WILSON, V H WILSON, V H	8408280178 8408210386* 8408210392* 8408210397* 8408210401*	50-289 P 50-329 A 50-329 A 50-329 A 50-329 A	WRAY, J R WRIGHT, C L	8408270317* 6408270364* 8408270423* 8408270447* 8408060315	50-335 Q 50-369 Q 70-143 50-369 Q 50-261 S	AONAGBFOOD' B 7 AONAGBFOOD' B 7 AONAGBFOOD' B 7 AONAGBFOOD' B 7 AONAGBFOOD' B 7	8408280342 8408280461 8408270365 8408300017 8408300230	50-445 A 50-445 A 50-454 A 50-423 A 50-456 A
WILSON,WE WILTERDING,DJ WILTERDING,DT WINDHAM,R WISE,CL	8408020085 8408270388= 8408220388= 8408070267 8408140482	PR 50-445 T 50-445 T 50-278 F 50-440 G	WRIGHT, C L WRIGHT, D R WRIGHT, D R WRIGHT, G WRIGHT, G	8408170188 8408220385* 8408220385* 8408100109 8408200308	50-261 8 50-445 T 50-445 T 50-275 S 50-255 S	ADNUGLINO'E N ADNUGLING'E N ADNUGLING'E N ADNUGBLOOG'B N	8408310171 8408150498* 8408150505* 8408150514* 8408150530*	50-440 F 50-322 T 50-322 T 50-322 T
WISE, R WISEMAN, G R WISEMAN, G R WITHERS, B D WITHERS, B D	8408160515* 8408270371* 8408280028* 8408010281* 8408020057	50-458 G 50-413 G 50-400 G 50-344 G 50-344 P	WRIGHT, G WRIGHT, G C WRIGHT, G C WRIGHT, G C WRIGHT, N A	8408210269 8408090177* 8408230211* 8408240088* 8408070302	50-315 S 50-295 G 50-315 G 50-255 G 50-352 G	YUHAS.G YUHAS.G YUHAS.G YUHAS.G YUHAS.G P	8408060123 8408060136 8408070004* 8408070071* 8408070021*	50-312 S 50-312 S 50-361 Q 50-312 Q 50-344 Q
WITHERS, B D	8408070447 8408080314 8408090158 8408090237 8408130414	50-344 P 50-344 P 50-344 P 50-344 P 50-344 F	WRIGHT,N A WRIGHT,N A WRIGHT,N A WRIGHT,R J WRIGHT,R J	8408150425 8408280415 8408300119 8408010123 8408030279	50-352 0 50-352 0 50-352 0 HASTE MOT WASTE MOT	YUHAS,G P YUNDT,C P YUNDT,C P ZAHNLEUTER,R J	8408070080* 8408230087* 8408070040 8408280149 8408020200	50-344
WITHERS, B D	8408140202 8408140287 8408210137 8408210415 8408210438	50-344 P 50-344 P 50-344 P 50-344 F 50-344 P	L S'THOISM C S'THOISM C S'THOISM C S'THOISM C S'THOISM	8408060242 8408060275 8408130144 8408200404 8408200444	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT	ZAHNLEUTER, R J ZAHNLEUTER, R J ZAHNLEUTER, R J ZAHNLEUTER, R J ZAHNLEUTER, R J	8408080410 8408130142 8408130244 8408130284 8408140138	50~322 G 50~322 G 50~322 G 50~322 G 50~322 G
WITHERS, B D WITTENBURG, K C WDCKENFUSS, W A WOHLD, P. R WOJTULEWICZ, T.	8408280242 8408040283 8408300079 8408140193* 8408130144	50-344 P 50-374 S 50-166 P 50-483 Q 50-249 S	WRIGHT,T W WRIGHT,T W WRIGHT,T W WU,R R WUNDERLICH,R C	8408010181 8408010181 8408170382 8408230196* 8408030283	50-454 G 50-454 G 50-454 G 70-1450 Wabte Mot	ZAHNLEUTER,R J ZALIZNYAK,M ZALIZNYAK,M A ZECH,G G ZECH,G G	8408160210 8408170339* 8408170342* 8408060043 8408060087	50-322 G 50-354 G 50-354 G GA999 GA999
WOJTULEWICZ,T WOLF,J.F WOLF,T WOLF,T R WOLFE,J F	8408130330 8408170291 8408070242* 8408070234 8408030078	50-237 S 50-320 G TOPREP TOPREP 50-320 G	WYANT, F J WYNGARDEN, B D YANDELL, L A YANDELL, L A YANG, M S	8408080357 8408290351 8408060313* 8408270500* 8408130420*	NUREG 70-143 50-285 Q 50-298 Q 50-454 Q	ZECH, G G ZECH, G G ZECH, G G ZECH, G G	8408040131 8408070387 8408080944 8408080350 8408080114	GA999 GA999 GA999 GA999 GA999
WOLFE.S J WOLLETT.S WOLLETT.S WOLLETT.S	8408150139 8408310148 8408010041 8408070047 8408080502	50-289 G 50-338 G CONTRACT CONTRACT CONTRACT	YEH.N YEN.T C YIN.I T YIN.I T YIN.I T	8408160390* 8408130455* 8408020131* 8408020134* 8408160341*	50-45B A 50-445 A 50-275 G 50-275 G 50-341 G	ZECH, G G ZECH, G G ZECH, G G ZECH, G G	8408080130 8408080282 8408080306 8408080308 8408080311	QA999 QA999 QA999 QA999 QA999
WOLLETT.S WOLLETT.S WOLLETT.S WOLTNER.E	8408090135 8408090548 8408140510 8408270557 8408150580#	CONTRACT CONTRACT CONTRACT CONTRACT 50-29 Q	YORK, J W YOUNG, C YOUNG, C YOUNG, F YOUNG, O O	8408270469* 8408080087* 8408090220 8408150271* 8408010188*	50-370 G 50-320 H 50-320 H 30-289 G 50-327 D	ZECH, O G ZECH, O G ZECH, O G ZECH, O G ZECH, O G	8408080336 8408080341 8408070006 8408070043 8408070174	QA999 QA999 QA999 QA999 QA999
MODD'N W MOD'N M MONG'N N MOTHES'E	8408270445* 8408310087 8408170117* 8408220370 8408270005	50-271 Q NUREG 50-443 Q NUREG 50-354 D	YQUNG, G G YQUNG, M A YQUNG, M A YQUNG, M A	8408010191* 8408010213 8408070305 8408070477 8408150133	50-329 D 50-250 G 50-250 G 50-414 G 50-244 G	ZECH. 0 0 ZECH. 0 0 ZECH. 0 0 ZECH. 0 0 ZECH. 0 0	8408070181 8408070170 8408100128 8408140270 8408140278	GA979 GA999 GA999 GA999 GA999
WOODARD, C WOODARD, C H WOODARD, J D WOODHEAD, C P WOODHEAD, C P	8408070330* 6408150110* 8408230515 8408010207 8408070498	50-322 G 50-336 G 50-348 S 50-142 G 50-440 G	YDUNG, T YDUNG, T YDUNG, T YDUNG, T	8408080501# 8408080513# 8408300100# 8408300105# 8408300114#	50-275 Q 50-275 Q 50-528 Q 50-528 Q 50-312 Q	ZECH. G G ZECH. G G ZECH. G G ZECH. G G ZECH. G G	8408170024 8408170057 8408170105 8408200194 8408200315	GA979 GA999 GA999 50-400 S GA999
WOODHEAD, C P WOODHARD, C H WOODHARD, J D WOOLEVER, E J	8408270057 84080903246 8408160246* 8408200611 8408010154	50-440 G 50-304 B 50-245 G 50-248 R 50-412 F	Adnusproov B ?	8408300133* 8408010078 8408010082 8408010098 8408010099	50-312 Q 50-445 A 50-483 P 50-445 Q 50-387 P	ZECH. O G ZECH. O G ZECH. O G ZECH. O G ZECH. O G	8408200351 8408210370 8408210377 8408220320 8408220360	0A999 0A999 50-400 S 0A999 0A999
WODLEVER, E J WODLEVER, E J WODLEVER, E J WODLEVER, E, J WODLEVER, E J	8408020011 8408020019 8408060259 8408070355* 8408070414	50-412 E 50-412 E 50-412 B 50-412 G 50-412 F	ADNABEGGD: B ?	8408010112 8408010116 8408010127 8408010131* 8408010197	50-445 A 50-454 A 50-423 D 50-423 D 50-423 D	ZECH. G G ZECH. G G ZECH. G G ZECH. G G ZECH. G G	8408220383 8408240013 8408240125 8408270353 8408280120	GA799 50-352 G GA799 GA799 GA799
WOOLEVER, E J WOOLEVER, E J WOOLEVER, E J WOOLEVER, E J	8408070432 8408130005 8408130312 8408140088 8408140127	50-412 E 50-412 E 50-412 E 50-412 E 50-412 E	AUNOBFODO B ?	8408010252 8408020140 8408060240* 8408060379 8408070028	50-423 D 50-423 D 50-482 A 50-482 A 50-482 A	ZECH. 0 G ZECH. 0 G ZECH. L W ZECH. L W	8408280215 8408270201 8408270315 8408230202 8408280427	50-390 @ QA999 QA999 50-275 G 50-289 @
VER,E J VER,E J VER,E J FIFR E J	8408150179 8408160333 8408160379 8408210437 8408210476	50-412 E 50-412 E 50-412 E 50-412 A 50-412 B	AUNOBFOOD B 7 AUNOBFOOD B 7 AUNOBFOOD B 7 AUNOBFOOD B 7	8408070034 8408070137 8408130181 8408130247 8408130449	50-454 A 50-440 A 50-445 B 50-445 F 50-445 A	ZEFF, D W ZEFF, D W ZEUGIN, L B ZEUGIN, L B ZIBULSKY, H	B408280270# B408280277# 8408130347 B408130347 8408080209#	70-1201 70-1201 50-322 G 50-322 G 50-220 G
	8408230246 8408230327 8408240275 8408270071 8408270141	50-412 A 50-412 E 50-412 G 50-412 P 50-412 E	AONOBITOOD B 7 AUNOBITOOD B 7 AUNOBITOOD B 7 AUNOBITOOD B 7 AUNOBITOOD B 7	8408130492 8408150324 8408160047 8408170138 8408200469	50-440 A 50-423 E 50-483 P 60-445 E 50-423 E	ZIBULBKY, H ZIBULSKY, H ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8408200023* 8408270473* 8408160242 8408010136 8408060054	9 7287-05 50-333 0 50-333 0 70-3333 71-3334 71-3334 71-3334 71-3334
	8408270165 8408280200	50-412 E 50-412 E E A F	AUNOBEDOD B 7 AUNOBEDOD B 7 AUNOBEDOD B 7 AUNOBEDOD B 7 AUNOBEDOD B 7	8408200471* 8408200533 8408210158 8408240222 8408280301	50-423 E 50-423 A 50-445 F 50-423 A 50-454 E	ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8408040435 8408070175 8408070181 8408070202 8408070204	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ZIMMEPMAN, J V	8408070209	XPORTLIC
ZIMMERMAN, J V	8408070214	XPORTLIC
ZIMMERMAN, J V	8408070506	XPORTLIC
ZIMMERMAN, J V	8408070510	XPORTLIC
ZIMMERMAN, J V	8408070512	XPORTLIC
ZIMMERMAN, J V	8408080108	XPORTLIC
ZIMMERMAN, J V	8408080118	XPORTLIC
ZIMMERMAN, J V	8408080534	XPORTLIC
ZIMMERMAN, J V	8408150112	XPORTLIC
ZIMMERMAN, J V	8408150163	XPORTLIC
ZIMMERMAN, J V	8408150166	XPORTLIC
ZIMMERMAN, J V	8408150169	XPORTLIC
ZIMMERMAN, J V	8408150246	XPORTLIC
ZIMMERMAN, J V	8408150270	XPORTLIC
ZIMMERMAN, J V	8408150708	XPORTLIC
ZIMMERMAN, J V	8408150713	XPORTLIC
ZIMMERMAN, J V	8408150717	XPORTLIC
ZIMMERMAN, J V	8408170405	XPORTLIC
ZIMMERMAN, J V	8408170411	XPORTLIC
ZIMMERMAN, J V	8408170423	XPORTLIC
ZIMMERMAN, J V	8408200150	XPORTLIC
ZIMMERMAN, J V	8408200160	XPORTLIC
ZIMMERMAN, J V	8408200189	XPORTLIC
ZIMMERMAN, J V	8408200450	XPORTLIC
ZIMMERMAN, J V	8408200485	XPORTLIC
ZIMMERMAN, J V	8408200596	XPORTLIC
ZIMMERMAN, J V	8408220420	XPORTLIC
ZIMMERMAN, J V	8408220421	XPORTLIC
ZIMMERMAN, J V	8408220422	XPORTLIC
ZIMMERMAN, J V	8408220430	XPORTLIC
ZIMMERMAN, J V	8408230516	XPORTLIC
ZIMMERMAN, J V	8408230517	XPORTLIC
ZIMMERMAN, J V	8408230525	XPORTLIC
ZIMMERMAN, J V	8408230530	XPORTLIC
ZIMMERMAN, J V	8408230535	XPORTLIC
ZIMMERMAN, J V	8408230550	XPORTLIC
ZIMMERMAN, J V	8408310001	XPORTLIC
ZIMMERMAN, J V	8408310005	XPORTLIC
ZIMMERMAN, J V	8408310017	XPORTLIC
ZIMMERMAN, J V	8408310178	XPORTLIC
ZIMMERMAN, J V	8408310317	XPORTLIC
ZIMMERMAN, J V	8408310330	XPORTLIC
ZIMMERMAN, J V	8408310341	XPORTLIC
ZIMMERMAN, R	8408300175*	50-528 G
ZIMMERMAN, S R	8408060074	50-261 P
ZIMMERMAN, 8 R	8408040192	50-400 A
ZIMMERMAN, 8 R	8408070407	PR
ZIMMERMAN, 8 R	8408080271	50-400 A
ZIMMERMAN, 8 R	8408080274	50-324 P
ZIMMERMAN, 8 R	8408080285	50-400 F
ZIMMERMAN, S.R.	8408080332	50-261 P
ZIMMERMAN, S.R.	8408080337	50-400 E
ZIMMERMAN, S.R.	8408070507	50-400 K
ZIMMERMAN, S.R.	8408140354	50-261 P
ZIMMERMAN, S.R.	8408230221	50-324 P
ZIMMERMAN, S R	8408280199	50-261 P
ZIMMERMAN, S R	8408280207	50-400 A
ZIMMERMAN, S R	8408290011	50-261 P
ZIMMERMAN, S R	8408300243	50-400 Q
ZUKOR, D J	8408010206*	50-329 D
ZUPKO, J M ZUPKO, J M ZUPKO, J M	8408310269 8408090076 8408130588 8408160276 8408200276	50-344 S 50-311 S 50-311 S 50-272 S 50-311 R
ZUPKO, J M	8408300349	50-311 5
ZUPKO, J M	8408300400	50-311 8
ZUPKO, J W	8408230501	50-272 8
ZURAKOWSKI, P R	8408080151*	70-734
ZURAKOWSKI, P R	8408130511*	70-1257
ZUTOVSKY,L E	8408270.347*	CONTRACT
ZHAHR,J E	8408220338*	50-445 T
ZWAHR,J E	8408220388*	50-445 T



The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
ACE Federal Reporters, Inc	8408270503* 8408270508*	CONTRACT CONTRACT
Aerojet Energy Conversion Co (subs of General Tire & Rubber Co )	8408100121 8408140200	TOPREP
	8408140204*	TOPREP
Agriculture, Dept of	8408160486 8408230187	50-354 D 50-423 D
Agriculture, Dept of, Research Center	8408230412 8408230024	50-458 D 50-410 D
Air and Water Pollution Patrol	8408010233	50-352 Q
	8409140450 8408140450	50-352 G 50-352 G
	8408140452*	50-352 Q
	8408140452*	50-352 0
	8408200433	50-352 0
	8408200442* 8408200447*	50-352 G 50-352 G
	8408220354	50-352 G
44.1 (64.14.1 - 11.1	8408240240	50-352 G
Alabama Electric Cooperative, Inc	8408080197	50~348 M
	8408080197 8408080202	50-348 M 50-348 M
	8408080202	50-348 M
	8408080241	50-348 M
	8408080241	50-348 M
Alabama Power Co	8408060070	50-348 F
	8408040070	50-348 F 50-348 V
	8408070314 8408070469	50-348 V 50-348 F
	8408070449	50-348 F
	8408100036	50-34B P
	8408130345	50-364 G
	8408130374 8408130374	50-348 F
,	8408200611	50-348 R
,	8408210412	30-364 P
	8408210417	50-364 F
	8408230326 8408230326	50~348 F 50~348 F
	8408230398	50-348 P
	8408230378	50-348 P
	6408230399* 6408230399*	50-348 P
	8408230515	50-34B B
	8408280048	50-34B G
	8408280174	50-348 Q
Alaska, State of	8408300169 8408240026*	50~348 Q 50~382 Q
Alden Research Laboratory	8408270147*	50-382 G
Allied Chemical Corp	8408130240	40-3372
	8408130273	40-3392
	8408170395	40-3372
American Insulated Hire Corp American Nuclear Corp	8408090002 8408270361	0A797 40-4472
		–

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
American Nuclear Society American Society of Mechanical Engineers	8408310338 840807034 <i>b</i> 8408080277 8408280124* 8408280137*	40-4472 PR NUREG GA799 GA797
American Society of Quality Control American Society of Utility Investors	8408080255 8408290245 8408290269*	NUREG 50-287 T 50-287 T
American Statistical Association Amersham Corp	840808000B* 8408080532	CONTRACT
Ametek, Inc Anaconda Co (subs of Atlantic Richfield Co )	8408030175 8408200288*	QA999 50~528 9
Anaheim, CA Anchor/Darling Valve Co (subs of Anchor/Darling Industries, Inc.)	8408070174# 8408070074	9 14E-08 9799
Anefeo, Inc	8408170070	71-9192
Ann Riley & Associates Anthony, R L	8408170204 8408200444 8408080191 8408090263* 8408280491	71-9192 50-454 T 50-352 G 50-352 G 50-352 G
Argonne National Laboratory	8408310094 8408020234 8408020239* 8408080374 8408100151	50-352 G WASTE MGT WASTE MGT NUREG NUREG
	8408170152* 8408170157* 8408240322 8408310077 8408310083	50-329 Q 50-329 Q NUREG NUREG NUREG
Arizona Public Service Co	8408010215 8408010215 8408010215 8408010344 8408010344	50-528 K 50-528 K 50-528 B 50-528 B
	8408010344 8408010377 8408010377 8408010377 8408010381	50-528 S 50-528 S 50-528 S 50-528 S 50-528 S
	8408010381 8408010381 8408010384 8408010384 8408010384	50-528 8 50-528 8 50-528 8 50-528 8 50-528 8
	8408010388 8408010388 8408010388 8408020229 8408020232	50-528 8 50-528 8 50-528 8 50-527 8 50-528 9
	8408020232 8408020232 8408030048	50-528 8 50-528 8 50-528 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	<u>′</u>
	8408030053 8408030053 8408030053 8408030061 8408030061	50-528 50-528 50-528 50-529 50-529	\$ \$ \$ \$ \$		8408200255 8408200285 8408200297 8408200297 8408200297	50-528 50-528 50-528	A 8 8 8 8
	B408030097 B408030097 B408030097 B408030144 B408030144	50-528 50-528 50-528 50-528 50-528	F F A A		8408200322 8408200322 8408200322 8408200579 8408200579	50-528 50-528 50-529	88944
	8408030144 8408030240 8408030240 8408030240 8408030302	50-528 50-528 50-528 50-528 50-528	A 5 5 5 8		8408200899 8408200600* 8408220071* 8408220128 8408220128	50-528	F G S S
	8408030302 8408030302 8408040075 8408060075 8408060075	50-528 50-528 50-528 50-528 50-528	ទ ទ ស ស ស		8408220128 8408220143 8408220143 8408220143 8408220143	50-528 50-528 50-528 50-528 50-528	8 8 8 8
	8408060319 8408080048 8408080048 8408080048 8408080499	50-528 50-528 50-528 50-528 50-528	A A A A		8408240261 8408240261 8408240263* 8408240263* 8408240263*	50-528 50-528 50-528 50-528 50-528	A A A A
	8408080499 8408080499 8408080529 8408080529 8408080529	50~528 50~528 50~528 50~528 50~528	9 9 9 9		8408240289 8408240289 8408240289 8408270133	50-528 50-528 50-528 50-528 50-528	A A E E
	8408070012 8408070012 8408070012 8408100127 8408100127	50-528 50-528 50-528 50-528 50-528	8 8 A A		8408270133 8408270140* 8408270140* 8408270140* 8408270260	50-528 50-528 50-528 50-528 50-528	EEEF
	8408100127 8408130172 8408130172 8408130172 8408130274	50-528 50-528 50-528 50-528 50-528	A 8 8 8 A		8408270240 8408270240 8408280204 8408280204 8408280204	50-528 50-528 50-528 50-528 50-528	F 55 85
	8408130274 8408130274 8408130277* 8408130277* 8408130277*	50-528 50-528 50-528 50-528 50-528	A A A		8408280263 8408280263 8408280275 8408280283 8408280297	50-528 50-528 50-528 50-528 50-528	8 8 8 8
	8408130303 8408130332 8408130332 8408130332 8408130344	50-528 50-528 50-528 50-528 50-528	8 8 8 9 5		8408280297 8408280297 8408280302 8408280302 8408280302	50-528 50-528 50-528 50-528 50-528	8 8 8 9
	8408130344 8408130351 8408130351 8408130351 8408130429	50-528 50-528 50-528 50-528 50-529	8 E E		8408280317 8408280317 8408280317 8408280325 8408280335	50-528 50-528 50-528 50-528 50-528	88888
	8408140227 8408140227 8408140227 8408150207 8408150207	50-528 50-528 50-528 50-528 50-528	^ ^ ^		8408280335 8408280335 8408280357 8408280357 8408280357	50-528 50-528 50-528 50-528 50-528	8888
	8408150207 8408160192 8408160192 8408160192 8408160180	50-528 50-528 50-528 50-528 50-528	A 8 8 8	Arizona, State of Arkansas Power & Light Co	8408070104* 8408200334* 8408060187 8408070483 8408070483*	CONTRACT 50-528 50-368 50-313 50-313	F 8 P
	8408160480 8408160480 8408160506 8408160506 8408160506	50~528 50~528 50~528 50~528 50~528	8 8 8 8		8408080493 8408080500 8408080512 8408080528 8408130190	50-348 50-348 50-368 50-368 50-313	8888
	8408170348 8408170348 8408170348 8408170384 8408200112	50-528 50-528 50-528 50-528 50-528	A A A 9		8408130326 8408130367 8408140328 8408140355 8408140355	50-313 50-368 50-368 50-313 50-313	9 P P
	8408200112 8408200112 8408200217 8408200217 8408200217	50-528 50-528 50-528 50-528 50-528	F F F		8408140403 8408140429 8408150180 8408150184* 8408150317*	50-313 50-313 50-313 50-313 50-313	P P P G
	8408200224* 8408200224* 8408200224* 8408200255 8408200255	50-528 50-528 50-528 50-528 50-528	F F A		8408170061 8408170061 8408200303 8408280313 8408280316#	50-313 50-313 50-313 50-313 50-313	PPP

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
W	8408230401 8408230417 8408240053 8408240077 8408240080	50-313 F 50-313 F 50-313 S 50-368 S	Bechtel Corp	8408020070* 8408030058* 8408030093 8408030102 8408030102	50-133 P 50-329 A 50-528 K 50-528 K
	8408280184 8408280184 8408280188* 8408280188* 8408300154	50-313 f 50-313 F 50-313 F 50-313 F 50-313 Q		8408030102 8408030133 8408030142 8408030142 8408030142	50-528 K GA999 50-528 K 50-528 K 50-528 K
Armed Forces Radiobiological Research Institute	8408300475 8408300496 8408310231 8408090537*	50-348 8 50-348 8 50-313 P 50-170 P		8408070456* 8408140065* 8408140071* 8408140076* 8408140079*	50-498 A 50-329 A 50-329 A 50-329 A 50-329 A
Army, Dept of, Corps of Engineers	8104230479* 8408010182* 8408140144* 8408140144* 8408140232*	50-329 0 CDNTRACT 50-329 A 50-329 A 50-329 A		8408140314* 8408140314* 8408140320* 8408140326* 8408140326*	50-352 E 50-352 E 50-352 E 50-352 E
	8408140317* 8408140367* 8408140557* 8408150015* 8408150015*	50-329 A 50-329 A 50-329 A 50-329 A 50-329 A		8408140570* 8408150546* 8408150571* 8408150720* 8408170343*	50-329 A 50-329 A 50-329 A 50-329 A 50-354 Q
Arthur D. Little, Inc Ashtabula County, DH Aspen Systems, Inc Atlas Foundry & Machine Co Atlas Minerals, Inc	8408010224* 8408140482 8408230125 8408150592 8408240056	50-354 E 50-440 G NUREG 71-9147 40-3453	Beltway Limousine Service, Inc Bendix Corp	8408270307* 8408280062 8408080480* 8408030197* 8408030264*	50-243 P GA999 CONTRACT WASTE MOT WASTE MOT
Atomic Industrial Forum  Australia. Govt of  BIW Cable Systems. Inc  Babcock & Wilcox Co	8408080303* 8408070351* 8408150131 8408230215 8408010020	NUREG CONTRACT XPORTLIC GA999 70-364		8408030268* 8408030270* 8408150533* 8408270253* 8408270256*	WASTE MGT WASTE MGT WASTE MGT WASTE MGT
	8408020203 8408070389 8408070392* 8408080016 8408130454	70-824 50-269 P 50-249 P TOPREP 70-27	Berger, D Berkshirø Medical Center, Pittsfield, MA	8408270262* 8408270264* 8408270267* 8408310238 8408230176*	WASTE MGT WASTE MGT WASTE MGT 30-287 P 70-1450
	8408140413* 8408150115 8408150118* 840815067 8408210387*	50-346 P 50-313 P 50-13 P 50-13 P 70-364 50-338 P	Bishop, Liberman, Cook, Purceli & Reynolds	8408020040 8408030081 8408080142 8408080142 8408080413	50-413 G 50-416 O 50-445 O 50-445 O 50-445 O
	8408210373* 8408210483 8408230064 6408270121* 8408270159	50-338 P 70-27 TOPREP 70-27 TOPREP		8409080413 8409130093 8409130305 8409220331 8409220331	50~445 G 50~445 G 50~445 G 50~445 G
	8408270258# 8408270274# 8408280270# 8408280277# 8408300141	70-27 70-27 70-1201 70-1201 TOPREP		8408220334 8408220347 8408220347 8408220347 8408220347	50-445 Q 50-445 T 50-445 T 50-445 G
Baltimore Gas & Electric Co	8408300194# 8408310039# 8408070074 8408070074 8408070343	70-824 70-27 50-317 G 50-317 G 50-317 F		8408230187 8408230257 8408230319 8408230319 8408270154	50-445 0 50-445 0 50-445 0 50-445 0 50-445 0
	8408130402 8408150188 8408150395 8408170084 8408170261	PR 50-317		8408280093 8408280156 8408280156 8408280155 8408280165	50-445 0 50-445 0 50-445 0 50-445 0 50-445 0
	8408200492 8408200512 8408270535 8408270258 8408310042	50-318 8 50-318 8 50-317 8 50-317 8 50-318 8	Barg-Harner Corp	8408280251 8408280251 8408280265 8408310216 8408150722	50-445 Q 50-445 Q 50-445 Q 50-445 Q XPORTLIC
Barris, Sott. Denn & Driket Basalt Waste Isolation Project Battelle Memorial Institute, Columbus Laboratories	8408150692* 8408070149 8408070153* 8408010048*	50-327 A Waste mot Waste mot Contract	Boston Edison Ca	8408020130 8408020139* 8408020142* 8408020144* 8408020147*	50-273 P 50-273 P 50-273 P 50-273 P 50-273 P
Battelle Memorial Institute, Pacific Northwest Laboratories	8408170016 8408220387* 8408040405	70-8 CONTRACT 50-204 S		8408020149* 8408030022 8408030121 8408060005	50-273 P 50-273 S 50-273 P 50-273 P 50-273 P
Bear Creek Uraniun Co	8408130043 8408220370 8408290171 8408310075 8408080429	NUREO NUREO NUREO NUREO 40-8452	•	8408060003 8408080503 8408090114 8408090248 8408100008	50-273 P 50-273 R 50-273 B 50-273 P 50-273 G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	RY	AUTHOR AFF[LIATION	ACCESSION NUMBER	SUBJEC	RY
	8408100044 8408100079 8408140239 8408140245* 8408140280	50-293 50-293 50-293 50-293 50-293	8 8 P P	Cabot Corp California Instruments	8408210426* 8408200543 8408200546* 8408070171 8408200457	50-29 XPORTLI XPORTLI XPORTLI XPORTLI	Р С С
	8408140251 8408140256* 8408150055 8408150087 8408160033	50-273 50-273 50-273 50-273 50-273	P 0 P P		8408200537 8408200541 8408230473 8408230485 8408230493	XPORTLIO XPORTLIO XPORTLIO XPORTLIO XPORTLIO	C C
	8408160036# 8408160041 8408160045# 8408160094	50-293 50-293 50-293 50-293 50-293	P P R F	California, Univ of: Berkeley, CA	8408230500 8408230505 8408020211 8408310154 8408270091	XPORTLIC XPORTLIC ACRS PR 50-326	
	8408140349# 8408140374 8408220133 8408280249 8408300198	50-273 50-273 50-273 50-273 50-273	ন	,	8408010339 8408150141 8408150143* 8408210359 8408270142	50-142 71-522 71-522 PR 50-142	P
Brookhaven National Laboratory	8408300348 8408010151 8408010146 8408010179 8408070014	50-293 NUREO NUREO NUREO NUREO	8	California, Univ of, Riverside, CA California, Univ of, San Francisco, CA	8408300109 8408310141 8408310154 8408310154 8408130074#	50-142 PR PR PR PR 50-433	R
	8408070208 8408220333 8408220415* 8408220417* 8408270070	50-206 50-352 50-445 50-445 Waste M	P A G G		8408010253 8408010253 8408010267 8408010267 8408100124	50-424 50-424 50-424 50-424 QA999	0 0 0
Brown & Root. Inc (subs of Halliburton Co )	8408070273	50-445 50-445	T T	•	8408070443 8408200548 8408310205	50-413 50-413 50-413	G G
	8408070273 8408080023 8408080023	50-445 50-445 50-445	T T		8406070060 8407260111 8407260111	50~325 50~324 50~324	K B
	8408080027 8408080032 8408080032 8408080089 8408080089	50~445 50~445 50~445 50~445 50~445	ፓ ፕ ፕ ፕ	!	8407260112* 8407260112* 8408010275 8408020012	50~324 50~324 50~325 50~400	K S A
	8408080257 8408080257 8408220371# 8408220371# 8408220374#	50~445 50~445 50~445 50~445 50~445	ፐ ፐ ፕ ፕ		8408020054 8408030034 8408030034 8408030040 8408030040	50-400 50-324 50-324 50-324 50-324	0 F F
	8408220374# 8408220380# 8408220380# 8408220381# 8408220381#	50~445 50~445 50~445 50~445 50~445	T T T T		8408030074 8408030074 8408030100* 8408030142 8408030234	50-241 50-241 50-241 50-241 50-241	F P P
	8408220385* 8408220385* 8408220386* 6408220388* 8408220393*	50-445 50-445 50-445 50-445 50-445	T T T T		9409040074 9409040099 9409040129 9409040172 9409040174*	50-241 50-325 50-325 50-400 50-400	P 8 8 A A
	8408220393* 8408220399* 8408220399* 8408220403* 8408220403*	50-445 50-445 50-445 50-445 50-445	T T T T		8408060257 8408060315 8408070374 8408070378* 8408070381	50-400 50-261 50-261 50-261 50-400	A B P K
Brown Bover( corp (subs of Brown Bover) & Co , Ltd )	8408220405* 8408220405* 8408030087	50-445 50-445 GA79 <del>9</del>	T		3408070394* 3408070407 3408080217 3408080252	50-400 PR 50-400 50-324	K Q P
4,40, 2,44,	8408030145 8408070317	94999 94999			340808 <b>02</b> 71 3408080274 3408080274	50-400 50-324 50-324	A P P
Brunswick Go Brush Wallman, Inc.	8408220317 8408240259 8408240276 8408080219 8408060300	50-245 GA977 GA977 XPORTL 10 40-8722	8	1 1 2	9408080285 9408080332 9408080337	50-400 50-261 50-400	F P E
Businessman for the Public Interest	8406260276 8408080375 8408170298 8408170326*	50-454 50-454 50-454 50-454	0 G T T		3408070014 3408070031 3408070066 3408070131 3408070291	50-400 50-400 50-400 50-400 50-400	\$ 8 8 8 8 8
C-E Operating Plants Owners Oroup	8408170382 8408170382 8408280174 8408310201 8408130349	50-454 50-454 50-367 50-454 TOPREP	T G G	E E	9408090390 9408090432 9408090509 9408100004 9408100010*	50-324 50-325 50-400 50-261 50-261	9 8 4 F
CEIP Fund, Inc CEPA CYGNA Energy Services	8408140409 8408240350 8408140540 8408140422*	TOPREP PR • 50-352 PR	G	S E	1408100039 1408130288 1408130338 1408140004 1408140008	50-324 50-400 50-324 50-400 50-400	8 9 8 9

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	₹Y	AUTHOR AFFILIATION	ACCESS I DN NUMBER	SUBJEC	
	8408140014 8408140018* 8408140022 8408140023* 8408140027*	50-400 50-400 50-400 50-400 50-400	T T Q T		8408070434* 8408070463* 8408070463* 8408070471* 8408070471*	50-445 50-445 50-445 50-445 50-445	0
	8408140036# 8408140048 8408140057 8408140146 8408140151#	50-400 50-400 50-400 50-400 50-400	T Q G T T		8408090480* 8408090480* 8408090488* 8408090488* 8408090503*	50-445 50-445 50-445 50-445 50-445	0 0 0
	8408140336 8408160075 8408160129 8408160133 8408160144	50-261 50-325 50-324 50-325 50-261	P S G S R		8408070503* 8408070512* 8408070512* 8408160106 8408160106	50-445 50-445 50-445 50-445 50-445	9 9 9
	8408160168 8408160408 8408160416 8408160437 8408160438	50-400 50-400 50-400 50-400 50-400	8 8 8		8408140113* 8408140113* 8408160114 8408160114 8408160131*	50-445 50-445 50-445 50-445 50-445	0
	8408160443 8408170188 8408210027 8408210486 8408220126	50-400 50-261 50-400 TOPREP 50-261	8 S J F		8408160131* 8408160141 8408160141 8408160133* 8408160153*	50-445 50-445 50-445 50-445 50-445	0 0 0
	8408220227 8408230093 8408230117 8408230221 8408240095*	50-261 50-261 50-261 50-324 50-261	P P P Q		8408160158* 8408160158* 8408160171 8408160171 8408160178*	50-445 50-445 50-445 50-445 50-445	9999
	8408240227 8408270431* 8408270321* 8408280035* 8408280133	50-324 50-324 50-261 50-261 50-261	8 0 0 0		8408160178* 8408160187* 8408160187* 8408200605 8408230173	50-445 50-445 50-445 50-445 50-445	0
	8408280166 8408280166 8408280186 8408280199 8408280207	50-324 50-324 50-400 50-261 50-400	Q Q Q P A		B408240244 B408240247 B408240247 B408240248* B408240248*	50-445 50-445 50-445 50-445 50-445	G T T T
	8408280235 8408280460* 8408280465* 8408280469* 8408270011	50-324 50-400 50-400 50-400 50-261	F Q Q Q P		8406280136 8408280136 8406280141* 8408280141* 8408280146*	50-445 50-445 50-445 50-445 50-445	0
	8408270025* 8408270028* 8408300243 8408300312 8408300350*	50-261 50-261 50-400 50-325 50-400	0 0 0 5		8408290319 8408310102 8408310102 8408310105* 8408310105*	50-445 50-445 50-445 50-445 50-445	0 0 0
Center for Law in the Public Interest	8408040046 8408040046 8408060217 8408060217 8408130389	50-275 50-275 50-275 50-275 50-275	0 0 0 0	Citizens for Safe Energy Citizens for an Orderly Energy Policy, Inc City College of New York	8408210104 8408220301 8408020021 8408310194*	50-382 50-322 50-322 50-454	0 0 T T
Central lowa Power Cooperative	8408130389 8408140464 8408140464 8408310210 8408210268*	50-275 50-275 50-275 50-275 50-331	0 0 0	Clark, R B Clermont County, OH Cleveland Electric Illuminating Co	8408310088* 8408040017* 8408010214 8408010214 8408010217*	CONTRAC CONTRAC 50-440 50-440 50-440	ο Θ Θ
Chattanooga State Technical Community College, Chattanooga, TN	8408080064*	CONTRACT			8408010217* 8408020118	50-440 50-440	Q I
Chem-Nuclear Systems, Inc Chemical Haste Management, Inc Chicago Fluid Power Co	8408170021 8408170023* 8408210549* 8408210278	71-6244 71-6244 50-171 50-282	R S		8408020118 8408030145 8408070184 8408090148	50-440 50-440 50-440 50-440	A A S
Chicago, Univ of, Chicago, IL Christic Institute Christy, H	8408310194* 8408060201 8408060224* 8408070382 8408070408	50-454 50-269 50-289 50-269 50-269	T G G G		8408070148 8408070261 8408130393 8408150467 8408220498	50-440 50-440 50-440 50-440 50-440	a
Cincinnati Gas & Electric Co Citizens Against Nuclear Power Citizens Association for Bound Energy	8408140479 8408070461 8408100110 8408090200 8408090200	50-287 50-358 50-295 50-445 50-445	G G F G G		840820502 8408270320 8408280131* 8408280131* 8408300054	50-440 50-440 50-440 50-440 50-440	G
	8408070206* 8408070206* 8408070408 8408070408 8408070420*	50-445 50-445 50-445 50-445 50-445	0 0 0 0	Caslition for Responsible Energy Education Coffey County, KS Cohen, D.A. MD Colorado, State of	8408270350 8408020117* 8408140377 8408230253 8408230253	PR 50-482 PR State F	Prog
	8408070420* 8408070426* 8408070426* 8408070434*	50-445 50-445 50-445 50-445	0 0 0	Colt Industries, Inc Combustion Engineering, Inc	8408230239 8408200307 8408010247* 8408010236*	50-352 50-361 50-361	8 P

AUTHOR AFF1L (AT LON	ACCESSION NUMBER	SUBJECT CATEGOR	₹Y	AUTHOR AF# ILIATION	 ACCESSION NUMBER	SUBJECT	
	8408020031 8408020205 8408020207* 8408100137* 8408140230	50-317 70-36 70-36 50-528 50-470	P A E	 	8408100040* 8408100119* 8408130108* 8408130108* 8408130146	50-454 50-454 50-454 50-454 50-249	T G G
	8408140390 8408210183 8408210190* 8408210197* 8408270412*	50-470 70-36 70-36 70-36 50-361	A P		8408130231 8408130231 8408130231 8408130231 8408130231	50-454 50-454 50-454 50-454 50-454	8 8 8 8
	8408270412* 8408270416* 8408270416* 8408270418* 8408270418*	50-361 50-361 50-361 50-361 50-361	P P P P		8408130271 8408130271 8408130330 8408130405 8408130409	50-237 50-237 50-237 50-304 50-434	8 8 9
ommerce, Dept of, ommerce, Dept of, Natl Oceanographic & Atmospheric Administration	8408310368* 8408160454	CONTRACT 50-354	Д		8408130413# 8408130415 8408130456 8408130604	50-10 50-454 50-304 50-295	F 0 5 8
ommittee to Bridge the Gap	8408230506* 8408290005 8408070386	CONTRACT 50-354 50-142	D G		8408140028 8408140028 8408140034*	50-456 50-456 50-456	G G
ommanwealth Edison Co	8408070474 8408310152 8403250241 8407100002 8408010165	50-142 50-142 50-454 50-456 50-295	G P G S F		8408140034* 8408140036* 8408140038*	50-454 50-454 50-456 50-237	0 0 F
	8408010165 8408010171* 8408010171* 8408030252*	50-295 50-295 50-295 50-10	F F Q		8408140139 8408140139 8408140139 8408140139 8408140139	50-237 50-237 50-237 50-237	۲ ۲ ۲
	8408040042 8408040055 8408040043 8408040045 8408040071	50-374 50-373 50-373 50-254 50-249	8 8 8 9		8408140169* 8408140179 8408140179 8408140180* 8408140190*	50-374 50-373 50-373 50-374 50-374	0 F 0
	8408040085 8408040085 8408040100 8408040101*	50-373 50-373 50-237 50-373	0 Q S F		8408140234 8408140234 8408140241* 8408140317 8408140323	50-454 50-454 50-454 50-254 50-373	F Q P
	8408060101* 8408060107 8408060108 8408060136 8408060144	50-373 50-374 50-254 50-454 50-374	F S Q A P		8408140323 8408140365 8408140371 8408140371	50-373 50-254 50-454 50-454	P F E
	8408040145 8408040145 8408040153* 8408040153*	50-373 50-373 50-373 50-373	Р Р		8408140371 8408140371 8408140372 8408140372	50-454 50-237 50-237	E
	8408040148 8408040203 8408040207 8408040227	50-374 50-237 50-373 50-374	P 9 8		8408140372 8408140372 8408140372 8408140372	50-237 50-237 50-237 50-237	<b>&gt;</b>
	8408040251 8408040255 8408040274 8408040274	50-265 50-373 50-237 50-237	S S P P		8408140372 8408140380 8408140380	50-237 50-454 50-454 50-454	V A A
	8408060280* 8408060280* 8408060283 8408060290	50-237 50-237 50-374 50-304 50-237	P 9 9 9		8408140380 8408140380 8408140386 8408140386	50-454 50-454 50-456 50-456	A A A
	8408060293 8408070212* 8408070239 8408070239 8408070240	50-257 50-295 50-295 50-295	Q F F F		8408140387* 8408140387* 8408140387* 8408140387* 8408140387*	50-237 50-237 50-237 50-237 50-237	55555
	8408070240 8408070391 8408070490 8408080198	50-295 50-374 50-374 50-454 50-454	F 8 5 F		8408140397 8408140405 8408140428 8408140428 8408150098	50-237 50-374 50-295 50-295 50-237	F P F G
	8408080198 8408080198 8408080198 8408080198 8408080205#	50-454 50-454 50-454 50-454	F F F F		8408150098 8408150098 8408150098 8408150098	50-237 50-237 50-237 50-237	9
	8408080205* 8408080205* 8408080205* 8408080205* 8408090047	50-454 50-454 50-454 50-454 50-304	F F F B		8408150078 8408150078 8408150078 8408150078	50-237 50-237 50-237 50-237 50-237	9 9
	8408090052 8408090151 8408090324 8408090326 8408090404 8408100015	50-237 50-237 50-373 50-304 50-275 50-275	5 5 5 5 5 6 7		8408150098 8408150098 8408150098 8408150113 8408160122 8408160122	50-237 50-237 50-237 50-237 50-275 50-275	G G P R R

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8408160140 8408160140 8408160145# 8408160150 8408160345	50-373 50-373 50-10 50-295 50-237	R R G S P		8406240218 8408270087 8408270113 8408270114 8408270114	50-237 50-295 50-454 50-237 50-237	Б О А Р
	8408140345 8408140345 8408140344 8408140344 8408140387	50-237 50-237 50-373 50-373 50-373	<u>፡</u>		8408270114 8408270118 8408270118 8408270163 8408270172*	50-237 50-454 50-454 50~454 50-454	P A G G
	8408160387 8408160415 8408160415 8408170069 8408170398	50-373 50~454 50-454 50-454 50-275	P A A A		8408270204 8408270218 8408270218 8408270265 8408270358	50-454 50-454 50-454 50-454 50-373	E F E F
	8408170398 8408170399* 8408170399* 8408200323 8408200331	50-295 50-295 50-295 50-373 50-237	F F S Q		8408270362* 8408270372 8408270373 8408270373 8408270373	50-373 50-295 50-454 50-454 50-454	F P E E
	8408200331 8408200331 8408200331 8408200331 8408200331	50-237 50-237 50-237 50-237 50-237	0 . 0 0 0		8408270455 8408280117 8408280274 8408290038 8408300044	50-247 50-275 50-454 50-10 30-456	8 9 J
	8408200331 1820028048 1820028048 1820028048 18200281	50-237 50-237 50-237 50-237 50-237	G G G G		8408300044 840830053 840830053 840830053 840830053	50-454 50-454 50-454 50-454 50-454	8 K K K
	8408200331 8408200331 6408200458* 6408200458* 6408200501	50-237 50-237 50-454 50-454 50-10	0 T T B		1408300053 8408300073 8408300136 8408300214 8408300214	50-454 50-275 50-275 50-454 50-454	8 R S S
	8408200519 8408200526 6408200547 8408210068 8408210068	50-247 50-373 50-304 50-254 50-254	8 8 8 R R		8408300299 8408300299 8408300308* 8408300329* 8408300336*	50-254 50-254 50-254 50-254 50-254	R R R R
	8408210104 8408210203* 8408210336 8408210336 8408210344*	50-249 50-374 50-454 50-454 50-454	S Q G G		8408300368 8408300388 840830380 840830393* 840830308	50-10 50-373 50-373 50-373 50-373	R R R R
	8408210344* 8408210358* 8408210358* 8408220079 8408220079	50-454 50-454 50-454 50-454 50-454	0 G G G		8408300508 8408300513* 8408300516* 8408310047 8408310053	50-373 50-373 50-373 50-373 50-374	R R S S
	8408220079 8408220079 8408220079 8408220086 8408220106	50-454 50-454 50-454 50-275 50-454	G G G G F		8408310063 8408310067 8408310071 8408310115 8408310163	50-237 50-237 50-249 50-304 50-454	8 8 P A
	8408220106 8408220112* 8408220237 8408220237 8408220237	50-454 50-454 50-454 50-454 50-454	F A A		8408310168 8408310200 8408310202 8408310203	50-295 50-295 50-295 50-254 50-254	F P P P
	8408220239 8408220239 8408220306 8408220306 8408220306	50-454 50-454 50-454 50-454 50-454	A A E E E		8408310204 * 8408310204 * 8408310211 8408310211		5 5 5 5 5
	8408220306 8408220306 8408220348 8408220348 8408230270	50-454 50-454 50-454 50-454 50-254	E A A F	Concerned Citizens of Louisa County, VA Confederated Tribes of Unatilla Indian Reservation	8408310226 8408310233 8408010250 8408010114	50-454 50-373 50-338 WABTE MG]	
	8408230283 8408230435 8408230435 8408230496 8408230514	50-10 50-254 50-254 50-254 50-275	F R R S	Connecticut Yankes Atumic Power Co	8408070321 8408070180 8408100063 8408100116 8408160388 8408210480	50-213 50-213 50-213 50-213 50-213 50-213	HOPOFO
	8408230524 8408230533 8408240042 8408240044 8408240137	50-374 50-374 50-275 50-374 50-454	8 8 8		8408220222 8408230482 8408290298 8408300135 8408310107	50-213 50-213 50-213 50-213 50-213	0 8 P P
	8408240139 8408240173 8408240173 8408240179 8408240176	50-454 50-454 50-454 50-374 50-454	F F 8 Q	Conner & Wetterhahn	8408310187 8408310187 8408010244 8408010255	50-213 50-213 50-354 50-352	F

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	łY	AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO	ΥF
	8408060053 8408060053 8408060182 8408060182 8408060228	50-352 50-352 50-352 50-352 50-352	G G G G		8408030116* 8408030150 8408030151* 8408030152* 8408040115*	50-155 50-255 50-255 50-255 50-155	P P Q
	8408040228 8408070287 8408070287 8408070291* 8408070291*	50-352 50-352 50-352 50-352 50-352	e e e e		8408040263 8408070180* 8408070183 8408070183 8408070227	50-255 50-327 50-327 50-327 50-327	S G G
	8408070350 8408070350 8408070363 8408070363 8408070372	50-352 50-352 50-352 50-352 50-352	G G G		8408070227 8408070431 8408070435 8408070438* 8408070441*	50-329 50-255 50-255 50-255 50-255	0 P P F
	8408070372 8408070412 8408070412 8408070429 8408070429	50-352 50-352 50-352 50-352 50-352	G G G G		8408080224 8408080331 8408090032 8408090166 8408090171*	50-155 50-255 50-325 50-155 50-155	9 8 P P
	8408070444 8408070444 8408070461 8408070495	50-352 50-352 50-358 50-352 50-352	G O O O		8408070284 8408070284 8408070327* 8408070378 8408100134	50-329 50-329 50-155 50-255 50-255	8 9 8 9
	8408080019 8408080389 8408080399 8408080399 8408080404	50-354 50-354 50-352 50-352 50-352	D G G G		8408100138* 8408130227* 8408130227* 8408130235* 8408130255*	50-255 50-329 50-329 50-329 50-329	P
	8408080404 8408130398 8408150387 8408150477 8408240236	50-352 PR 50-352 50-352 50-352	G G G		8408130290+ 8408130348* 8408130353 8408130376* 8408140031*	50-329 50-329 50-255 50-155 50-400	A F F
	8408240236 8408240241 8408240241 8408240254 8408240254	50-352 50-352 50-352 50-352 50-352	6 0 6 T T		8408140050* 8408140055* 8408140059* 8408140263* 8408140275	50-329 50-329 50-329 50-329 50-255	A A A F
	8408240256 8408240256 8408280223 8408280388 8408280448	50-352 50-352 50-354 50-352 50-354	0 0 0 0		8408140388 8408140553* 8408140562* 8408140573* 8408150577*	50-255 50-329 50-329 50-329 50-329	P A A A
Conservation Council of North Carolina Conselzdated Edison Co. of New York, Inc	8408310223 8408070495 8408020138 8408040349 8408040349	50-352 50-400 50-247 50-3 50-3	Q Q P F F		8408150577* 8408150586* 8408150608* 8408150635* 8408150644*	50-329 50-329 50-329 50-329 50-329	A A A Q
	8408070114 8408070421 8408070423 8408130211 8408130325	50-247 50-247 50-247 50-247 50-247	F		84081 50644* 84081 50651 * 84081 50652* 84081 50662* 84081 50667*	50-329 50-329 50-329 50-329 50-329	G A A G
	8408130368* 8408140473 8408140473 8408150121 8408150121	50-247 50-247 50-247 50-3 50-3	9 9 F F		8408150672* 8408150672* 8408150685* 8408150712* 8408150712*	50-329 50-329 50-329 50-329 50-329	G A A
	8408150125* 8408170270 8408170270 8408200309 8408200539	50-3 50-247 50-247 50-247 50-247	F Q Q Q S		8408150716* 8408150718* 8408150718* 8408150735* 8408150738*	50-329 50-329 50-329 50-329 50-329	A A A A
Construction Technology Laboratories	8408210002 8408220214 8408240164 8408270279 8408150678*	50-247 50-247 50-247 50-247 50-329	F 9 Q A		8408150747* 8408160181 8408160255 8408160279 8408170081*	50-327 50-155 50-255 50-255 50-327	A R B A
Construction Technology Laboratories  Consumers Power Co	8408010147* 8408010149* 8408010163* 8408010260 8408010263*	50-329 50-329 50-329 50-355 50-155	0 A 0 9		8408170102* 8408170187* 8408170195* 8408170279* 8408170358*	50-329 50-329 50-329 50-329 50-329	A A A A
	8408010269* 8408020014 8408020014 8408020015 8408020015	50-155 50-329 50-329 50-329 50-329	g A A A		8408170364 8408170365* 8408170367* 8408170367* 8408170372*	50-255 50-329 50-329 50-329 50-329	F A A A
	8408020106 8408020122* 8408030064* 8408030109 8408030113*	NUREG 50-329 50-329 50-155 50-155	A A P P		8408170374* 8408170374* 8408170377* 8408170377* 8408210287	50-327 50-327 50-327 50-327 50-155	K A A P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408210454* 8408210498 8408220059* 8408220059* 8408230201	50-327 E 50-155 F 50-327 Q 50-327 Q 50-255 P		8408080516 8408090055 8408090062 8408090071 8408130163*	50-341 S 50-341 S 50-341 S 50-341 S 50-341 Q
	8408230239 8408240161 8408270127 8408270130 8408270281*	50-155 S 50-255 P 50-255 S 50-255 S 50-255 Q		8408140014 8408160444 8408160474 8408210079 8408210085*	50-341 S 50-341 S 50-341 A 50-341 A 50-341 A
	8408270330* 8408270372* 8408280003* 8408270067 8408270251	50-329 Q 50-155 Q 50-255 Q 50-155 S 50-155 S		8408220135 8408220175 8408220193 8408220209 8408230274	50-341 8 50-341 8 50-341 8 50-341 8 50-341 F
	8408300986 8408310054 8408310054 8408310056 8408310059	50-155 B 50-329 S 50-329 S 50-255 S 50-255 S		8408230274 8408230301 * 8408230387 8408230391 * 8408270352*	50-341 E 50-341 E 50-341 F 50-341 F 50-341 Q
Containment Issues Owners Group	8408310141 8408310145* 8408310259 8408310259 8408210376	50-255 Q 50-255 Q 50-329 S 50-329 S TOPREP		8408300045 8408300061 8408300069 8408300209 8408300216	50-341 8 50-341 8 50-341 9 50-341 6 50-341 6
CorSTAR Research, Inc Corn Belt Power Cooperative Covington & Burling	8408210382* 8408240271 8408210272* 8408070482 8408080235	TDPREP Wabte Mana 50-331 I 40-2061 40-2061		6408300223 6408300251 6408300257 6408310166 6408310171*	50-341 8 50-341 8 50-341 8 50-341 F 50-341 F
Crawford Fitting Co Creare, Inc Critical Mass Energy Project Crystal River, FL Dairyland Power Cooperative	8408240313 8408210382* 8408030282* 8408200606* 8408060004	50-327 8 TOPREP MISC CONTRACT 50-409 G	Detroit, MI Doberty, JF Domus Design Studios, Inc Don L Warner, Inc	8408220343 8408140419 8408220400* 8408220404* 8408020161	PR PR CONTRACT CONTRACT 40-8027
	8408140287 8408150212 8408160186 8408160307 8408210333	50-407 P 50-407 P 50-407 S 50-407 S 50-407 F	Dougherty, JB Dr W J Hall Duke Power Co	8408010250 8408140174* 8405270062 8405270062 8405270062	50-338
	8408220105 8408220190 8408270080 8408270294* 8408310174	50-409 F 50-409 R 50-409 P 50-409 G 50-409 P		8405290179 8405290179 8405290179 8408020060 8408020060	50-204 S 50-204 S 50-206 S 50-413 0 50-413 G
Dames & Moore  Data Consultants, Inc	8408310179* 8408060252 8408090072* 8408150149* 8408270576*	50-409 P WASTE MGT 50-429 A WASTE MGT CONTRACT		8408020066* 8408020066* 8408030130 8408030135*	50-413 0 50-413 9 50-367 P 50-367 P 50-367 P
Dauphin County, PA Dayton X-Ray Co	84081 40449 84081 50122 84081 50122 84081 50122 84081 50507	50-219		8408030135* 8408060035 8408060035 8408060050 8408060072	50-369 P 50-413 0 50-413 0 50-206 8 50-413 A
DeKalb Area Alliance for Responsible Energy	8408150607 8408150607 8408010177	71-6717 71-6717 30-454 G		8408060097 8408060102 8408060102 8408060102 8408060104*	50-413 P 50-206 B 50-206 B 50-206 B 50-413 P
Dal-Aware Unlimited, Inc	8408010181 8408010181 9760808048 8408170319 8408010803	50-454 G 50-454 G 50-454 T 50-352 G		8408060117 8408060119# 8408060324 8408060324 8408070263	50-413 P 50-413 P 50-206 S 50-206 E 50-413 P
	8408010228 8408010228* 8408010228* 8408010248 8408070226	50-352 0 50-352 0 50-352 0 50-352 0		8408070263 8408070298 8408070322 8408070351 8408070351	50-413 P 50-369 F 50-413 F 50-413 F 50-413 F
Delaware Solid Waste Authority Delaware, Stats of	8408130368 8408140484 8408140403 8408100003 8408070284	50-352		8408070445 8408070445 8408070468 8408070487 8408080275	50-413 8 50-413 8 50-369 P 50-413 F 50-413 E
Detroit Edison Co	8408010037 8408010216 8408020029 8408060082 8408070336*	50-341 A 50-341 E 50-341 K 50-341 G		8408080275 8408080337 8408080337 8408090007 8408090007	50-413 E 50-413 Q 50-413 F 50-413 F
	8408070440 8408080299 8408080302* 8408080303 8408080511	50-341 A 50-341 F 50-341 F 50-341 B		8408090274 8408090278 8408090278 8408130169 8408140103	50-370 S 50-413 S 50-413 S 50-369 P 50-413 0

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJE	)RY	AVTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC.	
	6408140103 8408140110* 8408140110* 8408140115*	50-413 50-413 50-413 50-413 50-413	G G G		8408270259* 8408270339 8408270339 8408270339 8408270345*	50-369 50-269 50-269 50-269 50-269	0 Р Р
	8408140430 8408140430 8408150221 8408150326 8408150335*	50-413 50-413 50-369 50-269 50-269	Р 9 5 F		8408270345* 8408270345* 8408270391 8408270391 8408280205	50-249 50-249 50-413 50-413 50-413	9 9 0 0 T
	84081 60050 84081 60121 84081 60159 84081 60174 84081 60174	50~369 50-413 50~413 50~369 50-369	P G S P P		8408280230 8408280234 8408280234 8408280241 8408280281	50-369 50-369 50-369 50-269 50-413	0 0 0 P
	8408160183 8408160183 8408160394 8408160394 8408160394	50-413 50-413 50-206 50-206 50-206	5 5 5 5		8408280372 8408280372 8408280377* 8408280377* 8408280389	50-413 50-413 50-413 50-413 50-369	F F 8
	8408160395 8408160395 8408160395 8408160417 8408160429	50-206 50-206 50-206 50-269 50-413	8 8 8		8408280476* 8408290094 8408290179 8408300014 8408300014	50-249 50-370 50-204 50-269 50-269	0 8 F F
	8408160429 8408160468 8408160517 8408160517 8408170329	50-413 50-413 50-413 50-413 50-269	8 8 8		8408300014 8408300014 8408300014 8408300014 8408300014	50-269 50-269 50-269 50-269 50-269	F F F F
	8408170329 8408170329 8408200059 8408200059 8408200059	50-269 50-269 50-269 50-269 50-269	ե ե ե		8408300021 * 8408300021 * 8408300021 * 8408300021 *	50-269 50-269 50-269 50-269 50-269	F F F F
	8408200069* 8408200069* 8408200069* 8408200100 8408200149	50-269 50-269 50-269 50-369 50-269	Р Р F Р		8408300021* 8408300021* 8408300021* 8408300028* 8408300028*	50-249 50-269 50-269 50-269 50-269	7 7 7
	8408200149 8408200155* 8408200155* 8408200155*	50-269 50-269 50-269 50-269	9 9 9 9		8408300028* 8408300028* 8408300028* 8408300028* 8408300028*	50-269 50-269 50-269 50-269 50-269	F F F
	8408210362 8408210365 8408210365 8408210396 8408220091	50-413 50-413 50-413 50-367 50-269	р Р Р Р		8408300028* 8408300406 8408300497 8408300501 8408300507	50-249 50-413 50-267 50-413 50-370	F 8 8
	8408220201 8408220201 8408220208* 8408220208*	50-267 50-267 50-267 50-267 50-267	K K K	Duqueane Light Ca	8408310121 8408010154 8408010156* 8408020011 8408020019	50-269 50-412 50-412 50-412 50-412	F F E
	8408220208* 8408220272 8408220272 8408220272 8408220303	50-269 50-269 50-269 50-269 50-413	К Р Р		8408060259 8408070355* 8408070414 8408070432 8408100092	50-412 50-412 50-412 50-412 50-334	8 0 F E 8
	8408220303 8408220347 8408220465 8408220465 8408220468	50-413 50-413 50-369 50-369 50-269	и В В В		8408100113 8408130005 8408130312 8408130436 8408130437*	50-334 50-412 50-412 50-334 50-334	8 E P P
	8408230051 8408230527 8408230527 8408230527 8408230527	50-413 50-269 50-269 50-269 50-269	Р Р Р		8408130441* 8408140088 8408140127 8408150124 8408150199	50-334 50-412 50-412 50-334 50-412	P E P E
	8408230327 8408230527 8408240224 8408240224 8408240224	50-249 50-249 50-413 50-413 50-413	Р І І І		8408150499 8408160333 8408160399 8408210016 8408210023	50-334 50-412 50-412 50-334 50-334	8 E E E
	8408240242* 8408240242* 8408240242* 8408240242* 8408270160	50-413 50-413 50-413 50-413 50-247	I I I I P		8408210437 8408210476 8408230246 8408230299 8408230329	50-412 50-412 50-412 50-334 50-412	A A G E
	8408270160 8408270160 8408270169* 8408270169*	50-249 50-249 50-249 50-249 50-269	P P P		8408240275 8408270071 8408270141 8408270165 8408270341*	50-412 50-412 50-412 50-412 50-334	Q P E Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Durham, NH	8408280200 8408290222 8408290336 8408310208 8408140436	50-412 E 50-412 E 50-412 A 50-412 F 50-443 G		8408200430 8408200435 8408200437 8408200504 8408200514	WASTE MGT WASTE MGT WASTE MGT WASTE MGT
E C Rodabaugh Associates. Inc E I du Pant de Nemours & Co , inc	8408130041 8408270582* 8408310025* 8408310303 8408310446	NUREG CONTRACT XPORTLIC XPORTLIC XPORTLIC		8408200517 8408210038 8408210171 8408220122 8408220215	WASTE MGT WASTE MGT WASTE MGT WASTE MGT
EA Engineering, Science & Technology, Inc EG&G. Inc	8408070334 8405210578 8405210579 8408010027* 8408090019*	50-287 R NUREG NUREG 50-278 P 50-397 G		8408220223 8408220227 8408220232 8408220234 8408230043*	WASTE MGT WASTE MGT WASTE MGT WASTE MGT
	8408130455* 8408160248 8408240377 8408240382 8408300060*	50-445 A 50-269 P NUREG NUREG 50-263 Q		8408230469 8408240211 8408240354 8408240355* 8408270250	XPORTLIC 40-1341 Waste Mgt Waste Mgt Waste Mgt
EarthFax Engineering, Inc Ebasco Services, Inc (subs of Enserch Corp )	8408070509 8408030021	40-808 <b>4</b> Ga999		8408270319 8408290350* 8408290352* 8408310005*	PR COMMISSION COMMISSION XPORTLIC
	8408070273 8408070273 8408080051 8408080257 8408140027* 8408140031*	30-445 T 30-445 T 30-445 T 50-445 T 50-400 T 50-400 T	Engineering Planning & Management, Inc Engineers International, Inc	8408310270 8408310273 8408310335* 8408310339* 8408170327* 8408240221	WASTE MGT WASTE MGT WASTE MGT S0-315 F WASTE MANA
Eberling Instrument Corp Eddleman, W	8408310337 8408030070 8408070459 8408140002 8408140119	SPORTLIC SO-400 G SO-400 G SO-400 G SO-400 G	Environmental Protection Agency	8408160264* 8408160292* 8408210205 8408210326 8408220151	DRG DRG 50~354 D 50~354 D 50~456 D
Edison Electric Institute	8408140122* 8408140123* 8408160105 8408200498 8408070457*	50-400	Essex Corp European Communities, Cormission of Everest Minerals Corp	B40B170056* B40B230464 B40B2B001B 840B2B0022* B40B2B0024*	50-354 F XPORTLIC 40-8857 40-8857 40-8857
Edlow International Co Elgar Corp End Nuclear Dumping in the Pacific Energy Fuels Nuclear, Inc	8408310307 8408310180 8408220343 8408080144 8408240393 8408280010	XPQRTLIC XPQRTLIC PR 40-8681 40-8681 40-8675	Extran, Inc	8408280366* 8408280373* 8408280378* 8408280380* 8408280381*	50-295 P 50-295 P 50-295 P 50-295 P 50-295 P
Energy, Dept of	8408280012* 8408280110 8408290216 8408290366 8408010046	40-8675 40-8675 40-8681 40-8681 WASTE MOT	Exxon Corp Exxon Nuclear Co , Inc (subs of Exxon Corp )	8408260411* 8408280422* 8408280430* 8408040297 8407300143	50-295 P 50-295 P 50-295 P 40-8102 TOPREP
	8408010053* 8408010063* 8408010064 8408010072* 8408030082 8408030084	WASTE MOT  TOM STEAM  TOM STEAM  TOM STEAM  TOM STEAM  TOM STEAM  TOM STEAM  TOM STEAM		840809019B 8408090209* 8408090230 8408140191 8408140363*	50-316 P 50-316 P TOPREP TOPREP 50-261 P
	8408030092 8408030187 8408030263 8408030279 8408030283	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT		8408230103* 8408230122* 8408230263 8408230264	TOPREP 50-261 P 50-261 P 50-315 P 50-315 P
	8408060059 8408060067 8408060106 8408060111* 8408060122*	WASTE MGT WASTE MGT WASTE MGT WASTE MGT		8408240268 8408240309 8408280122 8408280212 8408310195	TOPREP 50-261 P TOPREP TOPREP TOPREP
	8408060264 8408070063 8408080013 8408070303* 8408130116	WASTE MOT WASTE MOT XFORTLIC WASTE MOT WASTE MOT	Failure Analysis Associates	8405270075* 8405270075* 8405270075* 8405270075* 8405270075*	50-206 S 50-206 S 50-206 S 50-206 S 50-206 S
	8408130137 8408150144 8408150193 8408150363 8408150365	WASTE MGT WASTE MGT 40-6500 WASTE MGT WASTE MGT		8405270075* 8405270271* 8408060387* 8408060387* 8408060387*	50-204 8 50-206 S 50-206 B 50-206 B 50-206 S
	8408150400 8408150403 8408150419 6408150531 8408150542	WASTE MOT WASTE MOT WASTE MOT WASTE MOT 71-6346		84080.60387* 84080.60387* 84081.60397* 84081.60397* 84081.60397*	50-206 S 50-206 S 50-206 B 50-206 S 50-206 S
	8408160278 8408160283* 8408160289	WASTE MOT WASTE MOT WASTE MOT		8408160397# 8408160397# 8408160403* 8408210370*	50-206 S 50-206 S 50-206 S 50-413 P

AUTHOR AFF (LIATION	ACCESSION NUMBER	SUBJE		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
Fauske & Associates, Inc Federal Emergency Management Agency	8408230112* 8404040169 8404040172* 8405240290 8408070427	50-327 50-10 50-10 50-3 50-322	P F F G		8408270019 8408270200* 8408270203 8408270298* 8408270316*	50-250 50-335 50-250 50-335 50-250	P G G
	8408080138 8408080141* 8408090042 8408090056 8408090059*	50-416 50-416 50-413 50-247 50-247	F F F		8408270344 8408270344 8408270384 8408280058 8408280077	50-250 50-250 50-250 50-335 50-335	P Q Q F
	8408070059* 8408070061* 8408070061* 8408100060 8408130373	50-247 50-247 50-247 50-295 50-322	취 무 뭐 지		8408280106 8408280182 8408280236 8408280238 8408280238	50-389 50-335 50-335 50-250 50-250	G G P P
	8408150443 8408200497* 8408210346 8408210354* 8408210408	50-322 50-400 50-302 50-302 50-272	0 6 F F	Florida Power Corp	8408310133 8408310145 8408020010 8408020018* 8408060199	50-250 50-389 50-302 50-302 50-302	F P P P
	8408210408 8408270206* 8408270356 8408270357* 8408300211*	50-272 50-266 COMMISS COMMISS 50-302			8408060304 8408080189 8408160238 8408160247 8408160410	50-302 50-302 50-302 50-302	9 8 8
Florida Power & Light Co	8408300317* 8408300323* 8407260218 8407260220* 8408010311	50-324 50-324 50-250 50-250 50-251	F K K B		8408160526 8408200278 8408200311 8408200330 8408200346	50-302 50-302 50-302 50-302 50-302	R P F P S
	8408020123 8408030164 8408030235 8408030237 8408080230	50-389 50-335 50-335 50-250 50-250	F B B S		8408230424 8408230430 8408240155 8408270211* 8408280047*	50-302 50-302 50-302 50-302 50-302	8 F 0
	8408090009 8408090009 8408090096 8408090243 8408090397	50-335 50-335 50-389 50-335 50-250	F F P O	Florida, Univ of, Gainesville, FL Franklin Institute/Franklin Research Center	8408280170 8408280170 8408300341 8408130261 8103130143*	50-302 50-302 50-302 70-1068 50-293	Р G В
	8408070377 8408070437 8408070437 8408100016 8408100016	50-250 50-250 50-250 50-250 50-250	G G F F	••••	8204150347* 8307010039* 8404040095* 8404040095* 8404040098*	50-293 50-277 50-388 50-388 50-388	P C U U
	8408100016 8408100016 8408100016 8408100054* 8408100054*	50-250 50-250 50-250 50-250 50-250	ፑ F F #	Friends of the Earth	8404040098* 8407090037* 8407300136* 8408280321* 8408080191	50-388 50-219 50-213 50-346 50-352	P P
	8408100034* 8408100034* 8408100034* 8408130215 8408130215	50-250 50-250 50-250 50-335 50-335	F F F F	GA Technologies, Inc /General Atomic Co	8408280491 8408310094 8405310247 8408020253 8408020256*	50-352 50-352 PR 70-734 70-734	G G
	8408140214 8408140214 8408140220# 8408140220# 8408140226#	50-250 50-250 50-250 50-250 50-250	0 0 0	General Electric Co	8408150109 8408270311 8312020299* 8405300761 8405300762*	71-6346 50-89 50-354 70-1113 70-1113	F
	8408140236* 8408140236* 8408140233* 8408140233* 8408140262*	50-250 50-250 50-250 50-250 50-250	0 0 0 0		8405300743* 8408090335* 8408090337* 8408130033	70-1113 50-73 50-73 70-1306 50-331	P P
	8408140242* 8408140271* 8408140271* 8408140277* 8408140277*	50-250 50-250 50-250 50-250 50-250	0 0 0 0		8408150084 8408160377 8408160384* 8408160390* 8408160466*	TOPREP TOPREP TOPREP 50-458 70-1308	A
	8408160521 8408170054 8408170084 8408170233 8408170237#	50-250 50-389 50-250 50-335 50-335	В Р Q Q		8408160472* 8408170262* 8408170339* 8408170342* 8408230209	70-1308 50-263 50-354 50-354 50-447	P G G A
	8408200143 8408200200 8408200273 8408210347 8408210347	50-389 50-389 50-250 50-250 50-250	P B Q Q		8408230468 8408230513 8408240122 8408240348 8408270155	XPORTLIC XPORTLIC TOPREP 50-155 50-447	
	8408210380 8408210380 8408210441 8408230155* 8408270015	20-520 20-521 20-520 20-520 20-520	9 9 H Q P		8408270175# 8408280111 8408280209# 8408280211#	50-331 70-1113 50-331 50-331	P P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
General Public Utilities - OPV Service Corp	8408310140 8408310184 8408010293 8408010329*	50-373 50-219 50-219 50-320	S S S		8408130412 8408130561 8408130561 8408130567* 8408130567*	50-424 50-321 50-321 50-321 50-321	A P P P
	8408010331* 8408020137 8408020141* 8408030006 8408030089	50-320 50-289 50-289 50-289	P K F F		8408140106 8408140106 84081401 <b>24</b> 8408140124* 8408150242	50-321 50-321 50-321 50-321 50-366	P P P
	8408030107* 8408030108* 8408030141 8408060142* 8408060166 8408060310	50-289 50-289 50-320 50-219 50-320 50-320	G G F G F G F		8408150494 8408170258 8408170258 8408170301 8408200001	50-424 50-321 50-321 50-424 50-321	A F A R
	8408070152 8408070203 8408070238 8408070280 8408070300	50-219 50-320 50-289 50-289 50-219	P Q P P		8408200001 8408200438 8408210175 8408210235* 8408210357	50~321 50~366 50~366 50~366 50~321	8 9 P P
	8408070306* 8408070348 8408070454 8408080300 8408080498	50-219 50-219 50-219 50-289 50-219	P P Q		9408210357 9406210416 8408210472 9408210472 9408210472	50-321 REOGD 50-321 50-321 50-321	P F F
	8408070100 8408070144 8408070250 8408070257* 8408070334	50-320 50-289 50-219 50-219 50-289	F B P P		8408210474 8408220491 8408230251 8408230251 8408230251	50-321 50-346 50-321 50-321 50-424	P 8 P Q
	8408100130 8408130191 8408130218 8408130343 8408140197	50-320 50-219 50-289 50-289 50-320	a F P P		9408270227 9408270247* 9408270301 9408270430* 9408280183	50-321 50-321 50-321 50-424 50-366	9 6 6
	8408140279 8408140406 8408140411 8408140415* 8408160035	50-320 50-289 50-289 50-289 50-320	Р Р		8408280208 8408280208 8408280213* 8408280213* 8408280233	50-424 50-424 50-424 50-424 50-321	A A A F
	8408140182 8408200115 8408210320 8408220218 8408220354	50-289 50-320 50-320 50-289 50-219	8 F P		8408280239 8408300024 8408300024 8408300072 8408300115	50-321 50-321 50-321 50-321 50-366	G P P I
	8408220363 8408220365* 8408220375 8408230098* 8408230101*	50-289 50-289 50-219 50-219 50-219	P P G	Qeotechnical Engineers, Inc	8408300333 8408300346* 8408300517 8210130322* 8305270222*	50-321 50-424 50-366 50-329 50-329	8 9 8 A
	8408230382 8408230382 8408240066 8408240167 8408240225	50-287 50-287 50-287 50-287 50-320	F F R P H		8408020181* 8408140185* 8408140185* 8408140196* 8408140196*	50-329 50-329 50-329 50-329 50-329	A A A
	8408240257* 8408270145 8408270195 8408270285 8408270285	50-219 50-289 50-289 50-219 50-219	0 0 S P	Gerard Kluyskens Co , Inc Gesellschaft fuer Nuklear Service, mbH	9409140296# 9409140300# 9409210094 9408090562 9409090564#	50-329 50-329 XPDRTL IC PROJ PROJ	Ā
	8408270381 8408280074 8408280178 8408280179 8408300031	50-219 50-320 50-289 50-289 50-320	P OP F P	Gibbs & Hill, Inc (subs of Dravo Corp ) i Gibert/Commonwealth, Inc (formerly Gibert Associates, Inc.)	8408240336 8408240346 8408070170 8408220332	40-6659 40-6659 GA979 NUREG	
	8408300303 8408310128 8408310127 8408310153 8408310164	50-287 50-217 50-320 50-287 50-287	0 P P	Government Accountability Project	8408240370 8408010235 8408010235 8408010237* 8408010237*	WASTE MA 50-275 50-275 50-275 50-275	
Georgia Institute of Technology, Atlanta, QA Georgia Power Co		50-140 50-424 50-321 50-321	F H F		8408020152 8408020152 8408060201 8408060224* 8408070382	50-275 50-275 50-287 50-287 50-289	00000
	8408060003 8408070141 8408070148 8408090023 8408090287	50-424 50-366 50-321 50-424 50-321	F G F S S		8408070408 8408140479 8408170223* 8408170312* 8408220258	50-287 50-287 50-327 50-327 50-287	0 0 T 0
	8408100045 8408100045* 8408130375 8408130375	50-344 50-346 50-321 50-321	P F F	!	8408220263* 8408220366 8408240251 8408270336*	50-287 50-287 50-287 50-327	0 0 0 T

AUTHOR HELLATTUL	ACCESSION NUMBER	SUBJECT CATEGOR	17	AUTHUR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Guild, R	8408310106 8408310207 8408070443 8408200548 8408310205	50-382 50-142 50-413 50-413 50-413	G G G G	House of Rep , Interior , Insulai Affairs	8408200454* 8408280056* 8408080432* 8408200279* 8407100397*	50-352 U 50-322 H 50-416 U 50-367 U 50-413 U
Gulf Nuclear: Inc Gulf States Utilities Co	8408010025 8408010004 8408010012 8408010241 8408020025	71-9163 50-458 50-458 50-458 50-458	5 5 6 5	Houston Lighting & Paver Co	8408010222 8408010222 8408010225* 8408010225* 8408070446	50-498 K 50-498 K 50-498 K 50-498 K 50-498 A
	8408060028 8408060147 8408070520 8408070529 8408080199	50-458 50-458 50-458 50-458 50-458	A E S S		8408080186 8408150387 8408160176 8408210076* 8408210311	50-498 G 50-498 G 50-498 G 50-498 Q 50-498 A
	8408080236 8408080471 8408100068 8408100108 8408140095*	50-458 50-458 50-458 50-458 50-458	5 G G		8408210311 8408210317* 8408210317* 8408210500 8408210500	50-498 A 50-498 A 50-498 A 50-498 A 50-498 A
	8408140340 8408140421 8408140554 8408150152 8408150142	50-458 50-458 50-458 50-458 50-458	E A S S S		8408210503* 8408210503* 8408220130 8408220161 8408240312	50-498 A 50-498 A 50-498 S 50-498 A 50-498 B
	8408150177 8408150308 8408150385 8408150491 8408150704	50-458 50-458 50-458 50-458 50-458	5 5 5 6 8		8408270212 8408270355 8408270355 8408300370 8408300370	50-478 Q 50-478 A 50-478 A 50-478 S 50-478 S
	8408150707 8408160194 8408160242 8408160386 8408160437*	50-458 50-458 50-458 50-458 50-458	9 9 6 A 0	Hunter Corp Hunton & Williams	8408310174* 8408010169 8408010261 8408020024 8408030090	50-454 T 50-322 0 50-322 0 50-322 0 50-322 0
	84082103/6 8408210490 8408220504 8408220505 8408220511	TOPREP 50-458 50-458 50-458 50-458	A 8 8		8408070256 8408070274 8408070399 8408070442 8408070448*	50-322 0 50-322 0 50-322 0 50-322 0 50-322 0
	8408230538 8408240310 8408240404 8408240426 8408280408	50-458 50-458 50-458 50-458 50-458	8 8 9 0 8		8408080408 8408080417 8408080428 8408090218 8408090223*	50-322
	8408280414 8408280416 8408280428 8408280446 8408280458	50-458 50-458 50-458 50-458 50-458	6 8 8 9 8		8408090411 8408090431 8408130347 8408140003 8408150438	50-322 G 50-322 G 50-322 G 50-322 G
	8408300343 8408300494 8408300507 8408310087 8408310172	50-458 50-458 50-458 50-458 50-458	S 8 9 9		8408150464 8408150464 8408150473 8408160100 8408200477	50-338 0 50-338 0 50-322 T 50-322 0 50-338 0
H    Holmes Testing Laboratories, Inc 	B408270276* 8408270284* 8408270292* B408270296* B408240094*	50-454 50-454 50-454 50-454 CONTRACT	E E T		8408200477 8408230231 8408230409 8408280394 8408280433	50-338
Mahnemann Univ Nosp , Philadelphia, PA (formerly Hohnemann Medical Coll & Hosp) Harmon & Wesss	8408040378* 8408040382* 8408070284 8408130374	70-1362 70-1362 PR PR 50-289	o		8408280492 8408290317 8408300124 8408300177 8408300177	50-322
	8408140035 8408140474 8408220362 8408240234	50~289 50-289 50-289 50-443	G G G		8408310197 8408310150 8408310150 8408310218 8408310224	F01A 50-338 0 50-338 6 50-382 6 50-382 0
Harrischfeger Corp Harrisburg, PA	8408240245 8408270359 8408280493 8408150250* 8408150642 8408140449	50-289 50-289 50-289 XPORTLIC XPORTLIC		INTERA Tochnologies, Inc Idaho, Univ. of, Moscow, ID Illinois Power Co	8408080321* 8408280121 8408040364 8408070217 8408070440*	CONTRACT WABTE MANA 50-461 S 50-461 R 50-461 Q
Hatfield Electric Co Hittman Nuclear & Develupment Corp (subs of Hittman Corp)	8408220307 8408310194* 8408080258	50-219 50-289 50-454 71-9092	G T		8408080540 8408100089 8408130238 8408140351 8408270135	50-461 B 50-461 B 50-461 E 50-461 A
Homestake Mining Co House of Rep	8408280345 8408020208 8408070215* 8408070217* 8408130210*	40-8434 50-289 50-416 50-322 50-416	0 H U		8408270318 8408280094 8408300022 8408300076 8408300210	50-461 8 50-461 A 50-461 5 50-461 8 50-461 6

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
Illinois, State of	8408300224 8408070311 8408130329 8408130337# 8408140335	50-461 40-2061 40-2061 40-2061 50-436	S A		8408210499 8408210492* 8408220202 8408230429 8408240105	50-331 50-331	Р Р В П
	8408140376 8408170314 8408170323 8408170383 8408170387#	50-456 50-461 50-461 40-2061 40-2061	A G G		8408240118 8408240124* 8408240172 8408240235* 8408270167	50-331 50-331	P 5 P
Illingis, Univ of, Urbana, IL	8408170389* 8408170396 8408290008 8408290309 8408030276	40-2061 40-2061 40-2061 50-454 50-151	G F	Iowa Wesleyan College, Mt Pleasant, IA	8408270173* 8408280202 8408280206* 8408310228 8408080335	50-331 50-331	P P E
Impell Corp Indian River Community College, Ft Pierce, HI Indiana & Michigan Electric Co	8408300184 8408080522 8408060048*	50-151 WASTE MC CONTRACT		Isham, Lincoln & Deale	8405250241 8408010249 8408010240 8408080224 84081440028	50-454 50-155 50-155	0 T 0 0
THE TANKE TO THE T	8404080109 8404080113* 8408040076 8408040118 8408040118	50-314 50-315 50-315 50-315 50-315	P P F F		8408140028 8408140034* 8408140034* 8408140102* 8408140102*	50~456 50~456 50~456 50~329	G G G A A
	8408050151 8408050348 8408050348 8408070272 8408070272 8408070307	50-316 50-315 50-315 50-315 50-315 50-315	E E E E E E E E E E E E E E E E E E E	Jacobs Engineering Group, Inc Japan, Govt of	8408210336 8408270163 8408060266 8408280112 8405160213		
	8408070307 8408080084 8408080084 8408080536	50-315 50-315 50-315 50-315	F ០ ០ ទ	Johns Hopkins Medicel Institutions, Baltimore, XD Joint Intervanors - Dieblo Canyon	8408150128 8408150179 8408220448# 8408040046		P
	8408100074 8408130307 8408130321 8408140164 8408160127 8408160188	50-316 50-315 50-315 50-316 50-316	F 8 F 8 8 8		84080400217 8408040217 8408040217 8408070297 8408070297 8408130389	50-275 50-275 50-275 50-275	G G G G
	8408160527 8408170322 8408210156 8408210156 8408220486	50-315 50-315 50-315 50-315 50-315	8 F F	Jaint Intervenors - River Dend	8408130369 8408140464 8408140464 8408210210 8408010250	50-275 50-275 50-275 50-275	6 6 6
Industry Degraded Core Rulemaking Program	8408240121 8408240188 8408240188 8408240188 8408230105*	50-314 50-315 50-315 50-315 50-327	ዮ ዮ ፍ ይ	Joint Intervenors - Shearon Harris  KMC, Inc	8408010244 8408030070 8408140478 8408210323 8408220322	50~400 50~400	G G T G
	8408230105* 8408230108* 8408230112* 8408230112* 8408230114*	50-327 50-327 50-327 50-327 50-327	ր թ թ	KM9 Fusion. Inc (Subs of KM9 Industrie s. Inc ) Kansas City Power & Light Kansas Gas / Electric Co	8408150359 8408150341* 8408020088 8408020105 8408030012		FA
Inhelation Toxicology Research Institute		50-327 50-327 50-327 50-327 NUREG	ь Б Б		8408030016* 8408030157 8408100066 8408100075* 8408140001	50-482 50-482 50-482	A A E G
Institute of Auclear Power Operations Interior: Dept of	8408020071 8408020102 8408220310* 8408220315* 8408210213	NUREQ REGGD DRG DRG 50-354	α		8408140020 8408140237 8408140308 8408140337 8408140350	50-482 50-482 50-482	8 9 F A
Interior, Dept of, Durgau of Mines Interior, Dept of, Geological Survey Interstate Amiosite Corp	8408270074 8408270078* 8408200121 8408220238 8408070413	WASTE MO WASTE MO 50-274 WASTE MO PR	PF F		8408160505 8408160514 8408200119 8408200123* 8408220158	50-482 50-482 50-482 50-482	9 8 A A
Iowa Electric Light & Power Co	8408020004 8408020007* 8408030038 8408060001 8408060141	50-331 50-331 50-331 50-331	р Р Р Б		8408220207 8408220217 8408220248 8408220389 8408220479	50-482 50-482 50-482 50-482	6 8 8
_	8408080083 8408130170 8408140247 8408140435 8408150004	50-331 50-331 50-331 50-331 50-331	P P P Q	Kensas State Univ , Manhattan, KS	8408270377 8408280193 8408280435 8408290033 8408310117	50-482 50-482 50-482	A V S F
	8408160261 8408160471 8408210256 8408210263*	50-331 50-331 50-331 50-331	8 1 1	Kansas, State of Kelley Drye & Warren	8408020114* 8408080173 8408080180*		F

AUTHOR AFFILIATION	ACCEBSION NUMBER	SUBJECT Category	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp )	8408220351 8408070294	40-2061 40-2061		8408080423+ 8408080428 8408070218 8408070223+	50-322
Kerr-McGee Corp	B408080235 B408200403 B408020153	40-2061 40-2061 40-8027		8408090411 8408090431	50-322 G
	8408070482 8408150671 8408150675* 8408300322	40-2061 40-8027 40-8027 70-925		8408130347 8408130352* 8408130355* 8408130359*	50-322 G 50-322 G 50-326 G
Kirkpatrick, Lockhart, Hill, Christopher & Phillips	8408010239 8408030074	50-322 G 50-322 G		8408140003 8408150438 8408150473 8408150476*	50-322 9 50-322 9 50-322 T 50-322 T
	8408030084 8408030105 8408070308 8408070424	50-322 G 50-322 G 50-322 G 50-322 G		8408150485* 8408150498* 8408150505*	50-322 T 50-322 T 50-322 T
	8408080338 8408080410 8408140013 8408140466	50-322 0 50-322 0 50-322 T 50-322 9		8408150514* 8408150530* 8408160100	50-322 T 50-322 T 50-322 0
	8408140470 8408140477* 8408140210	50-322 G 50-322 G 50-322 G		8408200328 8408230231 8408230407 8408270226	50-322 A 50-322 0 50-322 C 50-322 A 50-322 G
	8408170315 8408210389 8408230174	50-322 G 50-322 G 50-322 G		8408280187* 8408280374 8408280397* 8408280433	50-322 T 50-322 T 50-322 T 50-322 Q
	8408230199 8408230264 8408280249 8408280405	50-322 0 50-322 0 50-322 0 50-322 0		8408280492 8408290317 8408290486*	50-322 0 50-322 0 50-322 0
Korea Electric Co Kulm: V Lancaster County: PA	8408280471* 8408160407* 8408200455	COMMISSION 50-508 A 50-287 Q		8408300123 8408300124 8408310218 8408310224	50-322 V 50-322 Q 50-322 Q 50-322 Q
Latir Energy Consultants Law Engineering Testing Co	8408130079* 8408130597*	WASTE MGT WASTE MGT CONTRACT WASTE MOT	Los Alamos Scientific Laboratory	8406230301 8408010308* 8408080357	50-317 P 50-151 G NUREO
Lawrence Berkeley Laboratory Lawrence Livermore National Laboratory	8408310344* 8404230171* 8408010155 8408070140* 8408080515*	50-400 F NUREQ WASTE MOT 50-275 G		8408080409 8408100153 8408160146 8408220065	NUREO NUREO NUREO WASTE MOT
	8408080517* 8408080521* 8408200173*	50-275 G 50-275 G 50-336 P	Louisiana Power & Light Co	8408220337 8408240247 8408010399	PR Nureg 50-382 B
Land Land Laybu & MacDan	8408240265 8408240275 8408240388 8408020120	HABTE MANA WABTE MANA WABTE MGT PR		8408020033 8408020035* 8408030294 8408040032	50-382 A 50-382 A 50-382 S 50-382 S 50-382 S
LeBoeuf, Lamb, Leiby & MacRae	8408070420 8408130378 8408200507	50-244 G PR 50-244 G		8408060061 8408070109 8408070230	50-382 F 50-382 F 50-382 F 50-382 8
League of Homen Voters of Pennsylvania League of Homen Voters of Rockford, IL	8408100144* 8408010177 8408010177 8408010181	50-287 G 50-454 G 50-454 G 50-454 G		8408070027 8408100005 8408100007	50-382 Q 50-382 Q 50-382 F
Legal Environmental Assistance Foundation	8408010181 8408080390 8408010267	50-454 G 50-454 G 50-424 G		8408130342 8408140284 8408160180 8408160221	50-382 F 50-382 A 50-382 S 50-382 S
Lewis, M	8408020111 8408070349 8408140465 8408280412	PR PR 50-287 G 50-287 G		8408160228 8408210305 8408210361*	50-382 8 50-382 A 50-382 A
Limerick Ecology Action	8408010190 8408040170 8408090258 8408170381	50-352		8408210378 8408230179 8408230284*	50-382 A 50-382 A 50-382 Q 50-382 8
Lone Star Screw Co Lone Tree Council Long Island Lighting Co	8408140071 8408170304* 8408010149	GA777 50-327 T 50-322 Q		8408240407 8408270303 8408280219 8408280436	50-382 A 50-382 O 50-382 B
End than Ellinaid on	8408010261 8408020024 8408020048	50-322		8408280440 8408270131 8408270137 8408270145	50-382 8 50-382 8 50-382 8 50-382 8
	8408030090 8408040323 8408070254 8408070274	50-322		8408300521 8408310225 8408310234	50-382 F 50-382 A
	8408070385 8408070399 8408070442	50-322 V 50-322 G 50-322 G 50-322 G	Louisiana, State of	8408010194 8408010210 8408010210	50-416 Q 50-458 Q 50-458 Q
	8408070448* 8408070458* 8408080340 8408080408	50-322		8408010245 8408010245 8408090154* 8408140458	50-45B G
	8408080417	50-322 0	MATHTECH, Inc	8408080472	NUREO

569

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	BRY	AUTHOR AFF IL IAYYON	ACCESSION NUMBER	SUBJECT CATEGOR	RΥ
MHB Technical Associates  MPR Associates: Inc  Madison: IN  Maine Yankee Atomic Power Co	8408020127 8408030112* 8408100080* 8408050214* 8408020121	50-322 50-322 50-220 CONTRAC 50-309	T Q P		8408060187 8408060193* 8408060200* 8408060249 8408060249	50-416 50-416 50-416 50-416 50-416	988
	8408020125* 8408030008 8408030272 8408070367 8408070173	50-309 50-309 50-309 50-309 50-309	K F B P		8408070404 8408070404 8408070430 8408070436 8408070436	50-416 50-416 50-416 50-416 50-416	5 6 6
	8408140399 8408230331 8408280210 8408280227 8408310204	50-309 50-309 50-309 50-309 50-309	ե Ե Է		8408070486 8408070486 840808053B 8408090137 8408090163	50-416 50-416 50-416 50-416 50-416	P 9 9 9
Management Analysis Co Manhattan College, Riverdale, NY Maricopa County, AZ	8408130269* 8408130306* 8408150710* 8408170407 8408200334*	50-329 50-329 50-329 50-199 50-528	A A I F		8408130150 8408130365 8408130371 8408140116 8408150151	50-416 50-416 50-416 50-416 50-416	0 8 8 P
Marsh & McLennan, Inc  Manyland, Univ of, College Park, MD	8408150129 8408160344 8408220148 8408290006	50-244 50-413 50-369 50-269	ורבננ		84081 501 54* 84081 501 60 84081 50201 84081 50201	50-416 50-416 50-416 50-416	P P P
Massachusetts Institute of Technology, Cambridge, MA	8408220172 B408240248* B408300079 B408300083* B408130205	50-146 50-445 50-166 50-166 70-938	R Т Р		84081 60061 84081 60175 84081 60175 84081 60421 84081 60421 8408200127	50-416 50-416 50-416 50-416 50-416 50-417	S S S S S A
Massachusetts, Commonweelth of Matheson Oas Products Maxima Corp	8408130212*  8408210046* 8408210477 8408210478* 8408150786 8408290349*	70-938 50-204 State P State P XPORTLI CONTRAC	rog C		8408210105 8408210151 8408210151 8408210484 8408240210	50-416 50-416 50-416 50-416 50-416	R F F S
Melosh, H J Memphis State Univ , Memphis, TN Meteorological Evaluation Services, Inc Metropolitan Edison Co	8408160411* 8408170286 8408270552* 8408010231* 8408020042	50-508 50-538 CONTRAC 50-354 50-287	A F		8408270263* 8408270321* 8408280137 8408280137 8408280143	50-417 50-414 50-414 50-414 50-416	0 0 0 0
	8408070418 8408070437 8408070470 8408070423 8408130300	50-320 50-287 50-320 50-289 50-289	0 0 0 0	Missouri. State of	8408280143 8408280176 8408300470 8408310222 8408310137	50-414 50-414 50-414 50-414 PR	F 0 9 P
	8408140007 8408150458 8408170325 8408170330* 8408200468	50-287 50-287 50-287 50-287 50-287	0 0 0 0	Mitsubishi International Corp (subs of Mitsubishi Corp )  Mitsui & Co (USA), Inc (subs of Mitsui & Co , Ltd )	8408170406 8408170408# 8408060402	XPORTLIC XPORTLIC XPORTLIC	
	8408200515 8408200557 8408200561 8408230207 8408230272	50-287 50-287 50-287 50-287 50-287	G G G G	Montesano, WA Morgan Associates Morris, IL Morrison-Knudsen Co , Inc	8408040404 8408040438* 8408040037* 8408140488 8408040040* 8408070141	XPORTLIC XPORTLIC CONTRACT 50-247 CONTRACT WASTE MG	0
Michigan State Univ , East Lansing, MI Michigan, Univ of, Ann Arbor, MI	8408270115 8408310207 8408090162 8408090145* 8408020235	50-287 50-287 50-294 50-294 ACRS	9 9 V V		8408100101* 8408170413 8408170413* 8408200154 8408200157*	SO-461 WASTE MG WASTE MG WASTE MG WASTE MG	A T T
Middletown, CT Midwest Electric Cooperative Minnesota, State of	8408130314* 8408170307 8408210032* 8408080534 8408080333	CONTRACT 50-454 CONTRACT 50-315 PR	T	Mount Horris Times, Mount Horris, IL N C Kist & Associates, Inc NUS Corp	8408200342 8408290313 8408140517# 8408140401 8408150733	WASTE MG 50-454 CONTRACT 50-382 71-9073	G
Miranda Associates, Inc Mississippi Power & Light Co	8408080334* 8408220378 8408020027 8408030075 8408030075	PR NUREG 50-416 50-416 50-416	g P P		84081 50736 * 84081 50739 * 84081 50742 * 84081 50744 * 84081 60297	71-9073 71-9073 71-9073 71-9073 WASTE MG1	т
	8408030081 8408030075 8408030075 8408030103 8408030103	50-416 50-416 50-416 50-416 50-416	9 P P P	NUTECH Engineers, Inc Nantz, J L National Board of Boiler & Pressure	8408210403 8408210409* 8408160132* 8408070451 8407230153	50-382 50-382 50-324 PRM NUREG	A G
	8408030104 8408030120 8408030120 8408040030 8408040174	50-417 50-416 50-416 50-416 50-416	A 8 8 8 P	Vessel Inspectors  National Lawyers Quild, Los Angeles Chapter National Technical Systems	8408070117 8408280093 8408030041	QA999 PR QA999	
	8408040174 8408040185 8408040185 8408040189	50-416 50-416 50-416 50-416	P 8 8	National Technical Systems Nebraska Public Power District	8408030011 8408070267 8408070275	50-298 50-298 50-298	Q F P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408070316 8408100014 8408100017* 8408100145 8408140431	50-298 F 50-298 R 50-298 R 50-298 P 50-298 F		8408100111* 8408100118 8408100120* 8408160367 8408160372*	50-220 P 50-410 8 50-220 P 50-220 P
Neutron Products, Inc Novada, State of	8408150447 8408240072 8408240171 8408150598 8408080227	50-298 I 50-298 S 50-298 F 71-9073 State Prog		8408200535 8408210437 8408210447 8408230237 8408280001	50-220 S 50-410 S 50-410 F 50-220 X 50-410 E
New England Coalition on Nuclear Pollution New Jersey, State of	8408130130 8408220041 8408240234	WASTE MGT WASTE MGT 50-443 G 50-354 D		8408280163 8408280248* 8408300035 8408300037* 8408300041*	50-410 E 50-220 G 50-220 P 50-220 P 50-220 P
and correctly clude of	8408070255 8408140543 8408230083 8408230070* 8408270136 8408280353	50-354 G 50-354 G 50-354 D 50-354 D 50-354 D 50-354 H		8408300300 8408300345 8408300342 8408300345 8408310235	50-410 A 50-410 S 50-410 S 50-410 S 50-410 Q
Now Yurk, State Univ of, Buffalo, NY	8408280447 8408280449 8408290014 8408300304 8408060162	50-354	Nichiren Shoshu Temple North Carolina Municipal Power Agencies North Carolina State Univ , Raleigh, NC	8408080173 8408080180* 8408220351 8408240239* 8408020045	40-2061 40-2061 40-2061 50-413 I 50-277 P
New York, State of	8408050157* 8405040335 8408010077 8408010239	50-57 F 50-322 G 50-322 T 50-322 G	North Dakota, State of Northeast Nuclear Energy Co (subs of Northeast Utilities)	8408020069* 8408010334 8408070112	50-297 P State Prog 50-245 S
	8408070437*	50-322 G 50-220 F		8408070321 8408070321	50-213 H 50-213 H
	8408080410 8408130152 8408130254 8408130284	50-322 0 50-322 0 50-322 0 50-322 0		8408070321 8408070341 8408080414* 8408090082	50-213 H 50-336 P 50-245 Q 50-423 A
	8408140005 8408140138 8408140470 8408140477* 8408160210	50-322 G 50-322 G 50-322 G 50-320 G		8408070340 8408100043 8408100043 8408100064 8408100102	50-245 S 50-213 P 50-213 P 50-423 B 50-245 P
Nowman & Holtzinger	8408160224* 8408030087 8408030127 8408070453 8408080186	50-322 G 50-331 J 50-331 J PRM 50-498 G		8408100116 8408100116 8408100116 8408130316 8408150232	50-213 0 50-213 0 50-213 0 50-336 P 50-336 P
	8408140214 8408140214 8408140220* 8408140220* 8408140236*	50-250		8408200172 8408200594 8408210306 8408210339 8408210469*	50-336 P 50-336 R 50-245 P 50-423 E 50-336 0
	8408140236* 8408140253* 8408140253* 8408140271*	50-250		8408210480 8408230431 8408280159 8408280258 8408280258	50-213 G 50-245 R 50-423 E 50-423 E 50-423 E
	8408140277* 8408140277* 8408160196 8408210347 8408210347	50-250 G 50-250 G 50-498 G 50-250 G 50-250 G	Northeast Utilities	8408290004 8408290298 8408310187 8408070112 8408070321	50-245 8 50-213 P 50-213 F 50-245 8 50-213 H
Ntagara Mohawk Power Corp	8408210380 8408210380 8408310247 8407090212 8408020079	50-250 G 50-250 G 50-275 G 50-410 K NUREG		8408070321 8408070321 8408070341 8408080414# 8408080531	50-213 H 50-213 H 50-336 P 50-245 Q 50-336 8
	8408020115 8408020117* 8408030201 8408060154 8408060171	50-220 R 50-220 R 50-220 S 50-220 P 50-220 F		8408070082 8408070340 8408100063 8408100063 8408100064	50-423 A 50-245 8 50-213 P 50-213 P 50-423 8
	8408060248 8408060260 8408060284 8408070434 8408080259	50-220 P 50-410 A 50-410 A 50-220 F 50-220 S		8408100070* 8408100070* 8408100077* 8408100077* 8408100102	50-213 P 50-213 P 50-213 P 50-213 P 50-245 P
	8408080483 8408090077 8408090081# 8408100071 8408100074	50-220 B 50-220 P 50-220 P 50-410 B 50-220 P		8408100116 8408100116 8408100116 8408130316 8408150232	50-213 Q 50-213 Q 50-213 Q 50-336 P 50-336 P
	8408100074 8408100081* 8408100086* 8408100103	50-220 P 50-220 P 50-220 P 50-220 P		8408140350 8408140350 8408140407 8408200172	50-213 F 50-213 F TOPREP 50-336 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT
	8408200594 8408210304 8408210339 8408210469* 8408210480	50-336 R 50-245 P 50-423 E 50-336 Q 50-213 Q	Ocean Fleets Consultancy Service Office of Management & Budge+	8408300282 8408300287 8408310265 8408020129 8408060019	NUREG NUREG WASTE MANA 50-322 T DRG
	8408230421 8408280159 8408280258 8408290004 8408290298	50-243 R 50-423 E 50-423 E 50-245 S 50-213 P	Ogle Petroleum, Inc	8408060114 8408060219 8408070031 8408240050 8408240079	ORG ORG ORG 40~8745 40-8745
Northeast Utilities Service Co (subs o Northeast Utilities)	_	50-213 F 50-423 A	Ohia Citizens for Responsible Energy	84080901 <i>96</i> 84080901 <i>96</i> 8408090202#	50-440 G 50-440 G 50-440 G
Northern States Power Co	8408130349 8407100420 8408070197*	TOPREP 50-263 S 50-282 G		8408090202* 8408090231 8408090231	50-440 G 50-440 G 50-440 G
	8408080077 8408070011 8408070014* 8408130020 8408130021*	50-263	Oklahoma, Univ of, Norman, OK Omaha Public Power District	8408090245 8408090245 8408030066 8408060289	50-440 G 50-440 G 50-112 F 50-285 S
	8408130024* 8408160169 8408160222 8408160229* 8408160233*	71-83 50-263 F 50-263 P 50-263 P 50-263 P		8408070128 8408070401 8408070405 8408100062* 8408100104	50-285 P 50-285 S 50-285 G 50-285 P
	8408170252 8408240238 8408270293 8408270299* 8408270302*	50-263 P 50-282 S 50-263 P 50-263 P 50-263 P		8408150136 8408200587 8408240230 8408270244 8408280288	71~25A 50~285 R 50~285 S 50~285 P 50~285 S
	8409280127 8408280160 8408280164* 8408280169* 8408300176	50-263 B 50-263 P 50-263 P 50-260 P 50-263 F	Oregon State Univ , Corvallis, QR Oregon, State of	8408280343 8408020061 8408200229 8408200234 8408200242	50-285 S PR WASTE MOT WASTE MOT WASTE MOT
Nuclear Fuel Services, Inc. (subs. of	8408300176 8408300176 8408300176 8408300180# 8408300180#	50-263 F 50-263 F 50-263 F 50-263 F 50-263 F	Owens-Corning Fiberglas Corp Pacific Qas & Electric Co	8408200245 8408200252 8408230107 8406150149 8408010036	WASTE MGT WASTE MGT TOPREP 50-275 P 71-202
	8408300180# 8408300180# 8408300183# 8408310112# 8408020154	50-243 F 50-263 F 50-263 F TOPREP 70-143		8408020054 8408020043* 8408020047* 8408040120 8408040124	50-133 P 50-133 P 50-133 P 50-323 A 50-323 A
Getty Gil Co }	8408130381# 8408150156 8408150161# 8408150545	70-143 70-143 70-143 70-143		8408070278 8408070327* 8408070369 8408080453 8408080458*	50-323 A 50-275 G 50-275 S 50-275 F 50-275 F
	8408170012 8408170392 8408270413* 8408280053* 8408280174	70-143 70-143 70-143 70-143 70-143		8408130003 6408130186 8408130188 8408130271 8408140011	50-275 P 50-275 P 50-275 P 50-275 Q 30-275 P
Nuclear Information & Resource Service Nuclear System Nuclear Utility Task Action Committee Nucph. Inc	8408280299* 8408140417 8408090510* 8408140423* 8408010274*	70-143 NUREQ CONTRACT 50-45B A 50-206 P		8408   4001   8408   4034   1 8408   4034   8408   60234 8408   60267 8408   60267	50-275 P 50-323 P 50-275 G 50-275 F 50-275 F
O'Donnell & Associates, Inc O'Neill, J	8408010287* 8408280268* 8408210327 8408210330* 8408210337*	50-204 P 50-445 0 50-155 0 50-155 0 50-155 0		8408160273* 8408160273* 8408160471 8408200318* 8408200318*	50-275 F 50-275 F 50-275 S 50-275 G
DTHA, Inc Oak Ridge Associated Univs Oak Ridge National Laboratory	8408210432 8408280244 8408070462* 8408020225* 8408070007	PR 50-155 G PRM 70-8 NUREG		8408210224 8408210404 8408210639 8408210637 8408230008	50-275 S 50-275 P 50-275 P 50-275 P 50-275 P
·	8408080355 8408080415 8408080415 8408080422 8408130001	NUREG NUREG NUREG NUREG NUREG		8408230012* 8408230476 8408230553 8408230553 8408230553	50-275 P 50-275 S 50-275 F 50-275 F 50-275 F
	8408130007 8408130009 8408130041 8408230184* 8408230191*	NUREG NUREG NUREG 50-317 P		8408230558* 8408270112 8408270394 8408300482 8408310038	50-275 F 50-275 B 50-323 A 50-275 P 50-275 S
	8408270050 8408270170 8408270178 8408300272	WASTE MANA NUREO NUREO NUREO	Palmetto Alliance	8408310143 8408310230 8408070443 8408200548 8408310205	50-275 B 50-275 F 50-413 G 50-413 G 50-413 G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
Parameter: Inc	8408080307* 8408090074* 8408090272 8408130265 8408310084	CONTRACT CONTRACT NUREO NUREO NUREO	-		8408070336 8408070330 8408070330 8408070363 8408070363	50-352 50~352 50-352 50-352 50-352	F 0 0
Pathfinder Mines Corp	8408080326 8408200400 840820040!* 8408240334 8408240413	40-6622 40-2259 40-2259 40-6622 40-2259			8408070346 8408070346 8408070372 8408070372 8408070412	50-352 50-352 50-352 50-352 50-352	9
Pełton, J R Pennsylvania Power & Light Co	8408240414 8408240419* 8408270093 8408160414* 8408030178*	40~2259 40~2259 40~2259 50~50B 50~387	A Q		8408070412 8408070415# 8408070415# 8408070429 8408070429	50-352 50-352 50-352 50-352 50-352	9
	9409060143 8409070342 8409070342 8409080142 8409080269	50-387 50-387 50-387 50-388 50-387	1 P P S G		8408070433* 8408070433* 8408070444 8408070444 8408070450*	50-352 50-352 50-352 50-352 50-352	0000
	8408080269 8408090393 8408090395 8408090396 8408090421	50~387 50~388 50~387 50~387 50~387	0 9 9		8408070450* 8408070495 8408070495 8408070513 8408070513	50-352 50-352 50-352 50-352 50-352	O O E E
	8408090439 8408100125 8408130129 8408160164 8408200283	50~387 50~387 50~387 50~388 50~387	9 F F 8 9		8408080399 8408080399 8408080404 8408080404 8408080533	50-352 50-352 50-352 50-352 50-277	0
	8408210290 8408240065 8408240245 8408300189 8408300340	50-387 50-387 50-387 50-388 50-387	9 8 9 8 9		8408080535 8408100048 8408130274 8408130274 8408130317	50-277 50-278 50-352 50-352 50-352	9. 9. 9. 9. 9.
	8408300399 8408300484 8408300489 8408310118 8408310214	50-388 50-388 50-387 50-387 50-387	\$ \$ \$ \$		8408130317 8408130361 8408130361 8408130601 8408140303	50-352 50-277 50-277 50-277 50-352	A P S E
Pennsylvania Power Co Pennsylvania State Univ , University Park, PA	8408310214 8408020126* 8408090046*	50-387 50-440 CONTRACT	F		8408140303 8408130387 8408130387 8408130404 8408130404	50-352 50-352 50-352 50-352 50-352	E 0 0
Pennsylvania, Commonwealth of,	8408020047 8408140131 8408140449 8408230440#	50-352 50-289 50-219 50-289	G G H		8408150477 8408150477 8408150402 8408160355 8408160355	50-352 50-352 71-711 50-352 50-352	00 FF
Perry. OH Philadelphia Electric Co	8408210047* 8407160090 8407160091* 8408010255 8408010255 8408020030	50-277 50-277 50-352 50-352 50-352 50-352	F G G A		8408160360* 8408160379 8408160379 8408200147 8408200147	50-352 50-352 50-352 50-352 50-352	F E F F
	8408020030 8408020058 8408020058 8408020075* 8408020075*	50-352 50-352 50-352 50-352 50-352	A A A A		8408200206 8408200206 8408200262 8408200262 8408200286	50-352 50-352 50-352 50-352 50-352	F E G
	8408020080* 8408020080* 8408020084* 8408020094* 8408020070*	50-352 50-352 50-352 50-352 50-352	C C K K		8408200285 8408210031 8408210031 8408210076 8408210076	50-352 50-352 50-352 50-352 50-352	0 E E K K
	8408020090* 8408040053 8408040053 8408040228 8408040228	50-352 50-352 50-352 50-352 50-352	A G G		8408210303 8408210303 8408210387 8408210387 8408210394#	50-352 50-352 50-277 50-277 50-352	A P P Q
	8408060232 8408060232 8408060321 8408070033 8408070033	50-352 50-352 50-277 50-352 50-352	E P A		8408210427* 8408210452 8408210452 8408210513 8408210513	50-352 50-352 50-352 50-352 50-352	Q F A A
	8408070037 8408070037 8408070228 8408070287 8408070287	50-352 50-352 50-352 50-352 50-352	A A O		8408210520* 8408210546 8408220119 8408220119 8408220165	50-352 50-171 50-352 50-352 50-352	A A A
	8408070289 8408070289 8408070291* 8408070291* 8408070303	50-352 50-352 50-352 50-352 50-278	E G G P		8408220169 8408220169* 8408220169* 8408220497 8408220497	50-352 50-352 50-352 50-352	A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AFF	AUTHOR TETATION	ACCESSION NUMBER	SUBJEC	
	8408220501* 8408220501* 8408230185 8408230185 8408230258	50-352 F 50-352 F 50-277 F 50-277 F 50-352 V			8408140202 8408140287 8408210137 8408210272 8408210415	50-344 50-344 50-344 50-344 50-344	P P F F
	8408230292 8408230292 8408230297* 8408240236 8408240236	50-352 E 50-352 E 50-352 E 50-352 G 50-352 G	Pawer Authority c	of the State of New York	8408210438 8408280149 8408280242 8408280253 8408010317	50-344 50-344 50-344 50-344 50-286	P 9 P 8
	8408240241 8408240241 8408240254 8408240254 8408240256	50-352 G 50-352 T 50-352 T 50-352 T 50-352 G			8408010319 8408010321* 8408010322* 8408030254 8408030256	50-333 50-333 50-333 50-333 50-333	6 6 8
	8408240256 8408240262 8408270161 8408270161 8408270376	50-352 G 50-352 G 50-352 A 50-352 E			8408030287 8408070364 8408070417 8408070423* 8408070428*	50-333 50-333 50-333 50-333 50-333	R P P
	8408270374 8408280130 8408280130 8408280132* 8408280177	50-352 E 50-352 A 50-352 A 50-352 A			8408100087 8408100105* 8408130309 8408130313* 8408140488	50-333 50-333 50-286 50-286 50-247	F F G
	8408280272 8408280273# 8408280278# 8408280388 8408280388	50-278 P 50-278 P 50-278 P 50-352 G 50-352 G			8408150147 8408150230 8408160311 8408170277 8408210281*	71-240 50-284 50-333 50-286 50-333	F P Q
	8408270107 8408310004 8408310004 8408310007 8408310008	50-277 S 50-277 Q 50-277 Q 50-352 A 50-352 F			8408210436* 8408210443 8408210447* 8408210451* 8408220224	50-333 50-284 50-284 50-286 50-333	О Р Р Р
	8408310008 8408310012 8408310012 8408310018 8408310018	50-352 F 50-352 A 50-352 A 50-352 A			8408230164 8408230171* 8408230354 8408230428 8408240048	50-286 50-333 50-286 50-286 50-286	F 8 8
	8408310058 8408310058 8408310110 8408310110 8408310124	50-352 Q 50-352 Q 50-352 S 50-352 S			8408240145 8408240243 8408270144 8408310095 8408310177	50-333 50-333 50-333 50-333 50-286	P 5 9 0
	8408310146 8408310146 8408310223 8408310413 8408310413	50-352 A 50-352 A 50-352 G 50-352 A 50-352 A	Power Breakers, I Public Interest R California		8408240270 8408060183 8408060191* 8408060197*	9A999 50-70 50-70 50-70	0 0
Philadelphia, PA Philbrick, S S Phillips Industries, Inc	8408310417 8408220379 8408020237 8408200332 8408200332	50-352 Q 50-352 Q ACR8 50-461 S	Public Service Co	of Colorado	8408010006 8408010006 8408010008* 8408020198 8408030148	50-70 50-267 50-267 50-267 50-267	Q R R P
	8408200332 8408200332 8408200333 8408200333 8408200333	50-461 B 50-461 B 50-528 S 50-528 S 50-528 S			8408070233 8408070313 8408080514 8408080520 8408080525	50-267 50-267 50-267 50-267 50-267	\$ 6 6
Phoenixvills, PA Pickard, Lowe & Garrick, Inc Pittsburgh, Univ of, Pittsburgh, PA Plateau Resources, Ltd	8408200338 8408040179 8408130225* 8408020021 8408130272	50-461 8 50-352 G 50-289 P 50-322 T 40-9674			8408070316* 8408070316* 8408070322* 8408130306 8408160207 8408200557	50-267 50-267 50-267 50-267 50-267 50-267	F G G F
Plymouth, MA Portland Cament Association	8408240047 8408240351 8408240410 8408200597* 8408220090*	40-8674 40-7869 40-8698 CONTRACT 50-329 A			8408210428 8408210462 8408230456 8408230457* 8408230457*	50-267 50-267 50-267 50-267 50-267	O P R R
Portland General Electric Co	8408010281* 8408020050 8408020051* 8408020057 8408020059*	50-344 Q 50-344 K 50-344 K 50-344 P 50-344 P	Pyblic Service Co	of New Hampshire	8408280480 8408290181 8408290236 8408290264 8408070332	50-267 50-267 50-267 50-267 50-247	r F F F A
	8408020061* 8408060058 8408070447 8408080316 8408090060	50-344 P 50-344 F 50-344 P 50-344 P		Public Service Co of New Hampshire	8408070342 8408070342 8408100013 8408100013 8408100083	50-443 50-443 50-443 50-443 50-443	
	8408070158 8408070237 8408100058 8408130414 8408130416*	50-344 P 50-344 P 50-344 F 50-344 F	Public Service Cl Jersøy	ectric & Gas Co of New	8408100136 8408100136 8408160371 8408010217	50-443 50-443 50-443 50-354	9 A E

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT
	8408010234* 840801024& 8408020100 8408020108* 8408030049	50-354 50-354 50-272 50-272 50-354	Е В К К		8408100056* 8408130357 8408140161 8408140167* 8408150108	50-244 Q 50-244 P 50-244 F 50-244 F 50-244 P
	8408030247* 8408040174 8408040279 8408070326* 8408080270	50+272 50-354 50-354 50-354 50-354	Q E A Q E		8408170047 8408170058 8408200507 8408270252 8408270112	50-244 P 50-244 P 50-244 G 50-244 F 50-244 S
	8408080344 8408080346* 8408080389 8408070076 8408100065	50-354 50-354 50-354 50-311 50-354	A G G F	Rockester, NY Rockbestos Co Rockwell International Corp	8408040025# 8408070334 8408070466 8408030048# 8408150564	CONTRACT GA999 GA999 50-329 A 70-25
	8408100067* 8408100085 8408100096 8408100140 8408130362	50-354 50-354 50-354 50-354 50-311	F 9 6 5 6	Rocky Mountain Energy Co Rogers & Associates Engineering Corp Sacramento Municipal Utility District	8408280007* 8408240031 8408240102 8408310331 8408060004	HASTE MGT 40-8697 40-8380 WASTE MGT 50-312 V
	8408130589 8408140336 8408150223 8408150245 8408150245	50-311 50-354 50-272 50-272 50-272	9 E F P		8408060011 8408060177 8408130207 8408140259 8408160290	50-312 Q 50-312 P 50-312 F 50-312 P 71-5926
	8408140142 8408160142 8408140276 8408140334 8408140348	50-272 50-272 50-272 50-354 50-354	R R B A E		8408170362 8408200339 8408240111 8408240112 8408270061	50-312 P 50-312 Q 50-312 8 50-312 P 50-312 P
	8408170052 8408170103 8408170336 8408170337 8408200276	50-354 50-354 50-354 50-354 50-311	F E G A R		8408270401 8408280240 8408270288 8408310113 8408310176	50-312 P 50-312 P 50-312 S 50-312 P 50-312 B
	8408200343 8408210335 8408210335 8408210442 8408230332	50-272 50-272 50-272 50-354 50-354	р Р Р А		8408310217 8408310220* 8408310237* 8408310237*	50-312 P 50-312 P 50-312 P 50-312 P 50-312 P
	8408230345* 8408230371* 8408230501 8408240117 8408240117	50-354 50-354 50-272 50-272 50-272	6 8 6	Safe Energy Alliance San Diego Cas & Electric Co San Jose State Univ , San Jose, CA Sandia Laboratories	8408310246* 8408140447 8408070174* 8408020127 8408080357	50-312 P 50-219 G 50-361 P 50-322 T NUREG
	8408240273 8408240288* 8408240293 6408280066 8408280089	50-354 50-354 50-354 50-354 50-354	E D Q Q		8408080367 8408100147 8408100152 8408100155 8408130006	NUREO NUREO NUREO NUREO NUREO
	8409280201 8408280223 8409280448 8409270002 8408270078	50-354 50-354 50-354 50-354 50-354	E G G F A		8408130577 8408240214 8408240240 8408240284 8408240320	WASTE MGT WASTE MANA WASTE MANA WASTE MANA NUREG
	8408290102* 8408290134 8408290138* 8408290144* 8408290149*	50-354 50-354 50-354 50-354 50-354	A E E E	Sandvik Special Metals Corp	8408280009* 8408290337 8408300178 8408310089 8408010142	WASTE MOT WASTE MANA WASTE MANA NUREG XPORTLIC
	8408270160* 8408300153 8408300342 8408300347 8408300400	50-354 50-354 50-354 50-311 50-311	£ 8 8	Sargent & Lundy, inc	8408030143 8408130420* 8408270172* 8408310192 8408310192	GA999 50-454 G 50-454 G 50-454 T 50-454 T
Pullman, Inc Radiation Management Corp	8408310178 8408130278 8408130283* 8408020228 8408020230*	50-354 71-184 71-184 40-8724 40-8724	К	Science & Engineering Associates, Inc	8408310194* 8408310194* 8408310199* 8408310199* 8408080472	50-454 T 50-454 T 50-454 T 50-454 T NUREQ
Re/Spec. Inc Reactor Experiments, Inc Rhode Island & Providence Plantation Rhode Island. State of Rockester Oas & Electric Corp	8408150114* 8408040432 8408210328 8408070332 8408030014*	71-6346 XPORTLIC 50-173 PR 50-244	C 5:	Science Applications, Inc	8408130437* 8408130442* 8408130445* 8408150275* 8408210180	CONTRACT CONTRACT CONTRACT 50-219 F WASTE MGT
	8408070178* 8408070198 8408070248 8408070420 8408070513	50-244 50-244 50-244 50-244 50-244	9 9 9 9 P	Senate	8408270558* 8408310262* 8405180152* 8408010340* 8408070048*	CONTRACT CONTRACT 50-347 H 50-335 H 50-414 H
	8408070516* 8408070524 8408070526* 8408080091 8408100032*	50-244 50-244 50-244 50-244 50-244	P P P ው	Sequoyah Fuels Corp Bhaw, Pittman, Potts & Trowbridge	8408220296 8408230063* 8408240339 8408240377 8408010214	50-289 Q 50-272 H 40-8769 40-8768 50-440 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	VCCE ARI DW	SUBJECT CATEGORY
	8408010229 8408020042 8408020054 8408070418 8408070437	50-440 9 50-287 9 50-400 9 50-320 9 50-287 9	Southern California Edison Co	84082 60287 84083 00514 84080 10226 84080 10240 84080 10272	50-395 Q 50-395 S 50-206 P 50-361 P 50-206 P
	8408070470 8408080217 8408090423 8408130300 8408140004	50-320 G 50-400 G 50-287 G 50-287 G 50-400 G		8408010304 8408030123 8408030123 8408030146 8408030165*	50-361 8 50-206 F 50-206 F 50-206 P
	8408140007 8408140008 8408140014 8408140022 8408140048	50-287 G 50-400 G 50-400 T 50-400 G 50-400 G		84080&0034 84080&0037* 84080&0080 84080&0080 84080& <b>01</b> 12	50-361 8 50-361 8 50-361 P 50-361 P 50-361 Q
	8408140057 8408140420 8408150467 8408170325 8408170330*	50-400 G PR 50-440 G 50-287 G 50-287 G		8408060112 8408060223 8408070379 8408070411 8408070411	50-361 G 50-361 B 50-206 B 50-206 G 50-206 G
	8408200448 8408200515 8408200557 8408200541 8408230207	50-287 Q 50-287 Q 50-287 Q 50-287 Q 50-289 Q		8408080489 8408090187 8408090187 8408090194* 8408090194*	30-361 P 50-361 P 50-361 P 50-361 P
Sigrra Club	8408230272 8408270115 8408280219 8408310207 8408310106	50~287		8408090201* 8408090201* 8408190418 8408100091	50-361 P 50-361 P 50-362 B 50-361 P 50-361 P
Bigma Chemical Co Binclair, M Binnissippi Alliance for the Environment (BAFE)	8408170220 8408170297* 8408010177 8408010177	XPORTLIC 50-329 T 50-454 G		84081 001 15 84081 30203 84081 402 16 84081 40260 84081 40260	50-361 P 50-206 G 50-206 S 50-361 G 50-361 G
Bmall Business Administration	8408010181 8408080370 8408220080* 8408220400* 8408220404* 8408270347*	50-454 G CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT		84081 60215 84081 70057 8408200335 8408200335 8408210165	50-206 P 50-361 8 50-361 Q 50-361 Q 50-206 P
Society Against Nuclear Energy Bouth Carolina Electric & Qas Co	8408140449 8408040103 8408040134 8408040140 8408070373	50-217 G 50-395 P 50-395 P 50-395 P 50-395 P		8408210179* 8408210479 8408220098 8408220098 8408230178	50-204 P 50-362 Q 50-341 R 50-341 R 50-204 P
	8408070402 8408080124 8408080187 8408080192* 8408080176#	50-375		8408240084 8408240168 8408240200 8408240267 8408240267	50-361 S 50-206 P 50-362 S 50-361 P 50-361 P
	8408080200* 8408080207* 8408080214* 8408080221* 8408080226*	50-395 K 50-395 K 50-395 K 50-395 K 50-395 K		8408240274 8408240297* 8408270409 8408270409 8408280225	50-361 P 50-361 P 50-361 P 50-361 P
	8408080228* 8408080232* 8408080237* 8408080240* 8408080244*	50-395 K 50-395 K 50-395 K 50-395 K 50-395 K		8408280296 8408300163 8408300163 8408300165* 8408300165*	50-361 S 50-361 P 50-361 P 50-361 P 50-361 P
	8408080248* 8408080251* 8408080254*	50-375 K 50-375 K 50-375 K	Southern California, Univ of, Los Angeles, CA	8408300232 8408300472 8408140405*	50-204 £ 50-341 £ 50-508 A
	8408080260* 8408080262*	50-395 K 50-395 K	Southern Ca Services, Inc Bpiegel & McDiarmid	8408020104 8408030154	NUREQ 50-275 P
	8408080265* 8408070143 8408070241 8408100002 8408100012*	50-375 K 50-395 8 50-395 8 50-395 F 50-395 F	Stamiris, B Standardised Nuclear Unit Power Plant System	8408290342 8408020107* 8408170272* 8407310144	50-458 M 50-329 G 50-329 T 50-482 A
	8408130340 8408130344	50-375 B 50-375 F		8408010386 8408010386	50-482 B
	8408140265 8408160525 8408170308	50-375 P 71-7151 50-375 V		8408010386 8408030255 8408030255 8408030255	50-482 8 50-482 8 50-482 8 50-482 8
	8408170318# 8408170318# 8408200340 8408200344 8408230507	50-375 V 50-375 S 50-375 S 50-375 S		8408040234 8408140043 8408140043 8408210313 8408270389	50-482 A 50-482 F 50-482 A 50-482 A
	6408240002 6408270174* 6408280104 6408280114*	50-395 P 50-395 Q 50-395 P 50-395 P		8408270389 8408300090 8408310101	50-482 F 50-482 F 50-482 A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE CATEQ	ORY	AUTHDR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
State. Dept of Steel, Hector & Davis	8408010138 8408090397 8408090397 8408090437 8408090437	XPDRTL 50-250 50-250 50-250 50-250	IC O O		8405290062 8405290062 8405290179 8405290179 8405290179	50-206 8 50-206 8 50-206 8 50-206 8 50-206 8
	8408140236* 8408140233* 8408140253* 8408140253* 8408140277*	50-250 50-250 50-250 50-250 50-250	0 0		8405290179 8405290179 8405290179 8405290179 8405290179	50-204 S 50-204 S 50-204 S 50-206 S 50-204 S
Stewart & Stevenson Services Stone & Webster Engineering Corp	8408140277* 8408100106* 8408030136 8408960138* 8408210382*	50-250 50-461 GA797 50-206 TOPREP	Q A S		8405290179 8405290179 8405290179 8405290179 8405290179	50-206 B 50-206 B 50-206 B 50-206 B 50-206 B
Stane & Webster, Inc	8408280203* 8408310213* 8406010038 8408150714* 8408240132	50-412 50-412 50-327 50-327 50-327	፫ 5 A R		8405290179 8405290179 8405290179 8405290179 8405290179	50-204 8 50-204 8 50-204 8 50-206 8 50-206 8
	8408240138* 8408240138* 8408240143* 8408240148* 8408240132*	50-327 50-329 50-329 50-329 50-329	ន R R R		8405270177 8405270177 8405270177 8405270177 8405270177	50-206 8 50-206 8 50-206 8 50-206 8
Streich, Lang, Weeks & Cardon Suffolk County, NY	8408240157* 8407120136 8408010237 8408020021 8408030074	50-327 50-528 50-322 50-322 50-322	R D G T G		8408040050 8408040102 8408040324 8408140374 8408140375	50-204 8 50-206 8 50-206 8 50-206 8 50-206 8
	8408030105 8408030112* 8408070308 8408070424	50-322 50-322 50-322 50-322 50-322	6 6 6	TERA Corp	8408290179 84081400122* 8408150741* 8408150741* 8408150745*	50-20A 8 50-275 P 50-329 A 50-329 A 50-329 A
	8408080338 8408080410 8408130341 8408140013 8408140017#	50-322 50-322 50-322 50-322	9 9 7 7	TMI Public Health Fund Tayloe Associates	8408150745* 8408270149* 8408310157* 8408310239* 8408100030	50-329 A 50-287 G 50-287 P 50-289 P 50-454 T
	8408140466 8408140477 8408140477* 8408160210 8408160224*	50-322 50-322 50-322 50-322 50-322	0 0 0 0		84081 50524 84081 60076 84081 60079 84081 60099 84081 601 03	50-413 0 50-322 0 50-352 0 50-352 0
	8408170315 8408210388 8408230194 8408230197 8408230244	20-355 20-355 20-355 20-355 20-355	0 0 0		8408160107 8408160112 8408160118 8408160123 8408160188	50-413 0 50-352 0 50-322 0 50-322 0 50-400 0
สิบฐ <b>ล</b> ากลก & Denworth	8408280249 8408280405 8408010223 8408010223 8408010228*	50-322 50-322 50-352 50-352 50-352	0 0 0 0	Tech/Ops Technology for Energy Corp Teladyne Engineering Bervices Teledyne Gaotach Teledyne Saotach	8408020201 8408230077 8408060016* 8408310310 8408210355*	71-9021 50-327 P 50-293 P XPORTLIC 50-171 R
	8408010228* 8408010248 8408090226 8408090233* 8408130368	50-352 50-352 50-352 50-352 50-352	0 0 0 0	Telefiex, Inc Temple Univ , Philadelphia, PA Tennessee Valley Authority	8408150724 8408200314 8408170326# 8408010172 8408010172	XFORTLIC XFORTLIC 50-454 T 50-390 A 50-390 A
Sunflower Alliance TDI (Transamerica Delaval, Inc ) Owners Group	8408140484 8408010227 8408280437 8405270062	50-352 50-440 50-440 50-206	9 9 8		8408010344 8408010344 8408010344 8408020145 8408020145	50-259 P 50-259 P 50-259 P 50-259 F
	8405270042 8405270042 8405270042 8405270042 8405270042	50-206 50-206 50-206 50-206	6 6 6 6 6		8408020145 8408020151* 8408020151* 8408020151* 8408020155*	50-257 F 50-257 F 50-257 F 50-257 F 50-257 F
	8405270062 8405270062 8405270062 8405270062 8405270062	50-204 50-204 50-204 50-206 50-206	8 8 8 8		8408020156# 8408020156# 8408020242 8408020242 8408030015	50-259 F 50-259 F 50-275 D 50-275 D 50-259 F
	8403270062 8403270062 8403270062 8403270062 8403270062	50-204 50-204 50-204 50-204 50-206	8 8 8		8409030019 8408030025* 8409030026 8409030026 8409030032	50-327 P 50-327 P 50-327 P 50-327 P 50-390 F
	8403270042 8403270062 8403270062 8403270062	50-206 50-206 50-206	5 6 8		8408030032 8408030128 8408030128 8408030155 8408030257	50-370 F 50-370 A 50-370 A 50-438 A 50-259 B

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO!		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	
	8408040021 8408040029* 8408040098 8408040113 8408040220	50~259 50~259 50~259 50~259 50~259	P ? R S P		8408270156 8408270162* 8408270162* 8408270199* 8408270366	50-327 50-327 50-327 50-259 50-259	P P Q
	8408040241 8408040254 8408040254 8408070133 8408070133	50-327 50-327 50-327 50-327 50-327	ទ ក F P P		8408270369* 8408270370* 8408270374* 8408270468* 8408270475*	50-257 50-327 50-259 50-438 50-438	R G R G
	8408070370 8408070370 8408070370 8408070375* 8408070375*	50-259 50-259 50-259 50-259 50-259	P P P P		8408270483* 8408280086 8408280100 8408280116* 8408280220	50-438 50-238 50-259 50-259 50-260	0 G G
	8408070375* 8408070376 8408080518 8408070020 8408070024	50-259 NUREQ 50-259 50-259 50-439	P 8 8 8		8408280222* 8408280226* 8408280349 8408290245 8408290245	50-260 50-260 50-259 50-259 50-259	P 8 F F
	8408070025 8408070025 8408070028 8408070028 8408070033	50-438 50-438 50-438 50-438 50-438	5 8 8 8		8408270250 8408270250 8408270355 8408270355 8408300467*	50-370 50-370 50-370 50-370 50-327	A A A Q
	8408090033 8408090057 8408090045 8408090078 8408090156	50-438 50-438 50-390 50-390 50-327	3 5 5 5	Texas A&M Univ , College Station, TX Texas Nuclear Div (subs of Ramsay Enginearing Co )	8408300477* 8408310030 8408150371 8408150135	50-327 50-327 50-59 XPORTLIC	Qi B R C
	8408090248	50~438	S	Texas Tech Univ , Lubbock, TX	8408220327	NUREG	
	8408090279 8408090341	50-43B 50-259	8 8	Texas Utilities Electric Co (formerly Texas Utilities Generating Co )	8408020072	NUREG	_
	8408070416 8408070416 8408100024	50-438 50-438 50-327	8 8 F		E408030115 B408030153 B408030153 B408040165	50-445 50-445 50-445 50-445	9 A A A
	8408100024 8408130275	50-327 50-390	F A		B408060184	50-445	R
	8408130275 8408130280* 8408130280*	50-390 50-390 50-390	A A		8408070105 8408070105 8408080026 8408080026	50-445 50-445 50-445 50-445	† T T
	8408130375 8408140331 8408140375 8408140532	50-370 50-259 50-259 50-327	A 8 P P		8408080032 8408080032 8408080051 8408080051	50-445 50-445 50-445	T T T
	8408140532 8408140535* 8408140535* 8408150213 8408160058	50-327 50-327 50-327 50-276 50-438	P P O S		8408080100 8408080146 8408080146 8408080162 8408080162	50-445 50-445 50-445 50-445 50-445	T T G Q
	8408160066 8408160154	50-438 50-390	8 8		8408080148*	50-445	¢
	8408160154 8408160173 8408160173	50-390 50-390 50-390	8 8 9		8408080148* 8408080245 8408080245 8408080272	50-445 50-445 50-445 50-445	g T T
	8408160173 8408160179 8408160179 8408160179 8408160200	50-390 50-390 50-390 50-390 50-438	S S S S		8408080272 8408080294 8408080294 8408080413	50-445 50-445 50-445	T T T C
	8408140269	50~328	<b>5</b>		8408080413 8408090044	50-445 50-445	8
	8408160434 8408160453 8408160493 8408160508	50-438 50-327 50-327 50-259	9 9		8408090044 8408090105* 8408130093 8408130093	50-445 50-445 50-445 50-445	8 A Q
	8408160518 8408160519	50~259 50~259	8 8		8408130305	50-445	ě
	8408160522 8408170053 8408200131	50-327 50-328 50-257	S S P		8408140393 8408140393 8408160157 8408160157	50-445 50-445 50-445 50-445	K A A
	8408200300 8408200412	50~259 50~296	8 8		8408160185	50-445	s
	8408210435 8408220137 8408230192*	50-390 50-259 50-259	A P G		8408160185 8408160204* 8408160330 8408160330	50-445 50-445 50-445 50-445	8 Q Q
	8408230172* 8408230172* 8408230208*	50-259 50-259 50-259	a a a		8408160335 8408160335	50-445 50-445	A
	8408230208* 8408230208* 8408230309	50-257 50-259 50-327	g g s		8408160340* 8408160340* 8408160412 8408160412	50-445 50-445 50-445 50-445	A A A
	8408240109 8408270098 8408270150 8408270156	50-259 50-438 50-296 50-327	Q A 8 P		8408140510 8408170045 8408170045	50-445 50-445 50-445	8 R R

AUTHÜR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEQUA	Υ	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408200295 8408200295 8408220331 8408220331 8408220367	50-445 50-445 50-445 50-445 50-445	9 9 0 9 T	Three Mile Island Alert	8408080038# 8408140477 8408060201 8408060224# 8408070382	COMMISSION WASTE MOT 50-289 0 50-289 0
	8408220367 8408220371 * 8408220371 * 8408220374 * 8408220374 *	50-445 50-445 50-445 50-445 50-445	T T T T		8408070408 8408140010 8408140449 8408140449 8408140479	50-289 0 50-289 0 50-219 0 50-219 0 50-289 0
	8408220380* 8408220380* 8408220381* 8408220381* 8408220385*	50-445 50-445 50-445 50-445 50-445	T T T T		8408220258 8408220263* 8408220366 8408240250 8408240251	50-287 G 50-287 G 50-287 G 50-217 G 50-287 G
	8408220385* 8408220388* 8408220386* 8408220373* 8408220373*	50-445 50-445 50-445 50-445 50-445	T T T T	Toledo Edison Co	8408010313 8408060322 8408070301 8408070335 8408080506	50-346 B 50-346 F 50-346 X 50-346 P 50-346 B
	8408220394* 8408220394* 6408220403* 8408220403* 8408220405*	50-445 50-445 50-445 50-445 50-445	T T T T		8408080508 8408090024 8408100061 8408130390# 8408130395#	50-346 8 50-346 8 50-346 F 50-346 0 50-346 0
	8408220405* 8408220412* 8408230187 8408230187 8408230257	50-445 50-445 50-445 50-445 50-445	T G G G		8408130411# 8408130421 8408130428* 8408140410 8408160199	50-346 G 50-346 P 50-346 P 50-346 P 50-346 8
	8408230317 8408230317 8408230370 8408230397* 8408230400*	50-445 50-445 50-445 50-445 50-445	Q F F F		8408160477 8408170214 8408200073 8408200124 8408200135	50-346 B 50-346 G 50-346 F 50-346 F 50-346 F
	8408230432 8408270030 8408270030 8408270067 8408270067	50-445 50-445 50-445 50-445 50-445	T A A A A		8408210345 8408210456 8408230104 8408280087 8408280145	50-346 Q 50-346 P 50-346 F 50-346 F
	8408270075 8408270123 8408270123 8408270124 8408270132	50-445 50-445 50-445 50-445 50-445	A A A	Torrey Pines Technology Transamerica Delaval, Inc	8408280197 8408280198* 8408060419 8408310023 8408230229	50-346 K 50-346 K 50-352 R 50-352 R 9A999
	8408270132 8408270134 8408270154 8408270271 8408270271	50-445 50-445 50-445 50-445 50-445	A G O X X	Transpuclear, Inc	8408140467 8408140476* 8408140485* 8408150594 8408150600*	71-9016 71-9016 71-9016 71-9016 71-9016
	8408270368 8408270368 8408280083 8408280083 8408280142	50-445 50-445 50-445 50-445 50-445	F G G A		8408150647 8408150654* 8408210314 8408230562 8408230563*	71-9016 71-9016 PR XPORTLIC XPORTLIC
	6406280142 6406280154 6406280154 6406280145 8406280145	50-445 50-445 50-445 50-445 50-445	A G G G	Transportation, Dept of, Federal Highway Administration Trial Lawyers for Public Justice	8408310321# 8408310325# 8408240165 8408090200 8408090200	XPORTLIC XPORTLIC 50-354 D 50-445 Q 50-445 Q
	8408280190 8408280190 8408280218 8408280218 8408280221	50-445 50-445 50-445 50-445 50-445	A A A O		8408070206* 8408070206* 8408140475 8408230173 8408240247	50-445 Q 50-445 Q 50-445 Q 50-445 Q 50-445 T
	8408280221 8408280251 8408280251 8408280265 8408280375	50-445 50-445 50-445 50-445 50-445	0 0 0 8	Turk, J Tuskagee Institute, Tuskegee, AL U S Ecology, Inc (formerly Nuclear	8408280157 8408290319 8408060209 8408060426* 8408010034	50-445 0 50-445 0 50-70 0 CONTRACT 27-48
	8408280375 8408280384 8408280384 8408280468 8408280468	50-445 50-445 50-445 50-445 50-445	9 9 9 8	Engineering, Inc ) U.S. Gupsum Co	8408060026 8408130081* 8408060045 8408060047*	27-39 Waste mgt Waste mgt Waste mgt
	8408290125 8408290125 8408290208 8408290208 8408290211*	50-445 50-445 50-445 50-445 50-445	8 8 K K K	U S. Merchant Marine Academy, Kings Point, NY UMETCO Minerals Corp (subs. of Union Carbide Corp )	8408080144	50-322 T 40-8681
Texas, State of	8408270211* 8408300237 8408300237 8408310216 8408020110	50-445 50-445 50-445 50-445 PR	K A A Q	Uniformed Bervices Univ. of Health Beiences Union 76 Minerals Exploration Co Union Carbide Corp	8408300237* 8408270157 8407230131 8408060383	50-289 P 40-8584 40-299 40-299

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
<b></b>	8408090556 8408150247 8408240018 8408240344 8408240384	70-687 70-687 40-299 40-299 40-299		8408020041 8408020041 8408020041 8408020041 8408020132	50-280 G 50-280 G 50-280 G 50-280 F
	8408240396 8408240400* 8408240412 8408270077 8408270120	40-279 40-279 40-279 40-279 40-279		8408070039 8408070039 8408070039 8408070039 8408070039	50-280 F 50-280 F 50-280 F 50-280 F
Union Electric Co	8408270188 8408280399 8406140221 8408030098 8408060148	40-277 40-277 50-483 A 50-483 P 50-483 S		B408070400 8408070400 8408070406* 8408070487 B408090149	50-338 F 50-338 F 50-338 F 50-280 V 50-338 P
	8408060286 8408060287* 8408070123 8408070271 8408100034*	50-483 P 50-483 P 50-483 9 50-483 5 50-483 Q		8408090235 8408090235 8408090239* 8408090239* 8408100098	50-338 P 50-338 P 50-338 P 50-339 P 50-280 F
	8408130397 8408140129 8408140385 8408140404* 8408160176	50-483 F 50-483 F 50-483 P 50-483 Q 50-483 8		8408130400* 8408130403* 8408130403* 8408130438* 8408130438*	50-338 Q 50-338 Q 50-338 Q 50-338 Q
	8408160256 8408210402 8408220278 8408230427 8408230546	50-483 8 50-483 F 50-483 P 50-483 S 50-483 S		8408130585 8408150464 8408150464 8408160039 8408160406	50-280 P 50-338 Q 50-338 Q 50-280 P 50-280 F
Union Minerals	8408240193 8408240315 8408270393 8408240408 8408240417	50-483 8 50-483 8 50-483 F 40-8584 40-8584		8408160406 8408170222 8408170222 8408170300 8408200477	50-280 F 50-280 F 50-280 F 50-338 P 50-338 G
Union of Concerned Scientists	8408240423* 8408270238 8408270243* 8408020040 8408070027*	40-8584 40-8584 40-8584 50-289 G 50-447 H		8408200477 8408210132 8408210132 8408210375 8408210375	50-33B G 50-280 P 50-280 P 50-338 P 50-338 P
	8408130394 8408140035 8408140448 8408140474 8408130145	50-289 G 50-289 G 50-247 G 50-289 G 50-289 G		8408220171 8408220171 8408240280 8408270448* 8408280150	50-280 R 50-280 R 50-280 P 50-280 G
	84081 60339 84081 70335 8408220362 8408230325 8408240245	50-447 A 50-289 Q 50-289 Q 50-289 Q 50-289 Q		9409280150 8409280150 8408280150 8408280150 8408290150	50-280 0 50-280 0 50-280 0 50-280 0 50-338 8
United Nuclear Corp	8408270359 8408280493 8408010024 8408020096 8408290185	50-289 G 50-289 G 70-820 70-820 NUREO	Virginia Polytechnic Instituta & Btate Univ , Blacksburg, VA	8408300177 8408300177 8408310150 8408310150 8408220156*	50-33B
United Technologies Corp Uranerz UBA, Inc Uranium Resources, Inc Utility Nuclear Waste Management Group	8408300134 8408230198* 8408240341 8408240353 8408070457*	70-371 40-791 40-8783 40-8784 PRM	Virginia, Univ of, Charlottesville, VA	8408010350 8408010391 8408310390* 8408080197	50-62 F 50-62 F CONTRACT 50-348 M 50-348 M
Utility Safety Classification Group Venice Alliance for Survival Vermont Yankee Nuclear Power Corp	8408090106* 8408130346 8408020082 8408060226 8408080041	COMMIBBION PR 50-271 Q 50-271 Q 50-271 F	W J Woalley Co	8408080202 8408080202 8408080241 8408080241 8408130137	50-348 M 50-348 M 50-348 M 50-348 M PT21
	8408070085 8408160052 8408160056* 8408230534	50-271 Q 50-271 P 50-271 P 50-271 S	WESTEC Services, Inc Walworth Co (subs of IU International Corp )	8408070053* 8408210093	CONTRACT 71-39
	8408230542 8408240004	50-271 B 50-271 P	Warren Wilson College, Swannanos, NC	8408280360 8408280383* 8408280387*	50-275 P 50-275 P 50-275 P
	8408270152 8408280055 8408280307 8408300478	50-271 R 50-271 P 50-271 S 50-271 S	Washington Public Power Supply System	B406070192 B408030280 8408060233 8408060235 8408060301	50-397 R 50-397 S 50-397 S 50-397 S 50-397 S
Virginia Electric & Power Co	8408310093 8408310279 8408010056 8408010060*	50-271 F 50-271 H 50-280 B 50-280 B		8408070247 8408070275 8408070325 8408070333	50-397 0 50-305 F 50-397 P 50-397 P
	8408010069* 8408010076* 8408020028 8408020028 8408020041	50-280 8 50-280 8 50-338 F 50-338 F 50-280 0		8408090262 8408090262 8408090443 8408090450	50-460 A 50-397 P 50-397 8 50-397 B

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEODRY
	8408070458 8408160404 8408170031 8408170255 8408200132	50-397 8 50-508 A 50-460 A 50-508 9 50-397 B		8408230488 8408230498 8408230510 8408240349 8408240379	XPORTLIC XPORTLIC XPORTLIC 40-8502 NUREG
	8408200317 8408200341 8408270073 8408270153 8408280320	50-440 8 50-397 8 50-397 P 50-397 P 50-397 R		8408240381 8408240397 8408240409 8408240427 8408270028	40-8502 40-8502 40-8502 40-8502 40-8585
	8408270017 8408270024 8408270030 8408270116 8408270143	50-397 8 50-397 8 50-397 9 50-397 9 50-397 8		8408270027* 8408270031 8408270032 8408270034* 8408270034	40-8595 40-8502 40-8502 40-8502 40-8502
Washington State Univ , Pullnan, WA Washington, State of	8408020085 8408300293 8406210304 8408210064 8408210071	PR 50-27 R Waste Mgt Waste Mgt Waste Mgt		8408270138 8408270177 8408270246* 8408270312 8408270449	40-8502 40-8502 50-266 P TOPREP TOPREP
Washington, Univ of, Seattle, WA	8408220240 8408010158 8408060386 8408160405* 8408170040	WASTE MGT NUREG NUREG 50-508 A 50-139 F		8408270545 8408270542 8408270564 8408270571 8408280148	40-8502 40-8502 40-8502 40-8502 70-1151
Water Engineering & Technology, Inc Watkins, L B Wasd Instrument Co . Inc Western Nuclear, Inc (subs of Phelps Dodge Corp )	8408060431 8408010258 8408150001 8408270038	WASTE MOT 50-458 Q GA999 40-8684	Westinghouse Hittman Nuclear, Inc	8408280259 8408280260* 8408290560 8408310194* 8408200187	TOPREP TOPREP 70-1151 50-454 T WABTE MOT
Westinghouse Electric Corp	8408270131 8407230200	40-1162 TOPREP	Westinghouse Operating Plants Dwners	8408210486	TOPREP
1100 Table	8407230203* 8408010040 8408030037	TOPREP 70-1151 0A999	Group Weston Geophysical Corp Hheeler Basin Regional Library, Decatur, AL	8408290295 8408080067*	WARTE MANA CONTRACT
	8408060116	TOPREP	Whicher, J M	8406260276 8408280194	50-454 Q 50-367 Q
	8408060125* 8408060231* 8408070257* 8408070282* 8408070288*	TOPREP 50-328 P 50-244 P 50-305 F 50-305 F	Whiting Corp Williams & Associates Wilson Hill Associates, Inc Hisconsin Electric Power Co	8408010269* 8408070080* 8408220080* 8407310166 8407310166	50-155 Q CONTRACT CONTRACT 50-266 K 50-266 K
	8408070419# 8408070465# 8408080278 8408080280# 8408080284#	50-412 F 50-498 A 50-601 K 50-413 E 50-413 E		8408020148* 8408020148* 8408020155* 8408030167 8408030167	50-246 K 50-246 K 50-266 F 50-266 F 50-266 F
	8408080286* 8408080287* 8408080272* 8408080274 8408080275*	30-601 K 50-601 K 50-601 K 50-445 T 50-601 K		8408030170* 8408030170* 8408040127 8408070030 8408070030	50-266 F 50-266 F 50-266 P 50-266 P 50-266 P
	8408080278* 8408080301* 8408080304* 8408080307* 8408080307*	50-401 K 50-401 K 50-401 K 50-401 K 50-401 K		8408070245 8408070245 8408070328 8408070328 8408070330*	50-266 P 50-266 P 50-266 P 50-266 P
	8408080312* 8408080315* 8408080316* 8408080320* 8408080323*	50-401 K 50-401 K 50-401 K 50-401 K 50-401 K		8408070330* 8408100052* 8408100052* 8408170203* 8408170203*	50-244 P 50-244 Q 50-244 Q 50-244 Q 50-246 Q
	8408080330* 8408080342* 8408080343* 8408080345* 8408080347*	50-601 K 50-601 K 50-601 K 50-601 K 50-601 K		8408210232 8408210232 8408210343 8408270233 8408280128	50-244 R 50-244 R 50-244 F 50-244 P 50-244 P
	8408140018* 8408140226* 8408140262* 8408140278 8408150237	50-400 T 50-250 G 50-250 G 50-401 A XPORTLIC	Wisconsin Public Service Corp	8408280216 8408300511 8408300518 8408310227 8407260161	50-266 P 50-266 S 50-266 S 50-266 R 50-205 K
	8408150589 8408150589* 8408150719 8408150730 8408160352	70-1151 70-1151 XPORTLIC XPORTLIC 70-1151		8407240166* 8408020073 8408020078* 8408060093 8408060244	50-305 K 50-305 P 50-305 P 50-305 P 50-305 S
	8408160373* 8408160378* 8408200493* 8408210164 8408210169	50-443 A 50-449 A XPORTLIC XPORTLIC XPORTLIC		8408070292 8408070296* 8408080033 8408080510 8408100019	50-305 F 50-305 F 50-305 B 50-305 S 50-305 F
	8408210489* 8408220321* 8408230340 8408230346*	TOPREP 50-454 E TOPREP TOPREP		8408100078 8408160211 8408220284	50-305 P 50-305 R 50-305 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8408240199	50-305	Р
	8408240205*	50-305	Ρ
	8408280144	50-305	F
	8408280475	50-305	P
	8408310122	50-305	P
	840B310126#	50-305	P
Wisconsin's Environmental Decade	8408210349	PR	
Wisconsin, Univ of, Madison, WI	8408140521	50-156	F
Women's International League for Peace &	8408140449	50-219	G
Freedom Woodward-Clyde Consultants, Inc	8408160413#	50-508	Α
Worcester Polytechnic Institute,	8408070345	PR	
Worcester, MA Wule Laboratories	8408210516#	50~352	Α
Wyoming Mineral Corp	8408240402	40-8502	
Wucming, State of	8408240040	40-8727	
	8408240374	WASTE MG	т
			•
	8408240375	40~8768	
	8408240399	40-4492	
	8408240406	40-8584	
	8408270042	40-8502	
	8408270104	40-4492	
	8408270424	40-8502	
	B40B270550	40-8502	
Yankee Atomic Electric Co	B408010141	50-29	Р
, <u></u>	8408020039	50-29	P
	B40B020097#	50-271	ū
	8408070332	50~443	Α
	8408070362	50-443	F
	8408070362	50-443	F
	8408070365#	50-443	F
	8408070393	50-29	F
	8408070472	50-29	Р
	840807047B*	50-29	P
	8408070104	50-29	9
	B4080901B2*	50~309	P
	B408100013	50-443	8
	8408100013	50-443	8
	840B100053	50-29	G
	8408100136	50-443	8
	8408100134	50-443	8
	8408130322	50-29	F
	B40B130354*	50-29	G
	8408140304	50-29	F
	B408140312	50-29	P
	B40B160357	50-271	F
	8408160371	50-443	A
	8408160529	50-29	8
	8408210350	50-29	8
	8408210419	50-29	Р
	8408220012	50-29	F
	8408230162	50-29	þ
	8408230540	50-29	8
	8408240153	50-29	F
	8408300441	50-29	8



# REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
1-263-07-557-48	8408150275*	50-219 F	TAC 51185	NUREG-0020 VOB NOA	8408160191	NUREG	· ~um>-u
125	8408230459*	50-267 R		NUREG-0040 VOB NO2	8408130186	NUREG	
124	8408230457#	50-267 R		NUREG-0090 V07 NO1	8408270353	NUREG	
170-107 170-109	8408170339# 8408170342#	50-354 Q 50-354 Q		NUREG-0304 VO9 NO2 NUREG-0386 DO3	B408300279	NUREG NUREG	
170-107	*2460770345	20-224 6		EOU ABEO-DERION	8408230125	MOKEG	
19	8408210555*	50-171 R		NUREG-0420 SOA	8408220107	50-322 E	•
20	8408270276*	50~454 E		NUREG-0540 VO6 NOS	8408130049	NUREG	
23A1739 ROO	8409280211#	50-331 P		NUREQ-0675 624	8408130002	50-275	
2DVM-179 37	8408280203* 8408270284*	50~412 £ 50-454 E		NUREG-0675 925 NUREG-0675 926	8408160080 8408220346	50-275 £	
٠	O-TOGE/ORU-T-	00 104 6		Moneo odyo deg	4400220040	00 270 0	•
41	8408210549*	50-171 R		NUREG-0675 827	8408160250	50-275 E	
46960~4	84082105184	50-352 A		NUREG-0680 S03	E1408060413	50-289 F	•
580 ROO 81	84082702904	50~219 P 50-454 E		NUREG-0748 VO4 NO6 NUREG-0750 V19 NO3	8408080363 8408240187	NUREG NUREG	
84-M-004 RO2	8408270292* 8408060200*	50~416 S		NUREG-0776 507	B406190069	50-387 E	
D1 401 N-2				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
97	8498270296*	50-454 E		NUREG-0853 803	8406190045		<u>:</u>
AECC-2-NP AOS	8408140204*	TOPREP		NUREQ-0933 801	8409220265	NUREG	
BAW-1638 BAW-1794	8408210393 <b>+</b> 8408210387*	50-33B P		NUREG-0936 VO3 NO2 NUREG-0940 VO3 NO2	8408100149 8408220308	NUREG NUREG	
BAN-1834	8408140413*	50-336 P		NUREG-0954 503	B408070009	50~413 6	Ξ
27.11		<b>-</b> ·		1,			<u>-</u>
BAW-1836	8408140433*	50-313 P		NUREO-1020LD V01	8407130502	50-289 (	
BFN-REP R14	8408020156*	50-259 F		NUREG-1031	8408160262	50-429 E	Ē
BWIP STP 1 0 DRFT C-50918	8408200491* 8408010224*	WASTE MOT 50-354 E		NUREO-1054 NUREO-1044	8408330292 8408310148	NUREG 50-423 [	
CEN-176(8)-NP RO2	8408270418*	50~361 P		NUREG-1068	8408290158	50-352	
Cent Tractal III III	D.102,0112	,					•
CEN-266(S) -NP ROO	8408270416*	50-341 P		NUREG-1072	8408130011	50-413 F	
CEN-247(8)-NP 800	8408270412*	50-361 P		NUREO-1073	8408220325	50-45B [	)
CEN-281(8)-NP CEN-284(8)-NP	8408010255* 8408010247*	50-361 P 50-361 P		NUREG-1075 NUREG/BR-0018 RO2	8408090370 8408090371	NUREG NUREG	
CEN-584(A) 800	B408100137*	50-528 A		NUREO/BR-0025 V10 N6	8408300289	NUREG	
CPL-19-103 RO1	8408160132*	50-324 0		NVREG/BR-0081	8408220378	NUREO	
DBD-8Y-1 RO1 DDC/EI8-0099-F	8408230400* 8408010053*	50-445 F WASTE MOT		NUREG/CP-0053 NUREG/CR-1740 RO1	8406240249 8408240382	NUREG NUREG	LA-10127-C EGG-2307
DOE/EIS-0077-F	8408010053*	WASTE MOT		NUREO/CR-2000 VO3 NA	8408070007	NUREG	ORNL/NS1C-200
DOE/NE-8HO1 ERR	8408020234	WASTE MOT		NUREG/CR-2000 VO3 N7	8408300287	NUREG	GRNL/NSIC-200
					040	111000	
DOE/NE-BHOP ERR	8408020239#	WASTE MOT		NUREG/CR-2331 VO3 N3 NUREG/CR-3053	8408010179 8408130265	NUREG NUREG	BNL-NUREG-51454 1EB-80-08
DOE/8-0014/L E-Y-YR-83033-4 ROO	8408270352* 8408210426*	50-29 P		NUREO/CR-3139	B408130283	NUREG	ORNL/ENG/TH-25
E99-FM-4521	B40B010027*		TAC 46657	NUREG/CR-3273	8408100155	NUREG	5501-EBUMA
EG/1ES(84)-164	B40B160340*	50~445 A		NUREQ/CR-3346	8408130009	NUREG	ORNL/TM-B795
maaa -04 O 14	B408000075	50-206 8		NUREQ/CR-3369	8408130004	NUREQ	SAND93-1439
FAAA-84-2-14 FAAA-84-3-16	8405290075+ 8405290271+	50-206 S		NUREG/CR-3492 VO4	8408130001	NUREG	DRNL/TM-8921/V4
FAAA-84-5-23	8408210370*		PA07702	NUREQ/CR-3493	8408220333		BNL-NUREG-51711
FAAA-84-5-7	8408160397+	50-204 9		NUREG/CR-3518 VO1	8408010166	NUREG	BNL-NUREC-51714
FAAA-84-6-53	8408160403#	20~509 8	PA07596	NUREG/CR-3549	8408270171	NUREG	PNL-4915
FAAA-8454	8408040387*	50-206 8		NUREG/CR-3590	8408300272	NUREG	ORNL/TM-9006
FAAA-84-6-56 FAI/84-9 DRFT	8408230112*	50~327 P		NUREG/CR-3591 VO1	8408290190	NUREQ	enner III 7000
FTR-75744-1	8408100106*	50-461 A		NUREG/CR-3591 VO2	8408290198	NUREG	
INPO 84-013	84082203154	ORG		NUREO/CR-3599	8408130041	NUREO	
MPR-820 RO2	84081000804	50-220 P		NUREG/CR-3618	8408090415	NUREG	ORNL-5991
NEDU-12725A	8408070337*	50-73 P	BONEDOSP	NURE0/CR-3633 V02	8405210578	NUREG	EGQ-2294
NEDO-21087-09 APP A	B4082802094	50-331 P		NURE9/CR-3633 V03	8405210579	NUREG	EGG-2274
NEDO-24284-A	#49E041B04B	TOPREP		NUREO/CR-3643	8408090359	NUREG	EPPS-EBUNAS
NEDU-30477 RO1	8408170262#	50-263 P		NUREG/CR-3471	8408080419	NUREG	DRNL6047
NEDD-30603	8408270175*	50-331 P		NUREG/CR-3678	8408080409	NUREG	LA-10038

REPORT	ACCESSION	SUBJECT	OTHER REPORT
NUMBER	NUMBER	CATEGORY	NUMBER
NUREG/CR-3679	8408030357	NUREG	LA-10041-MS
NUREG/CR-3689 VOI	8408100151	NUREG	ANL-83-85
NUREG/CR-3689 VO2	8409310083	NUREG	ANL-83-85
NUREG/CR-3690	8408310077	NUREG	ANL-83-85
NUREG/CR-3690	8408310089	NUREG	SAND-0402
NUREO/CR-3704	8406230301	50-317 P	LA-10039-MS
NUREO/CR-3708	8408240379	NUREG	
NUREO/CR-3714 NUREO/CR-3734	8408090422	NUREG	9RNL-6006
NUREG/CR-3735	8408100152	NUREG	SAND84-0688
	8408160146	NUREG	LA-100079-MS
NUREG/CR-3742	8498100153	NUREG	LA-10087-MS
NUREG/CR-3744 VOI	8498380355	NUREG	GRNL/TM-9154/VI
NUREG/CR-3751	E400130043	NUREG	PNL-5048
NUREG/CR-3761	8408160248	50-269 P	EGG-2310
NUREG/CR-3777	8408090367	NUREG	9AND84-0912
NUREG/CR-3792	8408310084	NUREG	IED-79-11
NUREG/CR-3795	8408070272	NUREG	IEB-82-04
NUREG/CR-3/98	8408310075	NUREG	PNL-5153
NUREG/CR-3804 V01	8408030374	NUREO	ANL-84-35
NUREG/CR-3818	8408240320	NUREG	SAND-84-0374
NUREG/CR-3B20 VOI	8408100147	NUREG	SAND84-1025/1
NUREG/CR-3B26	8408010155	NUREG	UCRL-53538
NURE0/CR-3834	B408070014	NUREG	BNL/NUREG-5178
NUREG/CR-3840	8408030472	NUREG	BNL-NUREG-51787
NUREG/CR-3844	8408010151	NUREG	
NUREG/CR-3851 VO1 NUREG/CR-3869	8408300282	NUREO	ORNL/TM-9191/VI
NUREG/CR-3B70	8408220370	NUREG	PNL-5149
	8408140125	NUREG	LMF-109
NUREQ/CR-3874	8408220327	NUREG	
NUREQ/CR-3884	8408290185	NUREG	
NUREO/CR-3894	8408240322	NUREG	ANL-84-1
NUREO/CR-3896	8408050386	NUREG	
NUREO/CR-3897	8408010158	NUREG	
NUSCO 140-1	8408100070*	50-213 P	
NUSCO 140-2	8408100077*	50-213 P	
PALO DURO STP-1 O DR	8408010088*	WASTE MOT	
PARADOX STP-1 O DRFT	8408010083*	Waste Mgt	
PLG-0370	8408130225*	50-289 P	
GO6-30-84	8408070153*	WASTE MOT	
REA-0J-34247-RS REA-	8408270256*	WASTE MGT	
REACCILS REA-7 DRFT	8408030270*	WASTE MOT	
REA00153&03142 REA-5	8408270264*	WASTE MOT	
REA00270 REA-E-D-7DR	8408030197*	WASTE MOT	
REA05785-GJ REA-112A	8408270267*	WASTE MOT	
REA06318-GJ REA-108/	8408270262*	WASTE MOT	
REAGB742 REA-104/LS REA13716 REA-7 DRFT	8408030264* 8408030268*	WASTE MOT	
SAD-431 R01	*0540E1B048	50-454 Q	
SD-BWI-DP-001 RA-0	8408280007*	WASTE MOT	GF-83-58
SECY-84-215	8407030011*	REVIEW GRP	
SECY-84-290A	8407300105	50-322 A	
SECY-84-301	8408070406	SECY	
SECY-84-329	8409240110	SECY	
TDR 481 ROO TDR 519 ROO	8408070257* 8408070306*	50-219 P	
TDR 543	8408030108*	50-289 G	
TER~C5257-040	8105130143*	50-293 P	
TER-C5257-548	0204150347*	50-293 P	
TER-05506-108/109	8307010039*	50-277 P	8122
TER-05506-358	8407300136*	50-213 P	TAC 07993
TER-05506-489 DRFT	8408280321*	50-346 P	TAC 52271
TER-05506-524	8404040098*	50-388 U	
TER-C5506-525	#7E007070#	50-219 P	TAC 48787
TR-4052-1 RO2	8408210382* 8408050016*	TOPREP 50-293 P	
TVA-RLR-002	8408280226#	50-240 P	
UCID-19718	8408200173#	50-334 P	
UCRL-15619	8408070140#	WASTE MOT	
UMTRA-DDE/AL-0229	8408310339*	WASTE MOT	
UMTRA-DDE/AL-0230	8408310335*	WASTE MOT	
UMTRA-DDE/AL-050102 UMTRA-DDE/AL-050102	8408050111* 8408050122*	WASTE MOT	
USC-684-1NP ERR	8408040047#	WASTE MOT	
WCAP-10170 APC S1 R0	8408070419*	50-412 F	
WCAP-10509	8408040231*	50-328 P	
WCAP-10566	8408160378#	50-443 A	
WCAP-7685-A	8408070288#	50-305 F	
WCAP-7819 RO1A	8408070282*	50-305 F	
XN-NF-83-61	84082302664	50-315 P	
XN-NF-83-72 S01 R02	8408140363#	50-261 P	
14-21 (NP) RO2 14-72 501	8408090209*	50-314 P	
14-74	8408230103* 8408230122*	50-261 P	
37	8408070478*	50-29 P	

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSION	NOTIBER			
	PRINCIPAL	DATE	SUBJECT	
ENCLOSURE	DOCUMENT	ISSUED	CATEGORY	
7812070142	8408010061	84/07/18	50-329 A	
790929 <b>011</b> 9	B40B010061	84/07/18	50-329 A	
8004040738	8408010061	B4/07/18	50-329 A	
B00B130744	8408010061	84/07/18	50-329 A	
8010160005	8408010061	B4/07/18	50~329 0	
			F0 0000 1	
8011240409	B408010061	84/07/18	50-329 A	
8104230479	8409010061	84/07/18 84/07/18	50-329 D 50~329 A	
8105070480 8105130143	8408010061 8408060157	84/07/02	50-293 P	
B110190801	8408010061	84/07/18	50~329 A	
B110170401	0400010001	54707716	00 027 11	
8110260082	8408010061	84/07/18	50~329 6	
8111240064	8408010061	84/07/18	50-329 A	
8201050043	8408010061	84/07/18	50-329 A	
8201220049	8408010061	B4/07/18	50-329 A	
8202040352	8408010061	84/07/18	50-329 A	
8203020050	8408010061	84/07/18	50-329 A	
8204150347	8408060157	84/07/02	50-293 P	
8205050209	8408010061	84/07/18	50-329 A	
EE002120033	8408010061	84/07/18	50-329 A	
8205210467	8408010061	84/07/18	50-329 A	
8205240403	8408010061	84/07/18	50-329 0	
8206020051	8408010061	84/07/18	50-327 A	
8204040000	8408010061	B4/07/18	50-329 D	
8206240401	8408010061	B4/07/18	50-325 A	
8206290161	8408010061	84/07/18	50-327 A	
820714033D	8408010041	84/07/18	50-329 A	
8209230536	8408010061	94/07/18	50-329 €	
8210130322	B40B010061	84/07/18	50-329 A	
8210150698	9408010061	84/07/18	50-329 A	
0210270126	8408010041	84/07/1B	5D-329 Q	
8211030222	8408010061	84/07/18	50~329 Q	
83011904B7	8408010061	84/07/18	50-329 G	
8303300734	8303300734	B4/03/03	50-445 A	
8305270222	8408010061	84/07/18	50-329 A	
8306060387	8408010061	84/07/18	50-329 A	
8307010039	8408220527	84/08/03	50-277 P	
8307130423	8408010061	84/07/1B	50-329 A	
8307130425	8408010061	84/07/1B	50~329 A	
0309130017	6408010061	84/07/18	50~329 Q 50-445 A	
8307130112	6309130110	83/08/18	20 142 M	
8309130117	B309130110	83/08/18	50-445 A	
8309220362	9408280340	84/07/22	50-295 P	
8307270346	8408010061	84/07/18	50-329 0	
8309270518	8408010041	94/07/18	50-329 0	
8310050136	8408010061	84/07/18	50-329 G	
6816688.07	D4000100//	04/07/10	50-329 G	
6310070101	8408010061 8408010061	84/07/18 84/07/18	50-329 G	
8310070262 8310070262	8408010061	84/07/18	50-327 K	
8310240271 8312020277	8408010081	84/07/24	50-354 E	
8312020277	8408010061	84/07/18	50-329 A	
7215000100	~.00#10001			

ACCESSION NUMBER

	PRINCIPAL	DATE	SUBJECT
ENCLOSURE	DOCUMENT	ISSUED	CATEGORY
***			
8312120393	8408010061	84/07/18	50-329 A
8402020372	8408010124	84/07/24	50-354 E
B404040095	8408200225	B4/08/10	50-388 U
8404040098	8408200225	84/08/10	
8404040172	8404040169	84/03/26	50-10 F
8404040322	8408300436	84/05/07	50-321 F
8404230171	8408150137	84/08/01	50-400 F
8404250191	8408070268	84/07/27	PR
8405010079	8408100074	B4/08/06	50-315 F
8405140473	8405160470	84/04/27	50-87 P
8405160476	8405160470	84/04/27	50-89 P
8405180152	8405180145	84/05/04	50-347 H
8405180433	8407020541	84/06/27	REVIEW GRP
8405290075	8405270062	84/05/24	50204 S
8405270075	8405270062	B4/05/24	50-206 8
		_ ,, _•	
8405290271	8405290179	B4/05/24	50-204 5
8405300762	8405300761	84/04/11	70-1113
8405300763	8405300741	B4/Q4/11	70-1113
8406010162	8408070074	84/07/30	50-366 8
8406020280	8408010061	84/07/18	50-329 A
GTOUVEUEUU	D400010001	04/0//10	VV U47 11
*******			50-31A P
8404080113	8406080107	84/06/04	,
8404140090	8408290041	B4/08/29	50-413 F
8406140102	8406140101	84/05/22	50~456 G
8406140104	8406140101	B4/05/22	50-456 Q
8406200226	8408070268	84/07/27	PR
8404240179	8406260175	84/06/06	70-1143
8406260184	8406260175	84/06/06	70-1143
8404280010	8408070269	B4/07/27	PR
B407020544	8407020541	B4/06/27	REVIEW GRP
8407030011	8407020541	84/06/27	REVIEW GRP
840709003 <i>7</i>	8408070052	84/07/27	50-219 P
8407100397	8408090508	84/07/31	50~413 U
8407160091	8407160090	83/08/29	50-277 F
8407170316	8407170313	84/07/11	NUREO
8407230203	8407230200	84/07/09	TOPREP
8407250575	840B070026	B4/07/19	ORG
8407260112	8407260111	84/07/20	50-324 K
8407260166	8407260161	B4/07/20	50-305 K
8407260220	8407260218	84/07/23	
8407300136	8408220326	B4/0B/20	50-513 P
8407300151	8407300142	84/07/24	50-329 G
E407300156	8407300142	84/07/24	50-329 C
8408010008	8408010006	84/07/20	50-267 R
8408010022	8408010018	84/07/23	
840B010027	8408010018	84/07/23	50-298 P
8408010028	8408010025	84/05/07	71-9163
E0010931	B40B010025	B4/05/07	71-9163
8408010031 8408010047	8408010025 8408010045	B4/05/07 B4/07/25	71-9163 50-156 F
8408010031 8408010047 8408010048	8408010025 8408010045 8408010041	B4/05/07 B4/07/25 B4/07/24	71-9163 50-156 F CONTRACT
8408010031 8408010047	8408010025 8408010045	B4/05/07 B4/07/25	71-9163 50-156 F

ACCESSION NUMBER

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSIO	N NUMBER					ACCESSION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 198UED	SUBJEC CATEGOR		<b>የ</b> አነ	CLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	Y
8408010033 8408010060 8408010063 8408010069 8408010072	8408010044 8408010056 8408010046 8408010056 8408010064	84/07/13 84/07/19 84/07/13 84/07/19 84/07/17	WASTE MO 50-280 WASTE MO 50-280 WASTE MO	5 9T 9	84 84 84	08020038 08020043 08020031 08020039 08020061	8408010041 8408010041 8408020030 8408020037 8408020037	84/07/18 84/07/18 84/07/20 84/07/27 84/07/27	50-329 50-329 50-344 50-344 50-344	AAKP
8408010076 8408010083 8408010085 8408010088 8408010131	8408010056 8408010079 8408010082 8408010079 8408010129	84/07/19 84/07/19 84/07/18 84/07/19 84/07/24	50-280 WASTE MG 50-483 WASTE MG 50-423	P	84( 84( 84(	08020063 08020066 08020067 08020068 08020069	8408020036 8408020040 8408020036 8408020042 8408020045	84/07/30 84/07/30 84/07/30 84/07/27 84/07/26	50-133 50-413 50-133 50-413 50-297	P G P G P
8408010132 8408010135 8408010143 8408010147 8408010149	8408010061 8408010061 8408010061 8408010061 8408010061	84/07/18 84/07/18 84/07/18 84/07/18 84/07/18	50-329 50-329 50-329 50-329 50-329	0 0 0 A	841 841 841	08020070 08020071 08020074 08020075 08020078	8408020056 8408010041 8408010041 8408020058 8408020073	84/07/30 84/07/18 84/07/18 84/07/31 84/07/27	50-133 50-329 50-329 50-352 50-305	P
8408010152 8408010153 8408010154 8408010140 8408010143	8408010041 8408010041 8408010154 8408010041 8408010041	84/07/18 84/07/18 84/07/26 84/07/18 84/07/18	50-329 50-329 50-412 50-329 50-329	0 F S	94( 84( 84(	08020080 08020084 08020086 08020090 08020097	8408020058 8408020058 8408010041 8408020058 8408020062	84/07/31 84/07/31 84/07/18 84/07/31 84/07/30		C K G A G
8408010148 8408010171 8408010173 8408010178 8408010182	8408010061 8408010165 8408010061 8408010061 8408010175	84/07/18 84/07/27 84/07/18 84/07/18 84/05/14	50-329 50-295 50-329 50-329 CONTRACT	0 F 0	84 84 84	08020079 08020107 08020108 08020112 08020114	8408010061 8408010061 8408020100 8408010061 8408020105	84/07/18 84/07/18 84/07/23 84/07/18 84/07/31	20-354	A G K A F
8408010183 8408010188 8408010171 8408010175 8408010178	8408010061 8408010061 8408010061 8408010061 8408010061	84/07/18 84/07/18 84/07/18 84/07/18 84/07/18	50-329 50-329 50-329 50-329 50-329	0 0 0	94 94 94	08020117 08020117 08020122 08020125 08020126	8408020105 8408020115 8408010061 8408020121 8408020118	84/07/31 84/07/26 84/07/18 84/07/23 84/07/20	50-220 50-329	F R A K I
8408010202 8408010204 8408010204 8408010217 8408010221	8408010061 8408010061 8408010061 8408010214 8408010218	84/07/18 84/07/18 84/07/18 84/07/30 84/07/20	50-329 50-329 50-329 50-440 50-334	0 0 0 0 P	94 94 94	08020127 08020131 08020134 08020139 08020141	8408010041 8407310035 8407310035 8408020130 8408020137	84/07/18 84/07/30 84/07/30 84/07/27 84/07/26		G Q Q P K
8408010224 8408010225 8408010228 8408010231 8408010234	8408010219 8408010222 8408010223 8408010219 8408010219	84/07/27 84/07/27 84/07/13 84/07/27 84/07/27	50-354 50-498 50-352 50-354 50-354	E Q E E	841 841 841	08020142 08020144 08020147 08020148 08020149	8408020130 8408020130 8408020130 8407310146 8408020130	84/07/27 84/07/27 84/07/27 84/07/20 84/07/27	50~273 50~273 50~246	P P K P
8408010237 8408010247 8408010256 8408010263 8408010269	8408010235 8408010240 8408010240 8408010260 8408010260	84/07/30 84/07/20 84/07/20 84/07/30 84/07/30	50-275 50-361 50-361 50-155 50-155	С Р С С	949 949 949	08020151 08020155 08020156 08020171 08020173	8408020145 8408020130 8408020145 8408010041 8408020172	84/07/27 84/07/27 84/07/27 84/07/18 84/07/09	50-266 50-259 50-329	F F G P
8408010276 8408010277 8408010281 8408010284 8408010285	8408010272 8408010275 8408010278 8408010282 8408010283	84/07/30 84/07/20 84/07/16 84/07/13 84/07/16	50-206 50-275 50-344 50-247 50-341	Р G G	841 841 841	08020174 08020177 08020178 08020180 08020181	8408020172 8408010061 8408010061 8408010061 8408010061	84/07/09 84/07/18 84/07/18 84/07/18 84/07/18	50-329 50-329	P G T G
8408010286 8408010287 8408010270 8408010271 8408010292	8408010282 8408010272 8408010288 8408010289 8408010288	84/07/13 84/07/30 84/07/11 84/07/10 84/07/11	50-247 50-206 50-245 50-373 50-245	0 P 0 0	840 840 840	08020182 08020183 08020184 08020185 08020186	9408010061 9408010061 9408010061 9408010061	84/07/18 84/07/18 84/07/18 84/07/18 84/07/18	50-329 50-329 50-329	0 0 0 0
8408010274 8408010278 8408010277 8408010300 8408010306	8408010287 8408010274 8408010297 8408010296 8408010303	84/07/10 84/07/12 84/07/10 84/07/12 84/07/17	50-373 50-247 50-409 50-247 50-335	0 0 0 0 F	841 840 840	08020187 08020188 08020189 08020190 08020192	8408010051 8408010051 8408010061 8408010061 8408010061	84/07/18 84/07/18 84/07/18 84/07/18 84/07/18	50-329 50-329 50-329	G A G G A
8408010308 8408010314 8408010316 8408010321 8408010322	8408010302 8408010312 8408010312 8408010317 8408010317	84/07/19 84/07/13 84/07/13 84/07/25 84/07/25	50-151 50-374 50-374 50-333 50-333	G G P P	946 946 946	08020173 08020174 08020175 08020176 08020177	8408010061 8408010061 8408010061 8408010061 8408010061	84/07/18 84/07/18 84/07/18 84/07/18 84/07/18	50-327 50-329 50-329	A Q A Q A
8408010327 8408010331 8408010340 8408010341 8408010342	8408010328 8408010328 8408010338 8408010332 8408010338	84/07/24 84/07/24 84/07/20 84/07/10 84/07/20	50-320 50-320 50-335 50-454 50-335	Р Р Н С	840 840 840	08020202 08020207 08020207 08020223 08020225	8408010041 8408020205 8408020205 8408020220 8408020220	84/07/18 84/05/31 84/05/31 84/07/06 84/07/06	50-329 70-34 70-34 70-8 70-8	G
8408010345 8408010366 8408010368 8408010372 8408010378	8408010343 8408010364 8408010364 8408010364 8408010375	84/06/06 83/11/19 83/11/18 83/11/18 84/07/09	50-318 GA999 GA999 GA999 50-387	8	840 840 840	08020227 08020230 08020231 08020233	8408020222 8408020228 8408020222 8408020222 8408020222	84/08/01 84/06/28 84/08/01 84/08/01 84/08/01	40-8724 50-275 50-275	G G G
8408010400 8408010402 8408020009 8408020018 8408020035	8408010397 8408010401 8408020006 8408020010 8408020033	84/07/19 84/07/12 84/07/25 84/07/25 84/07/27	40~4479 50~263 50~331 50~302 50~382	G P P A	840 840 840	08020237 08020256 08030001 08030004 08030007	8408020236 8408020253 8408010061 8408010061 8408010061	84/07/05 84/06/28 84/07/18 84/07/18 84/07/18	50-329	A A A

ACCESSIO	N NUMBER				ACCESSI	ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC CATEGO	
8408030013 8408030014	8408010061 8408030005	84/07/1B 84/07/26	50-329 50-244	A	8408040142 8408040153	8408060137 8408060145	84/07/18	50-219	
8408030016 8408030020	8408030012 8408010041	84/07/31 84/07/18	50-482 90-329	Ă	8408060160 8408060160 8408060161	8408060146 8408060157	84/07/25 84/07/26	50~373 50~134	F
B408030025	8408030019	84/07/27	50-327	P	8408040167	8408060157	84/07/02 84/07/31	50-293 50-57	þ
8408030028 8408030031	8408010061 8408030027	84/07/19 84/07/30	50-329 50-272	A G	8408040172 8408040180	6408060157 6408060175	84/07/02 84/05/25	50-293 50-482	P Q
8408030033 8408030042	8408030029 8408010061	84/07/27 84/07/18	70-143 50-329	Α	8408040191 8408040193	8408060183 8408060185	84/07/30 84/07/27	50-70 50-416	9
B408030051	6408010061	84/07/18	50~327	A	8408060196	8408060192	84/07/27	50-400	Ā
840B030056 840B030057	8408010061 8408030052	84/07/18 84/07/24	50-327 50-271	A F	8408040197 8408040200	8408040183 8408040185	84/07/30 84/07/27	50-70 50~416	G
8408030058 8408030064	8408010061 8408010061	84/07/18 84/07/18	50-327 50-329	A	8408060206 8408060208	8408060183 8408060190	84/07/30 84/07/09	50-70 50-213	G G
8408030068	8408010061	84/07/19	50-329	A	8408060214	8408060211	84/07/24	CONTRAG	Г
B408030076 B408030100	9408030071 8408030096	84/07/12 84/07/20	50-329 50-241	Q P	8408060224 8408060231	8408060201 8408060220	84/07/31 84/07/31	50-289 50-328	G P
8408030107 8408030108	8408030104 8408030104	84/07/30 84/07/30	50-287 50-287	G G	8408060240 8408060273	8408060234 8408060268	84/07/27 84/07/27	50-482 50-352	A
8408030112	8408030105	84/08/01	50-322	G	8408060280	8408060276	84/09/02	50~237	P
8408030113 8408030116	8408030109 8408030109	84/07/30 84/07/30	50-155 50-155	P P	8408040287 8408040303	8408060286 8408060302	84/08/01 84/07/20	50-483 50-456	P Q
8408030125 8408030127	8408030110 8408030126	84/07/11 84/07/30	50-296 50-335	D D	8408060307 8408060313	8408060302 8408060307	84/07/20 84/06/29	50-456 50-285	Q Q
8408030135	B408030130	84/07/31	50-369	P	0408080313 02E060804B	8408060317	84/07/09	20-385 20-583	œ.
8408030140 8408030147	8408030110 8408030146	84/07/11 84/07/31	50-296 70-371	P	8408040325 8408040344	8408060317 8407310030	84/07/09 84/07/27	50-382 50-454	9 8
8408030148 8408030151	8408030146 8408030150	84/07/31 84/07/30	70-371 50-255	Р	8408060371	8408060368	84/07/27	· 70-2988	
8408030152	8408030150	84/07/30	50-255	P	8408040375 8408040378	8408060368 8408060373	84/07/27 84/07/16	70-2988 70-1362	
8408030169 8408030170	8408030166 8408030167	84/08/01 84/07/31	50-206 50~266	P F	64080A0382 84080A0387	8408060373 8408060324	84/07/14 84/08/01	70-1362 50-206	_
840803017B	8408030173	B4/07/26	50-367	G	8408040424	8408050424	84/07/24	CONTRACT	
8408030179 8408030192	8408030176 8408030188	B4/07/13 B4/07/13	50-155 50-410	G G	8408040438 8408070011	8408040435 8408040445	84/07/27 84/07/24	XPDRTL 10 50-394	P
8408030197 8408030207	8408030187 8408030203	84/07/23 84/07/13	WASTE MG	T <sub>Q</sub>	8408070018 8408070027	8408070016	84/07/26	50-324	P
8408030215	8408030211	84/07/17	50-320	P	8408070029	8408070025 8408070025	B4/07/25 B4/07/25	50-447 50-447	H
8408030218 8408030220	8408030211 8408030211	84/07/17 84/07/17	50-320 50-320	P P	8408070038 6408070048	8408070035 8408070041	84/07/30 84/07/26	50-170 50-416	P H
8408030221 8408030223	8408030209 8408030211	84/07/03 84/07/17	50-333 50-320	Q P	B408070053 B4080700B4	8408070047 8408070082	84/07/25	CONTRACT	
8408030224	8408030222	84/07/12	50-271	G	B408070087	8408070080	84/07/26 84/07/26	CONTRACT	
8408030226 8408030228	8408030211 8408030211	B4/07/17 B4/07/17	50-320 50-320	P P	8408070104 8408070127	8408070101 8408070124	84/07/25 84/07/31	CDNTRACT 50-146	P
B408030229	8408030222	84/07/12	50-271	Q.	8408070140	8408070136	84/07/24	WASTE MG	
8408030231 8408030247	8408030211 8408030234	B4/07/17 84/07/1B	50-320 50-272	P Q	8408070153 8408070178	8408070149 8408070174	84/07/26 84/08/02	WASTE MG 50-244	T G
8408030252 8408030244	8408030251 8408030263	84/07/10 84/07/16	50-10 WASTE MOT	G C	8408070180 8408070197	8408070173 8408070187	84/07/31 84/07/31	50-329 50-202	A Q
8408030267	8408030257	84/07/11	50-272	Q.	B408070207	8408070201	84/07/27	50-416	Ū
8408030268 8408030270	8408030263 8408030263	84/07/16 84/07/16	WASTE MOT		8408070212 8408070215	8408070204	84/08/01	50-454	a
8408030275	8408030266	84/05/31	20-365	G	8408070214	8408070201 8408070213	84/07/27 84/07/30	50-416 50-454	G G
8408030282 8408060008	8408030277 8408060005	84/07/24 84/07/30	M18C 50-293	P	6408070217	8408070211	04/07/25	50-322	Н
8408060016	8708060005	84/07/30	50~293	P	8408070221 8408070231	8408070213 8408070226	84/07/30 84/07/09	50-454 40-8786	Q
8408060017 8408060025	8408060014 8408060018	84/07/20 84/07/24	CONTRACT		8408070237 8408070242	8408070232 8408070236	84/08/02 84/06/18	50-272 TOPREP	Q
9408060029	8408060021	84/07/31	50-259	P	8408070255	8408070251	84/07/31	50-244	P
8408060036 8408060037	8408060024 8408060031	84/07/30 84/07/24	50-341 CONTRACT	G.	8408070257 8408070258	9409070248 9408070251	84/07/31 84/07/31	50-244 50-244	P P
8408960039	8408060034 8408060038	84/07/25		s	8408070282	8408070275	84/0B/01	50-305	F
8408040040 8408040047	8408060045	84/06/19 84/07/19	WASTE MOT	•	8408070288 8408070291	8408070275 8408070287	84/08/01 84/08/03	50-352 50-352	F G
8408060048 8408060057	8408060041 8408060054	84/07/24 84/06/12	CONTRACT 50-382	Q.	B408070274 B408070304	8408070292 8408070300	84/07/31 84/07/30	50-305 50-219	F P
8408060073	8408060069	84/07/23	MIBC	-	B40B070309	8408070304	84/08/02	50-219	P
8408060077 8408060081	8408060069 8408060069	84/07/23 84/07/23	WIEC WIEC		8408070324 8408070327	8408070323 8408070324	84/08/01 84/08/01	50-354 50-275	G G
8408040083 8408040099	8408060069 8408060092	84/07/23 84/07/03	MISC 50-482	a	8408070330 9408070340	8408070328 8408070338	84/08/01	50-246 50-456	p O
8408060101	8408060095	84/08/01	50-373	F	8408070355	8408070353	84/07/18 84/08/01	50-412	ũ
8408060104 8408060111	8408060097 8408060106	84/07/31 84/07/20	50-413 WASTE MOT	P	8408070356 8408070360	8408070354 8408070357	84/08/02 84/07/31	50-341 50-280	G G
8408040115	8408060110	84/07/31		Q P	8408070345	8408070362	B4/07/30	50-443	F
840806011 <i>9</i> 8408060122	8408060117 8408060106	84/07/27 84/07/20	WASTE MOT		8408070375 8408070378	8408070370 8408070374	84/08/01 84/08/01	50-259 50-261	ь Б
8408040125 8408040138	8408060116 8408060102	84/07/23 84/07/27	TOPREP 50-206	ខ	8408070384 840807039⊋	8408070381 8408070387	84/07/27 84/07/24	50-400 50-269	K P

ACCESS I O	NUMBER				ACCESS10	N NUMBER			
ENCLOSURE	PR ENCIPAL DOCUMENT	DATE GSUEB	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	Υ
8408070398 8408070406 8408070409 8408070415 8408070419	8408070383 8408070400 8408070405 8408070412 8408070414	84/08/02 84/07/27 84/08/03 84/08/02 84/08/01	PR 50-338 50-390 50-352 50-412	F G F	8408080302 8408080303 8408080303 8408080307 8408080307	8408080299 8408080297 8408080278 8408080278 8408080278	84/08/04 84/07/30 84/07/31 84/07/31 84/07/31	50-341 NUREQ 50-401 50-401 50-401	FKKK
8408070423 8408070428 8408070433 8408070438 8408070439	8408070417 8408070417 8408070429 8408070431 8408070434	84/07/27 84/07/27 84/08/03 84/07/31 84/08/03	50-333 50-333 50-352 50-255 50-220	P Q P F	8408080312 8408080315 8408080319 8408080319 8408080320	8408080278 8408080278 8408080278 8408080314 8408080278	84/07/31 84/07/31 84/07/31 84/07/24 84/07/31	50-601 50-601 50-601 50-374 50-601	***
8408070441 8408070448 8408070450 8408070456 8408070457	8408070435 8408070442 8408070444 8408070446 8408070453	84/07/31 84/08/03 84/08/06 84/07/17 84/07/31	50-255 50-322 50-352 50-498 PRM	F Q Q A	8408080321 8408080322 8408080323 8408080330 8408080334	8408080317 8408080314 8408080278 8408080278 8408080333	84/08/01 84/07/24 84/07/31 84/07/31 84/08/01	CDNTRACT 50-374 50-401 50-401 PR	Р К К
8408070458 8408070460 .8408070462 8408070465 8408070478	8408070442 8408070452 8408070453 8408070446 8408070472	84/08/03 84/08/02 84/07/31 84/07/17 84/08/01	50-322 50-461 PRM 50-498 50-29	G G A P	8408080342 8408080343 8408080345 8408080346 8408080346	8408080278 8408080278 8408080278 8408080344 8408080278	84/07/31 84/07/31 84/07/31 84/07/30 84/07/31	50-601 50-601 50-601 50-354 50-601	K K K A K
8408070485 8408070502 8408070505 8408070511 8408070516	8408070483 8408070499 8408070499 8408070508 8408070515	84/07/31 84/07/20 84/07/20 84/07/27 84/07/31	50-313 50-346 50-346 50-344 50-244	P P P P	8408080383 8408080394 8408080404 8408080414 8408080423	8408080353 8408080353 8408080353 8408080353 8408080417	B4/07/20 B4/07/20 B4/07/20 B4/07/20 B4/08/06	50-245 50-245 50-245 50-245 50-322	0 0 0 0
8408070526 8408070532 8408080008 8408080025 8408080037	8408070524 8408070531 8408080005 8408080020 8408080031	84/07/09 84/07/20 84/07/31 84/07/06 84/07/26	50-244 50-275 CONTRACT CONTRACT 50-346		8408080432 8408080448 8408080449 8408080458 8408080461	8408080430 8408080212 8408080445 8408080453 8408080454	84/07/23 84/07/17 84/07/27 84/07/16 84/07/18	50-334 50-312	U 0 F F 0
8408080038 8408080064 8408080067 8408080087 8408080141	8408080034 8408080032 8408080039 8408080082 8408080138	84/07/20 94/07/31 94/07/26 84/07/26 84/07/30	COMMISSI CONTRACT CONTRACT 50-320 50-416	•	8408080464 8408080467 8408080478 8408080480 8408080480	6408080464 6408080463 6408080473 6408080476 6408080485	84/07/17 84/07/20 84/07/16 84/08/01 84/07/18	50-245 50-219 50-322 CONTRACT 50-295	g g g
8408080151 8408080155 8408080158 8408080157 8408080165	8408080147 8408080148 8408080152 8408080148 8408080152	84/07/18 84/07/03 84/07/27 84/07/03 84/07/27	70-734 50-373 50-313 50-373 50-313	P P P	8408080490 8408080494 8408080497 8408080501 8408080507	8408080481 8408080485 8408080474 8408080471 8408080502	84/07/18 84/07/18 84/07/20 84/07/27 84/07/18	50-289 50-295 50-344 50-275 CONTRACT	G G G
8408080164 8408080168 8408080170 8408080174 8408080180	8409080157 8409080142 8408080141 8408080171 8408080173	84/07/18 84/08/07 84/07/31 84/07/20 84/08/06	50-387 50-445 50-312 50-263 40-2061	0 0 P 0	8408080513 8408080515 8408080517 8408080521 8408080526	8408080491 8408080491 8408080491 8408080491 8408080523	84/07/27 84/07/27 84/07/27 84/07/27 84/07/17	50-275 50-275 50-275	0 0 0 0
8408080181 8408080172 8408080175 8408080176 8408080200	8408080171 8408080187 8408080188 8408080187 8409080187	84/07/20 84/08/02 84/07/18 84/08/02 84/08/02	50-243 50-395 50-454 50-395 50-395	0 K 0 K K	8408080527 8408080530 8408070013 8408070014	8408080523 8408080523 8408070001 8408070010 8408070011	84/07/31 84/07/17 84/07/25 84/07/26 84/07/31	50-352 50-341 50-313	Р О Р Р
8408080205 8408080207 8408080209 8408080213 8408080214	8408080198 8408080197 8408080204 8408080212 8408080187	84/08/02 84/08/02 84/07/19 84/07/17 84/08/02	50-454 50-395 50-220 50-334 50-395	F K Q Q K	8408070017 8408070021 8408070037 8408070037 8408070045	8408070016 8408070017 8408070034 8408070036 8408070043	84/07/24 84/07/25 84/07/05 84/07/18 84/07/27	50-344 50-278 50-277	G G G
8409080221 8409080226 8409080228 8409080232	8408080187 8408080187 8408080187 8408080187 8408080187	84/08/02 84/08/02 84/08/02 84/08/02 84/08/02	50-395 50-395 50-395 50-395 50-395	K K K K	8408090046 8408090048 8408090051 8408090053 8408090059	8408070041 8408070040 8408070036 8408070040 8408070056	84/07/31 84/07/19 84/07/18 84/07/19 84/07/31	50-277 50-387	Q Q Q F
8408080238 8408080240 8408080242 8408080244 8408080248	940 9080233 840 8080187 840 9080233 840 8080187 840 8080187	84/07/16 84/08/02 84/07/16 84/08/02 84/08/02	50-244 50-395 50-244 50-395 50-395	0 K Q K K	8408090061 8408090073 8408090074 8408090080 8408090081	8408070086 8408070070 8408070072 8408070075 8408070077	84/07/31 84/07/20 84/07/31 84/07/23 84/08/03	50-382 CDNTRACT 50-344	F G G P
8408080250 8408080251 8408080254 8408080256 8408080260	8408080243 8408080187 8408080187 8408080243 8408080187	84/07/18 84/08/02 84/08/02 84/07/18 84/08/02	50-287 50-395 50-395 50-287 50-395	0 K K 0 K	8408090088 8408090091 8408090092 8408090093 8408090105	8408070085 8408070086 8408070082 8408070070 8408070455	84/05/08 84/07/23 84/07/31 84/07/10 84/08/03	50-312 50-423 50-458	Q Q A Q A
8408080262 8408080265 8408080280 8408080284 8408080286	8409080187 8409080187 8409080275 8409080275 8408080279	84/08/02 84/08/02 84/07/30 84/07/30 84/07/31	50-395 50-395 50-413 50-413 50-401	X E E K	8408070106 8408070111 8408070113 8408070122 8408070124	8408070102 8408070107 8408070107 8408070120 8408310345	84/07/25 84/07/25 84/07/25 84/07/23 84/08/23	COMMISSIO COMMISSIO COMMISSIO 70-984 TOPREP	N
8408080287 8408080272 8408080275 8408080278 8408080301	8408080278 8408080278 8408080278 8408080278 8408080278	94/07/31 94/07/31 94/07/31 84/07/31 94/07/31	50-601 50-601 50-601 50-601 50-601	K K K K	8408070130 8408090142 8408090142 8408070154 8408070160	8408070121 8408070133 8408070135 8408070145 8408070150	84/07/17 84/07/20 84/07/24 84/08/07 84/07/11	50-213 CONTRACT 50-414	Q Q Q

ACCESSIO	N NUMBER				ACLESSI	ON NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	١٧	ENCL DEURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8408090165 8408090171 8408090177 8408090182	8408090162 8408090166 8408090169 8408090173	84/07/24 84/08/06 84/07/20	50-294 50-155 50-295	V P G	8409130027 8409130027 8409130032	8408130020 8408130020 8408130026	84/06/28 84/06/28 84/07/27	71-83 71-83 50-259 P
8408090189	8408090184	84/08/03 84/07/23	50-309 50-266	Q Q	8408130037 8408130079	8408130026 8408130077	84/07/27 84/07/13	50-259 P WASTE MGT
8408090194 8408090195 8408090201	8408090187 8408090192 8408090187	84/08/07 84/07/24 84/08/07	50-361 50-255 50-361	P G P	8408130081 8408130094 8408130101	8408130077 8408130091 8408130099	84/07/13 84/08/07 84/07/30	WASTE MGT 50-433 Q WASTE MGT
8408090202 8408090205	8408090196 8408090197	84/08/03 84/08/06	50-440 50-352	G	8408130108 8408130156	8408130103 8408130152	84/08/06 84/08/01	50~454 Q 50~461 A
8408090206 8408090209	8408090200 8408090198	84/08/01 84/08/07	50-445 50-314	G P	8408130143 8408130144	8408130153 8408130149	84/08/08 84/08/07	50-341 0 50-249 0
8408090213 8408090217 8408090223	8408090210 8408090212 8408090218	84/08/07 84/07/23 84/08/06	50-322 50-454 50-322	о о	8408130168 8408130173 8408130177	8408130164 8408130170 8408130164	84/07/18 84/08/08 84/07/18	50-413 P 50-331 P 50-413 P
8408090233 8408090236	8408090226 8408090229	84/08/03 84/08/07	50-352 50-352	G	8408130179	8408130164	84/07/18	50-413 P
8408090237	8408070235	84/08/01	50~338	T P	8408130204 8408130210	8408130194 8408130202	84/08/07 84/07/31	50-395 Q 50-416 U
8408090257 8408090263	8408070250 8408070258	84/08/03 84/08/06	50-219 50-352	e G	8408130212 8408130225	8408130205 8408130218	84/07/13 84/08/08	70-938 50-289 p
8408090281	8408090275	84/07/24	50-244	P	8408130224	8408130223	84/07/24	50-33B P
8408090298 8408090303	8408090293 8408090299	84/07/18 84/07/27	50~440 WASTE MO	G T	8408130227 8408130230	8408010061 8408010061	84/07/18 84/07/18	50-329 A 50-329 A
8408070304 8408070316	8408090293	84/07/18	50~440	G	8408130234	8408010061	84/07/18	50-329 A
8408090322	8408070311 8408070311	84/07/31 84/07/31	50~267 50~267	P P	8408130241 8408130244	8408010061 8408010061	84/07/18	50-329 A 50-329 A
8408090327 8408090330	8408090166 8408090315	84/08/06 84/07/16	50-15 <b>5</b> 50-322	P	8408130251	8408130248	84/08/07	20-3B5 6
8408090337 8408090409	8408090335 8408090407	84/08/02 84/07/27	50-73 50-397	P P	8408130255 8408130254 8408130258	8408010061 8408130248 8408130233	84/07/18 84/08/07 84/07/25	50-327 A 50-382 0 50-348 P
8408090410	8408090407	84/07/27	50-397	P	8408130240	8409130249	84/08/07	50-382 0
8408090412 8408090414	8408090407 8408090407	84/07/27 84/07/27	50~397 50-397	P	8408130269 8408130277	8408010061 8408130274	84/07/18 84/08/07	50-329 A 50-528 A
8408090420 8408090426	840809040B 840809040B	84/08/06 84/08/06	50-445 50-445	0	8409130280 8409130283	8408130275 8408130278	84/08/07 84/07/10	50-390 A 71-184
8408090434 8408090463	8408090408 8408090408	84/08/06 84/08/06	50-445 50-445	G G	8408130270 8408130272	8408010061 8408130278	84/07/18 84/07/10	50-329 A 71-184
8408090471 8408090480	8408070408 8408070408	84/08/04 84/08/06	50-445 50-445	G G	8408130278 8408130301	8408130287 8408010061	84/08/10 84/07/18	50-10 F 50-329 A
8408090488	8408090409	84/08/06	50-445	¢	8408130304	8408010041	84/07/18	50-329 A
8408070503 8408070510	8408090408 8408090504	84/08/0 <i>6</i> 84/08/01	50-445 CONTRACT	C	8408130311 8408130313	8408010061 8408130309	84/07/18 94/08/03	50-329 A 50-286 F
8408090512 8408090517	8408070408 8408070515	84/09/06 84/07/30	50-445 50-334	O P	8408130314	8408130308	84/08/01	CONTRACT
8408070524	8408090521	84/07/30	50-334	Р	8408130315 8408130320	8408010041 8408010041	84/07/18 84/07/18	50-329 Y 50-329 A
8408090534 8408090536	8408090533 8408090533	84/08/01 84/08/01	50-170 50-170	P P	8408130323	8408010061	84/07/18	50-329 A
8408090537	8408090533	84/08/01	50-170	P	8408130324 8408130327	8408130319 8408010061	84/08/09 84/07/18	50-362 0 50-327 A
8408090551 8408090564	840809 <b>0</b> 548 8408090562	84/07/31 84/07/23	CONTRACT PROJ		8408130326 8408130333	8408130319 8408130319	84/08/09 84/08/09	20-385 6 20-385 6
B40B100010 B40B100012	8408100004 8408100002	84/08/07 84/07/30	50-261 50-395	F F	8408130334 8408130337	8408010061	84/07/18	50-329 A
8408100017	B40B100014	84/07/09	50-278	R	8408130337	8408130329 8408130319	84/08/07 84/08/09	40-2061 50-382 0
8408100032 8408100034	8408100022 8408100026	94/08/03 94/08/06	50-244 50-483	G G	8408130349 8408130352	8408010061 9408130347	84/07/18 84/08/08	50-325 0
840B100037 840B100040	840B100029 840B100030	84/08/03 84/08/07	50-282 50-454	GI T	8408130354	8408130350	84/08/07 84/08/08	50-29 Q
8408100049	0400100045	84/08/06	30-366 346-08	P	8408130355 8408130356	8408130347 8408010061	84/07/18	50-322 G 50-329 A
8408100051 8408100052	8408100041 8408100044	84/08/07 84/08/03	70-1941 50-266	q	8408130359 8408130343	8408130347 8408130358	84/08/08 84/08/09	50-322 G 50-29 P
8408100054 8408100056	9408100016 8408100043	84/08/08 84/08/03	50-250 50-244	F G	8408130376 8408130381	8409130370 8408130380	84/08/09 84/08/09	50-155 F 70-143
8408100062	8408100057	84/08/07	50-285	Q	8408130382	8408130380	84/08/09	70-143
8408100067 8408100070	8408100065 8408100063	84/07/20 84/07/30	50-354 50-213	F	6408130383 8408130388	8408130380 8408130385	84/08/09 84/08/08	70-143 50-247 0
8408100075 8408100077	8408100069 9408100063	84/07/31 84/07/30	50-482 50-213	G P	8408130390 8408130395	8408130387 8408130391	84/08/07 84/08/08	50-346 G 50-346 G
8409100080	8408100074	B4/08/04	50-220	P	E408130400	B408130394	84/08/09	50-339 q
8408100081 8408100086	8408100076 8408100076	84/08/06 84/08/06	50-220 50-220	P	8408130403 8408130408	8408130374 8408130374	84/08/09 84/08/09	50-338 G
8408100101 8408100105	8408100089 8408100087	84/08/06 84/05/07		A F	8409130410 8409130411	8408130405 8408130407	84/08/08 84/08/07	50-287 Q 50-346 Q
8408100106	8408100087	84/08/06	50-461	Α	8408130413	8408130401	84/08/07	50-10 F
8408100111 8408100119	8408100103 8408100112	84/09/07 84/09/03	50~456	6 0	8408130416 8408130417	8408130414 8408130406	84/07/31 84/08/08	50-344 F 50-289 0
8408100120 8408100137	8408100103 8408100127	84/08/07 84/08/02		P A	8408130418 8408130420	8408130374 8408130415	84/08/09 84/04/13	50-336 G 50-454 G
8408100138 8408100144	8408100134 8408100133	84/08/05 84/08/08	50-255	P G	8408130429	8408130421	84/08/04	50-346 P
8408130021	B40B130020	94/06/28	71-83	•	8408130437 8408130438	8408130435 8408130433	84/08/02 84/08/09	CONTRACT 50-33B 0

ACCESSIO	N NUMBER				ACCESSIO	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC	٩Y	ENCLOBURE	PRINCIPAL DOCUMENT	DATE DAVED	SUBJECT CATEGORY	′
8408130439 8408130441 8408130442 8408130443	8408130436 8408130436 8408130440 8408130433	84/07/31 84/07/31 84/08/02 84/08/09	50-334 50-334 CONTRAC 50-338	þ	8408140286 8408140296 8408140300 8408140311	8408010061 8408010061 8408010061 8408060061	84/07/18 84/07/18 84/07/18 84/07/18	50-327 50-329	A A A
8408130445 8408130446	8408130444 8408130433	84/08/02 84/08/09	CONTRACT		8408140314 8408140319	8408140303 8408010061	84/08/08 84/07/18	50~3\$2	E A
8408130455 8408130507	8408130449 8408130502	84/07/26 84/07/27	50-445 70-1257	A	6408140320 6408140326	6408140303 6408140303	84/08/08 84/08/08		E
8408130511 8408130537	8408130502 8408130530	84/07/27 84/07/25	70~1257 50-346	Р	8408140347 8408140349	8408010061 8408210097	84/07/18 84/08/15	50-329	F
8409130545 8408130559	8408130530 8408130554	84/07/25 84/08/01	50-34 <i>6</i> 50-334	P	8408140352 8408140359	8408010061 8408010061	84/07/18 84/07/18		A
8408130540	8408130555 8408130561	84/08/03 84/08/01	PRM 1SE-06	Р	8408140363 8408140367	8408140356 8408010061	84/08/08 84/07/18		P A
8408130567 8408130597	8408130592	84/08/04	CONTRACT	•	8408140389	8408140372	84/08/07	50-237	٧
8408140012 8408140017	840 B 1400 1 1 840 B 1400 13	84/07/20 84/08/07	50~275 50~322	P T	8408140404 8408140413	8408140402 8408140410	84/08/10 84/09/10		Q P
8408140018 8408140023	8408140014 8408140014	84/08/09 84/08/09	50-400 50-400	T T	8408140415 8408140422	8408140411 8408140420	84/08/08 84/08/10	50-289 PR	P
840B140027	8408140014	84/08/09	50-400	۲	8408140423	8408140421	B4/08/03	50-458	Α
8409140031 8408140033	8408140014 8408140029	84/08/09 84/07/24	50-400 50-338	F	8408140433 8408140452	8408140427 8408140450	84/08/06 84/08/08		P G
B408140034	8409140028	84/08/09	50-456	G	B408140476	8408140469	84/04/24	71-9014	
8408140036 8408140038	8408140014 8408140028	84/08/09 84/08/09	50-400 50-456	T	8408140477 8408140480	8408140470 8408140469	84/08/13 84/06/26	50-322 71-9016	G
8408140039 8408140050	8408010061 8408010061	84/07/18 84/07/19	50~329 50~329	A	8408140485 8408140513	8408140469 8408010061	84/06/26 84/07/18	71-9016 50-329	A
B408140055	8408010061	84/07/18	50-329	Ą	8408140517	8408140510	84/07/26	CONTRACT	
8408140060 8408140065	8408010061 8408010061	84/07/18 84/07/18	50-327 50-327	A	8408140522 8408140526	8408010061 8408010061	84/07/18 84/07/18		A
8408140069 8408140070	8408010061 8408140064	84/07/18 84/08/09	50-329 50-400	A	8408140530 8408140535	8408010061 8408140532	84/07/18 84/08/06		A
B40B140071	8408010051	84/07/18	50-329	A	8408140537	8408010061	84/07/18	50-329	A
8408140075 8408140076	8408140064 8408010061	84/08/09 84/07/18	50-400 50-329	T A	8408140553 8408140554	8408010061 8408010061	84/07/18 84/07/18		A
B408140079 B408140081	8408010061 8408140064	84/07/18 84/08/09	50-329 50-400	A	8408140557 8408140361	8408010061 8408140558	84/07/18 84/08/07		A
8408140086	8409140064	84/08/09	50-400	T	8408140362	8408010061	84/07/18	50-329	٨
8408140093 8408140095	8408140064 8408140071	84/08/09 84/08/10	50-400 50-458	ď	8408140544 8408140545	8408140558 8408010061	84/08/07 84/07/18		P A
8409140102	8408010061	84/07/18	50-329	A	8408140966	8408010061	84/07/18	50-329	A
8408140110 8408140115	8408140103 8408140103	84/08/10 84/08/10	50-413 50-413	Ģ	8408140569 8408140570	8408140558 8408010061	84/09/07 84/07/18		P A
8408140122 8408140124	8408140119 8408140106	84/08/09 84/08/07	50~400 50~321	G P	8408140573 8408140575	8408010061 8408010061	84/07/18 84/07/18	50-329	A
8408140125	8408140119	84/08/09	50-400	Ç	8408150015	8408010061	84/07/18	50~329	A
8408140134 8408140144	8408010051 8408010051	84/07/18 84/07/18	50-329 50-329	A	8408150019	8408010061	64/07/18	50-327	A
B40B140151	8408140146	84/08/09	50-400	Ť	84081 50022 84081 50027	8408010061 840801 <b>0</b> 061	84/07/18 84/07/18	50~329	A
8409140152 8408140158	8408010061 8408010061	84/07/18	50-329	A	8408130029	8408010061	84/07/18		Α .
E40B140163	8408010061	84/07/18 84/07/18	50-329 50-329	A	8408150033 8408150042	8408010061 8408010061	84/07/18 84/07/18		A
8408140167 8408140169	8408140161 8408140156	84/08/09 84/08/09	50-244 50-374	F	8408150046	8408010061	84/07/18	50-327	Α
B408140170	8408010061	84/07/18	50-329	A	84081 50094 84081 50097	8408150071 8408150071	84/07/26 84/07/26		Q Q
8408140180 8408140185	8408140156 8408010061	84/08/09 84/07/18	50-374 50-329	Q A	8408150102 8408150110	8408150091 8408150107	84/07/26 84/07/26		Q G
840814019Q	840B140156	84/08/09	<b>50-374</b>	G	8408150114	8408150107	94/07/27	71-6346	
8408140194 8408140196	8408010061	84/08/07 84/07/18	50-206 50-329	P	8408150118 8408150125	8408150115 8408150121	84/08/07 84/07/16		F
8408140204 8408140207	8408140200 8408010061	84/09/10 84/07/18	TOPREP 50-329	A	8408150127	8408150119	84/08/13 84/08/13		Ţ
8408140213	8408010061	84/07/18	50-329	A	8408150132 8408150143	8408150119 8408150141	84/09/13 84/07/10	50-454 71-522	Т
8408140218 6408140220	8408010061 8408140214	84/07/18 84/08/10	50-329 50-250	Q.	8408150147 8408150154	8408150144 8408150151	84/08/01 84/08/14	WASTE MOT	P
8408140223 8408140226	8408010061 8408140214	84/07/18 84/08/10	50-327 50-250	A	8408150161	8408150156	84/07/27	70-143	_
8408140232	8408010061	84/07/18	50-329	Ā	8408150184 8408150228	8408150180 8408150225	84/08/13 84/08/09		P
8408140236 8408140241	8409140214 8408140229	84/08/10 84/08/09	50-250 50-454	G G	8408150236 8408150244	8408150233 8408150233	84/07/24 84/07/26	50-277	G G
8408140242 8408140245	8408010061 8408140239	84/07/18 84/08/09	50~3 <u>2</u> 9	A	8408150250	8408150246	84/08/08	XPORTLIC	_
8409140248	8408010061	84/07/18	50-293 50-329	A	8408150255 8408150258	8408150251 8408150256	84/07/25 84/07/24		Q Q
8408140253 8408140256	8408140214 8408140251	84/08/10 84/08/09	50-250 50-293	Ç P	8408150242 8408150271	8408150256 8408150264	84/07/24 84/07/24	50-443	Q Q
8408140258 8408140262	8408010061	84/07/18	90-329	Q	8408150275	8408150249	84/08/14		F
8408140263	8408140214 8408010041	84/08/10 84/07/18	50-250 50-327	Q A	84081 50293 84081 50299	6408150270 6408150273	84/07/25 84/07/25		Q Q
8408140271 8408140277	8408140214 8408140214	84/08/10 84/08/10	50-250 50-250	9	6408150301	8408150278	84/07/18	50-317	Œ
		2., 547.14		٠	8408150305	8408150298	84/07/18	50-317	Q.

ACCESSIO	N NUMBER					N NUMBER			
ENCLOBURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATEGO:		ENCLOSURE	PRINCIPAL DOCUMENT	DATE IBSUED	SUBJECT CATEGOR	
8408150317 8408150335	8408150312 8408150324 8408150337	84/07/23 84/07/17 84/07/05	50-269 50-269 WASTE MK	Q F	84081 50664 84081 50669 84081 50672	8408010061 8408010061 8408010061	84/07/18 84/07/18 84/07/18	50-329 50-329 50-329	A G
84081 50341 84081 50344 84081 50361	8408150337 8408150337 8408150359	84/07/05 84/07/05 84/08/06	WASTE ME XPORTLIC	)T	8408150673 8408150673	8408010081 8408010061	84/07/26 84/07/18	40-8027 50-329	A
8409150368 8409150370 8409150373	8408150366 8408150366 8408150372	84/07/25 84/07/25 84/05/16	50-272 50-272 50-313	G G	8408150477 8408150681 8408150682	8408010061 8408010061 8408010061	84/07/18 84/07/18 84/07/18	50~327 50-327 50-327	G A A
B408150373 B408150381	8408150372 8408150380	84/03/16 84/03/16 84/07/27	50-313 50-440	G G	84081 50683 84081 50683 84081 50686	8408010061 8408010061	84/07/18 84/07/18	50-327 50-327	A
8408150394 8408150401	8408150386 8408150392	84/07/27 84/07/26	50-454 50-254	G G	84081 50687 84081 50670	8408010061 8408010061	84/07/18 84/07/18	50-32 <del>9</del> 50-32 <del>9</del>	A
8408150406 8408150407 8408150417	84081 50399 84081 50398 84081 50414	84/07/25 84/07/27 84/07/26	50-266 70-371 50-445	a	8408150692 8408150693 8408150694	8408010061 8408130688 8408010061	84/07/18 84/07/27 84/07/18	50-329 50-245 50-329	A G S
8408150424 8408150440	8408150409 8408150414	84/07/25 84/07/26	50~277 50-445	G G	84081 50495 84081 50498	8408010061 8408010061	84/07/18 84/07/18	50-329 50-329	A R
8408150455 8408150475	84081 50453 84081 50471	84/07/26 84/07/27	50-333 50-341	G G	6408150700 8408150701	8408010061 8408150697	84/07/18 84/07/27	50-329 50-286	A G
B40B150476	8408150473	84/08/14	20-355	Т	8408150702	8408010061	84/07/18	50-329	0
8408150485 8408150487	8408150473 8408150482	84/08/14 84/07/27	50-322 50-454	T G	8408150706 8408150709	8408010061 8408010061	84/07/18 84/07/18	50-327 50-327	A
8408150498 8408150505	8408150473 8408150473	84/08/14 84/08/14	50-322 50-322	T T	8408150710 8408150712	8408010061 8408010061	84/07/18 84/07/18	50-327 50-327	A
8408150507	8408150502	84/07/27	50-461	œ	8408150714	8408010061	84/07/18	50-329	A
8408150511 8408150514	8408150502 8408150473	84/07/27 84/08/14	50-461 50-322	G T	8408150715 8408150716	8408150711 8408010061	84/07/27 84/07/18	50-317 50-329	⊕ A
8408150515 8408150530	8408150510 8408150473	84/07/20 84/08/14	50-382 50-322	G T	8408150718 8408150720	8408010061 8408010061	84/07/18 84/07/18	50-329 50-329	A
8408150533	8408150531	84/08/01	WASTE MG	Т	8408150721	8408150711	84/07/27	50-317	Q.
8408150337 8408150541	84081 50537 84081 50537	84/07/27 84/07/27	50-333 50-333	g G	8408150723 8408150725	8408010061 8408010061	84/07/18 84/07/18	50-32 <del>7</del> 50-329	A
8408150546 8408150547	8408150544 8408150544	B4/07/26 B4/07/26	50-263 50-263	Q.	84081 50727 84081 50728	8408010061 8408010061	84/07/18 84/07/18	50-327 50-327	A
8408150540	8408010061	84/07/18	50-329	Ā	8408150727	8408010061	84/07/18	50-329	A
8408150566 8408150569	8408010061 8408150565	84/07/18 84/08/03	50-329 50-346	A P	8408150731 8408150732	8408010061 8408010061	84/07/18 84/07/18	50-329 50-329	A
8408150571 8408150572	8408010061 8408150568	84/07/18 84/06/29	50-329 WASTE MG	A	8408150734 8408150735	8408010061 8408010061	84/07/18 84/07/18	50-329 50-329	A
8408150577	8408010061	84/07/18	50-329	A	B40B1 30734	8408150733	84/07/31	71-9073	^
8408150580 8408150585	8408150579 8408150579	84/07/26 84/07/30	50-29 50-271	Q. P	9409150737 9409150738	8408010061 8408010061	84/07/18 84/07/18	50-329 50-329	A
8408150584 8408150587	8408010061 8408130583	84/07/18 84/07/24	50-329 70-1151	A	84081 50739 84081 50740	8408150733 8408010061	84/07/31 84/07/18	71-9073 50-329	A
8408150593	840815058B	84/08/02	50-254	P	8408150741	8408010061	84/07/18	50-329	Ä
8408150595 8408150597	8408010061 8408150588	84/07/18 84/08/02	50-327 50-254	A	8408150742 8408150743	8408150733 8408010061	84/07/31 B4/07/18	71-9073 50-329	A
8408150400 8408150403	8408150594 8408010061	84/07/31 84/07/18	71-9016 50-329	R	8408150744 8408150745	8408150733 8408010061	84/07/31 84/07/18	71~9073 50~329	A
8408150604	8408150599	84/08/01	50-271	P	B408150747	8408010061	84/07/18	50-329	Ä
8408150404 8408150408	8408150599 8408010061	84/08/01 84/07/18	50-271 50-329	P A	8408150749 8408150750	8408010061 8408010061	84/07/18 84/07/18	50-329 50-329	A
8408150412 8408150413	8408010061 8408150609	84/07/18 84/08/03	50-329 50-333	Ē	840B130751 840B130752	8408010061 8408010061	84/07/18 84/07/18	50-329 50-329	A
8408150615	8408150409	84/08/03	50-333	þ	8408160034	8408160033	84/08/09	50-273	P
8408150616 8408150617	8408010061 8408010061	84/07/18 84/07/18	50-329 50-329	A	8408160037 8408160045	8408160026 8408160041	84/07/26 84/08/09	50-445 50-293	Q P
8408150622	8408010061	84/07/18	50-329	g	B408160056	8408140052	B4/08/10	50-271	P
8408150423 8408150424	8408010061	84/07/31 84/07/18	50-293 50-329	Ā	8408160070 8408160072	8408160062 8408160067	84/08/06 84/08/07	50-237 50-483	P
8408150626 8408150630	840801 <b>0</b> 061 8408 <b>010</b> 061	84/07/18 84/07/18	50-329 50-329	A	8408160082 8408160107	8408160073 8408160102	84/07/27 84/07/24	50-27 50-317	Q Q
8408150633	8408010061	84/07/18	50-329	œ	840B160113	8408160106	84/08/13	50-445	Q
8408150635 8408150635	8408150631 8408010061	84/07/24 84/07/18	50-272 50-329	Q A	8408160115 8408160131	8408160102 8408160106	84/07/24 84/08/13	50-317 50-445	G G
8408150639 8408150640	8408010061 8408010061	84/07/18 84/07/18	50-3 <u>2</u> 9 50-329	G G	8408140132 8408140145	8408160129 8408160139	84/08/10 84/08/10	50-324 50-10	Q Q
8408150643 8408150644	8408010061 8408010061	84/07/18 84/07/18	50-329 50-329	A	8408160153 8408160158	8408160141 8408160141	84/08/13 84/08/13	50-445 50-445	ö
B408150646	84081 50639	84/07/27	50-341	Ğ.	8408160166	8408160163	84/08/09	50-410	Đ
8408150648 8408150651	B408010061 B408010061	84/07/18 84/07/18	50-329 50-329	A	9408140178 8408140187	8408140171 8408160171	84/08/13 84/08/13	50-445 50-445	0
8408150452 8408150453	8408010061 8408150650	84/07/18 84/07/24	50-329 50-354	A	8408140170 8408140173	8408140184 8408140184	84/07/30 84/07/30	50-483 50-483	Q Q
B40B150654	840B1 50647	84/07/30	71-9014	-	8408160204	8408160201	84/07/23	50-445	Q.
8408150655	84081 50647 840801 0061	84/07/23	50-445 50-329	Q A	840B140206	8408140198	84/08/10	50-373	Q.
8408150454 8408150458	8408010061	84/07/18 84/07/18	50-329	8	8408160216 8408160217	8408160212 8408160212	84/07/30 B4/07/30	50-454 50-454	G G
8408150662 8408150665	8408010061 8408010061	84/07/18 84/07/18	50-329 50-329	A	8408160224 8408160226	8408160210 8408160220	84/08/13 84/06/28	50-322 50-382	G G

ACCESSION					ACCESS10	и мимвея			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 18SVED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE IBSUED	SUBJECT CATEODE	
8408160229	8408160222	84/07/27	50-263	 P	8408170205	8408010061	84/07/18	50-329	G
8408160233 8408160237	8408160222 8408160230	84/07/27 84/07/30	50-263 50-458	P G	8408170223 8408170232	8408010061 8408010061	84/07/18 84/07/18	50-329 50-329	G G
8408160246 8408160240	8408160235 8408160251	84/08/01 84/08/01	50-245 50-322	0	8408170236 8408170237	8408010061 8408170233	84/07/18 84/08/14	50-329 50-335	g g
8408160264 8408160271	840B160257	84/06/29	DRG DRG		8408170243	8408170227	84/08/08	50-373 50-373	P P
8408160272	8408160257 8408160266	B4/06/29 B4/07/30	50-334	œ	8408170247 8408170253	9408170227 9408010061	84/08/08 84/07/18	50-329 50-329	A
8408160273 8408160275	8408160267 8408160257	84/07/20 84/06/29	50-275 DRG	F	8409170257 8408170260	8408010061 8408010061	84/07/18 84/07/18	50-327	A
B408160280 B408160281	8408140257 8408140270	84/06/29 84/07/20	ORG 50-311	a	8408170262 8408170265	8408170252 8408170263	84/08/16 84/08/09	50-263 50-295	P G
84 081 60283 84 081 60288	8408160278 8408160257	84/08/07 84/06/29	WASTE MG		8408170268 8408170271	8408010061 8408010061	84/07/18 84/07/18	50-329 50-329	F G
8408160292	8408160257	84/06/29	ORG		8408170274	8408010061	84/07/19	50-329	ā
8408160317 8408160325	8408160310 8408160319	84/08/03 84/08/07	70-143 50-250	Р	B408170274 B408170279	8408010061 8408010061	84/07/18 84/07/16	50-329 50-329	8 A
6408160327 8408160331	8408160324 8408160329	84/07/30 84/07/30	50-346 50-266	G G	8408170284 8408170292	8408010051 8408010051	84/07/18 84/07/18	50~329 50-329	A
6408160338	8408160334	84/07/30	50-341	Q	8408170297	8408010061	84/07/18	50-329	Ť
8408160340 8408160341	8408160335 8408160334	84/08/10 84/07/30	50-445 50-341	A Q	8408170304 8408170312	8408010061 8408010061	84/07/18 84/07/18	50-329 50-329	Ţ
8408140354 8408140340	8408160353 8408160355	84/08/14 84/07/09	50-244 50-352	P F	8408170313 8408170318	8408170308 8408170308	84/08/10 84/08/10	50-395 50-395	Ÿ
8408160361	840B160353	84/08/14	50-244	P	8408170320	B408010061	84/07/18	50-327	À
8408160369 8408160372	8408160368 8408160367	84/08/14 84/08/14	50-293 50-220	F P	8408170321 8408170326	8408170319 8408170319	84/08/13 84/08/13	50-454 50-454	T T
8408160373 8408160378	8408160371 8408160371	84/08/09 84/08/09	50-443 50-443	A A	8408170327 8408170330	8408170322 8408170325	84/08/13 84/08/15	50-315 50-289	F G
8408140384	B40B160377	84/07/27	TOPREP		8408170339	840B170334	84/08/14	50-354	ā
8408160390 8408160397	8408140386 8408160395	84/07/31 84/08/14	50~458 50~206	A	8408170342 8408170343	8408170334 8408170334	84/08/14 84/08/14	50-354 50-354	G G
8408160403 8408160405	8408160394 8408160404	84/08/10 84/08/08	50-204 50-50B	8 A	8408170358 8408170360	8408010061 8408010061	84/07/18 84/07/18	50-329 50-329	Ā
8408160407	8408160404	84/08/08	50-50B	Ä	8408170365	8408010061	84/07/18	50-329	A
8408160411 8408160413	8408160404 8408160404	84/08/08 84/08/08	50-50B 50-50B	A	84081 70367 84081 70372	8408010061 8408010061	84/07/18 84/07/18	50-329 50-329	A
8408160414 8408160426	8408160404 8408160424	84/08/08 84/07/30	50-508 50-259	A	8408170374 8408170377	8408010061 8408010061	84/07/18 84/07/18	50-329 50-329	K A
8408160427	8408160424	84/07/30	50-259	P	8408170387	8408170383	84/08/15	40-2041	
8408160432 84081604 <b>5</b> 7	8408160428 8408160455	84/08/01 84/06/20	50-245 50-458	Q G	8408170389 8408170393	94091703B3 8409170392	84/08/15 84/03/30	40-2061 70-143	
8408160466 8408160469	8408160461 8408160465	84/08/10 84/08/02	70-1308 50-254	P	8408170394 8408170399	8408170392 8408170398	84/03/30 84/07/31	70-143 50-295	F
84 OB1 60472	840B160461	84/08/10	70-1308	•	8408170408	8408170406	84/08/03	XPORTLIC	
840B160475 840B160495	8408160470 8408160485	84/07/31 84/07/30	WASTE MG	T G	8408170415 8408200017	8409170413 8408200014	84/07/27 84/07/31	WASTE MO	e e
B40B160500 B40B160502	8408140485 8408140501	84/07/30 84/08/02	50-445 50-445	ē T	840820023 AE00028048	8408200014 8408200032	84/07/31 84/07/31	50-289 50-387	Ģ G
B40B160504	8408160498	84/07/23	50-313	Ġ	8408200041	8408200032	84/07/31	50-387	Ğ
8408160507 8408160513	8408160507 8408160507	84/07/23 84/07/23	50-267 50-267	Q ()	8408200052 8408200069	8408200043 8408200059	84/07/30 84/08/08	50-272 50-269	G P
8408160515 8408160516	8408140511 8408140507	84/07/30 84/07/23	50-458 50-247	0	840820090 8408200123	8408200086 8408200117	84/08/13 84/08/15	71-240 50-482	Α
B408160523	8408160520	84/07/27	50-482	ā	8408200155	8409200149	84/08/02	50-269	P
8408170023 8408170046	8408170021 8408170041	84/08/03 84/07/30	71-6244 50-334	F	8408200157 8408200164	8408200154 8408200161	84/07/26 84/08/02	WASTE MO	¥T P
8409170056 8408170081	8408010052 8408010061	84/08/14 84/07/18	50-354 50-329	F A	8408200169 8408200173	8408200161 8408200161	84/08/02 84/08/02	50-336 50-336	P P
8408170090	8408010061	84/07/18	50-329	8	8408200184	8408200182	84/08/08	50-255	ā
8408170098 8408170102	8408010061 8408010061	84/07/18 84/07/18	50-327 50-327	T A	8408200224 8408200227	8408200217 8408200221	84/08/16 84/08/03	50-528 50-454	F
8408170117 8408170117	B40B170109 B40B170109	84/07/18 84/07/18	50-443 50-443	Q Q	8408200235 8408200241	8408200225 8408200233	84/08/10 84/08/02	50-388 50-155	นั้ ด
8409170117	8408170107	84/07/18	50-443	ā	8408200263	B408200225	84/08/10	50-416	Ģ
8408170117 8408170141	8408010061 8408010061	84/07/18 84/07/18	50-329 50-329	Q A	8408200267 8408200267	8408200225 8408200244	84/08/10 84/08/02	50-416 50-259	G P
8408170143 3408170145	8408170130 8408010061	84/08/07 84/07/18	50-329 50-206	P	8408200271 8408200279	8408200225 8408200225	84/08/10 84/08/10	50-416 50-369	Q U
3408170147	840B170144	84/08/02	50-344	P	8408200280	8408200264	84/08/02	50-259	P
3408170150 3408170152	8408170144 8408010061	84/08/02 84/07/18	50-344 50-329	P	8408200282 8408200288	8408200274 8408200285	84/08/13 84/08/10	50-289 50-328	H S
34 OB1 701 55 84 OB1 701 57	8408170130 8408010061	84/08/07 84/07/18	50-206 50-329	P	8408200292 8408200304	8408200270 8408200277	84/08/02 84/08/02	50-458 50-498	Q Q
8408170166	8408010051	84/07/18	50-327	Ä	8406200318	8408200313	84/08/13	50-275	ã
8408170174 8408170181	840801 0061 840801 0061	84/07/18 84/07/18	50-329 50-329	G G	8408200321 8408200325	840820031 <i>6</i> 8408200320	84/08/02 84/08/01	50-458 50-317	Q P
B408170187 B408170195	8408010061 8408010061	84/07/18 84/07/18	50-329 50-329	Ā	8408200326 8408200327	8408200316 8408200320	84/08/02 84/08/01	50-458 50-317	Q. P
B408170203	8409170178	84/08/13	50-266	ũ	8408200334	8408200112	84/08/16	50-528	F

BION	NUMBER				ACCESS10N				
=	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEOOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 18SUED	SUBJECT CATEGORY	_
50 51 55 56 73	8408200359 8408200359 8408200364 8408200364 8408200390	84/08/02 84/08/02 84/07/31 84/07/31	50-285 50-285 50-354 50-354 50-260	P G G P	8409210379 8408210381 8408210382 8408210384 8408210386	8408010051 8408210358 8408210375 8408010051 8408010051	84/07/18 84/08/02 84/07/27 84/07/18 84/07/18	50-329 A 50-352 G TOPREP 50-329 A 50-329 A	4
)1 24 32 11	8408200400 8408200414 8408200426 8408200437 8408200433	84/06/29 84/08/09 84/07/30 84/08/13 84/08/14	40-2259 50-269 WASTE MG 50-260 50-352	F	8408210387 8408210391 8408210392 8408210393 8408210394	8408210375 8408010061 8408010061 8408210375 8408210368	84/08/16 84/07/18 84/07/18 84/08/16 84/08/02	50-338 P 50-329 Q 50-329 A 50-338 P 50-352 Q	) }
7  14  日  4  1	8408200433 8408200449 8408200446 8408200461 8408200469	84/09/14 84/08/08 84/08/20 84/08/19 84/08/13	50-352 50-352 50-454 50-188 50-423	0 U T E E	8408210397 8408210398 8408210401 8408210404 8408210409	8408010061 8408010061 8408010061 8408010061 8408210403	84/07/18 84/07/18 84/07/18 84/07/18 84/08/15	50-329 A 50-329 A 50-329 A 50-329 A	
5 17 19 19	8408200470 8408200476 8408200484 8408200480 8408200485	84/07/31 84/07/30 84/07/31 84/07/31 84/08/14	WASTE MO 50-29 WASTE MO XPORTLIC	G F	8408210410 8408210411 8408210414 8408210418 8408210421	8408010061 8408010061 8408010061 8408010061 8408010061	84/07/18 84/07/18 84/07/18 84/07/18 84/07/18	50-329 A 50-329 A 50-329 A 50-329 A 50-329 A	
741B0	8408200490 8408200495 8408200499 8408200510 8408200510	84/08/14 84/08/01 84/08/15 84/08/01 84/08/01	50~400 50~354 50~413 50~247 50~247	e e c c a	8408210425 8408210426 8408210427 8408210430 8408210433	8408010061 8408210419 8408210420 8408010061 8408010061	84/07/18 84/08/16 84/08/14 84/07/18 84/07/18	50-329 A 50-29 P 50-352 Q 50-329 A 50-329 A	1
4 6 3 7	8408200510 8408200540 8408200563 8408200587 8408200590	84/08/01 84/08/09 84/08/09 84/08/13 84/08/14	50-247 50-458 XPORTLIC 50-338 CONTRACT	e D	9408210436 9408210446 8408210449 8408210450 8408210451	8408210424 8408010061 8408210443 8408010061 8408210443	84/08/16 84/07/18 84/08/13 84/07/16 84/08/13	50-333 G 50-329 A 50-286 P 50-329 A 50-286 P	
0 4 5 7	8408200577 8408200602 8408210003 8408210001 8408210003	84/08/15 84/08/14 84/08/09 84/08/14 84/08/09	50-528 CONTRACT 50-259 50-10 50-259	F P F P	8408210453 8408210454 8408210455 8408210461 8408210463	8408010061 8408010061 8408010061 8408010061	84/07/18 84/07/18 84/07/18 84/07/18 84/07/18	50-329 A 50-329 E 50-329 A 50-329 A 50-329 A	
20026	8408210009 8408210009 8408210009 8408210024 8408210042	84/08/20 84/08/10 84/08/10 84/08/14 84/06/12	50-219 50-325 50-325 CONTRACT 50-206	P P P	8408210464 8408210467 8408210471 8408210478 8408210478	8408010061 8408210468 8408210470 8408210477 8408210486	84/07/18 84/08/16 84/08/17 84/06/15 84/08/15	50-327 G 50-336 G 50-461 G State Prog TOPREP	1
7 1 5 3	8408210040 9408210054 8408210054 8408210062 8408210062	84/08/14 84/08/13 84/08/13 84/08/10 84/08/10	CONTRAC') 50-302 50-302 50-312 50-312	P P P	8408210495 8408210496 8408210501 8408210502 8408210503	8408210494 8408210494 8408210494 8408210499 8408210500	84/08/01 84/08/01 64/08/01 84/08/16 84/04/02	50-245 G 50-245 G 50-245 G 50-231 P 50-498 A	)
5 1 1 7	8408210079 8408210070 8408210110 8408210110 8408210101	84/07/25 84/08/16 84/07/31 84/07/31 84/08/14	50-341 50-498 40-2259 40-2259 50-116	A q	8408210517 8408210518 8408210520 8408210549 8408210555	8408210515 8408210513 8408210513 8408210546 8408210546	84/08/01 84/08/16 84/08/16 84/08/07 84/08/07	50-336 Q 50-352 A 50-352 A 50-171 R 50-171 R	
3 1 1	8408210110 8408210115 8408210129 8408210129 8408210129	84/07/31 84/07/30 84/08/03 84/08/03 84/08/03	40-2259 WASTE MO 40-4492 40-4492 40-4492	r	8408210376 8408210382 8408220037 8408220064 8408220070	8408210567 8408210567 8408010061 8408010061	84/08/10 84/08/10 84/07/18 84/07/18 84/07/18	50-302 P 50-302 P 50-329 Q 50-329 T 50-329 A	
, , ,	8408210141 8408210145 8408210183 8408210187 8408210183	84/07/24 84/08/14 82/02/26 84/07/28 82/02/26	50-142 50-206 70-36 70-303 70-36	Q P	8408220071 8408220078 8408220080 8408220081 8408220085	8408220051 8408010061 8408220075 8408220076 8408010061	84/08/14 84/07/18 84/08/02 84/08/13 84/07/18	50-528 0 50-327 0 CONTRACT WASTE MOT 50-327 A	
] ; ] !	8408210173 8408210175 8408210238 8408210256 8408210256	84/08/14 84/08/16 84/08/02 84/08/14 84/08/14	50-374 50-366 50-247 50-331 50-331	Q G I I	8408220090 8408220099 8408220112 8408220156 8408220157	8408220073 8408220106 8408220150 8408220152	84/07/18 84/08/20 84/08/16 84/08/10 84/07/19	50-329 A 50-409 P 50-454 F CONTRACT 50-458 Q	
,	8408210254 8408210277 8408210307 8408210311 8408210327	84/08/14 84/08/15 84/08/20 83/11/01 84/08/15	50-331 50-333 50-255 50-498 50-155	I Q P A Q	9408220168 8408220208 8408220217 8408220252 8408220256	8408220201 8408220201 8408220215 8408220247 8408220247	84/08/15 84/08/15 84/08/10 84/07/31 84/07/31	50-352 A 50-269 K Waste Mot 50-382 G 50-382 G	
	8408210327 8408210336 8408210346 8408210342 8408210305	84/08/15 84/08/16 84/08/13 84/08/15 84/08/16	50-155 50-454 50-302 50-456 50-382	0 0 F G A	8408220263 8408220302 8408220310 8408220315 8408220316	8408220258 8408220274 8408220274 8408220274 8408220313	84/08/20 84/08/15 84/08/15 84/08/13 84/08/15	50-267 G ORG ORG ORG 50-313 P	
	8408010061 8408210365 8408210368 8408210366 8408010061	84/07/18 84/08/14 84/08/02 84/08/17 84/07/18	50-327 50-413 50-352 50-358 50-327	A P Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q	8408220321 8408220330 8408220365 8408220371 8408220373	8408220304 8408220324 8408220343 8408220367 8408220366	84/08/13 84/08/20 84/08/16 84/08/20 84/08/20	50-454 E 50-213 P 50-289 P 50-445 T 50-289 Q	

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER

ACCESS 10					ACCESSI	ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE IBSUED	SUBJECT		ENCLOSURE	PRINCIPAL DOCUMENT	DATC 198VED	SUBJECT CATEGOR	RY
8408220374 8408220380	8409220367 8408220367	84/08/20 84/08/20	50-445 50-445	T	8408230365 8408230371		84/08/20 84/08/20 84/08/20	50-354 50-354 50-219	C K P
8408220381 8408220385 8408220387	8408220367 8408220367 8408220384	84/08/20 84/08/20 84/08/02	50-445 50-445 CONTRACT	T	8408230385 8408230391 8408230397	8408230389 8408230390	84/08/16 84/08/16	50-341 50-445	F F
8408220398 8408220393	8408220367 8408220367	84/08/20 84/08/20	50-445 50-445	T T	B408230399 B408230400	8408230398 8408230390	84/08/17 84/08/16	50-348 50-445	p
8408220374 8408220377 8408220400	8408220367 8408220367 8408220397	84/08/20 84/08/20 84/07/18	50-445 50-445 CONTRACT	T T	8408230440 8408230457 8408230459	8408230436 8408230456 8408230456	84/08/16 84/08/15 84/08/15	50-287 50-267 50-267	H R R
8408220403	8408220367	84/08/20 84/07/18	50~445 CONTRACT	т	8408230465 8408230466	8408230461 8408230461	84/07/23 84/07/23	50-265 50-265	Q. Q.
8408220404 8408220405 8408220412	8408220397 8408220367 8408160313	84/08/20 84/08/07	50-445 50-445	T Q	8408230470 8408230479 8408230478	8408230465 8408230472 8408230472	84/08/09 84/07/31 84/07/31	50-344 40-8102 40-8102	Р
B408220415 B408220419	8408160313 8408160313	84/08/07 84/08/07	50-445 50-445	Q Q	8408230480	8408230474	84/08/03	50-358	G
8408220424 8408220448 8408220500	8408140313 8408220444 8408220474	84/08/07 84/08/16 84/07/31	50-445 50-320 50-382	Q P Q	8408230481 8408230492 8408230493	8408230472 8408230487 8408230487	84/07/31 84/08/02 84/08/02	40-B102 50-309 50-309	Q Q
8408220501	8408220497	84/08/07	50-352	F	8408230497 8408230504	8408230489 8408230484	84/07/26 84/08/16	50-263 CONTRACT	Gi T
8408220530 8408220531 8408230012	6408220527 6408220527 6408230008	84/08/03 84/08/03 84/08/20	50-277 50-277 50-275	P P	8408230512 8408230522	8408230502 8408230471	84/08/03 84/07/05	50-329 50-267	G
8408230013 8408230043	8408230010 8408230038	84/07/31 84/08/11	50-298 WASTE MG	T	8408230551 8408230555	8408230549 8408230549	84/08/03 84/08/03	50-254 50-254	ä
9408230063 8408230087 9408230070	8408230056 8408230078 8408230083	84/08/15 84/07/30 84/08/17	50-272 50-312 50-354	H 0 0	8408230558 8408230563 8408230567	8408230553 8408230562 8408230566	84/08/08 84/08/16 84/08/02	50-275 XPORTLIC 50-293	F G
B40B230070 B40B230078	840 8230082 840 8230094	84/08/03 84/08/10	50~293 50-219	G G	8408230547 8408240010	8408230566 8408240007	84/08/02 84/07/10	50-293 50-261	Q.
8408230101 8408230103	B408230094 8408230093	84/08/10 84/08/20	50-219 50-261	G P	8408240017 8408240020 8408240026	8408240015 8408240015 8408240021	84/08/02 84/08/02 84/08/16	50-317 50-317 50-382	P P Q
8408230105 8408230108 8408230112	8408230097 8408230097 8408230097	84/08/07 84/08/07 84/08/07	50-327 50-327 50-327	P P	8408240026 8408240076 8408240085	8408240021 8408240082	84/08/03 84/07/24	50-334 50-255	G G
8408230114 8408230119	8408230097 8408230097	84/09/07 84/08/07	50-327 50-327	P P	8408240088 8408240094	8408240082 8408240087	84/07/24 84/08/17	50~255 CONTRACT	
8408230122 8408230131 8408230133	8408230117 8408230097 8408230130	84/08/20 84/08/07 84/08/03	50-241 50-327 50-277	P P O	8408240095 8408240124 8408240128	8408240091 8408240118 8408240129	84/08/21 84/08/17 84/07/27	50~241 50~331 ga799	Q P
8408230136 8408230142	8408230130 8408230141	84/09/03 84/09/06	50-277 50-341	Q Q	8408240131 8408240134	8408240125 8408240132	84/07/27 84/08/07	0A779 50-329	R
8408230144 8408230145 8408230147	8408230141 8408230137 8408230146	84/08/06 84/08/01 84/08/04	50-341 50-271 50-409	0 0	8408240136 8408240140 8408240143	8408240132 8408240125 8408240132	84/08/07 84/07/27 84/08/07	50-329 0A999 50-329	R
B408230152 B408230155	8408230147 8408230151	84/07/20 84/08/17	50-445 50-251	G G	8408240144 8408240148	8408240136 8408240132	84/08/20 84/08/07	50~329 50-329	G R
8408230157 8408230158	8408230153 8408230151	84/08/03 84/08/17	50-352 50-251	G G	8408240152 8408240157 8408240159	8408240132 8408240115 8408240132	84/08/07 84/08/13 84/08/07	50-327 50-206 50-327	R S
8408230161 8408230166	8408230151 8408230151	84/08/17 84/08/17	50-251 50-251	Q Q	8408240166	8408240163	84/08/08	40-299	ĸ
8408230171 8408230180 8408230184	8408230164 8408230167 8408230172	84/08/16 84/08/13 84/07/30	50-266 50-257 50-317	F G P	8408240178 8408240180 8408240183	8408240175 8408240175 8408240175	84/07/25 84/07/25 84/07/25	40-8769 40-8768 40-8768	
8408230191 8408230192	9408230172 8408230167	84/07/30 84/08/13	50-317 50-259	P Q	8408240197 8408240198	8408240172 8408240175	84/08/07 84/08/07	40-277 40-8698	
8408230196 8408230198	8408230183 8408230193	84/08/15 84/08/17	70-1450 40-791		8408240201 8408240205 8408240223	8408240172 8408240177 8408240220	84/08/07 84/08/20 84/08/06	40-299 50-305 50-213	P G
8408230208 8408230211	8408230167 8409230204	84/08/13 84/07/24	50-259 50-315	G G	8408240226	8408240220	84/08/06	50-213	ā
8408230219 8408230225 8408230230	8408230167 8408230167 8408230226	84/08/13 84/08/13 84/08/01	50-259 50-259 50-220	G G	8408240231 8408240235 8408240237	8408240220 8408240105 8408240233	84/08/04 84/08/20 84/08/06	50-213 50-331 50-410	О Р
8408230233 8408230234	8408230220 8408230227	84/07/26 84/07/31	50-483 50-409	G G	8408240237 8408240242	8408240224 8408240224	84/08/16 84/08/16	50-413 50-413	I
8408230235 8408230238	9408230226 9408230227	84/08/01 84/07/31	50-220 50-409	Q Q	9409240248 8409240253 8408240257	8408240247 8408240233 8408240230	84/08/20 84/08/06 84/08/22	50-445 50-410 50-219	T G G
8408230248 8408230248 8408230252	8408230167 8408230242 8408230245	84/08/13 84/08/03 84/08/06	50-259 50-322 50-454	Q Q	8408240263 8408240281	8408240261 8408240266	84/08/21 84/08/23	50-528 50-528	A F
8408230255 8408230266	8408230249 8408230263	84/08/20 84/08/21	50-324 50-315	Q P	8408240288 8408240297	8408240273 8408240274	84/08/15 84/08/21	50~354 50-361	E P
8408230284 8408230285 8408230277	8408230275 8408230276 8408230292	84/08/17 84/08/01 84/08/13	50-392 50-293 50-352	Q Q E	8408240319 8408240321 8408240330	8408240316 8408240314 8408240328	84/08/21 84/08/03 84/08/13	50-261 50-461 50-250	G G F
8408230298 8408230301	8408230293 8408230296	84/08/06 84/08/16	50-373 50-341	0 E	8408240333 8408240342	8408240331 8408240338	84/08/07 84/07/12	40-8586 50-259	Q
8408230334 8408230344 8408230340	8408230330 8408230340 8408230355	84/08/03 84/08/10 84/08/16	CONTRACT TOPREP	н	8408240355 8408240357 8408240362	8408240354 8408240356 8408240360	84/07/10 84/07/10 84/07/13	WASTE MG* 50-321 50-370	Q Q
_ , , , , , , , , , , , , , , , , , , ,		34,00,10	TO NOT	••	# 4 2 # E 7 # H C E		J. 17 0// 4G	J. J.70	**

	NUMBER					ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISBUED	CATEGO	łΥ	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJEC CATEOD	
8408240343 8408240366 8408240367	8408240361 8408240364 8408240365	84/08/08 84/07/11 84/07/24	50-317 50-321 50-424	0	8408270292 8408270294 8408270295	8408270287	84/08/10 84/08/21	50-454 50-409	E
8408240368 8408240370	6408240365 6408240365	84/07/24 84/07/24	50-424 50-424	G G	8408270296 8408270297	8408270269 8408270265 8408270283	84/08/10 84/08/10 84/08/09	50-250 50-454 40-672	E
8408240371 8408240400 8408240419	8408240365 8408240396 8408240414	84/07/24 84/07/17 84/08/02	50-424 40-299 40-2259	Q	8408270298 8408270299 8408270302	B408270291 B408270293 B408270293	84/08/02 84/08/17 84/08/17	50-335 50-263	G P
8408240421 8408240423	8408240416 8408240417	84/07/19 84/07/27	50-269 40-8584	a	840B270306 840B270307	8408270291 8408270293	84/08/02 84/08/17	50-263 50-335 50-263	Р 0 Р
8408240429 8408270007 8408270029	8408240428 8408270003 8408270028	84/08/06 84/08/20 84/02/27	50~305 50~458 40~8585	Q Q	8408270310 8408270313 8408270314	8408270291 8408010061 8408270314	84/08/02 84/07/18	50-335 50-329	G A
8409270034 8409270078	8408270032 8408270074	84/03/19 84/08/10	40-8502 WABTE MG	т	8408270317 8408270321	8408270314 8408270313	84/07/31 84/08/02 84/08/02	50-250 50-335 50-416	Q Q
8408270088 8408270090	8408270082 8408270084	84/08/17 84/08/10	50-322 50-341	Q Q	9409270322 9409270323	8408270314 8408010061	84/07/31 84/07/18	50-250 50-329	G A
8408270103 8408270121	8408270094 8408270116	84/08/22 84/08/09	50-445 70-27	G	B408270324	8408270314	B4/07/31	50~250	a
8408270125	8408270116	84/09/09	70-27	_	8408270324 8408270329	8408270313 8408270314	84/08/02 84/07/31	50-416 50-250	Q Q
8408270140 8408270143	8408270133 8408270137	84/08/20 84/08/17	50-526 50-322	E.	8408270330 8408270333	8408010061 8408270313	84/07/18 84/08/02	50-329 50-416	0
B408270147 B408270147	8408270141	84/08/22 84/08/23	50-412	E	8408270336	9408010061	B4/07/18	50-329	Q. T
8408270162	8408270145 8408270154	84/08/20	50~269 50~327	С Р	84 0827033B 84 08270340	8408270334 8408270313	84/07/20 84/08/02	50-321 50-416	G G
8408270169 8408270170	8408270160 8408270164	84/08/14 84/08/22	50-269 50-155	P	8408270341	B40B270335	84/09/21	50-334	a
B408270172	8408270163	84/08/19	50-454	G	840B270345 840B270346	8408270339 8408270337	84/08/15 84/08/21	50-269 70-734	P
8408270173 8408270174	8408270168 8408270168	84/08/17 84/08/10	50-331 50-395	P G	8408270347 8408270351	8408270313 8408270342	84/08/02 84/07/17	50-416 50-424	g g
6408270175 6408270176	8408270167	84/08/17 84/08/10	50-331	P	8408270352	8408270348	84/08/22	50-341	Q
8408270182	8408270168 8408270168	84/08/10	50-395 50-395	Q Q	8408270362 8408270363	8408270358 8408270360	84/08/21 84/07/27	50-373 50-335	F G
8408270183 8408270186	8408270176 8408270179	84/08/20 84/08/20	50-269 50-445	G Q	8408270369 8408270370	8408270366 8408270365	B4/08/21 B4/07/27	50-259 50-327	Ř Q
8408270187 8408270191	8408270168	84/08/10	50-395	g	840B270371	8408270367	84/07/17	50-413	q
8408270199	8408270184 8408270196	84/07/09 84/07/31	50-413 50-259	G G	849B270374 849B270375	8408270366 8408270365	84/08/21 84/07/27	50-259 50-327	R
8408270200 8408270209	8408270192 8408270192	84/07/27 84/07/27	50-335 50-335	Q Q	6408270378 6408270382	8408270345 8408270345	84/07/27 84/07/27	50-327 50-327	Ğ
8408270211 8408270214	6408270206	84/08/01	50-302	g	8408270386	8408270383	84/07/20	50-349	Q
8408270219	8408270192 8408270206	84/07/27 84/08/01	50-335 50-302	G G	8409270388 8409270392	8408270387 8408270390	84/07/11 84/08/22	50-338 50-155	Q
8408270221 8408270224	8408270192 8408270206	84/07/27 84/08/01	50-335 50-302	Q Q	6408270407 8408270410	8408270406 8408270406	84/08/06 84/08/06	50-309 50-309	Ğ G
8408270225	8408270222	84/08/09	70-1151		8408270412	8408270409	84/08/01	50-361	P
8408270227 8408270237	8408270206 8408270234	84/08/01 84/08/08	50-302 50-410	G G	8408270413 8408270414	8408270411 8408270408	84/09/02	70-143	_
8409270240 8408270242	8408270232	84/07/26	50~43B	œ	8409270415	8408270411	84/07/12 84/08/02	50-424 70-143	G
8408270243	8408270234 8408270238	84/08/08	50-410 40-8584	Q.	8408270416 8408270418	8408270409 8408270409	84/08/01 84/08/01	50-361 50-361	P P
8408270246 8408270247	8408270233 8408270241	84/08/17 84/07/20	50-266	P	8409270419	8408270417	84/07/09	50-390	Q
8408270253	8400270250	84/08/01	50-321 Waste Mot	G. F	8408270421 8408270423	8408270411 8408270411	84/08/02 84/08/02	70-143 70-143	
8408270255 8408270256	8408270241 8408270250	84/07/20 84/08/01	50-321 WASTE MOT	Q -	8408270427	B40B270420	B4/08/09	70-143	_
8408270258	8408270254	84/08/01	70-27		8408270430 8408270431	8408270 <b>4</b> 27 8408270 <b>4</b> 26	84/07/25 84/07/31	50-424 50-324	9
8408270259 8408270261	9409270247 9409270241	84/08/09 84/07/20	50-369 50-321	g A	8408270432	8408270428	84/07/10	50-302	a
8408270262	8409270250	84/08/01	WARTE NOT	-	8408270433 840827043 <b>5</b>	8408270429 8408270426	84/07/25 84/07/31	50-424 50-324	G G
8408270263 8408270264	8408270257 8408270250	84/08/01 84/08/01	50-417 WASTE MOT	G	8408270434 8408270437	8408270429 8408270426	84/07/25	50-424 50-324	a
8408270266	8408270249	84/08/09	50-369	G	840B270439	8408270426	84/07/31 84/07/31	30-324	g g
8408270268 8408270268	8408270250 8408270257	84/08/01 84/08/01	WASTE MOT 50-417	a	8408270440 8408270447	8408270427 8408270444	84/07/25 84/07/24	50-424 50-369	G G
8408270269 8408270270	8408270241 8408270249	84/07/20 84/08/09		Q G	8408270448	8408270443	84/07/31	50-280	g.
8408270272	B408270257	84/08/01	50-417	G	9408270452 8408270454	8409270443 8409270443	84/07/31 84/07/31	50~280 50~280	g g
8408270274 8408270275	8408270254 8408270257	84/08/01 84/08/01	70-27 50-417	a	8408270454 8408270465	8408270443 8408270461	84/07/31 84/08/08	50-280 50-271	a
8408270276 8408270277	8408270245	84/08/10	50-454	E	8408270466	8408270462	B4/08/21	50-166	P
6406270279	8408270245 8408270249	84/08/10 84/08/0 <del>9</del>		Q Q	8408270469 8408270469	8408270460 8408270463	84/07/26 84/07/13	50~438 50~390	Q
6408270260 6408270261	8408270254 8408270273	84/08/01 84/08/21	70-27	G G	8408270473	8408270470	84/08/08	50-333	Q
8409270282	9409270254	84/08/01	70-27		8408270475 8408270478	8408270440 8408270471	84/07/26 84/08/20	50-438 50-344	a F
8408270284 8408270286	8408270245 8408270254	84/08/10 84/08/01	50-454 70-27	E	8408270480	8408270474	B4/07/17	50-413	Q
8408270288	8408270276	84/08/10	50-440	Q	8408270483 8408270486	8408270460 8408270477	84/07/26 84/08/06	50-438 50-184	Q Q
8408270290	8408270285	84/08/22	20-514	P	8408270492	8408270484	84/07/23	50-413	G

ACCESSION	NUMBER				ACCE6910			
ENGLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	łΥ	ENCLOGURE	PRINCIPAL DOCUMENT	DATE	SUBJECT CATEGORY
8408270494 8408270500 8408270501 8408270503 8408270504	8408270489 8408270489 8408270498 8408270497 8408270498	84/08/08 84/08/08 84/08/14 84/08/06 84/08/14	50-298 50-298 50-397 CONTRACT 50-397	Q Q P	8408280282 8408280285 8408280289 8408280293 8408280299	8408280070 8408280070 8408280271 8408280278	84/08/03 84/08/03 84/08/03 84/08/10 84/07/26	70-1201 70-1201 70-1201 50-219 0 70-143
8409270508 8408270518 8408270521 8408270528 8408270530	8408270497 8408270510 8408270513 8408270513	84/08/04 84/08/07 84/07/30 84/07/30 84/07/30	CONTRACT 50-54 50-261 50-261 50-261	Q Q Q	8408280300 8408280321 8408280327 8408280346 8408280348	8408280298 8408280319 8408280327 8408280342 8408280345	84/07/24 84/08/17 84/07/17 84/08/17 84/09/14	70-143 50-344 P 50-413 Q 50-445 A 50-346 F
8408270531 8408270536 8408270540 8408270541 8408270552	8408270524 8408270513 8408270534 8408270538 8408270547	84/07/27 84/07/20 84/07/27 84/08/03 84/08/20	70-27 50-261 70-1113 50-333 CONTRACT	Q Q	8408280366 8408280370 8408280370 8408280373 8408280373	8408280360 8408280362 8408280361 8408280360 8408280372	84/07/22 84/08/09 84/07/20 84/07/22 84/08/06	50-295 P 70-1113 50-249 0 50-295 P 50-413 F
8408270558 8408270572 8408270576 8408270579 8408270582	8408270557 8408270561 8408270574 8408270577 8408270581	84/08/13 84/07/23 84/07/30 84/08/10 84/08/20	CONTRACT 50-395 CONTRACT 50-29 CONTRACT	. Q	8408280378 8408280380 8408280381 8408280383 8408280383	8408280340 8408280340 8408280340 8408280340 8408280340	84/07/22 84/07/22 84/07/22 84/07/22 84/07/22	50-295 P 50-295 P 50-295 P 50-295 P 50-295 P
8409280003 8409280007 8409280007 8409280012 8409280016	8408280002 8408280005 8408280005 8408280010 8408280014	84/08/24 84/08/13 84/08/13 84/03/25 84/07/16	50-255 WASTE MG WASTE MG 40-8675 40-8502		8408280370 8408280379 8408280399 8408280397 8408280400	8408280340 8408280384 8408280340 8408280344 8408280340	84/07/22 84/07/11 84/07/22 84/08/24 84/07/22	50-295 P 50-413 Q 50-295 P 50-322 T 50-295 P
8408280022 8408280024 8408280028 8408280035 8408280037	8408280018 8408280018 8408280026 8408280027 8408280027	84/07/24 84/07/24 84/07/27 84/08/07 84/08/07	40-8857 40-8857 50-400 50-261 50-261	Q Q	8409280404 8408280407 8408280411 9408280422 8408280422	8408280360 8408280360 8408280360 8408280360 8408280360	84/07/22 84/07/22 84/07/22 84/07/22 84/07/22	50-295 P 50-295 P 50-295 P 50-295 P 50-295 P
8408280042 8408280045 8408280047 8408280053 8408280056	B4082B0027 B4082B0027 B4082B0030 B4082B0051 B40B2B0054	84/08/07 84/08/07 84/07/11 84/07/26 84/08/20	50-261 50-261 50-390 70-143 50-322	а а а	8408280460 8408280465 8408280457 8408280471 8408280476	8408280456 8408280456 8408280456 8408280467 8408280472	84/08/10 84/08/10 84/08/10 84/08/13 84/08/01	50-400 0 50-400 0 50-400 0 COMMISSION 50-267 0
8408280069 8408280072 8408280077 8408280082 8408280085	8408280061 8408280061 8408280061 8408280061 8408280080	84/07/19 84/07/19 84/07/19 84/07/19 84/08/13	50-302 50-302 50-302 50-302 50-254	0 0 0	8408280477 8408280481 8408280485 840829007 8408290025	8408280472 8408280472 8408280472 8408290003 8408290021	84/08/01 84/08/01 84/08/01 84/08/10 84/08/07	50-269 G 50-269 G 50-269 G 50-423 G 50-261 G
8408280091 8408280101 8408280114 8408280114 8408280118	8408280088 8408220453 8408280104 8408280075 8408280111	84/07/24 84/08/20 84/08/24 84/07/25 84/07/17	50-400 50-352 50-395 50-259 70-1113	Q A P Q	8408270028 8408270031 8408270034 8408270035 8408270037	8408270021 8408270021 8408270021 8408270021 8408270021	84/08/07 84/08/07 84/08/07 84/08/07	50-261 Q 50-261 Q 50-261 Q 50-261 Q
8408280123 8408280124 8408280126 8408280131 8408280132	9409280111 8409280076 8409280120 8409280127 8409280130	84/07/17 84/07/25 84/08/22 84/08/23 84/08/23	70-1113 50-259 GA999 50-440 50-352	0 0 A	8408270102 8408270104 8408270108 8408270115 8408270138	8408290098 8408290101 8408290103 8408290113 8408290134	84/08/24 84/08/16 84/07/31 84/08/01 84/08/24	50-354 A 50-278 Q 50-458 Q 50-368 Q 50-354 E
8408280134 9408280139 408280140 08280141 08280146	8408280094 8408280120 8408280094 8408280134	84/07/25 84/08/22 84/07/25 84/08/20 84/08/20	50-259 0A999 50-259 50-445 50-445	0 0 0	8408270142 8408270144 8408270147 8408270160 8408270176	8408270140 8408270134 8408270134 8408270134 8408270172	84/08/08 84/08/24 84/08/24 84/08/24 84/08/01	50~285 Q 50~354 E 50~354 E 50~354 E 50~368 Q
08280155 ;08280164 408280169 ;408280187 8408280188	8408280147 8408280140 8408280140 8408280180 8408280184	84/08/23 84/08/17 84/08/17 84/08/21 84/08/15	50-315 50-263 50-263 50-322 50-313	0 P 0 F	8408270204 8408270211 8408270287 8408270286 8408270287	8408270197 8408270208 8408270265 8408270277 8408270282	84/08/24 84/08/27 84/08/24 84/08/17 84/08/15	50-266 F 50-445 K 50-209 T 50-163 P 50-259 P
8408280192 8408280198 8408280203 8408280206 8408280209	8408280189 8408280197 8408280200 8408280202 8408280202	84/08/23 84/08/17 84/08/21 84/08/17	70-143 50-346 50-412 50-331 50-331	K E P	\$408270291 8408270297 8408290297 8408290324 8408290327	8408290277 8408290282 8408290290 8408290314 8408290314	84/08/17 84/08/15 84/08/22 84/08/15 84/08/15	50-163 P 50-259 P PR 50-263 P 50-263 P
8408280211 8408280213 8408280222 8408280226 8408280248	8408280202 8408280208 8408280220 8408280220 8408280220	84/08/17 84/08/24 84/08/23 84/08/23 84/08/20	50-331 50-424 50-240 50-240 50-220	P A P G	8408270347 8408270330 8408270352 8408270357 8408270483	8408290347 8408290348 8408290348 8408290354 8408290478	84/08/14 84/08/15 84/08/05 84/08/05 84/08/08	CONTRACT COMMISSION COMMISSION COMMISSION 50-322 G
8408280260 8408280261 8408280262 8408280266 8408280268	8408280257 8408280257 8408280258 8408220173 8408280265	84/08/16 84/08/15 84/08/16 84/08/17 84/08/25	TOPREP 50-239 50-423 50-445 50-445	P E T G	8408270486 8408270553 8408270551 8408270570 8408300021	8408270478 8408270547 8408270547 8408270565 8408300014	84/08/08 84/08/07 84/08/07 84/08/10 84/08/10	50-322 G 50-456 G 50-456 G 50-266 G 50-267 F
8408280270 8408280273 8408280276 8408280277 9408280278	8408280090 8408280272 8408280257 8408280090 8408280272	84/08/03 84/08/24 84/08/15 84/08/03 84/08/24	50-259 70-1201	₽ ₽ ₽	8408300028 840830037 840830041 840830060 840830083	8408300014 8408300035 8408300035 8408300058 8408300079	84/08/10 84/08/27 84/08/27 84/08/13 84/08/17	50-269 F 50-220 P 50-220 P 50-263 G 50-166 P

50-412 F PR 50-312 P PR 50-312 P

50-289 P 50-204 Q 50-312 P 70-1131 CONTRACT

50-344 50-305 50-255 50-289 50-289

XPORTLIC XPORTLIC HABTE MOT HABTE MOT WASTE MOT

71-66 50-298 8 50-373 8 CONTRACT 50-317 S

CONTRACT 50-341 Q 50-293 P 50-260 P 50-260 P

50~293 P 71~16 50~373 P 71~216 71~169

ACCESS10					ACCESSIO	ON NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJEC		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJE
8408300096 8408300099 8408300100 8408300105 8408300108	8408300087 8408300095 8408300094 8408300095	84/08/10 84/08/08 84/08/07 84/08/07 84/08/08	50-219 50-10 50-528 50-528 50-10	9	8408310177 8408310191 8408310194 8408310197 8408310204	8408310176 8408310188 8408310192 8408310192 8408310203	84/08/23 84/08/24 84/08/30 84/08/30 84/08/23	50-409 50-341 50-454 50-454 50-254
8408300111 8408300113 8408300114 8408300116 8408300121	8408300102 8408300106 8408300110 8408300107 8408300118	84/08/27 84/08/14 84/08/08 84/08/13 84/08/14	50-237 50-247 50-312 50-29 50-456	9 0 0	8408310213 8408310215 8408310220 8408310221 8408310237	8408310208 8408310212 8408310217 8408310217 8408310234	84/08/27 84/08/16 84/06/27 84/08/24 84/06/25	50-412 PR 50-312 PR 50-312
8408300127 8408300132 8408300133 8408300149 8408300140	8408300125 8408300128 8408300110 8408300140 8408300134	84/08/03 84/08/23 84/08/08 84/08/09 84/08/24	50-528 50-255 50-312 50-275 50-313	9	B408310234 B408310244 B408310246 B408310255 B408310255	8408310238 8408310243 8408310245 8408310254 8408310260	84/08/27 84/08/03 84/08/21 84/05/31 84/08/16	50-289 50-204 50-312 70-113: CONTRAC
8408300164 8408300165 8408300166 8408300175 8408300180	8408300156 8408300163 8408300154 8408300172 8408300176	84/07/11 84/08/27 84/08/24 84/08/23 84/08/02	50-255 50-361 50-313 50-219 50-263	9 4 9 4 6	8408310275 8408310276 8408310302 8408310308 8408310311	8408310269 8408310288 8408310299 8408310305 8408310305	84/08/01 84/08/17 84/08/15 84/08/07 84/08/07	50-344 50-305 50-255 50-289 50-289
8408300183 8408300186 8408300188 8408300194 8408300195	8408300174 8408300179 8408300181 8408300190 8408300187	84/08/02 84/08/14 84/08/14 84/06/19 84/08/02	50-263 50-440 50-315 70-824 50-528	F G G	8408310321 8408310325 8408310335 8408310344	8408310317 8408310317 8408310331 8408310331 8408310331	84/08/21 84/08/21 84/03/27 84/03/27 84/03/27	XPORTL XPORTL WASTE ! WASTE !
8408300194 8408300199 8408300200 8408300202 8408300204	8408300179 8408300192 8408300190 8408300190 8408300193	84/08/14 84/08/14 84/06/19 84/06/19 84/06/15	50-440 50-305 70-824 70-824 50-369	7 00 2	8408310358 8408310359 8408310362 8408310362 8408310368	8408310354 8408310355 8408310361 8408310363 8408310365	84/08/28 84/08/20 84/08/02 84/08/23 84/08/04	71-66 50-298 50-373 CONTRAC
8408300206 8408300207 8408300211 8408300217 8408300217	8408300190 8408300203 8408300208 8408300197 8408300197	84/06/19 84/08/14 84/06/05 84/08/22 84/08/22	70-824 50-341 50-302 50-364 50-364	9 4 4	8408310370 8408310374 8408310430 8408310431 8408310432	8408310385 8408310381 8408310396 8408310424 8408310424	84/08/27 84/08/17 84/08/22 84/08/17 84/08/17	CONTRAC 50-341 50-293 50-260 50-260
8408300220 8408300237 8408300230 8408300234 8408300307	8408300203 8408300233 8408300248 8408300248 8408300276	84/08/14 84/08/14 84/08/10 84/08/10 84/06/06	50-341 50-287 50-312 50-312 70-1201	0 0	8408310433 8408310433 8408310442 8408310442 8408310436	8408310396 8408310436 8408310439 8408310449 8408310455	84/08/22 84/08/28 84/08/27 84/08/28 84/08/28	50~293 71~16 50~373 71~216 71~169
8408300308 8408300319 8408300323 8408300329	8409300277 8409300315 8409300315 8409300277	84/08/15 84/07/19 84/07/19 84/08/15	50-254 50-324 50-324 50-254	***	8408310457	8408310443	84/09/29	71-70
8408300344 8408300346 8408300350 8408300387 8408300380 8408300381	8408300277 8408300344 8408300347 8408300373 8408300374	84/08/15 84/07/19 84/06/08 84/08/01 84/08/01 84/08/10	50-254 50-424 50-400 50-344 50-344 50-320	R 00000				
8408300387 8408300387 8408300390 8408300393 8408300394	8408300385 8408300385 8408300383 8408300388 8408300391	84/08/23 84/08/23 84/08/08 84/07/23 84/06/28	50-328 50-328 50-528 50-373 70-27	P P G R				
8408300397 8408300401 8408300407 8408300451 8408300454	8408300398 8408300398 8408300383 8408300444 8408300444	84/08/08 84/07/18 84/08/08 84/08/07 84/08/07	50-528 70-27 50-328 50-397 50-397	0				
8408300469 8408300477 8408300498 8408300504 8408300513	8408300459 8408300459 8408300483 8408300483 8408300508	84/07/13 84/07/13 84/08/02 84/08/02 84/07/23	50-327 50-327 50-312 50-312 50-373	0 0 0 0 0				
8408300515 8408300516 8408310005 8408310025 8408310035	8408300512 8408300508 8408310001 8408310017 8408310032	84/08/17 84/07/25 84/08/21 84/08/24 84/08/01	50-261 50-373 XPORTLIC XPORTLIC 50-275	F R P				
8408310039 8408310048 8408310088 8408310105 8408310112	8408310031 8408310044 8408310082 8408310102 8408310108	84/07/12 84/08/01 84/08/23 84/08/14 84/08/24	70-27 50-470 CONTRACT 50-445 TOPREP	Q Q				
8408310114 8408310124 8408310144 8408310157 8408310165	8408310109 8408310122 8408310140 8408310153 8408310161	84/07/09 84/08/21 84/08/23 84/08/28 84/08/02	50-259 50-305 70-2571 50-289 50-255	b 4				

#### APPENDIX A

#### **DEFINITIONS OF DOCKET 50 CATEGORIES**

#### A APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are

- 1 Application for construction permit
- 2 General Information submitted with construction permit application
- 3 Amendments and changes to items 1 and 2
- 4 NRC questions, requests for additional information, and applicant responses
- 5. Correspondence and documents relating to unresolved design and construction issues
- 6 Meeting announcements and summaries of meeting discussions on issues of item 5
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.)
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information
- 12 Application for operating license.
- 13 General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application

### B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report)
- 2. Amendments and changes to the PSAR.

- 3 Transmittal and acknowledgement letters
- 4 Certificates of service to the PSAR

#### C UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filled in Categories A. D. M. P. or R.

- I Environmental Report (FR) submitted by the audity
- 2 Amendments and supplements to the IR
- 3 Transmittal and acknowledgement letters
- 4 Information on scheduling of submittal or review of LR
- 5 NRC questions, requests for additional information, and applicant responses
- 6. Federal register notices citing the availability of items 1 and 2
- 7 Correspondence relating to the review of ER
- 8 Meeting announcements or reports of meetings where the primary subject of discussion is the ER

## D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A. C. M. P or R

- 1 Draft and Final Environmental (Impact) Statements (DES and FFS) prepared by the NRC
- 2 Supplements to the DES and FES.
- 3 Correspondence relating to the DES and FES
- 4. Comments from other federal state and local government agencies
- 5. Transmittal and acknowledgement letters
- 6 Documents related to NRC review of environmental issues or of LR obtained for purposes of writing the environmental statements
- 7 Backup technical documents submitted in connection with above
- 8 Federal register notice citing availability of nons 1 and 2
- 9 Site visits to obtain information for DES or FES
- Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES

#### E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A. P or W. depending on the phase of the licensing process

- 1 Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report)
- 2 Supplements to SER
- 3 Correspondence relating to SER
- 4 Federal register notices citing availability of items 1 and 2
- 5 Information on scheduling of SER submittals and review
- 6 Requests for additional information for use in preparing SLR, responses to such requests
- 7 Meeting announcements or reports of meetings where the primary subject of discussion is the SLR
- 8 Transmittal and acknowledgement letters

#### F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

- I Fire Hazard Protection Plan and surveys
- 2. Plant evacuation correspondence
- 3 Safeguards Contingency Plans
- 4 Review of Health Physics Program
- 5 Correspondence relating to aforementioned plans
- 6. Supplements, changes and revisions to plans

#### G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T

- Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2 Federal register notices regarding hearings
- 3 Requests to make appearances at hearings.
- 4 Motions, briefs, arguments, statements and related correspondence filed by participants for hearings
- 5 Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6 Correspondence to and from intervenors
- 7. Board orders and decisions
- 8 Petitions for Commission action.
- 9 Legal filings and Commission orders and decisions resulting from item 8

#### H. GENERAL CORRESPONDENCE

This category includes documents with fittle or no bearing on the status of the application or license litems that have no substantive technical content or meaning for the status of the license or application are included

- I Change of address notifications
- 2 Changes in structure of organization
- 3 Changes in service lists
- 4 NRC requests to applicant for additional copies of documents.
- 5 Correspondence from the public requesting information about the facility and NRC responses.
- 6 Correspondence on strictly administrative matters
- 7 Letters of support, concern or opposition to the facility
- 8 Correspondence regarding the Local Public Document Rooms (LPDRs)
- 9 Professional qualification statements not pertaining to the hearing process

#### I FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2 Separately submitted financial information and related correspondence

#### J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies
- 3 Other correspondence regarding indemnity and insurance matters.

### K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P

- Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2 Amendments and changes to the FSAR
- 3 Federal register notices citing availability of items 1 and 2
- 4 Transmittal and acknowledgement letters
- 5 Certificates of service to the FSAR.

### L LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit

- 1 Limited Work Authorizations (LWA) and amendments
- 2 Correspondence pertaining to work performed under LWA's

#### M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrusi Review"
- 2 Correspondence where the primary topic of discussion is antitrust matters
- 3 All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N

#### N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M

## O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews
- 2. Correspondence from ACRS
- 3 Announcement of ACRS meetings
- 4 Transmittal and acknowledgement letters
- 5 ACRS reports
- 6 Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings
- 7 Minutes at ACRS Subcommittee Meetings

#### P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license

- 1. Operating license amendments, proposed amendments changes and related correspondence
- 2 Technical specifications and changes.

- 3 Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2
- 4 Federal register notices citing availability of items 1 and 2
- 5 Correspondence regarding the Final Safety Analysis Report (FSAR)
- 6 All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R)
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11 Owner's group meeting announcements and reports
- 12 Quality assurance information.
- 13 Environmental matters (technical)
- 14. Emergency core cooling system documents.
- 15 Radioactive waste information
- 16. Correspondence regarding expansion of spent fuel storage pool
- 17. Start-up test reports
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility, not covered by an IE Bulletin.
- 19. Reports of site visits

## Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1 Inspection reports
- 2 IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN s).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

#### R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature

- Monthly, semiannual, or annual operating reports (other than financial)
- 2 Periodic environmental monitoring, effluent testing, or similar reports
- 3 Periodic personnel exposure reports
- 4 Operational Logbooks

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets

5 Correspondence or other documents relating to the above listed items

#### S REPORTABLE OCCURRENCES, PNOS. PNSs AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes.

- All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences)
- 2 Potential or possible reportable deficiency reports and related correspondence.
- 3 Personnel exposure reports.
- 4 Construction deficiency reports submitted under 10 CFR 50.55e
- 5. Preliminary Notification of Occurrence (PNOs) and Preliminary Notification of Safeguards Events (PNs).
- 6. Environmental Technical Specifications violation reports and Environmental Event reports
- 7 Part 21 Reports of defects and noncompliance
- 8. Correspondence or other documents relating to items 1-7.

#### T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts
- 2. Testimony and statements submitted to ASLB and ASLAB.
- 3 Commission meeting transcripts.
- 4. NRC staff briefings to the Commission
- 5. Statements and written testimony submitted at Commission meeting or hearings
- 6. Transcripts of utility briefs to NRC staff
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts
- 8. Corrections to above items

#### U CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H

- Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches
- 2 Preparatory and backup documents for item 1
- 3 Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters

#### V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1. Operator licenses or administrative information bearing on licensing of operators
- 2 NRC examination results
- 3 Power plant examination summary sheet

#### W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward

- 1. Application for authority to voluntarily surrender license
- 2. Application to dismantle the facility and dispose of component parts
- Technical documents submitted in support of items 1 and 2, such as Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning
- 4. Documents relating to disposal of radioactive material and decontamination of the site
- 5. Other correspondence relating to above items.
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P

#### X. ONSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

#### Y. INDEPENDENT SPENT FUEL STORAGE INSTALLATIONS (ISFSI)

This category contains documents with an NMSS license and/or a Docket-72 number. For installations on a reactor site, the associated Docket-50 number will also be identified.

- 1. License applications, licenses, amendments and proposed amendments to possess power reactor spent fuel and other radioactive materials associated with spent storage in an independent spent fuel storage installation. (Such spent fuel storage installations may be on a reactor site or at a separate site.)
- 2. All related correspondence and reports to the above.

#### APPENDIX B

#### DEFINITIONS OF NONDOCKETED CATEGORIES

#### 10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes

- 1 Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3 Certification of General Counsel on closed meetings.
- 4 Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings
- 5. Verbatim unofficial and official transcripts of portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence
- 7. Staff requirements memoranda for open meetings, memoranda to record; record of votes of Commissioners on items under consideration at meetings.

#### ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters
- 2. · ACRS meeting announcements, description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available
- 4. ACRS consultant reports, comments and related correspondence.
- 5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

#### ADVCM - NRC Advisory Committees

This category contains documentation pertaining to the responsibilities of all NRC advisory committees, other than the Advisory Committee on Reactor Safeguards. The documents in this category are:

- 1. Charters of each advisory committee.
- 2. Verbatim transcripts of committee meetings.

- 3 Meeting announcements; description of meeting agendas.
- 4. Committee generated reports, memoranda, and correspondence that are publicly available.
- 5. Committee related correspondence.

#### COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including

- Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.
- 2 Travel vouchers, telephone logs and official appointment calendars of individual Commissioners
- Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (LDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTI for transcripts of Commission meetings, see IOCFR category. For all other staff papers with a SICY series designation prepared for Commission review, see SECY category.

#### CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AFC and NRC contracts and Interagency Agreements, including

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RTP or IFB) issued by the NRC.
- 3. Notifications of contract execution specifying contract number, project title, contractor name, contract type, funding, and period of performance
- 4 Contractual documents and contract modifications, if any,

#### DISCLOSURE - Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

#### FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include

- Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- 2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records of portions of records released in response to specific requests made under FOIA.

#### GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- Death reports of action plans to accomplish generic tasks in the regulatory program
- 2 Correspondence with industry and internal correspondence regarding the methodologies analyses, and programmatic and technical aspects of issues
- 3. Meeting notifications and minutes
- 4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

#### I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1 I&I Circulars, which describe an event at a licensed facility and are informational in nature
- 2 I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3. I&F Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event
- 4 Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety of public interest significance

NOTF For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories

#### MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories

#### NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors

- 1. These reports are normally final work products and are characterized by the following criteria
  - a They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
  - b They present the results of Commission licensing and policy decisions.
  - c. They present the results of technical research conducted for the Commission
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- 3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

### ORG - Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations, records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development, and energency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are

- Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
- 2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility, e.g., EPA has authority to control all radioactive pollutants emitted into the air
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S plants to withstand earthquakes.

NOTE For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, resemd or change an NRC regulation, see the PRM category.

#### PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are.

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- 4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR

#### PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- 1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.

- 3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
- 4 Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

#### PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects (1) commercial nuclear power plants for which NRC has full licensing responsibilities, and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1 "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

- A. Application/Construction Stage
  - I. Application submitted by the utility.
  - 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
  - 3. Applicant's Quality Assurance Manual
  - 4. Early site review information.
  - 5. Backup technical documents submitted in support of the application.
  - 6, Early site visits.
- B. Utility PSAR and Amendments
  - 1. PSARs submitted by the utility.
  - 2. Amendments and changes to the PSAR.
  - 3. Transmittal letters.
  - 4. Letters acknowledging receipt of the PSAR.
- G. Adjudicatory Correspondence
  - 1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.
- M. Antitrust Correspondence
  - 1. Submittals and related material pertaining to the antitrust review.

#### O. Inspection Reports

- Inspection reports of the applicant's quality assurance program.
- Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

#### 2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

### PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include.

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- 2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

#### OA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

regulatory guides issued by the Commission and related corthe industry and the public methods acceptable to the NRC staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides
- NOT1 For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

### RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are

- 1. Project description documents
- 2. Letter reports of accomplishments and data reports, for example,
  - a. model documentation reports
  - b. code documentation reports
  - c. code verification reports
- 3. Pre-test prediction reports.
- 4. "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE For final reports of research conducted by contractors, see also NUREG reports.

#### REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are

- 1 Agendas for quarterly review group meetings
- 2 Summary minutes of review group meetings representing views expressed, including dissenting views.
- 3 Research plans and predicted results of major experiments, presentations by research contractors.
- 4 Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5 Internal memoranda relating to topics under discussion.

#### RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2 Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

#### SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- 1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

#### **STATE PROG** – **State Programs**

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies, and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

- 1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
  - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance
  - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
- 3. State Legislative Reports.
- 4. Agreement State Licensing Statistics Reports.

NOTE. For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category

#### TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

#### WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- 2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

- 3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes
- NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories

### XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3 Commission letters requesting Executive Branch views
- 4 Review and findings of the Executive Branch on whether issuance of a license would be mimical to U.S. common defense and security
- 5. Correspondence from foreign governments, international organizations, and members of the public
- 6. Staft position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8 Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1

NOTE For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

C FORM 335 U.S. NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET		1 REPORT NUMBER (Assigned by DDC) NUREG-0540 Vol. 6, No. 8	
4 TITLE AND SUBTITLE (Add Volume No., if appropriate) Title List of Documents Made Publicly Available August 1-31, 1984		2 (Leave blank) 3 RECIPIENT'S ACCESSION NO	
7 AUTHOR(S)		5 DATE REPORT COMPLETED  MONTH YEAR	
9 PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code) Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, DC 20555  12 SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code) Same as 9, above.		DATE REPORT ISSUED  MONTH OCTOBER  1984  6 (Leave blank)  8 (Leave blank)  10 PROJECT/TASK/WORK UNIT NO  11 FIN NO	
13 TYPE OF REPORT	PERIOD COVERE	D (Inclusive dates)	
Monthly	August	t 1-31, 1984	
15 SUPPLEMENTARY NOTES	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	14 (Leave plank)	
This document is a monthly publication containing descriptions of information received and generated by the U.S. NRC. This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials, and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. The following indexes are included: Personal Author Index, Corporate Source Index, Report Number Index, and Cross Reference to Principal Documents Index.			
176 IDENTIFIERS OPEN ENDED TERMS			
18 AVAILABILITY STATEMENT Unlimited	Uncla 20 SECURITY	ssified	21 NO OF PAGES 22 PRICE S